SUMMARY REPORT OF THE 2009 EXPLORATION PROGRAM

ON THE

CANADIAN CREEK PROPERTY

WHITEHORSE MINING DISTRICT, YUKON TERRITORY

NTS: 115J/10,11,14,15
Latitude 62^0 44'N, Longitude 138^0 56'W

For

Alder Resources Ltd.
1710-1177 W Hastings Street
Vancouver, BC, V6E 2L3

and

Eastfield Resources Ltd.
110-325 Howe St.
Vancouver, B.C.
V6C 1Z7

By

R.J. (Bob) Johnston, P.Geo.

Mincord Exploration Consultants Ltd.

November 6, 2009

Registered Owners; Eastfield Resources Ltd. ,
CRS Copper Resources Corp.

Date of Fieldwork; July 9-Sept 28, 2009

VOLUME 1

TABLE OF CONTENTS

	Page
1.) Summary	1
2.) Introduction and Terms of Reference	4
3.) Reliance on other Experts	4
4.) Property Description and Location	4
5.) Accessibility, Climate, Local Resources, Infrastructure and Physiography	7
6.) History	8
7.) Geological Setting	10
8.) Deposit Types	10
9.) Mineralization	13
10.) Exploration	14
2009 Exploration Program	24
2009 Grid Work	25
2009 Soil Geochemistry	25
2009 Geophysical Survey	26
2009 Prospecting and Reconnaissance	27
2009 Drilling	28
11.) Drilling	34
12.) Sampling Method and Approach	40
13.) Sample Preparation, Analyses and Security	40
14.) Data Verification	42
15.) Adjacent Properties	42
16.) Mineral Resource and Metallurgical Testing	42
17.) Mineral Resource and Mineral Resource Estimates	42
18.) Other Relevant Data and Information	43
19.) Interpretation and Conclusions	43
20.) Recommendations	45
21.) 2009 Expenditure Statement	46
22.) Statement of Qualifications	47
23.) References	48

TABLES:

1.	Canadian Creek Claims List	4
2.	Casino B Claims List	5
3.	Canadian Creek Drilling 1970-2009	36
4.	Ana Significant Drill Results	38
5.	Koffee Significant Drill Results	38
6.	Casino B Significant Drill Results	38
7.	Coffee Can Significant Drill Results	39
8:	Recommended Budget for Next Phase of Exploration at Canadian Creek	45
9.	Expenditure Statement; Canadian Creek 2009	46

APPENDICES

APPENDIX 1	Drill Sections; CC09-01-10
APPENDIX 2	Drill Logs; CC09-01-10
APPENDIX 3	Canadian Creek 2009 Analytical Results
APPENDIX 4	Canadian Creek Rock Sample Descriptions
APPENDIX 5	Canadian Creek 2009 Inverted Chargeability Plans
APPENDIX 6	Canadian Creek 2009 Inverted Resistivity Plans
APPENDIX 7	Canadian Creek 2009 Inverted Chargeability Sections
APPENDIX 8	Canadian Creek 2009 Inverted Resistivity Sections

LIST OF FIGURES

		Page
Figure 1	Location Map	3
Figure 2	Claim Map	6
Figure 3	Regional Geology	12
Figure 4	Soil Grids	17
Figure 23	Compilation Map	44
Figure 5	Au Soil, Rock Geochemistry	attachment
Figure 6	As Soil Geochemistry	attachment
Figure 7	Sb Soil Geochemistry	attachment
Figure 8	Bi Soil Geochemistry	attachment
Figure 9	Cu Soil Geochemistry	attachment
Figure 10	Mo Soil Geochemistry	attachment
Figure 11	2009 Chargeability Map	attachment
Figure 12	2009 Resistivity Map	attachment
Figure 13	2009 Ground Magnetics Map	attachment
Figure 14	Coffee Can Zone; Drillhole Locations on 50ppb Au, 12.5 mV chargeability contours	attachment
Figure 15	Drill Section CC09-01	attachment
Figure 16	Drill Section CC09-02	attachment
Figure 17	Drill Section CC09-03, 04	attachment
Figure 18	Drill Section CC09-05	attachment
Figure 19	Drill Section CC09-06, 07	attachment
Figure 20	Drill Section CC09-08	attachment
Figure 21	Drill Section CC09-09	attachment
Figure 22	Drill Section CC09-10	attachment

1. SUMMARY

The Canadian Creek property is located in the Yukon Territory approximately 160 kilometres south of Dawson City, adjacent to Western Copper Corp.'s Casino property immediately to the east. The Canadian Creek property, consisting of 245 claims, is owned by Cariboo Rose Resources Ltd., in part by outright claim ownership and in part by an option agreement that gives Cariboo Rose the right to earn a 100% interest in additional claims on the east side of the property. Alder Resources Ltd. has an option with Cariboo Rose Resources that grants it the right to earn a 60% interest in the property by making cash payments totaling $250,000, making share issuances totaling 250,000 shares and completing exploration expenditures totaling $2,500,000 before June 18, 2013.

Rocks belonging to the Dawson Range Batholith, Casino Complex intrusions and the Yukon Metamorphic Complex occur on the Canadian Creek property. The Dawson Range intrusive rocks are the most widespread and are of Cretaceous age. They are typically granodiorite in composition and intrude schists and gneisses of the Paleozoic-aged Yukon Metamorphic Complex rocks. The Casino Complex intrusions are also Cretaceous but post-date the Dawson Range intrusions. They are generally recessive and not well exposed and include quartz monzonite varying to granodiorite and minor quartz diorite, along with a rhyodacitic unit known as the Patton Porphyry, as well as several varieties of breccia. These rocks are host to the copper-gold molybdenum porphyry mineralization at the Casino Deposit.

The Canadian Creek property is located within the prolific Tintina Gold Province, situated between the significant gold occurrences of Underworld Resources' White Gold property 50 kilometres to the northwest, and Northern Freegold Resources' Mount Freegold Property 75 kilometres southeast.

Exploration in the Canadian Creek area dates back to the era of the Klondike gold rush, when placer exploration was conducted on creeks in the area. A placer gold-tungsten deposit immediately north of the property on Canadian Creek was worked up to the 1990's. Modern exploration began in the 1960's with the discovery of the Casino porphyry copper-gold deposit, when soil grids were emplaced and prospecting and mapping conducted over the area of the present Canadian Creek property.

Recent exploration on the property commenced in 1993 when Eastfield Resources Ltd. acquired the property and put in exploration grids and completed six diamond drill-holes on the Ana area and one drill-hole on the Koffee area. The 1993-94 work was followed by extensive field programs in 1996, 1997 and 1999 consisting of induced polarization surveying, road construction and trenching on the Ana, Koffee, Maya and Ice claims. In 2000, a 1,985-metre diamond-drill program was completed on the property. This drill program confirmed the presence of a gold mineralized intrusion related system discovered by Pacific Sentinel Gold Corp. in a 1994 drill hole located in the Casino "B" claims (55.17 metre intersection grading 0.72 g/t gold). Minor soil geochemistry completed in 2001 was followed by small programs in 2003, 2004 and 2005. In 2007 a diamond drill program consisting of five holes (879 metres total) was completed at a cost of $448,000. In 2008 a program of satellite imagery "aster analysis" was completed on the claims at a cost of $8,783.

In December of 2006 Wildrose Resources Ltd. was reorganized into Wildrose Resources Ltd. and Cariboo Rose Resources Ltd. with the Canadian Creek property being assigned to Cariboo Rose Resources Ltd.

In 2009 the Canadian Creek property was optioned to Alder Resources Ltd., who funded a major exploration program on the Canadian Creek property. The work was directed at a 1993 arsenic in soil anomaly that occurs in the north part of the Koffee Creek grid, which is referred to as the Coffee Can zone. The 2009 program funding was due to interest generated by the discovery of the nearby Underworld Resources' White Gold occurrence earlier in 2009, which is hosted in similar geology with a similar geochemical signature. The 2009 work at Canadian Creek was conducted by Mincord Exploration Consultants.

The 2009 program included grid emplacement, soil and rock sampling, prospecting, ground geophysics and diamond drilling. The soil survey revealed large areas of strongly anomalous gold in soils, as high as 2287ppb, that stretch for over four kilometres in an east-northeast direction, associated with other anomalies in arsenic, bismuth and antimony. The zone of anomalous gold remains open to the east. The geophysical survey revealed numerous strong chargeability anomalies, many of which coincide with the gold in soil anomalies.

Results from the drilling revealed numerous anomalous gold intervals, generally associated with elevated arsenic, antimony and bismuth hosted in both gneiss and granodiorite, often in clay altered structures, sheeted pyrite veins or quartz-carbonate veins. Highlights include 7.25 metres of 683ppb Au; including 3 metres of 1099ppb Au from hole CC09-10, and 1.5 metres of 3458ppb Au from hole CC09-08. Both of these holes are near to the eastern end of the 2009 grid.

Resampling of old trenches in other parts of the property was undertaken in order to verify historical results and significant gold results. In trench TR-2 of 1993, located in the Ana Pass area, a grab sample of a tourmaline-pyrite-quartz altered intrusive returned 2516ppb Au. Near to the Casino property claim boundary in Canadian Creek, trench 9076-C ran 493ppb Au over 35 metres, including a 5 metre interval of 1079ppb Au.

Results from historical work and the 2009 programme have revealed three areas on the Canadian Creek property which have the potential to host significant gold mineralization. These are the Coffee Can, Casino B, and Ana Pass areas. All contain large >50ppb Au in soils anomalies, and all have returned grab samples or short drill intervals of high gold values (Coffee Can and Ana Pass), or long drill intervals of strongly anomalous gold values, (Casino B).

An exploration programme totaling $1,000,000 is proposed to test all three of these areas. This work would involve extending the 2009 Coffee Can soil and geophysical grid, data compilation of the other two targets, mechanical trenching at Ana Pass, followed by 3000 metres of drilling on all three targets.

Figure 1: Location Map



2. INTRODUCTION AND TERMS OF REFERENCE

This report is being undertaken by the author, a contractor working for Mincord Exploration Consultants Ltd. to describe the 2009 exploration program at Canadian Creek, and to interpret the results from that program. The report was completed for Alder Resources Ltd. and Cariboo Rose Resources Ltd. The author managed the 2009 field program and was on site for the drill programme and the last half of the geophysical survey.

3. RELIANCE ON OTHER EXPERTS

The author is not qualified to comment on legal, environmental, political or other issues that might be relevant to this report, and therefore does not address these issues.

4 PROPERTY DESCRIPTION AND LOCATION

Canadian Creek Claims

These are held by Eastfield Resources Ltd., a Yukon registered company, in trust for Cariboo Rose Resources Ltd. The claims are located in the Whitehorse Mining District, Yukon Territory, approximately 160 km south of Dawson City.

Table 1: Canadian Creek Claims List

Claim Name	Grant Number(s)	Expiry Date	Registered Owner
ANA 1-10	YA86735-YA86744	17-Feb-12	EASTFIELD Resources Ltd.
ANA 15-26	YA86749-YA86760	17-Feb-12	EASTFIELD Resources Ltd.
ANA 29-40	YA86763-YA86774	17-Feb-12	EASTFIELD Resources Ltd.
ANA 43-54	YA86777-YA86788	17-Feb-12	EASTFIELD Resources Ltd.
KOFFEE 1-58	YB37482-YB37539	21-Sep-13	EASTFIELD Resources Ltd.
AZTEC 1-10	YB37540-YB37549	21-Sep-13	EASTFIELD Resources Ltd.
MAYA 31-40	YB37622-YB37631	21-Sep-13	EASTFIELD Resources Ltd.
1CE 1-5	YB37801-YB37805	27-Jan-14	EASTFIELD Resources Ltd.
1CE 9-18	YB37809-YB37818	27-Jan-14	EASTFIELD Resources Ltd.
1CE 25-33	YB37825-YB37833	27-Jan-14	EASTFIELD Resources Ltd.
1CE 41-47	YB37841-YB378247	27-Jan-14	EASTFIELD Resources Ltd.
KANA 1-35	YC99879-YC99913	24-Jun-10	EASTFIELD Resources Ltd.
KANA F36-45	YC99914-YC99923	29-Sep-10	EASTFIELD Resources Ltd.

The Ana claims are subject to a 5% net profits interest in favour of Western Copper Corporation. GTO Resources Inc. (formerly Breckenridge Resources Ltd.) an earlier partner with Eastfield on the project, retains a diluting 14.97% working interest restricted to the Ana claims. Continuing dilution by GTO Resources Inc. is anticipated.

Casino “B” Claims

The Casino “B” claims (55 claims in total) are registered in the name of Copper Resources Corp. (through the amalgamation of Big Creek Resources Ltd. and Pacific Sentinel Resources Inc. by Great Basin Gold Ltd and subsequently sold to Western Copper Corporation and are under an option to Cariboo Rose Resources Ltd. The option

allows Cariboo Rose (formerly Wildrose Resources Ltd.) to earn a 100% interest in the claims by undertaking sufficient work to meet assessment work requirements on both the Casino "B" and 83 contiguous claims (the Casino "A" claims) until 2020. All of the claims constituting the Casino "A" and Casino "B" claims presently have sufficient work filed to keep them valid until at least March 25, 2012. The Casino "B' claims are subject to a 10% net profits interest in favour of Western Copper Corporation.

Table 2: Casino B Claims List

Claim Name	Grant Number(s)	Expiry Date	Registered Owner
CAS 31-36	YB36618-YB36623	25-Mar-12	Copper Resources Corp.
CAT 63-70	95740-95747	25-Mar-12	Copper Resources Corp.
E 23-25	YB37242-YB37244	25-Mar-12	Copper Resources Corp.
E 27-32	YB37246-YB37251	25-Mar-12	Copper Resources Corp.
F 27-28	YB37278-YB37279	25-Mar-12	Copper Resources Corp.
I 1-4	YB37640-YB37643	25-Mar-12	Copper Resources Corp.
I 19-20	YB37658-YB37659	25-Mar-12	Copper Resources Corp.
MOUSE 3-16	Y35194-Y35207	25-Mar-12	Copper Resources Corp.
MOUSE 89-90	Y35483-Y35484	25-Mar-12	Copper Resources Corp.
MOUSE 97-98	Y35491-Y35492	25-Mar-12	Copper Resources Corp.
MOUSE 123-128	Y35517-Y35522	25-Mar-12	Copper Resources Corp.


The surface area covered by all the Canadian Creek Claims (including the Casino "B" claims) is 5675 hectares.

There are no environmental problems or aboriginal issues known to the author specific to the Canadian Creek claims other than those that are general to the Yukon Territory and Canada.
A land-use permit issued by the Government of the Yukon is required to carry out exploration on the Canadian Creek property. Eastfield (in right of Cariboo Rose) currently holds a valid Class 3 Mining Land-use Permit, number LQ0061, which covers exploration, diamond-drilling, trenching, and road building on the Canadian Creek claims and the Casino "B" claims. This permit expires in 2011 and is in full compliance.

Alder Resources Ltd. has an option with Cariboo Rose Resources Ltd. that grants it the right to earn a 60% interest in the property by making cash payments totaling $250,000, making share issuances totaling 250,000 shares and completing exploration expenditures totaling $2,500,000 before June 18, 2013.

Assessment work requirements in the Yukon Territory require that exploration work in the amount of $100 per claim per year be completed. A filing fee of $5 per claim per year is also required. Excess expenditures incurred in any year can be filed up to an amount that moves the expiry date up to ten years into the future.

Figure 2: Claim Map



5. ACCESSIBILITY, CLIMATE, LOCAL RESOURCES, INFRASTRUCTURE AND PHYSIOGRAPHY

The Canadian Creek property consists of 245 contiguous claims in the Whitehorse Mining District, Yukon Territory. The property is located approximately 300 km northwest of Whitehorse and 160 kilometres south of Dawson City. The Canadian Creek claims vary in elevation from 1,000 metres (~3,300 feet) in the lower reaches of Canadian Creek and 700 metres (~2300 feet) in the lower reaches of Coffee Creek to a maximum elevation of about 1,650 metres (~5,400 feet) in the Ana Peak area north of the camp. Alpine grasses, moss and buckbrush dominate vegetation at the higher elevations while sparse stands of spruce cover the lower elevations. With the exception of the very highest elevations, topography is subdued, weathering has been recessive and outcrop is scarce. This area of the Yukon is one of the few regions in Canada not subjected to Pleistocene glaciation and as a result, it has undergone a long period of surface weathering, oxidation and surface leaching.

Outcrop on the property is generally restricted to the ridges. Much of the rest of the property is covered in caribou moss and large expanses of felsenmeer.

Field work on the Canadian Creek property is conducted out of a camp located in the Aztec Creek drainage in the south-central part of the property. Access is via roads from the Yukon River and an airstrip on the adjacent Casino property. The barge service, though necessary for large equipment and cheaper for large loads, is erratic. During 2009 supplies and personnel for the Canadian Creek project came in via air, though use was made of heavy equipment based at Casino that had been barged in by Kluane Drilling in 2008.

When it is operating the barge option consists of using a 65-tonYukon River barge from Minto or a 100-ton barge from Dawson City. A barge-landing site at the mouth of Britannia Creek connects to the Casino and Canadian Creek properties. Western Copper Corp. has upgraded this road during their extensive work programs at Casino over the last two years. The barge service, which mainly services placer mining operations on tributaries of the Yukon River, is somewhat erratic and as a result, costs and timing are difficult to predict. During the 2000 program costs averaged approximately $10,000 per trip each way. An alternate route to the property is via a winter road extending from the Mount Freegold Road approximately 90 kilometres to the southeast, though this route has not been used for many years.

Air transport to the property is availed by a landing strip on the adjacent Casino property. This strip which historically has handled aircraft up to DC-3 size, is road accessible from the Canadian Creek property. It is located 6.5 km east of the Canadian Creek camp and has been used extensively by past programs with personnel and supplies generally flown in from Whitehorse. The airstrip has been extensively upgraded by Western Copper and currently is able to safely land Otter, Caravan and Navajo aircraft. During 2009 Alkan Air Ltd., from Whitehorse, was used for air transport.

Helicopters are available in Whitehorse, Carmacks and Dawson City. The 2009 program at Canadian Creek was largely land based, but when required, helicopters were procured from Sonora Gulch, Thistle Creek or Casino.

The climate of this region is both semiarid and subarctic. The field season generally begins in May and extends until the end of September. Records indicate that precipitation for the closest weather station, at the village of Carmacks 120 kilometres to the southeast of the property, averages 25.4 cm (~10 inches) per year, predominantly falling in the summer.

The rolling nature of this landscape with its numerous broad, subsidiary valleys offers many options for the construction of surface facilities and tailings impoundment sites, and there are numerous sources of readily available water.

6. HISTORY

The Klondike Gold Rush of 1898 prompted the first prospecting the area, leading to the staking of the "Discovery" placer claim on Canadian Creek in 1911, immediately north of the Casino B claims of the current Canadian Creek property. The first recorded lode mineral claim in the area was staked in 1917. From the 1930's to the 1960's, the area was explored for placer gold, silver-lead-zinc veins and tungsten.

The "Bomber" silver-lead galena vein, two kilometres east of the Canadian Creek property near the Casino airstrip, was probably first staked in 1943. In the late 1960's development work was initiated and a total of nearly 400 tonnes of hand cobbed ore was shipped to the Trail smelter up to 1980.

In 1967 the porphyry potential of Patton Hill (largely occurring on the adjacent Casino property) was recognized and as a result the property holder, Casino Silver Mines Limited, was acquired by a syndicate which included Teck Corporation, the Brynelson Group and Quintana Minerals Corporation. Between 1967 and 1971 this group completed a major exploration program on the adjacent Casino deposit and a feasibility study was completed. A decline in metal prices led to a cessation in work in 1971. However, the discovery of the Casino deposit initiated a large amount of work to be carried out on adjacent areas, including that which is currently covered by the Canadian Creek claims.

In 1985 and 1986 Nordac Mining Corporation, using the technical services of Archer, Cathro & Associates, completed soil geochemical surveys in the Canadian Creek watershed (largely in the area now within the Casino "B" claims).

In 1985 Archer, Cathro & Associates optioned the Casino Silver Mines property and in 1991 vended this option into Big Creek Resources Ltd. In 1992 Pacific Sentinel Resources Ltd. amalgamated with both Big Creek Resources Ltd. and Casino Silver Mines Limited. Between 1991 and 1994 Big Creek and then Pacific Sentinel Gold Corp. expended approximately 20 million dollars on evaluating the Casino deposit. This work led to a pre-feasibility report that showed the deposit, while positive, would not return a satisfactory return on investment. At that time, only a small amount of work was directed at the Casino "B" claims, which are now the subject of a 100% option interest in favour of Cariboo Rose and are part of the current property.

In 1985 Archer, Cathro & Associates Ltd. also staked the Ana claims. Eastfield subsequently purchased these claims in 1992, and proceeded to stake the Koffee, Aztec, Maya and Ice claim blocks. In 1993, after assembling the property, Eastfield entered into

three separate options concerning three of the claim blocks (with Breckenridge Resources Ltd., Rockwealth International Resources Corp. and Canadian Comstock Explorations Ltd.). These options were responsible for approximately $550,000 in exploration funding before they were terminated in 1994. Exploration funded by these options in 1993 consisted of establishing initial exploration grids and the drilling of 6 diamond drill holes on the Ana claims and 1 drill hole on the Koffee claims.

The 1993-94 work was followed by extensive field programs in 1996, 1997 and 1999 which consisting of induced polarization (IP) surveys, road construction and mechanical trenching on the Ana, Koffee, Maya and Ice claims. These programs were completed preparatory to a 2000 diamond-drill program.

In June of 1996 Eastfield consolidated the 5 claim blocks into the Canadian Creek property and entered into an option agreement with Alexis Resources Ltd. (now Alexis Minerals Ltd.). In 1996 and 1997 Alexis expended approximately $450,000 completing surface surveys, trenching and road building. In 1997 Eastfield reorganized into Eastfield Resources Ltd. and Wildrose Resources Ltd. with the Canadian Creek property going to Wildrose.

In May of 2000 the Canadian Creek property was significantly expanded with the addition of 55 claims from Great Basin Gold Ltd. (In 1997 Pacific Sentinel Gold Corp. (later Pacific Sentinel Resources Inc.) was reorganized and renamed Great Basin Gold Ltd.). The new claims extended the property in an eastern and northeastern direction by approximately 1.5 kilometres to within 700 metres of the Casino deposit. Also in 2000 a twelve hole reconnaissance drill program (eleven holes reaching bedrock) totaling 2,066 metres was completed between July 9 and August 14. The year 2000 diamond-drill program was completed at a cost of $425,000.

In July 2003, a soil grid was established over an area of approximately 1.5 by 1.1 kilometres on the Casino “B” claims and a total of 343 soil samples were collected and analyzed. A robust, 900 metre by 600 metre, copper-gold-molybdenum soil anomaly was outlined which indicated that the area was prospective for both intrusion related gold and copper-gold-molybdenum mineralization similar to the adjacent Casino deposit. Approximately $45,000 was expended in the 2003 program.

In 2005, a small two man program was completed in which a number of silt and rock samples were collected to infill existing anomalies.

In 2006 a modest program consisting of minor grid extensions to the “Casino B” soil grid and surveying of drill holes and other features were completed in the Casino B grid and Koffee Areas.

In 2007 a diamond drill program consisting of five holes (879 metres total) was conducted in the Casino B area. The drilling encountered Paleozoic gneiss, Cretaceous Dawson Range Batholith granodiorite as well as dacite (“Patton Porphyry”), feldspar porphyry and heterolithic breccia of the Casino Complex. Encouraging gold results were received from this work; including 3.5 metres of 1.91g/t Au from CC-DDH-07-3 and

135.0 metres of 0.31gt Au, including 6.0 metres of 2.96g/t, from CC-DDH-07-04. The program was completed at a cost of $448,000.

In 2008 a program of satellite imagery “aster analysis” was completed on the claims at a cost of $8,783.

7. GEOLOGICAL SETTING

The Canadian Creek property lies within the Dawson Range Batholith at its northern contact with the Yukon Metamorphic Complex. Intrusives and breccias of the Casino complex are common in the eastern part of the property adjacent to the Casino deposit. The area lies within the Tintina Gold Province, situated between the significant gold occurrences of Mount Freegold and White Gold.

The oldest rocks on the area of the Canadian Creek Property are of the Yukon Metamorphic Complex which is composed of quartz-feldspar-mica schists and gneisses, with lesser quartzite, amphibolite and minor marble, of Paleozoic age. The most widespread rocks on the property are granodiorite, and lesser monzonite of the Creataceous Dawson Range Batholith, which are well exposed on Ana Peak and on the ridge south of Canadian Creek.

The Casino Complex intrusions, which host the porphyry mineralization on the adjacent Casino property, are generally recessive and not well exposed. These rocks consist of quartz monzonite varying to granodiorite and minor quartz diorite, along with a rhyodacitic unit known as the Patton Porphyry, and several varieties of breccia. Casino Complex rocks occur in a number of locations on the Canadian Creek Property; in the Ana Saddle, on the south side of the Canadian Creek valley on the Casino “B” claims and have been intersected in drill-holes in the Koffee bowl areas. A homolithic intrusion breccia, adjacent to a large area of rhyolitic to dacitic volcanics was exposed in excavator trenches in the Koffee Saddle in 1997. This intrusive breccia and volcanic unit are also included within the Casino Complex suite.

The Yukon Metamorphic Belt Complex and the Dawson Range (including Casino Suite) Belt are in east-west fault contact along the northern edge of the Canadian Creek claim block. This fault (related to the Big Creek fault system) represents a major bounding structure. The Coffee Can zone, where the 2009 grid work was focused, straddles this contact though it’s exact location is not evident in the field.

8. DEPOSIT TYPES

Several target types exist on the Canadian Creek property including; bulk tonnage intrusion related gold, structurally hosted gold and copper-gold molybdenum porphyry mineralization. A brief synopsis of the various target types is as follows:

Bulk Tonnage Intrusion Related Gold

Bulk tonnage style gold mineralization was first identified at the Casino “B” target in 1993 when an excavator trench exposed 40 metres of mineralized rock grading 0.57 g/t gold including 10 metres grading 1.69 g/t (Trench 9076-C). A diamond drill hole completed in 1993 (93-319) intersected 149.96 metres grading 0.49 g/t gold including 55.17 metres grading 0.72 g/t gold. In 2007 hole CC-DDH-07-04 intersected 135.0

metres grading 0.31 g/t gold. Gold mineralization occurs with pyrite and minor quartz veining in granodiorite and latite intrusives. A large area to the south, east and west of the target remains untested. This area is located in Canadian Creek near the eastern edge of the claims, adjacent to the Casino property.

Structurally Hosted Gold

This was the target of the 2009 exploration program at Canadian Creek, which is referred to as the Coffee Can zone. Results revealed a zone of gold-arsenic+/-antimony-bismuth in soil anomalies that is over four kilometres in length and open to the east. This area is underlain largely by quartz-feldspar-biotite gneiss with lesser intrusions of granodiorite. The 2009 drilling here discovered widespread anomalous gold mineralization associated with clay altered shears, sheeted pyrite veins and in quartz-carbonate veins. The geochemistry, geological setting and mineralization styles are all similar to the Underworld Resources' White Gold Property, 50 kilometres to the northwest, where drilling has returned intercepts such as 104.0 metres averaging 3.39g/t Au.


Copper-Gold-Molybdenum Porphyry Mineralization

Two regions of the Canadian Creek claim group contain a number of features that suggest continuations of the style of mineralization which typifies the Casino deposit located immediately to the east. The Casino deposit, owned by Western Copper Corporation, has a large global reserve (914 million tonnes grading 0.21% copper, 0.24 g/t gold and 0.02% Mo) for which a pre-feasibility report was published in 2008. The two areas of potential include the Casino B area on the east side of the property in Canadian Creek adjacent to the Casino property, and the Koffee area located approximately 4 kilometres further to the west. The Casino "B" target is defined by strong Cu, Mo and Au soil responses, a magnetic high and proximity to the Casino deposit located a mere 700 metres further to the east. The Koffee target, which has not had significant exploration since 2000, is defined by a very large induced polarization anomaly centered on a magnetic high and porphyry style alteration encountered in first pass drilling in 1993 and 2000 which included short intervals of economic grades. In addition to mineralization encountered in drill core, mineralized rubble containing as much as 3.25% copper has been sampled.

Copper-Gold-Molybdenum Porphyry Mineralization

Two regions of the Canadian Creek claim group contain a number of features that suggest continuations of the style of mineralization which typifies the Casino deposit located immediately to the east. The Casino deposit, owned by Western Copper Corporation, has a large global reserve (914 million tonnes grading 0.21% copper, 0.24 g/t gold and 0.02% Mo) for which a pre-feasibility report was published in 2008. The two areas of potential include the Casino B area on the east side of the property in Canadian Creek adjacent to the Casino property, and the Koffee area located approximately 4 kilometres further to the west. The Casino "B" target is defined by strong Cu, Mo and Au soil responses, a magnetic high and proximity to the Casino deposit located a mere 700 metres further to the east. The Koffee target, which has not had significant exploration since 2000, is defined by a very large induced polarization anomaly centered on a magnetic high and porphyry style alteration encountered in first pass drilling in 1993 and 2000 which included short intervals of economic grades. In addition to mineralization encountered in drill core, mineralized rubble containing as much as 3.25% copper has been sampled.

Figure 3: Regional Geology



9. MINERALIZATION

Mineralization on the Canadian Creek property is found in five main locations: 1) the "Casino B" Intrusion-Related Gold Target; 2) the "Coffee Can" Gold Arsenic Anomaly ; 3) the "Casino B" Porphyry Copper-Gold-Molybdenum Target; 4) the Koffee Bowl Porphyry Copper-Gold Target; and 5) the Ana Intrusive Breccia Target.

"Casino B" Intrusion-Related Gold Target

Bulk tonnage style gold mineralization was first identified at the Casino "B" target in 1993 when an excavator trench exposed 40 metres of mineralized rock grading 0.57g/t g/t gold including 10 metres grading 1.69 g/t. A diamond drill hole completed in 1993 (93-319) intersected 149.96 metres grading 0.49 g/t gold including 55.17 metres grading 0.72 g/t gold. In 2007 hole CC-DDH-07-04 intersected 135.0 metres grading 0.31 g/t gold. Gold mineralization occurs with pyrite and minor quartz veining in granodiorite and latite intrusives. A large area to the south, east and west of the target remains untested. These drill holes are located within a >50ppb Au in soil anomaly that is over 1.5 kilometres long and up to 1 kilometre wide. The area hosts strong copper and molybdenum soil anomalies as well.

2.) "Coffee Can" Target

This area is located in the northern part of the Canadian Creek property and hosts a four kilometre long zone of strong gold- arsenic +/- antimony and bismuth soil anomalies with local concentrations of bismuth and antimony. Grab samples of quartz vein material from this area have returned gold values up to 6.6g/t gold and 51g/t silver from pyrite and arsenopyrite bearing quartz veins. Results from the 2009 drilling revealed the presence of anomalous gold values in clay altered shears, sheeted pyrite veins and quartz carbonate veins in zones of strong sausserite, sericite and clay alteration. Drill highlights include to 3 metres of 1.1g/t gold in CC09-10, and 1.5 metres of 3.46g/t Au in CC09-08.

3.) "Casino B" Porphyry Copper-Gold-Molybdenum Target

A very strong total field magnetic anomaly exists in the swampy lowlands of the Canadian Creek valley. A similar feature corresponds directly to the Casino deposit. Hole 1994-323, located just beyond the south-western corner of the anomaly, intersected highly altered Patton Porphyry well mineralized with molybdenum through most of its length. Individual sample intervals in this hole contained up to 1550 ppm molybdenum. The magnetic anomaly down slope from this hole has never been drill tested. This area contains significant copper, molybdenum and gold in soil anomalies.

4.) Koffee Bowl Porphyry Copper-Gold Target

An open ended, 3000 metre by 2500 metre, chargeability anomaly (>20mv/V) occupies the heart of the Koffee target. A central zone of lower chargeability (1200 metres by 900 metres) occupies the centre of this feature creating a "donut" pattern. A strong total field magnetic anomaly occupies the centre of the donut and extends across to an area of higher chargeability response in a west southwesterly direction. Six holes defining an east-west drill fence have tested the centre of the donut (five completed in 2000 and one completed in 1993). Overburden averages 20 metres (66) feet for the 6 holes completed in the target. A seventh hole attempted in 2000 was abandoned in overburden at 81 metres (266 feet). All holes predominantly encountered granodiorite although Patton

Porphyry was cored in two holes in the centre of the drill fence (93-K-1 and CC2000-06) and in the most westerly hole (CC2000-04). Strong phyllic alteration (chlorite–sericite) with a strong quartz pyrite stockwork was encountered on the western edge of the drill fence while strong potassium-magnetite alteration and a quartz dominant vein stockwork was encountered in the centre and on the eastern side of the fence. Although no economic grade/intercepts were obtained, highly anomalous concentrations of copper and or molybdenum plus minor gold were encountered in the central holes such as CC2000-06 with 11.71 metres grading 0.30% copper and 0.02 g/t gold.

A prominent resistivity high exists on the northern edge of the "donut-hole" in an area where leached outcrop has been determined to be a microbreccia derived from quartz-monzonite. This resistivity target remains untested. A sample of silicified rubble sampled in 2001 from the northern region of this feature returned an analysis of 737 ppb gold and 508 ppm molybdenum.

A mineralized angular boulder was discovered approximately 300 metres east of hole CC2000-05 at the end of the 2000 program which consisted of a dark biotite-altered micro breccia containing a network of millimetre to centimetre scale malachite and chalcopyrite veinlets. It returned an assay of 3.25 % copper with minor gold and molybdenum, though follow up prospecting in 2009 failed to find either this boulder or any others. The source area for the boulder probably occurs upslope, possibly within the resistivity high. Much of the Koffee target remains untested.

5.) Ana Intrusive Breccia Target
Eastfield Resources Ltd. completed an initial six hole diamond drill program on the Ana claims in 1993. This drilling was designed to test geophysical and geochemical targets in an area where the original Casino exploration group had mapped "Casino Breccia" in the early 1970's. The first five of the 1993 drillholes; 93-A-1 to 93-A-5, intersected intervals of intrusive breccia up to 44 metres in thickness associated with anomalous concentrations of copper and gold. A petrographic study of samples from this drilling suggests that alteration style is increasing in intensity and in potassium content towards the east. Hole 93-06, the most eastward of the 1993 holes, intersected Patton Porphyry though its entire length (Patton Porphyry is diagnostic at the adjacent Casino deposit). The combination of intrusive breccia in proximity to Patton Porphyry is analogous to the geological setting at the Casino deposit. The vector of increasing alteration targets the area to the northeast and northwest of hole 93-A-5, an area that has not yet been drill tested. Hole 93-A-1 returned a 3.05 metre intercept grading 1.92 g/t gold and hole 93-A-5 returned a 6.0 metre intercept grading 0.54 g/t gold.

10. EXPLORATION

Exploration specific to the Canadian Creek area began with a claim-staking rush in 1969 that followed the discovery of the Casino copper porphyry deposit. Because of its proximity to the Casino property and its similar geological environment, the Canadian Creek area was quickly staked and various parts of the present property were covered by a number of preliminary ground surveys by several different companies. The following chronology is excerpted from Chapman and Garratt:
1969: The mid-western part of the property [Ana Claims] was staked as the Aztec claims and a copper soil geochemical survey was carried out [Operator not mentioned].

1969 - Archer, Cathro & Associates conducted a limited soil sampling program on the Zappa 1-8 claims in the head waters of Coffee Creek [Koffee Claims] which returned moderately anomalous copper and molybdenum results.

1970: Trans-Columbia Explorations Ltd. performed a soil geochemical survey over a large area west of the Casino deposit. Included within this survey was approximately 60% of the area covered by the present Ana and Koffee claims. Results outlined a strong copper-molybdenum anomaly in the headwaters of Coffee Creek [Koffee claims] that was coincident with the previously identified Archer, Cathro & Associates anomaly, and a separate copper anomaly trending east from Ana Peak [Ana claims].

1970: Brameda Resources carried out a program of mapping, IP, ground magnetometer, soil geochemistry and 49 BQ and NQ diamond drill holes and 35 rotary holes in the Casino area, east of the Canadian Creek property. Two of these diamond drill holes, referred to as D1 and D2, are believed to be on the Casino "B" claims, but no information is available to the author about this work.

1970: Colin Godwin mapped the eastern part of the Ana claims while working on the Casino Project and recognized Casino-style breccias on the Ana claims.

1986: Nordac Mining Corporation, again using the technical services of Archer, Cathro & Associates, expanded the 1985 grid [Ana claims] and collected an additional 250 soil samples which increased the size of the previously identified gold anomaly.

1993-2008: The recent phase of exploration on the property began in 1992 with the purchase of the Ana claims by Eastfield Resources Ltd. and the subsequent staking of the Koffee, Maya, Aztec and Ice claims in 1993. Mineral exploration commenced in 1993 and continued in 1994, 1996, 1997, 1999, 2000, 2001, 2003, 2005, 2006, 2007 and 2009. Much of this work entailed extensive geochemical and geophysical surveys, excavator trenching and road construction. Diamond drill program were completed in 1993, 2000, 2007 and 2009. The following list summarizes the predominant activities completed by Eastfield, Wildrose or Cariboo Rose between 1993 and 2009, and includes work done on claims that are no longer part of the Canadian Creek property.


Type of Work	**Amount of Work**
Induced Polarization Survey	75.0 line kilometres.
Magnetometer Survey	94.4 line kilometres.
Soil Surveys	2790 samples; (collected at varying intervals from 25-75 metres)
Diamond Drilling	40 holes totaling 5221 m
Road Construction	approximately 16.2 kilometres
Mechanical Trenching	approximately 100 trenches and pits, (many did not reach bedrock)
Remote Sensing	Aster Image of property and surrounding area

The 1993 exploration program was funded through three separate option agreements with Breckenridge Resources Ltd. [Ana claims], Rockwealth International Resources Corp. [Koffee claims] and Canadian Comstock Explorations Ltd. [Aztec, Maya claims] with Eastfield as operator. These options were responsible for approximately $550,000 in exploration funding before they were terminated in 1994. Exploration work was contracted to Mincord Exploration Consultants Ltd. while physical work was carried out by Bruce Cairns (Tintina Trenching Ltd.), geophysical surveys by Scott Geophysics Ltd., and diamond-drilling by E. Caron Diamond Drilling Ltd. The exploration program consisted of road building, geological mapping, rock and soil sampling along with ground magnetic and IP surveys and a 7-hole diamond-drill program.

The results of the surface surveys outlined a multi-element soil geochemical anomaly on the Ana claims, which measured 1.8 km by 1 km. The east end of this anomaly reportedly exhibits a high degree of correlation with the Casino soil geochemistry, and similarly the magnetic and IP results on the Ana claims reportedly tie in well with the Casino data. In the Coffee Creek area, the surface surveys outlined a large open-ended multi-element soil geochemical anomaly covering an area approximately 2 km in an east-west direction by 1 km north-south. This anomaly coincides with a magnetic high and an IP chargeability anomaly greater than 15 ^{mv}/v.

Several shallow trenches were excavated using a D-8 Cat that was brought in for road building and moving the drill. Of four trenches attempted in the Ana saddle, two succeeded in reaching bedrock at 1.5 to 3.0 metres depth. These trenches exposed pyrite and vuggy quartz-tourmaline veins in strongly phyllic-altered granodiorite. A chip sample (TR-2-2) of this material assayed 560 ppb gold and 40 ppm copper. Samples of float in this area have assayed higher gold values. Three trenches were excavated in the Koffee area, exposing highly anomalous regolith, which analyzed as high as 2327 ppm copper with 72 ppm molybdenum and 36 ppm gold (sample K-23). This seemingly high copper value was thought to be due to the presence of chalcocite since no sulphides had been visible in the sample (Chapman and Garratt, 1993-2, p.20). One prospecting grab sample, JC-K-16, returned a value of 280 ppb gold and this location became a focus of road building and drilling in subsequent programs. It was collected from a small topographic high near Coffee Creek with gossanous soil, which was visible from a distance (grid location: 11600W / 11700N). The sample was described as a “breccia: quartz-limonite-sericite-clay rock [with] vuggy quartz veins up to 1.5 cm wide, no visible sulphides”. Another intriguing pair of samples are: JC-K-22, described as “Quartz-monzonite: moderately silicified and clay altered [with] extensive hairline quartz tourmaline veinlets, trace - 2% disseminated pyrite”, and sample JC-K-23 described as “Soil: oxidized granodiorite / quartz monzonite regolith”; respectively these samples returned analyses of 344 ppm Cu, 180 ppb Au and 26 ppm Mo, and 2327 ppm Cu, 36 ppb Au and 72 ppm Mo, respectively (Chapman and Garratt, 1993-2, Appendix: Rock Sample Descriptions, p.3). These samples were collected in the Koffee area at grid location 10600W / 11575N. No further work was done in this area, which is referred to as the Koffee summit area

Figure. 4: Soil Grids



Several shallow trenches were excavated using a D-8 Cat that was brought in for road building and moving the drill. Of four trenches attempted in the Ana saddle, two succeeded in reaching bedrock at 1.5 to 3.0 metres depth. These trenches exposed pyrite and vuggy quartz-tourmaline veins in strongly phyllic-altered granodiorite. A chip sample (TR-2-2) of this material assayed 560 ppb gold and 40 ppm copper. Samples of float in this area have assayed higher gold values. Three trenches were excavated in the Koffee area, exposing highly anomalous regolith, which analyzed as high as 2327 ppm copper with 72 ppm molybdenum and 36 ppm gold (sample K-23). This seemingly high copper value was thought to be due to the presence of chalcocite since no sulphides had been visible in the sample (Chapman and Garratt, 1993-2, p.20). One prospecting grab sample, JC-K-16, returned a value of 280 ppb gold and this location became a focus of road building and drilling in subsequent programs. It was collected from a small topographic high near Coffee Creek with gossanous soil, which was visible from a distance (grid location: 11600W / 11700N). The sample was described as a "breccia: quartz-limonite-sericite-clay rock [with] vuggy quartz veins up to 1.5 cm wide, no visible sulphides". Another intriguing pair of samples are: JC-K-22, described as "Quartz-monzonite: moderately silicified and clay altered [with] extensive hairline quartz tourmaline veinlets, trace - 2% disseminated pyrite", and sample JC-K-23 described as "Soil: oxidized granodiorite / quartz monzonite regolith"; respectively these samples returned analyses of 344 ppm Cu, 180 ppb Au and 26 ppm Mo, and 2327 ppm Cu, 36 ppb Au and 72 ppm Mo, respectively (Chapman and Garratt, 1993-2, Appendix: Rock Sample Descriptions, p.3). These samples were collected in the Koffee area at grid location 10600W / 11575N. No further work was done in this area, which is referred to as the Koffee summit area.

The diamond-drill program in 1993 consisted of 6 holes (803.89 metres) in the Ana claims and one 46.65-metre hole in the Koffee claim area for a total of 7 holes (850.54 metres). The entire core drilled was HQ in size and the core remains stored on the property at the Canadian Creek camp location. Five of the six holes in the Ana claims and the one hole in the Koffee claims intersected favorable host rocks and alteration, and two of which (93-A-6 and 93-K-1) intersected a rock similar to the Patton Porphyry at Casino. With the exception of part of DDH 93-A-3, a short 41.77-metre hole in the Ana saddle, all core was split and assayed. The results of the 1993 diamond-drilling were mixed, with assays as high as 307 ppm copper and 1920 ppb gold over 3.05 metres being returned from DDH 93-A-1 (from 89.02 to 92.07 metres depth) but most intervals were weakly mineralized and returned only moderately anomalous copper and gold assays. It was concluded that the presence of Casino Complex intrusives and breccias form an east-west trending zone through the centre of the property [Ana claims] both on surface and in drill holes 93-A-1, 4, 5, and 6 appear to define a vector of increasing potassium alteration in an eastward direction.

The single hole in the Koffee area, DDH 93-K-1 was lost due to caving at 46.55 metres, but provided some very intriguing results. The upper 40 metres averaged approximately 500 ppm copper despite the "core" being frozen regolith. This hole was collared on the southern flank of a strong magnetic anomaly and falls within an area of high copper (225 ppm) and gold (36 ppb) soil geochemistry.

The work described in the reports by Chapman and Garratt, on the 1993 program is in the author's opinion truthful, factual and of high professional quality. Statements and analyses quoted in the report are substantiated by copies of assay certificates, drill-logs, sample descriptions and thin-section reports in the appendices. The program accomplished its stated objective.

Road construction proceeded through the summer of 1993 and by the end of the program; a rough road had been built from the Casino road network and airstrip to the Koffee claim area. The road construction and up-grading continued on a limited scale during the 1994 field season.

During the period 1992-1994 Pacific Sentinel Gold Corp. carried out a large exploration program on the adjacent Casino Property, including four holes drilled in 1994 in the area now known as the Casino "B" option claims. Hole 1994-319, drilled by Pacific Sentinel Gold Corporation on what in now the Casino "B" area intersected 150 metres averaging 0.49 g/t gold in the south central region of this target. The gold appears to be associated with a quartz-pyrite stockwork spatially related to a latite dyke and is found in both the latite and in the hosting granodiorite. It appears that the latite intrusive is striking east-west and dipping steeply to the south. Holes 1994-323 and 1994-325 encountered full-length intercepts of distinctive feldspar biotite porphyry considered to be a key and diagnostic unit at the adjacent Casino deposit. This unit, named "Patton Porphyry", was well altered in both holes but copper mineralization was weak. Hole 1994-323 had consistent high molybdenum values with individual 3 metre samples returning up to 1555 ppm Mo. This hole and hole 1994-325 contained a number of erratic gold values, with values reaching 0.38 g/t Au in hole 1994-323 and 0.25 g/t in hole 1994-325. Latite was not intersected in holes 1994-323, 325 and 328. Both target types remain open.

In 1996 Eastfield consolidated the Ana, Koffee, Aztec, Maya and ICE claim groups into the Canadian Creek property and optioned it to a private company, Alexis Resources Ltd. (now Alexis Minerals Corporation). In July and August of 1996, Alexis funded a $240,000 field program which was contracted to Mincord Exploration Consultants Ltd. with Geophysical surveys carried out by Scott Geophysics Ltd. and physical work contracted to Bruce Cairns (Tintina Trenching Ltd.) The 1996 program included road construction and improvement, mechanical trenching, soil sampling, geological mapping and limited ground magnetic geophysical surveys. A total of 2 km of new access road was built, 3 km of existing road was upgraded and 1 km of drill access trail was stripped for thawing. Approximately 13.3 km of new north-south grid lines were flagged for a total grid on the property of approximately 75 km. A total of 164 soil samples were taken on the new grid lines, and 18.8 km of IP and ground magnetics completed on the new grid, along with two infill lines on grid lines 102+00W and 110+00W to improve definition in this area. An excavator was utilized to dig 76 trenches and 8 test pits. In addition, 6 of the 7 pits dug in 1993 were enlarged or deepened. A total of 184 rock samples were collected and analyzed. The trenching program was able to augment the data collected for geological mapping and provide samples for rock and soil geochemistry. However, the large number of trenches (76) and pits (8) reflects the difficulty in penetrating the permafrost and the resulting low success rate of reaching bedrock within the first half metre of the surface. The problem was compounded by the great depth of Tertiary weathering present on the property, and the active solifluction

which takes place in the zone of thawed ground with the result that it is difficult to determine if the material exposed is regolith or weathered bedrock, and if regolith, is it transported or in place? The rock and soil geochemical surveys identified anomalies in gold, copper and arsenic-silver in several different locations on the property.

A gold anomaly (analysis > 40 ppb) in the Koffee area was identified as extending from 1200 N / 11000 W to 11200 N / 11800 W and is coincident with a magnetic high, chargeability low and weak resistivity high. This was interpreted as suggesting a buried intrusive centre (Lindinger, 1996 ;). Gold anomalies were noted to be concentrated in the 20 – 40 millivolt/volt chargeability zone, with a weaker concentration in the 200 to 500 ohm-metre resistivity zone, and in high magnetic gradient areas between moderately strong magnetic highs and lows. This was noted to be especially true in the west end of Canadian Creek where existing gold anomalies were confirmed but not extended. Two large copper anomalies (Cu analysis > 40 ppm) were identified on the Canadian Creek property. On the Ana claims a broad anomaly covers the south and west portions of the Canadian Creek valley and continues onto the Casino "B" claims. Two higher-grade areas, with copper values in excess of 80 ppm cover Ana Peak and the other extends northeasterly for 1.5 km along the south side of Canadian Creek. In the Koffee area, a broad copper anomaly is centred at 11700 N / 11000 W in the upper Coffee Creek drainage and extends approximately 800 metres to the northwest and southeast. There appears to be a correlation between weakly anomalous gold soil geochemistry and anomalous copper soil geochemistry. The northeast quarter of the Koffee grid and the northwest side of the Ana grid both contain elevated values of arsenic (As analysis > 100 ppm) and silver (Ag analysis > 2 ppm) in soils. This area is underlain by Yukon Metamorphic Complex rocks, which although mostly gneiss, also include meta-diorite, quartzite, skarned limestone and marl. It is cross-cut by northeast striking quartz monzonite and quartz diorite dykes.

Trenching and surface mapping in the Koffee area identified a large phyllic alteration zone in quartz diorite of the Koffee Creek stock. The rocks are moderately well silicified with feldspars altered to clays and sericite, and biotite to muscovite. The dominant sulfide is crystalline disseminated and fracture-controlled pyrite. Fracture sets are generally oriented north-northwest with a steep easterly dip. Larger structures with this orientation commonly have been intruded by late-stage crowded quartz porphyry feldspar dykes.

In the Ana saddle area trenching partly exposed a 600 m by 150m east-northeast striking quartz monzonite breccia body striking from 11000 N / 8300 W to 11200 N / 7700 W, which contains lithological, and alteration characteristics similar to the Casino deposit located 5 km to the east, including leucocratic quartz monzonite, quartz monzonitic homolithic breccias, rocks resembling "microbreccia", and rocks resembling at least 3 phases of "Patton Porphyry" (Lindinger, 1996). Some of the breccias were noted as altered to a characteristic light brown to dirty yellow colour similar to the Casino breccia. Toward the east end of the Ana saddle a swarm of north-northwest striking faults hosts several phases of the Patton Porphyry and an associated limonitic gouge zone exposed in Trench 96-59 (located at 11000 N / 7600 W) analysed 1340 ppb gold (sample # TRENCH 50C) over 6 metres.

In 1997,Alexis Resources Ltd., then a private company, funded a $240,000 program of road construction, stripping, and drill-site preparation. Management and fieldwork were contracted to Mincord Exploration Consultants Ltd. and physical work was carried out by Landmark Management Ltd. of Whitehorse. A total of 2.1 km of new road were constructed and 3.6 km of existing road rebuilt and ditched. Twelve drill pads were completed and an additional 20 sites stripped along Coffee Creek to allow permafrost to thaw for future trenching. Approximately 620 m of stripping was carried out around a new sulfide stockwork zone named the "Creek Zone" at the end of the Koffee road extension. A plywood storage building was constructed at the camp site to better store equipment on the site between field programs. Also, during the road construction 84 rock and 129 soil samples were collected and were stored pending an assay budget.

In 1999, a small program (costing $19,875) funded by Alexis was contracted to Bruce Cairns (Landmark Management Ltd.) and supervised by Mincord Exploration Consultants Ltd. Fifty-two hours of D-6 bulldozer time was devoted to road maintenance and re-contouring of road cuts and disturbed areas that dated from activity in 1996 and 1997. Nine grab samples of altered intrusive and quartz veining were collected during the reclamation work and submitted along with 84 rock and 129 soil samples collected during road construction in 1997. The analytical results confirmed the presence of geochemical anomalies known from previous programs. A thin section of a boulder collected at the Creek Zone (Koffee claims) [in 1997] was described as a "highly phyllic altered and carbonatized quartz diorite" with a trace of free gold noted.

In 2000, Alexis funded a $425,717 diamond-drill program on the Canadian Creek property (which now included 55 claims of the Casino "B" option) with a total of 2,066 metres drilled in 12 holes (eleven of which reached bedrock). Project management, personnel and camp equipment was contracted to Mincord Exploration Consultants Ltd. Major Drilling Ltd. of Smithers BC provided a Longyear 38 drill, drilling NQ core. The drill was mobilized from Britannia Landing on the Yukon River and moved between drill sites by a bulldozer provided by Tintina Trenching of Whitehorse. Big Salmon Air of Whitehorse provided necessary fixed wing air services using the gravel airstrip at Casino.

In the Koffee area five diamond drill holes (1152.5 metres) were completed in an east-west drill fence across the centre of a significant donut shaped induced polarization and magnetic anomaly (3 km by 2 km> 20mv/V). A strong pyrite dominant stockwork was discovered on the west end of the drill fence which progressed into a strong quartz dominant stockwork on the east end of the fence. A strong potassium-enriched and magnetite-rich centre corresponds to holes CC2000-6, 7 and 9 drilled within the geophysical donut towards the east end of the anomaly. The style of alteration was noted to progress from phyllic in holes CC2000-4 and 5 at the western end of the drill fence into a more potassic-style of alteration in holes CC2000-6, 7 and 9 toward the eastern end of the drill fence. A distinctive feldspar porphyry, very similar to the Patton Porphyry at Casino, locally intrudes the granodiorite in this eastern end of the drill fence. The best intersection was in hole CC2000-6 where 11.7 metres (between 49.9 and 61.6 metres depth) averaged 0.29% copper with only a trace of gold, within which 2.9 metres (between 49.86 to 52.73 metres) returned an analysis of 4829 ppm copper and 17 ppb gold.

In the Ana claim area, two holes, numbered CC2000-3 and CC2000-10, were drilled for a total footage of 300.2 metres. Both holes were spotted in areas of anomalous soil and rock geochemistry. Hole CC2000-3 penetrated a structurally broken-up, limonite-rich zone with little visible sulphide and poor geochemistry. Hole CC2000-10 was drilled through weak to moderately sericite altered quartz diorite and granodiorite that was weakly mineralized with minor pyrite and chalcopyrite, but when analysed was found to contain anomalous copper geochemistry (Cu> 200 ppm) through most of its length.

Diamond-drilling in the Casino "B" option ground consisted of 4 holes (CC2000-1, 2, 11, 12) for a total of 531.6 metres. The first hole drilled in the program, CC2000-01 was designed to follow up Pacific Sentinel Gold's hole 1994-319 which had intersected 159.96 metres averaging 0.49 g/t gold including 55.17 metres averaging 0.72 g/t. In 2000Alexis, drilling 40 metres to the north, intersected 25.75 metres grading 1.04 g/t gold from 18.5 metres to 44.2 metres in hole CC2000-1. This hole ended in mineralization at 118.87 metres with the last 30 metres averaging 0.52 g/t gold. Hole CC2000-11, located approximately 250 metres west of CC2000-01, contained numerous anomalous sample intervals (generally ~3 metres each) with gold values as high as 965 ppb. In hole CC2000-11 a much fresher granodiorite than that intersected in CC2000-01 and 1994-319 was encountered and the latite intrusive found in holes 1994-319 and CC2000-01 was absent. The fresher character of the intrusive in CC2000-11 allows anomalous intervals to be directly correlated to the presence of quartz vein stockwork. It is quite possible that the western extension of mineralization has been offset to the south although this has yet to be tested.

Near the end of the 2000 program, field crews discovered a mineralized angular boulder in the Koffee target area. This material, which consists of a dark, biotite-altered micro breccia, is mineralized by a network of millimetre to centimetre scale malachite and chalcopyrite veinlets. The material is high grade and returned an assay of 3.25 % copper with minor gold and molybdenum. The source area for the mineralized boulder is interpreted to occur upslope within or on the edge of the large (4 kilometre by 2 kilometres) chargeability anomaly. A prominent resistively high occurring within the edge of the anomaly remains a prime target area for the source. The inferred source for these mineralized boulders lies within ground controlled by Cariboo Rose.

In 2001, a short program of prospecting, reclamation and demobilisation, costing approximately $21,000 was carried out on the Canadian Creek Property. The objective of the 2001 program was to conduct more general surface geochemical and prospecting work outbound from areas drill tested in 1993, 1994 and 2000 (areas previously overlooked because of budget constraints). Prospecting and rock sampling was focused in two areas; in the area east of drill hole CC2000-01, and in the central-eastern side of the large induced polarization anomaly located in the Koffee bowl. Time constraints compromised the time spent in the Koffee Bowl, and no further pieces of high-grade rubble were located. In the Casino "B" option area traces of the 1986 Archer, Cathro & Associates grid were located and were tied into the Ana grid to allow the different data sets to be merged. Reconnaissance soil sampling was carried out across this area, with the results confirming copper and gold geochemical anomalies previously identified by Archer, Cathro & Associates.

In 2003 a small geochemical program costing $45,000 was completed in the eastern region of the property called the Casino “B” claims area. A soil grid was established over an area of approximately 1.5 by 1.1 kilometres. A total of 343 soil samples were collected and analyzed. The results of this work define a robust, 900 metre by 600 metre, copper-gold-molybdenum soil anomaly.

In 2005 a small program consisting of a two man prospecting team completed additional rock, silt and soil sampling in the Ana and Koffee target areas.

In August 2006 a modest program consisting of minor grid extensions to the “Casino B” soil grid and surveying of drill holes and other features were completed in the “Casino B” and Koffee grid areas. The results of the 2006 soil geochemical program confirmed known soil anomalies identified in 2003.

In 2007 a diamond drill program consisting of five holes (879 metres total) was conducted in the Casino B area. The drilling was done by Beaudoin Diamond Drilling, using a fly rig that was finishing work at the nearby Idaho Creek property. The rig was flown by helicopter to Canadian Creek, and later flown by fixed wing out to Minto after the job was over. Helicopter support for the drilling was done by Fireweed Helicopters and Heli Dynamics Ltd., of Whitehorse. Supplies, camp and personnel were flown into Casino airstrip from Whitehorse by Alkan Air Ltd.

Though the drill moves were carried out by helicopter, shift changes were done by quad or on foot, resulting in significant cost saving. Work was conducted out of the Mincord Exploration camp located in the Aztec Creek drainage. As with the previous programs, the drill core was logged and split and stored here at the end of the job.

The drilling encountered Paleozoic gneiss, Cretaceous Dawson Range Batholith granodiorite as well as dacite (“Patton Porphyry”), feldspar porphyry and heterolithic breccia of the Casino Complex. Some interesting gold results were received from this work; including 3.5 metres of 1.91g/t Au from CC-DDH-07-3 and 135.0 metres of 0.31gt Au, including 6.0 metres of 2.96g/t, from CC-DDH-07-04. The program was completed at a cost of $448,000.

In 2008 a remote sensing “Aster image” program was completed and is included here in some detail:
Aster Satellite Iron Oxide Alteration:
1.) An area of iron oxide alteration covering an area of approximately 400 metres by 200 metres occurs immediately north of the camp centered at 606000E, 6956560N (NAD 83).
2.) An area of iron oxide alteration covering an area of approximately 1000 metres by 400 metres occurs and trends off the northwestern boundary of the Ana claims. This area has a centre at approximately 606200E, 6959200N (NAD 83).
3.) A small area of well defined iron oxide alteration occurs on the western end of the Koffee road at drill site 00-04, 603000E, 6957400N (NAD 83). Outcrop in this area consist of gossanous quartz diorite to granodiorite hosting a well developed sulphide stockwork.

4.) A small area of well defined iron oxide alteration occurs on the northern branch of the Koffee road at 603600E, 6958200N (NAD 83). The feature compares favorably with #3, located 800 kilometres distant. It requires field checking.

Aster Satellite Alunite Alteration:
5.) An area of probable alunite alteration occurs to the north of the access road and south of hole 1994-328 over an extent of approximately 1000 metres.
6.) An area of probable alunite alteration occurs to the north of drill holes 93-01, 93-02 and 93-03 and continues as far north as the access road.
7.) An area of probable alunite alteration occurs along the slope of the ridge located to the north of the camp that trends southeasterly to the claim boundary covering and area of approximately three kilometres by one kilometre. Alunite has not previously been documented in this area which contains abundant rubble. A sedimentary origin to the alunite in quartzite and sandstone which makes up some of this rubble is conceivable.

Aster Satellite Sericite Alteration:
8.) An area of probable sericite alteration covering an area of approximately 400 metres by 400 metres in the bottom of Canadian Creek roughly 500 metres northwest of hole 1994-323 and 500 metres northeast of hole 00-10 at 608000E, 6958200N (NAD 83). A similar feature covers a small area of the eastern side of the Casino deposit (which is not cloud covered here) approximately 3 kilometres to the east.

2009 Exploration Program
In 2009 a major exploration program was carried out on the Canadian Creek property, focusing on an area in the northern part of the property which has been named the "Coffee Can" Zone. The work consisted of grid, emplacement, soil sampling, an IP-magnetometer geophysical survey, and diamond drilling. The work commenced on July 9 and the last of the crew flew out to Whitehorse on September 28.

The target was an arsenic in soil anomaly from the 1993 survey that was located northeast of Koffee Bowl and extended off the north side of the grid. Work in 1993 also discovered a sample of quartz vein float that retuned a gold value of 6.6g/t in this same area. In June of 2009, new claims ("Kana 1-35") were staked to cover the projected east-northeast extension of this anomaly. Work on this target was initiated in response to the announcement, earlier in 2009, of impressive gold mineralization at Underworld Resources' White Gold project, located 50 kilometres to the northwest, which has a similar geochemical signature and is hosted in the same suite of rocks as at Canadian Creek.

As with most of the programs conducted on the Canadian Creek property, the work was conducted out of the 1993 camp located in the Aztec Creek drainage. The 2009 program was initiated in early July with the refurbishing of the camp and upgrading of roads using equipment that was based at Casino airstrip. Western Copper Corp, carried out a major exploration program on the Casino property in 2009 and had a large camp at Casino airstrip.

Camp gear, supplies and personnel were flown in from Whitehorse to Casino airstrip where these were moved by road to camp. Alkan Air supplied the flying services in 2009

and were most helpful and efficient. The airstrip has been upgraded by Western Copper and is now able to land Otters, Caravans, and Navajos.

Filed work was accessed by quads or on foot by a crew that varied in size from 7-10 people. For safety and efficiency reasons a repeater was installed on Ana Peak giving good radio communication across the property, and a telephone-internet satellite dish array was set up in camp.

2009 Grid work
A total of 29.9 kilometres of grid was emplaced during 2009, covering part of the 1993 Koffee grid and extending to the east and north. Start and end points were located by GPS and the lines were compassed, and brushed out as necessary. Twenty five metre stations were emplaced using tight chain and were marked with inscribed aluminum tags stapled to pickets.

2009 Soil Geochemistry
The western part of the Yukon, which includes the Canadian Creek property area was not glaciated during the latest continental event and had resulted in deep leaching of the soils. As a result soil anomalies in these areas tend to be subtler than would be expected under normal conditions.

Soil samples were collected along the lines in areas north of the previous grids. Samples were collected at the 25 metre stations using hand augers, which were able to penetrate deeper into the subsurface than was practical using mattock or shovel. A total of 1126 samples were collected on the grid, while a further 40 were taken on reconnaissance lines. Twenty-eight of these reconnaissance samples were taken from areas outside of the Canadian Creek claims. One line was resampled over the area of the old Koffee grid as a check of the old data and to compare the 2009 auger sampling method with the 1993 mattock approach. The results matched well, confirming the validity of the old data.

Results from the soil sampling revealed a 6.5 kilometre long zone across the north side of the property that hosts large areas of >20ppb gold in soil. This area includes the 2009 samples as well as those from the northern part of the 1993 Koffee grid. Anomalous arsenic in soils coincides with the anomalous gold in soils across this area, and is accompanied by anomalous antimony and bismuth in the eastern areas. A very strong antinomy-molybdenum anomaly occurs in the Ana Peak area, south of the anomalous gold in soil areas.

The strongest part of the Coffee Can zone is to the east where two separate areas of strongly anomalous Au in soils occur. The larger of these is at the southern part of the 2009 grid where linear, east-northeast trending >50ppb Au in soil anomalies remain open to the east past the limits of the 2009 sampling. This area is also underlain by discrete chargeability highs. The largest of these zones extends for over 1400 metres, with individual results returning as high as 2287ppb Au. This zone was tested by drill holes C09-05, 06 and 07.

A separate gold in soil anomaly occurs at the north end of the easternmost lines in the area of another discrete chargeability high. The final three holes of the 2009 program; CC09-08-10, were drilled here.

Copper shows up as a weakly anomalous zone along the southern edge of the eastern part of the 2009 grid, due possibly to the areas' proximity to the Casino deposit, but is also coincidental with the largest of the 50ppb Au in soil anomalies. Molybdenum is low throughout the area of the 2009 sampling except for the Ana Peak area, where it is coincident with a prominent high antinomy in soil anomaly.

The eastern part of the Coffee Can zone 20ppb gold in soil anomaly connects with the large gold anomaly in Canadian Creek in the Casino B and Ana areas to the south, which also contain extensive areas of >50ppb gold in soils. The Canadian Creek area is also strongly anomalous in copper and molybdenum while arsenic is only sporadically anomalous. Antimony and bismuth were only analyzed for in a minority of the Casino B soil sampling, but do appear to be anomalous there.

A small amount of reconnaissance soil sampling was undertaken away form the main 2009 grid. One sample line was run north from the 2009 grid area north to the newly staked "Sugar" claims, though nothing anomalous was encountered here. The other area was off the northwest corner of the Canadian Creek property where more ridge sampling was carried out. One 21ppb Au soil value was obtained from here at 601480/6960980.

2009 Geophysical Survey
Induced polarization (IP) and magnetometer surveys were performed at the Canadian Creek Property within the period August 6-28, 2009 by Scott Geophysics Ltd. of Vancouver. The following summary of the survey is taken from the Scott report.

A total of 29.9 km of IP and magnetometer surveys were performed at the Canadian Creek Property. The pole-dipole array was used for the IP survey with an "a" spacing of 25 metres at "n" separations of 1 to 3 plus an "a" spacing of 50m at "n" separations of 2 to 4. The on line current electrode was to the south of the potential electrodes on all survey lines.

A GDD Rx8 receiver and a GDD TxII transmitter were used for the IP survey. Readings were taken in the time domain using a 2 second on/2 second off alternating square wave. The chargeability values plotted on the accompanying pseudosections and plan maps is for the interval 690 to 1050 millisecs after shutoff. A Scintrex ENVI was used for the magnetometer survey. All data was corrected for diurnal drift with reference to a Scintrex ENVI base station cycling at 10 second intervals.

A plot of the chargeability shows a significant northwest trending break that runs northwest from the south end of line 8400W. East of this occurs a large east-west trending chargeability high that runs form Ana Peak west to the Koffee area. Hole CC09-01, was located on the northern edge of this, also targeting a east-west >50ppb Au in soil anomaly.

Property Boundary

Western
Copper Claims

Casino
Proposed Pit

1994-328
114.91m

93-A-4
(152.44m)

93-A-1
(152.44m)

93-A-5
(152.44m)

93-A-6
(152.44m)

93-A-2
(152.44m)

93-A-3
41.77m

93-K-1
(46.5m)

CC2000-4
(251.46m)

CC2000-5
(171.6m)

CC2000-8
(81m)

CC2000-6
(219.15m)

CC2000-9
(255.12m)

CC2000-7
(255.12m)

CC2000-3
(99.06m)

CC2000-10
(201.17m)

CC2000-12
(102.72m)

CC2000-11
(151.87m)

CC-DDH-07-04
(240.79m)

CC-DDH-07-03
(208.48m)

CC2000-2
(152.4m)

CC09-01

CC09-02

CC09-03

CC09-04

CC09-05

CC09-06

CC09-07

CC09-08

CC09-09

CC09-10

2009 Rock samples - Au (ppb)

▲	>500	(9)
△	100 to 500	(23)
△	0 to 100	(130)

1993 Rock Samples - Au (ppb)

▲	500 to 10,000	(5)
△	100 to 500	(16)
△	0 to 100	(39)

2009 Soil Grid - Au (ppb)

>100	
50	to 100
20	to 50
<20	

Historic soil grid - Au (ppb)

>100	
50	to 100
20	to 50
<20	

0 100 200 300 500
metres

Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

Soil and Rock Geochemistry Au (ppb)

Scale:	1:10,000	UTM	UTM zone 7 - NAD83
Date:	Nov 16, 2009	NTS	115J/10,11,14,15
By:	MJD	File	CanCk_10Kbase

Fig 5

Property Boundary

Western
Copper Claims

Casino
Proposed Pit

1994-328
114.91m

1994-323
(118.67m)

1994-324
(131.67m)

1994-326
(152.4m)

1994-327
(166.12m)

CC2000-2
(152.4m)

CC2000-3
(99.06m)

CC2000-4
(251.46m)

CC2000-5
(171.6m)

CC2000-6
(219.15m)

CC2000-7
(255.12m)

CC2000-8
(81m)

CC2000-9
(255.12m)

CC2000-10
(201.17m)

CC2000-12
(102.72m)

CC-DDH-07-01
(118.87m)

CC-DDH-07-02
(240.79m)

CC-DDH-07-03
(208.48m)

CC-DDH-07-04
(240.79m)

93-A-1
(152.44m)

93-A-2
(152.44m)

93-A-3
(152.44m)

93-A-4
(152.44m)

93-A-5
(152.44m)

93-A-6
(152.44m)

93-K-1
(46.5m)

1499.7

41.77m

6961000 mN
6960000 mN
6959000 mN
6958000 mN
6957000 mN
6956000 mN
6955000 mN

603000 mE
604000 mE
605000 mE
606000 mE
607000 mE
608000 mE
609000 mE
610000 mE
611000 mE
612000 mE

2009 Rock samples - As (ppm)

>200		(9)
100	to 200	(7)
0	to 100	(146)

2009 Soil grid - As (ppm

>200		(264)
100	to 200	(262)
0	to 100	(639)

Historic soil grids - As (ppm)

>200		(90)
100	to 200	(115)
0	to 100	(1370)


Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

Soil and Rock Geochemistry As (ppm)

Scale:	1:10,000	UTM	UTM zone 7 - NAD83
Date:	Nov 16, 2009	NTS	115J/10,11,14,15
By:	MJD	File	CanCk_10KassMaps

Fig 6


Property Boundary
Western
Copper Claims
Casino
Proposed Pit
93-A-1
(152.44m)
93-A-2
(152.44m)
93-A-3
41.77m
93-A-4
(152.44m)
93-A-5
(152.44m)
93-A-6
(152.44m)
93-K-1
(46.5m)
CC2000-3
(99.06m)
CC2000-4
(251.46m)
CC2000-5
(171.6m)
CC2000-6
(219.15m)
CC2000-7
(255.12m)
CC2000-8
(81m)
CC2000-9
(255.12m)
CC2000-10
(201.17m)
CC2000-11
(152.4m)
CC2000-12
(102.72m)
CC2000-2
(152.4m)
CC2000-1
(118.87m)
CC-DDH-07-04
(207.9m)
CC-DDH#97-01
(208.48m)
CC-DDH-05-01
(166.12m)
CC-DDH-09-02
(152.4m)
1994-328
114.91m
1994-323
(150.5m)
1994-329 (152.4m)
1994-330
(121.92m)
CC09-01
CC09-02
CC09-03
CC09-04
CC09-05
CC09-06
CC09-07
CC09-08
CC09-09
CC09-10
2009 Rock samples - Sb (ppm)
>20
6 to 20
3 to 6
0 to 3
2009 soil grid - Sb (ppm)
>20
6 to 20
3 to 6
0 to 3
Historic soil grid - Sb (ppm)
>20
6 to 20
3 to 6
0.25 to 3
no data
0 100 200 300 500
metres
Cariboo Rose Resources Ltd.
Alder Resources Ltd.
Canadian Creek Property
Soil and Rock Geochemistry
Sb (ppm)
Scale: 1:10,000
Date: Nov 17, 2009
By: MJD
UTM UTM zone 7 - NAD83
NTS 115J/10,11,14,15
File CanCk_10KassMaps
Fig 7

Property Boundary

Western
Copper Claims

Casino
Proposed Pit

CC2000-4
(251.46m)

CC2000-5
(171.6m)

CC2000-8
(81m)

CC2000-6
(219.15m)

CC2000-1
(255.12m)

CC2000-7
(255.12m)

93-K-1
(46.5m)

CC09-01

93-A-4
(152.44m)

93-A-1
(152.44m)

93-A-5
(152.44m)

93-A-6
(152.44m)

93-A-2
(152.44m)

93-A-3
41.77m

CC2000-10
(201.17m)

CC2000-3
(99.06m)

CC09-09

CC09-10

CC09-08

CC09-06

CC09-07

CC09-05

CC09-02

CC09-03

CC09-04

1994-328
114.91m

CC-DDH-05-01
(166.12m)

1994-323
(150.6m)

CC2000-2
(152.4m)

1994-329
(121.92m)

CC2000-9
(118.87m)

1994-330 (152.4m)

CC2000-12
(102.72m)

CC2000-11
(152.4m)

CC-DDH-07-05
(127.76m)

CC-DDH-07-04
(207.9m)

CC-DDH-07-02
(152.4m)

CC-DDH-07-03
(208.48m)

CC2000-13
(152.4m)

10.9

Historic soil grid - Bi (ppm)
- >25
- 10 to 25
- 3 to 10
- 0 to 3
- no data

2009 soil grid - Bi (ppm)
- >25
- 10 to 25
- 3 to 10
- 0 to 3

2009 rock samples - Bi (ppm)
- >25
- 10 to 25
- 3 to 10
- 0 to 3

0 100 200 300 500
metres

Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

Soil and Rock Geochemistry
Bi (ppm)

Scale:	1:10,000	UTM	UTM zone 7 - NAD83	Fig
Date:	Nov 17, 2009	NTS	115J/10,11,14,15	8
By:	MJD	File	CanCk_10KassMaps	

Property Boundary

Western
Copper Claims

Casino
Proposed Pit

1994-328
114.91m

CC2000-8
(81m)

CC2000-6
(219.15m)

CC2000-4
(251.46m)

CC2000-5
(171.6m)

CC2000-9
(255.12m)

CC2000-7
(255.12m)

93-K-1
(46.5m)

CC2000-3
(99.06m)

93-A-1
(152.44m)

93-A-2
(152.44m)

93-A-3
(152.44m)

93-A-4
(152.44m)

93-A-5
(152.44m)

93-A-6
(152.44m)

CC2000-10
(201.17m)

CC2000-12
(102.72m)

CC-DDH-07-01
(166.12m)

CC-DDH-07-02
(152.4m)

CC-DDH-07-03
(200.46m)

CC-DDH-07-04
(240.79m)

CC-DDH-07-05
(118.87m)

CC-DDH-07-06
(131.67m)

1994-323
(115.82m)

1994-324
(152.4m)

1994-325
(152.4m)

1994-326
(152.4m)

1994-327
(152.4m)

CC2000-1
(120.7m)

CC2000-2
(152.4m)

CC-DDH-07-07
(120.7m)

CC-DDH-07-08
(120.7m)

CC-DDH-07-09
(120.7m)

CC09-01

CC09-02

CC09-03

CC09-04

CC09-05

CC09-06

CC09-07

CC09-08

CC09-09

CC09-10

6961000 mN
6960000 mN
6959000 mN
6958000 mN
6957000 mN
6956000 mN
6955000 mN

604000 mE
605000 mE
606000 mE
607000 mE
608000 mE
609000 mE
610000 mE
611000 mE
612000 mE

1993 Rock samples - Cu (ppm)
- >200
- 100 to 200
- 50 to 100
- <50

2009 Rock samples - Cu (ppm)
- >200
- 100 to 200
- 50 to 100
- <50

2009 Soil grid Cu (ppm)
- >200 (5)
- 100 to 200 (13)
- 50 to 100 (134)
- <50 (1013)

Historic soil grid - Cu (ppm)
- >200
- 100 to 200
- 50 to 100
- <50

0 100 200 300 500
metres

Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

Soil and Rock Geochemistry Cu (ppm)

Scale:	1:10,000	UTM	UTM zone 7 - NAD83	Fig
Date:	Nov 16, 2009	NTS	115J/10,11,14,15	9
By:	MJD	File	CanCk_10KassMaps	

Property Boundary

Western
Copper Claims

Casino
Proposed Pit

1994-328
114.91m

CC2000-8
(81m)

CC2000-6
(219.15m)

CC2000-4
(251.46m)

CC2000-5
(171.6m)

CC2000-3
(255.12m)

CC2000-7
(255.12m)

93-K-1
(46.5m)

93-A-4
(152.44m)

93-A-1
(152.44m)

93-A-5
(152.44m)

93-A-6
(152.44m)

93-A-2
(152.44m)

93-A-3
41.77m

CC2000-3
(99.06m)

CC2000-10
(401.17m)

CC2000-12
(102.72m)

CC2000-11
(117.36m)

CC2000-9
(118.87m)

CC2000-2
(152.4m)

CC-DDH-07-05
(112.78m)

CC-DDH-07-04
(240.79m)

CC-DDH-07-03
(208.48m)

CC-DDH-05-01
(166.12m)

CC-DDH-07-02
(152.4m)

1994-323
(152.4m)

1994-326
(131.67m)

1994-327
(152.4m)

1994-328
(152.4m)

1994-329
(152.4m)

CC09-01

CC09-02

CC09-03

CC09-04

CC09-05

CC09-06

CC09-07

CC09-08

CC09-09

CC09-10

1993 Rock samples - Cu (ppm)

- >200
- 100 to 200
- 50 to 100
- <50

2009 Rock samples - Cu (ppm)

- >200
- 100 to 200
- 50 to 100
- <50

2009 Soil grid Cu (ppm)

- >200 (5)
- 100 to 200 (13)
- 50 to 100 (134)
- <50 (1013)

Historic soil grid - Cu (ppm)

- >200
- 100 to 200
- 50 to 100
- <50


0 100 200 300 500
metres


Cariboo Rose Resources Ltd.
Alder Resources Ltd.


Canadian Creek Property

Soil and Rock Geochemistry
Mo (ppm)

Scale:	1:10,000	UTM	UTM zone 7 - NAD83	Fig
Date:	Nov 16, 2009	NTS	115J/10,11,14,15	10
By:	MJD	File	CanCk_10KassMaps	


CC09-09
CC09-10
CC09-08
CC09-02
CC09-05
CC09-03
CC09-04
CC09-01
93-A-4
93-A-1
93-A-5
93-A-6
93-A-2
1994-328
1994-323
CC2000-10
CC2000-12
CC2000-3
CC2000-9
CC2000-7
93-K-1
14500N
14200N
14000N
13900N
13700N
13500N
13525N
13400N
13300N
13250N
13200N
13175N
13000N
12700N
12500N
12400N
12300N
12100N
12000N
11800N
11700N
11625N
11425N
L6600W
L6800W
L7000W
L7200W
L7400W
L7600W
L7800W
L8000W
L8200W
L8400W
L8600W
L8800W
L9000W
L9200W
L9400W
L9600W
L9800W
L10000W
L10200W
L10400W
6960000 mN
6959000 mN
6958000 mN
0
100
200
300
500
metres
Chargeability (mV/V)
Cariboo Rose Resources Ltd.
Alder Resources Ltd.
Canadian Creek Property
2009 Chargeabilty Map
Scale: 1:5,000
Date: Nov 17, 2009
By: MJD
UTM zone 7 - NAD83
NTS 115J/10,11,14,15
File CanCk_10Kbase
Fig 11


L10400W
L10200W
L10000W
L9800W
L9600W
L9400W
L9200W
L9000W
L8800W
L8600W
L8400W
L8200W
L8000W
L7800W
L7600W
L7400W
L7200W
L7000W
L6800W
L6600W
14500N
14200N
14000N
13900N
13700N
13525N
13500N
13400N
13300N
13250N
13200N
13175N
13000N
12700N
12500N
12400N
12300N
12100N
12000N
11800N
11700N
11625N
11425N
CC09-01
CC09-02
CC09-03
CC09-04
CC09-05
CC09-06
CC09-07
CC09-08
CC09-09
CC09-10
CC09-06,07
93-A-1
93-A-2
93-A-4
93-A-5
93-A-6
93-K-1
1994-328
1994-323
CC2000-3
CC2000-7
CC2000-9
CC2000-10
CC2000-12
0
100
200
300
500
metres
Resistivity (ohm-m)
Cariboo Rose Resources Ltd.
Alder Resources Ltd.
Canadian Creek Property
2009 Resistivity Map
Scale: 1:5,000
Date: Nov 18, 2009
By: MJD
UTM: UTM zone 7 - NAD83
NTS: 115J/10,11,14,15
File: CanCk_10Kbase
Fig 12




Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

2009 Ground Magnetics Map

Scale:	1:5,000	UTM	UTM zone 7 - NAD83	Fig	13
Date:	Nov 18, 2009	NTS	115J/10,11,14,15		
By:	MJD	File	CanCk_10Kbase		


L11040W
L11020W
L11000W
L10980W
L10960W
L10940W
L10920W
L10900W
L10880W
L8600W
L8400W
L8200W
L8000W
L7800W
L7600W
L7400W
L7200W
L7000W
L6800W
L6600W
14500N
14200N
14000N
13900N
13700N
13500N
13525N
13400N
13300N
13250N
13200N
13175N
13000N
12700N
12500N
12400N
12300N
12100N
12000N
11800N
11700N
11625N
11425N
CC09-09
CC09-10 - 3.0m of 1099ppb Au
CC09-08 - 1.5m of 3458ppb Au
CC09-06 -15.0m of 330ppb Au
CC09-07
CC09-05
CC09-02
CC09-04
CC09-03,04
CC09-01
93-A-4
(152.44m)
93-A-1
(152.44m)
47.7m @ 0.3% Cu,
0.184g/t Au
93-A-5
(152.44m)
62.96m @ 0.013% Cu,
0.108g/t Au
93-A-6
(152.44m)
93-A-2
(152.44m)
CC2000-10
(201.17m)
6.71m @ 0.047% Cu
0.105g/t Au
CC2000-12
(102.72m)
CC2000-3
(99.06m)
CC2000-9
(255.12m)
CC2000-7
(255.12m)
93-K-1
1994-323
(152.4m)
1994-32
114.91m
0
100
200
300
500
metres
LEGEND
12.5 mV chargeability anomaly
Au in soils >50ppb
drill hole collar
Cariboo Rose Resources Ltd.
Alder Resources Ltd.
Canadian Creek Property
Coffee Can Zone
Drill Holes on Au Anomalies
and Chargeability Highs
Scale: 1:5,000
UTM zone 7 - NAD83
Date: Nov 19, 2009
NTS 115J/10,11,14,15
By: MJD
File CanCk_10KassMaps
Fig 14

East of the break the chargeability plot shows three distinct highs. Two of these, on the southern half of the grid are arranged east-northeast, the same orientation as the prolific >50ppb Au in soil anomalies in this area. The third chargeability high occurs in the northeast of the 2009 grid, also accompanied by anomalous Au in soil. The chargeability highs and anomalous gold in soil areas do show a rough spatial coincidence.

The eastern chargeability highs are rounded and have the appearance of intrusive bodies. A knob of granodiorite does underlie part of the westernmost of these anomalies, and extensive granodiorite was encountered in the drill holes in the northeast corner of the grid. Drilling in the other chargeability high encountered quartz-feldspar gneiss with only local granodiorite dykes. Outcrop in the eastern area is poor and the geological relationships are not well known.
Plots of inverted chargeability indicate that chargeability increases at depth with all of the eastern anomalies merging. Though strongly anomalous chargeability values occur in areas of drilling the amount of sulfide (pyrite) encountered was generally low (to 0.5%), which would not seem to be enough to give such values.

Magnetometer values from the 2009 survey are generally low in the west but show local significant highs in the eastern area. The largest and strongest high occurs in the northeast corner of the grid to the north of the chargeability and gold in soil highs that were drilled in the final three holes of this year's program. The next highest zone occurs southwest of this again on the north side of the grid, separate again from Au in soil and chargeability highs.

Resistivity readings were hampered by the presence of local permafrost and extensive boulder fields in the east. No real obvious patterns were noted on the plots.

2009 Prospecting and Reconnaissance
Prospecting and sampling work was conducted across the area of the 2009 grid, following up on the 1993 arsenic in soil anomaly and the 6.6g/t Au float sample, as well as in other areas around the property to search for new areas of gold mineralization. A total of 162 rock samples were collected in 2009, all but 14 of these collected on the Canadian Creek claims.

Prospecting in the 2009 grid area was difficult due to local lack of outcrop and local extensive areas of felsenmeer. Only three rocks samples from this area returned >100ppb Au, to a high of 649ppb. These were all float samples of iron stained gneiss, and all were from the same area of the eastern part of the grid south and west of 2009 drill hole CC09-05.

Three trenches in the Casino B area were cleaned and sampled, to verify high gold samples reported by Pacific Sentinel Gold in 1993, prior to Eastfield's acquisition of these claims in 2000. The highest of these results was trench 9076-C which reported historical values of 568ppb Au over 40 metres, including 10 metres of 1680ppb. The 2009 samples from this trench returned comparable values of 50 metres of 376ppb Au, including 10 metres of 927ppb. These samples were all collected as 5 metre "panel" samples. Rocks in the trench are described as yellow-dark brown soft sericite altered intrusive with local quartz-pyrite.

Other resampling returned 35 metres of 339ppb Au from Trench 9053-A, and 45 metres of 51ppb Au from trench 9076-C. Significant drill results have been obtained from this area in three different campaigns of drilling in 1994, 2000 and 2007. These include hole 1994-319 which returned 149.96 metres of 0.49g/t Au, including 55.17 metres of 0.72 g/t Au. This area is also underlain by a >50ppb Au in soil anomaly that is over two kilometres in length and up to one kilometre wide, indicating the existence of a large gold-bearing mineralizing system in this area.

In the Ana Pass area the 1993 trench Tr-2 was examined and sampled. A grab of a 0.5 metre wide quartz-pyrite tourmaline altered structure returned 2516 ppb Au, along with high arsenic values. A three metre chip sample across this structure and altered wallrock ran 866ppb Au. An extensive trenching and pitting program was undertaken in this area in 1996. These trenches have since been backfilled, but impressive results were obtained such as 6 metres of 1340ppb Au from 400 metres southwest of Tr-2, and a grab sample running 1897ppb from 800 metres west of Tr-2.

Other 2009 rock samples from the Ana Pass area also returned anomalous gold values, often from unimpressive looking rocks. Variably iron stained granodiorite float sample from 400 and 850 metres west of Tr-2 returned 187 and 126ppb Au, respectively.

A small amount of prospecting was carried out to the north and west of the Canadian Creek property to follow up on arsenic and antimony anomalies generated from government regional silt sediment surveys. Some rock samples were collected but no results of note were returned and prospecting failed to find anything of interest.

2009 Drilling

The diamond drill portion of the 2009 exploration program at Canadian Creek commenced on August 31 and finished on September 19. This work was conducted by Kluane Drilling Ltd. of Whitehorse, YT. Drill moves were done by helicopter but the drillers were able to access all of the sites by quad or on foot, greatly reducing costs. Ten diamond drill holes, totalling 1425.60m, were drilled, ranging in depth from 128.04 to 170.73 metres. Core size was NTW. Hole targeting was based on Au in soil geochemistry and inverted chargeability anomalies which extend for over four kilometres across the 2009 grid.

Production was good and core recoveries were generally good as well, though hole CC09-02 was unable to penetrate below 163.1 metres due to poor ground conditions. Overburden depths were not significant, the maximum being 9.14 metres in CC09-01. Even in areas of extensive felsenmeer cover only three to five metres of casing was required. Surface weathering of bedrock extended from five to ten metres below bedrock surface.

The dominant rock type encountered in holes CC09-01 to 07 was quartz-feldspar-biotite orthogenesis of the Yukon Metamorphic Complex. This unit is cut by relatively minor units of foliated quartz diorite and granodiorite (pre-Dawson Range intrusives of pre-Creataceous age), and abundant dykes of medium-coarse grained granodiorite of the Cretaceous Dawson Range Batholith. Local finer grained monzonite bodies (probably

also part of the Dawson Range Batholith) occur in holes CC09-04-06, in the central part of the drilled area. Holes CC09-08 to 10, at the eastern end of the drilled area, encountered almost entirely coarse grained granodiorite with minor gneiss xenoliths.

Zones of pervasive sausserite and sericite, often with fine disseminated pyrite, occurred in all of the holes to varying degrees of intensity. Strong clay alteration was common in narrow discrete structural zones and often contained dark grey to black very fine-grained muddy pyrite and white calcite veins. Anomalous gold mineralization occurred in a number of these zones.

Fine stringers of pyrite occurred in varying amounts in all of the holes. These were generally 1-2 millimetres in width and usually had dark sericite alteration haloes ranging in width from a few millimetres to over 20 centimetres. Pyrite in the western holes tended to be white while it was more yellow to the east. Other sulphides were rare; arsenopyrite was noted in CC09-02, 05, 09 and 10, sphalerite in CC09-08, chalcopyrite in CC09-06, pyrhottite in CC09-09, and molybdenite in CC09-01 and 06.

Sample intervals containing over >100ppb gold are considered anomalous and are discussed in the hole descriptions below. Nineteen intervals were encountered in the 2009 program. These occur in a number of settings; in clay altered structural gouge zones, with quartz-carbonate veins with or without pyrite, with pyrite veins and veinlets, or in the zone of surface oxidation as in CC09-04, 06, 07 and 08.

In a general sense anomalous gold values are associated with higher arsenic, antimony and bismuth, though there are numerous examples of high gold without anomalous pathfinders, or strongly anomalous pathfinders without strongly anomalous gold. Copper values are generally low, while increased molybdenum values were noted in hole CC09-01.

The best drill results were received from two of the easternmost holes; three metres of 1099ppb Au in hole CC09-10, and 1.5 metres of 3458ppb Au in hole CC09-08. The gold in soil anomalies remains open to the east of here, indicating strong potential for more gold mineralization in that direction.

CC09-01
This was the westernmost drill hole of the 2009 program and was located near L9200W/12350N. It was drilled to the south at -45^0 to depth of 137.19 metres and targeted the south end of an Au in soil high, with values to 51ppb, and a coincidental inverted chargeability high.

This hole encountered mostly quartz-feldspar biotite gneiss with lesser medium grained granodiorite. Alteration and veining were not common. The only Au result over 0.1g/t was a 0.5 metre interval from 105.0-105.5 metres which sampled a 4 centimetre 40^0 CA fine grained grey qtz vein with minor pyrite which returned 207ppb Au, and 57ppb Bi, the second highest bismuth value for the 2009 drilling. There was no obvious alteration halo to the vein and no other anomalous values associated with it. Similar looking veins in this hole did return any Au values of note.

CC09-01 returned the highest molybdenum values of the 2009 drilling; 23.7 metres of 16ppm Mo from 108.5 metres to the near end of the hole at 132.2 metres. This interval straddled a contact of coarse grained granodiorite and biotite gneiss which contained local zones of moderate-strong fracture related sausserite alteration. Minor molybdenite was noted in local quartz veins. This zone also returned weakly anomalous copper, lead, zinc, silver and arsenic, with gold to a high of 17.5ppb.

CC09-02

This hole was located near L8000W/12925N, 1.3 kilometres northeast of CC09-01. It was drilled to the southeast at -45^0. It too was located at the north end of an Au in soil anomaly, with values to 117ppb, but with a deeper, weaker inverted chargeability high. The final hole depth was 163.10 metres.

As in the first hole, the dominant rock type encountered was quartz-feldspar-biotite gneiss, which included intervals of dark, pyritic biotite gneiss. Foliated diorite was also encountered for a nine metre interval near the top of the hole. Granodiorite occurred as dykes up to over 20 metres in (drilled) width. Variable sausserite alteration, from weak to very strong, and clay alteration occurred throughout the hole in all rock types.

The only >100ppb Au value of note was a 3 metre interval from 154.15 metres, near the bottom of the hole, which returned 199ppb Au, 34ppm Bi, which occurred within a 24.3 metre interval of strongly anomalous arsenic, with values to 4609ppm. The anomalous gold value occurred within a zone of low CA 1-2 millimetre pyrite stringers and clay altered shears in gneiss which contained local minor arsenopyrite. It was intended for the hole to go deeper based on the strong alteration and presence of arsenopyrite, but further progress was thwarted by bad ground conditions.

The rest of the hole above this zone returned various zones of strongly anomalous arsenic with weakly anomalous gold to 89ppb and local elevated antimony and bismuth. A 9 metre zone of anomalous lead (to 504ppm) and zinc (to 2157ppm) ,and moderately anomalous arsenic from 36.65m returned gold values to a high of 3.5ppb.

CC09-03

This hole was located 200 metres southeast of CC09-02, near L7800W/12675N. Two holes were drilled from this location; CC09-03 to the south and CC09-04 to the north. The collars were situated in the middle of a strong gold in soil anomaly with values to 261ppb. The soil anomaly was underlain at 25-50 metres depth by a moderate inverted chargeability high.

CC09-03 was oriented to azimuth 175^0, -45^0 and went to 152.43 metres. As with the previous holes it encountered mostly quartz-feldspar-biotite gneiss with minor granodiorite. Variable sausserite alteration occurred throughout and local strong clay alteration was also present. Pyrite was minor, mostly occurring in low angle stringers and veinlets.

As with the previous two holes; this hole returned only one sample with >100ppb gold. This was a 0.55 metre sample, from 119.95 metres, of a 0.3 metre wide gouge zone of

black clay and white calcite veins with 10% pyrite, which returned 181ppb Au along with anomalous arsenic (277ppm) and bismuth (15.4ppm).

This hole contained weak-moderate arsenic values (100-500ppb) with corresponding weakly anomalous gold to 72ppb, from the top of the hole to 74.2m. Anomalous bismuth (5-19ppm) occurs in the bottom 24m of this section. A similar interval of anomalous arsenic near the bottom of the hole from 108-147.5 metres (with the exception of the 181ppb sample described above), contains gold values to a high of 22ppb. Nearly half of the samples from hole CC09-03 returned anomalous molybdenum from 2-20ppm while anomalous copper (50-730ppm) occurs in the upper 63 metres.

CC09-04
This was drilled from the same location as CC09-03, but oriented to the north at 355^0, inclined at -43^0, to test the northern part of the soil anomaly. Final hole depth was 134.14 metres. Gneiss was the dominant rock type encountered but a number of intrusive rock types were also present; strongly foliated granodiorite, and granodiorite and monzonite. Sausserite alteration is common and pyrite again minor.
Two 3 metre intervals of >100ppb Au were returned, both from near the top of the hole, and both occurring within a larger interval of anomalous arsenic values from 100-692ppm. The first of these ran from 11.2 metres and returned 125ppb Au, and the second from 20.2 metres, returned 132ppb Au. Both intervals are hosted in broken surface weathered gneiss with local low CA iron oxide cemented breccia zones. Copper (to 104ppm), and molybdenum (to 7.2ppm), were also weak-moderately anomalous in this zone. The rest of the hole encountered only sporadic, weak pathfinder element anomalies.

CC09-05
This hole was located 600 metres east of CC09-04, near L7200W/12875N, drilled to the northwest at azimuth 330^0, -45^0, to a depth of 126.52 metres. The hole was aimed towards a strong inverted chargeability anomaly at depth to the north and was located in the middle of a gold in soil high, with values to134ppb. This east-northeast trending >50ppb Au anomaly extends for over 1500 metres east-northeast is open beyond that. Holes CC09-06 and 7 are also located in this anomaly.

Quartz-feldspar-biotite gneiss was the most common rock type in hole CC09-05, with lesser intervals of medium grained granodiorite, fine grained monzonite, and foliated granodiorite, as described in the previous holes. Green sausserite alteration occurs to varying degrees throughout the hole. Clay alteration is locally strong and resulted in intervals of poor recoveries in the strongest altered zones.

The interval from 63.97-71.24 metres returned 7.37 metres of 159ppb Au, within a larger arsenic anomaly with values to 850ppm, which coincides with antimony values to 94ppm and bismuth to 183ppm. This interval is hosted in a strongly broken, clay-sausserite altered monzonite containing clay gouge zones with up to 50% pyrite and local quartz veins to 2cm. The rest of CC09-05 returned only sporadic, minor pathfinder element anomalies.

CC09-06

Two holes, CC09-06 and 07, were drilled from this site, near L6800/12950N, located 400 metres east of CC09-05. The holes were collared near the southern edge of a prominent Au in soil anomaly. CC09-06 was drilled to the northwest into the soil anomaly targeting values to 162ppb, with an inverted chargeability high at depth. The hole was oriented azimuth 330^0, -60^0, and finished at a depth of 153.73 metres.

CC09-06 was comprised mostly of gneiss, with local intervals of granodiorite. It returned five intervals of significant gold mineralization while arsenic values were low throughout the hole, to a high of only 92ppm.

The first interval runs from the top of bedrock at 5 metres to 20 metres depth and averages 330ppb, and occurs with anomalous antimony, to 86ppb, and bismuth to 7ppm. This interval is hosted by granodiorite which is strongly oxidized and broken to 13m, with disseminated pyrite to 0.5% below that.

A 2 metre sample from 44.0-46.0 metres returned 283ppb Au with moderate copper (462ppm) being the only other anomalous element. This sample was hosted in strongly sericite-sausserite altered granodiorite which contained abundant 2-5mm sheeted pyrite veins.
The 6 metre interval from 81.5 metres returned 171ppb Au, hosted in a foliated diorite which contains local low CA quartz-carbonate veins with local pyrite. No other anomalous elements occur with this gold intercept.

The fourth interval of this hole ran from 114.45-123.45 metres; 9 metres of 106ppb Au. The host rock here was feldspar-biotite gneiss with abundant low-moderate CA quartz veins and stockworks with minor pyrite. Weakly anomalous antimony and bismuth occur in one of the samples. This section of the hole is noted with having a strong yellow stain to the gneiss.

The final anomalous interval was from near the bottom of the hole; 3 metres of 105ppb Au from 144.45m, coincident with anomalous antimony (19ppm) and bismuth (11ppm). The rocks here contain low CA calcite-pyrite veins and local low CA clay altered gouge.

CC09-07
This was the second hole located at this site, drilled southeast at azimuth 150^0, -45^0, to a depth of 170.73 metres, the deepest hole of the 2009 program. This hole was on the south edge of the 100ppb Au soil contour but was still directed towards Au in soil values to 95ppb. The main target for this hole was a prominent discrete spike of high inverted chargeability that came to surface 25m south of the drill collar. As with all of the other holes, no explanation for the inverted chargeability high was obvious from the drill core.

Again, gneiss was the dominant rock encountered in this hole, along with lesser amounts of Creataceous medium grained granodiorite and older, foliated quartz diorite. Green sausserite alteration occurred locally though less than in the previous holes.

Two anomalous gold intervals were returned in this hole. As with CC09-06, one of these occurred at the top of the hole in the 9 metres from the bedrock surface at 4.9 metres and returned 126ppb Au with moderately anomalous copper values to 232ppm. The host

rocks were sericite-sausserite altered feldspar-biotite gneiss with numerous similarly altered granodiorite dykes. Both rock types were cut by abundant fine pyrite stringers.

A second anomalous interval occurred at 141.45-144.45 metres. This 3 metre interval returned 106ppb, with a 198ppm Cu value being the only other anomalous element. This zone was hosted in gneiss with sheeted 1-2 millimetre pyrite veins. As with CC09-06, arsenic, antimony and bismuth values were low.

CC09-08

The final three holes were located in the northeast corner of the 2009 grid, 800 metres north of CC09-07, in a separate zone of coincident moderately anomalous gold in soils and inverted chargeability highs. Hole CC09-08 was collared near L6600W/13740N, drilled to the north at azimuth 000^0, -68^0, to a depth of 137.77 metres. The hole targeted an inverted chargeability that surfaced in a zone of moderately anomalous gold in soil with values to 33ppb.

The dominant rock type in this hole was variably sausserite altered medium-coarse grained granodiorite with local intervals (xenoliths?) of gneiss. Three intervals of anomalous gold were encountered in the hole, the first of which occurs again near surface. The 3 metres from 6.05 metres returned 129ppb Au from granodiorite with no associated anomalous arsenic, antimony or bismuth.

A 1.5 metre sample from 77.8-79.3 metres returned the highest gold result of the 2009 drill program; 3458ppb. This sample also contains anomalous silver, arsenic, antimony, bismuth, copper, lead and zinc. The sample includes a granodiorite hosted low CA 10 centimetre wide structural zone with abundant white euhedral pyrite and minor chalcopyrite.

A 7 metre interval from 111.5-118.5 metres returned 100ppb Au along with bismuth to 21ppm, within a zone of spotty anomalous arsenic values to 772ppm. The rocks in this zone were sausserite altered granodiorite with local low CA clay-fine grained pyrite altered gouge zones.

Anomalous arsenic occurs locally throughout the hole, generally in and around higher gold values. Base metals are weak overall, though copper values are weakly anomalous, to 165ppm in the lower part of the hole. A five centimetre vein of massive sphalerite was noted at 63.8m which also contained 2967ppm As, 1.1g/t Ag, and 55ppb Au.

CC09-09

This hole was located 225 metres north of CC09-08, at L6600W/13965N, drilled to the south at azimuth 180^0, -58^0 to a depth of 137.77 metres. As with CC09-08, this hole targeted a coincidental inverted chargeability and gold in soil anomaly.

This hole encountered leucocratic and mesocratic granodiorite with local intervals of sausserite alteration. Only one sample of anomalous gold was returned from this hole. At 115.35 metres a 0.45 metre wide sample containing 5 and 10 millimetre moderate CA carbonate veins with pyrite and minor arsenopyrite returned 149ppb Au and 5038ppm As, and was also anomalous in bismuth, copper, lead and zinc. Local arsenopyrite was noted

in minor pyrite veins throughout the hole, all associated with elevated gold values. Pyrhottite occurs in minor amounts in the lower half of the hole.

Arsenic values were sporadically anomalous in this hole, with molybdenum having the only other (minor) anomalous results.

CC09-10
The final hole of the 2009 program was located 200 metres east of holes CC09-08 and 09, collared at 6400W/13836N. It was drilled to the north at a -59^0 dip to a depth of 121.95 metres, and ran through granodiorite along the entire length. Sausserite alteration was common throughout the hole, which also had numerous intervals of strong broken clay alteration. Moderate to high CA narrow pyrite veins with local arsenopyrite are locally common.

Three significant auriferous intervals were discovered here. The uppermost of these was from 20.85-29.85 metres which returned 9 metres of 100ppb Au, associated with weakly anomalous arsenic (to 172ppm), antimony (to 39ppm) and bismuth to 5.9ppm. This interval occurs in strongly sausserite altered granodiorite with local low CA pyrite stringers and abundant quartz-clay-pyrite broken zones.

The second zone runs from 82.8-92.0 metres; 7.25 metres of 683ppb Au, which includes a three metre sample of 1099ppb Au and 30.4ppm Ag. This was the highest silver value returned from the 2009 drill program. The interval is also strongly anomalous in arsenic (to 3267ppm), antimony (to 222ppm), bismuth (to 60ppm), copper (to 600ppm), lead (772ppm) and zinc to 304ppm. This zone occurs in strongly sausserite-muscovite +/-clay altered granodiorite with clay zones containing up to 50% pyrite.

The final interval of interest ran from 102.5-108.7 metres and returned 6.2 metres of 146ppb Au. The zone also contain strongly anomalous arsenic (to 2103ppm), antimony (to 933ppm), and weakly anomalous bismuth, copper, lead and zinc. The host rock is again a sausserite altered granodiorite with disseminated pyrite and local quartz veins with pyrite and minor arsenopyrite. The antimony values were the highest returned from the 2009 drilling.

11. DRILLING

The first drilling on the Canadian Creek property was carried out in 1970 on the Casino "B" Option area by Brameda Resources Ltd. In 1993 Eastfield and its option partners drilled the Ana and Koffee areas. In 1994 (before Eastfield acquired these claims) Pacific Sentinel Gold Corp drilled four holes in the Casino B area. In 2000 on the Ana, Koffee and Casino "B" claims were drilled by Wildrose and it's option partners, and in 2007 on the Casino "B" claims were drilled by Eastfield's successor company Cariboo Rose and it's option partners. In 2009 a 10 hole, 1425 metre drill program was conducted in the Coffee Can Zone by Cariboo Rose Resources and Alder Resources.

A total of 40 drill holes have been drilled in the Canadian Creek property since 1970. The total meterage is 5773.27 metres plus the unknown depths of the 1970 Brameda holes. Efforts have been made in recent programs to locate and obtain GPS coordinates for all of the holes, though a few have yet to be definitively located.

In 1969 and 1970 Brameda Resources [Ltd.?] carried out a large exploration program in the Casino area. Two of the 49 holes drilled by Brameda during this period, referred to as D1 and D2,are believed to be on the Casino "B" Option ground, but no further information is available to the author.

The 1993 program was contracted to E. Caron Diamond Drilling Ltd. of Whitehorse and consisted of 850.54 metres of HQ core in seven holes. Recoveries were generally very high; low recoveries being associated with faults and sheer zones. All the core was logged and with the exception of hole 93-A-3 (13 samples selected from 93-A-3) all the core was split with half sent to a lab for analysis and the other half returned to the core box for a visual record. This core is stored at the Canadian Creek camp. The analysis (multi-element ICP and MIBK/Graphite furnace with AA finish gold) was carried out by Pioneer Laboratories Inc. of New Westminster, BC. Gold and copper assays were performed by Chemex Labs Ltd. of North Vancouver.

The 1994 diamond-drilling on the Casino "B" option was part of a larger program on the Casino property by Pacific Sentinel Gold Corp. Diamond-drilling was contracted to E. Caron Diamond Drilling Ltd. and 551.38 metres of HQ core was drilled in four holes (1994-319, 1994-323, 1994-325, 1994-328). Recoveries are not stated in the drill summaries available to the author, but the core from each of these holes was examined by the author in 2000 and recoveries were high, usually 100%. The core was split, or in some cases sawn, in two with half returned to the core box and some portion of the remainder being sent to Chemex Labs Ltd. of North Vancouver for analysis (32-element ICP and copper/molybdenum/gold assay). The core is stored in a well organized core-library at the Casino airstrip.

The 2000 diamond-drill program, funded by Alexis Resources Ltd., was contracted to Major Drilling Ltd. of Smithers, BC and a total of 1,985 metres of NQ core was drilled in 11 holes (not including hole CC2000-8 which was lost and produced no core). This program tested three areas: on the Koffee claims five holes (plus one lost) were drilled for a total of 1152.5 metres (not including the 81 metres lost in hole CC2000-8), on the Ana claims 300.2 metres were drilled in two holes, and on the Casino "B" Option 531.6 metres were drilled in four holes. Recoveries when solid bedrock was reached were very high, often 100%, but in the Koffee bowl deep overburden, combined with intense weathering, surface leaching and clay-alteration proved very difficult to drill. Casing in several holes exceeded 40 metres and an unknown thickness of altered bedrock was washed away before competent rock was reached and coring could begin. All core recovered was transported to the camp where all core was split and logged, with the split fraction shipped to Acme Analytical Laboratories Ltd. where it was analyzed (30-element ICP and FA/ICP gold). The core is stored on site at the Canadian Creek camp.

The 2007 diamond drill program, funded by Veraz Petroleum ltd., was completed by Beaudoin Diamond Drilling Ltd. The program consisted of five holes totaling 879 metres of thin wall "BQ" drill core. All drilling was completed in the area of the claims referred to as the Casino "B" claims. Overburden varied from 4.6 to 23.4 metres. This core was processed at the Canadian Creek camp and the remaining portion is stored there. Sample

analysis was done by Eco-Tech Labs, of Kamloops BC, with sample preparation done at their facility in Whitehorse.

The 2009 drilling in the Coffee Can area, funded by Alder Resources Ltd. was carried out by Kluane Drilling Ltd. of Whitehorse. A total of 1425.6 metres of NTW core was drilled in 10 holes. The drilling went well, and recoveries were also generally good. As with all of the previous Eastfield/Cariboo Rose drill programmes, the core was logged and sampled at the Canadian Creek camp, with the remaining split stored there. Samples were sent to Acme Analytical Laboratories in Smithers BC, for preparation, who then forwarded the samples to their Vancouver facility. A 15 gramme sample was analyzed for 36 elements using the 1DX-15 package, which utilizes a 1:1:1 Aqua Regia digestion followed by ICP-M3 analysis.

The 1993, 2000, 2007 and 2009 drill programs followed standard mining exploration procedures for logging, splitting, numbering samples for analysis, and shipping and for the storing of logged and split core. Pacific Sentinel Gold Corp. is believed to have done likewise. It is unknown what procedures were followed by Brameda Resources. The drill programs on the Canadian Creek property from 1993 to the 2009 have all been supervised by registered professional engineers and/or geoscientists who were and continue to be members in good standing of their professional associations. All analyses and assays have been carried out at laboratories using standard industry techniques, including check assays, repeat analysis and standards analysis, and have been supervised by certified BC assayers. The exploration drilling on the Canadian Creek property is and continues to be of an "early-stage" and as such the orientation of mineralization intersected in drill-holes is unknown. There is no known relationship between sample length and true thickness of the mineralization. The following tables summarize the diamond drilling on the Canadian Creek property to date:

Table 3: Canadian Creek Diamond Drill Holes 1970-2009

Hole ID	Area	Year	UTM E (NAD 83 Z7)	UTM N (NAD 83 Z7)	Depth (m)	Azimuth	Dip	Geology
93-A-1	Ana	1993	606498	6958253	152.44	-	-90	Leached-cap with supergene and hypogene phyllic alt gneiss, quartzite, granodiorite, intrusive breccia
93-A-2	Ana	1993	606458	6958043	152.44	-	-90	Leached-cap with hypogene phyllic and propylitic alt granodiorite, intrusive breccia.
93-A-3	Ana	1993	606661	6957465	41.77	-	-90	Hypogene propylitic alt granodiorite.
93-A-4	Ana	1993	606590	6958420	152.44	-	-90	Leached-cap mafic gneiss, supergene phyllic alt intrusive breccia, hypogene propylitic alt granodiorite.
93-A-5	Ana	1993	606792	6958214	152.44	-	-90	Leached-cap, phyllic alt heterolithic, intrusive breccia, gneiss, granodiorite
93-A-6	Ana	1993	607040	6958162	152.44	-	-90	Phyllic-alt supergene and hypogene Patton Porphyry
CC2003-3	Ana	2000	607153	6957396	99.06	230	-45	Propylitic alt granodiorite
CC2003-10	Ana	2000	607800	9658071	201.17	180	-45	Propylitic alt quartz diorite

93-K-1	Koffee	1993	603905	6957384	46.5	-	-90	Limonitic regolith after Patton Porphyry
CC2000-4	Koffee	2000	602678	6957712	251.46	215	-45	Patton Porphyry, propylitic alt granodiorite
CC2000-5	Koffee	2000	602834	6957714	171.6	210	-60	Granodiorite
CC2000-6	Koffee	2000	603537	6957768	219.15	-	-90	Leached-cap granodiorite, Patton Porphyry, quartz diorite.
CC2000-7	Koffee	2000	604220	6957729	255.12	54	-80	Phyllic alt granodiorite.
CC2000-8	Koffee	2000	603164	6957817	81	no data	no data	Hole lost while setting casing.
CC2000-9	Koffee	2000	603867	6957805	255.12	045	-70	Leached-cap, granodiorite, potassic alt
D-1	Casino B	1970	no data	no data	no data	no data	no data	No information
D-2	Casino B	1970	no data	no data	no data	no data	no data	No information
1994-319	Casino B	1994	608568	6957739	152.4	-	-90	Brecciated latite dyke, propylitic alt granodiorite.
1994-323	Casino B	1994	608482	6958120	152.4	-	-90	Propylitic alt Patton Porphyry, weak potassic alt, magnetite rich toward bottom of hole.
1994-325	Casino B	1994	608911	6957970	131.67	-	-90	Weak propylitic alt Patton Porphyry.
1994-328	Casino B	1994	608516	6959232	114.91	-	-90	Weak propylitic alt foliated granodiorite and quartzite.
CC2000-1	Casino B	2000	608576	6957766	118.87	200	-45	Propylitic alt granodiorite, plagioclase porphyry latite
CC2000-2	Casino B	2000	608625	6957966	152.4	200	-45	Patton Porphyry, propylitic alt granodiorite
CC2000-11	Casino B	2000	608405	6957735	157.58	200	-45	Weak propylitic alt granodiorite becoming fresh toward bottom
CC2000-12	Casino B	2000	608193	6957883	102.72	200	-45	Weak propylitic alt granodiorite becoming fresh toward bottom
CC-DDH-07-01	Casino B	2007	608784	6958202	166.12	-	-90	Gneiss with granodiorite dykes
CC-DDH-07-02	Casino B	2007	608973	6958400	152.4	-	-90	Granodiorite, gneiss and Patton Porphyry
CC-DDH-07-03	Casino B	2007	609013	6957573	208.48	-	-60	Latite, granodiorite
CC-DDH-07-04	Casino B	2007	608605	6957715	240.79	-	-90	Granodiorite, latite
CC-DDH-07-05	Casino B	2007	608377	6957715	112.78	-	-90	Granodiorite, latite, Patton Porphyry
CC09-01	Coffee Can	2009	605173	6958510	137.19	178	-44	variable saus alt gneiss , granodiorite dykes
CC09-02	Coffee Can	2009	606327	6959075	163.1	156	-44	gneiss , granodiorite dykes
CC09-03	Coffee Can	2009	606546	6958859	152.43	175	-43	gneiss , granodiorite dykes
CC09-04	Coffee Can	2009	606546	6958863	134.14	355	-45	gneiss , granodiorite dykes
CC09-05	Coffee Can	2009	607121	6959090	126.52	330	-45	gneiss , granodiorite dykes

CC09-06	Coffee Can	2009	607510	6959204	153.73	330	-60	gneiss , granodiorite dykes
CC09-07	Coffee Can	2009	607511	6959200	170.73	150	-45	gneiss , granodiorite dykes
CC09-08	Coffee Can	2009	607685	6959998	137.77	000	-68	granodiorite
CC09-09	Coffee Can	2009	607668	6960222	128.04	180	-58	granodiorite
CC09-10	Coffee Can	2009	607875	6960125	121.95	000	-59	granodiorite
				Total Metres	5773.27			

Table 4: Ana Significant Results (Ana threshold is Cu>0.100 % and Au>0.100 g/t)

Hole No.	From (m)	To (m)	Interval (m)	Copper (%)	Gold (g/t)
93-A-1	56.30	104.00	47.7	0.030	0.184
including:	89.02	92.07	3.05	0.030	1.920
93-A-5	2.44	65.40	62.96	0.013	0.108
including:	47.40	53.40	6.00	0.010	0.535
	131.40	152.44	21.04	0.025	0.120
CC2000-10	20.42	27.13	6.71	0.047	0.105

Table 5: Koffee Significant Results (Koffee threshold is Cu>0.100 %, and Au>0.100 g/t)

Hole No.	From (m)	To (m)	Interval (m)	Copper (%)	Gold (g/t)
CC2000-1	80.00	82.90	2.90	0.0507	0.105
	107.05	110.64	3.59	0.020	0.187
	122.22	125.27	3.05	0.046	0.345
CC-2000-06	49.86	61.57	11.71	0.298	0.020
Including:	49.86	52.73	2.87	0.483	0.017
	92.6	95.4	2.8	0.367	0.010
CC2000-7	26.52	32.31	5.79	0.003	0.150
	71.63	74.58	2.95	0.009	0.110
CC2000-9	127.11	130.15	3.04	0.120	0.046

Table 6: Casino B Option Significant Results

Hole No.	From (m)	To (m)	Interval (m)	Copper (%)	Gold (g/t)
1994-319	2.44	152.4	149.96	0.06	0.49
Including:	2.44	57.61	55.17	0.09	0.72
Including:	108.81	132.59	23.78	0.05	0.7
1994-323	33.83	36.27	2.44	0.05	0.38
Including:	60.05	63.4	3.35	0.01	0.31
1994-325	Sample # 643962 – no interval supplied with assays			0.02	0.34
	Sample # 643975 – no interval supplied with assays			0.08	0.27
	Sample # 643979 – no interval supplied with assays			0.09	0.62

1994-328	Sample # 927008 – no interval supplied with assays			0.08	0.62
	Sample # 927028 – no interval supplied with assays			0.08	0.55
	Sample # 927029 – no interval supplied with assays			0.01	0.75
CC-2000-01	18.45	68.88	50.43	Minor	0.71
Including:	18.45	44.2	25.75	Minor	1.04
	88.7	118.87	30.17	0.066	0.52
CC-2000-11	102.72	105.77	3.05	0.12	0.97
	121.22	132.18	10.96	Minor	0.4
	136.25	139.29	3.04	Minor	0.84
CC2000-12	57	60.05	3.05	0.2	0.36
CC-DDH-07-01	16.8	117	100.2	0.06	0.12
CC-DDH-07-02	45	108	63	0.05	0.14
CC-DDH-07-03	4.6	208.5	203.1	0.03	0.17
Including	168.2	171.5	3.3	0.03	1.91
CC-DDH-07-04	9.1	145	135.9	0.05	0.31
Including	139	145	6	0.01	2.96
CC-DDH-07-05	7.9	112.8	104.9	0.07	0.14

Table 7: Coffee Can Significant Results (Coffee Can threshold is Au>100ppb)

Hole No.	From (m)	To (m)	Interval (m)	Au ppb
CC09-01	105.0	105.5	0.5	208
CC09-02	154.15	157.15	3.0	199
CC09-03	119.95	120.5	0.55	181
CC09-04	11.2	14.2	3.0	125
	20.2	23.2	3.0	132
CC09-05	63.97	71.24	7.37	159
includes	64.9	65.24	0.34	531
CC09-06	5.0	20.0	15.0	330
	44.0	46.0	2.0	283
	81.5	87.5	6.0	171
	114.5	123.45	9.0	106
CC09-07	4.9	13.9	9.0	126
	141.45	144.45	3.0	106
CC09-08	6.05	9.05	3.0	129
	77.8	79.3	1.5	3458
	111.5	118.5	7.0	100
CC09-09	115.35	115.75	0.4	149
CC09-10	20.85	29.85	9.0	100
	82.8	90.05	7.25	683
includes	82.8	85.8	3.0	1099
	102.5	108.7	6.2	146

The drilling summaries of significant results indicate that while the best copper values have been found in the Koffee area, the best gold intersections have been in the Casino "B" option area. In the Koffee bowl area (7 holes), large intervals of anomalous copper, in the range of 200 to 600 ppm, are common but significant higher-grade intersections have so far been infrequent. In the Ana area (8 holes) there have been large intercepts of anomalous copper geochemistry, but gold mineralization is not common and is limited to a few narrow intercepts. Drill results from the Coffee Can zone show the presence of a large area containing intervals of anomalous (>100ppb) gold values, though higher grade results occur in the eastern part of the area.
The most successful drilling has been in the Casino "B" option area (15 holes), both in terms of the size of mineralized intersections and in their number. This is especially true in regard to anomalous gold intersections in this area. Hole 1994-319 is outstanding in this regard, with virtually the entire hole mineralized (149.96 metres of 0.49 grams per tonne gold including the top 55.17 metres of core grading 0.72g/t). The system remains open to the south, east and possibly west if the system has merely been interrupted by cross faults.

In the Coffee Can area the best gold results were returned from the easternmost drill holes. The area of anomalous gold in soils remains open to the east near here.

12. SAMPLING METHOD AND APPROACH

Numerous exploration programs have been carried out on the Canadian Creek property. Much of the work was completed prior to the implementation of national policy 43-101 and there is occasionally incomplete documentation concerning sampling methods, sample quality and other parameters. In the opinion of the author, the programs run by Eastfield Resources Ltd., Wildrose Resources Ltd., Cariboo Rose Resources Ltd and Pacific Sentinel Gold Corporation, which this report largely draws upon for information, have been professionally managed and the programs conducted according to accepted industry standards. Internal standards provided by the certified laboratory and some reruns initiated by the laboratory were routinely completed. Standards were routinely submitted by CARIBOO ROSE in the 2007 and 2009 drill programs although no company prepared internal standards are believed to have been employed previous to this program.

13. SAMPLE PREPARATION, ANALYSIS AND SECURITY

As this report draws from much work completed prior to the implementation of national policy 43-101 the discussion provided here is predominantly provided as a recommendation for work which occurs on the Canadian Creek property.

Standard Industry Procedures
Rock samples are bagged in heavy plastic bags and closed with a wire-tie, sample numbers are written on the outside of the bag. Each geologist has a unique number sequence so that they are not mixed up with other samples. The geologist collecting the sample writes Field descriptions on site. In general, only the geologist takes rock samples so that the field relationships of the sample can be properly described. Often a duplicate sample is taken so that it can be referred to when assay results are received. All field geologists are encouraged to select representative samples, and when high assay results are received, the location is resampled, often by a different geologist. The

duplicate sample is also used for the more detailed descriptions that may be written later in the camp, when the samples are tabulated in a spreadsheet on a laptop computer.

Soil and silt samples are collected in Kraft paper bags and tied shut with flagging tape. In camp it is usually necessary for them to be dried before shipment and they are sometimes strung on wires for this purpose. The reliability of soil sampling is greatly enhanced by training the field-crew to collect samples in a consistent and standardized way. The soil samples are taken from holes dug with a tree planting shovel, mattock or auger from approximately 30 to 40 cm depth. In areas where soil horizons have developed, an attempt is made to always sample the "B" horizon. By limiting the organic content in samples through deep sampling it is possible to reduce the variability at a site.

Drill core is placed in numbered core boxes at the drill site by the driller's helper whenever the core tube is pulled up and it contains core. A wooden run block marks the bottom end of the core recovered in the box each time the tube is pulled. The driller keeps track of the footage/depth by counting the number of ten-foot rods in the hole. The "zero" point, usually the top of the casing or the surface of the drill-deck is discussed and agreed upon by the driller and the geologist prior to the first hole being drilled. Core is generally transported twice a day from the drill site to a core storage and splitting facility constructed near the camp. during helicopter supported drill programmes, the core is usually transported to camp at the end of each hole.

At the core facility the core is laid out, metric conversions of the run-blocks footages are carried out and the core boxes are labeled with a weather-proof metal tag. The laid-out core is examined by the project geologist who does a preliminary evaluation of the hole's potential, identifies the main rock types, estimates recoveries, marks the contacts and divides the core into sample intervals. Any mistakes made by the driller or helper in marking the boxes or run blocks are caught at this stage.

The core is then split, generally using a mechanical core splitter, with half the sample bagged and the other half left in the core boxes for detailed logging and stacking on site. Books of pre-printed, numbered assay tags are filled in by the core splitters as they work. In each heavy-duty poly sample bag they place a uniquely numbered tear-off section from the assay book. A corresponding number is stapled into the core box and it is noted in the drill-log. No other number or mark is made on the core samples and from that point on no person handling the core when it is shipped, received at the lab or when it is being analyzed can identify the hole or property that the core is from. The poly sample bags are closed with a cinch strap and bundled in groups of 3 or 4 (weighing 20 to 30 kg.) into an opaque rice-sack which is sealed. Standard samples are introduced into the analytical stream at a ratio of generally one standard to 20 or 30 samples.

Samples are stored in a secure location, such as the exploration office prior to shipment. During the core splitting there are normally several people present, and none of the core-splitters wear jewelry. No sample preparation other than splitting the original core is carried out on the property.

Analysis - Laboratories
The issuer plans to use only certified Canadian laboratories for analytical work it completes on the Canadian Creek project. Occasional samples should be submitted to alternate facilities for comparison. Drilling completed in 1993 was analyzed by Pioneer Laboratories Inc of Vancouver, BC while drilling completed in 2000, 2007 and 2009 was analyzed by Acme analytical Laboratories Ltd. of Vancouver BC which is an ISO 9001:2000 certified facility. The 2007 core samples were analyzed by Eco-Tech Laboratory Ltd.

14. DATA VERIFICATION

This report draws much information from work completed prior to the implementation of national policy 43-101. In the opinion of the author, the programs run by Eastfield Resources Ltd., Wildrose Resources Ltd., Cariboo Rose Resources Ltd and Pacific Sentinel Gold Corporation, which this report largely draws upon for information, have been professionally managed and the programs conducted according to accepted industry standards including acceptable verification of results.

15. ADJACENT PROPERTIES

The Casino porphyry copper-gold-molybdenum property adjoins the Canadian Creek property on its east side. The Casino project is presently being explored by Western Copper Corp. A documented NI 43-101 Compliant Reserve Estimate of 913,546,000 tonnes (proven and probable) grading 0.212% Cu, 0.237g/t Au and 0.0236% Mo, was released in 2008. Included within this was total proven reserves of 143,804,000 tonnes grading 0.284% Cu, 0.354 g/t gold and 0.0311% Mo (Western Copper website; Technical Report: August 2008; QP: M. Hester, FAusIMM).

The discovery in 2008 of gold mineralization at Underworld Resources' White Gold project provided a major spark for exploration in the western Yukon in 2009, including that at the Canadian Creek project. Mineralization at White Gold is hosted in Yukon Metamorphic Complex schists and gneisses and in Creataceous intrusives of the Dawson Range Batholith. Drilling has returned numerous results in the order of 3.39g/t Au over 104 metres, variously associated with elevated molybdenum, arsenic or antimony. Similar geology and geochemistry exist at the Coffee Can zone of the Canadian Creek property, which is 50 kilometres southeast of White Gold.

A similar setting occurs at Kaminak Resources' Coffee property, located 20 kilometres northwest of the Canadian Creek claims. No drilling has been conducted there to date but trenching has returned results including 11.72 g/t Au over 10 metres from within large gold, arsenic and antimony soil anomalies.

16. MINERAL PROCESSING AND METALLURGICAL TESTING

The author is not aware of any metallurgical testing of materials from the Canadian Creek property.

17. MINERAL RESOURCE AND MINERAL RESERVE ESTIMATES

There are no mineral resources or estimates computed for the Canadian Creek property.

18. OTHER RELEVANT DATA AND INFORMATION

The authors are not aware of any other relevant data or information that should be in this report.

19. INTERPRETATIONS AND CONCLUSIONS

The Canadian Creek property is underlain by Yukon Metamorphic Complex gneisses that have been intruded by Creataceous Dawson Range Batholith granodiorite and monzonite, and Casino Complex intrusive rocks and breccias. This area is within the Tintina Gold Province which contains numerous major gold deposits in the Yukon and Alaska. On a smaller scale, Canadian Creek is located between the White Gold and Mount Freegold projects, which both host significant gold mineralization in similar geological settings as Canadian Creek.


The 2009 exploration program in the Coffee Can area outlined a large new zone containing anomalous gold, arsenic, antimony and bismuth in soils that is over four kilometres long and still open to the east. Gold values range as high as 2287ppb in soil in the eastern part of the grid. Many of these soil anomalies coincide with inverted chargeability highs.

Drilling within this zone returned anomalous gold values from across the length of the soil anomalies., and The best results from this drilling, 3 metres of 1089 ppb in CC09-10, and 1.5 metres of 3458ppb from CC09-08 are both located at the east end of the soil anomaly that remains open to the east, possibly indicating the strengthening of the system in that direction.

Resampling of old trenches in two other areas of the property confirmed the presence of gold mineralization. Trench 9053-A from the Casino B area returned values of 50 metres of 376ppb Au, including 10 metres of 927ppb. Historic drillholes from this area have returned gold values up to 149.96 metres averaging 0.49g/t Au. This area is underlain by a large >50ppb Au in soil anomaly that is accompanied by anomalous copper and molybdenum in soils as well.

In the Ana Pass area, the 1993 trench TR-2 contains a 0.5 metre wide quartz-pyrite tourmaline altered structure that returned 2516 ppb Au, along with high arsenic values. Other historical sampling in the area returned other results up to 1340ppb Au over 6 metres and grab samples to 1897ppb. This area is also underlain by a large>50ppb Au in soil anomaly.

Figure 23: Compilation Map



20. RECOMMENDATIONS

The next phase of exploration on the Canadian Creek Property should involve exploration on the three areas that each have significant potential for the discovery of economic gold mineralization. These are the Coffee Can, Casino B and Ana Pass area. A programme of limited soil sampling and IP, accompanied by 3000 metres of diamond drilling, is proposed.

Exploration in the Coffee Can area should continue with the extension of the 2009 grid to the east in order to determine the extent of the gold in soil anomalies discovered in 2009 which remain open to the east. The best drill results of 2009; 3 metres of 1089 ppb in CC09-10, and 1.5 metres of 3458ppb from CC09-08 have come from the easternmost drill holes and the highest soils, to 2287ppb have also come from the east side of the grid. This exceptionally high soil value was received after the end of the 2009 field work, as has yet to be followed up.

Approximately 8 kilometres of grid would be required to take the soil sampling and geophysical survey up to the eastern boundary of the claims. A proposed 1000 metres of drilling will be required to follow up on the new results received as well as to target the high soils received at the end of the 2009 programme, and for other chargeability and Au in soil highs that were not tested in 2009

The Casino B area has returned the best gold in drill results on the property to date, including to 149.96 metres averaging 0.49g/t Au. A compilation of the historical data should be carried out in order to target 1200 metres of drilling, with a view to testing deeper than the previous holes. The area is well covered by soil grids emplaced in 2003 and 2006.

Interesting gold results have been returned from the Ana Pass area, where resamples of the 1993 trench Tr-2 returned gold values to 2516pp and historical sampling has returned other >1g/t gold results. Trenching has been conducted in the past with good success at finding bedrock and strong gold values. To date, there is only 1 short (47.77m) drillhole in the area, which was located far from any of the known >1g/t gold samples. A programme of mechanical trenching and 800 metres of drilling is recommended for this area.

Table 8: Recommended Budget for Next Phase of Exploration at Canadian Creek

Geologist		$55,000
Crew of 4-6		$160,000
Camp, Rentals, Consumables		$60,000
Helicopter		$70,000
Fixed wing		$100,000
Soil, rock, core samples		$50,000
Geophysics; 10 kilometres		$20,000
Trenching		$100,000
Drilling; 3000 metres		$360,000
Reports, Filing Assessment		$25,000
	Total	$1,000,000

21. 2009 EXPENDITURE STATEMENT

Table 9: Expenditure Statement; Canadian Creek 2009

Professional Fees:		
R. Johnston	60 days @ $680/day	40,800.00
G.L. Garratt	8 days @ $680/day	5,440.00
J.W. Morton	7 days @ $680/day	4,760.00
C. Russell	37 days @ $680/day	25,160.00
Field Personnel Fees:		
J.P. Charbonneau	99 days @ $420/day	41,580.00
F. Larocque	8 days @ $420/day	3,360.00
R. Dennett	35 days @ $533.57/day	18,675.00
S. McGovern	34 days @ $445/day	15,130.00
M. Kozenko	50 days @ $310/day	15,500.00
C. Stark	14 days @ $420/day	5,880.00
G. Parent	26 days @ $360/day	9,360.00
N. Lefebvre	49 days @ $460/day	22,540.00
R. Cadorette	78 days @ $385/day	30,030.00
M. West	50 days @ $310/day	15,500.00
L. Johnson	9 days @ $330/day	2,970.00
T. Graham	37 days @ $330/day	12,210.00
Rentals:		
6 Handheld Radios	6 days @ $5/day each	180.00
5 Handheld Radios	32 days @ $5/day each	800.00
7 Hand held Radios	13 days @ $5/day each	455.00
4 Hand held Radios	2 days @ $5/day each	40.00
3 Hand held Radios	1 day @ $5/day each	15.00
2 Hand held Radios	4 days @ $5/day each	40.00
10 Hand held Radios	23 days @ $5/day each	1,150.00
2 Generators	81 days @ $50/day each	8,100.00
Camp	81 days @ $400/day	32,400.00
2 ATV's	77 days @ $90/day each	13,860.00
1 ATV	3 days @ $25/day	270.00
Sat Phone	80 days @ $30/day	2,400.00
Brush Saw	18 days @ $25/day	450.00
2 Brush Saws	3 days @ $25/day each	150.00
2 ATV's (Val Geo Tech)	66 days @ $90/day each + PST	12,711.60
1 ATV (Val Geo Tech)	12 days @ $90/day + PST	1,155.60
Radio System Rental		5,312.50
Truck (Larocque)	30 days @ $80/day	2,400.00
Truck (National Car Rental)		196.22
GPS (Stark)	5 days @ $5/day	25.00
GPS (Charbonneau)	45 days @ $5/day	225.00
Chainsaw (Charbonneau)	11 days @ $25/day	275.00
GPS (Dennett)	22 days @ $5/day	110.00
Chainsaw (Kozenko)	5 days @ $25/day	125.00
Transportation:		
Fixed Wing		99,161.00
Scheduled Flights		10,384.72
Helicopter	53.3 hours @ $1,058.01/hr	56,391.95
Travel Expenses:		4,897.64

Fuel:			39,820.72
Field Equipment:			22,310.55
Analyses:			
Assay	1,851 samples @ $21.93/sample		40,598.41
Sub Contractor:	Expediting		11,749.76
	Geophysical		48,857.78
	Road Building		33,375.50
	Drilling		171,711.35
	Geological		962.50
Government:	Filing Assessment		2,291.50
	Staking		386.50
Communication:	Telephone		2,424.96
Freight:			13,534.94
Reproduction:	Maps		72.21
	Reports		16.26
Miscellaneous:			465.87
Food:			22,353.61
Accommodation:			3,774.92
Vehicle Expense:			359.51
Warehouse / Storage:			1,054.97
	TOTAL	$	938,698.05

22. STATEMENT OF QUALIFICATIONS

I, R.J.Johnston, am a graduate of the University of Saskatchewan with a B.Sc. (Advanced) 1982, in Geological Science.

I, R.J.Johnston, am a member of the Association of Professional Engineers and Geoscientists of the Province of BC (P.Geo.), registration number 19253.

I have practiced my profession since graduation in Western Canada, Mexico and Central America.

I, R.J.Johnston, supervised the 2009 exploration programme outlined in this report and personally oversaw the diamond drill programme.

Dated this 26th day of January, 2010.

_____

R.J.Johnston P.Geo.

23. REFERENCES

Archer, A.R. and C.A. Main, (1971): Casino, Geochemical Exploration; CIM Special Volume 11, pp.67-77.

Bakke, A.A., (1995): "Porphyry" Gold deposit, Porphyry Deposits of the Northwestern Cordillera of North America, Fairbanks Gold Mining Inc., CIM Special Volume 46.

Geological and Geophysical Surveys, Staff of, (2000): Alaska's Mineral Industry 1999, Division of Mining, Land & Water, Special Report 54, Appendix D, p.55.

Bower B., J. Payne, C. DeLong and C.M. Rebagliati, (1995): The Oxide-Gold, Supergene and Hypogene Zones at the Casino Deposit, West Central Yukon; CIM Special Volume 46, pp.352-366.

Carne, R.C., (1987): Report on Geochemical survey on the Ana Property, Casino Area, Yukon; Assessment Report.

Chapman J. and G.L. Garratt, (1993): Geological, Geochemical and Diamond Drilling Report on the Ana Claims dated October, 1993. Vancouver Petrographics Ltd. Thin Section Report by John Payne dated October 1993; Assessment Report, 36 pages with attachments.

Chapman J. and G.L. Garratt, (1993): Geological, Geochemical and Diamond Drilling Report on the Koffee Claims dated October, 1993, inc. Volume 2 – Attachments, Assessment Report, 27 pages with attachments.

Godwin C.L., (1976): Casino, Porphyry Deposits of the Canadian Cordillera, CIM Special Volume 15, pp. 344 – 345.

Geologic Survey if Canada, (1994): Airborne Geologic Survey, Selwyn River / West, Yukon Territory, 115 J/10, 11, 14, and 15.

Lindinger J.E.L., (1996): Report on the Canadian Creek Property, Dawson Range, Yukon Territory; dated December 2, 1996, 42 pages with attachments.

McMillan W.J., Thompson J.F.H., Hart C.J.R. and Johnston S.T., (1995): Regional geological and tectonic setting of porphyry deposits in British Columbia and Yukon Territory; CIM Special Volume 46, pp. 40-57.

Morton J.W., (1997): Report on Trenching, Road Rehabilitation and Road Construction on the Canadian Creek Property, dated January, 1997, inc. Vancouver Petrographics Ltd. Thin Section Reports by John Payne dated September 1996 and November, 1996; Assessment Report, 16 pages with attachments.

Morton J.W., (1998): Summary Report, The Canadian Creek Property, dated March 6, 1998; Assessment Report, 16 pages with attachments.

Morton J.W., (2000): Report on Rock and Soil Sampling and Road Reclamation the Canadian Creek Property, dated May, 2000; Assessment Report, 5 pages with attachments.

Morton J.W., (2001): Report on the year 2000 Diamond Drilling and Other Fieldwork completed on the Canadian Creek Property, dated January 23, 2001, Assessment Report, 14 pages with attachments.

Morton J.W., (2002): 2001 Target Evaluation Program, Canadian Creek Property, dated February 1, 2002; Assessment Report, 19p.

Morton J.W., (2002): Canadian Creek Property, dated October 15, 2002; unpublished report, 12p.

Morton J.W., (Dec. 20, 2003): Exploration Report on the Canadian Creek Property, Whitehorse Mining District, Yukon Territory, for Sargold Resources Corp. and Wildrose Resources Ltd., filed for assessment work requirements.

Morton J.W., (Jan 20, 2007): Summary Report of the 2006 field program o the Canadian Creek Property, filed for Assessment Work.

Morton J.W., (Dec 5, 2008): Summary Report of the 2008 Aster Image program on the Canadian Creek Property, filed for Assessment Work.

Morton J.W., Russell C.W.P.; (2009): Summary Report of the 2006 field program o the Canadian Creek Property filed on SEDAR as a National Policy 43-101 report.

M3 Engineering and Technology, (August 5, 2008): Casino Project Pre-Feasibility Study, Yukon Territory Canada, Prepared for Western Copper Corporation, as a technical report on the Western Copper Corporation web site.

Page Jay, W, (Feb 7, 2003): Compilation Report, A summary of the Exploration Programs and Results, the Canadian Creek Property, Whitehorse Mining District, Yukon Territory, with Recommendations for Further Exploration, for Canley Developments Inc., filed on SEDAR as a National Policy 43-101 report.

Page Jay, W, and Morton J.W., (October 25, 2006): Summary Report on the Canadian Creek Property with Recommendations for Continuing Exploration for North American Vanadium Inc. and Wildrose Resources Ltd. filed on SEDAR as a National Policy 43-101 report.

Payne J.G., R.A. Gonzalez, K. Akhurst and W.G Sisson, (1987): Geology of Colorado Creek, Selwyn River and Prospector Mountain Map Area; DIAND Open File 1987-3.

Selby D., R. Creser and E. Nesbitt, (1999): Major and trace element compositions and Sr-Nd-Pb systematics of crystalline rocks from the Dawson Range, Yukon, Canada, Canadian Journal of Earth Sciences, September 1999

Tempelman-Kluit, D.J. (1973): Geology, Snag Mapsheet; GSC Map 16-1973.


Tempelman-Kluit, D.J. (1974): Reconnaissance Geology at Aishihik Lake, Snag and part of Stewart River Map Areas; GSC Paper 73-41.

Thurston, B. (1994): Drill Summary in Pacific Sentinel Gold Corp information package, unpublished, 32p.

Titley, E. D, (Feb 2004): Report Revised Resource Estimate, Casino Property, Yukon Territory, for Lumina Copper Corp.

APPENDIX 1

Drill Sections CC09-01 – 10
Figures 15-22




Cariboo Rose Resources Ltd.
Alder Resources Ltd.


Canadian Creek Property

Drill Section
CC09-01

Looking West

Date: Nov 10, 2009	Scale: 1:1000	Figure 15
Projection: UTM zone7 NAD83	NTS: 115J/10,11,14,15	
Drawn by: MJD	File: CanCk_09DDHsects	


LEGEND
Lithology
GN gneiss
GD granodiorite
FI foliated intrusive
MO monzonite
Alteration
Lithology
Drill hole
Au (ppb) values
Alteration
clay
sericite-sausserite
clay/sericite-sausserite
6959000mN
606350mE
6959050mN
6959100mN
CC09-02
1550mRL
1525mRL
1500mRL
1475mRL
1450mRL
1425mRL
1400mRL
6958950mN
6959000mN
606350mE
6959050mN
0.6
<0.5
<0.5
<0.5
16.1
2.9
6.5
<0.5
<0.5
<0.5
3.5
1.7
<0.5
2.8
<0.5
<0.5
<0.5
<0.5
<0.5
2.9
16.8
4
31
17.6
41.5
61.2
28.3
53
59.6
3.9
4.2
30.1
3.6
<0.5
6
3.5
5.6
<0.5
2.8
13
3.7
55.7
<0.5
0.8
30.5
35.1
9.9
21.6
24.6
198.6
24.4
69.6
16.4
3m @199ppb Au
CC09-02
163.1m
0
10
20
30
50
metres
Cariboo Rose Resources Ltd.
Alder Resources Ltd.
Canadian Creek Property
Drill Section
CC09-02
Looking West
Date
Nov 10, 2009
Scale
1:1000
Projection
UTM zone7 NAD83
NTS
115J/10,11,14,15
Drawn by
MJD
File
CanCk_09DDHsects
Figure
16




Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

Drill Section
CC09-03, 04

Looking West

Date: Nov 10, 2009	Scale: 1:1000	Figure 17
Projection: UTM zone7 NAD83	NTS: 115J/10,11,14,15	
Drawn by: MJD	File: CanCk_09DDHsects	



Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

Drill Section
CC09-05

Looking West

Date: Nov 10, 2009	Scale: 1:1000	Figure 18
Projection: UTM zone7 NAD83	NTS: 115J/10,11,14,15	
Drawn by: MJD	File: CanCk_09DDHsects	


Cariboo Rose Resources Ltd.
Alder Resources Ltd.


Canadian Creek Property

Drill Section
CC09-06,07

Looking West

Date: Nov 10, 2009	Scale: 1:1000	Figure 19
Projection: UTM zone7 NAD83	NTS: 115J/10,11,14,15	
Drawn by: MJD	File: CanCk_09DDHsects	






Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

Drill Section
CC09-08

Looking West

Date: Nov 10, 2009	Scale: 1:1000	Figure 20
Projection: UTM zone7 NAD83	NTS: 115J/10,11,14,15	
Drawn by: MJD	File: CanCk_09DDHsects	




Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

Drill Section
CC09-09

Looking West

Date: Nov 10, 2009	Scale: 1:1000	Figure	21
Projection: UTM zone7 NAD83	NTS: 115J/10,11,14,15		
Drawn by: MJD	File: CanCk_09DDHsects		



Cariboo Rose Resources Ltd.
Alder Resources Ltd.

Canadian Creek Property

Drill Section
CC09-10

Looking West

Date: Nov 10, 2009	Scale: 1:1000	Figure 22
Projection: UTM zone7 NAD83	NTS: 115J/10,11,14,15	
Drawn by: MJD	File: CanCk_09DDHsects	

APPENDIX 2

Drill Logs CC09-01 - 10

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests					
Hole # CC09-01	NAD 83 Z7 UTM E 605173	depth	corrected dip				
Depth (m); 137.19	UTM N 6958510	137.19	-42		Start Date: Aug 31/09		
Core size; NTW	Azimuth: 178°				Completion: Sept 1/09		
Drilled by; Kluane Drilling	Inclination: -44 °	GRID W	101+85W		Logged By: Johnston		
NOTES;	Elevation: 1452m	GRID N	124+41N		Date logged; Sept 3-6/09		

CC09-01

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	4.98	casing										
4.98	10.20	**qtz-biot gneiss**	**GN**	937001	4.98	7.98	3.0	102	64.9	3.1	1.9	0.3
		strongly foliated; local rafts of bk-bn biot, gn chl; complete surface weath to 7m; strong feox frax after		937002	7.98	10.93	2.95	100	37.1	13.2	0.8	0.3
		8m; local dk gn chl vns with tr py										
		10.2m; sharp 30CA contact										
10.2	13.44	**mg granodiorite**	**GD**	937003	10.93	13.44	2.51	96	71.9	7.7	2	1.9
		1-2mm qtz, felds; most of biots to lt bn ser-biot alt; or-bn surface weath throughout										
		sharp 60CA lower contact										
13.44	16.3	**gy quartzite**	**GN**	937004	13.44	16.3	2.86	101	317	13.7	13.5	0.3
		upper 0.4m soft, broken										
		14.2m; 5cm high CA zone of bk-rd clay with strong Mnox; after goes into qtz-limonite zone; local discrete qtz vns to 1cm at 30-40CA; locally strong limonitic boxwork (ex py?)										
16.3	30.75	**qtz-biot gneiss**	**GN**	937005	16.3	19.3	3.0	100	7.7	<0.5	4.9	0.1
		competent boring qtz-biot gneiss; tr diss sx; local cg qtz-feld peg? dykes to 2cm; local gn chl frax with bleaching, biot alt to chl in wallrock		937006	19.3	22.3	3.0	100	4	<0.5	0.4	0.2
		23.9m; 3cm 45 CA po vn		937007	22.3	25.3	3.0	100	6.4	3.5	0.4	0.8
		27.65-29.1m; wh fg-mg aplite dyke with gn tinge; bn Fe carb alt frax		937008	25.3	27.65	2.35	100	4.1	<0.5	0.7	0.2
30.75	50.0	**lt gn saus alt qtz-biot gneiss**	**GN-S**	937009	27.65	30.75	3.1	100	4.7	<0.5	0.5	0.1
		as above with pervasive saus alt; includes mg aplite dykes; tr sx; local (1-2/m) 1-3mm qv's with minor py, local open spaces with qtz xtls; local Feox		937010	30.75	33.75	3.0	100	357.2	22.2	3.1	4.2
		33.8-35.7m; unalt gnss		937011	33.75	36.75	3.0	100	21.9	0.9	1.1	1.3
		36m; 0.5m with fine bk py stringers 0-10CA		937012	36.75	39.75	3.0	100	63.7	3.1	1.8	0.3
				937013	39.75	42.75	3.0	100	112.6	7.9	1.2	0.2
				937014	42.75	45.75	3.0	100	68.3	3.8	1.6	0.4
				937015	45.75	48.75	3.0	100	138.1	6.1	1.8	0.2
50	71.3	**qtz-biot gneiss**	**GN**	937016	48.75	51.75	3.0	100	72.5	5	0.9	0.3
		local gn saus alt sections make up 30% of interval; minor py in low CA vns		937017	51.75	54.5	2.75	100	5	3	0.4	0.2
		54.5-57.5m; gn ser alt		937018	54.5	57.5	3.0	100	91.8	8.5	2.2	0.2
		64m; 0.5m of gn ser-saus alt around 0CA gn chl vns with py in wallrock		937019	57.5	60.5	3.0	100	30	4.1	1	0.1
		66.8m; 0.4m of strong gn ser alt, incl single 60CA 2cm py vn		937020	Standard CDN-GS-1C				335.8	827.9	26.8	0.2
		69.35m; 2cm 30CA wh qtz vn with minor py, po, tr cp with 2cm gn ser-saus alt halo		937021	60.5	63.5	3.0	100	2.8	<0.5	0.7	0.1
				937022	63.5	66.5	3.0	100	4.9	1.3	0.9	<0.1
				937023	66.5	67.5	1.0	100	16.3	1.1	2.9	0.4
				937024	67.5	70.5	3.0	100	22.4	7.2	1	1.2
				937025	70.5	73.5	3.0	100	20.4	1.6	2.4	0.1

CC09-01												
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
from	to											
71.3	78.6	**strongly ser-saus alt qtz-feld-biot gneiss**	**GN-S**	937026	73.5	76.5	3.0	100	49.8	6.8	7.2	0.6
		minor diss wh eu py; v strong alt obscures textures as 71.13-75, 76-78.5m										
		75.9m; 3mm aspy blob on frac										
		78.04m; minor mo in frac										
78.6	86.8	**foliated diorite**	**FI**	937027	76.5	79.5	3.0	100	67.1	3	3.9	0.3
		mg-cg intrusive with strong foliation; wk saus alteration; local cg qtz-feld peg dykes/veins; tr diss py		937028	79.5	82.5	3.0	100	9.7	5.2	10.6	0.5
				937029	82.5	85.5	3.0	100	2	2.7	0.4	0.1
86.8	89.50	**mod ser alt cg granodiorite**	**GD-S**	937030	85.5	88.5	3.0	100	2.9	0.9	1	<0.1
		local gn saus alt felds; local qtz-feld peg vns										
89.5	122.2	**cg granodiorite**	**GD**	937031	88.5	91.5	3.0	60	2.8	<0.5	4.4	0.1
		local foliation; local ser-saus alt zones; tr py on frax		937032	91.5	94.5	3.0	80	6.9	0.7	4.9	0.2
		92.8m; 0.5m of strong alt in strongly foliated interval; shear?		937033	94.5	97.5	3.0	100	24.1	5.1	5.6	0.3
		92.25-95.7m; strong 70, 60CA contacts on wh-gn cg qtz-ser aplite?		937034	97.5	100.5	3.0	100	159	12.8	12.4	0.5
		95.8-96.45m; sim aplite to above but contacts not well defined		937035	100.5	103.5	3.0	100	5.5	<0.5	4.8	0.4
		98.4-100.9m; strong gn ser alt includes 20cm of strong 90CA fabric (shear) at 98.7m		937036	103.5	105	1.5	100	69.6	4.4	3.2	5.8
		99.6m; sgl 2mm 20Ca py vn		937037	105	105.5	0.5	100	2.4	207.7	3.8	57
		102.5m; 15cm xeno of biot gneiss		937038	105.5	108.5	3.0	100	1.8	0.6	1.7	0.5
		103.2m; 0.6m ser+ep alt zone with 30CA fabric; original texture gone		937039	108.5	111.5	3.0	100	0.8	3.8	0.6	0.4
		105.2m; 4cm 40CA gy fg qtz vn with minor py		937040	Standard CDN-GS-1C				339.4	866.5	35.2	0.3
		110.2m; 5mm 10CA qtz vn with minor mo		937041	111.5	114.5	3.0	100	1.7	<0.5	1.3	<0.1
		106-114m; v fresh; no alt		937042	114.5	116.5	2.0	100	2.9	<0.5	0.9	1.7
		116.8m; 2cm 50 CA gy qtz vn with local py; minor ser alt wallrock		937043	116.5	119.5	3.0	100	37.3	2.3	2.1	1.6
		117.4-118.5m; gn saus alt around 30CA foliated zone with no texture left; minor qv's		937044	119.5	122.5	3.0	100	30.4	4.2	1.5	0.9
		118.8m; 0.25m of strong gn saus alt										
		119.8m-120.5m; strong gn saus alt; includes 2cm 30CA fg gy qtz vn with minor py at 120.0m										
122.2	137.19	**biot-feld gneiss**	**GN**	937045	122.5	124.5	2.0	100	3.3	8.8	2	6.1
		dk bn biot to 30%; wh feld porphyroblasts to 2cm; 1-3% py; local granodiorite dykes		937046	124.5	126.2	1.7	100	491.2	17.5	12.1	0.7
		124.5-125.9m; gn ser-saus alt granodiorite dyke		937047	126.2	129.2	3.0	100	85.9	9.1	21.1	1.9
		125.7m; 5mm 30CA fg gy qtz vn with py		937048	129.2	132.2	3.0	100	261.4	17.3	11.1	1.8
		131-end of interval; gn ser-saus alt dykes to 0.5m		937049	132.2	135.2	3.0	100	62.9	7	1.4	0.6
				937050	135.2	137.19	1.99	100	18.4	6.3	0.6	2.1
		EOH		937050	135.2	137.19	1.99	100	18.4	6.3	0.6	2.1

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests					
Hole # CC09-02	NAD 83 Z7 UTM E 606327	depth	corrected dip				
Depth (m); 163.10	UTM N 6959075	none	taken	Start Date: Sept 2/09			
Core size; NTW	Azimuth: 156°			Completion: Sept 4/09			
Drilled by; Kluane Drilling	Inclination: -44 °	GRID W	79+81	Logged By: Johnston			
NOTES;	Elevation: 1556m	GRID N	129+19	Date logged; Sept 6-8/09			
CC09-02							

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	9.14	casing										
91.40	9.47	intrusive boulder rubble										
9.47	12.19	**soft gn clay - gneiss?**	**GN-C**									
		poor recovery		937051	9.47	12.19	2.72	37	4.3	0.6	0.6	0.2
12.19	22.0	**qtz-feld-biot gneiss**	**GN**	937052	12.19	15.24	3.05	23	7	<0.5	0.6	1.5
		surface weath on frax; local cc, vns; minor diss py with inc biot		937053	15.24	18.24	3.0	106	0.8	<0.5	1.2	0.5
		18.3-end of interval; strong or feox on frax		937054	18.24	20.24	2.0	100	4.5	<0.5	0.9	0.7
		21-22m; v strong soft gn clay zones in wallrock around 2 x 1cm 30CA qtz-py vns		937055	20.24	22.3	2.06	101	528.8	16.1	2	3.6
22.0	31.62	**gn clay-saus alt gneiss**	**GN-CS**	937056	22.3	25.3	3.0	95	544.6	2.9	1	0.5
		contains wh feld porphyroblasts; mod broken; soft, with local intervals completely gone to gn mud as 23.3-24.5m		937057	25.3	28.3	3.0	90	1440.5	6.5	0.4	0.5
		22-26m; abund soft gn clay with local comp frags; v broken		937058	28.3	31.3	3.0	97	11.4	<0.5	0.3	0.3
		26-end of interval; core more comp										
		31.2-31.62m; v broken, feox stained										
31.62	40.8	**gn ser alt foliated diorite**	**FI-S**	937059	31.3	34.3	3.0	105	7.9	<0.5	0.5	0.2
		bk biots to 5mm; felds locally to 1cm		937060	Standard CDN-GS-1C				374	975.7	32.6	0.2
		36.05-36.54m; bn biot gneiss; sharp 80CA contact at top; 30CA shear contact at bottom		937061	34.3	36.65	2.35	82	12.7	<0.5	1.5	0.1
		36.65-39.4m; v strong gn clay alt		937062	36.65	39.4	2.75	104	148.1	3.5	1.6	1
		39.6m; 0CA 3mm qy qtz vn with strong ser alt wallrock		937063	39.4	40.8	1.4	112	796.9	1.7	13.4	0.4
		40.7m; 10CA 2mm qtz vn with red sp										
40.8	43.1	**dk bn biot gneiss**	**GN**	937064	40.8	43.1	2.3	100	144.1	0.7	4.5	0.8
		minor qtz; diss py to 0.5%; sharp contacts; 80CA upper 60CA lower										
43.1	52.05	**medium grained granodiorite**	**GD**	937065	43.1	46.1	3.0	100	19.1	<0.5	0.6	0.2
		5% biots to 2mm; local zones of gn ser alt; local biot gneiss xenos		937066	46.1	49.1	3.0	110	66.6	2.8	1.5	0.6
		45.75m; 0.4m of strong or feox stain along 20Ca frac		937067	49.1	52.05	2.95	67	12.9	<0.5	1	0.4
		46-47.5m; strong gn ser alt around 3mm 10CA qtz vn										
		47.5m; 30cm of broken core with strong feox										
		51.0m; 15cm of broken core with strong feox										
52.05	54.8	**dk gy-bk biot-qtz gneiss**	**GN**	937068	52.05	54.8	2.75	103	16.1	<0.5	3	0.2
		minor diss py, local 1cm metamorphic py masses; locally weakly magnetic										
		52.3m; 0.4m granodiorite dyke										
54.8	66.3	**mixed saus alt granodiorite and qtz-feld biot gneiss**	**GD-S**	937069	54.8	57.8	3.0	100	30.5	<0.5	1.6	0.3
		prob large gneiss xenos in granodiorite; wh feld porphyroblasts in gnss		937070	57.8	60.8	3.0	100	18.1	<0.5	1.2	0.2
		56.2m; 1cm 30CA qtz vn with fg py in granodiorite; gn-bn ser alt in wallrock		937071	60.8	62.9	2.1	100	8.4	<0.5	0.7	0.2

CC09-02												
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
from	to											
		58.4m; 2mm 30CA py vn		937072	62.9	65.0	2.1	103	595.7	19.8	4.7	3.2
		58.55m; 1cm 30CA qtz vn with minor py; 2cm clay alt halo; perpendicular to 58.4m py vn		937073	65.0	66.3	1.3	97	112.9	89.1	2.3	1.2
		58.65-59.0m; 40CA fabric in gy met qtz										
		62.9-66.3m; strong gn ser alt granodiorite with 0-20CA py vns to 5mm; 1-2veins/metre; sharp upper 70CA contact; lower contact diffuse										
66.3	68.0	**qtz-feld biot gneiss**	**GN**	937074	66.3	69.3	3.0	100	11.9	2.9	0.8	0.2
		wh feld porphyroblasts										
68.0	79.0	**mixed saus alt granodiorite and qtz-feld biot gneiss**	**GD-S**	937075	69.3	72.3	3.0	100	31.1	16.8	1.3	1.3
		as above; local mod saus alt; local py on frax		937076	72.3	74.5	2.2	100	34.1	4	0.7	0.5
		71.4-71.6m; v broken core; incl 30CA gy qtz vn with py		937077	74.5	77.2	2.7	100	591.6	31	2.1	3.8
		72.4m; 2mm 60CA py vn with chl alt wallrock		937078	77.2	80.2	3.0	96	112.6	17.6	1.9	1.1
		74.5-77.2m; strong gn saus alt gneiss with 1-2mm low CA py; up to 2-3/m										
		75.3m; 2cm 20CA gy qtz-pk k-feld vn with 30% py, minor aspy										
		79.7m; 2mm irreg 10CA wh py vn in saus alt granodiorite										
79.0	102.0	**mod-strong saus alt granodiorite**	**GD-S**	937079	80.2	83.2	3.0	94	2010.8	41.5	5.2	13
		pervasive gn saus alt; locally abundant py vns		937080	Standard CDN-BL-4				8.7	1.4	0.4	<0.1
				937081	83.2	86.6	3.4	101	437.7	61.2	2.5	5.1
		80.1m; 7mm 30CA qtz-py vn		937082	86.6	89.6	3.0	100	384.6	28.3	2.9	2
		81-82.5m; 0CA fracture zone; clay alt, soft, broken; incl 1-2mm py vns		937083	89.6	92.6	3.0	102	393.9	53	3.7	3
		84.5-86.5m; strong saus alt'n with abund low-mod CA py vns; almost a stockwork; veins of py, also fine bk sulfide, poss aspy, cp; up to 15 vns/metre		937084	92.6	95.6	3.0	100	148.1	59.6	1.8	2.6
		86.5-95m; 1-2 py vns/metre		937085	95.6	98.6	3.0	103	76	3.9	1.3	0.7
		88.9m; 10cm red feox clay zone		937086	98.6	101.5	2.9	90	51.3	4.2	1.3	0.5
		89.6m; 40CA 8mm qtz vn with py, fine bk sx										
		90.2-92.4m; v broken, clay alt'n; 0.5% wh eu diss py on frax										
		92.4-99m; py vnlts to 5 vns/m										
		94.5-95.0m; crackle bx with bk sx on frax										
		98-101m; strong feox on frax										
		101.5-103m; soft gn ser-chl clay alt; local met qtz frags; granodiorite-gneiss contact somewhere in middle										
102.0	120.45	**qtz-feld-biot gneiss**	**GN**	937087	101.5	103.4	1.9	100	476	30.1	2.5	1.9
		locally abund py stringers in ser-saus alt'n haloes; local soft clay alt zones to 0.5m		937088	103.4	106.4	3.0	100	41.7	3.6	0.6	0.6
		102.65m; 2x 30CA 5mm py-bk sx vns		937089	106.4	109.4	3.0	100	13.9	<0.5	0.9	0.7
		107.0m; 0.4m zone of lt gy-gn ser alt around fine py stringers		937090	109.4	112.4	3.0	100	16.3	6	0.7	0.9
		110.0-116.5m; local soft wh clay alt zones to 0.5m		937091	112.4	115.4	3.0	100	12.7	3.5	0.5	0.5
		112.2m; 0.3m sl bleached zone around fine py stringers		937092	115.4	118.4	3.0	100	112.4	5.6	0.6	0.9
		116.7m; 2mm 30CA py vn at bottom of 0.3m gn saus alt interval		937093	118.4	121.4	3.0	100	4.2	<0.5	0.2	0.2
120.45	123.2	**leucocratic granodiorite**	**GD**	937094	121.4	124.4	3.0	100	8.9	2.8	0.5	0.4
		5% biotites, wk gn chl alt mafics; boring; high CA chill margin at upper contact; lower contact in zone of broken core										
123.2	163.1	**qtz-feld-biot gniess**	**GN**	937095	124.4	127.4	3.0	100	20.2	13	0.7	1.7
		local zones of gn saus+/-ser+/-clay alt'n inc to bottom of hole, with py vns, stringers; minor wh gyp on frax; local 1cm chl bands with 2% mg py		937096	127.4	130.0	2.6	102	143.8	3.7	0.5	0.4
		124.5m; 0.3m saus alt zone with fine py stringers		937097	130.0	132.8	2.8	103	227.1	55.7	1.3	3.4

CC09-02												
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
from	to											
		126.8m; 0.4m wide broken saus-clay alt zone with py stringers, minor diss eu py		937098	132.8	135.8	3.0	88	2.2	<0.5	0.3	0.3
		127-134.8m; wk saus alt		937099	135.8	138.8	3.0	103	2.7	0.8	0.5	0.5
		130-132.8m; strong gn ser-saus-clay alt; py vns up to 3vns/metre at low-mod CA's; local carb vns; local soft gn-turquoise mineral; anhydrite?		937100	Standard CDN-GS-1C				355.8	815.4	32.6	0.2
		138-145.15m; wk-mod gn saus alt with minor diss py; local 0CA qtz-py vns; incl strong alt from 139.6-141.9m with 1% py, local crumbly clay alt intervals		937101	138.8	142.0	3.2	102	1144.6	30.5	1.5	2.1
		146.5m; 0.2m strong ser alt zone alt around py vns		937102	142.0	145.15	3.15	103	463.6	35.1	1	2.9
		147.1-147.83m; cg granodiorite dyke; sharp 70CA upper, 80CA lower contact in 1cm clay alt zone		937103	145.15	148.15	3.0	104	17.3	9.9	0.7	0.7
		147.83-148.4m; mod gn ser-saus alt with 0CA py vns to 2mm		937104	148.15	151.15	3.0	93	513.2	21.6	1.4	2
		149.55-150.26m; gn saus alt cg granodiorite dyke		937105	151.15	154.15	3.0	107	617.6	24.6	1.6	3.3
		150.26-157.6m; wk-mod ser-saus alt with low CA 1-2mm py vns; 1-3vns/metre overall; 155-157m vns inc to 5-10/metre; 156m; 1cm 10CApy vn		937106	154.15	157.15	3.0	95	857.8	198.6	2.7	34.8
		157.6-159.4m; wk saus alt		937107	157.15	159.4	2.25	101	53.7	24.4	0.9	2.4
		159.4-160.18m; strong gn saus alt around 7mm dk gy-gn 0CA qtz vn with 5% py, minor aspy		937108	159.4	160.18	0.78	100	4609.5	89.6	2.5	12.1
		160.18-end of interval; mod saus alt, local ep		937109	160.18	163.1	2.92	100	122.4	16.4	0.9	1
		162.5m; 30cm strong alt zone around 2cm 20CA py vn										
		EOH										

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests							
Hole # CC09-03	NAD 83 Z7	depth	corrected dip						
Depth; 152.43	UTM E 606546								
Core size; NTW	UTM N 6958859	152.43	-48		Start Date: Sept 4/09				
Drilled by; Kluane Drilling	Azimuth: 175°				Completion: Sept 6/09				
NOTES;	Inclination: -43 °	GRID W	77+98		Logged By: Johnston				
CC09-03	Elevation: 1583m	GRID N	126+75		Date logged; Sept 8-11/09				

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	4.57	casing										
4.57	23.90	**feld-biot gneiss**	**GN**	937110	4.57	7.62	3.05	82	128.1	5.8	3.2	1.2
		chl alt, feox, abund jarosite on frax; local soft gy clay alt zones		937111	7.62	110.67	103.1	92	248.3	17.3	4.6	1.2
		strong surface ox'n, v broken to 10m; local ferricrete, jarosite in open spaces; Fe-Mnox		937112	110.67	13.67	97	92	243.1	3.9	3.1	0.7
		12-18.m; less broken, still strong Fe-Mnox on frax		937113	13.67	15.67	2.0	103	207.9	4.2	2.3	0.5
		18-23m; local unweath intervals; Fe-Mnox, jarosite cont on frax; local low CA cg py vns		937114	15.67	18.1	2.43	110	155.3	7	2.7	0.7
				937115	18.1	21.1	3.0	90	959	33.7	4.7	1.6
				937116	21.1	24.0	2.9	93	354	23.8	3.5	1.3
23.9	37.5	**dk gy-bk feld-biot gneiss**	**GN**	937117	24.0	27.0	3.0	96	173.3	13.6	3.4	0.9
		diss py to 0.5%; chl alt from 30m; Feox, local py on frax		937118	27.0	30.0	3.0	106	267.7	27.1	1.4	5.4
		27.5-30m; 2 x 2,4mm 20CA wh qtz vns with open spaces, local py; 2nd vn with geothite		937119	30.0	33.0	3.0	94	266.7	6.6	1	0.7
		34.9m; 2mm 80CA py vn		937120	Standard CDN-CM-5				41	312.8	5.8	0.3
		36.9m; 0.3m granodiorite dyke		937121	33.0	35.0	2.0	100	348.7	4.4	1.3	1
				937122	35.0	37.5	2.5	104	69	20.1	0.8	3.1
37.5	44.2	**soft, broken clay alt zone**	**GN-C**	937123	37.5	40.9	3.4	80	493	71.7	0.9	4
		37.5-40.9m; core comp gone to y-or clay		937124	40.9	42.68	1.78	106	114.9	23.4	0.7	1.4
		40.9-42.68m; mod soft ser-chl alt gneiss with y-or clay, pyrolusite on frax; local diss py; incl 1cm 20cm qtz vn with py cubes in vugs										
		42.68-44.2m; core comp gone to y-or clay										
44.2	61.0	**soft dk-lt gn wk-mod ser-saus alt feld-qtz-biot gneiss**	**GN-S**	937125	42.68	44.2	1.52	63	10	4.4	0.8	0.5
		local broken zones; Feox on frax; diss py to 0.5%; common limonite coated pits - ex py?; local zones of qtz veining with open spaces, py to 1%; strong y stain in feldspars, mafics in competent core; not jarosite, Mo stain		937126	44.2	47.2	3.0	105	181.8	21.1	1.9	2.2
		47.0m; 0.25m wide 10CA porphyry dyke; 1-10mm wh felds in gn groundmass, fine diss py		937127	47.2	50.2	3.0	100	179.9	30.3	1.6	3.2
		48.0m; 10CA frax with eu py and metallic pyrolusite?		937128	50.2	53.2	3.0	106	248	59	2.7	19.2
		51.5m; 0.75m granodiorite dyke; other dykes to end of interval		937129	53.2	56.2	3.0	100	224.6	48.3	2.4	5
		52.5m; local fine qtz vns at various CA's with tr py		937130	56.2	59.2	3.0	98	137.3	28.6	1	2.9
		55.0-56.5m; 0CA 1-2mm qtz-carb-py vns		937131	59.2	62.2	3.0	97	150.7	38.8	1.4	7.4
		54-end of interval; strong gn chl alt, (with anhydrite?); and more yellow stain; diss py to 1%; abund vugs now filled with py xtls; common 0CA qtz-carb vns										
		59.0-60.0m; v broken, gn clay alt'n; wh py throughout										
61.0	69.1	**strong ser-saus alt granodiorite**	**GD-S**	937132	62.2	65.2	3.0	106	1316.5	18.1	1.6	5.2
		gn saus alt felds; bk biots alt to fg bn biot; minor diss py; local gneiss xenos?		937133	65.2	68.2	3.0	101	82.6	13.2	1.2	4.2
		63.9-65.9m; chl alt gneiss; incl 10cm mass of chl with wh mg py, minor aspy, at 64.5m										
		68.3m; 0.75m with 2-3mm 30CA gn chl-py vns; diss py in wallrock										
69.1	80.5	**fg-mg granodiorite**	**GD**	937134	68.2	71.2	3.0	108	157.6	25.1	1	8.4

CC09-03													
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm	
from	to												
		as above, but less alt;minor ep; contains local (1-2vns/m) py vns +/-chl, carb, to 75m; xcut by fresher cg granodiorite dykes		937135	71.2	74.2	3.0	100	103.4	43.8	1.8	15.5	
				937136	74.2	77.2	3.0	100	65.9	8.9	1.3	1.9	
				937137	77.2	80.2	3.0	100	46.6	9.9	1.1	3.9	
80.5	123.5	**qtz-feld-biot gneiss**	**GN**	937138	80.2	82.2	2.0	100	46.4	5	1	3.8	
		wk-mod chl alt; local ser, saus alt zones; feld porphyroblasts to 3cm; minor diss, vein py; intervals of strong clay alt		937139	82.2	84.9	2.7	100	38.1	7.4	1.2	4.7	
		84.9m; 20CA contact with 0.3m gy-y broken strongly clay alt zone w 1% eu py vns;		937140	Standard CDN-BL-4				6.6	0.6	0.4	0.1	
		84.9-88m; y-wh clay on frax		937141	84.9	87.0	2.1	86	31	4.7	1.1	1.1	
		88-92m; wk-mod ser-saus alt; local eu py on frax		937142	87.0	90.0	3.0	103	43.9	5.6	1.4	1.3	
		93.5-95.15m; local 0CA chl py vns		937143	90.0	93.0	3.0	98	36.1	4.4	0.6	1.2	
		96.3m; 5cm 45CA wh clay alt shear?; y-wh clay on frax to 97.4m		937144	93.0	96.0	3.0	103	136.2	13	0.7	2.7	
		100.75m; 15cm soft gn ser alt shear; 1-2% eu py		937145	96.0	99.0	3.0	83	47.3	5.6	0.8	2.8	
		102-end of interval; chl alt		937146	99.0	102.0	3.0	100	80.8	4.1	0.9	1.4	
		102.5-109m; y-gn clay on local frax; local carb vns to 102m		937147	102.0	105.0	3.0	99	21.8	1.9	0.7	0.9	
		103.2-103.65m; soft v strong alt zone		937148	105.0	108.0	3.0	100	27.2	4.6	0.9	0.8	
		105-end of interval; local fresh leucocratic granodiorite dykes to 1m		937149	108.0	111.0	3.0	104	227.9	14.9	1.7	1.2	
		109-114m; 1-2 py vns/metre		937150	111.0	114.0	3.0	100	136.3	24.6	2.5	4.5	
		111.5-114m; gneiss with 1-2% diss, frax py		937151	114.0	117.0	3.0	100	98.6	14.5	3.6	2.3	
		119.95-120.5m; soft dk gn clay gouge?, incl 5mm wh carb vns, py to 10%; sharp 45CA upper contact		937152	117.0	119.95	2.95	100	47	13.2	1	1	
		123.3m; minor diss cp		937153	119.95	120.5	0.55	100	277.1	180.8	1.7	15.4	
				937154	120.5	123.5	3.0	100	102.7	20.6	2.3	2.5	
123.3	133.32	**wk ser alt fg diorite**	**GD**	937155	123.5	126.5	3.0	100	79.1	22.2	1.6	1.8	
		local coarser sections; lt gn throughout; hbs alt to fg biot; local wh carb vns to 5mm; local gneiss xenos		937156	126.5	129.5	3.0	100	249.4	8.5	1.4	1	
		128.5-130m; common 0CA 1mm py vns		937157	129.5	132.5	3.0	100	80.2	5	1.4	1	
		131.09m; 15cm of caved rock in corebox											
		132-end of interval; biot gneiss xenos to 1.8m											
		135.69-136.6m; lt gn saus-clay alt											
133.2	143	**qtz-feld-biot gneiss**	**GN**	937158	132.5	135.5	3.0	100	282.7	6	1.2	1.1	
		biot gneiss in upper 2m; local granodiorite dykes with local saus alt		937159	135.5	138.5	3.0	100	230.7	4.2	2.7	0.7	
		136.6m; 0.75m soft gn saus alt zone		937160	Standard CDN-CM-5				43.4	225.8	5.5	0.3	
				937161	138.5	141.5	3.0	100	218.2	3.7	0.6	0.8	
				937162	141.5	144.5	3.0	100	57.8	6.2	0.9	2.6	
143	152.43	**granodiorite**	**GD**	937163	144.5	147.5	3.0	100	150.3	6.5	0.8	0.8	
		local gn saus alt, minor py on frax, local ep on frax with py; incl local gneiss xenos		937164	147.5	150.5	3.0	100	42.7	6.1	0.8	0.6	
		147.9m; 2mm 30CA py vn with 20cm gn saus alt halo		937165	150.5	152.43	1.93	100	19.9	6.8	1	0.8	
		EOH											

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests						
Hole # CC09-04	NAD 83 Z7 UTM E 606546	depth	corrected dip					
134.14	UTM N 6958863	134.14	-55		Start Date: Sept 6/09			
Core size; NTW	Azimuth: 355°				Completion: Sept 7/09			
Drilled by; Kluane Drilling	Inclination: -53 °	GRID W	77+98		Logged By: Johnston			
NOTES;	Elevation: 1583m	GRID N	126+79		Date logged; Sept 11-13/09			

CC09-04

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	4.57	casing	OB									
4.57	5.20	rubble	OB									
5.20	17.50	**qtz-feld-musc-biot gneiss**	GN	937166	5.2	8.2	3.0	93	114.1	3.8	3.9	1
		v broken; local strong surface weathered zones; ferricrete in fractures		937167	8.2	11.2	3.0	99	244.9	10.4	3.4	1.5
		10m; 2-3mm 60, 90CA py vns		937168	11.2	14.2	3.0	91	101.6	125.1	2.3	2.2
		10.2-10.7m; bleached ser alt clayey zone		937169	14.2	17.2	3.0	97	205.3	27.1	4.7	2.7
		14-end of interval; lt gn mod saus alt										
		15.2-19.0m; wh qtz as veins, irreg blobs to 3cm										
		15.6m; bx of wh qtz with gnss fragments										
		16.8m; 0.25m with frothy qtz vns, local cg py; strong Feox cont										
17.5	23.2	**lt gn saus alt qtz-feld-musc gneiss**	GN-S	937170	17.2	20.2	3.0	100	67.7	12	2.4	2
		mod broken; minor Feox; local low CA bx zones to 3cm to 22m; minor diss py local 1mm py vns		937171	20.2	23.2	3.0	97	134.8	132.2	2.3	2.3
23.2	31.3	**qtz-feld-biot gneiss**	GN	937172	23.2	26.2	3.0	100	196.6	26.7	2.7	3.6
		chl alt; diss py to 0.5%; local cg qtz-feld pegmatite vns		937173	26.2	29.2	3.0	100	692.6	15.1	2.7	2.4
		27.4m; 2cm 10CA ferricrete zone		937174	29.2	32.2	3.0	100	266.9	13	6.3	1.3
		34.5m; 15cm v broken core with strong Feox										
31.3	52.0	**wk-mod saus alt leucocratic foliated granodiorite**	GD-S	937175	32.2	35.2	3.0	93	78.6	18.4	1.9	0.9
		fg and mg zones; some foliated intervals; local qtz-feld-biot gneiss; minor mafics to biot ;tr diss, vn py		937176	35.2	38.2	3.0	100	74.2	8.6	2	0.7
		42.5m; 2 x 1mm 70CA py vns		937177	38.2	41.2	3.0	100	274.9	22.8	2	1.3
		42.7-44.46m; qtz-feld-biot gneiss; feld porphyroblasts to 2cm; lower contact is 10cm clay zone		937178	41.2	44.2	3.0	103	49.4	4.7	1.1	0.7
		45.5-end of interval; local strong y-gn clay on frax, locally with eu wh py; felds locally yellow		937179	44.2	47.2	3.0	109	45	5.3	2.5	1.5
		51.6m; 1mm chl-py vn		937180	Standard CSN-CM-5				44.4	234.5	6	0.3
				937181	47.2	50.2	3.0	104	74.1	7.9	3.2	5.3
52.0	57.5	**qtz-feld biot gneiss**	GN	937182	50.2	53.2	3.0	88	37.9	23.9	3.5	15.3
		local wh saus alt; common calcareous clay zones with minor py; local ep vns in bottom 2m		937183	53.2	56.2	3.0	102	26.7	5.2	1.9	2.1
		54.2m; 1m of 0CA frax with strong y calcareous clay alt'n										
57.5	62.56	**fresh leucocratic monzonite?**	MO	937184	56.2	59.2	3.0	100	31.3	4.3	1.5	1.1
		5% bk biots; gn tinge; local chl, ep; minor feld xenos to 0.3m		937185	59.2	62.2	3.0	100	27.6	2.6	1.3	0.8
		60.3m; 2cm 45CA chl-py vn										
		sharp 70CA lower contact										
62.56	76.7	**foliated granodiorite**	FI	937186	62.2	65.2	3.0	100	36.5	3.4	0.8	10.2
		variably foliated from none to moderate; diss py, locally to 1%; ep diss and as frax +/-py; y calcareous clay on frax, strong from 66m		937187	65.2	68.2	3.0	100	29.5	8.9	1.8	0.7

CC09-04												
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
from	to											
		74.75-76.7m; dk gy-gn diorite dyke with gn saus alt		937188	68.2	71.2	3.0	83	25.5	4.1	1.9	0.5
				937189	71.2	74.2	3.0	54	23.6	7.1	2.2	0.5
76.7	105.5	**gn saus alt feld-biot gneiss**	**GN-S**	937190	74.2	77.2	3.0	100	45.9	7.1	1.2	0.6
		minor diss py; local chl-py vns; yellow calcareous clay on frax, less strong than above		937191	77.2	80.2	3.0	102	124.3	21.4	1.9	2.9
		78-79.5m; 4 x 1-2mm 30 CA py vns		937192	80.2	83.2	3.0	100	57	5.5	2.3	0.6
		82.2-84m; local qtz-chl-feld pegmatite vns to 0.3m		937193	83.2	86.2	3.0	100	39.5	6.3	1.5	0.3
		85.5-95m; local 1mm high CA py-carb vns; 1-2vns/m		937194	86.2	89.2	3.0	100	71	7.1	1.5	0.4
		89-end of interval; broken core, abund wh cc on frax, minor py		937195	89.2	92.2	3.0	100	88.5	33.9	1.1	0.6
		89-93m; minor 2-3mm py-qtz vns with ep, carb		937196	92.2	95.2	3.0	88	85.3	43.2	2.5	0.6
		91-94m; strong chl alt		937197	95.2	98.2	3.0	102	36.2	7.1	1.5	0.4
		101.5-end of interval; strong chl alt, local high CA py vns		937198	98.2	101.2	3.0	100	41.3	4.1	1.3	0.3
				937199	101.2	104.2	3.0	100	292.9	6.3	3.4	0.4
				937200	Standard CSN-CM-5				44.9	230	5.9	0.3
105.5	111.6	**lt gn saus-clay alt feld-biot gneiss**	**GN-S**	937201	104.2	107.2	3.0	96	82.9	22.9	2.6	0.4
		mod soft; gy qv's to 2mm with local py; tr diss py		937202	107.2	110.2	3.0	110	333.3	21.7	2.1	0.5
111.6	118.8	**chl alt qtz-feld-biot gneiss**	**GN**	937203	110.2	113.2	3.0	100	46.8	11.4	1.4	0.4
		competent; minor py in frax with ep; tr diss py; incl qtz-feld pegmatite vns to 5cm		937204	113.2	116.2	3.0	97	42.8	7.5	1.8	0.3
118.8	123.3	**fg-mg granodiorite**	**GD**	937205	116.2	119.2	3.0	102	14.7	2.8	1	0.3
		118.8-121.1m; fg granodiorite, lt gn ser-saus alt; textures gone; minor diss py, Feox		937206	119.2	122.2	3.0	95	7.7	2.1	0.7	0.2
		121.1-123.3; mg granodiorite; minor chl-ep frax		937207	122.2	125.2	3.0	100	7.5	3.9	0.4	0.4
123.3	134.14	**qtz-feld-biot gneiss**	**GN**	937208	125.2	128.2	3.0	100	9.3	3.6	0.5	0.3
		wk chl alt around local frax; 20% of interval is biot gneiss		937209	128.2	131.2	3.0	100	7.5	1.5	0.4	0.3
		125.05m; 40cm chl-qtz pegmatite vn with py masses to 7mm		937210	131.2	134.14	2.94	100	5.1	1.7	0.5	0.3
		126.15-128.0m; fg-mg monzonite dyke; 5% biots to chl; sharp 80CA contacts										
		132-end of interval; local rd Feox stain around frax with local musc on frax										
		EOH										

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests							
Hole # CC09-05	NAD 83 Z7	depth	corrected dip						
126.52	UTM E 607121								
Core size; NTW	UTM N 6959090	126.52	-48		Start Date: Sept 8/09				
Drilled by; Kluane Drilling	Azimuth: 330°				Completion: Sept 9/09				
NOTES;	Inclination: -45 °	GRID W	71+98		Logged By: Johnston				
CC09-05	Elevation: 1616m	GRID N	128+87		Date logged; Sept 14-16/09				

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	4.57	casing	OB									
4.57	6.05	rubble	OB									
6.05	25.6	**qtz-feld-biot gneiss**	GN	937211	6.05	9.14	3.09	45	12.2	1.4	1.9	0.5
		tr diss py; local v strong surface weathering to 14.5m		937212	9.14	12.14	3.0	73	38	5.3	2.3	4.6
		9.3-10.1m; competent unweath		937213	12.14	15.14	3.0	47	30.2	3.7	1.1	4.4
		10.2-11.7m; or weath; strong gn saus alt'n		937214	15.14	18.14	3.0	90	10	2	1	0.5
		11.7-12.1m; dh gy-gn chl alt weath		937215	18.14	21.14	3.0	100	14.3	3.5	1.2	0.6
		14.5-end of interval; comp unweath gneiss; rd-or Feox on frax		937216	21.14	24.14	3.0	97	4.4	0.7	0.8	0.6
				937217	24.14	25.6	1.46	99	3	1.3	0.5	0.8
25.6	28.1	**ser alt fg monzonite?**	MO	937218	25.6	28.1	2.5	84	92	12.7	0.8	1.6
		lt gn, soft, broken; Feox frax; minor diss py										
28.1	34.6	**qtz-feld-biot gneiss**	GN	937219	28.1	31.1	3.0	106	2.3	1.6	0.5	0.4
		surface weath on frax to 33.5m		937220	Standard CDN-BL-4				6	0.5	0.4	0.1
		32.2-32.95m; ser alt monzonite dyke as above		937221	31.1	34.1	3.0	94	28.2	7.3	1.2	1
34.6	39.0	**strong ser-saus alt qtz-feld-biot gneiss**	GN-S	937222	34.1	37.1	3.0	83	18.4	2.5	0.7	0.5
		v broken, clay alt; lt gn; local py to 0.5% on frax; includes ser alt monzonite dykes but hard to see contacts due to broken core		937223	37.1	39.0	1.9	99	970.5	49.7	2.7	1.6
		37.6m; dk gy sx (aspy?) with py on frax										
39.0	49.95	**qtz-feld-biot gneiss**	GN	937224	39.0	42.0	3.0	100	18.2	5.8	1.9	0.6
		unalt; competent; incl granodiorite dykes; minor py on feox, diss		937225	42.0	45.0	3.0	100	24.7	5.2	0.8	1.5
		39.7m; 1.5m mg granodiorite dyke with saus alt, local py on frax		937226	45.0	48.0	3.0	97	6.7	1.8	0.7	0.6
		42.6-44.02m; mg granodiorite dyke with saus alt, local py on frax; incl 10cm 90CA soft buff-bn clay alt interval at 43.7m with fine eu diss py		937227	48.0	49.95	1.95	106	2.5	0.9	0.8	0.6
		46.5-end of interval; local soft crumbly clay alt zones from 10-15cm										
49.95	53.65	**strong saus-clay alt qtz-feld-biot gneiss**	GN-S	937228	49.95	51.95	2.0	78	31.3	3.8	1.5	1.1
		lt gn, mod soft; minor diss, frax py; common calcite on frax; some lost core in interval		937229	51.95	53.65	1.7	88	18.5	2.6	1.6	1.1
53.65	54.87	**qtz-feld-biot gneiss**	GN	937230	53.65	54.87	1.22	104	2.6	0.9	0.8	0.3
		unalt										
54.87	92.4	**ser alt fg monzonite?**	MO-S	937231	54.87	57.87	3.0	85	71.2	36.1	2.1	3.2
		strong gn ser-saus-clay alt fg intrusive as above; soft, rubbly, abund clay; strong or staining, jarosite to 56.80m; gneiss xenos? make up 30% of interval		937232	57.87	60.87	3.0	90	92.2	42.9	2.4	3.3
		57.0-59.5m; bx zone; comp int frags in soft gn qtz-clay; yellow stain throughout		937233	60.87	63.87	3.0	90	180.7	71.9	2.4	3.8
		59.5-61.0m; mod soft, mod broken interval; lt gn saus musc alt, local yellow stain		937234	63.87	64.9	1.03	83	329.5	117.6	2.9	5.6
		61.0-62.5m; py to 0.5% in 1-2mm diss blebs and frax at various CA's		937235	64.9	65.24	0.34	100	790.5	531.1	94.2	183.9

CC09-05												
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
from	to											
		62.5-64.9m; v broken clayey gneiss; py to 1%		937236	65.24	68.24	3.0	81	849.7	185.7	2.2	4.7
		63.15m; 2cm wh high CA qtz vn with py in rubble		937237	68.24	71.24	3.0	99	165.6	103.4	2.1	7.8
		64.9-65.24m; soft dk gy-gn clay alt zone with 50% py		937238	71.24	74.24	3.0	95	112.8	26	1.9	6.4
		68.1, 68.8m; 5cm high CA clay-py zone as 64.9-65.24m		937239	74.24	77.24	3.0	100	102.5	18.5	1.5	1.6
		70-74m; py to 1% as diss, frax		937240	Standard CDN-CM-5				40.7	271.9	5.9	0.4
		72.5-73.6m; fault zone?; comp ang-round alt monz frags to 3cm in sandy gn clay; local y-gn stain		937241	77.24	80.24	3.0	87	67.4	8.7	1	0.9
		76.52-79.4m; lt-dk gn chl-saus alt gneiss; local y stain		937242	80.24	83.24	3.0	92	60.1	7.6	1.3	1
		79.4-90.5m; strong ser-saus alt, textures largely gone; minor py; local broken clay alt intervals; includes both monzonite and gneiss but hard to see contacts		937243	83.24	86.24	3.0	83	405.9	78.5	3.5	1.7
		86.4-90.3m; gneiss with bright yellow stained felds, mafics; not jarosite, Mo stain; as in hole CC09-03; 44-60m		937244	86.24	89.24	3.0	49	95.9	12.9	1.7	1.9
		91.8m; 0.3m interval with vfg bn-bk sx in irreg blebs, 60CA stringers, fine aspy		937245	89.24	92.24	3.0	98	41.1	7	2.8	0.9
		90.5-end of interval; wk-mod ser-saus alt gneiss; minor py, tr aspy										
92.4	95.05	**chl alt qtz-feld-biot gneiss**	**GN**	937246	92.24	95.24	3.0	100	8.9	6.1	1.3	0.3
		nod-strong chl alt; dk gn										
95.05	113.0	**ser-musc alt foliated intrusive**	**FI**	937247	95.24	98.24	3.0	100	30	7.8	1.2	0.5
		qtz diorite-granodiorite composition; prominent met fabric; lt gn, mod soft; texture locally destroyed; local eu yellow py as diss, frax		937248	98.24	101.24	3.0	99	26	3.5	1	0.4
		97-99.5m; strong alt, no textures left		937249	101.24	104.24	3.0	100	50.1	9.9	1.1	1
		111-112m; 3 x 1mm py vns		937250	104.24	107.24	3.0	97	72.3	9	1.8	1.3
				937251	107.24	110.24	3.0	78	52.9	26.8	1.3	1.5
				937252	110.24	113.24	3.0	90	75.9	65.7	1.7	27.7
113.0	119.0	**saus-chl alt feld-biot gneiss**	**GN-S**	937253	113.24	116.24	3.0	103	32.1	19.2	1	3.1
		lt-dk gn; incl feld porphyroblasts to 2cm; minor py as diss, frax		937254	116.24	119.24	3.0	97	51.3	17	0.9	2.7
119.0	124.2	**strong saus alt feld-biot gneiss**	**GN-S**	937255	119.24	121.24	2.0	100	90.3	43.6	1.7	4.1
		sim to above but with less saus alt; v broken core; local strong soft clay alt zones; minor diss py		937256	121.24	122.56	1.32	88	96.2	67.9	1.7	14.8
		122.56-123.8m; lost core										
124.2	126.52	**saus alt feld-biot gneiss**	**GN-S**	937257	123.8	126.52	2.72	92	41.1	27.1	1.3	3.7
		as above but with red-bn stain; minor py										
		EOH										

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests						
Hole # CC09-06	NAD 83 Z7 UTM E 607510	depth	corrected dip					
153.73	UTM N 6959204	no	test		Start Date: Sept 10/09			
Core size; NTW	Azimuth: 330°				Completion: Sept 11/09			
Drilled by; Kluane Drilling	Inclination: -60 °	GRID W	67+99		Logged By: Johnston			
NOTES;	Elevation: 1545m	GRID N	129+50		Date logged; Sept 16-17/09			

CC09-06

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	4.57	casing	OB									
4.57	6.70	rubble	OB									
6.70	10.5	**strong saus alt feld-biot gneiss**	GN-S	937258	5.0	8.0	3.0	98	15.3	175.1	2.9	2.4
		lt gn; strong alt, weathering destroys most of texture; strong surface as Fe-Mnox on frax		937259	8.0	11.0	3.0	93	47.3	193	14.6	4.1
10.5	32.6	**saus alt fg-mg monzonite?**	MO-S	937260	Standard CDN-CM-5				42.1	225.4	5.5	0.3
		lt gn-gy alt, again most of texture is gone; 0.5% diss py, locally to 1%; local 1-2mm qtz-py vns at various CA's		937261	11.0	14.0	3.0	65	30.1	596.6	16.2	3.7
		strong surface weath to 16.6m		937262	14.0	17.0	3.0	103	58.1	540.6	85.6	6.9
		20.5-23.5m; stwk of dk gy ser-py vns		937263	17.0	20.0	3.0	100	55.2	146.3	4.8	5.3
		21.2m; 7mm wh-gy qtz vn with py, ex-py boxwork		937264	20.0	23.0	3.0	106	49.7	73.1	20.2	4.1
		27.1m; 1cm 30CA banded py-fg gy qtz vn; also 2 sets of py-lim stringers cont to 30m		937265	23.0	26.0	3.0	98	20.4	34.2	34.4	1.3
		30.5-end of interval; alt dec		937266	26.0	29.0	3.0	100	22.3	80.9	10.9	1.2
				937267	29.0	32.0	3.0	100	6.2	56.8	1.7	1.3
32.6	39.7	**qtz-feld-biot gneiss**	GN	937268	32.0	35.0	3.0	100	7.3	26.9	0.5	1.4
		competent; local mod saus alt; diss py to 0.5%; cont local py-lim vns to 5mm		937269	35.0	38.0	3.0	100	14.2	26.1	0.4	1.4
		36.0-37.1m; granodiorite dyke		937270	38.0	41.0	3.0	100	27.2	39.6	0.3	1.1
39.7	68.85	**mg granodiorite**	GD	937271	41.0	44.0	3.0	100	8.4	33	0.3	0.8
		salt and pepper texture; 5% biots to 5mm, locally alt to musc; minor fine diss py; minor 2-4mm wh py-lim vns (locally with minor qtz) at mod-high CA's		937272	44.0	46.0	2.0	100	49.7	283	1	2.1
		44.1-45.9m; v strong saus-clay alt, locally bleached; contains 10 x 2-5mm py-lim vns		937273	46.0	49.0	3.0	100	8	55.2	0.4	1.4
		44.4m; 5mm 70CA py vn with minor mo, cp		937274	49.0	52.0	3.0	100	5.6	76.9	0.3	1.2
		59.6m; 0.7m chl alt gneiss xeno; local py-lim vns		937275	52.0	55.0	3.0	100	17.2	31.5	0.4	1.1
		59-66m; 2-5mm wh-lt gn ser alt haloes around 30CA 1-2mm py vns		937276	55.0	57.5	2.5	100	25.1	64.4	0.6	1.2
		68.6m; 15cm of gy met qtz at lower contact		937277	57.5	60.5	3.0	100	5.5	16	0.4	0.5
				937278	60.5	63.5	3.0	100	2.1	7.4	0.3	0.4
				937279	63.5	66.5	3.0	100	1.6	10.5	0.3	0.3
				937280	Standard CDN-CM-5				45.5	257	7.9	0.4
				937281	66.5	69.5	3.0	100	<0.5	5.7	0.3	0.4
68.85	71.35m	**chl alt feld-biot gneiss**	GN	937282	69.5	72.5	3.0	100	3.2	10.3	1.1	0.9
		dk gn; common feld porphyroblasts; common 1-2mm py vns with 5-10mm wh-gy ser alt haloes										
		71.35m; lower contact is 20cm wh clay halo around 2mm py vns										
71.35	114.45	**foliated monzonite?**	FI	937283	72.5	75.5	3.0	100	2.6	5	1.8	0.6
		local foliated intervals look like gneiss; local low-mod CA 1-2mm py vns with ser alt haloes to 10cm cont from above		937284	75.5	78.5	3.0	100	2.1	15.8	0.4	0.6
		71.35-108m; 1-3 py vns/metre		937285	78.5	81.5	3.0	100	3.2	18.8	2.2	0.8

CC09-06													
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm	
from	to												
		79.5-80.5m; ser alt around 5 py vns		937286	81.5	84.5	3.0	100	47.3	121.7	0.9	1.6	
		85-end of interval; chl alt inc		937287	84.5	87.5	3.0	100	3.3	221.7	4.6	1.4	
		82.5m; 2cm 0-10CA cg wh py vn run for 1.2m along core; ser alt wallrock		937288	87.5	90.5	3.0	100	1.3	63.4	4.7	0.6	
		85.60-93.0m; mod broken zone; strong dk gn chl alt includes frac zone with slickensides (0CA plane, 90 CA rakes); incl low CA chl-hem vns; local ep on frax		937289	90.5	93.5	3.0	103	5.9	23.1	1	0.6	
		96.0-97.2m; local biot "rafts" to 3cm		937290	93.5	96.5	3.0	100	7.9	43.3	1.1	0.5	
		99.2-104.0m; fine lim-py vns with 5mm alt haloes; mod CA; up to 10vns/metre		937291	96.5	99.5	3.0	100	2.5	35.2	0.4	0.9	
		106.5m; 1cm 80CA pk feld-py vn		937292	99.5	102.5	3.0	100	2.1	21.4	1	0.6	
		111.5-end of interval; v broken; strong clay alt; local slickensides as above		937293	102.5	105.5	3.0	100	3.8	28.1	1.6	0.7	
				937294	105.5	108.5	3.0	100	5.4	19.5	2.8	0.7	
				937295	108.5	111.5	3.0	101	3.9	18.1	1.3	1	
				937296	111.5	114.45	2.95	103	1.1	14.6	2.7	0.6	
114.45	123.3	**ser alt feld-biot gneiss**	**GN-S**	937297	114.45	117.45	3.0	94	76.6	102.3	22.4	5	
		lt gy; 1-2mm low CA py vns with ser alt haloes cont		937298	117.45	120.45	3.0	100	15.4	24.2	1.4	1.1	
		114.45-116.5m; soft rubbly clay alt; local bright yellow stain as in holes CC09-03, 05		937299	120.45	123.45	3.0	100	16.7	190.7	2	1.9	
		114.45-118m; py vns as stwk		937300	Standard CDN-CM-5				44.3	267.2	7.4	0.4	
		116.75-118.5m; 2cm 10CA soft clay-py frac zone											
		117.3m; 30CA py frac with lt blue soft anhydrite?											
		118m; 1m of stwk of fine py vns in bn-yellow stained wallrock											
		119-121.5m; local strong yellow stain											
		122.8m; 1.5cm py fill in frac											
		125.5-127.5m; granodiorite dyke; local py ser vns cont; incl 0.3m gn saus alt zone destroys textures											
		126.4m; 1cm 40CA cg py vn											
123.3	134.4	**foliated intrusive**	**FI**	937301	123.45	126.45	3.0	100	1.2	6.5	0.9	0.5	
		qtz diorite?; local feld porphyroblasts; gen unalt but with local ser alt zones; py vns with ser haloes continue; local strong ep in biot rich zones		937302	126.45	129.45	3.0	100	1.3	9.4	<0.1	0.6	
		128-129.2m; strong ser alt		937303	129.45	132.45	3.0	100	1.2	7.8	0.1	0.5	
		130.75m; 8mm 30CA cg wh py vn											
134.4	153.6	**ser, saus alt feld-biot gneiss**	**GN-S**	937304	132.45	135.45	3.0	100	8.2	18.2	1.3	1	
		varies between gy ser alt and gn saus alt'n; locally abund porphyroblasts; ser-py vns common as above		937305	135.45	138.45	3.0	100	5.2	16.8	1	0.8	
		134.4-136.5m; lt gn saus alt around abund (15/metre) 30CA py vns		937306	138.45	141.45	3.0	100	45.6	30	6.2	1.9	
		136.5m; 0.6m with 0.5% diss, frac py		937307	141.45	144.45	3.0	100	92.3	29.6	4.2	3.3	
		137.93m; 1cm 30CA wh cg qtz vn		937308	144.45	147.45	3.0	100	80.8	105	19.1	11.8	
		138.0m; 0.6m y-bn ser alt		937309	147.45	150.45	3.0	100	7.1	17.9	1.4	1.2	
		139-147m; blotchy ser alt'n; abund 2-5mm patches of dk gy ser, abund musc flakes; interval with 0.5% diss py; 5-10 ser-py vns/metre		937310	150.45	152.45	2.0	100	1.8	9.4	1.5	0.7	
		142.8m; 0.5m of 0CA vfg muddy py-ser vns to 7mm		937311	152.45	153.62	1.17	100	5.7	20.8	1.9	1.2	
		145.2m; 8mm 30CA wh calcite-py vn											
		144.6m; 20cm 30CA vfg muddy py-ser vn											
		147.4m; 0.3m of soft gn-y clay alt											
		149.7m; 0.4m of 5-7mm py-ser vns											
		150.3-end of interval; unalt ex for 0.75m of wk lt gy-gn ser-saus alt											
		153.0m; 0.2m of soft gn y clay											
		EOH											

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests							
Hole # CC09-07	NAD 83 Z7	depth	corrected dip						
170.73	UTM E 607511								
Core size; NTW	UTM N 6959200	170.73	-48		Start Date: Sept 12/09				
Drilled by; Kluane Drilling	Azimuth: 150°				Completion: Sept 13/09				
NOTES;	Inclination: -45 °	GRID W	68+00		Logged By: Johnston				
CC09-07	Elevation: 1545m	GRID N	129+46		Date logged; Sept 17-20/09				

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	4.57	casing	OB									
4.57	4.90	rubble	OB									
4.90	19.7	**wk-mod ser-saus alt qtz-feld-biot gneiss**	GN-S	937312	4.9	7.9	3	87	8.2	157.4	3	4
		lt gn; ser-saus alt granodiorite dykes to 2m as 30% of interval; local unalt intervals of gneiss, dykes; local py 2-8mm py vns with ser alt haloes up to 10vns/metre		937313	7.9	10.9	3	101	4.8	77.9	1.7	2.7
		4.9-5.8m; unalt dyke		937314	10.9	13.9	3	100	8.6	141.6	0.8	3.1
		5.8-6.56m; alt gneiss with 10 py vns		937315	13.9	16.9	3	100	3.3	44.6	0.6	1.7
		17-19.7m; py vns dec to local		937316	16.9	19.9	3	100	2.5	44.7	0.5	2.4
19.7	41.8	**qtz-feld-biot gneiss**	GN	937317	19.9	22.9	3	100	3.8	25.5	0.4	1.1
		gy, unalt; local wk, pk porphyroblasts; granodiorite dykes continue; local ser-py vns as above		937318	22.9	25.9	3	100	7.7	27.5	0.5	2
		24.6m; 2cm 30CA cg wh py vn		937319	25.9	28.9	3	98	3	11.1	0.7	0.7
		26.2-30.9m; strong y clay, calcite on frax		937320	Standard CDN-CM-5				48.6	198.1	7.1	0.3
		27.8-29.0m; v broken		937321	28.9	30.9	2	102	1.2	5.5	0.3	0.6
		30.1-30.7m; v broken		937322	30.9	33.9	3	100	2.1	90.5	0.3	0.6
				937323	33.9	36.9	3	100	14	53.3	0.5	1.6
				937324	36.9	39.9	3.0	100	2.1	14.1	0.2	0.5
				937325	39.9	41.8	1.9	100	1.4	26.6	0.5	0.3
41.8	50.0	**wk-mod ser-saus alt qtz-feld-biot gneiss**	GN-S	937326	41.8	44.8	3.0	87	3.8	17	2	0.6
		up to 0.5% diss wh py in stronger alt interval; py vns with ser alt haloes cont; no dykes		937327	44.8	46.8	2.0	100	17.5	31.9	1.2	1.6
		48.5-50m; wk alt		937328	46.8	48.5	1.7	100	44.2	35.9	1.3	1.5
		54m; py vns with wh carb, lim		937329	48.5	51.5	3.0	100	1.8	4.1	0.2	0.3
50	61.6	**saus alt granodiorite**	GD-S	937330	51.5	54.5	3.0	100	2.6	22.9	0.4	0.5
		local intervals of gn saus alt; local saus alt gneiss xenos?; py-ser vns cont as above		937331	54.5	57.5	3.0	100	4.7	20.2	0.2	0.9
				937332	57.5	60.5	3.0	100	21.2	36.9	1	0.8
61.6	92.37	**feld-qtz-biot gneiss**	GN	937333	60.5	63.5	3.0	100	4.4	38.8	0.3	0.7
		local bn carb-ser alt intervals; 0CA py vns with ser alt haloes cont at 1-3 vns/metre to 66m, dec to		937334	63.5	66.5	3.0	100	1.4	4.9	0.2	0.5
		73-75.5m; 2 x dk gn chl alt biot gneiss intervals, py to 1%, local met qtz blowouts		937335	66.5	69.5	3.0	100	3.7	13	0.6	0.6
		78.0-79.3m; mod soft lt gy ser-clay alt; local bright gn anhydrite?; local met qtz; inc py stringers at various CA's		937336	69.5	72.5	3.0	100	1	5	0.1	0.2
		79.3-87.6m; unalt gneiss		937337	72.5	75.5	3.0	100	1.5	6.3	0.2	0.4
		87.9-end of interval; bn-red Fe-carb flooding; inc feox on frax; inc py vns to 3/m		937338	75.5	78	2.5	100	1.3	5.8	0.4	0.6
		90.1m; 3mm py-qtz vn		937339	78	79.3	1.3	100	213	81.9	8.1	6.9
				937340	Standard CDN-CM-5				47.8	268.7	6.2	0.3
				937341	79.3	82.3	3.0	100	1.8	3.9	1	0.4
				937342	82.3	85.3	3.0	100	4.3	17.9	0.4	0.6
				937343	85.3	88.3	3.0	100	3.3	10.8	0.8	0.4

CC09-07													
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm	
from	to												
				937344	88.3	91.3	3.0	100	13.2	28.8	1	0.7	
				937345	91.3	92.37	1.07	100	5.4	6.1	0.9	0.3	
92.37	94.84	**v broken feld-qtz-biot gneiss**	**GN**	937346	92.37	94.84	2.47	101	44.1	52.4	3.9	3.1	
		v broken, strong or lim on frax; local bright yellow stain (as in holes CC09-03, 05, 06); minor gy fg chalcedonic qtz vns; diss wh py to 0.5%											
94.84	99.5	**feld-qtz-biot gneiss**	**GN**	937347	94.84	97.84	3.0	103	7.1	31.5	3.4	0.5	
		incl broken intervals as above; common 1-2mm py-ser vns at various CA's as above		937348	97.84	100.84	3.0	100	9.5	13.3	1	0.5	
				937349	100.84	103.84	3.0	100	1.9	6.2	0.8	0.3	
99.5	133.2	**foliated qtz diorite?**	**FI**	937350	103.84	106.84	3.0	100	3	4.6	1.1	0.4	
		unalt; Feox-calcite common on frax		937351	106.84	109.84	3.0	100	2.9	11	0.8	0.6	
		99.5-102.5m; local py-ser vns as above		937352	109.84	112.84	3.0	100	2.1	18.8	0.3	0.7	
		104.24m; 0.4m soft broken zone, strong Feox		937353	112.84	115.84	3.0	100	11.6	10.1	0.5	0.6	
		109.14m; 0.7m soft wh clay rubbly interval		937354	115.84	118.84	3.0	100	5.1	24.4	0.2	0.6	
		119.5m; 0.75m wide lt gn ser alt around 0CA py vn		937355	118.84	121.84	3.0	100	14.5	18.4	0.5	0.8	
		115-133.5m; 1cm ser alt haloes around 1mm py vns; 1-2 vns/metre		937356	121.84	124.84	3.0	100	1.3	13	0.2	0.8	
				937357	124.84	127.84	3.0	100	4.4	14.3	0.2	1.7	
				937358	127.84	130.84	3.0	100	4.9	10.6	0.2	0.5	
				937359	130.84	133.2	2.36	100	3.5	12.5	0.2	0.6	
				937360	Standard CDN-BL-4				6.8	<0.5	0.4	0.1	
133.2	136.05	**Fe-carb alt feld-qtz-biot gneiss**	**GN**	937361	133.2	136.05	2.85	103	11.3	15.6	0.6	0.7	
		soft bn alt; locally v broken; strong or lim, wh calcite on frax; low CA py vns											
136.05	141.45	**foliated qtz diorite?**	**FI**	937362	136.05	139.05	3.0	100	7.6	90.1	2.5	0.7	
		unalt, common rd-or lim-calcite-Feox vns to 2mm		937363	139.05	141.45	2.4	100	9	48.2	0.9	0.4	
141.45	170.73	**ser alt feld-qtz-biot gneiss**	**GN-S**	937364	141.45	144.45	3.0	100	56.6	106.1	4.6	1.3	
		lt gy with gn tinge; 40 % of interval unalt; common feld porphyroblasts; common 1-2mm gy fg qtz vns with local py up to 10 vns/metre		937365	144.45	147.45	3.0	100	45.7	71.2	2.3	1.6	
				937366	147.45	150.45	3.0	100	1.7	66.4	0.3	0.3	
		EOH		937367	150.45	153.45	3.0	100	22.8	36.7	0.6	0.6	
				937368	153.45	156.45	3.0	100	16.6	60	0.3	0.9	
				937369	156.45	159.45	3.0	100	3.5	25.1	0.6	0.6	
				937370	159.45	162.45	3.0	100	21.4	31.5	1.7	1.5	
				937371	162.45	165.45	3.0	100	8.1	11.6	0.7	0.7	
				937372	165.45	168.45	3.0	100	2.5	13.5	0.1	0.3	
				937373	168.45	170.73	2.28	100	15.6	45.5	0.5	0.6	

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests						
Hole # CC09-08	NAD 83 Z7 UTM E 607685	depth	corrected dip					
depth; 137.77m	UTM N 6959998	no	test		Start Date: Sept 14/09			
Core size; NTW	Azimuth: 000°				Completion: Sept 16/09			
Drilled by; Kluane Drilling	Inclination: -68 °	GRID W	65+89		Logged By: Johnston			
NOTES;	Elevation: 1438m	GRID N	137+39		Date logged; Sept 20-21/09			

CC09-08

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	3.05	casing	OB									
3.05	29.90	**mg granodiorite**	GD	937374	3.05	6.05	3.0	96	12.6	10.5	3.3	1.1
		10% 1-3mm bk biots; local gn saus alt; gn felds, biots alt to fine bn biot in stronger alt sections; tr diss py; surface weath to 4m		937375	6.05	9.05	3.0	97	7.2	129.4	5.4	1.9
		8.3m; 0.4m of soft clay alt		937376	9.05	12.05	3.0	96	13.4	69.3	3.7	3.4
		9.8-18m; strong or lim on frax; inc saus alt		937377	12.05	15.05	3.0	100	4.2	42.1	2.4	1.7
		16.8m; 5cm gn saus alt halo around 1mm 45CA py vns		937378	15.05	18.05	3.0	100	221.7	30.3	3.2	2.1
		18-end of interval; local wk saus alt		937379	18.05	21.05	3.0	100	4	4.8	0.2	0.1
		26.5-end of interval; local (1-2/metre) 5-10mm low CA lt gn carb vns		937380	Standard CDN-CM-5				42.4	201.2	6.3	0.3
				937381	21.05	24.05	3.0	100	33.5	46	0.7	13.5
				937382	24.05	27.05	3.0	100	4	10.4	0.2	<0.1
29.9	51.0	**wk pervasive saus alt mg granodiorite**	GD	937383	27.05	30.05	3.0	100	7.4	7.8	0.4	0.8
		as above, but with gn saus alt thoughout; local py vns; local gy qtz vns, with local vfg muddy py		937384	30.05	33.05	3.0	100	4.6	6.7	0.3	0.8
		36-44m; 5-10mm gn carb vns at various CA's; 2-4vns/metre		937385	33.05	36.05	3.0	100	8.6	57.5	0.5	7.1
				937386	36.05	39.05	3.0	100	86.5	19.4	0.4	0.6
				937387	39.05	42.05	3.0	100	19.8	9.8	1.1	0.5
				937388	42.05	45.05	3.0	100	174.4	16.7	7	1.2
				937389	45.05	48.05	3.0	100	13.3	1.7	2.2	0.1
				937390	48.05	51.05	3.0	100	26.9	8.2	4.1	0.2
51.0	80.0	**mg granodiorite**	GD	937391	51.05	54.05	3.0	100	39.7	6.9	0.8	0.3
		unalt; local sp vns		937392	54.05	57.05	3.0	100	45.8	7.1	0.4	0.3
		53.65m; 1cm 90CA mgt-sp vn with 2cm gn saus alt halo		937393	57.05	60.05	3.0	100	5.8	<0.5	0.6	<0.1
		55.9m; 5mm 90CA sp-py vn		937394	60.05	63.05	3.0	100	25	13.2	0.5	0.6
		61.0m; 2 x 2mm py-sp vns 20cm apart		937395	63.05	64.2	1.15	100	2967.6	54.8	8	4
		63.8m; 5cm red-bn sp vn		937396	64.2	67.2	3.0	100	5.4	0.9	0.4	0.1
		74.6m; 8cm gn saus alt around 2 x 1mm 90CA py vns		937397	67.2	70.2	3.0	100	4.3	0.7	0.5	<0.1
		77.8-79.3m; gn saus alt halo around 10cm 20CA zone with calcite, wh eu py and sgl 1cm cp bleb,		937398	70.2	73.2	3.0	100	2.4	<0.5	0.2	<0.1
				937399	73.2	76.2	3.0	100	8.9	7.9	0.7	0.9
				937400	Standard CDN-CM-5				41.3	332	5.5	0.3
				937401	76.2	77.8	1.6	100	5	7.5	2.1	0.1
				937402	77.8	79.3	1.5	100	833.6	3458.1	10.4	19.4
80.0	110.0	**wk pervasive saus alt mg granodiorite**	GD	937403	79.3	82.3	3.0	100	3.3	5.1	0.8	0.2
		minor diss py, local py vns		937404	82.3	85.3	3.0	100	2.6	6.9	0.2	<0.1
		88.85m; 1cm 40CA py-ser vn in 10cm saus alt halo		937405	85.3	88.3	3.0	100	3.5	5.1	0.2	0.2
		91.12m; 5cm 90CA vfg muddy py-carb vn in 2cm gn saus alt halo		937406	88.3	91.3	3.0	100	5.4	2.9	0.3	0.4
		91.8-94.35m; broken core; minor diss wh eu py; minor wh calcite vns		937407	91.3	94.3	3.0	100	15.4	18.7	0.6	0.8
		95.2m; 0.4m of clay-saus alt around series of 2-3mm 20CA py vns		937408	94.3	97.3	3.0	100	14.2	25.6	0.7	0.8
		100.88m; 1cm 30CA vfg muddy py vn in 20cm clay-saus alt halo		937409	97.3	100.3	3.0	100	27.5	22.6	1.5	0.8

CC09-08													
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm	
from	to												
		103.5-105.3m; inc mg yellow py vns; 5 vns through interval at 20,90CA		937410	100.3	103.3	3.0	100	53.4	26.6	1.4	1	
				937411	103.3	106.3	3.0	100	107.3	6.6	1.4	1.2	
				937412	106.3	109.3	3.0	100	1.8	<0.5	0.2	<0.1	
110.0	124.5	**mod saus alt granodiorite**	**GD-S**	937413	109.3	111.5	2.2	100	773.4	46.1	1.5	0.9	
		softer, more broken that above; minor diss py		937414	111.5	113.2	1.7	100	20.3	129.9	3.4	7.5	
		111.5-113.2m; locally strong saus-clay alt zones around vfg muddy py and mg py vns		937415	113.2	116.0	2.8	100	40.6	74.4	2.6	4.2	
		116.9-118.5m; soft lt gn clay alt with both vfg muddy py and mg py vns and low CA qtz-carb +/-py vns		937416	116.0	118.5	2.5	100	200	108.6	4.4	20.9	
		119.6m; 1cm 90CA carb vn with fg, mg py, surrounded by qtz-carb vns to 1cm with clay-saus alt halo		937417	118.5	122.0	3.5	100	23	32.5	2.4	3.9	
		120.45m; 2 x 2mm 30CA vfg muddy py vns in 20cm strong clay-saus alt halo		937418	122.0	124.5	2.5	100	157.3	94.4	5.9	7.5	
		123.90m; 1cm 30CA fg-mg py vn in strong clay alt wallrock											
		124.5m; 2mm 10CA fg-mg py vn in strong clay alt wallrock											
124.5	133.84	**mod soft clay alt granodiorite**	**GD-C**	937419	124.5	127.5	3.0	100	65.8	22	3.7	6.4	
		wh-gy soft clay alt granodiorite, local zones of lt gn saus alt; local wh mg py on frax		937420	Standard CDN-CM-5				42.9	234.6	4.9	0.3	
		130.1-133.84m; soft mushy gn, wh clay around 0CA structure with wh calcite, vfg py vns; some lost core		937421	127.5	130.1	2.6	100	26.9	27.6	2.7	1.9	
				937422	130.1	132.62	2.52	67	55.1	22.7	4.6	2	
				937423	132.62	133.84	1.22	77	655.4	10.5	5.6	0.4	
133.84	137.77	**mg granodiorite**	**GD**	937424	133.84	135.84	2.0	100	343	27.3	6.7	2	
		wk-mod saus alt dec to none at 135m		937425	135.84	137.77	1.93	100	3.5	4.7	0.3	0.1	
		EOH											

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests						
Hole # CC09-09	NAD 83 Z7	depth	corrected dip					
depth; 137.77m	UTM E 607668							
	UTM N 6960222	121.92m	-60		Start Date: Sept 16/09			
Core size; NTW	Azimuth: 180°				Completion: Sept 18/09			
Drilled by; Kluane Drilling	Inclination: -58 °	GRID W	65+98		Logged By: Johnston			
NOTES;	Elevation: 1442m	GRID N	139+65		Date logged; Sept 21-22/09			

CC09-09

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	3.04	casing	OB									
3.04	19.5	**leucocratic granodiorite**	GD	937426	3.04	6.04	3.0	100	3.2	0.7	0.1	<0.1
		v fresh, boring; 10-20% biots, sharp boundaries on local intervals with inc mafics		937427	6.04	9.04	3.0	100	1	<0.5	<0.1	<0.1
		16.6-19.5m; or lim on frax; locally v broken		937428	9.04	12.04	3.0	100	1.8	0.7	0.1	<0.1
				937429	12.04	15.04	3.0	100	1.3	<0.5	<0.1	<0.1
				937430	15.04	18.04	3.0	100	4	<0.5	0.5	<0.1
				937431	18.04	20.6	2.56	100	3.8	<0.5	0.3	<0.1
19.5	44.4	**mod-strong saus alt granodiorite**	GD-S	937432	20.6	22.9	2.3	100	2005.6	92.3	1.9	1.1
		lt gn mod pervasive saus alt; locally strong; or lim on frax continues		937433	22.9	25.9	3.0	100	7.3	3.2	0.4	0.1
		20.6-22.9m; strong gn saus alt; locally destroy textures, but still hard, competent core; local low CA soft gn carb vns; minor py vns		937434	25.9	28.9	3.0	100	26.8	12.7	0.8	0.2
		22.3m; 1cm 30CA fg py vn with aspy		937435	28.9	31.9	3.0	100	2.7	<0.5	0.2	<0.1
		26.8-29.0m; strong saus alt w/ local 2-4mm dk gy ser alt frax		937436	31.9	34.9	3.0	100	1.1	<0.5	0.2	<0.1
		37-42m; mod broken zone with lim-calcite frax, local vfg 0-30CA py stringers; local bk 0CA bk chl frax		937437	34.9	37.9	3.0	100	11.9	0.6	0.2	<0.1
				937438	37.9	40.9	3.0	100	70.1	3	0.4	0.2
				937439	40.9	43.9	3.0	100	71.7	9.4	0.6	0.3
				937440	Standard CDN-CM-5				46.6	312.5	6.7	0.4
44.4	57.5	**leucocratic granodiorite**	GD	937441	47.0	50.0	3.0	100	3.6	<0.5	<0.1	<0.1
		as above; v fresh, v boring		937442	53.0	56.0	3.0	100	123.5	8.5	0.2	0.2
		53-end of interval; local py on frax		937443	56.0	59.0	3.0	100	1565.2	76.7	0.5	0.7
				937444	59.0	62.0	3.0	100	302	26.9	0.2	1
57.5	112.0	**wk-mod saus alt granodiorite**	GD-S	937445	62.0	65.0	3.0	100	3.3	1.1	0.1	<0.1
		pervasive gn alt, locally strong; local vns with aspy		937446	65.0	68.0	3.0	100	645.3	30.2	0.3	1.1
		57.85m; minor aspy on frax with py		937447	68.0	71.0	3.0	100	1354.9	61.8	0.5	1.2
		66.5-71.5m; incl 5 x 30CA py vns to 3mm with wh clay and minor aspy; py vns cont after but without aspy		937448	71.0	74.0	3.0	100	197.6	6.1	0.2	0.3
		85.3-87.25m; strong saus alt; bk biots alt to fg bn biot; local py vns; local calcite vns to 7mm		937449	74.0	77.0	3.0	100	25	1.4	0.2	1
		85.6m; 4mm 30CA py-aspy vn		937450	77.0	80.0	3.0	100	3	1.2	0.4	0.2
		90-99.15m; mod soft strong gn saus alt		937451	80.0	82.5	2.5	100	2.5	2	0.4	0.3
		93.4-96.5m; soft rubbly clay with local diss eu py		937452	82.5	85.3	2.8	100	0.8	0.7	0.3	0.4
		96.5-98.05m; lt gn saus alt 45CA shear?; strong fabric, sharp contacts; 0.5% diss py		937453	85.3	87.25	1.95	100	568.4	57.8	2.3	2.2
		99.45-end of interval; local dk gn-gy ser alt frax; minor py		937454	87.25	90.25	3.0	100	8.9	3.4	1.6	0.7
		104.5-106.0m; strong y-gn saus alt zone around numerous 1-2mm 30CA py-carb veinlets		937455	90.25	93.25	3.0	100	242.4	12.2	6	0.7
		110.55m; 8mm 30CA wh carb vn with po, hem		937456	93.25	96.25	3.0	100	192	5.5	6.9	0.5
				937457	96.25	99.25	3.0	100	1397.7	34.4	7.4	1.2
				937458	99.25	102.25	3.0	100	4.5	0.6	1.3	<0.1
				937459	102.25	105.25	3.0	100	7.3	1.4	1.5	0.2
				937460	Standard CDN-GS-P3				177.7	217.2	14.1	<0.1

CC09-09												
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
from	to											
				937461	105.25	108.25	3.0	100	53.7	2.8	1.1	<0.1
				937462	108.25	111.25	3.0	100	2.3	0.6	0.2	0.1
112.0	128.04	**unalt granodiorite**	**GD**	937463	111.25	114.25	3.0	100	1.2	1.3	0.1	0.1
		115.5m; 5, 10mm 60CA fg gy py vns with aspy in 10cm strong ser-clay alt wallrock		937464	114.25	115.35	1.1	100	1.5	<0.5	0.2	<0.1
		126.1m; 1mm 60CA po vn in 1cm saus alt halo		937465	115.35	115.75	0.4	100	5038	149	8.3	5.7
		127.0m; 2mm 60CA py vn in 3cm saus alt halo		937466	115.75	118.75	3.0	100	36.1	3.1	0.1	<0.1
				937467	118.75	121.75	3.0	100	3.9	1.7	0.1	0.1
		EOH		937468	121.75	124.75	3.0	100	5.5	<0.5	<0.1	<0.1
				937469	124.75	126.0	1.25	100	4	<0.5	0.4	0.3
				937470	126.0	128.04	2.04	100	28.9	2	0.4	0.4

PROPERTY: CANADIAN CREEK	Loc Method; GPS	dip tests						
Hole # CC09-10	NAD 83 Z7	depth	corrected dip					
depth; 121.95m	UTM E 607875							
	UTM N 6960125	121.92m	-60		Start Date: Sept 18/09			
Core size; NTW	Azimuth: 000°				Completion: Sept 19/09			
Drilled by; Kluane Drilling	Inclination: -59 °	GRID W	64+00		Logged By: Johnston			
NOTES;	Elevation: 1374m	GRID N	138+46		Date logged; Sept 22-23/09			

CC09-10

depth (m) from	depth (m) to	description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
0.00	3.57	casing	OB									
3.57	20.15	**cg granodiorite**	GD	937471	3.57	6.57	3.0	100	0.5	<0.5	0.4	0.3
		10-30% fresh bk biots to 2mm; local 90CA 1mm y py vns (with tr aspy sp, mgt) with 1-2cm gn saus alt haloes (1-2vns/box)		937472	6.57	9.57	3.0	100	443.3	28.4	0.6	0.9
		4,5m; mgt-chl on frac		937473	9.57	12.57	3.0	100	18.7	1.6	0.5	0.3
		8.0m; 2mm 90CA py-aspy vn		937474	12.57	15.57	3.0	100	<0.5	<0.5	0.5	0.2
		8.4m; red sp on 90CA frac		937475	15.57	18.57	3.0	100	<0.5	<0.5	0.6	0.3
				937476	18.57	20.85	2.28	93	46.7	24.2	6.4	4.6
20.15	30.3	**strong saus alt granodiorite**	GD-S	937477	20.85	23.85	3.0	97	172.4	158.2	20.9	5.2
		finer grained than above; lt bn patches of bn biot alt'n?; strong pervasive gn saus alt throughout; local low CA 1-2mm yellow py stringers		937478	23.85	26.85	3.0	97	13.9	38.9	15.2	0.9
		20.85-24.24m; v broken, rubbly; 10cm of soft clay at top		937479	26.85	29.85	3.0	100	123.8	102.2	39.6	5.9
		22.9m; 15cm of soft clay		937480	Standard CDN-GS-P3				173.5	241.5	15	0.2
		23.6m; 10cm of soft clay										
		24.2-25.8m; dk gn chl-saus alt										
		25.8-end of interval; lt gn strong saus alt'n with local 1-5mm low CA py stringers, with both fg muddy py and mg yellow py										
30.3	81.2	**mod saus alt granodiorite**	GD-S	937481	29.85	32.85	3.0	100	1.4	1.1	0.8	0.3
		as above, with weaker alt; strong gn chl on frax; tr diss, frac py		937482	32.85	35.85	3.0	100	0.9	<0.5	0.7	0.2
		43.1m; 1-2mm 30CA po vn		937483	35.85	38.85	3.0	100	1.2	<0.5	0.7	0.3
		50-56m; mod broken zone; local 1-2mm high CA gy qtz vns with local py, minor alt haloes; chl, calcite on frax; local 90CA slickensides		937484	38.85	41.85	3.0	100	<0.5	<0.5	0.5	0.3
		51.0m; pp qtz vn with rd Feox		937485	41.85	44.85	3.0	100	1.4	0.5	1	0.3
		65.4m; 3mm qtz-carb vn with po; 2cm bleached halo		937486	44.85	47.85	3.0	100	1.7	3.2	1	0.3
		68.45m; 10cm pk ksp? flooded zone		937487	47.85	50.85	3.0	100	<0.5	<0.5	0.7	0.2
		69.6-71.15m; sl beached buff coloured zone with 8 x 1-3mm mod-high CA py vns; both vfg muddy py and mg yellow py		937488	50.85	53.85	3.0	100	5.3	<0.5	1.7	0.2
		72.6m; 25cm bleached saus alt halo around 2mm 60CA vfg muddy py vn		937489	53.85	56.85	3.0	100	20.7	<0.5	1.6	0.2
		73.0m; 10cm bleached saus alt halo around 2mm 60CA vfg muddy py vn		937490	56.85	59.85	3.0	100	<0.5	<0.5	0.6	0.2
		79.15m; 20cm bleached saus alt halo around 2 x 2mm 45CA vfg muddy py vn		937491	59.85	62.85	3.0	100	<0.5	<0.5	0.7	0.2
				937492	62.85	65.85	3.0	100	1.7	4	0.7	0.4
				937493	65.85	68.85	3.0	100	<0.5	<0.5	0.5	0.2
				937494	68.85	71.15	2.3	100	3.3	65.5	1.2	1.4
				937495	71.15	74.15	3.0	100	10.3	16.4	0.8	1
				937496	74.15	77.15	3.0	100	1.5	4.8	0.5	0.3
				937497	77.15	80.15	3.0	100	4	10.1	0.7	0.3
81.2	90.5	**strong musc-ser alt granodiorite**	GD-S	937498	80.15	82.8	2.65	100	547.8	51	38	15.3
		gy ser alt, musc on frax; local gn saus; local bleaching around 10CA zones of wh qtz vns with		937499	82.8	85.8	3.0	96	3267.2	1098.7	222.1	60.6
		81.2-82.0m; strong lt gn saus alt around 1% diss py masses and py vnlets to 1mm		937500	Standard CDN-BL-4				6.2	<0.5	0.4	0.1

CC09-10												
depth (m)		description	litho code	sample #	from (m)	to (m)	m	rec %	As ppm	Au ppb	Sb ppm	Bi ppm
from	to											
		81.50m; 0.4m alt halo around 1-3mm 45CA fg muddy py vns with local cp		933251	85.8	88.0	2.2	100	276.3	197.1	55.8	5.1
		82.0-82.8m; wh bleached zone with diss py		933252	88.0	90.05	2.05	100	628.8	595.6	52.8	8.3
		82.9-83.7m; soft dk gy clay with 50% eu wh py										
		83.7-90.5m; gn saus alt with 2-5% diss py with local py stringers										
		83.85m; 15nm 20CA mass brassy-yellow py vn										
		84.2m; 10mm 10CA fg muddy py vn with minor aspy										
		85.3m; 2cm fg gy 20CA qtz vn; fg py at margins										
90.5	99.5	**wk-mod saus alt mg-cg granodiorite**	**GD-S**	933253	90.05	93.05	3.0	100	96.4	32.4	10.7	0.5
		local high CA narrow py-chl vns with local po		933254	93.05	96.05	3.0	100	31.5	16	3.1	0.4
		94.9m; 1mm 80CA fg muddy py vn with minor cp		933255	96.05	99.05	3.0	100	45.3	24.2	2.4	0.3
		98.5m; 0CA frax with strong gn chl, wh calcite										
99.5	108.7	**strong saus alt granodiorite**	**GD-S**	933256	99.05	102.05	3.0	100	568	51.3	933.6	8.9
		common 0CA frax; local fine mod-high CA vfg muddy py vns; diss py to 0.5%		933257	102.05	105.05	3.0	100	567.8	172.6	296.1	2
		103.25m; 2mm 60CA py vn with minor aspy		933258	105.05	107.0	1.95	100	185.3	50.4	258.7	2.6
		104.0-105.2m; locally abund vfg bk py masses to 5mm		933259	107.0	108.7	1.7	100	2103.7	171.6	62.7	11.3
108.7	121.95	**wk saus alt mg granodiorite**	**GD**	933260	108.7	111.7	3.0	100	6.7	3.3	2.6	0.3
		wk pervasive saus alt throughout; local high CA py vns, frax to 2mm with 1-5cm saus alt haloes at		933261	111.7	114.7	3.0	100	1456.6	49.7	1.1	0.2
				933262	114.7	117.7	3.0	100	113	53.9	0.9	0.9
		EOH		933263	117.7	120.0	2.3	100	3.6	1.8	0.4	0.1
				933264	120.0	121.95	1.95	100	5	5.7	0.4	0.3

APPENDIX 3

2009 Rock Sample Descriptions

2009 Canadian Creek Project - Rock Sample Descriptions

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb
79301	RDC01	604179	6957889	14-Jul-09	met									py?	grab	float	Gneiss w lg 5mm feldspar dis py? large talus boulders	West side of Can Ck Property	near S end of line 10200 on 09 Grid	2.5
79302	RDC02	604179	6957889	14-Jul-09	int		sil								grab	float	fine grained qtz rich granodiorite with 2 mm qtz band large talus boulders	West side of Can Ck Property	near S end of line 10200 on 09 Grid	2.5
79303	RDC03	604146	6957925	14-Jul-09	met		sil								grab	float	qtz rich Gneiss W lg feldspar ~1cm in lg boulders	West side of Can Ck Property	near S end of line 10200 on cat trail 09 Grid	5
79304	RDC04	604059	6958313	14-Jul-09	met		sil								grab	float	atz rich gneiss w feldspar biotite in larger angular boulders	West side of Can Ck Property	near mid line 10200 09 Grid	2.5
79305	RDC05	604148	6958468	14-Jul-09	met		sil							py	grab	float	fine grained weakly foliated quartz biotite gneiss w disseminated py in angular boulders	West side of Can Ck Property	near mid line 10200 09 Grid	2.5
79306	RDC06	604157	6958498	14-Jul-09	met		sil			chl?					grab	float	fine grnd grey/green sil/chloritic?gneiss (tuff) Angular Talus boulders	West side of Can Ck Property	near mid line 10200 09 Grid	2.5
79307	RDC07	604166	6958534	14-Jul-09	met									py	grab	float	fine grnd foliated gneiss w py 1 cm feldspar Angular Talus boulders	West side of Can Ck Property	e of mid line 10200 09 Grid	2.5
79308	RDC08	604173	6958544	14-Jul-09	met		sil							py	grab	float	Gneissic w lg 1 cm wide qtz lens dis. Py in qtz Angular Talus boulders	West side of Can Ck Property	e of mid line 10200 09 Grid	2.5
79309	RDC09	604259	6957441	18-Jul-09	int		sil								grab	float	Course grained Granodiorite with biot qtz dark feldspar crystal 1 cmx.5cm in lg angular boulders	West side of Can Ck Property	between 10200/11425 & 10000/11425 09 Grid 09 Grid+U39	1.8
79310	RDC10	604622	6957474	18-Jul-09	int		sil								grab	float	Course grained Granodiorite with biot 2 mm qtz feldspar in lg talus boulders below outcrop	West side of Can Ck Property	9800/11425 09 Grid 09 Grid	0.25
79311	RDC11	604579	6957750	18-Jul-09	int		sil								grab	float	Course grained Granodiorite with lg grey black altered? Feldspar~4 mm biot qtz in lg talus boulders	West side of Can Ck Property		0.25
79312	RDC12	604579	6957750	18-Jul-09	met		sil							py	grab	float	fine grnd dark gneiss w weakly disem py 2-12 mm qtz banding with 8 mm diag qtz band in large mixed Angular Talus boulders	West side of Can Ck Property		1.4
79313	RDC13	604579	6957750	18-Jul-09	int		sil							py	grab	float	Course grained qtz, biotite Granodiorite with weakly dis. Py in lg mixed talus boulders	West side of Can Ck Property		2.3
79314	RDC14	604534	6957801	18-Jul-09	met		sil							py	grab	float	Grey white Quartzite? With weakly dis py in mixed large boulders	West side of Can Ck Property		4.1
79315	RDC15	604503	6957916	18-Jul-09	int		sil							py	grab	float	Fine grnd sil.qtz biot granodiorite w fw pyr specs mixed large angular boulders	West side of Can Ck Property		1.3

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb
79316	RDC16	604503	6957916	18-Jul-09	met		sil								grab	float	Fine grnd qtz biot in large angular boulders	West side of Can Ck Property		2.4
79317	RDC17	604503	6957916	18-Jul-09	met	x	sil							py?	grab	float	Qtz rich orange wx with minor biot fw py? Alt? Tan Feldspar lg ang boulders	West side of Can Ck Property		18.4
79318	RDC18	604476	6957995	18-Jul-09	met		sil							py	grab	float	7 cm qtz vein on large boulder in mixed boulders	West side of Can Ck Property		0.25
79319	RDC19	604476	6957995	18-Jul-09	met		sil								grab	float	Fine grnd gneiss with biot lg to 2 cm feldspar and qtz vein in lg boulder	West side of Can Ck Property		0.25
79320	RDC20	604343	695833	18-Jul-09	met		sil							py	grab	float	Fine grnd sil gneiss with biot skly dis fine grnd py 1 cm qtz band lg angular boulders	West side of Can Ck Property	L10000/12300N 09 Grid	0.25
79321	RDC21	604339	6958575	18-Jul-09	met		sil							py	grab	s/c?	Fine grnd gneiss with 50% biot foliations 1 cm feldspar and qtz fw specs py in lg ang boulders	West side of Can Ck Property	L10000/12525N 09 Grid	0.25
79322	RDC22	604330	6958670	18-Jul-09	met		sil								grab	s/c?	Fine grnd sil. gneiss with larger 1+cm white qtz bands embedded biot some folding to in lg angular boulders	West side of Can Ck Property	L10000/12635N 09 Grid	0.25
79323	RDC23	604335	6958618	18-Jul-09	met		sil								grab	s/c?	Mostly fine grnd biot rich gneiss with Qtz biotite embedded some iron staining in lg angular boulders	West side of Can Ck Property	L10000/12585N 09 Grid	86.8
79324	RDC24	604335	6958618	18-Jul-09	met		sil								grab	s/c	Fine grnd grey gneiss with some qtz to 1cm biot fw py? in lg angular boulders sub o/c	West side of Can Ck Property		0.25
79325	RDC25	604238	6958547	18-Jul-09	met		sil								grab	s/c	Fine grnd sil gneiss with some 1mm biot qtz bandng to 2.5 cm some folding in lg angular boulders near peak	West side of Can Ck Property		2.7
79326	RDC26	604254	6958541	18-Jul-09	met		sil								grab	s/c	Fine grnd sil gneiss with mass biot 1 cm band white/orange qtz in lg angular boulders near peak	West side of Can Ck Property		1.6
79327	RDC27	604254	6958541	18-Jul-09	vein		sil								grab	s/c	mass opaque qtz.	West side of Can Ck Property		0.9
79328	RDC28	604254	6958541	18-Jul-09	met		sil							py	grab	s/c	Sil gneiss with massv ~3cm qtz minor py lg 1cm biot lg angular boulders	West side of Can Ck Property	near L10000/12435 09 Grid	0.25
79329	RDC29	604431	6958455	18-Jul-09	met		sil							py	grab	float	Fine grnd wkly foliated gneiss? with 1cm qtz band minr py biot qtz in lg angular boulders	West side of Can Ck Property	~75mE L10000/12400N 09 Grid	0.9

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb
79330	RDC30	604467	6958464	18-Jul-09	int		sil								grab	s/c	lt. Orng brwn finegrnd sil.meta sandstn? Or alt. Granodiort? Mstly qtz minor biot in lg angular mixed gneiss mss? boulders near ridge top	West side of Can Ck Property	100m E L10000/12400 09 Grid	0.25
79331	RDC31	604506	6958462	18-Jul-09	met		sil								grab	s/c	Fine grnd sil gneiss with qtz biot 5 mm qtz band on surface lg angular boulders	West side of Can Ck Property		1.6
79332	RDC32	604530	6958460	18-Jul-09	met		sil							py	grab	s/c	silicious orange wx gneiss with +50% biot qtz few py some qtz 2cmx3cm in lg angular boulders	West side of Can Ck Property		2.2
79333	RDC33	604550	6958470	18-Jul-09	met		sil								grab	s/c	lite orange wx gneiss with mstly biot 2cm band lg angular boulders	West side of Can Ck Property		0.25
79334	RDC34	600637	6960877	25-Jul-09	met	x	sil							py	grab	float	biotite(+75%) rich sil gneiss with qtz ckasts limonite minor py	Regional	7.5 km NW of [property	0.25
79335	RDC35	601099	6960718	25-Jul-09	met	x	sil							py?	grab	float	limonite stnd sil quartzite?/gneiss with mstly qtz some bio fw py?	Regional	7.5 km NW of [property	1.3
79336	RDC36	601584	6960865	25-Jul-09	met	x	sil								grab	float	alt? Limonite stnd sil. Quartzite	Regional	7.5 km NW of [property	4.1
79337	RDC37	601678	6960903	25-Jul-09	met	x	sil								grab	float/sub c	quarzite/gneiss with >1 biot With qutz & limonite stnng	Regional	7.5 km NW of [property	0.7
79338	RDC38	601984	6961934	26-Jul-09	int		sil								grab	o/c	lil grey, green quarztite? In Granodiorite	Regional	7.5 km NW of [property	0.25
79339	RDC39	599586	6960363	26-Jul-09	met		sil								grab	sub o/s	hard grey green sil quartzite	Regional	7.5km NW; sthrn saddle heli stop on reg. Traverse	0.25
79340	RDC40	599484	6960363	26-Jul-09	met		sil								grab	o/c	sil lim stnd. Prop Qtz monz with fw vugs Some bio in adj rocks	Regional	7.5 km NW of [property	0.25
79341	RDC41	606706	6958932	28-Jul-09	int		sil								grab	sub o/c	sil. Breciated qutz monz? With qtz, biot. Single angular float close to ridge in mixed qutz monz boulders	S/E end of 09 Grid between L 7800/7200	btwn. Line 7800/7600 S end of 09 grid below 6+ g Au rock sample	9.6
79342	RDC42	606800	6958852	28-Jul-09	int	x	sil							py	grab	sub o/c	Lite lim. Stnd recessive sil. Alt. Fine grnd. Sugary quartzite with qtz few specs py	S/E end of 09 Grid between L 7800/7201		3.3
79343	RDC43	607138	6958832	28-Jul-09	int	x	sil							py	grab	sub o/c	lite lim. stnd sil. Alt. Fine grnd. Sugary quartzite with fine grnd. qtz / altered gneiss with fw bio	S/E end of 09 Grid between L 7800/7202	S end of L7200 09 Grid	130.9
79344	RDC44	607139	6958823	28-Jul-09	int	x	sil							py	grab	sub o/c	Qtz vein with small limonite stnd vugs attached to alt gneiss/qutz monz?with foliations contains qutz and bio	S/E end of 09 Grid between L 7800/7203		12.5

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb
79345	RDC45	607195	6958864	28-Jul-09	int	x	sil								grab	sub o/c	limonite stnd alt.sugary Qtz. Monz/gneiss? With qtz minor bio	S/E end of 09 Grid between L 7800/7204		649.7
79346	RDC46	607252	6959076	28-Jul-09	int	x	sil								grab	sub o/c	bleached lite wkly limonite stnd alt. Quartzite with qtz	S/E end of 09 Grid between L 7800/7205		11.1
79347	RDC47	602528	6957681	30-Jul-09	int		sil							py	chip	o/c	1 m+x15cm thick qtz vein with + dis/fracture coat py in alt granodiorite	Headwaters Canadian Ck	Above CC2000-04 out crop exposed by slump on S side of ck	0.7
79348	RDC48	602528	6957681	30-Jul-09	met		sil							py	grab	o/c	Course grnd sil alt granodiorite with bio, qutz, +dis py, sericite in some float	Headwaters Canadina Ck	Above CC2000-04 out crop exposed by slump on S side of ck	3.4
79349	RDC49	602625	6957673	30-Jul-09	met	x	sil							py	grab	o/c	bleached lite wkly limonite stnd alt. Sil Quartzite with + qtz fw py	Headwaters Canadina Ck	~250m downstream from CC2000-05	97.6
101651	101651	607561	6958377	23-Aug-09	int			ser						py	grab	float	morgan find lt gy phyllic alt int; strong ser, wh py to 1%; qv's with py, aspy?	Canadian Ck	near Canadain CK at stn 6800W/12100N	11.6
101652	101652	605365	6958563	25-Aug-09	met										grab	float	feox-lim alt biot gnss - boring	Ana N	on CC09-01 road	0.25
101653	101653	605417	6958575	25-Aug-09	met	x									grab	o/c	y-or weath strongly weath zone at up of gnss o/c	Ana N	on CC09-01 road	1.6
101654	101654	605579	6958574	25-Aug-09	met	x									grab	o/c	grabs of 5cm v strong clay alt shear at top of o/c	Ana N	on CC09-01 road	18
101655	101655	606576	6958601	25-Aug-09	met	x								minor	rec chip	o/c	grabs along 4 m of old trench of feox stained biot gnss; minor py	Ana	jct of CC09-01 road and casino rd	3.5
101656	101656	606596	6958542	25-Aug-09	met									1%	rec chip	o/c	grabs of roadcut of reusty biot-qtz gnss with 1% py	Ana	on road 50m S of CC09-01 rd jct	47.2
101657	101657	607084	6957442	26-Aug-09	int		x		x					20%	grab	trench	grab from trench of 0.5m wide az 010 sil-py-tourmaline alt zone	Ana Pass	in 1993 trench TR-2	2516.9
101658	101658	607100	6957639	26-Aug-09	int									minor	grab	s/c	luecocratic fg int; jarosite	Ana Pass	on road below CC2000-3	10.8
101659	101659	607120	6957523	26-Aug-09	int			x						minor	grab	s/c	rd weath gd; rusty Fe-Mn stain; wk ser, minor py	Ana Pass	at drill site CC2000-3	34.7
101660	101660	606824	6957234	26-Aug-09	int			x						minor	grab	float	rysty cg gd; ser alt, minor py	Ana Pass	old trench	89
101661	101661	607013	6957371	29-Aug-09	int	x									grab	float	grabs of strongly feox alt gd?	Kana	L6400/13850N	18.9
101662	101662	608107	6959447	31-Aug-09	met	x									grab	float	morgan sample feox stained qtzite	Kana	L6200W/13150N	36
101663	101663	605173	6958505	06-Sep-09	met										grab	float	grabs of quartzite from overbuden cored at top of CC09-01	Ana N	overbuden from hole CC09-01	2.2
101664	101664	607013	6957374	24-Sep-09	qtz vn	x									grab	float	grab of sgl oc 3cm wide feox stained qtz vn	Ana Pass	old trench? 50m SW of 1993 TR-2	294.7

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb
101665	101665	607058	6957379	24-Sep-09	int	x				x	x			1%	grab	float	strong fe-mnox stained chl-sas alt gd with 1% wh py	Ana Pass	old trench? 25m SW of 1993 TR-2	39.1
101666	101666	607082	6957445	24-Sep-09	int		x	x	x	x				to 10%	chip	trench	3m chip across 0.5m wide sil-torm-py alt structure (101557 sample) and ser-py alt wallrocks	Ana Pass	in TR-2	866.5
101667	101667	607084	6957447	24-Sep-09	int			x	x	x	x				grab	trench	grabs of or weath saus-ser alt gd; local tourm	Ana Pass	in TR-2	448.6
101668	101668	607082	6957440	24-Sep-09	int			x		x	x			5%	rec chip	trench	grabs over 1m of wallrock to 101557 structure; saus-chl-py alt gd	Ana Pass	in TR-2	573.7
101669	101669	607080	6957449	24-Sep-09	int				x	x	x			2%	grab	trench	gn chl-saus-py alt gd on E side 101557 structure	Ana Pass	in TR-2	167.8
101670	101670	607102	6957369	24-Sep-09	int	x						x			grab	float	fe-mnox stained gd; no py, abund mgt, lim boxwork	Ana Pass	40m S of TR-2; buried trench?	160.8
101671	101671	607015	6957438	24-Sep-09	int							x		2%	grab	float	0.3m float strong or weath gd with 1-2% wh diss py masses, local mgt	Ana Pass	50m W of TR-2	62
101672	101672	607093	6957421	24-Sep-09	int				x						grab	float	0.2m float lim alt gd with 1cm lim-tourm vn	Ana Pass	50m W of TR-2	299.9
101951	CRC51	609076	6957933	8-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on east wall; intermittently yellow to dk red-brown, primarily yellow (ser?) alt'n; qtz/py	Trench 9076-C	starts at south end of trench, continues to N	34.7
101952	CRC52	609074	6957936	8-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on east wall; intermittently yellow to dk red-brown, primarily yellow (ser?) alt'n; qtz/py	Trench 9076-C	Casino B	150.4
101953	CRC53	609073	6957939	8-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on east wall; intermittently yellow to dk red-brown, primarily yellow (ser?) alt'n; qtz/py	Trench 9076-C	Casino B	124.9
101954	CRC54	609072	6957943	8-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on east wall; intermittently yellow to dk red-brown, primarily yellow (ser?) alt'n; qtz/py	Trench 9076-C	Casino B	776
101955	CRC55	609070	6957946	8-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on east wall; intermittently yellow to dk red-brown, primarily yellow (ser?) alt'n; qtz/py	Trench 9076-C	Casino B	1078.9
101956	CRC56	609069	6957949	8-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on east wall; intermittently yellow to dk red-brown, primarily yellow (ser?) alt'n; qtz/py	Trench 9076-C	Casino B	255.1

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb	
101957	CRC57	609067	6957952	8-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on east wall; intermittently yellow to dk red-brown, primarily yellow (ser?) alt'n; qtz/py	Trench 9076-C	Casino B	250	
101958	CRC58	609066	6957955	8-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on east wall; intermittently yellow to dk red-brown, primarily yellow (ser?) alt'n; qtz/py	Trench 9076-C	Casino B	125.9	
101959	CRC59	609064	6957959	8-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on east wall; intermittently yellow to dk red-brown, primarily yellow (ser?) alt'n; qtz/py	Trench 9076-C	Casino B	188.4	
101960	CRC60	609068	6957935	8-Aug-09	int		x	x						x	grab	trench	West wall of trench across from CRC55, qtz/py with yellow/brown (ser? and lim) alt'n	Trench 9076-C	Casino B	780.3	
101961	CRC61	608974	6957809	9-Aug-09	int		x	x		x				x	grab	trench	str phyllic (qtz-ser-py) alt'n, blocky, coarse grained, probable g'diorite protolith	Trench 9053-A	south end of trench	131.7	
101962	CRC62	608973	6957813	9-Aug-09	int		x	x						x	chip	trench	~5m chip/panel taken on west wall; predominantly light yellow brown (ser-lim)	Trench 9053-A	samples start at S end of trench, run to N	494.3	
101963	CRC63	608974	6957818	9-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, more lim than ser		Trench 9053-A	259.4	
101964	CRC64	608976	6957823	9-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, as above, patches of clay (kaolinite?)		Trench 9053-A	222.4	
101965	CRC65	608977	6957828	9-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, limonitic to south end of sample, more ser to N		Trench 9053-A	572.5	
101966	CRC66	608979	6957833	9-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, sericitic, latter 1/2 of sample predominantly clay (kaolinite)		Trench 9053-A	118.1	
101967	CRC67	608980	6957838	9-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, front 1/3 is clay, latter ser		Trench 9053-A	573.8	2372.2
101968	CRC68	608808	6957946	13-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, unconsolidated, weathered, lite yellow to rusty red-brown (sericite-limonite), qtz chips, g'diorite	Trench 9076-E	starts at south end of trench, continues to N	36.6	
101969	CRC69	608810	6957951	13-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, as above	Casino B	Trench 9076-E	30.2	
101970	CRC70	608812	6957956	13-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, as above	Casino B	Trench 9076-E	42.5	
101971	CRC71	608814	6957962	13-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, more blocky, locally sil, 7-10% frac py, tr bornite?, poss cp?	Casino B	Trench 9076-E	76.4	
101972	CRC72	608816	6957967	13-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, rockier, blocky, lite brown to beige, locally lim	Casino B	Trench 9076-E	60.7	
101973	CRC73	608819	6957972	13-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, as above, very friable	Casino B	Trench 9076-E	46.6	

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb
101974	CRC74	608821	6957977	13-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, blocky, more competent g'diorite sxns, alt'd, limonitic th/out	Casino B	Trench 9076-E	68.5
101975	CRC75	608823	6957983	13-Aug-09	int		x	x						x	chip	trench	~5m chip/panel, less blocky, 50/50 limonitic/sericitic?, weathered, alt'd	Casino B	Trench 9076-E	69.8
101976	CRC76	608814	6957962	13-Aug-09	int		x	x					x	x	grab	trench	alt'd, strongly siliceous, 7-10% frac py, trace bornite, poss cp	Casino B	Trench 9076-E	27.9
101977	CRC77	603996	6957436	15-Aug-09	int	x	x							x	grab	s/c/float?	well weathered g'diorite-diorite, lt yellow to med brown, limonitic, tr py, local bxwk	L10400W	small patch of pebbles/cobbles; creek debris?	48.4
101978	CRC78	604045	6957468	15-Aug-09	int		x	x		x		x		x	grab	s/c/float?	in dry ck, hem after mt, ser-chl, tr py, lt green matrix, g'diorite to diorite	L10400W	dry creek bed	74.2
101979	CRC79	604039	6957467	15-Aug-09	int										grab	float	granular, limonitic pebbles/rock chips to 1cm, stream deposit material	L10400W	dry creek bed	35.9
101980	CRC80	603993	6957856	15-Aug-09	met	x	x	x		x				x	grab	float	angular up to 20-25cm, matrix dk grey to lt green, vfg to aphanitic, tr py, probable ser-chl, 30-40% biotite, limonitic spots, gneissic texture	L10400W	dry creek bed	3
101981	CRC81	603869	6958782	15-Aug-09	met	x	x							x	grab	float/s/c	off-white to beige, wkly limonitic, tr-locally 0.5% py, probable qtzite	L10400W	bottom of slope, ~40-50m S of line	1.8
101982	CRC82	603940	6959077	15-Aug-09	met		x	x		x				x	grab	s/c/o/c?	str limonite coating, tr to locally 0.5-1% py, gen as frac coat and/or diss, probable ser+/-chl, greenish tinge th/out, 50%? Fg biotite, gneissic	L10400W	small o/c at bottom of hill slope	1.3
101983	CRC83	605598	6958047	17-Aug-09	vein		x							x	grab	o/c	lt grey, tr py, g/diorite wallrock	L8800W	top of Koffee Pk	0.9
101984	CRC84	605587	6958037	17-Aug-09	vein		x								grab	o/c		L8800W	top of Koffee Pk	1.9
101985	CRC85	605587	6958038	17-Aug-09	met	x	x	x							grab	float/s/c	angular; ~ 15x30cm, v. strongly limonitic, 30-40% fg biot, str qtz veining, probably ser, gneiss	L8800W	top of Koffee Pk, ~ 1m north of previous sample	1.5
101986	CRC86	605598	6958505	17-Aug-09	met	x	x							x	grab	float/s/c	limonitic qtzites & gneisses, v.fg biotite, tr py, siliceous, gneiss	L8800W	L8800W/12425N	23.7
101987		606529	6958805	20-Aug-09	met	x	x	x							grab	s/c	str limonite, ser, siliceous, dk grey fg matrix, fg biotite?, qtzite	L7800W	boulder fields, somewhat recessive zone	3.6
101988		606540	6958831	20-Aug-09			x	x							grab	s/c	angular, mod-str lim, lite green-grey to lite yellow matrix, ser-sil, qtzite	L7800W	8m south from 12650N	3.6
101989		606557	6958956	20-Aug-09		x	x							x	grab	s/c	strongly alt'd, limonitic, tr py, qtzite w/ qtz monz	L7800W	recessive area 8m east of 12775N	36.7

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb
101990		605795	6958028	20-Aug-09		x	x							x	grab	s/c	interlayered/banded qtzite, some bands strongly limonitic, tr py?	L8600W	11900N pkt	2.3
101991		606747	6959148	22-Aug-09		x	x	x						x	grab	float	strongly limonitic, ser, sil, 0.5-2% diss py, protolith probable intrusive	L7600W	~10m east of 12975N	28.9
173660	CRC10	606420	6957919	24-Jul-09	met	x	x					x		x	grab	s/c	probable qtz monz, wk-mod limonitic	Ana Pk area		6.1
173661	CRC11	606405	6957997	24-Jul-09	int	x	x	x		x				x	grab	s/c	probable Patton ppy or variety, very strg limonite	Ana Pk area	recessive, ~1.5w x 8m long (uphill)	115.5
173662	CRC12	606392	6958139	24-Jul-09	int	x								x	grab	o/c	mod to strg limonite	Ana Pk area		40.3
173663	CRC13	606392	6958139	24-Jul-09	met	x	x								grab	o/c	strg limonite, dk gry to blk, fg	Ana Pk area	taken immed. N of last sample	9.2
173664	CRC14	606395	6958179	24-Jul-09	int		x						x	x	grab	o/c	dk gry to blk fg matrix w/ 3-6mm ang qtz/f'spr clasts/xtls, probable Patton ppy	Ana Pk area		39.4
173665	CRC15	600459	6960865	25-Jul-09	met	x	x							x	grab	o/c	str limonite, gneissic (diorite?)	north regional		0.25
173666	CRC16	600459	6960865	25-Jul-09	vein	x	x							x	grab	s/c	limonitic qtz vein next to above sample, 4-5cm width	northwest regional - ~ 7.5 km	taken next to above	4.8
173667	CRC17	600682	6960925	25-Jul-09	int	x	x								grab	o/c	strongly alt'd/bleached, buff colour, fg-mg, limonitic frac coat, local Mn? On fracs; carbonitization?, probable qtz monz	northwest regional - ~ 7.5 km		0.25
173668	CRC18	601525	6961241	25-Jul-09	vein	x	x							x	grab	float/s/c	wk-mod lim, 3-5% py	northwest regional - ~ 7.5 km	small talus/bldr jumble on w slope	0.25
173669	CRC19	601910	6961750	25-Jul-09	volc		x							x	grab	o/c	rusty/limonitic o/c, siliceous, 5-10% qtz "eyes", remnant plag, probable rhyo-dacite	northwest regional - ~ 7.5 km	recessive limonitic area	0.25
173670	CRC20	602783	6963825	26-Jul-09	int		x							x	grab	o/c	recessive/shattered rk, mod-str limonitic, qtz flooded, Mn on fracs, tr py	northwest regional - ~ 7.5 km		1.8
173671	CRC21	603143	6961041	26-Jul-09	met		x							x	grab	o/c	meta-diorite (gneissic), local Mn, strongly alt'd, recessive	northwest regional - ~ 7.5 km		0.25
173672	CRC22	599231	6960399	26-Jul-09	met	x	x								grab	o/c	meta-diorite, limonitic	northwest regional - ~ 7.5 km		0.25
173673	CRC23	599406	6960352	26-Jul-09	met	x	x							x	grab	o/c	meta-diorite/qtz veining, strong limonite, alt'd/bleached, tr py	northwest regional - ~ 7.5 km	recessive limonitic area	0.25
173674	CRC24	606476	6958360	28-Jul-09	met	x	x	x							grab	s/c	meta-sed, fg-mg, limonitic, almost phyllitic in appearance	Au anomalies near Ana Pk	recessive	22.7
173675	CRC25	606484	6958444	28-Jul-09	int	x	x							x	grab	s/c	strongly alt'd qtz monzonite?, granular	Au anomalies near Ana Pk	very recessive	3.5

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb
173676	CRC26	606542	6958526	28-Jul-09	met	x	x	x							grab	o/c	phyllitic appearance, str limonite, meta-sed?	Au anomalies near Ana Pk		9.4
173677	CRC27	606807	6958915	28-Jul-09	met	x	x							x	grab	o/c	strongly bleached/alt'd, sucrosic, qtzite?	Au anomalies near Ana Pk		116.7
173678	CRC28	607110	6958874	28-Jul-09	met		x								grab	s/c	limonitic frac coat alt'd/bleached qtzite, poss old sample site	Au anomalies near Ana Pk	next to old pkt - no tag	1.8
173679	CRC29	607146	6958914	28-Jul-09	met		x							x	grab	o/c	30-35% bt, sucrosic, qtzite	Au anomalies near Ana Pk		9.3
173680	CRC30	607142	6958935	28-Jul-09	vein	x	x								grab	s/c	recessive/shattered rk, bx'd qtz with >30% fg bt, limonitic, boxwk	Au anomalies near Ana Pk	recessive limonitic scree, middle of talus slope, open grassy area	81.2
173681	CRC31	607151	6958968	28-Jul-09	met	x	x								grab	s/c	recessive, limonitic, <2% bt, qtzite	Au anomalies near Ana Pk	recessive	34.7
173682	CRC32	606336	6957345	29-Jul-09	int									x	grab	float	large g'diorite bldrs, mg-cg	Au anomalies east of Ana Pk		20.6
173683	CRC33	606247	6957201	29-Jul-09	int					x				x	grab	s/c/o/c?	jumble of g'diorite bldrs, wkly friable, str chl	Ana Pass	break in slope, poss lineament?, trends ~126-306	126
173684	CRC34	606376	6957018	29-Jul-09	int	x	x							x	grab	s/c	frost heaved ang bldrs, alt'd qtz flooded cobbles, limonitic, boxwork common, tr py, alt'd g'diorite	Ana Pass	patch of alt'd cobbles	16.7
173685	CRC35	606693	6957323	29-Jul-09	int		x								grab	float	trench site, strongly alt'd/bleached, local boxwork, alt'd diorite	Ana Pass	disturbed area, site of 405ppb Au? In soil	187.6
173686	CRC36	605722	6956224	29-Jul-09	int	x	x								chip	o/c	~1m vertical chip, alt'd g'diorite	across from core shack	test pit dug in ck for water, strong limonite	1.8
173687	CRC37	605725	6956224	29-Jul-09	int	x	x								chip	o/c	~1.5m vertical chip, alt'd g'diorite	across from core shack	test pit dug in ck for water, strong limonite	3
173688	CRC38	602948	6957605	30-Jul-09	int		x							x	grab	o/c	strongly alt'd, 3-5% diss/stringer py in qtz-ser (phyllic alt)	upstream from CC2000-05	south bank of ck	5.8
173689	CRC39	602999	6957594	30-Jul-09	int		x							x	grab	o/c	as above, locally up to 50% py on fracs	upstream from CC2000-05	south bank of ck	50.7
173690	CRC40	607252	6958955	1-Aug-09	met	x	x							x	grab	o/c- s/c	mod-str limonite, strongly bleached/alt'd, minor bt, tr py, probable alt'd qtz monz	Au soil anoms from L7200 to L6400	close to brow of hill, minimal transport	20.4
173691	CRC41	607403	6959013	1-Aug-09	met	x	x	x						x	grab	o/c- s/c	str limonite, alt'd, rare local yellow cast-ser?, 1-3% vfg py, occ qtz stringer, qtzite	Au soil anoms from L7200 to L6401		17.8
173692	CRC42	607518	6958982	1-Aug-09	vein	x	x							x	grab	s/c-talus	white, crystalline, limonitic on fracs, occ vug, tr py, poss tr actinolite?	Au soil anoms from L7200 to L6402	talus slope	9.6

Sample_ ID	Field ID	UTM_ Easting	UTM_ Northing	Sample_ Date	Litho	lim	sil	ser	tourm	chl	saus	mgt	cp	py	Sample_ Method	Rock_ Source	Sample Description	Area	Location Description	Au ppb
173693	CRC43	607592	6959157	1-Aug-09	met		x			x				x	grab	o/c- s/c	fg light grey to off-white, sucrosic, 1-2% vfg chl plus/minus ser spots, tr py, qtzite	Au soil anoms from L7200 to L6403	on ridge	13
173694	CRC44	607903	6959055	1-Aug-09	met	x	x	x						x	grab	s/c-talus	mod-str limonite, alt'd to buff yellow, occ qtz stringer, tr py, tr actinolite, qtzite	Au soil anoms from L7200 to L6404	close to ridge crest	5
173695	CRC45	602932	6957616	2-Aug-09	int		x							x	grab	float	qtz-py-ser with trace moly, locally up to >50% py, gen 5-10% as frac coat/stringers	Koffee Creek Zone upstream fr CC2000-05	in creek	210
173696	CRC46	603041	6957584	7-Aug-09	int		x	x		x				x	grab	o/c	strongly alt'd g'diorite, light yellow/ser alt'n overprint with qtz-py (phyllic alt)	Koffee Creek Zone upstream fr CC2000-05	slumped S bank of ck, pyritic "yellow" zone	13.1
173697	CRC47	603077	6957573	7-Aug-09	int	x	x					x		x	grab	o/c	strong dk brown-red limonitic, alt'd g'diorite, mod mag, 1-3, locally 5-7% diss/frac coat py	Koffee Creek Zone upstream fr CC2000-05	slumped S bank of ck, strongly fractured/jointed	346.1
173698	CRC48	609079	6958028	8-Aug-09	int		x	x						x	grab	float/s/c	Pebbles/debris taken in ck	Near Trench 9076-C	old trench?, ck flows through	58.5
173699	CRC49	609079	6958031	8-Aug-09	int		x	x						x	grab	float/s/c	Pebbles/debris taken in ck	Near Trench 9076-C	old trench?, ck flows through	48.1
173700	CRC50	609083	6958032	8-Aug-09	int		x	x						x	grab	float/s/c	Pebbles/debris taken in ck	Near Trench 9076-C	old trench?, ck flows through	35.6
793651	CRC1	604607	6957800	23-Jul-09	met	x	x								grab	talus	gneiss, fg, limonitic, foliated	west As anomaly area	downslope fr ridge crest	1.2
793652	CRC2	604607	6958473	23-Jul-09	met		x							x	grab	o/c	gneiss,foliated	west As anomaly area	b/twn 9600-9800W, ~12600N	3.2
793653	CRC3	604695	6958344	23-Jul-09	met	x								x	grab	o/c	gneiss, foliated, limonitic	west As anomaly area		7.4
793654	CRC4	604767	6958383	23-Jul-09	vein / met	x		x						x	grab	talus	qtz rubble, limonitic, 5-7% py, occas qtz rich gneiss	west As anomaly area	recessive, ~4-5m wide	16.2
793655	CRC5	604017	6958215	23-Jul-09	int									x	grab	s/c	bx'd?, poss mfc inclusions, qtz monzonite	west As anomaly area	south of saddle (ctc zone)	0.25
793656	CRC6	605003	6958451	23-Jul-09	int / met									x	grab	s/c	ctc zone? Qtz monz; gneissic, fine grained, tr moly	west As anomaly area	b/twn 9400-9200	4.4
793657	CRC7	605052	6958443	23-Jul-09	met									x	grab	s/c	probable metased, fg, laminated/foliated, limonitic	west As anomaly area		2.9
793658	CRC8	605137	6958419	23-Jul-09	met		x							x	grab	s/c	probable metased, fg, laminated/foliated, limonitic	west As anomaly area		1
793659	CRC9	604628	6958727	23-Jul-09	met		x							x	grab	s/c	quartzite? (Yukon Meta Cmplx), light beige to lt brown, crystalline	west As anomaly area		0.9

APPENDIX 4

2009 Analytical Results

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: September 25, 2009
Report Date: October 08, 2009
Page: 1 of 4

CERTIFICATE OF ANALYSIS SMI09000284.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC-CO-09-04
P.O. Number
Number of Samples: 70

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200	66	Crush split and pulverize 250g drill core to 200 mesh			VAN
1DX15	70	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000284.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937135	Drill Core	8.55	1.7	94.7	9.3	38	0.4	7.3	12.6	380	3.74	103.4	2.2	43.8	10.0	31	<0.1	1.8	15.5	64	0.69
937136	Drill Core	8.09	0.9	31.9	7.1	29	<0.1	5.1	8.3	287	2.53	65.9	2.6	8.9	12.7	19	0.1	1.3	1.9	33	0.59
937137	Drill Core	8.40	7.9	30.7	6.7	42	0.2	6.5	9.2	440	3.50	46.6	3.5	9.9	13.3	23	<0.1	1.1	3.9	72	0.69
937138	Drill Core	5.65	1.1	24.9	5.0	38	0.1	11.1	7.5	363	2.43	46.4	2.7	5.0	12.3	19	<0.1	1.0	3.8	44	0.51
937139	Drill Core	6.79	20.3	12.9	6.8	35	0.2	5.6	5.8	336	2.20	38.1	2.9	7.4	17.6	10	<0.1	1.2	4.7	22	0.42
937140	Rock Pulp	0.04	2.9	34.9	21.1	80	0.2	23.6	9.1	737	3.60	6.6	0.4	0.6	1.2	34	0.2	0.4	0.1	61	0.77
937141	Drill Core	5.84	0.7	16.1	8.2	25	0.2	5.7	4.6	214	2.05	31.0	2.2	4.7	15.1	13	0.1	1.1	1.1	23	0.73
937142	Drill Core	6.27	1.4	10.8	8.9	25	0.1	5.2	4.3	227	2.01	43.9	2.7	5.6	14.5	13	0.1	1.4	1.3	20	0.77
937143	Drill Core	8.91	0.8	11.4	7.2	19	<0.1	4.2	4.0	192	1.71	36.1	6.3	4.4	17.6	12	<0.1	0.6	1.2	17	0.66
937144	Drill Core	7.53	1.0	9.2	8.5	26	0.2	7.5	8.4	322	2.47	136.2	4.7	13.0	17.2	19	<0.1	0.7	2.7	22	1.34
937145	Drill Core	7.50	5.3	26.5	4.9	28	0.1	15.0	7.8	288	2.73	47.3	3.2	5.6	17.1	25	<0.1	0.8	2.8	63	0.75
937146	Drill Core	9.13	2.5	13.3	5.7	24	0.1	5.3	6.0	269	2.10	80.8	2.8	4.1	13.7	24	0.1	0.9	1.4	21	0.95
937147	Drill Core	6.53	0.9	11.8	4.7	26	<0.1	5.5	5.7	257	2.14	21.8	2.8	1.9	15.5	18	<0.1	0.7	0.9	27	0.51
937148	Drill Core	10.59	4.5	13.4	5.8	24	<0.1	5.2	5.4	241	2.06	27.2	4.2	4.6	16.9	29	<0.1	0.9	0.8	27	0.68
937149	Drill Core	10.01	2.4	59.7	11.2	27	0.2	18.2	9.1	278	2.41	227.9	3.9	14.9	6.7	29	0.2	1.7	1.2	44	1.18
937150	Drill Core	9.40	2.2	90.8	12.3	27	0.4	41.9	10.6	316	3.34	136.3	3.5	24.6	8.5	35	0.2	2.5	4.5	60	1.95
937151	Drill Core	12.25	0.4	88.5	7.7	45	0.3	249.9	31.2	479	4.07	98.6	0.9	14.5	2.4	88	0.2	3.6	2.3	87	3.16
937152	Drill Core	7.49	0.9	34.3	6.5	26	0.2	27.4	6.7	196	2.31	47.0	3.8	13.2	12.6	29	0.1	1.0	1.0	59	0.96
937153	Drill Core	2.20	1.3	2.8	8.7	43	0.3	123.3	225.1	511	10.36	277.1	4.9	180.8	13.4	42	<0.1	1.7	15.4	87	3.38
937154	Drill Core	10.08	1.3	171.1	8.4	40	0.5	58.0	12.9	452	4.99	102.7	2.2	20.6	10.4	39	0.1	2.3	2.5	84	2.20
937155	Drill Core	10.28	1.2	64.5	7.6	26	0.3	9.4	8.7	282	3.32	79.1	3.3	22.2	14.9	51	0.1	1.6	1.8	35	1.82
937156	Drill Core	10.97	0.5	16.0	11.4	27	0.1	7.0	6.8	217	2.12	249.4	3.0	8.5	13.0	53	0.2	1.4	1.0	18	1.68
937157	Drill Core	10.41	8.9	41.3	8.3	26	0.1	26.4	6.2	225	1.98	80.2	8.6	5.0	15.7	39	<0.1	1.4	1.0	80	1.13
937158	Drill Core	10.07	4.5	78.2	5.8	35	0.2	45.1	9.1	281	2.73	282.7	5.4	6.0	7.9	26	0.2	1.2	1.1	123	0.91
937159	Drill Core	10.36	1.3	20.6	9.9	51	<0.1	8.6	5.5	381	1.70	230.7	7.0	4.2	13.5	43	0.1	2.7	0.7	21	1.38
937160	Rock Pulp	0.08	485.0	3112	9.7	64	1.7	20.6	18.6	641	4.41	43.4	0.4	225.8	1.1	123	1.7	5.5	0.3	87	4.31
937161	Drill Core	10.48	0.6	21.4	5.7	21	<0.1	4.3	5.7	204	2.01	218.2	3.4	3.7	12.4	34	<0.1	0.6	0.8	27	0.79
937162	Drill Core	10.55	0.7	34.7	6.8	22	0.2	6.9	4.6	197	1.99	57.8	2.9	6.2	11.8	30	<0.1	0.9	2.6	26	0.80
937163	Drill Core	10.47	0.6	16.4	8.4	27	0.1	4.5	5.6	258	2.06	150.3	4.3	6.5	14.8	41	<0.1	0.8	0.8	27	0.79
937164	Drill Core	9.29	0.4	7.7	5.0	29	<0.1	4.5	5.8	292	2.15	42.7	4.0	6.1	11.6	42	<0.1	0.8	0.6	28	0.69

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000284.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937135	Drill Core	0.057	17	27	1.14	141	0.147	2	1.95	0.062	0.32	31.7	<0.01	4.5	0.3	0.92	7	0.6
937136	Drill Core	0.047	27	18	0.70	174	0.103	1	1.28	0.055	0.32	0.2	<0.01	2.8	0.3	0.49	5	<0.5
937137	Drill Core	0.059	24	22	1.03	287	0.162	1	1.69	0.054	0.71	7.9	<0.01	6.2	0.6	0.41	7	<0.5
937138	Drill Core	0.055	30	43	0.77	161	0.174	<1	1.35	0.082	0.67	5.4	<0.01	3.8	0.5	0.17	6	<0.5
937139	Drill Core	0.041	33	21	0.63	46	0.096	<1	1.08	0.038	0.33	3.0	<0.01	2.8	0.2	0.33	6	<0.5
937140	Rock Pulp	0.069	7	25	0.95	83	0.131	3	2.17	0.075	0.14	0.2	<0.01	4.4	<0.1	<0.05	7	<0.5
937141	Drill Core	0.043	29	20	0.72	37	0.057	<1	1.37	0.029	0.22	0.6	<0.01	3.1	0.1	0.29	8	<0.5
937142	Drill Core	0.041	34	20	0.62	37	0.033	1	1.11	0.033	0.20	0.3	<0.01	2.8	0.1	0.36	7	<0.5
937143	Drill Core	0.031	30	16	0.48	42	0.037	1	0.92	0.040	0.24	0.3	<0.01	2.9	0.2	0.22	5	<0.5
937144	Drill Core	0.041	42	20	0.55	49	0.010	1	1.00	0.033	0.16	0.2	<0.01	2.6	0.1	0.93	6	0.8
937145	Drill Core	0.029	29	37	0.84	163	0.127	1	1.62	0.073	0.51	0.4	<0.01	5.0	0.4	0.31	7	<0.5
937146	Drill Core	0.042	32	18	0.57	109	0.066	<1	1.11	0.045	0.35	1.5	<0.01	3.7	0.3	0.32	6	<0.5
937147	Drill Core	0.046	33	21	0.71	82	0.126	1	1.38	0.046	0.58	0.2	<0.01	4.0	0.5	0.10	7	<0.5
937148	Drill Core	0.041	26	16	0.65	102	0.101	<1	1.39	0.074	0.43	0.4	<0.01	3.6	0.3	0.18	6	<0.5
937149	Drill Core	0.046	17	30	0.71	66	0.015	<1	1.77	0.023	0.20	0.2	<0.01	2.8	0.2	0.70	6	1.0
937150	Drill Core	0.083	19	72	0.58	46	0.048	2	1.36	0.060	0.16	0.3	<0.01	3.3	0.3	1.14	5	1.1
937151	Drill Core	0.246	15	147	1.19	122	0.189	4	2.34	0.107	0.34	0.5	<0.01	4.0	0.6	0.94	8	1.3
937152	Drill Core	0.028	27	45	0.67	69	0.034	2	1.34	0.077	0.21	0.1	<0.01	3.6	0.2	0.32	7	0.6
937153	Drill Core	0.067	182	98	1.83	11	0.004	3	3.20	0.006	0.15	0.2	<0.01	5.4	0.3	5.13	16	4.8
937154	Drill Core	0.043	29	69	1.51	40	0.016	3	2.68	0.051	0.20	<0.1	<0.01	5.4	0.4	0.88	15	1.3
937155	Drill Core	0.065	32	20	0.99	73	0.008	2	2.29	0.139	0.14	<0.1	<0.01	4.4	0.2	0.56	10	0.7
937156	Drill Core	0.044	25	13	0.59	80	0.008	3	1.67	0.136	0.18	<0.1	<0.01	3.2	0.2	0.41	6	0.5
937157	Drill Core	0.048	19	33	0.47	113	0.025	2	1.07	0.101	0.24	12.3	<0.01	2.9	0.3	0.39	5	1.1
937158	Drill Core	0.091	18	59	0.72	140	0.064	1	0.99	0.029	0.38	0.5	<0.01	4.5	0.4	0.83	5	2.8
937159	Drill Core	0.043	24	12	0.48	84	0.026	2	0.97	0.048	0.20	0.2	0.02	3.2	0.4	0.19	4	0.7
937160	Rock Pulp	0.114	8	24	1.25	47	0.005	4	1.42	0.078	0.22	2.9	0.15	6.4	<0.1	1.65	6	7.4
937161	Drill Core	0.041	26	18	0.60	134	0.104	<1	1.45	0.131	0.40	0.4	<0.01	3.5	0.3	0.16	6	<0.5
937162	Drill Core	0.044	20	21	0.73	61	0.077	1	1.45	0.081	0.18	23.9	<0.01	2.8	0.2	0.23	7	<0.5
937163	Drill Core	0.044	22	16	0.69	163	0.110	1	1.73	0.140	0.34	0.2	<0.01	3.6	0.2	0.32	7	<0.5
937164	Drill Core	0.050	22	18	0.72	254	0.168	1	1.72	0.155	0.62	0.5	<0.01	4.0	0.4	0.11	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000284.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937165	Drill Core	6.65	0.7	36.3	5.6	29	0.1	6.0	5.7	249	2.12	19.9	3.2	6.8	8.7	33	<0.1	1.0	0.8	30	0.79
937166	Drill Core	7.68	2.5	118.0	6.4	38	0.4	22.3	8.9	110	2.06	114.1	4.7	3.8	6.4	3	0.3	3.9	1.0	33	0.16
937167	Drill Core	7.40	7.1	102.6	6.5	67	0.3	22.7	9.3	157	3.54	244.9	5.4	10.4	8.7	3	0.3	3.4	1.5	28	0.11
937168	Drill Core	6.83	4.2	98.5	8.0	40	0.6	29.5	10.3	293	2.78	101.6	5.0	125.1	3.8	2	0.2	2.3	2.2	31	0.08
937169	Drill Core	7.88	1.2	90.6	6.2	42	0.5	21.8	8.5	304	2.83	205.3	3.6	27.1	3.0	3	0.2	4.7	2.7	18	0.12
937170	Drill Core	8.02	1.7	93.8	7.0	66	0.5	26.0	11.2	389	2.87	67.7	6.0	12.0	5.6	4	1.0	2.4	2.0	26	0.23
937171	Drill Core	8.88	1.8	79.6	9.5	61	0.4	35.2	18.5	366	3.46	134.8	4.6	132.2	6.9	5	0.7	2.3	2.3	43	0.21
937172	Drill Core	10.27	7.2	94.6	6.7	64	0.4	60.7	15.8	451	3.92	196.6	5.6	26.7	5.8	6	0.6	2.7	3.6	89	0.37
937173	Drill Core	10.20	4.7	104.1	6.7	51	0.4	44.2	11.1	273	3.30	692.6	4.8	15.1	6.8	4	0.7	2.7	2.4	75	0.16
937174	Drill Core	10.36	3.5	71.4	7.4	58	0.4	44.3	12.0	488	3.44	266.9	2.8	13.0	5.8	7	0.4	6.3	1.3	78	0.29
937175	Drill Core	8.24	2.0	86.5	5.2	52	0.2	30.0	11.3	500	3.38	78.6	2.6	18.4	5.1	7	0.2	1.9	0.9	63	0.32
937176	Drill Core	9.83	0.7	18.6	8.9	32	0.2	7.5	5.3	306	2.13	74.2	4.7	8.6	14.9	24	0.2	2.0	0.7	19	0.87
937177	Drill Core	9.09	1.0	24.7	5.4	39	0.2	14.8	8.8	401	2.96	274.9	2.9	22.8	14.9	15	0.2	2.0	1.3	21	0.97
937178	Drill Core	10.34	1.5	10.3	8.4	30	0.1	6.5	4.2	337	1.94	49.4	4.3	4.7	16.4	19	0.2	1.1	0.7	16	1.13
937179	Drill Core	10.15	0.6	32.0	9.4	30	0.2	6.5	4.5	325	1.97	45.0	1.9	5.3	9.8	21	0.2	2.5	1.5	21	1.04
937180	Rock Pulp	0.06	483.7	3131	9.5	64	1.7	21.8	17.8	655	4.71	44.4	0.4	234.5	1.0	124	1.4	6.0	0.3	86	4.15
937181	Drill Core	9.26	1.0	21.1	15.7	36	0.4	5.4	4.2	322	2.07	74.1	1.8	7.9	12.0	19	0.2	3.2	5.3	18	0.80
937182	Drill Core	8.83	0.7	248.8	11.4	32	1.5	5.7	4.5	258	1.79	37.9	3.5	23.9	14.4	16	0.2	3.5	15.3	18	0.64
937183	Drill Core	9.47	0.6	95.4	8.6	31	0.5	6.1	4.5	274	1.90	26.7	4.6	5.2	15.8	19	0.7	1.9	2.1	20	0.65
937184	Drill Core	9.45	0.5	53.9	7.8	30	0.3	4.3	4.5	275	1.91	31.3	3.9	4.3	12.3	28	<0.1	1.5	1.1	22	0.68
937185	Drill Core	10.25	0.7	23.2	6.3	34	0.1	4.5	6.1	272	1.85	27.6	3.4	2.6	11.7	29	0.1	1.3	0.8	23	0.60
937186	Drill Core	9.66	0.3	36.8	5.0	28	0.2	5.5	4.6	215	1.67	36.5	2.8	3.4	10.0	14	<0.1	0.8	10.2	22	0.41
937187	Drill Core	8.58	0.3	64.9	8.8	26	0.3	5.3	4.1	223	1.61	29.5	2.4	8.9	15.0	15	0.1	1.8	0.7	15	0.55
937188	Drill Core	7.55	0.5	62.7	9.4	29	0.3	5.8	4.2	252	1.66	25.5	2.2	4.1	16.8	16	0.1	1.9	0.5	15	0.64
937189	Drill Core	4.99	0.4	21.6	7.9	26	0.1	4.7	3.8	261	1.68	23.6	2.2	7.1	15.3	20	0.2	2.2	0.5	14	0.88
937190	Drill Core	10.89	1.1	22.5	8.2	40	0.1	5.8	9.4	434	3.24	45.9	3.2	7.1	11.2	22	0.1	1.2	0.6	61	1.05
937191	Drill Core	10.16	0.5	58.1	16.8	44	0.4	11.9	9.5	387	3.30	124.3	3.7	21.4	15.1	20	0.2	1.9	2.9	32	1.20
937192	Drill Core	9.67	0.7	14.5	12.6	33	0.2	12.4	5.6	275	1.81	57.0	4.7	5.5	14.0	19	0.2	2.3	0.6	19	0.98
937193	Drill Core	10.51	1.3	7.0	9.7	33	<0.1	11.0	5.2	275	1.70	39.5	4.0	6.3	13.5	20	0.1	1.5	0.3	22	0.63
937194	Drill Core	10.58	2.7	18.6	9.9	32	0.1	10.6	4.4	264	1.55	71.0	3.4	7.1	14.5	26	0.1	1.5	0.4	18	0.95

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000284.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937165	Drill Core	0.051	18	23	0.71	148	0.132	1	1.49	0.136	0.61	4.4	<0.01	2.6	0.5	0.24	6	<0.5
937166	Drill Core	0.110	44	16	0.03	46	0.002	2	0.78	0.002	0.15	0.2	<0.01	2.8	0.4	0.26	2	0.6
937167	Drill Core	0.081	30	17	0.04	42	0.001	2	0.97	0.001	0.17	0.3	0.03	2.2	0.6	0.28	3	<0.5
937168	Drill Core	0.074	15	15	0.04	28	<0.001	2	0.60	<0.001	0.11	0.3	<0.01	1.5	0.2	0.57	2	1.9
937169	Drill Core	0.066	15	12	0.05	34	0.001	3	0.52	<0.001	0.13	0.2	0.01	1.3	0.3	0.67	2	0.7
937170	Drill Core	0.098	22	16	0.10	28	<0.001	3	0.82	<0.001	0.14	0.3	<0.01	1.6	0.2	0.36	3	0.8
937171	Drill Core	0.083	20	31	0.40	54	0.007	3	1.24	<0.001	0.18	0.4	<0.01	2.8	0.2	0.80	4	1.6
937172	Drill Core	0.161	17	60	0.67	146	0.027	3	1.51	<0.001	0.31	0.3	<0.01	4.0	0.3	1.08	5	3.7
937173	Drill Core	0.069	12	49	0.62	148	0.010	2	1.37	0.001	0.22	0.4	<0.01	2.5	0.2	0.87	4	3.3
937174	Drill Core	0.076	21	61	0.87	116	0.007	2	1.45	0.004	0.18	0.3	<0.01	3.9	0.2	0.82	6	2.9
937175	Drill Core	0.066	19	41	0.91	34	0.013	1	1.55	0.006	0.10	0.4	<0.01	3.9	0.1	0.36	6	1.0
937176	Drill Core	0.047	25	16	0.51	57	0.002	2	1.30	0.069	0.13	1.0	<0.01	2.9	<0.1	0.26	5	<0.5
937177	Drill Core	0.052	38	25	0.75	48	0.002	3	1.56	0.014	0.16	<0.1	<0.01	3.0	0.1	0.35	6	<0.5
937178	Drill Core	0.041	34	19	0.61	37	0.013	2	1.15	0.025	0.21	0.1	<0.01	3.2	0.1	0.10	7	0.5
937179	Drill Core	0.048	23	17	0.67	44	0.011	1	1.39	0.050	0.11	0.1	<0.01	2.7	0.1	0.10	7	<0.5
937180	Rock Pulp	0.106	8	25	1.27	76	0.005	4	1.37	0.078	0.19	3.2	0.17	6.5	<0.1	1.69	5	6.1
937181	Drill Core	0.048	23	17	0.61	41	0.012	2	1.28	0.038	0.10	7.4	<0.01	2.2	<0.1	0.16	7	0.6
937182	Drill Core	0.039	29	19	0.57	54	0.049	<1	1.08	0.042	0.18	20.4	<0.01	2.6	0.1	0.13	6	1.3
937183	Drill Core	0.043	29	20	0.65	118	0.073	<1	1.19	0.038	0.21	2.7	<0.01	3.0	0.2	0.10	6	<0.5
937184	Drill Core	0.040	23	16	0.63	289	0.075	<1	1.31	0.077	0.24	2.5	<0.01	2.6	0.2	0.13	6	<0.5
937185	Drill Core	0.041	22	15	0.60	146	0.096	<1	1.23	0.086	0.28	2.4	<0.01	2.6	0.2	0.11	6	0.7
937186	Drill Core	0.040	27	20	0.59	89	0.129	1	1.07	0.071	0.51	55.1	<0.01	3.8	0.4	<0.05	5	0.5
937187	Drill Core	0.034	29	18	0.50	28	0.026	2	0.96	0.029	0.21	0.3	<0.01	2.5	0.2	0.15	5	<0.5
937188	Drill Core	0.038	35	18	0.48	51	0.012	<1	0.92	0.029	0.14	0.1	<0.01	2.8	0.1	0.12	5	<0.5
937189	Drill Core	0.041	30	16	0.55	40	0.002	<1	1.05	0.031	0.08	0.1	<0.01	2.3	<0.1	0.20	5	0.5
937190	Drill Core	0.061	20	20	1.01	227	0.110	1	1.64	0.058	0.48	0.2	<0.01	4.6	0.4	0.42	7	<0.5
937191	Drill Core	0.042	34	27	0.83	44	0.005	2	1.44	0.028	0.14	0.5	<0.01	3.4	0.1	1.04	8	0.6
937192	Drill Core	0.033	27	23	0.56	30	0.012	2	1.01	0.033	0.13	<0.1	<0.01	2.4	<0.1	0.33	6	<0.5
937193	Drill Core	0.032	21	28	0.55	33	0.052	2	1.06	0.041	0.20	0.2	<0.01	2.9	0.1	0.10	6	<0.5
937194	Drill Core	0.029	23	23	0.57	29	0.023	1	1.02	0.030	0.14	0.1	<0.01	2.1	<0.1	0.12	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000284.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937195	Drill Core	10.11	2.2	4.7	8.8	32	<0.1	12.8	10.4	384	2.82	88.5	2.6	33.9	15.3	43	<0.1	1.1	0.6	35	1.57
937196	Drill Core	10.35	0.8	48.2	10.1	58	0.2	8.5	15.7	650	4.97	85.3	1.6	43.2	7.2	67	0.1	2.5	0.6	123	1.95
937197	Drill Core	8.56	0.4	4.8	9.7	26	<0.1	12.6	7.2	289	1.68	36.2	2.2	7.1	16.4	33	0.1	1.5	0.4	18	1.25
937198	Drill Core	8.78	0.6	3.9	8.0	32	<0.1	11.9	5.2	315	1.86	41.3	2.9	4.1	14.4	27	<0.1	1.3	0.3	22	0.85
937199	Drill Core	9.92	2.0	11.6	14.3	38	0.1	12.8	6.0	284	2.29	292.9	3.1	6.3	20.1	26	0.2	3.4	0.4	21	0.95
937200	Rock Pulp	0.04	482.5	3146	8.8	64	1.6	22.7	18.6	646	4.67	44.9	0.4	230.0	0.9	126	1.6	5.9	0.3	85	4.11
937201	Drill Core	8.15	0.8	6.5	10.1	27	<0.1	13.3	5.0	143	1.60	82.9	4.1	22.9	19.8	36	0.1	2.6	0.4	14	1.08
937202	Drill Core	9.89	0.6	3.6	8.8	27	<0.1	9.7	4.4	333	1.12	333.3	4.3	21.7	21.9	32	0.1	2.1	0.5	6	1.21
937203	Drill Core	9.14	0.9	4.9	12.5	32	<0.1	7.3	5.3	350	1.61	46.8	4.3	11.4	24.8	38	0.3	1.4	0.4	11	1.33
937204	Drill Core	8.61	0.7	6.3	19.7	45	0.1	8.5	3.9	253	1.69	42.8	6.2	7.5	20.8	30	0.3	1.8	0.3	14	1.10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000284.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937195	Drill Core	0.044	34	26	1.02	34	0.002	1	1.81	0.049	0.13	<0.1	<0.01	4.0	<0.1	0.62	8	<0.5
937196	Drill Core	0.085	17	38	1.98	138	0.036	2	3.48	0.090	0.27	0.1	<0.01	10.4	0.2	0.75	12	<0.5
937197	Drill Core	0.039	35	27	0.60	35	0.003	1	1.07	0.029	0.14	<0.1	<0.01	2.8	<0.1	0.25	6	<0.5
937198	Drill Core	0.039	29	26	0.62	38	0.033	<1	1.15	0.031	0.28	<0.1	<0.01	3.0	0.1	0.13	6	<0.5
937199	Drill Core	0.033	41	27	0.56	43	0.013	1	1.17	0.030	0.20	<0.1	<0.01	3.8	0.1	0.25	6	<0.5
937200	Rock Pulp	0.107	8	24	1.29	85	0.005	4	1.41	0.078	0.20	3.3	0.16	6.5	<0.1	1.67	5	6.9
937201	Drill Core	0.031	42	16	0.17	46	0.002	<1	0.80	0.013	0.15	<0.1	<0.01	2.9	0.2	0.22	3	<0.5
937202	Drill Core	0.033	41	9	0.09	35	<0.001	2	0.55	0.004	0.18	<0.1	<0.01	1.8	0.2	0.29	2	<0.5
937203	Drill Core	0.036	43	13	0.25	45	0.002	2	0.74	0.012	0.16	<0.1	<0.01	2.1	0.2	0.29	3	<0.5
937204	Drill Core	0.028	41	20	0.31	37	0.003	2	0.82	0.029	0.15	<0.1	<0.01	2.4	0.1	0.13	4	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

QUALITY CONTROL REPORT SMI09000284.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
937153	Drill Core	2.20	1.3	2.8	8.7	43	0.3	123.3	225.1	511	10.36	277.1	4.9	180.8	13.4	42	<0.1	1.7	15.4	87	3.38
REP 937153	QC		1.2	3.0	8.9	44	0.3	122.6	220.6	495	10.34	286.0	4.8	210.9	13.5	42	<0.1	1.7	15.3	86	3.38
937189	Drill Core	4.99	0.4	21.6	7.9	26	0.1	4.7	3.8	261	1.68	23.6	2.2	7.1	15.3	20	0.2	2.2	0.5	14	0.88
REP 937189	QC		0.4	22.6	8.2	27	0.2	4.7	3.7	270	1.72	24.8	2.1	6.2	14.9	21	0.1	2.3	0.5	14	0.90
Core Reject Duplicates																					
937155	Drill Core	10.28	1.2	64.5	7.6	26	0.3	9.4	8.7	282	3.32	79.1	3.3	22.2	14.9	51	0.1	1.6	1.8	35	1.82
DUP 937155	QC		1.2	63.8	8.0	29	0.3	10.4	8.6	292	3.38	86.4	3.6	17.5	16.0	53	0.2	1.5	2.0	36	1.83
937190	Drill Core	10.89	1.1	22.5	8.2	40	0.1	5.8	9.4	434	3.24	45.9	3.2	7.1	11.2	22	0.1	1.2	0.6	61	1.05
DUP 937190	QC		1.1	23.8	7.4	38	0.2	6.0	9.1	434	3.23	38.8	3.1	6.5	10.4	21	<0.1	1.1	0.5	63	1.03
Reference Materials																					
STD DS7	Standard		19.7	102.6	70.0	393	0.8	52.8	9.1	650	2.44	50.7	5.1	103.0	4.9	74	5.9	5.7	4.2	84	1.02
STD DS7	Standard		20.0	103.5	70.3	405	0.8	52.0	8.9	649	2.42	51.0	5.2	81.5	5.0	73	6.3	5.6	4.4	84	0.99
STD DS7	Standard		20.1	104.2	68.8	392	0.8	53.8	8.8	650	2.44	46.8	4.9	72.9	4.5	71	5.4	5.1	4.0	83	0.99
STD DS7	Standard		20.2	108.9	68.2	404	0.8	55.1	9.0	635	2.45	48.4	4.7	64.0	4.4	72	6.0	5.2	4.0	83	1.00
STD DS7	Standard		19.9	106.9	69.6	402	0.9	57.3	9.6	615	2.48	52.4	4.6	75.8	4.3	70	6.3	5.6	4.4	83	0.97
STD DS7	Standard		18.7	114.2	67.1	404	0.8	57.8	9.8	621	2.51	51.1	4.6	64.9	4.1	68	6.5	5.4	4.4	85	0.97
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	0.7	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.2	34.2	2.9	53	<0.1	4.0	4.5	631	2.12	2.1	1.8	5.5	4.2	59	<0.1	0.2	<0.1	43	0.58
G1	Prep Blank		0.2	28.8	2.7	49	<0.1	4.0	4.2	585	2.08	1.6	1.7	3.8	3.8	59	<0.1	0.2	<0.1	41	0.59

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

QUALITY CONTROL REPORT SMI09000284.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
937153	Drill Core	0.067	182	98	1.83	11	0.004	3	3.20	0.006	0.15	0.2	<0.01	5.4	0.3	5.13	16	4.8
REP 937153	QC	0.067	185	91	1.82	12	0.004	3	3.17	0.006	0.15	0.2	<0.01	5.0	0.3	5.10	16	4.9
937189	Drill Core	0.041	30	16	0.55	40	0.002	<1	1.05	0.031	0.08	0.1	<0.01	2.3	<0.1	0.20	5	0.5
REP 937189	QC	0.043	31	17	0.57	42	0.002	1	1.06	0.032	0.09	<0.1	<0.01	2.3	<0.1	0.20	5	0.7
Core Reject Duplicates																		
937155	Drill Core	0.065	32	20	0.99	73	0.008	2	2.29	0.139	0.14	<0.1	<0.01	4.4	0.2	0.56	10	0.7
DUP 937155	QC	0.074	33	20	0.99	77	0.007	4	2.28	0.135	0.16	<0.1	<0.01	4.4	0.2	0.58	10	0.7
937190	Drill Core	0.061	20	20	1.01	227	0.110	1	1.64	0.058	0.48	0.2	<0.01	4.6	0.4	0.42	7	<0.5
DUP 937190	QC	0.058	19	19	1.03	225	0.108	<1	1.62	0.055	0.46	0.3	<0.01	4.4	0.4	0.37	6	<0.5
Reference Materials																		
STD DS7	Standard	0.077	15	217	1.04	411	0.122	37	1.10	0.104	0.43	4.1	0.19	2.6	4.2	0.20	5	3.3
STD DS7	Standard	0.080	14	214	1.05	411	0.119	40	1.10	0.102	0.45	4.1	0.18	2.5	4.4	0.20	5	3.3
STD DS7	Standard	0.076	13	218	1.06	414	0.124	40	1.07	0.101	0.45	3.6	0.19	2.3	4.1	0.19	5	3.7
STD DS7	Standard	0.077	13	219	1.05	408	0.126	39	1.07	0.100	0.45	3.7	0.16	2.3	4.4	0.19	5	3.6
STD DS7	Standard	0.079	12	209	1.02	414	0.110	42	1.05	0.097	0.46	4.2	0.20	2.5	4.1	0.20	5	4.1
STD DS7	Standard	0.077	12	217	1.05	415	0.110	36	1.06	0.098	0.45	3.9	0.20	2.3	4.2	0.20	5	3.6
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.093	9	10	0.64	285	0.141	2	1.01	0.072	0.57	0.1	<0.01	2.1	0.4	<0.05	5	<0.5
G1	Prep Blank	0.080	8	9	0.62	256	0.131	1	1.02	0.072	0.57	<0.1	<0.01	2.2	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: September 25, 2009
Report Date: October 12, 2009
Page: 1 of 3

CERTIFICATE OF ANALYSIS SMI09000285.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC-CO-09-03
P.O. Number
Number of Samples: 50

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200	48	Crush split and pulverize 250g drill core to 200 mesh			VAN
1DX15	50	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 12, 2009

CERTIFICATE OF ANALYSIS SMI09000285.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937085	Drill Core	8.92	0.8	19.6	11.0	25	0.2	3.5	3.8	623	1.52	76.0	3.8	3.9	13.3	43	<0.1	1.3	0.7	6	2.04
937086	Drill Core	9.13	0.7	4.9	18.8	28	0.2	4.5	4.4	473	1.51	51.3	3.9	4.2	15.0	42	<0.1	1.3	0.5	9	1.58
937087	Drill Core	5.76	0.6	22.1	46.9	48	0.4	7.4	3.4	465	1.98	476.0	6.7	30.1	12.9	37	0.2	2.5	1.9	3	1.33
937088	Drill Core	8.00	0.6	4.3	6.6	28	<0.1	8.7	4.2	324	1.75	41.7	6.3	3.6	14.8	18	<0.1	0.6	0.6	17	0.41
937089	Drill Core	9.35	0.6	10.4	7.0	22	<0.1	10.7	4.0	274	1.64	13.9	6.6	<0.5	15.6	29	<0.1	0.9	0.7	14	0.53
937090	Drill Core	9.27	0.5	7.3	8.9	23	0.1	14.9	5.3	293	1.77	16.3	5.8	6.0	13.5	53	<0.1	0.7	0.9	17	0.67
937091	Drill Core	9.35	0.5	5.8	9.3	25	<0.1	8.7	3.5	300	1.45	12.7	4.8	3.5	11.7	35	0.1	0.5	0.5	14	0.58
937092	Drill Core	9.46	0.6	10.2	8.3	28	0.1	9.5	4.1	327	1.67	112.4	7.4	5.6	12.1	30	<0.1	0.6	0.9	14	0.66
937093	Drill Core	9.34	0.7	5.4	5.5	30	<0.1	8.1	4.0	310	1.67	4.2	3.0	<0.5	13.0	38	<0.1	0.2	0.2	19	0.47
937094	Drill Core	8.65	0.2	21.6	5.5	25	<0.1	5.8	4.0	321	1.74	8.9	3.5	2.8	11.1	52	<0.1	0.5	0.4	20	0.66
937095	Drill Core	8.84	0.7	27.4	7.0	24	0.2	9.2	4.3	330	1.81	20.2	4.2	13.0	12.6	36	<0.1	0.7	1.7	15	0.81
937096	Drill Core	8.02	0.7	7.4	5.3	24	<0.1	9.9	4.1	331	1.64	143.8	4.6	3.7	12.1	22	<0.1	0.5	0.4	19	0.45
937097	Drill Core	9.48	0.6	28.4	10.8	20	0.2	5.1	2.4	265	1.96	227.1	3.7	55.7	16.9	38	<0.1	1.3	3.4	3	0.86
937098	Drill Core	7.34	0.8	2.9	5.6	23	<0.1	3.4	2.0	272	1.23	2.2	5.2	<0.5	21.6	19	<0.1	0.3	0.3	9	0.32
937099	Drill Core	8.17	0.4	5.6	3.6	28	<0.1	15.7	5.3	397	2.02	2.7	4.7	0.8	13.5	24	<0.1	0.5	0.5	24	0.42
937100	Rock Pulp	0.12	6.8	58.9	19.0	108	1.9	15.7	7.6	158	3.23	355.8	0.1	815.4	0.5	6	0.3	32.6	0.2	15	0.17
937101	Drill Core	9.73	0.4	14.2	9.7	26	0.2	11.7	4.8	326	2.18	1145	4.5	30.5	12.9	38	<0.1	1.5	2.1	12	0.63
937102	Drill Core	9.98	0.9	37.6	10.3	23	0.3	11.1	4.2	351	2.11	463.6	6.0	35.1	14.7	34	<0.1	1.0	2.9	9	0.85
937103	Drill Core	9.08	0.8	12.1	7.1	26	<0.1	4.3	5.0	314	1.94	17.3	6.1	9.9	18.8	32	<0.1	0.7	0.7	29	0.55
937104	Drill Core	8.93	0.8	20.8	11.6	29	0.2	3.4	5.4	192	2.32	513.2	6.4	21.6	18.6	38	<0.1	1.4	2.0	19	0.41
937105	Drill Core	9.69	0.7	31.7	9.9	24	0.3	7.9	4.7	183	2.20	617.6	7.4	24.6	16.7	47	<0.1	1.6	3.3	8	0.55
937106	Drill Core	9.18	1.1	175.5	68.7	28	2.1	8.3	7.4	274	5.35	857.8	5.1	198.6	14.8	36	0.2	2.7	34.8	3	0.78
937107	Drill Core	7.38	0.7	23.2	9.6	32	0.2	7.4	4.5	416	2.03	53.7	5.8	24.4	18.1	32	<0.1	0.9	2.4	13	0.55
937108	Drill Core	2.32	0.6	29.3	41.4	24	1.0	6.5	3.7	219	3.42	4609	4.7	89.6	14.6	23	<0.1	2.5	12.1	<2	0.58
937109	Drill Core	10.08	0.6	11.5	6.0	23	<0.1	3.3	3.0	275	1.66	122.4	5.2	16.4	20.2	25	<0.1	0.9	1.0	10	0.49
937110	Drill Core	7.79	1.7	70.8	5.7	28	0.3	30.4	3.7	353	3.03	128.1	3.2	5.8	7.5	3	<0.1	3.2	1.2	47	0.07
937111	Drill Core	9.47	2.4	83.7	6.2	45	0.4	43.6	5.8	596	4.78	248.3	4.4	17.3	5.9	3	<0.1	4.6	1.2	91	0.12
937112	Drill Core	8.65	2.2	44.9	6.0	24	0.4	13.9	3.6	357	2.33	243.1	4.2	3.9	4.0	4	<0.1	3.1	0.7	47	0.16
937113	Drill Core	5.41	2.6	49.5	4.1	46	0.3	20.8	11.5	678	3.31	207.9	2.8	4.2	3.9	6	0.2	2.3	0.5	45	0.24
937114	Drill Core	8.51	3.5	70.1	4.4	37	0.3	20.7	7.5	403	2.78	155.3	3.3	7.0	3.6	5	0.2	2.7	0.7	56	0.20

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 12, 2009

CERTIFICATE OF ANALYSIS SMI09000285.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937085	Drill Core	0.041	27	9	0.25	93	0.002	3	0.56	0.018	0.25	0.1	<0.01	1.4	0.2	0.25	2	<0.5
937086	Drill Core	0.030	30	7	0.26	87	0.004	3	0.84	0.053	0.18	<0.1	<0.01	1.7	0.1	0.19	3	<0.5
937087	Drill Core	0.030	15	5	0.28	33	<0.001	1	0.65	0.002	0.16	0.1	0.01	0.9	0.3	0.91	2	<0.5
937088	Drill Core	0.021	26	17	0.49	52	0.095	<1	1.09	0.038	0.58	0.4	<0.01	3.0	0.3	0.09	6	<0.5
937089	Drill Core	0.026	27	17	0.41	37	0.033	<1	0.90	0.031	0.28	0.2	<0.01	2.2	0.2	0.16	4	<0.5
937090	Drill Core	0.032	23	19	0.58	42	0.036	1	1.29	0.025	0.38	0.3	<0.01	2.4	0.2	0.20	5	<0.5
937091	Drill Core	0.021	21	18	0.44	30	0.035	1	0.92	0.022	0.29	0.3	<0.01	2.1	0.2	0.11	4	<0.5
937092	Drill Core	0.036	22	17	0.41	40	0.043	2	0.92	0.033	0.37	5.3	<0.01	2.4	0.2	0.26	5	<0.5
937093	Drill Core	0.024	23	19	0.54	116	0.099	<1	1.15	0.084	0.50	0.3	<0.01	3.4	0.3	0.06	5	<0.5
937094	Drill Core	0.029	15	15	0.72	160	0.097	<1	1.47	0.104	0.34	0.2	<0.01	2.9	0.2	0.14	6	<0.5
937095	Drill Core	0.027	25	21	0.68	54	0.045	<1	1.10	0.045	0.35	0.2	<0.01	2.3	0.2	0.38	6	<0.5
937096	Drill Core	0.031	23	20	0.66	49	0.080	<1	1.03	0.049	0.50	0.3	<0.01	3.3	0.3	0.16	6	<0.5
937097	Drill Core	0.010	18	7	0.24	46	0.002	<1	0.65	0.017	0.16	0.2	<0.01	1.0	0.1	1.01	2	<0.5
937098	Drill Core	0.009	34	11	0.43	53	0.051	<1	0.83	0.047	0.41	0.3	<0.01	2.5	0.3	0.06	5	<0.5
937099	Drill Core	0.030	25	26	0.83	66	0.083	<1	1.29	0.043	0.59	0.2	<0.01	3.6	0.4	0.09	7	<0.5
937100	Rock Pulp	0.038	7	30	0.09	28	0.002	2	0.32	0.004	0.21	0.5	3.63	1.5	4.1	2.16	2	12.2
937101	Drill Core	0.025	20	17	0.48	37	0.012	<1	1.03	0.024	0.25	0.2	0.02	1.7	0.2	0.77	4	<0.5
937102	Drill Core	0.026	17	14	0.41	32	0.006	1	0.80	0.022	0.21	0.1	0.01	1.4	0.2	0.74	3	<0.5
937103	Drill Core	0.031	27	13	0.52	195	0.084	1	1.07	0.055	0.45	0.5	0.01	3.4	0.3	0.23	5	<0.5
937104	Drill Core	0.031	26	8	0.34	147	0.030	1	0.93	0.034	0.26	0.2	0.02	3.2	0.2	0.74	3	<0.5
937105	Drill Core	0.031	24	9	0.29	42	0.003	2	0.81	0.022	0.19	<0.1	<0.01	1.6	0.2	0.88	3	<0.5
937106	Drill Core	0.027	10	6	0.29	46	0.001	1	0.45	0.007	0.24	0.2	<0.01	0.8	0.2	4.96	1	0.9
937107	Drill Core	0.022	27	14	0.52	48	0.026	2	0.81	0.029	0.35	0.3	<0.01	2.3	0.2	0.44	4	<0.5
937108	Drill Core	0.021	6	5	0.17	42	<0.001	2	0.31	0.006	0.21	0.1	<0.01	0.4	0.1	2.96	<1	<0.5
937109	Drill Core	0.027	29	12	0.27	44	0.014	<1	0.61	0.034	0.21	0.2	<0.01	2.2	0.1	0.31	3	<0.5
937110	Drill Core	0.046	21	50	0.81	107	0.003	2	1.64	<0.001	0.22	0.2	<0.01	2.9	0.1	0.21	5	1.0
937111	Drill Core	0.090	14	107	1.60	51	0.006	1	2.44	<0.001	0.11	0.1	<0.01	4.8	<0.1	0.28	8	0.7
937112	Drill Core	0.089	9	27	0.68	49	0.006	1	1.23	0.002	0.07	0.1	<0.01	2.2	<0.1	0.13	4	<0.5
937113	Drill Core	0.073	11	27	1.13	37	0.051	1	1.83	0.003	0.11	0.2	<0.01	3.0	<0.1	0.13	6	<0.5
937114	Drill Core	0.081	16	29	0.88	52	0.023	1	1.62	0.002	0.14	<0.1	<0.01	3.0	0.1	0.24	6	0.8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 12, 2009

CERTIFICATE OF ANALYSIS SMI09000285.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937115	Drill Core	7.27	3.8	101.4	14.5	19	0.5	10.7	3.1	104	2.37	959.0	3.6	33.7	6.7	12	0.1	4.7	1.6	27	0.10
937116	Drill Core	6.99	5.4	101.0	10.0	40	0.2	19.7	20.3	148	3.65	354.0	4.4	23.8	4.9	9	0.3	3.5	1.3	38	0.15
937117	Drill Core	6.55	4.8	96.8	11.1	77	0.4	35.2	13.1	518	3.01	173.3	2.6	13.6	8.2	10	0.3	3.4	0.9	59	0.55
937118	Drill Core	10.16	5.1	145.1	10.3	69	0.6	82.3	20.7	644	4.76	267.7	4.3	27.1	6.8	17	0.3	1.4	5.4	95	0.59
937119	Drill Core	8.68	1.6	12.0	6.0	35	<0.1	35.2	12.4	338	2.29	266.7	3.8	6.6	10.7	8	0.1	1.0	0.7	28	0.29
937120	Rock Pulp	0.11	487.9	3019	9.5	62	1.7	21.4	18.9	639	4.47	41.0	0.5	312.8	1.1	114	1.2	5.8	0.3	78	4.15
937121	Drill Core	6.18	1.3	33.2	7.1	54	0.2	45.0	22.5	551	4.05	348.7	2.5	4.4	15.7	13	0.2	1.3	1.0	64	0.44
937122	Drill Core	8.43	2.4	80.3	9.2	57	0.3	41.1	14.2	467	3.46	69.0	4.7	20.1	18.6	12	0.2	0.8	3.1	39	0.46
937123	Drill Core	7.14	4.8	156.1	11.0	56	0.4	46.5	85.0	333	5.28	493.0	7.7	71.7	10.7	8	0.8	0.9	4.0	51	0.28
937124	Drill Core	4.70	14.1	23.3	11.4	180	0.1	34.7	28.9	730	3.89	114.9	5.5	23.4	12.7	11	0.7	0.7	1.4	70	0.60
937125	Drill Core	3.35	0.8	35.7	13.2	83	0.1	6.6	1.8	208	1.52	10.0	7.3	4.4	18.7	8	0.8	0.8	0.5	21	0.22
937126	Drill Core	8.21	1.1	73.1	12.4	126	0.5	19.7	13.5	737	4.92	181.8	7.2	21.1	21.6	8	0.5	1.9	2.2	37	0.29
937127	Drill Core	7.96	2.6	85.7	16.7	86	0.5	22.6	19.0	835	7.27	179.9	13.0	30.3	27.4	12	0.6	1.6	3.2	60	0.54
937128	Drill Core	8.63	1.6	729.6	26.2	83	1.8	31.6	12.4	528	4.86	248.0	8.4	59.0	13.7	8	0.9	2.7	19.2	75	0.35
937129	Drill Core	8.78	1.4	272.7	16.6	89	0.8	34.3	21.7	693	7.36	224.6	7.7	48.3	10.2	22	1.1	2.4	5.0	138	0.62
937130	Drill Core	8.14	1.3	40.5	7.0	93	0.2	17.5	13.4	696	6.89	137.3	6.5	28.6	14.3	20	0.6	1.0	2.9	65	0.45
937131	Drill Core	7.42	1.4	130.3	13.4	139	0.6	14.0	19.1	1226	10.18	150.7	6.4	38.8	18.9	12	0.2	1.4	7.4	93	0.50
937132	Drill Core	8.33	1.4	43.2	25.1	40	0.4	5.4	9.1	380	3.65	1316	3.9	18.1	17.0	21	0.2	1.6	5.2	49	0.90
937133	Drill Core	7.18	0.7	17.1	7.5	79	0.1	6.1	6.4	430	2.77	82.6	5.7	13.2	24.5	11	0.1	1.2	4.2	26	0.47
937134	Drill Core	7.04	1.7	24.7	7.7	65	0.2	8.9	27.1	606	5.78	157.6	3.0	25.1	11.8	9	0.2	1.0	8.4	90	0.52

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 12, 2009

CERTIFICATE OF ANALYSIS SMI09000285.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937115	Drill Core	0.077	32	26	0.19	105	0.002	1	0.77	0.011	0.27	0.2	<0.01	2.3	0.2	0.72	3	1.4
937116	Drill Core	0.086	23	25	0.24	48	0.002	2	0.69	0.007	0.16	0.2	<0.01	1.9	0.1	2.15	3	1.9
937117	Drill Core	0.101	38	40	0.85	42	0.009	2	1.33	0.014	0.14	<0.1	<0.01	4.5	0.1	0.74	7	1.2
937118	Drill Core	0.185	35	99	2.10	132	0.093	2	2.42	0.006	0.28	0.2	<0.01	3.8	0.2	0.80	11	1.8
937119	Drill Core	0.034	18	46	0.85	43	0.031	1	1.25	0.014	0.20	<0.1	<0.01	2.7	0.2	0.09	5	<0.5
937120	Rock Pulp	0.105	8	24	1.25	52	0.006	3	1.40	0.075	0.18	3.2	0.16	6.2	<0.1	1.63	6	6.5
937121	Drill Core	0.026	24	78	1.20	165	0.138	<1	2.24	0.030	0.63	0.2	<0.01	6.2	0.4	0.17	9	0.6
937122	Drill Core	0.047	53	61	0.99	68	0.010	1	1.85	0.019	0.16	<0.1	<0.01	2.9	0.2	0.40	7	0.9
937123	Drill Core	0.057	41	33	0.87	41	<0.001	<1	2.11	0.010	0.12	0.2	<0.01	2.4	0.1	2.82	8	2.5
937124	Drill Core	0.108	73	28	0.82	63	<0.001	3	1.90	0.046	0.19	0.2	<0.01	1.5	0.1	0.85	8	1.5
937125	Drill Core	0.038	28	7	0.49	69	<0.001	2	1.27	0.018	0.19	<0.1	<0.01	1.4	0.2	<0.05	4	<0.5
937126	Drill Core	0.043	39	19	0.90	54	0.002	1	2.05	0.036	0.12	<0.1	<0.01	3.0	0.1	1.22	10	1.3
937127	Drill Core	0.065	46	22	1.60	58	0.003	2	3.28	0.035	0.15	<0.1	<0.01	6.1	0.1	1.64	16	1.5
937128	Drill Core	0.120	36	85	1.06	57	0.004	<1	2.36	0.017	0.11	<0.1	<0.01	6.8	<0.1	1.01	10	1.0
937129	Drill Core	0.124	27	52	1.81	63	0.020	1	3.80	0.053	0.11	<0.1	<0.01	9.6	<0.1	1.56	16	1.8
937130	Drill Core	0.064	23	33	1.60	50	0.002	<1	3.51	0.027	0.11	<0.1	<0.01	4.1	0.1	1.07	13	1.2
937131	Drill Core	0.086	28	30	2.30	38	0.004	<1	4.67	0.017	0.10	0.1	<0.01	8.2	0.1	1.32	18	1.2
937132	Drill Core	0.050	25	18	1.06	38	0.005	<1	1.95	0.069	0.08	<0.1	<0.01	5.5	<0.1	0.70	10	0.9
937133	Drill Core	0.040	37	18	0.68	34	0.003	1	1.32	0.050	0.11	<0.1	<0.01	3.6	<0.1	0.66	7	0.7
937134	Drill Core	0.067	16	28	1.53	75	0.077	<1	2.34	0.024	0.18	0.4	<0.01	6.7	0.2	1.71	11	1.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 12, 2009

QUALITY CONTROL REPORT SMI09000285.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
937096	Drill Core	8.02	0.7	7.4	5.3	24	<0.1	9.9	4.1	331	1.64	143.8	4.6	3.7	12.1	22	<0.1	0.5	0.4	19	0.45
REP 937096	QC		1.0	7.2	5.7	25	<0.1	9.6	4.3	327	1.63	148.3	4.5	2.8	12.4	22	<0.1	0.6	0.5	18	0.46
937133	Drill Core	7.18	0.7	17.1	7.5	79	0.1	6.1	6.4	430	2.77	82.6	5.7	13.2	24.5	11	0.1	1.2	4.2	26	0.47
REP 937133	QC		0.7	16.4	7.4	73	0.2	6.3	6.2	415	2.67	78.8	5.3	10.9	23.9	11	0.2	1.1	3.9	25	0.45
Core Reject Duplicates																					
937109	Drill Core	10.08	0.6	11.5	6.0	23	<0.1	3.3	3.0	275	1.66	122.4	5.2	16.4	20.2	25	<0.1	0.9	1.0	10	0.49
DUP 937109	QC		0.8	13.6	6.5	25	0.1	2.9	3.6	285	1.72	115.3	5.5	10.9	20.8	25	<0.1	1.1	1.0	9	0.46
Reference Materials																					
STD DS7	Standard		21.7	112.3	69.0	393	0.8	59.5	9.1	653	2.52	51.5	4.9	61.6	4.6	83	6.1	6.1	4.6	86	1.01
STD DS7	Standard		20.4	104.5	66.0	397	0.8	57.1	9.0	643	2.48	49.2	4.5	86.0	4.4	80	5.8	5.8	4.3	83	0.99
STD DS7	Standard		21.8	111.6	71.9	411	0.9	58.3	10.0	664	2.55	50.1	5.0	66.1	4.8	71	6.1	5.4	4.7	83	1.00
STD DS7	Standard		23.0	116.9	72.4	404	0.9	63.7	10.5	697	2.65	52.4	5.1	77.8	5.0	81	6.6	5.6	4.8	86	1.11
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.2	2.8	3.0	44	<0.1	4.0	4.4	581	2.03	<0.5	1.6	2.9	3.8	55	<0.1	0.1	<0.1	39	0.51
G1	Prep Blank		0.3	10.5	2.8	75	<0.1	4.0	4.3	602	2.07	0.6	1.8	1.6	4.4	66	0.2	0.5	0.1	39	0.57

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 12, 2009

QUALITY CONTROL REPORT SMI09000285.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
937096	Drill Core	0.031	23	20	0.66	49	0.080	<1	1.03	0.049	0.50	0.3	<0.01	3.3	0.3	0.16	6	<0.5
REP 937096	QC	0.031	22	21	0.65	47	0.079	<1	0.99	0.048	0.51	0.2	<0.01	3.1	0.3	0.16	6	<0.5
937133	Drill Core	0.040	37	18	0.68	34	0.003	1	1.32	0.050	0.11	<0.1	<0.01	3.6	<0.1	0.66	7	0.7
REP 937133	QC	0.039	35	18	0.66	29	0.002	<1	1.26	0.049	0.10	<0.1	<0.01	3.4	<0.1	0.64	7	<0.5
Core Reject Duplicates																		
937109	Drill Core	0.027	29	12	0.27	44	0.014	<1	0.61	0.034	0.21	0.2	<0.01	2.2	0.1	0.31	3	<0.5
DUP 937109	QC	0.029	30	11	0.27	47	0.013	<1	0.61	0.033	0.20	0.2	<0.01	2.0	0.2	0.33	3	<0.5
Reference Materials																		
STD DS7	Standard	0.081	14	224	1.08	430	0.125	36	1.06	0.101	0.48	4.2	0.19	2.5	4.0	0.20	5	4.0
STD DS7	Standard	0.073	13	225	1.05	412	0.125	40	1.05	0.100	0.43	4.0	0.19	2.6	4.1	0.20	5	3.9
STD DS7	Standard	0.074	13	233	1.08	397	0.124	39	1.09	0.100	0.49	4.0	0.21	2.5	4.4	0.19	5	3.7
STD DS7	Standard	0.074	15	255	1.14	446	0.137	40	1.19	0.110	0.51	4.2	0.20	2.6	4.5	0.20	6	4.0
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.087	7	13	0.61	309	0.135	1	0.96	0.071	0.56	0.8	<0.01	2.1	0.3	<0.05	5	<0.5
G1	Prep Blank	0.087	9	10	0.62	294	0.145	<1	0.99	0.074	0.59	<0.1	<0.01	2.3	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: September 26, 2009
Report Date: October 08, 2009
Page: 1 of 3

CERTIFICATE OF ANALYSIS SMI09000286.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC-CO-09-02
P.O. Number
Number of Samples: 34

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200	32	Crush split and pulverize 250g drill core to 200 mesh			VAN
1DX15	34	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000286.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937051	Drill Core	2.42	0.6	5.1	10.0	32	0.2	4.9	4.7	715	2.27	4.3	5.4	0.6	12.3	36	<0.1	0.6	0.2	12	2.30
937052	Drill Core	2.02	0.2	4.4	10.6	42	<0.1	2.4	2.4	382	1.00	7.0	4.5	<0.5	20.6	8	0.3	0.6	1.5	5	0.22
937053	Drill Core	10.19	0.6	8.5	5.9	36	<0.1	3.5	3.1	331	1.34	0.8	4.6	<0.5	20.5	9	<0.1	1.2	0.5	11	0.27
937054	Drill Core	6.17	1.4	10.6	8.7	24	<0.1	2.0	2.3	283	1.01	4.5	6.5	<0.5	21.3	9	<0.1	0.9	0.7	5	0.31
937055	Drill Core	7.00	0.7	27.4	9.8	80	0.4	3.5	13.2	893	4.46	528.8	4.3	16.1	8.3	20	0.3	2.0	3.6	69	0.88
937056	Drill Core	8.60	0.5	12.3	13.5	35	0.1	2.5	3.0	446	1.26	544.6	8.0	2.9	19.1	26	0.1	1.0	0.5	5	1.18
937057	Drill Core	8.55	0.7	5.6	9.5	84	<0.1	2.2	2.8	339	1.33	1441	6.2	6.5	15.7	13	0.5	0.4	0.5	7	0.47
937058	Drill Core	9.68	0.8	6.6	13.6	32	<0.1	1.4	1.5	276	0.83	11.4	9.7	<0.5	23.6	8	<0.1	0.3	0.3	4	0.37
937059	Drill Core	9.45	1.8	10.2	9.7	23	0.1	2.0	2.6	303	1.01	7.9	5.1	<0.5	20.0	24	<0.1	0.5	0.2	8	0.71
937060	Rock Pulp	0.12	7.4	60.0	19.7	106	2.0	15.3	8.7	157	3.40	374.0	0.1	975.7	0.5	6	0.3	32.6	0.2	15	0.21
937061	Drill Core	6.05	1.1	16.2	7.5	40	<0.1	34.1	5.9	544	1.71	12.7	4.6	<0.5	11.1	45	<0.1	1.5	0.1	27	1.79
937062	Drill Core	9.48	2.3	20.9	96.0	219	0.8	7.7	6.0	821	1.24	148.1	6.9	3.5	11.2	48	1.4	1.6	1.0	6	2.81
937063	Drill Core	5.07	1.6	28.0	504.8	2157	1.9	19.9	6.9	1294	1.85	796.9	4.1	1.7	9.1	28	17.2	13.4	0.4	12	1.79
937064	Drill Core	7.11	8.1	87.6	193.1	751	1.1	55.7	7.7	638	2.06	144.1	3.1	0.7	3.0	15	6.6	4.5	0.8	130	0.80
937065	Drill Core	10.15	1.0	11.4	7.2	58	<0.1	7.4	5.0	504	1.97	19.1	3.6	<0.5	12.4	46	0.2	0.6	0.2	29	0.83
937066	Drill Core	13.18	0.9	16.8	14.0	59	0.2	10.2	5.4	584	1.88	66.6	4.3	2.8	10.9	45	0.3	1.5	0.6	28	1.12
937067	Drill Core	5.81	0.6	7.0	6.9	39	<0.1	3.5	5.1	557	1.80	12.9	7.5	<0.5	10.2	48	<0.1	1.0	0.4	22	1.35
937068	Drill Core	8.45	4.4	61.9	5.6	53	0.1	31.4	10.3	323	2.04	16.1	3.4	<0.5	9.3	31	0.1	3.0	0.2	64	0.70
937069	Drill Core	9.97	1.0	28.2	5.6	47	<0.1	12.2	7.1	643	2.30	30.5	5.1	<0.5	19.0	39	<0.1	1.6	0.3	43	1.11
937070	Drill Core	9.56	1.1	18.2	5.8	40	0.1	9.1	5.2	513	1.95	18.1	3.2	<0.5	8.5	39	<0.1	1.2	0.2	26	1.07
937071	Drill Core	6.65	0.9	6.7	8.3	55	<0.1	6.5	6.0	484	2.39	8.4	4.0	<0.5	18.1	42	<0.1	0.7	0.2	25	0.54
937072	Drill Core	6.38	1.0	28.7	52.4	131	0.5	12.0	7.0	885	1.71	595.7	4.1	19.8	10.4	46	1.1	4.7	3.2	4	2.71
937073	Drill Core	3.54	0.6	57.7	14.1	25	0.3	4.3	4.0	534	2.36	112.9	4.9	89.1	13.1	39	<0.1	2.3	1.2	2	1.68
937074	Drill Core	9.50	0.7	4.8	7.7	41	<0.1	5.9	4.7	412	1.91	11.9	4.0	2.9	20.5	28	<0.1	0.8	0.2	17	0.83
937075	Drill Core	6.79	0.7	21.4	10.1	40	0.4	6.5	4.7	297	2.02	31.1	4.7	16.8	20.0	22	<0.1	1.3	1.3	16	0.78
937076	Drill Core	6.69	4.5	11.9	10.7	31	<0.1	3.7	2.5	329	1.57	34.1	4.3	4.0	19.9	18	<0.1	0.7	0.5	6	0.70
937077	Drill Core	9.18	0.8	72.4	25.5	32	0.6	3.5	4.7	621	3.00	591.6	3.7	31.0	17.0	25	<0.1	2.1	3.8	9	1.28
937078	Drill Core	8.28	1.0	32.9	7.6	38	0.2	4.6	8.1	552	3.15	112.6	5.3	17.6	13.4	27	<0.1	1.9	1.1	29	1.13
937079	Drill Core	10.30	0.6	72.6	76.4	73	1.4	2.2	3.0	748	3.64	2011	3.0	41.5	14.7	13	0.5	5.2	13.0	<2	0.51
937080	Rock Pulp	0.12	3.0	37.7	21.1	78	0.1	22.5	10.2	731	3.60	8.7	0.3	1.4	1.1	33	0.2	0.4	<0.1	55	0.66

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000286.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937051	Drill Core	0.036	25	5	0.39	275	0.008	2	1.28	0.002	0.20	0.5	<0.01	2.1	0.2	0.13	5	<0.5
937052	Drill Core	0.019	25	5	0.17	33	0.017	2	0.64	0.016	0.21	0.2	<0.01	1.5	0.2	0.05	3	<0.5
937053	Drill Core	0.026	27	13	0.32	35	0.055	1	0.63	0.040	0.38	0.1	<0.01	2.5	0.3	0.07	4	<0.5
937054	Drill Core	0.020	23	10	0.15	16	0.014	2	0.43	0.030	0.16	0.3	<0.01	1.6	0.1	0.09	3	<0.5
937055	Drill Core	0.043	12	5	0.72	114	0.064	2	1.19	0.027	0.42	1.9	<0.01	6.3	0.4	1.44	4	<0.5
937056	Drill Core	0.030	26	8	0.25	29	0.013	2	0.66	0.027	0.18	0.1	<0.01	1.5	0.2	0.22	3	<0.5
937057	Drill Core	0.026	21	8	0.22	37	0.036	1	0.59	0.024	0.27	0.2	<0.01	1.7	0.2	0.17	3	<0.5
937058	Drill Core	0.016	20	8	0.10	13	0.015	1	0.42	0.030	0.16	0.2	<0.01	1.3	0.2	<0.05	2	<0.5
937059	Drill Core	0.017	26	8	0.16	52	0.005	<1	0.61	0.043	0.10	0.1	<0.01	1.0	<0.1	<0.05	2	<0.5
937060	Rock Pulp	0.042	8	33	0.08	29	0.002	2	0.34	0.005	0.22	0.7	3.92	1.4	4.4	2.24	2	11.0
937061	Drill Core	0.036	20	37	0.53	202	0.025	3	1.02	0.068	0.26	<0.1	<0.01	2.5	0.2	0.11	3	0.5
937062	Drill Core	0.044	24	2	0.25	29	<0.001	1	0.91	0.002	0.09	0.2	0.06	1.8	0.3	0.40	3	0.6
937063	Drill Core	0.037	13	14	0.24	75	0.005	3	0.50	0.023	0.17	0.1	0.13	1.7	0.6	0.64	2	0.7
937064	Drill Core	0.126	9	52	0.52	116	0.029	2	0.67	0.011	0.26	0.2	<0.01	3.3	0.3	0.88	4	5.4
937065	Drill Core	0.040	22	16	0.47	219	0.105	2	1.32	0.138	0.46	0.2	<0.01	3.8	0.3	0.08	5	<0.5
937066	Drill Core	0.044	19	27	0.43	162	0.076	2	1.04	0.090	0.40	0.2	<0.01	2.7	0.3	0.14	4	<0.5
937067	Drill Core	0.040	17	9	0.35	110	0.031	1	1.00	0.058	0.20	0.2	<0.01	3.0	0.2	0.06	3	0.5
937068	Drill Core	0.056	17	47	0.53	245	0.106	1	0.99	0.052	0.43	0.2	<0.01	3.4	0.3	0.38	4	1.3
937069	Drill Core	0.045	35	29	0.58	3719	0.096	1	1.21	0.065	0.48	0.2	<0.01	4.8	0.4	0.15	5	0.5
937070	Drill Core	0.039	18	22	0.48	158	0.090	1	1.15	0.075	0.46	0.3	<0.01	3.6	0.3	0.25	5	<0.5
937071	Drill Core	0.047	34	18	0.55	230	0.147	1	1.32	0.039	0.65	0.2	<0.01	5.3	0.4	<0.05	6	0.6
937072	Drill Core	0.036	12	9	0.24	68	<0.001	4	0.35	0.004	0.19	0.1	0.02	0.9	0.4	0.99	<1	0.6
937073	Drill Core	0.040	12	3	0.27	61	<0.001	3	0.49	0.005	0.21	<0.1	0.02	0.7	0.5	1.36	1	0.5
937074	Drill Core	0.040	40	17	0.37	79	0.064	3	0.92	0.033	0.38	0.1	<0.01	3.3	0.3	<0.05	4	0.6
937075	Drill Core	0.048	41	16	0.36	73	0.055	2	0.96	0.031	0.35	1.2	<0.01	2.5	0.4	0.25	4	0.5
937076	Drill Core	0.048	36	11	0.22	26	0.005	2	0.61	0.015	0.14	0.1	<0.01	1.2	0.1	0.16	3	<0.5
937077	Drill Core	0.036	21	8	0.36	56	0.002	3	0.51	0.013	0.20	0.1	0.04	1.6	0.3	1.57	2	0.6
937078	Drill Core	0.075	21	7	0.47	115	0.041	2	1.17	0.020	0.36	0.2	<0.01	3.4	0.3	0.66	4	<0.5
937079	Drill Core	0.022	10	5	0.22	39	<0.001	4	0.32	0.003	0.21	0.1	0.05	0.6	0.3	2.44	<1	0.8
937080	Rock Pulp	0.070	6	29	0.94	75	0.124	3	2.04	0.066	0.13	0.1	<0.01	4.1	<0.1	<0.05	6	0.6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000286.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937081	Drill Core	11.03	0.8	116.0	33.7	51	0.9	5.7	3.5	790	4.14	437.7	3.7	61.2	15.6	12	0.3	2.5	5.1	<2	0.48
937082	Drill Core	11.47	0.8	54.4	33.6	51	0.4	3.9	4.1	801	2.95	384.6	2.8	28.3	13.3	25	0.2	2.9	2.0	3	1.18
937083	Drill Core	8.94	0.6	70.7	35.7	42	0.6	4.4	5.1	585	3.44	393.9	2.9	53.0	10.3	20	0.3	3.7	3.0	2	0.92
937084	Drill Core	10.16	0.6	55.4	30.7	57	0.5	5.0	4.1	496	2.61	148.1	2.6	59.6	9.2	18	0.3	1.8	2.6	3	0.89

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000286.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937081	Drill Core	0.032	10	6	0.26	48	<0.001	3	0.29	0.003	0.21	0.2	<0.01	0.5	0.2	2.34	<1	0.7
937082	Drill Core	0.039	13	7	0.33	56	<0.001	3	0.33	0.003	0.24	0.2	<0.01	0.8	0.3	1.43	<1	0.6
937083	Drill Core	0.040	10	5	0.25	66	<0.001	4	0.40	0.003	0.29	0.2	0.02	0.8	0.4	2.26	<1	0.5
937084	Drill Core	0.040	10	6	0.21	63	<0.001	3	0.41	0.005	0.27	0.1	<0.01	0.6	0.4	1.67	1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

QUALITY CONTROL REPORT SMI09000286.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
937057	Drill Core	8.55	0.7	5.6	9.5	84	<0.1	2.2	2.8	339	1.33	1441	6.2	6.5	15.7	13	0.5	0.4	0.5	7	0.47
REP 937057	QC		0.7	5.4	9.6	84	<0.1	2.5	2.8	338	1.33	1442	6.6	5.4	16.0	13	0.4	0.4	0.5	6	0.48
Core Reject Duplicates																					
937064	Drill Core	7.11	8.1	87.6	193.1	751	1.1	55.7	7.7	638	2.06	144.1	3.1	0.7	3.0	15	6.6	4.5	0.8	130	0.80
DUP 937064	QC		9.2	90.8	221.6	754	1.2	57.3	8.1	689	2.20	148.8	3.4	0.8	3.0	17	7.1	4.8	0.8	136	0.87
Reference Materials																					
STD DS7	Standard		20.1	104.2	68.8	392	0.8	53.8	8.8	650	2.44	46.8	4.9	72.9	4.5	71	5.4	5.1	4.0	83	0.99
STD DS7	Standard		20.2	108.9	68.2	404	0.8	55.1	9.0	635	2.45	48.4	4.7	64.0	4.4	72	6.0	5.2	4.0	83	1.00
STD DS7	Standard		20.4	106.8	66.6	392	0.8	59.0	9.8	613	2.45	51.5	4.5	66.4	4.2	71	6.1	5.4	4.4	80	0.95
STD DS7	Standard		20.1	106.3	65.6	378	0.8	53.1	9.1	603	2.41	50.1	4.6	62.6	4.2	66	5.7	5.1	4.3	77	0.96
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.2	13.1	2.4	46	<0.1	4.2	4.5	551	1.98	0.7	1.6	1.5	3.7	62	<0.1	0.1	0.1	37	0.53
G1	Prep Blank		0.1	7.6	2.1	45	<0.1	3.4	4.1	543	1.82	<0.5	1.4	<0.5	3.4	53	<0.1	<0.1	<0.1	35	0.52

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

QUALITY CONTROL REPORT SMI09000286.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
937057	Drill Core	0.026	21	8	0.22	37	0.036	1	0.59	0.024	0.27	0.2	<0.01	1.7	0.2	0.17	3	<0.5
REP 937057	QC	0.026	21	8	0.21	38	0.036	2	0.57	0.023	0.27	0.2	<0.01	1.7	0.2	0.17	3	<0.5
Core Reject Duplicates																		
937064	Drill Core	0.126	9	52	0.52	116	0.029	2	0.67	0.011	0.26	0.2	<0.01	3.3	0.3	0.88	4	5.4
DUP 937064	QC	0.136	9	55	0.55	116	0.030	2	0.74	0.013	0.28	0.2	<0.01	3.8	0.3	0.91	4	6.6
Reference Materials																		
STD DS7	Standard	0.076	13	218	1.06	414	0.124	40	1.07	0.101	0.45	3.6	0.19	2.3	4.1	0.19	5	3.7
STD DS7	Standard	0.077	13	219	1.05	408	0.126	39	1.07	0.100	0.45	3.7	0.16	2.3	4.4	0.19	5	3.6
STD DS7	Standard	0.079	12	225	1.05	406	0.107	36	1.03	0.096	0.45	3.8	0.18	2.2	4.3	0.19	5	4.0
STD DS7	Standard	0.074	13	221	1.01	394	0.112	38	1.03	0.096	0.45	3.7	0.19	2.3	4.0	0.19	5	3.5
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.084	7	9	0.59	259	0.118	2	0.95	0.071	0.54	0.1	<0.01	1.8	0.3	<0.05	5	<0.5
G1	Prep Blank	0.080	6	8	0.56	247	0.113	2	0.88	0.056	0.52	<0.1	<0.01	1.7	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: September 26, 2009
Report Date: October 08, 2009
Page: 1 of 3

CERTIFICATE OF ANALYSIS SMI09000288.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC-CO-09-01
P.O. Number
Number of Samples: 50

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200	48	Crush split and pulverize 250g drill core to 200 mesh			VAN
1DX15	50	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000288.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937001	Drill Core	9.62	0.8	12.5	10.4	68	0.2	10.4	5.1	388	1.80	64.9	5.5	3.1	21.5	12	0.3	1.9	0.3	28	0.34
937002	Drill Core	9.93	2.1	16.5	10.2	67	0.1	9.7	5.0	422	1.73	37.1	4.8	13.2	21.0	12	0.1	0.8	0.3	24	0.31
937003	Drill Core	7.81	5.0	3.4	10.5	60	0.2	3.9	3.0	445	1.23	71.9	4.2	7.7	24.5	8	0.2	2.0	1.9	15	0.10
937004	Drill Core	9.12	2.1	9.8	28.5	145	0.3	19.1	5.2	1127	1.69	317.0	6.4	13.7	21.1	8	0.5	13.5	0.3	5	0.12
937005	Drill Core	8.82	1.0	18.7	109.6	120	0.3	5.7	4.7	439	1.71	7.7	4.5	<0.5	19.1	23	1.8	4.9	0.1	16	0.63
937006	Drill Core	9.82	0.7	4.5	47.9	57	<0.1	5.2	5.2	399	1.82	4.0	5.1	<0.5	16.4	15	0.2	0.4	0.2	21	0.42
937007	Drill Core	9.85	0.6	9.6	21.5	58	0.2	5.0	5.2	420	1.85	6.4	6.4	3.5	15.6	11	0.4	0.4	0.8	20	0.40
937008	Drill Core	7.46	1.0	1.2	10.9	49	<0.1	3.8	4.5	559	1.77	4.1	6.3	<0.5	16.3	16	<0.1	0.7	0.2	20	0.47
937009	Drill Core	10.63	6.9	1.6	11.1	30	<0.1	2.8	2.8	326	1.17	4.7	9.6	<0.5	16.1	12	<0.1	0.5	0.1	11	0.35
937010	Drill Core	8.70	1.8	7.5	47.9	68	0.6	1.9	2.6	824	1.40	357.2	10.0	22.2	18.8	34	0.3	3.1	4.2	3	1.00
937011	Drill Core	10.99	0.6	5.0	10.4	47	0.2	4.5	4.4	519	1.95	21.9	4.6	0.9	12.3	20	<0.1	1.1	1.3	15	0.58
937012	Drill Core	10.21	4.4	4.4	26.6	50	0.2	1.3	1.3	491	0.79	63.7	8.8	3.1	22.9	26	0.3	1.8	0.3	<2	0.69
937013	Drill Core	8.89	2.2	3.8	24.5	42	0.2	0.9	1.3	367	0.74	112.6	9.3	7.9	23.1	22	0.3	1.2	0.2	<2	0.53
937014	Drill Core	10.10	3.2	11.3	47.0	77	0.3	1.2	1.6	557	0.89	68.3	10.9	3.8	21.0	17	0.4	1.6	0.4	<2	0.52
937015	Drill Core	10.43	1.1	11.2	16.4	36	0.2	1.5	2.2	496	1.08	138.1	8.5	6.1	20.7	19	0.3	1.8	0.2	3	0.52
937016	Drill Core	9.72	1.1	11.7	17.2	41	0.1	3.2	3.2	580	1.38	72.5	7.1	5.0	15.5	21	0.2	0.9	0.3	8	0.53
937017	Drill Core	8.54	1.3	10.7	8.5	38	<0.1	1.9	3.0	379	1.37	5.0	6.7	3.0	17.6	12	<0.1	0.4	0.2	10	0.31
937018	Drill Core	10.20	1.9	12.6	17.8	49	0.2	2.3	3.1	485	1.36	91.8	8.5	8.5	21.5	26	0.2	2.2	0.2	6	0.72
937019	Drill Core	10.25	0.9	9.2	10.7	52	<0.1	2.2	3.4	376	1.54	30.0	6.0	4.1	24.0	17	0.1	1.0	0.1	12	0.45
937020	Rock Pulp	0.12	6.6	53.8	16.9	98	1.8	16.0	7.6	139	2.95	335.8	0.1	827.9	0.4	5	0.2	26.8	0.2	15	0.18
937021	Drill Core	10.30	2.3	9.9	8.4	50	<0.1	2.5	3.8	404	1.58	2.8	6.0	<0.5	20.1	16	<0.1	0.7	0.1	17	0.40
937022	Drill Core	10.14	1.0	7.4	10.9	44	<0.1	1.9	4.6	436	1.75	4.9	6.6	1.3	23.9	21	<0.1	0.9	<0.1	26	0.55
937023	Drill Core	3.25	1.8	4.9	9.7	56	0.2	2.5	7.2	1256	3.06	16.3	5.7	1.1	29.7	71	0.2	2.9	0.4	31	2.75
937024	Drill Core	9.90	2.2	11.5	10.2	45	0.2	2.1	6.7	559	2.31	22.4	3.9	7.2	16.8	30	<0.1	1.0	1.2	53	0.73
937025	Drill Core	9.77	2.4	11.1	10.4	22	<0.1	0.8	1.5	222	0.84	20.4	7.4	1.6	24.6	16	<0.1	2.4	0.1	6	0.44
937026	Drill Core	10.00	3.8	13.5	21.6	33	0.4	2.0	2.4	341	1.13	49.8	7.2	6.8	21.7	23	0.2	7.2	0.6	4	0.62
937027	Drill Core	9.52	4.5	9.5	13.4	39	0.1	1.3	1.7	263	0.94	67.1	7.9	3.0	20.9	19	<0.1	3.9	0.3	4	0.53
937028	Drill Core	9.61	1.3	13.0	10.0	35	<0.1	2.2	2.9	348	1.34	9.7	5.9	5.2	17.7	14	<0.1	10.6	0.5	11	0.43
937029	Drill Core	8.08	1.3	6.5	19.3	47	0.1	2.9	3.2	408	1.49	2.0	5.7	2.7	19.0	17	0.1	0.4	0.1	13	0.47
937030	Drill Core	10.02	3.8	3.1	8.7	25	<0.1	1.5	1.7	366	0.92	2.9	6.2	0.9	19.0	15	<0.1	1.0	<0.1	7	0.49

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000288.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937001	Drill Core	0.048	41	22	0.40	65	0.104	<1	0.74	0.037	0.42	1.1	<0.01	3.8	0.3	<0.05	5	<0.5
937002	Drill Core	0.050	38	18	0.31	65	0.060	1	0.74	0.043	0.28	0.4	<0.01	3.2	0.2	<0.05	4	<0.5
937003	Drill Core	0.022	29	7	0.16	104	0.018	1	0.51	0.039	0.18	0.1	<0.01	1.9	0.1	<0.05	2	<0.5
937004	Drill Core	0.041	34	9	0.03	164	<0.001	1	0.39	0.005	0.17	0.2	0.02	1.5	0.2	<0.05	1	<0.5
937005	Drill Core	0.042	35	17	0.44	71	0.041	<1	0.95	0.033	0.25	0.2	<0.01	2.5	0.2	<0.05	6	<0.5
937006	Drill Core	0.042	27	21	0.67	81	0.138	<1	1.06	0.050	0.65	0.2	<0.01	4.0	0.5	<0.05	6	<0.5
937007	Drill Core	0.036	21	19	0.60	53	0.131	<1	1.01	0.047	0.57	0.4	<0.01	3.9	0.5	<0.05	6	<0.5
937008	Drill Core	0.035	22	17	0.57	89	0.089	<1	0.95	0.039	0.50	<0.1	<0.01	3.2	0.5	<0.05	6	<0.5
937009	Drill Core	0.020	17	15	0.33	41	0.075	1	0.59	0.041	0.40	0.1	<0.01	2.4	0.4	<0.05	4	<0.5
937010	Drill Core	0.019	13	9	0.35	60	0.004	2	0.37	0.020	0.18	0.2	<0.01	1.0	0.2	0.37	1	<0.5
937011	Drill Core	0.035	22	14	0.47	50	0.060	1	0.70	0.036	0.33	0.4	<0.01	2.8	0.4	0.07	4	<0.5
937012	Drill Core	0.015	14	8	0.10	41	<0.001	1	0.30	0.016	0.16	<0.1	<0.01	0.5	0.2	0.11	<1	<0.5
937013	Drill Core	0.011	16	12	0.11	26	<0.001	2	0.22	0.023	0.15	<0.1	<0.01	0.5	0.1	0.13	<1	<0.5
937014	Drill Core	0.012	18	9	0.20	28	<0.001	1	0.30	0.023	0.14	<0.1	<0.01	0.8	0.1	0.15	<1	<0.5
937015	Drill Core	0.015	18	11	0.14	37	<0.001	<1	0.27	0.030	0.13	<0.1	<0.01	0.9	0.1	0.25	1	<0.5
937016	Drill Core	0.022	17	11	0.26	32	0.033	2	0.43	0.031	0.25	<0.1	<0.01	1.8	0.2	0.17	2	<0.5
937017	Drill Core	0.018	23	15	0.25	34	0.076	1	0.57	0.044	0.36	<0.1	<0.01	2.3	0.3	0.07	3	<0.5
937018	Drill Core	0.021	23	11	0.23	41	0.019	1	0.46	0.031	0.23	<0.1	<0.01	1.6	0.2	0.24	2	<0.5
937019	Drill Core	0.030	39	15	0.27	54	0.073	1	0.59	0.040	0.35	0.1	<0.01	2.6	0.3	0.08	3	<0.5
937020	Rock Pulp	0.038	7	29	0.08	26	0.002	1	0.34	0.004	0.21	0.6	3.41	1.2	3.8	1.99	2	10.0
937021	Drill Core	0.031	35	14	0.32	96	0.090	1	0.66	0.045	0.43	<0.1	<0.01	2.6	0.4	0.05	4	<0.5
937022	Drill Core	0.031	35	14	0.41	210	0.101	1	0.75	0.047	0.46	<0.1	<0.01	2.9	0.3	<0.05	4	<0.5
937023	Drill Core	0.040	37	8	0.80	257	0.043	2	1.14	0.024	0.40	0.8	<0.01	3.0	0.3	0.18	4	<0.5
937024	Drill Core	0.035	31	12	0.62	442	0.136	<1	1.22	0.086	0.58	1.2	<0.01	3.8	0.5	0.07	5	<0.5
937025	Drill Core	0.011	20	10	0.15	48	0.006	2	0.32	0.032	0.15	0.2	<0.01	0.8	0.1	0.07	1	<0.5
937026	Drill Core	0.022	19	11	0.17	27	0.002	<1	0.32	0.028	0.12	<0.1	0.01	1.2	0.1	0.17	2	<0.5
937027	Drill Core	0.014	18	11	0.16	24	0.011	1	0.43	0.034	0.17	0.2	<0.01	1.2	0.1	0.13	2	<0.5
937028	Drill Core	0.025	23	13	0.27	38	0.046	<1	0.54	0.036	0.25	0.1	<0.01	2.3	0.3	0.14	3	<0.5
937029	Drill Core	0.030	30	15	0.30	39	0.068	<1	0.55	0.042	0.33	<0.1	<0.01	2.7	0.3	0.09	4	<0.5
937030	Drill Core	0.015	18	12	0.20	39	0.033	2	0.41	0.040	0.22	<0.1	<0.01	1.3	0.1	<0.05	2	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000288.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937031	Drill Core	5.18	6.2	5.6	9.5	31	<0.1	1.6	3.8	538	1.44	2.8	6.0	<0.5	15.1	59	<0.1	4.4	0.1	25	1.66
937032	Drill Core	7.37	1.1	12.0	13.9	43	<0.1	3.0	5.0	461	1.89	6.9	6.1	0.7	24.4	43	<0.1	4.9	0.2	27	0.67
937033	Drill Core	11.63	1.3	8.6	11.2	32	<0.1	3.0	3.8	495	1.54	24.1	7.3	5.1	19.4	38	0.1	5.6	0.3	16	0.80
937034	Drill Core	9.13	1.5	18.5	59.0	78	0.5	2.2	2.6	1215	1.22	159.0	9.4	12.8	21.6	29	0.5	12.4	0.5	3	0.80
937035	Drill Core	9.00	1.5	24.0	11.8	35	0.1	2.9	3.3	390	1.62	5.5	9.4	<0.5	25.6	46	<0.1	4.8	0.4	10	0.63
937036	Drill Core	4.74	1.1	21.9	26.7	52	0.9	2.9	3.2	584	1.89	69.6	9.8	4.4	22.2	29	0.3	3.2	5.8	9	0.76
937037	Drill Core	1.55	1.1	42.0	12.1	26	0.4	3.1	4.2	287	1.62	2.4	9.0	207.7	20.4	20	<0.1	3.8	57.0	11	0.40
937038	Drill Core	8.99	1.9	7.6	8.3	34	<0.1	2.9	2.7	335	1.35	1.8	8.5	0.6	23.8	19	<0.1	1.7	0.5	13	0.39
937039	Drill Core	9.58	58.6	10.0	7.1	25	<0.1	2.8	2.5	255	1.21	0.8	9.5	3.8	23.3	12	<0.1	0.6	0.4	12	0.24
937040	Rock Pulp	0.12	6.5	58.9	19.9	103	1.9	14.8	7.8	156	3.07	339.4	0.1	866.5	0.5	6	0.3	35.2	0.3	14	0.17
937041	Drill Core	9.94	1.0	7.7	7.6	31	<0.1	3.4	2.7	319	1.36	1.7	8.4	<0.5	23.9	16	<0.1	1.3	<0.1	12	0.33
937042	Drill Core	5.48	9.2	11.4	7.8	33	0.2	2.6	3.0	325	1.41	2.9	7.8	<0.5	25.9	18	<0.1	0.9	1.7	12	0.51
937043	Drill Core	8.18	13.1	14.5	11.4	39	0.3	2.2	4.1	503	1.69	37.3	7.2	2.3	23.7	35	<0.1	2.1	1.6	19	0.99
937044	Drill Core	9.18	8.0	8.3	11.1	35	0.1	2.6	3.1	372	1.40	30.4	7.1	4.2	25.1	30	<0.1	1.5	0.9	10	0.67
937045	Drill Core	6.76	12.2	21.1	6.1	52	<0.1	11.3	5.7	437	2.29	3.3	4.6	8.8	19.9	27	<0.1	2.0	6.1	48	0.57
937046	Drill Core	5.73	6.0	36.1	158.0	269	1.1	13.7	7.0	3659	2.41	491.2	3.9	17.5	5.4	48	2.0	12.1	0.7	23	1.61
937047	Drill Core	10.04	12.3	109.5	171.5	550	1.8	75.6	5.3	1991	1.96	85.9	4.8	9.1	3.6	46	5.4	21.1	1.9	64	1.44
937048	Drill Core	10.28	13.6	89.5	53.8	328	0.9	58.8	11.0	1747	2.99	261.4	5.1	17.3	2.9	59	3.1	11.1	1.8	103	1.57
937049	Drill Core	10.40	2.9	75.7	12.0	99	0.4	46.0	12.7	598	3.33	62.9	2.9	7.0	5.5	44	0.3	1.4	0.6	96	0.85
937050	Drill Core	6.68	4.2	80.8	6.9	54	<0.1	27.7	8.6	425	2.47	18.4	5.4	6.3	15.7	29	<0.1	0.6	2.1	92	0.64

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

CERTIFICATE OF ANALYSIS SMI09000288.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937031	Drill Core	0.027	19	8	0.42	254	0.061	1	0.80	0.028	0.33	0.1	<0.01	2.1	0.2	<0.05	3	<0.5
937032	Drill Core	0.037	32	14	0.44	172	0.095	1	0.82	0.042	0.43	0.1	<0.01	3.1	0.3	0.06	3	<0.5
937033	Drill Core	0.030	24	10	0.31	78	0.043	2	0.58	0.035	0.31	0.2	<0.01	2.2	0.3	0.11	2	<0.5
937034	Drill Core	0.023	16	6	0.18	236	0.002	2	0.47	0.009	0.20	0.2	0.02	0.9	0.4	0.58	1	<0.5
937035	Drill Core	0.029	30	8	0.30	126	0.035	2	0.68	0.030	0.25	0.2	<0.01	2.2	0.3	0.13	3	<0.5
937036	Drill Core	0.027	28	9	0.29	42	0.041	2	0.52	0.023	0.30	0.2	<0.01	1.9	0.3	0.33	2	<0.5
937037	Drill Core	0.024	27	11	0.28	48	0.052	1	0.62	0.036	0.28	0.2	<0.01	2.1	0.3	0.27	3	<0.5
937038	Drill Core	0.023	30	13	0.31	52	0.082	<1	0.67	0.041	0.39	0.5	<0.01	2.3	0.3	<0.05	3	<0.5
937039	Drill Core	0.019	27	12	0.28	46	0.071	<1	0.62	0.053	0.36	0.2	<0.01	2.1	0.3	0.09	3	<0.5
937040	Rock Pulp	0.038	7	29	0.08	25	0.002	2	0.32	0.004	0.21	0.6	3.59	1.2	4.0	2.04	1	9.8
937041	Drill Core	0.021	30	15	0.30	59	0.080	<1	0.66	0.050	0.37	0.3	<0.01	2.3	0.3	0.09	3	<0.5
937042	Drill Core	0.025	31	13	0.31	34	0.054	<1	0.68	0.046	0.29	0.7	<0.01	2.1	0.2	0.07	3	<0.5
937043	Drill Core	0.029	25	13	0.41	96	0.036	2	0.69	0.031	0.27	<0.1	<0.01	2.1	0.2	0.10	3	<0.5
937044	Drill Core	0.026	31	12	0.27	43	0.032	1	0.64	0.037	0.28	<0.1	<0.01	1.8	0.2	0.07	3	<0.5
937045	Drill Core	0.036	36	26	0.56	205	0.135	<1	1.09	0.075	0.60	0.2	<0.01	4.8	0.6	0.18	4	0.6
937046	Drill Core	0.064	10	10	0.48	106	0.008	2	0.68	0.007	0.28	0.2	0.05	2.7	1.1	1.35	2	2.2
937047	Drill Core	0.257	10	29	0.31	133	0.002	3	0.33	0.002	0.15	0.4	0.05	1.6	1.3	1.18	1	14.0
937048	Drill Core	0.199	9	42	0.64	90	0.081	2	1.48	0.072	0.38	1.6	0.02	3.4	1.2	1.27	4	8.1
937049	Drill Core	0.060	10	75	1.14	125	0.113	2	1.43	0.056	0.60	1.0	<0.01	5.7	0.5	0.99	5	3.5
937050	Drill Core	0.096	21	48	0.70	282	0.124	1	1.11	0.061	0.58	0.6	<0.01	4.8	0.5	0.41	5	1.8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

QUALITY CONTROL REPORT SMI09000288.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
937014	Drill Core	10.10	3.2	11.3	47.0	77	0.3	1.2	1.6	557	0.89	68.3	10.9	3.8	21.0	17	0.4	1.6	0.4	<2	0.52
REP 937014	QC		3.5	11.3	44.2	74	0.3	1.1	1.3	545	0.89	64.9	10.4	4.1	20.2	17	0.5	1.5	0.3	<2	0.51
937044	Drill Core	9.18	8.0	8.3	11.1	35	0.1	2.6	3.1	372	1.40	30.4	7.1	4.2	25.1	30	<0.1	1.5	0.9	10	0.67
REP 937044	QC		7.2	7.8	10.8	34	<0.1	3.1	2.7	352	1.33	27.0	6.7	2.8	23.8	29	0.1	1.4	0.9	9	0.65
Core Reject Duplicates																					
937011	Drill Core	10.99	0.6	5.0	10.4	47	0.2	4.5	4.4	519	1.95	21.9	4.6	0.9	12.3	20	<0.1	1.1	1.3	15	0.58
DUP 937011	QC		0.5	5.3	11.2	47	0.2	5.1	4.5	516	1.82	22.0	4.8	1.7	13.5	22	0.1	1.2	1.4	14	0.55
937046	Drill Core	5.73	6.0	36.1	158.0	269	1.1	13.7	7.0	3659	2.41	491.2	3.9	17.5	5.4	48	2.0	12.1	0.7	23	1.61
DUP 937046	QC		7.2	37.9	169.9	283	1.3	16.1	7.7	3743	2.54	494.4	4.2	21.2	5.7	50	2.1	12.8	0.7	27	1.66
Reference Materials																					
STD DS7	Standard		20.1	104.2	68.8	392	0.8	53.8	8.8	650	2.44	46.8	4.9	72.9	4.5	71	5.4	5.1	4.0	83	0.99
STD DS7	Standard		20.2	108.9	68.2	404	0.8	55.1	9.0	635	2.45	48.4	4.7	64.0	4.4	72	6.0	5.2	4.0	83	1.00
STD DS7	Standard		19.7	110.0	74.0	392	0.8	56.7	9.2	630	2.50	49.4	5.3	55.4	4.7	81	5.9	6.3	4.8	81	0.98
STD DS7	Standard		18.9	98.7	67.6	351	0.7	52.1	8.6	566	2.28	46.8	4.7	56.4	4.5	74	5.7	6.0	4.5	74	0.89
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.1	2.2	3.6	58	<0.1	3.6	4.4	552	2.02	60.3	1.6	2.6	3.7	58	0.2	0.5	0.2	40	0.54
G1	Prep Blank		0.1	2.0	2.7	51	<0.1	4.0	4.4	589	1.93	4.8	1.9	<0.5	3.8	57	<0.1	0.2	<0.1	38	0.50

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 08, 2009

QUALITY CONTROL REPORT SMI09000288.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
937014	Drill Core	0.012	18	9	0.20	28	<0.001	1	0.30	0.023	0.14	<0.1	<0.01	0.8	0.1	0.15	<1	<0.5
REP 937014	QC	0.012	16	9	0.19	26	<0.001	<1	0.28	0.023	0.13	<0.1	<0.01	0.8	<0.1	0.15	<1	<0.5
937044	Drill Core	0.026	31	12	0.27	43	0.032	1	0.64	0.037	0.28	<0.1	<0.01	1.8	0.2	0.07	3	<0.5
REP 937044	QC	0.025	29	11	0.27	41	0.031	1	0.63	0.036	0.26	<0.1	<0.01	1.6	0.1	0.07	3	<0.5
Core Reject Duplicates																		
937011	Drill Core	0.035	22	14	0.47	50	0.060	1	0.70	0.036	0.33	0.4	<0.01	2.8	0.4	0.07	4	<0.5
DUP 937011	QC	0.039	23	14	0.44	52	0.061	1	0.67	0.034	0.34	0.4	<0.01	2.8	0.4	0.06	4	<0.5
937046	Drill Core	0.064	10	10	0.48	106	0.008	2	0.68	0.007	0.28	0.2	0.05	2.7	1.1	1.35	2	2.2
DUP 937046	QC	0.066	11	12	0.50	128	0.010	2	0.77	0.009	0.32	0.2	0.05	2.8	1.2	1.38	2	2.0
Reference Materials																		
STD DS7	Standard	0.076	13	218	1.06	414	0.124	40	1.07	0.101	0.45	3.6	0.19	2.3	4.1	0.19	5	3.7
STD DS7	Standard	0.077	13	219	1.05	408	0.126	39	1.07	0.100	0.45	3.7	0.16	2.3	4.4	0.19	5	3.6
STD DS7	Standard	0.074	13	226	1.04	414	0.120	41	1.05	0.098	0.46	4.0	0.19	2.3	4.0	0.19	4	3.6
STD DS7	Standard	0.071	12	204	0.96	380	0.114	38	0.96	0.090	0.43	3.6	0.18	2.0	3.7	0.18	4	3.6
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.082	7	16	0.60	246	0.124	<1	1.04	0.088	0.52	0.1	<0.01	1.9	0.4	<0.05	6	<0.5
G1	Prep Blank	0.090	8	11	0.58	256	0.129	<1	0.97	0.067	0.55	0.2	<0.01	1.9	0.5	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: September 29, 2009
Report Date: October 13, 2009
Page: 1 of 3

CERTIFICATE OF ANALYSIS SMI09000298.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC-CO-09-05
P.O. Number
Number of Samples: 57

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200	54	Crush split and pulverize 250g drill core to 200 mesh			VAN
1DX15	57	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000298.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937205	Drill Core	10.59	0.6	6.3	10.2	27	0.1	5.9	4.3	257	1.74	14.7	7.7	2.8	18.9	26	0.1	1.0	0.3	14	0.58
937206	Drill Core	9.73	0.3	2.7	6.9	17	<0.1	2.7	2.1	175	0.96	7.7	6.1	2.1	16.9	19	<0.1	0.7	0.2	4	0.54
937207	Drill Core	10.88	0.6	5.3	5.7	30	<0.1	4.8	5.6	293	1.92	7.5	6.4	3.9	16.4	16	<0.1	0.4	0.4	17	0.43
937208	Drill Core	10.32	0.4	5.0	4.3	16	<0.1	3.7	4.3	187	1.29	9.3	6.2	3.6	15.3	13	<0.1	0.5	0.3	10	0.45
937209	Drill Core	9.22	0.5	3.3	3.4	14	<0.1	3.6	3.2	203	1.40	7.5	6.0	1.5	14.7	16	<0.1	0.4	0.3	11	0.45
937210	Drill Core	10.81	0.3	2.7	4.6	12	<0.1	3.3	1.7	163	1.01	5.1	5.9	1.7	16.8	17	<0.1	0.5	0.3	6	0.42
937211	Drill Core	3.91	0.9	10.5	8.1	26	<0.1	4.1	3.8	183	1.50	12.2	4.5	1.4	16.4	7	<0.1	1.9	0.5	12	0.26
937212	Drill Core	6.60	0.7	34.8	10.0	29	0.3	5.1	5.8	204	1.63	38.0	4.9	5.3	14.9	12	<0.1	2.3	4.6	13	0.30
937213	Drill Core	4.21	0.7	6.4	9.4	25	<0.1	4.3	4.9	271	1.54	30.2	2.6	3.7	17.1	18	<0.1	1.1	4.4	8	0.49
937214	Drill Core	8.36	0.4	13.8	6.1	35	<0.1	5.2	5.4	323	2.00	10.0	3.7	2.0	17.8	12	<0.1	1.0	0.5	19	0.42
937215	Drill Core	8.86	0.3	23.1	6.1	24	<0.1	3.7	4.5	199	1.49	14.3	5.5	3.5	19.0	14	<0.1	1.2	0.6	13	0.44
937216	Drill Core	9.17	0.4	6.1	6.9	24	<0.1	3.9	5.0	252	1.64	4.4	6.1	0.7	21.6	40	<0.1	0.8	0.6	14	0.54
937217	Drill Core	5.15	0.4	7.9	8.1	27	<0.1	4.5	5.1	302	1.85	3.0	4.0	1.3	17.4	66	<0.1	0.5	0.8	16	0.58
937218	Drill Core	6.14	0.4	4.7	10.7	23	0.1	4.0	5.0	982	1.24	92.0	4.8	12.7	15.5	25	<0.1	0.8	1.6	5	2.07
937219	Drill Core	10.10	0.3	6.9	7.1	33	<0.1	4.9	5.2	325	1.87	2.3	3.2	1.6	16.4	25	<0.1	0.5	0.4	19	0.56
937220	Rock Pulp	0.04	2.8	38.4	19.5	76	0.2	24.9	10.3	731	3.61	6.0	0.3	0.5	1.1	30	0.2	0.4	0.1	55	0.68
937221	Drill Core	7.95	0.3	17.2	9.7	27	0.1	4.3	4.5	324	1.61	28.2	6.2	7.3	20.3	23	<0.1	1.2	1.0	13	0.94
937222	Drill Core	7.36	1.0	6.9	7.9	25	<0.1	4.2	2.8	261	1.72	18.4	6.7	2.5	19.8	18	<0.1	0.7	0.5	8	0.56
937223	Drill Core	5.30	0.5	67.1	8.8	23	0.2	4.1	4.1	243	1.40	970.5	5.2	49.7	13.9	25	<0.1	2.7	1.6	3	1.21
937224	Drill Core	8.92	0.2	29.7	7.2	32	0.1	3.5	4.9	360	1.99	18.2	4.3	5.8	12.5	54	<0.1	1.9	0.6	19	0.97
937225	Drill Core	10.26	0.3	28.3	4.9	36	0.1	4.3	6.1	367	2.06	24.7	3.4	5.2	11.5	48	<0.1	0.8	1.5	21	0.86
937226	Drill Core	9.03	0.3	11.1	7.9	39	<0.1	4.4	5.3	345	1.78	6.7	3.8	1.8	18.1	26	<0.1	0.7	0.6	18	0.77
937227	Drill Core	7.05	0.4	8.7	4.6	32	<0.1	4.0	5.0	315	1.75	2.5	3.7	0.9	19.2	51	<0.1	0.8	0.6	17	0.58
937228	Drill Core	4.67	0.5	24.3	8.0	30	0.2	6.4	6.6	409	1.86	31.3	7.3	3.8	25.4	68	<0.1	1.5	1.1	12	1.28
937229	Drill Core	4.33	0.5	18.8	5.6	23	0.1	4.7	5.3	367	1.63	18.5	5.2	2.6	18.6	40	<0.1	1.6	1.1	11	0.92
937230	Drill Core	5.04	0.3	6.5	6.2	45	<0.1	6.3	5.5	373	1.83	2.6	6.2	0.9	24.2	20	0.1	0.8	0.3	18	0.37
937231	Drill Core	7.87	0.3	44.4	14.6	21	0.2	4.0	3.6	117	2.12	71.2	4.8	36.1	14.3	22	0.2	2.1	3.2	6	0.11
937232	Drill Core	9.02	0.6	33.6	7.8	18	0.2	4.2	3.9	29	2.23	92.2	4.3	42.9	16.4	14	0.1	2.4	3.3	2	0.04
937233	Drill Core	7.82	1.7	43.3	7.6	8	0.2	4.0	5.6	26	2.82	180.7	4.5	71.9	16.9	32	<0.1	2.4	3.8	3	0.03
937234	Drill Core	2.49	2.8	56.4	18.2	5	0.3	4.4	5.8	28	5.79	329.5	2.9	117.6	13.0	19	<0.1	2.9	5.6	4	0.03

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000298.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937205	Drill Core	0.031	31	16	0.42	41	0.038	<1	1.03	0.040	0.29	0.1	<0.01	2.9	0.2	0.12	6	<0.5
937206	Drill Core	0.016	28	11	0.21	22	0.004	1	0.58	0.029	0.16	<0.1	<0.01	1.2	0.1	0.06	3	<0.5
937207	Drill Core	0.030	25	19	0.53	64	0.085	2	1.04	0.062	0.47	4.7	<0.01	3.6	0.3	0.23	6	<0.5
937208	Drill Core	0.022	22	13	0.33	34	0.033	<1	0.71	0.052	0.22	0.1	<0.01	2.0	0.1	0.17	5	<0.5
937209	Drill Core	0.027	26	15	0.37	32	0.029	<1	0.73	0.045	0.23	0.1	<0.01	2.6	0.2	0.10	5	<0.5
937210	Drill Core	0.013	28	12	0.30	21	0.011	1	0.64	0.048	0.19	<0.1	<0.01	1.7	0.1	<0.05	5	<0.5
937211	Drill Core	0.035	45	11	0.29	28	0.016	1	1.18	0.019	0.21	<0.1	<0.01	2.7	0.2	<0.05	5	<0.5
937212	Drill Core	0.038	25	13	0.29	75	0.031	<1	1.07	0.025	0.33	<0.1	<0.01	2.6	0.3	0.13	5	<0.5
937213	Drill Core	0.040	38	9	0.18	81	0.009	1	0.78	0.021	0.23	<0.1	<0.01	1.6	0.2	0.40	3	<0.5
937214	Drill Core	0.037	34	20	0.64	64	0.057	7	1.12	0.047	0.33	<0.1	<0.01	3.8	0.2	0.08	6	<0.5
937215	Drill Core	0.033	35	14	0.32	44	0.023	<1	0.99	0.036	0.23	0.1	<0.01	2.6	0.2	0.11	4	<0.5
937216	Drill Core	0.037	33	15	0.43	94	0.021	<1	1.22	0.039	0.22	<0.1	<0.01	3.1	0.2	0.07	5	<0.5
937217	Drill Core	0.035	31	16	0.54	161	0.023	<1	1.34	0.045	0.20	<0.1	<0.01	3.2	0.2	0.09	6	<0.5
937218	Drill Core	0.040	46	7	0.11	36	<0.001	2	0.62	0.015	0.17	0.1	<0.01	1.0	0.2	0.71	2	<0.5
937219	Drill Core	0.040	35	21	0.53	78	0.093	1	1.00	0.054	0.47	0.4	<0.01	4.0	0.4	0.05	5	<0.5
937220	Rock Pulp	0.061	6	28	0.97	70	0.121	2	2.14	0.077	0.13	0.1	0.01	3.6	<0.1	<0.05	6	<0.5
937221	Drill Core	0.034	32	16	0.37	35	0.023	1	0.80	0.025	0.24	0.3	<0.01	2.7	0.1	0.19	4	<0.5
937222	Drill Core	0.028	26	9	0.24	36	0.005	1	0.93	0.012	0.19	0.4	0.01	1.9	0.1	0.10	3	<0.5
937223	Drill Core	0.039	18	7	0.12	73	<0.001	2	0.57	0.004	0.21	0.4	<0.01	0.8	0.1	0.46	2	<0.5
937224	Drill Core	0.039	20	12	0.49	325	0.065	1	1.33	0.103	0.34	2.5	<0.01	2.8	0.3	0.19	5	<0.5
937225	Drill Core	0.044	20	17	0.59	209	0.089	<1	1.21	0.059	0.46	11.8	<0.01	3.5	0.3	0.23	5	<0.5
937226	Drill Core	0.037	36	16	0.59	51	0.054	<1	1.13	0.032	0.42	0.1	<0.01	4.5	0.3	0.09	5	<0.5
937227	Drill Core	0.035	34	19	0.55	144	0.068	1	1.01	0.034	0.44	0.1	<0.01	4.4	0.2	<0.05	5	<0.5
937228	Drill Core	0.042	46	12	0.41	124	0.008	1	1.48	0.013	0.21	0.1	<0.01	3.0	0.3	0.25	5	<0.5
937229	Drill Core	0.041	37	10	0.34	60	0.011	<1	1.08	0.018	0.21	1.7	<0.01	2.8	0.2	0.25	4	<0.5
937230	Drill Core	0.035	38	16	0.50	70	0.080	<1	0.96	0.038	0.50	0.2	<0.01	4.1	0.3	<0.05	5	<0.5
937231	Drill Core	0.024	8	7	0.13	58	0.006	2	0.56	0.006	0.26	0.2	0.07	1.1	0.3	1.48	2	0.6
937232	Drill Core	0.013	9	8	0.02	58	<0.001	3	0.33	0.004	0.26	0.3	0.06	0.5	0.2	2.13	<1	<0.5
937233	Drill Core	0.015	8	11	0.01	40	<0.001	3	0.28	0.003	0.22	0.2	0.09	0.6	0.2	2.81	<1	<0.5
937234	Drill Core	0.013	6	7	0.01	21	<0.001	2	0.23	0.004	0.16	0.2	0.10	0.4	0.2	5.74	<1	1.6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000298.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937235	Drill Core	1.65	1.5	825.6	62.5	1254	13.5	6.8	9.4	24	29.38	790.5	4.9	531.1	15.7	21	12.8	94.2	183.9	2	0.02
937236	Drill Core	8.24	1.8	17.4	9.2	3	0.3	5.5	5.6	31	3.24	849.7	6.5	185.7	20.2	6	<0.1	2.2	4.7	2	0.03
937237	Drill Core	10.04	1.7	15.4	8.2	6	0.4	4.1	6.9	22	3.81	165.6	7.1	103.4	27.2	10	<0.1	2.1	7.8	3	0.04
937238	Drill Core	9.32	1.2	4.7	5.9	12	0.2	3.7	4.6	30	2.22	112.8	6.7	26.0	26.2	8	<0.1	1.9	6.4	2	0.09
937239	Drill Core	9.63	0.4	8.0	10.0	32	0.1	10.8	4.9	65	1.71	102.5	8.9	18.5	25.1	5	0.2	1.5	1.6	3	0.10
937240	Rock Pulp	0.08	473.7	3057	10.2	62	1.7	21.5	18.2	615	4.50	40.7	0.5	271.9	1.1	119	1.1	5.9	0.4	82	3.95
937241	Drill Core	8.20	0.3	10.2	8.2	27	0.1	7.3	4.1	262	1.97	67.4	7.0	8.7	25.3	13	<0.1	1.0	0.9	8	0.53
937242	Drill Core	8.63	0.8	29.4	12.9	22	0.2	2.5	2.5	123	1.08	60.1	7.1	7.6	30.2	10	0.2	1.3	1.0	2	0.36
937243	Drill Core	8.42	0.6	3.1	12.5	26	0.3	3.6	3.5	20	2.08	405.9	5.1	78.5	22.5	3	0.2	3.5	1.7	<2	0.06
937244	Drill Core	4.82	0.8	16.5	14.2	40	0.2	2.9	2.9	77	1.51	95.9	11.2	12.9	25.8	13	0.3	1.7	1.9	3	0.23
937245	Drill Core	8.66	0.7	33.6	14.9	29	0.1	6.5	4.5	571	2.32	41.1	7.6	7.0	24.9	24	<0.1	2.8	0.9	6	0.70
937246	Drill Core	8.33	0.5	12.7	4.8	24	<0.1	8.7	5.3	365	1.83	8.9	5.1	6.1	20.8	25	<0.1	1.3	0.3	20	0.83
937247	Drill Core	9.62	0.7	7.0	8.8	20	<0.1	2.9	3.3	176	1.26	30.0	5.7	7.8	18.6	34	<0.1	1.2	0.5	7	0.73
937248	Drill Core	8.84	0.7	12.8	13.1	28	0.1	2.5	2.2	121	0.77	26.0	9.3	3.5	27.2	23	0.1	1.0	0.4	2	0.50
937249	Drill Core	9.60	0.7	14.6	13.2	9	0.1	0.9	0.9	37	0.48	50.1	10.1	9.9	29.7	14	0.1	1.1	1.0	<2	0.16
937250	Drill Core	9.26	0.8	14.7	13.5	17	0.2	2.1	1.2	32	0.55	72.3	10.3	9.0	29.3	16	0.2	1.8	1.3	<2	0.16
937251	Drill Core	7.69	1.1	26.1	10.1	36	0.2	7.0	1.6	86	0.75	52.9	11.2	26.8	29.8	21	0.2	1.3	1.5	<2	0.20
937252	Drill Core	9.32	0.7	76.7	34.0	30	1.1	7.1	2.7	79	1.78	75.9	13.1	65.7	29.7	14	0.2	1.7	27.7	<2	0.12
937253	Drill Core	9.80	0.4	14.8	8.6	18	0.2	14.1	3.9	224	1.31	32.1	7.6	19.2	22.4	34	<0.1	1.0	3.1	3	0.64
937254	Drill Core	8.73	1.6	19.6	9.6	17	0.1	7.5	3.8	187	1.21	51.3	9.1	17.0	25.5	41	0.1	0.9	2.7	2	0.58
937255	Drill Core	5.78	0.8	128.0	11.2	40	0.3	2.6	2.6	83	1.28	90.3	4.6	43.6	19.6	7	0.5	1.7	4.1	<2	0.20
937256	Drill Core	4.02	2.0	56.5	13.3	21	0.5	3.0	2.2	20	2.35	96.2	7.6	67.9	23.3	6	0.2	1.7	14.8	<2	0.07
937257	Drill Core	7.28	0.7	39.2	10.2	24	0.2	3.0	2.0	104	0.98	41.1	7.1	27.1	21.7	45	0.2	1.3	3.7	<2	0.28
937258	Drill Core	8.81	0.6	32.1	4.5	6	0.3	3.3	0.9	46	1.62	15.3	1.5	175.1	10.6	12	<0.1	2.9	2.4	7	0.05
937259	Drill Core	8.13	0.5	28.6	32.2	2	0.5	2.7	0.5	24	2.25	47.3	1.6	193.0	14.9	32	<0.1	14.6	4.1	3	<0.01
937260	Rock Pulp	0.08	466.0	3011	9.5	62	1.6	20.7	17.2	641	4.32	42.1	0.5	225.4	1.0	128	0.8	5.5	0.3	79	3.99
937261	Drill Core	4.61	0.2	19.6	24.2	5	0.4	1.1	0.2	21	1.59	30.1	1.5	596.6	22.8	34	<0.1	16.2	3.7	4	0.02

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000298.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937235	Drill Core	0.014	7	4	<0.01	9	<0.001	3	0.15	0.002	0.08	0.2	1.02	0.7	0.4	>10	<1	26.9
937236	Drill Core	0.025	4	7	0.01	37	<0.001	2	0.29	0.003	0.20	0.2	0.09	0.5	0.2	3.26	<1	0.7
937237	Drill Core	0.029	6	7	0.01	40	<0.001	3	0.25	0.002	0.19	0.2	0.10	0.4	0.3	3.84	<1	0.8
937238	Drill Core	0.029	6	5	0.02	63	<0.001	3	0.34	0.003	0.26	0.3	0.05	0.4	0.2	2.16	<1	<0.5
937239	Drill Core	0.032	11	8	0.06	53	<0.001	3	0.54	0.003	0.24	0.4	0.03	0.6	0.3	1.38	1	<0.5
937240	Rock Pulp	0.098	8	24	1.24	77	0.006	4	1.35	0.075	0.19	2.9	0.16	6.5	<0.1	1.60	5	5.0
937241	Drill Core	0.036	37	10	0.28	26	0.002	1	1.02	0.014	0.13	0.1	0.01	1.5	0.1	0.45	3	<0.5
937242	Drill Core	0.029	24	8	0.15	30	<0.001	1	0.56	0.013	0.16	0.3	0.03	0.4	0.1	0.51	1	<0.5
937243	Drill Core	0.017	7	7	0.02	42	<0.001	3	0.28	0.002	0.21	0.4	0.08	0.3	0.3	2.06	<1	<0.5
937244	Drill Core	0.023	25	8	0.19	27	<0.001	1	0.83	0.001	0.15	0.3	0.05	0.8	0.2	0.47	2	<0.5
937245	Drill Core	0.028	28	9	0.34	37	<0.001	2	0.76	0.004	0.15	0.4	0.05	1.1	0.5	0.51	2	<0.5
937246	Drill Core	0.032	36	25	0.44	76	0.036	1	0.84	0.052	0.23	<0.1	<0.01	2.7	0.2	0.13	4	<0.5
937247	Drill Core	0.022	23	9	0.25	92	0.003	2	0.86	0.044	0.18	<0.1	<0.01	1.4	0.2	0.28	3	<0.5
937248	Drill Core	0.017	27	8	0.21	32	<0.001	1	0.51	0.021	0.13	0.1	<0.01	0.7	<0.1	0.26	1	<0.5
937249	Drill Core	<0.001	11	8	0.07	15	<0.001	1	0.36	0.028	0.11	<0.1	<0.01	0.4	<0.1	0.29	<1	<0.5
937250	Drill Core	0.001	10	10	0.08	27	<0.001	<1	0.39	0.015	0.13	<0.1	0.01	0.3	<0.1	0.38	<1	0.5
937251	Drill Core	0.011	13	7	0.09	41	<0.001	1	0.57	0.003	0.12	0.4	0.02	0.5	0.2	0.40	1	<0.5
937252	Drill Core	0.007	7	10	0.07	30	<0.001	1	0.41	0.005	0.16	0.2	0.01	0.4	<0.1	1.60	<1	<0.5
937253	Drill Core	0.019	15	11	0.22	36	0.001	1	0.48	0.019	0.15	0.1	<0.01	0.9	<0.1	0.81	1	<0.5
937254	Drill Core	0.022	18	9	0.22	43	<0.001	2	0.63	0.011	0.18	0.2	<0.01	0.7	<0.1	0.74	1	<0.5
937255	Drill Core	0.021	12	7	0.09	51	<0.001	3	0.34	0.004	0.24	0.7	0.01	0.4	0.1	1.10	<1	<0.5
937256	Drill Core	0.018	4	6	0.03	37	<0.001	2	0.25	0.004	0.18	0.8	<0.01	0.2	0.1	2.51	<1	1.2
937257	Drill Core	0.024	17	5	0.13	25	<0.001	1	0.58	0.003	0.11	0.5	<0.01	0.5	<0.1	0.77	<1	<0.5
937258	Drill Core	0.019	10	9	0.15	149	0.006	2	0.78	0.029	0.22	1.1	<0.01	1.1	0.2	0.11	3	1.0
937259	Drill Core	0.016	18	8	0.05	82	0.005	1	0.33	0.012	0.18	0.3	0.03	0.5	0.1	0.25	4	2.1
937260	Rock Pulp	0.108	7	23	1.24	51	0.006	3	1.28	0.075	0.19	2.8	0.15	6.1	<0.1	1.63	5	6.2
937261	Drill Core	0.025	12	5	0.06	136	<0.001	2	0.79	0.009	0.19	0.2	0.03	0.8	<0.1	0.07	3	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

QUALITY CONTROL REPORT SMI09000298.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
937247	Drill Core	9.62	0.7	7.0	8.8	20	<0.1	2.9	3.3	176	1.26	30.0	5.7	7.8	18.6	34	<0.1	1.2	0.5	7	0.73
REP 937247	QC		0.7	6.7	8.3	21	0.1	2.5	2.9	177	1.25	29.9	5.7	6.5	17.4	34	<0.1	1.1	0.5	7	0.72
937259	Drill Core	8.13	0.5	28.6	32.2	2	0.5	2.7	0.5	24	2.25	47.3	1.6	193.0	14.9	32	<0.1	14.6	4.1	3	<0.01
REP 937259	QC		0.5	27.2	31.5	2	0.5	2.5	0.4	24	2.24	47.7	1.4	1227	14.9	32	<0.1	14.4	4.0	3	0.01
Core Reject Duplicates																					
937214	Drill Core	8.36	0.4	13.8	6.1	35	<0.1	5.2	5.4	323	2.00	10.0	3.7	2.0	17.8	12	<0.1	1.0	0.5	19	0.42
DUP 937214	QC		0.5	14.3	5.6	32	<0.1	5.1	5.4	303	1.95	9.8	3.6	1.6	17.8	11	<0.1	1.2	0.5	18	0.40
937249	Drill Core	9.60	0.7	14.6	13.2	9	0.1	0.9	0.9	37	0.48	50.1	10.1	9.9	29.7	14	0.1	1.1	1.0	<2	0.16
DUP 937249	QC		0.6	14.6	14.3	10	0.1	0.9	1.0	45	0.51	53.9	10.7	11.3	34.1	15	<0.1	1.3	1.0	<2	0.15
Reference Materials																					
STD DS7	Standard		19.7	102.9	77.6	398	0.8	56.8	9.2	609	2.42	48.1	5.5	109.0	5.3	67	6.2	5.7	5.0	79	0.94
STD DS7	Standard		20.9	104.2	73.1	396	0.8	55.1	9.3	620	2.46	47.2	5.0	59.6	4.7	73	5.8	5.7	4.5	82	0.96
STD DS7	Standard		21.8	111.6	71.9	411	0.9	58.3	10.0	664	2.55	50.1	5.0	66.1	4.8	71	6.1	5.4	4.7	83	1.00
STD DS7	Standard		23.0	116.9	72.4	404	0.9	63.7	10.5	697	2.65	52.4	5.1	77.8	5.0	81	6.6	5.6	4.8	86	1.11
STD DS7	Standard		20.3	101.1	69.7	370	0.8	52.4	8.5	603	2.33	48.3	4.8	262.5	4.4	76	6.3	5.5	4.7	79	0.95
STD DS7	Standard		20.7	100.5	68.4	387	0.8	54.7	9.0	630	2.37	50.1	5.0	75.3	4.7	79	5.7	6.0	4.9	79	0.97
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	4.1	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.1	1.8	2.2	50	<0.1	4.1	4.9	608	2.07	<0.5	1.8	1.4	4.0	51	<0.1	<0.1	<0.1	39	0.53
G1	Prep Blank		0.1	1.7	2.4	48	<0.1	4.0	4.5	584	2.00	<0.5	1.8	0.7	4.1	54	<0.1	<0.1	<0.1	38	0.54

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

QUALITY CONTROL REPORT SMI09000298.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
937247	Drill Core	0.022	23	9	0.25	92	0.003	2	0.86	0.044	0.18	<0.1	<0.01	1.4	0.2	0.28	3	<0.5
REP 937247	QC	0.021	24	10	0.24	88	0.003	1	0.82	0.043	0.18	<0.1	<0.01	1.4	0.1	0.28	2	<0.5
937259	Drill Core	0.016	18	8	0.05	82	0.005	1	0.33	0.012	0.18	0.3	0.03	0.5	0.1	0.25	4	2.1
REP 937259	QC	0.016	17	8	0.05	79	0.005	2	0.32	0.011	0.18	0.3	0.02	0.5	0.1	0.25	3	1.9
Core Reject Duplicates																		
937214	Drill Core	0.037	34	20	0.64	64	0.057	7	1.12	0.047	0.33	<0.1	<0.01	3.8	0.2	0.08	6	<0.5
DUP 937214	QC	0.034	35	20	0.61	61	0.054	<1	1.09	0.042	0.31	<0.1	<0.01	3.7	0.2	0.08	6	<0.5
937249	Drill Core	<0.001	11	8	0.07	15	<0.001	1	0.36	0.028	0.11	<0.1	<0.01	0.4	<0.1	0.29	<1	<0.5
DUP 937249	QC	0.001	12	8	0.08	17	<0.001	2	0.41	0.030	0.13	<0.1	0.02	0.5	<0.1	0.29	<1	<0.5
Reference Materials																		
STD DS7	Standard	0.068	14	207	1.01	408	0.118	36	1.01	0.096	0.44	4.0	0.22	2.4	4.2	0.19	5	3.1
STD DS7	Standard	0.074	14	215	1.03	412	0.127	39	1.05	0.097	0.44	3.9	0.19	2.5	4.0	0.18	4	3.5
STD DS7	Standard	0.074	13	233	1.08	397	0.124	39	1.09	0.100	0.49	4.0	0.21	2.5	4.4	0.19	5	3.7
STD DS7	Standard	0.074	15	255	1.14	446	0.137	40	1.19	0.110	0.51	4.2	0.20	2.6	4.5	0.20	6	4.0
STD DS7	Standard	0.072	12	199	1.03	400	0.116	38	1.03	0.098	0.44	3.8	0.17	2.2	4.1	0.19	5	3.2
STD DS7	Standard	0.073	13	209	1.03	421	0.121	38	1.05	0.100	0.45	3.8	0.19	2.3	4.2	0.19	4	3.7
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.083	8	12	0.62	253	0.136	<1	1.07	0.085	0.58	<0.1	<0.01	1.9	0.4	<0.05	6	<0.5
G1	Prep Blank	0.082	8	13	0.61	252	0.135	<1	1.06	0.093	0.55	<0.1	<0.01	2.0	0.4	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: September 30, 2009
Report Date: October 13, 2009
Page: 1 of 6

CERTIFICATE OF ANALYSIS SMI09000301.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC-CO-09-06
P.O. Number
Number of Samples: 125

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200	119	Crush split and pulverize 250g drill core to 200 mesh			VAN
1DX15	125	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937262	Drill Core	9.09	0.6	25.4	58.1	3	2.7	1.9	0.7	22	1.62	58.1	0.9	540.6	11.6	43	<0.1	85.6	6.9	2	0.03
937263	Drill Core	8.78	0.6	11.9	11.2	3	0.6	3.5	3.0	21	2.83	55.2	0.7	146.3	6.9	29	<0.1	4.8	5.3	<2	0.02
937264	Drill Core	9.89	0.7	23.7	26.9	7	2.5	1.9	2.4	15	2.02	49.7	1.4	73.1	16.3	45	<0.1	20.2	4.1	<2	0.01
937265	Drill Core	8.03	0.7	95.9	20.5	14	0.7	1.1	1.1	20	0.96	20.4	2.1	34.2	22.7	119	0.1	34.4	1.3	<2	0.03
937266	Drill Core	9.77	0.4	387.2	8.2	33	0.3	4.1	5.8	309	2.24	22.3	12.8	80.9	12.3	19	0.3	10.9	1.2	<2	0.32
937267	Drill Core	9.48	0.4	77.2	4.1	20	<0.1	3.5	6.7	309	2.02	6.2	4.9	56.8	12.7	35	<0.1	1.7	1.3	17	1.05
937268	Drill Core	10.90	0.3	54.1	4.9	21	<0.1	7.1	5.6	256	1.96	7.3	4.2	26.9	15.4	18	<0.1	0.5	1.4	15	0.68
937269	Drill Core	10.48	0.3	67.1	6.2	15	<0.1	3.8	3.8	164	1.74	14.2	4.6	26.1	13.3	24	<0.1	0.4	1.4	8	0.83
937270	Drill Core	10.24	0.7	37.7	4.6	10	<0.1	6.0	3.6	130	1.96	27.2	5.5	39.6	16.3	22	<0.1	0.3	1.1	6	0.87
937271	Drill Core	10.06	1.1	41.2	4.0	14	<0.1	2.0	4.2	142	1.65	8.4	3.6	33.0	10.6	41	<0.1	0.3	0.8	10	1.16
937272	Drill Core	7.16	0.4	462.2	7.7	8	0.3	9.1	5.3	81	3.47	49.7	4.6	283.0	9.2	26	<0.1	1.0	2.1	3	1.35
937273	Drill Core	10.24	0.3	56.3	4.5	11	<0.1	1.6	4.0	124	1.44	8.0	3.7	55.2	11.5	46	<0.1	0.4	1.4	11	1.12
937274	Drill Core	10.45	1.2	119.7	3.6	16	0.1	5.3	6.5	151	2.28	5.6	3.2	76.9	10.5	33	<0.1	0.3	1.2	12	1.12
937275	Drill Core	9.88	0.3	78.0	4.5	21	0.1	1.8	3.9	167	1.46	17.2	3.7	31.5	12.4	41	<0.1	0.4	1.1	11	0.82
937276	Drill Core	8.42	0.8	59.2	6.3	18	0.1	1.9	5.0	198	2.32	25.1	4.8	64.4	12.3	40	<0.1	0.6	1.2	11	1.12
937277	Drill Core	8.86	0.5	34.1	7.9	23	0.1	3.0	4.7	208	0.49	5.5	6.0	16.0	12.3	35	<0.1	0.4	0.5	4	1.09
937278	Drill Core	9.50	0.7	17.5	3.4	16	<0.1	2.0	4.1	184	1.85	2.1	5.7	7.4	14.0	37	<0.1	0.3	0.4	12	1.17
937279	Drill Core	11.61	1.4	17.3	4.4	24	<0.1	3.9	4.5	222	1.83	1.6	4.5	10.5	17.4	33	<0.1	0.3	0.3	19	0.89
937280	Rock Pulp	0.08	494.7	3233	10.6	67	1.7	22.3	18.3	685	4.60	45.5	0.5	257.0	1.2	143	1.1	7.9	0.4	88	4.42
937281	Drill Core	8.68	0.8	11.4	3.3	18	<0.1	2.6	4.0	233	1.73	<0.5	3.6	5.7	15.1	48	<0.1	0.3	0.4	17	1.20
937282	Drill Core	10.20	1.6	19.3	5.8	12	<0.1	5.0	4.5	134	2.07	3.2	5.7	10.3	19.7	17	<0.1	1.1	0.9	7	0.84
937283	Drill Core	10.22	1.0	16.7	5.7	21	<0.1	7.1	4.5	203	1.87	2.6	7.1	5.0	18.2	14	<0.1	1.8	0.6	13	0.57
937284	Drill Core	10.18	0.5	22.7	6.3	15	<0.1	7.3	4.2	167	2.05	2.1	5.9	15.8	16.0	13	<0.1	0.4	0.6	11	0.59
937285	Drill Core	10.95	0.6	19.2	3.4	11	<0.1	7.1	4.2	143	2.21	3.2	4.0	18.8	18.7	11	<0.1	2.2	0.8	10	0.51
937286	Drill Core	9.26	0.5	33.7	6.4	13	0.1	9.2	5.2	303	6.55	47.3	5.6	121.7	17.6	20	<0.1	0.9	1.6	4	1.56
937287	Drill Core	9.41	0.4	228.9	9.9	16	0.2	14.4	6.7	185	2.46	3.3	5.8	221.7	18.1	16	<0.1	4.6	1.4	12	0.78
937288	Drill Core	7.07	0.6	113.7	6.7	19	<0.1	4.8	5.6	243	2.15	1.3	5.0	63.4	25.5	21	<0.1	4.7	0.6	25	0.92
937289	Drill Core	8.70	0.2	65.2	6.2	27	<0.1	12.8	6.5	340	2.39	5.9	5.7	23.1	15.5	28	<0.1	1.0	0.6	35	1.28
937290	Drill Core	9.97	0.3	109.0	4.5	21	<0.1	29.2	5.7	223	1.93	7.9	5.9	43.3	12.1	19	<0.1	1.1	0.5	21	0.82
937291	Drill Core	10.41	0.6	143.0	6.6	17	0.1	32.6	6.3	197	2.12	2.5	6.0	35.2	14.0	21	<0.1	0.4	0.9	19	0.80

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937262	Drill Core	0.014	12	5	0.02	85	<0.001	<1	0.38	0.006	0.23	0.1	0.10	0.3	0.1	0.94	2	1.0
937263	Drill Core	0.005	7	4	0.02	51	<0.001	2	0.29	0.004	0.27	0.9	0.02	0.2	0.1	2.64	<1	0.9
937264	Drill Core	0.007	8	5	0.01	53	<0.001	<1	0.25	0.003	0.23	0.8	0.03	0.1	0.1	2.04	<1	0.6
937265	Drill Core	0.014	13	4	0.01	54	<0.001	<1	0.29	0.003	0.18	0.1	0.05	0.3	<0.1	0.76	1	<0.5
937266	Drill Core	0.027	15	4	0.08	55	<0.001	<1	0.83	0.007	0.16	2.4	<0.01	0.7	0.1	1.75	1	<0.5
937267	Drill Core	0.044	19	7	0.37	118	0.028	<1	0.88	0.060	0.24	7.0	<0.01	2.3	0.1	0.94	3	<0.5
937268	Drill Core	0.031	28	11	0.40	76	0.035	<1	0.64	0.039	0.26	2.1	<0.01	2.1	0.2	0.83	3	<0.5
937269	Drill Core	0.021	15	8	0.25	79	0.006	<1	0.51	0.048	0.14	0.9	<0.01	0.9	<0.1	1.10	2	<0.5
937270	Drill Core	0.018	14	6	0.23	83	0.008	<1	0.52	0.038	0.15	0.2	<0.01	0.9	<0.1	1.52	2	<0.5
937271	Drill Core	0.027	18	5	0.27	139	0.011	<1	0.87	0.097	0.14	0.3	<0.01	1.8	<0.1	0.89	3	0.6
937272	Drill Core	0.033	15	4	0.11	18	<0.001	<1	0.51	0.035	0.16	0.3	<0.01	0.5	<0.1	3.36	1	1.5
937273	Drill Core	0.026	19	5	0.27	77	0.005	<1	0.81	0.091	0.10	0.8	<0.01	1.3	<0.1	0.76	3	<0.5
937274	Drill Core	0.051	22	12	0.49	50	0.026	<1	0.94	0.079	0.21	0.3	<0.01	1.9	0.1	1.31	4	<0.5
937275	Drill Core	0.022	18	5	0.25	156	0.023	<1	0.96	0.130	0.16	26.7	<0.01	1.9	0.2	0.71	3	<0.5
937276	Drill Core	0.027	19	5	0.27	81	0.011	<1	1.05	0.101	0.15	10.1	<0.01	2.0	0.1	1.56	3	0.5
937277	Drill Core	0.032	19	10	0.33	134	0.049	<1	0.94	0.026	0.28	1.4	<0.01	2.2	0.2	0.28	3	<0.5
937278	Drill Core	0.027	22	6	0.31	116	0.031	<1	0.96	0.092	0.24	1.1	<0.01	1.9	0.2	0.96	3	0.6
937279	Drill Core	0.030	24	9	0.38	189	0.057	<1	1.04	0.093	0.31	0.2	<0.01	2.1	0.2	0.71	3	<0.5
937280	Rock Pulp	0.108	8	26	1.33	87	0.007	5	1.43	0.079	0.20	3.1	0.14	6.2	<0.1	1.70	6	6.0
937281	Drill Core	0.032	25	9	0.36	275	0.047	<1	1.10	0.093	0.28	0.2	<0.01	2.0	0.2	0.60	3	<0.5
937282	Drill Core	0.030	29	9	0.26	70	0.010	2	0.58	0.022	0.21	0.1	<0.01	1.2	<0.1	1.46	2	<0.5
937283	Drill Core	0.020	26	16	0.39	45	0.055	<1	0.83	0.024	0.40	0.4	<0.01	1.9	0.2	0.80	4	<0.5
937284	Drill Core	0.020	23	13	0.31	41	0.032	1	0.66	0.027	0.31	0.5	<0.01	1.6	0.2	1.23	3	<0.5
937285	Drill Core	0.018	26	12	0.25	38	0.021	1	0.67	0.018	0.31	0.5	<0.01	1.4	0.2	1.64	3	0.6
937286	Drill Core	0.032	20	6	0.21	32	0.003	1	0.42	0.008	0.26	0.4	<0.01	0.7	0.1	6.97	2	3.4
937287	Drill Core	0.046	24	24	0.47	46	0.013	1	1.21	0.018	0.31	1.0	<0.01	2.4	0.3	1.65	4	1.0
937288	Drill Core	0.033	41	10	0.58	143	0.048	<1	1.39	0.018	0.39	0.1	<0.01	3.6	0.3	0.79	4	<0.5
937289	Drill Core	0.042	26	18	0.79	185	0.082	1	1.61	0.028	0.59	0.4	<0.01	3.9	0.4	0.85	5	<0.5
937290	Drill Core	0.035	20	28	0.75	55	0.079	<1	1.08	0.038	0.57	0.2	<0.01	2.5	0.3	0.78	5	<0.5
937291	Drill Core	0.032	23	41	0.63	148	0.067	2	0.91	0.039	0.49	0.5	<0.01	2.4	0.3	1.04	4	0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937292	Drill Core	10.69	0.7	145.7	6.7	13	<0.1	10.7	5.5	147	2.14	2.1	4.4	21.4	16.4	25	0.1	1.0	0.6	11	0.85
937293	Drill Core	10.44	1.2	84.1	4.7	10	<0.1	8.5	5.2	165	2.35	3.8	4.9	28.1	15.4	18	<0.1	1.6	0.7	13	0.96
937294	Drill Core	10.42	0.6	35.3	4.4	12	<0.1	7.8	5.7	183	2.54	5.4	5.7	19.5	18.2	17	<0.1	2.8	0.7	13	0.73
937295	Drill Core	8.11	0.9	31.5	11.6	20	<0.1	9.9	6.8	239	2.34	3.9	5.9	18.1	16.8	25	<0.1	1.3	1.0	17	1.12
937296	Drill Core	8.28	0.6	39.4	8.0	19	<0.1	11.7	6.7	410	2.19	1.1	3.9	14.6	11.9	43	<0.1	2.7	0.6	24	1.74
937297	Drill Core	7.77	0.7	42.1	75.7	167	0.3	7.3	5.8	244	4.70	76.6	4.8	102.3	14.4	11	1.5	22.4	5.0	4	0.53
937298	Drill Core	10.05	0.5	40.1	6.1	10	<0.1	8.2	5.2	84	2.20	15.4	6.2	24.2	16.7	20	<0.1	1.4	1.1	3	0.53
937299	Drill Core	8.94	0.7	38.2	5.8	6	<0.1	7.2	4.3	63	3.26	16.7	5.0	190.7	20.7	17	<0.1	2.0	1.9	3	0.36
937300	Rock Pulp	0.08	479.3	3163	9.8	64	1.7	22.9	17.6	666	4.45	44.3	0.5	267.2	1.1	141	1.1	7.4	0.4	85	4.20
937301	Drill Core	11.50	0.6	18.9	3.9	12	<0.1	5.5	4.0	190	1.95	1.2	3.6	6.5	13.1	79	<0.1	0.9	0.5	11	1.08
937302	Drill Core	9.73	0.3	22.6	2.8	10	<0.1	7.1	4.8	144	1.74	1.3	4.4	9.4	14.6	59	<0.1	<0.1	0.6	13	0.98
937303	Drill Core	10.56	0.5	24.2	6.4	17	<0.1	12.1	7.9	238	2.33	1.2	4.1	7.8	16.1	95	<0.1	0.1	0.5	31	1.13
937304	Drill Core	10.01	0.6	16.6	5.3	11	<0.1	5.3	4.2	165	2.06	8.2	5.4	18.2	19.5	18	<0.1	1.3	1.0	8	0.41
937305	Drill Core	10.28	0.7	38.8	7.4	11	<0.1	14.4	6.3	235	2.28	5.2	5.6	16.8	15.2	47	<0.1	1.0	0.8	11	1.04
937306	Drill Core	9.78	0.7	20.2	14.9	9	0.1	5.5	4.0	234	2.34	45.6	6.7	30.0	19.4	7	<0.1	6.2	1.9	<2	0.25
937307	Drill Core	10.76	0.8	15.7	10.1	11	0.2	6.6	5.0	72	4.19	92.3	5.8	29.6	17.8	4	0.1	4.2	3.3	<2	0.11
937308	Drill Core	10.09	0.6	49.2	23.4	22	0.3	5.1	3.9	101	3.20	80.8	6.8	105.0	17.1	6	0.2	19.1	11.8	<2	0.13
937309	Drill Core	9.34	0.6	36.7	12.1	13	0.1	4.0	3.5	122	1.99	7.1	7.0	17.9	20.6	28	<0.1	1.4	1.2	5	0.46
937310	Drill Core	7.51	0.5	43.3	5.1	9	<0.1	5.2	3.6	175	1.40	1.8	7.6	9.4	20.9	22	<0.1	1.5	0.7	8	0.77
937311	Drill Core	4.09	0.6	46.8	5.7	11	<0.1	11.0	6.6	270	2.20	5.7	6.2	20.8	20.5	40	<0.1	1.9	1.2	11	1.20
937312	Drill Core	7.39	0.6	232.9	5.7	18	0.2	18.5	4.6	147	1.75	8.2	5.7	157.4	16.2	13	<0.1	3.0	4.0	12	0.18
937313	Drill Core	9.36	0.5	141.6	4.5	20	<0.1	12.3	4.9	188	1.92	4.8	6.0	77.9	14.6	25	<0.1	1.7	2.7	14	0.57
937314	Drill Core	9.90	0.5	180.3	5.6	14	0.1	4.4	6.0	140	2.70	8.6	5.8	141.6	13.5	39	<0.1	0.8	3.1	19	0.93
937315	Drill Core	9.61	1.5	90.3	4.3	22	<0.1	5.5	6.6	140	2.55	3.3	6.1	44.6	14.5	17	<0.1	0.6	1.7	15	0.59
937316	Drill Core	10.00	1.6	68.7	4.1	20	<0.1	4.2	6.5	140	3.14	2.5	7.8	44.7	18.4	21	<0.1	0.5	2.4	13	0.68
937317	Drill Core	10.43	1.1	50.6	5.2	23	<0.1	3.2	4.8	181	1.86	3.8	5.1	25.5	13.6	34	0.1	0.4	1.1	15	0.64
937318	Drill Core	9.41	0.4	53.0	6.6	29	0.1	11.7	5.1	202	2.28	7.7	5.6	27.5	16.6	12	<0.1	0.5	2.0	14	0.36
937319	Drill Core	8.70	0.9	27.0	6.7	41	<0.1	6.2	5.6	237	1.94	3.0	7.0	11.1	20.5	23	0.2	0.7	0.7	20	0.75
937320	Rock Pulp	0.08	491.9	3179	10.4	68	1.7	21.8	19.1	661	4.56	48.6	0.4	198.1	1.1	136	1.6	7.1	0.3	84	4.64
937321	Drill Core	5.74	0.7	16.2	5.6	27	<0.1	11.3	5.0	247	1.88	1.2	4.6	5.5	13.5	24	<0.1	0.3	0.6	16	0.91

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937292	Drill Core	0.036	31	13	0.40	107	0.021	1	0.77	0.026	0.25	0.1	<0.01	1.4	0.1	1.34	3	<0.5
937293	Drill Core	0.032	28	15	0.45	69	0.034	1	0.72	0.022	0.34	0.1	<0.01	1.8	0.2	1.63	2	0.9
937294	Drill Core	0.041	27	13	0.40	59	0.043	1	0.90	0.023	0.36	<0.1	<0.01	2.6	0.2	1.64	3	0.7
937295	Drill Core	0.040	30	18	0.56	67	0.045	2	1.20	0.026	0.43	<0.1	<0.01	2.5	0.3	1.25	4	<0.5
937296	Drill Core	0.041	24	27	0.86	77	0.047	<1	1.95	0.007	0.56	<0.1	<0.01	3.6	0.3	0.46	6	<0.5
937297	Drill Core	0.031	14	7	0.09	39	0.001	1	0.54	0.004	0.21	0.2	0.05	0.7	0.3	5.11	1	1.7
937298	Drill Core	0.027	19	6	0.23	38	0.001	<1	0.55	0.006	0.18	0.2	<0.01	0.7	0.1	2.17	1	0.7
937299	Drill Core	0.026	20	5	0.17	48	<0.001	1	0.54	0.006	0.21	0.1	<0.01	0.5	0.1	3.42	1	1.5
937300	Rock Pulp	0.111	8	25	1.26	105	0.007	4	1.42	0.078	0.20	2.9	0.16	6.0	<0.1	1.65	5	7.0
937301	Drill Core	0.030	21	9	0.33	83	0.031	1	0.77	0.071	0.30	<0.1	<0.01	1.8	0.1	1.23	2	<0.5
937302	Drill Core	0.034	22	14	0.41	145	0.041	1	0.70	0.044	0.32	0.2	<0.01	2.1	0.2	0.94	2	<0.5
937303	Drill Core	0.028	24	26	0.76	163	0.109	1	1.67	0.111	0.59	0.1	<0.01	3.4	0.4	0.95	5	<0.5
937304	Drill Core	0.020	23	10	0.28	118	0.034	1	0.58	0.020	0.33	0.2	<0.01	1.4	0.2	1.46	2	0.8
937305	Drill Core	0.045	18	14	0.44	74	0.010	1	0.78	0.025	0.25	0.1	<0.01	1.9	0.2	1.94	2	1.1
937306	Drill Core	0.027	9	6	0.09	32	<0.001	2	0.28	0.003	0.19	0.1	0.01	0.3	0.1	2.52	<1	0.7
937307	Drill Core	0.023	5	6	0.04	39	<0.001	2	0.26	0.004	0.22	0.1	<0.01	0.2	0.2	4.64	<1	1.3
937308	Drill Core	0.024	11	6	0.04	32	<0.001	2	0.28	0.003	0.21	0.2	0.01	0.4	0.1	3.47	<1	2.0
937309	Drill Core	0.024	19	9	0.18	27	0.010	<1	0.66	0.013	0.22	<0.1	<0.01	1.2	0.2	1.55	2	0.6
937310	Drill Core	0.030	29	12	0.26	26	0.029	<1	0.53	0.037	0.24	<0.1	<0.01	1.7	0.2	0.49	2	<0.5
937311	Drill Core	0.041	28	26	0.39	29	0.007	1	0.62	0.019	0.24	0.2	<0.01	2.2	0.2	1.73	2	0.8
937312	Drill Core	0.034	21	19	0.30	186	0.012	<1	0.90	0.036	0.19	<0.1	<0.01	1.8	0.1	0.61	2	<0.5
937313	Drill Core	0.035	24	16	0.49	142	0.027	<1	1.05	0.064	0.24	<0.1	<0.01	1.9	0.2	0.72	4	<0.5
937314	Drill Core	0.045	23	7	0.44	48	0.010	2	0.93	0.050	0.21	0.8	<0.01	1.7	0.1	1.95	3	0.5
937315	Drill Core	0.042	26	11	0.53	82	0.028	1	1.03	0.046	0.26	0.3	<0.01	2.3	0.2	1.51	4	0.5
937316	Drill Core	0.059	29	9	0.49	70	0.026	2	1.04	0.045	0.25	0.2	<0.01	2.3	0.2	2.22	4	0.7
937317	Drill Core	0.033	22	9	0.47	181	0.048	<1	1.11	0.097	0.29	0.3	<0.01	2.6	0.2	0.77	4	0.6
937318	Drill Core	0.031	24	20	0.51	64	0.045	1	0.91	0.040	0.33	0.3	0.01	2.4	0.2	1.30	4	0.6
937319	Drill Core	0.038	25	11	0.56	165	0.042	<1	1.30	0.049	0.36	<0.1	<0.01	2.7	0.3	0.67	4	<0.5
937320	Rock Pulp	0.119	8	26	1.31	79	0.006	4	1.35	0.081	0.19	3.4	0.16	6.2	<0.1	1.72	5	7.5
937321	Drill Core	0.034	16	18	0.67	219	0.031	2	1.64	0.060	0.34	0.3	<0.01	2.2	0.2	0.57	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937322	Drill Core	9.10	2.1	89.0	3.4	24	<0.1	4.0	6.2	233	2.24	2.1	3.9	90.5	10.2	71	<0.1	0.3	0.6	45	0.92
937323	Drill Core	10.39	1.0	142.7	4.6	16	0.2	4.4	4.0	147	1.70	14.0	4.9	53.3	18.0	14	<0.1	0.5	1.6	9	0.64
937324	Drill Core	10.70	0.3	31.3	5.5	29	<0.1	3.7	3.4	245	1.55	2.1	6.7	14.1	18.7	18	<0.1	0.2	0.5	11	0.54
937325	Drill Core	5.05	0.9	34.1	4.5	26	<0.1	4.1	3.7	224	1.49	1.4	4.2	26.6	16.7	21	0.1	0.5	0.3	13	0.51
937326	Drill Core	7.16	2.0	55.5	5.9	22	<0.1	20.5	4.9	191	1.50	3.8	4.4	17.0	13.8	23	<0.1	2.0	0.6	13	0.75
937327	Drill Core	5.96	0.1	65.7	8.1	10	0.1	1.8	3.8	158	2.45	17.5	4.1	31.9	11.6	35	<0.1	1.2	1.6	5	1.55
937328	Drill Core	6.67	0.2	54.0	5.6	15	<0.1	8.1	6.6	144	2.95	44.2	3.8	35.9	12.4	26	<0.1	1.3	1.5	11	0.90
937329	Drill Core	10.15	0.9	22.3	3.2	34	<0.1	9.5	6.9	270	2.26	1.8	3.7	4.1	13.8	28	<0.1	0.2	0.3	22	0.67
937330	Drill Core	10.97	0.4	44.5	3.7	17	<0.1	3.0	5.7	150	2.33	2.6	5.5	22.9	15.0	34	<0.1	0.4	0.5	29	0.91
937331	Drill Core	9.31	0.6	22.8	3.7	18	<0.1	2.8	6.7	147	3.19	4.7	4.3	20.2	15.6	29	<0.1	0.2	0.9	27	0.94
937332	Drill Core	9.89	0.4	47.5	6.0	22	0.1	3.1	7.7	219	2.56	21.2	4.6	36.9	14.3	52	<0.1	1.0	0.8	37	1.02
937333	Drill Core	9.46	0.4	44.3	9.5	31	<0.1	9.4	8.5	276	2.63	4.4	5.1	38.8	13.8	25	<0.1	0.3	0.7	56	0.59
937334	Drill Core	9.66	0.4	4.1	4.5	20	<0.1	9.5	4.2	217	1.83	1.4	5.1	4.9	11.8	16	<0.1	0.2	0.5	10	0.72
937335	Drill Core	9.29	0.4	11.5	3.8	15	<0.1	9.7	4.7	168	2.03	3.7	3.9	13.0	12.0	13	<0.1	0.6	0.6	9	0.55
937336	Drill Core	9.63	0.3	7.5	11.8	29	<0.1	11.5	4.2	289	1.45	1.0	4.7	5.0	10.8	10	<0.1	0.1	0.2	18	0.22
937337	Drill Core	11.05	0.4	42.2	4.5	29	<0.1	111.3	12.1	298	2.31	1.5	4.0	6.3	11.2	21	<0.1	0.2	0.4	30	0.89
937338	Drill Core	8.42	0.6	34.8	3.0	31	<0.1	17.5	6.7	371	2.34	1.3	6.0	5.8	18.1	35	<0.1	0.4	0.6	20	0.64
937339	Drill Core	4.49	0.5	164.8	9.4	18	0.4	106.8	10.3	413	3.81	213.0	4.7	81.9	10.8	25	<0.1	8.1	6.9	6	1.10
937340	Rock Pulp	0.08	496.0	3189	10.3	66	1.7	21.7	18.8	654	4.51	47.8	0.5	268.7	1.1	132	1.3	6.2	0.3	85	4.71
937341	Drill Core	10.20	0.5	34.9	4.2	31	<0.1	13.1	5.3	268	1.64	1.8	4.8	3.9	12.1	15	<0.1	1.0	0.4	21	0.46
937342	Drill Core	9.10	0.5	28.4	5.1	23	<0.1	10.4	5.7	206	2.12	4.3	3.3	17.9	14.2	13	<0.1	0.4	0.6	16	0.42
937343	Drill Core	9.76	0.6	47.5	2.5	26	<0.1	5.7	5.2	216	1.90	3.3	4.8	10.8	16.2	9	<0.1	0.8	0.4	15	0.29
937344	Drill Core	9.38	0.7	90.6	5.3	19	<0.1	6.2	5.8	159	1.93	13.2	5.3	28.8	17.2	19	<0.1	1.0	0.7	20	0.65
937345	Drill Core	2.73	0.1	14.0	4.8	23	<0.1	16.9	5.0	176	1.54	5.4	5.1	6.1	10.7	12	<0.1	0.9	0.3	17	0.41
937346	Drill Core	7.55	0.5	17.7	4.7	2	<0.1	34.4	6.0	21	3.46	44.1	2.3	52.4	8.7	7	<0.1	3.9	3.1	<2	0.04
937347	Drill Core	9.53	0.7	66.4	4.4	20	<0.1	14.6	5.6	208	1.74	7.1	5.5	31.5	14.4	13	<0.1	3.4	0.5	17	0.41
937348	Drill Core	8.07	0.5	7.6	5.0	15	<0.1	7.6	5.2	352	2.10	9.5	4.9	13.3	14.9	17	<0.1	1.0	0.5	9	1.24
937349	Drill Core	9.15	0.5	20.3	3.6	29	<0.1	13.9	6.7	261	2.22	1.9	4.6	6.2	13.6	19	<0.1	0.8	0.3	26	0.52
937350	Drill Core	9.56	4.4	32.2	5.0	20	<0.1	6.4	3.6	231	1.38	3.0	8.4	4.6	57.5	13	<0.1	1.1	0.4	16	0.45
937351	Drill Core	8.87	0.7	47.0	5.0	33	<0.1	15.7	6.1	336	2.11	2.9	4.2	11.0	16.8	16	<0.1	0.8	0.6	28	0.74

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937322	Drill Core	0.077	18	10	0.84	113	0.069	<1	1.40	0.105	0.33	0.1	<0.01	4.0	0.3	0.75	5	0.5
937323	Drill Core	0.037	36	10	0.47	73	0.014	1	0.85	0.050	0.20	<0.1	<0.01	2.2	0.1	0.85	4	<0.5
937324	Drill Core	0.028	28	10	0.37	75	0.038	<1	0.84	0.062	0.25	<0.1	<0.01	2.4	0.2	0.39	4	<0.5
937325	Drill Core	0.029	24	13	0.42	177	0.052	2	0.89	0.069	0.30	<0.1	<0.01	2.3	0.2	0.30	4	<0.5
937326	Drill Core	0.032	21	30	0.73	36	0.008	<1	1.41	0.022	0.17	0.3	<0.01	1.8	0.1	0.54	5	<0.5
937327	Drill Core	0.030	18	3	0.35	60	<0.001	2	1.11	0.056	0.14	0.5	<0.01	0.9	<0.1	2.38	3	0.8
937328	Drill Core	0.034	18	13	0.40	39	0.009	1	1.00	0.055	0.22	0.4	<0.01	1.5	0.1	2.35	3	0.8
937329	Drill Core	0.047	23	23	0.71	251	0.104	<1	1.24	0.085	0.51	0.2	<0.01	3.6	0.4	0.52	5	<0.5
937330	Drill Core	0.041	15	9	0.57	105	0.056	2	1.19	0.096	0.27	0.4	<0.01	2.6	0.2	1.46	4	0.5
937331	Drill Core	0.038	15	7	0.59	58	0.033	2	1.24	0.075	0.21	1.3	<0.01	2.3	0.2	2.40	4	1.5
937332	Drill Core	0.073	20	6	0.57	147	0.078	<1	1.53	0.153	0.37	2.0	<0.01	3.0	0.4	1.21	5	0.7
937333	Drill Core	0.068	22	19	0.88	190	0.118	1	1.29	0.060	0.60	0.4	<0.01	4.4	0.5	0.80	6	0.5
937334	Drill Core	0.028	19	14	0.35	78	0.039	1	0.63	0.030	0.34	0.4	<0.01	1.7	0.2	1.02	3	<0.5
937335	Drill Core	0.023	17	13	0.32	43	0.036	1	0.65	0.026	0.34	0.1	<0.01	1.4	0.2	1.28	3	<0.5
937336	Drill Core	0.024	19	25	0.48	48	0.114	<1	0.90	0.047	0.60	0.3	<0.01	2.6	0.3	0.07	5	<0.5
937337	Drill Core	0.045	18	154	1.61	185	0.133	1	1.77	0.068	0.94	0.8	<0.01	3.6	0.8	0.55	7	<0.5
937338	Drill Core	0.050	38	26	0.59	270	0.117	1	0.95	0.048	0.62	0.7	<0.01	4.5	0.4	0.55	5	<0.5
937339	Drill Core	0.038	8	31	0.53	35	0.002	1	0.61	0.007	0.19	0.4	0.03	1.3	0.4	3.60	2	1.0
937340	Rock Pulp	0.111	8	24	1.28	66	0.006	3	1.35	0.081	0.18	3.2	0.20	6.5	<0.1	1.71	5	6.8
937341	Drill Core	0.037	25	23	0.50	56	0.103	<1	0.92	0.049	0.52	0.2	<0.01	3.2	0.3	0.16	5	<0.5
937342	Drill Core	0.032	26	19	0.48	55	0.086	<1	1.07	0.041	0.55	0.2	<0.01	3.0	0.3	0.66	5	0.7
937343	Drill Core	0.032	30	12	0.50	68	0.111	<1	1.08	0.045	0.57	0.3	<0.01	3.5	0.3	0.23	6	<0.5
937344	Drill Core	0.036	26	14	0.51	141	0.047	<1	0.89	0.053	0.36	0.2	<0.01	3.4	0.3	0.80	4	<0.5
937345	Drill Core	0.044	18	19	0.42	36	0.055	<1	0.97	0.035	0.36	0.2	<0.01	2.7	0.2	0.33	4	<0.5
937346	Drill Core	0.013	9	8	0.03	40	<0.001	3	0.31	0.005	0.21	0.3	0.02	0.3	<0.1	3.57	1	1.2
937347	Drill Core	0.037	25	19	0.45	43	0.058	<1	1.06	0.027	0.36	0.3	<0.01	2.6	0.2	0.40	4	<0.5
937348	Drill Core	0.035	30	12	0.32	79	0.031	<1	1.11	0.019	0.31	0.2	<0.01	2.1	0.2	1.06	4	0.7
937349	Drill Core	0.038	23	28	0.68	109	0.122	<1	1.18	0.035	0.64	0.1	<0.01	4.2	0.4	0.51	5	0.5
937350	Drill Core	0.024	47	18	0.47	62	0.065	<1	0.90	0.032	0.39	0.3	<0.01	3.0	0.2	0.10	4	<0.5
937351	Drill Core	0.037	28	36	0.85	57	0.112	<1	1.35	0.027	0.71	8.2	<0.01	4.9	0.4	0.41	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937352	Drill Core	10.18	0.7	45.4	5.6	28	<0.1	16.1	6.2	274	2.10	2.1	4.7	18.8	12.8	14	<0.1	0.3	0.7	28	0.51
937353	Drill Core	10.58	0.7	29.4	4.4	25	<0.1	29.2	8.0	249	2.31	11.6	3.6	10.1	9.1	11	<0.1	0.5	0.6	29	0.42
937354	Drill Core	8.35	0.9	31.9	2.7	21	<0.1	22.7	7.6	231	2.22	5.1	3.6	24.4	11.4	15	<0.1	0.2	0.6	31	0.45
937355	Drill Core	9.48	0.7	60.1	4.2	17	<0.1	12.8	6.2	172	2.23	14.5	3.6	18.4	17.1	14	<0.1	0.5	0.8	23	0.51
937356	Drill Core	10.12	0.5	36.2	3.4	23	<0.1	13.7	6.8	227	2.06	1.3	3.9	13.0	14.4	14	<0.1	0.2	0.8	30	0.43
937357	Drill Core	10.13	0.8	60.6	3.6	23	<0.1	11.2	6.3	214	2.01	4.4	4.2	14.3	15.5	12	<0.1	0.2	1.7	27	0.48
937358	Drill Core	10.06	0.6	64.1	4.0	32	<0.1	8.4	5.7	273	1.79	4.9	3.9	10.6	16.8	13	<0.1	0.2	0.5	22	0.48
937359	Drill Core	7.72	0.7	54.5	2.7	24	<0.1	10.9	6.2	235	1.95	3.5	3.8	12.5	13.4	17	<0.1	0.2	0.6	25	0.55
937360	Rock Pulp	0.08	2.7	39.7	20.8	81	0.2	23.9	10.1	743	3.61	6.8	0.3	<0.5	1.2	33	0.3	0.4	0.1	54	0.66
937361	Drill Core	8.11	0.4	21.0	4.8	15	<0.1	21.0	7.3	166	2.61	11.3	3.2	15.6	15.0	19	<0.1	0.6	0.7	13	1.19
937362	Drill Core	8.89	1.0	49.3	4.1	13	<0.1	10.0	5.9	147	2.25	7.6	5.6	90.1	15.4	17	<0.1	2.5	0.7	17	1.01
937363	Drill Core	8.12	0.4	69.4	4.4	16	<0.1	10.0	6.5	179	3.45	9.0	6.1	48.2	13.5	18	<0.1	0.9	0.4	14	1.28
937364	Drill Core	10.23	0.6	198.5	6.5	12	0.2	9.2	4.6	91	2.14	56.6	4.8	106.1	15.5	9	0.3	4.6	1.3	6	0.52
937365	Drill Core	9.66	0.4	97.6	5.8	10	0.2	5.6	3.4	89	1.81	45.7	6.3	71.2	18.4	9	<0.1	2.3	1.6	3	0.46
937366	Drill Core	10.04	0.4	84.6	5.4	16	<0.1	7.0	4.0	159	1.46	1.7	4.9	66.4	18.8	14	<0.1	0.3	0.3	10	0.47
937367	Drill Core	10.10	0.5	109.2	6.4	13	<0.1	5.0	4.4	132	1.80	22.8	4.8	36.7	18.0	13	<0.1	0.6	0.6	9	0.54
937368	Drill Core	10.47	0.5	192.6	8.5	8	0.1	5.5	4.0	109	2.08	16.6	5.7	60.0	20.0	16	<0.1	0.3	0.9	5	0.70
937369	Drill Core	10.02	0.6	58.4	7.6	15	<0.1	4.1	3.7	168	1.59	3.5	7.6	25.1	19.1	13	<0.1	0.6	0.6	8	0.59
937370	Drill Core	9.91	0.5	95.9	7.0	11	0.1	5.6	3.4	118	1.59	21.4	6.6	31.5	17.4	20	<0.1	1.7	1.5	4	0.66
937371	Drill Core	10.20	0.5	51.7	6.8	9	<0.1	3.7	3.1	150	1.34	8.1	7.0	11.6	19.7	18	<0.1	0.7	0.7	4	0.80
937372	Drill Core	10.71	0.4	18.4	5.2	18	<0.1	4.4	3.3	245	1.48	2.5	5.8	13.5	22.6	12	<0.1	0.1	0.3	10	0.50
937373	Drill Core	7.98	0.5	99.2	6.1	15	<0.1	8.9	6.8	168	2.48	15.6	5.0	45.5	15.5	569	<0.1	0.5	0.6	36	0.99
937374	Drill Core	8.32	1.1	14.8	3.7	27	<0.1	2.9	7.2	300	2.20	12.6	3.7	10.5	16.7	45	<0.1	3.3	1.1	47	1.14
937375	Drill Core	8.38	0.8	27.3	4.7	24	<0.1	2.3	6.0	238	1.98	7.2	4.5	129.4	13.7	72	<0.1	5.4	1.9	35	1.30
937376	Drill Core	8.61	1.0	59.8	4.2	24	0.1	1.9	5.8	256	2.18	13.4	4.2	69.3	13.9	64	<0.1	3.7	3.4	32	1.27
937377	Drill Core	9.50	1.0	22.3	4.1	29	<0.1	2.1	6.9	274	2.16	4.2	4.8	42.1	14.6	76	<0.1	2.4	1.7	49	1.06
937378	Drill Core	10.13	1.2	27.7	4.7	35	<0.1	3.5	8.5	315	2.91	221.7	5.9	30.3	15.8	43	<0.1	3.2	2.1	58	0.98
937379	Drill Core	8.86	1.4	8.2	3.8	36	<0.1	2.9	7.4	327	2.08	4.0	7.0	4.8	15.4	32	<0.1	0.2	0.1	60	0.67
937380	Rock Pulp	0.08	463.5	2992	8.6	62	1.7	21.1	17.0	628	4.41	42.4	0.4	201.2	0.9	132	1.2	6.3	0.3	80	3.93
937381	Drill Core	8.62	1.1	20.3	4.8	34	<0.1	3.0	8.8	365	2.60	33.5	5.5	46.0	16.2	40	<0.1	0.7	13.5	62	0.97

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937352	Drill Core	0.039	32	38	0.82	76	0.139	<1	1.14	0.051	0.71	0.2	<0.01	4.9	0.3	0.36	6	<0.5
937353	Drill Core	0.045	21	46	0.93	69	0.128	<1	1.17	0.040	0.75	0.2	<0.01	5.0	0.3	0.75	6	<0.5
937354	Drill Core	0.043	31	45	0.91	128	0.153	<1	1.19	0.059	0.79	1.1	<0.01	5.1	0.4	0.45	5	<0.5
937355	Drill Core	0.039	33	29	0.68	104	0.080	<1	0.94	0.031	0.47	6.9	<0.01	4.1	0.3	0.93	5	<0.5
937356	Drill Core	0.046	30	38	0.84	87	0.142	1	1.11	0.055	0.70	0.1	<0.01	5.3	0.4	0.27	5	<0.5
937357	Drill Core	0.038	33	35	0.79	69	0.119	1	1.05	0.044	0.62	0.1	<0.01	4.9	0.3	0.37	6	<0.5
937358	Drill Core	0.034	33	28	0.64	55	0.103	<1	0.97	0.045	0.56	0.2	<0.01	4.3	0.3	0.21	5	<0.5
937359	Drill Core	0.041	36	33	0.73	185	0.110	<1	1.01	0.041	0.54	0.3	<0.01	4.6	0.3	0.38	5	<0.5
937360	Rock Pulp	0.071	6	28	0.96	70	0.124	2	2.01	0.068	0.12	0.1	<0.01	4.2	<0.1	<0.05	6	<0.5
937361	Drill Core	0.035	28	29	0.58	41	0.024	<1	1.22	0.011	0.38	0.3	<0.01	2.1	0.2	1.71	4	0.5
937362	Drill Core	0.037	29	19	0.47	37	0.056	<1	0.97	0.025	0.41	0.2	<0.01	3.2	0.2	1.18	4	0.6
937363	Drill Core	0.035	21	16	0.39	40	0.048	<1	0.77	0.025	0.34	0.1	<0.01	2.8	0.2	2.49	3	1.0
937364	Drill Core	0.029	13	9	0.20	36	0.008	1	0.51	0.014	0.28	0.1	0.04	1.1	0.2	1.85	2	0.6
937365	Drill Core	0.023	17	5	0.14	37	0.003	1	0.47	0.020	0.23	<0.1	0.01	0.7	0.1	1.58	1	0.5
937366	Drill Core	0.023	29	13	0.42	40	0.051	<1	0.57	0.033	0.35	0.2	<0.01	2.0	0.2	0.38	3	<0.5
937367	Drill Core	0.027	26	11	0.33	34	0.025	1	0.60	0.035	0.27	0.1	<0.01	1.8	0.1	0.98	3	<0.5
937368	Drill Core	0.028	18	9	0.28	28	0.006	<1	0.36	0.025	0.19	<0.1	<0.01	1.1	0.1	1.70	1	0.6
937369	Drill Core	0.029	28	11	0.27	28	0.031	<1	0.57	0.032	0.24	<0.1	<0.01	2.0	0.2	0.63	3	<0.5
937370	Drill Core	0.028	17	7	0.26	31	0.006	<1	0.37	0.020	0.20	0.1	<0.01	0.9	0.1	1.15	1	<0.5
937371	Drill Core	0.027	24	7	0.25	28	0.005	<1	0.38	0.029	0.17	<0.1	<0.01	1.0	0.1	0.80	2	<0.5
937372	Drill Core	0.022	34	12	0.31	41	0.047	<1	0.60	0.043	0.32	0.2	<0.01	2.2	0.2	0.33	3	<0.5
937373	Drill Core	0.058	25	13	0.66	78	0.066	<1	0.79	0.044	0.40	<0.1	<0.01	4.1	0.4	1.45	3	<0.5
937374	Drill Core	0.042	23	12	0.68	195	0.102	<1	1.33	0.086	0.19	0.6	<0.01	3.5	0.2	0.19	5	<0.5
937375	Drill Core	0.040	18	9	0.52	301	0.080	<1	1.34	0.119	0.18	0.4	<0.01	2.3	0.1	0.33	4	<0.5
937376	Drill Core	0.038	21	8	0.59	214	0.047	<1	1.40	0.088	0.16	0.1	<0.01	2.7	<0.1	0.31	4	<0.5
937377	Drill Core	0.045	19	10	0.61	416	0.132	<1	1.51	0.125	0.27	0.4	<0.01	2.7	0.2	0.20	4	<0.5
937378	Drill Core	0.047	22	14	0.78	215	0.113	2	1.36	0.075	0.23	0.9	<0.01	4.1	0.1	0.53	5	<0.5
937379	Drill Core	0.047	23	14	0.70	348	0.183	<1	1.25	0.102	0.39	1.3	<0.01	3.1	0.3	<0.05	5	<0.5
937380	Rock Pulp	0.113	8	23	1.23	77	0.006	3	1.26	0.074	0.19	2.9	0.15	6.6	<0.1	1.58	5	6.3
937381	Drill Core	0.048	24	16	0.78	291	0.162	<1	1.37	0.097	0.35	3.9	<0.01	4.6	0.3	0.40	4	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937382	Drill Core	9.01	1.2	9.5	7.3	48	<0.1	3.5	9.5	419	2.45	4.0	4.3	10.4	13.6	33	<0.1	0.2	<0.1	67	1.19
937383	Drill Core	9.84	1.6	16.4	5.1	61	<0.1	4.4	10.1	436	2.74	7.4	3.6	7.8	15.4	44	0.2	0.4	0.8	72	1.31
937384	Drill Core	9.57	2.7	15.0	4.3	27	<0.1	2.5	7.2	300	2.07	4.6	4.4	6.7	17.5	65	<0.1	0.3	0.8	48	1.22
937385	Drill Core	8.34	1.1	14.8	4.5	19	<0.1	1.5	4.7	203	1.42	8.6	5.6	57.5	17.6	65	<0.1	0.5	7.1	22	1.31
937386	Drill Core	9.36	1.5	14.7	5.3	21	<0.1	2.6	8.0	376	2.24	86.5	4.5	19.4	18.4	68	<0.1	0.4	0.6	32	2.60

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

CERTIFICATE OF ANALYSIS SMI09000301.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937382	Drill Core	0.051	20	16	0.92	227	0.181	<1	1.58	0.086	0.26	0.8	<0.01	3.8	0.2	<0.05	6	<0.5
937383	Drill Core	0.058	21	17	0.99	230	0.171	1	1.70	0.091	0.21	0.6	<0.01	3.9	0.2	0.13	6	<0.5
937384	Drill Core	0.046	19	11	0.63	315	0.122	1	1.46	0.139	0.23	0.5	<0.01	3.0	0.1	0.17	5	<0.5
937385	Drill Core	0.028	16	6	0.31	267	0.045	<1	1.06	0.120	0.23	0.2	0.02	1.1	<0.1	0.20	3	<0.5
937386	Drill Core	0.038	23	10	0.69	124	0.012	1	1.22	0.047	0.19	0.1	0.01	2.5	<0.1	0.38	4	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

QUALITY CONTROL REPORT SMI09000301.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
937268	Drill Core	10.90	0.3	54.1	4.9	21	<0.1	7.1	5.6	256	1.96	7.3	4.2	26.9	15.4	18	<0.1	0.5	1.4	15	0.68
REP 937268	QC		0.3	55.2	4.9	22	<0.1	7.1	5.5	255	1.93	7.9	4.0	15.9	14.7	19	<0.1	0.5	1.4	15	0.67
937308	Drill Core	10.09	0.6	49.2	23.4	22	0.3	5.1	3.9	101	3.20	80.8	6.8	105.0	17.1	6	0.2	19.1	11.8	<2	0.13
REP 937308	QC		0.8	52.1	26.5	24	0.3	4.9	3.7	106	3.28	86.6	7.1	77.8	17.8	6	0.3	19.8	12.1	<2	0.13
937344	Drill Core	9.38	0.7	90.6	5.3	19	<0.1	6.2	5.8	159	1.93	13.2	5.3	28.8	17.2	19	<0.1	1.0	0.7	20	0.65
REP 937344	QC		0.7	95.3	6.1	18	<0.1	6.7	5.9	158	1.94	13.8	5.7	29.6	17.5	20	<0.1	1.1	0.7	21	0.66
937377	Drill Core	9.50	1.0	22.3	4.1	29	<0.1	2.1	6.9	274	2.16	4.2	4.8	42.1	14.6	76	<0.1	2.4	1.7	49	1.06
REP 937377	QC		1.2	23.3	4.1	27	<0.1	2.8	6.8	283	2.16	4.8	4.8	53.5	14.9	73	<0.1	2.6	1.7	48	1.05
937386	Drill Core	9.36	1.5	14.7	5.3	21	<0.1	2.6	8.0	376	2.24	86.5	4.5	19.4	18.4	68	<0.1	0.4	0.6	32	2.60
REP 937386	QC		1.7	13.8	5.0	21	<0.1	2.8	7.9	367	2.21	82.0	4.5	16.2	17.5	67	<0.1	0.4	0.5	31	2.56
Core Reject Duplicates																					
937266	Drill Core	9.77	0.4	387.2	8.2	33	0.3	4.1	5.8	309	2.24	22.3	12.8	80.9	12.3	19	0.3	10.9	1.2	<2	0.32
DUP 937266	QC		0.5	371.8	8.0	33	0.3	3.8	5.6	298	2.21	24.8	11.8	61.4	12.0	19	0.3	10.0	1.2	<2	0.31
937301	Drill Core	11.50	0.6	18.9	3.9	12	<0.1	5.5	4.0	190	1.95	1.2	3.6	6.5	13.1	79	<0.1	0.9	0.5	11	1.08
DUP 937301	QC		0.5	19.3	3.9	13	<0.1	6.3	4.2	190	2.01	1.6	3.5	5.3	14.3	77	<0.1	1.1	0.6	11	1.03
937336	Drill Core	9.63	0.3	7.5	11.8	29	<0.1	11.5	4.2	289	1.45	1.0	4.7	5.0	10.8	10	<0.1	0.1	0.2	18	0.22
DUP 937336	QC		0.3	7.4	12.3	28	<0.1	10.6	4.1	262	1.36	0.8	4.5	3.1	10.6	10	<0.1	0.1	0.3	17	0.22
937371	Drill Core	10.20	0.5	51.7	6.8	9	<0.1	3.7	3.1	150	1.34	8.1	7.0	11.6	19.7	18	<0.1	0.7	0.7	4	0.80
DUP 937371	QC		0.6	54.6	7.0	10	<0.1	4.6	3.0	153	1.31	8.7	7.1	20.1	20.9	19	<0.1	0.6	0.8	4	0.80
Reference Materials																					
STD DS7	Standard		20.6	109.9	73.7	408	0.8	57.5	9.4	657	2.49	52.1	5.2	70.3	4.8	79	6.1	6.1	5.0	86	0.99
STD DS7	Standard		21.6	111.4	76.3	406	0.9	59.3	9.5	664	2.51	53.6	5.5	63.9	4.9	85	6.5	6.6	5.1	86	1.01
STD DS7	Standard		19.1	101.8	64.8	380	0.8	54.8	9.0	608	2.43	45.9	4.5	53.7	4.4	71	5.7	5.6	4.3	79	0.94
STD DS7	Standard		19.6	101.3	66.0	366	0.8	52.8	8.3	598	2.34	47.7	4.7	54.2	4.3	74	5.8	5.5	4.4	77	0.93
STD DS7	Standard		21.2	113.0	74.6	394	0.8	58.4	9.9	639	2.52	49.5	5.1	86.1	5.1	78	6.3	5.4	4.8	85	1.00
STD DS7	Standard		20.9	112.9	71.3	390	0.8	55.7	9.7	627	2.47	49.0	5.0	73.8	4.8	77	5.8	5.5	4.5	85	0.99
STD DS7	Standard		20.7	111.2	70.6	406	0.8	57.5	9.9	635	2.52	53.4	4.9	61.1	4.7	76	6.0	5.8	4.4	84	1.01
STD DS7	Standard		19.8	110.5	66.7	412	0.9	58.8	9.2	634	2.51	51.7	4.7	52.8	4.5	73	6.1	5.5	4.4	84	0.99

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

QUALITY CONTROL REPORT SMI09000301.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
937268	Drill Core	0.031	28	11	0.40	76	0.035	<1	0.64	0.039	0.26	2.1	<0.01	2.1	0.2	0.83	3	<0.5
REP 937268	QC	0.032	28	12	0.40	74	0.035	<1	0.61	0.038	0.26	2.1	<0.01	2.2	0.2	0.82	3	0.6
937308	Drill Core	0.024	11	6	0.04	32	<0.001	2	0.28	0.003	0.21	0.2	0.01	0.4	0.1	3.47	<1	2.0
REP 937308	QC	0.025	11	6	0.04	34	<0.001	2	0.29	0.004	0.22	0.2	0.02	0.4	0.1	3.55	<1	1.4
937344	Drill Core	0.036	26	14	0.51	141	0.047	<1	0.89	0.053	0.36	0.2	<0.01	3.4	0.3	0.80	4	<0.5
REP 937344	QC	0.041	28	14	0.51	157	0.049	<1	0.88	0.052	0.35	0.2	<0.01	3.7	0.2	0.81	4	<0.5
937377	Drill Core	0.045	19	10	0.61	416	0.132	<1	1.51	0.125	0.27	0.4	<0.01	2.7	0.2	0.20	4	<0.5
REP 937377	QC	0.046	19	10	0.61	420	0.132	<1	1.47	0.124	0.27	0.4	<0.01	2.8	0.2	0.19	5	<0.5
937386	Drill Core	0.038	23	10	0.69	124	0.012	1	1.22	0.047	0.19	0.1	0.01	2.5	<0.1	0.38	4	<0.5
REP 937386	QC	0.039	22	10	0.68	118	0.010	<1	1.18	0.044	0.17	<0.1	<0.01	2.5	<0.1	0.37	4	<0.5
Core Reject Duplicates																		
937266	Drill Core	0.027	15	4	0.08	55	<0.001	<1	0.83	0.007	0.16	2.4	<0.01	0.7	0.1	1.75	1	<0.5
DUP 937266	QC	0.026	15	4	0.07	58	<0.001	<1	0.77	0.007	0.16	6.2	<0.01	0.7	0.1	1.74	1	0.5
937301	Drill Core	0.030	21	9	0.33	83	0.031	1	0.77	0.071	0.30	<0.1	<0.01	1.8	0.1	1.23	2	<0.5
DUP 937301	QC	0.032	22	10	0.35	96	0.034	2	0.74	0.064	0.28	<0.1	<0.01	1.9	0.2	1.27	2	<0.5
937336	Drill Core	0.024	19	25	0.48	48	0.114	<1	0.90	0.047	0.60	0.3	<0.01	2.6	0.3	0.07	5	<0.5
DUP 937336	QC	0.022	19	21	0.46	45	0.103	<1	0.88	0.047	0.56	0.3	<0.01	2.5	0.4	0.06	5	<0.5
937371	Drill Core	0.027	24	7	0.25	28	0.005	<1	0.38	0.029	0.17	<0.1	<0.01	1.0	0.1	0.80	2	<0.5
DUP 937371	QC	0.027	24	7	0.25	30	0.005	<1	0.38	0.027	0.17	<0.1	<0.01	1.1	<0.1	0.79	1	<0.5
Reference Materials																		
STD DS7	Standard	0.076	13	229	1.09	410	0.125	42	1.09	0.101	0.47	3.8	0.20	2.3	4.1	0.20	5	3.1
STD DS7	Standard	0.078	13	231	1.10	425	0.129	45	1.10	0.103	0.47	4.1	0.19	2.3	4.4	0.20	5	3.5
STD DS7	Standard	0.077	12	210	1.01	395	0.121	36	1.01	0.097	0.42	3.8	0.16	2.5	4.0	0.19	4	3.5
STD DS7	Standard	0.067	13	209	1.00	398	0.119	41	1.01	0.096	0.43	3.7	0.19	2.4	3.9	0.18	4	2.5
STD DS7	Standard	0.075	14	226	1.06	411	0.130	39	1.08	0.107	0.46	3.7	0.21	2.5	4.3	0.20	5	3.9
STD DS7	Standard	0.072	13	222	1.05	405	0.131	34	1.07	0.107	0.44	3.6	0.17	2.5	4.1	0.20	5	4.1
STD DS7	Standard	0.083	13	224	1.10	423	0.122	42	1.09	0.106	0.45	4.1	0.19	2.4	4.0	0.20	5	4.1
STD DS7	Standard	0.073	12	220	1.08	410	0.118	41	1.07	0.104	0.45	3.8	0.18	2.3	4.1	0.20	5	3.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

QUALITY CONTROL REPORT SMI09000301.1

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
STD DS7	Standard		20.4	103.6	66.1	397	0.9	56.4	9.2	616	2.36	64.1	4.6	70.8	4.2	65	5.9	6.0	4.2	80	0.90
STD DS7	Standard		21.3	104.6	65.2	385	0.8	56.0	9.6	620	2.44	51.3	4.6	82.7	4.4	70	5.8	5.3	4.1	81	0.94
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.1	3.6	3.6	45	<0.1	3.9	4.6	549	2.02	6.8	1.6	<0.5	3.6	53	<0.1	0.1	<0.1	42	0.52
G1	Prep Blank		0.2	11.8	30.3	142	0.3	4.2	4.8	566	2.08	4.5	1.6	<0.5	3.7	47	0.1	3.9	0.3	41	0.50

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 13, 2009

QUALITY CONTROL REPORT SMI09000301.1

		1DX15 P % 0.001	1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5
STD DS7	Standard	0.073	12	225	0.99	394	0.111	36	0.96	0.101	0.43	4.0	0.18	2.2	4.2	0.19	5	3.4
STD DS7	Standard	0.074	12	231	1.01	403	0.112	37	1.03	0.103	0.45	3.9	0.19	2.3	4.1	0.20	5	3.8
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.077	7	10	0.58	238	0.123	<1	0.96	0.088	0.51	<0.1	<0.01	1.7	0.3	<0.05	5	<0.5
G1	Prep Blank	0.082	7	11	0.59	243	0.123	1	0.93	0.067	0.54	<0.1	<0.01	1.7	0.3	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: October 05, 2009
Report Date: October 19, 2009
Page: 1 of 6

CERTIFICATE OF ANALYSIS SMI09000314.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC-CO-09-07
P.O. Number
Number of Samples: 128

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200	122	Crush split and pulverize 250g drill core to 200 mesh			VAN
1DX15	128	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
935251	Drill Core	7.81	1.9	280.3	38.4	51	0.8	5.1	11.8	789	7.82	276.3	3.6	197.1	15.2	32	0.3	55.8	5.1	9	1.11
935252	Drill Core	6.76	0.4	137.4	79.8	53	1.3	4.2	34.5	705	6.57	628.8	8.4	595.6	19.2	35	0.4	52.8	8.3	11	1.60
935253	Drill Core	10.03	0.6	40.0	3.2	28	<0.1	4.9	14.0	377	3.82	96.4	3.8	32.4	23.6	32	<0.1	10.7	0.5	88	1.30
935254	Drill Core	9.28	1.5	23.0	4.0	37	<0.1	4.7	12.5	449	2.99	31.5	4.6	16.0	22.5	36	<0.1	3.1	0.4	92	1.05
935255	Drill Core	9.16	1.3	17.1	4.2	34	<0.1	3.0	8.9	332	2.48	45.3	4.6	24.2	21.0	31	<0.1	2.4	0.3	59	0.76
935256	Drill Core	8.45	0.9	55.3	14.2	265	0.1	3.6	11.1	464	3.16	568.0	4.8	51.3	12.3	49	2.1	933.6	8.9	44	1.54
935257	Drill Core	10.39	0.6	143.3	584.7	548	1.0	4.7	15.3	4841	4.07	567.8	3.3	172.6	14.2	62	3.0	296.1	2.0	25	2.92
935258	Drill Core	6.44	0.5	93.6	436.1	166	0.4	3.9	10.1	1994	3.21	185.3	3.0	50.4	12.2	61	0.9	258.7	2.6	43	2.14
935259	Drill Core	4.47	0.4	61.1	144.1	578	0.5	3.6	12.4	1382	3.23	2104	2.8	171.6	11.0	47	3.0	62.7	11.3	15	2.11
935260	Drill Core	9.97	0.4	19.0	4.3	33	0.2	3.3	8.8	380	2.58	6.7	3.4	3.3	9.7	38	<0.1	2.6	0.3	54	0.90
935261	Drill Core	7.92	0.4	20.8	3.5	43	<0.1	3.5	12.1	426	2.76	1457	4.2	49.7	10.3	39	<0.1	1.1	0.2	66	0.81
935262	Drill Core	10.88	0.5	31.9	12.8	38	0.2	3.7	11.7	426	3.10	113.0	3.3	53.9	6.0	38	<0.1	0.9	0.9	67	1.12
935263	Drill Core	7.74	0.4	27.0	3.1	38	<0.1	4.0	9.7	379	2.49	3.6	3.4	1.8	6.4	37	<0.1	0.4	0.1	71	0.73
935264	Drill Core	6.39	0.7	40.2	3.3	59	<0.1	5.3	16.3	556	3.79	5.0	2.5	5.7	5.4	33	<0.1	0.4	0.3	113	0.92
937387	Drill Core	8.37	1.8	9.6	3.3	29	<0.1	3.9	11.0	424	3.04	19.8	4.8	9.8	16.1	40	<0.1	1.1	0.5	60	1.95
937388	Drill Core	9.18	1.9	24.7	3.8	38	<0.1	4.4	11.3	474	3.15	174.4	4.4	16.7	16.2	50	<0.1	7.0	1.2	47	2.70
937389	Drill Core	9.04	1.1	13.3	3.4	34	<0.1	2.8	9.0	379	2.36	13.3	4.9	1.7	17.4	43	<0.1	2.2	0.1	55	1.23
937390	Drill Core	8.77	1.2	22.0	3.8	53	<0.1	4.3	12.8	1154	3.31	26.9	3.8	8.2	11.4	42	0.1	4.1	0.2	76	2.29
937391	Drill Core	9.73	1.6	26.4	5.3	682	<0.1	4.7	13.7	1605	3.33	39.7	4.0	6.9	10.9	51	6.0	0.8	0.3	86	1.53
937392	Drill Core	10.04	1.2	23.3	5.6	174	<0.1	5.1	14.4	1074	3.38	45.8	4.4	7.1	11.6	49	1.2	0.4	0.3	100	1.42
937393	Drill Core	8.50	1.4	22.7	58.2	78	0.3	4.5	13.3	835	3.09	5.8	4.5	<0.5	11.0	45	0.3	0.6	<0.1	95	1.21
937394	Drill Core	9.32	1.3	23.8	7.8	568	0.1	4.1	12.7	695	3.00	25.0	3.6	13.2	11.6	41	4.8	0.5	0.6	88	1.23
937395	Drill Core	4.32	0.6	53.6	70.2	>10000	1.1	5.1	14.2	1443	5.54	2968	3.1	54.8	13.4	42	179.7	8.0	4.0	61	1.66
937396	Drill Core	4.88	1.6	21.1	5.1	75	<0.1	4.1	11.2	429	2.71	5.4	4.3	0.9	10.7	33	0.5	0.4	0.1	78	0.99
937397	Drill Core	9.94	3.5	17.5	4.5	64	<0.1	4.6	11.8	442	2.81	4.3	3.9	0.7	12.7	40	0.2	0.5	<0.1	89	0.95
937398	Drill Core	10.40	1.3	21.3	4.5	52	<0.1	4.7	12.6	474	2.90	2.4	3.8	<0.5	13.2	38	0.1	0.2	<0.1	85	1.31
937399	Drill Core	9.77	1.2	38.4	11.0	50	0.1	4.6	12.9	464	3.22	8.9	4.6	7.9	13.5	41	<0.1	0.7	0.9	83	1.13
937400	Rock Pulp	0.07	434.6	3003	8.8	62	1.7	22.2	18.7	631	4.54	41.3	0.4	332.0	0.9	123	1.5	5.5	0.3	81	4.01
937401	Drill Core	4.18	1.2	25.9	4.3	57	<0.1	4.9	13.1	407	4.22	5.0	4.3	7.5	10.4	41	<0.1	2.1	0.1	84	1.12
937402	Drill Core	4.69	1.3	579.5	152.9	128	3.5	5.4	25.4	438	10.97	833.6	5.0	3458	10.8	33	0.9	10.4	19.4	34	1.16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
935251	Drill Core	0.055	4	6	0.55	20	<0.001	3	0.33	0.005	0.18	0.1	0.01	1.8	0.2	7.15	<1	1.2
935252	Drill Core	0.033	5	7	0.71	35	<0.001	3	0.32	0.004	0.19	0.2	0.02	1.9	0.2	6.15	<1	1.7
935253	Drill Core	0.065	19	19	1.10	249	0.104	<1	1.71	0.062	0.43	0.1	<0.01	7.9	0.5	0.62	6	<0.5
935254	Drill Core	0.056	20	21	0.98	340	0.173	<1	1.62	0.132	0.64	0.1	<0.01	5.4	0.6	0.22	5	<0.5
935255	Drill Core	0.037	20	15	0.69	166	0.118	1	1.25	0.095	0.50	0.1	<0.01	4.3	0.4	0.30	4	<0.5
935256	Drill Core	0.043	11	13	0.78	93	0.018	2	1.02	0.030	0.27	0.3	<0.01	5.9	0.4	1.25	3	0.6
935257	Drill Core	0.051	12	7	0.99	59	0.002	2	0.59	0.006	0.18	<0.1	<0.01	5.8	0.4	2.68	2	0.7
935258	Drill Core	0.044	20	11	0.81	123	0.010	2	0.88	0.022	0.21	<0.1	<0.01	6.7	0.3	0.96	3	<0.5
935259	Drill Core	0.044	14	5	0.62	60	<0.001	2	0.37	0.004	0.18	<0.1	<0.01	4.2	0.3	2.09	<1	0.8
935260	Drill Core	0.042	15	17	0.77	480	0.141	1	1.36	0.119	0.57	0.2	<0.01	4.2	0.5	0.24	4	<0.5
935261	Drill Core	0.053	16	18	0.83	824	0.168	<1	1.55	0.144	0.65	0.2	<0.01	3.4	0.5	0.15	5	<0.5
935262	Drill Core	0.056	12	16	0.85	277	0.149	1	1.45	0.110	0.57	0.2	<0.01	4.0	0.5	0.64	4	<0.5
935263	Drill Core	0.054	16	17	0.85	945	0.180	<1	1.51	0.142	0.61	0.2	<0.01	3.3	0.4	0.09	5	<0.5
935264	Drill Core	0.087	14	27	1.23	1443	0.266	<1	1.90	0.128	1.03	0.1	<0.01	5.0	0.7	0.14	6	<0.5
937387	Drill Core	0.043	16	16	1.00	110	0.035	<1	1.54	0.043	0.15	<0.1	<0.01	5.4	<0.1	0.37	6	0.5
937388	Drill Core	0.044	16	16	0.93	109	0.014	2	1.43	0.024	0.17	<0.1	<0.01	4.6	0.1	0.85	5	0.5
937389	Drill Core	0.044	18	13	0.74	257	0.109	1	1.51	0.113	0.22	0.2	<0.01	4.4	0.2	0.10	5	<0.5
937390	Drill Core	0.052	17	19	1.16	182	0.040	1	1.81	0.048	0.21	<0.1	<0.01	6.3	0.2	0.28	6	<0.5
937391	Drill Core	0.066	16	21	0.99	722	0.170	2	1.77	0.111	0.56	0.2	<0.01	5.6	0.4	0.25	6	<0.5
937392	Drill Core	0.071	15	22	1.10	644	0.185	1	1.97	0.127	0.54	0.3	<0.01	6.2	0.4	0.14	7	<0.5
937393	Drill Core	0.068	14	21	1.04	778	0.199	<1	1.92	0.141	0.58	0.3	<0.01	4.9	0.4	0.06	6	<0.5
937394	Drill Core	0.064	15	19	0.99	670	0.178	<1	1.72	0.118	0.65	0.2	<0.01	5.2	0.5	0.23	6	<0.5
937395	Drill Core	0.057	18	14	0.98	76	0.029	2	1.33	0.034	0.30	0.1	0.04	6.7	0.4	2.97	4	1.6
937396	Drill Core	0.062	16	19	0.94	470	0.181	<1	1.57	0.110	0.39	0.4	<0.01	4.0	0.3	<0.05	6	<0.5
937397	Drill Core	0.064	16	20	0.99	721	0.210	<1	1.81	0.149	0.59	0.3	<0.01	4.1	0.5	<0.05	6	<0.5
937398	Drill Core	0.063	19	19	1.02	255	0.176	2	1.74	0.119	0.21	0.3	<0.01	4.3	0.1	<0.05	6	<0.5
937399	Drill Core	0.068	15	21	1.00	437	0.156	2	1.78	0.112	0.35	0.4	<0.01	4.0	0.3	0.30	6	<0.5
937400	Rock Pulp	0.098	7	25	1.24	55	0.005	3	1.29	0.074	0.16	3.0	0.17	6.2	<0.1	1.65	5	6.5
937401	Drill Core	0.065	13	18	1.00	718	0.149	1	2.19	0.077	0.48	0.3	<0.01	5.3	0.3	0.12	7	<0.5
937402	Drill Core	0.059	5	9	0.77	36	0.002	2	0.84	0.003	0.18	0.2	<0.01	3.4	0.6	10.00	2	1.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937403	Drill Core	9.45	1.3	29.8	3.9	44	<0.1	4.3	12.4	404	3.00	3.3	4.0	5.1	9.7	51	<0.1	0.8	0.2	93	0.98
937404	Drill Core	8.30	0.9	26.5	3.6	44	<0.1	4.7	12.3	413	2.87	2.6	3.8	6.9	9.6	52	<0.1	0.2	<0.1	94	0.96
937405	Drill Core	9.83	1.0	31.2	2.6	44	<0.1	4.7	13.1	415	3.10	3.5	3.1	5.1	8.1	37	<0.1	0.2	0.2	101	0.89
937406	Drill Core	10.77	0.8	37.0	6.6	51	<0.1	5.3	14.4	536	3.66	5.4	2.6	2.9	7.9	51	<0.1	0.3	0.4	104	1.28
937407	Drill Core	9.21	1.0	41.9	3.4	48	0.1	5.1	14.6	529	3.77	15.4	4.7	18.7	8.3	51	<0.1	0.6	0.8	110	1.28
937408	Drill Core	9.21	1.3	43.2	3.7	48	<0.1	5.1	15.0	538	3.94	14.2	3.5	25.6	8.8	61	<0.1	0.7	0.8	103	1.53
937409	Drill Core	8.74	0.7	52.0	4.0	41	<0.1	5.2	14.4	399	3.63	27.5	3.1	22.6	12.6	46	<0.1	1.5	0.8	98	1.06
937410	Drill Core	10.00	1.1	37.2	4.4	44	<0.1	4.6	14.4	424	3.62	53.4	3.0	26.6	9.7	44	<0.1	1.4	1.0	100	1.17
937411	Drill Core	5.61	1.5	34.7	3.7	47	<0.1	4.8	13.7	442	3.34	107.3	3.6	6.6	10.3	45	<0.1	1.4	1.2	105	1.03
937412	Drill Core	9.92	1.1	20.1	4.3	40	<0.1	4.5	10.9	369	2.59	1.8	3.3	<0.5	11.6	52	<0.1	0.2	<0.1	83	0.92
937413	Drill Core	7.46	1.2	22.4	16.1	39	0.2	3.7	12.4	406	2.77	773.4	2.1	46.1	8.0	33	<0.1	1.5	0.9	67	1.08
937414	Drill Core	5.16	0.9	165.7	4.5	22	0.2	4.8	13.9	302	4.67	20.3	2.3	129.9	7.1	41	<0.1	3.4	7.5	61	1.41
937415	Drill Core	7.72	1.2	72.5	4.7	29	<0.1	4.5	14.4	423	3.92	40.6	3.9	74.4	9.1	40	<0.1	2.6	4.2	76	1.69
937416	Drill Core	7.21	1.3	87.2	12.1	35	0.4	4.9	14.1	374	5.79	200.0	3.1	108.6	7.7	32	0.1	4.4	20.9	56	1.21
937417	Drill Core	9.82	0.9	55.9	4.4	33	<0.1	4.1	12.3	371	3.65	23.0	2.6	32.5	9.4	33	<0.1	2.4	3.9	69	1.29
937418	Drill Core	8.66	1.5	141.5	10.0	51	0.3	6.9	19.1	528	6.58	157.3	3.7	94.4	9.8	19	<0.1	5.9	7.5	118	0.79
937419	Drill Core	8.72	0.9	86.0	9.2	29	0.1	3.7	8.4	390	2.84	65.8	6.4	22.0	19.1	52	0.1	3.7	6.4	29	1.23
937420	Rock Pulp	0.07	467.2	3097	8.3	62	1.6	22.6	19.2	646	4.56	42.9	0.4	234.6	1.0	118	1.5	4.9	0.3	83	4.01
937421	Drill Core	6.66	2.7	54.1	7.7	33	<0.1	3.1	7.1	270	2.69	26.9	6.6	27.6	20.2	46	<0.1	2.7	1.9	33	1.14
937422	Drill Core	3.84	1.9	74.2	5.5	22	0.1	2.9	11.9	1401	3.95	55.1	4.4	22.7	13.2	91	<0.1	4.6	2.0	34	7.28
937423	Drill Core	2.30	1.4	22.6	10.6	34	0.2	3.4	9.4	762	2.00	655.4	5.7	10.5	14.4	73	<0.1	5.6	0.4	28	3.80
937424	Drill Core	6.19	3.1	45.7	5.5	24	<0.1	3.2	8.7	373	2.58	343.0	6.5	27.3	17.2	38	<0.1	6.7	2.0	46	1.34
937425	Drill Core	6.18	1.9	23.3	5.0	34	<0.1	3.6	8.2	349	2.28	3.5	2.8	4.7	17.5	28	<0.1	0.3	0.1	57	0.81
937426	Drill Core	9.64	0.4	4.7	4.0	45	<0.1	3.4	9.2	452	2.44	3.2	3.4	0.7	8.6	49	<0.1	0.1	<0.1	54	0.86
937427	Drill Core	5.39	0.5	4.8	2.4	35	<0.1	1.3	4.8	260	1.87	1.0	3.5	<0.5	8.2	78	<0.1	<0.1	<0.1	27	0.89
937428	Drill Core	10.16	0.4	4.5	2.9	29	<0.1	0.9	4.1	251	1.64	1.8	3.4	0.7	8.4	113	<0.1	0.1	<0.1	20	1.02
937429	Drill Core	8.79	0.3	5.0	2.9	30	<0.1	1.1	4.7	238	1.73	1.3	3.6	<0.5	8.7	106	<0.1	<0.1	<0.1	22	1.02
937430	Drill Core	9.77	0.4	8.6	3.3	29	<0.1	0.8	4.4	329	1.76	4.0	3.7	<0.5	8.8	80	<0.1	0.5	<0.1	19	1.09
937431	Drill Core	9.39	0.6	4.6	9.7	41	<0.1	0.9	4.2	853	1.75	3.8	4.1	<0.5	11.3	78	0.2	0.3	<0.1	18	1.45
937432	Drill Core	6.48	0.3	17.8	16.1	35	0.3	0.8	4.9	979	2.62	2006	3.2	92.3	10.6	64	0.2	1.9	1.1	12	2.06

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937403	Drill Core	0.069	13	20	0.93	975	0.204	2	1.91	0.164	0.72	0.3	<0.01	4.4	0.5	0.13	6	<0.5
937404	Drill Core	0.067	11	20	0.97	979	0.219	<1	1.93	0.193	0.75	0.4	<0.01	4.2	0.5	0.07	6	<0.5
937405	Drill Core	0.075	12	22	1.05	950	0.221	1	1.77	0.134	0.81	0.3	<0.01	4.2	0.5	0.18	6	<0.5
937406	Drill Core	0.073	12	23	1.11	729	0.202	<1	2.08	0.175	0.76	0.3	<0.01	6.0	0.5	0.32	7	<0.5
937407	Drill Core	0.070	12	22	1.31	561	0.200	1	2.16	0.098	0.84	0.3	<0.01	7.0	0.6	0.35	7	<0.5
937408	Drill Core	0.066	11	21	1.25	329	0.187	1	2.22	0.128	0.75	0.2	<0.01	7.1	0.5	0.54	6	0.7
937409	Drill Core	0.071	13	21	1.10	298	0.187	<1	1.95	0.124	0.67	0.3	<0.01	5.7	0.5	0.64	6	<0.5
937410	Drill Core	0.075	12	22	1.06	294	0.192	2	1.92	0.144	0.60	0.2	<0.01	4.8	0.4	0.61	6	<0.5
937411	Drill Core	0.072	12	22	1.03	774	0.223	<1	1.89	0.143	0.81	0.3	<0.01	5.1	0.6	0.27	6	<0.5
937412	Drill Core	0.058	15	17	0.85	886	0.206	<1	1.85	0.199	0.68	0.4	<0.01	3.8	0.5	<0.05	6	<0.5
937413	Drill Core	0.052	17	14	0.87	214	0.132	2	1.42	0.093	0.39	0.3	<0.01	4.4	0.3	0.17	5	0.6
937414	Drill Core	0.047	12	15	1.06	103	0.029	2	1.53	0.029	0.28	0.1	<0.01	5.8	0.3	1.91	5	0.9
937415	Drill Core	0.051	15	16	1.19	172	0.049	2	1.80	0.040	0.29	0.1	<0.01	7.9	0.3	1.06	6	0.6
937416	Drill Core	0.056	10	11	0.78	49	0.009	1	1.43	0.012	0.23	0.1	<0.01	7.0	0.2	3.70	5	1.0
937417	Drill Core	0.049	14	15	0.96	172	0.071	1	1.70	0.039	0.36	0.1	<0.01	6.3	0.3	0.85	6	<0.5
937418	Drill Core	0.086	12	25	1.43	46	0.161	1	2.00	0.036	0.72	0.1	<0.01	8.5	0.5	2.42	6	0.8
937419	Drill Core	0.036	19	9	0.55	53	<0.001	1	0.82	0.003	0.11	<0.1	<0.01	4.8	0.1	0.81	2	<0.5
937420	Rock Pulp	0.100	7	27	1.26	60	0.006	4	1.37	0.074	0.18	2.7	0.16	6.6	<0.1	1.66	5	6.6
937421	Drill Core	0.038	22	9	0.57	63	0.003	<1	1.53	0.008	0.14	<0.1	<0.01	5.1	0.2	0.46	5	0.6
937422	Drill Core	0.028	36	7	1.35	80	0.005	<1	1.40	0.006	0.15	0.2	<0.01	4.4	0.2	0.74	4	0.9
937423	Drill Core	0.035	33	7	0.69	67	<0.001	<1	1.02	0.007	0.08	0.1	<0.01	5.8	<0.1	0.23	3	<0.5
937424	Drill Core	0.037	20	14	0.75	111	0.064	2	1.05	0.059	0.25	0.6	<0.01	4.2	0.2	0.57	4	<0.5
937425	Drill Core	0.037	22	17	0.70	187	0.136	2	1.28	0.092	0.41	0.1	<0.01	3.9	0.3	0.09	4	<0.5
937426	Drill Core	0.055	13	14	0.80	921	0.197	<1	1.59	0.184	0.64	0.2	<0.01	4.8	0.5	<0.05	5	<0.5
937427	Drill Core	0.041	15	10	0.42	1042	0.175	<1	1.73	0.252	0.45	0.2	<0.01	2.7	0.3	<0.05	5	<0.5
937428	Drill Core	0.039	15	7	0.35	871	0.152	2	1.81	0.279	0.33	0.2	<0.01	1.9	0.2	<0.05	5	<0.5
937429	Drill Core	0.040	15	8	0.37	923	0.162	1	1.86	0.289	0.35	0.2	<0.01	2.2	0.2	<0.05	6	<0.5
937430	Drill Core	0.037	16	5	0.36	757	0.128	<1	1.50	0.189	0.29	0.2	<0.01	2.1	0.2	0.10	5	<0.5
937431	Drill Core	0.034	17	7	0.33	758	0.105	2	1.57	0.202	0.34	0.2	<0.01	2.5	0.2	<0.05	5	<0.5
937432	Drill Core	0.035	15	4	0.27	150	0.023	2	0.97	0.072	0.22	0.1	<0.01	1.8	0.2	1.37	3	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937433	Drill Core	10.11	0.3	8.2	4.6	27	<0.1	0.9	4.0	564	1.64	7.3	3.1	3.2	10.2	72	<0.1	0.4	0.1	16	1.34
937434	Drill Core	7.88	0.4	7.7	7.6	22	<0.1	0.8	3.9	705	1.61	26.8	3.3	12.7	10.5	80	<0.1	0.8	0.2	17	1.89
937435	Drill Core	9.17	0.6	4.4	3.2	31	<0.1	1.6	4.8	288	1.86	2.7	3.1	<0.5	10.3	75	<0.1	0.2	<0.1	27	0.98
937436	Drill Core	9.74	0.7	3.5	3.5	25	<0.1	0.8	3.3	225	1.52	1.1	3.4	<0.5	13.3	93	<0.1	0.2	<0.1	18	0.86
937437	Drill Core	9.73	0.4	3.9	3.4	25	<0.1	0.7	3.7	274	1.68	11.9	3.6	0.6	10.0	89	<0.1	0.2	<0.1	18	1.06
937438	Drill Core	9.08	0.7	4.8	3.4	22	<0.1	0.8	3.3	250	1.56	70.1	2.9	3.0	10.1	83	<0.1	0.4	0.2	15	1.12
937439	Drill Core	10.07	0.6	11.7	4.4	25	<0.1	1.1	3.9	343	1.83	71.7	2.6	9.4	10.4	84	<0.1	0.6	0.3	19	1.40
937440	Rock Pulp	0.08	486.6	3134	10.2	68	1.7	24.0	19.3	675	4.61	46.6	0.5	312.5	1.1	133	1.4	6.7	0.4	84	4.23
937441	Drill Core	10.24	0.7	9.3	3.3	21	<0.1	0.7	3.1	199	1.35	3.6	3.0	<0.5	8.9	131	<0.1	<0.1	<0.1	15	0.95
937442	Drill Core	9.25	0.7	12.4	3.1	19	<0.1	0.6	2.8	184	1.32	123.5	2.8	8.5	8.8	114	<0.1	0.2	0.2	14	0.92
937443	Drill Core	9.42	1.0	10.1	5.8	21	<0.1	0.8	3.0	186	1.47	1565	3.0	76.7	9.0	132	<0.1	0.5	0.7	14	0.89
937444	Drill Core	9.29	5.3	6.6	7.3	21	<0.1	0.7	2.9	188	1.51	302.0	3.3	26.9	9.4	149	<0.1	0.2	1.0	14	0.89
937445	Drill Core	7.30	1.3	3.4	3.5	20	<0.1	0.9	3.0	205	1.33	3.3	3.7	1.1	11.5	166	<0.1	0.1	<0.1	15	1.05
937446	Drill Core	6.66	0.4	13.8	3.7	18	<0.1	0.7	3.0	179	1.64	645.3	4.4	30.2	10.7	94	<0.1	0.3	1.1	13	1.00
937447	Drill Core	7.95	0.3	4.7	4.4	23	<0.1	0.7	3.2	201	1.58	1355	3.4	61.8	10.1	104	<0.1	0.5	1.2	15	0.98
937448	Drill Core	10.22	0.3	8.4	3.6	19	<0.1	0.7	2.9	198	1.53	197.6	3.2	6.1	11.0	93	<0.1	0.2	0.3	14	1.06
937449	Drill Core	9.80	0.4	7.3	4.5	20	<0.1	0.7	2.9	209	1.31	25.0	4.0	1.4	11.1	99	<0.1	0.2	1.0	14	1.03
937450	Drill Core	9.07	0.2	8.6	4.6	21	<0.1	0.5	2.5	635	1.17	3.0	4.0	1.2	10.2	86	<0.1	0.4	0.2	10	1.46
937451	Drill Core	8.54	0.4	16.2	5.2	20	<0.1	0.8	2.7	762	1.23	2.5	3.7	2.0	9.3	98	<0.1	0.4	0.3	11	1.49
937452	Drill Core	8.89	0.4	8.6	3.6	21	<0.1	0.8	2.6	310	1.26	0.8	3.6	0.7	11.3	98	<0.1	0.3	0.4	12	1.21
937453	Drill Core	6.40	0.7	44.5	15.2	18	0.2	0.8	3.6	451	1.61	568.4	4.5	57.8	11.9	109	<0.1	2.3	2.2	3	3.07
937454	Drill Core	9.78	7.6	11.9	7.0	19	<0.1	0.9	2.5	284	1.14	8.9	9.1	3.4	15.6	94	<0.1	1.6	0.7	9	1.45
937455	Drill Core	8.65	0.8	14.6	8.6	15	<0.1	0.8	3.1	344	1.64	242.4	6.5	12.2	14.4	118	<0.1	6.0	0.7	6	1.71
937456	Drill Core	9.59	3.1	16.1	8.4	74	0.2	6.1	17.2	1670	4.03	192.0	3.9	5.5	11.5	59	0.1	6.9	0.5	52	0.50
937457	Drill Core	8.54	2.5	16.7	15.9	52	0.2	3.3	8.5	885	2.49	1398	4.4	34.4	17.9	46	0.3	7.4	1.2	15	0.40
937458	Drill Core	9.86	1.4	9.9	4.3	38	<0.1	2.9	8.2	433	2.13	4.5	5.0	0.6	18.1	59	<0.1	1.3	<0.1	49	1.04
937459	Drill Core	9.95	0.9	10.0	3.6	30	<0.1	2.1	6.9	481	1.98	7.3	3.7	1.4	14.6	78	<0.1	1.5	0.2	31	1.58
937460	Rock Pulp	0.08	6.5	78.6	4.2	53	0.6	234.1	12.9	167	2.67	177.7	0.1	217.2	0.6	7	0.1	14.1	<0.1	17	0.13
937461	Drill Core	10.51	1.8	24.1	3.1	47	<0.1	4.9	13.8	683	3.21	53.7	3.1	2.8	13.5	68	<0.1	1.1	<0.1	74	1.75
937462	Drill Core	10.48	0.5	29.6	3.6	148	<0.1	4.0	10.8	484	2.66	2.3	3.6	0.6	10.5	60	0.7	0.2	0.1	65	1.04

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937433	Drill Core	0.033	16	7	0.31	726	0.099	2	1.52	0.196	0.33	<0.1	<0.01	2.3	0.3	0.07	5	<0.5
937434	Drill Core	0.034	15	5	0.31	374	0.047	2	1.19	0.113	0.24	<0.1	<0.01	1.8	0.2	0.19	3	<0.5
937435	Drill Core	0.040	19	9	0.43	680	0.146	1	1.53	0.193	0.38	<0.1	<0.01	3.2	0.3	<0.05	5	<0.5
937436	Drill Core	0.034	22	6	0.31	607	0.122	1	1.47	0.208	0.33	<0.1	<0.01	2.1	0.2	<0.05	4	<0.5
937437	Drill Core	0.037	15	7	0.32	693	0.118	<1	1.58	0.218	0.33	<0.1	<0.01	2.5	0.2	<0.05	5	<0.5
937438	Drill Core	0.031	17	5	0.28	539	0.085	<1	1.47	0.205	0.26	0.6	<0.01	2.0	0.2	0.09	4	<0.5
937439	Drill Core	0.033	20	7	0.33	442	0.065	2	1.53	0.188	0.25	0.1	<0.01	2.8	0.2	0.17	5	<0.5
937440	Rock Pulp	0.117	8	26	1.27	67	0.007	4	1.41	0.077	0.19	3.1	0.17	6.8	<0.1	1.71	6	6.3
937441	Drill Core	0.026	15	8	0.26	763	0.138	<1	1.91	0.323	0.34	0.2	<0.01	1.8	0.2	<0.05	5	<0.5
937442	Drill Core	0.024	15	6	0.24	587	0.118	<1	1.64	0.269	0.27	0.2	<0.01	1.5	0.2	0.07	4	<0.5
937443	Drill Core	0.024	14	8	0.24	594	0.102	<1	1.55	0.237	0.28	0.3	<0.01	1.6	0.2	0.19	4	<0.5
937444	Drill Core	0.024	14	6	0.24	594	0.125	1	1.66	0.269	0.31	0.2	<0.01	1.6	0.2	0.28	4	<0.5
937445	Drill Core	0.024	20	9	0.26	721	0.132	<1	1.99	0.346	0.31	0.6	<0.01	1.9	0.2	<0.05	5	<0.5
937446	Drill Core	0.026	16	5	0.26	512	0.086	1	1.59	0.218	0.27	0.3	<0.01	1.4	0.2	0.36	4	<0.5
937447	Drill Core	0.026	17	7	0.30	626	0.109	<1	1.79	0.279	0.28	0.7	<0.01	1.5	0.2	0.28	5	<0.5
937448	Drill Core	0.026	18	5	0.27	529	0.093	1	1.62	0.240	0.26	0.6	<0.01	1.7	0.2	0.26	5	<0.5
937449	Drill Core	0.023	18	8	0.25	559	0.089	1	1.67	0.270	0.25	0.3	<0.01	1.8	0.2	<0.05	4	<0.5
937450	Drill Core	0.022	18	4	0.18	357	0.043	1	1.07	0.155	0.19	0.2	<0.01	1.4	0.1	0.06	3	<0.5
937451	Drill Core	0.023	17	7	0.20	419	0.052	2	1.31	0.200	0.20	1.3	<0.01	1.6	0.1	0.06	4	<0.5
937452	Drill Core	0.024	17	5	0.21	457	0.060	1	1.38	0.227	0.20	1.0	<0.01	1.7	0.2	<0.05	4	<0.5
937453	Drill Core	0.022	14	4	0.10	136	<0.001	2	0.59	0.035	0.19	10.3	<0.01	0.9	0.2	0.88	1	<0.5
937454	Drill Core	0.020	15	5	0.20	257	0.027	1	1.06	0.140	0.15	3.8	<0.01	1.9	0.1	0.08	3	<0.5
937455	Drill Core	0.025	16	4	0.24	117	<0.001	1	1.13	0.040	0.12	0.2	<0.01	1.0	0.2	0.41	3	<0.5
937456	Drill Core	0.070	17	11	0.24	66	0.002	1	0.79	0.011	0.11	0.7	0.32	8.4	2.1	1.35	3	<0.5
937457	Drill Core	0.042	25	6	0.16	77	<0.001	2	0.45	0.007	0.21	0.3	0.07	3.7	1.0	1.33	1	<0.5
937458	Drill Core	0.048	28	13	0.62	433	0.136	<1	1.16	0.096	0.35	0.1	<0.01	4.6	0.3	<0.05	4	<0.5
937459	Drill Core	0.036	22	12	0.56	355	0.063	2	0.96	0.072	0.31	0.1	<0.01	3.5	0.3	0.15	3	<0.5
937460	Rock Pulp	0.028	7	260	0.14	39	0.002	2	0.63	0.007	0.27	0.8	2.08	1.7	1.5	1.60	2	4.7
937461	Drill Core	0.076	18	17	1.02	744	0.173	2	1.35	0.087	0.58	0.1	0.02	3.7	0.6	0.27	5	<0.5
937462	Drill Core	0.064	19	18	0.85	675	0.188	2	1.52	0.152	0.59	0.2	<0.01	3.9	0.4	0.11	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937463	Drill Core	9.76	0.5	12.7	4.0	41	<0.1	3.0	8.7	418	2.36	1.2	4.8	1.3	34.1	51	<0.1	0.1	0.1	59	0.82
937464	Drill Core	3.57	0.5	13.6	3.8	35	<0.1	2.3	6.7	317	1.93	1.5	4.4	<0.5	13.5	60	<0.1	0.2	<0.1	45	0.82
937465	Drill Core	1.38	0.4	153.7	143.0	367	1.1	3.3	8.8	574	4.97	5038	3.0	149.0	12.5	85	2.6	8.3	5.7	31	1.60
937466	Drill Core	8.80	1.2	13.0	3.8	44	<0.1	3.7	9.4	442	2.47	36.1	3.9	3.1	16.4	57	<0.1	0.1	<0.1	66	0.92
937467	Drill Core	4.11	0.2	14.6	3.7	46	<0.1	3.7	10.4	468	2.74	3.9	4.2	1.7	10.1	57	<0.1	0.1	0.1	75	0.92
937468	Drill Core	10.35	0.4	23.9	4.4	48	<0.1	3.7	10.4	486	2.77	5.5	4.4	<0.5	8.6	58	<0.1	<0.1	<0.1	70	0.88
937469	Drill Core	4.59	0.3	33.6	4.1	44	<0.1	3.4	8.6	449	2.73	4.0	4.8	<0.5	8.2	47	<0.1	0.4	0.3	59	0.84
937470	Drill Core	8.07	0.3	76.2	4.1	46	<0.1	3.3	9.7	444	2.95	28.9	4.7	2.0	10.2	52	0.1	0.4	0.4	60	0.89
937471	Drill Core	7.56	1.0	24.6	4.1	49	<0.1	4.7	13.1	494	3.28	0.5	3.5	<0.5	10.1	49	<0.1	0.4	0.3	113	0.88
937472	Drill Core	10.31	1.0	30.9	4.7	132	<0.1	5.0	14.2	503	3.58	443.3	3.7	28.4	10.4	50	0.8	0.6	0.9	115	1.01
937473	Drill Core	10.19	1.0	28.1	4.0	50	<0.1	4.2	12.9	477	3.12	18.7	3.5	1.6	9.6	45	<0.1	0.5	0.3	105	0.84
937474	Drill Core	4.86	0.7	20.2	4.2	43	<0.1	4.3	11.1	443	2.81	<0.5	4.3	<0.5	12.0	51	<0.1	0.5	0.2	92	0.90
937475	Drill Core	5.74	1.0	14.8	5.0	36	<0.1	3.1	8.6	385	2.39	<0.5	5.9	<0.5	22.5	37	<0.1	0.6	0.3	68	0.87
937476	Drill Core	6.98	1.4	28.3	47.1	78	0.5	2.6	7.9	316	2.58	46.7	6.8	24.2	25.3	37	0.8	6.4	4.6	43	1.05
937477	Drill Core	8.85	2.2	52.5	37.5	73	0.6	2.7	10.4	299	3.72	172.4	7.5	158.2	27.2	27	0.9	20.9	5.2	6	1.35
937478	Drill Core	8.25	1.1	20.5	8.7	38	<0.1	4.8	14.2	355	4.65	13.9	5.5	38.9	11.4	45	0.1	15.2	0.9	84	1.73
937479	Drill Core	9.98	1.5	82.7	47.7	95	0.4	5.8	13.6	848	5.59	123.8	5.2	102.2	12.7	46	0.5	39.6	5.9	31	2.16
937480	Rock Pulp	0.08	6.4	77.3	5.5	52	0.5	241.9	12.8	163	2.66	173.5	0.2	241.5	0.6	6	0.1	15.0	0.2	17	0.15
937481	Drill Core	8.31	0.8	24.8	4.8	47	<0.1	4.4	12.3	502	3.10	1.4	4.6	1.1	12.0	54	<0.1	0.8	0.3	93	1.20
937482	Drill Core	10.23	0.5	18.3	4.5	49	<0.1	4.0	11.4	504	2.87	0.9	5.3	<0.5	13.7	43	<0.1	0.7	0.2	83	1.15
937483	Drill Core	9.60	1.1	27.8	4.0	48	<0.1	4.6	12.7	485	3.15	1.2	4.4	<0.5	11.8	56	<0.1	0.7	0.3	100	1.00
937484	Drill Core	9.89	1.4	27.1	4.1	50	<0.1	4.9	13.3	513	3.27	<0.5	4.4	<0.5	10.0	54	<0.1	0.5	0.3	107	1.00
937485	Drill Core	9.36	6.6	19.3	3.9	48	<0.1	4.6	12.7	523	3.23	1.4	5.0	0.5	13.3	63	<0.1	1.0	0.3	101	1.23
937486	Drill Core	9.08	0.6	29.1	4.4	46	<0.1	4.3	12.1	472	3.18	1.7	5.0	3.2	11.2	58	0.1	1.0	0.3	96	1.24
937487	Drill Core	9.28	0.4	24.9	4.1	44	<0.1	4.1	12.2	473	3.01	<0.5	4.2	<0.5	9.1	52	<0.1	0.7	0.2	95	1.05
937488	Drill Core	8.54	0.5	21.2	4.1	48	<0.1	4.2	13.4	568	3.19	5.3	4.7	<0.5	11.6	44	<0.1	1.7	0.2	94	1.43
937489	Drill Core	8.51	0.5	20.3	4.6	45	<0.1	4.3	12.8	568	3.23	20.7	4.1	<0.5	12.4	59	<0.1	1.6	0.2	98	1.54
937490	Drill Core	7.13	0.5	20.4	4.5	44	<0.1	4.1	11.3	433	2.85	<0.5	3.7	<0.5	9.6	53	<0.1	0.6	0.2	92	0.88
937491	Drill Core	8.02	0.4	20.3	4.5	47	<0.1	4.4	12.1	471	3.03	<0.5	5.0	<0.5	11.7	50	<0.1	0.7	0.2	97	0.95
937492	Drill Core	9.68	0.4	20.3	5.0	43	<0.1	4.2	12.3	473	3.07	1.7	4.4	4.0	13.2	56	<0.1	0.7	0.4	95	1.06

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937463	Drill Core	0.053	81	14	0.77	617	0.184	2	1.37	0.113	0.57	0.2	<0.01	3.7	0.4	<0.05	5	<0.5
937464	Drill Core	0.036	30	15	0.59	508	0.149	1	1.36	0.155	0.43	0.2	<0.01	3.2	0.3	<0.05	5	<0.5
937465	Drill Core	0.041	25	8	0.58	86	0.014	4	0.86	0.025	0.23	<0.1	0.02	4.1	0.6	2.48	3	0.8
937466	Drill Core	0.057	34	18	0.78	818	0.207	1	1.61	0.175	0.62	<0.1	<0.01	3.8	0.4	<0.05	6	<0.5
937467	Drill Core	0.063	18	17	0.87	1003	0.216	1	1.72	0.175	0.69	<0.1	<0.01	3.8	0.5	0.10	6	<0.5
937468	Drill Core	0.065	18	19	0.83	1006	0.219	2	1.70	0.185	0.74	<0.1	<0.01	4.2	0.6	<0.05	6	<0.5
937469	Drill Core	0.062	13	15	0.78	765	0.195	2	1.59	0.161	0.67	0.2	<0.01	3.3	0.5	0.06	5	<0.5
937470	Drill Core	0.060	17	16	0.81	835	0.202	2	1.65	0.164	0.64	0.2	<0.01	4.2	0.5	0.24	6	0.6
937471	Drill Core	0.084	12	22	1.11	963	0.260	2	1.95	0.176	0.98	0.4	<0.01	4.6	0.6	<0.05	6	<0.5
937472	Drill Core	0.089	13	24	1.21	761	0.230	1	1.99	0.158	0.91	0.4	<0.01	4.8	0.7	0.28	6	<0.5
937473	Drill Core	0.086	11	22	1.09	920	0.241	1	1.83	0.151	0.91	0.3	<0.01	3.9	0.6	0.10	6	<0.5
937474	Drill Core	0.067	15	21	0.96	718	0.230	1	1.82	0.188	0.82	0.3	<0.01	4.4	0.6	<0.05	6	<0.5
937475	Drill Core	0.049	34	15	0.73	537	0.181	1	1.41	0.125	0.65	0.2	<0.01	4.0	0.5	<0.05	5	<0.5
937476	Drill Core	0.040	26	13	0.51	228	0.082	3	1.06	0.070	0.42	0.2	0.02	3.6	0.4	0.90	3	<0.5
937477	Drill Core	0.031	8	6	0.40	69	<0.001	3	0.40	0.006	0.23	0.5	0.07	1.4	0.3	2.93	<1	<0.5
937478	Drill Core	0.070	14	19	1.11	160	0.078	2	2.22	0.036	0.38	0.2	0.01	8.6	0.5	0.55	6	<0.5
937479	Drill Core	0.078	9	11	0.57	57	<0.001	3	0.63	0.006	0.20	0.2	0.18	3.9	0.5	3.83	2	<0.5
937480	Rock Pulp	0.030	7	287	0.13	37	0.002	3	0.62	0.007	0.27	1.0	2.24	1.6	1.7	1.57	2	4.5
937481	Drill Core	0.076	14	19	0.97	778	0.201	<1	1.79	0.148	0.71	0.1	<0.01	5.0	0.5	<0.05	5	<0.5
937482	Drill Core	0.071	14	18	0.98	500	0.192	3	1.65	0.119	0.47	0.2	<0.01	4.2	0.4	<0.05	6	<0.5
937483	Drill Core	0.082	17	21	1.06	846	0.231	<1	1.96	0.181	0.82	0.1	<0.01	4.7	0.6	0.08	6	<0.5
937484	Drill Core	0.089	13	21	1.14	935	0.256	<1	2.01	0.174	0.89	0.1	<0.01	4.6	0.6	<0.05	6	<0.5
937485	Drill Core	0.077	18	21	1.08	730	0.217	<1	1.93	0.160	0.75	0.2	<0.01	5.5	0.6	0.08	6	<0.5
937486	Drill Core	0.074	12	19	1.10	696	0.191	<1	1.89	0.135	0.71	0.4	<0.01	5.7	0.6	0.11	6	<0.5
937487	Drill Core	0.081	11	21	1.04	768	0.229	<1	1.87	0.177	0.72	<0.1	<0.01	4.7	0.5	<0.05	6	<0.5
937488	Drill Core	0.083	13	21	1.14	535	0.173	<1	1.82	0.090	0.54	<0.1	<0.01	5.3	0.4	0.05	6	<0.5
937489	Drill Core	0.077	17	22	1.14	624	0.187	1	2.04	0.119	0.63	0.1	<0.01	5.8	0.5	0.08	6	<0.5
937490	Drill Core	0.076	14	19	0.98	825	0.225	<1	1.85	0.191	0.78	0.2	<0.01	3.6	0.5	<0.05	6	<0.5
937491	Drill Core	0.081	12	23	1.10	812	0.230	1	1.88	0.168	0.77	0.4	<0.01	4.2	0.5	<0.05	6	<0.5
937492	Drill Core	0.076	17	20	1.09	782	0.219	<1	1.87	0.168	0.74	0.2	<0.01	4.5	0.5	0.09	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
937493	Drill Core	10.01	0.8	23.9	4.3	46	<0.1	3.9	11.2	428	2.77	<0.5	4.9	<0.5	10.0	48	<0.1	0.5	0.2	86	0.86
937494	Drill Core	7.45	0.7	64.6	6.9	35	<0.1	5.9	15.9	472	4.61	3.3	5.9	65.5	15.0	70	<0.1	1.2	1.4	101	2.19
937495	Drill Core	10.43	0.7	36.0	5.8	46	<0.1	5.5	16.3	486	4.13	10.3	4.3	16.4	11.6	54	<0.1	0.8	1.0	124	1.43
937496	Drill Core	7.33	0.5	24.6	3.6	40	<0.1	4.5	12.8	429	3.23	1.5	5.2	4.8	11.6	55	<0.1	0.5	0.3	103	1.15
937497	Drill Core	10.14	0.3	34.5	3.8	37	<0.1	4.3	12.0	422	3.27	4.0	4.0	10.1	9.2	58	<0.1	0.7	0.3	91	1.40
937498	Drill Core	9.50	0.9	85.5	343.5	304	5.9	6.2	17.0	900	7.87	547.8	3.9	51.0	9.2	35	2.4	38.0	15.3	50	1.19
937499	Drill Core	12.05	3.2	600.5	772.5	230	30.4	4.4	20.9	1307	23.33	3267	4.6	1099	16.4	22	2.1	222.1	60.6	7	0.98
937500	Rock Pulp	0.07	2.9	39.9	21.2	80	0.2	24.4	10.4	733	3.63	6.2	0.3	<0.5	1.2	34	0.3	0.4	0.1	55	0.69

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000314.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
937493	Drill Core	0.072	13	20	0.97	719	0.219	1	1.69	0.163	0.71	0.2	<0.01	3.6	0.5	<0.05	5	<0.5
937494	Drill Core	0.079	14	22	1.31	201	0.108	3	1.89	0.068	0.59	<0.1	<0.01	8.1	0.5	1.15	6	<0.5
937495	Drill Core	0.090	16	24	1.35	511	0.208	2	1.94	0.110	0.81	0.1	<0.01	6.8	0.6	0.57	6	<0.5
937496	Drill Core	0.078	16	22	1.08	834	0.227	<1	1.89	0.172	0.83	0.2	<0.01	5.1	0.5	0.18	6	<0.5
937497	Drill Core	0.076	13	18	1.03	650	0.200	2	1.72	0.151	0.78	0.1	<0.01	4.8	0.5	0.34	5	<0.5
937498	Drill Core	0.083	9	11	0.80	26	0.048	2	0.88	0.047	0.41	0.1	<0.01	5.0	0.5	6.02	3	0.7
937499	Drill Core	0.046	3	3	0.33	13	<0.001	33	0.25	0.009	0.15	0.5	0.03	1.2	0.8	>10	<1	4.4
937500	Rock Pulp	0.070	6	27	0.95	71	0.128	2	2.06	0.068	0.12	0.2	<0.01	3.9	<0.1	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

QUALITY CONTROL REPORT SMI09000314.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
937400	Rock Pulp	0.07	434.6	3003	8.8	62	1.7	22.2	18.7	631	4.54	41.3	0.4	332.0	0.9	123	1.5	5.5	0.3	81	4.01
REP 937400	QC		445.0	3084	8.8	63	1.6	23.2	19.3	638	4.57	42.9	0.4	272.3	0.9	123	1.4	5.2	0.3	82	4.01
937440	Rock Pulp	0.08	486.6	3134	10.2	68	1.7	24.0	19.3	675	4.61	46.6	0.5	312.5	1.1	133	1.4	6.7	0.4	84	4.23
REP 937440	QC		484.5	3137	10.1	66	1.8	22.1	19.2	676	4.58	45.1	0.4	372.4	1.1	132	1.5	6.9	0.3	83	4.23
937484	Drill Core	9.89	1.4	27.1	4.1	50	<0.1	4.9	13.3	513	3.27	<0.5	4.4	<0.5	10.0	54	<0.1	0.5	0.3	107	1.00
REP 937484	QC		1.5	28.3	3.9	51	<0.1	5.0	13.5	517	3.28	<0.5	4.4	<0.5	10.0	53	<0.1	0.5	0.2	107	0.97
Core Reject Duplicates																					
937391	Drill Core	9.73	1.6	26.4	5.3	682	<0.1	4.7	13.7	1605	3.33	39.7	4.0	6.9	10.9	51	6.0	0.8	0.3	86	1.53
DUP 937391	QC		1.9	25.6	5.5	579	<0.1	5.0	13.9	1621	3.41	40.4	4.1	7.0	10.8	55	4.9	0.8	0.3	89	1.56
937426	Drill Core	9.64	0.4	4.7	4.0	45	<0.1	3.4	9.2	452	2.44	3.2	3.4	0.7	8.6	49	<0.1	0.1	<0.1	54	0.86
DUP 937426	QC		0.4	4.6	4.1	44	<0.1	3.4	8.9	450	2.48	1.4	3.2	0.6	8.4	51	<0.1	0.1	<0.1	56	0.91
937461	Drill Core	10.51	1.8	24.1	3.1	47	<0.1	4.9	13.8	683	3.21	53.7	3.1	2.8	13.5	68	<0.1	1.1	<0.1	74	1.75
DUP 937461	QC		1.1	23.1	2.9	48	<0.1	4.3	12.6	674	3.14	49.9	3.3	6.8	14.2	66	<0.1	1.1	<0.1	71	1.72
937496	Drill Core	7.33	0.5	24.6	3.6	40	<0.1	4.5	12.8	429	3.23	1.5	5.2	4.8	11.6	55	<0.1	0.5	0.3	103	1.15
DUP 937496	QC		0.4	24.8	4.4	39	<0.1	4.6	12.3	430	3.16	1.6	4.6	4.9	11.1	55	<0.1	0.5	0.3	103	1.15
Reference Materials																					
STD DS7	Standard		21.5	119.2	71.6	411	0.8	59.7	10.0	654	2.45	54.1	5.1	67.2	4.7	79	6.7	6.2	5.0	84	0.98
STD DS7	Standard		21.7	110.8	67.4	409	0.8	59.0	9.7	643	2.41	51.4	5.0	66.5	4.6	80	6.2	6.4	4.8	83	0.97
STD DS7	Standard		21.3	114.1	73.1	403	0.8	57.1	9.4	631	2.43	50.7	5.1	70.7	4.7	78	6.6	6.2	4.9	83	0.96
STD DS7	Standard		20.2	112.6	64.1	383	0.7	57.5	9.8	628	2.45	48.8	4.8	55.5	4.5	74	6.1	5.9	4.5	84	0.98
STD DS7	Standard		21.2	117.4	62.0	386	0.8	60.0	9.9	617	2.48	47.7	4.3	62.1	4.0	59	6.2	4.7	3.9	80	0.96
STD DS7	Standard		20.5	117.1	60.6	385	0.7	57.5	9.8	599	2.38	47.0	4.1	55.3	3.9	62	5.8	4.7	3.8	79	0.94
STD DS7	Standard		22.1	115.1	67.0	396	0.8	60.6	10.1	605	2.42	48.1	4.4	62.5	3.9	58	6.4	5.0	4.1	78	0.93
STD DS7	Standard		21.1	121.7	65.6	398	0.8	60.5	10.3	622	2.45	49.2	4.5	101.5	4.2	60	5.7	4.9	4.1	81	0.95
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

QUALITY CONTROL REPORT SMI09000314.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
937400	Rock Pulp	0.098	7	25	1.24	55	0.005	3	1.29	0.074	0.16	3.0	0.17	6.2	<0.1	1.65	5	6.5
REP 937400	QC	0.103	7	25	1.24	57	0.005	3	1.34	0.074	0.16	3.1	0.19	6.4	<0.1	1.66	5	6.3
937440	Rock Pulp	0.117	8	26	1.27	67	0.007	4	1.41	0.077	0.19	3.1	0.17	6.8	<0.1	1.71	6	6.3
REP 937440	QC	0.117	9	26	1.26	70	0.007	3	1.41	0.077	0.19	3.1	0.16	7.1	<0.1	1.70	5	6.2
937484	Drill Core	0.089	13	21	1.14	935	0.256	<1	2.01	0.174	0.89	0.1	<0.01	4.6	0.6	<0.05	6	<0.5
REP 937484	QC	0.093	13	22	1.13	920	0.254	<1	2.01	0.168	0.91	<0.1	<0.01	4.4	0.6	<0.05	6	<0.5
Core Reject Duplicates																		
937391	Drill Core	0.066	16	21	0.99	722	0.170	2	1.77	0.111	0.56	0.2	<0.01	5.6	0.4	0.25	6	<0.5
DUP 937391	QC	0.065	16	20	1.00	711	0.168	1	1.83	0.115	0.57	0.2	<0.01	5.6	0.5	0.26	6	<0.5
937426	Drill Core	0.055	13	14	0.80	921	0.197	<1	1.59	0.184	0.64	0.2	<0.01	4.8	0.5	<0.05	5	<0.5
DUP 937426	QC	0.056	13	15	0.81	870	0.204	<1	1.58	0.197	0.63	0.1	<0.01	5.2	0.5	<0.05	6	<0.5
937461	Drill Core	0.076	18	17	1.02	744	0.173	2	1.35	0.087	0.58	0.1	0.02	3.7	0.6	0.27	5	<0.5
DUP 937461	QC	0.073	19	17	1.00	701	0.167	2	1.32	0.083	0.55	0.1	0.02	3.8	0.6	0.27	5	<0.5
937496	Drill Core	0.078	16	22	1.08	834	0.227	<1	1.89	0.172	0.83	0.2	<0.01	5.1	0.5	0.18	6	<0.5
DUP 937496	QC	0.075	16	23	1.07	840	0.231	<1	1.89	0.170	0.84	0.5	<0.01	4.9	0.6	0.17	6	<0.5
Reference Materials																		
STD DS7	Standard	0.079	13	221	1.06	412	0.131	39	1.06	0.101	0.46	3.9	0.19	2.6	4.1	0.20	5	3.5
STD DS7	Standard	0.076	14	220	1.05	416	0.134	39	1.07	0.101	0.45	3.9	0.18	2.5	4.0	0.20	5	3.7
STD DS7	Standard	0.078	13	208	1.03	394	0.122	43	1.04	0.100	0.46	4.0	0.21	2.3	4.3	0.19	5	3.9
STD DS7	Standard	0.078	12	213	1.04	382	0.126	38	1.06	0.100	0.44	3.6	0.18	2.3	3.9	0.20	5	3.3
STD DS7	Standard	0.070	11	228	1.03	386	0.108	36	1.02	0.094	0.42	3.7	0.19	2.4	4.0	0.19	5	3.8
STD DS7	Standard	0.070	11	218	1.01	381	0.106	37	1.00	0.092	0.41	3.7	0.18	2.3	4.1	0.19	4	3.1
STD DS7	Standard	0.070	12	220	1.02	397	0.107	39	1.01	0.091	0.40	3.9	0.18	2.3	4.2	0.19	5	3.6
STD DS7	Standard	0.066	12	225	1.03	393	0.108	34	1.04	0.092	0.40	3.9	0.19	2.4	4.3	0.20	5	3.5
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

QUALITY CONTROL REPORT SMI09000314.1

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.2	1.8	2.4	47	<0.1	4.0	4.5	551	1.97	<0.5	1.4	<0.5	3.5	49	<0.1	<0.1	<0.1	38	0.49
G1	Prep Blank		0.3	2.7	2.9	48	<0.1	4.2	4.9	570	2.06	<0.5	1.5	<0.5	3.7	51	<0.1	0.3	<0.1	39	0.53

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

QUALITY CONTROL REPORT SMI09000314.1

		1DX15 P % 0.001	1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.078	6	11	0.60	249	0.117	<1	0.94	0.062	0.50	<0.1	<0.01	1.9	0.4	<0.05	5	<0.5
G1	Prep Blank	0.077	8	11	0.60	255	0.127	<1	1.02	0.087	0.51	<0.1	<0.01	2.0	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 19, 2009
Report Date: September 13, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000149.1

CLIENT JOB INFORMATION

Project: None Given
Shipment ID:
P.O. Number
Number of Samples: 1

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
VA475	1	Vegetation Ashing at 475	15	In Progress	VAN
WGHT	1	Weight of sample received			VAN
Split Ash from VA475	1	Analysis sample split/packet			VAN
Split Vegetation	1	Analysis sample split/packet			VAN
1VE	1	Aqua Regia digestion ICP-MS analysis	1	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: None Given
Report Date: September 13, 2009

CERTIFICATE OF ANALYSIS SMI09000149.1

Method		VA475	VA475	WGHT	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE
Analyte		Wt - Xtra	Weight	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi
Unit		g	g	g	ppm	ppm	ppm	ppm	ppb	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm
MDL		0.01	0.01	0.01	0.01	0.01	0.01	0.1	2	0.1	0.01	1	0.001	0.1	0.01	0.2	0.01	0.5	0.01	0.02	0.02
CRCM01	Moss				5.72	68.76	18.62	94.5	158	13.3	11.86	941	2.433	31.3	5.15	8.3	6.73	86.2	1.39	0.82	0.54

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: None Given
Report Date: September 13, 2009

CERTIFICATE OF ANALYSIS SMI09000149.1

	Method	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE
	Analyte	V	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Sc	Tl	S	Hg	Se	Te	Ga
	Unit	ppm	%	%	ppm	ppm	%	ppm	ppm	ppm	%	%	%	ppm	ppm	ppm	%	ppb	ppm	ppm	ppm
	MDL	2	0.01	0.001	0.01	0.1	0.001	0.1	1	1	0.01	0.001	0.01	0.1	0.1	0.02	0.01	1	0.1	0.02	0.1
CRCM01	Moss	47	1.07	0.226	16.36	17.7	0.633	321.6	718	3	2.03	0.044	0.43	0.3	3.8	0.29	0.13	<1	1.0	0.08	5.0

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: None Given
Report Date: September 13, 2009

QUALITY CONTROL REPORT SMI09000149.1

	Method	VA475	VA475	WGHT	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE
	Analyte	Wt - Xtra	Weight	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi
	Unit	g	g	g	ppm	ppm	ppm	ppm	ppb	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm
	MDL	0.01	0.01	0.01	0.01	0.01	0.01	0.1	2	0.1	0.01	1	0.001	0.1	0.01	0.2	0.01	0.5	0.01	0.02	0.02
Pulp Duplicates																					
CRCM01	Moss				5.72	68.76	18.62	94.5	158	13.3	11.86	941	2.433	31.3	5.15	8.3	6.73	86.2	1.39	0.82	0.54
REP CRCM01	QC				6.61	69.22	19.03	99.3	175	13.1	13.09	1040	2.457	34.6	5.17	8.0	7.22	89.5	1.42	0.81	0.55
Reference Materials																					
STD V14	Standard				0.04	4.17	0.70	13.4	23	1.1	0.76	2039	0.010	10.9	<0.01	4.5	<0.01	5.9	0.20	0.05	0.08
STD V16	Standard				1.66	7.02	2.72	37.1	31	7.3	1.23	688	0.457	1.5	<0.01	0.7	0.01	10.6	0.08	0.08	<0.02
STD V14 Expected					0.072	5.178	0.881	15.838	24	1.488	0.827	2147.12	0.016	11.038		8.633		6.668	0.227	0.067	0.089
STD V16 Expected					1.77	6.92	3.11	41.1	35	7.8	1.17	767	0.4367	1.7		1.1		12.4	0.093	0.07	
FLOUR	Blank				0.51	3.03	0.09	24.6	<2	0.2	<0.01	30	<0.001	<0.1	<0.01	<0.2	<0.01	0.9	0.03	<0.02	0.04
BLK	Blank				<0.01	<0.01	<0.01	<0.1	<2	<0.1	<0.01	<1	<0.001	<0.1	<0.01	<0.2	<0.01	<0.5	<0.01	<0.02	<0.02

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: None Given
Report Date: September 13, 2009

QUALITY CONTROL REPORT SMI09000149.1

	Method	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE	1VE
	Analyte	V	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Sc	Tl	S	Hg	Se	Te	Ga
	Unit	ppm	%	%	ppm	ppm	%	ppm	ppm	ppm	%	%	%	ppm	ppm	ppm	%	ppb	ppm	ppm	ppm
	MDL	2	0.01	0.001	0.01	0.1	0.001	0.1	1	1	0.01	0.001	0.01	0.1	0.1	0.02	0.01	1	0.1	0.02	0.1
Pulp Duplicates																					
CRCM01	Moss	47	1.07	0.226	16.36	17.7	0.633	321.6	718	3	2.03	0.044	0.43	0.3	3.8	0.29	0.13	<1	1.0	0.08	5.0
REP CRCM01	QC	50	1.05	0.223	17.00	19.1	0.633	332.6	720	4	2.03	0.045	0.44	0.7	4.0	0.31	0.11	<1	1.1	0.05	5.4
Reference Materials																					
STD V14	Standard	<2	0.58	0.080	<0.01	1.0	0.069	1.3	6	11	0.14	<0.001	0.48	<0.1	0.1	0.04	0.07	43	<0.1	<0.02	0.2
STD V16	Standard	<2	0.28	0.049	<0.01	349.9	0.046	2.9	11	5	0.04	0.001	0.23	<0.1	0.2	<0.02	<0.01	39	<0.1	0.02	0.1
STD V14 Expected			0.668	0.093	0.03	1.242	0.079	1.449	6.699	17.359	0.147	0.002	0.509		0.117	0.038	0.058	52	0.15		0.1
STD V16 Expected			0.3259	0.0541	0.05	345.2	0.0572	1.9	12	6	0.0498	0.0015	0.2455				0.0174	41			0.2
FLOUR	Blank	<2	0.02	0.345	<0.01	1.1	0.120	3.0	15	<1	<0.01	0.001	0.32	<0.1	0.2	<0.02	0.20	<1	0.6	<0.02	<0.1
BLK	Blank	<2	<0.01	<0.001	<0.01	<0.1	<0.001	0.6	<1	<1	<0.01	<0.001	<0.01	<0.1	<0.1	<0.02	<0.01	<1	<0.1	<0.02	<0.1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

4-Aug-09

Stewart Group
ECO TECH LABORATORY LTD.
10041 Dallas Drive
KAMLOOPS, B.C.
V2C 6T4

Phone: 250-573-5700
Fax : 250-573-4557

ICP CERTIFICATE OF ANALYSIS AW 2009- 8089

Mincord Exploration
110-325 Howe St
Vancouver, BC
V6C 1Z7

No. of samples received: 8
Sample Type: Rock
Project: Canadian Creek
Submitted by: Ron Dennett

Values in ppm unless otherwise reported

Et #.	Tag #	Au ppb	Ag ppm	Al %	As ppm	Ba ppm	Bi ppm	Ca %	Cd ppm	Co ppm	Cr ppm	Cu ppm	Fe %	Ga ppm	Hg ppb	K %	La ppm	Mg %	Mn ppm	Mo ppm	Na %	Ni ppm	P ppm	Pb ppm	S %	Sb ppm	Sc ppm	Se ppm	Sr ppm	Te ppm	Th ppm	Ti %	Tl ppm	U ppm	V ppm	W ppm	Zn ppm
1	79301	<5	<0.1	1.10	3.3	77.5	0.06	0.17	0.08	5.4	146.0	3.1	2.30	8.6	<5	0.73	20.0	0.61	422	0.41	0.067	9.7	405	7.92	<0.02	0.36	6.1	0.9	7.0	0.08	13.7	0.177	0.58	2.0	28	0.5	54.5
2	79302	<5	<0.1	0.53	1.8	70.0	0.12	0.06	0.02	2.2	141.0	3.2	1.11	3.6	<5	0.23	10.0	0.20	266	1.37	0.061	5.5	157	6.63	<0.02	0.28	2.0	0.3	5.0	0.06	17.8	0.034	0.22	2.4	10	1.8	24.9
3	79303	5	0.1	0.91	5.0	50.5	0.12	0.12	0.24	4.8	139.0	4.3	2.02	7.4	<5	0.44	26.0	0.50	422	0.44	0.059	8.8	356	8.91	<0.02	0.54	4.2	1.0	6.0	0.06	18.2	0.080	0.34	3.6	20	0.3	73.5
4	79304	<5	0.1	0.78	10.6	52.5	0.26	0.54	0.87	4.7	140.5	5.5	2.09	7.6	<5	0.18	41.5	0.31	679	0.45	0.058	8.4	392	13.93	0.04	1.60	2.8	1.3	13.5	0.04	17.6	0.016	0.18	3.7	16	0.4	81.3
5	79305	<5	<0.1	0.56	2.1	32.0	0.26	0.11	0.13	2.4	134.5	2.1	1.24	6.0	<5	0.30	23.5	0.23	196	0.75	0.058	5.9	280	5.21	<0.02	0.28	1.8	0.8	4.0	0.06	20.4	0.034	0.22	2.4	8	0.4	45.2
6	79306	<5	0.1	0.59	5.5	59.0	0.32	0.66	0.19	3.0	103.0	3.7	1.27	5.8	<5	0.24	33.0	0.24	340	0.25	0.054	6.2	468	7.92	0.06	1.54	1.2	1.0	16.0	0.08	23.3	0.015	0.16	2.5	6	0.2	41.7
7	79307	<5	<0.1	0.79	2.6	42.0	0.04	0.35	0.07	3.2	139.0	2.6	1.60	6.6	<5	0.35	25.5	0.34	310	1.46	0.073	6.2	240	3.95	0.06	0.48	3.5	1.0	10.0	0.06	16.4	0.052	0.24	3.3	14	0.2	30.9
8	79308	<5	<0.1	0.48	2.0	24.5	0.14	0.33	0.03	2.5	145.5	3.6	1.07	4.9	<5	0.19	22.0	0.19	231	0.77	0.058	5.8	227	5.42	0.04	0.34	1.5	0.8	8.0	0.04	17.8	0.013	0.12	6.7	6	0.2	26.7
QC DATA:																																					
Repeat:																																					
1	79301	<5	<0.1	1.12	3.3	75.5	0.04	0.16	0.07	5.4	145.5	3.1	2.33	8.4	<5	0.73	19.0	0.63	425	0.37	0.072	9.3	425	6.70	<0.02	0.36	6.2	0.9	7.0	0.10	13.2	0.175	0.52	1.9	28	0.4	54.1
Resplit:																																					
1	79301	<5	<0.1	1.13	3.3	75.5	0.02	0.17	0.07	5.4	145.0	2.8	2.36	8.5	<5	0.74	18.5	0.64	428	0.39	0.069	9.4	427	6.88	<0.02	0.36	6.2	0.9	7.0	0.12	12.9	0.178	0.54	1.9	28	0.3	53.8
Standard:																																					
Pb129a			11.7	0.79	5.8	60.5	0.42	0.49	57.55	5.1	11.5	1418.0	1.60	2.4	80	0.10	3.5	0.62	373	1.83	0.042	5.5	420	6171.00	0.79	15.72	0.7	0.3	24.0	0.24	0.5	0.032	0.06	<0.1	16	0.2	9996.0
SF30		835																																			

Aqua Regia Digest/ICPMS Finish

ECO TECH LABORATORY LTD.
Norman Monteith
B.C. Certified Assayer

NM/nw
df/msr8089s
XLS/09

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: July 31, 2009
Report Date: August 13, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000074.1

CLIENT JOB INFORMATION

Project: Canadian Creek (03)
Shipment ID:
P.O. Number
Number of Samples: 9

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	9	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	9	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP	Store After 90 days Invoice for Storage
DISP-RJT	Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek (03)
Report Date: August 13, 2009

CERTIFICATE OF ANALYSIS SMI09000074.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
793651	Rock	2.13	0.6	11.1	5.8	17	<0.1	1.5	1.5	176	0.98	2.4	3.0	1.2	14.2	3	<0.1	0.3	0.4	8	0.04
793652	Rock	1.63	0.2	24.8	14.5	60	0.2	2.8	3.0	370	1.35	4.3	4.5	3.2	23.1	13	0.1	0.8	0.6	8	0.32
793653	Rock	1.67	1.2	13.2	10.6	36	<0.1	4.3	4.3	348	1.71	1.0	2.7	7.4	17.5	5	0.1	1.6	2.3	17	0.10
793654	Rock	2.55	0.6	7.1	31.8	65	0.1	6.1	3.6	571	1.25	225.0	3.9	16.2	14.6	5	0.6	10.6	0.2	4	0.11
793655	Rock	2.42	1.5	96.3	3.5	75	0.1	26.9	18.9	662	5.00	5.0	2.1	<0.5	6.8	32	0.1	1.2	0.1	105	0.67
793656	Rock	1.91	0.8	48.5	45.4	61	1.8	6.6	6.2	451	2.16	2.5	4.9	4.4	22.9	12	0.2	4.7	5.2	22	0.41
793657	Rock	1.84	1.1	103.9	5.8	72	0.5	167.7	33.3	188	3.72	14.2	0.5	2.9	1.5	163	0.3	3.4	0.4	41	2.66
793658	Rock	1.63	1.7	42.5	7.3	62	0.3	8.9	2.2	129	2.90	3.7	0.5	1.0	2.7	9	0.2	1.0	0.2	111	0.06
793659	Rock	1.75	0.8	16.6	4.8	29	<0.1	4.9	4.0	352	1.47	3.6	3.7	0.9	15.9	9	0.4	1.6	0.3	8	0.30

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek (03)
Report Date: August 13, 2009

CERTIFICATE OF ANALYSIS SMI09000074.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
793651	Rock	0.013	8	11	0.21	38	0.027	2	0.45	0.027	0.17	<0.1	<0.01	1.4	0.1	<0.05	3	0.6
793652	Rock	0.023	25	16	0.26	69	0.018	2	0.58	0.027	0.20	<0.1	<0.01	1.5	0.2	0.08	3	<0.5
793653	Rock	0.034	23	16	0.45	54	0.112	<1	0.84	0.036	0.48	0.6	<0.01	3.3	0.4	<0.05	4	0.6
793654	Rock	0.034	26	15	0.10	67	<0.001	1	0.44	0.011	0.17	1.1	<0.01	1.2	0.2	<0.05	1	<0.5
793655	Rock	0.079	16	64	1.38	617	0.268	<1	2.31	0.084	0.60	0.4	<0.01	3.0	0.3	0.29	7	0.6
793656	Rock	0.056	44	23	0.53	70	0.136	3	0.93	0.050	0.52	>100	*	3.5	0.7	0.16	5	0.6
793657	Rock	0.195	9	83	0.87	173	0.185	2	4.01	0.241	0.10	0.6	<0.01	1.4	<0.1	1.28	9	4.6
793658	Rock	0.044	10	88	0.70	508	0.049	2	1.46	0.010	0.45	1.0	<0.01	4.4	0.2	0.14	5	2.0
793659	Rock	0.013	23	12	0.41	52	0.044	<1	0.83	0.039	0.35	0.4	<0.01	1.7	0.2	0.09	4	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek (03)
Report Date: August 13, 2009

QUALITY CONTROL REPORT SMI09000074.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Reference Materials																					
STD DS7	Standard		19.9	105.1	72.0	385	0.8	55.4	9.6	597	2.41	50.1	4.8	68.4	4.2	73	5.6	6.1	4.5	79	0.95
STD DS7	Standard		19.7	102.5	67.6	375	0.7	54.2	8.7	571	2.31	46.1	4.6	61.3	3.9	67	5.3	5.3	4.5	76	0.90
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.2	4.1	2.7	49	<0.1	3.7	4.6	579	2.07	0.5	1.8	1.2	3.9	65	<0.1	<0.1	0.1	39	0.55
G1	Prep Blank		0.4	36.6	2.6	54	<0.1	5.7	4.8	606	2.07	<0.5	1.7	4.3	4.1	54	<0.1	0.3	0.2	40	0.64

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek (03)
Report Date: August 13, 2009

QUALITY CONTROL REPORT SMI09000074.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																		
STD DS7	Standard	0.079	13	197	1.02	400	0.123	36	1.02	0.085	0.41	3.7	0.22	2.0	4.3	0.19	5	3.1
STD DS7	Standard	0.071	12	188	0.97	373	0.117	37	0.97	0.079	0.40	3.6	0.19	2.0	4.0	0.18	4	3.7
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.090	8	24	0.63	267	0.140	<1	1.06	0.088	0.56	<0.1	<0.01	2.3	0.4	<0.05	5	<0.5
G1	Prep Blank	0.100	7	24	0.68	273	0.140	1	0.97	0.061	0.55	0.1	<0.01	2.0	0.5	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: July 31, 2009
Report Date: August 17, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000075.1

CLIENT JOB INFORMATION

Project: Canadian Creek (03)
Shipment ID:
P.O. Number
Number of Samples: 25

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	25	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	25	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek (03)
Report Date: August 17, 2009

CERTIFICATE OF ANALYSIS SMI09000075.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
79309	Rock	1.84	0.5	18.7	8.9	81	<0.1	3.3	7.9	662	2.59	5.4	3.1	1.8	15.3	25	0.2	1.1	<0.1	62	0.40
79310	Rock	1.94	0.3	9.3	2.0	46	<0.1	2.8	7.4	513	2.56	<0.5	3.1	<0.5	17.0	24	<0.1	0.2	<0.1	66	0.46
79311	Rock	1.57	0.6	16.7	3.1	61	<0.1	6.9	13.1	508	3.37	2.9	1.8	<0.5	6.4	82	0.1	0.5	<0.1	102	1.06
79312	Rock	1.37	0.8	6.1	8.7	46	<0.1	8.6	7.1	396	2.39	1.3	0.4	1.4	2.0	20	0.2	0.3	0.2	35	0.68
79313	Rock	1.93	0.9	6.5	2.6	48	<0.1	2.9	7.3	494	2.46	1.8	1.5	2.3	7.1	41	0.1	0.2	<0.1	52	0.43
79314	Rock	1.59	0.2	19.8	18.3	23	0.1	1.3	0.8	89	0.28	16.1	1.7	4.1	9.6	3	0.2	0.9	0.2	<2	0.09
79315	Rock	2.19	0.3	3.8	8.0	17	<0.1	0.8	0.5	158	0.50	6.2	3.2	1.3	25.5	2	<0.1	0.3	0.4	<2	0.02
79316	Rock	1.59	0.2	3.2	12.0	58	<0.1	4.3	3.0	464	1.51	49.6	2.9	2.4	17.1	6	0.3	2.9	0.2	14	0.12
79317	Rock	1.94	0.4	8.5	14.9	36	0.5	1.4	0.7	117	0.52	25.6	6.7	18.4	26.9	3	<0.1	7.9	3.8	2	0.05
79318	Rock	1.03	0.2	1.2	12.1	9	<0.1	0.8	0.2	68	0.21	3.6	0.9	<0.5	1.7	1	0.1	0.2	<0.1	<2	0.06
79319	Rock	1.80	0.5	2.2	10.9	98	<0.1	6.1	5.1	474	2.02	5.2	2.8	<0.5	14.7	13	0.4	1.3	0.2	22	0.35
79320	Rock	1.66	<0.1	9.9	10.8	73	<0.1	9.7	6.0	425	2.07	4.4	2.4	<0.5	17.6	7	0.2	0.4	0.2	23	0.18
79321	Rock	1.69	0.2	1.5	8.6	25	<0.1	1.7	1.6	196	0.85	1.6	2.1	<0.5	12.4	5	<0.1	0.5	0.4	6	0.07
79322	Rock	2.08	0.5	1.7	3.8	40	<0.1	7.7	5.1	404	1.72	1.9	2.9	<0.5	17.2	11	0.2	0.3	0.4	19	0.26
79323	Rock	1.44	0.3	31.5	>10000	173	58.5	0.9	0.1	24	0.46	723.0	9.6	86.8	5.5	4	17.8	>2000	1.8	<2	<0.01
79324	Rock	1.99	1.1	2.4	26.2	44	<0.1	13.8	5.1	412	1.79	2.4	4.3	<0.5	18.2	9	0.2	7.5	0.7	20	0.22
79325	Rock	2.14	0.2	1.2	58.5	29	0.2	2.8	2.3	245	1.09	4.7	2.2	2.7	21.9	3	0.2	18.0	0.3	6	0.13
79326	Rock	1.89	0.7	7.6	5.3	40	<0.1	9.8	6.0	413	1.94	6.0	2.8	1.6	15.0	8	<0.1	0.8	0.1	25	0.18
79327	Rock	1.91	0.2	2.1	12.6	5	<0.1	1.0	0.2	55	0.23	3.0	4.7	0.9	2.3	<1	<0.1	4.2	2.3	<2	0.03
79328	Rock	2.34	0.2	4.0	4.1	11	<0.1	1.4	1.3	149	0.68	0.9	2.5	<0.5	10.1	3	<0.1	0.3	0.8	3	0.04
79329	Rock	2.08	1.1	0.9	7.5	44	<0.1	8.9	4.6	304	1.55	1.7	1.6	0.9	10.4	7	0.1	0.9	0.1	20	0.11
79330	Rock	2.09	0.1	5.7	7.0	8	<0.1	0.7	0.3	79	0.51	2.4	3.8	<0.5	25.6	2	<0.1	0.9	<0.1	<2	0.02
79331	Rock	1.83	1.0	11.2	13.8	151	<0.1	2.1	2.8	414	1.11	4.8	6.3	1.6	21.7	7	1.1	7.9	0.2	6	0.25
79332	Rock	1.78	0.1	42.8	30.6	247	0.3	3.4	3.6	573	1.84	2.9	5.9	2.2	21.3	8	1.4	8.4	1.0	16	0.31
79333	Rock	1.90	0.5	3.9	13.1	57	<0.1	1.7	2.0	349	1.09	4.8	4.1	<0.5	21.9	4	0.2	2.6	0.4	7	0.09

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek (03)
Report Date: August 17, 2009

CERTIFICATE OF ANALYSIS SMI09000075.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
79309	Rock	0.051	20	21	0.75	422	0.176	3	1.28	0.085	0.50	0.3	0.02	4.5	0.4	<0.05	4	<0.5
79310	Rock	0.052	27	20	0.72	479	0.180	3	1.27	0.098	0.60	<0.1	<0.01	4.1	0.5	<0.05	5	<0.5
79311	Rock	0.142	18	10	1.09	776	0.324	2	2.62	0.195	0.96	0.2	<0.01	2.3	0.5	<0.05	7	<0.5
79312	Rock	0.057	8	25	0.85	99	0.162	2	1.21	0.061	0.17	0.4	<0.01	3.1	<0.1	<0.05	5	<0.5
79313	Rock	0.054	13	15	0.66	557	0.197	3	1.63	0.176	0.75	<0.1	<0.01	3.1	0.5	<0.05	5	<0.5
79314	Rock	0.009	8	19	0.03	28	0.020	3	0.11	0.022	0.04	0.5	<0.01	0.5	<0.1	<0.05	<1	<0.5
79315	Rock	0.004	7	14	0.05	14	0.003	2	0.30	0.038	0.10	<0.1	<0.01	0.5	<0.1	<0.05	1	<0.5
79316	Rock	0.038	24	24	0.50	44	0.024	2	0.90	0.034	0.14	<0.1	<0.01	2.4	0.2	<0.05	5	<0.5
79317	Rock	0.008	7	15	0.06	44	0.006	2	0.30	0.032	0.10	2.3	<0.01	0.5	<0.1	<0.05	1	<0.5
79318	Rock	0.001	2	24	<0.01	16	<0.001	3	0.09	0.016	0.08	<0.1	<0.01	0.1	<0.1	<0.05	<1	<0.5
79319	Rock	0.046	36	24	0.62	83	0.138	2	1.16	0.041	0.56	0.2	<0.01	3.7	0.4	<0.05	6	<0.5
79320	Rock	0.044	30	30	0.54	51	0.083	2	0.99	0.035	0.39	<0.1	<0.01	3.1	0.3	<0.05	5	<0.5
79321	Rock	0.022	13	15	0.16	34	0.052	1	0.49	0.029	0.27	0.2	<0.01	1.5	0.2	<0.05	2	<0.5
79322	Rock	0.023	26	30	0.54	141	0.107	2	1.09	0.046	0.56	0.7	<0.01	2.8	0.3	<0.05	6	<0.5
79323	Rock	0.002	<1	25	<0.01	33	<0.001	3	0.09	0.002	0.09	<0.1	0.13	0.1	<0.1	0.38	<1	2.1
79324	Rock	0.027	28	36	0.60	111	0.131	2	1.00	0.048	0.63	0.8	<0.01	3.2	0.3	<0.05	6	<0.5
79325	Rock	0.056	29	17	0.43	39	0.019	2	0.77	0.027	0.24	<0.1	<0.01	0.7	0.2	<0.05	4	<0.5
79326	Rock	0.034	31	32	0.55	94	0.108	2	1.07	0.043	0.54	0.2	<0.01	3.7	0.4	<0.05	6	<0.5
79327	Rock	0.004	2	29	0.01	5	<0.001	1	0.06	0.007	0.03	0.3	<0.01	0.2	<0.1	<0.05	<1	<0.5
79328	Rock	0.015	13	22	0.12	31	0.006	2	0.31	0.026	0.12	<0.1	0.01	0.7	<0.1	<0.05	2	<0.5
79329	Rock	0.034	19	29	0.48	52	0.100	3	0.87	0.046	0.46	<0.1	<0.01	3.1	0.4	<0.05	5	<0.5
79330	Rock	0.002	4	16	0.02	10	0.001	1	0.21	0.031	0.11	<0.1	<0.01	0.5	<0.1	<0.05	<1	<0.5
79331	Rock	0.019	24	16	0.15	30	0.017	3	0.45	0.036	0.16	0.1	<0.01	1.5	0.1	<0.05	2	<0.5
79332	Rock	0.034	44	17	0.53	61	0.091	<1	0.93	0.045	0.52	0.2	<0.01	3.9	0.3	0.05	5	<0.5
79333	Rock	0.021	28	13	0.13	32	0.019	<1	0.40	0.030	0.16	<0.1	<0.01	1.6	0.1	<0.05	2	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek (03)
Report Date: August 17, 2009

QUALITY CONTROL REPORT SMI09000075.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
79330	Rock	2.09	0.1	5.7	7.0	8	<0.1	0.7	0.3	79	0.51	2.4	3.8	<0.5	25.6	2	<0.1	0.9	<0.1	<2	0.02
REP 79330	QC		0.2	5.9	6.8	7	<0.1	0.7	0.3	76	0.49	2.2	3.6	1.2	25.8	2	<0.1	0.8	<0.1	<2	0.02
79332	Rock	1.78	0.1	42.8	30.6	247	0.3	3.4	3.6	573	1.84	2.9	5.9	2.2	21.3	8	1.4	8.4	1.0	16	0.31
REP 79332	QC		0.2	44.1	30.4	250	0.3	3.5	3.8	571	1.83	2.8	6.0	1.7	21.7	8	1.3	8.5	1.0	16	0.31
Reference Materials																					
STD DS7	Standard		19.9	105.1	72.0	385	0.8	55.4	9.6	597	2.41	50.1	4.8	68.4	4.2	73	5.6	6.1	4.5	79	0.95
STD DS7	Standard		19.7	102.5	67.6	375	0.7	54.2	8.7	571	2.31	46.1	4.6	61.3	3.9	67	5.3	5.3	4.5	76	0.90
STD DS7	Standard		19.5	100.3	68.6	376	0.8	55.3	9.4	599	2.36	49.7	4.8	55.5	4.3	69	6.2	5.7	4.6	78	0.94
STD DS7	Standard		19.9	109.9	67.5	382	0.8	53.9	9.5	642	2.37	50.2	4.9	58.2	4.2	67	6.7	5.7	4.9	78	0.94
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.1	4.0	2.4	46	<0.1	4.6	4.8	613	2.06	1.1	1.8	<0.5	4.0	61	<0.1	<0.1	<0.1	40	0.58
G1	Prep Blank		<0.1	2.2	2.5	46	<0.1	4.1	4.1	545	1.96	0.7	1.7	1.5	3.9	60	<0.1	<0.1	<0.1	37	0.56

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek (03)
Report Date: August 17, 2009

QUALITY CONTROL REPORT SMI09000075.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
79330	Rock	0.002	4	16	0.02	10	0.001	1	0.21	0.031	0.11	<0.1	<0.01	0.5	<0.1	<0.05	<1	<0.5
REP 79330	QC	0.002	4	16	0.02	9	0.001	2	0.20	0.032	0.10	<0.1	<0.01	0.5	<0.1	<0.05	<1	<0.5
79332	Rock	0.034	44	17	0.53	61	0.091	<1	0.93	0.045	0.52	0.2	<0.01	3.9	0.3	0.05	5	<0.5
REP 79332	QC	0.037	46	18	0.53	63	0.092	<1	0.92	0.044	0.50	0.3	<0.01	3.7	0.4	0.06	5	<0.5
Reference Materials																		
STD DS7	Standard	0.079	13	197	1.02	400	0.123	36	1.02	0.085	0.41	3.7	0.22	2.0	4.3	0.19	5	3.1
STD DS7	Standard	0.071	12	188	0.97	373	0.117	37	0.97	0.079	0.40	3.6	0.19	2.0	4.0	0.18	4	3.7
STD DS7	Standard	0.073	12	198	1.02	413	0.110	38	1.00	0.104	0.44	4.0	0.20	2.3	3.9	0.19	5	3.6
STD DS7	Standard	0.076	11	197	1.03	431	0.109	36	1.00	0.100	0.41	3.9	0.19	2.2	4.2	0.19	4	3.4
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.085	8	16	0.62	265	0.146	<1	1.02	0.074	0.55	<0.1	<0.01	2.0	0.4	<0.05	5	<0.5
G1	Prep Blank	0.089	7	16	0.60	258	0.132	2	0.96	0.074	0.54	<0.1	<0.01	1.9	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 05, 2009
Report Date: August 26, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000101.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 22

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	22	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	22	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 26, 2009

CERTIFICATE OF ANALYSIS SMI09000101.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
173660	Rock	2.16	3.5	93.5	11.7	24	<0.1	3.3	1.6	288	0.73	1.8	1.2	6.1	36.9	12	0.2	0.2	1.0	7	0.28
173661	Rock	2.35	12.5	110.7	6.4	25	0.6	1.8	3.1	299	4.95	7.3	0.8	115.5	7.5	43	<0.1	0.5	3.2	57	0.26
173662	Rock	2.16	18.0	238.0	3.9	42	0.2	13.9	13.8	468	3.94	6.8	1.8	40.3	19.1	24	<0.1	0.4	1.1	99	0.54
173663	Rock	1.99	6.2	97.2	2.0	27	0.1	27.1	1.9	239	2.64	4.1	0.6	9.2	6.1	5	<0.1	0.2	1.2	33	0.05
173664	Rock	1.86	35.9	103.0	3.7	34	0.2	5.5	9.9	348	4.53	11.7	0.9	39.4	5.1	26	<0.1	0.5	7.5	62	0.41
173665	Rock	2.10	0.7	9.4	6.8	35	<0.1	8.8	5.6	551	1.81	6.4	2.8	<0.5	14.2	6	0.2	2.0	0.7	20	0.14
173666	Rock	1.66	0.5	15.8	77.7	12	6.3	4.3	2.5	123	0.99	5.4	1.1	4.8	4.9	3	<0.1	1.8	35.0	7	0.05
173667	Rock	1.58	0.6	2.4	7.7	24	<0.1	2.5	2.0	227	0.96	<0.5	2.0	<0.5	17.1	3	<0.1	0.2	0.3	3	0.08
173668	Rock	1.05	0.3	4.1	6.6	11	<0.1	1.4	1.1	81	0.78	10.7	3.6	<0.5	12.7	10	<0.1	0.7	1.9	<2	0.06
173669	Rock	2.75	0.6	4.8	11.0	22	<0.1	1.0	1.2	31	1.00	11.2	2.7	<0.5	5.1	12	<0.1	3.0	0.2	13	0.03
173670	Rock	1.99	0.3	4.3	9.1	12	0.2	2.1	1.9	410	0.79	35.5	1.9	1.8	12.8	15	<0.1	1.4	0.3	7	0.38
173671	Rock	1.72	0.2	2.6	4.4	29	<0.1	6.2	4.1	246	1.54	<0.5	1.2	<0.5	17.0	5	<0.1	0.2	0.2	16	0.09
173672	Rock	2.07	0.3	9.3	14.7	36	<0.1	5.2	4.5	243	1.68	1.8	1.3	<0.5	14.0	9	<0.1	<0.1	0.5	19	0.19
173673	Rock	1.97	1.2	13.5	9.1	13	<0.1	2.0	1.8	97	0.68	24.2	1.9	<0.5	10.5	6	<0.1	0.6	0.2	2	0.05
L9200 12025N	Rock	0.82	0.9	27.3	8.7	68	0.2	16.3	5.9	229	2.49	5.6	1.1	<0.5	7.6	3	0.2	0.9	0.2	65	0.10
79334	Rock	1.91	0.5	4.8	54.8	72	<0.1	10.7	6.1	527	2.02	1.6	2.9	<0.5	19.1	7	0.1	0.2	0.5	24	0.15
79335	Rock	1.74	0.4	3.2	3.1	8	<0.1	1.4	0.6	61	0.85	43.4	1.2	1.3	7.8	6	<0.1	0.8	0.8	6	0.05
79336	Rock	1.52	3.6	2.5	17.5	26	<0.1	0.8	0.5	39	0.58	70.8	4.7	4.1	16.5	52	<0.1	2.7	0.3	2	0.01
79337	Rock	1.43	0.3	1.0	7.3	10	<0.1	0.6	0.4	73	0.48	3.9	2.0	0.7	22.3	2	<0.1	0.5	0.3	<2	0.02
79338	Rock	1.67	1.3	13.5	3.6	23	<0.1	2.5	4.6	359	1.53	1.8	5.9	<0.5	36.6	31	<0.1	0.8	0.3	27	0.54
79339	Rock	1.35	0.3	2.0	8.1	23	<0.1	1.1	0.7	213	0.80	2.0	1.7	<0.5	13.0	5	<0.1	0.7	0.4	<2	0.04
79340	Rock	1.33	0.2	6.0	9.3	26	0.1	3.1	2.5	94	1.52	2.6	2.2	<0.5	15.9	7	<0.1	0.2	0.3	34	0.30

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 26, 2009

CERTIFICATE OF ANALYSIS SMI09000101.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
173660	Rock	0.016	32	8	0.10	476	<0.001	2	0.55	0.047	0.24	<0.1	<0.01	0.3	0.1	<0.05	2	<0.5
173661	Rock	0.061	5	20	1.31	137	0.103	1	1.67	0.047	0.20	0.3	<0.01	4.9	0.2	0.66	8	1.3
173662	Rock	0.079	33	30	1.66	262	0.169	1	2.40	0.094	1.00	<0.1	<0.01	10.7	0.7	0.52	9	0.7
173663	Rock	0.027	7	48	0.77	196	0.006	2	1.58	0.003	0.31	<0.1	<0.01	1.9	0.2	0.09	5	<0.5
173664	Rock	0.076	6	23	1.56	177	0.058	4	2.47	0.079	0.32	<0.1	<0.01	5.4	0.2	0.81	8	0.7
173665	Rock	0.041	24	20	0.28	57	0.038	<1	0.75	0.024	0.34	0.1	0.01	2.9	0.3	<0.05	4	<0.5
173666	Rock	0.015	6	24	0.08	30	0.007	2	0.37	0.016	0.16	0.1	<0.01	0.8	0.1	<0.05	2	<0.5
173667	Rock	0.030	28	11	0.02	37	0.001	2	0.25	0.020	0.17	0.5	<0.01	0.9	<0.1	<0.05	<1	<0.5
173668	Rock	0.013	14	14	<0.01	162	0.001	2	0.29	0.015	0.12	0.4	0.17	0.4	<0.1	0.25	<1	<0.5
173669	Rock	0.027	5	7	<0.01	77	<0.001	3	0.92	0.002	0.03	0.1	0.93	2.1	0.5	<0.05	2	<0.5
173670	Rock	0.021	14	9	0.02	745	<0.001	2	0.59	0.003	0.18	<0.1	0.83	1.2	0.6	<0.05	1	<0.5
173671	Rock	0.028	14	18	0.32	54	0.062	1	0.63	0.050	0.41	0.1	<0.01	3.6	0.2	<0.05	4	<0.5
173672	Rock	0.041	26	19	0.49	93	0.102	<1	1.05	0.066	0.67	0.1	0.02	3.8	0.5	<0.05	6	<0.5
173673	Rock	0.015	12	17	0.04	102	0.004	2	0.53	0.050	0.21	<0.1	0.06	0.8	0.2	<0.05	2	<0.5
L9200 12025N	Rock	0.046	17	66	0.89	119	0.014	2	1.63	0.011	0.27	<0.1	<0.01	2.8	0.1	<0.05	5	<0.5
79334	Rock	0.038	18	26	0.35	84	0.102	1	0.93	0.060	0.61	0.1	<0.01	4.2	0.4	<0.05	5	<0.5
79335	Rock	0.019	16	13	0.07	281	0.011	2	0.36	0.025	0.21	<0.1	<0.01	0.8	0.3	<0.05	2	<0.5
79336	Rock	0.017	27	10	<0.01	55	<0.001	3	0.55	0.001	0.14	0.3	0.21	1.0	<0.1	<0.05	2	<0.5
79337	Rock	0.003	5	9	0.02	16	0.002	<1	0.22	0.025	0.10	0.2	<0.01	1.1	<0.1	<0.05	<1	<0.5
79338	Rock	0.023	30	20	0.50	104	0.070	1	1.08	0.071	0.17	0.3	<0.01	2.0	0.1	<0.05	4	<0.5
79339	Rock	0.014	28	5	0.07	86	0.009	2	0.51	0.046	0.17	0.3	<0.01	0.7	0.1	<0.05	3	<0.5
79340	Rock	0.051	15	12	0.21	58	0.089	2	0.54	0.045	0.24	4.6	<0.01	1.4	<0.1	<0.05	3	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 26, 2009

QUALITY CONTROL REPORT SMI09000101.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Reference Materials																					
STD DS7	Standard		19.3	100.8	53.6	383	1.0	53.8	8.9	627	2.37	48.0	4.1	65.4	3.8	67	5.6	4.8	4.1	79	0.97
STD DS7	Standard		20.9	108.7	59.1	387	0.7	57.2	9.2	647	2.45	49.8	3.9	66.0	3.9	70	5.8	4.5	4.0	82	1.02
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.2	3.3	6.7	49	<0.1	4.3	4.6	603	2.13	<0.5	1.5	<0.5	3.5	54	<0.1	<0.1	0.2	41	0.59
G1	Prep Blank		0.2	19.1	5.7	48	<0.1	3.9	4.7	595	2.06	<0.5	1.5	1.0	3.6	79	<0.1	0.2	0.2	40	0.63

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 26, 2009

QUALITY CONTROL REPORT SMI09000101.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																		
STD DS7	Standard	0.073	12	215	1.02	408	0.101	39	1.04	0.097	0.43	3.9	0.19	2.2	4.2	0.19	5	3.3
STD DS7	Standard	0.075	13	216	1.09	409	0.105	38	1.09	0.100	0.46	3.5	0.19	2.5	4.1	0.19	5	3.6
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.084	8	12	0.63	259	0.124	<1	1.06	0.083	0.55	<0.1	<0.01	2.1	0.4	<0.05	5	<0.5
G1	Prep Blank	0.083	9	12	0.63	278	0.125	1	1.05	0.082	0.58	0.2	0.01	2.1	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 06, 2009
Report Date: August 17, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000111.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 14

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	14	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	14	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP	Store After 90 days Invoice for Storage
DISP-RJT	Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

CERTIFICATE OF ANALYSIS SMI09000111.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
173674	Rock	1.85	1.4	75.8	9.3	24	0.2	14.7	1.9	107	2.14	49.0	0.8	22.7	5.2	12	0.1	0.6	2.6	27	0.02
173675	Rock	1.71	0.9	6.0	3.5	7	<0.1	<0.1	0.7	65	0.81	10.8	1.5	3.5	20.7	19	<0.1	0.2	1.1	4	0.10
173676	Rock	1.78	4.8	78.6	8.7	58	0.1	55.3	12.7	375	3.52	89.3	1.0	9.4	5.6	5	0.3	0.5	0.6	116	0.16
173677	Rock	1.92	0.9	26.8	10.9	8	0.3	1.6	1.8	89	1.28	16.6	2.4	116.7	15.4	5	<0.1	0.5	1.3	6	0.14
173678	Rock	1.63	0.6	7.2	8.5	25	<0.1	4.6	2.9	163	1.22	4.2	2.6	1.8	17.6	14	<0.1	0.7	0.3	12	0.11
173679	Rock	1.65	0.4	15.3	6.5	14	<0.1	2.2	2.3	115	1.76	10.5	7.5	9.3	19.1	11	<0.1	1.2	0.7	14	0.17
173680	Rock	1.64	0.3	5.0	18.0	3	0.2	0.7	0.5	28	1.09	43.9	1.0	81.2	8.0	9	<0.1	0.8	7.6	<2	0.02
173681	Rock	1.33	0.8	38.0	5.5	4	0.2	0.9	0.5	27	2.25	83.2	1.2	34.7	28.0	26	<0.1	1.2	2.3	5	0.02
79341	Rock	1.43	0.4	3.1	9.4	50	0.1	6.6	5.0	274	1.61	23.2	5.1	9.6	16.7	8	0.2	1.1	0.4	22	0.25
79342	Rock	1.57	0.9	6.5	8.2	8	<0.1	0.6	0.6	25	0.64	15.2	2.7	3.3	30.5	4	<0.1	0.6	0.7	<2	0.03
79343	Rock	1.68	0.5	92.0	13.4	7	0.2	1.5	0.7	32	1.11	12.7	2.5	130.9	17.3	11	<0.1	0.7	13.2	4	0.04
79344	Rock	1.23	0.2	19.0	2.2	3	<0.1	1.5	0.7	46	0.37	4.7	1.0	12.5	5.5	3	<0.1	0.2	0.8	<2	0.04
79345	Rock	1.90	0.6	71.5	4.3	8	0.1	2.5	1.3	35	1.07	8.9	1.2	649.7	17.0	14	<0.1	0.8	3.2	5	0.04
79346	Rock	1.71	0.5	1.8	4.1	1	<0.1	0.5	0.2	25	0.53	9.1	0.7	11.1	6.7	4	<0.1	0.6	0.8	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

CERTIFICATE OF ANALYSIS SMI09000111.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
173674	Rock	0.021	12	33	0.43	183	0.011	<1	0.95	0.009	0.23	<0.1	<0.01	1.4	0.2	0.10	4	1.2
173675	Rock	0.011	5	8	0.16	99	0.001	<1	0.60	0.071	0.11	0.2	<0.01	0.7	<0.1	<0.05	2	<0.5
173676	Rock	0.057	6	98	1.29	265	0.228	<1	1.95	0.025	1.07	0.6	<0.01	6.9	0.5	0.57	8	2.1
173677	Rock	0.046	13	11	0.08	50	0.083	<1	0.31	0.047	0.12	8.5	<0.01	1.3	<0.1	0.06	1	0.6
173678	Rock	0.029	12	12	0.35	64	0.043	<1	0.75	0.060	0.28	<0.1	<0.01	2.3	0.2	<0.05	4	<0.5
173679	Rock	0.043	8	12	0.40	69	0.107	<1	0.76	0.054	0.25	0.2	<0.01	2.3	0.2	<0.05	4	<0.5
173680	Rock	0.012	13	9	0.03	40	0.002	77	0.18	0.051	0.11	0.1	<0.01	0.5	<0.1	0.20	<1	<0.5
173681	Rock	0.040	23	8	0.08	315	0.002	3	0.39	0.050	0.47	0.2	<0.01	0.6	0.2	0.67	3	0.7
79341	Rock	0.059	26	19	0.60	255	0.115	3	0.88	0.065	0.53	0.7	<0.01	3.2	0.4	0.07	5	<0.5
79342	Rock	0.006	11	7	0.02	31	0.002	<1	0.28	0.042	0.10	0.1	<0.01	0.5	<0.1	<0.05	<1	<0.5
79343	Rock	0.019	27	7	0.15	46	0.003	1	0.46	0.037	0.15	<0.1	<0.01	0.9	0.1	0.06	3	<0.5
79344	Rock	0.019	2	13	0.07	23	0.004	<1	0.21	0.017	0.09	<0.1	<0.01	0.4	<0.1	<0.05	<1	<0.5
79345	Rock	0.023	23	9	0.11	69	0.005	2	0.50	0.066	0.17	<0.1	<0.01	1.1	0.1	0.12	3	<0.5
79346	Rock	0.005	8	12	<0.01	64	<0.001	3	0.18	0.004	0.21	0.1	0.03	0.2	0.1	0.12	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

QUALITY CONTROL REPORT SMI09000111.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
173680	Rock	1.64	0.3	5.0	18.0	3	0.2	0.7	0.5	28	1.09	43.9	1.0	81.2	8.0	9	<0.1	0.8	7.6	<2	0.02
REP 173680	QC		0.3	5.0	17.3	4	0.2	0.8	0.5	30	1.04	44.9	1.0	65.9	8.4	9	<0.1	0.8	7.9	<2	0.02
Reference Materials																					
STD DS7	Standard		18.7	99.3	63.1	372	0.8	54.1	9.3	601	2.32	48.9	4.6	69.2	4.1	66	6.1	5.4	4.6	75	0.91
STD DS7	Standard		21.2	101.0	69.5	390	0.9	53.8	9.5	598	2.32	54.1	4.9	64.1	4.5	74	6.6	6.0	4.7	78	0.93
STD DS7	Standard		18.3	105.3	65.4	382	0.7	51.8	8.4	590	2.30	50.1	4.5	68.9	4.1	67	5.9	6.0	4.9	79	0.89
STD DS7	Standard		17.8	104.2	65.4	385	0.8	52.6	8.8	611	2.33	49.6	4.3	67.3	4.1	67	5.7	5.8	4.8	80	0.91
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		4.4	2.8	80.1	156	0.5	3.5	4.2	544	1.86	0.9	1.6	0.8	3.5	54	1.4	0.1	1.0	37	0.53
G1	Prep Blank		0.5	2.2	8.3	51	<0.1	2.7	4.2	541	1.97	<0.5	1.6	<0.5	3.5	67	<0.1	<0.1	0.2	39	0.56

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

QUALITY CONTROL REPORT SMI09000111.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
173680	Rock	0.012	13	9	0.03	40	0.002	77	0.18	0.051	0.11	0.1	<0.01	0.5	<0.1	0.20	<1	<0.5
REP 173680	QC	0.013	13	9	0.03	41	0.002	78	0.18	0.049	0.12	0.1	<0.01	0.3	<0.1	0.19	<1	<0.5
Reference Materials																		
STD DS7	Standard	0.080	11	187	0.99	388	0.102	41	0.95	0.102	0.40	3.6	0.18	2.3	3.8	0.18	4	3.1
STD DS7	Standard	0.085	12	174	1.00	411	0.112	40	0.98	0.100	0.43	3.8	0.19	2.4	4.1	0.19	5	3.7
STD DS7	Standard	0.076	11	180	1.00	380	0.106	38	0.96	0.085	0.40	3.8	0.19	2.1	4.1	0.18	4	3.2
STD DS7	Standard	0.077	11	175	1.02	369	0.106	36	0.99	0.084	0.42	3.9	0.16	2.0	4.2	0.19	5	3.9
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.081	7	9	0.58	253	0.123	<1	0.96	0.065	0.52	<0.1	0.01	1.8	0.5	<0.05	5	<0.5
G1	Prep Blank	0.075	8	16	0.58	242	0.127	<1	1.05	0.087	0.54	<0.1	<0.01	1.9	0.3	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 06, 2009
Report Date: August 17, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000115.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 11

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	11	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	11	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

CERTIFICATE OF ANALYSIS SMI09000115.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
79347	Rock	2.39	1.6	25.1	3.5	4	<0.1	0.8	2.5	38	1.24	0.8	8.0	0.7	16.3	13	<0.1	0.1	0.2	5	0.10
79348	Rock	1.64	0.3	49.2	2.6	20	<0.1	2.7	7.9	199	2.74	1.5	2.1	3.4	12.5	22	<0.1	0.2	0.2	61	0.60
79349	Rock	1.61	0.7	7.4	6.8	1	0.1	0.5	0.3	23	0.95	39.7	0.8	97.6	8.8	12	<0.1	4.7	0.2	4	0.02
173682	Rock	1.75	0.4	42.6	7.1	29	<0.1	2.4	5.0	190	2.89	14.8	3.0	20.6	14.7	19	<0.1	0.4	0.6	57	0.23
173683	Rock	1.86	0.7	22.0	10.7	32	0.1	1.4	4.8	141	4.17	110.0	1.5	126.0	11.0	13	<0.1	0.7	33.3	58	0.04
173684	Rock	1.61	1.5	8.0	5.1	13	0.2	1.1	1.8	84	1.61	24.3	0.9	16.7	5.7	9	<0.1	0.6	1.5	9	0.04
173685	Rock	1.40	1.3	12.5	6.8	2	0.6	0.4	0.7	22	2.17	41.6	0.4	187.6	4.1	8	<0.1	0.4	4.3	4	0.01
173686	Rock	2.01	10.9	14.0	54.8	148	0.4	5.5	7.2	3932	2.74	153.9	9.4	1.8	22.2	26	1.1	6.2	0.1	31	0.21
173687	Rock	2.38	17.0	16.3	41.8	211	0.4	7.0	7.7	7387	3.63	277.5	13.3	3.0	19.4	29	1.8	9.6	0.2	33	0.21
173688	Rock	1.95	3.3	35.4	2.0	8	<0.1	1.6	5.1	156	1.52	29.4	0.7	5.8	4.3	6	0.1	0.7	0.2	6	0.22
173689	Rock	1.50	4.1	251.8	3.5	9	0.4	2.8	20.0	45	4.22	725.1	1.6	50.7	6.5	16	<0.1	10.7	1.5	8	0.04

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

CERTIFICATE OF ANALYSIS SMI09000115.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
79347	Rock	0.006	3	9	0.12	118	0.005	1	0.30	0.015	0.15	<0.1	<0.01	0.7	<0.1	0.88	<1	0.6
79348	Rock	0.053	20	11	0.93	162	0.081	<1	1.41	0.081	0.51	<0.1	<0.01	5.2	0.3	0.83	5	<0.5
79349	Rock	0.012	7	5	0.02	269	<0.001	4	0.38	0.007	0.27	0.1	0.22	0.4	0.4	0.42	1	<0.5
173682	Rock	0.049	13	10	0.84	252	0.026	2	1.28	0.074	0.19	<0.1	<0.01	5.0	0.2	0.26	7	<0.5
173683	Rock	0.049	11	8	0.64	177	0.004	<1	1.32	0.026	0.14	0.1	<0.01	3.5	0.1	0.28	8	<0.5
173684	Rock	0.019	7	5	0.13	306	0.001	13	0.43	0.015	0.21	0.2	<0.01	1.0	0.1	0.15	1	0.7
173685	Rock	0.015	18	3	0.02	153	0.001	18	0.22	0.014	0.50	0.4	<0.01	0.4	0.2	0.91	<1	0.9
173686	Rock	0.046	43	5	0.19	670	0.015	3	0.71	0.023	0.28	0.7	0.11	4.5	0.7	<0.05	3	<0.5
173687	Rock	0.047	57	7	0.10	897	0.004	2	0.70	0.010	0.19	0.6	0.20	5.5	1.0	<0.05	2	<0.5
173688	Rock	0.024	8	6	0.11	123	<0.001	1	0.36	0.007	0.20	<0.1	0.04	0.7	0.4	1.07	<1	0.8
173689	Rock	0.024	11	4	0.07	17	0.002	3	0.51	0.008	0.35	0.1	0.08	1.2	1.2	4.31	<1	3.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

QUALITY CONTROL REPORT SMI09000115.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
173686	Rock	2.01	10.9	14.0	54.8	148	0.4	5.5	7.2	3932	2.74	153.9	9.4	1.8	22.2	26	1.1	6.2	0.1	31	0.21
REP 173686	QC		10.0	14.1	54.0	142	0.4	5.2	6.9	3918	2.70	151.4	9.1	1.9	20.5	24	1.0	5.9	0.1	31	0.19
Reference Materials																					
STD DS7	Standard		20.6	107.9	70.6	405	0.8	59.2	9.9	615	2.45	53.9	5.0	63.2	4.5	73	6.7	6.2	4.7	86	1.00
STD DS7	Standard		21.1	104.1	68.1	412	0.8	57.5	9.5	590	2.37	56.1	4.7	90.3	4.5	74	6.6	6.0	4.6	82	0.97
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<0.1	2.4	2.6	49	<0.1	4.2	4.6	572	2.02	0.5	1.8	1.8	4.4	62	<0.1	<0.1	0.1	42	0.59
G1	Prep Blank		<0.1	2.8	2.5	46	<0.1	3.9	4.7	556	2.09	0.9	1.8	<0.5	4.3	58	<0.1	<0.1	0.1	43	0.58

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

QUALITY CONTROL REPORT SMI09000115.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
173686	Rock	0.046	43	5	0.19	670	0.015	3	0.71	0.023	0.28	0.7	0.11	4.5	0.7	<0.05	3	<0.5
REP 173686	QC	0.041	40	6	0.18	649	0.014	2	0.69	0.021	0.26	0.7	0.10	4.6	0.6	<0.05	3	<0.5
Reference Materials																		
STD DS7	Standard	0.092	13	199	1.07	406	0.115	40	1.05	0.095	0.47	3.8	0.20	2.6	4.3	0.20	5	3.1
STD DS7	Standard	0.084	14	181	1.03	401	0.112	44	1.02	0.088	0.46	3.9	0.20	2.2	4.0	0.19	5	3.5
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.113	9	13	0.63	253	0.132	1	1.05	0.088	0.58	<0.1	<0.01	2.2	0.4	<0.05	5	<0.5
G1	Prep Blank	0.097	8	14	0.61	239	0.128	2	1.05	0.089	0.55	<0.1	<0.01	2.2	0.3	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 06, 2009
Report Date: August 17, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000116.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 21

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	21	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	21	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

CERTIFICATE OF ANALYSIS SMI09000116.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L9600 12675N	Rock	1.77	0.6	3.4	5.1	27	<0.1	3.6	3.8	224	1.58	1.5	4.5	0.7	18.5	19	<0.1	0.4	0.2	9	0.41
L9600 12700N	Rock	1.88	0.6	8.0	3.0	38	<0.1	4.6	4.5	250	1.84	1.1	3.2	<0.5	15.1	9	<0.1	0.4	0.3	16	0.29
L9600 12850N	Rock	1.39	0.5	4.6	4.8	46	<0.1	10.9	6.6	394	2.12	0.8	2.5	<0.5	13.0	6	0.2	0.5	0.1	27	0.12
L9600 12875N	Rock	0.76	0.3	6.3	9.0	43	<0.1	3.6	3.7	333	1.63	1.5	3.0	<0.5	21.1	7	0.1	0.8	0.3	15	0.12
L9800 12525N	Rock	1.13	0.4	3.9	20.9	86	<0.1	5.6	3.5	308	1.34	5.5	3.3	1.7	18.9	4	0.1	1.9	0.3	13	0.07
L9800 12550N	Rock	1.58	0.1	5.8	5.0	24	<0.1	2.2	2.2	279	1.10	1.5	3.7	<0.5	25.2	10	0.1	2.8	0.4	5	0.28
L9800 12675N	Rock	1.94	0.3	276.2	404.3	100	17.7	3.2	0.9	498	0.45	309.6	0.8	28.5	3.2	3	1.1	256.5	1.8	<2	0.18
L10000 12650N	Rock	0.77	0.4	2.2	3.5	25	<0.1	12.4	4.6	257	1.53	2.3	2.6	<0.5	10.5	11	<0.1	1.2	0.2	22	0.17
L10000 12675N	Rock	1.37	0.3	2.4	6.5	31	0.1	7.7	3.8	378	1.37	1.9	3.2	1.1	16.9	8	0.2	1.8	0.3	13	0.18
L10000 12700N	Rock	1.17	0.2	2.6	5.6	14	<0.1	1.1	0.4	271	0.37	5.5	0.3	<0.5	1.1	<1	0.1	2.2	<0.1	<2	0.03
L10000 12725N	Rock	1.73	0.3	2.3	5.2	50	<0.1	15.0	7.2	424	1.84	2.7	1.9	<0.5	12.9	18	0.2	0.9	0.3	25	0.47
L10000 12750N	Rock	1.02	1.2	43.7	11.2	34	0.2	4.1	5.0	450	2.23	1.4	4.8	0.8	16.2	9	<0.1	0.6	0.8	25	0.21
L10000 12775N	Rock	2.02	0.8	21.0	1.5	29	<0.1	56.4	13.6	366	2.29	1.5	1.7	2.6	12.3	26	<0.1	0.7	<0.1	77	0.89
L10000 12800N	Rock	1.45	0.6	9.0	4.7	48	<0.1	11.7	6.8	421	2.30	1.5	1.9	1.2	13.0	5	<0.1	0.4	0.2	31	0.10
L10200 12500N	Rock	2.14	1.3	6.4	3.1	42	<0.1	3.0	3.5	265	1.37	3.5	2.8	1.3	17.4	6	0.2	0.5	0.5	14	0.11
L10200 12525N	Rock	1.50	0.4	3.1	7.5	39	<0.1	2.4	2.4	185	1.18	3.0	2.5	1.3	26.3	5	0.2	0.5	0.3	8	0.10
L10200 12575N	Rock	1.96	1.4	5.7	9.4	57	<0.1	3.6	4.0	337	1.63	43.9	2.3	<0.5	18.3	4	0.2	0.5	0.8	15	0.08
L10200 12625N	Rock	1.96	0.2	4.5	10.5	129	<0.1	5.3	4.8	281	1.91	2.3	3.1	<0.5	19.7	16	2.1	2.8	0.2	20	0.21
L10200 12975N	Rock	1.64	0.4	2.5	4.8	45	<0.1	10.1	6.1	432	2.19	0.9	1.7	<0.5	13.8	6	<0.1	0.2	0.2	29	0.11
L10200 13025N	Rock	1.59	0.3	3.4	10.4	37	<0.1	6.9	4.1	302	1.47	3.1	3.3	1.1	14.7	6	0.1	1.0	0.2	11	0.09
L10200 13175N	Rock	1.55	0.5	5.6	13.6	79	<0.1	10.0	6.7	466	2.07	20.6	2.4	0.7	15.4	6	0.3	0.9	0.2	21	0.11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

CERTIFICATE OF ANALYSIS SMI09000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L9600 12675N	Rock	0.020	32	14	0.38	41	0.036	1	0.73	0.031	0.28	0.1	<0.01	2.0	0.2	<0.05	4	<0.5
L9600 12700N	Rock	0.038	27	19	0.46	60	0.104	2	0.92	0.041	0.50	0.1	<0.01	3.6	0.3	0.08	5	<0.5
L9600 12850N	Rock	0.034	24	29	0.57	99	0.140	1	1.13	0.049	0.71	0.5	<0.01	4.0	0.4	<0.05	6	<0.5
L9600 12875N	Rock	0.034	33	14	0.34	63	0.090	<1	0.77	0.053	0.48	0.2	<0.01	3.3	0.4	<0.05	4	<0.5
L9800 12525N	Rock	0.024	18	20	0.30	45	0.047	1	0.67	0.038	0.33	0.1	<0.01	2.0	0.2	<0.05	4	<0.5
L9800 12550N	Rock	0.019	28	14	0.21	39	0.005	2	0.52	0.033	0.18	<0.1	<0.01	1.2	<0.1	<0.05	3	<0.5
L9800 12675N	Rock	0.005	5	22	0.02	40	<0.001	2	0.10	0.001	0.07	<0.1	0.01	0.3	<0.1	0.09	<1	<0.5
L10000 12650N	Rock	0.043	13	40	0.52	121	0.109	1	0.97	0.066	0.64	4.4	<0.01	3.5	0.4	<0.05	5	<0.5
L10000 12675N	Rock	0.027	28	25	0.41	59	0.051	1	0.82	0.044	0.34	0.2	<0.01	2.1	0.2	<0.05	5	<0.5
L10000 12700N	Rock	0.003	1	12	<0.01	22	<0.001	1	0.05	<0.001	0.04	<0.1	<0.01	0.1	<0.1	<0.05	<1	<0.5
L10000 12725N	Rock	0.036	27	41	0.65	111	0.094	1	1.16	0.051	0.56	0.3	<0.01	3.6	0.3	<0.05	5	<0.5
L10000 12750N	Rock	0.037	16	21	0.42	71	0.099	<1	0.88	0.063	0.44	2.7	<0.01	3.2	0.3	0.17	5	<0.5
L10000 12775N	Rock	0.169	8	129	1.30	239	0.218	1	1.29	0.078	0.62	0.3	<0.01	2.6	0.3	<0.05	5	<0.5
L10000 12800N	Rock	0.037	26	27	0.60	78	0.170	2	1.33	0.043	0.91	0.9	<0.01	4.4	0.6	<0.05	7	<0.5
L10200 12500N	Rock	0.021	25	17	0.59	69	0.104	2	0.94	0.044	0.61	0.2	<0.01	2.7	0.4	<0.05	5	<0.5
L10200 12525N	Rock	0.034	27	17	0.24	24	0.038	2	0.55	0.037	0.29	0.1	<0.01	1.9	0.2	<0.05	4	<0.5
L10200 12575N	Rock	0.035	13	14	0.29	40	0.089	1	0.73	0.040	0.43	0.3	<0.01	3.0	0.4	<0.05	4	<0.5
L10200 12625N	Rock	0.047	35	19	0.46	405	0.079	<1	0.73	0.049	0.45	0.3	<0.01	3.9	0.3	<0.05	5	<0.5
L10200 12975N	Rock	0.042	27	28	0.57	94	0.176	<1	1.22	0.052	0.94	0.4	<0.01	4.7	0.5	<0.05	7	<0.5
L10200 13025N	Rock	0.034	28	16	0.25	46	0.006	2	0.72	0.035	0.16	<0.1	<0.01	1.9	0.1	<0.05	4	<0.5
L10200 13175N	Rock	0.040	27	25	0.48	58	0.066	1	1.00	0.039	0.37	0.2	<0.01	2.9	0.3	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

QUALITY CONTROL REPORT SMI09000116.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Reference Materials																					
STD DS7	Standard		18.7	99.3	63.1	372	0.8	54.1	9.3	601	2.32	48.9	4.6	69.2	4.1	66	6.1	5.4	4.6	75	0.91
STD DS7	Standard		21.2	101.0	69.5	390	0.9	53.8	9.5	598	2.32	54.1	4.9	64.1	4.5	74	6.6	6.0	4.7	78	0.93
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.2	4.6	2.2	43	<0.1	3.5	4.5	529	1.91	<0.5	1.6	<0.5	3.7	51	<0.1	<0.1	<0.1	36	0.49
G1	Prep Blank		0.1	4.0	2.3	47	<0.1	3.6	4.2	538	1.95	<0.5	1.5	<0.5	3.7	56	<0.1	<0.1	<0.1	37	0.52

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 17, 2009

QUALITY CONTROL REPORT SMI09000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																		
STD DS7	Standard	0.080	11	187	0.99	388	0.102	41	0.95	0.102	0.40	3.6	0.18	2.3	3.8	0.18	4	3.1
STD DS7	Standard	0.085	12	174	1.00	411	0.112	40	0.98	0.100	0.43	3.8	0.19	2.4	4.1	0.19	5	3.7
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.087	7	12	0.57	246	0.118	1	0.92	0.074	0.52	<0.1	<0.01	1.9	0.4	<0.05	5	<0.5
G1	Prep Blank	0.091	8	11	0.58	237	0.122	2	0.97	0.080	0.53	<0.1	<0.01	2.0	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 13, 2009
Report Date: August 26, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000131.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 6

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	6	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	6	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP	Store After 90 days Invoice for Storage
DISP-RJT	Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 26, 2009

CERTIFICATE OF ANALYSIS SMI09000131.1

Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
173690 Rock	1.99	3.0	20.6	7.0	7	<0.1	2.0	1.1	50	0.88	4.8	3.3	20.4	42.0	6	<0.1	1.3	1.0	3	0.04
173691 Rock	2.09	0.7	19.2	50.7	18	0.5	0.8	0.6	27	1.54	13.3	1.4	17.8	14.7	11	<0.1	5.7	1.5	<2	<0.01
173692 Rock	1.64	0.5	3.0	2.8	2	<0.1	1.0	0.2	29	0.36	12.5	0.5	9.6	2.2	2	<0.1	0.5	0.5	<2	<0.01
173693 Rock	1.69	0.9	22.1	5.9	6	<0.1	1.0	0.4	35	0.62	2.7	3.1	13.0	23.5	4	<0.1	2.0	0.6	<2	0.02
173694 Rock	2.00	0.8	10.1	7.5	12	<0.1	1.2	0.4	30	0.88	7.9	1.3	5.0	16.6	5	<0.1	3.1	0.8	<2	0.02
173695 Rock	2.57	33.0	102.8	5.2	10	0.4	2.1	13.8	23	5.02	743.0	2.4	210.0	4.1	11	<0.1	16.1	1.6	6	0.05

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 26, 2009

CERTIFICATE OF ANALYSIS SMI09000131.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
173690	Rock	0.012	15	7	0.06	28	0.007	1	0.40	0.034	0.15	0.1	<0.01	0.9	0.1	0.05	2	<0.5
173691	Rock	0.007	16	8	0.02	290	<0.001	1	0.28	0.004	0.21	0.1	<0.01	0.3	<0.1	0.59	<1	0.7
173692	Rock	0.002	2	16	0.01	76	<0.001	2	0.17	0.005	0.13	<0.1	0.02	0.2	<0.1	<0.05	<1	<0.5
173693	Rock	0.004	13	10	0.04	49	0.002	<1	0.40	0.034	0.12	<0.1	<0.01	0.9	<0.1	<0.05	2	<0.5
173694	Rock	0.007	14	7	0.02	62	<0.001	1	0.30	0.017	0.20	0.2	0.02	0.4	<0.1	0.09	<1	<0.5
173695	Rock	0.016	12	9	0.12	16	0.001	4	0.55	0.009	0.30	<0.1	0.11	1.0	1.1	5.21	<1	2.6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 26, 2009

QUALITY CONTROL REPORT SMI09000131.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Reference Materials																					
STD DS7	Standard		19.3	108.1	69.7	400	0.8	53.6	8.9	599	2.38	51.4	4.7	60.3	4.1	75	6.4	6.5	5.1	82	0.96
STD DS7	Standard		19.3	102.4	69.8	380	0.7	52.4	8.7	598	2.34	50.4	4.6	51.4	4.1	74	5.9	6.5	4.9	79	0.95
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.2	5.0	3.4	53	<0.1	4.3	4.4	554	1.92	<0.5	1.6	<0.5	3.4	62	<0.1	0.2	<0.1	38	0.53
G1	Prep Blank		0.3	7.2	3.2	49	<0.1	3.9	4.4	564	1.94	<0.5	1.8	<0.5	3.8	68	<0.1	<0.1	<0.1	38	0.53

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 26, 2009

QUALITY CONTROL REPORT SMI09000131.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																		
STD DS7	Standard	0.075	13	175	1.04	405	0.120	41	1.03	0.087	0.43	4.0	0.17	2.3	4.0	0.20	5	3.2
STD DS7	Standard	0.075	13	178	1.02	392	0.124	38	1.03	0.089	0.43	3.9	0.16	2.3	3.9	0.19	4	3.5
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.079	7	10	0.59	254	0.146	<1	0.99	0.067	0.53	<0.1	<0.01	1.9	0.3	<0.05	5	<0.5
G1	Prep Blank	0.088	8	11	0.60	258	0.144	1	1.00	0.070	0.54	<0.1	<0.01	2.0	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 19, 2009
Report Date: September 01, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000148.1

CLIENT JOB INFORMATION

Project: None Given
Shipment ID:
P.O. Number
Number of Samples: 22

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200	22	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	22	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: None Given
Report Date: September 01, 2009

CERTIFICATE OF ANALYSIS SMI09000148.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
101951	Drill Core	8.45	57.8	41.7	16.5	22	0.3	1.0	1.9	159	0.96	10.9	0.4	34.7	2.9	23	0.2	1.2	1.6	4	0.17
101952	Drill Core	9.32	95.3	56.0	12.1	23	0.7	1.0	0.8	80	1.79	21.6	0.4	150.4	4.7	24	0.2	2.0	1.3	4	0.11
101953	Drill Core	9.17	127.1	98.0	30.5	22	0.7	1.1	2.4	163	2.84	31.1	0.6	124.9	5.4	28	0.2	2.6	2.1	5	0.11
101954	Drill Core	8.96	195.4	108.2	43.2	24	2.3	0.7	0.8	74	3.44	39.8	0.9	776.0	7.2	57	0.4	13.6	24.0	6	0.05
101955	Drill Core	10.23	114.7	79.2	51.6	15	1.5	0.9	0.8	76	3.17	35.0	0.8	1079	11.7	107	0.2	3.4	102.0	6	0.06
101956	Drill Core	13.08	124.3	89.1	22.8	35	0.9	1.3	1.5	111	3.78	31.2	1.1	255.1	16.0	89	0.2	2.2	26.6	7	0.11
101957	Drill Core	9.61	129.7	80.8	43.3	29	1.1	1.0	1.2	86	2.88	16.0	1.0	250.0	13.8	60	0.3	2.7	16.1	6	0.13
101958	Drill Core	11.66	89.9	56.4	105.3	16	1.1	0.9	0.8	61	2.90	42.2	1.4	125.9	28.8	199	0.1	5.1	8.2	6	0.11
101959	Drill Core	10.32	99.8	171.8	70.7	36	1.5	2.4	2.2	121	5.35	33.6	2.1	188.4	30.4	152	0.3	5.6	4.7	17	0.11
101960	Drill Core	2.53	100.8	60.3	34.7	9	3.4	0.6	0.2	27	1.57	17.1	0.7	780.3	6.0	34	<0.1	17.2	10.3	3	0.02
101961	Drill Core	2.13	37.5	171.1	5.0	44	0.6	2.1	2.5	75	3.13	2.8	1.4	131.7	9.2	19	<0.1	0.3	1.3	24	0.05
101962	Drill Core	9.85	79.6	124.1	22.4	16	1.4	0.5	0.4	26	3.45	18.8	0.9	494.3	13.9	23	<0.1	4.1	3.9	10	0.04
101963	Drill Core	10.00	70.4	134.9	29.8	19	1.3	1.0	0.8	46	3.31	20.6	1.2	259.4	9.7	24	<0.1	5.9	3.0	11	0.04
101964	Drill Core	9.34	107.9	103.5	33.9	16	1.5	0.7	0.7	36	2.93	27.9	1.2	222.4	13.2	28	0.1	4.5	4.5	10	0.04
101965	Drill Core	10.39	57.2	94.0	17.1	13	1.1	0.6	0.5	36	3.06	23.7	1.0	572.5	14.8	21	<0.1	3.4	2.5	9	0.05
101966	Drill Core	8.95	119.9	94.4	20.4	12	1.1	0.4	0.4	29	4.54	44.6	1.2	118.1	25.9	32	0.2	2.6	2.1	10	0.05
101967	Drill Core	11.02	51.3	98.7	15.0	24	0.9	0.9	1.2	112	3.51	32.7	1.7	573.8	17.8	25	0.1	3.1	2.1	9	0.10
173696	Drill Core	2.33	45.1	62.8	2.4	7	0.1	1.7	6.3	62	2.41	<0.5	0.5	13.1	4.2	8	<0.1	0.2	0.3	25	0.03
173697	Drill Core	2.11	9.4	106.9	4.7	42	<0.1	4.7	11.8	457	4.08	5.3	4.6	346.1	26.5	31	0.1	0.2	0.2	121	0.52
173698	Drill Core	3.52	13.7	83.5	25.5	42	0.3	2.0	2.5	182	2.70	14.9	1.8	58.5	4.9	15	0.1	2.0	2.5	31	0.11
173699	Drill Core	4.54	10.4	100.6	31.5	50	0.4	3.5	3.2	226	3.21	16.5	2.5	48.1	6.1	15	0.1	2.4	1.5	37	0.15
173700	Drill Core	4.86	9.0	87.0	27.2	45	0.3	2.2	2.6	191	2.72	14.8	1.9	35.6	5.1	14	0.1	2.0	1.7	31	0.11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: None Given
Report Date: September 01, 2009

CERTIFICATE OF ANALYSIS SMI09000148.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
101951	Drill Core	0.007	12	3	0.07	729	<0.001	1	0.41	0.004	0.19	0.2	0.01	0.4	0.1	0.12	1	0.9
101952	Drill Core	0.010	15	3	0.08	610	<0.001	1	0.39	0.008	0.26	0.3	0.01	0.2	0.1	0.20	1	1.2
101953	Drill Core	0.012	17	4	0.07	544	<0.001	2	0.45	0.010	0.28	0.3	0.02	0.4	0.1	0.21	2	1.7
101954	Drill Core	0.024	19	2	0.06	504	0.002	2	0.38	0.009	0.30	0.7	0.03	0.4	0.3	0.27	1	2.5
101955	Drill Core	0.044	19	3	0.08	313	0.002	2	0.41	0.013	0.41	0.7	0.02	0.4	0.4	0.46	1	2.5
101956	Drill Core	0.086	19	4	0.12	476	0.001	2	0.51	0.017	0.36	0.3	<0.01	0.7	0.2	0.36	2	2.2
101957	Drill Core	0.046	24	4	0.13	513	0.001	2	0.60	0.012	0.40	0.4	<0.01	0.6	0.2	0.34	1	2.3
101958	Drill Core	0.073	24	4	0.09	283	0.001	2	0.45	0.015	0.46	0.6	<0.01	0.5	0.2	0.63	1	1.9
101959	Drill Core	0.076	21	8	0.15	214	0.011	2	0.77	0.026	0.53	0.5	0.02	1.6	0.3	0.68	3	3.0
101960	Drill Core	0.015	25	4	0.03	447	<0.001	2	0.27	0.008	0.27	0.8	0.02	0.2	0.2	0.22	<1	1.6
101961	Drill Core	0.048	6	7	0.32	329	0.001	1	0.85	0.024	0.19	0.8	<0.01	1.5	0.1	0.17	3	0.8
101962	Drill Core	0.044	25	3	0.12	252	0.001	1	0.71	0.018	0.36	1.3	<0.01	0.8	0.2	0.49	2	1.8
101963	Drill Core	0.042	21	5	0.12	604	0.002	2	0.68	0.016	0.28	1.6	<0.01	0.9	0.2	0.31	2	2.2
101964	Drill Core	0.063	26	3	0.12	361	0.001	2	0.63	0.013	0.30	1.2	<0.01	0.7	0.2	0.34	2	1.5
101965	Drill Core	0.053	20	5	0.11	325	0.001	1	0.66	0.016	0.32	7.0	<0.01	0.8	0.2	0.39	2	1.4
101966	Drill Core	0.089	25	3	0.10	107	0.001	1	0.67	0.053	0.54	2.4	<0.01	0.8	0.2	0.97	2	2.1
101967	Drill Core	0.067	19	4	0.12	147	<0.001	2	0.69	0.015	0.44	1.1	<0.01	1.0	0.2	0.69	2	1.6
173696	Drill Core	0.016	9	5	0.88	119	0.008	1	1.20	0.022	0.38	0.1	<0.01	1.9	0.3	1.46	3	3.1
173697	Drill Core	0.077	56	19	1.36	559	0.207	1	2.10	0.141	0.85	0.1	<0.01	8.8	0.4	0.27	7	<0.5
173698	Drill Core	0.045	11	10	0.29	399	0.027	2	0.76	0.014	0.19	0.6	<0.01	1.4	0.1	<0.05	2	<0.5
173699	Drill Core	0.056	11	12	0.37	315	0.041	2	0.96	0.019	0.17	0.6	<0.01	1.8	0.1	<0.05	3	<0.5
173700	Drill Core	0.046	10	10	0.31	360	0.031	1	0.78	0.019	0.17	0.4	0.01	1.6	0.1	<0.05	3	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: None Given
Report Date: September 01, 2009

QUALITY CONTROL REPORT SMI09000148.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Reference Materials																					
STD DS7	Standard		19.2	104.8	70.4	393	0.9	56.3	9.4	605	2.41	48.1	5.0	73.7	4.1	68	6.2	6.0	4.9	86	0.97
STD DS7	Standard		22.0	107.3	64.9	388	0.8	56.6	9.5	640	2.42	50.1	4.7	112.1	4.0	71	6.3	5.9	4.8	87	0.98
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.3	37.7	9.7	78	0.1	4.4	4.7	588	1.99	<0.5	1.6	5.1	3.6	48	0.4	0.3	0.1	40	0.56
G1	Prep Blank		0.2	4.9	9.8	82	0.1	4.0	4.8	566	2.04	<0.5	1.6	<0.5	3.0	52	0.3	0.2	<0.1	41	0.66

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: None Given
Report Date: September 01, 2009

QUALITY CONTROL REPORT SMI09000148.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																		
STD DS7	Standard	0.083	12	194	1.06	403	0.108	44	1.01	0.086	0.42	4.3	0.21	2.1	4.2	0.20	4	3.6
STD DS7	Standard	0.081	12	196	1.06	381	0.109	42	1.02	0.088	0.41	4.1	0.20	2.0	4.2	0.20	5	3.3
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.094	6	12	0.67	251	0.130	1	0.92	0.049	0.57	<0.1	<0.01	1.6	0.4	<0.05	5	0.5
G1	Prep Blank	0.092	6	11	0.72	244	0.124	1	0.97	0.052	0.57	<0.1	<0.01	1.6	0.4	<0.05	5	0.6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 26, 2009
Report Date: September 11, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000170.1

CLIENT JOB INFORMATION

Project:	Canadian Creek
Shipment ID:	CC09-14
P.O. Number	
Number of Samples:	9

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	9	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	9	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP	Store After 90 days Invoice for Storage
DISP-RJT	Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 11, 2009

CERTIFICATE OF ANALYSIS SMI09000170.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
101968	Rock	6.71	9.2	248.6	245.0	76	2.3	3.3	1.8	120	5.91	22.7	2.4	36.6	15.1	15	0.1	14.5	1.0	63	0.10
101969	Rock	9.42	13.8	211.1	123.3	53	2.4	3.1	1.9	106	5.06	10.1	2.4	30.2	14.2	14	0.1	3.5	0.7	65	0.10
101970	Rock	9.67	14.4	175.9	61.5	40	1.9	2.7	1.7	106	3.99	6.1	3.0	42.5	28.4	18	<0.1	1.7	0.6	59	0.11
101971	Rock	8.31	14.0	232.1	67.4	52	1.6	3.3	2.1	98	5.21	7.2	3.0	76.4	28.6	13	0.2	2.1	1.0	60	0.08
101972	Rock	9.37	17.9	308.8	129.7	103	1.5	4.8	4.0	141	6.34	40.2	3.6	60.7	16.1	14	0.2	3.6	1.5	80	0.09
101973	Rock	8.80	17.8	217.1	32.4	71	1.0	8.1	4.2	97	5.29	10.1	3.9	46.6	8.4	22	<0.1	4.3	0.6	56	0.11
101974	Rock	11.13	14.6	191.2	11.1	70	0.7	11.5	6.4	118	5.08	6.3	2.7	68.5	7.1	22	0.1	4.2	0.2	69	0.17
101975	Rock	10.17	13.9	208.4	41.5	91	0.7	11.1	6.9	138	5.13	72.7	3.2	69.8	8.5	18	0.2	21.0	0.9	62	0.18
101976	Rock	3.28	9.6	66.5	16.8	20	0.8	1.0	1.5	39	0.93	3.8	0.7	27.9	9.4	7	0.1	1.0	0.4	5	0.02

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 11, 2009

CERTIFICATE OF ANALYSIS SMI09000170.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
101968	Rock	0.044	8	9	0.49	170	0.023	<1	1.76	0.019	0.14	0.2	<0.01	3.5	<0.1	<0.05	7	0.5
101969	Rock	0.036	9	9	0.53	135	0.037	1	1.63	0.025	0.17	0.2	<0.01	3.6	<0.1	<0.05	6	<0.5
101970	Rock	0.037	15	9	0.69	180	0.071	<1	1.92	0.024	0.28	0.2	<0.01	5.2	0.1	0.06	6	<0.5
101971	Rock	0.034	12	8	0.47	129	0.034	<1	1.47	0.028	0.19	0.2	<0.01	3.7	<0.1	0.09	6	0.6
101972	Rock	0.053	12	11	0.67	171	0.053	2	2.10	0.017	0.26	0.4	<0.01	5.1	0.1	0.05	7	<0.5
101973	Rock	0.077	15	27	0.79	128	0.085	<1	1.92	0.025	0.38	0.3	0.01	4.2	0.2	0.14	7	<0.5
101974	Rock	0.081	13	35	1.03	161	0.113	<1	2.03	0.028	0.39	0.4	<0.01	5.0	0.2	0.07	8	<0.5
101975	Rock	0.079	11	31	0.85	167	0.097	1	2.07	0.028	0.33	0.4	<0.01	4.4	0.2	<0.05	7	<0.5
101976	Rock	0.003	2	14	0.04	71	0.002	<1	0.23	0.035	0.12	0.6	<0.01	0.2	<0.1	0.17	1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 11, 2009

QUALITY CONTROL REPORT SMI09000170.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Reference Materials																					
STD DS7	Standard		19.3	103.8	71.0	392	0.8	54.7	8.7	557	2.31	48.1	4.8	65.6	4.5	78	6.0	6.2	5.0	77	0.93
STD DS7	Standard		19.0	103.8	71.5	375	0.8	52.6	8.7	544	2.32	46.2	4.7	60.3	4.5	74	5.8	6.1	4.8	76	0.95
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.2	3.4	74.7	95	0.2	4.0	4.6	584	2.01	1.2	1.9	5.3	4.3	71	0.4	<0.1	0.2	38	0.58
G1	Prep Blank		0.2	3.9	119.3	133	0.2	4.1	4.6	592	2.08	1.5	1.8	1.5	4.1	73	0.7	0.2	0.2	38	0.62

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 11, 2009

QUALITY CONTROL REPORT SMI09000170.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																		
STD DS7	Standard	0.077	11	158	0.98	353	0.126	41	0.93	0.083	0.39	3.8	0.20	2.1	3.8	0.19	4	3.4
STD DS7	Standard	0.069	12	158	0.98	363	0.120	37	0.96	0.078	0.37	3.3	0.17	2.0	3.7	0.18	4	2.5
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.083	8	14	0.59	257	0.154	<1	1.00	0.074	0.51	<0.1	<0.01	1.9	0.3	<0.05	5	<0.5
G1	Prep Blank	0.077	8	14	0.60	243	0.147	<1	1.00	0.070	0.50	<0.1	0.02	1.9	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 31, 2009
Report Date: September 14, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000182.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC09-16
P.O. Number
Number of Samples: 14

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	14	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	14	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

CERTIFICATE OF ANALYSIS SMI09000182.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
101977	Rock	2.29	22.5	136.1	12.8	18	0.2	1.2	7.2	276	1.04	2.8	2.5	48.4	13.2	9	0.1	0.4	0.2	8	0.05
101978	Rock	3.03	39.6	114.9	11.2	19	0.4	1.1	3.7	121	2.16	4.6	2.4	74.2	16.0	20	0.2	0.5	0.3	19	0.06
101979	Rock Chip	3.60	16.9	209.4	17.9	46	0.1	2.7	15.4	401	2.73	13.1	3.9	35.9	15.7	18	0.2	0.8	0.3	27	0.14
101980	Rock	2.25	0.7	4.1	14.9	111	<0.1	6.2	4.2	614	1.69	62.3	2.6	3.0	16.6	12	0.5	1.0	0.3	15	0.30
101981	Rock	2.51	0.4	9.9	11.2	11	<0.1	1.3	1.8	116	0.86	17.7	3.3	1.8	26.0	4	0.1	5.0	0.2	2	0.05
101982	Rock	2.52	0.8	5.6	16.8	48	<0.1	8.1	4.4	425	1.61	10.5	3.2	1.3	15.7	9	0.2	1.7	0.3	16	0.22
101983	Rock	0.96	2.6	2.0	14.8	18	<0.1	1.0	1.8	213	0.80	8.6	11.7	0.9	15.8	14	<0.1	0.5	0.7	9	0.30
101984	Rock	1.88	1.1	2.2	11.7	12	0.1	1.4	0.4	67	0.33	6.4	10.2	1.9	22.7	2	<0.1	0.2	1.7	3	0.02
101985	Rock	1.90	1.5	43.4	4.8	74	0.3	11.8	4.4	368	4.61	7.1	1.2	1.5	10.5	7	<0.1	0.2	0.2	174	0.08
101986	Rock	1.69	18.7	25.9	49.4	57	0.4	5.9	1.4	102	1.72	46.5	6.3	23.7	3.5	17	0.2	7.2	0.4	205	0.14
101987	Rock	2.04	2.4	26.5	5.1	26	0.2	22.0	2.9	270	2.50	95.6	1.3	3.6	7.7	4	0.1	1.5	1.4	53	0.09
101988	Rock	2.35	8.3	26.2	4.8	9	0.3	6.3	0.6	93	0.79	39.6	4.0	3.6	4.0	5	<0.1	1.0	0.9	56	0.25
101989	Rock	2.52	0.9	140.8	64.3	15	1.0	2.1	1.0	43	1.54	1128	3.6	36.7	6.2	9	0.1	5.3	5.1	4	0.04
101990	Rock	2.18	5.9	40.3	19.9	57	0.3	15.6	1.5	341	1.78	34.4	2.9	2.3	3.3	7	0.1	1.0	0.5	104	0.17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

CERTIFICATE OF ANALYSIS SMI09000182.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
101977	Rock	0.013	18	4	0.09	94	<0.001	2	0.53	0.017	0.23	0.1	<0.01	1.0	0.2	<0.05	1	<0.5
101978	Rock	0.016	17	7	0.24	801	0.003	2	1.00	0.033	0.51	0.1	<0.01	1.2	0.3	0.08	3	0.8
101979	Rock Chip	0.035	16	6	0.35	196	0.009	2	1.25	0.028	0.29	0.1	<0.01	2.1	0.2	<0.05	4	<0.5
101980	Rock	0.047	23	17	0.56	112	0.029	2	1.10	0.046	0.16	<0.1	<0.01	2.8	0.1	<0.05	6	<0.5
101981	Rock	0.013	21	7	0.02	56	0.003	<1	0.21	0.040	0.12	0.8	<0.01	0.8	<0.1	0.12	<1	<0.5
101982	Rock	0.036	29	13	0.30	56	0.017	1	0.74	0.030	0.18	0.2	<0.01	2.1	0.2	<0.05	4	<0.5
101983	Rock	0.011	7	7	0.19	73	0.023	2	0.53	0.060	0.11	0.3	<0.01	1.4	<0.1	<0.05	2	<0.5
101984	Rock	0.001	2	8	0.06	17	0.003	<1	0.23	0.026	0.09	<0.1	<0.01	0.4	<0.1	<0.05	<1	<0.5
101985	Rock	0.038	17	115	1.21	714	0.404	<1	2.06	0.023	1.60	0.3	<0.01	12.6	1.0	0.08	9	1.2
101986	Rock	0.080	12	50	0.40	166	0.020	<1	0.90	0.010	0.29	0.7	<0.01	2.3	0.1	0.11	4	3.1
101987	Rock	0.042	7	51	0.69	212	0.009	2	1.37	0.002	0.24	<0.1	<0.01	2.0	0.1	0.17	5	1.3
101988	Rock	0.134	8	25	0.12	60	0.002	1	0.49	0.003	0.12	0.2	<0.01	0.9	<0.1	<0.05	2	0.9
101989	Rock	0.032	18	5	0.02	108	<0.001	3	0.64	0.004	0.30	0.2	<0.01	0.8	0.3	0.22	1	<0.5
101990	Rock	0.113	8	54	0.56	300	0.005	<1	1.03	0.005	0.14	0.1	<0.01	2.0	<0.1	0.07	4	3.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

QUALITY CONTROL REPORT SMI09000182.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
REP G1	QC		0.1	4.0	3.3	47	<0.1	3.4	4.5	557	2.03	<0.5	1.7	<0.5	4.3	62	<0.1	<0.1	<0.1	40	0.69
101985	Rock	1.90	1.5	43.4	4.8	74	0.3	11.8	4.4	368	4.61	7.1	1.2	1.5	10.5	7	<0.1	0.2	0.2	174	0.08
REP 101985	QC		1.5	44.1	4.6	73	0.3	12.2	4.5	377	4.70	7.6	1.1	3.2	10.5	7	<0.1	0.2	0.1	180	0.08
Reference Materials																					
STD DS7	Standard		18.4	100.2	61.6	365	0.8	50.9	8.5	542	2.17	45.4	4.4	52.0	3.8	57	5.7	5.1	4.1	73	0.87
STD DS7	Standard		19.0	103.4	81.4	374	0.9	52.5	9.3	554	2.20	47.4	4.7	59.6	4.1	58	5.8	5.3	4.4	74	0.90
STD DS7	Standard		19.0	110.4	70.1	404	0.8	57.4	9.2	656	2.43	51.0	4.9	60.6	4.7	79	6.1	5.8	4.7	83	1.00
STD DS7	Standard		20.1	102.8	68.4	388	0.8	51.9	9.1	635	2.38	50.4	4.9	56.7	4.6	83	6.1	5.4	4.3	81	1.00
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank																				
G1	Prep Blank		0.1	3.2	12.4	46	<0.1	4.2	4.8	567	2.16	<0.5	1.7	<0.5	4.1	65	<0.1	<0.1	<0.1	41	0.58
G1	Prep Blank		0.1	4.0	3.1	47	<0.1	4.2	4.5	560	2.01	<0.5	1.7	<0.5	4.3	60	<0.1	<0.1	<0.1	40	0.67

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

QUALITY CONTROL REPORT SMI09000182.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
REP G1	QC	0.085	9	12	0.66	251	0.146	<1	1.03	0.087	0.53	<0.1	<0.01	2.1	0.3	<0.05	5	<0.5
101985	Rock	0.038	17	115	1.21	714	0.404	<1	2.06	0.023	1.60	0.3	<0.01	12.6	1.0	0.08	9	1.2
REP 101985	QC	0.040	17	116	1.26	725	0.414	<1	2.14	0.023	1.55	0.3	<0.01	12.5	1.0	0.08	10	1.0
Reference Materials																		
STD DS7	Standard	0.068	11	159	0.93	347	0.104	37	0.89	0.077	0.38	4.1	0.17	1.9	4.0	0.17	4	3.6
STD DS7	Standard	0.067	12	165	0.97	352	0.104	38	0.92	0.079	0.38	3.9	0.20	1.9	4.3	0.18	4	3.4
STD DS7	Standard	0.078	14	218	1.06	411	0.128	40	1.06	0.101	0.45	3.8	0.20	2.6	4.0	0.19	5	3.7
STD DS7	Standard	0.071	14	205	1.05	398	0.127	34	1.08	0.094	0.45	3.9	0.18	2.6	3.9	0.19	5	3.3
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank																	
G1	Prep Blank	0.078	9	12	0.61	252	0.145	1	1.08	0.091	0.54	0.1	<0.01	2.1	0.4	<0.05	5	<0.5
G1	Prep Blank	0.082	9	13	0.66	247	0.143	<1	1.00	0.080	0.50	<0.1	<0.01	2.0	0.3	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: September 08, 2009
Report Date: September 21, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000203.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC09-18
P.O. Number
Number of Samples: 11

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R150	11	Crush, split and pulverize rock to 200 mesh			VAN
1DX15	11	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 21, 2009

CERTIFICATE OF ANALYSIS SMI09000203.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
101551	Rock	0.70	1.1	5.3	4.2	3	0.1	5.5	4.5	22	2.80	36.0	0.7	11.6	9.7	7	<0.1	0.4	0.8	2	0.01
101552	Rock	1.45	4.7	14.9	8.2	22	0.2	1.3	1.1	115	1.84	4.8	1.5	<0.5	22.0	5	<0.1	0.8	0.2	14	0.01
101553	Rock	1.81	2.6	12.0	37.2	120	0.2	6.4	5.7	1423	1.52	148.4	6.1	1.6	14.3	17	0.9	4.4	0.2	8	0.35
101554	Rock	2.50	1.1	14.7	36.1	199	0.5	5.4	6.2	716	1.73	158.8	3.7	18.0	14.5	17	1.0	2.4	0.6	6	0.32
101555	Rock	3.12	2.5	55.3	4.3	35	0.2	13.2	3.3	220	2.15	36.2	2.4	3.5	5.5	9	<0.1	3.1	0.6	58	0.07
101556	Rock	2.45	0.9	63.2	4.7	32	0.1	26.6	4.9	232	3.05	43.6	3.0	47.2	9.6	15	<0.1	1.5	3.2	54	0.06
101557	Rock	2.27	2.1	285.2	23.8	13	1.0	6.0	117.7	30	22.25	1500	3.2	2517	2.8	5	<0.1	1.0	10.9	8	0.03
101558	Rock	2.09	19.8	10.7	5.4	6	<0.1	2.4	0.3	29	0.63	14.3	0.5	10.8	3.1	35	<0.1	0.2	0.7	29	<0.01
101559	Rock	2.75	0.5	25.6	12.2	13	0.1	1.0	1.5	25	1.54	22.5	0.5	34.7	5.9	38	<0.1	0.4	1.9	3	0.26
101560	Rock	2.46	0.4	106.2	26.4	55	1.6	1.7	1.2	188	2.34	44.1	2.2	89.0	9.0	17	<0.1	0.9	8.8	17	0.07
101991	Rock	0.67	0.7	11.5	38.4	12	0.6	0.7	0.5	25	2.43	1727	0.8	28.9	4.9	5	0.1	3.2	2.8	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 21, 2009

CERTIFICATE OF ANALYSIS SMI09000203.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
101551	Rock	0.009	19	7	0.02	49	0.002	3	0.30	0.005	0.21	0.2	<0.01	0.2	<0.1	2.44	<1	2.2
101552	Rock	0.010	33	13	0.18	70	0.075	1	0.55	0.030	0.35	0.2	<0.01	1.9	0.3	<0.05	3	0.9
101553	Rock	0.045	28	9	0.16	71	0.002	<1	1.01	0.002	0.12	0.2	<0.01	2.9	0.2	<0.05	4	0.6
101554	Rock	0.035	33	7	0.71	54	<0.001	2	1.40	0.004	0.18	0.1	<0.01	1.8	0.1	<0.05	3	<0.5
101555	Rock	0.026	11	57	0.56	84	0.021	1	1.17	0.005	0.13	<0.1	<0.01	1.8	0.1	<0.05	4	1.2
101556	Rock	0.037	28	57	0.66	239	0.042	2	1.65	0.011	0.48	0.2	<0.01	2.7	0.4	0.10	5	1.2
101557	Rock	0.004	2	7	0.10	5	0.009	27	0.20	0.024	0.09	<0.1	<0.01	0.5	0.1	>10	2	5.6
101558	Rock	0.054	9	17	0.01	142	0.003	<1	0.16	0.007	0.16	0.5	<0.01	0.8	<0.1	0.18	<1	1.6
101559	Rock	0.031	10	1	0.16	268	<0.001	4	1.48	0.069	0.22	<0.1	<0.01	0.7	0.2	0.15	3	0.8
101560	Rock	0.025	18	8	0.37	272	0.002	1	0.91	0.006	0.22	0.8	<0.01	1.4	0.2	0.10	3	0.5
101991	Rock	0.005	8	4	0.01	90	0.002	5	0.22	0.003	0.19	0.3	0.15	0.4	0.2	1.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 21, 2009

QUALITY CONTROL REPORT SMI09000203.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Reference Materials																					
STD DS7	Standard		19.6	104.3	67.6	377	0.8	56.2	9.1	578	2.33	46.1	4.6	68.5	4.3	61	5.8	5.6	4.1	80	0.94
STD DS7	Standard		21.0	106.6	68.0	388	0.8	56.8	9.3	595	2.31	48.6	4.6	62.0	4.3	65	5.7	5.3	4.2	80	0.95
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.5	3.7	3.1	52	<0.1	4.2	4.9	609	2.13	<0.5	1.7	<0.5	4.0	61	<0.1	<0.1	<0.1	41	0.56
G1	Prep Blank		0.3	4.9	2.8	49	<0.1	4.9	4.9	589	2.11	0.6	1.7	<0.5	4.0	61	<0.1	<0.1	<0.1	41	0.56

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 21, 2009

QUALITY CONTROL REPORT SMI09000203.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																		
STD DS7	Standard	0.074	11	165	1.03	367	0.110	40	0.98	0.076	0.37	4.0	0.16	2.1	4.0	0.19	4	3.2
STD DS7	Standard	0.073	12	168	1.03	361	0.111	37	0.99	0.078	0.39	4.0	0.18	2.3	4.0	0.19	4	3.5
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.084	8	10	0.63	265	0.150	<1	1.08	0.091	0.57	<0.1	<0.01	2.1	0.4	<0.05	5	<0.5
G1	Prep Blank	0.085	8	29	0.62	245	0.146	3	1.04	0.079	0.55	0.1	<0.01	2.0	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: October 05, 2009
Report Date: October 19, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000317.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC09-21
P.O. Number
Number of Samples: 12

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	12	Crush, split and pulverize 250 g rock to 200 mesh			VAN
1DX2	12	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000317.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
101661	Rock	0.42	2.0	56.1	7.3	37	<0.1	3.2	5.8	322	4.43	22.1	4.0	18.9	9.8	27	0.2	15.9	2.9	113	0.26
101662	Rock	0.83	0.7	3.3	3.8	13	<0.1	2.0	2.8	106	1.37	30.3	1.9	36.0	16.9	5	<0.1	0.5	1.9	7	0.17
101663	Rock	0.81	0.2	4.4	21.5	31	0.1	2.7	0.6	143	0.45	10.9	7.3	2.2	38.8	4	<0.1	1.7	0.3	<2	0.04
101664	Rock	1.27	0.7	41.5	8.4	6	1.9	0.7	6.5	38	2.15	75.9	1.7	294.7	2.8	9	<0.1	1.4	6.0	8	0.03
101665	Rock	2.38	0.2	76.5	8.5	49	0.2	2.7	16.3	376	3.33	68.1	1.2	39.1	9.7	12	<0.1	0.6	4.9	43	0.17
101666	Rock	4.97	1.7	47.8	18.5	7	0.5	0.9	22.9	34	7.69	477.6	2.1	866.5	5.1	23	<0.1	0.8	10.9	13	0.03
101667	Rock	2.54	0.6	30.0	12.6	8	0.3	0.3	1.1	40	2.87	114.9	1.1	448.6	3.1	22	<0.1	0.9	3.3	11	0.09
101668	Rock	4.01	1.7	404.9	17.8	36	0.6	2.7	16.2	208	8.75	190.4	2.6	573.7	15.5	14	<0.1	0.6	4.5	52	0.20
101669	Rock	3.25	0.2	101.3	11.4	51	0.1	3.8	1.0	265	4.74	23.4	2.3	167.8	17.8	70	0.1	0.5	1.4	80	0.96
101670	Rock	2.18	0.3	108.6	20.4	39	0.6	3.8	7.5	340	5.20	140.2	1.1	160.8	6.7	19	<0.1	2.1	15.3	72	0.28
101671	Rock	2.39	0.4	40.5	11.2	44	0.2	1.9	5.3	284	3.72	73.6	1.9	62.0	10.4	56	<0.1	0.8	3.7	60	0.67
101672	Rock	0.85	0.2	83.1	12.2	14	0.3	0.9	3.2	97	2.87	43.9	2.5	299.9	12.7	26	<0.1	1.1	2.0	24	0.08

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

CERTIFICATE OF ANALYSIS SMI09000317.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
101661	Rock	0.085	12	25	1.54	818	0.024	2	2.26	0.051	0.20	<0.1	<0.01	10.1	0.3	0.13	8	<0.5
101662	Rock	0.034	19	9	0.34	57	0.005	1	0.58	0.032	0.12	0.3	<0.01	1.7	0.1	0.31	3	<0.5
101663	Rock	0.002	10	4	0.02	20	<0.001	1	0.19	0.038	0.09	0.1	<0.01	0.3	<0.1	<0.05	<1	<0.5
101664	Rock	0.008	2	4	0.09	85	0.007	13	0.22	0.035	0.17	0.3	<0.01	0.7	0.1	0.92	1	1.0
101665	Rock	0.051	13	11	1.02	64	0.007	1	1.76	0.040	0.09	<0.1	<0.01	4.5	0.1	0.76	7	<0.5
101666	Rock	0.015	6	3	0.19	21	0.016	7	0.41	0.135	0.31	0.1	<0.01	0.8	0.3	5.58	3	3.3
101667	Rock	0.013	5	2	0.29	72	0.005	7	0.60	0.100	0.24	0.1	<0.01	0.5	0.3	1.00	4	1.2
101668	Rock	0.073	6	10	1.89	30	0.011	4	2.08	0.048	0.20	0.2	<0.01	3.6	0.2	6.74	12	1.3
101669	Rock	0.075	16	13	1.80	69	0.083	8	2.96	0.160	0.26	0.4	<0.01	7.2	0.4	0.59	12	<0.5
101670	Rock	0.044	7	11	1.15	127	0.047	1	1.70	0.042	0.30	<0.1	<0.01	4.5	0.5	0.25	9	0.6
101671	Rock	0.049	6	8	1.14	63	0.129	3	2.27	0.262	0.75	3.3	<0.01	3.7	1.0	1.63	8	<0.5
101672	Rock	0.040	6	7	0.32	171	0.004	2	0.65	0.036	0.14	<0.1	<0.01	2.7	<0.1	0.51	4	0.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

QUALITY CONTROL REPORT SMI09000317.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Reference Materials																					
STD DS7	Standard		21.3	114.1	73.1	403	0.8	57.1	9.4	631	2.43	50.7	5.1	70.7	4.7	78	6.6	6.2	4.9	83	0.96
STD DS7	Standard		20.2	112.6	64.1	383	0.7	57.5	9.8	628	2.45	48.8	4.8	55.5	4.5	74	6.1	5.9	4.5	84	0.98
STD DS7	Standard		20.4	107.7	68.9	382	0.8	55.0	8.9	590	2.31	49.7	4.8	56.4	4.7	74	6.1	5.7	4.5	79	0.93
STD DS7	Standard		20.7	111.9	71.9	391	0.8	56.6	9.0	612	2.39	52.8	4.9	66.6	4.7	80	5.9	6.1	4.5	82	0.96
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		0.1	2.0	3.1	47	<0.1	4.1	4.6	542	2.03	<0.5	1.7	<0.5	3.8	59	<0.1	0.2	<0.1	39	0.54
G1	Prep Blank		<0.1	2.5	2.6	48	<0.1	4.2	4.7	574	2.10	0.5	1.8	<0.5	3.9	67	<0.1	0.1	<0.1	41	0.59

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 19, 2009

QUALITY CONTROL REPORT SMI09000317.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																		
STD DS7	Standard	0.078	13	208	1.03	394	0.122	43	1.04	0.100	0.46	4.0	0.21	2.3	4.3	0.19	5	3.9
STD DS7	Standard	0.078	12	213	1.04	382	0.126	38	1.06	0.100	0.44	3.6	0.18	2.3	3.9	0.20	5	3.3
STD DS7	Standard	0.072	12	198	1.02	378	0.120	36	1.02	0.093	0.43	3.5	0.17	2.3	3.9	0.19	4	3.3
STD DS7	Standard	0.075	13	207	1.03	395	0.125	40	1.04	0.096	0.44	3.7	0.20	2.4	4.0	0.19	4	3.9
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
Prep Wash																		
G1	Prep Blank	0.085	7	10	0.59	243	0.138	1	1.00	0.083	0.55	0.1	<0.01	2.0	0.4	<0.05	5	<0.5
G1	Prep Blank	0.086	8	11	0.61	268	0.152	1	1.07	0.092	0.56	<0.1	<0.01	2.2	0.4	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: July 31, 2009
Report Date: August 08, 2009
Page: 1 of 5

CERTIFICATE OF ANALYSIS SMI09000076.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 108

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	106	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	106	Dry at 60C			SMI
1DX15	105	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

CERTIFICATE OF ANALYSIS SMI09000076.1

		Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L9400 13025N	Soil			2.2	24.6	24.1	128	0.6	19.8	8.1	715	2.32	151.0	5.5	7.8	0.8	45	1.1	5.8	0.3	52	0.64
L9400 13050N	Soil			1.6	21.5	29.2	123	0.4	22.0	7.9	445	2.59	103.4	2.7	6.4	2.6	27	0.5	5.7	0.4	62	0.39
L9400 13075N	Soil			1.1	17.2	46.1	174	0.9	22.2	7.7	314	2.89	123.3	6.0	8.0	2.9	33	0.4	8.0	0.5	62	0.39
L9400 13100N	Soil			1.7	26.8	39.4	170	0.8	23.0	10.5	868	2.82	137.7	6.0	8.9	1.9	42	0.7	5.1	0.7	58	0.53
L9400 13125N	Soil			1.1	18.5	21.6	108	0.2	19.4	9.4	348	2.79	42.9	3.8	3.6	3.0	40	0.5	1.7	0.3	65	0.54
L9400 13150N	Soil			0.6	14.9	13.5	57	<0.1	17.0	6.2	166	2.10	6.8	1.8	1.8	3.5	25	0.2	0.9	0.2	68	0.35
L9400 13175N	Soil			0.9	13.7	11.4	69	<0.1	17.6	8.4	562	2.47	7.5	1.3	11.6	2.5	27	0.3	0.8	0.2	61	0.37
L9400 13200N	Soil			1.1	15.3	8.7	48	0.1	16.4	7.4	350	2.13	5.3	1.4	1.1	1.4	25	0.3	0.4	0.2	51	0.27
L9400 13225N	Soil			1.5	11.0	5.4	21	<0.1	7.8	3.1	81	1.42	5.2	0.5	3.1	0.9	9	0.1	0.5	0.2	43	0.07
L9400 13250N	Soil			I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9600 11625N	Soil			1.6	24.1	87.7	262	0.5	21.3	12.0	1129	3.14	115.7	5.5	5.3	3.9	35	1.4	2.1	0.3	73	0.52
L9600 11650N	Soil			1.0	23.5	71.2	179	0.5	20.8	11.8	946	3.01	79.3	7.1	4.9	8.6	27	1.0	2.0	0.2	71	0.44
L9600 11675N	Soil			1.5	24.7	111.6	238	0.9	22.3	12.2	669	3.23	160.4	7.4	7.0	7.3	32	0.9	3.4	0.3	75	0.50
L9600 11700N	Soil			2.2	22.9	96.2	215	1.0	18.7	10.9	974	3.05	146.6	6.4	5.3	6.5	34	0.7	3.6	0.5	70	0.60
L9600 11725N	Soil			2.7	27.5	81.2	204	1.4	20.0	12.1	1194	3.53	196.8	6.6	9.6	5.7	38	0.7	5.3	0.8	73	0.59
L9600 11750N	Soil			2.5	29.1	105.7	205	1.5	23.9	13.3	965	3.57	168.8	6.8	7.0	4.6	37	0.4	6.2	0.8	79	0.49
L9600 11775N	Soil			3.7	35.8	88.9	194	1.4	28.1	14.6	1069	4.01	231.0	5.5	8.9	4.4	35	0.6	9.1	1.1	81	0.49
L9600 11800N	Soil			2.1	27.4	45.1	155	0.9	25.7	10.8	800	3.04	118.0	2.2	7.0	3.7	33	0.8	5.0	0.3	71	0.43
L9600 11825N	Soil			2.3	36.3	23.0	111	0.3	25.8	26.5	1659	5.36	97.9	2.7	3.0	6.6	39	0.5	6.8	0.2	126	0.67
L9600 11850N	Soil			2.3	35.4	45.3	143	0.8	27.3	13.3	916	3.34	111.1	2.9	11.0	2.6	33	0.7	4.9	0.2	82	0.48
L9600 11875N	Soil			2.2	38.7	902.8	1386	3.4	20.2	15.1	1795	5.28	7770	2.8	39.2	2.5	42	13.6	12.1	2.7	78	0.40
L9600 11900N	Soil			2.1	37.9	93.8	155	1.2	23.8	12.8	1050	2.99	170.6	2.1	6.1	1.2	34	0.9	8.7	0.3	80	0.51
L9600 11925N	Soil			2.2	31.8	84.2	194	1.0	20.6	13.6	1366	3.23	269.8	3.0	8.6	1.3	31	2.6	12.8	1.1	70	0.41
L9600 12700N	Soil			0.9	22.1	43.5	102	0.5	20.1	9.4	521	2.36	106.3	3.3	15.2	6.0	32	0.6	16.7	0.5	54	0.52
L9600 12725N	Soil			1.0	21.9	68.7	126	0.6	22.4	8.8	504	2.38	175.7	3.6	14.1	8.6	27	0.4	26.0	0.7	50	0.42
L9600 12750N	Soil			0.9	23.0	51.5	122	0.4	20.3	8.9	725	2.39	176.5	3.4	13.8	5.7	33	0.8	22.3	0.6	48	0.53
L9600 12775N	Soil			1.3	24.1	49.6	108	0.5	18.9	9.2	632	2.55	142.6	4.3	17.9	4.8	28	0.6	21.5	0.7	54	0.41
L9600 12800N	Soil			0.8	26.7	55.5	120	0.6	25.9	10.4	435	2.75	146.7	4.5	12.1	8.3	24	0.7	15.3	0.7	61	0.35
L9600 12825N	Soil			1.4	33.0	67.1	126	0.9	30.3	19.4	1714	4.16	249.4	7.6	12.0	4.8	30	0.8	21.0	0.8	80	0.38
L9600 12850N	Soil			L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

CERTIFICATE OF ANALYSIS SMI09000076.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L9400 13025N	Soil	0.142	12	32	0.53	130	0.030	<1	1.50	0.015	0.06	0.2	0.05	1.6	0.1	0.09	5	0.8
L9400 13050N	Soil	0.083	11	35	0.57	135	0.070	<1	1.74	0.012	0.07	0.5	0.02	2.9	0.1	<0.05	6	<0.5
L9400 13075N	Soil	0.055	18	37	0.59	207	0.049	<1	2.35	0.015	0.05	0.2	0.04	3.5	0.2	<0.05	7	0.6
L9400 13100N	Soil	0.084	25	37	0.58	242	0.038	<1	2.18	0.016	0.05	0.3	0.05	3.1	0.2	<0.05	6	1.3
L9400 13125N	Soil	0.070	18	33	0.57	199	0.064	1	1.90	0.016	0.08	0.4	0.03	3.6	0.2	<0.05	6	0.8
L9400 13150N	Soil	0.071	11	30	0.59	170	0.086	<1	1.89	0.017	0.06	0.2	0.02	2.8	0.2	<0.05	6	<0.5
L9400 13175N	Soil	0.071	10	28	0.50	188	0.072	<1	1.72	0.014	0.07	0.4	0.03	2.4	0.1	<0.05	6	<0.5
L9400 13200N	Soil	0.073	11	27	0.38	148	0.072	<1	1.46	0.018	0.06	0.3	0.05	2.3	0.1	<0.05	6	0.5
L9400 13225N	Soil	0.025	5	15	0.10	37	0.052	<1	0.99	0.015	0.03	0.2	0.05	1.1	0.1	<0.05	5	<0.5
L9400 13250N	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9600 11625N	Soil	0.088	18	31	0.66	264	0.078	<1	1.81	0.020	0.09	0.3	0.07	3.6	0.3	0.05	6	0.5
L9600 11650N	Soil	0.101	22	27	0.64	214	0.093	1	1.67	0.022	0.12	0.3	0.06	3.9	0.3	<0.05	6	0.7
L9600 11675N	Soil	0.082	22	33	0.71	271	0.089	<1	2.04	0.021	0.12	0.3	0.05	5.3	0.3	<0.05	6	0.5
L9600 11700N	Soil	0.091	19	28	0.67	231	0.082	<1	1.67	0.022	0.13	0.8	0.06	5.0	0.3	<0.05	6	<0.5
L9600 11725N	Soil	0.090	24	32	0.67	247	0.065	<1	2.05	0.017	0.11	0.5	0.06	5.4	0.2	<0.05	6	0.7
L9600 11750N	Soil	0.075	24	39	0.72	263	0.082	1	2.12	0.022	0.11	0.6	0.06	5.3	0.3	<0.05	7	0.8
L9600 11775N	Soil	0.074	22	40	0.78	270	0.077	1	2.29	0.016	0.14	0.4	0.06	5.4	0.3	<0.05	8	0.6
L9600 11800N	Soil	0.063	12	34	0.63	179	0.079	<1	1.62	0.017	0.12	0.4	0.04	3.7	0.2	<0.05	5	<0.5
L9600 11825N	Soil	0.122	17	36	0.97	349	0.163	<1	2.18	0.018	0.27	0.2	<0.01	8.6	0.5	<0.05	7	0.7
L9600 11850N	Soil	0.080	15	38	0.62	228	0.086	<1	1.84	0.018	0.11	0.2	0.04	4.3	0.2	<0.05	6	0.6
L9600 11875N	Soil	0.068	12	30	0.54	500	0.045	<1	1.65	0.019	0.12	0.4	0.05	4.9	0.2	0.10	6	1.0
L9600 11900N	Soil	0.094	13	38	0.57	233	0.071	<1	1.62	0.017	0.08	0.3	0.05	3.4	0.2	0.07	6	0.6
L9600 11925N	Soil	0.102	14	32	0.59	208	0.055	<1	1.87	0.021	0.08	0.3	0.10	3.2	0.2	0.06	6	0.7
L9600 12700N	Soil	0.061	17	31	0.52	127	0.075	<1	1.44	0.023	0.08	1.1	0.04	3.3	0.2	<0.05	5	<0.5
L9600 12725N	Soil	0.064	20	38	0.54	113	0.085	<1	1.46	0.019	0.09	1.2	0.03	3.3	0.2	<0.05	5	<0.5
L9600 12750N	Soil	0.054	20	31	0.48	143	0.065	1	1.35	0.017	0.08	1.1	0.03	2.9	0.1	<0.05	5	<0.5
L9600 12775N	Soil	0.069	21	35	0.52	129	0.062	<1	1.52	0.015	0.08	1.2	0.03	3.3	0.2	<0.05	5	0.6
L9600 12800N	Soil	0.070	22	38	0.59	151	0.077	<1	1.96	0.017	0.08	0.4	0.03	4.0	0.2	<0.05	6	<0.5
L9600 12825N	Soil	0.101	30	48	0.62	191	0.048	1	2.62	0.019	0.09	0.3	0.06	4.9	0.2	0.05	8	0.8
L9600 12850N	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

CERTIFICATE OF ANALYSIS SMI09000076.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L9600 12875N	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
L9600 12900N	Soil		0.7	17.4	50.0	98	0.5	18.7	6.4	197	2.14	117.6	2.3	10.6	6.6	21	0.5	17.5	0.7	50	0.35
L9600 12925N	Soil		0.8	21.3	63.6	105	0.4	19.4	8.5	273	2.48	60.7	3.0	10.9	9.8	21	0.4	16.1	0.5	55	0.38
L9600 12950N	Soil		1.5	20.9	40.8	101	0.2	18.4	15.5	2981	2.97	77.4	3.9	4.0	5.4	31	0.8	12.5	0.3	54	0.56
L9600 12975N	Soil		1.0	21.9	35.4	99	0.6	24.4	11.2	1915	2.46	36.3	4.6	7.9	2.8	28	0.9	7.7	0.3	58	0.41
L9600 13000N	Soil		1.1	19.1	55.6	119	0.3	21.7	11.9	527	2.81	68.8	3.0	6.8	5.5	20	0.5	15.7	0.4	62	0.33
L9600 13025N	Soil		0.9	20.8	34.4	84	0.4	16.7	8.6	636	2.26	59.0	4.1	6.0	1.6	26	0.7	12.2	0.3	52	0.36
L9600 13050N	Soil		1.9	15.2	44.5	99	0.3	16.0	19.0	3670	3.79	213.4	3.2	9.5	3.1	20	1.1	13.5	0.4	70	0.28
L9600 13075N	Soil		0.9	17.2	45.3	114	0.2	19.8	11.0	918	2.02	41.8	2.7	3.5	4.6	18	0.8	10.2	0.4	54	0.24
L9600 13100N	Soil		1.4	12.4	35.7	103	0.3	16.1	8.5	369	2.31	55.5	1.5	5.0	2.3	24	0.6	6.6	0.4	58	0.32
L9600 13125N	Soil		1.4	18.4	49.6	135	0.3	21.5	10.4	477	2.72	86.5	2.6	3.6	3.6	26	0.7	9.6	0.5	66	0.32
L9600 13150N	Soil		1.3	17.7	41.3	142	0.5	21.6	11.2	540	2.71	74.9	2.5	14.1	4.0	23	0.5	5.6	0.5	63	0.35
L9600 13175N	Soil		1.6	20.7	36.3	146	0.5	19.7	8.5	345	2.84	118.6	3.6	11.6	4.3	33	0.7	4.1	0.7	69	0.46
L9600 13200N	Soil		1.2	18.9	20.7	107	0.4	20.9	9.6	424	2.80	51.5	3.3	5.5	3.2	39	0.4	2.0	0.4	64	0.53
L9600 13225N	Soil		1.4	19.5	18.9	103	0.2	22.9	15.2	1158	3.11	16.2	4.5	1.1	3.7	47	0.6	1.1	0.3	62	0.62
L9600 13250N	Soil		1.8	20.5	12.7	62	0.1	24.9	10.4	420	3.94	19.8	1.1	1.6	3.6	24	0.3	1.1	0.3	90	0.25
L9800 12575N	Soil		0.9	48.0	635.5	983	10.4	19.4	10.7	2402	3.50	1103	8.7	56.6	8.3	27	6.1	153.9	2.9	49	0.35
L9800 12600N	Soil		0.6	28.1	76.8	213	1.1	23.8	9.9	822	2.81	297.4	3.3	14.0	6.5	21	1.3	18.8	0.6	65	0.36
L9800 12625N	Soil		1.5	13.8	31.8	52	1.2	8.2	2.7	115	1.48	119.3	3.5	16.4	0.6	11	0.5	6.7	0.4	37	0.08
L9800 12650N	Soil		0.6	20.4	193.9	301	2.1	17.2	7.8	934	2.56	423.3	3.0	11.6	8.6	27	1.8	42.0	0.6	57	0.49
L9800 12700N	Soil		1.1	20.8	192.0	376	1.5	19.7	10.4	1333	3.73	695.8	4.3	18.6	5.9	25	1.9	71.0	0.9	54	0.34
L9800 12725N	Soil		1.2	28.6	136.3	278	1.8	18.6	8.7	1554	2.93	501.7	7.2	24.1	3.4	37	1.8	54.6	0.6	40	0.64
L9800 12750N	Soil		1.0	24.1	132.2	277	1.2	33.0	12.2	1063	4.02	712.0	4.6	32.9	7.9	25	1.3	57.6	0.6	60	0.40
L9800 12775N	Soil		1.0	29.3	189.9	256	2.2	28.2	10.2	1027	3.44	482.5	6.7	33.8	6.4	36	1.7	75.7	0.6	54	0.65
L9800 12800N	Soil		0.9	23.7	77.4	196	1.1	23.1	8.8	623	2.90	305.5	4.5	21.6	5.1	31	1.0	41.2	0.6	54	0.56
L9800 12825N	Soil		0.7	24.2	59.4	170	0.8	22.4	9.2	650	2.51	164.1	5.1	17.2	6.5	28	1.0	33.0	0.5	52	0.51
L9800 12850N	Soil		0.9	25.6	68.8	178	0.6	26.0	11.1	853	3.35	177.1	4.7	12.5	7.9	22	1.1	31.4	0.5	57	0.38
L9800 12875N	Soil		1.0	28.3	47.4	285	0.6	30.5	11.6	844	3.35	206.8	5.6	17.9	5.7	26	0.8	22.7	0.5	69	0.39
L9800 12900N	Soil		1.3	29.0	62.9	221	0.8	25.9	9.2	598	3.41	262.2	7.1	12.5	2.9	40	1.6	34.0	0.6	65	0.68
L9800 12925N	Soil		1.8	27.2	55.5	181	0.9	27.5	23.0	5367	3.75	203.2	6.6	14.7	3.4	34	2.8	47.6	0.4	64	0.54

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

CERTIFICATE OF ANALYSIS SMI09000076.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L9600 12875N	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
L9600 12900N	Soil	0.057	16	32	0.55	114	0.075	<1	1.58	0.014	0.09	0.9	0.03	2.8	0.2	<0.05	5	<0.5
L9600 12925N	Soil	0.066	20	33	0.60	135	0.084	<1	1.82	0.025	0.10	0.3	0.04	3.9	0.2	<0.05	6	<0.5
L9600 12950N	Soil	0.120	22	34	0.56	216	0.095	<1	1.64	0.017	0.13	0.2	0.04	4.9	0.4	<0.05	7	0.7
L9600 12975N	Soil	0.080	27	40	0.62	224	0.052	<1	2.14	0.017	0.06	0.2	0.06	3.9	0.3	<0.05	7	<0.5
L9600 13000N	Soil	0.076	18	39	0.54	138	0.058	<1	1.99	0.012	0.08	0.3	0.03	3.4	0.3	<0.05	7	<0.5
L9600 13025N	Soil	0.121	15	39	0.42	163	0.040	<1	1.65	0.013	0.05	0.2	0.05	2.9	0.2	0.07	6	0.6
L9600 13050N	Soil	0.100	21	31	0.43	198	0.034	<1	1.54	0.011	0.06	0.2	0.03	2.6	0.2	<0.05	6	<0.5
L9600 13075N	Soil	0.061	17	38	0.53	137	0.054	<1	1.88	0.013	0.07	0.3	0.03	3.0	0.2	<0.05	6	<0.5
L9600 13100N	Soil	0.089	11	34	0.46	160	0.052	<1	1.51	0.015	0.05	0.2	0.02	2.7	0.2	<0.05	6	<0.5
L9600 13125N	Soil	0.077	13	41	0.58	186	0.057	<1	2.08	0.015	0.08	0.3	0.02	3.3	0.2	<0.05	7	<0.5
L9600 13150N	Soil	0.074	18	38	0.56	210	0.071	<1	2.09	0.025	0.07	0.3	0.03	3.5	0.2	<0.05	6	<0.5
L9600 13175N	Soil	0.061	18	38	0.57	191	0.063	<1	1.97	0.018	0.06	0.8	0.04	3.6	0.2	<0.05	6	0.6
L9600 13200N	Soil	0.068	18	38	0.59	227	0.066	<1	2.23	0.020	0.06	0.3	0.04	3.6	0.2	<0.05	6	0.8
L9600 13225N	Soil	0.098	28	39	0.56	271	0.079	<1	2.39	0.024	0.15	0.7	0.05	4.1	0.2	<0.05	7	<0.5
L9600 13250N	Soil	0.052	9	39	0.56	180	0.090	<1	2.71	0.016	0.08	0.4	0.06	3.0	0.2	<0.05	10	<0.5
L9800 12575N	Soil	0.073	20	30	0.45	118	0.047	<1	1.39	0.017	0.10	0.4	0.09	3.1	0.2	0.06	5	0.7
L9800 12600N	Soil	0.071	16	33	0.53	114	0.076	<1	1.53	0.020	0.09	0.6	0.04	3.1	<0.1	<0.05	5	<0.5
L9800 12625N	Soil	0.094	13	23	0.11	57	0.026	<1	0.86	0.013	0.05	0.1	0.12	1.4	0.1	0.07	4	0.6
L9800 12650N	Soil	0.078	21	29	0.44	107	0.077	<1	1.21	0.023	0.09	0.4	0.02	2.8	0.1	<0.05	4	<0.5
L9800 12700N	Soil	0.079	19	36	0.52	128	0.031	<1	1.78	0.013	0.12	0.2	0.04	3.2	0.2	<0.05	6	<0.5
L9800 12725N	Soil	0.108	28	29	0.36	148	0.021	<1	1.33	0.016	0.10	0.2	0.06	2.7	0.1	0.09	4	0.5
L9800 12750N	Soil	0.063	20	54	0.67	134	0.052	<1	1.78	0.014	0.11	0.8	0.04	3.5	0.1	<0.05	5	0.5
L9800 12775N	Soil	0.079	23	40	0.58	150	0.048	<1	1.67	0.018	0.11	0.4	0.05	4.1	0.1	<0.05	5	<0.5
L9800 12800N	Soil	0.060	18	36	0.53	129	0.052	<1	1.58	0.018	0.09	0.6	0.04	3.3	0.1	<0.05	5	0.5
L9800 12825N	Soil	0.071	21	35	0.55	128	0.061	<1	1.62	0.018	0.09	0.4	0.03	3.6	0.1	<0.05	5	0.5
L9800 12850N	Soil	0.075	21	38	0.58	139	0.070	<1	1.78	0.017	0.09	0.5	0.04	4.2	0.1	<0.05	5	<0.5
L9800 12875N	Soil	0.076	22	44	0.66	153	0.076	<1	2.17	0.018	0.09	0.4	0.04	4.4	0.1	<0.05	7	0.6
L9800 12900N	Soil	0.099	19	41	0.60	171	0.049	1	2.04	0.027	0.08	0.2	0.05	4.0	0.2	0.08	7	0.5
L9800 12925N	Soil	0.109	19	45	0.58	216	0.046	<1	2.01	0.017	0.08	0.2	0.05	4.3	0.2	0.06	7	0.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

CERTIFICATE OF ANALYSIS SMI09000076.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L9800 12950N	Soil		1.0	25.0	74.5	191	0.5	27.2	13.1	376	3.17	189.9	5.0	9.7	7.1	22	0.9	29.4	0.4	64	0.34
L9800 12975N	Soil		1.3	19.2	50.4	164	0.5	22.3	12.9	715	3.50	163.1	3.5	6.5	2.5	29	0.3	28.4	0.4	72	0.45
L9800 13000N	Soil		1.3	14.7	45.8	287	0.5	20.8	13.1	1261	3.25	181.8	6.1	8.2	5.7	26	0.8	22.2	0.3	58	0.40
L9800 13025N	Soil		1.1	24.5	72.4	242	0.5	28.4	9.9	614	3.28	193.8	7.5	11.7	7.5	24	1.3	29.1	0.4	66	0.41
L9800 13050N	Soil		1.2	14.2	66.5	186	0.3	19.7	8.0	340	2.56	86.3	4.3	6.4	6.8	22	0.6	22.3	0.3	60	0.37
L9800 13075N	Soil		1.9	16.7	48.9	166	0.4	16.7	12.7	1201	3.56	161.4	6.1	4.5	2.7	30	1.0	27.9	0.5	76	0.47
L9800 13100N	Soil		1.6	19.8	86.6	198	0.6	27.0	16.4	1542	4.91	270.1	4.1	8.0	5.4	34	1.1	33.7	0.3	84	0.53
L9800 13125N	Soil		0.6	18.9	67.5	135	0.3	21.9	11.4	643	2.40	59.0	2.2	5.0	7.5	22	0.4	20.5	0.3	62	0.38
L9800 13150N	Soil		0.9	19.4	57.5	140	0.3	23.3	12.9	394	3.00	88.0	2.8	5.9	5.9	21	0.6	17.4	0.3	69	0.34
L9800 13175N	Soil		1.3	15.4	42.9	90	0.3	19.9	13.3	1227	3.02	57.0	2.7	7.0	4.2	24	0.4	14.6	0.3	63	0.40
L10000 12625N	Soil		1.0	24.4	206.1	343	2.1	21.4	8.1	684	3.00	575.0	3.6	68.9	5.5	21	1.3	16.5	1.1	57	0.28
L10000 12825N	Soil		1.1	22.6	41.1	96	0.2	28.3	10.0	312	2.66	62.2	3.3	7.4	7.5	30	0.3	8.3	0.3	63	0.52
L10000 12850N	Soil		1.4	18.2	45.1	105	0.2	26.2	12.4	674	3.36	116.4	1.6	4.1	6.2	24	0.6	10.0	0.4	74	0.31
L10000 12875N	Soil		1.7	22.7	43.1	111	0.3	23.9	14.4	574	3.61	134.9	4.8	3.7	5.9	28	0.5	9.6	0.4	66	0.48
L10000 12900N	Soil		1.1	17.1	43.3	98	0.2	23.4	9.9	315	2.77	90.2	2.5	11.0	6.3	25	0.4	9.6	0.4	63	0.42
L10000 12925N	Soil		0.9	21.6	40.1	112	0.2	24.5	11.1	409	2.69	62.0	2.9	8.4	6.7	21	0.4	9.1	0.4	61	0.33
L10000 12950N	Soil		0.9	17.9	38.6	101	0.2	23.1	10.0	306	2.52	58.8	2.1	13.6	5.8	21	0.4	8.4	0.4	59	0.33
L10000 12975N	Soil		0.7	19.9	33.5	101	0.2	24.3	12.7	677	2.65	48.3	2.2	15.6	5.5	24	0.5	5.6	0.3	63	0.39
L10000 13000N	Soil		0.9	19.6	28.5	113	0.2	24.9	11.0	714	2.91	52.6	2.5	8.2	4.5	22	0.6	4.3	0.3	65	0.32
L10000 13025N	Soil		1.5	13.4	30.9	83	0.1	19.3	8.3	421	2.76	51.6	1.4	4.6	2.9	15	0.5	4.2	0.3	77	0.18
L10000 13050N	Soil		1.8	29.0	110.6	155	0.5	23.8	12.4	1376	3.18	212.0	4.7	40.9	3.6	33	1.0	27.5	1.3	52	0.52
L10000 13075N	Soil		2.2	23.3	66.4	136	0.5	26.4	10.8	894	4.64	381.6	4.0	6.9	4.4	28	0.9	8.6	0.6	90	0.39
L10000 13100N	Soil		0.7	19.0	55.9	118	0.3	22.2	11.8	670	2.92	73.4	2.3	4.5	7.0	22	0.6	7.1	0.4	65	0.37
L10000 13125N	Soil		1.0	11.7	51.5	130	0.2	20.8	14.5	1721	2.90	71.0	1.6	3.9	5.2	23	0.5	5.7	0.4	60	0.36
L10000 13150N	Soil		6.5	21.0	99.2	151	0.7	18.6	89.7	9468	10.00	1111	6.4	7.1	3.1	39	2.2	26.8	0.5	129	0.52
L10000 13175N	Soil		0.9	12.6	53.9	186	0.7	17.8	13.3	2164	2.59	102.3	4.2	10.9	3.3	23	1.1	8.7	0.4	47	0.36
L10000 13200N	Soil		1.1	14.6	52.0	165	0.8	20.3	10.7	600	3.33	167.4	3.9	6.6	2.7	26	0.8	10.6	0.5	56	0.35
L10200 12550N	Soil		0.8	25.1	323.9	392	2.4	23.1	9.2	736	3.19	805.1	7.5	98.7	8.4	29	2.2	13.5	1.9	56	0.50
L10200 12600N	Soil		1.2	25.4	114.1	120	0.8	17.9	6.8	427	2.56	149.3	5.1	7.8	1.8	22	0.7	8.2	0.4	58	0.28
L10200 12650N	Soil		0.9	21.1	435.9	167	2.1	25.4	11.5	737	3.33	656.3	5.0	12.2	5.0	20	0.8	7.2	0.3	62	0.29

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

CERTIFICATE OF ANALYSIS SMI09000076.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L9800 12950N	Soil	0.078	20	45	0.67	163	0.086	<1	2.19	0.018	0.10	0.3	0.04	5.0	0.2	<0.05	7	0.5
L9800 12975N	Soil	0.092	13	43	0.66	125	0.055	<1	1.99	0.016	0.07	0.2	0.04	3.3	0.2	0.05	7	<0.5
L9800 13000N	Soil	0.078	22	38	0.59	147	0.066	<1	1.93	0.017	0.08	0.2	0.08	4.0	0.3	<0.05	6	<0.5
L9800 13025N	Soil	0.078	24	43	0.57	134	0.081	<1	2.04	0.018	0.10	0.3	0.06	5.2	0.5	<0.05	6	0.6
L9800 13050N	Soil	0.073	19	38	0.59	102	0.080	1	1.83	0.017	0.08	0.6	0.05	3.6	0.3	<0.05	6	<0.5
L9800 13075N	Soil	0.166	16	40	0.50	128	0.054	1	1.63	0.015	0.06	0.3	0.06	3.6	0.3	0.08	7	0.6
L9800 13100N	Soil	0.098	17	47	0.63	193	0.105	<1	2.34	0.029	0.09	0.3	0.06	4.7	0.3	<0.05	7	0.6
L9800 13125N	Soil	0.061	19	39	0.61	127	0.093	<1	2.07	0.018	0.08	0.3	0.04	3.8	0.3	<0.05	6	<0.5
L9800 13150N	Soil	0.073	17	43	0.62	143	0.080	<1	2.21	0.019	0.08	0.3	0.03	4.5	0.2	<0.05	6	<0.5
L9800 13175N	Soil	0.085	16	39	0.58	149	0.083	<1	1.89	0.017	0.07	0.3	0.03	3.5	0.2	<0.05	7	<0.5
L10000 12625N	Soil	0.068	24	37	0.52	127	0.060	<1	1.95	0.015	0.10	0.3	0.05	4.0	0.2	<0.05	6	0.6
L10000 12825N	Soil	0.069	20	47	0.70	119	0.116	<1	2.05	0.023	0.14	0.4	0.03	3.9	0.2	<0.05	7	<0.5
L10000 12850N	Soil	0.050	17	42	0.59	118	0.096	<1	1.98	0.017	0.11	0.4	0.03	3.2	0.1	<0.05	8	0.5
L10000 12875N	Soil	0.070	26	42	0.60	147	0.085	<1	1.97	0.020	0.10	0.3	0.04	4.7	0.2	<0.05	7	0.5
L10000 12900N	Soil	0.064	16	37	0.63	119	0.102	2	1.85	0.024	0.11	0.4	0.03	3.6	0.2	<0.05	6	<0.5
L10000 12925N	Soil	0.063	18	38	0.64	135	0.109	<1	1.95	0.016	0.11	0.4	0.04	4.2	0.2	<0.05	6	<0.5
L10000 12950N	Soil	0.065	15	37	0.65	118	0.103	2	1.83	0.016	0.11	0.4	0.03	3.6	0.2	<0.05	6	<0.5
L10000 12975N	Soil	0.074	16	36	0.61	143	0.106	2	1.73	0.017	0.10	0.5	0.02	3.7	0.1	<0.05	6	<0.5
L10000 13000N	Soil	0.073	16	36	0.60	146	0.094	1	1.80	0.015	0.10	0.5	0.03	3.6	0.1	<0.05	6	<0.5
L10000 13025N	Soil	0.045	12	34	0.45	106	0.099	2	1.62	0.013	0.07	0.2	0.04	2.6	0.1	<0.05	7	<0.5
L10000 13050N	Soil	0.089	22	32	0.37	189	0.039	2	1.49	0.015	0.11	0.4	0.05	3.6	0.2	<0.05	5	0.5
L10000 13075N	Soil	0.092	23	43	0.59	194	0.066	1	2.29	0.017	0.08	0.4	0.06	4.6	0.2	<0.05	7	0.5
L10000 13100N	Soil	0.073	18	38	0.64	147	0.102	1	1.89	0.014	0.11	0.3	0.02	4.3	0.2	<0.05	6	<0.5
L10000 13125N	Soil	0.074	14	34	0.62	150	0.088	1	1.84	0.013	0.08	0.3	0.03	3.2	0.2	<0.05	7	<0.5
L10000 13150N	Soil	0.173	24	35	0.30	273	0.042	<1	1.46	0.014	0.05	0.2	0.06	4.5	0.3	0.08	6	0.6
L10000 13175N	Soil	0.112	18	34	0.49	148	0.068	1	1.90	0.018	0.08	0.3	0.06	4.1	0.3	<0.05	7	0.5
L10000 13200N	Soil	0.128	15	46	0.54	147	0.064	2	2.07	0.016	0.07	0.2	0.05	4.2	0.2	0.06	7	0.6
L10200 12550N	Soil	0.076	34	34	0.53	172	0.069	1	1.73	0.016	0.11	0.8	0.04	4.6	0.2	<0.05	5	<0.5
L10200 12600N	Soil	0.072	30	31	0.35	177	0.052	2	1.76	0.015	0.06	0.2	0.05	2.9	0.1	<0.05	6	<0.5
L10200 12650N	Soil	0.072	30	32	0.54	147	0.057	2	1.97	0.013	0.08	0.3	0.05	3.2	0.4	<0.05	6	0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

CERTIFICATE OF ANALYSIS SMI09000076.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L10200 12675N	Soil		0.7	16.9	318.9	436	2.6	21.2	8.6	729	2.84	153.9	5.4	13.3	6.3	20	1.1	17.1	0.4	55	0.33
L10200 12700N	Soil		1.0	22.8	81.9	163	0.5	27.7	11.0	773	3.57	114.3	4.0	7.8	6.0	23	0.9	20.9	0.4	63	0.32
L10200 12725N	Soil		0.9	24.9	36.0	95	0.2	26.9	8.2	351	2.84	53.0	4.8	4.7	7.6	21	0.4	2.6	0.3	65	0.36
L10200 12750N	Soil		0.8	24.5	26.3	90	0.2	30.1	10.7	442	3.22	60.2	13.5	6.2	10.5	29	0.4	3.7	0.6	66	0.47
L10200 12775N	Soil		0.8	21.9	382.5	548	2.8	20.7	7.8	2008	3.60	1560	6.4	30.8	10.8	26	3.4	15.6	0.4	46	0.31
L10200 12800N	Soil		0.9	22.0	2919	955	11.6	24.4	9.2	2699	4.37	5104	4.3	51.8	8.0	20	11.6	35.4	0.4	48	0.26
L10200 12825N	Soil		0.9	20.8	1073	1019	5.1	25.4	11.0	2212	3.60	1773	3.5	26.6	8.9	18	5.1	16.2	0.4	50	0.26
L10200 12850N	Soil		1.3	18.8	119.9	272	0.8	24.7	12.0	780	3.19	277.3	3.1	6.6	7.6	21	0.8	11.2	0.4	60	0.36
L10200 12875N	Soil		0.8	25.9	128.6	240	0.8	31.4	10.9	508	3.22	181.1	3.8	7.1	8.4	27	0.9	4.5	0.3	66	0.45
L10200 12900N	Soil		1.4	19.0	56.4	124	0.5	19.1	10.3	693	3.13	127.1	1.5	1.8	4.3	20	0.7	2.6	0.3	70	0.24
L10200 12925N	Soil		2.1	17.7	13.1	38	0.1	11.8	4.0	136	1.86	17.1	1.3	1.2	2.7	12	0.6	0.9	0.3	67	0.11
L10200 12950N	Soil		1.3	25.0	65.4	166	0.3	28.0	13.3	916	3.37	109.3	2.9	6.6	4.8	26	0.8	2.3	0.3	74	0.40
L10200 13000N	Soil		1.6	26.5	58.3	121	0.3	29.4	12.3	793	3.27	88.8	3.4	8.0	6.2	23	0.6	2.5	0.3	70	0.36
L10200 13050N	Soil		2.6	32.1	55.8	139	0.4	27.9	13.2	989	3.31	93.7	5.9	5.4	3.7	32	0.7	2.4	0.5	68	0.49
L10200 13075N	Soil		1.2	16.2	45.0	113	0.2	24.2	9.8	249	2.48	40.6	2.3	4.4	6.0	29	0.3	2.1	0.3	62	0.51
L10200 13100N	Soil		2.4	22.4	80.1	182	0.5	26.8	12.7	706	2.83	166.4	4.7	5.2	4.8	29	0.6	3.0	0.5	61	0.48
L10200 13125N	Soil		0.9	17.7	39.4	156	0.3	22.6	9.7	682	2.48	61.0	3.2	6.6	4.1	30	0.8	2.8	0.4	55	0.55
L10200 13150N	Soil		1.5	23.1	44.5	130	0.3	29.2	11.6	681	2.99	73.0	4.1	15.8	5.6	24	0.5	2.4	0.3	66	0.39

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

CERTIFICATE OF ANALYSIS SMI09000076.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L10200 12675N	Soil	0.051	19	32	0.51	124	0.053	3	1.73	0.014	0.08	0.2	0.11	3.2	0.3	<0.05	5	<0.5
L10200 12700N	Soil	0.058	23	35	0.55	207	0.063	<1	2.06	0.013	0.09	0.3	0.04	3.6	0.2	<0.05	6	<0.5
L10200 12725N	Soil	0.066	24	40	0.56	167	0.087	<1	1.95	0.016	0.07	0.3	0.04	5.3	0.2	<0.05	6	<0.5
L10200 12750N	Soil	0.076	28	44	0.71	171	0.112	2	2.12	0.017	0.15	0.5	0.04	6.1	0.3	<0.05	7	<0.5
L10200 12775N	Soil	0.063	23	36	0.48	103	0.064	2	1.68	0.013	0.15	0.4	0.15	4.3	0.6	<0.05	5	<0.5
L10200 12800N	Soil	0.064	19	35	0.58	167	0.070	<1	1.57	0.011	0.23	0.6	0.15	3.7	0.6	<0.05	6	<0.5
L10200 12825N	Soil	0.059	23	33	0.49	113	0.062	<1	1.66	0.011	0.12	0.3	0.11	3.5	0.5	<0.05	5	0.5
L10200 12850N	Soil	0.075	22	40	0.61	127	0.094	3	2.04	0.015	0.12	0.5	0.04	4.6	0.2	<0.05	6	<0.5
L10200 12875N	Soil	0.075	22	53	0.71	146	0.124	1	2.00	0.021	0.15	0.4	0.04	5.3	0.3	<0.05	6	<0.5
L10200 12900N	Soil	0.061	16	33	0.48	111	0.087	2	1.74	0.013	0.09	0.3	0.06	2.7	0.2	<0.05	7	<0.5
L10200 12925N	Soil	0.042	15	19	0.15	49	0.069	<1	0.99	0.014	0.07	0.2	0.08	1.2	0.1	<0.05	7	<0.5
L10200 12950N	Soil	0.087	17	38	0.62	152	0.093	2	1.87	0.016	0.13	0.4	0.05	3.4	0.2	<0.05	7	<0.5
L10200 13000N	Soil	0.084	17	37	0.57	153	0.095	2	2.03	0.017	0.10	0.4	0.03	3.5	0.2	<0.05	7	<0.5
L10200 13050N	Soil	0.095	20	36	0.62	164	0.073	2	2.04	0.023	0.12	0.2	0.11	3.7	0.2	<0.05	7	<0.5
L10200 13075N	Soil	0.072	16	34	0.60	129	0.110	1	1.62	0.023	0.09	0.3	0.03	3.3	0.1	<0.05	5	<0.5
L10200 13100N	Soil	0.076	20	35	0.52	139	0.079	<1	1.75	0.020	0.08	0.3	0.03	3.6	0.2	<0.05	6	<0.5
L10200 13125N	Soil	0.084	18	33	0.59	152	0.083	2	1.58	0.017	0.09	0.3	0.04	3.7	0.1	<0.05	6	<0.5
L10200 13150N	Soil	0.073	21	39	0.61	150	0.094	2	1.91	0.017	0.10	0.3	0.05	4.1	0.2	<0.05	6	0.6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

QUALITY CONTROL REPORT SMI09000076.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
L9400 13050N	Soil		1.6	21.5	29.2	123	0.4	22.0	7.9	445	2.59	103.4	2.7	6.4	2.6	27	0.5	5.7	0.4	62	0.39
REP L9400 13050N	QC		1.8	21.2	30.7	123	0.4	22.1	8.4	451	2.66	104.1	2.6	11.5	2.7	26	0.5	6.0	0.4	63	0.38
L9600 12700N	Soil		0.9	22.1	43.5	102	0.5	20.1	9.4	521	2.36	106.3	3.3	15.2	6.0	32	0.6	16.7	0.5	54	0.52
REP L9600 12700N	QC		1.0	21.2	42.9	101	0.5	20.7	8.9	514	2.30	105.5	3.1	11.6	5.9	32	0.5	16.7	0.5	54	0.52
L9800 12750N	Soil		1.0	24.1	132.2	277	1.2	33.0	12.2	1063	4.02	712.0	4.6	32.9	7.9	25	1.3	57.6	0.6	60	0.40
REP L9800 12750N	QC		1.0	23.2	128.6	275	1.1	34.2	12.0	1055	4.00	699.3	4.5	29.7	8.1	26	1.3	55.7	0.6	61	0.42
L9800 13100N	Soil		1.6	19.8	86.6	198	0.6	27.0	16.4	1542	4.91	270.1	4.1	8.0	5.4	34	1.1	33.7	0.3	84	0.53
REP L9800 13100N	QC		1.7	20.8	87.9	199	0.7	26.2	16.5	1541	4.92	269.6	4.1	5.7	5.4	34	1.0	33.6	0.4	83	0.54
L10200 12675N	Soil		0.7	16.9	318.9	436	2.6	21.2	8.6	729	2.84	153.9	5.4	13.3	6.3	20	1.1	17.1	0.4	55	0.33
REP L10200 12675N	QC		0.8	17.1	322.3	447	2.6	20.3	8.6	735	2.84	157.3	5.3	16.9	6.4	19	1.0	16.4	0.4	56	0.34
L10200 12800N	Soil		0.9	22.0	2919	955	11.6	24.4	9.2	2699	4.37	5104	4.3	51.8	8.0	20	11.6	35.4	0.4	48	0.26
REP L10200 12800N	QC		0.9	22.2	3010	959	11.8	25.6	9.4	2719	4.44	5208	4.4	49.4	8.2	20	12.1	36.4	0.4	49	0.26
Reference Materials																					
STD DS7	Standard		18.6	103.2	68.2	382	0.8	54.4	9.1	614	2.38	49.2	4.7	74.2	4.3	74	6.2	5.5	4.5	82	0.96
STD DS7	Standard		20.5	108.1	66.2	397	0.8	57.7	9.6	662	2.52	50.1	4.7	62.0	4.3	82	6.6	5.5	4.5	91	1.05
STD DS7	Standard		19.8	108.1	66.7	402	0.8	56.9	9.8	642	2.46	48.8	4.7	57.8	4.2	75	6.4	5.7	4.5	90	1.02
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 08, 2009

QUALITY CONTROL REPORT SMI09000076.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
L9400 13050N	Soil	0.083	11	35	0.57	135	0.070	<1	1.74	0.012	0.07	0.5	0.02	2.9	0.1	<0.05	6	<0.5
REP L9400 13050N	QC	0.085	12	35	0.57	146	0.072	<1	1.75	0.013	0.08	0.6	0.02	2.9	0.1	<0.05	6	0.6
L9600 12700N	Soil	0.061	17	31	0.52	127	0.075	<1	1.44	0.023	0.08	1.1	0.04	3.3	0.2	<0.05	5	<0.5
REP L9600 12700N	QC	0.058	17	31	0.52	128	0.076	1	1.42	0.021	0.08	0.7	0.03	3.2	0.1	<0.05	5	<0.5
L9800 12750N	Soil	0.063	20	54	0.67	134	0.052	<1	1.78	0.014	0.11	0.8	0.04	3.5	0.1	<0.05	5	0.5
REP L9800 12750N	QC	0.066	20	54	0.67	131	0.056	<1	1.79	0.016	0.12	0.8	0.03	3.6	0.1	<0.05	5	<0.5
L9800 13100N	Soil	0.098	17	47	0.63	193	0.105	<1	2.34	0.029	0.09	0.3	0.06	4.7	0.3	<0.05	7	0.6
REP L9800 13100N	QC	0.097	18	47	0.64	191	0.103	<1	2.32	0.030	0.09	0.2	0.05	4.8	0.2	<0.05	7	<0.5
L10200 12675N	Soil	0.051	19	32	0.51	124	0.053	3	1.73	0.014	0.08	0.2	0.11	3.2	0.3	<0.05	5	<0.5
REP L10200 12675N	QC	0.050	20	33	0.52	129	0.054	<1	1.83	0.015	0.08	0.3	0.10	3.3	0.3	<0.05	5	<0.5
L10200 12800N	Soil	0.064	19	35	0.58	167	0.070	<1	1.57	0.011	0.23	0.6	0.15	3.7	0.6	<0.05	6	<0.5
REP L10200 12800N	QC	0.070	19	35	0.59	165	0.070	1	1.65	0.013	0.23	0.5	0.16	3.5	0.6	<0.05	6	<0.5
Reference Materials																		
STD DS7	Standard	0.077	12	205	1.03	389	0.112	37	1.05	0.108	0.46	3.7	0.17	2.4	4.4	0.16	5	3.8
STD DS7	Standard	0.080	14	242	1.08	407	0.128	40	1.15	0.122	0.47	3.7	0.19	2.6	4.2	0.17	5	3.8
STD DS7	Standard	0.077	13	229	1.06	419	0.123	42	1.05	0.100	0.48	3.8	0.18	2.4	4.1	0.17	5	3.3
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 05, 2009
Report Date: August 14, 2009
Page: 1 of 4

CERTIFICATE OF ANALYSIS SMI09000103.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 71

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	71	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	71	Dry at 60C			SMI
1DX15	66	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000103.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
RDCX 01	Soil		1.1	27.3	16.5	66	<0.1	34.4	17.2	531	4.17	78.3	1.4	3.4	9.0	18	0.3	1.4	0.7	85	0.20
RDCX 02	Soil		1.3	20.7	15.7	51	<0.1	27.7	11.9	301	3.59	22.1	0.9	3.2	4.6	18	0.3	2.0	0.3	94	0.21
RDCX 03	Soil		0.5	19.2	23.4	52	<0.1	25.9	7.4	185	2.27	7.3	1.3	3.5	10.5	20	0.2	0.5	0.3	61	0.32
RDCX 04	Soil		0.7	20.5	10.8	53	<0.1	30.0	12.8	474	2.78	7.2	1.3	3.2	7.8	18	0.3	0.5	0.2	64	0.26
RDCX 05	Soil		0.7	27.5	10.7	59	<0.1	25.8	13.3	474	3.10	8.5	1.8	2.7	7.5	23	0.2	0.5	0.3	72	0.32
RDCX 06	Soil		0.7	27.1	9.5	59	<0.1	35.1	15.2	492	3.08	9.5	0.9	1.7	4.9	22	0.3	0.6	0.2	75	0.30
RDCX 07	Soil		0.5	30.9	14.2	52	<0.1	24.8	9.4	234	2.89	18.2	1.8	3.3	8.8	25	0.1	1.1	0.2	68	0.31
RDCX 08	Soil		1.3	22.8	12.5	58	<0.1	27.4	12.6	466	3.34	10.0	1.2	3.0	4.0	17	0.2	0.7	0.2	77	0.18
RDCX 09	Soil		0.9	20.5	11.8	57	<0.1	30.2	12.2	399	3.23	9.9	0.8	3.6	3.7	16	0.2	0.7	0.2	70	0.19
CRCX 01	Soil		0.6	19.6	8.1	55	<0.1	24.4	11.3	482	2.59	5.9	1.9	7.4	7.1	20	0.2	0.4	0.3	62	0.32
CRCX 02	Soil		0.9	24.7	13.8	62	<0.1	25.4	12.2	579	3.12	49.1	2.8	21.6	8.5	19	0.3	3.4	0.4	77	0.27
L9000 11800N	Soil		5.7	32.6	22.3	100	0.1	27.1	15.9	1034	3.88	42.5	13.9	4.9	6.5	33	0.4	1.7	0.2	78	0.42
L9000 11825N	Soil		1.7	29.6	15.8	78	<0.1	23.3	11.9	594	2.95	18.3	3.4	2.0	7.6	33	0.3	0.9	0.2	75	0.35
L9000 11850N	Soil		1.6	23.4	26.8	102	0.2	19.2	12.9	781	3.33	40.5	3.3	4.4	7.1	34	0.5	1.3	0.2	79	0.36
L9000 11875N	Soil		1.4	19.9	47.8	131	0.2	30.0	11.6	423	2.94	36.7	3.7	4.2	10.0	31	0.7	2.2	0.5	80	0.48
L9000 11900N	Soil		4.4	26.2	45.8	126	0.3	27.8	12.7	855	3.12	55.8	4.2	5.4	13.1	29	0.7	7.2	0.4	79	0.48
L9000 11925N	Soil		2.2	46.6	45.2	130	0.3	28.1	11.6	390	2.76	53.6	4.6	6.2	11.9	27	0.9	6.2	0.6	76	0.42
L9000 11950N	Soil		2.0	38.4	33.1	124	0.3	27.8	13.7	991	3.54	94.6	4.6	8.5	7.7	34	0.7	9.1	0.3	75	0.50
L9000 11975N	Soil		3.3	27.6	62.8	129	0.4	23.8	11.2	643	2.97	155.9	2.5	7.9	3.7	39	0.6	15.8	0.6	67	0.34
L9000 12000N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9000 12025N	Soil		7.4	91.0	29.5	215	0.5	78.6	23.2	1296	4.81	108.9	7.9	4.0	10.4	42	1.0	9.4	0.3	120	0.27
L9000 12225N	Soil		3.9	47.3	79.6	255	0.9	40.5	12.9	1035	3.61	323.3	3.7	26.3	4.6	52	1.3	11.2	0.5	86	0.42
L9000 12250N	Soil		3.7	65.7	54.9	288	0.7	56.8	16.3	1169	4.05	292.9	4.2	18.1	4.9	36	1.1	10.4	0.5	107	0.35
L9000 12275N	Soil		3.0	39.2	46.6	147	0.5	34.1	11.0	507	3.18	151.0	2.5	11.7	4.9	30	0.5	6.8	0.6	67	0.38
L9000 12300N	Soil		3.3	53.2	105.2	213	1.5	35.8	15.0	1191	3.31	346.8	4.5	14.6	3.5	34	1.3	6.9	0.6	76	0.38
L9000 12325N	Soil		3.0	26.0	30.9	50	0.5	19.2	4.4	159	1.68	40.1	1.2	3.4	0.2	24	0.4	2.1	0.3	48	0.19
L9000 12350N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9000 12375N	Soil		6.1	45.7	188.8	333	3.0	30.3	7.1	343	2.86	580.6	4.1	74.8	4.8	29	1.7	19.4	4.1	73	0.40
L9000 12400N	Soil		5.2	56.0	543.1	483	8.3	34.7	9.8	662	3.46	1058	4.8	53.5	5.5	30	2.4	37.7	1.6	71	0.35
L9000 12425N	Soil		4.7	35.4	146.6	341	1.3	31.0	10.9	975	3.12	351.3	3.8	14.7	7.2	40	1.6	11.9	1.4	73	0.38

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000103.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
RDCX 01	Soil	0.036	13	50	0.74	134	0.144	2	3.07	0.016	0.15	0.6	0.03	6.1	0.3	<0.05	9	<0.5
RDCX 02	Soil	0.026	11	42	0.49	104	0.145	2	2.59	0.014	0.07	0.4	0.03	3.7	0.1	<0.05	8	<0.5
RDCX 03	Soil	0.054	18	37	0.55	104	0.117	<1	1.73	0.016	0.06	0.4	0.02	3.8	0.1	<0.05	5	<0.5
RDCX 04	Soil	0.049	12	37	0.55	115	0.109	2	2.29	0.016	0.06	0.7	0.02	3.7	0.1	<0.05	6	<0.5
RDCX 05	Soil	0.062	23	42	0.62	128	0.135	1	2.49	0.015	0.08	0.4	0.02	5.2	0.1	<0.05	7	<0.5
RDCX 06	Soil	0.039	9	44	0.74	150	0.137	2	2.69	0.019	0.09	2.0	0.02	4.7	0.1	<0.05	6	<0.5
RDCX 07	Soil	0.042	19	41	0.61	162	0.125	2	2.46	0.017	0.06	0.2	0.03	5.7	0.1	<0.05	6	<0.5
RDCX 08	Soil	0.047	12	40	0.57	118	0.092	<1	2.52	0.014	0.06	0.2	0.03	3.7	0.1	<0.05	7	<0.5
RDCX 09	Soil	0.036	9	39	0.57	109	0.104	2	2.36	0.014	0.06	0.1	0.05	3.5	0.2	<0.05	7	<0.5
CRCX 01	Soil	0.065	15	33	0.46	90	0.116	2	1.49	0.022	0.08	0.9	0.02	3.2	<0.1	<0.05	5	<0.5
CRCX 02	Soil	0.055	22	36	0.52	114	0.113	1	1.73	0.016	0.06	0.3	0.06	3.8	<0.1	<0.05	5	<0.5
L9000 11800N	Soil	0.076	27	36	0.70	250	0.062	2	2.14	0.017	0.08	0.1	0.07	5.1	0.2	<0.05	7	0.7
L9000 11825N	Soil	0.099	18	32	0.65	213	0.107	2	1.97	0.025	0.09	0.8	0.07	4.1	0.2	<0.05	6	<0.5
L9000 11850N	Soil	0.093	22	31	0.65	238	0.106	1	1.92	0.022	0.08	0.2	0.04	4.9	0.3	0.06	6	<0.5
L9000 11875N	Soil	0.082	17	53	0.93	201	0.090	2	2.35	0.016	0.07	0.1	0.03	5.4	0.2	<0.05	7	<0.5
L9000 11900N	Soil	0.085	21	56	0.90	183	0.083	<1	2.21	0.015	0.09	0.2	0.03	5.2	0.2	<0.05	8	<0.5
L9000 11925N	Soil	0.081	24	39	0.71	211	0.087	2	1.98	0.017	0.11	0.2	0.03	6.0	0.2	<0.05	6	0.6
L9000 11950N	Soil	0.083	22	39	0.60	224	0.107	2	1.74	0.017	0.10	0.2	0.08	5.8	0.2	<0.05	5	0.6
L9000 11975N	Soil	0.064	15	31	0.59	231	0.071	2	1.84	0.020	0.08	0.5	0.03	3.6	0.2	0.06	5	<0.5
L9000 12000N	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9000 12025N	Soil	0.094	20	67	0.94	346	0.119	1	2.36	0.018	0.29	0.2	0.04	7.1	0.4	0.14	8	1.7
L9000 12225N	Soil	0.101	18	47	0.62	327	0.072	<1	1.86	0.014	0.15	0.3	0.07	3.8	0.2	0.15	6	1.0
L9000 12250N	Soil	0.093	17	60	0.67	226	0.071	<1	1.89	0.014	0.17	0.3	0.05	4.6	0.2	0.13	7	1.1
L9000 12275N	Soil	0.071	17	37	0.63	176	0.058	1	1.67	0.012	0.09	0.3	0.03	3.7	0.1	<0.05	5	0.6
L9000 12300N	Soil	0.114	18	44	0.58	226	0.052	<1	1.85	0.015	0.09	0.4	0.06	4.6	0.2	0.10	6	1.4
L9000 12325N	Soil	0.097	7	32	0.20	115	0.043	<1	0.91	0.026	0.05	0.4	0.06	1.5	<0.1	0.11	4	<0.5
L9000 12350N	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9000 12375N	Soil	0.096	17	37	0.58	193	0.053	1	1.84	0.011	0.11	0.9	0.09	3.8	0.3	0.06	6	1.6
L9000 12400N	Soil	0.097	18	39	0.57	169	0.059	2	1.93	0.014	0.11	0.6	0.13	4.5	0.3	0.06	6	1.9
L9000 12425N	Soil	0.086	19	37	0.61	222	0.090	<1	1.75	0.019	0.11	1.2	0.06	4.0	0.2	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000103.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L9000 12450N	Soil		3.4	20.3	45.1	127	0.1	14.9	8.1	552	2.69	146.9	1.7	4.7	5.6	19	0.3	6.9	0.5	68	0.15
L9200 11700N	Soil		0.8	21.0	69.4	131	0.4	19.5	10.6	623	3.51	152.2	4.9	3.6	13.8	28	0.5	3.0	0.2	77	0.39
L9200 11725N	Soil		1.3	25.4	147.8	228	0.9	16.2	12.1	1196	3.85	532.8	7.5	5.3	17.7	32	1.2	5.9	0.3	73	0.40
L9200 11750N	Soil		0.4	19.9	21.8	86	0.1	17.0	8.0	364	2.65	46.2	4.4	3.1	9.7	37	0.2	1.6	0.4	63	0.41
L9200 11775N	Soil		0.8	19.2	31.0	117	0.2	20.1	9.5	544	2.97	77.8	1.8	3.3	5.7	25	0.4	5.9	0.5	65	0.22
L9200 11800N	Soil		1.2	23.5	22.1	78	0.3	20.4	8.0	376	3.04	49.0	2.7	4.1	5.4	20	0.2	3.3	0.2	71	0.25
L9200 11825N	Soil		0.7	22.5	9.1	61	<0.1	19.1	9.4	362	2.71	14.5	1.7	3.0	5.2	35	0.3	0.8	0.2	65	0.36
L9200 11850N	Soil		0.7	21.4	11.3	70	<0.1	18.5	9.4	522	2.80	19.1	1.5	3.0	4.7	30	0.2	1.1	0.2	66	0.37
L9200 11875N	Soil		0.7	30.6	12.4	83	<0.1	25.2	13.4	692	3.21	20.8	2.6	4.2	6.3	53	0.4	1.0	0.2	82	0.49
L9200 11900N	Soil		1.1	24.1	128.7	262	1.2	19.2	10.7	911	3.06	286.0	2.2	6.2	6.1	38	1.5	11.0	0.8	71	0.46
L9200 11925N	Soil		1.1	31.0	31.5	134	0.3	24.1	12.4	807	3.21	87.7	3.5	4.5	5.6	37	0.7	3.9	0.4	75	0.42
L9200 11950N	Soil		2.6	32.9	40.9	116	0.4	18.1	13.5	1073	3.78	208.5	4.8	12.4	9.7	39	0.5	5.1	1.7	77	0.37
L9200 11975N	Soil		2.3	49.2	21.5	106	0.3	39.8	14.2	641	3.45	91.9	2.1	7.1	4.2	24	0.3	3.7	0.2	74	0.27
L9200 12000N	Soil		1.4	34.9	21.0	101	0.2	33.1	15.2	837	3.37	74.2	1.2	4.6	1.9	27	0.5	4.4	0.2	72	0.27
L9200 12050N	Soil		2.3	45.9	223.9	355	1.6	47.8	16.4	932	4.39	419.4	2.3	13.9	4.7	28	1.8	41.3	0.2	86	0.22
L9200 12075N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9200 12100N	Soil		3.1	57.4	230.2	263	2.3	43.2	13.8	826	4.63	658.5	2.4	14.4	4.8	42	1.2	34.6	0.3	109	0.20
L9200 12125N	Soil		3.2	56.7	309.3	272	4.3	39.2	12.2	853	3.79	675.0	3.8	13.7	4.4	44	1.7	35.7	0.2	85	0.44
L9200 12150N	Soil		2.5	45.0	62.7	242	1.4	34.2	12.8	973	3.83	255.5	5.4	8.0	5.0	42	1.2	9.6	0.2	94	0.50
L9200 12175N	Soil		1.2	25.2	9.5	62	0.1	16.8	7.8	444	2.29	13.9	1.5	1.6	1.1	28	0.5	0.9	0.2	50	0.33
L9200 12200N	Soil		1.4	27.6	36.9	158	0.6	32.1	11.3	647	2.77	108.2	4.0	6.5	8.8	36	0.7	4.9	0.2	73	0.44
L9200 12225N	Soil		1.2	26.5	38.4	150	0.3	27.8	14.6	590	3.28	56.6	5.1	3.1	12.1	30	0.8	3.3	0.3	84	0.36
L9200 12250N	Soil		1.4	21.0	30.4	115	0.3	24.4	11.3	1183	3.15	55.8	3.0	2.2	3.5	28	0.8	2.6	0.3	78	0.28
L9200 12275N	Soil		1.4	24.9	24.8	140	0.4	26.0	11.8	1639	2.99	63.7	3.5	10.7	5.9	38	1.4	4.5	0.3	68	0.55
L9200 12300N	Soil		1.5	20.8	9.8	56	0.1	14.4	6.1	416	1.91	13.3	1.4	2.1	1.1	23	0.7	1.2	0.2	43	0.25
L9200 12325N	Soil		2.1	25.7	94.5	272	2.0	26.7	8.6	283	2.40	65.3	2.5	16.5	6.5	31	0.9	13.2	0.4	63	0.43
L9200 12350N	Soil		2.4	30.8	320.3	246	6.3	21.5	7.8	419	2.69	312.5	3.5	14.9	6.7	32	1.2	20.0	0.5	70	0.41
L9200 12375N	Soil		3.3	35.5	111.3	240	1.5	26.9	9.3	309	2.85	160.8	3.5	16.8	8.5	24	1.5	18.5	0.4	81	0.34
L9200 12400N	Soil		2.0	36.7	46.8	328	0.6	46.4	12.4	798	3.27	728.1	3.2	56.5	8.8	24	1.9	9.3	1.7	74	0.33
L9200 12425N	Soil		2.8	35.6	132.6	299	1.6	36.0	15.9	1095	3.41	568.7	3.4	*	6.8	29	1.4	15.5	1.1	75	0.35

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000103.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L9000 12450N	Soil	0.049	14	28	0.42	85	0.107	1	1.26	0.014	0.11	0.6	0.04	2.9	0.3	<0.05	8	<0.5
L9200 11700N	Soil	0.075	24	34	0.59	209	0.094	1	1.87	0.018	0.10	0.1	0.04	5.8	0.4	<0.05	6	<0.5
L9200 11725N	Soil	0.086	30	28	0.62	286	0.099	1	1.97	0.018	0.18	0.4	0.07	8.2	0.5	<0.05	7	<0.5
L9200 11750N	Soil	0.088	21	30	0.60	263	0.102	2	1.90	0.022	0.09	0.6	0.03	5.6	0.2	<0.05	5	0.5
L9200 11775N	Soil	0.064	10	30	0.58	153	0.070	3	2.27	0.013	0.08	0.7	0.05	3.6	0.1	<0.05	6	<0.5
L9200 11800N	Soil	0.062	20	31	0.57	135	0.107	2	2.25	0.014	0.09	0.3	0.04	4.9	0.2	<0.05	7	<0.5
L9200 11825N	Soil	0.101	15	31	0.63	182	0.129	2	2.04	0.019	0.12	0.5	0.04	4.2	0.2	<0.05	6	<0.5
L9200 11850N	Soil	0.085	14	34	0.61	205	0.129	3	1.94	0.020	0.10	0.4	0.03	4.6	0.1	<0.05	5	<0.5
L9200 11875N	Soil	0.104	18	40	0.78	307	0.172	3	2.10	0.032	0.16	1.2	0.03	5.7	0.2	<0.05	6	0.6
L9200 11900N	Soil	0.100	17	30	0.64	201	0.111	3	1.93	0.021	0.12	0.8	0.05	4.8	0.2	<0.05	5	<0.5
L9200 11925N	Soil	0.110	21	32	0.70	217	0.118	2	1.95	0.026	0.11	0.3	0.04	5.1	0.2	<0.05	6	0.6
L9200 11950N	Soil	0.084	27	27	0.69	294	0.098	3	2.09	0.019	0.12	0.5	0.04	6.1	0.3	<0.05	6	<0.5
L9200 11975N	Soil	0.064	15	43	0.82	151	0.135	4	2.26	0.019	0.12	0.3	0.04	4.7	0.2	<0.05	7	0.8
L9200 12000N	Soil	0.069	11	38	0.69	156	0.096	4	2.02	0.024	0.12	0.4	0.05	3.5	0.2	0.07	6	0.7
L9200 12050N	Soil	0.059	12	45	0.69	168	0.098	2	2.06	0.019	0.16	0.5	0.04	4.6	0.2	0.07	7	0.6
L9200 12075N	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9200 12100N	Soil	0.086	14	64	0.83	248	0.119	2	2.42	0.037	0.33	0.5	0.05	5.8	0.4	0.27	8	1.7
L9200 12125N	Soil	0.102	17	49	0.70	233	0.095	3	1.97	0.030	0.17	0.4	0.05	5.2	0.3	0.16	6	1.8
L9200 12150N	Soil	0.104	24	45	0.74	325	0.082	3	2.31	0.026	0.14	0.3	0.07	5.9	0.3	0.10	7	1.2
L9200 12175N	Soil	0.094	12	23	0.43	125	0.056	3	1.22	0.037	0.06	0.1	0.15	2.3	0.1	0.10	4	0.7
L9200 12200N	Soil	0.093	21	48	0.78	236	0.116	3	2.02	0.023	0.10	0.2	0.03	5.1	0.2	<0.05	6	<0.5
L9200 12225N	Soil	0.086	25	44	0.87	264	0.119	<1	2.37	0.019	0.10	0.2	0.04	7.1	0.3	<0.05	7	0.5
L9200 12250N	Soil	0.092	18	42	0.69	344	0.069	2	2.26	0.017	0.07	0.1	0.05	4.3	0.3	<0.05	7	<0.5
L9200 12275N	Soil	0.104	19	37	0.71	328	0.082	4	1.85	0.021	0.07	0.2	0.07	4.9	0.2	0.06	6	0.8
L9200 12300N	Soil	0.082	9	23	0.34	102	0.053	2	1.23	0.035	0.05	0.2	0.09	2.1	0.1	0.08	4	1.0
L9200 12325N	Soil	0.079	16	37	0.70	253	0.106	2	2.08	0.016	0.10	0.2	0.10	4.8	0.3	<0.05	6	0.7
L9200 12350N	Soil	0.082	19	36	0.70	238	0.098	2	2.12	0.017	0.11	0.3	0.08	5.2	0.3	<0.05	6	0.8
L9200 12375N	Soil	0.074	20	42	0.71	237	0.104	2	2.12	0.016	0.13	0.3	0.05	5.0	0.3	<0.05	6	1.5
L9200 12400N	Soil	0.091	18	77	0.87	189	0.143	2	1.91	0.021	0.18	0.9	0.04	4.7	0.3	<0.05	6	1.3
L9200 12425N	Soil	0.093	17	48	0.73	236	0.105	2	2.14	0.016	0.15	0.8	0.05	5.1	0.3	<0.05	6	1.0

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000103.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L9200 12450N	Soil		2.6	33.4	76.0	188	1.2	23.8	9.9	1058	2.81	208.0	2.8	12.0	0.8	30	2.5	8.9	0.8	61	0.29
L9200 12475N	Soil		3.3	40.3	58.4	206	1.1	26.3	12.5	935	3.15	234.3	4.9	13.9	2.3	40	2.6	11.5	1.1	63	0.40
L9200 12500N	Soil		3.6	32.3	51.1	263	0.7	25.6	9.4	767	3.25	304.8	4.5	13.5	8.4	26	1.0	15.8	0.9	58	0.29
L9200 12525N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9200 12550N	Soil		3.8	18.1	218.7	191	1.4	16.8	5.4	618	3.07	506.9	4.1	63.2	12.6	24	1.2	37.4	0.6	46	0.30
L9200 12575N	Soil		3.8	21.0	150.3	259	1.7	18.5	6.4	899	2.85	385.6	4.8	17.0	14.2	25	0.8	30.5	0.7	44	0.28
L9200 12600N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9200 12625N	Soil		3.8	41.0	153.4	315	4.3	28.5	10.3	946	3.88	1076	7.3	47.7	3.9	32	1.3	31.8	1.5	71	0.33
L9200 12650N	Soil		2.0	23.9	69.9	189	1.5	23.4	8.5	645	2.68	316.6	2.6	23.9	5.8	26	1.1	18.8	0.4	64	0.36
L9200 12675N	Soil		5.6	22.9	18.8	65	1.0	12.6	4.8	380	2.11	57.9	1.7	11.8	0.7	13	0.4	3.5	7.4	56	0.10
L9200 12700N	Soil		2.2	29.4	59.5	169	0.9	23.4	9.8	787	3.00	237.9	4.2	7.6	3.1	31	0.6	13.7	0.5	68	0.39

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000103.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L9200 12450N	Soil	0.123	15	38	0.46	240	0.066	2	1.86	0.024	0.07	0.5	0.06	3.1	0.3	0.09	7	1.0
L9200 12475N	Soil	0.104	30	35	0.53	367	0.071	4	1.98	0.022	0.09	0.7	0.05	3.7	0.3	0.07	7	0.8
L9200 12500N	Soil	0.060	24	34	0.50	224	0.075	2	1.74	0.015	0.13	0.8	0.04	4.2	0.2	<0.05	6	0.6
L9200 12525N	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9200 12550N	Soil	0.078	30	27	0.49	184	0.066	1	1.79	0.014	0.17	0.4	0.04	4.7	0.4	<0.05	6	0.9
L9200 12575N	Soil	0.071	32	29	0.53	188	0.075	<1	2.05	0.012	0.19	0.4	0.05	4.8	0.5	<0.05	6	0.7
L9200 12600N	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L9200 12625N	Soil	0.107	25	42	0.63	202	0.053	2	2.34	0.013	0.11	0.4	0.10	4.5	0.3	0.08	7	1.1
L9200 12650N	Soil	0.070	16	36	0.55	126	0.096	2	1.57	0.017	0.10	0.5	0.07	3.6	0.2	<0.05	5	0.9
L9200 12675N	Soil	0.090	7	24	0.21	64	0.051	3	1.17	0.014	0.05	0.3	0.18	1.6	0.1	0.15	5	0.8
L9200 12700N	Soil	0.064	14	40	0.58	163	0.078	3	1.62	0.013	0.08	0.5	0.07	3.3	0.1	0.13	6	0.9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

QUALITY CONTROL REPORT SMI09000103.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
RDCX 07	Soil		0.5	30.9	14.2	52	<0.1	24.8	9.4	234	2.89	18.2	1.8	3.3	8.8	25	0.1	1.1	0.2	68	0.31
REP RDCX 07	QC		0.5	28.6	14.1	51	<0.1	23.5	9.6	225	2.71	17.7	1.7	3.3	8.5	24	0.1	1.0	0.2	65	0.30
L9200 11700N	Soil		0.8	21.0	69.4	131	0.4	19.5	10.6	623	3.51	152.2	4.9	3.6	13.8	28	0.5	3.0	0.2	77	0.39
REP L9200 11700N	QC		0.9	19.7	73.1	137	0.4	18.9	10.8	634	3.34	153.6	5.0	4.0	14.1	28	0.5	3.0	0.2	77	0.39
L9200 11950N	Soil		2.6	32.9	40.9	116	0.4	18.1	13.5	1073	3.78	208.5	4.8	12.4	9.7	39	0.5	5.1	1.7	77	0.37
REP L9200 11950N	QC		2.6	33.0	39.1	116	0.4	18.0	13.6	1066	3.72	203.6	4.9	22.1	9.9	40	0.5	4.9	1.9	80	0.38
L9200 12575N	Soil		3.8	21.0	150.3	259	1.7	18.5	6.4	899	2.85	385.6	4.8	17.0	14.2	25	0.8	30.5	0.7	44	0.28
REP L9200 12575N	QC		3.5	21.3	145.5	258	1.7	18.7	6.4	909	2.79	382.4	4.9	19.8	14.2	25	0.8	30.8	0.7	41	0.27
Reference Materials																					
STD DS7	Standard		19.8	112.0	62.5	403	0.9	55.8	9.3	634	2.44	53.7	4.7	62.3	4.4	85	6.9	6.2	4.5	85	1.00
STD DS7	Standard		21.2	115.2	63.7	406	0.8	57.7	9.7	663	2.50	53.6	4.7	63.5	4.2	82	6.4	6.2	4.4	87	0.99
STD DS7	Standard		22.0	120.6	76.4	403	0.8	60.5	10.3	646	2.53	49.7	5.8	73.5	5.2	87	6.5	6.5	5.4	87	1.03
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

QUALITY CONTROL REPORT SMI09000103.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
RDCX 07	Soil	0.042	19	41	0.61	162	0.125	2	2.46	0.017	0.06	0.2	0.03	5.7	0.1	<0.05	6	<0.5
REP RDCX 07	QC	0.045	18	43	0.59	158	0.115	<1	2.33	0.016	0.06	0.3	0.03	5.4	0.1	<0.05	6	<0.5
L9200 11700N	Soil	0.075	24	34	0.59	209	0.094	1	1.87	0.018	0.10	0.1	0.04	5.8	0.4	<0.05	6	<0.5
REP L9200 11700N	QC	0.076	24	34	0.62	207	0.086	<1	1.93	0.018	0.10	0.1	0.04	5.7	0.4	<0.05	6	<0.5
L9200 11950N	Soil	0.084	27	27	0.69	294	0.098	3	2.09	0.019	0.12	0.5	0.04	6.1	0.3	<0.05	6	<0.5
REP L9200 11950N	QC	0.079	27	27	0.68	296	0.103	2	2.05	0.019	0.12	0.4	0.04	6.5	0.3	<0.05	6	<0.5
L9200 12575N	Soil	0.071	32	29	0.53	188	0.075	<1	2.05	0.012	0.19	0.4	0.05	4.8	0.5	<0.05	6	0.7
REP L9200 12575N	QC	0.069	32	28	0.53	188	0.073	2	2.02	0.011	0.19	0.3	0.04	4.8	0.5	<0.05	7	0.8
Reference Materials																		
STD DS7	Standard	0.079	15	212	1.04	427	0.139	39	1.10	0.103	0.47	3.9	0.19	3.1	4.2	0.19	5	3.8
STD DS7	Standard	0.083	14	219	1.03	429	0.143	41	1.05	0.103	0.46	3.9	0.19	2.9	4.2	0.22	5	3.5
STD DS7	Standard	0.078	15	216	1.02	401	0.140	40	1.03	0.103	0.46	4.0	0.19	2.9	4.3	0.24	5	3.0
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 06, 2009
Report Date: August 14, 2009
Page: 1 of 5

CERTIFICATE OF ANALYSIS SMI09000112.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 111

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	111	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	111	Dry at 60C			SMI
1DX15	111	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000112.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L8800 11800N	Soil		2.6	23.0	21.1	88	<0.1	21.8	9.4	428	3.58	15.4	0.9	2.1	1.3	19	0.2	0.7	0.4	80	0.16
L8800 11825N	Soil		4.0	23.9	22.7	85	<0.1	21.6	9.3	386	3.05	15.9	0.8	2.1	1.4	16	0.3	0.7	0.5	72	0.18
L8800 11850N	Soil		5.2	35.0	68.3	176	0.1	28.1	12.5	453	3.03	35.8	1.1	5.1	2.7	31	1.2	0.9	0.6	67	0.26
L8800 11875N	Soil		3.1	22.6	13.6	67	0.3	14.5	4.4	153	1.73	42.9	0.8	2.6	0.3	22	0.5	0.7	0.6	45	0.22
L8800 11900N	Soil		2.9	38.9	46.2	184	0.2	30.3	11.1	523	3.63	105.6	1.2	4.4	2.0	20	0.7	1.5	0.9	66	0.18
L8800 11925N	Soil		2.3	102.6	33.8	139	0.2	76.0	24.0	486	3.54	131.7	2.7	8.2	0.4	15	0.7	2.0	0.3	64	0.22
L8800 11950N	Soil		4.8	69.5	80.1	149	0.2	33.7	15.8	661	3.39	180.5	1.9	4.8	2.3	19	0.6	4.3	0.8	75	0.24
L8800 11975N	Soil		6.6	87.3	91.1	227	0.7	49.5	11.9	572	3.77	1332	4.8	11.1	2.0	35	1.1	6.6	1.0	80	0.21
L8800 12000N	Soil		3.3	46.7	61.3	167	0.2	33.4	14.5	839	3.79	123.1	1.7	2.6	1.9	20	0.8	2.4	0.5	80	0.14
L8800 12025N	Soil		3.1	58.3	80.4	192	0.2	36.5	19.0	1738	3.71	280.7	2.8	4.0	6.7	32	0.8	6.3	0.9	61	0.23
L8800 12050N	Soil		2.5	64.1	72.1	200	0.5	46.7	16.3	789	3.90	350.7	2.8	8.9	1.8	23	0.7	5.8	0.7	69	0.17
L8800 12075N	Soil		3.4	59.5	56.4	184	0.4	48.2	16.4	772	4.16	291.5	2.7	5.4	4.3	20	0.5	6.5	0.6	66	0.14
L8800 12100N	Soil		1.8	37.9	19.1	116	0.1	34.8	10.7	504	3.09	55.1	1.6	4.9	3.9	23	0.7	1.8	0.3	70	0.33
L8800 12125N	Soil		13.5	87.1	29.5	574	0.5	124.7	15.2	922	3.69	153.5	6.1	4.7	1.2	27	3.2	7.3	0.4	133	0.36
L8800 12150N	Soil		1.9	37.6	10.4	107	0.1	28.4	11.8	589	2.99	26.1	2.2	1.9	2.1	26	0.6	1.1	0.3	70	0.40
L8800 12175N	Soil		118.1	135.2	23.9	680	0.6	131.5	20.0	853	4.54	99.8	3.5	7.7	3.6	34	4.2	5.8	0.5	110	0.27
L8800 12200N	Soil		6.0	36.3	13.2	95	<0.1	28.7	10.8	551	3.74	27.6	1.2	4.0	1.1	22	0.3	1.4	0.2	92	0.17
L8800 12225N	Soil		2.7	32.4	14.3	89	<0.1	29.1	12.7	585	3.88	16.1	1.2	3.4	1.3	19	0.3	1.1	0.2	97	0.18
L8800 12250N	Soil		6.7	105.8	120.2	398	0.4	106.7	27.1	1320	5.62	293.8	6.3	16.2	4.4	38	2.7	19.5	0.5	88	0.24
L8800 12275N	Soil		8.3	59.0	70.2	382	0.5	62.5	14.3	652	3.78	143.0	1.9	5.6	1.5	26	1.9	7.0	0.3	95	0.24
L8800 12300N	Soil		5.9	52.8	45.9	242	0.5	39.8	12.1	683	3.07	84.2	2.7	2.9	2.9	38	1.5	3.3	2.5	73	0.48
L8800 12325N	Soil		12.6	67.4	42.2	370	0.2	76.9	15.2	611	3.42	190.0	4.0	19.1	3.0	23	2.2	8.6	1.9	76	0.20
L8800 12350N	Soil		6.7	45.6	30.8	208	0.3	42.0	12.1	484	3.20	99.3	2.1	8.2	2.4	24	0.9	3.2	1.6	85	0.24
L8800 12375N	Soil		6.5	67.5	611.7	406	11.4	34.8	14.3	1215	5.09	3634	3.5	33.3	4.6	42	2.3	96.6	2.3	67	0.27
L8800 12400N	Soil		3.6	46.9	154.2	320	1.4	43.9	14.0	855	3.88	622.2	2.1	18.4	5.1	26	1.1	17.7	0.6	78	0.18
L8800 12425N	Soil		6.9	43.5	278.5	345	1.2	40.5	13.9	1454	3.17	909.4	2.6	21.6	3.8	27	2.3	15.6	0.8	50	0.37
L8800 12450N	Soil		5.9	98.9	84.3	216	1.2	61.6	17.7	1159	4.29	541.7	4.6	50.3	4.5	26	1.0	18.3	1.9	75	0.32
L8800 12475N	Soil		4.4	57.0	229.0	214	3.9	38.3	14.0	915	3.53	318.9	3.7	31.7	5.6	32	0.7	12.0	1.1	74	0.34
L8800 12500N	Soil		6.6	58.4	64.4	146	1.0	31.9	14.4	1045	3.40	330.2	5.5	25.2	2.4	36	0.5	9.0	1.1	68	0.42
L8800 12525N	Soil		4.5	50.5	80.4	174	0.5	34.4	12.3	708	3.32	221.1	3.4	51.9	4.8	27	0.6	9.5	1.1	77	0.28

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000112.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L8800 11800N	Soil	0.049	9	38	0.54	101	0.078	1	2.21	0.009	0.06	0.1	0.04	2.3	0.1	0.06	7	<0.5
L8800 11825N	Soil	0.052	8	34	0.56	109	0.069	2	1.96	0.010	0.05	0.1	0.04	2.7	<0.1	0.05	6	<0.5
L8800 11850N	Soil	0.052	10	37	0.69	378	0.070	1	2.18	0.014	0.04	0.2	0.03	3.2	0.1	<0.05	6	0.5
L8800 11875N	Soil	0.081	7	26	0.24	198	0.032	1	1.05	0.013	0.03	0.1	0.05	1.2	<0.1	0.12	4	0.7
L8800 11900N	Soil	0.060	12	35	0.51	103	0.058	3	1.88	0.011	0.07	0.2	0.06	2.5	0.1	0.06	6	<0.5
L8800 11925N	Soil	0.184	10	41	0.52	78	0.030	2	2.60	0.009	0.06	0.2	0.10	1.1	0.1	0.14	5	2.0
L8800 11950N	Soil	0.066	11	35	0.60	103	0.063	3	1.69	0.013	0.06	0.3	0.04	2.8	<0.1	<0.05	6	1.0
L8800 11975N	Soil	0.104	17	41	0.49	199	0.045	3	1.77	0.016	0.14	0.2	0.08	2.7	0.3	0.18	5	2.2
L8800 12000N	Soil	0.071	14	40	0.48	130	0.064	2	1.69	0.011	0.10	0.1	0.05	2.6	0.1	0.10	6	0.9
L8800 12025N	Soil	0.063	18	32	0.62	290	0.038	1	1.92	0.010	0.09	0.2	0.04	3.2	0.2	0.06	5	0.8
L8800 12050N	Soil	0.075	15	39	0.53	145	0.039	2	1.82	0.012	0.08	0.2	0.06	2.5	0.2	0.07	6	1.2
L8800 12075N	Soil	0.055	16	41	0.59	107	0.047	1	1.78	0.010	0.10	0.2	0.06	2.9	0.2	0.06	6	0.9
L8800 12100N	Soil	0.077	12	35	0.56	132	0.098	2	1.51	0.018	0.07	0.2	0.04	3.0	0.1	<0.05	4	0.9
L8800 12125N	Soil	0.162	15	43	0.55	269	0.046	3	1.66	0.011	0.08	0.6	0.08	2.8	0.1	0.10	5	2.9
L8800 12150N	Soil	0.116	12	30	0.55	180	0.081	1	1.65	0.021	0.07	0.2	0.06	2.9	0.1	0.07	5	0.6
L8800 12175N	Soil	0.111	14	57	0.74	186	0.089	2	1.97	0.014	0.12	2.8	0.05	4.2	0.2	0.10	6	4.1
L8800 12200N	Soil	0.063	10	43	0.55	127	0.088	3	1.88	0.015	0.09	0.5	0.09	2.9	0.1	0.07	8	0.8
L8800 12225N	Soil	0.065	10	47	0.52	106	0.100	2	1.71	0.011	0.08	0.2	0.08	2.9	0.1	0.08	8	<0.5
L8800 12250N	Soil	0.115	19	42	0.66	193	0.057	2	1.97	0.020	0.15	0.2	0.06	5.5	0.3	0.11	6	2.0
L8800 12275N	Soil	0.088	12	46	0.52	160	0.076	2	1.53	0.016	0.09	0.4	0.10	2.9	0.2	0.12	5	2.7
L8800 12300N	Soil	0.128	15	34	0.52	333	0.049	2	1.72	0.022	0.11	8.1	0.07	2.8	0.2	0.10	5	1.7
L8800 12325N	Soil	0.075	12	34	0.57	175	0.034	2	1.69	0.011	0.10	14.4	0.04	2.8	0.2	0.10	5	2.9
L8800 12350N	Soil	0.067	10	36	0.58	159	0.070	2	1.48	0.012	0.10	9.2	0.04	2.6	0.1	0.08	6	1.2
L8800 12375N	Soil	0.063	12	35	0.53	286	0.032	2	1.43	0.022	0.35	0.5	0.06	4.0	0.4	0.61	5	1.2
L8800 12400N	Soil	0.055	10	38	0.59	209	0.044	3	1.91	0.012	0.15	0.9	0.04	3.6	0.3	0.17	5	0.7
L8800 12425N	Soil	0.077	20	29	0.45	202	0.020	2	1.62	0.011	0.09	1.1	0.07	2.7	0.2	0.09	5	1.0
L8800 12450N	Soil	0.088	16	40	0.67	195	0.041	2	1.97	0.014	0.10	0.9	0.08	4.1	0.2	0.06	6	1.3
L8800 12475N	Soil	0.065	16	36	0.68	214	0.064	1	1.83	0.015	0.11	1.1	0.05	4.2	0.2	<0.05	6	0.7
L8800 12500N	Soil	0.099	21	35	0.54	214	0.033	2	1.87	0.013	0.09	1.1	0.09	3.4	0.2	0.08	5	1.0
L8800 12525N	Soil	0.075	16	41	0.67	181	0.067	1	1.77	0.013	0.11	2.1	0.04	3.6	0.2	<0.05	6	0.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000112.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L8800 12550N	Soil		4.5	45.1	119.8	219	0.9	28.8	13.1	893	3.56	350.7	5.4	22.7	5.6	30	0.6	7.7	1.9	64	0.34
L8800 12575N	Soil		2.0	31.1	33.5	105	0.1	25.5	10.6	510	2.74	183.8	2.3	25.3	4.7	21	0.4	4.3	0.6	60	0.31
L8800 12600N	Soil		2.3	32.6	32.7	108	0.1	32.0	11.6	507	3.00	104.1	2.1	7.9	4.2	23	0.4	4.0	0.5	71	0.29
L8800 12625N	Soil		2.8	25.6	35.8	92	0.5	17.0	7.7	375	2.48	125.4	3.1	11.7	1.1	23	0.2	3.0	1.0	51	0.25
L8800 12650N	Soil		3.7	42.1	50.2	138	0.6	29.4	12.9	667	3.13	171.2	9.4	22.6	6.0	23	0.5	5.2	0.9	65	0.28
L8800 12675N	Soil		6.9	33.2	40.3	120	0.8	25.0	13.2	1219	3.25	169.5	8.0	13.9	1.4	54	0.6	4.1	0.9	66	0.86
L8800 12700N	Soil		10.7	36.5	37.7	96	0.6	22.9	8.8	583	2.02	53.6	5.8	12.1	0.6	33	0.4	3.3	0.4	53	0.52
L9000 12050N	Soil		2.1	26.5	13.5	54	0.6	18.6	4.1	132	1.65	25.9	1.0	3.4	0.2	19	0.4	1.4	0.2	42	0.21
L9000 12075N	Soil		5.5	69.7	67.4	157	1.5	43.1	11.9	857	3.91	408.3	3.9	29.0	2.4	33	0.6	9.3	0.3	81	0.30
L9000 12100N	Soil		4.7	67.5	2038	528	13.6	36.0	11.5	1262	5.03	1841	5.9	13.2	9.8	52	4.0	287.8	0.2	88	0.24
L9000 12125N	Soil		4.7	64.8	126.2	165	2.1	29.9	6.4	366	3.81	433.6	2.8	23.8	1.0	31	0.6	9.7	0.4	95	0.20
L9000 12150N	Soil		2.7	52.0	135.5	255	1.2	36.3	13.0	930	3.67	165.9	2.5	10.3	5.7	30	1.4	9.3	0.3	88	0.28
L9000 12175N	Soil		2.6	47.6	157.0	216	2.0	39.0	12.6	844	3.57	353.5	2.5	17.9	5.0	43	1.0	17.9	0.4	84	0.34
L9000 12200N	Soil		3.4	47.9	107.5	271	1.4	42.0	10.8	845	2.77	240.2	3.7	14.7	2.2	37	1.7	9.8	0.3	59	0.42
L9000 12475N	Soil		2.3	26.0	57.0	169	0.7	27.9	11.4	709	3.05	170.9	2.0	6.9	6.1	20	1.1	4.6	0.4	73	0.27
L9000 12500N	Soil		2.5	27.0	651.5	251	11.1	23.4	9.5	1053	3.23	1582	2.4	17.9	3.8	23	1.7	14.0	0.5	60	0.24
L9000 12525N	Soil		1.7	18.9	61.5	150	0.4	19.6	9.0	538	2.70	146.5	1.0	12.0	3.8	22	0.8	3.8	0.3	71	0.32
L9000 12550N	Soil		3.4	32.2	136.2	388	2.2	23.2	11.8	1169	3.73	471.4	6.7	24.0	6.8	39	1.0	11.3	0.8	61	0.53
L9000 12575N	Soil		2.2	22.0	66.2	330	0.7	20.3	9.4	813	2.71	246.6	2.5	9.4	4.8	28	1.0	7.5	0.5	60	0.40
L9000 12600N	Soil		2.4	24.1	211.8	463	1.7	24.1	11.2	1405	3.48	510.5	3.8	19.9	5.3	23	1.8	35.1	0.4	66	0.28
L9000 12625N	Soil		2.1	33.7	246.3	415	7.2	16.9	8.7	1721	3.39	1123	9.5	40.3	3.7	43	1.2	54.1	0.4	45	0.63
L9000 12650N	Soil		1.6	22.1	45.7	136	0.6	16.8	8.6	970	2.49	214.1	3.3	4.8	1.9	18	0.6	6.8	0.3	49	0.22
L9000 12675N	Soil		1.0	23.5	42.9	144	0.5	28.3	10.4	700	2.89	162.2	3.0	9.3	6.8	26	0.6	6.1	0.3	70	0.41
L9000 12700N	Soil		1.3	24.5	57.8	196	0.8	27.5	10.7	870	2.98	236.7	3.7	6.9	5.6	23	0.7	9.9	0.4	65	0.34
L9000 12725N	Soil		1.7	28.5	151.0	271	2.6	24.7	10.2	1336	3.17	532.2	7.0	26.5	6.7	30	0.9	56.9	0.5	60	0.41
L9000 12750N	Soil		1.7	16.4	69.5	113	1.1	14.7	11.3	1116	2.06	205.2	2.9	6.5	0.8	21	0.5	19.1	0.3	43	0.23
L9000 12775N	Soil		2.0	28.6	53.2	161	1.4	20.9	9.4	758	2.50	261.5	7.2	11.8	1.4	43	1.0	12.7	0.4	54	0.67
L9000 12800N	Soil		2.8	24.2	76.8	194	1.4	22.8	11.6	1331	2.89	281.3	6.7	14.9	3.8	36	1.1	12.3	0.5	55	0.57
L9000 12825N	Soil		2.8	25.5	183.9	374	3.6	21.8	9.4	740	3.04	618.7	4.6	23.3	2.2	31	1.7	23.1	0.5	57	0.43
L9000 12850N	Soil		5.1	25.6	47.4	189	0.9	22.6	14.9	958	2.82	154.6	3.1	10.5	1.5	27	1.9	5.6	0.7	65	0.34

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000112.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L8800 12550N	Soil	0.082	20	33	0.62	160	0.049	2	1.77	0.013	0.10	1.0	0.04	3.7	0.2	<0.05	6	<0.5
L8800 12575N	Soil	0.083	15	29	0.53	116	0.067	3	1.35	0.015	0.09	1.8	0.02	2.7	0.1	<0.05	4	<0.5
L8800 12600N	Soil	0.075	14	35	0.61	130	0.075	2	1.70	0.018	0.08	1.3	0.03	2.9	0.1	<0.05	5	<0.5
L8800 12625N	Soil	0.068	10	22	0.39	103	0.032	1	1.37	0.014	0.07	0.3	0.04	2.0	0.2	0.05	5	<0.5
L8800 12650N	Soil	0.078	25	37	0.65	165	0.050	2	1.94	0.011	0.09	1.0	0.06	4.2	0.2	<0.05	6	1.0
L8800 12675N	Soil	0.116	15	35	0.56	195	0.032	3	1.94	0.013	0.09	0.4	0.06	2.8	0.2	0.11	7	1.2
L8800 12700N	Soil	0.144	16	41	0.52	175	0.023	<1	2.01	0.012	0.05	0.3	0.07	2.1	0.3	0.15	5	1.5
L9000 12050N	Soil	0.082	5	23	0.15	164	0.032	3	0.71	0.018	0.05	0.1	0.04	1.1	0.1	0.11	3	<0.5
L9000 12075N	Soil	0.116	15	37	0.41	263	0.033	1	1.41	0.011	0.13	0.2	0.14	3.6	0.4	0.15	5	2.4
L9000 12100N	Soil	0.100	23	31	0.43	294	0.042	2	1.43	0.015	0.29	0.1	0.19	5.8	1.0	0.36	5	1.8
L9000 12125N	Soil	0.105	11	50	0.43	205	0.046	2	1.56	0.012	0.18	0.2	0.08	2.8	0.3	0.21	6	1.7
L9000 12150N	Soil	0.082	15	40	0.58	246	0.077	1	1.59	0.010	0.18	0.3	0.03	3.8	0.3	0.10	5	1.1
L9000 12175N	Soil	0.094	16	45	0.58	289	0.064	1	1.67	0.011	0.17	0.3	0.04	3.9	0.2	0.11	5	1.3
L9000 12200N	Soil	0.094	17	37	0.35	251	0.033	2	1.44	0.013	0.14	2.1	0.06	2.4	0.2	0.16	5	1.2
L9000 12475N	Soil	0.061	15	35	0.59	124	0.112	2	1.87	0.014	0.10	1.0	0.05	3.5	0.2	<0.05	6	<0.5
L9000 12500N	Soil	0.071	13	32	0.48	157	0.057	1	1.66	0.012	0.09	0.6	0.10	2.8	0.2	0.09	6	0.6
L9000 12525N	Soil	0.059	11	31	0.48	107	0.104	<1	1.29	0.014	0.08	0.9	0.05	2.6	0.1	<0.05	5	<0.5
L9000 12550N	Soil	0.072	28	35	0.60	219	0.056	2	2.12	0.012	0.12	0.4	0.08	4.9	0.3	<0.05	7	<0.5
L9000 12575N	Soil	0.054	20	29	0.50	152	0.078	2	1.47	0.013	0.09	1.1	0.05	3.1	0.2	<0.05	5	<0.5
L9000 12600N	Soil	0.069	23	33	0.53	146	0.063	2	1.72	0.011	0.10	0.6	0.07	3.4	0.2	<0.05	6	<0.5
L9000 12625N	Soil	0.101	37	26	0.37	143	0.026	2	1.50	0.012	0.09	0.5	0.17	3.5	0.2	0.09	5	0.9
L9000 12650N	Soil	0.091	14	28	0.32	89	0.042	<1	1.21	0.014	0.09	0.4	0.13	2.0	0.2	0.09	5	0.7
L9000 12675N	Soil	0.083	19	33	0.59	179	0.099	2	1.57	0.026	0.10	0.6	0.03	3.6	0.1	<0.05	5	<0.5
L9000 12700N	Soil	0.076	19	35	0.57	147	0.086	2	1.75	0.016	0.10	0.9	0.06	3.8	0.2	<0.05	5	<0.5
L9000 12725N	Soil	0.079	22	34	0.49	154	0.053	2	1.68	0.013	0.11	0.7	0.07	3.6	0.2	<0.05	5	<0.5
L9000 12750N	Soil	0.087	13	26	0.20	99	0.028	1	0.96	0.014	0.05	0.2	0.06	1.5	0.2	0.09	4	<0.5
L9000 12775N	Soil	0.103	23	31	0.43	164	0.035	1	1.47	0.016	0.06	0.2	0.07	2.4	0.2	0.11	5	0.8
L9000 12800N	Soil	0.096	21	37	0.58	180	0.043	2	1.94	0.014	0.08	0.3	0.07	3.5	0.2	0.08	6	0.7
L9000 12825N	Soil	0.093	16	38	0.56	157	0.037	2	1.96	0.010	0.07	0.3	0.06	3.0	0.2	0.06	6	0.7
L9000 12850N	Soil	0.122	12	43	0.53	166	0.045	1	1.88	0.009	0.06	0.3	0.05	2.8	0.2	0.08	6	1.0

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000112.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L9000 12875N	Soil		5.9	21.1	34.0	110	0.6	20.8	8.1	262	3.01	211.9	4.1	7.0	4.0	36	0.5	3.2	1.0	81	0.44
L9000 12900N	Soil		2.8	27.6	19.6	120	0.4	21.6	9.5	510	2.66	98.6	3.0	79.2	2.4	41	0.6	1.6	1.0	61	0.48
L9000 12925N	Soil		1.2	15.1	28.1	173	0.5	18.1	7.7	395	2.37	89.7	3.2	9.2	2.1	33	0.7	1.0	0.6	50	0.38
L9000 12950N	Soil		1.3	21.8	45.7	140	0.5	19.1	9.9	335	2.45	94.5	3.3	6.0	5.4	32	0.7	1.8	0.5	57	0.39
L9000 12975N	Soil		1.2	24.5	44.5	142	0.4	24.7	10.3	669	2.84	48.5	1.9	4.7	5.5	34	0.8	2.7	0.3	71	0.41
L9000 13000N	Soil		1.6	18.7	33.0	108	0.4	18.3	9.5	583	2.51	31.6	2.3	3.1	1.4	34	0.5	1.9	0.2	64	0.40
L9000 13025N	Soil		1.3	15.6	40.8	97	0.3	16.9	8.7	735	2.70	32.7	1.8	4.3	1.9	21	0.5	2.3	0.2	65	0.27
L9000 13050N	Soil		1.8	19.1	29.6	103	0.2	19.6	10.0	707	2.98	31.6	3.0	3.0	1.4	28	0.7	1.7	0.3	71	0.32
L9000 13075N	Soil		2.1	17.1	22.2	98	0.2	18.4	8.9	761	2.42	30.7	4.0	10.9	0.9	33	0.7	1.7	0.3	53	0.42
L9000 13100N	Soil		1.8	15.9	26.4	91	0.2	16.6	10.2	880	2.69	30.9	2.2	4.1	0.9	25	0.6	1.7	0.3	62	0.30
L9000 13125N	Soil		2.3	17.9	26.3	144	0.4	21.2	8.1	581	2.81	46.0	3.6	2.4	1.2	35	1.2	2.3	0.3	61	0.43
L9000 13150N	Soil		2.1	20.0	30.4	155	0.3	25.4	11.0	809	3.03	52.3	5.3	5.3	2.3	35	0.6	2.2	0.3	68	0.38
L9000 13175N	Soil		1.3	22.3	29.2	125	0.3	23.8	10.9	676	2.90	29.8	5.3	10.0	4.1	20	0.8	1.9	0.3	73	0.24
L9000 13200N	Soil		0.9	11.8	26.3	103	<0.1	16.1	9.6	410	2.77	31.8	1.5	7.1	3.7	18	0.5	1.3	0.2	65	0.24
L9000 13225N	Soil		1.2	21.3	26.0	93	0.1	25.8	11.3	280	2.33	30.7	2.8	14.3	7.6	24	0.5	1.9	0.3	67	0.33
L9000 13250N	Soil		1.3	21.9	23.3	83	0.3	21.6	11.7	1540	2.70	25.5	5.0	6.3	2.3	40	0.6	1.1	0.3	56	0.52
L9000 13275N	Soil		0.9	12.8	15.6	73	<0.1	17.5	7.0	330	2.09	13.3	1.2	5.6	3.7	19	0.7	0.8	0.2	50	0.26
L9000 13300N	Soil		0.9	19.0	23.6	84	0.1	23.9	10.8	393	2.68	18.4	2.9	3.5	5.3	24	0.3	1.3	0.3	59	0.32
L9200 12725N	Soil		2.2	21.4	39.7	91	0.6	19.7	11.5	1062	2.80	114.2	3.3	4.7	1.4	18	0.6	6.7	0.4	63	0.18
L9200 12750N	Soil		1.9	17.1	37.5	90	0.4	21.1	7.2	415	3.00	119.3	1.8	4.1	3.2	17	0.3	7.6	0.5	72	0.16
L9200 12775N	Soil		1.7	20.8	8.2	34	0.1	16.5	3.5	92	1.64	5.5	1.2	3.7	0.7	14	0.2	0.9	0.2	38	0.12
L9200 12800N	Soil		1.4	34.6	78.1	147	1.1	28.7	11.6	736	3.53	354.0	7.5	16.5	5.5	31	0.6	20.4	0.7	57	0.41
L9200 12825N	Soil		2.8	51.1	96.7	181	2.1	28.8	15.8	1465	2.70	280.6	10.7	17.9	1.8	34	1.0	14.2	0.8	59	0.42
L9200 12850N	Soil		1.5	27.8	55.2	147	0.9	26.9	9.6	461	2.65	142.6	3.8	12.6	5.3	26	0.6	10.5	0.4	61	0.36
L9200 12875N	Soil		1.8	27.7	74.0	226	1.2	29.6	9.7	375	2.77	201.0	4.2	16.8	4.8	24	0.8	17.1	0.5	65	0.31
L9200 12900N	Soil		2.0	27.2	96.9	213	1.9	23.5	11.0	1414	2.62	200.5	6.5	8.4	1.6	43	1.8	24.1	0.5	54	0.52
L9200 12925N	Soil		3.5	22.2	85.0	197	0.9	21.2	12.7	2140	4.80	576.0	6.3	12.5	8.2	28	1.5	13.5	0.4	59	0.35
L9200 12950N	Soil		1.3	18.7	42.1	174	0.6	19.3	8.4	484	2.47	131.4	3.7	7.7	7.5	27	1.0	10.3	0.4	55	0.40
L9200 12975N	Soil		2.2	27.2	55.8	222	1.2	25.4	10.2	531	3.19	258.4	5.0	12.7	3.1	42	1.1	8.0	0.7	64	0.51
L9200 13000N	Soil		2.2	26.6	24.7	151	0.4	23.8	9.7	569	2.79	112.7	3.4	9.3	2.0	44	0.9	1.5	0.9	64	0.47

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000112.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L9000 12875N	Soil	0.080	16	64	0.62	222	0.063	1	2.30	0.015	0.06	0.4	0.04	4.8	0.2	<0.05	6	1.7
L9000 12900N	Soil	0.080	16	39	0.58	213	0.047	2	1.91	0.013	0.06	0.9	0.03	3.2	0.2	0.06	5	0.9
L9000 12925N	Soil	0.060	14	36	0.50	175	0.056	<1	1.98	0.013	0.06	0.3	0.03	3.2	0.1	<0.05	5	<0.5
L9000 12950N	Soil	0.069	17	38	0.55	171	0.086	1	1.99	0.018	0.08	0.3	0.02	4.2	0.2	<0.05	5	0.6
L9000 12975N	Soil	0.077	14	40	0.58	189	0.098	1	1.91	0.015	0.11	0.4	0.02	3.7	0.1	<0.05	6	0.5
L9000 13000N	Soil	0.066	11	35	0.50	135	0.066	1	1.72	0.013	0.07	0.3	0.02	2.3	0.2	<0.05	6	0.7
L9000 13025N	Soil	0.072	12	31	0.49	118	0.054	1	1.65	0.009	0.07	0.3	0.03	2.3	0.2	<0.05	6	<0.5
L9000 13050N	Soil	0.071	13	38	0.54	150	0.061	1	1.91	0.012	0.06	0.1	0.02	2.7	0.2	<0.05	7	<0.5
L9000 13075N	Soil	0.092	14	34	0.53	153	0.043	<1	1.79	0.012	0.05	0.2	0.03	2.3	0.1	0.06	6	<0.5
L9000 13100N	Soil	0.076	12	36	0.48	151	0.043	1	1.60	0.009	0.05	0.2	0.02	1.9	0.1	<0.05	6	<0.5
L9000 13125N	Soil	0.089	13	40	0.57	187	0.041	2	1.99	0.012	0.06	0.3	0.04	2.7	0.1	<0.05	6	<0.5
L9000 13150N	Soil	0.088	20	40	0.61	224	0.054	2	2.27	0.013	0.07	0.3	0.03	3.4	0.2	<0.05	7	<0.5
L9000 13175N	Soil	0.083	14	43	0.69	155	0.092	1	2.56	0.012	0.09	0.5	0.05	4.0	0.2	<0.05	8	<0.5
L9000 13200N	Soil	0.068	13	30	0.49	114	0.080	1	1.67	0.011	0.08	0.9	0.04	2.5	0.1	<0.05	5	0.6
L9000 13225N	Soil	0.068	19	43	0.57	185	0.093	1	1.85	0.014	0.09	0.6	0.03	4.1	0.2	<0.05	6	<0.5
L9000 13250N	Soil	0.112	30	35	0.51	218	0.053	1	1.87	0.017	0.06	0.2	0.06	3.9	0.2	0.07	6	<0.5
L9000 13275N	Soil	0.060	12	30	0.41	83	0.078	<1	1.23	0.013	0.09	0.8	0.07	2.6	0.1	<0.05	5	<0.5
L9000 13300N	Soil	0.064	18	38	0.60	174	0.086	1	1.99	0.014	0.09	0.3	0.03	3.8	0.2	<0.05	6	<0.5
L9200 12725N	Soil	0.086	14	34	0.33	126	0.052	2	1.56	0.019	0.07	0.2	0.13	2.3	0.2	0.07	6	<0.5
L9200 12750N	Soil	0.050	11	34	0.35	94	0.066	2	1.43	0.014	0.06	0.3	0.07	2.5	0.1	<0.05	7	<0.5
L9200 12775N	Soil	0.076	9	32	0.22	85	0.038	1	1.05	0.024	0.04	0.2	0.09	1.5	0.1	0.09	4	<0.5
L9200 12800N	Soil	0.082	26	40	0.48	153	0.047	1	1.60	0.014	0.10	0.5	0.05	4.1	0.2	<0.05	6	<0.5
L9200 12825N	Soil	0.106	47	45	0.40	242	0.039	2	2.00	0.017	0.07	0.3	0.08	4.6	0.3	0.09	6	0.9
L9200 12850N	Soil	0.087	19	39	0.56	152	0.085	2	1.58	0.017	0.08	0.4	0.03	3.6	0.2	<0.05	5	<0.5
L9200 12875N	Soil	0.064	17	42	0.61	149	0.074	1	1.85	0.011	0.09	0.7	0.04	3.8	0.2	<0.05	6	<0.5
L9200 12900N	Soil	0.091	27	38	0.44	228	0.042	1	1.75	0.018	0.06	0.2	0.08	3.0	0.3	0.08	6	0.6
L9200 12925N	Soil	0.078	27	36	0.45	203	0.058	1	1.54	0.010	0.07	0.7	0.04	4.2	0.3	<0.05	5	0.8
L9200 12950N	Soil	0.066	23	37	0.45	153	0.077	<1	1.49	0.012	0.07	1.0	0.04	3.4	0.2	<0.05	5	<0.5
L9200 12975N	Soil	0.084	21	42	0.60	214	0.057	2	1.89	0.013	0.07	0.3	0.05	4.0	0.2	0.05	6	1.0
L9200 13000N	Soil	0.083	18	41	0.63	228	0.055	2	2.00	0.014	0.07	0.4	0.05	3.3	0.2	0.07	6	0.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000112.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L9200 13025N	Soil		1.1	18.0	34.5	157	0.4	20.6	8.8	528	2.63	47.9	3.5	2.1	2.9	50	1.0	1.8	0.3	63	0.63
L9200 13050N	Soil		1.4	18.3	29.7	100	0.3	21.1	9.2	499	2.57	32.8	3.6	3.3	2.6	47	0.4	1.8	0.3	60	0.56
L9200 13075N	Soil		0.4	14.4	32.3	74	0.3	17.5	6.7	195	2.16	23.4	4.7	1.7	2.8	34	0.3	1.8	0.3	57	0.38
L9200 13100N	Soil		1.2	19.5	31.7	117	0.2	19.7	8.3	201	2.38	33.0	5.9	12.4	4.8	37	0.9	3.2	0.2	68	0.49
L9200 13125N	Soil		1.3	16.7	21.6	91	0.1	20.8	9.1	443	2.90	50.2	3.1	3.0	1.8	31	0.4	1.9	0.3	68	0.39
L9200 13150N	Soil		1.2	19.7	14.7	88	0.2	22.7	11.5	837	3.06	18.9	3.3	<0.5	1.8	29	0.3	1.1	0.3	70	0.36
L9200 13175N	Soil		1.3	19.2	14.6	85	0.1	21.5	11.1	736	3.02	19.7	3.9	4.4	1.9	27	0.2	1.7	0.2	66	0.31
L9200 13200N	Soil		1.4	19.3	13.9	86	0.1	21.7	10.4	715	2.99	18.0	3.6	4.8	1.8	27	0.3	1.5	0.2	70	0.31
L9200 13225N	Soil		1.6	18.4	16.8	103	0.1	19.3	10.9	693	3.09	17.8	3.3	3.1	1.9	25	0.2	2.1	0.2	75	0.26
L9200 13250N	Soil		1.7	16.8	19.3	94	0.1	16.5	10.2	738	2.76	14.4	2.9	2.5	1.9	25	0.4	1.8	0.2	66	0.29
CRCX 03	Soil		0.8	18.0	6.1	51	<0.1	16.9	10.9	406	2.90	24.3	1.0	2.2	2.8	20	0.1	0.7	0.2	72	0.25
CRCX 04	Soil		1.1	19.8	11.5	63	<0.1	22.8	12.2	515	3.61	43.1	1.7	3.9	6.2	11	0.3	1.3	0.1	65	0.12
CRCX 05	Soil		1.6	15.1	15.6	75	<0.1	15.8	11.8	615	4.02	4.1	2.8	1.4	13.5	11	<0.1	0.4	0.3	39	0.15
CRCX 06	Soil		1.4	20.3	14.0	67	0.1	22.0	11.1	421	3.88	15.3	0.8	2.7	4.2	13	0.2	0.8	0.3	82	0.13
RDCK 10	Soil		5.4	17.3	10.3	65	<0.1	23.2	10.5	630	3.07	45.7	1.3	5.9	7.5	19	0.1	1.7	0.1	58	0.23
RDCK 11	Soil		1.3	19.0	9.6	73	<0.1	21.0	9.5	420	3.17	31.7	0.9	2.7	2.9	17	0.2	0.9	0.1	59	0.18
RDCK 12	Soil		1.0	21.2	9.6	64	<0.1	27.8	12.0	385	3.18	13.5	0.8	2.5	3.2	17	0.1	0.6	0.2	67	0.17
RDCK 13	Soil		1.2	19.8	10.1	67	<0.1	27.6	13.8	558	3.69	9.4	0.9	1.0	4.2	17	0.2	0.6	0.2	71	0.20
RDCK 14	Soil		0.8	17.3	11.7	72	<0.1	22.6	10.7	486	3.12	8.1	1.7	2.0	7.4	14	0.2	0.6	0.4	58	0.18
RDCK 15	Soil		1.2	19.2	30.5	130	<0.1	19.0	15.4	744	5.19	180.0	2.0	2.2	16.9	14	<0.1	2.0	0.4	70	0.12
RDCK 16	Soil		1.1	19.9	20.0	98	0.3	18.7	10.7	336	4.70	15.7	1.4	1.1	7.5	9	0.3	1.2	0.2	87	0.12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

CERTIFICATE OF ANALYSIS SMI09000112.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L9200 13025N	Soil	0.080	20	37	0.56	217	0.073	1	1.89	0.020	0.07	0.3	0.06	3.4	0.2	0.06	6	<0.5
L9200 13050N	Soil	0.072	19	37	0.60	189	0.061	1	1.98	0.020	0.06	0.3	0.03	3.5	0.2	0.08	5	<0.5
L9200 13075N	Soil	0.060	22	39	0.51	151	0.062	1	1.89	0.016	0.05	0.3	0.03	3.3	0.2	0.06	5	<0.5
L9200 13100N	Soil	0.073	20	39	0.59	168	0.094	<1	2.05	0.017	0.09	0.6	0.04	4.7	0.2	0.12	6	0.6
L9200 13125N	Soil	0.076	13	40	0.59	205	0.060	1	2.02	0.015	0.05	0.3	0.04	3.2	0.2	0.11	6	<0.5
L9200 13150N	Soil	0.088	15	39	0.62	210	0.084	1	2.03	0.012	0.07	0.5	0.05	3.4	0.1	0.12	7	<0.5
L9200 13175N	Soil	0.073	15	35	0.55	194	0.062	2	2.02	0.012	0.06	0.6	0.03	3.1	0.2	0.07	7	<0.5
L9200 13200N	Soil	0.078	16	36	0.55	187	0.067	1	2.07	0.012	0.06	0.4	0.05	3.0	0.1	0.08	7	<0.5
L9200 13225N	Soil	0.070	16	34	0.55	191	0.065	1	1.95	0.011	0.06	0.4	0.03	2.9	0.2	0.06	7	0.5
L9200 13250N	Soil	0.074	15	30	0.50	190	0.060	<1	1.88	0.012	0.06	0.4	0.04	2.6	0.2	0.07	6	<0.5
CRCX 03	Soil	0.052	9	28	0.56	151	0.113	1	2.00	0.015	0.06	0.4	0.04	2.5	0.1	<0.05	6	<0.5
CRCX 04	Soil	0.040	14	37	0.53	111	0.069	<1	2.67	0.010	0.06	0.2	0.05	3.6	0.1	<0.05	6	<0.5
CRCX 05	Soil	0.045	12	24	0.41	81	0.025	<1	2.68	0.007	0.09	0.7	0.02	4.6	0.2	<0.05	7	<0.5
CRCX 06	Soil	0.032	10	43	0.50	130	0.107	<1	2.54	0.010	0.06	0.2	0.04	4.1	0.2	<0.05	8	<0.5
RDCK 10	Soil	0.039	12	34	0.54	187	0.087	2	1.66	0.012	0.08	0.4	0.03	3.6	0.2	<0.05	5	<0.5
RDCK 11	Soil	0.056	9	36	0.47	147	0.070	<1	2.25	0.010	0.06	0.2	0.07	2.6	0.1	<0.05	5	0.8
RDCK 12	Soil	0.036	10	41	0.59	198	0.083	2	2.55	0.013	0.05	0.1	0.06	4.2	0.3	<0.05	6	<0.5
RDCK 13	Soil	0.057	10	43	0.59	116	0.111	<1	2.78	0.013	0.08	0.2	0.04	4.1	0.1	<0.05	7	0.7
RDCK 14	Soil	0.044	14	33	0.48	91	0.078	1	1.98	0.011	0.07	0.6	0.03	3.1	0.1	<0.05	6	<0.5
RDCK 15	Soil	0.026	19	42	1.18	127	0.223	<1	4.72	0.009	0.50	0.4	0.03	9.8	1.0	<0.05	17	<0.5
RDCK 16	Soil	0.031	10	31	0.63	100	0.237	<1	2.72	0.011	0.08	1.1	0.03	4.9	0.3	<0.05	11	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

QUALITY CONTROL REPORT SMI09000112.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
L8800 12000N	Soil		3.3	46.7	61.3	167	0.2	33.4	14.5	839	3.79	123.1	1.7	2.6	1.9	20	0.8	2.4	0.5	80	0.14
REP L8800 12000N	QC		3.2	47.4	61.0	170	0.2	34.0	13.8	820	3.72	126.6	1.7	2.2	2.0	21	0.8	2.6	0.5	80	0.15
L8800 12450N	Soil		5.9	98.9	84.3	216	1.2	61.6	17.7	1159	4.29	541.7	4.6	50.3	4.5	26	1.0	18.3	1.9	75	0.32
REP L8800 12450N	QC		6.1	96.5	82.1	212	1.3	61.3	18.0	1198	4.26	539.3	4.5	46.6	4.6	27	1.0	18.2	1.8	77	0.33
L9000 12200N	Soil		3.4	47.9	107.5	271	1.4	42.0	10.8	845	2.77	240.2	3.7	14.7	2.2	37	1.7	9.8	0.3	59	0.42
REP L9000 12200N	QC		3.3	50.6	112.8	269	1.5	42.9	11.0	889	2.83	245.0	3.9	16.4	2.2	38	1.9	10.0	0.4	63	0.45
L9000 13025N	Soil		1.3	15.6	40.8	97	0.3	16.9	8.7	735	2.70	32.7	1.8	4.3	1.9	21	0.5	2.3	0.2	65	0.27
REP L9000 13025N	QC		1.3	15.4	39.0	92	0.3	16.6	8.8	697	2.63	31.6	1.9	3.4	1.9	22	0.4	2.1	0.2	64	0.28
L9200 12925N	Soil		3.5	22.2	85.0	197	0.9	21.2	12.7	2140	4.80	576.0	6.3	12.5	8.2	28	1.5	13.5	0.4	59	0.35
REP L9200 12925N	QC		3.6	24.0	87.1	193	0.9	22.0	13.7	2357	5.20	588.1	6.5	8.8	8.3	28	1.5	14.0	0.4	61	0.38
L9200 13150N	Soil		1.2	19.7	14.7	88	0.2	22.7	11.5	837	3.06	18.9	3.3	<0.5	1.8	29	0.3	1.1	0.3	70	0.36
REP L9200 13150N	QC		1.5	21.1	15.4	91	0.1	22.6	11.9	867	3.16	19.5	3.4	0.5	2.0	29	0.3	1.1	0.3	73	0.36
Reference Materials																					
STD DS7	Standard		21.2	115.2	63.7	406	0.8	57.7	9.7	663	2.50	53.6	4.7	63.5	4.2	82	6.4	6.2	4.4	87	0.99
STD DS7	Standard		20.5	111.6	62.3	388	0.8	54.9	9.1	615	2.38	50.3	4.5	61.8	3.9	72	6.1	5.8	4.2	84	0.92
STD DS7	Standard		20.2	110.6	66.5	397	0.8	56.6	9.3	616	2.38	52.1	4.8	71.5	4.7	78	6.6	5.7	4.9	84	0.92
STD DS7	Standard		19.9	104.7	65.1	377	0.8	56.4	9.3	606	2.38	48.6	4.6	55.9	4.1	69	5.5	5.1	4.1	85	0.95
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 14, 2009

QUALITY CONTROL REPORT SMI09000112.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
L8800 12000N	Soil	0.071	14	40	0.48	130	0.064	2	1.69	0.011	0.10	0.1	0.05	2.6	0.1	0.10	6	0.9
REP L8800 12000N	QC	0.072	14	39	0.50	136	0.065	2	1.73	0.012	0.10	0.2	0.05	2.7	0.1	0.11	7	1.4
L8800 12450N	Soil	0.088	16	40	0.67	195	0.041	2	1.97	0.014	0.10	0.9	0.08	4.1	0.2	0.06	6	1.3
REP L8800 12450N	QC	0.084	17	41	0.66	196	0.045	2	1.94	0.014	0.11	0.8	0.09	4.2	0.2	0.06	6	1.1
L9000 12200N	Soil	0.094	17	37	0.35	251	0.033	2	1.44	0.013	0.14	2.1	0.06	2.4	0.2	0.16	5	1.2
REP L9000 12200N	QC	0.094	18	38	0.37	263	0.039	2	1.51	0.015	0.16	2.1	0.06	2.6	0.2	0.18	4	1.1
L9000 13025N	Soil	0.072	12	31	0.49	118	0.054	1	1.65	0.009	0.07	0.3	0.03	2.3	0.2	<0.05	6	<0.5
REP L9000 13025N	QC	0.072	13	32	0.49	113	0.058	1	1.65	0.010	0.07	0.2	0.02	2.4	0.1	<0.05	6	<0.5
L9200 12925N	Soil	0.078	27	36	0.45	203	0.058	1	1.54	0.010	0.07	0.7	0.04	4.2	0.3	<0.05	5	0.8
REP L9200 12925N	QC	0.076	27	39	0.45	206	0.065	1	1.58	0.011	0.07	0.7	0.04	4.9	0.3	<0.05	5	0.6
L9200 13150N	Soil	0.088	15	39	0.62	210	0.084	1	2.03	0.012	0.07	0.5	0.05	3.4	0.1	0.12	7	<0.5
REP L9200 13150N	QC	0.085	16	39	0.64	220	0.075	1	2.04	0.013	0.06	0.5	0.05	3.8	0.1	0.13	7	<0.5
Reference Materials																		
STD DS7	Standard	0.083	14	219	1.03	429	0.143	41	1.05	0.103	0.46	3.9	0.19	2.9	4.2	0.22	5	3.5
STD DS7	Standard	0.074	12	201	1.01	392	0.129	39	1.02	0.104	0.44	3.6	0.18	2.8	4.2	0.23	5	3.7
STD DS7	Standard	0.076	13	209	0.98	408	0.113	39	0.94	0.087	0.44	4.0	0.19	2.4	4.1	0.18	4	3.4
STD DS7	Standard	0.076	13	221	1.02	380	0.117	39	0.99	0.099	0.44	3.5	0.18	2.4	4.0	0.20	5	3.2
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 06, 2009
Report Date: August 13, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000113.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 1

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	1	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	1	Dry at 60C			SMI
1DX15	1	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 13, 2009

CERTIFICATE OF ANALYSIS SMI09000113.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
RDS 01	Silt		2.7	32.1	7.4	68	0.2	24.5	12.2	1153	2.98	105.9	3.0	10.7	3.5	31	0.2	5.5	0.4	70	0.49

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 13, 2009

CERTIFICATE OF ANALYSIS SMI09000113.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
RDS 01	Silt	0.083	15	36	0.67	273	0.105	2	1.96	0.016	0.07	1.3	0.09	4.4	0.2	0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 13, 2009

QUALITY CONTROL REPORT SMI09000113.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Reference Materials																					
STD DS7	Standard	20.5	111.6	62.3	388	0.8	54.9	9.1	615	2.38	50.3	4.5	61.8	3.9	72	6.1	5.8	4.2	84	0.92	0.074
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 13, 2009

QUALITY CONTROL REPORT SMI09000113.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																	
STD DS7	Standard	12	201	1.01	392	0.129	39	1.02	0.104	0.44	3.6	0.18	2.8	4.2	0.23	5	3.7
STD DS7 Expected		12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 06, 2009
Report Date: August 19, 2009
Page: 1 of 12

CERTIFICATE OF ANALYSIS SMI09000114.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 330

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	328	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	328	Dry at 60C			SMI
1DX15	327	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7200 12525	Soil		1.7	44.8	14.4	53	0.2	21.4	10.6	443	3.69	17.8	2.7	45.1	5.4	27	0.3	0.9	2.5	72	0.19
L7200 12550	Soil		1.0	32.2	9.9	45	<0.1	22.4	9.8	289	3.00	12.5	2.3	28.6	4.7	19	0.2	0.7	1.2	66	0.16
L7200 12600	Soil		1.2	64.5	9.7	54	0.1	22.5	11.1	445	3.29	22.2	2.4	80.8	5.8	28	0.4	0.9	3.7	68	0.19
L7200 12625	Soil		1.8	62.4	10.2	72	0.1	23.5	9.0	293	3.60	30.6	2.7	89.0	5.5	33	0.5	1.1	7.1	69	0.17
L7200 12675	Soil		1.5	37.3	9.5	53	<0.1	28.3	13.8	451	3.57	28.7	2.6	50.8	4.7	29	0.3	0.8	1.6	74	0.18
L7200 12700	Soil		2.0	65.3	11.0	62	0.1	32.3	19.7	547	3.83	54.2	6.3	117.1	9.1	36	0.3	1.1	5.5	72	0.27
L7200 12725	Soil		1.2	53.6	10.5	48	<0.1	21.8	14.5	461	3.65	32.7	4.5	40.6	8.3	57	0.1	1.1	1.9	75	0.24
L7200 12750	Soil		1.7	36.0	13.5	60	<0.1	24.2	11.5	376	3.97	25.1	4.6	25.4	8.5	20	0.2	1.0	1.0	81	0.16
L7200 12775	Soil		4.8	39.9	11.5	77	0.2	25.1	11.8	661	3.34	23.1	2.1	3.2	0.4	18	0.3	0.9	0.4	89	0.18
L7200 12800	Soil		1.6	36.6	7.9	52	<0.1	21.1	8.4	294	2.47	11.8	1.0	15.9	1.3	19	0.1	0.8	0.6	54	0.18
L7200 12825	Soil		6.0	21.9	19.7	55	0.3	15.4	6.5	222	2.79	116.8	2.1	38.3	5.3	26	0.1	3.2	4.2	83	0.25
L7200 12850	Soil		4.4	39.3	40.1	91	0.7	16.0	6.2	219	4.00	340.0	4.9	134.3	9.9	34	0.2	5.7	5.1	61	0.23
L7200 12875	Soil		4.6	64.4	21.2	104	0.7	40.9	14.8	490	4.23	185.2	3.2	95.1	6.7	35	0.4	2.8	5.1	125	0.31
L7200 12900	Soil		4.3	53.1	33.9	85	0.7	25.9	9.4	574	4.11	428.9	4.4	107.3	3.3	30	0.3	4.8	7.6	71	0.16
L7200 12925	Soil		5.4	69.4	18.5	80	0.7	25.1	7.4	269	3.79	238.0	5.0	83.7	11.5	55	0.3	6.9	6.8	67	0.33
L7200 12950	Soil		3.3	60.9	30.7	114	0.9	34.6	12.7	623	4.27	365.5	1.9	99.3	4.6	32	0.4	6.2	13.3	89	0.30
L7200 12975	Soil		2.4	45.3	17.6	79	0.3	28.2	10.8	460	3.12	197.9	2.9	14.3	2.7	25	0.4	2.9	5.0	72	0.34
L7200 13000	Soil		3.4	25.6	14.8	50	0.3	16.4	15.3	1088	2.14	66.7	2.7	4.6	0.8	31	0.2	1.0	1.0	61	0.28
L7200 13025	Soil		1.7	40.3	19.8	89	0.2	22.5	9.8	316	3.21	138.6	3.0	16.7	6.5	40	0.5	1.4	1.8	71	0.37
L7200 13050	Soil		1.5	26.9	15.3	89	0.2	19.6	10.6	351	2.64	74.3	3.2	5.2	6.1	64	0.4	0.8	1.0	70	0.51
L7200 13075	Soil		2.5	36.1	29.2	142	0.4	25.4	12.9	401	3.84	233.6	6.5	13.3	6.7	39	0.3	1.4	1.9	91	0.44
L7200 13100	Soil		1.6	38.3	19.6	94	0.5	19.8	8.9	314	3.00	224.0	4.7	12.2	5.9	32	0.3	2.4	2.1	61	0.33
L7200 13125	Soil		1.2	33.1	11.0	75	0.2	23.8	12.2	386	3.17	47.3	4.0	6.3	7.6	34	0.2	0.9	0.5	89	0.42
L7200 13150	Soil		1.7	32.5	23.1	75	0.4	24.3	11.4	216	3.55	281.1	6.0	13.4	7.9	32	0.2	1.6	1.2	87	0.35
L7200 13175	Soil		1.2	43.7	23.1	87	0.6	18.6	11.5	483	4.06	660.0	6.0	26.1	8.8	43	0.3	3.2	2.0	83	0.42
L7200 13200	Soil		1.1	33.4	41.5	96	0.6	18.4	11.7	428	3.80	828.3	3.1	27.9	6.8	44	0.3	2.2	4.1	83	0.39
L7200 13225	Soil		1.2	35.3	43.9	103	0.8	19.2	12.3	593	3.57	817.0	3.9	25.9	8.7	42	0.5	2.1	3.2	85	0.47
L7200 13250	Soil		0.8	23.0	10.5	81	<0.1	15.6	12.0	628	3.14	83.2	2.5	5.4	7.1	36	0.3	1.0	0.3	87	0.42
L7200 13275	Soil		1.1	30.9	25.8	122	0.1	19.1	12.8	560	3.75	197.3	3.1	7.2	8.2	43	0.3	1.3	0.7	102	0.51
L7200 13300	Soil		1.4	23.2	28.4	102	0.2	15.6	10.8	606	3.18	212.3	2.7	6.1	4.8	29	0.3	1.0	0.5	89	0.37

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7200 12525	Soil	0.057	20	35	0.54	131	0.070	<1	2.08	0.022	0.10	0.2	0.07	2.9	0.2	0.13	8	<0.5
L7200 12550	Soil	0.044	18	34	0.53	109	0.080	<1	2.06	0.017	0.07	0.3	0.03	3.0	0.1	0.08	6	<0.5
L7200 12600	Soil	0.063	22	33	0.57	144	0.086	1	1.84	0.028	0.10	0.4	0.05	2.9	0.2	0.15	6	<0.5
L7200 12625	Soil	0.055	23	38	0.49	105	0.074	<1	1.74	0.031	0.11	0.7	0.04	2.6	0.1	0.18	7	<0.5
L7200 12675	Soil	0.049	17	39	0.63	104	0.096	<1	1.90	0.028	0.10	1.2	0.05	2.9	0.2	0.14	6	0.5
L7200 12700	Soil	0.110	32	40	0.68	112	0.095	2	1.92	0.037	0.12	2.1	0.04	3.8	0.2	0.17	6	<0.5
L7200 12725	Soil	0.067	21	28	0.63	159	0.096	<1	1.92	0.063	0.13	3.6	0.03	3.4	0.2	0.27	6	0.7
L7200 12750	Soil	0.044	23	41	0.55	80	0.106	1	1.76	0.021	0.06	0.7	0.04	3.0	0.1	0.11	7	<0.5
L7200 12775	Soil	0.111	11	43	0.53	99	0.039	2	2.01	0.018	0.07	1.8	0.09	1.5	0.2	0.14	7	0.6
L7200 12800	Soil	0.068	11	28	0.48	81	0.055	<1	1.58	0.030	0.06	0.4	0.05	2.5	0.2	0.10	5	0.5
L7200 12825	Soil	0.067	21	41	0.49	225	0.083	<1	1.67	0.015	0.13	1.6	0.05	3.5	0.3	0.08	6	0.7
L7200 12850	Soil	0.068	25	31	0.43	245	0.032	2	1.64	0.018	0.13	1.7	0.10	3.6	0.4	0.10	5	1.5
L7200 12875	Soil	0.103	20	66	0.75	320	0.142	<1	1.92	0.026	0.32	3.6	0.07	5.4	0.4	0.22	7	1.5
L7200 12900	Soil	0.073	17	36	0.42	236	0.021	2	1.55	0.024	0.21	2.1	0.12	2.9	0.4	0.39	6	0.9
L7200 12925	Soil	0.088	21	38	0.46	290	0.077	<1	1.36	0.031	0.26	1.0	0.07	3.7	0.5	0.44	5	0.9
L7200 12950	Soil	0.085	15	47	0.66	322	0.103	1	1.83	0.027	0.30	0.7	0.04	3.9	0.4	0.35	7	1.4
L7200 12975	Soil	0.060	17	38	0.54	140	0.065	<1	1.95	0.019	0.07	0.5	0.03	3.2	0.1	0.08	6	<0.5
L7200 13000	Soil	0.096	14	29	0.34	228	0.046	<1	1.30	0.025	0.04	0.4	0.04	2.4	0.3	0.13	5	<0.5
L7200 13025	Soil	0.087	19	37	0.59	204	0.121	<1	1.64	0.024	0.12	0.5	0.03	3.8	0.2	0.13	5	<0.5
L7200 13050	Soil	0.071	19	31	0.68	315	0.097	1	2.32	0.024	0.12	0.3	0.02	4.1	0.2	0.07	6	<0.5
L7200 13075	Soil	0.080	28	42	0.80	336	0.106	2	3.11	0.026	0.14	0.3	0.06	6.3	0.3	0.11	8	<0.5
L7200 13100	Soil	0.063	19	30	0.55	240	0.080	2	2.02	0.022	0.09	0.3	0.04	3.9	0.2	0.09	6	<0.5
L7200 13125	Soil	0.089	21	41	0.78	330	0.141	<1	2.51	0.020	0.14	0.3	0.04	5.2	0.3	0.06	7	<0.5
L7200 13150	Soil	0.058	22	41	0.69	293	0.101	2	2.70	0.021	0.08	0.2	0.05	5.7	0.3	0.06	8	<0.5
L7200 13175	Soil	0.070	21	41	0.64	267	0.108	1	2.23	0.020	0.15	0.2	0.03	6.6	0.2	0.05	6	<0.5
L7200 13200	Soil	0.082	16	34	0.71	248	0.145	1	2.00	0.021	0.12	0.2	0.01	4.7	0.2	0.08	6	0.7
L7200 13225	Soil	0.079	19	38	0.69	272	0.136	1	2.14	0.021	0.17	0.2	0.03	6.0	0.2	<0.05	6	<0.5
L7200 13250	Soil	0.094	18	33	0.71	264	0.147	<1	2.08	0.020	0.16	0.2	0.03	4.8	0.2	<0.05	6	<0.5
L7200 13275	Soil	0.098	18	41	0.78	338	0.194	1	2.13	0.024	0.22	0.3	0.01	5.9	0.3	<0.05	6	<0.5
L7200 13300	Soil	0.099	13	36	0.60	227	0.137	<1	1.82	0.022	0.11	0.2	0.05	3.9	0.2	0.07	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7200 13325	Soil		1.3	23.9	12.0	83	0.1	17.1	12.4	641	3.53	197.0	2.1	2.8	6.2	23	0.4	1.0	0.5	85	0.33
L7200 13350	Soil		1.2	30.8	18.3	107	0.1	16.9	16.5	562	4.46	133.5	3.3	4.3	9.8	27	0.3	1.0	0.3	108	0.36
L7200 13375	Soil		1.4	31.9	10.7	94	0.1	18.1	14.9	584	4.04	42.4	5.0	9.3	12.2	34	0.3	1.3	0.4	114	0.59
L7200 13400	Soil		1.1	29.3	13.5	96	<0.1	21.3	10.8	382	3.20	82.1	2.8	2.3	6.6	21	0.4	0.8	0.6	90	0.31
L7200 13425	Soil		0.8	24.0	9.2	71	<0.1	19.9	11.3	289	2.89	18.7	2.2	2.0	6.7	25	0.2	1.0	0.2	85	0.41
L7200 13450	Soil		1.3	28.7	55.1	430	0.3	21.0	11.8	689	3.22	263.0	2.9	11.0	8.2	26	2.3	1.8	0.4	80	0.41
L7200 13475	Soil		1.3	20.5	7.0	57	<0.1	20.1	7.8	247	2.40	9.7	0.9	4.3	2.9	13	0.3	0.3	0.2	67	0.21
L7200 13500	Soil		0.6	25.0	7.1	57	<0.1	19.9	10.0	256	2.55	9.9	2.2	4.2	6.1	23	0.2	0.3	0.3	72	0.37
L7400 12525	Soil		3.3	27.4	20.6	39	0.4	15.0	7.4	277	2.86	137.5	3.3	65.7	4.4	24	<0.1	3.4	5.2	58	0.18
L7400 12550	Soil		2.9	34.7	21.1	58	0.4	20.0	8.2	315	3.15	142.4	3.1	52.1	7.0	29	0.1	3.5	3.0	74	0.27
L7400 12575	Soil		2.7	25.4	21.4	34	0.5	11.5	7.2	620	2.32	129.7	8.9	58.1	1.2	30	0.3	3.3	3.5	37	0.55
L7400 12600	Soil		2.2	57.8	15.8	48	0.3	18.8	8.3	356	2.83	162.8	5.4	28.2	1.8	19	0.2	2.1	3.5	55	0.20
L7400 12625	Soil		1.4	47.0	9.4	56	0.2	22.9	11.1	449	2.75	52.8	3.9	14.2	6.3	21	0.2	1.3	2.2	63	0.32
L7400 12650	Soil		1.5	46.9	15.1	74	0.3	22.9	11.5	619	2.59	67.7	4.9	16.0	2.5	26	0.5	1.4	2.3	56	0.36
L7400 12675	Soil		1.8	43.8	16.0	66	0.3	17.5	8.4	500	2.58	74.8	2.6	19.5	1.6	22	0.3	1.3	2.2	55	0.26
L7400 12700	Soil		1.6	57.3	14.4	56	0.2	15.8	8.9	420	2.68	128.9	3.2	20.5	4.6	22	0.2	2.6	3.2	47	0.25
L7400 12725	Soil		1.7	113.1	23.0	79	0.3	23.4	12.5	611	3.44	198.9	4.9	25.7	3.7	20	0.3	3.0	7.1	55	0.20
L7400 12750	Soil		1.1	91.6	18.1	59	0.3	21.0	9.6	466	2.97	87.9	5.2	231.2	5.7	26	0.2	1.2	10.7	56	0.21
L7400 12775	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
L7400 12800	Soil		1.7	34.9	12.5	66	0.1	26.6	13.9	690	3.19	142.7	4.6	12.2	3.2	23	0.2	1.3	1.3	65	0.36
L7400 12825	Soil		1.4	25.9	9.2	52	0.2	19.1	9.0	577	2.69	66.8	3.9	6.6	2.2	16	0.2	0.7	0.5	60	0.18
L7400 12850	Soil		1.6	27.5	9.9	61	0.1	20.3	8.3	430	2.51	49.0	1.6	3.0	1.0	15	0.3	0.7	0.4	55	0.17
L7400 12875	Soil		1.4	22.3	10.6	73	<0.1	23.5	10.6	523	3.08	16.1	1.0	4.8	0.8	14	0.2	0.6	0.2	76	0.15
L7400 12900	Soil		1.2	25.8	7.2	65	<0.1	24.0	10.9	463	2.66	16.4	0.8	2.6	1.7	18	0.1	0.5	0.2	64	0.24
L7400 12925	Soil		1.5	25.1	20.8	78	<0.1	25.5	11.6	523	3.05	162.2	1.3	23.9	1.3	16	0.1	1.2	0.3	72	0.20
L7400 12950	Soil		1.2	25.5	25.8	115	0.1	26.5	12.0	562	2.93	118.7	2.3	9.7	5.5	25	0.3	0.8	0.5	58	0.25
L7400 12975	Soil		1.5	23.4	90.4	291	0.2	24.6	11.7	755	2.93	71.1	3.3	7.8	5.8	20	1.7	1.0	0.3	60	0.30
L7400 13000	Soil		0.9	22.1	31.1	113	0.3	15.1	11.0	738	2.88	274.5	3.8	8.7	8.2	39	0.6	1.1	0.8	49	0.41
L7400 13025	Soil		1.1	26.1	37.5	103	0.2	19.8	12.9	646	3.00	37.0	2.9	3.9	6.7	23	0.5	0.7	0.3	78	0.32
L7400 13050	Soil		1.5	39.6	9.1	82	<0.1	21.4	11.2	457	3.28	19.9	1.4	2.7	2.7	18	0.4	0.5	0.2	98	0.23

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7200 13325	Soil	0.080	13	34	0.65	180	0.151	<1	2.06	0.018	0.11	0.3	0.04	3.9	0.2	<0.05	6	<0.5
L7200 13350	Soil	0.060	18	41	0.87	283	0.158	<1	2.56	0.017	0.17	0.2	0.02	7.0	0.2	<0.05	7	<0.5
L7200 13375	Soil	0.095	25	43	0.90	351	0.214	<1	2.34	0.025	0.29	0.2	0.02	8.6	0.4	<0.05	7	<0.5
L7200 13400	Soil	0.077	17	40	0.63	175	0.152	<1	2.13	0.021	0.11	0.3	0.03	5.2	0.3	<0.05	6	0.8
L7200 13425	Soil	0.085	17	38	0.63	174	0.160	<1	2.01	0.023	0.09	0.2	0.03	4.8	0.2	<0.05	6	<0.5
L7200 13450	Soil	0.075	19	37	0.61	170	0.137	<1	1.82	0.021	0.10	0.4	0.03	6.0	0.2	<0.05	5	<0.5
L7200 13475	Soil	0.057	8	33	0.49	89	0.095	2	1.75	0.011	0.04	0.2	0.03	2.5	0.1	<0.05	5	0.6
L7200 13500	Soil	0.081	15	36	0.58	128	0.115	2	1.68	0.018	0.07	0.2	0.02	4.6	0.1	<0.05	5	<0.5
L7400 12525	Soil	0.073	23	36	0.41	218	0.031	3	1.40	0.010	0.10	1.0	0.05	2.7	0.2	0.09	5	1.2
L7400 12550	Soil	0.075	23	44	0.60	278	0.063	2	1.87	0.013	0.16	0.8	0.07	3.7	0.3	0.06	6	1.6
L7400 12575	Soil	0.121	36	26	0.17	160	0.016	4	1.14	0.019	0.13	0.9	0.09	1.5	0.2	0.29	4	1.8
L7400 12600	Soil	0.087	42	31	0.40	151	0.024	2	1.94	0.018	0.05	0.4	0.06	2.1	0.2	0.09	6	1.0
L7400 12625	Soil	0.070	23	32	0.67	176	0.084	2	1.67	0.013	0.11	2.4	0.01	3.9	0.2	<0.05	5	0.8
L7400 12650	Soil	0.088	33	32	0.51	144	0.046	2	1.66	0.018	0.08	0.8	0.12	2.5	0.2	0.08	6	1.0
L7400 12675	Soil	0.083	16	27	0.42	140	0.039	2	1.45	0.014	0.06	0.4	0.07	1.8	0.1	0.08	6	<0.5
L7400 12700	Soil	0.058	22	23	0.41	141	0.037	2	1.61	0.014	0.07	0.5	0.03	2.7	0.2	<0.05	5	0.7
L7400 12725	Soil	0.066	20	31	0.52	158	0.032	2	1.87	0.014	0.06	0.5	0.03	2.6	0.2	0.05	6	0.5
L7400 12750	Soil	0.058	27	29	0.46	122	0.055	2	1.51	0.025	0.10	1.1	0.04	2.6	0.2	0.12	5	0.6
L7400 12775	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
L7400 12800	Soil	0.088	21	35	0.64	166	0.064	2	1.80	0.016	0.07	2.2	0.05	2.9	0.1	<0.05	6	0.9
L7400 12825	Soil	0.087	15	31	0.49	76	0.066	2	1.33	0.014	0.09	2.4	0.07	2.5	0.2	0.11	6	0.7
L7400 12850	Soil	0.108	11	32	0.39	79	0.046	2	1.41	0.017	0.07	1.1	0.11	2.0	0.2	0.09	6	1.0
L7400 12875	Soil	0.056	9	38	0.48	88	0.062	2	1.78	0.010	0.05	1.0	0.05	2.2	<0.1	<0.05	7	0.6
L7400 12900	Soil	0.056	9	34	0.55	142	0.080	2	1.98	0.013	0.05	0.2	0.05	2.6	<0.1	<0.05	6	0.8
L7400 12925	Soil	0.050	10	36	0.54	91	0.067	2	1.72	0.012	0.06	1.0	0.04	2.3	<0.1	<0.05	7	0.5
L7400 12950	Soil	0.077	15	32	0.55	88	0.090	2	1.73	0.017	0.08	0.9	0.04	3.0	0.1	0.06	5	<0.5
L7400 12975	Soil	0.083	19	34	0.56	85	0.078	2	1.52	0.015	0.07	0.6	0.05	3.0	0.1	<0.05	6	<0.5
L7400 13000	Soil	0.084	26	25	0.44	153	0.068	2	1.22	0.026	0.16	0.5	0.03	4.0	0.2	0.16	4	<0.5
L7400 13025	Soil	0.082	17	31	0.69	204	0.128	2	1.85	0.016	0.15	0.2	0.03	4.2	0.2	<0.05	6	0.6
L7400 13050	Soil	0.072	10	43	0.70	206	0.128	3	2.18	0.014	0.08	<0.1	0.04	3.4	0.2	<0.05	7	0.9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7400 13075	Soil		1.3	28.7	20.8	82	0.1	23.8	14.9	640	3.27	18.3	1.6	3.7	4.0	27	0.3	0.5	0.2	95	0.35
L7400 13100	Soil		2.7	36.8	14.1	79	<0.1	27.0	15.2	699	3.38	14.2	2.7	2.6	3.3	21	0.2	0.6	0.2	92	0.32
L7400 13125	Soil		1.1	26.4	6.9	73	<0.1	18.6	15.9	563	3.68	11.3	2.5	4.3	7.4	26	0.1	0.4	0.1	114	0.38
L7400 13150	Soil		0.9	20.3	75.0	393	0.2	16.9	11.8	541	2.91	94.5	1.9	4.9	4.5	28	1.5	0.7	0.2	76	0.33
L7400 13175	Soil		0.7	23.8	12.7	101	<0.1	16.0	11.1	515	2.76	40.9	3.2	7.3	5.9	58	0.5	0.4	0.2	75	0.46
L7400 13200	Soil		1.2	24.5	9.1	75	<0.1	17.3	13.0	545	2.99	67.2	3.4	2.2	7.9	46	0.4	0.4	0.2	91	0.46
L7400 13225	Soil		1.7	28.1	8.8	68	<0.1	20.2	12.6	502	2.96	148.7	3.0	7.0	5.8	37	0.2	0.6	0.4	89	0.35
L7400 13250	Soil		1.1	25.8	8.0	82	<0.1	17.2	13.5	574	3.21	54.6	2.9	2.1	6.1	30	0.4	0.7	0.4	92	0.36
L7400 13275	Soil		1.7	22.8	36.0	131	0.1	21.1	12.1	522	3.08	79.7	1.5	5.5	3.5	26	0.9	0.9	0.4	80	0.26
L7400 13300	Soil		0.9	17.1	14.5	60	<0.1	16.4	8.6	277	2.40	10.8	1.2	1.3	3.6	120	0.3	0.6	0.2	72	0.32
L7400 13325	Soil		1.1	25.8	8.5	62	<0.1	20.2	11.1	426	2.54	11.9	2.0	3.7	4.3	45	0.3	0.4	0.2	76	0.42
L7400 13350	Soil		1.1	28.2	8.7	69	<0.1	21.0	12.8	430	3.05	16.7	3.8	2.9	5.9	54	0.2	0.4	0.2	87	0.44
L7400 13375	Soil		1.4	25.4	13.6	59	<0.1	18.4	12.4	358	3.31	20.3	2.2	11.6	5.6	21	0.2	0.5	0.2	92	0.28
L7400 13400	Soil		0.8	23.1	11.3	69	<0.1	16.8	11.6	385	2.59	11.3	2.3	3.6	6.3	40	0.2	0.4	0.2	81	0.40
L7400 13425	Soil		0.7	25.7	10.0	59	<0.1	20.0	11.5	467	2.63	11.7	1.8	2.5	5.4	50	0.2	0.4	0.3	81	0.40
L7400 13450	Soil		1.7	34.6	8.5	55	<0.1	20.6	8.0	269	2.38	14.2	1.2	2.3	1.4	23	0.2	0.7	0.2	57	0.19
L7400 13475	Soil		0.7	25.4	15.6	91	<0.1	17.1	11.7	497	3.05	24.4	3.4	3.4	7.2	39	0.3	0.5	0.4	93	0.46
L7400 13500	Soil		1.7	23.6	17.3	76	0.2	17.7	12.1	836	3.31	55.9	3.1	2.3	2.5	22	0.2	0.7	0.4	85	0.18
L7600 12525	Soil		1.0	22.2	9.4	58	<0.1	23.9	10.9	460	2.76	11.4	1.4	15.6	3.4	18	0.2	0.6	0.2	71	0.29
L7600 12550	Soil		2.5	49.7	11.9	53	0.1	20.6	12.7	539	2.84	89.3	2.2	15.2	3.9	23	0.2	2.0	1.2	57	0.25
L7600 12575	Soil		3.4	48.9	10.5	57	0.2	23.0	11.4	487	2.99	148.3	2.6	6.0	5.4	26	0.2	2.3	1.7	62	0.29
L7600 12600	Soil		1.6	30.7	7.8	54	<0.1	24.8	11.8	416	2.65	19.5	1.6	4.7	2.7	168	0.1	0.6	0.3	63	0.29
L7600 12625	Soil		0.9	25.0	11.5	58	<0.1	24.0	11.9	453	2.84	12.7	1.3	3.2	2.4	20	0.3	0.6	0.2	69	0.22
L7600 12650	Soil		0.6	24.1	9.4	55	<0.1	21.4	8.5	267	2.48	25.8	1.1	3.9	3.8	21	0.4	0.6	0.6	59	0.31
L7600 12675	Soil		1.0	21.8	9.0	49	<0.1	20.5	8.8	336	2.49	47.6	2.0	3.9	3.4	16	0.1	0.7	0.6	60	0.22
L7600 12700	Soil		1.6	22.0	9.9	62	0.2	15.9	8.2	663	2.46	152.0	1.9	4.4	1.6	19	0.5	0.7	1.4	60	0.22
L7600 12725	Soil		1.9	42.1	17.0	62	0.4	18.7	9.9	578	2.71	373.8	6.5	8.6	2.2	21	0.3	1.1	3.7	46	0.19
L7600 12750	Soil		1.0	27.0	12.0	58	0.2	20.7	8.8	432	2.54	375.7	1.6	9.3	2.6	23	0.3	0.8	2.1	54	0.20
L7600 12775	Soil		0.6	20.4	7.3	55	<0.1	22.0	9.5	365	2.38	55.9	1.6	5.2	5.3	19	0.2	0.5	0.7	63	0.27
L7600 12825	Soil		1.3	24.5	9.3	58	<0.1	21.4	9.2	372	2.65	35.4	1.9	11.2	2.0	14	0.3	0.5	0.8	67	0.18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7400 13075	Soil	0.088	11	38	0.74	210	0.146	2	1.91	0.015	0.17	0.3	0.04	3.4	0.2	<0.05	6	<0.5
L7400 13100	Soil	0.099	12	38	0.74	180	0.117	3	2.01	0.019	0.11	0.1	0.05	3.7	0.2	0.06	6	0.9
L7400 13125	Soil	0.100	14	40	0.92	268	0.206	2	2.26	0.015	0.32	0.2	0.02	5.0	0.4	<0.05	7	<0.5
L7400 13150	Soil	0.084	12	30	0.64	167	0.115	2	1.95	0.016	0.15	0.2	0.03	3.0	0.2	<0.05	5	0.5
L7400 13175	Soil	0.084	16	28	0.70	338	0.115	1	1.99	0.021	0.17	0.2	0.02	3.1	0.2	<0.05	5	<0.5
L7400 13200	Soil	0.097	18	32	0.76	306	0.165	1	1.93	0.022	0.24	0.5	0.01	3.7	0.3	<0.05	6	<0.5
L7400 13225	Soil	0.078	16	35	0.68	225	0.139	2	1.88	0.020	0.15	0.3	0.03	3.4	0.2	<0.05	6	<0.5
L7400 13250	Soil	0.097	14	33	0.78	220	0.145	2	2.01	0.015	0.16	0.3	0.04	4.3	0.2	<0.05	6	<0.5
L7400 13275	Soil	0.066	9	33	0.64	169	0.109	2	1.96	0.014	0.09	0.4	0.03	2.9	0.1	<0.05	6	<0.5
L7400 13300	Soil	0.078	10	28	0.54	239	0.111	1	1.98	0.013	0.10	0.3	0.04	2.6	0.1	<0.05	6	<0.5
L7400 13325	Soil	0.095	13	33	0.59	271	0.139	2	1.68	0.028	0.15	0.2	0.05	3.1	0.2	<0.05	5	<0.5
L7400 13350	Soil	0.105	18	37	0.73	355	0.164	2	1.90	0.019	0.17	0.2	0.02	4.3	0.2	<0.05	6	<0.5
L7400 13375	Soil	0.089	12	38	0.65	163	0.135	2	2.39	0.013	0.10	0.2	0.04	3.5	0.3	<0.05	6	<0.5
L7400 13400	Soil	0.089	16	33	0.63	283	0.178	<1	1.82	0.020	0.15	0.4	0.03	3.6	0.2	<0.05	5	<0.5
L7400 13425	Soil	0.090	16	36	0.59	230	0.155	1	1.57	0.019	0.12	0.4	0.02	3.5	0.1	<0.05	5	<0.5
L7400 13450	Soil	0.066	8	29	0.45	82	0.059	2	1.44	0.030	0.05	0.1	0.09	2.5	0.1	0.12	4	<0.5
L7400 13475	Soil	0.095	17	36	0.71	283	0.193	<1	1.91	0.021	0.16	0.5	0.02	4.4	0.2	<0.05	6	<0.5
L7400 13500	Soil	0.079	13	36	0.52	227	0.092	<1	2.07	0.018	0.06	0.2	0.09	3.5	0.2	0.09	6	<0.5
L7600 12525	Soil	0.069	13	35	0.57	88	0.107	1	1.31	0.013	0.07	0.4	0.03	2.7	0.1	<0.05	6	<0.5
L7600 12550	Soil	0.062	13	29	0.54	154	0.068	<1	1.90	0.015	0.06	2.4	0.05	2.5	0.1	<0.05	6	<0.5
L7600 12575	Soil	0.061	17	30	0.57	202	0.077	<1	2.01	0.017	0.08	1.4	0.03	3.7	0.2	<0.05	6	<0.5
L7600 12600	Soil	0.062	12	33	0.56	271	0.089	1	2.06	0.016	0.06	0.5	0.03	2.4	0.2	<0.05	5	<0.5
L7600 12625	Soil	0.057	11	36	0.59	96	0.110	2	1.81	0.018	0.07	0.3	0.06	3.1	0.1	<0.05	6	<0.5
L7600 12650	Soil	0.062	11	35	0.54	153	0.103	1	1.83	0.019	0.06	0.4	0.03	3.1	0.1	<0.05	5	<0.5
L7600 12675	Soil	0.057	15	29	0.46	83	0.080	<1	1.51	0.011	0.06	0.3	0.03	2.6	0.1	<0.05	5	<0.5
L7600 12700	Soil	0.062	10	28	0.41	104	0.079	1	1.17	0.013	0.07	0.7	0.06	2.0	0.1	0.07	6	<0.5
L7600 12725	Soil	0.092	58	29	0.39	137	0.055	<1	1.64	0.024	0.08	0.6	0.06	2.5	0.2	0.11	6	0.6
L7600 12750	Soil	0.052	12	28	0.43	144	0.063	<1	1.67	0.021	0.08	0.4	0.04	2.3	0.1	0.07	5	<0.5
L7600 12775	Soil	0.038	13	31	0.50	96	0.125	<1	1.45	0.021	0.07	0.6	0.04	2.7	0.1	<0.05	4	<0.5
L7600 12825	Soil	0.057	12	32	0.45	93	0.085	<1	1.60	0.015	0.05	0.6	0.05	2.3	0.2	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7600 12850	Soil		1.4	20.1	7.5	34	0.2	12.4	4.0	132	1.67	99.0	1.5	2.8	0.4	13	0.4	0.6	1.3	39	0.10
L7600 12875	Soil		1.1	43.1	12.7	63	0.3	19.3	9.4	427	2.52	457.8	3.2	7.6	3.4	28	0.2	0.7	3.5	48	0.26
L7600 12900	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
L7600 12925	Soil		1.5	114.1	47.4	75	2.9	16.3	9.3	532	4.29	1383	8.9	206.6	8.5	57	0.2	4.9	170.1	43	0.28
L7600 12950	Soil		0.7	28.6	18.9	100	0.2	21.0	9.8	512	2.75	402.5	3.0	33.3	7.7	25	0.4	1.2	1.7	52	0.21
L7600 12975	Soil		1.1	24.1	32.7	107	0.6	16.8	8.3	610	3.43	1538	3.8	57.0	8.5	40	0.5	3.6	5.0	43	0.25
L7600 13000	Soil		2.4	34.0	51.5	109	0.8	20.9	10.1	770	4.71	2600	6.3	33.7	6.4	41	0.4	3.6	5.0	55	0.30
L7600 13025	Soil		1.4	23.5	46.6	78	1.0	8.8	7.5	474	5.24	6145	6.4	27.9	14.3	49	0.2	5.2	4.9	53	0.26
L7600 13050	Soil		2.4	37.8	26.1	82	0.6	18.2	13.5	1228	3.33	1275	4.9	16.3	0.8	26	0.3	1.7	3.4	62	0.20
L7600 13075	Soil		1.7	17.9	22.8	98	0.2	14.7	9.0	692	2.37	116.0	1.8	1.7	1.2	25	0.7	0.9	0.4	57	0.32
L7600 13100	Soil		1.0	27.0	16.6	78	0.1	21.7	10.4	417	2.58	166.9	3.0	5.5	4.4	20	0.3	0.7	0.5	60	0.26
L7600 13125	Soil		2.6	28.9	9.5	62	0.1	20.0	9.6	528	2.86	8.3	0.8	1.9	0.6	20	0.2	0.7	0.2	79	0.16
L7600 13150	Soil		1.4	32.8	7.8	71	<0.1	27.1	12.6	559	2.55	10.4	2.5	4.0	3.1	32	0.3	0.5	0.2	62	0.39
L7600 13175	Soil		1.6	34.1	9.9	75	<0.1	23.4	13.0	735	2.56	25.4	3.6	0.9	2.3	22	0.3	0.6	0.3	57	0.29
L7600 13200	Soil		0.9	24.1	6.1	56	<0.1	21.9	12.7	488	2.70	9.0	1.0	2.5	3.1	22	0.2	0.4	0.1	85	0.35
L7600 13225	Soil		1.5	29.4	6.3	60	<0.1	19.8	10.2	402	2.42	9.0	1.8	6.2	2.3	24	0.2	0.5	0.1	67	0.32
L7600 13250	Soil		1.1	25.3	45.7	133	0.2	20.1	13.3	790	2.97	37.8	2.9	2.1	4.8	26	0.5	0.7	0.1	75	0.35
L7600 13275	Soil		1.3	26.4	6.9	42	<0.1	14.0	5.9	265	2.04	6.8	1.2	1.4	0.7	16	0.2	0.5	0.2	50	0.15
L7600 13300	Soil		1.4	28.5	62.0	215	0.5	19.7	9.4	161	1.70	115.4	4.7	7.7	1.6	32	2.7	1.7	0.2	58	0.64
L7600 13325	Soil		0.7	27.1	181.1	470	1.0	18.0	12.3	589	3.13	140.0	3.7	11.3	8.0	26	5.4	2.8	0.2	76	0.31
L7600 13350	Soil		0.3	16.2	60.9	149	0.4	12.1	9.5	414	3.22	62.9	2.3	9.7	10.4	24	0.7	1.5	0.2	72	0.35
L7600 13375	Soil		0.2	16.6	57.2	141	0.4	10.3	9.5	409	2.78	16.9	2.0	2.7	8.5	27	0.5	1.0	0.7	57	0.40
L7600 13400	Soil		0.3	15.6	9.1	47	<0.1	13.2	10.1	211	3.66	6.6	2.8	4.9	8.2	33	0.1	0.4	0.3	61	0.42
L7600 13425	Soil		0.5	22.4	8.1	61	<0.1	14.1	11.7	353	3.29	5.9	2.6	2.3	10.2	36	0.2	0.5	0.3	82	0.45
L7600 13450	Soil		0.8	12.4	9.3	57	<0.1	13.3	12.4	518	3.52	7.2	1.7	3.0	6.3	31	0.1	0.6	0.3	81	0.36
L7600 13475	Soil		0.9	19.7	51.1	99	0.4	15.5	15.2	822	3.62	34.5	3.1	3.6	11.1	28	0.4	2.4	0.2	92	0.34
L7600 13500	Soil		0.9	17.3	40.0	108	0.3	14.4	13.2	633	3.40	21.5	2.8	3.3	12.3	27	0.3	4.6	0.2	84	0.38
L7800 12500	Soil		1.1	34.6	8.7	53	0.1	17.1	10.9	655	3.03	59.6	2.3	21.4	5.9	34	0.2	1.2	3.9	62	0.38
L7800 12525	Soil		2.4	25.5	31.4	76	0.3	14.2	21.3	3637	3.33	250.0	7.0	58.0	2.8	37	0.6	5.1	10.2	48	0.21
L7800 12550	Soil		0.9	22.8	22.9	50	0.3	15.0	6.5	179	2.30	191.1	4.3	54.2	10.0	26	0.1	6.5	6.3	47	0.21

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7600 12850	Soil	0.091	9	22	0.19	62	0.035	1	0.93	0.016	0.04	0.3	0.10	1.2	0.1	0.13	3	<0.5
L7600 12875	Soil	0.075	16	26	0.45	165	0.062	1	1.61	0.029	0.08	2.1	0.05	2.4	0.2	0.10	5	<0.5
L7600 12900	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
L7600 12925	Soil	0.067	33	24	0.43	314	0.030	2	2.29	0.056	0.35	0.7	0.10	3.7	0.4	0.73	6	1.2
L7600 12950	Soil	0.054	20	30	0.57	125	0.092	1	1.68	0.013	0.11	0.5	0.04	3.3	0.3	0.07	6	<0.5
L7600 12975	Soil	0.042	25	27	0.57	193	0.050	1	1.76	0.017	0.22	0.6	0.06	3.2	0.5	0.32	6	<0.5
L7600 13000	Soil	0.070	26	33	0.48	252	0.029	4	1.87	0.022	0.32	0.4	0.09	3.2	0.5	0.62	7	0.7
L7600 13025	Soil	0.063	23	18	0.42	292	0.070	1	1.26	0.031	0.46	0.4	0.03	3.9	0.6	0.83	5	<0.5
L7600 13050	Soil	0.124	19	29	0.39	199	0.031	1	1.80	0.017	0.12	0.1	0.06	1.5	0.3	0.27	6	<0.5
L7600 13075	Soil	0.075	8	24	0.42	185	0.046	2	1.23	0.016	0.07	0.3	0.08	1.8	0.1	0.07	5	<0.5
L7600 13100	Soil	0.070	18	32	0.52	124	0.108	2	1.48	0.021	0.10	0.5	0.06	3.3	0.2	0.07	5	<0.5
L7600 13125	Soil	0.071	7	31	0.41	151	0.096	<1	1.33	0.015	0.06	0.2	0.08	1.8	0.2	0.08	8	<0.5
L7600 13150	Soil	0.097	15	32	0.56	179	0.095	1	1.73	0.031	0.08	0.2	0.10	3.1	0.1	0.06	5	<0.5
L7600 13175	Soil	0.085	14	32	0.52	86	0.080	2	1.60	0.030	0.08	0.2	0.14	3.0	0.2	0.09	5	0.6
L7600 13200	Soil	0.082	10	33	0.62	221	0.165	<1	1.66	0.018	0.15	0.1	0.04	2.7	0.2	<0.05	5	<0.5
L7600 13225	Soil	0.076	10	28	0.51	208	0.116	1	1.43	0.029	0.11	0.2	0.12	3.0	0.2	0.08	4	<0.5
L7600 13250	Soil	0.065	16	31	0.61	221	0.103	1	1.85	0.018	0.08	0.1	0.05	3.9	0.2	<0.05	5	<0.5
L7600 13275	Soil	0.081	9	23	0.32	93	0.055	<1	1.34	0.022	0.05	0.2	0.11	1.8	0.1	0.10	5	<0.5
L7600 13300	Soil	0.080	17	30	0.54	208	0.059	<1	1.89	0.019	0.09	0.2	0.10	3.6	0.3	0.38	6	<0.5
L7600 13325	Soil	0.054	18	34	0.55	250	0.115	<1	1.68	0.014	0.17	0.2	0.09	5.4	0.4	<0.05	5	<0.5
L7600 13350	Soil	0.058	18	28	0.65	314	0.066	2	2.43	0.016	0.09	0.1	0.03	4.7	0.3	<0.05	7	<0.5
L7600 13375	Soil	0.063	18	23	0.66	388	0.034	1	2.51	0.018	0.07	0.1	0.02	4.6	0.2	<0.05	6	<0.5
L7600 13400	Soil	0.057	18	27	0.59	447	0.059	1	2.52	0.023	0.06	<0.1	0.02	4.9	0.2	<0.05	7	<0.5
L7600 13425	Soil	0.076	18	30	0.82	460	0.125	2	2.88	0.024	0.18	0.1	0.01	5.8	0.2	<0.05	7	<0.5
L7600 13450	Soil	0.093	11	28	0.78	283	0.097	2	2.65	0.023	0.09	0.2	0.03	4.1	0.2	<0.05	8	0.5
L7600 13475	Soil	0.087	19	32	0.76	232	0.097	2	2.49	0.017	0.11	0.2	0.03	5.5	0.3	<0.05	7	<0.5
L7600 13500	Soil	0.087	16	29	0.81	201	0.120	2	2.31	0.021	0.14	0.3	0.03	4.7	0.3	<0.05	6	<0.5
L7800 12500	Soil	0.092	18	27	0.74	229	0.104	2	2.09	0.020	0.13	1.5	0.03	3.6	0.2	<0.05	6	<0.5
L7800 12525	Soil	0.118	31	27	0.36	222	0.028	2	2.14	0.021	0.08	0.3	0.08	2.5	0.4	0.16	7	0.6
L7800 12550	Soil	0.052	24	27	0.49	131	0.057	2	2.14	0.014	0.09	0.3	0.04	3.6	0.2	0.07	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7800 12575	Soil		0.9	32.5	27.0	65	0.4	15.3	5.8	328	3.41	239.8	8.0	96.1	13.8	50	0.2	8.0	23.2	39	0.22
L7800 12600	Soil		1.3	58.4	27.9	81	0.6	17.4	7.0	198	3.49	273.8	11.5	57.2	15.0	31	0.2	4.1	6.4	56	0.18
L7800 12625	Soil		1.1	46.7	18.0	74	0.5	11.9	5.2	193	3.19	377.0	7.9	125.6	17.3	56	0.2	5.7	6.1	35	0.19
L7800 12650	Soil		1.0	41.8	27.4	75	0.4	16.2	6.9	326	3.64	287.4	5.7	86.8	15.2	48	0.2	4.9	6.3	44	0.20
L7800 12675	Soil		1.4	46.5	20.2	47	0.4	12.5	4.2	149	2.32	141.0	4.8	132.8	11.9	28	0.2	7.5	8.5	39	0.22
L7800 12700	Soil		2.8	144.3	70.7	37	1.7	12.6	3.4	114	5.13	692.9	15.5	261.8	13.8	45	0.2	12.8	23.4	52	0.16
L7800 12725	Soil		2.6	39.0	52.6	93	1.0	22.6	12.2	1016	4.61	843.5	12.2	103.4	4.0	53	0.3	12.4	9.3	66	0.29
L7800 12750	Soil		1.4	41.3	33.7	81	0.6	21.5	8.3	352	4.26	1101	10.5	48.6	7.0	29	0.2	5.4	6.5	58	0.21
L7800 12775	Soil		0.9	33.2	26.3	63	0.5	13.4	6.8	333	3.65	709.2	3.4	34.5	12.9	41	0.2	3.9	6.5	39	0.21
L7800 12800	Soil		0.6	32.6	26.9	53	0.7	12.3	6.5	377	3.39	1154	3.9	48.7	12.4	57	0.1	10.8	16.7	38	0.26
L7800 12825	Soil		1.4	30.8	21.9	71	0.5	15.5	9.6	1366	3.07	940.5	4.3	30.0	0.8	29	0.7	3.9	8.2	47	0.18
L7800 12850	Soil		1.5	46.7	40.7	95	0.9	19.8	9.4	648	4.32	2433	7.9	59.6	4.0	50	0.3	10.9	15.3	50	0.22
L7800 12875	Soil		0.7	30.3	16.1	76	0.4	17.5	8.3	435	2.98	574.0	4.1	26.4	9.8	29	0.3	2.9	4.1	45	0.29
L7800 12900	Soil		0.8	25.9	15.2	90	0.4	15.3	8.3	478	3.05	357.5	3.7	309.6	10.5	32	0.4	2.1	2.7	45	0.33
L7800 12925	Soil		0.9	26.1	16.8	92	0.4	21.9	10.0	554	3.09	335.4	5.0	50.6	8.0	30	0.5	3.0	3.7	61	0.34
L7800 12950	Soil		1.2	41.1	19.0	97	0.4	18.3	8.5	378	3.21	339.8	5.4	42.9	9.1	41	0.4	3.5	5.2	50	0.28
L7800 12975	Soil		1.5	40.4	51.6	123	1.8	21.7	10.6	750	4.40	1820	6.8	48.7	5.6	36	0.3	8.1	9.3	63	0.30
L7800 13000	Soil		1.9	31.0	44.5	110	0.7	17.8	8.5	436	4.24	1158	5.0	69.8	9.2	24	0.5	10.3	2.6	48	0.24
L7800 13025	Soil		2.1	26.6	50.4	212	0.9	21.8	11.0	762	3.71	642.9	6.7	25.7	7.1	38	1.2	5.0	1.7	55	0.49
L7800 13050	Soil		0.7	19.9	55.2	190	0.4	14.9	10.3	489	2.77	193.4	4.0	6.1	9.8	34	1.0	1.7	0.4	53	0.44
L7800 13075	Soil		1.0	23.4	95.8	229	0.9	15.9	9.3	552	3.15	55.0	3.7	1.9	5.3	34	0.8	1.4	0.3	73	0.44
L7800 13100	Soil		0.7	18.4	9.4	73	<0.1	17.8	8.8	375	2.61	11.9	2.3	3.1	5.9	28	0.2	0.6	0.2	55	0.35
L7800 13125	Soil		0.8	29.9	9.0	54	0.1	15.7	9.1	354	2.90	8.3	3.8	1.7	5.9	70	0.1	0.6	0.2	66	0.44
L7800 13150	Soil		0.6	25.2	9.4	58	0.1	17.6	11.5	419	3.13	9.1	3.6	2.8	6.7	95	0.1	0.7	0.2	75	0.52
L7800 13175	Soil		1.8	27.8	33.3	136	0.6	22.9	15.5	1667	4.63	28.3	5.9	1.8	11.2	54	1.0	1.7	0.2	113	0.67
L7800 13200	Soil		1.9	18.5	14.7	592	0.7	11.4	15.1	1352	4.72	5.0	6.6	0.6	7.5	39	3.3	1.1	0.1	106	0.84
L7800 13225	Soil		0.8	33.2	12.5	75	0.1	43.1	13.5	564	3.67	8.0	3.3	2.7	7.7	37	0.1	0.8	0.1	104	0.44
L7800 13250	Soil		0.6	24.5	9.5	60	<0.1	19.1	10.6	320	2.89	10.2	2.9	3.8	6.6	29	0.1	0.8	0.1	74	0.34
L7800 13275	Soil		0.7	28.1	11.5	62	<0.1	23.0	10.3	398	2.87	11.7	2.2	2.9	6.6	27	0.2	0.7	0.2	73	0.33
L7800 13300	Soil		0.6	18.3	14.5	68	<0.1	18.7	8.9	273	2.43	12.0	1.8	2.2	6.5	25	0.3	0.7	0.2	67	0.36

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7800 12575	Soil	0.061	32	23	0.49	188	0.048	2	1.81	0.014	0.14	0.4	0.05	3.4	0.2	0.06	6	0.6
L7800 12600	Soil	0.068	49	30	0.62	149	0.069	2	2.42	0.012	0.13	0.2	0.07	5.1	0.3	<0.05	8	0.7
L7800 12625	Soil	0.059	41	22	0.45	168	0.044	2	1.94	0.010	0.12	0.2	0.05	3.6	0.3	0.05	6	0.5
L7800 12650	Soil	0.061	32	25	0.56	172	0.061	3	2.03	0.018	0.21	0.4	0.03	3.6	0.3	0.17	7	<0.5
L7800 12675	Soil	0.066	34	23	0.44	119	0.059	2	1.47	0.013	0.11	0.2	0.04	3.1	0.3	<0.05	5	<0.5
L7800 12700	Soil	0.144	59	27	0.28	203	0.011	4	2.67	0.009	0.11	0.4	0.18	4.3	0.6	0.16	8	0.9
L7800 12725	Soil	0.150	44	40	0.51	212	0.029	5	2.80	0.018	0.16	0.4	0.10	2.9	0.5	0.17	9	1.1
L7800 12750	Soil	0.099	37	33	0.63	165	0.036	3	2.64	0.024	0.12	0.3	0.06	4.1	0.3	0.13	8	0.5
L7800 12775	Soil	0.067	25	22	0.37	178	0.059	2	1.40	0.027	0.33	0.7	0.03	2.6	0.4	0.48	5	0.6
L7800 12800	Soil	0.050	26	21	0.41	259	0.050	<1	1.74	0.034	0.30	0.7	0.03	3.1	0.4	0.40	6	<0.5
L7800 12825	Soil	0.105	25	26	0.34	241	0.017	3	2.30	0.019	0.13	0.2	0.06	1.4	0.4	0.15	7	0.7
L7800 12850	Soil	0.113	42	31	0.45	311	0.025	3	3.15	0.022	0.22	0.3	0.05	3.4	0.6	0.21	9	0.6
L7800 12875	Soil	0.060	21	26	0.49	127	0.081	1	1.70	0.021	0.16	0.4	0.03	3.4	0.2	0.09	6	<0.5
L7800 12900	Soil	0.070	22	24	0.45	142	0.085	2	1.42	0.022	0.18	0.5	0.02	3.1	0.2	0.09	5	<0.5
L7800 12925	Soil	0.064	28	32	0.64	183	0.098	2	2.11	0.023	0.13	0.3	0.05	4.3	0.3	<0.05	6	<0.5
L7800 12950	Soil	0.097	29	29	0.59	180	0.084	1	2.12	0.020	0.16	0.3	0.04	3.8	0.3	0.06	7	<0.5
L7800 12975	Soil	0.091	29	35	0.59	301	0.030	1	3.27	0.019	0.22	0.2	0.07	4.2	0.5	0.13	9	0.5
L7800 13000	Soil	0.059	27	28	0.49	166	0.053	<1	2.05	0.014	0.18	0.3	0.10	3.5	0.5	0.13	6	<0.5
L7800 13025	Soil	0.082	33	31	0.56	206	0.055	2	2.22	0.024	0.16	0.4	0.08	4.4	0.4	<0.05	7	0.7
L7800 13050	Soil	0.067	24	26	0.71	448	0.081	<1	2.50	0.021	0.14	0.2	0.04	4.5	0.3	<0.05	7	<0.5
L7800 13075	Soil	0.111	20	33	0.68	315	0.074	<1	2.80	0.018	0.09	0.1	0.04	6.3	0.2	<0.05	8	<0.5
L7800 13100	Soil	0.074	14	28	0.63	258	0.103	<1	2.21	0.020	0.10	<0.1	0.04	3.0	0.2	<0.05	6	0.5
L7800 13125	Soil	0.067	23	30	0.75	416	0.057	<1	3.47	0.018	0.11	0.2	0.02	4.3	0.2	<0.05	7	<0.5
L7800 13150	Soil	0.067	17	32	0.78	509	0.092	<1	3.00	0.019	0.17	0.1	0.04	5.3	0.3	<0.05	8	<0.5
L7800 13175	Soil	0.105	26	43	0.87	432	0.135	<1	3.33	0.026	0.23	0.3	0.09	7.9	0.4	<0.05	8	<0.5
L7800 13200	Soil	0.152	17	35	0.96	242	0.155	<1	1.82	0.019	0.09	0.1	0.06	4.9	0.2	0.14	7	<0.5
L7800 13225	Soil	0.089	19	59	0.87	334	0.184	2	2.20	0.017	0.19	0.2	0.02	6.9	0.3	<0.05	7	<0.5
L7800 13250	Soil	0.074	18	34	0.68	192	0.119	2	1.98	0.017	0.08	0.2	0.03	5.3	0.2	<0.05	6	<0.5
L7800 13275	Soil	0.077	16	35	0.65	202	0.107	2	2.35	0.013	0.09	0.2	0.02	4.7	0.2	<0.05	6	<0.5
L7800 13300	Soil	0.078	15	32	0.61	171	0.109	2	1.92	0.013	0.09	0.3	0.03	3.7	0.2	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7800 13325	Soil		0.8	21.1	38.1	94	0.8	8.0	2.6	64	1.04	14.1	22.3	6.0	5.8	30	0.7	2.2	0.2	33	0.52
L7800 13350	Soil		1.7	24.1	7.7	41	<0.1	14.4	5.8	206	2.25	5.6	3.1	1.5	1.3	19	0.1	0.6	0.3	56	0.21
L7800 13375	Soil		1.7	28.1	7.4	66	<0.1	25.6	13.9	612	3.05	7.8	2.2	6.3	3.7	20	0.3	0.6	0.2	87	0.31
L7800 13400	Soil		1.9	28.8	7.0	49	<0.1	16.0	7.5	280	2.30	5.9	1.5	<0.5	1.9	18	0.2	0.6	0.2	59	0.18
L7800 13425	Soil		1.4	20.1	8.1	48	<0.1	14.2	6.8	270	2.42	6.2	1.0	2.2	0.9	14	0.3	0.5	0.3	78	0.15
L7800 13450	Soil		0.5	26.0	6.7	56	<0.1	19.5	10.2	304	2.54	3.6	1.2	1.3	5.0	35	0.2	0.6	0.3	79	0.40
L7800 13475	Soil		0.8	32.7	6.9	58	<0.1	19.1	10.9	457	3.22	7.5	1.5	2.7	7.0	43	<0.1	0.4	0.4	94	0.45
L7800 13500	Soil		1.2	31.6	7.2	55	<0.1	21.3	14.6	639	3.62	9.4	2.2	4.8	6.5	41	0.1	0.4	0.4	89	0.45
L8000 12450	Soil		1.9	35.4	9.5	66	0.2	21.0	12.4	352	3.07	54.6	3.5	187.8	7.2	25	0.2	1.2	2.0	81	0.36
L8000 12475	Soil		1.0	21.4	9.0	56	0.1	14.6	7.4	302	2.39	83.0	2.2	46.8	6.6	21	0.3	1.6	1.8	49	0.28
L8000 12500	Soil		2.8	23.1	12.3	52	0.1	13.2	11.1	1514	2.74	98.3	2.8	26.1	2.6	17	0.3	1.6	2.2	68	0.12
L8000 12525	Soil		0.9	24.5	8.2	62	0.1	24.2	12.6	544	2.64	57.2	2.1	193.6	5.0	19	0.4	1.0	0.8	60	0.24
L8000 12550	Soil		2.0	25.8	10.8	59	0.3	18.5	7.3	380	3.01	69.8	1.4	2.1	1.7	17	0.3	1.1	0.8	70	0.15
L8000 12575	Soil		1.6	26.5	8.2	47	0.1	19.5	9.6	340	2.29	58.0	1.3	5.6	3.9	17	0.3	1.1	0.7	65	0.21
L8000 12600	Soil		2.9	47.1	12.7	72	0.4	30.9	12.5	560	3.40	130.2	4.6	11.7	3.1	25	0.3	2.5	1.7	77	0.26
L8000 12625	Soil		1.9	34.9	16.2	70	0.1	21.6	10.0	379	3.23	249.4	3.0	12.7	5.6	18	0.3	2.9	2.9	62	0.18
L8000 12650	Soil		1.3	38.0	17.0	69	0.4	17.4	9.5	537	2.95	113.6	4.3	15.7	3.4	30	0.3	2.4	3.2	57	0.31
L8000 12675	Soil		1.0	22.1	7.7	41	<0.1	11.8	4.1	171	1.82	12.6	1.9	5.2	2.5	16	0.1	0.6	0.4	40	0.16
L8000 12700	Soil		2.0	46.7	24.6	88	0.8	22.4	12.4	973	3.91	713.8	7.6	77.7	4.4	40	0.3	4.8	9.8	62	0.38
L8000 12725	Soil		1.6	25.9	14.4	66	0.4	13.2	8.0	644	2.21	275.9	4.7	15.3	1.3	39	0.7	1.9	2.6	41	0.39
L8000 12750	Soil		1.5	33.8	21.7	106	0.2	21.4	10.3	553	3.77	422.6	5.1	23.5	6.3	18	0.5	2.8	4.1	66	0.16
L8000 12775	Soil		1.7	38.3	26.6	107	0.3	23.4	15.2	1509	3.48	567.0	6.4	39.2	3.1	28	0.4	3.0	5.8	66	0.21
L8000 12800	Soil		2.2	47.2	27.5	126	0.8	27.9	12.0	1066	3.80	732.1	6.3	50.2	3.2	37	0.6	4.3	7.6	67	0.37
L8000 12825	Soil		2.0	39.1	32.1	75	1.1	16.4	15.9	1629	4.67	1166	8.9	52.8	5.5	32	0.4	4.6	8.9	57	0.27
L8000 12850	Soil		1.6	37.9	41.1	120	2.0	15.1	11.1	1646	3.35	731.9	4.6	117.1	2.8	26	2.9	10.0	29.8	47	0.19
L8000 12875	Soil		1.3	57.0	48.8	110	1.0	15.6	8.5	621	2.85	602.4	5.4	65.4	3.9	30	0.7	7.3	9.8	44	0.30
L8000 12900	Soil		0.8	36.4	26.1	147	0.5	17.7	8.1	391	2.81	377.0	4.2	53.9	7.3	24	0.4	6.2	3.1	52	0.29
L8000 12925	Soil		1.2	12.2	17.4	133	0.3	12.1	5.7	663	2.23	134.8	3.0	6.9	0.9	24	2.4	1.8	0.8	44	0.26
L8000 12950	Soil		0.5	8.8	35.4	140	0.2	10.4	7.7	394	2.25	63.2	3.0	11.3	12.5	22	0.6	1.7	0.4	35	0.32
L8000 12975	Soil		1.0	34.4	120.9	264	3.6	14.2	7.3	386	4.03	535.5	6.0	47.4	11.2	22	0.8	13.9	3.5	49	0.28

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7800 13325	Soil	0.084	33	23	0.18	220	0.008	6	1.80	0.009	0.13	0.2	0.13	6.4	0.3	0.13	4	0.5
L7800 13350	Soil	0.106	9	23	0.31	77	0.054	2	1.08	0.021	0.06	0.2	0.16	2.2	0.2	0.14	4	0.7
L7800 13375	Soil	0.088	11	35	0.61	127	0.105	2	2.02	0.013	0.08	0.3	0.05	3.0	0.2	0.06	6	<0.5
L7800 13400	Soil	0.094	10	25	0.43	81	0.074	2	1.50	0.032	0.07	0.3	0.09	2.5	0.2	0.10	5	<0.5
L7800 13425	Soil	0.072	8	30	0.30	68	0.076	2	1.60	0.009	0.04	0.2	0.06	2.2	0.1	<0.05	6	<0.5
L7800 13450	Soil	0.080	13	37	0.63	160	0.113	1	1.88	0.015	0.10	0.3	0.03	4.6	0.2	<0.05	5	<0.5
L7800 13475	Soil	0.097	17	40	0.67	245	0.140	2	2.21	0.017	0.15	0.2	0.02	5.2	0.2	<0.05	6	<0.5
L7800 13500	Soil	0.099	18	40	0.71	234	0.143	2	2.26	0.018	0.13	0.2	0.02	5.1	0.2	<0.05	6	<0.5
L8000 12450	Soil	0.096	20	37	0.84	210	0.140	2	2.42	0.013	0.14	2.3	0.03	4.9	0.3	<0.05	7	<0.5
L8000 12475	Soil	0.074	20	27	0.51	104	0.090	1	1.54	0.011	0.09	0.9	0.02	3.0	0.2	<0.05	5	<0.5
L8000 12500	Soil	0.087	16	29	0.39	132	0.073	2	1.57	0.009	0.09	0.5	0.04	3.4	0.2	0.05	7	<0.5
L8000 12525	Soil	0.066	15	31	0.58	106	0.097	2	1.94	0.012	0.07	0.6	0.03	3.4	0.1	<0.05	5	<0.5
L8000 12550	Soil	0.060	10	29	0.41	95	0.079	2	1.62	0.014	0.07	0.3	0.07	2.4	0.2	0.06	8	<0.5
L8000 12575	Soil	0.066	12	28	0.43	80	0.091	2	1.32	0.013	0.08	0.5	0.03	2.6	0.2	<0.05	5	<0.5
L8000 12600	Soil	0.089	21	45	0.63	142	0.067	2	2.20	0.014	0.09	0.4	0.05	4.2	0.2	0.07	7	0.8
L8000 12625	Soil	0.070	16	32	0.49	113	0.060	2	1.96	0.009	0.07	0.4	0.03	3.1	0.2	<0.05	7	<0.5
L8000 12650	Soil	0.093	25	29	0.49	150	0.051	2	1.83	0.015	0.09	0.3	0.07	3.1	0.2	0.07	6	<0.5
L8000 12675	Soil	0.079	11	19	0.30	118	0.051	2	1.36	0.027	0.07	0.5	0.11	2.3	0.2	0.14	4	0.6
L8000 12700	Soil	0.112	32	34	0.59	250	0.029	2	2.79	0.014	0.09	0.3	0.06	4.0	0.3	0.11	8	0.5
L8000 12725	Soil	0.127	28	23	0.32	186	0.029	2	1.45	0.024	0.08	0.3	0.12	2.1	0.2	0.14	5	<0.5
L8000 12750	Soil	0.053	33	36	0.59	135	0.048	3	2.92	0.009	0.08	0.2	0.05	4.3	0.3	<0.05	9	0.6
L8000 12775	Soil	0.095	26	37	0.54	206	0.036	2	2.41	0.012	0.09	0.2	0.06	3.6	0.3	0.09	8	<0.5
L8000 12800	Soil	0.124	32	38	0.55	246	0.030	2	2.52	0.013	0.11	0.3	0.06	3.7	0.3	0.15	8	0.5
L8000 12825	Soil	0.134	35	27	0.36	218	0.016	2	2.35	0.011	0.09	0.3	0.09	3.9	0.4	0.13	6	0.7
L8000 12850	Soil	0.115	25	26	0.39	237	0.018	3	2.15	0.009	0.10	0.2	0.13	2.5	0.6	0.12	7	<0.5
L8000 12875	Soil	0.084	26	25	0.41	159	0.037	2	1.77	0.013	0.10	0.2	0.09	2.7	0.4	0.10	5	<0.5
L8000 12900	Soil	0.070	21	28	0.53	129	0.068	2	2.03	0.012	0.10	0.3	0.07	3.6	0.3	<0.05	6	<0.5
L8000 12925	Soil	0.092	17	24	0.41	186	0.029	1	1.70	0.013	0.05	0.3	0.05	1.9	0.3	0.10	7	<0.5
L8000 12950	Soil	0.056	25	24	0.66	174	0.069	<1	2.07	0.011	0.21	0.2	0.04	4.7	0.5	<0.05	8	<0.5
L8000 12975	Soil	0.073	23	27	0.54	158	0.053	2	2.11	0.011	0.15	0.3	0.11	4.3	0.5	<0.05	7	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L8000 13000	Soil		0.6	25.8	48.4	235	0.8	13.7	7.1	523	2.60	196.3	8.2	22.6	9.9	27	1.1	3.2	1.4	47	0.39
L8000 13025	Soil		0.8	24.7	74.3	217	2.7	17.2	11.7	868	3.27	128.4	5.0	8.2	7.0	27	0.8	4.0	1.0	67	0.29
L8000 13050	Soil		0.7	21.8	55.4	131	0.5	18.3	9.1	725	2.92	16.0	6.5	3.0	9.3	35	0.5	1.1	0.3	62	0.35
L8000 13075	Soil		0.6	13.6	86.2	164	0.5	13.3	8.9	318	3.91	100.5	4.8	4.7	11.0	21	0.4	1.7	0.3	53	0.25
L8000 13100	Soil		1.5	29.6	60.4	232	0.8	23.7	11.7	319	3.70	68.1	9.5	6.4	10.3	29	1.2	1.8	0.3	82	0.33
L8000 13125	Soil		1.3	21.3	90.2	125	0.7	17.1	9.3	333	2.45	18.2	8.0	11.4	7.3	38	0.5	1.9	0.3	60	0.34
L8000 13150	Soil		0.7	25.7	52.0	151	0.3	19.5	11.6	864	3.25	18.7	5.2	5.9	8.4	40	0.8	1.7	0.2	74	0.47
L8000 13175	Soil		1.5	28.4	8.1	53	<0.1	19.1	8.1	315	2.30	7.1	1.2	1.6	1.3	23	0.2	0.7	0.2	50	0.23
L8000 13200	Soil		1.9	32.0	16.3	78	0.2	25.3	15.8	1509	3.17	20.1	6.7	2.8	2.4	53	0.8	0.9	0.3	66	0.66
L8000 13225	Soil		0.9	15.2	22.5	92	<0.1	15.9	10.5	598	3.03	15.9	2.1	7.4	4.5	37	0.5	0.7	0.3	64	0.25
L8000 13250	Soil		1.2	27.3	12.0	70	0.1	21.5	12.4	984	3.26	16.2	6.3	4.1	6.3	55	0.2	0.8	0.3	87	0.70
L8000 13275	Soil		1.5	25.8	8.4	65	<0.1	19.6	8.2	522	2.27	7.0	3.1	3.3	1.5	34	0.7	0.6	0.2	53	0.44
L8000 13300	Soil		1.0	22.5	10.7	64	<0.1	17.8	9.8	404	2.86	13.1	3.5	4.3	7.8	49	0.2	0.8	0.3	78	0.45
L8000 13325	Soil		1.5	22.4	12.8	63	0.1	20.3	11.7	464	3.20	24.8	3.7	4.4	7.2	33	0.2	1.6	0.3	80	0.33
L8000 13350	Soil		3.0	42.3	14.2	106	0.2	27.6	10.9	542	3.11	25.6	4.5	3.1	5.8	47	0.4	1.6	0.4	76	0.38
L8000 13375	Soil		1.7	29.3	15.5	104	0.1	29.4	11.7	544	3.24	22.6	2.5	4.8	4.5	25	0.4	1.2	0.3	77	0.25
L8000 13400	Soil		2.6	30.8	10.7	69	0.3	21.7	8.9	491	3.02	15.4	2.1	2.7	0.7	35	0.5	1.1	0.3	82	0.30
L8000 13425	Soil		1.4	23.3	6.3	38	<0.1	10.9	4.6	147	1.86	3.7	1.2	1.0	1.4	17	0.1	0.6	0.2	56	0.18
L8000 13450	Soil		1.5	27.2	7.1	55	<0.1	15.5	6.5	271	2.18	6.1	1.0	2.4	1.1	20	0.1	0.7	0.2	51	0.16
L8000 13475	Soil		1.2	21.7	7.0	49	<0.1	15.4	7.8	336	2.60	5.1	1.2	2.1	1.1	34	0.3	0.5	0.2	76	0.20
L8000 13500	Soil		2.0	28.7	7.7	56	<0.1	17.6	8.4	352	2.48	8.3	2.8	2.4	2.0	25	0.2	0.6	0.2	63	0.28
L8200 12575	Soil		1.9	35.8	28.7	76	0.6	18.4	10.9	743	3.35	483.6	8.4	32.0	1.8	29	0.3	3.5	2.9	62	0.27
L8200 12600	Soil		1.4	24.7	24.5	84	0.2	17.0	9.4	586	3.06	550.3	3.7	17.1	3.7	22	0.3	2.5	2.5	58	0.21
L8200 12625	Soil		1.4	28.3	27.8	111	0.2	16.1	8.3	555	2.78	646.8	3.8	17.7	6.0	23	0.5	3.6	1.8	48	0.22
L8200 12650	Soil		1.0	23.8	17.0	94	0.4	16.1	7.7	514	2.61	341.6	4.2	19.3	8.2	24	0.3	2.0	1.9	46	0.29
L8200 12675	Soil		1.3	23.6	23.3	93	0.4	15.7	5.6	263	2.60	412.0	4.7	20.6	9.2	21	0.2	2.5	2.2	44	0.32
L8200 12700	Soil		1.8	26.0	32.8	119	0.5	14.9	7.1	758	2.79	522.3	6.4	18.0	3.2	30	0.8	2.7	3.2	40	0.30
L8200 12725	Soil		2.3	39.6	34.9	169	0.5	20.8	10.3	1448	3.35	657.8	9.6	21.7	2.4	40	0.8	3.2	3.4	51	0.47
L8200 12750	Soil		1.6	41.6	36.4	129	0.8	15.4	9.9	1426	2.69	445.8	11.7	24.9	2.3	42	1.1	3.7	3.2	47	0.46
L8200 12775	Soil		1.2	24.3	35.4	107	0.5	10.6	9.7	1541	2.37	424.3	6.5	20.7	6.1	24	0.9	3.7	2.4	35	0.30

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L8000 13000	Soil	0.072	28	25	0.57	190	0.063	3	1.92	0.013	0.13	0.2	0.07	4.6	0.3	<0.05	6	<0.5
L8000 13025	Soil	0.074	20	32	0.70	226	0.069	2	2.45	0.012	0.09	0.2	0.05	4.6	0.3	<0.05	7	<0.5
L8000 13050	Soil	0.077	33	33	0.75	192	0.072	<1	2.55	0.012	0.10	0.2	0.04	5.8	0.3	<0.05	8	<0.5
L8000 13075	Soil	0.077	25	28	0.54	156	0.045	1	2.12	0.011	0.08	0.1	0.04	5.1	0.3	<0.05	7	<0.5
L8000 13100	Soil	0.080	38	41	0.80	228	0.104	1	2.68	0.014	0.12	0.2	0.05	6.8	0.4	<0.05	8	0.8
L8000 13125	Soil	0.081	31	33	0.74	144	0.065	2	2.43	0.012	0.11	0.4	0.05	5.3	0.4	<0.05	8	<0.5
L8000 13150	Soil	0.096	24	31	0.65	192	0.114	1	1.72	0.017	0.16	0.3	0.03	6.5	0.3	<0.05	6	<0.5
L8000 13175	Soil	0.076	12	26	0.45	86	0.057	2	1.51	0.039	0.07	0.1	0.09	2.7	0.2	0.08	5	0.6
L8000 13200	Soil	0.133	40	32	0.60	331	0.044	3	2.83	0.021	0.09	0.3	0.10	3.7	0.2	0.13	8	<0.5
L8000 13225	Soil	0.068	14	29	0.71	170	0.086	2	2.34	0.013	0.11	0.4	0.03	3.7	0.3	<0.05	7	<0.5
L8000 13250	Soil	0.083	26	35	0.70	316	0.109	3	2.45	0.023	0.11	0.3	0.04	6.1	0.3	0.06	7	<0.5
L8000 13275	Soil	0.091	12	28	0.47	173	0.058	3	1.31	0.045	0.07	0.2	0.10	2.4	0.2	0.11	4	0.6
L8000 13300	Soil	0.066	19	32	0.71	275	0.116	2	2.16	0.025	0.12	0.7	0.02	4.4	0.3	<0.05	6	<0.5
L8000 13325	Soil	0.072	19	34	0.68	240	0.104	2	2.38	0.017	0.11	0.2	0.04	4.6	0.3	<0.05	7	<0.5
L8000 13350	Soil	0.094	23	35	0.71	230	0.097	1	2.18	0.016	0.14	0.5	0.05	4.6	0.3	<0.05	6	<0.5
L8000 13375	Soil	0.080	15	35	0.61	144	0.088	2	1.99	0.014	0.10	0.6	0.03	3.3	0.2	<0.05	7	<0.5
L8000 13400	Soil	0.121	10	30	0.49	198	0.059	2	1.91	0.021	0.09	0.2	0.13	2.0	0.2	0.14	7	0.6
L8000 13425	Soil	0.096	7	20	0.20	93	0.069	2	1.15	0.027	0.07	0.2	0.13	2.1	0.1	0.17	5	0.7
L8000 13450	Soil	0.088	9	24	0.37	93	0.060	2	1.65	0.032	0.06	0.2	0.06	2.3	0.1	0.10	5	0.7
L8000 13475	Soil	0.076	8	28	0.43	136	0.076	<1	1.64	0.016	0.05	0.2	0.06	2.1	0.2	0.07	6	<0.5
L8000 13500	Soil	0.094	9	26	0.47	125	0.075	2	1.53	0.041	0.09	0.1	0.17	2.7	0.2	0.13	5	0.7
L8200 12575	Soil	0.091	43	34	0.50	145	0.037	1	2.03	0.012	0.07	0.3	0.04	2.9	0.2	0.11	7	0.6
L8200 12600	Soil	0.056	17	30	0.53	124	0.048	<1	1.77	0.010	0.08	0.4	0.03	2.7	0.2	0.06	7	<0.5
L8200 12625	Soil	0.054	22	25	0.49	180	0.055	<1	1.79	0.010	0.13	0.6	0.03	3.1	0.3	<0.05	6	<0.5
L8200 12650	Soil	0.067	23	24	0.52	134	0.076	<1	1.65	0.015	0.12	1.0	0.03	3.5	0.3	<0.05	5	<0.5
L8200 12675	Soil	0.069	28	24	0.47	130	0.047	1	1.77	0.010	0.12	0.5	0.03	3.4	0.3	0.05	6	<0.5
L8200 12700	Soil	0.102	40	22	0.37	204	0.017	2	1.82	0.010	0.08	0.3	0.05	2.6	0.3	0.09	5	<0.5
L8200 12725	Soil	0.121	29	31	0.49	227	0.023	2	2.13	0.013	0.08	0.3	0.05	3.0	0.3	0.12	6	0.6
L8200 12750	Soil	0.148	41	28	0.43	202	0.030	2	1.92	0.016	0.08	0.3	0.09	3.2	0.4	0.17	6	0.7
L8200 12775	Soil	0.076	28	19	0.37	152	0.024	1	1.56	0.010	0.07	0.2	0.05	2.7	0.4	0.07	5	0.6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

		Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L8200 12800	Soil			1.0	14.9	28.0	132	0.4	10.4	7.2	413	2.84	351.2	4.0	15.7	11.8	24	0.7	2.6	2.0	39	0.31
L8200 12825	Soil			0.8	17.5	45.2	149	0.7	13.2	5.3	295	2.64	426.1	4.0	49.6	8.9	21	0.5	3.5	3.3	39	0.23
L8200 12850	Soil			0.7	27.5	39.1	199	0.6	14.6	6.9	298	2.36	140.3	8.7	37.0	7.3	25	1.0	2.5	3.8	52	0.32
L8200 12875	Soil			0.8	24.1	34.7	165	0.3	14.4	9.9	533	3.04	194.9	4.9	27.9	10.0	27	0.9	2.2	1.1	54	0.39
L8200 12900	Soil			1.1	29.8	36.9	251	0.9	15.4	10.1	886	3.97	373.0	6.1	64.5	11.7	25	1.5	5.3	4.2	55	0.32
L8200 12925	Soil			2.7	30.7	69.4	156	0.6	15.5	19.1	4248	5.17	494.8	11.7	21.4	2.5	24	0.9	3.8	3.5	69	0.21
L8200 12950	Soil			1.3	23.7	40.0	247	0.2	18.4	11.4	811	3.73	298.2	1.7	30.8	3.8	30	4.6	3.8	5.7	68	0.29
L8200 12975	Soil			1.3	23.6	49.8	199	0.3	18.7	8.8	508	3.80	436.9	1.7	18.6	4.6	23	1.3	4.3	5.4	69	0.21
L8200 13000	Soil			3.4	13.7	36.3	145	0.6	11.0	35.6	5734	5.01	317.8	5.2	12.4	3.6	26	2.4	2.7	3.6	64	0.35
L8200 13025	Soil			0.8	19.7	38.0	119	0.5	15.0	6.9	248	3.24	484.2	4.1	38.5	10.9	17	0.4	3.3	4.5	58	0.23
L8200 13050	Soil			0.9	13.3	43.7	114	0.3	12.6	8.2	359	2.74	121.4	5.4	10.3	11.2	20	0.5	1.7	0.7	50	0.24
L8200 13075	Soil			0.7	21.0	54.3	204	0.7	12.7	8.5	456	2.35	199.3	6.0	14.5	11.3	19	1.5	2.1	0.9	45	0.28
L8200 13100	Soil			0.6	24.1	51.1	233	1.3	14.8	9.1	551	2.60	119.6	4.7	14.2	10.4	23	1.0	2.4	1.2	55	0.29
L8200 13125	Soil			1.1	13.3	49.7	155	0.5	14.3	8.9	217	3.38	121.0	3.9	7.1	9.6	43	1.0	1.2	0.3	47	0.27
L8200 13150	Soil			3.1	20.0	27.0	59	0.3	13.4	13.4	524	4.92	101.5	8.0	4.0	4.1	36	0.4	1.1	0.3	97	0.54
L8200 13175	Soil			0.8	17.2	41.7	86	0.3	14.5	7.6	178	2.37	48.9	5.4	2.7	12.0	24	0.4	1.3	0.3	47	0.25
L8200 13200	Soil			0.7	12.9	37.9	76	0.3	12.6	7.3	218	2.36	42.5	2.9	8.7	8.2	30	0.2	1.2	0.3	53	0.28
L8200 13225	Soil			1.1	22.6	20.3	56	0.3	19.2	9.4	268	2.76	22.8	5.8	2.3	7.8	35	0.2	1.1	0.3	67	0.38
L8200 13250	Soil			1.1	21.3	20.7	63	0.1	20.1	9.3	335	2.43	12.5	3.7	3.2	8.1	27	0.2	0.9	0.2	60	0.39
L8200 13275	Soil			2.7	21.8	29.7	82	0.3	18.9	15.3	1445	3.58	53.6	4.3	5.2	5.0	36	0.6	1.7	0.3	51	0.55
L8200 13300	Soil			1.8	31.0	14.7	70	0.2	21.1	11.2	724	3.01	13.9	5.2	3.8	7.9	40	0.3	1.1	0.4	82	0.44
L8200 13325	Soil			0.9	19.6	11.1	55	<0.1	16.0	8.1	309	2.56	11.1	2.0	2.8	5.9	41	0.1	1.0	0.3	72	0.40
L8200 13350	Soil			0.9	23.1	24.7	152	0.1	20.6	9.7	561	2.67	28.8	2.4	3.8	4.9	32	0.7	1.0	0.1	67	0.31
L8200 13375	Soil			3.5	22.5	15.2	84	0.2	23.2	12.8	1377	2.89	20.9	3.2	4.5	1.6	35	0.5	1.1	0.2	76	0.38
L8200 13400	Soil			I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L8200 13425	Soil			2.0	32.4	17.3	91	0.2	26.7	9.6	375	3.13	27.5	4.6	3.5	6.2	28	0.3	2.0	0.2	79	0.42
L8200 13450	Soil			2.3	31.6	15.3	95	0.2	22.8	12.2	576	3.31	25.8	4.4	2.8	6.9	35	0.3	1.6	0.2	94	0.45
L8200 13475	Soil			1.9	36.5	33.1	138	0.3	22.6	15.1	852	4.05	39.8	6.1	2.5	8.6	27	0.4	5.3	0.2	102	0.38
L8200 13500	Soil			1.6	30.8	11.5	66	0.1	23.0	11.9	629	3.38	23.3	2.9	2.2	5.0	22	0.2	1.0	0.1	85	0.26
L8400 12575	Soil			0.7	27.3	9.8	71	0.1	20.8	7.2	304	2.60	98.3	2.3	8.6	4.2	22	0.2	0.9	1.0	60	0.32

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L8200 12800	Soil	0.070	26	20	0.45	164	0.042	<1	1.72	0.010	0.11	0.4	0.04	3.2	0.4	<0.05	6	<0.5
L8200 12825	Soil	0.052	23	24	0.46	141	0.045	1	1.85	0.010	0.10	0.5	0.06	3.2	0.4	<0.05	6	<0.5
L8200 12850	Soil	0.095	23	31	0.57	178	0.062	2	2.29	0.012	0.09	0.3	0.09	5.1	0.3	0.07	7	<0.5
L8200 12875	Soil	0.089	21	26	0.48	167	0.083	<1	1.55	0.014	0.10	0.4	0.04	3.7	0.3	<0.05	5	<0.5
L8200 12900	Soil	0.075	23	28	0.56	210	0.074	1	2.00	0.012	0.11	0.3	0.07	3.9	0.4	<0.05	7	<0.5
L8200 12925	Soil	0.219	32	34	0.42	245	0.044	2	2.56	0.018	0.08	0.3	0.11	3.9	0.7	0.18	8	0.6
L8200 12950	Soil	0.059	13	31	0.52	164	0.079	2	1.87	0.014	0.11	0.5	0.03	2.8	0.2	0.10	7	<0.5
L8200 12975	Soil	0.051	14	32	0.55	155	0.078	2	1.98	0.014	0.09	0.5	0.02	2.9	0.2	0.08	7	<0.5
L8200 13000	Soil	0.135	17	27	0.38	242	0.043	<1	1.42	0.014	0.05	0.4	0.06	3.3	0.5	0.23	5	<0.5
L8200 13025	Soil	0.048	20	29	0.56	127	0.077	1	1.73	0.012	0.09	0.3	0.03	4.3	0.3	<0.05	6	<0.5
L8200 13050	Soil	0.056	22	28	0.47	133	0.067	1	1.68	0.012	0.08	0.2	0.04	4.1	0.3	<0.05	6	<0.5
L8200 13075	Soil	0.055	23	26	0.45	125	0.070	<1	1.54	0.011	0.07	0.2	0.05	4.1	0.3	<0.05	5	<0.5
L8200 13100	Soil	0.056	21	27	0.50	149	0.064	2	1.79	0.012	0.06	0.2	0.03	4.0	0.2	<0.05	6	<0.5
L8200 13125	Soil	0.065	20	25	0.46	216	0.040	<1	1.90	0.014	0.06	0.1	0.02	3.8	0.2	<0.05	5	<0.5
L8200 13150	Soil	0.186	29	34	0.41	252	0.031	2	2.06	0.017	0.04	0.3	0.08	4.2	0.4	0.17	6	1.0
L8200 13175	Soil	0.039	25	27	0.48	192	0.047	<1	1.82	0.015	0.07	0.2	0.03	4.2	0.3	<0.05	6	<0.5
L8200 13200	Soil	0.044	19	24	0.51	201	0.040	2	1.96	0.015	0.06	0.2	0.04	3.5	0.3	<0.05	6	<0.5
L8200 13225	Soil	0.065	27	34	0.64	223	0.081	<1	2.23	0.016	0.08	0.2	0.04	5.2	0.3	<0.05	7	0.5
L8200 13250	Soil	0.062	21	33	0.64	192	0.084	<1	1.86	0.015	0.07	0.2	0.03	4.0	0.2	<0.05	6	0.5
L8200 13275	Soil	0.082	22	30	0.50	211	0.032	<1	1.87	0.019	0.06	0.2	0.05	3.6	0.2	0.07	6	1.2
L8200 13300	Soil	0.076	25	39	0.68	242	0.114	<1	2.25	0.017	0.13	0.3	0.03	5.4	0.3	<0.05	7	0.6
L8200 13325	Soil	0.068	15	31	0.60	249	0.097	<1	1.82	0.022	0.09	0.3	0.02	3.3	0.2	<0.05	5	0.5
L8200 13350	Soil	0.056	14	30	0.59	214	0.104	2	1.86	0.022	0.09	0.2	0.03	3.2	0.2	<0.05	6	<0.5
L8200 13375	Soil	0.083	11	38	0.56	239	0.052	1	2.03	0.016	0.09	0.2	0.04	2.9	0.3	0.07	7	0.5
L8200 13400	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L8200 13425	Soil	0.075	18	41	0.65	279	0.116	2	2.17	0.021	0.10	0.3	0.03	5.3	0.2	<0.05	6	0.6
L8200 13450	Soil	0.077	19	38	0.72	297	0.124	2	2.24	0.021	0.11	0.2	0.03	5.2	0.3	<0.05	6	0.6
L8200 13475	Soil	0.077	23	38	0.79	300	0.116	<1	2.60	0.016	0.13	0.2	0.06	9.3	0.4	<0.05	7	0.7
L8200 13500	Soil	0.067	15	32	0.68	202	0.106	<1	2.24	0.014	0.09	0.2	0.02	4.4	0.3	<0.05	6	<0.5
L8400 12575	Soil	0.079	15	33	0.55	121	0.105	1	1.93	0.016	0.08	0.3	0.02	3.4	0.1	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L8400 12600	Soil		0.8	21.6	10.0	75	0.1	18.7	7.2	361	2.51	125.6	1.8	17.3	3.7	24	0.3	0.9	1.7	56	0.33
L8400 12625	Soil		0.8	31.3	9.6	81	0.1	23.2	9.4	474	3.07	179.1	2.5	11.9	7.7	21	0.5	1.0	1.0	61	0.34
L8400 12650	Soil		1.0	23.3	18.3	174	0.5	14.2	8.5	567	2.52	448.8	5.7	21.3	3.4	21	0.8	1.4	1.4	50	0.29
L8400 12675	Soil		1.0	23.2	21.2	131	0.2	15.5	7.6	543	2.56	253.0	3.5	11.2	3.9	25	1.0	1.6	1.8	54	0.27
L8400 12700	Soil		1.0	26.5	33.7	214	0.4	18.6	8.7	802	2.82	314.0	6.9	14.2	3.8	22	1.1	1.9	2.1	54	0.24
L8400 12725	Soil		1.3	32.8	52.8	342	0.8	19.6	10.0	991	2.70	246.3	11.5	12.5	2.0	52	4.2	1.9	0.9	49	0.61
L8400 12750	Soil		1.4	26.4	57.5	339	0.4	19.2	11.5	1279	3.13	239.7	6.2	12.4	2.3	33	2.4	1.9	0.8	56	0.37
L8400 12775	Soil		1.9	23.1	44.9	181	0.3	16.2	7.8	1462	2.69	153.7	4.7	12.1	0.7	26	3.1	1.6	0.7	55	0.26
L8400 12800	Soil		1.3	26.1	79.6	286	0.8	21.5	8.8	877	3.17	299.3	7.0	23.5	5.5	33	1.3	2.9	1.3	54	0.39
L8400 12825	Soil		1.6	27.8	57.0	310	0.6	23.7	9.2	808	3.56	317.0	6.6	11.7	1.8	38	2.2	2.5	1.8	64	0.43
L8400 12850	Soil		1.8	31.4	120.5	309	1.3	22.5	10.6	914	3.09	218.8	10.8	14.4	1.7	42	2.4	2.3	1.2	59	0.54
L8400 12875	Soil		2.0	20.6	53.7	189	0.4	19.8	7.2	505	2.70	119.4	4.8	3.6	1.8	25	1.2	1.6	0.6	62	0.28
L8400 12900	Soil		1.3	22.5	62.7	165	0.6	22.7	9.6	690	2.97	78.5	4.7	57.3	4.3	27	1.0	1.6	0.5	59	0.36
L8400 12925	Soil		1.1	23.1	77.5	201	0.4	24.2	10.3	731	2.98	101.4	3.4	9.5	3.9	21	1.8	1.7	0.4	58	0.28
L8400 12950	Soil		2.2	23.0	77.0	157	0.3	25.2	12.9	1286	3.26	93.3	5.3	8.4	1.7	22	1.1	2.5	0.8	64	0.23
L8400 12975	Soil		2.9	29.0	101.5	237	0.9	23.4	11.7	1015	3.55	181.2	8.4	13.2	4.9	37	1.2	3.2	1.0	60	0.50
L8400 13000	Soil		1.4	22.7	42.7	164	0.4	21.9	10.0	600	2.80	79.8	3.7	4.1	5.3	24	0.9	1.7	0.3	62	0.33
L8400 13025	Soil		1.2	25.6	247.6	265	1.5	19.4	9.2	562	2.96	162.6	5.2	8.4	3.3	26	2.7	3.4	0.5	53	0.27
L8400 13050	Soil		1.2	20.3	73.5	203	0.4	17.2	8.6	525	2.92	95.9	2.0	3.0	2.5	24	1.4	2.1	0.6	63	0.25
L8400 13075	Soil		1.2	25.5	78.1	222	0.7	16.6	9.2	716	2.76	230.0	5.0	12.6	3.0	33	1.3	2.8	1.4	50	0.36
L8400 13100	Soil		0.8	22.2	83.4	232	0.9	14.7	8.7	728	2.23	156.3	3.2	8.7	2.5	35	3.2	2.2	0.9	47	0.40
L8400 13125	Soil		0.9	21.6	116.8	336	1.0	15.0	8.0	661	2.92	435.1	3.6	11.8	7.8	31	1.8	6.3	0.7	39	0.31
L8400 13150	Soil		1.9	34.5	100.6	213	2.1	16.8	9.4	902	2.03	195.1	10.4	11.8	1.3	62	3.2	3.8	0.7	37	0.97
L8400 13175	Soil		1.5	21.4	157.2	401	2.0	21.8	11.4	909	3.24	191.4	4.4	4.3	4.9	33	1.6	5.0	0.6	64	0.42
L8400 13200	Soil		1.2	21.0	119.5	198	0.9	16.5	6.9	526	2.25	88.8	3.4	5.4	1.6	38	3.6	5.2	0.3	49	0.48
L8400 13225	Soil		1.5	23.2	97.4	208	0.6	22.0	10.7	926	2.66	62.0	3.5	12.1	3.8	39	2.5	7.7	0.3	71	0.54
L8400 13250	Soil		2.6	23.2	44.2	157	0.4	19.6	8.5	353	2.83	50.1	3.1	3.8	6.0	24	0.7	4.4	0.2	92	0.35
L8400 13275	Soil		1.4	20.4	7.1	50	0.1	12.3	6.7	699	1.67	5.4	1.4	1.5	0.2	12	0.6	0.6	0.2	46	0.12
L8400 13300	Soil		1.3	27.7	9.5	53	<0.1	20.7	7.7	262	2.32	5.8	1.4	2.8	2.0	22	0.3	0.6	0.2	57	0.25
L8400 13325	Soil		1.3	28.6	14.2	59	<0.1	19.8	7.6	289	2.21	5.8	1.3	0.9	2.2	21	0.5	0.7	0.2	52	0.24

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L8400 12600	Soil	0.055	13	32	0.55	125	0.105	2	1.76	0.014	0.08	0.6	0.03	3.1	0.1	<0.05	6	0.6
L8400 12625	Soil	0.084	18	35	0.57	147	0.123	<1	2.12	0.018	0.10	0.3	0.02	4.0	0.2	<0.05	5	<0.5
L8400 12650	Soil	0.074	20	26	0.43	97	0.065	<1	1.45	0.011	0.08	0.6	0.04	2.6	0.1	<0.05	5	<0.5
L8400 12675	Soil	0.048	19	27	0.45	135	0.078	<1	1.34	0.012	0.09	0.5	0.02	2.4	0.2	0.06	5	<0.5
L8400 12700	Soil	0.061	21	31	0.50	144	0.058	<1	1.90	0.011	0.08	0.2	0.04	3.2	0.2	<0.05	6	<0.5
L8400 12725	Soil	0.118	45	26	0.39	223	0.041	2	1.66	0.015	0.09	0.2	0.09	2.9	0.2	0.13	5	<0.5
L8400 12750	Soil	0.100	16	33	0.47	172	0.047	2	1.86	0.011	0.10	0.3	0.06	2.9	0.2	0.08	6	0.6
L8400 12775	Soil	0.189	12	28	0.31	172	0.027	1	1.78	0.011	0.07	0.2	0.07	1.5	0.3	0.17	6	<0.5
L8400 12800	Soil	0.067	22	35	0.49	186	0.056	<1	1.96	0.014	0.11	0.7	0.04	3.7	0.2	<0.05	6	<0.5
L8400 12825	Soil	0.101	23	35	0.51	210	0.039	<1	2.31	0.014	0.10	0.3	0.05	2.9	0.2	0.08	7	<0.5
L8400 12850	Soil	0.108	30	32	0.47	191	0.037	<1	2.06	0.017	0.08	0.2	0.07	3.3	0.2	0.11	6	<0.5
L8400 12875	Soil	0.080	18	34	0.41	137	0.054	<1	1.65	0.014	0.07	0.8	0.06	2.5	0.2	0.07	6	0.5
L8400 12900	Soil	0.058	18	33	0.54	148	0.067	1	1.92	0.014	0.07	0.4	0.06	3.3	0.2	<0.05	5	0.6
L8400 12925	Soil	0.071	18	30	0.56	129	0.076	<1	1.88	0.018	0.10	0.3	0.04	3.1	0.2	<0.05	6	<0.5
L8400 12950	Soil	0.080	20	35	0.47	152	0.041	3	1.81	0.012	0.07	0.2	0.07	2.5	0.2	0.08	6	<0.5
L8400 12975	Soil	0.082	27	35	0.54	159	0.038	2	1.95	0.012	0.08	0.4	0.06	3.6	0.2	0.09	6	<0.5
L8400 13000	Soil	0.052	20	31	0.56	118	0.083	12	1.56	0.012	0.08	0.4	0.03	3.1	0.2	<0.05	5	<0.5
L8400 13025	Soil	0.071	27	30	0.49	162	0.032	1	1.79	0.011	0.06	0.3	0.06	3.2	0.2	0.06	6	<0.5
L8400 13050	Soil	0.048	13	30	0.55	142	0.056	2	1.78	0.011	0.06	0.3	0.06	2.7	0.2	<0.05	6	<0.5
L8400 13075	Soil	0.068	28	26	0.50	234	0.027	3	1.79	0.014	0.05	0.2	0.06	2.9	0.2	0.07	6	<0.5
L8400 13100	Soil	0.059	24	25	0.39	199	0.047	3	1.38	0.015	0.05	0.4	0.04	2.3	0.2	0.09	4	<0.5
L8400 13125	Soil	0.039	18	23	0.51	175	0.055	2	1.46	0.011	0.14	0.6	0.05	2.8	0.3	0.07	5	<0.5
L8400 13150	Soil	0.146	49	26	0.38	254	0.030	4	1.54	0.016	0.07	0.2	0.09	2.6	0.2	0.19	4	0.7
L8400 13175	Soil	0.069	18	37	0.56	203	0.038	4	2.56	0.013	0.08	0.4	0.08	4.3	0.2	0.09	7	<0.5
L8400 13200	Soil	0.074	19	28	0.48	235	0.034	4	1.75	0.020	0.05	0.6	0.06	2.4	0.2	0.14	5	0.8
L8400 13225	Soil	0.072	18	32	0.58	279	0.084	3	1.72	0.021	0.07	0.4	0.06	3.9	0.2	0.06	5	<0.5
L8400 13250	Soil	0.074	16	40	0.59	227	0.110	3	1.85	0.014	0.07	0.3	0.04	4.6	0.3	<0.05	6	<0.5
L8400 13275	Soil	0.102	6	22	0.20	68	0.034	2	0.85	0.016	0.05	0.1	0.12	1.0	0.1	0.15	4	<0.5
L8400 13300	Soil	0.066	10	26	0.53	90	0.088	1	1.25	0.037	0.10	0.1	0.15	2.5	0.2	0.09	4	0.5
L8400 13325	Soil	0.059	9	26	0.52	85	0.088	3	1.27	0.039	0.11	0.1	0.08	2.5	0.2	0.08	5	0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L8400 13350	Soil		1.2	22.8	5.8	39	<0.1	13.2	5.1	220	1.83	3.9	1.2	3.0	1.5	15	0.2	0.5	0.2	41	0.14
L8400 13375	Soil		1.6	26.2	8.6	48	<0.1	19.2	7.4	231	2.24	5.6	1.6	1.2	1.9	18	0.2	0.6	0.2	56	0.19
L8400 13400	Soil		1.2	22.4	19.8	72	0.1	18.0	11.6	274	2.80	6.8	4.1	2.4	12.4	27	0.3	0.9	0.2	90	0.35
L8400 13425	Soil		0.9	19.5	25.1	102	0.1	16.6	11.6	441	3.21	14.5	3.6	3.3	12.1	26	0.3	1.1	0.1	93	0.34
L8400 13450	Soil		1.0	25.7	82.3	143	0.6	27.5	12.1	615	3.04	43.8	3.4	2.1	5.9	21	0.5	1.8	0.2	80	0.26
L8400 13475	Soil		2.0	36.9	22.4	82	0.1	28.9	15.8	1100	3.20	11.9	6.3	1.9	2.0	33	0.5	1.4	0.3	77	0.41
L8400 13500	Soil		1.2	24.4	7.4	37	<0.1	14.6	5.0	197	1.84	4.5	1.3	2.6	1.3	14	0.1	0.7	0.2	42	0.13
L8600 12900	Soil		1.7	19.6	89.1	420	0.4	18.3	8.8	786	2.78	162.9	4.7	3.7	0.8	25	2.8	1.9	0.6	53	0.29
L8600 12925	Soil		1.0	13.9	72.5	285	0.3	16.7	6.5	377	2.43	103.4	2.2	6.7	4.9	21	1.5	2.2	0.6	50	0.27
L8600 12950	Soil		1.3	23.6	119.0	332	1.0	21.1	10.8	696	3.16	177.1	4.5	6.9	1.8	24	0.8	2.6	0.6	64	0.27
L8600 12975	Soil		1.5	25.8	115.8	306	1.0	21.8	9.8	570	3.22	164.7	5.0	8.0	1.5	21	0.5	2.7	0.5	68	0.23
L8600 13000	Soil		1.4	27.3	94.5	297	1.2	19.6	8.5	633	2.80	187.6	6.1	9.8	1.3	29	0.6	2.8	0.8	55	0.34
L8600 13025	Soil		1.3	26.0	86.0	391	0.9	20.4	9.7	840	3.00	228.0	6.0	9.4	1.5	32	1.6	3.0	0.8	55	0.42
L8600 13050	Soil		1.4	21.4	90.6	346	0.8	17.8	8.5	601	2.85	214.0	4.8	6.7	1.9	25	1.1	3.1	0.5	55	0.33
L8600 13075	Soil		1.5	16.0	82.5	248	0.9	14.4	6.9	473	2.33	123.4	3.7	3.6	1.7	30	1.2	2.9	0.3	47	0.39
L8600 13100	Soil		1.6	23.3	56.5	224	0.6	17.9	8.1	765	2.15	48.7	4.3	2.4	1.2	57	3.4	3.6	0.3	48	0.78
L8600 13125	Soil		1.8	23.7	57.6	207	0.3	23.5	10.8	716	2.82	48.8	3.1	2.7	2.6	27	1.2	3.3	0.2	75	0.35
L8600 13150	Soil		2.0	25.4	98.7	302	0.8	24.1	9.9	515	3.28	74.3	3.9	3.2	1.9	25	0.7	5.4	0.3	84	0.29
L8600 13175	Soil		1.5	24.3	83.1	229	0.9	20.9	10.8	978	2.76	50.0	4.4	2.2	1.7	33	2.4	5.5	0.2	68	0.39
L8600 13200	Soil		1.9	14.5	100.5	259	1.1	17.6	10.9	1541	2.82	50.6	3.3	4.6	1.9	36	4.8	6.0	0.3	68	0.49
L8600 13225	Soil		1.2	22.2	50.3	144	0.4	20.0	9.6	638	2.87	31.6	4.6	4.4	1.8	24	0.6	1.7	0.3	64	0.21
L8600 13250	Soil		1.4	26.5	47.8	164	0.5	26.7	11.0	886	3.38	50.9	5.7	3.6	4.4	47	1.2	2.0	0.4	80	0.54
L8600 13275	Soil		0.9	21.5	56.9	118	0.3	26.2	10.0	569	2.90	54.2	2.7	5.0	5.8	24	0.6	3.2	0.3	69	0.29
L8600 13300	Soil		1.5	22.5	36.8	93	0.7	19.8	10.6	774	2.63	76.0	4.2	6.1	1.3	39	1.0	3.0	0.4	56	0.54
L8600 13325	Soil		0.9	24.7	25.9	92	0.2	24.1	9.5	521	2.53	43.7	2.2	12.0	4.1	27	0.7	2.0	0.3	54	0.30
L8600 13350	Soil		1.0	20.9	60.6	150	0.3	22.8	10.7	949	2.93	106.5	2.6	18.8	3.6	23	1.0	5.2	0.5	58	0.31
L8600 13375	Soil		2.0	22.7	58.8	91	0.2	23.6	14.3	1214	3.25	65.1	4.2	7.6	2.1	20	0.3	3.1	0.5	67	0.20
L8600 13400	Soil		1.5	23.8	38.1	86	0.5	22.0	8.8	618	2.95	37.6	3.3	3.5	1.7	26	0.4	2.9	0.5	64	0.31
L8600 13425	Soil		1.5	18.5	20.2	91	0.2	17.1	6.3	419	2.63	23.4	1.1	2.8	1.2	13	0.4	1.4	0.4	64	0.13
L8600 13450	Soil		1.7	22.2	80.3	162	0.6	24.0	9.1	835	3.40	91.8	3.9	6.1	2.3	27	0.8	3.8	0.6	66	0.34

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L8400 13350	Soil	0.066	8	20	0.31	96	0.053	<1	1.24	0.024	0.06	0.1	0.09	1.9	0.1	0.11	4	1.1
L8400 13375	Soil	0.054	8	29	0.44	75	0.069	2	1.19	0.030	0.07	0.1	0.12	2.0	0.2	0.09	4	<0.5
L8400 13400	Soil	0.062	21	36	0.66	190	0.150	1	1.96	0.020	0.13	0.2	0.04	4.5	0.3	<0.05	6	<0.5
L8400 13425	Soil	0.064	20	36	0.67	182	0.131	2	2.04	0.020	0.14	0.3	0.03	5.1	0.2	<0.05	6	0.5
L8400 13450	Soil	0.052	18	39	0.64	182	0.106	2	2.22	0.014	0.08	0.2	0.06	4.2	0.2	<0.05	6	<0.5
L8400 13475	Soil	0.101	27	42	0.61	241	0.065	2	2.37	0.018	0.07	0.3	0.06	3.5	0.2	0.11	7	<0.5
L8400 13500	Soil	0.056	8	24	0.29	58	0.058	2	1.07	0.022	0.07	0.1	0.09	2.3	0.2	0.10	4	<0.5
L8600 12900	Soil	0.104	16	33	0.49	133	0.032	2	1.70	0.009	0.06	0.2	0.04	1.9	0.2	0.11	5	<0.5
L8600 12925	Soil	0.042	20	30	0.48	111	0.064	2	1.47	0.011	0.07	0.2	0.02	2.5	0.2	<0.05	5	<0.5
L8600 12950	Soil	0.063	20	35	0.61	156	0.045	2	2.10	0.010	0.06	0.2	0.04	2.9	0.2	<0.05	6	<0.5
L8600 12975	Soil	0.071	22	38	0.61	149	0.040	2	2.16	0.010	0.05	0.2	0.02	2.7	0.2	0.06	6	<0.5
L8600 13000	Soil	0.081	34	31	0.54	207	0.028	2	2.00	0.010	0.05	0.2	0.03	2.4	0.2	0.07	6	<0.5
L8600 13025	Soil	0.079	23	34	0.57	199	0.028	2	2.03	0.011	0.06	0.2	0.05	2.7	0.2	0.07	6	0.7
L8600 13050	Soil	0.069	24	31	0.54	163	0.030	1	1.89	0.009	0.06	0.2	0.04	2.6	0.2	0.05	6	<0.5
L8600 13075	Soil	0.076	21	27	0.43	174	0.033	2	1.46	0.009	0.05	0.2	0.04	2.1	0.2	0.07	5	<0.5
L8600 13100	Soil	0.081	32	25	0.43	299	0.036	1	1.38	0.013	0.06	0.4	0.04	2.0	0.2	0.10	5	<0.5
L8600 13125	Soil	0.064	19	35	0.59	200	0.070	3	1.74	0.012	0.07	0.4	<0.01	3.1	0.2	0.06	6	<0.5
L8600 13150	Soil	0.072	17	41	0.63	230	0.050	2	2.28	0.011	0.07	0.2	0.03	3.2	0.2	0.07	7	<0.5
L8600 13175	Soil	0.082	22	34	0.59	254	0.044	1	1.94	0.012	0.06	0.2	0.06	2.7	0.2	0.09	6	<0.5
L8600 13200	Soil	0.089	11	33	0.55	247	0.042	2	1.74	0.012	0.08	0.2	0.06	2.7	0.2	0.08	6	<0.5
L8600 13225	Soil	0.100	27	31	0.47	164	0.040	3	2.02	0.013	0.06	0.2	0.05	2.2	0.2	0.10	7	<0.5
L8600 13250	Soil	0.074	31	38	0.67	292	0.060	1	2.28	0.013	0.10	0.3	0.05	3.5	0.2	<0.05	7	0.5
L8600 13275	Soil	0.068	14	34	0.66	168	0.083	1	2.03	0.014	0.07	0.4	0.04	3.2	0.2	<0.05	6	<0.5
L8600 13300	Soil	0.089	31	32	0.42	200	0.036	<1	1.73	0.013	0.06	0.3	0.07	2.4	0.2	0.09	6	0.6
L8600 13325	Soil	0.072	15	28	0.58	273	0.061	2	1.86	0.012	0.07	1.0	0.03	2.5	0.1	<0.05	5	<0.5
L8600 13350	Soil	0.068	14	33	0.51	153	0.056	<1	1.84	0.017	0.08	0.4	0.04	2.7	0.1	<0.05	6	<0.5
L8600 13375	Soil	0.077	19	36	0.52	163	0.039	1	2.38	0.017	0.06	0.2	0.06	3.0	0.2	0.05	7	<0.5
L8600 13400	Soil	0.082	18	34	0.52	171	0.042	<1	1.92	0.012	0.06	0.2	0.05	2.5	0.1	<0.05	7	0.5
L8600 13425	Soil	0.062	9	28	0.35	85	0.051	<1	1.55	0.009	0.06	0.2	0.06	1.5	<0.1	<0.05	7	<0.5
L8600 13450	Soil	0.093	21	34	0.58	160	0.033	2	1.89	0.009	0.08	0.2	0.06	2.4	0.1	<0.05	7	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L8600 13475	Soil		1.4	19.4	72.0	186	0.5	21.3	8.6	860	3.02	102.0	3.3	6.7	3.6	25	0.8	3.2	0.5	64	0.30
L8600 13500	Soil		2.7	23.6	125.2	295	0.7	19.3	10.7	1732	3.27	182.4	6.0	3.9	1.3	33	1.4	4.4	0.6	53	0.36
L8800 12725	Soil		8.6	24.2	83.1	155	0.9	23.6	6.6	208	2.89	124.9	3.1	7.3	2.3	24	0.4	2.5	0.7	61	0.33
L8800 12750	Soil		5.4	22.4	60.0	145	0.8	21.2	7.7	298	2.63	92.4	3.0	3.3	2.1	30	0.3	2.0	0.7	64	0.42
L8800 12775	Soil		4.2	28.0	52.4	164	0.6	23.1	7.2	236	2.59	89.5	2.5	8.5	3.3	27	0.6	1.7	1.0	64	0.35
L8800 12800	Soil		1.9	25.1	13.6	102	0.3	22.3	8.4	515	2.48	145.3	9.0	7.1	1.3	54	0.5	1.1	1.0	52	0.59
L8800 12825	Soil		1.1	21.0	18.4	111	0.3	17.1	7.5	362	1.92	69.7	5.3	4.5	1.6	32	0.5	0.9	0.6	43	0.37
L8800 12850	Soil		0.9	11.7	29.7	133	0.3	14.1	5.8	628	2.12	46.0	2.8	1.4	1.5	24	1.3	0.9	0.5	48	0.29
L8800 12875	Soil		0.7	17.4	51.6	196	0.3	22.8	8.9	580	2.62	64.8	3.0	8.4	5.1	25	1.4	1.6	0.5	55	0.37
L8800 12900	Soil		1.2	14.6	42.2	154	0.4	16.9	7.3	535	2.65	62.3	2.3	3.8	0.9	22	0.8	1.0	0.5	59	0.25
L8800 12925	Soil		1.2	13.2	72.6	176	0.4	13.6	7.6	788	2.58	87.2	2.2	12.0	1.4	26	1.2	1.6	0.3	59	0.31
L8800 12950	Soil		1.2	16.1	46.3	171	0.4	15.5	7.9	634	2.51	73.2	2.3	6.6	0.8	29	3.8	1.4	0.4	59	0.33
L8800 12975	Soil		1.6	14.8	45.0	187	0.4	15.4	7.6	736	2.64	111.0	2.6	8.3	0.9	28	1.4	1.5	0.5	62	0.31
L8800 13000	Soil		1.3	18.5	47.7	150	0.6	17.1	9.4	701	2.66	106.1	2.5	3.5	2.3	27	0.9	1.9	0.5	58	0.34
L8800 13025	Soil		1.1	13.6	41.3	122	0.2	15.9	6.0	412	2.42	64.0	1.1	26.3	2.1	24	0.7	2.1	0.4	60	0.25
L8800 13050	Soil		1.9	17.1	52.9	141	0.4	17.0	14.0	1586	2.30	31.9	2.3	1.9	0.8	31	2.2	1.8	0.2	59	0.34
L8800 13075	Soil		1.3	17.7	39.7	153	0.4	19.6	8.0	525	2.69	42.9	1.7	3.2	2.8	25	0.8	2.5	0.2	70	0.30
L8800 13100	Soil		1.2	19.5	42.3	142	0.3	24.4	8.7	727	3.00	40.2	1.9	3.9	3.9	27	0.6	2.5	0.2	77	0.38
L8800 13125	Soil		1.0	14.4	31.7	109	0.2	17.2	5.8	348	2.33	27.4	1.2	2.4	2.5	27	0.7	3.2	0.2	61	0.37
L8800 13150	Soil		1.1	17.1	36.5	107	0.2	18.5	8.9	550	2.62	22.5	2.6	7.7	2.1	28	0.4	1.5	0.2	66	0.37
L8800 13175	Soil		1.4	13.1	26.0	98	0.1	16.0	6.8	366	2.67	25.8	1.2	1.6	1.2	16	2.5	1.2	0.3	66	0.17
L8800 13200	Soil		1.7	24.1	41.6	112	0.5	25.0	11.4	789	3.29	50.8	4.2	9.5	1.8	25	0.3	2.4	0.4	70	0.35
L8800 13225	Soil		1.5	11.6	21.3	65	0.3	11.0	4.4	228	1.63	17.7	0.9	1.6	0.7	12	1.5	1.3	0.3	40	0.12
L8800 13250	Soil		1.2	23.9	28.2	105	0.3	23.8	10.7	807	2.97	36.0	4.1	7.9	4.0	22	0.4	1.9	0.3	65	0.30
L8800 13275	Soil		1.4	17.3	44.6	79	0.5	17.8	9.4	557	2.52	25.2	6.9	3.0	1.8	26	0.9	1.5	0.4	55	0.25
L8800 13300	Soil		1.1	19.6	50.6	204	0.6	21.7	8.9	948	2.63	55.4	5.5	4.5	3.7	32	1.9	2.8	0.4	53	0.48
L8800 13325	Soil		1.3	22.2	51.0	220	0.6	21.9	10.3	1825	2.52	41.0	5.8	3.0	1.8	61	10.5	3.0	0.4	49	0.74
L8800 13350	Soil		2.1	33.3	51.6	160	1.5	19.7	8.9	2267	2.03	66.3	15.0	9.8	1.9	55	5.8	4.2	0.3	38	0.84
L8800 13375	Soil		1.3	16.3	41.9	192	0.3	22.3	12.8	971	3.22	42.1	2.8	4.7	4.4	37	2.0	3.1	0.3	66	0.45
L8800 13400	Soil		1.1	19.7	39.7	107	0.3	19.9	10.4	611	2.83	59.5	2.2	13.4	4.9	29	0.7	2.9	0.2	71	0.36

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

CERTIFICATE OF ANALYSIS SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L8600 13475	Soil	0.064	19	32	0.53	159	0.041	2	1.68	0.011	0.07	0.4	0.03	2.5	0.1	<0.05	6	<0.5
L8600 13500	Soil	0.167	23	31	0.40	203	0.017	<1	2.14	0.011	0.08	0.3	0.07	2.0	0.2	0.14	6	<0.5
L8800 12725	Soil	0.101	14	40	0.58	219	0.020	<1	2.34	0.009	0.05	0.3	0.07	2.5	0.3	0.10	6	2.0
L8800 12750	Soil	0.110	13	38	0.62	249	0.032	<1	2.19	0.010	0.05	0.3	0.05	3.0	0.3	0.06	6	1.3
L8800 12775	Soil	0.085	15	41	0.71	238	0.039	1	2.48	0.015	0.07	0.8	0.02	3.3	0.2	0.07	7	0.8
L8800 12800	Soil	0.093	21	41	0.55	275	0.043	<1	1.85	0.017	0.05	0.4	0.04	2.6	0.2	0.09	6	1.6
L8800 12825	Soil	0.083	20	35	0.43	191	0.051	<1	1.89	0.019	0.05	0.3	0.04	2.6	0.2	0.05	5	0.8
L8800 12850	Soil	0.086	10	29	0.43	171	0.045	<1	1.61	0.014	0.05	0.3	0.03	2.1	0.2	0.08	5	<0.5
L8800 12875	Soil	0.081	16	35	0.51	167	0.085	<1	2.02	0.013	0.08	0.5	0.02	3.2	0.2	<0.05	5	<0.5
L8800 12900	Soil	0.068	12	31	0.52	119	0.051	<1	1.77	0.011	0.06	0.2	0.03	1.8	0.1	<0.05	7	<0.5
L8800 12925	Soil	0.069	16	27	0.46	154	0.055	<1	1.37	0.010	0.07	0.2	0.03	2.2	0.1	<0.05	6	<0.5
L8800 12950	Soil	0.093	14	29	0.43	156	0.050	1	1.55	0.011	0.08	0.2	0.02	1.9	0.1	0.05	7	<0.5
L8800 12975	Soil	0.094	14	30	0.51	164	0.039	<1	1.69	0.011	0.07	0.3	0.03	1.7	0.2	0.07	6	<0.5
L8800 13000	Soil	0.081	15	32	0.49	165	0.063	<1	1.74	0.014	0.07	0.2	0.03	2.6	0.2	<0.05	6	<0.5
L8800 13025	Soil	0.050	11	30	0.48	154	0.076	<1	1.42	0.013	0.07	0.4	0.02	2.0	0.1	<0.05	5	<0.5
L8800 13050	Soil	0.096	12	30	0.44	195	0.049	<1	1.58	0.018	0.07	0.3	0.03	2.2	0.2	0.06	6	<0.5
L8800 13075	Soil	0.066	12	33	0.59	164	0.079	<1	1.84	0.018	0.09	0.4	0.02	2.6	0.2	<0.05	6	<0.5
L8800 13100	Soil	0.071	12	35	0.65	219	0.091	1	1.97	0.013	0.11	0.2	0.02	2.9	0.2	<0.05	6	<0.5
L8800 13125	Soil	0.049	11	30	0.51	171	0.085	<1	1.37	0.013	0.11	0.3	0.02	2.4	0.1	<0.05	5	<0.5
L8800 13150	Soil	0.070	17	30	0.61	157	0.069	2	1.71	0.014	0.07	0.3	0.03	2.5	0.1	<0.05	6	<0.5
L8800 13175	Soil	0.077	8	31	0.47	97	0.060	<1	1.59	0.011	0.06	0.2	0.05	2.0	0.2	<0.05	7	<0.5
L8800 13200	Soil	0.077	22	39	0.65	229	0.047	1	2.58	0.015	0.07	0.3	0.03	3.3	0.2	<0.05	8	<0.5
L8800 13225	Soil	0.064	9	19	0.25	102	0.036	1	1.01	0.012	0.06	0.2	0.08	1.3	0.1	0.06	5	<0.5
L8800 13250	Soil	0.072	22	34	0.57	210	0.057	1	2.17	0.010	0.07	0.4	0.04	3.9	0.2	<0.05	6	<0.5
L8800 13275	Soil	0.121	48	29	0.38	278	0.030	<1	1.96	0.013	0.05	0.2	0.09	3.3	0.2	0.08	6	0.7
L8800 13300	Soil	0.064	29	33	0.55	212	0.048	<1	1.98	0.015	0.07	0.3	0.05	3.6	0.2	<0.05	6	<0.5
L8800 13325	Soil	0.112	45	31	0.47	453	0.031	<1	2.06	0.012	0.08	0.3	0.08	2.7	0.2	0.10	5	<0.5
L8800 13350	Soil	0.158	56	34	0.36	265	0.030	1	1.67	0.015	0.09	0.3	0.15	4.2	0.2	0.24	4	1.1
L8800 13375	Soil	0.061	27	36	0.66	202	0.064	<1	1.87	0.011	0.11	0.4	0.04	3.1	0.1	<0.05	7	<0.5
L8800 13400	Soil	0.054	13	29	0.65	158	0.076	<1	1.65	0.012	0.10	0.5	0.02	2.9	0.1	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

QUALITY CONTROL REPORT SMI09000114.1

		Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																						
L7200 12700	Soil			2.0	65.3	11.0	62	0.1	32.3	19.7	547	3.83	54.2	6.3	117.1	9.1	36	0.3	1.1	5.5	72	0.27
REP L7200 12700	QC			2.0	66.9	11.2	64	0.2	33.2	19.8	556	3.91	54.5	6.4	132.8	9.1	36	0.2	1.0	5.9	75	0.28
L7200 13125	Soil			1.2	33.1	11.0	75	0.2	23.8	12.2	386	3.17	47.3	4.0	6.3	7.6	34	0.2	0.9	0.5	89	0.42
REP L7200 13125	QC			1.2	32.2	10.7	74	0.1	22.4	11.5	385	3.15	46.4	4.1	5.6	7.7	34	0.2	0.9	0.5	89	0.45
L7400 12900	Soil			1.2	25.8	7.2	65	<0.1	24.0	10.9	463	2.66	16.4	0.8	2.6	1.7	18	0.1	0.5	0.2	64	0.24
REP L7400 12900	QC			1.4	25.4	7.7	66	<0.1	25.5	11.2	468	2.71	16.9	0.8	2.5	1.7	19	0.1	0.5	0.2	65	0.25
L7400 13100	Soil			2.7	36.8	14.1	79	<0.1	27.0	15.2	699	3.38	14.2	2.7	2.6	3.3	21	0.2	0.6	0.2	92	0.32
REP L7400 13100	QC			2.5	38.2	13.6	75	<0.1	26.3	14.8	674	3.29	14.3	2.6	2.4	3.2	21	0.2	0.6	0.2	90	0.29
L7400 13500	Soil			1.7	23.6	17.3	76	0.2	17.7	12.1	836	3.31	55.9	3.1	2.3	2.5	22	0.2	0.7	0.4	85	0.18
REP L7400 13500	QC			1.5	25.4	17.9	79	0.2	17.6	12.6	843	3.39	55.9	3.1	2.2	2.3	22	0.1	0.8	0.4	88	0.19
L7600 12950	Soil			0.7	28.6	18.9	100	0.2	21.0	9.8	512	2.75	402.5	3.0	33.3	7.7	25	0.4	1.2	1.7	52	0.21
REP L7600 12950	QC			0.8	28.8	19.4	101	0.2	20.9	9.7	516	2.76	404.5	3.1	30.1	7.6	25	0.3	1.2	1.7	52	0.21
L7800 12650	Soil			1.0	41.8	27.4	75	0.4	16.2	6.9	326	3.64	287.4	5.7	86.8	15.2	48	0.2	4.9	6.3	44	0.20
REP L7800 12650	QC			1.2	38.9	27.0	72	0.3	15.3	6.4	294	3.30	276.7	5.7	68.4	15.1	49	0.1	4.6	6.1	42	0.19
L7800 12775	Soil			0.9	33.2	26.3	63	0.5	13.4	6.8	333	3.65	709.2	3.4	34.5	12.9	41	0.2	3.9	6.5	39	0.21
REP L7800 12775	QC			0.9	32.1	25.4	63	0.5	13.6	6.6	334	3.58	717.3	3.2	32.8	12.6	41	0.2	3.7	6.4	39	0.21
L7800 13400	Soil			1.9	28.8	7.0	49	<0.1	16.0	7.5	280	2.30	5.9	1.5	<0.5	1.9	18	0.2	0.6	0.2	59	0.18
REP L7800 13400	QC			1.8	28.3	7.0	48	<0.1	15.8	7.4	277	2.36	5.5	1.5	2.0	1.9	18	0.2	0.6	0.2	59	0.19
L8000 12750	Soil			1.5	33.8	21.7	106	0.2	21.4	10.3	553	3.77	422.6	5.1	23.5	6.3	18	0.5	2.8	4.1	66	0.16
REP L8000 12750	QC			1.8	35.6	21.1	106	0.2	22.7	10.7	558	3.79	404.5	4.8	20.7	6.3	19	0.5	2.8	3.9	64	0.15
L8000 13075	Soil			0.6	13.6	86.2	164	0.5	13.3	8.9	318	3.91	100.5	4.8	4.7	11.0	21	0.4	1.7	0.3	53	0.25
REP L8000 13075	QC			0.7	13.7	87.0	166	0.5	13.9	9.3	316	4.04	100.6	4.7	4.1	11.4	21	0.5	1.7	0.3	54	0.26
L8200 12725	Soil			2.3	39.6	34.9	169	0.5	20.8	10.3	1448	3.35	657.8	9.6	21.7	2.4	40	0.8	3.2	3.4	51	0.47
REP L8200 12725	QC			2.2	37.3	33.2	166	0.5	20.9	10.0	1416	3.23	658.5	9.1	20.3	2.4	38	0.8	3.0	3.3	52	0.44
L8200 13150	Soil			3.1	20.0	27.0	59	0.3	13.4	13.4	524	4.92	101.5	8.0	4.0	4.1	36	0.4	1.1	0.3	97	0.54
REP L8200 13150	QC			2.9	20.5	28.1	59	0.3	13.3	13.2	518	4.93	104.1	8.0	2.6	4.0	37	0.4	1.2	0.3	79	0.54
L8400 12925	Soil			1.1	23.1	77.5	201	0.4	24.2	10.3	731	2.98	101.4	3.4	9.5	3.9	21	1.8	1.7	0.4	58	0.28
REP L8400 12925	QC			1.0	23.1	75.6	205	0.4	24.6	10.0	756	3.08	103.7	3.4	8.0	3.9	22	1.7	1.7	0.4	57	0.27

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

QUALITY CONTROL REPORT SMI09000114.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
L7200 12700	Soil	0.110	32	40	0.68	112	0.095	2	1.92	0.037	0.12	2.1	0.04	3.8	0.2	0.17	6	<0.5
REP L7200 12700	QC	0.113	32	40	0.69	112	0.099	<1	1.97	0.037	0.13	2.1	0.04	3.8	0.2	0.17	6	0.6
L7200 13125	Soil	0.089	21	41	0.78	330	0.141	<1	2.51	0.020	0.14	0.3	0.04	5.2	0.3	0.06	7	<0.5
REP L7200 13125	QC	0.088	21	40	0.77	323	0.150	<1	2.52	0.021	0.14	0.3	0.03	5.2	0.3	<0.05	7	<0.5
L7400 12900	Soil	0.056	9	34	0.55	142	0.080	2	1.98	0.013	0.05	0.2	0.05	2.6	<0.1	<0.05	6	0.8
REP L7400 12900	QC	0.058	10	35	0.57	152	0.083	2	2.03	0.013	0.05	0.2	0.04	2.7	<0.1	<0.05	6	0.7
L7400 13100	Soil	0.099	12	38	0.74	180	0.117	3	2.01	0.019	0.11	0.1	0.05	3.7	0.2	0.06	6	0.9
REP L7400 13100	QC	0.097	12	37	0.72	175	0.114	3	1.98	0.018	0.11	0.2	0.05	3.5	0.2	0.06	6	0.6
L7400 13500	Soil	0.079	13	36	0.52	227	0.092	<1	2.07	0.018	0.06	0.2	0.09	3.5	0.2	0.09	6	<0.5
REP L7400 13500	QC	0.083	14	37	0.59	232	0.121	3	2.08	0.016	0.06	0.3	0.12	3.5	0.3	0.06	7	<0.5
L7600 12950	Soil	0.054	20	30	0.57	125	0.092	1	1.68	0.013	0.11	0.5	0.04	3.3	0.3	0.07	6	<0.5
REP L7600 12950	QC	0.054	20	30	0.58	126	0.089	<1	1.70	0.016	0.11	0.5	0.04	3.2	0.2	0.06	6	<0.5
L7800 12650	Soil	0.061	32	25	0.56	172	0.061	3	2.03	0.018	0.21	0.4	0.03	3.6	0.3	0.17	7	<0.5
REP L7800 12650	QC	0.054	31	24	0.50	166	0.049	1	1.83	0.016	0.21	0.3	0.04	3.5	0.3	0.15	6	0.6
L7800 12775	Soil	0.067	25	22	0.37	178	0.059	2	1.40	0.027	0.33	0.7	0.03	2.6	0.4	0.48	5	0.6
REP L7800 12775	QC	0.064	26	20	0.35	182	0.064	2	1.25	0.025	0.34	0.7	0.02	2.6	0.4	0.46	5	<0.5
L7800 13400	Soil	0.094	10	25	0.43	81	0.074	2	1.50	0.032	0.07	0.3	0.09	2.5	0.2	0.10	5	<0.5
REP L7800 13400	QC	0.093	11	24	0.42	83	0.075	2	1.46	0.030	0.07	0.2	0.10	2.4	0.2	0.11	5	<0.5
L8000 12750	Soil	0.053	33	36	0.59	135	0.048	3	2.92	0.009	0.08	0.2	0.05	4.3	0.3	<0.05	9	0.6
REP L8000 12750	QC	0.050	35	35	0.58	139	0.048	2	2.79	0.009	0.08	0.2	0.04	4.2	0.3	<0.05	8	<0.5
L8000 13075	Soil	0.077	25	28	0.54	156	0.045	1	2.12	0.011	0.08	0.1	0.04	5.1	0.3	<0.05	7	<0.5
REP L8000 13075	QC	0.071	25	28	0.54	160	0.045	1	2.06	0.012	0.08	0.2	0.04	5.0	0.4	<0.05	7	<0.5
L8200 12725	Soil	0.121	29	31	0.49	227	0.023	2	2.13	0.013	0.08	0.3	0.05	3.0	0.3	0.12	6	0.6
REP L8200 12725	QC	0.124	28	30	0.48	222	0.023	1	2.13	0.013	0.08	0.2	0.04	2.9	0.3	0.12	7	0.7
L8200 13150	Soil	0.186	29	34	0.41	252	0.031	2	2.06	0.017	0.04	0.3	0.08	4.2	0.4	0.17	6	1.0
REP L8200 13150	QC	0.179	30	33	0.40	256	0.031	<1	1.98	0.017	0.04	0.4	0.08	3.9	0.4	0.14	6	0.7
L8400 12925	Soil	0.071	18	30	0.56	129	0.076	<1	1.88	0.018	0.10	0.3	0.04	3.1	0.2	<0.05	6	<0.5
REP L8400 12925	QC	0.071	17	31	0.55	127	0.073	<1	1.88	0.013	0.09	0.4	0.03	3.1	0.2	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

QUALITY CONTROL REPORT SMI09000114.1

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L8400 13000	Soil		1.4	22.7	42.7	164	0.4	21.9	10.0	600	2.80	79.8	3.7	4.1	5.3	24	0.9	1.7	0.3	62	0.33
REP L8400 13000	QC		1.4	24.4	44.3	169	0.4	22.3	10.6	626	2.89	83.7	4.0	5.9	5.7	25	1.0	1.8	0.3	64	0.34
L8600 12975	Soil		1.5	25.8	115.8	306	1.0	21.8	9.8	570	3.22	164.7	5.0	8.0	1.5	21	0.5	2.7	0.5	68	0.23
REP L8600 12975	QC		1.4	25.7	119.7	315	1.0	23.1	10.2	595	3.31	170.2	5.1	8.3	1.6	22	0.4	2.6	0.6	67	0.23
L8600 13225	Soil		1.2	22.2	50.3	144	0.4	20.0	9.6	638	2.87	31.6	4.6	4.4	1.8	24	0.6	1.7	0.3	64	0.21
REP L8600 13225	QC		1.4	23.2	50.4	140	0.4	18.4	9.6	642	2.78	31.6	4.9	3.8	1.7	23	0.7	1.9	0.3	61	0.23
L8800 13125	Soil		1.0	14.4	31.7	109	0.2	17.2	5.8	348	2.33	27.4	1.2	2.4	2.5	27	0.7	3.2	0.2	61	0.37
REP L8800 13125	QC		1.0	14.4	31.3	115	0.2	17.2	6.0	382	2.32	26.9	1.4	3.7	2.7	30	0.9	3.1	0.2	62	0.38
Reference Materials																					
STD DS7	Standard		20.0	106.1	60.1	360	0.8	54.6	9.6	585	2.27	46.7	4.2	69.3	3.9	63	5.4	5.0	4.1	84	0.90
STD DS7	Standard		19.1	109.3	67.3	400	0.8	58.8	9.8	604	2.43	48.0	4.8	81.0	4.6	74	6.4	5.7	4.8	90	0.92
STD DS7	Standard		21.1	110.2	66.3	374	0.7	57.3	9.7	579	2.29	43.4	4.7	65.2	4.1	67	5.4	5.5	4.0	86	0.88
STD DS7	Standard		21.4	106.6	66.7	401	0.8	58.9	9.5	647	2.56	52.0	5.0	99.6	4.8	79	6.0	5.9	4.6	79	0.97
STD DS7	Standard		21.1	111.1	65.0	379	0.8	56.9	9.8	594	2.32	46.1	4.6	88.8	4.1	69	5.9	5.7	4.1	87	0.92
STD DS7	Standard		21.9	113.3	64.8	381	0.7	57.3	9.7	590	2.32	45.2	4.6	68.4	4.2	66	5.5	5.4	4.0	88	0.88
STD DS7	Standard		20.6	102.6	68.7	381	0.9	57.3	9.6	611	2.35	53.6	4.6	63.0	4.3	71	6.8	6.1	4.6	83	0.91
STD DS7	Standard		19.7	97.5	68.6	366	0.8	53.7	8.8	584	2.39	49.3	4.8	120.5	4.5	70	6.3	5.4	4.5	81	0.93
STD DS7	Standard		21.1	117.8	65.0	393	0.9	58.9	9.6	634	2.43	51.6	4.9	66.3	4.4	73	6.3	5.5	4.2	86	0.98
STD DS7	Standard		20.4	101.8	64.4	373	0.8	51.7	9.2	589	2.29	47.3	5.0	61.1	4.2	74	6.3	5.8	4.7	85	0.92
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

QUALITY CONTROL REPORT SMI09000114.1

		1DX15 P % 0.001	1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5
L8400 13000	Soil	0.052	20	31	0.56	118	0.083	12	1.56	0.012	0.08	0.4	0.03	3.1	0.2	<0.05	5	<0.5
REP L8400 13000	QC	0.054	20	32	0.55	121	0.083	3	1.66	0.012	0.08	0.3	0.02	3.3	0.1	0.07	5	<0.5
L8600 12975	Soil	0.071	22	38	0.61	149	0.040	2	2.16	0.010	0.05	0.2	0.02	2.7	0.2	0.06	6	<0.5
REP L8600 12975	QC	0.072	22	39	0.62	156	0.039	1	2.21	0.012	0.06	0.1	0.04	2.8	0.2	0.06	7	<0.5
L8600 13225	Soil	0.100	27	31	0.47	164	0.040	3	2.02	0.013	0.06	0.2	0.05	2.2	0.2	0.10	7	<0.5
REP L8600 13225	QC	0.101	29	32	0.45	157	0.042	1	2.23	0.013	0.06	0.2	0.07	2.4	0.2	0.06	7	<0.5
L8800 13125	Soil	0.049	11	30	0.51	171	0.085	<1	1.37	0.013	0.11	0.3	0.02	2.4	0.1	<0.05	5	<0.5
REP L8800 13125	QC	0.056	11	31	0.54	181	0.090	1	1.55	0.014	0.10	0.3	0.02	2.4	0.1	<0.05	5	<0.5
Reference Materials																		
STD DS7	Standard	0.071	12	205	0.97	372	0.115	37	0.94	0.088	0.40	3.6	0.18	2.4	3.8	0.19	4	3.6
STD DS7	Standard	0.080	13	218	1.04	378	0.124	41	1.02	0.094	0.44	3.8	0.18	2.6	4.1	0.18	5	3.0
STD DS7	Standard	0.066	12	212	0.95	371	0.128	33	0.96	0.085	0.39	3.6	0.16	2.4	3.9	0.21	4	3.1
STD DS7	Standard	0.077	14	213	1.08	400	0.120	41	1.06	0.109	0.46	3.9	0.19	2.3	4.1	0.14	5	3.3
STD DS7	Standard	0.067	13	204	0.96	371	0.138	35	0.97	0.088	0.40	3.8	0.19	2.5	4.1	0.20	5	3.3
STD DS7	Standard	0.068	13	207	0.94	371	0.138	33	0.94	0.081	0.39	3.7	0.20	2.3	4.0	0.20	4	3.0
STD DS7	Standard	0.082	13	198	0.98	406	0.108	35	0.90	0.090	0.46	3.8	0.19	2.2	4.2	0.15	5	3.4
STD DS7	Standard	0.075	13	200	1.09	413	0.107	42	1.03	0.111	0.43	3.6	0.20	2.3	4.3	0.18	5	3.4
STD DS7	Standard	0.074	14	214	1.05	395	0.135	34	1.07	0.095	0.44	3.9	0.18	2.7	4.2	0.21	5	4.0
STD DS7	Standard	0.082	13	192	1.04	383	0.119	42	1.05	0.101	0.44	4.0	0.19	2.7	4.2	0.20	5	3.3
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

QUALITY CONTROL REPORT SMI09000114.1

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 19, 2009

QUALITY CONTROL REPORT SMI09000114.1

		1DX15 P % 0.001	1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 13, 2009
Report Date: August 20, 2009
Page: 1 of 7

CERTIFICATE OF ANALYSIS SMI09000133.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID:
P.O. Number
Number of Samples: 172

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	172	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	172	Dry at 60C			SMI
1DX15	172	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7000 12950N	Soil		4.8	72.8	16.2	85	0.9	31.4	7.0	440	3.31	209.2	6.1	58.8	2.5	37	0.6	4.6	4.7	89	0.49
L7000 12975N	Soil		2.7	59.7	15.2	67	0.8	23.2	6.8	245	3.23	188.5	2.3	100.5	4.2	24	0.2	4.7	9.7	73	0.32
L7000 13000N	Soil		7.3	118.1	30.0	70	2.3	21.3	6.6	291	6.30	1225	3.3	126.1	4.1	22	0.2	5.0	24.6	120	0.24
L7000 13025N	Soil		2.5	72.4	16.5	116	0.7	27.8	11.0	708	3.29	261.7	3.4	19.2	3.0	36	0.9	1.8	5.2	76	0.37
L7000 13050N	Soil		3.0	61.5	17.8	124	0.5	21.4	9.1	390	3.04	301.9	2.8	12.6	4.7	38	0.7	2.3	2.9	80	0.39
L7000 13075N	Soil		5.8	55.2	26.4	110	0.7	15.6	5.7	205	2.91	264.5	2.4	9.7	4.2	39	0.7	3.8	3.9	75	0.39
L7000 13100N	Soil		2.9	65.2	14.9	164	0.4	31.7	11.0	288	3.02	143.8	3.6	10.4	4.3	36	1.0	1.8	1.7	85	0.46
L7000 13125N	Soil		2.2	47.1	14.6	95	0.4	22.0	11.9	973	3.06	179.5	3.4	10.2	2.6	43	0.8	1.1	3.0	76	0.48
L7000 13150N	Soil		0.8	33.3	9.9	79	0.3	19.7	8.2	273	2.61	125.9	2.8	18.6	6.0	34	0.3	1.0	2.1	65	0.40
L7000 13175N	Soil		0.9	36.5	12.6	79	0.3	16.5	9.4	364	3.05	320.1	2.8	12.9	6.4	35	0.2	1.2	2.8	78	0.39
L7000 13200N	Soil		0.8	25.9	12.5	82	0.2	18.3	10.6	471	2.83	98.8	3.0	7.2	7.2	37	0.3	0.9	0.6	84	0.48
L7000 13225N	Soil		1.5	24.7	7.8	53	0.1	14.2	6.8	418	2.43	54.7	1.1	2.6	0.5	17	0.3	0.7	0.3	63	0.15
L7000 13250N	Soil		0.7	23.2	9.1	79	<0.1	14.8	11.5	518	2.87	183.5	2.6	3.9	7.1	36	0.4	0.8	0.5	89	0.48
L7000 13275N	Soil		1.5	31.7	14.0	111	0.1	23.3	12.2	656	3.26	166.9	3.1	4.4	2.9	45	0.7	0.9	0.5	79	0.46
L7000 13300N	Soil		1.7	32.9	7.7	60	<0.1	18.6	7.9	425	2.47	13.6	1.0	1.8	1.0	26	0.2	0.8	0.3	58	0.25
L7000 13325N	Soil		1.4	28.4	7.3	52	<0.1	16.9	7.3	366	2.31	8.6	1.2	0.7	1.0	26	0.2	0.6	0.3	57	0.29
L7000 13350N	Soil		1.7	28.5	7.6	49	<0.1	16.9	7.1	301	2.15	7.7	1.1	1.3	0.7	26	0.1	0.7	0.3	49	0.26
L7000 13375N	Soil		0.8	20.3	19.4	124	<0.1	17.2	8.3	436	2.40	82.4	1.0	120.8	2.1	20	0.7	0.7	0.4	67	0.25
L7000 13400N	Soil		1.1	29.8	13.0	101	<0.1	24.3	12.6	628	3.04	88.5	2.8	4.3	6.6	32	0.4	0.7	1.0	83	0.43
L7000 13425N	Soil		1.3	28.6	19.0	116	<0.1	21.5	9.1	424	2.85	38.0	1.6	6.2	1.3	42	0.2	0.7	0.4	73	0.27
L7000 13450N	Soil		1.0	23.5	13.6	104	0.1	16.6	10.8	624	2.91	78.4	3.8	3.2	7.9	33	0.5	0.8	0.4	62	0.45
L7000 13475N	Soil		1.0	25.1	13.6	101	<0.1	20.0	11.7	534	2.92	24.5	2.0	10.2	6.6	28	0.4	0.5	0.4	82	0.41
L7000 13500N	Soil		1.4	27.4	6.5	39	<0.1	13.3	5.3	147	1.96	6.8	1.0	3.9	0.7	18	<0.1	0.6	0.2	53	0.15
L7000 13525N	Soil		1.1	29.4	17.3	91	<0.1	26.8	13.0	643	3.37	24.2	3.5	4.2	7.5	24	0.3	0.6	0.4	89	0.32
L7000 13550N	Soil		1.3	20.3	858.4	841	4.9	10.6	8.0	784	2.86	478.1	4.9	15.7	10.2	32	7.0	6.0	0.2	35	0.42
L7000 13575N	Soil		97.2	29.7	621.9	328	3.7	19.2	8.6	534	3.41	357.8	2.3	22.6	8.1	48	0.9	6.7	0.5	73	0.43
L7000 13600N	Soil		2.8	33.4	129.4	120	0.6	22.7	9.7	402	3.15	158.4	3.8	13.6	7.9	32	0.5	2.1	0.5	77	0.39
L7000 13625N	Soil		1.8	32.3	14.3	86	0.1	23.1	11.4	552	3.11	16.6	3.4	17.3	6.6	34	0.5	1.5	0.4	78	0.45
L7000 13650N	Soil		1.6	23.7	11.7	86	<0.1	21.6	11.7	600	3.54	7.6	1.7	9.1	3.9	38	0.2	0.6	0.2	108	0.34
L7000 13675N	Soil		1.4	28.9	10.0	65	<0.1	22.7	12.9	641	3.35	6.9	2.8	7.9	7.1	32	0.1	0.5	0.2	98	0.37

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7000 12950N	Soil	0.185	25	57	0.62	429	0.070	1	2.11	0.027	0.20	1.2	0.13	5.2	0.3	0.35	7	1.3
L7000 12975N	Soil	0.098	18	40	0.62	236	0.085	<1	1.98	0.017	0.10	0.9	0.07	4.3	0.2	0.07	6	1.7
L7000 13000N	Soil	0.113	17	57	0.77	331	0.086	<1	2.29	0.014	0.15	0.5	0.07	5.2	0.3	0.08	8	3.0
L7000 13025N	Soil	0.095	18	37	0.59	264	0.076	1	2.36	0.028	0.11	0.4	0.06	4.1	0.2	0.07	7	1.1
L7000 13050N	Soil	0.088	15	36	0.59	240	0.099	2	1.78	0.027	0.13	1.0	0.04	3.7	0.2	0.07	6	1.1
L7000 13075N	Soil	0.125	16	29	0.38	191	0.068	<1	1.26	0.025	0.09	3.9	0.04	2.6	0.1	0.10	4	1.3
L7000 13100N	Soil	0.130	15	37	0.64	230	0.100	<1	2.07	0.029	0.10	0.4	0.03	4.1	0.2	<0.05	6	1.0
L7000 13125N	Soil	0.082	18	34	0.64	289	0.089	2	2.12	0.029	0.06	0.3	0.04	4.1	0.2	0.07	6	0.6
L7000 13150N	Soil	0.074	16	32	0.65	224	0.124	2	2.16	0.031	0.12	0.4	0.03	4.4	0.2	<0.05	6	<0.5
L7000 13175N	Soil	0.091	17	31	0.67	221	0.132	<1	2.14	0.029	0.15	0.3	0.02	4.0	0.2	<0.05	6	<0.5
L7000 13200N	Soil	0.089	17	37	0.75	231	0.170	<1	2.26	0.037	0.14	0.3	0.04	4.9	0.2	<0.05	6	<0.5
L7000 13225N	Soil	0.080	9	26	0.35	91	0.058	1	1.79	0.023	0.05	0.4	0.11	1.8	0.1	0.09	6	<0.5
L7000 13250N	Soil	0.112	19	33	0.60	268	0.152	<1	1.74	0.031	0.16	0.4	0.01	3.8	0.2	<0.05	5	<0.5
L7000 13275N	Soil	0.091	19	36	0.66	389	0.109	2	2.38	0.034	0.10	0.2	0.05	4.4	0.2	0.06	7	<0.5
L7000 13300N	Soil	0.073	9	28	0.41	107	0.068	<1	1.47	0.040	0.06	0.1	0.10	2.6	0.1	0.08	5	<0.5
L7000 13325N	Soil	0.079	10	25	0.39	109	0.072	2	1.49	0.039	0.08	0.2	0.11	2.6	0.1	0.11	5	0.5
L7000 13350N	Soil	0.077	8	24	0.37	93	0.056	2	1.37	0.045	0.07	0.2	0.14	2.2	0.1	0.09	5	<0.5
L7000 13375N	Soil	0.073	10	27	0.43	160	0.083	<1	1.45	0.025	0.06	0.5	0.05	2.5	<0.1	<0.05	5	<0.5
L7000 13400N	Soil	0.088	17	36	0.64	261	0.124	2	2.11	0.033	0.08	0.4	0.03	4.5	0.2	<0.05	6	<0.5
L7000 13425N	Soil	0.102	11	30	0.46	167	0.068	1	2.00	0.026	0.06	0.3	0.07	2.5	0.1	0.05	6	0.6
L7000 13450N	Soil	0.088	19	23	0.58	303	0.084	<1	2.01	0.045	0.11	0.3	0.04	4.2	0.1	<0.05	6	<0.5
L7000 13475N	Soil	0.095	15	31	0.62	200	0.138	<1	1.90	0.033	0.10	0.3	0.03	3.5	0.2	<0.05	6	<0.5
L7000 13500N	Soil	0.063	7	23	0.29	70	0.062	2	1.41	0.034	0.05	0.2	0.08	1.9	0.1	0.08	5	<0.5
L7000 13525N	Soil	0.073	17	39	0.73	193	0.132	<1	2.37	0.027	0.09	0.3	0.04	4.3	0.1	<0.05	7	0.6
L7000 13550N	Soil	0.054	27	17	0.39	239	0.017	<1	2.09	0.022	0.13	0.1	0.06	4.2	0.3	<0.05	5	<0.5
L7000 13575N	Soil	0.075	19	29	0.51	163	0.089	2	1.44	0.027	0.17	0.7	0.08	3.6	0.5	0.23	5	0.6
L7000 13600N	Soil	0.088	20	35	0.59	156	0.128	2	1.88	0.028	0.11	3.8	0.07	4.0	0.4	<0.05	6	<0.5
L7000 13625N	Soil	0.109	20	34	0.65	165	0.133	2	1.81	0.027	0.12	3.0	0.04	3.8	0.2	<0.05	6	<0.5
L7000 13650N	Soil	0.096	12	38	0.70	191	0.138	1	1.96	0.021	0.14	0.2	0.06	3.2	0.2	0.05	8	<0.5
L7000 13675N	Soil	0.078	16	36	0.79	215	0.110	<1	2.46	0.022	0.13	0.2	0.05	3.8	0.2	<0.05	7	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6800 12950N	Soil		1.0	67.1	9.0	41	0.2	14.7	4.9	165	2.66	19.2	4.0	122.3	16.3	25	<0.1	1.7	4.2	36	0.23
L6800 12975N	Soil		1.5	37.8	9.8	40	0.2	15.3	5.4	218	3.11	41.1	2.3	162.4	11.1	22	0.1	1.8	3.6	41	0.20
L6800 13000N	Soil		1.5	40.1	13.4	56	0.3	16.8	7.1	206	2.72	78.1	3.1	127.3	11.2	20	0.1	2.8	4.1	56	0.24
L6800 13025N	Soil		2.3	53.1	14.6	64	0.4	20.1	7.0	228	2.98	118.9	3.3	62.9	8.7	20	0.2	2.7	5.3	65	0.23
L6800 13050N	Soil		2.9	62.1	18.1	59	0.7	18.1	6.2	209	3.02	192.7	3.0	127.6	7.8	25	0.2	3.6	7.6	76	0.24
L6800 13075N	Soil		1.7	76.1	11.7	62	0.4	20.7	7.5	364	3.07	105.7	2.6	62.3	6.6	21	0.2	2.6	5.9	64	0.22
L6800 13100N	Soil		1.6	91.4	11.4	52	0.4	18.3	7.5	322	4.20	140.9	3.4	132.1	6.7	15	0.2	2.0	6.9	58	0.20
L6800 13125N	Soil		2.6	77.1	13.3	75	0.6	21.9	11.3	326	4.12	200.6	3.0	74.7	8.5	19	0.3	1.7	4.2	65	0.28
L6800 13150N	Soil		2.0	95.4	14.5	96	0.5	22.8	11.9	250	2.75	110.5	4.7	31.9	7.6	21	0.4	1.6	3.8	63	0.29
L6800 13175N	Soil		2.2	67.4	11.0	112	0.4	23.7	14.4	447	3.63	222.8	3.8	18.0	5.4	24	0.7	1.1	2.4	74	0.35
L6800 13200N	Soil		0.9	38.8	9.0	87	0.2	22.5	12.5	352	2.77	92.0	2.7	7.2	5.8	23	0.4	0.7	1.0	70	0.36
L6800 13225N	Soil		0.9	18.4	7.8	71	0.2	17.5	8.4	296	2.31	101.4	1.4	11.3	3.9	25	0.2	0.6	1.0	57	0.34
L6800 13250N	Soil		0.8	22.7	8.9	69	0.2	17.5	10.0	395	2.40	109.4	2.2	7.0	3.9	28	0.2	0.6	0.7	66	0.43
L6800 13275N	Soil		1.0	21.8	7.4	62	<0.1	15.7	9.2	390	2.48	77.3	1.5	2.8	2.6	22	0.4	0.6	0.4	68	0.29
L6800 13300N	Soil		1.3	28.1	9.4	65	0.1	21.5	11.2	424	2.93	100.2	2.5	6.8	3.9	25	0.2	0.7	0.5	78	0.37
L6800 13325N	Soil		0.7	23.8	7.8	66	<0.1	17.8	10.8	472	2.44	60.5	1.8	7.8	4.7	26	0.3	0.6	0.4	73	0.43
L6800 13350N	Soil		0.9	26.4	12.5	81	0.1	20.8	11.0	385	2.76	71.4	2.6	3.3	5.4	23	0.4	0.6	0.8	77	0.36
L6800 13375N	Soil		0.9	23.0	12.1	62	<0.1	23.9	10.7	500	2.73	46.6	1.4	24.9	4.4	17	0.4	0.7	0.3	67	0.27
L6800 13400N	Soil		1.0	26.1	16.0	113	<0.1	21.9	10.8	480	2.72	61.9	2.7	4.7	5.0	22	0.5	0.8	0.4	66	0.32
L6800 13425N	Soil		1.5	31.9	19.4	115	0.2	23.9	13.5	758	3.18	106.7	4.8	3.8	3.4	52	0.3	0.9	0.5	73	0.67
L6800 13450N	Soil		1.7	34.1	22.8	133	0.2	26.2	13.7	799	3.36	83.4	5.5	2.8	5.5	43	0.6	0.7	0.6	78	0.69
L6800 13475N	Soil		1.8	32.7	395.6	630	3.1	17.8	4.7	125	1.13	67.9	5.8	18.2	2.6	38	8.8	4.1	0.4	44	0.50
L6800 13500N	Soil		2.1	21.8	49.8	130	0.2	13.3	6.3	446	2.27	63.2	1.0	3.8	0.5	17	1.4	1.2	0.3	59	0.19
L6800 13525N	Soil		1.6	30.6	50.6	362	0.3	24.5	15.6	784	3.37	227.0	5.6	15.2	3.5	22	1.0	1.1	0.5	77	0.23
L6800 13550N	Soil		1.5	23.3	29.2	213	0.2	22.4	10.7	369	3.41	138.3	1.4	19.7	4.6	25	0.9	0.9	0.5	81	0.29
L6800 13575N	Soil		0.8	21.7	20.2	135	<0.1	21.9	9.7	392	2.63	118.6	1.7	9.6	6.0	17	0.6	0.7	0.3	68	0.30
L6800 13600N	Soil		1.0	19.4	17.8	145	0.1	18.9	8.5	362	2.56	68.0	1.1	2.3	2.6	17	0.7	0.6	0.3	68	0.24
L6800 13625N	Soil		1.4	22.6	30.7	170	0.3	18.1	9.5	420	2.96	88.5	1.7	7.7	4.2	15	1.0	1.5	0.4	67	0.20
L6800 13650N	Soil		1.6	27.9	89.7	234	0.7	20.9	9.4	482	3.32	677.1	4.3	13.5	2.8	17	1.2	1.3	0.8	69	0.16
L6800 13675N	Soil		1.3	25.6	106.3	333	0.6	24.3	11.7	548	3.08	712.2	2.7	15.2	6.5	19	2.2	1.3	0.8	67	0.24

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6800 12950N	Soil	0.053	27	26	0.53	245	0.076	<1	1.99	0.020	0.20	0.7	0.03	3.7	0.2	<0.05	6	0.8
L6800 12975N	Soil	0.058	23	28	0.47	189	0.065	<1	1.75	0.016	0.17	0.7	0.03	2.9	0.2	<0.05	6	0.7
L6800 13000N	Soil	0.063	21	31	0.57	231	0.082	<1	2.17	0.017	0.13	1.4	0.06	4.0	0.2	<0.05	6	0.8
L6800 13025N	Soil	0.072	20	35	0.58	219	0.078	<1	2.23	0.016	0.13	1.0	0.06	4.0	0.2	<0.05	7	0.8
L6800 13050N	Soil	0.085	22	38	0.57	253	0.069	1	2.11	0.017	0.11	0.9	0.06	3.7	0.3	<0.05	7	1.1
L6800 13075N	Soil	0.068	16	36	0.59	161	0.097	<1	1.76	0.017	0.11	0.7	0.03	3.4	0.2	<0.05	6	0.5
L6800 13100N	Soil	0.065	17	33	0.53	119	0.057	3	1.71	0.010	0.11	0.6	0.03	2.9	0.2	0.10	6	0.9
L6800 13125N	Soil	0.075	19	29	0.56	168	0.073	1	2.22	0.010	0.13	0.9	0.05	3.4	0.3	<0.05	6	0.8
L6800 13150N	Soil	0.074	22	28	0.55	187	0.074	1	2.04	0.012	0.12	0.4	0.03	3.9	0.3	<0.05	6	1.2
L6800 13175N	Soil	0.089	18	31	0.61	236	0.086	2	1.98	0.013	0.13	0.4	0.03	4.0	0.3	0.05	6	0.8
L6800 13200N	Soil	0.081	19	33	0.62	258	0.097	1	1.99	0.015	0.11	0.4	0.03	4.1	0.2	<0.05	6	<0.5
L6800 13225N	Soil	0.065	10	24	0.56	224	0.081	<1	1.85	0.014	0.08	0.4	0.03	2.6	0.2	<0.05	6	<0.5
L6800 13250N	Soil	0.080	13	28	0.58	241	0.081	1	1.83	0.019	0.07	0.2	0.04	3.1	0.2	<0.05	5	<0.5
L6800 13275N	Soil	0.072	11	25	0.50	190	0.082	2	1.57	0.017	0.08	0.4	0.03	2.2	0.1	0.07	5	<0.5
L6800 13300N	Soil	0.075	14	32	0.63	254	0.088	3	2.00	0.018	0.09	0.8	0.02	3.3	0.2	<0.05	6	0.6
L6800 13325N	Soil	0.075	13	30	0.59	232	0.096	3	1.69	0.021	0.09	0.5	0.02	3.0	0.2	<0.05	5	<0.5
L6800 13350N	Soil	0.078	15	34	0.67	242	0.112	2	2.17	0.021	0.10	0.3	0.02	3.7	0.2	<0.05	6	<0.5
L6800 13375N	Soil	0.064	10	30	0.50	121	0.081	2	1.88	0.014	0.06	0.8	0.03	2.6	0.1	<0.05	5	<0.5
L6800 13400N	Soil	0.072	18	30	0.58	183	0.077	2	2.06	0.015	0.07	0.4	0.04	3.2	0.2	<0.05	6	<0.5
L6800 13425N	Soil	0.081	21	33	0.63	298	0.062	3	2.52	0.027	0.08	0.3	0.05	3.7	0.2	0.07	7	0.8
L6800 13450N	Soil	0.082	24	34	0.71	327	0.081	3	2.66	0.026	0.11	0.3	0.04	4.6	0.2	0.06	7	0.7
L6800 13475N	Soil	0.096	23	28	0.33	274	0.036	4	2.24	0.018	0.09	0.2	0.10	3.8	0.5	0.18	6	0.6
L6800 13500N	Soil	0.079	8	22	0.31	129	0.043	3	1.46	0.015	0.06	0.3	0.11	1.5	0.2	0.11	6	0.8
L6800 13525N	Soil	0.079	41	38	0.65	228	0.070	2	2.70	0.014	0.07	0.5	0.07	4.4	0.3	<0.05	7	0.7
L6800 13550N	Soil	0.071	12	32	0.60	182	0.102	1	2.06	0.018	0.08	0.7	0.03	3.0	0.2	<0.05	8	<0.5
L6800 13575N	Soil	0.060	14	30	0.59	123	0.108	3	1.57	0.015	0.11	1.6	0.02	2.9	0.2	<0.05	5	<0.5
L6800 13600N	Soil	0.068	11	30	0.52	114	0.096	<1	1.47	0.014	0.09	0.7	0.03	2.4	0.2	<0.05	6	<0.5
L6800 13625N	Soil	0.069	12	29	0.53	99	0.077	2	1.69	0.010	0.08	1.2	0.04	3.1	0.2	0.05	6	<0.5
L6800 13650N	Soil	0.077	19	33	0.55	160	0.053	1	2.17	0.011	0.09	0.5	0.05	2.8	0.3	0.10	7	0.9
L6800 13675N	Soil	0.067	14	31	0.58	135	0.090	1	1.85	0.015	0.13	2.0	0.04	2.9	0.2	0.11	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6800 13700N	Soil		0.8	25.5	80.8	236	0.5	18.9	9.3	479	3.05	871.7	3.6	9.8	6.7	24	1.5	1.6	1.2	53	0.37
L6800 13725N	Soil		1.6	29.8	33.3	72	0.1	16.1	6.4	221	2.25	43.0	1.1	1.7	0.8	17	0.4	0.7	0.2	52	0.16
L6800 13750N	Soil		0.8	16.6	43.5	119	0.2	12.2	7.7	595	2.32	50.9	3.1	2.6	7.1	20	0.5	1.3	0.2	42	0.33
L6800 13775N	Soil		1.1	24.6	18.5	112	<0.1	16.5	11.9	534	2.85	18.6	2.4	3.1	3.8	23	0.5	0.7	0.2	73	0.42
L6800 13800N	Soil		0.9	22.8	47.4	174	0.4	19.3	10.4	702	2.70	75.9	2.7	6.0	5.5	25	0.5	0.8	0.2	66	0.39
L6800 13825N	Soil		2.6	39.4	173.6	372	1.5	24.7	9.6	367	2.98	299.4	6.1	13.0	6.5	34	2.1	2.7	0.3	79	0.63
L6800 13850N	Soil		1.3	23.9	118.7	149	0.9	18.6	7.8	198	2.39	75.8	4.1	4.1	7.1	24	0.5	1.1	0.2	60	0.39
L6800 13875N	Soil		3.8	23.0	91.2	131	0.5	16.7	7.5	163	4.39	183.5	4.9	3.4	6.7	17	0.3	1.2	0.2	71	0.27
L6800 13900N	Soil		2.1	15.0	74.2	182	0.5	15.7	8.3	536	2.73	77.4	2.8	2.3	6.1	27	0.6	0.9	0.2	65	0.42
L6600 13000N	Soil		0.8	56.4	12.0	38	0.2	16.1	9.4	342	3.00	29.6	3.6	275.0	9.9	22	0.1	2.7	3.7	55	0.22
L6600 13025N	Soil		0.9	44.4	10.7	42	0.2	15.5	6.1	193	2.79	26.6	2.2	139.7	8.9	22	0.1	2.2	3.5	57	0.28
L6600 13050N	Soil		1.0	60.2	8.1	44	0.1	16.3	8.0	304	3.00	27.8	2.8	114.1	8.1	22	0.2	2.1	2.9	50	0.23
L6600 13075N	Soil		1.2	45.8	9.8	49	0.1	16.8	9.3	485	2.90	30.6	2.5	74.3	4.6	18	0.2	2.1	2.5	55	0.21
L6600 13100N	Soil		0.9	54.6	10.6	38	0.2	16.0	5.9	179	2.92	42.8	3.0	142.7	8.9	19	0.1	3.7	4.2	54	0.24
L6600 13125N	Soil		0.9	39.1	9.5	40	0.1	14.5	5.6	170	2.18	54.7	2.4	111.7	9.4	21	0.1	2.3	3.0	45	0.27
L6600 13150N	Soil		1.5	43.9	10.7	45	0.3	16.8	7.4	305	2.81	53.4	2.7	57.8	8.4	19	0.1	2.1	3.0	57	0.28
L6600 13175N	Soil		1.5	94.9	12.1	66	0.2	24.7	9.2	589	2.95	69.2	9.7	321.2	10.3	18	0.2	2.2	4.4	43	0.14
L6600 13200N	Soil		1.2	60.9	8.8	68	0.2	20.9	10.7	711	2.75	35.6	4.8	42.6	8.2	17	0.2	1.3	1.9	53	0.23
L6600 13225N	Soil		1.1	64.4	8.5	64	0.2	17.8	6.3	299	2.78	51.1	4.2	73.8	9.3	15	0.2	1.7	2.5	55	0.18
L6600 13250N	Soil		1.8	89.3	12.8	65	0.5	20.4	9.0	384	2.98	111.2	5.1	168.9	4.2	17	0.3	2.1	4.9	68	0.20
L6600 13275N	Soil		1.8	84.2	11.5	80	0.3	20.3	11.4	590	3.22	116.9	3.5	32.9	2.8	21	0.4	1.3	3.4	64	0.26
L6600 13300N	Soil		1.5	59.8	9.8	92	0.2	20.9	8.0	915	2.68	76.5	5.2	62.3	5.4	27	0.6	1.1	3.0	53	0.32
L6600 13325N	Soil		1.3	66.4	9.7	90	0.1	24.1	10.8	721	2.68	71.9	6.5	7.6	1.8	27	0.4	0.8	1.7	63	0.32
L6600 13350N	Soil		1.2	24.2	8.1	92	0.1	18.3	10.6	633	2.62	70.6	2.0	7.4	1.6	23	0.8	0.6	0.6	66	0.26
L6600 13375N	Soil		1.0	23.3	8.3	69	<0.1	17.6	10.8	588	2.70	111.2	1.9	6.9	3.2	24	0.2	0.7	0.7	70	0.34
L6600 13400N	Soil		1.7	27.2	14.5	95	0.1	25.2	12.2	659	3.30	156.5	2.9	8.9	2.1	23	0.2	1.1	0.8	79	0.29
L6600 13425N	Soil		1.7	23.3	18.0	114	0.1	23.4	11.6	656	3.22	173.0	2.8	9.6	2.6	23	0.2	1.1	0.8	74	0.32
L6600 13450N	Soil		2.0	20.5	23.3	128	0.1	22.5	9.7	414	3.40	227.8	2.3	10.6	2.9	24	0.4	1.3	0.8	80	0.32
L6600 13475N	Soil		1.8	29.2	23.4	145	0.3	24.0	12.4	686	3.49	341.7	5.2	16.1	4.2	25	0.6	1.4	1.0	82	0.36
L6600 13500N	Soil		1.4	14.8	47.1	238	0.4	17.1	10.4	666	2.78	186.3	3.0	9.1	4.0	33	1.1	1.6	0.6	63	0.47

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6800 13700N	Soil	0.071	24	25	0.56	264	0.053	2	1.83	0.012	0.09	0.4	0.01	3.2	0.2	<0.05	5	<0.5
L6800 13725N	Soil	0.060	8	25	0.35	88	0.058	2	1.57	0.023	0.06	0.1	0.08	1.9	0.2	0.11	5	0.9
L6800 13750N	Soil	0.064	23	18	0.40	192	0.045	1	1.24	0.017	0.10	0.4	0.01	3.0	0.2	<0.05	4	<0.5
L6800 13775N	Soil	0.084	14	26	0.63	230	0.101	1	1.68	0.026	0.11	0.2	0.04	3.5	0.2	0.06	5	<0.5
L6800 13800N	Soil	0.076	18	30	0.56	249	0.097	<1	1.58	0.020	0.10	0.5	0.02	3.3	0.1	<0.05	5	<0.5
L6800 13825N	Soil	0.066	28	37	0.52	341	0.079	2	2.38	0.017	0.14	0.3	0.06	5.5	0.3	0.10	7	1.2
L6800 13850N	Soil	0.061	20	32	0.54	264	0.065	1	1.95	0.016	0.08	0.2	0.05	3.8	0.2	<0.05	6	0.6
L6800 13875N	Soil	0.061	20	32	0.48	209	0.053	2	1.93	0.013	0.09	0.3	0.03	3.8	0.2	0.09	6	0.6
L6800 13900N	Soil	0.056	14	26	0.54	247	0.082	1	1.65	0.019	0.11	0.5	0.03	2.9	0.2	0.05	5	<0.5
L6600 13000N	Soil	0.070	24	27	0.52	174	0.082	<1	1.68	0.013	0.18	2.3	0.03	3.4	0.3	0.06	6	0.6
L6600 13025N	Soil	0.072	21	27	0.60	208	0.087	<1	1.82	0.013	0.17	3.8	0.02	3.1	0.3	<0.05	6	<0.5
L6600 13050N	Soil	0.074	18	23	0.46	126	0.074	<1	1.44	0.018	0.15	2.1	0.02	2.5	0.2	0.09	5	<0.5
L6600 13075N	Soil	0.066	15	28	0.45	128	0.058	2	1.67	0.015	0.11	2.3	0.04	2.4	0.2	0.09	6	0.6
L6600 13100N	Soil	0.074	21	26	0.57	151	0.076	<1	1.73	0.011	0.20	5.4	0.02	3.0	0.3	<0.05	6	<0.5
L6600 13125N	Soil	0.060	20	25	0.47	115	0.065	<1	1.52	0.014	0.11	2.3	0.03	2.5	0.3	<0.05	5	<0.5
L6600 13150N	Soil	0.067	18	29	0.55	152	0.077	2	1.83	0.010	0.14	2.7	0.04	3.0	0.2	<0.05	6	0.5
L6600 13175N	Soil	0.059	37	33	0.55	145	0.070	<1	2.13	0.009	0.28	0.9	0.02	3.5	0.4	<0.05	8	1.0
L6600 13200N	Soil	0.059	27	30	0.65	185	0.102	<1	2.01	0.011	0.33	1.0	0.03	4.0	0.5	<0.05	7	0.5
L6600 13225N	Soil	0.052	27	31	0.60	171	0.101	<1	1.99	0.010	0.32	0.9	0.01	4.1	0.4	<0.05	7	<0.5
L6600 13250N	Soil	0.075	21	35	0.60	189	0.063	<1	2.19	0.009	0.13	1.1	0.03	3.3	0.3	<0.05	7	0.9
L6600 13275N	Soil	0.072	16	31	0.55	172	0.058	<1	2.06	0.010	0.09	1.0	0.03	2.9	0.2	<0.05	6	0.9
L6600 13300N	Soil	0.069	22	26	0.48	190	0.059	<1	1.85	0.011	0.09	1.1	0.03	3.0	0.2	<0.05	6	0.6
L6600 13325N	Soil	0.078	25	30	0.55	245	0.056	<1	2.00	0.015	0.06	0.7	0.02	2.9	0.2	<0.05	7	0.9
L6600 13350N	Soil	0.071	11	28	0.50	224	0.069	<1	1.79	0.017	0.07	0.3	0.05	2.6	0.1	<0.05	6	<0.5
L6600 13375N	Soil	0.067	12	28	0.55	231	0.073	<1	1.81	0.022	0.07	0.5	0.02	2.9	0.2	<0.05	5	<0.5
L6600 13400N	Soil	0.076	13	36	0.66	236	0.057	<1	2.39	0.011	0.07	0.5	0.03	3.0	0.2	<0.05	7	0.7
L6600 13425N	Soil	0.074	14	34	0.61	226	0.052	1	2.30	0.011	0.07	0.3	0.03	3.2	0.2	<0.05	7	<0.5
L6600 13450N	Soil	0.068	11	34	0.60	191	0.052	<1	2.37	0.012	0.08	0.4	0.05	2.9	0.2	<0.05	7	0.6
L6600 13475N	Soil	0.083	24	38	0.62	226	0.051	<1	2.67	0.013	0.08	0.4	0.05	4.3	0.2	<0.05	8	0.6
L6600 13500N	Soil	0.060	15	29	0.41	260	0.058	<1	2.05	0.019	0.07	0.3	0.05	3.6	0.2	<0.05	6	0.6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6600 13525N	Soil		1.6	14.4	49.9	196	0.5	14.0	10.4	663	2.69	318.6	3.0	17.7	4.9	28	0.7	2.0	1.0	53	0.39
L6600 13550N	Soil		1.4	16.9	53.4	200	0.6	16.7	7.4	298	2.26	184.4	2.4	26.6	5.1	29	0.9	2.2	1.1	55	0.37
L6600 13575N	Soil		1.3	20.9	35.7	209	0.4	18.5	9.3	536	2.69	234.0	3.2	11.3	3.7	32	0.7	1.6	0.5	64	0.55
L6600 13600N	Soil		1.7	13.0	23.9	114	0.1	15.6	9.7	609	2.59	149.9	1.2	9.7	2.6	15	2.6	0.7	0.9	63	0.18
L6600 13625N	Soil		1.2	17.1	40.8	180	0.3	14.3	9.8	619	2.59	216.3	2.3	9.1	6.5	18	1.2	1.4	0.6	54	0.30
L6600 13650N	Soil		1.5	18.7	61.1	190	0.4	16.4	7.8	335	2.84	329.5	3.9	12.0	4.2	21	0.8	1.4	0.5	60	0.29
L6600 13675N	Soil		1.3	12.0	35.3	145	0.3	15.3	7.0	359	2.12	125.6	2.1	6.9	5.2	26	0.7	1.1	0.3	54	0.42
L6600 13700N	Soil		1.3	18.8	20.3	114	0.2	18.1	9.4	421	2.56	199.6	1.8	6.6	4.4	20	0.8	1.0	0.7	65	0.29
L6600 13725N	Soil		0.9	20.0	31.7	124	0.2	19.6	9.0	439	2.45	125.4	2.3	7.6	4.6	27	0.7	0.8	0.2	63	0.44
L6600 13750N	Soil		1.5	14.8	53.1	251	0.4	16.7	11.8	552	2.98	205.0	1.4	5.3	5.2	19	0.8	1.1	0.5	66	0.26
L6600 13775N	Soil		1.4	20.8	36.9	129	0.3	17.3	10.0	463	2.65	219.8	2.0	26.6	5.4	29	1.0	1.0	0.4	66	0.40
L6600 13800N	Soil		2.6	32.7	44.1	167	0.4	19.3	11.5	690	3.13	279.0	3.7	33.1	4.1	36	0.6	1.3	1.5	64	0.59
L6600 13825N	Soil		1.0	17.1	28.3	94	0.2	18.3	8.4	304	2.35	51.0	1.7	7.7	4.4	24	0.4	0.7	0.2	62	0.40
L6600 13850N	Soil		1.0	40.3	31.3	93	0.3	19.7	10.1	521	2.85	518.5	3.3	42.3	5.9	29	0.4	1.1	1.6	64	0.44
L6600 13875N	Soil		1.5	27.3	34.7	129	0.3	19.0	10.5	559	3.10	169.2	1.9	32.4	3.9	25	0.9	1.8	1.8	64	0.39
L6600 13900N	Soil		0.8	21.6	20.6	129	0.1	16.7	8.5	449	2.51	105.8	3.0	15.5	6.1	30	0.5	1.1	0.4	61	0.45
L6600 13925N	Soil		1.2	16.3	36.7	181	0.5	14.5	9.4	338	2.75	253.5	2.0	32.7	5.5	18	0.7	2.8	1.3	58	0.33
L6600 13950N	Soil		0.8	24.6	35.0	140	0.3	17.5	8.8	736	2.68	631.7	4.0	30.1	7.2	26	0.6	2.2	0.8	57	0.40
L6600 13975N	Soil		1.2	17.6	81.5	212	1.4	12.1	6.7	313	2.74	244.2	3.9	29.9	7.7	27	0.4	5.8	1.0	46	0.36
L6600 14000N	Soil		1.0	20.3	53.7	165	0.5	19.6	10.3	538	2.80	193.8	2.9	10.4	6.3	27	0.6	3.3	0.5	59	0.34
L6400 13000N	Soil		0.9	32.5	11.4	57	<0.1	20.7	9.3	320	2.88	22.4	2.0	29.6	7.9	16	0.2	1.8	1.2	52	0.19
L6400 13025N	Soil		1.0	36.6	24.4	75	0.2	18.6	11.3	425	3.19	46.7	4.6	28.0	12.2	16	0.3	3.0	2.2	56	0.22
L6400 13050N	Soil		1.2	24.0	18.5	81	0.1	19.2	11.5	521	3.10	43.3	3.0	12.6	6.2	16	0.3	2.3	1.7	59	0.20
L6400 13075N	Soil		1.1	47.3	17.3	62	<0.1	21.0	11.4	436	2.94	38.0	2.9	53.6	9.6	18	0.2	2.7	2.8	56	0.21
L6400 13100N	Soil		1.6	98.7	23.4	74	0.3	26.1	16.1	639	3.82	66.5	18.1	35.3	9.6	22	0.2	3.6	3.6	66	0.22
L6400 13125N	Soil		1.1	46.4	13.7	58	0.2	17.4	7.1	209	2.97	59.5	7.3	28.0	13.7	28	0.2	2.8	2.9	49	0.30
L6400 13150N	Soil		1.2	48.7	14.8	57	0.2	20.1	12.8	648	2.80	38.6	5.8	18.1	7.6	26	0.2	3.3	4.1	54	0.36
L6400 13175N	Soil		1.3	35.2	14.3	63	0.2	20.4	10.8	330	3.25	37.8	4.8	55.6	7.9	24	0.4	2.6	3.5	61	0.27
L6400 13200N	Soil		0.8	36.0	10.7	56	0.1	19.5	9.4	309	2.64	26.7	3.2	48.4	8.9	22	0.2	2.1	2.3	53	0.28
L6400 13225N	Soil		0.9	32.7	11.6	49	0.2	18.2	9.3	279	2.89	28.9	4.3	46.3	9.4	24	0.2	2.0	3.0	56	0.30

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6600 13525N	Soil	0.071	15	25	0.47	202	0.044	<1	1.81	0.015	0.07	0.3	0.05	3.3	0.3	<0.05	5	0.6
L6600 13550N	Soil	0.068	15	30	0.54	193	0.057	<1	2.04	0.015	0.08	0.5	0.04	3.2	0.3	<0.05	6	<0.5
L6600 13575N	Soil	0.074	19	31	0.56	230	0.065	<1	2.06	0.016	0.07	0.5	0.04	3.7	0.2	<0.05	6	<0.5
L6600 13600N	Soil	0.049	8	30	0.45	95	0.076	<1	1.60	0.013	0.06	0.3	0.06	2.5	0.2	<0.05	6	<0.5
L6600 13625N	Soil	0.081	15	23	0.47	126	0.081	<1	1.30	0.013	0.10	0.9	0.02	2.8	0.2	<0.05	4	<0.5
L6600 13650N	Soil	0.054	23	29	0.48	182	0.060	1	1.84	0.016	0.07	0.3	0.04	3.5	0.2	<0.05	5	0.7
L6600 13675N	Soil	0.049	14	27	0.49	172	0.087	<1	1.56	0.019	0.09	0.4	0.03	3.1	0.2	<0.05	5	<0.5
L6600 13700N	Soil	0.070	13	27	0.48	131	0.089	<1	1.61	0.017	0.10	0.3	0.04	2.8	0.2	<0.05	5	0.5
L6600 13725N	Soil	0.069	17	27	0.54	168	0.092	<1	1.56	0.024	0.08	0.3	0.02	2.9	0.1	<0.05	4	<0.5
L6600 13750N	Soil	0.057	11	28	0.48	206	0.069	<1	1.98	0.014	0.09	0.3	0.03	2.8	0.1	<0.05	7	0.7
L6600 13775N	Soil	0.068	13	29	0.54	206	0.100	<1	1.68	0.021	0.09	0.3	0.01	3.2	0.2	<0.05	5	0.6
L6600 13800N	Soil	0.072	20	30	0.48	288	0.049	<1	2.19	0.017	0.08	0.2	0.04	3.4	0.2	<0.05	6	0.6
L6600 13825N	Soil	0.068	14	28	0.54	189	0.095	<1	1.76	0.018	0.09	0.3	0.03	3.0	0.2	<0.05	5	<0.5
L6600 13850N	Soil	0.079	19	31	0.52	227	0.085	<1	1.68	0.026	0.09	0.3	0.03	3.6	0.1	<0.05	5	<0.5
L6600 13875N	Soil	0.069	11	30	0.55	241	0.065	<1	1.89	0.014	0.11	0.2	0.02	3.0	0.2	<0.05	5	0.5
L6600 13900N	Soil	0.073	21	28	0.53	281	0.074	<1	1.70	0.019	0.09	0.3	0.02	3.6	0.1	<0.05	5	<0.5
L6600 13925N	Soil	0.074	12	24	0.49	198	0.072	<1	1.73	0.014	0.08	0.5	0.03	3.0	0.2	<0.05	5	<0.5
L6600 13950N	Soil	0.066	22	28	0.50	227	0.073	<1	1.59	0.017	0.09	0.2	0.03	3.8	0.2	<0.05	5	<0.5
L6600 13975N	Soil	0.050	16	25	0.46	245	0.051	2	1.93	0.019	0.10	0.2	0.05	3.7	0.3	<0.05	5	<0.5
L6600 14000N	Soil	0.058	14	28	0.53	197	0.081	2	1.88	0.024	0.09	0.3	0.03	3.3	0.2	<0.05	5	<0.5
L6400 13000N	Soil	0.058	16	29	0.45	83	0.083	2	1.76	0.015	0.09	0.3	0.03	2.9	0.2	0.07	5	0.6
L6400 13025N	Soil	0.056	27	33	0.51	92	0.093	3	1.96	0.019	0.10	0.2	0.05	4.4	0.2	<0.05	6	0.6
L6400 13050N	Soil	0.060	18	33	0.51	105	0.096	2	1.77	0.013	0.10	0.3	0.04	3.5	0.2	<0.05	6	<0.5
L6400 13075N	Soil	0.067	22	34	0.49	82	0.111	1	1.77	0.019	0.15	1.3	0.02	3.2	0.3	0.07	5	<0.5
L6400 13100N	Soil	0.082	62	46	0.60	140	0.099	2	2.56	0.018	0.11	0.6	0.06	6.0	0.4	0.07	7	1.3
L6400 13125N	Soil	0.074	33	28	0.46	103	0.086	2	1.52	0.021	0.13	0.8	0.03	3.8	0.2	0.07	5	0.6
L6400 13150N	Soil	0.083	22	33	0.51	104	0.094	1	1.64	0.025	0.10	1.0	0.03	3.9	0.2	0.06	5	0.7
L6400 13175N	Soil	0.070	23	34	0.54	130	0.099	<1	1.84	0.016	0.12	1.0	0.04	4.2	0.2	<0.05	6	0.8
L6400 13200N	Soil	0.074	19	29	0.50	97	0.096	1	1.44	0.018	0.11	0.9	0.02	3.3	0.2	<0.05	4	<0.5
L6400 13225N	Soil	0.078	22	29	0.48	105	0.104	2	1.34	0.020	0.11	1.3	0.02	3.7	0.2	<0.05	4	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6400 13250N	Soil		1.6	45.1	16.3	56	0.3	20.0	9.9	318	3.49	61.7	6.1	33.1	6.9	22	0.2	2.9	6.9	61	0.25
L6400 13275N	Soil		1.2	67.1	12.6	67	<0.1	20.2	10.7	404	3.99	71.0	4.6	27.3	14.3	18	0.3	2.8	4.8	59	0.19
L6400 13300N	Soil		1.2	37.3	11.7	62	0.1	21.5	9.9	476	3.06	23.2	4.1	19.4	5.8	18	0.3	1.5	2.7	60	0.19
L6400 13325N	Soil		0.8	33.9	9.4	51	0.1	16.4	7.2	313	2.32	22.2	2.5	31.6	6.5	24	0.2	1.7	2.3	48	0.26
L6400 13350N	Soil		1.0	38.5	7.5	44	0.1	14.8	7.0	323	2.05	26.9	4.4	21.0	2.8	24	0.2	1.4	1.8	42	0.25
L6400 13375N	Soil		1.4	34.4	11.1	64	0.2	17.9	9.4	423	2.64	52.0	3.1	23.7	3.0	25	0.3	1.4	2.8	58	0.24
L6400 13400N	Soil		1.3	24.8	11.7	79	<0.1	21.1	12.5	645	3.18	116.0	2.8	23.0	2.6	24	0.2	0.8	1.0	71	0.25
L6400 13425N	Soil		1.3	23.4	11.0	78	<0.1	21.4	12.0	635	3.34	125.5	2.3	37.5	2.4	26	0.3	0.7	0.8	76	0.28
L6400 13450N	Soil		1.8	22.9	14.2	373	<0.1	22.6	12.4	708	4.40	145.2	2.5	11.5	2.7	22	0.3	1.1	0.8	66	0.25
L6400 13475N	Soil		1.3	18.8	14.0	73	0.1	18.5	11.2	579	2.88	141.3	2.7	12.2	2.6	22	0.3	1.1	0.8	69	0.25
L6400 13500N	Soil		1.4	29.5	17.1	94	0.2	23.8	15.9	1228	3.22	172.8	3.7	8.6	3.1	27	0.3	1.2	0.9	74	0.32
L6400 13525N	Soil		0.7	16.5	9.9	94	<0.1	15.8	9.5	390	2.42	83.6	1.5	5.2	6.1	24	0.7	0.8	0.3	63	0.36
L6400 13550N	Soil		1.6	21.6	39.1	160	0.3	17.4	10.5	630	2.66	222.4	5.3	6.1	3.2	34	0.8	1.5	0.7	63	0.40
L6400 13575N	Soil		1.1	18.0	42.9	132	0.2	14.9	9.4	510	2.47	122.6	2.9	8.0	6.5	29	0.7	1.4	0.4	58	0.41
L6400 13600N	Soil		1.1	17.8	21.6	136	0.2	17.7	10.5	328	2.88	194.1	2.6	13.7	5.3	22	0.6	1.4	1.1	58	0.24
L6400 13625N	Soil		1.6	21.7	32.6	139	0.3	17.7	9.8	337	3.43	271.5	3.7	34.4	8.1	27	0.5	2.5	1.8	68	0.35
L6400 13650N	Soil		1.6	26.4	37.7	123	0.5	16.3	9.1	269	3.21	241.7	4.6	264.9	6.8	28	0.5	5.2	5.5	63	0.32
L6400 13675N	Soil		1.6	28.5	34.2	137	0.3	21.4	12.7	473	3.64	259.1	4.3	37.3	7.3	30	0.4	3.1	3.0	77	0.39
L6400 13700N	Soil		0.8	15.0	20.3	81	<0.1	17.9	9.6	328	2.40	53.7	1.3	9.8	5.4	21	0.6	0.9	0.6	59	0.31
L6400 13725N	Soil		1.5	12.8	14.5	57	0.1	10.0	4.8	210	2.29	60.1	0.6	13.0	1.8	10	0.2	1.0	0.7	67	0.09
L6400 13750N	Soil		1.6	25.8	17.4	61	0.2	18.9	9.8	309	3.04	62.0	1.3	570.6	3.8	22	0.5	1.5	4.8	64	0.19
L6400 13775N	Soil		1.9	32.5	27.3	98	0.2	20.4	11.8	432	3.33	143.7	3.5	78.0	6.0	32	0.6	2.3	7.7	67	0.26
L6400 13800N	Soil		0.9	25.6	18.1	71	0.1	18.4	9.6	454	2.47	40.2	2.7	39.7	5.4	31	0.4	1.2	2.8	60	0.38
L6400 13825N	Soil		0.7	23.4	11.6	60	<0.1	18.6	9.4	413	2.53	31.3	2.4	34.0	5.9	31	0.3	1.3	1.7	63	0.36
L6400 13850N	Soil		1.1	36.0	13.9	69	0.1	20.2	13.0	516	3.21	59.1	3.7	52.2	6.2	27	0.2	1.1	1.6	78	0.37
L6400 13875N	Soil		0.9	21.4	25.4	76	0.1	15.0	9.2	489	2.37	91.6	2.0	82.3	5.0	22	0.4	1.2	1.3	54	0.32
L6400 13900N	Soil		2.6	40.5	30.3	102	0.3	17.7	8.2	200	2.82	264.6	5.1	125.7	5.1	29	0.3	2.2	3.6	56	0.45
L6400 13925N	Soil		1.1	21.1	19.3	75	0.2	14.1	8.4	420	2.24	123.7	2.1	39.8	5.6	22	0.5	3.9	1.2	49	0.33
L6400 13950N	Soil		1.6	34.4	38.0	145	0.5	22.6	11.5	703	3.31	399.7	4.9	32.2	4.3	47	0.3	2.6	1.7	66	0.71
L6400 13975N	Soil		1.1	17.4	18.3	90	0.1	16.2	9.5	548	2.84	129.2	2.3	112.3	4.9	24	0.5	2.2	1.0	56	0.34

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6400 13250N	Soil	0.081	28	33	0.52	110	0.080	2	1.97	0.019	0.11	1.0	0.05	3.9	0.2	0.05	6	0.8
L6400 13275N	Soil	0.072	20	31	0.53	115	0.117	2	1.71	0.020	0.19	2.4	0.02	3.8	0.4	0.05	6	<0.5
L6400 13300N	Soil	0.073	19	32	0.55	108	0.095	1	1.74	0.017	0.13	1.2	0.05	3.4	0.2	0.06	6	<0.5
L6400 13325N	Soil	0.057	17	28	0.50	120	0.093	2	1.38	0.018	0.10	1.2	0.01	2.9	0.2	<0.05	5	0.6
L6400 13350N	Soil	0.073	17	23	0.39	117	0.060	2	1.22	0.016	0.08	1.0	0.01	2.4	0.2	0.05	4	<0.5
L6400 13375N	Soil	0.061	16	33	0.48	159	0.074	2	1.71	0.013	0.10	1.2	0.02	2.7	0.2	<0.05	6	<0.5
L6400 13400N	Soil	0.074	13	33	0.62	188	0.079	2	2.14	0.013	0.07	0.4	0.02	2.9	0.2	<0.05	7	0.5
L6400 13425N	Soil	0.066	12	37	0.59	212	0.086	2	2.07	0.016	0.07	0.3	0.02	3.3	0.2	<0.05	7	<0.5
L6400 13450N	Soil	0.068	13	35	0.52	153	0.069	2	1.98	0.014	0.06	0.4	0.02	3.0	0.2	<0.05	6	<0.5
L6400 13475N	Soil	0.074	15	35	0.50	155	0.067	2	1.99	0.014	0.05	1.0	0.03	3.1	0.2	<0.05	6	<0.5
L6400 13500N	Soil	0.077	19	38	0.57	232	0.069	2	2.27	0.019	0.06	0.3	0.03	4.2	0.2	<0.05	7	<0.5
L6400 13525N	Soil	0.079	13	26	0.47	138	0.109	1	1.46	0.029	0.08	0.5	0.02	2.5	0.1	<0.05	5	<0.5
L6400 13550N	Soil	0.083	20	32	0.52	207	0.066	2	2.02	0.022	0.09	0.3	0.03	3.5	0.2	<0.05	6	<0.5
L6400 13575N	Soil	0.076	19	28	0.49	149	0.110	1	1.46	0.022	0.12	0.8	0.01	3.5	0.2	<0.05	5	<0.5
L6400 13600N	Soil	0.062	13	30	0.49	152	0.084	2	1.91	0.017	0.09	0.9	0.04	3.2	0.2	<0.05	6	<0.5
L6400 13625N	Soil	0.083	20	32	0.62	200	0.105	3	2.01	0.017	0.12	0.3	0.03	4.4	0.3	<0.05	6	<0.5
L6400 13650N	Soil	0.081	22	29	0.57	231	0.083	4	2.07	0.017	0.10	0.3	0.03	4.4	0.3	0.07	6	0.8
L6400 13675N	Soil	0.056	22	35	0.61	310	0.102	3	2.21	0.020	0.12	0.3	0.03	4.5	0.2	0.06	7	<0.5
L6400 13700N	Soil	0.066	12	26	0.52	159	0.107	1	1.82	0.019	0.07	0.3	0.03	2.8	0.2	<0.05	5	<0.5
L6400 13725N	Soil	0.029	5	19	0.22	65	0.093	3	1.06	0.014	0.05	0.2	0.05	1.7	0.1	<0.05	7	<0.5
L6400 13750N	Soil	0.059	10	28	0.40	139	0.072	3	2.06	0.016	0.08	0.3	0.05	2.6	0.1	<0.05	6	<0.5
L6400 13775N	Soil	0.058	15	31	0.50	245	0.075	2	2.26	0.023	0.09	0.3	0.04	3.5	0.2	<0.05	6	<0.5
L6400 13800N	Soil	0.076	16	29	0.50	211	0.099	3	1.68	0.027	0.09	0.3	0.01	3.2	0.1	<0.05	5	<0.5
L6400 13825N	Soil	0.069	17	29	0.53	234	0.112	1	1.44	0.035	0.09	0.4	0.01	3.7	0.1	<0.05	5	0.6
L6400 13850N	Soil	0.084	18	31	0.69	314	0.103	<1	1.96	0.015	0.13	0.3	0.03	4.0	0.2	<0.05	6	<0.5
L6400 13875N	Soil	0.065	14	23	0.44	261	0.068	<1	1.46	0.019	0.09	0.3	0.01	2.4	0.1	<0.05	4	<0.5
L6400 13900N	Soil	0.072	22	27	0.51	202	0.049	1	1.92	0.016	0.09	0.3	0.03	3.4	0.2	0.06	6	0.6
L6400 13925N	Soil	0.066	15	20	0.40	193	0.062	<1	1.24	0.021	0.08	0.5	0.02	2.2	0.1	<0.05	4	<0.5
L6400 13950N	Soil	0.075	19	32	0.55	321	0.042	<1	2.31	0.024	0.09	0.2	0.04	3.8	0.2	0.07	6	0.6
L6400 13975N	Soil	0.071	13	24	0.45	245	0.058	<1	1.58	0.017	0.09	0.5	0.02	2.9	0.2	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6400 14000N	Soil		0.7	26.8	23.0	250	0.2	19.9	10.9	480	2.65	203.6	3.0	22.3	5.6	24	0.9	2.5	0.8	61	0.34
L10200 12500N	Soil		1.8	14.4	67.6	194	0.4	15.6	6.4	360	2.75	249.5	1.4	6.5	3.7	14	0.9	3.7	0.5	63	0.19
L10200 12525N	Soil		1.2	15.1	80.8	134	0.8	14.4	6.5	343	2.53	280.6	2.4	8.8	3.8	11	1.6	3.0	0.5	59	0.14
L10200 12575N	Soil		1.0	17.1	71.6	107	1.5	12.5	5.0	369	2.31	258.7	2.0	9.0	0.9	13	1.2	2.8	0.8	50	0.16
L10200 12625N	Soil		1.3	20.1	206.6	168	0.8	19.2	8.8	646	2.95	135.6	2.7	11.5	3.7	19	1.5	5.1	0.4	62	0.26
L10200 12975N	Soil		1.6	18.2	62.1	138	0.2	25.9	11.1	563	3.70	105.8	1.5	3.8	6.8	21	0.5	2.8	0.3	64	0.21
L10200 13025N	Soil		1.4	17.2	20.2	58	0.1	16.0	7.0	323	2.35	27.0	0.8	3.8	2.4	13	0.4	0.9	0.2	58	0.14
L9600 12675N	Soil		0.7	18.3	27.1	73	0.1	19.7	8.9	376	2.33	82.4	1.1	7.4	4.8	23	0.3	8.8	0.3	59	0.43
L9600 12700N	Soil		0.9	22.1	39.2	80	0.4	18.5	7.7	304	2.10	102.6	2.4	9.2	4.3	30	0.5	14.4	0.5	53	0.55
L9600 12850N	Soil		0.9	28.8	49.5	89	0.6	21.5	13.7	598	2.99	146.5	6.1	9.9	6.5	21	0.6	15.6	0.6	61	0.27
L9600 12875N	Soil		1.8	30.0	42.4	73	0.6	19.2	11.4	3502	2.29	132.3	6.3	13.8	2.9	15	3.6	14.1	0.6	53	0.16
L10000 12650N	Soil		1.1	16.9	242.9	164	1.6	23.8	12.3	527	3.01	157.7	0.9	4.2	3.9	18	1.6	10.3	0.4	62	0.25
L10000 12675N	Soil		1.3	13.6	44.8	86	0.1	14.6	5.5	345	2.50	110.1	0.8	12.9	3.8	11	0.3	6.2	0.4	79	0.13
L10000 12700N	Soil		0.7	14.0	53.2	112	0.2	21.6	10.2	521	2.56	100.2	1.5	7.4	5.5	18	0.7	4.9	0.3	56	0.31
L10000 12725N	Soil		1.0	13.1	37.4	79	0.2	16.7	5.8	386	2.19	88.4	1.1	5.7	1.7	15	0.5	3.7	0.3	56	0.19
L10000 12750N	Soil		1.0	23.7	35.8	96	0.1	27.1	11.4	666	2.89	145.8	1.5	31.7	3.5	18	0.4	4.8	0.4	67	0.32
L10000 12775N	Soil		0.7	6.0	6.7	35	<0.1	66.4	14.5	282	2.73	7.1	0.7	<0.5	5.8	11	0.4	0.6	<0.1	109	0.20
L10000 12800N	Soil		2.4	16.6	19.2	44	<0.1	14.8	5.0	183	2.84	63.2	0.6	4.1	4.0	8	0.2	3.7	0.4	121	0.07
L9200 12025N	Soil		1.9	30.1	19.8	84	0.2	23.7	9.0	360	3.02	208.1	1.1	5.5	0.9	13	0.4	3.0	0.2	80	0.13
L9800 12525N	Soil		0.7	23.6	78.3	317	0.5	24.1	10.4	937	2.84	397.7	3.1	15.6	7.4	24	1.9	21.2	0.5	59	0.36
L9800 12550N	Soil		0.9	30.1	155.5	235	0.9	24.6	11.7	925	2.95	278.4	3.6	13.5	6.5	21	2.2	34.8	0.6	60	0.31
L9800 12675N	Soil		1.1	42.3	250.9	490	5.2	21.3	9.5	1159	3.34	926.9	9.1	30.6	5.2	38	2.3	76.6	1.3	51	0.72

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

CERTIFICATE OF ANALYSIS SMI09000133.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6400 14000N	Soil	0.056	17	30	0.53	173	0.075	<1	1.49	0.019	0.07	0.2	0.02	4.1	0.1	<0.05	5	<0.5
L10200 12500N	Soil	0.046	12	26	0.37	77	0.061	1	1.33	0.009	0.08	0.2	0.06	2.1	0.1	<0.05	6	0.5
L10200 12525N	Soil	0.047	14	23	0.29	63	0.055	1	1.29	0.008	0.08	0.4	0.07	2.0	0.1	<0.05	5	<0.5
L10200 12575N	Soil	0.044	11	25	0.22	72	0.038	<1	1.38	0.010	0.05	0.2	0.08	1.5	0.1	<0.05	5	0.9
L10200 12625N	Soil	0.060	14	29	0.39	125	0.045	<1	1.53	0.010	0.07	0.1	0.05	2.2	0.1	<0.05	6	<0.5
L10200 12975N	Soil	0.062	16	34	0.55	118	0.078	<1	1.81	0.009	0.09	0.4	0.04	3.0	0.2	<0.05	7	<0.5
L10200 13025N	Soil	0.048	9	24	0.28	67	0.068	<1	1.07	0.013	0.07	0.2	0.03	1.8	<0.1	<0.05	6	<0.5
L9600 12675N	Soil	0.065	12	28	0.52	78	0.084	<1	1.11	0.021	0.08	0.9	0.02	2.4	<0.1	<0.05	4	<0.5
L9600 12700N	Soil	0.050	16	28	0.49	116	0.064	<1	1.29	0.017	0.06	0.9	0.03	2.7	0.1	<0.05	4	<0.5
L9600 12850N	Soil	0.074	32	37	0.53	141	0.046	<1	2.00	0.010	0.07	0.5	0.06	4.7	0.2	<0.05	6	0.7
L9600 12875N	Soil	0.083	29	30	0.31	184	0.036	<1	1.47	0.012	0.05	0.3	0.07	3.6	0.2	<0.05	5	0.8
L10000 12650N	Soil	0.055	12	35	0.50	75	0.078	<1	1.87	0.011	0.07	0.4	0.06	2.8	<0.1	<0.05	6	0.6
L10000 12675N	Soil	0.033	13	31	0.18	68	0.090	<1	0.96	0.008	0.06	0.3	0.05	1.7	<0.1	<0.05	7	<0.5
L10000 12700N	Soil	0.058	14	34	0.57	103	0.094	<1	1.73	0.013	0.10	0.9	0.04	2.9	0.2	<0.05	6	<0.5
L10000 12725N	Soil	0.047	11	25	0.34	83	0.061	<1	1.16	0.012	0.06	0.5	0.03	2.0	0.1	<0.05	5	<0.5
L10000 12750N	Soil	0.081	12	33	0.53	95	0.081	2	1.69	0.015	0.08	0.4	0.07	2.8	0.1	<0.05	6	0.7
L10000 12775N	Soil	0.029	6	168	1.35	213	0.374	<1	1.77	0.013	0.53	0.3	0.02	1.3	0.3	<0.05	8	<0.5
L10000 12800N	Soil	0.020	10	29	0.19	44	0.173	<1	1.08	0.006	0.04	0.2	0.02	1.7	0.1	<0.05	12	<0.5
L9200 12025N	Soil	0.075	8	34	0.35	101	0.045	<1	1.45	0.008	0.06	0.4	0.07	1.9	0.1	0.06	7	1.0
L9800 12525N	Soil	0.072	17	29	0.56	129	0.064	<1	1.59	0.013	0.08	0.2	0.02	2.9	0.1	<0.05	5	<0.5
L9800 12550N	Soil	0.086	15	31	0.50	118	0.065	<1	1.60	0.013	0.09	0.3	0.04	2.7	0.1	0.06	5	0.5
L9800 12675N	Soil	0.096	36	33	0.40	168	0.034	<1	1.96	0.014	0.12	0.2	0.09	3.9	0.2	0.10	5	0.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

QUALITY CONTROL REPORT SMI09000133.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
L7000 13000N	Soil		7.3	118.1	30.0	70	2.3	21.3	6.6	291	6.30	1225	3.3	126.1	4.1	22	0.2	5.0	24.6	120	0.24
REP L7000 13000N	QC		7.4	117.8	31.2	69	2.3	21.4	6.5	294	6.37	1314	3.3	106.2	4.1	23	0.3	5.3	24.8	123	0.24
L6800 12950N	Soil		1.0	67.1	9.0	41	0.2	14.7	4.9	165	2.66	19.2	4.0	122.3	16.3	25	<0.1	1.7	4.2	36	0.23
REP L6800 12950N	QC		1.1	67.3	9.2	38	0.2	14.4	4.9	165	2.63	20.3	4.0	154.8	16.5	25	<0.1	1.7	4.2	39	0.23
L6800 13400N	Soil		1.0	26.1	16.0	113	<0.1	21.9	10.8	480	2.72	61.9	2.7	4.7	5.0	22	0.5	0.8	0.4	66	0.32
REP L6800 13400N	QC		1.0	25.1	15.8	109	<0.1	22.2	10.8	494	2.74	61.4	2.7	24.6	5.0	22	0.5	0.9	0.4	68	0.33
L6800 13750N	Soil		0.8	16.6	43.5	119	0.2	12.2	7.7	595	2.32	50.9	3.1	2.6	7.1	20	0.5	1.3	0.2	42	0.33
REP L6800 13750N	QC		0.9	17.1	43.5	125	0.2	12.4	8.2	616	2.37	51.9	3.0	2.6	7.2	21	0.4	1.3	0.2	42	0.34
L6600 13100N	Soil		0.9	54.6	10.6	38	0.2	16.0	5.9	179	2.92	42.8	3.0	142.7	8.9	19	0.1	3.7	4.2	54	0.24
REP L6600 13100N	QC		1.0	53.7	10.3	39	0.2	15.7	5.7	179	2.90	42.8	2.9	291.0	9.0	19	0.1	3.7	4.1	55	0.26
L6600 13925N	Soil		1.2	16.3	36.7	181	0.5	14.5	9.4	338	2.75	253.5	2.0	32.7	5.5	18	0.7	2.8	1.3	58	0.33
REP L6600 13925N	QC		1.1	15.9	36.7	180	0.4	13.4	9.4	337	2.72	249.5	2.0	35.0	5.6	19	0.8	2.9	1.1	59	0.32
L6400 13225N	Soil		0.9	32.7	11.6	49	0.2	18.2	9.3	279	2.89	28.9	4.3	46.3	9.4	24	0.2	2.0	3.0	56	0.30
REP L6400 13225N	QC		0.9	33.2	11.0	48	0.1	17.4	9.4	284	2.90	28.0	4.0	56.3	8.5	23	0.3	2.0	2.6	55	0.30
L6400 13575N	Soil		1.1	18.0	42.9	132	0.2	14.9	9.4	510	2.47	122.6	2.9	8.0	6.5	29	0.7	1.4	0.4	58	0.41
REP L6400 13575N	QC		1.1	16.8	43.6	125	0.2	13.7	8.7	493	2.33	120.1	2.8	9.3	6.5	27	0.7	1.4	0.4	56	0.39
L9600 12675N	Soil		0.7	18.3	27.1	73	0.1	19.7	8.9	376	2.33	82.4	1.1	7.4	4.8	23	0.3	8.8	0.3	59	0.43
REP L9600 12675N	QC		0.7	18.4	28.1	72	0.1	18.9	8.9	381	2.35	82.5	1.1	5.9	4.7	23	0.3	9.0	0.4	58	0.42
L10000 12650N	Soil		1.1	16.9	242.9	164	1.6	23.8	12.3	527	3.01	157.7	0.9	4.2	3.9	18	1.6	10.3	0.4	62	0.25
REP L10000 12650N	QC		1.0	16.5	242.0	166	1.6	23.2	12.1	515	2.93	158.3	0.9	3.6	4.0	18	1.6	10.1	0.4	61	0.26
Reference Materials																					
STD DS7	Standard		20.4	108.6	62.7	383	0.8	57.0	9.9	645	2.51	50.1	4.4	76.1	4.0	70	5.5	4.8	4.2	88	1.01
STD DS7	Standard		20.6	115.4	60.2	377	0.8	58.4	9.7	633	2.40	48.6	4.3	69.6	3.9	69	6.1	5.1	4.0	87	0.98
STD DS7	Standard		20.6	114.3	58.9	372	0.8	56.6	9.6	627	2.36	48.8	4.2	84.0	3.7	65	5.8	4.9	4.0	86	0.94
STD DS7	Standard		21.8	114.0	65.1	417	0.9	55.9	9.8	661	2.49	52.2	4.9	64.3	4.6	82	6.9	5.9	4.5	91	1.00
STD DS7	Standard		20.7	106.7	63.5	391	0.8	58.8	10.4	631	2.56	51.7	4.9	61.1	4.4	78	6.1	5.3	4.4	86	0.95
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

QUALITY CONTROL REPORT SMI09000133.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
L7000 13000N	Soil	0.113	17	57	0.77	331	0.086	<1	2.29	0.014	0.15	0.5	0.07	5.2	0.3	0.08	8	3.0
REP L7000 13000N	QC	0.117	18	60	0.77	334	0.091	<1	2.33	0.015	0.16	0.5	0.08	5.6	0.2	0.07	8	3.0
L6800 12950N	Soil	0.053	27	26	0.53	245	0.076	<1	1.99	0.020	0.20	0.7	0.03	3.7	0.2	<0.05	6	0.8
REP L6800 12950N	QC	0.053	28	26	0.52	249	0.079	<1	1.99	0.019	0.20	0.7	0.03	3.8	0.2	<0.05	6	0.8
L6800 13400N	Soil	0.072	18	30	0.58	183	0.077	2	2.06	0.015	0.07	0.4	0.04	3.2	0.2	<0.05	6	<0.5
REP L6800 13400N	QC	0.070	18	30	0.57	184	0.079	1	2.06	0.014	0.07	0.5	0.03	3.2	0.2	<0.05	6	<0.5
L6800 13750N	Soil	0.064	23	18	0.40	192	0.045	1	1.24	0.017	0.10	0.4	0.01	3.0	0.2	<0.05	4	<0.5
REP L6800 13750N	QC	0.067	23	18	0.40	191	0.045	<1	1.23	0.016	0.09	0.3	0.02	3.2	0.2	<0.05	4	<0.5
L6600 13100N	Soil	0.074	21	26	0.57	151	0.076	<1	1.73	0.011	0.20	5.4	0.02	3.0	0.3	<0.05	6	<0.5
REP L6600 13100N	QC	0.072	21	26	0.57	148	0.080	<1	1.76	0.011	0.20	4.8	0.02	3.0	0.3	<0.05	6	<0.5
L6600 13925N	Soil	0.074	12	24	0.49	198	0.072	<1	1.73	0.014	0.08	0.5	0.03	3.0	0.2	<0.05	5	<0.5
REP L6600 13925N	QC	0.072	12	25	0.46	195	0.076	<1	1.66	0.015	0.08	0.5	0.04	2.7	0.2	<0.05	5	<0.5
L6400 13225N	Soil	0.078	22	29	0.48	105	0.104	2	1.34	0.020	0.11	1.3	0.02	3.7	0.2	<0.05	4	<0.5
REP L6400 13225N	QC	0.075	20	30	0.45	100	0.099	1	1.30	0.018	0.11	1.1	0.02	3.7	0.2	<0.05	4	<0.5
L6400 13575N	Soil	0.076	19	28	0.49	149	0.110	1	1.46	0.022	0.12	0.8	0.01	3.5	0.2	<0.05	5	<0.5
REP L6400 13575N	QC	0.069	18	27	0.48	147	0.100	1	1.43	0.024	0.11	0.7	0.01	3.4	0.2	<0.05	5	0.6
L9600 12675N	Soil	0.065	12	28	0.52	78	0.084	<1	1.11	0.021	0.08	0.9	0.02	2.4	<0.1	<0.05	4	<0.5
REP L9600 12675N	QC	0.063	12	28	0.51	77	0.082	<1	1.13	0.021	0.08	0.9	0.02	2.4	<0.1	<0.05	4	<0.5
L10000 12650N	Soil	0.055	12	35	0.50	75	0.078	<1	1.87	0.011	0.07	0.4	0.06	2.8	<0.1	<0.05	6	0.6
REP L10000 12650N	QC	0.054	12	35	0.51	74	0.076	<1	1.90	0.011	0.07	0.4	0.06	2.7	0.1	<0.05	6	<0.5
Reference Materials																		
STD DS7	Standard	0.075	13	245	1.05	416	0.120	35	1.08	0.111	0.49	3.8	0.20	2.6	4.2	0.16	5	3.9
STD DS7	Standard	0.074	13	232	1.05	396	0.114	40	1.03	0.098	0.47	3.7	0.18	2.6	3.9	0.18	5	4.1
STD DS7	Standard	0.072	12	210	1.03	402	0.113	40	1.05	0.102	0.46	3.5	0.18	2.4	4.0	0.22	5	2.9
STD DS7	Standard	0.076	15	230	1.07	425	0.146	37	1.15	0.119	0.51	3.8	0.22	3.4	4.1	0.19	5	3.8
STD DS7	Standard	0.078	13	222	1.01	415	0.131	42	1.01	0.106	0.49	3.8	0.19	3.2	3.9	0.19	5	3.3
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

QUALITY CONTROL REPORT SMI09000133.1

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: August 20, 2009

QUALITY CONTROL REPORT SMI09000133.1

		1DX15 P % 0.001	1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 26, 2009
Report Date: September 04, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000171.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC09-15
P.O. Number
Number of Samples: 25

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	25	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	25	Dry at 60C			VAN
1DX15	25	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 04, 2009

CERTIFICATE OF ANALYSIS SMI09000171.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
CRCX07	Soil		2.7	14.1	30.2	135	0.3	14.4	7.8	454	2.51	39.4	2.2	58.0	3.5	29	0.4	1.0	0.5	58	0.40
CRCX08	Soil		1.9	16.5	53.1	150	0.3	15.5	14.0	2238	2.78	72.8	2.8	11.5	3.4	19	1.2	1.0	0.6	60	0.23
CRCX09	Soil		12.9	87.5	15.5	7	0.3	1.1	2.4	21	7.07	1415	2.2	34.8	26.4	18	<0.1	8.6	0.5	38	0.05
CRCX10	Soil		12.7	330.3	20.0	9	0.1	2.1	1.8	44	7.52	480.1	2.0	9.3	25.6	33	<0.1	7.4	0.3	78	0.02
JPCX01	Soil		0.7	26.5	12.5	72	<0.1	20.2	11.0	355	3.10	8.9	2.9	1.7	7.5	35	0.2	0.7	0.2	88	0.29
JPCX02	Soil		1.0	25.2	9.0	75	<0.1	22.2	11.6	361	3.89	27.6	2.4	3.9	8.1	44	0.2	1.0	0.2	97	0.48
JPCX03	Soil		0.8	25.2	46.4	198	<0.1	17.4	13.0	692	4.05	64.5	5.6	1.8	11.4	52	0.6	2.2	0.2	94	0.42
JPCX04	Soil		1.3	27.8	9.5	83	<0.1	22.5	16.3	812	3.69	7.8	5.2	1.7	7.1	48	0.1	0.7	0.2	97	0.45
JPCX05	Soil		0.7	24.2	5.8	66	<0.1	19.6	12.6	534	3.30	6.1	4.3	2.1	9.4	32	0.2	0.4	0.1	108	0.47
JPCX06	Soil		1.6	25.6	8.0	76	<0.1	26.0	15.6	677	3.55	9.8	2.5	6.9	6.2	24	0.3	0.4	0.1	95	0.31
JPCX07	Soil		1.0	20.8	8.3	77	<0.1	22.3	12.9	666	3.19	7.9	2.1	2.3	4.2	22	0.3	0.6	0.1	88	0.32
JPCX08	Soil		0.8	24.4	6.9	72	<0.1	21.9	13.6	517	3.24	7.0	2.7	2.6	7.3	27	0.2	0.4	<0.1	93	0.41
JPCX09	Soil		1.2	28.5	8.7	74	<0.1	25.3	16.0	780	3.57	18.4	4.9	2.6	8.7	51	0.3	0.6	0.1	92	0.66
JPCX10	Soil		1.1	38.3	10.5	81	0.1	24.1	15.9	354	3.89	12.8	6.7	2.8	10.7	38	0.2	0.7	0.3	101	0.53
JPCX11	Soil		1.5	17.7	9.1	52	<0.1	15.2	10.9	332	2.27	7.4	2.8	4.2	6.8	23	0.1	1.1	0.3	90	0.36
JPCX12	Soil		0.8	25.1	7.4	60	<0.1	24.9	11.3	303	2.94	6.3	1.2	1.7	5.1	26	0.1	0.4	0.1	78	0.37
JPCX13	Soil		2.1	27.0	9.2	58	0.1	16.8	13.3	960	3.01	5.6	6.4	1.5	3.1	46	0.2	0.9	0.4	65	0.59
JPCX14	Soil		8.9	14.0	6.7	21	0.2	7.8	28.0	1946	14.60	187.2	3.0	4.0	5.1	22	0.2	2.3	0.4	132	0.31
JPCX15	Soil		0.6	11.8	10.8	63	<0.1	13.1	10.6	295	2.77	11.7	1.6	2.1	7.3	19	<0.1	1.6	0.2	76	0.33
JPCX16	Soil		1.9	31.2	8.3	69	0.1	21.8	13.8	588	3.63	6.1	4.7	5.2	10.6	31	0.3	0.5	0.4	97	0.52
JPCX17	Soil		1.7	32.6	6.8	57	<0.1	21.7	10.2	340	3.35	8.9	4.5	2.7	6.2	37	0.1	0.5	0.2	87	0.46
JPCX18	Soil		0.8	33.6	6.9	67	<0.1	20.9	13.6	383	3.66	5.9	3.0	1.2	6.9	35	0.2	0.4	0.1	103	0.57
JPCX19	Soil		1.2	21.1	6.7	57	<0.1	18.6	12.4	532	3.09	6.3	3.0	10.5	10.6	26	0.2	0.6	0.1	96	0.49
JPCX20	Soil		1.1	21.7	7.6	57	<0.1	16.8	11.9	530	3.11	6.6	2.1	1.5	5.5	26	0.2	0.6	0.2	93	0.39
JPCX21	Soil		0.7	20.9	6.1	51	<0.1	20.5	10.2	427	2.79	11.9	1.4	2.6	5.7	25	0.3	0.9	0.3	82	0.42

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 04, 2009

CERTIFICATE OF ANALYSIS SMI09000171.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
CRCX07	Soil	0.065	10	27	0.55	210	0.062	1	1.60	0.009	0.06	0.4	0.03	2.7	0.1	<0.05	5	<0.5
CRCX08	Soil	0.066	15	31	0.51	215	0.055	<1	1.82	0.009	0.05	0.3	0.03	3.3	0.2	<0.05	5	<0.5
CRCX09	Soil	0.144	26	5	0.14	162	0.015	<1	0.66	0.024	0.53	<0.1	0.20	5.2	2.2	1.37	2	5.8
CRCX10	Soil	0.103	83	7	0.56	91	0.089	4	1.10	0.053	1.47	<0.1	0.21	11.3	8.4	2.30	5	9.5
JPCX01	Soil	0.058	19	38	0.69	237	0.124	2	2.51	0.011	0.10	0.1	0.02	5.1	0.3	<0.05	7	0.6
JPCX02	Soil	0.105	18	44	0.77	279	0.136	1	2.35	0.016	0.15	0.2	0.04	5.9	0.3	<0.05	7	<0.5
JPCX03	Soil	0.078	22	33	0.71	500	0.117	1	2.47	0.013	0.20	0.2	0.06	7.7	0.4	<0.05	7	<0.5
JPCX04	Soil	0.085	20	38	0.76	361	0.141	2	2.39	0.023	0.15	0.2	0.04	5.1	0.4	<0.05	7	0.8
JPCX05	Soil	0.100	17	36	0.69	265	0.144	1	1.72	0.028	0.14	0.2	0.02	3.8	0.3	<0.05	5	<0.5
JPCX06	Soil	0.081	12	37	0.68	258	0.124	2	2.18	0.015	0.11	0.2	0.05	3.5	0.2	<0.05	6	0.5
JPCX07	Soil	0.076	11	34	0.62	243	0.112	2	1.84	0.017	0.10	0.2	0.04	3.2	0.2	<0.05	6	<0.5
JPCX08	Soil	0.088	14	34	0.73	272	0.148	1	1.93	0.029	0.14	0.2	0.02	3.8	0.2	<0.05	6	<0.5
JPCX09	Soil	0.100	19	35	0.76	376	0.113	1	1.99	0.028	0.13	0.1	0.06	5.8	0.3	<0.05	6	0.6
JPCX10	Soil	0.095	25	40	0.81	367	0.141	1	2.13	0.021	0.14	0.2	0.07	7.9	0.3	<0.05	6	<0.5
JPCX11	Soil	0.075	15	34	0.67	209	0.092	1	2.06	0.013	0.08	0.2	0.05	4.8	0.2	<0.05	6	0.5
JPCX12	Soil	0.086	12	36	0.69	200	0.138	2	2.19	0.014	0.12	0.1	0.02	3.6	0.2	<0.05	6	<0.5
JPCX13	Soil	0.086	20	23	0.62	343	0.043	1	2.06	0.014	0.06	0.1	0.09	4.1	0.3	0.07	6	<0.5
JPCX14	Soil	0.115	13	26	0.19	226	0.062	2	1.18	0.011	0.04	0.3	0.08	3.1	0.2	0.15	5	0.9
JPCX15	Soil	0.075	12	29	0.66	233	0.138	1	2.02	0.016	0.14	0.4	0.06	3.9	0.4	<0.05	7	0.7
JPCX16	Soil	0.095	22	39	0.73	360	0.152	1	1.99	0.028	0.25	0.2	0.03	6.3	0.4	<0.05	6	0.6
JPCX17	Soil	0.086	20	39	0.70	434	0.148	1	2.42	0.021	0.17	0.3	0.03	5.6	0.2	<0.05	6	<0.5
JPCX18	Soil	0.104	16	41	0.83	514	0.183	2	1.99	0.031	0.33	0.2	0.02	5.8	0.3	<0.05	6	<0.5
JPCX19	Soil	0.100	17	33	0.64	226	0.145	1	1.45	0.030	0.18	0.6	0.01	3.0	0.3	<0.05	5	<0.5
JPCX20	Soil	0.087	12	33	0.65	271	0.144	1	1.85	0.018	0.16	0.3	0.04	3.2	0.3	<0.05	6	<0.5
JPCX21	Soil	0.094	12	30	0.60	246	0.119	2	1.49	0.021	0.12	0.3	0.02	2.8	0.2	<0.05	4	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 04, 2009

QUALITY CONTROL REPORT SMI09000171.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
JPCX03	Soil		0.8	25.2	46.4	198	<0.1	17.4	13.0	692	4.05	64.5	5.6	1.8	11.4	52	0.6	2.2	0.2	94	0.42
REP JPCX03	QC		0.8	26.1	45.6	202	<0.1	17.0	13.1	707	4.10	65.5	5.6	1.6	11.3	54	0.7	2.1	0.2	95	0.42
Reference Materials																					
STD DS7	Standard		21.7	107.4	70.0	405	0.8	58.3	10.2	625	2.53	52.2	4.9	63.5	4.3	71	6.5	5.5	4.7	86	0.97
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 04, 2009

QUALITY CONTROL REPORT SMI09000171.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
JPCX03	Soil	0.078	22	33	0.71	500	0.117	1	2.47	0.013	0.20	0.2	0.06	7.7	0.4	<0.05	7	<0.5
REP JPCX03	QC	0.078	23	34	0.74	521	0.116	<1	2.51	0.013	0.21	0.2	0.05	7.8	0.4	<0.05	7	<0.5
Reference Materials																		
STD DS7	Standard	0.077	13	195	1.03	415	0.120	40	1.01	0.085	0.42	4.1	0.18	2.3	4.4	0.21	5	4.0
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: August 31, 2009
Report Date: September 14, 2009
Page: 1 of 4

CERTIFICATE OF ANALYSIS SMI09000183.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC09-17
P.O. Number
Number of Samples: 70

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	70	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	70	Dry at 60C			SMI
1DX15	70	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

CERTIFICATE OF ANALYSIS SMI09000183.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L10400 11425N	Soil		83.9	530.4	25.6	64	0.2	5.3	5.4	142	4.25	13.6	11.1	70.1	21.5	16	0.2	1.0	0.8	44	0.18
L10400 11450N	Soil		32.4	255.0	22.4	75	0.2	7.5	10.9	385	3.99	23.2	6.2	110.6	15.7	21	0.3	1.5	0.4	56	0.28
L10400 11475N	Soil		8.1	79.4	26.3	101	0.2	12.9	12.6	629	3.19	48.5	3.2	18.5	6.8	31	0.5	1.9	0.6	65	0.38
L10400 11500N	Soil		24.2	295.6	23.2	92	0.3	11.5	9.6	549	3.83	42.3	5.7	48.1	13.2	25	0.3	1.9	0.4	65	0.30
L10400 11525N	Soil		12.7	159.9	21.7	91	0.4	13.3	8.8	605	3.06	48.7	5.4	20.0	7.7	30	0.3	1.9	0.4	63	0.38
L10400 11550N	Soil		5.8	74.5	21.8	130	0.2	16.1	8.7	557	2.95	80.6	3.2	11.7	7.0	31	0.3	2.4	0.4	68	0.38
L10400 11575N	Soil		22.4	319.2	15.2	82	0.2	5.9	4.0	249	2.38	27.6	6.6	56.0	27.8	19	0.1	1.2	0.2	53	0.25
L10400 11600N	Soil		3.2	43.2	18.8	163	0.3	19.5	8.2	427	2.62	153.9	2.7	11.7	5.6	32	0.3	2.9	0.4	69	0.42
L10400 11625N	Soil		2.0	33.1	26.3	228	0.4	23.3	10.1	765	2.97	356.0	4.3	9.1	4.1	28	0.4	4.7	0.4	68	0.36
L10400 11650N	Soil		1.6	25.6	24.4	170	0.3	21.4	9.8	959	2.72	211.3	2.7	13.1	4.4	28	0.5	4.8	0.4	66	0.41
L10400 11675N	Soil		1.5	33.0	33.4	177	0.4	23.5	14.2	917	2.90	165.8	3.4	15.5	6.0	29	0.6	5.8	0.5	72	0.47
L10400 11700N	Soil		1.5	26.3	38.6	206	0.7	18.8	8.5	454	2.70	178.0	4.3	22.5	4.1	31	0.6	6.2	0.6	69	0.44
L10400 11725N	Soil		3.7	45.3	37.2	179	0.6	17.1	10.0	905	2.98	248.5	4.1	24.9	4.9	31	0.9	5.5	0.6	69	0.44
L10400 11750N	Soil		2.3	45.1	32.2	209	0.3	17.1	11.1	1023	2.92	151.1	3.2	31.8	6.3	35	1.1	5.6	0.6	63	0.48
L10400 11775N	Soil		3.0	62.4	47.4	230	0.9	18.4	9.1	818	2.67	165.3	7.1	25.8	4.1	36	0.8	6.8	0.7	60	0.48
L10400 11800N	Soil		2.0	31.5	51.0	227	0.8	19.9	13.0	2280	2.95	215.0	5.2	12.9	5.9	30	1.4	7.7	0.7	62	0.48
L10400 11825N	Soil		0.8	19.1	42.5	166	0.4	16.0	8.6	492	2.59	110.0	3.9	11.7	7.2	27	0.5	3.6	1.0	61	0.43
L10400 11850N	Soil		1.6	32.2	48.6	211	0.3	18.4	8.3	318	4.34	448.3	7.6	9.1	12.5	25	0.8	3.5	1.0	66	0.40
L10400 11875N	Soil		1.3	23.2	34.9	175	0.2	14.1	9.9	1108	2.37	159.0	3.0	18.3	7.6	22	0.9	3.9	0.6	47	0.40
L10400 11925N	Soil		0.6	30.7	80.7	247	0.6	16.3	9.6	604	2.54	219.7	3.3	17.4	7.3	30	1.5	4.4	1.0	54	0.53
L10400 11950N	Soil		1.1	20.3	78.3	336	0.7	18.2	14.0	3684	3.28	347.8	3.3	20.5	8.4	24	1.8	7.1	0.7	58	0.39
L10400 11975N	Soil		0.7	32.2	81.4	244	0.7	20.4	9.4	496	2.58	217.2	4.1	34.4	8.3	24	1.3	8.7	0.9	62	0.39
L10400 12000N	Soil		0.9	27.4	73.7	330	0.5	20.1	9.1	630	2.84	193.7	3.1	15.4	7.2	29	1.1	13.8	0.8	63	0.42
L10400 12025N	Soil		0.6	32.2	89.0	323	0.8	20.4	7.9	415	2.58	162.8	4.8	15.2	8.5	26	1.6	10.2	0.8	61	0.41
L10400 12050N	Soil		1.0	29.5	87.8	398	0.5	18.5	9.0	668	2.74	279.5	3.7	13.3	5.2	31	1.6	10.4	0.8	52	0.44
L10400 12075N	Soil		0.7	18.6	88.7	459	0.3	18.5	9.3	709	2.81	334.9	2.1	12.1	6.6	24	1.3	9.4	0.8	62	0.36
L10400 12100N	Soil		0.7	20.7	93.3	286	0.3	15.8	9.6	816	2.67	297.6	2.0	16.2	8.6	25	1.9	9.3	0.9	55	0.37
L10400 12125N	Soil		0.5	22.2	256.6	307	1.2	14.2	4.6	186	2.57	647.6	5.4	22.7	11.3	21	1.1	14.6	1.3	65	0.33
L10400 12150N	Soil		0.8	29.6	150.7	322	1.2	18.2	8.4	517	2.78	245.7	7.8	18.8	9.7	22	1.3	9.7	1.1	60	0.33
L10400 12175N	Soil		1.0	33.7	147.3	284	1.2	16.8	11.4	505	3.63	314.8	8.8	135.7	13.5	21	1.4	9.9	2.4	60	0.30

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

CERTIFICATE OF ANALYSIS SMI09000183.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L10400 11425N	Soil	0.066	25	6	0.34	218	0.011	2	1.12	0.007	0.13	0.2	<0.01	2.9	0.2	<0.05	3	1.1
L10400 11450N	Soil	0.059	20	11	0.40	238	0.026	<1	1.24	0.008	0.11	0.3	0.02	2.6	0.2	0.05	5	0.7
L10400 11475N	Soil	0.067	14	25	0.56	279	0.074	2	1.56	0.012	0.09	0.6	0.03	2.9	0.2	<0.05	6	0.7
L10400 11500N	Soil	0.065	16	21	0.53	218	0.054	2	1.67	0.010	0.10	0.3	0.01	3.3	0.2	<0.05	6	0.5
L10400 11525N	Soil	0.065	15	22	0.49	200	0.055	<1	1.59	0.011	0.09	0.3	0.04	3.2	0.2	0.05	6	0.5
L10400 11550N	Soil	0.051	13	26	0.55	195	0.077	2	1.72	0.011	0.10	0.5	0.03	3.3	0.2	<0.05	6	<0.5
L10400 11575N	Soil	0.035	28	10	0.52	169	0.056	<1	2.00	0.008	0.17	0.1	0.01	5.2	0.1	<0.05	6	0.6
L10400 11600N	Soil	0.059	13	32	0.59	219	0.096	2	1.75	0.014	0.12	0.4	0.02	3.5	0.2	<0.05	6	<0.5
L10400 11625N	Soil	0.061	15	37	0.58	254	0.089	3	1.81	0.015	0.11	0.3	0.04	4.3	0.2	<0.05	6	0.9
L10400 11650N	Soil	0.070	14	35	0.56	225	0.095	2	1.70	0.015	0.11	0.3	0.03	3.5	0.1	<0.05	5	0.7
L10400 11675N	Soil	0.077	19	38	0.64	258	0.116	2	1.95	0.016	0.11	0.3	0.03	5.2	0.2	<0.05	6	<0.5
L10400 11700N	Soil	0.071	20	34	0.57	295	0.086	2	1.97	0.014	0.09	0.3	0.04	4.1	0.2	<0.05	6	0.6
L10400 11725N	Soil	0.068	21	30	0.51	292	0.077	2	1.71	0.012	0.09	0.4	0.04	3.8	0.2	<0.05	5	0.7
L10400 11750N	Soil	0.076	22	32	0.60	252	0.106	2	1.70	0.014	0.12	0.4	0.02	3.7	0.2	<0.05	6	<0.5
L10400 11775N	Soil	0.083	24	33	0.53	268	0.064	1	1.89	0.014	0.08	0.4	0.06	4.2	0.2	<0.05	5	0.7
L10400 11800N	Soil	0.081	24	34	0.53	236	0.093	3	1.84	0.016	0.11	0.5	0.05	4.9	0.2	<0.05	6	0.6
L10400 11825N	Soil	0.060	21	32	0.58	171	0.104	2	1.77	0.012	0.10	0.5	0.05	4.7	0.2	<0.05	6	<0.5
L10400 11850N	Soil	0.077	37	36	0.56	140	0.103	<1	1.73	0.012	0.11	0.6	0.04	6.4	0.3	<0.05	6	0.6
L10400 11875N	Soil	0.070	21	23	0.47	123	0.094	<1	1.18	0.012	0.12	1.0	0.03	3.6	0.2	<0.05	4	0.7
L10400 11925N	Soil	0.077	22	33	0.52	131	0.094	1	1.63	0.014	0.11	0.4	0.05	4.7	0.2	<0.05	5	0.6
L10400 11950N	Soil	0.078	27	30	0.49	208	0.085	<1	1.59	0.012	0.08	0.3	0.04	3.8	0.2	<0.05	5	0.6
L10400 11975N	Soil	0.068	25	35	0.54	153	0.093	2	1.77	0.012	0.10	0.2	0.04	5.1	0.2	<0.05	6	<0.5
L10400 12000N	Soil	0.066	20	37	0.62	161	0.113	2	1.83	0.013	0.12	0.4	0.03	4.7	0.2	<0.05	6	<0.5
L10400 12025N	Soil	0.065	28	37	0.61	182	0.107	2	1.91	0.012	0.12	0.4	0.04	5.5	0.2	<0.05	6	0.6
L10400 12050N	Soil	0.070	25	29	0.50	171	0.078	2	1.64	0.014	0.11	0.3	0.04	3.8	0.2	0.06	6	0.8
L10400 12075N	Soil	0.049	17	35	0.61	132	0.113	2	1.70	0.013	0.10	0.4	0.02	3.5	0.2	<0.05	6	<0.5
L10400 12100N	Soil	0.064	19	27	0.51	132	0.110	1	1.26	0.016	0.11	0.3	0.02	3.0	0.2	<0.05	5	<0.5
L10400 12125N	Soil	0.059	24	33	0.51	101	0.086	<1	1.82	0.012	0.10	0.2	0.05	4.3	0.2	<0.05	6	<0.5
L10400 12150N	Soil	0.060	36	36	0.57	134	0.091	<1	2.09	0.013	0.10	0.2	0.06	5.0	0.2	<0.05	6	0.6
L10400 12175N	Soil	0.064	40	35	0.54	127	0.085	2	2.04	0.011	0.10	0.2	0.05	4.7	0.2	<0.05	6	0.9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

CERTIFICATE OF ANALYSIS SMI09000183.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L10400 12200N	Soil		0.9	31.4	160.7	283	1.4	15.6	6.3	364	3.02	360.7	6.0	52.3	12.0	23	1.1	10.8	3.7	54	0.37
L10400 12225N	Soil		0.7	28.4	167.6	267	2.3	13.3	10.4	789	2.08	315.3	9.3	62.3	6.4	23	2.3	10.0	3.5	42	0.34
L10400 12250N	Soil		0.7	32.9	113.7	276	1.5	18.1	6.0	268	2.53	163.8	6.2	51.1	9.1	20	1.6	7.9	2.0	52	0.31
L10400 12275N	Soil		1.0	34.8	160.3	290	1.8	17.1	9.4	513	3.67	404.5	8.5	35.1	11.2	22	1.8	10.1	1.2	59	0.31
L10400 12300N	Soil		1.1	20.2	251.8	280	1.6	16.9	8.0	380	2.84	467.5	5.3	40.5	11.2	23	1.7	10.4	1.8	53	0.36
L10400 12325N	Soil		1.2	33.3	163.8	303	2.0	20.0	9.6	518	3.15	295.5	10.0	60.5	10.8	23	1.5	6.6	2.6	60	0.35
L10400 12350N	Soil		0.9	25.3	185.3	354	1.1	18.7	9.3	542	2.90	307.9	5.2	54.8	10.7	26	1.8	5.9	2.0	53	0.39
L10400 12375N	Soil		1.2	36.8	255.0	402	2.9	20.7	11.0	1251	3.06	512.6	7.1	46.8	4.7	28	4.3	6.3	2.1	57	0.43
L10400 12400N	Soil		1.1	30.4	381.2	584	2.5	21.6	9.7	740	3.30	538.7	9.2	62.1	6.5	28	3.6	6.7	1.5	54	0.46
L10400 12425N	Soil		0.9	26.6	342.2	505	1.8	23.4	9.7	732	3.39	678.2	6.6	32.6	9.7	28	2.4	9.2	2.4	57	0.38
L10400 12450N	Soil		1.0	25.5	260.5	498	1.4	24.7	10.0	767	3.01	754.8	8.0	42.0	11.2	26	3.2	7.0	1.5	54	0.41
L10400 12475N	Soil		0.8	19.9	506.7	347	2.4	16.9	8.0	621	2.75	689.1	4.6	48.1	12.4	26	2.9	10.6	2.2	49	0.37
L10400 12500N	Soil		0.9	22.2	509.2	464	2.3	20.2	11.2	969	3.33	1060	5.0	60.3	9.1	21	3.1	10.0	3.5	53	0.29
L10400 12525N	Soil		0.8	27.0	166.4	845	0.9	25.4	11.8	900	2.85	475.5	6.4	22.9	10.6	30	3.8	12.5	0.8	58	0.46
L10400 12550N	Soil		1.0	33.8	350.8	495	2.4	27.3	12.0	1156	3.84	709.4	7.9	21.7	6.4	37	3.5	7.2	0.9	67	0.63
L10400 12575N	Soil		0.8	17.5	128.3	289	0.5	19.4	10.6	868	2.75	339.9	2.7	15.7	8.9	25	2.0	6.3	0.4	55	0.43
L10400 12600N	Soil		1.4	21.9	146.7	230	1.3	18.0	12.3	952	3.07	396.4	5.5	18.1	3.6	20	1.8	8.9	0.3	55	0.24
L10400 12625N	Soil		0.9	20.0	92.7	186	0.4	20.7	10.0	754	2.71	269.4	2.8	14.3	8.0	30	1.0	6.2	1.4	58	0.50
L10400 12650N	Soil		1.4	29.3	80.3	208	1.1	25.5	9.9	764	3.17	274.7	6.9	10.1	4.8	29	0.7	7.2	0.4	64	0.46
L10400 12675N	Soil		0.9	21.0	64.3	149	0.2	20.5	9.8	518	2.86	103.6	5.2	5.1	5.2	22	0.8	28.6	0.4	60	0.28
L10400 12700N	Soil		1.0	22.4	45.2	161	0.2	21.0	16.1	785	4.21	117.8	2.5	5.4	7.5	25	0.6	4.0	0.3	86	0.56
L10400 12725N	Soil		1.5	20.7	41.0	91	0.4	21.2	10.6	538	2.90	70.6	2.9	4.4	3.6	22	0.6	2.1	0.4	69	0.28
L10400 12750N	Soil		1.1	17.7	8.5	34	0.2	9.8	3.6	108	1.48	8.0	0.8	2.8	0.4	15	0.3	0.7	0.2	35	0.15
L10400 12775N	Soil		1.2	22.1	75.9	136	0.3	23.8	11.6	600	3.03	111.0	3.1	3.2	7.0	25	0.6	3.4	0.3	63	0.44
L10400 12800N	Soil		1.2	25.7	57.6	128	0.1	27.2	13.0	699	3.14	83.2	2.6	3.3	6.8	20	0.7	2.7	0.5	68	0.35
L10400 12825N	Soil		2.1	21.8	26.4	81	0.2	22.7	9.5	557	3.54	36.1	1.6	3.3	3.9	15	0.5	1.2	0.3	75	0.20
L10400 12850N	Soil		1.7	18.3	14.1	85	<0.1	20.2	8.3	278	3.59	16.2	0.9	2.6	2.3	13	0.6	0.9	0.3	82	0.13
L10400 12875N	Soil		2.1	22.4	115.4	147	0.8	21.8	8.1	344	3.07	128.8	1.3	3.6	1.0	18	0.7	5.5	0.5	67	0.16
L10400 12900N	Soil		2.3	28.9	74.2	165	0.5	45.6	14.1	596	3.60	150.3	4.4	2.6	7.3	24	1.7	3.4	0.5	84	0.27
L10400 12925N	Soil		2.3	23.7	55.0	197	0.2	28.0	12.0	776	3.15	107.9	2.6	12.2	6.4	23	0.8	3.3	0.3	71	0.36

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

CERTIFICATE OF ANALYSIS SMI09000183.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L10400 12200N	Soil	0.069	28	30	0.52	114	0.080	2	1.75	0.012	0.10	0.2	0.04	3.3	0.2	<0.05	5	0.6
L10400 12225N	Soil	0.074	37	26	0.41	140	0.046	1	1.75	0.010	0.08	0.2	0.08	3.7	0.2	<0.05	5	0.6
L10400 12250N	Soil	0.063	31	34	0.54	130	0.074	2	2.13	0.011	0.09	0.2	0.07	4.3	0.2	<0.05	6	<0.5
L10400 12275N	Soil	0.082	35	32	0.51	139	0.071	2	1.97	0.012	0.09	0.2	0.07	4.6	0.2	<0.05	5	1.0
L10400 12300N	Soil	0.061	28	30	0.48	152	0.069	1	1.88	0.013	0.09	0.2	0.06	4.0	0.2	<0.05	5	0.5
L10400 12325N	Soil	0.060	40	35	0.54	164	0.063	2	2.25	0.012	0.11	0.2	0.06	5.2	0.2	<0.05	7	0.9
L10400 12350N	Soil	0.059	28	32	0.56	156	0.085	2	1.75	0.015	0.09	0.2	0.03	3.9	0.2	<0.05	5	<0.5
L10400 12375N	Soil	0.086	31	34	0.50	187	0.051	2	1.94	0.012	0.09	0.2	0.08	4.0	0.2	<0.05	6	0.7
L10400 12400N	Soil	0.079	24	34	0.53	154	0.048	2	1.83	0.013	0.11	0.2	0.07	3.5	0.2	0.05	6	<0.5
L10400 12425N	Soil	0.065	25	35	0.58	177	0.065	2	1.84	0.013	0.10	0.2	0.03	4.1	0.2	<0.05	5	<0.5
L10400 12450N	Soil	0.071	34	33	0.56	177	0.084	2	1.82	0.015	0.10	0.4	0.04	3.9	0.2	<0.05	5	0.6
L10400 12475N	Soil	0.063	28	27	0.45	111	0.082	2	1.29	0.018	0.13	0.5	0.02	3.5	0.2	0.06	4	<0.5
L10400 12500N	Soil	0.076	27	30	0.50	150	0.062	1	1.83	0.011	0.11	0.6	0.04	3.4	0.2	0.06	5	<0.5
L10400 12525N	Soil	0.075	27	32	0.55	123	0.096	2	1.48	0.028	0.11	0.5	0.03	4.7	0.2	<0.05	5	<0.5
L10400 12550N	Soil	0.081	34	36	0.56	271	0.061	2	2.18	0.015	0.10	1.6	0.06	4.6	0.1	<0.05	6	0.6
L10400 12575N	Soil	0.070	24	28	0.47	123	0.091	1	1.40	0.018	0.08	1.2	0.02	3.0	0.1	<0.05	4	<0.5
L10400 12600N	Soil	0.074	23	30	0.40	120	0.049	1	1.83	0.012	0.07	0.4	0.07	2.8	0.2	<0.05	6	0.6
L10400 12625N	Soil	0.081	22	30	0.60	154	0.105	1	1.52	0.018	0.10	0.6	0.02	3.5	0.2	<0.05	5	<0.5
L10400 12650N	Soil	0.080	26	40	0.61	186	0.082	2	2.17	0.014	0.10	0.3	0.06	4.6	0.2	<0.05	7	<0.5
L10400 12675N	Soil	0.059	25	36	0.49	210	0.058	1	2.32	0.014	0.06	0.3	0.05	4.8	0.2	<0.05	7	<0.5
L10400 12700N	Soil	0.128	19	30	0.89	165	0.175	<1	2.39	0.019	0.23	1.3	0.02	5.7	0.5	<0.05	8	<0.5
L10400 12725N	Soil	0.066	15	35	0.48	142	0.091	2	2.01	0.017	0.08	0.5	0.06	3.6	0.2	<0.05	7	0.5
L10400 12750N	Soil	0.075	7	18	0.16	55	0.040	1	0.84	0.018	0.07	0.1	0.14	1.4	0.1	0.10	4	0.6
L10400 12775N	Soil	0.064	25	33	0.59	160	0.102	1	1.76	0.015	0.13	0.6	0.02	3.9	0.2	<0.05	6	0.5
L10400 12800N	Soil	0.089	20	35	0.67	130	0.113	1	2.04	0.017	0.11	0.6	0.03	3.9	0.2	<0.05	6	<0.5
L10400 12825N	Soil	0.081	12	35	0.53	79	0.097	2	2.06	0.012	0.08	0.2	0.08	3.0	0.1	<0.05	8	<0.5
L10400 12850N	Soil	0.041	10	34	0.38	96	0.097	1	2.10	0.011	0.05	0.2	0.05	2.7	0.1	<0.05	8	0.6
L10400 12875N	Soil	0.054	13	34	0.36	89	0.058	1	1.64	0.014	0.05	0.2	0.06	2.0	0.2	<0.05	7	0.6
L10400 12900N	Soil	0.075	21	86	0.77	128	0.151	3	2.21	0.020	0.11	0.5	0.07	4.0	0.3	<0.05	8	<0.5
L10400 12925N	Soil	0.079	20	36	0.62	135	0.111	2	1.85	0.016	0.10	0.5	0.04	3.7	0.2	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

CERTIFICATE OF ANALYSIS SMI09000183.1

		Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L10400 12950N	Soil			1.6	23.2	46.7	115	0.1	24.2	13.7	763	3.26	73.0	1.9	10.1	5.7	23	0.5	2.6	0.4	70	0.37
L10400 12975N	Soil			2.0	29.2	58.6	175	0.3	26.3	12.3	677	3.24	100.7	3.7	2.5	4.3	24	0.4	3.1	0.4	68	0.33
L10400 13000N	Soil			1.4	27.8	51.9	138	0.2	27.8	12.9	687	3.33	77.9	3.1	4.4	5.2	24	0.5	2.2	0.3	77	0.37
L10400 13025N	Soil			0.7	12.5	17.7	68	0.1	9.1	5.1	319	1.58	32.3	1.4	1.3	1.1	10	0.3	1.5	0.1	38	0.14
L10400 13050N	Soil			1.6	29.1	67.7	161	0.3	29.1	11.6	648	3.09	127.1	3.7	6.6	5.9	24	0.7	6.4	0.4	66	0.35
L10400 13075N	Soil			1.8	18.9	59.7	125	0.2	21.4	8.7	441	3.95	127.3	1.9	8.1	5.3	13	0.4	4.7	0.5	78	0.17
L10400 13100N	Soil			2.1	40.7	93.2	183	0.8	33.9	12.6	893	3.82	207.3	10.6	6.1	6.1	42	0.7	8.4	0.8	68	0.70
L10400 13125N	Soil			1.5	26.3	45.4	119	0.3	27.2	11.0	625	3.00	70.5	4.6	2.8	8.1	25	0.4	4.6	0.4	66	0.44
L10400 13150N	Soil			2.4	25.2	52.3	148	0.4	27.5	10.4	440	3.19	88.8	8.2	5.6	10.5	28	0.4	7.4	0.5	60	0.51
L10400 13175N	Soil			2.1	29.8	35.8	104	0.2	27.9	13.8	1087	3.09	52.9	7.8	2.6	7.2	27	0.6	4.1	0.4	63	0.50

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

CERTIFICATE OF ANALYSIS SMI09000183.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
		Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
		MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L10400 12950N	Soil		0.079	18	34	0.54	111	0.094	1	1.64	0.015	0.09	0.7	0.05	3.0	0.1	<0.05	6	0.6
L10400 12975N	Soil		0.071	21	36	0.54	169	0.078	2	1.87	0.017	0.08	0.4	0.04	3.9	0.2	<0.05	7	0.7
L10400 13000N	Soil		0.075	20	38	0.68	165	0.094	2	2.13	0.015	0.08	0.4	0.03	4.0	0.2	<0.05	7	<0.5
L10400 13025N	Soil		0.038	7	13	0.15	58	0.050	<1	0.69	0.012	0.04	0.1	0.03	1.2	<0.1	<0.05	3	<0.5
L10400 13050N	Soil		0.076	20	34	0.60	155	0.092	1	1.82	0.016	0.07	0.6	0.04	4.0	0.1	<0.05	5	<0.5
L10400 13075N	Soil		0.057	16	34	0.44	66	0.060	1	1.86	0.008	0.07	0.6	0.04	2.7	0.2	<0.05	8	0.5
L10400 13100N	Soil		0.093	39	40	0.58	279	0.054	2	2.25	0.016	0.10	0.3	0.09	6.3	0.3	<0.05	7	0.8
L10400 13125N	Soil		0.079	29	36	0.56	159	0.098	1	1.60	0.018	0.09	0.6	0.08	4.7	0.2	<0.05	5	<0.5
L10400 13150N	Soil		0.079	29	37	0.60	155	0.078	1	1.93	0.016	0.10	0.6	0.14	5.6	0.3	<0.05	6	<0.5
L10400 13175N	Soil		0.085	27	35	0.61	165	0.086	1	1.93	0.016	0.08	0.4	0.05	5.2	0.2	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

QUALITY CONTROL REPORT SMI09000183.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
L10400 11625N	Soil		2.0	33.1	26.3	228	0.4	23.3	10.1	765	2.97	356.0	4.3	9.1	4.1	28	0.4	4.7	0.4	68	0.36
REP L10400 11625N	QC		2.0	33.4	27.3	231	0.4	22.0	9.9	796	2.97	362.1	4.3	14.0	4.0	28	0.6	5.4	0.4	73	0.39
L10400 12075N	Soil		0.7	18.6	88.7	459	0.3	18.5	9.3	709	2.81	334.9	2.1	12.1	6.6	24	1.3	9.4	0.8	62	0.36
REP L10400 12075N	QC		0.7	16.5	87.1	454	0.3	17.1	8.7	696	2.76	341.6	2.0	15.6	6.5	24	1.3	9.3	0.8	61	0.36
L10400 13050N	Soil		1.6	29.1	67.7	161	0.3	29.1	11.6	648	3.09	127.1	3.7	6.6	5.9	24	0.7	6.4	0.4	66	0.35
REP L10400 13050N	QC		1.5	26.8	70.8	158	0.3	28.0	11.1	656	3.11	126.7	3.9	20.8	6.5	24	0.6	6.8	0.4	66	0.36
Reference Materials																					
STD DS7	Standard		21.9	109.3	66.0	406	0.8	57.7	9.7	610	2.40	54.8	4.9	69.1	4.6	75	6.7	6.4	5.1	86	0.96
STD DS7	Standard		19.9	104.0	67.0	377	0.8	54.3	8.8	549	2.19	50.1	4.8	63.0	4.4	67	6.4	6.0	4.6	85	0.89
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 14, 2009

QUALITY CONTROL REPORT SMI09000183.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
L10400 11625N	Soil	0.061	15	37	0.58	254	0.089	3	1.81	0.015	0.11	0.3	0.04	4.3	0.2	<0.05	6	0.9
REP L10400 11625N	QC	0.066	16	36	0.66	260	0.110	2	1.97	0.015	0.12	0.2	0.05	4.4	0.2	<0.05	6	0.8
L10400 12075N	Soil	0.049	17	35	0.61	132	0.113	2	1.70	0.013	0.10	0.4	0.02	3.5	0.2	<0.05	6	<0.5
REP L10400 12075N	QC	0.046	17	33	0.62	128	0.108	1	1.71	0.013	0.10	0.2	0.02	3.5	0.2	<0.05	6	<0.5
L10400 13050N	Soil	0.076	20	34	0.60	155	0.092	1	1.82	0.016	0.07	0.6	0.04	4.0	0.1	<0.05	5	<0.5
REP L10400 13050N	QC	0.075	21	35	0.61	164	0.091	1	1.84	0.017	0.07	0.5	0.03	4.0	0.1	<0.05	6	0.6
Reference Materials																		
STD DS7	Standard	0.077	13	181	1.04	402	0.125	40	1.03	0.093	0.43	4.1	0.19	2.5	4.3	0.19	5	3.7
STD DS7	Standard	0.078	12	171	1.00	380	0.115	35	0.98	0.078	0.40	4.1	0.19	2.2	4.1	0.19	4	3.4
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: September 08, 2009
Report Date: September 18, 2009
Page: 1 of 6

CERTIFICATE OF ANALYSIS SMI09000204.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC09-19
P.O. Number
Number of Samples: 143

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	142	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	142	Dry at 60C			SMI
1DX15	140	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6400W 12700N	Soil		1.5	23.4	390.1	54	1.3	12.7	5.0	184	3.71	117.0	2.6	15.0	26.4	114	0.4	11.6	1.5	39	0.22
L6400W 12725N	Soil		1.6	24.7	288.0	60	4.8	21.6	9.8	293	3.52	51.0	1.3	16.9	10.2	28	0.3	14.2	0.8	67	0.16
L6400W 12750N	Soil		1.5	25.6	17.5	66	0.1	23.3	9.2	301	3.74	16.4	1.1	4.0	5.5	17	0.3	2.2	0.6	80	0.13
L6400W 12775N	Soil		1.6	23.9	13.5	62	<0.1	25.8	11.5	413	3.45	14.2	1.0	2.1	4.6	17	0.2	1.3	0.4	75	0.15
L6400W 12800N	Soil		1.1	26.5	15.2	71	<0.1	29.0	12.0	477	3.26	19.1	1.3	5.9	4.3	18	0.2	1.3	0.5	70	0.17
L6400W 12825N	Soil		0.8	43.0	13.9	55	0.1	27.5	11.0	296	2.86	56.3	4.0	43.3	17.5	24	0.1	4.6	1.5	50	0.27
L6400W 12850N	Soil		0.9	59.0	15.3	56	0.2	25.2	9.8	372	3.33	39.5	5.0	73.4	16.0	34	0.2	4.4	3.1	52	0.23
L6400W 12875N	Soil		0.6	50.9	16.1	37	0.1	17.8	5.0	145	3.63	54.3	3.2	73.1	19.7	32	0.1	4.4	2.7	42	0.18
L6400W 12900N	Soil		1.0	41.6	10.8	47	<0.1	16.8	6.8	302	2.98	23.3	2.7	59.0	17.5	35	0.1	2.6	2.0	53	0.35
L6400W 12925N	Soil		0.8	50.1	12.5	50	<0.1	21.8	8.4	367	3.47	18.5	2.7	31.3	17.6	25	0.2	2.4	2.6	53	0.25
L6400W 12950N	Soil		1.3	26.9	12.8	52	<0.1	22.3	9.5	294	3.34	17.8	1.6	18.2	8.0	19	0.1	1.8	2.0	69	0.17
L6400W 12975N	Soil		0.9	35.1	11.7	58	<0.1	20.5	8.7	269	2.94	23.6	2.1	63.7	8.8	18	0.3	2.6	2.3	54	0.18
L6400W 14025N	Soil		0.7	22.8	27.1	108	0.2	19.0	9.2	461	2.42	105.4	2.9	71.6	6.5	38	0.5	3.2	1.7	58	0.40
L6400W 14050N	Soil		1.0	19.5	45.6	276	0.4	23.7	10.6	497	3.13	246.2	3.3	35.8	6.7	31	3.5	3.4	1.1	61	0.29
L6400W 14075N	Soil		0.8	17.8	41.5	199	<0.1	21.5	9.5	436	2.65	126.7	1.5	4.4	5.4	23	1.5	2.7	0.6	61	0.22
L6400W 14100N	Soil		1.0	21.5	27.3	143	0.3	21.7	10.2	554	2.63	89.5	3.0	6.1	4.4	42	0.7	1.7	0.3	63	0.33
L6400W 14125N	Soil		1.2	27.6	55.0	221	0.4	20.9	10.1	692	2.89	157.3	4.8	8.6	4.2	53	1.0	2.8	0.4	63	0.55
L6400W 14150N	Soil		1.5	31.2	8.7	61	<0.1	16.3	6.4	281	2.14	8.5	1.1	0.9	0.7	17	0.2	0.8	0.3	45	0.16
L6400W 14175N	Soil		1.6	30.6	10.3	55	<0.1	18.1	7.3	294	2.33	8.7	1.4	1.4	0.8	26	0.3	0.7	0.3	49	0.21
L6400W 14200N	Soil		1.9	38.8	51.7	112	0.3	26.4	14.8	1228	2.83	80.7	7.1	1.7	2.4	42	0.7	2.5	3.6	55	0.43
L6400W 14225N	Soil		1.5	22.4	78.5	194	0.4	19.3	10.9	919	2.81	123.0	3.9	5.6	3.6	38	1.2	3.7	0.5	60	0.47
L6400W 14250N	Soil		1.2	19.2	329.3	493	2.1	16.9	11.2	888	2.85	269.4	4.2	27.5	6.6	34	2.8	26.9	0.4	57	0.41
L6400W 14275N	Soil		1.3	18.9	40.0	94	0.2	19.5	9.7	537	2.55	68.9	2.0	6.5	6.4	26	0.4	2.5	0.2	63	0.32
L6400W 14300N	Soil		1.4	20.7	45.7	127	0.3	19.5	11.2	769	2.78	78.3	3.5	9.6	5.4	30	0.7	3.4	0.3	65	0.40
L6400W 14325N	Soil		1.5	24.9	126.8	193	0.3	23.3	13.3	1230	3.13	109.3	2.4	13.2	5.7	21	1.1	9.6	0.4	73	0.27
L6400W 14350N	Soil		1.8	24.1	38.6	105	0.3	21.1	11.9	760	2.92	55.2	2.6	9.8	2.8	22	0.3	2.3	0.9	67	0.23
L6400 14350	Soil		1.1	23.9	6.6	54	<0.1	12.8	5.4	192	1.77	6.7	0.9	2.4	0.9	14	0.2	0.6	0.2	41	0.12
L6400W 14375N	Soil		1.5	24.7	36.6	91	0.1	23.3	12.8	719	2.93	36.0	2.5	2.8	4.4	19	0.5	2.0	0.4	74	0.25
L6400W 14400N	Soil		1.5	21.5	22.9	72	0.2	19.4	10.0	572	2.65	22.8	2.2	7.9	3.5	22	0.3	1.9	0.3	71	0.27
L6400W 14425N	Soil		1.8	27.8	16.2	87	0.1	25.1	11.7	641	3.15	15.1	1.9	6.2	2.2	26	0.6	1.4	0.3	74	0.30

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6400W 12700N	Soil	0.062	38	22	0.35	244	0.029	<1	1.72	0.028	0.32	<0.1	0.02	2.5	0.3	0.56	6	<0.5
L6400W 12725N	Soil	0.046	18	32	0.46	131	0.075	2	2.11	0.016	0.12	0.1	0.07	2.7	0.2	0.16	7	<0.5
L6400W 12750N	Soil	0.045	14	36	0.49	87	0.092	1	2.32	0.011	0.06	0.2	0.04	2.8	0.1	0.05	8	0.7
L6400W 12775N	Soil	0.039	12	37	0.54	94	0.098	2	2.30	0.012	0.08	0.1	0.04	2.9	0.1	<0.05	7	<0.5
L6400W 12800N	Soil	0.047	12	36	0.61	100	0.102	2	2.26	0.015	0.09	0.1	0.04	3.1	0.1	<0.05	7	<0.5
L6400W 12825N	Soil	0.063	29	39	0.68	111	0.115	<1	2.04	0.014	0.23	0.3	0.03	4.2	0.4	<0.05	6	0.5
L6400W 12850N	Soil	0.071	32	36	0.56	134	0.088	2	1.82	0.016	0.16	0.2	0.02	3.7	0.2	<0.05	6	0.5
L6400W 12875N	Soil	0.059	33	28	0.48	97	0.093	1	1.39	0.015	0.15	1.5	0.01	2.9	0.3	<0.05	5	<0.5
L6400W 12900N	Soil	0.066	27	31	0.49	128	0.127	1	1.45	0.026	0.16	0.2	0.02	4.0	0.2	<0.05	5	<0.5
L6400W 12925N	Soil	0.083	25	31	0.52	99	0.105	1	1.96	0.018	0.11	0.3	0.02	3.1	0.2	0.06	5	<0.5
L6400W 12950N	Soil	0.038	15	34	0.46	94	0.104	2	2.23	0.012	0.07	0.3	0.04	3.0	0.1	<0.05	7	0.6
L6400W 12975N	Soil	0.050	20	29	0.45	90	0.085	<1	1.76	0.015	0.07	0.3	0.03	2.7	0.2	0.06	5	0.6
L6400W 14025N	Soil	0.048	14	28	0.48	184	0.096	2	1.54	0.026	0.07	0.3	0.02	3.4	0.2	<0.05	4	<0.5
L6400W 14050N	Soil	0.051	12	31	0.48	184	0.064	2	2.34	0.016	0.07	0.3	0.06	2.9	0.2	<0.05	5	<0.5
L6400W 14075N	Soil	0.036	13	30	0.49	163	0.074	2	2.23	0.016	0.06	0.2	0.03	2.7	0.2	<0.05	5	<0.5
L6400W 14100N	Soil	0.065	14	30	0.50	158	0.082	2	1.74	0.023	0.07	0.2	0.08	3.0	0.1	<0.05	5	0.6
L6400W 14125N	Soil	0.057	18	32	0.52	260	0.065	2	2.06	0.026	0.07	0.2	0.05	4.1	0.2	0.06	5	<0.5
L6400W 14150N	Soil	0.078	7	22	0.33	70	0.047	2	1.63	0.026	0.05	0.1	0.10	1.8	0.1	0.10	5	1.2
L6400W 14175N	Soil	0.071	10	25	0.36	96	0.056	2	1.55	0.038	0.06	0.1	0.12	2.1	0.1	0.11	5	<0.5
L6400W 14200N	Soil	0.093	28	31	0.55	234	0.060	2	1.97	0.029	0.08	0.4	0.12	3.2	0.2	0.08	6	0.5
L6400W 14225N	Soil	0.075	17	29	0.50	233	0.065	2	1.79	0.022	0.09	0.2	0.06	3.5	0.2	<0.05	5	0.6
L6400W 14250N	Soil	0.074	19	26	0.47	222	0.070	1	1.61	0.019	0.09	0.3	0.05	3.3	0.2	<0.05	5	<0.5
L6400W 14275N	Soil	0.033	12	27	0.56	190	0.112	1	1.50	0.021	0.08	0.2	0.02	3.1	0.2	<0.05	4	<0.5
L6400W 14300N	Soil	0.072	17	31	0.60	222	0.089	2	1.87	0.036	0.10	0.4	0.03	3.7	0.2	<0.05	5	<0.5
L6400W 14325N	Soil	0.075	13	34	0.61	217	0.087	2	2.03	0.018	0.12	0.3	0.04	3.6	0.3	<0.05	6	<0.5
L6400W 14350N	Soil	0.066	13	33	0.60	187	0.085	2	2.21	0.019	0.09	0.2	0.05	3.1	0.2	<0.05	7	<0.5
L6400 14350	Soil	0.053	6	21	0.32	63	0.050	2	1.46	0.029	0.05	0.2	0.05	1.4	0.1	0.06	4	0.6
L6400W 14375N	Soil	0.059	11	36	0.60	160	0.104	2	2.26	0.019	0.09	0.2	0.06	3.3	0.2	<0.05	6	<0.5
L6400W 14400N	Soil	0.073	14	30	0.53	162	0.089	2	1.69	0.019	0.08	0.4	0.05	2.8	0.1	<0.05	6	<0.5
L6400W 14425N	Soil	0.096	11	34	0.56	183	0.086	1	1.94	0.020	0.09	0.1	0.06	2.8	0.2	0.06	7	0.9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6400W 14450N	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
L6400W 14475N	Soil		1.8	33.0	10.1	67	<0.1	19.8	7.2	272	2.75	9.9	1.2	2.7	1.0	15	0.2	1.0	0.2	63	0.13
L6400W 14500N	Soil		1.0	27.7	13.6	72	<0.1	23.9	12.3	584	2.91	13.6	3.2	3.9	6.2	31	0.2	1.1	1.0	76	0.41
L6600W 12700N	Soil		1.2	44.1	22.2	56	0.3	25.2	11.0	420	3.48	28.0	2.4	25.9	7.4	28	0.1	5.3	1.2	62	0.21
L6600W 12725N	Soil		1.0	34.0	32.6	46	0.3	17.6	7.4	248	2.95	34.1	1.4	40.0	13.0	49	0.2	9.5	1.6	50	0.24
L6600W 12750N	Soil		1.6	64.6	104.4	80	0.6	15.1	6.0	301	3.37	84.5	2.7	32.8	14.6	48	0.2	25.2	2.0	42	0.16
L6600W 12775N	Soil		2.1	23.9	21.8	52	0.1	20.1	8.3	307	3.44	16.2	0.7	16.9	3.7	16	0.2	3.3	0.9	81	0.11
L6600W 12800N	Soil		1.4	29.7	49.6	57	0.2	23.9	9.6	335	3.56	18.2	1.0	9.4	6.1	20	0.2	5.5	1.0	68	0.14
L6600W 12825N	Soil		2.5	21.4	14.2	50	<0.1	17.8	7.3	316	3.84	13.5	0.8	11.7	3.4	14	0.2	1.7	0.7	90	0.11
L6600W 12850N	Soil		1.1	37.3	11.9	62	0.1	24.0	10.1	498	3.26	19.0	1.5	32.1	4.7	25	0.2	3.5	1.9	66	0.20
L6600W 12875N	Soil		1.0	23.4	9.7	56	<0.1	24.4	13.8	471	3.13	10.8	0.9	13.3	3.5	17	0.1	1.0	0.4	65	0.17
L6600W 12900N	Soil		0.6	32.2	8.4	58	<0.1	28.1	13.6	472	3.02	12.6	0.8	16.5	4.5	19	0.2	1.2	1.1	63	0.22
L6600W 12925N	Soil		0.9	39.8	9.9	59	0.1	31.4	11.1	482	3.15	16.6	1.0	67.9	5.1	18	0.2	2.6	1.5	59	0.17
L6600W 12950N	Soil		1.5	31.2	18.7	52	0.3	16.1	5.8	260	3.13	29.1	1.1	67.1	5.3	16	0.2	10.6	7.1	71	0.09
L6600W 12975N	Soil		0.9	53.4	27.4	45	0.2	19.0	9.2	305	3.39	38.5	3.2	115.8	11.7	30	<0.1	5.3	4.7	57	0.24
L6800W 12600N	Soil		1.5	68.2	20.3	48	0.2	15.0	5.6	242	3.23	18.7	6.6	25.3	4.1	33	0.2	2.9	1.3	48	0.20
L6800W 12625N	Soil		1.3	57.8	14.5	34	0.1	15.4	6.0	266	2.97	19.6	3.7	64.0	6.9	37	0.1	2.6	1.9	40	0.22
L6800W 12650N	Soil		1.4	75.6	16.9	51	0.1	22.0	10.2	430	3.73	22.5	4.8	47.7	12.3	34	0.2	2.3	1.4	52	0.22
L6800W 12675N	Soil		1.3	59.0	13.6	29	0.2	11.6	4.9	167	2.97	24.5	2.6	51.9	7.9	35	<0.1	2.8	1.6	33	0.17
L6800W 12700N	Soil		0.8	48.2	18.5	29	0.1	10.1	4.3	174	2.75	29.5	2.5	66.5	29.3	48	<0.1	3.1	1.3	27	0.24
L6800W 12725N	Soil		0.9	50.5	15.2	34	0.2	13.7	5.9	193	3.34	26.9	1.6	49.3	13.5	36	0.1	5.1	1.5	40	0.19
L6800W 12750N	Soil		0.6	72.7	17.6	23	0.3	6.9	3.0	128	2.82	28.8	2.2	82.3	12.5	52	<0.1	5.6	2.2	18	0.17
L6800W 12775N	Soil		1.0	60.0	10.2	33	0.2	12.5	6.3	261	2.93	15.1	1.7	61.1	8.0	32	0.1	2.1	1.4	39	0.11
L6800W 12800N	Soil		1.0	77.8	12.0	39	0.1	14.4	7.4	363	2.85	16.1	2.1	234.2	12.5	29	0.1	2.9	1.8	37	0.15
L6800W 12825N	Soil		1.2	31.4	9.1	56	<0.1	24.5	9.2	344	3.50	14.1	0.9	116.9	6.9	18	0.2	1.0	0.7	65	0.15
L6800W 12850N	Soil		0.8	40.4	11.2	35	0.1	13.2	5.4	200	3.07	23.5	2.8	44.1	14.9	23	<0.1	2.0	2.1	40	0.16
L6800W 12875N	Soil		0.8	31.2	11.6	34	0.1	13.9	4.4	147	1.87	17.0	2.9	88.6	8.2	18	<0.1	1.8	2.2	36	0.15
L6800W 12900N	Soil		0.9	30.7	14.0	28	0.3	10.6	3.7	133	2.79	44.2	3.1	67.3	7.6	25	<0.1	2.2	3.1	33	0.15
L6800W 12925N	Soil		0.8	27.9	10.0	27	0.1	9.9	3.1	141	2.37	27.0	2.1	95.8	8.2	16	<0.1	1.9	3.3	26	0.12
L7000W 12400N	Soil		0.8	50.6	8.6	39	<0.1	17.1	6.2	199	3.02	14.7	3.4	74.6	11.4	42	0.1	1.3	1.3	54	0.21

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6400W 14450N	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
L6400W 14475N	Soil	0.059	6	31	0.39	90	0.063	2	1.90	0.021	0.05	0.2	0.09	2.2	0.2	0.09	7	0.9
L6400W 14500N	Soil	0.094	18	34	0.65	342	0.127	<1	1.97	0.022	0.14	0.5	0.02	4.7	0.2	<0.05	6	0.5
L6600W 12700N	Soil	0.079	21	37	0.65	151	0.085	1	2.29	0.027	0.14	1.6	0.03	3.9	0.2	0.10	6	0.7
L6600W 12725N	Soil	0.069	23	27	0.48	127	0.081	<1	1.37	0.026	0.19	2.0	0.03	2.6	0.2	0.20	5	0.9
L6600W 12750N	Soil	0.065	33	24	0.40	164	0.044	<1	1.23	0.032	0.26	1.0	0.04	2.4	0.5	0.38	5	0.8
L6600W 12775N	Soil	0.045	11	35	0.38	95	0.083	2	1.82	0.012	0.08	0.4	0.04	2.5	0.1	0.07	8	<0.5
L6600W 12800N	Soil	0.040	14	37	0.56	113	0.087	1	2.23	0.020	0.12	1.2	0.04	3.1	0.2	0.13	7	<0.5
L6600W 12825N	Soil	0.039	11	34	0.36	85	0.099	<1	1.55	0.008	0.05	0.5	0.02	2.5	0.2	<0.05	10	0.7
L6600W 12850N	Soil	0.055	15	36	0.63	120	0.090	2	1.68	0.022	0.13	1.5	0.03	3.0	0.2	0.11	7	0.6
L6600W 12875N	Soil	0.049	11	37	0.62	94	0.095	2	2.26	0.017	0.08	0.5	0.03	3.6	0.1	<0.05	6	0.9
L6600W 12900N	Soil	0.040	10	35	0.71	112	0.110	2	2.34	0.021	0.11	1.0	0.03	4.0	0.2	<0.05	6	0.6
L6600W 12925N	Soil	0.052	11	36	0.62	118	0.100	1	2.55	0.019	0.11	1.9	0.04	3.4	0.2	<0.05	5	0.5
L6600W 12950N	Soil	0.044	12	28	0.33	96	0.074	<1	1.36	0.018	0.10	1.4	0.03	2.2	0.2	0.10	8	<0.5
L6600W 12975N	Soil	0.081	26	30	0.61	173	0.100	1	1.69	0.018	0.21	2.3	0.02	4.4	0.3	<0.05	6	0.8
L6800W 12600N	Soil	0.085	33	26	0.40	209	0.026	<1	2.08	0.023	0.11	0.4	0.04	2.1	0.2	0.16	7	1.0
L6800W 12625N	Soil	0.059	25	27	0.44	232	0.030	<1	1.73	0.022	0.12	1.4	0.02	2.2	0.2	0.11	6	0.7
L6800W 12650N	Soil	0.069	30	30	0.49	210	0.042	1	2.31	0.031	0.13	0.5	0.02	3.0	0.2	0.14	7	0.8
L6800W 12675N	Soil	0.058	22	22	0.40	281	0.021	<1	1.71	0.029	0.11	0.8	0.02	1.8	0.2	0.16	6	0.8
L6800W 12700N	Soil	0.054	37	16	0.35	209	0.028	1	1.17	0.049	0.18	0.2	0.03	2.7	0.2	0.30	4	0.6
L6800W 12725N	Soil	0.056	22	21	0.35	162	0.041	1	1.28	0.037	0.16	1.5	0.04	1.9	0.2	0.27	4	1.0
L6800W 12750N	Soil	0.044	24	11	0.29	242	0.010	<1	1.52	0.056	0.13	4.6	0.02	1.7	0.2	0.21	5	0.7
L6800W 12775N	Soil	0.048	19	22	0.34	159	0.034	<1	1.81	0.037	0.09	1.7	0.04	1.9	0.1	0.13	6	0.7
L6800W 12800N	Soil	0.064	18	20	0.33	127	0.045	<1	1.42	0.039	0.12	0.9	0.04	2.2	0.1	0.12	5	0.8
L6800W 12825N	Soil	0.052	14	38	0.50	101	0.082	1	1.95	0.019	0.08	0.5	0.05	2.8	0.1	0.09	7	<0.5
L6800W 12850N	Soil	0.060	20	22	0.46	172	0.051	<1	1.83	0.023	0.17	0.7	0.02	2.8	0.2	0.09	6	0.8
L6800W 12875N	Soil	0.055	19	24	0.45	121	0.051	1	1.78	0.014	0.10	0.7	0.04	2.6	0.2	<0.05	6	1.0
L6800W 12900N	Soil	0.061	22	20	0.38	208	0.023	<1	1.85	0.012	0.11	0.9	0.06	2.5	0.2	<0.05	6	0.8
L6800W 12925N	Soil	0.052	15	16	0.32	174	0.018	<1	1.77	0.013	0.11	0.7	0.03	2.0	0.2	<0.05	5	0.9
L7000W 12400N	Soil	0.079	22	28	0.55	176	0.088	<1	1.50	0.038	0.20	0.3	0.02	3.2	0.2	0.21	5	0.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7000W 12425N	Soil		1.5	59.7	14.4	48	0.2	21.4	7.9	289	3.61	19.5	3.7	79.3	7.8	46	0.1	1.6	1.9	52	0.18
L7000W 12450N	Soil		1.1	64.3	13.4	46	0.1	23.2	8.2	313	3.71	17.8	3.5	50.6	13.7	53	0.2	1.5	1.8	52	0.22
L7000W 12500N	Soil		1.4	65.4	22.7	40	0.2	14.6	6.1	258	3.29	31.7	3.6	93.3	15.0	76	0.1	3.2	4.4	39	0.17
L7000W 12525N	Soil		1.4	77.5	26.6	42	0.2	15.0	7.2	387	3.51	37.1	10.4	105.7	14.4	73	<0.1	3.3	4.1	40	0.15
L7000W 12550N	Soil		1.0	45.6	17.5	45	<0.1	16.0	7.7	347	3.09	24.4	3.7	43.4	13.1	50	0.2	2.0	2.3	42	0.25
L7000W 12575N	Soil		1.4	31.5	14.1	41	<0.1	15.3	5.9	224	3.01	20.2	1.9	32.2	5.6	23	0.2	1.4	1.4	63	0.12
L7000W 12600N	Soil		1.6	42.8	16.0	45	<0.1	16.9	7.1	361	3.50	25.7	1.7	109.8	14.1	26	<0.1	1.8	1.9	70	0.11
L7000W 12625N	Soil		1.6	35.1	12.4	34	0.2	18.2	4.5	159	2.48	18.0	1.7	83.5	8.4	27	0.1	1.4	1.6	57	0.14
L7000W 12650N	Soil		1.3	30.0	12.1	43	<0.1	20.8	8.1	255	2.86	27.2	2.2	45.7	7.1	25	0.2	1.6	1.3	57	0.15
L7000W 12675N	Soil		1.1	30.8	11.3	46	<0.1	20.8	8.7	298	2.89	28.5	2.6	38.3	9.6	24	0.2	1.5	1.3	62	0.18
L7000W 12700N	Soil		1.3	27.6	11.5	56	<0.1	22.8	8.5	354	2.90	23.9	1.9	47.2	6.3	21	0.2	1.3	1.1	60	0.17
L7000W 12725N	Soil		1.4	53.2	14.0	66	0.1	23.7	9.5	405	3.41	30.9	4.4	60.5	14.8	36	0.3	2.1	2.3	52	0.23
L7000W 12750N	Soil		1.3	47.9	18.0	55	0.1	18.3	8.5	405	3.21	32.3	5.5	47.1	12.0	41	0.1	3.4	1.4	45	0.15
L7000W 12775N	Soil		1.6	20.4	12.5	45	<0.1	15.0	6.0	275	3.05	14.0	1.6	20.3	3.8	16	0.2	1.1	0.7	72	0.13
L7000W 12800N	Soil		1.3	24.2	10.7	46	<0.1	15.5	5.2	211	2.39	15.4	2.6	9.4	1.2	22	0.2	1.0	1.1	50	0.12
L7000W 12825N	Soil		1.0	35.5	14.7	46	<0.1	21.4	10.5	396	3.18	20.5	5.4	51.6	13.7	28	0.2	1.1	1.8	50	0.15
L7000W 12850N	Soil		1.1	38.3	16.0	63	<0.1	19.6	10.1	383	3.57	29.4	3.7	45.4	10.5	47	0.3	1.4	2.1	49	0.16
L7000W 12875N	Soil		0.9	29.5	10.7	56	<0.1	27.2	11.2	446	3.18	15.9	3.5	32.1	9.9	26	0.3	1.1	1.3	60	0.22
L7000W 12900N	Soil		1.0	22.7	16.9	47	0.2	12.2	5.5	233	3.48	60.9	3.0	72.5	18.7	90	0.1	5.4	2.6	33	0.17
L7000W 12925N	Soil		1.7	23.1	21.0	46	0.3	12.8	4.5	161	2.60	105.1	3.4	50.7	13.7	33	0.1	4.2	3.6	50	0.19
L7200W 12200N	Soil		1.4	39.4	11.8	43	0.2	17.2	7.5	225	2.84	18.9	3.1	27.3	9.2	32	0.1	1.7	0.9	53	0.24
L7200W 12225N	Soil		1.1	33.5	13.0	52	0.1	18.9	7.8	270	2.82	17.1	2.8	28.3	4.8	21	0.1	1.2	0.8	59	0.22
L7200W 12250N	Soil		1.1	35.8	14.8	49	0.2	16.7	7.2	252	2.84	22.5	2.1	234.9	7.7	29	0.1	2.1	1.2	52	0.27
L7200W 12275N	Soil		1.5	48.6	13.3	55	0.1	22.1	9.5	353	3.10	19.7	4.6	28.7	7.3	27	0.1	1.6	1.4	57	0.23
L7200W 12300N	Soil		1.8	47.5	14.8	49	0.2	16.3	9.0	452	2.67	13.4	4.3	16.3	4.3	37	0.2	1.6	1.0	48	0.26
L7200W 12325N	Soil		1.8	50.3	16.3	45	0.2	16.7	7.5	278	3.01	14.8	5.0	46.9	4.9	33	0.1	1.8	1.0	55	0.25
L7200W 12350N	Soil		1.1	55.7	19.0	46	0.1	14.1	6.6	191	2.85	16.8	3.1	59.6	10.6	37	0.1	2.3	1.2	41	0.22
L7200W 12375N	Soil		1.2	59.5	23.4	45	0.3	14.3	6.5	232	3.04	21.2	4.7	45.6	9.2	41	0.1	3.2	1.3	40	0.22
L7200W 12400N	Soil		1.3	35.3	18.3	51	<0.1	19.9	8.5	239	3.74	20.9	1.9	20.9	9.5	22	0.2	1.2	1.6	68	0.17
L7200W 12425N	Soil		2.1	43.2	17.9	54	<0.1	19.3	8.6	306	3.81	19.3	1.7	18.5	7.9	20	0.2	1.4	1.9	84	0.14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7000W 12425N	Soil	0.074	25	33	0.50	186	0.055	2	1.90	0.039	0.16	0.9	0.04	2.8	0.2	0.26	7	1.3
L7000W 12450N	Soil	0.068	30	36	0.63	215	0.080	2	1.81	0.046	0.22	1.3	0.02	3.2	0.2	0.27	7	0.7
L7000W 12500N	Soil	0.057	38	24	0.40	180	0.043	2	1.43	0.037	0.24	0.6	0.02	2.2	0.2	0.36	6	0.9
L7000W 12525N	Soil	0.059	43	25	0.46	187	0.032	2	1.67	0.033	0.23	0.7	0.03	2.7	0.3	0.34	6	<0.5
L7000W 12550N	Soil	0.062	32	26	0.45	178	0.056	1	1.37	0.029	0.18	0.9	0.02	2.4	0.2	0.23	5	<0.5
L7000W 12575N	Soil	0.050	18	28	0.35	92	0.060	2	1.57	0.013	0.09	0.4	0.05	2.0	0.1	0.11	7	1.1
L7000W 12600N	Soil	0.044	21	29	0.40	98	0.106	2	1.36	0.021	0.13	0.5	0.02	2.3	0.2	0.14	8	0.9
L7000W 12625N	Soil	0.042	21	31	0.36	106	0.087	1	1.10	0.014	0.18	0.5	0.03	2.2	0.2	0.15	8	0.5
L7000W 12650N	Soil	0.041	17	28	0.43	116	0.072	2	1.67	0.016	0.09	0.6	0.02	2.5	0.2	0.12	5	0.7
L7000W 12675N	Soil	0.044	17	28	0.49	118	0.083	1	1.82	0.015	0.10	0.6	0.03	2.8	0.2	0.09	6	<0.5
L7000W 12700N	Soil	0.047	16	34	0.47	98	0.079	1	1.81	0.013	0.09	0.5	0.03	2.6	0.1	0.08	6	0.7
L7000W 12725N	Soil	0.072	34	30	0.54	162	0.063	<1	1.84	0.026	0.17	0.4	0.03	2.9	0.2	0.20	5	<0.5
L7000W 12750N	Soil	0.054	24	27	0.45	134	0.048	<1	1.77	0.019	0.18	0.5	0.03	2.6	0.2	0.19	6	<0.5
L7000W 12775N	Soil	0.048	11	30	0.30	75	0.080	1	1.28	0.008	0.06	0.5	0.03	2.1	0.1	0.05	8	0.7
L7000W 12800N	Soil	0.068	12	27	0.33	75	0.044	2	1.35	0.015	0.07	0.9	0.05	1.4	0.2	0.13	6	0.6
L7000W 12825N	Soil	0.039	19	27	0.49	104	0.081	2	1.80	0.022	0.15	1.2	0.02	2.8	0.2	0.15	5	<0.5
L7000W 12850N	Soil	0.055	20	24	0.43	141	0.061	1	1.70	0.062	0.11	3.9	0.03	2.5	0.1	0.26	6	0.8
L7000W 12875N	Soil	0.049	18	35	0.64	127	0.108	1	1.92	0.015	0.10	2.2	0.03	3.2	0.2	0.07	5	<0.5
L7000W 12900N	Soil	0.054	22	19	0.33	244	0.041	1	1.30	0.054	0.33	1.8	0.03	2.1	0.4	0.65	5	0.6
L7000W 12925N	Soil	0.047	26	29	0.47	187	0.058	2	1.78	0.008	0.11	0.9	0.12	3.5	0.3	<0.05	6	<0.5
L7200W 12200N	Soil	0.057	25	31	0.55	213	0.089	<1	1.66	0.016	0.09	0.3	0.03	3.4	0.2	0.05	5	0.7
L7200W 12225N	Soil	0.059	15	31	0.52	144	0.084	1	1.77	0.015	0.07	0.3	0.03	2.9	0.1	<0.05	6	0.6
L7200W 12250N	Soil	0.062	16	26	0.53	164	0.081	1	1.59	0.016	0.08	0.4	0.02	2.8	0.1	0.05	5	<0.5
L7200W 12275N	Soil	0.058	23	35	0.61	196	0.078	<1	2.00	0.015	0.09	0.3	0.03	3.3	0.2	<0.05	6	<0.5
L7200W 12300N	Soil	0.067	29	26	0.50	272	0.065	1	1.72	0.025	0.09	0.4	0.03	2.4	0.2	0.10	6	1.0
L7200W 12325N	Soil	0.072	31	29	0.50	186	0.061	<1	1.86	0.024	0.08	0.4	0.03	2.6	0.2	0.12	6	0.6
L7200W 12350N	Soil	0.048	26	21	0.52	193	0.058	<1	1.53	0.036	0.14	0.7	0.02	2.6	0.2	0.14	5	<0.5
L7200W 12375N	Soil	0.062	33	21	0.43	190	0.043	<1	1.56	0.032	0.11	0.4	0.03	2.2	0.1	0.15	6	<0.5
L7200W 12400N	Soil	0.041	19	32	0.54	136	0.100	2	1.70	0.017	0.09	0.2	0.04	2.9	0.2	0.07	7	<0.5
L7200W 12425N	Soil	0.048	15	31	0.47	117	0.096	<1	2.12	0.015	0.08	0.2	0.04	2.9	0.2	0.07	8	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7200W 12450N	Soil		1.7	34.6	13.5	56	0.1	13.7	7.0	299	3.37	16.4	1.5	15.7	5.2	20	0.2	0.9	1.9	82	0.13
L7200W 12475N	Soil		1.0	65.7	10.7	55	<0.1	23.5	12.3	397	3.65	24.1	2.3	56.1	7.9	31	0.3	1.0	3.0	78	0.25
L7600W 12300N	Soil		1.6	36.6	18.3	93	0.2	20.6	8.8	312	2.53	46.5	4.1	28.4	8.0	22	0.3	6.1	2.0	55	0.33
L7600W 12325N	Soil		2.1	41.7	14.6	60	0.2	23.9	10.2	302	3.40	78.8	5.5	49.6	7.6	24	0.2	2.3	2.2	65	0.34
L7600W 12350N	Soil		4.0	44.2	14.2	47	0.2	22.9	12.9	425	3.75	96.8	5.5	20.2	5.7	19	0.1	2.0	1.6	69	0.24
L7600W 12375N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L7600W 12400N	Soil		2.7	20.8	13.7	53	<0.1	15.6	8.4	493	2.90	24.9	1.7	10.5	3.2	15	0.2	1.0	1.0	72	0.12
L7600W 12425N	Soil		2.0	39.2	13.8	59	0.1	26.4	12.7	416	3.17	53.1	3.3	10.1	7.1	20	0.2	1.6	0.8	72	0.25
L7600W 12450N	Soil		1.6	23.7	20.0	54	<0.1	19.8	10.0	358	3.19	40.5	2.7	7.4	8.3	17	0.2	1.8	0.8	61	0.17
L7600W 12475N	Soil		1.0	41.2	12.1	66	<0.1	25.2	12.1	467	3.00	27.4	2.1	10.1	6.3	22	0.3	1.3	0.9	61	0.30
L7600W 12500N	Soil		1.7	29.0	14.5	71	0.1	24.1	13.4	731	3.08	18.6	2.7	4.8	1.8	29	0.2	1.0	0.8	64	0.31
L8600W 11800N	Soil		3.8	68.2	19.7	93	0.2	36.8	14.5	534	3.89	26.6	2.8	6.9	3.0	20	0.4	1.5	0.9	73	0.21
L8600W 11825N	Soil		3.4	33.2	17.9	67	0.6	21.5	8.7	409	3.96	18.4	1.0	7.3	2.0	13	0.3	1.3	0.5	106	0.09
L8600W 11850N	Soil		2.9	65.3	17.7	108	<0.1	42.1	15.8	607	3.86	28.1	1.5	4.0	1.3	15	0.5	1.4	0.8	95	0.13
L8600W 11875N	Soil		3.8	70.8	26.6	128	0.2	54.6	21.3	717	3.80	48.5	2.2	18.2	2.9	17	0.8	1.8	1.8	94	0.17
L8600W 11900N	Soil		3.6	56.5	20.3	283	0.4	86.2	31.8	1413	3.55	178.9	2.6	5.1	15.2	14	1.7	1.6	1.3	50	0.20
L8600W 11925N	Soil		6.9	164.5	32.3	189	0.3	24.2	4.4	150	4.84	103.2	7.1	5.4	30.4	98	0.6	2.4	1.3	43	0.07
L8600W 11950N	Soil		6.1	130.4	61.1	194	0.9	37.5	9.2	388	4.62	84.8	7.1	6.6	11.0	48	0.7	2.6	1.4	80	0.20
L8600W 11975N	Soil		6.7	108.6	38.7	226	1.2	47.8	12.0	553	3.60	66.6	6.6	1.6	2.1	24	1.3	2.2	1.2	89	0.17
L8600W 12000N	Soil		6.5	106.1	50.2	277	0.6	68.6	18.2	731	4.18	68.0	4.0	5.3	5.6	24	1.7	2.2	0.9	110	0.28
L8600W 12025N	Soil		4.4	87.2	64.3	208	0.4	58.8	21.6	803	4.09	93.8	2.6	4.1	3.9	49	1.3	2.4	1.2	87	0.38
L8600W 12050N	Soil		2.1	69.0	75.2	220	0.3	52.3	25.7	793	3.37	82.9	2.5	3.5	7.8	41	0.9	1.7	0.9	72	0.42
L8600W 12075N	Soil		2.5	72.7	59.4	172	0.2	45.2	19.7	767	3.83	109.9	2.4	2.6	7.5	39	0.7	2.1	1.1	81	0.38
L8600W 12100N	Soil		3.8	54.3	41.8	119	0.3	31.2	12.5	608	3.56	41.9	1.8	12.6	1.5	22	0.3	1.3	0.7	84	0.20
L8600W 12125N	Soil		5.5	78.1	146.0	336	1.1	48.1	16.4	913	3.81	93.2	2.9	3.5	2.5	43	1.6	2.9	1.0	89	0.37
L8600W 12150N	Soil		3.1	61.7	106.8	294	0.6	38.0	12.7	1096	3.15	132.4	3.8	3.1	6.8	57	2.1	2.6	0.8	61	0.74
L8600W 12175N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L8600W 12200N	Soil		5.7	94.5	137.8	377	0.6	43.7	15.6	758	3.61	116.4	3.9	2.8	6.2	38	2.0	2.5	0.9	74	0.49
L8600W 12225N	Soil		3.9	65.4	71.9	217	0.6	37.9	13.8	602	3.33	65.0	3.9	6.8	3.7	33	1.1	1.4	0.9	71	0.44
L8600W 12250N	Soil		4.0	64.4	71.4	246	0.6	38.9	13.8	712	3.34	67.2	3.6	9.4	4.4	31	1.1	1.8	0.6	73	0.42

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
		Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
		MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7200W 12450N	Soil		0.064	12	27	0.47	127	0.108	<1	1.84	0.015	0.09	0.4	0.06	2.6	0.2	0.09	9	<0.5
L7200W 12475N	Soil		0.069	21	32	0.80	186	0.106	1	2.15	0.026	0.17	0.3	0.03	3.4	0.2	0.12	6	<0.5
L7600W 12300N	Soil		0.073	24	35	0.65	163	0.089	<1	1.99	0.012	0.06	0.3	0.03	4.0	0.2	<0.05	6	<0.5
L7600W 12325N	Soil		0.074	22	38	0.70	153	0.081	1	2.22	0.013	0.07	0.6	0.04	4.2	0.2	<0.05	7	0.5
L7600W 12350N	Soil		0.068	22	39	0.68	121	0.092	1	2.33	0.012	0.06	0.3	0.04	3.6	0.2	<0.05	7	0.7
L7600W 12375N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L7600W 12400N	Soil		0.049	9	29	0.40	71	0.085	2	1.28	0.009	0.05	0.5	0.03	2.2	0.1	0.06	8	<0.5
L7600W 12425N	Soil		0.051	17	35	0.70	122	0.093	2	1.87	0.011	0.07	0.3	0.03	3.1	0.1	<0.05	7	<0.5
L7600W 12450N	Soil		0.050	14	29	0.57	78	0.073	2	1.79	0.010	0.06	0.2	0.03	2.9	0.1	<0.05	8	0.7
L7600W 12475N	Soil		0.060	14	31	0.68	113	0.103	2	1.75	0.012	0.08	0.4	0.03	3.2	0.2	<0.05	6	0.8
L7600W 12500N	Soil		0.104	16	32	0.61	156	0.065	3	1.82	0.015	0.08	0.8	0.06	2.3	0.2	0.09	7	0.8
L8600W 11800N	Soil		0.075	18	44	0.50	116	0.058	2	1.45	0.009	0.10	0.2	0.03	2.4	0.2	0.06	6	0.8
L8600W 11825N	Soil		0.052	9	33	0.36	65	0.090	2	1.45	0.007	0.05	0.2	0.05	2.1	0.1	<0.05	10	0.9
L8600W 11850N	Soil		0.063	12	46	0.58	152	0.068	2	2.06	0.010	0.06	0.2	0.04	2.8	0.2	0.05	8	0.9
L8600W 11875N	Soil		0.081	17	47	0.61	193	0.054	2	2.09	0.008	0.07	0.2	0.04	2.8	0.2	<0.05	7	1.3
L8600W 11900N	Soil		0.051	32	14	0.77	283	0.001	<1	3.02	0.003	0.05	<0.1	0.02	2.4	0.3	<0.05	6	1.3
L8600W 11925N	Soil		0.151	78	14	0.21	265	0.003	<1	1.69	0.023	0.37	0.1	0.03	2.8	0.5	0.69	3	2.2
L8600W 11950N	Soil		0.172	45	33	0.38	419	0.032	1	1.44	0.020	0.25	0.2	0.05	3.9	0.3	0.46	5	4.8
L8600W 11975N	Soil		0.135	19	43	0.44	811	0.048	2	2.10	0.014	0.08	0.3	0.09	3.4	0.2	0.15	6	1.9
L8600W 12000N	Soil		0.118	23	50	0.64	340	0.065	2	1.79	0.014	0.09	0.3	0.05	3.8	0.1	0.09	6	1.8
L8600W 12025N	Soil		0.108	17	54	0.80	450	0.035	1	2.00	0.010	0.08	0.1	0.05	3.1	0.1	0.09	6	1.6
L8600W 12050N	Soil		0.093	15	56	0.95	231	0.024	2	2.40	0.009	0.05	<0.1	0.02	4.0	0.1	<0.05	6	0.9
L8600W 12075N	Soil		0.095	17	50	0.84	339	0.052	2	1.96	0.011	0.07	0.3	0.04	3.3	0.1	<0.05	6	0.9
L8600W 12100N	Soil		0.094	12	46	0.55	216	0.027	1	1.46	0.010	0.08	0.2	0.05	2.2	0.1	0.09	6	1.1
L8600W 12125N	Soil		0.100	14	53	0.59	329	0.051	3	1.69	0.013	0.10	0.7	0.06	3.2	0.1	0.09	6	0.9
L8600W 12150N	Soil		0.098	18	35	0.69	657	0.016	1	1.91	0.011	0.12	0.2	0.09	4.2	0.3	0.11	5	1.2
L8600W 12175N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L8600W 12200N	Soil		0.100	17	42	0.65	266	0.050	1	1.61	0.017	0.08	0.3	0.04	3.1	0.1	0.08	5	1.6
L8600W 12225N	Soil		0.097	18	40	0.61	278	0.043	2	1.69	0.015	0.07	0.3	0.05	3.5	0.1	0.05	5	1.1
L8600W 12250N	Soil		0.083	18	43	0.65	228	0.051	2	1.69	0.019	0.08	0.4	0.05	3.7	0.1	0.05	5	0.9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L8600W 12275N	Soil		3.5	68.3	76.2	218	0.7	38.1	13.7	707	3.38	64.7	3.7	3.4	2.6	42	1.1	1.6	1.2	72	0.48
L8600W 12300N	Soil		3.8	39.4	129.3	246	0.5	22.2	11.1	990	3.23	108.3	2.6	3.3	7.4	34	0.8	2.6	1.4	51	0.38
L8600W 12325N	Soil		3.0	35.6	146.4	205	0.6	21.6	10.3	604	2.88	117.3	2.9	3.7	8.2	35	0.6	2.1	1.0	55	0.51
L8600W 12350N	Soil		3.9	36.3	61.1	125	0.4	20.1	8.3	388	2.52	74.4	2.4	1.8	1.0	27	0.5	1.3	0.9	57	0.28
L8600W 12375N	Soil		4.5	41.4	129.1	202	0.7	23.7	11.8	771	3.29	105.2	3.3	3.1	5.3	31	0.5	2.1	0.9	60	0.38
L8600W 12400N	Soil		3.6	37.5	56.9	126	0.7	18.4	8.4	499	2.57	60.3	4.0	3.9	1.0	48	0.5	1.4	0.7	52	0.69
L8600W 12425N	Soil		2.8	28.5	23.9	59	0.4	14.9	5.2	214	2.12	22.0	2.1	2.9	0.4	43	0.2	1.0	0.4	48	0.54
L8600W 12450N	Soil		4.5	40.4	177.0	254	0.6	29.4	10.8	763	3.42	204.6	2.5	12.0	6.4	26	0.8	3.6	1.1	55	0.35
L8600W 12475N	Soil		6.0	60.2	125.7	314	1.1	37.6	11.0	364	3.10	121.7	4.8	8.4	3.4	32	1.4	3.0	0.9	76	0.39
L8600W 12500N	Soil		6.5	55.3	120.9	286	1.2	35.3	11.4	503	3.07	110.8	5.2	7.5	3.2	30	0.9	2.7	0.9	71	0.39
L8600W 12525N	Soil		8.0	55.0	143.9	319	1.2	37.2	14.5	894	3.99	179.9	5.1	6.3	5.9	24	0.7	2.7	1.1	75	0.30
L8600W 12550N	Soil		7.8	54.9	181.3	303	1.7	35.6	12.0	551	3.50	320.3	4.3	11.0	5.3	25	0.7	3.4	1.1	62	0.28
L8600W 12575N	Soil		2.8	37.2	45.6	112	0.6	30.6	11.6	701	3.08	90.4	2.0	12.6	4.7	19	0.5	1.0	0.8	70	0.31
L8600W 12600N	Soil		3.8	54.6	11.9	67	0.2	27.3	11.8	581	3.23	61.0	3.1	80.2	3.3	27	0.2	0.8	1.1	76	0.32
L8600W 12625N	Soil		1.5	18.6	11.1	69	0.1	20.6	7.6	352	2.54	62.8	1.6	5.9	3.7	24	0.2	0.8	1.0	62	0.33
L8600W 12650N	Soil		2.0	25.7	16.6	87	0.1	20.9	15.4	1419	3.53	209.5	3.8	12.7	2.8	18	0.2	1.1	1.5	78	0.19
L8600W 12675N	Soil		1.2	22.0	16.6	162	0.2	18.2	8.9	618	2.98	320.7	4.1	9.3	2.0	20	0.9	1.1	1.3	64	0.24
L8600W 12700N	Soil		1.3	22.7	26.4	149	0.4	18.2	9.1	816	2.93	226.6	4.2	15.3	2.3	15	0.5	1.5	2.1	59	0.18
L8600W 12725N	Soil		0.8	21.5	17.0	142	0.2	20.5	8.5	434	2.63	118.1	2.1	6.3	4.7	18	0.9	1.2	1.3	62	0.30
L8600W 12750N	Soil		0.7	18.9	18.8	171	0.1	18.0	8.2	382	2.71	85.0	3.1	6.6	4.4	18	0.6	1.1	0.5	59	0.26
L8600W 12775N	Soil		0.6	19.5	19.7	122	0.2	19.9	9.2	460	2.45	50.3	1.9	13.5	6.5	20	0.7	0.8	0.3	59	0.35
L8600W 12800N	Soil		1.2	20.6	32.9	146	0.2	18.7	10.4	733	3.02	75.2	3.3	3.2	2.1	20	0.7	1.0	0.4	71	0.26
L8600W 12825N	Soil		0.8	18.5	34.2	134	0.3	21.7	9.5	338	2.85	97.1	2.7	6.6	6.2	20	0.6	1.3	0.6	64	0.34

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

CERTIFICATE OF ANALYSIS SMI09000204.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L8600W 12275N	Soil	0.105	16	45	0.62	299	0.043	2	2.14	0.014	0.08	0.5	0.05	3.5	0.2	0.06	6	0.8
L8600W 12300N	Soil	0.086	18	26	0.60	256	0.034	1	1.48	0.011	0.08	1.0	0.03	3.1	0.1	<0.05	4	<0.5
L8600W 12325N	Soil	0.089	17	30	0.64	257	0.053	2	1.46	0.018	0.07	1.1	0.02	3.0	0.1	<0.05	4	0.6
L8600W 12350N	Soil	0.089	10	32	0.39	230	0.032	1	1.33	0.012	0.05	0.8	0.06	2.1	0.1	0.10	5	0.9
L8600W 12375N	Soil	0.067	18	31	0.67	242	0.039	2	1.77	0.012	0.07	0.8	0.03	3.0	0.1	0.05	6	<0.5
L8600W 12400N	Soil	0.103	18	30	0.42	186	0.037	2	1.46	0.020	0.07	0.2	0.06	2.3	0.1	0.09	5	0.7
L8600W 12425N	Soil	0.088	9	24	0.28	133	0.036	2	1.26	0.022	0.05	0.1	0.03	1.5	<0.1	0.09	4	<0.5
L8600W 12450N	Soil	0.080	16	27	0.52	171	0.035	1	1.29	0.009	0.08	0.5	0.02	2.6	0.2	0.07	4	0.8
L8600W 12475N	Soil	0.105	20	43	0.63	279	0.033	<1	2.22	0.014	0.09	0.3	0.06	4.4	0.2	0.07	7	1.3
L8600W 12500N	Soil	0.108	20	42	0.67	259	0.023	2	2.31	0.012	0.09	0.2	0.08	4.2	0.2	0.10	7	1.6
L8600W 12525N	Soil	0.092	22	45	0.68	249	0.023	2	2.31	0.011	0.09	0.3	0.07	4.8	0.3	<0.05	6	0.9
L8600W 12550N	Soil	0.094	16	38	0.58	207	0.017	2	2.10	0.015	0.08	0.3	0.10	3.6	0.3	<0.05	6	0.6
L8600W 12575N	Soil	0.073	14	41	0.59	160	0.060	2	2.15	0.008	0.06	0.4	0.02	3.6	0.1	<0.05	6	0.7
L8600W 12600N	Soil	0.072	22	45	0.68	236	0.062	<1	2.28	0.012	0.07	0.8	0.04	4.5	0.2	<0.05	6	1.0
L8600W 12625N	Soil	0.056	13	37	0.52	186	0.083	<1	1.93	0.011	0.05	0.7	0.02	3.3	0.2	<0.05	6	0.5
L8600W 12650N	Soil	0.055	19	43	0.51	127	0.070	<1	2.51	0.009	0.05	0.2	0.03	3.4	0.2	<0.05	8	0.9
L8600W 12675N	Soil	0.051	14	36	0.49	108	0.061	<1	1.72	0.008	0.06	0.3	0.03	2.4	0.1	<0.05	7	<0.5
L8600W 12700N	Soil	0.064	19	35	0.43	118	0.049	<1	1.99	0.008	0.06	0.3	0.02	2.8	0.2	<0.05	7	0.8
L8600W 12725N	Soil	0.063	14	30	0.47	103	0.101	1	1.62	0.010	0.08	0.4	0.01	3.0	0.2	<0.05	5	<0.5
L8600W 12750N	Soil	0.035	15	32	0.50	98	0.105	<1	1.65	0.009	0.07	0.3	0.03	3.3	0.1	<0.05	7	<0.5
L8600W 12775N	Soil	0.077	16	29	0.46	127	0.114	<1	1.55	0.013	0.08	0.3	0.01	3.1	0.1	<0.05	5	<0.5
L8600W 12800N	Soil	0.058	16	35	0.52	135	0.083	2	1.86	0.009	0.07	0.2	0.03	3.0	0.2	<0.05	8	<0.5
L8600W 12825N	Soil	0.086	16	33	0.50	107	0.106	<1	2.00	0.014	0.07	0.3	0.03	3.5	0.1	<0.05	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

QUALITY CONTROL REPORT SMI09000204.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
L6400W 12975N	Soil		0.9	35.1	11.7	58	<0.1	20.5	8.7	269	2.94	23.6	2.1	63.7	8.8	18	0.3	2.6	2.3	54	0.18
REP L6400W 12975N	QC		1.0	34.9	11.6	58	<0.1	20.1	8.7	280	2.97	23.6	2.2	34.0	8.7	19	0.3	2.6	2.4	55	0.18
L6400W 14425N	Soil		1.8	27.8	16.2	87	0.1	25.1	11.7	641	3.15	15.1	1.9	6.2	2.2	26	0.6	1.4	0.3	74	0.30
REP L6400W 14425N	QC		1.7	27.6	15.9	89	0.1	24.9	12.0	637	3.09	15.8	2.0	6.5	2.2	25	0.8	1.5	0.3	76	0.32
L6800W 12825N	Soil		1.2	31.4	9.1	56	<0.1	24.5	9.2	344	3.50	14.1	0.9	116.9	6.9	18	0.2	1.0	0.7	65	0.15
REP L6800W 12825N	QC		1.2	29.9	9.3	56	<0.1	24.4	9.5	339	3.47	13.9	0.9	44.7	6.9	18	0.2	0.9	0.7	65	0.14
L7000W 12600N	Soil		1.6	42.8	16.0	45	<0.1	16.9	7.1	361	3.50	25.7	1.7	109.8	14.1	26	<0.1	1.8	1.9	70	0.11
REP L7000W 12600N	QC		1.9	41.8	16.1	45	<0.1	16.8	7.3	349	3.45	25.6	1.8	69.5	14.5	27	0.1	1.7	1.9	70	0.13
L7600W 12325N	Soil		2.1	41.7	14.6	60	0.2	23.9	10.2	302	3.40	78.8	5.5	49.6	7.6	24	0.2	2.3	2.2	65	0.34
REP L7600W 12325N	QC		2.3	42.8	14.4	58	0.2	23.8	9.9	295	3.33	79.7	5.3	21.4	7.7	25	0.2	2.1	2.2	67	0.34
L7600W 12500N	Soil		1.7	29.0	14.5	71	0.1	24.1	13.4	731	3.08	18.6	2.7	4.8	1.8	29	0.2	1.0	0.8	64	0.31
REP L7600W 12500N	QC		1.7	28.9	15.0	72	0.1	24.8	13.1	717	3.08	19.1	2.8	11.0	1.8	29	0.2	1.0	0.8	63	0.29
L8600W 12525N	Soil		8.0	55.0	143.9	319	1.2	37.2	14.5	894	3.99	179.9	5.1	6.3	5.9	24	0.7	2.7	1.1	75	0.30
REP L8600W 12525N	QC		8.2	53.0	142.8	313	1.2	36.2	13.7	838	3.87	180.2	5.2	8.0	6.0	24	0.7	2.9	1.0	72	0.29
L8600W 12650N	Soil		2.0	25.7	16.6	87	0.1	20.9	15.4	1419	3.53	209.5	3.8	12.7	2.8	18	0.2	1.1	1.5	78	0.19
REP L8600W 12650N	QC		2.0	24.8	16.4	85	0.1	21.5	14.5	1449	3.56	210.3	3.7	8.3	2.8	17	0.2	1.0	1.5	76	0.18
Reference Materials																					
STD DS7	Standard		20.8	103.4	67.7	391	0.8	51.8	8.9	602	2.30	51.0	4.7	68.5	4.3	72	6.0	5.9	4.5	83	0.89
STD DS7	Standard		20.1	121.5	76.9	425	0.8	55.6	10.0	619	2.37	52.7	5.5	67.1	4.6	78	6.8	6.6	5.3	85	0.96
STD DS7	Standard		20.1	118.7	76.5	418	0.8	58.3	9.9	596	2.39	53.0	5.4	64.0	4.7	74	6.7	7.0	5.0	85	0.91
STD DS7	Standard		19.7	117.3	77.4	396	0.8	56.7	9.8	607	2.39	51.1	5.6	84.8	5.0	76	6.3	6.8	5.1	84	0.97
STD DS7	Standard		21.8	113.5	75.8	407	0.8	59.6	9.9	608	2.38	50.0	5.0	60.3	4.5	63	5.9	5.3	4.3	87	0.94
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: September 18, 2009

QUALITY CONTROL REPORT SMI09000204.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
L6400W 12975N	Soil	0.050	20	29	0.45	90	0.085	<1	1.76	0.015	0.07	0.3	0.03	2.7	0.2	0.06	5	0.6
REP L6400W 12975N	QC	0.051	19	29	0.42	92	0.088	1	1.75	0.015	0.07	0.2	0.02	2.8	0.2	<0.05	5	<0.5
L6400W 14425N	Soil	0.096	11	34	0.56	183	0.086	1	1.94	0.020	0.09	0.1	0.06	2.8	0.2	0.06	7	0.9
REP L6400W 14425N	QC	0.091	11	34	0.54	182	0.091	1	1.97	0.019	0.09	0.2	0.05	3.0	0.2	<0.05	7	0.7
L6800W 12825N	Soil	0.052	14	38	0.50	101	0.082	1	1.95	0.019	0.08	0.5	0.05	2.8	0.1	0.09	7	<0.5
REP L6800W 12825N	QC	0.051	14	38	0.51	101	0.083	<1	1.99	0.019	0.08	0.4	0.04	2.8	0.1	0.10	7	0.8
L7000W 12600N	Soil	0.044	21	29	0.40	98	0.106	2	1.36	0.021	0.13	0.5	0.02	2.3	0.2	0.14	8	0.9
REP L7000W 12600N	QC	0.041	20	29	0.40	97	0.108	1	1.36	0.022	0.13	0.5	0.04	2.3	0.2	0.15	8	<0.5
L7600W 12325N	Soil	0.074	22	38	0.70	153	0.081	1	2.22	0.013	0.07	0.6	0.04	4.2	0.2	<0.05	7	0.5
REP L7600W 12325N	QC	0.076	23	37	0.72	151	0.084	1	2.17	0.013	0.08	0.6	0.04	4.5	0.2	<0.05	7	0.7
L7600W 12500N	Soil	0.104	16	32	0.61	156	0.065	3	1.82	0.015	0.08	0.8	0.06	2.3	0.2	0.09	7	0.8
REP L7600W 12500N	QC	0.105	16	33	0.64	150	0.065	2	1.91	0.015	0.08	0.8	0.06	2.1	0.2	0.09	7	0.9
L8600W 12525N	Soil	0.092	22	45	0.68	249	0.023	2	2.31	0.011	0.09	0.3	0.07	4.8	0.3	<0.05	6	0.9
REP L8600W 12525N	QC	0.088	22	42	0.65	231	0.020	1	2.19	0.010	0.08	0.3	0.08	4.7	0.3	<0.05	7	1.1
L8600W 12650N	Soil	0.055	19	43	0.51	127	0.070	<1	2.51	0.009	0.05	0.2	0.03	3.4	0.2	<0.05	8	0.9
REP L8600W 12650N	QC	0.052	18	42	0.49	128	0.064	<1	2.42	0.008	0.05	0.2	0.03	3.3	0.2	<0.05	8	1.0
Reference Materials																		
STD DS7	Standard	0.076	12	167	0.96	368	0.112	37	0.93	0.096	0.42	4.5	0.18	2.5	4.4	0.16	4	4.0
STD DS7	Standard	0.078	13	176	1.01	405	0.128	40	1.00	0.087	0.41	4.0	0.18	2.5	4.2	0.22	5	3.7
STD DS7	Standard	0.081	12	171	1.02	405	0.120	42	0.96	0.080	0.42	4.1	0.19	2.1	4.2	0.20	4	3.2
STD DS7	Standard	0.081	12	174	1.04	408	0.121	38	1.00	0.090	0.40	4.2	0.21	2.2	4.1	0.18	5	4.0
STD DS7	Standard	0.074	13	185	1.01	381	0.122	36	0.97	0.074	0.42	4.2	0.18	2.2	4.3	0.21	5	3.9
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: September 26, 2009
Report Date: October 09, 2009
Page: 1 of 6

CERTIFICATE OF ANALYSIS SMI09000287.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC09-20
P.O. Number
Number of Samples: 142

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	142	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	142	Dry at 60C			SMI
1DX15	141	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6000W 13000N	Soil		1.1	54.4	257.9	91	4.3	10.7	5.1	164	3.25	110.7	4.0	141.6	14.3	34	0.4	9.9	3.5	46	0.19
L6000W 13025N	Soil		0.9	40.4	148.4	62	3.4	11.6	4.1	115	2.91	74.5	2.4	103.7	15.5	28	0.4	7.5	2.9	45	0.21
L6000W 13050N	Soil		1.1	41.9	171.4	72	3.0	10.3	4.4	125	3.82	98.9	1.9	135.6	15.2	25	0.3	10.0	3.5	45	0.15
L6000W 13075N	Soil		1.1	33.3	81.4	67	1.7	11.1	5.1	150	3.77	80.6	2.3	185.1	8.6	20	0.3	4.2	2.4	51	0.21
L6000W 13100N	Soil		0.9	32.1	92.5	65	2.1	12.2	5.1	128	2.78	50.3	2.2	71.0	8.5	24	0.4	4.4	2.5	47	0.21
L6000W 13125N	Soil		0.8	39.6	60.2	71	1.5	12.8	5.8	159	3.69	50.8	2.9	82.9	15.7	20	0.3	4.3	2.6	53	0.22
L6000W 13150N	Soil		0.8	46.2	59.3	67	1.8	14.0	5.3	129	3.01	51.4	2.6	64.3	14.1	19	0.3	4.5	3.5	52	0.19
L6000W 13175N	Soil		0.8	36.7	64.6	60	1.6	13.6	5.2	131	3.17	46.5	1.9	46.2	11.2	17	0.3	3.7	3.1	52	0.19
L6000W 13200N	Soil		0.9	28.8	25.0	77	0.5	12.8	6.4	184	4.15	53.6	2.0	51.9	11.9	17	0.2	2.6	1.9	54	0.22
L6000W 13225N	Soil		1.0	30.5	28.4	73	0.6	12.9	7.0	251	3.09	39.3	1.7	68.5	8.3	18	0.2	2.3	1.8	56	0.26
L6000W 13250N	Soil		0.9	43.1	35.3	94	0.7	14.2	9.1	291	2.86	41.2	3.2	61.3	13.3	19	0.5	2.4	1.5	52	0.32
L6000W 13275N	Soil		1.0	41.2	44.0	82	0.9	11.7	7.7	207	3.19	55.6	3.7	44.5	11.8	22	0.3	3.1	2.7	54	0.22
L6000W 13300N	Soil		1.1	44.0	41.6	105	0.7	13.5	10.5	450	3.33	54.9	3.3	47.9	13.2	19	0.3	2.7	2.4	56	0.25
L6000W 13325N	Soil		0.7	25.2	32.1	74	0.6	10.6	5.5	197	2.38	30.7	2.0	131.3	9.8	15	0.3	2.1	1.8	47	0.23
L6000W 13350N	Soil		1.1	28.9	45.6	84	0.9	11.6	6.8	258	3.15	75.5	2.1	54.6	7.9	15	0.3	3.1	2.2	53	0.21
L6000W 13375N	Soil		1.4	23.3	50.3	81	1.1	11.7	6.8	366	3.14	79.2	2.0	44.3	6.9	16	0.3	3.4	3.4	57	0.23
L6000W 13400N	Soil		1.0	30.0	88.1	90	1.9	12.8	6.0	165	3.18	149.3	2.2	56.1	9.9	16	0.3	6.3	7.9	52	0.21
L6000W 13425N	Soil		0.8	32.1	101.7	87	1.8	13.3	10.7	654	2.89	142.3	1.9	75.7	10.3	16	0.3	8.4	5.3	47	0.19
L6000W 13450N	Soil		1.0	37.1	95.0	91	1.6	13.6	9.9	510	3.07	139.2	2.6	177.7	8.2	18	0.4	7.0	4.9	58	0.21
L6000W 13475N	Soil		1.2	28.0	96.5	101	2.0	13.9	23.9	1274	3.25	120.8	2.2	45.7	6.0	20	0.4	5.9	5.1	62	0.21
L6000W 13500N	Soil		1.3	32.5	86.3	67	1.6	11.6	9.5	803	3.03	127.9	3.1	23.6	1.3	16	0.4	3.9	4.5	60	0.14
L6000W 13525N	Soil		1.1	25.5	63.4	68	1.4	10.8	9.0	334	2.74	103.4	2.2	19.3	1.7	17	0.3	4.2	4.5	50	0.16
L6000W 13550N	Soil		1.1	28.2	50.6	82	0.9	13.4	6.1	229	2.65	112.9	2.2	34.3	3.7	16	0.4	4.2	4.2	61	0.20
L6000W 13575N	Soil		1.0	26.3	51.9	80	0.7	15.1	19.6	1725	3.41	88.4	1.5	52.9	7.0	19	0.4	3.8	3.3	61	0.26
L6000W 13600N	Soil		1.0	23.7	36.1	86	0.6	14.8	11.1	609	2.83	53.4	2.0	196.3	4.8	19	0.5	3.3	4.4	61	0.24
L6000W 13625N	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L6000W 13650N	Soil		1.4	31.3	17.4	69	0.2	18.0	15.0	1144	3.47	41.9	2.7	43.4	4.6	20	0.3	2.4	2.8	70	0.26
L6000W 13675N	Soil		1.7	32.8	15.6	67	0.3	18.6	13.2	1229	2.94	63.1	3.6	40.5	3.7	30	0.2	1.9	2.3	64	0.35
L6000W 13700N	Soil		1.2	33.6	10.6	89	0.1	24.1	12.6	713	3.03	76.1	3.2	35.3	3.1	29	0.4	1.0	1.7	72	0.31
L6000W 13725N	Soil		0.8	22.3	10.0	82	0.1	18.4	9.3	459	2.51	77.7	1.7	8.1	5.1	30	0.4	0.8	0.7	64	0.44

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6000W 13000N	Soil	0.075	32	25	0.43	135	0.057	<1	1.83	0.019	0.15	0.9	0.14	3.7	0.3	0.15	6	<0.5
L6000W 13025N	Soil	0.065	29	25	0.38	127	0.069	1	1.38	0.016	0.12	0.8	0.12	3.2	0.3	0.08	5	0.7
L6000W 13050N	Soil	0.062	27	22	0.39	135	0.057	2	1.41	0.015	0.13	1.0	0.11	2.9	0.2	0.11	6	0.6
L6000W 13075N	Soil	0.059	22	25	0.46	101	0.068	1	1.57	0.010	0.10	0.7	0.07	3.6	0.3	0.07	6	<0.5
L6000W 13100N	Soil	0.060	23	26	0.45	125	0.062	1	1.52	0.012	0.09	0.6	0.09	3.3	0.3	0.07	6	<0.5
L6000W 13125N	Soil	0.059	24	30	0.63	109	0.096	1	1.93	0.012	0.14	0.6	0.08	4.9	0.3	<0.05	7	<0.5
L6000W 13150N	Soil	0.046	21	28	0.50	120	0.082	1	1.73	0.013	0.10	0.5	0.08	4.6	0.2	<0.05	5	<0.5
L6000W 13175N	Soil	0.046	20	27	0.51	109	0.082	1	1.71	0.011	0.09	0.6	0.08	3.7	0.2	<0.05	6	<0.5
L6000W 13200N	Soil	0.064	19	29	0.69	83	0.101	1	2.07	0.010	0.14	0.5	0.04	4.4	0.3	<0.05	8	<0.5
L6000W 13225N	Soil	0.075	17	26	0.57	93	0.104	1	1.59	0.012	0.13	0.7	0.03	3.9	0.2	<0.05	6	<0.5
L6000W 13250N	Soil	0.077	27	29	0.58	106	0.109	1	1.75	0.014	0.14	0.8	0.03	4.6	0.3	<0.05	6	0.6
L6000W 13275N	Soil	0.067	26	28	0.57	120	0.093	1	1.89	0.012	0.14	0.5	0.05	4.7	0.4	<0.05	7	0.5
L6000W 13300N	Soil	0.071	23	30	0.62	110	0.111	1	2.04	0.012	0.14	0.4	0.02	4.7	0.4	<0.05	8	<0.5
L6000W 13325N	Soil	0.062	18	24	0.59	83	0.106	1	1.84	0.012	0.11	0.5	0.03	3.8	0.3	<0.05	6	<0.5
L6000W 13350N	Soil	0.071	18	26	0.55	87	0.091	<1	1.73	0.010	0.10	0.5	0.04	3.6	0.3	<0.05	7	<0.5
L6000W 13375N	Soil	0.080	17	27	0.60	91	0.095	<1	1.68	0.011	0.11	0.4	0.04	4.0	0.2	<0.05	7	<0.5
L6000W 13400N	Soil	0.058	20	27	0.55	97	0.086	1	1.84	0.010	0.11	0.3	0.06	3.6	0.3	<0.05	7	<0.5
L6000W 13425N	Soil	0.065	21	24	0.48	94	0.071	<1	1.67	0.010	0.10	0.4	0.03	3.0	0.3	<0.05	6	<0.5
L6000W 13450N	Soil	0.069	23	28	0.47	121	0.080	2	1.90	0.011	0.11	0.4	0.04	3.6	0.3	<0.05	6	<0.5
L6000W 13475N	Soil	0.074	18	30	0.56	129	0.073	2	2.08	0.011	0.10	0.3	0.05	3.6	0.3	<0.05	7	<0.5
L6000W 13500N	Soil	0.109	12	32	0.38	104	0.035	1	1.61	0.011	0.05	0.2	0.06	2.3	0.4	0.12	6	0.5
L6000W 13525N	Soil	0.079	14	27	0.39	98	0.033	1	1.49	0.011	0.05	0.2	0.04	2.3	0.3	0.07	5	<0.5
L6000W 13550N	Soil	0.073	16	31	0.49	99	0.065	1	1.84	0.012	0.07	0.2	0.04	2.9	0.3	<0.05	6	<0.5
L6000W 13575N	Soil	0.079	16	28	0.47	101	0.094	1	1.51	0.013	0.10	0.6	0.02	2.8	0.2	<0.05	5	<0.5
L6000W 13600N	Soil	0.071	16	30	0.52	122	0.077	2	1.89	0.013	0.08	0.4	0.03	3.0	0.2	<0.05	7	<0.5
L6000W 13625N	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
L6000W 13650N	Soil	0.077	16	38	0.55	123	0.086	2	1.81	0.013	0.09	0.5	0.03	3.4	0.2	<0.05	6	0.6
L6000W 13675N	Soil	0.071	19	35	0.53	143	0.075	2	1.81	0.019	0.08	0.4	0.02	3.3	0.2	0.06	6	0.6
L6000W 13700N	Soil	0.066	19	35	0.61	224	0.078	2	2.19	0.016	0.08	0.5	0.02	3.4	0.2	<0.05	7	0.5
L6000W 13725N	Soil	0.078	15	29	0.49	196	0.087	1	1.62	0.024	0.09	1.1	0.04	3.1	0.1	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6000W 13750N	Soil		0.9	21.6	28.2	94	0.1	19.1	9.4	452	2.47	67.2	1.6	21.5	5.5	26	0.7	0.9	0.5	60	0.40
L6000W 13775N	Soil		0.9	15.6	21.6	115	0.1	16.1	9.1	546	2.58	125.6	1.7	6.6	5.0	23	0.4	1.1	0.7	57	0.36
L6000W 13800N	Soil		1.4	20.6	23.4	112	0.2	18.3	11.9	540	3.08	150.2	2.7	12.5	3.8	33	0.5	1.6	1.5	67	0.50
L6000W 13825N	Soil		0.7	18.2	12.3	71	<0.1	13.2	8.6	285	2.46	45.0	1.7	70.2	6.4	22	0.3	1.8	0.9	64	0.41
L6000W 13850N	Soil		1.1	22.7	14.7	83	0.1	17.2	10.5	451	2.67	53.8	2.3	147.9	5.0	29	0.3	1.7	2.1	65	0.41
L6000W 13875N	Soil		1.6	25.7	17.1	84	0.1	22.0	14.2	739	3.17	82.0	2.7	64.6	5.9	23	0.5	1.7	2.9	69	0.23
L6000W 13900N	Soil		0.9	21.6	13.7	76	0.1	15.3	9.2	453	2.51	68.7	2.0	239.3	5.2	22	0.3	1.5	1.3	60	0.30
L6000W 13925N	Soil		1.4	28.5	17.6	144	0.3	14.2	10.7	633	3.15	433.1	3.3	293.3	5.9	38	0.9	7.4	1.9	62	0.57
L6000W 13950N	Soil		1.5	27.3	18.4	138	0.3	17.4	11.6	859	3.02	317.0	3.7	35.9	5.8	41	0.6	2.9	1.0	68	0.61
L6000W 13975N	Soil		1.0	19.8	17.3	93	0.1	15.5	9.3	527	2.51	121.1	2.0	7.1	5.2	27	0.6	2.3	0.7	59	0.41
L6000W 14000N	Soil		1.7	31.6	22.3	122	0.3	20.9	13.2	626	3.28	186.0	5.1	15.6	4.7	32	0.4	2.1	1.3	64	0.40
L6000W 14025N	Soil		0.9	25.1	31.9	295	0.2	10.2	10.8	1038	3.11	328.3	2.6	9.9	11.2	32	1.0	4.7	0.7	54	0.60
L6000W 14050N	Soil		0.8	17.4	19.1	118	0.1	14.9	10.1	552	2.58	175.3	2.0	85.2	7.0	24	0.5	2.4	0.9	58	0.34
L6000W 14075N	Soil		0.8	20.5	19.5	120	0.3	15.9	9.3	487	2.52	173.8	2.2	189.7	5.1	34	0.5	2.8	0.8	58	0.53
L6000W 14100N	Soil		0.9	17.1	20.2	145	0.1	14.6	9.8	504	2.67	254.1	1.9	10.3	6.3	28	0.6	3.3	0.6	58	0.38
L6000W 14125N	Soil		0.9	17.3	28.4	164	0.2	16.6	9.6	478	2.67	207.6	1.5	20.2	5.2	28	0.8	4.6	0.6	60	0.36
L6000W 14150N	Soil		1.7	21.5	37.0	183	0.3	20.4	12.1	713	3.15	251.7	2.3	13.8	3.5	38	0.5	5.8	0.9	70	0.53
L6000W 14175N	Soil		0.7	46.8	36.5	202	0.1	11.5	13.7	842	3.66	159.9	1.8	13.7	7.3	26	0.8	4.9	6.2	81	0.46
L6000W 14200N	Soil		0.8	18.4	26.3	131	0.2	18.9	10.6	573	2.64	74.0	1.2	886.5	5.6	23	0.7	2.0	0.2	66	0.34
L6000W 14225N	Soil		1.1	19.4	34.2	152	0.2	23.4	12.0	551	3.03	115.2	1.4	12.1	5.6	22	0.9	3.3	0.5	72	0.33
L6000W 14250N	Soil		1.3	23.7	42.2	144	0.3	25.2	13.3	767	3.44	121.2	2.8	6.0	6.0	24	0.6	5.8	0.3	79	0.33
L6000W 14275N	Soil		1.5	21.2	86.4	190	0.9	21.7	14.8	1039	3.20	128.9	3.0	9.4	7.6	22	0.9	9.6	0.4	75	0.27
L6000W 14300N	Soil		1.5	22.1	72.1	183	0.4	20.3	13.3	742	3.23	120.2	2.8	10.2	6.5	17	0.9	7.4	0.3	79	0.23
L6000W 14325N	Soil		1.1	18.7	21.7	69	0.1	21.9	11.3	432	2.88	40.0	1.1	5.3	5.2	19	0.4	2.1	0.2	72	0.29
L6000W 14350N	Soil		2.3	28.1	42.8	136	0.5	25.0	14.4	1176	3.51	101.1	4.3	10.9	4.7	48	0.6	6.2	0.3	88	0.78
L6000W 14375N	Soil		1.2	23.3	27.7	96	0.2	20.9	13.6	840	3.19	63.9	3.0	7.3	7.8	22	0.5	4.5	0.2	84	0.34
L6000W 14400N	Soil		0.9	15.3	22.0	87	<0.1	18.9	12.2	598	2.81	38.0	1.2	20.3	6.5	18	0.4	3.2	0.2	73	0.30
L6000W 14425N	Soil		0.7	22.2	18.6	79	0.1	21.1	10.7	557	2.63	38.6	2.0	45.0	5.5	26	0.5	2.6	0.2	74	0.41
L6000W 14450N	Soil		4.4	68.5	74.2	198	0.5	50.5	25.9	1545	6.44	138.4	11.9	6.4	10.8	32	0.5	3.0	0.8	150	0.44
L6000W 14475N	Soil		0.8	24.1	16.1	76	<0.1	22.0	12.3	517	2.78	26.5	1.7	4.8	6.2	22	0.4	0.8	0.2	71	0.35

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
		Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
		MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6000W 13750N	Soil		0.082	15	27	0.56	163	0.098	1	1.32	0.024	0.10	0.4	0.02	3.2	0.1	<0.05	4	<0.5
L6000W 13775N	Soil		0.065	12	28	0.52	189	0.082	<1	1.61	0.018	0.08	0.8	0.02	2.8	0.2	<0.05	5	<0.5
L6000W 13800N	Soil		0.053	16	34	0.53	252	0.072	1	1.95	0.017	0.07	0.3	0.04	3.7	0.2	0.05	6	<0.5
L6000W 13825N	Soil		0.090	13	25	0.54	173	0.094	<1	1.19	0.021	0.11	0.4	0.02	2.7	0.2	<0.05	4	<0.5
L6000W 13850N	Soil		0.074	14	28	0.53	261	0.079	<1	1.83	0.020	0.08	0.6	0.03	3.1	0.1	<0.05	5	<0.5
L6000W 13875N	Soil		0.071	13	30	0.50	259	0.069	<1	2.53	0.022	0.08	0.2	0.03	3.1	0.1	<0.05	7	<0.5
L6000W 13900N	Soil		0.069	16	27	0.47	212	0.078	<1	1.70	0.022	0.07	0.3	0.02	2.7	0.1	<0.05	5	<0.5
L6000W 13925N	Soil		0.088	20	24	0.57	319	0.079	1	1.67	0.021	0.15	0.3	0.04	3.3	0.2	<0.05	6	<0.5
L6000W 13950N	Soil		0.081	21	28	0.54	350	0.073	1	1.83	0.021	0.13	0.4	0.03	4.1	0.2	<0.05	6	<0.5
L6000W 13975N	Soil		0.067	14	23	0.49	243	0.075	1	1.47	0.023	0.08	0.3	0.02	2.9	0.1	<0.05	5	<0.5
L6000W 14000N	Soil		0.073	31	32	0.50	343	0.050	1	2.55	0.019	0.07	0.3	0.05	4.2	0.2	<0.05	7	0.6
L6000W 14025N	Soil		0.109	22	17	0.52	406	0.047	<1	1.69	0.027	0.12	0.4	0.03	4.3	0.2	<0.05	6	<0.5
L6000W 14050N	Soil		0.065	15	22	0.51	273	0.081	<1	1.66	0.023	0.11	0.5	0.02	2.7	0.1	<0.05	5	<0.5
L6000W 14075N	Soil		0.075	15	25	0.48	258	0.076	2	1.72	0.026	0.09	0.3	0.02	2.7	0.1	<0.05	5	<0.5
L6000W 14100N	Soil		0.056	13	22	0.50	293	0.093	1	1.55	0.032	0.11	0.4	0.03	2.7	0.1	<0.05	5	<0.5
L6000W 14125N	Soil		0.060	14	24	0.51	277	0.094	2	1.64	0.024	0.10	0.4	0.02	3.0	0.1	<0.05	5	<0.5
L6000W 14150N	Soil		0.053	15	33	0.48	292	0.054	2	2.00	0.020	0.08	0.3	0.04	3.4	0.2	<0.05	7	<0.5
L6000W 14175N	Soil		0.094	15	22	0.83	538	0.120	1	2.61	0.022	0.36	0.5	0.03	3.8	0.4	<0.05	8	<0.5
L6000W 14200N	Soil		0.078	13	29	0.49	182	0.100	1	1.72	0.022	0.08	0.4	0.03	2.9	0.1	<0.05	5	<0.5
L6000W 14225N	Soil		0.071	12	32	0.52	183	0.089	2	2.26	0.020	0.08	0.5	0.02	2.8	0.1	<0.05	5	<0.5
L6000W 14250N	Soil		0.072	15	34	0.56	246	0.084	2	2.42	0.021	0.10	0.4	0.04	3.9	0.1	<0.05	7	<0.5
L6000W 14275N	Soil		0.053	14	31	0.56	240	0.087	2	2.32	0.022	0.09	0.3	0.05	3.8	0.2	<0.05	7	<0.5
L6000W 14300N	Soil		0.058	16	32	0.53	249	0.093	2	2.34	0.021	0.09	0.3	0.04	3.8	0.2	<0.05	7	<0.5
L6000W 14325N	Soil		0.067	11	32	0.50	153	0.102	2	2.40	0.018	0.07	0.4	0.04	3.0	0.1	<0.05	5	<0.5
L6000W 14350N	Soil		0.076	18	39	0.67	383	0.101	3	2.58	0.025	0.13	0.2	0.05	4.9	0.3	<0.05	8	0.6
L6000W 14375N	Soil		0.053	17	32	0.61	266	0.127	<1	1.98	0.025	0.12	0.2	0.03	4.0	0.2	<0.05	6	<0.5
L6000W 14400N	Soil		0.058	12	28	0.55	162	0.114	<1	1.68	0.022	0.09	0.4	0.02	2.7	0.1	<0.05	5	<0.5
L6000W 14425N	Soil		0.081	16	30	0.58	216	0.109	1	1.65	0.025	0.09	0.3	0.03	3.8	0.1	<0.05	4	<0.5
L6000W 14450N	Soil		0.105	34	62	1.07	696	0.128	3	5.45	0.017	0.24	0.3	0.10	10.1	0.5	<0.05	13	0.7
L6000W 14475N	Soil		0.079	15	32	0.64	233	0.127	<1	1.92	0.028	0.11	0.3	0.02	3.1	0.2	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6000W 14500N	Soil		1.0	20.7	28.9	89	0.2	18.9	11.9	554	2.87	44.2	3.2	5.3	7.4	20	0.6	1.2	0.3	77	0.35
L6200W 13000N	Soil		1.3	60.8	14.5	84	0.2	21.8	10.7	521	3.09	24.4	3.0	145.2	8.2	22	0.6	1.7	3.6	56	0.22
L6200W 13025N	Soil		1.6	24.3	11.4	57	<0.1	25.1	10.9	384	3.87	13.2	0.8	43.4	4.3	14	0.4	0.8	0.8	82	0.15
L6200W 13050N	Soil		1.0	57.5	28.5	82	0.3	23.5	10.5	360	3.11	29.0	5.5	27.1	7.5	20	0.4	1.8	1.8	67	0.25
L6200W 13075N	Soil		1.2	85.9	45.1	95	0.7	17.4	9.6	384	3.17	57.5	6.2	180.9	10.7	32	0.6	3.0	2.3	61	0.33
L6200W 13100N	Soil		1.3	64.1	75.9	103	0.7	16.7	14.3	1105	3.41	77.3	3.6	276.0	8.5	24	0.5	4.3	2.8	63	0.25
L6200W 13125N	Soil		1.1	39.2	13.4	65	0.1	24.3	11.9	465	3.25	23.1	2.2	56.0	8.1	18	0.4	1.2	1.6	63	0.21
L6200W 13150N	Soil		1.1	46.4	18.8	75	0.3	22.7	12.1	240	2.93	49.3	3.2	264.0	8.9	18	0.5	1.5	2.8	55	0.24
L6200W 13175N	Soil		2.6	60.1	34.9	103	0.6	26.0	16.1	806	4.70	97.5	6.4	32.0	6.7	23	0.8	2.4	4.5	86	0.21
L6200W 13200N	Soil		1.7	113.8	23.2	95	0.4	22.5	15.1	550	4.64	114.3	6.2	358.0	15.9	30	0.4	3.9	9.5	57	0.23
L6200W 13225N	Soil		1.4	32.9	15.1	62	0.2	23.5	11.6	446	3.11	35.9	2.4	71.6	7.8	17	0.2	1.1	1.6	67	0.22
L6200W 13250N	Soil		1.7	37.8	21.9	48	0.5	10.2	4.8	205	4.47	81.9	3.1	2287	8.4	24	0.1	5.9	13.2	48	0.11
L6200W 13275N	Soil		1.7	44.6	11.0	74	0.2	10.2	14.4	449	5.42	43.4	10.2	61.4	14.5	69	0.3	8.3	13.2	93	0.36
L6200W 13300N	Soil		2.0	54.6	32.7	80	0.7	19.2	11.7	602	3.47	73.6	9.3	47.6	7.5	23	0.2	3.4	3.0	59	0.28
L6200W 13325N	Soil		1.3	41.8	18.0	74	0.3	21.4	14.0	664	3.55	35.9	4.4	59.5	9.4	20	0.4	2.0	1.9	75	0.27
L6200W 13350N	Soil		1.1	35.4	16.7	60	<0.1	13.8	9.3	409	3.47	35.4	3.0	79.8	10.9	18	0.2	3.8	1.3	56	0.23
L6200W 13375N	Soil		1.5	38.6	20.7	74	0.3	18.6	10.3	547	3.51	57.9	3.4	118.0	9.4	20	0.3	3.3	3.5	64	0.22
L6200W 13400N	Soil		1.4	51.9	24.0	68	0.6	19.5	10.6	376	3.46	55.5	4.7	102.3	9.6	19	0.2	3.1	3.6	62	0.24
L6200W 13425N	Soil		1.0	53.7	19.1	61	0.6	15.1	7.3	174	3.06	63.0	3.5	82.9	12.3	18	0.2	3.3	4.4	53	0.22
L6200W 13450N	Soil		1.2	60.0	16.5	58	0.5	15.5	7.8	154	2.99	45.8	4.0	88.1	12.7	18	0.2	3.2	6.3	54	0.19
L6200W 13475N	Soil		1.1	30.3	15.1	48	0.4	15.2	8.8	310	2.61	20.2	3.2	46.4	5.6	15	0.2	2.0	4.2	48	0.20
L6200W 13500N	Soil		1.0	28.6	17.3	66	0.3	19.4	10.5	515	2.52	16.5	3.2	29.5	6.5	17	0.3	2.1	5.4	54	0.22
L6200W 13525N	Soil		0.9	24.7	13.8	52	0.3	15.5	7.7	275	3.30	39.0	2.3	14.7	6.2	15	0.1	1.9	4.8	55	0.20
L6200W 13550N	Soil		1.4	31.2	12.9	77	0.2	22.2	12.8	723	3.32	73.6	4.0	25.0	3.5	21	0.2	1.2	2.0	70	0.20
L6200W 13575N	Soil		1.2	27.7	11.3	87	0.1	19.2	11.0	633	2.97	90.8	2.9	43.6	3.2	24	0.3	0.9	1.3	69	0.29
L6200W 13600N	Soil		1.1	19.7	11.4	64	0.1	17.5	8.3	358	2.81	80.4	1.3	10.8	2.7	21	0.3	0.8	0.6	70	0.27
L6200W 13625N	Soil		0.5	18.0	8.6	64	<0.1	16.3	7.9	347	2.27	51.1	1.3	10.1	5.5	20	0.4	0.7	0.3	60	0.37
L6200W 13650N	Soil		1.2	18.6	40.3	115	0.3	17.7	9.3	237	2.77	125.9	4.1	9.9	6.8	23	0.4	1.2	0.5	61	0.34
L6200W 13675N	Soil		1.0	15.6	38.8	121	0.3	17.5	8.0	259	2.27	74.7	3.5	18.1	6.0	24	0.5	1.2	0.6	61	0.33
L6200W 13700N	Soil		1.1	17.1	29.5	114	0.3	18.6	6.9	256	2.50	139.9	3.2	12.4	3.0	31	0.5	1.2	0.7	54	0.40

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6000W 14500N	Soil	0.086	16	29	0.59	202	0.120	1	1.93	0.023	0.12	0.6	0.02	3.4	0.2	<0.05	5	0.6
L6200W 13000N	Soil	0.064	20	27	0.43	114	0.086	2	1.66	0.028	0.12	0.5	0.06	2.8	0.1	0.16	5	<0.5
L6200W 13025N	Soil	0.029	10	39	0.46	89	0.097	1	2.42	0.013	0.05	0.2	0.04	3.1	0.1	<0.05	8	<0.5
L6200W 13050N	Soil	0.064	23	36	0.58	133	0.091	1	2.35	0.016	0.08	0.2	0.07	4.2	0.1	0.05	7	0.5
L6200W 13075N	Soil	0.082	35	27	0.48	125	0.094	<1	1.51	0.027	0.14	1.4	0.04	3.8	0.2	0.14	5	0.9
L6200W 13100N	Soil	0.073	19	27	0.45	109	0.076	1	1.62	0.019	0.10	0.5	0.05	3.0	0.1	0.11	6	0.8
L6200W 13125N	Soil	0.057	14	31	0.56	104	0.093	2	2.00	0.016	0.08	0.5	0.03	2.9	0.2	0.09	6	0.6
L6200W 13150N	Soil	0.071	16	30	0.54	100	0.095	1	1.99	0.013	0.08	1.1	0.05	3.0	0.2	<0.05	7	0.5
L6200W 13175N	Soil	0.080	23	42	0.66	182	0.072	2	2.55	0.025	0.08	0.5	0.10	3.6	0.3	0.10	9	0.5
L6200W 13200N	Soil	0.098	28	28	0.51	138	0.071	2	1.76	0.022	0.13	1.2	0.03	3.3	0.2	0.20	7	<0.5
L6200W 13225N	Soil	0.060	13	34	0.56	104	0.092	1	2.25	0.017	0.06	1.5	0.04	3.3	0.2	<0.05	7	0.7
L6200W 13250N	Soil	0.056	16	20	0.29	141	0.064	3	1.12	0.041	0.35	0.5	0.03	2.0	0.4	0.74	7	0.8
L6200W 13275N	Soil	0.113	30	26	0.80	340	0.157	<1	2.21	0.041	0.71	0.3	0.03	6.6	0.8	0.44	8	<0.5
L6200W 13300N	Soil	0.091	27	31	0.55	135	0.059	<1	1.99	0.017	0.09	0.4	0.07	3.7	0.3	<0.05	7	0.9
L6200W 13325N	Soil	0.081	19	33	0.68	158	0.115	1	1.94	0.014	0.13	0.6	0.03	3.7	0.2	<0.05	7	0.8
L6200W 13350N	Soil	0.054	15	27	0.63	83	0.076	<1	1.98	0.011	0.16	0.3	0.02	3.1	0.3	0.07	8	<0.5
L6200W 13375N	Soil	0.070	19	31	0.59	117	0.097	1	1.88	0.013	0.13	0.5	0.04	3.3	0.3	0.07	8	0.7
L6200W 13400N	Soil	0.079	20	32	0.61	136	0.082	1	1.97	0.013	0.10	0.5	0.05	3.9	0.3	<0.05	7	0.7
L6200W 13425N	Soil	0.057	21	30	0.56	111	0.100	<1	1.66	0.012	0.09	0.4	0.03	4.1	0.3	<0.05	6	<0.5
L6200W 13450N	Soil	0.061	22	29	0.55	119	0.087	1	1.90	0.010	0.09	0.3	0.03	4.0	0.3	<0.05	6	0.5
L6200W 13475N	Soil	0.057	17	32	0.48	114	0.076	1	1.81	0.011	0.07	0.4	0.05	3.6	0.3	<0.05	6	<0.5
L6200W 13500N	Soil	0.059	15	37	0.66	126	0.098	2	2.20	0.012	0.09	0.3	0.04	3.8	0.3	<0.05	8	0.5
L6200W 13525N	Soil	0.065	15	29	0.57	101	0.093	1	1.72	0.011	0.07	0.4	0.03	3.2	0.3	<0.05	7	<0.5
L6200W 13550N	Soil	0.074	19	33	0.60	181	0.073	2	2.23	0.013	0.07	0.7	0.02	3.2	0.2	<0.05	7	0.6
L6200W 13575N	Soil	0.074	13	33	0.61	193	0.076	1	2.04	0.016	0.08	0.7	0.03	2.8	0.2	0.07	7	0.8
L6200W 13600N	Soil	0.060	10	29	0.49	129	0.084	1	1.88	0.017	0.06	0.4	0.05	2.6	0.1	<0.05	7	<0.5
L6200W 13625N	Soil	0.081	12	23	0.49	142	0.099	<1	1.44	0.023	0.07	0.4	0.03	2.4	0.1	<0.05	4	0.7
L6200W 13650N	Soil	0.067	19	32	0.54	175	0.079	2	2.28	0.018	0.07	0.5	0.04	4.2	0.2	<0.05	6	<0.5
L6200W 13675N	Soil	0.063	18	31	0.54	197	0.076	1	2.10	0.016	0.07	0.4	0.03	4.0	0.2	0.07	6	0.6
L6200W 13700N	Soil	0.077	15	32	0.49	196	0.066	2	2.10	0.019	0.05	0.4	0.05	3.2	0.2	0.07	6	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6200W 13725N	Soil		1.3	20.9	26.0	117	0.2	19.5	13.2	1066	3.01	157.6	3.9	20.4	7.5	25	0.5	2.1	1.4	65	0.44
L6200W 13750N	Soil		1.8	24.9	32.5	114	0.3	23.1	10.4	409	3.64	201.9	4.2	28.8	4.6	31	0.3	2.2	1.8	85	0.44
L6200W 13775N	Soil		1.6	21.2	26.9	105	0.1	18.1	10.5	514	3.23	131.8	2.9	22.0	7.1	28	0.6	2.2	1.6	74	0.40
L6200W 13800N	Soil		1.1	23.2	18.5	74	0.1	16.3	10.1	457	2.91	66.0	2.1	96.4	8.0	23	0.3	2.5	2.4	63	0.35
L6200W 13825N	Soil		1.8	26.4	20.3	61	0.2	18.6	10.5	323	3.32	70.6	3.5	29.5	7.3	16	0.4	2.1	3.2	76	0.19
L6200W 13850N	Soil		0.9	21.2	12.7	63	0.1	16.6	9.7	440	2.63	52.2	2.2	629.9	7.5	24	0.3	1.6	1.6	60	0.31
L6200W 13875N	Soil		1.5	35.5	20.0	87	0.1	24.3	12.9	585	3.38	113.3	4.3	41.6	8.0	26	0.4	2.2	2.0	69	0.28
L6200W 13900N	Soil		1.0	18.4	11.2	52	<0.1	17.2	8.5	449	2.23	36.3	1.7	26.3	4.5	18	0.2	1.0	0.6	52	0.27
L6200W 13925N	Soil		1.7	21.3	25.4	88	0.2	17.3	8.6	387	3.05	171.9	2.7	33.2	5.7	21	0.4	1.7	2.1	69	0.25
L6200W 13950N	Soil		1.9	24.5	26.8	116	0.2	20.7	10.5	575	3.08	185.0	3.1	18.5	5.2	34	0.4	2.3	1.4	66	0.51
L6200W 13975N	Soil		1.1	21.5	22.8	96	0.2	17.3	8.8	562	2.62	170.3	4.1	14.0	8.0	26	0.2	2.1	0.9	57	0.33
L6200W 14000N	Soil		0.9	18.1	60.8	173	0.3	15.5	9.2	595	2.74	328.2	3.3	36.2	8.3	31	1.1	5.7	1.0	51	0.36
L6200W 14025N	Soil		0.8	19.9	21.2	86	0.1	16.7	9.6	524	2.46	116.2	3.2	46.8	8.0	32	0.5	2.7	1.1	57	0.37
L6200W 14050N	Soil		1.2	26.2	50.9	145	0.3	18.3	12.4	805	2.78	303.2	4.8	25.2	7.2	26	1.1	5.2	1.5	59	0.27
L6200W 14075N	Soil		0.8	22.3	28.1	108	0.2	18.2	9.7	350	2.44	108.9	3.2	14.5	7.3	26	0.5	3.2	1.2	57	0.31
L6200W 14100N	Soil		1.1	23.3	27.2	137	0.2	19.5	9.7	555	2.56	117.9	3.3	8.3	5.2	29	0.7	2.2	1.1	60	0.35
L6200W 14125N	Soil		2.8	23.9	47.8	95	0.2	15.9	7.4	293	3.14	388.6	1.9	87.9	3.6	18	0.6	8.9	0.8	84	0.13
L6200W 14150N	Soil		0.9	23.1	53.4	184	0.2	19.0	12.2	760	2.89	183.5	3.5	12.2	8.7	33	1.2	7.9	0.4	69	0.43
L6200W 14175N	Soil		0.9	25.0	62.0	198	0.3	18.1	9.9	581	2.45	98.7	3.6	7.3	7.5	31	1.3	3.1	0.4	61	0.39
L6200W 14200N	Soil		1.1	26.5	54.0	128	0.2	18.3	12.7	772	2.97	105.8	5.7	30.5	9.9	33	0.8	5.1	2.3	72	0.43
L6200W 14225N	Soil		1.3	27.8	51.4	186	0.4	24.1	13.3	812	3.35	152.6	3.8	10.7	7.7	30	0.9	7.9	0.6	75	0.32
L6200W 14250N	Soil		1.7	28.0	130.6	201	0.4	22.8	14.3	540	3.72	203.2	4.6	20.4	9.6	22	0.9	13.1	0.5	83	0.22
L6200W 14275N	Soil		1.3	20.1	85.3	193	0.3	18.8	11.1	605	2.96	112.1	2.2	123.1	5.4	26	1.9	7.9	0.4	67	0.30
L6200W 14300N	Soil		2.4	44.6	12.1	92	0.1	26.2	15.9	932	3.06	12.9	2.3	2.5	1.9	28	0.4	1.1	0.2	70	0.30
L6200W 14325N	Soil		2.3	19.7	40.1	106	0.1	15.3	6.9	298	3.09	92.0	1.0	3.8	3.2	16	0.4	4.9	0.4	96	0.15
L6200W 14350N	Soil		2.3	28.9	44.7	174	0.4	24.0	14.0	606	3.71	181.6	3.6	14.5	7.7	26	0.7	8.7	0.5	86	0.23
L6200W 14375N	Soil		1.9	34.7	10.2	64	<0.1	16.0	8.0	453	2.44	9.3	2.1	1.0	0.7	18	0.3	0.9	0.3	61	0.14
L6200W 14400N	Soil		2.8	23.4	55.7	151	0.3	18.4	10.3	471	3.80	139.4	3.9	5.1	4.6	28	0.7	5.4	0.5	93	0.35
L6200W 14425N	Soil		1.5	28.4	7.7	46	<0.1	10.7	5.0	261	1.92	6.0	1.2	1.5	0.7	15	0.2	0.6	0.2	53	0.13
L6200W 14450N	Soil		0.9	22.2	31.7	85	0.1	18.6	11.0	540	2.67	29.2	1.8	13.8	6.7	19	0.5	1.3	0.3	74	0.27

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6200W 13725N	Soil	0.084	21	33	0.59	224	0.097	2	2.05	0.018	0.09	0.4	0.04	4.8	0.2	0.05	6	0.7
L6200W 13750N	Soil	0.077	17	37	0.62	268	0.081	1	2.44	0.017	0.08	0.2	0.03	4.2	0.3	0.08	8	<0.5
L6200W 13775N	Soil	0.051	14	30	0.56	245	0.101	1	2.03	0.018	0.09	0.3	0.03	3.6	0.2	<0.05	7	0.8
L6200W 13800N	Soil	0.076	13	25	0.56	229	0.109	1	1.88	0.024	0.10	0.4	0.02	3.1	0.2	<0.05	6	0.6
L6200W 13825N	Soil	0.054	22	33	0.50	189	0.088	2	2.78	0.016	0.07	0.2	0.06	3.8	0.2	<0.05	8	0.7
L6200W 13850N	Soil	0.068	14	25	0.54	232	0.096	<1	1.88	0.022	0.08	0.4	0.02	3.0	0.1	<0.05	5	<0.5
L6200W 13875N	Soil	0.070	23	36	0.54	299	0.073	<1	2.84	0.017	0.08	0.4	0.04	4.6	0.2	<0.05	8	<0.5
L6200W 13900N	Soil	0.078	11	22	0.45	153	0.081	1	1.67	0.019	0.06	0.3	0.05	2.4	<0.1	<0.05	5	<0.5
L6200W 13925N	Soil	0.047	14	30	0.44	205	0.072	<1	2.25	0.017	0.07	0.3	0.04	3.3	0.2	<0.05	7	<0.5
L6200W 13950N	Soil	0.073	13	31	0.51	274	0.063	2	2.23	0.022	0.08	0.3	0.04	3.4	0.2	0.08	6	<0.5
L6200W 13975N	Soil	0.066	20	27	0.47	290	0.088	<1	1.74	0.024	0.10	0.5	0.03	3.4	0.2	<0.05	5	0.6
L6200W 14000N	Soil	0.067	20	23	0.52	311	0.075	1	1.67	0.025	0.11	0.4	0.04	2.9	0.2	0.08	5	<0.5
L6200W 14025N	Soil	0.077	19	27	0.53	246	0.100	2	1.84	0.027	0.08	0.3	0.03	4.0	0.2	<0.05	5	<0.5
L6200W 14050N	Soil	0.069	22	27	0.51	258	0.067	2	2.22	0.023	0.08	0.3	0.05	4.1	0.2	<0.05	6	<0.5
L6200W 14075N	Soil	0.068	15	29	0.50	192	0.076	2	1.94	0.024	0.06	0.3	0.03	3.7	0.2	<0.05	5	<0.5
L6200W 14100N	Soil	0.066	15	27	0.52	199	0.070	2	2.00	0.021	0.07	0.2	0.05	3.6	0.1	<0.05	5	0.6
L6200W 14125N	Soil	0.045	8	26	0.28	120	0.067	2	2.12	0.013	0.05	0.3	0.05	2.9	0.2	<0.05	9	0.5
L6200W 14150N	Soil	0.087	19	29	0.62	282	0.121	2	1.87	0.029	0.13	0.4	0.03	4.5	0.2	<0.05	5	<0.5
L6200W 14175N	Soil	0.078	18	27	0.55	232	0.105	1	1.61	0.023	0.09	0.3	0.02	4.6	0.2	<0.05	5	<0.5
L6200W 14200N	Soil	0.092	19	31	0.58	289	0.122	1	1.67	0.025	0.09	0.5	0.03	5.6	0.2	<0.05	5	0.5
L6200W 14225N	Soil	0.086	16	33	0.57	266	0.101	2	2.76	0.021	0.09	0.4	0.04	4.5	0.2	<0.05	7	<0.5
L6200W 14250N	Soil	0.047	18	36	0.62	227	0.066	2	3.01	0.025	0.07	0.2	0.04	5.5	0.3	<0.05	8	<0.5
L6200W 14275N	Soil	0.066	15	27	0.51	220	0.095	2	1.80	0.021	0.09	0.3	0.05	3.8	0.1	<0.05	6	0.6
L6200W 14300N	Soil	0.115	6	32	0.63	173	0.072	2	2.55	0.028	0.08	<0.1	0.10	2.7	0.2	0.07	7	0.9
L6200W 14325N	Soil	0.035	7	28	0.43	98	0.126	2	1.76	0.011	0.06	0.2	0.06	3.0	0.2	<0.05	9	<0.5
L6200W 14350N	Soil	0.059	12	35	0.63	227	0.106	2	2.58	0.018	0.10	0.2	0.06	4.8	0.2	<0.05	8	<0.5
L6200W 14375N	Soil	0.121	7	25	0.36	90	0.051	2	1.91	0.021	0.06	<0.1	0.13	1.7	0.2	0.13	7	0.8
L6200W 14400N	Soil	0.054	11	32	0.60	155	0.101	2	2.26	0.014	0.08	0.2	0.04	3.9	0.2	<0.05	8	<0.5
L6200W 14425N	Soil	0.089	5	20	0.19	62	0.057	2	1.45	0.022	0.04	0.2	0.12	1.9	0.1	0.14	5	0.9
L6200W 14450N	Soil	0.091	12	27	0.58	167	0.133	1	1.83	0.023	0.11	0.3	0.05	3.0	0.2	<0.05	5	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

		Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L6200W 14475N	Soil			1.7	21.9	33.6	87	0.2	18.2	10.6	561	2.73	28.5	3.3	3.6	6.1	21	0.4	1.5	0.3	75	0.30
L6200W 14500N	Soil			2.1	35.3	39.7	92	0.4	22.2	12.1	572	3.03	42.4	5.0	4.1	4.9	28	0.6	1.8	0.4	78	0.32
L6800W 12100N	Soil			1.3	40.8	12.3	51	0.1	19.3	17.0	436	3.38	17.4	5.1	30.5	9.9	31	0.2	2.1	0.9	56	0.31
L6800W 12125N	Soil			1.5	62.6	11.0	60	0.1	27.1	59.6	1960	6.60	28.6	16.5	34.8	8.1	28	0.2	2.0	0.9	52	0.23
L6800W 12150N	Soil			1.5	52.9	12.2	51	<0.1	23.7	31.2	431	3.91	18.5	7.6	27.0	12.3	31	0.2	2.3	0.9	56	0.29
L6800W 12175N	Soil			0.9	49.7	10.6	46	0.1	21.4	26.9	847	3.94	15.0	7.8	49.0	9.1	32	0.1	1.2	0.9	60	0.30
L6800W 12200N	Soil			1.0	50.2	15.8	44	0.2	17.5	6.8	157	3.02	14.8	8.8	82.4	9.0	23	0.1	1.6	1.6	53	0.21
L6800W 12225N	Soil			0.9	35.2	12.4	47	0.1	16.4	8.3	298	3.38	13.8	3.8	86.2	8.4	24	0.1	1.3	1.1	58	0.26
L6800W 12250N	Soil			4.8	54.4	14.4	50	0.3	20.4	25.8	2582	8.18	39.1	15.8	20.3	10.0	42	0.2	2.1	0.6	35	0.36
L6800W 12275N	Soil			2.2	33.8	18.0	39	0.3	15.7	24.2	1305	5.16	26.0	6.8	54.4	13.3	30	<0.1	3.8	0.6	39	0.27
L6800W 12300N	Soil			1.1	27.0	10.4	41	0.2	15.2	5.4	146	2.56	10.5	3.9	18.4	3.9	23	0.1	0.9	0.6	49	0.23
L6800W 12325N	Soil			0.9	31.0	9.6	47	<0.1	18.3	7.4	233	2.70	13.0	2.4	13.4	8.1	25	0.2	1.1	0.6	54	0.27
L6800W 12350N	Soil			1.2	35.1	14.2	48	0.2	16.3	6.7	195	2.82	17.0	4.1	28.0	6.2	24	0.1	1.4	0.9	56	0.21
L6800W 12375N	Soil			1.1	38.0	12.0	47	0.1	17.3	6.6	180	2.61	13.5	4.0	37.1	8.2	21	0.1	1.7	0.8	54	0.20
L6800W 12400N	Soil			0.9	35.1	11.7	43	<0.1	16.1	6.1	217	2.46	10.8	4.2	56.9	15.3	31	0.2	1.9	0.6	51	0.30
L6800W 12425N	Soil			0.6	30.2	11.5	40	<0.1	15.7	5.9	210	2.39	8.9	2.3	30.6	11.4	29	0.2	1.6	0.4	52	0.32
L6800W 12450N	Soil			0.7	42.5	18.5	24	<0.1	6.3	2.6	75	2.34	12.4	3.7	49.2	14.4	54	<0.1	2.3	0.7	22	0.12
L6800W 12475N	Soil			1.3	69.7	42.2	37	0.2	10.7	5.1	148	3.05	16.3	5.5	61.8	14.1	51	0.2	5.4	0.7	39	0.17
L6800W 12500N	Soil			1.3	55.5	29.8	41	0.4	12.3	4.6	125	3.46	23.3	7.7	52.2	14.2	31	0.1	4.8	0.9	40	0.15
L6800W 12525N	Soil			1.2	50.2	18.8	59	0.1	19.9	8.8	295	3.55	14.5	4.3	29.9	13.5	24	0.2	1.9	0.6	53	0.17
L6800W 12550N	Soil			1.2	50.1	44.0	53	0.1	13.6	8.1	399	2.90	18.2	3.0	30.0	14.7	20	0.2	4.0	1.1	36	0.12
L6800W 12575N	Soil			1.2	58.1	23.5	56	0.2	13.0	6.1	302	3.06	18.2	4.8	30.9	8.0	26	0.4	2.8	1.2	41	0.15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

CERTIFICATE OF ANALYSIS SMI09000287.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
		Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
		MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L6200W 14475N	Soil		0.102	13	30	0.53	185	0.119	2	1.79	0.024	0.13	0.6	0.05	3.3	0.2	0.06	6	0.5
L6200W 14500N	Soil		0.096	17	30	0.60	251	0.118	2	2.25	0.027	0.09	0.3	0.11	4.3	0.3	0.07	7	0.5
L6800W 12100N	Soil		0.081	22	32	0.51	197	0.097	<1	1.89	0.017	0.08	0.3	0.03	5.2	0.2	<0.05	5	0.8
L6800W 12125N	Soil		0.094	28	31	0.46	200	0.074	1	2.18	0.013	0.06	0.4	0.07	5.5	0.4	<0.05	6	0.9
L6800W 12150N	Soil		0.076	22	30	0.50	169	0.110	<1	1.71	0.023	0.10	0.3	0.03	5.5	0.2	<0.05	5	0.8
L6800W 12175N	Soil		0.070	23	36	0.49	166	0.110	1	1.89	0.014	0.07	0.6	0.04	5.5	0.2	<0.05	5	0.6
L6800W 12200N	Soil		0.071	20	31	0.49	122	0.085	1	2.12	0.013	0.08	0.4	0.09	3.7	0.2	<0.05	6	0.9
L6800W 12225N	Soil		0.079	17	30	0.49	133	0.098	1	1.84	0.014	0.08	0.4	0.05	3.4	0.2	<0.05	5	0.5
L6800W 12250N	Soil		0.113	33	24	0.29	250	0.034	1	1.85	0.012	0.05	0.3	0.18	5.3	0.3	0.05	5	1.3
L6800W 12275N	Soil		0.072	27	24	0.37	158	0.066	<1	1.57	0.011	0.08	0.7	0.07	3.6	0.3	<0.05	5	0.7
L6800W 12300N	Soil		0.061	17	28	0.43	112	0.072	1	1.64	0.013	0.06	0.3	0.05	3.1	0.1	<0.05	6	0.6
L6800W 12325N	Soil		0.076	18	31	0.52	119	0.106	<1	1.82	0.017	0.08	0.4	0.03	3.6	0.2	<0.05	6	0.7
L6800W 12350N	Soil		0.068	21	30	0.51	119	0.076	1	2.02	0.014	0.08	0.3	0.04	3.7	0.2	<0.05	7	0.6
L6800W 12375N	Soil		0.063	21	30	0.49	114	0.083	1	1.88	0.013	0.07	0.4	0.04	3.5	0.2	<0.05	6	<0.5
L6800W 12400N	Soil		0.059	25	28	0.47	161	0.112	<1	1.48	0.025	0.10	0.3	0.02	4.2	0.1	<0.05	4	<0.5
L6800W 12425N	Soil		0.073	21	26	0.44	111	0.115	<1	1.20	0.026	0.10	0.3	0.02	3.1	0.1	<0.05	4	0.7
L6800W 12450N	Soil		0.043	23	10	0.31	177	0.015	<1	1.78	0.029	0.09	0.4	0.02	2.1	0.1	0.11	5	1.0
L6800W 12475N	Soil		0.068	30	18	0.43	209	0.044	<1	1.74	0.047	0.17	1.1	0.02	2.9	0.2	0.21	5	0.7
L6800W 12500N	Soil		0.074	39	22	0.42	216	0.033	<1	2.03	0.017	0.10	0.4	0.07	3.2	0.2	0.11	6	1.2
L6800W 12525N	Soil		0.068	24	25	0.53	167	0.059	<1	2.28	0.026	0.11	0.3	0.02	3.1	0.1	0.12	7	0.6
L6800W 12550N	Soil		0.056	22	19	0.36	134	0.036	<1	1.43	0.024	0.14	0.5	0.02	1.9	0.1	0.12	6	<0.5
L6800W 12575N	Soil		0.061	30	21	0.36	233	0.029	<1	1.87	0.028	0.12	0.3	0.04	2.1	0.1	0.17	7	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

QUALITY CONTROL REPORT SMI09000287.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
L6000W 13075N	Soil		1.1	33.3	81.4	67	1.7	11.1	5.1	150	3.77	80.6	2.3	185.1	8.6	20	0.3	4.2	2.4	51	0.21
REP L6000W 13075N	QC		1.1	34.5	82.5	72	1.6	11.2	5.3	157	3.83	82.2	2.5	51.7	8.9	20	0.3	4.2	2.5	51	0.20
L6000W 13425N	Soil		0.8	32.1	101.7	87	1.8	13.3	10.7	654	2.89	142.3	1.9	75.7	10.3	16	0.3	8.4	5.3	47	0.19
REP L6000W 13425N	QC		0.9	33.6	100.5	88	1.8	11.7	10.4	644	2.80	135.3	1.9	52.9	10.0	18	0.3	8.4	5.2	45	0.20
L6000W 14150N	Soil		1.7	21.5	37.0	183	0.3	20.4	12.1	713	3.15	251.7	2.3	13.8	3.5	38	0.5	5.8	0.9	70	0.53
REP L6000W 14150N	QC		1.4	21.4	35.5	180	0.3	20.5	11.0	684	2.92	245.6	2.3	12.9	3.4	36	0.6	5.8	0.9	66	0.50
L6200W 13050N	Soil		1.0	57.5	28.5	82	0.3	23.5	10.5	360	3.11	29.0	5.5	27.1	7.5	20	0.4	1.8	1.8	67	0.25
REP L6200W 13050N	QC		1.0	63.7	29.7	84	0.4	27.2	11.0	385	3.42	29.9	5.7	183.1	8.1	21	0.5	1.8	2.0	73	0.25
L6200W 13225N	Soil		1.4	32.9	15.1	62	0.2	23.5	11.6	446	3.11	35.9	2.4	71.6	7.8	17	0.2	1.1	1.6	67	0.22
REP L6200W 13225N	QC		1.2	32.5	15.8	63	0.2	24.4	12.4	472	3.37	36.4	2.4	58.8	7.9	17	0.3	1.1	1.5	70	0.23
L6200W 13725N	Soil		1.3	20.9	26.0	117	0.2	19.5	13.2	1066	3.01	157.6	3.9	20.4	7.5	25	0.5	2.1	1.4	65	0.44
REP L6200W 13725N	QC		1.3	19.3	25.2	111	0.2	19.0	13.6	1058	3.02	162.1	3.8	21.1	7.8	26	0.5	2.0	1.3	66	0.41
L6200W 14175N	Soil		0.9	25.0	62.0	198	0.3	18.1	9.9	581	2.45	98.7	3.6	7.3	7.5	31	1.3	3.1	0.4	61	0.39
REP L6200W 14175N	QC		1.0	26.2	62.9	208	0.3	18.9	10.2	618	2.61	99.6	3.5	17.3	7.5	33	1.4	3.4	0.5	64	0.42
L6800W 12325N	Soil		0.9	31.0	9.6	47	<0.1	18.3	7.4	233	2.70	13.0	2.4	13.4	8.1	25	0.2	1.1	0.6	54	0.27
REP L6800W 12325N	QC		1.0	30.7	9.9	47	<0.1	18.2	7.3	233	2.66	12.9	2.4	18.7	8.3	24	0.2	1.1	0.6	54	0.27
L6800W 12500N	Soil		1.3	55.5	29.8	41	0.4	12.3	4.6	125	3.46	23.3	7.7	52.2	14.2	31	0.1	4.8	0.9	40	0.15
REP L6800W 12500N	QC		1.5	59.7	30.3	44	0.4	13.4	5.0	123	3.63	24.7	7.9	50.3	14.0	30	0.1	5.0	0.9	40	0.16
Reference Materials																					
STD DS7	Standard		20.3	121.0	79.0	385	0.9	55.8	9.6	611	2.42	53.4	5.5	63.7	4.9	73	7.2	6.5	5.2	82	0.91
STD DS7	Standard		20.0	112.7	65.8	384	0.8	58.0	9.7	630	2.47	51.4	4.2	63.1	4.0	72	6.1	5.2	4.3	85	0.94
STD DS7	Standard		20.3	114.3	62.9	418	0.8	58.7	9.6	641	2.51	52.2	3.9	71.3	3.7	70	6.2	5.4	4.2	89	1.00
STD DS7	Standard		20.8	107.6	73.6	394	0.8	55.4	9.2	605	2.47	52.4	4.6	63.5	4.5	69	6.2	5.1	4.2	84	0.96
STD DS7	Standard		20.6	106.2	70.9	375	0.8	56.0	9.2	626	2.43	49.5	4.8	61.5	4.5	69	6.0	5.4	4.1	84	0.99
STD DS7 Expected			20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

QUALITY CONTROL REPORT SMI09000287.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Pulp Duplicates																		
L6000W 13075N	Soil	0.059	22	25	0.46	101	0.068	1	1.57	0.010	0.10	0.7	0.07	3.6	0.3	0.07	6	<0.5
REP L6000W 13075N	QC	0.059	22	25	0.44	106	0.067	<1	1.51	0.009	0.10	0.6	0.06	3.6	0.3	0.05	6	<0.5
L6000W 13425N	Soil	0.065	21	24	0.48	94	0.071	<1	1.67	0.010	0.10	0.4	0.03	3.0	0.3	<0.05	6	<0.5
REP L6000W 13425N	QC	0.060	21	24	0.46	97	0.075	<1	1.68	0.009	0.10	0.4	0.02	3.0	0.3	<0.05	6	<0.5
L6000W 14150N	Soil	0.053	15	33	0.48	292	0.054	2	2.00	0.020	0.08	0.3	0.04	3.4	0.2	<0.05	7	<0.5
REP L6000W 14150N	QC	0.055	15	31	0.46	286	0.052	1	1.96	0.019	0.07	0.3	0.05	3.3	0.1	<0.05	6	<0.5
L6200W 13050N	Soil	0.064	23	36	0.58	133	0.091	1	2.35	0.016	0.08	0.2	0.07	4.2	0.1	0.05	7	0.5
REP L6200W 13050N	QC	0.067	25	38	0.61	143	0.094	2	2.29	0.017	0.09	0.3	0.06	4.2	0.2	<0.05	6	0.7
L6200W 13225N	Soil	0.060	13	34	0.56	104	0.092	1	2.25	0.017	0.06	1.5	0.04	3.3	0.2	<0.05	7	0.7
REP L6200W 13225N	QC	0.055	14	36	0.53	104	0.101	2	2.18	0.013	0.06	1.3	0.03	3.5	0.1	<0.05	7	0.6
L6200W 13725N	Soil	0.084	21	33	0.59	224	0.097	2	2.05	0.018	0.09	0.4	0.04	4.8	0.2	0.05	6	0.7
REP L6200W 13725N	QC	0.083	20	31	0.57	230	0.095	1	1.87	0.016	0.09	0.6	0.03	4.6	0.2	0.05	6	<0.5
L6200W 14175N	Soil	0.078	18	27	0.55	232	0.105	1	1.61	0.023	0.09	0.3	0.02	4.6	0.2	<0.05	5	<0.5
REP L6200W 14175N	QC	0.079	18	29	0.57	233	0.117	2	1.67	0.027	0.10	0.3	0.03	4.9	0.2	<0.05	5	<0.5
L6800W 12325N	Soil	0.076	18	31	0.52	119	0.106	<1	1.82	0.017	0.08	0.4	0.03	3.6	0.2	<0.05	6	0.7
REP L6800W 12325N	QC	0.075	18	30	0.51	117	0.104	2	1.88	0.017	0.07	0.5	0.03	3.6	0.1	<0.05	5	0.6
L6800W 12500N	Soil	0.074	39	22	0.42	216	0.033	<1	2.03	0.017	0.10	0.4	0.07	3.2	0.2	0.11	6	1.2
REP L6800W 12500N	QC	0.074	40	22	0.44	215	0.033	<1	2.00	0.018	0.11	0.5	0.08	3.1	0.3	0.09	7	1.0
Reference Materials																		
STD DS7	Standard	0.084	14	187	1.07	389	0.131	41	1.07	0.108	0.42	3.5	0.20	2.9	4.1	0.17	5	3.3
STD DS7	Standard	0.073	13	217	0.99	401	0.119	39	0.96	0.094	0.47	3.5	0.20	2.5	4.3	0.20	5	3.6
STD DS7	Standard	0.073	12	231	1.03	398	0.121	39	1.01	0.099	0.50	3.8	0.20	2.5	4.1	0.17	5	3.9
STD DS7	Standard	0.074	13	209	1.06	414	0.115	39	1.05	0.102	0.45	3.9	0.21	2.3	4.6	0.20	5	4.0
STD DS7	Standard	0.074	12	221	1.02	409	0.122	38	1.01	0.102	0.47	4.0	0.20	2.4	4.5	0.24	5	4.0
STD DS7 Expected		0.08	12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

QUALITY CONTROL REPORT SMI09000287.1

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 09, 2009

QUALITY CONTROL REPORT SMI09000287.1

		1DX15 P % 0.001	1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Submitted By: Glen Garratt
Receiving Lab: Canada-Smithers
Received: October 02, 2009
Report Date: October 14, 2009
Page: 1 of 2

CERTIFICATE OF ANALYSIS SMI09000312.1

CLIENT JOB INFORMATION

Project: Canadian Creek
Shipment ID: CC09-22
P.O. Number
Number of Samples: 9

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	9	Dry at 60C sieve 100g to -80 mesh			SMI
Dry at 60C	9	Dry at 60C			SMI
1DX15	9	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Mincord Exploration Consultants Ltd.
110 - 325 Howe St.
Vancouver BC V6C 1Z7
Canada

CC: Bob Johnston

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 14, 2009

CERTIFICATE OF ANALYSIS SMI09000312.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01
L7800 12275	Soil		2.7	39.8	10.0	44	0.1	15.2	6.7	250	2.65	21.2	4.7	77.0	5.5	14	0.1	0.9	1.2	47	0.13
L7800 12300	Soil		1.2	54.0	7.6	23	<0.1	11.0	5.8	118	2.20	30.7	2.7	57.5	9.3	24	<0.1	1.9	0.8	27	0.16
L7800 12325	Soil		1.8	45.6	9.1	52	0.2	28.2	11.0	396	3.29	57.1	1.3	28.0	4.6	17	<0.1	1.0	1.4	74	0.15
L7800 12350	Soil		1.1	31.7	7.2	55	<0.1	30.4	12.4	412	2.89	28.3	0.7	3.7	2.5	16	0.2	0.6	0.4	64	0.19
L7800 12375	Soil		1.4	47.5	10.7	43	0.2	20.7	14.2	310	4.18	106.3	1.9	86.9	6.9	148	0.1	1.2	4.9	60	0.39
L7800 12400	Soil		1.5	69.9	5.8	44	0.1	32.4	13.6	306	3.67	59.7	0.9	26.3	5.3	22	<0.1	1.2	1.3	81	0.19
L7800 12425	Soil		1.8	44.5	10.1	66	<0.1	28.0	12.7	473	3.92	42.1	0.7	6.2	2.2	12	0.1	1.3	0.6	87	0.11
L7800 12450	Soil		2.4	65.6	8.5	58	<0.1	20.6	13.2	394	3.44	53.9	1.6	42.7	4.3	26	0.1	1.3	3.5	67	0.25
L7800 12475	Soil		10.9	84.7	14.9	54	0.2	14.2	13.5	370	3.83	162.0	3.2	96.1	7.3	23	0.2	2.0	10.0	45	0.26

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 14, 2009

CERTIFICATE OF ANALYSIS SMI09000312.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
L7800 12275	Soil	0.054	16	21	0.40	84	0.036	1	1.78	0.016	0.05	0.2	0.04	2.1	<0.1	0.05	6	0.7
L7800 12300	Soil	0.042	9	11	0.35	319	0.023	<1	2.46	0.025	0.10	0.1	0.01	2.6	0.2	0.05	5	<0.5
L7800 12325	Soil	0.041	13	37	0.66	145	0.093	<1	2.31	0.017	0.09	0.3	0.03	3.7	0.1	<0.05	5	1.3
L7800 12350	Soil	0.041	9	33	0.61	125	0.088	<1	1.94	0.015	0.08	0.2	0.03	3.2	0.1	<0.05	5	<0.5
L7800 12375	Soil	0.072	13	36	0.75	464	0.099	<1	2.54	0.043	0.23	0.5	0.02	3.6	0.3	<0.05	6	0.9
L7800 12400	Soil	0.059	13	49	0.67	136	0.106	<1	1.85	0.026	0.17	0.4	0.01	3.4	0.3	0.09	5	1.1
L7800 12425	Soil	0.042	10	45	0.64	112	0.084	<1	2.15	0.010	0.09	0.2	0.05	3.0	0.2	<0.05	7	1.0
L7800 12450	Soil	0.063	11	32	0.69	183	0.105	<1	2.40	0.021	0.15	23.7	0.02	3.6	0.3	<0.05	6	0.7
L7800 12475	Soil	0.069	17	22	0.64	157	0.046	<1	1.92	0.015	0.10	1.0	0.01	2.8	0.2	<0.05	5	0.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 14, 2009

QUALITY CONTROL REPORT SMI09000312.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Reference Materials																					
STD DS7	Standard	20.3	117.1	66.6	402	0.8	56.2	10.3	640	2.45	51.4	5.0	71.5	4.4	74	5.9	5.4	4.6	87	0.94	0.078
STD DS7	Standard	18.9	106.5	57.2	393	0.9	54.7	9.4	618	2.33	50.1	4.4	58.7	4.0	71	5.9	5.1	4.2	82	0.90	0.073
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Mincord Exploration Consultants Ltd.**
110 - 325 Howe St.
Vancouver BC V6C 1Z7 Canada

Project: Canadian Creek
Report Date: October 14, 2009

QUALITY CONTROL REPORT SMI09000312.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5
Reference Materials																	
STD DS7	Standard	13	221	1.04	407	0.126	37	1.07	0.115	0.46	3.7	0.22	2.7	4.2	0.17	5	3.7
STD DS7	Standard	13	208	0.96	401	0.122	38	1.03	0.112	0.45	3.6	0.18	2.7	3.8	0.22	5	3.7
STD DS7 Expected		12	179	1.05	370	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

APPENDIX 5

2009 Inverted Chargeability Plan Maps

Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV inverted data

Grid coordinates: WGS84 UTM



Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted chargeability data
15 m depth plan

Drawn By: B Scott Date: August 2009
Scott Geophysics Ltd.

Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV inverted data

Grid coordinates: WGS84 UTM



Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted chargeability data
30 m depth plan

Drawn By: B Scott
Date: August 2009
Scott Geophysics Ltd.

Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV inverted data

Grid coordinates: WGS84 UTM



Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted chargeability data
50 m depth plan

Drawn By: B Scott
Date: August 2009
Scott Geophysics Ltd.

Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV inverted data

Grid coordinates: WGS84 UTM



Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted chargeability data
90 m depth plan

Drawn By: B Scott Date: August 2009
Scott Geophysics Ltd.

APPENDIX 6

2009 Inverted Resistivity Plan Maps

Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV inverted data

Grid coordinates: WGS84 UTM



Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted resistivity data
15 m depth plan

Drawn By: B Scott
Date: August 2009

Scott Geophysics Ltd.

Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV inverted data

Grid coordinates: WGS84 UTM



Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted resistivity data
30 m depth plan

Drawn By: B Scott
Date: August 2009
Scott Geophysics Ltd.

Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV inverted data

Grid coordinates: WGS84 UTM



Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted resistivity data
50 m depth plan

Drawn By: B Scott Date: August 2009

Scott Geophysics Ltd.

Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV inverted data

Grid coordinates: WGS84 UTM




Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted resistivity data
90 m depth plan


Drawn By: B Scott
Date: August 2009


Scott Geophysics Ltd.


APPENDIX 7


2009 Inverted Chargeability Sections

















Survey Specifications

Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV true depth inverted sections

N


Chargeability (mV/V)

60
50
40
35
30
25
20
17.5
15
12.5
10
7.5
5
2.5
0

Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted chargeability model sections
Lines 6200W-7400W
Drawn By: B Scott Date: August 2009
Scott Geophysics Ltd.

METRES
0 50 100 150 200 250

8800W



Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec


Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV true depth inverted sections


8600W




8400W




8200W




Chargeability (mV/V)




8000W



7800W



7600W



Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted Chargeability model sections
Lines 7600W-8800W


Drawn By: B Scott — Date: August 2009

Scott Geophysics Ltd.


METRES

0 50 100 150 200 250


10200W




10000W




9800W




9600W




9400W



9200W



9000W



Survey Specifications

Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV true depth inverted sections

Chargeability (mV/V)

60
50
40
35
30
25
20
17.5
15
12.5
10
7.5
5
2.5
0

METRES

0 50 100 150 200 250


Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted chargeability model sections
Lines 9000W-10200W


Drawn By: B Scott Date: August 2009


Scott Geophysics Ltd.


APPENDIX 8


2009 Inverted Resistivity Sections

















Survey Specifications

Survey performed: August 2009


Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV true depth inverted sections



Resistivity (Ωm)



Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted resistivity model sections
Lines 6200W-7400W


Drawn By: B Scott | Date: August 2009

Scott Geophysics Ltd.

METRES

0 50 100 150 200 250

8800W



Survey Specifications


Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec


Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV true depth inverted sections


8600W




8400W




8200W




8000W



7800W



7600W



Resistivity (Ωm)

30000
20000
15000
10000
7000
5000
3000
2000
1500
1000
700
500
300
200
150
100
70
50

Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted resistivity model sections
Lines 7600W-8800W


Drawn By: B Scott — Date: August 2009

Scott Geophysics Ltd.


METRES

0 50 100 150 200 250


10200W




10000W




9800W



9600W




9400W




Resistivity (Ωm)

30000
20000
15000
10000
7000
5000
3000
2000
1500
1000
700
500
300
200
150
100
70
50

9200W



9000W



Survey Specifications

Survey performed: August 2009

Receiver: GDD GRx8
Transmitter: GDD TxII
Pulse time: 2 sec
Mx receive window: 690-1050 msec

Array: pole-dipole
a spacing, n separations: a = 25m, n = 1-3 + a = 50m, n = 2-4
Current electrode south of potential electrodes

RES2DINV true depth inverted sections

N

METRES

0 50 100 150 200 250

Mincord Exploration Consultants Ltd.
Canadian Creek Property
Casino area, Yukon
Induced Polarization Survey
RES2DINV inverted resistivity model sections
Lines 9000W-10200W

Drawn By: B Scott Date: August 2009

Scott Geophysics Ltd.