Assessment Report on the 2010 Geological and Geochemical Programs On the 3ACE Property, Southeast Yukon Northern Tiger Resources Inc.

Volume 1: Report, Appendices 1, 2

YC72439 – YC72448 (KING 1-10), YC72452 – YC72459 (KING 11-18), YC89511 – YC89520 (KING 19-28), YC72724 – YC72733 (KING 29-38), YC73284 – YC73295 (KING 39-50), YC73848 – YC73859 (KING 51-62), YC89521 – YC89530 (KING 63-72), YD07129 – YD07138 (KING 73-82), YD10860 – YD10869 (KING 83-92), YD10900 – YD10919 (KING 93-112), YD 07109 – YD07128 (ACE 1-20), YD59328 – YD59459 (ACE 21-152), YD29165 – YD29172 (JACK 5-12), YD29183 – YD29199 (JACK 23-39), YD10920 – YD10924 (JAN 1-4)

Little Hyland River area, southeast Yukon

NTS Sheets 105H09, 105H16
61°43'37"N Lat, 128°21'46"W Long
UTM (NAD 83): 533700E, 6843800N, Zone 9
Watson Lake Mining District

Effective Date: Nov 26, 2010

For: Northern Tiger Resources Inc.
Suite 220 – 17010 103rd Ave.
Edmonton, Alberta T5S 1K7
Phone (780) 428-3465 Fax (780) 428-3476
Email: douellette@northern-tiger.com

By: Carl M. Schulze, BSc, PGeo
All-Terrane Mineral Exploration Services
35 Dawson Rd
Whitehorse, Yukon Y1A 5T6
Tel: 867-633-4807
Fax: 867-633-4883
allterrane@northwestel.net

Chris Buchanan
Buchanan Geoscience Services
10 Prospero Place
St. John's, NL
A1B 3W7
709-754-3115
crbuchanan@mun.ca

Summary

In April 2010 Northern Tiger Resources Inc (NTR-TSX-V) acquired an option to attain a 100% interest from Mr. Alex McMillan in the 2,772-hectare 3Ace property in south-eastern Yukon, Canada. At the time, two significant mineralized occurrences were known: the Main Zone", hosting spectacular visible gold at the "Discovery Outcrop", and the "North Zone" which also hosts locally abundant visible gold. The property was expanded to a total of 293 claims covering 6,153 hectares prior to mid-July, 2010.

The property is located within Neoproterozoic Hyland Group, Yusezyu Formation stratigraphy forming the base of the Selwyn Basin, a succession of shelf and off-shelf clastic and lesser chemical sedimentary and volcanic rock deposited along the margin of the Ancient North American Platform. The Yusezyu Formation consists primarily of two major lithological settings: a coarse clastic package of quartz-pebble conglomerate through sandstone, typically arkosic and sub-arkosic; and a fine grained set of black shales, siltstone and fine grained phyllite. Lesser limestone and calcareous clastic sediments also occur within this formation. The majority of mineralized horizons identified to date occur within the coarse clastic package.

Sampling of the Discovery Outcrop in mid-June 2010 returned values from 83.58 g/t (2.441 oz/ton) to 4,259.31 g/t (129.396 oz/ton) gold. In early July, Northern Tiger embarked on a surface exploration program consisting of geological mapping, silt sampling and systematic soil sampling across much of the property. This led to identification of two major "new" zones: the Sleeping Giant Zone about 1.2 kilometres east of the Main Zone, and the Green Zone/ Green Mile prospects roughly 2.0 kilometres north of the Main Zone. The Sleeping Giant Zone consists of a north-south trending corridor of lenticular auriferous quartz units. The Green Zone/ Green Mile horizon consists of auriferous and arsenical mineralization along a previously emplaced east-west striking, south-dipping thrust fault. The program also focused on detailed geological and geochemical exploration of the Main Zone, resulting in northward extension of its known strike length of about 50 metres.

Chip sampling at the Main Zone returned extremely high gold values ranging from 64.585 g/t Au (1.88 oz/ton) across 1.0m to 795.917 g/t Au (23.25 oz/ton) across 1.1m, including high values from the northern extension discovered in 2010. Chip sampling on the Sleeping Giant Zone returned numerous high grade gold values to 11.34 g/t Au across 6.0m. This led to a diamond drilling program targeting both zones in the fall of 2010.

Surface exploration at the Green Zone revealed a 450-metre east-west trending horizon of auriferous altered coarse clastic sediments directly south of the interpreted trace of the thrust fault. A single 1999 drill hole collared about 200 metres to the north returned a 1.5-metre intercept grading 4.5 g/t Au from fine clastic sediments. The zone was not drilled tested in 2010 but remains a viable target.

Recommendations for 2011 consist of a Phase 1 program of detailed surface soil geochemical surveying across the Main and Sleeping Giant zones as well as chip sampling across the Sleeping Giant Zone. Induced Polarization surveying, particularly resistivity surveying is recommended

for all three zones. Results are to be compiled and analyzed, leading to identification of drill targets for a Phase 2 program later in the season focusing on all three zones. This phase is recommended to consist of 2,500 metres of NTW-sized diamond drilling in 15-20 holes targeting the Main Zone; a further 1,500 metres in 10-12 holes targeting the Sleeping Giant Zone, including its southward strike extension; and up to 2,000 metres in 12-15 holes targeting the Green Zone.

Reconnaissance-style geological mapping and stream silt sampling is also recommended to cover the expanded claim block. Further detailed surface work is recommended to "ground-truth" soil geochemical anomalies identified in 2010, and to determine viability of the auriferous "Hoito" quartz vein zone southwest of the Green Zone. Projected Phase 1 expenditures stand at CDN$284,140; with 15% contingency this figure stands at $326,761. Phase 2 expenditures stand at $2,383,913; with 15% contingency this figure stands at $2,759,391.

Table of Contents

	Page
Summary	2
1.0 Introduction	6
1.1 Introductory Statement	6
1.2 Terms of Reference	6
1.3 Sources of Information	6
1.4 Field Involvement of Qualified Person	7
2.0 Property Description and Location	7
2.1 Property Description	7
2.2 Option Agreements	7
3.0 Physiography, Climate, Access and Infrastructure	8
3.1 Physiography and Climate	8
3.2 Access, Infrastructure and Local Resources	9
4.0 History	14
5.0 Geology	16
5.1 General Geology	16
5.2 Property Geology	14
5.3 Structural Geology	17
6.0 Deposit Types	19
7.0 Mineralization	20
7.1 Main Zone	20
7.2 Sleeping Giant Zone	21
7.3: Green Zone	21
7.4 North Zone	22
8.0 2010 Work Program	23
8.1. Description of Surface Exploration Program	23
8.2 Main Zone	23
8.2.1 Bedrock Geochemical Results, Main Zone	23
8.2.2: Geochemical Results, Main Zone	24
8.3 Sleeping Giant Zone	25
8.4 Green Zone	25
8.4.1 Bedrock Geochemical Results, Green Zone	25
8.4.2 Surface Geochemical Results, Green Zone	26
8.5 North Zone	27
8.6 Other Discussion	27
8.7 Personnel	27
9.0 Sampling Method and Approach	28
10.0 Sample Preparation, Analysis and Security	29
11.0 Data Verification	30
12.0 Adjacent Properties	31
13.0 Mineral Processing and Metallogenic Testing	32
14.0 Mineral Resource and Mineral Reserve Estimates	32
15.0 Other Relevant Data and Information	32
16.0 Discussion and Conclusion	33
16.1 Discussion	33
16.1.1 Main Zone	34
16.1.2 Sleeping Giant Zone	35
16.1.3 Green Zone	35
16.1.4 North Zone	36
16.1.5 Other Discussion	37
16.2 Conclusions	37
17.0 Recommendations	40
17.1 Recommendations	40

Table of Contents (cont'd)

	Page
17.2 Recommended Budget: Phase 1	41
17.3 Recommended Budget: Phase 2	42
18.0 References	43
18.1 References, C. Schulze, All-Terrane Services	43
18.2 References, Buchanan Geoscience Services	45

Tables

Table 1: Claim Status	12

List of Figures

Figure 1: Location Map	10
Figure 2: Regional Location Map	11
Figure 3: Claim Map (also in pocket)	13

Appendices

Appendix 1a: Certificate of Author(s)	46
Appendix 1b: Statement of Expenditures	48
Appendix 2: Sample Descriptions	49
Appendix 2a: Rock Sample Descriptions	50
Appendix 2b: Soil Sample Descriptions	
Appendix 2c: Silt Sample Descriptions	
Appendix 3: Original Results	Volume 2

Maps

Map 1a: Geology, South Half, 3Ace Property	In pocket
Map 1b: Geology, North Half, 3Ace Property	In pocket
Map 2: Au Geochemical Map, 3Ace Property	In pocket
Map 3: Au Geochemistry, 3Ace Property – Main Zone	In pocket
Map 3: Au Geochemistry, 3Ace Property – Green Zone	In pocket
Map 3: Au Geochemistry, 3Ace Property- Sleeping Giant Zone	In pocket

1.0 Introduction

1.1 Introductory Statement

In April 2010, Northern Tiger Resources Inc (NTR, TSX-V) finalized its agreement to acquire a 100% interest in the 2,772-hectare 3Ace property from Mr. Alex McMillan of Watson Lake, Yukon. The original claim block consisted of 112 Yukon quartz mining claims; Northern Tiger subsequently added a further 156 claims prior to June, 2010, and a further 25 in early July, 2010 at the onset of a surface exploration program of detailed geological mapping, systematic soil sampling, silt sampling and prospecting. This program consisted of detailed geochemical sampling and geological mapping on the Main Zone, focusing on a high grade lode gold occurrence called the "Discovery Outcrop", discovered by Mr. McMillan. The summer program led to identification of the "Green" and "Sleeping Giant" zones, the latter returning high grade gold values from chip sampling.

This assessment report covers results of a June property visit and the July to August 2010 surface exploration program.

1.2 Terms of Reference

The author has been requested to write this report for Northern Tiger Resources Inc. using these terms of reference:

a) To review and compile the available information and data, including geological, structural and geochemical data obtained by Northern Tiger Resources Inc. prior to property acquisition and pertaining to the 3Ace property and associated interpreted gold potential.

b) To comply with the TSX Venture Exchange regulatory requirements.

c) To follow the guidelines and framework defined in the Form 43-101-F1, pertaining to National Instrument 43-101: "Standards of Disclosure for Mineral Projects".

d) To support the technical disclosure by Northern Tiger Resources in its Annual Information Form.

e) To satisfy assessment requirements of the Watson Lake Mining Recorder, Ministry of Energy, Mines and Resources, Government of Yukon.

1.3 Sources of Information

Much of the historical information in this report was provided by several assessment reports submitted in 1998 and 1999 by M. D. Buchanan of Hudson Bay Exploration and Development Co. Ltd, and by in-house data from that period now available to Northern Tiger Resources. Specific reports used are: Assessment Report #094112, Diamond Drilling, Hit property;

Assessment Report #093975, Geochemical Survey, 3Ace property; Assessment Report #093975, Geochemical Survey, Hit Property; and Assessment Report #094114, Geochemical Survey, Hat property. This report also incorporates findings from a 2005 paper entitled "Gold Mineralization in the upper Hyland River area: A non-magmatic origin" by C. Hart and L. Lewis of the Yukon Geology Survey, published in the annual "Yukon Exploration and Geology 2005" overview by the Government of Yukon.

Chris Buchanan, MSc (no relation), of Buchanan Geoscience Services, provided the majority of the structural data in this report, and was responsible for detailed mapping across the Main and Sleeping Giant zones.

1.4 Involvement of Qualified Person

Mr. Carl Schulze, BSc, PGeo, Qualified Person for the 3Ace project, was on site for the entire field program from July 3 to Aug 20, 2010. Mr. Schulze also managed all compilation of data from the surface program.

2.0 Property Description and Location

2.1 Property Description

As of mid-July, 2010, the 3Ace property consisted of 284 quartz mining claims covering roughly 5,964 hectares, within the Watson Lake Mining Division (Table 1, Figure 3). The property is centered roughly on the Main Zone at 61^{o}43'37"N Latitude, 128^{o}21'46"W Longitude (UTM coordinates (NAD 83): 533700E, 6843800N, Zone 9). The property has since been expanded to 966 claims (20,286 hectares), covering areas to the north and the intermediate territory between it and the SPROGGE property to the east. Any claims staked subsequently to July 16th are not subject to assessment filing in this report.

The 3Ace property hosts three significant mineralized zones: the "Main Zone", hosting coarse visible gold in the south-central property area; the Green Zone, in west-central areas, and the Sleeping Giant Zone in the east-central area. No mineral reserves or resources have been delineated on the property to date. There are no mine workings, existing tailings ponds, waste deposits or other improvements, with the exception of the Nahanni Range Road (Yukon Highway 10) extending through the south-eastern property area.

As of February 8th, no permit has been issued for work done on the property. The 2010 work was considered as Class 1 activity which does not require permitting.

2.2 Option Agreements

On April 8, 2010, Northern Tiger announced completion of its Definitive Option Agreement with vendor Alex McMillan. The following was taken directly from the April 8th News Release:

"The Option Agreement, which is subject to TSX Venture Exchange approval, provides Northern Tiger with an option to earn a 100% interest in the property. To complete the option, Northern Tiger will be required to make cash payments of $500,000, issue 2,000,000 shares and incur $700,000 in exploration expenditures, all over a four year period. All shares issued shall be subject to resale restrictions prescribed by applicable securities laws and the polices of the TSX Venture Exchange. An annual advance royalty payment of $45,000 will start on the 5th anniversary of the agreement and continue until the commencement of commercial production.

"The Vendor will retain a 2% net smelter return interest (NSR) on the property. If a National Instrument 43-101 compliant resource estimate in excess of 500,000 ounces of gold at a grade greater than 5 g/t is defined on the property, the Vendor's NSR will increase to 2.5% and the vendor will receive a bonus payment of $300,000 (in cash or equivalent Northern Tiger shares). If a National Instrument 43-101 compliant resource estimate in excess of 1,000,000 ounces of gold at a grade greater than 5 g/t is defined on the property, the Vendor's NSR will increase to 3.0% and the vendor will receive an additional bonus payment of $300,000 (in cash or equivalent Northern Tiger shares). Each 1% of the NSR can be purchased by Northern Tiger for $2,000,000." (Northern Tiger website, 2010)

Other than the Net Smelter Return (NSR) and the terms listed above, there are no other royalties, back-in rights or other agreements and encumbrances to which this property is subject.

3.0 Physiography, Climate, Access and Infrastructure

3.1 Physiography and Climate

The 3ACE property that is the subject of this report occurs in an area of moderate to rugged terrain directly north of the confluence of the Hyland and Little Hyland Rivers, with elevations ranging from 940 to 2,100 metres (3,080 to 6,890 feet). The property is covered by coniferous forest to about 1,500m, and by tundra vegetation to 1,800m, with scattered taiga to 1,650m. White and black spruce forest covers lower elevations, and subalpine fir covers higher forested elevations. There are no permanent snowfields on the areas staked prior to September, 2010.

Outcrop is fairly abundant above tree line, particularly along ridge lines and areas above 1,800m in elevation. Outcrop is sparse towards the floor of the Little Hyland River valley, although scattered exposures exist along valley walls, particularly along the west limb. Much of the mid to higher elevations are covered by rubblecrop and talus.

The 3ACE property has a northern alpine climate, with cool summers and very cold winters. Daily high temperatures in July average 15^{o}C, with variation depending on elevation; daily highs in January average -20^{o}C, although temperatures as low as -50^{o}C have been recorded. Precipitation is moderate, although higher than most other areas of Yukon. Snowfall levels average about 1.5 metres by mid-March. The field season extends from late June to mid-September, although diamond drilling may continue into early winter.

3.2 Access, Infrastructure and Local Resources

Areas east of the Little Hyland River in the eastern property area are directly accessible by the Nahanni Range Road (Highway 10), an all-weather gravel road open year-round and extending from the Robert Campbell Highway to the Cantung tungsten mine. The property is located about 250 road kilometers from Watson Lake, Yukon. The majority of the property is located west of the Little Hyland River and is thus accessible by helicopter, based from a campsite at Kilometre 138. The Hyland airstrip, in good serviceable condition, is located along the Nahanni Range Road about 23 kilometers south of Kilometre 138.

The 3ACE property is large enough to contain any future mining, milling and waste disposal areas, as well as heap leach pads and potential processing plant sites. The Little Hyland River and the major tributaries of the Hyland River to the west have an adequate water supply to service any future operations. Numerous smaller streams with adequate water also occur across the property, although some highland areas, particularly along ridge lines are quite distant from adequate water sources.

Watson Lake is a full-service community along the Alaska Highway with a population of about 1,700, including surrounding communities. The town has good hotel and restaurant facilities, grocery, hardware, lumber, fuel and expediting services, as well as a hospital. The town is serviced by local diesel-electric power and has a limited available work force. The Cantung Mine, roughly 50 road kilometres north of the property, also provides emergency medical facilities. Watson Lake is located about 450 kilometres east of Whitehorse, a full service community with a population of about 25,000, including a sophisticated mineral exploration service community and an available workforce.

No metal or concentrate production has occurred on the property.


140°0'0"W
135°0'0"W
130°0'0"W
125°0'0"W
120°0'0"W
68°0'0"N
66°0'0"N
64°0'0"N
62°0'0"N
60°0'0"N
ALASKA
UNITED STATES OF AMERICA
NORTHWEST TERRITORIES
3Ace Property
Whitehorse
BRITISH COLUMBIA
Legend
3Ace Property
Watershed
Road
Yukon Border
N
Kilometers
0 50 100 200 300
Northern Tiger Resources Inc
Figure 1: Property Location Map
3Ace Property
Yukon Territory, Canada
NTS 105H09/10/15/16
UTM Nad83, Zone 8
Edmonton, AB
Scale: 1:6,000,000
Whitehorse Mining District
December, 2010


480000
500000
520000
540000
560000
580000
600000
6880000
6860000
6840000
6820000
6800000
6780000
6760000
6740000
6720000
N
140°0'0"W
120°0'0"W
65°0'0"N
60°0'0"N
130°0'0"W
3Ace
Sprogge
ROYAL
FLUSH
SPADE
CLUB
DIAMOND
JOKER
POKER
Legend
Claims
NTR Claims
Other Quartz Claims
Yukon-NWT Border
Transport
Road
Limited-use Road
Trail
Kilometers
0 5 10 20 30 40 50
Northern Tiger Resources Inc
Figure 2: Regional Location Map
3 Ace Property
Yukon Territory, Canada
NTS 105H/95E
UTM Nad83, Zone 9
Edmonton, AB
Scale: 1:750,000
Watson Lake Mining District
February, 2011

522000 523000 524000 525000 526000 527000 528000 529000 530000 531000 532000 533000 534000 535000 536000 537000 538000 539000 540000 541000

6860000 6858000 6856000 6854000 6852000 6850000 6848000 6846000 6844000 6842000 6840000 6838000 6836000

N

Hyland River

Lake Finland Road

Nahanni Range Road

Pigeon Creek

Quantity Creek

Legend

- 3Ace Claims Prior to September, 2010
- 3 Ace Claims

Transport

- Road
- Limited Use Road
- Trail

Watershed

- Lake/River
- Stream
- 20m Contours

Meters

0 1,000 2,000 4,000

Northern Tiger Resources

Figure 3: Claims Map
3 Ace Property
Yukon Territory, Canada

NTS 105H09/10/15/16
UTM Nad 83, Zone 9
Edmonton, AB

Scale: 1:25,000
Watson Lake Mining District
February, 2011

4.0 History

The earliest exploration in the present 3ACE area occurred in 1964 when the Norquest Joint Venture staked the RAIN 1-6 claims about 14 kilometres southwest of the Kilometre 138 campsite. The Norquest JV conducted geological mapping in 1965.

The RAIN block was restaked as the SUN 1-8 claims in 1980, and sold to Conquest Exploration Ltd. In 1987 the Vista Resource Company optioned the property, conducted surface magnetometer surveying and geological mapping, and followed with a 4-hole, 389-metre diamond drilling program targeting copper-gold skarn mineralization.

The SUN property was restaked as the JUSTIN 1-4 claims in 1995 by Mr. Bernie Kreft, who optioned them to Hemlo Gold Mines, which added the SUN 5-25 claims later that year. In 1996, Hemlo merged with Battle Mountain Gold; the successor company, also called Battle Mountain Gold, discovered abundant quartz-arsenopyrite veining returning values to 34 g/t gold in a cirque called the "Sugar Bowl" 9 kilometres to the northwest. The company staked the SPROGGE 1-74 claims to cover a sizable area of abundant vein and dyke-hosted mineralization, as well as areas of pervasive limonitization with a strong gold-in-soil signature. In 1997 Battle Mountain Gold optioned the JUSTIN and SPROGGE properties to Viceroy Exploration (Canada) Ltd, which conducted some further surface exploration and added the SNOW 26-101 claims surrounding the JUSTIN block, and also the SPROGGE 75-158 claims farther west, transforming the two blocks into a single large continuous package (Yukon MINFILE, 2010).

In 1998 Viceroy conducted a more comprehensive surface exploration program. The Sprogge discovery encouraged the Hudson Bay Exploration and Development Co. to conduct a regional geochemical survey and to stake the HIT 1-32 claims late that year. In 1998 Hudson Bay staked the HIT 33-129 claims and conducted grid geological sampling across much of this block. Alex MacMillan staked the 3ACE 1-83 claims directly to the south in August to September 1998, and optioned them to Hudson Bay. Hudson Bay also staked the HAB 1-113 and HAT 1-20 claims to the northwest, eventually forming a contiguous northwest-trending block, including the 3ACE claims, between the Nahanni Range Road and the HAT block.

Results of the 1998 Hudson Bay geochemical program revealed several strong gold-in-soil anomalies. Four of these were selected for a diamond drilling program consisting of 600.1 metres, with one hole testing each anomaly. One, targeting the northernmost anomaly, returned a value of 4.506 g/t gold across 1.5m from a siltstone-shale layer overlying a large unit of greywacke to conglomerate, the latter returning anomalous gold and arsenic values. No significant values were returned from the other three holes.

In 1999 NovaGold Resources Inc. acquired a 100% interest in the SPROGGE block and conducted limited surface exploration. In 2000 NovaGold entered into an agreement with Kennecott Canada Inc, which conducted a 4-hole, 762-metre diamond drilling program in the Sugar Bowl area (Yukon MINFILE, 2010). No significant results were reported.

In 2002 Eagle Plains Resources Ltd. acquired a 100% interest in the JUSTIN block, and conducted surface exploration later that year. The project remained idle until 2010, when Eagle Plains flew a 207-km airborne survey followed by a surface exploration program. The latter confirmed results from the 1996 and 1997 programs, and led to discovery of the "Pow" zone towards the northern property boundary, as well as lead-zinc-silver mineralization towards the southeast boundary (News Release, Eagle Plains Resources, Nov 4, 2010). The JUSTIN block is now called the SPROGGE property.

Ownership of the Sugar Bowl area 9 kilometres to the northwest was transferred to Alexco Resource Corporation, although no further significant work was reported. This block is also called the SPROGGE property. Most of the area between the two SPROGGE blocks was allowed to lapse and has recently been restaked by Valley High Ventures Ltd.

In 2000 Hudson Bay returned the 3ACE property to Alex MacMillan. In 2003 Mr. MacMillan discovered significant gold-arsenic mineralization along the Nahanni Range Road, returning values from grab sampling to 0.99 oz/ton (33.90 g/t) gold. Mr. MacMillan also discovered the Discovery Outcrop of the "Main Zone"; grab sampling returned values to 157.53 oz/ton. The property was optioned to North American Tungsten Corporation Ltd which conducted detailed grid soil geochemical surveying on both sides of the Little Hyland River and on a small grid southeast of the Main Zone.

No further exploration was reported prior to acquisition of the 3ACE property by Northern Tiger Resources early in 2010.

5.0 Geology

5.1 General Geology

The 3ACE area is located within the south-eastern portion of the Selwyn Basin, a thick sequence of shelf and off-shelf sedimentary and lesser volcanic strata deposited along the southern margin of the Ancient North American Platform. Strata were deposited from the late Proterozoic to early Triassic, and underlie much of central and south-eastern Yukon north of the Tintina Trench. Much of the area within about 100 kilometres of the Tintina Fault has undergone district-scale transpressional faulting.

More specifically, the 3Ace property is underlain by late Precambrian to early Cambrian Hyland Group, Yusezyu Formation strata, consisting of coarse clastic sediments intercalated with fine clastics and lesser limestone and mixed clastic and chemical sediments. This stratigraphic assemblage extends south-southeast along the southwest side of the district-scale March Fault, separating Hyland Group sediments from coeval Neoproterozoic shales and siltstone of the Vampire Formation (Hart and Lewis, 2005) north of the present 3Ace block, and Cambro-Ordovician limestone of the Rabbitkettle Formation north of the Sprogge blocks. The district-scale "Owls Creek Anticlinorium" has been identified as extending within the Hyland Group through the northern portions of the 3Ace property and paralleling the March Fault (Hart and Lewis, 2005).

5.2 Property Geology

Mapping in 2010 indicated that the entire accessible property area is underlain by Yusezyu Formation sediments. This can be subdivided into two main members: a coarse clastic member consisting of quartz pebble conglomerate, sandstone, "grits", greywacke and lesser quartzite; and a fine clastic member consisting of black fine grained phyllite to slate with lesser siltstone. These form a complex intercalated package, with phyllite underlying roughly 40% of the southern area and occurring as wide to narrow units within the coarse clastics (Map 1). Contacts are interpreted as northwest-trending, roughly conformable with the trend of the Hyland Group package and the March Fault. Lesser units of grey limestone occur in northern portions of the southern property area.

The northern property area underwent limited mapping in 2010, suggesting a similar northwest trending assemblage of coarse clastic sediments with somewhat less abundant units of black phyllite and slate. South-eastern portions of the northern block also host at least one broad unit of limestone, locally fractured with weakly ankeritic limy infilling. 1999 mapping by Hudson Bay interpreted portions of this as phyllite intercalated with limestone. The extreme northwest portion of the property (prior to September, 2010), previously held as the HAT 1-20 block, is also partially underlain by a thick package of grey limestone, in contact with quartz-pebble conglomerate, locally calcareous, to the north and phyllite to slate in extreme western areas.

The individual sublithologies of the coarse clastic units can be considered as a continuum, with lithologies essentially blending into each other. The most coarsely grained and most common

sublithology is a quartz-pebble conglomerate (QPC, shown as PrChc on Map 1), consisting of subangular to subrounded grains from 0.2 to 1.5 cm in length. The composition is sub-arenitic, with 60 – 70% white quartz grains, 15 – 20% feldspathic grains, and minor mafic grains. Sandstone and greywacke units have roughly the same composition, and are classified as to sorting (sandstones are well sorted, greywackes are poorly sorted). "Grits" are coarse clastic arenaceous rocks with angular to subangular clasts; these comprise a fairly minor portion of the coarse clastic sediments. Feldspathic grains have almost universally undergone strong clay alteration regardless of depth and grain size and degree of sorting.

Coarse clastic sediments also typically host abundant tension gash veining, ranging from sub-centimetre to greater than 20 centimetres in width. The majority of larger, metre-plus scale quartz veins are also hosted by this unit. Coarse clastics also commonly display weak to moderate pervasive silicification, and weak argillic alteration. The bulk of arsenical and auriferous mineralization occurs within coarse clastic sediments.

The black shales to fine phyllites (PrChs) typically show millimetre-scale bedding, commonly folded on hand specimen-scale, and with a strongly developed cleavage. Grain size is typically mudstone to shale, with rare interbedded or gradational sandstone beds. Quartz veining is much less abundant (although still fairly common) than in the coarse clastics; veins tend to be much more irregular in orientation, with local metre-scale areas of quartz flooding. Minor chloritic shales (PrChsc) occur in the northern portion of the area of detailed mapping.

The coarse clastic and fine phyllitic members tend to occur as distinct units with sharp although conformable contacts, with lesser fault and shear-based contacts. Despite the age of the stratigraphy, metamorphic grade is very low, limited to weak slate development of shales and weak foliation and grain orientation of the coarse clastics.

5.3: Structural Geology

The following section was taken verbatim from an in-house summary structural report prepared by Christopher Buchanan, MSc, PGeo, of Buchanan Geoscience Services of St John's, Newfoundland and Labrador. Other portions of Mr. Buchanan's report will be included in subsequent sections of this report.

The structural geology of the 3Ace Property has not been documented in detail by previous workers and it has only been noted that the regional stratigraphy is moderately-dipping and cross-cut by late quartz vein systems (M. Buchanan, 1999). A detailed geology map of the Hat claims (i.e., the northern extent of the 3Ace property) by A. Tessier and A. Fonseca, published in Buchanan (2000), indicates the area underwent complex polyphase deformation. The deformation history presented by Tessier and Fonseca includes: early, south-verging thrust faults, north-trending open folds, and late north- and east-trending normal faults (Buchanan, 2000). During the 2010 field program these structural elements were identified and mapped in the vicinity of the primary gold prospects on the 3Ace Property. However, the pre-mineralization structural history is more complex than what is presented by Buchanan (2000).

Four phases of deformation (i.e., D_1, D_2, D_3 and post-D_3) were identified on the 3Ace Property during the 2010 mapping program. Although three of the deformation events pre-date the gold-bearing quartz veins, the early deformation history has an important role in generating fluid pathways, like reactivated faults and cleavages, for subsequent mineralized fluids (Peters, 1993). The structural elements that define each stage of the deformation history are described in the following sections:

D_1 Deformation: The oldest structural element preserved on the 3Ace Property is a gently- to moderately-dipping S_1 cleavage. S_1 is a pressure-solution cleavage that forms a penetrative fabric and defines the general sheet dip at many of the outcrops on the property. Locally, the S_1 fabric is axial planar to recumbent, tight F_1 folds, which have only been observed as small-scale, rootless parasitic folds preserved in a few outcrops. However, the penetrative nature of the axial planar cleavage and truncated, overturned limbs of the parasitic folds indicate that the F_1 fold system is regionally significant. The D_1 structures are interpreted to have formed early in the Mesozoic-aged compressional deformation of the Selwyn Basin (Gordey and Anderson, 1993). These early folds and thrust faults are the primary control on the regional distribution and geometry of the Hyland Group sedimentary rocks; particularly the competent, strongly fractured quartz pebble conglomerate package.

D_1 thrust faults are not commonly exposed on the property, but the distinct lithological break across the Green Zone is interpreted to occur along the trace of a first order D_1 thrust. The upper imbricate sheet, north of the Green Zone, contains a sequence of interbedded phyllite, limestone, and calcareous sandstone. In contrast, the footwall imbricate sheet is comprised of interbedded black phyllite, green siltstone, and quartz pebble conglomerate. The thrust was re-activated during younger, brittle deformation events which resulted in widespread brecciation (see post-D_3 deformation).

D_2 Deformation: The second generation structures (F_{2a}) are characterized by west-northwest to southwest-trending, southerly-verging, steeply-inclined, tight asymmetric folds. A non-penetrative axial planar cleavage (S_2) is locally developed in the hinge zones of F_{2a} folds. The F_2 fold system folds both bedding (S_o) and S_1, creating distinct domains of moderately- and steeply-dipping stratigraphy across the property.

Also identified is an unmineralized quartz tension vein array (TVA) developed in a west-trending shear zone that dips moderately to the north. The TVA indicates the fault underwent reverse dip-slip, but the sense of strike-slip displacement is unknown for this fault. This population of brittle-ductile shear zones cross-cut D_1 structures and are interpreted to be kinematically associated with the south-verging F_{2a} fold system. The D_2 thrust faults formed as break-thrusts which truncate and offset the forelimb F_2 folds.

Locally, another generation of folds (F_{2b}) overprints the S_1 cleavage, but has the opposite asymmetry (i.e., northerly-verging) of the main F_2 fold system. The significance of these folds is not yet known because the relative overprinting relationships between F_{2a} and F_{2b} folds were not observed. It is hypothesized that F_{2b} folds are associated with north-verging, antithetic shear zones formed to accommodate shortening of the D_2 fold-thrust system (Mitra, 2002). Further analysis of the available datasets is required to determine the significance of the F_{2b} fold system.

D_3 Deformation: Third generation structures consist of gently-plunging, north-trending, upright, open folds (F_3). The F_3 fold system has a large wavelength (i.e., approximately 0.5 km) and at the property scale is noted primarily as meso-scale parasitic folds, conjugate kink-bands, and a gentle warping of orientation patterns of earlier structural elements (i.e., bedding, D_1, and D_2) across the property. The F_3 fold system will likely affect the regional distribution of the Hyland Group, but at the property scale this structural element has minimal effect on the geometry of prospective stratigraphic horizons.

Post-D_3 Deformation: The older structural elements on the 3Ace property are cross-cut by late, brittle-ductile fault zones that are delineated by 0.4 m to 1.5m-wide laminated fault-fill quartz veins. Typically the veins contain pyrite, arsenopyrite and gold mineralisation. The Main Zone and Sleeping Giant faults are north-northwest- to north-trending; the Main Zone is a moderately to steeply east-dipping structure. The two faults are interpreted to be coeval and formed in the same strain environment. The vein system at the Main Zone fault zone has been mapped over a strike length of 60 metres and has an apparent width of approximately 27 metres.

6.0 Deposit Types

Although exploration in the late 1990s in the 3Ace – Sprogge area was focused on intrusion-related mineralization typical of the Tintina Gold Belt, a 2005 paper entitled "Gold Mineralization in the upper Hyland River area: A non-magmatic origin" by C. Hart and L. Lewis of the Yukon Geology Survey, suggests an orogenic origin to gold mineralization. Briefly, in this setting gold may have been concentrated in metamorphic fluids which were subsequently remobilized along deep crustal fault structures and emplaced among zones of high permeability, such as normal faults and areas of pervasive fracturing. In such a setting, mineralization occurs primarily in a mesothermal lode setting; in the upper Hyland River areas it is manifested as quartz-arsenopyrite veins, quartz-pyrite-galena veins, massive arsenopyrite veins and disseminated pyrite and arsenopyrite in coarse clastic sediments (Hart and Lewis, 2005). Vein settings of the first three may also occur as quartz stringer and stockwork zones, depending on degree of structural preparation.

Areas near the main crustal-scale structure are more likely to host larger, more continuous quartz veins, potentially of deposit size, whereas more distal areas may host zones of more narrow quartz veining and stockwork zones. Certain deposit settings, primarily replacement-style settings such as skarns or intrusion-hosted "Fort Knox-style settings" typical of intrusion-related systems, are not expected to occur in the Upper Hyland River area except for areas proximal to Tintina Gold Belt intrusions. Mesothermal veins may also occur in intrusion-related systems, which focused early workers on this style of deposit setting in the Upper Hyland River area.

7.0 Mineralization

Prior to the 2010 field season, two significant mineralized showings had been discovered on the 3Ace property: the Main Zone, consisting of spectacular visible gold in a quartz vein; and the North Zone, an arsenical quartz vein with spotty visible gold. Two significant zones were identified in 2010: the Green Zone – Green Mile prospects occurring along an interpreted south-dipping thrust fault towards the north end of the southern block, and the Sleeping Giant Zone, about 1.2 km east of the Main Zone (Map 1).

7.1: Main Zone

The "Discovery Showing" of the Main Zone consists of a 7-metre exposure of a north-south striking white quartz vein averaging 1.0 metres in width. Very spectacular visible gold occurs along the eastern, hanging wall side of the vein, locally comprising much of the slickenside face along this side. Lesser, although still very abundant, visible gold occurs elsewhere throughout the vein. The Main Zone vein is moderately arsenical, with weakly elevated levels of copper (Cu), lead (Pb), and antimony (Sb). Gold occurs largely as free gold, although some correlation with arsenic occurs, particularly in the western outcrop. The eastern, hanging wall side consists of strongly silicified quartz-pebble conglomerate with abundant quartz veining ranging in width from 1-10 cm. Similarly moderately silicified, argillically altered and weakly pyritic and arsenical quartz-pebble conglomerate occurs up to 25 metres west of the footwall side.

The Main Zone vein is located along a north-south trending shear zone separating a quartz-pebble conglomerate unit on the eastern, hanging wall side to the east, from sheared phyllites along the footwall side to the west. Hand trenching of the vein roughly 15 – 20 metres to the north revealed two "step-overs" caused by dextral faulting along north-south trending fault traces at a scale of about four metres between upper and lower limbs. C. Buchanan has interpreted these features as en-echelon faults, stating: "The veins form an array of en echelon fault segments with individual strike lengths of five to seven metres. Displacement along the fault segments is propagated through quartz stockwork zones developed in the three to four metre stepovers between the overlapping veins" (Buchanan, 2010). Buchanan states the "Main Zone", including mineralized wallrock, has "an apparent width of approximately 27 metres" (Buchanan, 2010).

Buchanan also states: "Kinematic indicators are poorly developed in the laminated fault parallel veins, and quartz TVA are not developed at the Main Zone, obscuring the shear sense of the fault zone. However, deflection of the S_1 cleavage within the hanging wall of the fault zone suggests the strike-slip shear sense is dextral. Slickengrooves on fault parallel laminations within the veins are oblique to the strike of the veins and indicate the Main Zone Fault has a dextral-normal sense of shear" (Buchanan, 2010).

Early in the 2010 program, visible gold in quartz was discovered in outcrop about 50 metres north of the Discovery outcrop, increasing the known strike length to about 60 metres. The

setting of this occurrence, with the footwall side adjacent to altered phyllite, is similar to the Discovery Outcrop, suggesting the structural setting extends between the two exposures.

A second quartz vein of similar size was discovered about 40 metres west of the Main Zone; however a single chip sample returned low gold values.

7.2 Sleeping Giant Zone

The Sleeping Giant Zone, located about 1.3 kilometres east of the Main Zone, was discovered through "ground truthing" of very strong gold-in-soil values returned from the 1998 Hudson Bay geochemical surveying program. The zone has been interpreted as a series of north-east trending lenticular quartz vein bodies along a north-south extending corridor currently traced for about 220 metres (Map 5). Quartz occurs as nearly massive bodies to 25 metres in width, and appears as impressively large surface exposures. The quartz veining consistently hosts 2-4% clotty and fracture-controlled arsenopyrite. Visible gold has been identified as accretions on arsenopyrite blebs at three locations, two towards the southern end including fairly abundant gold directly at the southern extreme, and one in central areas of the zone.

Year-2010 mapping and prospecting towards the north end of the zone revealed that the style of veining trends from massive quartz to abundant smaller tension gash veins within silicified quartz-pebble conglomerate, with minor clotty arsenopyrite. Vein exposure at the southern end terminates abruptly, in an area of fine grained patchy visible gold with minor arsenopyrite.

In 1999 Hudson Bay collared a single diamond drill hole about 150 metres northeast of the north end of the Sleeping Giant zone. No significant gold values were returned.

7.3: Green Zone

In 2010, Northern Tiger Resources delineated a trend of quartz-arsenopyrite +/- scorodite veining and mineralization extending roughly east-west for a distance of about 2.0 kilometres. The zone was delineated from a combination of detailed geological mapping and geochemical sampling across its western end, incorporating geochemical results from Hudson Bay's 1998 program. The western portion which was the subject of the detailed surface work is called the Green Zone; the eastern portion, which underwent year-2010 geological mapping and rock sampling but no systematic soil sampling, is called the "Green Mile". These are separated by an interval lacking anomalous values located roughly at the mid-point.

The Green Zone consists of abundant tension gash arsenical quartz veining within subarkosic quartz-pebble conglomerate and lesser greywacke. In central and western areas this is comprised of a corridor up to 100 metres in width with poddy occurrences of strongly scoroditic and arsenical quartz veining and strongly scoroditic wallrock. Several pods of strongly brecciated, strongly scoroditic quartz pebble conglomerate occur in western areas. The zone was named based on its high green to yellow scorodite content.

Detailed geological mapping and geochemical sampling delineated an east-west corridor from 10 – 20 metres in width, exposed in two major rubblecrop locations. The eastern exposure, traceable for about 150 metres in an east-west orientation, occurs as a 10-metre wide rubblecrop corridor of silicified, scoroditic +/- arsenical coarse clastic rocks with localized limonitic areas. The western exposure extends about 250 metres west-northwest from a point roughly 120 metres west of the aforementioned zone. Towards its eastern limit, abundant brecciated scoroditic quartz-pebble conglomerate talus float suggests a structurally-hosted setting.

At least three other smaller mineralized trends located north of the western trend were delineated from detailed surface exploration, including one north-south extending trend of scoroditic coarse clastic rocks.

The highest gold value from the central Green Zone area was returned from a specific composite grab rubblecrop sample of quartz pebble conglomerate with arsenical and scoroditic quartz veining. Rock sampling throughout the Green Zone indicated gold values have a much stronger correlation with silver, arsenic, lead and antimony than within the Main and Sleeping Giant zones; silver values are typically significant where associated with high gold values.

A rubblecrop occurrence of auriferous quartz-pyrite veining in greywacke at the extreme northwest end of the Green Zone was identified. Although exposures of limonitic, altered coarse clastic rocks with fairly abundant quartz +/- pyrite +/- scorodite veining extend several hundred metres farther to the west-northwest, sampling returned near-background gold values.

An occurrence of veined and brecciated quartz pebble conglomerate and quartz veining, likely associated with the same northwest trending, southwest dipping thrust fault controlling the Green Zone occurs roughly four kilometres north-northwest of the central Green Zone area. The zone hosts rare proximal float of quartz-arsenopyrite veining.

The 2010 surface program on the Green Mile segment was limited to geological mapping and rock sampling. This segment, consisting of abundant quartz-arsenopyrite-scorodite veining and silicified and moderately limonitic coarse clastic sediments extends for 1.2 kilometres along a steep, south-facing rocky exposure (Map 2). The Green Mile is likely the source of very high gold-in-soil geochemical values returned from the 1998 program by Hudson Bay. Composite grab and chip sampling typically returned anomalous but not significantly high gold values, with the exception of a grab sample of talus float returning 66.516 g/t Au with 8.13 g/t Ag. Again, gold has a very strong correlation with arsenic, lead and antimony, although the correlation with silver is somewhat weaker than in the Green Zone segment.

7.4 North Zone

The North Zone was the first significant mineralized zone discovered within the present 3Ace property boundary. This consists of a northeast trending quartz vein with roughly 1% clotty arsenopyrite and localized visible gold occurring along arsenopyrite grain boundaries.

The North Zone is located towards the western end of an area of abundant quartz veining and flooding extending at least 70 metres eastward. Numerous chip samples returned low to weakly anomalous gold values, with the exception of a 1.5-metre chip sample of quartz-pebble conglomerate with sheeted quartz veining and clotty arsenopyrite which returned 1.500 g/t Au. Silver values were low to near-background.

8.0 2010 Work Program

8.1. Description of Surface Exploration Program

A surface exploration program was conducted from June 29 through Aug 20, 2010, focusing primarily on the southern portion of the claim block as of June, 2010. This program consisted of geological mapping across the southern half of the property (Map 1a) and more cursory mapping across the northern portion (Map 1b). The program included establishment of two soil geochemical surveys: one covering an area of 1.2 by 1.0 km, and consisting of soil sampling at a100-metre northwest-oriented line spacing and 25-metre station spacing. This grid covered both the Main and North Zones, and areas to the northwest (Map 2). The grid included a 100 by 100-metre area of detailed soil sampling with a 10-metre line spacing and 10-metre station spacing, centered on the Discovery Outcrop of the Main Zone (Map 3). The second major grid covered the "Green Zone", and consisted of northeast-oriented soil lines at a 50-metre line spacing and 25-metre station spacing. Approximately 0.7 km^2 were covered by this survey.

The majority of the southern portion of the pre-September property extent underwent geological mapping, prospecting and rock sampling (Map 1). Detailed geological mapping was conducted across the entire Green Zone grid, and the Main Zone area of the larger grid. Detailed structural mapping was also conducted across the property, focusing on the Main and Sleeping Giant zones. Silt geochemical sampling was also done along all streams in the southern part of the block, at 250-metre intervals along the main stem and from tributaries.

The northern property area received limited geological mapping, due to distance from the central campsite. Silt sampling was also done along the two major streams and several tributaries within this area.

The 2010 program also included a property visit on June 13, 2010 by Mr. Dennis Ouellette, VP of Exploration for Northern Tiger Resources. This visit focused on rock sampling of the Discovery Outcrop area of the Main Zone.

8.2 Main Zone

8.2.1 Bedrock Geochemical Results, Main Zone

On June 13th, 2010, nine grab samples of quartz vein material were taken from the Discovery Vein area and analyzed by Metallic Screen Fire Assay (MSFA) analysis. Of these, four were taken from bedrock vein material, returning gold values from 29.88 g/t (0.873 oz/ton) to 4,820

g/t (140.771 oz/ton). The other five, taken from proximal quartz float or rubblecrop, returned values from 83.58 g/t (2.441 oz/ton) to 4,259.31 g/t (129.396 oz/ton) gold. In all samples, the "plus fraction": minus fraction ratio (coarse: fine gold) ranged from 17.5 to 135, indicating the vast majority of gold occurs as coarse gold.

The Discovery Outcrop of the Main Zone was the subject of nine further chip samples taken in July 2010, including three of quartz-pebble conglomerate hosting quartz veining along the hanging wall side. Results from 50-gram fire assay analysis ranged from 64.585 g/t Au (1.88 oz/ton) with 3.87 g/t silver (Ag) across 1.0m to 795.917 g/t Au (23.25 oz/ton) with 50.19 g/t Ag across 1.1m. MSFA gold analysis returned a value of 91.69 g/t (2.68 oz/ton) Au for the former and of 1,013.54 g/t (29.60 opt) for the latter. The lowest gold value returned from MSFA analysis was of 86.03 g/t (2.51 oz/ton) Au with 4.3 g/t Ag across 0.65m. Chip sampling of the conglomerate hanging wall returned anomalous gold values from 0.240 g/t Au across 0.9 metres to 1.350 g/t across 0.2m. Chip sampling of similar material up to 25 metres west, stratigraphically below the footwall side, returned elevated gold values to 0.242 g/t Au across 1.3m (Appendices 2 and 3).

The area of en echelon fault segments directly west of the Discovery Outcrop also underwent detailed chip sampling. Chip sampling in this area returned values from 9.591 g/t Au with 2.08 g/t Ag across 1.5m, to 181.056 g/t (5.29 oz/ton) Au with 13.06 g/t Ag across 1.0m.

At the auriferous quartz vein exposure 50 metres north of the Discovery outcrop, a 0.9-metre chip sample of quartz vein material returned 30.20 g/t Au with 1.31 g/t Ag; a separate 0.6-metre chip sample returned 38.102 g/t Au with 8.09 g/t Ag. Chip sampling of the conglomerate hanging wall returned values to 2.44 g/t Au across 1.1m.

A single 1.0-metre chip sample taken from a separate vein 40 metres to the west returned a value of 0.082 g/t Au with background silver values. Chip sampling of two proximal boulders slightly uphill, possibly belonging to this vein, returned values of 0.736 g/t Au across 0.7m and 0.338 g/t Au across 1.2m.

8.2.2: Geochemical Results, Main Zone

The Main Zone was the subject of a very detailed soil geochemical grid, with a 10-metre line spacing and 10-metre station spacing covering a 100 m^2 area centered on the Discovery outcrop (Map 3). This occurs within a much larger soil geochemical grid covering a 1.2 by 1.0-km area, and encompassing both the Main and North Zones (Map 2). Predictably, the detailed survey returned very high gold-in-soil results typically exceeding 0.500 g/t to a maximum of 19.319 g/t downslope of the vein. This signature extends from roughly 15 metres south of the Discovery outcrop to beyond the limit of detailed surveying (Map 3). High gold-in-soil values to 4.318 g/t were returned from the northwest boundary of the grid. A value of 4.509 g/t was returned from a soil sample from the larger grid beyond the northwest limit of the detailed grid; follow-up sampling of a 15-cm long float boulder (B. Pollries, pers comm.) returned a value of 150.85 g/t Au with 12.30 g/t Ag. Also, two values of 2.477 and 2.449 g/t Au were returned roughly 25

metres southeast of the Discovery outcrop, suggesting a right-lateral offsetting of the zone, consistent with small scale fault offsets revealed from hand trenching.

Gold values decrease with downslope distance from the Main Zone vein, suggesting no other significantly mineralized zones occur within the detailed grid. Moderately elevated values to 0.411 g/t Au occur a short distance uphill of the vein, likely representing weakly auriferous coarse clastic hanging wall rock. Anomalous gold values were returned from several locations along a small stream downslope to the southwest; panning returned numerous gold "colours".

8.3 Sleeping Giant Zone

The Sleeping Giant Zone underwent chip sampling at three main locations: the extreme south end, the central area near one of the visible gold occurrences, and the northern end (Map 5). Chip sampling at the south end returned values to 43.67 g/t Au with 4.89 g/t Ag across 1.1m at one of the visible gold-bearing sites, and 11.541 g/t Au with 0.46 g/t Ag across 1.5m near the southernmost site with the most abundant visible gold. The Au: As ratio within these samples is higher than average for the zone. There is a high variance of gold values returned from surface sampling towards the south end, the lowest being 0.030 g/t Au from a composite grab sample, to a maximum of 82.27 g/t Au with 10.11 g/t Ag from a grab sample. Of 17 samples taken, 9 returned values exceeding 1.0 g/t Au; 4 returned values exceeding 10.0 g/t Au.

Chip sampling at the central location returned abundant high grade gold values including: 11.34 g/t Au across 6.0m, 7.55 g/t Au across 8.6m, and 6.78 g/t Au across 6.0m. Again, a high variance of gold values was revealed, ranging from 0.08 g/t from a grab sample to 29.07 g/t Au from a 2.0-metre chip sample. Of 19 samples taken in this area, 10 returned values exceeding 1.0 g/t Au; 5 returned values exceeding 10.0 g/t. A strong nugget effect is suggested by fire assay versus MSFA results for sample 481558; the former returned a value of 35.774 g/t Au across 2.0m; MSFA analysis returned a value of 15.58 g/t Au.

Chip sampling at the northern location returned gold values from 0.010 to 5.359 g/t Au across 2.0m. Gold values are lower here than in the other two major sampled areas, with only 2 of 13 samples returning values exceeding 1.0 g/t Au.

Elsewhere within the zone, five samples taken from 20 to 40 metres north, and uphill of, the southern sampled area returned values ranging from 0.06 to 0.43 g/t Au. The remaining areas of the zone remain untested on surface.

8.4: Green Zone

8.4.1 Bedrock Geochemical Results, Green Zone

Detailed geological mapping and rock geochemical sampling, as well as grid soil sampling, were conducted across the Green Zone. Composite-grab rock geochemical sampling of the eastern

east-west trending corridor returned values from 0.022 g/t across 1.2m to 1.100 g/t Au with 36.51 g/t Ag and 3.695 g/t Au with 34.2 g/t Ag from composite grab sampling (Map 4).

Composite and specific composite grab sampling towards the eastern limit of the western zone returned values from 4.072 g/t Au with 32.04 g/t Ag to 6.568 g/t Au with 62.66 g/t Ag. A 1.3-metre chip sample of similar material in rubblecrop returned a value of 0.818 g/t Au with 1.98 g/t Ag. Roughly 50 metres northwest, a composite grab sample of rubblecrop returned 3.68 g/t Au and 25.07 g/t Ag. Sampling in this area also returned numerous low gold values to a minimum of 0.01 g/t Au. However, many of the samples in the eastern portion of this zone returned gold values exceeding 1.0 g/t.

Rock sampling of the north-south extending trend of scoroditic coarse clastic rocks, returned values to 1.129 g/t Au with 59.17 g/t Ag. A nearby chip sample of similar material returned 0.568 g/t Au with 0.49 g/t Ag.

The highest gold value from the central Green Zone, returned from a specific composite grab rubblecrop sample of quartz pebble conglomerate, is of 7.338 g/t Au with 67.55 g/t Ag. The grab sample of quartz-arsenopyrite veining in greywacke at the extreme western end of the Green Zone returned a value of 8.041 g/t gold. A second composite grab sample taken nearby returned 0.097 g/t Au.

Rock sampling at the occurrence roughly four kilometres to the northwest returned weakly elevated gold values, with the exception of a specific composite grab sampling of quartz-arsenopyrite veining returning 3.307 g/t Au with 13.73 g/t Ag.

Composite grab and chip sampling at the Green Mile segment typically returned anomalous but not significantly high gold values, with the exception of a grab sample of talus float returning 66.516 g/t Au with 8.13 g/t Ag. Other notable values include a composite grab sample of talus of quartz – arsenic veining with minor galena returning a value of 1.078 g/t Au with 88.0 g/t Ag. Two composite grab samples taken near the eastern limit returned values of 1.606 and 1.054 g/t Au respectively.

8.4.2 Surface Geochemical Results, Green Zone

Surface geochemical sampling across the Green Zone consistently returned gold values in the 0.100 to 0.500 g/t range (Map 4). Values exceeding 0.500 g/t were also returned downslope of the eastern trend of strongly scoroditic altered quartz pebble conglomerate. Sampling also revealed a cluster of four samples ranging from 0.850 g/t Au to 2.581 g/t, near the top of a rubblecrop slope and roughly coincident with the north-south mineralized trend north of the main trend of the Green Zone.

Towards the extreme western limit a value of 1.607 g/t Au in soil was returned from the approximate location of the rock sample returning 8.041 g/t Au. The adjacent soil +sample 25 metres northeast returned 0.187 g/t Au.

8.5 North Zone

At the North Zone, a 1.5-metre chip sample returned 90.803 g/t Au with 5.04 g/t Ag. Two other chip samples at the same exposure returned values of 1.212 g/t Au across 1.5m and 0.030 g/t Au across 1.0m. The 1.5-metre chip sample of quartz-pebble conglomerate with sheeted quartz veining and clotty arsenopyrite about 75 metres east-northeast returned a value of 1.500 g/t Au. Silver values were low to near-background.

Soil sampling directly downslope of the North Zone outcrop returned a value exceeding 0.500 g/t Au, with values in the 0.100 to 0.500 g/t range returned from the next two downslope samples. Weakly anomalous gold-in-soil values from 0.050 to 0.100 g/t were returned along strike for about 200 metres in both directions.

8.6 Other Mineralized Occurrences

The "Hoito Occurrence" located southwest of the Green Zone consists of an exposure of weakly arsenical and pyritic white quartz with a minimum width of 5.0 metres. Three outcrop chip sampling returned values ranging from 0.855 g/t Au with 2.08 g/t Ag across 1.5m to 5.88 g/t Au with 2.03 g/t Ag across 2.0m. A composite grab sample returned 1.708 g/t Au with background Ag. Ironically, a "high grade" sample taken merely to test for gold presence returned only 0.044 g/t Au. All samples returned moderately anomalous arsenic, lead and antimony values.

Two composite grab samples of semi-massive arsenopyrite veining farther southwest of the Green Zone returned 9.464 g/t Au with 2.72 g/t Ag, and 22.89 g/t Au with 174.4 g/t Ag. However, the veins are small and of limited extent.

A composite grab sample of quartz veining with visible gold in a small rubblecrop occurrence north of the Main Zone returned 2.244 g/t Au. A sample of a separate rubblecrop boulder returned 0.471 g/t Au. The exposure is likely of limited extent.

A composite grab sample of quartz-arsenopyrite veining somewhat south of the Green Mile returned a value of 15.544 g/t Au with 43.97 g/t Ag, from a narrow northeast trending shear zone.

8.7 Personnel

The following personnel were involved with the surface program:

Carl Schulze, BSc, PGeo:	Project Geologist and Qualified Person
Chris Buchanan, MSc, PGeo:	Structural Geologist, Buchanan Geoscience Services
Alex McMillan:	Contract prospector, Alex McMillan Prospecting
Fred McMillan:	Contract prospector, Alex McMillan Prospecting
Craig Tervit:	Field technician

Michael Linley:	Field Technician
Cody Wilkinson:	Field technician
Agnes McIntosh:	Cook

Dennis Ouellette, VP of Exploration for Northern Tiger Resources, visited the property on June 13th, 2010.

Helicopter services were provided by Trans North Helicopters based at Watson Lake. Expediting services were provided by Liard McMillan. Carl Schulze, Michael Linley and Craig Tervit were employed by All-Terrane Mineral Exploration Services based at Whitehorse, Yukon under contract to Northern Tiger.

A total of 336 rock, 1,178 soil and 103 silt samples were taken during the July - August 2010 program; a further 9 samples were taken by Mr. Ouellette on June 13, 2010. Sample analysis was done by Inspectorate Mining and Exploration Services, based at Richmond, British Columbia, with a preparatory lab based at Whitehorse.

9.0 Sampling Method and Approach

All geochemical sampling was subject to rigorous parameters, including detailed descriptions of each sample. Rock samples were obtained using an Estwing rock hammer or a "Geotul" hammer, and located in the field using a non-differential Global Positioning System (GPS) instrument. Samples were placed in plastic bags designed specifically for rock sampling. A tag with the unique sample number, supplied by Inspectorate Mining and Exploration Services, was placed in the bag; the sample number was written on both sides of the bag using "Magic Markers". The sample numbers were also written on soft metal "butter tags"; the tags were attached to the sample locations in the field. Some samples numbers were written on flagging tape with "Magic Markers".

Rock samples were recorded as to location (UTM - NAD 83), sample type (grab, composite grab, chip, etc), exposure type (outcrop, rubblecrop, float, etc.), formation, lithology, modifier (for textural or structural descriptions), colour, degrees of carbonate presence and silicification, other alteration if applicable, economic mineralization including estimated amounts, date, sampler and comments. Minimum sample weight was 0.5 kg, although samples tend to be larger than this.

Soil samples were recorded as to location (UTM – NAD 83), horizon, depth, slope angle, colour, presence of permafrost, vegetation type, surficial geology, fragment lithology (if known), percent organics, date, sampler and comments. If a particular parameter could not be determined, particularly for fragment lithology, no record was made. Samples were preferably taken of B-horizon material, although sampling of A or C horizon soil was done where B-horizon material was unavailable. This was preferable to omitting the sample. The minimum original sample weight was 0.25 kg. Sample numbers supplied by Inspectorate Services were scratched onto a small metal "butter tag" and tied on to the station picket. Samples were placed in kraft bags,

with a tag supplied by Inspectorate showing the unique sample number placed in the bag, and the sample number written in "Magic Marker" on both sides of the bag. The bags were then dried as much as possible before shipping.

Variability in results of soil sampling may be caused by depth of overburden, slope angle, and outcrop exposure, with lower values expected in flat areas with thick overburden. Gold ions are less mobile also; thus samples with high copper-gold ratios may reflect transport distance rather than low bedrock gold values.

Silt samples were taken from several locations at a particular site to improve representability, focusing on fine material. Sample locations in UTM NAD-83 format were recorded in the field using a non-differential GPS and described as to percent fines, colour, stream grade and width, date, sampler and comments. Samples were placed in kraft bags with a sample tag showing unique sample number, labelled and marked in the field in the same manner as soil samples. All samples were taken in order to provide accurate representation of mineralization present.

Field data was entered into Microsoft Excel spreadsheet format, and later matched with analytical results. This process was continually re-checked to ensure correct results are associated with descriptions.

The routine and repetitive methodology of soil and silt sampling should eliminate any chance of bias; metal values should accurately represent actual amounts per site. Soil anomalies may be transported, depending on slope and groundwater conditions; detailed records of slope, vegetation, soil conditions are used to determine probability of transportation. Care was taken during rock sampling to obtain as representative a sample as possible, including a comprehensive description of sample types. Chip samples are most representative of true grades, followed by composite grabs, then by single-piece grab samples.

10.0 Sample Preparation, Analysis and Security

All rock samples were placed in thick plastic industry standard sample bags, sealed with thick plastic serrated "Zap Straps" and sent in a similarly sealed rice bag to a preparatory lab of Inspectorate Mining and Exploration Services based at Whitehorse, Yukon, an analytical laboratory with ISO 9001:2008 certification**.** Sealed rice bags were personally handed to Liard McMillan, expediter for the project, and then handed to the courier, Twilite Services Ltd. and were delivered by the courier directly to Inspectorate. All rock samples were crushed to ensure that a minimum of 80% of the material was less than 2.0 mm in size; this material was thoroughly mixed. From this, a 250g sample was pulverized so that a minimum of 90% could pass through a -200 mesh screen; then a 30-gram sample of this underwent 4-Acid digestion followed by fire assay analysis with atomic absorption finish. This technique provides gold analysis ranging from 0.005 to 10.0 g/t gold. "Overlimits" were analyzed by gravimetric analytical techniques.

Individual soil and silt samples were placed in "kraft bags" and also sealed with a "Zap Strap"; samples were placed in properly labelled rice bags, also sealed with a "Zap Strap", and shipped to Inspectorate in the same manner as rock samples. Soil and silt samples were screened to 180-micron size (minus-80 mesh); the fine fraction then underwent gold analysis by 30-gram fire assay with ICP – AES finish, providing a detection limit of 0.005 g/t.

All samples were also analyzed by 48-element ICP to test for abundances of Ag, Al, As, Ba, Be, Bi, Ca, Cd, Ce, Co, Cr, Cs, Cu, Fe, Ga, Ge, Hf, In, K, La, Li, Mg, Mn, Mo, Na, Nb, Ni, P, Pb, Rb, Re, S, Sb, Sc, Se, Sn, Sr, Ta, Te, Th, Ti, Tl, U, V, W, Y, Zn and Zr.

Select samples, including many from the Main Zone chip sampling, were re-analyzed utilizing "Metallic Screen Fire Assay" (MSFA) analysis, whereby a 500-gram sample underwent screening at a 150-mesh level, with both the "+ 150-mesh" (coarse fragment) and "- 150-mesh" (fine fragment) analyzed separately. Then two values were recombined using a weighted average for a total gold value. This determines the proportion of gold occurring as coarse gold, and also provides a more reliable assay value due to the much larger sample size. This analysis was done on eight samples of the Main Zone, one from the North Zone and two from the Sleeping Giant Zone, as well as the nine samples taken in June. In all cases where both analytical techniques were employed, the MSFA values were publicly reported, as the larger sample size improves the accuracy of representation of true gold grades.

None of the samples obtained during the July and August programs were taken by a director or officer of Northern Tiger Resources. Although one direct staff member, Mr. Cody Wilkinson, of Northern Tiger was a member of the exploration crew, all activities were supervised by Carl Schulze of All-Terrane Mineral Exploration Services, which has no affiliation other than the provision of contract services. Mr. Dennis Ouellette, VP of Exploration for Northern Tiger Resources, took nine rock samples on June 13th, 2010.

Inspectorate provides comprehensive in-house quality-control, using numerous blanks to test for any potential contamination, confirming that no detectable contamination has occurred. Inspectorate also conducts repeated in-house standard sampling for all 48 elements involved in ICP analysis and gold to determine accuracy of analysis (Appendix 3: Original Results). Results of in-house standard sampling show a strong correlation with known values. Blank sampling also returned nil values for most elements, indicating a lack of contamination during the analytical process. This author is of the opinion that all analytical results are representative of metal or elemental content within the sample, and has no reason to suspect any breach of security of shipment has occurred.

11.0 Data Verification

Results of the soil geochemical survey across the Green Zone is in part a due diligence survey of systematic soil surveying conducted by Hudson Bay Exploration and Development Co. Ltd in 1998. The Hudson Bay survey outlined a significant geochemical anomaly, the "Hit A3" anomaly, confirmed by the 2010 survey which utilized the existing grid orientation and station

nomenclature as much as possible for comparison of results, although the latter survey has a much narrower line spacing (Map 4). The 2010 results compared fairly well with the 1998 results, confirming the presence of a strong gold-in-soil anomaly and leading to preliminary delineation of the Green Zone.

The North Zone area and areas northwest of the Main Zone underwent grid soil sampling in 1998 and 2010. The North Zone occurs towards the uphill terminus of the "Hit A5" anomaly identified in 1998 and repeated in 2010 (Map 2). Anomaly "Hit A6" identified northwest of the Main Zone in 1998 showed a strong correlation with anomalous 2010 results (Map 2). A small visible gold occurrence was discovered at the location of strongest gold-in-soil values in this area. The actual Main Zone was not covered by the 1998 grid.

The 1998 grid was misplotted across most of its extent in the 1998 Hudson Bay report. The verification of results was possible only when the true field locations were determined.

Several samples from the Green Zone returning gold values from 1 to 10 grams from fire assay analysis were re-assayed by gravimetric analysis. Of 11 Green Zone samples, 10 showed a strong correlation, indicating a high degree of sample repeatability. A single sample, RI480068, returned a significantly higher value of 3.047 g/t Au from gravimetric analysis, compared with one of 2.005 g/t Au from fire assay analysis. Samples having gold contents exceeding 10.0 g/t were automatically re-analyzed by gravimetric analysis; no correlation could be made to fire assay results.

The metallic screen fire assay (MSFA) analysis revealed a high degree of variance between the original analysis and the larger screened samples. In most, although not all cases, the MSFA value exceeded the earlier value, to a maximum increase of 27% from a 1.1-metre chip sample returning 1.013.54 g/t Au from the MSFA sample versus 795.917 g/t from the "original" sample. Data analysis of surface sampling indicates the "plus fraction" returned much higher gold values than the finer fraction, ranging from 20 to 150 x the fine fraction value.

12.0 Adjacent Properties

The Sprogge property consisting of the SPROGGE 1-72 claims was held by Alexco Resource Corporation as of August 20, 2010. The property hosts a combination of orogenic and intrusion-related auriferous lode showings, some of which may have a partial origin from both settings. The most notable showings are: the "Meadows Zone" consisting of arsenical quartz veining within a phyllitic host and returning values from chip sampling to 6.9 g/t Au across 12.0m; the "Ridge Zone", a large occurrence consisting of fracture controlled quartz vein and stockwork mineralization returning values to 1.09 g/t Au across 4.0m and abundant gold-in-soil values exceeding 1.0 g/t; and the Sheila/ Swagman zone returning values to 9.55 g/t across 4.0m. Significant gold mineralization was first discovered in 1996; the property underwent several exploration stages through 1999 followed by a four-hole, 776-metre diamond drilling program targeting the Meadows Zone and areas directly north of the Ridge Zone. No significant

mineralized intercepts were returned. The property has since been optioned by Northern Tiger Resources.

A second “Sprogge” property, formerly called the “Justin” property, is located roughly nine kilometres southeast of the aforementioned Sprogge property. This property, held by Eagle Plains Resources Inc, was staked in 1995 to cover several intrusion-related skarn, replacement-style and epithermal vein-style occurrences. The property was incorporated into a contiguous claim block with the western Sprogge block in 1997 by Viceroy Resource Corporation, although the holdings between the two blocks were allowed to lapse by early 2010. The lapsed claims were restaked by Valley High Ventures late in 2010 following the summer exploration program. The Sprogge (Justin) property was optioned by Aben Resources Ltd early in 2011.

Several small claim blocks have been staked adjacent or proximal to the south boundary of the 3Ace property: the TRACEY 1-12 claims held by A. Black; the VICTOR 1-12 claims held by T. Charlie; and the WADE 1-20 claims held by F. Charlie. The VG 1-16 claims, held by M. Specogna extend along the Nahanni Range Road directly south of the 3Ace block. Similarly, the AU 1-6 claims extend along the Nahanni Range Road directly north of the 3Ace block.

13.0 Mineral Processing and Metallogenic Testing

No mineral processing or metallogenic testing is known to have been done on the Phil property.

14.0 Mineral Resource and Mineral Reserve Estimates

No mineral resource or reserve estimates compliant with current resource standards under National Instrument 43-101 have been calculated.

15.0 Other Relevant Data and Information

In June 1996 Westmin Resources Ltd staked the FER 1-76 claims centered about 20 kilometres northwest of the Green Zone. In September 1996 the Phelps Dodge Corporation of Canada Ltd. staked the HY 1-76 claims, tying on to the northwest boundary of the FER claims. Exploration in 1997 and 1998 identified several soil anomalies with gold values locally exceeding 1.0 g/t gold; rock sampling returned values to 9.9 g/t Au from arsenical quartz veining. Mineralogical descriptions in the Yukon Minfile suggest the mineralized setting is similar to that of the 3Ace property. The former FER-HY claims have been restaked as the HY and REEF claims by Archer Cathro & Associates (1981) Ltd. Valley High Ventures tied the JAY 1-258 claim block on to the northwest side of the HY-REEF claims. The combined block is not contiguous with the 3Ace property.

16.0 Discussion and Conclusion

16.1 Discussion

The following section, provided by Chris Buchanan in his 2010 summary report, forms an excellent overview on the structural settings of the major mineralized zones and the overall property-wide setting of mineralization:

"Gold mineralization on the 3Ace Property is hosted in three distinct structural settings: laminated quartz veins which formed as fault-fill veins in late brittle-ductile fault zones, quartz vein stockwork zones controlled by pre-existing fracture sets and east-southeast trending cross-faults in the quartz pebble conglomerate beds of the Yusezyu Formation, and disseminated arsenopyrite in reactivated D_1 thrust faults.

"The quartz veins are typically laminated crack-seal style veins that are comprised of milky white quartz. The crack-seal laminations and sharp wall-rock contacts indicate syntaxial vein growth, particularly at the Main Zone. Spalled wall-rock fragments occur in the veins, suggesting that locally, antitaxial mode vein growth occurred. The accessory mineralogy of the quartz veins at the Main, North and Sleeping Giant zones typically consists only of pyrite+arsenopyrite+iron carbonate+minor white clay±gold. Limonite and scorodite commonly overprint the quartz veins, but are associated with oxidation of Fe-bearing minerals and arsenopyrite by surficial water. Native gold forms in vugs, flakes in microfractures, distributed along slickengrooves, and is also associated with arsenopyrite grains. Wall rock alteration is limited to narrow envelopes around the veins, but is locally more extensive within fault zones (e.g., pervasive clay alteration of wall rocks at the Main Zone).

"The vein textures, mode of formation, alteration assemblages, and style of deformation indicate that veins formed as part of a structurally controlled, high-crustal level mesozonal vein system. This interpretation of the field relationships is supported by the homogenization temperature of fluid inclusions, which range from about 230^{o} to 300^{o}C, and phase separation of H_2O and CO_2 in individual inclusions (J. Conliffe, Memorial University, P.Comm). The phase separation of fluid components is the result of repeated pressure fluctuations within the fault zones during progressive deformation, promoting the deposition of gold (Cox, 1995; Wilkinson, 1996).

"In contrast to the narrow, rock-dominated alteration vein systems, mineralization and alteration at the Green Zone is suggestive of much higher fluid flux. Mineralization at the Green Zone consists of pyrite + arsenopyrite disseminated throughout broad zones of clay altered, brecciated quartz pebble conglomerate (C. Schulze, P.Comm). The distinctive green colouration of the conglomerate at this showing is caused by abundant scorodite formed from weathered arsenopyrite in the outcrop exposures. The alteration system at the Green Zone is significantly larger than the systems observed at the other showings. However, fluid flow and the distribution of alteration at the Green Zone are interpreted to be controlled by the geometry of the intersection between competent stratigraphy, reactivated D_1 thrust faults, and north-trending brittle-ductile fault zones" (Buchanan, 2010).

16.1.1 Main Zone

The Main Zone has been determined to occur as a shear-hosted vein zone striking at 340^{o} and dipping at -50^{o} to the east. The vein zone commonly occurs as a set of several veins, of which the vein directly along the main basal shear zone typically hosts the highest gold values. The base of the vein set, forming the footwall side, is a unit of strongly sheared graphitic phyllite a few metres in thickness and underlain in turn by coarse clastic sediments. This setting is seen at the Discovery Outcrop, where the vein is exposed for 7 metres long strike and averages about 1.0 metres in width. Here, the vein is hosted by quartz-pebble conglomerate, which has also undergone moderate to strong silicification and lesser centimetre-scale quartz veining, and bounded along the footwall side by sheared phyllite. Farther west, the hanging wall side inter-vein segments consists most of quartz-pebble conglomerate, with strongly auriferous phyllite grading 28.924 g/t Au across 0.3m, directly along the hanging wall side of the southernmost vein segments.

At the Discovery outcrop, abundant and locally spectacular visible gold is most pronounced along the hanging wall side of the vein, where it locally forms much of the slickenside fabric. Buchanan states that movement is dextral-normal, and that fault displacement and gold emplacement are coeval (Buchanan, 2010). Lesser, although still abundant visible gold, occurs throughout the rest of the Discovery Outcrop vein. Anomalous gold values were also returned from the hanging wall quartz-pebble conglomerate, typically in potentially recoverable amounts. Significant gold values also occur in the graphitic phyllite footwall, although metallurgical studies are recommended to determine whether the graphite may inhibit gold recoveries. The graphitic phyllite may form a favourable target for Induced Polarization “resistivity” surveying. Anomalous gold values were returned from the coarse clastic sediments underlying the footwall phyllite unit.

Hand trenching also revealed the presence of at least two en-echelon fault segments with individual strike lengths of five to seven metres with “stepovers” of 3-4 metres (Buchanan, 2010), directly west of the Discovery outcrop. These result in a southward displacement of the vein, although Buchanan has interpreted a dextral displacement along north-trending fault traces. Analysis of the detailed grid soil sampling, combined with the location of the western outcrop, suggests the presence of further similar faulting, but also suggest continuity of the vein at least 25 metres to the south and an undetermined distance to the north. Gold values decrease somewhat from the spectacular levels at the Discovery outcrop to the 30-gram range both at the northern outcrop and from drilled intercepts in its vicinity. However, a 15-centimetre float boulder coincident with a high gold-in-soil value 20 metres northwest of the detailed grid returned a value of 150.85 g/t Au, suggesting values may again increase with northing.

The metallic screen fire assay (MSFA) analysis revealed a high degree of variance between the original analysis and the larger screened samples. In most, although not all cases, the MSFA value exceeded the earlier value, to a maximum increase of 27% from a 1.1-metre chip sample returning 1.013.54 g/t Au from the MSFA sample versus 795.917 g/t from the “original” sample. This indicates that most of the gold occurs as coarse gold, in nugget form; the high degree of

variability results from unequal distribution of gold within a sample, rather than poor analytical techniques.

Although the extremely high gold values at the Discovery outcrop are likely anomalous compared to the rest of the Main Zone, average values throughout the Main Zone, excluding gold- deficient areas, appear to be consistently in the ounce-plus range. The Main Zone forms a favourable target for development of a small high-grade gold deposit.

16.1.2 Sleeping Giant Zone

The Sleeping Giant Zone occurs as a series of northeast-trending lenticular bodies along a corridor striking at about 340^{o}. C. Buchanan has interpreted this as coeval with the Main Zone. Mineralization occurs as fracture-controlled and clotty arsenopyrite, fairly uniformly distributed throughout the entire zone and comprising up to 4% of the rock mass. Chip sampling revealed two areas of high grade gold mineralization towards the southern end and at the central portion of the zone respectively. Low to background values were returned elsewhere from chip sampling, with the exception of a 2.0-metre chip sample returning 5.359 g/t gold and a separate 1.2-metre sample returning 1.261 g/t Au, both from the “420” portion towards the northern end of the Sleeping Giant Zone.

The high gold: silver ratios, similar to those of the Main Zone, support C. Buchanan’s findings that the two veins are coeval and share a common origin. Three samples assayed by MSFA analysis indicate a very high ratio of “plus-fraction” to “minus-fraction” gold values, from 55:1 to 116:1, roughly equivalent to that of the Main Zone. The variance from fire assay values is very strong, ranging from a 16% increase to 56% reduction of values returned from MSFA analysis. This suggests that the arsenopyrite grains likely hold a small amount of refractory gold, and that higher grades result from coarse gold enrichment, likely as late coatings on the arsenopyrite grains. This enrichment becomes progressively more pronounced towards the south, and may increase farther south, beyond the known limit of surface exposure.

Towards the south end, the Sleeping Giant Vein contained abundant small phyllite fragments, despite a local coarse clastic host rock. This suggests incorporation and transportation of phyllite fragments from elsewhere along the fluid path. These fragments form nuclei for arsenopyrite accretion which, at one location, in turn hosts late accretional visible gold.

16.1.3: Green Zone

As stated by C. Buchanan (2010) the Green Zone likely occurs along an east-west trending, south dipping D_1 thrust fault that “bends” west-northwest from the western portion of the Green Zone (Maps 1a, 1b, 2). This likely correlates with the thrust-fault associated quartz veining and brecciated quartz-pebble conglomerate occurrence about four kilometres to the northwest. The thrust fault area is typified by silicified, scoroditic and arsenical quartz-pebble conglomerate with abundant quartz veining, both barren and arsenical. The area lacks large discrete quartz veins as seen at the Main and Sleeping Giant zones. Alteration is more pervasive in the Green Zone area

than the Green Mile portion; at the latter, mineralization more typically occurs as quartz-arsenopyrite veins in the 1 to 10-centimetre range.

The mineralogy of the Green Zone differs significantly from that of the Main and Sleeping Giant zones. Silver: gold ratios are much higher; Ag: Au ratios range from 3:1 to 30:1. Samples are typically strongly arsenical; however lead (Pb) values exceeding 1.0% are common and antimony (Sb) values are much higher than at the other zones. Although no samples were reanalyzed by MSFA techniques, numerous samples were re-analyzed by gravimetric analysis, producing highly repeatable results, typically within 10% variance of the original value. This suggests a fairly minimal coarse gold effect.

The highest mineral potential occurs with a 450-metre section of the Green Zone, centred on, but not limited to, the east-west trends of strongly scoroditic mineralization. One of the holes drilled during the 1999 Hudson Bay program was collared about 200 metres north of these trends, but drilled at an azimuth roughly paralleling them. This hole returned a 1.5-metre intercept grading 1.140 g/t Au from "subarkosic wacke to fine conglomerate" (M. Buchanan, 1999). Somewhat farther downhole, a second 1.5-metre intercept of fine siltstone to shale returned 4.506 g/t Au; this fine grained unit is sandwiched between overlying and underlying coarse clastic strata. The balance of the hole returned low to background gold values from predominantly coarse clastic sediments; the hole did not extend to the strongly altered east-west trending horizons identified in 2010. Potential elsewhere along the Green Zone and throughout the Green Mile appears more limited, although high gold values in a single rock sample at the western extreme of the Green Zone warrants further exploration.

The soil sampling survey returned values consistently exceeding 0.100 g/t Au. However, these were taken largely from areas of talus and rubblecrop, with poor, if any, soil development. This type of setting requires high gold values exceeding 0.300 g/t gold to signify the presence of potentially significant auriferous zones, suggesting the central Green Zone area and the north-south trending zone, indicated by the gram-plus gold-in-soil values north of this, represent the areas of highest potential within the Green Zone. Some potential also exists along the strike extent of the narrow fine clastic unit intersected in the 1999 drilling by Hudson Bay.

The thrust fault controlling the Green Zone likely represents a significant displacement between the hanging wall and footwall sides, represented by the change in lithology along the north, footwall side. Although surface exploration by Northern Tiger Resources was limited, fairly abundant previous exploration has taken place, particularly in the late 1990s. To date, no significant mineral occurrences or strong geochemical anomalies have been identified north of the Green Zone fault line.

16.1.4 North Zone

The North Zone received the least attention during the 2010 program; however, fairly abundant rock chip sampling suggests the auriferous portion is of limited extent, confined to quartz-arsenopyrite veining traced for several metres at a northeast orientation. The mineralogy, including gold: silver and gold: arsenopyrite ratios, is consistent with that of the Main and

Sleeping Giant zones, suggesting the three are coeval. The large area of quartz flooding and veining directly east is deficient in gold, suggesting a separate emplacement history, with the exception of a north trending zone of sheeted veining and clotty arsenopyrite of uncertain temporal history. A single 1999 drill hole collared and directed downslope of the main area of quartz flooding failed to intersect significant gold values. This suggests limited potential for sizable mineralized zones within the North Zone area.

16.1.5 Other Discussion

Hart and Lewis (2005) hypothesized that gold in the area hosting the 3Ace property is of orogenic origin, originating from low temperature fluids migrating along deep north-south trending crustal faults. Initial fluid inclusion studies suggest low salinities and a temperature of emplacement ranging from about 230^{o}C at the Sleeping Giant Zone to 300^{o}C at the Main and Green Zones. Fluids were likely metamorphic crustal fluids, rather than intrusion-related (Conliffe, 2010).

The orogenic origin of gold-bearing fluids is further supported by the lack of any intrusion-related features, with the exception of the (Justin) Sprogge property about 20 kilometres to the east, where mineralization is at least partially intrusion-related. Mineralized occurrences are proximal to, and always to the west of, the north-northwest trending March Fault, which forms the area's dominant structural feature. The fault, which displays normal, thrust and strike-slip characteristics, has been active during Neoproterozoic and Cretaceous time (Hart and Lewis, 2005). Hart and Lewis's suggestion that north-south trending structures form the primary structural orientation for emplacement is substantiated by the orientation of the Main and Sleeping Giant zones.

16.2 Conclusions

The following conclusions may be made from the 2010 exploration programs on the 3Ace property:

- The program's findings support the hypothesis by Hart and Lewis that mineralization at the 3Ace property has an orogenic origin. The proximity to the March Fault, interpreted as a deep, crustal feature; the northward orientation of the Main and Sleeping Giant Zones, and the lack of intrusion-related features form the basis for this hypothesis.

- Mineralization to date occurs primarily within coarse clastic sediments, due to their permeability and tendency to result in quartz vein emplacement. However, the 2010 program indicated that gold may also occur in fine grained black shale to phyllite.

- The Main and Sleeping Giant zones share a common mineralogy, with sulphide minerals consisting primarily of arsenopyrite with minor pyrite. In both zones, gold: silver ratios are very high, with weakly elevated values of lead and antimony. The zones are likely coeval.

- The Main Zone occurs as very strongly auriferous quartz veining within a north-south trending, steeply east-dipping fault zone up to 27 metres wide, bound on the hanging wall side by altered and weakly to moderately auriferous quartz-pebble conglomerate and lesser phyllite, and along the immediate footwall side by a narrow unit of sheared, graphitic phyllite. Significant gold values have been returned from both sides of the auriferous vein.

- The Main Zone has undergone faulting, disrupting the zone into segments of 7-8 metres, with "stepovers" (displacement) of 3-4 metres. These consist of a right-lateral displacement along north-trending fault traces. However, the zone may otherwise be considered as a fairly linear structure, as vein widths remain fairly constant.

- Soil geochemical surveying suggests the Main Zone extends at least 25 metres farther to the south and at least 50 metres to the north, where it remains open-ended. Gold grades decrease northward from the Discovery outcrop, although remain in the ounce-plus range. A small boulder, likely talus float, discovered north of the detailed grid returned higher values, suggesting grades may increase farther north.

- A strong "coarse gold effect" exists at the Main Zone. Metallic Screen Fire Assay (MSFA) analysis revealed that gold content of the coarse fraction ranges from 20 to > 150 times that of the fine fraction. In the majority of samples analyzed both by fire assay/ gravimetric analysis and by MSFA, higher values were returned from the latter, largely because of improved accuracy due to larger sample size.

- The Main Zone forms a favourable target for development of a low-tonnage, high grade gold deposit. The proximity of the property to road access and fairly extensive lowland areas amenable to infrastructure development support this.

- The Sleeping Giant Zone has been interpreted to date as a north-northwest trending corridor about 220 metres long consisting of large en-echelon lenticular quartz-arsenopyrite bodies. On surface this appears as a large quartz vein up to 25 metres wide.

- Surface chip sampling revealed two areas of high-grade gold mineralization in the southern end and central portions of this zone. Visible gold, as accretions on arsenopyrite grains, occurs at two locations at the former and one at the latter.

- The Green Zone/ Green Mile trend, extending east-west roughly 2.0 kilometres north of the Main Zone, has been interpreted as occurring along a south-dipping thrust fault, with a substantial displacement between the southern hanging wall and northern, footwall side.

- The Green Zone represents an area of much higher fluid flux, with lower gold values up to about 7.0 g/t, and much higher silver: gold ratios (silver may represent an important commodity here). High gold values are associated with high arsenic and antimony values, and very high lead values. Mineralization occurs as small arsenical – scoroditic

quartz veins and strongly silicified, altered and mineralized coarse clastic sediments, rather than as larger quartz veins.

- The most prospective area of the Green Zone occurs along a 450-metre east-west trending corridor of arsenical and scoroditic mineralization, locally associated with brecciated coarse clastic sediments. The strongest gold-in-soil values were returned downslope of the eastern portion of this corridor, and from a north-south trending mineralized horizon to the north.

- Drilling in 1999 north of this corridor returned a 1.5-metre interval grading 4.5 g/t Au from a unit of siltstone to shale between coarse clastic units. This, combined with high gold values from narrow phyllite horizons at the Main Zone, suggests that fine sediments may also form a prospective host for gold mineralization.

- Although more cursory exploration took place along the Green Mile section east of the Green Zone, fairly abundant rock sampling returned lower gold values in the Green Mile. Mineralization occurs within small quartz-arsenopyrite veins with lesser wallrock alteration. This, combined with very steep, rocky terrain, suggests the Green Mile forms a less viable target than the Green Zone.

- The North Zone has a similar mineralogy to the Main and Sleeping Giant Zones, including local visible gold associated with arsenopyrite, suggesting it is coeval with these zones. However, it has a northeast-southwest orientation, and is subvertical.

- The North Zone is likely to have limited strike extent. A sizable area of white quartz veining and quartz flooding directly to the east returned low gold values.

- Other prospective areas include the Hoito Zone, consisting of a 5-metre wide auriferous quartz vein southeast of the Green Zone, and several strong gold-in-soil anomalies identified from the main soil geochemical survey. To date, no significant mineralized occurrences have been identified north of the Green Zone.

17.0 Recommendations

17.1 Recommendations

The 2011 program on the Main Zone is recommended to consist of an early phase of detailed geochemical sampling at the same line and station spacing as the detailed survey across the Discovery outcrop and extending well beyond the 2010 extent. Induced Polarization resistivity surveying, with lines oriented east-west, is also recommended, due to the graphitic nature of the sheared phyllite along the footwall side of the zone. Results should be utilized to determine the full extent of the Main Zone structure, and to conduct follow-up rock sampling at sites of high gold-in-soil values. These in turn can be utilized to determine locations of a follow-up Phase 2 diamond drilling program of 2,500 metres in 15 – 20 holes, with the objective of building an Inferred Resource as determined by standards under National Instrument 43-101.

The program on the Sleeping Giant zone is recommended to commence with an early detailed soil geochemical program, partially as due diligence on results of the 1998 Hudson Bay geochemical program, and partially to determine areas of potential high grade gold mineralization. Detailed chip sampling is recommended for the surface quartz exposures, to determine extent of mineralization. Line cutting, with lines oriented east-west, followed by Induced Polarization surveying (chargeability and resistivity) is strongly recommended to determine the setting of the quartz bodies. The surveys should be extended south of the known extent, as grades and coarse gold content increase towards the south end, and may extend farther south.

A second phase of diamond drilling following adequate compilation of results is recommended for the Sleeping Giant Zone. The 2011 drilling program should not exceed 1,500 metres in 10-12 holes. Re-analysis, including MSFA analysis, of pulps and rejects of the high grade samples from 2010 surface sampling is also recommended as a due-diligence exercise.

The Green Zone area underwent the most comprehensive geological mapping, rock sampling and systematic soil geochemical surveying of the 2010 program, delineating the most prospective east-west trending mineralized zone. Induced Polarization chargeability and resistivity surveying, with lines oriented north-northeast (parallel to the 2010 geochemical survey lines) is recommended to determine down-dip extent of the zones. Surveying should extend across the 1999 Hudson Bay drill hole. Results should be used to determine drill targets for the Phase 2 program, of roughly 2,000-metres in 12-15 holes. This area is quite rugged, consisting of rubblecrop, talus and local outcrop, with the exception of a plateau north of the eastern portion of the Green Zone. Pad building will require skilled personnel and will be expensive.

The drilling program is recommended to be heli-supported, due to rugged, blocky terrain at the Green Zone and steep slopes separating the Main and Sleeping Giant Zones. Projected Phase 1 expenditures stand at CDN$284,140; with 15% contingency this figure stands at $326,761. Phase 2 expenditures stand at $2,383,913; with 15% contingency this figure stands at $2,759,391. Phase 1 exploration may commence on or around June 15th, with line cutting commencing somewhat earlier; drilling should commence by late July.

17.2 Recommended Budget: Phase 1

Wages: Project Geologist: 36 days (incl pre-program) @ $640/day:		$ 23,040
Wages: 2nd Geologist: 32 Days @ $600/day:		$ 19,200
Wages: 3rd Geologist: 32 Days @ $500/day:		$ 16,000
Wages: Technician 1: 32 Days @ $375/day:		$ 12,000
Wages: Technician 2: 32 Days @ $350/day:		$ 11,200
Wages: Technician 3: 32 Days @ $300/day:		$ 9,600
Wages: Cook: 29 Days @ $350/day:		$ 10,150
Rock Sampling: 462 samples @ $35/sample:		$ 16,170
Soil/ Silt Samples: 660 @ $32/sample:		$ 21,120
Shipping: 1,122 samples @ $2/sample:		$ 2,240
Helicopter: 39.6 hrs @ $1,200/hr, incl. fuel:		$ 47,520
Line Cutting: 20 km @ $1,200/km:		$ 24,000
Induced Polarization: 20 km @ $1,800/km:		$ 36,000
Truck mileage: 2,800 km @ $0.55/km:		$ 1,540
Per Diems: 18 person-days @ $75/day:		$ 1,350
Travel Fuel:		$ 1,000
Groceries: 203 person-days @ $50/day:		$ 10,150
Accommodations: 18 person-days @ $150/day:		$ 2,700
Travel Expenses:		$ 1,500
Expediting:		$ 4,000
Gear Rental: 29 Days @ $50/day:		$ 1,450
Field Office Supplies:		$ 350
Equipment, incl. Expendables:		$ 600
	Field Expenditures:	**$272,880**
Digitization:		$ 2,500
Report Writing, incl. IP Report:		$ 8,760
	Project Expenditures:	**$284,140**
	15% Contingency:	$ 42,621
	Total Proposed Expenditures:	**$326,761**

17.3 Recommended Budget: Phase 2

Wages: Project Geologist: 89 days (incl pre-program) @ $640/day:		$ 56,960
Wages: Core Loggers: 162 Person-Days @ $500/day:		$ 81,000
Wages: Technicians: 162 Person-Days @ $375/day:		$ 60.750
Wages: Samplers: 162 Person-Days @ $350/day:		$ 56,700
Wages: Camp Manager: 81 Days @ $500/day:		$ 40,500
Wages: Cook: 81 Days @ $437.50/day:		$ 35,438
Wages: Cook: 81 Days @ $325/day:		$ 26,325
Pad Building:		$ 62,000
Surveying:		$ 5,000
Per Diems: 32 person-days @ $75/day:		$ 2,400
Drilling: 6,000m @ $175/m, all-in:		$1,050,000
Mobe-Demob:		$ 18,000
Drill Equipment Rental: 75 Days @ $50/day:		$ 3,750
Helicopter: 243 hours @ $1,200/hr:		$ 291,600
Pad preparation supplies:		$ 12,000
Tests:		$ 6,000
Drill survey tool rental:		$ 8,000
Samples: 4,720 @ $35/sample:		$ 165,200
MSFA Samples: 56 samples @ $80/sample:		$ 4,480
Shipping: 4,720 samples @ $2/sample:		$ 9,440
Standards:		$ 1,500
Groceries: 1,423 person-days @ $50/day:		$ 71,150
Accommodations: 32 person-days @ $150/day:		$ 4,800
Expediting:		$ 19,200
Camp Fuel:		$ 52,500
Drilling Fuel, incl. pump:		$ 144,160
Gasoline:		$ 1,050
Propane:		$ 5,000
Gear Purchase:		$ 50,000
Generator Rental: 2.5 mo @ $2,000/mo:		$ 5,000
Camp wiring:		$ 3,500
Mileage: 4,200 km @ $0.55/km:		$ 2,310
Satellite Dish rental: 2.5 mo @ $2,500/mo:		$ 6,250
Travel Fuel:		$ 800
Travel Meals:		$ 450
Travel Expenses:		$ 2,500
Office supplies:		$ 1,200
Lumber (mostly drill pads):		$ 6,000
Supplies (incl. expendables):		$ 2,000
Core boxes: 600 boxes @ $15/box:		$ 9,000
	Field Total:	**$2,383,913**
Digitizing:		$ 5,000
Report writing, data compilation:		$ 10,540
	Sub-Total:	**$2,399,453**
	15% Contingency:	$ 359,918
	Project Total:	**$2,759,391**

17.0 References

17.1 References, C. Schulze, All-Terrane Services

Bidwell, G, and Schulze, C, 1996: "Sprogge Property, 1996 Exploration Program, Watson Lake Mining Division", Assessment Report #093586 for Battle Mountain Canada Ltd. Filed with Watson Lake Mining Recorder, Dept. of Energy Mines and Resources, Government of Yukon.

Buchanan, M.D. 1999: "Assessment Report, Geochemical Survey, Hit Property", Assessment Report "093075", for: Hudson Bay Exploration and Development Co. Ltd. Assessment Report, filed with Watson Lake Mining Recorder, Dept. of Energy Mines and Resources, Government of Yukon.

Buchanan, M.D. 2000: "Assessment Report, 3Ace Property, Geochemical Survey". Assessment Report #090477 for: Hudson Bay Exploration and Development Co. Ltd. Assessment Report, filed with Watson Lake Mining Recorder, Dept. of Energy Mines and Resources, Government of Yukon.

Buchanan, M.D. 2000: "Assessment Report, Diamond Drilling, Hit Property"; Assessment Report #094112 for: Hudson Bay Exploration and Development Co. Ltd. Assessment Report, filed with Watson Lake Mining Recorder, Dept. of Energy Mines and Resources, Government of Yukon.

Buchanan, M.D. 2000: "Assessment Report, Geochemical Survey, Hat property". Assessment Report #094114 for: Hudson Bay Exploration and Development Co. Ltd. Assessment Report, filed with Watson Lake Mining Recorder, Dept. of Energy Mines and Resources, Government of Yukon.

Hart, C. and Lewis, L, 2005: "Gold Mineralization in the Upper Hyland River area: A non-magmatic origin", In: Yukon Exploration and Geology, 2005, Ed. D.S. Edmond, G.D. Bradshaw, L.L. Lewis and L.H. Weston, Yukon Geology Survey, Energy, Mines and Resources, Government of Yukon, pp. 109 – 125.

McMillan, L. 2005: "2003 – 2004 Assessment Report; Results of Prospecting and Geochemical Sampling For the 3Ace Property"; Assessment Report, for Alex McMillan Exploration, filed with Watson Lake Mining Recorder, Dept. of Energy Mines and Resources, Government of Yukon.

McMillan, L. 2001: 3Ace Target Analysis Program, YMIP 01-017, "Results of Geochemical Surveying and Rock Sampling", Assessment Report 094318, For: Alex McMillan Exploration, filed with Watson Lake Mining Recorder, Dept. of Energy Mines and Resources, Government of Yukon.

Northern Tiger Resources Inc, 2010: Website, updated as of November, 2010.

Schulze, C, 1997: 1997 Geological, Geochemical and Trenching Report on the Sprogge 1-74 and Justin 1-25 Claims", Assessment Report 093783 for Battle Mountain Canada Ltd. Assessment Report, filed with Watson Lake Mining Recorder, Dept. of Energy Mines and Resources, Government of Yukon.

Tessier, A, and Fonseca, A, 1999: Hab/ Hat Geology Map, part of Assessment Report #094113, for Hudson Bay Exploration and Development Co. Ltd. Filed with the Watson Lake Mining Recorder, Dept. of Energy Mines and Resources, Government of Yukon.

Yukon Geology Survey, 2010: Yukon "Minfile", Yukon Geology Program, Dept. of Energy Mines and Resources, Government of Yukon.

17.2 References, Buchanan Geoscience Services

Buchanan, M., 2000, Assessment Report: Geochemical Survey, Hat Property: Hudson Bay Exploration and Development Corporation Limited, Yukon Geological Survey.

Buchanan, M., 1999, Assessment Report: Geochemical Survey, Hit Property: Hudson Bay Exploration and Development Corporation Limited, Yukon Geological Survey.

Cox, F.S., 1995, Faulting processes at high fluid pressures: An example of fault valve behaviour from the Wattle Gully Fault, Victoria, Australia: Journal of Geophysical Reasearch, v. 100, p. 12841-12859.

Gordey, S., and Anderson, R., 1993, Evolution of the Northern Cordilleran Migoecline, Nahanni Map Area (105I), Yukon and Northwest Territories: Geological Survey of Canada.

Mitra, S., 2002, Fold-accomodation faults: AAPG Bulletin, v. 86, no. 4, p. 671-693.

Peters, S.G., 1993, Formation of oreshoots in mesothermal gold-quartz vein deposits: examples from Queensland, Australia: Ore Geology Reviews, v. 8, no. 3-4, p. 277-301.

Wilkinson, J.J., 1996, Pressure fluctuations, phase separation, and gold precipitation during seismic fracture propagation.: Geology [Boulder], v. 24, no. 5, p. 395 - 398.

Appendix 1a. Certificate of Author

I, Carl M. Schulze, PGeo, hereby certify that:

1) I am a self-employed Consulting Geologist and sole proprietor of:
All-Terrane Mineral Exploration Services
35 Dawson Rd
Whitehorse, Yukon Y1A 5T6

2) I graduated with a Bachelor of Science Degree in geology from Lakehead University, Thunder Bay, Ontario, in 1984.

3) I am a member in good standing of the Association of Professional Engineers and Geoscientists of British Columbia (APEGBC).

4) I have worked as a geologist for a total of 27 years since my graduation from Lakehead University.

5) I have read the definition of "qualified person" set out in National Instrument 43-101 ("NI 43-101") and certify that by reason of my education, affiliation with a professional association (as defined in NI 43-101) and past relevant work experience, I fulfill the requirements to be a "qualified person" for the purposes of NI 43-101.

6) I am responsible for preparation of all sections of the preliminary report titled "Assessment Report on the 2010 Geological and Geochemical Programs on the 3ACE Property, Southeast Yukon, Northern Tiger Resources Inc." on the entire property area comprising the 3Ace Project. I was active on-site during the entire surface program of 49 days from July 3 to August 20, 2010.

7) I have not had prior involvement with the properties that are the subject of the Preliminary Report prior to July 2010.

8) I am independent of the issuers applying all of the tests in section 1.4 of National Instrument 43-101.

10) I have read National Instrument 43-101 and Form 43-101F1, and the Technical Report has been prepared in compliance with that instrument and form. It is to be filed as an Assessment Report and has some additional data required thereof.

10) I consent to the public filing of the Assessment Report with the Yukon Mining Recorder, Ministry of Energy, Mines and Resources, Government of Yukon.

11) The effective date of this report is Nov 26, 2010.

Dated this 11th Day of February, 2011

"Carl Schulze"

Carl Schulze, BSc, PGeo
Address: 35 Dawson Rd
Whitehorse, Yukon Y1A 5T6
Telephone: 867-633-4807
Fax: 867-633-4883
E-mail: allterrane@northwestel.net

Statement of Qualifications, Chris R. Buchanan

I Chris R. Buchanan, M.Sc., P.Geo., hereby certify that:

1. I am currently a self-employed Consulting Geologist residing at:

   10 Prospero Place
   St. John's, NL
   A1B 3W7

2. I graduated with an Honours Bachelor of Science, co-op degree in Geology from the University of Waterloo, Waterloo, Ontario, in 1996. I obtained a Master of Science degree in Geology from Memorial University of Newfoundland, St. John's, Newfoundland and Labrador, in 2004.

3. I am registered with the following professional organizations:

   Professional Geoscientist with the Professional Engineers and Geologists of Newfoundland and Labrador (PEGNL) since 2006, member number 04608.

4. I have worked as a Professional Geoscientist since graduation with an Honours Bachelor of Science, co-op degree from the University of Waterloo, including defending research for a Master of Science degree from Memorial University of Newfoundland in 2004.

5. I have read the definition of "qualified person" set out in National Instrument 43-101 (NI 43-101) and certify by reason of my education, work experience and registration with PEGNL that I fulfill the requirements to be a "qualified person" for the purposes of NI 43-101.

6. I am responsible for the preparation, in part, of the technical report titled "Preliminary Report on the 2010 Geological, Geochemical and Diamond Drilling Programs on the 3ACE Property, Southeast Yukon". The report, dated Dec 6, 2010 was prepared for Hewlett-Packard Company, relating to the mineral [Exploration License].

7. I do not have, nor do I expect to receive, directly or indirectly, any interest in the [Exploration Property Name], properties of Hewlett-Packard Company or any affiliated companies

Dated: [Publish Date]:

Appendix 1b: Statement of Expenditures

Time frame: July 20 – Aug 20, 2010

Type of Activity	No. of Units	Cost/unit	Total Cost
Wages, Proj. Geologist	32	$640/day	$ 20,480
Wages, Structural Geologist	32	$500/day	$ 16,000
Wages, Senior Technician	27	$375/day	$ 10,125
Wages, Technician	17	$375/day	$ 6,375
Wages, Technician	23	$225/day	$ 5,175
Wages, Prospector 1	15	$350/day	$ 5,250
Wages, Prospector 2	15	$350/day	$ 5,250
Wages, Cook:	32	$350/day	$ 11,200
Helicopter:	30	$1,190/hr, incl fuel	$ 35,700
Rock samples:	345	$35/sample	$ 12,075
Soil/ Silt samples:	777	$32/sample	$ 24,864
Shipping/ Expediting			$ 3,312
Groceries and Camp Supplies	183	$50/person-day	$ 9,150
Digitization:			$ 3,000
Report Writing, Data Comp.	10	$640/day	$ 6,400
Totals:			**$174,356**

Appendix 2: Sample Descriptions

Appendix 2a: Rock Sample Descriptions
Appendix 2b: Soil Sample Descriptions
Appendix 2c: Silt Sample Descriptions

All-Terrane Mineral Exploration Services

ROCK SAMPLE DESCRIPTION SHEET

2010 Program, 3-ACE Project
Northern Tiger Resources Inc.

Main Zone
North Zone
Green Zone
West Ext, Green Zone
Sleeping Giant Zone
Hoito Zone
VG outside of major zone
Note: Darker shades indicate VG-bearing sample or higher-grade result

Sample No.	Easting	Northing	Sample	Width	Sample	Mineralized	Formation	Lithology	Modifier	Colour	Carb.	Silicification	Alteration	Alt 2	Other	Mineral	Amount	Min 2	Amt	Other	Amt	Date	Sampler	Comments
	UTM NAD 83	(UTM NAD 83)	Type	(m)	Description	Zone					Presence		1			1	(%)		(%)	Mineral	(%)			
R1480001	533647	6843816	Chip	0.5	Rcrop	Main	PrCh	QPC	Vein	Gr-white		S3			L2	Py	<1	As	tr			Jul-05	CS	Majority = Qz-arseno vein: QPC = Quartz-pebble cong
R1480002	533650	6843816	CGr		Rcrop	Main	PrCh	QPC	Vned	Tan		S2			L2	Py	tr					Jul-05	CS	30-40% fractured quartz veins
R1480003	533534	6844108	CGr		Rcrop		PrCh	QPC	Vned	grn-gry		S2	Ph2		L1	Py	2	As	1	Scor	mod	Jul-05	CS	Qz-scor veins, pyrite boxwork
R1480004	533636	6843877	Chip	0.9	Ocrop	Main	PrCh	Qz Vn	Foliated	gry-wh		S3				Py	tr	As	tr			Jul-05	CS	Incl. Some QPC; Arseno in wallrock
R1480005	533807	6844514	CGr		Rcrop		PrCh	QPC	Vned	bf-wh		S1	Ph1	A2	L1	Py	<1	As	<1			Jul-05	CS	Weak silica outside of quartz veins
R1480006	533699	6845001	Grab		Float		PrCh	QPC	Vned	grey		S2-3	Ph1	A2	L1	Py	2					Jul-05	CS	Large proximal (?) float
R1480007	533658	6843830	Chip	0.45	Ocrop	Main	PrCh	Qz Vn	Massive	buff					L1	As	tr					Jul-06	CS	Minor clots of As-rich material
R1480008	533657	6843828	Chip	0.6	Ocrop	Main	PrCh	QPC	Vned	grey		S2	Ph1	A2		Py	<1	As	tr			Jul-06	CS	Hanging wallrock to E
R1480009	533658	6843828	Chip	0.65	Ocrop	Main	PrCh	Qz Vn	Massive	white						As	tr					Jul-06	CS	Minor arsenical clots
R1480010	533659	6843826	Chip	0.9	Ocrop	Main	PrCh	QPC	Vned	grey		S1	Ph1-2	A2		As	tr	Py	1	Scor	tr	Jul-06	CS	Hanging wallrock; 15-20% Qz veins
R1480011	533658	6843826	Chip	0.9	Ocrop	Main	PrCh	Qz Vn	shear	white						VG	tr					Jul-06	CS	VG largely along slick adj. to hanging wall
R1480012	533658	6843825	Chip	0.2	Ocrop	Main	PrCh	QPC	shear	tan		S2	Ph1	A2		Py	<1	Scor	tr			Jul-06	CS	20% Qz veins; hanging wall
R1480013	533657	6843825	Chip	1.1	Ocrop	Main	PrCh	Qz Vn	fractured	white					L1	VG	tr	As	<1			Jul-06	CS	VG in vugs and with arseno
R1480014	533657	6843824	Chip	1.0	Ocrop	Main	PrCh	Qz Vn	fractured	wh-tan					L1	Py	tr					Jul-06	CS	Sulphide boxwork; includes sheeted fractures
R1480015	533657	6843826	Chip	1.2	Ocrop	Main	PrCh	Qz Vn	Massive	white						VG	tr					Jul-06	CS	Crosses crosscutting shear
R1480016	533658	6843814	Chip	1.0	Ocrop	Main	PrCh	Qz Vn	fractured	wh-tan												Jul-06	CS	2 pieces; poss. NE-SW trending vein?
R1480017	533643	6843825	Chip	1.3	Ocrop	Main	PrCh	QPC	Vned	grey		S2	A2	Ph2	L1	Py	<1					Jul-06	CS	10-15% quartz veins
R1480018	533632	6843816	Chip	1.3	Ocrop	Main	PrCh	QPC	Vned	gr-blue		S2	A3	Ph1	L1	Py	1	Scor	tr			Jul-06	CS	8-10% Qz veins, likely vfg pyrite
R1480019	533912	6844294	Chip	1.0	Ocrop	North	PrCh	QPC	Qz vn	white		S1	A2	Ph1	L1	As	tr					Jul-07	CS	30-40% QPC, weak nsilica
R1480020	533913	6844292	Chip	1.5	Ocrop	North	PrCh	Qz Vn	fractured	white					L1	VG	tr	As	1			Jul-07	CS	Clots of arseno, one with tr VG
R1480021	533914	6844291	Chip	1.5	Ocrop	North	PrCh	QPC	Vned	Beige-wh		S2	A3		L1	As	<1					Jul-07	CS	60% Qz veins in QPC
R1480022	533934	6844290	Chip	2.0	Oc/Rc	North	PrCh	Qz Vn	shear	white					L1	As	<1					Jul-07	CS	Locally clotty arseno
R1480023	533934	6844288	Chip	0.6	Rcrop	North	PrCh	Qz Vn	Massive	white												Jul-07	CS	Locally vuggy
R1480024	533943	6844285	Chip	0.8	Ocrop	North	PrCh	QPC	Vned	wh-tan		S3			L1	As	<1	Py	tr			Jul-07	CS	Includes late chalcedonic (?) veins
R1480025	533942	6844286	Chip	2.0	Ocrop	North	PrCh	QPC	Vned	buff		S1	A2		L1							Jul-07	CS	35% Qz +/- carb veins
R1480026	533944	6844285	Chip	2.0	Oc/Rc	North	PrCh	QPC	Vned	buff		S3	A2		L2	As	tr	Py	tr			Jul-07	CS	Qz veins +/- silicified QPC
R1480027	533946	6844283	Chip	2.0	Ocrop	North	PrCh	QPC	Vned	bf-gry		S2	A2		L1	As	tr	Py	tr			Jul-07	CS	Arseno in wallrock
R1480028	533947	6844282	Chip	2.0	Ocrop	North	PrCh	QPC	Vned	wh-buff		S1	A3		L1	As	tr	Py	tr			Jul-07	CS	40% Qz veins, including stringers
R1480029	533948	6844281	Chip	1.4	Ocrop	North	PrCh	Qz Vn	Massive	wh-buff		S1	A2	Ph1	L1	As	<1	Py	tr			Jul-07	CS	Approx 20% QPC; Arseno in certain portions
R1480030	533980	6844317	Chip	1.5	Ocrop	North	PrCh	QPC	Vned	wh-brn		S2	A1		L2	As	3					Jul-07	CS	Clotty (replacerment?) arseno, also As vein
R1480031	533980	6844319	Chip	1.3	Ocrop	North	PrCh	Sstone	Vned	grey	C1	S1	A1	Ph2	L1	As	>1					Jul-07	CS	Includes 5 cm phyllite; 15-20% veins
R1480032	533950	6844289	Chip	1.0	Ocrop	North	PrCh	QPC	Vned	bf-wh		S2	A2		L1	As	<1	Py	<1			Jul-07	CS	> 50% Qz veins
R1480033	531807	6850421	CGr		Talus		PrCh	Qz Vn	Vuggy	tan					L3	Py	<1	Ga	tr			Jul-08	CS	Locally abundant white quartz
R1480034	531812	6850394	SCGr		Talus		PrCh	Qz Vn	Vuggy	tan		S1		Ph2	L2	Cpy	<1	Py	2			Jul-08	CS	Includes QPC wallrock; vuggy sulphides
R1480035	529410	6851562	CGr		Ta/Rc		PrCh	QPC	Vned	beige	C2	S1	A1	Ph2	L1	Scor	tr					Jul-08	CS	Clotty limonitic alteration
R1480036	533506	6845815	Chip	1.8	Ocrop	Green	PrCh	QPC	shear	grn-bf		S2	A3	Ph2		As	1	Scor	mod	Py	tr	Jul-09	CS	Increasing breccia towards south end
R1480037	533510	6845810	CGr		Rcrop	Green	PrCh	QPC	Breccia	grn-wh		S1	A3	Ph1		As	tr	Scor	mod			Jul-09	CS	Strong sulphide boxwork
R1480038	533509	6845803	Chip	2.0	Rcrop	Green	PrCh	QPC	Vned	buff		S2	A2					Scor	wk			Jul-09	CS	20% Qz veins; "buff" colour likely scorodite
R1480039	533516	6845829	Chip	1.0	Ocrop	Green	PrCh	QPC	Vned	Grn/bge		S2	A2	Ph1		As	3	Scor	mod			Jul-09	CS	Arseno possibly favours N-S shear
R1480040	533375	6845808	CGr		Rcrop	Green	PrCh	QPC	Crse gr	buff		S2	A3	Ph1		As	tr	Scor	wk			Jul-09	CS	Scoroditic rubblecrop
R1480041	533384	6845869	CGr		Rcrop	Green	PrCh	Phy?	Breccia	Dk brn					L3							Jul-09	CS	5-10% Qz, strongly lim onitic
R1480042	533355	6845889	CGr		Rcrop	Green	PrCh	QPC	Breccia	grn-bf		S2	A3	Ph2		As	1	Scor	mod	Ga	tr	Jul-09	CS	Sheared Qz vns + brecciated, scoroditic QPC
R1480043	533361	6845888	CGr		Rcrop	Green	PrCh	SS/QPC	Breccia	Green		S2	A3	Ph1		As	<1	Scor	mod			Jul-09	CS	Fairly abundant float
R1480044	533129	6845917	CGr		Rcrop	Green	PrCh	QPC	Breccia	Green		S2-3	A3	Ph2		As	1	Scor	mod			Jul-09	CS	Likely along small shear
R1480045	532857	6846035	SCGr		Talus	Green	PrCh	QPC	shear	Green		S2	A1	Ph2		As		Scor	mod			Jul-09	CS	Scorodite along shear plane
R1480046	532857	6846035	SCGr		Talus	Green	PrCh	QPC	Breccia	brown		S1	A1		L3			Scor	wk			Jul-09	CS	Limonitic matrix; wk scorodite
R1480047	533044	6846260	CGr		Rcrop	Green	PrCh	QPC	Vned	Tan		S2-3	A2	Ph1	L1	As		Scor	wk			Jul-09	CS	Includes fine rubblecrop fragments, largely Qz Vns
R1480051	533102	6846228	SCGr		Talus	Green	PrCh	QPC	shear	green		S2	A1			As	2	Scor	mod			Jul-10	CS	Some fragments show weak shearing
R1480052	533081	6846232	Chip	1.4	Ocrop	Green	PrCh	QPC	shear	grn-tan		S2	A2	Ph2		As	tr	Scor	mod	Py	>1	Jul-10	CS	2 shear orientations; dissem pyrite
R1480053	532949	6846542	CGr		Talus	Green	PrCh	QPC	Foliated	Yel/tan		S2-3	A3	Ph2		As	tr	Scor	wk	Py	<1	Jul-10	CS	Fine frac-controlled pyrite
R1480054	532936	6846546	CGr		Talus	Green	PrCh	QPC	Crse gr	Yel/gry		S2	A3	Ph1		As	tr	Scor		Py	2	Jul-10	CS	3 pieces of proximal talus
R1480055	532825	6846576	Chip	2.0	Ocrop	Green	PrCh	QPC	shear	Tan		S1	A3	Ph1		Py	<1	Scor	wk			Jul-10	CS	Moderate sulphide boxwork
R1480056	532739	6846596	CGr		Ta/Rc	Green	PrCh	QPC	Vned	grn-bf		S2	A3	Ph2		Py	<1	Scor	wk			Jul-10	CS	Mod sulphide boxwork
R1480057	532996	6846087	CGr		Rcrop	Green	PrCh	QPC	Crse gr	grn-bf		S2-3	A3	Ph2	L1	Py	tr	Scor	wk			Jul-10	CS	Strong sulphide boxwork
R1480058	533019	6845920	SCGr		Talus	Green	PrCh	QPC	Breccia	Green		S2	A2			As	2	Scor	strong			Jul-10	CS	Qz fragments to 5 cm in breccia
R1480059	533432	6845901	Chip	2.0	Rc-Oc	Green	PrCh	QPC	Vned	bge-gry		S1	A2	Ph1	L1	Py	5	Scor	wk			Jul-12	CS	Also moderately brecciated
R1480060	534447	6845928	Chip	2.0	Rcrop	Green	PrCh	QPC	Breccia	bf-tan		S1	A1		L2	Py	<1					Jul-12	CS	Includes strongly silicified section
R1480061	534447	6845930	Chip	2.0	Rcrop	Green	PrCh	QPC	Breccia	bf-tan		S2	A1-2		L1	Py	4	Scor	wk			Jul-12	CS	Includes strongly silicified section
R1480062	534447	6845932	Chip	1.2	Rcrop	Green	PrCh	QPC	Breccia	tan		S2	A1-2		L2	Py	3	Scor	wk			Jul-12	CS	Includes mod limonitic (ankeritic?) section
R1480063	533446	6845928	SCGr		Rcrop	Green	PrCh	QPC	Breccia	green		S2	A2	Ph2	L1	Py	tr	Scor	mod			Jul-12	CS	Possibly mixed with pyrite?
R1480064	533439	6845936	Chip	2.0	Ocrop	Green	PrCh	QPC	fractured	gry-blue		S2	A1	Ph1		Py	<1					Jul-12	CS	F. Gr. Pyrite along bands
R1480065	533333	6845909	Chip	1.8	Ocrop	Green	PrCh	QPC	shear	Green		S2	A2			As	tr	Scor	mod			Jul-12	CS	15% Qz veins, strong sulphide boxwork

RI480066	533337	6845903	Chip	2.0	Ocrop	Green	PrCh	Qz Vn	shear	white		S3	A3			Scor	wk						Jul-12	CS	Incl. Minor QPC; strong boxwork
RI480067	533342	6845917	Chip	1.7	Ocrop	Green	PrCh	QPC	Vned	grn-bf		S2	A2	Ph1		As	tr	Scor	wk	Py	tr		Jul-12	CS	Approx 15-20% Qz veins
RI480068	533342	6845918	Chip	0.15	Ocrop	Green	PrCh	Qz Vn	Breccia	Green		S3	A2			As	2	Scor	mod				Jul-12	CS	Vein and strongly brecciated wallrock
RI480069	533371	6845971	Chip	0.35	Rcrop	Green	PrCh	QPC	Breccia	Tan			A1	Ph1	L2	Py	tr	Mang	wk				Jul-12	CS	Chip along a single 35-cm piece of rcrop-float
RI480070	533250	6845963	Grab		Rc/Ta	Green	PrCh	QPC	Vned	Green		S2	A2	Ph1		As	5	Scor	strong				Jul-12	CS	8-cm qz-scor-arseno vein
RI480071	533255	6845930	CGr		Rc/Ta	Green	PrCh	QPC	Vned	bf-grn		S2	A2	Ph1		As	1	Scor	wk	Py	tr		Jul-12	CS	Abnt talus - rcrop - proximal?
RI480072	533342	6845686	SCGr		Rc/Ta	Green	PrCh	QPC	Breccia	bf-grn		S2	A2	Ph1		Py	1	Scor	wk				Jul-12	CS	Locally sheared
RI480073	534075	6845713	CGr		Talus	Green	PrCh	Qz Vn	fractured	grn/wh						As	8	Scor	wk				Jul-13	CS	2 pieces, coarse arsenopyrite
RI480074	534082	6845766	CGr		Talus	Green	PrCh	Qz Vn	banded	grn-yel						As	1	Scor	mod	Ga	tr		Jul-13	CS	Green-yellow scor; 1 large clot galena
RI480075	534335	6845433	CGr		Talus	Green	PrCh	QPC	Vned	grn-bf		S1	A2		L1	As	2	Scor	mod	Py	<1		Jul-13	CS	Fairly abundant talus
RI480076	534667	6845413	SCGr		Talus	Green	PrCh	Qz Vn	fractured	wh/grn						As	4	Scor	wk				Jul-13	CS	Locally sheared, variable fabrics
RI480077	534667	6845397	Grab		Talus	Green	PrCh	Qz Vn	fractured	wh/grn						As	5	Scor	wk				Jul-13	CS	Frac-controlled arseno, scorodite
RI480078	534895	6845474	SCGr		Talus	Green	PrCh	Qz Vn	fractured	gry-wh						As	9						Jul-14	CS	In QPC; Essentially a "high grade"
RI480079	534781	6845526	Chip	0.9	Ocrop	Green	PrCh	QPC	Foliated	bf-gry		S2	A1	Ph2		Scor	wk						Jul-14	CS	Adj. To qz vein, locally arsenical
RI480080	534809	6845520	Chip	0.7	Ocrop	Green	PrCh	Qz Vn	fractured	gry-wh		S3	A3			As	<1	Scor	wk				Jul-14	CS	Abundant scoroditic talus directly downslope
RI480081	534785	6845521	Chip	0.9	Ocrop	Green	PrCh	Qz Vn	Foliated	gry		S3	A3			As	tr	Scor	wk				Jul-14	CS	Qz vein and some silicified QPC
RI480082	534742	6845512	Grab		Talus	Green	PrCh	Qz Vn	fractured	grn						As	1	Scor	strong				Jul-14	CS	Arseno/scorodite along fractures
RI480083	534442	6845634	CGr		Oc/Rc	Green	PrCh	Qz Vn	fractured	grn-wh						As	1	Scor	wk				Jul-14	CS	Arseno/scorodite along fractures
RI480084	533353	6845035	CGr		Rcrop		PrCh	Grit	Qz-carb	white	C2					Py	tr						Jul-16	CS	Sheared: Qz vein, carb along fractures
RI480085	533327	6845042	Grab		Rc/Ta		PrCh	Qz-As	fractured	gry-grn		S2			L1	As	25	Scor	strong	Py	tr		Jul-16	CS	Likely narrow massive Arseno-Qz vein
RI480086	533199	6845005	SCGr		Talus		PrCh	Qz-As	Breccia	Green		S2			L1	As	10	Scor	strong	Py	tr		Jul-16	CS	Fine arsenical quartz stringers
RI480087	532939	6844742	CGr		Rcrop		PrCh	Grit	Breccia	brown		S1	A1		L3	Py	tr						Jul-16	CS	Very strongly limonitic
RI480088	533400	6844058	CGr		Rcrop		PrCh	QPC	Breccia	grn-tan		S2	A1	Ph2		Py	tr	Scor	wk				Jul-16	CS	Moderate sulphide boxwork
RI480089	533363	6844001	CGr		Rcrop		PrCh	QPC	Vned	tan-blue		S2	A1	Ph2	L2	Py	2	Scor	tr				Jul-16	CS	Abundant quartz veining; brassy Py in QPC
RI480090	533077	6845928	SCGr		Talus	Green	PrCh	Qz-As	Breccia	Green		S1	A2			As	4	Scor	strong				Jul-17	CS	Brecciated quartz fragments; also slickensides
RI480091	533042	6845943	Chip	1.3	Rcrop	Green	PrCh	Qz-As	Breccia	wh-grn		S2	A1	Ph1		As	1	Scor	mod				Jul-17	CS	Rubblecrop; not true chip
RI480092	533027	6846006	CGr		Rcrop	Green	PrCh	Qz Vn	fractured	wh-tan								Scor	wk				Jul-17	CS	Sgtrong sulphide boxwork; banded limonite
RI480093	533038	6846043	SCGr		Rcrop	Green	PrCh	QPC	Breccia	tan		S1	A2		L3	Py	tr						Jul-17	CS	Includes 20% brecciated qz veins
RI480094	533035	6846070	CGr		Rcrop	Green	PrCh	QPC	Breccia	grn-bf		S2	A2			AS	2	Scor	mod				Jul-17	CS	Some quartz veining
RI480101	533173	6847308	CGr		Rcrop		PrCh	Sstone	Breccia	tan		S2	A2	Ph1	L2	Py	<1	Scor	wk				Jul-17	CS	Local well-developed sulphide boxwork
RI480102	533233	6847381	CGr		Rcrop		PrCh	QPC	fractured	gry-blue		S2	A1	Ph1	L3	Py	7						Jul-17	CS	Fracture controlled grey and brassy pyrite
RI480103	533230	6847390	CGr		Rcrop		PrCh	QPC	fractured	gry-blue		S1-2	A1-2	Ph1	L3	Py	3	Scor	wk				Jul-17	CS	Fracture controlled limonite
RI480104	534123	6845776	CGr		Talus	Green	PrCh	QPC	Vned	grn-bf		S2	A3			As	<1	Scor	wk				Jul-18	CS	Locally almost brecciated
RI480105	534176	6845716	Chip	0.7	Ocrop	Green	PrCh	QPC	Vned	grn-bf		S2-3	A3			As	tr	Scor	mod				Jul-18	CS	Quartz veins form near-stockwork
RI480106	534177	6845724	Chip	0.8	Ocrop	Green	PrCh	QPC	shear	grn-bf		S1-2	A3			As	<1	Scor	mod				Jul-18	CS	Includes vertical component to chip sample
RI480107	534172	6845713	Grab		Rcrop	Green	PrCh	QPC	Breccia	Green		S2	A2			As	3	Scor	strong				Jul-18	CS	Fairly abundant similarly mineralized rubblecrop
RI480108	533860	6845379	Chip	1.5	Ocrop		PrCh	QPC	shear	tan		S2	A2			Py	tr						Jul-18	CS	Mostly decrepitated; includes qz veins
RI480109	533918	6845374	Grab		Talus		PrCh	Qz-As	Breccia	gry/gn		S2				As	18	Scor	strong	Py	4		Jul-18	CS	Possibly from zone hosting RI480108
RI480110	533758	6845293	Chip	1.6	Oc/Rc		PrCh	QPC	Vned	brown		S1	A2		L2	Py	tr						Jul-18	CS	Strongly decrepitated
RI480111	533752	6845196	CGr		Rcrop		PrCh	Qz Vn	fractured	tan						As	4	Py	<1				Jul-18	CS	Py, arseno along feldspathic fractures
RI480112	533784	6845161	Chip		Float		PrCh	Qz Vn	fractured	wh-tan		S2	A1		L1	As	5	Py	1				Jul-18	CS	Includes QPC with cm-scale veining
RI480113	533776	6845234	CGr		Rcrop		PrCh	Grit	Vned	tan-yel		S2	A2		L2	As	tr	Py	tr	Scor	wk		Jul-18	CS	35% weakly scoroditic quartz veins
RI480114	533768	6845235	CGr		Rcrop		PrCh	Grit	fractured	tan		S2	A1		L2	Py	3						Jul-18	CS	Grit: Phyllite contact; strong sulphide boxwork
RI480115	534390	6844783	Grab		Talus		PrCh	Qz Vn	fractured	wh-tan					L1	As	tr						Jul-20	CS	1 cm-scale fracture-controlled arseno grain
RI480116	534480	6846648	Grab		Float		PrCh	Qz Vn	fractured	wh-tan					L1	Py	tr						Jul-20	CS	Large boulder, approx 1 metre long: L4500E, 3950N
RI480117	534733	6844239	CGr		Oc/Rc	Sleeping Giant	PrCh	Qz Vn	fractured	tan					L1	Py	tr						Jul-20	CS	Strong fracture-controlled boxwork
RI480118	534716	6844229	CGr		Prox Flt	Sleeping Giant	PrCh	Qz Vn	fractured	wh-tan					L1								Jul-20	CS	Vuggy; phyllite inclusions
RI480119	534726	6844219	CGr		Rcrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh-tan					L1-2	Py	tr						Jul-20	CS	Fracture controlled limonitic boxwork
RI480120	**534738**	**6844206**	**Grab**		**Prox Flt**	**Sleeping Giant**	**PrCh**	**Qz Vn**	**fractured**	**wh-tan**					**L1**	**As**	**<1**	**Py**	**tr**				**Jul-20**	**CS**	**Arseno along fractures; some pyrite boxwork**
RI480121	534745	6844191	CGr		Rcrop	Sleeping Giant	PrCh	Qz Vn	fractured	blue-tan			Ph2		L1	As	<1	Py	tr	Scor	wk		Jul-20	CS	Arseno along fractures; sericite weakly scoroditic?
RI480122	534759	6844180	Grab		Rc/Oc	Sleeping Giant	PrCh	Qz Vn	fractured	wh-tan			Ph2		L1	As	1	Py	tr				Jul-20	CS	Pyrite with arseno; fracture-controlled sulphides
RI480123	532641	6845443	CGr		Ta/Rc		PrCh	QPC	Vned	bf-tan		S2	A3	Ph1	L1	Py	<1	Scor	wk				Jul-21	CS	Argillic alteration of feldspars
RI480124	532572	6845375	SCGr		Talus		PrCh	QPC	Vned	white		S2	A3		L1	Py	tr	As	tr				Jul-21	CS	70-80% Qz Vns in QPC
RI480125	531901	6848541	SCGr		Talus	West Green	PrCh	QPC	Vned	brown		S2	A1		L3	As	5	Py	7				Jul-22	CS	Qz-arseno vein; Py in QPC
RI480126	531903	6848536	Chip	1.1	Ocrop	West Green	PrCh	QPC	Breccia	tan		S1	A2-3	Ph2	L1	Py	tr						Jul-22	CS	Moderately decrepitated
RI480127	531914	6848554	Chip		Ocrop	West Green	PrCh	QPC	Vned	bf-tan		S2	A2-3	Ph2	L1								Jul-22	CS	Possible Qz-carb alteration also
RI480128	531950	6848473	Chip	2.0	Ocrop	West Green	PrCh	QPC	fractured	bf-tan		S2	A2-3	Ph1	L1	Py	tr						Jul-22	CS	Early silicification; late fracturing
RI480129	531976	6848392	CGr		Ta/Rc	West Green	PrCh	Qz Vn	fractured	white			A2		L1	Py	tr						Jul-22	CS	Argillic (?) alteration along fractures
RI480130	531933	6848355	CGr		Talus	West Green	PrCh	Qz Vn	fractured	white			A2										Jul-22	CS	Argillic (?) alteration along fractures
RI480131	533637	6843875	Chip	0.6	Ocrop	Main	PrCh	Qz Vn	Banded	wh-gry						VG	tr	As	2	Py	tr		Jul-23	CS	Qz vein, banded; some QPC wallrock
RI480132	533489	6844002	CGr		Rc/flt		PrCh	Qz Vn	fractured	wh-tan						As	<1	Py	<1				Jul-23	CS	Arseno along fracture; foliated
RI480133	533146	6844437	CGr		Rcrop		PrCh	QPC	fractured	tan		S2	A3	Ph2	L1	Py	tr						Jul-23	CS	15% Qz veins, some sulphide boxwork
RI480134	533069	6844483	CGr		Rcrop		PrCh	Qz Vn	fractured	wh-tan						Py	tr	Scor	tr				Jul-23	CS	Possible realgar; mod fracture-controlled boxwork
RI480135	533377	6844263	Grab		Rcrop		PrCh	Qz Vn	fractured	wh-tan						As	<1	Py	tr				Jul-23	CS	Arseno along fractures; strong boxwork
RI480136	533378	6844263	Grab		Rcrop		PrCh	Qz Vn	fractured	wh-tan						Ga	tr	Scor	wk				Jul-23	CS	One galena lath; moderate boxwork
RI480137	533388	6844272	Grab		Prox Flt		PrCh	Qz Vn	fractured	tan-gry						VG	tr	As	2	Py	tr		Jul-25	CS	VG at edge of boxwork vugs
RI480138	533400	6844227	CGr		Prox Flt		PrCh	QPC	Vned	tan-wh		S3	A2	Ank 1		As	<1						Jul-25	CS	Arseno along edge of quartz veins
RI480139	533366	6844253	Chip	1.2	Ocrop		PrCh	Qz Vn	fractured	wh-tan					L1								Jul-25	CS	Minor phyllite along fractures
RI480151	533354	6844233	SCGr		Talus		PrCh	Qz Vn	fractured	tan					L2	Py	tr						Jul-25	CS	Strong limonite along fractures
RI480152	533369	6843910	CGr		Talus		PrCh	Sstone	Vned	tan		S1	A1	Ph2	L2	As	2	Py	tr				Jul-25	CS	Arseno in veinlets, along qz veins with boxwork
RI480153	533432	6843936	CGr		Rcrop		PrCh	Qz Vn	fractured	wh-tan					L1								Jul-25	CS	Some clay-altered fractures; fractures include boxwork
RI480154	535328	6845714	CGr		Rc/Ta	Green	PrCh	QPC	Vned	buff		S2	A3		L1	Py	tr	Scor	wk				Jul-26	CS	Almost all pieces show similar alteration
RI480155	535115	6845492	Grab		Talus	Green	PrCh	Qz Vn	Massive	white						As	6	Py	tr				Jul-26	CS	Arseno clots > 1.0 cm
RI480156	535059	6845498	Chip	1.8	Ocrop	Green	PrCh	Qz Vn	Massive	white					L1	As	tr						Jul-26	CS	Minor QPC +/- arseno
RI480157	534912	6845317	CGr		Rcrop	Green	PrCh	Qz Vn	Vuggy	wh-tan					L1								Jul-26	CS	Base of similar quartz vein
RI480158	534942	6845285	Chip	0.6	Talus	Green	PrCh	Qz Vn	fractured	wh-tan					L1	As	2						Jul-26	CS	Abundant large similar talus
RI480159	534936	6845326	Chip	1.3	Ocrop	Green	PrCh	Qz Vn	fractured	white					L1	As	<1						Jul-26	CS	Banded arseno at north end of vein
RI480160	534758	6844179	Chip	2.0	Ocrop	Sleeping Giant	PrCh	QPC	Vned	wh-bf		S3	A3		L1	As	tr	Scor	tr				Jul-27	ML/CS	50-60% Qz veins; sulphide boxwork
RI480161	534759	6844178	Chip	2.0	Ocrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/tan				Ph2	L1	As	<1	Py	<1				Jul-27	ML/CS	Fine grained pyrite; 15% QPC
RI480162	534761	6844177	Chip	2.0	Ocrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/tan					L1	As	tr	Py	tr	Scor	wk		Jul-27	ML/CS	Vuggy fractures with trace Arseno
RI480163	534762	6844176	Chip	2.0	Ocrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/tan		S3	A3		L1	As	tr	Py	tr				Jul-27	ML/CS	Strong boxwork along vuggy fractures
RI480164	534763	6844175	Chip	2.0	Ocrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/tan					L1	As	tr	Py	tr	Scor	wk		Jul-27	ML/CS	Arseno, scorodite along fractures
RI480165	534764	6844174	Chip	2.0	Ocrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/tan		S3	A3	Ph2	L1	As	tr	Py	1				Jul-27	ML/CS	15% QPC, f. Gr pyrite boxwork
RI480166	534765	6844173	Chip	2.0	Ocrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/tan		S3	A2	Ph2	L1	Py	tr						Jul-27	ML/CS	Parallel fractures, minor QPC
RI480167	534714	6844244	CGr		Rcrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/gry						As	5	Py	<1				Jul-27	CS	In QPC; massive arseno along fractures

RI480168	534631	6844089	Chip	1.1	Ocrop	Sleeping Giant	PrCh	Qz Vn	Breccia	wh/gry						VG	tr	As	5	Py	<1	Jul-27	CS	5-10% phylite xenoliths
RI480169	534616	6844078	CGr		Rcrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/gry						As	4	Py	tr			Jul-27	CS	In QPC; rcrop under stump
RI480170	534713	6844240	Chip	2	Ocrop	Sleeping Giant	PrCh	Qz Vn	fractured	h						Py	tr					Jul-27	ML/CS	Qz veins; approx 10% QPC, some boxwork along fractures
RI480171	534562	6844272	Chip	1.2	Ocrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/gry						As	8	Py	<1			Jul-27	CS	Arseno along fractures; some arseno blebs
RI480172	534386	6846613	CGr		Rcrop		PrCh	Qz Vn	fractured	white					L1							Jul-29	CS	Inclusions of calcareous sandstone
RI480173	534365	6845985	Chip	1.5	Oc/Rc		PrCh	Phy	Breccia	brown		S1		Ph1	L3	Scor	wk					Jul-29	CS	Fine quartz stringers, localized silicification
RI480174	534362	6845986	Chip	0.8	Oc/Rc		PrCh	Phy	Breccia	brown		S1		Ph1	L3							Jul-29	CS	Qz vein; very strong boxwork; interstitial material removed
RI480175	534631	6844065	Grab		Rcrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/gry						VG	tr	As	4			Jul-30	CS	Locally abundant gold with arsenopyrite
RI480176	534622	6844067	Chip	1.5	Ocrop	Sleeping Giant	PrCh	Qz Vn	fractured	white						As	2					Jul-30	CS	Possibly slumped somewhat
RI480177	534617	6844095	Chip	1.2	Ocrop	Sleeping Giant	PrCh	Qz Vn	Massive							As	2					Jul-30	CS	Roughly 40 cm arseno enriched
RI480178	534612	6844115	CGr		Rcrop	Sleeping Giant	PrCh	Qz Vn	fractured	wh/gry						As	<1					Jul-30	CS	Incl 15% sil. QPC +/- tr arseno
RI480179	533333	6846100	CGr		Ocrop	Green	PrCh	QPC	Vned	bf-tan		S2	A3			As	<1	Py	1			Aug-01	CS	QPC to Sandstone: arseno in wallrock and veins
RI480180	533327	6846030	CGr		Rc/Ta	Green	PrCh	QPC	Vned	gry-bf		S1-2	A2			As	tr	Py	tr			Aug-01	CS	Arseno along quartz veins
RI480181	533385	6845987	CGr		Rcrop	Green	PrCh	Sstone	Breccia	tan		S2-3	A3	Ph2	L2	Py	tr	Scor	wk			Aug-01	CS	Mod sulphide boxwork; yellow scorodite
RI480182	533379	6845854	CGr		Rcrop	Green	PrCh	QPC	Vned	buff		S3	A3	Ph1	L1	Py	tr	Scor	wk			Aug-01	CS	Local vein stockwork; frac-controlled scorodite
RI480183	533353	6845820	CGr		Rcrop	Green	PrCh	QPC	Breccia	yel/bf		S2	A2		L1	Py	tr	Scor	wk			Aug-01	CS	Some quartz stockwork; scorodite along fractures
RI480184	533344	6845824	SCGr		Rcrop	Green	PrCh	QPC	Breccia	Green		S2	A2		L1	As	2	Scor	mod	As	tr	Aug-01	CS	Mod-strong sulphide boxwork
RI480185	533333	6845770	SCGr		Rcrop	Green	PrCh	QPC	Breccia	pink/bf		S2-3	A3		L1	Py	tr	Scor	wk	Py	tr	Aug-01	CS	10-15% quartz veins
RI480186	533314	6845735	CGr		Rcrop	Green	PrCh	QPC	Breccia	tan		S2	A2		L2	Py	tr					Aug-01	CS	Strong pyrite boxwork; some quartz veins
RI480187	533326	6845701	SCGr		Talus	Green	PrCh	QPC	Breccia	bf/grn		S1-2	A3	Ph2	L1	Scor	wk					Aug-02	CS	Fairly abundant talus
RI480188	533352	6845682	SCGr		Talus	Green	PrCh	QPC	Breccia	bf/tan		S2	A2-3	Ph1	L1	Scor	wk	Py	tr			Aug-02	CS	Mod pyrite boxwork
RI480189	528700	6852694	SCGr		Talus		PrCh	Sstone	Vned	grn/brn		S1	A2	Ph2	L1	As	4	Py	2	Scor	mod	Aug-03	CS	Proximal talus
RI480190	528665	6852700	Grab		Talus		PrCh	QPC	Foliated	gry/blue		S1	A2	Ph1	L2	Py	5	Scor	wk			Aug-03	CS	Fine grained pyrite within silicified fracture
RI480191	533539	6845735	CGr		Talus	Green	PrCh	Qz Vn	Breccia	brown					L3							Aug-04	CS	Proximal source; limonite after sulphides
RI480192	533541	6845741	SCGr		Talus	Green	PrCh	Qz Vn	Vuggy	white					L1	Ga	tr	As	tr			Aug-04	CS	Dark brown limonite after galena?
RI480193	533544	6845767	Chip		Ocrop	Green	PrCh	Qz Vn	fractured	white						As	4					Aug-04	CS	Large arseno clots to 2 cm
RI480194	533602	6845613	CGr		Rcrop	Green	PrCh	QPC	Vned	buff		S2	A3		L1	Py	1	Scor	wk			Aug-04	CS	30% quartz vein frags
RI480201	533356	6845932	CGr		Rcrop	Green	PrCh	QPC	Breccia	tan		S1	A3		L2							Aug-04	CS	Early silicification; late brecciation; includes qz veins
RI480202	533347	6845925	Chip	1.2	Ocrop	Green	PrCh	QPC	Vned	wh-gry		S2-3	A2		L1	Py	tr	Scor	wk			Aug-04	CS	Typical of large ocrop; 10% qz veins
RI480203	533330	6845915	Chip	1.2	Ocrop	Green	PrCh	QPC	Foliated	grey		S2	A2-3		L1	Py	tr					Aug-04	CS	5-6% mm-scale quartz stringers
RI480204	533320	6845906	CGr		Rcrop	Green	PrCh	QPC	Breccia	Green		S2-3	A2-3			As	<1	Scor	mod	Py	<1	Aug-04	CS	Strong local sulphide boxwork
RI480205	533292	6845902	CGr		Rc/Ta	Green	PrCh	Qz Vn	fractured	grn/wh						As	4	Scor	strong	Py	tr	Aug-04	CS	Abnt qz vein, qz-breccia float to 40 cm
RI480206	533278	6845958	CGr		Rc/Ta	Green	PrCh	Sstone	Vned	grn/bf		S2	A3		L1	As	<1	Scor	mod			Aug-04	CS	Scorodite largely along fractures, surfaces
RI480207	533692	6845662	CGr		Rcrop	Green	PrCh	QPC	Vned	buff		S1	A2-3		L2	Py	tr					Aug-05	CS	Limonite along fractures; cross-cutting quartz
RI480208	533682	6845650	CGr		Prox Flt	Green	PrCh	QPC	Vned	bf/blue		S2-3	A3		L2	Py	tr					Aug-05	CS	Limonitic vesicles after feldspathic clasts
RI480209	533631	6845622	CGr		Rcrop	Green	PrCh	QPC	fractured	grn/blue		S2	A3	Ph2	L2	Py	<1	Scor	wk			Aug-05	CS	Mod-strong sulphide boxwork
RI480210	533623	6845616	CGr		Rcrop	Green	PrCh	QPC	Vned	grn/tan		S2	A2-3	Ph2	L2	Py	<1	As	1	Scor	wk	Aug-05	CS	Variable scorodite; mod sulphide boxwork
RI480211	533618	6845613	CGr		Rcrop	Green	PrCh	QPC	Breccia	grn/blue		S2-3	A2		L2	As	2	Py	>1	Scor	wk	Aug-05	CS	Interstitial fracture-controlled py, arseno
RI480212	533599	6845606	SCGr		Talus	Green	PrCh	QPC	Foliated	grn/blue		S2	A2	Ph2	L1	As	tr	Py	1	Scor	wk	Aug-05	CS	Almost rubblecrop; small slope near top
RI480213	533390	6845935	SCGr		Rcrop	Green	PrCh	QPC	Breccia	tan		S1	A2	Ph2	L3							Aug-05	CS	Along edge of altered QPC unit
RI480214	533369	6845914	Chip	2.0	Ocrop	Green	PrCh	QPC	Vned	wh/buff		S2	A3	Ph1	L1	Py	<1	Scor	wk			Aug-05	CS	Euhedral pyrite and pyrite boxwork
RI480215	533350	6845889	CGr		Rcrop	Green	PrCh	Qz Vn	fractured	gry/wh						As	3	Scor	mod			Aug-05	CS	Arseno along fractures
RI480216	533350	6845886	Chip	2.0	Rcrop	Green	PrCh	QPC	Vned	gry/wh		S2-3	A2			As	4	Scor	mod			Aug-05	CS	Chip of small rcrop frags
RI480217	533297	6845860	CGr		Rc/Ta	Green	PrCh	QPC	Vned	grn/wh		S3	A2-3			As	<1	Scor	mod	Py	tr	Aug-05	CS	30% Qz +/- arseno vein; abundant pieces
RI480218	533297	6845842	Chip	1.5	Rc/Ta	Green	PrCh	QPC	Vned	tan		S1	A1	Ph1	L1							Aug-05	CS	25-30% Quartz veins
RI480219	533284	6845891	Chip	2.0	Ocrop	Green	PrCh	QPC	bu	buff		S2-3	A2-3		L1	As	tr	Scor	wk			Aug-05	CS	Incl 20 cm white Qz vein
RI480220	533314	6845926	CGr		Rcrop	Green	PrCh	QPC	Vned	buff		S2-3	A2-3		L1							Aug-05	CS	Mod-strong sulphide boxwork
RI480221	533189	6845287	CGr		Rcrop	Green	PrCh	QPC	Foliated	beige			A2	Ph2	L1							Aug-06	CS	Probable felsenmeer within talus, 10% Qz vns
RI480222	**533240**	**6845827**	**CGr**		**Rcrop**	**Green**	**PrCh**	**QPC**	**Vned**	**beige**		**S2**	**A2**	**Ph1**	**L1**	**As**	**tr**	**Scor**	**wk**			**Aug-06**	**CS**	**Moderately foliated**
RI480223	533242	6846005	CGr		Rcrop	Green	PrCh	QPC	Vned	wh/gry		S2-3	A3	Ph1	L1							Aug-06	CS	Limonitic vugs
RI480224	533222	6846050	CGr		Rcrop	Green	PrCh	QPC	Vned	bf/grn		S2	A3		L1			Scor	wk			Aug-06	CS	Vuggy, fracture-controlled limonite
RI480225	533223	6846044	Chip	1.0	Ocrop	Green	PrCh	QPC	Vned	bf/grn		S2	A2-3	Ph1		As	tr	Scor	wk	Py	tr	Aug-06	CS	Possible proximal rubblecrop boulder
RI480226	533215	6846036	CGr		Rcrop	Green	PrCh	QPC	Breccia	tan		S1	A2		L2			Scor	mod			Aug-06	CS	Occurs as large rubblecrop boulders
RI480227	533215	6846038	CGr		Rcrop	Green	PrCh	QPC	Breccia	bf/grn		S3	A3			As	tr	Scor	wk			Aug-06	CS	Some Qz vein fragments
RI480228	533190	6846010	Chip	0.6	Ocrop	Green	PrCh	Sstone	Vuggy	buff		S2-3	A3	Ph1		As	tr					Aug-06	CS	Mod euhedral sulphide boxwork
RI480229	533187	6845997	CGr		Ta/Rc	Green	PrCh	QPC	shear	yel/grn		S2	A3		L1	As	tr	Scor	strong			Aug-06	CS	Slickensides visible
RI480230	533134	6845974	Chip	0.9	Ocrop	Green	PrCh	QPC	Vned	wh/buff		S2	A2	Ph1	L1							Aug-08	CS	Vuggy Qz veins comprise 60% of sample
RI480231	533014	6845856	SCGr		Rcrop	Green	PrCh	QPC	Vned	Green		S1	A1	Ph2	L1	As	3	Scor	strong			Aug-08	CS	Sub-cm Qz-arseno veinlets; pervasive scorodite
RI480232	533028	6845901	CGr		Rc/ta	Green	PrCh	QPC	fractured	bf/grn		S3	A3			As	tr	Scor	mod			Aug-08	CS	Incl. some sandstone; strong sulphide boxwork
RI480233	533029	6845930	SCGr		Talus	Green	PrCh	QPC	Breccia	Green		S1-2	A2		L1	As	<1	Scor	mod			Aug-09	CS	Some very strongly brecciated fragments
RI480234	533056	6845962	CGr		Rc/Ta	Green	PrCh	Qz-As	Banded	Green		S2-3		Ph1	L1	As	12	Scor	strong	Py	tr	Aug-09	CS	Sub-cm massive arseno bands
RI480235	533159	6846038	CGr		Rcrop	Green	PrCh	Qz-As	fractured	yel/grn		S2	A2			As	2	Scor	mod			Aug-09	CS	Sub-cm scale arseno/scorodite stringers
RI480236	533162	6846076	CGr		Rcrop	Green	PrCh	QPC	Foliated	bf/tan		S1	A2-3		L2	Py	tr	Scor	wk			Aug-09	CS	Limonite in clay-altered vugs after feldspar
RI480237	533199	6846076	CGr		Rcrop	Green	PrCh	QPC	Breccia	yel/grn		S2	A2-3		L1	Py	<1	Scor	wk			Aug-09	CS	Silica flooding of matrix
RI480238	533033	6846002	CGr		Rcrop	Green	PrCh	QPC	Breccia	tan			A1		L3							Aug-09	CS	Fine sulphide boxwork; Qz vein frags
RI480239	533040	6846005	CGr		Rcrop	Green	PrCh	QPC	Vned	white		S2	A3	Ph2	L1	Py	tr					Aug-09	CS	60-70% Qz veins; fine grained dark grey mica
RI480240	533017	6845990	CGr		Rcrop	Green	PrCh	QPC	Vned	Green		S2-3	A2	Ph3		As	5	Scor	strong			Aug-09	CS	Fine Qz-As stringers and larger veins
RI480241	533029	6845967	CGr		Rcrop	Green	PrCh	QPC	fractured	tan		S1-2	A2	Ph1	L2			Scor	wk			Aug-09	CS	Fairly strong sulphide boxwork
RI480242	533010	6845959	Chip	1.7	Rcrop	Green	PrCh	QPC	stwork	grn/gry		S2-3	A3	Ph1	L1	As	3	Scor	mod			Aug-09	CS	Variety of fabrics in rubblecrop chips
RI480243	533014	6845960	CGr		Rcrop	Green	PrCh	QPC	Vned	Green		S3	A2	Ph2	L1	As	7	Scor	strong			Aug-09	CS	Brecciated; fine silica stockwork
RI480244	532948	6845874	CGr		Prox Talus	Green	PrCh	QPC	Vned	yel/gry		S2	A3	Ph1	L1	As	2	Scor	wk	Py	tr	Aug-09	CS	Local arseno/scorodite banding; fairly large boulders
RI480245	534514	6844605	SCGr		Float	Green		Qz Vn	fractured	White						As	3					12/08/2010	CS	Frac-controlled arseno, minor scorodite in wallrock
RI480246	534740	6844058	CGr		Oc/Rc	Green		Qz Vn	fractured	White						As	2					12/08/2010	CS	Includes minot QPC
RI480247	534743	6844062	Grab		Prox Flt	Green		QPC	Vned	gry-wh		S2				As	7	Scor	wk			12/08/2010	CS	2-3 cm Qz-arseno vein in QPC
RI480253	532956	6846040	CGr		Rc/Ta	Green		QPC	Vned	wh/tan		S2	A2		L1	Py	tr					14-Aug	CS	Mod-strong sulphide boxwork
RI480254	533083	6846175	Chip	1.6	Ocrop	Green		QPC	Vned	yel/wh		S2	A2-3		L1	As	tr	Scor	wk			14-Aug	CS	Includes 15 cm strongly pasty section at S end
RI480255	533087	6846181	Chip	0.7	Ocrop	Green		QPC	stwork	buff		S1-2	A2-3					Scor	wk			14-Aug	CS	Possibly large prox talus boulder
RI480256	533276	6846373	CGr		Ta/Rc	Green		Gwke	Vned	bf/gry		S2	A2		L1							14-Aug	CS	Fairly strong pyrite boxwork
RI480257	532995	6846082	Chip	2.0	Rcrop	Green		QPC	Vned	buff		S1-2	A2-3		L1			Scor	wk			14-Aug	CS	Limonite in clay-altered vugs after feldspar
RI480258	532994	6846075	Chip	0.6	Rc bldr	Green		QPC	Breccia	brown		S2	A2		L3	Py	tr					14-Aug	CS	Mod-strong sulphide boxwork
RI480259	533049	6846266	Chip	0.7	Rcrop	Green		QPC	fractured	bf/tan		S2	A2		L2			Scor	wk			14-Aug	CS	2-3% fine quartz stringers; possible talus?
RI480260	533177	6846381	Grab		Rc bldr	Green		Gwke	Vned	brown		S1	A1	Ch1	L1	As	7	py	<1			15-Aug	CS	Massive arseno along edg of qz vein
RI480261	533182	6846376	CGr		Rcrop	Green		Gwke	Vned	brown	C1	S1	A1	Ank 1	L1	As	tr	py	<1	Ga	tr	15-Aug	CS	25-30% Quartz veins; trace late galena
RI480262	533157	6846515	Chip	1.1	Ocrop	Green		QPC	shear	gry/tan		S2	A2		L1	As	tr	py	tr	Scor	wk	15-Aug	CS	Scor, possible f. Gr arseno along small shear
RI480263	532929	6846143	Chip	1.1	Ocrop	Green		QPC	shear	yel/brn		S1-2	A2		L1			Scor	wk			16-Aug	CS	Scorodite directly along slickensides

RI480264	532972	6846038	CGr		Rcrop	Green		QPC	Breccia	Yel/tan			S1	A2-3		L2	Py	<1	Scor	wk			16-Aug	CS	Strong fracture-controlled pyrite boxwork
RI480265	532671	6845792	Chip	1.2	Ocrop	Hoito		Qz Vn	Vuggy	wh/tan							As	tr	py	>1	cpy	tr	16-Aug	CS	Fracture-controlled sulphides; c gr sulphides in vugs
RI480266	532670	6845792	Chip	1.5	Ocrop	Hoito		Qz Vn	fractured	wh/tan							As	tr	py	<1			16-Aug	CS	Chip "offset" due to difficult chipping conditions
RI480267	532673	6845788	CGr		Oc/Rc	Hoito		Qz Vn	fractured	wh/tan							As	<1					16-Aug	CS	Clotty, fracture-ontrolled arseno
RI480268	533073	6845535	SCGr		Talus			QPC	fractured	tan			S1-2	A3		L2	Py	tr	Scor	wk	As	tr	16-Aug	CS	Some fine silica veining
RI480269	532569	6845920	SCGr		Rcrop			Qz Vn	fractured	wh/tan						L1	py	<1					17-Aug	CS	Strong pyrite boxwork in some pieces
RI480270	532532	6845590	Chip	1.4	Ocrop			QPC	shear	bf/tan			S1	A1	Ph2	L1							17-Aug	CS	10-15% cm-scale foliatuin-parallel qz veins
RI480271	532532	6845589	Chip	1.0	Ocrop			Qz Vn	shear	wh/tan						L2	py	tr					17-Aug	CS	Mod fracture-controlled py boxwork
RI480272	532672	6845787	Chip	2.0	Ocrop	Hoito		Qz Vn	fractured	White							py	tr					17-Aug	CS	Local fine fracturing
RI480273	532671	6845786	CGr		Ocrop	Hoito		Qz Vn	fractured	White							As	<1	py	tr			17-Aug	CS	High-grade: Is there any gold there?? Post Script: Irony - see above
RI481001	534670	6845674	Grab		Ocrop		PrCh	QPC	Vein	Grn-wh			S3	A2			As	6					Jul-07	AM	>90% Qz vein; arseno in vein + QPC wallrock
RI481002	534733	6845523	CGr		Ocrop		PrCh	QPC	Vein	Grn-wh			S2	A2			As	8					Jul-07	AM	Arsenical QPC + Az-arseno vein
RI481003	531053	6848776	Grab		Ocrop		PrCh	QPC	shear	gry-blue			S1	A1	Ph2	L1	Py	1					Jul-08	AM	Pyrite-enriched coarse sandstone
RI481004	531053	6848776	CGr		Ocrop		PrCh	QPC	Foliated	gry-blue			S2	A2	Ph2	L2	Py	3					Jul-08	AM	Strong sulphide boxwork
RI481005	533911	6846492	CGr		Ocrop		PrCh	Qz-As	Breccia	Green							As	15	Scor	strong			Jul-09	AM	Banded, brecciated Qz-As vein
RI481006	533859	6845341	CGr		Ocrop		PrCh	Qz-As	Banded	grn-wh							As	20	Scor	mod	Py	<1	Jul-10	AM	Euhedral py, arseno
RI481007	534067	6844659	CGr		Ocrop		PrCh	QPC	Vned	wh-gry	C1		S1	A1		L1	As	>1					Jul-10	AM	Clotty, replacement-style arseno
RI481008	535023	6845500	CGr		Ocrop	Green	PrCh	Qz-As	Banded	grn/gry							As	20	Scor	strong			Jul-12	AM	Hosted by phyllite
RI481009	535019	6845500	CGr		Ocrop	Green	PrCh	Qz-As	Banded	grn/gry							As	25	Scor	strong			Jul-12	AM	Similar to RI481008; semi-massive Arseno
RI481010	533543	6843992	CGr		Ocrop		PrCh	Qz Vn	fractured	gry-wh							As	4	Py	1	Ga	tr	Jul-13	AM	Arseno +/- pyrite along fractures
RI481011	532546	6845379	CGr		Ocrop		PrCh	Sstone	Vned	wh/tan			S1	A1	Ph1		Scor	wk	Py	1			Jul-14	AM	40% quartz; minor phyllite
RI481012	532599	6845536	Grab		Ocrop	Green	PrCh	Qz Vn	fractured	wh/tan							Ga	<1	Py	tr			Jul-14	AM	One large vug of galena
RI481013	533353	6844003	CGr		Ocrop		PrCh	QPC	Vned	wh-gry			S2	A1		L2	As	2					Jul-23	AM	65% veins; arseno along fractures
RI481014	532599	6845536	CGr		Ocrop		PrCh	Qz Vn	fractured	wh-gry							As	8					Jul-26	AM	Arseno along fractures
RI481015	534623	6844065	CGr		Ocrop		PrCh	Qz Vn	Vuggy	Gr/white							As	6	Py	tr			Jul-29	AM	Includes some QPC with arseno
RI481016	532549	6845411	CGr		Ocrop		PrCh	Qz Vn	fractured	wh/tan						L1	As	<1	Py	>1			Jul-30	AM	Euhedral py, arseno along fractures
RI481017	535545	6841825	CGr		Ocrop		PrCh	QPC	Vned	gry/brn			S2	A2		L1	As	15	Py	<1	Scor	strong	Aug-02	AM	One piece shows mass arseno as breccia matrix
RI481501	533880	6844239	Grab				Hyland	QPC		grey	N	Y	Fecb	cy			py		asp				10/07/2010	CB	QPC with disseminated py+asp
RI481502	533936	6844244	Chip	0.8			Hyland	QPC		grey	N	Y	Fecb				py		asp				10/07/2010	CB	Quartz veins with asp
RI481503	532849	6844205	Grab		Boulder			QZVN		White	N		Lim	Fecb			py	2	asp	1			18/07/2010	CB	Quartz vein boulder with py+asp+Fecb
RI481504	533929	6843754	Grab		Boulder			QZVN		White	N		Lim	Fecb			asp	0.5	py	1			23/07/2010	CB	
RI481505	533743	6843807	Grab		Boulder			QZVN		White	N		Lim	Fecb			py	2	gn	0.5	cy		26/07/2010	CB	tr. Asp; gn±asp form in seams along fractures
RI481506	533230	6844231	Chip	1	Outcrop		Hyland	QPC		buff	N	Y	cy	Fecb			py	2	asp	1	cy		27/07/2010	CB	sulphides are disseminated in QPC and in quartz veinlets
RI481507	533230	6844231	Chip	1	Outcrop		Hyland	QPC		buff	N	Y	cy	Fecb			py	2	asp	1	cy		27/07/2010	CB	sulphides are disseminated in QPC and in quartz veinlets; extension of zone in RI481506
RI481508	534627	6844085	Chip	1	Outcrop	Sleeping Giant		QZVN		White	N		Fecb				asp	1	py	1			30/07/2010	CB	blebs of asp disseminated through milky white quartz; extends sample RI480168 for 1m upslope
RI481509	534627	6844085	Grab		Boulder	Sleeping Giant		QZVN		White	N		Fecb	Lim			asp	2	py	3			30/07/2010	CB	Altered boulder with py+asp+fecb along fractures
RI481510	534627	6844085	Grab		Boulder	Sleeping Giant		QZVN		White	N		Fecb	Lim			asp	1	py	2			30/07/2010	CB	Altered boulder with py+asp+fecb along fractures
RI481511	533633	6843822	Chip	0.6	Outcrop	Main	Hyland	QPC		grey	N	Y	cy	Fecb			py	2	asp	0.1	scr		05/08/2010	CB	QPC with cy altered fsp and seams with py and tr. asp (scoridite)
RI481512	533633	6843821	Chip	1	Outcrop	Main	Hyland	QPC		grey	N	Y	cy	Fecb			py	2	asp	0.1	scr		05/08/2010	CB	1.0 m SW of RI481512 in the same unit and alteration system
RI481513	533646	6843831	Chip	1.2	Outcrop	Main	Hyland	QPC		grey	N		cy	Fecb			py	3	asp	1	scr		05/08/2010	CB	Strongly altered QPC with fracture controlled and disseminated py+asp+fecb
RI481514	533627	6843852	Chip	0.7	Boulder	Main		QZVN		White	N		Fecb	cy			py	2	asp	1			05/08/2010	CB	disseminated asp+py in a slightly displaced QZVN boulder
RI481515	533626	6843852	Chip	1.2	Boulder	Main		QZVN		White	N		Fecb	cy			py	2	asp	1			05/08/2010	CB	disseminated asp+py in a slightly displaced QZVN boulder
RI481516	533623	6843852	Chip	1.0	Outcrop	Main		QZVN		White	N		Fecb	cy			py	1	asp	0.5			05/08/2010	CB	Faulted QZVN in outcrop. Steeply dipping with weak mineralisation.
RI481517	533648	6843843	Chip	1.3	Outcrop	Main	Hyland	QPC	QZVN	grey	N	Y	Fecb	cy			py	2	asp	1			05/08/2010	CB	Heavily veined QPC with cy+py+asp; veins contain py+asp
RI481518	533640	6843840	Chip	1.1	Outcrop	Main		QZVN		White	N						asp	0.5	Au(vg)	0.1	py		05/08/2010	CB	Plain qtz with tr. asp and Au(vg)
RI481519	533651	6843838	Chip	1.5	Outcrop	Main		QZVN		White	N						py	0.5	asp	0.1			05/08/2010	CB	tr. Sulphides in milky white qtz.
RI481520	533651	6843836	Chip	1.0	Outcrop	Main		QZVN		White	N		Fecb				py	1	asp	1	Au(vg)		05/08/2010	CB	3 Au grains in a patch of asp and 2 Au grains in qtz.
RI481521	533650	6843837	Chip	0.45	Boulder	Main		QZVN		White	N		Lim				py	0.5	asp	0.1	Au(vg)		06/08/2010	CB	7-8 Au grains on 2 chips; Au occurs in patches of free sulphides
RI481522	**533649**	**6843837**	**Chip**	**0.5**	**Boulder**	**Main**		**QZVN**		**White**	**N**		**Fecb**	**Lim**			**py**	**1**	**asp**	**0.5**	**Au(vg)**		**06/08/2010**	**CB**	**3-4 Au grains on 2 chips; associated with walirock fragments**
RI481523	533637	6843877	Chip	0.3	Outcrop	Main		QZVN		White	N		Lim				py	1	asp	0.5			06/08/2010	CB	30 cm thick QZVN which appears sub-parallel to the Main Zone.
RI481524	533637	6843877	Chip	1.1	Outcrop	Main	Hyland	QPC		grey			Fecb	cy	lim		py	2	asp	1	scr	0.1	06/08/2010	CRB	Strong cy alteration in QPC + asp in QPC and QZVN
RI481525	533636	6843876	Chip	1.4	Outcrop	Main	Hyland	QPC		grey			Fecb	cy	lim		py	2	asp	0.5	scr	0.5	08/08/2010	CRB	tr. Asp diss in QPC host
RI481526	533610	6844962	Chip	1.4	Outcrop		Hyland	QPC		green			cy	scr			py	1	asp	0.1			08/08/2010	CRB	diss asp in QPC
RI481527	533627	6844967	Chip	0.35	Outcrop		Hyland	QPC		buff			cy	ser	Fecb	py	py	3	asp	0.5			08/08/2010	CRB	diss asp
RI481528	533627	6844967	Chip	1.0	Outcrop		Hyland	QPC		buff			cy	ser	Fecb	py	py	3	asp	0.5			08/08/2010	CRB	diss asp
RI481529	533840	6844524	Grab		Boulder			QZVN		White			Lim				py	2	asp	1			09/08/2010	CRB	diss asp
RI481530	533854	6844522	Grab		Boulder			QZVN		White			Lim	Fecb			py	3	asp	2			09/08/2010	CRB	diss asp
RI481531	534000	6844421	Grab		Boulder			QZVN		White			Lim	Fecb			py	2	asp	1			09/08/2010	CRB	diss asp
RI481532	534000	6844421	Chip		Boulder			QZVN		White			Lim	Fecb			py	3	asp	2			09/08/2010	CRB	diss asp
RI481533	534061	6844397	Grab		Boulder			QZVN		White			Fecb				py	2	asp	2			09/08/2010	CRB	diss asp
RI481534	534569	6844280	Chip	1.7	OC	Sleeping Giant		QZVN		White			Lim	cy			py	0.5	asp	1			10/08/2010	CRB	diss asp
RI481535	534567	6844281	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	cy			py	1	asp	2			10/08/2010	CRB	diss asp + SH frag
RI481536	534567	6844278	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	cy			py	0.5	asp	1			10/08/2010	CRB	diss asp
RI481537	534568	6844274	Chip	2.0	OC	Sleeping Giant		QZVN		White			Fecb	cy	lim		py	1	asp	0.5			10/08/2010	CRB	diss asp + SH frag
RI481538	534569	6844273	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim				py	1	asp	0.1			10/08/2010	CRB	SH frag
RI481539	534571	6844271	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim				py	1	asp	1			10/08/2010	CRB	asp in fracture seams
RI481540	534572	6844270	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	Fecb			asp	3	py	2			10/08/2010	CRB	asp in fracture seams and diss
RI481541	534574	6844269	Chip	2.3	OC	Sleeping Giant		QZVN		White			Lim	Fecb			py	2	asp	2			10/08/2010	CRB	asp in frac seams + SH frag
RI481542	534565	6844272	Chip	2.5	OC	Sleeping Giant		QZVN		White			Fecb	cy	lim		py	2	asp	2			10/08/2010	CRB	diss asp grains and blebs + SH frag
RI481543	534569	6844269	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	cy			py	2	asp	2			10/08/2010	CRB	diss asp grains
RI481544	534571	6844268	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	cy			py	1	asp	0.5			10/08/2010	CRB	diss asp grains
RI481545	534572	6844267	Chip	1.9	OC	Sleeping Giant		QZVN		White			cy	scr	lim		py	1	asp	0.5			10/08/2010	CRB	diss asp grains
RI481546	534602	6844209	Chip	1.0	OC	Sleeping Giant		QZVN		White			cy	scr	Fecb		py	2	asp	1			10/08/2010	CRB	diss asp grains
RI481547	534597	6844204	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	cy			py	2	asp	0.5			10/08/2010	CRB	diss asp + SH frag
RI481548	534598	6844203	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	scr	Fecb		py	2	asp	2			10/08/2010	CRB	fine-grained diss asp + SH frag
RI481549	534600	6844201	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	Fecb	scr		py	2	asp	2			10/08/2010	CRB	fine-grained diss asp + SH frag
RI481550	534601	6844200	Chip	2.6	OC	Sleeping Giant		QZVN		White			Lim	scr			py	1	asp	2			10/08/2010	CRB	fine-grained diss asp + SH frag
RI481551	534579	6844190	Grab		Boulder	Sleeping Giant		QZVN		White			Fecb	Lim	cy		py	1	asp	1			10/08/2010	CRB	quartz vein boulder at edge of the gulch
RI481552	534605	6844178	Chip	1.35	OC	Sleeping Giant		QZVN		White			scr				asp	1	py	0.1			10/08/2010	CRB	abundant SH frag
RI481553	534606	6844177	Chip	1.35	OC	Sleeping Giant		QZVN		White			scr				asp	0.5	py	0.1			11/08/2010	CRB	abundant SH frag
RI481554	534596	6844179	Chip	2.0	OC	Sleeping Giant		QZVN		White			lim				py	2	asp	1			11/08/2010	CRB	abundant SH frag + asp grains
RI481555	534597	6844178	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	Fecb			py	2	asp	1			11/08/2010	CRB	diss asp
RI481556	534598	6844177	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim				py	2	asp	1			11/08/2010	CRB	diss asp + SH frag
RI481557	534593	6844175	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim				py	1	asp	2			11/08/2010	CRB	
RI481558	534595	6844174	Chip	2.0	OC	Sleeping Giant		QZVN		White			Fecb	Lim			py	2	asp	3	Au(vg)	0.1	11/08/2010	CRB	diss asp + SH frag and 1 grain of fine AU(vg)

RI481559	534596	6844173	Chip	2.0	OC	Sleeping Giant		QZVN		White			Fecb	Lim		py	2	asp	3			11/08/2010	CRB	diss asp + 8% SH frag
RI481560	534591	6844195	Chip	1.5	OC	Sleeping Giant		QZVN		White			Lim	Fecb		py	2	asp	1			11/08/2010	CRB	diss asp
RI481561	534589	6844186	Chip	1.7	OC	Sleeping Giant		QZVN		White			Lim	Fecb		py	2	asp	1			11/08/2010	CRB	diss asp
RI481562	534589	6844184	Chip	1.7	OC	Sleeping Giant		QZVN		White			Lim	Fecb		py	2	asp	2			11/08/2010	CRB	diss asp + SH frag
RI481563	534589	6844178	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	Fecb		py	2	asp	2			11/08/2010	CRB	diss asp; large grain masses
RI481564	534581	6844216	Chip	2.0	OC	Sleeping Giant		QZVN		White			Lim	cy		py	2	asp	2			12/08/2010	CRB	diss asp
RI481565	534646	6844190	Chip	1.0	OC	Sleeping Giant		QZVN		White			cy									12/08/2010	CRB	Not Collected
RI481566	534599	6844131	Chip	2.0	OC	Sleeping Giant		QZVN		White			cy	Fecb	lim	py	2	asp	1			12/08/2010	CRB	diss asp
RI481567	534601	6844130	Chip	2.0	OC	Sleeping Giant		QZVN		White			cy	Fecb		py	2	asp	1			12/08/2010	CRB	diss asp
RI481568	534602	6844130	Chip	2.0	OC	Sleeping Giant		QZVN		White			cy	Fecb	scr	py	3	asp	1			12/08/2010	CRB	diss asp +minor scr patches
RI481569	534603	6844129	Chip	2.0	OC	Sleeping Giant		QZVN		White			cy	scr		py	3	asp	0.5			12/08/2010	CRB	diss asp
RI481570	534620	6844096	Chip	2.0	OC	Sleeping Giant		QZVN		White			cy	scr		py	2	asp	4			12/08/2010	CRB	diss asp + SH frag
RI481571	534618	6844093	Chip	2.0	OC	Sleeping Giant		QZVN		White			cy	Lim	scr	py	2	asp	1			12/08/2010	CRB	diss asp + SH frag
RI481572	534618	6844091	Chip	2.0	OC	Sleeping Giant		QZVN		White			cy	scr		py	2	asp	3			12/08/2010	CRB	diss asp + SH frag
RI481573	534613	6844090	Chip	2.0	OC	Sleeping Giant		QZVN		White			cy	Lim		py	2	asp	1			12/08/2010	CRB	diss asp
RI481574	534615	6844090	Chip	2.0	OC	Sleeping Giant		QZVN		White			Fecb	cy	scr	py	3	asp	2			12/08/2010	CRB	diss asp + rare SH frag
RI481575	534616	6844089	Chip	2.0	OC	Sleeping Giant		QZVN		White			Fecb	cy	scr	py	3	asp	3			12/08/2010	CRB	diss asp
RI481576	534627	6844067	Chip	2.0	OC	Sleeping Giant		QZVN		White			Fecb	cy	scr	py	3	asp	1			12/08/2010	CRB	diss asp + SH frag
RI481577	534628	6844066	Chip	2.0	OC	Sleeping Giant		QZVN		White			cy			py	1	asp	0.1			12/08/2010	CRB	minor diss asp; Au(vg) was observerd in this rubble crop prior to sampling

All-Terrane Mineral Exploration Services

SOIL SAMPLE DESCRIPTION SHEET

2010 Program, 3-ACE Project
Northern Tiger Resources Inc.

Main Zone
Green Zone

Sample No.	Easting	Northing	Traverse	Horizon	Depth	Slope	Colour	Permafrost	% Coarse	Vegetation	Surficial	Fragment	%	Date	Sampler	Comments
	UTM Nad 83	UTM Nad 83	(Station)		(cm)	Angle		(yes/no?)	Fragments		Geology	Lithology	Organics			
N SMP	533190	6845778	4700E			S		N		Alpe				Aug 7,2010	CW	
N SMP	533135	6845787	4675E			S				Alpe				Aug 9,2010	CW	
N SMP	533203	6845960	4850E			S		N		Alpe			10	Aug 9,2010	CW	
SE296251	534037	6843915	TL4000/3500E	B	25	steep	orange/brown	No	15	mix			10	05-Jul	Craig	
SE296252	534050	6845934	3525E	B	20	steep	orange/brown	No	15	mix			10	05-Jul	Craig	
SE296253	534063	6845952	3550E	B	30	steep	brown	No	20	fir			10	05-Jul	Craig	
SE296254	534076	6845971	3575E	B	30	steep	orange/brown	No	25	fir			10	05-Jul	Craig	
SE296255	534090	6843990	3600E	B	25	steep	brown	No	15	fir			15	05-Jul	Craig	
SE296256	534103	6844014	3625E	B	30	moderate	brown	No	20	fir			5	05-Jul	Craig	
SE296257	534116	6844038	3650E	B	25	steep	brown	No	15	fir			5	05-Jul	Craig	
SE296258	534129	6844062	3675E	B	30	steep	brown	No	20	fir			5	05-Jul	Craig	
SE296259	534142	6844086	3700E	B	35	steep	brown	No	20	fir			10	05-Jul	Craig	
SE296260	534160	6844104	3725E	B	30	steep	brown	No	25	fir			10	05-Jul	Craig	
SE296261	534178	6844121	3750E	B	35	steep	brown	No	20	fir			5	05-Jul	Craig	
SE296262	534196	6844139	3775E	B	30	steep	brown	No	25	fir			10	05-Jul	Craig	
SE296263	534213	6844156	3800E	B	25	steep	brown	No	20	fir			5	05-Jul	Craig	
SE296264	534230	6844174	3825E	B	30	steep	orange/brown	No	25	fir			5	05-Jul	Craig	
SE296265	534247	6844192	3850E	B	20	moderate	brown	No	20	fir			10	05-Jul	Craig	
SE296266	534264	6844210	3875E	B	25	gentle	brown	No	30	fir			5	05-Jul	Craig	
SE296267	534280	6844229	3900E	B	25	steep	brown	No	20	mix			10	05-Jul	Craig	
SE296268	534297	6844248	3925E	B	25	steep	brown	No	25	mix			20	05-Jul	Craig	
SE296269	534314	6844266	3950E	B	20	steep	brown	No	20	mix			5	05-Jul	Craig	
SE296270	534331	6844285	3975E	B	25	steep	brown	No	15	mix			10	05-Jul	Craig	
SE296271	534347	6844303	4000E	B	20	steep	brown	No	25	mix			5	05-Jul	Craig	
SE296272	534025	6843895	3475E	B	25	steep	brown	No	20	mix			10	06-Jul	Craig	
SE296273	534013	6843875	3450E	B	20	steep	orange/brown	No	15	mix			5	06-Jul	Craig	
SE296274	534001	6843855	3425E	B	20	steep	orange/brown	No	15	mix			5	06-Jul	Craig	
SE296275	533989	6843835	3400E	B	25	moderate	orange/brown	No	20	mix			5	06-Jul	Craig	
SE296276	533975	6843814	3375E	B	20	moderate	tan	No	20	mix			5	06-Jul	Craig	
SE296277	533960	6843793	3350E	B	25	moderate	tan	No	25	mix			10	06-Jul	Craig	
SE296278	533946	6843772	3325E	B	20	moderate	brown	No	20	mix			5	06-Jul	Craig	
SE296279	533931	6843751	3300E	B	25	moderate	tan	No	20	mix			5	06-Jul	Craig	
SE296280	533917	6843729	3275E	B	20	moderate	orange/brown	No	25	mix			5	06-Jul	Craig	
SE296281	533903	6843707	3250E	B	25	moderate	orange/brown	No	20	mix			15	06-Jul	Craig	
SE296282	533889	6843685	3225E	B	20	moderate	brown	No	15	mix			5	06-Jul	Craig	
SE296283	533876	6843663	3200E	B	25	moderate	brown	No	20	mix			5	06-Jul	Craig	
SE296284	533859	6843643	3175E	B	20	gentle	brown	No	20	mix			10	06-Jul	Craig	
SE296285	533842	6843624	3150E	B	30	gentle	orange/brown	No	15	mix			5	06-Jul	Craig	
SE296286	533825	6843604	3125E	B	25	moderate	orange/brown	No	25	mix			5	06-Jul	Craig	
SE296287	533809	6843585	3100E	B	20	moderate	orange/brown	No	20	mix			5	06-Jul	Craig	
SE296288	533793	6843562	3075E	B	25	moderate	orange/brown	No	25	mix			10	06-Jul	Craig	
SE296289	533777	6843540	3050E	B	20	moderate	brown	No	20	mix			5	06-Jul	Craig	
SE296290	533761	6843518	3025E	B	25	moderate	grey/brown	No	20	mix			5	06-Jul	Craig	
SE296291	533745	6843496	3000E	B	20	moderate	brown	No	25	mix			5	06-Jul	Craig	
SE296292	533855	6843677	3200E/4025N	B	20	steep	brown	No	20	mix			10	06-Jul	Craig	
SE296293	533834	6843692	4050N	B	25	steep	orange/brown	No	25	mix			5	06-Jul	Craig	

SE296294	533813	6843706	4075N	B	20	steep	brown	No	20	mix			5	06-Jul	Craig	
SE296295	533792	6843721	4100N	B	25	steep	red/brown	No	25	alpine			5	06-Jul	Craig	
SE296296	533772	6843737	4125N	B	20	steep	brown	No	30	alpine			5	06-Jul	Craig	
SE296297	533751	6843752	4150N	B	25	steep	brown	No	20	alpine			10	06-Jul	Craig	
SE296298	533731	6843768	4175N	B	20	steep	tan	No	20	alpine			10	06-Jul	Craig	
SE296299	533710	6843783	4200N	B	25	steep	brown	No	25	alpine			5	06-Jul	Craig	
SE296300	533691	6843798	4225N	B	20	steep	brown	No	20	alpine			5	06-Jul	Craig	
SE296301	533671	6843813	4250N	B	25	steep	brown	No	25	alpine			5	06-Jul	Craig	
SE296302	533651	6843828	4275N	B	20	steep	orange/brown	No	20	alpine			5	06-Jul	Craig	
SE296303	533631	6843842	4300N	B	25	steep	brown	No	30	alpine			5	06-Jul	Craig	
SE296304	533612	6843858	4325N	B	25	steep	brown	No	25	alpine			5	06-Jul	Craig	
SE296305	533593	6843874	4350N	B	20	steep	brown	No	20	alpine			5	06-Jul	Craig	
SE296306	533574	6843890	4375N	B	20	steep	orange/brown	No	20	alpine			10	06-Jul	Craig	
SE296307	533555	6843907	4400N	B	20	steep	orange/brown	No	25	alpine			5	06-Jul	Craig	
SE296308	533536	6843924	4425N	B	20	steep	brown	No	20	alpine			5	06-Jul	Craig	
SE296309	533517	6843941	4450N	B	25	steep	orange/brown	No	25	alpine			5	06-Jul	Craig	
SE296310	533645	6843830	4280N/3200E	B	20	steep	brown	No	10	alpine			10	07-Jul	Craig	
SE296311	533641	6843821	3190E	B	20	steep	light brown	No	20	alpine			5	07-Jul	Craig	
SE296312	533637	6843812	3180E	B	25	steep	orange/brown	No	20	alpine			5	07-Jul	Craig	
SE296313	533633	6843803	3170E	B	25	steep	orange/brown	No	20	alpine			5	07-Jul	Craig	
SE296314	533629	6843794	3160E	B	20	steep	orange/brown	No	25	alpine			5	07-Jul	Craig	
SE296315	533625	6843785	3150E	B	25	steep	brown	No	20	alpine			10	07-Jul	Craig	
SE296316	533618	6843792	4290N/3150E	B	20	steep	orange/brown	No	20	alpine			5	07-Jul	Craig	
SE296317	533623	6843800	3160E	B	25	steep	orange/brown	No	20	alpine			5	07-Jul	Craig	
SE296318	533628	6843809	3170E	B	20	steep	orange/brown	No	15	alpine			5	07-Jul	Craig	
SE296319	533633	6843817	3180E	B	25	steep	orange/brown	No	20	alpine			5	07-Jul	Craig	
SE296320	533638	6843826	3190E	B	20	steep	orange/brown	No	20	alpine			5	07-Jul	Craig	
SE296321	533642	6843834	3200E	B	25	steep	orange/brown	No	20	alpine			5	07-Jul	Craig	
SE296338	533668	6843803	4250N/3190E	B	25	steep	brown	No	30	alpine			5	09-Jul	Craig	
SE296339	533663	6843796	3180E	B	20	steep	brown	No	20	alpine			5	09-Jul	Craig	
SE296340	533658	6843788	3170E	B	20	steep	orange/brown	No	20	alpine			5	09-Jul	Craig	
SE296341	533654	6843781	3160E	B	25	steep	tan	No	20	alpine			5	09-Jul	Craig	
SE296342	533649	6843773	3150E	B	20	steep	brown	No	14	alpine			5	09-Jul	Craig	
SE296343	533656	6843767	4240N/3150E	B	25	steep	brown	No	30	alpine			5	09-Jul	Craig	
SE296344	533660	6843775	3160E	B	25	steep	brown	No	20	alpine			10	09-Jul	Craig	
SE296345	533664	6843783	3170E	B	20	steep	tan	No	20	alpine			5	09-Jul	Craig	
SE296346	533668	6843791	3180E	B	25	steep	brown	No	20	alpine			5	09-Jul	Craig	
SE296347	533672	6843799	3190E	B	15	steep	brown	No	40	alpine			5	09-Jul	Craig	
SE296348	533677	6843808	3200E	B	20	steep	brown	No	40	alpine			10	09-Jul	Craig	
SE296349	533682	6843815	3210E	B	25	steep	brown	No	20	alpine			5	09-Jul	Craig	
SE296350	533688	6843822	3220E	B	20	steep	brown	No	20	alpine			5	09-Jul	Craig	
SE296351	533693	6843829	3230E	B	15	steep	brown	No	20	alpine			5	09-Jul	Craig	
SE296352	533699	6843836	3240E	B	20	steep	brown	No	15	alpine			5	09-Jul	Craig	
SE296353	533705	6843842	3250E	B	25	steep	orange/brown	No	20	alpine			5	09-Jul	Craig	
SE296354	533696	6843849	4250N/3250E	B	20	steep	brown	No	20	alpine			10	09-Jul	Craig	
SE296355	533691	6843841	3240E	B	25	steep	tan	No	20	alpine			5	09-Jul	Craig	
SE296356	533687	6843834	3230E	B	20	steep	tan	No	15	alpine			5	09-Jul	Craig	
SE296357	533682	6843826	3220E	B	25	steep	brown	No	20	alpine			10	09-Jul	Craig	
SE296358	533677	6843819	3210E	B	20	steep	brown	No	25	alpine			10	09-Jul	Craig	
SE296359	533664	6843764	4230N/3150E	B	25	steep	brown	No	20	alpine			10	09-Jul	Craig	
SE296360	533668	6843771	3160E	B	20	steep	brown	No	20	alpine			5	09-Jul	Craig	
SE296361	533672	6843778	3170E	B	20	steep	brown	No	15	alpine			5	09-Jul	Craig	
SE296362	533676	6843785	3180E	B	20	steep	red/brown	No	20	alpine			5	09-Jul	Craig	
SE296363	533680	6843792	3190E	B	15	steep	brown	No	20	alpine			5	09-Jul	Craig	
SE296364	533685	6843800	3200E	B	20	steep	brown	No	25	alpine			5	09-Jul	Craig	
SE296365	533690	6843806	3210E	B	25	steep	brown	No	25	alpine			5	09-Jul	Craig	
SE296366	533695	6843812	3220E	B	20	steep	brown	No	20	alpine			5	09-Jul	Craig	
SE296367	533700	6843819	3230E	B	25	steep	brown	No	40	alpine			5	09-Jul	Craig	
SE296368	533705	6843826	3240E	B	15	steep	tan	No	15	alpine			5	09-Jul	Craig	
SE296369	533709	6843833	3250E	B	20	steep	tan	No	20	alpine			5	09-Jul	Craig	
SE296370	533493	6843954	3200E/4475N	B	20	steep	tan	No	20	alpine			5	10-Jul	Craig	

SE296371	533469	6843967	4500N	B	25	steep	brown	No	15	alpine			5	10-Jul	Craig	
SE296372	533445	6843980	4525N	B	20	steep	brown	No	20	alpine			5	10-Jul	Craig	
SE296373	533421	6843993	4550N	B	25	steep	tan	No	10	alpine			5	10-Jul	Craig	
SE296374	533397	6844006	4575N	B	20	steep	tan	No	20	alpine			10	10-Jul	Craig	
SE296375	533287	6843884	TL4600N/3025E	B	30	steep	tan	No	20	alpine			10	10-Jul	Craig	
SE296376	533301	6843904	3050E	B	20	steep	brown	No	20	alpine			5	10-Jul	Craig	
SE296377	533315	6843924	3075E	B	20	steep	red/brown	No	20	alpine			5	10-Jul	Craig	
SE296378	533329	6843944	3100E	B	25	steep	orange/brown	No	25	alpine			10	10-Jul	Craig	
SE296379	533343	6843964	3125E	B	20	steep	brown	No	30	alpine			5	10-Jul	Craig	
SE296380	533357	6843985	3150E	B	20	steep	brown	No	20	alpine			10	10-Jul	Craig	
SE296381	533371	6844005	3175E	B	25	steep	brown	No	25	alpine			10	10-Jul	Craig	
SE296382	533384	6844026	3200E	B	20	steep	brown	No	40	alpine			5	10-Jul	Craig	
SE296383	533400	6844046	3225E	B	15	steep	brown	No	20	alpine			10	10-Jul	Craig	
SE296384	533416	6844066	3250E	B	20	steep	brown	No	20	alpine			5	10-Jul	Craig	
SE296385	533432	6844086	3275E	B	25	steep	orange/brown	No	30	alpine			5	10-Jul	Craig	
SE296386	533447	6844107	3300E	B	20	steep	orange/brown	No	25	none	oc		10	10-Jul	Craig	
SE296387	533459	6844129	3325E	B	15	steep	brown	No	20	none	oc		5	10-Jul	Craig	
SE296388	533471	6844151	3350E	B	20	steep	tan	No	20	none	oc		5	10-Jul	Craig	
SE296389	533483	6844173	3375E	B	25	moderate	brown	No	20	alpine			5	10-Jul	Craig	
SE296390	533496	6844195	3400E	B	20	gentle	brown	No	15	alpine			10	10-Jul	Craig	
SE296391	533510	6844214	3425E	B	25	moderate	brown	No	15	alpine			10	10-Jul	Craig	
SE296392	533527	6844233	3450E	B	30	moderate	brown	No	20	alpine			10	10-Jul	Craig	
SE296393	533543	6844252	3475E	B	30	steep	brown	No	25	alpine			5	10-Jul	Craig	
SE296394	533560	6844272	3500E	B	20	F	light brown	No	20	alpine			5	10-Jul	Craig	
SE296395	533576	6844293	3525E	B	20	steep	tan	No	10	alpine			5	10-Jul	Craig	
SE296396	533592	6844313	3550E	B	25	steep	brown	No	20	alpine			5	10-Jul	Craig	
SE296397	533608	6844334	3575E	B	20	moderate	brown	No	20	alpine			10	12-Jul	Craig	
SE296398	533623	6844354	3600E	B	20	moderate	brown	No	20	alpine			5	12-Jul	Craig	
SE296399	533644	6844376	3625E	B	25	moderate	brown	No	20	alpine			5	12-Jul	Craig	
SE296400	533665	6844398	3650E	B	20	moderate	grey/brown	No	20	alpine			5	12-Jul	Craig	
SE296401	533686	6844420	3675E	B	30	moderate	brown	No	15	alpine			5	12-Jul	Craig	
SE296402	533678	6844439	3700E	B	30	steep	brown	No	20	alpine			10	12-Jul	Craig	
SE296403	533691	6844461	3725E	B	30	steep	brown	No	10	alpine			5	12-Jul	Craig	
SE296404	533704	6844483	3750E	B	25	steep	brown	No	20	alpine			5	12-Jul	Craig	
SE296405	533717	6844505	3775E	B	20	steep	brown	No	20	alpine			10	12-Jul	Craig	
SE296406	533731	6844527	3800E	B	25	steep	brown	No	25	alpine			5	12-Jul	Craig	
SE296407	533744	6844547	3825E	B	30	steep	brown	No	20	alpine			10	12-Jul	Craig	
SE296408	533757	6844567	3850E	B	20	steep	brown	No	30	alpine			5	12-Jul	Craig	
SE296409	533770	6844587	3875E	B	25	steep	tan	No	25	alpine			5	12-Jul	Craig	
SE296410	533783	6844607	3900E	B	25	steep	brown	No	20	alpine			5	12-Jul	Craig	
SE296411	533797	6844628	3925E	B	20	steep	tan	No	15	alpine			5	12-Jul	Craig	
SE296412	533811	6844649	3950E	B	25	steep	brown	No	20	alpine			5	12-Jul	Craig	
SE296413	533825	6844670	3975E	B	25	moderate	brown	No	20	alpine			5	12-Jul	Craig	
SE296414	533839	6844691	4000E	B	20	steep	brown	No	20	alpine			10	12-Jul	Craig	
SE296415	534343	6844314	4600E/4025N	B	25	steep	orange/brown	No	20	mix			10	12-Jul	Craig	
SE296416	534320	6844331	4050N	B	20	steep	orange/brown	No	25	mix			5	12-Jul	Craig	
SE296417	534297	6844348	4075N	B	25	steep	brown	No	20	mix			10	12-Jul	Craig	
SE296418	534274	6844365	4100N	B	20	steep	orange/brown	No	15	mix			5	12-Jul	Craig	
SE296419	534251	6844382	4125N	B	25	steep	orange/brown	No	15	mix			5	12-Jul	Craig	
SE296420	534229	6844400	4150N	B	20	steep	brown	No	20	mix			5	12-Jul	Craig	
SE296421	534206	6844417	4175N	B	25	steep	brown	No	20	mix			5	12-Jul	Craig	
SE296422	534184	6844435	4200N	B	20	steep	brown	No	15	mix			15	12-Jul	Craig	
SE296423	534162	6844450	4225N	B	20	steep	tan	No	20	mix			5	12-Jul	Craig	
SE296424	534140	6844465	4250N	B	25	moderate	orange/brown	No	20	mix			5	12-Jul	Craig	
SE296425	534118	6844480	4275N	B	20	steep	brown	No	15	mix			5	12-Jul	Craig	
SE296426	534096	6844494	4300N	B	25	steep	tan	No	20	mix			5	12-Jul	Craig	
SE296427	534075	6844510	4325N	B	20	steep	brown	No	20	alpine			10	12-Jul	Craig	
SE296428	534053	6844526	4350N	B	25	steep	brown	No	20	alpine			5	12-Jul	Craig	
SE296429	534031	6844542	4375N	B	25	steep	brown	No	30	alpine			5	12-Jul	Craig	
SE296430	534009	6844557	4400N	B	25	steep	brown	No	25	alpine			5	12-Jul	Craig	
SE296431	533988	6844573	4425N	B	20	steep	brown	No	20	alpine			5	12-Jul	Craig	

SE296432	533967	6844590	4450N	B	25	steep	brown	No	15	alpine			5	12-Jul	Craig	
SE296433	533946	6844607	4475N	B	20	steep	brown	No	20	alpine			10	12-Jul	Craig	
SE296434	533925	6844623	4500N	B	25	steep	brown	No	20	alpine			5	12-Jul	Craig	
SE296435	533904	6844639	4525N	B	25	steep	brown	No	25	alpine			5	12-Jul	Craig	
SE296436	533883	6844655	4550N	B	20	steep	brown	No	25	alpine			5	12-Jul	Craig	
SE296437	533862	6844671	4575N	B	30	steep	brown	No	25	alpine			5	12-Jul	Craig	
SE296438	533799	6844570	3900E/4575N	B	30	steep	brown	No	20	alpine			10	13-Jul	Craig	
SE296439	533821	6844558	4550N	B	25	steep	brown	No	20	alpine			5	13-Jul	Craig	
SE296440	533843	6844546	4525N	B	20	steep	orange/brown	No	20	alpine			5	13-Jul	Craig	
SE296441	533865	6844534	4500N	B	25	steep	brown	No	15	alpine			5	13-Jul	Craig	
SE296442	533887	6844522	4475N	B	15	steep	brown	No	25	alpine			5	13-Jul	Craig	
SE296443	533909	6844509	4450N	B	20	steep	brown	No	20	alpine			10	13-Jul	Craig	
SE296444	533931	6844497	4425N	B	30	steep	tan	No	25	alpine			5	13-Jul	Craig	
SE296445	533952	6844484	4400N	B	25	steep	orange/brown	No	25	alpine			5	13-Jul	Craig	
SE296446	533971	6844431	4375N	B	20	steep	orange/brown	No	15	alpine			5	13-Jul	Craig	
SE296447	533989	6844419	4350N	B	30	steep	orange/brown	No	20	alpine			5	13-Jul	Craig	
SE296448	534008	6844407	4325N	B	20	steep	orange/brown	No	20	alpine			10	13-Jul	Craig	
SE296449	534026	6844395	4300N	B	25	steep	tan	No	25	alpine			10	13-Jul	Craig	
SE296450	534046	6844378	4275N	B	30	steep	brown	No	20	alpine			5	13-Jul	Craig	
SE296451	534066	6844360	4250N	B	25	steep	brown	No	25	fir			5	13-Jul	Craig	
SE296452	534086	6844343	4225N	B	20	steep	brown	No	30	fir			5	13-Jul	Craig	
SE296453	534106	6844325	4200N	B	25	steep	tan	No	20	fir			5	13-Jul	Craig	
SE296454	534127	6844313	4175N	B	20	steep	brown	No	20	fir			10	13-Jul	Craig	
SE296455	534148	6844302	4150N	B	20	steep	brown	No	25	fir			5	13-Jul	Craig	
SE296456	534169	6844291	4125N	B	25	steep	brown	No	20	fir			5	13-Jul	Craig	
SE296457	534190	6844280	4100N	B	20	steep	brown	No	25	fir			5	13-Jul	Craig	
SE296458	534211	6844269	4075N	B	25	steep	brown	No	20	fir			5	13-Jul	Craig	
SE296459	534232	6844258	4050N	B	20	steep	brown	No	15	fir			10	13-Jul	Craig	
SE296460	534253	6844247	4025N	B	20	steep	brown	No	25	fir			5	13-Jul	Craig	
SE296461	534112	6844095	3700E/4025N	B	25	steep	brown	No	20	fir			5	13-Jul	Craig	
SE296462	534095	6844110	4050N	B	20	steep	brown	No	25	fir			5	13-Jul	Craig	
SE296463	534078	6844125	4075N	B	25	steep	brown	No	25	alpine			10	13-Jul	Craig	
SE296464	534061	6844140	4100N	B	20	steep	orange/brown	No	20	alpine			5	13-Jul	Craig	
SE296465	534044	6844155	4125N	B	20	steep	tan	No	25	alpine			5	13-Jul	Craig	
SE296466	534027	6844170	4150N	B	25	steep	brown	No	25	alpine			5	13-Jul	Craig	
SE296467	534010	6844185	4175N	B	20	steep	orange/brown	No	20	alpine			10	13-Jul	Craig	
SE296468	533993	6844201	4200N	B	25	steep	brown	No	15	alpine			5	13-Jul	Craig	
SE296469	533974	6844217	4225N	B	20	steep	brown	No	25	alpine			10	13-Jul	Craig	
SE296470	533956	6844233	4250N	B	25	steep	brown	No	20	alpine			10	13-Jul	Craig	
SE296471	533938	6844249	4275N	B	20	steep	brown	No	25	alpine			5	13-Jul	Craig	
SE296472	533920	6844265	4300N	B	25	steep	brown	No	20	alpine			5	13-Jul	Craig	
SE296473	533900	6844280	4325N	B	20	steep	red/brown	No	15	alpine			5	13-Jul	Craig	
SE296474	533881	6844295	4350N	B	20	moderate	red/brown	No		alpine			5	13-Jul	Craig	
SE296475	533861	6844310	4375N	B	25	moderate	red/brown	No		alpine			10	13-Jul	Craig	
SE296476	533842	6844325	4400N	B	20	moderate	brown	No		alpine			5	13-Jul	Craig	
SE296477	533823	6844340	4425N	B	20	moderate	orange/brown	No		alpine			5	13-Jul	Craig	
SE296478	533804	6844355	4450N	B	25	moderate	tan	No		alpine			10	13-Jul	Craig	
SE296479	533785	6844370	4475N	B	20	gentle	orange/brown	No		alpine			10	13-Jul	Craig	
SE296480	533721	6843510	3000E/4025N	B	20	moderate	brown	No	25	alpine			10	14-Jul	Craig	
SE296481	533702	6843526	4050N	B	25	moderate	orange/brown	No	20	alpine			5	14-Jul	Craig	
SE296482	533683	6843542	4075N	B	20	steep	brown	No	20	alpine			5	14-Jul	Craig	
SE296483	533664	6843558	4100N	B	25	steep	brown	No	25	alpine			10	14-Jul	Craig	
SE296484	533645	6843574	4125N	B	20	steep	orange/brown	No	20	alpine			5	14-Jul	Craig	
SE296485	533627	6843591	4150N	B	20	steep	brown	No	15	alpine			5	14-Jul	Craig	
SE296486	533608	6843607	4175N	B	25	steep	orange/brown	No	20	alpine			5	14-Jul	Craig	
SE296487	533590	6843624	4200N	B	20	steep	brown	No	20	mix			10	14-Jul	Craig	
SE296488	533571	6843640	4225N	B	20	steep	orange/brown	No	15	mix			5	14-Jul	Craig	
SE296489	533553	6843656	4250N	B	20	steep	orange/brown	No	15	mix			5	14-Jul	Craig	
SE296490	533535	6843672	4275N	B	25	steep	orange/brown	No	20	mix			5	14-Jul	Craig	
SE296491	533516	6843689	4300N	B	20	steep	orange/brown	No	15	mix			5	14-Jul	Craig	
SE296492	533498	6843707	4325N	B	25	steep	orange/brown	No	20	mix			10	14-Jul	Craig	

SE296493	533479	6843725	4350N	B	20	steep	orange/brown	No	25	mix			5	14-Jul	Craig	
SE296494	533460	6843743	4375N	B	20	steep	orange/brown	No	20	mix			5	14-Jul	Craig	
SE296495	533441	6843761	4400N	B	25	steep	orange/brown	No	20	mix			10	14-Jul	Craig	
SE296496	533423	6843778	4425N	B	25	steep	brown	No	30	mix			10	14-Jul	Craig	
SE296497	533404	6843795	4450N	B	20	steep	brown	No	20	mix			5	14-Jul	Craig	
SE296498	533386	6843812	4475N	B	20	steep	brown	No	35	mix			5	14-Jul	Craig	
SE296499	533367	6843829	4500N	B	45	steep	brown	No	40	mix			10	14-Jul	Craig	
SE296500	533347	6843844	4525N	B	20	steep	tan	No	20	mix			10	14-Jul	Craig	
SG312315	532921	6846096	L6050N, 4775E	B	50	40	brown	N	5	tundra			0	15/08/2010	ML	
SG312316	532906	6846073	L6050N, 4750E	B	40	30	brown	N	5	tundra			0	15/08/2010	ML	
SG312317	532891	6846050	L6050N, 4725E	B	20	30	brown	N	20	tundra			5	15/08/2010	ML	Rocky
SG312318	532876	6846027	L6050N, 4700E	B	30	30	brown	N	10	tundra			5	15/08/2010	ML	Rocky
SG312319	532861	6846004	L6050N, 4675E	B	30	30	brown	N	5	tundra			5	15/08/2010	ML	Rocky
SG312320	532846	6845980	L6050N, 4650E	B	50	25	brown	N	5	tundra			5	15/08/2010	ML	Rocky
SG312321	532831	6845956	L6050N, 4625E	B	30	20	brown	N	5	tundra			5	15/08/2010	ML	
SG312322	532816	6845933	L6050N, 4600E	B	40	25	brown	N	5	tundra			5	15/08/2010	ML	
SG312323	532799	6845915	L6050N, 45750E	B	50	10	brown	N	5	tundra			0	15/08/2010	ML	
SG312324	532783	6845897	L6050N, 4550E	B	50	5	brown	N	5	tundra			0	15/08/2010	ML	
SG312325	532827	6845876	L6000N, 4550E	B	30	5	brown	N	5	tundra			0	15/08/2010	ML	
SG312326	532843	6845892	L6000N, 4575E	B	50	15	orange	N	10	tundra			0	15/08/2010	ML	
SG312327	532859	6845908	L6000N, 4600E	B	50	20	orange	N	5	tundra			0	15/08/2010	ML	
SG312328	532875	6845928	L6000N, 4625E	B	50	30	brown	N	5	tundra			0	15/08/2010	ML	
SG312329	532891	6845948	L6000N, 4650E	B	40	30	brown	N	20	tundra			5	15/08/2010	ML	Rocky
SG312330	532907	6845968	L6000N, 4675E	B	50	30	brown	N	10	tundra			5	15/08/2010	ML	Rocky
SG312331	532922	6845988	L6000N, 4700E	B	40	40	orange	N	5	tundra				15/08/2010	ML	Rocky
SG312332	532936	6846008	L6000N, 4725E	B	40	40	brown	N	10	tundra			5	15/08/2010	ML	Rocky
SG312333	532951	6846029	L6000N, 4750E	B	50	40	or/brn	N	5	tundra				15/08/2010	ML	Rocky
SG312334	532966	6846049	L6000N, 4775E	B	50	40	brown	N	10	tundra			10	15/08/2010	ML	
SG312335	532980	6846070	L6000N, 4800E	B	50	40	or/brn	N	5	tundra			5	15/08/2010	ML	Rocky
SG312336	532996	6846090	L6000N, 4825E	B	10	30	or/brn	N	20	tundra			5	15/08/2010	ML	Rocky
SG312337	533012	6846110	L6000N, 4850E	B	10	30	grey	N	50	tundra			10	15/08/2010	ML	Rocky
SG312338	533028	6846130	L6000N, 4875E	B	5	30	brown	N	30	tundra			30	15/08/2010	ML	Rocky
SG312339	533043	6846149	L6000N, 4900E	B	5	40	brown	N	30	tundra			30	15/08/2010	ML	Rocky
SG312340	533072	6846190	L6000N, 4950E	B	5	50	brown	N	30	tundra			5	15/08/2010	ML	Rocky
SG312341	533086	6846210	L6000N, 4975E	B	5	60	or/brn	N	30	tundra			10	15/08/2010	ML	Cliff
SG312342	533100	6846230	L6000N, 5000E	B	5	60	brown	N	50	tundra			10	15/08/2010	ML	Rocky
SG312343	533116	6846249	L6000N, 5025E	B	15	30	brown	N	20	tundra			5	15/08/2010	ML	Rocky
SG312344	533149	6846288	L6000N, 5075E	B	20	25	grey	N	5	tundra				15/08/2010	ML	
SG312345	533165	6846307	L6000N, 5100E	B	30	30	grey	N	15	tundra			5	15/08/2010	ML	
SG312346	533181	6846326	L6000N, 5125E	B	30	20	grey	N	10	tundra			5	15/08/2010	ML	
SG312347	533197	6846345	L6000N, 5150E	B	30	20	brown	N	10	tundra			5	15/08/2010	ML	
SG312348	532941	6846096	L6050N, 4800E	B	30	40	brown	N	5	tundra			2	16/08/2010	ML	
SG312349	532957	6846117	L6050N, 4825E	B	10	35	grey	N	30	tundra				16/08/2010	ML	slide
SG312350	532973	6846138	L6050N, 4850E	B	20	30	grey	N	20	tundra			2	16/08/2010	ML	Rocky
SG312351	532989	6846159	L6050N, 4875E	B	50	25	brown	N	10	tundra			2	16/08/2010	ML	Rocky
SG312352	533005	6846179	L6050N, 4900E	B	10	30	brown	N	10	tundra			2	16/08/2010	ML	Rocky
SG312353	533022	6846198	L6050N, 4925E	C	5	30	brown	N	10	tundra			5	16/08/2010	ML	Rocky
SG312354	533039	6846217	L6050N, 4950E	C	5	30	brown	N	10	tundra			40	16/08/2010	ML	Rocky
SG312355	533056	6846236	L6050N, 4975E	C	5	30	orange	N	40	tundra				16/08/2010	ML	Rocky
SG312356	533073	6846254	L6050N, 5000E	C	5	30	orange	N	40	tundra			2	16/08/2010	ML	Rocky
SG312357	533086	6846274	L6050N, 5025E	B	10	20	brown	N	30	tundra				16/08/2010	ML	Rocky
SG312358	533100	6846295	L6050N, 5050E	B	5	10	brown	N	30	tundra			2	16/08/2010	ML	Rocky
SG312359	533113	6846315	L6050N, 5075E	B	30	20	grey	N	10	grass			2	16/08/2010	ML	Rocky
SG312360	533127	6846336	L6050N, 5100E	B	40	20	grey	N	10	tundra			5	16/08/2010	ML	
SG312361	533141	6846357	L6050N, 5125E	B	40	10	grey	N	10	tundra				16/08/2010	ML	
SG312362	533155	6846380	L6050N, 5150E	B	40	10	grey	N	5	tundra				16/08/2010	ML	
SG312363	533184	6846426	L6050N, 5200E	B	40	20	grey	N	5	tundra				16/08/2010	ML	Rocky
SG312364	533200	6846442	L6050N, 5225E	B	40	20	brown	N	10	tundra				16/08/2010	ML	
SG312365	533216	6846458	L6050N, 5250E	B	40	20	grey	N	10	grass			5	16/08/2010	ML	
SG312366	533232	6846474	L6050N, 5275E	B	30	20	gry/brown	N	5	grass			5	16/08/2010	ML	
SG312367	533248	6846491	L6050N, 5300E	B	40	40	gry/brown	N	5	mossy			5	16/08/2010	ML	

SG312368	533263	6846511	L6050N, 5325E	B	30	20	gry/brown	N	5	grass			5	16/08/2010	ML	
SG312369	533278	6846532	L6050N, 5350E	B	30	10	gry/brown	N	5	grass			5	16/08/2010	ML	
SG312370	533293	6846553	L6050N, 5375E	B	20	30	gry/brown	N	10	grass				16/08/2010	ML	Side of stream
SG312371	533307	6846574	L6050N, 5400E	B	30	40	gry/brown	N	5	grass			5	16/08/2010	ML	End of line
SG312372	533314	6846507	L6000N, 5350E	B	30	20	gry/brown	N	5	grass			5	16/08/2010	ML	
SG312373	533295	6846480	L6000N, 5325E	B	30	20	gry/brown	N	10	grass			5	16/08/2010	ML	
SG312374	533275	6846452	L6000N, 5300E	B	30	50	gry/brown	N	10	grass			5	16/08/2010	ML	
SG312375	533255	6846424	L6000N, 5275E	B	30	30	gry/brown	N	5	grass			5	16/08/2010	ML	
SG312376	533245	6846413	L6000N, 5250E	B	20	30	gry/brown	N	10	grass			5	16/08/2010	ML	
SG312377	533226	6846392	L6000N, 5200E	B	5	40	brown	N	10				5	16/08/2010	ML	Rock field
SG312378	533214	6846378	L6000N, 5170E	B	5	20	brown	N	5					16/08/2010	ML	Rock field
SG312379	533364	6844809	L3800E, 5075N	B	20	20	brown	N	5	tundra			5	17/08/2010	ML	
SG312380	533384	6844794	L3800E, 5050N	B	20	20	brown	N		grass			5	17/08/2010	ML	
SG312381	533404	6844779	L3800E, 5025N	B	50	20	brown	N	2	tundra				17/08/2010	ML	
SG312382	533424	6844764	L3800E, 5000N	B	40	15	brown	N	2	tundra				17/08/2010	ML	
SG312383	533444	6844748	L3800E, 4975N	B	50	20	brown	N	2	tundra				17/08/2010	ML	
SG312384	533465	6844733	L3800E, 4950N	B	20	10	brown	N	5	tundra				17/08/2010	ML	
SG312385	533485	6844718	L3800E, 4925N	B	10	15	brown	N	5	tundra			5	17/08/2010	ML	
SG312386	533506	6844703	L3800E, 4900N	B	20	20	gry/brown	N	5	tundra				17/08/2010	ML	
SG312387	533526	6844689	L3800E, 4875N	B	30	10	brown	N	5	tundra				17/08/2010	ML	
SG312388	533545	6844674	L3800E, 4850N	B	30	10	brown	N	5	tundra				17/08/2010	ML	
SG312389	533565	6844659	L3800E, 4825N	B	30	5	brown	N	5	tundra				17/08/2010	ML	
SG312390	533584	6844644	L3800E, 4800N	B	20	5	brown	N	5	tundra			5	17/08/2010	ML	
SG312391	533604	6844628	L3800E, 4775N	B	30	10	brown	N	5	tundra			5	17/08/2010	ML	
SG312392	533624	6844612	L3800E, 4750N	B	30	10	brown	N	5	tundra			5	17/08/2010	ML	
SG312393	533644	6844596	L3800E, 4725N	B	10	30	brown	N	20	tundra			5	17/08/2010	ML	
SG312394	533664	6844579	L3800E, 4700N	B	20	40	brown	N	5	tundra				17/08/2010	ML	
SG312395	533684	6844562	L3800E, 4675N	B	10	15	brown	N	10	tundra				17/08/2010	ML	
SG312396	533704	6844545	L3800E, 4650N	B	20	5	brown	N	5	tundra			5	17/08/2010	ML	
SG312397	533724	6844528	L3800E, 4625N	B	30	5	brown	N	10	tundra			5	17/08/2010	ML	
SG312398	532861	6846154	L6150N, 4800E	B	30	30	grey	N	50	tundra				18/08/2010	ML	
SG312399	532877	6846177	L6150N, 4825E	B	30	30	grey	N	30	tundra				18/08/2010	ML	Rocky
SG312400	532893	6846200	L6150N, 4850E	B	20	40	grey	N	50	tundra				18/08/2010	ML	Rocky
SG312401	532909	6846223	L6150N, 4875E	B	10	40	brown	N	10	tundra				18/08/2010	ML	Rocky
SG312402	532924	6846247	L6150N, 4900E	B	20	30	brown	N	5	tundra				18/08/2010	ML	Rocky
SG312403	532938	6846266	L6150N, 4925E	B	10	40	grey	N	25	tundra				18/08/2010	ML	Rocky
SG312404	532953	6846285	L6150N, 4950E	B	10	40	grey	N	25	tundra				18/08/2010	ML	Rocky
SG312405	532968	6846304	L6150N, 4975E	B	20	30	grey	N	20	tundra				18/08/2010	ML	Rocky
SG312406	532982	6846323	L6150N, 5000E	B	30	30	grey	N	20	tundra				18/08/2010	ML	Rocky
SG312407	532997	6846343	L6150N, 5025E	B	40	30	grey	N	10	tundra				18/08/2010	ML	Rocky
SG312408	533012	6846362	L6150N, 5050E	B	10	30	grey	N	30	tundra				18/08/2010	ML	Rock field
SG312409	533028	6846382	L6150N, 5075E	B	20	20	brown	N	10	tundra				18/08/2010	ML	Rock field
SG312410	533043	6846402	L6150N, 5100E	B	30	25	grey	N	20	tundra				18/08/2010	ML	
SG312411	533060	6846421	L6150N, 5125E	B	30	20	grey	N	10	tundra				18/08/2010	ML	
SG312412	533075	6846440	L6150N, 5150E	B	40	40	grey	N	5	tundra				18/08/2010	ML	
SG312413	533091	6846460	L6150N, 5175E	B	30	40	brown	N	5	tundra				18/08/2010	ML	
SG312414	533106	6846480	L6150N, 5200E	B	10	30	brown	N		fir			5	18/08/2010	ML	
SG312415	533122	6846499	L6150N, 5225E	B	20	40	brown	N	10	fir			5	18/08/2010	ML	Cliff
SG312416	533137	6846519	L6150N, 5250E	B	10	5	brown	N	20	tundra			2	18/08/2010	ML	
SG312417	533153	6846538	L6150N, 5275E	B	20	40	brown	N	10	tundra			5	18/08/2010	ML	Rocky
SG312418	533168	6846558	L6150N, 5300E	B	20	20	grey	N	20	tundra				18/08/2010	ML	Rocky
SG312419	533184	6846578	L6150N, 5325E	B	20	20	grey	N	10	tundra				18/08/2010	ML	
SG312420	533199	6846598	L6150N, 5350E	B	30	10		N	5	tundra				18/08/2010	ML	
SG312421	533214	6846618	L6150N, 5375E	B	10	30		N	5	tundra				18/08/2010	ML	
SG312422	533228	6846637	L6150N, 5400E	B	20	20		N	10	tundra				18/08/2010	ML	
SG312423	533671	6845817	L5300N, 5025E	B	50	10	brown	N	5	tundra				19/08/2010	ML	
SG312424	533686	6846837	L5300N, 5050E	B	50	15	gry/brown	N	5	tundra				19/08/2010	ML	
SG312425	533701	6847857	L5300N, 5075E	B	50	10	gry/brown	N	5	tundra				19/08/2010	ML	
SG312426	533717	6845876	L5300N, 5100E	B	50	5	gry/brown	N	5	tundra				19/08/2010	ML	
SG312427	533731	6845896	L5300N, 5125E	B	50	20	gry/brown	N	5	tundra				19/08/2010	ML	
SG312428	533745	6845916	L5300N, 5150E	B	50	25	brown	N	5	tundra				19/08/2010	ML	

SG312429	533789	6845885	L5250N, 5150E	B	20	40	brown	N	10	tundra				19/08/2010	ML	
SG312430	533770	6845864	L5250N, 5125E	B	40	40	brown	N	10	tundra				19/08/2010	ML	
SG312431	533750	6845844	L5250N, 5100E	B	40	40	orange	N	10	tundra				19/08/2010	ML	
SG312432	533737	6845826	L5250N, 5075E	B	40	20	orange	N	5	tundra				19/08/2010	ML	
SG312433	533724	6845808	L5250N, 5050E	B	40	10	orange	N	5	tundra				19/08/2010	ML	
SG312434	533710	6845789	L5250N, 5025E	B	40	10	brown	N	5	tundra				19/08/2010	ML	
SI480501	533003	6846029	5950N 4775E	B	8	S	Brown		15	tundra	QPC	QPC+QZVN	5	17/08/2010	CRB	Carl sampled\GPSd the tie line
SI480502	532988	6846008	5950N 4750E	TF	3	S	grey-buff		30	tundra	QPC	QPC	1	17/08/2010	CRB	
SI480503	532973	6845987	5950N 4725E	B	5	M	grey-brown		20	stunted trees	QPC	QPC+Phyl	5	17/08/2010	CRB	
SI480504	532958	6845966	5950N 4700E	B	5	M	buff		20	tundra	QPC	QPC+QZVN	5	17/08/2010	CRB	
SI480505	532943	6845944	5950N 4675E	TF\B	3	M	buff		30	tundra	QPC	QPC+QZVN	5	17/08/2010	CRB	
SI480506	532927	6845923	5950N 4650E	B	10	M	grey-buff		20	tundra\bushes	QPC	QPC+QZVN	5	17/08/2010	CRB	
SI480507	532911	6845902	5950N 4625E	TF\B	3	M	brown		35	tundra	QPC	QPC+QZVN	8	17/08/2010	CRB	
SI480508	532896	6845881	5950N 4600E	B	8	M	orange-brown		20	trees\bushes	QPC	QPC+Phyl	5	17/08/2010	CRB	
SI480509	532878	6845861	5950N 4575E	B	15	M	tan		0	trees\bushes	QPC		10	17/08/2010	CRB	
SI480510	532863	6845841	5950N 4550E	B	10	M	brown-orange		15	trees\bushes	QPC	QPC+QZVN	8	17/08/2010	CRB	
SI480511	532901	6846125	6100N 4800E	TF	3	S	grey-buff		20	talas	QPC	QPC+Phyl	2	17/08/2010	CRB	
SI480512	532916	6846146	6100N 4825E	TF	3	S	grey		30	talas	QPC	Phyl	0	17/08/2010	CRB	
SI480513	532932	6846167	6100N 4850E	B	8	S	orange-buff		3	tundra	QPC	Phyl	5	17/08/2010	CRB	A small runoff gulch
SI480514	532947	6846188	6100N 4875E	TF	3	S	grey		30	talas	QPC	Phyl+QZVN	0	17/08/2010	CRB	
SI480515	532963	6846209	6100N 4900E	B\TF	3	S	orange-tan		25	tundra	QPC	QPC+Phyl	5	17/08/2010	CRB	
SI480516	532978	6846229	6100N 4925E	TF	3	S	grey		25	tundra	QPC	Phyl	1	17/08/2010	CRB	near the top of the ridge
SI480517	532993	6846249	6100N 4950E	TF	3	F	grey		40	tundra	QPC	QPC+Phyl	2	17/08/2010	CRB	Coarse sample on top of ridge
SI480518	533008	6846269	6100N 4975E	B	10	M	brown		15	tundra	QPC	QPC	8	17/08/2010	CRB	
SI480519	533024	6846288	6100N 5000E	B	5	M	brown		15	tundra	QPC	QPC	5	17/08/2010	CRB	
SI480520	533037	6846308	6100N 5025E	TF	10	F	grey		20	tundra	QPC	Phyl	5	17/08/2010	CRB	
SI480521	533049	6846328	6100N 5050E	B	10	F	orange-brown		10	tundra	QPC	QPC	5	17/08/2010	CRB	Sample is off the picket in bldr. Talas
SI480522	533065	6846348	6100N 5075E	B	10	F	grey		5	tundra	QPC	QPC+Phyl	15	17/08/2010	CRB	
SI480523	533082	6846368	6100N 5100E	B	10	F	grey		15	tundra	QPC	Phyl	10	17/08/2010	CRB	
SI480524	533099	6846388	6100N 5125E	B\TF	10	F	grey		20	tundra	QPC	Phyl	15	17/08/2010	CRB	
SI480525	533116	6846408	6100N 5150E	B	15	F	brown		20	tundra\scrub trees	QPC	QPC+Phyl	5	17/08/2010	CRB	
SI480526	533133	6846428	6100N 5175E	B\TF	10	F	grey		25	tundra	QPC	Phyl	10	17/08/2010	CRB	
SI480551	533018	6846035	L5950N, 4800E	B	15	steep	gr/brn		20	st conifers	Talus	QPC	15	17/08/2010	CS	Small conifer patch on talus slope
SI480552	533034	6846056	L5950N, 4825E	B	15	gentle	gr/brn		15	tundra	Ta/Rcrop	QPC	10	17/08/2010	CS	Small mound, rubblecrop?
SI480553	533050	6846077	L5950N, 4850E	TF	5	steep	gr/brn		30	No veg	Talus	QPC	10	17/08/2010	CS	Small patch of talus fines/soil
SI480554	533066	6846098	L5950N, 4875E	TF	10	steep	gr/brn		35	No veg	Talus	QPC/Gwke	5	17/08/2010	CS	Weakly scoroditic talus
SI480555	533081	6846119	L5950N, 4900E	B	25	steep	brown		15	tundra	Talus	QPC/Gwke	10	17/08/2010	CS	Stabilized talus
SI480556	533097	6846139	L5950N, 4925E	B	20	steep	gr/brn		25	tundra	Talus	QPC/Gwke	15	17/08/2010	CS	B-horizon mixed wigth talus fines; thin veg
SI480557	533113	6846158	L5950N, 4950E	TF	15	steep	gr/brn		30	No veg	Talus	Gwke	<5	17/08/2010	CS	Small patch in coarse talus
SI480558	533129	6846178	L5950N, 4975E	TF	10	Mod	gr/brn		30	tundra	Talus	Phy/gwke	10	17/08/2010	CS	Small patch; some "B"-horizon development
SI480559	533144	6846197	L5950N, 5000E	TF	15	steep	bf-brn		40	No veg	Talus	QPC	<5	17/08/2010	CS	Weakly bleached, silicified QPC
SI480560	533159	6846217	L5950N, 5025E	B/TF	15	steep	brown		10	tundra	Ta/Rcrop	QPC	10	17/08/2010	CS	Strongly foliated QPC in prox. Talus
SI480561	533172	6846233	L5950N, 5044E	B/TF	10	Mod	lt brown		20	tundra	Talus	QPC	10	17/08/2010	CS	Small patch of tundra
SI480562	533202	6846279	L5950N, 5100E	TF	15	gentle	grey		40	tundra	Colluvium	Slate	<5	17/08/2010	CS	Essentially fine slate in colluvium
SI480563	533217	6846298	L5950N, 5125E	B/TF	15	gentle	grey		30	tundra	Colluvium	Slate	5	17/08/2010	CS	
SI480564	533232	6846317	L5950N, 5150E	B	20	Mod	grey		15	Scon/tdra	Colluvium	QPC	5	17/08/2010	CS	Clay-rich; overlying soils are reddish
SI480565	533247	6846336	L5950N, 5175E	B	20	Mod	brown		15	tundra	Ta/Rcrop	QPC	10	17/08/2010	CS	Soil on stabilized talus
SI480566	533263	6846356	L5950N, 5200E	TF	10	Mod	grey		25	tundra	Ta/Rcrop	QPC	5	17/08/2010	CS	Actual loc: 533252E, 6846361N; clay-rich
SI480567	533286	6846383	L5950N, 5235E	TF	10	Mod	grey		35	No veg	Ta/Rcrop	QPC	10	17/08/2010	CS	Small patch; some grass
SI480568	533307	6846414	L5950N, 5275E	B/TF	15	steep	gr/brn		30	No veg	Talus	QPC	10	17/08/2010	CS	Small patch; limited vegetation
SI480569	533321	6846433	L5950N, 5300E	B/TF	15	steep	grey		30	Willow	Talus	Slate	15	17/08/2010	CS	Slope from NE
SI480570	533336	6846454	L5950N, 5325E	B	20	Mod	brn/gry		15	tundra	Colluvium	Slate	10	17/08/2010	CS	Stunted conifer nearby
SI480571	533352	6846474	L5950N, 5350E	B	15	gentle	brn/gry		20	tundra	Colluvium	Phy	10	17/08/2010	CS	Locally calcareous phyllite
SI480572	533265	6846604	L6100N, 5400E	B	20	steep	lt brown		15	tundra	Colluvium	QPC	10	17/08/2010	CS	St conifer and willow directly downslope
SI480573	533251	6846585	L6100N, 5370E	B	20	gentle	gr-brn		15	Willow	CV/Rcrop	QPC	10	17/08/2010	CS	Willow patch
SI480574	533236	6846565	L6100N, 5350E	B	10	Mod	grey		10	Td/ willow	Colluvium	Slate	<5	17/08/2010	CS	Clay-rich; some large QPC boulders
SI480575	533221	6846545	L6100N, 5325E	B	20	Mod	grey		20	Td/ willow	Colluvium	Slate	10	17/08/2010	CS	Clay-rich
SI480576	533206	6846525	L6100N, 5300E	B	20	gentle	grey		10	Td/ willow	Colluvium	Gwke/slate	5	17/08/2010	CS	Clay rich; willow copse
SI480577	533191	6846504	L6100N, 5275E	TF	15	steep	lt brown		35	st conifers	Talus	QPC	<5	17/08/2010	CS	Quartz veining in QPC
SI480578	533176	6846483	L6100N, 5250E	B	25	steep	gry-brown		<5	st conifers	Ta/Rcrop	QPC	20	17/08/2010	CS	Bouldery; high organics
SI480579	533161	6846462	L6100N, 5225E	B	10	steep	lt brown		15	tundra	Ta/Rcrop	QPC	10	17/08/2010	CS	Small patch of stabilized talus

SI480580	533147	6846441	L6100N, 5200E	B	20	steep	gr-brn		20	td/scon	Ta/CV	QPC/Phy	15	17/08/2010	CS	Near small talus slope
SI480581	532892	6846714	L6100N, 4775E	B	20	steep	brown		15	tundra	Ta/CV	QPC	10	18/08/2010	CS	Mod foliated QPC boulders
SI480582	532876	6846893	L6100N, 4750E	B	25	steep	brown		15	tundra	Ta/CV	Slate	10	18/08/2010	CS	Larger QPC talus float in area
SI480583	532860	6847072	L6100N, 4725E	B	25	steep	brown		10	tundra	Ta/CV	QPC	10	18/08/2010	CS	Local QPC talus/rcrop
SI480584	532843	6846056	L6100N, 4700E	B/TF	10	steep	brown		20	No veg	Ta/CV	QPC/Phy	5	18/08/2010	CS	85% QPC, 15% Phy talus float
SI480585	532827	6849023	L6100N, 4675E	B	20	Mod	lt brown		10	tundra	Ta/CV	QPC	10	18/08/2010	CS	Stabilized talus, large QPC boulders
SI480586	532810	6848007	L6100N, 4650E	B/TF	15	Mod	lt brown		25	tundra	Ta/CV	QPC	5	18/08/2010	CS	Small frost boil
SI480587	532794	6846991	L6100N, 4625E	B	20	Mod	lt brown		20	Tdra/Scon	Colluvium	Sstone	10	18/08/2010	CS	Strong B-horizon development
SI480588	532777	6845975	L6100N, 4600E	B	15	gentle	rd/brn		15	Tdra/Scon	Colluvium	Sstone	10	18/08/2010	CS	Near base of slope to NE
SI480589	532761	6845954	L6100N, 4575E	B	20	gentle	brown		10	Tdra/Scon	Colluvium	Slate	10	18/08/2010	CS	Small mounds; CV/ till nearby
SI480590	532746	6845934	L6100N, 4550E	B	20	gentle	gry-brown		15	Tdra/Scon	Colluvium	QPC	5	18/08/2010	CS	Mod clay content; grassy
SI481051	533327	6843859	4550N	B	25	steep	brown	No	30	mix			10	14-Jul	Craig	
SI481052	533306	6843873	4575N	B	15	steep	brown	No	25	mix			5	14-Jul	Craig	
SI481053	533265	6843899	4625N	B	20	steep	brown	No	20	mix			5	14-Jul	Craig	
SI481054	533245	6843913	4650N	B	25	steep	light brown	No	25	mix			5	14-Jul	Craig	
SI481055	533225	6843928	4675N	B	30	steep	brown	No	20	mix			10	14-Jul	Craig	
SI481056	533205	6843943	4700N	B	35	steep	brown	No	20	mix			5	14-Jul	Craig	
SI481057	533193	6843959	4725N	B	30	steep	orange/brown	No	20	mix			5	14-Jul	Craig	
SI481058	533171	6843975	4750N	B	30	steep	brown	No	30	mix			5	14-Jul	Craig	
SI481059	533149	6843991	4775N	B	35	steep	brown	No	20	mix			5	14-Jul	Craig	
SI481060	533127	6844007	4800N	B	20	steep	brown	No	25	mix			10	14-Jul	Craig	
SI481061	533107	6844023	4825N	B	25	steep	orange/brown	No	20	mix			5	14-Jul	Craig	
SI481062	533087	6844039	4850N	B	25	steep	brown	No	20	mix			10	14-Jul	Craig	
SI481063	533067	6844055	4875N	B	20	steep	brown	No	25	mix			5	14-Jul	Craig	
SI481064	533048	6844072	4900N	B	25	steep	orange/brown	No	20	mix			5	14-Jul	Craig	
SI481065	533028	6844086	4925N	B	20	steep	brown	No	20	mix			5	14-Jul	Craig	
SI481066	533009	6844100	4950N	B	50	steep	brown	No	25	mix			5	14-Jul	Craig	
SI481067	532989	6844114	4975N	B	25	steep	brown	No	20	mix			10	14-Jul	Craig	
SI481068	532970	6844127	5000N	B	20	steep	orange/brown	No	20	mix			5	14-Jul	Craig	
SI481069	533771	6844522	3800E/4575N	B	20	steep	brown	No	15	alpine			10	16-Jul	Craig	
SI481070	533791	6844507	4550N	B	20	steep	orange/brown	No	30	alpine			5	16-Jul	Craig	
SI481071	533811	6844493	4525N	B	25	moderate	orange/brown	No	20	alpine			5	16-Jul	Craig	
SI481072	533831	6844478	4500N	B	20	moderate	brown	No	25	alpine			5	16-Jul	Craig	
SI481073	533850	6844463	4475N	B	25	steep	brown	No	40	alpine			5	16-Jul	Craig	
SI481074	533870	6844449	4450N	B	20	steep	brown	No	30	alpine			10	16-Jul	Craig	
SI481075	533890	6844434	4425N	B	25	steep	brown	No	25	alpine			5	16-Jul	Craig	
SI481076	533910	6844420	4400N	B	20	steep	brown	No	15	alpine			5	16-Jul	Craig	
SI481077	533929	6844403	4375N	B	35	steep	orange/brown	No	20	alpine			5	16-Jul	Craig	
SI481078	533949	6844387	4350N	B	30	steep	brown	No	25	alpine			10	16-Jul	Craig	
SI481079	533969	6844370	4325N	B	20	steep	brown	No	30	alpine			5	16-Jul	Craig	
SI481080	533989	6844354	4300N	B	25	steep	brown	No	20	alpine			5	16-Jul	Craig	
SI481081	534007	6844335	4275N	B	20	steep	brown	No	20	alpine			5	16-Jul	Craig	
SI481082	534025	6844317	4250N	B	25	steep	tan	No	25	alpine			5	16-Jul	Craig	
SI481083	534043	6844299	4225N	B	30	steep	light brown	No	15	alpine			10	16-Jul	Craig	
SI481084	534061	6844281	4200N	B	25	steep	brown	No	20	alpine			10	16-Jul	Craig	
SI481085	534079	6844265	4175N	B	30	steep	brown	No	20	mix			10	16-Jul	Craig	
SI481086	534097	6844249	4150N	B	25	steep	tan	No	25	mix			5	16-Jul	Craig	
SI481087	534115	6844233	4125N	B	20	steep	orange/brown	No	20	fir			5	16-Jul	Craig	
SI481088	534132	6844216	4100N	B	25	steep	brown	No	25	fir			5	16-Jul	Craig	
SI481089	534150	6844200	4075N	B	20	steep	tan	No	20	fir			5	16-Jul	Craig	
SI481090	534168	6844184	4050N	B	20	steep	orange/brown	No	25	fir			10	16-Jul	Craig	
SI481091	534186	6844168	4025N	B	25	steep	brown	No	25	fir			5	16-Jul	Craig	
SI481092	534053	6843990	3600E/4025N	B	25	steep	brown	No	25	fir			10	16-Jul	Craig	
SI481093	534035	6844008	4050N	B	20	steep	brown	No	20	fir			10	16-Jul	Craig	
SI481094	534017	6844026	4075N	B	25	steep	brown	No	25	fir			5	16-Jul	Craig	
SI481095	533999	6844044	4100N	B	20	steep	brown	No	20	fir			5	16-Jul	Craig	
SI481096	533981	6844062	4125N	B	20	steep	brown	No	15	fir			10	16-Jul	Craig	
SI481097	533963	6844080	4150N	B	20	steep	brown	No	20	fir			10	16-Jul	Craig	
SI481098	533945	6844098	4175N	B	20	steep	orange/brown	No	20	fir			1	16-Jul	Craig	
SI481099	533927	6844116	4200N	B	20	steep	orange/brown	No	20	fir			10	16-Jul	Craig	
SI481100	533904	6844126	4225N	B	25	steep	orange/brown	No	15	fir			5	16-Jul	Craig	

SI481101	533882	6844139	4250N	B	25	steep	brown	No	25	mix			10	16-Jul	Craig	
SI481102	533860	6844152	4275N	B	20	steep	brown	No	20	mix			10	16-Jul	Craig	
SI481103	533838	6844165	4300N	B	20	steep	orange/brown	No	20	mix			5	16-Jul	Craig	
SI481104	533819	6844182	4325N	B	35	steep	orange/brown	No	25	mix			5	16-Jul	Craig	
SI481105	533800	6844199	4350N	B	20	steep	brown	No	15	mix			5	16-Jul	Craig	
SI481106	533781	6844216	4375N	B	25	steep	brown	No	20	mix			10	17-Jul	CT, ML	
SI481107	533762	6844232	4400N	B	20	moderate	tan	No	25	mix			10	17-Jul	CT, ML	
SI481108	533743	6844249	4425N	B	20	steep	brown	No	20	mix			5	17-Jul	CT, ML	
SI481109	533724	6844266	4450N	B	25	steep	brown	No	20	mix			5	17-Jul	CT, ML	
SI481110	533705	6844283	4475N	B	20	steep	brown	No	25	mix			5	17-Jul	CT, ML	
SI481111	533685	6844300	4500N	B	30	steep	brown	No	20	mix			10	17-Jul	CT, ML	
SI481112	533666	6844317	4525N	B	35	steep	grey/brown	No	30	alpine			5	17-Jul	CT, ML	
SI481113	533647	6844334	4550N	B	30	steep	brown	No	30	alpine			5	17-Jul	CT, ML	
SI481114	533628	6844351	4575N	B	20	steep	light brown	No	25	alpine			5	17-Jul	CT, ML	
SI481115	533685	6844422	3700E/4575N	B	25	steep	orange/brown	No	20	alpine			10	17-Jul	CT, ML	
SI481116	533710	6844409	4550N	B	20	steep	brown	No	20	alpine			10	17-Jul	CT, ML	
SI481117	533735	6844396	4525N	B	25	steep	orange/brown	No	15	alpine			5	17-Jul	CT, ML	
SI481118	533760	6844383	4500N	B	20	steep	orange/brown	No	20	alpine			10	17-Jul	CT, ML	
SI481119	533957	6843850	L3900E/4025N	B	25	steep	brown	No	20	alpine			10	18-Jul	CT, ML	
SI481120	533937	6843866	4050N	B	20	steep	light brown	No	15	alpine			5	18-Jul	CT, ML	
SI481121	533917	6843882	4075N	B	15	steep	orange/brown	No	10	alpine			10	18-Jul	CT, ML	
SI481122	533897	6843898	4100N	B	20	steep	brown	No	20	alpine			5	18-Jul	CT, ML	
SI481123	533877	6843913	4125N	B	25	steep	brown	No	20	alpine			5	18-Jul	CT, ML	
SI481124	533857	6843929	4150N	B	30	steep	R	No	25	alpine			5	18-Jul	CT, ML	
SI481125	533837	6843945	4175N	B	20	steep	tan	No	20	alpine			5	18-Jul	CT, ML	
SI481126	533817	6843961	4200N	B	20	steep	orange/brown	No	20	alpine			10	18-Jul	CT, ML	
SI481127	533797	6843975	4225N	B	20	steep	orange/brown	No	20	alpine			10	18-Jul	CT, ML	
SI481128	533777	6843989	4250N	B	25	steep	orange/brown	No	20	alpine			5	18-Jul	CT, ML	
SI481129	533757	6844003	4275N	B	20	steep	grey/brown	No	25	alpine			5	18-Jul	CT, ML	
SI481130	533738	6844018	4300N	B	20	steep	brown	No	20	alpine			5	18-Jul	CT, ML	
SI481131	533718	6844032	4325N	B	25	steep	orange/brown	No	20	alpine			10	18-Jul	CT, ML	
SI481132	533698	6844046	4350N	B	20	steep	grey/brown	No	25	alpine			5	18-Jul	CT, ML	
SI481133	533678	6844060	4375N	B	20	steep	grey/brown	No	20	alpine			5	18-Jul	CT, ML	
SI481134	533657	6844075	4400N	B	20	steep	brown	No	25	alpine			5	18-Jul	CT, ML	
SI481135	533686	6844091	4425N	B	20	moderate	orange/brown	No	20	alpine			10	18-Jul	CT, ML	
SI481136	533716	6844106	4450N	B	25	moderate	light brown	No	25	alpine			5	18-Jul	CT, ML	
SI481137	533746	6844121	4475N	B	20	moderate	brown	No	20	alpine			5	18-Jul	CT, ML	
SI481138	533776	6844136	4500N	B	25	gentle	orange/brown	No	25	alpine			5	18-Jul	CT, ML	
SI481139	533806	6844151	4525N	B	30	moderate	grey/brown	No	30	alpine			10	18-Jul	CT, ML	
SI481140	533836	6844166	4550N	B	30	moderate	orange/brown	No	20	alpine			5	18-Jul	CT, ML	
SI481141	533866	6844181	4575N	B	35	steep	orange/brown	No	25	alpine			5	18-Jul	CT, ML	
SI481142	534020	6843928	3500E/4025N	B	30	steep	orange/brown	No	20	alpine			5	18-Jul	CT, ML	
SI481143	534000	6843944	4050N	B	30	steep	orange/brown	No	25	alpine			10	18-Jul	CT, ML	
SI481144	533980	6843959	4075N	B	25	steep	grey/brown	No	30	alpine			5	18-Jul	CT, ML	
SI481145	533960	6843974	4100N	B	30	steep	grey/brown	No	25	alpine			5	18-Jul	CT, ML	
SI481146	533940	6843989	4125N	B	20	steep	grey/brown	No	20	alpine			5	18-Jul	CT, ML	
SI481147	533920	6844004	4150N	B	25	steep	grey/brown	No	20	alpine			5	18-Jul	CT, ML	
SI481148	533900	6844018	4175N	B	20	steep	brown	No	20	alpine			10	18-Jul	CT, ML	
SI481149	533881	6844032	4200N	B	25	steep	brown	No	25	alpine			5	18-Jul	CT, ML	
SI481150	533861	6844047	4225N	B	20	steep	brown	No	20	alpine			10	18-Jul	CT, ML	
SI481151	533840	6844062	4250N	B	20	steep	brown	No	10	alpine			10	18-Jul	CT, ML	
SI481152	533819	6844077	4275N	B	20	steep	brown	No	20	alpine			5	18-Jul	CT, ML	
SI481153	533799	6844092	4300N	B	25	steep	brown	No	25	alpine			5	18-Jul	CT, ML	
SI481154	533780	6844108	4325N	B	20	steep	orange/brown	No	20	alpine			5	18-Jul	CT, ML	
SI481155	533761	6844124	4350N	B	25	steep	brown	No	25	alpine			5	18-Jul	CT, ML	
SI481156	533742	6844140	4375N	B	20	steep	brown	No	20	alpine			10	18-Jul	CT, ML	
SI481157	533724	6844155	4400N	B	25	steep	orange/brown	No	20	alpine			5	18-Jul	CT, ML	
SI481158	533703	6841170	4425N	B	20	steep	orange/brown	No	15	alpine			5	18-Jul	CT, ML	
SI481159	533682	6842184	4450N	B	20	steep	orange/brown	No	20	alpine			5	18-Jul	CT, ML	
SI481160	533661	6843198	4475N	B	20	moderate	orange/brown	No	25	alpine			10	18-Jul	CT, ML	
SI481161	533639	6844212	4500N	B	15	gentle	brown	No	20	alpine			5	18-Jul	CT, ML	

SI481162	533618	6845226	4525N	B	20	gentle	brown	No	15	alpine			5	18-Jul	CT, ML	
SI481163	533597	6846240	4550N	B	25	steep	brown	No	20	alpine			10	18-Jul	CT, ML	
SI481164	533576	6847254	4575N	B	25	steep	brown	No	30	alpine			10	18-Jul	CT, ML	
SI481203	533596	6844368	3600E/4625N	B	30	steep	orange/brown	No	20	alpine			10	20-Jul	CT, ML	
SI481204	533576	6844384	4650N	B	40	steep	orange/brown	No	40	alpine			10	20-Jul	CT, ML	
SI481205	533556	6844400	4675N	B	20	steep	dark brown	No	20	alpine			5	20-Jul	CT, ML	
SI481206	533536	6844416	4700N	B	25	steep	tan	No	25	alpine			5	20-Jul	CT, ML	
SI481207	533516	6844432	4725N	B	20	steep	brown	No	20	alpine			5	20-Jul	CT, ML	
SI481208	533496	6844448	4750N	B	25	steep	brown	No	20	alpine			10	20-Jul	CT, ML	
SI481209	533476	6844464	4775N	B	20	moderate	grey/brown	No	30	alpine			5	20-Jul	CT, ML	
SI481210	533456	6844480	4800N	B	15	steep	grey/brown	No	30	alpine			5	20-Jul	CT, ML	
SI481211	533436	6844495	4825N	B	20	steep	grey/brown	No	20	alpine			5	20-Jul	CT, ML	
SI481212	533417	6844510	4850N	B	25	steep	brown	No	25	alpine			10	20-Jul	CT, ML	
SI481213	533397	6844525	4875N	B	20	steep	brown	No	20	alpine			10	20-Jul	CT, ML	
SI481214	533378	6844540	4900N	B	25	steep	grey/brown	No	25	alpine			5	20-Jul	CT, ML	
SI481215	533358	6844556	4925N	B	20	steep	brown	No	25	alpine			5	20-Jul	CT, ML	
SI481216	533339	6844572	4950N	B	25	steep	grey/brown	No	20	alpine			10	20-Jul	CT, ML	
SI481217	533320	6844588	4975N	B	30	steep	brown	No	20	alpine			5	20-Jul	CT, ML	
SI481218	533301	6844604	5000N	B	25	steep	brown	No	25	alpine			10	20-Jul	CT, ML	
SI481219	533269	6899610	3600/5025	b	25	stp	brn	n	20	mix			10		ML	
SI481220	533250	6899626	5050	b	30	stp	brn	n	25	mix			5		ML	
SI481221	533231	6899642	5075	b	30	stp	brn	n	20	mix			5		ML	
SI481222	533212	6899658	5100	b	25	stp	or/brn	n	25	mix			5		ML	
SI481223	533193	6899674	5125	b	25	stp	brn	n	20	mix			5		ML	
SI481224	533175	6899690	5150	b	30	stp	or/brn	n	30	mix			10		ML	
SI481225	533156	6899706	5175	b	30	stp	or/brn	n	20	mix			5		ML	
SI481226	533138	6844721	5200	b	0	stp	or/brn	n	20	mix			10		ML	
SI481227	533124	6850699	tl5200n/4575e	b	25	stp	brn	n	25	mix			10		ML	
SI481228	533108	6848679	4550e	b	25	stp	brn	n	20	mix			5		ML	
SI481229	533092	6846659	4525e	b	20	stp	gr/brn	n	25	mix			5		ML	
SI481230	533076	6844639	4500e, 5200N	b	25	stp	brn	n	20	mix			10		ML	
SI481231	533097	6844622	l4500e/5175n	b	30	stp	brn	n	25	mix			5		ML	
SI481232	533118	6844605	5150n	b	30	stp	brn	n	20	mix			10		ML	
SI481233	533139	6844588	5125n	b	35	stp	or/brn	n	20	mix			5		ML	
SI481234	533160	6844571	5100n	b	35	stp	brn	n	20	mix			5		ML	
SI481235	533180	6844557	3500e/5075n	b	25	stp	or/brn	n	20	mix			15		ML	
SI481236	533200	6844544	5050n	b	30	stp	rd/brn	n	25	mix			5		ML	
SI481237	533220	6844531	5025n	b	20	stp	brn	n	20	mix			10		ML	
SI481238	533239	6844518	5000n	b	25	stp	brn	n	20	alpine			10		ML	
SI481239	533260	6844503	4975n	b	20	stp	or/brn	n	20	alpine			5		ML	
SI481240	533280	6844487	4950n	b	25	stp	brn	n	25	alpine			5		ML	
SI481241	533300	6844471	4925n	b	25	stp	gr/brn	n	25	alpine			5		ML	
SI481242	533320	6844455	4900n	b	30	stp	or/brn	n	20	alpine			10		ML	
SI481243	533340	6844440	4875n	b	35	stp	brn	n	25	alpine			5		ML	
SI481244	533361	6844425	4850n	b	35	stp	gr/brn	n	25	alpine			5		ML	
SI481245	533381	6844410	4825n	b	35	gentle	brn	n	20	alpine			10		ML	
SI481246	533402	6844394	4800n	b	20	mod	brn	n	20	alpine			5		ML	
SI481247	533422	6844379	4775n	b	30	mod	or/brn	n	25	alpine			5		ML	
SI481248	533442	6844364	4750n	b	30	stp	or/brn	n	20	alpine			5		ML	
SI481249	533462	6844349	4725n	b	35	stp	or/brn	n	25	alpine			10		ML	
SI481250	533481	6844333	4700n	b	25	mod	or/brn	n	20	alpine			5		ML	
SI481251	533500	6844317	4675n	b	25	mod	or/brn	n	25	alpine			10		ML	
SI481252	533519	6844301	4650n	b	20	stp	or/brn	n	20	alpine			5		ML	
SI481253	533538	6844285	4625n	b	25	mod	brn	n	15	alpine			10		ML	
SI481254	533433	6844122	3300e/4625n	b	15	stp	rd/brn	n	10	none			10		ML	
SI481255	533413	6844137	4650n	b	20	stp	or/brn	n	40	alpine			20		ML	
SI481256	533393	6844152	4675n	b	30	stp	brn	n	20	alpine			5		ML	
SI481257	533373	6844167	4700n	b	20	stp	brn	n	25	alpine			10		ML	
SI481258	533353	6844182	4725n	b	30	stp	tan	n	20	alpine			5		ML	
SI481259	533333	6844198	4750n	b	30	stp	brn	n	25	alpine			10		ML	
SI481260	533313	6844213	4775n	b	20	stp	brn	n	20	alpine			10		ML	

SI481261	533294	6844229	4800n	b	25	stp	brn	n	25	alpine			5		ML	
SI481262	533274	6844244	4825n	b	25	stp	tan	n	20	alpine			10		ML	
SI481263	533254	6844259	4850n	b	30	stp	tan	n	15	alpine			5		ML	
SI481264	533234	6844274	4875n	b	25	stp	brn	n	20	alpine			10		ML	
SI481265	533214	6844289	4900n	b	30	stp	or/brn	n	25	alpine			5		ML	
SI481266	533194	6844304	4925n	b	25	stp	or/brn	n	20	alpine			5		ML	
SI481267	533174	6844319	4950n	b	20	stp	brn	n	15	alpine			5		ML	
SI481268	533154	6844334	4975n	b	20	stp	brn	n	20	alpine			10		ML	
SI481269	533134	6844349	5000n	b	25	stp	brn	n	10	mix			5		ML	
SI481270	533114	6844364	3300e/5025n	b	20	stp	brn	n	15	mix			10		ML	
SI481271	533094	6844379	5050n	b	25	stp	gr/brn	n	20	mix			5		ML	
SI481272	533074	6844394	5075n	b	30	stp	brn	n	20	mix			5		ML	
SI481273	533053	6844410	5100n	b	20	stp	brn	n	20	mix			5		ML	
SI481274	533033	6844426	5125n	b	20	mod	or/brn	n	25	mix			10		ML	
SI481275	533014	6844442	5150n	b	25	mod	or/brn	n	15	mix			5		ML	
SI481276	532994	6844458	5175n	b	20	stp	brn	n	20	mix			10		ML	
SI481277	532975	6844474	5200n	b	25	mod	tan	n	25	mix			5		ML	
SI481278	532991	6844494	5200n/3325e	b	30	mod	brn	n	20	mix			5		ML	
SI481279	533006	6844514	3350e	b	20	stp	or/brn	n	25	mix			5		ML	
SI481280	533021	6844534	3375e	b	2	mod	brn	n	25	mix			10		ML	
SI481281	533036	6844554	3400e/5200n	b	20	stp	or/brn	n	25	mix			5		ML	
SI481282	533056	6844538	5175n	b	25	mod	or/brn	n	20	mix			5		ML	
SI481283	533075	6844524	5150n	b	30	mod	brn	n	25	mix			10		ML	
SI481284	533095	6844510	5125n	b	30	stp	brn	n	25	mix			10		ML	
SI481285	533114	6844496	5100n	b	20	stp	brn	n	20	mix			5		ML	
SI481286	533132	6844481	5075	b	25	mod	gr/brn	n	20	mix			5		ML	
SI481287	533150	6844467	5050	b	20	stp	gr/brn	n	15	mix			5		ML	
SI481288	533168	6844453	5025	b	30	stp	gr/brn	n	20	alpine			10		ML	
SI481289	533185	6844438	5000	b	25	stp	gr/brn	n	25	alpine			10		ML	
SI481290	533203	6844424	4975	b	30	stp	gr/brn	n	15	alpine			5		ML	
SI481291	533221	6844410	4950	b	20	stp	brn	n	20	alpine			5		ML	
SI481292	533239	6844395	4925	b	20	stp	brn	n	25	alpine			10		ML	
SI481293	533257	6844380	4900	b	30	stp	gr/brn	n	30	alpine			5		ML	
SI481294	533277	6844365	4875	b	20	stp	gr/brn	n	20	alpine			10		ML	
SI481295	533298	6844350	4850	b	25	stp	brn	n	40	alpine			5		ML	
SI481296	533318	6844335	4825	b	20	stp	or/brn	n	30	alpine			5		ML	
SI481297	533339	6844319	4800	b	25	stp	or/brn	n	15	alpine			10		ML	
SI481298	533359	6844303	4775	b	20	stp	or/brn	n	30	alpine			5		ML	
SI481299	533379	6844287	4750	b	30	stp	or/brn	n	35	alpine			5		ML	
SI481300	533399	6844271	4725	b	20	stp	brn	n	20	alpine			10		ML	
SI481301	533418	6844256	4700	b	25	stp	brn	n	15	alpine			5		ML	
SI481302	533438	6844240	4675	b	20	stp	or/brn	n	25	alpine			5		ML	
SI481303	533458	6844224	4650	b	30	mod	or/brn	n	30	alpine			5		ML	
SI481304	533478	6844208	4625	b	20	stp	or/brn	n	20	alpine			10		ML	
SI481327	533917	6843758	3300E/4025N	B	25	steep	brown	No	20	alpine			10	25-Jul	CT/ML	
SI481328	533896	6843774	4050N	B	20	steep	brown	No	15	alpine			10	25-Jul	CT/ML	
SI481329	533875	6843790	4075N	B	25	steep	orange/brown	No	20	alpine			5	25-Jul	CT/ML	
SI481330	533854	6843806	4100N	B	30	steep	orange/brown	No	10	alpine			5	25-Jul	CT/ML	
SI481331	533833	6843822	4125N	B	20	steep	tan	No	25	alpine			5	25-Jul	CT/ML	
SI481332	533813	6843837	4150N	B	25	steep	tan	No	20	alpine			10	25-Jul	CT/ML	
SI481333	533793	6843852	4175N	B	20	steep	brown	No	25	alpine			5	25-Jul	CT/ML	
SI481334	533773	6843867	4200N	B	25	steep	red/brown	No	20	alpine			10	25-Jul	CT/ML	
SI481335	533754	6843882	4225N	B	20	steep	grey/brown	No	25	alpine			5	25-Jul	CT/ML	
SI481336	533735	6843897	4250N	B	25	steep	orange/brown	No	20	alpine			10	25-Jul	CT/ML	
SI481337	533716	6843912	4275N	B	20	gentle	orange/brown	No	20	alpine			5	25-Jul	CT/ML	
SI481338	533696	6843926	4300N	B	25	moderate	orange/brown	No	15	alpine			5	25-Jul	CT/ML	
SI481339	533676	6843934	4325N	B	20	steep	orange/brown	No	15	alpine			10	25-Jul	CT/ML	
SI481340	533655	6843942	4350N	B	20	steep	tan	No	20	alpine			5	25-Jul	CT/ML	
SI481341	533635	6843950	4375N	B	20	steep	tan	No	15	alpine			10	25-Jul	CT/ML	
SI481342	533614	6843958	4400N	B	30	steep	grey/brown	No	20	alpine			5	25-Jul	CT/ML	
SI481343	533593	6843981	4425N	B	25	steep	orange/brown	No	25	alpine			10	25-Jul	CT/ML	

SI481344	533573	6844004	4450N	B	20	steep	brown	No	20	alpine			5	25-Jul	CT/ML	
SI481345	533553	6844027	4475N	B	15	moderate	brown	No	15	alpine			10	25-Jul	CT/ML	
SI481346	533533	6844049	4500N	B	25	steep	brown	No	15	alpine			5	25-Jul	CT/ML	
SI481347	533513	6844071	4525N	B	20	steep	orange/brown	No	10	alpine			10	25-Jul	CT/ML	
SI481348	533493	6844093	4550N	B	15	steep	orange/brown	No	20	alpine			5	25-Jul	CT/ML	
SI481349	533473	6844115	4575N	B	20	steep	orange/brown	No	25	alpine			10	25-Jul	CT/ML	
SI481350	533819	6844706	4000E/4625N	B	30	steep	brown	No	20	alpine			10	25-Jul	CT/ML	
SI481351	533798	6844721	4650N	B	25	steep	orange/brown	No	25	alpine			5	25-Jul	CT/ML	
SI481352	533778	6844736	4675N	B	30	steep	brown	No	20	alpine			10	25-Jul	CT/ML	
SI481353	533757	6844751	4700N	B	25	steep	brown	No	15	alpine			5	25-Jul	CT/ML	
SI481354	533737	6844766	4725N	B	20	steep	tan	No	20	alpine			5	25-Jul	CT/ML	
SI481355	533716	6844781	4750N	B	25	steep	brown	No	10	alpine			10	25-Jul	CT/ML	
SI481356	533696	6844796	4775N	B	20	steep	brown	No	30	alpine			5	25-Jul	CT/ML	
SI481357	533675	6844811	4800N	B	30	steep	brown	No	20	alpine			5	25-Jul	CT/ML	
SI481358	533656	6844828	4825N	B	20	steep	orange/brown	No	25	alpine			5	25-Jul	CT/ML	
SI481359	533636	6844844	4850N	B	25	steep	brown	No	10	alpine			10	25-Jul	CT/ML	
SI481360	533616	6844860	4875N	B	20	steep	orange/brown	No	15	alpine			5	25-Jul	CT/ML	
SI481361	533596	6844876	4900N	B	25	moderate	brown	No	20	alpine			10	25-Jul	CT/ML	
SI481362	533576	6844890	4925N	B	30	gentle	red/brown	No	20	alpine			5	25-Jul	CT/ML	
SI481363	533556	6844905	4950N	B	25	gentle	tan	No	15	alpine			5	25-Jul	CT/ML	
SI481364	533536	6844920	4975N	B	20	gentle	red/brown	No	20	alpine			10	25-Jul	CT/ML	
SI481365	533516	6844935	5000N	B	20	gentle	red/brown	No	20	alpine			5	25-Jul	CT/ML	
SI481366	533496	6844949	5025N	B	20	gentle	red/brown	No	15	alpine			10	25-Jul	CT/ML	
SI481367	533476	6844963	5050N	B	20	steep	orange/brown	No	20	alpine			5	25-Jul	CT/ML	
SI481368	533456	6844977	5075N	B	20	steep	orange/brown	No	15	alpine			10	25-Jul	CT/ML	
SI481369	533436	6844991	5100N	B	15	steep	orange/brown	No	25	alpine			5	25-Jul	CT/ML	
SI481371	533417	6845006	5125N	B	25	steep	red/brown	No	20	alpine			10	25-Jul	CT/ML	
SI481372	533397	6845022	5150N	B	15	steep	brown	No	15	alpine			15	25-Jul	CT/ML	
SI481373	533378	6845038	5175N	B	20	steep	brown	No	30	alpine			5	25-Jul	CT/ML	
SI481374	533358	6845054	5200N	B	25	steep	grey/brown	No	30	alpine			10	25-Jul	CT/ML	
SI481375	533303	6843959	3100E/4625N	B	30	steep	orange/brown	No	30	mix			5	26-Jul	CT/ML	
SI481376	533284	6843975	4650N	B	20	steep	orange/brown	No	30	mix			5	26-Jul	CT/ML	
SI481377	533265	6843991	4675N	B	20	moderate	brown	No	20	mix			10	26-Jul	CT/ML	
SI481378	533246	6844007	4700N	B	25	steep	tan	No	20	mix			5	26-Jul	CT/ML	
SI481379	533227	6844022	4725N	B	20	steep	brown	No	25	mix			5	26-Jul	CT/ML	
SI481380	533208	6844038	4750N	B	15	steep	orange/brown	No	15	mix			5	26-Jul	CT/ML	
SI481381	533189	6844054	4775N	B	25	steep	tan	No	10	mix			10	26-Jul	CT/ML	
SI481382	533169	6844070	4800N	B	20	steep	brown	No	10	mix			5	26-Jul	CT/ML	
SI481383	533149	6844083	4825N	B	25	steep	brown	No	25	mix			5	26-Jul	CT/ML	
SI481384	533130	6844097	4850N	B	20	moderate	tan	No	25	mix			10	26-Jul	CT/ML	
SI481385	533111	6844110	4875N	B	25	steep	brown	No	20	mix			10	26-Jul	CT/ML	
SI481386	533091	6844124	4900N	B	20	steep	brown	No	15	mix			5	26-Jul	CT/ML	
SI481387	533069	6844140	4925N	B	25	steep	brown	No	20	mix			5	26-Jul	CT/ML	
SI481388	533048	6844156	4950N	B	20	steep	grey/brown	No	10	mix			5	26-Jul	CT/ML	
SI481389	533027	6844172	4975N	B	25	steep	brown	No	20	mix			10	26-Jul	CT/ML	
SI481390	533006	6844188	5000N	B	20	steep	orange/brown	No	15	mix			5	26-Jul	CT/ML	
SI481391	532987	6844203	5025N	B	25	steep	tan	No	25	mix			10	26-Jul	CT/ML	
SI481392	532969	6844219	5050N	B	20	moderate	grey/brown	No	20	mix			5	26-Jul	CT/ML	
SI481393	532950	6844235	5075N	B	15	steep	brown	No	15	mix			10	26-Jul	CT/ML	
SI481394	532932	6844250	5100N	B	20	steep	orange/brown	No	20	mix			5	26-Jul	CT/ML	
SI481395	532912	6844265	5125N	B	25	steep	brown	No	10	mix			5	26-Jul	CT/ML	
SI481396	532891	6844279	5150N	B	20	steep	grey/brown	No	15	mix			5	26-Jul	CT/ML	
SI481397	532871	6844294	5175N	B	25	steep	brown	No	20	mix			10	26-Jul	CT/ML	
SI481398	532850	6844308	5200N	B	20	steep	orange/brown	No	15	mix			5	26-Jul	CT/ML	
SI481399	532951	6844145	3000E/5025N	B	25	steep	tan	No	20	mix			10	26-Jul	CT/ML	
SI481400	532931	6844161	5050N	B	15	steep	orange/brown	No	10	mix			5	26-Jul	CT/ML	
SI481401	532912	6844177	5075N	B	20	steep	brown	No	20	mix			10	26-Jul	CT/ML	
SI481402	532892	6844193	5100N	B	25	steep	orange/brown	No	15	mix			5	26-Jul	CT/ML	
SI481403	532873	6844212	5125N	B	20	steep	brown	No	10	mix			5	26-Jul	CT/ML	
SI481404	532853	6844226	5150N	B	15	steep	brown	No	15	mix			5	26-Jul	CT/ML	
SI481405	532834	6844240	5175N	B	20	steep	brown	No	15	mix			10	26-Jul	CT/ML	

SI481406	532814	6844254	5200N	B	25	steep	orange/brown	No	20	mix			5	26-Jul	CT/ML	nr. Creek
SI481407	532910	6844390	3200E/5200N	B	20	moderate	brown	No	15	mix			10	26-Jul	CT/ML	
SI481408	532930	6844374	5175N	B	20	steep	brown	No	10	mix			5	26-Jul	CT/ML	
SI481409	532950	6844359	5150N	B	25	steep	tan	No	10	mix			5	26-Jul	CT/ML	
SI481410	532970	6844344	5125N	B	15	steep	orange/brown	No	20	mix			10	26-Jul	CT/ML	
SI481411	532991	6844329	5100N	B	20	steep	orange/brown	No	15	mix			10	26-Jul	CT/ML	
SI481412	533010	6844313	5075N	B	30	moderate	red/brown	No	10	mix			5	26-Jul	CT/ML	
SI481413	533030	6844298	5050N	B	20	steep	grey/brown	No	15	mix			10	26-Jul	CT/ML	
SI481414	533050	6844282	5025N	B	25	steep	orange/brown	No	20	mix			5	26-Jul	CT/ML	
SI481415	533070	6844267	5000N	B	20	steep	tan	No	15	mix			5	26-Jul	CT/ML	
SI481416	533090	6844252	4975N	B	25	steep	brown	No	20	mix			10	26-Jul	CT/ML	
SI481417	533110	6844236	4950N	B	20	steep	brown	No	25	mix			5	26-Jul	CT/ML	
SI481418	533130	6844221	4925N	B	25	steep	brown	No	20	mix			10	26-Jul	CT/ML	
SI481419	533149	6844205	4900N	B	15	steep	tan	No	15	mix			5	26-Jul	CT/ML	
SI481420	533168	6844189	4875N	B	20	steep	brown	No	20	mix			10	26-Jul	CT/ML	
SI481421	533187	6844174	4850N	B	25	steep	orange/brown	No	15	mix			5	26-Jul	CT/ML	
SI481422	533206	6844159	4825N	B	20	steep	brown	No	10	mix			10	26-Jul	CT/ML	
SI481423	533246	6844130	4775N	B	25	steep	brown	No	15	mix			5	26-Jul	CT/ML	
SI481424	533268	6844115	4750N	B	20	steep	grey/brown	No	30	mix			5	26-Jul	CT/ML	
SI481425	533290	6844101	4725N	B	25	steep	grey/brown	No	35	mix			10	26-Jul	CT/ML	
SI481426	533311	6844086	4700N	B	20	steep	orange/brown	No	10	mix			5	26-Jul	CT/ML	
SI481427	533333	6844072	4675N	B	25	steep	orange/brown	No	15	mix			5	26-Jul	CT/ML	
SI481428	533224	6844144	4800N	B	20	steep	tan	No	20	mix			10	26-Jul	CT/ML	
SI481429	533355	6844057	4650N	B	20	steep	tan	No	20	mix			10	26-Jul	CT/ML	
SI481430	533377	6844042	4625N	B	25	steep	brown	No	25	mix			5	26-Jul	CT/ML	
SI481431	533306	6844965	3900N/5200E	B	20	steep	orange/brown	No	10	alpine			5	27-Jul	Craig	
SI481432	533325	6844950	5175N	B	25	steep	tan	No	20	alpine			5	27-Jul	Craig	
SI481433	533344	6844936	5150N	B	20	steep	brown	No	15	alpine			5	27-Jul	Craig	
SI481434	533363	6844922	5125N	B	25	steep	brown	No	25	alpine			5	27-Jul	Craig	
SI481435	533382	6844907	5100N	B	20	steep	brown	No	15	alpine			10	27-Jul	Craig	
SI481436	533403	6844893	5075N	B	25	steep	orange/brown	No	20	alpine			5	27-Jul	Craig	
SI481437	533423	6844878	5050N	B	20	steep	orange/brown	No	15	alpine			10	27-Jul	Craig	
SI481438	533444	6844864	5025N	B	25	steep	tan	No	20	alpine			5	27-Jul	Craig	
SI481439	533464	6844849	5000N	B	20	steep	brown	No	25	alpine			5	27-Jul	Craig	
SI481440	533484	6844833	4975N	B	25	steep	brown	No	30	alpine			5	27-Jul	Craig	
SI481441	533504	6844817	4950N	B	20	steep	red/brown	No	10	alpine			5	27-Jul	Craig	
SI481442	533524	6844801	4925N	B	15	steep	orange/brown	No	20	alpine			10	27-Jul	Craig	
SI481443	533543	6844786	4900N	B	20	steep	brown	No	15	alpine			5	27-Jul	Craig	
SI481444	533563	6844770	4875N	B	15	moderate	red/brown	No	10	alpine			5	27-Jul	Craig	
SI481445	533582	6844755	4850N	B	20	moderate	grey/brown	No	20	alpine			5	27-Jul	Craig	
SI481446	533601	6844740	4825N	B	15	moderate	red/brown	No	15	alpine			10	27-Jul	Craig	
SI481447	533620	6844725	4800N	B	20	steep	orange/brown	No	25	alpine			5	27-Jul	Craig	
SI481448	533641	6844710	4775N	B	25	steep	orange/brown	No	20	alpine			10	27-Jul	Craig	
SI481449	533662	6844695	4750N	B	30	steep	brown	No	20	alpine			10	27-Jul	Craig	
SI481450	533683	6844680	4725N	B	25	moderate	tan	No	15	alpine			5	27-Jul	Craig	
SI481451	533703	6844665	4700N	B	30	steep	orange/brown	No	15	alpine			5	27-Jul	Craig	
SI481452	533724	6844650	4675N	B	25	steep	tan	No	20	alpine			5	27-Jul	Craig	
SI481453	533745	6844635	4650N	B	15	steep	brown	No	15	alpine			5	27-Jul	Craig	
SI481454	533766	6844620	4625N	B	20	steep	orange/brown	No	20	alpine			10	27-Jul	Craig	
SI481455	533478	6846061	5600N/5100E	B	20	hilltop	tan	No	20	alpine			5	30-Jul	CT/CW	
SI481456	533463	6846041	5075E	B	25	steep	grey/brown	No	25	alpine			5	30-Jul	CT/CW	
SI481457	533448	6846021	5050E	B	20	steep	light brown	No	20	alpine			5	30-Jul	CT/CW	
SI481458	533433	6846001	5025E	B	15	steep	orange/brown	No	25	alpine			5	30-Jul	CT/CW	
SI481459	533418	6845981	5000E	B	30	steep	brown	No	30	alpine			10	30-Jul	CT/CW	
SI481460	533402	6845962	4975E	B	20	steep	light brown	No	15	alpine			5	30-Jul	CT/CW	
SI481461	533386	6845942	4950E	B	25	gentle	light brown	No	25	alpine			5	30-Jul	CT/CW	
SI481462	533371	6845923	4925E	B	20	moderate	brown	No	20	alpine			5	30-Jul	CT/CW	
SI481463	533356	6845903	4900E	B	25	steep	brown	No	30	alpine			10	30-Jul	CT/CW	sample 5 m south
SI481464	533341	6845884	4875E	B	20	steep	orange/brown	No	25	alpine			5	30-Jul	CT/CW	
SI481465	533325	6845864	4850E	B	20	steep	brown	No	30	alpine			5	30-Jul	CT/CW	
SI481466	533309	6845844	4825E	B	25	steep	light brown	No	20	alpine			5	30-Jul	CT/CW	

SI481467	533293	6845824	4800E	B	30	steep	brown	No	25	alpine			10	30-Jul	CT/CW	
SI481468	533277	6845805	4775E	B	15	steep	light brown	No	30	alpine			5	30-Jul	CT/CW	
SI481469	533261	6845785	4750E	B	10	steep	orange/brown	No	20	alpine			10	30-Jul	CT/CW	sample 10m south
SI481470	533245	6845765	4725E	B	30	steep	light brown	No	15	alpine			15	30-Jul	CT/CW	sample 10m south
SI481471	533229	6845745	4700E	B	15	steep	light brown	No	10	alpine			10	30-Jul	CT/CW	
SI484501	533520	6845955	L5550N/5050E	B	25	steep	light grey	No	20	alpine			5	01-Aug	CW	
SI484502	533505	6845936	5025E	B	25	steep	light grey	No	15	alpine			5	01-Aug	CW	
SI484503	533535	6845974	5075E	B	30	steep	light grey	No	15	alpine			5	01-Aug	CW	
SI484504	533517	6846031	5100E	B	25	steep	light grey	No	20	alpine			5	01-Aug	CW	
SI484505	533587	6846038	5500N/5150E	B	20	steep	light grey	No	25	alpine			0	01-Aug	CW	
SI484506	533571	6846017	5125E	B	20	steep	light grey	No	20	alpine			0	01-Aug	CW	
SI484507	533556	6845996	5100E	B	20	steep	light grey	No	20	alpine			0	01-Aug	CW	
SI484508	533533	6845979	5075E	B	20	steep	light grey	No	20	alpine			0	01-Aug	CW	
SI484509	533510	6845961	5050E	B	15	steep	dark brown	No	5	alpine			10	01-Aug	CW	
SI484510	533487	6845944	5025E	B	15	steep	light brown	No	5	alpine			15	01-Aug	CW	
SI484511	533464	6845927	4975E	B	15	flat	light brown	No	10	alpine			10	01-Aug	CW	
SI484512	533441	6845909	4950E	B	15	flat	dark brown	No	10	alpine			10	01-Aug	CW	
SI484513	533418	6845891	4925E	B	10	steep	dark brown	No	15	alpine			10	01-Aug	CW	
SI484514	533394	6845873	4900E	B	15	steep	dark brown	No	15	alpine			10	01-Aug	CW	
SI484515	533378	6845854	4875E	B	20	steep	dark brown	No	15	alpine			5	01-Aug	CW	
SI484516	533363	6845834	4850E	B	20	steep	dark brown	No	15	alpine			10	01-Aug	CW	
SI484517	533347	6845815	4825E	B	20	steep	dark grey	No	20	alpine			15	01-Aug	CW	
SI484518	533332	6845795	4800E	B	20	steep	dark brown	No	15	alpine			15	01-Aug	CW	
SI484519	533316	6845776	4775E	B	20	steep	dark brown	No	15	alpine			10	01-Aug	CW	
SI484520	533300	6845756	4750E	B	26	steep	light brown	No	10	alpine			10	01-Aug	CW	
SI484521	533284	6845736	4725E	B	26	steep	light brown	No	10	alpine			10	01-Aug	CW	
SI484522	533269	6845717	4700E	B	20	steep	light brown	No	15	alpine			5	01-Aug	CW	
SI484523	533306	6845680	5550N/4700E	B	26	steep	light brown	No	15	alpine			10	01-Aug	CW	
SI484524	533321	6845701	4725E	B	26	steep	dark brown	No	15	alpine			5	01-Aug	CW	
SI484525	533337	6845722	4750E	B	26	steep	dark brown	No	15	alpine			5	01-Aug	CW	
SI484526	533353	6845743	4775E	B	26	steep	dark brown	No	10	alpine			10	01-Aug	CW	
SI484527	533369	6845765	4800E	B	20	steep	dark brown	No	15	alpine			10	01-Aug	CW	
SI484528	533385	6845784	4825E	B	15	steep	light grey	No	15	alpine			0	01-Aug	CW	
SI484529	533400	6845803	4850E	B	35	steep	dark grey	No	15	alpine			10	01-Aug	CW	
SI484530	533415	6845822	4875E	B	25	steep	dark grey	No	15	alpine			10	01-Aug	CW	
SI484531	533430	6845841	4900E	B	10	steep	dark brown	No	10	alpine			15	01-Aug	CW	
SI484532	533445	6845860	4925E	B	20	flat	dark brown	No	10	alpine			10	01-Aug	CW	
SI484533	533460	6845879	4950E	B	20	flat	dark brown	No	10	alpine			10	01-Aug	CW	
SI484534	533475	6845898	4975E	B	25	steep	dark brown	No	10	alpine			10	01-Aug	CW	
SI484535	533521	6845871	L5450N 4975E	B	20	S	LG	N	10	Alpe			5	Aug 2,2010	CW	
SI484536	533505	6845851	4950E	B	20	S	LG	N	15	Alpe			10	Aug 2,2010	CW	
SI484537	533488	6845831	4925E	B	20	S	LG	N	15	Alpe			10	Aug 2,2010	CW	
SI484538	533473	6845811	4900E	B	15	F	LG	N	15	Alpe			10	Aug 2,2010	CW	
SI484539	533458	6845792	4875E	B	10	F	LG	N	10	Alpe			5	Aug 2,2010	CW	
SI484540	533442	6845772	4850E	B	15	F	LG	N	10	Alpe			10	Aug 2,2010	CW	
SI484541	533426	6845752	4825E	B	15	S	DB	N	5	Alpe			15	Aug 2,2010	CW	
SI484542	533410	6845732	4800E	B	15	S	DB	N	10	Alpe			15	Aug 2,2010	CW	2m South SS
SI484543	533393	6845712	4775E	B	15	S	DB	N	10	Alpe			15	Aug 2,2010	CW	
SI484544	533377	6845692	4750E	B	10	S	DB	N	10	Alpe			10	Aug 2,2010	CW	
SI484545	533360	6845672	4725E	B	15	S	LB	N	10	Alpe			5	Aug 2,2010	CW	
SI484546	533344	6845652	L5450N, 4700E	B	30	S	LB	N	10	Alpe			15	Aug 2,2010	CW	end of line
SI484547	533551	6845834	5400N 4975E	B	30	S	LB	N	5	Alpe			10	Aug 4,2010	CW	
SI484548	533536	6845816	4950E	B	25	S	LB	N	5	Alpe			10	Aug 4,2010	CW	
SI484549	533521	6845798	4925E	B	15	S	LB	N	10	Alpe			10	Aug 4,2010	CW	
SI484550	533506	6845779	4900E	B	20	F	DB	N	10	Alpe			10	Aug 4,2010	CW	
SI484551	533492	6845761	4875E	B	15	F	LB	N	5	Alpe			10	Aug 4,2010	CW	
SI484552	533477	6845742	4850E	B	15	S	LG	N	10	Alpe			5	Aug 4,2010	CW	
SI484553	533462	6845724	4825E	B	15	S	LB	N	10	Alpe			10	Aug 4,2010	CW	3m east of stake
SI484554	533447	6845705	4800E	B	15	S	LB	N	15	Alpe			10	Aug 4,2010	CW	
SI484555	533432	6845683	4775E	B	15	S	LG	N	10	Alpe			5	Aug 4,2010	CW	NW 2m stack
SI484556	533417	6845661	4750E	B	15	S	LB	N	10	Alpe			10	Aug 4,2010	CW	

SI484557	533402	6845639	4725E	B	20	S	LB	N	15	Alpe			10	Aug 4,2010	CW	
SI484558	533387	6845617	4700E	B	15	S	LB	N	15	Alpe			10	Aug 4,2010	CW	end of line
SI484559	533430	6845591	5350N 4700E	B	15	S	LG	N	10	Alpe			10	Aug 4,2010	CW	start of line
SI484560	533444	6845611	4725E	B	15	S	DB	N	10	Alpe			10	Aug 4,2010	CW	
SI484561	533458	6845631	4750E	B	20	S	LG	N	5	Alpe			5	Aug 4,2010	CW	
SI484562	533472	6845651	4775E	B	20	S	DB	N	20	Alpe			5	Aug 4,2010	CW	
SI484563	533487	6845670	4800E	B	15	S	LB	N	15	Alpe			0	Aug 4,2010	CW	
SI484564	533501	6845690	4825E	B	20	S	LB	N	15	Alpe			5	Aug 4,2010	CW	
SI484565	533515	6845710	4850E	B	20	S	LB	N	10	Alpe			15	Aug 4,2010	CW	
SI484566	533529	6845730	4875E	B	20	S	LG	N	10	Alpe			5	Aug 4,2010	CW	
SI484567	533542	6845749	4900E	B	20	S	LG	N	10	Alpe			5	Aug 4,2010	CW	
SI484568	533555	6845768	4925E	B	20	S	LB	N	5	Alpe			10	Aug 4,2010	CW	
SI484569	533568	6845787	4950E	B	15	S	LG	N	15	Alpe			5	Aug 4,2010	CW	
SI484570	533581	6845806	4975E	B	20	S	LB	N	10	Alpe			15	Aug 4,2010	CW	2m north of stake
SI484571	533553	6845890	5450N 5025E	B	30	F	LB	N	10	Alpe			13	Aug 4,2010	CW	stake
SI484572	533568	6845915	5050E	B	25	S	LB	N	10	Alpe			5	Aug 4,2010	CW	
SI484573	533583	6845940	5075E	B	25	S	LB	N	5	Alpe			10	Aug 4,2010	CW	
SI484574	533598	6845965	5100E	B	25	S	LB	N	10	Alpe			5	Aug 4,2010	CW	
SI484575	533613	6845990	5125E	B	20	S	LG	N	10	Alpe			10	Aug 4,2010	CW	
SI484576	533628	6846014	5150E	B	20	S	DB	N	10	Alpe			10	Aug 4,2010	CW	end
SI484577	533666	6845975	5400N 5150E	B	20	S	LG	N	10	Alpe			5	Aug 4,2010	CW	
SI484578	533649	6845958	5125E	B	25	S	LG	N	10	Alpe			10	Aug 4,2010	CW	
SI484579	533633	6845940	5100E	B	15	S	LB	N	5	Alpe			10	Aug 4,2010	CW	
SI484580	533617	6845922	5075E	B	15	S	LB	N	10	Alpe			15	Aug 4,2010	CW	
SI484581	533601	6845904	5050E	B	20	S	LB	N	5	Alpe			10	Aug 4,2010	CW	
SI484582	533585	6845886	5025E	B	20	S	LB	N	5	Alpe			10	Aug 4,2010	CW	
SI484583	533633	6845775	5300N 4975E	B	25	S	LB	N	5	Alpe			10	Aug 4,2010	CW	
SI484584	533618	6845755	4950E	B	20	S	LB	N	5	Alpe			10	Aug 6,2010	CW	
SI484585	533604	6845735	4925E	B	30	S	LB	N	5	Alpe			10	Aug 6,2010	CW	
SI484586	533589	6845715	4900E	B	20	S	LB	N	5	Alpe			10	Aug 6,2010	CW	
SI484587	533574	6845694	4875E	B	25	S	LB	N	10	Alpe			10	Aug 6,2010	CW	
SI484588	533560	6845674	4850E	B	20	S	LB	N	10	Alpe			10	Aug 6,2010	CW	
SI484589	533545	6845654	4825E	B	15	S	LB	N	10	Alpe			15	Aug 6,2010	CW	
SI484590	533531	6845634	4800E	B	15	S	LB	N	5	Alpe			15	Aug 6,2010	CW	
SI484591	533499	6845616	4775E	B	10	F	LB	N	5	Alpe			15	Aug 6,2010	CW	
SI484592	533468	6845599	4750E	B	15	S	LB	N	10	Alpe			15	Aug 6,2010	CW	
SI484593	533437	6845581	4725E	B	10	S	LB	N	15	Alpe			10	Aug 6,2010	CW	
SI484594	533406	6845563	4700E	B	30	S	LG	N	15	Alpe			5	Aug 6,2010	CW	end of line
SI484595	533505	6845529	5250N 4700E	B	10	S	LG	N	15	Alpe			15	Aug 6,2010	CW	start of line
SI484596	533521	6845549	4725E	B	15	S	LB	N	10	Alpe			15	Aug 6,2010	CW	
SI484597	533537	6845569	4750E	B	15	F	LB	N	10	Alpe			10	Aug 6,2010	CW	
SI484598	533553	6845589	4775E	B	10	F	LG	N	20	Alpe			0	Aug 6,2010	CW	
SI484599	533569	6845610	4800E	B	18	F	LG	N	20	Alpe			5	Aug 6,2010	CW	
SI484600	533584	6845629	4825E	B	30	S	LB	N	20	Alpe			5	Aug 6,2010	CW	2.5m south
SI484601	533599	6845648	4850E	B	25	S	LB	N	10	Alpe			15	Aug 6,2010	CW	
SI484602	533614	6845667	4875E	B	20	S	LB	N	5	Alpe			15	Aug 6,2010	CW	
SI484603	533629	6845687	4900E	B	25	S	LB	N	5	Alpe			15	Aug 6,2010	CW	2.5m east
SI484604	533644	6845707	4925E	B	15	S	LB	N	5	Alpe			15	Aug 6,2010	CW	
SI484605	533659	6845727	4950E	B	20	S	LB	N	5	Alpe			15	Aug 6,2010	CW	
SI484606	533674	6845747	4975E	B	20	S	LB	N	5	Alpe			20	Aug 6,2010	CW	end of line
SI484607	533719	6845726	5200N 4975E	B	25	S	LG	N	5	Alpe			15	Aug 6,2010	CW	start of line
SI484608	533703	6845705	4950E	B	25	S	LB	N	10	Alpe			15	Aug 6,2010	CW	
SI484609	533687	6845684	4925E	B	20	S	LB	N	5	Alpe			15	Aug 6,2010	CW	
SI484610	533671	6845663	4900E	B	10	S	LB	N	5	Alpe			15	Aug 6,2010	CW	
SI484611	533657	6845642	4875E	B	15	S	LB	N	10	Alpe			10	Aug 6,2010	CW	
SI484612	533641	6845621	4850E	B	20	S	LB	N	15	Alpe			20	Aug 6,2010	CW	
SI484613	533625	6845600	4825E	B	15	S	LB	N	10	Alpe			15	Aug 6,2010	CW	
SI484614	533609	6845579	4800E	B	15	S	LB	N	10	Alpe			15	Aug 6,2010	CW	
SI484615	533593	6845560	4775E	B	20	S	LB	N	10	Alpe			10	Aug 6,2010	CW	
SI484616	533577	6845541	4750E	B	20	S	LB	N	5	Alpe			10	Aug 6,2010	CW	
SI484617	533561	6845522	4725E	B	20	S	LB	N	10	Alpe			10	Aug 6,2010	CW	

SI484618	533546	6845502	4700E	B	10	F	LB	N	10	Alpe			10	Aug 6,2010	CW	end of line
SI484619	533365	6845987	5650N 4975E	B	15	S	LG	N	10	Alpe			5	Aug 7,2010	CW	
SI484620	533349	6845968	4950E	B	15	S	LG	N	20	Alpe			5	Aug 7,2010	CW	
SI484621	533333	6845949	4925E	B	15	S	LG	N	20	Alpe			5	Aug 7,2010	CW	
SI484622	533317	6845930	4900E	B	10	S	LB	N	25	Alpe			0	Aug 7,2010	CW	
SI484623	533300	6845911	4875E	B	15	S	LB	N	10	Alpe			10	Aug 7,2010	CW	
SI484624	533284	6845892	4850E	B	10	S	LB	N	10	Alpe			10	Aug 7,2010	CW	
SI484625	533268	6845873	4825E	B	15	S	LB	N	15	Alpe			10	Aug 7,2010	CW	
SI484626	533252	6845854	4800E	B	15	S	LB	N	15	Alpe			15	Aug 7,2010	CW	
SI484627	533236	6845835	4775E	B	15	S	LB	N	10	Alpe			10	Aug 7,2010	CW	
SI484628	533221	6845816	4750E	B	15	S	LG	N	10	Alpe			5	Aug 7,2010	CW	
SI484629	533205	6845797	4725E	B	15	S	LG	N	10	Alpe			0	Aug 7,2010	CW	
SI484630	533175	6845757	4675E	B	10	S	LB	N	20	Alpe			5	Aug 8,2010	CW	
SI484631	533160	6845737	4650E	B	10	S	DB	N	10	Alpe			10	Aug 8,2010	CW	
SI484632	533145	6845716	4625E	B	30	S	DB	N	10	Alpe			15	Aug 8,2010	CW	
SI484633	533130	6845696	4600E	B	20	S	DB	N	5	Alpe			15	Aug 8,2010	CW	
SI484634	533030	6845652	5700N 4500E	B	10	S	LB	N	5	Alpe			10	Aug 8,2010	CW	Runs north of
SI484635	533045	6845670	4525E	B	20	S	LB	N	5	Alpe			15	Aug 8,2010	CW	
SI484636	533060	6845689	4550E	B	15	S	LB	N	0	Alpe			15	Aug 8,2010	CW	
SI484637	533075	6845707	4575E	B	20	S	LB	N	5	Alpe			15	Aug 8,2010	CW	
SI484638	533090	6845726	4600E	B	15	S	LB	N	5	Alpe			15	Aug 8,2010	CW	
SI484639	533398	6845992	5650N 5025E	B	15	S	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484640	533414	6846011	5050E	B	15	S	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484641	533430	6846030	5075E	B	20	S	LG	N	15	Alpe			5	Aug 9,2010	CW	
SI484642	533438	6846088	5100E	B	20	S	LG	N	15	Alpe			5	Aug 9,2010	CW	
SI484643	533396	6846122	5700N 5100E	B	15	S	LG	N	20	Alpe			5	Aug 9,2010	CW	
SI484644	533381	6846101	5075E	B	20	S	LB	N	10	Alpe			5	Aug 9,2010	CW	
SI484645	533366	6846081	5050E	B	20	S	LB	N	5	Alpe			10	Aug 9,2010	CW	
SI484646	533352	6846061	5025E	B	15	F	LB	N	5	Alpe			10	Aug 9,2010	CW	
SI484647	533323	6846020	4975E	B	10	F	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484648	533309	6846000	4950E	B	10	S	LB	N	10	Alpe			15	Aug 9,2010	CW	
SI484649	533294	6845980	4925E	B	5	S	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484650	533279	6845960	4900E	B	10	S	LB	N	10	Alpe			10	Aug 9,2010	CW	2m of stake E
SI484651	533262	6845941	4875E	B	20	S	DG	N	10	Alpe			10	Aug 9,2010	CW	
SI484652	533246	6845921	4850E	B	10	S	DB	N	20	Alpe			5	Aug 9,2010	CW	
SI484653	533230	6845901	4825E	B	20	S	LB	N	15	Alpe			5	Aug 9,2010	CW	
SI484654	533214	6845881	4800E	B	15	S	LB	N	15	Alpe			5	Aug 9,2010	CW	
SI484655	533198	6845863	4775E	B	10	S	LB	N	10	Alpe			10	Aug 9,2010	CW	1.5m south of
SI484656	533183	6845844	4750E	B	15	S	LB	N	20	Alpe			5	Aug 9,2010	CW	
SI484657	533168	6845826	4725E	B	20	S	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484658	533153	6845807	4700E	B	10	S	LB	N	15	Alpe			5	Aug 9,2010	CW	
SI484659	533117	6845767	4650E	B	15	S	LB	N	15	Alpe			5	Aug 9,2010	CW	
SI484660	533099	6845747	4625E	B	20	S	LB	N	10	Alpe			10	Aug 9,2010	CW	2.5m east of
SI484661	532994	6845677	5750N 4500E	B	15	S	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484662	533009	6845697	4525E	B	15	S	LB	N	5	Alpe			15	Aug 9,2010	CW	
SI484663	533025	6845716	4550E	B	20	S	LB	N	5	Alpe			10	Aug 9,2010	CW	
SI484664	533040	6845736	4575E	B	20	S	LB	N	5	Alpe			15	Aug 9,2010	CW	
SI484665	533056	6845756	4600E	B	10	S	LB	N	5	Alpe			15	Aug 9,2010	CW	3m east of
SI484666	533072	6845777	4625E	B	15	S	LB	N	5	Alpe			15	Aug 9,2010	CW	
SI484667	533088	6845798	4650E	B	15	S	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484668	533104	6845819	4675E	B	15	S	DB	N	15	Alpe			5	Aug 9,2010	CW	
SI484669	533120	6845839	4700E	B	15	S	LB	N	10	Alpe			10	Aug 9,2010	CW	2m east of
SI484670	533135	6845858	4725E	B	20	S	LB	N	10	Alpe			5	Aug 9,2010	CW	
SI484671	533150	6845877	4750E	B	15	S	LB	N	5	Alpe			10	Aug 9,2010	CW	
SI484672	533165	6845896	4775E	B	20	S	LB	N	5	Alpe			15	Aug 9,2010	CW	
SI484673	533180	6845914	4800E	B	15	S	DB	N	20	Alpe			5	Aug 9,2010	CW	
SI484674	533191	6845937	4825E	B	15	S	LB	N	15	Alpe			10	Aug 9,2010	CW	
SI484675	533219	6845978	4875E	B	15	S	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484676	533235	6845997	4900E	B	15	S	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484677	533251	6846016	4925E	B	20	S	LB	N	10	Alpe			10	Aug 9,2010	CW	
SI484678	533267	6846035	4950E	B	10	S	DB	N	10	Alpe			5	Aug 9,2010	CW	

SI484679	533283	6846054	4975E	B	20	F	DB	N	5	Alpe			10	Aug 9,2010	CW	
SI484680	533229	6846061	5800N 4950E	B	10	S	DB	N	15	Alpe			0	Aug14,2010	CW	1.5m west of
SI484681	533213	6846044	4925E	B	20	S	LB	N	10	Alpe			5	Aug14,2010	CW	
SI484682	533197	6846026	4900E	B	15	S	DB	N	10	Alpe			10	Aug14,2010	CW	
SI484683	533185	6846007	4875E	B	10	S	DB	N	15	Alpe			5	Aug15,2010	CW	
SI484684	533172	6845988	4850E	B	15	S	LB	N	10	Alpe			5	Aug15,2010	CW	
SI484685	533159	6845969	4825E	B	10	S	LB	N	15	Alpe			5	Aug15,2010	CW	north east 1.5m
SI484686	533146	6845950	4800E	B	10	S	LB	N	15	Alpe			10	Aug15,2010	CW	north of 2m
SI484687	533100	6845975	5850N 4800E	B	15	S	DB	N	5	Alpe			10	Aug15,2010	CW	
SI484688	533114	6845997	4825E	B	10	S	LB	N	10	Alpe			10	Aug15,2010	CW	
SI484689	533128	6846019	4850E	B	15	S	LB	N	5	Alpe			10	Aug15,2010	CW	
SI484690	533142	6846041	4875E	B	15	S	LB	N	10	Alpe			10	Aug15,2010	CW	
SI484691	533155	6846062	4900E	B	15	S	LB	N	5	Alpe			10	Aug15,2010	CW	
SI484692	533172	6846082	4925E	B	20	S	LB	N	10	Alpe			10	Aug15,2010	CW	
SI484693	533190	6846101	4950E	B	15	S	LB	N	10	Alpe			5	Aug15,2010	CW	
SI484694	533150	6846138	5900N 4950E	B	20	S	LB	N	10	Alpe			10	Aug15,2010	CW	
SI484695	533131	6846113	4925E	B	20	S	LB	N	5	Alpe			10	Aug15,2010	CW	
SI484696	533112	6846087	4900E	B	15	S	LB	N	10	Alpe			10	Aug15,2010	CW	
SI484697	533099	6846068	4875E	B	15	S	LB	N	10	Alpe			10	Aug15,2010	CW	
SI484698	533086	6846048	4850E	B	20	S	LB	N	15	Alpe			15	Aug15,2010	CW	
SI484699	533073	6846028	4825E	B	15	S	LB	N	20	Alpe			5	Aug15,2010	CW	
SI484700	533060	6846008	4800E	B	15	S	LB	N	20	Alpe			5	Aug15,2010	CW	
SI484701	533126	6845920	5800N 4775E	B	20	S	LB	N	15	Alpe			5	Aug15,2010	CW	
SI484702	533110	6845901	4750E	B	15	S	DB	N	10	Alpe			5	Aug15,2010	CW	
SI484703	533094	6845882	4725E	B	15	S	DB	N	5	Alpe			10	Aug16,2010	CW	
SI484704	533078	6845862	4700E	B	15	S	LB	N	10	Alpe			15	Aug16,2010	CW	
SI484705	533063	6845843	4675E	B	20	S	LB	N	5	Alpe			15	Aug16,2010	CW	
SI484706	533047	6845823	4650E	B	15	S	LB	N	5	Alpe			15	Aug16,2010	CW	
SI484707	533031	6845804	4625E	B	15	S	LB	N	10	Alpe			15	Aug16,2010	CW	
SI484708	533015	6845784	4600E	B	15	S	LB	N	10	Alpe			10	Aug16,2010	CW	
SI484709	533001	6845765	4575E	B	15	S	LB	N	10	Alpe			15	Aug16,2010	CW	
SI484710	532987	6845746	4550E	B	15	S	LB	N	5	Alpe			10	Aug16,2010	CW	
SI484711	532973	6845727	4525E	B	15	S	LB	N	5	Alpe			10	Aug16,2010	CW	
SI484712	532959	6845708	4500E	B	15	S	LB	N	5	Alpe			10	Aug16,2010	CW	
SI484713	532909	6845740	5850N 4500E	B	20	S	LB	N	5	Alpe			10	Aug16,2010	CW	
SI484714	532929	6845760	4525E	B	15	S	LB	N	10	Alpe			10	Aug16,2010	CW	
SI484715	532944	6845779	4550E	B	15	S	LB	N	5	Alpe			15	Aug16,2010	CW	
SI484716	532959	6845798	4575E	B	15	S	LB	N	5	Alpe			15	Aug16,2010	CW	
SI484717	532974	6845817	4600E	B	15	S	LB	N	5	Alpe			15	Aug16,2010	CW	
SI484718	532989	6845836	4625E	B	15	S	LB	N	10	Alpe			10	Aug16,2010	CW	
SI484719	533004	6845855	4650E	B	15	S	LB	N	5	Alpe			15	Aug16,2010	CW	
SI484720	533019	6845874	4675E	B	20	S	LB	N	5	Alpe			10	Aug16,2010	CW	
SI484721	533035	6845894	4700E	B	20	S	LB	N	15	Alpe			10	Aug16,2010	CW	
SI484722	533051	6845914	4725E	B	20	S	LB	N	15	Alpe			10	Aug16,2010	CW	
SI484723	533067	6845934	4750E	B	20	S	DB	N	0	Alpe			15	Aug16,2010	CW	
SI484724	533083	6845954	4775E	B	20	S	DB	N	5	Alpe			20	Aug16,2010	CW	
SI484725	533044	6845999	5900N 4775E	B	15	S	DB	N	20	Alpe			5	Aug16,2010	CW	
SI484726	533028	6845978	4750E	B	15	S	DB	N	10	Alpe			10	Aug16,2010	CW	
SI484727	533012	6845957	4725E	B	25	S	LB	N	15	Alpe			10	Aug16,2010	CW	
SI484728	532996	6845936	4700E	B	15	S	LB	N	10	Alpe			10	Aug16,2010	CW	
SI484729	532979	6845916	4675E	B	20	S	LB	N	5	Alpe			15	Aug16,2010	CW	
SI484730	532963	6845895	4650E	B	20	S	LB	N	5	Alpe			10	Aug16,2010	CW	
SI484731	532947	6845874	4625E	B	30	S	LB	N	10	Alpe			10	Aug16,2010	CW	
SI484732	532931	6845853	4600E	B	20	S	LB	N	10	Alpe			10	Aug16,2010	CW	
SI484733	532927	6845832	4575E	B	20	S	LG	N	10	Alpe			10	Aug16,2010	CW	
SI484734	532904	6845812	4550E	B	30	S	LB	N	5	Alpe			15	Aug16,2010	CW	
SI484735	533660	6844452	3700N 4625E	B	15	M	DB	N	5	Alpe			10	Aug17,2010	CW	
SI484736	533639	6844468	4650E	B	15	M	DB	N	5	Alpe			10	Aug17,2010	CW	
SI484737	533619	6844484	4675E	B	20	M	DB	N	5	Alpe			10	Aug17,2010	CW	
SI484738	533598	6844500	4700E	B	15	M	DB	N	5	Alpe			15	Aug17,2010	CW	
SI484739	533577	6844516	4725E	B	20	M	DB	N	10	Alpe			15	Aug17,2010	CW	

SI484740	533557	6844532	4750E	B	20	M	GB	N	10	Alpe			15	Aug17,2010	CW	
SI484741	533536	6844548	4775E	B	20	M	DB	N	10	Alpe			15	Aug17,2010	CW	
SI484742	533516	6844564	4800E	B	20	M	LB	N	10	Alpe			15	Aug17,2010	CW	
SI484743	533496	6844579	4825E	B	20	M	LB	N	15	Alpe			10	Aug17,2010	CW	
SI484744	533477	6844593	4850E	B	20	M	LB	N	10	Alpe			15	Aug17,2010	CW	
SI484745	533457	6844608	4875E	B	20	M	LB	N	10	Alpe			15	Aug17,2010	CW	
SI484746	533438	6844622	4900E	B	20	M	LB	N	15	Alpe			15	Aug17,2010	CW	
SI484747	533419	6844638	4925E	B	25	M	DB	N	10	Alpe			15	Aug17,2010	CW	
SI484748	533399	6844654	4950E	B	25	M	LB	N	5	Alpe			10	Aug17,2010	CW	
SI484749	533379	6844670	4975E	B	20	M	DG	N	15	Alpe			5	Aug17,2010	CW	by creek
SI484750	533359	6844685	5000E	B	20	M	DG	N	20	Alpe			5	Aug17,2010	CW	
SI484751	533335	6844696	3700E 5025N	B	20	S	LB	N	15	Alpe			10	Aug17,2010	CW	
SI484752	533316	6844712	5050N	B	20	S	DB	N	15	Alpe			5	Aug17,2010	CW	
SI484753	533297	6844728	5075N	B	20	S	LG	N	0	Alpe			10	Aug17,2010	CW	
SI484754	533277	6844744	5100N	B	20	S	LB	N	5	Alpe			15	Aug17,2010	CW	
SI484755	533258	6844760	5125N	B	20	S	LB	N	10	Alpe			10	Aug17,2010	CW	
SI484756	533238	6844776	5150N	B	20	S	DB	N	0	Alpe			15	Aug17,2010	CW	
SI484757	533219	6844792	5175N	B	15	S	DB	N	0	Alpe			15	Aug17,2010	CW	
SI484758	533199	6844808	5200N	B	20	S	DB	N	5	Alpe			15	Aug17,2010	CW	
SI484759	533263	6844887	3800E 5200N	B	20	S	LB	N	10	Alpe			10	Aug17,2010	CW	
SI484760	533283	6844872	5175N	B	15	S	LB	N	15	Alpe			15	Aug17,2010	CW	
SI484761	533304	6844856	5150N	B	25	S	LB	N	10	Alpe			15	Aug17,2010	CW	
SI484762	533324	6844840	5125N	B	15	S	LG	N	5	Alpe			15	Aug17,2010	CW	
SI484763	533345	6844825	5100N	B	15	S	LB	N	5	Alpe			15	Aug17,2010	CW	
SI484764	532819	6846185	6200N 4800E	B	25	S	LB	N	10	Alpe			10	Aug18,2010	CW	
SI484765	532836	6846207	4825E	B	20	S	LB	N	5	Alpe			10	Aug18,2010	CW	
SI484766	532853	6846229	4850E	B	20	S	LB	N	5	Alpe			15	Aug18,2010	CW	
SI484767	532870	6846251	4875E	B	20	S	LB	N	15	Alpe			5	Aug18,2010	CW	
SI484768	532887	6846274	4900E	B	25	S	DB	N	15	Alpe			10	Aug18,2010	CW	
SI484769	532902	6846293	4925E	B	25	S	DB	N	15	Alpe			10	Aug18,2010	CW	
SI484770	532917	6846312	4950E	B	25	S	DB	N	10	Alpe			10	Aug18,2010	CW	
SI484771	532932	6846331	4975E	B	20	S	DB	N	10	Alpe			10	Aug18,2010	CW	
SI484772	532946	6846349	5000E	B	25	S	DG	N	15	Alpe			5	Aug18,2010	CW	
SI484773	532961	6846369	5025E	B	20	S	DB	N	5	Alpe			10	Aug18,2010	CW	
SI484774	532976	6846390	5050E	B	20	S	LB	N	10	Alpe			15	Aug18,2010	CW	
SI484775	532991	6846410	5075E	B	20	S	LB	N	5	Alpe			10	Aug18,2010	CW	
SI484776	533007	6846431	5100E	B	25	S	LB	N	15	Alpe			5	Aug18,2010	CW	
SI484777	533022	6846450	5125E	B	20	S	LB	N	15	Alpe			5	Aug18,2010	CW	
SI484778	533038	6846469	5150E	B	20	S	LB	N	5	Alpe			10	Aug18,2010	CW	
SI484779	533053	6846488	5175E	B	25	S	LB	N	10	Alpe			10	Aug18,2010	CW	
SI484780	533069	6846507	5200E	B	20	S	LB	N	20	Alpe			5	Aug18,2010	CW	
SI484781	533084	6846527	5225E	B	25	S	LB	N	10	Alpe			10	Aug18,2010	CW	
SI484782	533100	6846547	5250E	B	20	S	LB	N	10	Alpe			10	Aug18,2010	CW	
SI484783	533115	6846567	5275E	B	25	S	LB	N	15	Alpe			10	Aug18,2010	CW	
SI484784	533131	6846588	5300E	B	20	S	DB	N	10	Alpe			10	Aug18,2010	CW	
SI484785	533146	6846610	5325E	B	15	S	DB	N	10	Alpe			10	Aug18,2010	CW	
SI484786	533161	6846632	5350E	B	15	S	DB	N	10	Alpe			15	Aug18,2010	CW	
SI484787	533176	6846654	5375E	B	20	S	LB	N	10	Alpe			10	Aug18,2010	CW	
SI484788	533190	6846670	5400E	B	15	S	LB	N	10	Alpe			10	Aug18,2010	CW	
SI484789	533701	6845952	5350N 5150E	B	20	S	DB	N	20	Alpe			10	Aug18,2010	CW	
SI484790	533684	6845930	5125E	B	15	S	LB	N	5	Alpe			10	Aug18,2010	CW	
SI484791	533668	6845909	5100E	B	20	S	DB	N	10	Alpe			10	Aug18,2010	CW	
SI484792	533652	6845888	5075E	B	15	S	LB	N	15	Alpe			10	Aug18,2010	CW	
SI484793	533636	6845867	5050E	B	15	S	LB	N	10	Alpe			10	Aug18,2010	CW	
SI484794	533620	6845846	5025E	B	15	S	LB	N	10	Alpe			10	Aug18,2010	CW	
SI484795	533756	6845748	5200N 5025E	B	25	S	LB	N	20	Alpe			5	Aug18,2010	CW	
SI484796	533770	6845770	5050E	B	20	S	LB	N	15	Alpe			10	Aug18,2010	CW	
SI484797	533784	6845792	5075E	B	20	S	LB	N	20	Alpe			10	Aug18,2010	CW	
SI484798	533798	6845814	5100E	B	20	S	LB	N	5	Alpe			10	Aug18,2010	CW	
SI484799	533812	6845836	5125E	B	20	S	LB	N	15	Alpe			10	Aug18,2010	CW	
SI484800	533825	6845859	5150E	B	20	S	LB	N	10	Alpe			10	Aug18,2010	CW	1

SM268901	533788	6843598	L3100E 40+25N	B	40	30	BRN		5	FIR			5		CT/ML	
SM268902	533768	6843613	50N	B	20	30	BRN		10	FIR			2		CT/ML	
SM268903	533748	6843628	75N	B	50	35	BRN		10	FIR			2		CT/ML	
SM268904	533728	6843643	41+00N	BC	50	25	OR		30	FIR			0		CT/ML	
SM268905	533708	6843658	25N	B	40	25	BRN		10	FIR			2		CT/ML	
SM268906	533689	6843673	50N	B	40	15	BRN		5	FIR			5		CT/ML	
SM268907	533669	6843688	75N	B	30	25	OR		10	FIR			2		CT/ML	
SM268908	533650	6843703	42+00N	B	20	25	OR		10	FIR			2		CT/ML	
SM268909	533630	6843718	25N	B	50	25	OR		10	FIR			5		CT/ML	
SM268910	533610	6843733	50N	B	60	25	GRY		5	FIR			5		CT/ML	FROST BOIL
SM268911	533590	6843748	75N	B	60	40	GRYOR		5	FIR			2		CT/ML	
SM268912	533574	6843766	43+00N	B	50	55	GRY		10	FIR			5		CT/ML	
SM268913	533548	6843782	25N	B	10	60	BRN		30	FIR			2		CT/ML	
SM268914	533661	6843819	L3200E 42+60N	B	30	40	BRN		10	FIR			5		CT/ML	
SM268915	533657	6843810	4260N 31+90E	B	50	50	GRY		10	FIR			2		CT/ML	
SM268916	533652	6843801	80E	B	50	45	BRNGRY		10	FIR			2		CT/ML	
SM268917	533647	6843792	70E	B	50	45	BRNGRY		10	FIR			5		CT/ML	
SM268918	533642	6843783	60E	BC	50	50	GOLD		10	FIR			0		CT/ML	
SM268919	533637	6843774	50E	B	50	50	BRNOR		5	FIR			2		CT/ML	
SM268920	533631	6843781	42+70N 31+50E	B	50	35	BRNOR		5	FIR			2		CT/ML	
SM268921	533636	6843790	60E	B	50	40	BRNOR		10	FIR			0		CT/ML	
SM268922	533640	6843798	70E	BC	50	40	BRNOR		10	FIR			0		CT/ML	
SM268923	533644	6843806	80E	B	50	40	ORGRY		10	FIR			0		CT/ML	
SM268924	533648	6843814	90E	B	50	40	GRY		10	FIR			0		CT/ML	
SM268925	533653	6843822	L3200E 42+70N	B	50	50	BRN		10	FIR			0		CT/ML	
SM268926	533669	6843826	4260N 32+10E	B	40	50	BRN		10	FIR			2		CT/ML	
SM268927	533675	6843834	20E	B	50	50	BRN		5	FIR			0		CT/ML	
SM268928	533681	6843841	30E	B	50	50	BRN		5	FIR			0		CT/ML	
SM268929	533687	6843849	40E	B	40	60	BRN		5	FIR			0		CT/ML	
SM268930	533692	6843857	50E	B	60	50	BRNGRY		20	FIR			0		CT/ML	
SM268931	533686	6843862	4270N 32+50E	B	60	50	BRNGRY		20	FIR			0		CT/ML	
SM268932	533679	6843854	40E	B	50	60	BRNGRY		20	FIR			0		CT/ML	
SM268933	533673	6843846	30E	B	50	60	BRNGRY		20	FIR			0		CT/ML	
SM268934	533666	6843838	20E	B	60	60	BRN		5	FIR			5		CT/ML	
SM268935	533659	6843830	10E	B	50	60	BRNOR		20	FIR			5		CT/ML	
SM268936	533650	6843838	4280N 32+10E	B	50	50	BRN		5	FIR			5		CT/ML	
SM268937	533655	6843847	20E	B	60	50	BRN		15	FIR			5		CT/ML	
SM268938	533660	6843856	30E	B	50	50	BRN		15	FIR			5		CT/ML	
SM268939	533665	6843864	40E	B	50	50	BRNGRY		15	FIR			5		CT/ML	
SM268940	533670	6843872	50E	B	50	50	BRN		15	FIR			5		CT/ML	
SM268941	533672	6843884	4290N 32+50E	B	50	50	BRN		15	FIR			5		CT/ML	
SM268942	533666	6843874	40E	B	40	50	BRNOR		10	FIR			5		CT/ML	
SM268943	533660	6843864	32+30E	B	50	50	BRN		10	FIR			2		CT/ML	
SM268944	533654	6843854	20E	B	50	50	BRN		10	FIR			2		CT/ML	
SM268945	533648	6843844	10E	B	40	50	BRN		50	FIR			2		CT/ML	
SM268946	533606	6843800	43+00N 31+50E	B	50	35	BRN		10	FIR			2		CT/ML	
SM268947	533612	6843810	60E	B	40	55	BRN		10	FIR			2		CT/ML	
SM268948	533618	6843820	70E	B	50	60	BRNOR		10	FIR			2		CT/ML	
SM268949	533624	6843830	80E	B	50	60	BRN		10	FIR			2		CT/ML	
SM268950	533630	6843840	90E	B	60	60	BRN		5	FIR			0		CT/ML	
SM268951	533636	6843849	32+10E	B	60	40	BRNOR		10	FIR			0		CT/ML	
SM268952	533640	6843861	20E	B	70	60	BRNGRYOR		10	FIR			0		CT/ML	
SM268953	533645	6843873	30E	B	60	70	BRN		5	FIR			10		CT/ML	
SM268954	533650	6843885	40E	B	50	70	BRN		15	FIR			10		CT/ML	
SM268955	533654	6843897	50E	B	70	70	BRNGRY		25	FIR			10		CT/ML	
SM268956	533626	6843850	L3200E 43+10N	B	70	50	BRN		10	FIR			2		CT/ML	
SM268957	533621	6843841	31+90E	B	50	50	BRN		5	FIR			10		CT/ML	
SM268958	533616	6843832	80E	B	60	50	RN		5	FIR			2		CT/ML	
SM268959	533611	6843823	70E	B	60	50	BRN		5	FIR			2		CT/ML	
SM268960	533606	6843814	60E	B	70	50	ORGRYBRN		5	FIR			2		CT/ML	
SM268961	533600	6843804	50E	B	60	50	GRYBRN		10	FIR			2		CT/ML	

SM268962	533596	6843808	43+20N 31+50E	B	70	40	GRYBRN		5	FIR			2		CT/ML	
SM268963	533599	6843818	60E	B	70	50	GRYBRN		5	FIR			2		CT/ML	
SM268964	533602	6843829	70E	B	60	50	GRYBRNOR		10	FIR			2		CT/ML	
SM268965	533606	6843839	80E	B	70	40	GRYBRNOR		5	FIR			2		CT/ML	
SM268966	533610	6843850	90E	B	70	50	GRYBRNOR		5	FIR			2		CT/ML	
SM268967	533613	6843860	L3200E 43+20N	B	70	40	ORBRN		10	FIR			1-		CT/ML	
SM268968	533618	6843867	32+10E	B	70	30	BRNGRY		10	FIR			2		CT/ML	
SM268969	533623	6843874	20E	B	50	40	BRNGRY		10	FIR			2		CT/ML	
SM268970	533628	6843881	30E	B	60	40	BRNGRY		10	FIR			2		CT/ML	
SM268971	533633	6843888	40E	B	60	40	BRNGRY		20	FIR			2		CT/ML	
SM268972	533638	6843894	50E	B	60	45	BRNGRY		10	FIR			2		CT/ML	
SM268973	533651	6843893	L4310N 32+50E	B	50	50	BRN		15	FIR			2		CT/ML	
SM268974	533647	6843883	40E	B	50	50	BRNGRY		10	FIR			2		CT/ML	
SM268975	533642	6843874	30E	B	60	50	BRNGRY		15	FIR			2		CT/ML	
SM268976	533638	6843864	20E	B	50	40	BRNGRY		10	FIR			2		CT/ML	
SM268977	533633	6843855	10E	B	60	40	BRNGRY		15	FIR			2		CT/ML	
SM268978	533529	6843793	L31+00E 43+50N	B	60	25	BRNGRYOR		10	FIR			2		CT/ML	
SM268979	533508	6843805	75N	B	70	25	BRNGRY		10	FIR			2		CT/ML	
SM268980	533486	6843825	44+00N	B	70	30	BRNGRY		10	FIR			2		CT/ML	
SM268981	533472	6843840	25N	B	60	50	BRN		5	FIR			5		CT/ML	
SM268982	533445	6843854	50N	B	50	45	ORBRN		5	FIR			5		CT/ML	
SM268983	533427	6843871	75N	B	70	45	BRN		5	FIR			5		CT/ML	
SM268984	533406	6843884	45+00N	B	60	50	BRNOR		5	FIR			5		CT/ML	
SM268985	533388	6843903	25N	B	60	50	OR		5	FIR			5		CT/ML	
SM268986	533368	6843916	50N	B	50	40	OR		5	FIR			5		CT/ML	
SM268987	533351	6843933	75N	B	50	50	OR		5	FIR			5		CT/ML	
SM268988	533586	6843816	L43+30N 31+50E	B	50	30	BRN		5	FIR			2		CT/ML	OTHER SIDE OF VALLEY
SM268989	533590	6843826	60E	B	50	40	BRN		5	FIR			2		CT/ML	
SM268990	533594	6843835	70E	B	50	40	BRN		5	FIR			2		CT/ML	
SM268991	533598	6843844	80E	B	50	40	BRN		5	FIR			2		CT/ML	
SM268992	533602	6843853	90E	B	55	40	GRY		5	FIR			2		CT/ML	
SM268993	533607	6843863	L3200E 43+30N	B	70	35	BRNGRY		5	FIR			2		CT/ML	
SM268994	533611	6843872	32+10E	B	60	35	GRY		5	FIR			2		CT/ML	
SM268995	533612	6843876	L43+30N, 32+20E	BC	50	35	grey	N	40	fir				12/07/2010	ML	
SM268996	533619	6843885	L43+30N, 32+30E	BC	40	40	grey	N	40	fir				12/07/2010	ML	
SM268997	533626	6843894	L43+30N, 32+40E	BC	50	45	brn-gry	N	20	fir				12/07/2010	ML	
SM268998	533633	6843902	L43+30N, 32+50E	BC	70	40	brn-gry	N	30	fir				12/07/2010	ML	

All-Terrane Mineral Exploration Services

SILT SAMPLE DESCRIPTION SHEET

2010 Program, 3-Ace Property
Northern Tiger Resources Inc.

Sample No.	Easting	Northing	% Fines	Colour	Stream Grade	Stream Width	Date	Sampler	Comments
TG296322	531295	6848381	70	brown	steep	50	08-Jul	Craig	No Water
TG296323	531222	6848249	40	grey/brown	steep	70	08-Jul	Craig	Trib
TG296324	531223	6848143	60	brown	moderate	120	08-Jul	Craig	
TG296325	531299	6847913	80	brown	moderate	50	08-Jul	Craig	
TG296326	531499	6847786	90	brown	moderate	30	08-Jul	Craig	
TG296327	531713	6847654	70	brown	moderate	50	08-Jul	Craig	
TG296328	531798	6847435	80	brown	gentle	50	08-Jul	Craig	
TG296329	531896	6847182	70	grey/brown	moderate	60	08-Jul	Craig	
TG296330	531970	6847001	80	grey/brown	gentle	270	08-Jul	Craig	main river
TG296331	531874	6846781	70	grey/brown	gentle	180	08-Jul	Craig	
TG296332	531765	6846556	80	grey/brown	gentle	130	08-Jul	Craig	
TG296333	531784	6846517	90	grey/brown	gentle	30	08-Jul	Craig	Trib
TG296334	531802	6846500	80	grey/brown	moderate	40	08-Jul	Craig	2nd trib
TG296335	532060	6846528	60	brown	moderate	60	08-Jul	Craig	
TG296336	532277	6846423	70	brown	moderate	60	08-Jul	Craig	
TG296337	532456	6846370	80	brown	gentle	20	08-Jul	Craig	dry/top of stream
TG312301	534095	6844024	60	brown	steep	0.6	10-Aug	ML	
TG312302	534237	6843989	70	brown	steep	0.6	10-Aug	ML	
TG312303	534397	6844006	70	brown	moderate	1.5	10-Aug	ML	
TG312304	534568	6844010	80	gry-brn	steep	1.2	10-Aug	ML	
TG312305	534722	6843968	80	gry-brn	steep	1.2	10-Aug	ML	
TG312306	534843	6843896	80	gry-brn	steep	1.2	10-Aug	ML	Dry
TG312307	534948	6843780	80	gry-brn	moderate	1.2	10-Aug	ML	
TG312308	535060	6843680	80	gry-brn	moderate	1.5	10-Aug	ML	
TG312309	535194	6843611	80	gry-brn	gentle	1.5	10-Aug	ML	
TG312310	535329	6843508	80	gry-brn	gentle	1.5	10-Aug	ML	
TG312311	535468	6843446	90	gry-brn	steep	2.5	10-Aug	ML	
TG312312	534798	6843013	80	brown	moderate	0.9	11-Aug	ML	
TG312313	534934	6842944	50	brown	gentle	0.6	11-Aug	ML	Dry
TG312314	535382	6843047	70	brown	steep	0.3	11-Aug	ML	Dry
TI480048	530161	6851652	55	grey	Mod	1.5	Jul-08	CS	Mossmat; trib from west
TI480049	530181	6851671	60	grey	Mod	2	Jul-08	CS	Rare silt, mostly mossmat
TI480050	530234	6851484	50	gry-brn	Mod	0.5	Jul-08	CS	Dry; mossmat, rare silt
TI480095	533087	6844569	75	grey	moderate	0.6	16-Jul	CS	Abundant clay; includes mossmat
TI480096	533073	6844579	60	gry-brn	Steep	0.4	16-Jul	CS	Abundant sandy bank silt
TI480097	534029	6845558	60	grey	Steep	0.4	Jul-13	CS	Dry; mossmat, phyllite flakes
TI480098	534045	6845596	60	grey	Steep	0.2	Jul-13	CS	Fairly abundant silt; phyllite pebbles
TI480099	534077	6845612	70	gry-brn	Steep	0.6	Jul-13	CS	Mossmat, several sites, rare silt
TI480100	533985	6834790	75	gry-brn	Steep	0.4	Jul-13	CS	Mossmat, several sites, rare silt
TI480140	533557	6843987	80	gry-brn	Steep	0.4	23-Jul	CS	Dry; stabilized silt and mossmat
TI480141	531939	6848523	70	brown	Steep	0.2	22-Jul	CS	Dry, fairly abundant silt; wet upstream
TI480142	533271	6845479	65	Grey	Steep	0.3	21-Jul	CS	Dry; mossmat, near head of gulch
TI480143	533189	6845222	60	Grey	gentle	0.3	21-Jul	CS	Near spring; mossmat
TI480144	533076	6845303	55	Grey	Steep	0.8	21-Jul	CS	Dry; rare silt, mostly bank silts
TI480145	532897	6845395	70	Grey	moderate	1.5	21-Jul	CS	Mossmat; rare stream silt
TI480146	532723	6845335	90	Grey	Steep	1.2	21-Jul	CS	Mossmat; abnt quartz-phyllite float in creek
TI480147	532586	6845211	65	Grey	moderate	1.5	21-Jul	CS	Rare silt, mostly mossmat
TI480148	534552	6844602	80	gr-brn	moderate	0.5	20-Jul	CS	High organics, largely mossmat
TI480149	534250	6844890	45	dk brn	Steep	0.4	20-Jul	CS	Sparse silt; several sites
TI480150	533978	6845878	50	gry-brn	Steep	0.6	18-Jul	CS	Mostly bank silt and mossmat
TI480195	533405	6843780	75	grey	Steep	0.2	Jul-28	CS	Trickle, E side of gulch near panned sample (?)
TI480196	532852	6844064	90	gr-brn	gentle	0.3	Jul-28	CS	Active, abundant silt
TI480197	533112	6844194	80	grey	moderate	0.2	Jul-28	CS	Trickle, abundant silt
TI480198	535377	6846054	70	gr-brn	Steep	0.5	Jul-26	CS	mostly mossmat; intermittent flow
TI480199	535270	6846000	90	grey	Steep	0.4	Jul-26	CS	Locally wet; silt and mossmat

TI480200	533463	6843836	75	gr-brn	Steep	0.3	Jul-25	CS	Dry; stabilized silt, high organics
TI481165	529994	6852718	80	brown	gentle	150	19-Jul	CT, ML	
TI481166	530121	6852495	70	grey/brown	moderate	150	19-Jul	CT, ML	
TI481167	530104	6852196	65	grey/brown	moderate	100	19-Jul	CT, ML	
TI481168	529987	6852089	80	brown	moderate	30	19-Jul	CT, ML	Trib
TI481169	530063	6851951	80	brown	moderate	90	19-Jul	CT, ML	
TI481170	530321	6851429	70	brown	moderate	110	19-Jul	CT, ML	
TI481171	530446	6851216	90	grey/brown	steep	20	19-Jul	CT, ML	Trib
TI481172	530475	6851218	70	grey/brown	moderate	80	19-Jul	CT, ML	
TI481173	530462	6851058	90	grey/brown	moderate	30	19-Jul	CT, ML	Trib
TI481174	530515	6850993	70	grey/brown	moderate	160	19-Jul	CT, ML	
TI481175	530526	6850734	80	grey/brown	moderate	100	19-Jul	CT, ML	
TI481176	530535	6851698	95	brown	moderate	25	19-Jul	CT, ML	Trib
TI481177	530467	6850508	60	brown	gentle	70	19-Jul	CT, ML	
TI481178	530443	6850451	95	grey/brown	gentle	20	19-Jul	CT, ML	Trib
TI481179	530436	6850428	80	grey/brown	moderate	50	19-Jul	CT, ML	bigger trib
TI481180	530337	6850291	90	brown	moderate	130	19-Jul	CT, ML	
TI481181	530193	6850081	75	brown	moderate	130	19-Jul	CT, ML	
TI481201	530089	6849867	80	grey/brown	moderate	110	19-Jul	CT, ML	
TI481202	530086	6849794	90	grey/brown	moderate	20	19-Jul	CT, ML	Trib
TI481305	532407	6850446	80	brown	moderate	70	22-Jul	CT, ML	
TI481306	532668	6850415	70	grey/brown	moderate	50	22-Jul	CT, ML	
TI481307	532892	6850302	80	grey/brown	moderate	60	22-Jul	CT, ML	
TI481308	532983	6850212	80	grey/brown	moderate	50	22-Jul	CT, ML	Trib
TI481309	533115	6850193	90	brown	moderate	80	22-Jul	CT, ML	
TI481310	533381	6849938	90	brown	gentle	120	22-Jul	CT, ML	Trib
TI481311	533248	6849911	80	grey/brown	moderate	60	22-Jul	CT, ML	
TI481312	533220	6849649	90	grey/brown	gentle	110	22-Jul	CT, ML	
TI481313	533203	6849441	90	brown	gentle	20	22-Jul	CT, ML	Trib
TI481314	533246	6849394	80	grey/brown	gentle	70	22-Jul	CT, ML	
TI481315	533219	6849294	70	grey/brown	gentle	50	22-Jul	CT, ML	Trib
TI481316	533200	6849155	80	grey/brown	gentle	130	22-Jul	CT, ML	
TI481317	533157	6849121	90	grey/brown	moderate	40	22-Jul	CT, ML	Trib
TI481318	533191	6848899	80	grey/brown	gentle	180	22-Jul	CT, ML	
TI481319	533111	6848641	70	brown	gentle	180	22-Jul	CT, ML	
TI481320	533047	6848587	90	brown	gentle	30	22-Jul	CT, ML	Trib
TI481321	532993	6848430	80	grey/brown	gentle	160	22-Jul	CT, ML	
TI481322	532815	6848237	90	grey/brown	gentle	200	22-Jul	CT, ML	
TI481323	532650	6848076	90	grey/brown	gentle	180	22-Jul	CT, ML	
TI481324	532520	6847803	80	brown	gentle	170	22-Jul	CT, ML	
TI481325	532399	6847563	80	grey/brown	gentle	110	22-Jul	CT, ML	
TI481326	532238	6847388	90	brown	gentle	190	22-Jul	CT, ML	
TI481472	528336	6853104	80		moderate	3	03-Aug	CT, CW	Dry
TI481473	528337	6852854	50		moderate	1	03-Aug	CT, CW	Wet
TI481474	528267	6852647	30		gentle	1.5	03-Aug	CT, CW	Dry
TI481475	528126	6852502	40		gentle	2	03-Aug	CT, CW	Dry, end of stream outwash
TI481476	528350	6852172	90		moderate	2.5	03-Aug	CT, CW	Dry
TI481477	528214	6851993	85		moderate	0.4	03-Aug	CT, CW	Dry

532000 533000 534000 535000

6846000 6844000

N

Approx Trace of Green Zone

Hoito Showing
Qz-Aspy-Py Vein

Approx. trace of "Green Mile"

North Zone, V.G.

Sleeping Giant Zone, V.G.

Main Zone, V.G.

LEGEND

Upper Proterozoic - Lower Cambrian

Hyland Group, Yusezyu Formation

- 4 $PrCh_l$ *Limestone, thin to medium bedded, typically dark grey; minor interbedding with limy sandstone*
- 3 $PrCh_{sc}$ *Simlar to $PrCh_s$; weak to moderate chlorite alteration*
- 2 $PrCh_s$ *Slate to phyllite; thinly bedded, typically very fine-grained with strongly developed cleavage*
- 1 $PrCh_c$ *Quartz-Pebble Conglomerate, including greywacke, "grits," and coarse- to medium-grained sandstone. Subarkosic composition; 60-70% rounded quartz grains, 25-30% feldspar grains, typically strongly argillically altered*

SYMBOLS

- Bedding
- Joint
- Vein
- Fault
- F_3 Fold Axis
- Cleavage, 1st Generation
- Cleavage, 2nd Generation
- Thrust
- Small Outcrop/Rubblecrop
- F_3 Synform Axial Trace, Inferred
- F_3 Antiform Axial Trace, Inferred
- Fault, Observed
- Fault, Inferred
- Lithological Contact
- 3Ace Au Qz Vein Showings
- Outcrop
- Rubblecrop
- Significant arsenical +/- scoroditic zones in rubblecrop +/- outcrop

ABBREVIATIONS

alt: Alteraion
ank: Ankerite
arg: Argillic alteration
brecc: Brecciated
calc: Calcareous
carb: Carbonate altered
chl: Chlorite
cpy: Chalcopyrite
flt: fault
Gwke: Greywacke
lim: Limonite
loc: Local
Lst: Limestone
Lsst: Limy Siltstone
mass: Massive
mod: Moderate
O/C: Outcrop
Phy: Phyllite
phyl: Phyllic alteration
QPC: Quartz-Pebble-Conglomerate
Qz: Quartz
Qzte: Quartzite
Qz Vn: Quartz Vein
R/C: Rubblecrop
scor: Scorodite
Sh: Shale
sil: silicified
Sl: Slate
Sst: Sandstone
str: Strong
stwk: Stockwork
Ta: Talus
tr: trace
wk: weak

Meters
0 125 250 500

Northern Tiger Resources Inc

Map 1a: Geology, S. Half
3 Ace Property

Yukon Territory, Canada

NTS 105H09/H16
UTM Nad 83, Zone 9
Edmonton, AB

Scale: 1:5,000
Watson Lake Mining District
February, 2011

528000 529000 530000 531000 532000 533000

6852000 6850000 6848000 6846000

N

QPC, QVns
QPC
Shale
QPC(?)
Shale, w/ maroon colouration
R/C: Lst
Shale,
QPC, sil, chl, QVns
Ta: Lst, incl lst cong
Calc. Sst, Qz stringers
Calc Sst
R/C: Lst
Slide, largely Sandstone-QPC
Phy, lim, QVns
QPC, sheeted QVns
Ta: QPC, grits, QVns
Ta: Wk carb QPC-Sst
Ta: QPC, stkwk, mod bxwrk
Lst
Lst, frac, carb vns
Ta: Lst
Ta: QPC
R/C: QVn, QPC, tr Gn/Cpy/Aspy
R/C: Phy
Carb-alt Sst
R/C: Gwke-Qzte
Qzte-Sst, QVns
Sst-"Grit" minor Qz
Phy-Sl
Gwke, wk arg alt
Gwke, wk carb
R/C: calc Sst
R/C: Gwke, wk chl
R/C: QPC
Phy
Gwke-QPC
QPC-As, QVns, arg
R/C-O/C: QPC-Sst, QVns
R/C: QPC, QVns
Ta: Sst-grit
Ta-R/C: Lst
Sst-grit, chl
Sst-grit
QPC-Grit
QPC-Sst
QPC, sil
QPC, ser
Sst-QPC, trn, Py, wk scor
QPC, loc scor
Gwke-QPC
R/C: QPC
Ta: QPC, loc Sst
Ta: QPC, abnt QVns, sil
R/C: Gwke-QPC, loc ca
R/C: Sst-Gwke

1 2 4

1940 1920 1900 2020 1980 2060 2080 2040 2000 1880 1780 1580 1560 1460 1500 1840 1540 1520 1600 1620 1640 1660 1680 1720 1760 1800 1820 1860 1740 1700 1960 1940 1880 1900 1660 1720 1680 1820 1980 1960 1940 1920 1900 1880 1940 1460 1640 1520 1480 1500 1440 1400 1360 1320 1280 1760 1860 1880 1740 1600 1440 1220 960 1080 1400 1360 1540 1560 1580 1200 1180 1140 1100 1040 1020 1160 1240 980 1260 1420 1380 1280 1240 1260 1300 1060 1000 1220 1120 1200 1180 1220 1460

LEGEND

Upper Proterozoic - Lower Cambrian
Hyland Group, Yusezyu Formation

- 4 $PrCh_l$ — *Limestone, thin to medium bedded, typically dark grey; minor interbedding with limy sandstone*
- 3 $PrCh_{sc}$ — *Simlar to $PrCh_s$; weak to moderate chlorite alteration*
- 2 $PrCh_s$ — *Slate to phyllite; thinly bedded, typically very fine-grained with strongly developed cleavage*
- 1 $PrCh_c$ — *Quartz-Pebble Conglomerate, including greywacke, "grits," and coarse- to medium-grained sandstone. Subarkosic composition; 60-70% rounded quartz grains, 25-30% feldspar grains, typically strongly argillically altered*

SYMBOLS

- Bedding
- Joint
- Vein
- Fault
- F_3 Fold Axis
- Cleavage, 1st Generation
- Cleavage, 2nd Generation
- Thrust
- Small Outcrop/Rubblecrop
- F_3 Synform Axial Trace, Inferred
- F_3 Antiform Axial Trace, Inferred
- Fault, Observed
- Fault, Inferred
- Lithological Contact
- 3Ace Au Qz Vein Showings
- Outcrop
- Rubblecrop
- Significant arsenical +/- scoroditic zones in rubblecrop +/- outcrop

ABBREVIATIONS

alt: Alteraion
ank: Ankerite
arg: Argillic alteration
brecc: Brecciated
calc: Calcareous
carb: Carbonate altered
chl: Chlorite
cpy: Chalcopyrite
flt: fault
Gwke: Greywacke
lim: Limonite
loc: Local
Lst: Limestone
Lsst: Limy Siltstone
mass: Massive
mod: Moderate
O/C: Outcrop
Phy: Phyllite
phyl: Phyllic alteration
QPC: Quartz-Pebble-Conglomerate
Qz: Quartz
Qzte: Quartzite
Qz Vn: Quartz Vein
R/C: Rubblecrop
scor: Scorodite
Sh: Shale
sil: silicified
Sl: Slate
Sst: Sandstone
str: Strong
stwk: Stockwork
Ta: Talus
tr: trace
wk: weak

Meters
0 250 500 1,000

NORTHERN TIGER RESOURCES INC.

Northern Tiger Resources Inc

Map 1b: Geology, N. Half
3 Ace Property

Yukon Territory, Canada

NTS 105H09/H16
UTM Nad 83, Zone 9
Edmonton, AB

Scale: 1:7,000
Watson Lake Mining District
February, 2011


2010 Rock Samples
Au (g/t)
<0.25
0.25-0.50
0.50-1.0
1.0-10.0
10.0-1,013.5
2010 Soil Samples
Au (g/t)
<0.025
0.025 - 0.05
0.05 - 0.10
0.10 - 0.50
0.50 - 19.32
2010 Silt Samples
Au (g/t)
<0.01
0.01 - 0.02
0.02 - 0.03
0.03 - 0.05
0.05 - 0.11
HOITO SHOWING
GREEN ZONE WEST
SLEEPING GIANT
NORTH ZONE
MAIN ZONE
Nahanni Range Road
Little Hyland River
Legend
2010 Drill Camp
Road
Stream
20m Contours
Meters
0
250
500
1,000
N
Northern Tiger Resources Inc
Map 2: Au Geochemical Map
3 Ace Property
Yukon Territory, Canada
NTS 105H09/H16
UTM Nad 83, Zone 9
Edmonton, AB
Scale: 1:10,000
Watson Lake Mining District
February, 2011
531500
532000
532500
533000
533500
534000
534500
535000
535500
536000
536500
6846500
6846000
6845500
6845000
6844500
6844000
6843500

533600 533650 533700 533750

6843850 6843800

N

Legend

20m Contours

Discovery Vein, Projected

2010 Soil Samples

Au (g/t)

- <0.025
- 0.025 - 0.05
- 0.05 - 0.10
- 0.10 - 0.50
- 0.50 - 19.32

2010 Rock Samples

Au (g/t)

- <0.25
- 0.25-0.50
- 0.50-1.0
- 1.0-10.0
- >10.0

Meters

0 25 50

NORTHERN TIGER RESOURCES INC

Northern Tiger Resources Inc

Map 3: Au Geochemistry

3 Ace Property - Main Zone

Yukon Territory, Canada

NTS 105H09/H16
UTM Nad 83, Zone 9
Edmonton, AB

Scale: 1:500
Watson Lake Mining District
February, 2011


533000
533500
534000
534500
535000
6847000
6846500
6846000
6845500
6845000
N
2010 Silt Samples
Au (g/t)
0.005 - 0.011
0.012 - 0.018
0.019 - 0.027
0.028 - 0.049
>0.050
2010 Rock Samples
Au (g/t)
<0.25
0.25-0.50
0.50-1.0
1.0-10.0
>10.0
2010 Soil Samples
Au (g/t)
<0.025
0.025-0.050
0.050-0.100
0.100-0.500
>0.500
Legend
Stream
20m Contours
Meters
0
125
250
500
Northern Tiger Resources
Map 4: Au Geochemistry
3 Ace Property - Green Zone
Yukon Territory, Canada
NTS 105H09/H16
UTM Nad 83, Zone 9
Edmonton, AB
Scale: 1:2,500
Watson Lake Mining District
February, 2011


534600
534700
6844200
6844100
N
2010 Rock Samples
Au (g/t)
<0.25
0.25-0.50
0.50-1.0
1.0-10.0
>10.0
1280
1260
1240
1220
1200
Legend
Vein Segments, Inferred
20m Contours
Meters
0
25
50
Northern Tiger Resources Inc
Map 5: Au Geochemistry
3 Ace Property - Sleeping Giant Zone
Yukon Territory, Canada
NTS 105H09/H16
UTM Nad 83, Zone 9
Edmonton, AB
Scale: 1:1,000
Watson Lake Mining District
February, 2011

Assessment Report on the
2010 Geological and Geochemical Programs
On the 3ACE Property, Southeast Yukon
Northern Tiger Resources Inc.

Volume 2: Appendix 3, Original Results

YC72439 – YC72448 (KING 1-10), YC72452 – YC72459 (KING 11-18),
YC89511 – YC89520 (KING 19-28), YC72724 – YC72733 (KING 29-38),
YC73284 – YC73295 (KING 39-50), YC73848 – YC73859 (KING 51-62),
YC89521 – YC89530 (KING 63-72), YD07129 – YD07138 (KING 73-82),
YD10860 – YD10869 (KING 83-92), YD10900 – YD10919 (KING 93-112),
YD 07109 – YD07128 (ACE 1-20), YD59328 – YD59459 (ACE 21-152),
YD29165 – YD29172 (JACK 5-12), YD29183 – YD29199 (JACK 23-39),
YD10920 – YD10924 (JAN 1-4)

Little Hyland River area, southeast Yukon

NTS Sheets 105H09, 105H16
61°43'37"N Lat, 128°21'46"W Long
UTM (NAD 83): 533700E, 6843800N, Zone 9
Watson Lake Mining District

Effective Date: Nov 26, 2010

For: Northern Tiger Resources Inc.
Suite 220 – 17010 103rd Ave.
Edmonton, Alberta T5S 1K7
Phone (780) 428-3465 Fax (780) 428-3476
Email: douellette@northern-tiger.com

By: Carl M. Schulze, BSc, PGeo
All-Terrane Mineral Exploration Services
35 Dawson Rd
Whitehorse, Yukon Y1A 5T6
Tel: 867-633-4807
Fax: 867-633-4883
allterrane@northwestel.net

Chris Buchanan
Buchanan Geoscience Services
10 Prospero Place
St. John's, NL
A1B 3W7
709-754-3115
crbuchanan@mun.ca

Appendix 3 : Original Sample Results

Sample_no	X_nad83z9	Y_nad83z9	Sample_Type	Sample_Description	Zone	Add_Com	Lithology	Modifier	Colour	Mineral_1	Min_1_Amt_per	Min_2	Amt_per	Date	Sampler	Comments
RI034654	533651	6843820	Grab	Float	Main	Qz Boulder	Qtz	boulder	wh	Au	tr			13-Jun-10	DO	boulder 1.5m in front of OC; VG dissem
RI034655	533657	6843822	Grab	Outcrop	Main	Discovery Vn	QV	vn	wh	Au	tr			13-Jun-10	DO	from N end of vn; VG
RI034656	533650	6843828	Grab	Outcrop	Main	Discovery Vn	QV	vn	wh	Au	tr			13-Jun-10	DO	5m downslope fr vn; rx frag in vn locus for VG
RI034657	533657	6843818	Grab	Outcrop	Main	Discovery Vn	QV	vn	wh					13-Jun-10	DO	from material chipped off S end of vn
RI034658	533647	6843826	Grab	Float	Main	Qz Float	Qtz	frac	wh	Au	abndt			13-Jun-10	DO	fr downslope of vn; abndt VG frac & dissem
RI034659	533650	6843830	Grab	Float	Main	Qz Float	Qtz	frac	wh	Au	abndt	Aspy	tr	13-Jun-10	DO	abndt VG along frac & dissem, vfg aspy
RI034660	533650	6843832	Grab	Float	Main	Qz Boulder	Qtz	boulder	wh-gry	Au	tr	Aspy	tr	13-Jun-10	DO	gry clr aspy?; dissem VG w/ aspy
RI034661	533650	6843832	Grab	Rubblecrop?	Main	Discovery Vn Rcrop	Qtz		wh	Au	tr			13-Jun-10	DO	minor VG, crs qz xtals, very wh vn
RI034662	533657	6843819	Grab	Outcrop	Main	Discovery Vn	QV	frac	wh	Au	tr			13-Jun-10	DO	VG on fracs

Assay_No	Ttl_Smpl_g	+150Smpl_g	-150Smpl_g	Au+150gpmt	Au-150gpmt	AuTtl_gpmt	Au-150gpmt	Au-150gpmt
I034654	297.96	8.96	289.00	2105.59	20.90	83.58	21.31	20.48
I034655	323.67	13.67	310.00	504.17	8.96	29.88	8.92	8.99
I034656	317.63	11.63	306.00	22555.14	1284.55	2063.56	1238.66	1330.44
I034657	343.43	18.43	325.00	5706.45	301.55	591.65	303.38	299.73
I034658	363.81	20.81	343.00	30656.77	767.83	2477.09	779.79	755.86
I034659	339.77	18.77	321.00	43979.38	1937.23	4259.31	1953.82	1920.64
I034660	270.14	3.14	267.00	74737.26	554.32	1416.59	574.98	533.66
I034661	293.35	6.35	287.00	1649.76	85.82	119.66	88.34	83.30
I034662	317.78	11.78	306.00	89382.13	1566.36	4820.60	1518.70	1614.01

Certificate of Analysis

10-360-02025-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Dennis Ouellette
EMail: douellette@nothern-tiger.com

Attention: A.Terrane
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **None Given**
Description:

Date Received: 06/22/2010
Date Completed: 06/29/2010
Invoice:

Samples	Type	Preparation Description
9	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02025-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01
I034654	Rock	1.49	0.08	121.2	9	0.1	0.24	0.02	0.03	0.42	0.7	141	0.2	15.3	0.28
I034655	Rock	0.05	0.16	160.0	12	0.1	0.19	0.02	0.09	0.90	0.9	142	0.2	14.0	0.41
I034656	Rock	63.82	0.06	300.7	5	0.1	0.27	<0.01	0.11	0.32	0.8	147	0.1	7.7	0.31
I034657	Rock	26.44	0.44	466.9	30	0.2	0.21	<0.01	0.07	3.51	0.9	258	0.4	4.3	0.33
I034658	Rock	55.86	0.07	247.1	<5	0.1	0.58	<0.01	0.09	0.29	0.7	272	0.1	13.3	0.26
I034659	Rock	>100	0.15	2721.1	17	0.1	1.07	0.01	0.37	1.55	1.0	263	0.3	13.7	0.46
I034660	Rock	90.97	0.05	996.0	27	<0.05	0.62	0.01	0.11	0.23	0.8	234	0.1	11.0	0.30
I034661	Rock	27.42	0.08	234.9	7	0.1	0.08	<0.01	0.08	0.38	0.7	155	0.1	16.7	0.25
I034662	Rock	>100	0.34	2826.5	26	0.2	1.90	0.01	0.20	2.73	0.8	252	0.4	11.4	0.48

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02025-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10
I034654	Rock	0.3	2.3	<0.1	<0.01	0.03	<0.5	3.6	<0.01	24	2.07	<0.01	0.1	4.7	<10
I034655	Rock	0.8	2.4	<0.1	<0.01	0.06	<0.5	4.4	<0.01	41	1.57	<0.01	0.2	4.6	14
I034656	Rock	0.3	2.6	<0.1	0.05	0.02	<0.5	6.5	<0.01	54	1.45	<0.01	0.1	4.8	28
I034657	Rock	1.7	2.6	<0.1	<0.01	0.16	1.6	4.0	0.02	46	1.29	<0.01	0.2	4.1	18
I034658	Rock	0.3	2.7	<0.1	0.01	0.02	<0.5	5.0	<0.01	27	1.36	<0.01	<0.1	3.2	12
I034659	Rock	0.6	2.2	<0.1	0.03	0.06	0.8	3.8	<0.01	34	1.31	<0.01	0.1	3.3	11
I034660	Rock	0.2	2.6	<0.1	<0.01	0.02	<0.5	3.3	<0.01	36	1.27	<0.01	0.1	6.5	<10
I034661	Rock	0.4	2.3	<0.1	<0.01	0.03	<0.5	2.5	<0.01	42	1.44	<0.01	<0.1	3.0	14
I034662	Rock	1.7	2.2	<0.1	0.01	0.15	1.4	3.3	0.02	32	1.37	<0.01	0.1	4.0	27

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02025-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02
I034654	Rock	40.5	1.5	<0.005	<0.01	3.36	<0.1	<0.5	0.3	3.1	<0.05	<0.05	<0.2	<0.005	<0.02
I034655	Rock	41.4	3.1	<0.005	<0.01	3.14	0.1	1.1	0.5	3.8	<0.05	0.07	0	<0.005	<0.02
I034656	Rock	211.6	0.8	<0.005	<0.01	4.20	<0.1	<0.5	0.2	5.0	<0.05	0.06	<0.2	<0.005	<0.02
I034657	Rock	83.9	8.2	0.01	<0.01	3.38	0.4	<0.5	0.6	7.6	<0.05	0.10	1	0.006	<0.02
I034658	Rock	316.7	0.9	0.01	<0.01	3.97	<0.1	<0.5	<0.2	4.1	<0.05	<0.05	<0.2	<0.005	<0.02
I034659	Rock	455.4	2.9	<0.005	0.04	6.35	0.2	<0.5	0.3	10.8	<0.05	0.14	0	<0.005	<0.02
I034660	Rock	290.4	0.8	<0.005	0.03	3.90	<0.1	<0.5	<0.2	3.0	<0.05	<0.05	<0.2	<0.005	<0.02
I034661	Rock	17.1	1.3	<0.005	<0.01	2.89	0.1	<0.5	0.2	2.7	<0.05	<0.05	<0.2	<0.005	<0.02
I034662	Rock	800.1	7.6	<0.005	0.03	9.04	0.3	1.1	0.7	7.7	<0.05	<0.05	1	0.005	0.03

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02025-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
I034654	Rock	<0.1	<1	5.28	<0.1	42	<0.5
I034655	Rock	<0.1	4	3.25	0.1	53	1.0
I034656	Rock	0	<1	1.72	<0.1	50	<0.5
I034657	Rock	0	2	0.25	0.3	48	3.1
I034658	Rock	<0.1	<1	<0.1	<0.1	44	<0.5
I034659	Rock	0	1	1.82	0.3	50	1.4
I034660	Rock	<0.1	<1	1.78	<0.1	44	<0.5
I034661	Rock	<0.1	<1	<0.1	<0.1	42	<0.5
I034662	Rock	0	3	0.22	0.2	43	2.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02025-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01
QCV1006-00462-0001-BLK		<0.01	<0.01	0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2	<0.01
I034654	Rock	1.49	0.08	121.2	9	0.1	0.24	0.02	0.03	0.42	0.7	141	0.2	15.3	0.28
I034654 Dup		0.78	0.08	115.4	9	0.1	0.25	0.02	0.04	0.41	0.7	138	0.2	15.7	0.28
QCV1006-00462-0003-BLK		<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2	<0.01
STD-SY-4 expected					340	2.6				122.00	2.8	12	1.5	7.0	
STD-SY-4 result		0.16	>10	10.2	320	3.3	0.06	5.75	0.10	105.71	2.8	8	1.5	8.8	4.52

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02025-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10
QCV1006-00462-0001-BLK		<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1	<0.2	<10
I034654	Rock	0.3	2.3	<0.1	<0.01	0.03	<0.5	3.6	<0.01	24	2.07	<0.01	0.1	4.7	<10
I034654 Dup		0.3	2.2	<0.1	<0.01	0.03	<0.5	3.6	<0.01	24	2.07	<0.01	0.1	4.2	<10
QCV1006-00462-0003-BLK		<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1	<0.2	<10
STD-SY-4 expected		35.0		10.60			58.0	37.0					13.0	9.0	
STD-SY-4 result		29.2	0.4	1.26	0.04	1.36	47.3	36.2	0.32	722	0.31	5.10	12.2	6.0	566

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02025-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02
QCV1006-00462-0001-BLK		<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2	<0.005	<0.02
I034654	Rock	40.5	1.5	<0.005	<0.01	3.36	<0.1	<0.5	0.3	3.1	<0.05	<0.05	<0.2	<0.005	<0.02
I034654 Dup		40.3	1.4	0.01	<0.01	3.50	<0.1	<0.5	0.3	3.0	<0.05	<0.05	<0.2	<0.005	<0.02
QCV1006-00462-0003-BLK		<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2	<0.005	<0.02
STD-SY-4 expected		10.0	55.0				1.1			1191.0	0.90		1		
STD-SY-4 result		12.4	46.2	0.02	<0.01	<0.05	0.8	<0.5	7.1	990.4	1.13	0.21	1	0.170	0.23

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02025-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1006-00462-0001-BLK		<0.1	<1	<0.1	<0.1	<2	<0.5
I034654	Rock	<0.1	<1	5.28	<0.1	42	<0.5
I034654 Dup		<0.1	<1	4.96	<0.1	43	<0.5
QCV1006-00462-0003-BLK		<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected		1	8		119.0	93	517.0
STD-SY-4 result		1	1	0.59	98.7	130	55.4

Certificate of Analysis

10-360-02304-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description:

Date Received: 07/27/2010
Date Completed: 08/10/2010
Invoice:

Samples	Type	Preparation Description
34	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-1AT-GV	Au, 1AT, Gravimetric
Au-2AT-AA	Au, 2AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02304-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA ppb 5	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480001	Rock		677	0.79	0.56	801.2	42	0.2	0.07	0.02	<0.01	5.35	1.1	222	1.1
RI 480002	Rock		254	0.86	0.27	1752.4	32	0.2	0.10	0.04	0.04	2.48	1.5	197	0.6
RI 480003	Rock		148	0.82	2.01	2920.8	100	0.7	0.10	0.01	0.55	22.45	1.6	217	1.7
RI 480004	Rock	26.938	>10000	1.31	1.51	1797.1	86	0.9	0.10	0.03	0.24	20.42	1.7	228	1.8
RI 480005	Rock		48	0.63	1.79	539.4	20	0.2	0.07	0.02	0.05	27.77	3.1	249	0.6
RI 480006	Rock		26	0.52	2.28	145.8	124	0.7	0.08	<0.01	0.03	22.09	2.8	201	1.3
RI 480007	Rock	760.995	>10000	62.00	0.12	359.7	17	0.1	0.22	<0.01	0.05	0.95	1.1	308	0.2
RI 480008	Rock		793	0.65	2.75	1528.0	164	1.3	0.04	0.01	0.13	29.83	2.7	239	2.1
RI 480009	Rock	111.611	>10000	4.30	0.15	283.5	14	0.2	0.18	<0.01	0.05	1.36	1.1	224	0.2
RI 480010	Rock		240	0.54	2.96	1414.6	178	1.4	0.06	0.01	0.10	30.42	1.7	218	2.1
RI 480011	Rock	208.083	>10000	6.80	0.12	236.3	12	0.1	0.21	<0.01	0.03	1.09	1.1	320	0.2
RI 480012	Rock		1350	0.32	2.13	3332.5	101	1.1	0.06	0.02	0.49	28.15	3.9	269	1.9
RI 480013	Rock	795.917	>10000	50.19	0.33	1884.1	29	0.2	0.68	0.01	0.06	3.69	2.2	247	0.4
RI 480014	Rock	64.585	>10000	3.87	0.70	300.6	52	0.4	0.18	<0.01	0.07	8.79	1.7	223	0.7
RI 480015	Rock	172.651	>10000	14.32	0.28	243.1	37	0.2	0.20	<0.01	0.03	2.05	1.1	170	0.4
RI 480016	Rock		150	0.59	0.16	56.9	11	0.1	0.03	0.02	<0.01	1.24	1.3	206	0.2
RI 480017	Rock		121	0.67	2.41	612.0	133	0.8	0.08	0.02	0.16	29.82	1.5	178	2.9
RI 480018	Rock		242	2.40	2.23	1429.1	122	0.7	0.98	0.01	0.38	32.69	1.6	202	2.6
RI 480019	Rock		30	0.84	0.84	864.0	25	0.2	0.07	0.01	0.17	8.27	1.1	228	0.3
RI 480020	Rock	90.803	>10000	5.04	0.80	3418.7	16	0.2	1.81	0.02	0.60	5.92	3.2	236	0.3
RI 480021	Rock		1212	1.00	1.02	4396.3	25	0.3	0.21	0.02	0.35	9.69	1.3	208	0.4
RI 480022	Rock		436	0.67	1.70	1956.8	30	0.3	0.09	0.02	0.31	13.12	1.4	199	0.6
RI 480023	Rock		27	0.50	0.44	378.3	10	0.1	0.03	0.02	0.16	6.37	1.1	172	0.2
RI 480024	Rock		109	0.77	0.25	1053.2	8	0.1	0.16	<0.01	0.06	1.05	2.6	221	0.2
RI 480025	Rock		30	1.10	1.63	1183.4	46	0.5	0.04	0.02	0.10	16.61	2.4	196	0.6
RI 480026	Rock		41	0.75	0.62	317.1	19	0.3	0.13	0.01	0.11	5.70	2.0	199	0.3
RI 480027	Rock		99	0.90	1.57	577.6	67	0.5	0.04	<0.01	0.16	17.20	2.9	203	0.8
RI 480028	Rock		21	0.44	1.09	1024.5	31	0.3	0.04	0.01	0.08	11.30	2.4	203	0.4
RI 480029	Rock		19	0.49	1.22	553.2	46	0.4	0.05	0.01	0.14	16.17	3.0	185	0.6
RI 480030	Rock		1500	0.60	3.80	>10000	48	0.8	0.17	0.06	0.04	19.46	5.9	137	0.7
RI 480031	Rock		40	0.58	4.01	1003.8	158	1.2	0.06	0.06	0.06	34.24	8.2	190	2.0
RI 480032	Rock		24	0.45	1.78	1610.8	87	0.5	0.03	0.04	0.17	15.02	2.5	222	0.9
RI 481001	Rock		3089	0.56	0.12	>10000	10	0.1	0.11	<0.01	0.06	2.90	2.0	259	0.1
RI 481002	Rock		417	7.67	1.45	>10000	68	0.5	0.32	<0.01	0.38	10.57	7.1	193	0.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02304-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
RI 480001	Rock	4.5	0.48	1.8	2.6	0.27	<0.01	0.18	2.5	5.2	0.02	46	0.83	<0.01	0.3
RI 480002	Rock	5.6	1.09	0.9	2.8	<0.1	<0.01	0.10	1.2	6.8	<0.01	67	0.69	<0.01	0.2
RI 480003	Rock	5.6	0.92	5.3	1.7	1.31	0.02	0.84	10.4	3.4	0.07	40	0.83	0.13	0.9
RI 480004	Rock	7.3	0.75	6.8	2.2	0.96	<0.01	0.58	9.0	10.3	0.05	41	0.87	0.02	0.7
RI 480005	Rock	5.8	0.94	3.2	1.3	1.31	<0.01	0.07	13.9	97.2	0.02	112	0.91	1.04	1.1
RI 480006	Rock	5.5	1.02	5.2	1.0	1.13	0.01	0.67	10.3	20.5	0.04	65	0.90	0.05	1.2
RI 480007	Rock	4.8	0.40	0.6	3.1	<0.1	0.01	0.04	<0.5	6.0	<0.01	42	1.01	<0.01	0.3
RI 480008	Rock	7.5	0.95	9.1	1.3	1.42	0.02	1.00	14.0	16.5	0.09	65	0.81	0.03	1.3
RI 480009	Rock	3.6	0.34	0.8	3.1	<0.1	<0.01	0.06	0.6	3.8	<0.01	50	0.93	<0.01	0.2
RI 480010	Rock	6.7	0.94	9.0	1.8	1.48	0.02	1.02	13.8	13.8	0.09	46	0.79	0.03	1.1
RI 480011	Rock	3.2	0.35	0.7	2.8	<0.1	<0.01	0.04	<0.5	2.9	<0.01	35	0.95	<0.01	0.2
RI 480012	Rock	5.6	1.58	7.5	1.9	1.27	0.02	0.64	13.0	5.9	0.07	79	1.01	0.02	0.8
RI 480013	Rock	4.6	0.44	1.8	3.0	<0.1	0.01	0.15	1.7	3.8	0.01	38	1.02	<0.01	0.2
RI 480014	Rock	3.9	0.36	3.8	2.8	0.36	0.01	0.27	4.1	5.9	0.03	54	0.88	<0.01	0.4
RI 480015	Rock	3.9	0.32	1.6	3.1	<0.1	<0.01	0.12	1.0	3.3	0.01	41	1.09	<0.01	0.3
RI 480016	Rock	4.3	0.38	0.7	1.5	<0.1	<0.01	0.05	0.6	2.0	<0.01	34	1.17	<0.01	0.2
RI 480017	Rock	4.7	0.67	6.2	1.4	1.47	0.02	0.83	13.7	9.9	0.06	33	0.76	0.03	1.1
RI 480018	Rock	6.8	0.83	6.1	1.2	1.80	0.23	0.74	15.1	6.9	0.07	32	0.87	0.04	1.3
RI 480019	Rock	4.3	0.45	1.6	1.4	0.37	<0.01	0.13	3.9	1.3	0.02	33	0.89	0.42	0.4
RI 480020	Rock	4.2	0.68	1.0	1.6	0.28	0.04	0.10	3.1	1.1	0.01	28	0.92	0.42	0.3
RI 480021	Rock	4.8	0.73	1.7	1.5	0.37	0.01	0.18	4.6	1.5	0.02	32	0.87	0.43	0.4
RI 480022	Rock	4.4	0.62	2.7	1.4	0.63	<0.01	0.19	6.1	6.2	0.03	44	0.81	0.92	0.6
RI 480023	Rock	5.2	0.42	0.8	1.3	0.11	<0.01	0.06	3.0	8.0	0.01	37	0.89	0.16	0.3
RI 480024	Rock	4.2	0.71	0.7	1.6	<0.1	<0.01	0.05	<0.5	5.3	<0.01	35	0.91	0.09	0.2
RI 480025	Rock	8.0	0.72	3.5	1.5	0.83	0.01	0.30	8.1	11.1	0.03	178	0.82	0.71	0.7
RI 480026	Rock	21.6	0.58	1.4	1.6	0.26	<0.01	0.12	2.7	13.6	0.01	42	0.78	0.22	0.3
RI 480027	Rock	43.0	0.60	4.3	1.4	0.88	0.03	0.48	8.3	9.5	0.04	86	0.78	0.31	1.1
RI 480028	Rock	6.5	0.63	2.2	1.4	0.47	<0.01	0.22	5.2	2.1	0.02	165	0.83	0.45	0.5
RI 480029	Rock	7.5	0.73	3.3	1.6	0.70	0.01	0.33	7.6	4.3	0.03	216	0.73	0.34	0.6
RI 480030	Rock	6.8	2.34	6.1	1.7	1.20	0.03	0.31	8.5	5.4	0.04	279	0.82	2.92	1.0
RI 480031	Rock	12.8	2.20	10.0	1.4	1.65	0.02	1.08	15.3	26.7	0.24	280	0.80	1.05	1.6
RI 480032	Rock	5.4	0.83	4.7	1.7	0.64	0.01	0.57	6.9	2.4	0.05	200	0.95	0.43	0.7
RI 481001	Rock	5.9	1.92	0.3	1.4	<0.1	0.02	0.02	1.6	1.1	<0.01	27	1.39	<0.01	0.3
RI 481002	Rock	63.3	3.09	4.0	1.5	0.87	1.23	0.30	5.3	16.9	0.03	19	1.50	<0.01	1.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02304-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
RI 480001	Rock	4.1	<10	2.8	12.3	<0.005	<0.01	2.81	0.7	<0.5	0.6	14.4	<0.05	0.09	1
RI 480002	Rock	4.1	28	4.5	5.9	<0.005	0.02	2.49	0.6	<0.5	0.6	19.7	<0.05	<0.05	0
RI 480003	Rock	5.7	43	103.3	41.9	<0.005	0.07	2.85	2.3	<0.5	5.7	30.7	0.16	0.14	6
RI 480004	Rock	5.0	81	16.1	33.1	<0.005	0.02	3.72	1.7	<0.5	1.2	12.4	0.11	<0.05	6
RI 480005	Rock	8.2	88	11.1	4.5	0.009	0.01	1.37	1.5	1.8	0.6	40.3	0.14	0.05	8
RI 480006	Rock	7.3	75	19.5	33.2	0.007	0.01	1.05	2.4	<0.5	0.9	13.1	0.15	0.18	5
RI 480007	Rock	17.3	<10	89.8	2.4	<0.005	<0.01	3.16	0.4	1.9	0.6	4.9	<0.05	0.14	1
RI 480008	Rock	8.2	60	7.3	56.4	<0.005	0.01	2.90	2.7	<0.5	1.1	9.7	0.16	<0.05	8
RI 480009	Rock	4.5	<10	85.2	3.3	<0.005	<0.01	2.99	0.4	<0.5	0.5	3.5	<0.05	<0.05	0
RI 480010	Rock	8.8	53	9.2	57.8	0.006	<0.01	2.49	2.8	<0.5	1.0	11.9	0.16	0.08	9
RI 480011	Rock	5.1	<10	109.9	2.6	<0.005	<0.01	3.01	0.4	2.5	0.5	3.2	<0.05	0.08	0
RI 480012	Rock	11.0	80	11.5	36.9	<0.005	0.02	4.97	2.0	<0.5	1.0	17.4	0.09	0.15	7
RI 480013	Rock	4.9	<10	346.5	8.2	<0.005	0.05	6.32	0.6	1.7	0.9	7.2	<0.05	0.18	1
RI 480014	Rock	4.2	14	83.5	16.3	<0.005	<0.01	4.84	1.0	1.9	1.0	10.1	<0.05	0.20	2
RI 480015	Rock	5.2	<10	81.0	7.2	<0.005	<0.01	3.42	0.5	<0.5	0.9	4.9	<0.05	0.18	0
RI 480016	Rock	7.9	<10	2.5	2.7	<0.005	<0.01	1.25	0.4	<0.5	0.4	2.1	<0.05	0.09	0
RI 480017	Rock	4.5	85	60.4	47.2	<0.005	0.02	2.90	2.4	<0.5	3.9	18.6	0.13	0.12	6
RI 480018	Rock	5.1	40	530.9	42.6	0.005	0.01	2.13	2.1	<0.5	3.4	14.3	0.16	0.10	8
RI 480019	Rock	4.9	13	32.3	7.3	<0.005	0.02	1.63	0.8	<0.5	0.7	17.5	0.06	0.15	2
RI 480020	Rock	5.6	11	530.3	5.1	<0.005	0.13	3.34	0.7	2.2	0.9	23.4	0.06	0.10	1
RI 480021	Rock	5.2	20	85.2	9.4	<0.005	0.14	3.18	0.8	1.6	1.2	21.9	0.06	0.14	2
RI 480022	Rock	5.6	28	17.9	10.1	<0.005	0.03	1.71	1.2	1.6	0.5	54.6	0.08	0.26	3
RI 480023	Rock	4.8	51	7.7	3.3	<0.005	<0.01	0.76	0.7	<0.5	0.4	9.9	<0.05	0.05	1
RI 480024	Rock	6.0	<10	10.7	2.7	<0.005	0.05	1.96	0.4	1.6	0.4	10.3	<0.05	0.15	0
RI 480025	Rock	6.8	71	7.1	16.5	<0.005	0.03	1.69	1.5	<0.5	0.7	29.7	0.07	0.10	4
RI 480026	Rock	4.9	19	22.9	6.4	<0.005	0.02	1.34	1.1	2.1	0.5	15.8	<0.05	<0.05	1
RI 480027	Rock	5.7	29	52.9	25.1	0.007	0.02	1.15	1.6	<0.5	0.9	14.5	0.11	<0.05	5
RI 480028	Rock	6.2	30	10.5	11.6	<0.005	0.03	1.22	1.3	1.4	0.8	17.4	<0.05	0.09	3
RI 480029	Rock	7.3	38	11.5	17.0	<0.005	0.01	1.27	1.6	1.3	0.8	15.3	0.08	0.17	4
RI 480030	Rock	15.0	87	4.6	12.5	0.008	0.35	9.08	2.7	1.6	0.7	102.4	0.11	0.33	4
RI 480031	Rock	20.3	162	3.7	57.2	<0.005	0.04	1.47	4.5	<0.5	1.2	39.6	0.22	<0.05	8
RI 480032	Rock	8.3	174	24.4	29.0	<0.005	0.05	1.70	2.0	<0.5	1.9	19.0	0.09	0.07	4
RI 481001	Rock	6.3	18	10.4	1.0	0.010	0.83	7.57	0.4	3.6	0.4	24.5	<0.05	0.71	1
RI 481002	Rock	10.8	96	6045.9	16.8	0.012	1.23	30.55	1.7	11.1	1.1	57.7	<0.05	1.50	9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02304-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480001	Rock	0.007	0.05	0	<1	3.18	0.8	4	7.7
RI 480002	Rock	<0.005	0.03	0	1	3.10	0.7	4	2.7
RI 480003	Rock	0.024	0.18	1	7	3.68	3.1	30	39.3
RI 480004	Rock	0.023	0.15	1	11	4.29	2.3	17	34.3
RI 480005	Rock	0.025	<0.02	1	<1	4.26	2.7	25	42.4
RI 480006	Rock	0.030	0.13	1	13	2.98	2.7	68	40.3
RI 480007	Rock	<0.005	<0.02	0	<1	2.51	0.2	5	1.8
RI 480008	Rock	0.038	0.23	1	15	4.54	3.0	42	51.9
RI 480009	Rock	<0.005	<0.02	<0.1	<1	1.59	0.1	3	1.2
RI 480010	Rock	0.036	0.24	1	15	4.49	4.4	30	57.6
RI 480011	Rock	<0.005	<0.02	<0.1	<1	1.77	0.1	4	1.3
RI 480012	Rock	0.025	0.14	2	11	3.84	3.8	101	48.8
RI 480013	Rock	<0.005	0.03	0	1	6.36	0.3	5	2.9
RI 480014	Rock	0.012	0.05	0	6	3.15	0.8	6	15.1
RI 480015	Rock	<0.005	<0.02	0	2	1.80	0.2	3	2.3
RI 480016	Rock	<0.005	<0.02	<0.1	<1	2.39	0.3	6	2.1
RI 480017	Rock	0.034	0.21	1	9	5.06	3.6	20	53.6
RI 480018	Rock	0.032	0.18	2	9	4.96	3.7	19	57.2
RI 480019	Rock	0.008	<0.02	0	<1	2.85	0.9	14	12.2
RI 480020	Rock	0.006	<0.02	1	<1	3.67	0.7	75	10.3
RI 480021	Rock	0.010	0.02	0	<1	2.32	1.2	21	14.6
RI 480022	Rock	0.015	0.03	1	5	2.02	1.9	26	21.5
RI 480023	Rock	<0.005	<0.02	0	<1	2.52	1.1	15	5.3
RI 480024	Rock	<0.005	<0.02	0	3	2.62	0.2	6	1.4
RI 480025	Rock	0.019	0.05	1	6	2.64	2.0	16	29.1
RI 480026	Rock	0.008	<0.02	0	<1	3.05	0.7	15	9.0
RI 480027	Rock	0.029	0.08	1	10	6.60	2.0	30	32.4
RI 480028	Rock	0.013	0.02	1	3	2.87	1.2	13	17.3
RI 480029	Rock	0.017	0.04	1	6	2.90	1.8	28	23.1
RI 480030	Rock	0.026	0.05	1	10	3.39	3.2	14	42.3
RI 480031	Rock	0.053	0.20	1	30	4.90	4.7	46	59.7
RI 480032	Rock	0.021	0.10	1	9	2.31	2.0	34	24.4
RI 481001	Rock	<0.005	<0.02	0	<1	3.53	0.4	3	4.0
RI 481002	Rock	0.015	0.09	1	5	6.24	1.7	21	22.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02304-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA ppb 5	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480012	Rock		1350												
RI 480012 Dup			31												
STD-Oxi67 expected			1817												
STD-Oxi67 result			1779												
QCV1007-00896-0004-BLK			<5												
QCV1007-00897-0001-BLK				<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
RI 480001	Rock			0.79	0.56	801.2	42	0.2	0.07	0.02	<0.01	5.35	1.1	222	1.1
RI 480001 Dup				0.87	0.56	810.4	41	0.2	0.07	0.02	<0.01	5.20	1.1	217	1.1
STD-ME-8 expected				61.70											
STD-ME-8 result				57.62	4.50	2663.5	668	1.0	4.58	6.66	177.97	26.50	16.8	42	3.2
RI 480019	Rock			0.84	0.84	864.0	25	0.2	0.07	0.01	0.17	8.27	1.1	228	0.3
RI 480019 Dup				0.91	0.85	877.4	24	0.2	0.07	0.01	0.17	8.24	1.1	230	0.3
STD-ME-8 expected				61.70											
STD-ME-8 result				58.71	4.67	2836.4	675	0.9	4.76	6.80	177.70	25.71	16.6	42	3.2
QCV1007-00897-0006-BLK				0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
STD-SY-4 expected							340	2.6				122.00	2.8	12	1.5
STD-SY-4 result				0.44	9.54	70.0	363	3.3	0.05	5.60	0.09	114.45	3.8	7	1.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02304-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
QCV1007-00897-0001-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
RI 480001	Rock	4.5	0.48	1.8	2.6	0.27	<0.01	0.18	2.5	5.2	0.02	46	0.83	<0.01	0.3
RI 480001 Dup		4.5	0.48	1.8	2.5	0.27	<0.01	0.19	2.4	5.2	0.02	46	0.79	<0.01	0.3
STD-ME-8 expected		1030.0													
STD-ME-8 result		1054.5	3.80	10.4	0.6	1.27	0.09	1.39	12.9	16.6	0.71	2939	5.60	1.17	4.1
RI 480019	Rock	4.3	0.45	1.6	1.4	0.37	<0.01	0.13	3.9	1.3	0.02	33	0.89	0.42	0.4
RI 480019 Dup		4.1	0.45	1.6	1.4	0.38	<0.01	0.13	3.8	1.3	0.02	32	0.89	0.42	0.4
STD-ME-8 expected		1030.0													
STD-ME-8 result		1036.7	3.92	9.5	0.7	1.14	0.10	1.45	12.8	15.2	0.73	3110	5.62	1.24	4.0
QCV1007-00897-0006-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
STD-SY-4 expected		7.0		35.0		10.60			58.0	37.0					13.0
STD-SY-4 result		8.5	4.39	33.2	0.4	1.20	0.05	1.42	52.5	39.0	0.30	692	0.26	4.96	14.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02304-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
QCV1007-00897-0001-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
RI 480001	Rock	4.1	<10	2.8	12.3	<0.005	<0.01	2.81	0.7	<0.5	0.6	14.4	<0.05	0.09	1
RI 480001 Dup		4.1	<10	2.6	12.0	<0.005	<0.01	2.77	0.7	<0.5	0.6	14.5	<0.05	0.09	1
STD-ME-8 expected				19400											
STD-ME-8 result		32.5	588	>10000	70.0	0.007	1.70	65.59	7.1	4.3	3.3	371.6	0.41	0.56	4
RI 480019	Rock	4.9	13	32.3	7.3	<0.005	0.02	1.63	0.8	<0.5	0.7	17.5	0.06	0.15	2
RI 480019 Dup		4.7	13	32.1	7.0	<0.005	0.02	1.65	0.8	<0.5	0.8	18.0	0.06	0.15	2
STD-ME-8 expected				19400											
STD-ME-8 result		29.5	595	>10000	72.4	<0.005	2.06	65.90	7.0	4.0	3.5	376.7	0.43	0.98	4
QCV1007-00897-0006-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
STD-SY-4 expected		9.0		10.0	55.0				1.1			1191.0	0.90		1
STD-SY-4 result		7.6	524	13.6	37.0	0.018	<0.01	<0.05	1.0	<0.5	9.1	1203.4	1.16	0.34	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02304-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1007-00897-0001-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
RI 480001	Rock	0.007	0.05	0	<1	3.18	0.8	4	7.7
RI 480001 Dup		0.007	0.04	0	<1	3.15	0.8	4	8.0
STD-ME-8 expected								19200	
STD-ME-8 result		0.195	0.80	2	59	11.17	12.2	>10000	32.6
RI 480019	Rock	0.008	<0.02	0	<1	2.85	0.9	14	12.2
RI 480019 Dup		0.008	<0.02	0	<1	2.84	0.9	14	12.2
STD-ME-8 expected								19200	
STD-ME-8 result		0.204	0.81	2	60	11.85	11.0	>10000	32.2
QCV1007-00897-0006-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected				1	8		119.0	93	517.0
STD-SY-4 result		0.172	0.22	0	<1	4.03	110.9	92	60.8

Certificate of Analysis

10-360-02305-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description:

Date Received: 07/27/2010
Date Completed: 08/10/2010
Invoice:

Samples	Type	Preparation Description
95	Soil	SP-SS-1K/Soils, Humus Sediments 1kg dried, sieved and riffle split

Method	Description
50-AR-UT	50 Element, Aqua Regia, ICPMS, Ultra Trace Level
Au-1AT-AA	Au, 1AT Fire Assay, AAS
Au-1AT-GV	Au, 1AT, Gravimetric

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SM 268901	Soil	22		0.18	0.84	154.2	39	0.3	0.32	0.01	0.23	18.66	7.2	13	2.3
SM 268902	Soil	5		<0.01	0.42	28.2	53	0.1	0.14	0.01	0.08	10.72	2.8	5	1.0
SM 268903	Soil	65		0.11	1.13	245.8	38	0.3	0.34	0.01	0.23	20.78	10.4	17	1.2
SM 268904	Soil	242		0.07	0.46	710.3	25	0.2	0.28	0.01	0.36	21.66	10.7	9	1.1
SM 268905	Soil	26		<0.01	0.54	131.6	41	0.1	0.36	0.02	0.13	20.38	6.9	8	1.3
SM 268906	Soil	176		0.08	0.57	212.7	30	0.2	0.27	0.02	0.16	19.46	5.3	8	1.2
SM 268907	Soil	78		0.04	0.46	432.4	30	0.1	0.22	0.02	0.24	18.07	15.3	6	0.5
SM 268908	Soil	18		<0.01	0.54	133.4	19	0.2	0.25	<0.01	0.08	17.07	7.8	10	1.0
SM 268909	Soil	149		0.04	1.07	244.2	28	0.3	0.38	<0.01	0.24	20.29	12.2	17	0.8
SM 268910	Soil	21		<0.01	0.67	40.7	20	0.2	0.39	<0.01	0.04	22.98	8.7	12	1.1
SM 268911	Soil	5		<0.01	0.93	57.2	12	0.3	0.52	<0.01	0.12	19.45	17.9	21	1.3
SM 268912	Soil	135		0.06	0.43	907.1	32	0.3	0.36	0.02	0.20	16.97	12.9	7	0.7
SM 268913	Soil	459		0.41	0.42	994.9	16	0.3	0.24	0.02	2.11	15.75	13.8	8	1.0
SM 268914	Soil	345		0.05	0.47	702.4	30	0.1	0.18	0.01	0.16	10.58	4.2	4	1.0
SM 268915	Soil	2709	2.987	0.55	0.45	2938.7	61	0.9	0.72	0.01	0.55	24.93	22.6	6	3.4
SM 268916	Soil	971	0.999	0.13	0.58	993.2	31	0.4	0.50	0.01	0.11	36.50	14.6	8	1.9
SM 268917	Soil	1892	1.407	0.17	0.28	2368.1	102	0.3	0.47	<0.01	0.18	33.36	11.4	3	1.6
SM 268918	Soil	1053	0.841	0.08	0.26	1320.4	107	0.1	0.21	0.01	0.14	18.87	6.7	6	0.8
SM 268919	Soil	156		0.08	0.39	1010.6	14	0.2	0.23	<0.01	0.19	17.97	12.4	6	0.6
SM 268920	Soil	198		<0.01	0.46	854.1	18	0.1	0.21	<0.01	0.12	22.27	6.4	8	0.8
SM 268921	Soil	350		0.05	0.40	1265.2	49	0.2	0.34	<0.01	0.19	26.06	8.3	6	1.0
SM 268922	Soil	2025		0.15	0.36	739.6	25	0.1	0.24	<0.01	0.13	21.74	4.8	5	0.9
SM 268923	Soil	1151		0.12	0.59	1006.9	34	0.4	0.55	0.02	0.20	34.39	14.5	10	1.8
SM 268924	Soil	1033		0.28	0.28	1092.7	32	0.5	0.53	<0.01	0.12	33.08	13.6	4	2.9
SM 268925	Soil	1811		<0.01	0.58	457.4	62	0.2	0.13	0.04	0.22	11.22	6.1	4	0.8
SM 269251	Soil	37		<0.01	1.48	163.2	25	0.3	0.49	0.02	0.17	30.31	13.1	23	1.4
SM 269252	Soil	36		<0.01	1.24	174.7	19	0.2	0.47	0.01	0.13	17.99	11.8	20	0.7
SM 269253	Soil	13		<0.01	1.03	56.0	20	0.2	0.48	0.02	0.13	13.81	14.0	20	0.8
SM 269254	Soil	8		<0.01	0.49	46.8	11	0.1	0.25	0.01	0.04	17.74	8.7	11	0.6
SM 269255	Soil	26		<0.01	1.77	87.0	62	0.9	0.43	0.23	0.18	33.36	27.4	37	1.8
SM 269256	Soil	14		<0.01	1.98	22.7	21	0.3	0.69	0.11	0.14	19.85	16.2	33	2.8
SM 269257	Soil	13		<0.01	1.28	31.3	17	0.5	0.67	0.23	0.06	19.87	20.8	26	4.1
SM 269258	Soil	110		<0.01	2.37	399.0	26	0.4	0.42	0.02	0.18	25.90	14.3	35	1.3
SM 269259	Soil	2450		0.41	1.57	1002.3	35	0.4	0.63	0.05	0.83	19.31	15.0	25	2.1
SM 269260	Soil	26		0.86	2.21	52.9	33	0.4	0.49	0.03	0.15	35.73	17.8	36	2.2
SM 269261	Soil	16		0.31	1.53	51.6	72	0.4	0.32	0.02	0.24	18.56	18.9	20	1.9
SM 269262	Soil	36		0.21	1.40	54.4	37	0.2	0.41	<0.01	0.14	24.81	11.2	23	1.4
SM 269263	Soil	42		0.09	1.77	62.3	29	0.3	0.42	<0.01	0.07	25.35	11.7	28	1.0
SM 269264	Soil	28		0.18	1.66	66.6	36	0.3	0.39	0.01	0.12	21.17	11.0	27	1.9
SM 269265	Soil	29		0.11	1.71	72.1	43	0.4	0.42	0.05	0.14	16.82	14.2	26	2.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SM 269266	Soil	45		0.08	1.91	64.7	17	0.3	0.50	<0.01	0.08	19.52	12.2	31	1.2
SM 269267	Soil	31		0.03	2.14	81.5	38	0.4	0.48	<0.01	0.12	20.97	13.7	31	1.4
SM 269268	Soil	29		0.05	2.06	107.2	31	0.4	0.43	0.01	0.12	19.56	13.8	31	1.0
SM 269269	Soil	25		0.10	1.74	86.9	44	0.5	0.44	0.02	0.13	21.93	16.7	24	1.5
SM 269270	Soil	10		0.03	1.72	74.4	30	0.4	0.48	0.03	0.10	23.36	13.7	25	1.8
SM 269271	Soil	22		0.04	2.19	87.8	18	0.4	0.65	0.02	0.11	28.51	19.8	31	1.6
SM 269272	Soil	61		0.16	1.06	332.4	24	0.2	0.47	<0.01	0.44	21.00	10.4	17	0.8
SM 269273	Soil	181		0.17	0.91	224.2	25	0.2	0.57	<0.01	0.18	23.94	7.7	15	1.1
SM 269274	Soil	212		0.09	1.11	371.5	17	0.3	0.55	<0.01	0.37	18.70	12.0	17	0.7
SM 269275	Soil	24		0.06	1.12	161.1	24	0.2	0.42	<0.01	0.19	22.02	7.9	16	1.1
SM 269276	Soil	98		0.04	1.20	215.6	27	0.3	0.38	<0.01	0.21	22.50	12.3	18	0.7
SM 269277	Soil	29		0.27	1.10	131.0	30	0.2	0.42	<0.01	0.20	19.08	10.5	19	1.0
SM 269278	Soil	162		0.36	0.61	231.4	22	0.2	0.48	<0.01	0.13	16.09	9.1	11	0.6
SM 269279	Soil	48		0.11	0.54	270.6	23	0.2	0.49	<0.01	0.11	17.68	9.2	10	0.7
SM 269280	Soil	525		0.19	1.32	342.0	26	0.2	0.66	<0.01	0.27	19.72	11.0	18	0.8
SM 269281	Soil	29		0.44	0.70	263.5	34	0.2	0.47	0.01	0.86	11.62	8.0	11	1.0
SM 269282	Soil	60		0.35	1.28	116.0	35	0.4	0.75	0.02	0.14	18.10	12.6	21	1.6
SM 269283	Soil	27		<0.01	0.57	545.9	22	0.2	0.20	<0.01	0.21	17.94	17.6	10	0.7
SM 269284	Soil	117		<0.01	0.51	394.0	27	0.2	0.42	<0.01	0.11	33.78	10.3	8	1.8
SM 269285	Soil	17		0.02	0.34	25.5	15	0.1	0.12	<0.01	0.13	12.62	3.2	4	1.3
SM 269286	Soil	10		0.33	0.54	3.9	8	0.1	0.03	0.03	0.03	1.98	0.6	1	0.1
SM 269287	Soil	28		<0.01	0.37	59.2	24	0.1	0.18	0.01	0.09	5.16	6.5	6	0.7
SM 269288	Soil	40		<0.01	0.93	203.4	31	0.2	0.37	<0.01	0.07	23.71	10.0	14	0.7
SM 269289	Soil	22		0.18	1.10	68.0	33	0.3	0.54	0.01	0.12	22.27	11.4	24	1.9
SM 269290	Soil	27		<0.01	0.38	61.9	31	0.4	0.69	<0.01	0.03	20.94	11.6	10	1.7
SM 269291	Soil	15		0.04	1.40	64.0	48	0.3	0.41	0.01	0.08	26.51	10.5	21	0.6
SM 269292	Soil	19		0.12	0.54	105.2	32	0.1	0.37	<0.01	0.22	25.40	5.2	9	0.6
SM 269293	Soil	17		0.06	0.66	38.6	34	0.2	0.19	<0.01	0.12	14.10	5.9	5	0.8
SM 269294	Soil	25		0.16	0.86	68.9	36	0.2	0.41	0.01	0.11	16.68	9.4	14	1.6
SM 269295	Soil	32		0.04	0.71	188.5	34	0.2	0.39	0.03	0.33	16.90	8.5	11	1.0
SM 269296	Soil	77		0.65	1.16	164.3	29	0.4	0.51	<0.01	0.16	11.25	11.8	17	1.7
SM 269297	Soil	508		0.17	0.98	63.3	30	0.3	0.31	0.02	0.31	9.33	10.6	12	1.2
SM 269298	Soil	31		0.30	1.01	63.5	32	0.3	0.27	0.02	0.20	9.61	6.2	12	1.2
SM 269299	Soil	55		0.32	0.93	294.5	29	0.3	0.35	0.02	1.13	15.53	14.7	16	0.9
SM 269300	Soil	75		0.28	0.82	776.9	26	0.3	0.38	0.03	1.29	11.69	13.5	14	1.2
SM 269301	Soil	2730	2.477	0.27	0.53	1807.4	104	0.2	0.24	0.02	0.82	15.05	6.7	3	0.8
SM 269302	Soil	8698	8.815	0.96	0.33	1338.7	35	0.3	0.42	0.01	0.50	16.93	19.9	4	2.6
SM 269303	Soil	3630	3.016	0.46	0.40	993.2	59	0.2	0.34	0.03	0.44	16.33	11.0	8	1.0
SM 269304	Soil	227		0.24	1.02	441.5	51	0.5	0.47	0.05	0.32	11.76	8.5	19	2.0
SM 269305	Soil	5489	4.509	0.58	0.46	1761.7	56	0.3	0.42	<0.01	0.13	23.82	9.8	8	1.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SM 269306	Soil	50		0.28	1.70	154.2	26	0.4	0.48	0.02	0.18	20.22	14.3	31	3.2
SM 269307	Soil	68		<0.01	0.37	463.0	36	0.1	0.27	0.07	0.35	21.85	7.2	6	0.5
SM 269308	Soil	200		0.14	0.78	133.5	35	0.2	0.34	0.03	0.17	21.26	7.9	11	0.7
SM 269309	Soil	130		0.16	1.14	226.9	29	0.2	0.37	0.02	0.20	23.16	10.3	15	0.9
SM 269310	Soil	>10000	19.316	1.09	0.46	1599.6	63	0.3	0.46	<0.01	0.63	22.12	15.2	7	1.8
SM 269311	Soil	2211	1.656	0.05	0.40	485.9	38	0.2	0.31	<0.01	0.08	17.30	9.7	6	1.7
SM 269312	Soil	562		0.08	0.56	910.9	30	0.3	0.42	<0.01	0.11	28.31	10.7	9	1.5
SM 269313	Soil	313		0.19	0.35	252.1	21	0.1	0.21	<0.01	0.06	12.19	6.6	4	0.6
SM 269314	Soil	227		0.47	0.35	271.9	24	0.1	0.21	0.01	0.05	15.19	5.1	5	0.6
SM 269315	Soil	169		0.16	0.87	704.0	22	0.3	0.30	0.01	0.14	22.33	13.7	14	1.3
SM 269316	Soil	377		0.21	0.61	381.7	42	0.2	0.31	0.01	0.13	25.58	7.1	12	1.0
SM 269317	Soil	104		0.19	0.81	309.5	30	0.2	0.22	<0.01	0.09	16.35	7.1	8	0.7
SM 269318	Soil	636		0.21	0.42	288.8	22	0.2	0.14	0.01	0.07	11.47	4.0	3	0.8
SM 269319	Soil	735		0.25	0.64	820.6	29	0.4	0.44	0.02	0.31	23.43	18.7	9	2.4
SM 269320	Soil	9528	8.029	0.73	0.31	1783.6	52	0.3	0.51	0.01	0.55	24.63	15.5	5	1.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SM 268901	Soil	28.0	2.64	3.8	<0.05	<0.02	0.02	0.03	10.2	6.4	0.12	286	0.63	<0.01	0.3
SM 268902	Soil	9.2	0.98	2.6	<0.05	<0.02	<0.01	0.02	5.4	0.5	0.01	954	0.40	0.01	0.1
SM 268903	Soil	23.1	3.27	3.6	<0.05	<0.02	0.03	0.03	11.2	17.3	0.26	435	0.65	<0.01	0.4
SM 268904	Soil	17.2	4.23	3.1	<0.05	<0.02	0.04	0.02	11.3	1.7	0.04	326	0.71	<0.01	0.2
SM 268905	Soil	17.4	1.83	3.7	<0.05	<0.02	0.01	0.03	11.2	1.1	0.03	366	0.69	<0.01	0.1
SM 268906	Soil	17.1	2.02	3.1	<0.05	<0.02	0.03	0.03	10.3	2.0	0.05	259	0.60	0.01	0.3
SM 268907	Soil	14.5	2.11	2.9	<0.05	<0.02	0.01	0.02	9.7	1.2	0.03	348	0.42	0.01	0.1
SM 268908	Soil	16.8	2.58	2.7	<0.05	<0.02	0.01	0.02	9.4	2.9	0.06	544	0.49	0.01	0.2
SM 268909	Soil	28.9	3.67	3.0	<0.05	<0.02	0.04	0.02	11.3	19.7	0.30	402	0.41	<0.01	0.2
SM 268910	Soil	29.3	2.61	2.2	<0.05	<0.02	0.01	0.02	14.0	9.8	0.12	206	0.48	<0.01	0.1
SM 268911	Soil	49.5	4.46	2.5	<0.05	<0.02	0.02	0.01	11.6	15.1	0.20	322	0.45	<0.01	0.1
SM 268912	Soil	28.9	2.85	1.5	<0.05	<0.02	0.02	0.02	9.7	2.2	0.04	253	0.49	<0.01	<0.05
SM 268913	Soil	28.9	3.49	1.3	<0.05	<0.02	0.04	0.02	8.2	3.9	0.07	436	0.53	<0.01	0.1
SM 268914	Soil	12.4	1.63	2.1	<0.05	<0.02	0.01	0.02	5.6	0.9	0.02	347	0.38	0.01	0.1
SM 268915	Soil	74.7	5.25	1.6	<0.05	<0.02	0.04	0.07	14.0	1.1	0.02	1447	0.94	<0.01	0.1
SM 268916	Soil	34.3	3.81	1.7	<0.05	<0.02	0.03	0.05	21.3	8.4	0.12	315	0.54	<0.01	0.1
SM 268917	Soil	30.0	3.31	1.2	<0.05	<0.02	0.03	0.06	19.0	0.5	<0.01	202	0.54	<0.01	0.1
SM 268918	Soil	17.2	2.45	1.0	<0.05	<0.02	0.02	0.02	9.2	0.2	0.01	789	0.35	<0.01	<0.05
SM 268919	Soil	21.8	3.24	1.8	<0.05	<0.02	0.02	0.02	9.2	0.7	0.02	577	0.44	<0.01	0.1
SM 268920	Soil	16.2	2.26	1.7	<0.05	<0.02	0.02	0.02	11.3	5.6	0.09	336	0.31	<0.01	0.1
SM 268921	Soil	25.4	2.88	2.0	<0.05	<0.02	0.02	0.03	13.8	1.3	0.03	343	0.54	<0.01	0.1
SM 268922	Soil	18.6	2.10	2.0	<0.05	<0.02	0.01	0.03	11.6	0.9	0.02	167	0.44	0.01	0.2
SM 268923	Soil	33.9	3.84	2.3	<0.05	<0.02	0.03	0.05	19.7	8.8	0.13	333	0.64	<0.01	0.4
SM 268924	Soil	39.4	3.03	1.0	<0.05	<0.02	0.04	0.06	19.3	0.7	0.01	340	0.45	<0.01	<0.05
SM 268925	Soil	9.3	1.10	2.1	<0.05	<0.02	<0.01	0.03	5.5	1.1	0.04	1915	0.32	0.02	0.1
SM 269251	Soil	33.7	4.23	5.2	<0.05	<0.02	0.03	0.02	16.6	34.9	0.47	390	0.53	<0.01	0.4
SM 269252	Soil	33.4	4.86	5.1	<0.05	<0.02	0.02	0.02	9.7	21.7	0.33	346	0.66	<0.01	0.5
SM 269253	Soil	45.5	3.87	4.2	<0.05	<0.02	0.02	0.02	7.3	18.5	0.29	298	0.70	<0.01	0.3
SM 269254	Soil	14.6	2.23	2.9	<0.05	<0.02	<0.01	0.01	8.9	5.2	0.11	190	0.65	<0.01	0.2
SM 269255	Soil	69.3	5.67	5.3	<0.05	0.04	0.03	0.07	17.9	46.1	0.70	890	0.68	<0.01	0.6
SM 269256	Soil	36.6	4.31	5.6	<0.05	<0.02	0.02	0.02	9.7	55.7	0.83	490	0.60	<0.01	0.1
SM 269257	Soil	52.3	4.17	3.9	<0.05	<0.02	0.04	0.02	9.1	34.6	0.57	298	0.49	<0.01	<0.05
SM 269258	Soil	32.2	5.75	6.4	<0.05	0.03	0.03	0.02	13.9	62.7	0.92	399	0.45	<0.01	0.3
SM 269259	Soil	35.9	5.13	6.3	<0.05	<0.02	0.03	0.04	10.6	35.1	0.50	530	0.56	<0.01	0.3
SM 269260	Soil	33.6	4.98	6.3	<0.05	<0.02	0.03	0.03	19.8	58.9	0.83	633	0.55	<0.01	0.3
SM 269261	Soil	20.6	3.46	5.5	<0.05	<0.02	0.02	0.04	9.7	29.5	0.39	877	0.42	0.01	0.4
SM 269262	Soil	21.8	4.13	5.8	<0.05	<0.02	0.02	0.02	13.6	32.9	0.47	587	0.43	<0.01	0.4
SM 269263	Soil	26.1	4.56	6.2	<0.05	<0.02	0.02	0.02	13.2	43.0	0.61	413	0.41	<0.01	0.3
SM 269264	Soil	28.8	4.17	5.5	<0.05	<0.02	0.02	0.02	11.1	40.4	0.56	456	0.43	<0.01	0.4
SM 269265	Soil	32.0	4.03	5.6	<0.05	<0.02	0.03	0.02	8.6	44.2	0.62	617	0.46	<0.01	0.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SM 269266	Soil	27.0	5.02	6.2	<0.05	<0.02	0.02	0.02	10.3	51.1	0.76	493	0.48	<0.01	0.2
SM 269267	Soil	35.8	5.04	5.8	<0.05	<0.02	0.03	0.02	10.9	52.7	0.80	439	0.49	<0.01	0.2
SM 269268	Soil	32.4	4.68	5.9	<0.05	<0.02	0.02	0.02	10.3	50.9	0.74	573	0.46	<0.01	0.2
SM 269269	Soil	40.5	4.25	5.6	<0.05	<0.02	0.02	0.02	11.1	41.3	0.60	551	0.50	<0.01	0.3
SM 269270	Soil	30.9	4.39	6.4	<0.05	<0.02	0.03	0.02	12.7	42.6	0.64	645	0.55	<0.01	0.4
SM 269271	Soil	52.1	5.17	6.5	<0.05	0.02	0.03	0.02	15.2	65.8	0.91	499	0.54	<0.01	0.2
SM 269272	Soil	27.9	4.51	4.2	<0.05	<0.02	0.03	0.02	11.1	17.4	0.26	305	0.71	<0.01	0.5
SM 269273	Soil	22.5	3.63	4.6	<0.05	<0.02	0.03	0.02	13.2	12.8	0.21	241	0.77	<0.01	0.5
SM 269274	Soil	34.9	4.26	3.2	<0.05	<0.02	0.03	0.01	10.2	24.7	0.35	363	0.52	<0.01	0.1
SM 269275	Soil	22.0	3.53	5.3	<0.05	<0.02	0.02	0.02	11.7	18.3	0.33	278	0.80	<0.01	0.6
SM 269276	Soil	32.8	3.70	3.9	<0.05	<0.02	0.02	0.02	12.5	27.0	0.34	318	0.54	<0.01	0.3
SM 269277	Soil	26.3	3.80	4.8	<0.05	<0.02	0.02	0.02	10.0	20.1	0.34	515	0.77	<0.01	0.5
SM 269278	Soil	25.5	3.66	4.4	<0.05	<0.02	0.03	0.02	8.6	5.8	0.09	442	0.74	<0.01	0.6
SM 269279	Soil	27.9	3.99	3.9	<0.05	<0.02	0.03	0.02	10.0	4.2	0.07	299	0.68	<0.01	0.4
SM 269280	Soil	30.5	5.28	5.1	<0.05	<0.02	0.03	0.02	10.5	18.5	0.35	380	0.61	<0.01	0.5
SM 269281	Soil	27.1	3.01	4.1	<0.05	<0.02	0.02	0.02	6.7	6.5	0.12	243	0.59	0.01	0.2
SM 269282	Soil	41.6	6.25	6.0	<0.05	<0.02	0.02	0.02	10.0	16.8	0.30	314	0.66	<0.01	0.4
SM 269283	Soil	18.3	3.75	1.9	<0.05	<0.02	0.02	0.01	9.1	4.9	0.08	867	0.43	<0.01	0.1
SM 269284	Soil	29.0	3.38	3.1	<0.05	<0.02	0.02	0.02	19.5	2.6	0.06	381	0.63	<0.01	0.3
SM 269285	Soil	10.5	1.52	2.1	<0.05	<0.02	<0.01	0.01	6.2	0.3	<0.01	53	0.33	<0.01	0.2
SM 269286	Soil	2.0	0.31	2.0	<0.05	<0.02	<0.01	0.01	1.0	0.1	0.02	30	0.14	0.02	0.1
SM 269287	Soil	18.0	1.23	2.0	<0.05	<0.02	<0.01	0.02	3.0	4.8	0.08	146	0.33	0.01	<0.05
SM 269288	Soil	28.7	3.86	5.1	<0.05	<0.02	0.02	0.02	13.4	12.9	0.18	309	0.48	<0.01	0.4
SM 269289	Soil	31.1	4.85	6.1	<0.05	<0.02	0.02	0.03	11.8	17.2	0.27	329	0.93	<0.01	1.1
SM 269290	Soil	30.5	3.19	1.4	<0.05	<0.02	0.03	0.02	12.1	3.5	0.05	116	1.61	<0.01	0.1
SM 269291	Soil	24.3	4.02	6.0	<0.05	<0.02	0.02	0.02	14.2	27.9	0.36	355	0.68	<0.01	1.2
SM 269292	Soil	18.5	2.21	6.3	<0.05	<0.02	0.02	0.02	13.3	1.6	0.04	211	0.87	<0.01	0.3
SM 269293	Soil	16.7	1.66	3.6	<0.05	<0.02	0.01	0.02	7.2	1.7	0.03	260	0.49	<0.01	0.2
SM 269294	Soil	27.5	2.88	5.4	<0.05	<0.02	0.02	0.02	9.1	4.7	0.07	344	0.66	<0.01	0.2
SM 269295	Soil	21.6	3.14	4.4	<0.05	<0.02	0.02	0.03	9.0	6.5	0.10	336	0.65	<0.01	0.4
SM 269296	Soil	38.7	4.25	3.8	<0.05	<0.02	0.02	0.03	6.2	19.5	0.30	616	0.85	<0.01	0.3
SM 269297	Soil	20.5	2.37	3.2	<0.05	<0.02	0.01	0.03	4.7	10.7	0.17	498	0.46	0.01	0.3
SM 269298	Soil	27.4	2.46	3.3	<0.05	<0.02	0.01	0.03	5.0	10.3	0.15	496	0.45	0.01	0.3
SM 269299	Soil	26.3	3.38	4.0	<0.05	<0.02	0.03	0.04	8.0	9.9	0.13	632	0.63	<0.01	0.3
SM 269300	Soil	38.1	3.78	2.9	<0.05	<0.02	0.02	0.03	6.8	9.0	0.12	411	0.48	<0.01	0.2
SM 269301	Soil	17.9	2.23	2.3	<0.05	<0.02	0.03	0.03	7.6	0.5	0.03	299	0.48	<0.01	0.1
SM 269302	Soil	54.2	3.18	0.9	<0.05	<0.02	0.03	0.05	9.9	1.0	0.02	535	0.53	<0.01	0.1
SM 269303	Soil	27.2	2.96	2.2	<0.05	<0.02	0.02	0.04	8.5	0.8	0.02	553	0.59	<0.01	0.1
SM 269304	Soil	48.4	3.77	5.0	<0.05	<0.02	0.03	0.04	5.9	12.7	0.18	700	0.55	0.01	0.2
SM 269305	Soil	29.2	2.70	1.3	<0.05	<0.02	0.02	0.04	13.5	4.9	0.07	149	0.45	<0.01	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SM 269306	Soil	43.6	6.27	6.5	<0.05	0.03	0.03	0.02	11.0	22.1	0.34	882	0.69	<0.01	0.3
SM 269307	Soil	21.2	2.76	3.1	<0.05	<0.02	0.01	0.03	11.4	0.9	0.03	201	0.51	<0.01	0.1
SM 269308	Soil	15.9	3.18	4.2	<0.05	<0.02	0.01	0.03	12.0	8.3	0.15	273	0.52	<0.01	0.3
SM 269309	Soil	26.4	4.58	4.4	<0.05	<0.02	0.02	0.03	12.9	16.5	0.25	312	0.57	<0.01	0.4
SM 269310	Soil	38.6	4.38	2.7	<0.05	<0.02	0.03	0.04	11.7	1.7	0.04	860	0.78	<0.01	0.2
SM 269311	Soil	23.0	2.17	1.8	<0.05	<0.02	0.02	0.04	9.4	0.9	0.02	452	0.44	0.01	0.1
SM 269312	Soil	27.4	3.60	2.9	<0.05	<0.02	0.02	0.04	16.3	4.5	0.08	324	0.56	<0.01	0.3
SM 269313	Soil	14.7	1.59	2.1	<0.05	<0.02	0.01	0.02	6.6	0.4	<0.01	156	0.41	<0.01	0.1
SM 269314	Soil	15.9	1.62	2.6	<0.05	<0.02	0.01	0.02	8.0	0.4	0.01	110	0.54	<0.01	0.1
SM 269315	Soil	25.3	3.76	2.3	<0.05	<0.02	0.02	0.04	11.9	11.0	0.18	376	0.65	<0.01	0.2
SM 269316	Soil	21.6	2.57	3.6	<0.05	<0.02	0.02	0.04	12.8	2.0	0.04	218	1.04	0.01	0.2
SM 269317	Soil	18.5	2.21	2.8	<0.05	<0.02	0.02	0.03	8.6	4.9	0.08	238	0.49	0.01	0.3
SM 269318	Soil	10.6	1.09	1.7	<0.05	<0.02	<0.01	0.03	6.1	0.9	0.02	98	0.33	0.02	0.1
SM 269319	Soil	34.9	3.37	1.9	<0.05	<0.02	0.03	0.04	13.2	8.1	0.11	714	0.54	<0.01	0.1
SM 269320	Soil	39.4	4.61	1.3	<0.05	<0.02	0.03	0.05	13.4	0.5	0.01	451	0.57	<0.01	0.1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SM 268901	Soil	16.9	551	38.2	6.4	<0.01	0.03	<0.05	0.2	0.5	0.4	6.0	<0.01	0.07	<0.2
SM 268902	Soil	5.4	292	10.5	1.9	<0.01	0.02	<0.05	0.1	<0.2	0.3	3.0	<0.01	0.02	<0.2
SM 268903	Soil	23.5	369	37.0	5.1	<0.01	0.02	<0.05	0.6	0.4	0.4	4.7	<0.01	0.08	0
SM 268904	Soil	20.5	575	61.7	3.1	<0.01	0.02	<0.05	0.3	0.4	0.4	5.5	<0.01	0.09	0
SM 268905	Soil	11.4	538	21.1	4.2	<0.01	0.02	0.19	0.2	0.2	0.5	6.0	<0.01	0.08	<0.2
SM 268906	Soil	10.1	383	58.8	5.7	<0.01	0.02	0.11	0.3	<0.2	0.4	5.0	<0.01	0.05	<0.2
SM 268907	Soil	10.4	416	17.8	3.8	<0.01	0.02	<0.05	0.3	<0.2	0.2	4.4	<0.01	0.07	<0.2
SM 268908	Soil	14.4	397	16.7	4.2	<0.01	0.02	<0.05	0.3	0.3	0.2	3.0	<0.01	0.08	<0.2
SM 268909	Soil	26.8	305	58.9	3.3	<0.01	<0.01	<0.05	0.7	0.3	<0.2	3.1	<0.01	0.14	1
SM 268910	Soil	20.0	276	18.6	3.4	<0.01	0.01	0.26	0.6	<0.2	<0.2	5.0	<0.01	0.13	2
SM 268911	Soil	40.0	541	25.1	2.3	<0.01	0.02	<0.05	0.6	0.4	<0.2	5.2	<0.01	0.16	2
SM 268912	Soil	22.3	387	33.8	2.9	<0.01	0.03	0.70	0.4	<0.2	<0.2	10.8	<0.01	0.16	0
SM 268913	Soil	29.2	423	127.6	2.9	<0.01	0.02	0.54	0.4	0.3	<0.2	4.0	<0.01	0.20	1
SM 268914	Soil	9.5	391	43.0	3.6	<0.01	0.03	0.30	0.2	0.3	<0.2	3.4	<0.01	0.04	<0.2
SM 268915	Soil	51.8	406	58.9	5.3	<0.01	0.07	3.44	1.7	0.8	0.2	20.9	<0.01	0.22	4
SM 268916	Soil	30.1	226	52.4	4.4	<0.01	0.04	1.00	1.5	0.4	0.3	12.9	<0.01	0.16	5
SM 268917	Soil	24.5	306	51.2	6.1	<0.01	0.05	1.41	1.1	0.4	0.2	23.0	<0.01	0.13	3
SM 268918	Soil	29.8	318	39.8	2.1	<0.01	0.01	0.33	0.3	<0.2	<0.2	4.7	<0.01	0.06	0
SM 268919	Soil	24.1	369	47.6	2.2	<0.01	0.02	0.22	0.3	<0.2	0.2	6.7	<0.01	0.05	1
SM 268920	Soil	14.5	292	40.8	3.0	<0.01	0.02	0.18	0.3	<0.2	<0.2	5.2	<0.01	0.07	0
SM 268921	Soil	19.2	315	35.3	4.2	<0.01	0.02	0.51	0.5	<0.2	0.3	5.0	<0.01	0.07	1
SM 268922	Soil	11.0	509	27.8	4.4	<0.01	0.01	0.55	0.3	0.3	0.3	4.2	<0.01	0.07	0
SM 268923	Soil	31.4	366	43.1	5.3	<0.01	0.03	1.17	1.6	0.3	0.3	18.0	<0.01	0.11	7
SM 268924	Soil	29.0	185	78.0	4.4	<0.01	0.04	1.45	1.6	0.3	0.3	25.4	<0.01	0.13	5
SM 268925	Soil	6.8	533	31.2	3.8	<0.01	0.03	0.42	0.2	<0.2	<0.2	6.6	<0.01	0.04	<0.2
SM 269251	Soil	31.2	436	47.0	3.3	<0.01	0.01	<0.05	1.4	0.4	0.3	4.7	<0.01	0.13	3
SM 269252	Soil	24.4	410	26.6	2.9	<0.01	0.01	<0.05	1.1	0.2	0.2	2.8	<0.01	0.10	5
SM 269253	Soil	26.9	442	25.7	2.5	<0.01	0.01	<0.05	0.6	<0.2	0.2	3.3	<0.01	0.09	2
SM 269254	Soil	16.8	331	11.8	1.7	<0.01	0.01	<0.05	0.4	<0.2	0.2	2.4	<0.01	0.04	0
SM 269255	Soil	55.1	964	33.7	4.1	<0.01	<0.01	<0.05	3.6	0.3	0.3	24.9	<0.01	0.07	7
SM 269256	Soil	35.2	418	22.3	3.2	<0.01	0.02	<0.05	1.5	<0.2	<0.2	6.2	<0.01	0.13	3
SM 269257	Soil	44.2	227	26.0	3.3	<0.01	0.02	<0.05	3.0	0.6	0.2	13.1	<0.01	0.13	5
SM 269258	Soil	44.4	324	25.5	4.0	<0.01	0.01	<0.05	1.9	<0.2	<0.2	6.2	<0.01	0.11	6
SM 269259	Soil	28.4	624	40.8	6.5	<0.01	0.03	0.05	1.0	0.3	0.2	12.1	<0.01	0.09	1
SM 269260	Soil	38.7	453	30.1	4.6	<0.01	0.01	<0.05	1.6	0.3	0.2	5.5	<0.01	0.10	4
SM 269261	Soil	21.3	524	29.0	5.2	<0.01	0.02	<0.05	0.9	<0.2	<0.2	4.6	<0.01	0.06	2
SM 269262	Soil	23.4	602	22.5	3.1	<0.01	<0.01	<0.05	1.2	<0.2	0.2	2.9	<0.01	0.10	5
SM 269263	Soil	30.5	373	18.8	2.7	<0.01	<0.01	<0.05	1.3	<0.2	0.2	2.9	<0.01	0.06	4
SM 269264	Soil	29.2	444	22.8	4.0	<0.01	0.01	<0.05	1.0	<0.2	<0.2	3.7	<0.01	0.08	2
SM 269265	Soil	31.3	465	22.9	4.6	<0.01	0.01	<0.05	0.8	<0.2	<0.2	6.0	<0.01	0.10	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SM 269266	Soil	34.7	377	22.4	3.6	<0.01	<0.01	<0.05	1.3	<0.2	<0.2	2.7	<0.01	0.09	4
SM 269267	Soil	38.1	322	25.2	3.3	<0.01	<0.01	<0.05	1.5	0.3	<0.2	3.9	<0.01	0.09	4
SM 269268	Soil	35.7	470	23.5	3.4	<0.01	<0.01	<0.05	1.1	<0.2	<0.2	3.9	<0.01	0.12	2
SM 269269	Soil	30.7	563	26.0	3.4	<0.01	<0.01	<0.05	1.3	<0.2	<0.2	5.2	<0.01	0.09	3
SM 269270	Soil	29.5	489	24.8	3.9	<0.01	0.01	<0.05	1.2	<0.2	0.2	4.7	<0.01	0.09	2
SM 269271	Soil	44.8	395	28.5	2.6	<0.01	<0.01	<0.05	2.0	<0.2	<0.2	3.8	<0.01	0.16	6
SM 269272	Soil	24.5	497	48.7	3.6	<0.01	0.02	0.29	0.9	0.4	0.3	7.5	<0.01	0.09	2
SM 269273	Soil	17.1	465	42.5	5.2	<0.01	0.01	0.32	0.6	0.3	0.4	5.2	<0.01	0.12	1
SM 269274	Soil	28.7	345	59.5	2.7	<0.01	0.01	0.81	1.1	0.2	<0.2	4.5	<0.01	0.11	3
SM 269275	Soil	19.4	460	31.2	4.4	<0.01	0.02	0.12	0.6	0.3	0.4	3.6	<0.01	0.14	0
SM 269276	Soil	28.7	290	45.8	2.9	<0.01	0.01	0.28	1.0	0.4	0.2	4.1	<0.01	0.11	3
SM 269277	Soil	21.7	498	33.8	4.3	<0.01	0.02	0.32	0.6	0.4	0.4	4.9	<0.01	0.12	0
SM 269278	Soil	16.6	433	68.6	3.6	<0.01	0.01	0.74	0.7	0.3	0.4	3.3	<0.01	0.11	1
SM 269279	Soil	17.5	420	66.5	3.8	<0.01	0.01	0.86	0.7	0.4	0.3	4.2	<0.01	0.11	2
SM 269280	Soil	24.4	455	58.5	3.9	<0.01	0.02	<0.05	0.8	0.4	0.3	3.9	<0.01	0.09	1
SM 269281	Soil	18.5	597	38.4	3.7	<0.01	0.03	0.06	0.3	<0.2	0.3	4.2	<0.01	0.10	<0.2
SM 269282	Soil	29.0	908	35.2	4.1	<0.01	0.03	0.07	0.5	0.5	0.3	4.7	<0.01	0.13	0
SM 269283	Soil	21.7	371	38.7	2.4	<0.01	<0.01	<0.05	0.5	0.2	<0.2	3.9	<0.01	0.08	1
SM 269284	Soil	23.0	611	26.5	5.4	<0.01	<0.01	0.12	0.8	0.2	0.3	5.2	<0.01	0.12	1
SM 269285	Soil	8.9	290	8.0	2.7	<0.01	<0.01	<0.05	0.2	<0.2	<0.2	2.3	<0.01	0.04	<0.2
SM 269286	Soil	0.3	230	5.4	0.8	<0.01	0.02	<0.05	0.1	<0.2	<0.2	4.1	<0.01	0.02	<0.2
SM 269287	Soil	11.1	429	8.8	2.3	<0.01	0.02	0.13	0.1	0.3	<0.2	3.3	<0.01	0.11	<0.2
SM 269288	Soil	21.1	467	32.1	3.0	<0.01	<0.01	<0.05	0.9	0.4	0.3	3.3	<0.01	0.08	4
SM 269289	Soil	24.0	660	22.6	5.1	<0.01	0.02	<0.05	1.0	0.4	0.5	4.2	0.01	0.07	2
SM 269290	Soil	17.3	350	50.0	3.3	<0.01	0.02	2.37	0.7	0.8	<0.2	31.8	<0.01	0.30	2
SM 269291	Soil	24.9	308	23.3	3.1	<0.01	0.01	<0.05	1.2	0.4	0.5	4.7	<0.01	0.06	3
SM 269292	Soil	10.3	446	18.8	2.7	<0.01	0.01	<0.05	0.2	<0.2	0.7	3.8	<0.01	0.04	<0.2
SM 269293	Soil	8.8	446	19.9	3.4	<0.01	0.02	<0.05	0.4	<0.2	0.2	2.6	<0.01	0.03	<0.2
SM 269294	Soil	10.7	841	18.0	5.2	<0.01	0.03	0.06	0.2	0.4	0.3	5.3	<0.01	0.06	<0.2
SM 269295	Soil	16.6	542	31.8	4.0	<0.01	0.03	0.23	0.3	0.5	0.4	8.0	<0.01	0.10	0
SM 269296	Soil	22.4	759	44.8	4.5	<0.01	0.03	1.65	0.9	0.3	0.2	5.2	<0.01	0.15	1
SM 269297	Soil	13.3	688	20.0	3.8	<0.01	0.05	0.74	0.2	<0.2	<0.2	5.3	<0.01	0.07	<0.2
SM 269298	Soil	13.1	606	19.8	3.0	<0.01	0.04	0.93	0.2	<0.2	<0.2	5.4	<0.01	0.05	<0.2
SM 269299	Soil	22.9	898	60.9	5.8	<0.01	0.06	<0.05	0.3	0.4	0.3	5.6	<0.01	0.08	0
SM 269300	Soil	37.0	840	37.2	4.1	<0.01	0.05	0.21	0.3	0.4	<0.2	6.1	<0.01	0.12	1
SM 269301	Soil	12.8	534	63.1	3.7	<0.01	0.03	1.46	0.2	0.3	<0.2	5.0	<0.01	0.05	<0.2
SM 269302	Soil	44.5	317	134.6	3.9	<0.01	0.04	1.19	1.1	0.4	<0.2	42.4	<0.01	0.08	2
SM 269303	Soil	20.4	725	52.3	6.3	<0.01	0.04	1.66	0.2	0.2	<0.2	11.4	<0.01	0.08	<0.2
SM 269304	Soil	16.5	1207	52.0	4.7	<0.01	0.09	0.47	0.2	0.5	<0.2	17.3	<0.01	0.17	<0.2
SM 269305	Soil	18.7	502	46.0	4.3	<0.01	0.06	1.67	0.4	0.3	<0.2	13.6	<0.01	0.15	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SM 269306	Soil	23.9	1443	41.5	4.0	<0.01	0.04	<0.05	0.6	0.6	<0.2	4.7	<0.01	0.10	1
SM 269307	Soil	13.3	433	17.7	4.8	<0.01	0.02	0.07	0.2	<0.2	<0.2	6.8	<0.01	0.06	<0.2
SM 269308	Soil	12.2	568	18.3	5.1	<0.01	0.02	<0.05	0.2	<0.2	0.3	6.9	<0.01	0.06	<0.2
SM 269309	Soil	21.5	629	22.2	5.0	<0.01	0.02	<0.05	0.5	<0.2	0.2	6.1	<0.01	0.13	1
SM 269310	Soil	28.3	482	106.5	5.8	<0.01	0.04	1.64	0.8	0.5	0.3	15.4	<0.01	0.12	1
SM 269311	Soil	19.3	399	26.2	5.4	<0.01	0.03	1.28	0.3	0.3	<0.2	7.3	<0.01	0.06	0
SM 269312	Soil	21.3	375	37.1	5.6	<0.01	0.02	0.76	0.8	<0.2	0.3	11.5	<0.01	0.07	2
SM 269313	Soil	9.6	417	13.0	3.1	<0.01	0.02	0.38	<0.1	<0.2	<0.2	3.0	<0.01	0.03	<0.2
SM 269314	Soil	11.7	411	14.5	2.9	<0.01	0.01	0.07	0.1	<0.2	0.2	3.6	<0.01	0.06	<0.2
SM 269315	Soil	23.5	554	33.3	5.1	<0.01	0.03	<0.05	0.4	0.3	<0.2	5.6	<0.01	0.09	1
SM 269316	Soil	17.1	579	21.9	7.0	<0.01	0.03	0.11	0.2	0.2	0.3	4.9	<0.01	0.08	<0.2
SM 269317	Soil	11.3	479	18.7	4.2	<0.01	0.02	0.10	0.2	<0.2	<0.2	3.2	<0.01	0.06	<0.2
SM 269318	Soil	7.5	407	13.8	3.7	<0.01	0.03	0.69	<0.1	0.4	<0.2	5.2	<0.01	0.02	<0.2
SM 269319	Soil	30.3	436	49.0	5.0	<0.01	0.02	0.48	1.0	0.4	0.2	9.0	<0.01	0.10	3
SM 269320	Soil	30.4	417	101.2	4.4	<0.01	0.06	2.04	0.8	0.4	0.2	27.5	<0.01	0.17	2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SM 268901	Soil	<0.005	<0.05	1	18	0.71	1.6	56	<0.5
SM 268902	Soil	<0.005	<0.05	0	13	0.45	0.7	24	<0.5
SM 268903	Soil	0.008	<0.05	1	18	1.85	2.2	83	<0.5
SM 268904	Soil	<0.005	<0.05	1	14	3.52	1.7	160	<0.5
SM 268905	Soil	<0.005	<0.05	1	21	2.25	1.3	47	<0.5
SM 268906	Soil	0.010	<0.05	1	17	3.18	1.3	51	<0.5
SM 268907	Soil	<0.005	<0.05	0	12	6.50	1.2	51	<0.5
SM 268908	Soil	<0.005	<0.05	1	13	2.64	1.2	56	<0.5
SM 268909	Soil	<0.005	<0.05	1	11	1.07	1.7	103	<0.5
SM 268910	Soil	<0.005	<0.05	1	8	3.43	1.1	65	<0.5
SM 268911	Soil	<0.005	<0.05	1	11	0.41	1.6	106	<0.5
SM 268912	Soil	<0.005	<0.05	1	6	1.36	1.6	89	<0.5
SM 268913	Soil	<0.005	<0.05	1	6	2.67	2.1	151	<0.5
SM 268914	Soil	<0.005	<0.05	1	9	0.71	1.1	53	<0.5
SM 268915	Soil	<0.005	0.07	2	6	1.13	3.5	156	<0.5
SM 268916	Soil	<0.005	0.06	1	7	3.52	1.4	103	<0.5
SM 268917	Soil	<0.005	0.06	1	6	0.87	1.4	88	<0.5
SM 268918	Soil	<0.005	<0.05	0	6	1.56	1.1	97	<0.5
SM 268919	Soil	<0.005	<0.05	1	7	2.79	2.2	133	<0.5
SM 268920	Soil	<0.005	<0.05	0	7	1.00	1.2	77	<0.5
SM 268921	Soil	<0.005	<0.05	1	10	17.17	1.7	98	<0.5
SM 268922	Soil	0.005	<0.05	0	10	1.48	1.0	59	<0.5
SM 268923	Soil	0.005	0.06	1	11	1.41	2.3	104	1.4
SM 268924	Soil	<0.005	0.06	1	4	0.60	1.7	102	1.0
SM 268925	Soil	<0.005	<0.05	0	9	0.94	1.1	47	<0.5
SM 269251	Soil	0.008	<0.05	1	18	0.83	1.9	98	<0.5
SM 269252	Soil	0.008	<0.05	1	17	1.25	1.4	97	1.3
SM 269253	Soil	<0.005	<0.05	1	14	1.02	1.2	97	<0.5
SM 269254	Soil	0.005	<0.05	1	15	1.04	1.3	50	<0.5
SM 269255	Soil	0.007	<0.05	2	27	0.73	5.4	156	2.4
SM 269256	Soil	<0.005	<0.05	1	14	0.35	2.4	121	0.7
SM 269257	Soil	<0.005	<0.05	2	12	0.35	3.4	121	1.4
SM 269258	Soil	<0.005	<0.05	1	19	0.62	1.7	121	2.1
SM 269259	Soil	<0.005	<0.05	1	19	0.29	1.6	147	<0.5
SM 269260	Soil	<0.005	<0.05	1	20	1.54	3.0	116	<0.5
SM 269261	Soil	<0.005	<0.05	1	17	1.27	1.4	82	0.6
SM 269262	Soil	<0.005	<0.05	1	19	0.83	1.3	91	0.9
SM 269263	Soil	<0.005	<0.05	1	19	0.40	1.4	90	<0.5
SM 269264	Soil	<0.005	<0.05	1	17	0.45	1.5	89	<0.5
SM 269265	Soil	<0.005	<0.05	1	17	0.44	2.3	97	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SM 269266	Soil	<0.005	<0.05	1	17	0.25	1.2	104	<0.5
SM 269267	Soil	<0.005	<0.05	1	17	0.33	2.1	108	<0.5
SM 269268	Soil	<0.005	<0.05	1	17	0.43	1.7	107	<0.5
SM 269269	Soil	<0.005	<0.05	1	17	0.56	2.0	94	<0.5
SM 269270	Soil	0.005	<0.05	1	19	0.45	1.6	93	<0.5
SM 269271	Soil	<0.005	<0.05	1	20	0.65	2.0	115	1.6
SM 269272	Soil	0.005	<0.05	1	18	1.06	1.8	117	<0.5
SM 269273	Soil	0.006	<0.05	1	20	1.26	1.4	76	<0.5
SM 269274	Soil	<0.005	<0.05	1	10	1.61	1.8	118	<0.5
SM 269275	Soil	0.011	<0.05	1	23	1.14	1.5	72	<0.5
SM 269276	Soil	<0.005	<0.05	1	14	1.55	1.7	89	<0.5
SM 269277	Soil	0.011	<0.05	1	21	1.95	1.4	90	<0.5
SM 269278	Soil	0.008	<0.05	1	20	0.80	1.4	79	<0.5
SM 269279	Soil	<0.005	<0.05	1	17	1.47	1.4	86	<0.5
SM 269280	Soil	0.006	<0.05	1	18	1.13	1.8	94	<0.5
SM 269281	Soil	<0.005	<0.05	1	17	0.43	1.3	115	<0.5
SM 269282	Soil	<0.005	<0.05	1	20	0.49	1.7	91	<0.5
SM 269283	Soil	<0.005	<0.05	1	9	0.94	1.9	142	<0.5
SM 269284	Soil	0.006	<0.05	1	16	0.47	1.6	80	<0.5
SM 269285	Soil	<0.005	<0.05	0	10	0.46	0.8	36	<0.5
SM 269286	Soil	0.008	<0.05	0	6	0.39	0.4	4	<0.5
SM 269287	Soil	<0.005	<0.05	0	8	0.72	0.6	37	<0.5
SM 269288	Soil	<0.005	<0.05	1	18	1.53	1.4	72	<0.5
SM 269289	Soil	0.021	<0.05	1	27	2.08	1.9	76	0.8
SM 269290	Soil	<0.005	<0.05	1	9	3.41	1.6	82	<0.5
SM 269291	Soil	0.009	<0.05	1	26	0.77	1.8	74	<0.5
SM 269292	Soil	0.005	<0.05	1	34	1.11	1.3	52	<0.5
SM 269293	Soil	<0.005	<0.05	0	17	2.52	1.2	47	<0.5
SM 269294	Soil	<0.005	<0.05	1	23	5.73	1.3	50	<0.5
SM 269295	Soil	0.006	<0.05	1	21	2.57	1.4	76	<0.5
SM 269296	Soil	0.005	<0.05	1	12	3.24	1.8	102	<0.5
SM 269297	Soil	<0.005	<0.05	1	10	5.11	1.1	56	<0.5
SM 269298	Soil	<0.005	<0.05	1	10	0.65	1.3	51	<0.5
SM 269299	Soil	<0.005	<0.05	1	17	2.37	2.2	120	<0.5
SM 269300	Soil	<0.005	<0.05	1	12	1.70	2.2	169	<0.5
SM 269301	Soil	<0.005	<0.05	1	9	7.67	1.6	98	<0.5
SM 269302	Soil	<0.005	0.05	2	4	2.09	2.3	190	<0.5
SM 269303	Soil	<0.005	<0.05	1	10	2.00	1.6	165	<0.5
SM 269304	Soil	<0.005	<0.05	1	17	0.82	2.6	66	<0.5
SM 269305	Soil	<0.005	<0.05	1	6	4.96	1.1	83	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SM 269306	Soil	<0.005	<0.05	1	21	3.37	1.8	95	1.2
SM 269307	Soil	<0.005	<0.05	1	14	3.21	1.6	78	<0.5
SM 269308	Soil	<0.005	<0.05	1	17	3.60	1.1	54	<0.5
SM 269309	Soil	<0.005	<0.05	1	16	3.91	1.5	79	<0.5
SM 269310	Soil	<0.005	0.05	1	12	3.00	2.2	180	<0.5
SM 269311	Soil	<0.005	<0.05	0	8	2.06	0.9	62	<0.5
SM 269312	Soil	<0.005	0.05	1	13	3.79	1.5	81	<0.5
SM 269313	Soil	<0.005	<0.05	0	11	6.87	0.7	46	<0.5
SM 269314	Soil	<0.005	<0.05	0	14	2.71	0.9	51	<0.5
SM 269315	Soil	<0.005	<0.05	1	10	12.70	2.1	99	<0.5
SM 269316	Soil	<0.005	<0.05	1	18	2.99	1.6	77	<0.5
SM 269317	Soil	<0.005	<0.05	1	11	8.99	1.1	57	<0.5
SM 269318	Soil	<0.005	<0.05	0	7	1.71	0.6	32	<0.5
SM 269319	Soil	<0.005	<0.05	1	8	3.07	1.9	119	<0.5
SM 269320	Soil	<0.005	0.07	1	6	2.07	1.9	185	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SM 268901	Soil	22													
SM 268901 Dup		24													
SM 268919	Soil	156													
SM 268919 Dup		163													
STD-Oxi67 expected		1817													
STD-Oxi67 result		1785													
QCV1007-00890-0004-BLK		7													
SM 269262	Soil	36													
SM 269262 Dup		48													
SM 269280	Soil	525													
SM 269280 Dup		56													
STD-Oxi67 expected		1817													
STD-Oxi67 result		1944													
QCV1007-00890-0008-BLK		9													
SM 269298	Soil	31													
SM 269298 Dup		35													
SM 269316	Soil	377													
SM 269316 Dup		365													
STD-Oxi67 expected		1817													
STD-Oxi67 result		1955													
QCV1007-00890-0012-BLK		8													
STD-Oxi67 expected		1817													
STD-Oxi67 result		1887													
QCV1007-00891-0001-BLK				0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
SM 268901	Soil			0.18	0.84	154.2	39	0.3	0.32	0.01	0.23	18.66	7.2	13	2.3
SM 268901 Dup				0.12	0.84	154.1	40	0.3	0.33	0.01	0.22	18.80	7.2	13	2.3
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.31	3.16	19.8	206	0.6	0.17	0.25	0.10	34.17	106.1	880	0.9
SM 268919	Soil			0.08	0.39	1010.6	14	0.2	0.23	<0.01	0.19	17.97	12.4	6	0.6
SM 268919 Dup				0.03	0.39	1019.2	15	0.2	0.22	<0.01	0.18	17.83	12.4	6	0.6
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.25	3.34	6.5	209	0.6	0.15	0.25	0.09	30.67	93.0	924	0.9
SM 269262	Soil			0.21	1.40	54.4	37	0.2	0.41	<0.01	0.14	24.81	11.2	23	1.4
SM 269262 Dup				0.23	1.37	55.0	38	0.2	0.39	<0.01	0.14	24.83	11.5	23	1.4
STD-ME-6 expected				101											
STD-ME-6 result				>100	1.17	269.2	75	0.2	5.32	0.60	31.52	8.15	13.0	31	0.3
SM 269280	Soil			0.19	1.32	342.0	26	0.2	0.66	<0.01	0.27	19.72	11.0	18	0.8
SM 269280 Dup				0.20	1.31	345.0	27	0.2	0.65	<0.01	0.27	18.88	11.1	21	0.8
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.28	2.96	5.7	204	0.7	0.17	0.25	0.10	33.93	107.9	856	0.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SM 269298	Soil			0.30	1.01	63.5	32	0.3	0.27	0.02	0.20	9.61	6.2	12	1.2
SM 269298 Dup				0.25	1.00	65.2	33	0.3	0.26	0.02	0.20	9.70	6.3	12	1.2
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.17	3.16	10.4	205	0.7	0.17	0.25	0.10	34.03	105.4	872	0.9
SM 269316	Soil			0.21	0.61	381.7	42	0.2	0.31	0.01	0.13	25.58	7.1	12	1.0
SM 269316 Dup				0.13	0.61	379.8	42	0.2	0.31	0.01	0.13	24.90	6.8	13	0.9
QCV1007-00891-0013-BLK				<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
STD-DS-1 expected				0.47	4.48	6930.0	221						9.5		
STD-DS-1 result				0.47	0.38	6872.5	21	0.4	0.07	6.63	1.11	21.97	11.1	20	1.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Cu	Fe	Ga	Ge	Hf	In	K	La	Li	Mg	Mn	Mo	Na	Nb
		50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample Description	Sample Type	ppm	%	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%	ppm
		0.2	0.01	0.05	0.05	0.02	0.01	0.01	0.2	0.1	0.01	1	0.05	0.01	0.05
QCV1007-00891-0001-BLK		<0.2	<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05
SM 268901	Soil	28.0	2.64	3.8	<0.05	<0.02	0.02	0.03	10.2	6.4	0.12	286	0.63	<0.01	0.3
SM 268901 Dup		28.4	2.61	3.8	<0.05	<0.02	0.02	0.03	10.3	6.6	0.12	284	0.64	<0.01	0.3
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		660.4	>10	16.3	0.1	0.53	0.09	0.07	15.6	5.0	0.10	1077	0.98	0.02	0.5
SM 268919	Soil	21.8	3.24	1.8	<0.05	<0.02	0.02	0.02	9.2	0.7	0.02	577	0.44	<0.01	0.1
SM 268919 Dup		21.9	3.27	1.8	<0.05	<0.02	0.02	0.02	9.1	0.7	0.02	590	0.44	<0.01	0.1
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		696.4	>10	14.6	0.1	0.47	0.08	0.08	14.2	4.9	0.11	1082	0.90	0.02	0.4
SM 269262	Soil	21.8	4.13	5.8	<0.05	<0.02	0.02	0.02	13.6	32.9	0.47	587	0.43	<0.01	0.4
SM 269262 Dup		21.8	4.10	6.0	<0.05	<0.02	0.02	0.02	13.6	33.4	0.47	591	0.43	<0.01	0.4
STD-ME-6 expected		6130.0													
STD-ME-6 result		6361.4	5.40	3.9	<0.05	0.15	0.44	0.09	3.7	7.8	0.76	1681	20.47	0.06	0.1
SM 269280	Soil	30.5	5.28	5.1	<0.05	<0.02	0.03	0.02	10.5	18.5	0.35	380	0.61	<0.01	0.5
SM 269280 Dup		30.0	5.23	5.1	<0.05	<0.02	0.03	0.02	10.4	18.5	0.35	386	0.60	<0.01	0.5
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		646.2	>10	17.0	0.1	0.50	0.09	0.07	15.6	4.6	0.09	1062	1.01	0.02	0.6
SM 269298	Soil	27.4	2.46	3.3	<0.05	<0.02	0.01	0.03	5.0	10.3	0.15	496	0.45	0.01	0.3
SM 269298 Dup		26.7	2.31	3.3	<0.05	<0.02	0.01	0.03	4.9	10.4	0.14	509	0.45	0.01	0.3
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		660.6	>10	16.8	0.1	0.54	0.10	0.07	15.4	4.8	0.10	1097	1.03	0.02	0.5
SM 269316	Soil	21.6	2.57	3.6	<0.05	<0.02	0.02	0.04	12.8	2.0	0.04	218	1.04	0.01	0.2
SM 269316 Dup		21.0	2.58	3.5	<0.05	<0.02	0.02	0.04	13.3	2.0	0.04	224	1.04	0.01	0.2
QCV1007-00891-0013-BLK		<0.2	<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05
STD-DS-1 expected		27.1									2.76	437			
STD-DS-1 result		25.9	2.92	1.1	<0.05	0.09	0.05	0.11	10.7	1.9	2.65	436	3.80	<0.01	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
QCV1007-00891-0001-BLK		<0.2	<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2
SM 268901	Soil	16.9	551	38.2	6.4	<0.01	0.03	<0.05	0.2	0.5	0.4	6.0	<0.01	0.07	<0.2
SM 268901 Dup		17.4	556	38.0	6.9	<0.01	0.03	<0.05	0.2	0.5	0.4	6.1	<0.01	0.07	<0.2
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		285.2	357	18.1	8.6	<0.01	0.03	<0.05	46.2	0.5	1.7	14.5	<0.01	0.04	6
SM 268919	Soil	24.1	369	47.6	2.2	<0.01	0.02	0.22	0.3	<0.2	0.2	6.7	<0.01	0.05	1
SM 268919 Dup		24.6	371	47.9	2.2	<0.01	0.02	0.21	0.3	<0.2	0.2	6.7	<0.01	0.05	1
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		303.3	370	15.9	8.2	<0.01	0.03	<0.05	43.5	0.4	1.5	12.8	<0.01	0.02	5
SM 269262	Soil	23.4	602	22.5	3.1	<0.01	<0.01	<0.05	1.2	<0.2	0.2	2.9	<0.01	0.10	5
SM 269262 Dup		24.7	598	23.4	3.1	<0.01	<0.01	<0.05	1.2	<0.2	0.2	2.9	<0.01	0.10	5
STD-ME-6 expected				10200											
STD-ME-6 result		27.4	436	>10000	3.2	0.01	2.08	372.16	3.6	2.2	1.6	25.4	<0.01	1.60	1
SM 269280	Soil	24.4	455	58.5	3.9	<0.01	0.02	<0.05	0.8	0.4	0.3	3.9	<0.01	0.09	1
SM 269280 Dup		24.8	457	58.4	4.1	<0.01	0.02	<0.05	0.8	0.4	0.3	4.0	<0.01	0.09	1
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		276.3	358	17.7	8.4	<0.01	0.03	<0.05	45.1	<0.2	1.7	14.5	<0.01	0.05	6
SM 269298	Soil	13.1	606	19.8	3.0	<0.01	0.04	0.93	0.2	<0.2	<0.2	5.4	<0.01	0.05	<0.2
SM 269298 Dup		13.1	606	19.9	3.0	<0.01	0.04	0.90	0.2	<0.2	<0.2	5.4	<0.01	0.05	<0.2
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		280.9	355	18.5	8.4	<0.01	0.03	<0.05	45.6	<0.2	1.7	14.3	<0.01	0.05	6
SM 269316	Soil	17.1	579	21.9	7.0	<0.01	0.03	0.11	0.2	0.2	0.3	4.9	<0.01	0.08	<0.2
SM 269316 Dup		16.7	581	21.7	6.9	<0.01	0.03	0.11	0.2	<0.2	0.3	4.9	<0.01	0.07	<0.2
QCV1007-00891-0013-BLK		<0.2	<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2
STD-DS-1 expected		48.7	340	13.8											
STD-DS-1 result		49.3	318	10.5	4.7	<0.01	2.47	59.66	6.3	0.8	0.9	53.5	<0.01	0.08	2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02305-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
QCV1007-00891-0001-BLK		<0.005	<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
SM 268901	Soil	<0.005	<0.05	1	18	0.71	1.6	56	<0.5
SM 268901 Dup		<0.005	<0.05	1	17	0.78	1.6	57	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.154	0.06	1	213	0.65	9.3	127	20.8
SM 268919	Soil	<0.005	<0.05	1	7	2.79	2.2	133	<0.5
SM 268919 Dup		<0.005	<0.05	1	7	2.78	2.1	136	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.172	0.05	1	195	1.90	8.0	142	18.3
SM 269262	Soil	<0.005	<0.05	1	19	0.83	1.3	91	0.9
SM 269262 Dup		<0.005	<0.05	1	19	0.82	1.3	91	1.0
STD-ME-6 expected								5170	
STD-ME-6 result		0.073	0.18	1	37	2.67	5.8	5420	4.0
SM 269280	Soil	0.006	<0.05	1	18	1.13	1.8	94	<0.5
SM 269280 Dup		0.006	<0.05	1	17	1.24	1.8	104	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.142	0.06	1	221	0.64	9.3	124	21.3
SM 269298	Soil	<0.005	<0.05	1	10	0.65	1.3	51	<0.5
SM 269298 Dup		<0.005	<0.05	1	11	0.72	1.3	50	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.153	0.05	1	212	1.38	9.1	138	20.7
SM 269316	Soil	<0.005	<0.05	1	18	2.99	1.6	77	<0.5
SM 269316 Dup		<0.005	<0.05	1	17	2.91	1.5	78	<0.5
QCV1007-00891-0013-BLK		<0.005	<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
STD-DS-1 expected			20.00					206	
STD-DS-1 result		<0.005	16.65	1	41	7.68	9.2	211	2.7

Certificate of Analysis

10-360-02306-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description:

Date Received: 07/27/2010
Date Completed: 08/12/2010
Invoice:

Samples	Type	Preparation Description
60	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-1AT-GV	Au, 1AT, Gravimetric
Au-2AT-AA	Au, 2AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480033	Rock		0.055	16.29	0.49	146.9	32	0.2	5.18	<0.01	0.03	8.52	1.3	237	0.3
RI 480034	Rock		0.175	16.87	2.39	543.3	117	0.5	0.22	0.03	0.08	19.36	1.6	280	0.9
RI 480035	Rock		0.005	1.60	1.81	27.6	94	0.4	0.11	1.29	0.09	26.25	2.5	176	0.8
RI 480036	Rock		0.605	14.61	2.08	9704.8	120	0.7	0.46	<0.01	0.40	25.92	1.3	210	1.7
RI 480037	Rock	2.219	2.218	13.56	1.34	>10000	101	0.4	1.65	0.01	3.82	10.06	<0.1	130	2.6
RI 480038	Rock		0.150	2.11	2.01	1020.8	103	0.4	0.11	<0.01	0.05	22.75	0.7	203	2.5
RI 480039	Rock	3.359	3.253	2.03	2.32	9500.8	159	1.0	0.79	0.01	0.10	20.85	1.8	233	1.8
RI 480040	Rock		0.048	1.46	1.93	210.1	81	0.5	0.10	<0.01	0.07	20.75	0.8	188	1.5
RI 480041	Rock		0.118	1.95	6.29	>10000	297	2.8	0.46	0.03	1.33	45.16	0.3	59	3.8
RI 480042	Rock	1.250	1.220	3.90	1.57	>10000	98	0.4	0.16	<0.01	0.29	13.97	0.3	140	1.6
RI 480043	Rock	1.100	1.013	36.51	2.76	>10000	178	0.9	1.01	<0.01	0.16	22.79	0.8	172	2.9
RI 480044	Rock		0.234	7.55	1.99	4369.6	101	0.5	0.09	<0.01	0.26	22.04	0.6	187	2.4
RI 480045	Rock	1.273	1.281	15.17	1.31	>10000	68	0.3	0.11	<0.01	1.07	15.15	0.4	186	0.9
RI 480046	Rock		0.036	1.78	2.20	1130.6	96	0.6	0.08	<0.01	0.64	22.04	5.7	205	2.5
RI 480047	Rock		0.113	2.25	2.27	244.6	126	0.6	0.10	<0.01	0.33	26.90	1.3	184	1.8
RI 480051	Rock		0.159	10.23	1.55	866.4	81	0.4	0.43	0.01	0.52	16.64	0.9	168	1.6
RI 480052	Rock		0.031	3.07	2.06	310.1	123	0.6	0.30	<0.01	1.33	27.58	1.0	187	1.9
RI 480053	Rock		0.033	1.67	2.33	69.1	138	0.6	0.13	0.01	0.21	26.28	1.2	204	1.5
RI 480054	Rock		0.032	1.85	2.34	103.9	137	0.5	0.18	0.01	0.02	24.31	1.4	193	1.2
RI 480055	Rock		0.006	1.74	2.22	32.2	121	0.6	0.13	0.02	0.05	22.36	3.0	194	1.8
RI 480056	Rock		0.027	1.60	1.93	93.1	89	0.3	0.28	<0.01	0.16	19.02	2.0	193	1.8
RI 480057	Rock		0.044	1.48	1.52	193.6	76	0.4	0.10	<0.01	0.07	17.66	0.7	222	1.4
RI 480058	Rock	5.288	5.545	39.68	0.94	>10000	59	0.2	0.71	<0.01	3.61	10.62	<0.1	143	1.1
RI 480059	Rock		0.699	2.29	1.94	1042.7	94	0.4	0.13	0.02	0.10	22.40	1.4	182	3.6
RI 480060	Rock		0.181	5.32	2.65	563.5	167	0.7	0.11	0.01	0.57	36.06	4.9	227	4.7
RI 480061	Rock		0.200	3.92	1.49	383.7	97	0.4	0.08	<0.01	0.24	26.50	3.8	196	2.3
RI 480062	Rock		0.138	2.26	2.37	387.4	142	0.6	0.09	0.01	0.82	35.03	3.4	189	4.5
RI 480063	Rock	2.853	3.120	93.86	2.33	9338.9	148	0.6	0.75	0.02	1.07	23.86	7.8	185	3.1
RI 480064	Rock		0.711	2.15	2.35	400.4	122	0.6	0.09	<0.01	0.07	27.47	2.6	120	2.7
RI 480065	Rock		0.288	3.49	2.02	>10000	153	0.5	0.08	0.01	0.25	25.29	0.5	203	1.7
RI 480066	Rock		0.152	1.83	0.40	295.8	25	0.2	0.04	<0.01	0.05	4.15	0.5	239	0.4
RI 480067	Rock		0.090	1.93	1.71	3355.9	93	0.5	0.06	<0.01	0.05	24.30	0.6	204	1.5
RI 480068	Rock	3.047	2.005	4.36	0.62	>10000	47	0.2	0.10	<0.01	0.11	6.67	0.1	221	0.9
RI 480069	Rock		0.012	1.96	1.80	127.8	115	0.9	0.06	<0.01	0.18	15.71	18.9	161	4.4
RI 480070	Rock	3.014	3.076	9.14	1.61	>10000	124	0.7	0.08	0.02	0.57	19.28	<0.1	154	5.1
RI 480071	Rock		0.195	2.60	2.50	1658.7	151	0.6	0.11	<0.01	0.11	28.31	0.8	179	3.0
RI 480072	Rock		0.135	7.27	2.15	722.8	94	0.5	0.14	<0.01	0.11	22.33	0.8	200	2.6
RI 480073	Rock		0.187	2.16	0.21	>10000	12	<0.05	0.15	<0.01	0.04	4.78	0.8	255	0.3
RI 480074	Rock	1.078	1.040	88.00	1.44	>10000	130	0.5	1.23	0.01	1.02	23.13	0.7	203	1.6
RI 480075	Rock		0.731	35.43	2.41	>10000	214	0.5	0.55	0.02	9.21	15.82	1.6	184	2.0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480076	Rock		0.310	2.54	1.51	>10000	134	0.7	0.38	<0.01	0.12	15.47	0.8	253	1.3
RI 480077	Rock		0.046	2.41	0.12	4542.6	16	0.1	0.10	<0.01	0.04	1.84	0.8	265	0.2
RI 480078	Rock		0.128	1.90	0.49	>10000	37	0.3	0.14	<0.01	0.11	4.72	1.5	251	0.4
RI 480079	Rock		0.062	2.03	2.61	534.2	142	0.8	0.10	<0.01	0.04	28.92	0.9	245	2.2
RI 480080	Rock		0.443	1.96	0.31	7146.2	37	0.2	0.13	0.01	0.06	6.75	0.3	251	0.4
RI 480081	Rock		0.056	2.24	1.38	4066.2	94	0.5	0.16	<0.01	0.08	15.24	0.6	258	1.6
RI 480082	Rock	66.515	>10	8.13	1.08	>10000	56	0.3	0.07	<0.01	1.72	8.27	0.1	197	0.9
RI 480083	Rock		0.185	2.01	0.75	8261.5	51	0.3	0.16	<0.01	0.13	14.94	0.4	250	0.5
RI 481003	Rock		0.023	1.79	2.41	105.9	58	0.3	0.58	0.70	<0.01	25.35	9.5	230	0.8
RI 481004	Rock		0.234	2.37	2.54	103.1	94	0.5	1.19	0.01	<0.01	27.24	21.4	238	1.3
RI 481005	Rock		0.930	2.70	0.20	>10000	16	0.2	0.98	<0.01	0.07	10.22	0.8	256	0.3
RI 481006	Rock	15.544	>10	43.97	0.91	>10000	45	0.2	0.48	0.01	73.53	5.04	<0.1	129	1.7
RI 481007	Rock		0.154	1.48	1.97	2824.6	61	0.5	0.13	0.31	0.20	24.61	4.9	214	0.8
RI 481008	Rock	1.606	1.524	4.00	0.14	>10000	8	0.1	3.35	<0.01	0.35	0.77	3.3	190	0.2
RI 481009	Rock	1.014	1.015	1.97	0.15	>10000	13	0.1	0.60	<0.01	0.18	3.69	3.9	202	0.2
RI 481010	Rock		0.247	1.62	0.88	2319.8	49	0.3	0.08	0.03	0.58	12.75	1.0	254	0.7
RI 481011	Rock		0.018	1.64	1.68	937.7	65	0.7	0.15	0.02	0.07	13.00	3.5	257	0.7
RI 481012	Rock		0.017	3.60	0.83	203.1	38	0.3	3.89	0.02	0.32	8.73	1.8	295	0.6
RI 481501	Rock		0.061	1.47	1.07	878.9	21	0.3	0.07	0.02	0.08	17.31	1.7	164	0.3
RI 481502	Rock		0.103	1.52	2.21	246.2	57	0.5	0.14	0.03	0.36	26.10	3.9	190	0.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
RI 480033	Rock	325.1	2.27	1.3	0.8	0.48	0.12	0.16	4.1	7.4	0.01	27	0.88	0.02	0.4
RI 480034	Rock	2717.5	2.43	4.9	0.9	1.26	0.21	0.68	9.1	13.4	0.06	46	0.88	0.63	0.8
RI 480035	Rock	18.7	2.17	3.4	0.7	0.65	0.02	0.47	12.2	31.1	0.15	571	0.61	0.34	0.6
RI 480036	Rock	12.2	1.54	4.6	1.2	1.31	0.07	0.86	12.1	3.6	0.06	57	0.75	0.03	0.9
RI 480037	Rock	10.5	4.54	4.0	1.5	0.98	0.54	0.53	4.9	5.4	0.05	40	0.68	0.02	0.8
RI 480038	Rock	6.7	0.37	4.1	1.5	0.97	0.02	0.81	10.5	34.1	0.06	29	0.69	0.03	1.0
RI 480039	Rock	9.2	1.50	6.0	1.8	0.98	0.02	0.93	9.8	6.1	0.08	67	0.91	0.03	0.8
RI 480040	Rock	5.4	0.44	3.6	1.3	1.04	<0.01	0.44	9.6	6.8	0.03	24	0.71	0.02	1.0
RI 480041	Rock	156.6	>10	18.8	1.2	3.23	0.33	1.78	21.8	18.9	0.15	95	2.92	0.05	1.1
RI 480042	Rock	22.9	1.93	4.0	1.8	1.02	0.35	0.70	7.0	4.3	0.06	25	0.71	0.02	0.8
RI 480043	Rock	41.8	2.58	7.0	1.4	1.63	0.07	1.14	11.2	7.1	0.08	28	0.97	0.03	1.0
RI 480044	Rock	6.2	0.73	3.8	1.5	1.13	1.05	0.80	9.8	8.5	0.06	23	0.76	0.03	0.9
RI 480045	Rock	28.4	1.54	2.7	2.2	0.70	0.73	0.36	7.2	6.5	0.04	27	0.60	0.02	0.5
RI 480046	Rock	14.7	3.22	4.0	1.7	1.18	0.02	0.48	10.2	15.5	0.03	232	0.95	0.03	0.8
RI 480047	Rock	8.6	0.50	4.4	1.3	1.35	0.02	0.77	12.1	11.4	0.05	30	0.59	0.05	1.2
RI 480051	Rock	14.2	0.89	3.4	1.8	0.79	0.75	0.55	7.9	6.1	0.09	42	0.69	0.04	0.8
RI 480052	Rock	8.0	0.54	4.5	1.2	1.14	0.02	0.83	12.6	11.2	0.05	26	0.67	0.04	1.0
RI 480053	Rock	8.6	0.73	5.2	1.0	1.52	<0.01	0.72	12.5	6.5	0.07	52	0.75	0.05	1.2
RI 480054	Rock	6.4	0.92	4.4	1.3	1.26	0.01	0.78	11.7	6.1	0.05	34	0.84	0.03	0.9
RI 480055	Rock	7.9	1.11	4.4	1.2	0.94	0.01	0.48	10.0	17.2	0.03	278	0.62	0.03	0.9
RI 480056	Rock	7.8	0.86	4.0	0.9	1.02	0.02	0.48	8.5	6.4	0.02	74	0.68	0.04	0.9
RI 480057	Rock	6.2	0.46	3.0	1.5	0.93	<0.01	0.33	8.1	16.7	0.02	26	0.68	0.02	0.7
RI 480058	Rock	92.3	6.16	2.5	1.7	0.44	1.01	0.42	5.5	6.1	0.03	39	0.71	0.02	0.4
RI 480059	Rock	6.5	0.58	4.5	2.3	1.34	0.02	0.46	10.6	10.1	0.03	92	0.60	0.02	1.2
RI 480060	Rock	16.2	0.92	6.3	1.4	1.58	0.11	0.95	16.9	13.7	0.06	216	0.85	0.04	1.9
RI 480061	Rock	9.1	0.53	3.7	1.4	1.39	0.14	0.50	12.9	7.5	0.03	187	0.66	0.02	1.4
RI 480062	Rock	13.5	1.03	5.7	1.3	1.39	0.02	0.71	16.7	12.0	0.04	117	0.73	0.04	1.4
RI 480063	Rock	91.5	2.73	5.3	2.7	0.98	0.48	0.93	11.5	7.8	0.06	255	0.88	0.03	0.7
RI 480064	Rock	7.1	0.85	5.2	1.3	1.30	0.01	0.64	12.8	8.1	0.03	88	0.46	0.03	1.2
RI 480065	Rock	10.0	1.31	5.4	1.6	1.46	0.23	0.98	11.7	3.9	0.07	28	0.78	0.03	1.1
RI 480066	Rock	8.4	0.33	1.0	1.5	0.33	<0.01	0.12	2.0	2.4	0.01	25	1.03	<0.01	0.3
RI 480067	Rock	6.6	0.62	3.8	1.6	1.06	0.01	0.79	11.5	3.2	0.06	27	0.81	0.02	0.9
RI 480068	Rock	15.8	1.59	1.2	1.7	0.30	0.04	0.22	3.2	7.2	0.03	28	0.85	0.01	0.4
RI 480069	Rock	6.8	5.28	3.4	0.8	0.72	<0.01	0.37	7.5	39.1	0.03	581	1.39	0.02	0.5
RI 480070	Rock	141.7	3.57	3.4	1.9	0.97	0.36	0.55	9.0	29.9	0.04	43	0.76	0.03	0.5
RI 480071	Rock	13.3	0.49	5.8	1.5	1.68	0.03	1.01	13.2	11.8	0.07	28	0.72	0.03	1.1
RI 480072	Rock	7.0	0.75	4.7	1.9	1.15	0.04	0.83	10.9	17.1	0.07	29	0.73	0.03	1.0
RI 480073	Rock	11.0	1.35	0.6	1.3	0.19	0.02	0.08	2.3	1.7	<0.01	24	1.17	<0.01	0.3
RI 480074	Rock	75.0	2.10	3.8	1.8	1.14	4.44	0.64	11.3	9.9	0.05	24	1.63	0.02	0.8
RI 480075	Rock	56.2	3.12	5.5	1.5	1.14	2.50	0.72	7.8	16.8	0.04	21	0.70	0.03	0.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
RI 480076	Rock	11.6	2.08	4.6	1.2	0.76	0.07	0.65	7.5	7.7	0.05	28	1.29	0.02	0.7
RI 480077	Rock	6.8	0.65	0.5	1.4	<0.1	0.02	0.05	0.9	2.1	<0.01	27	1.19	<0.01	0.2
RI 480078	Rock	10.2	2.08	1.4	1.0	0.29	0.03	0.16	2.4	2.1	0.02	44	1.24	<0.01	0.3
RI 480079	Rock	6.0	0.48	5.8	1.3	1.46	<0.01	0.72	13.4	11.0	0.06	23	0.79	0.02	1.3
RI 480080	Rock	10.0	0.86	1.4	1.4	0.27	0.02	0.14	3.3	6.7	0.01	32	1.18	<0.01	0.3
RI 480081	Rock	6.8	0.66	3.6	1.4	0.67	0.03	0.43	7.2	7.9	0.03	25	1.01	0.01	0.6
RI 480082	Rock	36.6	1.44	2.3	2.1	0.59	0.09	0.44	3.9	3.9	0.04	23	0.77	0.01	0.5
RI 480083	Rock	10.5	0.87	1.5	1.3	0.71	0.03	0.17	7.2	10.8	0.02	28	1.00	<0.01	0.6
RI 481003	Rock	9.2	1.66	4.7	0.8	1.20	0.01	0.32	11.3	19.9	0.28	221	0.67	0.86	1.0
RI 481004	Rock	13.9	3.26	5.2	0.7	1.52	<0.01	0.58	13.1	12.7	0.11	42	0.87	0.54	1.2
RI 481005	Rock	12.6	6.72	1.0	0.9	0.44	0.12	0.09	5.3	2.0	<0.01	26	1.97	<0.01	0.3
RI 481006	Rock	43.8	>10	2.8	0.9	0.53	0.88	0.39	2.9	2.9	0.03	45	0.63	0.03	0.4
RI 481007	Rock	20.9	1.17	4.1	1.3	0.84	0.01	0.42	10.8	3.5	0.07	271	0.80	0.87	0.8
RI 481008	Rock	17.1	>10	0.7	0.5	0.11	0.21	0.03	1.3	2.2	<0.01	36	3.81	<0.01	0.2
RI 481009	Rock	11.8	>10	0.7	0.6	0.12	0.17	0.06	2.4	1.5	<0.01	25	2.98	<0.01	0.2
RI 481010	Rock	6.0	0.76	2.1	1.4	0.59	0.02	0.40	5.8	3.8	0.04	57	0.94	0.02	0.6
RI 481011	Rock	30.4	2.51	3.9	1.3	0.49	0.02	0.26	6.4	21.4	0.19	209	0.85	0.02	0.6
RI 481012	Rock	17.4	0.72	1.9	1.3	0.27	<0.01	0.19	4.5	6.9	0.04	51	1.04	0.07	0.6
RI 481501	Rock	6.8	0.71	1.8	1.7	0.81	<0.01	0.11	8.1	4.7	0.02	219	0.55	0.64	0.6
RI 481502	Rock	14.0	1.07	4.8	1.6	1.29	<0.01	0.37	12.2	8.0	0.10	244	0.94	0.96	1.1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
RI 480033	Rock	5.3	30	1080.9	9.0	0.005	0.08	11.65	0.8	5.9	0.8	5.2	<0.05	0.08	2
RI 480034	Rock	6.7	179	140.8	35.3	<0.005	0.41	3.88	2.4	<0.5	1.2	35.3	0.13	<0.05	7
RI 480035	Rock	8.5	110	20.8	22.6	<0.005	<0.01	<0.05	1.9	<0.5	0.5	33.6	0.07	0.12	6
RI 480036	Rock	4.5	98	3097.1	42.9	<0.005	0.09	49.84	2.1	<0.5	3.0	16.2	0.12	<0.05	7
RI 480037	Rock	2.0	407	6616.0	29.0	<0.005	0.17	100.80	2.4	<0.5	4.2	31.8	0.05	<0.05	9
RI 480038	Rock	3.0	112	145.0	41.2	<0.005	0.02	4.60	2.4	<0.5	3.9	29.0	0.11	<0.05	5
RI 480039	Rock	5.4	72	63.0	47.6	<0.005	0.13	15.54	2.5	<0.5	0.9	17.1	0.11	0.20	6
RI 480040	Rock	3.7	74	34.3	22.4	<0.005	<0.01	2.56	1.6	<0.5	0.8	36.1	0.11	<0.05	5
RI 480041	Rock	10.9	1181	74.4	87.7	<0.005	0.09	46.50	9.0	2.5	2.8	34.6	0.18	0.21	59
RI 480042	Rock	2.2	328	675.1	35.3	<0.005	0.07	33.73	2.8	1.3	5.1	19.7	0.10	0.20	5
RI 480043	Rock	3.8	546	>10000	55.0	<0.005	0.36	58.56	3.8	1.6	6.0	40.7	0.13	<0.05	12
RI 480044	Rock	2.8	56	3869.2	39.2	<0.005	0.07	15.29	1.8	<0.5	11.4	17.8	0.10	<0.05	5
RI 480045	Rock	2.7	148	6650.6	17.5	<0.005	0.11	36.97	1.6	1.8	3.9	12.5	0.05	<0.05	4
RI 480046	Rock	14.2	315	76.6	25.2	<0.005	<0.01	4.38	2.0	<0.5	1.0	30.5	0.07	<0.05	8
RI 480047	Rock	4.9	66	83.0	38.9	<0.005	<0.01	1.70	2.1	1.2	5.3	27.3	0.18	<0.05	5
RI 480051	Rock	4.0	414	4295.8	27.3	<0.005	0.14	7.07	2.8	2.1	9.0	27.7	0.08	0.10	7
RI 480052	Rock	4.0	72	223.5	40.8	<0.005	<0.01	1.99	2.0	1.7	4.9	24.0	0.12	<0.05	7
RI 480053	Rock	4.7	103	79.5	36.1	<0.005	<0.01	1.95	2.4	<0.5	2.1	15.0	0.15	<0.05	5
RI 480054	Rock	4.5	378	75.0	39.4	<0.005	0.15	1.78	2.0	<0.5	2.2	12.7	0.12	<0.05	7
RI 480055	Rock	7.2	125	31.8	23.7	<0.005	<0.01	0.60	1.9	<0.5	0.6	11.2	0.13	<0.05	6
RI 480056	Rock	6.0	61	45.1	27.2	<0.005	<0.01	0.29	1.9	<0.5	0.7	21.2	0.11	<0.05	6
RI 480057	Rock	3.5	118	31.4	17.0	<0.005	0.01	2.04	1.5	<0.5	0.7	57.5	0.10	<0.05	4
RI 480058	Rock	2.7	246	>10000	20.7	<0.005	0.68	99.97	2.1	<0.5	8.9	13.0	<0.05	0.20	4
RI 480059	Rock	3.9	109	87.5	25.5	<0.005	<0.01	4.29	2.1	1.9	1.3	62.3	0.12	<0.05	5
RI 480060	Rock	9.9	168	863.5	45.5	<0.005	0.02	5.90	3.6	<0.5	5.1	83.1	0.19	<0.05	8
RI 480061	Rock	5.7	132	845.4	25.4	<0.005	0.01	6.36	2.4	<0.5	3.7	68.1	0.12	<0.05	6
RI 480062	Rock	9.6	131	94.9	35.2	<0.005	<0.01	3.28	3.1	<0.5	1.2	75.7	0.21	0.06	7
RI 480063	Rock	10.2	1121	>10000	45.5	0.006	0.43	68.93	6.9	<0.5	22.3	130.4	0.08	<0.05	14
RI 480064	Rock	5.4	112	123.0	32.1	<0.005	<0.01	3.69	2.3	<0.5	0.8	72.2	0.15	<0.05	6
RI 480065	Rock	3.3	108	468.4	49.1	<0.005	0.13	10.43	2.5	1.7	5.4	13.8	0.14	0.11	4
RI 480066	Rock	3.8	27	35.3	7.2	<0.005	<0.01	1.96	1.0	<0.5	0.6	4.3	<0.05	0.05	1
RI 480067	Rock	3.4	75	58.3	41.5	<0.005	0.04	4.99	1.8	<0.5	10.0	10.5	0.10	<0.05	3
RI 480068	Rock	3.5	148	84.6	12.3	<0.005	0.03	18.06	1.2	<0.5	11.5	11.3	<0.05	0.09	1
RI 480069	Rock	48.6	121	34.2	19.1	<0.005	0.01	1.51	2.4	<0.5	0.7	48.8	0.06	<0.05	5
RI 480070	Rock	3.2	192	173.4	27.7	<0.005	0.22	60.74	2.3	<0.5	10.2	42.4	0.09	0.17	12
RI 480071	Rock	3.3	84	76.2	52.5	<0.005	0.02	3.74	2.4	<0.5	6.5	24.3	0.13	<0.05	5
RI 480072	Rock	3.5	80	1134.7	40.7	<0.005	0.05	5.76	2.1	<0.5	4.5	23.6	0.11	0.06	5
RI 480073	Rock	5.2	20	31.1	4.2	<0.005	0.24	8.51	0.7	3.3	0.7	4.6	<0.05	0.46	1
RI 480074	Rock	3.7	543	>10000	30.5	<0.005	0.39	81.27	2.5	<0.5	5.8	276.1	0.08	0.11	25
RI 480075	Rock	3.9	877	>10000	31.4	<0.005	0.76	44.43	2.7	1.3	5.6	879.9	0.10	0.43	8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
RI 480076	Rock	4.0	164	242.8	28.2	<0.005	0.17	16.71	2.9	5.0	0.9	107.6	0.09	2.01	5
RI 480077	Rock	5.1	33	84.4	2.5	<0.005	0.11	2.60	0.7	2.4	0.4	22.3	<0.05	0.13	0
RI 480078	Rock	6.9	60	64.5	7.7	<0.005	0.63	8.35	1.0	5.8	0.5	25.2	<0.05	0.80	2
RI 480079	Rock	3.8	134	32.2	35.2	<0.005	<0.01	1.45	2.3	<0.5	0.9	133.6	0.14	<0.05	7
RI 480080	Rock	4.4	65	29.2	7.3	<0.005	0.05	2.57	1.3	2.8	0.6	22.6	<0.05	0.53	2
RI 480081	Rock	4.1	129	126.9	21.4	<0.005	0.03	2.26	2.2	1.5	0.6	112.4	0.06	0.15	5
RI 480082	Rock	2.8	48	133.2	22.5	<0.005	0.06	8.56	2.3	2.5	3.3	21.0	<0.05	<0.05	2
RI 480083	Rock	3.5	109	39.4	8.4	<0.005	<0.01	7.25	1.4	<0.5	0.9	98.7	<0.05	1.12	4
RI 481003	Rock	12.5	106	24.4	16.1	<0.005	0.18	0.80	2.7	<0.5	0.6	36.7	0.10	0.16	6
RI 481004	Rock	17.8	75	51.3	29.0	<0.005	1.94	4.56	2.9	<0.5	1.0	19.9	0.14	0.25	5
RI 481005	Rock	7.2	34	28.1	4.7	<0.005	1.90	50.59	1.0	20.9	0.4	3.0	<0.05	3.42	3
RI 481006	Rock	4.7	53	>10000	21.5	<0.005	8.80	174.93	1.3	2.9	6.9	24.8	<0.05	0.11	3
RI 481007	Rock	8.3	241	75.1	20.6	<0.005	0.25	2.68	2.6	<0.5	0.9	43.5	0.14	0.10	5
RI 481008	Rock	11.4	49	422.1	1.9	<0.005	4.98	61.95	1.0	37.8	0.3	6.3	<0.05	6.16	1
RI 481009	Rock	11.0	69	37.5	3.1	0.006	4.08	60.52	0.8	14.1	0.3	4.9	<0.05	5.00	1
RI 481010	Rock	5.2	63	222.3	18.9	<0.005	0.13	2.85	1.4	<0.5	3.5	5.3	<0.05	0.08	3
RI 481011	Rock	20.2	154	46.2	15.4	<0.005	0.06	0.90	2.2	<0.5	0.5	12.0	<0.05	0.10	4
RI 481012	Rock	8.9	133	1586.9	11.3	<0.005	0.03	1.31	1.6	4.4	0.5	8.6	<0.05	0.41	3
RI 481501	Rock	5.5	49	24.2	6.4	<0.005	0.04	1.87	1.8	<0.5	0.5	33.6	0.06	<0.05	4
RI 481502	Rock	10.3	121	42.2	20.2	<0.005	<0.01	1.67	2.5	<0.5	0.8	32.9	0.12	<0.05	6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480033	Rock	0.007	0.03	1	<1	1.25	0.9	8	16.3
RI 480034	Rock	0.023	0.19	1	12	2.79	3.0	14	36.0
RI 480035	Rock	0.020	0.10	1	10	3.48	3.9	27	21.4
RI 480036	Rock	0.028	0.21	1	8	5.51	2.3	34	38.6
RI 480037	Rock	0.014	0.18	1	7	5.93	1.3	148	30.5
RI 480038	Rock	0.025	0.20	1	11	7.48	2.0	6	38.6
RI 480039	Rock	0.027	0.23	1	13	4.31	2.3	15	38.6
RI 480040	Rock	0.024	0.09	1	3	17.73	2.4	10	34.1
RI 480041	Rock	0.045	0.48	7	98	16.75	15.2	194	125.5
RI 480042	Rock	0.024	0.19	1	7	8.65	1.8	23	31.7
RI 480043	Rock	0.034	0.31	2	17	5.88	3.0	17	46.9
RI 480044	Rock	0.026	0.18	1	11	6.22	2.7	23	39.0
RI 480045	Rock	0.013	0.08	1	<1	5.25	1.5	47	24.7
RI 480046	Rock	0.019	0.13	2	9	14.81	3.0	160	41.4
RI 480047	Rock	0.029	0.17	1	12	6.66	3.4	15	45.5
RI 480051	Rock	0.021	0.14	1	4	5.19	2.1	35	33.8
RI 480052	Rock	0.030	0.18	1	5	6.73	3.0	14	42.1
RI 480053	Rock	0.033	0.16	1	7	9.50	3.1	17	48.0
RI 480054	Rock	0.026	0.18	1	6	2.90	3.2	18	45.3
RI 480055	Rock	0.022	0.08	1	8	7.12	3.3	18	32.9
RI 480056	Rock	0.022	0.12	1	9	5.02	2.8	80	41.6
RI 480057	Rock	0.020	0.06	1	2	10.24	2.2	6	31.6
RI 480058	Rock	0.012	0.09	0	2	6.78	1.2	119	17.6
RI 480059	Rock	0.031	0.12	1	13	6.81	2.9	11	46.9
RI 480060	Rock	0.045	0.22	2	16	9.78	4.3	102	58.4
RI 480061	Rock	0.037	0.12	2	5	8.73	3.4	58	50.9
RI 480062	Rock	0.040	0.16	2	16	7.84	3.6	69	55.2
RI 480063	Rock	0.024	0.24	11	16	9.72	3.3	188	38.1
RI 480064	Rock	0.034	0.15	1	14	9.76	3.3	22	48.1
RI 480065	Rock	0.032	0.23	1	10	7.48	3.4	16	53.5
RI 480066	Rock	0.008	<0.02	0	<1	6.48	0.6	5	9.2
RI 480067	Rock	0.024	0.18	1	7	5.66	2.4	8	37.6
RI 480068	Rock	0.008	0.06	0	<1	6.55	0.7	9	14.2
RI 480069	Rock	0.016	0.08	2	7	3.96	3.6	122	33.9
RI 480070	Rock	0.016	0.19	1	1	3.20	3.1	28	31.5
RI 480071	Rock	0.033	0.25	1	13	2.99	3.1	7	44.0
RI 480072	Rock	0.029	0.20	1	12	9.00	2.5	11	40.6
RI 480073	Rock	<0.005	0.02	0	<1	5.19	0.5	5	6.1
RI 480074	Rock	0.023	0.32	3	6	6.08	2.9	106	37.7
RI 480075	Rock	0.026	0.23	2	13	15.24	4.7	393	43.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480076	Rock	0.023	0.19	1	14	6.80	1.9	9	24.7
RI 480077	Rock	<0.005	<0.02	<0.1	<1	3.70	0.2	5	2.4
RI 480078	Rock	0.007	0.02	0	<1	7.73	0.8	9	10.1
RI 480079	Rock	0.035	0.15	1	10	11.26	3.7	5	44.3
RI 480080	Rock	0.008	0.18	0	<1	15.48	0.8	4	10.5
RI 480081	Rock	0.020	0.13	1	<1	6.19	1.8	4	24.3
RI 480082	Rock	0.013	0.09	1	4	5.50	1.1	30	18.7
RI 480083	Rock	0.014	0.03	1	<1	5.60	1.7	8	29.0
RI 481003	Rock	0.028	0.12	1	7	4.32	4.0	20	40.3
RI 481004	Rock	0.036	0.60	1	11	4.52	3.7	11	54.5
RI 481005	Rock	0.007	0.13	0	<1	4.07	1.0	10	17.0
RI 481006	Rock	0.008	0.13	1	6	5.20	1.3	8594	18.3
RI 481007	Rock	0.027	0.08	1	15	20.64	3.0	22	30.2
RI 481008	Rock	<0.005	0.02	0	<1	11.65	0.3	32	4.1
RI 481009	Rock	<0.005	0.05	0	<1	4.68	0.4	15	5.3
RI 481010	Rock	0.013	0.06	0	<1	11.33	1.3	30	20.8
RI 481011	Rock	0.016	0.05	1	1	12.78	1.9	53	20.3
RI 481012	Rock	0.012	0.03	1	<1	12.46	1.0	36	11.1
RI 481501	Rock	0.015	<0.02	1	<1	13.45	2.7	11	31.0
RI 481502	Rock	0.026	0.07	1	1	5.07	3.1	47	44.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480033	Rock		0.055												
RI 480033 Dup			0.044												
RI 480054	Rock		0.032												
RI 480054 Dup			0.029												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.786												
QCV1007-00916-0004-BLK			<0.005												
RI 480072	Rock		0.135												
RI 480072 Dup			0.142												
RI 481009	Rock		1.015												
RI 481009 Dup			1.009												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.834												
QCV1007-00916-0008-BLK			<0.005												
QCV1007-00917-0001-BLK				0.02	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
RI 480033	Rock			16.29	0.49	146.9	32	0.2	5.18	<0.01	0.03	8.52	1.3	237	0.3
RI 480033 Dup				15.47	0.49	146.4	31	0.2	4.98	<0.01	0.03	8.60	1.3	233	0.3
STD-ME-8 expected				61.70											
STD-ME-8 result				58.82	4.51	2600.9	604	0.9	4.35	6.73	163.94	24.48	<0.1	42	2.9
RI 480054	Rock			1.85	2.34	103.9	137	0.5	0.18	0.01	0.02	24.31	1.4	193	1.2
RI 480054 Dup				1.80	2.36	106.7	135	0.5	0.17	0.01	0.02	23.76	1.4	202	1.2
STD-OREAS-45P-4A expected						13.4			0.21				122.0	1103	
STD-OREAS-45P-4A result					6.12	41.0	284	0.9	0.24	0.25	0.14	45.62	111.3	934	2.2
RI 480072	Rock			7.27	2.15	722.8	94	0.5	0.14	<0.01	0.11	22.33	0.8	200	2.6
RI 480072 Dup				7.29	2.15	715.9	93	0.4	0.14	<0.01	0.11	22.53	0.8	207	2.5
STD-ME-8 expected				61.70											
STD-ME-8 result				59.30	4.18	2831.4	572	1.0	4.35	6.40	167.39	23.42	<0.1	42	3.0
RI 481009	Rock			1.97	0.15	>10000	13	0.1	0.60	<0.01	0.18	3.69	3.9	202	0.2
RI 481009 Dup				1.72	0.15	>10000	14	0.1	0.61	<0.01	0.18	3.68	4.0	201	0.2
QCV1007-00917-0009-BLK				0.02	<0.01	0.9	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
STD-SY-4 expected							340	2.6				122.00	2.8	12	1.5
STD-SY-4 result				1.55	8.13	141.6	306	3.3	0.04	5.42	0.11	80.73	3.6	7	1.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
QCV1007-00917-0001-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
RI 480033	Rock	325.1	2.27	1.3	0.8	0.48	0.12	0.16	4.1	7.4	0.01	27	0.88	0.02	0.4
RI 480033 Dup		327.9	2.25	1.3	0.9	0.46	0.11	0.16	4.1	7.5	0.01	27	0.82	0.02	0.4
STD-ME-8 expected		1030.0													
STD-ME-8 result		969.9	3.71	9.2	0.5	1.09	0.09	1.40	12.0	15.0	0.72	2986	5.42	1.20	3.7
RI 480054	Rock	6.4	0.92	4.4	1.3	1.26	0.01	0.78	11.7	6.1	0.05	34	0.84	0.03	0.9
RI 480054 Dup		6.3	0.92	4.4	1.4	1.20	<0.01	0.78	10.7	6.1	0.05	35	0.85	0.03	0.9
STD-OREAS-45P-4A expected		749.0												0.08	
STD-OREAS-45P-4A result		744.5	>10	20.7	1.7	3.85	0.11	0.33	22.7	13.7	0.22	1256	2.13	0.07	20.5
RI 480072	Rock	7.0	0.75	4.7	1.9	1.15	0.04	0.83	10.9	17.1	0.07	29	0.73	0.03	1.0
RI 480072 Dup		6.8	0.75	4.5	1.9	1.15	0.04	0.83	10.7	17.0	0.07	29	0.73	0.03	0.9
STD-ME-8 expected		1030.0													
STD-ME-8 result		1018.9	3.85	9.6	0.6	1.14	0.08	1.42	11.5	14.8	0.74	3062	5.54	1.23	3.7
RI 481009	Rock	11.8	>10	0.7	0.6	0.12	0.17	0.06	2.4	1.5	<0.01	25	2.98	<0.01	0.2
RI 481009 Dup		11.7	>10	0.7	0.6	0.11	0.17	0.06	2.4	1.4	<0.01	26	3.11	<0.01	0.2
QCV1007-00917-0009-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
STD-SY-4 expected		7.0		35.0		10.60			58.0	37.0					13.0
STD-SY-4 result		9.2	4.11	32.6	0.5	0.97	0.03	1.32	33.6	35.2	0.25	803	0.24	5.12	13.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
QCV1007-00917-0001-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
RI 480033	Rock	5.3	30	1080.9	9.0	0.005	0.08	11.65	0.8	5.9	0.8	5.2	<0.05	0.08	2
RI 480033 Dup		5.3	31	1077.4	8.7	<0.005	0.08	11.17	0.8	5.3	0.8	5.1	<0.05	<0.05	2
STD-ME-8 expected				19400											
STD-ME-8 result		28.1	612	>10000	63.5	<0.005	1.45	50.67	7.2	3.1	3.1	380.8	0.37	0.52	4
RI 480054	Rock	4.5	378	75.0	39.4	<0.005	0.15	1.78	2.0	<0.5	2.2	12.7	0.12	<0.05	7
RI 480054 Dup		4.7	377	76.4	38.5	<0.005	0.15	1.81	2.0	<0.5	2.2	12.6	0.12	0.06	7
STD-OREAS-45P-4A expected		385.0	454	22.0				0.92							
STD-OREAS-45P-4A result		364.9	424	42.8	23.9	<0.005	0.02	<0.05	59.9	<0.5	2.9	30.8	1.70	0.13	9
RI 480072	Rock	3.5	80	1134.7	40.7	<0.005	0.05	5.76	2.1	<0.5	4.5	23.6	0.11	0.06	5
RI 480072 Dup		3.5	81	1109.8	40.9	<0.005	0.05	5.82	2.1	<0.5	4.5	23.7	0.11	0.06	5
STD-ME-8 expected				19400											
STD-ME-8 result		29.0	628	>10000	65.8	<0.005	1.59	49.88	6.7	3.3	3.1	369.0	0.38	0.59	4
RI 481009	Rock	11.0	69	37.5	3.1	0.006	4.08	60.52	0.8	14.1	0.3	4.9	<0.05	5.00	1
RI 481009 Dup		11.6	67	37.1	3.1	<0.005	4.12	60.63	0.8	17.2	0.3	4.7	<0.05	5.03	1
QCV1007-00917-0009-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
STD-SY-4 expected		9.0		10.0	55.0				1.1			1191.0	0.90		1
STD-SY-4 result		6.5	546	23.9	18.8	0.010	<0.01	<0.05	1.1	<0.5	8.4	859.9	1.08	0.29	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02306-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1007-00917-0001-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
RI 480033	Rock	0.007	0.03	1	<1	1.25	0.9	8	16.3
RI 480033 Dup		0.008	0.03	0	<1	1.11	0.9	8	16.7
STD-ME-8 expected								19200	
STD-ME-8 result		0.192	0.73	2	58	11.73	10.3	>10000	31.9
RI 480054	Rock	0.026	0.18	1	6	2.90	3.2	18	45.3
RI 480054 Dup		0.025	0.18	1	6	2.63	3.2	18	44.4
STD-OREAS-45P-4A expected								142	
STD-OREAS-45P-4A result		1.039	0.17	2	247	3.58	12.6	135	152.6
RI 480072	Rock	0.029	0.20	1	12	9.00	2.5	11	40.6
RI 480072 Dup		0.029	0.20	1	12	9.32	2.5	11	40.0
STD-ME-8 expected								19200	
STD-ME-8 result		0.195	0.70	2	63	13.63	9.7	>10000	32.0
RI 481009	Rock	<0.005	0.05	0	<1	4.68	0.4	15	5.3
RI 481009 Dup		<0.005	0.05	0	<1	4.32	0.4	15	5.5
QCV1007-00917-0009-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected				1	8		119.0	93	517.0
STD-SY-4 result		0.157	0.21	1	1	1.34	92.1	93	50.2

Certificate of Analysis

10-360-02307-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description:

Date Received: 07/27/2010
Date Completed: 08/12/2010
Invoice:

Samples	Type	Preparation Description
275	Soil	SP-SS-1K/Soils, Humus Sediments 1kg dried, sieved and riffle split

Method	Description
50-AR-UT	50 Element, Aqua Regia, ICPMS, Ultra Trace Level
Au-1AT-AA	Au, 1AT Fire Assay, AAS
Au-1AT-GV	Au, 1AT, Gravimetric

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SG 296338	Soil	1.573	2.449	0.41	0.61	1908.5	49	0.2	0.31	0.02	0.32	24.41	9.2	8	2.2
SG 296339	Soil	0.415		0.32	0.42	1151.5	39	0.7	0.49	<0.01	0.10	39.11	21.0	6	4.2
SG 296340	Soil	0.432		0.16	0.28	470.5	52	0.1	0.14	0.04	0.14	11.45	4.0	3	0.8
SG 296341	Soil	0.021		0.02	0.18	13.3	10	<0.05	0.02	0.02	0.04	1.06	1.2	1	0.1
SG 296342	Soil	0.405		0.12	0.48	193.4	192	0.2	0.20	0.05	0.36	19.48	12.6	9	1.4
SG 296343	Soil	0.013		0.03	0.39	43.0	70	0.1	0.06	0.08	0.14	4.73	3.1	5	0.6
SG 296344	Soil	0.101		0.07	0.40	287.1	28	0.2	0.07	0.03	0.25	6.96	17.9	4	0.5
SG 296345	Soil	0.554		0.16	0.46	1009.2	83	0.2	0.12	0.04	0.19	12.75	6.4	4	1.0
SG 296346	Soil	0.268		<0.01	0.28	588.9	25	0.2	0.20	<0.01	0.23	18.01	9.6	5	0.9
SG 296347	Soil	0.275		0.10	0.46	293.5	64	0.2	0.18	0.05	0.33	14.21	8.0	8	1.0
SG 296348	Soil	0.012		0.12	0.39	41.8	22	0.1	0.08	0.02	0.27	5.09	5.9	5	0.5
SG 296349	Soil	0.027		0.08	0.77	207.8	35	0.2	0.22	0.02	0.44	22.21	9.1	9	1.0
SG 296350	Soil	0.007		0.02	0.35	55.1	46	0.1	0.09	0.04	0.53	6.82	7.1	4	0.4
SG 296351	Soil	0.021		0.10	0.75	517.7	40	0.3	0.27	0.02	1.73	23.37	13.5	12	1.7
SG 296352	Soil	0.045		<0.01	1.06	342.7	35	0.3	0.27	0.02	0.78	25.02	9.8	13	1.6
SG 296353	Soil	0.037		0.08	0.95	360.3	40	0.3	0.32	0.02	0.99	26.94	13.9	13	1.6
SG 296354	Soil	0.048		<0.01	1.86	206.6	42	0.7	0.46	0.04	0.53	29.61	28.8	28	5.0
SG 296355	Soil	0.012		0.35	1.39	351.8	35	0.6	0.35	0.04	0.68	18.71	29.5	16	2.4
SG 296356	Soil	0.023		0.28	1.11	501.8	39	0.4	0.42	0.02	0.79	24.27	12.2	15	1.3
SG 296357	Soil	0.016		0.25	0.71	520.1	50	0.3	0.29	0.07	1.27	20.71	15.1	12	1.4
SG 296358	Soil	0.017		0.66	0.67	218.5	25	0.2	0.17	0.01	0.58	13.66	7.7	8	0.9
SG 296359	Soil	0.049		0.19	0.18	10.3	28	<0.05	0.05	0.02	0.13	3.43	1.9	4	0.4
SG 296360	Soil	0.511		0.25	0.37	75.4	52	0.1	0.13	0.08	0.26	8.54	19.8	4	1.0
SG 296361	Soil	0.041		0.29	0.65	174.0	32	0.2	0.10	0.05	0.25	10.50	4.7	8	0.8
SG 296362	Soil	0.347		0.25	0.41	1519.0	42	0.2	0.18	0.02	0.50	28.18	13.5	5	1.3
SG 296363	Soil	0.031		0.24	1.05	627.5	30	0.4	0.42	0.02	1.11	26.50	15.8	17	1.8
SG 296364	Soil	0.022		0.38	1.00	439.2	42	0.3	0.37	0.04	0.99	17.65	13.5	17	1.2
SG 296365	Soil	0.038		0.24	0.54	346.4	32	0.2	0.31	0.01	0.71	22.40	8.1	8	1.2
SG 296366	Soil	0.037		0.34	1.14	480.2	27	0.4	0.38	0.01	1.20	32.36	14.1	16	1.9
SG 296367	Soil	0.027		0.26	0.71	481.3	38	0.3	0.32	0.03	1.24	23.89	10.4	11	1.8
SG 296368	Soil	0.070		0.28	0.72	566.5	32	0.3	0.35	0.01	1.29	35.18	12.5	11	1.8
SG 296369	Soil	0.053		0.28	0.81	265.1	31	0.2	0.37	<0.01	0.43	35.74	12.1	12	1.5
SG 296370	Soil	0.045		0.32	0.90	206.4	41	0.2	0.38	0.01	0.20	39.70	10.5	15	1.4
SG 296371	Soil	0.043		0.48	1.17	383.1	76	0.5	0.52	0.04	0.73	25.50	17.8	20	3.3
SG 296372	Soil	0.030		0.43	0.33	115.7	50	0.1	0.13	0.09	0.46	9.36	12.2	5	1.3
SG 296373	Soil	0.173		0.85	0.67	350.4	49	0.5	0.15	0.16	2.06	9.30	16.3	5	2.4
SG 296374	Soil	0.026		0.49	0.14	26.4	68	0.1	0.05	0.04	0.25	2.47	5.3	2	0.4
SG 296375	Soil	0.081		0.30	0.38	103.3	25	0.1	0.30	0.03	0.38	21.81	7.6	10	0.6
SG 296376	Soil	0.073		0.41	0.23	226.1	13	0.1	0.17	0.03	0.28	32.31	7.9	5	0.4
SG 296377	Soil	0.041		0.44	0.48	152.6	81	0.2	0.30	0.02	0.25	33.89	9.8	7	0.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SG 296378	Soil	0.041		0.36	0.64	203.7	55	0.2	0.34	0.02	0.72	35.20	7.4	7	1.1
SG 296379	Soil	0.023		0.26	0.65	296.3	85	0.2	0.34	<0.01	1.73	35.15	10.2	9	1.5
SG 296380	Soil	0.050		0.49	0.50	1026.9	26	0.2	0.25	0.06	1.35	16.62	9.1	4	0.7
SG 296381	Soil	0.555		0.70	0.32	2674.3	38	0.1	0.41	0.02	1.47	21.70	6.1	4	0.8
SG 296382	Soil	0.178		0.32	0.40	1126.3	20	0.3	0.33	0.03	1.23	22.02	14.4	4	0.6
SG 296383	Soil	0.327		0.70	0.37	1713.6	22	0.5	0.60	0.06	2.87	24.05	28.2	5	1.0
SG 296384	Soil	0.408		0.32	0.56	1452.9	42	0.3	0.26	0.04	0.46	16.72	10.7	5	0.9
SG 296385	Soil	0.452		0.66	0.56	2853.8	19	0.7	0.28	0.14	1.25	32.94	35.5	5	1.1
SG 296386	Soil	0.275		0.26	0.78	618.7	37	0.3	0.37	0.04	0.24	21.42	10.8	10	1.4
SG 296387	Soil	0.042		0.24	1.15	314.7	45	0.3	0.36	0.02	0.26	26.41	13.2	15	1.5
SG 296388	Soil	0.166		0.23	0.67	497.0	32	0.2	0.17	0.02	0.19	11.51	12.0	7	1.1
SG 296389	Soil	9.897	9.271	0.80	1.21	850.3	56	0.5	0.48	<0.01	0.21	45.56	18.6	18	2.1
SG 296390	Soil	0.019		0.20	1.47	49.2	38	0.3	0.47	<0.01	0.12	33.69	12.8	23	3.1
SG 296391	Soil	0.010		0.23	1.43	16.6	24	0.2	0.48	<0.01	0.09	25.98	9.3	25	2.1
SG 296392	Soil	0.010		0.19	0.78	3.8	36	0.1	0.26	0.01	0.09	16.81	4.3	14	1.8
SG 296393	Soil	0.010		0.17	2.49	19.7	22	0.3	0.52	0.03	0.19	38.31	16.3	37	4.8
SG 296394	Soil	0.024		0.13	2.62	45.2	22	0.4	0.53	<0.01	0.17	40.23	20.0	36	2.8
SG 296395	Soil	0.013		0.18	0.68	3.8	34	0.2	0.20	0.02	0.10	15.10	9.0	10	1.8
SG 296396	Soil	0.008		0.14	2.13	13.8	28	0.5	0.47	0.02	0.14	27.52	8.8	30	5.8
SG 296397	Soil	0.007		0.19	1.66	9.0	43	0.4	0.40	0.02	0.18	30.07	11.6	23	3.2
SG 296398	Soil	0.009		0.14	2.47	16.5	36	0.5	0.55	0.01	0.16	44.62	19.2	35	4.4
SG 296399	Soil	0.011		0.12	1.38	9.3	44	0.3	0.49	0.01	0.10	31.35	9.8	21	3.0
SG 296400	Soil	0.017		0.10	1.79	24.6	29	0.3	0.48	0.01	0.09	28.39	17.1	27	1.8
SG 296401	Soil	0.030		0.16	0.72	46.3	25	0.6	1.00	<0.01	0.13	26.50	38.5	14	2.8
SG 296402	Soil	0.057		0.11	1.57	17.6	30	0.3	0.46	0.02	0.11	35.72	13.8	24	2.1
SG 296403	Soil	0.015		0.14	1.74	24.1	35	0.4	0.50	0.01	0.10	45.17	22.0	28	2.2
SG 296404	Soil	0.044		0.15	1.38	104.9	39	0.4	0.60	0.01	0.12	35.53	24.9	21	2.5
SG 296405	Soil	0.017		0.17	1.52	34.9	41	0.4	0.44	0.02	0.10	36.89	17.9	24	5.4
SG 296406	Soil	0.011		0.36	2.33	24.5	40	0.5	0.56	0.03	0.18	26.78	41.1	37	7.6
SG 296407	Soil	0.010		0.82	2.14	35.2	30	0.4	0.48	0.01	0.12	33.91	17.1	31	4.6
SG 296408	Soil	0.072		0.22	1.42	22.0	34	0.3	0.33	0.04	0.09	33.06	13.6	21	4.3
SG 296409	Soil	0.012		0.26	1.48	37.6	26	0.3	0.28	0.02	0.12	25.04	10.9	21	1.7
SG 296410	Soil	0.026		0.25	1.34	27.7	32	0.2	0.36	0.02	0.07	25.23	12.2	21	2.3
SG 296411	Soil	0.021		0.18	1.99	27.0	31	0.3	0.41	0.02	0.09	42.14	14.2	33	2.2
SG 296412	Soil	0.014		0.20	1.82	22.9	31	0.3	0.41	0.02	0.09	38.21	17.6	32	1.9
SG 296413	Soil	0.353		0.36	1.96	440.9	32	0.5	0.38	0.02	0.21	38.99	22.7	28	1.7
SG 296414	Soil	0.024		0.28	2.39	46.9	24	0.4	0.43	0.02	0.14	41.88	17.0	35	1.3
SG 296415	Soil	0.042		0.24	2.14	112.1	32	0.5	0.53	0.01	0.09	54.26	15.9	31	2.4
SG 296416	Soil	0.015		0.27	1.50	82.5	45	0.4	0.46	0.01	0.18	52.92	11.1	20	3.1
SG 296417	Soil	0.025		0.24	1.84	87.0	44	0.5	0.42	0.01	0.10	61.30	13.9	25	2.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SG 296418	Soil	0.045		0.27	1.32	108.8	34	0.3	0.42	<0.01	0.11	40.86	10.8	19	1.1
SG 296419	Soil	0.015		0.28	1.83	65.9	56	0.5	0.57	0.06	0.16	34.32	18.5	28	2.6
SG 296420	Soil	0.019		0.25	2.20	128.6	52	0.5	0.58	0.03	0.18	38.42	23.6	32	2.2
SG 296421	Soil	0.014		0.35	1.77	72.0	43	0.5	0.48	0.03	0.27	38.00	22.2	25	3.1
SG 296422	Soil	0.013		0.34	1.86	41.4	43	0.4	0.45	0.02	0.21	45.27	16.3	27	1.8
SG 296423	Soil	0.025		0.23	2.41	56.2	33	0.7	0.56	0.03	0.18	52.01	27.8	36	1.4
SG 296424	Soil	0.013		0.20	2.39	60.4	35	0.6	0.54	0.02	0.16	54.20	22.7	37	1.6
SG 296425	Soil	0.034		0.48	2.62	51.6	26	0.5	0.51	0.02	0.12	48.73	24.1	37	1.4
SG 296426	Soil	0.024		0.37	2.50	71.3	41	0.6	0.52	0.03	0.26	46.82	23.7	32	1.5
SG 296427	Soil	0.088		0.47	1.08	255.7	61	0.4	0.52	0.03	0.44	27.35	13.3	20	1.9
SG 296428	Soil	0.021		0.25	2.18	51.4	31	0.5	0.48	0.01	0.13	37.13	21.7	33	1.6
SG 296429	Soil	0.021		0.24	2.28	46.5	31	0.5	0.49	0.01	0.12	40.53	20.7	33	1.7
SG 296430	Soil	0.017		0.21	2.32	45.5	37	0.5	0.41	0.02	0.10	49.37	21.1	33	1.4
SG 296431	Soil	0.023		0.22	2.11	54.9	51	0.5	0.38	0.02	0.13	44.59	23.3	29	1.5
SG 296432	Soil	0.014		0.22	2.18	43.0	46	0.3	0.40	0.01	0.09	44.87	17.1	32	1.8
SG 296433	Soil	0.018		0.21	2.53	53.9	57	0.5	0.45	0.01	0.16	46.73	18.7	35	2.0
SG 296434	Soil	0.023		0.25	2.61	72.8	56	0.5	0.47	0.02	0.18	49.57	23.2	35	1.8
SG 296435	Soil	0.029		0.23	1.76	79.6	39	0.3	0.44	0.03	0.12	47.05	14.3	29	2.3
SG 296436	Soil	0.018		0.23	1.76	143.6	38	0.3	0.42	0.02	0.20	29.06	14.8	27	1.6
SG 296437	Soil	0.017		0.42	1.92	46.0	35	0.5	0.41	0.01	0.21	21.80	14.4	25	2.0
SG 296438	Soil	0.010		0.24	1.76	59.5	24	0.3	0.41	0.01	0.11	28.57	19.0	28	2.6
SG 296439	Soil	0.053		0.32	1.59	71.4	36	0.4	0.46	0.02	0.24	39.97	20.4	24	4.2
SG 296440	Soil	0.290		0.48	1.90	382.2	52	0.6	0.40	0.03	0.30	45.77	25.9	29	1.7
SG 296441	Soil	0.042		0.21	2.27	163.0	33	0.5	0.43	0.03	0.13	40.16	21.1	29	1.5
SG 296442	Soil	0.012		0.21	1.57	11.7	42	0.4	0.35	0.04	0.10	30.74	14.5	25	1.9
SG 296443	Soil	0.073		0.60	1.57	75.7	38	0.4	0.44	0.02	0.14	37.18	15.7	28	1.8
SG 296444	Soil	0.013		0.36	2.08	28.7	27	0.4	0.48	0.02	0.13	39.87	12.8	31	3.3
SG 296445	Soil	0.117		0.33	1.87	31.9	28	0.4	0.63	0.01	0.12	30.36	20.6	26	2.4
SG 296446	Soil	0.012		0.34	1.77	52.4	41	0.4	0.50	0.01	0.25	23.98	20.0	27	2.4
SG 296447	Soil	0.061		0.34	1.44	119.8	65	0.3	0.45	0.02	0.29	20.46	16.5	24	1.8
SG 296448	Soil	0.006		0.29	1.35	28.5	24	0.2	0.40	<0.01	0.08	19.01	10.1	23	1.4
SG 296449	Soil	0.020		0.27	1.76	87.5	39	0.4	0.50	0.01	0.16	26.01	20.0	28	1.8
SG 296450	Soil	0.061		0.33	1.45	400.3	35	0.4	0.48	0.04	0.20	27.53	20.8	21	1.1
SG 296451	Soil	0.024		0.38	1.78	70.8	44	0.4	0.49	0.01	0.50	22.62	21.7	27	1.5
SG 296452	Soil	0.053		0.45	1.10	149.7	43	0.2	0.46	0.01	0.37	25.36	11.6	18	1.2
SG 296453	Soil	0.048		0.36	1.72	178.8	22	0.2	0.49	0.03	0.25	19.08	16.1	26	0.8
SG 296454	Soil	0.075		0.97	1.35	113.6	35	0.3	0.40	0.02	0.25	29.01	11.4	20	1.0
SG 296455	Soil	0.033		0.67	2.27	78.8	27	0.5	0.52	0.03	0.14	31.79	24.3	30	1.5
SG 296456	Soil	0.022		0.28	2.13	90.3	54	0.5	0.59	0.04	0.11	30.50	24.4	29	1.7
SG 296457	Soil	0.039		0.27	2.16	78.5	40	0.4	0.58	0.03	0.07	32.66	18.0	29	1.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SG 296458	Soil	0.015		0.36	1.96	48.0	31	0.4	0.49	0.03	0.22	26.11	18.2	27	1.6
SG 296459	Soil	0.015		0.35	1.94	86.7	27	0.4	0.61	0.01	0.15	32.00	15.3	29	2.0
SG 296460	Soil	0.029		0.37	2.15	78.7	39	0.5	0.46	0.02	0.12	32.16	21.0	32	1.8
SG 296461	Soil	0.015		0.74	1.98	33.3	33	0.4	0.55	0.03	0.29	24.70	18.6	30	3.9
SG 296462	Soil	0.155		0.37	2.21	49.5	39	0.5	0.48	0.03	0.09	22.94	20.1	30	1.5
SG 296463	Soil	0.021		0.37	1.94	44.5	34	0.3	0.41	0.01	0.12	35.84	18.6	27	2.4
SG 296464	Soil	0.042		0.36	2.10	43.8	32	0.4	0.44	0.01	0.12	30.50	20.2	30	2.1
SG 296465	Soil	0.041		0.34	2.35	46.1	49	0.4	0.49	0.04	0.11	29.43	22.2	32	2.1
SG 296466	Soil	0.023		0.26	2.17	50.3	27	0.3	0.52	0.03	0.14	33.04	20.0	33	1.8
SG 296467	Soil	0.019		0.57	2.36	48.0	65	1.0	0.72	0.38	0.44	38.47	35.7	27	4.0
SG 296468	Soil	0.042		0.19	2.44	48.5	42	0.4	0.51	0.03	0.14	29.78	20.3	34	1.5
SG 296469	Soil	0.032		0.22	1.92	108.1	42	0.5	0.54	0.02	0.11	25.58	19.6	26	1.8
SG 296470	Soil	0.428		0.34	2.00	572.2	37	0.5	0.54	0.09	0.15	22.74	18.6	28	1.3
SG 296471	Soil	0.223		0.34	1.84	910.9	44	0.4	0.52	0.02	0.72	18.00	18.9	25	1.1
SG 296472	Soil	3.213	2.532	0.55	0.99	2804.4	103	0.3	0.78	0.02	1.07	26.04	21.0	11	0.6
SG 296473	Soil	0.066		0.40	2.07	665.5	81	0.4	0.39	0.01	0.69	40.49	23.4	31	1.2
SG 296474	Soil	0.018		0.46	2.03	56.6	30	0.3	0.49	<0.01	0.21	26.70	14.2	33	1.2
SG 296475	Soil	0.019		0.29	2.45	34.2	32	0.4	0.50	0.01	0.13	28.91	21.9	36	1.3
SG 296476	Soil	0.008		0.33	1.84	44.6	38	0.5	0.52	0.02	0.19	30.14	17.2	30	3.5
SG 296477	Soil	0.029		0.32	1.47	35.7	32	0.4	0.43	0.02	0.23	28.85	18.3	24	1.8
SG 296478	Soil	0.006		0.33	1.43	36.3	30	0.3	0.43	0.02	0.14	20.46	12.1	23	1.6
SG 296479	Soil	0.015		0.31	1.36	27.5	32	0.2	0.36	0.01	0.08	21.94	9.8	19	1.3
SG 296480	Soil	0.063		0.52	1.07	87.0	27	0.3	0.54	<0.01	0.10	22.76	14.2	16	1.2
SG 296481	Soil	0.018		0.44	0.99	46.4	63	0.4	0.33	0.04	0.24	16.35	13.4	19	1.2
SG 296482	Soil	0.029		0.43	1.79	51.2	41	0.5	0.51	0.01	0.25	20.29	15.2	26	3.3
SG 296483	Soil	0.021		0.42	1.59	95.4	61	0.4	0.51	0.02	0.33	24.79	12.6	26	4.2
SG 296484	Soil	0.041		0.40	1.40	139.9	37	0.4	0.42	0.02	0.13	32.34	14.5	24	2.2
SG 296485	Soil	0.066		0.47	0.90	151.9	76	0.4	0.31	0.04	0.61	19.65	13.6	16	4.9
SG 296486	Soil	0.045		0.36	1.28	160.2	31	0.3	0.37	0.01	0.15	32.93	13.7	18	2.1
SG 296487	Soil	0.013		0.57	0.62	79.7	76	0.2	0.10	0.03	0.51	5.94	3.6	5	1.5
SG 296488	Soil	0.011		0.44	0.64	107.7	83	0.2	0.35	0.04	0.44	24.70	9.6	10	1.5
SG 296489	Soil	0.089		0.50	1.18	284.6	40	0.2	0.30	0.02	0.17	30.99	8.2	16	1.1
SG 296490	Soil	0.023		0.65	0.79	244.3	38	0.2	0.26	0.01	0.35	17.30	5.8	8	0.9
SG 296491	Soil	0.021		0.58	0.46	186.7	18	0.1	0.19	0.03	0.13	22.24	7.2	12	0.7
SG 296492	Soil	0.005		0.52	1.07	117.5	27	0.3	0.32	0.11	0.18	28.40	10.5	16	1.0
SG 296493	Soil	0.016		0.57	0.99	58.1	37	0.2	0.34	0.03	0.15	27.02	9.1	13	1.2
SG 296494	Soil	0.005		0.71	0.38	31.2	12	0.1	0.10	<0.01	0.05	20.64	2.2	4	0.7
SG 296495	Soil	0.019		0.49	0.44	53.9	26	0.1	0.42	0.02	0.11	33.99	7.3	10	1.1
SG 296496	Soil	<0.005		0.55	1.06	43.6	27	0.2	0.34	0.02	0.18	28.50	12.6	16	1.8
SG 296497	Soil	0.007		0.69	0.46	24.6	23	0.2	0.16	0.02	0.06	13.40	3.8	5	1.6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SG 296498	Soil	0.064		0.44	0.42	127.7	37	0.2	0.23	0.06	0.17	25.37	12.6	9	0.9
SG 296499	Soil	0.015		0.57	0.41	147.5	24	0.2	0.20	0.09	0.17	14.23	9.1	6	0.6
SG 296500	Soil	0.009		0.47	0.19	269.9	15	0.1	0.14	0.13	0.30	16.51	10.5	7	0.5
SG 296321	Soil	7.443	8.796	1.84	0.62	1242.7	47	0.2	0.29	0.03	0.42	24.00	9.0	5	1.4
SI 481051	Soil	0.014		0.50	0.41	402.8	19	0.1	0.18	0.36	0.37	12.33	6.2	6	1.7
SI 481052	Soil	0.033		0.38	0.24	121.4	34	0.3	0.46	0.01	0.09	46.68	15.0	14	0.9
SI 481053	Soil	0.014		0.37	0.75	137.9	35	0.3	0.28	0.07	0.54	32.28	17.2	12	0.8
SI 481054	Soil	0.055		0.38	0.22	445.4	20	0.1	0.14	0.09	0.12	22.04	5.3	6	0.6
SI 481055	Soil	0.029		0.41	1.21	396.8	30	0.3	0.37	0.02	0.05	36.41	9.8	18	2.0
SI 481056	Soil	0.010		0.52	1.23	43.8	42	0.5	0.49	0.04	0.27	36.35	14.0	16	3.9
SI 481057	Soil	0.046		0.45	0.95	154.4	34	0.4	0.39	0.03	0.08	26.39	13.8	18	1.3
SI 481058	Soil	0.033		0.78	0.59	68.3	39	0.5	0.53	0.10	0.13	30.66	17.6	12	2.5
SI 481059	Soil	<0.005		0.55	0.46	26.0	57	0.2	0.36	0.09	0.08	20.01	8.2	8	2.0
SI 481060	Soil	0.042		0.40	0.92	94.2	39	0.4	0.40	0.04	0.03	43.87	13.4	15	1.4
SI 481061	Soil	0.080		0.54	0.35	177.9	47	0.3	0.40	0.10	0.10	31.14	12.7	9	1.5
SI 481062	Soil	0.304		0.63	0.41	313.4	71	0.5	0.44	0.09	0.11	36.78	17.4	9	2.1
SI 481063	Soil	0.032		0.41	1.08	140.0	53	0.4	0.40	0.08	0.60	29.91	13.2	16	2.4
SI 481064	Soil	0.046		0.42	2.10	268.2	33	0.5	0.49	0.12	0.13	40.48	17.4	31	2.3
SI 481065	Soil	0.033		0.54	1.48	103.2	45	0.4	0.43	0.34	0.20	25.98	14.4	21	4.8
SI 481066	Soil	0.125		0.89	1.00	704.8	58	0.5	0.45	0.35	0.17	20.53	12.7	14	2.3
SI 481067	Soil	0.013		0.42	0.48	95.2	26	0.1	0.30	0.18	0.54	25.29	5.6	8	1.6
SI 481068	Soil	0.092		0.38	1.13	116.3	34	0.4	0.42	0.07	0.10	29.96	11.6	16	2.1
SM 268926	Soil	0.257		0.44	0.82	404.8	28	0.2	0.21	0.02	0.30	16.13	6.0	6	1.1
SM 268927	Soil	0.411		0.39	0.69	1023.3	28	0.4	0.50	0.08	1.20	21.01	17.5	10	1.6
SM 268928	Soil	0.030		0.42	0.95	368.3	30	0.3	0.34	0.02	0.31	17.81	13.3	12	1.5
SM 268929	Soil	0.024		0.44	1.87	114.4	27	0.6	0.43	0.03	0.36	16.44	21.2	28	3.7
SM 268930	Soil	0.018		0.42	1.27	67.3	28	0.3	0.31	0.04	0.16	15.62	13.8	18	2.2
SM 268931	Soil	0.068		0.49	2.14	127.9	22	0.5	0.39	0.02	0.15	49.92	23.5	30	3.3
SM 268932	Soil	0.029		0.52	1.80	82.0	35	0.5	0.39	0.03	0.31	22.67	14.7	27	2.6
SM 268933	Soil	0.015		1.04	1.16	373.9	44	0.6	0.62	0.07	0.34	35.72	35.8	16	3.4
SM 268934	Soil	0.269		0.57	0.97	601.0	29	0.3	0.26	0.03	0.63	25.35	12.0	12	1.7
SM 268935	Soil	3.364	3.722	0.77	0.62	1927.9	36	0.2	0.25	0.02	2.60	27.68	14.6	7	1.4
SM 268936	Soil	0.441		0.41	0.40	1294.4	31	0.2	0.18	0.02	0.40	29.97	15.9	4	1.8
SM 268937	Soil	0.019		0.48	1.01	223.1	55	0.3	0.29	0.04	0.28	11.84	12.0	15	1.7
SM 268938	Soil	0.022		0.49	1.86	41.3	22	0.6	0.41	0.02	0.16	19.10	19.0	28	3.3
SM 268939	Soil	0.025		0.46	1.35	67.4	35	0.3	0.33	0.02	0.17	20.41	12.1	21	2.4
SM 268940	Soil	0.079		0.44	1.26	102.8	34	0.2	0.28	0.01	0.16	21.26	11.3	21	2.5
SM 268941	Soil	0.036		0.49	1.38	97.3	39	0.3	0.30	0.03	0.23	27.06	13.8	21	4.2
SM 268942	Soil	0.046		0.59	1.59	57.7	54	0.4	0.38	0.07	0.34	25.14	15.6	25	4.7
SM 268943	Soil	0.034		0.55	1.71	77.2	41	0.5	0.40	0.02	0.24	24.08	14.2	26	4.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SM 268944	Soil	0.891	1.161	0.56	1.76	316.3	29	0.5	0.36	0.03	0.30	19.77	15.7	27	2.3
SM 268945	Soil	0.521		0.63	0.41	697.8	56	0.2	0.28	0.02	0.45	20.25	7.9	6	1.4
SM 268946	Soil	0.057		0.45	0.54	471.3	26	0.2	0.42	<0.01	0.11	24.19	9.5	10	1.1
SM 268947	Soil	0.247		0.46	0.42	747.7	30	0.2	0.25	0.02	0.17	25.15	8.9	6	1.1
SM 268948	Soil	1.588	0.998	0.54	0.41	1045.4	42	0.2	0.34	<0.01	0.18	26.86	9.2	7	1.3
SM 268949	Soil	2.037	1.762	0.56	0.50	1095.1	42	0.3	0.36	0.02	0.18	40.41	13.4	7	1.4
SM 268950	Soil	3.693	4.329	0.89	1.04	1001.7	35	0.3	0.43	<0.01	0.20	41.37	13.6	16	1.4
SM 268951	Soil	6.962	7.490	1.42	0.48	1648.2	30	0.4	0.29	0.01	3.13	47.88	11.2	8	2.4
SM 268952	Soil	0.120		0.53	1.74	49.1	35	0.5	0.38	0.02	0.18	16.16	17.1	27	2.9
SM 268953	Soil	0.009		0.56	0.82	28.0	27	0.3	0.20	0.05	0.15	9.70	12.2	11	1.9
SM 268954	Soil	0.014		0.46	1.68	39.4	36	0.3	0.36	0.04	0.26	21.03	13.3	24	3.1
SM 268955	Soil	0.027		0.52	1.85	35.7	27	0.4	0.34	0.06	0.16	24.97	15.1	26	4.6
SM 268956	Soil	3.956	4.977	1.02	0.51	1122.6	29	0.2	0.28	0.02	0.99	19.07	5.6	4	1.6
SM 268957	Soil	2.756	3.447	0.67	0.39	1558.4	41	0.3	0.44	0.02	0.57	22.56	13.3	6	1.5
SM 268958	Soil	1.591	1.394	0.61	0.32	618.7	36	0.2	0.31	0.01	0.15	21.89	11.0	6	1.0
SM 268959	Soil	2.785	1.888	0.68	0.43	641.2	35	0.3	0.37	0.02	0.15	20.75	9.1	5	1.0
SM 268960	Soil	1.061	1.705	0.75	0.33	943.3	17	0.3	0.43	<0.01	0.60	22.43	16.1	5	1.6
SM 268961	Soil	0.141		0.54	0.42	535.8	18	0.3	0.43	<0.01	0.13	25.77	16.1	11	1.9
SM 268962	Soil	0.112		0.56	1.03	455.4	23	0.3	0.44	<0.01	0.21	23.75	17.6	17	1.4
SM 268963	Soil	0.311		0.76	0.54	548.3	20	0.5	0.49	<0.01	0.42	17.50	22.4	10	1.7
SM 268964	Soil	0.573		0.59	0.23	638.3	19	0.1	0.50	<0.01	0.23	24.66	10.4	5	1.2
SM 268965	Soil	0.434		0.61	0.48	687.6	15	0.4	0.56	<0.01	0.37	26.42	28.7	8	1.8
SM 268966	Soil	0.206		0.69	0.40	431.3	21	0.4	0.72	<0.01	0.30	29.60	18.3	9	2.1
SM 268967	Soil	1.109	0.632	0.66	1.48	427.0	26	0.3	0.40	0.02	0.43	10.23	10.8	23	1.5
SM 268968	Soil	2.539	2.636	1.02	0.39	1731.9	45	0.5	0.67	<0.01	0.42	33.10	20.7	6	3.7
SM 268969	Soil	0.392		0.80	1.29	101.9	31	0.3	0.32	0.02	0.23	11.42	11.0	19	2.3
SM 268970	Soil	1.087	0.828	0.81	1.48	450.4	30	0.5	0.37	0.03	0.18	19.87	23.5	23	4.1
SM 268971	Soil	0.015		0.56	1.28	12.5	34	0.3	0.29	0.04	0.11	13.41	12.4	17	3.3
SM 268972	Soil	0.008		0.53	2.06	31.2	32	0.5	0.56	0.02	0.13	29.25	33.8	32	6.3
SM 268973	Soil	0.020		0.60	1.90	21.4	43	0.7	0.50	0.04	0.23	32.58	33.6	26	7.1
SM 268974	Soil	0.010		0.63	1.69	17.5	39	0.4	0.37	0.04	0.25	21.64	14.4	24	3.3
SM 268975	Soil	0.140		0.62	1.59	53.4	30	0.5	0.31	0.05	0.23	17.72	17.6	22	3.7
SM 268976	Soil	0.013		0.60	1.31	39.8	28	0.4	0.36	0.02	0.13	14.74	12.9	21	2.5
SM 268977	Soil	0.828	1.740	0.51	0.95	381.8	23	0.2	0.26	0.02	0.31	7.94	8.0	13	1.2
SM 268978	Soil	0.032		0.50	0.57	665.7	20	0.3	0.44	0.06	0.12	16.16	17.2	13	0.9
SM 268979	Soil	0.174		0.71	0.53	650.9	18	0.3	0.30	0.18	0.29	13.31	9.6	8	1.0
SM 268980	Soil	0.153		0.45	1.09	441.1	19	0.2	0.30	0.07	0.21	23.04	12.0	17	0.7
SM 268981	Soil	0.089		0.98	0.87	187.5	46	0.4	0.41	0.03	0.85	20.72	16.2	15	1.8
SM 268982	Soil	0.074		1.12	1.00	161.3	34	0.4	0.43	0.04	0.58	20.99	12.7	15	1.5
SM 268983	Soil	0.071		0.60	1.51	249.7	30	0.5	0.43	0.03	0.89	31.13	15.1	21	1.1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SM 268984	Soil	0.015		0.84	0.89	223.5	56	0.4	0.28	0.03	2.39	18.83	17.0	11	1.3
SM 268985	Soil	0.100		0.58	0.93	247.7	30	0.3	0.33	<0.01	0.53	20.40	10.9	13	0.9
SM 268986	Soil	0.243		0.88	1.04	566.4	30	0.3	0.34	0.02	0.72	20.29	18.0	14	0.9
SM 268987	Soil	0.270		1.17	0.81	650.4	38	0.2	0.37	0.04	0.84	20.15	13.1	11	0.7
SM 268988	Soil	0.168		0.77	0.32	335.6	18	0.2	0.38	<0.01	0.14	20.75	16.2	7	1.1
SM 268989	Soil	0.181		0.59	0.22	503.7	15	0.2	0.36	<0.01	0.22	20.46	10.9	6	0.8
SM 268990	Soil	1.869	1.345	0.94	0.55	652.4	32	0.3	0.37	0.01	0.36	14.59	10.9	10	1.2
SM 268991	Soil	0.442		0.50	1.10	256.0	22	0.3	0.37	<0.01	0.16	26.98	13.9	16	0.9
SM 268992	Soil	0.417		0.61	0.49	298.0	17	0.7	0.68	<0.01	0.19	20.34	20.8	13	2.0
SM 268993	Soil	0.519		0.53	0.41	344.7	18	0.7	0.54	<0.01	0.20	34.80	18.9	11	2.5
SM 268994	Soil	3.950	4.318	0.94	0.54	1639.6	35	0.4	0.71	<0.01	0.15	39.08	17.9	9	3.5
SM 268995	Soil	<0.005		0.50	2.23	11.4	20	0.3	0.36	0.07	0.10	22.72	15.9	33	2.4
SM 268996	Soil	<0.005		0.49	1.50	5.3	24	0.2	0.30	0.06	0.08	14.32	14.6	21	1.8
SM 268997	Soil	<0.005		0.55	1.92	20.2	31	0.4	0.41	0.03	0.18	18.40	13.3	27	3.2
SM 268998	Soil	<0.005		0.48	1.85	12.4	26	0.4	0.40	0.05	0.11	23.65	15.3	28	3.1
TG 296322	Soil	0.014		0.52	2.21	55.4	30	0.4	0.42	0.13	0.11	15.15	17.1	29	1.0
TG 296323	Soil	0.007		0.59	2.02	47.9	25	0.4	0.44	0.34	0.15	10.90	16.2	27	2.7
TG 296324	Soil	0.009		0.49	2.09	59.1	21	0.3	0.40	0.18	0.11	13.40	19.0	29	2.1
TG 296325	Soil	0.010		0.52	2.10	49.3	19	0.4	0.39	0.15	0.11	12.68	18.1	29	1.2
TG 296326	Soil	0.007		0.52	2.21	32.9	32	0.4	0.42	0.22	0.13	16.61	18.8	29	1.0
TG 296327	Soil	0.012		0.54	2.14	38.1	32	0.4	0.44	0.33	0.14	16.76	18.2	30	1.1
TG 296328	Soil	0.006		0.74	2.19	30.3	28	0.3	0.40	0.22	0.13	18.74	17.2	29	1.0
TG 296329	Soil	0.006		0.56	2.09	34.1	29	0.4	0.39	0.27	0.11	15.61	16.4	29	0.9
TG 296330	Soil	0.006		0.49	1.54	24.6	28	0.3	0.31	0.29	0.09	16.56	13.2	21	0.4
TG 296331	Soil	0.005		0.48	1.60	20.6	27	0.3	0.32	0.31	0.08	17.69	13.1	21	0.4
TG 296332	Soil	0.006		0.44	1.52	28.7	29	0.3	0.31	0.35	0.10	15.43	14.1	21	0.4
TG 296333	Soil	0.010		0.52	1.82	39.0	34	0.4	0.31	0.34	0.08	12.28	13.3	25	0.7
TG 296334	Soil	0.011		0.45	1.77	38.4	23	0.4	0.32	0.27	0.11	13.34	14.4	26	1.1
TG 296335	Soil	0.015		0.56	1.63	37.9	31	0.4	0.31	0.40	0.18	12.04	13.5	22	1.4
TG 296336	Soil	0.026		0.62	1.88	53.8	40	0.5	0.36	0.26	0.61	18.02	21.7	29	2.9
TG 296337	Soil	0.012		0.68	1.61	31.8	66	0.5	0.40	0.22	0.16	14.89	11.6	22	4.9
TI 480097	Soil	0.024		0.52	1.74	266.5	29	0.5	0.47	0.25	0.22	10.63	27.6	23	1.5
TI 480098	Soil	0.049		0.81	1.27	321.4	18	0.4	0.43	0.47	0.43	9.52	11.2	20	3.2
TI 480099	Soil	0.007		0.59	1.70	23.9	20	0.5	0.39	0.60	0.11	10.33	15.2	27	0.9
TI 480100	Soil	0.006		0.68	1.17	22.4	18	0.5	0.32	0.68	0.09	8.83	11.4	19	0.6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SG 296338	Soil	21.1	2.82	3.5	<0.05	<0.02	0.03	0.04	12.9	3.4	0.06	440	0.96	<0.01	0.4
SG 296339	Soil	49.0	4.33	1.7	<0.05	<0.02	0.03	0.06	23.6	2.6	0.03	298	0.62	<0.01	<0.05
SG 296340	Soil	8.9	1.00	1.6	<0.05	<0.02	<0.01	0.03	5.9	0.4	0.01	211	0.45	0.02	0.2
SG 296341	Soil	2.2	0.24	0.9	<0.05	<0.02	<0.01	0.02	0.6	0.2	0.01	33	0.21	0.03	<0.05
SG 296342	Soil	22.2	1.98	2.9	<0.05	<0.02	<0.01	0.04	9.5	0.6	0.03	2578	0.83	0.01	0.1
SG 296343	Soil	8.2	0.72	2.9	<0.05	<0.02	<0.01	0.02	2.3	0.7	0.02	1031	0.47	0.02	0.1
SG 296344	Soil	11.9	0.84	1.6	<0.05	<0.02	<0.01	0.03	3.7	0.7	0.02	98	0.33	0.02	0.2
SG 296345	Soil	13.6	1.34	2.3	<0.05	<0.02	<0.01	0.03	6.4	2.5	0.03	113	0.48	0.02	0.2
SG 296346	Soil	14.9	2.07	2.8	<0.05	<0.02	0.01	0.03	9.3	0.8	0.02	187	0.74	<0.01	0.2
SG 296347	Soil	20.5	1.60	2.8	<0.05	<0.02	0.01	0.04	7.6	1.0	0.03	392	0.84	0.01	0.3
SG 296348	Soil	9.4	0.74	2.1	<0.05	<0.02	<0.01	0.03	2.7	0.8	0.02	84	0.54	0.02	0.2
SG 296349	Soil	19.0	2.12	3.9	<0.05	<0.02	0.01	0.04	12.2	9.5	0.13	282	0.57	0.02	0.3
SG 296350	Soil	12.7	0.71	2.0	<0.05	<0.02	<0.01	0.03	3.5	0.8	0.02	55	0.36	0.02	0.1
SG 296351	Soil	26.6	2.83	4.0	<0.05	<0.02	0.04	0.05	12.3	8.8	0.13	495	0.80	<0.01	0.3
SG 296352	Soil	25.0	2.91	4.9	<0.05	<0.02	0.03	0.03	13.2	13.2	0.20	376	0.86	0.01	0.4
SG 296353	Soil	29.1	3.13	4.9	<0.05	<0.02	0.03	0.04	14.9	11.3	0.16	497	0.92	0.01	0.3
SG 296354	Soil	59.2	5.08	7.3	<0.05	<0.02	0.03	0.05	16.5	41.7	0.53	1406	1.00	0.01	0.3
SG 296355	Soil	61.6	4.05	4.4	<0.05	<0.02	0.03	0.03	9.6	28.3	0.35	1299	1.02	<0.01	0.2
SG 296356	Soil	26.9	3.54	5.2	<0.05	<0.02	0.06	0.03	13.1	10.9	0.15	385	0.99	<0.01	0.4
SG 296357	Soil	24.3	2.60	3.7	<0.05	<0.02	0.03	0.04	10.9	9.2	0.13	470	0.89	0.01	0.2
SG 296358	Soil	24.6	1.57	3.1	<0.05	<0.02	0.01	0.03	7.2	4.4	0.06	199	0.68	0.02	0.3
SG 296359	Soil	3.9	0.36	1.1	<0.05	<0.02	<0.01	0.02	1.8	0.3	0.01	206	0.33	0.02	0.1
SG 296360	Soil	8.9	0.82	2.4	<0.05	<0.02	<0.01	0.04	4.4	0.9	0.04	793	0.43	0.02	0.1
SG 296361	Soil	12.8	1.16	2.4	<0.05	<0.02	<0.01	0.03	5.5	4.9	0.07	212	0.69	0.02	0.2
SG 296362	Soil	14.2	3.83	2.6	<0.05	<0.02	0.03	0.04	14.8	0.7	0.02	386	0.76	<0.01	0.2
SG 296363	Soil	43.8	3.75	4.2	<0.05	<0.02	0.03	0.05	16.2	19.0	0.22	449	0.63	<0.01	0.2
SG 296364	Soil	36.7	4.34	5.8	<0.05	<0.02	0.03	0.04	9.7	11.8	0.17	749	0.80	<0.01	0.5
SG 296365	Soil	23.3	2.53	5.3	<0.05	<0.02	0.02	0.03	12.3	1.6	0.03	191	0.72	<0.01	0.2
SG 296366	Soil	27.0	3.83	5.0	<0.05	<0.02	0.04	0.04	17.0	19.0	0.20	545	0.91	<0.01	0.7
SG 296367	Soil	25.1	3.03	4.6	<0.05	<0.02	0.03	0.04	12.8	5.0	0.07	296	0.81	<0.01	0.4
SG 296368	Soil	29.6	3.46	4.9	<0.05	<0.02	0.03	0.04	20.0	9.8	0.11	383	0.75	<0.01	0.6
SG 296369	Soil	25.1	3.70	5.7	<0.05	<0.02	0.03	0.04	20.0	8.9	0.12	240	0.75	<0.01	0.5
SG 296370	Soil	21.6	3.35	5.1	<0.05	<0.02	0.02	0.04	22.5	14.5	0.19	517	0.64	<0.01	0.5
SG 296371	Soil	49.3	3.99	5.4	<0.05	<0.02	0.03	0.06	13.9	12.0	0.14	742	0.76	<0.01	0.4
SG 296372	Soil	13.4	0.79	2.0	<0.05	<0.02	<0.01	0.04	5.2	1.0	0.03	277	0.27	0.02	0.1
SG 296373	Soil	31.4	1.17	2.7	<0.05	<0.02	0.01	0.02	4.1	4.4	0.05	2061	0.39	0.01	0.3
SG 296374	Soil	4.0	0.35	1.2	<0.05	<0.02	<0.01	0.02	1.0	0.3	0.01	1299	0.20	0.02	0.1
SG 296375	Soil	24.9	1.83	2.8	<0.05	<0.02	<0.01	0.03	12.9	4.3	0.06	107	0.32	<0.01	0.1
SG 296376	Soil	14.7	2.03	1.5	<0.05	<0.02	0.06	0.02	16.4	0.3	0.01	144	0.43	<0.01	0.1
SG 296377	Soil	15.9	2.31	3.8	<0.05	<0.02	0.01	0.02	18.1	1.6	0.02	974	0.67	<0.01	0.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SG 296378	Soil	17.1	2.43	4.4	<0.05	<0.02	0.03	0.03	19.7	4.3	0.04	331	0.55	<0.01	0.4
SG 296379	Soil	19.7	2.82	4.2	<0.05	<0.02	0.02	0.04	19.2	5.3	0.08	1167	0.71	<0.01	0.3
SG 296380	Soil	22.3	2.93	2.2	<0.05	<0.02	0.02	0.03	8.4	0.7	0.03	288	0.58	<0.01	0.2
SG 296381	Soil	17.4	3.64	2.5	<0.05	<0.02	0.07	0.02	11.1	0.5	0.01	150	0.57	<0.01	0.2
SG 296382	Soil	20.5	3.56	1.9	<0.05	<0.02	0.05	0.03	11.3	1.1	0.03	598	0.50	<0.01	0.1
SG 296383	Soil	51.4	4.77	1.0	<0.05	<0.02	0.08	0.02	13.0	4.0	0.05	1266	0.79	<0.01	<0.05
SG 296384	Soil	18.6	2.58	1.9	<0.05	<0.02	0.02	0.03	8.3	3.2	0.06	465	0.50	<0.01	0.1
SG 296385	Soil	19.9	5.58	1.2	<0.05	<0.02	0.04	0.02	16.1	6.1	0.10	1126	0.60	<0.01	0.1
SG 296386	Soil	22.4	3.05	3.4	<0.05	<0.02	0.02	0.04	11.1	11.5	0.13	390	0.79	<0.01	0.4
SG 296387	Soil	28.3	3.37	4.8	<0.05	<0.02	0.02	0.05	14.2	16.9	0.20	617	0.94	<0.01	0.5
SG 296388	Soil	17.5	1.99	2.9	<0.05	<0.02	0.02	0.02	6.0	7.4	0.11	291	0.48	0.02	0.1
SG 296389	Soil	56.3	4.80	3.6	<0.05	<0.02	0.04	0.03	27.2	34.0	0.41	442	0.66	<0.01	0.2
SG 296390	Soil	36.7	4.18	6.0	<0.05	<0.02	0.03	0.03	19.2	29.3	0.37	500	0.72	<0.01	0.3
SG 296391	Soil	31.1	4.80	5.3	<0.05	<0.02	0.02	0.01	14.6	30.8	0.44	385	0.69	<0.01	0.3
SG 296392	Soil	10.3	1.66	4.1	<0.05	<0.02	0.01	0.02	8.0	10.2	0.14	425	0.47	<0.01	0.1
SG 296393	Soil	63.2	5.22	8.0	<0.05	0.05	0.04	0.02	20.7	73.4	0.96	585	0.62	<0.01	0.1
SG 296394	Soil	42.2	5.45	7.9	<0.05	<0.02	0.03	0.02	21.0	89.9	1.04	504	0.53	<0.01	0.1
SG 296395	Soil	18.0	1.58	3.5	<0.05	<0.02	<0.01	0.02	8.1	12.9	0.18	711	0.47	0.01	0.2
SG 296396	Soil	39.7	4.76	7.4	<0.05	0.03	0.03	0.03	13.7	59.4	0.78	349	0.59	<0.01	0.2
SG 296397	Soil	33.3	4.12	7.7	<0.05	0.04	0.03	0.03	16.3	30.8	0.41	798	0.67	0.01	0.4
SG 296398	Soil	57.2	5.80	8.5	<0.05	0.07	0.03	0.04	25.8	67.8	0.87	599	0.73	<0.01	0.3
SG 296399	Soil	33.2	3.62	7.3	<0.05	<0.02	0.03	0.04	17.5	19.3	0.24	465	0.88	0.01	0.4
SG 296400	Soil	37.6	4.86	5.6	<0.05	0.02	0.02	0.02	15.8	46.8	0.66	416	0.45	<0.01	0.1
SG 296401	Soil	62.7	4.98	2.6	<0.05	<0.02	0.04	0.02	15.4	16.2	0.26	776	0.59	<0.01	0.1
SG 296402	Soil	31.7	4.06	6.2	<0.05	<0.02	0.02	0.03	20.2	42.9	0.53	400	0.75	<0.01	0.4
SG 296403	Soil	36.5	4.57	6.5	<0.05	<0.02	0.03	0.03	25.8	50.2	0.72	453	0.69	<0.01	0.4
SG 296404	Soil	48.4	4.03	5.0	<0.05	<0.02	0.03	0.03	19.4	35.8	0.47	841	0.77	<0.01	0.3
SG 296405	Soil	43.6	4.02	7.4	<0.05	<0.02	0.02	0.04	19.9	35.3	0.48	612	0.87	0.01	0.4
SG 296406	Soil	69.2	5.62	9.2	<0.05	<0.02	0.03	0.03	11.2	69.6	0.86	810	0.88	<0.01	0.5
SG 296407	Soil	46.7	5.16	8.3	<0.05	<0.02	0.03	0.04	16.8	55.2	0.83	427	0.74	0.01	0.4
SG 296408	Soil	31.8	3.33	6.4	<0.05	<0.02	0.02	0.03	16.9	28.6	0.43	342	0.74	0.02	0.4
SG 296409	Soil	29.0	3.44	5.2	<0.05	<0.02	0.02	0.02	13.0	36.2	0.52	375	0.48	0.01	0.3
SG 296410	Soil	26.4	3.80	5.7	<0.05	<0.02	0.02	0.03	13.5	30.7	0.48	491	0.66	0.01	0.3
SG 296411	Soil	35.3	4.93	7.6	<0.05	<0.02	0.03	0.03	22.3	47.9	0.76	544	0.79	<0.01	0.4
SG 296412	Soil	32.3	4.75	7.5	<0.05	<0.02	0.02	0.04	20.0	40.0	0.61	803	0.79	<0.01	0.5
SG 296413	Soil	43.4	5.24	6.5	<0.05	<0.02	0.03	0.02	20.0	53.0	0.74	967	0.61	0.01	0.2
SG 296414	Soil	41.9	5.44	7.0	<0.05	0.03	0.03	0.03	21.7	61.6	0.94	599	0.66	<0.01	0.3
SG 296415	Soil	38.2	5.60	6.7	<0.05	<0.02	0.03	0.03	31.9	65.1	0.81	418	0.62	<0.01	0.3
SG 296416	Soil	27.9	4.10	7.7	<0.05	<0.02	0.02	0.04	31.6	39.8	0.45	407	0.61	0.01	0.6
SG 296417	Soil	38.4	4.34	7.2	<0.05	<0.02	0.02	0.04	34.3	53.7	0.67	393	0.56	<0.01	0.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SG 296418	Soil	25.1	3.52	7.5	<0.05	<0.02	0.02	0.02	23.0	30.8	0.35	447	0.53	<0.01	0.4
SG 296419	Soil	47.5	4.48	7.8	<0.05	<0.02	0.03	0.03	19.2	48.7	0.56	860	0.70	<0.01	0.3
SG 296420	Soil	40.1	5.50	8.2	<0.05	<0.02	0.04	0.03	21.2	66.4	0.82	1011	0.72	<0.01	0.4
SG 296421	Soil	57.3	4.34	7.8	<0.05	0.05	0.03	0.04	20.7	47.9	0.55	781	0.70	<0.01	0.3
SG 296422	Soil	40.3	4.52	7.6	<0.05	<0.02	0.03	0.03	25.1	58.2	0.68	505	0.73	<0.01	0.3
SG 296423	Soil	55.7	5.55	8.2	<0.05	<0.02	0.03	0.03	28.6	87.2	1.00	687	0.61	<0.01	0.1
SG 296424	Soil	50.2	5.75	8.2	<0.05	<0.02	0.03	0.03	29.9	76.4	0.95	701	0.56	<0.01	0.2
SG 296425	Soil	47.2	5.91	8.0	<0.05	<0.02	0.03	0.03	26.9	87.1	1.09	574	0.58	<0.01	0.1
SG 296426	Soil	53.7	5.45	7.8	<0.05	<0.02	0.03	0.03	24.1	74.3	0.94	649	0.60	0.01	0.2
SG 296427	Soil	42.2	3.69	5.9	<0.05	<0.02	0.04	0.03	14.5	19.5	0.24	1088	0.71	<0.01	0.2
SG 296428	Soil	49.3	5.05	6.9	<0.05	<0.02	0.03	0.02	20.0	71.1	0.89	653	0.53	<0.01	0.1
SG 296429	Soil	51.0	5.26	7.9	<0.05	<0.02	0.03	0.02	21.9	72.2	0.91	560	0.57	<0.01	0.1
SG 296430	Soil	50.2	5.06	8.3	<0.05	<0.02	0.03	0.02	26.9	70.9	0.94	571	0.65	<0.01	0.1
SG 296431	Soil	51.1	4.34	7.9	<0.05	<0.02	0.03	0.03	24.1	67.7	0.84	522	0.59	0.01	0.2
SG 296432	Soil	38.6	4.65	8.6	<0.05	<0.02	0.03	0.03	24.2	63.7	0.84	447	0.69	<0.01	0.2
SG 296433	Soil	44.8	5.28	9.2	<0.05	<0.02	0.04	0.04	25.1	66.8	0.89	484	0.87	0.01	0.5
SG 296434	Soil	52.6	5.45	9.2	<0.05	<0.02	0.03	0.04	26.3	75.6	1.01	538	0.83	<0.01	0.2
SG 296435	Soil	33.9	4.16	9.1	<0.05	<0.02	0.03	0.04	25.3	38.5	0.60	550	1.15	<0.01	0.3
SG 296436	Soil	36.8	4.32	7.9	<0.05	<0.02	0.03	0.04	14.8	43.3	0.59	547	0.87	<0.01	0.4
SG 296437	Soil	43.6	4.20	7.4	<0.05	<0.02	0.03	0.03	11.0	31.1	0.43	549	0.81	<0.01	0.5
SG 296438	Soil	45.3	4.73	7.7	<0.05	<0.02	0.03	0.02	14.9	50.6	0.71	479	0.74	<0.01	0.3
SG 296439	Soil	45.1	4.19	7.9	<0.05	<0.02	0.03	0.03	20.8	40.5	0.52	480	0.99	<0.01	0.4
SG 296440	Soil	45.0	5.09	6.4	<0.05	<0.02	0.03	0.03	24.9	54.5	0.83	782	0.81	<0.01	0.4
SG 296441	Soil	45.8	5.02	6.9	<0.05	<0.02	0.03	0.02	21.9	71.2	0.99	721	0.68	<0.01	0.3
SG 296442	Soil	21.0	3.08	7.0	<0.05	<0.02	0.02	0.04	16.4	35.4	0.43	706	0.98	0.01	0.5
SG 296443	Soil	42.8	5.27	5.9	<0.05	<0.02	0.03	0.03	20.8	45.8	0.60	772	0.75	<0.01	0.3
SG 296444	Soil	42.5	5.03	7.3	<0.05	<0.02	0.03	0.04	22.0	61.4	0.82	489	0.74	<0.01	0.4
SG 296445	Soil	44.0	4.45	5.5	<0.05	<0.02	0.02	0.02	17.1	61.0	0.84	649	0.69	<0.01	0.2
SG 296446	Soil	45.3	5.19	6.1	<0.05	0.03	0.03	0.02	13.1	46.1	0.70	926	0.62	<0.01	0.2
SG 296447	Soil	34.3	4.75	6.7	<0.05	<0.02	0.02	0.03	10.9	25.1	0.38	1810	0.72	<0.01	0.3
SG 296448	Soil	26.6	4.26	5.7	<0.05	<0.02	0.02	0.02	10.0	25.9	0.44	570	0.61	<0.01	0.2
SG 296449	Soil	43.6	5.19	7.7	<0.05	<0.02	0.03	0.02	14.0	43.0	0.60	1350	0.77	<0.01	0.2
SG 296450	Soil	39.4	4.36	4.6	<0.05	<0.02	0.03	0.02	14.5	46.0	0.58	792	0.69	<0.01	0.1
SG 296451	Soil	37.1	4.29	6.5	<0.05	<0.02	0.03	0.02	11.7	43.1	0.58	1279	0.66	<0.01	0.2
SG 296452	Soil	27.4	3.98	7.0	<0.05	<0.02	0.02	0.02	14.1	21.6	0.29	856	0.67	<0.01	0.2
SG 296453	Soil	34.8	4.96	5.8	<0.05	<0.02	0.02	0.02	10.2	56.3	0.79	567	0.65	<0.01	0.1
SG 296454	Soil	25.9	3.94	5.6	<0.05	<0.02	0.02	0.02	16.5	33.7	0.49	431	0.70	<0.01	0.2
SG 296455	Soil	47.5	5.33	6.8	<0.05	<0.02	0.03	0.02	17.2	66.1	0.93	806	0.58	<0.01	0.1
SG 296456	Soil	55.5	5.20	6.7	<0.05	<0.02	0.03	0.02	16.0	65.3	0.85	692	0.60	<0.01	0.1
SG 296457	Soil	50.6	4.99	6.3	<0.05	<0.02	0.03	0.02	17.7	63.3	0.86	578	0.52	<0.01	0.1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SG 296458	Soil	33.1	4.30	6.3	<0.05	<0.02	0.02	0.02	13.9	50.4	0.68	725	0.50	<0.01	0.1
SG 296459	Soil	42.8	4.75	6.4	<0.05	<0.02	0.03	0.02	17.4	58.7	0.73	549	0.62	<0.01	0.1
SG 296460	Soil	50.0	4.86	6.3	<0.05	<0.02	0.03	0.02	17.9	67.0	0.88	512	0.55	<0.01	0.1
SG 296461	Soil	32.1	4.97	8.0	<0.05	<0.02	0.03	0.04	13.8	62.1	0.73	506	0.68	<0.01	0.3
SG 296462	Soil	55.0	5.12	6.5	<0.05	<0.02	0.03	0.02	12.2	66.0	0.91	533	0.47	<0.01	0.1
SG 296463	Soil	30.0	4.56	6.8	<0.05	<0.02	0.03	0.03	19.7	47.8	0.67	522	0.48	<0.01	0.2
SG 296464	Soil	38.0	4.80	7.0	<0.05	<0.02	0.03	0.02	17.1	61.3	0.80	574	0.48	<0.01	0.1
SG 296465	Soil	43.1	5.39	8.0	<0.05	<0.02	0.03	0.02	15.7	64.4	0.92	1079	0.53	<0.01	0.1
SG 296466	Soil	32.3	5.00	8.6	<0.05	<0.02	0.03	0.02	18.3	68.6	0.87	609	0.60	<0.01	0.2
SG 296467	Soil	100.4	6.71	6.3	<0.05	<0.02	0.07	0.02	18.0	58.8	0.81	3861	1.12	<0.01	0.1
SG 296468	Soil	42.2	5.44	8.0	<0.05	<0.02	0.03	0.02	15.8	70.0	1.02	481	0.48	<0.01	0.1
SG 296469	Soil	47.1	4.52	6.3	<0.05	<0.02	0.03	0.02	13.4	52.0	0.68	539	0.54	<0.01	0.1
SG 296470	Soil	43.4	5.03	6.7	<0.05	<0.02	0.04	0.02	11.8	55.7	0.75	517	0.58	<0.01	0.1
SG 296471	Soil	41.1	4.78	6.5	<0.05	<0.02	0.04	0.02	8.9	47.5	0.65	823	0.62	<0.01	0.2
SG 296472	Soil	53.3	5.09	3.3	<0.05	<0.02	0.05	0.02	13.3	13.0	0.19	799	0.76	<0.01	0.2
SG 296473	Soil	36.8	6.02	7.6	<0.05	<0.02	0.04	0.04	22.2	45.2	0.67	1039	0.85	<0.01	0.4
SG 296474	Soil	40.1	5.06	7.0	<0.05	<0.02	0.03	0.02	14.1	53.4	0.74	486	0.62	<0.01	0.3
SG 296475	Soil	41.8	5.34	7.2	<0.05	<0.02	0.03	0.02	15.4	73.4	0.99	526	0.41	<0.01	0.1
SG 296476	Soil	44.8	5.55	7.2	<0.05	<0.02	0.03	0.03	16.2	37.5	0.57	855	0.85	<0.01	0.3
SG 296477	Soil	28.9	5.02	5.0	<0.05	<0.02	0.04	0.03	13.9	28.6	0.47	988	0.61	<0.01	0.3
SG 296478	Soil	33.6	4.55	4.7	<0.05	<0.02	0.02	0.02	11.0	33.6	0.52	585	0.53	<0.01	0.2
SG 296479	Soil	27.8	3.44	4.9	<0.05	<0.02	0.02	0.02	12.0	25.6	0.39	484	0.61	<0.01	0.3
SG 296480	Soil	37.6	4.71	3.3	<0.05	<0.02	0.03	0.02	13.0	20.6	0.28	263	0.86	<0.01	0.3
SG 296481	Soil	34.2	4.24	3.7	<0.05	<0.02	0.03	0.03	8.5	10.3	0.17	708	1.07	0.01	0.3
SG 296482	Soil	53.7	5.41	6.5	<0.05	<0.02	0.03	0.03	11.4	33.1	0.43	508	0.90	0.01	0.4
SG 296483	Soil	43.2	5.11	7.5	<0.05	<0.02	0.03	0.04	14.1	25.7	0.35	657	0.82	0.01	0.8
SG 296484	Soil	38.1	4.59	3.9	<0.05	<0.02	0.03	0.03	19.0	24.6	0.30	373	0.60	<0.01	0.5
SG 296485	Soil	25.4	3.01	3.8	<0.05	<0.02	0.02	0.05	10.5	5.9	0.11	1655	0.54	0.01	0.2
SG 296486	Soil	36.3	3.84	3.8	<0.05	<0.02	0.02	0.03	19.0	29.3	0.36	395	0.51	0.01	0.2
SG 296487	Soil	13.3	0.81	2.9	<0.05	<0.02	<0.01	0.04	2.9	1.5	0.02	3594	0.27	0.02	0.1
SG 296488	Soil	23.1	2.78	3.9	<0.05	<0.02	0.02	0.04	13.8	5.8	0.09	2224	0.60	0.01	0.2
SG 296489	Soil	21.0	3.90	4.0	<0.05	<0.02	0.02	0.04	17.8	19.6	0.25	286	0.57	0.01	0.3
SG 296490	Soil	13.7	2.15	3.6	<0.05	<0.02	0.02	0.03	9.1	6.2	0.10	586	0.46	0.01	0.2
SG 296491	Soil	12.5	2.10	1.7	<0.05	<0.02	0.01	0.02	11.5	7.4	0.13	402	0.38	<0.01	0.1
SG 296492	Soil	21.0	3.97	3.8	<0.05	<0.02	0.02	0.04	14.4	21.9	0.30	487	0.64	0.01	0.2
SG 296493	Soil	17.6	3.56	4.1	<0.05	<0.02	0.02	0.04	14.1	11.5	0.14	445	0.65	0.01	0.5
SG 296494	Soil	7.5	1.27	0.8	<0.05	<0.02	<0.01	0.01	9.7	1.1	0.03	123	0.24	<0.01	0.1
SG 296495	Soil	24.9	3.27	4.1	<0.05	<0.02	0.01	0.03	20.0	1.3	0.05	233	0.48	0.01	0.2
SG 296496	Soil	28.1	3.64	4.2	<0.05	<0.02	0.02	0.03	16.7	23.5	0.30	324	0.43	0.01	0.2
SG 296497	Soil	11.6	1.19	2.3	<0.05	<0.02	<0.01	0.03	7.3	3.3	0.04	104	0.28	0.02	0.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SG 296498	Soil	17.7	2.25	1.6	<0.05	<0.02	0.01	0.03	13.7	3.5	0.08	891	0.45	0.01	0.1
SG 296499	Soil	13.4	1.59	1.6	<0.05	<0.02	<0.01	0.03	7.7	3.1	0.05	332	0.32	0.01	0.1
SG 296500	Soil	10.3	2.20	0.6	<0.05	<0.02	<0.01	0.04	7.6	1.2	0.04	505	0.35	<0.01	<0.05
SG 296321	Soil	20.5	2.52	2.1	<0.05	<0.02	0.02	0.04	12.6	2.1	0.03	566	0.54	0.01	0.2
SI 481051	Soil	11.6	1.49	1.7	<0.05	<0.02	<0.01	0.04	6.3	4.2	0.08	338	0.30	0.02	0.1
SI 481052	Soil	42.7	3.38	1.5	<0.05	<0.02	0.02	0.03	30.0	1.7	0.02	285	0.58	<0.01	<0.05
SI 481053	Soil	24.2	3.90	2.7	<0.05	<0.02	0.02	0.03	17.1	13.6	0.15	665	0.57	<0.01	0.2
SI 481054	Soil	9.3	1.50	0.8	<0.05	<0.02	<0.01	0.02	11.7	2.5	0.04	281	0.23	<0.01	<0.05
SI 481055	Soil	26.2	3.80	3.5	<0.05	<0.02	0.02	0.03	21.9	34.5	0.43	286	0.39	<0.01	0.1
SI 481056	Soil	43.9	3.44	3.9	<0.05	<0.02	0.02	0.05	20.9	26.2	0.26	591	0.65	0.01	0.4
SI 481057	Soil	34.5	3.54	2.6	<0.05	<0.02	0.02	0.03	15.7	20.3	0.26	308	0.55	<0.01	0.2
SI 481058	Soil	51.3	4.70	1.7	<0.05	<0.02	0.03	0.04	18.2	11.1	0.14	401	1.09	<0.01	<0.05
SI 481059	Soil	24.7	2.51	2.0	<0.05	<0.02	0.01	0.03	12.2	6.2	0.08	245	0.66	<0.01	0.1
SI 481060	Soil	33.1	3.55	2.5	<0.05	<0.02	0.02	0.03	27.2	23.7	0.33	241	0.36	<0.01	<0.05
SI 481061	Soil	34.7	3.31	1.4	<0.05	<0.02	0.02	0.04	18.9	4.9	0.08	305	0.73	0.01	<0.05
SI 481062	Soil	44.6	4.06	1.2	<0.05	<0.02	0.03	0.05	22.9	5.4	0.09	477	0.61	0.01	<0.05
SI 481063	Soil	36.0	3.40	3.2	<0.05	<0.02	0.02	0.04	17.1	30.2	0.35	395	0.45	0.01	0.1
SI 481064	Soil	46.9	5.48	5.2	<0.05	<0.02	0.03	0.04	23.7	73.1	0.85	747	0.35	0.01	0.1
SI 481065	Soil	35.1	4.06	3.9	<0.05	<0.02	0.03	0.04	15.0	40.0	0.51	622	0.49	0.01	0.3
SI 481066	Soil	36.9	3.42	2.7	<0.05	<0.02	0.07	0.04	11.1	20.0	0.24	473	0.44	0.01	0.1
SI 481067	Soil	16.9	1.77	3.4	<0.05	<0.02	0.02	0.03	14.3	8.1	0.12	175	0.40	0.01	0.2
SI 481068	Soil	27.4	3.67	3.1	<0.05	<0.02	0.03	0.03	17.5	29.9	0.38	247	0.34	<0.01	0.1
SM 268926	Soil	15.7	1.85	3.5	<0.05	<0.02	0.02	0.03	8.4	3.7	0.05	303	0.55	0.02	0.3
SM 268927	Soil	28.6	3.68	2.6	<0.05	<0.02	0.03	0.03	10.3	6.6	0.10	564	0.61	<0.01	0.1
SM 268928	Soil	24.1	3.08	4.7	<0.05	<0.02	0.03	0.03	9.0	10.0	0.15	436	0.77	0.01	0.5
SM 268929	Soil	67.6	5.13	6.3	<0.05	0.02	0.03	0.03	9.4	45.9	0.62	746	0.78	<0.01	0.2
SM 268930	Soil	41.9	3.24	4.4	<0.05	<0.02	0.02	0.03	9.0	32.0	0.41	550	0.56	0.01	0.2
SM 268931	Soil	69.4	5.25	6.0	<0.05	<0.02	0.03	0.03	30.1	67.7	0.83	607	0.52	<0.01	0.1
SM 268932	Soil	49.3	5.00	6.4	<0.05	0.04	0.03	0.03	12.3	37.8	0.51	823	0.60	<0.01	0.3
SM 268933	Soil	76.4	5.50	3.8	<0.05	<0.02	0.05	0.03	21.0	24.8	0.34	1701	0.93	0.01	0.1
SM 268934	Soil	23.3	3.19	4.0	<0.05	<0.02	0.07	0.03	12.9	10.7	0.18	698	0.71	0.01	0.3
SM 268935	Soil	24.1	3.30	2.4	<0.05	<0.02	0.03	0.03	13.9	4.9	0.09	385	0.58	<0.01	0.2
SM 268936	Soil	27.3	2.95	1.7	<0.05	<0.02	0.02	0.02	15.6	2.0	0.04	556	0.51	<0.01	0.1
SM 268937	Soil	36.1	3.47	4.9	<0.05	<0.02	0.02	0.03	6.6	10.9	0.17	1046	0.61	0.01	0.2
SM 268938	Soil	62.7	5.42	5.9	<0.05	<0.02	0.02	0.02	10.2	45.3	0.62	485	0.62	<0.01	0.2
SM 268939	Soil	39.7	3.92	6.0	<0.05	<0.02	0.02	0.03	11.4	27.6	0.37	608	0.55	0.01	0.3
SM 268940	Soil	32.5	3.64	5.4	<0.05	<0.02	0.02	0.03	12.2	23.5	0.32	782	0.44	<0.01	0.2
SM 268941	Soil	38.1	4.19	6.3	<0.05	<0.02	0.02	0.04	15.5	31.3	0.41	671	0.48	0.01	0.2
SM 268942	Soil	46.2	4.59	6.4	<0.05	<0.02	0.03	0.04	13.8	30.9	0.43	750	0.64	0.01	0.4
SM 268943	Soil	53.5	5.25	6.6	<0.05	0.04	0.03	0.03	13.3	33.3	0.43	784	0.68	0.01	0.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SM 268944	Soil	48.9	5.29	6.4	<0.05	<0.02	0.02	0.03	10.9	30.7	0.44	749	0.63	<0.01	0.4
SM 268945	Soil	22.1	2.11	2.9	<0.05	<0.02	0.02	0.03	10.6	1.1	0.02	566	0.65	0.01	0.1
SM 268946	Soil	22.6	2.87	3.1	<0.05	<0.02	0.02	0.03	13.2	5.0	0.09	555	0.63	0.01	0.1
SM 268947	Soil	22.1	3.01	2.4	<0.05	<0.02	0.02	0.03	13.4	1.8	0.04	462	0.62	<0.01	0.1
SM 268948	Soil	25.9	2.96	2.1	<0.05	<0.02	0.02	0.03	14.3	1.7	0.03	311	0.56	<0.01	0.1
SM 268949	Soil	32.1	3.59	2.4	<0.05	<0.02	0.03	0.05	23.8	2.8	0.04	373	0.62	<0.01	0.2
SM 268950	Soil	36.9	4.38	3.7	<0.05	<0.02	0.03	0.04	24.4	22.1	0.29	425	0.58	<0.01	0.1
SM 268951	Soil	28.0	3.11	1.5	<0.05	<0.02	0.03	0.04	26.3	6.9	0.08	206	0.48	<0.01	<0.05
SM 268952	Soil	49.1	4.90	5.9	<0.05	0.04	0.02	0.03	8.8	36.8	0.48	1154	0.60	<0.01	0.2
SM 268953	Soil	27.4	2.13	2.9	<0.05	<0.02	0.02	0.03	5.4	14.8	0.19	364	0.43	0.02	0.1
SM 268954	Soil	39.2	4.32	5.9	<0.05	<0.02	0.02	0.03	11.9	42.8	0.56	653	0.45	0.01	0.3
SM 268955	Soil	52.2	4.40	5.8	<0.05	<0.02	0.03	0.03	13.8	47.1	0.58	697	0.40	0.01	0.2
SM 268956	Soil	15.4	1.98	1.6	<0.05	<0.02	0.02	0.04	10.1	1.8	0.02	184	0.47	0.01	0.1
SM 268957	Soil	33.7	3.99	1.7	<0.05	<0.02	0.03	0.04	12.8	3.1	0.04	433	0.97	<0.01	0.1
SM 268958	Soil	29.1	2.75	1.8	<0.05	<0.02	0.02	0.03	12.5	0.8	0.02	343	0.52	<0.01	0.1
SM 268959	Soil	24.0	2.44	1.8	<0.05	<0.02	0.02	0.03	11.6	1.6	0.03	214	0.46	<0.01	0.1
SM 268960	Soil	28.2	3.55	0.9	<0.05	<0.02	0.03	0.02	11.8	1.4	0.02	361	0.52	<0.01	0.1
SM 268961	Soil	33.6	3.75	1.7	<0.05	<0.02	0.02	0.02	15.2	3.8	0.06	393	0.48	<0.01	<0.05
SM 268962	Soil	39.2	4.36	2.8	<0.05	<0.02	0.02	0.02	13.7	21.8	0.31	419	0.48	<0.01	0.1
SM 268963	Soil	54.8	5.23	1.4	<0.05	<0.02	0.04	0.02	9.8	4.3	0.06	627	0.71	<0.01	0.1
SM 268964	Soil	17.0	2.57	1.1	<0.05	<0.02	0.02	0.02	13.1	1.1	0.02	212	0.52	<0.01	<0.05
SM 268965	Soil	49.2	5.00	1.0	<0.05	<0.02	0.03	0.02	15.0	3.3	0.03	707	0.90	<0.01	<0.05
SM 268966	Soil	45.4	4.33	1.5	<0.05	<0.02	0.03	0.03	17.9	2.8	0.03	458	1.35	<0.01	0.1
SM 268967	Soil	31.4	4.49	5.0	<0.05	<0.02	0.02	0.03	5.4	27.5	0.42	552	0.49	<0.01	0.2
SM 268968	Soil	58.4	4.54	1.2	<0.05	<0.02	0.04	0.07	19.6	5.4	0.07	235	0.72	<0.01	<0.05
SM 268969	Soil	33.2	4.08	5.2	<0.05	<0.02	0.02	0.02	6.2	22.6	0.35	812	0.45	0.01	0.2
SM 268970	Soil	56.1	4.56	3.9	<0.05	<0.02	0.03	0.03	10.7	30.9	0.48	1214	0.55	<0.01	0.1
SM 268971	Soil	37.3	3.20	4.0	<0.05	<0.02	0.02	0.03	7.4	28.9	0.44	633	0.42	0.01	0.2
SM 268972	Soil	76.9	5.49	6.7	<0.05	<0.02	0.04	0.03	16.3	51.4	0.76	1453	0.82	<0.01	0.2
SM 268973	Soil	74.3	4.64	6.0	<0.05	<0.02	0.04	0.03	17.7	50.0	0.69	1351	0.70	0.01	0.2
SM 268974	Soil	43.8	4.07	5.9	<0.05	<0.02	0.02	0.03	11.8	39.5	0.55	824	0.44	0.01	0.2
SM 268975	Soil	48.1	3.69	4.8	<0.05	<0.02	0.02	0.03	9.8	32.8	0.46	768	0.42	0.01	0.2
SM 268976	Soil	46.1	4.14	5.0	<0.05	<0.02	0.02	0.03	7.8	22.6	0.33	570	0.58	<0.01	0.2
SM 268977	Soil	21.7	2.64	3.2	<0.05	<0.02	0.01	0.03	4.3	15.7	0.24	372	0.37	<0.01	0.1
SM 268978	Soil	42.3	3.78	2.0	<0.05	<0.02	0.02	0.01	9.2	14.8	0.22	776	0.80	<0.01	<0.05
SM 268979	Soil	23.9	2.26	1.7	<0.05	<0.02	0.02	0.03	7.2	9.2	0.12	282	0.29	0.01	0.1
SM 268980	Soil	23.5	3.68	2.8	<0.05	<0.02	0.02	0.02	13.1	28.4	0.41	309	0.30	<0.01	0.1
SM 268981	Soil	35.4	3.95	3.4	<0.05	<0.02	0.03	0.04	11.6	12.8	0.20	1026	0.55	<0.01	0.2
SM 268982	Soil	33.0	4.29	3.6	<0.05	<0.02	0.08	0.04	11.4	15.0	0.23	362	0.52	<0.01	0.2
SM 268983	Soil	33.2	4.96	3.5	<0.05	<0.02	0.02	0.04	17.3	35.7	0.53	559	0.40	<0.01	0.1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
SM 268984	Soil	18.3	3.40	3.2	<0.05	<0.02	0.02	0.04	9.8	12.2	0.14	2033	0.45	<0.01	0.2
SM 268985	Soil	22.6	3.34	3.0	<0.05	<0.02	0.02	0.02	10.9	17.8	0.26	364	0.42	<0.01	0.1
SM 268986	Soil	18.7	3.94	3.2	<0.05	<0.02	0.04	0.02	10.5	19.0	0.24	892	0.79	<0.01	0.4
SM 268987	Soil	21.1	3.54	3.4	<0.05	<0.02	0.03	0.03	10.5	12.2	0.16	473	0.65	<0.01	0.3
SM 268988	Soil	28.3	3.32	1.7	<0.05	<0.02	0.02	0.02	11.7	1.8	0.03	480	0.64	<0.01	0.1
SM 268989	Soil	22.8	2.66	1.3	<0.05	<0.02	0.02	0.02	10.6	1.3	0.02	288	0.51	<0.01	0.1
SM 268990	Soil	30.6	3.22	2.9	<0.05	<0.02	0.02	0.02	8.0	2.8	0.05	536	0.62	<0.01	0.1
SM 268991	Soil	32.0	3.69	2.7	<0.05	<0.02	0.02	0.03	15.4	27.8	0.35	353	0.42	<0.01	0.1
SM 268992	Soil	56.2	4.76	1.6	<0.05	<0.02	0.03	0.02	12.3	6.8	0.09	403	0.91	<0.01	<0.05
SM 268993	Soil	49.2	3.28	1.6	<0.05	<0.02	0.02	0.03	21.6	4.9	0.05	337	0.53	<0.01	<0.05
SM 268994	Soil	44.1	4.24	1.8	<0.05	<0.02	0.04	0.04	23.1	9.3	0.12	315	0.92	<0.01	<0.05
SM 268995	Soil	38.1	4.76	5.9	<0.05	<0.02	0.02	0.03	12.9	71.8	0.97	572	0.47	0.01	0.1
SM 268996	Soil	28.0	2.88	4.2	<0.05	<0.02	0.02	0.03	8.3	44.7	0.56	800	0.34	0.01	0.1
SM 268997	Soil	43.7	4.81	6.0	<0.05	<0.02	0.03	0.02	10.3	49.4	0.66	885	0.51	<0.01	0.2
SM 268998	Soil	56.5	4.27	5.8	<0.05	<0.02	0.03	0.02	13.3	53.0	0.70	544	0.68	<0.01	0.1
TG 296322	Soil	36.1	4.83	5.3	<0.05	<0.02	0.02	0.02	8.2	69.7	1.04	739	0.52	<0.01	<0.05
TG 296323	Soil	41.7	4.36	5.1	<0.05	<0.02	0.02	0.03	5.9	63.8	0.97	722	0.47	<0.01	<0.05
TG 296324	Soil	40.6	4.78	5.5	<0.05	<0.02	0.02	0.02	7.3	71.6	1.03	768	0.49	<0.01	<0.05
TG 296325	Soil	34.9	4.69	5.6	<0.05	<0.02	0.02	0.02	7.0	69.8	1.05	770	0.48	<0.01	<0.05
TG 296326	Soil	35.1	5.07	6.0	<0.05	<0.02	0.02	0.02	8.8	68.8	0.99	765	0.57	<0.01	0.1
TG 296327	Soil	39.8	4.77	5.9	<0.05	<0.02	0.02	0.02	9.0	71.5	0.98	678	0.45	<0.01	0.1
TG 296328	Soil	34.1	4.86	6.0	<0.05	<0.02	0.02	0.02	10.1	75.8	1.02	546	0.37	<0.01	<0.05
TG 296329	Soil	34.1	4.64	5.5	<0.05	<0.02	0.02	0.02	8.4	72.1	0.96	535	0.35	<0.01	<0.05
TG 296330	Soil	25.9	3.65	4.0	<0.05	<0.02	0.02	0.02	8.7	50.0	0.71	479	0.28	<0.01	<0.05
TG 296331	Soil	25.0	3.58	4.0	<0.05	<0.02	0.02	0.03	9.0	48.9	0.72	386	0.25	<0.01	<0.05
TG 296332	Soil	27.2	3.46	3.9	<0.05	<0.02	0.02	0.02	8.1	48.3	0.65	581	0.33	<0.01	<0.05
TG 296333	Soil	31.4	3.75	4.1	<0.05	<0.02	0.02	0.03	6.5	45.7	0.78	480	0.29	<0.01	0.1
TG 296334	Soil	31.8	3.92	4.3	<0.05	<0.02	0.02	0.02	6.9	51.2	0.84	412	0.29	<0.01	0.1
TG 296335	Soil	34.6	3.51	3.6	<0.05	<0.02	0.02	0.03	6.7	42.9	0.72	382	0.26	<0.01	0.1
TG 296336	Soil	45.2	4.07	4.7	<0.05	<0.02	0.02	0.03	9.5	53.5	0.81	827	0.54	<0.01	0.1
TG 296337	Soil	29.1	3.63	4.3	<0.05	<0.02	0.02	0.04	8.4	40.7	0.55	424	0.44	<0.01	0.2
TI 480097	Soil	52.9	4.50	4.3	<0.05	<0.02	0.02	0.02	5.9	49.1	0.70	654	0.68	<0.01	0.1
TI 480098	Soil	38.7	3.20	2.9	<0.05	<0.02	0.03	0.04	5.2	32.0	0.51	526	0.48	<0.01	<0.05
TI 480099	Soil	49.7	3.57	3.9	<0.05	<0.02	0.02	0.03	6.1	44.7	0.77	602	0.62	<0.01	0.1
TI 480100	Soil	34.4	2.67	2.7	<0.05	<0.02	0.02	0.04	4.7	26.1	0.45	324	0.61	<0.01	0.1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SG 296338	Soil	18.0	620	57.5	8.1	<0.01	0.05	1.05	0.5	0.7	0.3	6.7	<0.01	0.08	0
SG 296339	Soil	44.2	275	33.3	5.7	<0.01	0.03	1.48	2.5	0.5	0.5	23.8	<0.01	0.16	7
SG 296340	Soil	7.5	430	12.2	3.5	<0.01	0.02	1.11	0.2	0.4	0.2	7.6	<0.01	0.04	<0.2
SG 296341	Soil	1.2	284	2.3	0.5	<0.01	0.02	<0.05	0.1	0.3	<0.2	6.0	<0.01	<0.01	<0.2
SG 296342	Soil	17.3	865	29.0	6.4	<0.01	0.03	0.10	0.2	0.5	0.2	12.4	<0.01	0.04	<0.2
SG 296343	Soil	5.3	372	7.7	2.6	<0.01	0.03	<0.05	0.2	0.2	<0.2	19.7	<0.01	<0.01	<0.2
SG 296344	Soil	6.9	401	7.7	3.3	<0.01	0.04	0.28	0.2	<0.2	<0.2	7.3	<0.01	0.02	<0.2
SG 296345	Soil	11.2	463	16.2	3.8	<0.01	0.03	1.21	0.2	0.4	<0.2	10.4	<0.01	0.03	<0.2
SG 296346	Soil	18.0	424	25.2	5.8	<0.01	0.03	0.86	0.3	0.3	0.2	5.8	<0.01	0.04	<0.2
SG 296347	Soil	15.6	630	18.3	5.8	<0.01	0.05	0.18	0.3	0.5	0.2	10.1	<0.01	0.03	<0.2
SG 296348	Soil	5.2	515	8.4	3.3	<0.01	0.04	<0.05	0.2	0.6	<0.2	5.3	<0.01	0.01	<0.2
SG 296349	Soil	14.5	443	28.3	6.5	<0.01	0.03	0.10	0.4	0.4	0.2	6.9	<0.01	0.04	0
SG 296350	Soil	5.5	375	9.1	2.6	<0.01	0.03	<0.05	0.2	0.3	<0.2	8.5	<0.01	0.02	<0.2
SG 296351	Soil	20.5	717	74.9	6.8	<0.01	0.06	0.59	0.4	0.6	0.3	6.5	<0.01	0.05	0
SG 296352	Soil	19.4	559	41.1	6.0	<0.01	0.04	0.20	0.6	0.7	0.3	6.6	<0.01	0.08	0
SG 296353	Soil	21.8	706	66.1	7.4	<0.01	0.05	0.27	0.5	0.7	0.4	8.4	<0.01	0.08	0
SG 296354	Soil	39.4	1102	58.5	8.0	<0.01	0.04	<0.05	0.8	0.7	0.3	7.8	<0.01	0.11	1
SG 296355	Soil	42.1	630	80.5	3.7	<0.01	0.03	0.21	0.9	0.5	<0.2	5.5	<0.01	0.07	2
SG 296356	Soil	22.3	701	78.2	4.8	<0.01	0.05	<0.05	0.5	1.0	0.4	6.5	<0.01	0.06	0
SG 296357	Soil	21.5	742	54.4	7.0	<0.01	0.04	0.08	0.3	0.8	<0.2	16.9	<0.01	0.08	<0.2
SG 296358	Soil	11.8	643	25.8	4.0	<0.01	0.04	0.11	0.2	0.6	<0.2	5.1	<0.01	0.02	<0.2
SG 296359	Soil	2.7	265	4.3	1.8	<0.01	0.02	<0.05	0.1	0.3	<0.2	5.6	<0.01	0.03	<0.2
SG 296360	Soil	6.3	637	10.7	8.1	<0.01	0.04	0.14	0.2	0.5	<0.2	13.8	<0.01	0.02	<0.2
SG 296361	Soil	12.2	562	12.3	3.0	<0.01	0.05	0.19	0.2	0.5	<0.2	10.2	<0.01	0.02	<0.2
SG 296362	Soil	30.8	535	23.8	5.9	<0.01	0.03	0.98	0.6	0.4	0.2	4.8	<0.01	0.10	1
SG 296363	Soil	36.8	887	32.9	7.1	<0.01	0.02	<0.05	0.5	0.4	<0.2	4.5	<0.01	0.12	1
SG 296364	Soil	25.1	938	47.5	7.3	<0.01	0.06	<0.05	0.4	0.8	0.3	8.7	<0.01	0.12	0
SG 296365	Soil	15.1	813	26.2	5.1	<0.01	0.03	0.10	0.3	0.5	0.3	6.3	<0.01	0.08	<0.2
SG 296366	Soil	25.1	491	93.5	7.4	<0.01	0.03	0.20	0.9	0.6	0.4	7.2	<0.01	0.08	1
SG 296367	Soil	20.7	737	61.0	7.4	<0.01	0.06	0.31	0.4	0.7	0.3	7.8	<0.01	0.06	0
SG 296368	Soil	22.8	430	66.4	8.9	<0.01	0.02	<0.05	1.3	0.4	0.4	4.7	<0.01	0.09	7
SG 296369	Soil	21.4	548	55.4	6.2	<0.01	0.02	<0.05	0.8	0.6	0.3	4.6	<0.01	0.11	1
SG 296370	Soil	18.7	684	32.5	8.6	<0.01	0.01	<0.05	0.6	0.6	0.3	7.6	<0.01	0.08	1
SG 296371	Soil	31.6	1127	40.5	11.3	<0.01	0.04	0.31	0.4	0.5	0.3	15.9	<0.01	0.14	0
SG 296372	Soil	5.9	529	7.4	6.2	<0.01	0.03	0.25	0.3	0.5	<0.2	13.4	<0.01	0.02	<0.2
SG 296373	Soil	22.0	876	17.4	3.0	<0.01	0.06	0.18	0.2	0.6	<0.2	21.1	<0.01	0.01	<0.2
SG 296374	Soil	1.9	494	6.7	1.8	<0.01	0.03	<0.05	<0.1	<0.2	<0.2	7.1	<0.01	<0.01	<0.2
SG 296375	Soil	15.6	410	16.0	3.6	<0.01	0.01	<0.05	0.3	<0.2	<0.2	9.9	<0.01	0.10	0
SG 296376	Soil	18.6	329	27.1	2.4	<0.01	0.01	0.84	0.3	0.3	<0.2	3.1	<0.01	0.02	0
SG 296377	Soil	16.1	514	27.5	5.3	<0.01	0.01	0.23	0.4	0.4	0.3	7.6	<0.01	0.08	0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SG 296378	Soil	13.8	489	99.9	6.6	<0.01	0.01	0.20	0.6	0.3	0.4	7.4	<0.01	0.06	1
SG 296379	Soil	17.3	525	28.3	8.5	<0.01	0.02	0.14	0.5	0.7	0.4	6.3	<0.01	0.08	0
SG 296380	Soil	23.7	1084	97.4	4.2	<0.01	0.06	1.57	0.4	0.4	<0.2	17.4	<0.01	0.06	0
SG 296381	Soil	18.0	601	431.6	2.7	<0.01	0.04	7.03	0.3	0.3	0.5	34.9	<0.01	0.26	0
SG 296382	Soil	24.2	600	217.6	3.8	<0.01	0.02	2.19	0.7	0.5	0.2	14.1	<0.01	0.08	2
SG 296383	Soil	38.6	483	144.2	2.0	<0.01	0.02	4.85	1.9	0.5	<0.2	18.7	<0.01	0.35	6
SG 296384	Soil	20.1	714	39.5	4.4	<0.01	0.05	1.85	0.4	0.5	<0.2	12.9	<0.01	0.10	0
SG 296385	Soil	57.2	698	109.4	2.7	<0.01	0.01	3.31	1.7	0.5	<0.2	15.1	<0.01	0.07	9
SG 296386	Soil	23.1	672	46.2	5.9	<0.01	0.05	0.89	0.6	0.6	0.2	8.9	<0.01	0.11	1
SG 296387	Soil	22.6	1340	43.1	10.4	<0.01	0.06	0.79	0.7	0.8	0.3	7.4	<0.01	0.06	1
SG 296388	Soil	12.0	902	19.4	3.7	<0.01	0.05	0.49	0.3	0.4	<0.2	5.1	<0.01	0.04	<0.2
SG 296389	Soil	45.6	320	78.4	4.5	<0.01	0.02	2.26	1.7	0.6	<0.2	14.7	<0.01	0.13	6
SG 296390	Soil	28.3	761	35.7	6.0	<0.01	0.03	0.49	0.7	0.5	<0.2	4.8	<0.01	0.08	1
SG 296391	Soil	25.2	695	17.6	3.0	<0.01	0.02	1.20	0.6	0.4	<0.2	2.1	<0.01	0.13	1
SG 296392	Soil	7.2	777	10.1	4.1	<0.01	0.04	<0.05	0.2	0.5	<0.2	4.5	<0.01	0.03	<0.2
SG 296393	Soil	45.4	757	36.0	3.9	<0.01	0.04	<0.05	1.3	0.4	<0.2	3.5	<0.01	0.20	4
SG 296394	Soil	52.6	298	37.8	3.9	<0.01	0.01	<0.05	2.0	0.4	<0.2	3.6	<0.01	0.11	5
SG 296395	Soil	10.2	724	10.6	3.0	<0.01	0.06	<0.05	0.2	0.5	<0.2	3.7	<0.01	0.07	<0.2
SG 296396	Soil	33.9	853	30.7	5.8	<0.01	0.04	<0.05	1.0	0.4	<0.2	5.7	<0.01	0.04	2
SG 296397	Soil	21.8	1308	21.4	6.4	<0.01	0.06	<0.05	0.7	0.8	0.2	5.0	<0.01	0.10	1
SG 296398	Soil	43.3	986	29.1	5.9	<0.01	0.03	<0.05	1.2	0.5	<0.2	4.6	<0.01	0.11	2
SG 296399	Soil	18.1	1373	22.0	7.8	<0.01	0.07	0.12	0.4	0.9	0.4	7.0	<0.01	0.08	<0.2
SG 296400	Soil	37.9	754	23.2	3.7	<0.01	0.02	<0.05	0.9	0.4	<0.2	5.5	<0.01	0.10	2
SG 296401	Soil	51.1	461	44.3	3.0	<0.01	<0.01	5.63	3.3	0.6	<0.2	4.9	<0.01	0.23	2
SG 296402	Soil	33.1	724	22.2	4.8	<0.01	0.03	<0.05	0.8	0.6	0.2	6.1	<0.01	0.07	1
SG 296403	Soil	41.6	524	22.6	5.1	<0.01	0.01	0.16	1.4	0.6	0.3	8.6	<0.01	0.12	1
SG 296404	Soil	37.2	729	38.5	5.5	<0.01	0.03	0.64	1.0	0.8	<0.2	13.1	<0.01	0.11	1
SG 296405	Soil	29.3	1076	28.6	6.6	<0.01	0.04	0.24	0.7	0.7	0.3	8.1	<0.01	0.10	1
SG 296406	Soil	53.6	886	47.3	6.7	<0.01	0.04	0.72	1.6	0.6	0.2	7.4	<0.01	0.12	2
SG 296407	Soil	45.1	634	22.1	5.0	<0.01	0.03	0.23	1.1	0.5	0.3	7.7	<0.01	0.15	1
SG 296408	Soil	23.6	625	20.0	5.9	<0.01	0.04	0.25	0.7	0.6	0.3	8.9	<0.01	0.06	0
SG 296409	Soil	28.6	491	21.3	3.7	<0.01	0.03	0.20	0.7	0.4	<0.2	4.5	<0.01	0.06	1
SG 296410	Soil	24.2	718	23.4	4.7	<0.01	0.04	0.20	0.5	0.4	0.3	5.5	<0.01	0.06	0
SG 296411	Soil	36.2	646	26.9	5.4	<0.01	0.02	<0.05	1.1	0.5	0.3	6.3	<0.01	0.05	1
SG 296412	Soil	31.0	1030	21.4	6.4	<0.01	0.04	<0.05	0.7	0.4	0.3	6.6	<0.01	0.09	1
SG 296413	Soil	48.7	679	47.7	3.7	<0.01	0.03	1.09	1.3	0.5	<0.2	15.9	<0.01	0.09	1
SG 296414	Soil	46.7	717	22.9	5.4	<0.01	0.02	<0.05	1.2	0.4	<0.2	6.1	<0.01	0.11	2
SG 296415	Soil	42.2	489	25.9	5.0	<0.01	<0.01	<0.05	2.1	<0.2	0.3	5.8	<0.01	0.12	9
SG 296416	Soil	26.6	594	27.3	9.8	<0.01	0.01	<0.05	1.4	0.2	0.3	7.5	<0.01	0.09	4
SG 296417	Soil	36.0	447	25.7	7.3	<0.01	<0.01	0.07	1.2	0.4	0.2	7.8	<0.01	0.10	2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SG 296418	Soil	22.4	522	19.5	3.8	<0.01	<0.01	0.30	1.1	0.5	0.2	4.7	<0.01	0.09	3
SG 296419	Soil	36.2	811	24.7	7.5	<0.01	0.01	0.20	1.0	0.4	0.2	11.0	<0.01	0.12	1
SG 296420	Soil	45.8	617	31.8	6.0	<0.01	0.01	0.35	1.3	0.5	0.2	8.4	<0.01	0.16	1
SG 296421	Soil	37.7	1352	37.8	7.8	<0.01	0.03	0.17	1.1	0.4	<0.2	11.0	<0.01	0.14	2
SG 296422	Soil	40.5	890	29.8	5.0	<0.01	0.01	0.08	1.0	0.5	<0.2	9.6	<0.01	0.07	1
SG 296423	Soil	62.7	517	40.7	3.6	<0.01	0.01	0.16	2.6	0.5	<0.2	8.9	<0.01	0.09	6
SG 296424	Soil	53.9	699	32.5	4.9	<0.01	<0.01	<0.05	2.5	0.5	0.2	8.0	<0.01	0.11	7
SG 296425	Soil	59.6	523	31.6	4.2	<0.01	<0.01	<0.05	2.1	0.5	<0.2	7.0	<0.01	0.10	5
SG 296426	Soil	57.3	597	32.8	4.3	<0.01	0.02	<0.05	1.7	0.4	<0.2	8.0	<0.01	0.12	2
SG 296427	Soil	25.5	1016	48.8	5.9	<0.01	0.03	1.04	0.6	0.6	<0.2	9.2	<0.01	0.10	0
SG 296428	Soil	51.9	483	25.8	4.0	<0.01	0.01	0.14	1.7	0.3	<0.2	8.0	<0.01	0.10	2
SG 296429	Soil	55.6	599	25.9	4.8	<0.01	0.02	0.18	1.6	0.3	<0.2	8.1	<0.01	0.12	2
SG 296430	Soil	54.0	638	23.3	4.8	<0.01	0.01	0.13	1.5	0.6	<0.2	8.0	<0.01	0.09	2
SG 296431	Soil	53.9	557	23.9	5.9	<0.01	0.02	<0.05	1.3	0.5	<0.2	9.0	<0.01	0.10	1
SG 296432	Soil	46.7	605	23.9	6.7	<0.01	0.02	<0.05	1.3	0.5	0.2	9.9	<0.01	0.10	1
SG 296433	Soil	49.2	624	30.2	7.4	<0.01	0.02	<0.05	1.3	0.7	0.3	10.6	<0.01	0.08	1
SG 296434	Soil	58.0	492	34.8	6.2	<0.01	0.01	0.09	2.0	0.7	0.2	9.9	<0.01	0.11	3
SG 296435	Soil	35.1	839	22.6	10.6	<0.01	0.03	0.38	0.7	0.7	0.5	9.8	<0.01	0.08	0
SG 296436	Soil	34.7	725	41.3	6.5	<0.01	0.03	0.36	0.7	0.5	0.3	7.8	<0.01	0.10	0
SG 296437	Soil	27.8	1014	50.6	6.5	<0.01	0.07	0.22	0.4	1.0	0.3	6.2	<0.01	0.08	<0.2
SG 296438	Soil	44.1	737	34.5	4.4	<0.01	0.03	0.51	1.1	0.6	<0.2	6.2	<0.01	0.04	1
SG 296439	Soil	41.4	649	47.0	6.6	<0.01	0.02	0.73	1.0	0.7	0.3	9.6	<0.01	0.10	0
SG 296440	Soil	52.2	549	38.7	5.3	<0.01	0.02	1.21	2.7	0.6	0.3	16.4	<0.01	0.11	3
SG 296441	Soil	52.6	463	29.7	4.1	<0.01	0.02	0.27	1.6	<0.2	<0.2	9.7	<0.01	0.07	2
SG 296442	Soil	21.8	776	22.5	7.8	<0.01	0.04	<0.05	0.6	0.8	0.5	8.9	<0.01	<0.01	<0.2
SG 296443	Soil	39.8	871	27.9	5.0	<0.01	0.03	0.25	1.1	0.5	<0.2	12.6	<0.01	0.09	1
SG 296444	Soil	40.8	925	33.6	5.3	<0.01	0.04	0.41	0.8	0.5	0.2	10.9	<0.01	0.07	1
SG 296445	Soil	39.1	578	26.1	3.1	<0.01	0.02	0.45	0.5	0.5	<0.2	5.9	<0.01	0.10	1
SG 296446	Soil	35.2	1013	32.0	3.3	<0.01	0.04	0.35	0.7	0.5	<0.2	6.3	<0.01	0.13	1
SG 296447	Soil	23.4	1303	31.0	6.2	<0.01	0.05	0.18	0.3	0.7	<0.2	7.0	<0.01	0.10	0
SG 296448	Soil	21.2	904	17.4	4.5	<0.01	0.03	<0.05	0.3	0.7	<0.2	4.3	<0.01	0.04	0
SG 296449	Soil	35.8	1203	35.7	4.9	<0.01	0.03	0.07	0.6	0.6	<0.2	6.3	<0.01	0.11	1
SG 296450	Soil	39.0	615	37.1	3.0	<0.01	0.02	1.72	1.0	0.5	<0.2	9.0	<0.01	0.07	1
SG 296451	Soil	34.4	1087	32.6	4.4	<0.01	0.02	0.07	0.6	0.6	<0.2	5.9	<0.01	0.08	1
SG 296452	Soil	21.2	1017	26.4	6.1	<0.01	0.02	0.21	0.2	0.7	<0.2	6.2	<0.01	0.12	<0.2
SG 296453	Soil	39.8	495	30.4	3.3	<0.01	0.01	0.61	0.8	0.3	<0.2	5.4	<0.01	0.10	1
SG 296454	Soil	27.8	599	22.3	4.2	<0.01	0.02	1.25	0.4	0.5	<0.2	6.9	<0.01	0.13	1
SG 296455	Soil	45.8	526	31.0	3.4	<0.01	0.01	0.40	1.2	0.3	<0.2	5.3	<0.01	0.16	2
SG 296456	Soil	47.8	553	32.9	3.4	<0.01	0.01	0.49	1.2	0.4	<0.2	7.2	<0.01	0.16	1
SG 296457	Soil	45.6	349	30.3	3.0	<0.01	<0.01	0.32	2.2	0.4	<0.2	5.1	<0.01	0.18	5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SG 296458	Soil	33.4	719	25.3	4.1	<0.01	0.01	<0.05	0.7	0.4	<0.2	5.7	<0.01	0.09	1
SG 296459	Soil	34.5	530	29.2	4.0	<0.01	<0.01	0.39	1.2	0.4	<0.2	3.4	<0.01	0.17	2
SG 296460	Soil	44.4	363	34.0	3.3	<0.01	<0.01	0.21	1.6	0.5	<0.2	4.5	<0.01	0.12	4
SG 296461	Soil	37.8	630	28.2	9.7	<0.01	0.01	0.15	1.3	0.5	0.2	6.3	<0.01	0.11	4
SG 296462	Soil	47.5	382	26.1	3.0	<0.01	<0.01	0.15	2.0	0.5	<0.2	6.4	<0.01	0.12	6
SG 296463	Soil	35.4	539	21.5	6.0	<0.01	<0.01	<0.05	1.6	0.4	0.3	5.5	<0.01	0.07	6
SG 296464	Soil	43.3	477	21.3	5.6	<0.01	0.01	<0.05	1.1	0.4	<0.2	4.9	<0.01	0.09	2
SG 296465	Soil	47.4	448	24.9	4.9	<0.01	<0.01	<0.05	1.2	<0.2	<0.2	6.1	<0.01	0.16	2
SG 296466	Soil	44.2	452	26.3	5.2	<0.01	0.01	<0.05	1.3	0.5	<0.2	5.1	<0.01	0.12	2
SG 296467	Soil	74.0	770	47.3	3.9	<0.01	0.03	3.84	3.8	1.0	<0.2	24.9	<0.01	0.18	3
SG 296468	Soil	55.5	331	28.4	3.1	<0.01	<0.01	<0.05	1.5	0.4	<0.2	6.1	<0.01	0.12	2
SG 296469	Soil	42.6	472	28.6	4.6	<0.01	0.01	0.97	0.9	0.5	<0.2	6.8	<0.01	0.18	1
SG 296470	Soil	45.2	371	38.5	3.9	<0.01	0.01	0.75	1.3	0.4	<0.2	9.9	<0.01	0.12	2
SG 296471	Soil	41.3	559	74.4	4.5	<0.01	0.03	0.57	1.0	0.5	<0.2	6.5	<0.01	0.14	1
SG 296472	Soil	31.4	539	249.4	3.7	<0.01	0.02	1.22	0.6	0.6	<0.2	7.3	<0.01	0.05	1
SG 296473	Soil	40.5	731	59.6	5.5	<0.01	0.02	0.33	0.9	0.6	0.2	10.9	<0.01	0.04	1
SG 296474	Soil	38.5	618	41.0	4.0	<0.01	0.02	0.28	0.9	0.6	<0.2	4.5	<0.01	0.12	1
SG 296475	Soil	53.2	380	33.1	3.5	<0.01	0.01	<0.05	1.5	0.5	<0.2	3.8	<0.01	0.09	3
SG 296476	Soil	29.1	1450	40.0	5.7	<0.01	0.06	0.21	0.4	0.6	<0.2	7.1	<0.01	0.10	0
SG 296477	Soil	33.1	989	32.0	4.1	<0.01	0.04	1.80	0.5	0.8	<0.2	6.2	<0.01	0.09	0
SG 296478	Soil	31.1	1012	22.4	3.6	<0.01	0.05	0.36	0.4	0.6	<0.2	6.9	<0.01	0.12	0
SG 296479	Soil	21.2	726	17.3	2.9	<0.01	0.03	0.29	0.3	0.8	<0.2	5.7	<0.01	0.04	0
SG 296480	Soil	29.2	260	38.4	4.2	<0.01	0.01	3.12	1.3	0.9	0.2	5.4	<0.01	0.23	6
SG 296481	Soil	33.4	930	23.7	4.0	<0.01	0.04	<0.05	0.3	0.7	0.3	11.3	<0.01	0.12	<0.2
SG 296482	Soil	29.7	1109	45.6	5.4	<0.01	0.05	<0.05	0.4	0.8	0.3	7.3	<0.01	0.09	0
SG 296483	Soil	26.4	1006	39.7	8.6	<0.01	0.03	<0.05	0.5	0.7	0.4	9.3	<0.01	0.12	0
SG 296484	Soil	35.9	559	26.1	4.7	<0.01	0.02	<0.05	1.1	0.7	<0.2	9.3	<0.01	0.11	2
SG 296485	Soil	18.4	1475	44.8	12.9	<0.01	0.05	0.13	0.2	0.4	<0.2	11.9	<0.01	0.09	0
SG 296486	Soil	30.6	516	60.6	5.1	<0.01	0.01	<0.05	0.7	0.4	<0.2	5.9	<0.01	0.11	1
SG 296487	Soil	4.5	591	14.8	4.3	<0.01	0.03	<0.05	<0.1	0.4	<0.2	5.8	<0.01	0.03	<0.2
SG 296488	Soil	19.3	793	29.6	8.3	<0.01	0.02	0.16	0.3	0.4	0.2	9.2	<0.01	0.09	0
SG 296489	Soil	19.2	387	31.9	5.6	<0.01	0.01	0.38	0.9	0.4	<0.2	9.4	<0.01	0.09	4
SG 296490	Soil	9.7	498	59.0	5.0	<0.01	0.02	0.31	0.4	0.3	0.2	4.3	<0.01	0.05	0
SG 296491	Soil	15.7	491	29.6	3.3	<0.01	0.01	0.11	0.3	0.5	<0.2	3.1	<0.01	0.08	0
SG 296492	Soil	20.4	831	29.7	7.0	<0.01	0.01	<0.05	0.8	0.4	0.2	14.8	<0.01	0.06	4
SG 296493	Soil	16.1	501	32.4	6.4	<0.01	0.02	<0.05	0.6	0.7	0.3	6.4	<0.01	0.08	2
SG 296494	Soil	4.8	237	9.1	2.1	<0.01	<0.01	<0.05	0.2	0.2	<0.2	1.6	<0.01	0.03	1
SG 296495	Soil	17.0	429	12.1	4.4	<0.01	<0.01	<0.05	0.4	0.3	0.2	5.1	<0.01	0.12	1
SG 296496	Soil	25.0	430	17.0	4.8	<0.01	0.01	<0.05	0.8	0.3	<0.2	5.0	<0.01	0.12	4
SG 296497	Soil	5.3	407	9.5	3.9	<0.01	0.01	<0.05	0.2	0.3	<0.2	4.9	<0.01	0.04	<0.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SG 296498	Soil	17.8	540	24.4	3.6	<0.01	0.03	<0.05	0.2	0.4	<0.2	8.0	<0.01	0.06	0
SG 296499	Soil	13.2	369	26.3	2.3	<0.01	0.02	<0.05	0.1	0.4	<0.2	7.8	<0.01	0.08	<0.2
SG 296500	Soil	16.8	458	20.8	2.8	<0.01	0.03	<0.05	0.1	<0.2	<0.2	6.9	<0.01	0.02	<0.2
SG 296321	Soil	15.9	513	44.2	5.8	<0.01	0.03	2.74	0.3	0.7	<0.2	14.5	<0.01	0.12	0
SI 481051	Soil	9.4	520	38.6	5.8	<0.01	0.03	0.09	0.2	0.4	<0.2	12.0	<0.01	0.05	0
SI 481052	Soil	31.5	243	25.2	2.4	<0.01	<0.01	0.80	1.2	0.4	<0.2	36.4	<0.01	0.18	7
SI 481053	Soil	30.4	659	19.8	4.2	<0.01	0.02	0.11	0.4	0.6	<0.2	12.8	<0.01	0.05	1
SI 481054	Soil	9.7	289	14.9	3.1	<0.01	0.01	0.05	0.4	0.3	<0.2	13.1	<0.01	0.06	2
SI 481055	Soil	27.1	317	20.3	5.4	<0.01	0.01	<0.05	1.1	0.5	<0.2	19.3	<0.01	0.11	4
SI 481056	Soil	23.1	363	32.7	7.7	<0.01	0.01	0.14	1.2	0.5	0.2	12.9	<0.01	0.12	3
SI 481057	Soil	31.8	428	23.8	3.5	<0.01	0.01	0.84	0.8	0.5	<0.2	17.0	<0.01	0.11	1
SI 481058	Soil	38.7	330	36.2	4.3	<0.01	0.02	3.22	1.8	0.5	<0.2	19.4	<0.01	0.22	5
SI 481059	Soil	17.4	336	17.6	5.2	<0.01	0.02	1.20	0.5	0.6	<0.2	25.2	<0.01	0.12	1
SI 481060	Soil	32.3	213	22.1	2.9	<0.01	<0.01	0.72	1.5	0.4	<0.2	17.3	<0.01	0.08	6
SI 481061	Soil	30.8	293	27.2	3.1	<0.01	0.02	2.48	1.5	0.5	<0.2	31.6	<0.01	0.12	3
SI 481062	Soil	41.9	265	23.1	3.6	<0.01	0.02	2.28	2.3	0.5	<0.2	43.3	<0.01	0.14	6
SI 481063	Soil	32.5	555	30.6	6.6	<0.01	0.02	0.09	1.1	0.4	<0.2	18.9	<0.01	0.12	2
SI 481064	Soil	48.9	398	31.2	4.0	<0.01	0.01	0.13	2.5	0.4	<0.2	11.7	<0.01	0.12	9
SI 481065	Soil	32.5	713	31.0	6.6	<0.01	0.03	0.21	2.3	0.8	<0.2	24.5	<0.01	0.08	2
SI 481066	Soil	26.5	717	111.5	7.0	<0.01	0.03	0.24	1.8	0.9	<0.2	42.5	<0.01	0.12	3
SI 481067	Soil	11.0	329	18.2	6.0	<0.01	0.01	<0.05	0.4	0.3	<0.2	16.3	<0.01	0.07	1
SI 481068	Soil	30.7	302	27.0	3.9	<0.01	<0.01	0.24	2.0	0.6	<0.2	8.0	<0.01	0.10	5
SM 268926	Soil	10.2	447	25.1	4.8	<0.01	0.03	0.21	0.3	0.5	0.2	5.0	<0.01	0.03	<0.2
SM 268927	Soil	30.2	1036	56.8	3.7	<0.01	0.03	0.72	0.2	0.5	<0.2	13.6	<0.01	0.15	0
SM 268928	Soil	18.0	577	54.7	4.3	<0.01	0.04	<0.05	0.4	0.6	0.3	4.8	<0.01	0.07	0
SM 268929	Soil	40.1	1060	55.0	5.0	<0.01	0.03	<0.05	0.7	0.5	<0.2	5.2	<0.01	0.13	1
SM 268930	Soil	25.8	681	43.7	3.6	<0.01	0.03	0.11	0.5	0.3	<0.2	6.0	<0.01	0.06	0
SM 268931	Soil	47.0	476	47.5	3.5	<0.01	0.01	0.06	1.3	0.4	<0.2	6.2	<0.01	0.09	3
SM 268932	Soil	31.1	1346	43.3	5.6	<0.01	0.04	<0.05	0.8	0.8	<0.2	7.1	<0.01	0.16	1
SM 268933	Soil	62.2	858	110.3	3.7	<0.01	0.02	0.53	1.0	0.6	<0.2	12.5	<0.01	0.12	2
SM 268934	Soil	20.0	564	188.9	5.7	<0.01	0.03	0.28	0.5	0.6	0.3	6.8	<0.01	0.08	0
SM 268935	Soil	28.1	406	66.4	4.3	<0.01	0.02	2.35	0.7	0.4	<0.2	11.3	<0.01	0.10	1
SM 268936	Soil	32.1	327	41.1	4.0	<0.01	0.01	0.55	0.5	0.6	<0.2	5.1	<0.01	0.07	1
SM 268937	Soil	20.1	1123	36.0	4.7	<0.01	0.05	0.07	0.2	0.7	<0.2	10.1	<0.01	0.11	<0.2
SM 268938	Soil	41.1	866	43.8	3.8	<0.01	0.03	<0.05	0.7	0.4	<0.2	4.4	<0.01	0.08	1
SM 268939	Soil	25.2	968	26.5	6.0	<0.01	0.04	<0.05	0.4	0.5	<0.2	6.1	<0.01	0.13	1
SM 268940	Soil	23.6	887	20.7	5.4	<0.01	0.03	<0.05	0.6	0.4	<0.2	5.0	<0.01	0.06	1
SM 268941	Soil	28.6	1114	29.9	6.9	<0.01	0.04	<0.05	0.5	0.4	<0.2	7.4	<0.01	0.11	0
SM 268942	Soil	27.1	1110	38.5	6.0	<0.01	0.05	<0.05	0.5	0.5	0.2	15.6	<0.01	0.08	1
SM 268943	Soil	30.6	1387	46.3	6.4	<0.01	0.04	<0.05	0.6	0.9	0.2	7.6	<0.01	0.14	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SM 268944	Soil	32.7	1131	36.5	4.6	<0.01	0.04	0.27	0.6	0.8	<0.2	7.3	<0.01	0.08	1
SM 268945	Soil	14.3	503	53.0	5.4	<0.01	0.02	1.07	0.2	0.3	0.2	6.8	<0.01	0.05	<0.2
SM 268946	Soil	17.7	464	24.5	5.2	<0.01	0.02	0.81	0.3	0.8	0.2	8.1	<0.01	0.13	<0.2
SM 268947	Soil	19.8	550	47.7	5.2	<0.01	0.03	0.94	0.5	0.7	0.3	6.8	<0.01	0.08	0
SM 268948	Soil	19.0	408	44.1	5.5	<0.01	0.02	1.41	0.5	0.4	<0.2	7.9	<0.01	0.10	1
SM 268949	Soil	28.2	408	48.3	6.6	<0.01	0.02	1.83	1.0	0.5	0.3	12.5	<0.01	0.08	3
SM 268950	Soil	33.2	490	50.8	5.9	<0.01	0.02	1.56	0.8	0.6	<0.2	13.9	<0.01	0.10	2
SM 268951	Soil	23.3	337	64.5	4.1	<0.01	0.03	4.51	1.1	0.6	0.3	31.6	<0.01	0.15	2
SM 268952	Soil	31.7	1497	36.3	4.9	<0.01	0.05	<0.05	0.7	0.5	<0.2	5.4	<0.01	0.13	1
SM 268953	Soil	13.8	662	23.0	2.8	<0.01	0.04	<0.05	0.1	0.4	<0.2	7.1	<0.01	0.02	<0.2
SM 268954	Soil	29.5	983	26.3	4.2	<0.01	0.05	<0.05	0.5	0.3	<0.2	7.3	<0.01	0.08	1
SM 268955	Soil	30.0	918	41.3	3.8	<0.01	0.03	0.05	0.7	0.4	<0.2	6.1	<0.01	0.09	1
SM 268956	Soil	10.5	437	68.2	4.0	<0.01	0.05	3.39	0.2	0.3	<0.2	18.2	<0.01	0.14	<0.2
SM 268957	Soil	27.0	480	59.4	4.1	<0.01	0.04	3.10	0.4	0.6	<0.2	15.7	<0.01	0.21	0
SM 268958	Soil	26.1	453	32.4	4.8	<0.01	0.02	1.94	0.4	0.3	<0.2	7.1	<0.01	0.06	0
SM 268959	Soil	19.5	422	37.1	5.0	<0.01	0.02	1.42	0.4	0.3	<0.2	9.8	<0.01	0.09	0
SM 268960	Soil	31.8	332	60.4	2.6	<0.01	0.03	1.79	1.0	0.9	0.6	8.3	<0.01	0.14	3
SM 268961	Soil	38.8	276	25.9	3.5	<0.01	0.01	0.74	0.8	0.3	0.3	5.3	<0.01	0.16	2
SM 268962	Soil	38.7	350	35.4	3.3	<0.01	0.02	0.23	1.1	0.4	<0.2	5.2	<0.01	0.18	4
SM 268963	Soil	43.9	495	62.6	3.1	<0.01	0.03	2.37	1.4	0.8	0.2	11.3	<0.01	0.16	4
SM 268964	Soil	21.2	232	56.3	2.7	<0.01	0.01	1.71	0.6	0.2	<0.2	5.7	<0.01	0.17	1
SM 268965	Soil	56.3	352	40.4	2.9	<0.01	0.02	3.03	1.5	0.7	<0.2	4.0	<0.01	0.24	4
SM 268966	Soil	29.8	363	53.3	3.1	<0.01	0.02	5.64	1.2	0.4	<0.2	12.8	<0.01	0.55	2
SM 268967	Soil	24.2	1028	54.9	3.7	<0.01	0.04	0.64	0.4	0.7	<0.2	8.2	<0.01	0.14	0
SM 268968	Soil	38.4	258	82.7	6.1	<0.01	0.13	2.23	1.5	0.5	0.2	21.1	<0.01	0.19	4
SM 268969	Soil	19.0	958	36.1	3.5	<0.01	0.05	<0.05	0.3	0.4	<0.2	5.8	<0.01	0.09	<0.2
SM 268970	Soil	31.5	1001	70.8	3.4	<0.01	0.03	0.36	0.7	0.3	<0.2	7.2	<0.01	0.10	1
SM 268971	Soil	20.6	751	35.5	2.9	<0.01	0.04	<0.05	0.4	<0.2	<0.2	5.5	<0.01	0.11	<0.2
SM 268972	Soil	36.1	1075	83.3	3.9	<0.01	0.02	<0.05	0.9	0.5	<0.2	3.7	<0.01	0.11	1
SM 268973	Soil	35.4	927	76.4	5.2	<0.01	0.02	<0.05	1.2	0.4	<0.2	5.7	<0.01	0.10	1
SM 268974	Soil	27.6	955	31.7	3.6	<0.01	0.03	<0.05	0.6	0.4	<0.2	7.3	<0.01	0.11	1
SM 268975	Soil	25.8	1146	45.8	4.2	<0.01	0.04	<0.05	0.5	0.4	<0.2	5.9	<0.01	0.09	0
SM 268976	Soil	22.0	1076	37.4	3.3	<0.01	0.05	<0.05	0.3	0.6	<0.2	4.4	<0.01	0.11	<0.2
SM 268977	Soil	15.6	704	40.8	2.7	<0.01	0.04	0.52	0.3	0.4	<0.2	6.1	<0.01	0.11	0
SM 268978	Soil	33.1	288	29.7	1.4	<0.01	0.01	1.55	1.2	<0.2	<0.2	10.1	<0.01	0.24	7
SM 268979	Soil	21.6	507	54.7	3.4	<0.01	0.03	0.41	0.4	0.7	<0.2	13.7	<0.01	0.11	0
SM 268980	Soil	30.2	226	34.7	2.8	<0.01	0.01	<0.05	1.0	0.6	<0.2	8.1	<0.01	0.11	4
SM 268981	Soil	26.5	864	59.2	6.0	<0.01	0.03	0.23	0.4	0.5	<0.2	7.5	<0.01	0.15	0
SM 268982	Soil	25.9	689	117.2	5.6	<0.01	0.02	0.15	0.5	<0.2	<0.2	7.4	<0.01	0.13	0
SM 268983	Soil	35.4	512	59.9	3.9	<0.01	0.01	<0.05	0.9	0.2	<0.2	7.9	<0.01	0.14	2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
SM 268984	Soil	28.2	523	35.5	4.9	<0.01	0.02	<0.05	0.5	0.4	<0.2	7.2	<0.01	0.10	0
SM 268985	Soil	24.0	390	35.3	3.5	<0.01	0.01	0.08	0.6	0.4	<0.2	3.8	<0.01	0.12	1
SM 268986	Soil	24.9	410	100.1	4.9	<0.01	0.01	0.19	0.9	0.6	0.2	5.4	<0.01	0.09	3
SM 268987	Soil	21.3	515	97.3	4.2	<0.01	0.01	<0.05	0.7	0.3	0.2	7.3	<0.01	0.09	2
SM 268988	Soil	30.4	369	66.7	3.1	<0.01	0.02	1.94	0.5	0.6	0.2	7.4	<0.01	0.14	1
SM 268989	Soil	22.8	342	36.4	2.3	<0.01	0.01	1.33	0.5	0.2	<0.2	4.8	<0.01	0.16	1
SM 268990	Soil	18.5	689	46.6	3.6	<0.01	0.03	1.53	0.2	0.3	<0.2	7.6	<0.01	0.14	0
SM 268991	Soil	31.2	273	49.8	2.7	<0.01	0.01	0.52	1.1	0.3	<0.2	5.5	<0.01	0.12	4
SM 268992	Soil	41.3	266	53.5	2.7	<0.01	0.03	3.61	1.6	0.7	<0.2	9.0	<0.01	0.31	7
SM 268993	Soil	38.3	425	37.2	2.9	<0.01	0.02	1.75	0.6	0.5	<0.2	7.7	<0.01	0.25	1
SM 268994	Soil	31.3	332	78.9	4.5	<0.01	0.06	3.65	1.2	0.5	0.2	18.8	<0.01	0.20	3
SM 268995	Soil	41.8	796	26.4	2.4	<0.01	0.02	<0.05	0.9	<0.2	<0.2	4.8	<0.01	0.14	1
SM 268996	Soil	26.2	705	27.7	1.9	<0.01	0.02	<0.05	0.6	0.2	<0.2	4.3	<0.01	0.05	0
SM 268997	Soil	30.9	1121	37.5	3.5	<0.01	0.03	<0.05	0.5	<0.2	<0.2	4.5	<0.01	0.11	1
SM 268998	Soil	33.5	780	47.8	2.8	<0.01	0.02	<0.05	0.9	<0.2	<0.2	5.5	<0.01	0.06	1
TG 296322	Soil	44.2	545	30.0	3.0	<0.01	0.01	<0.05	1.3	0.5	<0.2	7.7	<0.01	0.14	2
TG 296323	Soil	40.6	729	25.4	3.9	<0.01	0.05	<0.05	1.2	0.5	<0.2	12.7	<0.01	0.10	1
TG 296324	Soil	46.8	536	24.1	2.3	<0.01	0.02	<0.05	1.5	0.7	<0.2	9.2	<0.01	0.14	3
TG 296325	Soil	45.7	479	24.2	2.5	<0.01	0.01	<0.05	1.4	0.5	<0.2	7.4	<0.01	0.10	2
TG 296326	Soil	46.5	541	24.4	2.8	<0.01	0.02	<0.05	1.7	0.4	<0.2	10.7	<0.01	0.11	3
TG 296327	Soil	47.2	583	25.1	3.0	<0.01	0.02	<0.05	1.9	0.4	<0.2	13.8	<0.01	0.11	3
TG 296328	Soil	47.8	514	22.0	2.8	<0.01	0.02	<0.05	1.9	0.3	<0.2	10.9	<0.01	0.09	3
TG 296329	Soil	46.0	504	22.9	2.6	<0.01	0.02	<0.05	1.8	0.5	<0.2	11.8	<0.01	0.11	3
TG 296330	Soil	33.9	441	20.4	2.1	<0.01	0.02	<0.05	1.5	0.4	<0.2	28.5	<0.01	0.08	4
TG 296331	Soil	32.3	493	18.3	2.5	<0.01	0.03	<0.05	1.4	0.5	<0.2	28.8	<0.01	0.06	4
TG 296332	Soil	32.5	467	21.6	2.1	<0.01	0.03	<0.05	1.5	0.6	<0.2	31.1	<0.01	0.04	4
TG 296333	Soil	34.9	516	24.5	2.3	<0.01	0.02	<0.05	1.4	0.3	<0.2	18.5	<0.01	0.09	2
TG 296334	Soil	40.4	508	26.2	2.2	<0.01	0.02	<0.05	1.6	0.4	<0.2	16.4	<0.01	0.10	3
TG 296335	Soil	37.9	598	27.6	3.1	<0.01	0.04	<0.05	1.5	0.7	<0.2	21.5	<0.01	0.09	3
TG 296336	Soil	48.6	693	37.0	3.0	<0.01	0.03	0.10	1.7	0.4	<0.2	16.9	<0.01	0.12	2
TG 296337	Soil	30.1	810	29.2	5.7	<0.01	0.03	0.14	0.9	0.3	<0.2	15.4	<0.01	0.08	1
TI 480097	Soil	41.8	838	43.2	3.3	<0.01	0.05	0.79	0.9	<0.2	<0.2	14.6	<0.01	0.08	1
TI 480098	Soil	31.5	1249	47.4	3.3	<0.01	0.08	1.11	0.7	1.4	<0.2	21.0	<0.01	0.09	1
TI 480099	Soil	35.5	818	32.8	2.2	<0.01	0.09	0.56	0.8	3.0	<0.2	28.6	<0.01	0.06	1
TI 480100	Soil	24.0	842	20.8	2.6	<0.01	0.08	0.94	0.7	1.8	<0.2	31.2	<0.01	0.04	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SG 296338	Soil	0.006	0.05	1	17	10.73	2.3	80	<0.5
SG 296339	Soil	<0.005	0.08	1	8	2.37	2.7	99	1.0
SG 296340	Soil	0.005	<0.05	0	10	1.99	0.7	33	<0.5
SG 296341	Soil	<0.005	<0.05	0	7	1.67	0.2	5	<0.5
SG 296342	Soil	<0.005	<0.05	0	19	4.60	1.3	80	<0.5
SG 296343	Soil	0.007	<0.05	0	11	1.64	0.5	25	<0.5
SG 296344	Soil	<0.005	<0.05	1	7	10.25	0.8	23	<0.5
SG 296345	Soil	<0.005	<0.05	1	9	4.58	1.7	44	<0.5
SG 296346	Soil	0.005	<0.05	1	15	4.08	1.6	93	<0.5
SG 296347	Soil	0.006	<0.05	1	18	2.71	1.5	77	<0.5
SG 296348	Soil	<0.005	<0.05	0	12	5.63	0.6	19	<0.5
SG 296349	Soil	0.008	<0.05	1	18	3.58	1.4	66	<0.5
SG 296350	Soil	<0.005	<0.05	0	13	3.43	0.7	31	<0.5
SG 296351	Soil	0.005	<0.05	1	18	2.39	3.2	131	<0.5
SG 296352	Soil	0.011	<0.05	1	23	1.20	2.9	118	<0.5
SG 296353	Soil	0.007	<0.05	1	25	3.81	2.9	155	<0.5
SG 296354	Soil	0.010	0.05	2	29	2.76	3.0	153	<0.5
SG 296355	Soil	<0.005	<0.05	2	14	3.39	3.7	169	<0.5
SG 296356	Soil	0.007	<0.05	1	24	3.44	3.5	113	<0.5
SG 296357	Soil	<0.005	<0.05	1	17	3.82	2.6	118	<0.5
SG 296358	Soil	<0.005	<0.05	1	13	3.44	1.4	58	<0.5
SG 296359	Soil	<0.005	<0.05	0	6	0.91	0.3	11	<0.5
SG 296360	Soil	<0.005	<0.05	0	13	7.33	0.6	33	<0.5
SG 296361	Soil	<0.005	<0.05	1	11	1.44	2.3	34	<0.5
SG 296362	Soil	<0.005	<0.05	1	13	3.19	3.6	184	<0.5
SG 296363	Soil	<0.005	<0.05	2	16	2.02	2.6	138	<0.5
SG 296364	Soil	<0.005	<0.05	1	21	2.94	1.9	114	<0.5
SG 296365	Soil	<0.005	<0.05	1	25	1.96	1.6	82	<0.5
SG 296366	Soil	0.009	<0.05	1	24	2.47	2.9	154	<0.5
SG 296367	Soil	<0.005	<0.05	1	22	3.24	2.6	127	<0.5
SG 296368	Soil	0.007	<0.05	1	22	2.40	2.8	141	0.9
SG 296369	Soil	0.006	<0.05	1	25	4.08	2.0	95	<0.5
SG 296370	Soil	0.006	<0.05	1	22	1.87	1.6	71	<0.5
SG 296371	Soil	<0.005	<0.05	1	23	3.36	2.2	110	<0.5
SG 296372	Soil	<0.005	<0.05	0	10	10.66	0.6	39	<0.5
SG 296373	Soil	<0.005	<0.05	2	8	3.70	2.4	103	<0.5
SG 296374	Soil	<0.005	<0.05	0	7	1.02	0.3	15	<0.5
SG 296375	Soil	<0.005	<0.05	0	11	1.11	0.8	56	<0.5
SG 296376	Soil	<0.005	<0.05	0	10	1.36	1.5	110	<0.5
SG 296377	Soil	0.010	<0.05	1	21	3.34	1.6	74	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SG 296378	Soil	0.005	<0.05	1	20	2.87	1.5	86	<0.5
SG 296379	Soil	0.008	<0.05	1	20	3.21	1.9	84	<0.5
SG 296380	Soil	<0.005	<0.05	1	10	2.23	2.5	184	<0.5
SG 296381	Soil	<0.005	<0.05	1	14	1.08	1.9	212	<0.5
SG 296382	Soil	<0.005	<0.05	1	8	1.93	2.9	192	<0.5
SG 296383	Soil	<0.005	<0.05	3	5	1.32	5.9	283	<0.5
SG 296384	Soil	<0.005	<0.05	1	9	1.51	3.1	95	<0.5
SG 296385	Soil	<0.005	<0.05	4	6	2.50	10.7	209	0.6
SG 296386	Soil	0.006	<0.05	1	16	1.41	2.7	82	<0.5
SG 296387	Soil	0.009	0.05	1	23	8.62	3.5	73	<0.5
SG 296388	Soil	<0.005	<0.05	1	12	6.54	2.4	39	<0.5
SG 296389	Soil	<0.005	<0.05	2	14	2.15	2.6	129	<0.5
SG 296390	Soil	<0.005	<0.05	1	21	0.84	2.2	90	<0.5
SG 296391	Soil	<0.005	<0.05	1	16	0.67	1.6	81	0.5
SG 296392	Soil	<0.005	<0.05	1	15	2.16	1.0	27	<0.5
SG 296393	Soil	<0.005	<0.05	1	22	3.49	2.3	104	1.3
SG 296394	Soil	<0.005	<0.05	1	21	0.69	2.2	115	<0.5
SG 296395	Soil	<0.005	<0.05	1	14	2.14	1.2	32	<0.5
SG 296396	Soil	<0.005	<0.05	1	20	0.77	1.9	91	1.0
SG 296397	Soil	<0.005	<0.05	1	24	0.83	2.3	63	1.6
SG 296398	Soil	<0.005	<0.05	1	25	1.43	2.6	109	2.3
SG 296399	Soil	<0.005	0.07	1	32	1.46	2.3	54	<0.5
SG 296400	Soil	<0.005	<0.05	1	18	1.87	2.0	95	0.8
SG 296401	Soil	<0.005	0.06	1	12	5.23	8.1	114	<0.5
SG 296402	Soil	0.007	<0.05	1	25	9.59	2.2	80	<0.5
SG 296403	Soil	0.010	0.05	1	25	7.37	2.7	95	<0.5
SG 296404	Soil	0.005	<0.05	1	21	2.82	2.8	90	<0.5
SG 296405	Soil	0.007	<0.05	1	28	4.19	2.4	77	<0.5
SG 296406	Soil	0.007	<0.05	1	29	0.99	2.1	111	<0.5
SG 296407	Soil	0.009	<0.05	1	29	0.79	2.2	102	0.6
SG 296408	Soil	0.014	<0.05	1	29	3.35	2.0	63	<0.5
SG 296409	Soil	0.006	<0.05	1	18	0.95	1.6	74	<0.5
SG 296410	Soil	0.008	<0.05	1	23	0.80	1.7	68	<0.5
SG 296411	Soil	0.012	<0.05	1	31	0.93	2.5	96	<0.5
SG 296412	Soil	0.009	<0.05	1	29	3.07	2.5	83	<0.5
SG 296413	Soil	<0.005	<0.05	1	22	1.03	3.0	122	0.5
SG 296414	Soil	0.007	<0.05	1	26	1.09	2.2	110	1.0
SG 296415	Soil	<0.005	<0.05	1	24	2.67	2.3	105	1.3
SG 296416	Soil	0.006	<0.05	1	26	1.23	2.0	79	<0.5
SG 296417	Soil	<0.005	<0.05	1	24	1.60	3.1	89	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SG 296418	Soil	<0.005	<0.05	1	25	0.92	1.8	63	<0.5
SG 296419	Soil	<0.005	<0.05	1	29	2.18	5.9	94	0.7
SG 296420	Soil	0.006	<0.05	1	27	1.84	4.5	115	<0.5
SG 296421	Soil	<0.005	<0.05	1	25	1.94	2.6	91	1.7
SG 296422	Soil	<0.005	<0.05	1	27	2.61	2.3	91	0.8
SG 296423	Soil	<0.005	<0.05	1	23	4.46	2.9	146	<0.5
SG 296424	Soil	<0.005	<0.05	1	25	2.50	3.2	124	<0.5
SG 296425	Soil	<0.005	<0.05	1	24	2.49	2.7	134	<0.5
SG 296426	Soil	<0.005	<0.05	1	24	1.97	3.5	122	<0.5
SG 296427	Soil	<0.005	<0.05	1	24	1.10	3.8	84	<0.5
SG 296428	Soil	<0.005	<0.05	1	21	1.23	2.8	118	<0.5
SG 296429	Soil	<0.005	<0.05	1	23	1.40	3.2	115	<0.5
SG 296430	Soil	<0.005	<0.05	1	25	3.66	3.2	109	0.6
SG 296431	Soil	<0.005	<0.05	1	24	3.02	3.0	101	<0.5
SG 296432	Soil	<0.005	<0.05	1	26	1.78	2.7	97	<0.5
SG 296433	Soil	0.007	<0.05	1	32	0.79	3.3	108	<0.5
SG 296434	Soil	<0.005	<0.05	1	26	3.30	3.2	120	<0.5
SG 296435	Soil	0.012	0.06	1	39	1.47	3.0	81	<0.5
SG 296436	Soil	0.008	<0.05	1	30	0.94	2.4	93	<0.5
SG 296437	Soil	<0.005	<0.05	1	26	1.04	2.7	73	<0.5
SG 296438	Soil	0.006	<0.05	1	25	1.23	2.2	97	0.6
SG 296439	Soil	0.013	<0.05	1	34	5.67	3.1	97	<0.5
SG 296440	Soil	0.015	<0.05	1	28	7.48	5.6	120	<0.5
SG 296441	Soil	0.007	<0.05	1	25	1.53	3.0	104	<0.5
SG 296442	Soil	0.015	0.05	1	38	5.42	2.7	58	<0.5
SG 296443	Soil	<0.005	<0.05	1	24	1.25	2.7	103	<0.5
SG 296444	Soil	0.009	<0.05	1	25	1.36	2.3	96	<0.5
SG 296445	Soil	0.005	<0.05	1	18	1.24	2.2	94	<0.5
SG 296446	Soil	<0.005	<0.05	1	19	1.84	1.8	103	1.0
SG 296447	Soil	<0.005	<0.05	1	24	6.72	1.7	79	<0.5
SG 296448	Soil	<0.005	<0.05	1	19	1.50	1.4	82	<0.5
SG 296449	Soil	0.005	<0.05	1	23	2.72	2.1	93	0.7
SG 296450	Soil	<0.005	<0.05	1	16	4.72	2.8	93	<0.5
SG 296451	Soil	<0.005	<0.05	1	21	3.81	2.4	100	0.8
SG 296452	Soil	<0.005	<0.05	1	24	2.99	1.5	65	<0.5
SG 296453	Soil	<0.005	<0.05	1	17	0.97	1.6	103	<0.5
SG 296454	Soil	<0.005	<0.05	1	18	1.76	1.8	79	<0.5
SG 296455	Soil	<0.005	<0.05	1	18	3.16	2.4	114	<0.5
SG 296456	Soil	<0.005	<0.05	1	19	4.50	3.1	118	<0.5
SG 296457	Soil	<0.005	<0.05	1	18	1.17	2.9	106	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SG 296458	Soil	<0.005	<0.05	1	17	1.86	2.2	93	0.7
SG 296459	Soil	<0.005	<0.05	1	19	2.82	2.2	108	<0.5
SG 296460	Soil	<0.005	<0.05	1	18	4.57	2.5	111	<0.5
SG 296461	Soil	<0.005	<0.05	1	24	1.54	1.7	126	<0.5
SG 296462	Soil	<0.005	<0.05	1	18	6.74	1.8	110	1.5
SG 296463	Soil	<0.005	<0.05	1	19	6.31	1.8	111	<0.5
SG 296464	Soil	<0.005	<0.05	1	19	1.17	1.7	114	<0.5
SG 296465	Soil	<0.005	<0.05	1	22	2.77	2.1	113	<0.5
SG 296466	Soil	<0.005	<0.05	1	21	2.90	1.9	109	<0.5
SG 296467	Soil	<0.005	<0.05	3	15	2.62	21.0	180	<0.5
SG 296468	Soil	<0.005	<0.05	1	20	4.04	2.2	124	<0.5
SG 296469	Soil	<0.005	<0.05	1	17	4.75	2.1	92	<0.5
SG 296470	Soil	<0.005	<0.05	1	16	3.69	2.4	107	<0.5
SG 296471	Soil	<0.005	<0.05	1	17	1.24	2.1	120	<0.5
SG 296472	Soil	<0.005	<0.05	1	12	4.62	2.7	166	<0.5
SG 296473	Soil	0.007	<0.05	1	37	5.54	3.1	132	<0.5
SG 296474	Soil	<0.005	<0.05	1	20	1.90	1.6	102	<0.5
SG 296475	Soil	<0.005	<0.05	1	19	4.43	2.1	125	<0.5
SG 296476	Soil	<0.005	<0.05	1	24	1.48	2.3	84	0.6
SG 296477	Soil	<0.005	<0.05	1	19	9.05	3.1	88	<0.5
SG 296478	Soil	<0.005	<0.05	1	18	2.27	2.1	84	<0.5
SG 296479	Soil	<0.005	<0.05	1	19	1.63	1.7	63	<0.5
SG 296480	Soil	<0.005	<0.05	1	13	6.62	1.7	91	0.6
SG 296481	Soil	<0.005	<0.05	1	24	0.99	2.2	72	<0.5
SG 296482	Soil	0.006	<0.05	1	22	0.57	2.1	96	0.5
SG 296483	Soil	0.011	<0.05	1	31	0.92	2.1	85	<0.5
SG 296484	Soil	0.005	<0.05	1	20	1.20	2.3	96	<0.5
SG 296485	Soil	<0.005	<0.05	1	18	0.74	1.8	75	<0.5
SG 296486	Soil	<0.005	<0.05	1	14	0.60	2.0	95	<0.5
SG 296487	Soil	<0.005	<0.05	0	8	0.34	0.5	35	<0.5
SG 296488	Soil	0.006	<0.05	1	15	0.98	1.6	75	<0.5
SG 296489	Soil	<0.005	<0.05	1	12	0.79	1.5	68	<0.5
SG 296490	Soil	0.005	<0.05	0	13	1.14	1.2	49	<0.5
SG 296491	Soil	<0.005	<0.05	1	9	3.64	1.6	57	<0.5
SG 296492	Soil	<0.005	<0.05	1	15	0.64	2.6	79	<0.5
SG 296493	Soil	0.007	<0.05	1	20	0.98	1.7	67	<0.5
SG 296494	Soil	<0.005	<0.05	0	4	0.63	0.7	25	<0.5
SG 296495	Soil	0.005	<0.05	0	18	0.73	1.6	60	<0.5
SG 296496	Soil	<0.005	<0.05	1	15	0.58	1.6	75	<0.5
SG 296497	Soil	0.007	<0.05	0	10	0.70	0.7	20	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SG 296498	Soil	<0.005	<0.05	1	7	0.60	1.3	56	<0.5
SG 296499	Soil	<0.005	<0.05	1	7	0.43	1.1	48	<0.5
SG 296500	Soil	<0.005	<0.05	1	4	0.71	1.5	72	<0.5
SG 296321	Soil	0.005	<0.05	1	10	1.61	1.8	111	<0.5
SI 481051	Soil	<0.005	<0.05	1	8	0.50	1.2	55	<0.5
SI 481052	Soil	<0.005	<0.05	2	8	0.48	2.5	97	<0.5
SI 481053	Soil	<0.005	<0.05	1	11	1.01	2.3	101	<0.5
SI 481054	Soil	<0.005	<0.05	1	4	0.80	1.3	40	<0.5
SI 481055	Soil	<0.005	<0.05	1	11	0.41	2.0	73	<0.5
SI 481056	Soil	<0.005	<0.05	2	17	0.58	1.9	78	<0.5
SI 481057	Soil	<0.005	<0.05	1	13	0.72	1.6	85	<0.5
SI 481058	Soil	<0.005	<0.05	3	8	0.84	3.6	106	<0.5
SI 481059	Soil	<0.005	<0.05	2	8	0.80	1.2	57	<0.5
SI 481060	Soil	<0.005	<0.05	1	9	1.14	2.1	86	<0.5
SI 481061	Soil	<0.005	<0.05	2	8	0.93	2.6	81	<0.5
SI 481062	Soil	<0.005	<0.05	3	6	0.75	3.6	100	<0.5
SI 481063	Soil	<0.005	<0.05	1	12	0.45	2.9	98	<0.5
SI 481064	Soil	<0.005	<0.05	1	16	0.80	4.2	131	<0.5
SI 481065	Soil	<0.005	<0.05	2	13	0.55	8.4	97	<0.5
SI 481066	Soil	<0.005	<0.05	3	10	0.73	6.4	103	<0.5
SI 481067	Soil	<0.005	<0.05	1	14	0.48	1.2	69	<0.5
SI 481068	Soil	<0.005	<0.05	1	10	0.47	4.6	88	<0.5
SM 268926	Soil	0.007	<0.05	1	15	7.34	1.5	62	<0.5
SM 268927	Soil	<0.005	<0.05	2	11	2.27	4.5	157	<0.5
SM 268928	Soil	0.010	<0.05	1	20	1.22	3.6	107	<0.5
SM 268929	Soil	<0.005	<0.05	2	19	0.40	2.4	142	1.3
SM 268930	Soil	0.007	<0.05	1	16	0.63	1.6	85	<0.5
SM 268931	Soil	<0.005	<0.05	1	17	1.00	2.5	128	<0.5
SM 268932	Soil	0.005	<0.05	1	20	0.51	2.7	97	1.9
SM 268933	Soil	<0.005	<0.05	2	16	1.71	4.5	196	<0.5
SM 268934	Soil	0.009	<0.05	1	18	3.41	2.9	148	<0.5
SM 268935	Soil	<0.005	<0.05	1	11	3.23	3.7	187	<0.5
SM 268936	Soil	<0.005	<0.05	1	7	1.49	2.6	219	<0.5
SM 268937	Soil	<0.005	<0.05	1	18	0.70	2.1	87	<0.5
SM 268938	Soil	<0.005	<0.05	1	17	0.40	2.0	118	1.0
SM 268939	Soil	<0.005	<0.05	1	19	0.52	1.6	73	0.7
SM 268940	Soil	<0.005	<0.05	1	17	0.64	1.4	72	0.7
SM 268941	Soil	<0.005	<0.05	1	20	0.85	1.8	80	<0.5
SM 268942	Soil	0.005	<0.05	1	23	0.52	2.0	96	0.8
SM 268943	Soil	<0.005	<0.05	1	23	0.66	2.2	90	1.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SM 268944	Soil	0.006	<0.05	1	20	0.96	2.2	112	1.1
SM 268945	Soil	<0.005	<0.05	1	16	1.38	1.7	95	<0.5
SM 268946	Soil	<0.005	<0.05	1	14	2.08	1.6	67	<0.5
SM 268947	Soil	<0.005	<0.05	1	13	1.81	2.3	110	<0.5
SM 268948	Soil	<0.005	<0.05	1	11	3.60	1.7	114	<0.5
SM 268949	Soil	<0.005	<0.05	1	12	1.67	1.8	107	<0.5
SM 268950	Soil	<0.005	<0.05	1	13	1.76	2.0	118	<0.5
SM 268951	Soil	<0.005	<0.05	2	8	3.82	4.1	174	<0.5
SM 268952	Soil	<0.005	<0.05	1	18	0.59	2.0	99	1.8
SM 268953	Soil	<0.005	<0.05	1	11	1.18	1.4	55	<0.5
SM 268954	Soil	<0.005	<0.05	1	17	0.69	1.5	83	0.7
SM 268955	Soil	<0.005	<0.05	1	17	0.41	2.9	102	0.6
SM 268956	Soil	<0.005	<0.05	1	7	1.09	1.3	100	<0.5
SM 268957	Soil	<0.005	<0.05	1	9	2.17	2.4	122	<0.5
SM 268958	Soil	<0.005	<0.05	0	10	0.93	1.2	103	<0.5
SM 268959	Soil	<0.005	<0.05	1	9	1.26	1.1	73	<0.5
SM 268960	Soil	<0.005	<0.05	2	6	1.56	3.0	143	<0.5
SM 268961	Soil	<0.005	<0.05	1	9	0.85	1.8	107	<0.5
SM 268962	Soil	<0.005	<0.05	1	11	1.13	1.9	120	<0.5
SM 268963	Soil	<0.005	<0.05	2	8	2.71	2.9	213	<0.5
SM 268964	Soil	<0.005	<0.05	1	6	1.13	1.6	120	<0.5
SM 268965	Soil	<0.005	<0.05	2	7	1.10	2.8	211	<0.5
SM 268966	Soil	<0.005	<0.05	1	8	1.71	1.7	121	<0.5
SM 268967	Soil	<0.005	<0.05	1	15	1.21	1.4	83	<0.5
SM 268968	Soil	<0.005	0.07	1	6	0.84	2.8	156	<0.5
SM 268969	Soil	<0.005	<0.05	1	15	0.46	1.4	67	<0.5
SM 268970	Soil	<0.005	<0.05	2	13	0.75	2.2	120	<0.5
SM 268971	Soil	<0.005	<0.05	1	12	0.73	1.2	62	<0.5
SM 268972	Soil	<0.005	<0.05	1	19	0.34	2.2	128	0.6
SM 268973	Soil	0.006	<0.05	1	19	0.39	3.3	118	<0.5
SM 268974	Soil	<0.005	<0.05	1	17	0.61	1.4	85	1.2
SM 268975	Soil	<0.005	<0.05	1	15	1.05	1.6	83	0.7
SM 268976	Soil	<0.005	<0.05	1	16	0.30	1.9	80	<0.5
SM 268977	Soil	<0.005	<0.05	1	10	0.78	1.1	65	<0.5
SM 268978	Soil	<0.005	<0.05	1	8	0.85	2.4	88	0.6
SM 268979	Soil	<0.005	<0.05	1	6	1.40	3.3	82	<0.5
SM 268980	Soil	<0.005	<0.05	1	9	0.72	1.3	98	<0.5
SM 268981	Soil	<0.005	<0.05	1	14	1.15	1.8	107	<0.5
SM 268982	Soil	<0.005	<0.05	1	14	0.70	1.8	137	<0.5
SM 268983	Soil	<0.005	<0.05	1	11	0.62	1.9	119	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SM 268984	Soil	<0.005	<0.05	1	14	0.54	1.9	161	<0.5
SM 268985	Soil	<0.005	<0.05	1	12	1.08	1.4	95	<0.5
SM 268986	Soil	<0.005	<0.05	1	13	2.35	2.1	131	<0.5
SM 268987	Soil	<0.005	<0.05	1	15	3.69	1.4	145	<0.5
SM 268988	Soil	<0.005	<0.05	1	9	1.38	1.7	117	<0.5
SM 268989	Soil	<0.005	<0.05	1	7	1.32	2.1	146	<0.5
SM 268990	Soil	<0.005	<0.05	1	11	2.04	1.7	103	<0.5
SM 268991	Soil	<0.005	<0.05	1	9	2.12	1.5	97	<0.5
SM 268992	Soil	<0.005	<0.05	2	8	1.01	1.7	141	<0.5
SM 268993	Soil	<0.005	<0.05	2	7	0.57	1.5	105	<0.5
SM 268994	Soil	<0.005	0.05	1	7	1.66	1.8	129	<0.5
SM 268995	Soil	<0.005	<0.05	1	16	0.62	1.5	107	<0.5
SM 268996	Soil	<0.005	<0.05	1	12	0.53	1.2	68	<0.5
SM 268997	Soil	<0.005	<0.05	1	17	0.35	1.8	85	0.6
SM 268998	Soil	<0.005	<0.05	1	17	0.61	2.1	92	<0.5
TG 296322	Soil	<0.005	<0.05	2	15	0.13	3.3	119	<0.5
TG 296323	Soil	<0.005	<0.05	3	15	0.23	5.1	112	<0.5
TG 296324	Soil	<0.005	<0.05	2	15	0.30	3.7	119	<0.5
TG 296325	Soil	<0.005	<0.05	2	15	0.26	3.2	114	<0.5
TG 296326	Soil	<0.005	<0.05	3	17	0.21	4.2	115	<0.5
TG 296327	Soil	<0.005	<0.05	3	17	0.40	5.1	119	<0.5
TG 296328	Soil	<0.005	<0.05	2	17	0.36	4.2	116	<0.5
TG 296329	Soil	<0.005	<0.05	2	16	0.44	4.1	116	<0.5
TG 296330	Soil	<0.005	<0.05	1	12	0.50	4.3	88	<0.5
TG 296331	Soil	<0.005	<0.05	1	11	0.32	4.5	87	<0.5
TG 296332	Soil	<0.005	<0.05	2	11	0.64	4.7	87	<0.5
TG 296333	Soil	<0.005	<0.05	2	12	0.56	3.9	100	<0.5
TG 296334	Soil	<0.005	<0.05	1	13	0.30	4.3	103	<0.5
TG 296335	Soil	<0.005	<0.05	1	11	0.33	6.1	105	0.5
TG 296336	Soil	<0.005	<0.05	1	16	0.32	6.0	145	<0.5
TG 296337	Soil	<0.005	<0.05	1	13	0.64	3.4	96	<0.5
TI 480097	Soil	<0.005	<0.05	1	13	0.48	2.6	130	<0.5
TI 480098	Soil	<0.005	<0.05	1	8	0.35	7.2	124	0.6
TI 480099	Soil	<0.005	<0.05	7	12	0.71	9.5	80	<0.5
TI 480100	Soil	<0.005	<0.05	10	8	0.29	7.7	60	1.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
SG 296338	Soil	1.573													
SG 296338 Dup		2.443													
SG 296356	Soil	0.023													
SG 296356 Dup		0.022													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.830													
QCV1007-00965-0004-BLK		<0.005													
SG 296374	Soil	0.026													
SG 296374 Dup		0.025													
SG 296392	Soil	0.010													
SG 296392 Dup		0.007													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.836													
QCV1007-00965-0008-BLK		0.008													
SG 296410	Soil	0.026													
SG 296410 Dup		0.021													
SG 296428	Soil	0.021													
SG 296428 Dup		0.019													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.839													
QCV1007-00965-0012-BLK		0.006													
SG 296446	Soil	0.012													
SG 296446 Dup		0.019													
SG 296464	Soil	0.042													
SG 296464 Dup		0.024													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.874													
QCV1007-00965-0016-BLK		<0.005													
SG 296482	Soil	0.029													
SG 296482 Dup		0.013													
SG 296500	Soil	0.009													
SG 296500 Dup		0.006													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.740													
QCV1007-00965-0020-BLK		<0.005													
SI 481067	Soil	0.013													
SI 481067 Dup		0.042													
SM 268942	Soil	0.046													
SM 268942 Dup		0.021													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.861													

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Au Au-1AT-GV g/ton 0.100	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05
QCV1007-00965-0024-BLK		<0.005													
SM 268960	Soil	1.061													
SM 268960 Dup		1.217													
SM 268978	Soil	0.032													
SM 268978 Dup		0.032													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.825													
QCV1007-00965-0028-BLK		<0.005													
SM 268996	Soil	<0.005													
SM 268996 Dup		<0.005													
TG 296337	Soil	0.012													
TG 296337 Dup		0.013													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.269													
QCV1007-00966-0001-BLK				<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
SG 296338	Soil			0.41	0.61	1908.5	49	0.2	0.31	0.02	0.32	24.41	9.2	8	2.2
SG 296338 Dup				0.37	0.60	1897.2	48	0.2	0.30	0.02	0.33	25.65	9.3	8	2.2
STD-ME-6 expected				101											
STD-ME-6 result				>100	1.28	239.7	95	0.3	5.84	0.68	34.86	10.01	14.4	34	0.4
SG 296356	Soil			0.28	1.11	501.8	39	0.4	0.42	0.02	0.79	24.27	12.2	15	1.3
SG 296356 Dup				0.27	1.14	501.3	38	0.4	0.42	0.02	0.79	24.31	12.0	15	1.3
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.35	3.72	5.6	203	0.8	0.18	0.24	0.11	36.91	113.1	908	1.2
SG 296374	Soil			0.49	0.14	26.4	68	0.1	0.05	0.04	0.25	2.47	5.3	2	0.4
SG 296374 Dup				0.47	0.14	26.3	67	0.1	0.05	0.05	0.25	2.48	5.1	2	0.4
STD-ME-6 expected				101.00											
STD-ME-6 result				99.06	1.29	240.7	99	0.2	5.75	0.68	34.58	10.32	14.1	34	0.4
SG 296392	Soil			0.19	0.78	3.8	36	0.1	0.26	0.01	0.09	16.81	4.3	14	1.8
SG 296392 Dup				0.17	0.79	3.8	36	0.1	0.26	0.01	0.09	17.05	4.2	14	1.9
STD-ME-6 expected				101.00											
STD-ME-6 result				97.80	1.21	217.6	100	0.2	5.81	0.64	36.43	10.42	15.2	32	0.4
SG 296410	Soil			0.25	1.34	27.7	32	0.2	0.36	0.02	0.07	25.23	12.2	21	2.3
SG 296410 Dup				0.27	1.34	28.2	32	0.2	0.36	0.02	0.06	25.62	12.0	21	2.4
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.29	3.67	6.3	222	0.8	0.19	0.24	0.13	40.37	113.6	913	1.4
SG 296428	Soil			0.25	2.18	51.4	31	0.5	0.48	0.01	0.13	37.13	21.7	33	1.6
SG 296428 Dup				0.25	2.14	50.8	32	0.6	0.48	0.01	0.14	39.08	20.9	33	1.7
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.30	3.54	6.2	212	0.8	0.18	0.23	0.12	38.26	112.5	895	1.3
SG 296446	Soil			0.34	1.77	52.4	41	0.4	0.50	0.01	0.25	23.98	20.0	27	2.4
SG 296446 Dup				0.28	1.75	51.5	41	0.4	0.48	0.01	0.25	24.21	19.6	27	2.6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Au	Au	Ag	Al	As	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr	Cs
		Au-1AT-AA	Au-1AT-GV	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample	Sample	g/ton	g/ton	ppm	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm
Description	Type	0.005	0.100	0.01	0.01	0.1	5	0.05	0.01	0.01	0.01	0.02	0.1	1	0.05
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.49	3.66	6.3	203	0.7	0.20	0.24	0.11	37.19	109.0	853	1.1
SG 296464	Soil			0.36	2.10	43.8	32	0.4	0.44	0.01	0.12	30.50	20.2	30	2.1
SG 296464 Dup				0.34	2.09	43.2	32	0.4	0.43	0.01	0.12	29.57	21.4	29	2.0
STD-ME-6 expected				101.00											
STD-ME-6 result				94.24	1.18	231.1	87	0.2	5.81	0.60	32.15	9.11	13.7	32	0.3
SG 296482	Soil			0.43	1.79	51.2	41	0.5	0.51	0.01	0.25	20.29	15.2	26	3.3
SG 296482 Dup				0.49	1.80	51.6	43	0.5	0.52	0.01	0.25	20.42	15.5	27	3.2
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.32	3.33	8.3	187	0.6	0.17	0.24	0.10	33.20	108.9	875	1.1
SG 296500	Soil			0.47	0.19	269.9	15	0.1	0.14	0.13	0.30	16.51	10.5	7	0.5
SG 296500 Dup				0.40	0.20	270.3	15	0.1	0.14	0.14	0.30	16.15	10.2	7	0.5
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.35	3.24	7.6	179	0.6	0.17	0.23	0.11	31.39	108.8	836	1.0
SI 481067	Soil			0.42	0.48	95.2	26	0.1	0.30	0.18	0.54	25.29	5.6	8	1.6
SI 481067 Dup				0.38	0.48	94.5	27	0.1	0.30	0.17	0.54	24.97	5.7	8	1.6
SM 268942	Soil			0.59	1.59	57.7	54	0.4	0.38	0.07	0.34	25.14	15.6	25	4.7
SM 268942 Dup				0.56	1.60	58.4	54	0.4	0.37	0.07	0.30	25.03	15.6	25	4.7
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.35	3.24	16.0	196	0.6	0.16	0.23	0.12	34.22	107.0	843	1.1
SM 268960	Soil			0.75	0.33	943.3	17	0.3	0.43	<0.01	0.60	22.43	16.1	5	1.6
SM 268960 Dup				0.81	0.32	953.3	16	0.3	0.44	<0.01	0.58	21.90	15.8	5	1.6
STD-ME-6 expected				101.00											
STD-ME-6 result				94.31	1.17	232.8	79	0.2	5.89	0.59	32.77	8.81	12.2	31	0.3
SM 268978	Soil			0.50	0.57	665.7	20	0.3	0.44	0.06	0.12	16.16	17.2	13	0.9
SM 268978 Dup				0.47	0.57	670.4	21	0.3	0.44	0.06	0.12	16.33	17.4	13	0.9
STD-ME-6 expected				101.00											
STD-ME-6 result				94.83	1.18	230.5	79	0.2	6.08	0.60	31.74	8.69	13.4	32	0.3
SM 268996	Soil			0.49	1.50	5.3	24	0.2	0.30	0.06	0.08	14.32	14.6	21	1.8
SM 268996 Dup				0.56	1.49	5.5	23	0.2	0.29	0.06	0.08	14.40	14.5	22	1.8
STD-ME-6 expected				101.00											
STD-ME-6 result				93.46	1.13	238.4	66	0.2	5.97	0.57	31.40	8.11	11.7	31	0.3
TG 296337	Soil			0.68	1.61	31.8	66	0.5	0.40	0.22	0.16	14.89	11.6	22	4.9
TG 296337 Dup				0.69	1.59	32.2	67	0.5	0.39	0.21	0.15	14.82	11.6	21	4.8
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.31	3.08	4.4	187	0.7	0.18	0.24	0.10	34.46	110.2	836	0.9
QCV1007-00966-0034-BLK				0.02	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
STD-OREAS-45P-AR expected				0.30		4.4			0.18		0.09		107.0	892	
STD-OREAS-45P-AR result				0.29	2.82	5.8	183	0.6	0.18	0.24	0.10	33.35	107.1	805	0.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05
QCV1007-00966-0001-BLK		<0.2	<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05
SG 296338	Soil	21.1	2.82	3.5	<0.05	<0.02	0.03	0.04	12.9	3.4	0.06	440	0.96	<0.01	0.4
SG 296338 Dup		21.1	2.89	3.5	<0.05	<0.02	0.02	0.04	13.3	3.4	0.06	445	0.92	0.01	0.4
STD-ME-6 expected		6130.0													
STD-ME-6 result		6481.2	5.81	4.7	<0.05	0.23	0.49	0.11	4.6	9.8	0.90	1729	22.75	0.06	0.2
SG 296356	Soil	26.9	3.54	5.2	<0.05	<0.02	0.06	0.03	13.1	10.9	0.15	385	0.99	<0.01	0.4
SG 296356 Dup		27.2	3.61	5.2	<0.05	<0.02	0.06	0.03	13.2	11.0	0.16	384	1.01	<0.01	0.5
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		673.9	>10	18.7	0.2	0.59	0.10	0.08	17.1	6.6	0.12	1118	1.24	0.02	0.5
SG 296374	Soil	4.0	0.35	1.2	<0.05	<0.02	<0.01	0.02	1.0	0.3	0.01	1299	0.20	0.02	0.1
SG 296374 Dup		4.1	0.35	1.2	<0.05	<0.02	<0.01	0.02	1.0	0.3	0.02	1304	0.19	0.02	0.1
STD-ME-6 expected		6130.0													
STD-ME-6 result		6486.1	5.83	4.5	<0.05	0.25	0.46	0.11	4.7	9.7	0.90	1718	22.59	0.06	0.3
SG 296392	Soil	10.3	1.66	4.1	<0.05	<0.02	0.01	0.02	8.0	10.2	0.14	425	0.47	<0.01	0.1
SG 296392 Dup		10.6	1.69	4.4	<0.05	<0.02	0.01	0.02	8.0	10.4	0.14	431	0.48	<0.01	0.1
STD-ME-6 expected		6130.0													
STD-ME-6 result		6207.8	5.61	4.8	<0.05	0.21	0.50	0.10	4.9	10.0	0.86	1658	22.72	0.06	0.2
SG 296410	Soil	26.4	3.80	5.7	<0.05	<0.02	0.02	0.03	13.5	30.7	0.48	491	0.66	0.01	0.3
SG 296410 Dup		27.1	3.80	6.0	<0.05	<0.02	0.02	0.03	13.7	30.6	0.48	493	0.66	0.01	0.3
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		681.3	>10	21.3	0.2	0.54	0.12	0.08	19.3	7.4	0.12	1113	1.75	0.02	0.6
SG 296428	Soil	49.3	5.05	6.9	<0.05	<0.02	0.03	0.02	20.0	71.1	0.89	653	0.53	<0.01	0.1
SG 296428 Dup		50.2	5.03	7.0	<0.05	<0.02	0.03	0.03	20.0	72.5	0.88	650	0.53	<0.01	0.1
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		670.0	>10	20.7	0.2	0.51	0.11	0.08	18.1	7.1	0.12	1100	1.70	0.02	0.6
SG 296446	Soil	45.3	5.19	6.1	<0.05	0.03	0.03	0.02	13.1	46.1	0.70	926	0.62	<0.01	0.2
SG 296446 Dup		45.4	5.18	6.1	<0.05	0.02	0.03	0.02	12.7	46.0	0.68	926	0.63	<0.01	0.2
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		642.0	>10	17.6	0.1	0.51	0.10	0.07	17.2	5.7	0.11	1091	1.58	0.02	0.6
SG 296464	Soil	38.0	4.80	7.0	<0.05	<0.02	0.03	0.02	17.1	61.3	0.80	574	0.48	<0.01	0.1
SG 296464 Dup		39.3	4.77	7.3	<0.05	<0.02	0.03	0.02	17.1	61.7	0.80	571	0.46	<0.01	0.1
STD-ME-6 expected		6130.0													
STD-ME-6 result		6289.3	5.57	4.3	<0.05	0.19	0.45	0.09	4.2	8.9	0.82	1656	21.04	0.06	0.2
SG 296482	Soil	53.7	5.41	6.5	<0.05	<0.02	0.03	0.03	11.4	33.1	0.43	508	0.90	0.01	0.4
SG 296482 Dup		52.8	5.45	6.6	<0.05	<0.02	0.03	0.03	11.6	33.2	0.44	514	0.90	0.01	0.4
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		649.8	>10	16.6	0.1	0.47	0.09	0.07	15.6	5.3	0.11	1088	1.49	0.02	0.6
SG 296500	Soil	10.3	2.20	0.6	<0.05	<0.02	<0.01	0.04	7.6	1.2	0.04	505	0.35	<0.01	<0.05
SG 296500 Dup		10.3	2.12	0.6	<0.05	<0.02	<0.01	0.04	7.7	1.2	0.05	506	0.35	<0.01	<0.05
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		629.4	>10	15.7	0.1	0.43	0.09	0.07	14.8	5.0	0.10	1060	1.47	0.02	0.6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Cu	Fe	Ga	Ge	Hf	In	K	La	Li	Mg	Mn	Mo	Na	Nb
		50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample Description	Sample Type	ppm	%	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%	ppm
		0.2	0.01	0.05	0.05	0.02	0.01	0.01	0.2	0.1	0.01	1	0.05	0.01	0.05
SI 481067	Soil	16.9	1.77	3.4	<0.05	<0.02	0.02	0.03	14.3	8.1	0.12	175	0.40	0.01	0.2
SI 481067 Dup		17.3	1.74	3.4	<0.05	<0.02	0.01	0.03	14.3	8.4	0.12	173	0.40	0.01	0.2
SM 268942	Soil	46.2	4.59	6.4	<0.05	<0.02	0.03	0.04	13.8	30.9	0.43	750	0.64	0.01	0.4
SM 268942 Dup		46.4	4.62	6.4	<0.05	<0.02	0.03	0.04	14.1	31.4	0.43	760	0.67	0.01	0.4
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		631.2	>10	17.2	0.1	0.47	0.10	0.07	15.9	5.3	0.10	1066	1.50	0.02	0.6
SM 268960	Soil	28.2	3.55	0.9	<0.05	<0.02	0.03	0.02	11.8	1.4	0.02	361	0.52	<0.01	0.1
SM 268960 Dup		27.8	3.55	0.9	<0.05	<0.02	0.03	0.02	11.8	1.4	0.02	362	0.52	<0.01	0.1
STD-ME-6 expected		6130.0													
STD-ME-6 result		6390.5	5.66	4.0	<0.05	0.14	0.45	0.09	4.0	8.2	0.82	1686	19.37	0.06	0.1
SM 268978	Soil	42.3	3.78	2.0	<0.05	<0.02	0.02	0.01	9.2	14.8	0.22	776	0.80	<0.01	<0.05
SM 268978 Dup		42.4	3.80	2.0	<0.05	<0.02	0.02	0.01	9.4	15.4	0.22	779	0.80	<0.01	<0.05
STD-ME-6 expected		6130.0													
STD-ME-6 result		6420.8	5.84	3.9	<0.05	0.13	0.44	0.09	4.0	8.6	0.85	1696	21.36	0.06	0.1
SM 268996	Soil	28.0	2.88	4.2	<0.05	<0.02	0.02	0.03	8.3	44.7	0.56	800	0.34	0.01	0.1
SM 268996 Dup		28.5	2.86	4.1	<0.05	<0.02	0.02	0.03	8.0	45.7	0.56	812	0.34	0.01	0.1
STD-ME-6 expected		6130.0													
STD-ME-6 result		6499.6	5.39	3.7	<0.05	0.12	0.42	0.09	3.8	8.6	0.76	1699	20.28	0.06	0.1
TG 296337	Soil	29.1	3.63	4.3	<0.05	<0.02	0.02	0.04	8.4	40.7	0.55	424	0.44	<0.01	0.2
TG 296337 Dup		29.6	3.63	4.1	<0.05	<0.02	0.02	0.04	8.3	41.5	0.55	423	0.45	<0.01	0.1
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		624.5	>10	15.8	0.1	0.44	0.09	0.07	15.6	5.1	0.10	1087	1.42	0.02	0.5
QCV1007-00966-0034-BLK		<0.2	<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05
STD-OREAS-45P-AR expected		674.0													
STD-OREAS-45P-AR result		601.0	>10	15.1	0.1	0.42	0.09	0.07	15.3	4.3	0.09	1069	1.37	0.02	0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2
QCV1007-00966-0001-BLK		<0.2	<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2
SG 296338	Soil	18.0	620	57.5	8.1	<0.01	0.05	1.05	0.5	0.7	0.3	6.7	<0.01	0.08	0
SG 296338 Dup		18.1	616	57.8	8.1	<0.01	0.05	1.05	0.5	0.7	0.3	6.8	<0.01	0.08	0
STD-ME-6 expected				10200											
STD-ME-6 result		31.4	453	>10000	4.0	0.02	2.19	421.50	4.6	2.9	1.8	31.8	<0.01	1.81	1
SG 296356	Soil	22.3	701	78.2	4.8	<0.01	0.05	<0.05	0.5	1.0	0.4	6.5	<0.01	0.06	0
SG 296356 Dup		22.1	709	79.3	4.8	<0.01	0.05	<0.05	0.5	1.0	0.3	6.6	<0.01	0.07	0
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		317.2	373	19.3	10.5	<0.01	0.03	<0.05	56.5	0.5	1.8	16.6	<0.01	0.03	6
SG 296374	Soil	1.9	494	6.7	1.8	<0.01	0.03	<0.05	<0.1	<0.2	<0.2	7.1	<0.01	<0.01	<0.2
SG 296374 Dup		1.8	497	6.6	1.8	<0.01	0.03	<0.05	<0.1	<0.2	<0.2	7.1	<0.01	<0.01	<0.2
STD-ME-6 expected				10200											
STD-ME-6 result		30.0	452	>10000	4.0	<0.01	2.19	442.47	4.4	2.5	1.8	31.2	<0.01	1.60	1
SG 296392	Soil	7.2	777	10.1	4.1	<0.01	0.04	<0.05	0.2	0.5	<0.2	4.5	<0.01	0.03	<0.2
SG 296392 Dup		7.2	774	10.1	4.1	<0.01	0.04	<0.05	0.2	0.5	<0.2	4.6	<0.01	0.03	<0.2
STD-ME-6 expected				10200											
STD-ME-6 result		32.0	431	>10000	4.1	0.01	2.07	401.90	4.8	3.2	1.8	31.9	<0.01	1.96	1
SG 296410	Soil	24.2	718	23.4	4.7	<0.01	0.04	0.20	0.5	0.4	0.3	5.5	<0.01	0.06	0
SG 296410 Dup		24.7	719	24.6	4.7	<0.01	0.04	0.25	0.4	0.3	0.3	5.5	<0.01	0.05	0
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		303.6	372	20.5	12.9	<0.01	0.03	<0.05	57.3	0.5	2.2	18.8	<0.01	0.07	7
SG 296428	Soil	51.9	483	25.8	4.0	<0.01	0.01	0.14	1.7	0.3	<0.2	8.0	<0.01	0.10	2
SG 296428 Dup		52.6	475	25.4	4.2	<0.01	0.01	0.17	1.8	0.3	<0.2	8.1	<0.01	0.09	3
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		289.2	369	19.2	11.9	<0.01	0.03	<0.05	56.1	0.4	2.0	17.8	<0.01	0.06	6
SG 296446	Soil	35.2	1013	32.0	3.3	<0.01	0.04	0.35	0.7	0.5	<0.2	6.3	<0.01	0.13	1
SG 296446 Dup		36.4	1030	31.8	3.2	<0.01	0.04	0.36	0.7	0.5	<0.2	6.4	<0.01	0.12	1
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		293.6	361	19.7	9.8	<0.01	0.03	<0.05	54.8	0.9	2.0	15.9	<0.01	0.08	7
SG 296464	Soil	43.3	477	21.3	5.6	<0.01	0.01	<0.05	1.1	0.4	<0.2	4.9	<0.01	0.09	2
SG 296464 Dup		44.5	479	21.7	5.0	<0.01	0.01	<0.05	1.1	0.4	<0.2	4.9	<0.01	0.10	1
STD-ME-6 expected				10200											
STD-ME-6 result		27.7	436	>10000	3.5	0.01	2.12	402.24	3.7	2.2	1.8	27.2	<0.01	1.61	1
SG 296482	Soil	29.7	1109	45.6	5.4	<0.01	0.05	<0.05	0.4	0.8	0.3	7.3	<0.01	0.09	0
SG 296482 Dup		30.8	1084	45.0	5.5	<0.01	0.05	<0.05	0.4	0.8	0.3	7.3	<0.01	0.10	1
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		277.5	360	18.0	9.7	<0.01	0.03	<0.05	55.4	0.5	1.7	14.4	<0.01	0.08	6
SG 296500	Soil	16.8	458	20.8	2.8	<0.01	0.03	<0.05	0.1	<0.2	<0.2	6.9	<0.01	0.02	<0.2
SG 296500 Dup		16.9	460	21.0	2.8	<0.01	0.03	<0.05	0.1	<0.2	<0.2	6.9	<0.01	0.02	<0.2
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		268.9	348	17.8	9.1	<0.01	0.03	<0.05	55.2	0.7	1.6	13.6	<0.01	0.04	6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
		50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample Description	Sample Type	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		0.2	5	0.2	0.1	0.01	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
SI 481067	Soil	11.0	329	18.2	6.0	<0.01	0.01	<0.05	0.4	0.3	<0.2	16.3	<0.01	0.07	1
SI 481067 Dup		11.8	326	18.3	6.3	<0.01	0.01	<0.05	0.4	0.3	<0.2	16.6	<0.01	0.07	1
SM 268942	Soil	27.1	1110	38.5	6.0	<0.01	0.05	<0.05	0.5	0.5	0.2	15.6	<0.01	0.08	1
SM 268942 Dup		25.8	1126	39.2	5.9	<0.01	0.05	<0.05	0.5	0.5	0.2	15.5	<0.01	0.08	1
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		293.2	348	18.2	9.7	<0.01	0.03	<0.05	54.3	0.4	1.8	15.2	<0.01	0.05	6
SM 268960	Soil	31.8	332	60.4	2.6	<0.01	0.03	1.79	1.0	0.9	0.6	8.3	<0.01	0.14	3
SM 268960 Dup		31.4	334	60.2	2.6	<0.01	0.03	1.74	1.0	0.8	0.6	8.2	<0.01	0.14	3
STD-ME-6 expected				10200											
STD-ME-6 result		27.5	442	>10000	3.3	<0.01	2.15	388.19	3.9	2.3	1.7	26.5	<0.01	1.44	1
SM 268978	Soil	33.1	288	29.7	1.4	<0.01	0.01	1.55	1.2	<0.2	<0.2	10.1	<0.01	0.24	7
SM 268978 Dup		33.0	291	30.5	1.4	<0.01	0.01	1.55	1.2	<0.2	<0.2	10.3	<0.01	0.23	7
STD-ME-6 expected				10200											
STD-ME-6 result		28.3	443	>10000	3.3	<0.01	2.15	396.70	3.9	2.1	1.7	25.8	<0.01	1.61	1
SM 268996	Soil	26.2	705	27.7	1.9	<0.01	0.02	<0.05	0.6	0.2	<0.2	4.3	<0.01	0.05	0
SM 268996 Dup		25.8	710	26.8	1.9	<0.01	0.02	<0.05	0.6	0.2	<0.2	4.2	<0.01	0.06	0
STD-ME-6 expected				10200											
STD-ME-6 result		26.9	452	>10000	3.1	0.01	2.19	413.60	3.4	2.6	1.6	23.9	<0.01	1.55	1
TG 296337	Soil	30.1	810	29.2	5.7	<0.01	0.03	0.14	0.9	0.3	<0.2	15.4	<0.01	0.08	1
TG 296337 Dup		30.0	791	28.4	5.8	<0.01	0.03	0.15	0.9	0.3	<0.2	14.6	<0.01	0.08	1
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		274.8	365	19.2	8.1	<0.01	0.03	<0.05	53.9	<0.2	1.7	13.8	<0.01	0.10	6
QCV1007-00966-0034-BLK		<0.2	<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2
STD-OREAS-45P-AR expected		292.0		19.0				0.38							
STD-OREAS-45P-AR result		260.9	357	18.1	7.5	<0.01	0.02	<0.05	51.7	<0.2	1.6	13.5	<0.01	0.10	6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
QCV1007-00966-0001-BLK		<0.005	<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
SG 296338	Soil	0.006	0.05	1	17	10.73	2.3	80	<0.5
SG 296338 Dup		0.006	<0.05	1	17	10.33	2.3	79	<0.5
STD-ME-6 expected								5170	
STD-ME-6 result		0.097	0.21	1	48	1.84	7.2	5863	6.2
SG 296356	Soil	0.007	<0.05	1	24	3.44	3.5	113	<0.5
SG 296356 Dup		0.007	<0.05	1	24	3.54	3.5	113	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.184	0.06	1	236	0.56	9.7	145	24.0
SG 296374	Soil	<0.005	<0.05	0	7	1.02	0.3	15	<0.5
SG 296374 Dup		<0.005	<0.05	0	7	1.02	0.2	15	<0.5
STD-ME-6 expected								5170	
STD-ME-6 result		0.101	0.20	1	47	4.41	7.4	5700	6.1
SG 296392	Soil	<0.005	<0.05	1	15	2.16	1.0	27	<0.5
SG 296392 Dup		<0.005	<0.05	1	15	2.16	1.0	26	<0.5
STD-ME-6 expected								5170	
STD-ME-6 result		0.093	0.19	1	48	1.91	7.6	5630	6.4
SG 296410	Soil	0.008	<0.05	1	23	0.80	1.7	68	<0.5
SG 296410 Dup		0.008	<0.05	1	24	0.81	1.7	68	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.196	0.06	1	236	2.94	11.3	130	24.9
SG 296428	Soil	<0.005	<0.05	1	21	1.23	2.8	118	<0.5
SG 296428 Dup		<0.005	<0.05	1	22	1.28	2.9	118	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.183	0.06	1	230	3.12	10.8	118	24.2
SG 296446	Soil	<0.005	<0.05	1	19	1.84	1.8	103	1.0
SG 296446 Dup		<0.005	<0.05	1	19	1.77	1.9	102	1.0
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.159	0.06	1	227	2.95	10.0	139	22.1
SG 296464	Soil	<0.005	<0.05	1	19	1.17	1.7	114	<0.5
SG 296464 Dup		<0.005	<0.05	1	19	1.15	1.8	113	<0.5
STD-ME-6 expected								5170	
STD-ME-6 result		0.082	0.20	1	43	5.74	6.7	5536	4.9
SG 296482	Soil	0.006	<0.05	1	22	0.57	2.1	96	0.5
SG 296482 Dup		0.006	<0.05	1	23	0.61	2.1	95	0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.167	0.05	1	231	0.42	9.4	122	20.3
SG 296500	Soil	<0.005	<0.05	1	4	0.71	1.5	72	<0.5
SG 296500 Dup		<0.005	<0.05	1	4	0.67	1.5	71	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.154	<0.05	1	222	0.93	8.8	136	19.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02307-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481067	Soil	<0.005	<0.05	1	14	0.48	1.2	69	<0.5
SI 481067 Dup		<0.005	<0.05	1	13	0.45	1.2	67	<0.5
SM 268942	Soil	0.005	<0.05	1	23	0.52	2.0	96	0.8
SM 268942 Dup		0.005	<0.05	1	22	0.54	2.0	98	0.9
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.157	0.05	1	223	0.51	9.9	133	21.1
SM 268960	Soil	<0.005	<0.05	2	6	1.56	3.0	143	<0.5
SM 268960 Dup		<0.005	<0.05	2	6	1.54	2.8	143	<0.5
STD-ME-6 expected								5170	
STD-ME-6 result		0.078	0.22	1	41	0.73	6.4	5720	4.3
SM 268978	Soil	<0.005	<0.05	1	8	0.85	2.4	88	0.6
SM 268978 Dup		<0.005	<0.05	1	8	0.89	2.3	89	0.6
STD-ME-6 expected								5170	
STD-ME-6 result		0.079	0.20	1	41	2.31	6.3	5793	4.2
SM 268996	Soil	<0.005	<0.05	1	12	0.53	1.2	68	<0.5
SM 268996 Dup		<0.005	<0.05	1	12	0.47	1.2	69	<0.5
STD-ME-6 expected								5170	
STD-ME-6 result		0.067	0.20	1	38	0.54	5.7	5411	3.6
TG 296337	Soil	<0.005	<0.05	1	13	0.64	3.4	96	<0.5
TG 296337 Dup		<0.005	<0.05	1	13	0.67	3.4	95	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.144	0.06	1	224	0.56	9.4	139	18.8
QCV1007-00966-0034-BLK		<0.005	<0.05	<0.05	<1	0.06	<0.05	<1	<0.5
STD-OREAS-45P-AR expected								123	
STD-OREAS-45P-AR result		0.132	<0.05	1	220	0.36	9.2	136	11.9

Certificate of Analysis

10-360-02339-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description:

Date Received: 07/27/2010
Date Completed: 08/17/2010
Invoice:

Samples	Type	Preparation Description
102	Soil	SP-SS-1K/Soils, Humus Sediments 1kg dried, sieved and riffle split

Method	Description
50-AR-UT	50 Element, Aqua Regia, ICPMS, Ultra Trace Level
Au-1AT-AA	Au, 1AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481069	Soil	6	0.28	1.61	40.6	38	0.3	0.56	0.02	0.15	28.08	11.4	29	1.9	34.1
SI 481070	Soil	118	0.23	1.93	419.9	57	0.5	0.42	0.09	0.23	48.79	17.5	26	1.5	36.9
SI 481071	Soil	6	0.21	1.75	35.7	45	0.3	0.44	0.02	0.14	24.96	12.4	24	1.8	22.7
SI 481072	Soil	8	0.18	1.95	60.0	23	0.2	0.44	0.01	0.15	28.10	11.8	29	1.2	25.1
SI 481073	Soil	<5	0.21	1.95	37.7	44	0.4	0.41	0.04	0.26	23.35	18.0	31	2.7	30.6
SI 481074	Soil	15	0.11	2.38	48.9	35	0.4	0.53	0.01	0.15	30.29	19.5	34	1.3	38.3
SI 481075	Soil	9	0.19	1.92	33.4	37	0.4	0.54	0.03	0.13	30.83	11.7	29	1.6	29.1
SI 481076	Soil	18	0.21	1.34	15.4	63	0.3	0.34	0.04	0.32	16.03	9.1	21	2.5	29.8
SI 481077	Soil	6	0.17	1.27	9.6	53	0.3	0.24	0.03	0.19	16.87	5.2	10	2.5	23.2
SI 481078	Soil	14	0.23	1.57	59.4	43	0.3	0.46	0.02	0.22	24.02	13.6	24	2.1	34.3
SI 481079	Soil	17	0.18	1.90	103.1	33	0.4	0.52	0.01	0.24	32.64	15.0	32	1.5	35.2
SI 481080	Soil	24	0.20	1.88	272.0	28	0.3	0.48	<0.01	0.24	35.41	14.3	29	1.5	34.5
SI 481081	Soil	11	0.23	1.61	228.5	50	0.3	0.62	0.01	0.23	29.18	16.1	26	2.1	30.6
SI 481082	Soil	66	0.25	1.98	1411.0	52	0.8	0.69	0.02	0.29	31.91	36.0	25	1.6	53.4
SI 481083	Soil	14	0.16	2.15	209.4	28	0.6	0.69	0.03	0.22	30.35	25.9	31	2.0	55.4
SI 481084	Soil	35	0.15	2.28	195.8	34	0.6	0.64	0.04	0.09	38.03	22.2	35	1.6	47.6
SI 481085	Soil	21	0.21	2.25	75.7	31	0.5	0.70	0.04	0.10	29.63	19.7	36	1.5	44.0
SI 481086	Soil	26	0.26	2.39	113.5	49	0.7	0.72	0.04	0.10	35.00	20.2	35	2.4	56.9
SI 481087	Soil	25	0.29	2.24	76.4	45	0.4	0.57	0.09	0.09	38.07	17.1	35	2.3	37.5
SI 481088	Soil	15	0.22	1.96	81.7	42	0.5	0.70	0.03	0.16	36.29	18.2	29	2.8	35.5
SI 481089	Soil	26	0.28	2.23	97.3	43	0.4	0.65	0.03	0.13	39.82	20.3	32	3.2	45.6
SI 481090	Soil	24	0.29	2.15	80.3	29	0.4	0.48	<0.01	0.09	36.50	15.2	31	1.6	34.3
SI 481091	Soil	20	0.29	1.72	53.0	37	0.3	0.42	<0.01	0.14	38.76	10.7	25	3.6	28.0
SI 481092	Soil	<5	0.75	1.51	64.1	47	0.6	0.46	1.03	0.16	16.35	11.6	24	12.5	67.9
SI 481093	Soil	10	0.34	2.59	31.8	21	0.5	0.56	0.16	0.13	39.07	21.4	39	4.8	61.3
SI 481094	Soil	<5	0.48	2.03	12.5	24	0.3	0.42	0.04	0.13	35.27	24.2	32	4.1	35.3
SI 481095	Soil	8	0.37	1.90	37.7	34	0.3	0.51	0.02	0.16	34.54	13.0	26	3.9	40.2
SI 481096	Soil	18	0.27	2.11	55.8	44	0.5	0.55	0.09	0.17	48.69	22.5	32	6.9	55.4
SI 481097	Soil	<5	0.34	1.47	29.2	49	0.3	0.51	0.07	0.19	17.48	13.5	22	3.8	35.6
SI 481098	Soil	9	0.28	1.96	61.8	77	0.6	0.60	0.03	0.29	32.34	22.5	30	3.3	57.9
SI 481099	Soil	8	0.34	1.98	26.8	51	0.5	0.61	0.29	0.17	21.63	15.5	29	2.8	44.2
SI 481100	Soil	13	0.21	1.91	86.4	70	0.5	0.67	0.09	0.36	29.90	20.5	32	2.2	42.2
SI 481101	Soil	22	0.42	2.35	195.7	36	0.6	0.67	0.07	0.50	34.17	24.6	35	2.1	56.6
SI 481102	Soil	7	0.28	2.46	44.1	27	0.6	1.07	0.03	0.15	33.84	32.5	36	3.4	79.0
SI 481103	Soil	8	0.61	1.82	27.4	43	0.4	0.62	0.17	0.19	19.24	17.2	28	2.5	38.0
SI 481104	Soil	<5	0.34	2.04	25.1	33	0.4	0.64	0.01	0.21	14.05	17.1	30	1.8	37.3
SI 481105	Soil	6	0.24	1.71	32.6	101	0.3	0.58	0.03	0.19	12.40	16.5	32	2.9	29.4
SI 481106	Soil	11	0.36	1.28	29.2	72	0.3	0.49	0.09	0.15	7.67	13.2	27	1.6	34.4
SI 481107	Soil	10	0.21	2.15	36.9	19	0.3	0.57	0.06	0.14	17.37	15.9	33	1.4	28.9
SI 481108	Soil	6	0.30	2.17	13.6	30	0.5	0.54	0.06	0.14	6.88	18.0	33	2.6	40.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481109	Soil	6	0.25	2.12	20.8	23	0.6	0.61	0.04	0.19	10.03	25.7	34	4.1	70.5
SI 481110	Soil	6	0.22	1.96	28.6	39	0.7	0.68	0.04	0.19	9.46	36.8	29	3.8	62.1
SI 481111	Soil	9	0.26	1.32	15.3	42	0.5	0.36	0.04	0.20	8.52	13.7	14	2.3	45.7
SI 481112	Soil	<5	0.24	1.97	29.4	32	0.7	0.67	0.09	0.08	12.66	23.4	26	3.9	84.5
SI 481113	Soil	6	0.19	1.92	16.4	41	0.3	0.47	0.04	0.19	9.87	18.9	28	2.7	47.0
SI 481114	Soil	7	0.30	1.41	35.6	33	0.4	0.56	0.02	0.16	12.91	13.0	23	2.9	43.1
SI 481115	Soil	10	0.23	0.52	40.9	60	0.1	0.49	<0.01	0.08	12.50	8.6	10	1.7	21.8
SI 481116	Soil	16	0.24	1.65	68.0	25	0.5	0.37	0.05	0.12	18.48	28.7	25	2.3	52.9
SI 481117	Soil	<5	0.20	0.89	4.9	20	0.1	0.11	0.03	0.06	6.91	3.6	8	0.7	9.6
SI 481118	Soil	7	0.22	1.88	86.0	36	0.5	0.47	0.02	0.17	17.43	27.6	28	1.5	54.0
SI 481119	Soil	132	0.31	0.97	365.3	21	0.2	0.49	<0.01	0.34	14.70	11.3	15	0.9	33.4
SI 481120	Soil	72	0.38	1.46	384.0	26	0.4	0.72	0.01	0.48	12.67	18.1	23	1.7	54.2
SI 481121	Soil	69	0.45	0.91	361.5	26	0.2	0.80	0.01	0.25	14.24	10.2	16	1.7	27.1
SI 481122	Soil	9	0.34	1.87	49.3	20	0.5	0.55	0.01	0.15	36.45	27.9	28	2.9	57.0
SI 481123	Soil	32	0.39	1.05	51.7	23	0.2	0.33	0.03	0.07	27.36	5.3	17	2.6	18.4
SI 481124	Soil	35	0.31	1.75	122.7	36	0.4	0.52	0.01	0.13	39.42	13.9	26	3.8	42.2
SI 481125	Soil	22	0.26	1.77	130.7	42	0.3	0.48	0.01	0.12	47.72	12.8	27	2.9	32.6
SI 481126	Soil	10	0.42	1.92	76.9	33	0.5	0.59	0.01	0.12	44.47	14.2	25	4.9	56.4
SI 481127	Soil	30	0.29	2.14	163.0	37	0.3	0.51	0.01	0.12	52.77	15.0	32	4.5	38.6
SI 481128	Soil	110	0.27	2.01	199.3	35	0.3	0.43	<0.01	0.17	58.13	14.5	30	4.3	41.9
SI 481129	Soil	6	0.25	2.60	29.8	19	0.5	0.63	0.03	0.13	57.11	18.2	42	6.3	58.8
SI 481130	Soil	8	0.22	2.29	27.1	31	0.3	0.63	0.04	0.15	54.15	23.8	36	4.6	43.9
SI 481131	Soil	45	0.19	1.67	197.9	33	0.2	0.49	0.01	0.21	39.29	14.4	27	3.2	31.4
SI 481132	Soil	46	0.26	1.94	86.1	32	0.3	0.52	0.03	0.11	54.80	10.7	33	4.1	29.7
SI 481133	Soil	9	0.28	2.19	42.1	24	0.4	0.60	0.02	0.13	55.38	30.0	31	5.8	56.8
SI 481134	Soil	<5	0.25	1.93	11.0	30	0.2	0.42	0.02	0.12	45.85	10.9	32	4.6	16.0
SI 481135	Soil	24	0.24	2.57	56.4	32	0.4	0.45	0.04	0.09	89.95	17.5	37	2.0	40.8
SI 481136	Soil	14	0.18	2.60	55.0	25	0.4	0.65	<0.01	0.10	85.83	20.3	36	2.5	52.0
SI 481137	Soil	45	0.22	1.97	163.0	42	0.4	0.43	<0.01	0.10	57.65	15.4	29	5.4	36.2
SI 481138	Soil	15	0.31	2.39	73.7	44	0.5	0.41	0.04	0.13	45.45	16.3	31	2.2	33.7
SI 481139	Soil	50	0.55	2.55	52.6	36	0.4	0.60	0.13	0.10	44.46	20.4	39	4.5	66.7
SI 481140	Soil	29	0.37	1.72	62.8	35	0.3	0.54	0.06	0.34	28.27	16.6	29	2.8	30.5
SI 481141	Soil	141	0.35	1.93	227.3	38	0.6	0.58	0.06	0.15	37.64	22.5	26	2.0	49.1
SI 481142	Soil	69	0.28	1.85	155.3	30	0.3	0.62	0.02	0.12	43.83	15.0	28	2.4	39.4
SI 481143	Soil	40	0.37	1.38	99.0	19	0.3	0.47	0.02	0.11	32.55	12.2	19	1.8	33.9
SI 481144	Soil	38	0.34	2.17	85.2	27	0.5	0.58	0.04	0.15	57.71	19.4	33	4.2	50.9
SI 481145	Soil	7	0.33	1.76	44.4	32	0.3	1.05	<0.01	0.12	43.35	21.7	24	3.4	111.5
SI 481146	Soil	17	0.37	1.54	175.2	24	0.2	0.49	0.01	0.12	46.91	10.6	25	2.9	31.5
SI 481147	Soil	<5	0.28	2.63	11.2	15	0.3	0.52	0.03	0.10	59.51	17.1	40	3.8	42.9
SI 481148	Soil	<5	0.30	1.81	63.5	24	0.3	0.53	<0.01	0.06	57.00	8.0	30	3.4	45.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481149	Soil	19	0.28	1.63	16.0	20	0.2	0.54	0.01	0.09	41.52	12.0	28	4.5	30.1
SI 481150	Soil	143	0.24	2.33	121.7	23	0.3	0.52	<0.01	0.13	43.21	16.4	37	2.8	36.4
SI 481151	Soil	12	0.24	1.82	70.0	33	0.3	0.56	<0.01	0.14	52.27	14.3	27	3.6	36.7
SI 481152	Soil	22	0.26	1.96	72.1	31	0.2	0.46	0.01	0.12	55.06	12.2	31	4.9	26.9
SI 481153	Soil	7	0.19	1.60	39.3	41	0.2	0.47	0.02	0.11	49.79	11.7	28	5.3	24.7
SI 481154	Soil	11	0.41	1.65	74.2	22	0.2	1.45	<0.01	0.10	49.51	6.6	31	3.9	37.1
SI 481155	Soil	15	0.42	2.08	48.9	49	0.8	0.63	0.54	0.09	37.22	21.3	31	14.6	77.5
SI 481156	Soil	6	0.29	2.29	33.6	39	0.7	0.74	0.17	0.29	54.03	24.7	32	2.9	49.3
SI 481157	Soil	9	0.62	1.50	27.7	28	0.3	0.49	0.02	0.10	40.08	14.2	24	3.3	35.3
SI 481158	Soil	11	0.26	2.74	32.6	97	1.0	0.59	0.18	0.18	64.62	23.7	42	4.1	60.2
SI 481159	Soil	31	0.25	2.07	71.5	37	0.4	0.43	0.03	0.06	36.70	14.2	29	1.2	33.8
SI 481160	Soil	53	0.27	2.22	94.1	30	0.4	0.45	0.01	0.09	41.63	15.4	31	1.7	34.1
SI 481161	Soil	12	0.28	2.39	49.2	22	0.5	0.90	0.04	0.18	28.42	41.8	35	2.2	69.9
SI 481162	Soil	7	0.25	2.66	18.6	33	0.4	0.59	0.07	0.17	33.62	15.4	39	3.2	32.5
SI 481163	Soil	<5	0.24	3.19	18.4	13	0.2	0.64	0.10	0.12	42.00	18.0	48	2.6	34.6
SI 481164	Soil	<5	0.30	1.96	9.3	19	0.2	0.37	0.02	0.10	37.05	10.4	31	2.0	26.5
TI 480048	Soil	6	0.35	1.79	39.6	23	0.5	0.51	0.36	0.13	28.61	20.5	25	0.6	53.4
TI 480049	Soil	5	0.36	1.85	56.2	19	0.4	0.46	0.36	0.13	27.02	20.1	29	0.4	41.7
TI 480050	Soil	7	0.28	1.86	32.2	25	0.4	0.50	0.34	0.11	22.20	22.7	25	0.7	51.3
TI 480095	Soil	69	0.28	1.98	61.1	21	0.5	0.54	0.33	0.10	21.62	20.4	29	2.3	56.2
TI 480096	Soil	55	0.30	1.38	95.2	25	0.4	0.42	0.15	0.09	26.59	14.5	19	1.0	49.6
TI 480150	Soil	6	0.42	1.47	31.2	19	0.4	0.40	0.54	0.08	16.30	12.1	25	0.7	35.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481069	Soil	4.82	7.9	<0.05	<0.02	0.03	0.04	14.4	28.6	0.44	1220	1.00	<0.01	0.6	25.3
SI 481070	Soil	4.26	4.8	<0.05	<0.02	0.02	0.03	25.7	47.9	0.75	855	0.78	<0.01	0.4	42.2
SI 481071	Soil	3.95	6.0	<0.05	<0.02	0.02	0.03	12.5	33.1	0.50	810	0.92	0.01	0.5	26.0
SI 481072	Soil	4.90	6.8	<0.05	<0.02	0.02	0.03	15.2	49.3	0.75	437	0.61	<0.01	0.5	32.2
SI 481073	Soil	5.41	7.4	<0.05	<0.02	0.02	0.03	12.5	44.0	0.66	1951	0.77	<0.01	0.4	31.5
SI 481074	Soil	5.41	6.6	<0.05	<0.02	0.03	0.03	15.9	70.4	1.00	877	0.59	<0.01	0.1	47.9
SI 481075	Soil	4.06	6.3	<0.05	<0.02	0.03	0.03	16.9	43.0	0.67	432	0.77	<0.01	0.5	30.9
SI 481076	Soil	3.04	5.2	<0.05	<0.02	0.02	0.02	8.9	17.1	0.23	1296	0.58	<0.01	0.3	15.3
SI 481077	Soil	1.56	4.3	<0.05	<0.02	0.01	0.02	9.1	4.9	0.08	673	0.55	0.01	0.3	6.4
SI 481078	Soil	4.04	4.5	<0.05	<0.02	0.02	0.03	13.3	34.0	0.45	934	0.42	<0.01	0.1	27.0
SI 481079	Soil	5.05	6.3	<0.05	<0.02	0.03	0.03	17.7	50.7	0.71	760	0.59	<0.01	0.3	36.8
SI 481080	Soil	4.91	5.8	<0.05	<0.02	0.03	0.03	19.7	52.7	0.72	489	0.68	<0.01	0.2	38.6
SI 481081	Soil	4.31	6.4	<0.05	<0.02	0.03	0.03	15.7	32.1	0.45	1418	0.72	<0.01	0.3	25.1
SI 481082	Soil	5.67	4.1	<0.05	<0.02	0.05	0.02	16.2	45.5	0.61	1654	0.80	<0.01	0.2	53.4
SI 481083	Soil	4.91	5.9	<0.05	<0.02	0.03	0.03	16.3	64.9	0.90	733	0.56	<0.01	0.1	46.6
SI 481084	Soil	5.39	6.4	<0.05	<0.02	0.04	0.02	20.5	73.6	0.95	804	0.50	<0.01	0.1	51.2
SI 481085	Soil	5.15	6.4	<0.05	<0.02	0.04	0.02	15.7	70.0	0.93	661	0.56	<0.01	0.1	43.8
SI 481086	Soil	5.34	7.2	<0.05	<0.02	0.04	0.03	18.2	67.9	0.90	681	0.53	<0.01	0.1	47.8
SI 481087	Soil	5.22	7.1	<0.05	<0.02	0.03	0.03	21.4	65.6	0.89	719	0.61	<0.01	0.1	46.5
SI 481088	Soil	4.62	6.4	<0.05	<0.02	0.03	0.03	20.2	54.3	0.71	892	0.52	<0.01	0.2	39.2
SI 481089	Soil	5.36	7.4	<0.05	<0.02	0.03	0.03	22.8	63.7	0.87	605	0.52	<0.01	0.1	45.0
SI 481090	Soil	5.08	6.3	<0.05	<0.02	0.03	0.02	19.6	58.2	0.83	423	0.51	<0.01	0.2	44.3
SI 481091	Soil	4.24	6.6	<0.05	<0.02	0.02	0.03	22.1	39.6	0.56	438	0.57	<0.01	0.2	28.4
SI 481092	Soil	2.86	4.2	<0.05	<0.02	0.03	0.03	9.5	45.5	0.49	318	0.48	0.02	0.2	30.3
SI 481093	Soil	5.31	7.4	<0.05	<0.02	0.03	0.02	22.3	86.4	1.15	525	0.47	<0.01	<0.05	57.9
SI 481094	Soil	4.37	6.6	<0.05	<0.02	0.03	0.02	22.1	57.0	0.84	1193	0.37	<0.01	0.1	40.3
SI 481095	Soil	3.91	6.1	<0.05	0.02	0.03	0.02	19.8	45.6	0.67	434	0.49	<0.01	0.1	33.7
SI 481096	Soil	4.62	7.0	<0.05	<0.02	0.03	0.03	28.1	60.9	0.84	813	0.54	<0.01	0.1	45.1
SI 481097	Soil	3.68	5.8	<0.05	<0.02	0.03	0.03	9.0	33.1	0.52	472	0.45	0.01	0.2	29.3
SI 481098	Soil	4.78	7.0	<0.05	<0.02	0.04	0.04	16.9	40.9	0.61	1386	0.50	0.01	0.4	40.8
SI 481099	Soil	4.22	6.3	<0.05	<0.02	0.03	0.02	11.6	56.8	0.78	641	0.65	0.01	0.2	38.7
SI 481100	Soil	4.45	6.2	<0.05	<0.02	0.03	0.04	15.3	48.3	0.74	1076	0.62	<0.01	0.4	41.0
SI 481101	Soil	5.84	6.8	0.1	<0.02	0.05	0.03	18.0	66.5	0.95	825	0.70	<0.01	0.2	49.9
SI 481102	Soil	5.62	7.3	0.1	<0.02	0.04	0.02	17.1	72.6	1.04	982	0.67	<0.01	0.1	49.8
SI 481103	Soil	4.20	5.5	0.1	<0.02	0.03	0.02	10.3	44.3	0.63	1080	0.53	<0.01	0.1	33.0
SI 481104	Soil	5.19	6.9	<0.05	0.04	0.04	0.01	7.2	54.0	0.75	934	0.63	<0.01	0.1	35.4
SI 481105	Soil	4.60	6.5	<0.05	0.04	0.02	0.04	6.6	32.4	0.52	1206	0.84	<0.01	0.5	26.5
SI 481106	Soil	4.34	5.7	<0.05	<0.02	0.02	0.02	4.0	22.5	0.30	1556	0.52	<0.01	0.2	21.6
SI 481107	Soil	4.68	6.4	<0.05	<0.02	0.03	0.02	8.8	61.8	0.94	560	0.61	<0.01	0.3	41.9
SI 481108	Soil	5.00	6.7	0.1	0.03	0.03	0.02	3.2	55.2	0.85	890	0.42	<0.01	0.1	37.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481109	Soil	5.48	6.8	0.1	0.07	0.05	0.02	4.8	58.0	0.80	1063	0.62	<0.01	0.1	39.9
SI 481110	Soil	4.74	6.0	0.1	0.03	0.04	0.02	4.6	53.3	0.74	1355	0.68	<0.01	0.1	40.5
SI 481111	Soil	2.60	4.5	<0.05	0.02	0.06	0.02	4.1	25.3	0.35	1603	0.46	0.01	0.2	21.9
SI 481112	Soil	4.49	6.2	0.1	<0.02	0.05	0.02	6.7	56.3	0.79	692	0.72	<0.01	0.1	38.0
SI 481113	Soil	4.61	6.9	0.1	0.05	0.03	0.02	5.4	50.4	0.70	923	0.52	<0.01	0.2	35.6
SI 481114	Soil	4.09	5.0	<0.05	0.02	0.03	0.02	6.4	23.9	0.37	692	0.60	<0.01	0.2	25.7
SI 481115	Soil	2.96	2.6	<0.05	<0.02	0.02	0.01	6.8	4.2	0.10	640	0.45	<0.01	0.1	16.4
SI 481116	Soil	3.51	4.8	0.1	<0.02	0.02	0.02	9.6	45.8	0.63	672	0.67	<0.01	0.1	37.6
SI 481117	Soil	1.11	3.0	0.1	<0.02	<0.01	0.01	3.5	11.4	0.19	221	0.32	0.01	0.2	7.3
SI 481118	Soil	4.79	5.7	0.1	0.03	0.03	0.02	8.5	52.9	0.77	1735	0.95	<0.01	0.2	45.1
SI 481119	Soil	4.36	4.0	0.1	<0.02	0.03	0.02	8.3	18.0	0.24	272	0.68	<0.01	0.1	27.4
SI 481120	Soil	4.73	4.2	0.1	<0.02	0.06	0.02	6.7	28.2	0.39	621	0.86	<0.01	0.1	38.1
SI 481121	Soil	4.05	4.6	0.1	<0.02	0.04	0.02	7.7	15.3	0.24	334	0.73	<0.01	0.3	23.7
SI 481122	Soil	4.57	4.7	0.1	<0.02	0.03	0.02	21.3	46.9	0.67	532	0.57	<0.01	<0.05	48.3
SI 481123	Soil	2.70	4.7	0.1	<0.02	0.02	0.03	16.0	19.8	0.28	224	0.56	0.01	0.4	14.9
SI 481124	Soil	4.83	6.1	0.1	<0.02	0.03	0.03	22.2	36.9	0.49	1004	0.55	<0.01	0.2	28.3
SI 481125	Soil	4.41	6.2	0.1	<0.02	0.03	0.04	27.4	34.1	0.45	645	0.84	<0.01	0.3	27.4
SI 481126	Soil	4.73	6.0	0.1	<0.02	0.03	0.03	25.3	42.4	0.59	555	0.73	0.01	0.2	35.8
SI 481127	Soil	5.35	6.5	0.1	<0.02	0.03	0.05	29.1	54.3	0.74	580	0.68	<0.01	0.3	38.5
SI 481128	Soil	5.65	6.0	0.1	<0.02	0.04	0.04	34.4	54.9	0.78	1084	0.53	0.01	0.1	37.8
SI 481129	Soil	5.41	8.0	0.1	<0.02	0.04	0.03	33.8	87.2	1.13	586	0.39	<0.01	0.1	52.0
SI 481130	Soil	5.19	7.1	0.1	<0.02	0.03	0.03	30.8	70.2	1.01	747	0.60	<0.01	0.2	46.9
SI 481131	Soil	4.63	6.1	0.1	<0.02	0.03	0.03	21.9	38.5	0.51	706	0.61	<0.01	0.3	31.3
SI 481132	Soil	4.26	7.6	0.1	<0.02	0.03	0.04	31.3	50.3	0.71	320	0.87	<0.01	0.3	34.0
SI 481133	Soil	4.52	6.5	0.1	<0.02	0.04	0.03	31.8	64.7	0.88	960	0.61	0.01	0.1	46.5
SI 481134	Soil	4.10	8.3	0.1	<0.02	0.02	0.03	23.9	53.6	0.69	393	0.74	<0.01	0.3	32.2
SI 481135	Soil	5.32	7.4	0.1	<0.02	0.03	0.03	50.6	82.2	1.08	491	0.39	<0.01	<0.05	58.0
SI 481136	Soil	5.94	7.2	0.1	<0.02	0.03	0.02	48.5	77.1	1.08	457	0.83	<0.01	0.1	54.8
SI 481137	Soil	4.95	5.8	0.1	<0.02	0.03	0.03	32.6	51.7	0.67	413	0.66	<0.01	0.1	43.1
SI 481138	Soil	4.73	6.7	0.1	<0.02	0.03	0.04	24.7	61.8	0.88	670	0.58	0.01	0.2	41.9
SI 481139	Soil	5.70	7.1	0.1	<0.02	0.04	0.04	24.1	81.6	1.07	630	0.55	<0.01	0.1	57.2
SI 481140	Soil	4.81	7.1	<0.05	<0.02	0.03	0.03	15.3	36.0	0.56	869	0.74	<0.01	0.5	31.3
SI 481141	Soil	5.35	4.8	<0.05	<0.02	0.04	0.03	19.8	49.4	0.66	951	0.51	<0.01	0.2	49.3
SI 481142	Soil	5.26	6.8	0.1	<0.02	0.03	0.03	24.2	45.6	0.61	571	0.61	<0.01	0.3	33.2
SI 481143	Soil	3.39	4.7	<0.05	<0.02	0.02	0.02	17.8	36.3	0.47	368	0.43	0.01	0.1	27.2
SI 481144	Soil	5.29	7.4	0.1	<0.02	0.03	0.03	33.9	65.8	0.85	524	0.51	<0.01	0.2	43.2
SI 481145	Soil	4.87	6.7	0.1	<0.02	0.03	0.02	25.0	48.0	0.63	865	1.57	<0.01	<0.05	38.4
SI 481146	Soil	4.59	6.7	0.1	<0.02	0.03	0.03	26.6	37.8	0.47	370	0.58	<0.01	0.3	27.6
SI 481147	Soil	5.83	9.0	0.1	<0.02	0.03	0.02	35.7	82.2	1.15	602	0.33	0.03	<0.05	52.6
SI 481148	Soil	4.93	7.0	0.1	<0.02	0.04	0.02	32.1	42.8	0.56	280	0.57	<0.01	0.1	31.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481149	Soil	3.96	7.0	0.1	<0.02	0.02	0.03	23.7	44.6	0.65	751	0.50	<0.01	0.2	29.7
SI 481150	Soil	5.66	7.8	0.1	<0.02	0.03	0.02	24.3	68.0	0.93	473	0.45	<0.01	0.2	44.4
SI 481151	Soil	4.35	7.9	0.1	<0.02	0.03	0.02	30.0	43.7	0.59	787	0.51	<0.01	0.2	30.3
SI 481152	Soil	4.88	8.6	0.1	<0.02	0.03	0.02	30.7	47.1	0.67	480	0.58	<0.01	0.3	31.6
SI 481153	Soil	4.14	8.1	0.1	<0.02	0.02	0.04	28.4	30.9	0.48	525	0.81	<0.01	0.3	24.5
SI 481154	Soil	5.35	7.5	0.1	<0.02	0.02	0.03	28.7	39.1	0.58	371	0.82	0.01	0.2	24.7
SI 481155	Soil	4.37	7.1	0.1	<0.02	0.03	0.04	21.0	65.0	0.81	729	0.53	0.01	0.4	47.5
SI 481156	Soil	5.94	6.6	0.1	<0.02	0.06	0.02	27.2	69.4	0.88	2723	0.49	<0.01	0.1	49.3
SI 481157	Soil	3.90	6.6	0.1	<0.02	0.03	0.03	21.4	36.4	0.51	910	0.51	0.01	0.1	26.1
SI 481158	Soil	6.21	8.4	0.1	<0.02	0.06	0.05	31.9	53.4	0.96	2560	0.48	<0.01	0.5	48.8
SI 481159	Soil	4.45	6.6	0.1	<0.02	0.02	0.02	19.8	62.5	0.87	463	0.37	<0.01	0.1	39.5
SI 481160	Soil	5.13	7.0	0.1	<0.02	0.02	0.03	22.8	61.7	0.86	484	0.40	<0.01	0.1	42.2
SI 481161	Soil	6.62	7.6	0.1	<0.02	0.05	0.02	15.3	70.8	1.00	1025	0.81	<0.01	0.1	50.0
SI 481162	Soil	5.40	9.4	0.1	<0.02	0.04	0.03	16.9	74.1	0.99	589	0.58	<0.01	0.2	40.0
SI 481163	Soil	6.14	10.6	0.1	<0.02	0.04	0.02	22.1	103.6	1.35	482	0.43	<0.01	<0.05	54.8
SI 481164	Soil	3.85	7.5	0.1	0.03	0.02	0.02	19.9	48.2	0.69	403	0.37	0.01	0.1	29.8
TI 480048	Soil	4.08	5.1	0.1	<0.02	0.03	0.04	15.7	51.1	0.96	636	0.42	<0.01	<0.05	40.1
TI 480049	Soil	4.06	5.6	0.1	<0.02	0.02	0.03	13.9	61.9	0.96	613	0.35	<0.01	<0.05	41.8
TI 480050	Soil	3.89	5.1	0.1	<0.02	0.02	0.04	12.0	49.9	0.91	787	0.54	<0.01	0.1	38.9
TI 480095	Soil	4.89	6.5	0.1	<0.02	0.03	0.02	11.1	59.7	0.85	505	0.42	<0.01	<0.05	49.1
TI 480096	Soil	4.13	4.9	0.1	<0.02	0.02	0.03	14.9	41.6	0.49	364	0.50	<0.01	0.1	36.2
TI 480150	Soil	2.94	4.2	0.1	<0.02	0.02	0.04	8.5	32.7	0.55	281	0.51	<0.01	0.1	29.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481069	Soil	1786	37.8	7.5	<0.01	0.08	<0.05	0.6	0.8	0.3	6.2	<0.01	0.24	0	0.010
SI 481070	Soil	695	31.7	5.1	<0.01	0.02	0.37	2.3	0.5	0.3	15.0	<0.01	0.26	5	0.019
SI 481071	Soil	626	27.2	4.7	<0.01	0.04	<0.05	0.5	0.8	0.3	6.7	<0.01	0.23	0	0.009
SI 481072	Soil	569	15.7	4.5	<0.01	0.03	<0.05	0.9	0.8	<0.2	4.6	<0.01	0.26	1	0.008
SI 481073	Soil	1448	37.1	4.8	<0.01	0.07	<0.05	0.6	0.9	0.2	7.4	0.01	0.31	0	0.008
SI 481074	Soil	607	38.3	3.4	<0.01	0.02	<0.05	1.2	0.7	<0.2	5.1	<0.01	0.29	1	<0.005
SI 481075	Soil	862	24.6	4.3	<0.01	0.03	<0.05	0.7	1.0	0.3	6.6	<0.01	0.28	0	0.009
SI 481076	Soil	1130	22.6	3.1	<0.01	0.07	0.16	0.3	0.8	<0.2	7.3	<0.01	0.34	<0.2	<0.005
SI 481077	Soil	1165	14.3	3.3	<0.01	0.09	0.06	0.2	0.9	<0.2	6.9	<0.01	0.36	<0.2	<0.005
SI 481078	Soil	1182	27.7	5.1	<0.01	0.04	<0.05	0.5	0.5	<0.2	7.7	<0.01	0.43	1	<0.005
SI 481079	Soil	1058	35.3	4.5	<0.01	0.04	<0.05	0.8	0.8	<0.2	6.6	<0.01	0.58	1	0.005
SI 481080	Soil	764	38.4	4.7	<0.01	0.03	<0.05	0.7	1.0	<0.2	6.0	<0.01	0.64	1	<0.005
SI 481081	Soil	1200	34.6	7.3	<0.01	0.04	<0.05	0.5	1.8	<0.2	5.4	<0.01	1.41	0	<0.005
SI 481082	Soil	551	54.0	2.7	<0.01	0.02	2.28	1.5	0.8	<0.2	14.5	<0.01	0.25	2	<0.005
SI 481083	Soil	596	40.9	3.0	<0.01	0.02	<0.05	0.9	0.5	<0.2	5.4	<0.01	0.25	1	<0.005
SI 481084	Soil	405	39.7	3.0	<0.01	<0.01	0.06	1.7	0.4	<0.2	6.3	<0.01	0.26	3	<0.005
SI 481085	Soil	435	47.8	3.0	<0.01	<0.01	<0.05	1.5	0.5	<0.2	5.0	<0.01	0.28	3	<0.005
SI 481086	Soil	738	41.7	5.1	<0.01	0.01	<0.05	1.2	0.4	<0.2	7.2	<0.01	0.25	2	<0.005
SI 481087	Soil	504	33.1	4.9	<0.01	0.01	<0.05	1.5	0.4	<0.2	8.7	<0.01	0.20	2	<0.005
SI 481088	Soil	460	42.8	4.2	<0.01	0.02	<0.05	1.1	0.4	<0.2	6.1	<0.01	0.25	1	<0.005
SI 481089	Soil	438	35.8	5.1	<0.01	0.01	<0.05	1.4	0.3	<0.2	7.0	<0.01	0.16	2	<0.005
SI 481090	Soil	459	30.6	4.2	<0.01	0.01	<0.05	1.4	0.6	<0.2	4.4	<0.01	0.19	2	<0.005
SI 481091	Soil	771	22.3	7.1	<0.01	0.01	<0.05	0.7	0.3	<0.2	5.1	<0.01	0.18	1	<0.005
SI 481092	Soil	722	34.4	4.3	<0.01	0.08	<0.05	0.8	2.6	<0.2	34.9	<0.01	0.22	1	<0.005
SI 481093	Soil	504	29.5	2.4	<0.01	0.01	<0.05	2.2	0.6	<0.2	7.8	<0.01	0.20	6	<0.005
SI 481094	Soil	740	32.9	3.2	<0.01	0.02	<0.05	0.8	0.4	<0.2	3.5	<0.01	0.19	1	<0.005
SI 481095	Soil	833	30.4	4.3	<0.01	0.02	<0.05	0.7	0.4	<0.2	5.6	<0.01	0.17	1	<0.005
SI 481096	Soil	663	40.8	4.8	<0.01	0.01	<0.05	0.8	<0.2	<0.2	8.5	<0.01	0.22	1	<0.005
SI 481097	Soil	948	25.8	5.3	<0.01	0.03	0.16	0.6	0.5	<0.2	7.8	<0.01	0.19	1	<0.005
SI 481098	Soil	946	37.5	7.1	<0.01	0.02	<0.05	0.8	0.3	<0.2	7.8	<0.01	0.19	1	<0.005
SI 481099	Soil	944	27.2	4.8	<0.01	0.04	<0.05	1.1	0.7	<0.2	15.9	<0.01	0.23	1	<0.005
SI 481100	Soil	1127	40.4	6.3	<0.01	0.03	<0.05	0.8	<0.2	<0.2	14.9	<0.01	0.19	1	0.007
SI 481101	Soil	678	90.7	3.4	<0.01	0.02	<0.05	1.2	0.6	<0.2	9.2	<0.01	0.22	1	<0.005
SI 481102	Soil	614	54.9	3.1	<0.01	0.02	<0.05	1.8	0.6	<0.2	4.0	<0.01	0.29	2	<0.005
SI 481103	Soil	926	28.0	4.0	<0.01	0.03	<0.05	0.7	0.6	<0.2	9.0	<0.01	0.20	1	<0.005
SI 481104	Soil	1016	30.4	2.6	<0.01	0.03	<0.05	0.8	0.3	<0.2	3.5	<0.01	0.20	1	<0.005
SI 481105	Soil	1613	28.7	9.5	<0.01	0.05	0.11	0.5	<0.2	<0.2	12.4	<0.01	0.17	1	0.007
SI 481106	Soil	2325	31.4	3.0	<0.01	0.08	<0.05	0.2	0.3	<0.2	9.8	<0.01	0.13	<0.2	<0.005
SI 481107	Soil	580	23.7	3.2	<0.01	0.01	<0.05	1.2	0.5	<0.2	4.2	<0.01	0.20	2	0.007
SI 481108	Soil	1143	32.4	2.6	<0.01	0.04	<0.05	1.0	0.4	<0.2	5.1	<0.01	0.24	1	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481109	Soil	1252	67.0	3.8	<0.01	0.03	0.25	1.3	0.7	<0.2	3.0	<0.01	0.18	2	<0.005
SI 481110	Soil	960	72.4	3.1	<0.01	0.03	1.28	1.2	0.5	<0.2	4.5	<0.01	0.26	1	<0.005
SI 481111	Soil	806	40.8	2.7	<0.01	0.05	0.24	0.7	0.9	<0.2	6.3	<0.01	0.14	0	0.006
SI 481112	Soil	922	74.9	3.3	<0.01	0.02	0.91	1.5	0.6	<0.2	10.5	<0.01	0.19	3	<0.005
SI 481113	Soil	1333	31.7	3.4	<0.01	0.04	0.06	0.8	0.6	<0.2	4.9	<0.01	0.17	1	0.005
SI 481114	Soil	1331	28.8	4.1	<0.01	0.05	0.77	0.7	0.4	<0.2	4.0	<0.01	0.24	1	<0.005
SI 481115	Soil	731	19.9	3.9	<0.01	0.03	0.94	0.2	0.2	<0.2	4.4	<0.01	0.24	<0.2	<0.005
SI 481116	Soil	767	61.3	2.0	<0.01	0.02	0.82	0.5	0.3	<0.2	5.7	<0.01	0.12	0	<0.005
SI 481117	Soil	687	7.1	1.5	<0.01	0.04	<0.05	0.2	0.4	<0.2	4.2	<0.01	0.08	<0.2	<0.005
SI 481118	Soil	1326	40.4	3.0	<0.01	0.05	0.37	0.8	0.4	<0.2	30.9	<0.01	0.19	1	0.005
SI 481119	Soil	533	47.4	4.0	<0.01	0.02	2.23	0.9	0.5	<0.2	8.3	<0.01	0.20	2	<0.005
SI 481120	Soil	671	84.1	3.6	<0.01	0.02	0.80	0.8	0.7	<0.2	6.7	<0.01	0.16	1	<0.005
SI 481121	Soil	554	71.9	3.1	<0.01	0.02	0.56	0.2	0.5	<0.2	5.6	<0.01	0.19	0	0.005
SI 481122	Soil	381	41.3	4.0	<0.01	<0.01	<0.05	1.2	<0.2	<0.2	4.0	<0.01	0.16	3	<0.005
SI 481123	Soil	536	15.4	5.0	<0.01	0.03	<0.05	0.3	0.4	0.3	5.8	<0.01	0.11	<0.2	0.009
SI 481124	Soil	1043	39.4	5.5	<0.01	0.03	<0.05	0.6	0.5	<0.2	5.3	<0.01	0.13	2	<0.005
SI 481125	Soil	904	32.7	6.8	<0.01	0.02	<0.05	0.4	0.3	<0.2	7.0	<0.01	0.17	0	0.006
SI 481126	Soil	752	38.9	6.3	<0.01	0.03	0.07	0.7	0.4	<0.2	5.3	<0.01	0.22	1	<0.005
SI 481127	Soil	696	34.9	7.2	<0.01	0.02	<0.05	0.8	0.5	<0.2	7.0	<0.01	0.18	1	0.006
SI 481128	Soil	701	44.2	5.2	<0.01	0.03	<0.05	0.9	0.5	<0.2	5.5	<0.01	0.13	2	<0.005
SI 481129	Soil	595	75.8	4.1	<0.01	0.02	<0.05	1.2	0.6	<0.2	3.2	<0.01	0.10	3	<0.005
SI 481130	Soil	775	38.4	4.1	<0.01	0.02	<0.05	1.1	0.4	<0.2	4.8	<0.01	0.16	2	<0.005
SI 481131	Soil	759	41.8	4.4	<0.01	0.02	<0.05	0.6	0.5	<0.2	5.4	<0.01	0.15	1	<0.005
SI 481132	Soil	767	38.8	7.1	<0.01	0.03	<0.05	0.7	0.5	0.3	8.2	<0.01	0.14	0	0.009
SI 481133	Soil	550	37.1	4.5	<0.01	0.02	0.18	1.7	0.4	<0.2	5.4	<0.01	0.20	4	<0.005
SI 481134	Soil	841	15.5	6.9	<0.01	0.02	<0.05	0.6	0.3	0.3	5.9	<0.01	0.08	1	0.007
SI 481135	Soil	197	53.9	4.2	<0.01	<0.01	<0.05	2.4	0.3	<0.2	6.3	<0.01	0.14	8	<0.005
SI 481136	Soil	329	39.2	3.3	<0.01	0.01	0.08	2.7	0.4	<0.2	5.2	<0.01	0.16	9	<0.005
SI 481137	Soil	428	39.0	5.6	<0.01	0.01	<0.05	1.1	0.4	<0.2	7.9	<0.01	0.13	2	<0.005
SI 481138	Soil	625	25.5	5.3	<0.01	0.03	<0.05	1.0	0.5	<0.2	7.6	<0.01	0.13	1	<0.005
SI 481139	Soil	358	33.0	5.6	<0.01	0.02	<0.05	4.2	0.4	0.2	10.6	<0.01	0.19	8	<0.005
SI 481140	Soil	803	25.0	6.6	<0.01	0.04	<0.05	0.6	<0.2	0.2	7.3	<0.01	0.16	1	0.007
SI 481141	Soil	647	71.9	5.1	<0.01	0.01	0.39	1.6	0.5	<0.2	8.0	<0.01	0.15	5	<0.005
SI 481142	Soil	727	40.3	4.9	<0.01	0.02	<0.05	0.6	0.3	<0.2	6.0	<0.01	0.16	1	0.007
SI 481143	Soil	551	33.6	3.3	<0.01	0.01	<0.05	0.5	0.3	<0.2	4.9	<0.01	0.17	1	<0.005
SI 481144	Soil	602	37.6	5.4	<0.01	0.01	<0.05	1.4	0.5	<0.2	5.1	<0.01	0.13	5	<0.005
SI 481145	Soil	626	30.8	4.5	<0.01	0.01	0.38	0.9	0.4	<0.2	3.3	<0.01	0.23	1	<0.005
SI 481146	Soil	575	33.5	5.6	<0.01	0.01	<0.05	0.7	0.3	<0.2	5.6	<0.01	0.17	1	0.006
SI 481147	Soil	671	30.9	4.4	<0.01	0.01	<0.05	1.4	<0.2	<0.2	2.6	<0.01	0.12	3	<0.005
SI 481148	Soil	545	34.6	4.9	<0.01	0.02	<0.05	1.1	0.5	<0.2	5.4	<0.01	0.18	3	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481149	Soil	621	19.3	6.0	<0.01	0.02	<0.05	0.5	0.3	<0.2	3.4	<0.01	0.17	0	0.006
SI 481150	Soil	573	39.0	3.5	<0.01	0.01	<0.05	0.9	0.3	<0.2	3.5	<0.01	0.14	1	<0.005
SI 481151	Soil	736	31.1	4.8	<0.01	0.02	<0.05	0.6	<0.2	<0.2	4.2	<0.01	0.17	1	<0.005
SI 481152	Soil	976	20.7	5.6	<0.01	0.02	<0.05	0.6	0.5	<0.2	5.3	<0.01	0.14	1	0.005
SI 481153	Soil	759	22.1	8.2	<0.01	0.02	<0.05	0.5	0.4	0.3	6.7	<0.01	0.16	0	0.006
SI 481154	Soil	1176	48.0	4.7	<0.01	0.04	0.62	0.5	0.4	<0.2	4.6	<0.01	0.30	1	<0.005
SI 481155	Soil	831	36.4	6.4	<0.01	0.06	0.27	2.9	0.9	<0.2	22.8	<0.01	0.17	2	0.010
SI 481156	Soil	1170	42.6	3.6	<0.01	0.02	<0.05	3.0	0.4	<0.2	6.0	<0.01	0.17	4	<0.005
SI 481157	Soil	924	23.8	5.5	<0.01	0.03	<0.05	0.4	<0.2	<0.2	4.7	<0.01	0.13	0	<0.005
SI 481158	Soil	1410	29.8	4.5	<0.01	0.01	<0.05	4.0	0.5	0.2	12.1	<0.01	0.16	3	0.008
SI 481159	Soil	390	23.9	3.5	<0.01	0.01	<0.05	1.0	0.2	<0.2	6.1	<0.01	0.07	1	<0.005
SI 481160	Soil	496	28.3	3.8	<0.01	<0.01	<0.05	0.7	<0.2	<0.2	5.3	<0.01	0.12	1	<0.005
SI 481161	Soil	790	63.3	3.3	<0.01	0.03	1.46	1.5	0.5	<0.2	4.3	<0.01	0.25	3	<0.005
SI 481162	Soil	836	36.4	6.0	<0.01	0.02	<0.05	0.9	<0.2	<0.2	6.8	<0.01	0.17	1	0.006
SI 481163	Soil	970	27.5	2.4	<0.01	0.02	<0.05	1.5	0.3	<0.2	4.4	<0.01	0.20	4	<0.005
SI 481164	Soil	870	19.5	3.6	<0.01	0.03	<0.05	0.6	0.5	<0.2	3.2	<0.01	0.09	1	<0.005
TI 480048	Soil	652	34.6	3.5	<0.01	0.03	<0.05	2.4	1.5	<0.2	36.5	<0.01	0.19	4	<0.005
TI 480049	Soil	637	28.5	2.6	<0.01	0.04	<0.05	1.7	1.2	<0.2	33.8	<0.01	0.12	5	<0.005
TI 480050	Soil	661	35.0	4.0	<0.01	0.03	<0.05	1.3	0.8	<0.2	32.9	<0.01	0.13	2	<0.005
TI 480095	Soil	464	32.3	3.2	<0.01	0.03	<0.05	2.1	0.5	<0.2	14.2	<0.01	0.15	4	<0.005
TI 480096	Soil	539	35.7	3.6	<0.01	0.02	0.70	0.7	0.3	<0.2	12.1	<0.01	0.14	1	<0.005
TI 480150	Soil	810	22.2	3.6	<0.01	0.06	0.50	1.1	2.4	<0.2	29.8	<0.01	0.10	1	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481069	Soil	0.06	1	35	0.37	2.2	69	<0.5
SI 481070	Soil	<0.05	2	25	0.85	5.4	97	<0.5
SI 481071	Soil	<0.05	1	25	0.55	2.1	67	<0.5
SI 481072	Soil	<0.05	1	23	0.45	1.6	84	<0.5
SI 481073	Soil	<0.05	1	28	0.48	2.2	79	<0.5
SI 481074	Soil	<0.05	1	20	0.33	2.3	111	<0.5
SI 481075	Soil	0.06	1	28	0.47	3.0	76	<0.5
SI 481076	Soil	<0.05	1	18	0.68	1.5	45	<0.5
SI 481077	Soil	<0.05	1	16	1.38	1.5	26	<0.5
SI 481078	Soil	<0.05	1	17	0.73	1.5	76	0.6
SI 481079	Soil	<0.05	1	22	0.64	2.1	94	0.8
SI 481080	Soil	<0.05	1	20	0.67	2.1	102	<0.5
SI 481081	Soil	<0.05	1	23	0.33	1.9	70	<0.5
SI 481082	Soil	<0.05	2	15	0.51	5.4	125	<0.5
SI 481083	Soil	<0.05	1	16	0.51	2.3	109	<0.5
SI 481084	Soil	<0.05	1	19	0.51	3.5	112	<0.5
SI 481085	Soil	<0.05	1	19	0.39	2.1	107	<0.5
SI 481086	Soil	<0.05	1	22	0.30	3.7	114	0.7
SI 481087	Soil	<0.05	1	22	0.26	3.8	116	<0.5
SI 481088	Soil	<0.05	1	18	0.70	2.2	97	<0.5
SI 481089	Soil	<0.05	1	20	0.54	2.7	110	<0.5
SI 481090	Soil	<0.05	1	21	0.80	2.3	99	<0.5
SI 481091	Soil	<0.05	1	22	0.44	1.9	80	<0.5
SI 481092	Soil	<0.05	19	12	0.33	4.9	79	1.4
SI 481093	Soil	<0.05	3	20	0.47	4.8	126	<0.5
SI 481094	Soil	<0.05	1	18	0.42	2.3	88	<0.5
SI 481095	Soil	<0.05	1	18	0.24	2.2	82	1.3
SI 481096	Soil	<0.05	2	18	0.49	3.0	107	<0.5
SI 481097	Soil	<0.05	1	18	0.38	1.8	74	<0.5
SI 481098	Soil	<0.05	1	26	0.23	3.3	101	0.6
SI 481099	Soil	<0.05	2	19	0.70	4.0	102	0.5
SI 481100	Soil	<0.05	1	25	0.26	2.8	100	<0.5
SI 481101	Soil	<0.05	1	21	0.37	2.9	128	<0.5
SI 481102	Soil	<0.05	1	20	0.49	3.1	122	<0.5
SI 481103	Soil	<0.05	1	16	0.43	2.5	88	0.7
SI 481104	Soil	<0.05	1	18	0.62	1.7	88	1.2
SI 481105	Soil	<0.05	1	32	0.40	1.6	97	1.1
SI 481106	Soil	<0.05	1	24	0.49	1.1	64	<0.5
SI 481107	Soil	<0.05	1	21	1.05	2.1	94	<0.5
SI 481108	Soil	<0.05	1	19	0.33	2.1	93	1.0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481109	Soil	<0.05	1	21	0.53	2.7	113	1.8
SI 481110	Soil	<0.05	1	16	0.27	2.7	103	1.1
SI 481111	Soil	<0.05	1	13	0.41	16.2	58	0.9
SI 481112	Soil	<0.05	2	18	0.91	3.2	102	<0.5
SI 481113	Soil	<0.05	1	22	0.55	1.9	90	2.0
SI 481114	Soil	<0.05	1	18	0.93	4.6	72	1.1
SI 481115	Soil	<0.05	0	14	0.66	1.1	55	<0.5
SI 481116	Soil	<0.05	1	15	0.31	2.0	92	<0.5
SI 481117	Soil	<0.05	0	9	0.23	0.9	16	<0.5
SI 481118	Soil	<0.05	1	25	0.23	2.8	94	1.7
SI 481119	Soil	<0.05	1	16	2.70	1.7	94	<0.5
SI 481120	Soil	<0.05	2	18	1.52	2.5	143	<0.5
SI 481121	Soil	<0.05	1	21	1.37	1.5	92	<0.5
SI 481122	Soil	<0.05	1	14	0.78	1.9	127	<0.5
SI 481123	Soil	<0.05	1	22	0.37	1.4	44	<0.5
SI 481124	Soil	<0.05	1	20	1.26	2.1	83	1.2
SI 481125	Soil	<0.05	1	25	1.79	2.3	84	<0.5
SI 481126	Soil	<0.05	3	17	0.40	2.8	92	0.7
SI 481127	Soil	<0.05	1	23	1.01	2.9	103	<0.5
SI 481128	Soil	<0.05	1	17	1.28	2.4	110	<0.5
SI 481129	Soil	<0.05	1	20	1.04	2.8	118	<0.5
SI 481130	Soil	<0.05	1	21	0.50	2.8	106	<0.5
SI 481131	Soil	<0.05	1	20	0.78	2.3	92	<0.5
SI 481132	Soil	0.06	1	31	0.63	2.6	85	<0.5
SI 481133	Soil	<0.05	1	17	0.31	3.5	96	<0.5
SI 481134	Soil	<0.05	1	31	1.19	2.0	72	<0.5
SI 481135	Soil	<0.05	1	20	0.46	3.1	112	<0.5
SI 481136	Soil	<0.05	2	19	0.85	3.2	126	<0.5
SI 481137	Soil	<0.05	1	18	1.15	2.7	98	<0.5
SI 481138	Soil	<0.05	1	21	0.53	3.9	92	<0.5
SI 481139	Soil	<0.05	4	21	0.66	10.9	117	0.5
SI 481140	Soil	<0.05	1	25	1.21	1.9	78	<0.5
SI 481141	Soil	<0.05	2	15	1.08	3.3	120	<0.5
SI 481142	Soil	<0.05	1	21	1.00	2.2	88	<0.5
SI 481143	Soil	<0.05	1	15	1.02	1.6	78	<0.5
SI 481144	Soil	<0.05	1	21	0.61	2.8	112	<0.5
SI 481145	Soil	<0.05	2	19	0.55	3.1	186	<0.5
SI 481146	Soil	<0.05	1	22	1.08	1.8	81	<0.5
SI 481147	Soil	<0.05	1	22	0.36	2.6	115	<0.5
SI 481148	Soil	<0.05	1	17	0.50	2.0	85	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481149	Soil	<0.05	1	22	0.34	1.8	72	<0.5
SI 481150	Soil	<0.05	1	20	0.46	2.2	107	<0.5
SI 481151	Soil	<0.05	1	22	0.63	2.4	75	0.5
SI 481152	Soil	<0.05	1	26	0.50	2.8	76	0.6
SI 481153	Soil	<0.05	1	31	0.41	2.3	67	<0.5
SI 481154	Soil	<0.05	1	19	0.29	1.4	71	0.5
SI 481155	Soil	0.05	6	19	0.40	8.2	92	0.6
SI 481156	Soil	<0.05	1	16	0.31	8.4	126	<0.5
SI 481157	Soil	<0.05	1	20	0.56	2.1	72	<0.5
SI 481158	Soil	0.07	3	37	0.85	8.1	105	<0.5
SI 481159	Soil	<0.05	1	19	0.20	2.2	88	<0.5
SI 481160	Soil	<0.05	1	19	0.32	1.9	96	<0.5
SI 481161	Soil	0.08	1	18	0.24	2.7	114	<0.5
SI 481162	Soil	<0.05	1	29	0.49	3.4	101	<0.5
SI 481163	Soil	<0.05	1	25	0.28	2.2	120	<0.5
SI 481164	Soil	<0.05	1	18	0.26	2.0	68	1.1
TI 480048	Soil	<0.05	2	15	0.14	6.0	89	<0.5
TI 480049	Soil	<0.05	3	16	0.30	4.6	93	<0.5
TI 480050	Soil	<0.05	3	14	0.68	4.2	87	<0.5
TI 480095	Soil	<0.05	2	15	0.23	3.6	119	<0.5
TI 480096	Soil	<0.05	2	13	0.73	2.0	87	<0.5
TI 480150	Soil	<0.05	10	11	0.44	6.5	64	0.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481069	Soil	6													
SI 481069 Dup		8													
SI 481087	Soil	25													
SI 481087 Dup		21													
STD-Oxi67 expected		1817													
STD-Oxi67 result		1779													
QCV1007-00971-0004-BLK		<5													
SI 481105	Soil	6													
SI 481105 Dup		6													
SI 481123	Soil	32													
SI 481123 Dup		13													
STD-Oxi67 expected		1817													
STD-Oxi67 result		1828													
QCV1007-00971-0008-BLK		<5													
SI 481141	Soil	141													
SI 481141 Dup		149													
SI 481159	Soil	31													
SI 481159 Dup		24													
STD-Oxi67 expected		1817													
STD-Oxi67 result		1830													
QCV1007-00972-0001-BLK			<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
SI 481069	Soil		0.28	1.61	40.6	38	0.3	0.56	0.02	0.15	28.08	11.4	29	1.9	34.1
SI 481069 Dup			0.28	1.61	40.5	38	0.3	0.54	0.02	0.15	28.89	11.4	29	2.0	33.5
STD-ME-6 expected			101.00												6130.0
STD-ME-6 result			95.52	1.20	286.9	75	0.2	5.94	0.61	32.60	8.93	12.2	33	0.4	6224.2
SI 481087	Soil		0.29	2.24	76.4	45	0.4	0.57	0.09	0.09	38.07	17.1	35	2.3	37.5
SI 481087 Dup			0.26	2.28	76.8	47	0.4	0.59	0.09	0.09	40.80	17.4	35	2.3	36.7
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.41	3.39	5.1	213	0.7	0.20	0.25	0.10	38.24	107.5	891	1.0	639.5
SI 481105	Soil		0.24	1.71	32.6	101	0.3	0.58	0.03	0.19	12.40	16.5	32	2.9	29.4
SI 481105 Dup			0.27	1.68	32.2	101	0.3	0.58	0.03	0.19	12.36	16.6	31	3.0	28.6
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.29	2.59	9.9	207	0.6	0.19	0.24	0.10	36.10	110.0	760	0.7	577.4
SI 481123	Soil		0.39	1.05	51.7	23	0.2	0.33	0.03	0.07	27.36	5.3	17	2.6	18.4
SI 481123 Dup			0.33	1.07	51.5	23	0.2	0.33	0.03	0.07	28.26	5.3	18	2.8	17.8
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.35	4.16	6.3	224	0.7	0.20	0.26	0.11	41.88	118.3	994	1.4	712.0
SI 481141	Soil		0.35	1.93	227.3	38	0.6	0.58	0.06	0.15	37.64	22.5	26	2.0	49.1
SI 481141 Dup			0.25	1.99	237.8	40	0.6	0.59	0.06	0.15	39.39	23.4	26	2.1	50.2
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.31	3.80	5.5	210	0.7	0.22	0.25	0.10	38.88	119.2	940	1.2	710.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA ppb 5	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481159	Soil		0.25	2.07	71.5	37	0.4	0.43	0.03	0.06	36.70	14.2	29	1.2	33.8
SI 481159 Dup			0.24	2.10	72.6	37	0.4	0.42	0.03	0.06	37.41	14.2	30	1.2	34.2
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.28	3.96	9.5	194	0.7	0.21	0.25	0.12	35.31	113.7	951	1.1	678.8
QCV1007-00972-0014-BLK			<0.01	<0.01	1.5	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
STD-DS-1 expected			0.47	4.48	6930.0	221						9.5			27.1
STD-DS-1 result			0.55	0.48	7199.5	20	0.4	0.09	6.98	1.22	21.98	9.9	22	1.7	27.6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
QCV1007-00972-0001-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
SI 481069	Soil	4.82	7.9	<0.05	<0.02	0.03	0.04	14.4	28.6	0.44	1220	1.00	<0.01	0.6	25.3
SI 481069 Dup		4.86	7.6	<0.05	<0.02	0.03	0.04	14.9	29.1	0.44	1238	0.97	<0.01	0.6	24.6
STD-ME-6 expected															
STD-ME-6 result		5.37	4.1	<0.05	0.17	0.46	0.09	4.3	9.0	0.81	1704	22.05	0.06	0.1	29.1
SI 481087	Soil	5.22	7.1	<0.05	<0.02	0.03	0.03	21.4	65.6	0.89	719	0.61	<0.01	0.1	46.5
SI 481087 Dup		5.23	7.1	<0.05	<0.02	0.03	0.03	22.3	68.8	0.90	726	0.61	<0.01	0.1	46.6
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	17.7	0.1	0.58	0.10	0.07	17.5	5.7	0.11	1123	1.31	0.02	0.6	314.8
SI 481105	Soil	4.60	6.5	<0.05	0.04	0.02	0.04	6.6	32.4	0.52	1206	0.84	<0.01	0.5	26.5
SI 481105 Dup		4.55	6.6	<0.05	0.03	0.02	0.04	6.5	32.2	0.51	1199	0.87	<0.01	0.4	26.5
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	17.2	0.1	0.41	0.10	0.06	16.5	3.6	0.09	1072	1.75	0.02	0.6	275.6
SI 481123	Soil	2.70	4.7	0.1	<0.02	0.02	0.03	16.0	19.8	0.28	224	0.56	0.01	0.4	14.9
SI 481123 Dup		2.71	4.6	0.1	<0.02	0.02	0.03	16.4	19.2	0.28	222	0.57	0.01	0.4	15.4
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	21.0	0.2	0.57	0.11	0.08	19.3	8.1	0.14	1208	1.35	0.02	0.3	376.0
SI 481141	Soil	5.35	4.8	<0.05	<0.02	0.04	0.03	19.8	49.4	0.66	951	0.51	<0.01	0.2	49.3
SI 481141 Dup		5.31	4.9	<0.05	<0.02	0.04	0.03	20.8	49.6	0.65	945	0.52	<0.01	0.2	49.7
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	21.8	0.2	0.56	0.11	0.08	18.0	7.1	0.12	1152	1.19	0.02	0.4	354.4
SI 481159	Soil	4.45	6.6	0.1	<0.02	0.02	0.02	19.8	62.5	0.87	463	0.37	<0.01	0.1	39.5
SI 481159 Dup		4.51	6.5	0.1	<0.02	0.02	0.02	20.6	63.7	0.88	467	0.37	<0.01	0.1	39.3
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	22.5	0.2	0.53	0.10	0.08	16.3	6.8	0.13	1170	0.98	0.02	0.3	334.9
QCV1007-00972-0014-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
STD-DS-1 expected										2.76	437				48.7
STD-DS-1 result		3.06	1.7	<0.05	0.08	0.05	0.13	10.6	2.5	2.98	460	3.39	<0.01	<0.05	51.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
QCV1007-00972-0001-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
SI 481069	Soil	1786	37.8	7.5	<0.01	0.08	<0.05	0.6	0.8	0.3	6.2	<0.01	0.24	0	0.010
SI 481069 Dup		1778	37.6	7.4	<0.01	0.08	<0.05	0.6	0.7	0.3	6.4	<0.01	0.25	0	0.010
STD-ME-6 expected			10200												
STD-ME-6 result		451	>10000	3.4	0.01	2.18	398.49	4.0	2.3	1.7	27.3	<0.01	1.80	1	0.078
SI 481087	Soil	504	33.1	4.9	<0.01	0.01	<0.05	1.5	0.4	<0.2	8.7	<0.01	0.20	2	<0.005
SI 481087 Dup		506	32.9	5.0	<0.01	0.01	<0.05	1.4	0.4	<0.2	8.9	<0.01	0.18	2	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		373	19.8	9.5	<0.01	0.03	<0.05	52.7	<0.2	1.9	16.0	<0.01	0.18	7	0.162
SI 481105	Soil	1613	28.7	9.5	<0.01	0.05	0.11	0.5	<0.2	<0.2	12.4	<0.01	0.17	1	0.007
SI 481105 Dup		1570	28.8	9.4	<0.01	0.05	0.15	0.5	<0.2	<0.2	12.2	<0.01	0.17	1	0.007
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		362	19.1	7.6	<0.01	0.02	<0.05	47.9	<0.2	1.7	15.6	<0.01	0.17	6	0.110
SI 481123	Soil	536	15.4	5.0	<0.01	0.03	<0.05	0.3	0.4	0.3	5.8	<0.01	0.11	<0.2	0.009
SI 481123 Dup		547	15.8	5.0	<0.01	0.03	<0.05	0.3	0.4	0.3	5.8	<0.01	0.11	<0.2	0.009
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		396	20.4	12.7	<0.01	0.03	<0.05	62.9	<0.2	2.0	18.3	<0.01	0.10	7	0.211
SI 481141	Soil	647	71.9	5.1	<0.01	0.01	0.39	1.6	0.5	<0.2	8.0	<0.01	0.15	5	<0.005
SI 481141 Dup		633	73.1	5.0	<0.01	0.01	0.43	1.6	0.5	<0.2	8.2	<0.01	0.15	5	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		382	21.5	12.1	<0.01	0.03	<0.05	57.0	<0.2	1.8	18.1	<0.01	0.08	7	0.184
SI 481159	Soil	390	23.9	3.5	<0.01	0.01	<0.05	1.0	0.2	<0.2	6.1	<0.01	0.07	1	<0.005
SI 481159 Dup		391	25.1	3.6	<0.01	0.01	<0.05	1.0	<0.2	<0.2	6.0	<0.01	0.07	1	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		393	19.8	11.8	<0.01	0.03	<0.05	51.7	<0.2	1.7	17.6	<0.01	0.07	6	0.185
QCV1007-00972-0014-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
STD-DS-1 expected		340	13.8												
STD-DS-1 result		342	13.8	6.4	<0.01	2.68	48.13	6.1	1.0	0.9	60.6	<0.01	0.19	3	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02339-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
QCV1007-00972-0001-BLK		<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
SI 481069	Soil	0.06	1	35	0.37	2.2	69	<0.5
SI 481069 Dup		0.06	1	34	0.36	2.1	69	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.21	1	44	0.76	6.4	4947	4.5
SI 481087	Soil	<0.05	1	22	0.26	3.8	116	<0.5
SI 481087 Dup		<0.05	1	22	0.27	3.8	115	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.07	1	237	0.32	10.3	129	22.2
SI 481105	Soil	<0.05	1	32	0.40	1.6	97	1.1
SI 481105 Dup		<0.05	1	31	0.45	1.6	94	1.0
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.06	1	214	0.43	10.2	122	18.4
SI 481123	Soil	<0.05	1	22	0.37	1.4	44	<0.5
SI 481123 Dup		<0.05	1	23	0.37	1.4	44	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.07	1	251	0.22	11.4	139	24.3
SI 481141	Soil	<0.05	2	15	1.08	3.3	120	<0.5
SI 481141 Dup		<0.05	2	15	1.09	3.4	118	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.08	1	248	0.19	10.5	137	21.5
SI 481159	Soil	<0.05	1	19	0.20	2.2	88	<0.5
SI 481159 Dup		<0.05	1	19	0.19	2.3	89	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.08	1	228	0.82	9.7	138	19.6
QCV1007-00972-0014-BLK		<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
STD-DS-1 expected		20.00					206	
STD-DS-1 result		21.45	1	53	4.84	9.1	204	2.6

Certificate of Analysis

10-360-02340-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description:

Date Received: 07/27/2010
Date Completed: 08/12/2010
Invoice:

Samples	Type	Preparation Description
25	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-1AT-GV	Au, 1AT, Gravimetric
Au-2AT-AA	Au, 2AT Fire Assay, AAS
Ag-4A-OR	Ag, 4 Acid, AA, Ore Grade

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02340-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag Ag-4A-OR ppm 1.0	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1
RI 480084	Rock		0.050		0.90	0.67	132.1	22	0.2	0.16	0.99	0.06	7.75	2.8	234
RI 480085	Rock	9.464	8.709		2.72	0.16	>10000	36	0.1	2.49	0.03	0.03	<0.02	21.2	66
RI 480086	Rock	22.890	>10	174.4	>100	1.81	>10000	87	0.6	0.68	0.01	38.04	6.79	0.5	36
RI 480087	Rock		0.087		0.80	2.11	817.9	122	1.6	0.08	<0.01	0.15	18.57	8.5	182
RI 480088	Rock		0.083		0.39	1.95	393.9	104	0.7	0.07	0.02	0.26	25.74	2.1	181
RI 480089	Rock		0.076		1.60	1.47	701.6	68	0.4	0.05	<0.01	0.27	20.54	1.0	191
RI 480090	Rock		0.698		42.08	0.73	>10000	78	0.3	0.20	0.01	0.61	17.51	0.6	140
RI 480091	Rock		0.818		1.98	1.47	>10000	73	0.4	0.25	<0.01	0.89	15.55	0.7	168
RI 480092	Rock		0.022		0.58	0.93	320.9	42	0.4	0.13	<0.01	0.06	9.77	0.7	249
RI 480093	Rock		0.049		0.95	1.64	2134.7	113	0.5	0.10	0.01	3.06	19.81	0.6	172
RI 480094	Rock	1.052	1.021		27.80	1.60	>10000	90	0.5	0.27	0.01	2.13	24.66	0.7	182
RI 480101	Rock		0.109		0.70	2.44	519.4	84	0.6	0.12	0.16	0.05	35.84	1.9	172
RI 480102	Rock		0.191		0.39	4.22	558.8	293	1.5	0.66	0.02	<0.01	46.19	4.8	138
RI 480103	Rock		0.153		0.87	2.42	274.5	122	0.7	0.46	0.02	<0.01	39.40	2.3	166
RI 480104	Rock		0.118		1.42	2.35	1961.7	194	0.7	0.10	0.01	0.39	28.31	1.4	179
RI 480105	Rock		0.265		0.39	1.30	8471.2	92	0.3	0.05	<0.01	0.17	14.91	0.8	212
RI 480106	Rock		0.073		0.17	1.11	1063.9	81	0.4	0.04	<0.01	0.11	16.29	0.5	10
RI 480107	Rock	4.332	3.969		6.36	1.34	>10000	91	0.3	0.17	0.01	0.63	8.14	<0.1	77
RI 480108	Rock		0.256		4.15	2.31	1551.2	103	0.6	0.11	0.05	6.67	34.85	2.6	252
RI 480109	Rock	4.345	4.495		2.47	0.26	>10000	22	0.1	0.21	0.01	0.07	0.87	<0.1	139
RI 480110	Rock		0.068		0.48	5.29	435.7	304	1.9	0.26	0.03	0.09	51.67	11.4	151
RI 480111	Rock		0.175		0.69	1.85	4893.9	21	0.3	0.14	0.01	0.15	10.38	2.0	197
RI 480112	Rock		0.105		0.36	1.75	9799.9	21	0.2	0.14	0.07	0.10	14.62	3.6	193
RI 480113	Rock		0.181		0.67	2.79	3701.6	56	0.8	0.39	0.02	0.16	35.33	3.0	197
RI 480114	Rock		0.107		0.52	3.85	676.4	24	0.5	0.16	0.02	0.12	35.49	4.8	136

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02340-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01
RI 480084	Rock	0.4	5.8	1.37	1.6	1.1	0.14	0.01	0.08	3.3	44.3	0.06	796	1.12	0.02
RI 480085	Rock	0.4	14.6	>10	0.7	0.5	<0.1	0.29	0.03	1.1	34.2	<0.01	30	2.38	<0.01
RI 480086	Rock	8.1	295.4	>10	5.5	0.4	1.09	6.08	0.52	4.9	49.6	0.04	103	1.09	0.08
RI 480087	Rock	2.0	47.6	5.76	4.4	0.7	1.61	0.05	0.46	8.7	17.9	0.03	151	0.81	0.03
RI 480088	Rock	2.0	6.7	0.58	4.9	1.2	1.58	0.03	0.49	12.0	26.0	0.11	65	0.92	0.17
RI 480089	Rock	1.4	6.8	0.65	2.8	1.6	0.94	0.05	0.55	9.5	2.7	0.10	38	0.89	0.03
RI 480090	Rock	2.3	47.7	3.20	2.0	2.2	0.74	0.65	0.26	8.6	11.7	0.06	32	1.85	0.02
RI 480091	Rock	1.8	23.0	1.53	3.0	2.1	0.90	0.15	0.42	7.4	49.7	0.04	35	0.75	0.02
RI 480092	Rock	0.8	8.5	0.60	1.8	1.7	0.42	0.02	0.18	4.6	16.0	0.02	27	1.02	0.01
RI 480093	Rock	4.4	15.5	3.25	3.7	1.5	0.85	0.09	0.34	9.7	23.7	0.03	31	0.99	0.02
RI 480094	Rock	1.7	26.2	1.53	3.6	2.4	1.18	3.98	0.62	11.8	5.7	0.08	49	0.97	0.03
RI 480101	Rock	0.7	6.6	1.22	4.3	0.9	1.33	0.04	0.31	17.4	14.9	0.21	134	0.68	0.56
RI 480102	Rock	2.0	7.7	4.52	10.3	1.2	2.01	0.03	1.30	22.3	17.7	0.38	73	0.69	0.46
RI 480103	Rock	0.8	9.0	1.83	4.6	1.1	1.34	0.01	0.46	18.8	5.6	0.17	59	0.68	0.80
RI 480104	Rock	2.6	16.3	0.73	6.1	1.7	1.13	0.56	0.79	13.5	12.8	0.07	39	1.04	0.03
RI 480105	Rock	2.6	9.9	0.92	3.4	2.1	0.49	0.05	0.55	7.5	7.8	0.07	29	0.93	0.02
RI 480106	Rock	1.5	4.2	0.39	2.7	2.0	0.71	0.03	0.33	8.1	13.0	0.12	14	0.17	0.04
RI 480107	Rock	1.6	40.1	6.76	4.3	1.6	0.48	0.15	0.58	4.6	7.5	0.07	32	0.51	0.02
RI 480108	Rock	4.0	12.5	1.40	5.5	0.9	1.21	0.10	0.62	15.9	24.5	0.09	440	0.95	0.16
RI 480109	Rock	0.5	8.6	9.52	0.9	1.0	<0.1	0.14	0.09	1.0	3.4	0.02	39	0.62	<0.01
RI 480110	Rock	4.6	27.7	3.16	13.0	1.6	1.90	0.04	1.54	26.5	24.7	0.31	741	1.26	0.33
RI 480111	Rock	0.6	11.4	1.28	2.2	1.5	0.48	0.02	0.06	5.2	17.9	0.02	74	0.93	1.34
RI 480112	Rock	0.4	11.8	1.51	1.8	1.2	0.59	0.02	0.04	6.9	16.7	0.02	842	0.90	1.34
RI 480113	Rock	0.7	66.9	0.89	3.0	1.4	1.21	0.02	0.03	15.4	29.9	0.05	96	0.81	1.89
RI 480114	Rock	0.3	20.7	2.28	4.4	1.3	1.83	0.02	0.04	16.5	53.8	0.03	329	1.24	3.07

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02340-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05
RI 480084	Rock	0.3	9.3	83	64.1	5.2	0.011	<0.01	0.20	1.2	<0.5	0.4	17.6	<0.05	0.19
RI 480085	Rock	0.2	65.0	94	37.8	1.8	0.009	3.93	151.92	2.1	35.9	0.3	11.3	<0.05	17.47
RI 480086	Rock	0.5	4.8	122	>10000	34.6	0.007	1.79	277.05	3.7	<0.5	37.4	32.0	0.06	0.27
RI 480087	Rock	0.7	29.8	170	233.6	27.0	0.011	0.02	1.82	4.0	1.2	0.7	12.1	0.12	0.07
RI 480088	Rock	0.9	7.7	59	78.5	30.0	0.014	<0.01	1.87	2.4	<0.5	3.1	25.7	0.19	0.30
RI 480089	Rock	0.6	5.0	42	382.3	32.4	0.014	0.03	2.81	1.8	<0.5	6.7	14.6	0.09	0.12
RI 480090	Rock	0.5	3.7	97	>10000	14.6	0.013	0.22	78.99	1.6	1.8	5.7	19.8	0.07	0.17
RI 480091	Rock	0.5	3.3	77	551.8	25.9	<0.005	0.04	21.87	2.0	<0.5	2.5	21.0	0.08	0.49
RI 480092	Rock	0.4	5.2	65	82.0	11.6	<0.005	<0.01	24.02	1.8	<0.5	0.7	13.8	0.05	0.11
RI 480093	Rock	0.4	4.8	127	53.2	22.2	0.009	0.03	5.41	3.6	<0.5	1.8	59.3	0.07	0.12
RI 480094	Rock	0.7	4.2	298	6065.2	39.0	<0.005	0.18	34.58	3.2	<0.5	12.9	22.2	0.09	<0.05
RI 480101	Rock	1.0	6.8	85	125.0	19.2	0.012	<0.01	2.79	3.3	<0.5	0.8	57.2	0.14	<0.05
RI 480102	Rock	1.6	14.0	124	38.8	74.2	0.011	0.86	5.15	7.1	1.7	1.6	41.7	0.28	<0.05
RI 480103	Rock	1.1	9.1	59	40.0	29.2	0.008	0.33	5.89	3.3	<0.5	0.9	80.2	0.19	<0.05
RI 480104	Rock	1.1	4.1	255	779.4	47.4	0.007	0.02	20.79	3.1	<0.5	5.2	247.2	0.15	0.08
RI 480105	Rock	0.5	4.0	78	73.4	36.0	0.008	0.03	13.57	2.1	1.8	9.8	52.4	0.06	0.33
RI 480106	Rock	0.5	0.7	88	13.0	20.6	<0.005	0.02	3.37	1.9	<0.5	3.4	40.7	0.06	0.06
RI 480107	Rock	0.3	1.6	118	100.4	38.0	0.006	0.05	197.43	2.2	1.6	11.2	27.2	<0.05	0.94
RI 480108	Rock	0.8	10.6	138	1379.6	37.1	0.011	0.02	7.14	3.5	<0.5	2.5	34.9	0.13	<0.05
RI 480109	Rock	0.2	2.9	44	132.9	5.9	0.006	2.04	104.29	1.0	<0.5	1.8	9.2	<0.05	0.43
RI 480110	Rock	1.6	37.1	402	25.9	86.1	0.010	0.02	4.31	8.8	<0.5	1.5	52.1	0.27	0.06
RI 480111	Rock	0.4	9.0	66	30.2	3.9	0.006	0.18	5.18	2.1	<0.5	0.4	63.4	0.06	0.67
RI 480112	Rock	0.5	11.6	94	14.6	2.6	0.010	0.39	7.67	2.4	1.9	0.4	61.7	0.09	0.69
RI 480113	Rock	0.7	11.0	182	12.1	2.2	0.005	0.02	3.13	2.6	<0.5	0.4	92.5	0.09	0.53
RI 480114	Rock	0.8	18.4	75	14.2	2.2	0.007	0.02	2.34	4.9	1.3	0.5	122.6	0.13	0.17

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02340-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480084	Rock	2	<0.005	<0.02	0	<1	5.02	3.3	19	6.1
RI 480085	Rock	2	<0.005	0.09	0	<1	2.47	0.4	18	4.0
RI 480086	Rock	4	0.012	0.23	2	11	3.53	2.9	1914	19.8
RI 480087	Rock	6	0.020	0.12	1	12	5.58	5.1	149	31.9
RI 480088	Rock	5	0.022	0.12	1	9	5.30	3.2	26	37.3
RI 480089	Rock	4	0.015	0.15	1	<1	4.44	2.0	34	26.2
RI 480090	Rock	9	0.013	0.09	1	1	10.69	1.8	36	25.5
RI 480091	Rock	4	0.015	0.12	1	5	7.47	1.7	52	27.5
RI 480092	Rock	3	0.007	0.02	1	<1	22.45	1.1	5	14.1
RI 480093	Rock	11	0.011	0.11	1	9	3.04	2.6	33	25.0
RI 480094	Rock	10	0.017	0.21	1	5	5.44	3.4	90	39.1
RI 480101	Rock	9	0.028	0.06	1	11	6.03	4.1	8	43.1
RI 480102	Rock	10	0.049	0.40	3	42	4.90	5.2	20	59.1
RI 480103	Rock	9	0.029	0.12	1	13	6.12	3.9	11	43.0
RI 480104	Rock	6	0.029	0.40	1	15	6.90	4.1	15	37.0
RI 480105	Rock	3	0.014	0.24	0	2	6.15	1.2	5	18.6
RI 480106	Rock	2	0.019	0.14	1	8	5.62	1.8	8	26.5
RI 480107	Rock	3	0.011	0.68	1	7	10.39	1.0	18	17.7
RI 480108	Rock	8	0.022	0.17	1	11	3.99	4.1	809	41.9
RI 480109	Rock	2	<0.005	0.03	0	<1	6.38	0.4	13	5.5
RI 480110	Rock	11	0.047	0.43	2	45	5.26	6.7	54	62.0
RI 480111	Rock	3	0.007	<0.02	1	<1	3.27	1.6	44	18.2
RI 480112	Rock	4	0.008	<0.02	1	<1	4.45	2.3	13	23.0
RI 480113	Rock	7	0.014	<0.02	2	2	3.84	4.5	15	40.8
RI 480114	Rock	9	0.019	<0.02	2	7	5.57	4.7	36	62.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02340-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag Ag-4A-OR ppm 1.0	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1
RI 480101	Rock		0.109												
RI 480101 Dup			0.308												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.804												
QCV1007-00920-0004-BLK			0.006												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.823												
QCV1007-00921-0001-BLK					0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1
RI 480084	Rock				0.90	0.67	132.1	22	0.2	0.16	0.99	0.06	7.75	2.8	234
RI 480084 Dup					0.94	0.67	133.7	22	0.2	0.15	1.00	0.06	7.23	2.9	235
STD-ME-8 expected					61.70										
STD-ME-8 result					58.88	4.29	2366.4	672	1.1	4.97	6.27	175.28	27.14	13.0	41
RI 480108	Rock				4.15	2.31	1551.2	103	0.6	0.11	0.05	6.67	34.85	2.6	252
RI 480108 Dup					3.97	2.32	1508.3	101	0.6	0.10	0.05	6.72	33.82	2.7	244
QCV1007-00921-0005-BLK					<0.01	<0.01	0.2	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1
STD-SY-4 expected								340	2.6				122.00	2.8	12
STD-SY-4 result					0.57	9.48	89.5	378	3.6	0.04	5.31	0.14	126.73	3.9	8
QCV1008-00116-0001-BLK				<1.0											
RI 480086	Rock			174.4											
RI 480086 Dup				171.0											
QCV1008-00116-0003-BLK				<1.0											
STD-ME-7 expected				150.7											
STD-ME-7 result				142.0											

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02340-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01
QCV1007-00921-0001-BLK		<0.05	<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01
RI 480084	Rock	0.4	5.8	1.37	1.6	1.1	0.14	0.01	0.08	3.3	44.3	0.06	796	1.12	0.02
RI 480084 Dup		0.5	5.6	1.37	1.5	1.1	0.16	0.01	0.08	3.3	43.0	0.06	803	1.08	0.02
STD-ME-8 expected			1030.0												
STD-ME-8 result		3.3	1085.8	3.47	9.8	0.6	1.43	0.09	1.27	13.5	17.8	0.77	3052	5.79	1.16
RI 480108	Rock	4.0	12.5	1.40	5.5	0.9	1.21	0.10	0.62	15.9	24.5	0.09	440	0.95	0.16
RI 480108 Dup		3.9	12.2	1.43	5.3	0.9	1.22	0.10	0.62	15.6	25.1	0.09	447	0.98	0.16
QCV1007-00921-0005-BLK		<0.05	<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01
STD-SY-4 expected		1.5	7.0		35.0		10.60			58.0	37.0				
STD-SY-4 result		1.8	9.5	3.92	33.3	0.4	1.47	0.04	1.27	58.6	41.7	0.34	820	0.28	4.92

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02340-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te
		50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT
Sample	Sample	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
Description	Type	0.1	0.2	10	0.5	0.1	0.005	0.01	0.05	0.1	0.5	0.2	0.2	0.05	0.05
QCV1007-00921-0001-BLK		<0.1	<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05
RI 480084	Rock	0.3	9.3	83	64.1	5.2	0.011	<0.01	0.20	1.2	<0.5	0.4	17.6	<0.05	0.19
RI 480084 Dup		0.2	9.0	83	64.3	5.1	0.010	<0.01	0.23	1.2	<0.5	0.4	17.3	<0.05	0.17
STD-ME-8 expected					19400										
STD-ME-8 result		3.8	32.5	545	>10000	69.1	0.010	1.47	66.72	8.9	5.2	3.1	417.5	0.50	0.81
RI 480108	Rock	0.8	10.6	138	1379.6	37.1	0.011	0.02	7.14	3.5	<0.5	2.5	34.9	0.13	<0.05
RI 480108 Dup		0.9	10.8	138	1346.0	36.8	0.009	0.03	6.71	3.5	<0.5	2.4	34.6	0.13	<0.05
QCV1007-00921-0005-BLK		<0.1	<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05
STD-SY-4 expected		13.0	9.0		10.0	55.0				1.1			1191.0	0.90	
STD-SY-4 result		14.6	7.5	479	26.8	47.6	0.026	0.02	<0.05	1.4	<0.5	8.8	1172.3	1.44	0.31

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02340-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1007-00921-0001-BLK		<0.2	<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
RI 480084	Rock	2	<0.005	<0.02	0	<1	5.02	3.3	19	6.1
RI 480084 Dup		2	<0.005	<0.02	0	<1	4.77	3.3	19	6.4
STD-ME-8 expected									19200	
STD-ME-8 result		4	0.175	0.84	2	71	14.37	11.9	>10000	27.0
RI 480108	Rock	8	0.022	0.17	1	11	3.99	4.1	809	41.9
RI 480108 Dup		8	0.023	0.16	1	11	4.04	4.1	811	41.9
QCV1007-00921-0005-BLK		<0.2	<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected		1			1	8		119.0	93	517.0
STD-SY-4 result		1	0.152	0.21	1	3	8.71	121.5	88	60.9

Certificate of Analysis

10-360-02389-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 07/30/2010
Date Completed: 08/13/2010
Invoice:

Samples	Type	Preparation Description
11	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-2AT-AA	Au, 2AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02389-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-2AT-AA ppb 5	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2
RI 480115	Rock	12	0.10	0.57	514.3	20	0.2	0.24	<0.01	0.08	8.21	1.4	162	0.5	10.4
RI 480116	Rock	6	0.20	0.13	65.5	6	<0.05	0.24	<0.01	0.05	0.80	0.9	108	0.2	20.7
RI 480117	Rock	10	0.20	0.93	85.9	39	0.2	0.83	<0.01	0.07	13.38	1.9	104	0.4	25.4
RI 480118	Rock	<5	0.39	0.76	83.8	49	0.2	0.96	0.06	0.06	11.92	0.9	144	0.5	19.0
RI 480119	Rock	8	0.10	0.86	80.5	47	0.3	0.48	0.01	0.04	9.71	1.1	114	0.5	7.1
RI 480120	Rock	9	<0.01	0.31	482.5	16	0.1	0.52	0.01	0.04	1.37	1.0	151	0.2	4.0
RI 480121	Rock	10	0.10	1.22	375.8	59	0.2	1.05	<0.01	0.06	12.37	0.8	124	0.6	8.0
RI 480122	Rock	30	0.30	1.14	1119.4	64	0.3	0.90	<0.01	0.05	17.19	0.8	114	0.7	11.1
RI 480123	Rock	16	0.20	1.56	25.4	45	0.3	0.18	0.01	0.02	23.50	1.8	142	0.9	11.8
RI 480124	Rock	193	0.20	1.62	679.8	49	0.3	0.24	0.02	0.09	17.45	2.2	173	0.6	9.5
RI 481503	Rock	9	0.10	0.22	24.1	<5	<0.05	0.31	0.03	0.03	2.90	1.1	120	0.1	8.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02389-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2
RI 480115	Rock	0.54	1.5	0.2	<0.1	<0.01	0.11	3.7	5.2	0.01	118	0.49	0.21	0.4	6.3
RI 480116	Rock	0.35	0.4	0.9	<0.1	<0.01	0.04	<0.5	1.9	0.01	33	0.08	<0.01	0.2	4.5
RI 480117	Rock	0.61	2.0	0.7	0.21	0.01	0.21	6.1	7.6	0.01	58	<0.05	0.01	0.5	5.7
RI 480118	Rock	0.52	2.0	0.2	<0.1	<0.01	0.27	5.6	2.0	0.02	36	0.16	0.01	0.5	5.4
RI 480119	Rock	0.58	2.1	0.6	0.15	<0.01	0.28	4.4	3.7	0.02	40	<0.05	0.01	0.4	5.2
RI 480120	Rock	0.32	0.6	1.5	<0.1	<0.01	0.12	0.7	1.7	<0.01	26	<0.05	<0.01	0.2	3.6
RI 480121	Rock	0.39	2.5	0.8	0.31	<0.01	0.45	5.8	3.0	0.04	28	<0.05	0.02	0.5	3.6
RI 480122	Rock	0.47	2.7	0.5	0.39	<0.01	0.46	7.8	7.3	0.04	27	<0.05	0.02	0.5	3.4
RI 480123	Rock	0.46	2.8	0.5	0.79	<0.01	0.23	10.6	11.1	0.05	72	<0.05	0.03	0.8	5.2
RI 480124	Rock	0.73	2.6	0.6	0.66	<0.01	0.24	7.9	2.4	0.03	165	<0.05	0.80	0.5	5.4
RI 481503	Rock	0.33	0.3	0.1	<0.1	<0.01	0.01	1.4	1.5	<0.01	50	<0.05	0.13	0.2	4.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02389-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005
RI 480115	Rock	37	10.5	6.6	0.018	0.02	0.99	0.9	3.1	0.9	9.5	<0.05	1.76	1	0.007
RI 480116	Rock	<10	8.2	2.1	0.013	<0.01	0.85	0.5	2.5	1.1	1.9	<0.05	2.11	<0.2	<0.005
RI 480117	Rock	64	5.6	12.6	0.018	<0.01	0.47	1.5	3.8	0.8	23.9	<0.05	4.85	3	0.011
RI 480118	Rock	360	12.0	15.6	0.007	<0.01	0.43	1.4	3.4	0.8	16.6	<0.05	3.43	2	0.012
RI 480119	Rock	61	26.1	15.8	0.008	<0.01	0.52	1.4	2.4	1.1	8.7	<0.05	0.96	2	0.011
RI 480120	Rock	25	6.5	6.3	0.007	0.02	1.27	0.6	<0.5	1.5	3.0	<0.05	0.59	0	<0.005
RI 480121	Rock	38	10.2	24.1	0.010	<0.01	0.99	1.4	2.5	4.8	9.8	<0.05	0.68	2	0.013
RI 480122	Rock	58	12.5	25.7	0.012	0.03	2.06	1.5	2.8	4.8	10.9	0.05	1.07	3	0.014
RI 480123	Rock	73	6.0	15.7	0.010	<0.01	0.58	1.3	2.6	0.7	12.9	0.13	0.87	4	0.016
RI 480124	Rock	107	4.0	14.1	0.005	0.01	1.48	1.5	2.6	0.7	45.9	0.08	0.93	5	0.012
RI 481503	Rock	38	3.4	0.9	0.009	0.02	0.22	0.5	3.3	0.5	6.0	<0.05	1.29	0	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02389-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480115	Rock	0.46	0	1	1.63	1.0	12	5.0
RI 480116	Rock	0.47	<0.1	<1	1.49	0.1	5	0.8
RI 480117	Rock	0.50	1	3	3.37	1.5	25	14.6
RI 480118	Rock	0.53	0	4	2.38	1.5	8	8.3
RI 480119	Rock	0.52	0	4	2.19	1.4	11	9.7
RI 480120	Rock	0.48	<0.1	2	2.70	0.2	4	1.2
RI 480121	Rock	0.54	0	5	3.42	1.4	6	16.5
RI 480122	Rock	0.57	1	5	2.89	1.4	6	19.5
RI 480123	Rock	0.48	1	5	2.03	2.1	5	29.4
RI 480124	Rock	0.48	1	4	2.96	2.3	12	27.8
RI 481503	Rock	0.46	0	<1	1.25	0.5	3	2.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02389-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-2AT-AA ppb 5	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2
RI 480115	Rock	12													
RI 480115 Dup		13													
STD-Oxi67 expected		1817													
STD-Oxi67 result		1869													
QCV1007-01009-0001-BLK			<0.01	<0.01	0.2	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
RI 480115	Rock		0.10	0.57	514.3	20	0.2	0.24	<0.01	0.08	8.21	1.4	162	0.5	10.4
RI 480115 Dup			0.10	0.57	511.2	20	0.2	0.21	<0.01	0.08	8.03	1.4	165	0.4	11.2
QCV1007-01009-0003-BLK			<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
STD-SY-4 expected						340	2.6				122.00	2.8	12	1.5	7.0
STD-SY-4 result			0.10	>10	3.4	373	3.3	0.11	5.66	0.13	126.71	3.2	8	1.9	8.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02389-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2
QCV1007-01009-0001-BLK		<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1	<0.2
RI 480115	Rock	0.54	1.5	0.2	<0.1	<0.01	0.11	3.7	5.2	0.01	118	0.49	0.21	0.4	6.3
RI 480115 Dup		0.54	1.5	0.2	<0.1	<0.01	0.11	3.7	5.1	0.01	116	0.50	0.21	0.4	6.5
QCV1007-01009-0003-BLK		<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1	<0.2
STD-SY-4 expected			35.0		10.60			58.0	37.0					13.0	9.0
STD-SY-4 result		4.20	37.0	0.6	1.55	0.04	1.33	58.4	40.0	0.30	854	<0.05	5.45	14.7	7.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02389-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th	Ti
		50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT
Sample	Sample	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%
Description	Type	10	0.5	0.1	0.005	0.01	0.05	0.1	0.5	0.2	0.2	0.05	0.05	0.2	0.005
QCV1007-01009-0001-BLK		<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2	<0.005
RI 480115	Rock	37	10.5	6.6	0.018	0.02	0.99	0.9	3.1	0.9	9.5	<0.05	1.76	1	0.007
RI 480115 Dup		36	10.5	6.5	0.019	0.02	1.04	0.9	3.0	0.8	9.4	<0.05	1.78	1	0.007
QCV1007-01009-0003-BLK		<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2	<0.005
STD-SY-4 expected			10.0	55.0				1.1			1191.0	0.90		1	
STD-SY-4 result		533	12.9	46.5	0.023	0.01	<0.05	1.3	2.0	9.0	1188.0	1.65	0.63	1	0.147

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02389-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1007-01009-0001-BLK		<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
RI 480115	Rock	0.46	0	1	1.63	1.0	12	5.0
RI 480115 Dup		0.50	0	1	1.62	1.0	11	5.1
QCV1007-01009-0003-BLK		<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected			1	8		119.0	93	517.0
STD-SY-4 result		0.58	1	2	1.09	118.9	88	59.7

Certificate of Analysis

10-360-02393-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 07/30/2010
Date Completed: 08/23/2010
Invoice:

Samples	Type	Preparation Description
129	Soil	SP-SS-1K/Soils, Humus Sediments 1kg dried, sieved and riffle split

Method	Description
50-AR-UT	50 Element, Aqua Regia, ICPMS, Ultra Trace Level
Au-1AT-AA	Au, 1AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481203	Soil	<0.005	0.22	1.66	16.1	28	0.4	0.41	0.04	0.18	19.45	16.9	21	3.3	42.8
SI 481204	Soil	0.011	0.23	1.95	35.0	41	0.5	0.65	0.02	0.28	22.67	30.2	29	3.8	47.1
SI 481205	Soil	<0.005	0.17	1.64	19.8	37	0.6	0.54	0.05	0.27	16.49	20.6	22	5.1	59.9
SI 481206	Soil	0.006	0.09	1.36	7.8	32	0.3	0.28	0.09	0.09	20.49	11.7	16	1.6	32.5
SI 481207	Soil	<0.005	0.10	1.78	14.9	36	0.4	0.48	0.06	0.17	25.56	16.6	27	4.2	50.0
SI 481208	Soil	0.008	0.09	1.99	23.2	21	0.4	0.68	<0.01	0.21	42.76	21.0	26	2.8	70.2
SI 481209	Soil	0.010	0.25	2.47	34.7	37	0.9	1.24	0.28	0.22	38.87	56.7	34	3.2	119.2
SI 481210	Soil	<0.005	0.10	2.68	13.2	22	0.4	0.51	0.08	0.10	41.34	20.9	36	2.2	56.8
SI 481211	Soil	0.012	0.17	1.88	39.1	38	0.6	0.69	0.12	0.14	41.04	22.4	25	3.4	64.1
SI 481212	Soil	0.007	0.20	1.78	26.6	33	0.4	0.60	0.18	0.07	33.61	14.4	23	3.9	37.9
SI 481213	Soil	0.009	0.15	2.69	22.8	30	0.6	0.66	0.08	0.10	49.78	22.6	35	1.8	64.1
SI 481214	Soil	0.011	0.11	2.07	29.8	45	0.6	0.69	0.10	0.10	38.21	16.0	29	3.6	53.8
SI 481215	Soil	0.009	0.08	2.80	40.2	31	0.5	0.54	0.04	0.11	20.17	21.7	39	3.7	48.1
SI 481216	Soil	0.005	0.14	2.28	16.9	44	0.5	0.42	0.14	0.11	25.23	15.8	33	4.9	37.5
SI 481217	Soil	0.012	0.06	2.42	37.9	46	0.5	1.12	0.14	0.13	25.10	26.5	32	2.7	50.3
SI 481218	Soil	0.007	0.03	2.02	44.2	30	0.4	0.68	0.05	0.13	22.69	19.0	30	3.6	48.8
SI 481219	Soil	0.009	0.11	1.85	28.5	33	0.3	0.59	0.01	0.21	26.67	24.9	29	4.2	50.0
SI 481220	Soil	0.013	0.19	2.39	37.8	41	0.4	0.59	0.01	0.16	30.36	26.9	34	3.1	54.7
SI 481221	Soil	0.013	0.12	2.06	43.6	36	0.5	0.71	0.04	0.13	28.08	32.9	27	3.0	53.8
SI 481222	Soil	0.042	0.31	1.69	120.8	27	0.7	0.58	0.58	0.21	26.46	28.2	25	9.2	71.7
SI 481223	Soil	0.015	0.12	2.20	32.5	39	0.6	0.57	0.03	0.15	29.63	20.0	29	2.4	45.8
SI 481224	Soil	0.006	0.19	1.95	39.0	33	0.4	0.54	<0.01	0.17	25.09	17.7	30	2.3	39.7
SI 481225	Soil	<0.005	0.13	2.12	44.7	23	0.6	0.78	0.02	0.13	16.40	31.1	28	2.7	75.0
SI 481226	Soil	0.006	0.17	1.82	36.2	32	0.5	0.46	0.03	0.12	22.08	18.2	26	2.4	45.0
SI 481227	Soil	<0.005	0.23	2.38	27.0	26	0.6	0.87	0.26	0.10	17.32	30.2	35	4.4	78.5
SI 481228	Soil	<0.005	0.18	2.65	44.3	24	0.6	1.15	0.10	0.10	23.36	39.3	36	5.2	78.2
SI 481229	Soil	0.016	0.30	2.07	47.8	29	0.6	1.13	0.41	0.16	29.32	40.3	29	3.1	83.8
SI 481230	Soil	0.047	0.14	1.28	122.0	30	0.4	0.44	<0.01	0.13	36.66	12.4	15	1.0	38.3
SI 481231	Soil	0.005	0.23	1.93	24.6	40	0.6	0.70	0.33	0.10	15.65	17.3	22	5.4	48.5
SI 481232	Soil	0.009	0.22	2.27	44.7	33	0.6	0.77	0.29	0.13	30.82	26.6	30	3.3	75.2
SI 481233	Soil	<0.005	0.32	2.51	29.2	30	0.8	0.71	0.31	0.20	36.25	37.4	33	6.1	100.5
SI 481234	Soil	0.009	0.32	2.10	34.7	42	0.7	0.62	0.37	0.16	19.48	23.6	31	10.0	69.7
SI 481235	Soil	0.020	0.20	2.15	89.5	30	0.6	0.54	0.01	0.13	38.51	21.0	29	2.7	64.3
SI 481236	Soil	0.012	0.18	1.03	40.9	31	0.2	0.50	0.02	0.10	23.40	8.7	15	2.2	29.0
SI 481237	Soil	0.024	0.67	1.13	132.3	29	0.3	0.55	0.01	0.16	21.06	14.0	18	4.0	41.1
SI 481238	Soil	0.033	0.28	1.37	121.5	32	0.3	0.42	0.02	0.18	21.93	12.9	18	4.8	34.7
SI 481239	Soil	0.031	0.14	1.37	102.1	32	0.2	0.43	0.02	0.08	25.74	9.1	19	3.2	25.3
SI 481240	Soil	<0.005	0.15	1.83	27.1	38	0.4	0.55	0.02	0.11	16.02	14.5	24	4.8	36.1
SI 481241	Soil	0.009	0.20	1.23	28.5	21	0.2	0.26	0.02	0.05	12.26	6.1	13	2.1	22.7
SI 481242	Soil	0.047	0.13	1.94	127.1	40	0.5	0.52	0.01	0.13	32.39	21.1	27	3.1	60.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481243	Soil	0.075	0.17	1.75	173.3	47	0.3	0.42	0.02	0.17	31.93	18.3	23	3.1	40.5
SI 481244	Soil	0.038	0.10	2.24	92.1	35	0.4	0.60	<0.01	0.07	20.35	10.3	29	4.1	51.6
SI 481245	Soil	0.099	0.24	2.01	171.6	45	0.7	0.76	0.03	0.09	44.19	37.0	24	3.8	79.7
SI 481246	Soil	0.049	0.21	2.01	108.3	33	0.4	0.53	<0.01	0.13	26.09	16.3	28	2.9	45.9
SI 481247	Soil	0.060	0.09	2.26	82.2	34	0.4	0.49	0.02	0.18	32.64	17.9	33	2.9	38.4
SI 481248	Soil	0.041	0.13	2.29	101.4	39	0.5	0.53	<0.01	0.13	45.87	24.8	32	4.1	59.2
SI 481249	Soil	0.093	0.19	2.09	24.9	30	0.2	0.47	0.01	0.11	28.13	18.4	30	3.2	32.0
SI 481250	Soil	0.014	0.13	2.49	28.1	36	0.4	0.57	0.02	0.17	36.91	23.4	34	3.4	50.2
SI 481251	Soil	0.010	0.05	2.42	36.3	30	0.3	0.68	0.03	0.12	41.24	19.6	38	2.4	43.9
SI 481252	Soil	0.009	0.12	2.08	44.6	32	0.4	0.48	0.03	0.16	22.22	15.5	31	4.3	42.5
SI 481253	Soil	<0.005	0.17	1.89	12.9	41	0.2	0.42	0.04	0.15	14.13	11.3	29	2.9	21.1
SI 481254	Soil	0.553	0.31	0.60	2307.9	35	0.4	0.51	0.03	0.90	24.96	22.9	<1	1.1	27.0
SI 481255	Soil	0.533	0.44	0.93	123.6	29	0.3	0.56	0.01	0.09	24.49	9.6	12	1.5	38.7
SI 481256	Soil	<0.005	0.23	1.08	35.5	68	0.4	0.41	0.05	0.40	15.76	6.6	13	1.9	39.9
SI 481257	Soil	0.020	0.20	0.88	62.6	34	0.2	0.34	0.05	0.06	13.93	5.0	8	1.3	26.5
SI 481258	Soil	0.040	0.20	1.08	106.9	27	0.3	0.41	0.01	0.09	16.70	11.1	15	2.5	35.6
SI 481259	Soil	0.035	0.36	1.24	60.8	48	0.3	0.44	0.02	0.28	16.61	7.4	20	2.1	35.2
SI 481260	Soil	0.061	0.37	1.53	308.4	31	0.3	0.50	0.02	0.20	20.03	14.0	22	2.3	41.7
SI 481261	Soil	0.069	0.21	1.07	336.6	41	0.3	0.31	0.02	0.26	19.82	23.3	12	0.9	24.7
SI 481262	Soil	0.087	0.32	0.89	352.2	41	0.2	0.36	0.01	0.15	17.91	9.6	10	1.3	24.0
SI 481263	Soil	0.819	0.42	0.65	1785.6	87	0.3	0.44	0.01	0.41	22.35	17.8	7	1.2	31.2
SI 481264	Soil	0.294	0.39	1.31	823.4	28	0.3	0.45	0.02	0.17	20.24	13.6	18	1.1	35.1
SI 481265	Soil	0.006	0.40	1.14	233.2	50	0.4	0.54	0.03	0.65	22.86	18.6	16	1.7	36.8
SI 481266	Soil	0.051	0.20	0.43	230.9	34	0.3	0.51	0.02	0.30	18.53	17.1	9	1.2	37.8
SI 481267	Soil	0.094	0.26	0.37	263.8	20	0.3	0.47	<0.01	0.20	37.85	13.8	7	1.1	38.5
SI 481268	Soil	0.044	0.19	0.56	66.4	26	0.3	0.34	<0.01	0.11	25.47	9.6	8	1.0	28.5
SI 481269	Soil	0.032	0.30	0.88	167.7	36	0.3	0.36	0.16	0.28	12.97	11.9	9	1.7	29.1
SI 481270	Soil	0.172	0.22	0.49	282.4	35	0.2	0.25	0.13	0.67	11.75	6.2	<1	0.8	15.4
SI 481271	Soil	0.043	0.50	1.37	114.5	36	0.4	0.37	0.07	0.56	20.66	12.6	16	3.5	39.5
SI 481272	Soil	0.007	0.21	1.98	42.6	27	0.5	0.50	0.09	0.11	22.30	20.8	25	2.2	58.9
SI 481273	Soil	0.092	0.52	0.33	519.6	24	0.2	0.41	0.01	0.11	22.49	12.8	9	1.1	32.9
SI 481274	Soil	0.326	0.24	0.40	734.5	42	0.1	0.33	<0.01	0.27	45.73	3.9	<1	0.7	15.0
SI 481275	Soil	0.030	0.14	1.16	128.0	32	0.2	0.50	0.02	0.15	35.48	6.9	12	1.6	20.0
SI 481276	Soil	<0.005	0.29	0.58	29.8	34	0.2	0.15	0.04	0.14	12.90	2.9	<1	0.9	8.9
SI 481277	Soil	0.033	0.34	1.28	136.1	54	0.3	0.36	0.02	0.18	28.42	11.2	14	1.0	26.6
SI 481278	Soil	0.044	0.24	1.38	123.8	29	0.3	0.38	<0.01	0.12	31.26	10.7	16	0.8	23.7
SI 481279	Soil	0.039	0.26	1.38	139.1	24	0.3	0.36	<0.01	0.11	44.00	12.0	15	0.8	25.1
SI 481280	Soil	0.101	0.30	1.01	335.2	59	0.5	0.59	0.13	0.13	38.64	16.1	13	3.5	47.9
SI 481281	Soil	0.026	0.27	1.62	115.3	29	0.5	0.46	0.02	0.16	34.47	19.0	20	1.6	51.9
SI 481282	Soil	0.016	0.16	1.54	116.2	43	0.5	0.54	0.27	0.19	26.28	19.5	19	4.7	37.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481283	Soil	<0.005	0.23	0.89	26.6	34	0.3	0.32	0.04	0.40	16.44	7.2	10	1.6	27.5
SI 481284	Soil	0.008	0.21	1.51	48.3	43	0.6	0.55	0.04	0.28	31.18	26.4	22	3.8	64.0
SI 481285	Soil	0.095	0.24	0.45	92.3	22	0.4	0.35	0.08	0.14	22.08	14.0	8	0.8	29.1
SI 481286	Soil	0.021	0.17	0.76	42.9	29	0.4	0.45	0.11	0.13	20.17	15.1	12	2.4	34.4
SI 481287	Soil	0.040	0.20	0.39	62.5	17	0.4	0.65	0.19	0.08	39.92	21.2	12	1.0	58.4
SI 481288	Soil	0.020	0.27	1.17	70.2	41	0.2	0.37	0.02	0.11	30.60	8.9	13	1.6	24.6
SI 481289	Soil	0.026	0.29	1.39	79.4	32	0.3	0.39	0.02	0.14	31.96	12.1	17	1.7	29.9
SI 481290	Soil	0.005	0.34	1.16	45.7	40	0.3	0.50	0.01	0.11	27.16	12.1	16	2.7	37.9
SI 481291	Soil	0.012	0.82	0.99	44.7	32	0.2	0.35	0.02	0.10	24.95	8.6	13	2.2	28.1
SI 481292	Soil	0.013	0.32	1.53	29.6	28	0.4	0.38	0.02	0.07	16.51	13.7	17	2.0	44.7
SI 481293	Soil	0.009	0.23	1.44	35.6	24	0.3	0.42	<0.01	0.06	18.53	9.6	17	2.5	37.1
SI 481294	Soil	0.006	0.24	1.49	36.8	26	0.4	0.49	0.04	0.08	17.22	9.5	18	2.8	43.8
SI 481295	Soil	0.017	0.16	1.57	60.3	25	0.4	0.62	0.01	0.11	20.19	8.3	19	3.0	43.8
SI 481296	Soil	0.010	0.28	1.50	64.7	39	0.3	0.47	0.03	0.17	32.41	12.0	18	2.7	38.1
SI 481297	Soil	0.005	0.28	1.00	33.7	37	0.3	0.38	0.02	0.15	20.89	8.7	11	2.4	28.6
SI 481298	Soil	0.011	0.20	1.43	77.3	39	0.3	0.97	0.02	0.09	37.25	11.9	20	2.6	31.8
SI 481299	Soil	0.030	0.12	0.93	106.2	33	0.2	0.35	0.01	0.07	28.03	9.0	11	1.7	24.7
SI 481300	Soil	0.078	0.14	1.02	149.2	52	0.2	0.41	0.02	0.10	33.78	10.3	13	2.3	27.3
SI 481301	Soil	0.056	0.12	0.82	188.6	38	0.2	0.32	0.01	0.11	27.73	9.3	11	3.6	23.5
SI 481302	Soil	0.169	0.19	2.06	109.3	34	0.4	0.77	0.02	0.13	38.95	25.5	27	6.3	52.9
SI 481303	Soil	<0.005	0.24	1.19	29.2	26	0.3	0.57	<0.01	0.10	30.58	18.6	17	4.1	46.8
SI 481304	Soil	<0.005	0.13	1.51	26.7	24	0.2	0.36	<0.01	0.08	28.90	9.2	20	2.7	20.9
TI 480142	Soil	0.025	0.43	1.21	107.3	19	0.6	0.69	0.25	0.22	48.49	26.0	19	2.5	64.2
TI 480143	Soil	0.098	0.71	1.84	182.2	50	0.6	0.48	0.55	0.24	22.32	16.7	25	13.9	45.6
TI 480144	Soil	0.015	0.25	2.00	110.1	35	0.7	0.64	0.24	0.21	32.10	24.0	30	9.1	60.1
TI 480145	Soil	0.014	0.38	1.94	96.6	34	0.5	0.66	0.32	0.23	34.92	24.0	29	5.8	56.9
TI 480146	Soil	0.016	0.64	2.18	98.4	31	0.5	0.67	0.29	0.16	36.59	27.8	31	4.9	64.2
TI 480147	Soil	0.054	0.23	1.91	94.6	27	0.4	0.59	0.21	0.16	23.32	22.9	28	3.2	52.9
TI 480148	Soil	0.071	0.38	1.88	316.1	39	0.7	0.50	1.04	1.88	16.13	16.2	25	10.5	70.4
TI 480149	Soil	<0.005	0.56	1.68	69.6	12	0.7	0.48	1.02	0.17	14.46	18.9	32	7.0	56.3
TI 481165	Soil	0.011	0.34	1.77	84.4	46	0.8	0.56	0.40	0.17	24.69	23.9	17	1.0	58.3
TI 481166	Soil	<0.005	0.24	1.91	38.0	34	0.6	0.55	0.32	0.10	26.34	21.9	22	0.7	49.7
TI 481167	Soil	<0.005	0.32	1.76	47.2	34	0.5	0.64	0.47	0.21	25.33	27.6	20	0.7	60.3
TI 481168	Soil	0.006	0.30	1.72	327.4	32	0.5	0.43	0.34	0.13	23.35	13.7	17	0.9	30.6
TI 481169	Soil	0.006	0.26	1.81	59.3	24	0.4	0.56	0.32	0.14	25.23	23.5	24	0.6	51.6
TI 481170	Soil	0.012	0.32	1.83	60.4	23	0.5	0.58	0.34	0.17	26.82	20.6	24	0.5	51.0
TI 481171	Soil	0.008	0.24	2.34	16.1	21	0.3	0.43	0.20	0.08	19.02	17.8	33	0.6	41.9
TI 481172	Soil	<0.005	0.34	1.84	59.6	27	0.5	0.56	0.35	0.14	20.71	20.8	25	0.5	50.8
TI 481173	Soil	<0.005	0.33	2.06	15.1	20	0.6	0.39	0.36	0.07	22.24	13.9	28	1.5	38.6
TI 481174	Soil	0.005	0.24	1.86	42.2	22	0.4	0.41	0.35	0.15	22.59	17.1	27	0.7	45.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
TI 481175	Soil	<0.005	0.34	1.79	38.2	24	0.4	0.40	0.34	0.17	23.80	17.9	26	0.5	40.0
TI 481176	Soil	<0.005	0.22	1.85	55.7	29	0.4	0.32	0.41	0.12	23.67	14.7	28	0.4	26.6
TI 481177	Soil	0.009	0.25	1.81	54.8	25	0.4	0.48	0.32	0.16	25.56	18.6	28	0.5	39.9
TI 481178	Soil	<0.005	0.23	1.86	57.3	28	0.4	0.31	0.46	0.06	19.82	16.0	23	0.5	22.6
TI 481179	Soil	0.011	0.47	1.86	85.8	24	0.4	0.45	0.97	0.08	29.37	20.3	25	0.4	41.1
TI 481180	Soil	<0.005	0.27	1.90	46.9	21	0.4	0.40	0.27	0.08	20.82	16.1	25	0.5	36.0
TI 481181	Soil	<0.005	0.23	1.87	53.3	26	0.4	0.39	0.37	0.09	20.92	17.7	27	0.6	34.3
TI 481201	Soil	0.005	0.16	2.04	45.5	23	0.4	0.39	0.32	0.09	23.05	17.4	28	0.5	34.4
TI 481202	Soil	0.007	0.23	1.90	29.4	36	0.4	0.38	0.89	0.14	17.30	15.2	24	0.9	39.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481203	Soil	3.69	5.1	<0.05	0.03	0.03	0.02	11.1	49.5	0.58	808	0.66	0.01	0.2	28.9
SI 481204	Soil	5.38	7.0	<0.05	<0.02	0.04	0.04	12.2	57.6	0.70	1610	0.84	<0.01	0.3	38.5
SI 481205	Soil	3.92	6.4	<0.05	0.03	0.03	0.04	9.2	48.4	0.55	1013	0.76	0.01	0.2	26.9
SI 481206	Soil	2.62	4.4	<0.05	<0.02	0.01	0.03	11.9	44.4	0.55	475	0.39	0.02	0.1	26.4
SI 481207	Soil	4.63	7.1	<0.05	<0.02	0.03	0.03	14.6	58.5	0.74	581	0.71	0.01	0.2	36.6
SI 481208	Soil	5.11	6.6	<0.05	<0.02	0.04	0.02	26.3	65.7	0.89	892	1.07	<0.01	0.1	47.8
SI 481209	Soil	6.00	9.1	<0.05	<0.02	0.10	0.02	19.5	87.2	1.10	2212	0.63	<0.01	<0.05	60.7
SI 481210	Soil	5.51	9.0	<0.05	<0.02	0.03	0.02	24.5	92.7	1.22	429	0.44	<0.01	<0.05	53.3
SI 481211	Soil	4.35	6.9	<0.05	<0.02	0.03	0.03	23.0	60.9	0.78	628	0.50	0.01	0.1	47.5
SI 481212	Soil	4.57	8.8	<0.05	<0.02	0.03	0.03	18.1	43.0	0.62	477	0.89	<0.01	0.2	34.9
SI 481213	Soil	6.15	9.1	<0.05	<0.02	0.04	0.02	28.4	93.3	1.22	627	0.64	<0.01	<0.05	61.9
SI 481214	Soil	4.71	7.2	<0.05	<0.02	0.04	0.02	21.8	63.3	0.87	405	0.66	<0.01	<0.05	49.8
SI 481215	Soil	5.65	9.7	<0.05	<0.02	0.03	0.02	9.4	93.4	1.18	414	0.67	<0.01	0.1	55.2
SI 481216	Soil	4.67	7.9	<0.05	<0.02	0.03	0.02	12.9	79.5	0.94	394	0.63	0.01	<0.05	47.4
SI 481217	Soil	6.20	8.3	<0.05	<0.02	0.04	0.02	11.4	85.0	1.04	2073	0.60	<0.01	0.1	54.1
SI 481218	Soil	4.83	8.2	<0.05	<0.02	0.04	0.02	11.4	66.1	0.79	499	0.73	<0.01	0.1	39.8
SI 481219	Soil	4.83	8.3	<0.05	0.03	0.04	0.02	13.9	54.0	0.67	703	0.78	<0.01	0.2	38.5
SI 481220	Soil	5.46	8.2	<0.05	<0.02	0.04	0.03	14.6	76.6	0.96	663	0.71	<0.01	0.1	50.6
SI 481221	Soil	5.02	7.2	<0.05	<0.02	0.04	0.02	12.6	64.4	0.85	1112	0.73	<0.01	0.1	46.9
SI 481222	Soil	4.45	5.3	<0.05	<0.02	0.04	0.02	14.0	46.5	0.71	687	1.10	0.01	0.1	49.1
SI 481223	Soil	5.09	7.5	<0.05	<0.02	0.04	0.02	14.0	72.2	0.89	650	0.56	<0.01	0.1	48.7
SI 481224	Soil	5.06	8.5	<0.05	<0.02	0.03	0.03	12.4	55.0	0.72	603	0.71	<0.01	0.3	39.2
SI 481225	Soil	4.81	7.0	<0.05	<0.02	0.04	0.02	6.7	66.4	0.91	467	0.75	<0.01	<0.05	50.1
SI 481226	Soil	4.45	6.8	<0.05	<0.02	0.03	0.03	10.8	54.7	0.70	457	0.49	<0.01	0.1	40.5
SI 481227	Soil	5.32	8.3	<0.05	<0.02	0.04	0.02	7.9	81.2	1.07	529	0.69	<0.01	<0.05	55.6
SI 481228	Soil	5.84	8.7	<0.05	<0.02	0.04	0.02	10.2	89.0	1.19	463	0.77	<0.01	<0.05	61.3
SI 481229	Soil	5.47	6.9	<0.05	<0.02	0.04	0.02	14.6	71.0	0.95	780	0.96	<0.01	<0.05	56.6
SI 481230	Soil	4.73	4.7	<0.05	<0.02	0.02	0.03	20.4	32.1	0.41	285	0.80	<0.01	0.3	30.6
SI 481231	Soil	3.91	6.4	<0.05	<0.02	0.03	0.02	7.2	56.5	0.75	396	0.51	0.01	0.2	37.5
SI 481232	Soil	5.70	7.4	<0.05	<0.02	0.05	0.02	16.3	76.9	0.97	750	0.87	<0.01	<0.05	57.9
SI 481233	Soil	6.70	8.3	<0.05	<0.02	0.06	0.02	16.9	83.2	1.04	1252	0.80	<0.01	<0.05	65.9
SI 481234	Soil	4.80	7.2	<0.05	<0.02	0.04	0.03	10.4	71.9	0.85	592	0.92	<0.01	0.1	51.5
SI 481235	Soil	5.27	6.7	<0.05	<0.02	0.03	0.03	22.0	69.5	0.83	560	0.47	<0.01	0.1	47.6
SI 481236	Soil	2.57	5.4	<0.05	<0.02	0.02	0.02	12.6	19.3	0.26	302	0.62	<0.01	0.2	14.9
SI 481237	Soil	4.24	7.7	<0.05	<0.02	0.03	0.03	10.9	22.1	0.31	593	0.82	<0.01	0.3	22.3
SI 481238	Soil	3.50	5.4	<0.05	<0.02	0.02	0.03	11.2	28.9	0.37	556	0.66	0.01	0.2	21.8
SI 481239	Soil	3.35	5.7	<0.05	<0.02	0.02	0.03	13.1	26.3	0.36	309	0.64	0.01	0.3	20.0
SI 481240	Soil	3.96	6.5	<0.05	<0.02	0.03	0.02	7.3	51.2	0.69	603	0.62	0.01	0.1	33.1
SI 481241	Soil	2.09	4.1	<0.05	<0.02	0.01	0.02	5.9	25.6	0.33	152	0.40	0.01	0.1	17.3
SI 481242	Soil	4.97	7.2	<0.05	<0.02	0.03	0.03	17.0	51.5	0.73	410	0.74	<0.01	0.2	43.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481243	Soil	3.97	5.9	<0.05	<0.02	0.03	0.03	17.3	40.9	0.54	494	0.59	<0.01	0.1	35.8
SI 481244	Soil	4.92	7.9	<0.05	<0.02	0.03	0.02	9.3	64.3	0.88	318	0.77	<0.01	<0.05	42.6
SI 481245	Soil	5.54	6.7	<0.05	<0.02	0.04	0.02	23.9	65.0	0.82	927	0.63	<0.01	<0.05	56.9
SI 481246	Soil	4.69	7.4	<0.05	<0.02	0.03	0.02	12.9	61.2	0.75	412	0.55	<0.01	0.1	43.5
SI 481247	Soil	4.96	8.2	<0.05	<0.02	0.03	0.03	15.9	71.6	0.92	468	0.59	<0.01	0.2	47.7
SI 481248	Soil	5.18	7.9	<0.05	<0.02	0.03	0.03	22.9	72.7	0.91	680	0.54	<0.01	0.1	52.7
SI 481249	Soil	4.49	8.0	<0.05	<0.02	0.03	0.03	13.1	63.1	0.84	556	0.50	<0.01	0.3	39.3
SI 481250	Soil	5.31	8.6	<0.05	<0.02	0.03	0.02	18.4	73.3	0.93	671	0.68	<0.01	0.2	43.9
SI 481251	Soil	5.24	8.5	<0.05	<0.02	0.03	0.02	21.9	73.6	1.00	434	0.72	<0.01	0.2	46.1
SI 481252	Soil	4.72	8.5	<0.05	<0.02	0.03	0.03	10.9	57.0	0.74	521	0.65	<0.01	0.2	36.9
SI 481253	Soil	4.22	8.5	<0.05	<0.02	0.02	0.02	6.4	42.1	0.55	904	0.91	<0.01	0.3	24.2
SI 481254	Soil	3.89	1.0	<0.05	<0.02	0.04	0.03	12.0	4.3	0.07	866	0.48	<0.01	<0.05	32.9
SI 481255	Soil	3.76	3.2	<0.05	<0.02	0.02	0.03	14.3	21.4	0.28	233	0.81	<0.01	0.1	21.5
SI 481256	Soil	3.86	4.8	<0.05	<0.02	0.02	0.05	9.3	15.9	0.20	309	0.81	0.01	0.5	19.5
SI 481257	Soil	2.34	3.2	<0.05	<0.02	0.02	0.03	7.6	16.2	0.22	221	0.71	0.02	0.2	12.6
SI 481258	Soil	3.29	4.5	<0.05	<0.02	0.02	0.03	9.6	24.3	0.30	311	0.77	0.01	0.2	22.0
SI 481259	Soil	3.86	6.0	<0.05	<0.02	0.02	0.03	9.1	18.1	0.21	508	0.80	0.01	0.3	17.3
SI 481260	Soil	4.69	5.5	<0.05	<0.02	0.04	0.03	10.8	30.6	0.39	574	0.70	<0.01	0.3	27.8
SI 481261	Soil	3.74	3.5	<0.05	<0.02	0.02	0.03	10.1	16.7	0.21	889	0.61	<0.01	0.1	27.0
SI 481262	Soil	3.47	4.4	<0.05	<0.02	0.02	0.03	9.6	12.7	0.15	588	0.60	<0.01	0.2	17.4
SI 481263	Soil	5.10	3.4	<0.05	<0.02	0.03	0.02	11.7	7.3	0.11	1425	0.72	<0.01	0.1	29.4
SI 481264	Soil	4.90	3.9	<0.05	<0.02	0.03	0.03	10.8	25.3	0.34	383	0.49	<0.01	0.2	29.6
SI 481265	Soil	4.82	5.3	<0.05	<0.02	0.03	0.04	12.6	16.2	0.22	1138	0.70	<0.01	0.2	26.8
SI 481266	Soil	3.11	2.3	<0.05	<0.02	0.02	0.02	10.8	4.5	0.04	368	0.57	<0.01	0.1	30.1
SI 481267	Soil	2.77	1.4	<0.05	<0.02	0.02	0.02	22.8	6.0	0.08	228	0.37	<0.01	<0.05	27.0
SI 481268	Soil	2.41	2.3	<0.05	<0.02	0.02	0.02	13.8	11.8	0.14	225	0.42	<0.01	<0.05	20.1
SI 481269	Soil	2.52	3.2	<0.05	<0.02	0.02	0.03	7.2	22.6	0.26	364	0.53	<0.01	0.1	21.4
SI 481270	Soil	1.57	1.9	<0.05	<0.02	0.02	0.02	6.1	7.2	0.08	239	0.29	0.01	0.1	10.6
SI 481271	Soil	3.62	4.8	<0.05	<0.02	0.04	0.03	11.8	41.3	0.47	428	0.52	<0.01	0.1	29.6
SI 481272	Soil	4.72	5.9	<0.05	<0.02	0.02	0.02	12.8	81.3	0.79	439	0.40	<0.01	0.1	47.7
SI 481273	Soil	3.40	2.1	<0.05	<0.02	0.02	0.02	11.7	2.5	0.06	472	0.57	<0.01	0.1	19.2
SI 481274	Soil	2.26	3.9	<0.05	<0.02	0.02	0.02	23.8	0.7	0.02	94	0.42	<0.01	0.1	8.7
SI 481275	Soil	4.03	5.9	<0.05	<0.02	0.02	0.03	20.1	23.6	0.27	248	0.66	<0.01	0.6	16.3
SI 481276	Soil	1.11	2.6	<0.05	<0.02	<0.01	0.03	6.4	2.6	0.03	127	0.43	0.02	0.2	5.6
SI 481277	Soil	3.90	3.6	<0.05	<0.02	0.02	0.03	14.9	33.0	0.40	832	0.45	<0.01	0.1	25.3
SI 481278	Soil	3.99	3.9	<0.05	<0.02	0.02	0.03	16.7	32.5	0.40	316	0.55	<0.01	0.2	24.4
SI 481279	Soil	3.87	3.5	<0.05	<0.02	0.02	0.03	24.2	38.7	0.47	311	0.40	<0.01	<0.05	28.9
SI 481280	Soil	4.20	2.9	<0.05	<0.02	0.02	0.04	21.9	25.1	0.32	438	0.74	<0.01	<0.05	34.2
SI 481281	Soil	4.66	4.6	<0.05	<0.02	0.02	0.03	20.2	50.7	0.58	402	0.51	<0.01	0.1	40.5
SI 481282	Soil	4.31	5.7	<0.05	<0.02	0.03	0.04	13.9	42.3	0.57	726	0.63	0.01	0.2	34.0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481283	Soil	2.51	3.6	<0.05	<0.02	0.01	0.02	9.2	15.8	0.22	209	0.39	0.01	0.2	14.6
SI 481284	Soil	5.01	5.8	<0.05	<0.02	0.03	0.04	16.3	42.7	0.49	440	0.70	<0.01	0.2	35.0
SI 481285	Soil	3.37	1.6	<0.05	<0.02	0.03	0.02	12.2	8.7	0.11	524	0.44	<0.01	<0.05	27.2
SI 481286	Soil	3.27	2.7	<0.05	<0.02	0.02	0.03	11.5	19.2	0.21	435	0.43	<0.01	0.1	30.6
SI 481287	Soil	3.78	1.6	<0.05	<0.02	0.02	0.03	24.6	8.5	0.13	617	0.44	<0.01	<0.05	40.2
SI 481288	Soil	3.33	4.8	<0.05	<0.02	0.02	0.03	17.1	20.5	0.24	413	0.65	<0.01	0.3	18.9
SI 481289	Soil	4.18	4.6	<0.05	<0.02	0.02	0.04	17.8	27.3	0.35	557	0.64	<0.01	0.2	26.8
SI 481290	Soil	3.98	5.9	<0.05	<0.02	0.02	0.04	14.9	17.1	0.20	562	0.86	<0.01	0.3	21.6
SI 481291	Soil	3.50	5.1	<0.05	<0.02	0.02	0.04	13.6	14.0	0.19	359	0.66	0.01	0.2	16.3
SI 481292	Soil	3.56	4.1	<0.05	<0.02	0.02	0.03	9.3	38.0	0.49	309	0.59	0.01	0.1	35.9
SI 481293	Soil	3.80	4.3	<0.05	<0.02	0.02	0.03	10.8	32.3	0.42	252	0.67	<0.01	0.2	26.9
SI 481294	Soil	4.25	4.2	<0.05	<0.02	0.02	0.03	9.9	36.2	0.46	260	0.74	<0.01	0.1	28.9
SI 481295	Soil	4.49	4.7	<0.05	<0.02	0.02	0.04	11.5	32.8	0.42	250	1.02	<0.01	0.2	25.3
SI 481296	Soil	4.59	5.7	<0.05	<0.02	0.02	0.05	17.8	32.4	0.41	427	0.79	<0.01	0.3	26.6
SI 481297	Soil	3.45	5.3	<0.05	<0.02	0.02	0.04	11.7	16.9	0.21	383	0.67	0.01	0.3	16.2
SI 481298	Soil	4.31	6.2	<0.05	<0.02	0.03	0.05	20.2	28.9	0.44	503	0.82	<0.01	0.3	27.4
SI 481299	Soil	3.23	4.4	<0.05	<0.02	0.02	0.03	15.1	13.2	0.19	313	0.67	<0.01	0.2	17.2
SI 481300	Soil	3.84	5.2	<0.05	<0.02	0.02	0.04	17.9	14.1	0.18	430	0.78	<0.01	0.2	19.6
SI 481301	Soil	3.34	4.5	<0.05	<0.02	0.02	0.03	14.9	8.6	0.13	570	0.68	<0.01	0.2	18.4
SI 481302	Soil	5.75	6.0	<0.05	<0.02	0.03	0.02	22.0	51.4	0.80	687	0.52	<0.01	<0.05	47.3
SI 481303	Soil	6.16	4.8	<0.05	<0.02	0.03	0.02	17.4	22.6	0.36	736	0.67	<0.01	0.1	34.9
SI 481304	Soil	3.64	6.2	<0.05	<0.02	0.02	0.02	16.5	28.7	0.45	231	0.53	0.01	0.2	23.2
TI 480142	Soil	4.76	3.9	<0.05	<0.02	0.03	0.03	27.8	39.4	0.54	905	0.75	<0.01	<0.05	52.6
TI 480143	Soil	4.50	5.0	<0.05	<0.02	0.03	0.04	12.4	54.9	0.74	436	0.52	0.01	0.1	40.5
TI 480144	Soil	5.55	6.3	<0.05	<0.02	0.04	0.03	16.6	74.0	0.91	710	0.69	<0.01	0.1	49.1
TI 480145	Soil	5.31	6.3	<0.05	<0.02	0.03	0.03	19.2	70.4	0.87	588	0.57	<0.01	0.1	50.7
TI 480146	Soil	5.91	6.9	<0.05	<0.02	0.04	0.03	19.4	79.6	1.00	726	0.63	<0.01	0.1	55.7
TI 480147	Soil	5.21	6.2	<0.05	<0.02	0.03	0.02	12.1	72.6	0.88	599	0.49	<0.01	0.1	48.2
TI 480148	Soil	4.17	5.2	<0.05	<0.02	0.03	0.03	9.0	63.1	0.82	468	0.40	0.01	0.2	40.1
TI 480149	Soil	3.79	4.4	<0.05	<0.02	0.02	0.04	7.9	58.4	0.90	742	0.65	0.01	0.2	35.8
TI 481165	Soil	4.42	4.0	<0.05	<0.02	0.04	0.05	12.9	45.0	0.65	348	0.59	0.01	0.2	38.4
TI 481166	Soil	4.66	5.3	<0.05	<0.02	0.02	0.04	14.2	67.3	0.83	412	0.36	0.01	0.1	41.0
TI 481167	Soil	4.76	4.8	<0.05	<0.02	0.03	0.05	13.7	62.0	0.87	703	0.61	0.01	<0.05	41.5
TI 481168	Soil	3.74	4.3	<0.05	<0.02	0.02	0.04	12.2	49.4	0.73	355	0.52	0.01	0.2	33.3
TI 481169	Soil	4.33	4.9	<0.05	<0.02	0.02	0.03	13.8	66.2	0.87	552	0.58	<0.01	0.1	41.9
TI 481170	Soil	4.53	4.9	<0.05	<0.02	0.02	0.02	14.4	65.0	1.00	741	0.58	<0.01	<0.05	41.1
TI 481171	Soil	4.78	6.5	<0.05	<0.02	0.02	0.02	9.5	81.0	1.13	507	0.42	<0.01	0.1	47.5
TI 481172	Soil	4.32	5.0	<0.05	<0.02	0.02	0.03	11.0	65.5	0.95	552	0.42	<0.01	0.1	39.2
TI 481173	Soil	4.28	5.6	<0.05	<0.02	0.02	0.03	11.6	71.6	0.95	337	0.48	0.01	0.1	33.9
TI 481174	Soil	4.44	5.2	<0.05	<0.02	0.02	0.03	12.0	65.4	0.99	551	0.46	<0.01	0.1	40.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
TI 481175	Soil	4.13	5.0	<0.05	<0.02	0.02	0.03	12.8	68.5	0.93	677	0.44	<0.01	0.1	37.9
TI 481176	Soil	4.01	5.3	<0.05	<0.02	0.02	0.02	12.8	67.1	0.88	663	0.35	<0.01	0.2	38.4
TI 481177	Soil	4.27	5.3	<0.05	<0.02	0.02	0.02	13.5	68.1	0.97	803	0.62	<0.01	0.1	39.8
TI 481178	Soil	4.16	5.3	<0.05	<0.02	0.02	0.02	10.7	73.8	0.87	528	0.26	<0.01	0.1	40.2
TI 481179	Soil	4.69	5.1	<0.05	<0.02	0.02	0.02	15.6	75.5	0.92	750	0.35	<0.01	0.1	43.4
TI 481180	Soil	4.17	5.0	<0.05	<0.02	0.02	0.02	10.8	69.6	0.89	411	0.37	<0.01	0.1	40.9
TI 481181	Soil	4.16	5.2	<0.05	<0.02	0.02	0.02	11.4	76.5	0.76	714	0.38	<0.01	0.1	40.8
TI 481201	Soil	4.61	5.7	<0.05	<0.02	0.02	0.02	12.2	81.8	1.01	664	0.34	<0.01	0.1	41.7
TI 481202	Soil	4.30	5.3	<0.05	<0.02	0.02	0.03	9.5	69.3	0.91	673	0.34	<0.01	0.2	40.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481203	Soil	813	27.9	3.4	<0.01	0.03	0.15	0.6	0.3	<0.2	4.4	<0.01	0.10	1	<0.005
SI 481204	Soil	1141	46.8	7.2	<0.01	0.06	1.10	0.9	0.4	<0.2	4.1	<0.01	0.23	1	0.006
SI 481205	Soil	1334	52.9	6.1	<0.01	0.07	0.45	0.5	0.5	<0.2	6.0	<0.01	0.13	1	0.005
SI 481206	Soil	605	18.3	3.0	<0.01	0.01	<0.05	0.6	<0.2	<0.2	7.0	<0.01	0.09	0	0.006
SI 481207	Soil	807	24.6	5.7	<0.01	0.04	0.18	0.7	0.3	<0.2	6.7	<0.01	0.13	1	<0.005
SI 481208	Soil	376	31.2	4.7	<0.01	0.01	1.60	2.8	0.4	0.2	2.3	<0.01	0.21	4	<0.005
SI 481209	Soil	1030	54.7	3.3	<0.01	0.01	0.89	4.0	0.8	<0.2	15.9	<0.01	0.40	7	<0.005
SI 481210	Soil	575	20.4	2.6	<0.01	<0.01	<0.05	2.0	<0.2	0.2	4.7	<0.01	0.18	6	<0.005
SI 481211	Soil	511	39.5	4.3	<0.01	0.02	0.13	1.6	0.3	<0.2	9.6	<0.01	0.21	2	<0.005
SI 481212	Soil	1096	26.5	5.2	<0.01	0.02	0.28	0.7	0.4	0.3	11.3	<0.01	0.23	1	<0.005
SI 481213	Soil	287	26.9	3.1	<0.01	<0.01	0.26	3.5	0.3	0.3	6.2	<0.01	0.21	9	<0.005
SI 481214	Soil	478	16.4	5.7	<0.01	0.02	1.76	1.8	0.4	<0.2	8.1	<0.01	0.20	2	<0.005
SI 481215	Soil	420	29.4	4.2	<0.01	0.01	<0.05	1.7	0.4	<0.2	5.6	<0.01	0.22	3	<0.005
SI 481216	Soil	665	16.8	6.1	<0.01	0.02	<0.05	1.3	<0.2	<0.2	10.2	<0.01	0.09	1	<0.005
SI 481217	Soil	446	26.0	3.8	<0.01	0.01	<0.05	2.5	0.3	<0.2	9.9	<0.01	0.26	4	<0.005
SI 481218	Soil	802	25.9	4.2	<0.01	0.02	0.08	0.7	0.4	<0.2	7.3	<0.01	0.20	1	0.169
SI 481219	Soil	1103	45.1	5.1	<0.01	0.03	<0.05	0.8	0.4	<0.2	4.6	<0.01	0.19	1	<0.005
SI 481220	Soil	565	36.1	4.6	<0.01	0.01	<0.05	1.2	<0.2	<0.2	4.2	<0.01	0.15	1	<0.005
SI 481221	Soil	650	39.6	3.3	<0.01	0.02	<0.05	1.2	0.4	<0.2	3.9	<0.01	0.18	1	<0.005
SI 481222	Soil	609	37.4	3.7	<0.01	0.06	1.09	2.4	2.8	<0.2	22.3	<0.01	0.18	2	<0.005
SI 481223	Soil	476	37.4	4.6	<0.01	<0.01	<0.05	1.7	0.5	<0.2	4.6	<0.01	0.13	2	<0.005
SI 481224	Soil	695	25.1	4.8	<0.01	0.01	<0.05	0.8	<0.2	<0.2	3.8	<0.01	0.11	1	<0.005
SI 481225	Soil	490	42.2	2.5	<0.01	0.01	<0.05	1.5	0.6	<0.2	4.8	<0.01	0.19	2	<0.005
SI 481226	Soil	658	29.7	4.2	<0.01	0.02	<0.05	0.8	0.4	<0.2	4.3	<0.01	0.15	1	<0.005
SI 481227	Soil	555	35.8	3.3	<0.01	0.01	<0.05	2.6	0.3	<0.2	11.6	<0.01	0.26	3	<0.005
SI 481228	Soil	249	38.3	3.4	<0.01	<0.01	<0.05	3.1	<0.2	0.2	5.9	<0.01	0.30	9	<0.005
SI 481229	Soil	450	39.4	3.1	<0.01	0.02	<0.05	3.8	0.3	<0.2	14.0	<0.01	0.31	7	<0.005
SI 481230	Soil	518	29.0	4.2	<0.01	0.01	1.11	1.1	0.5	<0.2	5.5	<0.01	0.16	3	0.005
SI 481231	Soil	528	24.1	4.2	<0.01	0.03	<0.05	2.1	0.4	<0.2	12.8	<0.01	0.12	2	<0.005
SI 481232	Soil	463	38.8	3.4	<0.01	0.02	0.21	3.4	<0.2	<0.2	12.5	<0.01	0.16	6	<0.005
SI 481233	Soil	692	46.7	3.3	<0.01	0.01	0.78	5.1	0.5	0.2	13.1	<0.01	0.20	10	<0.005
SI 481234	Soil	788	37.0	5.5	<0.01	0.04	<0.05	2.0	0.6	<0.2	12.8	<0.01	0.20	2	<0.005
SI 481235	Soil	443	54.9	4.0	<0.01	<0.01	<0.05	1.1	0.4	<0.2	3.8	<0.01	0.12	2	<0.005
SI 481236	Soil	830	28.4	4.9	<0.01	0.03	0.12	0.2	0.5	0.2	4.4	<0.01	0.09	<0.2	<0.005
SI 481237	Soil	877	30.3	6.6	<0.01	0.04	0.48	0.3	0.5	0.2	3.8	<0.01	0.18	<0.2	<0.005
SI 481238	Soil	673	24.4	6.1	<0.01	0.03	0.27	0.3	0.4	<0.2	6.1	<0.01	0.11	0	<0.005
SI 481239	Soil	729	17.4	5.3	<0.01	0.03	<0.05	0.3	0.6	0.2	4.8	<0.01	0.08	0	<0.005
SI 481240	Soil	837	20.6	5.5	<0.01	0.03	0.17	0.7	0.3	<0.2	4.6	<0.01	0.17	1	<0.005
SI 481241	Soil	579	14.5	3.4	<0.01	0.02	<0.05	0.3	0.2	<0.2	3.9	<0.01	0.09	0	<0.005
SI 481242	Soil	594	29.7	5.2	<0.01	0.01	0.36	1.6	0.5	<0.2	7.0	<0.01	0.15	2	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481243	Soil	643	30.1	6.2	<0.01	0.02	0.52	0.7	0.4	<0.2	6.5	<0.01	0.16	1	<0.005
SI 481244	Soil	348	28.4	4.5	<0.01	0.01	1.18	1.9	0.5	<0.2	5.1	<0.01	0.20	3	<0.005
SI 481245	Soil	230	42.8	4.4	<0.01	<0.01	2.10	2.8	0.6	0.2	5.5	<0.01	0.22	6	<0.005
SI 481246	Soil	582	29.2	5.8	<0.01	0.02	0.19	1.1	0.6	<0.2	3.3	<0.01	0.19	1	<0.005
SI 481247	Soil	646	30.3	4.9	<0.01	0.02	<0.05	1.2	0.6	<0.2	4.8	<0.01	0.14	2	<0.005
SI 481248	Soil	360	31.2	5.1	<0.01	<0.01	0.27	1.8	0.5	0.2	3.8	<0.01	0.11	4	<0.005
SI 481249	Soil	537	19.2	4.7	<0.01	0.02	<0.05	1.0	0.4	0.3	3.7	<0.01	0.14	1	0.006
SI 481250	Soil	940	39.1	5.8	<0.01	0.02	<0.05	0.9	0.6	0.2	3.5	<0.01	0.17	1	<0.005
SI 481251	Soil	686	30.3	4.1	<0.01	0.01	<0.05	1.1	0.4	0.2	3.8	<0.01	0.14	1	0.006
SI 481252	Soil	1052	21.6	5.8	<0.01	0.04	<0.05	0.8	0.7	<0.2	3.6	<0.01	0.08	1	<0.005
SI 481253	Soil	1191	27.6	3.6	<0.01	0.05	<0.05	0.8	0.6	0.2	4.7	<0.01	0.13	1	<0.005
SI 481254	Soil	736	140.3	3.0	<0.01	0.01	2.77	1.4	0.8	<0.2	9.6	<0.01	0.13	5	<0.005
SI 481255	Soil	326	41.3	4.0	<0.01	0.02	4.18	0.9	0.3	<0.2	7.4	<0.01	0.19	3	<0.005
SI 481256	Soil	761	18.4	7.2	<0.01	0.04	1.76	0.3	0.5	0.2	15.6	<0.01	0.14	<0.2	0.006
SI 481257	Soil	482	24.0	4.1	<0.01	0.02	2.81	0.6	0.4	<0.2	10.7	<0.01	0.10	1	0.009
SI 481258	Soil	755	26.9	4.5	<0.01	0.04	1.42	0.3	0.7	<0.2	7.7	<0.01	0.14	<0.2	<0.005
SI 481259	Soil	1434	29.1	5.8	<0.01	0.05	0.45	0.2	0.9	<0.2	8.2	<0.01	0.14	<0.2	<0.005
SI 481260	Soil	858	131.3	6.3	<0.01	0.03	0.82	0.4	0.7	<0.2	10.0	<0.01	0.19	0	<0.005
SI 481261	Soil	515	38.3	3.8	<0.01	0.02	0.43	0.3	0.6	<0.2	6.3	<0.01	0.08	0	<0.005
SI 481262	Soil	672	31.5	5.9	<0.01	0.02	0.50	0.2	0.6	<0.2	4.7	<0.01	0.08	<0.2	<0.005
SI 481263	Soil	572	45.3	6.0	<0.01	0.02	2.13	0.4	0.5	<0.2	5.6	<0.01	0.34	0	<0.005
SI 481264	Soil	677	36.4	4.2	<0.01	0.02	0.77	0.4	0.6	<0.2	7.1	<0.01	0.16	0	<0.005
SI 481265	Soil	913	28.2	7.1	<0.01	0.03	0.51	0.3	0.7	<0.2	7.7	<0.01	0.16	0	<0.005
SI 481266	Soil	434	30.3	4.2	<0.01	0.01	1.50	0.4	0.2	<0.2	17.8	<0.01	0.19	1	<0.005
SI 481267	Soil	242	39.2	3.6	<0.01	<0.01	1.00	0.8	0.2	<0.2	10.6	<0.01	0.16	6	<0.005
SI 481268	Soil	383	21.2	3.4	<0.01	<0.01	0.55	0.4	<0.2	<0.2	13.3	<0.01	0.11	0	<0.005
SI 481269	Soil	702	29.0	5.4	<0.01	0.03	0.48	0.5	0.4	<0.2	20.9	<0.01	0.13	1	<0.005
SI 481270	Soil	412	47.9	3.4	<0.01	0.02	0.60	0.4	0.3	<0.2	16.9	<0.01	0.05	0	<0.005
SI 481271	Soil	520	48.8	5.4	<0.01	0.02	0.38	0.6	0.3	<0.2	12.7	<0.01	0.11	1	<0.005
SI 481272	Soil	310	48.8	3.3	<0.01	<0.01	<0.05	1.5	0.3	<0.2	12.1	<0.01	0.15	4	<0.005
SI 481273	Soil	556	37.2	4.4	<0.01	0.01	0.38	0.3	0.3	<0.2	7.2	<0.01	0.21	<0.2	<0.005
SI 481274	Soil	383	33.0	4.0	<0.01	<0.01	0.65	0.2	0.3	<0.2	5.6	<0.01	0.13	<0.2	<0.005
SI 481275	Soil	541	18.3	7.5	<0.01	0.02	0.05	0.9	0.3	0.4	4.4	<0.01	0.11	5	0.007
SI 481276	Soil	437	17.8	3.9	<0.01	0.03	0.11	0.1	<0.2	<0.2	7.2	<0.01	0.04	<0.2	<0.005
SI 481277	Soil	539	26.5	3.7	<0.01	0.01	0.14	0.5	0.4	<0.2	5.9	<0.01	0.11	1	<0.005
SI 481278	Soil	541	24.4	3.6	<0.01	0.02	<0.05	0.5	0.4	<0.2	5.1	<0.01	0.10	1	<0.005
SI 481279	Soil	382	28.1	3.6	<0.01	<0.01	0.25	0.7	0.4	<0.2	4.4	<0.01	0.07	2	<0.005
SI 481280	Soil	511	31.3	6.5	<0.01	0.01	2.45	1.2	0.4	<0.2	24.1	<0.01	0.15	2	<0.005
SI 481281	Soil	422	38.3	3.5	<0.01	0.01	<0.05	1.1	0.4	<0.2	7.5	<0.01	0.13	4	<0.005
SI 481282	Soil	1032	53.9	7.6	<0.01	0.04	0.11	1.0	0.4	<0.2	20.7	<0.01	0.12	1	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481283	Soil	699	21.8	4.0	<0.01	0.03	0.37	0.2	0.3	<0.2	7.6	<0.01	0.14	<0.2	<0.005
SI 481284	Soil	1162	60.6	5.4	<0.01	0.05	1.11	0.6	0.6	<0.2	25.2	<0.01	0.21	1	<0.005
SI 481285	Soil	363	66.8	2.9	<0.01	0.02	0.78	1.1	0.4	<0.2	12.0	<0.01	0.12	4	<0.005
SI 481286	Soil	572	35.2	4.5	<0.01	0.02	0.40	0.8	0.3	<0.2	14.2	<0.01	0.15	2	<0.005
SI 481287	Soil	619	47.1	2.8	<0.01	<0.01	0.51	1.6	0.7	<0.2	37.4	<0.01	0.17	10	<0.005
SI 481288	Soil	552	29.1	7.5	<0.01	0.02	0.92	0.3	0.5	<0.2	5.6	<0.01	0.10	0	<0.005
SI 481289	Soil	586	35.4	6.3	<0.01	0.01	0.90	0.5	0.5	<0.2	7.3	<0.01	0.10	1	<0.005
SI 481290	Soil	809	26.2	7.3	<0.01	0.02	1.33	0.4	0.6	<0.2	5.9	<0.01	0.12	0	<0.005
SI 481291	Soil	694	20.4	7.0	<0.01	0.02	0.51	0.3	0.6	<0.2	6.0	<0.01	0.12	<0.2	<0.005
SI 481292	Soil	457	27.4	3.5	<0.01	0.02	1.59	0.6	0.3	<0.2	9.3	<0.01	0.11	1	<0.005
SI 481293	Soil	407	25.2	4.7	<0.01	0.01	2.10	0.9	0.4	<0.2	5.2	<0.01	0.12	2	<0.005
SI 481294	Soil	481	31.7	5.2	<0.01	0.02	2.92	0.8	0.2	<0.2	7.8	<0.01	0.18	2	<0.005
SI 481295	Soil	568	40.6	5.9	<0.01	0.02	4.81	0.8	0.5	<0.2	6.9	<0.01	0.20	1	0.005
SI 481296	Soil	788	32.2	7.4	<0.01	0.02	1.30	0.5	0.5	<0.2	8.9	<0.01	0.16	0	0.006
SI 481297	Soil	769	24.8	7.5	<0.01	0.03	0.42	0.3	0.3	<0.2	5.9	<0.01	0.12	<0.2	0.005
SI 481298	Soil	522	43.4	10.5	<0.01	0.03	0.32	0.5	0.6	0.4	7.5	<0.01	0.12	0	0.010
SI 481299	Soil	492	23.7	6.3	<0.01	0.02	0.48	0.2	0.4	<0.2	5.2	<0.01	0.09	<0.2	<0.005
SI 481300	Soil	660	28.4	8.6	<0.01	0.03	0.48	0.3	0.5	0.2	7.0	<0.01	0.07	<0.2	<0.005
SI 481301	Soil	645	19.2	5.9	<0.01	0.03	0.51	0.3	0.3	<0.2	5.5	<0.01	0.09	0	<0.005
SI 481302	Soil	505	73.2	4.2	<0.01	0.01	0.88	1.6	0.5	<0.2	5.1	<0.01	0.20	3	<0.005
SI 481303	Soil	639	22.8	4.0	<0.01	0.02	2.32	1.8	0.5	<0.2	3.3	<0.01	0.18	3	<0.005
SI 481304	Soil	670	25.0	4.8	<0.01	0.02	0.28	0.5	0.5	<0.2	4.1	<0.01	0.06	0	<0.005
TI 480142	Soil	807	49.7	2.9	<0.01	0.03	4.46	2.2	0.3	<0.2	21.3	<0.01	0.20	4	<0.005
TI 480143	Soil	881	34.6	5.4	<0.01	0.09	0.69	2.2	1.6	<0.2	49.4	<0.01	0.10	2	<0.005
TI 480144	Soil	691	38.1	4.5	<0.01	0.03	0.82	2.3	0.7	<0.2	16.6	<0.01	0.14	3	<0.005
TI 480145	Soil	629	43.4	5.3	<0.01	0.04	0.25	2.2	0.5	<0.2	18.7	<0.01	0.18	4	<0.005
TI 480146	Soil	626	43.5	3.8	<0.01	0.03	0.17	2.9	0.3	<0.2	17.4	<0.01	0.15	7	<0.005
TI 480147	Soil	504	36.4	2.7	<0.01	0.02	0.14	2.2	0.4	<0.2	12.4	0.01	0.16	5	<0.005
TI 480148	Soil	771	47.5	4.4	<0.01	0.08	0.74	1.5	1.8	<0.2	54.3	0.01	0.05	2	<0.005
TI 480149	Soil	1235	29.7	3.7	<0.01	0.12	0.81	1.1	6.3	<0.2	49.7	0.01	0.09	1	<0.005
TI 481165	Soil	846	58.0	4.8	<0.01	0.04	0.38	2.5	1.5	0.2	72.9	<0.01	0.12	6	<0.005
TI 481166	Soil	558	39.0	3.4	<0.01	0.02	<0.05	2.0	0.9	<0.2	38.6	<0.01	0.07	9	<0.005
TI 481167	Soil	688	45.8	3.3	<0.01	0.03	0.57	2.2	1.2	<0.2	43.6	<0.01	0.12	8	<0.005
TI 481168	Soil	776	29.9	5.4	<0.01	0.05	0.29	0.9	1.6	<0.2	51.2	<0.01	0.06	1	0.005
TI 481169	Soil	672	40.4	2.7	<0.01	0.03	0.13	1.9	1.0	<0.2	33.7	<0.01	0.12	7	<0.005
TI 481170	Soil	627	35.3	2.0	<0.01	0.02	<0.05	2.2	0.9	<0.2	30.7	<0.01	0.09	6	<0.005
TI 481171	Soil	652	26.2	1.5	<0.01	<0.01	<0.05	1.9	0.2	<0.2	22.4	<0.01	0.10	5	<0.005
TI 481172	Soil	696	34.2	3.3	<0.01	0.03	<0.05	2.0	0.9	<0.2	37.2	<0.01	0.07	4	<0.005
TI 481173	Soil	729	29.8	3.5	<0.01	0.04	<0.05	1.4	1.2	<0.2	46.8	<0.01	0.03	2	<0.005
TI 481174	Soil	631	27.5	2.5	<0.01	0.03	<0.05	1.9	1.1	<0.2	33.0	<0.01	0.08	4	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
TI 481175	Soil	673	25.7	3.1	<0.01	0.03	<0.05	1.8	1.0	<0.2	30.2	<0.01	0.08	4	<0.005
TI 481176	Soil	605	19.1	3.2	<0.01	0.03	<0.05	1.8	0.6	<0.2	37.0	<0.01	0.04	3	0.007
TI 481177	Soil	604	29.1	2.2	<0.01	0.02	<0.05	2.2	0.8	<0.2	31.1	<0.01	0.10	5	<0.005
TI 481178	Soil	469	19.8	3.1	<0.01	0.04	<0.05	1.4	0.9	<0.2	41.4	<0.01	0.02	3	<0.005
TI 481179	Soil	647	29.7	1.9	<0.01	0.02	0.21	2.4	0.7	<0.2	62.2	<0.01	0.09	6	<0.005
TI 481180	Soil	624	25.1	2.0	<0.01	0.02	<0.05	1.7	0.6	<0.2	25.5	<0.01	0.10	4	<0.005
TI 481181	Soil	570	24.5	2.7	<0.01	0.02	<0.05	1.7	0.4	<0.2	34.7	<0.01	0.07	4	<0.005
TI 481201	Soil	585	24.4	2.6	<0.01	0.02	<0.05	1.7	0.4	<0.2	32.2	<0.01	0.06	4	<0.005
TI 481202	Soil	699	21.8	3.8	<0.01	0.07	<0.05	1.7	1.1	<0.2	35.3	<0.01	0.05	2	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481203	Soil	<0.05	1	16	0.20	2.0	86	0.9
SI 481204	Soil	0.06	1	22	0.35	2.6	112	<0.5
SI 481205	Soil	0.05	1	20	0.27	2.3	106	1.1
SI 481206	Soil	<0.05	1	12	0.55	2.7	61	<0.5
SI 481207	Soil	<0.05	1	22	0.19	2.0	111	<0.5
SI 481208	Soil	<0.05	1	18	0.26	3.8	133	<0.5
SI 481209	Soil	<0.05	1	21	0.23	12.5	144	<0.5
SI 481210	Soil	<0.05	1	21	0.22	3.1	129	<0.5
SI 481211	Soil	<0.05	1	20	0.38	4.6	120	<0.5
SI 481212	Soil	0.06	1	30	0.24	3.2	91	0.7
SI 481213	Soil	<0.05	2	21	0.17	5.7	145	0.9
SI 481214	Soil	<0.05	1	17	0.17	4.3	129	<0.5
SI 481215	Soil	<0.05	1	24	0.18	3.1	134	<0.5
SI 481216	Soil	<0.05	3	20	0.32	3.2	126	<0.5
SI 481217	Soil	<0.05	1	22	0.39	3.9	133	<0.5
SI 481218	Soil	<0.05	1	23	0.23	2.4	109	0.8
SI 481219	Soil	<0.05	1	23	0.35	2.3	103	1.4
SI 481220	Soil	<0.05	1	23	0.32	2.6	138	<0.5
SI 481221	Soil	<0.05	1	19	0.20	3.2	123	<0.5
SI 481222	Soil	<0.05	10	16	0.36	8.3	125	<0.5
SI 481223	Soil	<0.05	1	24	0.39	3.9	138	<0.5
SI 481224	Soil	<0.05	1	24	0.28	2.1	116	<0.5
SI 481225	Soil	<0.05	1	18	0.31	2.0	129	<0.5
SI 481226	Soil	<0.05	1	18	0.27	2.1	103	<0.5
SI 481227	Soil	<0.05	2	20	0.22	4.6	148	<0.5
SI 481228	Soil	<0.05	2	20	0.21	3.4	156	0.7
SI 481229	Soil	<0.05	3	18	0.11	5.6	160	0.7
SI 481230	Soil	<0.05	1	16	0.64	2.3	92	<0.5
SI 481231	Soil	<0.05	4	17	0.21	5.1	106	<0.5
SI 481232	Soil	<0.05	3	18	0.57	6.5	143	<0.5
SI 481233	Soil	<0.05	3	19	0.33	12.1	170	0.9
SI 481234	Soil	<0.05	6	18	0.33	8.0	146	<0.5
SI 481235	Soil	<0.05	1	18	0.40	2.2	127	<0.5
SI 481236	Soil	<0.05	1	18	0.40	1.5	46	<0.5
SI 481237	Soil	<0.05	1	25	0.72	1.8	76	<0.5
SI 481238	Soil	<0.05	1	18	0.56	2.2	82	<0.5
SI 481239	Soil	<0.05	1	20	0.66	1.9	64	<0.5
SI 481240	Soil	<0.05	1	17	0.27	2.1	95	<0.5
SI 481241	Soil	<0.05	1	14	0.27	1.1	47	<0.5
SI 481242	Soil	<0.05	2	23	0.80	3.3	116	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481243	Soil	<0.05	1	18	0.87	2.3	101	<0.5
SI 481244	Soil	<0.05	2	20	0.29	2.0	108	<0.5
SI 481245	Soil	<0.05	2	18	0.61	5.8	126	<0.5
SI 481246	Soil	<0.05	1	22	0.50	2.4	109	<0.5
SI 481247	Soil	<0.05	1	25	0.69	2.9	121	<0.5
SI 481248	Soil	<0.05	1	21	1.30	3.2	127	<0.5
SI 481249	Soil	<0.05	1	23	0.19	2.2	107	<0.5
SI 481250	Soil	<0.05	1	28	0.38	2.3	122	0.8
SI 481251	Soil	<0.05	1	27	0.40	2.9	124	<0.5
SI 481252	Soil	<0.05	1	25	0.27	1.9	107	0.7
SI 481253	Soil	<0.05	1	28	0.34	2.4	74	1.0
SI 481254	Soil	<0.05	3	4	1.39	10.3	141	<0.5
SI 481255	Soil	<0.05	1	12	1.29	1.5	79	<0.5
SI 481256	Soil	<0.05	1	20	0.48	1.4	69	<0.5
SI 481257	Soil	<0.05	1	12	0.51	1.3	55	<0.5
SI 481258	Soil	<0.05	1	16	0.39	1.6	77	<0.5
SI 481259	Soil	<0.05	1	22	0.35	1.7	57	<0.5
SI 481260	Soil	<0.05	2	18	4.20	1.9	103	<0.5
SI 481261	Soil	<0.05	1	13	1.55	3.0	99	<0.5
SI 481262	Soil	<0.05	1	18	1.29	1.6	68	<0.5
SI 481263	Soil	<0.05	1	15	0.82	3.6	110	<0.5
SI 481264	Soil	<0.05	1	14	1.15	2.2	106	<0.5
SI 481265	Soil	<0.05	1	20	0.58	2.6	107	<0.5
SI 481266	Soil	<0.05	2	11	0.85	1.9	114	<0.5
SI 481267	Soil	<0.05	1	8	0.77	1.6	100	<0.5
SI 481268	Soil	<0.05	1	10	0.52	1.5	71	<0.5
SI 481269	Soil	<0.05	1	10	0.89	1.7	93	<0.5
SI 481270	Soil	<0.05	1	7	0.47	1.6	64	<0.5
SI 481271	Soil	<0.05	1	13	0.54	1.9	103	<0.5
SI 481272	Soil	<0.05	2	15	0.33	3.2	134	<0.5
SI 481273	Soil	<0.05	1	10	0.58	1.4	78	<0.5
SI 481274	Soil	<0.05	1	15	4.25	1.8	61	<0.5
SI 481275	Soil	<0.05	1	21	1.39	1.6	72	<0.5
SI 481276	Soil	<0.05	1	12	0.76	1.0	31	<0.5
SI 481277	Soil	<0.05	1	12	0.77	1.9	93	<0.5
SI 481278	Soil	<0.05	1	13	1.74	1.8	84	<0.5
SI 481279	Soil	<0.05	1	11	1.09	1.9	92	<0.5
SI 481280	Soil	<0.05	2	11	0.90	4.1	119	<0.5
SI 481281	Soil	<0.05	2	14	0.47	2.6	120	<0.5
SI 481282	Soil	<0.05	3	17	0.28	2.7	115	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481283	Soil	<0.05	1	12	0.33	1.1	55	<0.5
SI 481284	Soil	<0.05	2	18	6.04	2.5	160	<0.5
SI 481285	Soil	<0.05	2	10	0.62	3.0	107	<0.5
SI 481286	Soil	<0.05	2	11	0.54	3.9	92	<0.5
SI 481287	Soil	<0.05	4	11	0.49	4.7	117	0.5
SI 481288	Soil	<0.05	1	19	0.72	1.9	71	<0.5
SI 481289	Soil	<0.05	1	16	0.54	2.0	95	<0.5
SI 481290	Soil	<0.05	1	22	0.41	2.1	79	<0.5
SI 481291	Soil	<0.05	1	19	0.54	1.6	63	<0.5
SI 481292	Soil	<0.05	1	12	0.32	1.7	91	<0.5
SI 481293	Soil	<0.05	1	13	0.21	1.5	85	<0.5
SI 481294	Soil	<0.05	1	12	0.70	1.5	93	<0.5
SI 481295	Soil	<0.05	1	14	2.89	1.6	94	<0.5
SI 481296	Soil	<0.05	1	21	0.72	2.1	95	<0.5
SI 481297	Soil	<0.05	1	21	0.45	1.6	64	<0.5
SI 481298	Soil	<0.05	1	26	0.67	2.4	87	<0.5
SI 481299	Soil	<0.05	1	19	0.48	2.0	62	<0.5
SI 481300	Soil	<0.05	1	23	0.88	2.5	71	<0.5
SI 481301	Soil	<0.05	1	18	1.61	2.3	65	<0.5
SI 481302	Soil	<0.05	1	17	0.70	2.3	135	<0.5
SI 481303	Soil	<0.05	1	13	0.43	2.3	112	<0.5
SI 481304	Soil	<0.05	1	21	6.72	1.3	71	<0.5
TI 480142	Soil	<0.05	2	16	5.05	5.0	151	<0.5
TI 480143	Soil	<0.05	7	15	6.35	9.6	133	<0.5
TI 480144	Soil	<0.05	3	18	2.82	5.3	162	<0.5
TI 480145	Soil	<0.05	2	19	4.10	5.2	149	<0.5
TI 480146	Soil	<0.05	2	20	1.16	5.4	168	<0.5
TI 480147	Soil	<0.05	2	17	0.86	4.0	147	<0.5
TI 480148	Soil	<0.05	5	14	0.29	6.6	380	0.6
TI 480149	Soil	<0.05	18	13	0.21	5.5	90	1.1
TI 481165	Soil	<0.05	13	14	3.29	10.6	131	<0.5
TI 481166	Soil	<0.05	4	14	0.16	6.3	117	<0.5
TI 481167	Soil	<0.05	3	15	2.87	7.0	114	<0.5
TI 481168	Soil	<0.05	7	15	0.24	5.1	102	<0.5
TI 481169	Soil	<0.05	4	17	0.25	6.0	106	<0.5
TI 481170	Soil	<0.05	3	17	5.19	5.2	108	<0.5
TI 481171	Soil	<0.05	2	17	0.18	2.9	120	0.6
TI 481172	Soil	<0.05	3	15	0.51	5.6	105	<0.5
TI 481173	Soil	<0.05	15	16	0.17	4.2	113	<0.5
TI 481174	Soil	<0.05	4	16	0.35	4.8	103	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
TI 481175	Soil	<0.05	5	16	0.54	5.0	107	<0.5
TI 481176	Soil	<0.05	4	16	0.19	5.0	110	<0.5
TI 481177	Soil	<0.05	4	17	0.26	4.7	108	<0.5
TI 481178	Soil	<0.05	3	16	0.27	4.1	102	<0.5
TI 481179	Soil	<0.05	2	16	0.62	7.5	103	<0.5
TI 481180	Soil	<0.05	4	14	0.37	5.6	99	<0.5
TI 481181	Soil	<0.05	2	15	0.32	4.7	110	<0.5
TI 481201	Soil	<0.05	3	16	0.20	4.4	119	<0.5
TI 481202	Soil	<0.05	2	14	0.92	5.6	126	0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481203	Soil	<0.005													
SI 481203 Dup		<0.005													
SI 481221	Soil	0.013													
SI 481221 Dup		0.006													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.873													
QCV1007-01011-0004-BLK		<0.005													
SI 481239	Soil	0.031													
SI 481239 Dup		0.037													
SI 481257	Soil	0.020													
SI 481257 Dup		0.022													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.812													
QCV1007-01011-0008-BLK		<0.005													
SI 481275	Soil	0.030													
SI 481275 Dup		0.024													
SI 481293	Soil	0.009													
SI 481293 Dup		0.008													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.864													
QCV1007-01011-0012-BLK		<0.005													
TI 480148	Soil	0.071													
TI 480148 Dup		0.057													
TI 481181	Soil	<0.005													
TI 481181 Dup		<0.005													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.819													
QCV1007-01012-0001-BLK			<0.01	<0.01	0.3	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
SI 481203	Soil		0.22	1.66	16.1	28	0.4	0.41	0.04	0.18	19.45	16.9	21	3.3	42.8
SI 481203 Dup			0.21	1.65	15.9	28	0.4	0.40	0.04	0.17	19.48	16.7	21	3.2	40.7
STD-ME-6 expected			101.00												6130.0
STD-ME-6 result			97.61	1.23	262.2	88	0.2	6.32	0.62	37.61	9.87	14.2	28	0.4	6716.6
SI 481221	Soil		0.12	2.06	43.6	36	0.5	0.71	0.04	0.13	28.08	32.9	27	3.0	53.8
SI 481221 Dup			0.15	2.10	43.6	37	0.5	0.73	0.04	0.13	27.32	33.6	26	3.1	53.3
STD-ME-6 expected			101.00												6130.0
STD-ME-6 result			97.93	1.20	250.8	88	0.3	6.64	0.62	37.11	10.10	14.5	29	0.4	6500.0
SI 481239	Soil		0.14	1.37	102.1	32	0.2	0.43	0.02	0.08	25.74	9.1	19	3.2	25.3
SI 481239 Dup			0.11	1.36	105.5	32	0.2	0.43	0.02	0.09	27.08	9.3	19	3.3	26.2
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.38	3.16	20.4	212	0.7	0.20	0.24	0.11	38.69	112.1	852	1.2	637.1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481257	Soil		0.20	0.88	62.6	34	0.2	0.34	0.05	0.06	13.93	5.0	8	1.3	26.5
SI 481257 Dup			0.19	0.88	59.8	35	0.2	0.34	0.05	0.07	13.39	4.9	8	1.4	26.3
STD-ME-6 expected			101.00												6130.0
STD-ME-6 result			98.08	1.18	232.9	98	0.2	6.70	0.61	35.28	10.02	13.2	26	0.4	6500.2
SI 481275	Soil		0.14	1.16	128.0	32	0.2	0.50	0.02	0.15	35.48	6.9	12	1.6	20.0
SI 481275 Dup			0.22	1.21	128.4	32	0.2	0.49	0.02	0.14	34.53	6.9	13	1.5	19.8
STD-ME-6 expected			101												6130.0
STD-ME-6 result			>100	1.29	262.9	99	0.2	7.06	0.68	36.27	11.24	13.7	30	0.4	6656.6
SI 481293	Soil		0.23	1.44	35.6	24	0.3	0.42	<0.01	0.06	18.53	9.6	17	2.5	37.1
SI 481293 Dup			0.19	1.45	35.7	24	0.3	0.44	<0.01	0.06	18.36	9.9	17	2.7	38.0
STD-ME-6 expected			101.00												6130.0
STD-ME-6 result			99.92	1.37	262.7	105	0.2	6.52	0.71	35.87	11.20	13.6	32	0.4	6859.3
TI 480148	Soil		0.38	1.88	316.1	39	0.7	0.50	1.04	1.88	16.13	16.2	25	10.5	70.4
TI 480148 Dup			0.45	1.87	320.4	39	0.7	0.49	1.04	1.84	16.21	16.2	25	10.6	69.5
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.48	3.50	6.1	207	0.7	0.20	0.25	0.11	36.38	110.0	915	1.3	681.5
TI 481181	Soil		0.23	1.87	53.3	26	0.4	0.39	0.37	0.09	20.92	17.7	27	0.6	34.3
TI 481181 Dup			0.27	1.94	53.7	27	0.4	0.40	0.37	0.09	20.57	17.9	27	0.6	34.1
QCV1007-01012-0017-BLK			<0.01	<0.01	1.4	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
STD-DS-1 expected			0.47	4.48	6930.0	221						9.5			27.1
STD-DS-1 result			0.55	0.42	6785.7	37	0.5	0.10	6.14	1.37	23.71	10.2	18	2.2	30.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
QCV1007-01012-0001-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
SI 481203	Soil	3.69	5.1	<0.05	0.03	0.03	0.02	11.1	49.5	0.58	808	0.66	0.01	0.2	28.9
SI 481203 Dup		3.65	5.1	<0.05	0.03	0.03	0.02	10.7	48.9	0.57	799	0.64	0.01	0.2	28.4
STD-ME-6 expected															
STD-ME-6 result		5.73	4.6	<0.05	0.16	0.52	0.10	4.6	9.9	0.85	1748	29.22	0.06	0.2	30.8
SI 481221	Soil	5.02	7.2	<0.05	<0.02	0.04	0.02	12.6	64.4	0.85	1112	0.73	<0.01	0.1	46.9
SI 481221 Dup		5.10	7.2	<0.05	<0.02	0.04	0.02	12.5	64.1	0.85	1113	0.72	<0.01	0.1	46.7
STD-ME-6 expected															
STD-ME-6 result		5.75	4.6	<0.05	0.18	0.54	0.10	4.7	10.1	0.86	1771	31.32	0.06	0.2	30.3
SI 481239	Soil	3.35	5.7	<0.05	<0.02	0.02	0.03	13.1	26.3	0.36	309	0.64	0.01	0.3	20.0
SI 481239 Dup		3.36	5.8	<0.05	<0.02	0.02	0.03	13.1	26.4	0.35	304	0.66	0.01	0.3	19.9
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	17.8	0.1	0.51	0.10	0.07	17.5	6.0	0.12	1165	1.78	0.02	0.7	316.1
SI 481257	Soil	2.34	3.2	<0.05	<0.02	0.02	0.03	7.6	16.2	0.22	221	0.71	0.02	0.2	12.6
SI 481257 Dup		2.32	3.0	<0.05	<0.02	0.01	0.03	7.7	16.4	0.22	217	0.70	0.02	0.2	12.2
STD-ME-6 expected															
STD-ME-6 result		5.73	4.5	<0.05	0.20	0.49	0.10	4.5	9.6	0.85	1711	27.25	0.06	0.2	28.3
SI 481275	Soil	4.03	5.9	<0.05	<0.02	0.02	0.03	20.1	23.6	0.27	248	0.66	<0.01	0.6	16.3
SI 481275 Dup		3.92	6.0	<0.05	<0.02	0.02	0.04	19.4	24.2	0.27	252	0.66	<0.01	0.6	16.4
STD-ME-6 expected															
STD-ME-6 result		5.97	4.8	<0.05	0.22	0.51	0.10	5.2	10.4	0.90	1768	28.76	0.06	0.2	29.3
SI 481293	Soil	3.80	4.3	<0.05	<0.02	0.02	0.03	10.8	32.3	0.42	252	0.67	<0.01	0.2	26.9
SI 481293 Dup		3.81	4.5	<0.05	<0.02	0.02	0.03	11.1	33.4	0.43	248	0.68	<0.01	0.1	26.7
STD-ME-6 expected															
STD-ME-6 result		6.43	4.8	<0.05	0.21	0.48	0.11	5.1	10.2	0.95	1808	25.06	0.07	0.3	29.4
TI 480148	Soil	4.17	5.2	<0.05	<0.02	0.03	0.03	9.0	63.1	0.82	468	0.40	0.01	0.2	40.1
TI 480148 Dup		4.08	5.1	<0.05	<0.02	0.03	0.03	9.6	62.4	0.81	474	0.41	0.01	0.2	40.7
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	18.5	0.1	0.53	0.11	0.08	17.2	7.0	0.12	1075	1.74	0.02	0.6	307.4
TI 481181	Soil	4.16	5.2	<0.05	<0.02	0.02	0.02	11.4	76.5	0.76	714	0.38	<0.01	0.1	40.8
TI 481181 Dup		4.09	5.3	<0.05	<0.02	0.02	0.02	11.4	75.7	0.75	718	0.37	<0.01	0.1	40.9
QCV1007-01012-0017-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
STD-DS-1 expected										2.76	437				48.7
STD-DS-1 result		2.89	1.4	<0.05	0.09	0.06	0.13	12.0	2.3	2.55	458	4.67	<0.01	<0.05	50.0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
QCV1007-01012-0001-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
SI 481203	Soil	813	27.9	3.4	<0.01	0.03	0.15	0.6	0.3	<0.2	4.4	<0.01	0.10	1	<0.005
SI 481203 Dup		824	26.7	3.4	<0.01	0.03	0.13	0.5	0.2	<0.2	4.5	<0.01	0.10	1	0.005
STD-ME-6 expected			10200												
STD-ME-6 result		430	>10000	4.1	0.01	2.43	440.11	4.2	3.0	2.0	29.7	<0.01	1.82	1	0.090
SI 481221	Soil	650	39.6	3.3	<0.01	0.02	<0.05	1.2	0.4	<0.2	3.9	<0.01	0.18	1	<0.005
SI 481221 Dup		654	39.2	3.2	<0.01	0.01	<0.05	1.2	0.4	<0.2	3.7	<0.01	0.17	1	<0.005
STD-ME-6 expected			10200												
STD-ME-6 result		489	>10000	4.0	0.02	2.39	415.25	4.3	2.6	2.0	28.8	<0.01	1.81	1	0.088
SI 481239	Soil	729	17.4	5.3	<0.01	0.03	<0.05	0.3	0.6	0.2	4.8	<0.01	0.08	0	<0.005
SI 481239 Dup		725	17.7	5.3	<0.01	0.03	<0.05	0.3	0.6	0.2	4.8	<0.01	0.08	0	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		533	20.2	10.6	<0.01	0.02	<0.05	55.7	0.5	2.0	13.0	<0.01	0.11	7	0.162
SI 481257	Soil	482	24.0	4.1	<0.01	0.02	2.81	0.6	0.4	<0.2	10.7	<0.01	0.10	1	0.009
SI 481257 Dup		474	24.4	4.1	<0.01	0.02	2.83	0.6	0.4	<0.2	10.3	<0.01	0.11	1	0.008
STD-ME-6 expected			10200												
STD-ME-6 result		478	>10000	3.9	0.01	2.37	450.61	4.3	2.5	2.0	28.7	<0.01	1.95	1	0.085
SI 481275	Soil	541	18.3	7.5	<0.01	0.02	0.05	0.9	0.3	0.4	4.4	<0.01	0.11	5	0.007
SI 481275 Dup		547	18.3	7.3	<0.01	0.02	0.07	0.9	0.3	0.4	4.5	<0.01	0.10	5	0.007
STD-ME-6 expected			10200												
STD-ME-6 result		464	>10000	4.2	0.01	2.45	427.53	4.7	2.7	2.0	31.5	<0.01	1.88	1	0.104
SI 481293	Soil	407	25.2	4.7	<0.01	0.01	2.10	0.9	0.4	<0.2	5.2	<0.01	0.12	2	<0.005
SI 481293 Dup		399	24.8	4.7	<0.01	0.02	2.16	0.9	0.4	<0.2	5.1	<0.01	0.12	2	<0.005
STD-ME-6 expected			10200												
STD-ME-6 result		455	>10000	4.2	0.01	2.53	469.74	4.6	2.8	1.9	33.6	<0.01	1.78	1	0.111
TI 480148	Soil	771	47.5	4.4	<0.01	0.08	0.74	1.5	1.8	<0.2	54.3	0.01	0.05	2	<0.005
TI 480148 Dup		788	47.0	4.5	<0.01	0.08	0.72	1.4	2.0	<0.2	55.5	0.01	0.06	2	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		385	22.0	10.6	<0.01	0.02	<0.05	51.7	0.7	1.9	15.9	<0.01	0.09	7	0.185
TI 481181	Soil	570	24.5	2.7	<0.01	0.02	<0.05	1.7	0.4	<0.2	34.7	<0.01	0.07	4	<0.005
TI 481181 Dup		567	24.1	2.6	<0.01	0.02	<0.05	1.7	0.5	<0.2	35.7	<0.01	0.07	3	<0.005
QCV1007-01012-0017-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
STD-DS-1 expected		340	13.8												
STD-DS-1 result		347	13.4	6.6	<0.01	2.48	103.94	7.0	0.8	1.3	68.1	<0.01	0.11	3	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02393-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
QCV1007-01012-0001-BLK		<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
SI 481203	Soil	<0.05	1	16	0.20	2.0	86	0.9
SI 481203 Dup		<0.05	1	16	0.18	2.1	84	1.0
STD-ME-6 expected							5170	
STD-ME-6 result		0.21	1	45	1.13	7.2	5840	4.9
SI 481221	Soil	<0.05	1	19	0.20	3.2	123	<0.5
SI 481221 Dup		<0.05	1	19	0.20	3.3	119	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.23	1	46	1.10	7.2	5916	5.0
SI 481239	Soil	<0.05	1	20	0.66	1.9	64	<0.5
SI 481239 Dup		<0.05	1	20	0.74	2.0	62	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.06	1	211	0.17	10.5	150	21.0
SI 481257	Soil	<0.05	1	12	0.51	1.3	55	<0.5
SI 481257 Dup		<0.05	1	12	0.50	1.3	54	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.22	1	46	1.22	7.0	5897	5.0
SI 481275	Soil	<0.05	1	21	1.39	1.6	72	<0.5
SI 481275 Dup		<0.05	1	20	1.39	1.6	74	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.23	1	49	0.84	8.0	6098	5.8
SI 481293	Soil	<0.05	1	13	0.21	1.5	85	<0.5
SI 481293 Dup		<0.05	1	13	0.21	1.6	83	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.24	1	50	0.94	8.0	6567	6.2
TI 480148	Soil	<0.05	5	14	0.29	6.6	380	0.6
TI 480148 Dup		<0.05	5	14	0.32	6.5	387	0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.09	1	223	3.17	9.7	152	20.7
TI 481181	Soil	<0.05	2	15	0.32	4.7	110	<0.5
TI 481181 Dup		<0.05	2	15	0.32	4.9	111	<0.5
QCV1007-01012-0017-BLK		<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
STD-DS-1 expected		20.00					206	
STD-DS-1 result		20.34	1	52	6.90	10.2	237	3.4

Certificate of Analysis

10-360-02437-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 08/05/2010
Date Completed: 08/20/2010
Invoice:

Samples	Type	Preparation Description
42	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-1AT-GV	Au, 1AT, Gravimetric
Au-2AT-AA	Au, 2AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480125	Rock		3.307	13.73	1.87	>10000	106	0.3	10.36	0.06	1.20	12.59	1.6	150	1.1
RI 480126	Rock		0.047	0.10	2.76	670.9	142	0.5	0.16	0.03	0.17	27.62	1.7	196	1.6
RI 480127	Rock		0.075	0.30	2.66	428.1	150	0.5	0.15	0.03	0.06	27.95	1.0	256	1.3
RI 480128	Rock		0.091	0.20	2.44	596.2	111	0.4	0.13	0.02	0.20	22.75	3.1	193	1.6
RI 480129	Rock		0.012	<0.01	0.58	64.4	32	0.1	0.07	0.03	0.02	7.35	1.5	229	0.4
RI 480130	Rock		0.008	0.20	0.60	27.5	36	0.1	0.05	0.01	0.03	4.95	1.3	215	0.4
RI 480131	Rock	38.102	>10	8.09	1.14	2728.7	64	0.4	0.13	0.01	0.14	14.09	0.9	215	1.2
RI 480132	Rock		0.060	<0.01	0.56	406.9	21	0.1	0.06	0.01	0.17	5.38	1.0	209	0.4
RI 480133	Rock		0.031	<0.01	1.67	46.6	62	0.5	0.15	<0.01	0.49	14.70	4.6	194	1.5
RI 480134	Rock		0.026	0.10	0.29	47.7	14	0.1	0.59	0.02	0.02	3.93	1.4	171	0.4
RI 480135	Rock		0.471	0.30	0.70	1208.6	42	0.2	0.21	0.03	0.11	7.97	1.6	210	0.5
RI 480136	Rock		0.060	1.79	0.29	65.8	21	0.1	3.82	0.01	0.03	5.86	1.1	194	0.3
RI 480137	Rock		2.244	0.49	0.48	1133.5	38	0.3	0.23	<0.01	0.04	3.70	0.9	178	1.3
RI 480138	Rock		0.022	<0.01	2.22	658.6	86	0.4	0.20	0.11	0.12	19.31	4.6	211	0.8
RI 480139	Rock		0.010	0.10	0.50	20.0	21	0.2	0.05	<0.01	0.03	3.17	1.6	281	0.3
RI 480151	Rock		0.010	<0.01	0.50	16.3	22	0.3	0.16	0.02	0.08	2.49	2.9	228	0.3
RI 480152	Rock		0.313	0.50	2.73	5785.4	181	0.6	0.19	0.02	8.33	24.90	2.5	197	3.1
RI 480153	Rock		0.014	0.50	0.27	104.6	9	0.1	0.06	0.02	0.12	2.65	1.0	110	0.4
RI 480154	Rock		<0.005	<0.01	2.70	27.7	150	0.6	0.14	0.01	0.07	28.40	1.1	213	0.9
RI 480155	Rock		0.057	0.20	0.20	>10000	42	0.1	0.26	<0.01	0.10	3.32	2.0	283	0.2
RI 480156	Rock		<0.005	0.10	0.93	1373.5	64	0.4	0.14	<0.01	0.56	8.94	1.2	250	0.5
RI 480157	Rock		0.028	0.10	0.25	315.0	54	0.1	0.14	0.01	0.36	32.40	1.6	182	0.4
RI 480158	Rock		0.044	1.59	0.78	465.2	64	0.2	0.13	<0.01	0.13	16.35	1.0	217	0.8
RI 480159	Rock		0.024	<0.01	0.12	275.6	13	0.1	0.08	<0.01	0.12	2.89	1.0	154	0.2
RI 480160	Rock		0.007	0.40	1.68	149.3	76	0.4	0.09	<0.01	0.08	17.18	1.0	227	0.8
RI 480161	Rock		0.010	1.00	1.27	185.6	64	0.3	0.41	<0.01	0.09	11.41	0.9	223	0.7
RI 480162	Rock		0.011	<0.01	1.21	224.3	58	0.3	0.21	<0.01	0.04	10.75	1.1	245	0.6
RI 480163	Rock		0.010	0.49	0.91	95.4	41	0.2	0.10	<0.01	0.05	9.23	1.1	230	0.5
RI 480164	Rock		0.011	<0.01	0.89	166.9	42	0.2	0.21	0.02	0.08	8.68	1.0	228	0.5
RI 480165	Rock		0.006	0.10	1.66	175.3	69	0.4	0.08	0.02	0.07	17.70	0.9	208	0.8
RI 480166	Rock		0.008	<0.01	1.69	138.2	74	0.5	0.24	<0.01	0.04	16.15	0.9	230	0.8
RI 480167	Rock		0.148	0.30	0.52	>10000	44	0.1	9.72	0.01	0.18	4.26	1.6	205	0.3
RI 480168	Rock	44.246	>10	4.89	0.46	4475.7	41	0.2	0.60	<0.01	0.02	4.97	1.0	235	0.5
RI 480169	Rock		0.030	0.10	0.47	2227.7	27	0.2	0.24	0.05	0.19	4.78	1.1	205	0.3
RI 480170	Rock		0.065	0.20	0.93	61.4	40	0.2	0.08	0.01	0.10	12.78	1.6	253	0.5
RI 480171	Rock		1.261	0.49	0.59	9467.5	44	0.2	0.16	0.07	0.10	5.45	3.4	217	0.3
RI 481013	Rock		0.051	0.10	1.29	1159.3	74	0.3	0.07	0.01	0.13	14.59	0.8	200	1.2
RI 481014	Rock		0.443	<0.01	0.31	7266.8	12	<0.05	0.05	<0.01	0.03	0.15	2.3	321	0.2
RI 481504	Rock		0.019	<0.01	0.02	385.4	<5	<0.05	0.04	<0.01	0.04	1.12	0.9	282	0.1
RI 481505	Rock		0.120	<0.01	1.53	201.7	82	0.3	0.09	<0.01	0.14	16.92	2.0	211	1.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Au	Au	Ag	Al	As	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr	Cs
		Au-1AT-GV	Au-2AT-AA	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT
Sample	Sample	g/ton	g/ton	ppm	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm
Description	Type	0.100	0.005	0.01	0.01	0.1	5	0.05	0.01	0.01	0.01	0.02	0.1	1	0.05
RI 481506	Rock		0.016	0.40	2.44	515.3	81	0.5	0.07	<0.01	0.29	19.09	2.7	201	0.9
RI 481507	Rock		0.081	0.50	2.27	645.8	100	0.5	0.05	<0.01	0.49	24.39	1.3	228	1.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
RI 480125	Rock	7.9	8.26	4.0	0.5	0.92	0.12	0.56	6.3	7.3	0.04	86	0.68	0.29	0.5
RI 480126	Rock	9.6	1.42	4.5	1.0	0.98	0.01	0.46	12.8	23.4	0.03	86	0.78	0.03	1.0
RI 480127	Rock	5.0	0.56	5.2	1.0	1.17	<0.01	0.68	13.2	14.0	0.04	59	1.09	0.03	0.9
RI 480128	Rock	4.3	0.99	4.4	1.1	0.84	<0.01	0.53	10.9	13.6	0.04	115	0.78	0.03	0.8
RI 480129	Rock	5.6	0.58	1.3	0.9	0.26	<0.01	0.17	3.5	16.1	0.01	159	0.81	0.02	0.3
RI 480130	Rock	3.7	0.43	1.3	0.8	<0.1	<0.01	0.18	2.4	6.3	0.01	135	0.76	0.01	0.3
RI 480131	Rock	8.7	0.57	4.8	1.8	2.26	<0.01	0.38	6.5	11.1	0.04	32	0.84	0.01	0.5
RI 480132	Rock	3.5	0.49	0.9	1.3	0.31	0.02	0.20	2.4	1.6	0.02	49	0.77	<0.01	0.3
RI 480133	Rock	5.9	2.24	2.9	0.3	1.63	<0.01	0.18	6.7	18.9	0.02	376	0.76	0.01	0.6
RI 480134	Rock	4.5	0.45	0.6	0.7	<0.1	<0.01	0.07	1.8	16.2	<0.01	69	0.79	<0.01	0.2
RI 480135	Rock	4.8	0.67	2.0	0.7	0.14	<0.01	0.16	3.7	3.8	0.02	83	0.78	0.24	0.3
RI 480136	Rock	27.4	0.65	0.9	1.0	<0.1	0.02	0.10	2.9	2.6	0.01	32	0.93	0.04	0.4
RI 480137	Rock	7.7	0.74	2.2	1.5	<0.1	<0.01	0.18	1.8	13.8	0.02	27	0.86	<0.01	0.3
RI 480138	Rock	6.4	1.82	3.2	0.9	0.81	0.01	0.20	9.0	43.8	0.04	743	0.88	1.01	0.7
RI 480139	Rock	5.4	0.52	1.1	0.9	<0.1	<0.01	0.09	1.6	7.6	0.04	49	0.96	0.07	0.2
RI 480151	Rock	28.2	1.74	1.1	0.7	<0.1	<0.01	0.05	1.4	21.0	0.03	113	0.90	<0.01	0.2
RI 480152	Rock	11.0	1.99	5.4	0.5	1.06	0.05	0.99	11.2	6.6	0.07	80	0.80	0.04	0.9
RI 480153	Rock	4.0	0.37	0.5	1.0	<0.1	<0.01	0.03	1.2	4.9	<0.01	46	0.80	<0.01	0.2
RI 480154	Rock	7.3	0.53	4.9	0.5	0.77	0.01	0.55	13.2	9.1	0.04	37	0.80	0.02	0.9
RI 480155	Rock	5.4	1.67	0.9	0.1	<0.1	0.03	0.09	1.7	1.5	<0.01	28	1.20	<0.01	0.2
RI 480156	Rock	6.7	0.60	2.2	0.6	0.13	0.01	0.23	4.1	4.3	0.02	36	1.02	<0.01	0.4
RI 480157	Rock	18.9	0.56	0.7	0.2	<0.1	0.05	0.05	14.2	8.8	<0.01	50	0.77	<0.01	0.2
RI 480158	Rock	5.7	0.35	2.2	0.9	0.25	<0.01	0.27	7.7	5.0	0.02	26	0.75	0.01	0.7
RI 480159	Rock	6.2	0.37	0.5	0.6	<0.1	<0.01	0.04	1.4	1.4	<0.01	29	0.85	<0.01	0.4
RI 480160	Rock	15.8	0.79	3.8	0.7	0.55	0.01	0.45	8.1	7.5	0.03	32	0.81	0.02	0.9
RI 480161	Rock	6.8	0.49	2.8	0.5	0.29	0.01	0.42	5.4	3.6	0.03	29	0.79	0.02	0.6
RI 480162	Rock	7.0	0.56	2.6	1.1	0.24	0.01	0.40	4.9	3.8	0.03	33	0.83	0.02	0.6
RI 480163	Rock	6.3	0.49	1.9	0.8	0.21	<0.01	0.25	4.3	9.4	0.02	29	0.77	0.02	0.5
RI 480164	Rock	5.9	0.42	2.0	1.2	0.16	0.02	0.29	3.9	3.0	0.02	29	0.78	0.01	0.5
RI 480165	Rock	8.2	0.72	3.2	1.0	0.61	0.02	0.43	8.2	6.8	0.03	27	0.68	0.02	0.7
RI 480166	Rock	6.5	0.65	3.6	1.3	0.49	0.01	0.48	7.5	4.6	0.03	30	0.79	0.02	0.7
RI 480167	Rock	4.7	1.38	1.3	1.1	<0.1	0.02	0.21	2.0	1.2	0.02	28	0.74	<0.01	0.4
RI 480168	Rock	3.0	0.62	1.9	2.2	<0.1	<0.01	0.21	2.3	5.0	0.02	25	0.78	0.01	0.3
RI 480169	Rock	8.0	0.52	1.3	1.2	<0.1	<0.01	0.13	2.4	15.9	0.01	31	0.79	<0.01	0.3
RI 480170	Rock	5.6	0.65	2.0	1.1	0.20	<0.01	0.21	6.0	3.6	0.01	56	0.80	0.01	0.5
RI 480171	Rock	4.2	1.38	1.2	1.2	<0.1	0.02	0.11	2.6	2.0	0.01	35	0.87	<0.01	0.3
RI 481013	Rock	3.5	0.50	3.1	1.6	0.37	0.01	0.53	6.6	1.6	0.04	31	0.78	0.02	0.5
RI 481014	Rock	61.4	1.52	1.1	1.2	<0.1	<0.01	0.03	<0.5	15.7	0.10	42	0.99	<0.01	0.1
RI 481504	Rock	3.0	0.33	0.2	1.1	<0.1	<0.01	<0.01	0.5	0.5	<0.01	29	0.95	<0.01	0.1
RI 481505	Rock	6.1	0.97	2.9	1.3	1.49	0.01	0.61	7.8	3.5	0.06	44	0.75	0.03	0.6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
RI 481506	Rock	9.3	1.21	4.2	0.9	1.68	0.02	0.41	8.8	7.9	0.03	55	0.73	0.02	0.6
RI 481507	Rock	7.4	0.67	4.0	1.0	1.31	0.17	0.86	11.7	4.8	0.07	47	0.72	0.03	0.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
RI 480125	Rock	4.0	63	4178.6	28.7	0.006	0.76	129.12	1.7	2.2	1.0	68.7	0.12	0.37	5
RI 480126	Rock	6.9	139	24.6	22.6	<0.005	0.04	7.03	2.4	<0.5	1.1	74.9	0.25	<0.05	8
RI 480127	Rock	5.0	73	27.7	37.5	0.007	<0.01	4.12	2.2	<0.5	1.3	29.9	0.46	<0.05	6
RI 480128	Rock	9.0	103	31.0	29.5	<0.005	<0.01	4.91	1.8	<0.5	1.1	15.7	0.21	<0.05	6
RI 480129	Rock	6.0	74	5.8	9.3	<0.005	<0.01	0.65	0.7	1.3	0.9	5.0	0.08	<0.05	2
RI 480130	Rock	5.2	54	6.1	10.3	0.005	<0.01	0.49	0.7	<0.5	0.8	4.5	0.07	0.06	1
RI 480131	Rock	4.2	40	19.7	23.4	0.022	0.04	3.63	0.9	<0.5	1.3	13.1	0.11	<0.05	3
RI 480132	Rock	4.1	55	70.8	9.4	0.015	0.02	1.23	0.4	<0.5	3.0	3.4	0.07	<0.05	1
RI 480133	Rock	11.7	66	18.0	10.0	0.006	<0.01	0.31	1.9	<0.5	0.9	13.8	0.14	<0.05	5
RI 480134	Rock	5.0	77	111.5	3.7	<0.005	<0.01	0.63	0.4	1.1	0.8	4.4	<0.05	<0.05	1
RI 480135	Rock	6.2	110	15.7	9.5	0.005	0.03	2.36	1.2	1.3	1.1	18.1	0.12	<0.05	2
RI 480136	Rock	5.8	147	1174.6	5.7	<0.005	0.07	2.18	0.8	3.2	1.2	17.2	0.09	<0.05	1
RI 480137	Rock	5.0	26	37.0	11.1	0.007	0.05	4.15	1.7	1.3	1.0	21.6	0.09	<0.05	2
RI 480138	Rock	12.9	92	39.6	11.5	0.010	0.02	1.02	2.4	1.4	1.1	76.8	0.21	<0.05	6
RI 480139	Rock	8.1	35	6.8	5.5	<0.005	<0.01	0.40	0.7	<0.5	1.0	5.4	0.07	<0.05	1
RI 480151	Rock	14.1	97	27.0	2.8	<0.005	<0.01	0.18	0.8	<0.5	0.9	7.5	0.09	<0.05	1
RI 480152	Rock	10.1	92	356.4	53.3	0.008	0.10	5.63	2.4	<0.5	11.3	12.1	0.24	0.09	8
RI 480153	Rock	4.8	22	13.7	1.8	<0.005	<0.01	0.56	0.5	1.3	0.9	3.4	0.06	<0.05	0
RI 480154	Rock	4.8	297	35.2	27.2	0.006	<0.01	0.75	2.4	<0.5	1.3	225.4	0.26	<0.05	5
RI 480155	Rock	7.0	226	40.5	4.4	<0.005	0.53	5.56	0.8	3.6	0.9	134.8	0.06	1.21	1
RI 480156	Rock	6.9	59	48.4	12.8	<0.005	0.03	0.86	1.2	2.5	1.0	17.2	0.10	<0.05	2
RI 480157	Rock	5.7	341	15.5	2.6	0.008	<0.01	0.72	1.4	1.7	0.8	188.3	0.06	<0.05	2
RI 480158	Rock	4.7	48	4.6	13.3	0.006	0.01	0.95	3.1	<0.5	1.0	30.3	0.11	0.17	2
RI 480159	Rock	4.4	63	3.4	2.1	0.020	<0.01	0.68	0.2	2.5	1.0	9.8	0.28	<0.05	<0.2
RI 480160	Rock	4.8	104	16.6	24.2	0.005	<0.01	0.77	1.6	1.4	1.4	15.0	0.39	<0.05	4
RI 480161	Rock	4.5	46	10.9	21.6	0.019	<0.01	1.12	1.1	<0.5	2.5	10.2	0.30	<0.05	3
RI 480162	Rock	4.7	46	13.0	20.7	<0.005	<0.01	1.27	1.1	1.4	3.1	11.2	0.29	<0.05	3
RI 480163	Rock	4.4	45	14.8	13.2	0.012	<0.01	0.61	1.0	1.2	1.4	13.6	0.22	0.06	2
RI 480164	Rock	4.1	46	11.5	15.2	<0.005	<0.01	0.98	1.0	<0.5	2.8	7.3	0.21	<0.05	2
RI 480165	Rock	3.7	74	26.9	22.8	0.008	<0.01	0.71	1.5	<0.5	1.3	7.1	0.27	<0.05	4
RI 480166	Rock	4.1	62	25.7	24.8	<0.005	<0.01	0.81	1.6	1.2	1.5	7.5	0.27	<0.05	3
RI 480167	Rock	4.3	71	31.5	11.1	0.009	0.50	8.57	0.9	1.1	3.4	6.2	0.14	0.22	2
RI 480168	Rock	4.0	22	16.4	10.9	0.007	0.12	4.51	0.8	1.9	1.2	3.9	0.13	<0.05	0
RI 480169	Rock	4.3	68	118.9	7.0	0.007	0.07	1.21	0.6	<0.5	1.3	6.5	0.13	<0.05	1
RI 480170	Rock	5.8	42	11.9	11.7	0.009	<0.01	0.38	1.2	<0.5	1.2	12.8	0.17	<0.05	3
RI 480171	Rock	7.7	496	14.7	6.5	0.007	0.37	4.59	0.7	2.8	1.0	11.4	0.12	0.24	1
RI 481013	Rock	4.0	65	63.2	28.9	<0.005	0.02	2.57	0.8	<0.5	5.1	6.5	0.10	<0.05	3
RI 481014	Rock	7.4	<10	9.4	2.1	0.009	0.26	15.06	0.2	<0.5	0.9	12.0	<0.05	<0.05	<0.2
RI 481504	Rock	4.7	<10	4.8	0.3	<0.005	0.02	0.74	0.2	<0.5	0.8	0.7	<0.05	<0.05	<0.2
RI 481505	Rock	5.7	105	9.0	34.4	0.014	<0.01	0.90	1.4	1.7	3.0	16.6	0.11	0.05	4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
RI 481506	Rock	10.6	67	25.5	22.1	<0.005	0.01	0.79	2.0	<0.5	1.1	10.0	0.14	<0.05	7
RI 481507	Rock	5.0	64	284.3	41.7	<0.005	0.03	2.01	1.7	<0.5	15.1	12.8	0.14	<0.05	6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480125	Rock	0.014	0.18	1	3	0.91	2.5	230	34.5
RI 480126	Rock	0.025	0.25	2	10	1.05	3.1	42	35.5
RI 480127	Rock	0.024	0.19	1	9	1.03	3.1	6	40.9
RI 480128	Rock	0.020	0.14	1	7	1.85	3.2	36	34.4
RI 480129	Rock	0.007	<0.02	0	<1	0.83	1.2	5	12.9
RI 480130	Rock	0.005	<0.02	0	<1	0.65	0.7	4	7.3
RI 480131	Rock	0.014	0.09	1	2	2.30	1.5	6	18.5
RI 480132	Rock	<0.005	<0.02	0	<1	1.14	0.6	22	5.7
RI 480133	Rock	0.015	0.04	1	7	1.57	2.2	43	20.4
RI 480134	Rock	<0.005	<0.02	0	<1	1.04	0.6	6	2.6
RI 480135	Rock	0.007	<0.02	0	2	1.24	1.3	10	9.8
RI 480136	Rock	0.006	<0.02	0	<1	0.98	0.5	7	4.8
RI 480137	Rock	0.005	0.04	0	5	1.78	0.4	6	5.5
RI 480138	Rock	0.014	0.04	1	7	1.79	5.0	22	29.2
RI 480139	Rock	<0.005	<0.02	0	<1	0.77	0.5	10	4.3
RI 480151	Rock	<0.005	<0.02	1	<1	0.79	0.8	39	7.9
RI 480152	Rock	0.025	0.20	2	9	2.38	4.4	246	37.7
RI 480153	Rock	<0.005	<0.02	0	<1	0.77	0.3	15	1.9
RI 480154	Rock	0.024	0.11	1	5	1.79	3.0	13	29.3
RI 480155	Rock	<0.005	0.02	0	<1	1.06	0.6	6	2.0
RI 480156	Rock	0.009	0.05	1	2	0.87	1.8	17	9.9
RI 480157	Rock	<0.005	<0.02	0	<1	0.89	33.5	20	1.9
RI 480158	Rock	0.019	0.05	1	3	2.53	5.9	5	15.2
RI 480159	Rock	<0.005	0.03	0	<1	0.79	1.0	3	1.2
RI 480160	Rock	0.015	0.09	1	2	1.54	1.8	14	19.9
RI 480161	Rock	0.011	0.06	0	4	1.46	1.3	8	13.0
RI 480162	Rock	0.011	0.08	0	<1	1.56	1.0	12	12.9
RI 480163	Rock	0.009	0.05	0	<1	1.07	1.0	11	11.1
RI 480164	Rock	0.009	0.04	0	2	1.17	0.9	9	10.3
RI 480165	Rock	0.017	0.07	1	6	1.55	1.7	21	21.7
RI 480166	Rock	0.017	0.09	1	<1	1.48	1.6	12	20.5
RI 480167	Rock	0.007	0.05	0	<1	1.53	0.8	6	7.5
RI 480168	Rock	0.006	0.02	0	<1	0.79	0.3	2	2.4
RI 480169	Rock	0.006	<0.02	0	<1	1.64	0.7	4	5.2
RI 480170	Rock	0.011	0.03	0	3	0.97	1.2	25	12.9
RI 480171	Rock	<0.005	<0.02	0	<1	1.28	2.0	7	8.5
RI 481013	Rock	0.012	0.10	1	3	1.98	1.4	15	17.9
RI 481014	Rock	<0.005	<0.02	0	<1	1.47	0.1	12	<0.5
RI 481504	Rock	<0.005	<0.02	<0.1	<1	0.97	0.3	5	<0.5
RI 481505	Rock	0.016	0.12	1	7	1.71	1.7	48	22.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 481506	Rock	0.018	0.07	1	7	1.89	2.2	69	25.6
RI 481507	Rock	0.023	0.14	1	12	2.19	2.4	36	30.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480125	Rock		3.307												
RI 480125 Dup			3.252												
RI 480154	Rock		<0.005												
RI 480154 Dup			0.006												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.767												
QCV1008-00090-0004-BLK			<0.005												
RI 481013	Rock		0.051												
RI 481013 Dup			0.049												
QCV1008-00090-0006-BLK			<0.005												
QCV1008-00091-0001-BLK				<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
RI 480125	Rock			13.73	1.87	>10000	106	0.3	10.36	0.06	1.20	12.59	1.6	150	1.1
RI 480125 Dup				13.56	1.88	>10000	104	0.3	9.95	0.06	1.22	12.29	1.7	152	1.1
STD-ME-8 expected				61.70											
STD-ME-8 result				60.21	5.29	2816.4	567	1.0	5.17	7.55	105.97	28.96	16.7	49	3.5
RI 480154	Rock			<0.01	2.70	27.7	150	0.6	0.14	0.01	0.07	28.40	1.1	213	0.9
RI 480154 Dup				0.20	2.65	26.5	152	0.6	0.15	0.01	0.07	28.33	1.1	214	0.9
STD-ME-8 expected				61.70											
STD-ME-8 result				59.90	5.39	2895.2	558	1.0	4.74	7.68	104.43	27.38	15.4	49	3.3
RI 481013	Rock			0.10	1.29	1159.3	74	0.3	0.07	0.01	0.13	14.59	0.8	200	1.2
RI 481013 Dup				0.30	1.29	1150.3	74	0.3	0.07	0.01	0.13	14.29	0.9	206	1.2
QCV1008-00091-0007-BLK				<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
STD-SY-4 expected							340	2.6				122.00	2.8	12	1.5
STD-SY-4 result				0.10	>10	<0.1	374	3.3	0.05	6.23	0.12	124.05	3.1	9	1.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
QCV1008-00091-0001-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
RI 480125	Rock	7.9	8.26	4.0	0.5	0.92	0.12	0.56	6.3	7.3	0.04	86	0.68	0.29	0.5
RI 480125 Dup		8.0	8.27	3.7	0.6	0.90	0.12	0.56	6.3	7.0	0.04	85	0.65	0.29	0.5
STD-ME-8 expected		1030.0													
STD-ME-8 result		1017.5	4.11	10.6	0.6	1.17	0.09	1.51	14.7	17.9	0.80	3253	5.95	1.30	4.2
RI 480154	Rock	7.3	0.53	4.9	0.5	0.77	0.01	0.55	13.2	9.1	0.04	37	0.80	0.02	0.9
RI 480154 Dup		7.3	0.54	5.0	0.6	0.78	0.01	0.56	13.2	9.4	0.04	37	0.81	0.02	0.9
STD-ME-8 expected		1030.0													
STD-ME-8 result		1019.3	4.20	10.1	0.4	1.18	0.08	1.54	13.7	16.3	0.82	2866	5.64	1.17	4.0
RI 481013	Rock	3.5	0.50	3.1	1.6	0.37	0.01	0.53	6.6	1.6	0.04	31	0.78	0.02	0.5
RI 481013 Dup		3.6	0.50	3.1	1.7	0.33	0.02	0.53	6.6	1.6	0.04	31	0.78	0.02	0.5
QCV1008-00091-0007-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
STD-SY-4 expected		7.0		35.0		10.60			58.0	37.0					13.0
STD-SY-4 result		7.2	4.53	34.0	0.4	3.13	0.04	1.47	59.0	39.6	0.32	783	0.27	5.18	14.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
QCV1008-00091-0001-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
RI 480125	Rock	4.0	63	4178.6	28.7	0.006	0.76	129.12	1.7	2.2	1.0	68.7	0.12	0.37	5
RI 480125 Dup		3.8	64	4135.5	28.8	<0.005	0.76	126.21	1.7	2.4	1.0	66.9	0.12	0.40	5
STD-ME-8 expected				19400											
STD-ME-8 result		33.4	637	>10000	72.0	0.005	2.15	69.31	9.0	4.2	3.8	419.0	0.84	0.64	4
RI 480154	Rock	4.8	297	35.2	27.2	0.006	<0.01	0.75	2.4	<0.5	1.3	225.4	0.26	<0.05	5
RI 480154 Dup		4.8	300	35.5	27.2	<0.005	<0.01	0.77	2.4	<0.5	1.3	220.8	0.24	<0.05	5
STD-ME-8 expected				19400											
STD-ME-8 result		30.4	634	>10000	66.5	0.007	2.12	64.28	8.3	4.0	3.7	389.4	0.99	0.49	4
RI 481013	Rock	4.0	65	63.2	28.9	<0.005	0.02	2.57	0.8	<0.5	5.1	6.5	0.10	<0.05	3
RI 481013 Dup		4.1	65	64.8	29.1	0.008	0.02	2.68	0.8	<0.5	5.2	6.4	0.09	<0.05	3
QCV1008-00091-0007-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
STD-SY-4 expected		9.0		10.0	55.0				1.1			1191.0	0.90		1
STD-SY-4 result		7.4	542	12.3	56.9	0.017	0.01	<0.05	1.1	<0.5	9.3	1110.5	1.79	<0.05	2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02437-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1008-00091-0001-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
RI 480125	Rock	0.014	0.18	1	3	0.91	2.5	230	34.5
RI 480125 Dup		0.014	0.18	1	3	0.97	2.5	227	34.1
STD-ME-8 expected								19200	
STD-ME-8 result		0.197	0.85	2	71	10.47	12.0	>10000	30.7
RI 480154	Rock	0.024	0.11	1	5	1.79	3.0	13	29.3
RI 480154 Dup		0.024	0.10	1	5	1.85	2.9	13	29.8
STD-ME-8 expected								19200	
STD-ME-8 result		0.204	0.81	2	66	9.85	11.6	>10000	27.9
RI 481013	Rock	0.012	0.10	1	3	1.98	1.4	15	17.9
RI 481013 Dup		0.012	0.10	1	4	1.97	1.3	15	17.7
QCV1008-00091-0007-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected				1	8		119.0	93	517.0
STD-SY-4 result		0.168	0.17	1	4	1.22	121.0	112	56.4

Certificate of Analysis

10-360-02438-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 08/05/2010
Date Completed: 08/23/2010
Invoice:

Samples	Type	Preparation Description
157	Soil	SP-SS-1K/Soils, Humus Sediments 1kg dried, sieved and riffle split

Method	Description
50-AR-UT	50 Element, Aqua Regia, ICPMS, Ultra Trace Level
Au-1AT-AA	Au, 1AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481327	Soil	0.084	0.30	0.97	250.9	28	0.2	0.45	<0.01	0.11	15.22	8.6	10	0.7	26.7
SI 481328	Soil	0.061	0.22	1.60	154.1	53	0.5	0.70	<0.01	0.17	20.96	19.0	21	1.0	56.0
SI 481329	Soil	0.020	0.33	0.96	64.6	22	0.2	0.59	0.01	0.14	16.23	7.0	17	1.4	31.7
SI 481330	Soil	0.012	0.28	0.39	31.3	19	0.1	0.17	0.03	0.20	4.35	3.7	6	0.5	14.2
SI 481331	Soil	0.014	0.29	0.62	134.3	32	0.1	0.65	<0.01	0.31	10.25	3.7	12	1.3	24.7
SI 481332	Soil	0.293	0.70	0.83	641.3	22	0.2	1.72	<0.01	1.10	30.94	9.4	12	1.5	25.8
SI 481333	Soil	0.106	2.34	0.57	631.0	37	0.2	16.98	0.02	0.78	17.54	4.9	9	2.1	36.3
SI 481334	Soil	0.154	0.21	1.31	218.9	25	0.4	0.41	0.03	0.13	18.66	16.5	18	2.0	46.2
SI 481335	Soil	0.038	0.15	1.69	69.8	19	0.3	0.42	0.02	0.08	21.12	16.3	23	2.4	47.1
SI 481336	Soil	0.126	0.02	1.32	299.0	28	0.3	0.45	<0.01	0.12	22.90	15.4	18	1.7	41.3
SI 481337	Soil	0.187	0.23	0.94	176.1	23	0.1	0.29	0.01	0.05	17.05	8.5	10	1.1	22.4
SI 481338	Soil	0.026	0.21	1.07	116.3	35	0.2	0.34	0.02	0.08	20.45	9.7	15	1.7	25.0
SI 481339	Soil	0.050	0.14	1.18	197.9	31	0.2	0.36	0.01	0.10	21.80	12.4	16	2.2	28.2
SI 481340	Soil	<0.005	0.12	1.06	22.8	15	0.1	0.22	0.01	0.06	14.68	6.2	16	1.6	19.7
SI 481341	Soil	0.012	0.16	2.02	66.0	20	0.6	0.59	0.01	0.14	30.00	16.7	28	2.8	49.0
SI 481342	Soil	<0.005	0.17	1.92	21.7	33	0.6	0.47	0.03	0.22	24.22	36.8	28	4.3	67.3
SI 481343	Soil	0.053	0.25	1.56	117.1	31	0.5	0.54	<0.01	0.11	30.29	12.7	21	2.7	43.5
SI 481344	Soil	<0.005	0.23	2.26	33.1	27	0.5	0.56	0.05	0.11	21.18	22.0	31	2.7	51.6
SI 481345	Soil	0.064	0.80	1.38	498.7	17	0.3	0.37	0.12	0.99	17.50	13.6	19	1.3	29.1
SI 481346	Soil	0.046	0.27	0.92	433.6	37	0.2	0.35	<0.01	0.86	20.12	9.1	12	1.1	23.3
SI 481347	Soil	0.050	0.31	1.09	224.4	31	0.2	0.37	<0.01	0.19	20.30	9.8	16	0.8	25.8
SI 481348	Soil	0.040	0.23	0.70	416.5	24	0.2	0.44	0.16	0.46	14.87	8.3	5	0.6	17.1
SI 481349	Soil	0.046	0.17	0.91	422.9	34	0.3	0.34	0.09	0.31	18.11	12.5	11	1.2	22.3
SI 481350	Soil	0.026	0.18	1.72	74.6	21	0.2	0.37	0.02	0.10	18.65	9.5	26	0.9	29.6
SI 481351	Soil	0.020	0.24	2.38	124.4	20	0.3	0.37	0.01	0.07	27.80	15.9	34	1.2	40.8
SI 481352	Soil	<0.005	0.22	2.15	38.4	17	0.3	0.45	0.02	0.08	23.78	18.3	32	3.6	45.8
SI 481353	Soil	<0.005	0.11	2.23	47.0	25	0.4	0.20	0.02	0.04	21.34	22.4	21	1.4	19.4
SI 481354	Soil	<0.005	0.22	1.97	74.8	25	0.3	0.19	0.02	0.06	18.12	18.2	20	1.4	12.7
SI 481355	Soil	0.007	0.21	1.27	167.0	32	0.2	0.35	0.01	0.11	17.37	10.3	21	1.2	23.9
SI 481356	Soil	0.024	0.37	1.24	480.8	90	0.4	0.34	0.02	0.27	16.58	13.8	15	1.1	24.3
SI 481357	Soil	0.065	0.28	1.43	428.6	34	0.3	0.36	0.02	0.11	21.49	9.8	18	1.4	21.9
SI 481358	Soil	0.010	0.26	1.56	271.0	34	0.3	0.49	0.02	0.10	28.39	11.8	26	1.4	22.5
SI 481359	Soil	0.186	0.34	1.44	967.3	46	0.3	0.41	0.04	0.20	28.64	16.7	21	1.2	33.3
SI 481360	Soil	0.066	0.23	1.90	504.0	38	0.4	0.53	0.02	0.17	27.37	15.9	26	1.1	42.0
SI 481361	Soil	0.139	0.68	1.96	532.7	28	0.3	0.39	0.01	0.20	23.43	11.7	26	1.0	32.8
SI 481362	Soil	0.006	0.44	1.56	34.6	28	0.2	0.38	0.02	0.10	23.06	9.8	27	1.3	24.5
SI 481363	Soil	0.005	0.29	2.96	31.4	18	0.3	0.35	0.06	0.08	47.76	14.4	43	1.1	37.7
SI 481364	Soil	0.007	0.17	2.37	59.2	15	0.4	0.48	0.04	0.12	35.94	18.7	36	1.9	47.2
SI 481365	Soil	<0.005	0.32	2.65	26.7	11	0.3	0.52	0.03	0.09	14.73	23.4	40	2.0	56.8
SI 481366	Soil	0.006	0.37	0.97	12.7	28	0.2	0.25	0.02	0.09	9.77	5.5	14	1.9	19.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481367	Soil	<0.005	0.38	1.98	25.7	29	0.4	0.44	0.02	0.15	31.04	12.3	35	2.7	29.0
SI 481368	Soil	<0.005	0.23	1.91	21.1	24	0.3	0.42	0.01	0.09	21.16	11.2	32	3.2	33.8
SI 481369	Soil	<0.005	0.26	2.20	49.7	24	0.4	0.42	0.02	0.11	22.30	17.8	32	3.1	44.6
SI 481371	Soil	<0.005	0.24	1.78	18.4	16	0.2	0.37	0.03	0.08	10.81	8.7	27	3.9	25.8
SI 481372	Soil	<0.005	0.26	1.25	17.6	19	0.3	0.23	0.04	0.06	13.57	9.6	18	2.6	32.9
SI 481373	Soil	<0.005	0.22	2.27	25.5	20	0.3	0.39	0.03	0.07	23.32	15.8	33	5.4	38.8
SI 481374	Soil	0.144	0.27	1.54	239.5	32	0.6	0.50	0.14	0.11	36.60	24.7	22	4.3	51.9
SI 481375	Soil	0.016	0.45	0.55	305.0	38	0.2	0.30	0.02	0.39	22.36	11.8	6	0.9	15.9
SI 481376	Soil	0.746	0.50	0.32	732.1	23	0.5	0.45	0.06	0.33	26.11	36.4	8	1.3	59.4
SI 481377	Soil	0.008	0.34	0.40	85.1	16	0.1	0.11	0.01	0.13	5.04	2.9	<1	0.4	6.3
SI 481378	Soil	0.456	0.15	0.28	281.4	32	0.3	0.49	<0.01	0.07	38.98	20.4	11	0.9	40.6
SI 481379	Soil	0.031	0.50	1.53	341.4	31	0.3	0.48	<0.01	0.12	27.96	13.1	22	1.3	34.5
SI 481380	Soil	0.009	0.33	1.50	56.5	27	0.3	0.52	0.01	0.15	22.90	14.1	24	1.5	31.3
SI 481381	Soil	0.023	0.62	1.42	96.2	33	0.3	0.44	0.03	0.16	24.91	17.4	21	1.4	33.2
SI 481382	Soil	0.107	0.27	1.35	274.3	27	0.6	0.48	0.01	0.11	39.87	28.2	19	1.8	50.8
SI 481383	Soil	<0.005	0.57	0.74	29.3	43	0.2	0.29	0.07	0.78	7.82	8.2	12	1.4	23.1
SI 481384	Soil	0.152	0.57	0.99	668.2	50	0.6	0.56	0.14	0.31	26.04	20.4	16	4.8	61.6
SI 481385	Soil	0.032	0.34	1.11	232.4	27	0.3	0.34	0.05	0.29	14.32	12.4	16	2.1	27.6
SI 481386	Soil	0.037	0.51	0.93	515.0	38	0.4	0.37	0.27	0.29	19.03	11.8	13	1.4	23.8
SI 481387	Soil	0.069	0.80	0.71	585.7	44	0.3	0.28	0.57	0.33	8.57	6.0	6	1.0	24.4
SI 481388	Soil	<0.005	0.34	0.55	17.2	16	0.5	0.57	0.02	0.14	24.27	11.8	18	2.2	71.3
SI 481389	Soil	<0.005	0.16	1.69	23.9	18	0.4	0.61	0.08	0.17	12.13	21.3	24	1.8	55.6
SI 481390	Soil	0.018	0.28	1.56	51.7	19	0.4	0.63	0.05	0.05	23.41	22.1	25	1.7	52.0
SI 481391	Soil	0.011	0.38	1.36	47.5	37	0.5	0.54	0.06	0.13	17.00	24.4	21	2.1	51.2
SI 481392	Soil	0.011	0.55	1.01	63.0	73	0.3	0.36	0.12	0.15	17.69	7.6	13	1.7	35.4
SI 481393	Soil	0.014	0.48	1.25	97.6	60	0.3	0.43	0.09	0.44	20.91	9.1	16	2.3	20.2
SI 481394	Soil	0.043	0.39	1.09	159.5	28	0.2	0.29	<0.01	0.12	37.86	5.9	13	0.7	14.5
SI 481395	Soil	0.039	0.43	1.01	174.0	33	0.3	0.31	0.09	0.24	18.66	8.0	12	0.9	15.7
SI 481396	Soil	0.050	0.46	1.13	140.4	29	0.4	0.36	0.24	0.19	16.94	13.5	17	1.1	37.8
SI 481397	Soil	0.023	0.65	1.37	117.4	33	0.3	0.34	0.03	0.10	26.66	10.0	17	0.7	34.7
SI 481398	Soil	0.013	0.38	1.05	120.6	50	0.2	0.29	0.03	0.17	25.01	8.2	13	0.6	17.5
SI 481399	Soil	0.043	0.35	1.19	136.0	36	0.3	0.31	0.08	0.12	24.90	10.4	16	0.7	29.1
SI 481400	Soil	0.010	0.51	0.90	68.7	36	0.3	0.23	0.03	0.13	20.01	6.5	10	0.5	12.6
SI 481401	Soil	0.031	0.33	1.43	110.5	28	0.4	0.31	<0.01	0.09	32.02	9.3	18	0.6	24.7
SI 481402	Soil	0.019	0.40	1.16	102.2	28	0.3	0.30	<0.01	0.07	31.90	10.2	16	0.5	23.4
SI 481403	Soil	0.032	0.45	1.21	109.3	32	0.3	0.30	0.02	0.09	31.53	9.8	16	0.6	28.3
SI 481404	Soil	0.030	0.25	1.38	111.7	30	0.3	0.33	0.04	0.06	29.41	9.4	17	0.5	26.3
SI 481405	Soil	0.023	0.31	1.14	114.6	21	0.3	0.31	0.01	0.08	28.15	7.8	16	0.5	18.5
SI 481406	Soil	0.025	0.36	1.10	125.2	29	0.3	0.33	0.02	0.14	21.43	8.4	15	0.6	22.5
SI 481407	Soil	0.061	0.48	1.25	130.1	25	0.4	0.40	0.13	0.18	16.04	14.6	20	1.3	35.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481408	Soil	0.010	0.43	0.73	27.2	23	0.5	0.71	0.02	0.09	22.05	21.0	16	1.6	66.8
SI 481409	Soil	0.021	0.40	1.43	58.3	25	0.4	0.43	0.02	0.14	19.70	12.3	20	1.4	35.0
SI 481410	Soil	0.009	0.43	0.91	40.6	47	0.3	0.41	0.03	0.34	24.18	10.2	15	1.8	26.8
SI 481411	Soil	0.020	0.33	0.87	93.9	43	0.2	0.38	0.16	0.28	20.39	10.1	16	1.6	26.6
SI 481412	Soil	0.048	0.48	1.54	123.5	36	0.6	0.66	0.27	0.35	20.95	54.2	19	2.4	57.9
SI 481413	Soil	0.036	0.53	0.86	213.8	46	0.5	0.60	0.20	0.21	12.07	8.3	13	1.2	52.1
SI 481414	Soil	0.109	0.43	0.35	1049.9	73	0.2	0.44	0.06	0.34	16.49	16.4	6	1.4	20.9
SI 481415	Soil	0.014	0.59	0.86	49.1	64	0.4	0.31	0.17	0.24	10.07	8.0	10	1.4	24.8
SI 481416	Soil	0.013	0.38	0.98	32.1	29	0.3	0.61	0.04	0.15	16.71	14.2	16	1.0	45.1
SI 481417	Soil	0.037	0.47	0.76	230.3	20	0.3	0.28	0.14	0.23	14.70	9.5	12	1.2	26.4
SI 481418	Soil	0.023	0.52	0.68	108.7	23	0.2	0.34	0.11	0.05	23.55	12.1	14	0.7	29.7
SI 481419	Soil	0.218	0.70	0.67	503.7	46	0.4	0.35	0.27	0.34	16.10	9.6	9	1.2	22.1
SI 481420	Soil	0.063	0.57	1.99	394.1	16	0.6	0.44	0.11	0.21	24.70	23.6	26	1.2	59.2
SI 481421	Soil	0.110	0.48	0.95	655.9	15	0.4	0.42	0.26	0.32	16.51	16.3	17	1.1	37.2
SI 481422	Soil	0.033	0.66	0.37	282.5	23	0.2	0.18	0.06	0.17	8.19	6.0	5	1.1	12.4
SI 481423	Soil	0.029	0.60	1.01	118.2	19	0.5	0.32	0.02	0.17	14.32	33.2	14	2.5	73.4
SI 481424	Soil	0.024	0.47	1.97	51.4	18	0.7	0.48	0.04	0.15	30.59	26.5	31	1.8	96.3
SI 481425	Soil	0.018	0.42	2.18	59.9	17	0.6	0.47	0.05	0.21	33.31	29.6	33	1.4	107.3
SI 481426	Soil	0.306	0.48	0.51	1652.2	11	0.3	0.17	0.02	0.23	24.03	5.2	<1	0.9	12.4
SI 481427	Soil	0.067	0.45	0.93	442.5	62	0.5	0.52	0.01	0.17	26.43	17.9	15	1.4	42.2
SI 481428	Soil	0.509	0.80	1.22	1215.8	29	0.7	0.51	0.07	0.31	30.18	26.3	18	2.3	72.2
SI 481429	Soil	0.058	0.50	0.81	440.7	71	0.5	0.52	0.08	0.49	25.07	16.0	16	1.3	40.7
SI 481430	Soil	0.060	0.50	1.17	244.3	113	0.9	0.46	0.27	0.26	31.98	23.8	23	1.8	50.4
SI 481431	Soil	0.051	0.48	1.21	303.5	25	0.6	0.56	0.05	0.07	51.85	17.3	18	1.4	57.2
SI 481432	Soil	0.073	0.50	0.60	162.9	20	0.4	0.42	0.03	0.04	46.06	15.4	10	2.2	46.1
SI 481433	Soil	0.105	0.48	0.62	264.3	18	0.5	0.34	0.05	0.07	26.55	17.6	9	2.0	43.2
SI 481434	Soil	0.007	0.49	1.71	49.3	29	0.7	0.45	0.05	0.08	15.15	49.3	24	4.9	68.1
SI 481435	Soil	0.018	0.43	1.77	104.9	29	0.4	0.34	0.01	0.13	18.27	19.4	27	1.9	40.0
SI 481436	Soil	0.060	0.60	0.73	288.7	29	0.1	0.27	<0.01	0.10	19.24	7.3	10	0.9	22.2
SI 481437	Soil	0.126	0.52	1.53	523.5	33	0.3	0.37	0.02	0.30	22.07	16.5	21	1.0	30.4
SI 481438	Soil	0.180	0.62	1.77	641.5	41	0.5	0.46	0.05	0.27	29.78	20.2	24	1.5	41.5
SI 481439	Soil	0.017	0.50	1.06	133.9	47	0.2	0.28	0.02	0.11	17.46	6.7	15	1.2	20.7
SI 481440	Soil	0.268	0.56	1.27	770.7	29	0.4	0.34	0.02	0.17	27.57	18.7	14	1.3	120.8
SI 481441	Soil	0.009	0.43	1.54	77.4	50	0.4	0.32	0.02	0.12	18.81	11.4	18	1.5	29.8
SI 481442	Soil	0.018	0.49	1.38	181.9	38	0.3	0.32	0.02	0.13	20.84	9.8	19	1.6	24.4
SI 481443	Soil	0.014	0.37	1.76	115.0	25	0.3	0.37	0.02	0.11	22.15	13.6	26	2.3	33.8
SI 481444	Soil	<0.005	0.40	1.67	21.3	21	0.2	0.24	0.01	0.06	16.91	8.7	22	1.8	23.9
SI 481445	Soil	0.008	0.54	1.89	35.8	20	0.3	0.39	0.02	0.12	19.06	14.6	32	2.6	35.1
SI 481446	Soil	0.014	0.45	1.77	187.1	26	0.2	0.37	<0.01	0.11	24.47	14.5	22	1.2	36.0
SI 481447	Soil	0.020	0.41	0.41	232.7	20	0.3	0.30	0.01	0.09	12.69	11.6	8	4.8	34.1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481448	Soil	0.023	0.38	0.85	57.9	22	0.3	0.27	<0.01	0.07	18.44	10.2	11	1.9	27.0
SI 481449	Soil	0.021	0.77	1.38	54.7	23	0.3	0.32	0.01	0.06	27.79	11.1	20	2.4	28.6
SI 481450	Soil	0.009	0.58	1.67	86.2	32	0.2	0.35	0.02	0.09	22.33	12.4	24	1.1	32.8
SI 481451	Soil	0.006	0.48	1.76	31.6	20	0.2	0.27	0.03	0.06	27.75	12.6	27	1.1	28.7
SI 481452	Soil	<0.005	0.53	2.35	44.0	29	0.5	0.43	0.04	0.13	32.32	54.3	36	3.0	68.6
SI 481453	Soil	0.005	0.53	1.96	37.4	18	0.3	0.30	<0.01	0.07	20.03	12.5	29	1.0	31.4
SI 481454	Soil	<0.005	0.55	1.40	27.8	22	0.2	0.32	0.01	0.06	15.42	9.3	24	1.6	20.5
TI 480140	Soil	0.129	0.73	1.33	237.5	35	0.3	0.32	0.39	0.45	16.23	14.6	19	2.6	29.3
TI 480141	Soil	0.030	0.92	0.84	197.4	57	0.6	0.62	0.64	0.31	21.92	19.1	9	0.5	71.1
TI 480195	Soil	0.050	0.62	0.46	311.2	18	0.2	0.21	0.28	0.32	11.76	9.0	7	1.5	21.8
TI 480196	Soil	0.049	0.51	1.29	51.8	30	0.4	0.33	0.55	0.15	18.17	12.3	18	1.5	28.2
TI 480197	Soil	0.073	0.69	0.95	288.3	22	0.3	0.35	0.20	0.28	23.49	12.1	15	1.0	33.0
TI 480198	Soil	0.007	0.56	1.57	21.4	29	0.4	0.36	0.51	0.11	17.85	14.6	24	0.6	30.9
TI 480199	Soil	0.008	0.43	1.73	33.1	33	0.4	0.43	0.57	0.22	15.21	16.7	23	3.2	32.5
TI 480200	Soil	0.170	0.70	0.98	359.3	30	0.3	0.26	0.57	0.51	9.50	11.4	12	2.3	30.1
TI 481305	Soil	0.015	0.62	1.55	249.1	40	0.5	0.38	0.48	0.16	13.36	16.8	20	0.9	36.3
TI 481306	Soil	<0.005	0.48	1.82	45.2	26	0.3	0.32	0.37	0.10	14.61	24.5	26	0.4	33.8
TI 481307	Soil	<0.005	0.56	1.57	8.0	43	0.3	0.23	0.53	0.14	11.71	11.9	21	0.3	16.9
TI 481308	Soil	<0.005	0.54	1.81	43.6	40	0.4	0.37	0.27	0.09	18.53	12.7	24	0.4	29.9
TI 481309	Soil	0.006	0.85	1.85	34.4	42	0.5	0.38	0.36	0.12	18.86	17.0	24	0.4	41.5
TI 481310	Soil	0.005	0.51	1.39	10.2	25	0.4	0.36	0.45	0.10	23.61	13.2	18	0.2	30.2
TI 481311	Soil	<0.005	0.60	1.75	32.7	29	0.4	0.29	0.31	0.10	17.30	13.9	24	0.3	27.1
TI 481312	Soil	<0.005	0.50	1.58	22.2	38	0.4	0.32	0.29	0.09	21.40	12.1	20	0.3	22.2
TI 481313	Soil	0.006	0.51	1.30	76.3	20	0.3	0.23	0.58	0.10	11.38	9.5	22	0.2	22.7
TI 481314	Soil	<0.005	0.51	1.46	15.7	29	0.4	0.32	0.27	0.08	14.19	12.1	18	0.2	24.2
TI 481315	Soil	0.006	0.55	1.32	84.2	25	0.4	0.30	0.45	0.10	16.46	11.8	16	0.2	23.2
TI 481316	Soil	<0.005	0.51	1.54	32.0	30	0.4	0.35	0.30	0.07	17.91	12.4	19	0.3	28.6
TI 481317	Soil	0.007	0.51	1.47	64.1	50	0.4	0.31	0.52	0.12	13.97	13.3	19	0.3	27.4
TI 481318	Soil	0.005	0.48	1.48	26.0	34	0.4	0.33	0.31	0.14	18.17	11.9	19	0.3	49.2
TI 481319	Soil	0.006	0.52	1.47	30.9	35	0.4	0.36	0.39	0.09	16.27	12.4	18	0.3	29.5
TI 481320	Soil	0.006	0.53	1.76	62.0	33	0.3	0.26	0.47	0.08	10.57	13.6	23	0.3	20.3
TI 481321	Soil	<0.005	0.46	1.63	29.2	29	0.3	0.30	0.27	0.07	17.23	11.5	20	0.2	21.4
TI 481322	Soil	0.005	0.49	1.46	25.5	29	0.3	0.29	0.30	0.08	13.08	11.5	19	0.2	21.8
TI 481323	Soil	0.006	0.58	1.57	30.2	34	0.4	0.33	0.36	0.09	15.58	12.4	20	0.3	26.3
TI 481324	Soil	0.006	0.43	1.50	36.3	34	0.4	0.30	0.33	0.11	15.73	12.3	19	0.3	24.2
TI 481325	Soil	0.005	0.59	1.41	24.8	25	0.3	0.26	0.30	0.08	17.75	11.6	19	0.2	19.4
TI 481326	Soil	<0.005	0.49	1.48	43.2	34	0.3	0.29	0.35	0.11	18.00	12.2	20	0.3	25.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481327	Soil	3.80	3.4	<0.05	<0.02	0.03	0.02	8.3	13.0	0.18	240	0.53	<0.01	0.3	18.9
SI 481328	Soil	5.15	4.1	<0.05	<0.02	0.04	0.03	11.7	35.7	0.51	418	0.58	<0.01	0.6	47.4
SI 481329	Soil	3.68	5.1	<0.05	<0.02	0.02	0.03	8.8	16.2	0.24	237	0.87	<0.01	0.4	16.9
SI 481330	Soil	1.38	2.2	<0.05	<0.02	<0.01	0.02	2.5	1.1	0.03	171	0.34	0.01	0.1	7.3
SI 481331	Soil	2.64	3.1	<0.05	<0.02	0.03	0.02	5.4	2.4	0.05	315	0.91	<0.01	0.2	7.2
SI 481332	Soil	3.73	4.4	<0.05	<0.02	0.12	0.03	15.3	12.1	0.18	338	0.83	<0.01	0.4	21.5
SI 481333	Soil	2.57	4.1	<0.05	<0.02	0.33	0.03	9.3	2.7	0.05	273	0.73	<0.01	0.2	10.6
SI 481334	Soil	3.79	3.6	<0.05	<0.02	0.02	0.02	9.9	30.8	0.46	483	0.45	<0.01	0.1	28.4
SI 481335	Soil	3.89	5.4	<0.05	<0.02	0.02	0.02	12.0	51.1	0.68	544	0.43	<0.01	0.1	39.1
SI 481336	Soil	4.05	4.5	<0.05	<0.02	0.02	0.02	12.8	36.2	0.43	400	0.51	<0.01	0.2	34.9
SI 481337	Soil	2.97	3.6	<0.05	<0.02	0.01	0.02	9.2	14.0	0.20	231	0.41	<0.01	0.3	17.0
SI 481338	Soil	2.75	4.3	<0.05	<0.02	0.02	0.02	10.9	23.8	0.28	352	0.50	<0.01	0.3	21.2
SI 481339	Soil	3.97	4.0	<0.05	<0.02	0.02	0.02	12.0	23.5	0.33	543	0.47	<0.01	0.2	25.5
SI 481340	Soil	2.50	3.5	<0.05	<0.02	0.02	0.02	8.1	27.0	0.38	372	0.29	0.01	0.1	19.0
SI 481341	Soil	5.10	5.9	<0.05	<0.02	0.03	0.02	16.8	65.4	0.79	888	0.31	<0.01	0.1	49.3
SI 481342	Soil	5.22	5.8	<0.05	<0.02	0.04	0.02	12.1	49.9	0.70	1116	0.55	<0.01	0.1	42.7
SI 481343	Soil	4.52	3.8	<0.05	<0.02	0.03	0.02	17.2	32.8	0.47	332	0.39	<0.01	0.1	32.0
SI 481344	Soil	5.09	6.7	<0.05	<0.02	0.03	0.01	11.7	75.8	0.95	662	0.63	<0.01	<0.05	49.9
SI 481345	Soil	4.00	4.1	<0.05	<0.02	0.20	0.02	9.1	43.2	0.56	398	0.46	<0.01	0.1	35.7
SI 481346	Soil	3.04	4.2	<0.05	<0.02	0.03	0.02	10.4	12.7	0.17	500	0.60	<0.01	0.3	19.3
SI 481347	Soil	3.92	4.1	<0.05	<0.02	0.02	0.03	11.0	20.4	0.28	377	0.54	<0.01	0.4	22.3
SI 481348	Soil	2.55	2.5	<0.05	<0.02	0.02	0.02	7.0	5.9	0.10	287	0.51	<0.01	0.1	16.4
SI 481349	Soil	3.39	3.8	<0.05	<0.02	0.03	0.04	8.9	14.9	0.20	492	0.62	<0.01	0.4	24.6
SI 481350	Soil	4.42	6.6	<0.05	<0.02	0.02	0.02	9.4	32.6	0.57	405	0.64	<0.01	0.4	28.4
SI 481351	Soil	5.35	6.6	<0.05	<0.02	0.02	0.01	14.1	59.3	0.96	559	0.48	<0.01	0.1	47.7
SI 481352	Soil	5.26	7.4	<0.05	<0.02	0.03	0.02	12.0	55.8	0.88	885	0.60	<0.01	0.1	44.7
SI 481353	Soil	4.90	6.0	<0.05	<0.02	0.02	0.02	11.1	69.5	1.04	1134	0.22	<0.01	0.1	55.5
SI 481354	Soil	4.45	5.2	<0.05	<0.02	0.01	0.02	9.9	54.2	0.89	934	0.25	<0.01	0.1	43.8
SI 481355	Soil	3.57	5.6	<0.05	<0.02	0.02	0.03	9.0	21.7	0.35	668	0.68	<0.01	0.3	20.7
SI 481356	Soil	3.12	4.5	<0.05	<0.02	0.02	0.03	7.7	11.7	0.21	3243	0.76	<0.01	0.2	16.2
SI 481357	Soil	3.64	4.8	<0.05	<0.02	0.02	0.04	10.7	17.9	0.32	1247	0.85	<0.01	0.4	18.7
SI 481358	Soil	4.24	5.9	<0.05	<0.02	0.03	0.04	14.3	33.1	0.55	642	0.76	<0.01	0.5	26.5
SI 481359	Soil	4.45	4.3	<0.05	<0.02	0.03	0.03	14.4	32.1	0.53	1046	0.57	<0.01	0.2	35.6
SI 481360	Soil	4.67	6.1	<0.05	<0.02	0.03	0.02	13.9	58.2	0.72	760	0.54	<0.01	0.2	46.2
SI 481361	Soil	5.32	6.3	<0.05	<0.02	0.03	0.02	11.5	45.4	0.63	788	0.55	<0.01	0.2	33.1
SI 481362	Soil	3.97	6.5	<0.05	<0.02	0.02	0.03	11.6	34.2	0.55	423	0.64	<0.01	0.4	26.4
SI 481363	Soil	5.90	8.3	<0.05	<0.02	0.02	0.02	24.5	86.3	1.28	580	0.37	<0.01	0.1	56.6
SI 481364	Soil	5.41	8.0	<0.05	<0.02	0.03	0.02	17.8	72.4	0.99	698	0.47	<0.01	0.1	53.3
SI 481365	Soil	6.09	8.8	<0.05	<0.02	0.03	0.02	5.6	71.2	1.06	737	0.57	<0.01	0.1	55.0
SI 481366	Soil	2.51	4.2	<0.05	<0.02	0.01	0.02	4.7	17.1	0.27	546	0.51	0.01	0.2	14.0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481367	Soil	5.29	8.2	<0.05	<0.02	0.02	0.02	15.3	50.7	0.67	893	0.69	<0.01	0.8	34.1
SI 481368	Soil	4.74	7.8	<0.05	<0.02	0.02	0.02	9.9	54.2	0.71	522	0.52	<0.01	0.3	34.2
SI 481369	Soil	5.10	6.8	<0.05	<0.02	0.03	0.02	10.4	64.8	0.88	604	0.56	<0.01	0.2	41.2
SI 481371	Soil	3.98	5.7	<0.05	<0.02	0.02	0.02	4.5	40.4	0.62	413	0.46	<0.01	0.2	26.4
SI 481372	Soil	2.39	4.3	<0.05	<0.02	0.01	0.02	6.0	36.8	0.47	349	0.37	0.01	0.1	25.0
SI 481373	Soil	5.05	7.1	<0.05	<0.02	0.02	0.02	10.1	66.6	0.94	591	0.46	<0.01	0.1	42.9
SI 481374	Soil	4.52	4.8	<0.05	<0.02	0.03	0.03	18.4	46.1	0.65	792	0.34	0.01	0.1	46.6
SI 481375	Soil	2.86	2.6	<0.05	<0.02	0.02	0.02	11.9	2.9	0.05	661	0.50	<0.01	0.2	24.9
SI 481376	Soil	4.71	1.0	<0.05	<0.02	0.03	0.04	15.4	3.6	0.06	1002	0.54	<0.01	<0.05	47.9
SI 481377	Soil	0.88	1.5	<0.05	<0.02	<0.01	0.02	2.6	0.7	0.02	221	0.21	0.01	0.1	4.8
SI 481378	Soil	3.04	1.4	<0.05	<0.02	0.02	0.02	23.7	2.2	0.05	530	0.44	<0.01	0.1	32.7
SI 481379	Soil	4.45	5.3	<0.05	<0.02	0.02	0.02	16.6	44.4	0.51	371	0.42	<0.01	0.2	34.5
SI 481380	Soil	4.35	5.7	<0.05	<0.02	0.02	0.04	12.7	38.0	0.49	427	0.66	<0.01	0.8	29.2
SI 481381	Soil	4.62	4.5	<0.05	<0.02	0.02	0.04	14.1	34.0	0.49	579	0.55	<0.01	0.3	29.3
SI 481382	Soil	6.00	3.6	<0.05	<0.02	0.02	0.03	23.3	35.1	0.48	779	0.46	<0.01	<0.05	51.1
SI 481383	Soil	2.37	3.1	<0.05	<0.02	<0.01	0.03	4.7	11.9	0.18	600	0.38	0.01	0.2	12.9
SI 481384	Soil	4.74	2.8	<0.05	<0.02	0.03	0.04	14.5	25.4	0.27	563	0.63	<0.01	0.1	46.9
SI 481385	Soil	3.18	3.1	<0.05	<0.02	0.02	0.03	8.1	30.8	0.39	436	0.32	<0.01	0.1	26.0
SI 481386	Soil	3.09	2.9	<0.05	<0.02	0.03	0.04	10.7	24.5	0.37	393	0.32	<0.01	0.1	27.5
SI 481387	Soil	1.78	2.0	<0.05	<0.02	0.05	0.03	4.6	16.9	0.20	227	0.25	0.02	0.2	15.8
SI 481388	Soil	5.22	2.2	<0.05	<0.02	0.03	0.02	14.6	11.6	0.22	249	0.20	<0.01	<0.05	51.0
SI 481389	Soil	4.82	4.5	<0.05	<0.02	0.03	0.02	7.0	56.1	0.71	316	0.40	<0.01	<0.05	51.6
SI 481390	Soil	5.32	4.6	<0.05	<0.02	0.03	0.02	13.6	53.0	0.67	375	0.46	<0.01	<0.05	56.6
SI 481391	Soil	4.49	4.4	<0.05	<0.02	0.03	0.03	9.2	34.4	0.48	987	0.51	<0.01	0.2	32.4
SI 481392	Soil	2.27	3.6	<0.05	<0.02	0.02	0.02	9.3	21.3	0.24	314	0.39	0.01	0.4	20.2
SI 481393	Soil	3.15	4.8	<0.05	<0.02	0.02	0.04	11.2	30.2	0.34	505	0.48	<0.01	0.6	18.1
SI 481394	Soil	3.32	4.3	<0.05	<0.02	0.02	0.02	20.8	22.9	0.30	193	0.43	<0.01	0.5	18.2
SI 481395	Soil	2.96	3.4	<0.05	<0.02	0.04	0.03	10.1	28.1	0.33	362	0.39	<0.01	0.3	19.9
SI 481396	Soil	3.43	3.4	<0.05	<0.02	0.02	0.02	9.2	35.3	0.44	470	0.42	<0.01	0.1	32.5
SI 481397	Soil	3.89	3.6	<0.05	<0.02	0.02	0.03	15.1	36.7	0.52	332	0.42	<0.01	0.1	31.0
SI 481398	Soil	3.31	3.6	<0.05	<0.02	0.01	0.02	13.3	26.3	0.32	472	0.49	<0.01	0.3	20.5
SI 481399	Soil	3.39	3.5	<0.05	<0.02	0.02	0.04	13.3	32.4	0.46	367	0.34	<0.01	0.1	29.5
SI 481400	Soil	2.60	3.5	<0.05	<0.02	0.01	0.03	10.4	17.8	0.21	240	0.37	<0.01	0.4	13.8
SI 481401	Soil	3.80	3.8	<0.05	<0.02	0.02	0.03	17.7	38.3	0.48	237	0.33	<0.01	0.2	30.2
SI 481402	Soil	3.00	3.2	<0.05	<0.02	0.02	0.03	17.3	34.7	0.41	283	0.29	<0.01	0.1	27.2
SI 481403	Soil	3.30	3.7	<0.05	<0.02	0.02	0.04	16.6	33.8	0.44	302	0.34	<0.01	0.1	29.5
SI 481404	Soil	3.67	3.5	<0.05	<0.02	0.02	0.04	15.5	39.1	0.50	254	0.33	<0.01	0.1	30.4
SI 481405	Soil	3.58	4.0	<0.05	<0.02	0.02	0.02	15.2	31.0	0.40	247	0.43	<0.01	0.3	24.7
SI 481406	Soil	3.41	3.5	<0.05	<0.02	0.02	0.02	11.3	33.8	0.39	260	0.38	<0.01	0.2	27.9
SI 481407	Soil	3.65	4.1	<0.05	<0.02	0.02	0.03	8.3	42.3	0.50	604	0.47	<0.01	0.1	36.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481408	Soil	3.60	2.7	<0.05	<0.02	0.03	0.02	13.3	17.9	0.25	440	0.39	<0.01	<0.05	48.4
SI 481409	Soil	3.73	4.4	<0.05	<0.02	0.02	0.02	11.3	46.5	0.57	364	0.35	<0.01	<0.05	33.3
SI 481410	Soil	3.02	5.6	<0.05	<0.02	0.02	0.03	13.3	13.0	0.19	682	0.58	<0.01	0.4	14.0
SI 481411	Soil	3.60	5.1	<0.05	<0.02	0.02	0.04	11.4	17.7	0.27	406	0.50	<0.01	0.2	22.0
SI 481412	Soil	6.60	4.1	<0.05	<0.02	0.06	0.02	9.4	42.9	0.61	2559	0.88	<0.01	0.1	67.6
SI 481413	Soil	4.19	2.8	<0.05	<0.02	0.03	0.03	6.7	14.9	0.20	446	1.18	<0.01	0.1	21.1
SI 481414	Soil	2.59	2.0	<0.05	<0.02	0.03	0.04	8.3	1.7	0.02	973	0.66	<0.01	0.1	18.1
SI 481415	Soil	2.17	2.6	<0.05	<0.02	0.01	0.03	5.3	16.2	0.19	292	0.29	<0.01	0.1	17.4
SI 481416	Soil	3.72	3.2	<0.05	<0.02	0.03	0.02	10.0	28.4	0.33	241	0.88	<0.01	<0.05	33.1
SI 481417	Soil	2.61	2.0	<0.05	<0.02	0.02	0.02	7.8	20.9	0.27	401	0.26	<0.01	<0.05	22.9
SI 481418	Soil	2.90	1.9	<0.05	<0.02	0.02	0.02	13.8	16.8	0.25	330	0.34	<0.01	<0.05	27.8
SI 481419	Soil	2.56	2.1	<0.05	<0.02	0.04	0.03	8.7	12.7	0.17	342	0.37	<0.01	0.1	17.8
SI 481420	Soil	5.19	5.6	<0.05	<0.02	0.03	0.02	14.8	68.3	0.80	556	0.38	<0.01	<0.05	47.9
SI 481421	Soil	3.07	3.2	<0.05	<0.02	0.03	0.03	9.1	32.3	0.40	372	0.33	<0.01	<0.05	34.9
SI 481422	Soil	1.26	2.1	<0.05	<0.02	0.02	0.03	4.4	4.6	0.07	169	0.32	0.01	0.1	13.9
SI 481423	Soil	3.13	3.4	<0.05	<0.02	0.02	0.02	8.2	21.6	0.29	463	0.52	<0.01	0.1	32.5
SI 481424	Soil	5.45	6.0	<0.05	<0.02	0.02	0.02	18.4	78.3	0.79	535	0.68	<0.01	<0.05	65.2
SI 481425	Soil	6.01	7.0	<0.05	0.03	0.03	0.02	20.7	92.3	0.90	615	0.60	<0.01	<0.05	68.9
SI 481426	Soil	3.55	0.5	<0.05	<0.02	0.03	0.01	11.5	1.5	0.02	114	0.41	<0.01	<0.05	20.1
SI 481427	Soil	4.50	3.0	<0.05	<0.02	0.03	0.04	15.5	13.9	0.18	536	0.75	<0.01	0.8	36.3
SI 481428	Soil	5.95	3.5	<0.05	<0.02	0.04	0.03	17.4	31.8	0.44	668	0.54	<0.01	0.1	57.8
SI 481429	Soil	4.14	2.8	<0.05	<0.02	0.03	0.05	15.2	6.8	0.09	483	0.83	<0.01	1.0	36.4
SI 481430	Soil	5.66	3.9	<0.05	<0.02	0.04	0.04	16.6	8.8	0.20	622	0.71	<0.01	1.0	53.1
SI 481431	Soil	4.37	4.1	<0.05	<0.02	0.03	0.02	29.5	40.0	0.52	515	0.55	<0.01	<0.05	50.9
SI 481432	Soil	3.32	2.1	<0.05	<0.02	0.02	0.02	25.6	14.5	0.20	456	0.46	<0.01	<0.05	37.6
SI 481433	Soil	3.65	1.9	<0.05	<0.02	0.02	0.02	13.7	16.5	0.25	861	0.43	<0.01	<0.05	42.1
SI 481434	Soil	3.95	6.1	<0.05	<0.02	0.03	0.02	6.1	50.4	0.65	785	0.58	0.01	0.2	37.6
SI 481435	Soil	4.82	5.7	<0.05	<0.02	0.02	0.02	9.0	42.5	0.64	757	0.60	<0.01	0.2	37.5
SI 481436	Soil	2.40	4.0	<0.05	<0.02	0.02	0.02	10.0	7.2	0.11	528	0.56	0.01	0.2	12.3
SI 481437	Soil	4.87	4.4	<0.05	<0.02	0.03	0.03	11.3	33.2	0.54	995	0.53	<0.01	0.2	33.5
SI 481438	Soil	4.91	5.1	<0.05	<0.02	0.03	0.03	14.7	46.2	0.68	1243	0.64	<0.01	0.2	44.8
SI 481439	Soil	3.14	4.5	<0.05	<0.02	0.02	0.02	9.0	13.0	0.22	815	0.53	0.01	0.3	13.3
SI 481440	Soil	4.40	3.7	<0.05	<0.02	0.02	0.02	13.2	26.4	0.43	1423	0.59	0.01	0.1	33.4
SI 481441	Soil	3.76	5.3	<0.05	<0.02	0.02	0.02	10.0	34.6	0.53	1205	0.49	<0.01	0.4	23.3
SI 481442	Soil	3.43	4.3	<0.05	<0.02	0.02	0.03	10.8	31.4	0.48	442	0.63	<0.01	0.3	25.6
SI 481443	Soil	4.58	6.1	<0.05	<0.02	0.02	0.02	11.4	45.2	0.66	578	0.51	<0.01	0.3	34.9
SI 481444	Soil	3.73	5.2	<0.05	<0.02	0.01	0.02	9.1	33.4	0.61	424	0.36	<0.01	0.2	21.3
SI 481445	Soil	4.64	6.3	<0.05	<0.02	0.02	0.03	10.2	38.0	0.73	692	0.51	<0.01	0.3	32.0
SI 481446	Soil	4.38	5.2	<0.05	<0.02	0.02	0.02	12.6	46.3	0.75	548	0.58	<0.01	0.2	36.7
SI 481447	Soil	2.69	1.0	<0.05	<0.02	0.02	0.03	5.0	3.3	0.04	515	0.35	<0.01	<0.05	26.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481448	Soil	2.44	2.6	<0.05	<0.02	0.01	0.02	8.7	16.5	0.23	340	0.30	<0.01	0.1	24.7
SI 481449	Soil	3.24	4.9	<0.05	<0.02	0.02	0.02	14.5	35.6	0.51	429	0.37	<0.01	0.1	32.9
SI 481450	Soil	3.78	5.7	<0.05	<0.02	0.02	0.02	11.2	40.4	0.57	459	0.55	<0.01	0.3	29.2
SI 481451	Soil	3.91	5.3	<0.05	<0.02	0.02	0.02	14.1	44.9	0.71	509	0.47	<0.01	0.2	33.9
SI 481452	Soil	5.63	8.3	<0.05	<0.02	0.03	0.01	16.2	82.8	1.02	1249	0.65	<0.01	0.1	60.8
SI 481453	Soil	4.70	6.0	<0.05	<0.02	0.02	0.02	10.0	43.7	0.75	461	0.47	<0.01	0.3	34.0
SI 481454	Soil	4.70	5.5	<0.05	<0.02	0.02	0.03	7.7	20.3	0.40	804	0.60	<0.01	0.3	17.1
TI 480140	Soil	3.55	3.5	<0.05	<0.02	0.03	0.03	8.9	41.2	0.49	413	0.52	<0.01	0.1	34.4
TI 480141	Soil	3.73	2.0	<0.05	0.07	0.03	0.04	11.2	20.7	0.64	894	3.08	<0.01	<0.05	38.0
TI 480195	Soil	2.12	1.3	<0.05	<0.02	0.01	0.02	7.1	8.5	0.13	348	0.32	<0.01	<0.05	19.2
TI 480196	Soil	3.74	3.2	<0.05	<0.02	0.02	0.03	10.1	35.7	0.49	340	0.30	<0.01	0.1	31.4
TI 480197	Soil	3.73	2.9	<0.05	<0.02	0.03	0.02	13.7	25.7	0.35	363	0.50	<0.01	0.1	28.1
TI 480198	Soil	3.64	4.1	<0.05	<0.02	0.02	0.02	9.8	47.7	0.74	466	0.39	<0.01	0.1	36.1
TI 480199	Soil	3.67	4.1	<0.05	<0.02	0.02	0.03	8.5	49.7	0.73	559	0.35	<0.01	0.2	35.2
TI 480200	Soil	2.88	2.2	<0.05	<0.02	0.02	0.04	5.6	17.5	0.27	591	0.44	<0.01	0.2	24.0
TI 481305	Soil	3.24	3.6	<0.05	<0.02	0.03	0.04	6.9	38.6	0.51	538	0.43	0.01	0.2	28.1
TI 481306	Soil	3.80	4.5	<0.05	<0.02	0.01	0.02	7.9	53.2	0.82	548	0.51	<0.01	0.1	35.9
TI 481307	Soil	3.21	3.5	<0.05	<0.02	0.01	0.03	6.2	45.8	0.63	641	0.60	0.01	0.1	25.5
TI 481308	Soil	3.74	5.2	<0.05	<0.02	0.02	0.03	10.0	65.3	0.76	340	0.37	<0.01	0.1	35.5
TI 481309	Soil	4.04	4.6	<0.05	<0.02	0.02	0.04	10.3	58.4	0.78	500	0.43	<0.01	0.1	37.8
TI 481310	Soil	3.69	3.9	<0.05	<0.02	0.02	0.02	11.8	46.8	0.62	553	0.34	<0.01	<0.05	31.0
TI 481311	Soil	3.59	4.3	<0.05	<0.02	0.01	0.03	9.2	55.0	0.76	389	0.33	<0.01	<0.05	33.7
TI 481312	Soil	3.53	4.3	<0.05	<0.02	0.02	0.03	10.7	53.3	0.67	415	0.39	<0.01	0.1	31.0
TI 481313	Soil	3.21	3.2	<0.05	0.02	0.02	0.02	6.0	45.5	0.57	279	0.29	<0.01	0.1	26.1
TI 481314	Soil	3.46	3.7	<0.05	<0.02	0.02	0.02	6.9	46.4	0.62	421	0.31	<0.01	0.1	28.0
TI 481315	Soil	3.27	3.5	<0.05	<0.02	0.02	0.03	8.0	46.2	0.59	314	0.27	<0.01	0.1	30.2
TI 481316	Soil	3.60	4.0	<0.05	<0.02	0.02	0.02	8.8	54.2	0.67	338	0.29	<0.01	0.1	32.0
TI 481317	Soil	3.63	3.6	<0.05	<0.02	0.02	0.03	7.1	48.9	0.64	414	0.54	<0.01	0.1	30.1
TI 481318	Soil	3.36	4.2	<0.05	<0.02	0.02	0.03	9.0	53.2	0.64	298	0.92	<0.01	0.1	33.1
TI 481319	Soil	3.60	4.0	<0.05	<0.02	0.02	0.02	8.4	49.6	0.63	527	0.36	<0.01	0.1	31.8
TI 481320	Soil	5.21	4.8	<0.05	<0.02	0.02	0.01	5.6	60.7	0.77	1490	0.41	<0.01	<0.05	37.7
TI 481321	Soil	3.82	4.4	<0.05	<0.02	0.02	0.02	8.7	58.6	0.72	494	0.30	<0.01	0.1	33.5
TI 481322	Soil	3.44	3.9	<0.05	<0.02	0.02	0.02	6.5	51.3	0.65	377	0.27	<0.01	<0.05	31.2
TI 481323	Soil	3.69	3.9	<0.05	<0.02	0.02	0.03	8.2	49.8	0.68	427	0.31	<0.01	0.1	31.7
TI 481324	Soil	3.48	4.1	<0.05	<0.02	0.02	0.02	7.8	52.4	0.67	569	0.32	<0.01	0.1	33.0
TI 481325	Soil	3.18	3.6	<0.05	<0.02	0.02	0.02	8.9	45.7	0.65	334	0.25	<0.01	<0.05	27.9
TI 481326	Soil	3.64	4.2	<0.05	<0.02	0.02	0.02	9.1	51.7	0.66	802	0.31	<0.01	0.1	32.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th	Ti
		50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample	Sample	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%
Description	Type	5	0.2	0.1	0.01	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2	0.005
SI 481327	Soil	489	71.2	4.2	<0.01	0.02	0.32	0.6	0.4	0.2	4.6	<0.01	0.10	2	<0.005
SI 481328	Soil	472	64.1	3.2	<0.01	0.02	0.37	1.3	0.6	0.2	17.3	<0.01	0.19	4	0.007
SI 481329	Soil	586	29.7	4.8	<0.01	0.03	1.43	0.3	0.5	0.4	4.9	<0.01	0.14	0	0.009
SI 481330	Soil	717	11.4	1.8	<0.01	0.04	0.65	<0.1	<0.2	<0.2	7.2	<0.01	0.04	<0.2	<0.005
SI 481331	Soil	844	56.5	3.8	<0.01	0.04	3.14	0.2	0.4	<0.2	5.2	<0.01	0.15	0	<0.005
SI 481332	Soil	515	177.0	5.3	<0.01	0.03	0.28	0.6	0.7	0.4	9.0	<0.01	0.07	1	0.008
SI 481333	Soil	711	743.3	4.8	<0.01	0.06	2.46	0.2	0.4	0.5	22.9	<0.01	0.11	<0.2	<0.005
SI 481334	Soil	623	54.1	3.3	<0.01	0.03	<0.05	0.5	<0.2	<0.2	5.2	<0.01	0.09	1	<0.005
SI 481335	Soil	486	45.5	2.7	<0.01	0.02	<0.05	0.7	0.4	<0.2	3.8	<0.01	0.04	1	<0.005
SI 481336	Soil	483	33.6	4.0	<0.01	0.02	<0.05	0.7	0.4	<0.2	5.6	<0.01	0.06	1	<0.005
SI 481337	Soil	379	19.4	2.5	<0.01	0.02	<0.05	0.4	0.4	0.2	4.2	<0.01	0.04	1	0.006
SI 481338	Soil	538	24.3	3.8	<0.01	0.03	<0.05	0.3	0.4	0.3	5.0	<0.01	0.08	0	0.006
SI 481339	Soil	530	26.7	4.0	<0.01	0.02	<0.05	0.4	<0.2	<0.2	4.7	<0.01	0.13	0	<0.005
SI 481340	Soil	464	18.3	1.8	<0.01	0.03	<0.05	0.3	<0.2	<0.2	2.9	<0.01	0.02	0	<0.005
SI 481341	Soil	448	29.3	3.0	<0.01	0.01	<0.05	1.3	0.2	<0.2	3.1	<0.01	0.13	2	<0.005
SI 481342	Soil	1034	51.9	3.7	<0.01	0.04	<0.05	0.8	<0.2	<0.2	4.6	<0.01	0.11	1	<0.005
SI 481343	Soil	472	44.6	4.2	<0.01	0.01	<0.05	0.8	0.5	<0.2	3.7	<0.01	0.08	2	<0.005
SI 481344	Soil	418	35.0	2.1	<0.01	0.01	<0.05	1.7	<0.2	<0.2	4.4	<0.01	0.08	3	<0.005
SI 481345	Soil	448	348.0	3.4	<0.01	0.02	0.53	0.9	0.4	<0.2	8.6	<0.01	0.07	3	<0.005
SI 481346	Soil	605	71.1	5.4	<0.01	0.03	0.27	0.4	0.2	0.3	5.5	<0.01	0.05	0	<0.005
SI 481347	Soil	561	36.4	4.1	<0.01	0.02	<0.05	0.4	<0.2	0.2	4.8	<0.01	0.05	1	<0.005
SI 481348	Soil	1437	53.6	2.7	<0.01	0.03	0.55	0.2	0.3	<0.2	12.7	<0.01	0.07	0	<0.005
SI 481349	Soil	644	41.7	5.4	<0.01	0.03	<0.05	0.6	0.4	0.3	8.6	<0.01	0.08	1	0.006
SI 481350	Soil	919	17.7	3.8	<0.01	0.05	<0.05	0.4	0.3	0.3	4.3	<0.01	0.04	0	0.006
SI 481351	Soil	455	27.6	2.6	<0.01	0.01	<0.05	1.3	<0.2	<0.2	4.1	<0.01	0.08	2	<0.005
SI 481352	Soil	805	34.0	3.7	<0.01	0.03	<0.05	1.1	<0.2	<0.2	4.4	<0.01	0.06	1	<0.005
SI 481353	Soil	613	8.0	2.3	<0.01	0.02	<0.05	1.2	0.3	<0.2	3.5	<0.01	0.05	1	<0.005
SI 481354	Soil	580	12.7	2.2	<0.01	0.02	<0.05	0.6	<0.2	<0.2	3.7	<0.01	0.05	1	<0.005
SI 481355	Soil	920	20.7	5.7	<0.01	0.05	<0.05	0.3	0.4	0.3	5.2	<0.01	0.03	<0.2	<0.005
SI 481356	Soil	1413	36.2	5.2	<0.01	0.15	0.32	0.3	0.6	0.3	7.4	<0.01	0.03	<0.2	<0.005
SI 481357	Soil	998	26.1	6.2	<0.01	0.08	0.12	0.4	0.6	0.4	6.9	<0.01	0.04	0	0.007
SI 481358	Soil	828	30.2	6.0	<0.01	0.04	<0.05	0.6	0.6	0.4	6.7	<0.01	0.09	0	0.011
SI 481359	Soil	838	50.0	3.6	<0.01	0.04	0.83	0.9	0.4	<0.2	13.2	<0.01	0.10	1	0.006
SI 481360	Soil	592	63.8	3.6	<0.01	0.03	0.31	1.2	0.3	<0.2	7.6	<0.01	0.10	2	<0.005
SI 481361	Soil	673	54.2	4.0	<0.01	0.05	0.12	0.9	0.2	<0.2	7.5	<0.01	0.07	1	<0.005
SI 481362	Soil	910	20.1	4.1	<0.01	0.05	<0.05	0.4	0.3	0.4	5.5	0.01	0.05	0	0.006
SI 481363	Soil	741	26.7	2.5	<0.01	0.01	<0.05	1.5	<0.2	<0.2	5.5	<0.01	0.03	4	<0.005
SI 481364	Soil	659	38.5	2.3	<0.01	0.01	<0.05	1.4	<0.2	<0.2	6.0	<0.01	0.07	3	<0.005
SI 481365	Soil	778	34.8	2.1	<0.01	0.02	<0.05	1.4	<0.2	<0.2	6.0	<0.01	0.12	2	<0.005
SI 481366	Soil	1275	16.8	3.8	<0.01	0.10	0.12	0.3	0.4	<0.2	4.1	<0.01	0.08	<0.2	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481367	Soil	754	29.9	4.6	<0.01	0.02	<0.05	1.4	0.4	0.3	4.1	<0.01	0.06	3	0.013
SI 481368	Soil	532	27.4	3.7	<0.01	0.01	<0.05	1.4	<0.2	0.2	5.3	<0.01	0.07	4	<0.005
SI 481369	Soil	480	36.6	3.4	<0.01	0.01	<0.05	1.6	<0.2	0.2	4.1	<0.01	0.06	3	<0.005
SI 481371	Soil	765	18.5	2.2	<0.01	0.04	<0.05	0.4	<0.2	<0.2	4.5	<0.01	0.04	1	<0.005
SI 481372	Soil	628	14.0	2.1	<0.01	0.03	<0.05	0.5	<0.2	<0.2	4.8	<0.01	0.07	0	0.007
SI 481373	Soil	639	30.0	3.3	<0.01	0.01	<0.05	1.7	<0.2	<0.2	5.2	<0.01	0.10	3	<0.005
SI 481374	Soil	597	38.0	2.6	<0.01	0.02	1.07	2.8	<0.2	0.2	14.3	<0.01	0.10	5	<0.005
SI 481375	Soil	392	29.8	4.6	<0.01	0.01	<0.05	0.4	0.3	0.2	4.4	<0.01	0.07	1	<0.005
SI 481376	Soil	369	49.7	2.9	<0.01	<0.01	<0.05	1.3	0.4	<0.2	6.0	<0.01	0.14	10	<0.005
SI 481377	Soil	343	10.4	1.6	<0.01	0.02	0.14	0.1	<0.2	<0.2	4.1	<0.01	0.02	<0.2	<0.005
SI 481378	Soil	385	44.3	2.2	<0.01	<0.01	<0.05	1.2	0.2	<0.2	43.9	<0.01	0.12	5	<0.005
SI 481379	Soil	502	39.6	5.3	<0.01	0.01	<0.05	1.2	0.3	0.2	8.6	<0.01	0.08	9	<0.005
SI 481380	Soil	715	28.9	6.9	<0.01	0.01	<0.05	1.1	<0.2	0.3	5.1	<0.01	0.07	4	0.013
SI 481381	Soil	572	30.1	4.8	<0.01	0.01	<0.05	0.9	<0.2	<0.2	7.8	<0.01	0.13	2	0.005
SI 481382	Soil	409	30.2	2.6	<0.01	0.01	<0.05	1.4	0.4	<0.2	13.4	<0.01	0.10	7	<0.005
SI 481383	Soil	1063	15.9	3.3	<0.01	0.06	0.07	0.2	0.4	<0.2	11.0	<0.01	0.08	<0.2	<0.005
SI 481384	Soil	725	51.5	5.7	<0.01	0.03	0.84	1.0	0.4	<0.2	34.4	<0.01	0.18	1	<0.005
SI 481385	Soil	759	35.1	4.7	<0.01	0.03	<0.05	0.4	<0.2	<0.2	11.0	<0.01	0.04	1	<0.005
SI 481386	Soil	594	49.0	5.4	<0.01	0.04	<0.05	1.1	0.5	<0.2	28.4	<0.01	0.05	3	<0.005
SI 481387	Soil	703	116.2	3.5	<0.01	0.05	0.17	0.6	0.3	<0.2	43.1	<0.01	0.03	1	<0.005
SI 481388	Soil	232	24.6	2.1	<0.01	<0.01	<0.05	1.2	<0.2	<0.2	8.8	<0.01	0.11	3	<0.005
SI 481389	Soil	398	29.2	2.2	<0.01	0.02	<0.05	1.4	<0.2	<0.2	9.0	<0.01	0.11	3	<0.005
SI 481390	Soil	317	25.8	2.1	<0.01	<0.01	<0.05	1.9	<0.2	<0.2	5.9	<0.01	0.13	7	<0.005
SI 481391	Soil	738	39.8	3.7	<0.01	0.02	<0.05	0.9	<0.2	<0.2	7.8	<0.01	0.14	1	<0.005
SI 481392	Soil	508	24.8	4.0	<0.01	0.03	<0.05	0.8	<0.2	0.2	16.1	<0.01	0.09	1	0.006
SI 481393	Soil	473	39.3	10.3	<0.01	0.01	<0.05	0.8	<0.2	0.3	13.5	<0.01	0.07	1	0.007
SI 481394	Soil	186	46.2	3.8	<0.01	<0.01	<0.05	0.9	<0.2	0.3	2.8	<0.01	0.08	6	<0.005
SI 481395	Soil	339	148.3	5.6	<0.01	0.01	<0.05	0.7	<0.2	<0.2	8.6	<0.01	0.05	1	<0.005
SI 481396	Soil	441	40.4	2.8	<0.01	0.02	0.08	1.3	0.3	<0.2	9.8	<0.01	0.09	3	<0.005
SI 481397	Soil	230	27.1	3.1	<0.01	<0.01	<0.05	1.3	0.4	<0.2	7.3	<0.01	0.08	5	<0.005
SI 481398	Soil	258	18.4	4.4	<0.01	<0.01	<0.05	1.0	<0.2	0.2	6.1	<0.01	0.04	4	<0.005
SI 481399	Soil	415	28.2	3.3	<0.01	<0.01	<0.05	1.3	<0.2	<0.2	7.1	<0.01	0.07	4	<0.005
SI 481400	Soil	299	18.7	3.6	<0.01	0.01	<0.05	0.5	<0.2	<0.2	4.4	<0.01	0.03	1	<0.005
SI 481401	Soil	213	26.2	3.7	<0.01	<0.01	<0.05	1.2	0.2	<0.2	3.0	<0.01	0.06	6	<0.005
SI 481402	Soil	214	23.7	3.6	<0.01	<0.01	<0.05	1.1	<0.2	<0.2	2.7	<0.01	0.05	5	<0.005
SI 481403	Soil	275	25.6	3.3	<0.01	<0.01	<0.05	1.3	<0.2	<0.2	5.3	<0.01	0.08	5	<0.005
SI 481404	Soil	223	24.8	3.1	<0.01	<0.01	<0.05	1.2	<0.2	<0.2	4.6	<0.01	0.11	5	<0.005
SI 481405	Soil	301	21.6	3.4	<0.01	<0.01	<0.05	0.9	0.3	<0.2	4.1	<0.01	0.07	4	<0.005
SI 481406	Soil	377	27.4	3.3	<0.01	<0.01	<0.05	0.9	<0.2	<0.2	4.0	<0.01	0.05	3	<0.005
SI 481407	Soil	408	33.9	2.6	<0.01	0.01	<0.05	1.4	<0.2	<0.2	6.8	<0.01	0.10	3	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481408	Soil	566	29.6	1.8	<0.01	<0.01	<0.05	1.0	0.3	<0.2	6.4	<0.01	0.09	2	<0.005
SI 481409	Soil	488	24.1	3.1	<0.01	0.01	<0.05	0.7	<0.2	<0.2	5.0	<0.01	0.08	1	<0.005
SI 481410	Soil	637	21.5	4.6	<0.01	0.02	<0.05	0.4	<0.2	0.4	7.0	<0.01	0.08	0	0.007
SI 481411	Soil	629	18.6	5.4	<0.01	0.02	<0.05	0.4	<0.2	<0.2	17.8	<0.01	0.10	0	<0.005
SI 481412	Soil	1916	74.2	2.9	<0.01	0.02	2.11	1.8	0.5	<0.2	14.7	<0.01	0.16	3	<0.005
SI 481413	Soil	699	59.5	4.3	<0.01	0.04	0.13	1.2	0.6	<0.2	17.5	<0.01	0.20	2	<0.005
SI 481414	Soil	560	82.1	5.9	<0.01	0.03	0.80	0.2	<0.2	<0.2	18.1	<0.01	0.13	0	<0.005
SI 481415	Soil	657	31.8	4.7	<0.01	0.03	<0.05	0.5	<0.2	<0.2	19.3	<0.01	0.04	1	<0.005
SI 481416	Soil	165	38.3	2.0	<0.01	0.01	<0.05	1.3	0.3	<0.2	8.3	<0.01	0.31	5	<0.005
SI 481417	Soil	339	50.4	2.4	<0.01	0.01	<0.05	1.0	0.3	<0.2	14.7	<0.01	0.07	4	<0.005
SI 481418	Soil	280	21.1	2.1	<0.01	<0.01	<0.05	1.1	<0.2	<0.2	12.4	<0.01	0.08	6	<0.005
SI 481419	Soil	540	83.3	4.3	<0.01	0.03	0.09	0.9	<0.2	<0.2	35.1	<0.01	0.09	2	<0.005
SI 481420	Soil	450	57.7	1.9	<0.01	<0.01	<0.05	1.7	<0.2	<0.2	14.1	<0.01	0.17	9	<0.005
SI 481421	Soil	675	73.2	4.0	<0.01	0.04	0.14	1.3	0.9	<0.2	29.2	<0.01	0.08	5	<0.005
SI 481422	Soil	436	41.8	3.6	<0.01	0.03	0.10	0.3	<0.2	<0.2	11.0	<0.01	0.03	<0.2	<0.005
SI 481423	Soil	718	54.4	2.5	<0.01	0.02	0.55	0.6	0.4	<0.2	8.3	<0.01	0.08	1	<0.005
SI 481424	Soil	600	46.9	1.6	<0.01	<0.01	0.31	2.2	<0.2	<0.2	15.5	<0.01	0.16	10	<0.005
SI 481425	Soil	515	40.0	1.5	<0.01	<0.01	<0.05	2.6	<0.2	<0.2	10.3	<0.01	0.13	11	<0.005
SI 481426	Soil	378	15.1	1.6	<0.01	<0.01	0.19	1.8	<0.2	<0.2	6.8	<0.01	0.07	9	<0.005
SI 481427	Soil	488	42.7	4.1	<0.01	0.03	1.42	1.6	0.4	0.3	18.2	<0.01	0.19	3	0.009
SI 481428	Soil	612	85.1	3.3	<0.01	0.03	0.25	1.7	0.4	<0.2	35.2	<0.01	0.15	7	<0.005
SI 481429	Soil	637	49.5	4.4	<0.01	0.05	2.36	1.1	0.3	0.3	28.2	<0.01	0.16	1	0.019
SI 481430	Soil	948	44.5	3.7	<0.01	0.03	1.71	4.0	0.4	0.5	42.7	<0.01	0.08	4	0.012
SI 481431	Soil	359	28.9	2.2	<0.01	<0.01	0.39	2.9	<0.2	<0.2	9.9	<0.01	0.14	6	<0.005
SI 481432	Soil	346	18.6	2.4	<0.01	<0.01	0.15	1.9	<0.2	<0.2	8.4	<0.01	0.09	3	<0.005
SI 481433	Soil	310	24.6	1.8	<0.01	<0.01	1.65	1.9	<0.2	<0.2	11.4	<0.01	0.06	3	<0.005
SI 481434	Soil	721	52.4	3.0	<0.01	0.02	0.57	1.7	<0.2	<0.2	8.3	<0.01	0.09	2	0.007
SI 481435	Soil	710	34.5	2.6	<0.01	0.03	0.67	0.9	0.3	0.2	4.6	0.02	0.04	1	0.005
SI 481436	Soil	730	36.8	3.1	<0.01	0.04	1.11	0.2	0.2	<0.2	5.0	0.02	0.02	<0.2	<0.005
SI 481437	Soil	829	74.1	3.1	<0.01	0.06	1.32	0.8	0.3	<0.2	11.0	0.01	0.05	1	<0.005
SI 481438	Soil	721	60.4	4.1	<0.01	0.03	1.38	1.3	0.4	<0.2	11.5	0.01	0.08	1	0.005
SI 481439	Soil	942	23.3	3.8	<0.01	0.08	0.30	0.3	0.4	0.2	5.2	0.01	<0.01	<0.2	<0.005
SI 481440	Soil	701	48.2	2.4	<0.01	0.06	1.25	1.0	0.3	0.3	20.2	<0.01	0.05	2	<0.005
SI 481441	Soil	971	24.6	4.2	<0.01	0.07	<0.05	0.6	0.3	<0.2	5.2	0.01	0.02	1	<0.005
SI 481442	Soil	765	28.9	3.9	<0.01	0.05	0.18	0.5	0.4	0.3	7.3	0.01	0.02	0	0.005
SI 481443	Soil	702	46.8	3.8	<0.01	0.04	0.20	0.9	<0.2	<0.2	5.0	<0.01	0.04	1	<0.005
SI 481444	Soil	826	11.9	3.2	<0.01	0.06	<0.05	0.6	0.3	<0.2	2.9	0.02	0.01	1	0.006
SI 481445	Soil	928	28.2	3.3	<0.01	0.05	<0.05	0.9	0.5	<0.2	3.8	0.01	0.02	1	0.007
SI 481446	Soil	561	31.4	2.8	<0.01	0.03	0.13	1.0	0.4	<0.2	4.7	<0.01	0.05	1	<0.005
SI 481447	Soil	522	22.8	3.4	<0.01	0.03	1.02	0.8	<0.2	<0.2	11.2	<0.01	0.02	1	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481448	Soil	601	20.3	2.6	<0.01	0.02	0.59	0.6	<0.2	<0.2	7.1	<0.01	0.03	0	<0.005
SI 481449	Soil	573	22.5	3.6	<0.01	0.03	0.20	0.8	<0.2	<0.2	6.4	<0.01	0.05	1	<0.005
SI 481450	Soil	877	37.8	3.3	<0.01	0.04	<0.05	0.9	0.3	<0.2	4.9	<0.01	0.03	1	<0.005
SI 481451	Soil	583	20.2	3.1	<0.01	0.02	<0.05	1.0	<0.2	<0.2	4.2	<0.01	0.02	1	0.007
SI 481452	Soil	456	81.9	2.0	<0.01	<0.01	0.26	2.4	<0.2	<0.2	4.8	<0.01	0.05	4	<0.005
SI 481453	Soil	712	21.0	3.0	<0.01	0.04	<0.05	0.8	<0.2	<0.2	3.1	<0.01	0.01	1	0.005
SI 481454	Soil	1370	23.4	4.5	<0.01	0.09	<0.05	0.4	0.2	0.3	4.1	<0.01	0.02	0	<0.005
TI 480140	Soil	608	58.5	4.3	<0.01	0.05	0.40	1.3	0.5	<0.2	17.3	<0.01	0.05	2	<0.005
TI 480141	Soil	572	33.8	2.9	<0.01	0.08	1.02	3.9	1.6	<0.2	33.8	<0.01	0.07	5	<0.005
TI 480195	Soil	520	22.4	3.0	<0.01	0.04	0.27	0.4	1.1	<0.2	16.7	<0.01	<0.01	1	<0.005
TI 480196	Soil	480	22.8	3.8	<0.01	0.05	<0.05	1.6	0.8	<0.2	27.2	<0.01	0.03	3	<0.005
TI 480197	Soil	392	40.0	3.3	<0.01	0.02	0.18	1.0	0.6	<0.2	19.4	<0.01	0.14	4	<0.005
TI 480198	Soil	668	22.7	2.9	<0.01	0.04	<0.05	1.5	1.0	<0.2	31.7	<0.01	0.06	3	<0.005
TI 480199	Soil	725	32.5	4.1	<0.01	0.05	<0.05	1.3	0.7	<0.2	33.3	<0.01	0.02	2	<0.005
TI 480200	Soil	1070	52.3	5.4	<0.01	0.08	0.42	0.5	0.6	<0.2	23.3	<0.01	0.03	1	<0.005
TI 481305	Soil	909	34.4	4.3	<0.01	0.07	0.35	1.1	1.3	<0.2	53.1	<0.01	<0.01	1	<0.005
TI 481306	Soil	648	20.0	2.2	<0.01	0.04	<0.05	1.1	1.1	<0.2	36.4	<0.01	<0.01	3	<0.005
TI 481307	Soil	669	14.8	2.9	<0.01	0.08	<0.05	0.9	1.3	<0.2	51.7	<0.01	<0.01	2	<0.005
TI 481308	Soil	671	25.7	3.2	<0.01	0.04	<0.05	1.1	0.8	<0.2	29.1	<0.01	0.01	3	<0.005
TI 481309	Soil	682	24.5	2.9	<0.01	0.04	<0.05	1.4	1.3	<0.2	39.8	<0.01	0.02	5	<0.005
TI 481310	Soil	621	24.9	2.1	<0.01	0.04	<0.05	1.6	0.5	<0.2	41.5	<0.01	0.03	6	<0.005
TI 481311	Soil	609	18.2	2.5	<0.01	0.05	<0.05	1.2	1.0	<0.2	33.1	<0.01	0.02	4	<0.005
TI 481312	Soil	526	19.6	2.8	<0.01	0.04	<0.05	1.5	0.6	<0.2	31.0	<0.01	<0.01	4	<0.005
TI 481313	Soil	575	18.1	2.1	<0.01	0.06	<0.05	1.0	1.8	<0.2	65.5	0.01	0.08	2	<0.005
TI 481314	Soil	528	20.5	2.2	<0.01	0.03	<0.05	1.2	0.4	<0.2	29.2	<0.01	<0.01	4	<0.005
TI 481315	Soil	618	22.8	2.9	<0.01	0.05	<0.05	1.4	0.9	<0.2	49.1	<0.01	<0.01	3	<0.005
TI 481316	Soil	543	21.1	2.6	<0.01	0.04	<0.05	1.6	0.6	<0.2	32.8	<0.01	<0.01	4	<0.005
TI 481317	Soil	599	23.0	2.3	<0.01	0.09	<0.05	1.4	0.9	<0.2	54.0	<0.01	0.04	4	<0.005
TI 481318	Soil	534	23.1	2.7	<0.01	0.04	<0.05	1.5	0.8	0.3	34.2	<0.01	<0.01	5	<0.005
TI 481319	Soil	567	22.7	2.4	<0.01	0.04	<0.05	1.3	0.6	<0.2	41.4	<0.01	<0.01	4	<0.005
TI 481320	Soil	568	15.4	1.7	<0.01	0.04	<0.05	1.2	0.7	<0.2	46.7	<0.01	<0.01	2	<0.005
TI 481321	Soil	506	18.1	2.2	<0.01	0.03	<0.05	1.5	0.4	<0.2	29.3	<0.01	0.02	5	<0.005
TI 481322	Soil	467	18.5	1.9	<0.01	0.03	<0.05	1.5	0.4	<0.2	32.2	<0.01	<0.01	4	<0.005
TI 481323	Soil	572	20.9	2.5	<0.01	0.04	0.27	1.6	0.8	<0.2	38.5	<0.01	<0.01	4	<0.005
TI 481324	Soil	504	19.8	2.5	<0.01	0.04	<0.05	1.5	0.6	<0.2	35.2	<0.01	<0.01	4	<0.005
TI 481325	Soil	523	16.3	2.1	<0.01	0.03	<0.05	1.3	0.5	<0.2	31.2	<0.01	<0.01	4	<0.005
TI 481326	Soil	494	20.4	2.3	<0.01	0.03	<0.05	1.6	0.7	<0.2	34.6	<0.01	0.01	4	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481327	Soil	<0.05	1	12	2.27	1.4	82	<0.5
SI 481328	Soil	<0.05	2	16	1.13	2.1	134	<0.5
SI 481329	Soil	<0.05	1	20	1.15	1.5	65	<0.5
SI 481330	Soil	<0.05	0	10	1.61	0.5	31	<0.5
SI 481331	Soil	<0.05	1	11	1.30	1.0	73	<0.5
SI 481332	Soil	<0.05	1	20	2.08	3.0	160	<0.5
SI 481333	Soil	<0.05	1	19	1.28	1.4	131	<0.5
SI 481334	Soil	<0.05	1	12	3.08	1.7	93	<0.5
SI 481335	Soil	<0.05	1	16	1.13	1.9	104	<0.5
SI 481336	Soil	<0.05	1	15	3.48	1.9	95	<0.5
SI 481337	Soil	<0.05	1	14	1.89	1.2	62	<0.5
SI 481338	Soil	<0.05	1	17	1.74	1.5	66	<0.5
SI 481339	Soil	<0.05	1	15	1.37	1.7	81	<0.5
SI 481340	Soil	<0.05	0	9	1.23	1.0	49	<0.5
SI 481341	Soil	<0.05	2	16	1.12	3.4	121	<0.5
SI 481342	Soil	<0.05	1	18	0.50	3.0	150	1.1
SI 481343	Soil	<0.05	1	12	1.21	1.8	107	<0.5
SI 481344	Soil	<0.05	1	16	1.01	2.3	137	<0.5
SI 481345	Soil	<0.05	2	13	1.33	1.9	178	<0.5
SI 481346	Soil	<0.05	1	17	1.82	1.6	115	<0.5
SI 481347	Soil	<0.05	1	15	1.61	1.5	83	<0.5
SI 481348	Soil	<0.05	1	10	1.51	3.7	108	<0.5
SI 481349	Soil	<0.05	1	18	1.91	3.3	92	<0.5
SI 481350	Soil	<0.05	1	23	0.52	1.7	80	<0.5
SI 481351	Soil	<0.05	1	21	0.97	2.1	114	<0.5
SI 481352	Soil	<0.05	1	21	0.95	1.7	103	<0.5
SI 481353	Soil	<0.05	1	18	1.41	2.0	94	<0.5
SI 481354	Soil	<0.05	1	15	1.64	2.0	89	<0.5
SI 481355	Soil	<0.05	1	22	1.31	1.6	73	<0.5
SI 481356	Soil	0.06	1	19	0.77	2.2	64	<0.5
SI 481357	Soil	<0.05	1	23	1.13	3.0	66	<0.5
SI 481358	Soil	<0.05	1	26	1.16	2.3	95	<0.5
SI 481359	Soil	<0.05	1	17	0.89	3.1	120	0.6
SI 481360	Soil	<0.05	1	18	0.76	2.6	111	1.0
SI 481361	Soil	<0.05	1	19	1.91	1.6	112	<0.5
SI 481362	Soil	<0.05	1	25	1.72	1.7	81	<0.5
SI 481363	Soil	<0.05	1	23	0.39	2.4	131	0.7
SI 481364	Soil	<0.05	1	21	2.19	2.2	124	<0.5
SI 481365	Soil	<0.05	1	23	1.01	1.9	131	<0.5
SI 481366	Soil	<0.05	1	17	1.28	1.1	42	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481367	Soil	<0.05	1	30	1.40	1.8	89	0.6
SI 481368	Soil	<0.05	1	23	1.45	1.6	95	<0.5
SI 481369	Soil	<0.05	1	21	1.61	2.2	103	0.5
SI 481371	Soil	<0.05	1	17	0.74	1.2	74	0.7
SI 481372	Soil	<0.05	1	16	0.98	2.2	60	<0.5
SI 481373	Soil	<0.05	1	20	1.68	2.2	100	<0.5
SI 481374	Soil	<0.05	2	16	1.56	5.1	120	0.8
SI 481375	Soil	<0.05	1	13	1.47	1.4	100	<0.5
SI 481376	Soil	<0.05	2	7	3.39	4.7	169	1.0
SI 481377	Soil	<0.05	0	8	1.37	0.5	28	<0.5
SI 481378	Soil	<0.05	2	9	0.46	2.4	91	<0.5
SI 481379	Soil	<0.05	1	15	1.81	1.4	94	1.4
SI 481380	Soil	<0.05	1	23	0.95	1.8	100	<0.5
SI 481381	Soil	<0.05	1	16	1.18	1.5	97	<0.5
SI 481382	Soil	<0.05	2	12	0.85	2.7	132	<0.5
SI 481383	Soil	<0.05	1	13	0.84	0.7	56	<0.5
SI 481384	Soil	<0.05	3	11	0.93	4.0	138	<0.5
SI 481385	Soil	<0.05	1	10	1.24	1.3	89	<0.5
SI 481386	Soil	<0.05	2	9	1.10	3.4	87	1.0
SI 481387	Soil	<0.05	2	7	1.03	2.7	74	1.3
SI 481388	Soil	<0.05	1	11	1.12	1.6	123	<0.5
SI 481389	Soil	<0.05	1	12	1.16	2.1	129	<0.5
SI 481390	Soil	<0.05	1	12	1.18	2.8	128	0.6
SI 481391	Soil	<0.05	2	14	0.91	3.3	93	<0.5
SI 481392	Soil	<0.05	2	14	0.83	4.2	59	<0.5
SI 481393	Soil	<0.05	2	20	1.27	2.7	110	<0.5
SI 481394	Soil	<0.05	1	15	1.26	1.4	64	0.7
SI 481395	Soil	<0.05	1	12	1.06	1.8	131	<0.5
SI 481396	Soil	<0.05	2	11	1.41	3.0	100	<0.5
SI 481397	Soil	<0.05	1	10	1.34	2.0	79	<0.5
SI 481398	Soil	<0.05	1	14	2.65	1.4	62	<0.5
SI 481399	Soil	<0.05	1	11	3.59	3.0	84	<0.5
SI 481400	Soil	<0.05	1	13	1.26	1.2	55	<0.5
SI 481401	Soil	<0.05	1	12	1.33	1.7	77	0.5
SI 481402	Soil	<0.05	1	11	1.86	1.7	70	<0.5
SI 481403	Soil	<0.05	1	11	1.17	3.2	75	<0.5
SI 481404	Soil	<0.05	1	11	2.01	1.8	74	<0.5
SI 481405	Soil	<0.05	1	13	2.64	1.4	64	<0.5
SI 481406	Soil	<0.05	1	11	2.43	1.4	74	<0.5
SI 481407	Soil	<0.05	2	11	2.04	2.4	102	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481408	Soil	<0.05	2	11	3.35	2.7	124	<0.5
SI 481409	Soil	<0.05	1	12	2.38	1.5	101	<0.5
SI 481410	Soil	<0.05	1	26	1.32	1.7	70	<0.5
SI 481411	Soil	<0.05	1	18	1.58	1.9	89	<0.5
SI 481412	Soil	<0.05	1	11	1.09	6.6	131	<0.5
SI 481413	Soil	<0.05	3	9	2.03	4.1	83	0.5
SI 481414	Soil	<0.05	1	8	2.87	1.3	85	<0.5
SI 481415	Soil	<0.05	2	8	1.84	3.0	49	<0.5
SI 481416	Soil	<0.05	2	10	2.34	1.9	147	0.5
SI 481417	Soil	<0.05	1	7	2.39	2.6	82	<0.5
SI 481418	Soil	<0.05	2	9	0.64	3.8	76	0.8
SI 481419	Soil	<0.05	2	8	2.02	3.9	76	<0.5
SI 481420	Soil	<0.05	2	14	4.09	2.6	135	1.4
SI 481421	Soil	<0.05	2	9	2.38	2.8	157	0.8
SI 481422	Soil	<0.05	1	7	1.90	0.8	50	<0.5
SI 481423	Soil	<0.05	2	12	1.34	1.6	90	<0.5
SI 481424	Soil	<0.05	3	19	1.83	3.1	157	1.1
SI 481425	Soil	<0.05	3	20	0.99	3.3	159	4.1
SI 481426	Soil	<0.05	1	2	4.26	3.7	74	0.9
SI 481427	Soil	<0.05	2	20	3.06	3.4	109	<0.5
SI 481428	Soil	<0.05	2	12	1.10	3.7	190	<0.5
SI 481429	Soil	<0.05	2	22	2.27	2.4	119	1.0
SI 481430	Soil	<0.05	2	40	1.11	6.2	104	2.2
SI 481431	Soil	<0.05	1	15	2.82	5.9	105	<0.5
SI 481432	Soil	<0.05	1	11	2.31	4.1	88	<0.5
SI 481433	Soil	<0.05	1	9	1.28	3.9	96	<0.5
SI 481434	Soil	<0.05	2	18	1.56	2.4	102	0.5
SI 481435	Soil	<0.05	1	18	1.08	1.8	110	0.7
SI 481436	Soil	<0.05	1	16	1.52	1.4	62	<0.5
SI 481437	Soil	<0.05	1	16	2.25	2.1	124	0.7
SI 481438	Soil	<0.05	1	18	2.52	3.8	128	<0.5
SI 481439	Soil	<0.05	1	18	2.46	1.4	51	<0.5
SI 481440	Soil	<0.05	1	12	2.64	3.0	89	<0.5
SI 481441	Soil	<0.05	1	18	2.75	1.8	60	1.0
SI 481442	Soil	<0.05	1	19	2.10	2.0	70	<0.5
SI 481443	Soil	<0.05	1	19	2.86	2.0	94	0.8
SI 481444	Soil	<0.05	1	15	1.43	1.1	68	1.4
SI 481445	Soil	<0.05	1	19	1.74	1.4	101	0.8
SI 481446	Soil	<0.05	1	20	1.94	1.8	93	0.7
SI 481447	Soil	<0.05	1	6	2.33	1.2	95	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481448	Soil	<0.05	1	9	3.25	1.4	71	<0.5
SI 481449	Soil	<0.05	1	16	2.09	1.5	87	<0.5
SI 481450	Soil	<0.05	1	21	0.89	1.6	86	1.1
SI 481451	Soil	<0.05	1	20	2.26	1.7	93	<0.5
SI 481452	Soil	<0.05	1	21	2.33	2.7	144	<0.5
SI 481453	Soil	<0.05	1	19	1.94	1.5	96	0.9
SI 481454	Soil	<0.05	1	20	3.05	1.4	65	<0.5
TI 480140	Soil	<0.05	5	11	1.31	3.5	157	0.6
TI 480141	Soil	0.06	3	10	3.29	11.7	63	5.7
TI 480195	Soil	<0.05	2	6	3.03	4.0	70	<0.5
TI 480196	Soil	<0.05	1	10	2.23	4.3	105	0.7
TI 480197	Soil	<0.05	2	9	2.48	2.7	106	<0.5
TI 480198	Soil	<0.05	2	13	1.90	6.1	92	0.8
TI 480199	Soil	<0.05	2	12	3.31	4.2	113	0.7
TI 480200	Soil	<0.05	3	8	6.67	5.2	128	0.9
TI 481305	Soil	<0.05	11	11	2.08	7.6	95	0.9
TI 481306	Soil	<0.05	16	13	0.92	4.8	83	<0.5
TI 481307	Soil	<0.05	22	9	1.73	5.2	88	0.6
TI 481308	Soil	<0.05	5	15	1.46	4.9	87	0.5
TI 481309	Soil	<0.05	16	14	2.80	9.1	89	0.5
TI 481310	Soil	<0.05	2	10	2.12	6.8	82	<0.5
TI 481311	Soil	<0.05	13	13	2.32	5.7	82	<0.5
TI 481312	Soil	<0.05	2	12	2.57	6.2	76	<0.5
TI 481313	Soil	<0.05	4	9	2.08	7.0	78	0.9
TI 481314	Soil	<0.05	2	9	0.88	6.0	76	<0.5
TI 481315	Soil	<0.05	2	10	0.88	6.8	73	0.9
TI 481316	Soil	<0.05	3	11	0.34	6.9	75	<0.5
TI 481317	Soil	<0.05	3	10	0.76	6.2	81	1.4
TI 481318	Soil	<0.05	2	11	0.72	6.4	75	1.0
TI 481319	Soil	<0.05	4	11	1.22	7.5	81	0.8
TI 481320	Soil	<0.05	4	13	0.91	3.4	92	1.0
TI 481321	Soil	<0.05	2	13	0.87	5.1	82	0.5
TI 481322	Soil	<0.05	1	11	0.75	5.3	77	0.6
TI 481323	Soil	<0.05	2	11	1.16	6.3	81	0.6
TI 481324	Soil	<0.05	2	11	0.71	5.5	79	0.6
TI 481325	Soil	<0.05	1	11	0.77	4.7	79	0.6
TI 481326	Soil	<0.05	2	12	1.31	5.6	82	0.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481327	Soil	0.084													
SI 481327 Dup		0.088													
SI 481345	Soil	0.064													
SI 481345 Dup		0.058													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.766													
QCV1008-00086-0004-BLK		<0.005													
SI 481363	Soil	0.005													
SI 481363 Dup		0.006													
SI 481382	Soil	0.107													
SI 481382 Dup		0.091													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.881													
QCV1008-00086-0008-BLK		<0.005													
SI 481400	Soil	0.010													
SI 481400 Dup		0.007													
SI 481418	Soil	0.023													
SI 481418 Dup		0.024													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.823													
QCV1008-00086-0012-BLK		<0.005													
SI 481436	Soil	0.060													
SI 481436 Dup		0.059													
SI 481454	Soil	<0.005													
SI 481454 Dup		0.014													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.790													
QCV1008-00086-0016-BLK		<0.005													
TI 481314	Soil	<0.005													
TI 481314 Dup		<0.005													
QCV1008-00087-0001-BLK			<0.01	<0.01	0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
SI 481327	Soil		0.30	0.97	250.9	28	0.2	0.45	<0.01	0.11	15.22	8.6	10	0.7	26.7
SI 481327 Dup			0.30	0.98	248.1	28	0.2	0.45	<0.01	0.11	15.78	8.6	11	0.7	28.2
STD-ME-6 expected			101												6130.0
STD-ME-6 result			>100	1.17	290.1	68	0.2	6.02	0.59	32.87	8.45	<0.1	30	0.3	6649.3
SI 481345	Soil		0.80	1.38	498.7	17	0.3	0.37	0.12	0.99	17.50	13.6	19	1.3	29.1
SI 481345 Dup			0.81	1.38	502.1	17	0.3	0.37	0.12	0.96	17.29	14.1	19	1.3	29.3
STD-ME-6 expected			101.00												6130.0
STD-ME-6 result			99.04	1.16	282.2	75	0.2	5.77	0.58	31.84	8.68	<0.1	27	0.3	6427.6
SI 481363	Soil		0.29	2.96	31.4	18	0.3	0.35	0.06	0.08	47.76	14.4	43	1.1	37.7
SI 481363 Dup			0.33	2.96	30.1	18	0.3	0.35	0.06	0.08	47.38	14.2	43	1.1	38.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
STD-ME-6 expected			101.00												6130.0
STD-ME-6 result			98.52	1.16	286.7	82	0.2	6.23	0.60	33.50	9.06	<0.1	28	0.3	6477.3
SI 481382	Soil		0.27	1.35	274.3	27	0.6	0.48	0.01	0.11	39.87	28.2	19	1.8	50.8
SI 481382 Dup			0.38	1.35	268.0	27	0.5	0.47	0.01	0.10	38.37	28.4	19	1.8	49.7
STD-ME-6 expected			101.00												6130.0
STD-ME-6 result			99.56	1.14	293.1	78	0.2	6.10	0.58	33.77	9.03	<0.1	31	0.3	6392.9
SI 481400	Soil		0.51	0.90	68.7	36	0.3	0.23	0.03	0.13	20.01	6.5	10	0.5	12.6
SI 481400 Dup			0.39	0.90	69.3	38	0.3	0.23	0.03	0.13	20.46	6.6	10	0.5	13.3
STD-ME-6 expected			101												6130.0
STD-ME-6 result			>100	1.15	289.7	70	0.2	6.23	0.58	34.43	8.82	<0.1	29	0.3	6443.6
SI 481418	Soil		0.52	0.68	108.7	23	0.2	0.34	0.11	0.05	23.55	12.1	14	0.7	29.7
SI 481418 Dup			0.46	0.68	109.0	23	0.2	0.35	0.11	0.05	24.02	12.1	14	0.7	29.9
STD-ME-6 expected			101												6130.0
STD-ME-6 result			>100	1.17	276.3	72	0.2	6.04	0.60	34.19	8.92	<0.1	29	0.3	6531.6
SI 481436	Soil		0.60	0.73	288.7	29	0.1	0.27	<0.01	0.10	19.24	7.3	10	0.9	22.2
SI 481436 Dup			0.44	0.73	281.5	29	0.1	0.26	<0.01	0.10	18.96	7.2	10	0.9	21.2
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.32	3.11	7.5	204	0.7	0.19	0.23	0.09	37.18	106.5	860	0.9	654.4
SI 481454	Soil		0.55	1.40	27.8	22	0.2	0.32	0.01	0.06	15.42	9.3	24	1.6	20.5
SI 481454 Dup			0.50	1.40	27.1	22	0.2	0.32	0.01	0.06	15.22	9.2	24	1.6	20.2
TI 481314	Soil		0.51	1.46	15.7	29	0.4	0.32	0.27	0.08	14.19	12.1	18	0.2	24.2
TI 481314 Dup			0.57	1.46	15.7	28	0.4	0.31	0.27	0.08	13.72	12.0	18	0.2	24.0
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.33	2.85	4.5	211	0.7	0.20	0.23	0.13	38.69	103.0	788	0.8	606.9
QCV1008-00087-0020-BLK			<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.32	3.02	5.0	197	0.7	0.18	0.24	0.10	36.16	107.2	842	0.8	630.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
QCV1008-00087-0001-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
SI 481327	Soil	3.80	3.4	<0.05	<0.02	0.03	0.02	8.3	13.0	0.18	240	0.53	<0.01	0.3	18.9
SI 481327 Dup		3.80	3.5	<0.05	<0.02	0.03	0.02	8.4	13.1	0.18	241	0.58	<0.01	0.3	18.8
STD-ME-6 expected															
STD-ME-6 result		6.12	3.8	<0.05	0.11	0.45	0.09	3.9	9.3	0.83	1758	20.78	0.06	0.1	28.3
SI 481345	Soil	4.00	4.1	<0.05	<0.02	0.20	0.02	9.1	43.2	0.56	398	0.46	<0.01	0.1	35.7
SI 481345 Dup		4.00	4.1	<0.05	<0.02	0.19	0.02	9.0	44.0	0.56	401	0.46	<0.01	0.1	36.2
STD-ME-6 expected															
STD-ME-6 result		5.83	4.1	<0.05	0.12	0.43	0.09	3.9	8.9	0.80	1731	20.62	0.06	0.1	29.1
SI 481363	Soil	5.90	8.3	<0.05	<0.02	0.02	0.02	24.5	86.3	1.28	580	0.37	<0.01	0.1	56.6
SI 481363 Dup		5.90	8.4	<0.05	<0.02	0.02	0.02	25.2	86.4	1.28	580	0.36	<0.01	0.1	55.4
STD-ME-6 expected															
STD-ME-6 result		5.71	4.1	<0.05	0.15	0.47	0.09	4.3	9.3	0.79	1752	20.77	0.06	0.1	29.7
SI 481382	Soil	6.00	3.6	<0.05	<0.02	0.02	0.03	23.3	35.1	0.48	779	0.46	<0.01	<0.05	51.1
SI 481382 Dup		6.00	3.6	<0.05	<0.02	0.02	0.02	23.5	35.3	0.48	780	0.45	<0.01	<0.05	49.3
STD-ME-6 expected															
STD-ME-6 result		5.85	4.0	<0.05	0.12	0.48	0.09	4.1	9.0	0.80	1752	22.72	0.06	0.1	29.4
SI 481400	Soil	2.60	3.5	<0.05	<0.02	0.01	0.03	10.4	17.8	0.21	240	0.37	<0.01	0.4	13.8
SI 481400 Dup		2.59	3.6	<0.05	<0.02	0.02	0.03	10.9	17.9	0.21	241	0.37	<0.01	0.4	14.1
STD-ME-6 expected															
STD-ME-6 result		5.66	4.1	<0.05	0.12	0.48	0.09	4.2	8.8	0.78	1775	22.51	0.06	0.1	29.2
SI 481418	Soil	2.90	1.9	<0.05	<0.02	0.02	0.02	13.8	16.8	0.25	330	0.34	<0.01	<0.05	27.8
SI 481418 Dup		2.90	1.9	<0.05	<0.02	0.02	0.02	14.0	17.7	0.25	329	0.36	<0.01	<0.05	28.5
STD-ME-6 expected															
STD-ME-6 result		5.94	4.3	<0.05	0.13	0.47	0.09	4.1	9.0	0.82	1748	22.28	0.06	0.1	29.8
SI 481436	Soil	2.40	4.0	<0.05	<0.02	0.02	0.02	10.0	7.2	0.11	528	0.56	0.01	0.2	12.3
SI 481436 Dup		2.40	3.8	<0.05	<0.02	0.02	0.02	9.7	7.2	0.11	528	0.55	0.01	0.2	12.2
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	17.6	0.1	0.59	0.10	0.07	17.3	6.2	0.12	1163	1.03	0.02	0.5	305.4
SI 481454	Soil	4.70	5.5	<0.05	<0.02	0.02	0.03	7.7	20.3	0.40	804	0.60	<0.01	0.3	17.1
SI 481454 Dup		4.71	5.2	<0.05	<0.02	0.02	0.03	7.7	20.3	0.40	798	0.60	<0.01	0.3	17.0
TI 481314	Soil	3.46	3.7	<0.05	<0.02	0.02	0.02	6.9	46.4	0.62	421	0.31	<0.01	0.1	28.0
TI 481314 Dup		3.46	3.5	<0.05	<0.02	0.02	0.02	6.7	46.1	0.62	420	0.32	<0.01	0.1	27.6
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	17.1	0.1	0.62	0.10	0.06	17.4	4.9	0.09	977	0.94	0.02	0.6	287.0
QCV1008-00087-0020-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	16.6	0.1	0.59	0.10	0.07	16.6	5.0	0.11	1242	0.88	0.02	0.5	274.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
QCV1008-00087-0001-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
SI 481327	Soil	489	71.2	4.2	<0.01	0.02	0.32	0.6	0.4	0.2	4.6	<0.01	0.10	2	<0.005
SI 481327 Dup		490	70.0	4.2	<0.01	0.02	0.34	0.6	0.4	0.2	4.5	<0.01	0.10	2	<0.005
STD-ME-6 expected			10200.0												
STD-ME-6 result		446	9971.5	3.3	0.01	2.72	381.19	3.8	2.1	1.6	27.8	<0.01	1.58	1	0.079
SI 481345	Soil	448	348.0	3.4	<0.01	0.02	0.53	0.9	0.4	<0.2	8.6	<0.01	0.07	3	<0.005
SI 481345 Dup		451	356.8	3.4	<0.01	0.02	0.52	1.0	0.4	<0.2	8.6	<0.01	0.06	3	<0.005
STD-ME-6 expected			10200.0												
STD-ME-6 result		456	9702.6	3.3	0.01	2.60	385.16	3.7	2.1	1.6	27.4	<0.01	1.53	1	0.082
SI 481363	Soil	741	26.7	2.5	<0.01	0.01	<0.05	1.5	<0.2	<0.2	5.5	<0.01	0.03	4	<0.005
SI 481363 Dup		739	27.8	2.4	<0.01	0.01	<0.05	1.5	<0.2	<0.2	5.7	<0.01	0.03	3	<0.005
STD-ME-6 expected			10200												
STD-ME-6 result		439	>10000	3.3	0.01	2.52	391.21	3.9	2.3	1.6	27.8	<0.01	1.62	1	0.082
SI 481382	Soil	409	30.2	2.6	<0.01	0.01	<0.05	1.4	0.4	<0.2	13.4	<0.01	0.10	7	<0.005
SI 481382 Dup		410	28.2	2.6	<0.01	0.01	<0.05	1.4	0.3	<0.2	13.5	<0.01	0.11	7	<0.005
STD-ME-6 expected			10200												
STD-ME-6 result		410	>10000	3.4	0.01	2.59	400.62	3.8	2.3	1.6	26.9	<0.01	1.62	1	0.079
SI 481400	Soil	299	18.7	3.6	<0.01	0.01	<0.05	0.5	<0.2	<0.2	4.4	<0.01	0.03	1	<0.005
SI 481400 Dup		301	19.7	3.7	<0.01	0.01	<0.05	0.5	<0.2	<0.2	4.5	<0.01	0.03	1	<0.005
STD-ME-6 expected			10200												
STD-ME-6 result		471	>10000	3.5	<0.01	2.54	411.47	4.1	2.4	1.7	27.0	<0.01	1.62	1	0.079
SI 481418	Soil	280	21.1	2.1	<0.01	<0.01	<0.05	1.1	<0.2	<0.2	12.4	<0.01	0.08	6	<0.005
SI 481418 Dup		280	22.2	2.2	<0.01	<0.01	<0.05	1.2	<0.2	<0.2	12.7	<0.01	0.08	6	<0.005
STD-ME-6 expected			10200.0												
STD-ME-6 result		445	9787.4	3.5	0.01	2.61	407.35	3.9	2.1	1.7	27.8	<0.01	1.56	1	0.082
SI 481436	Soil	730	36.8	3.1	<0.01	0.04	1.11	0.2	0.2	<0.2	5.0	0.02	0.02	<0.2	<0.005
SI 481436 Dup		729	36.6	2.9	<0.01	0.04	1.05	0.2	0.3	<0.2	5.2	0.01	0.01	<0.2	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		364	20.2	8.8	<0.01	0.03	<0.05	50.7	<0.2	1.8	14.7	<0.01	0.02	7	0.165
SI 481454	Soil	1370	23.4	4.5	<0.01	0.09	<0.05	0.4	0.2	0.3	4.1	<0.01	0.02	0	<0.005
SI 481454 Dup		1368	22.5	4.3	<0.01	0.09	<0.05	0.4	0.2	0.3	3.9	<0.01	0.02	0	<0.005
TI 481314	Soil	528	20.5	2.2	<0.01	0.03	<0.05	1.2	0.4	<0.2	29.2	<0.01	<0.01	4	<0.005
TI 481314 Dup		528	19.7	2.1	<0.01	0.03	<0.05	1.2	0.4	<0.2	28.7	<0.01	<0.01	4	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		355	21.2	8.3	<0.01	0.02	<0.05	48.7	<0.2	1.8	14.1	<0.01	0.06	7	0.140
QCV1008-00087-0020-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		377	20.0	8.3	<0.01	0.02	<0.05	46.7	<0.2	1.7	14.8	<0.01	0.02	6	0.152

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02438-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
QCV1008-00087-0001-BLK		<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
SI 481327	Soil	<0.05	1	12	2.27	1.4	82	<0.5
SI 481327 Dup		<0.05	1	12	2.30	1.4	82	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.21	1	41	3.15	5.9	5895	4.1
SI 481345	Soil	<0.05	2	13	1.33	1.9	178	<0.5
SI 481345 Dup		<0.05	2	13	1.33	2.0	179	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.21	1	41	2.30	6.0	5565	4.6
SI 481363	Soil	<0.05	1	23	0.39	2.4	131	0.7
SI 481363 Dup		<0.05	1	25	0.40	2.3	132	0.6
STD-ME-6 expected							5170	
STD-ME-6 result		0.22	1	42	2.29	6.4	5457	4.6
SI 481382	Soil	<0.05	2	12	0.85	2.7	132	<0.5
SI 481382 Dup		<0.05	2	12	0.88	2.7	134	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.21	1	43	2.54	6.3	5640	4.2
SI 481400	Soil	<0.05	1	13	1.26	1.2	55	<0.5
SI 481400 Dup		<0.05	1	13	1.32	1.2	56	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.20	1	43	4.19	6.4	5392	4.6
SI 481418	Soil	<0.05	2	9	0.64	3.8	76	0.8
SI 481418 Dup		<0.05	2	8	0.64	3.8	75	0.9
STD-ME-6 expected							5170	
STD-ME-6 result		0.21	1	43	3.81	6.4	5677	4.3
SI 481436	Soil	<0.05	1	16	1.52	1.4	62	<0.5
SI 481436 Dup		<0.05	1	15	1.48	1.3	61	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.06	1	187	1.55	9.9	129	21.7
SI 481454	Soil	<0.05	1	20	3.05	1.4	65	<0.5
SI 481454 Dup		<0.05	1	20	3.14	1.5	64	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result							126	
TI 481314	Soil	<0.05	2	9	0.88	6.0	76	<0.5
TI 481314 Dup		<0.05	2	9	0.92	5.8	75	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.06	1	186	0.79	10.2	122	21.4
QCV1008-00087-0020-BLK		<0.05	<0.05	<1	0.10	<0.05	<1	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.06	1	178	2.37	9.7	127	20.9

Certificate of Analysis

10-360-02521-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 08/12/2010
Date Completed: 08/25/2010
Invoice:

Samples	Type	Preparation Description
63	Soil	SP-SS-1K/Soils, Humus Sediments 1kg dried, sieved and riffle split

Method	Description
50-AR-UT	50 Element, Aqua Regia, ICPMS, Ultra Trace Level
Au-1AT-AA	Au, 1AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481455	Soil	<0.005	<0.01	3.50	13.2	17	0.8	0.36	0.09	0.19	41.39	30.5	48	2.1	59.0
SI 481456	Soil	<0.005	<0.01	3.33	25.5	19	0.4	0.35	0.08	0.17	46.82	41.8	48	2.5	85.5
SI 481457	Soil	<0.005	0.19	3.59	23.9	11	0.5	0.56	0.07	0.33	35.55	18.4	48	2.0	36.9
SI 481458	Soil	0.044	0.29	1.54	114.8	50	0.5	0.40	0.11	0.30	41.07	30.5	22	1.4	47.3
SI 481459	Soil	0.139	0.29	0.95	310.1	47	0.8	0.66	0.05	0.18	34.00	64.0	19	2.2	67.5
SI 481460	Soil	0.011	0.19	2.39	31.2	17	0.2	0.27	0.03	0.09	15.65	22.2	28	1.1	30.1
SI 481461	Soil	0.051	0.10	2.23	109.5	23	0.4	0.38	0.04	0.09	34.63	22.8	30	0.7	47.1
SI 481462	Soil	0.068	0.36	0.75	362.3	28	0.4	0.32	0.05	0.40	27.87	11.6	12	1.1	28.9
SI 481463	Soil	0.199	0.30	0.47	540.9	30	0.1	0.36	0.02	0.17	24.53	5.0	12	1.3	15.8
SI 481464	Soil	0.600	1.40	0.49	1206.8	41	0.2	0.50	0.02	0.55	28.35	7.0	8	2.1	24.8
SI 481465	Soil	0.480	1.21	0.36	1798.3	39	0.3	0.80	0.01	0.97	26.34	18.4	9	2.0	76.7
SI 481466	Soil	0.565	0.89	0.43	1302.3	28	0.3	0.52	0.02	0.51	23.33	12.2	9	1.4	43.1
SI 481467	Soil	0.612	4.44	0.39	2238.0	30	0.1	0.66	<0.01	0.87	16.45	8.1	9	1.3	43.0
SI 481468	Soil	0.235	0.74	0.45	724.5	98	0.2	0.39	0.02	0.51	13.97	11.8	11	0.9	31.2
SI 481469	Soil	0.119	0.42	1.16	444.2	38	0.4	0.42	0.07	0.51	26.40	16.4	18	1.3	41.0
SI 481470	Soil	0.109	0.22	1.78	169.1	28	0.3	0.39	0.04	0.10	18.61	14.3	26	1.1	41.9
SI 481471	Soil	0.017	0.21	1.02	72.0	26	0.2	0.26	0.04	0.10	10.85	7.0	12	0.8	25.9
SI 484501	Soil	<0.005	0.12	3.11	34.3	22	0.9	0.82	0.06	0.45	27.24	19.7	47	3.5	60.7
SI 484502	Soil	0.008	0.11	3.05	35.0	16	0.5	0.46	0.05	0.10	29.23	18.2	45	2.5	58.8
SI 484503	Soil	<0.005	0.20	3.13	24.2	22	0.4	0.43	0.06	0.06	32.54	25.6	45	2.2	67.8
SI 484504	Soil	<0.005	0.27	3.43	25.5	27	0.4	0.45	0.09	0.05	31.22	25.3	46	2.5	83.7
SI 484505	Soil	0.009	0.22	2.89	89.8	22	0.5	0.54	0.11	0.09	29.94	30.9	42	1.8	77.3
SI 484506	Soil	0.009	0.22	3.01	95.4	27	0.7	0.59	0.07	0.09	24.89	33.2	41	2.3	113.5
SI 484507	Soil	0.008	0.28	2.83	78.2	24	0.4	0.40	0.10	0.08	20.50	27.3	39	1.7	66.7
SI 484508	Soil	0.012	0.11	3.04	82.0	21	0.5	0.37	0.09	0.04	19.47	32.9	43	1.9	72.2
SI 484509	Soil	<0.005	0.31	1.51	12.9	18	0.3	0.26	0.03	0.03	7.98	12.5	21	1.1	24.7
SI 484510	Soil	0.005	0.19	1.83	20.8	16	0.1	0.26	0.06	0.05	15.37	12.9	26	1.7	26.1
SI 484511	Soil	0.101	0.29	0.37	466.4	71	0.3	0.24	0.01	0.38	23.65	13.7	10	1.3	21.8
SI 484512	Soil	0.839	0.50	0.64	360.7	60	0.1	0.40	0.01	0.09	28.46	6.5	10	1.3	16.4
SI 484513	Soil	0.108	0.23	1.60	172.1	29	0.4	0.31	0.05	0.11	28.92	12.9	24	0.7	31.1
SI 484514	Soil	0.032	0.31	1.29	167.5	44	0.3	0.45	0.03	0.18	20.07	11.9	22	1.2	28.1
SI 484515	Soil	0.504	0.76	0.83	3792.5	37	0.3	0.38	0.04	0.29	25.64	8.7	12	1.0	26.8
SI 484516	Soil	0.790	0.49	1.29	1162.6	35	0.4	0.32	0.07	0.26	25.24	12.6	20	0.8	26.7
SI 484517	Soil	0.019	0.32	0.34	132.4	21	<0.05	0.10	0.02	0.05	3.88	3.1	3	0.3	6.9
SI 484518	Soil	0.227	0.20	0.69	112.6	19	0.2	0.24	0.02	0.20	7.54	4.6	8	0.4	11.6
SI 484519	Soil	0.015	0.28	1.36	62.6	26	0.4	0.50	0.05	0.24	19.21	12.0	20	2.4	41.2
SI 484520	Soil	0.020	0.23	1.22	113.1	30	0.2	0.43	0.02	0.12	19.75	9.4	18	1.3	31.1
SI 484521	Soil	0.064	0.29	1.11	324.8	18	0.5	0.48	0.02	0.22	25.15	14.8	19	1.4	48.9
SI 484522	Soil	0.038	0.48	0.79	147.7	18	0.5	0.36	0.01	0.28	25.01	21.2	15	1.6	39.5
SI 484523	Soil	0.110	0.52	0.45	376.3	27	0.4	0.51	<0.01	0.16	21.67	19.8	9	1.9	52.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 484524	Soil	0.098	0.30	0.63	466.1	32	0.5	0.52	0.02	0.18	21.03	23.1	12	1.9	48.4
SI 484525	Soil	0.024	0.40	0.42	112.2	27	0.6	0.48	0.03	0.18	10.82	30.4	10	1.6	53.5
SI 484526	Soil	0.006	0.27	0.76	22.0	17	0.1	0.29	0.02	0.08	6.22	9.8	9	1.0	26.3
SI 484527	Soil	<0.005	0.29	1.53	34.4	18	0.2	0.39	0.03	0.02	10.22	6.6	21	1.1	30.6
SI 484528	Soil	0.012	0.27	1.24	28.3	21	0.3	0.62	0.06	0.04	17.70	10.7	16	1.5	40.5
SI 484529	Soil	0.012	0.35	1.94	52.8	26	0.8	0.48	0.06	0.07	26.66	33.3	27	3.1	87.0
SI 484530	Soil	0.089	0.20	2.10	29.5	30	0.6	0.44	0.08	0.14	32.02	28.3	29	2.6	84.5
SI 484531	Soil	<0.005	0.20	1.47	15.8	29	0.2	0.27	0.04	0.05	20.48	10.9	22	1.7	34.7
SI 484532	Soil	0.006	0.19	2.54	33.0	19	0.3	0.49	0.03	0.09	36.37	19.3	34	1.3	52.6
SI 484533	Soil	0.016	0.18	1.65	28.0	26	0.2	0.39	0.02	0.05	21.05	12.2	26	2.1	39.9
SI 484534	Soil	0.110	0.55	0.84	298.5	39	0.4	0.35	0.02	0.14	26.97	11.8	13	2.0	36.1
SI 484535	Soil	0.018	0.31	2.08	52.1	17	0.6	0.53	0.08	0.16	21.06	22.6	27	2.1	59.4
SI 484536	Soil	0.051	0.36	1.43	109.0	25	0.5	0.99	0.05	0.28	18.60	32.0	19	1.8	66.5
SI 484537	Soil	0.007	0.19	1.77	22.9	15	0.4	0.61	<0.01	0.08	26.38	20.1	25	3.3	62.9
SI 484538	Soil	0.011	0.19	1.51	23.7	26	0.2	0.43	0.02	0.04	19.35	12.2	20	2.1	30.4
SI 484539	Soil	0.008	0.23	2.23	29.5	26	1.0	0.67	0.01	0.19	31.80	40.6	27	2.3	47.6
SI 484540	Soil	0.015	0.39	1.97	58.8	14	0.7	0.52	0.01	0.10	31.18	23.6	28	1.4	78.2
SI 484541	Soil	0.006	0.34	1.73	25.8	20	0.2	0.46	0.02	0.09	7.26	8.9	27	1.4	42.8
SI 484542	Soil	0.006	0.22	2.22	63.3	22	0.4	0.49	0.03	0.12	6.12	11.3	28	1.8	47.5
SI 484543	Soil	0.010	0.27	1.52	58.5	20	0.5	0.50	0.01	0.09	6.05	10.4	24	1.6	47.5
SI 484544	Soil	0.013	0.56	1.73	57.2	13	0.4	0.56	0.01	0.06	6.84	10.4	25	1.4	44.2
SI 484545	Soil	0.614	2.50	0.51	2192.7	43	0.6	0.55	0.02	1.11	18.02	24.6	10	4.7	45.9
SI 484546	Soil	0.081	0.34	0.65	974.9	30	0.2	0.40	0.01	0.17	19.25	15.4	13	2.2	35.6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 481455	Soil	6.73	8.0	<0.05	<0.02	0.03	0.02	23.5	102.8	1.66	1024	0.32	<0.01	<0.05	61.4
SI 481456	Soil	6.49	7.5	0.1	0.07	0.10	0.02	23.8	90.4	1.54	779	0.44	<0.01	0.1	55.9
SI 481457	Soil	6.88	8.0	0.2	<0.02	0.27	0.02	18.8	94.1	1.65	613	0.59	<0.01	0.2	54.5
SI 481458	Soil	5.19	4.1	<0.05	<0.02	0.08	0.02	19.2	30.1	0.54	4782	0.64	<0.01	0.2	38.1
SI 481459	Soil	5.52	2.5	<0.05	<0.02	0.09	0.03	16.9	22.8	0.37	3576	1.32	<0.01	0.1	63.0
SI 481460	Soil	4.95	5.3	<0.05	<0.02	0.04	0.02	8.7	73.5	1.16	1084	0.48	<0.01	0.1	40.9
SI 481461	Soil	5.58	4.9	<0.05	<0.02	0.03	0.01	18.8	61.6	1.02	1076	0.49	<0.01	0.1	52.5
SI 481462	Soil	2.99	1.7	<0.05	<0.02	0.08	0.03	13.7	11.6	0.23	528	0.58	<0.01	0.3	26.3
SI 481463	Soil	1.97	2.1	<0.05	<0.02	0.03	0.04	12.4	1.6	0.06	100	1.30	0.01	0.3	9.4
SI 481464	Soil	2.71	1.5	<0.05	<0.02	0.04	0.06	15.1	4.4	0.10	138	0.65	<0.01	0.2	12.0
SI 481465	Soil	5.06	1.6	<0.05	0.03	0.05	0.05	14.3	3.6	0.07	354	0.64	<0.01	0.1	39.3
SI 481466	Soil	3.50	1.5	<0.05	<0.02	0.04	0.04	13.1	4.4	0.09	299	0.52	<0.01	0.1	27.5
SI 481467	Soil	3.88	1.7	<0.05	<0.02	0.25	0.06	9.3	0.6	0.03	172	0.61	<0.01	0.1	20.7
SI 481468	Soil	2.94	2.2	<0.05	<0.02	0.07	0.05	7.5	0.3	0.03	1945	0.90	<0.01	0.1	17.9
SI 481469	Soil	3.93	2.9	<0.05	<0.02	0.04	0.04	13.2	21.2	0.39	855	0.82	<0.01	0.3	31.7
SI 481470	Soil	4.45	4.6	<0.05	<0.02	0.02	0.03	10.5	49.9	0.76	583	0.57	<0.01	0.2	37.6
SI 481471	Soil	2.33	2.9	<0.05	<0.02	0.01	0.02	5.9	18.5	0.29	201	0.49	0.01	0.2	15.8
SI 484501	Soil	6.16	7.8	0.4	<0.02	0.35	0.03	12.5	83.5	1.40	627	0.88	0.01	0.3	53.1
SI 484502	Soil	6.13	7.6	<0.05	<0.02	0.08	0.02	12.9	74.3	1.38	782	0.47	<0.01	0.1	51.1
SI 484503	Soil	6.15	7.8	<0.05	0.10	0.05	0.02	15.4	85.3	1.46	631	0.55	<0.01	<0.05	54.5
SI 484504	Soil	6.75	7.4	<0.05	0.12	0.05	0.02	15.5	91.5	1.60	707	0.56	<0.01	<0.05	56.1
SI 484505	Soil	5.76	7.1	<0.05	0.10	0.04	0.02	16.0	85.3	1.41	963	0.85	<0.01	<0.05	54.0
SI 484506	Soil	6.07	6.8	<0.05	0.03	0.03	0.02	12.0	82.7	1.48	907	1.00	<0.01	<0.05	53.7
SI 484507	Soil	6.00	6.7	<0.05	0.09	0.03	0.02	10.0	73.0	1.34	879	0.61	<0.01	<0.05	54.1
SI 484508	Soil	6.24	7.2	<0.05	0.08	0.02	0.02	9.4	81.4	1.43	729	0.44	<0.01	<0.05	52.8
SI 484509	Soil	2.82	4.2	<0.05	0.02	0.01	0.02	3.6	35.0	0.61	446	0.33	0.01	0.2	22.0
SI 484510	Soil	3.50	5.2	<0.05	<0.02	0.03	0.02	7.4	42.6	0.73	432	0.34	0.01	0.1	27.8
SI 484511	Soil	3.23	1.4	<0.05	<0.02	0.04	0.03	12.2	4.3	0.09	652	0.42	<0.01	0.1	25.0
SI 484512	Soil	1.93	1.8	<0.05	<0.02	0.02	0.04	15.8	15.6	0.26	214	0.59	<0.01	0.1	13.8
SI 484513	Soil	3.98	4.2	<0.05	<0.02	0.02	0.03	14.8	39.7	0.69	472	0.68	<0.01	0.3	32.9
SI 484514	Soil	4.12	5.2	<0.05	<0.02	0.02	0.05	9.9	18.8	0.35	623	1.09	<0.01	0.3	22.6
SI 484515	Soil	3.33	2.3	<0.05	<0.02	0.06	0.05	12.6	15.0	0.28	260	0.66	<0.01	0.3	16.8
SI 484516	Soil	3.87	3.2	<0.05	<0.02	0.04	0.04	12.7	30.3	0.58	433	0.62	<0.01	0.2	29.6
SI 484517	Soil	0.76	1.6	<0.05	<0.02	0.01	0.02	2.0	1.4	0.04	96	0.29	0.01	0.1	2.9
SI 484518	Soil	1.19	2.3	<0.05	<0.02	0.12	0.02	3.9	6.8	0.14	93	0.43	0.01	0.2	7.3
SI 484519	Soil	3.53	4.1	0.1	<0.02	0.12	0.03	11.0	30.7	0.46	505	0.74	0.01	0.3	24.0
SI 484520	Soil	3.45	4.0	<0.05	<0.02	0.07	0.03	11.0	23.8	0.35	300	0.81	<0.01	0.4	20.3
SI 484521	Soil	5.81	2.9	<0.05	<0.02	0.06	0.03	13.7	27.0	0.40	392	0.83	<0.01	0.3	37.9
SI 484522	Soil	4.85	2.2	<0.05	<0.02	0.05	0.02	13.1	16.4	0.24	1107	0.73	<0.01	0.2	33.3
SI 484523	Soil	3.76	1.3	<0.05	<0.02	0.04	0.03	12.4	3.9	0.07	433	0.35	<0.01	0.1	37.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 484524	Soil	4.14	1.6	<0.05	<0.02	0.04	0.03	11.9	9.9	0.16	742	0.45	<0.01	0.1	37.1
SI 484525	Soil	3.92	1.1	<0.05	<0.02	0.02	0.03	6.3	3.2	0.07	1044	0.49	<0.01	<0.05	40.2
SI 484526	Soil	1.93	2.4	<0.05	<0.02	0.02	0.02	3.6	13.6	0.19	285	0.31	0.01	0.2	17.1
SI 484527	Soil	3.98	4.0	<0.05	<0.02	0.02	0.02	6.2	42.1	0.62	369	0.77	<0.01	0.2	25.5
SI 484528	Soil	3.16	3.3	<0.05	<0.02	0.02	0.03	10.4	33.9	0.52	392	0.89	0.02	0.2	23.5
SI 484529	Soil	5.23	5.0	<0.05	<0.02	0.02	0.02	16.1	58.3	0.84	788	0.77	<0.01	0.1	48.0
SI 484530	Soil	5.15	5.1	<0.05	<0.02	0.03	0.02	19.1	63.8	0.90	763	0.80	<0.01	0.1	49.9
SI 484531	Soil	3.57	4.9	<0.05	<0.02	0.02	0.03	12.0	35.5	0.54	378	0.63	0.01	0.3	22.1
SI 484532	Soil	5.61	5.7	<0.05	<0.02	0.02	0.02	22.0	77.0	1.09	602	0.48	<0.01	0.1	49.5
SI 484533	Soil	3.96	5.3	<0.05	<0.02	0.02	0.03	12.8	41.8	0.60	486	0.51	<0.01	0.2	27.5
SI 484534	Soil	3.09	2.7	<0.05	<0.02	0.03	0.03	15.0	11.9	0.18	363	0.53	<0.01	0.2	24.3
SI 484535	Soil	5.67	4.8	<0.05	<0.02	0.09	0.02	13.5	60.5	0.90	783	0.48	<0.01	0.1	51.0
SI 484536	Soil	5.83	3.8	<0.05	0.05	0.10	0.02	11.5	44.4	0.61	1039	0.63	<0.01	0.1	63.0
SI 484537	Soil	5.58	4.1	<0.05	<0.02	0.06	0.03	16.6	50.5	0.76	584	0.52	<0.01	0.1	49.4
SI 484538	Soil	4.22	3.8	<0.05	<0.02	0.03	0.03	11.8	39.0	0.58	730	0.55	0.01	0.2	28.0
SI 484539	Soil	6.93	4.2	<0.05	<0.02	0.03	0.02	20.8	63.5	0.90	3464	0.48	<0.01	<0.05	68.3
SI 484540	Soil	6.58	4.6	<0.05	<0.02	0.03	0.02	20.5	63.7	0.90	685	0.52	<0.01	<0.05	49.2
SI 484541	Soil	5.25	4.9	<0.05	0.04	0.03	0.03	4.7	43.2	0.62	454	0.64	<0.01	0.2	28.9
SI 484542	Soil	5.18	5.0	<0.05	0.03	0.03	0.03	3.6	55.4	0.80	582	0.41	<0.01	0.1	32.2
SI 484543	Soil	4.50	4.5	<0.05	<0.02	0.02	0.03	3.6	34.6	0.51	346	0.40	<0.01	0.2	24.1
SI 484544	Soil	5.38	5.1	<0.05	0.03	0.02	0.02	4.0	39.1	0.58	392	0.54	<0.01	0.3	26.3
SI 484545	Soil	4.44	1.2	<0.05	<0.02	0.11	0.06	9.9	5.3	0.07	996	0.42	<0.01	<0.05	39.3
SI 484546	Soil	4.42	2.3	<0.05	<0.02	0.02	0.04	10.9	7.0	0.12	558	0.53	<0.01	0.1	25.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 481455	Soil	375	18.3	1.7	<0.01	0.01	<0.05	2.2	<0.2	0.5	4.7	<0.01	0.11	7	<0.005
SI 481456	Soil	400	43.9	1.5	0.06	<0.01	<0.05	2.3	0.4	0.2	3.3	0.04	0.18	9	<0.005
SI 481457	Soil	416	24.3	1.3	0.28	<0.01	<0.05	1.7	1.1	0.4	2.7	0.08	0.49	6	<0.005
SI 481458	Soil	518	159.6	2.3	0.06	0.03	<0.05	1.3	0.6	0.2	18.3	0.02	0.17	6	<0.005
SI 481459	Soil	601	63.4	2.5	0.06	0.03	<0.05	1.4	0.9	<0.2	11.6	<0.01	0.33	1	<0.005
SI 481460	Soil	542	30.0	1.7	0.03	0.02	<0.05	0.4	<0.2	<0.2	3.0	<0.01	0.13	1	<0.005
SI 481461	Soil	360	31.1	1.6	0.01	<0.01	<0.05	1.5	0.6	<0.2	5.2	<0.01	0.15	6	<0.005
SI 481462	Soil	486	211.7	3.4	<0.01	0.02	0.82	1.2	0.4	0.3	42.3	<0.01	0.09	4	0.009
SI 481463	Soil	566	104.8	5.3	<0.01	0.08	1.96	0.2	0.8	0.4	30.5	<0.01	0.07	0	0.009
SI 481464	Soil	288	421.0	5.3	<0.01	0.09	2.67	0.9	1.1	0.8	37.8	<0.01	0.11	4	<0.005
SI 481465	Soil	357	357.1	3.8	<0.01	0.08	2.41	1.2	0.3	0.3	36.9	<0.01	0.11	11	<0.005
SI 481466	Soil	383	284.1	3.4	<0.01	0.05	1.78	0.5	0.5	0.3	18.6	<0.01	0.17	3	<0.005
SI 481467	Soil	534	2195.0	4.5	<0.01	0.12	5.07	0.2	0.5	1.2	24.9	<0.01	0.13	1	<0.005
SI 481468	Soil	907	357.3	5.1	0.02	0.12	1.83	<0.1	0.6	0.3	12.0	<0.01	0.15	<0.2	<0.005
SI 481469	Soil	778	154.4	4.7	<0.01	0.03	1.09	1.2	0.9	0.4	14.7	<0.01	0.13	4	0.012
SI 481470	Soil	541	46.9	3.2	<0.01	0.03	<0.05	0.7	0.5	<0.2	11.2	<0.01	<0.01	1	0.006
SI 481471	Soil	478	19.3	2.8	<0.01	0.04	0.17	<0.1	0.8	<0.2	6.5	<0.01	0.09	<0.2	0.008
SI 484501	Soil	414	50.8	1.7	0.31	0.01	<0.05	2.4	0.6	0.4	3.8	0.17	0.65	6	<0.005
SI 484502	Soil	440	42.9	1.6	0.05	0.01	<0.05	1.7	<0.2	<0.2	4.8	<0.01	0.22	5	<0.005
SI 484503	Soil	332	30.9	1.4	0.04	<0.01	<0.05	2.3	0.3	<0.2	3.7	0.02	0.13	8	<0.005
SI 484504	Soil	333	51.3	1.3	0.02	<0.01	<0.05	2.1	0.6	<0.2	4.7	<0.01	0.11	8	<0.005
SI 484505	Soil	314	73.7	1.2	0.03	<0.01	<0.05	1.9	0.6	<0.2	5.1	<0.01	0.11	8	<0.005
SI 484506	Soil	313	58.6	1.3	0.01	<0.01	<0.05	2.0	0.3	<0.2	3.9	<0.01	0.13	8	<0.005
SI 484507	Soil	328	48.7	1.1	0.02	<0.01	<0.05	2.1	<0.2	<0.2	6.4	<0.01	0.04	7	<0.005
SI 484508	Soil	346	41.0	1.1	<0.01	0.01	<0.05	2.2	0.3	<0.2	5.2	<0.01	0.13	7	<0.005
SI 484509	Soil	414	18.5	1.4	<0.01	0.03	<0.05	0.2	0.4	<0.2	3.1	<0.01	0.15	0	<0.005
SI 484510	Soil	489	20.4	1.8	0.01	0.01	<0.05	0.5	0.2	<0.2	3.8	<0.01	0.18	1	<0.005
SI 484511	Soil	377	42.2	2.4	<0.01	0.02	1.17	1.7	0.7	0.3	107.6	<0.01	0.07	3	<0.005
SI 484512	Soil	302	71.6	2.6	<0.01	0.05	2.47	0.6	0.5	0.2	140.7	<0.01	0.09	4	<0.005
SI 484513	Soil	518	29.1	3.5	<0.01	0.02	0.37	1.0	0.3	<0.2	25.6	<0.01	0.13	2	0.011
SI 484514	Soil	832	34.6	6.3	<0.01	0.07	<0.05	<0.1	0.7	0.4	10.8	<0.01	0.13	<0.2	0.006
SI 484515	Soil	496	309.3	4.1	0.01	0.08	3.41	0.7	0.9	0.3	22.8	<0.01	0.27	2	0.007
SI 484516	Soil	430	170.8	3.3	<0.01	0.03	1.20	1.6	0.3	0.3	20.7	<0.01	0.09	7	0.012
SI 484517	Soil	327	24.8	1.7	<0.01	0.04	0.19	<0.1	0.6	<0.2	4.6	<0.01	0.05	<0.2	0.005
SI 484518	Soil	376	21.4	2.1	0.12	0.04	0.32	<0.1	1.3	<0.2	8.3	0.04	0.15	<0.2	0.008
SI 484519	Soil	687	35.0	4.7	0.09	0.02	<0.05	0.4	0.5	0.3	12.9	0.04	0.24	1	0.008
SI 484520	Soil	533	29.7	4.8	0.05	0.04	0.13	0.2	0.6	0.3	7.6	0.02	0.15	0	0.007
SI 484521	Soil	558	50.2	2.7	0.03	0.04	1.44	0.7	1.0	0.2	10.5	0.01	0.26	2	0.007
SI 484522	Soil	564	54.1	2.6	0.03	0.02	0.92	1.1	1.2	<0.2	6.2	<0.01	0.07	6	<0.005
SI 484523	Soil	420	43.3	2.3	0.02	0.02	0.64	0.5	0.7	<0.2	18.0	<0.01	0.22	1	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 484524	Soil	470	55.0	3.1	0.02	0.03	0.42	0.9	0.5	<0.2	14.6	<0.01	0.31	2	<0.005
SI 484525	Soil	511	52.6	2.2	0.01	0.03	0.07	0.7	0.4	<0.2	12.9	<0.01	0.13	1	<0.005
SI 484526	Soil	347	19.5	2.2	<0.01	0.03	0.10	0.1	0.5	<0.2	4.9	<0.01	0.11	0	0.006
SI 484527	Soil	492	23.3	2.6	<0.01	0.02	0.09	0.7	0.7	<0.2	6.2	<0.01	0.13	2	0.007
SI 484528	Soil	450	38.4	2.7	<0.01	0.01	0.10	1.0	0.3	<0.2	9.2	<0.01	0.15	3	0.008
SI 484529	Soil	583	58.7	3.2	<0.01	0.02	<0.05	1.2	0.5	<0.2	9.5	<0.01	0.14	4	<0.005
SI 484530	Soil	574	61.2	2.4	<0.01	0.01	0.24	1.6	0.6	<0.2	8.5	<0.01	0.05	6	<0.005
SI 484531	Soil	662	13.3	4.4	<0.01	0.04	<0.05	0.2	0.5	0.2	5.6	<0.01	0.07	0	0.007
SI 484532	Soil	341	34.8	2.7	<0.01	0.01	<0.05	1.0	<0.2	<0.2	5.2	<0.01	0.13	3	<0.005
SI 484533	Soil	851	22.8	4.1	<0.01	0.04	<0.05	0.2	<0.2	<0.2	5.5	<0.01	0.07	1	<0.005
SI 484534	Soil	555	55.6	3.9	<0.01	0.04	1.09	0.2	<0.2	0.2	54.7	<0.01	0.15	0	<0.005
SI 484535	Soil	552	40.0	1.8	0.06	<0.01	<0.05	1.6	0.4	<0.2	8.8	0.03	0.35	8	<0.005
SI 484536	Soil	469	74.8	1.3	0.07	<0.01	<0.05	1.9	0.3	<0.2	16.7	0.02	0.31	12	<0.005
SI 484537	Soil	400	62.9	2.4	0.05	0.02	<0.05	1.7	1.1	0.2	8.0	0.02	0.15	9	<0.005
SI 484538	Soil	418	19.2	3.2	0.01	0.02	0.46	0.4	<0.2	<0.2	7.4	<0.01	0.22	1	0.007
SI 484539	Soil	258	34.3	2.2	0.01	<0.01	<0.05	2.4	<0.2	0.2	13.1	<0.01	0.22	9	<0.005
SI 484540	Soil	461	42.5	1.4	<0.01	0.02	0.25	1.7	0.7	<0.2	19.3	<0.01	0.13	8	<0.005
SI 484541	Soil	1013	35.4	3.6	0.01	0.07	<0.05	0.1	0.3	<0.2	11.3	<0.01	0.07	1	<0.005
SI 484542	Soil	1060	32.3	2.6	<0.01	0.07	<0.05	<0.1	0.7	<0.2	3.4	<0.01	0.13	1	<0.005
SI 484543	Soil	1232	48.9	3.4	<0.01	0.10	0.11	0.1	0.5	<0.2	2.5	<0.01	0.11	1	<0.005
SI 484544	Soil	1145	75.6	3.3	<0.01	0.08	0.14	0.2	1.0	<0.2	2.9	<0.01	0.13	1	<0.005
SI 484545	Soil	406	1212.7	3.8	<0.01	0.14	2.96	1.3	0.8	0.5	44.8	<0.01	0.15	2	<0.005
SI 484546	Soil	779	58.2	4.1	<0.01	0.07	1.34	<0.1	1.0	<0.2	20.1	<0.01	0.17	0	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 481455	Soil	<0.05	1	20	1.49	3.1	130	0.8
SI 481456	Soil	0.06	2	18	3.00	2.9	123	3.3
SI 481457	Soil	0.19	1	19	2.99	2.1	123	0.7
SI 481458	Soil	0.08	2	14	1.87	4.7	93	<0.5
SI 481459	Soil	0.09	2	10	1.62	7.8	117	<0.5
SI 481460	Soil	<0.05	1	14	0.52	1.3	82	<0.5
SI 481461	Soil	<0.05	1	15	2.30	3.2	109	<0.5
SI 481462	Soil	<0.05	1	12	6.44	3.4	113	<0.5
SI 481463	Soil	<0.05	1	15	4.50	1.8	53	<0.5
SI 481464	Soil	0.06	1	8	2.37	2.2	78	<0.5
SI 481465	Soil	<0.05	2	8	2.39	2.8	163	1.6
SI 481466	Soil	<0.05	2	7	2.82	2.0	102	<0.5
SI 481467	Soil	0.06	1	7	1.07	1.4	205	<0.5
SI 481468	Soil	0.06	1	14	3.61	1.4	120	<0.5
SI 481469	Soil	<0.05	2	15	1.92	3.5	123	<0.5
SI 481470	Soil	<0.05	1	15	1.47	2.8	97	<0.5
SI 481471	Soil	<0.05	1	12	3.44	1.7	49	<0.5
SI 484501	Soil	0.26	2	19	5.10	2.9	117	0.7
SI 484502	Soil	0.05	1	19	1.09	2.0	115	<0.5
SI 484503	Soil	<0.05	1	17	2.65	2.4	119	4.7
SI 484504	Soil	<0.05	1	17	2.37	2.8	124	5.5
SI 484505	Soil	<0.05	1	16	2.34	3.0	121	4.7
SI 484506	Soil	<0.05	2	16	2.40	2.9	129	3.1
SI 484507	Soil	<0.05	1	17	1.05	2.6	124	3.9
SI 484508	Soil	<0.05	1	17	2.65	2.7	118	4.3
SI 484509	Soil	<0.05	1	10	2.26	1.3	54	0.9
SI 484510	Soil	<0.05	1	13	3.18	1.4	67	<0.5
SI 484511	Soil	<0.05	2	11	2.35	2.2	83	<0.5
SI 484512	Soil	0.07	1	6	2.82	2.1	42	<0.5
SI 484513	Soil	<0.05	1	18	3.78	2.8	87	<0.5
SI 484514	Soil	<0.05	1	24	2.32	2.6	68	<0.5
SI 484515	Soil	<0.05	1	11	2.41	2.6	72	<0.5
SI 484516	Soil	<0.05	1	15	2.54	3.4	90	1.0
SI 484517	Soil	<0.05	0	8	2.80	0.5	16	<0.5
SI 484518	Soil	0.09	1	10	2.80	1.1	26	<0.5
SI 484519	Soil	0.09	1	15	2.23	2.3	68	<0.5
SI 484520	Soil	0.07	1	16	2.81	1.6	68	<0.5
SI 484521	Soil	<0.05	1	13	5.25	2.3	120	<0.5
SI 484522	Soil	<0.05	2	10	3.34	2.9	103	<0.5
SI 484523	Soil	<0.05	1	7	2.87	2.0	106	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 484524	Soil	<0.05	1	8	2.01	2.2	113	<0.5
SI 484525	Soil	0.05	1	7	2.38	1.8	102	<0.5
SI 484526	Soil	<0.05	1	7	2.59	0.9	47	<0.5
SI 484527	Soil	<0.05	1	12	3.96	1.2	68	<0.5
SI 484528	Soil	<0.05	1	11	2.96	1.7	60	<0.5
SI 484529	Soil	<0.05	2	14	2.93	2.7	126	<0.5
SI 484530	Soil	<0.05	2	15	0.97	2.9	129	<0.5
SI 484531	Soil	<0.05	1	18	2.81	1.6	64	<0.5
SI 484532	Soil	<0.05	1	17	2.54	2.1	113	<0.5
SI 484533	Soil	<0.05	1	16	1.93	1.4	72	0.6
SI 484534	Soil	<0.05	1	14	2.50	1.9	79	<0.5
SI 484535	Soil	0.06	1	12	4.30	2.7	122	<0.5
SI 484536	Soil	0.06	2	10	4.16	4.0	190	3.8
SI 484537	Soil	0.09	2	11	2.62	2.0	124	0.8
SI 484538	Soil	<0.05	1	11	1.67	1.4	73	<0.5
SI 484539	Soil	<0.05	1	11	0.84	5.8	127	2.9
SI 484540	Soil	<0.05	2	11	3.05	1.8	132	0.9
SI 484541	Soil	<0.05	1	12	1.78	1.0	84	1.0
SI 484542	Soil	<0.05	2	12	2.19	1.3	80	0.8
SI 484543	Soil	<0.05	2	13	0.92	1.5	72	0.7
SI 484544	Soil	<0.05	1	14	1.91	1.3	76	1.3
SI 484545	Soil	0.09	2	7	1.98	4.4	144	<0.5
SI 484546	Soil	<0.05	1	10	2.87	1.7	103	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 481455	Soil	<0.005													
SI 481455 Dup		<0.005													
SI 484502	Soil	0.008													
SI 484502 Dup		0.009													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.811													
QCV1008-00299-0004-BLK		<0.005													
SI 484520	Soil	0.020													
SI 484520 Dup		0.015													
SI 484538	Soil	0.011													
SI 484538 Dup		0.005													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.659													
QCV1008-00299-0008-BLK		<0.005													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.652													
QCV1008-00300-0001-BLK			<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
SI 481455	Soil		<0.01	3.50	13.2	17	0.8	0.36	0.09	0.19	41.39	30.5	48	2.1	59.0
SI 481455 Dup			<0.01	3.50	13.2	16	0.8	0.38	0.09	0.20	40.25	32.1	50	2.0	59.3
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.30	3.36	5.0	200	0.7	0.17	0.25	0.11	31.20	110.4	865	0.7	656.6
SI 484502	Soil		0.11	3.05	35.0	16	0.5	0.46	0.05	0.10	29.23	18.2	45	2.5	58.8
SI 484502 Dup			0.14	3.02	35.9	17	0.5	0.48	0.05	0.09	30.06	18.7	45	2.6	60.2
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.32	3.28	6.3	194	1.1	0.64	0.24	0.54	30.52	110.2	819	0.6	645.5
SI 484520	Soil		0.23	1.22	113.1	30	0.2	0.43	0.02	0.12	19.75	9.4	18	1.3	31.1
SI 484520 Dup			0.24	1.25	113.4	31	0.2	0.44	0.02	0.11	20.35	9.5	18	1.3	31.8
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.27	3.60	5.3	201	0.7	0.31	0.25	0.27	31.95	112.8	899	0.8	676.2
SI 484538	Soil		0.19	1.51	23.7	26	0.2	0.43	0.02	0.04	19.35	12.2	20	2.1	30.4
SI 484538 Dup			0.22	1.50	24.1	27	0.2	0.45	0.02	0.04	19.37	12.6	20	2.2	31.1
QCV1008-00300-0009-BLK			<0.01	<0.01	0.2	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.34	3.64	4.0	197	0.7	0.16	0.25	0.07	31.06	112.4	911	0.9	656.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Fe	Ga	Ge	Hf	In	K	La	Li	Mg	Mn	Mo	Na	Nb	Ni
		50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample Description	Sample Type	%	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%	ppm	ppm
		0.01	0.05	0.05	0.02	0.01	0.01	0.2	0.1	0.01	1	0.05	0.01	0.05	0.2
QCV1008-00300-0001-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
SI 481455	Soil	6.73	8.0	<0.05	<0.02	0.03	0.02	23.5	102.8	1.66	1024	0.32	<0.01	<0.05	61.4
SI 481455 Dup		6.77	8.3	<0.05	<0.02	0.02	0.02	22.3	105.1	1.70	1047	0.32	<0.01	<0.05	62.8
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	14.6	<0.05	0.49	0.07	0.07	13.8	3.7	0.10	1115	0.91	0.02	0.5	284.7
SI 484502	Soil	6.13	7.6	<0.05	<0.02	0.08	0.02	12.9	74.3	1.38	782	0.47	<0.01	0.1	51.1
SI 484502 Dup		6.13	8.0	<0.05	<0.02	0.07	0.02	13.4	73.6	1.33	772	0.48	<0.01	0.1	50.7
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	15.0	0.4	0.51	0.53	0.07	14.2	4.1	0.09	1056	1.29	0.02	0.9	278.8
SI 484520	Soil	3.45	4.0	<0.05	<0.02	0.07	0.03	11.0	23.8	0.35	300	0.81	<0.01	0.4	20.3
SI 484520 Dup		3.47	4.1	<0.05	<0.02	0.07	0.03	11.6	24.3	0.35	307	0.83	<0.01	0.4	20.6
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	15.5	0.1	0.51	0.22	0.07	14.9	4.6	0.11	1125	1.09	0.02	0.6	303.3
SI 484538	Soil	4.22	3.8	<0.05	<0.02	0.03	0.03	11.8	39.0	0.58	730	0.55	0.01	0.2	28.0
SI 484538 Dup		4.23	3.7	<0.05	<0.02	0.03	0.03	12.1	38.1	0.58	728	0.55	0.01	0.2	27.5
QCV1008-00300-0009-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	14.7	<0.05	0.57	0.08	0.07	14.2	4.9	0.11	1128	0.81	0.02	0.4	308.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th	Ti
		50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample Description	Sample Type	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%
		5	0.2	0.1	0.01	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2	0.005
QCV1008-00300-0001-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
SI 481455	Soil	375	18.3	1.7	<0.01	0.01	<0.05	2.2	<0.2	0.5	4.7	<0.01	0.11	7	<0.005
SI 481455 Dup		376	18.0	1.7	0.01	0.01	<0.05	2.3	<0.2	0.5	4.7	<0.01	0.10	7	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		300	18.4	6.8	<0.01	0.03	<0.05	46.8	0.2	1.5	11.9	<0.01	0.02	6	0.148
SI 484502	Soil	440	42.9	1.6	0.05	0.01	<0.05	1.7	<0.2	<0.2	4.8	<0.01	0.22	5	<0.005
SI 484502 Dup		442	44.4	1.6	0.05	0.01	<0.05	1.8	<0.2	<0.2	4.9	0.01	0.22	5	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		294	18.2	6.8	0.37	0.03	<0.05	44.3	1.2	1.9	12.2	0.20	0.90	6	0.141
SI 484520	Soil	533	29.7	4.8	0.05	0.04	0.13	0.2	0.6	0.3	7.6	0.02	0.15	0	0.007
SI 484520 Dup		537	30.3	4.9	0.05	0.04	0.12	0.2	0.6	0.3	7.6	0.02	0.15	0	0.007
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		307	18.5	7.1	0.16	0.03	<0.05	48.0	0.3	1.8	12.5	0.05	0.29	6	0.167
SI 484538	Soil	418	19.2	3.2	0.01	0.02	0.46	0.4	<0.2	<0.2	7.4	<0.01	0.22	1	0.007
SI 484538 Dup		419	19.3	3.2	0.01	0.02	0.45	0.4	<0.2	<0.2	7.4	<0.01	0.20	1	0.007
QCV1008-00300-0009-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		304	18.5	7.5	<0.01	0.03	<0.05	47.7	0.6	1.6	12.0	<0.01	0.05	6	0.179

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02521-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
QCV1008-00300-0001-BLK		<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
SI 481455	Soil	<0.05	1	20	1.49	3.1	130	0.8
SI 481455 Dup		<0.05	1	20	1.51	3.1	132	0.7
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		<0.05	1	174	2.08	8.5	128	19.7
SI 484502	Soil	0.05	1	19	1.09	2.0	115	<0.5
SI 484502 Dup		<0.05	1	20	1.06	2.0	115	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.34	1	176	3.38	8.8	125	19.5
SI 484520	Soil	0.07	1	16	2.81	1.6	68	<0.5
SI 484520 Dup		0.07	1	17	2.87	1.6	69	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.13	1	195	2.08	8.9	130	21.1
SI 484538	Soil	<0.05	1	11	1.67	1.4	73	<0.5
SI 484538 Dup		<0.05	1	11	1.65	1.4	72	<0.5
QCV1008-00300-0009-BLK		<0.05	<0.05	<1	0.12	<0.05	<1	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		<0.05	1	174	2.68	8.4	130	19.7

Certificate of Analysis

10-360-02522-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 08/12/2010
Date Completed: 08/27/2010
Invoice:

Samples	Type	Preparation Description
22	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
Pb-4A-OR-ICP	Pb, Ore Grade, 4 Acid, ICP
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-1AT-GV	Au, 1AT, Gravimetric
Au-2AT-AA	Au, 2AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02522-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Pb Pb-4A-OR-ICP % 0.01	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1
RI 480172	Rock		0.008		<0.01	0.89	14.0	51	0.2	0.11	0.16	0.40	12.09	3.1	228
RI 480173	Rock		0.015		<0.01	8.99	58.1	509	2.8	3.05	0.03	0.39	100.16	5.7	98
RI 480174	Rock		0.036		<0.01	9.74	93.4	527	3.4	3.47	0.07	0.29	107.83	7.9	106
RI 480175	Rock	70.908	>10		10.11	0.12	1595.9	10	0.2	0.27	<0.01	0.14	1.11	0.8	291
RI 480176	Rock	11.541	>10		0.46	0.52	796.9	26	0.2	0.39	<0.01	0.19	4.31	2.1	262
RI 480177	Rock		0.134		0.20	0.30	746.8	29	0.4	0.32	<0.01	0.23	3.97	0.8	245
RI 480178	Rock		0.426		<0.01	0.52	792.0	34	0.4	0.08	<0.01	0.14	4.25	0.7	209
RI 480179	Rock		0.676		<0.01	2.05	2073.5	116	1.2	0.14	0.17	0.12	19.26	2.5	146
RI 480180	Rock		0.100		<0.01	2.02	1206.7	143	0.6	0.21	<0.01	0.09	23.35	1.4	150
RI 480181	Rock		0.024		<0.01	2.01	1632.4	177	1.0	0.11	0.01	0.17	20.10	1.4	140
RI 480182	Rock		0.202		<0.01	2.11	1171.9	100	0.4	0.14	<0.01	0.13	19.07	0.6	158
RI 480183	Rock		1.671	1.61	22.83	1.47	6706.0	76	0.4	0.94	0.01	0.22	9.13	0.4	149
RI 480184	Rock		0.869		14.22	1.16	>10000	66	0.2	0.52	<0.01	1.05	14.49	<0.1	146
RI 480185	Rock		0.015		<0.01	1.49	369.6	79	0.6	0.10	<0.01	0.38	18.18	2.4	248
RI 480186	Rock		0.010		0.19	1.42	247.8	91	0.4	0.06	<0.01	0.05	16.35	0.8	165
RI 480187	Rock		0.316		7.20	2.23	2040.4	75	0.8	0.38	0.02	0.76	25.57	1.3	154
RI 480188	Rock		0.076		0.29	3.04	201.7	110	0.8	0.23	0.01	0.30	30.82	2.0	181
RI 481015	Rock		0.204		<0.01	0.62	2729.3	28	0.2	0.08	<0.01	0.14	5.50	0.6	174
RI 481016	Rock		0.029		0.02	0.51	268.4	27	0.2	0.03	0.01	0.08	6.29	1.2	214
RI 481508	Rock		1.644		0.47	0.26	5832.7	28	0.2	0.31	<0.01	0.09	1.38	0.6	251
RI 481509	Rock		0.072		<0.01	0.09	6866.7	6	0.1	0.16	0.01	0.02	1.66	0.8	211
RI 481510	Rock		0.082		<0.01	1.55	6050.5	134	0.9	0.30	0.01	<0.01	12.28	2.8	192

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02522-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01
RI 480172	Rock	0.3	8.8	0.85	1.6	0.5	0.31	0.01	0.22	6.2	8.8	0.15	198	0.95	0.02
RI 480173	Rock	5.7	62.0	6.39	17.4	1.7	2.66	0.06	2.77	52.9	47.5	0.47	147	3.01	0.67
RI 480174	Rock	7.4	59.1	7.62	18.7	1.6	2.14	0.06	3.00	57.6	61.2	0.63	221	2.73	0.72
RI 480175	Rock	0.2	5.5	0.44	0.5	2.4	<0.1	<0.01	0.05	0.5	4.7	<0.01	27	1.08	<0.01
RI 480176	Rock	0.4	6.2	0.64	1.4	1.2	0.17	<0.01	0.14	2.2	5.7	0.02	81	0.88	<0.01
RI 480177	Rock	0.3	6.0	0.38	1.1	0.8	<0.1	<0.01	0.15	1.7	2.9	0.02	31	1.01	<0.01
RI 480178	Rock	0.3	5.2	0.42	1.5	1.2	0.20	<0.01	0.19	2.1	2.1	0.02	32	0.95	<0.01
RI 480179	Rock	0.9	6.2	1.17	3.5	1.4	0.89	0.02	0.59	9.2	12.4	0.04	120	0.54	0.03
RI 480180	Rock	1.4	5.7	0.67	3.4	0.9	1.05	0.02	0.78	11.1	25.3	0.05	66	0.68	0.03
RI 480181	Rock	3.7	30.5	3.85	3.7	1.4	1.23	0.05	0.61	9.5	9.9	0.04	24	1.91	0.02
RI 480182	Rock	1.5	5.8	0.49	3.6	1.4	0.90	<0.01	0.62	9.6	4.1	0.04	17	0.75	0.02
RI 480183	Rock	1.1	30.1	1.30	2.8	1.9	0.75	1.11	0.64	4.7	3.4	0.06	25	1.39	0.02
RI 480184	Rock	1.1	16.5	3.23	2.3	1.5	0.76	0.48	0.33	7.4	6.8	0.08	34	1.65	0.04
RI 480185	Rock	1.1	5.8	0.66	2.6	1.0	0.88	0.02	0.42	8.7	7.1	0.03	101	0.87	0.02
RI 480186	Rock	3.7	6.5	0.65	3.5	1.2	2.14	0.02	0.40	7.7	22.0	0.02	21	0.70	0.02
RI 480187	Rock	2.6	17.3	2.57	3.6	2.3	0.92	0.04	0.46	12.0	37.1	0.04	63	0.79	0.02
RI 480188	Rock	2.5	10.3	0.85	4.8	1.9	1.33	0.01	0.67	14.4	34.9	0.04	69	0.64	0.03
RI 481015	Rock	0.4	3.1	0.54	1.2	1.4	0.25	<0.01	0.13	2.8	11.0	0.02	23	0.70	<0.01
RI 481016	Rock	0.3	4.4	0.57	0.9	1.1	0.21	<0.01	0.14	2.6	1.1	0.01	114	0.61	0.14
RI 481508	Rock	0.2	3.3	0.70	1.0	1.7	<0.1	<0.01	0.12	0.8	1.8	0.01	24	1.11	<0.01
RI 481509	Rock	0.1	4.1	0.79	0.3	1.1	<0.1	0.02	0.02	0.9	0.8	<0.01	29	1.09	<0.01
RI 481510	Rock	1.0	6.3	0.89	4.6	1.2	0.55	0.02	0.67	6.2	3.6	0.07	49	0.74	0.08

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02522-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05
RI 480172	Rock	0.3	12.3	57	4.7	9.7	0.015	<0.01	<0.05	1.0	<0.5	0.5	14.7	<0.05	0.07
RI 480173	Rock	3.6	17.7	352	198.9	123.9	<0.005	0.13	1.39	14.8	1.2	1.9	109.7	0.41	0.28
RI 480174	Rock	3.4	23.7	392	284.9	127.1	<0.005	0.03	1.98	15.6	<0.5	1.9	117.0	0.41	0.42
RI 480175	Rock	0.2	5.6	<10	19.3	2.2	<0.005	0.06	2.16	<0.1	<0.5	0.3	2.6	<0.05	0.21
RI 480176	Rock	0.3	8.8	28	93.5	6.7	<0.005	0.03	1.01	0.4	<0.5	0.4	3.7	<0.05	0.07
RI 480177	Rock	0.2	5.9	<10	29.8	6.9	<0.005	0.03	1.17	0.2	<0.5	0.4	3.6	<0.05	0.29
RI 480178	Rock	0.3	5.2	22	8.9	8.0	<0.005	0.03	0.86	0.5	1.6	0.5	3.8	<0.05	<0.05
RI 480179	Rock	0.2	9.5	258	16.0	25.1	0.029	0.07	4.73	2.5	<0.5	0.6	42.9	<0.05	0.36
RI 480180	Rock	0.7	5.7	80	86.4	34.5	<0.005	<0.01	2.83	1.8	<0.5	1.4	12.6	0.10	0.21
RI 480181	Rock	0.5	6.5	560	37.4	27.1	<0.005	0.01	5.50	1.7	<0.5	0.6	124.2	0.06	0.14
RI 480182	Rock	0.5	3.5	56	9.6	26.9	<0.005	0.02	3.62	1.8	<0.5	0.8	17.2	0.10	0.43
RI 480183	Rock	0.4	5.0	210	>10000	29.2	<0.005	0.21	37.25	0.5	2.1	8.8	19.6	0.05	0.14
RI 480184	Rock	0.4	3.3	252	7624.4	14.7	<0.005	0.33	74.04	1.2	<0.5	2.7	62.6	<0.05	0.07
RI 480185	Rock	0.6	6.2	61	76.1	18.4	<0.005	<0.01	2.47	1.2	<0.5	0.6	23.8	0.07	0.07
RI 480186	Rock	0.6	6.6	77	47.4	22.7	<0.005	<0.01	1.88	1.4	2.0	0.7	11.1	0.07	0.37
RI 480187	Rock	0.6	7.2	167	3102.8	21.6	<0.005	0.11	13.97	2.8	<0.5	1.5	56.7	0.07	0.14
RI 480188	Rock	1.1	6.4	94	125.7	28.0	<0.005	0.01	2.99	2.4	<0.5	0.9	57.2	0.14	0.14
RI 481015	Rock	0.2	4.7	27	22.4	6.5	<0.005	0.09	1.58	0.2	<0.5	0.3	5.5	<0.05	0.07
RI 481016	Rock	0.3	5.9	20	11.0	6.7	<0.005	0.02	0.68	0.6	<0.5	0.4	8.7	<0.05	0.07
RI 481508	Rock	0.2	5.1	<10	11.6	5.9	<0.005	0.18	4.76	0.3	<0.5	0.6	2.2	<0.05	0.50
RI 481509	Rock	0.2	5.7	45	9.6	0.7	<0.005	0.31	2.96	<0.1	<0.5	0.2	2.0	<0.05	0.50
RI 481510	Rock	0.6	7.6	54	9.1	28.2	<0.005	0.24	2.71	1.5	<0.5	2.0	6.8	0.06	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02522-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480172	Rock	2	0.007	0.04	0	<1	7.80	2.3	13	8.1
RI 480173	Rock	15	0.112	0.58	2	63	13.09	5.4	40	75.7
RI 480174	Rock	16	0.114	0.67	2	68	12.70	5.7	54	69.8
RI 480175	Rock	0	<0.005	<0.02	<0.1	<1	10.44	0.1	4	0.7
RI 480176	Rock	1	<0.005	<0.02	0	<1	7.86	0.6	14	5.3
RI 480177	Rock	0	<0.005	0.04	<0.1	<1	9.36	0.2	7	1.4
RI 480178	Rock	1	0.006	0.03	0	<1	46.25	0.6	5	6.4
RI 480179	Rock	5	0.017	0.43	1	6	2479.20	3.6	20	27.9
RI 480180	Rock	6	0.023	0.16	1	7	34.04	2.7	10	35.4
RI 480181	Rock	14	0.016	0.13	2	16	16.61	3.4	45	38.1
RI 480182	Rock	5	0.016	0.13	1	4	13.66	2.0	5	30.5
RI 480183	Rock	4	0.012	0.19	3	2	9.98	1.1	38	19.3
RI 480184	Rock	5	0.011	0.18	1	4	10.27	1.6	66	26.2
RI 480185	Rock	4	0.017	0.11	1	<1	14.87	2.1	19	29.1
RI 480186	Rock	6	0.015	0.07	1	8	4.08	2.0	9	24.9
RI 480187	Rock	6	0.017	0.17	3	12	11.67	3.5	50	33.2
RI 480188	Rock	6	0.034	0.14	1	12	13.81	3.3	25	44.7
RI 481015	Rock	2	<0.005	<0.02	0	<1	10.03	0.7	9	7.4
RI 481016	Rock	2	0.005	<0.02	0	<1	11.02	0.8	16	7.4
RI 481508	Rock	0	<0.005	<0.02	<0.1	<1	7.73	0.2	4	1.5
RI 481509	Rock	0	<0.005	<0.02	<0.1	<1	6.83	0.4	3	1.5
RI 481510	Rock	4	0.020	0.13	1	4	17.94	1.4	15	21.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02522-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Pb Pb-4A-OR-ICP % 0.01	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1
RI 480172	Rock		0.008												
RI 480172 Dup			0.007												
RI 481016	Rock		0.029												
RI 481016 Dup			0.020												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.778												
QCV1008-00296-0004-BLK			<0.005												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.741												
QCV1008-00297-0001-BLK					<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	0.02	<0.02	<0.1	<1
RI 480172	Rock				<0.01	0.89	14.0	51	0.2	0.11	0.16	0.40	12.09	3.1	228
RI 480172 Dup					<0.01	0.90	14.3	52	0.2	0.12	0.17	0.38	12.65	3.1	335
STD-ME-8 expected					61.70										
STD-ME-8 result					61.35	4.74	2843.8	467	1.9	2.04	7.07	105.86	21.93	<0.1	44
RI 481016	Rock				0.02	0.51	268.4	27	0.2	0.03	0.01	0.08	6.29	1.2	214
RI 481016 Dup					<0.01	0.51	266.6	27	0.2	0.03	0.01	0.08	6.64	1.2	220
QCV1008-00297-0005-BLK					<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1
STD-SY-4 expected								340	2.6				122.00	2.8	12
STD-SY-4 result					<0.01	>10	13.6	356	3.1	0.08	5.84	0.12	126.57	3.8	9
QCV1008-00995-0001-BLK				<0.01											
RI 480183	Rock			1.61											
RI 480183 Dup				1.59											
QCV1008-00995-0003-BLK				<0.01											
STD-ME-8 expected				1.94											
STD-ME-8 result				2.08											

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02522-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01
QCV1008-00297-0001-BLK		<0.05	<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01
RI 480172	Rock	0.3	8.8	0.85	1.6	0.5	0.31	0.01	0.22	6.2	8.8	0.15	198	0.95	0.02
RI 480172 Dup		0.3	9.2	0.86	1.6	0.5	0.32	<0.01	0.23	6.2	9.3	0.16	200	1.01	0.03
STD-ME-8 expected			1030.0												
STD-ME-8 result		2.5	952.2	3.90	8.0	0.8	0.71	<0.01	1.46	11.2	15.0	0.74	3161	4.34	1.29
RI 481016	Rock	0.3	4.4	0.57	0.9	1.1	0.21	<0.01	0.14	2.6	1.1	0.01	114	0.61	0.14
RI 481016 Dup		0.3	4.3	0.57	1.0	1.1	0.19	<0.01	0.14	2.8	1.2	0.01	114	0.60	0.13
QCV1008-00297-0005-BLK		<0.05	<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01
STD-SY-4 expected		1.5	7.0		35.0		10.60			58.0	37.0				
STD-SY-4 result		1.5	7.5	4.44	26.8	0.2	1.16	0.03	1.48	59.5	40.1	0.33	716	0.42	5.47

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02522-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05
QCV1008-00297-0001-BLK		<0.1	<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05
RI 480172	Rock	0.3	12.3	57	4.7	9.7	0.015	<0.01	<0.05	1.0	<0.5	0.5	14.7	<0.05	0.07
RI 480172 Dup		0.3	12.3	58	5.0	9.5	<0.005	<0.01	<0.05	1.0	<0.5	0.5	15.4	<0.05	0.07
STD-ME-8 expected					19400										
STD-ME-8 result		3.5	30.2	646	>10000	56.6	<0.005	2.08	58.36	1.5	<0.5	1.1	386.3	0.54	1.43
RI 481016	Rock	0.3	5.9	20	11.0	6.7	<0.005	0.02	0.68	0.6	<0.5	0.4	8.7	<0.05	0.07
RI 481016 Dup		0.3	5.5	19	11.0	6.5	<0.005	0.02	0.66	0.5	<0.5	0.4	8.6	<0.05	0.07
QCV1008-00297-0005-BLK		<0.1	<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05
STD-SY-4 expected		13.0	9.0		10.0	55.0				1.1			1191.0	0.90	
STD-SY-4 result		14.5	8.6	573	13.6	48.2	0.011	<0.01	<0.05	0.9	<0.5	8.2	1295.6	1.22	0.34

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02522-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1008-00297-0001-BLK		<0.2	<0.005	<0.02	<0.1	<1	0.11	<0.1	<2	<0.5
RI 480172	Rock	2	0.007	0.04	0	<1	7.80	2.3	13	8.1
RI 480172 Dup		2	0.007	0.05	0	<1	8.05	2.4	14	8.6
STD-ME-8 expected									19200	
STD-ME-8 result		3	0.189	0.83	2	49	95.38	9.8	>10000	25.8
RI 481016	Rock	2	0.005	<0.02	0	<1	11.02	0.8	16	7.4
RI 481016 Dup		1	0.005	<0.02	0	<1	11.65	0.8	16	7.4
QCV1008-00297-0005-BLK		<0.2	<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected		1			1	8		119.0	93	517.0
STD-SY-4 result		1	0.170	0.21	1	<1	10.24	109.9	99	58.6

Certificate of Analysis

10-360-02523-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 08/12/2010
Date Completed: 08/27/2010
Invoice:

Samples	Type	Preparation Description
51	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
Pb-4A-OR-ICP	Pb, Ore Grade, 4 Acid, ICP
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-1AT-GV	Au, 1AT, Gravimetric
Au-2AT-AA	Au, 2AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Pb Pb-4A-OR-ICP % 0.01	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1
RI 480189	Rock		0.419		<0.01	2.88	9368.3	162	0.5	0.33	0.76	0.25	25.80	5.2	142
RI 480190	Rock		0.121		<0.01	2.35	1103.9	88	0.4	0.53	0.04	0.15	37.96	1.9	156
RI 480191	Rock		0.620		11.68	0.53	7552.3	97	0.2	8.28	0.02	0.73	89.63	1.1	146
RI 480192	Rock		<0.005		<0.01	0.16	79.3	9	<0.05	0.27	0.04	0.10	7.35	1.1	245
RI 480193	Rock		0.058		<0.01	0.37	>10000	40	0.1	0.32	0.01	0.18	5.10	2.2	211
RI 480194	Rock		0.067		<0.01	2.47	616.8	99	0.6	0.15	<0.01	<0.01	25.54	3.3	166
RI 480201	Rock		0.010		<0.01	2.68	626.8	138	1.3	0.30	0.01	0.45	20.20	10.9	146
RI 480202	Rock		0.072		<0.01	1.93	782.2	97	0.4	0.22	<0.01	0.12	23.50	0.7	193
RI 480203	Rock		0.022		<0.01	2.72	237.8	143	0.9	0.33	<0.01	0.34	39.75	1.0	170
RI 480204	Rock		3.695	1.78	34.20	2.08	>10000	137	0.6	1.22	<0.01	0.54	13.57	<0.1	133
RI 480205	Rock		0.983		0.47	0.52	>10000	42	0.4	0.23	<0.01	0.28	4.81	<0.1	155
RI 480206	Rock		0.586		5.45	1.75	>10000	119	0.5	0.64	<0.01	0.52	18.43	0.4	211
RI 480207	Rock		0.009		<0.01	1.52	131.5	47	0.7	1.37	0.01	0.10	9.71	2.5	189
RI 480208	Rock		0.015		<0.01	2.45	495.3	136	0.8	0.10	0.01	0.16	22.18	3.8	144
RI 480209	Rock		0.093		<0.01	2.80	1594.2	109	1.1	0.15	0.01	<0.01	29.53	1.8	178
RI 480210	Rock		0.071		<0.01	2.43	893.6	78	0.5	0.14	0.01	0.06	26.36	2.0	165
RI 480211	Rock		0.222		<0.01	2.50	4931.8	97	0.9	0.17	0.02	0.14	24.36	2.8	165
RI 480212	Rock		0.095		<0.01	2.95	839.2	111	0.7	0.10	0.01	0.08	30.79	2.3	191
RI 480213	Rock		0.030		<0.01	2.36	629.2	139	0.7	0.17	<0.01	0.08	20.87	2.9	180
RI 480214	Rock		0.034		<0.01	2.75	197.7	151	0.8	0.25	<0.01	0.09	21.42	2.2	153
RI 480215	Rock		0.391		<0.01	0.87	5702.2	62	0.3	0.22	<0.01	<0.01	5.78	0.3	172
RI 480216	Rock		0.630		2.48	1.52	>10000	87	0.5	0.24	<0.01	0.15	16.04	0.4	136
RI 480217	Rock		1.405		8.17	1.81	>10000	105	0.9	0.34	<0.01	0.38	17.14	0.2	150
RI 480218	Rock		0.089		<0.01	2.66	956.0	140	0.8	0.12	0.08	1.55	31.07	4.0	182
RI 480219	Rock		0.023		0.28	2.22	395.5	121	0.6	0.10	<0.01	0.35	26.30	1.7	201
RI 480220	Rock		0.016		<0.01	2.48	460.9	142	0.6	0.15	<0.01	0.20	27.79	1.3	244
RI 480221	Rock		<0.005		<0.01	1.96	36.7	96	0.5	0.09	0.01	0.04	20.50	2.1	270
RI 480222	Rock		0.060		0.27	2.48	189.3	159	0.7	0.14	<0.01	<0.01	31.31	1.2	201
RI 480223	Rock		0.533		<0.01	1.49	182.8	79	0.7	0.08	<0.01	<0.01	13.58	0.8	191
RI 480224	Rock		0.049		<0.01	1.80	183.5	85	0.6	0.09	<0.01	0.32	18.14	1.4	142
RI 480225	Rock		0.051		<0.01	2.44	82.4	142	0.8	0.10	<0.01	<0.01	19.31	1.0	232
RI 480226	Rock		0.195		4.87	2.22	943.1	134	0.5	0.24	0.02	0.61	27.10	1.4	161
RI 480227	Rock		0.143		14.25	2.64	399.2	141	0.5	0.18	0.01	<0.01	23.50	1.2	158
RI 480228	Rock		0.568		0.49	2.82	1200.5	171	0.6	0.23	<0.01	<0.01	23.19	0.9	162
RI 480229	Rock		1.129	3.66	59.17	0.84	>10000	74	0.3	3.34	0.01	0.48	24.61	0.8	111
RI 481019	Rock		1.384		83.61	1.84	>10000	109	0.5	171.62	0.04	1.43	15.63	3.7	190
RI 481511	Rock		0.068		<0.01	1.94	454.8	81	0.5	0.13	0.01	0.10	23.50	1.2	246
RI 481512	Rock		0.057		<0.01	2.48	442.5	112	0.8	0.62	<0.01	0.16	29.00	1.0	216
RI 481513	Rock		0.072		<0.01	2.10	646.5	105	0.7	0.10	0.01	0.12	24.15	1.2	186
RI 481514	Rock		0.736		<0.01	0.52	2613.7	26	0.2	0.12	<0.01	0.10	3.35	0.4	255

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Pb Pb-4A-OR-ICP % 0.01	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1
RI 481515	Rock		0.338		<0.01	0.76	2678.0	48	0.4	0.24	<0.01	0.13	8.01	0.7	347
RI 481516	Rock		0.082		<0.01	0.12	1073.3	31	0.1	0.11	<0.01	<0.01	1.09	0.4	196
RI 481517	Rock		0.362		<0.01	1.22	1172.1	63	0.6	0.13	0.03	0.26	13.21	2.0	441
RI 481518	Rock	99.107	>10		6.23	0.62	191.7	38	0.4	0.14	0.01	0.03	6.10	0.8	293
RI 481519	Rock		9.591		2.08	0.46	295.4	19	0.1	0.07	<0.01	<0.01	6.41	1.6	387
RI 481520	Rock	181.056	>10		13.06	0.15	884.0	17	0.1	0.13	<0.01	<0.01	1.32	0.8	276
RI 481521	Rock	39.526	>10		2.07	0.04	29.6	15	<0.05	0.06	<0.01	<0.01	0.17	0.9	462
RI 481522	Rock	22.015	>10		4.00	0.08	149.5	9	0.1	0.10	<0.01	<0.01	0.49	0.9	427
RI 481523	Rock	22.972	>10		0.33	0.40	284.9	28	0.2	0.18	<0.01	<0.01	3.37	0.7	304
RI 481524	Rock		2.440		<0.01	2.51	2808.4	121	0.9	0.10	0.02	0.19	29.11	1.5	171
RI 481525	Rock		0.264		<0.01	2.45	807.3	129	1.0	0.14	0.03	0.40	39.89	4.3	195

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01
RI 480189	Rock	1.2	7.0	2.41	5.1	0.8	1.16	0.03	0.76	12.5	8.5	0.24	332	0.62	0.71
RI 480190	Rock	0.9	5.8	1.22	3.4	0.6	1.69	<0.01	0.34	17.4	11.8	0.20	48	0.71	0.75
RI 480191	Rock	0.7	752.2	3.21	0.8	1.7	<0.1	0.49	0.14	36.0	10.8	0.01	77	1.02	0.01
RI 480192	Rock	0.1	8.3	0.41	0.4	1.1	<0.1	0.02	0.03	3.8	12.7	<0.01	58	0.79	0.01
RI 480193	Rock	0.2	6.6	1.47	0.8	1.1	0.19	0.02	0.11	2.5	3.3	0.01	30	0.92	<0.01
RI 480194	Rock	1.5	5.6	1.31	4.4	1.3	1.12	0.02	0.70	12.2	19.1	0.08	164	0.75	0.07
RI 480201	Rock	4.6	44.1	3.87	3.8	0.8	1.21	0.03	0.60	9.9	34.7	0.03	146	0.75	0.03
RI 480202	Rock	1.7	4.1	0.45	3.3	1.6	1.42	0.02	0.77	11.3	18.2	0.05	21	0.72	0.03
RI 480203	Rock	1.6	18.5	0.57	4.7	0.9	2.39	0.03	0.87	19.3	6.3	0.06	18	0.80	0.03
RI 480204	Rock	1.7	89.4	4.80	9.3	2.0	0.88	1.35	0.88	7.5	6.3	0.09	23	1.46	0.04
RI 480205	Rock	0.5	59.3	2.63	1.4	1.9	0.32	0.21	0.22	2.3	4.2	0.02	20	0.85	0.01
RI 480206	Rock	1.3	8.7	1.73	3.2	1.7	1.21	0.58	0.75	8.4	6.9	0.05	26	0.83	0.03
RI 480207	Rock	0.9	14.6	0.95	2.0	1.1	0.38	0.02	0.18	4.5	12.2	0.04	205	0.89	0.03
RI 480208	Rock	1.5	10.7	0.96	4.2	0.7	1.27	0.02	0.73	10.8	13.2	0.06	142	0.55	0.05
RI 480209	Rock	1.5	3.6	1.29	4.8	1.0	1.38	<0.01	0.82	14.3	19.9	0.08	147	0.68	0.04
RI 480210	Rock	1.2	4.2	1.27	3.7	0.9	1.20	0.01	0.64	11.4	12.2	0.09	98	0.65	0.05
RI 480211	Rock	1.7	5.2	1.52	3.9	1.1	1.14	0.02	0.98	11.7	8.8	0.09	212	0.80	0.05
RI 480212	Rock	1.7	9.3	1.32	5.0	0.9	1.51	0.01	0.90	14.5	14.8	0.10	118	0.78	0.07
RI 480213	Rock	1.7	19.2	4.13	3.8	0.8	0.81	0.02	0.70	10.2	14.9	0.04	136	0.76	0.03
RI 480214	Rock	2.1	12.0	1.37	4.6	1.0	1.02	0.03	0.74	10.7	9.3	0.04	40	0.65	0.04
RI 480215	Rock	0.8	15.0	0.66	2.1	2.1	0.28	0.01	0.39	2.8	2.2	0.03	19	0.84	0.01
RI 480216	Rock	1.2	16.7	1.24	2.7	1.4	0.80	0.14	0.55	7.8	4.5	0.04	20	0.80	0.02
RI 480217	Rock	1.6	111.5	1.96	4.8	1.8	0.90	0.22	0.83	8.6	5.1	0.07	21	0.91	0.02
RI 480218	Rock	3.0	28.6	1.96	4.8	1.4	1.30	0.04	0.84	14.7	14.2	0.05	93	0.75	0.05
RI 480219	Rock	1.4	6.6	0.88	3.8	0.8	1.37	0.03	0.75	12.0	9.4	0.05	50	0.74	0.04
RI 480220	Rock	1.3	5.8	0.62	4.1	0.9	1.43	0.02	0.76	13.4	17.0	0.05	39	0.86	0.07
RI 480221	Rock	0.9	7.2	0.63	3.0	0.8	0.96	0.01	0.52	9.6	6.2	0.07	66	0.96	0.13
RI 480222	Rock	1.9	6.0	0.41	4.5	1.2	1.62	0.01	0.98	14.4	5.1	0.06	25	0.96	0.03
RI 480223	Rock	0.8	4.3	0.67	2.5	1.1	0.66	<0.01	0.47	6.3	10.7	0.03	33	0.85	0.02
RI 480224	Rock	1.9	6.3	0.60	3.0	1.2	1.01	<0.01	0.57	8.8	6.0	0.08	35	0.88	0.04
RI 480225	Rock	3.5	4.0	0.41	4.5	1.2	0.92	0.01	0.87	9.3	9.5	0.05	22	0.96	0.04
RI 480226	Rock	4.6	17.9	1.75	4.1	1.8	1.16	0.41	0.65	13.7	25.2	0.05	63	0.96	0.04
RI 480227	Rock	1.8	33.7	0.59	4.3	1.6	0.84	0.14	1.01	11.6	8.9	0.15	55	0.77	0.06
RI 480228	Rock	1.5	7.1	0.53	5.1	1.1	1.48	0.01	1.32	10.9	5.4	0.12	27	0.79	0.04
RI 480229	Rock	1.4	249.2	3.05	1.9	2.4	0.48	0.70	0.27	12.5	19.5	0.05	25	1.30	0.02
RI 481019	Rock	1.2	13.4	4.66	4.3	1.2	1.32	1.04	0.46	7.6	12.0	0.05	58	0.86	0.03
RI 481511	Rock	1.1	4.3	0.58	2.9	0.6	0.53	<0.01	0.47	10.3	5.0	0.03	26	0.79	0.02
RI 481512	Rock	1.8	4.5	0.57	4.1	1.0	1.29	0.02	0.74	13.2	5.8	0.05	22	0.71	0.03
RI 481513	Rock	1.9	3.8	0.56	4.1	1.1	1.08	<0.01	0.83	10.9	5.7	0.06	38	0.57	0.03
RI 481514	Rock	0.8	5.0	0.47	1.1	2.2	0.16	<0.01	0.13	1.6	4.5	0.01	25	0.79	<0.01

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01
RI 481515	Rock	1.7	6.9	0.62	2.1	2.0	0.32	<0.01	0.19	3.8	7.1	0.02	45	1.03	<0.01
RI 481516	Rock	0.3	2.7	0.33	0.4	1.7	<0.1	<0.01	0.04	<0.5	4.6	<0.01	19	0.67	<0.01
RI 481517	Rock	0.8	5.9	0.88	2.9	1.3	0.67	0.01	0.40	5.8	3.6	0.03	111	1.38	0.01
RI 481518	Rock	0.9	4.4	0.35	2.0	1.8	0.28	<0.01	0.17	2.7	6.0	0.04	31	0.92	0.02
RI 481519	Rock	0.3	4.9	0.49	0.8	1.9	0.23	<0.01	0.05	2.9	6.4	<0.01	46	1.20	<0.01
RI 481520	Rock	0.2	3.9	0.42	0.5	2.3	<0.1	<0.01	0.06	0.7	2.2	<0.01	38	1.01	<0.01
RI 481521	Rock	0.1	4.6	0.36	0.2	2.6	<0.1	<0.01	<0.01	<0.5	2.3	<0.01	31	1.17	<0.01
RI 481522	Rock	0.1	5.4	0.38	0.3	2.6	<0.1	<0.01	0.02	<0.5	2.4	<0.01	35	1.09	<0.01
RI 481523	Rock	0.6	5.5	0.35	1.9	2.5	<0.1	<0.01	0.16	1.6	8.9	0.02	29	0.94	<0.01
RI 481524	Rock	1.9	5.8	0.81	6.3	1.8	1.30	0.01	0.83	13.0	12.3	0.07	37	0.62	0.03
RI 481525	Rock	2.5	17.7	1.18	6.5	1.5	1.70	0.01	0.75	18.1	7.6	0.08	168	0.76	0.03

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05
RI 480189	Rock	0.6	11.6	75	111.0	33.8	0.007	0.83	10.67	3.0	<0.5	0.9	48.8	0.07	0.07
RI 480190	Rock	0.8	6.5	77	30.0	16.0	<0.005	0.22	1.56	1.8	<0.5	0.6	29.3	0.09	0.19
RI 480191	Rock	0.2	5.5	460	3463.3	5.8	0.010	0.16	39.91	1.6	8.3	1.0	301.3	<0.05	0.65
RI 480192	Rock	0.2	5.0	176	40.6	1.4	<0.005	<0.01	0.72	0.3	<0.5	0.3	7.1	<0.05	<0.05
RI 480193	Rock	0.3	7.1	19	37.4	5.1	<0.005	0.65	7.17	0.4	1.6	0.4	6.2	<0.05	0.78
RI 480194	Rock	0.7	7.8	60	7.2	32.9	<0.005	<0.01	2.32	2.4	<0.5	0.7	16.0	0.06	<0.05
RI 480201	Rock	0.5	24.7	661	18.0	24.7	<0.005	0.01	3.00	3.8	<0.5	0.7	73.8	0.06	0.20
RI 480202	Rock	1.3	3.2	99	87.6	32.8	<0.005	0.02	3.67	1.5	<0.5	4.0	35.3	0.12	0.26
RI 480203	Rock	1.1	5.6	82	146.1	36.2	<0.005	<0.01	4.75	2.6	<0.5	2.1	21.7	0.10	<0.05
RI 480204	Rock	0.5	2.7	625	>10000	36.6	<0.005	0.42	100.68	8.7	2.0	9.6	66.2	<0.05	1.37
RI 480205	Rock	0.2	3.4	125	67.1	9.9	<0.005	0.22	28.17	1.5	<0.5	2.6	5.0	<0.05	0.13
RI 480206	Rock	0.6	3.8	162	1885.8	30.8	<0.005	0.12	27.16	1.5	<0.5	4.9	19.3	0.06	0.46
RI 480207	Rock	0.4	8.3	75	69.0	9.0	<0.005	<0.01	1.29	1.3	<0.5	0.3	7.7	<0.05	0.33
RI 480208	Rock	0.7	9.6	97	19.1	30.9	<0.005	0.02	1.34	2.0	<0.5	0.5	12.5	0.07	<0.05
RI 480209	Rock	1.0	5.4	106	69.7	37.6	0.007	0.03	3.86	2.9	<0.5	0.8	10.5	0.11	<0.05
RI 480210	Rock	0.8	5.7	85	24.2	28.6	<0.005	0.04	2.18	2.3	<0.5	0.8	11.2	0.08	<0.05
RI 480211	Rock	0.9	6.7	71	105.6	44.3	<0.005	0.39	12.26	1.8	<0.5	1.3	10.5	0.08	0.13
RI 480212	Rock	1.1	7.0	129	38.4	40.4	0.007	0.03	2.76	3.0	<0.5	1.2	9.8	0.10	<0.05
RI 480213	Rock	0.5	9.6	475	27.0	28.4	<0.005	0.04	2.30	3.0	<0.5	0.5	86.1	<0.05	0.07
RI 480214	Rock	0.8	7.1	162	12.5	30.3	<0.005	<0.01	1.72	2.8	<0.5	0.8	47.1	0.06	0.19
RI 480215	Rock	0.3	3.5	40	15.6	18.7	<0.005	0.10	6.75	1.4	<0.5	0.6	8.9	<0.05	0.71
RI 480216	Rock	0.6	2.6	95	1192.7	25.0	<0.005	0.05	17.44	1.6	<0.5	2.6	14.6	<0.05	<0.05
RI 480217	Rock	0.5	2.7	222	2379.3	36.6	<0.005	0.13	32.49	2.7	3.5	5.3	34.0	<0.05	0.26
RI 480218	Rock	1.0	8.7	639	33.8	36.1	<0.005	0.01	3.47	3.0	<0.5	1.5	47.6	0.06	<0.05
RI 480219	Rock	1.1	5.1	80	254.1	31.7	<0.005	0.01	2.37	2.0	<0.5	2.3	14.7	0.12	<0.05
RI 480220	Rock	1.1	5.1	88	60.3	31.5	<0.005	<0.01	2.70	2.2	<0.5	1.5	17.0	0.10	0.19
RI 480221	Rock	0.8	6.7	66	26.4	21.3	<0.005	<0.01	0.74	1.4	<0.5	0.5	11.4	0.07	0.19
RI 480222	Rock	1.1	4.2	68	269.6	41.6	<0.005	0.01	3.68	2.1	<0.5	2.2	15.8	0.08	0.06
RI 480223	Rock	0.7	4.4	36	9.7	19.6	<0.005	<0.01	2.05	1.4	1.5	0.7	10.5	0.07	<0.05
RI 480224	Rock	0.7	4.6	71	12.4	24.8	0.007	<0.01	3.08	1.2	<0.5	3.5	16.6	<0.05	0.13
RI 480225	Rock	1.0	5.2	87	51.9	39.1	<0.005	0.01	1.87	1.8	<0.5	0.9	50.3	0.08	<0.05
RI 480226	Rock	0.7	5.8	692	2623.2	27.9	<0.005	0.10	14.07	2.0	2.7	5.7	148.3	0.07	0.19
RI 480227	Rock	0.8	3.5	417	4331.0	42.5	<0.005	0.10	4.40	2.5	<0.5	10.9	55.6	0.08	0.19
RI 480228	Rock	1.3	2.7	137	58.1	52.7	0.007	0.06	3.86	3.2	<0.5	14.2	17.7	0.12	0.13
RI 480229	Rock	0.3	4.3	378	>10000	11.7	<0.005	0.30	56.33	1.5	6.7	3.1	30.9	<0.05	0.13
RI 481019	Rock	0.5	8.9	57	7442.0	25.5	<0.005	2.48	36.86	1.9	6.4	2.6	41.7	0.06	0.57
RI 481511	Rock	0.4	4.1	71	49.6	21.2	<0.005	<0.01	1.32	1.0	<0.5	0.9	9.3	0.06	0.06
RI 481512	Rock	0.9	3.8	39	45.6	33.4	0.007	<0.01	1.43	1.1	<0.5	1.5	9.3	0.08	0.06
RI 481513	Rock	0.7	4.2	51	25.1	36.2	<0.005	0.02	1.77	1.7	<0.5	5.5	11.5	<0.05	0.06
RI 481514	Rock	0.2	3.7	<10	13.1	6.9	<0.005	0.06	2.44	0.2	1.3	0.3	4.8	<0.05	0.13

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05
RI 481515	Rock	0.4	6.0	39	29.2	13.7	<0.005	0.03	2.51	0.9	2.0	0.6	13.4	<0.05	0.25
RI 481516	Rock	<0.1	3.2	<10	9.8	2.9	0.007	0.01	1.98	<0.1	1.6	0.2	3.6	<0.05	<0.05
RI 481517	Rock	0.6	8.0	169	104.7	18.4	<0.005	0.12	2.26	1.1	<0.5	3.4	11.8	0.06	<0.05
RI 481518	Rock	0.3	4.4	<10	19.9	8.2	0.007	<0.01	1.75	0.3	<0.5	1.0	15.2	<0.05	0.20
RI 481519	Rock	0.5	7.9	27	17.7	2.6	<0.005	<0.01	2.38	0.2	<0.5	0.5	13.7	<0.05	<0.05
RI 481520	Rock	0.2	4.8	<10	38.7	2.6	<0.005	0.03	2.38	<0.1	<0.5	3.7	5.4	<0.05	0.07
RI 481521	Rock	0.2	5.8	<10	9.0	0.4	<0.005	<0.01	1.80	<0.1	<0.5	<0.2	1.6	<0.05	<0.05
RI 481522	Rock	0.2	5.1	<10	12.2	0.9	<0.005	<0.01	1.77	<0.1	<0.5	0.4	3.4	<0.05	0.07
RI 481523	Rock	0.2	3.9	<10	16.4	8.3	<0.005	<0.01	1.78	0.4	<0.5	0.4	4.8	<0.05	0.07
RI 481524	Rock	0.7	4.2	69	15.9	37.3	<0.005	0.02	4.98	2.0	<0.5	0.7	12.8	0.05	0.13
RI 481525	Rock	1.0	12.9	149	157.0	44.1	<0.005	<0.01	2.45	2.8	<0.5	0.8	9.7	0.11	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480189	Rock	9	0.023	0.20	1	11	8.04	3.7	22	38.9
RI 480190	Rock	11	0.024	0.10	2	2	8.88	4.1	12	58.1
RI 480191	Rock	2	<0.005	0.09	2	<1	9.37	32.6	23	6.9
RI 480192	Rock	1	<0.005	<0.02	0	<1	7.45	8.5	34	1.5
RI 480193	Rock	2	0.005	<0.02	0	<1	9.16	1.5	5	8.5
RI 480194	Rock	6	0.027	0.18	1	10	4.71	3.3	14	36.6
RI 480201	Rock	12	0.017	0.11	3	7	10.09	3.6	87	34.3
RI 480202	Rock	6	0.025	0.19	1	2	9.46	2.6	6	44.8
RI 480203	Rock	9	0.035	0.18	1	12	9.09	4.9	8	76.6
RI 480204	Rock	42	0.019	0.25	1	7	11.92	1.8	45	31.1
RI 480205	Rock	3	0.006	0.07	0	<1	7.96	0.6	26	11.1
RI 480206	Rock	4	0.021	0.13	1	4	11.03	2.2	25	39.0
RI 480207	Rock	2	0.008	0.04	0	<1	7.41	1.0	19	17.3
RI 480208	Rock	7	0.024	0.17	1	7	8.74	2.1	34	38.2
RI 480209	Rock	8	0.030	0.23	1	13	4.57	3.4	9	46.4
RI 480210	Rock	7	0.029	0.13	1	7	9.19	2.9	11	38.9
RI 480211	Rock	6	0.028	0.29	1	8	9.33	3.0	9	34.0
RI 480212	Rock	8	0.036	0.21	1	9	7.97	3.5	33	49.4
RI 480213	Rock	8	0.017	0.12	1	7	5.35	2.8	58	28.2
RI 480214	Rock	6	0.022	0.15	1	8	8.63	2.7	70	33.6
RI 480215	Rock	2	0.009	0.08	0	<1	7.63	0.6	5	11.3
RI 480216	Rock	4	0.018	0.14	1	3	11.58	1.7	21	30.4
RI 480217	Rock	11	0.018	0.21	1	6	9.40	2.0	23	31.2
RI 480218	Rock	8	0.029	0.20	2	8	7.94	4.5	78	43.4
RI 480219	Rock	6	0.030	0.16	1	5	10.70	3.2	48	48.4
RI 480220	Rock	6	0.032	0.14	1	8	7.99	3.2	13	44.2
RI 480221	Rock	5	0.023	0.10	1	5	6.91	2.4	17	35.6
RI 480222	Rock	5	0.035	0.18	1	8	7.74	3.4	9	57.0
RI 480223	Rock	3	0.019	0.09	1	2	8.24	1.7	16	23.0
RI 480224	Rock	4	0.023	0.10	1	4	8.04	2.3	13	30.7
RI 480225	Rock	4	0.026	0.21	1	5	11.44	1.8	9	31.3
RI 480226	Rock	10	0.021	0.18	2	7	9.48	3.0	63	38.3
RI 480227	Rock	5	0.027	0.24	1	8	8.38	2.3	22	24.7
RI 480228	Rock	4	0.042	0.28	1	13	10.92	2.6	6	47.5
RI 480229	Rock	13	0.008	0.11	4	<1	5.29	1.9	45	16.7
RI 481019	Rock	7	0.013	0.14	2	6	9.14	2.6	65	24.8
RI 481511	Rock	5	0.012	0.11	1	<1	3.86	2.1	17	27.7
RI 481512	Rock	7	0.025	0.17	1	3	10.89	2.6	10	42.3
RI 481513	Rock	5	0.024	0.19	1	6	6.61	2.4	12	33.7
RI 481514	Rock	1	<0.005	0.02	0	<1	7.89	0.4	4	5.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 481515	Rock	2	0.007	0.04	0	<1	11.14	0.9	5	10.9
RI 481516	Rock	0	<0.005	<0.02	<0.1	<1	10.41	0.1	2	0.9
RI 481517	Rock	3	0.015	0.08	1	<1	8.84	1.6	25	20.7
RI 481518	Rock	1	0.009	0.04	0	<1	7.50	0.6	6	9.6
RI 481519	Rock	2	0.007	<0.02	0	<1	4.21	0.9	11	9.3
RI 481520	Rock	0	<0.005	<0.02	<0.1	<1	5.28	0.3	5	1.7
RI 481521	Rock	<0.2	<0.005	<0.02	<0.1	<1	10.73	<0.1	2	<0.5
RI 481522	Rock	<0.2	<0.005	<0.02	<0.1	<1	7.22	0.1	4	0.8
RI 481523	Rock	1	0.006	<0.02	0	<1	8.64	0.4	4	5.0
RI 481524	Rock	8	0.024	0.20	1	10	10.11	2.7	27	42.9
RI 481525	Rock	11	0.027	0.21	2	16	93.76	4.3	53	50.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Pb Pb-4A-OR-ICP % 0.01	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1
RI 480189	Rock		0.419												
RI 480189 Dup			0.432												
RI 480213	Rock		0.030												
RI 480213 Dup			0.031												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.730												
QCV1008-00304-0004-BLK			<0.005												
RI 481511	Rock		0.068												
RI 481511 Dup			0.096												
QCV1008-00304-0006-BLK			<0.005												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.701												
QCV1008-00305-0001-BLK					<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	0.01	<0.02	<0.1	<1
RI 480189	Rock				<0.01	2.88	9368.3	162	0.5	0.33	0.76	0.25	25.80	5.2	142
RI 480189 Dup					<0.01	2.87	9362.9	159	0.5	0.35	0.75	0.28	25.18	5.0	138
STD-ME-8 expected					61.70										
STD-ME-8 result					58.33	4.57	2639.4	592	0.9	3.96	6.75	99.76	20.94	<0.1	44
RI 480213	Rock				<0.01	2.36	629.2	139	0.7	0.17	<0.01	0.08	20.87	2.9	180
RI 480213 Dup					<0.01	2.40	638.6	143	0.7	0.18	<0.01	0.08	21.49	2.8	181
RI 481511	Rock				<0.01	1.94	454.8	81	0.5	0.13	0.01	0.10	23.50	1.2	246
RI 481511 Dup					<0.01	1.93	450.9	85	0.5	0.15	0.01	0.10	23.65	1.2	254
STD-ME-8 expected					61.70										
STD-ME-8 result					58.86	4.48	2612.2	578	1.0	3.77	6.63	100.26	20.79	<0.1	43
QCV1008-00305-0008-BLK					<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1
STD-SY-4 expected								340	2.6				122.00	2.8	12
STD-SY-4 result					<0.01	>10	12.3	339	3.2	0.08	5.68	0.07	110.06	3.8	8
QCV1008-01014-0001-BLK				<0.01											
RI 480204	Rock			1.78											
RI 480204 Dup				1.76											
QCV1008-01014-0003-BLK				<0.01											
STD-ME-8 expected				1.94											
STD-ME-8 result				2.05											

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cs 50-4A-UT ppm 0.05	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01
QCV1008-00305-0001-BLK		<0.05	<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01
RI 480189	Rock	1.2	7.0	2.41	5.1	0.8	1.16	0.03	0.76	12.5	8.5	0.24	332	0.62	0.71
RI 480189 Dup		1.1	7.2	2.36	4.6	0.8	1.10	0.02	0.75	12.1	8.4	0.24	320	0.59	0.71
STD-ME-8 expected			1030.0												
STD-ME-8 result		2.4	1021.0	3.71	7.1	0.3	1.02	0.09	1.40	10.2	15.0	0.72	3016	5.13	1.24
RI 480213	Rock	1.7	19.2	4.13	3.8	0.8	0.81	0.02	0.70	10.2	14.9	0.04	136	0.76	0.03
RI 480213 Dup		1.7	19.7	4.20	3.8	0.8	0.81	0.01	0.70	10.8	15.3	0.04	140	0.77	0.03
RI 481511	Rock	1.1	4.3	0.58	2.9	0.6	0.53	<0.01	0.47	10.3	5.0	0.03	26	0.79	0.02
RI 481511 Dup		1.6	4.4	0.59	3.1	0.7	1.43	0.01	0.48	11.1	5.0	0.03	26	0.77	0.02
STD-ME-8 expected			1030.0												
STD-ME-8 result		2.5	989.4	3.70	7.6	0.5	1.09	0.08	1.36	10.3	15.3	0.70	2930	4.82	1.20
QCV1008-00305-0008-BLK		<0.05	<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01
STD-SY-4 expected		1.5	7.0		35.0		10.60			58.0	37.0				
STD-SY-4 result		1.4	7.0	4.33	25.1	0.2	1.10	0.03	1.42	51.3	35.2	0.32	732	0.29	5.36

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Nb 50-4A-UT ppm 0.1	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05
QCV1008-00305-0001-BLK		<0.1	<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05
RI 480189	Rock	0.6	11.6	75	111.0	33.8	0.007	0.83	10.67	3.0	<0.5	0.9	48.8	0.07	0.07
RI 480189 Dup		0.6	11.8	74	106.4	32.5	<0.005	0.80	10.04	3.1	<0.5	0.8	46.8	0.07	0.06
STD-ME-8 expected					19400										
STD-ME-8 result		3.4	26.3	604	>10000	52.5	<0.005	1.52	57.25	7.0	1.6	2.5	370.2	0.28	0.72
RI 480213	Rock	0.5	9.6	475	27.0	28.4	<0.005	0.04	2.30	3.0	<0.5	0.5	86.1	<0.05	0.07
RI 480213 Dup		0.5	10.1	487	27.0	29.0	<0.005	0.04	2.35	2.9	<0.5	0.5	88.4	0.05	0.06
RI 481511	Rock	0.4	4.1	71	49.6	21.2	<0.005	<0.01	1.32	1.0	<0.5	0.9	9.3	0.06	0.06
RI 481511 Dup		0.4	4.5	68	50.8	27.9	<0.005	<0.01	1.34	1.1	<0.5	1.0	9.5	0.11	0.07
STD-ME-8 expected					19400										
STD-ME-8 result		3.3	27.2	599	>10000	54.3	0.007	1.80	57.82	6.9	<0.5	2.3	371.0	0.29	0.59
QCV1008-00305-0008-BLK		<0.1	<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05
STD-SY-4 expected		13.0	9.0		10.0	55.0				1.1			1191.0	0.90	
STD-SY-4 result		13.7	6.0	532	12.6	46.9	0.029	<0.01	<0.05	0.6	<0.5	8.3	1260.3	0.93	0.31

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02523-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Th 50-4A-UT ppm 0.2	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1008-00305-0001-BLK		<0.2	<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
RI 480189	Rock	9	0.023	0.20	1	11	8.04	3.7	22	38.9
RI 480189 Dup		9	0.023	0.19	1	10	8.13	3.6	22	38.3
STD-ME-8 expected									19200	
STD-ME-8 result		3	0.186	0.69	2	45	15.09	8.7	>10000	23.4
RI 480213	Rock	8	0.017	0.12	1	7	5.35	2.8	58	28.2
RI 480213 Dup		8	0.017	0.11	1	7	5.93	2.9	59	28.4
RI 481511	Rock	5	0.012	0.11	1	<1	3.86	2.1	17	27.7
RI 481511 Dup		5	0.012	0.10	1	<1	3.70	2.1	17	28.2
STD-ME-8 expected									19200	
STD-ME-8 result		3	0.182	0.74	1	47	20.35	9.0	>10000	23.2
QCV1008-00305-0008-BLK		<0.2	<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected		1			1	8		119.0	93	517.0
STD-SY-4 result		1	0.165	0.22	1	<1	9.21	98.7	94	54.0

Certificate of Analysis

10-360-02524-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 08/12/2010
Date Completed: 08/27/2010
Invoice:

Samples	Type	Preparation Description
78	Soil	SP-SS-1K/Soils, Humus Sediments 1kg dried, sieved and riffle split

Method	Description
50-AR-UT	50 Element, Aqua Regia, ICPMS, Ultra Trace Level
Au-1AT-AA	Au, 1AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 484547	Soil	0.460	0.35	0.81	494.6	36	0.3	0.39	<0.01	0.43	16.40	8.9	11	1.5	29.5
SI 484548	Soil	0.281	0.25	0.28	340.3	28	0.3	0.39	0.02	0.30	13.43	13.7	7	1.5	29.8
SI 484549	Soil	0.097	0.21	0.29	315.2	33	0.5	0.56	0.02	0.15	27.29	19.8	10	1.5	46.1
SI 484550	Soil	0.031	0.08	0.86	66.4	27	0.2	0.33	0.02	0.08	7.69	6.1	13	1.6	24.4
SI 484551	Soil	0.026	0.08	0.86	145.5	23	0.3	0.53	<0.01	0.10	16.35	15.4	15	1.4	42.7
SI 484552	Soil	0.005	<0.01	1.43	26.6	23	0.3	0.49	0.01	0.06	8.45	9.5	21	1.3	41.4
SI 484553	Soil	0.012	<0.01	0.94	44.6	26	0.2	0.54	0.01	0.09	6.29	9.4	13	1.5	31.5
SI 484554	Soil	0.058	0.17	1.19	128.5	20	0.5	0.79	0.02	0.09	9.50	13.6	19	2.1	50.2
SI 484555	Soil	0.077	0.27	0.51	96.8	32	0.6	1.16	<0.01	0.05	14.75	17.0	9	3.2	55.2
SI 484556	Soil	0.016	0.15	1.69	73.7	26	0.6	0.57	0.10	0.13	14.78	34.8	25	1.0	73.7
SI 484557	Soil	0.021	0.01	1.66	82.5	25	0.6	0.58	0.04	0.19	9.30	22.9	23	1.5	61.2
SI 484558	Soil	0.155	0.35	1.11	373.7	26	0.6	0.74	0.01	0.20	14.99	25.7	18	3.3	62.5
SI 484559	Soil	0.078	0.13	1.71	129.3	17	0.5	0.68	0.01	0.17	17.63	21.4	26	3.0	65.5
SI 484560	Soil	0.056	0.31	1.49	219.9	29	0.5	0.95	0.03	0.15	11.29	21.6	21	4.7	57.2
SI 484561	Soil	0.023	0.11	0.51	85.2	27	0.5	0.65	0.04	0.11	27.98	31.0	18	2.1	61.7
SI 484562	Soil	0.013	0.06	1.30	45.8	16	0.2	0.45	0.05	0.07	9.16	12.7	15	1.4	40.0
SI 484563	Soil	0.019	0.06	2.02	106.6	22	0.6	0.70	0.01	0.09	16.39	24.7	23	3.3	84.6
SI 484564	Soil	0.008	0.06	1.17	33.6	33	0.3	0.24	0.02	0.10	4.53	7.3	12	0.7	22.6
SI 484565	Soil	0.026	<0.01	1.02	96.8	21	0.3	0.47	0.04	0.07	7.54	13.6	13	1.2	37.3
SI 484566	Soil	0.086	0.47	0.80	626.3	35	0.4	1.12	0.04	0.26	12.56	22.7	16	1.1	78.3
SI 484567	Soil	0.056	0.05	0.72	256.5	25	0.4	0.52	0.05	0.15	15.59	24.6	13	1.0	59.5
SI 484568	Soil	0.018	0.07	0.50	103.5	34	0.3	0.46	0.05	0.23	5.63	14.7	10	1.0	37.1
SI 484569	Soil	0.014	0.21	0.98	89.4	25	0.4	0.66	0.02	0.33	12.95	18.3	21	1.9	82.9
SI 484570	Soil	0.122	0.15	0.96	372.6	27	0.4	0.67	0.03	0.16	16.85	22.7	17	1.5	49.3
SI 484571	Soil	0.008	0.26	1.98	49.8	36	0.2	0.40	0.04	0.12	14.35	19.2	28	2.0	36.3
SI 484572	Soil	0.006	<0.01	2.35	23.4	15	0.2	0.44	0.03	0.05	7.22	14.9	31	3.3	38.1
SI 484573	Soil	0.018	0.08	2.04	104.3	24	0.5	0.56	0.09	0.10	10.38	20.0	28	1.8	53.1
SI 484574	Soil	0.014	0.04	2.40	162.7	20	0.4	0.46	0.12	0.16	13.38	19.1	32	1.1	59.3
SI 484575	Soil	0.005	<0.01	1.82	27.7	27	0.7	0.35	0.11	0.09	10.47	19.6	24	1.2	59.0
SI 484576	Soil	<0.005	<0.01	1.86	11.3	27	0.7	0.33	0.10	0.08	11.38	16.0	23	0.6	58.2
SI 484577	Soil	<0.005	<0.01	2.84	28.8	17	0.3	0.41	0.08	0.05	18.05	22.6	38	1.8	55.5
SI 484578	Soil	<0.005	<0.01	2.20	12.1	21	0.4	0.44	0.10	0.07	10.97	19.4	29	1.1	47.4
SI 484579	Soil	<0.005	0.02	2.33	24.1	18	0.4	0.43	0.08	0.07	9.31	16.2	31	0.9	49.2
SI 484580	Soil	0.021	<0.01	1.49	48.2	16	0.2	0.26	0.05	0.06	8.60	7.8	18	0.9	24.0
SI 484581	Soil	0.006	0.30	1.87	51.3	28	0.2	0.40	0.04	0.13	8.81	26.5	31	1.7	37.1
SI 484582	Soil	0.031	0.03	1.11	113.0	37	0.4	0.59	<0.01	0.06	40.74	15.4	14	2.1	34.9
SI 484583	Soil	0.039	0.09	1.63	200.5	31	0.3	0.48	0.01	0.23	26.53	14.1	22	1.4	39.1
SI 484584	Soil	0.027	0.07	1.03	253.1	30	0.2	0.27	0.04	0.15	13.19	7.8	11	0.7	21.2
SI 484585	Soil	0.127	0.63	0.63	610.4	31	0.3	0.43	0.01	0.17	35.10	14.6	12	3.2	41.2
SI 484586	Soil	0.053	0.58	0.37	214.6	28	0.5	0.67	0.66	1.18	25.19	30.0	7	1.8	40.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 484587	Soil	0.175	0.05	0.90	561.3	28	0.3	0.56	0.01	0.15	21.40	18.9	15	1.2	50.4
SI 484588	Soil	0.028	0.14	1.06	97.7	28	0.3	0.61	0.05	0.18	13.18	14.7	16	1.5	55.0
SI 484589	Soil	0.021	<0.01	1.92	99.8	26	0.4	0.57	0.05	0.09	19.65	22.2	26	2.0	58.6
SI 484590	Soil	0.006	0.12	1.17	34.2	23	0.3	0.34	0.02	0.09	8.21	8.0	12	1.4	32.7
SI 484591	Soil	<0.005	0.05	1.15	31.8	25	0.2	0.27	0.01	0.07	10.58	6.2	13	1.5	26.0
SI 484592	Soil	0.072	0.05	1.26	82.5	25	0.3	0.64	0.04	0.05	17.52	9.9	18	3.3	43.1
SI 484593	Soil	0.092	0.13	1.26	409.4	33	0.9	0.71	0.19	0.27	33.03	39.9	17	2.6	55.6
SI 484594	Soil	0.115	0.20	1.55	304.4	30	0.8	0.59	0.23	0.14	28.76	37.2	20	1.5	95.1
SI 484595	Soil	0.007	0.05	0.42	23.9	14	0.1	0.10	0.02	0.04	5.26	1.5	3	0.4	5.6
SI 484596	Soil	0.106	0.34	0.66	292.8	24	0.3	0.22	0.04	0.14	14.67	7.4	7	1.0	24.5
SI 484597	Soil	0.022	0.19	0.72	323.4	37	0.2	0.34	0.03	0.13	23.01	8.4	10	2.1	31.2
SI 484598	Soil	0.006	<0.01	2.01	45.9	22	0.4	0.49	0.05	0.10	20.48	20.9	31	2.4	54.4
SI 484599	Soil	0.223	0.69	1.13	647.6	37	0.9	1.10	0.01	0.27	27.86	45.9	16	3.2	76.4
SI 484600	Soil	0.104	0.46	0.88	478.6	34	1.0	1.06	0.13	0.76	43.45	49.6	17	3.1	87.8
SI 484601	Soil	0.022	0.23	1.17	73.2	34	0.3	0.50	0.03	0.18	13.84	14.1	16	1.2	46.9
SI 484602	Soil	0.059	0.27	0.93	618.5	35	0.4	0.64	0.02	0.28	22.64	19.4	17	1.3	60.8
SI 484603	Soil	0.015	<0.01	0.64	166.7	25	0.1	0.16	0.04	0.09	8.92	3.5	5	0.6	13.1
SI 484604	Soil	0.007	0.08	0.77	31.6	24	0.1	0.14	0.05	0.09	6.02	1.8	4	0.4	7.2
SI 484605	Soil	0.022	0.17	0.85	180.3	37	0.2	0.37	0.01	0.12	14.20	8.9	14	1.3	29.4
SI 484606	Soil	0.055	0.11	0.67	167.7	28	0.2	0.21	0.02	0.17	11.93	3.5	7	1.3	11.7
SI 484607	Soil	0.318	0.01	2.17	130.0	27	0.4	0.57	0.10	0.20	10.88	19.2	28	2.9	49.6
SI 484608	Soil	0.015	0.33	0.88	144.4	78	0.3	0.42	0.03	0.29	14.71	11.6	13	1.6	28.2
SI 484609	Soil	0.026	0.13	1.10	387.8	39	0.3	0.43	0.08	0.23	15.84	9.5	18	1.1	28.5
SI 484610	Soil	0.013	0.16	0.57	226.4	67	0.2	0.28	0.08	0.44	8.99	8.0	8	1.0	18.9
SI 484611	Soil	0.007	0.05	1.72	102.8	40	0.4	0.56	0.02	0.15	29.48	13.0	26	2.7	33.2
SI 484612	Soil	0.009	<0.01	1.46	101.1	21	0.4	0.38	0.01	0.09	17.72	20.2	22	2.0	49.6
SI 484613	Soil	0.006	<0.01	0.95	40.6	41	0.2	0.33	0.02	0.08	15.54	8.1	13	1.8	24.1
SI 484614	Soil	0.011	0.08	0.78	103.3	25	0.3	0.36	0.02	0.10	16.74	15.5	13	1.2	41.6
SI 484615	Soil	0.019	0.01	0.22	134.1	21	0.2	0.39	0.01	0.06	12.06	10.5	5	1.1	46.7
SI 484616	Soil	0.230	0.40	0.28	983.8	29	0.3	0.43	0.04	0.10	21.00	16.6	4	1.3	44.6
SI 484617	Soil	0.102	0.25	1.22	1120.8	53	0.5	0.37	0.02	0.14	32.62	17.0	15	2.5	36.4
SI 484618	Soil	<0.005	<0.01	1.99	61.0	29	0.6	0.45	0.06	0.10	35.29	21.5	26	2.4	71.7
TI 481472	Soil	0.019	0.11	1.94	102.0	46	0.5	0.44	0.15	0.16	25.38	13.3	23	1.0	36.1
TI 481473	Soil	0.022	0.15	2.32	107.7	29	0.6	0.52	0.20	0.28	18.80	26.4	31	2.0	66.3
TI 481474	Soil	0.038	0.16	1.77	176.5	34	0.6	0.47	0.95	0.37	25.78	21.9	23	1.3	57.3
TI 481475	Soil	0.108	0.13	1.47	126.8	28	0.6	0.48	1.48	0.26	28.56	21.3	20	0.8	55.6
TI 481476	Soil	0.015	0.14	1.21	29.2	39	0.6	0.44	0.52	0.17	28.17	16.8	10	0.7	43.2
TI 481477	Soil	0.012	0.12	1.23	26.5	45	0.6	0.38	0.46	0.19	30.37	14.0	10	0.5	37.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 484547	Soil	3.17	2.6	<0.05	<0.02	0.08	0.02	9.7	12.3	0.18	440	0.55	<0.01	0.1	20.8
SI 484548	Soil	2.92	1.2	<0.05	<0.02	0.02	0.02	7.6	3.1	0.06	948	0.38	<0.01	<0.05	28.9
SI 484549	Soil	4.39	1.4	<0.05	<0.02	0.03	0.02	16.0	2.2	0.05	955	0.42	<0.01	0.1	46.2
SI 484550	Soil	2.72	3.6	<0.05	<0.02	0.01	0.02	4.1	9.2	0.15	241	0.66	0.01	0.2	14.5
SI 484551	Soil	4.71	3.1	<0.05	<0.02	0.02	0.02	9.6	13.7	0.22	497	0.77	<0.01	0.3	34.7
SI 484552	Soil	4.11	4.3	<0.05	<0.02	0.02	0.02	5.1	33.4	0.53	451	0.58	<0.01	0.1	29.3
SI 484553	Soil	3.12	3.6	<0.05	<0.02	0.02	0.02	3.6	16.1	0.27	456	0.62	0.01	0.2	19.6
SI 484554	Soil	5.03	3.2	<0.05	<0.02	0.03	0.03	5.4	22.6	0.41	464	0.78	<0.01	0.1	30.5
SI 484555	Soil	4.51	1.1	<0.05	<0.02	0.03	0.02	7.9	8.1	0.14	259	0.62	<0.01	<0.05	34.2
SI 484556	Soil	6.35	4.2	<0.05	<0.02	0.02	0.02	8.4	44.3	0.73	902	0.61	<0.01	<0.05	61.3
SI 484557	Soil	4.84	4.7	<0.05	0.02	0.03	0.03	5.0	40.0	0.62	744	0.69	<0.01	0.1	40.0
SI 484558	Soil	5.18	3.2	<0.05	<0.02	0.03	0.03	8.7	21.6	0.35	813	0.91	<0.01	0.1	45.6
SI 484559	Soil	5.30	4.5	<0.05	<0.02	0.03	0.02	10.5	50.6	0.68	653	1.37	<0.01	<0.05	46.5
SI 484560	Soil	4.98	4.0	<0.05	<0.02	0.03	0.04	6.3	33.0	0.50	678	0.60	<0.01	0.2	38.0
SI 484561	Soil	4.35	2.2	<0.05	0.04	0.02	0.02	17.3	15.0	0.21	926	0.35	<0.01	<0.05	59.5
SI 484562	Soil	3.16	3.5	<0.05	<0.02	0.02	0.03	5.0	32.4	0.48	410	0.49	0.01	0.2	27.0
SI 484563	Soil	5.56	4.7	<0.05	<0.02	0.03	0.02	9.6	52.3	0.80	570	0.70	<0.01	<0.05	46.5
SI 484564	Soil	2.04	2.8	<0.05	<0.02	0.01	0.01	2.4	15.8	0.24	338	0.32	<0.01	0.2	13.6
SI 484565	Soil	3.23	2.9	<0.05	<0.02	0.02	0.02	4.1	22.5	0.32	579	0.36	<0.01	0.1	26.5
SI 484566	Soil	5.09	2.5	<0.05	<0.02	0.04	0.02	6.4	15.9	0.28	1883	0.56	<0.01	0.1	43.6
SI 484567	Soil	4.73	2.2	<0.05	<0.02	0.02	0.02	8.8	17.4	0.30	798	0.50	<0.01	<0.05	46.0
SI 484568	Soil	3.27	2.1	<0.05	<0.02	0.02	0.03	3.0	6.9	0.13	1115	0.43	<0.01	0.1	27.0
SI 484569	Soil	4.42	2.9	<0.05	<0.02	0.03	0.02	6.9	20.1	0.36	990	0.46	<0.01	<0.05	42.2
SI 484570	Soil	4.73	4.4	<0.05	<0.02	0.03	0.02	9.1	39.2	0.63	1090	0.61	<0.01	0.1	38.9
SI 484571	Soil	4.43	6.4	<0.05	<0.02	0.02	0.02	6.6	46.3	0.79	1798	0.55	<0.01	0.1	36.2
SI 484572	Soil	4.67	6.5	<0.05	<0.02	0.02	0.02	3.1	49.9	0.96	563	0.55	<0.01	<0.05	36.4
SI 484573	Soil	4.19	5.9	<0.05	<0.02	0.02	0.03	5.1	56.7	0.95	673	0.75	<0.01	<0.05	37.9
SI 484574	Soil	4.93	6.5	<0.05	<0.02	0.02	0.02	6.7	69.7	1.20	843	0.40	<0.01	<0.05	45.9
SI 484575	Soil	3.69	4.9	<0.05	0.05	0.01	0.02	4.7	64.7	1.00	1168	0.28	<0.01	<0.05	44.4
SI 484576	Soil	3.62	4.8	<0.05	<0.02	0.01	0.02	4.8	58.6	1.18	1408	0.24	<0.01	<0.05	39.6
SI 484577	Soil	5.49	8.0	<0.05	<0.02	0.02	0.01	9.1	77.7	1.35	705	0.34	<0.01	<0.05	48.9
SI 484578	Soil	4.37	5.8	<0.05	<0.02	0.01	0.02	5.3	63.4	1.22	848	0.38	<0.01	<0.05	44.3
SI 484579	Soil	4.70	6.4	<0.05	<0.02	0.01	0.03	4.1	66.9	1.20	635	0.36	<0.01	<0.05	45.3
SI 484580	Soil	2.62	4.7	<0.05	<0.02	0.01	0.01	4.2	34.3	0.61	333	0.47	0.01	0.1	22.6
SI 484581	Soil	5.31	7.2	<0.05	<0.02	0.02	0.02	4.4	33.4	0.61	1429	0.46	<0.01	0.1	30.3
SI 484582	Soil	3.57	3.1	<0.05	<0.02	0.02	0.03	25.1	22.0	0.37	631	0.38	<0.01	0.1	32.5
SI 484583	Soil	4.34	4.5	<0.05	<0.02	0.03	0.02	14.4	36.6	0.59	685	0.55	<0.01	0.1	35.5
SI 484584	Soil	2.93	3.5	<0.05	<0.02	0.02	0.03	7.1	7.3	0.15	635	0.52	0.02	0.3	14.0
SI 484585	Soil	4.77	2.3	<0.05	<0.02	0.07	0.03	19.7	6.6	0.10	433	0.54	<0.01	0.1	30.9
SI 484586	Soil	3.73	1.4	<0.05	<0.02	0.05	0.03	14.2	2.9	0.08	2114	0.60	0.01	0.1	55.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 484587	Soil	5.10	3.2	<0.05	<0.02	0.03	0.03	12.0	16.1	0.27	904	0.66	<0.01	0.2	38.8
SI 484588	Soil	4.13	3.1	<0.05	<0.02	0.02	0.03	7.6	25.2	0.38	523	0.36	<0.01	0.1	40.6
SI 484589	Soil	5.47	5.4	<0.05	<0.02	0.03	0.03	11.4	48.9	0.77	726	0.69	<0.01	0.2	46.4
SI 484590	Soil	2.44	3.3	<0.05	<0.02	0.02	0.02	4.7	22.1	0.32	243	0.41	0.01	0.2	21.9
SI 484591	Soil	2.49	3.9	<0.05	<0.02	0.01	0.02	6.3	20.8	0.28	264	0.35	0.01	0.2	15.8
SI 484592	Soil	4.58	4.7	<0.05	<0.02	0.02	0.02	10.2	29.2	0.37	370	1.41	0.01	0.2	20.8
SI 484593	Soil	5.24	3.5	<0.05	<0.02	0.04	0.02	19.4	34.6	0.42	4643	0.51	<0.01	<0.05	63.0
SI 484594	Soil	6.42	4.3	<0.05	<0.02	0.04	0.02	16.2	42.5	0.67	3000	0.45	<0.01	<0.05	77.4
SI 484595	Soil	0.49	1.8	<0.05	<0.02	<0.01	0.02	2.8	2.9	0.06	65	0.21	0.02	0.1	3.2
SI 484596	Soil	2.11	2.2	<0.05	<0.02	0.01	0.02	7.9	10.4	0.18	474	0.31	0.01	0.1	18.5
SI 484597	Soil	2.33	3.0	<0.05	<0.02	0.02	0.02	12.2	6.6	0.13	240	0.59	0.01	0.1	21.2
SI 484598	Soil	4.69	5.5	<0.05	<0.02	0.03	0.03	11.9	61.2	0.89	872	0.63	<0.01	0.3	44.8
SI 484599	Soil	6.75	3.7	<0.05	<0.02	0.05	0.03	14.8	26.4	0.38	2579	1.48	<0.01	0.1	68.0
SI 484600	Soil	6.63	2.9	<0.05	<0.02	0.06	0.02	24.9	24.4	0.34	2982	1.11	<0.01	<0.05	81.5
SI 484601	Soil	3.85	3.3	<0.05	<0.02	0.02	0.02	8.1	31.4	0.44	444	0.28	<0.01	<0.05	40.2
SI 484602	Soil	5.46	3.3	<0.05	<0.02	0.04	0.02	12.9	19.0	0.30	1433	0.62	<0.01	0.1	42.8
SI 484603	Soil	1.32	2.4	<0.05	<0.02	0.01	0.02	4.7	4.2	0.07	216	0.34	0.02	0.1	7.0
SI 484604	Soil	0.81	2.7	<0.05	<0.02	<0.01	0.02	3.1	2.1	0.04	77	0.30	0.02	0.2	3.7
SI 484605	Soil	3.34	4.1	<0.05	<0.02	0.02	0.03	8.0	9.9	0.17	567	0.60	<0.01	0.2	19.7
SI 484606	Soil	1.57	2.4	<0.05	<0.02	0.03	0.02	7.1	9.1	0.12	115	0.29	0.01	0.1	10.3
SI 484607	Soil	5.21	5.5	<0.05	<0.02	0.03	0.03	5.2	52.1	0.91	846	0.72	<0.01	0.1	44.2
SI 484608	Soil	3.39	4.2	<0.05	<0.02	0.03	0.03	7.1	9.7	0.15	2120	0.72	<0.01	0.2	20.3
SI 484609	Soil	4.55	4.7	<0.05	<0.02	0.02	0.04	8.5	15.8	0.28	472	0.68	<0.01	0.3	22.8
SI 484610	Soil	2.04	3.0	<0.05	<0.02	0.01	0.05	5.0	4.0	0.08	893	0.51	0.01	0.1	12.2
SI 484611	Soil	4.05	6.4	<0.05	<0.02	0.03	0.04	15.3	39.1	0.60	770	1.11	<0.01	0.7	31.1
SI 484612	Soil	4.34	4.7	<0.05	<0.02	0.02	0.01	9.5	43.6	0.67	1274	0.58	<0.01	0.1	43.9
SI 484613	Soil	4.29	4.5	<0.05	<0.02	0.01	0.02	8.6	10.9	0.66	750	0.79	0.01	0.3	14.4
SI 484614	Soil	3.05	3.0	<0.05	<0.02	0.02	0.02	8.9	16.1	0.28	619	0.82	<0.01	0.1	32.3
SI 484615	Soil	2.51	0.8	<0.05	<0.02	0.02	0.02	7.2	1.7	0.03	382	0.58	<0.01	<0.05	28.2
SI 484616	Soil	3.36	0.9	<0.05	<0.02	0.03	0.03	11.8	2.4	0.05	638	0.82	<0.01	<0.05	42.5
SI 484617	Soil	4.40	3.8	<0.05	<0.02	0.02	0.04	17.6	23.6	0.43	1226	0.86	<0.01	0.2	39.7
SI 484618	Soil	4.86	5.1	<0.05	<0.02	0.02	0.03	19.0	60.2	0.98	744	0.80	<0.01	0.4	40.8
TI 481472	Soil	4.00	4.1	<0.05	<0.02	0.02	0.04	14.0	51.9	0.87	353	1.03	<0.01	0.2	38.4
TI 481473	Soil	5.00	5.5	<0.05	<0.02	0.02	0.03	10.4	73.0	1.10	1102	1.21	0.01	0.1	50.3
TI 481474	Soil	5.05	3.8	<0.05	<0.02	0.03	0.03	13.6	49.5	0.82	818	1.09	<0.01	0.1	49.8
TI 481475	Soil	4.92	3.5	<0.05	<0.02	0.03	0.02	15.2	44.8	0.70	686	0.98	<0.01	<0.05	51.2
TI 481476	Soil	4.15	2.3	<0.05	0.05	0.04	0.04	14.2	22.6	0.40	331	0.46	<0.01	0.1	41.2
TI 481477	Soil	3.86	2.4	<0.05	<0.02	0.04	0.03	15.6	22.4	0.40	333	0.40	<0.01	0.2	34.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 484547	Soil	585	159.8	3.6	<0.01	0.03	1.23	0.5	0.3	0.3	12.2	<0.01	0.08	1	<0.005
SI 484548	Soil	403	64.2	2.1	<0.01	0.02	1.65	0.7	0.5	0.2	21.1	<0.01	0.10	1	<0.005
SI 484549	Soil	628	57.0	2.0	<0.01	0.02	3.47	1.3	<0.2	0.3	25.8	<0.01	0.14	2	<0.005
SI 484550	Soil	1088	23.3	4.4	<0.01	0.07	0.80	0.2	0.3	0.2	5.2	<0.01	0.08	<0.2	<0.005
SI 484551	Soil	637	29.3	3.9	<0.01	0.03	1.74	0.7	0.4	0.4	7.2	<0.01	0.13	1	<0.005
SI 484552	Soil	865	28.8	3.0	<0.01	0.04	0.34	0.5	0.5	<0.2	5.1	<0.01	0.10	1	<0.005
SI 484553	Soil	761	29.9	3.1	<0.01	0.05	0.98	0.4	0.3	<0.2	4.9	<0.01	0.05	1	<0.005
SI 484554	Soil	874	49.5	2.9	<0.01	0.03	1.86	0.9	0.7	<0.2	6.4	<0.01	0.17	2	<0.005
SI 484555	Soil	629	82.6	2.0	<0.01	0.04	0.93	1.5	0.5	0.2	41.8	<0.01	0.17	4	<0.005
SI 484556	Soil	791	60.8	1.4	<0.01	<0.01	0.87	1.6	<0.2	<0.2	13.1	<0.01	0.11	7	<0.005
SI 484557	Soil	1169	76.0	3.2	<0.01	0.04	0.64	0.8	0.5	<0.2	8.4	<0.01	0.16	1	<0.005
SI 484558	Soil	856	90.9	3.8	<0.01	0.03	2.74	1.0	0.6	0.3	13.5	<0.01	0.15	2	<0.005
SI 484559	Soil	634	47.3	2.3	<0.01	0.02	1.82	0.9	0.4	<0.2	5.2	<0.01	0.18	2	<0.005
SI 484560	Soil	945	107.6	4.0	<0.01	0.04	1.92	0.7	0.6	<0.2	10.3	<0.01	0.14	1	<0.005
SI 484561	Soil	478	40.3	1.5	<0.01	<0.01	2.70	2.2	<0.2	<0.2	7.2	<0.01	0.08	14	<0.005
SI 484562	Soil	725	39.8	3.0	<0.01	0.03	0.60	0.8	0.5	<0.2	6.1	<0.01	0.10	2	0.007
SI 484563	Soil	669	78.0	3.0	<0.01	0.02	1.15	1.6	0.3	<0.2	8.4	<0.01	0.14	5	<0.005
SI 484564	Soil	662	19.6	1.8	<0.01	0.06	0.25	0.2	0.5	<0.2	4.1	<0.01	0.02	<0.2	<0.005
SI 484565	Soil	737	67.9	2.1	<0.01	0.03	1.65	0.6	0.3	<0.2	6.7	<0.01	0.06	1	<0.005
SI 484566	Soil	770	182.1	2.7	<0.01	0.02	1.77	1.3	0.4	<0.2	21.8	<0.01	0.08	1	<0.005
SI 484567	Soil	590	59.4	1.6	<0.01	<0.01	1.08	1.5	0.3	<0.2	9.6	<0.01	0.06	5	<0.005
SI 484568	Soil	1121	48.6	3.5	<0.01	0.07	0.66	0.3	0.4	<0.2	8.3	<0.01	0.09	0	<0.005
SI 484569	Soil	641	117.9	2.4	<0.01	0.02	0.85	1.2	0.5	<0.2	7.9	<0.01	0.11	2	<0.005
SI 484570	Soil	666	157.7	2.9	<0.01	0.01	0.73	1.1	0.5	<0.2	7.4	<0.01	0.13	2	<0.005
SI 484571	Soil	1088	59.8	2.8	<0.01	0.03	<0.05	0.9	<0.2	<0.2	5.9	<0.01	0.07	1	<0.005
SI 484572	Soil	660	38.5	2.0	<0.01	0.02	<0.05	0.9	0.2	<0.2	3.4	<0.01	0.10	1	<0.005
SI 484573	Soil	538	56.8	1.8	<0.01	0.03	<0.05	0.9	<0.2	<0.2	5.6	<0.01	0.10	1	<0.005
SI 484574	Soil	441	41.2	1.1	<0.01	0.01	<0.05	1.6	<0.2	<0.2	5.5	<0.01	0.06	3	<0.005
SI 484575	Soil	501	26.0	1.9	<0.01	0.02	<0.05	1.5	<0.2	<0.2	6.2	<0.01	0.08	3	<0.005
SI 484576	Soil	557	14.4	1.5	<0.01	0.01	<0.05	1.3	<0.2	<0.2	6.2	<0.01	0.07	2	<0.005
SI 484577	Soil	467	37.0	1.3	<0.01	<0.01	<0.05	1.9	<0.2	<0.2	4.0	<0.01	0.05	4	<0.005
SI 484578	Soil	559	25.3	1.8	<0.01	0.02	<0.05	0.8	<0.2	<0.2	6.3	<0.01	0.07	1	<0.005
SI 484579	Soil	577	26.6	1.3	<0.01	0.02	<0.05	0.9	<0.2	<0.2	5.0	<0.01	0.06	1	<0.005
SI 484580	Soil	551	41.8	1.2	<0.01	0.02	<0.05	0.7	0.4	<0.2	4.0	<0.01	0.01	0	<0.005
SI 484581	Soil	1200	42.8	2.2	<0.01	0.06	0.27	0.5	0.6	<0.2	6.7	<0.01	0.04	0	<0.005
SI 484582	Soil	428	25.9	3.5	<0.01	0.02	0.19	0.9	0.3	<0.2	15.1	<0.01	0.10	2	<0.005
SI 484583	Soil	638	48.5	4.1	<0.01	0.03	0.42	0.7	<0.2	<0.2	8.0	<0.01	0.08	1	<0.005
SI 484584	Soil	704	66.1	3.4	<0.01	0.05	0.72	0.3	0.5	0.2	7.5	<0.01	0.03	<0.2	0.008
SI 484585	Soil	490	170.0	3.8	<0.01	0.03	2.57	1.1	0.3	0.7	17.4	<0.01	0.04	2	<0.005
SI 484586	Soil	521	69.7	2.2	<0.01	0.02	3.45	1.8	0.4	0.2	20.3	<0.01	0.13	2	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 484587	Soil	774	78.3	4.3	<0.01	0.03	1.85	0.8	0.5	<0.2	9.9	<0.01	0.07	1	<0.005
SI 484588	Soil	734	72.8	2.8	<0.01	0.03	0.85	0.6	0.4	<0.2	11.1	<0.01	0.10	1	<0.005
SI 484589	Soil	916	46.1	4.3	<0.01	0.02	0.66	1.3	0.5	0.2	7.7	<0.01	0.09	2	0.007
SI 484590	Soil	717	29.9	3.1	<0.01	0.06	0.45	0.2	0.5	<0.2	4.7	<0.01	0.04	<0.2	<0.005
SI 484591	Soil	700	15.3	4.0	<0.01	0.05	0.22	0.2	0.3	<0.2	4.3	<0.01	0.06	<0.2	<0.005
SI 484592	Soil	774	42.7	3.3	<0.01	0.03	4.69	0.6	0.6	<0.2	8.6	<0.01	0.17	1	0.006
SI 484593	Soil	447	91.2	3.0	<0.01	0.02	0.60	2.1	0.4	<0.2	10.2	<0.01	0.13	3	<0.005
SI 484594	Soil	338	47.4	1.6	<0.01	0.02	1.11	4.2	0.3	<0.2	13.3	<0.01	0.11	7	<0.005
SI 484595	Soil	425	6.8	1.8	<0.01	0.03	0.36	<0.1	0.6	<0.2	4.7	<0.01	<0.01	<0.2	<0.005
SI 484596	Soil	718	18.0	2.4	<0.01	0.04	1.30	0.4	0.7	<0.2	9.5	<0.01	0.02	<0.2	<0.005
SI 484597	Soil	1072	30.6	4.2	<0.01	0.05	1.87	0.3	0.4	<0.2	10.9	<0.01	0.04	<0.2	<0.005
SI 484598	Soil	694	40.9	3.9	<0.01	0.01	0.26	1.6	0.3	0.2	5.4	<0.01	0.03	5	0.006
SI 484599	Soil	708	98.3	3.5	<0.01	0.03	4.54	2.1	0.6	<0.2	6.5	<0.01	0.24	3	<0.005
SI 484600	Soil	1093	77.7	2.0	<0.01	0.02	3.11	3.7	0.4	0.2	12.8	<0.01	0.21	9	<0.005
SI 484601	Soil	681	69.3	2.7	<0.01	0.02	0.95	0.5	0.3	<0.2	8.3	<0.01	0.09	1	<0.005
SI 484602	Soil	1096	116.7	3.4	<0.01	0.03	1.73	0.5	0.6	<0.2	10.2	<0.01	0.14	1	<0.005
SI 484603	Soil	523	42.6	2.4	<0.01	0.03	0.49	0.1	0.4	<0.2	7.4	<0.01	0.02	<0.2	0.005
SI 484604	Soil	485	14.3	1.6	<0.01	0.03	0.06	0.1	0.5	<0.2	6.4	<0.01	<0.01	<0.2	0.006
SI 484605	Soil	1030	47.7	4.2	<0.01	0.06	0.85	0.2	0.6	0.2	6.7	<0.01	0.06	<0.2	<0.005
SI 484606	Soil	548	81.3	2.8	<0.01	0.03	0.43	0.2	0.3	<0.2	7.9	<0.01	0.01	<0.2	<0.005
SI 484607	Soil	795	45.0	2.6	<0.01	0.02	0.94	0.8	<0.2	<0.2	11.3	<0.01	0.05	1	<0.005
SI 484608	Soil	880	32.3	4.7	<0.01	0.05	0.79	0.3	0.4	0.3	6.6	<0.01	0.03	<0.2	<0.005
SI 484609	Soil	974	37.5	6.5	<0.01	0.07	0.68	0.2	0.5	0.2	10.5	<0.01	0.06	<0.2	<0.005
SI 484610	Soil	1075	31.1	7.2	<0.01	0.08	0.45	0.1	0.6	<0.2	11.6	<0.01	0.02	<0.2	<0.005
SI 484611	Soil	676	32.1	6.3	<0.01	0.03	0.64	0.8	0.7	0.6	11.5	<0.01	0.09	0	0.015
SI 484612	Soil	1013	23.7	2.5	<0.01	0.04	0.79	0.8	0.5	<0.2	11.1	<0.01	0.08	1	<0.005
SI 484613	Soil	1030	18.0	4.2	<0.01	0.05	0.14	0.2	0.5	0.2	10.9	<0.01	0.05	<0.2	<0.005
SI 484614	Soil	698	35.5	2.5	<0.01	0.03	1.83	0.4	0.4	<0.2	6.9	<0.01	0.05	<0.2	<0.005
SI 484615	Soil	294	26.1	2.2	<0.01	0.01	3.22	1.3	0.4	<0.2	25.4	<0.01	0.10	1	<0.005
SI 484616	Soil	415	31.0	2.6	<0.01	0.02	6.42	0.9	<0.2	<0.2	33.5	<0.01	0.07	0	<0.005
SI 484617	Soil	579	26.2	5.3	<0.01	0.06	3.39	1.2	0.6	0.2	41.9	<0.01	0.06	1	<0.005
SI 484618	Soil	557	23.6	3.8	<0.01	0.02	0.78	1.4	0.3	0.2	8.1	<0.01	0.04	2	0.009
TI 481472	Soil	647	30.6	4.7	<0.01	0.03	<0.05	1.3	0.5	<0.2	11.9	<0.01	0.04	2	<0.005
TI 481473	Soil	750	38.8	2.5	<0.01	0.03	<0.05	1.9	1.2	<0.2	11.8	<0.01	0.03	3	<0.005
TI 481474	Soil	881	46.7	2.9	<0.01	0.04	2.10	2.2	0.6	<0.2	43.1	<0.01	0.10	3	<0.005
TI 481475	Soil	714	39.6	2.2	<0.01	0.02	1.74	2.6	0.7	<0.2	59.0	<0.01	0.06	4	<0.005
TI 481476	Soil	632	40.3	2.5	<0.01	0.03	0.52	2.7	1.0	<0.2	57.7	<0.01	0.05	8	<0.005
TI 481477	Soil	544	37.7	2.4	<0.01	0.03	0.43	2.4	0.7	<0.2	48.1	<0.01	0.04	5	<0.005

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 484547	Soil	<0.05	1	10	2.47	1.4	168	<0.5
SI 484548	Soil	<0.05	1	5	2.26	1.9	126	<0.5
SI 484549	Soil	<0.05	2	10	1.68	3.0	125	<0.5
SI 484550	Soil	<0.05	1	14	2.99	1.3	48	<0.5
SI 484551	Soil	<0.05	1	14	2.38	1.7	107	<0.5
SI 484552	Soil	<0.05	1	12	1.18	1.2	91	0.6
SI 484553	Soil	<0.05	1	11	3.01	1.1	62	0.5
SI 484554	Soil	<0.05	2	14	3.01	1.5	108	<0.5
SI 484555	Soil	0.09	2	8	2.65	1.9	118	<0.5
SI 484556	Soil	<0.05	2	14	3.32	3.7	157	<0.5
SI 484557	Soil	<0.05	2	15	2.70	2.3	115	1.3
SI 484558	Soil	0.05	2	13	4.80	2.4	140	<0.5
SI 484559	Soil	<0.05	2	15	3.91	2.6	129	<0.5
SI 484560	Soil	0.07	2	14	2.78	2.4	123	0.6
SI 484561	Soil	<0.05	2	13	2.40	3.6	144	3.3
SI 484562	Soil	<0.05	1	12	2.08	1.7	75	1.0
SI 484563	Soil	<0.05	2	13	2.20	2.3	130	<0.5
SI 484564	Soil	<0.05	1	8	2.01	1.0	43	<0.5
SI 484565	Soil	<0.05	1	11	2.11	1.3	80	1.0
SI 484566	Soil	<0.05	2	11	2.94	4.2	151	<0.5
SI 484567	Soil	<0.05	2	10	1.41	3.3	137	<0.5
SI 484568	Soil	<0.05	1	11	6.50	1.2	87	<0.5
SI 484569	Soil	<0.05	1	12	4.71	3.2	118	<0.5
SI 484570	Soil	<0.05	1	14	50.74	2.4	165	<0.5
SI 484571	Soil	<0.05	1	16	2.67	2.2	96	<0.5
SI 484572	Soil	<0.05	1	16	2.08	1.0	93	0.6
SI 484573	Soil	<0.05	1	15	2.49	2.1	99	0.6
SI 484574	Soil	<0.05	1	15	0.75	2.5	121	<0.5
SI 484575	Soil	<0.05	2	13	1.78	2.9	92	2.1
SI 484576	Soil	<0.05	1	13	0.87	3.6	86	<0.5
SI 484577	Soil	<0.05	2	18	3.12	2.8	113	0.7
SI 484578	Soil	<0.05	1	15	2.80	1.7	105	0.5
SI 484579	Soil	<0.05	1	15	2.09	2.0	106	<0.5
SI 484580	Soil	<0.05	1	11	1.88	1.2	59	0.9
SI 484581	Soil	<0.05	1	17	1.91	1.6	87	0.5
SI 484582	Soil	<0.05	1	10	1.38	2.6	89	<0.5
SI 484583	Soil	<0.05	1	15	10.67	2.1	101	<0.5
SI 484584	Soil	<0.05	1	15	3.68	1.5	58	<0.5
SI 484585	Soil	0.05	1	13	2.42	2.3	187	<0.5
SI 484586	Soil	<0.05	1	7	2.47	6.9	222	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 484587	Soil	<0.05	2	15	3.54	2.4	131	<0.5
SI 484588	Soil	<0.05	2	12	2.83	2.7	113	<0.5
SI 484589	Soil	<0.05	2	19	3.52	2.8	121	<0.5
SI 484590	Soil	<0.05	1	9	5.52	1.4	57	<0.5
SI 484591	Soil	<0.05	1	12	2.44	1.0	47	<0.5
SI 484592	Soil	<0.05	1	16	2.72	1.5	66	<0.5
SI 484593	Soil	<0.05	2	11	1.85	9.0	109	<0.5
SI 484594	Soil	<0.05	1	12	5.44	11.0	167	1.8
SI 484595	Soil	<0.05	0	8	2.91	0.8	12	<0.5
SI 484596	Soil	<0.05	1	10	3.47	4.0	49	<0.5
SI 484597	Soil	<0.05	1	16	3.35	1.9	63	<0.5
SI 484598	Soil	<0.05	1	16	3.31	2.3	102	<0.5
SI 484599	Soil	0.07	2	13	2.21	7.3	145	0.6
SI 484600	Soil	0.09	3	13	4.18	12.8	185	0.8
SI 484601	Soil	<0.05	1	11	2.96	3.1	99	<0.5
SI 484602	Soil	<0.05	2	14	2.87	2.6	150	<0.5
SI 484603	Soil	<0.05	1	10	3.21	1.0	29	<0.5
SI 484604	Soil	<0.05	0	9	3.30	0.8	14	<0.5
SI 484605	Soil	<0.05	1	16	3.30	1.3	69	<0.5
SI 484606	Soil	<0.05	1	6	3.57	1.2	43	<0.5
SI 484607	Soil	<0.05	1	15	7.20	2.1	116	<0.5
SI 484608	Soil	<0.05	1	19	3.66	2.8	71	<0.5
SI 484609	Soil	<0.05	1	19	5.58	2.2	77	<0.5
SI 484610	Soil	<0.05	1	12	1.96	0.9	57	<0.5
SI 484611	Soil	0.07	1	31	4.12	3.4	84	<0.5
SI 484612	Soil	<0.05	1	17	3.11	2.2	102	0.7
SI 484613	Soil	<0.05	0	19	3.99	1.4	42	<0.5
SI 484614	Soil	<0.05	1	16	3.73	1.7	80	<0.5
SI 484615	Soil	<0.05	0	7	3.19	2.5	69	<0.5
SI 484616	Soil	<0.05	1	5	2.99	3.4	89	<0.5
SI 484617	Soil	<0.05	1	15	2.93	3.2	88	<0.5
SI 484618	Soil	<0.05	1	24	3.22	3.5	99	<0.5
TI 481472	Soil	<0.05	2	14	1.03	5.6	97	0.5
TI 481473	Soil	<0.05	4	16	4.01	7.5	120	<0.5
TI 481474	Soil	<0.05	3	12	1.02	9.8	134	0.8
TI 481475	Soil	<0.05	2	11	3.60	9.9	121	1.2
TI 481476	Soil	<0.05	3	8	4.28	12.0	108	5.4
TI 481477	Soil	<0.05	2	9	3.28	13.8	94	2.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 484547	Soil	0.460													
SI 484547 Dup		0.274													
SI 484565	Soil	0.026													
SI 484565 Dup		0.030													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.747													
QCV1008-00302-0004-BLK		<0.005													
SI 484583	Soil	0.039													
SI 484583 Dup		0.042													
SI 484601	Soil	0.022													
SI 484601 Dup		0.021													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.764													
QCV1008-00302-0008-BLK		<0.005													
TI 481472	Soil	0.019													
TI 481472 Dup		0.027													
QCV1008-00303-0001-BLK			<0.01	<0.01	0.8	<5	<0.05	0.04	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
SI 484547	Soil		0.35	0.81	494.6	36	0.3	0.39	<0.01	0.43	16.40	8.9	11	1.5	29.5
SI 484547 Dup			0.30	0.81	482.4	35	0.2	0.38	<0.01	0.43	16.34	9.1	11	1.4	28.8
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.46	3.15	5.3	184	0.6	0.20	0.23	0.10	33.10	101.2	776	0.7	597.3
SI 484565	Soil		<0.01	1.02	96.8	21	0.3	0.47	0.04	0.07	7.54	13.6	13	1.2	37.3
SI 484565 Dup			<0.01	1.04	99.9	22	0.3	0.46	0.04	0.08	8.00	14.1	14	1.2	37.1
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.25	3.17	5.5	197	0.7	0.20	0.24	0.10	35.28	101.3	777	0.7	601.1
SI 484583	Soil		0.09	1.63	200.5	31	0.3	0.48	0.01	0.23	26.53	14.1	22	1.4	39.1
SI 484583 Dup			0.11	1.64	189.3	31	0.3	0.47	0.01	0.22	25.14	14.6	22	1.4	38.7
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.22	3.32	6.2	200	0.6	0.22	0.23	0.11	35.91	101.7	805	0.9	618.5
SI 484601	Soil		0.23	1.17	73.2	34	0.3	0.50	0.03	0.18	13.84	14.1	16	1.2	46.9
SI 484601 Dup			0.17	1.18	72.8	32	0.3	0.51	0.03	0.18	13.87	13.8	16	1.2	46.7
STD-ME-6 expected			101.00												6130.0
STD-ME-6 result			96.65	1.19	309.3	76	0.2	6.08	0.61	34.45	8.80	12.5	32	0.3	6597.2
TI 481472	Soil		0.11	1.94	102.0	46	0.5	0.44	0.15	0.16	25.38	13.3	23	1.0	36.1
TI 481472 Dup			0.10	1.94	100.8	45	0.5	0.45	0.15	0.16	24.49	12.9	23	1.0	35.4
QCV1008-00303-0011-BLK			<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
STD-OREAS-45P-AR expected			0.30		4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result			0.30	3.39	7.4	191	0.7	0.19	0.24	0.10	34.72	103.4	815	0.8	629.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
QCV1008-00303-0001-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
SI 484547	Soil	3.17	2.6	<0.05	<0.02	0.08	0.02	9.7	12.3	0.18	440	0.55	<0.01	0.1	20.8
SI 484547 Dup		3.20	2.6	<0.05	<0.02	0.08	0.02	10.0	12.3	0.18	435	0.51	<0.01	0.1	20.9
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	16.0	0.1	0.49	0.09	0.06	15.1	4.3	0.09	1190	1.01	0.02	0.5	253.4
SI 484565	Soil	3.23	2.9	<0.05	<0.02	0.02	0.02	4.1	22.5	0.32	579	0.36	<0.01	0.1	26.5
SI 484565 Dup		3.29	3.0	<0.05	<0.02	0.02	0.02	4.2	22.6	0.32	581	0.36	<0.01	0.1	27.8
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	17.3	0.1	0.51	0.10	0.06	16.0	4.4	0.09	1198	1.11	0.02	0.6	276.5
SI 484583	Soil	4.34	4.5	<0.05	<0.02	0.03	0.02	14.4	36.6	0.59	685	0.55	<0.01	0.1	35.5
SI 484583 Dup		4.40	4.3	<0.05	<0.02	0.03	0.02	14.1	36.5	0.60	691	0.53	<0.01	0.1	34.8
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	16.9	0.1	0.54	0.10	0.07	16.3	5.1	0.10	1177	1.13	0.02	0.6	284.2
SI 484601	Soil	3.85	3.3	<0.05	<0.02	0.02	0.02	8.1	31.4	0.44	444	0.28	<0.01	<0.05	40.2
SI 484601 Dup		3.85	3.3	<0.05	<0.02	0.02	0.02	8.1	31.4	0.44	437	0.28	<0.01	<0.05	40.4
STD-ME-6 expected															
STD-ME-6 result		6.10	4.2	<0.05	0.12	0.47	0.09	4.1	9.0	0.87	1698	20.55	0.06	0.1	31.1
TI 481472	Soil	4.00	4.1	<0.05	<0.02	0.02	0.04	14.0	51.9	0.87	353	1.03	<0.01	0.2	38.4
TI 481472 Dup		3.92	4.2	<0.05	<0.02	0.02	0.03	13.8	51.8	0.87	348	1.02	<0.01	0.2	38.3
QCV1008-00303-0011-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	16.3	0.1	0.55	0.09	0.07	16.0	5.1	0.10	1238	1.17	0.02	0.6	287.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th	Ti
		50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample Description	Sample Type	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%
		5	0.2	0.1	0.01	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2	0.005
QCV1008-00303-0001-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	0.02	<0.2	<0.005
SI 484547	Soil	585	159.8	3.6	<0.01	0.03	1.23	0.5	0.3	0.3	12.2	<0.01	0.08	1	<0.005
SI 484547 Dup		590	154.5	3.6	<0.01	0.03	1.12	0.5	0.3	0.3	12.2	<0.01	0.09	1	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		349	18.8	7.0	<0.01	0.02	<0.05	41.8	<0.2	1.6	13.4	<0.01	<0.01	6	0.106
SI 484565	Soil	737	67.9	2.1	<0.01	0.03	1.65	0.6	0.3	<0.2	6.7	<0.01	0.06	1	<0.005
SI 484565 Dup		741	67.0	2.2	<0.01	0.04	1.52	0.6	0.3	<0.2	7.2	<0.01	0.05	1	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		351	19.4	7.7	<0.01	0.02	<0.05	45.9	<0.2	1.7	14.2	<0.01	0.04	6	0.104
SI 484583	Soil	638	48.5	4.1	<0.01	0.03	0.42	0.7	<0.2	<0.2	8.0	<0.01	0.08	1	<0.005
SI 484583 Dup		647	46.7	3.9	<0.01	0.03	0.38	0.7	<0.2	<0.2	7.7	<0.01	0.07	1	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		349	21.6	8.7	<0.01	0.02	<0.05	46.3	<0.2	1.7	15.0	<0.01	<0.01	6	0.122
SI 484601	Soil	681	69.3	2.7	<0.01	0.02	0.95	0.5	0.3	<0.2	8.3	<0.01	0.09	1	<0.005
SI 484601 Dup		677	70.0	2.7	<0.01	0.02	0.94	0.5	0.3	<0.2	8.5	<0.01	0.10	0	<0.005
STD-ME-6 expected			10200												
STD-ME-6 result		450	>10000	3.5	0.01	2.44	388.85	3.8	2.0	1.7	27.5	<0.01	1.42	1	0.065
TI 481472	Soil	647	30.6	4.7	<0.01	0.03	<0.05	1.3	0.5	<0.2	11.9	<0.01	0.04	2	<0.005
TI 481472 Dup		646	30.4	4.5	<0.01	0.03	<0.05	1.3	0.5	<0.2	11.6	<0.01	0.04	2	<0.005
QCV1008-00303-0011-BLK		<5	0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		354	19.7	8.0	<0.01	0.02	<0.05	47.7	0.5	1.7	14.2	<0.01	0.01	7	0.127

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02524-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
QCV1008-00303-0001-BLK		<0.05	<0.05	<1	0.51	<0.05	<1	<0.5
SI 484547	Soil	<0.05	1	10	2.47	1.4	168	<0.5
SI 484547 Dup		<0.05	1	10	2.48	1.4	172	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.06	1	170	3.61	8.6	132	18.4
SI 484565	Soil	<0.05	1	11	2.11	1.3	80	1.0
SI 484565 Dup		<0.05	1	11	2.18	1.4	81	0.9
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.06	1	183	0.79	9.5	130	20.5
SI 484583	Soil	<0.05	1	15	10.67	2.1	101	<0.5
SI 484583 Dup		<0.05	1	14	10.38	2.0	103	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.05	1	179	6.10	9.5	131	21.6
SI 484601	Soil	<0.05	1	11	2.96	3.1	99	<0.5
SI 484601 Dup		<0.05	1	11	2.95	3.0	98	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.20	1	43	6.85	6.2	6218	4.3
TI 481472	Soil	<0.05	2	14	1.03	5.6	97	0.5
TI 481472 Dup		<0.05	2	15	0.98	5.5	95	0.5
QCV1008-00303-0011-BLK		<0.05	<0.05	<1	0.07	<0.05	<1	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.06	1	173	2.84	9.3	131	19.8

Certificate of Analysis

10-360-02615-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 08/20/2010
Date Completed: 09/03/2010
Invoice:

Samples	Type	Preparation Description
56	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-1AT-GV	Au, 1AT, Gravimetric
Au-2AT-AA	Au, 2AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480230	Rock		0.744	1.83	1.10	90.8	91	0.2	94.63	0.02	0.02	11.85	1.5	273	1.0
RI 480231	Rock		7.338	67.55	1.97	>10000	146	0.4	47.75	0.02	3.68	17.33	1.3	158	1.8
RI 480232	Rock		0.223	6.49	2.22	5380.4	139	0.4	9.60	<0.01	0.33	29.86	1.3	205	2.1
RI 480233	Rock		4.072	32.04	1.47	>10000	78	0.4	12.22	<0.01	7.92	15.31	1.0	155	1.6
RI 480234	Rock		6.568	62.66	1.12	>10000	75	0.2	3.46	<0.01	5.74	2.34	0.4	110	0.9
RI 480235	Rock		0.844	3.57	2.14	>10000	160	0.6	7.09	0.01	0.26	26.84	1.0	173	2.2
RI 480236	Rock		0.037	2.09	2.20	282.9	137	0.6	3.60	0.06	0.06	27.69	2.7	219	1.3
RI 480237	Rock		0.142	2.58	2.33	981.0	132	0.5	5.16	<0.01	0.26	28.65	1.8	189	2.4
RI 480238	Rock		0.084	1.88	1.80	890.6	86	0.6	1.75	<0.01	0.59	25.21	2.8	180	4.4
RI 480239	Rock		0.030	1.82	1.29	131.2	55	0.3	5.09	<0.01	0.02	14.25	1.2	258	1.1
RI 480240	Rock		3.679	25.07	2.05	>10000	115	0.5	1.55	<0.01	3.89	15.94	0.9	188	2.6
RI 480241	Rock		0.078	1.65	2.28	264.8	105	0.6	2.18	<0.01	0.07	28.46	1.4	202	1.8
RI 480242	Rock		0.459	4.93	2.01	>10000	98	0.6	1.51	0.01	0.51	21.72	1.3	141	2.0
RI 480243	Rock		0.756	8.17	2.27	>10000	125	0.5	1.98	<0.01	0.52	24.23	0.7	185	1.9
RI 480244	Rock		0.189	3.13	2.07	4725.4	131	0.6	1.20	<0.01	0.24	27.52	1.0	213	1.5
RI 480245	Rock		0.065	1.86	0.62	2085.7	20	<0.05	1.57	0.02	0.23	11.91	1.6	186	0.2
RI 480246	Rock		0.667	1.79	0.37	4419.7	31	0.1	2.53	<0.01	0.12	5.14	1.2	267	0.3
RI 480247	Rock		0.059	1.45	1.75	>10000	111	0.4	3.15	0.01	0.14	22.15	2.5	270	1.1
RI 481526	Rock		0.224	2.06	2.35	25.8	34	0.4	0.94	0.02	0.02	37.30	5.1	207	0.8
RI 481527	Rock		0.055	2.02	2.63	52.1	66	0.4	1.10	0.05	0.02	42.42	4.1	201	1.4
RI 481528	Rock		0.101	1.65	2.88	136.7	74	0.4	0.77	0.03	0.05	42.05	3.6	201	1.5
RI 481529	Rock		0.165	1.78	0.65	633.1	17	<0.05	0.82	0.01	0.06	9.17	2.5	235	0.3
RI 481530	Rock		0.139	2.01	0.64	3364.2	30	0.2	0.77	0.12	0.13	9.10	1.8	230	0.4
RI 481531	Rock		0.033	2.04	0.12	1147.5	13	0.1	1.11	<0.01	0.04	1.02	0.8	160	0.1
RI 481532	Rock		0.035	1.67	0.29	899.4	16	0.1	0.69	0.16	0.05	2.06	2.5	187	0.2
RI 481533	Rock		0.083	5.08	0.13	59.8	135	0.1	1.99	<0.01	3.76	2.33	1.2	242	0.2
RI 481534	Rock		0.026	1.66	0.25	1394.9	31	0.1	0.62	<0.01	0.06	2.34	1.7	253	0.2
RI 481535	Rock		5.359	2.76	0.82	>10000	106	0.5	0.60	0.01	0.08	8.87	6.5	242	0.6
RI 481536	Rock		0.027	1.61	0.20	2341.6	24	0.1	0.66	<0.01	0.05	2.09	2.0	323	0.2
RI 481537	Rock		0.033	1.67	0.64	1610.1	64	0.4	0.64	0.01	0.11	7.06	1.7	338	0.6
RI 481538	Rock		0.007	1.48	0.80	345.1	73	0.5	0.45	0.01	0.04	8.48	2.3	275	0.7
RI 481539	Rock		0.253	1.64	0.72	5884.4	79	0.2	0.75	0.02	0.19	10.02	2.1	276	0.5
RI 481540	Rock		0.424	1.56	1.13	>10000	122	0.4	0.42	0.02	0.29	26.09	2.4	255	0.7
RI 481541	Rock		0.031	1.50	0.80	2626.2	63	0.3	0.62	0.02	0.15	13.93	1.9	298	0.4
RI 481542	Rock		0.045	1.65	0.75	7390.6	106	0.3	0.38	0.02	0.25	9.11	3.3	283	0.6
RI 481543	Rock		0.138	1.88	0.61	6882.1	75	0.2	0.44	0.04	0.42	10.14	2.6	243	0.4
RI 481544	Rock		0.099	1.30	0.22	3803.2	12	<0.05	0.32	<0.01	0.04	3.76	1.6	267	0.2
RI 481545	Rock		0.174	3.34	0.34	5745.5	24	0.1	0.39	0.01	0.12	8.13	1.5	327	0.2
RI 481546	Rock		0.800	4.97	0.04	3798.9	25	<0.05	2.28	0.01	0.45	0.38	1.1	194	0.1
RI 481547	Rock		0.100	5.00	0.21	2909.4	28	<0.05	0.83	<0.01	0.29	2.64	1.4	196	0.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 481548	Rock		0.467	10.83	0.29	7975.6	32	0.1	2.51	<0.01	0.51	2.79	1.4	223	0.3
RI 481549	Rock	29.074	>10	3.86	0.33	7779.9	44	0.2	12.93	<0.01	0.47	4.29	1.4	378	0.3
RI 481550	Rock		2.159	1.84	0.42	5453.0	45	0.3	7.95	<0.01	0.19	4.34	1.5	268	0.4
RI 481551	Rock		0.082	1.91	0.10	4714.4	14	<0.05	4.26	0.01	0.20	2.20	1.5	332	0.2
RI 481552	Rock		1.324	2.70	1.08	7115.8	104	0.8	2.94	<0.01	0.56	8.32	1.5	326	0.8
RI 481553	Rock		0.605	5.78	0.67	3356.0	63	0.4	1.96	<0.01	0.05	5.56	1.4	409	0.6
RI 481554	Rock		6.391	5.61	0.90	1817.7	101	0.6	2.23	0.01	0.24	7.45	1.5	304	0.7
RI 481555	Rock	12.670	>10	2.98	0.91	3091.1	88	0.6	1.15	<0.01	0.11	9.54	2.2	379	0.7
RI 481556	Rock		1.271	10.25	1.31	3468.5	133	0.9	0.85	0.01	0.51	14.19	1.9	431	1.0
RI 481557	Rock	13.258	>10	2.66	0.57	2510.1	76	0.3	1.66	0.01	0.40	4.48	1.6	385	0.5
RI 481558	Rock	35.774	>10	2.65	0.59	3236.5	91	0.3	14.37	0.02	0.31	6.01	1.5	362	0.6
RI 481559	Rock		5.192	2.05	0.69	3751.9	87	0.3	8.30	0.02	0.41	5.81	1.3	345	0.6
RI 481560	Rock		0.103	2.61	0.62	2859.7	94	0.2	7.54	0.02	0.19	11.82	2.3	453	0.5
RI 481561	Rock		0.088	5.06	1.04	3495.4	106	0.4	5.01	0.02	0.31	11.07	2.9	336	0.8
RI 481562	Rock		0.257	2.63	1.31	>10000	141	0.8	2.94	0.01	0.30	16.66	3.1	394	1.0
RI 481563	Rock	11.939	>10	2.44	0.40	4599.0	50	0.2	3.30	0.01	0.42	5.41	2.7	352	0.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
RI 480230	Rock	16.1	0.65	2.5	1.2	1.30	0.01	0.26	6.0	14.6	0.02	55	3.23	0.02	0.5
RI 480231	Rock	40.0	3.22	4.8	1.8	1.46	4.94	0.78	8.6	5.8	0.07	62	2.36	0.03	0.7
RI 480232	Rock	12.4	0.91	5.2	1.1	1.76	0.40	0.86	13.9	11.6	0.06	29	1.31	0.04	1.1
RI 480233	Rock	95.6	4.50	3.8	1.7	0.88	8.38	0.45	7.6	14.5	0.03	27	1.24	0.02	0.5
RI 480234	Rock	68.1	8.55	3.1	2.0	0.45	3.18	0.43	1.6	4.3	0.03	23	0.78	0.02	0.3
RI 480235	Rock	24.4	1.74	5.7	1.4	1.59	0.07	0.83	12.1	9.8	0.09	29	1.15	0.04	1.0
RI 480236	Rock	9.3	0.87	4.8	0.6	1.61	0.03	0.54	13.0	9.6	0.06	169	1.36	0.08	1.1
RI 480237	Rock	13.2	0.85	5.2	1.4	1.46	0.09	0.68	13.3	6.6	0.08	50	1.53	0.04	1.1
RI 480238	Rock	30.6	5.12	4.2	1.5	1.16	0.02	0.38	12.5	27.6	0.03	137	1.15	0.03	0.6
RI 480239	Rock	6.7	0.31	2.5	1.6	0.84	0.02	0.24	6.7	137.3	0.02	28	1.56	0.02	0.6
RI 480240	Rock	23.5	4.36	5.3	1.9	1.08	1.55	0.84	7.9	6.9	0.08	44	1.63	0.03	0.6
RI 480241	Rock	6.8	0.60	4.7	1.3	1.45	0.02	0.54	13.3	12.4	0.03	25	1.18	0.04	1.0
RI 480242	Rock	16.0	1.71	4.1	1.7	0.99	0.11	0.67	10.7	12.0	0.05	46	1.19	0.03	0.8
RI 480243	Rock	19.1	2.35	4.9	1.8	1.03	0.15	0.95	12.2	7.1	0.07	32	1.03	0.03	0.8
RI 480244	Rock	18.2	0.92	4.9	1.1	1.14	0.31	0.92	12.8	5.2	0.07	32	1.14	0.03	0.9
RI 480245	Rock	5.9	0.54	0.9	1.3	0.40	<0.01	0.01	5.7	22.7	<0.01	40	1.19	0.43	0.4
RI 480246	Rock	12.3	0.63	1.4	1.7	<0.1	0.01	0.14	2.4	1.8	0.02	32	1.63	<0.01	0.3
RI 480247	Rock	7.4	1.32	4.6	1.4	1.08	0.03	0.68	10.2	2.8	0.12	38	1.36	0.04	0.9
RI 481526	Rock	29.3	3.42	9.3	0.9	1.69	0.02	0.15	17.7	57.2	0.47	551	1.13	0.15	1.0
RI 481527	Rock	7.0	1.44	5.4	1.0	2.79	<0.01	0.36	20.8	20.8	0.05	576	0.97	1.15	1.4
RI 481528	Rock	12.4	1.42	5.9	1.1	2.45	0.01	0.41	20.8	23.7	0.07	198	0.93	0.82	1.3
RI 481529	Rock	5.2	0.45	0.8	1.5	0.29	<0.01	0.01	4.2	20.2	<0.01	317	0.98	0.43	0.3
RI 481530	Rock	5.7	0.65	1.0	1.6	0.18	<0.01	0.03	4.0	31.3	<0.01	49	1.09	0.39	0.2
RI 481531	Rock	29.3	0.41	0.5	1.5	<0.1	<0.01	0.03	0.5	2.7	<0.01	34	1.12	<0.01	0.1
RI 481532	Rock	15.6	0.80	0.9	1.3	<0.1	<0.01	0.04	0.9	2.2	0.02	277	1.73	0.13	0.2
RI 481533	Rock	6.0	0.37	0.4	1.3	<0.1	0.09	0.04	1.2	0.9	<0.01	59	1.45	0.01	0.2
RI 481534	Rock	5.2	0.42	1.1	1.4	<0.1	0.01	0.09	1.1	1.6	<0.01	37	1.48	<0.01	0.2
RI 481535	Rock	7.1	1.92	4.0	1.3	0.20	0.04	0.39	4.7	4.7	0.04	32	1.43	0.01	0.4
RI 481536	Rock	7.5	0.51	0.8	1.4	<0.1	<0.01	0.06	1.0	1.5	<0.01	38	1.29	<0.01	0.2
RI 481537	Rock	6.2	0.53	3.2	1.5	0.11	0.01	0.29	3.6	2.7	0.03	47	1.68	0.01	0.4
RI 481538	Rock	7.0	0.58	3.6	1.5	0.18	0.01	0.34	4.5	2.9	0.04	57	1.27	0.02	0.5
RI 481539	Rock	7.2	0.85	2.4	1.4	0.36	0.02	0.20	5.1	2.6	0.03	63	1.30	0.07	0.4
RI 481540	Rock	6.0	1.36	3.3	1.5	1.03	0.02	0.25	12.7	5.5	0.04	55	1.32	0.02	0.9
RI 481541	Rock	5.3	0.53	2.5	1.2	0.55	<0.01	0.18	6.9	2.0	0.03	43	1.27	0.20	0.7
RI 481542	Rock	5.9	0.99	2.6	1.3	0.35	0.02	0.23	4.3	4.0	0.02	46	1.38	<0.01	0.4
RI 481543	Rock	23.6	0.85	1.7	0.6	1.04	0.01	0.13	4.8	1.8	0.03	36	1.24	0.14	0.5
RI 481544	Rock	7.0	0.59	0.5	0.1	<0.1	<0.01	0.03	1.9	1.1	0.01	32	1.27	<0.01	0.2
RI 481545	Rock	6.8	0.74	0.9	0.9	0.22	0.01	0.07	3.9	1.3	0.01	34	1.32	0.06	0.3
RI 481546	Rock	8.2	0.56	0.3	0.7	<0.1	<0.01	0.02	<0.5	1.4	<0.01	32	1.22	<0.01	0.1
RI 481547	Rock	10.7	0.55	1.2	1.1	<0.1	<0.01	0.10	1.2	4.7	0.01	32	1.10	<0.01	0.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
RI 481548	Rock	26.3	0.90	1.5	1.0	<0.1	0.02	0.14	1.5	3.2	0.02	30	1.19	<0.01	0.2
RI 481549	Rock	31.2	0.98	1.8	1.2	<0.1	0.02	0.16	2.1	4.5	0.02	44	1.88	<0.01	0.3
RI 481550	Rock	13.5	0.75	2.2	1.0	0.11	0.02	0.21	2.3	3.6	0.02	35	1.25	<0.01	0.3
RI 481551	Rock	12.2	0.81	0.5	0.9	<0.1	<0.01	0.03	1.0	0.9	<0.01	82	1.60	<0.01	0.2
RI 481552	Rock	26.3	0.99	5.1	2.2	0.62	0.02	0.51	4.6	3.9	0.06	39	1.27	0.02	0.4
RI 481553	Rock	5.1	0.69	3.4	2.2	0.16	<0.01	0.34	3.0	2.9	0.04	42	1.37	0.01	0.4
RI 481554	Rock	5.7	0.63	4.5	2.0	0.23	<0.01	0.45	4.0	5.0	0.05	49	1.29	0.02	0.5
RI 481555	Rock	8.4	0.73	4.3	0.9	0.21	<0.01	0.45	4.7	5.3	0.05	47	1.51	0.02	0.7
RI 481556	Rock	18.2	0.77	6.2	1.7	0.35	0.01	0.63	7.0	6.3	0.07	60	1.54	0.02	0.7
RI 481557	Rock	23.8	0.63	2.7	1.2	<0.1	0.01	0.27	2.5	7.3	0.03	46	1.38	0.02	0.4
RI 481558	Rock	19.9	0.77	2.9	0.9	0.10	0.01	0.27	3.0	8.3	0.03	57	2.29	0.01	0.5
RI 481559	Rock	14.3	0.71	3.4	1.3	<0.1	0.01	0.33	3.3	5.8	0.04	49	1.58	0.02	0.4
RI 481560	Rock	5.8	0.74	2.0	1.3	0.37	0.02	0.20	5.8	3.0	0.02	60	2.09	0.01	0.5
RI 481561	Rock	8.7	1.09	3.3	1.0	0.38	0.01	0.28	5.3	4.4	0.03	82	1.56	0.02	0.6
RI 481562	Rock	14.1	1.65	5.2	1.3	0.62	0.03	0.55	7.6	7.8	0.06	58	1.85	0.02	0.9
RI 481563	Rock	20.0	0.93	1.7	1.1	0.11	0.01	0.15	2.8	2.5	0.02	58	1.68	<0.01	0.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
RI 480230	Rock	7.3	70	37.6	16.0	0.013	<0.01	2.68	1.0	<0.5	8.8	10.8	0.07	6.42	3
RI 480231	Rock	3.7	210	>10000	44.8	0.013	0.15	130.26	3.8	1.5	34.4	21.0	0.10	3.64	6
RI 480232	Rock	4.0	235	1866.1	49.5	0.008	0.08	10.98	2.3	<0.5	8.3	27.1	0.18	1.03	7
RI 480233	Rock	3.4	211	>10000	25.4	<0.005	0.28	94.97	2.0	1.2	14.7	21.5	0.06	1.34	5
RI 480234	Rock	2.6	60	>10000	23.7	0.018	2.89	248.54	2.2	<0.5	9.4	9.4	<0.05	0.77	2
RI 480235	Rock	3.5	226	181.8	47.9	<0.005	0.12	15.43	3.2	<0.5	4.5	51.3	0.14	0.89	7
RI 480236	Rock	8.9	244	112.1	29.9	<0.005	<0.01	1.52	1.8	<0.5	0.9	19.1	0.19	0.42	8
RI 480237	Rock	5.3	92	244.9	41.0	<0.005	0.03	4.21	2.5	<0.5	2.4	19.4	0.16	0.66	6
RI 480238	Rock	9.8	337	58.0	25.9	<0.005	0.02	3.51	1.9	<0.5	1.9	35.4	0.07	0.39	7
RI 480239	Rock	5.0	61	61.3	15.4	<0.005	<0.01	2.18	1.4	<0.5	15.5	21.0	0.07	0.56	3
RI 480240	Rock	3.7	473	9279.3	46.4	0.005	0.42	75.05	3.1	<0.5	27.7	17.9	0.09	0.53	6
RI 480241	Rock	4.1	76	65.5	31.6	<0.005	<0.01	2.88	1.9	<0.5	4.5	16.5	0.15	0.73	6
RI 480242	Rock	4.2	286	855.1	39.9	<0.005	0.08	34.03	3.8	1.1	8.1	21.7	0.11	0.74	7
RI 480243	Rock	3.5	704	6380.9	52.1	0.008	0.20	162.61	4.0	1.4	21.0	19.6	0.10	0.40	11
RI 480244	Rock	4.3	114	987.9	50.2	<0.005	0.08	6.47	2.5	<0.5	8.6	15.1	0.13	0.22	6
RI 480245	Rock	5.3	21	32.6	0.7	<0.005	0.03	3.16	0.5	<0.5	0.4	36.6	<0.05	0.79	3
RI 480246	Rock	10.1	16	119.2	8.2	0.005	0.16	5.23	0.7	<0.5	1.1	3.6	<0.05	0.48	1
RI 480247	Rock	5.3	31	27.6	42.2	<0.005	0.44	7.21	1.6	1.5	7.0	14.1	0.13	0.31	3
RI 481526	Rock	17.6	128	51.9	10.4	<0.005	<0.01	0.90	2.4	<0.5	0.8	9.8	0.15	0.31	9
RI 481527	Rock	10.4	106	10.3	24.5	<0.005	0.02	1.59	2.8	<0.5	14.3	39.5	0.21	0.23	13
RI 481528	Rock	10.9	139	16.6	26.9	<0.005	<0.01	1.80	3.0	<0.5	1.5	36.5	0.18	0.17	12
RI 481529	Rock	7.5	31	5.3	0.9	<0.005	0.02	2.15	0.7	<0.5	1.6	19.9	<0.05	0.24	2
RI 481530	Rock	7.5	566	9.2	2.1	<0.005	0.11	6.43	0.5	<0.5	0.4	45.2	<0.05	0.50	2
RI 481531	Rock	6.0	21	8.9	1.6	0.007	0.04	4.58	0.4	1.3	0.4	4.9	<0.05	0.32	0
RI 481532	Rock	10.7	35	15.0	2.8	<0.005	0.03	1.28	1.1	<0.5	0.4	15.3	<0.05	0.23	0
RI 481533	Rock	6.0	15	1351.0	2.3	0.005	0.03	4.40	0.4	<0.5	0.7	2.8	<0.05	0.38	0
RI 481534	Rock	7.1	25	14.0	6.2	<0.005	0.05	1.28	0.5	<0.5	3.1	4.9	<0.05	0.25	0
RI 481535	Rock	10.1	61	15.2	23.2	<0.005	0.49	11.71	1.4	2.3	1.5	8.3	<0.05	0.71	2
RI 481536	Rock	7.8	40	6.7	4.5	<0.005	0.06	1.56	0.6	<0.5	1.6	3.2	<0.05	0.21	1
RI 481537	Rock	7.8	39	6.1	18.7	<0.005	0.05	1.25	1.1	<0.5	23.9	6.5	<0.05	0.17	1
RI 481538	Rock	7.9	43	10.4	21.3	<0.005	0.01	1.19	1.5	<0.5	10.6	6.6	<0.05	0.10	1
RI 481539	Rock	8.4	68	10.1	12.8	0.006	0.17	2.76	1.1	2.2	2.2	10.9	<0.05	0.50	3
RI 481540	Rock	8.5	124	18.1	17.4	<0.005	0.34	4.89	1.3	1.1	0.8	18.3	0.08	0.38	6
RI 481541	Rock	7.3	60	5.9	11.6	<0.005	0.07	1.30	1.1	<0.5	0.8	16.0	0.05	0.27	3
RI 481542	Rock	10.5	153	10.1	14.6	<0.005	0.23	4.03	0.8	<0.5	1.0	10.0	<0.05	0.47	2
RI 481543	Rock	7.0	195	20.8	8.4	0.005	0.21	3.14	0.3	1.2	0.5	14.9	0.05	0.38	2
RI 481544	Rock	7.0	39	13.2	2.3	<0.005	0.10	1.78	<0.1	<0.5	0.5	2.6	<0.05	0.52	1
RI 481545	Rock	6.1	70	16.0	4.2	<0.005	0.11	5.93	0.3	<0.5	0.6	5.2	<0.05	0.29	2
RI 481546	Rock	5.0	20	54.5	1.3	<0.005	0.07	10.72	<0.1	1.5	0.6	1.8	<0.05	0.62	<0.2
RI 481547	Rock	5.4	21	19.5	5.7	<0.005	0.08	4.71	0.3	<0.5	0.6	4.9	<0.05	0.16	0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
RI 481548	Rock	5.9	28	38.8	8.2	<0.005	0.17	6.61	0.5	<0.5	0.7	6.2	<0.05	0.61	0
RI 481549	Rock	7.4	24	45.7	10.2	<0.005	0.15	9.41	0.5	1.4	0.7	6.0	<0.05	0.68	1
RI 481550	Rock	5.4	27	21.8	12.7	<0.005	0.09	6.43	0.7	<0.5	0.8	7.6	<0.05	0.58	1
RI 481551	Rock	8.4	24	41.4	1.7	<0.005	0.21	2.51	0.3	1.2	0.4	2.6	<0.05	0.59	<0.2
RI 481552	Rock	7.0	26	26.9	30.7	<0.005	0.21	7.54	1.6	<0.5	0.9	11.6	<0.05	0.48	1
RI 481553	Rock	6.9	20	8.4	20.3	<0.005	0.09	5.63	0.9	<0.5	0.6	9.4	<0.05	0.52	1
RI 481554	Rock	6.6	29	10.1	25.7	<0.005	0.05	3.81	1.3	1.1	0.9	17.7	0.05	0.52	1
RI 481555	Rock	8.7	28	16.2	25.2	<0.005	0.11	4.55	1.2	<0.5	0.7	17.7	<0.05	0.19	1
RI 481556	Rock	7.3	40	27.1	37.0	<0.005	0.08	4.04	1.6	<0.5	1.1	17.8	<0.05	0.18	2
RI 481557	Rock	6.3	32	27.5	16.5	<0.005	0.08	4.05	0.8	<0.5	0.7	13.8	<0.05	0.35	1
RI 481558	Rock	8.0	24	131.4	17.0	<0.005	0.09	4.70	0.9	<0.5	0.6	15.4	<0.05	0.56	1
RI 481559	Rock	6.4	26	33.1	20.1	<0.005	0.13	5.15	0.9	<0.5	0.7	18.9	<0.05	0.59	1
RI 481560	Rock	8.8	48	35.6	12.3	<0.005	0.11	2.20	0.7	<0.5	1.2	11.5	<0.05	0.37	2
RI 481561	Rock	9.2	55	20.1	17.3	<0.005	0.13	2.42	1.2	<0.5	0.7	12.6	<0.05	0.35	2
RI 481562	Rock	11.3	48	34.7	30.5	0.008	0.40	5.84	1.9	<0.5	1.0	10.3	0.09	0.42	3
RI 481563	Rock	8.3	28	23.7	8.5	<0.005	0.16	3.15	0.5	<0.5	0.6	7.0	<0.05	0.30	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480230	Rock	0.010	0.06	1	<1	383.26	1.8	17	20.3
RI 480231	Rock	0.019	0.24	1	12	216.05	2.5	112	34.6
RI 480232	Rock	0.028	0.24	1	11	50.49	2.8	16	42.0
RI 480233	Rock	0.014	0.14	1	4	49.34	1.6	209	27.2
RI 480234	Rock	0.009	0.15	0	4	21.51	1.0	420	17.0
RI 480235	Rock	0.029	0.26	1	13	33.27	3.4	12	49.1
RI 480236	Rock	0.023	0.12	2	8	18.53	4.1	27	48.1
RI 480237	Rock	0.028	0.20	1	11	25.87	3.4	35	46.2
RI 480238	Rock	0.014	0.14	1	14	16.37	3.4	52	40.9
RI 480239	Rock	0.013	0.05	1	2	37.65	1.7	4	24.7
RI 480240	Rock	0.019	0.27	1	13	14.30	2.2	103	33.9
RI 480241	Rock	0.024	0.13	1	8	22.50	3.5	18	46.6
RI 480242	Rock	0.021	0.19	1	7	15.57	2.5	31	36.0
RI 480243	Rock	0.023	0.26	1	12	20.69	2.2	48	36.1
RI 480244	Rock	0.024	0.25	1	9	11.23	2.2	13	34.2
RI 480245	Rock	0.008	<0.02	1	<1	18.60	1.1	10	17.8
RI 480246	Rock	<0.005	<0.02	0	<1	21.47	0.7	3	5.7
RI 480247	Rock	0.023	0.16	1	<1	14.52	2.7	12	37.3
RI 481526	Rock	0.024	0.03	2	11	13.13	4.7	83	58.2
RI 481527	Rock	0.033	0.09	2	3	12.51	6.7	15	90.3
RI 481528	Rock	0.033	0.10	2	12	11.79	5.2	22	80.1
RI 481529	Rock	0.007	<0.02	0	<1	10.44	1.0	10	13.3
RI 481530	Rock	<0.005	<0.02	0	<1	13.44	2.7	7	10.7
RI 481531	Rock	<0.005	<0.02	<0.1	<1	14.27	0.1	6	1.1
RI 481532	Rock	<0.005	<0.02	0	<1	10.67	1.6	23	3.8
RI 481533	Rock	<0.005	<0.02	0	<1	17.75	0.2	271	2.1
RI 481534	Rock	<0.005	<0.02	0	<1	19.99	0.4	5	2.7
RI 481535	Rock	0.012	0.08	0	<1	9.07	0.9	12	10.2
RI 481536	Rock	<0.005	<0.02	<0.1	<1	7.66	0.4	5	2.7
RI 481537	Rock	0.009	0.04	0	<1	11.93	0.9	7	6.9
RI 481538	Rock	0.012	0.05	0	<1	13.71	1.5	12	8.6
RI 481539	Rock	0.008	0.03	1	<1	9.78	1.4	9	14.6
RI 481540	Rock	0.016	0.05	1	<1	10.80	3.0	6	39.4
RI 481541	Rock	0.011	<0.02	1	<1	8.62	1.7	5	22.2
RI 481542	Rock	0.009	0.03	1	<1	11.89	1.4	7	14.9
RI 481543	Rock	0.009	<0.02	1	<1	8.93	1.6	9	15.4
RI 481544	Rock	<0.005	<0.02	0	<1	4.47	0.4	3	4.6
RI 481545	Rock	0.005	<0.02	0	<1	10.25	0.8	14	8.8
RI 481546	Rock	<0.005	<0.02	<0.1	<1	10.56	<0.1	27	0.6
RI 481547	Rock	<0.005	<0.02	<0.1	<1	12.97	0.2	14	1.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 481548	Rock	<0.005	<0.02	<0.1	<1	11.43	0.3	12	1.8
RI 481549	Rock	0.006	<0.02	0	<1	56.49	0.4	12	3.2
RI 481550	Rock	0.008	0.03	0	<1	48.13	0.4	6	3.9
RI 481551	Rock	<0.005	<0.02	<0.1	<1	34.05	0.2	11	0.9
RI 481552	Rock	0.014	0.11	0	<1	32.89	0.7	14	7.3
RI 481553	Rock	0.010	0.06	0	<1	20.19	0.5	6	4.4
RI 481554	Rock	0.015	0.07	0	8	21.65	0.8	14	6.0
RI 481555	Rock	0.016	0.12	0	<1	17.12	0.7	10	6.1
RI 481556	Rock	0.021	0.11	0	2	11.62	0.9	10	8.2
RI 481557	Rock	0.009	0.05	0	<1	17.22	0.5	10	3.9
RI 481558	Rock	0.010	0.04	0	<1	171.13	0.6	11	4.3
RI 481559	Rock	0.010	0.05	0	<1	105.59	0.7	13	4.5
RI 481560	Rock	0.009	<0.02	1	<1	95.51	1.2	11	14.1
RI 481561	Rock	0.013	0.05	1	<1	72.37	1.7	23	14.3
RI 481562	Rock	0.024	0.10	1	2	46.26	2.0	20	23.1
RI 481563	Rock	0.007	<0.02	0	<1	44.63	0.9	11	5.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
QCV1008-00724-0001-BLK				0.02	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
RI 480230	Rock			1.83	1.10	90.8	91	0.2	94.63	0.02	0.02	11.85	1.5	273	1.0
RI 480230 Dup				1.73	1.07	91.2	90	0.3	94.60	0.02	0.02	12.07	1.5	270	1.0
STD-ME-8 expected				61.70											
STD-ME-8 result				63.48	4.81	2615.2	662	0.9	5.08	7.10	191.46	28.84	14.6	49	3.4
RI 481526	Rock			2.06	2.35	25.8	34	0.4	0.94	0.02	0.02	37.30	5.1	207	0.8
RI 481526 Dup				2.15	2.29	24.4	33	0.4	0.93	0.02	0.02	37.60	4.8	206	0.8
STD-OREAS-45P-4A expected				0.32		13.4			0.21				122.0	1103	
STD-OREAS-45P-4A result				2.38	6.79	0.3	310	1.0	0.28	0.26	0.12	52.11	118.6	978	2.5
RI 481544	Rock			1.30	0.22	3803.2	12	<0.05	0.32	<0.01	0.04	3.76	1.6	267	0.2
RI 481544 Dup				2.03	0.22	3778.8	11	<0.05	0.32	<0.01	0.04	3.54	1.6	274	0.1
STD-ME-8 expected				61.70											
STD-ME-8 result				62.91	4.66	2520.8	408	1.0	4.90	6.84	180.57	27.90	15.0	53	3.3
RI 481562	Rock			2.63	1.31	>10000	141	0.8	2.94	0.01	0.30	16.66	3.1	394	1.0
RI 481562 Dup				2.72	1.32	>10000	143	0.8	3.15	0.01	0.34	16.89	3.2	395	1.0
QCV1008-00724-0009-BLK				0.02	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
STD-SY-4 expected							340	2.6				122.00	2.8	12	1.5
STD-SY-4 result				2.13	>10	8.3	355	3.1	0.07	5.61	0.24	126.03	4.6	11	1.8
RI 480230	Rock		0.744												
RI 480230 Dup			0.693												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.729												
RI 481526	Rock		0.224												
RI 481526 Dup			0.012												
QCV1008-00725-0004-BLK			<0.005												
RI 481544	Rock		0.099												
RI 481544 Dup			0.123												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.704												
RI 481562	Rock		0.257												
RI 481562 Dup			0.236												
QCV1008-00725-0008-BLK			<0.005												

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
QCV1008-00724-0001-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
RI 480230	Rock	16.1	0.65	2.5	1.2	1.30	0.01	0.26	6.0	14.6	0.02	55	3.23	0.02	0.5
RI 480230 Dup		16.4	0.63	2.4	1.2	1.24	0.02	0.26	5.7	14.6	0.02	54	3.20	0.02	0.5
STD-ME-8 expected		1030.0													
STD-ME-8 result		970.2	3.94	10.4	0.5	1.55	0.10	1.43	14.4	18.3	0.79	3062	6.18	1.24	4.1
RI 481526	Rock	29.3	3.42	9.3	0.9	1.69	0.02	0.15	17.7	57.2	0.47	551	1.13	0.15	1.0
RI 481526 Dup		29.2	3.33	9.4	0.9	1.70	0.02	0.15	17.7	57.9	0.46	557	1.11	0.15	1.0
STD-OREAS-45P-4A expected		749.0												0.08	
STD-OREAS-45P-4A result		772.3	>10	23.0	1.6	4.69	0.12	0.32	26.0	14.1	0.22	1357	2.45	0.07	22.1
RI 481544	Rock	7.0	0.59	0.5	0.1	<0.1	<0.01	0.03	1.9	1.1	0.01	32	1.27	<0.01	0.2
RI 481544 Dup		7.4	0.59	0.5	0.1	<0.1	<0.01	0.03	1.8	1.1	<0.01	31	1.24	<0.01	0.2
STD-ME-8 expected		1030.0													
STD-ME-8 result		939.4	3.77	10.2	0.4	1.97	0.10	1.39	13.8	17.9	0.76	2971	5.74	1.28	4.0
RI 481562	Rock	14.1	1.65	5.2	1.3	0.62	0.03	0.55	7.6	7.8	0.06	58	1.85	0.02	0.9
RI 481562 Dup		13.8	1.68	5.5	1.3	0.66	0.03	0.55	7.6	8.1	0.06	60	1.88	0.02	1.0
QCV1008-00724-0009-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
STD-SY-4 expected		7.0		35.0		10.60			58.0	37.0					13.0
STD-SY-4 result		13.1	4.16	33.5	0.4	1.69	0.04	1.34	59.4	41.0	0.30	775	0.38	5.26	14.2

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
QCV1008-00724-0001-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
RI 480230	Rock	7.3	70	37.6	16.0	0.013	<0.01	2.68	1.0	<0.5	8.8	10.8	0.07	6.42	3
RI 480230 Dup		7.7	69	39.6	15.9	0.013	<0.01	2.67	0.9	<0.5	9.1	10.3	0.08	6.44	4
STD-ME-8 expected				19400											
STD-ME-8 result		34.0	586	>10000	74.4	<0.005	1.68	72.07	8.5	3.5	3.5	417.3	0.50	0.77	4
RI 481526	Rock	17.6	128	51.9	10.4	<0.005	<0.01	0.90	2.4	<0.5	0.8	9.8	0.15	0.31	9
RI 481526 Dup		17.2	127	49.8	10.4	<0.005	<0.01	0.88	2.4	<0.5	0.8	9.9	0.15	0.27	9
STD-OREAS-45P-4A expected		385.0	454	22.0				0.92							
STD-OREAS-45P-4A result		432.9	408	25.8	27.6	<0.005	0.03	<0.05	67.2	<0.5	3.3	36.2	2.16	0.52	10
RI 481544	Rock	7.0	39	13.2	2.3	<0.005	0.10	1.78	<0.1	<0.5	0.5	2.6	<0.05	0.52	1
RI 481544 Dup		7.0	38	13.2	2.2	<0.005	0.11	1.80	<0.1	<0.5	0.5	2.5	<0.05	0.51	1
STD-ME-8 expected				19400											
STD-ME-8 result		32.6	596	>10000	71.0	<0.005	1.66	67.57	8.0	3.2	3.5	387.1	0.47	0.60	4
RI 481562	Rock	11.3	48	34.7	30.5	0.008	0.40	5.84	1.9	<0.5	1.0	10.3	0.09	0.42	3
RI 481562 Dup		11.8	48	35.2	31.2	<0.005	0.40	5.86	1.9	<0.5	1.0	10.7	0.09	0.38	3
QCV1008-00724-0009-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
STD-SY-4 expected		9.0		10.0	55.0				1.1			1191.0	0.90		1
STD-SY-4 result		6.9	512	19.0	52.4	0.025	0.04	<0.05	0.8	1.1	8.9	1101.5	1.38	0.30	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02615-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1008-00724-0001-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
RI 480230	Rock	0.010	0.06	1	<1	383.26	1.8	17	20.3
RI 480230 Dup		0.011	0.05	1	<1	379.63	1.8	16	20.5
STD-ME-8 expected								19200	
STD-ME-8 result		0.187	0.84	2	76	18.43	12.5	>10000	30.7
RI 481526	Rock	0.024	0.03	2	11	13.13	4.7	83	58.2
RI 481526 Dup		0.024	0.03	2	10	12.99	4.5	81	56.8
STD-OREAS-45P-4A expected								142	
STD-OREAS-45P-4A result		0.975	0.16	2	231	7.15	14.2	140	164.4
RI 481544	Rock	<0.005	<0.02	0	<1	4.47	0.4	3	4.6
RI 481544 Dup		<0.005	<0.02	0	<1	4.36	0.4	11	4.4
STD-ME-8 expected								19200	
STD-ME-8 result		0.182	0.80	2	64	18.24	11.8	>10000	30.0
RI 481562	Rock	0.024	0.10	1	2	46.26	2.0	20	23.1
RI 481562 Dup		0.024	0.10	1	2	47.69	2.0	21	23.3
QCV1008-00724-0009-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected				1	8		119.0	93	517.0
STD-SY-4 result		0.150	0.22	1	<1	9.13	118.9	95	57.7

Certificate of Analysis

10-360-02616-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 08/20/2010
Date Completed: 09/08/2010
Invoice:

Samples	Type	Preparation Description
75	Soil	SP-SS-1K/Soils, Humus Sediments 1kg dried, sieved and riffle split

Method	Description
50-AR-UT	50 Element, Aqua Regia, ICPMS, Ultra Trace Level
Au-1AT-AA	Au, 1AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 484619	Soil	0.030	0.42	1.91	54.0	22	0.4	0.46	0.12	0.14	35.61	26.7	28	1.7	61.9
SI 484620	Soil	0.099	0.56	1.50	91.6	22	0.5	0.56	0.10	0.11	26.00	26.8	24	1.5	61.2
SI 484621	Soil	0.046	0.40	1.10	217.7	30	0.5	0.62	0.16	0.15	29.43	26.4	17	1.3	63.8
SI 484622	Soil	0.612	3.50	0.56	1507.8	26	0.1	0.26	0.09	0.33	16.48	3.6	6	1.8	31.2
SI 484623	Soil	0.328	3.20	0.64	2001.0	50	0.3	0.56	0.02	0.91	24.14	12.3	8	3.4	46.6
SI 484624	Soil	0.366	0.89	0.97	2113.0	45	0.4	0.48	0.06	1.02	22.51	17.1	16	2.6	50.0
SI 484625	Soil	0.887	1.23	1.14	1397.4	33	0.3	0.44	0.04	0.41	23.56	12.9	19	1.5	35.5
SI 484626	Soil	0.442	5.87	0.70	2216.1	49	0.2	0.59	0.01	1.16	15.62	7.1	9	3.3	49.6
SI 484627	Soil	0.121	1.27	1.05	525.6	30	0.5	0.51	0.08	0.77	18.91	23.0	17	1.6	72.6
SI 484628	Soil	0.182	1.15	0.97	557.7	35	0.3	0.49	0.08	0.78	24.23	18.1	17	1.8	53.7
SI 484629	Soil	0.073	0.62	0.99	365.9	36	0.4	0.33	0.05	0.78	19.76	19.0	13	1.6	38.9
SI 484630	Soil	0.100	0.53	1.16	248.2	42	0.3	0.34	0.09	0.23	20.20	16.0	17	1.6	35.4
SI 484631	Soil	<0.005	0.42	1.38	41.3	29	0.6	0.53	0.03	0.13	13.78	14.1	19	6.4	61.7
SI 484632	Soil	0.009	0.43	1.72	97.5	40	1.0	0.48	0.05	0.23	18.40	47.9	26	3.5	97.7
SI 484633	Soil	0.011	0.55	0.97	158.1	35	0.3	0.34	0.09	1.35	9.31	13.1	16	4.2	31.9
SI 484634	Soil	0.013	0.30	0.70	95.8	15	0.2	0.28	0.01	0.09	22.63	9.9	12	1.5	24.8
SI 484635	Soil	0.015	0.57	1.27	129.1	42	0.3	0.48	0.03	0.30	22.06	12.4	21	1.7	33.8
SI 484636	Soil	0.040	0.94	1.15	397.9	55	0.4	0.39	0.04	0.51	15.47	12.2	17	2.7	39.8
SI 484637	Soil	0.087	0.89	1.28	429.7	35	0.4	0.47	0.06	0.27	12.57	12.9	24	8.5	48.8
SI 484638	Soil	0.035	0.68	1.06	319.0	53	0.3	0.37	0.08	0.26	14.39	9.2	17	3.6	34.0
SI 484639	Soil	0.031	0.36	2.04	36.3	17	0.4	0.44	0.02	0.08	19.33	11.9	37	4.4	64.0
SI 484640	Soil	<0.005	0.44	2.20	31.8	21	0.2	0.47	<0.01	0.03	12.21	6.0	36	3.6	33.1
SI 484641	Soil	<0.005	0.46	2.04	30.7	23	0.3	0.54	0.02	0.03	18.33	16.5	34	4.4	57.1
SI 484642	Soil	<0.005	0.38	2.74	31.3	14	0.3	0.45	0.05	0.03	33.64	18.1	43	3.7	54.3
SI 484643	Soil	0.048	0.44	1.95	96.7	28	0.3	0.39	0.04	0.05	15.43	13.7	30	3.9	34.4
SI 484644	Soil	0.007	0.40	1.89	26.2	25	0.3	0.36	0.02	0.04	11.89	9.8	30	3.0	39.6
SI 484645	Soil	<0.005	0.40	1.94	28.2	21	0.2	0.36	0.01	0.05	8.43	9.6	34	2.1	31.5
SI 484646	Soil	0.006	0.38	1.92	25.5	26	0.2	0.33	0.01	0.04	10.85	9.0	32	2.4	33.5
SI 484647	Soil	0.023	0.50	1.44	96.0	50	0.3	0.45	0.02	0.17	17.44	20.7	25	2.6	40.8
SI 484648	Soil	1.864	0.75	0.90	1863.3	108	0.4	0.40	0.03	0.75	28.72	9.9	13	1.9	33.0
SI 484649	Soil	0.472	0.56	0.57	414.5	21	0.1	0.12	0.06	0.15	10.46	2.7	4	0.9	14.1
SI 484650	Soil	0.010	0.43	1.89	38.8	32	0.3	0.31	0.02	0.06	26.53	19.9	26	2.8	33.0
SI 484651	Soil	0.020	0.49	2.10	64.9	20	0.4	0.43	0.09	0.07	40.01	22.6	30	1.6	52.5
SI 484652	Soil	0.234	0.68	0.66	386.2	29	0.3	0.31	0.06	0.48	38.08	15.3	10	1.4	35.1
SI 484653	Soil	0.106	0.73	1.20	465.4	33	0.3	0.34	0.04	0.32	27.16	15.9	19	1.5	39.2
SI 484654	Soil	0.133	1.85	1.08	895.1	37	0.3	0.38	0.06	0.54	41.24	14.2	17	1.6	44.1
SI 484655	Soil	0.082	0.63	1.03	618.1	31	0.3	0.35	0.05	0.44	29.32	10.6	17	1.1	34.5
SI 484656	Soil	0.036	0.36	0.46	121.8	14	0.1	0.08	0.10	0.06	7.42	2.2	<1	0.4	11.5
SI 484657	Soil	0.006	0.59	1.00	227.1	23	0.3	0.36	0.04	0.38	34.31	19.2	17	1.3	53.2
SI 484658	Soil	0.045	0.71	1.04	300.4	33	0.4	0.34	0.08	0.43	34.61	15.7	16	1.0	44.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Ag 50-AR-UT ppm 0.01	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2
SI 484659	Soil	0.122	0.89	1.11	542.6	40	0.4	0.40	0.07	0.65	39.09	17.2	18	1.1	54.4
SI 484660	Soil	0.102	1.19	1.52	588.3	50	0.5	0.49	0.03	0.28	24.96	16.4	26	4.1	46.5
SI 484661	Soil	0.006	0.62	0.17	24.6	23	0.1	0.15	0.01	0.04	22.99	6.9	4	1.1	14.2
SI 484662	Soil	<0.005	0.32	0.92	42.8	22	0.2	0.36	0.01	0.10	24.11	12.1	15	1.3	32.0
SI 484663	Soil	0.020	0.50	1.48	95.1	26	0.3	0.43	0.04	0.17	40.56	14.9	24	1.6	44.2
SI 484664	Soil	0.022	0.44	1.83	79.6	27	0.4	0.50	0.06	0.13	47.27	18.4	30	2.2	57.2
SI 484665	Soil	0.049	0.66	1.34	611.8	50	0.4	0.56	0.03	0.29	33.95	13.1	27	3.8	47.0
SI 484666	Soil	0.005	0.47	0.65	38.6	23	0.1	0.12	0.02	0.07	7.86	1.8	4	0.7	8.2
SI 484667	Soil	0.017	0.59	1.56	198.3	57	0.9	0.45	0.09	0.31	40.97	25.8	25	3.3	83.6
SI 484668	Soil	0.014	0.58	1.73	134.2	26	0.7	0.45	0.10	0.27	35.97	29.5	26	1.5	84.0
SI 484669	Soil	0.006	0.33	0.93	121.7	37	0.3	0.32	0.06	0.21	26.04	9.4	12	1.0	27.1
SI 484670	Soil	0.062	0.65	1.46	264.5	32	0.4	0.48	0.03	0.15	35.14	15.2	22	2.8	46.9
SI 484671	Soil	0.041	0.73	1.69	115.9	24	0.4	0.39	0.09	0.24	24.59	13.2	24	1.9	37.9
SI 484672	Soil	0.120	0.60	1.70	166.7	29	0.3	0.45	0.09	0.17	40.43	21.7	28	2.2	47.4
SI 484673	Soil	0.070	0.66	0.79	551.3	40	0.3	0.44	0.03	0.57	29.97	14.2	12	2.4	40.0
SI 484674	Soil	0.160	0.55	0.83	726.1	38	0.3	0.36	0.04	0.41	30.27	13.3	10	2.8	33.8
SI 484675	Soil	0.456	0.58	0.88	590.8	41	0.4	0.38	0.08	0.35	37.16	20.4	15	2.8	46.0
SI 484676	Soil	0.473	1.99	0.61	746.9	49	0.3	0.37	0.01	0.20	26.20	17.4	8	2.6	31.0
SI 484677	Soil	2.581	0.72	0.90	701.5	71	0.5	0.43	0.13	0.34	29.19	22.4	15	2.4	35.5
SI 484678	Soil	0.846	0.80	0.92	1045.6	56	0.4	0.33	0.11	0.53	29.95	21.4	13	2.0	28.8
SI 484679	Soil	0.178	0.58	0.68	361.3	23	0.2	0.26	0.03	0.29	21.66	8.6	10	1.0	15.5
TG 312301	Soil	<0.005	0.60	1.45	134.1	33	0.5	0.57	0.66	0.15	16.61	15.6	23	6.1	61.9
TG 312302	Soil	0.043	0.45	1.41	62.7	32	0.4	0.49	0.40	0.10	25.59	16.3	26	2.8	41.6
TG 312303	Soil	0.036	0.62	1.56	106.1	36	0.4	0.54	0.29	0.23	31.27	17.9	27	2.0	45.1
TG 312304	Soil	0.011	0.53	1.44	90.3	39	0.4	0.44	0.45	0.18	28.56	17.9	28	3.5	41.8
TG 312305	Soil	0.025	0.51	1.62	120.0	38	0.4	0.40	0.44	0.18	25.20	14.8	25	2.5	35.0
TG 312306	Soil	0.104	0.58	1.58	163.7	38	0.3	0.41	0.41	0.19	21.20	15.1	24	1.6	33.7
TG 312307	Soil	0.042	0.58	1.55	178.5	39	0.4	0.43	0.40	0.20	26.74	14.0	25	1.2	35.9
TG 312308	Soil	0.050	0.49	1.43	179.8	29	0.3	0.41	0.30	0.19	24.80	13.8	24	1.0	29.4
TG 312309	Soil	0.051	0.45	1.38	168.4	31	0.3	0.40	0.29	0.18	24.31	13.1	22	0.9	28.0
TG 312310	Soil	0.044	0.45	1.51	147.9	25	0.3	0.35	0.24	0.15	25.04	13.2	23	0.9	28.1
TG 312311	Soil	0.037	0.55	1.47	123.7	27	0.3	0.35	0.33	0.14	25.04	13.2	24	0.9	27.8
TG 312312	Soil	<0.005	0.74	1.19	290.0	67	0.5	0.60	0.55	0.37	20.50	14.1	16	1.6	42.8
TG 312313	Soil	0.016	0.99	1.04	148.3	74	0.5	0.48	1.17	0.53	10.92	8.7	13	0.9	49.9
TG 312314	Soil	<0.005	0.50	1.07	51.4	44	0.5	0.51	0.47	0.14	36.89	15.4	19	0.9	23.8

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 484619	Soil	4.52	6.4	<0.05	0.04	0.02	0.02	19.5	73.8	1.02	1660	0.45	<0.01	<0.05	60.1
SI 484620	Soil	4.52	5.2	<0.05	<0.02	0.02	0.02	13.0	53.8	0.71	1184	0.54	<0.01	<0.05	59.3
SI 484621	Soil	4.58	4.1	<0.05	<0.02	0.02	0.02	16.6	34.7	0.52	1446	0.55	<0.01	<0.05	63.3
SI 484622	Soil	1.60	2.3	<0.05	<0.02	0.14	0.06	7.7	4.2	0.12	140	0.85	0.02	0.3	9.0
SI 484623	Soil	3.06	2.0	<0.05	<0.02	0.07	0.04	12.6	8.4	0.14	399	0.83	<0.01	0.1	23.6
SI 484624	Soil	3.67	4.0	<0.05	<0.02	0.05	0.04	11.4	26.4	0.40	660	0.80	<0.01	0.2	41.6
SI 484625	Soil	3.86	4.4	<0.05	<0.02	0.08	0.04	12.1	30.2	0.45	828	0.78	<0.01	0.2	32.0
SI 484626	Soil	2.55	2.7	<0.05	<0.02	0.38	0.07	8.3	8.0	0.13	205	0.65	<0.01	0.1	18.5
SI 484627	Soil	4.21	3.6	<0.05	<0.02	0.07	0.02	9.8	28.1	0.46	782	0.54	<0.01	0.1	45.4
SI 484628	Soil	4.05	3.3	<0.05	<0.02	0.08	0.03	13.3	26.6	0.41	645	0.57	<0.01	0.1	43.9
SI 484629	Soil	4.09	2.8	<0.05	<0.02	0.04	0.02	10.1	21.5	0.31	1056	0.57	<0.01	<0.05	36.2
SI 484630	Soil	3.16	3.4	<0.05	<0.02	0.02	0.04	10.4	25.3	0.42	784	0.60	0.01	0.3	27.7
SI 484631	Soil	3.98	5.7	<0.05	<0.02	0.02	0.03	7.4	35.5	0.44	673	0.84	0.01	0.3	23.5
SI 484632	Soil	5.07	5.1	<0.05	<0.02	0.03	0.03	9.3	57.3	0.68	1407	0.88	0.03	0.1	44.5
SI 484633	Soil	2.86	4.1	<0.05	<0.02	0.01	0.04	5.0	20.0	0.29	945	0.52	0.01	0.1	17.1
SI 484634	Soil	2.94	3.0	<0.05	<0.02	0.01	0.02	12.0	13.5	0.20	276	0.57	<0.01	0.3	23.8
SI 484635	Soil	3.90	5.0	<0.05	<0.02	0.02	0.05	12.0	31.9	0.44	651	0.82	<0.01	0.4	28.3
SI 484636	Soil	2.82	4.2	<0.05	<0.02	0.03	0.04	8.0	24.0	0.36	595	0.76	0.01	0.2	26.7
SI 484637	Soil	3.82	4.7	<0.05	<0.02	0.03	0.04	7.0	33.3	0.46	552	0.66	<0.01	0.1	32.5
SI 484638	Soil	2.80	4.2	<0.05	<0.02	0.02	0.05	7.6	19.3	0.33	331	0.66	0.01	0.2	22.7
SI 484639	Soil	4.77	7.9	<0.05	<0.02	0.02	0.02	8.9	60.8	0.83	650	0.59	<0.01	0.2	39.1
SI 484640	Soil	4.82	8.5	<0.05	<0.02	0.02	0.02	4.8	68.8	0.94	440	0.71	<0.01	0.1	45.1
SI 484641	Soil	4.70	7.3	<0.05	<0.02	0.02	0.02	7.1	58.1	0.91	672	0.71	<0.01	<0.05	46.5
SI 484642	Soil	5.65	9.3	<0.05	<0.02	0.02	0.02	16.2	81.7	1.22	634	0.64	<0.01	<0.05	59.2
SI 484643	Soil	4.17	6.9	<0.05	<0.02	0.02	0.02	7.2	54.6	0.79	1028	0.35	0.01	<0.05	46.8
SI 484644	Soil	3.88	7.0	<0.05	<0.02	0.02	0.02	5.1	44.6	0.78	512	0.44	0.01	<0.05	39.3
SI 484645	Soil	4.43	7.1	<0.05	<0.02	0.02	0.02	3.7	52.3	0.77	645	0.41	<0.01	<0.05	40.3
SI 484646	Soil	3.80	7.3	<0.05	<0.02	0.02	0.02	4.6	57.7	0.77	494	0.40	<0.01	<0.05	44.1
SI 484647	Soil	3.74	5.7	<0.05	<0.02	0.03	0.03	8.9	38.6	0.59	2217	0.73	<0.01	0.2	34.9
SI 484648	Soil	3.71	2.9	<0.05	<0.02	0.06	0.05	14.6	14.3	0.27	324	0.92	<0.01	0.3	26.9
SI 484649	Soil	1.31	1.6	<0.05	<0.02	<0.01	0.03	5.0	4.1	0.09	161	0.36	0.02	0.2	6.1
SI 484650	Soil	4.04	6.3	<0.05	<0.02	0.01	0.03	14.6	62.0	0.81	1461	0.51	0.01	0.1	37.7
SI 484651	Soil	4.69	6.5	<0.05	<0.02	0.02	0.02	21.9	75.7	1.02	1216	0.65	<0.01	<0.05	57.0
SI 484652	Soil	2.88	2.0	<0.05	<0.02	0.02	0.03	20.8	16.1	0.23	611	0.50	<0.01	0.1	38.8
SI 484653	Soil	3.59	3.6	<0.05	<0.02	0.04	0.03	13.8	30.0	0.47	600	0.59	0.01	0.2	33.9
SI 484654	Soil	3.19	4.0	<0.05	<0.02	0.06	0.05	22.4	24.0	0.38	492	0.74	0.01	0.3	32.2
SI 484655	Soil	2.92	3.8	<0.05	<0.02	0.04	0.04	15.4	26.1	0.37	357	0.60	0.01	0.2	27.8
SI 484656	Soil	0.68	1.1	<0.05	<0.02	<0.01	0.03	3.4	1.3	0.05	86	0.25	0.03	0.2	2.8
SI 484657	Soil	3.56	2.9	<0.05	<0.02	0.03	0.02	18.4	22.3	0.32	930	0.56	<0.01	0.2	38.8
SI 484658	Soil	3.57	3.3	<0.05	<0.02	0.04	0.04	18.1	28.5	0.41	808	0.56	<0.01	0.3	36.0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
SI 484659	Soil	4.14	3.8	<0.05	<0.02	0.07	0.04	21.3	32.3	0.45	654	0.65	<0.01	0.3	41.0
SI 484660	Soil	4.12	5.1	<0.05	<0.02	0.04	0.05	13.4	35.1	0.48	938	0.82	0.01	0.2	30.6
SI 484661	Soil	1.12	2.5	<0.05	<0.02	<0.01	0.02	12.2	0.4	0.01	901	0.39	<0.01	<0.05	13.5
SI 484662	Soil	3.04	4.2	<0.05	<0.02	0.01	0.02	13.3	17.3	0.20	565	0.64	<0.01	0.3	27.9
SI 484663	Soil	4.07	5.5	<0.05	<0.02	0.02	0.04	23.5	46.2	0.54	594	0.66	<0.01	0.4	38.2
SI 484664	Soil	4.51	6.1	<0.05	<0.02	0.02	0.02	27.9	66.6	0.75	538	0.60	<0.01	0.2	48.4
SI 484665	Soil	3.90	6.8	<0.05	<0.02	0.05	0.07	17.9	30.2	0.39	716	1.14	<0.01	0.4	30.4
SI 484666	Soil	0.85	2.6	<0.05	<0.02	<0.01	0.02	4.0	2.1	0.04	60	0.33	0.02	0.2	3.4
SI 484667	Soil	4.30	5.5	<0.05	<0.02	0.04	0.04	22.0	54.5	0.61	743	0.94	<0.01	0.3	49.9
SI 484668	Soil	4.84	5.7	<0.05	<0.02	0.03	0.02	20.5	69.6	0.74	853	0.69	<0.01	0.1	54.6
SI 484669	Soil	2.12	3.7	<0.05	<0.02	0.02	0.04	13.4	15.3	0.23	488	0.82	0.02	0.4	21.3
SI 484670	Soil	3.73	5.4	<0.05	<0.02	0.03	0.03	20.0	57.8	0.68	806	0.70	<0.01	<0.05	41.9
SI 484671	Soil	3.70	5.7	<0.05	<0.02	0.02	0.03	13.3	61.5	0.79	575	0.56	<0.01	0.1	42.6
SI 484672	Soil	4.16	6.2	<0.05	<0.02	0.02	0.03	23.0	65.6	0.81	1081	0.70	<0.01	<0.05	49.3
SI 484673	Soil	3.64	2.4	<0.05	<0.02	0.02	0.04	15.8	12.5	0.19	569	0.88	<0.01	0.1	29.3
SI 484674	Soil	3.12	2.2	<0.05	<0.02	0.02	0.05	15.9	10.4	0.17	485	0.89	0.01	0.1	25.6
SI 484675	Soil	3.74	2.6	<0.05	<0.02	0.03	0.05	18.9	12.4	0.23	1022	0.99	0.01	0.3	36.2
SI 484676	Soil	3.36	2.2	<0.05	<0.02	0.02	0.04	13.9	4.6	0.10	720	0.74	<0.01	0.2	31.0
SI 484677	Soil	3.58	3.0	<0.05	<0.02	0.02	0.04	14.8	17.2	0.32	1213	0.75	<0.01	0.3	40.7
SI 484678	Soil	3.68	2.5	<0.05	<0.02	0.04	0.05	14.7	11.9	0.23	1230	0.80	<0.01	0.3	33.4
SI 484679	Soil	2.50	2.9	<0.05	<0.02	0.04	0.03	11.1	8.7	0.13	310	0.62	<0.01	0.6	18.6
TG 312301	Soil	3.69	4.7	<0.05	<0.02	0.02	0.03	8.9	46.7	0.62	410	0.53	0.01	0.1	40.5
TG 312302	Soil	3.53	5.4	<0.05	<0.02	0.02	0.03	13.0	54.6	0.62	380	0.44	0.01	0.1	43.1
TG 312303	Soil	3.70	5.5	<0.05	<0.02	0.02	0.03	17.3	61.0	0.71	590	0.43	<0.01	0.1	45.8
TG 312304	Soil	3.21	5.9	<0.05	<0.02	0.02	0.04	15.7	69.0	0.69	667	0.40	<0.01	0.1	48.3
TG 312305	Soil	3.66	5.1	<0.05	<0.02	0.02	0.03	13.4	57.2	0.71	462	0.33	<0.01	0.1	39.4
TG 312306	Soil	3.56	4.4	<0.05	<0.02	0.02	0.04	11.6	51.7	0.66	504	0.33	<0.01	0.1	36.8
TG 312307	Soil	3.53	5.2	<0.05	<0.02	0.02	0.04	14.9	60.0	0.68	451	0.38	<0.01	0.2	40.8
TG 312308	Soil	3.37	4.6	<0.05	<0.02	0.02	0.03	13.9	50.7	0.63	429	0.32	<0.01	0.1	36.7
TG 312309	Soil	3.26	4.6	<0.05	<0.02	0.02	0.03	13.6	50.6	0.61	415	0.32	<0.01	0.1	34.9
TG 312310	Soil	3.58	5.1	<0.05	<0.02	0.02	0.02	13.4	56.5	0.68	411	0.32	<0.01	0.1	36.8
TG 312311	Soil	3.43	4.5	<0.05	<0.02	0.01	0.03	13.8	52.9	0.65	433	0.29	<0.01	0.1	34.4
TG 312312	Soil	3.31	3.3	<0.05	<0.02	0.02	0.07	11.7	37.5	0.36	691	0.45	0.01	0.4	27.4
TG 312313	Soil	2.36	2.6	<0.05	0.05	0.02	0.07	6.7	21.2	0.32	295	0.53	0.02	0.3	24.3
TG 312314	Soil	2.64	3.7	<0.05	<0.02	0.01	0.05	18.5	41.6	0.44	565	0.32	<0.01	0.3	28.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 484619	Soil	511	44.9	1.2	<0.01	<0.01	0.15	2.7	<0.2	<0.2	14.0	<0.01	0.11	9	<0.005
SI 484620	Soil	508	36.6	1.5	<0.01	<0.01	1.01	2.5	<0.2	<0.2	13.9	<0.01	0.10	7	<0.005
SI 484621	Soil	525	44.5	1.7	<0.01	0.02	1.10	2.6	0.3	<0.2	19.6	<0.01	0.17	9	<0.005
SI 484622	Soil	874	1096.4	5.5	<0.01	0.10	6.67	0.9	0.5	1.5	26.6	<0.01	0.09	2	0.017
SI 484623	Soil	557	436.1	4.4	<0.01	0.07	5.83	1.5	0.5	0.5	29.8	<0.01	0.18	4	<0.005
SI 484624	Soil	745	168.9	4.4	<0.01	0.06	4.98	1.7	0.5	0.9	26.1	<0.01	0.20	7	0.008
SI 484625	Soil	862	386.2	5.4	<0.01	0.07	3.35	0.7	0.4	1.1	19.0	<0.01	0.13	1	0.006
SI 484626	Soil	717	1694.3	7.5	<0.01	0.16	6.98	0.7	0.5	2.4	33.4	<0.01	0.08	1	<0.005
SI 484627	Soil	680	390.8	2.3	<0.01	0.02	2.19	1.6	0.2	0.5	19.2	<0.01	0.17	7	<0.005
SI 484628	Soil	657	360.6	2.8	<0.01	0.02	2.32	1.6	<0.2	0.5	21.1	<0.01	0.13	7	<0.005
SI 484629	Soil	537	142.8	2.4	<0.01	0.01	1.96	2.0	<0.2	0.2	14.9	<0.01	0.10	14	<0.005
SI 484630	Soil	936	60.6	4.1	<0.01	0.03	0.57	0.9	0.3	0.2	18.5	<0.01	0.11	1	0.011
SI 484631	Soil	1207	48.4	5.2	<0.01	0.06	0.08	0.4	0.6	0.2	5.2	<0.01	0.16	0	0.006
SI 484632	Soil	1056	78.7	3.2	<0.01	0.02	3.72	0.8	0.4	<0.2	7.0	<0.01	0.14	1	<0.005
SI 484633	Soil	1303	49.6	5.3	<0.01	0.08	7.04	0.2	0.3	<0.2	10.0	<0.01	0.09	<0.2	<0.005
SI 484634	Soil	482	30.0	3.5	<0.01	0.02	1.36	0.7	0.3	0.2	6.4	<0.01	0.10	2	0.008
SI 484635	Soil	793	66.8	6.9	<0.01	0.05	1.29	0.4	0.5	0.3	8.7	<0.01	0.15	0	0.006
SI 484636	Soil	932	112.2	6.5	<0.01	0.07	1.77	0.3	0.4	0.3	14.9	<0.01	0.11	0	<0.005
SI 484637	Soil	1578	92.9	4.2	<0.01	0.10	2.47	0.3	0.5	<0.2	12.6	<0.01	0.10	0	<0.005
SI 484638	Soil	1078	90.7	6.0	<0.01	0.08	1.09	0.2	0.4	0.2	16.2	<0.01	0.07	<0.2	<0.005
SI 484639	Soil	1040	46.4	3.1	<0.01	0.04	0.47	1.1	0.5	<0.2	4.2	<0.01	0.15	1	<0.005
SI 484640	Soil	597	28.5	2.8	<0.01	0.03	<0.05	1.2	0.4	<0.2	3.9	<0.01	0.11	2	<0.005
SI 484641	Soil	405	80.7	2.4	<0.01	0.05	0.68	2.1	<0.2	<0.2	6.5	<0.01	0.16	4	<0.005
SI 484642	Soil	398	50.7	1.8	<0.01	<0.01	<0.05	2.5	<0.2	<0.2	4.1	<0.01	0.08	8	<0.005
SI 484643	Soil	636	27.3	3.3	<0.01	0.02	0.07	1.5	<0.2	<0.2	8.8	<0.01	0.08	2	<0.005
SI 484644	Soil	552	28.2	3.1	<0.01	0.03	0.10	1.2	0.3	<0.2	4.8	<0.01	0.10	2	<0.005
SI 484645	Soil	913	23.7	2.5	<0.01	0.06	<0.05	1.0	0.3	<0.2	3.3	<0.01	0.13	1	<0.005
SI 484646	Soil	548	27.3	2.8	<0.01	0.03	<0.05	1.1	<0.2	<0.2	4.2	<0.01	0.06	1	<0.005
SI 484647	Soil	1508	40.9	4.0	<0.01	0.08	0.19	0.6	0.6	<0.2	23.6	<0.01	0.12	0	<0.005
SI 484648	Soil	674	120.7	5.9	<0.01	0.09	4.64	0.9	0.9	0.3	27.2	<0.01	0.17	1	0.008
SI 484649	Soil	705	23.8	3.1	<0.01	0.04	0.88	0.3	0.3	<0.2	11.9	<0.01	0.05	<0.2	0.012
SI 484650	Soil	886	25.9	4.3	<0.01	0.03	<0.05	0.7	0.3	<0.2	9.1	<0.01	0.09	0	<0.005
SI 484651	Soil	518	34.2	1.8	<0.01	<0.01	0.55	2.0	<0.2	<0.2	9.8	<0.01	0.11	5	<0.005
SI 484652	Soil	434	36.2	2.2	<0.01	0.01	1.47	2.2	<0.2	<0.2	44.5	<0.01	0.08	8	<0.005
SI 484653	Soil	608	182.6	4.3	<0.01	0.02	1.97	1.4	0.4	0.4	15.5	<0.01	0.08	3	0.010
SI 484654	Soil	836	219.0	6.2	<0.01	0.05	2.82	1.4	0.4	0.6	23.7	<0.01	0.12	3	0.014
SI 484655	Soil	697	178.4	4.6	<0.01	0.05	2.10	0.6	0.5	0.3	16.3	<0.01	0.09	1	0.007
SI 484656	Soil	687	30.5	2.5	<0.01	0.02	0.30	0.3	0.4	<0.2	9.9	<0.01	0.03	0	0.017
SI 484657	Soil	545	116.1	2.7	<0.01	0.02	1.67	1.5	0.4	0.2	11.3	<0.01	0.07	6	0.007
SI 484658	Soil	740	214.6	3.9	<0.01	0.02	1.63	2.1	0.3	0.3	13.7	<0.01	0.07	10	0.013

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
SI 484659	Soil	737	296.0	4.5	<0.01	0.02	2.32	2.2	0.3	0.5	19.0	<0.01	0.12	11	0.015
SI 484660	Soil	1240	234.9	7.5	<0.01	0.06	2.96	0.3	0.7	0.4	15.8	<0.01	0.12	0	<0.005
SI 484661	Soil	453	14.2	2.2	<0.01	0.02	0.27	<0.1	<0.2	<0.2	5.6	<0.01	0.05	<0.2	<0.005
SI 484662	Soil	556	33.7	3.8	<0.01	0.02	0.36	0.4	0.5	0.2	6.9	<0.01	0.05	0	0.006
SI 484663	Soil	705	40.2	5.4	<0.01	0.02	0.18	1.0	0.3	0.3	8.5	<0.01	0.11	2	0.007
SI 484664	Soil	663	48.6	3.6	<0.01	0.01	<0.05	1.1	<0.2	<0.2	10.9	<0.01	0.10	2	<0.005
SI 484665	Soil	1220	178.3	9.9	<0.01	0.07	2.15	0.4	0.5	0.6	15.6	<0.01	0.13	<0.2	0.006
SI 484666	Soil	491	23.6	2.2	<0.01	0.06	0.22	0.1	0.5	<0.2	5.3	<0.01	0.05	<0.2	0.006
SI 484667	Soil	829	122.8	4.9	<0.01	0.03	1.10	1.7	0.6	0.3	15.2	<0.01	0.12	3	0.010
SI 484668	Soil	800	89.5	2.5	<0.01	<0.01	0.83	2.2	<0.2	0.2	11.5	<0.01	0.14	11	0.006
SI 484669	Soil	667	53.5	5.4	<0.01	0.04	1.54	0.7	0.4	0.3	10.3	<0.01	0.08	0	0.018
SI 484670	Soil	509	79.4	3.4	<0.01	0.02	2.21	1.2	<0.2	<0.2	26.9	<0.01	0.17	2	<0.005
SI 484671	Soil	680	46.5	2.8	<0.01	0.03	0.71	1.0	0.2	<0.2	18.5	<0.01	0.09	1	<0.005
SI 484672	Soil	612	54.2	3.1	<0.01	0.02	0.81	1.5	0.4	<0.2	23.6	<0.01	0.08	2	<0.005
SI 484673	Soil	586	47.4	4.6	<0.01	0.04	3.40	0.9	0.4	<0.2	32.1	<0.01	0.18	1	<0.005
SI 484674	Soil	958	63.0	5.3	<0.01	0.05	2.60	0.7	0.5	0.2	31.1	<0.01	0.15	1	<0.005
SI 484675	Soil	1104	61.9	6.7	<0.01	0.04	2.07	1.8	0.7	0.3	27.2	<0.01	0.13	6	0.012
SI 484676	Soil	758	45.6	6.4	<0.01	0.04	1.56	0.5	0.4	0.2	8.8	<0.01	0.11	1	<0.005
SI 484677	Soil	967	55.8	5.1	<0.01	0.03	2.36	1.6	0.4	0.2	16.9	<0.01	0.12	5	0.010
SI 484678	Soil	1357	109.0	6.0	<0.01	0.05	2.18	1.5	0.9	0.3	20.1	<0.01	0.11	3	0.012
SI 484679	Soil	551	136.9	4.5	<0.01	0.04	1.14	0.7	0.4	0.3	11.4	<0.01	0.04	1	0.013
TG 312301	Soil	611	27.6	4.0	<0.01	0.06	0.46	2.0	0.8	<0.2	31.1	<0.01	0.09	3	<0.005
TG 312302	Soil	466	24.1	4.0	<0.01	0.03	<0.05	2.2	0.6	<0.2	23.4	<0.01	0.09	5	<0.005
TG 312303	Soil	545	39.1	3.3	<0.01	0.02	<0.05	1.9	0.3	<0.2	20.5	<0.01	0.13	6	<0.005
TG 312304	Soil	571	31.4	4.2	<0.01	0.03	<0.05	2.0	0.4	<0.2	28.2	<0.01	0.08	7	<0.005
TG 312305	Soil	462	30.1	4.3	<0.01	0.03	<0.05	1.6	0.5	<0.2	28.9	<0.01	0.12	5	<0.005
TG 312306	Soil	479	27.9	4.3	<0.01	0.02	<0.05	1.4	0.4	<0.2	25.5	<0.01	0.07	4	<0.005
TG 312307	Soil	508	28.9	3.5	<0.01	0.02	<0.05	1.8	0.5	<0.2	23.3	<0.01	0.10	5	<0.005
TG 312308	Soil	459	26.3	2.8	<0.01	0.02	<0.05	1.4	0.3	<0.2	17.7	<0.01	0.08	5	<0.005
TG 312309	Soil	434	25.6	2.6	<0.01	0.02	<0.05	1.4	0.3	<0.2	16.9	<0.01	0.08	5	<0.005
TG 312310	Soil	398	23.4	2.6	<0.01	0.01	<0.05	1.5	0.4	<0.2	16.7	<0.01	0.05	5	<0.005
TG 312311	Soil	446	22.3	2.9	<0.01	0.02	<0.05	1.4	0.2	<0.2	18.7	<0.01	0.07	5	<0.005
TG 312312	Soil	456	48.8	7.1	<0.01	0.03	0.08	1.5	0.5	0.2	34.6	<0.01	0.08	3	<0.005
TG 312313	Soil	968	29.1	5.0	<0.01	0.16	0.37	0.8	0.8	<0.2	74.7	<0.01	0.10	1	<0.005
TG 312314	Soil	572	25.3	5.1	<0.01	0.04	<0.05	1.5	<0.2	<0.2	33.0	<0.01	0.06	6	0.006

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 484619	Soil	<0.05	1	18	1.56	3.6	126	3.8
SI 484620	Soil	<0.05	1	16	1.60	4.7	125	0.7
SI 484621	Soil	<0.05	1	13	1.81	4.9	133	1.0
SI 484622	Soil	0.06	1	14	1.90	2.0	52	0.5
SI 484623	Soil	<0.05	2	11	1.96	2.6	135	<0.5
SI 484624	Soil	<0.05	2	17	2.31	4.0	138	<0.5
SI 484625	Soil	<0.05	1	20	4.27	2.6	107	<0.5
SI 484626	Soil	0.08	1	10	1.98	2.4	141	<0.5
SI 484627	Soil	<0.05	2	14	1.53	3.7	163	<0.5
SI 484628	Soil	<0.05	2	14	1.84	3.8	145	<0.5
SI 484629	Soil	<0.05	2	11	2.09	6.1	149	2.2
SI 484630	Soil	<0.05	1	17	2.97	2.8	108	<0.5
SI 484631	Soil	<0.05	2	20	2.87	2.4	90	<0.5
SI 484632	Soil	<0.05	2	18	1.00	4.3	194	<0.5
SI 484633	Soil	<0.05	1	15	0.94	1.3	150	<0.5
SI 484634	Soil	<0.05	1	15	1.88	2.1	81	<0.5
SI 484635	Soil	<0.05	1	22	2.44	2.7	109	<0.5
SI 484636	Soil	<0.05	1	17	2.71	3.1	111	<0.5
SI 484637	Soil	<0.05	2	18	1.16	3.0	114	<0.5
SI 484638	Soil	<0.05	1	18	1.88	3.2	88	<0.5
SI 484639	Soil	<0.05	1	24	1.92	1.5	125	<0.5
SI 484640	Soil	<0.05	1	21	2.42	1.0	102	<0.5
SI 484641	Soil	<0.05	1	16	0.59	1.9	111	<0.5
SI 484642	Soil	<0.05	2	22	1.87	2.4	128	1.5
SI 484643	Soil	<0.05	1	19	1.68	2.4	99	<0.5
SI 484644	Soil	<0.05	1	19	1.41	1.1	97	<0.5
SI 484645	Soil	<0.05	1	20	1.75	1.0	102	<0.5
SI 484646	Soil	<0.05	1	19	2.25	1.1	100	<0.5
SI 484647	Soil	<0.05	1	28	1.99	2.5	89	0.7
SI 484648	Soil	<0.05	2	18	10.38	4.2	121	<0.5
SI 484649	Soil	<0.05	1	11	3.18	1.3	30	<0.5
SI 484650	Soil	<0.05	1	22	1.87	2.9	88	<0.5
SI 484651	Soil	<0.05	1	18	2.25	3.4	121	<0.5
SI 484652	Soil	<0.05	1	9	1.80	3.6	125	0.7
SI 484653	Soil	<0.05	2	17	2.79	3.0	115	<0.5
SI 484654	Soil	<0.05	2	19	1.23	3.9	136	<0.5
SI 484655	Soil	<0.05	1	16	2.72	2.8	111	<0.5
SI 484656	Soil	<0.05	0	11	2.28	1.2	16	<0.5
SI 484657	Soil	<0.05	2	14	2.50	3.5	128	<0.5
SI 484658	Soil	<0.05	2	17	2.18	4.6	125	1.0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 484659	Soil	<0.05	2	19	2.09	4.7	157	0.6
SI 484660	Soil	0.05	2	23	2.33	3.8	126	<0.5
SI 484661	Soil	<0.05	0	12	0.98	1.2	51	<0.5
SI 484662	Soil	<0.05	1	18	1.73	2.1	92	<0.5
SI 484663	Soil	<0.05	1	22	1.92	2.6	118	<0.5
SI 484664	Soil	<0.05	1	20	2.37	3.2	135	<0.5
SI 484665	Soil	0.08	2	34	2.10	6.2	114	<0.5
SI 484666	Soil	<0.05	0	13	1.68	0.8	16	<0.5
SI 484667	Soil	<0.05	2	22	3.09	6.3	153	<0.5
SI 484668	Soil	<0.05	2	18	2.43	4.8	157	0.6
SI 484669	Soil	<0.05	1	23	1.76	2.6	78	<0.5
SI 484670	Soil	<0.05	1	16	0.73	3.4	111	<0.5
SI 484671	Soil	<0.05	1	16	2.26	3.9	102	<0.5
SI 484672	Soil	<0.05	1	19	1.49	4.1	122	<0.5
SI 484673	Soil	<0.05	2	11	5.09	2.9	117	<0.5
SI 484674	Soil	<0.05	2	13	7.58	3.2	118	<0.5
SI 484675	Soil	0.06	2	18	13.48	4.9	131	<0.5
SI 484676	Soil	<0.05	2	13	21.06	3.3	115	<0.5
SI 484677	Soil	<0.05	2	17	21.78	5.6	126	<0.5
SI 484678	Soil	<0.05	2	18	76.10	6.1	145	<0.5
SI 484679	Soil	<0.05	1	18	12.14	2.3	117	<0.5
TG 312301	Soil	<0.05	3	13	2.15	6.2	143	1.1
TG 312302	Soil	<0.05	2	15	1.31	3.9	131	0.9
TG 312303	Soil	<0.05	2	16	2.26	4.3	130	0.9
TG 312304	Soil	<0.05	2	17	2.14	4.3	132	2.0
TG 312305	Soil	<0.05	2	14	2.30	3.6	124	0.7
TG 312306	Soil	<0.05	2	13	0.81	3.2	126	<0.5
TG 312307	Soil	<0.05	2	17	1.24	3.6	119	1.0
TG 312308	Soil	<0.05	2	14	4.47	2.9	120	0.8
TG 312309	Soil	<0.05	1	13	2.79	2.9	118	0.9
TG 312310	Soil	<0.05	1	13	2.02	2.9	110	0.8
TG 312311	Soil	<0.05	2	13	2.68	3.0	113	0.7
TG 312312	Soil	<0.05	2	13	2.26	7.3	97	0.8
TG 312313	Soil	<0.05	3	9	2.12	8.0	100	2.4
TG 312314	Soil	<0.05	1	13	0.97	5.0	92	1.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Au	Ag	Al	As	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr	Cs	Cu
		Au-1AT-AA	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample	Sample	g/ton	ppm	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
Description	Type	0.005	0.01	0.01	0.1	5	0.05	0.01	0.01	0.01	0.02	0.1	1	0.05	0.2
QCV1008-00726-0001-BLK			0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
SI 484619	Soil		0.42	1.91	54.0	22	0.4	0.46	0.12	0.14	35.61	26.7	28	1.7	61.9
SI 484619 Dup			0.25	1.85	55.0	21	0.4	0.47	0.12	0.13	37.07	28.0	29	1.7	62.2
STD-ME-6 expected			101												6130.0
STD-ME-6 result			>100	1.02	250.5	16	0.2	5.83	0.55	32.01	7.82	<0.1	28	0.3	5859.9
SI 484637	Soil		0.89	1.28	429.7	35	0.4	0.47	0.06	0.27	12.57	12.9	24	8.5	48.8
SI 484637 Dup			0.89	1.26	430.2	36	0.4	0.48	0.06	0.28	13.37	12.7	24	8.7	49.9
STD-OREAS-45P-AR expected					4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result				3.15	10.9	204	0.6	0.18	0.24	0.10	36.72	115.2	925	1.2	611.9
SI 484655	Soil		0.63	1.03	618.1	31	0.3	0.35	0.05	0.44	29.32	10.6	17	1.1	34.5
SI 484655 Dup			0.67	1.05	605.2	29	0.3	0.33	0.05	0.42	28.63	10.6	16	1.1	34.1
STD-ME-6 expected			101												6130.0
STD-ME-6 result			>100	1.01	256.0	20	0.2	5.82	0.60	33.72	8.70	<0.1	29	0.3	6440.7
SI 484673	Soil		0.66	0.79	551.3	40	0.3	0.44	0.03	0.57	29.97	14.2	12	2.4	40.0
SI 484673 Dup			0.69	0.79	533.1	38	0.3	0.42	0.03	0.53	29.18	13.7	12	2.4	38.0
STD-OREAS-45P-AR expected					4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result				2.94	7.2	211	0.7	0.21	0.23	0.10	38.41	120.0	909	1.2	642.0
TG 312312	Soil		0.74	1.19	290.0	67	0.5	0.60	0.55	0.37	20.50	14.1	16	1.6	42.8
TG 312312 Dup			0.65	1.15	300.3	66	0.5	0.58	0.54	0.37	20.47	14.0	16	1.6	43.2
QCV1008-00726-0011-BLK			0.02	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2
STD-OREAS-45P-AR expected					4.4			0.18		0.09		107.0	892		674.0
STD-OREAS-45P-AR result				3.00	7.9	193	0.6	0.18	0.22	0.09	35.57	105.2	850	1.0	588.1
SI 484619	Soil	0.030													
SI 484619 Dup		0.032													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.666													
SI 484637	Soil	0.087													
SI 484637 Dup		0.076													
QCV1008-00727-0004-BLK		<0.005													
SI 484655	Soil	0.082													
SI 484655 Dup		0.085													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.651													
SI 484673	Soil	0.070													
SI 484673 Dup		0.057													
QCV1008-00727-0008-BLK		<0.005													
TG 312312	Soil	<0.005													
TG 312312 Dup		0.006													
QCV1008-00727-0010-BLK		<0.005													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.790													

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Fe 50-AR-UT % 0.01	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2
QCV1008-00726-0001-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
SI 484619	Soil	4.52	6.4	<0.05	0.04	0.02	0.02	19.5	73.8	1.02	1660	0.45	<0.01	<0.05	60.1
SI 484619 Dup		4.49	6.4	<0.05	0.04	0.02	0.02	20.1	74.9	0.94	1600	0.43	<0.01	<0.05	59.5
STD-ME-6 expected															
STD-ME-6 result		5.08	3.9	<0.05	0.18	0.45	0.09	3.5	8.8	0.71	1674	20.15	0.06	0.1	27.8
SI 484637	Soil	3.82	4.7	<0.05	<0.02	0.03	0.04	7.0	33.3	0.46	552	0.66	<0.01	0.1	32.5
SI 484637 Dup		3.78	4.8	<0.05	<0.02	0.03	0.04	7.5	33.2	0.46	565	0.68	<0.01	0.1	32.3
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	18.9	0.1	0.53	0.10	0.08	17.0	5.8	0.12	1119	1.55	0.02	0.7	311.6
SI 484655	Soil	2.92	3.8	<0.05	<0.02	0.04	0.04	15.4	26.1	0.37	357	0.60	0.01	0.2	27.8
SI 484655 Dup		2.97	3.8	<0.05	<0.02	0.05	0.04	15.1	25.5	0.38	351	0.59	0.01	0.2	27.3
STD-ME-6 expected															
STD-ME-6 result		4.83	4.2	<0.05	0.20	0.47	0.10	3.9	9.5	0.69	1576	21.07	0.06	0.1	29.2
SI 484673	Soil	3.64	2.4	<0.05	<0.02	0.02	0.04	15.8	12.5	0.19	569	0.88	<0.01	0.1	29.3
SI 484673 Dup		3.21	2.3	<0.05	<0.02	0.02	0.04	15.7	12.1	0.19	573	0.83	<0.01	0.1	29.3
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	18.5	0.1	0.58	0.10	0.08	17.5	6.2	0.11	1051	1.50	0.02	0.8	320.1
TG 312312	Soil	3.31	3.3	<0.05	<0.02	0.02	0.07	11.7	37.5	0.36	691	0.45	0.01	0.4	27.4
TG 312312 Dup		3.27	3.4	<0.05	<0.02	0.02	0.07	11.7	36.0	0.35	703	0.43	0.01	0.4	28.3
QCV1008-00726-0011-BLK		<0.01	<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2
STD-OREAS-45P-AR expected															292.0
STD-OREAS-45P-AR result		>10	16.2	0.1	0.51	0.09	0.08	16.3	5.4	0.11	1172	1.46	0.02	0.7	284.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	P 50-AR-UT ppm 5	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005
QCV1008-00726-0001-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
SI 484619	Soil	511	44.9	1.2	<0.01	<0.01	0.15	2.7	<0.2	<0.2	14.0	<0.01	0.11	9	<0.005
SI 484619 Dup		526	43.4	1.2	<0.01	<0.01	0.10	2.7	<0.2	<0.2	14.0	<0.01	0.11	9	<0.005
STD-ME-6 expected			10200												
STD-ME-6 result		448	>10000	3.1	<0.01	2.35	407.00	3.2	2.0	1.6	24.6	<0.01	1.42	1	0.071
SI 484637	Soil	1578	92.9	4.2	<0.01	0.10	2.47	0.3	0.5	<0.2	12.6	<0.01	0.10	0	<0.005
SI 484637 Dup		1605	93.9	4.3	<0.01	0.11	2.37	0.3	0.5	<0.2	12.9	<0.01	0.11	0	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		407	20.1	10.5	<0.01	0.03	<0.05	49.7	<0.2	1.9	15.8	<0.01	0.09	7	0.175
SI 484655	Soil	697	178.4	4.6	<0.01	0.05	2.10	0.6	0.5	0.3	16.3	<0.01	0.09	1	0.007
SI 484655 Dup		716	174.0	4.6	<0.01	0.05	2.06	0.6	0.5	0.3	16.8	<0.01	0.09	1	0.007
STD-ME-6 expected			10200.0												
STD-ME-6 result		486	9814.3	3.4	<0.01	2.21	412.22	3.8	2.1	1.7	27.0	<0.01	1.32	1	0.083
SI 484673	Soil	586	47.4	4.6	<0.01	0.04	3.40	0.9	0.4	<0.2	32.1	<0.01	0.18	1	<0.005
SI 484673 Dup		601	48.1	4.5	<0.01	0.05	3.49	0.8	0.4	<0.2	32.1	<0.01	0.17	1	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		415	20.5	10.5	<0.01	0.03	<0.05	50.5	0.5	1.9	16.4	<0.01	0.11	7	0.162
TG 312312	Soil	456	48.8	7.1	<0.01	0.03	0.08	1.5	0.5	0.2	34.6	<0.01	0.08	3	<0.005
TG 312312 Dup		442	49.6	7.1	<0.01	0.03	0.07	1.5	0.5	0.3	34.0	<0.01	0.08	3	<0.005
QCV1008-00726-0011-BLK		<5	<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005
STD-OREAS-45P-AR expected			19.0				0.38								
STD-OREAS-45P-AR result		378	19.2	9.6	<0.01	0.03	<0.05	47.3	0.3	1.8	14.5	<0.01	0.12	6	0.162

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02616-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Tl 50-AR-UT ppm 0.05	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
QCV1008-00726-0001-BLK		<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
SI 484619	Soil	<0.05	1	18	1.56	3.6	126	3.8
SI 484619 Dup		<0.05	1	18	1.56	3.5	121	4.0
STD-ME-6 expected							5170	
STD-ME-6 result		0.20	1	38	2.46	5.8	5238	4.4
SI 484637	Soil	<0.05	2	18	1.16	3.0	114	<0.5
SI 484637 Dup		<0.05	2	18	1.08	3.1	117	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.05	1	205	1.43	9.6	150	22.0
SI 484655	Soil	<0.05	1	16	2.72	2.8	111	<0.5
SI 484655 Dup		<0.05	1	15	2.70	2.7	110	<0.5
STD-ME-6 expected							5170	
STD-ME-6 result		0.20	1	43	1.94	6.5	4981	5.2
SI 484673	Soil	<0.05	2	11	5.09	2.9	117	<0.5
SI 484673 Dup		<0.05	2	11	5.21	2.9	119	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.05	1	177	1.67	9.9	157	22.6
TG 312312	Soil	<0.05	2	13	2.26	7.3	97	0.8
TG 312312 Dup		<0.05	2	14	2.38	7.4	97	0.8
QCV1008-00726-0011-BLK		<0.05	<0.05	<1	<0.05	<0.05	<1	<0.5
STD-OREAS-45P-AR expected							123	
STD-OREAS-45P-AR result		0.05	1	170	2.46	9.2	138	20.4

Certificate of Analysis

10-360-02714-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 08/31/2010
Date Completed: 09/13/2010
Invoice:

Samples	Type	Preparation Description
307	Soil	SP-SS-1K/Soils, Humus Sediments 1kg dried, sieved and riffle split

Method	Description
50-AR-UT	50 Element, Aqua Regia, ICPMS, Ultra Trace Level
Au-1AT-AA	Au, 1AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SG 312315	Soil	0.026	0.74	157.0	31	0.4	0.47	0.04	0.35	33.78	29.3	<1	1.3	51.3	4.80
SG 312316	Soil	0.019	0.72	224.1	30	0.3	0.33	0.03	0.23	29.18	13.2	<1	1.1	31.9	2.66
SG 312317	Soil	0.009	0.49	86.0	17	0.1	0.18	0.04	0.07	13.56	11.4	<1	0.8	13.4	0.99
SG 312318	Soil	0.048	0.47	202.9	32	0.3	0.39	0.02	0.46	32.53	24.5	<1	2.0	36.9	3.25
SG 312319	Soil	0.095	0.52	356.1	34	0.4	0.40	0.01	0.74	45.15	20.6	<1	1.5	44.8	3.51
SG 312320	Soil	0.010	1.11	187.8	42	0.3	0.37	0.03	0.15	35.63	12.5	<1	1.0	20.1	2.95
SG 312321	Soil	0.046	0.57	251.6	30	0.2	0.32	0.02	0.16	27.02	15.6	<1	1.0	19.3	2.68
SG 312322	Soil	0.010	0.31	87.3	38	0.2	0.35	0.01	0.34	20.77	17.9	<1	1.7	32.0	2.27
SG 312323	Soil	0.018	0.77	196.3	47	0.4	0.45	0.01	0.34	50.53	31.3	<1	1.3	49.9	4.41
SG 312324	Soil	0.011	0.65	211.9	46	0.3	0.37	0.01	0.14	29.77	13.1	<1	2.5	27.6	2.67
SG 312325	Soil	0.023	0.61	198.3	50	0.3	0.37	0.02	0.29	36.81	21.1	<1	1.5	33.1	3.38
SG 312326	Soil	0.013	0.12	188.5	21	0.1	0.14	<0.01	0.11	32.77	10.8	<1	1.1	16.8	1.45
SG 312327	Soil	0.008	1.10	136.9	42	0.3	0.40	0.02	0.24	32.44	19.5	<1	1.0	25.7	3.81
SG 312328	Soil	0.006	1.53	61.4	34	0.3	0.46	0.02	0.14	36.79	28.6	<1	0.9	22.6	4.14
SG 312329	Soil	<0.005	0.46	44.8	21	0.1	0.17	0.03	0.07	15.97	5.0	<1	0.6	11.9	1.20
SG 312330	Soil	0.068	0.53	395.9	29	0.2	0.26	0.03	0.20	24.31	7.3	<1	1.0	20.9	2.06
SG 312331	Soil	0.097	0.27	526.7	31	0.2	0.26	0.02	0.63	21.98	11.6	<1	1.5	19.3	2.38
SG 312332	Soil	0.094	0.48	279.1	43	0.9	0.32	0.06	0.48	40.80	31.5	<1	1.4	54.6	4.32
SG 312333	Soil	0.057	0.46	243.0	29	0.3	0.43	0.01	0.53	27.28	18.3	<1	2.0	39.0	3.30
SG 312334	Soil	0.059	0.34	630.5	36	0.3	0.42	0.02	0.44	37.07	12.0	<1	3.1	25.8	2.14
SG 312335	Soil	0.087	0.61	685.3	38	0.3	0.24	0.04	0.34	33.23	13.9	<1	1.1	25.7	2.44
SG 312336	Soil	0.071	0.58	505.6	26	0.2	0.25	0.04	0.28	23.93	11.0	<1	1.5	26.5	2.18
SG 312337	Soil	0.030	0.35	229.8	22	0.2	0.44	0.01	0.39	31.28	16.0	<1	2.8	35.0	2.73
SG 312338	Soil	0.101	0.58	816.0	39	0.3	0.33	0.02	0.53	26.21	11.7	<1	2.3	25.7	2.91
SG 312339	Soil	0.017	0.48	215.0	22	0.3	0.28	0.20	0.77	13.13	17.3	<1	1.2	28.5	2.60
SG 312340	Soil	0.092	0.52	464.5	21	0.4	0.39	0.01	0.85	20.56	25.2	<1	1.6	66.3	4.14
SG 312341	Soil	0.070	0.39	1037.5	15	0.4	0.26	0.03	3.40	20.00	14.4	<1	1.4	35.8	4.76
SG 312342	Soil	0.089	0.22	550.3	29	0.2	0.33	0.02	1.06	24.30	18.7	<1	1.9	30.8	3.11
SG 312343	Soil	0.102	0.28	415.3	24	0.3	0.46	0.08	0.96	15.27	21.0	<1	1.3	31.8	2.86
SG 312344	Soil	0.013	2.48	35.9	18	0.4	0.37	0.10	0.05	36.12	27.9	38	1.3	57.6	5.39
SG 312345	Soil	0.007	2.56	36.5	22	0.5	0.43	0.11	0.05	38.40	25.6	34	1.7	63.4	5.42
SG 312346	Soil	0.085	0.77	166.4	38	0.6	0.46	0.12	0.05	36.62	25.8	<1	2.3	43.6	3.18
SG 312347	Soil	0.092	1.09	180.0	38	0.5	0.40	0.06	0.07	42.62	23.9	<1	1.8	45.1	3.95
SG 312348	Soil	0.065	0.64	212.0	30	0.5	0.57	0.02	0.30	25.81	27.1	<1	2.1	61.7	4.06
SG 312349	Soil	0.083	0.23	136.7	25	0.3	0.79	<0.01	0.09	20.51	15.7	<1	3.8	68.0	3.78
SG 312350	Soil	0.093	0.32	601.0	29	0.3	0.42	0.02	0.62	20.61	10.1	<1	2.3	36.3	3.00
SG 312351	Soil	0.049	0.31	351.4	28	0.3	0.29	0.02	0.80	24.12	11.8	<1	1.9	26.2	2.08
SG 312352	Soil	0.114	0.45	644.7	23	0.4	0.35	0.02	1.13	26.23	11.1	<1	1.7	40.4	2.91
SG 312353	Soil	0.113	0.47	765.3	26	0.5	0.48	<0.01	1.91	25.86	25.7	<1	2.6	57.6	4.44
SG 312354	Soil	0.022	0.51	142.6	16	0.2	0.17	0.06	0.37	12.78	13.5	<1	0.9	25.5	1.83

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SG 312355	Soil	0.112	0.32	808.0	15	0.1	0.23	0.02	2.24	16.66	5.3	<1	1.3	26.2	1.97
SG 312356	Soil	0.019	0.36	642.3	19	0.3	0.24	0.02	2.08	19.54	7.8	<1	1.3	33.4	2.20
SG 312357	Soil	0.128	0.31	405.2	25	0.3	0.34	0.04	0.98	23.74	20.6	<1	1.5	32.0	2.75
SG 312358	Soil	0.488	0.41	627.5	24	0.4	0.42	0.03	0.94	37.56	24.6	<1	1.4	43.4	3.61
SG 312359	Soil	0.100	2.44	166.1	20	0.3	0.34	0.08	0.11	24.16	20.8	29	1.9	43.2	5.11
SG 312360	Soil	0.011	1.70	51.2	42	0.6	0.37	0.15	0.12	30.65	34.2	23	1.2	64.4	4.06
SG 312361	Soil	0.057	1.86	117.5	29	0.4	0.40	0.08	0.06	31.27	29.4	32	2.0	50.6	4.94
SG 312362	Soil	0.052	1.51	110.2	27	0.5	0.42	0.12	0.09	35.92	29.8	26	2.0	49.7	4.36
SG 312363	Soil	0.005	1.55	40.5	42	0.5	0.37	0.02	0.08	24.71	18.9	<1	1.5	27.1	3.44
SG 312364	Soil	0.010	1.35	47.3	43	0.5	0.32	0.11	0.10	25.21	19.9	<1	1.3	34.0	3.15
SG 312365	Soil	0.007	1.45	31.7	34	0.6	0.33	0.20	0.12	26.64	22.4	<1	0.8	56.0	3.40
SG 312366	Soil	0.005	1.27	28.6	38	0.7	0.35	0.16	0.19	24.42	20.1	<1	0.6	49.5	2.92
SG 312367	Soil	0.006	1.46	16.4	52	0.8	0.36	0.46	0.09	19.25	13.9	24	0.5	69.1	3.00
SG 312368	Soil	0.009	1.20	41.7	35	0.7	0.38	0.31	0.06	14.47	17.5	<1	0.9	62.4	2.44
SG 312369	Soil	<0.005	1.34	14.2	30	0.6	0.36	0.16	0.07	20.76	23.9	<1	1.1	48.2	3.55
SG 312370	Soil	<0.005	1.34	12.2	28	0.7	0.45	0.22	0.06	20.61	16.8	<1	1.3	53.6	3.25
SG 312371	Soil	<0.005	1.24	8.4	30	0.4	0.40	0.16	0.06	19.32	18.4	<1	0.8	44.1	2.92
SG 312372	Soil	0.010	1.56	25.9	37	0.7	0.34	0.22	0.09	20.51	17.4	<1	0.8	44.9	3.12
SG 312373	Soil	0.061	1.68	37.1	35	0.7	0.45	0.19	0.13	32.16	28.1	<1	1.1	67.1	3.98
SG 312374	Soil	0.009	1.40	45.4	30	0.7	0.42	0.26	0.15	30.22	24.7	<1	0.8	60.4	3.65
SG 312375	Soil	0.007	1.56	51.7	41	0.6	0.36	0.21	0.27	21.97	20.9	<1	0.8	45.8	3.46
SG 312376	Soil	0.007	1.28	51.6	36	0.6	0.34	0.13	0.18	27.95	23.7	<1	0.8	43.5	3.34
SG 312377	Soil	0.187	1.26	163.3	36	0.5	0.28	0.06	0.16	15.02	23.1	<1	1.5	36.4	4.39
SG 312378	Soil	1.607	0.25	1074.5	27	0.2	0.47	0.02	0.67	13.46	10.9	<1	1.5	35.1	2.74
SG 312379	Soil	0.011	0.36	85.2	22	0.4	0.33	0.06	0.04	47.23	22.8	<1	1.4	42.5	3.04
SG 312380	Soil	0.027	1.17	114.7	50	0.5	0.30	0.09	0.17	17.52	16.1	<1	3.6	31.5	3.65
SG 312381	Soil	0.012	0.96	118.2	37	0.4	0.29	0.03	0.06	53.96	25.2	<1	3.9	39.1	3.20
SG 312382	Soil	0.006	1.42	80.0	56	0.3	0.38	0.02	0.11	22.29	18.5	<1	1.8	28.4	3.97
SG 312383	Soil	0.013	2.14	107.9	30	0.5	0.47	0.01	0.15	35.47	22.9	25	2.6	53.3	5.39
SG 312384	Soil	0.015	1.81	100.9	27	0.3	0.42	0.02	0.11	29.08	18.7	23	2.5	34.1	4.09
SG 312385	Soil	<0.005	1.09	8.9	23	0.3	0.19	0.03	0.06	16.14	13.8	<1	2.7	24.2	2.12
SG 312386	Soil	0.011	2.09	71.8	33	0.4	0.48	0.01	0.12	27.61	23.1	21	1.8	43.8	5.38
SG 312387	Soil	0.010	1.62	57.3	31	0.4	0.31	0.03	0.07	25.11	12.0	<1	1.8	34.0	3.50
SG 312388	Soil	<0.005	1.31	30.6	19	0.4	0.48	<0.01	0.10	26.95	31.1	<1	2.4	46.6	4.18
SG 312389	Soil	0.014	1.03	45.9	28	0.5	0.28	0.03	0.06	27.75	14.5	<1	3.5	33.2	3.07
SG 312390	Soil	<0.005	1.68	18.9	30	0.3	0.30	0.02	0.06	21.52	12.0	<1	2.5	34.8	3.68
SG 312391	Soil	0.013	2.26	42.7	59	0.6	0.44	0.02	0.13	40.10	34.2	26	1.9	43.9	4.99
SG 312392	Soil	0.012	2.15	49.9	30	0.5	0.37	0.04	0.10	45.59	20.5	27	1.2	43.7	4.85
SG 312393	Soil	<0.005	2.18	44.2	30	0.4	0.39	0.04	0.09	42.21	20.2	31	2.4	44.9	4.79
SG 312394	Soil	0.043	1.96	54.5	28	0.8	0.45	0.02	0.10	45.83	39.1	25	7.2	67.8	5.66

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SG 312395	Soil	0.009	0.91	10.0	16	0.2	0.20	0.01	0.05	7.73	11.1	<1	1.4	19.1	1.99
SG 312396	Soil	<0.005	0.91	12.6	25	0.2	0.22	0.02	0.04	14.84	15.5	<1	1.7	14.4	1.82
SG 312397	Soil	0.012	1.83	31.3	29	0.6	0.40	0.05	0.13	35.81	44.5	<1	2.2	55.4	4.49
SG 312398	Soil	0.077	0.33	165.1	21	0.3	0.51	0.01	0.21	30.11	19.0	<1	1.9	40.2	3.67
SG 312399	Soil	0.023	0.59	138.2	27	0.3	0.46	0.02	0.20	17.13	30.8	<1	4.5	46.4	2.91
SG 312400	Soil	0.027	0.44	220.3	22	0.4	0.49	<0.01	0.31	29.00	19.3	<1	3.1	52.5	3.68
SG 312401	Soil	0.008	0.27	51.6	15	0.1	0.14	0.02	0.06	11.52	6.1	<1	0.7	8.9	1.26
SG 312402	Soil	0.046	0.50	182.9	22	0.2	0.53	0.03	0.19	25.46	19.3	<1	1.6	37.1	3.66
SG 312403	Soil	0.033	0.42	284.9	29	0.4	0.52	<0.01	0.55	25.83	22.7	<1	5.2	45.8	3.78
SG 312404	Soil	0.029	0.41	322.4	29	0.6	0.48	<0.01	0.40	23.29	22.4	<1	3.9	46.6	4.23
SG 312405	Soil	0.046	0.45	167.9	31	0.5	0.49	0.01	0.21	23.83	18.3	<1	4.0	48.7	3.83
SG 312406	Soil	0.022	0.50	183.1	23	0.5	0.63	<0.01	0.34	22.61	20.7	<1	6.4	57.9	4.68
SG 312407	Soil	0.043	0.83	86.0	31	0.4	0.35	0.05	0.16	41.27	22.5	<1	1.7	36.1	3.49
SG 312408	Soil	0.519	0.88	435.6	18	0.3	0.50	0.13	0.47	28.80	24.6	<1	1.1	39.0	4.40
SG 312409	Soil	0.058	2.35	100.6	20	0.4	0.31	0.07	0.05	35.42	25.2	30	1.8	32.4	5.08
SG 312410	Soil	0.019	2.76	39.0	18	0.4	0.30	0.10	0.04	52.26	31.7	38	1.6	45.3	5.91
SG 312411	Soil	0.034	2.02	81.5	28	0.5	0.34	0.08	0.05	39.42	21.3	30	2.5	42.3	4.95
SG 312412	Soil	0.067	1.55	36.2	33	0.5	0.30	0.11	0.05	40.53	22.4	<1	1.2	32.2	3.65
SG 312413	Soil	0.022	1.16	54.2	21	0.5	0.37	0.01	0.12	15.72	20.6	<1	1.6	39.5	3.81
SG 312414	Soil	0.013	0.34	28.3	29	0.1	0.35	0.02	0.09	26.08	13.9	<1	1.5	16.2	1.92
SG 312415	Soil	0.008	0.29	29.1	13	0.2	0.39	<0.01	0.05	18.46	22.0	<1	1.8	41.5	2.92
SG 312416	Soil	0.021	0.49	182.6	23	0.2	0.43	0.01	0.08	33.83	13.9	<1	2.1	35.1	3.96
SG 312417	Soil	0.006	1.68	24.1	27	0.5	0.46	0.19	0.10	40.88	26.5	<1	1.2	48.8	4.73
SG 312418	Soil	<0.005	1.61	42.9	17	0.4	0.83	0.15	0.08	77.58	36.1	<1	1.5	64.7	5.23
SG 312419	Soil	0.011	1.43	39.6	28	0.6	0.52	0.34	0.12	37.80	39.3	<1	1.5	52.9	5.00
SG 312420	Soil	<0.005	1.37	22.9	32	0.7	0.38	0.31	0.22	41.09	23.5	<1	0.9	55.6	4.06
SG 312421	Soil	<0.005	1.29	20.2	36	0.7	0.35	0.67	0.36	38.47	19.4	<1	0.8	50.8	3.69
SG 312422	Soil	<0.005	1.23	33.3	34	0.7	0.38	0.68	0.37	29.14	30.0	<1	0.7	71.5	3.74
SG 312423	Soil	0.012	1.04	53.3	35	0.3	0.41	0.02	0.05	43.93	15.8	<1	2.2	34.0	3.40
SG 312424	Soil	<0.005	2.40	18.9	19	0.2	0.46	0.02	0.07	35.79	24.7	29	1.5	31.8	4.84
SG 312425	Soil	<0.005	2.59	26.7	16	0.2	0.44	0.03	0.05	34.93	20.2	41	2.9	39.1	5.48
SG 312426	Soil	<0.005	2.41	20.1	22	0.2	0.37	0.02	0.05	18.08	18.7	27	2.6	38.4	4.75
SG 312427	Soil	<0.005	2.61	24.6	20	0.3	0.33	0.06	0.10	33.25	22.8	33	2.1	44.6	5.28
SG 312428	Soil	<0.005	2.50	16.1	24	0.3	0.35	0.02	0.05	16.93	35.2	37	2.9	30.2	5.09
SG 312429	Soil	<0.005	1.82	40.6	29	0.4	0.37	0.10	0.14	39.47	41.3	24	1.6	83.4	4.43
SG 312430	Soil	<0.005	2.57	26.9	22	0.4	0.45	0.02	0.06	22.52	21.2	30	3.5	65.7	5.31
SG 312431	Soil	<0.005	2.91	27.6	17	0.3	0.37	0.05	0.07	28.56	40.0	42	2.6	57.1	5.98
SG 312432	Soil	<0.005	1.92	16.7	18	0.2	0.29	0.02	0.05	13.88	18.0	21	1.4	24.9	4.10
SG 312433	Soil	<0.005	2.22	24.4	27	0.3	0.35	0.02	0.07	31.29	20.3	30	2.3	33.6	4.39
SG 312434	Soil	<0.005	1.76	70.3	53	0.7	0.67	0.10	0.14	25.58	30.7	<1	4.5	73.8	4.62

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SI 480501	Soil	0.007	0.38	136.4	17	0.2	0.23	0.01	0.28	19.06	19.1	<1	1.4	22.9	2.64
SI 480502	Soil	0.082	0.46	212.3	60	0.6	0.31	0.02	0.28	45.44	17.8	<1	2.0	33.3	3.42
SI 480503	Soil	0.063	0.38	298.4	20	0.3	0.36	<0.01	0.29	28.02	21.4	<1	1.7	33.5	3.21
SI 480504	Soil	0.132	0.38	817.6	39	0.3	0.39	0.01	0.48	25.57	19.4	<1	1.8	40.5	2.88
SI 480505	Soil	0.032	0.26	502.0	24	0.1	0.26	0.02	0.33	21.24	7.6	<1	1.1	23.9	2.05
SI 480506	Soil	0.042	0.37	313.3	23	0.1	0.18	0.01	0.14	27.41	13.6	<1	0.6	19.0	1.50
SI 480507	Soil	0.111	0.43	533.2	41	0.2	0.33	0.04	0.32	29.27	12.5	<1	1.2	26.2	2.79
SI 480508	Soil	0.007	0.87	175.6	22	0.2	0.41	0.01	0.07	41.07	17.9	<1	1.0	18.3	3.37
SI 480509	Soil	0.030	0.66	196.7	64	0.2	0.28	0.02	0.61	24.10	6.5	<1	2.3	19.9	1.91
SI 480510	Soil	0.053	0.77	420.0	30	0.3	0.36	0.02	0.44	30.63	15.9	<1	2.0	30.9	3.54
SI 480511	Soil	0.072	0.50	193.9	27	0.3	0.47	<0.01	0.16	26.32	21.1	<1	2.0	38.9	3.88
SI 480512	Soil	0.084	0.32	141.8	24	0.2	0.56	<0.01	0.16	25.60	14.6	<1	2.7	40.7	3.61
SI 480513	Soil	0.027	0.37	147.0	26	0.1	0.22	0.02	0.19	9.08	11.2	<1	1.8	13.5	1.47
SI 480514	Soil	0.021	0.39	100.0	15	0.3	0.60	<0.01	0.11	14.40	22.2	<1	4.0	59.8	4.33
SI 480515	Soil	0.039	0.86	257.9	26	0.4	0.56	0.01	0.42	24.46	19.1	<1	4.1	47.9	4.30
SI 480516	Soil	0.039	0.39	243.7	26	0.4	0.57	<0.01	0.41	24.52	27.3	<1	4.7	50.8	4.47
SI 480517	Soil	0.031	0.54	429.4	18	0.4	0.39	0.03	1.17	28.41	16.3	<1	3.2	44.3	4.43
SI 480518	Soil	0.008	0.25	55.3	21	0.1	0.21	0.02	0.12	17.14	10.4	<1	2.1	17.8	1.66
SI 480519	Soil	0.033	0.36	230.9	28	0.3	0.31	0.02	0.38	22.86	16.9	<1	1.7	35.6	3.71
SI 480520	Soil	0.127	0.91	145.4	37	0.5	0.38	0.10	0.12	40.66	21.8	<1	2.8	35.1	3.18
SI 480521	Soil	0.031	0.66	136.5	38	0.3	0.21	0.08	0.15	11.40	17.6	<1	1.7	16.3	1.75
SI 480522	Soil	0.086	1.86	156.5	24	0.5	0.35	0.14	0.10	23.62	25.8	<1	2.3	46.1	4.19
SI 480523	Soil	0.011	1.53	46.9	36	0.6	0.28	0.15	0.07	25.02	30.5	<1	1.2	54.7	3.68
SI 480524	Soil	0.038	1.65	108.1	25	0.5	0.38	0.10	0.10	40.72	30.7	24	1.6	62.3	5.43
SI 480525	Soil	0.051	0.50	193.2	20	0.4	0.30	0.10	0.22	39.58	18.4	<1	1.6	46.1	3.48
SI 480526	Soil	0.035	2.24	77.6	21	0.4	0.30	0.08	0.07	47.36	21.7	30	2.4	46.6	5.32
SI 480551	Soil	0.007	0.32	102.5	27	0.2	0.27	<0.01	0.29	24.85	16.3	<1	2.1	28.1	2.80
SI 480552	Soil	0.017	0.68	277.5	47	0.4	0.31	0.06	0.73	37.82	22.4	<1	2.4	30.8	3.13
SI 480553	Soil	0.017	0.52	250.9	23	0.3	0.23	0.09	0.70	32.31	26.2	<1	1.8	28.4	3.20
SI 480554	Soil	0.031	0.62	449.0	29	0.4	0.38	0.05	0.59	32.68	17.8	<1	2.7	38.3	4.08
SI 480555	Soil	0.013	0.47	68.3	20	0.1	0.12	0.03	0.09	14.54	14.2	<1	0.8	11.7	1.08
SI 480556	Soil	0.035	0.50	210.3	26	0.3	0.33	0.01	0.45	23.07	20.9	<1	1.7	42.5	3.15
SI 480557	Soil	0.013	0.43	304.0	24	0.3	0.26	0.02	0.94	23.92	24.0	<1	2.3	40.7	3.53
SI 480558	Soil	<0.005	0.40	20.7	17	0.1	0.07	0.08	0.10	7.46	29.3	<1	0.9	11.4	0.85
SI 480559	Soil	0.027	0.45	42.5	24	0.3	0.24	0.14	0.38	18.64	19.1	<1	1.1	23.8	2.97
SI 480560	Soil	0.009	0.64	29.7	46	0.3	0.20	0.10	0.06	12.39	8.0	<1	1.7	13.4	2.13
SI 480561	Soil	0.086	0.58	157.2	18	0.3	0.28	0.02	0.24	19.97	32.0	<1	1.0	38.4	3.67
SI 480562	Soil	0.013	2.43	42.6	22	0.5	0.38	0.10	0.05	40.69	22.3	34	2.7	57.8	5.12
SI 480563	Soil	0.012	1.88	55.5	48	0.7	0.27	0.13	0.11	42.81	27.8	28	1.2	61.9	4.78
SI 480564	Soil	0.152	0.57	226.4	51	0.5	0.49	0.02	0.08	37.72	31.5	<1	3.9	46.6	3.89

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SI 480565	Soil	0.006	1.71	25.1	68	0.5	0.21	0.06	0.23	30.64	22.0	22	0.8	36.0	3.83
SI 480566	Soil	0.025	1.54	59.4	31	0.4	0.28	0.10	0.07	34.52	33.9	<1	1.0	34.0	4.47
SI 480567	Soil	0.042	1.14	95.7	36	0.5	0.23	0.11	0.20	29.61	19.3	<1	0.6	39.7	3.60
SI 480568	Soil	0.014	1.44	61.4	42	0.5	0.29	0.08	0.14	36.34	19.8	25	1.4	29.2	3.64
SI 480569	Soil	<0.005	1.08	30.4	33	0.7	0.28	0.22	0.15	25.49	20.9	<1	0.7	44.2	2.82
SI 480570	Soil	0.006	1.08	27.4	34	0.7	0.31	0.25	0.19	28.78	16.3	<1	0.6	52.6	2.76
SI 480571	Soil	<0.005	1.17	27.0	30	0.7	0.32	0.70	0.31	22.16	20.3	<1	0.5	57.6	2.95
SI 480572	Soil	<0.005	0.95	20.6	24	0.2	0.35	0.02	0.23	34.56	9.4	<1	0.8	19.2	3.16
SI 480573	Soil	<0.005	1.14	19.2	28	0.5	0.36	0.18	0.08	22.52	16.0	<1	1.3	24.1	2.88
SI 480574	Soil	0.073	0.97	123.5	32	0.6	0.55	0.10	0.04	32.52	21.2	<1	1.3	45.4	3.58
SI 480575	Soil	0.006	0.92	21.0	20	0.5	0.39	0.25	0.09	18.58	16.5	<1	1.0	37.4	2.57
SI 480576	Soil	0.006	1.04	21.5	21	0.5	0.43	0.19	0.04	22.46	17.0	22	1.0	29.8	2.92
SI 480577	Soil	0.007	0.82	53.9	26	0.3	0.35	0.03	0.11	21.77	40.0	<1	1.2	30.6	3.74
SI 480578	Soil	<0.005	0.93	19.0	40	0.4	0.33	0.24	0.16	17.08	12.7	<1	1.5	21.6	2.18
SI 480579	Soil	0.059	0.99	49.7	16	0.2	0.32	0.01	0.11	25.09	21.8	<1	1.3	24.3	3.98
SI 480580	Soil	0.013	1.46	28.5	38	0.6	0.32	0.13	0.12	27.31	24.9	<1	1.0	39.6	3.39
SI 480581	Soil	0.013	0.58	55.1	23	0.2	0.19	0.02	0.07	17.91	11.2	<1	0.9	18.2	1.51
SI 480582	Soil	<0.005	0.54	24.6	20	0.1	0.14	0.08	0.04	14.77	7.6	<1	0.7	17.8	1.24
SI 480583	Soil	0.007	0.54	65.8	21	0.1	0.20	0.01	0.05	19.29	14.5	<1	0.8	13.8	1.33
SI 480584	Soil	0.050	0.91	120.5	26	0.2	0.26	0.04	0.16	21.05	15.9	<1	0.7	27.3	2.70
SI 480585	Soil	0.034	0.45	214.9	29	0.4	0.34	0.01	0.29	32.51	18.4	<1	1.5	35.5	3.32
SI 480586	Soil	0.120	0.46	333.8	35	0.4	0.31	<0.01	0.45	33.19	24.0	<1	1.4	37.7	3.12
SI 480587	Soil	0.035	0.51	267.0	31	0.2	0.35	0.01	0.21	32.42	13.1	<1	1.1	21.4	2.55
SI 480588	Soil	<0.005	0.48	51.2	29	0.1	0.12	0.06	0.09	8.04	15.2	<1	1.0	10.5	0.98
SI 480589	Soil	<0.005	1.46	40.3	29	0.2	0.35	0.01	0.10	30.87	13.2	<1	2.0	25.2	4.04
SI 480590	Soil	<0.005	0.50	84.6	34	0.2	0.23	0.09	0.13	11.25	14.0	<1	1.0	17.7	1.70
SI 484680	Soil	0.129	0.38	179.1	18	0.1	0.19	0.10	0.33	15.03	21.4	<1	2.2	24.7	1.63
SI 484681	Soil	0.523	0.38	641.5	30	0.2	0.30	0.03	1.02	29.77	12.1	<1	2.6	35.6	2.38
SI 484682	Soil	0.238	0.53	617.5	32	0.3	0.29	0.03	0.72	18.01	18.8	<1	2.7	35.4	3.16
SI 484683	Soil	0.404	0.38	912.9	26	0.2	0.39	0.05	0.59	18.84	20.0	<1	2.1	29.2	3.31
SI 484684	Soil	0.211	0.52	966.9	29	0.3	0.33	0.04	1.18	24.19	22.0	<1	2.1	36.7	3.16
SI 484685	Soil	0.112	0.48	1248.3	29	0.3	0.36	0.03	0.68	24.80	17.3	<1	2.8	33.6	3.03
SI 484686	Soil	0.033	0.48	314.9	30	0.3	0.48	0.04	0.34	19.53	20.4	<1	3.2	46.1	3.91
SI 484687	Soil	0.041	0.78	235.7	36	0.9	0.18	0.02	0.43	31.53	28.7	<1	0.4	44.7	4.02
SI 484688	Soil	0.143	0.52	463.1	22	0.3	0.27	0.03	0.47	24.57	14.0	<1	1.4	31.4	3.06
SI 484689	Soil	0.167	0.45	715.7	30	0.3	0.38	<0.01	0.53	23.86	14.6	<1	2.5	32.1	3.39
SI 484690	Soil	0.259	0.59	674.0	27	0.3	0.32	0.05	0.50	22.61	20.2	<1	2.1	34.9	3.42
SI 484691	Soil	0.060	0.41	205.9	28	0.2	0.25	0.03	0.15	14.84	10.9	<1	0.9	18.5	2.28
SI 484692	Soil	0.331	0.64	738.5	30	0.3	0.35	0.03	0.41	25.13	19.8	<1	2.4	30.6	3.61
SI 484693	Soil	0.176	0.36	366.5	22	0.3	0.34	0.02	0.38	19.72	22.0	<1	2.1	36.9	3.02

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SI 484694	Soil	0.011	0.46	65.7	19	0.4	0.28	0.05	0.37	15.15	23.3	<1	1.1	29.9	3.49
SI 484695	Soil	0.101	0.70	316.3	30	0.4	0.35	0.03	0.31	28.18	17.7	<1	2.4	33.9	3.29
SI 484696	Soil	0.046	0.65	226.9	21	0.3	0.27	0.05	0.22	28.44	18.4	<1	1.5	25.5	3.18
SI 484697	Soil	0.031	0.69	163.5	22	0.4	0.37	0.03	0.23	24.64	23.5	<1	1.6	31.7	3.62
SI 484698	Soil	0.024	0.46	303.0	17	0.4	0.28	0.04	0.23	29.79	20.7	<1	2.2	31.5	3.42
SI 484699	Soil	0.017	0.35	119.7	39	0.5	0.27	0.04	0.32	35.10	27.9	<1	1.2	32.1	3.62
SI 484700	Soil	0.101	0.38	361.8	23	0.4	0.28	0.04	0.50	22.44	18.1	<1	1.5	30.0	3.23
SI 484701	Soil	0.104	0.40	442.6	29	0.3	0.34	0.02	0.64	30.16	15.5	<1	2.6	35.3	3.19
SI 484702	Soil	0.087	0.96	178.0	23	0.3	0.37	0.01	0.24	20.02	13.3	<1	1.7	31.6	3.73
SI 484703	Soil	0.020	0.58	131.5	19	0.2	0.26	0.01	0.11	23.90	13.7	<1	1.2	21.7	2.37
SI 484704	Soil	0.216	1.61	174.5	28	0.4	0.35	0.07	0.26	33.89	22.5	<1	2.0	32.8	4.05
SI 484705	Soil	0.101	1.54	193.9	24	0.4	0.35	0.10	0.23	37.91	23.1	<1	1.7	36.7	4.20
SI 484706	Soil	0.050	1.73	188.8	21	0.4	0.34	0.03	0.16	32.77	17.6	<1	2.2	36.6	4.25
SI 484707	Soil	0.078	1.71	237.1	26	0.4	0.37	0.05	0.17	29.04	20.2	<1	2.3	38.6	4.32
SI 484708	Soil	0.037	1.66	390.3	41	0.6	0.44	0.04	0.31	41.97	25.0	21	5.0	55.2	4.91
SI 484709	Soil	0.020	1.07	265.0	45	0.4	0.59	0.02	0.23	24.45	15.1	<1	6.2	40.6	3.43
SI 484710	Soil	0.006	0.55	148.0	17	0.2	0.36	<0.01	0.12	26.73	11.4	<1	0.7	29.2	2.88
SI 484711	Soil	0.020	0.67	99.3	25	0.2	0.42	0.02	0.13	30.87	12.2	<1	1.6	27.6	2.98
SI 484712	Soil	0.024	0.59	139.5	27	0.3	0.33	0.04	0.16	30.99	17.1	<1	1.6	30.8	3.42
SI 484713	Soil	0.011	0.60	53.2	21	0.2	0.21	0.03	0.08	20.96	22.1	<1	1.2	21.4	2.20
SI 484714	Soil	0.016	0.77	54.3	26	0.2	0.25	0.05	0.09	25.17	28.7	<1	1.6	35.5	2.63
SI 484715	Soil	0.039	0.92	156.8	24	0.3	0.34	0.02	0.19	43.37	34.6	<1	1.6	43.8	4.06
SI 484716	Soil	0.074	1.29	486.5	41	0.4	0.38	0.05	0.42	29.58	21.6	<1	4.1	39.0	3.81
SI 484717	Soil	0.068	0.88	328.0	32	0.3	0.28	0.03	0.39	14.65	6.9	<1	1.9	24.9	2.11
SI 484718	Soil	0.095	1.18	273.9	28	0.4	0.45	0.05	0.30	29.43	19.8	<1	1.7	42.1	3.71
SI 484719	Soil	0.047	0.85	341.8	43	0.3	0.49	0.02	0.67	29.55	14.0	<1	3.9	39.7	3.25
SI 484720	Soil	0.239	0.59	511.2	33	0.3	0.37	0.03	1.05	29.54	18.1	<1	2.6	37.8	3.22
SI 484721	Soil	0.061	0.32	305.5	34	0.4	0.42	0.01	0.53	38.61	19.3	<1	1.7	46.5	3.30
SI 484722	Soil	0.106	0.56	587.0	62	0.7	0.33	0.02	0.67	50.54	22.8	<1	2.3	48.2	4.12
SI 484723	Soil	<0.005	0.25	10.5	16	<0.05	0.04	0.03	0.07	2.44	3.5	<1	0.2	9.7	0.66
SI 484724	Soil	0.054	0.44	283.7	58	0.2	0.25	0.04	0.86	15.71	8.2	<1	0.8	21.0	2.02
SI 484725	Soil	0.079	0.36	320.1	25	0.4	0.44	0.02	0.52	36.63	14.8	<1	2.8	38.2	3.49
SI 484726	Soil	0.025	0.27	202.7	35	0.2	0.34	0.01	0.34	26.35	10.3	<1	1.7	32.4	2.18
SI 484727	Soil	0.261	0.23	1148.1	30	0.2	0.32	0.01	0.29	23.90	8.8	<1	1.3	22.1	2.80
SI 484728	Soil	0.122	0.31	954.8	23	0.2	0.33	0.01	0.32	25.62	9.9	<1	1.0	26.9	2.74
SI 484729	Soil	0.061	0.41	443.3	27	0.2	0.27	0.03	0.73	24.13	13.9	<1	1.3	30.8	2.66
SI 484730	Soil	0.068	0.48	396.9	53	0.3	0.31	0.01	0.44	25.21	8.3	<1	3.1	25.7	2.00
SI 484731	Soil	0.050	0.55	325.3	30	0.3	0.36	0.04	0.86	41.12	20.1	<1	1.6	44.2	3.66
SI 484732	Soil	0.085	0.66	524.5	31	0.3	0.38	0.02	1.46	30.63	17.3	<1	1.9	46.0	3.71
SI 484733	Soil	0.100	1.44	247.0	28	0.4	0.40	0.06	0.34	39.04	21.4	<1	1.6	43.1	4.16

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SI 484734	Soil	0.039	1.20	288.2	37	0.3	0.34	0.06	0.80	22.82	13.1	<1	2.3	27.4	3.19
SI 484735	Soil	0.012	1.12	35.0	42	0.2	0.46	0.01	0.13	21.12	11.1	<1	2.6	26.0	3.49
SI 484736	Soil	0.014	0.78	19.9	27	0.2	0.26	0.02	0.07	14.39	3.0	<1	1.7	16.8	1.93
SI 484737	Soil	0.007	1.12	12.4	41	0.3	0.27	0.03	0.14	16.39	9.7	<1	2.4	33.1	3.41
SI 484738	Soil	<0.005	0.99	13.9	29	0.2	0.22	0.02	0.09	17.66	10.4	<1	1.3	19.8	2.01
SI 484739	Soil	<0.005	1.57	8.9	41	0.3	0.24	0.01	0.09	28.86	16.9	<1	1.7	31.1	4.25
SI 484740	Soil	0.007	1.22	21.0	14	0.3	0.37	0.24	0.03	33.83	15.0	<1	1.2	24.7	3.26
SI 484741	Soil	0.026	1.51	77.1	35	0.5	0.51	0.16	0.11	48.84	28.7	25	1.7	56.4	5.19
SI 484742	Soil	0.008	1.34	67.6	66	0.5	0.40	0.06	0.17	25.00	19.2	<1	6.7	31.7	3.29
SI 484743	Soil	0.025	2.23	56.8	23	0.5	0.57	0.02	0.18	38.71	21.4	33	4.7	43.6	5.82
SI 484744	Soil	0.008	1.17	44.4	28	0.3	0.36	0.02	0.11	22.62	17.7	<1	3.5	40.9	3.76
SI 484745	Soil	<0.005	1.96	49.7	36	0.5	0.79	0.02	0.10	24.16	16.0	21	6.5	70.3	5.03
SI 484746	Soil	<0.005	1.31	20.2	33	0.3	0.39	0.01	0.08	21.36	7.2	<1	3.3	34.7	3.29
SI 484747	Soil	0.015	1.30	25.1	44	0.8	0.43	0.08	0.16	16.55	17.6	<1	4.7	39.5	2.69
SI 484748	Soil	0.006	0.40	3.2	11	0.2	0.11	0.04	0.03	5.71	3.0	<1	0.5	7.7	0.58
SI 484749	Soil	0.007	1.52	22.0	18	0.5	0.56	0.16	0.11	28.34	20.7	<1	2.1	59.1	4.16
SI 484750	Soil	0.012	1.72	36.2	21	0.5	0.89	0.23	0.15	25.36	35.8	<1	3.1	70.7	5.39
SI 484751	Soil	0.033	1.36	75.1	23	0.8	0.86	0.19	0.18	29.67	44.0	<1	3.2	74.7	4.75
SI 484752	Soil	0.132	1.27	296.7	31	0.7	0.60	0.17	0.10	21.92	21.2	<1	3.1	48.3	4.21
SI 484753	Soil	0.037	0.55	103.1	38	0.3	0.22	0.28	0.19	9.02	12.0	<1	2.3	20.6	1.45
SI 484754	Soil	0.013	0.84	65.3	47	0.8	0.32	0.20	0.35	13.43	14.6	<1	5.4	42.9	1.97
SI 484755	Soil	0.013	1.93	97.5	32	0.5	0.39	0.01	0.16	29.97	17.2	24	4.5	37.8	4.50
SI 484756	Soil	0.016	1.24	54.0	78	0.6	0.32	0.45	0.15	11.60	7.2	<1	3.4	45.1	1.91
SI 484757	Soil	0.007	0.24	9.7	112	0.1	0.12	1.04	2.32	3.14	12.3	<1	1.3	19.4	0.53
SI 484758	Soil	0.011	1.18	8.2	97	0.5	0.21	1.01	0.13	9.42	6.3	<1	2.9	49.2	1.34
SI 484759	Soil	0.172	0.86	612.4	24	0.6	0.43	0.04	0.10	68.88	20.1	<1	2.2	51.3	3.98
SI 484760	Soil	0.047	1.41	232.5	29	0.7	0.49	0.07	0.11	50.26	21.5	<1	2.7	57.2	4.29
SI 484761	Soil	0.170	0.62	1159.4	69	0.4	0.34	0.49	0.21	13.67	22.8	<1	0.8	44.7	2.51
SI 484762	Soil	0.031	1.57	283.5	17	0.5	0.41	0.10	0.06	18.91	21.2	<1	1.3	53.2	4.42
SI 484763	Soil	0.052	0.74	155.4	46	0.4	0.36	0.11	0.20	17.93	17.8	<1	2.2	37.0	3.28
SI 484764	Soil	0.042	0.50	188.9	33	0.3	0.42	0.02	0.30	18.87	9.9	<1	2.7	32.1	2.73
SI 484765	Soil	0.022	0.48	252.4	36	0.3	0.51	<0.01	0.35	13.04	11.8	<1	3.8	45.5	2.94
SI 484766	Soil	<0.005	0.05	0.8	7	<0.05	<0.01	0.01	0.01	0.99	0.7	<1	0.1	1.7	0.17
SI 484767	Soil	0.008	0.46	71.0	41	0.2	0.53	<0.01	0.12	23.30	8.8	<1	1.3	25.4	3.23
SI 484768	Soil	0.019	0.51	163.0	25	0.3	0.39	0.02	0.23	15.76	13.8	<1	3.7	37.4	2.78
SI 484769	Soil	0.049	0.45	175.3	32	0.4	0.55	<0.01	0.31	20.44	14.4	<1	5.5	46.7	3.66
SI 484770	Soil	0.014	0.49	97.8	27	0.3	0.40	0.01	0.13	13.00	10.9	<1	2.2	35.1	2.68
SI 484771	Soil	0.010	0.57	76.7	23	0.2	0.26	0.02	0.12	11.30	9.1	<1	1.3	24.1	2.56
SI 484772	Soil	0.027	0.43	298.6	26	0.5	0.65	<0.01	0.50	20.52	17.7	<1	6.1	63.5	5.09
SI 484773	Soil	0.055	0.30	271.4	30	0.2	0.37	0.08	1.17	13.88	13.4	<1	1.5	35.0	2.66

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SI 484774	Soil	0.066	1.89	175.2	26	0.4	0.35	0.08	0.17	21.07	17.8	24	2.3	36.5	4.60
SI 484775	Soil	0.075	1.84	203.0	32	0.4	0.43	0.11	0.05	24.41	18.3	<1	3.7	43.8	4.09
SI 484776	Soil	0.007	2.79	27.7	18	0.4	0.35	0.07	0.03	37.71	22.4	44	1.7	49.7	5.62
SI 484777	Soil	0.011	2.28	64.7	32	0.6	0.34	0.11	0.06	28.09	24.4	30	1.5	57.5	4.88
SI 484778	Soil	0.006	0.94	12.6	27	0.2	0.24	0.06	0.10	9.57	9.1	<1	0.8	15.5	2.20
SI 484779	Soil	0.009	1.35	31.1	20	0.4	0.50	0.32	0.09	14.39	16.6	<1	0.8	44.6	3.75
SI 484780	Soil	0.040	1.13	127.1	25	0.3	0.46	0.04	0.19	22.70	21.3	<1	1.4	39.1	3.99
SI 484781	Soil	0.058	0.28	257.8	25	0.2	0.29	0.03	0.10	36.44	10.7	<1	1.0	26.6	2.19
SI 484782	Soil	0.034	0.44	325.5	25	0.2	0.33	0.03	0.11	31.32	10.1	<1	1.7	30.1	2.87
SI 484783	Soil	0.150	0.45	397.3	17	0.2	0.31	0.01	0.12	30.04	13.5	<1	2.6	29.9	3.28
SI 484784	Soil	0.011	1.03	32.5	30	0.7	0.41	1.02	0.17	24.92	16.1	<1	1.2	44.8	4.40
SI 484785	Soil	<0.005	2.09	25.2	50	0.7	0.48	0.10	0.08	33.47	19.7	25	2.1	54.2	4.64
SI 484786	Soil	0.009	1.32	43.4	39	0.4	0.39	0.08	0.31	24.32	15.9	<1	2.3	35.2	3.47
SI 484787	Soil	0.007	1.86	22.0	30	0.5	0.42	0.05	0.22	26.29	16.9	22	2.0	41.0	4.40
SI 484788	Soil	<0.005	1.69	15.2	34	0.5	0.45	0.09	0.09	18.64	19.9	<1	0.9	57.2	3.90
SI 484789	Soil	<0.005	2.57	24.7	30	0.5	0.39	0.08	0.07	26.97	27.8	35	4.7	84.6	5.22
SI 484790	Soil	<0.005	1.35	13.3	24	0.2	0.29	0.03	0.07	15.97	10.0	<1	2.0	25.9	3.13
SI 484791	Soil	<0.005	0.91	6.5	28	0.2	0.23	0.04	0.05	12.79	6.0	<1	1.0	16.5	1.89
SI 484792	Soil	<0.005	2.28	39.8	25	0.5	0.65	0.02	0.06	30.52	26.2	34	3.6	46.9	4.50
SI 484793	Soil	0.021	2.12	110.1	32	0.5	0.46	0.11	0.14	33.53	21.2	27	3.7	53.0	4.34
SI 484794	Soil	0.026	1.95	108.2	28	0.4	0.60	0.03	0.16	43.92	30.6	<1	2.3	100.8	4.76
SI 484795	Soil	0.021	2.40	46.7	23	0.6	0.51	0.04	0.14	27.82	28.7	26	3.5	74.6	4.94
SI 484796	Soil	<0.005	1.22	42.5	65	0.4	0.34	0.31	0.20	11.64	29.6	<1	1.8	48.6	3.38
SI 484797	Soil	0.012	2.78	62.6	18	0.6	0.43	0.10	0.08	30.78	30.3	31	1.2	120.5	5.82
SI 484798	Soil	0.007	2.02	43.7	22	0.4	0.40	0.02	0.07	24.28	17.2	27	2.0	47.8	4.32
SI 484799	Soil	<0.005	1.37	13.1	14	0.2	0.27	0.03	0.06	18.47	11.3	<1	1.3	33.8	2.52
SI 484800	Soil	0.006	2.59	20.5	30	0.3	0.45	0.03	0.07	21.73	22.5	34	4.5	42.6	5.22

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5
SG 312315	Soil	2.7	<0.05	<0.02	0.03	0.02	18.5	16.8	0.21	1285	0.82	<0.01	0.2	46.2	708
SG 312316	Soil	3.3	<0.05	<0.02	0.02	0.02	16.0	16.4	0.20	472	0.69	0.01	0.2	22.9	436
SG 312317	Soil	2.5	<0.05	<0.02	0.01	0.03	6.7	1.8	0.04	74	0.46	0.02	0.2	5.9	474
SG 312318	Soil	1.9	<0.05	<0.02	0.03	0.03	18.6	8.2	0.11	382	0.82	<0.01	<0.05	31.5	477
SG 312319	Soil	1.9	<0.05	<0.02	0.04	0.03	26.2	12.2	0.16	429	0.57	<0.01	0.1	41.1	402
SG 312320	Soil	4.8	<0.05	<0.02	0.03	0.03	19.0	26.3	0.34	305	0.59	0.01	0.3	23.5	368
SG 312321	Soil	3.5	<0.05	<0.02	0.03	0.03	14.3	8.3	0.13	193	0.77	0.01	0.2	16.6	633
SG 312322	Soil	2.1	<0.05	<0.02	0.02	0.03	13.1	1.8	0.02	410	0.36	0.01	0.1	25.6	496
SG 312323	Soil	2.5	<0.05	<0.02	0.03	0.02	29.1	15.7	0.18	674	0.57	<0.01	<0.05	47.1	345
SG 312324	Soil	3.1	<0.05	<0.02	0.03	0.03	15.7	11.1	0.11	390	0.67	0.01	0.1	24.8	451
SG 312325	Soil	3.0	<0.05	<0.02	0.03	0.03	20.5	15.1	0.18	865	0.62	<0.01	0.2	31.9	436
SG 312326	Soil	0.8	<0.05	<0.02	<0.01	0.02	15.3	0.8	<0.01	118	0.24	<0.01	<0.05	7.0	189
SG 312327	Soil	4.8	<0.05	<0.02	0.03	0.04	17.1	27.7	0.37	295	0.55	<0.01	0.3	26.0	540
SG 312328	Soil	5.4	<0.05	<0.02	0.03	0.03	19.0	47.8	0.54	442	0.60	<0.01	0.5	32.2	462
SG 312329	Soil	3.0	<0.05	<0.02	0.01	0.02	8.5	5.9	0.08	112	0.46	0.02	0.2	7.3	322
SG 312330	Soil	2.8	<0.05	<0.02	0.05	0.02	12.5	7.7	0.10	175	0.63	0.01	0.2	16.3	445
SG 312331	Soil	1.1	<0.05	<0.02	0.05	0.02	11.0	3.8	0.05	204	0.35	<0.01	0.1	14.7	395
SG 312332	Soil	2.3	<0.05	<0.02	0.04	0.02	22.3	6.0	0.09	433	0.78	<0.01	0.1	67.6	988
SG 312333	Soil	1.9	<0.05	<0.02	0.04	0.02	14.5	11.4	0.14	446	0.82	<0.01	0.1	34.9	306
SG 312334	Soil	1.6	<0.05	<0.02	0.04	0.03	20.8	4.0	0.06	130	1.10	<0.01	0.2	12.1	279
SG 312335	Soil	2.1	<0.05	<0.02	0.04	0.03	16.4	5.4	0.09	311	0.58	<0.01	0.1	16.6	610
SG 312336	Soil	2.2	<0.05	<0.02	0.04	0.04	12.3	5.0	0.11	654	0.69	0.02	0.2	15.5	650
SG 312337	Soil	1.6	<0.05	<0.02	0.02	0.02	17.5	5.5	0.09	228	0.84	<0.01	0.1	20.0	436
SG 312338	Soil	2.6	<0.05	<0.02	0.03	0.04	13.1	9.8	0.17	197	1.01	<0.01	0.3	20.5	542
SG 312339	Soil	1.9	<0.05	<0.02	0.02	0.02	6.0	5.0	0.07	633	0.51	0.01	0.1	26.7	1069
SG 312340	Soil	1.8	<0.05	<0.02	0.16	0.02	10.3	7.4	0.12	373	0.59	<0.01	0.1	36.1	512
SG 312341	Soil	1.3	<0.05	<0.02	0.09	0.02	9.2	2.0	0.04	370	0.69	<0.01	<0.05	17.0	829
SG 312342	Soil	0.9	<0.05	<0.02	0.15	0.03	12.2	1.2	0.02	550	0.39	<0.01	<0.05	19.8	461
SG 312343	Soil	1.0	<0.05	<0.02	0.08	0.03	7.6	2.7	0.05	951	0.39	<0.01	0.1	30.2	510
SG 312344	Soil	7.3	0.1	<0.02	0.02	0.02	18.4	97.6	1.21	870	0.46	<0.01	<0.05	60.8	431
SG 312345	Soil	7.7	0.1	<0.02	0.02	0.02	19.9	96.3	1.23	826	0.51	<0.01	<0.05	62.8	430
SG 312346	Soil	2.7	<0.05	<0.02	0.02	0.02	20.1	22.4	0.30	474	0.45	<0.01	<0.05	42.2	319
SG 312347	Soil	4.2	<0.05	<0.02	0.02	0.02	23.2	40.1	0.50	697	0.50	<0.01	0.1	52.1	282
SG 312348	Soil	2.8	<0.05	<0.02	0.03	0.02	14.1	16.0	0.16	711	1.34	<0.01	0.2	40.0	600
SG 312349	Soil	1.1	<0.05	0.06	0.04	0.02	12.5	1.5	<0.01	188	1.61	<0.01	<0.05	27.2	263
SG 312350	Soil	1.5	<0.05	<0.02	0.03	0.02	11.0	6.1	0.08	210	0.84	<0.01	0.1	20.9	426
SG 312351	Soil	1.2	<0.05	<0.02	0.05	0.02	12.6	5.7	0.07	240	0.53	<0.01	0.1	13.8	397
SG 312352	Soil	1.5	<0.05	<0.02	0.07	0.02	13.8	5.3	0.07	185	0.54	<0.01	0.2	19.0	360
SG 312353	Soil	1.4	<0.05	<0.02	0.07	0.02	13.8	6.3	0.08	580	0.77	<0.01	0.1	31.7	413
SG 312354	Soil	1.9	<0.05	<0.02	0.03	0.02	6.4	6.7	0.11	195	0.33	0.02	0.2	14.9	438

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5
SG 312355	Soil	1.3	<0.05	<0.02	0.10	0.03	7.9	2.6	0.06	97	0.46	0.01	0.1	6.9	426
SG 312356	Soil	1.4	<0.05	<0.02	0.05	0.03	9.4	3.2	0.08	105	0.56	0.01	0.2	14.0	435
SG 312357	Soil	1.1	<0.05	<0.02	0.11	0.03	12.4	3.6	0.06	462	0.37	0.01	0.1	22.8	485
SG 312358	Soil	1.2	<0.05	<0.02	0.10	0.03	21.1	8.1	0.12	661	0.53	<0.01	<0.05	39.7	484
SG 312359	Soil	7.1	<0.05	<0.02	0.02	0.02	12.0	85.7	1.11	798	0.40	<0.01	<0.05	54.5	360
SG 312360	Soil	5.3	<0.05	<0.02	0.02	0.02	15.2	72.1	0.96	713	0.38	<0.01	0.1	57.5	518
SG 312361	Soil	7.2	<0.05	<0.02	0.02	0.02	15.7	65.1	0.82	911	0.42	<0.01	<0.05	55.1	508
SG 312362	Soil	5.2	<0.05	<0.02	0.02	0.02	18.7	53.3	0.69	840	0.41	<0.01	<0.05	56.4	478
SG 312363	Soil	4.5	<0.05	<0.02	0.02	0.03	12.1	50.2	0.69	408	0.55	<0.01	0.2	40.0	329
SG 312364	Soil	4.0	<0.05	<0.02	0.02	0.03	12.8	42.8	0.60	437	0.57	0.01	0.2	40.4	354
SG 312365	Soil	4.3	<0.05	0.04	0.02	0.03	14.6	57.4	0.81	457	0.96	<0.01	0.1	47.6	374
SG 312366	Soil	3.7	<0.05	0.05	0.02	0.03	12.7	48.4	0.66	506	1.08	<0.01	0.1	41.4	518
SG 312367	Soil	4.3	<0.05	0.06	0.02	0.04	11.0	50.5	0.75	312	0.54	<0.01	0.1	39.6	643
SG 312368	Soil	3.7	<0.05	0.03	0.02	0.03	7.8	42.8	0.60	337	0.47	0.01	0.1	34.2	355
SG 312369	Soil	4.1	<0.05	<0.02	0.02	0.02	10.8	47.8	0.70	646	0.47	<0.01	<0.05	43.0	440
SG 312370	Soil	3.9	<0.05	<0.02	0.02	0.03	10.4	44.9	0.67	350	0.47	<0.01	<0.05	40.6	352
SG 312371	Soil	3.7	<0.05	<0.02	<0.01	0.03	11.1	32.3	0.48	416	0.40	0.01	0.1	29.6	634
SG 312372	Soil	4.3	<0.05	0.08	0.02	0.03	11.2	50.0	0.75	391	0.64	<0.01	0.1	39.0	527
SG 312373	Soil	5.0	<0.05	0.04	0.02	0.03	17.4	68.2	0.87	837	0.87	<0.01	<0.05	49.9	373
SG 312374	Soil	4.1	<0.05	0.05	0.02	0.03	16.3	50.2	0.69	563	1.23	<0.01	<0.05	48.0	328
SG 312375	Soil	4.7	<0.05	0.06	0.02	0.03	11.6	56.7	0.75	551	0.95	<0.01	0.1	44.3	503
SG 312376	Soil	3.8	<0.05	<0.02	0.02	0.03	14.4	48.1	0.64	553	0.78	<0.01	0.1	45.6	385
SG 312377	Soil	3.8	<0.05	<0.02	0.02	0.02	7.1	29.5	0.44	1451	0.45	<0.01	0.2	37.7	708
SG 312378	Soil	1.3	<0.05	<0.02	0.04	0.03	6.9	2.1	0.03	138	0.45	0.01	0.2	20.4	352
SG 312379	Soil	1.5	<0.05	<0.02	0.02	0.03	26.6	6.7	0.14	753	0.39	0.01	<0.05	37.3	444
SG 312380	Soil	4.9	<0.05	0.04	0.02	0.03	9.3	21.1	0.32	1297	0.59	0.01	0.3	17.2	1508
SG 312381	Soil	3.2	<0.05	<0.02	0.02	0.02	29.6	23.6	0.35	1343	0.29	<0.01	<0.05	38.9	177
SG 312382	Soil	6.0	<0.05	<0.02	0.02	0.04	11.4	27.7	0.40	1860	0.68	0.01	0.3	21.0	1496
SG 312383	Soil	7.7	<0.05	<0.02	0.03	0.02	18.7	62.8	0.82	836	0.66	<0.01	0.4	44.7	644
SG 312384	Soil	6.5	<0.05	<0.02	0.03	0.03	14.7	52.0	0.67	492	0.66	0.01	0.5	36.6	624
SG 312385	Soil	4.1	<0.05	<0.02	0.01	0.02	8.7	25.2	0.38	282	0.37	0.02	0.2	19.4	532
SG 312386	Soil	6.8	<0.05	0.02	0.03	0.02	13.5	63.1	0.77	583	0.50	<0.01	0.2	43.0	363
SG 312387	Soil	5.0	<0.05	<0.02	0.02	0.02	12.2	45.1	0.57	345	0.39	0.01	0.2	30.9	294
SG 312388	Soil	4.1	<0.05	<0.02	0.03	0.02	13.7	28.9	0.48	583	0.47	<0.01	0.1	38.5	557
SG 312389	Soil	3.2	<0.05	<0.02	0.02	0.02	13.4	24.2	0.29	378	0.34	0.02	0.1	32.0	380
SG 312390	Soil	5.0	<0.05	0.05	0.02	0.03	10.9	36.0	0.55	350	0.43	0.02	0.3	26.9	613
SG 312391	Soil	6.3	<0.05	<0.02	0.03	0.03	19.5	70.1	0.86	747	0.51	0.01	0.2	51.2	384
SG 312392	Soil	6.4	<0.05	<0.02	0.03	0.02	23.3	62.8	0.88	526	0.56	<0.01	0.2	48.6	541
SG 312393	Soil	6.4	<0.05	<0.02	0.03	0.03	20.2	56.6	0.87	579	0.65	<0.01	0.3	45.0	466
SG 312394	Soil	6.2	<0.05	<0.02	0.03	0.03	23.7	53.7	0.76	1309	0.97	<0.01	0.1	55.6	674

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5
SG 312395	Soil	3.4	<0.05	<0.02	0.01	0.02	3.6	13.6	0.22	229	0.40	0.01	0.2	11.4	593
SG 312396	Soil	3.7	<0.05	<0.02	0.01	0.02	7.2	15.5	0.23	175	0.43	0.01	0.1	12.2	863
SG 312397	Soil	5.1	<0.05	<0.02	0.02	0.02	17.0	62.8	0.78	695	0.53	<0.01	0.2	50.2	495
SG 312398	Soil	1.5	<0.05	<0.02	0.02	0.02	18.0	4.6	0.06	270	1.21	<0.01	0.1	22.1	352
SG 312399	Soil	2.1	<0.05	<0.02	0.03	0.03	9.2	7.8	0.10	175	1.29	0.01	0.2	18.4	429
SG 312400	Soil	1.5	<0.05	<0.02	0.03	0.02	16.5	7.4	0.10	230	1.07	<0.01	0.1	25.8	224
SG 312401	Soil	2.0	<0.05	<0.02	<0.01	0.03	6.1	1.4	0.04	154	0.34	0.02	0.1	6.2	307
SG 312402	Soil	2.2	<0.05	<0.02	0.06	0.02	13.7	7.3	0.11	263	0.94	<0.01	0.1	22.0	586
SG 312403	Soil	1.3	<0.05	<0.02	0.03	0.03	14.5	5.3	0.07	319	1.13	<0.01	<0.05	24.2	306
SG 312404	Soil	1.2	<0.05	<0.02	0.03	0.02	12.6	6.3	0.08	336	1.07	<0.01	0.1	30.9	316
SG 312405	Soil	1.3	<0.05	<0.02	0.03	0.03	12.6	4.6	0.06	383	1.15	<0.01	0.1	28.5	346
SG 312406	Soil	1.6	<0.05	0.02	0.03	0.02	12.8	7.6	0.10	300	1.46	<0.01	<0.05	31.2	306
SG 312407	Soil	2.2	<0.05	<0.02	0.02	0.03	22.8	20.8	0.34	623	0.43	0.01	0.1	35.2	349
SG 312408	Soil	2.3	<0.05	<0.02	0.03	0.03	15.4	23.3	0.39	993	0.43	<0.01	<0.05	40.2	847
SG 312409	Soil	5.7	<0.05	<0.02	0.02	0.04	17.9	74.9	1.08	802	0.38	0.01	0.1	45.2	468
SG 312410	Soil	7.1	<0.05	<0.02	0.02	0.02	27.8	99.5	1.30	763	0.38	<0.01	<0.05	54.4	442
SG 312411	Soil	5.8	<0.05	<0.02	0.02	0.03	19.9	67.4	0.91	739	0.36	<0.01	<0.05	46.5	418
SG 312412	Soil	4.3	<0.05	<0.02	0.02	0.02	20.4	56.8	0.76	461	0.54	<0.01	0.1	41.8	349
SG 312413	Soil	3.5	<0.05	<0.02	0.02	0.02	8.2	31.5	0.37	514	0.55	<0.01	0.2	33.3	432
SG 312414	Soil	3.6	<0.05	<0.02	0.01	0.03	13.8	3.5	0.06	204	0.73	<0.01	0.1	12.5	520
SG 312415	Soil	1.0	<0.05	<0.02	0.02	0.02	9.8	0.9	0.02	286	0.46	<0.01	<0.05	31.2	528
SG 312416	Soil	3.1	<0.05	<0.02	0.02	0.04	18.0	3.6	0.06	563	0.91	<0.01	0.2	24.5	1144
SG 312417	Soil	4.1	<0.05	<0.02	0.03	0.03	24.0	58.7	0.75	798	0.37	<0.01	<0.05	44.7	479
SG 312418	Soil	4.2	<0.05	<0.02	0.02	0.02	45.5	61.7	0.74	1722	0.49	<0.01	<0.05	54.2	459
SG 312419	Soil	3.5	<0.05	<0.02	0.02	0.03	20.6	43.6	0.67	1112	0.61	<0.01	<0.05	49.4	468
SG 312420	Soil	3.1	<0.05	<0.02	0.02	0.04	21.9	43.3	0.75	897	0.72	<0.01	<0.05	41.9	661
SG 312421	Soil	2.9	<0.05	<0.02	0.02	0.05	19.6	38.8	0.88	935	0.91	<0.01	<0.05	41.4	856
SG 312422	Soil	3.1	<0.05	<0.02	0.02	0.05	14.4	40.5	0.83	975	1.27	<0.01	0.1	47.6	868
SG 312423	Soil	3.0	<0.05	<0.02	0.02	0.02	26.8	28.3	0.36	532	0.48	<0.01	<0.05	27.3	571
SG 312424	Soil	7.1	<0.05	0.02	0.02	0.01	17.2	78.0	0.99	523	0.43	0.01	0.1	48.3	457
SG 312425	Soil	8.0	<0.05	0.05	0.02	0.02	17.9	85.9	1.09	662	0.43	<0.01	<0.05	47.9	544
SG 312426	Soil	7.4	<0.05	0.03	0.02	0.02	7.0	83.8	1.03	532	0.48	<0.01	<0.05	48.2	375
SG 312427	Soil	7.8	<0.05	0.03	0.02	0.02	16.1	85.2	1.12	692	0.45	<0.01	0.1	53.8	555
SG 312428	Soil	7.2	<0.05	0.04	0.02	0.02	7.4	72.1	1.01	632	0.50	<0.01	<0.05	43.5	654
SG 312429	Soil	5.7	<0.05	<0.02	0.02	0.02	19.7	68.9	0.83	1792	0.43	<0.01	<0.05	56.5	512
SG 312430	Soil	7.9	<0.05	<0.02	0.03	0.02	9.4	79.7	1.07	673	0.52	<0.01	<0.05	53.1	473
SG 312431	Soil	8.1	0.1	<0.02	0.02	0.02	13.0	88.4	1.21	743	0.51	<0.01	0.1	58.5	458
SG 312432	Soil	6.6	0.1	<0.02	0.02	0.01	6.1	54.5	0.73	493	0.42	0.01	0.2	35.1	529
SG 312433	Soil	7.9	<0.05	0.07	0.02	0.02	15.3	65.8	0.83	500	0.56	0.01	0.2	39.1	594
SG 312434	Soil	5.1	<0.05	0.03	0.02	0.03	13.7	47.4	0.69	1340	0.75	0.01	0.1	43.0	977

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5
SI 480501	Soil	1.8	<0.05	<0.02	0.01	0.02	9.9	5.7	0.09	276	0.52	<0.01	0.1	23.9	337
SI 480502	Soil	2.2	<0.05	<0.02	0.04	0.02	24.3	3.2	0.04	206	0.87	<0.01	0.1	29.1	800
SI 480503	Soil	1.6	<0.05	<0.02	0.02	0.02	15.7	6.7	0.10	251	0.60	<0.01	0.1	27.5	333
SI 480504	Soil	1.3	<0.05	<0.02	0.05	0.02	13.4	7.0	0.09	316	0.52	<0.01	0.1	31.4	332
SI 480505	Soil	2.5	<0.05	<0.02	0.03	0.03	11.1	0.7	0.02	128	0.78	<0.01	0.2	14.4	428
SI 480506	Soil	2.8	<0.05	<0.02	0.04	0.02	14.1	0.5	0.01	87	0.66	0.01	0.4	10.1	354
SI 480507	Soil	3.7	<0.05	<0.02	0.03	0.04	14.7	0.9	0.03	144	1.04	<0.01	0.5	16.2	767
SI 480508	Soil	6.2	<0.05	<0.02	0.02	0.03	21.5	13.6	0.21	224	0.79	<0.01	0.7	15.3	473
SI 480509	Soil	3.1	<0.05	<0.02	0.03	0.04	12.2	4.9	0.07	122	0.68	<0.01	0.3	15.7	854
SI 480510	Soil	3.3	<0.05	<0.02	0.04	0.04	15.9	12.3	0.18	332	0.79	<0.01	0.4	26.6	553
SI 480511	Soil	1.7	<0.05	<0.02	0.03	0.02	14.5	6.7	0.08	631	1.14	<0.01	0.1	24.5	659
SI 480512	Soil	1.5	<0.05	<0.02	0.02	0.02	14.6	4.4	0.05	240	1.34	<0.01	0.1	22.0	319
SI 480513	Soil	1.5	<0.05	<0.02	0.02	0.02	4.7	3.7	0.06	107	0.43	<0.01	0.1	7.9	528
SI 480514	Soil	1.2	<0.05	<0.02	0.03	0.02	8.2	5.4	0.07	197	1.50	<0.01	<0.05	23.2	282
SI 480515	Soil	2.8	<0.05	<0.02	0.04	0.03	12.8	16.3	0.17	455	1.13	<0.01	0.4	25.2	424
SI 480516	Soil	1.2	<0.05	<0.02	0.03	0.03	13.5	4.1	0.05	239	1.32	<0.01	<0.05	25.3	357
SI 480517	Soil	1.2	<0.05	<0.02	0.03	0.03	14.3	8.1	0.13	340	1.40	<0.01	<0.05	25.9	495
SI 480518	Soil	2.0	<0.05	<0.02	0.01	0.04	9.1	0.9	0.02	115	0.67	0.01	0.1	11.7	539
SI 480519	Soil	1.7	<0.05	<0.02	0.07	0.03	11.4	2.0	0.03	435	0.55	<0.01	0.1	28.1	705
SI 480520	Soil	2.5	<0.05	<0.02	0.02	0.04	23.0	24.2	0.38	498	0.56	<0.01	0.1	37.5	428
SI 480521	Soil	1.8	<0.05	<0.02	0.03	0.03	5.8	5.4	0.08	413	0.32	0.01	0.1	13.8	348
SI 480522	Soil	5.2	<0.05	<0.02	0.02	0.02	12.0	70.0	0.88	621	0.33	<0.01	0.1	43.6	356
SI 480523	Soil	4.5	<0.05	<0.02	0.02	0.02	11.8	61.7	0.89	492	0.35	<0.01	0.1	48.8	567
SI 480524	Soil	4.7	<0.05	<0.02	0.02	0.02	21.1	57.2	0.76	1070	0.48	<0.01	<0.05	55.6	443
SI 480525	Soil	1.5	<0.05	<0.02	0.02	0.03	19.2	12.8	0.20	946	0.60	<0.01	<0.05	28.9	464
SI 480526	Soil	6.8	<0.05	<0.02	0.02	0.02	23.9	78.1	0.98	767	0.37	<0.01	0.1	50.6	522
SI 480551	Soil	1.8	<0.05	<0.02	0.02	0.03	14.0	1.1	0.01	213	0.74	<0.01	0.1	18.9	388
SI 480552	Soil	2.2	<0.05	<0.02	0.03	0.04	19.9	13.0	0.18	428	0.81	<0.01	0.3	25.4	529
SI 480553	Soil	1.8	<0.05	<0.02	0.01	0.03	15.6	7.2	0.13	493	0.63	0.01	0.2	24.5	783
SI 480554	Soil	1.9	<0.05	<0.02	0.02	0.04	16.0	8.9	0.15	442	1.05	<0.01	0.1	31.6	780
SI 480555	Soil	1.7	<0.05	<0.02	<0.01	0.02	7.4	3.0	0.05	113	0.36	0.02	0.1	8.1	364
SI 480556	Soil	2.0	<0.05	<0.02	0.04	0.03	11.9	7.2	0.10	544	0.50	<0.01	0.1	32.0	498
SI 480557	Soil	1.4	<0.05	<0.02	0.04	0.02	11.2	6.4	0.09	890	0.48	<0.01	0.2	36.2	420
SI 480558	Soil	1.2	<0.05	<0.02	<0.01	0.03	3.6	1.7	0.04	445	0.20	0.02	0.2	5.8	602
SI 480559	Soil	0.9	<0.05	<0.02	0.03	0.03	9.3	4.1	0.07	1179	0.36	0.01	0.1	24.0	508
SI 480560	Soil	1.6	<0.05	<0.02	0.02	0.03	6.8	5.1	0.07	516	0.55	0.01	0.1	10.2	656
SI 480561	Soil	1.8	<0.05	<0.02	0.02	0.02	10.0	11.0	0.17	417	0.45	<0.01	0.1	31.6	497
SI 480562	Soil	6.6	<0.05	0.03	0.02	0.02	20.7	90.8	1.15	760	0.45	<0.01	<0.05	53.0	316
SI 480563	Soil	5.1	<0.05	<0.02	0.02	0.03	20.6	74.9	1.09	757	0.33	<0.01	0.1	54.3	618
SI 480564	Soil	1.4	<0.05	<0.02	0.03	0.04	21.4	2.6	0.06	261	0.57	<0.01	<0.05	45.9	316

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5
SI 480565	Soil	4.1	<0.05	<0.02	0.02	0.03	14.3	44.0	0.71	1187	0.46	<0.01	0.3	38.5	679
SI 480566	Soil	4.6	<0.05	<0.02	0.02	0.02	17.3	52.1	0.72	728	0.38	<0.01	0.1	41.1	492
SI 480567	Soil	3.3	<0.05	<0.02	0.02	0.02	13.5	42.6	0.64	770	0.41	<0.01	0.3	46.0	713
SI 480568	Soil	4.4	<0.05	<0.02	0.02	0.03	17.9	51.4	0.65	673	0.50	<0.01	0.3	43.5	624
SI 480569	Soil	2.7	<0.05	0.04	0.02	0.03	13.8	37.4	0.59	446	0.91	<0.01	<0.05	33.7	492
SI 480570	Soil	2.6	<0.05	<0.02	0.02	0.03	14.9	33.5	0.52	406	1.09	<0.01	0.1	33.3	552
SI 480571	Soil	2.6	<0.05	0.04	0.02	0.03	11.6	33.3	0.60	368	1.19	<0.01	0.1	34.0	549
SI 480572	Soil	4.4	<0.05	<0.02	0.02	0.02	18.3	28.8	0.44	261	0.52	<0.01	0.3	24.6	407
SI 480573	Soil	3.6	<0.05	<0.02	0.02	0.03	11.5	38.1	0.56	317	0.41	<0.01	0.1	29.3	474
SI 480574	Soil	3.3	<0.05	<0.02	0.02	0.02	16.0	34.6	0.43	450	0.33	<0.01	<0.05	44.2	223
SI 480575	Soil	2.7	<0.05	<0.02	0.02	0.03	9.1	30.5	0.48	303	0.32	<0.01	<0.05	30.3	475
SI 480576	Soil	3.3	<0.05	<0.02	0.02	0.02	11.0	35.5	0.48	314	0.31	<0.01	<0.05	32.4	439
SI 480577	Soil	3.1	<0.05	<0.02	0.02	0.04	11.2	19.0	0.26	1753	0.89	<0.01	0.1	31.9	1054
SI 480578	Soil	3.1	<0.05	<0.02	0.02	0.03	9.1	25.2	0.32	458	0.43	0.01	0.2	19.8	480
SI 480579	Soil	3.8	<0.05	<0.02	0.02	0.03	13.5	21.9	0.33	683	0.60	<0.01	0.2	21.3	911
SI 480580	Soil	4.0	<0.05	<0.02	0.02	0.03	13.8	54.8	0.72	476	0.53	<0.01	0.1	42.3	427
SI 480581	Soil	2.4	<0.05	<0.02	0.01	0.02	9.2	7.0	0.09	242	0.48	0.01	0.1	11.0	324
SI 480582	Soil	2.2	<0.05	<0.02	<0.01	0.02	7.3	5.0	0.08	191	0.40	0.02	0.2	7.0	492
SI 480583	Soil	3.3	<0.05	<0.02	<0.01	0.02	10.0	9.3	0.12	187	0.55	0.01	0.1	9.8	327
SI 480584	Soil	3.3	<0.05	<0.02	0.02	0.02	10.3	25.9	0.32	625	0.53	<0.01	0.2	24.2	559
SI 480585	Soil	1.8	<0.05	<0.02	0.03	0.02	18.2	9.7	0.12	347	0.70	<0.01	0.1	33.1	410
SI 480586	Soil	1.8	<0.05	<0.02	0.05	0.02	18.0	7.6	0.10	312	0.57	<0.01	0.1	36.8	431
SI 480587	Soil	3.5	<0.05	<0.02	0.03	0.02	16.6	9.1	0.13	277	0.76	<0.01	0.2	17.5	510
SI 480588	Soil	2.2	<0.05	<0.02	<0.01	0.02	4.2	1.7	0.03	73	0.30	0.02	0.1	7.7	463
SI 480589	Soil	5.4	<0.05	<0.02	0.02	0.02	15.4	38.1	0.46	330	0.59	<0.01	0.3	25.9	413
SI 480590	Soil	3.2	<0.05	<0.02	0.02	0.02	6.1	4.8	0.07	195	0.46	0.01	0.1	11.0	544
SI 484680	Soil	1.3	<0.05	<0.02	0.03	0.03	7.0	2.7	0.07	483	0.61	0.01	0.2	13.6	708
SI 484681	Soil	1.5	<0.05	<0.02	0.08	0.05	14.7	5.4	0.08	488	0.64	<0.01	0.1	16.0	571
SI 484682	Soil	1.5	<0.05	<0.02	0.07	0.05	9.0	3.2	0.05	460	0.72	<0.01	0.1	27.2	1440
SI 484683	Soil	1.7	<0.05	<0.02	0.09	0.05	9.4	4.3	0.08	354	1.14	<0.01	0.2	24.6	704
SI 484684	Soil	1.8	<0.05	<0.02	0.07	0.04	11.7	9.7	0.13	242	0.89	<0.01	0.1	26.5	597
SI 484685	Soil	1.9	<0.05	<0.02	0.12	0.04	12.2	7.0	0.10	463	0.87	<0.01	0.1	25.6	592
SI 484686	Soil	1.7	<0.05	<0.02	0.03	0.04	10.6	5.8	0.08	540	0.72	<0.01	0.1	36.7	727
SI 484687	Soil	3.3	<0.05	<0.02	0.05	0.02	18.4	1.7	0.04	464	1.12	<0.01	0.2	72.6	1079
SI 484688	Soil	1.9	<0.05	<0.02	0.02	0.03	12.2	8.5	0.12	300	0.70	<0.01	0.2	22.9	423
SI 484689	Soil	1.8	<0.05	<0.02	0.03	0.04	12.6	4.0	0.06	219	1.32	<0.01	0.1	23.1	427
SI 484690	Soil	2.0	<0.05	<0.02	0.03	0.04	10.7	11.4	0.16	373	1.08	0.01	0.2	28.8	560
SI 484691	Soil	1.8	<0.05	<0.02	0.02	0.03	7.5	3.2	0.07	194	0.66	<0.01	0.2	15.5	572
SI 484692	Soil	2.3	<0.05	<0.02	0.03	0.03	12.1	13.6	0.21	631	0.79	<0.01	0.3	30.4	484
SI 484693	Soil	1.3	<0.05	<0.02	0.06	0.03	9.6	4.2	0.07	789	0.57	<0.01	0.1	32.2	425

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5
SI 484694	Soil	1.4	<0.05	<0.02	0.02	0.03	7.3	6.7	0.12	843	0.40	<0.01	0.1	31.2	529
SI 484695	Soil	2.6	<0.05	<0.02	0.04	0.03	14.1	11.7	0.18	555	0.76	<0.01	0.2	31.6	452
SI 484696	Soil	2.3	<0.05	<0.02	0.02	0.03	14.2	11.0	0.17	394	0.73	<0.01	0.2	26.0	592
SI 484697	Soil	2.1	<0.05	<0.02	0.02	0.03	12.4	9.0	0.14	488	1.07	<0.01	0.1	29.8	717
SI 484698	Soil	1.5	<0.05	<0.02	0.02	0.02	14.9	8.1	0.12	415	0.90	<0.01	0.2	31.8	476
SI 484699	Soil	1.3	<0.05	<0.02	0.02	0.02	17.8	4.7	0.06	622	0.56	<0.01	0.1	35.2	676
SI 484700	Soil	1.2	<0.05	<0.02	0.02	0.02	11.2	5.3	0.08	281	0.60	<0.01	0.1	23.1	568
SI 484701	Soil	1.2	<0.05	<0.02	0.06	0.03	15.9	6.9	0.09	397	0.54	<0.01	0.1	24.5	344
SI 484702	Soil	4.2	<0.05	<0.02	0.02	0.02	10.4	18.9	0.24	416	0.75	<0.01	0.3	23.6	600
SI 484703	Soil	3.0	<0.05	<0.02	0.01	0.02	12.8	4.4	0.08	187	0.64	<0.01	0.1	15.6	389
SI 484704	Soil	4.4	<0.05	<0.02	0.02	0.03	18.6	59.3	0.75	873	0.51	<0.01	0.1	38.5	447
SI 484705	Soil	3.9	<0.05	<0.02	0.02	0.03	20.8	55.6	0.74	940	0.54	<0.01	0.1	38.8	443
SI 484706	Soil	4.4	<0.05	<0.02	0.03	0.02	17.9	63.1	0.79	781	0.50	<0.01	0.1	37.9	436
SI 484707	Soil	4.6	<0.05	<0.02	0.07	0.02	15.3	64.4	0.80	865	0.56	<0.01	0.1	40.5	428
SI 484708	Soil	5.1	<0.05	<0.02	0.04	0.03	23.3	56.5	0.62	695	0.74	<0.01	0.3	45.6	612
SI 484709	Soil	5.9	<0.05	<0.02	0.05	0.03	13.0	21.2	0.28	570	0.99	<0.01	0.5	23.8	491
SI 484710	Soil	4.2	<0.05	<0.02	0.02	0.02	14.4	4.2	0.07	212	0.74	<0.01	0.2	22.8	592
SI 484711	Soil	4.6	<0.05	<0.02	0.02	0.03	16.4	8.7	0.12	351	0.80	<0.01	0.4	22.6	391
SI 484712	Soil	2.9	<0.05	<0.02	0.02	0.02	16.2	11.4	0.15	966	0.56	<0.01	0.1	33.2	673
SI 484713	Soil	2.7	<0.05	<0.02	0.02	0.02	11.0	10.0	0.14	354	0.42	0.01	0.1	21.5	343
SI 484714	Soil	3.1	<0.05	<0.02	0.02	0.02	13.3	18.7	0.24	608	0.45	0.01	0.2	27.7	542
SI 484715	Soil	3.7	<0.05	<0.02	0.03	0.02	23.3	26.7	0.35	1097	0.59	<0.01	0.2	41.7	481
SI 484716	Soil	4.5	<0.05	<0.02	0.04	0.04	16.5	31.8	0.44	502	0.67	0.01	0.2	33.0	483
SI 484717	Soil	3.2	<0.05	<0.02	0.07	0.02	7.8	16.6	0.23	224	0.52	0.01	0.2	16.0	444
SI 484718	Soil	3.8	<0.05	<0.02	0.03	0.02	16.3	41.1	0.55	840	0.62	<0.01	0.1	39.8	370
SI 484719	Soil	3.9	<0.05	<0.02	0.07	0.05	15.8	13.3	0.18	386	1.10	<0.01	0.2	29.1	495
SI 484720	Soil	2.2	<0.05	<0.02	0.08	0.03	16.0	13.1	0.16	736	0.70	<0.01	0.1	34.0	454
SI 484721	Soil	1.5	<0.05	<0.02	0.03	0.02	22.2	3.8	0.07	485	0.66	<0.01	0.1	39.9	460
SI 484722	Soil	2.8	<0.05	<0.02	0.08	0.03	28.4	4.0	0.06	349	1.08	<0.01	0.1	53.9	973
SI 484723	Soil	1.6	<0.05	<0.02	<0.01	0.02	1.3	0.3	0.02	31	0.18	0.03	0.1	2.5	190
SI 484724	Soil	2.1	<0.05	<0.02	0.03	0.03	8.1	3.1	0.06	154	0.78	<0.01	0.4	17.5	637
SI 484725	Soil	1.5	<0.05	<0.02	0.02	0.02	20.2	6.3	0.09	306	0.68	<0.01	<0.05	28.2	390
SI 484726	Soil	2.1	<0.05	<0.02	0.02	0.03	15.3	1.2	0.02	159	0.57	<0.01	0.1	22.3	245
SI 484727	Soil	1.7	<0.05	<0.02	0.04	0.02	12.4	1.6	0.03	146	0.66	<0.01	0.1	13.9	372
SI 484728	Soil	2.4	<0.05	<0.02	0.04	0.02	13.8	2.8	0.05	169	0.75	<0.01	0.2	19.5	272
SI 484729	Soil	2.0	<0.05	<0.02	0.04	0.03	13.2	5.1	0.08	357	0.49	<0.01	0.1	24.8	380
SI 484730	Soil	2.0	<0.05	<0.02	0.05	0.04	13.9	5.1	0.06	136	0.62	<0.01	0.1	20.6	398
SI 484731	Soil	2.1	<0.05	<0.02	0.04	0.02	23.2	12.6	0.18	565	0.56	<0.01	0.1	37.4	450
SI 484732	Soil	2.4	<0.05	<0.02	0.06	0.03	17.5	17.5	0.22	604	0.58	<0.01	0.1	37.1	415
SI 484733	Soil	4.6	<0.05	<0.02	0.03	0.02	22.3	52.2	0.69	872	0.57	<0.01	<0.05	43.5	397

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5
SI 484734	Soil	4.2	<0.05	<0.02	0.04	0.03	12.6	32.5	0.43	330	0.56	<0.01	0.2	28.2	453
SI 484735	Soil	4.2	<0.05	<0.02	0.02	0.02	11.2	21.0	0.29	656	0.68	<0.01	0.3	20.5	525
SI 484736	Soil	4.1	<0.05	<0.02	0.01	0.02	7.8	11.0	0.14	302	0.49	0.01	0.2	7.7	951
SI 484737	Soil	4.7	<0.05	0.03	0.02	0.02	8.8	11.4	0.17	909	0.55	0.01	0.3	10.2	1471
SI 484738	Soil	4.3	<0.05	<0.02	0.02	0.02	9.1	18.2	0.24	1256	0.50	0.01	0.3	12.3	592
SI 484739	Soil	5.8	<0.05	<0.02	0.02	0.02	16.7	44.8	0.58	785	0.45	<0.01	0.3	31.6	1008
SI 484740	Soil	3.8	<0.05	<0.02	0.02	0.02	19.2	40.3	0.55	346	0.23	<0.01	<0.05	36.4	454
SI 484741	Soil	4.8	<0.05	<0.02	0.03	0.02	27.9	53.3	0.73	1821	0.68	<0.01	<0.05	62.2	653
SI 484742	Soil	5.1	<0.05	<0.02	0.02	0.04	11.5	32.4	0.48	3055	0.78	0.01	0.3	29.5	1112
SI 484743	Soil	7.4	<0.05	<0.02	0.03	0.03	21.3	60.7	0.84	554	0.55	<0.01	0.2	46.0	610
SI 484744	Soil	5.0	<0.05	<0.02	0.02	0.02	12.4	31.1	0.44	602	0.66	<0.01	0.2	34.9	690
SI 484745	Soil	7.3	<0.05	0.07	0.04	0.02	13.1	71.2	0.77	692	0.95	0.01	0.1	44.4	767
SI 484746	Soil	5.7	<0.05	0.10	0.03	0.02	11.9	31.8	0.38	419	0.60	<0.01	0.3	20.2	983
SI 484747	Soil	5.3	<0.05	0.05	0.02	0.03	8.4	36.0	0.42	528	0.59	0.01	0.2	25.4	900
SI 484748	Soil	1.9	<0.05	<0.02	<0.01	0.01	3.0	6.4	0.08	42	0.15	0.02	0.1	4.4	167
SI 484749	Soil	4.8	<0.05	<0.02	0.04	0.02	13.6	54.8	0.71	301	0.44	<0.01	<0.05	54.4	420
SI 484750	Soil	5.5	<0.05	0.03	0.03	0.02	12.3	62.7	0.83	1036	0.62	<0.01	<0.05	61.4	348
SI 484751	Soil	4.1	<0.05	<0.02	0.05	0.03	15.2	42.3	0.62	1146	0.67	<0.01	<0.05	58.5	678
SI 484752	Soil	3.9	<0.05	<0.02	0.03	0.03	11.8	33.7	0.49	805	0.53	<0.01	0.1	38.9	630
SI 484753	Soil	2.6	<0.05	0.03	0.01	0.03	4.8	12.1	0.18	434	0.48	0.02	0.2	13.9	508
SI 484754	Soil	3.5	<0.05	<0.02	0.02	0.03	7.2	11.7	0.18	545	0.58	0.01	0.2	24.1	841
SI 484755	Soil	7.2	<0.05	<0.02	0.03	0.02	14.9	69.1	0.76	387	0.46	<0.01	0.1	48.1	338
SI 484756	Soil	3.7	<0.05	0.08	0.02	0.02	6.5	25.9	0.29	188	0.58	0.02	0.5	26.4	873
SI 484757	Soil	1.1	<0.05	0.10	<0.01	0.03	1.2	4.8	0.14	3257	0.32	0.01	0.1	16.0	947
SI 484758	Soil	3.6	<0.05	0.06	0.01	0.01	5.2	25.2	0.27	130	0.42	0.02	0.5	32.9	786
SI 484759	Soil	3.2	<0.05	<0.02	0.03	0.02	38.3	26.8	0.35	552	0.50	<0.01	<0.05	48.3	288
SI 484760	Soil	5.2	<0.05	<0.02	0.03	0.02	27.0	45.3	0.59	523	0.52	<0.01	<0.05	52.6	329
SI 484761	Soil	2.7	<0.05	0.04	0.02	0.03	6.5	6.9	0.15	1406	0.81	<0.01	0.1	21.1	638
SI 484762	Soil	5.7	<0.05	<0.02	0.03	0.02	9.5	41.0	0.67	488	0.54	<0.01	<0.05	49.7	377
SI 484763	Soil	3.6	<0.05	<0.02	0.02	0.04	9.6	15.4	0.24	1015	0.54	<0.01	0.1	27.0	1158
SI 484764	Soil	2.1	<0.05	<0.02	0.03	0.02	11.3	6.3	0.08	215	1.09	<0.01	0.1	16.5	291
SI 484765	Soil	2.5	<0.05	<0.02	0.04	0.03	7.3	6.5	0.08	136	1.27	<0.01	0.1	21.1	388
SI 484766	Soil	0.4	<0.05	<0.02	<0.01	0.01	0.5	0.2	<0.01	9	0.06	0.02	<0.05	0.9	127
SI 484767	Soil	6.2	<0.05	<0.02	0.02	0.02	11.8	4.2	0.06	616	0.89	<0.01	0.3	15.0	701
SI 484768	Soil	1.8	<0.05	<0.02	0.02	0.02	8.7	6.8	0.09	242	0.83	<0.01	0.1	22.3	264
SI 484769	Soil	1.7	<0.05	<0.02	0.03	0.02	11.6	7.3	0.09	239	1.22	<0.01	<0.05	26.8	282
SI 484770	Soil	3.0	<0.05	<0.02	0.02	0.02	6.7	5.9	0.07	245	0.88	<0.01	0.1	21.0	332
SI 484771	Soil	2.3	<0.05	<0.02	0.02	0.02	5.8	7.6	0.11	278	0.58	0.01	0.1	17.7	346
SI 484772	Soil	1.7	<0.05	<0.02	0.04	0.02	10.8	5.0	0.08	348	1.69	<0.01	<0.05	29.3	267
SI 484773	Soil	1.1	<0.05	<0.02	0.07	0.03	7.3	3.8	0.07	364	0.38	<0.01	<0.05	25.4	272

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5
SI 484774	Soil	5.7	<0.05	<0.02	0.02	0.03	10.7	61.3	0.85	804	0.42	<0.01	0.1	43.9	397
SI 484775	Soil	5.3	<0.05	<0.02	0.02	0.03	12.6	62.8	0.85	621	0.50	<0.01	0.1	41.5	332
SI 484776	Soil	8.2	<0.05	<0.02	0.02	0.02	20.1	98.7	1.32	699	0.39	<0.01	<0.05	60.8	393
SI 484777	Soil	7.0	<0.05	<0.02	0.02	0.02	13.9	89.0	1.17	693	0.39	<0.01	0.1	57.4	376
SI 484778	Soil	3.2	<0.05	<0.02	0.01	0.01	5.2	25.5	0.33	314	0.32	0.01	0.1	18.2	575
SI 484779	Soil	4.2	<0.05	<0.02	0.02	0.02	8.0	50.5	0.60	499	0.49	<0.01	<0.05	43.7	368
SI 484780	Soil	4.2	<0.05	<0.02	0.03	0.02	12.0	38.0	0.45	894	0.66	<0.01	0.2	37.9	687
SI 484781	Soil	3.8	<0.05	<0.02	0.02	0.03	19.6	1.7	0.03	176	0.59	<0.01	0.1	19.5	435
SI 484782	Soil	3.0	<0.05	<0.02	0.02	0.07	16.3	2.6	0.05	299	0.76	<0.01	0.3	22.1	739
SI 484783	Soil	1.8	<0.05	<0.02	0.02	0.03	14.7	7.2	0.10	441	0.58	<0.01	0.2	30.2	411
SI 484784	Soil	3.3	<0.05	<0.02	0.04	0.02	12.0	32.8	0.43	1028	1.01	<0.01	0.1	47.9	681
SI 484785	Soil	6.7	<0.05	<0.02	0.02	0.03	17.3	70.7	0.87	536	0.48	<0.01	<0.05	52.5	482
SI 484786	Soil	5.7	<0.05	0.04	0.02	0.03	12.6	38.5	0.49	422	0.53	<0.01	0.1	31.0	919
SI 484787	Soil	6.3	<0.05	<0.02	0.02	0.03	13.1	60.3	0.78	641	0.52	<0.01	0.1	39.3	484
SI 484788	Soil	5.6	<0.05	<0.02	0.02	0.02	9.6	61.4	0.79	566	0.47	<0.01	<0.05	45.5	259
SI 484789	Soil	8.7	<0.05	0.05	0.03	0.02	10.5	79.5	1.11	705	0.46	<0.01	<0.05	60.5	463
SI 484790	Soil	5.7	<0.05	0.05	0.01	0.02	8.0	32.5	0.46	669	0.59	0.01	0.2	21.4	881
SI 484791	Soil	4.5	<0.05	<0.02	0.01	0.02	5.9	19.4	0.26	278	0.62	0.02	0.2	13.2	613
SI 484792	Soil	7.3	<0.05	0.04	0.02	0.02	15.8	74.0	1.00	730	0.58	<0.01	<0.05	51.0	428
SI 484793	Soil	8.2	<0.05	<0.02	0.02	0.02	18.1	84.5	0.97	548	0.70	<0.01	<0.05	56.5	470
SI 484794	Soil	6.6	<0.05	<0.02	0.03	0.02	25.1	75.0	0.90	1773	1.21	<0.01	<0.05	64.5	621
SI 484795	Soil	7.9	<0.05	<0.02	0.04	0.02	13.7	87.4	1.08	1137	0.96	<0.01	<0.05	62.0	357
SI 484796	Soil	4.7	<0.05	0.08	0.02	0.04	5.3	41.2	0.59	4142	0.85	0.01	0.1	33.1	1948
SI 484797	Soil	8.1	<0.05	<0.02	0.03	0.02	16.2	111.0	1.41	2199	0.61	<0.01	<0.05	71.2	551
SI 484798	Soil	8.4	<0.05	0.09	0.02	0.01	12.0	63.9	0.79	700	0.71	<0.01	0.1	44.2	894
SI 484799	Soil	5.1	<0.05	0.07	0.02	0.01	9.0	37.6	0.50	511	0.47	0.01	0.2	27.0	392
SI 484800	Soil	7.9	<0.05	0.03	0.02	0.02	10.3	76.5	1.06	756	0.70	<0.01	<0.05	49.0	554

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05
SG 312315	Soil	57.5	3.3	<0.01	<0.01	0.99	1.7	0.2	0.2	18.9	<0.01	0.16	6	0.008	<0.05
SG 312316	Soil	45.0	4.4	<0.01	<0.01	0.95	0.7	0.4	0.3	11.5	<0.01	0.10	1	0.009	<0.05
SG 312317	Soil	30.2	3.8	<0.01	0.01	0.37	0.3	0.4	0.2	7.7	<0.01	0.05	0	0.016	<0.05
SG 312318	Soil	86.2	3.1	<0.01	<0.01	2.63	1.7	0.3	0.3	46.7	<0.01	0.18	4	<0.005	<0.05
SG 312319	Soil	121.5	3.3	<0.01	<0.01	1.58	2.5	<0.2	0.3	42.4	<0.01	0.13	11	<0.005	<0.05
SG 312320	Soil	72.4	5.6	<0.01	<0.01	0.16	0.7	0.5	0.3	12.1	<0.01	0.10	1	0.007	<0.05
SG 312321	Soil	80.0	4.6	<0.01	0.03	0.47	0.4	0.5	0.3	18.1	<0.01	0.08	0	0.006	<0.05
SG 312322	Soil	35.7	2.9	<0.01	<0.01	0.06	0.5	0.4	<0.2	44.8	<0.01	0.11	1	<0.005	<0.05
SG 312323	Soil	39.9	2.9	<0.01	<0.01	0.52	2.4	0.4	<0.2	64.2	<0.01	0.15	11	<0.005	<0.05
SG 312324	Soil	54.1	5.6	<0.01	<0.01	0.67	0.5	0.5	0.3	42.3	<0.01	0.10	1	<0.005	0.06
SG 312325	Soil	52.6	3.8	<0.01	<0.01	0.48	1.1	0.3	<0.2	56.0	<0.01	0.10	2	0.005	<0.05
SG 312326	Soil	41.1	1.3	<0.01	<0.01	0.90	0.5	0.2	<0.2	70.7	<0.01	0.04	6	<0.005	<0.05
SG 312327	Soil	46.7	7.0	<0.01	0.02	0.19	0.9	0.6	0.3	9.9	<0.01	0.10	2	<0.005	<0.05
SG 312328	Soil	37.4	6.8	<0.01	<0.01	<0.05	1.6	0.5	0.3	4.4	<0.01	0.10	5	0.007	<0.05
SG 312329	Soil	14.8	3.4	<0.01	<0.01	0.10	0.3	0.4	0.2	3.8	<0.01	0.04	<0.2	0.013	<0.05
SG 312330	Soil	193.1	4.8	<0.01	0.01	1.14	0.4	0.2	0.3	12.1	<0.01	0.06	0	0.008	<0.05
SG 312331	Soil	219.1	2.6	<0.01	<0.01	1.78	1.2	0.4	0.2	66.1	<0.01	0.05	6	<0.005	<0.05
SG 312332	Soil	68.0	2.4	<0.01	<0.01	2.33	6.1	0.4	0.5	128.0	<0.01	0.16	11	<0.005	<0.05
SG 312333	Soil	139.3	2.9	<0.01	<0.01	3.41	2.1	0.4	0.3	22.9	<0.01	0.16	11	<0.005	<0.05
SG 312334	Soil	93.8	4.1	<0.01	<0.01	5.28	1.2	0.8	0.3	42.6	<0.01	0.15	4	<0.005	<0.05
SG 312335	Soil	117.3	4.6	<0.01	0.02	1.63	0.6	0.4	0.3	43.4	<0.01	0.06	1	0.007	<0.05
SG 312336	Soil	128.1	5.1	<0.01	0.01	1.71	1.1	0.7	0.3	20.5	<0.01	0.07	2	0.015	<0.05
SG 312337	Soil	42.2	3.2	<0.01	<0.01	3.71	1.4	0.7	<0.2	16.6	<0.01	0.17	5	<0.005	<0.05
SG 312338	Soil	66.7	5.8	<0.01	0.04	3.11	1.0	0.6	0.4	21.4	<0.01	0.09	2	0.012	<0.05
SG 312339	Soil	90.3	2.7	<0.01	0.02	0.60	0.4	0.5	<0.2	27.3	<0.01	0.11	0	<0.005	<0.05
SG 312340	Soil	541.2	3.7	<0.01	0.02	2.37	2.1	0.6	0.5	51.0	<0.01	0.09	8	<0.005	<0.05
SG 312341	Soil	185.5	2.4	<0.01	0.02	1.96	2.3	0.8	0.2	24.3	<0.01	0.08	15	<0.005	<0.05
SG 312342	Soil	599.5	2.5	<0.01	0.05	2.52	1.7	0.5	1.0	55.9	<0.01	0.08	5	<0.005	<0.05
SG 312343	Soil	536.0	2.4	<0.01	0.02	2.54	1.8	0.4	0.7	41.4	<0.01	0.10	9	<0.005	<0.05
SG 312344	Soil	35.1	1.5	<0.01	<0.01	<0.05	2.7	<0.2	<0.2	8.5	<0.01	0.15	8	<0.005	<0.05
SG 312345	Soil	36.0	1.7	<0.01	<0.01	<0.05	3.1	0.3	<0.2	8.2	<0.01	0.13	9	<0.005	<0.05
SG 312346	Soil	24.2	3.2	<0.01	<0.01	2.00	2.9	0.3	0.2	20.3	<0.01	0.14	5	<0.005	<0.05
SG 312347	Soil	27.7	2.6	<0.01	<0.01	1.28	3.0	<0.2	<0.2	17.7	<0.01	0.11	7	<0.005	<0.05
SG 312348	Soil	70.0	3.8	<0.01	<0.01	2.43	1.7	0.8	0.3	15.6	<0.01	0.23	3	0.010	<0.05
SG 312349	Soil	58.4	2.6	<0.01	<0.01	7.93	3.9	0.8	0.2	18.1	<0.01	0.43	12	<0.005	<0.05
SG 312350	Soil	63.4	2.7	<0.01	<0.01	3.80	1.7	0.6	0.2	31.8	<0.01	0.14	13	<0.005	<0.05
SG 312351	Soil	163.6	2.5	<0.01	<0.01	1.91	1.3	0.5	0.3	49.8	<0.01	0.06	5	<0.005	<0.05
SG 312352	Soil	196.4	3.8	<0.01	0.01	2.72	1.4	0.6	0.5	42.3	<0.01	0.07	5	<0.005	<0.05
SG 312353	Soil	184.2	3.4	<0.01	0.01	3.51	2.4	0.5	0.4	53.5	<0.01	0.19	10	<0.005	<0.05
SG 312354	Soil	78.9	2.6	<0.01	<0.01	0.56	0.7	<0.2	<0.2	10.6	<0.01	0.10	2	0.013	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05
SG 312355	Soil	314.8	3.0	<0.01	0.02	2.42	0.7	0.6	0.4	28.3	<0.01	0.05	2	0.008	<0.05
SG 312356	Soil	84.8	4.2	<0.01	0.03	1.50	1.1	0.9	<0.2	32.3	<0.01	0.03	2	0.010	<0.05
SG 312357	Soil	516.8	2.6	<0.01	0.01	2.20	1.7	0.4	0.8	38.6	<0.01	0.08	11	<0.005	<0.05
SG 312358	Soil	279.3	2.7	<0.01	<0.01	2.79	2.1	0.4	0.3	32.0	<0.01	0.08	10	<0.005	<0.05
SG 312359	Soil	49.0	2.1	<0.01	<0.01	<0.05	2.5	0.2	<0.2	10.7	<0.01	0.07	7	<0.005	<0.05
SG 312360	Soil	35.9	1.9	<0.01	<0.01	<0.05	3.0	0.3	<0.2	11.4	<0.01	0.07	7	<0.005	<0.05
SG 312361	Soil	30.2	2.5	<0.01	<0.01	0.25	2.7	<0.2	<0.2	16.9	<0.01	0.13	7	<0.005	<0.05
SG 312362	Soil	28.6	2.3	<0.01	<0.01	0.90	3.3	<0.2	<0.2	18.5	<0.01	0.10	9	<0.005	<0.05
SG 312363	Soil	17.8	5.4	<0.01	<0.01	<0.05	1.5	0.3	<0.2	5.9	<0.01	0.08	2	<0.005	<0.05
SG 312364	Soil	16.0	4.4	<0.01	<0.01	0.22	1.8	0.3	<0.2	9.3	<0.01	0.09	2	0.005	<0.05
SG 312365	Soil	20.9	2.9	<0.01	<0.01	0.32	3.3	0.3	<0.2	10.9	<0.01	0.12	5	<0.005	<0.05
SG 312366	Soil	32.4	3.3	<0.01	<0.01	1.12	2.6	0.4	<0.2	9.2	<0.01	0.08	3	<0.005	<0.05
SG 312367	Soil	15.8	2.5	<0.01	0.03	<0.05	2.9	0.6	<0.2	21.1	<0.01	0.07	4	<0.005	<0.05
SG 312368	Soil	16.4	2.7	<0.01	0.01	<0.05	1.7	0.4	<0.2	15.7	<0.01	0.09	3	<0.005	<0.05
SG 312369	Soil	16.8	2.5	<0.01	<0.01	<0.05	2.2	0.4	<0.2	12.5	<0.01	0.08	4	<0.005	<0.05
SG 312370	Soil	19.2	3.4	<0.01	<0.01	<0.05	2.3	<0.2	<0.2	19.8	<0.01	0.05	5	<0.005	<0.05
SG 312371	Soil	18.7	3.4	<0.01	0.02	<0.05	0.5	0.5	<0.2	10.7	<0.01	0.12	1	<0.005	<0.05
SG 312372	Soil	19.9	3.6	<0.01	<0.01	<0.05	2.0	0.5	<0.2	12.3	<0.01	0.09	4	<0.005	<0.05
SG 312373	Soil	35.3	2.4	<0.01	<0.01	0.47	3.5	0.4	<0.2	14.0	<0.01	0.10	9	<0.005	<0.05
SG 312374	Soil	25.8	2.3	<0.01	<0.01	0.85	3.8	0.5	<0.2	16.4	<0.01	0.12	7	<0.005	<0.05
SG 312375	Soil	36.1	3.4	<0.01	0.02	0.27	2.3	0.7	<0.2	10.9	<0.01	0.07	4	<0.005	<0.05
SG 312376	Soil	25.6	3.0	<0.01	<0.01	0.23	2.8	0.4	<0.2	8.6	<0.01	0.09	5	<0.005	<0.05
SG 312377	Soil	39.6	4.2	<0.01	0.02	0.38	1.6	0.5	<0.2	7.4	<0.01	0.07	2	0.005	<0.05
SG 312378	Soil	105.7	4.1	<0.01	0.01	3.95	0.7	0.3	<0.2	22.1	<0.01	0.57	1	<0.005	<0.05
SG 312379	Soil	21.5	2.2	<0.01	<0.01	0.37	1.0	0.3	<0.2	13.2	<0.01	0.17	1	<0.005	<0.05
SG 312380	Soil	29.3	5.2	<0.01	0.07	0.25	0.5	0.5	<0.2	9.5	<0.01	0.09	1	0.005	<0.05
SG 312381	Soil	17.0	2.8	<0.01	<0.01	1.57	2.0	0.2	<0.2	9.1	<0.01	0.09	3	<0.005	<0.05
SG 312382	Soil	29.6	4.9	<0.01	0.06	<0.05	0.5	0.6	0.3	5.4	<0.01	0.05	1	0.005	<0.05
SG 312383	Soil	47.0	4.5	<0.01	<0.01	0.36	1.5	0.5	0.3	4.3	<0.01	0.08	2	0.007	<0.05
SG 312384	Soil	33.4	6.0	<0.01	0.01	0.09	1.0	0.4	0.3	4.5	<0.01	0.07	1	0.008	<0.05
SG 312385	Soil	16.2	3.3	<0.01	0.02	0.07	0.7	0.4	<0.2	3.5	<0.01	0.07	1	0.007	<0.05
SG 312386	Soil	32.4	4.3	<0.01	<0.01	<0.05	1.8	0.5	0.2	4.0	<0.01	0.08	4	<0.005	<0.05
SG 312387	Soil	26.3	3.5	<0.01	<0.01	<0.05	1.2	0.3	<0.2	4.3	<0.01	0.06	2	<0.005	<0.05
SG 312388	Soil	21.8	2.9	<0.01	<0.01	0.29	1.5	0.6	<0.2	4.9	<0.01	0.07	2	<0.005	<0.05
SG 312389	Soil	18.4	3.3	<0.01	<0.01	1.28	1.3	0.4	<0.2	12.1	<0.01	0.07	1	<0.005	<0.05
SG 312390	Soil	15.3	3.9	<0.01	0.04	0.55	0.9	0.4	0.8	5.4	<0.01	0.04	1	<0.005	<0.05
SG 312391	Soil	36.6	4.7	<0.01	<0.01	0.05	2.5	0.2	0.2	6.7	<0.01	0.13	6	<0.005	<0.05
SG 312392	Soil	29.9	3.5	<0.01	<0.01	0.08	2.3	0.2	0.2	6.6	<0.01	0.07	4	0.007	<0.05
SG 312393	Soil	29.3	4.6	<0.01	<0.01	0.09	2.0	0.6	0.2	7.2	<0.01	0.07	3	0.008	<0.05
SG 312394	Soil	52.1	5.0	<0.01	<0.01	0.83	2.4	0.4	<0.2	9.2	<0.01	0.12	4	<0.005	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05
SG 312395	Soil	13.3	2.3	<0.01	0.03	0.09	0.3	0.4	<0.2	2.9	<0.01	0.03	0	0.005	<0.05
SG 312396	Soil	17.1	2.8	<0.01	0.03	<0.05	0.3	0.5	<0.2	4.1	<0.01	0.05	0	<0.005	<0.05
SG 312397	Soil	30.0	2.8	<0.01	<0.01	0.19	2.1	0.4	<0.2	10.4	<0.01	0.08	5	0.006	<0.05
SG 312398	Soil	41.1	2.4	<0.01	<0.01	6.96	1.6	0.6	<0.2	17.4	<0.01	0.19	7	<0.005	<0.05
SG 312399	Soil	66.9	4.2	<0.01	0.01	2.58	1.4	0.7	0.2	24.2	<0.01	0.20	4	<0.005	<0.05
SG 312400	Soil	60.4	3.0	<0.01	<0.01	2.95	2.2	0.5	<0.2	17.8	<0.01	0.16	10	<0.005	<0.05
SG 312401	Soil	12.3	4.1	<0.01	<0.01	0.29	0.1	<0.2	<0.2	3.9	<0.01	0.03	<0.2	0.008	<0.05
SG 312402	Soil	142.1	4.0	<0.01	<0.01	2.59	0.8	0.5	0.2	13.5	<0.01	0.17	2	<0.005	<0.05
SG 312403	Soil	54.7	3.7	<0.01	<0.01	3.96	1.6	0.7	<0.2	16.8	<0.01	0.21	5	<0.005	<0.05
SG 312404	Soil	49.5	3.0	<0.01	<0.01	4.08	2.4	0.7	<0.2	12.7	<0.01	0.26	8	<0.005	<0.05
SG 312405	Soil	54.9	3.7	<0.01	<0.01	4.80	1.9	0.4	<0.2	12.9	<0.01	0.22	4	<0.005	<0.05
SG 312406	Soil	46.1	3.4	<0.01	<0.01	4.44	2.9	0.5	<0.2	11.9	<0.01	0.26	12	<0.005	<0.05
SG 312407	Soil	51.9	2.5	<0.01	<0.01	0.81	1.7	0.3	<0.2	23.9	<0.01	0.07	5	<0.005	<0.05
SG 312408	Soil	85.7	2.1	<0.01	<0.01	1.45	1.5	0.3	<0.2	24.4	<0.01	0.10	7	<0.005	<0.05
SG 312409	Soil	29.1	2.9	<0.01	<0.01	<0.05	1.5	<0.2	<0.2	11.4	<0.01	0.06	4	<0.005	<0.05
SG 312410	Soil	26.2	2.0	<0.01	<0.01	<0.05	2.1	<0.2	<0.2	7.3	<0.01	0.07	9	<0.005	<0.05
SG 312411	Soil	24.0	3.1	<0.01	<0.01	0.32	2.3	<0.2	<0.2	12.7	<0.01	0.09	6	<0.005	<0.05
SG 312412	Soil	20.2	2.9	<0.01	<0.01	<0.05	1.9	<0.2	<0.2	9.8	<0.01	0.07	5	<0.005	<0.05
SG 312413	Soil	30.7	3.5	<0.01	<0.01	0.47	0.8	0.4	<0.2	4.1	<0.01	0.09	2	<0.005	<0.05
SG 312414	Soil	16.0	5.3	<0.01	<0.01	0.45	<0.1	0.5	0.2	4.2	<0.01	0.09	<0.2	<0.005	<0.05
SG 312415	Soil	23.8	4.0	<0.01	<0.01	0.84	0.7	0.2	<0.2	4.2	<0.01	0.14	1	<0.005	<0.05
SG 312416	Soil	39.5	5.9	<0.01	0.04	1.04	0.6	0.5	0.3	15.4	<0.01	0.08	1	0.006	<0.05
SG 312417	Soil	22.5	2.7	<0.01	<0.01	0.31	2.4	0.4	<0.2	9.1	<0.01	0.09	5	<0.005	<0.05
SG 312418	Soil	39.2	1.7	<0.01	<0.01	0.17	2.9	0.3	<0.2	8.1	<0.01	0.26	12	<0.005	<0.05
SG 312419	Soil	31.5	2.9	<0.01	<0.01	1.64	2.7	0.3	<0.2	17.1	<0.01	0.12	8	<0.005	<0.05
SG 312420	Soil	25.2	2.8	<0.01	<0.01	<0.05	3.3	0.3	<0.2	19.0	<0.01	0.12	7	<0.005	<0.05
SG 312421	Soil	25.0	3.0	<0.01	<0.01	0.21	3.5	0.4	<0.2	27.2	<0.01	0.11	7	<0.005	<0.05
SG 312422	Soil	31.8	2.6	<0.01	<0.01	0.76	3.1	0.6	<0.2	22.3	<0.01	0.12	6	<0.005	<0.05
SG 312423	Soil	23.0	3.6	<0.01	<0.01	0.74	1.0	<0.2	<0.2	12.3	<0.01	0.08	3	<0.005	<0.05
SG 312424	Soil	21.6	2.7	<0.01	<0.01	<0.05	1.2	0.5	<0.2	3.0	<0.01	0.11	3	<0.005	<0.05
SG 312425	Soil	31.7	2.5	<0.01	<0.01	<0.05	1.5	0.3	<0.2	2.8	<0.01	0.11	3	<0.005	<0.05
SG 312426	Soil	48.4	2.6	<0.01	<0.01	<0.05	1.5	0.3	<0.2	3.6	<0.01	0.07	3	<0.005	<0.05
SG 312427	Soil	30.4	3.1	<0.01	<0.01	<0.05	1.5	0.3	<0.2	3.8	<0.01	0.05	3	<0.005	<0.05
SG 312428	Soil	24.3	3.1	<0.01	<0.01	<0.05	1.2	0.4	<0.2	2.8	<0.01	0.05	2	<0.005	<0.05
SG 312429	Soil	63.8	1.6	<0.01	<0.01	0.27	2.2	0.3	<0.2	9.6	<0.01	0.11	7	<0.005	<0.05
SG 312430	Soil	46.5	2.9	<0.01	<0.01	<0.05	2.3	0.3	<0.2	3.8	<0.01	0.13	4	<0.005	<0.05
SG 312431	Soil	32.4	2.4	<0.01	<0.01	<0.05	2.0	<0.2	<0.2	4.4	<0.01	0.08	5	<0.005	<0.05
SG 312432	Soil	17.6	2.4	<0.01	<0.01	<0.05	0.9	0.5	<0.2	2.7	<0.01	0.07	1	<0.005	<0.05
SG 312433	Soil	22.0	4.0	<0.01	0.01	<0.05	1.3	0.5	<0.2	6.1	<0.01	0.07	2	<0.005	<0.05
SG 312434	Soil	37.3	4.2	<0.01	0.03	<0.05	0.8	0.7	<0.2	8.8	<0.01	0.21	1	<0.005	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05
SI 480501	Soil	26.5	2.5	<0.01	<0.01	0.93	0.3	0.4	<0.2	9.1	<0.01	0.07	0	<0.005	<0.05
SI 480502	Soil	74.5	2.9	<0.01	<0.01	3.86	5.0	0.5	0.5	200.7	<0.01	0.13	7	<0.005	0.06
SI 480503	Soil	51.3	3.3	<0.01	<0.01	3.33	1.4	0.2	<0.2	34.0	<0.01	0.16	9	<0.005	<0.05
SI 480504	Soil	252.4	3.5	<0.01	<0.01	3.56	1.3	0.5	0.3	34.8	<0.01	0.08	6	<0.005	<0.05
SI 480505	Soil	143.3	4.2	<0.01	0.04	2.22	0.2	0.4	0.4	10.9	<0.01	0.07	0	<0.005	<0.05
SI 480506	Soil	97.8	2.6	<0.01	<0.01	1.43	0.3	<0.2	0.4	7.7	<0.01	0.08	1	0.011	<0.05
SI 480507	Soil	105.7	6.6	<0.01	0.07	1.83	0.3	0.3	0.6	12.3	<0.01	0.09	0	0.007	<0.05
SI 480508	Soil	29.3	5.4	<0.01	<0.01	0.43	0.8	0.2	0.5	5.0	<0.01	0.08	4	0.012	0.06
SI 480509	Soil	91.6	6.9	<0.01	0.05	0.98	0.1	0.6	0.3	37.7	<0.01	0.10	0	<0.005	0.06
SI 480510	Soil	104.8	6.4	<0.01	0.02	1.34	0.6	0.6	0.4	28.3	<0.01	0.11	1	0.006	0.05
SI 480511	Soil	49.6	3.3	<0.01	<0.01	5.46	1.2	0.6	<0.2	27.2	<0.01	0.17	3	<0.005	<0.05
SI 480512	Soil	46.5	2.6	<0.01	<0.01	8.95	1.6	0.4	<0.2	15.5	<0.01	0.25	8	<0.005	<0.05
SI 480513	Soil	56.1	3.0	<0.01	0.03	0.99	<0.1	0.6	<0.2	9.3	<0.01	0.03	0	<0.005	<0.05
SI 480514	Soil	50.4	2.2	<0.01	0.01	5.21	2.1	0.7	<0.2	11.6	<0.01	0.33	9	<0.005	<0.05
SI 480515	Soil	106.5	5.9	<0.01	<0.01	2.57	1.5	0.5	0.4	16.4	<0.01	0.17	6	0.006	<0.05
SI 480516	Soil	61.8	3.3	<0.01	<0.01	5.63	2.2	0.8	<0.2	18.0	<0.01	0.28	9	<0.005	<0.05
SI 480517	Soil	61.9	2.7	<0.01	<0.01	3.87	1.4	0.5	<0.2	21.4	<0.01	0.26	5	<0.005	<0.05
SI 480518	Soil	26.7	4.5	<0.01	<0.01	1.05	<0.1	0.4	0.2	8.9	<0.01	0.07	<0.2	<0.005	<0.05
SI 480519	Soil	194.5	3.4	<0.01	0.02	1.64	0.5	0.4	0.3	66.3	<0.01	0.07	1	<0.005	<0.05
SI 480520	Soil	44.2	3.0	<0.01	<0.01	1.53	1.8	0.3	<0.2	32.3	<0.01	0.10	4	<0.005	<0.05
SI 480521	Soil	132.1	4.1	<0.01	0.01	0.75	0.6	0.3	0.3	21.4	<0.01	0.03	1	<0.005	<0.05
SI 480522	Soil	43.8	2.4	<0.01	<0.01	<0.05	1.7	0.5	<0.2	13.9	<0.01	0.10	4	<0.005	<0.05
SI 480523	Soil	23.8	1.7	<0.01	<0.01	0.21	2.2	0.3	<0.2	11.8	<0.01	0.10	5	<0.005	<0.05
SI 480524	Soil	34.6	1.7	<0.01	<0.01	0.75	3.2	0.2	<0.2	14.2	<0.01	0.08	7	<0.005	<0.05
SI 480525	Soil	49.9	2.0	<0.01	<0.01	1.47	1.3	<0.2	<0.2	21.3	<0.01	0.07	4	<0.005	<0.05
SI 480526	Soil	27.2	2.3	<0.01	<0.01	<0.05	2.5	0.2	<0.2	10.4	<0.01	0.07	7	<0.005	<0.05
SI 480551	Soil	20.6	4.5	<0.01	0.01	2.05	0.7	0.4	0.2	20.1	<0.01	0.13	2	<0.005	<0.05
SI 480552	Soil	38.9	5.5	<0.01	<0.01	2.38	1.4	0.5	0.3	36.1	<0.01	0.08	4	0.009	<0.05
SI 480553	Soil	32.9	3.5	<0.01	<0.01	1.00	1.5	0.5	<0.2	20.5	<0.01	0.04	6	0.017	<0.05
SI 480554	Soil	40.7	4.9	<0.01	<0.01	1.87	1.6	0.5	<0.2	37.1	<0.01	0.13	7	0.006	<0.05
SI 480555	Soil	15.6	3.7	<0.01	<0.01	0.33	0.1	0.3	<0.2	6.3	<0.01	0.06	0	0.007	<0.05
SI 480556	Soil	75.3	5.2	<0.01	<0.01	0.88	1.0	0.4	0.2	8.3	<0.01	0.15	3	<0.005	<0.05
SI 480557	Soil	69.2	3.9	<0.01	<0.01	0.47	1.8	0.5	<0.2	9.2	<0.01	0.10	4	<0.005	<0.05
SI 480558	Soil	16.1	2.1	<0.01	<0.01	0.07	0.4	0.5	<0.2	8.9	<0.01	0.02	0	0.014	<0.05
SI 480559	Soil	82.7	2.6	<0.01	<0.01	0.61	1.1	0.2	<0.2	22.3	<0.01	0.07	4	<0.005	<0.05
SI 480560	Soil	35.0	5.4	<0.01	0.02	0.13	0.6	0.3	<0.2	18.8	<0.01	0.08	1	<0.005	<0.05
SI 480561	Soil	54.8	2.8	<0.01	0.01	0.75	1.0	0.5	<0.2	9.4	<0.01	0.11	3	<0.005	<0.05
SI 480562	Soil	33.0	2.0	<0.01	<0.01	<0.05	2.5	<0.2	<0.2	8.7	<0.01	0.06	9	<0.005	<0.05
SI 480563	Soil	32.6	2.1	<0.01	<0.01	0.07	2.7	0.4	<0.2	13.2	<0.01	0.07	7	0.006	<0.05
SI 480564	Soil	33.4	4.9	<0.01	<0.01	4.54	1.8	0.4	0.3	44.5	<0.01	0.16	3	<0.005	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05
SI 480565	Soil	16.1	4.4	<0.01	0.02	0.07	1.2	<0.2	<0.2	19.6	<0.01	0.09	1	0.005	<0.05
SI 480566	Soil	24.2	2.3	<0.01	<0.01	0.16	2.3	<0.2	<0.2	12.7	<0.01	0.10	7	<0.005	<0.05
SI 480567	Soil	25.6	2.6	<0.01	<0.01	0.29	2.3	0.2	<0.2	11.6	<0.01	0.04	4	0.011	<0.05
SI 480568	Soil	22.2	4.6	<0.01	<0.01	0.08	2.1	<0.2	0.2	10.5	<0.01	0.09	3	0.009	<0.05
SI 480569	Soil	19.4	2.6	<0.01	<0.01	0.25	2.5	0.4	<0.2	12.7	<0.01	0.08	3	<0.005	<0.05
SI 480570	Soil	22.1	2.8	<0.01	<0.01	0.48	2.6	0.6	<0.2	14.5	<0.01	0.10	3	<0.005	<0.05
SI 480571	Soil	29.7	2.5	<0.01	0.03	0.60	2.2	0.7	<0.2	26.9	<0.01	0.10	4	<0.005	<0.05
SI 480572	Soil	13.8	4.1	<0.01	<0.01	<0.05	0.8	0.2	<0.2	4.0	<0.01	0.11	1	0.006	<0.05
SI 480573	Soil	15.6	4.9	<0.01	<0.01	<0.05	0.6	0.3	<0.2	11.5	<0.01	0.08	1	<0.005	<0.05
SI 480574	Soil	18.8	2.1	<0.01	<0.01	2.20	3.0	0.3	<0.2	18.4	<0.01	0.07	8	<0.005	<0.05
SI 480575	Soil	15.2	2.0	<0.01	<0.01	0.23	2.2	0.3	<0.2	21.8	<0.01	0.11	4	<0.005	<0.05
SI 480576	Soil	15.1	2.1	<0.01	<0.01	0.17	2.2	<0.2	<0.2	30.7	<0.01	0.07	6	<0.005	<0.05
SI 480577	Soil	54.0	5.9	<0.01	0.04	0.54	0.4	0.6	<0.2	9.0	<0.01	0.07	1	<0.005	0.08
SI 480578	Soil	12.2	4.7	<0.01	0.02	0.24	0.7	0.3	<0.2	19.1	<0.01	0.07	1	<0.005	<0.05
SI 480579	Soil	25.4	5.5	<0.01	0.05	0.08	0.4	0.5	<0.2	8.5	<0.01	0.08	1	<0.005	<0.05
SI 480580	Soil	16.1	3.2	<0.01	<0.01	<0.05	1.8	0.5	<0.2	10.3	<0.01	0.08	3	<0.005	<0.05
SI 480581	Soil	18.4	3.7	<0.01	<0.01	0.43	0.4	0.4	<0.2	8.5	<0.01	0.07	0	0.010	<0.05
SI 480582	Soil	9.5	3.3	<0.01	<0.01	0.17	0.3	0.4	<0.2	7.3	<0.01	0.04	0	0.016	<0.05
SI 480583	Soil	15.5	4.8	<0.01	0.01	0.24	0.1	0.4	0.2	3.5	<0.01	0.03	0	0.006	<0.05
SI 480584	Soil	32.4	4.1	<0.01	<0.01	0.39	0.6	0.4	<0.2	6.6	<0.01	0.04	1	0.007	<0.05
SI 480585	Soil	72.4	2.4	<0.01	<0.01	2.46	2.0	0.3	0.3	55.1	<0.01	0.11	4	<0.005	<0.05
SI 480586	Soil	128.7	3.2	<0.01	<0.01	1.89	1.5	0.4	0.4	64.6	<0.01	0.14	2	<0.005	<0.05
SI 480587	Soil	88.7	4.2	<0.01	0.01	0.88	0.2	0.5	0.3	24.7	<0.01	0.11	0	0.005	<0.05
SI 480588	Soil	22.3	2.5	<0.01	0.02	0.12	<0.1	0.4	<0.2	25.1	<0.01	0.07	<0.2	<0.005	<0.05
SI 480589	Soil	23.2	4.6	<0.01	<0.01	<0.05	0.4	0.4	<0.2	10.1	<0.01	0.13	1	<0.005	<0.05
SI 480590	Soil	25.3	4.6	<0.01	0.03	0.20	<0.1	0.6	<0.2	20.3	<0.01	0.08	<0.2	<0.005	<0.05
SI 484680	Soil	91.9	3.6	<0.01	0.03	1.87	0.8	0.7	0.2	19.1	<0.01	0.07	1	0.011	<0.05
SI 484681	Soil	155.1	4.6	<0.01	0.07	4.55	1.2	0.4	0.5	72.4	<0.01	0.10	5	<0.005	0.07
SI 484682	Soil	169.9	6.4	<0.01	0.15	3.03	0.3	0.7	<0.2	66.4	<0.01	0.10	1	<0.005	<0.05
SI 484683	Soil	435.9	5.6	<0.01	0.06	4.87	1.3	0.8	0.4	50.5	<0.01	0.10	4	0.006	0.06
SI 484684	Soil	200.2	4.7	<0.01	0.04	4.72	1.3	0.6	0.3	41.1	<0.01	0.08	6	<0.005	0.05
SI 484685	Soil	531.0	5.0	<0.01	0.03	4.78	1.5	0.6	0.4	33.0	<0.01	0.09	8	<0.005	0.06
SI 484686	Soil	48.1	5.6	<0.01	0.03	3.52	0.5	0.5	<0.2	27.6	<0.01	0.17	1	<0.005	<0.05
SI 484687	Soil	71.5	1.7	<0.01	0.04	0.50	1.1	<0.2	0.5	93.0	<0.01	0.08	0	<0.005	<0.05
SI 484688	Soil	42.7	3.8	<0.01	<0.01	2.23	1.1	0.6	<0.2	12.4	<0.01	0.13	4	0.007	<0.05
SI 484689	Soil	75.3	5.7	<0.01	0.04	4.12	0.9	0.4	<0.2	26.8	<0.01	0.05	3	<0.005	0.06
SI 484690	Soil	95.5	5.2	<0.01	0.08	3.27	1.2	0.9	0.2	34.3	<0.01	0.11	3	0.008	0.07
SI 484691	Soil	46.4	4.4	<0.01	0.05	1.15	0.1	0.6	<0.2	11.7	<0.01	0.04	0	<0.005	<0.05
SI 484692	Soil	166.2	5.4	<0.01	0.02	3.71	1.4	0.4	0.4	23.3	<0.01	0.06	4	0.010	0.06
SI 484693	Soil	280.4	3.9	<0.01	0.03	2.18	0.7	0.5	0.2	17.9	<0.01	0.09	1	<0.005	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05
SI 484694	Soil	42.8	3.2	<0.01	0.01	0.70	0.5	0.4	<0.2	8.7	<0.01	0.12	1	<0.005	<0.05
SI 484695	Soil	133.5	5.9	<0.01	0.01	1.78	0.6	<0.2	0.4	12.3	<0.01	0.12	1	0.009	<0.05
SI 484696	Soil	58.7	5.1	<0.01	0.02	1.27	0.6	0.7	0.2	12.9	<0.01	0.05	1	0.009	<0.05
SI 484697	Soil	49.1	5.1	<0.01	0.03	1.47	0.3	0.6	<0.2	13.9	<0.01	0.12	1	<0.005	0.05
SI 484698	Soil	40.5	3.7	<0.01	<0.01	1.85	1.4	0.3	<0.2	18.9	<0.01	0.09	7	0.007	<0.05
SI 484699	Soil	33.2	1.9	<0.01	<0.01	1.16	3.1	0.3	0.4	192.3	<0.01	0.09	11	<0.005	<0.05
SI 484700	Soil	41.0	2.5	<0.01	<0.01	2.03	1.9	0.3	<0.2	34.1	<0.01	0.09	8	<0.005	<0.05
SI 484701	Soil	307.2	3.1	<0.01	<0.01	3.13	1.3	0.3	0.4	47.6	<0.01	0.11	5	<0.005	<0.05
SI 484702	Soil	30.6	4.6	<0.01	0.03	0.99	0.3	0.6	0.2	9.9	<0.01	0.13	1	<0.005	<0.05
SI 484703	Soil	29.2	4.6	<0.01	0.02	0.88	<0.1	0.3	0.2	9.9	<0.01	0.08	0	<0.005	<0.05
SI 484704	Soil	55.6	3.4	<0.01	0.01	1.27	1.0	0.3	<0.2	19.6	<0.01	0.12	2	<0.005	<0.05
SI 484705	Soil	61.7	2.6	<0.01	<0.01	1.77	1.4	<0.2	<0.2	26.6	<0.01	0.14	4	<0.005	<0.05
SI 484706	Soil	69.9	3.0	<0.01	<0.01	1.19	1.1	0.3	<0.2	17.2	<0.01	0.07	2	<0.005	<0.05
SI 484707	Soil	225.1	3.1	<0.01	0.01	1.57	1.2	<0.2	<0.2	17.8	<0.01	0.09	2	<0.005	<0.05
SI 484708	Soil	102.9	4.4	<0.01	<0.01	2.10	1.5	0.6	0.3	12.7	<0.01	0.11	3	0.007	<0.05
SI 484709	Soil	75.4	8.7	<0.01	0.03	1.21	0.4	0.6	0.5	9.6	<0.01	0.13	0	0.006	0.05
SI 484710	Soil	54.5	4.4	<0.01	0.03	0.54	0.2	0.4	0.3	3.7	<0.01	0.02	0	<0.005	<0.05
SI 484711	Soil	46.1	5.8	<0.01	0.02	0.50	0.3	0.6	0.4	7.0	<0.01	0.07	0	0.006	0.05
SI 484712	Soil	62.2	3.9	<0.01	<0.01	0.64	0.6	0.6	<0.2	16.1	<0.01	0.08	1	<0.005	<0.05
SI 484713	Soil	37.7	3.6	<0.01	0.01	0.29	0.3	<0.2	<0.2	9.2	<0.01	0.04	0	0.007	<0.05
SI 484714	Soil	36.0	3.6	<0.01	<0.01	0.37	1.1	0.3	<0.2	11.1	<0.01	0.04	4	0.010	<0.05
SI 484715	Soil	91.3	3.8	<0.01	<0.01	0.97	1.6	0.4	0.2	11.8	<0.01	0.08	4	0.006	<0.05
SI 484716	Soil	157.7	5.5	<0.01	0.02	2.31	0.6	0.7	0.3	14.3	<0.01	0.06	1	<0.005	<0.05
SI 484717	Soil	193.1	3.6	<0.01	0.02	1.65	0.3	0.5	0.2	8.3	<0.01	0.10	0	<0.005	<0.05
SI 484718	Soil	75.9	2.6	<0.01	<0.01	2.67	1.5	0.3	<0.2	26.3	<0.01	0.10	4	<0.005	<0.05
SI 484719	Soil	130.1	9.2	<0.01	0.02	1.77	0.5	0.5	0.4	26.2	<0.01	0.11	1	<0.005	0.08
SI 484720	Soil	209.7	3.8	<0.01	0.01	2.40	1.0	0.4	0.3	36.7	<0.01	0.12	2	<0.005	0.05
SI 484721	Soil	62.2	3.0	<0.01	<0.01	1.75	1.2	0.4	<0.2	65.9	<0.01	0.07	4	<0.005	<0.05
SI 484722	Soil	215.0	3.3	<0.01	0.02	2.95	5.7	0.6	0.7	195.8	<0.01	0.05	12	<0.005	0.06
SI 484723	Soil	4.3	0.9	<0.01	<0.01	<0.05	<0.1	0.2	<0.2	8.4	<0.01	<0.01	<0.2	0.023	<0.05
SI 484724	Soil	63.4	3.6	<0.01	0.09	1.37	0.3	0.6	0.3	15.9	<0.01	0.04	0	0.007	<0.05
SI 484725	Soil	36.9	2.8	<0.01	<0.01	4.80	2.0	0.4	<0.2	35.2	<0.01	0.12	10	<0.005	<0.05
SI 484726	Soil	39.6	4.6	<0.01	0.01	1.59	0.5	0.4	<0.2	36.1	<0.01	0.09	1	<0.005	<0.05
SI 484727	Soil	253.1	3.3	<0.01	0.02	4.88	0.5	0.2	0.3	15.2	<0.01	0.13	1	<0.005	<0.05
SI 484728	Soil	226.0	3.1	<0.01	<0.01	2.92	0.6	0.2	0.3	13.3	<0.01	0.09	1	0.005	<0.05
SI 484729	Soil	112.6	3.7	<0.01	<0.01	1.50	0.3	0.4	0.2	31.2	<0.01	0.04	0	<0.005	<0.05
SI 484730	Soil	154.0	5.8	<0.01	0.02	1.84	1.1	0.3	0.3	73.2	<0.01	0.08	2	<0.005	0.06
SI 484731	Soil	99.9	2.8	<0.01	<0.01	1.83	1.7	0.5	0.2	43.8	<0.01	0.11	7	<0.005	<0.05
SI 484732	Soil	139.3	3.2	<0.01	<0.01	2.04	1.5	0.4	0.3	25.2	<0.01	0.07	5	<0.005	<0.05
SI 484733	Soil	67.2	2.4	<0.01	<0.01	1.99	1.7	0.3	<0.2	22.7	<0.01	0.10	5	<0.005	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05
SI 484734	Soil	105.8	5.8	<0.01	0.02	1.32	0.3	<0.2	0.2	12.7	<0.01	0.04	0	<0.005	<0.05
SI 484735	Soil	22.4	4.5	<0.01	0.02	0.50	0.2	0.5	0.2	4.3	<0.01	0.05	0	<0.005	<0.05
SI 484736	Soil	10.7	3.2	<0.01	0.06	0.24	<0.1	0.5	<0.2	3.5	<0.01	0.02	0	<0.005	<0.05
SI 484737	Soil	15.6	3.0	<0.01	0.10	0.19	0.2	0.7	<0.2	10.9	<0.01	0.03	0	<0.005	<0.05
SI 484738	Soil	14.8	3.3	<0.01	0.05	<0.05	<0.1	0.4	<0.2	6.9	<0.01	0.05	<0.2	<0.005	<0.05
SI 484739	Soil	12.9	4.7	<0.01	0.04	<0.05	0.5	0.6	<0.2	25.4	<0.01	0.04	1	<0.005	<0.05
SI 484740	Soil	11.9	1.7	<0.01	<0.01	0.66	1.7	<0.2	<0.2	15.9	<0.01	0.08	6	<0.005	<0.05
SI 484741	Soil	40.4	1.9	<0.01	<0.01	0.48	3.2	<0.2	<0.2	26.3	<0.01	0.15	10	<0.005	<0.05
SI 484742	Soil	36.8	6.7	<0.01	0.09	0.07	0.3	0.4	<0.2	11.6	<0.01	0.09	0	<0.005	<0.05
SI 484743	Soil	29.7	4.6	<0.01	<0.01	<0.05	1.4	<0.2	<0.2	4.5	<0.01	0.17	3	<0.005	<0.05
SI 484744	Soil	22.9	4.4	<0.01	0.04	0.65	0.6	<0.2	<0.2	5.9	<0.01	0.05	1	<0.005	<0.05
SI 484745	Soil	75.6	3.9	<0.01	0.04	0.93	1.1	0.3	<0.2	6.6	<0.01	0.14	3	<0.005	<0.05
SI 484746	Soil	27.8	4.6	<0.01	0.05	0.11	0.6	0.3	<0.2	3.1	<0.01	0.10	2	<0.005	<0.05
SI 484747	Soil	28.3	7.0	<0.01	0.05	0.22	0.6	0.2	<0.2	7.3	<0.01	0.07	1	<0.005	<0.05
SI 484748	Soil	5.3	1.2	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	2.9	<0.01	<0.01	<0.2	0.008	<0.05
SI 484749	Soil	36.8	2.4	<0.01	<0.01	0.80	2.9	<0.2	<0.2	10.7	<0.01	0.09	6	<0.005	<0.05
SI 484750	Soil	49.7	2.0	<0.01	0.08	0.98	3.4	0.3	<0.2	10.3	<0.01	0.21	10	<0.005	0.07
SI 484751	Soil	60.1	2.4	<0.01	0.01	2.25	2.8	0.4	<0.2	14.6	<0.01	0.10	7	<0.005	<0.05
SI 484752	Soil	30.7	3.2	<0.01	<0.01	1.48	1.2	0.2	<0.2	11.1	<0.01	0.15	1	<0.005	<0.05
SI 484753	Soil	13.0	4.8	<0.01	0.03	0.55	0.2	0.4	<0.2	13.6	<0.01	0.06	1	<0.005	<0.05
SI 484754	Soil	33.6	5.9	<0.01	0.06	0.91	0.1	0.5	<0.2	17.3	<0.01	0.07	<0.2	<0.005	<0.05
SI 484755	Soil	23.7	5.0	<0.01	<0.01	0.33	1.6	<0.2	<0.2	9.2	<0.01	0.11	3	<0.005	<0.05
SI 484756	Soil	14.6	2.7	<0.01	0.12	0.46	0.9	0.6	<0.2	24.6	<0.01	0.05	1	<0.005	<0.05
SI 484757	Soil	8.7	3.0	<0.01	0.18	0.19	0.3	0.4	<0.2	39.4	0.02	0.04	0	<0.005	<0.05
SI 484758	Soil	8.0	2.8	<0.01	0.11	<0.05	0.6	0.9	<0.2	34.8	<0.01	<0.01	1	0.006	<0.05
SI 484759	Soil	32.9	2.8	<0.01	<0.01	5.03	2.2	<0.2	<0.2	10.5	<0.01	0.13	5	<0.005	<0.05
SI 484760	Soil	32.9	3.4	<0.01	<0.01	2.78	2.4	0.3	<0.2	7.0	<0.01	0.09	5	<0.005	<0.05
SI 484761	Soil	28.0	1.9	<0.01	0.06	6.23	0.4	0.3	<0.2	28.2	<0.01	0.11	1	<0.005	<0.05
SI 484762	Soil	18.5	2.3	<0.01	<0.01	1.46	1.7	<0.2	<0.2	8.9	<0.01	0.12	2	<0.005	<0.05
SI 484763	Soil	26.7	5.3	<0.01	0.06	1.26	0.5	<0.2	<0.2	8.9	<0.01	0.04	1	<0.005	<0.05
SI 484764	Soil	67.7	3.5	<0.01	<0.01	4.27	0.3	0.4	<0.2	18.6	<0.01	0.13	1	<0.005	<0.05
SI 484765	Soil	69.4	5.2	<0.01	<0.01	3.62	0.7	0.5	<0.2	15.6	<0.01	0.24	1	<0.005	<0.05
SI 484766	Soil	0.4	0.7	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	2.5	<0.01	<0.01	<0.2	0.007	<0.05
SI 484767	Soil	57.8	6.3	<0.01	0.01	0.34	<0.1	0.4	0.4	5.1	<0.01	0.08	0	<0.005	<0.05
SI 484768	Soil	35.8	3.2	<0.01	<0.01	2.93	0.8	<0.2	<0.2	9.1	<0.01	0.11	2	<0.005	<0.05
SI 484769	Soil	42.7	3.8	<0.01	<0.01	4.93	1.3	0.6	<0.2	9.3	<0.01	0.32	4	<0.005	<0.05
SI 484770	Soil	33.6	4.4	<0.01	<0.01	2.43	0.2	0.5	<0.2	4.5	<0.01	0.10	0	<0.005	<0.05
SI 484771	Soil	34.0	3.4	<0.01	0.01	1.27	0.1	0.5	<0.2	5.1	<0.01	0.06	0	<0.005	<0.05
SI 484772	Soil	61.5	3.4	<0.01	<0.01	6.65	2.5	0.6	<0.2	11.8	<0.01	0.39	9	<0.005	<0.05
SI 484773	Soil	255.9	2.8	<0.01	0.01	1.62	0.7	0.3	0.3	41.2	<0.01	0.08	3	<0.005	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05
SI 484774	Soil	53.2	3.1	<0.01	0.01	0.14	1.2	<0.2	<0.2	14.5	<0.01	0.08	2	<0.005	<0.05
SI 484775	Soil	44.3	3.0	<0.01	<0.01	0.06	1.6	<0.2	<0.2	14.5	<0.01	0.06	4	<0.005	<0.05
SI 484776	Soil	28.9	1.4	<0.01	<0.01	<0.05	2.1	<0.2	<0.2	4.8	<0.01	0.07	8	<0.005	<0.05
SI 484777	Soil	32.1	1.7	<0.01	<0.01	<0.05	2.1	<0.2	<0.2	8.1	<0.01	0.06	7	<0.005	<0.05
SI 484778	Soil	10.4	2.3	<0.01	0.03	0.08	0.2	<0.2	<0.2	4.8	<0.01	<0.01	1	<0.005	<0.05
SI 484779	Soil	26.1	1.7	<0.01	<0.01	0.64	1.6	0.3	<0.2	11.3	<0.01	0.12	3	<0.005	<0.05
SI 484780	Soil	49.8	4.3	<0.01	<0.01	0.53	1.5	<0.2	<0.2	9.9	<0.01	0.09	5	0.006	<0.05
SI 484781	Soil	36.8	4.2	<0.01	<0.01	1.22	<0.1	0.2	<0.2	15.7	<0.01	0.07	0	<0.005	<0.05
SI 484782	Soil	50.0	8.0	<0.01	0.03	1.27	0.3	0.5	0.3	24.2	<0.01	0.10	0	<0.005	0.05
SI 484783	Soil	35.2	5.9	<0.01	<0.01	1.18	0.9	0.4	<0.2	15.1	<0.01	0.07	3	<0.005	0.05
SI 484784	Soil	41.1	2.7	<0.01	0.05	2.66	2.5	0.9	<0.2	27.9	<0.01	0.06	3	<0.005	<0.05
SI 484785	Soil	29.2	4.4	<0.01	<0.01	0.09	1.4	<0.2	<0.2	10.5	<0.01	0.11	3	<0.005	<0.05
SI 484786	Soil	29.4	4.7	<0.01	0.04	0.60	0.6	<0.2	<0.2	9.9	<0.01	0.06	2	<0.005	<0.05
SI 484787	Soil	30.5	4.2	<0.01	0.01	<0.05	1.0	<0.2	<0.2	8.5	<0.01	0.07	3	<0.005	<0.05
SI 484788	Soil	36.7	2.5	<0.01	<0.01	<0.05	1.8	<0.2	<0.2	11.2	<0.01	0.08	5	<0.005	<0.05
SI 484789	Soil	45.8	2.5	<0.01	<0.01	<0.05	3.1	<0.2	<0.2	6.2	<0.01	0.04	9	<0.005	<0.05
SI 484790	Soil	22.1	3.5	<0.01	0.06	<0.05	0.4	0.4	<0.2	3.1	<0.01	0.01	1	<0.005	<0.05
SI 484791	Soil	12.8	3.2	<0.01	0.03	<0.05	0.1	0.3	<0.2	6.4	<0.01	0.03	0	0.005	<0.05
SI 484792	Soil	41.2	4.0	<0.01	<0.01	<0.05	0.9	<0.2	<0.2	4.0	<0.01	0.10	2	<0.005	<0.05
SI 484793	Soil	56.7	3.6	<0.01	<0.01	<0.05	1.4	<0.2	<0.2	6.4	<0.01	0.08	2	<0.005	<0.05
SI 484794	Soil	53.0	3.9	<0.01	<0.01	0.35	1.1	<0.2	<0.2	10.5	<0.01	0.19	2	<0.005	<0.05
SI 484795	Soil	38.2	2.9	<0.01	<0.01	1.66	2.8	<0.2	<0.2	7.1	<0.01	0.09	5	<0.005	<0.05
SI 484796	Soil	44.7	3.8	<0.01	0.11	0.14	0.7	0.3	<0.2	17.1	<0.01	0.05	1	<0.005	<0.05
SI 484797	Soil	41.2	2.1	<0.01	<0.01	<0.05	2.7	<0.2	<0.2	6.5	<0.01	0.14	3	<0.005	<0.05
SI 484798	Soil	29.7	3.1	<0.01	0.02	<0.05	1.2	0.4	<0.2	3.3	<0.01	0.06	2	<0.005	<0.05
SI 484799	Soil	17.1	2.3	<0.01	0.01	<0.05	0.6	0.5	<0.2	1.9	<0.01	0.03	1	0.006	<0.05
SI 484800	Soil	36.9	4.1	<0.01	<0.01	<0.05	1.1	<0.2	<0.2	4.4	<0.01	0.06	2	<0.005	<0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SG 312315	Soil	2	15	1.26	3.6	157	<0.5
SG 312316	Soil	1	16	1.01	2.1	75	<0.5
SG 312317	Soil	0	16	1.40	1.1	21	<0.5
SG 312318	Soil	1	13	1.49	2.6	123	<0.5
SG 312319	Soil	2	16	2.19	3.9	149	<0.5
SG 312320	Soil	1	21	0.99	2.3	70	<0.5
SG 312321	Soil	1	19	1.22	1.9	66	<0.5
SG 312322	Soil	2	11	1.39	2.1	79	<0.5
SG 312323	Soil	2	14	1.54	3.4	160	<0.5
SG 312324	Soil	1	16	0.97	2.5	73	<0.5
SG 312325	Soil	1	15	1.54	2.6	106	<0.5
SG 312326	Soil	1	2	1.66	1.3	47	1.4
SG 312327	Soil	1	21	1.20	2.4	80	<0.5
SG 312328	Soil	1	23	2.38	2.3	81	0.6
SG 312329	Soil	0	17	0.87	1.0	23	<0.5
SG 312330	Soil	1	17	0.89	1.9	74	<0.5
SG 312331	Soil	2	7	1.76	3.8	197	<0.5
SG 312332	Soil	2	49	2.16	7.6	126	3.0
SG 312333	Soil	2	11	1.37	3.1	122	0.6
SG 312334	Soil	1	10	1.54	2.2	49	<0.5
SG 312335	Soil	1	14	1.54	2.8	94	<0.5
SG 312336	Soil	1	17	0.64	3.1	83	<0.5
SG 312337	Soil	1	11	1.24	2.3	89	<0.5
SG 312338	Soil	2	18	2.01	3.2	81	<0.5
SG 312339	Soil	2	9	0.79	4.1	170	0.6
SG 312340	Soil	2	13	2.76	2.9	285	<0.5
SG 312341	Soil	4	7	1.49	3.5	241	<0.5
SG 312342	Soil	1	6	1.75	2.3	239	<0.5
SG 312343	Soil	1	5	2.05	3.7	171	1.5
SG 312344	Soil	1	21	1.04	3.1	136	2.4
SG 312345	Soil	1	23	0.24	3.2	136	2.6
SG 312346	Soil	1	13	1.61	4.6	88	<0.5
SG 312347	Soil	1	16	1.10	3.9	108	<0.5
SG 312348	Soil	2	18	1.41	3.2	117	<0.5
SG 312349	Soil	1	9	0.71	1.9	101	6.5
SG 312350	Soil	2	9	0.80	2.8	103	1.1
SG 312351	Soil	1	7	1.41	2.6	141	<0.5
SG 312352	Soil	2	12	2.91	2.6	128	<0.5
SG 312353	Soil	2	9	2.49	3.7	230	<0.5
SG 312354	Soil	1	14	1.54	1.7	76	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SG 312355	Soil	1	8	2.28	2.6	52	<0.5
SG 312356	Soil	3	11	2.34	3.4	80	<0.5
SG 312357	Soil	2	7	2.37	2.7	201	1.9
SG 312358	Soil	2	7	11.28	4.5	167	<0.5
SG 312359	Soil	1	20	5.29	2.7	128	1.2
SG 312360	Soil	2	23	5.15	4.5	110	1.2
SG 312361	Soil	1	20	2.14	2.9	126	0.6
SG 312362	Soil	1	18	2.69	3.9	118	1.6
SG 312363	Soil	1	19	1.42	3.1	89	1.1
SG 312364	Soil	1	19	1.66	4.4	83	0.8
SG 312365	Soil	2	17	1.76	8.9	89	2.2
SG 312366	Soil	2	16	1.15	8.4	83	3.1
SG 312367	Soil	3	15	1.36	9.6	78	2.9
SG 312368	Soil	1	12	1.49	4.9	66	2.0
SG 312369	Soil	2	14	1.47	5.6	86	1.0
SG 312370	Soil	2	13	3.06	5.6	81	1.1
SG 312371	Soil	1	14	1.96	2.3	69	1.2
SG 312372	Soil	1	13	1.99	6.7	89	3.1
SG 312373	Soil	1	16	1.73	8.2	95	3.8
SG 312374	Soil	1	14	1.78	9.7	92	2.4
SG 312375	Soil	2	15	2.04	6.7	105	2.7
SG 312376	Soil	2	16	1.47	7.6	87	1.3
SG 312377	Soil	2	15	29.37	4.4	113	1.2
SG 312378	Soil	1	7	3.94	1.8	152	<0.5
SG 312379	Soil	1	10	1.54	4.7	81	<0.5
SG 312380	Soil	1	18	1.67	2.4	63	2.1
SG 312381	Soil	1	12	6.48	3.8	83	<0.5
SG 312382	Soil	1	22	1.57	1.9	65	1.4
SG 312383	Soil	1	26	1.11	2.8	131	0.9
SG 312384	Soil	1	24	1.50	1.9	101	0.7
SG 312385	Soil	1	15	2.06	1.1	47	1.2
SG 312386	Soil	1	23	2.76	2.0	122	1.0
SG 312387	Soil	1	17	0.34	1.8	85	1.1
SG 312388	Soil	1	14	1.04	1.4	130	0.9
SG 312389	Soil	1	15	0.61	2.3	83	<0.5
SG 312390	Soil	1	17	0.38	1.5	84	1.8
SG 312391	Soil	1	21	1.00	3.5	121	0.7
SG 312392	Soil	1	25	0.27	3.6	123	0.6
SG 312393	Soil	1	26	0.32	2.9	118	<0.5
SG 312394	Soil	2	22	0.83	3.0	146	0.6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SG 312395	Soil	1	12	1.56	0.8	32	1.4
SG 312396	Soil	1	14	1.02	1.8	32	<0.5
SG 312397	Soil	1	20	1.38	3.6	117	0.8
SG 312398	Soil	1	8	1.85	1.8	105	<0.5
SG 312399	Soil	1	11	2.02	1.5	91	<0.5
SG 312400	Soil	1	8	1.11	1.9	113	1.2
SG 312401	Soil	0	14	0.33	0.7	29	<0.5
SG 312402	Soil	1	11	1.62	1.8	110	<0.5
SG 312403	Soil	1	7	1.83	1.9	114	<0.5
SG 312404	Soil	2	8	1.33	2.2	136	0.6
SG 312405	Soil	1	8	0.59	1.9	115	<0.5
SG 312406	Soil	2	8	0.54	2.1	138	3.3
SG 312407	Soil	1	12	1.74	3.2	118	<0.5
SG 312408	Soil	1	9	21.63	3.2	162	<0.5
SG 312409	Soil	1	18	2.86	2.0	126	<0.5
SG 312410	Soil	1	19	1.97	2.8	147	1.0
SG 312411	Soil	1	19	1.16	3.2	124	0.6
SG 312412	Soil	1	16	1.56	4.5	89	0.7
SG 312413	Soil	1	11	1.89	1.7	103	0.9
SG 312414	Soil	1	19	43.16	1.2	45	<0.5
SG 312415	Soil	1	5	3.54	1.9	112	<0.5
SG 312416	Soil	2	18	0.75	2.4	102	<0.5
SG 312417	Soil	1	14	1.18	6.8	121	<0.5
SG 312418	Soil	1	12	1.28	5.4	141	2.0
SG 312419	Soil	1	12	0.99	6.1	134	1.1
SG 312420	Soil	1	14	0.81	8.9	99	1.1
SG 312421	Soil	1	14	1.04	9.3	99	1.2
SG 312422	Soil	1	14	1.64	9.4	97	1.2
SG 312423	Soil	1	11	0.48	2.2	80	<0.5
SG 312424	Soil	1	21	1.15	1.6	106	1.2
SG 312425	Soil	1	23	1.05	1.7	118	1.7
SG 312426	Soil	2	21	1.27	1.3	110	1.1
SG 312427	Soil	1	25	0.59	2.1	132	1.1
SG 312428	Soil	1	20	1.20	1.4	116	1.4
SG 312429	Soil	2	18	1.48	3.8	123	<0.5
SG 312430	Soil	2	23	1.17	2.0	123	0.6
SG 312431	Soil	1	24	1.71	2.0	143	0.8
SG 312432	Soil	1	21	1.09	1.2	82	1.4
SG 312433	Soil	1	24	1.09	1.7	91	2.3
SG 312434	Soil	1	18	1.80	3.9	114	1.3

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 480501	Soil	1	12	1.58	2.1	100	<0.5
SI 480502	Soil	2	42	1.68	4.8	83	1.9
SI 480503	Soil	1	10	2.85	1.9	102	1.0
SI 480504	Soil	2	10	2.37	2.5	129	<0.5
SI 480505	Soil	1	19	0.99	1.4	101	<0.5
SI 480506	Soil	1	21	2.97	1.5	75	<0.5
SI 480507	Soil	1	30	2.03	2.0	102	<0.5
SI 480508	Soil	1	31	2.02	2.0	57	<0.5
SI 480509	Soil	1	17	1.00	4.0	69	<0.5
SI 480510	Soil	1	23	1.68	2.3	139	<0.5
SI 480511	Soil	2	10	3.24	2.1	115	<0.5
SI 480512	Soil	1	8	0.41	1.7	99	0.7
SI 480513	Soil	1	8	1.65	1.0	34	<0.5
SI 480514	Soil	1	7	1.36	1.2	110	2.0
SI 480515	Soil	2	16	1.64	2.1	121	<0.5
SI 480516	Soil	1	7	2.09	1.9	128	0.9
SI 480517	Soil	2	7	1.29	2.9	145	<0.5
SI 480518	Soil	1	15	1.38	0.9	51	<0.5
SI 480519	Soil	2	11	1.34	2.3	202	<0.5
SI 480520	Soil	1	13	2.09	4.1	93	<0.5
SI 480521	Soil	1	6	1.81	4.0	65	<0.5
SI 480522	Soil	1	15	2.87	3.3	106	0.8
SI 480523	Soil	1	20	6.16	3.6	98	0.9
SI 480524	Soil	1	18	1.10	3.8	144	<0.5
SI 480525	Soil	1	7	1.72	2.6	99	<0.5
SI 480526	Soil	1	22	1.02	2.9	131	<0.5
SI 480551	Soil	1	12	1.84	1.5	133	<0.5
SI 480552	Soil	2	17	1.89	3.4	166	<0.5
SI 480553	Soil	2	20	2.45	4.2	137	<0.5
SI 480554	Soil	2	13	1.01	4.4	137	<0.5
SI 480555	Soil	1	10	1.59	1.5	30	<0.5
SI 480556	Soil	1	12	2.35	2.6	207	<0.5
SI 480557	Soil	2	10	2.34	4.2	247	<0.5
SI 480558	Soil	0	10	2.68	1.7	27	0.7
SI 480559	Soil	1	5	1.47	5.0	176	<0.5
SI 480560	Soil	1	7	0.57	3.5	44	0.6
SI 480561	Soil	1	9	2.37	2.7	132	<0.5
SI 480562	Soil	1	19	0.28	3.0	126	2.7
SI 480563	Soil	1	24	1.18	4.4	128	0.8
SI 480564	Soil	1	9	2.44	2.2	125	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 480565	Soil	1	24	1.90	3.3	97	0.7
SI 480566	Soil	1	18	3.42	3.8	115	0.8
SI 480567	Soil	1	21	3.22	4.8	96	<0.5
SI 480568	Soil	2	25	2.02	4.1	99	<0.5
SI 480569	Soil	2	11	2.35	10.2	74	1.8
SI 480570	Soil	2	11	1.35	11.8	75	1.8
SI 480571	Soil	1	13	1.17	8.1	91	2.2
SI 480572	Soil	1	22	0.47	2.0	61	<0.5
SI 480573	Soil	1	15	0.29	2.1	71	0.7
SI 480574	Soil	1	13	1.38	3.8	90	0.6
SI 480575	Soil	2	10	2.36	5.0	68	1.0
SI 480576	Soil	2	11	1.55	4.0	77	1.2
SI 480577	Soil	2	15	7.61	2.6	115	<0.5
SI 480578	Soil	1	12	1.99	3.0	67	0.6
SI 480579	Soil	1	17	3.00	1.7	84	<0.5
SI 480580	Soil	2	15	2.38	5.8	92	0.8
SI 480581	Soil	1	12	1.58	1.4	37	<0.5
SI 480582	Soil	0	18	1.32	1.3	26	<0.5
SI 480583	Soil	1	17	3.12	1.1	28	<0.5
SI 480584	Soil	1	18	1.68	2.2	71	0.8
SI 480585	Soil	1	19	3.54	3.9	102	<0.5
SI 480586	Soil	2	20	3.91	3.5	117	<0.5
SI 480587	Soil	1	21	2.37	2.4	74	<0.5
SI 480588	Soil	1	8	3.22	2.3	24	<0.5
SI 480589	Soil	1	21	2.84	1.6	76	<0.5
SI 480590	Soil	1	15	8.96	1.8	33	<0.5
SI 484680	Soil	1	14	7.92	3.0	67	<0.5
SI 484681	Soil	3	9	4.95	3.5	84	<0.5
SI 484682	Soil	3	10	5.77	3.1	116	<0.5
SI 484683	Soil	2	12	9.61	3.2	110	<0.5
SI 484684	Soil	2	12	5.59	3.5	105	<0.5
SI 484685	Soil	2	13	4.18	3.4	128	<0.5
SI 484686	Soil	2	12	2.72	2.5	131	<0.5
SI 484687	Soil	1	71	2.76	5.8	114	<0.5
SI 484688	Soil	2	14	5.42	3.0	95	<0.5
SI 484689	Soil	2	13	6.57	4.0	101	<0.5
SI 484690	Soil	3	15	4.53	4.4	100	<0.5
SI 484691	Soil	1	13	4.38	1.7	69	<0.5
SI 484692	Soil	2	16	2.65	3.4	119	<0.5
SI 484693	Soil	2	9	7.77	3.0	137	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 484694	Soil	1	8	2.25	3.0	180	<0.5
SI 484695	Soil	1	20	3.32	3.2	122	<0.5
SI 484696	Soil	2	16	4.33	3.4	98	<0.5
SI 484697	Soil	2	17	5.57	4.0	104	<0.5
SI 484698	Soil	2	12	2.57	3.6	124	<0.5
SI 484699	Soil	2	23	5.54	4.7	126	0.7
SI 484700	Soil	2	14	5.80	3.5	110	<0.5
SI 484701	Soil	2	8	3.19	2.8	136	<0.5
SI 484702	Soil	1	22	3.06	2.0	82	<0.5
SI 484703	Soil	1	18	2.29	1.7	70	<0.5
SI 484704	Soil	1	15	2.66	2.9	104	<0.5
SI 484705	Soil	1	14	1.68	3.4	112	<0.5
SI 484706	Soil	1	15	1.17	3.4	108	<0.5
SI 484707	Soil	1	16	1.43	3.4	118	<0.5
SI 484708	Soil	2	23	1.31	4.0	185	<0.5
SI 484709	Soil	1	25	0.71	2.3	79	<0.5
SI 484710	Soil	1	22	1.03	2.2	75	<0.5
SI 484711	Soil	1	25	0.57	2.2	69	<0.5
SI 484712	Soil	2	16	0.79	3.2	100	<0.5
SI 484713	Soil	1	17	1.51	1.9	59	<0.5
SI 484714	Soil	1	17	2.71	2.5	75	<0.5
SI 484715	Soil	2	16	1.42	3.1	120	<0.5
SI 484716	Soil	2	18	1.50	3.2	168	<0.5
SI 484717	Soil	1	13	0.94	2.5	74	<0.5
SI 484718	Soil	1	13	1.61	3.0	102	<0.5
SI 484719	Soil	2	25	1.73	2.9	169	<0.5
SI 484720	Soil	2	15	2.02	3.2	170	<0.5
SI 484721	Soil	2	13	5.81	2.8	122	<0.5
SI 484722	Soil	2	57	0.78	6.4	128	2.8
SI 484723	Soil	0	22	0.49	0.4	10	<0.5
SI 484724	Soil	1	18	1.96	1.9	64	<0.5
SI 484725	Soil	2	12	2.00	3.4	101	<0.5
SI 484726	Soil	1	13	1.85	1.7	73	<0.5
SI 484727	Soil	1	11	2.44	1.6	138	<0.5
SI 484728	Soil	1	15	2.45	1.9	125	<0.5
SI 484729	Soil	1	14	2.74	1.9	125	<0.5
SI 484730	Soil	1	15	2.21	3.1	69	<0.5
SI 484731	Soil	2	15	3.44	3.1	163	<0.5
SI 484732	Soil	2	13	1.46	3.6	195	<0.5
SI 484733	Soil	1	15	1.00	3.1	115	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 484734	Soil	1	17	0.76	2.1	111	<0.5
SI 484735	Soil	1	20	3.01	1.7	65	<0.5
SI 484736	Soil	1	14	0.41	1.0	26	1.0
SI 484737	Soil	1	15	0.36	1.2	46	1.8
SI 484738	Soil	1	16	0.58	1.3	29	0.6
SI 484739	Soil	1	20	0.77	1.6	72	1.2
SI 484740	Soil	1	12	1.06	3.3	84	1.0
SI 484741	Soil	1	19	0.66	6.4	129	1.5
SI 484742	Soil	1	20	1.06	5.2	71	0.5
SI 484743	Soil	1	22	0.65	4.6	127	1.1
SI 484744	Soil	1	18	0.59	1.8	95	1.0
SI 484745	Soil	1	21	0.43	2.1	120	2.4
SI 484746	Soil	1	18	0.42	1.4	56	3.1
SI 484747	Soil	2	14	0.45	3.8	71	2.1
SI 484748	Soil	1	9	0.31	0.8	10	<0.5
SI 484749	Soil	1	14	0.66	4.0	159	1.0
SI 484750	Soil	1	15	0.75	3.8	151	4.0
SI 484751	Soil	2	13	0.63	5.1	153	1.6
SI 484752	Soil	1	12	0.61	6.6	117	1.1
SI 484753	Soil	1	10	0.74	1.5	46	1.5
SI 484754	Soil	2	15	0.33	6.4	72	<0.5
SI 484755	Soil	2	20	0.35	3.0	121	1.1
SI 484756	Soil	5	11	0.97	10.2	57	3.7
SI 484757	Soil	1	4	0.94	1.6	142	1.4
SI 484758	Soil	5	9	0.47	6.6	32	3.2
SI 484759	Soil	1	14	0.63	3.9	118	<0.5
SI 484760	Soil	1	17	0.68	4.4	120	0.5
SI 484761	Soil	1	8	0.42	2.9	60	2.8
SI 484762	Soil	1	19	0.67	1.6	118	<0.5
SI 484763	Soil	1	14	0.59	1.2	92	1.5
SI 484764	Soil	1	9	0.52	1.9	74	<0.5
SI 484765	Soil	1	11	0.76	1.5	82	<0.5
SI 484766	Soil	0	6	0.35	0.1	2	<0.5
SI 484767	Soil	1	31	0.57	1.6	49	<0.5
SI 484768	Soil	1	9	0.58	1.5	83	<0.5
SI 484769	Soil	1	9	0.79	1.5	106	<0.5
SI 484770	Soil	1	14	1.17	1.4	70	<0.5
SI 484771	Soil	1	10	0.63	1.4	75	<0.5
SI 484772	Soil	2	9	1.22	2.1	143	0.7
SI 484773	Soil	1	6	0.72	2.2	156	<0.5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 484774	Soil	1	17	2.08	2.1	119	0.6
SI 484775	Soil	1	16	2.50	2.6	99	0.6
SI 484776	Soil	1	21	0.76	2.6	142	1.3
SI 484777	Soil	1	21	0.55	2.8	132	1.0
SI 484778	Soil	1	11	1.99	1.3	50	0.9
SI 484779	Soil	1	12	0.69	4.7	101	1.1
SI 484780	Soil	1	16	1.51	2.7	105	<0.5
SI 484781	Soil	1	17	1.13	2.0	63	<0.5
SI 484782	Soil	1	18	1.37	2.3	81	<0.5
SI 484783	Soil	2	12	1.62	2.7	93	<0.5
SI 484784	Soil	1	13	0.64	9.9	106	1.0
SI 484785	Soil	1	19	0.44	3.1	116	<0.5
SI 484786	Soil	1	19	0.89	1.7	91	1.7
SI 484787	Soil	1	19	0.93	2.1	103	0.6
SI 484788	Soil	1	17	0.51	3.5	98	1.0
SI 484789	Soil	2	25	0.50	2.9	132	4.4
SI 484790	Soil	1	18	0.81	1.5	59	2.3
SI 484791	Soil	1	16	0.91	1.1	32	1.5
SI 484792	Soil	1	19	0.46	1.9	114	1.7
SI 484793	Soil	1	22	0.54	4.6	115	0.9
SI 484794	Soil	1	21	0.59	2.4	124	0.9
SI 484795	Soil	2	22	0.52	3.7	112	1.0
SI 484796	Soil	0	17	0.51	1.4	81	3.1
SI 484797	Soil	1	26	0.67	6.2	131	0.6
SI 484798	Soil	1	25	0.62	3.7	92	2.9
SI 484799	Soil	1	15	0.60	1.4	53	2.8
SI 484800	Soil	1	21	0.67	1.6	126	1.4

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
QCV1008-01111-0001-BLK			<0.01	<0.1	<5	<0.05	0.04	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2	<0.01
SG 312315	Soil		0.74	157.0	31	0.4	0.47	0.04	0.35	33.78	29.3	<1	1.3	51.3	4.80
SG 312315 Dup			0.75	160.3	31	0.4	0.46	0.04	0.35	34.89	29.9	<1	1.3	51.7	4.88
STD-ME-6 expected														6130.0	
STD-ME-6 result			1.04	269.8	95	0.2	5.86	0.55	32.16	9.09	25.3	<1	0.4	5789.3	5.27
SG 312333	Soil		0.46	243.0	29	0.3	0.43	0.01	0.53	27.28	18.3	<1	2.0	39.0	3.30
SG 312333 Dup			0.48	240.5	30	0.3	0.43	0.01	0.53	28.32	17.9	<1	2.0	38.4	3.27
STD-ME-6 expected														6130.0	
STD-ME-6 result			0.99	268.4	91	0.2	5.89	0.52	31.93	8.98	17.1	<1	0.4	5665.1	5.02
SG 312351	Soil		0.31	351.4	28	0.3	0.29	0.02	0.80	24.12	11.8	<1	1.9	26.2	2.08
SG 312351 Dup			0.34	350.8	28	0.2	0.28	0.02	0.79	24.56	11.8	<1	1.9	26.4	2.29
STD-ME-6 expected														6130.0	
STD-ME-6 result			1.08	285.2	92	0.3	5.95	0.58	32.86	9.89	19.5	<1	0.4	5888.3	5.21
SG 312369	Soil		1.34	14.2	30	0.6	0.36	0.16	0.07	20.76	23.9	<1	1.1	48.2	3.55
SG 312369 Dup			1.41	14.1	29	0.6	0.34	0.17	0.08	20.19	23.4	<1	1.1	46.9	3.81
STD-ME-6 expected														6130.0	
STD-ME-6 result			1.14	257.3	89	0.2	5.93	0.58	31.89	9.33	26.7	<1	0.4	6287.8	5.44
SG 312387	Soil		1.62	57.3	31	0.4	0.31	0.03	0.07	25.11	12.0	<1	1.8	34.0	3.50
SG 312387 Dup			1.62	57.6	32	0.4	0.31	0.03	0.07	25.37	11.6	<1	1.8	35.2	3.57
STD-OREAS-45P-AR expected				4.4			0.18		0.09		107.0	892		674.0	
STD-OREAS-45P-AR result			3.57	6.2	173	0.7	0.16	0.25	0.09	32.70	108.8	941	1.1	674.6	>10
SG 312405	Soil		0.45	167.9	31	0.5	0.49	0.01	0.21	23.83	18.3	<1	4.0	48.7	3.83
SG 312405 Dup			0.48	166.5	32	0.5	0.49	0.01	0.19	23.87	18.2	<1	4.1	48.0	3.98
STD-OREAS-45P-AR expected				4.4			0.18		0.09		107.0	892		674.0	
STD-OREAS-45P-AR result			3.74	4.4	174	0.7	0.17	0.25	0.12	34.32	110.3	941	1.2	693.6	>10
SG 312423	Soil		1.04	53.3	35	0.3	0.41	0.02	0.05	43.93	15.8	<1	2.2	34.0	3.40
SG 312423 Dup			1.01	54.0	36	0.3	0.44	0.01	0.05	44.57	15.5	<1	2.2	35.0	3.06
STD-OREAS-45P-AR expected				4.4			0.18		0.09		107.0	892		674.0	
STD-OREAS-45P-AR result			3.62	5.0	176	0.7	0.17	0.25	0.11	33.47	117.3	943	1.1	696.3	>10
SI 480507	Soil		0.43	533.2	41	0.2	0.33	0.04	0.32	29.27	12.5	<1	1.2	26.2	2.79
SI 480507 Dup			0.39	528.9	39	0.2	0.33	0.04	0.33	29.54	13.1	<1	1.2	25.8	2.55
STD-ME-6 expected														6130.0	
STD-ME-6 result			1.17	248.4	87	0.2	5.21	0.62	29.08	9.35	24.1	<1	0.4	6164.1	5.44
SI 480525	Soil		0.50	193.2	20	0.4	0.30	0.10	0.22	39.58	18.4	<1	1.6	46.1	3.48
SI 480525 Dup			0.56	192.1	20	0.3	0.31	0.11	0.22	39.55	19.3	<1	1.6	47.4	3.76
STD-OREAS-45P-AR expected				4.4			0.18		0.09		107.0	892		674.0	
STD-OREAS-45P-AR result			2.96	5.0	177	0.7	0.16	0.22	0.09	33.94	115.0	807	1.0	592.4	>10
SI 480567	Soil		1.14	95.7	36	0.5	0.23	0.11	0.20	29.61	19.3	<1	0.6	39.7	3.60
SI 480567 Dup			1.05	94.0	36	0.5	0.24	0.09	0.20	29.57	19.8	<1	0.6	39.2	3.28
STD-OREAS-45P-AR expected				4.4			0.18		0.09		107.0	892		674.0	
STD-OREAS-45P-AR result			2.78	4.6	160	0.6	0.16	0.21	0.08	31.70	100.2	774	0.9	567.8	>10

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SI 480585	Soil		0.45	214.9	29	0.4	0.34	0.01	0.29	32.51	18.4	<1	1.5	35.5	3.32
SI 480585 Dup			0.44	212.4	29	0.4	0.34	0.01	0.29	32.10	18.1	<1	1.5	34.2	3.12
STD-ME-6 expected														6130.0	
STD-ME-6 result			1.11	268.2	78	0.2	5.49	0.57	31.82	8.80	19.0	<1	0.4	6200.7	5.47
SI 484692	Soil		0.64	738.5	30	0.3	0.35	0.03	0.41	25.13	19.8	<1	2.4	30.6	3.61
SI 484692 Dup			0.66	725.4	29	0.3	0.34	0.03	0.41	26.54	20.8	<1	2.4	30.1	3.79
STD-ME-6 expected														6130.0	
STD-ME-6 result			1.02	245.6	78	0.2	5.34	0.54	30.00	8.70	18.6	<1	0.4	5589.1	4.95
SI 484710	Soil		0.55	148.0	17	0.2	0.36	<0.01	0.12	26.73	11.4	<1	0.7	29.2	2.88
SI 484710 Dup			0.56	144.3	18	0.2	0.35	<0.01	0.13	26.54	10.8	<1	0.7	28.0	2.73
STD-OREAS-45P-AR expected				4.4			0.18		0.09		107.0	892		674.0	
STD-OREAS-45P-AR result			3.59	5.0	212	0.7	0.19	0.24	0.11	38.60	123.0	923	1.5	679.8	>10
SI 484728	Soil		0.31	954.8	23	0.2	0.33	0.01	0.32	25.62	9.9	<1	1.0	26.9	2.74
SI 484728 Dup			0.30	945.7	24	0.2	0.33	0.01	0.33	26.04	10.1	<1	1.0	27.5	2.57
STD-OREAS-45P-AR expected				4.4			0.18		0.09		107.0	892		674.0	
STD-OREAS-45P-AR result			2.93	6.1	203	0.7	0.19	0.21	0.11	36.04	108.7	792	1.3	572.3	>10
SI 484746	Soil		1.31	20.2	33	0.3	0.39	0.01	0.08	21.36	7.2	<1	3.3	34.7	3.29
SI 484746 Dup			1.30	19.2	34	0.3	0.39	0.01	0.09	22.14	7.8	<1	3.3	35.1	3.25
STD-ME-6 expected														6130.0	
STD-ME-6 result			1.04	248.9	91	0.2	5.57	0.54	31.85	8.88	14.9	<1	0.4	5811.3	5.14
SI 484764	Soil		0.50	188.9	33	0.3	0.42	0.02	0.30	18.87	9.9	<1	2.7	32.1	2.73
SI 484764 Dup			0.50	202.9	33	0.3	0.43	0.02	0.31	19.32	10.2	<1	2.8	33.3	2.57
STD-OREAS-45P-AR expected				4.4			0.18		0.09		107.0	892		674.0	
STD-OREAS-45P-AR result			2.90	6.3	221	0.7	0.19	0.21	0.13	39.89	123.8	791	1.4	576.1	>10
STD-ME-6 expected														6130.0	
STD-ME-6 result			0.40	317.1	26	0.2	0.33	0.03	0.11	30.74	9.9	<1	1.6	31.0	2.83
SI 484782	Soil		0.44	325.5	25	0.2	0.33	0.03	0.11	31.32	10.1	<1	1.7	30.1	2.87
SI 484782 Dup			1.18	262.6	109	0.3	5.51	0.63	34.45	10.58	13.4	<1	0.4	6172.8	5.42
STD-OREAS-45P-AR expected				4.4			0.18		0.09		107.0	892		674.0	
STD-OREAS-45P-AR result			3.14	5.3	212	0.7	0.18	0.23	0.12	39.55	116.6	850	1.3	632.1	>10
SI 484800	Soil		2.59	20.5	30	0.3	0.45	0.03	0.07	21.73	22.5	34	4.5	42.6	5.22
SI 484800 Dup			2.61	20.0	30	0.3	0.44	0.03	0.07	22.60	22.0	31	4.6	42.4	5.45
QCV1008-01111-0038-BLK			<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05	<0.2	<0.01
STD-DS-1 expected			4.48	6930.0	221						9.5			27.1	
STD-DS-1 result			0.39	7025.6	35	0.5	0.07	5.75	1.27	23.76	10.4	21	2.1	29.4	2.83
SG 312315	Soil	0.026													
SG 312315 Dup		0.019													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.712													
SG 312333	Soil	0.057													
SG 312333 Dup		0.065													

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
QCV1008-01112-0004-BLK		<0.005													
SG 312351	Soil	0.049													
SG 312351 Dup		0.055													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.701													
SG 312369	Soil	<0.005													
SG 312369 Dup		<0.005													
QCV1008-01112-0008-BLK		<0.005													
SG 312387	Soil	0.010													
SG 312387 Dup		0.013													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.711													
SG 312405	Soil	0.046													
SG 312405 Dup		0.047													
QCV1008-01112-0012-BLK		<0.005													
SG 312423	Soil	0.012													
SG 312423 Dup		0.012													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.633													
SI 480507	Soil	0.111													
SI 480507 Dup		0.140													
QCV1008-01112-0016-BLK		<0.005													
SI 480525	Soil	0.051													
SI 480525 Dup		0.051													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.664													
SI 480567	Soil	0.042													
SI 480567 Dup		0.050													
QCV1008-01112-0020-BLK		<0.005													
SI 480585	Soil	0.034													
SI 480585 Dup		0.038													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.634													
SI 484692	Soil	0.331													
SI 484692 Dup		0.268													
QCV1008-01112-0024-BLK		<0.005													
SI 484710	Soil	0.006													
SI 484710 Dup		0.006													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.670													

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-AA g/ton 0.005	Al 50-AR-UT % 0.01	As 50-AR-UT ppm 0.1	Ba 50-AR-UT ppm 5	Be 50-AR-UT ppm 0.05	Bi 50-AR-UT ppm 0.01	Ca 50-AR-UT % 0.01	Cd 50-AR-UT ppm 0.01	Ce 50-AR-UT ppm 0.02	Co 50-AR-UT ppm 0.1	Cr 50-AR-UT ppm 1	Cs 50-AR-UT ppm 0.05	Cu 50-AR-UT ppm 0.2	Fe 50-AR-UT % 0.01
SI 484728	Soil	0.122													
SI 484728 Dup		0.135													
QCV1008-01112-0028-BLK		<0.005													
SI 484746	Soil	<0.005													
SI 484746 Dup		0.007													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.598													
SI 484764	Soil	0.042													
SI 484764 Dup		0.044													
QCV1008-01112-0032-BLK		<0.005													
SI 484782	Soil	0.034													
SI 484782 Dup		0.036													
STD-Oxi67 expected		1.817													
STD-Oxi67 result		1.616													
SI 484800	Soil	0.006													
SI 484800 Dup		<0.005													

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Ga	Ge	Hf	In	K	La	Li	Mg	Mn	Mo	Na	Nb	Ni	P
		50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample Description	Sample Type	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%	ppm	ppm	ppm
		0.05	0.05	0.02	0.01	0.01	0.2	0.1	0.01	1	0.05	0.01	0.05	0.2	5
QCV1008-01111-0001-BLK		<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2	<5
SG 312315	Soil	2.7	<0.05	<0.02	0.03	0.02	18.5	16.8	0.21	1285	0.82	<0.01	0.2	46.2	708
SG 312315 Dup		2.7	<0.05	<0.02	0.03	0.02	18.4	16.5	0.21	1289	0.84	<0.01	0.2	47.7	765
STD-ME-6 expected															
STD-ME-6 result		4.2	0.1	0.14	0.45	0.09	4.2	9.8	0.73	1665	20.66	0.06	0.2	31.1	556
SG 312333	Soil	1.9	<0.05	<0.02	0.04	0.02	14.5	11.4	0.14	446	0.82	<0.01	0.1	34.9	306
SG 312333 Dup		1.9	<0.05	<0.02	0.04	0.02	14.6	11.6	0.14	437	0.81	<0.01	0.1	34.7	318
STD-ME-6 expected															
STD-ME-6 result		4.1	0.1	0.15	0.44	0.08	4.1	9.7	0.71	1603	22.00	0.05	0.2	30.4	609
SG 312351	Soil	1.2	<0.05	<0.02	0.05	0.02	12.6	5.7	0.07	240	0.53	<0.01	0.1	13.8	397
SG 312351 Dup		1.2	<0.05	<0.02	0.05	0.02	12.7	5.6	0.07	271	0.54	<0.01	0.1	13.6	487
STD-ME-6 expected															
STD-ME-6 result		4.5	<0.05	0.14	0.49	0.09	4.7	10.6	0.77	1638	23.62	0.06	0.2	33.3	394
SG 312369	Soil	4.1	<0.05	<0.02	0.02	0.02	10.8	47.8	0.70	646	0.47	<0.01	<0.05	43.0	440
SG 312369 Dup		4.1	<0.05	<0.02	0.02	0.02	11.1	46.3	0.73	696	0.47	<0.01	<0.05	42.6	472
STD-ME-6 expected															
STD-ME-6 result		4.3	<0.05	0.15	0.47	0.09	4.3	10.0	0.79	1690	22.30	0.06	0.2	31.0	372
SG 312387	Soil	5.0	<0.05	<0.02	0.02	0.02	12.2	45.1	0.57	345	0.39	0.01	0.2	30.9	294
SG 312387 Dup		5.1	<0.05	<0.02	0.02	0.02	12.3	46.7	0.58	352	0.40	0.01	0.2	31.7	427
STD-OREAS-45P-AR expected														292.0	
STD-OREAS-45P-AR result		16.2	0.1	0.46	0.08	0.08	15.2	7.0	0.13	1251	1.43	0.02	0.4	303.9	331
SG 312405	Soil	1.3	<0.05	<0.02	0.03	0.03	12.6	4.6	0.06	383	1.15	<0.01	0.1	28.5	346
SG 312405 Dup		1.4	<0.05	<0.02	0.03	0.03	12.7	4.6	0.06	397	1.17	<0.01	0.1	28.3	299
STD-OREAS-45P-AR expected														292.0	
STD-OREAS-45P-AR result		16.2	0.1	0.43	0.09	0.08	15.0	7.5	0.14	1312	1.34	0.02	0.3	303.3	452
SG 312423	Soil	3.0	<0.05	<0.02	0.02	0.02	26.8	28.3	0.36	532	0.48	<0.01	<0.05	27.3	571
SG 312423 Dup		3.2	<0.05	<0.02	0.01	0.02	27.6	29.4	0.35	477	0.49	<0.01	<0.05	27.8	364
STD-OREAS-45P-AR expected														292.0	
STD-OREAS-45P-AR result		16.6	0.1	0.47	0.09	0.08	15.2	7.0	0.13	1284	1.54	0.02	0.5	312.4	433
SI 480507	Soil	3.7	<0.05	<0.02	0.03	0.04	14.7	0.9	0.03	144	1.04	<0.01	0.5	16.2	767
SI 480507 Dup		3.8	<0.05	<0.02	0.03	0.04	14.8	0.9	0.03	132	1.05	<0.01	0.6	15.8	673
STD-ME-6 expected															
STD-ME-6 result		4.0	<0.05	0.17	0.43	0.10	4.2	10.1	0.81	1678	20.34	0.06	0.2	28.8	432
SI 480525	Soil	1.5	<0.05	<0.02	0.02	0.03	19.2	12.8	0.20	946	0.60	<0.01	<0.05	28.9	464
SI 480525 Dup		1.6	<0.05	<0.02	0.02	0.03	19.6	13.1	0.22	999	0.59	<0.01	<0.05	29.9	542
STD-OREAS-45P-AR expected														292.0	
STD-OREAS-45P-AR result		15.7	0.1	0.50	0.09	0.07	15.3	6.4	0.11	1047	1.43	0.01	0.6	293.7	358
SI 480567	Soil	3.3	<0.05	<0.02	0.02	0.02	13.5	42.6	0.64	770	0.41	<0.01	0.3	46.0	713
SI 480567 Dup		3.2	<0.05	<0.02	0.02	0.02	13.9	42.3	0.60	719	0.40	<0.01	0.3	45.5	603
STD-OREAS-45P-AR expected														292.0	
STD-OREAS-45P-AR result		14.1	0.1	0.43	0.08	0.06	14.1	5.5	0.11	1054	1.35	0.02	0.5	261.3	294

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ga 50-AR-UT ppm 0.05	Ge 50-AR-UT ppm 0.05	Hf 50-AR-UT ppm 0.02	In 50-AR-UT ppm 0.01	K 50-AR-UT % 0.01	La 50-AR-UT ppm 0.2	Li 50-AR-UT ppm 0.1	Mg 50-AR-UT % 0.01	Mn 50-AR-UT ppm 1	Mo 50-AR-UT ppm 0.05	Na 50-AR-UT % 0.01	Nb 50-AR-UT ppm 0.05	Ni 50-AR-UT ppm 0.2	P 50-AR-UT ppm 5
SI 480585	Soil	1.8	<0.05	<0.02	0.03	0.02	18.2	9.7	0.12	347	0.70	<0.01	0.1	33.1	410
SI 480585 Dup		1.7	<0.05	<0.02	0.03	0.02	18.1	9.5	0.12	326	0.70	<0.01	0.1	31.7	401
STD-ME-6 expected															
STD-ME-6 result		4.0	0.1	0.15	0.42	0.09	4.1	10.2	0.78	1677	21.00	0.06	0.2	29.9	251
SI 484692	Soil	2.3	<0.05	<0.02	0.03	0.03	12.1	13.6	0.21	631	0.79	<0.01	0.3	30.4	484
SI 484692 Dup		2.2	<0.05	<0.02	0.03	0.03	12.4	13.3	0.22	668	0.78	<0.01	0.3	30.4	492
STD-ME-6 expected															
STD-ME-6 result		3.7	0.1	0.16	0.39	0.09	4.0	9.9	0.73	1543	20.03	0.05	0.2	26.9	383
SI 484710	Soil	4.2	<0.05	<0.02	0.02	0.02	14.4	4.2	0.07	212	0.74	<0.01	0.2	22.8	592
SI 484710 Dup		4.2	<0.05	<0.02	0.02	0.02	14.3	4.4	0.07	203	0.74	<0.01	0.2	22.5	530
STD-OREAS-45P-AR expected														292.0	
STD-OREAS-45P-AR result		19.2	0.1	0.54	0.11	0.08	17.7	6.9	0.13	1255	1.85	0.02	0.7	325.7	375
SI 484728	Soil	2.4	<0.05	<0.02	0.04	0.02	13.8	2.8	0.05	169	0.75	<0.01	0.2	19.5	272
SI 484728 Dup		2.5	<0.05	<0.02	0.04	0.01	14.0	2.9	0.05	158	0.74	<0.01	0.2	19.2	317
STD-OREAS-45P-AR expected														292.0	
STD-OREAS-45P-AR result		18.1	0.1	0.53	0.10	0.07	16.8	6.3	0.11	1010	1.69	0.01	0.6	306.2	311
SI 484746	Soil	5.7	<0.05	0.10	0.03	0.02	11.9	31.8	0.38	419	0.60	<0.01	0.3	20.2	983
SI 484746 Dup		5.9	<0.05	0.10	0.03	0.02	12.0	31.3	0.38	411	0.60	<0.01	0.3	20.8	924
STD-ME-6 expected															
STD-ME-6 result		4.0	0.1	0.12	0.46	0.09	4.1	9.5	0.73	1624	21.39	0.06	0.2	28.9	402
SI 484764	Soil	2.1	<0.05	<0.02	0.03	0.02	11.3	6.3	0.08	215	1.09	<0.01	0.1	16.5	291
SI 484764 Dup		2.1	<0.05	<0.02	0.03	0.02	11.1	6.3	0.08	199	1.17	<0.01	0.1	16.5	296
STD-OREAS-45P-AR expected														292.0	
STD-OREAS-45P-AR result		20.0	0.1	0.54	0.12	0.07	18.7	6.6	0.11	1034	1.96	0.02	0.8	355.7	285
STD-ME-6 expected															
STD-ME-6 result		3.0	<0.05	<0.02	0.02	0.06	15.6	2.5	0.04	288	0.78	<0.01	0.3	21.9	663
SI 484782	Soil	3.0	<0.05	<0.02	0.02	0.07	16.3	2.6	0.05	299	0.76	<0.01	0.3	22.1	739
SI 484782 Dup		4.6	<0.05	0.19	0.49	0.10	4.7	10.2	0.82	1719	23.39	0.06	0.3	31.3	419
STD-OREAS-45P-AR expected														292.0	
STD-OREAS-45P-AR result		19.4	0.1	0.55	0.11	0.07	17.8	6.4	0.12	1095	1.95	0.02	0.7	327.4	225
SI 484800	Soil	7.9	<0.05	0.03	0.02	0.02	10.3	76.5	1.06	756	0.70	<0.01	<0.05	49.0	554
SI 484800 Dup		7.7	<0.05	0.03	0.02	0.02	10.3	76.5	1.07	794	0.65	<0.01	<0.05	48.5	564
QCV1008-01111-0038-BLK		<0.05	<0.05	<0.02	<0.01	<0.01	<0.2	<0.1	<0.01	<1	<0.05	<0.01	<0.05	<0.2	<5
STD-DS-1 expected									2.76	437				48.7	340
STD-DS-1 result		1.3	<0.05	0.08	0.06	0.12	11.7	2.2	2.23	466	4.56	<0.01	<0.05	51.1	235

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th	Ti	Tl
		50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT	50-AR-UT
Sample Description	Sample Type	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm
		0.2	0.1	0.01	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2	0.005	0.05
QCV1008-01111-0001-BLK		<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005	<0.05
SG 312315	Soil	57.5	3.3	<0.01	<0.01	0.99	1.7	0.2	0.2	18.9	<0.01	0.16	6	0.008	<0.05
SG 312315 Dup		56.2	3.3	<0.01	<0.01	0.99	1.8	0.2	0.2	18.1	<0.01	0.16	6	0.008	<0.05
STD-ME-6 expected		10200													
STD-ME-6 result		>10000	3.7	0.01	2.35	378.14	4.5	2.6	1.7	23.2	<0.01	1.45	1	0.091	0.21
SG 312333	Soil	139.3	2.9	<0.01	<0.01	3.41	2.1	0.4	0.3	22.9	<0.01	0.16	11	<0.005	<0.05
SG 312333 Dup		138.3	2.9	<0.01	<0.01	3.36	2.0	0.4	0.3	23.8	<0.01	0.16	11	<0.005	<0.05
STD-ME-6 expected		10200													
STD-ME-6 result		>10000	3.5	0.01	2.27	355.31	4.4	2.8	1.6	22.0	<0.01	1.65	1	0.086	0.20
SG 312351	Soil	163.6	2.5	<0.01	<0.01	1.91	1.3	0.5	0.3	49.8	<0.01	0.06	5	<0.005	<0.05
SG 312351 Dup		164.6	2.5	<0.01	<0.01	1.91	1.3	0.5	0.3	55.1	<0.01	0.07	5	<0.005	<0.05
STD-ME-6 expected		10200													
STD-ME-6 result		>10000	4.0	0.01	2.37	363.76	5.0	3.0	1.7	24.4	<0.01	1.39	1	0.106	0.21
SG 312369	Soil	16.8	2.5	<0.01	<0.01	<0.05	2.2	0.4	<0.2	12.5	<0.01	0.08	4	<0.005	<0.05
SG 312369 Dup		16.3	2.6	<0.01	<0.01	<0.05	2.2	0.4	<0.2	13.4	<0.01	0.08	4	<0.005	<0.05
STD-ME-6 expected		10200													
STD-ME-6 result		>10000	3.8	<0.01	2.47	381.89	4.4	2.9	1.7	25.9	<0.01	1.51	1	0.092	0.21
SG 312387	Soil	26.3	3.5	<0.01	<0.01	<0.05	1.2	0.3	<0.2	4.3	<0.01	0.06	2	<0.005	<0.05
SG 312387 Dup		25.2	3.8	<0.01	<0.01	<0.05	1.3	0.3	<0.2	4.5	<0.01	0.06	2	<0.005	<0.05
STD-OREAS-45P-AR expected		19.0				0.38									
STD-OREAS-45P-AR result		17.4	9.8	<0.01	0.01	<0.05	52.0	<0.2	1.6	14.5	<0.01	0.06	6	0.194	0.07
SG 312405	Soil	54.9	3.7	<0.01	<0.01	4.80	1.9	0.4	<0.2	12.9	<0.01	0.22	4	<0.005	<0.05
SG 312405 Dup		54.7	3.8	<0.01	<0.01	4.81	1.9	0.4	<0.2	13.6	<0.01	0.21	5	<0.005	<0.05
STD-OREAS-45P-AR expected		19.0				0.38									
STD-OREAS-45P-AR result		17.6	9.8	<0.01	0.01	<0.05	49.9	<0.2	1.5	15.1	<0.01	0.07	6	0.206	0.07
SG 312423	Soil	23.0	3.6	<0.01	<0.01	0.74	1.0	<0.2	<0.2	12.3	<0.01	0.08	3	<0.005	<0.05
SG 312423 Dup		24.1	3.6	<0.01	<0.01	0.74	1.0	<0.2	<0.2	11.8	<0.01	0.07	3	<0.005	<0.05
STD-OREAS-45P-AR expected		19.0				0.38									
STD-OREAS-45P-AR result		17.7	9.7	<0.01	0.01	<0.05	52.6	<0.2	1.6	15.4	<0.01	0.05	6	0.189	0.06
SI 480507	Soil	105.7	6.6	<0.01	0.07	1.83	0.3	0.3	0.6	12.3	<0.01	0.09	0	0.007	<0.05
SI 480507 Dup		105.1	6.7	<0.01	0.07	1.88	0.3	0.3	0.6	11.0	<0.01	0.10	0	0.007	<0.05
STD-ME-6 expected		10200													
STD-ME-6 result		>10000	3.6	<0.01	2.49	371.03	3.9	2.1	1.5	31.1	<0.01	1.42	1	0.092	0.19
SI 480525	Soil	49.9	2.0	<0.01	<0.01	1.47	1.3	<0.2	<0.2	21.3	<0.01	0.07	4	<0.005	<0.05
SI 480525 Dup		50.4	2.0	<0.01	<0.01	1.56	1.3	<0.2	<0.2	25.7	<0.01	0.06	4	<0.005	<0.05
STD-OREAS-45P-AR expected		19.0				0.38									
STD-OREAS-45P-AR result		19.1	8.8	<0.01	<0.01	<0.05	52.1	<0.2	1.5	12.3	<0.01	0.07	6	0.159	0.06
SI 480567	Soil	25.6	2.6	<0.01	<0.01	0.29	2.3	0.2	<0.2	11.6	<0.01	0.04	4	0.011	<0.05
SI 480567 Dup		25.7	2.7	<0.01	<0.01	0.31	2.2	<0.2	<0.2	10.7	<0.01	0.05	4	0.011	<0.05
STD-OREAS-45P-AR expected		19.0				0.38									
STD-OREAS-45P-AR result		16.4	7.8	<0.01	<0.01	<0.05	47.3	<0.2	1.5	12.0	<0.01	0.07	6	0.146	0.05

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Pb 50-AR-UT ppm 0.2	Rb 50-AR-UT ppm 0.1	Re 50-AR-UT ppm 0.01	S 50-AR-UT % 0.01	Sb 50-AR-UT ppm 0.05	Sc 50-AR-UT ppm 0.1	Se 50-AR-UT ppm 0.2	Sn 50-AR-UT ppm 0.2	Sr 50-AR-UT ppm 0.2	Ta 50-AR-UT ppm 0.01	Te 50-AR-UT ppm 0.01	Th 50-AR-UT ppm 0.2	Ti 50-AR-UT % 0.005	Tl 50-AR-UT ppm 0.05
SI 480585	Soil	72.4	2.4	<0.01	<0.01	2.46	2.0	0.3	0.3	55.1	<0.01	0.11	4	<0.005	<0.05
SI 480585 Dup		72.1	2.4	<0.01	<0.01	2.40	1.9	0.3	0.3	54.3	<0.01	0.10	4	<0.005	<0.05
STD-ME-6 expected		10200													
STD-ME-6 result		>10000	3.6	0.01	2.47	435.15	4.0	2.4	1.6	24.9	<0.01	1.50	1	0.083	0.19
SI 484692	Soil	166.2	5.4	<0.01	0.02	3.71	1.4	0.4	0.4	23.3	<0.01	0.06	4	0.010	0.06
SI 484692 Dup		169.4	5.4	<0.01	0.02	3.64	1.5	0.4	0.4	25.3	<0.01	0.06	4	0.011	0.06
STD-ME-6 expected		10200													
STD-ME-6 result		>10000	3.5	<0.01	2.29	394.27	3.5	2.6	1.5	22.5	<0.01	1.49	1	0.079	0.19
SI 484710	Soil	54.5	4.4	<0.01	0.03	0.54	0.2	0.4	0.3	3.7	<0.01	0.02	0	<0.005	<0.05
SI 484710 Dup		55.7	4.4	<0.01	0.03	0.55	0.2	0.3	0.3	4.2	<0.01	0.02	0	<0.005	<0.05
STD-OREAS-45P-AR expected		19.0				0.38									
STD-OREAS-45P-AR result		19.6	11.7	<0.01	0.01	<0.05	52.1	0.4	1.9	14.5	<0.01	0.09	7	0.192	0.08
SI 484728	Soil	226.0	3.1	<0.01	<0.01	2.92	0.6	0.2	0.3	13.3	<0.01	0.09	1	0.005	<0.05
SI 484728 Dup		213.5	3.1	<0.01	<0.01	2.92	0.5	0.3	0.3	13.4	<0.01	0.09	1	0.005	<0.05
STD-OREAS-45P-AR expected		19.0				0.38									
STD-OREAS-45P-AR result		18.9	10.5	<0.01	<0.01	<0.05	50.3	<0.2	1.7	11.9	<0.01	0.09	7	0.153	0.08
SI 484746	Soil	27.8	4.6	<0.01	0.05	0.11	0.6	0.3	<0.2	3.1	<0.01	0.10	2	<0.005	<0.05
SI 484746 Dup		27.5	4.8	<0.01	0.05	0.12	0.6	0.3	<0.2	3.1	<0.01	0.08	2	<0.005	<0.05
STD-ME-6 expected		10200													
STD-ME-6 result		>10000	3.5	0.01	2.32	375.83	3.5	2.0	1.6	23.2	<0.01	1.39	1	0.078	0.20
SI 484764	Soil	67.7	3.5	<0.01	<0.01	4.27	0.3	0.4	<0.2	18.6	<0.01	0.13	1	<0.005	<0.05
SI 484764 Dup		69.2	3.4	<0.01	<0.01	4.35	0.3	0.4	<0.2	19.1	<0.01	0.14	1	<0.005	<0.05
STD-OREAS-45P-AR expected		19.0				0.38									
STD-OREAS-45P-AR result		19.8	11.5	<0.01	<0.01	<0.05	56.8	<0.2	2.0	12.2	<0.01	0.10	7	0.154	0.07
STD-ME-6 expected		10200.0													
STD-ME-6 result		51.4	7.5	<0.01	0.03	1.29	0.3	0.5	0.3	21.6	<0.01	0.08	0	<0.005	0.05
SI 484782	Soil	50.0	8.0	<0.01	0.03	1.27	0.3	0.5	0.3	24.2	<0.01	0.10	0	<0.005	0.05
SI 484782 Dup		>10000	4.2	0.01	2.41	403.71	3.9	2.2	1.7	27.0	<0.01	1.57	1	0.098	0.22
STD-OREAS-45P-AR expected		19.0				0.38									
STD-OREAS-45P-AR result		19.3	11.0	<0.01	<0.01	<0.05	55.9	0.5	1.8	13.2	<0.01	0.08	7	0.162	0.08
SI 484800	Soil	36.9	4.1	<0.01	<0.01	<0.05	1.1	<0.2	<0.2	4.4	<0.01	0.06	2	<0.005	<0.05
SI 484800 Dup		37.7	4.2	<0.01	<0.01	<0.05	1.0	<0.2	<0.2	4.4	<0.01	0.05	2	<0.005	<0.05
QCV1008-01111-0038-BLK		<0.2	<0.1	<0.01	<0.01	<0.05	<0.1	<0.2	<0.2	<0.2	<0.01	<0.01	<0.2	<0.005	<0.05
STD-DS-1 expected		13.8													20.00
STD-DS-1 result		11.8	6.0	<0.01	2.51	95.76	6.5	0.9	1.1	68.7	<0.01	0.06	3	<0.005	18.88

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
QCV1008-01111-0001-BLK		<0.05	<1	<0.05	<0.05	<1	<0.5
SG 312315	Soil	2	15	1.26	3.6	157	<0.5
SG 312315 Dup		2	15	1.37	3.6	158	<0.5
STD-ME-6 expected						5170	
STD-ME-6 result		1	47	2.01	6.9	5400	4.4
SG 312333	Soil	2	11	1.37	3.1	122	0.6
SG 312333 Dup		2	11	1.44	3.2	122	0.6
STD-ME-6 expected						5170	
STD-ME-6 result		1	45	1.66	6.8	5207	4.1
SG 312351	Soil	1	7	1.41	2.6	141	<0.5
SG 312351 Dup		1	7	1.47	2.5	151	<0.5
STD-ME-6 expected						5170	
STD-ME-6 result		1	51	3.53	7.8	5345	5.1
SG 312369	Soil	2	14	1.47	5.6	86	1.0
SG 312369 Dup		1	14	1.52	5.5	93	1.0
STD-ME-6 expected						5170	
STD-ME-6 result		1	47	3.24	7.1	5517	4.8
SG 312387	Soil	1	17	0.34	1.8	85	1.1
SG 312387 Dup		1	18	0.38	1.9	86	1.1
STD-OREAS-45P-AR expected						123	
STD-OREAS-45P-AR result		1	225	0.98	8.8	162	19.0
SG 312405	Soil	1	8	0.59	1.9	115	<0.5
SG 312405 Dup		1	8	0.63	1.9	120	<0.5
STD-OREAS-45P-AR expected						123	
STD-OREAS-45P-AR result		1	216	1.66	8.8	173	18.9
SG 312423	Soil	1	11	0.48	2.2	80	<0.5
SG 312423 Dup		1	11	0.44	2.2	72	<0.5
STD-OREAS-45P-AR expected						123	
STD-OREAS-45P-AR result		1	224	2.14	8.9	172	19.6
SI 480507	Soil	1	30	2.03	2.0	102	<0.5
SI 480507 Dup		1	30	2.02	2.0	93	<0.5
STD-ME-6 expected						5170	
STD-ME-6 result		1	44	2.88	6.6	5539	4.9
SI 480525	Soil	1	7	1.72	2.6	99	<0.5
SI 480525 Dup		1	7	1.70	2.7	106	<0.5
STD-OREAS-45P-AR expected						123	
STD-OREAS-45P-AR result		1	207	1.95	8.9	139	19.6
SI 480567	Soil	1	21	3.22	4.8	96	<0.5
SI 480567 Dup		1	20	2.79	4.8	87	<0.5
STD-OREAS-45P-AR expected						123	
STD-OREAS-45P-AR result		1	187	3.23	8.3	135	17.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02714-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	U 50-AR-UT ppm 0.05	V 50-AR-UT ppm 1	W 50-AR-UT ppm 0.05	Y 50-AR-UT ppm 0.05	Zn 50-AR-UT ppm 1	Zr 50-AR-UT ppm 0.5
SI 480585	Soil	1	19	3.54	3.9	102	<0.5
SI 480585 Dup		1	19	3.86	3.8	96	<0.5
STD-ME-6 expected						5170	
STD-ME-6 result		1	46	1.85	6.6	5511	4.7
SI 484692	Soil	2	16	2.65	3.4	119	<0.5
SI 484692 Dup		2	16	2.75	3.5	125	<0.5
STD-ME-6 expected						5170	
STD-ME-6 result		1	41	3.06	6.1	5050	4.5
SI 484710	Soil	1	22	1.03	2.2	75	<0.5
SI 484710 Dup		1	21	0.96	2.3	71	<0.5
STD-OREAS-45P-AR expected						123	
STD-OREAS-45P-AR result		1	231	1.56	9.9	164	22.9
SI 484728	Soil	1	15	2.45	1.9	125	<0.5
SI 484728 Dup		1	15	2.50	1.9	116	<0.5
STD-OREAS-45P-AR expected						123	
STD-OREAS-45P-AR result		1	223	0.31	9.3	137	21.7
SI 484746	Soil	1	18	0.42	1.4	56	3.1
SI 484746 Dup		1	19	0.42	1.4	55	3.1
STD-ME-6 expected						5170	
STD-ME-6 result		1	44	1.28	6.2	5297	4.5
SI 484764	Soil	1	9	0.52	1.9	74	<0.5
SI 484764 Dup		1	9	0.55	1.9	69	<0.5
STD-OREAS-45P-AR expected						123	
STD-OREAS-45P-AR result		1	266	0.64	10.8	136	24.2
STD-ME-6 expected						5170	
STD-ME-6 result		1	18	1.27	2.1	83	<0.5
SI 484782	Soil	1	18	1.37	2.3	81	<0.5
SI 484782 Dup		1	49	1.31	7.4	5530	5.8
STD-OREAS-45P-AR expected						123	
STD-OREAS-45P-AR result		1	247	0.67	10.4	146	23.1
SI 484800	Soil	1	21	0.67	1.6	126	1.4
SI 484800 Dup		1	20	0.65	1.6	133	1.4
QCV1008-01111-0038-BLK		<0.05	<1	<0.05	<0.05	<1	<0.5
STD-DS-1 expected						206	
STD-DS-1 result		1	51	6.16	9.7	233	3.1

Certificate of Analysis

10-360-02716-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 09/07/2010
Date Completed: 09/14/2010
Invoice:

Samples	Type	Preparation Description
36	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-1AT-GV	Au, 1AT, Gravimetric
Au-2AT-AA	Au, 2AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02716-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480253	Rock		0.021	<0.01	1.70	198.2	67	0.6	0.60	0.01	0.06	23.98	1.6	247	1.0
RI 480254	Rock		0.077	0.08	2.14	160.2	132	0.7	0.36	<0.01	0.46	23.99	1.2	161	12.6
RI 480255	Rock		0.011	<0.01	1.95	41.9	126	0.6	0.40	<0.01	0.06	30.51	1.3	240	2.6
RI 480256	Rock		0.204	0.53	3.02	578.5	197	1.2	0.24	<0.01	0.23	34.12	2.6	175	3.1
RI 480257	Rock		0.037	0.12	1.53	667.1	82	0.4	0.48	0.01	0.21	23.64	1.1	181	1.6
RI 480258	Rock		0.013	0.41	2.08	3131.1	114	1.0	0.59	0.02	2.12	27.22	1.2	148	2.1
RI 480259	Rock		0.008	<0.01	2.14	168.2	86	0.6	0.39	0.01	0.81	24.05	0.8	163	1.3
RI 480260	Rock		8.041	0.67	2.20	>10000	123	0.8	1.08	0.29	0.09	20.35	4.3	162	1.9
RI 480261	Rock		0.097	<0.01	2.55	1233.3	163	1.0	0.66	0.58	0.22	29.50	6.2	173	2.5
RI 480262	Rock		0.180	<0.01	2.19	372.5	136	0.7	0.44	0.01	0.07	31.65	1.1	150	1.8
RI 480263	Rock		0.007	<0.01	1.97	32.7	104	0.5	0.63	<0.01	0.04	28.26	2.1	224	1.8
RI 480264	Rock		0.023	0.12	2.53	361.9	84	0.9	0.35	<0.01	0.31	32.33	2.3	147	1.3
RI 480265	Rock		1.708	1.98	0.23	302.3	24	0.1	3.75	<0.01	0.14	2.52	1.1	222	0.6
RI 480266	Rock		0.855	2.08	0.18	218.4	25	0.2	3.89	<0.01	0.08	2.68	0.5	213	0.6
RI 480267	Rock		1.708	0.08	0.20	1778.0	20	0.1	0.58	<0.01	0.11	3.00	0.8	228	0.7
RI 480268	Rock		0.009	0.12	1.98	68.2	125	0.8	0.39	<0.01	0.08	31.01	1.4	164	2.3
RI 480269	Rock		<0.005	0.19	0.22	26.8	14	0.2	3.27	0.02	0.02	11.45	3.1	271	0.4
RI 480270	Rock		0.020	0.31	2.04	102.5	102	0.8	0.27	0.02	0.22	29.93	7.8	191	1.7
RI 480271	Rock		0.118	0.47	0.85	210.6	40	0.4	0.78	0.02	0.15	10.00	3.7	260	0.7
RI 480272	Rock		5.887	2.03	0.19	250.0	15	0.2	0.62	<0.01	0.09	2.05	0.9	237	0.8
RI 480273	Rock		0.044	<0.01	0.14	425.4	19	0.1	1.15	<0.01	0.05	2.28	0.7	223	0.5
RI 481564	Rock		0.109	0.44	0.41	5957.9	51	0.3	2.23	0.01	0.09	3.91	1.0	234	0.4
RI 481565	Rock	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
RI 481566	Rock		0.169	<0.01	0.17	2746.2	24	0.2	0.99	<0.01	0.05	2.40	0.8	271	0.2
RI 481567	Rock		0.159	0.06	0.39	3187.4	54	0.4	0.59	0.01	0.24	4.20	1.2	247	0.4
RI 481568	Rock		0.354	<0.01	0.84	4611.5	65	0.4	0.54	0.01	0.37	9.76	3.8	243	0.6
RI 481569	Rock		0.057	0.50	0.36	1490.6	33	0.3	0.64	<0.01	0.09	3.85	1.0	291	0.3
RI 481570	Rock	23.478	>10	0.94	0.52	>10000	50	0.4	1.28	<0.01	0.05	4.80	1.5	261	0.6
RI 481571	Rock		3.312	0.43	0.24	1117.1	26	0.3	0.98	<0.01	0.07	2.74	0.6	233	0.3
RI 481572	Rock		6.308	0.32	0.42	3585.2	40	0.3	0.75	<0.01	0.04	4.13	1.1	281	0.4
RI 481573	Rock		3.074	0.24	0.12	1908.9	16	0.1	1.59	<0.01	0.06	0.94	0.6	314	0.2
RI 481574	Rock		0.767	<0.01	0.08	1039.8	17	0.1	0.95	0.01	0.06	0.45	0.7	279	0.1
RI 481575	Rock		0.864	<0.01	0.27	3128.1	25	0.2	0.98	<0.01	0.03	2.34	0.6	301	0.3
RI 481576	Rock		1.278	<0.01	0.15	1122.7	14	0.1	0.46	<0.01	<0.01	1.39	0.6	273	0.2
RI 481577	Rock		0.045	0.56	2.19	5782.0	42	0.4	0.93	0.02	0.07	22.06	2.8	191	0.5
RI 481578	Rock		0.420	0.15	0.14	839.0	13	0.1	0.65	<0.01	0.04	2.91	1.1	281	0.2

NS = No Sample

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02716-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
RI 480253	Rock	11.3	0.78	3.1	0.1	2.94	0.01	0.25	11.5	54.4	0.02	40	1.25	0.02	0.9
RI 480254	Rock	6.5	0.43	5.4	0.6	2.57	0.02	0.79	11.5	10.9	0.06	43	0.83	0.04	0.6
RI 480255	Rock	4.8	0.32	5.1	<0.05	1.75	0.01	0.66	14.1	13.1	0.03	32	0.97	0.03	0.9
RI 480256	Rock	13.7	1.43	7.9	<0.05	2.61	0.02	1.20	16.5	6.3	0.08	73	0.79	0.05	1.1
RI 480257	Rock	7.1	0.58	3.3	<0.05	1.27	0.02	0.35	10.8	26.2	0.03	31	0.89	0.03	0.7
RI 480258	Rock	56.3	7.10	4.9	<0.05	1.85	0.05	0.40	12.9	25.1	0.03	75	1.14	0.04	0.4
RI 480259	Rock	22.7	0.56	4.2	0.3	1.54	0.01	0.41	11.0	6.2	0.04	26	0.78	0.04	0.7
RI 480260	Rock	8.6	2.09	5.6	<0.05	1.61	0.03	0.76	9.8	6.2	0.07	210	0.93	0.54	0.7
RI 480261	Rock	13.4	1.40	6.8	<0.05	1.70	0.02	0.93	13.9	7.5	0.13	338	0.80	0.54	0.9
RI 480262	Rock	6.6	0.62	5.2	<0.05	1.37	0.02	0.73	14.9	5.3	0.13	38	0.66	0.05	0.7
RI 480263	Rock	8.0	0.43	4.9	<0.05	1.72	<0.01	0.44	13.7	52.7	0.02	73	0.89	0.05	1.1
RI 480264	Rock	17.1	2.15	4.3	<0.05	1.50	0.02	0.32	15.8	110.9	0.02	56	0.82	0.02	0.5
RI 480265	Rock	59.6	0.78	0.9	<0.05	<0.1	0.13	0.07	1.2	16.5	<0.01	31	0.90	<0.01	<0.1
RI 480266	Rock	21.5	0.47	0.7	<0.05	<0.1	0.07	0.06	1.4	9.5	<0.01	29	0.79	<0.01	<0.1
RI 480267	Rock	8.4	0.56	0.6	<0.05	<0.1	<0.01	0.05	1.4	22.1	<0.01	55	1.07	<0.01	0.1
RI 480268	Rock	11.6	1.23	4.7	<0.05	1.42	<0.01	0.53	14.7	13.9	0.03	45	0.81	0.02	0.8
RI 480269	Rock	23.8	0.56	0.7	<0.05	0.14	<0.01	0.05	5.5	3.0	<0.01	67	1.06	0.03	0.4
RI 480270	Rock	13.7	1.37	5.1	<0.05	1.25	0.01	0.52	13.6	13.4	0.06	445	0.83	0.52	1.0
RI 480271	Rock	12.7	1.00	2.3	<0.05	0.14	<0.01	0.19	4.7	13.0	0.06	156	1.14	0.14	0.3
RI 480272	Rock	14.7	0.45	0.7	<0.05	<0.1	<0.01	0.05	1.0	17.6	<0.01	50	0.94	<0.01	<0.1
RI 480273	Rock	8.6	0.36	0.5	<0.05	<0.1	<0.01	0.03	1.1	22.1	<0.01	38	1.34	<0.01	0.1
RI 481564	Rock	92.0	0.71	1.7	<0.05	<0.1	0.02	0.13	1.9	1.9	0.02	36	1.24	0.01	<0.1
RI 481565	Rock	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
RI 481566	Rock	18.0	0.47	0.7	0.1	<0.1	<0.01	0.05	1.2	1.5	<0.01	33	1.26	<0.01	<0.1
RI 481567	Rock	11.9	0.53	1.8	<0.05	<0.1	<0.01	0.15	2.0	2.4	0.02	35	1.21	<0.01	0.2
RI 481568	Rock	11.4	0.77	3.3	<0.05	0.23	0.01	0.28	4.7	5.3	0.03	45	1.28	0.01	0.3
RI 481569	Rock	8.5	0.44	1.6	0.1	<0.1	<0.01	0.17	1.9	1.4	0.02	38	1.28	<0.01	0.1
RI 481570	Rock	5.9	1.43	2.6	<0.05	<0.1	0.02	0.25	2.7	3.9	0.03	36	1.30	0.01	0.2
RI 481571	Rock	6.9	0.36	1.2	<0.05	<0.1	<0.01	0.12	1.3	3.7	0.01	33	1.18	<0.01	<0.1
RI 481572	Rock	5.5	0.56	2.2	<0.05	<0.1	0.01	0.21	2.2	2.5	0.02	35	1.17	<0.01	0.2
RI 481573	Rock	4.6	0.46	0.6	<0.05	<0.1	<0.01	0.05	<0.5	2.5	<0.01	40	1.20	<0.01	<0.1
RI 481574	Rock	8.2	0.34	0.3	<0.05	<0.1	<0.01	0.02	<0.5	7.8	<0.01	34	0.82	<0.01	<0.1
RI 481575	Rock	4.2	0.57	1.1	<0.05	<0.1	<0.01	0.11	1.2	2.8	0.01	37	1.08	<0.01	0.1
RI 481576	Rock	3.9	0.36	0.7	<0.05	<0.1	<0.01	0.06	0.7	2.4	<0.01	31	0.86	<0.01	<0.1
RI 481577	Rock	6.3	0.91	3.3	<0.05	1.22	0.01	0.20	9.9	1.3	0.02	165	0.92	1.49	0.6
RI 481578	Rock	4.0	0.37	0.6	<0.05	<0.1	<0.01	0.05	1.4	3.0	<0.01	36	0.93	<0.01	<0.1

NS = No Sample

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02716-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
RI 480253	Rock	7.0	143	18.6	15.1	<0.005	<0.01	2.04	0.7	<0.5	0.9	57.1	0.14	0.07	6
RI 480254	Rock	4.2	97	56.8	44.9	<0.005	<0.01	2.77	1.8	<0.5	6.1	52.7	0.11	0.17	7
RI 480255	Rock	3.9	47	15.8	35.8	<0.005	<0.01	1.75	1.5	<0.5	1.3	24.1	0.12	0.08	5
RI 480256	Rock	7.9	86	13.5	62.4	0.008	0.02	2.84	4.1	<0.5	1.2	19.2	0.16	<0.05	8
RI 480257	Rock	5.0	161	35.9	20.2	<0.005	<0.01	3.26	1.4	<0.5	0.8	54.8	0.09	<0.05	6
RI 480258	Rock	8.5	1376	22.7	23.5	<0.005	0.01	3.91	3.6	<0.5	1.0	86.2	0.06	<0.05	18
RI 480259	Rock	4.6	76	9.0	23.5	<0.005	<0.01	1.17	2.0	<0.5	1.1	18.1	0.09	0.12	7
RI 480260	Rock	12.9	47	43.9	40.4	0.006	0.69	20.53	2.5	2.2	0.8	31.7	0.11	5.08	6
RI 480261	Rock	17.6	62	17.0	52.0	<0.005	0.05	3.00	3.6	1.5	0.8	35.1	0.11	0.28	7
RI 480262	Rock	3.6	104	113.4	39.6	0.006	0.01	2.79	2.2	<0.5	2.9	25.5	0.08	0.09	5
RI 480263	Rock	6.3	64	15.0	26.3	0.008	<0.01	0.97	1.7	<0.5	0.8	31.6	0.13	0.09	9
RI 480264	Rock	8.7	255	18.7	18.6	0.005	<0.01	2.94	2.4	<0.5	0.7	69.9	0.10	<0.05	9
RI 480265	Rock	5.1	34	362.6	4.8	<0.005	0.13	17.23	0.5	1.7	0.7	4.1	<0.05	<0.05	0
RI 480266	Rock	4.2	34	577.4	4.0	<0.005	0.03	5.85	0.4	2.4	0.7	5.1	<0.05	<0.05	0
RI 480267	Rock	5.5	30	17.7	4.4	<0.005	0.05	3.05	0.2	1.1	0.8	5.0	<0.05	0.22	0
RI 480268	Rock	5.8	133	13.2	29.2	<0.005	<0.01	7.21	2.1	<0.5	0.8	18.5	0.10	<0.05	7
RI 480269	Rock	8.7	83	5.1	3.2	<0.005	<0.01	0.38	0.5	1.5	0.4	3.9	<0.05	0.11	2
RI 480270	Rock	16.6	101	59.0	32.9	0.008	<0.01	0.97	2.3	<0.5	0.8	21.1	0.09	<0.05	6
RI 480271	Rock	12.3	76	15.2	12.7	<0.005	<0.01	1.00	1.2	<0.5	0.5	9.6	<0.05	0.06	2
RI 480272	Rock	4.8	16	98.6	4.4	0.006	<0.01	6.50	0.4	<0.5	0.4	3.0	<0.05	<0.05	0
RI 480273	Rock	5.8	<10	158.5	2.5	0.009	0.02	1.28	0.3	<0.5	0.4	5.6	<0.05	<0.05	0
RI 481564	Rock	6.9	21	27.5	8.1	<0.005	0.25	4.17	0.4	1.6	0.9	4.0	<0.05	0.17	0
RI 481565	Rock	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
RI 481566	Rock	5.7	13	11.7	3.5	<0.005	0.09	2.60	0.3	<0.5	0.4	2.7	<0.05	<0.05	0
RI 481567	Rock	6.8	21	24.3	9.9	<0.005	0.10	2.57	0.5	<0.5	0.7	4.8	<0.05	0.29	0
RI 481568	Rock	8.8	32	41.1	17.5	0.008	0.17	3.75	0.9	<0.5	0.9	8.6	<0.05	0.18	2
RI 481569	Rock	6.0	17	24.0	9.4	<0.005	0.04	1.54	0.4	<0.5	1.2	4.7	<0.05	0.14	0
RI 481570	Rock	6.3	44	34.4	14.7	<0.005	0.40	12.06	0.9	1.2	0.7	4.2	<0.05	0.24	1
RI 481571	Rock	5.8	16	74.1	6.7	<0.005	0.03	1.74	0.4	<0.5	0.7	2.8	<0.05	0.08	<0.2
RI 481572	Rock	5.5	22	38.1	12.5	<0.005	0.11	3.40	0.7	<0.5	0.7	2.9	<0.05	0.22	0
RI 481573	Rock	5.2	14	9.1	3.1	<0.005	0.05	2.49	0.2	1.5	0.5	2.2	<0.05	0.21	<0.2
RI 481574	Rock	4.1	<10	5.4	1.3	<0.005	0.02	1.57	0.2	<0.5	0.3	1.8	<0.05	<0.05	<0.2
RI 481575	Rock	4.8	18	5.9	6.2	<0.005	0.09	2.58	0.4	1.6	0.6	3.2	<0.05	0.15	<0.2
RI 481576	Rock	4.5	<10	8.9	3.4	<0.005	0.04	1.64	0.4	<0.5	0.3	2.5	<0.05	0.07	<0.2
RI 481577	Rock	9.1	44	2.3	11.2	0.006	0.27	3.98	1.8	<0.5	0.5	45.7	0.07	<0.05	6
RI 481578	Rock	4.5	14	62.8	2.8	<0.005	0.03	1.65	0.2	1.3	0.3	3.2	<0.05	<0.05	<0.2

NS = No Sample

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02716-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480253	Rock	0.017	0.02	1	<1	17.50	3.2	14	38.4
RI 480254	Rock	0.020	0.17	1	<1	17.99	3.3	8	39.6
RI 480255	Rock	0.025	0.13	1	<1	18.29	3.1	3	41.5
RI 480256	Rock	0.038	0.29	2	<1	14.81	4.6	28	58.3
RI 480257	Rock	0.018	0.07	2	<1	14.47	3.2	7	43.9
RI 480258	Rock	0.012	0.10	3	<1	13.98	5.3	57	45.8
RI 480259	Rock	0.021	0.07	1	<1	9.92	3.5	11	48.6
RI 480260	Rock	0.025	0.17	1	<1	20.37	3.6	40	43.6
RI 480261	Rock	0.030	0.22	1	<1	12.53	5.1	67	51.2
RI 480262	Rock	0.025	0.15	1	<1	14.39	3.8	11	42.6
RI 480263	Rock	0.027	0.08	2	<1	12.52	3.7	10	56.0
RI 480264	Rock	0.018	0.07	1	<1	19.82	3.9	41	49.6
RI 480265	Rock	<0.005	<0.02	0	<1	25.92	0.3	30	1.9
RI 480266	Rock	<0.005	<0.02	0	<1	17.56	0.3	19	2.6
RI 480267	Rock	<0.005	<0.02	0	<1	13.50	0.6	7	2.4
RI 480268	Rock	0.025	0.12	2	<1	22.35	3.7	17	49.9
RI 480269	Rock	0.008	<0.02	1	<1	36.28	1.7	9	12.5
RI 480270	Rock	0.027	0.11	1	<1	7.25	4.7	40	47.0
RI 480271	Rock	0.008	0.02	0	<1	22.72	1.8	23	12.8
RI 480272	Rock	<0.005	<0.02	<0.1	<1	19.05	0.4	13	1.8
RI 480273	Rock	<0.005	<0.02	<0.1	<1	37.77	0.2	5	1.3
RI 481564	Rock	<0.005	<0.02	0	<1	9.14	0.4	3	2.9
RI 481565	Rock	NS	NS	NS	NS	NS	NS	NS	NS
RI 481566	Rock	<0.005	<0.02	0	<1	20.74	0.3	2	1.9
RI 481567	Rock	0.005	<0.02	0	<1	14.55	0.5	6	3.5
RI 481568	Rock	0.009	0.03	0	<1	20.25	1.1	12	13.5
RI 481569	Rock	<0.005	<0.02	0	<1	16.06	0.4	3	3.1
RI 481570	Rock	0.008	0.04	0	<1	16.28	0.5	5	4.6
RI 481571	Rock	<0.005	<0.02	<0.1	1	10.44	0.2	2	1.0
RI 481572	Rock	0.006	<0.02	0	<1	7.48	0.4	2	2.3
RI 481573	Rock	<0.005	<0.02	<0.1	<1	10.88	0.1	<2	0.7
RI 481574	Rock	<0.005	<0.02	<0.1	<1	15.75	<0.1	3	0.6
RI 481575	Rock	<0.005	<0.02	<0.1	<1	4.65	0.3	<2	1.6
RI 481576	Rock	<0.005	<0.02	<0.1	<1	16.35	0.2	<2	0.8
RI 481577	Rock	0.016	<0.02	1	<1	19.49	3.1	10	40.8
RI 481578	Rock	<0.005	<0.02	<0.1	<1	13.89	0.2	2	1.0

NS = No Sample

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02716-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
QCV1009-00099-0001-BLK				<0.01	<0.01	<0.1	<5	<0.05	0.02	<0.01	<0.01	<0.02	<0.1	<1	<0.05
RI 480253	Rock			<0.01	1.70	198.2	67	0.6	0.60	0.01	0.06	23.98	1.6	247	1.0
RI 480253 Dup				<0.01	1.67	201.0	66	0.6	0.57	0.01	0.06	23.71	1.6	249	1.1
STD-ME-8 expected				61.70											
STD-ME-8 result				60.95	4.37	2583.9	580	1.0	4.67	6.48	101.48	29.05	<0.1	43	3.5
RI 480271	Rock			0.47	0.85	210.6	40	0.4	0.78	0.02	0.15	10.00	3.7	260	0.7
RI 480271 Dup				0.14	0.84	208.4	40	0.4	0.81	0.02	0.08	9.37	3.6	264	0.7
STD-OREAS-45P-4A expected				0.32		13.4			0.21				122.0	1103	
STD-OREAS-45P-4A result				0.30	6.11	40.3	291	1.1	0.30	0.25	0.19	52.67	112.2	941	2.5
QCV1009-00099-0006-BLK				<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
STD-SY-4 expected							340	2.6				122.00	2.8	12	1.5
STD-SY-4 result				0.49	9.84	65.1	343	3.2	0.03	5.50	0.09	132.14	4.0	9	1.9
RI 480253	Rock		0.021												
RI 480253 Dup			0.018												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.770												
RI 480271	Rock		0.118												
RI 480271 Dup			0.131												
QCV1009-00100-0004-BLK			<0.005												
STD-Oxi67 expected			1.817												
STD-Oxi67 result			1.734												

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02716-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
QCV1009-00099-0001-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
RI 480253	Rock	11.3	0.78	3.1	0.1	2.94	0.01	0.25	11.5	54.4	0.02	40	1.25	0.02	0.9
RI 480253 Dup		11.4	0.78	3.1	0.2	3.07	<0.01	0.24	11.4	54.2	0.02	42	1.29	0.02	0.8
STD-ME-8 expected		1030.0													
STD-ME-8 result		1054.5	3.56	10.6	<0.05	1.87	0.10	1.37	14.6	15.5	0.69	2996	6.26	1.19	4.2
RI 480271	Rock	12.7	1.00	2.3	<0.05	0.14	<0.01	0.19	4.7	13.0	0.06	156	1.14	0.14	0.3
RI 480271 Dup		12.9	0.98	2.3	<0.05	0.12	<0.01	0.19	4.3	12.8	0.06	157	1.16	0.14	0.3
STD-OREAS-45P-4A expected		749.0												0.08	
STD-OREAS-45P-4A result		753.5	>10	21.9	0.6	4.81	0.13	0.33	25.0	12.3	0.21	1293	2.42	0.07	22.2
QCV1009-00099-0006-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
STD-SY-4 expected		7.0		35.0		10.60			58.0	37.0					13.0
STD-SY-4 result		7.7	4.13	35.6	0.2	2.14	0.04	1.41	61.9	34.7	0.31	820	0.29	5.01	15.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02716-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
QCV1009-00099-0001-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
RI 480253	Rock	7.0	143	18.6	15.1	<0.005	<0.01	2.04	0.7	<0.5	0.9	57.1	0.14	0.07	6
RI 480253 Dup		7.1	137	18.8	15.0	<0.005	<0.01	1.94	0.7	<0.5	0.9	56.8	0.14	0.07	6
STD-ME-8 expected				19400											
STD-ME-8 result		33.7	622	>10000	74.8	0.005	1.90	51.19	8.8	4.0	3.6	367.8	0.47	0.51	4
RI 480271	Rock	12.3	76	15.2	12.7	<0.005	<0.01	1.00	1.2	<0.5	0.5	9.6	<0.05	0.06	2
RI 480271 Dup		12.2	76	15.7	12.1	<0.005	<0.01	0.97	1.0	<0.5	0.5	9.4	<0.05	0.06	2
STD-OREAS-45P-4A expected		385.0	454	22.0				0.92							
STD-OREAS-45P-4A result		415.3	435	24.8	26.4	0.008	0.02	<0.05	64.1	1.2	3.1	30.0	1.94	0.26	11
QCV1009-00099-0006-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
STD-SY-4 expected		9.0		10.0	55.0				1.1			1191.0	0.90		1
STD-SY-4 result		7.8	557	12.7	51.3	0.021	<0.01	<0.05	1.0	<0.5	9.6	1200.9	1.46	<0.05	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02716-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1009-00099-0001-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
RI 480253	Rock	0.017	0.02	1	<1	17.50	3.2	14	38.4
RI 480253 Dup		0.017	0.03	1	<1	17.98	3.0	15	40.5
STD-ME-8 expected								19200	
STD-ME-8 result		0.181	0.85	2	8	33.84	12.6	>10000	36.4
RI 480271	Rock	0.008	0.02	0	<1	22.72	1.8	23	12.8
RI 480271 Dup		0.008	0.02	0	<1	24.01	1.7	22	12.6
STD-OREAS-45P-4A expected								142	
STD-OREAS-45P-4A result		1.066	0.17	2	160	11.53	14.3	133	160.2
QCV1009-00099-0006-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected				1	8		119.0	93	517.0
STD-SY-4 result		0.163	0.22	1	<1	2.79	129.0	90	61.9

Certificate of Analysis

10-360-02717-01

Inspectorte America Corporation
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5 Canada
Phone: 604-272-7818

Distribution List

Attention: Greg Hayes
#220 17010 103rd Ave
Edmonton, AB T5S 1K7
EMail: ghayes@northern-tiger.com

Attention: Melanie Debnam

Attention: Dennis Ouellette
EMail: douellette@northern-tiger.com

Attention: Bonnie Pollries
EMail: bpollries@northern-tiger.com

Attention: Carl Schulze
EMail: allterrane@northwestel.net

Submitted By: **Northern Tiger Resources**
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Attention: **Greg Hayes**

Project: **3 ACE**
Description: **3 ACE**

Date Received: 09/07/2010
Date Completed: 09/15/2010
Invoice:

Samples	Type	Preparation Description
5	Rock	SP-RX-2K/Rock/Chips/Drill Core

Method	Description
50-4A-UT	50 Element, 4 Acid, ICPMS, Ultra Trace Level
Au-1AT-GV	Au, 1AT, Gravimetric
Au-2AT-AA	Au, 2AT Fire Assay, AAS

The results of this assay were based solely upon the content of the sample submitted. Any decision to invest should be made only after the potential investment value of the claim or deposit has been determined based on the results of assays of multiple samples of geologic materials collected by the prospective investor or by a qualified person selected by him and based on an evaluation of all engineering data which is available concerning any proposed project. For our complete terms and conditions please see our website at www.inspectorate.com.

By _____
David Chiu, BC Certified Assayer

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02717-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Au Au-1AT-GV g/ton 0.100	Au Au-2AT-AA g/ton 0.005	Ag 50-4A-UT ppm 0.01	Al 50-4A-UT % 0.01	As 50-4A-UT ppm 0.1	Ba 50-4A-UT ppm 5	Be 50-4A-UT ppm 0.05	Bi 50-4A-UT ppm 0.01	Ca 50-4A-UT % 0.01	Cd 50-4A-UT ppm 0.01	Ce 50-4A-UT ppm 0.02	Co 50-4A-UT ppm 0.1	Cr 50-4A-UT ppm 1	Cs 50-4A-UT ppm 0.05
RI 480248	Rock		1.578	<0.01	0.94	5791.1	71	0.5	3.57	0.02	<0.01	11.95	3.5	146	1.5
RI 480249	Rock		0.492	<0.01	8.28	2722.6	465	4.1	0.80	0.07	<0.01	57.32	18.9	85	8.2
RI 480250	Rock		4.548	<0.01	1.14	1920.8	78	0.6	5.65	0.02	<0.01	14.04	2.0	228	1.1
RI 480251	Rock	12.602	>10	<0.01	0.76	3672.5	48	0.3	0.73	0.02	<0.01	8.33	1.0	164	0.8
RI 480252	Rock		8.302	<0.01	2.87	>10000	184	1.2	1.33	<0.01	<0.01	29.40	3.1	159	5.9

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02717-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
RI 480248	Rock	14.8	0.95	2.8	0.1	<0.1	<0.01	0.41	6.2	5.3	0.06	76	1.09	0.03	0.6
RI 480249	Rock	34.4	4.84	26.8	<0.05	2.78	<0.01	3.47	25.7	75.8	1.04	694	0.49	0.65	8.7
RI 480250	Rock	14.8	0.92	3.1	<0.05	<0.1	<0.01	0.39	7.2	9.6	0.10	116	1.15	0.09	1.0
RI 480251	Rock	11.3	0.70	2.4	<0.05	<0.1	<0.01	0.32	4.3	4.5	0.05	51	0.85	0.03	0.6
RI 480252	Rock	47.5	2.86	8.9	<0.05	0.44	<0.01	1.22	15.6	11.1	0.11	55	1.25	0.10	1.6

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02717-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
RI 480248	Rock	6.3	14	16.9	25.2	<0.005	0.26	5.62	1.2	<0.5	1.6	14.5	<0.05	0.07	2
RI 480249	Rock	29.8	264	20.3	143.6	<0.005	0.12	6.92	14.2	<0.5	4.2	82.2	1.15	<0.05	13
RI 480250	Rock	6.1	44	20.9	23.8	<0.005	0.03	2.85	2.0	<0.5	1.9	21.8	0.12	0.12	2
RI 480251	Rock	4.0	91	19.5	19.9	<0.005	0.03	5.27	1.1	2.1	0.6	11.7	<0.05	0.09	1
RI 480252	Rock	9.1	51	14.1	76.0	<0.005	0.81	12.03	4.1	1.8	1.2	50.5	0.18	0.28	5

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02717-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
RI 480248	Rock	0.017	<0.02	0	4	14.21	1.7	22	7.6
RI 480249	Rock	0.151	0.63	3	93	21.04	12.6	85	84.0
RI 480250	Rock	0.022	<0.02	0	10	18.99	2.0	32	10.1
RI 480251	Rock	0.016	<0.02	0	5	13.00	0.8	20	5.6
RI 480252	Rock	0.047	0.19	1	30	20.64	2.4	17	21.7

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02717-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

		Au	Au	Ag	Al	As	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr	Cs
		Au-1AT-GV	Au-2AT-AA	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT	50-4A-UT
Sample	Sample	g/ton	g/ton	ppm	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm
Description	Type	0.100	0.005	0.01	0.01	0.1	5	0.05	0.01	0.01	0.01	0.02	0.1	1	0.05
QCV1009-00101-0001-BLK				<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
RI 480248	Rock			<0.01	0.94	5791.1	71	0.5	3.57	0.02	<0.01	11.95	3.5	146	1.5
RI 480248 Dup				<0.01	0.93	5932.1	70	0.5	3.55	0.02	<0.01	11.58	3.1	163	1.5
QCV1009-00101-0003-BLK				<0.01	<0.01	<0.1	<5	<0.05	<0.01	<0.01	<0.01	<0.02	<0.1	<1	<0.05
STD-SY-4 expected							340	2.6				122.00	2.8	12	1.5
STD-SY-4 result				<0.01	7.64	18.3	324	2.8	<0.01	5.43	<0.01	81.74	3.9	6	1.2
RI 480248	Rock		1.578												
RI 480248 Dup			1.657												
QCV1009-00102-0002-BLK			<0.005												

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02717-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Cu 50-4A-UT ppm 0.2	Fe 50-4A-UT % 0.01	Ga 50-4A-UT ppm 0.05	Ge 50-4A-UT ppm 0.05	Hf 50-4A-UT ppm 0.1	In 50-4A-UT ppm 0.01	K 50-4A-UT % 0.01	La 50-4A-UT ppm 0.5	Li 50-4A-UT ppm 0.2	Mg 50-4A-UT % 0.01	Mn 50-4A-UT ppm 5	Mo 50-4A-UT ppm 0.05	Na 50-4A-UT % 0.01	Nb 50-4A-UT ppm 0.1
QCV1009-00101-0001-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
RI 480248	Rock	14.8	0.95	2.8	0.1	<0.1	<0.01	0.41	6.2	5.3	0.06	76	1.09	0.03	0.6
RI 480248 Dup		15.0	0.96	2.8	<0.05	<0.1	<0.01	0.41	6.1	5.2	0.06	77	1.06	0.03	0.6
QCV1009-00101-0003-BLK		<0.2	<0.01	<0.05	<0.05	<0.1	<0.01	<0.01	<0.5	<0.2	<0.01	<5	<0.05	<0.01	<0.1
STD-SY-4 expected		7.0		35.0		10.60			58.0	37.0					13.0
STD-SY-4 result		7.6	4.44	32.0	<0.05	1.17	<0.01	1.24	33.4	34.2	0.24	746	0.40	4.80	14.0

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02717-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ni 50-4A-UT ppm 0.2	P 50-4A-UT ppm 10	Pb 50-4A-UT ppm 0.5	Rb 50-4A-UT ppm 0.1	Re 50-4A-UT ppm 0.005	S 50-4A-UT % 0.01	Sb 50-4A-UT ppm 0.05	Sc 50-4A-UT ppm 0.1	Se 50-4A-UT ppm 0.5	Sn 50-4A-UT ppm 0.2	Sr 50-4A-UT ppm 0.2	Ta 50-4A-UT ppm 0.05	Te 50-4A-UT ppm 0.05	Th 50-4A-UT ppm 0.2
QCV1009-00101-0001-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
RI 480248	Rock	6.3	14	16.9	25.2	<0.005	0.26	5.62	1.2	<0.5	1.6	14.5	<0.05	0.07	2
RI 480248 Dup		6.3	17	16.8	25.7	<0.005	0.26	6.22	1.2	<0.5	1.6	14.3	<0.05	0.08	2
QCV1009-00101-0003-BLK		<0.2	<10	<0.5	<0.1	<0.005	<0.01	<0.05	<0.1	<0.5	<0.2	<0.2	<0.05	<0.05	<0.2
STD-SY-4 expected		9.0		10.0	55.0				1.1			1191.0	0.90		1
STD-SY-4 result		8.3	474	16.3	12.8	<0.005	<0.01	2.84	0.6	<0.5	8.3	955.9	1.44	<0.05	1

INSPECTORATE
#200 - 11620 Horseshoe Way
Richmond, British Columbia V7A 4V5
Canada

Certificate of Analysis

10-360-02717-01

Northern Tiger Resources
#220 17010 103rd Ave
Edmonton, AB T5S 1K7

Sample Description	Sample Type	Ti 50-4A-UT % 0.005	Tl 50-4A-UT ppm 0.02	U 50-4A-UT ppm 0.1	V 50-4A-UT ppm 1	W 50-4A-UT ppm 0.1	Y 50-4A-UT ppm 0.1	Zn 50-4A-UT ppm 2	Zr 50-4A-UT ppm 0.5
QCV1009-00101-0001-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
RI 480248	Rock	0.017	<0.02	0	4	14.21	1.7	22	7.6
RI 480248 Dup		0.016	<0.02	0	4	15.07	1.5	18	7.3
QCV1009-00101-0003-BLK		<0.005	<0.02	<0.1	<1	<0.1	<0.1	<2	<0.5
STD-SY-4 expected				1	8		119.0	93	517.0
STD-SY-4 result		0.153	<0.02	0	2	3.11	88.8	94	55.1