Silver Quest Resources Ltd.

2010 GEOLOGICAL, GEOCHEMICAL, GEOPHYSICAL AND DIAMOND DRILLING REPORT ON THE PROSPECTOR MOUNTAIN PROPERTY, YUKON

Volume I – Text

Whitehorse Mining District
NTS 115I/05
62˚27' N Latitude; 137˚52' W Longitude

Claims: HAYES 1 to HAYES 271
YB66122-YB66233
YB97090-YB97216
YD33632-YD33663

Work Conducted June 20 to September 29, 2010

-prepared for-

SILVER QUEST RESOURCES LTD.
Suite 1410, 650 West Georgia Street
Vancouver, British Columbia, Canada V6B 4N8

-prepared by-

Darcy Baker, Ph.D., P.Geo
EQUITY EXPLORATION CONSULTANTS LTD.
Suite 200, 900 West Hastings Street
Vancouver, British Columbia, Canada, V6C 1E5

January, 2011

EQUITY

TABLE OF CONTENTS

TABLE OF CONTENTS 1
LIST OF APPENDICES 2
LIST OF TABLES 2
LIST OF FIGURES 2
1.0 SUMMARY 3
2.0 INTRODUCTION 3
3.0 RELIANCE ON OTHER EXPERTS 3
4.0 PROPERTY DESCRIPTION AND LOCATION 4
5.0 ACCESSIBILITY, CLIMATE, LOCAL RESOURCES, INFRASTRUCTURE, PHYSIOGRAPHY 4
6.0 HISTORY 7
6.1 2010 Exploration Programme 9
7.0 GEOLOGICAL SETTING 9
7.1 Regional Geology 9
7.2 Property Geology 11
7.3 Hydrothermal Activity at Prospector Mountain 11
8.0 GEOCHEMISTRY 14
8.1 Sampling 14
8.2 Soil Geochemistry 14
8.3 Rock Geochemistry 15
9.0 GROUND MAGNETIC GEOPHYSICS 17
10.0 DIAMOND DRILLING 17
10.1 Drill holes PM10-01 and PM10-02 18
10.2 Drill holes PM10-03 and PM10-04 18
10.3 Drill holes PM10-05 and PM10-06 19
10.4 Drill hole PM10-07 and PM10-08 19
11.0 DISCUSSION AND CONCLUSIONS 26
11.1 Deposit model 26
11.2 Exploration considerations 26
11.3 Recommendations 27
1.0 QUALITY ASSURANCE / QUALITY CONTROL 44
1.1 Chain of Custody 44
1.2 Blanks 44
1.3 Analytical Accuracy: Standard Performance 44
1.4 Analytical Precision: Duplicate Analysis 47
1.5 Conclusions 49

LIST OF APPENDICES

Appendix A: Bibliography
Appendix B: Statement of Expenditures
Appendix C: Claim Data
Appendix D-1: Soil Geochemical Certificates
Appendix D-2: Rock Geochemical Certificates
Appendix D-3: Core Geochemical Certificates
Appendix E: Rock Sample Descriptions
Appendix F: Drill Logs
Appendix G: Geophysical Report
Appendix H: Quality Control / Quality Assurance
Appendix I: Digital Data
Appendix J: Geologist's Certificate

LIST OF TABLES

Table 1: Prospector Mountain Exploration Programs 7
Table 2: Correlation Matrix for Select Elements for 2010 Soil Samples 15
Table 3: Soil Geochemistry Percentiles for Prospector Mountain Property 15
Table 4: 2010 Significant Rock Samples from Prospector Mountain 16
Table 5: Correlation Matrix for Select Elements for 2010 Rock Samples 16
Table 6: Screen Metallic Analyses for 2010 Rock Samples 16
Table 7: 2010 Prospector Mountain Drill Hole Location Data 17
Table 8: 2010 Prospector Mountain Drill Intersections 17

LIST OF FIGURES

Figure 1: Prospector Mountain Project Location Map 5
Figure 2: Prospector Mountain Project Tenure 6
Figure 3: Prospector Mountain Project Regional Geology 10
Figure 4: Prospector Mountain Compilation Map ..... map pocket
Figure 5: Bonanza Zone Soil and Rock Geochemistry ..... map pocket
Figure 6a: Drill Section PM10-01, -02 20
Figure 6b: Drill Section PM10-07, -08 21
Figure 6c: Drill Section PM10-03 22
Figure 6d: Drill Section PM10-04 23
Figure 6e: Drill Section PM10-05 24
Figure 6f: Drill Section PM10-06 25

LIST OF PLATES

Plate 1: Tourmaline altered quartz monzonite 12
Plate 2: Hydrothermal breccia with tourmaline cement 12
Plate 3: Gold-bearing quartz-specular hematite vein 13
Plate 4: Open-space epithermal veins 13
Plate 5: Banded, chalcedonic quartz vein 14
Plate 6: Mineralized core from PM10-01 18

1.0 SUMMARY

During the 2010 field season, Equity Exploration Consultants Ltd. completed a two-phase exploration programme at the Prospector Mountain project on behalf of Silver Quest Resources Ltd. During June and July, a three-person crew fly-camped on the property and completed rock (84 samples) and soil (221 samples) sampling, geological mapping and a ground magnetic survey. In September, an eight-hole (1463 m) diamond drilling programme was completed across the N-NW-trending gold (in rock and soil) anomalies of the Bonanza Zone. Minor prospecting (5 rock samples) was also completed during the drilling campaign.

These programmes were completed to further evaluate the Bonanza Zone, which was discovered in 2009 during prospecting in areas previously thought to have high potential for porphyry Cu-Mo+/-Au deposits. Instead, numerous rocks returned high-grade gold values from veins so attention was turned to the gold in vein potential.

Results of the 2010 programmes show that several elongate regions on surface contain sub-cropping vein boulders characterised by specular hematite and vuggy quartz with associated tourmaline and sericite alteration hosted by the Prospector Mountain suite monzonite. Rock samples from these boulder trains locally return highly elevated gold (corroborating the 2009 samples) whereas other samples of veined material return much lower grade. Numerous elements show positive correlation with Au including Ag, As, Bi, Co, Cu, Fe, Ni and U. The hydrothermal solutions responsible for these veins caused magnetite-destruction in the host rocks so the veins and mineralized zones form regions of low magnetic susceptibility in core and linear magnetic lows on surface.

Drilling below the surface soil and rock anomalies failed to return bonanza gold grades. The highest values returned in the drilling were 3.48 g/t Au over 3.40 m (PM10-01) whereas the broadest mineralized interval returned 0.76 g/t Au over 11.2 m (PM10-05).

In spite of drilling results that returned lower grades than surface samples, much potential exists within the Bonanza Zone. Soil sampling coverage needs to be expanded and some in-fill sampling within anomalous zones is also recommended to further delineate the Bonanza Zone. The ground magnetic geophysical coverage should also be expanded to extend the trends of magnetic lows. Expanding these datasets in combination with further mapping and prospecting should be completed to refine further drilling targets. In particular, the Bonanza Zone north of PM10-01 has not been adequately covered by soil sampling.

The potential of the Prospector Mountain property to host porphyry-style mineralization seems low. No porphyry-style mineralization or alteration was observed within the Bonanza Zone despite this area being labelled as a porphyry target for several decades. Precious metal-bearing veins seem to hold the best potential on the property. It is unclear how the poly-metallic veins in the western part of the property relate to the Bonanza Zone veins but they likely formed contemporaneously. The region-wide Carmacks volcanic suite-aged (ca. 70 Ma) hydrothermal event likely formed the Bonanza Zone veins. This important event in the southern Yukon formed the Casino porphyry deposit to the northwest and the porphyry and vein deposits at Mt. Nansen to the southeast.

2.0 INTRODUCTION

Equity Exploration Consultants Ltd. (“Equity”) was contracted by Silver Quest Resources Ltd. (“Silver Quest”) to carry out an exploration program in the summer of 2010 on the Prospector Mountain property. This program was carried out under the author’s direction and Silver Quest requested that Equity compile, interpret and report on the results. Information used in this report comprises government reports and maps, data from earlier assessment reports and data collected during the 2010 field program.

3.0 RELIANCE ON OTHER EXPERTS

In writing this report, I have not relied on a report, opinion or statement of any expert for information concerning legal, environmental, political or other issues.

4.0 PROPERTY DESCRIPTION AND LOCATION

The Prospector Mountain property lies within the Whitehorse Mining District, 88 km west-northwest of Carmacks in central Yukon (Figure 1). It is centred at 62°26' north latitude and 139°52' west longitude on the Prospector Mountain map sheet (NTS map sheet 115I/05). It comprises 271 contiguous quartz mineral claims covering approximately 43 km^2, as listed in Appendix C and shown on Figure 2. The claim boundaries are defined by the locations of claim posts on the ground, which have not been surveyed.

Silver Quest was granted the right to acquire up to a 70% interest in 239 contiguous quartz claims (HAYES 1 to 239) comprising the Prospector Mountain property by Tarsis Resources Ltd. ("Tarsis") in December, 2009. Under the terms of this agreement, Silver Quest must a) make cash payments totalling $300,000, b) issue 1,000,000 common shares and c) complete $4,000,000 in exploration work on the property over a four year period in order to earn an initial 60% interest in the property. Silver Quest can elect to earn an additional 10% interest by completing a feasibility study within 36 months of earning its 60% undivided interest. The property is subject to a 2% NSR in favour of Almaden Minerals Ltd. and Republic Resources Ltd. who sold the property to Tarsis. These underlying vendors are also entitled to receive 500,000 common shares (pro-rated between Silver Quest and Tarsis according to percentage interest) within three days of delivery of a bankable feasibility study.

Silver Quest expanded the property to the east in March, 2010. This area was covered with 32 additional claims (HAYES 240 to 271).

Surface rights over the Prospector Mountain property are owned by the Yukon Territory. No significant surface disturbances, other than the current drilling program, nor any major environmental liabilities were noted during the author's field visits. Depending on the nature of the program, exploration permits may be required from the Yukon Department of Energy, Mines and Resources prior to carrying out exploration on the property. The Mining Lands Branch of the Yukon Department of Energy, Mines and Resources granted a Class 3 permit (approval number LQ00286) to Silver Quest on July 29, 2010 which expires July 28, 2015. This permit approves trenching, drilling and a camp of up to 25 persons.

Surrounding the property to the north, west and south is a Selkirk First Nations block of settlement land withdrawn from staking (block R-7A).


5.0 ACCESSIBILITY, CLIMATE, LOCAL RESOURCES, INFRASTRUCTURE, PHYSIOGRAPHY

The Prospector Mountain property is located 88 km west-northwest of Carmacks. A network of gravel roads and trails provide access to the property via the Freegold Road which runs west from Carmacks to within 30 km of the property. From there a bulldozer trail known as the Lilypad road continues to the property. The trail is rugged but can be traversed by All Terrain Vehicle (ATV) and bulldozer, but would require upgrading for 4x4 vehicle use. This trail was used in 1999 to mobilize a diamond drill to the property.

The property covers Prospector Mountain to the east, the headwaters of Hayes Creek in the centre and Apex Mountain to the west. Most of the property is above treeline and covered by alpine vegetation since elevations on the property range from 1128 m to 1965 m. Lower slopes are covered by dwarf willow, alder and spruce trees, while north and east facing slopes are generally underlain by permafrost.

The area escaped continental glaciation, but has undergone some alpine glaciation. Because of the lack of glaciation and the effects of permafrost, outcrops are rare. Ridge tops and slopes are generally covered by subcrop, felsenmeer and talus.

Prospector Mountain is one of the highest mountains in the Dawson Range so temperatures tend to be depressed relative to other nearby areas. In 2010, daytime highs during June and July typically reached a maximum of about 20°C, with night-time temperatures of about 10°C. During the September drilling campaign, winter conditions hit Prospector Mountain sooner than other areas. Temperatures varied widely but got as low as -15°C and considerable snow fall occurred in early September.



0 150 300

kilometres


Silver Quest Resources Ltd.

Prospector Mountain Project

Location Map

EQUITY

Date: January 2010	Scale: 1:7,000,000	Figure 1
U.T.M. Zone: UTM 8 - NAD83	Mining District: Whitehorse	
N.T.S.: 115I/05	Province: Yukon	


346,000 mE
348,000 mE
350,000 mE
352,000 mE
354,000 mE
356,000 mE
358,000 mE
6,930,000 mN
6,928,000 mN
6,926,000 mN
6,924,000 mN
6,000
5,500
5,000
4,500
0 500 1,000
metres
Scale 1:50,000
N
Silver Quest Resources Ltd.
Prospector Mountain Project
Tenure Map
EQUITY
Date: January 2010
Scale: 1:50,000
Figure 2
U.T.M. Zone UTM 8 - NAD83
Mining District Whitehorse
N.T.S. 115I/05
Province Yukon

6.0 HISTORY

The earliest recorded mineral exploration in the Prospector Mountain area occurred during the 1960s. Since then, several phases of exploration have focused on the porphyry and epithermal potential of the area utilizing silt, soil and rock geochemistry, bulldozer trenching, geophysics and diamond drilling. Table 1 summarizes all known exploration work carried out on the ground currently comprising the Prospector Mountain property.

Table 1: Prospector Mountain Exploration Programs

Geochemistry	Geophysics	Trenching and Drilling	Reference
International Mines Services Ltd. (1970)			
1435 soils (Cu, Pb, Mo only)	-	-	(Waugh, 1970)
Phelps Dodge of Canada Corporation Limited (1970)			
713 soils (Ag, Cu, Pb, Zn only)	-	-	(Smith, 1971)
Occidental Minerals Corporation of Canada (1971)			
3789 soils (Cu, Zn, Mo only), 213 rocks	-	2 hand trenches	(Allebone and Mehrotra, 1971)
Nat Joint Venture (1980)			
910 soils (Au, Ag, As, Pb only), 76 rocks	-	-	(Onasick and Archer, 1981)
Nat Joint Venture (1981)			
1384 soil, 706 rocks	-	133 trenches	(Archer, 1981)
Nat Joint Venture (1982)			
-	-	7 ddh (637 m)	(Eaton, 1982)
Troymin Resources Limited (1997)			
160 rocks, 146 soils, 34 silts	-	-	(Doherty and Ouellette, 1997)
Troymin Resources Limited (1998)			
38 rocks	10.9 km IP; 12.5 km ground mag; 10.0 km radiometric	-	(Casselman, 1998; Power, 1998)
Troymin Resources Limited (1999)			
7 rocks	-	2 ddh (336 m)	(Casselman, 1999)
Tarsis Resources (2009)			
248 soils, 62 rocks	-	-	(Wengzynowski, 2010)
Silver Quest (2010)			
221 soils, 84 rocks	48 km ground mag	8 DDH (1,463 m)	This report
Totals: ~11,000 soils, ~1,300 rocks, 18 silts	10.9 km IP; 60.5 km ground mag; 10.0 km radiometric	135 trenches; 17 DDH (2,436 m)	

International Mines Services Ltd. completed the first documented work in the area during the late 1960s. Work comprised stream sediment geochemistry which highlighted a number of drainages yielding elevated values for copper, lead and zinc. In summer 1970, International Mines followed up the regional stream sediment data with focused grid soil sampling (1435 soil samples at 125 m by 60 m spacing) (Waugh, 1970). The samples were only analyzed for copper, lead and molybdenum. In general the results were considered poor and no further work was recommended at that time.

During the fall of 1970, Phelps Dodge of Canada Corporation Limited performed soil geochemical sampling, prospecting and mapping west of the International Mines ground late in the 1970 season but concluded that no anomalies of significance were identified (Smith, 1971). Their work suggested that lead and zinc are positively correlated but poorly correlated with copper.

Occidental Minerals Corporation of Canada conducted grid soil sampling across a 6 x 6 km area, mapping and prospecting east of the International Mines ground in 1971 (Allebone and Mehrotra, 1971), including across the Bonanza Zone. Soil samples were completed at 200 or 400 feet spacing. Six individual northwest trending copper-zinc-molybdenum anomalies were outlined across the soil grid and follow-up Induced Polarization (IP) geophysics was recommended but not completed.

In 1979, some soil samples from 1969 that had only been analysed for copper, molybdenum and lead, were reanalysed for gold and silver by Archer Cathro. Results showed several silver anomalies which were staked and vended to the NAT Joint Venture (50/50 between Chevron Canada Limited and Armco Mineral Exploration Ltd.). Between 1979 and 1982 the property was expanded to a contiguous block of 590 claims and mapping and sampling of lineaments, 133 bulldozer trenches, 637 m of diamond drilling in 7 holes and airstrip construction were completed (Archer, 1981; Eaton, 1982; Onasick and Archer, 1981). This exploration focused on precious metal-bearing epithermal veins and over 50 were discovered on the property. These known veins are mostly associated with recessive north-easterly trending lineaments near ridge tops that are up to 200 m wide. The veins are composed of transparent, chalcedonic, cockade, drusy or massive quartz with variable concentrations of silver and gold-bearing sulphosalts, galena, chalcopyrite, sphalerite and pyrite. Disseminated and massive tourmaline is noted within some vein occurrences. Numerous showings discovered in this time frame yielded specimens containing multi-ounce silver and multi-gram gold. The best analyses were reported for select specimens containing up to 26.88 g/t Au and 8400 g/t Ag with 69.3% Pb.

The best results include 8 g/t Au across 3 m including a sub interval of 19.6 g/t Au across 1 m. Another hole returned 346 g/t Ag and 15.3% Pb across 0.3 m. Mineralized material generally comprised strongly leached gouge or sludge with minor remnants of quartz and carbonate. A 55 m wide tourmaline-quartz-pyrite breccia zone was intersected in LP82-3 but only averaged 25 ppb Au (Eaton, 1982).

The Prospector Mountain area was geologically mapped by a regional mapping program in 1986 (Payne et al., 1987) that covered three 1:50,000 map sheets (Colorado Creek, Selwyn River and Prospector Mountain sheets).

Troymin Resources Ltd. explored the eastern part of the Prospector Mountain property in the late 1990s, focusing on the porphyry potential (Casselman, 1998, 1999; Doherty and Ouellette, 1997). This work expanded the soil geochemical coverage on two small grids (Lightening and No Sweat) in the eastern part of the property, surveyed approximately 13.5 line km of Induced Polarization (IP) surveys and drilled 336 m of in two core holes. Both holes were located on the Lightening IP grid in the vicinity of inverted chargeability IP anomalies and historical Cu and/or Mo soil geochemical anomalies. Sufficient disseminated pyrite was encountered in monzonite to explain the IP chargeability anomalies but no significant base or precious metals were encountered.

In 2009, Tarsis Resources explored the property to assess the merits of the historical porphyry and vein targets (Wengzynowski, 2010). This work included broad alteration mapping and prospecting within the eastern part of the property and examination of several vein zones within the western part of the claim block. The majority of the gold-bearing rock samples collected from the eastern part of the property plot within a well defined north-northwesterly trending structural corridor termed the Bonanza Zone. It hosts a series of high-grade gold-silver-copper showings along a 1,200 m portion of the trend near the eastern contact between Prospector Mountain Suite monzonite and the Carmacks Suite volcanic rocks. Ten samples from this area returned between 14 and 82 g/t Au and, interestingly, soil samples from this area (Allebone and Mehrotra, 1971) had not been analysed for gold.

Several historic trenches on the western vein targets were re-sampled in 2009. Results generally supported historic results and individual samples returned up to 17.35 g/t Au, 557 g/t Ag and 33.8% Pb**.** All veins examined are hosted by Carmacks Suite volcanic rocks and are mostly associated with north to

northeast trending recessive lineaments. The veins consist of steeply-dipping, highly sheared quartz and multi-colour clay gouge containing varying amounts of arsenic oxides and lead sulphide/sulphate.

6.1 2010 Exploration Programme

Exploration in 2010 at Prospector Mountain was completed in two phases. Between June 26 and July 2 a three-person crew (prospector, soil sampler and geologist) established a fly camp at the headwaters of Star Creek from a base at Boulevard Camp about 100 km to the northwest. The program focused on rock sampling in the areas of significant gold-in-rock results from 2009, geological mapping, soil sampling and ground magnetic surveying. 221 soil samples were collected in a grid across the core of the Bonanza Zone and 84 rock samples were collected.

As a follow-up to the early summer programme, an eight-hole diamond drilling programme, totalling 1463 m of NQ core, was completed in September. Mobilization and construction of a drill camp on Star Creek began August 29 from a staging area on the Freegold Road. The drill was mobilized on September 4 and drilling was done between September 6 and 24. A camp-based Hughes 500D helicopter from Prism Helicopters of Pitt Meadows, B.C. supported the program and Apex Diamond Drilling of Smithers, B.C. provided drilling services. Core was logged and split with a mechanical splitter at a core facility established at the camp site. Core remains cross-stacked at the camp site near Star Creek.

7.0 GEOLOGICAL SETTING

7.1 Regional Geology

The property lies within the Dawson Range part of the Yukon Tanana Terrain which is comprised of Devonian and older meta-igneous and metasedimentary rocks with a lower metasedimentary unit (quartzite, schist, meta-greywacke, argillite, slate, conglomerate, re-crystallized limestone, meta-volcanic rocks) and an upper quartz-feldspathic schist unit (schistose volcanic rocks and gneissic plutonic rocks) (Payne et al., 1987).


The Dawson Range area has been intruded by several plutonic suites but is dominated by the mid-Cretaceous, ca. 104 Ma (Selby and Creaser, 2001), Dawson Range Batholith. This voluminous intrusion extends approximately 300 km from Carmacks to the Alaskan border and is typically 60 km wide, composed of biotite-hornblende granodiorite (Payne et al., 1987).

The Prospector Mountain suite (Johnston, 1995) represents late Cretaceous (ca. 70 Ma) magmatism and intrudes the Dawson Range batholith generally as small stocks. Compositionally these are typically plagioclase-biotite and K-feldspar porphyritic rocks and are associated with porphyry Cu-Mo+/-Au mineralization at Casino, Cash and Mt. Nansen (Selby and Creaser, 2001).

Two volcanic suites are widespread in the region and include the ca. 108 Ma Mount Nansen suite to the south of the property and the ca. 70 Ma Carmacks suite which underlies much of the property. The Mount Nansen suite comprises high-K calc-alkaline bi-modal volcanic breccias (andesite and rhyolite). The Carmacks Suite comprises shoshonitic rocks including a lower succession of andesitic tuffs and breccias and an upper succession of basalt flows (Smuk et al., 1997). The intrusive Prospector Mountain suite quartz monzonite is apparently co-magmatic with the Carmacks suite (Smuk et al., 1997). The only available date for the Prospector Mountain suite is a K/Ar date of 68.2 +/- 1.6 Ma (Templeman-Kluit, 1984).

The dominant structure in the area is the northwest-trending Big Creek Fault 4 km northeast of the Bonanza Zone. Numerous north- to northeast-trending minor structures may be splays off the Big Creek Fault.

The region has numerous porphyry-style mineral deposits associated with Cretaceous porphyritic stocks, the most significant of which is the Casino Porphyry copper-gold-molybdenum deposit. Published reserves at Casino are 914 M tonnes grading 0.237 g/t Au, 0.212% Cu and 0.0236% (Giroux and Casselman, 2010).


345,000 mE
350,000 mE
355,000 mE
360,000 mE
365,000 mE
6,940,000 mN
6,935,000 mN
6,930,000 mN
6,925,000 mN
6,920,000 mN
mKW
LKP
uKC
DMPW
DMN
EJgA
EJL
mKN
Symbols
Prospector Mountain Claims
Contact
Fault
Geology
Cretaceous/Paleogene
PROSPECTOR MOUNTAIN SUITE; Quartz-bearing monzonite
Cretaceous
uKC uKW mKN
CARMACKS GROUP: Mafic to intermediate volcanics
DAWSON RANGE BATHOLITH Biotite-hornblende quartz monzonite to granodiorite
Jurassic
Early Jurassic granodiorite/diorite/ monzodiorite
Early Juarassic Syenite
Devonian/Mississippian
DMN DMPW
WOLVERINE CREEK METAMORPHIC ASSEMBLAGE
DMN: Mica Schist and Quartaite;
DMPW: Meta-igneous schist and gneiss
Geology after Johnston (1995)
0 500 1,000
metres
Scale 1:50,000
N
Silver Quest Resources Ltd.
Prospector Mountain Project
Regional Geology
EQUITY
Date: January 2010
Scale: 1:150000
Figure 3
U.T.M. Zone UTM 8 - NAD83
Mining District Whitehorse
N.T.S. 115I/05
Province Yukon

7.2 Property Geology

The property is underlain by volcanic rocks of the ca. 70 Ma Carmacks Suite which comprise a variety of andesite and basaltic tuffs, breccias and flows. The core of the property is underlain by quartz monzonite of the Prospector Mountain suite which forms an irregular east-west band surrounded by Carmacks suite rocks. The monzonitic body generally contains biotite and hornblende phenocrysts and has textures from equigranular to porphyritic with potassium feldspar phenocrysts up to 2 cm long. Numerous, late stage, andesite dykes intrude the quartz monzonite on the ridge west of the Prospector Mountain peak. The dykes are up to 20 metres wide and appear to follow north trending, steeply dipping, structures. Some dykes exhibit intense hydrothermal clay alteration and contain fine felted tourmaline rosettes. Similar dykes were encountered in most of the 2010 drill holes and these typically exhibit lower magnetic susceptibility than surround quartz monzonite.

The Prospector Mountain suite has not been directly dated but field relations suggest that at least part of the Carmacks volcanic suite was emplaced after crystallization of the plutonic body based on common andesite dykes that cut the monzonite. The current interpretation is that the extrusion of the Carmacks suite rocks overlapped in time with intrusion of the quartz monzonite.

Both of these main rock types underlying the property are strongly magnetic where unaltered. Outcrop exposures are rare but the area is characterized by frost-heaved, blocky subcrop and felsenmeer which underlies about 60% of the property. Intervening grassy patches separate lichen-covered subcrop areas. In general, subcrop appears to delineate the underlying outcrop patterns quite well. The Carmacks suite and Prospector Mountain suite rocks are undeformed apart from minor joints and faults which are probably common based on drilling but are poorly exposed at surface.

Common structural trends in the Bonanza Zone are generally N-S, although less common NNW and NNE trends also exist. In general the N-S trends are through-going whereas the NNW trends are less continuous. They are easily mapped as through-going linear depressions on ridge crests and are easily distinguished on available airphotos. Similarly in the western part of the property - where the NAT Joint Venture explored for veins generally through lineament prospecting – NE trending lineaments are more through-going while NNE lineaments are generally discontinuous (Eaton, 1982).

7.3 Hydrothermal Activity at Prospector Mountain

Typically, both the monzonite and andesite are unaltered. Minor chloritisation of hornblende in the monzonite is widespread but may just be a retrograde effect (i.e. metasomatic origin is not conclusive). The reported potassic altered zone (Wengzynowski, 2010) was not observed.

Locally, however, both units are altered by tourmaline which occurs as isolated radiating aggregates (Plate 1), massive replacements across a few centimetres and as hydrothermal breccia cement (Plate 2). This is clearly a metasomatic phase as tourmaline is associated with quartz-specular hematite veins as patches within the veins and as alteration selvedges along vein margins.

These vuggy quartz veins with specular hematite and tourmaline are the main target within the Bonanza Zone. Several of the high-grade samples from 2009 are strongly limonitic versions of these veins but some fresher samples also returned high-grade gold (Plate 3). Significantly, this style of veining occurs within several linear trends**.** Outcrops located in the eastern part of this mapped area contain two of these veins in situ where they strike 190^{o} and dip 85^{o}. This trend is consistent with the interpreted overall trend of the Bonanza Zone and is concordant to the linear vein float regions mapped.

Locally these veins contain up to 8% coarse-grained pyrite, have moderately sericitised wallrock, exhibit open-space epithermal-style textures (Plate 4) and chalcedonic banding (Plate 5) or cockscomb quartz locally with amethyst.



Plate 1: Tourmaline-altered monzonite. Black patches are radiating clusters of fine tourmaline possibly after hornblende.



Plate 2: Black tourmaline cemented hydrothermal breccia. Moderately sericitised monzonite wallrock.



Plate 3: Quartz-specular hematite vein with tourmaline-altered monzonite wallrock. Sampled in 2009 and returned 25.4 g/t Au (sample H886468).



Plate 4: Open-space, quartz-druse lined epithermal textures with local silica boxwork (lower left) associated with pyrite and silicification.



Plate 5: Chalcedonic quartz banding with layers of weathered pyrite.

The Bonanza Zone host rocks (monzonite and andesite) are typically strongly magnetic. Quartz-hematite veins and adjacent tourmaline-altered or sericitised wallrock, however, are non-magnetic. It seems, therefore, that magnetite destruction is likely an effect of the gold-bearing hydrothermal fluid and that linear magnetic lows would comprise targets. This is supported by lower magnetic susceptibility within and around gold-bearing zones in drill core.

8.0 GEOCHEMISTRY

8.1 Sampling

Over the course of the seven day phase I program, the crew collected 84 rock samples and 221 soil samples. An additional five rock samples were collected during the phase II drilling campaign. Rock sampling focused on identifying further high-grade mineralization starting at the best sample sites from 2009. Nine E-W soil lines at 100 m line spacing and 25 m sample spacing were completed across the main area of high-grade Bonanza Zone samples. Soil development is poor so most of these samples are C horizon material gathered locally from rare scattered grassy patches trapping minimal fine material.

8.2 Soil Geochemistry

The soil results for gold show multi-line gold anomalies which trend NNW similar to the Bonanza Zone trend (Figure 5). These anomalies are defined by >20 ppb Au but are cored by soil samples returning >100 ppb Au. The gold soil anomalies are also generally coincident with magnetic linear lows.

Table 2: Correlation Matrix for Select Elements for 2010 Soil Samples

	Au	Ag	As	Bi	Cd	Ce	Co	Cs	Cu	Fe	Mo	Ni	Pb	Sb	Sn	U	V	W	Zn
Au	1.00																		
Ag	0.20	1.00																	
As	0.00	0.66	1.00																
Bi	0.52	0.54	0.12	1.00															
Cd	-0.02	0.59	0.64	0.12	1.00														
Ce	-0.04	0.13	0.16	0.08	0.27	1.00													
Co	0.09	0.14	0.10	0.08	0.28	0.42	1.00												
Cs	0.01	0.28	0.16	0.12	0.16	0.53	0.21	1.00											
Cu	0.27	0.47	0.05	0.52	0.15	0.14	0.28	0.06	1.00										
Fe	0.13	0.36	0.38	0.20	0.39	0.43	0.68	0.24	0.27	1.00									
Mo	-0.05	0.48	0.38	0.12	0.35	0.39	0.17	0.49	0.06	0.29	1.00								
Ni	0.12	-0.13	-0.16	-0.07	-0.06	-0.20	0.52	-0.33	0.16	0.32	-0.42	1.00							
Pb	0.01	0.74	0.78	0.22	0.77	0.23	0.14	0.25	0.17	0.36	0.51	-0.24	1.00						
Sb	0.16	0.50	0.23	0.30	0.30	0.07	0.11	0.15	0.26	0.34	0.29	0.02	0.44	1.00					
Sn	-0.01	0.05	0.01	0.07	0.02	0.27	0.05	0.43	0.04	0.16	0.10	-0.20	0.05	0.05	1.00				
U	-0.07	0.32	0.31	0.09	0.30	0.58	0.11	0.62	0.11	0.14	0.63	-0.50	0.40	0.09	0.21	1.00			
V	0.12	-0.08	-0.07	-0.03	0.06	-0.02	0.52	-0.25	0.14	0.60	-0.35	0.81	-0.13	0.13	-0.17	-0.42	1.00		
W	0.02	0.01	-0.05	0.03	0.01	0.09	0.01	0.36	-0.01	0.11	-0.05	0.01	-0.05	0.09	0.80	-0.03	0.02	1.00	
Zn	0.04	0.67	0.72	0.24	0.85	0.32	0.31	0.20	0.23	0.52	0.45	-0.09	0.88	0.37	0.06	0.39	0.05	-0.04	1.00

Table 3: Soil Geochemistry Percentiles for Prospector Mountain Property

Field	Percentile70	Percentile85	Percentile90	Percentile95	Percentile98
AuAA23_ppm	0.015	0.029	0.041	0.071	0.133
Ag_ppm	0.34	0.49	0.69	1.18	1.588
As_ppm	13	20.4	25.9	43.3	83.34
Ba_ppm	120	150	170	210	280
Bi_ppm	3.33	5.44	7.03	11	14.69
Cd_ppm	0.43	0.57	0.68	0.91	1.614
Ce_ppm	48.4	53.5	59.2	67.3	76.9
Co_ppm	11.4	12.6	13.2	14.1	16.98
Cr_ppm	41	47	51	59	64
Cu_ppm	51.9	74.2	80.8	114.5	182.5
Fe_%	3.27	3.45	3.55	3.8	4.18
Mn_ppm	934	1260	1460	1870	2416
Mo_ppm	1.82	2.89	3.51	5.25	6.3
Ni_ppm	21.7	24.6	26.8	28.3	30.36
Pb_ppm	60.5	78.6	97.9	150	360.4
Sb_ppm	0.92	1.26	1.45	2.19	2.76
U_ppm	7.84	12.15	13.25	19.8	26.94
V_ppm	80	87	91	101	107
W_ppm	0.68	0.79	0.91	1.07	1.446
Zn_ppm	112	139	155	213	273.6

8.3 Rock Geochemistry

Rock descriptions are attached in Appendix E and geochemical certificates are in Appendix D-2. In general, these results corroborate the 2009 bonanza-grade gold values (Wengzynowski, 2010). The 2010 rock samples (Table 4) are highlighted by two samples which returned 112 and 50 g/t Au as well as several other samples returning >1.0 g/t Au. Rock samples locally returned elevated values for other metals such as Ag, As, Bi, Cu, Sb and Pb. Not all veined samples, however, returned significant results so clearly the distribution of gold within the vein systems is not homogenous.

Statistically, Au is most strongly correlated with Bi, Co, Ni, Cu and Fe and is moderately correlated with Ag, As and U (Table 5).

Some minor particulate or free gold is evidenced by screen metallic analyses which were conducted on samples which returned greater than 10 g/t Au in initial fire assay. As shown in Table 6, the screen metallic analyses are about 10% higher than the standard fire assay values indicating minor free gold. This is consistent with petrographic work completed in 2009 which identified gold in thin section (Wengzynowski, 2010).

Table 4: 2010 Significant Rock Samples from Prospector Mountain

Samp_ID	Au (ppm)	Ag (ppm)	As (ppm)	Bi (ppm)	Cu (ppm)	Mo (ppm)	Pb (ppm)	Sb (ppm)	Zn (ppm)
I031029	**112.5**	**543**	278	3710	**1.63%**	20.5	1855	22.3	200
I031039	**50.1**	**470**	632	5000	**2.20%**	56	4410	86.8	340
I031040	19.7	29.6	469	882	1495	5.23	448	5.82	189
I031047	14.15	56.6	342	576	2110	38.7	665	29.3	100
I031033	6.42	**509**	515	1320	**3.16%**	1.82	1025	6910	441
I034464	3.43	47	189	841	38.6	1.23	207	2.3	23
I031026	2.93	36.3	74.8	291	151.5	1.92	152	55.2	44
I034470	1.615	153	576	7.18	1640	66.8	**1.68%**	2980	528
I034474	0.461	1.98	12.7	11.2	19.3	3.47	50.8	19.35	87
I034473	0.449	0.29	29.6	52.6	12.1	0.91	12.6	3.68	21
I031035	0.344	2.62	80.5	11.9	12.6	1.47	24.6	2.67	7
I034454	0.337	61.9	184	4.32	227	27.4	1385	316	393
I031046	0.316	3.95	76.5	208	740	16.8	497	5.18	84
I034471	0.305	1.42	31.9	1.2	12.3	3.59	40.2	9.72	11

Table 5: Correlation Matrix for Select Elements for 2010 Rock Samples

	Au	Ag	As	Bi	Cd	Ce	Co	Cs	Cu	Fe	Mo	Ni	Pb	Sb	Sn	U	V	W	Zn
Au	1.00																		
Ag	0.64	1.00																	
As	0.45	0.83	1.00																
Bi	0.85	0.73	0.62	1.00															
Cd	0.04	0.49	0.42	0.20	1.00														
Ce	-0.15	-0.31	-0.29	-0.17	-0.14	1.00													
Co	0.87	0.62	0.52	0.92	0.00	-0.14	1.00												
Cs	0.10	0.02	0.18	0.08	-0.06	0.29	0.11	1.00											
Cu	0.78	0.83	0.69	0.88	0.58	-0.20	0.76	0.05	1.00										
Fe	0.78	0.64	0.66	0.74	-0.04	-0.21	0.79	0.31	0.64	1.00									
Mo	0.21	0.40	0.45	0.28	-0.01	-0.07	0.24	0.01	0.25	0.31	1.00								
Ni	0.85	0.56	0.47	0.86	-0.02	-0.09	0.94	0.16	0.72	0.75	0.20	1.00							
Pb	0.29	0.71	0.67	0.38	0.14	-0.20	0.33	-0.05	0.42	0.39	0.49	0.30	1.00						
Sb	0.03	0.59	0.53	0.17	0.94	-0.17	-0.02	-0.08	0.55	0.00	0.11	-0.03	0.42	1.00					
Sn	0.16	0.18	0.22	0.30	-0.04	-0.10	0.32	0.27	0.20	0.43	0.24	0.31	0.09	-0.05	1.00				
U	0.62	0.82	0.79	0.82	0.22	-0.18	0.73	0.12	0.78	0.74	0.46	0.66	0.70	0.32	0.32	1.00			
V	0.48	0.42	0.50	0.71	0.01	0.00	0.73	0.50	0.54	0.63	0.24	0.69	0.28	-0.01	0.46	0.68	1.00		
W	0.48	0.39	0.42	0.46	-0.04	-0.20	0.49	0.21	0.37	0.65	0.09	0.55	0.26	0.00	0.66	0.44	0.46	1.00	
Zn	0.26	0.63	0.58	0.35	0.43	-0.12	0.37	0.02	0.48	0.33	0.29	0.27	0.59	0.51	0.04	0.52	0.41	0.18	1.00

Table 6: Screen Metallic Analyses for 2010 Rock Samples

	Au-SCR21	Au-SCR21	Au-SCR21	Au-AA25	Au-AA25D
SAMPLE	Au Total (+)(-) Combined	Au (+) Fraction	Au (-) Fraction	Au	Au
DESCRIPTION	ppm	ppm	ppm	ppm	ppm
I030962	19.4	20.2	19.4	20.2	18.55
I031029	109	323	90.3	81.7	98.8
I031039	53	178.5	46.5	47.2	45.8
I031040	20.3	173.5	17.9	17.4	18.35
I031047	12.55	28.2	12.15	12.6	11.7
I031060	5.97	115.5	3.3	3.28	3.32

9.0 GROUND MAGNETIC GEOPHYSICS

19 E-W transect lines of ground magnetic geophysics was completed across the Bonanza Zone for a total of 27.9 line km between June 28 and July 2, 2010. This survey was designed by Francis Moul, geophysicist for Silver Quest. Moul's logistics and interpretation report provides the details of this survey and is presented in Appendix G.

Additionally, I have added interpreted structures based on interpretation of the total magnetic intensity map, drill intercepts, surface mapping and surface lineaments. These are shown on Figure 4 and generally comprise through-going, N-S trending magnetic lows inter-connected by discontinuous magnetic lows that truncate regions of higher magnetics. Together these interpreted structures form a network of structures consistent with a series of N-S faults with conjugate, possibly extensional, second-order faults.

10.0 DIAMOND DRILLING

Eight holes (1463 m) were drilled across the Bonanza Zone anomalies in 2010 from eight different drill set-ups on six different sections (Figures 4 & 6). Collar locations and survey information are provided in Table 7 and drill logs in Appendix F. Intervals of geochemically significant mineralization are summarized in Table 8. Sample intervals were selected based on mineralogical and lithological variations. Each drill run was measured for RQD, recovery and magnetic susceptibility and core was logged into Lagger software. Collar locations were recorded from a hand-held Garmin GPS60.

Table 7: 2010 Prospector Mountain Drill Hole Location Data

Hole ID	Target / Objective	Easting	Northing	Elevation	Length (m)	Azimuth	Dip
PM10-01	Bonanza Zone; complete fence across broadest part of anomaly with PM10-02	354988	6928037	1809 m	197.82	080°	-45°
PM10-02	Bonanza Zone; complete fence across broadest part of anomaly with PM10-01	354908	6928024	1780 m	203.91	080°	-45°
PM10-03	Southern end of Bonanza Zone near highest grade float samples	355140	6927533	1833 m	236.53	080°	-45°
PM10-04	Southern end of Bonanza Zone near highest grade float samples; step out SE from PM10-03	355172	6927498	1811 m	186.31	080°	-50°
PM10-05	Bonanza Zone; middle part	355044	6927795	1836 m	158.19	080°	-45°
PM10-06	Bonanza Zone; middle part	355023	6927890	1836 m	206.96	080°	-45°
PM10-07	Bonanza Zone; complete fence across broad part of anomaly with PM10-08	355009	6927993	1834 m	146.00	080°	-45°
PM10-08	Bonanza Zone; complete fence across broad part of anomaly with PM10-02	355074	6928000	1840 m	127.71	080°	-45°
				TOTAL	1463.43		

Table 8: 2010 Prospector Mountain Drill Intersections

Drill Hole	From (m)	To (m)	Interval (m)	Au (g/t)
PM10-01	77.40	81.90	4.50	2.68
including	77.40	80.80	3.40	3.48
PM10-05	77.80	89.00	11.20	0.76
including	79.80	82.69	2.89	2.25
PM10-06	75.90	78.70	2.80	0.49
PM10-06	172.63	174.00	1.37	1.44
PM10-07	36.27	38.62	2.35	0.15
PM10-08	41.23	41.70	0.47	2.58

*Note: True widths are estimated to be 80 to 90% of the mineralized intervals.

10.1 Drill holes PM10-01 and PM10-02

Together, PM10-01 and -02 (Figure 7a) complete a fence across the broadest part of the Bonanza Zone soil anomaly (Figure 5). Both holes intersected Prospector Mountain suite quartz monzonite throughout. Locally, this plutonic phase is cut by light grey, fine-grained andesite dykes with feldspar and hornblende phenocrysts and typically with 4% fine-grained disseminated pyrite and slightly lesser disseminated magnetite. These dykes typically have chilled margins and vary from 3 to 13 m wide in core length.

Hole PM10-01 intersected a vuggy quartz vein with associated specular hematite stringer veins and mottled tourmaline alteration at about 80 m depth. The highest grade sample returned 10.1 g/t Au over 0.57 m from 78.75 m within a broader interval of 4.5 m of 2.68 g/t Au (Table 8). Some pathfinder elements are also weakly elevated in this interval including Ag (up to 15 g/t), As (up to 381 ppm), Bi (547 ppm), Mo (up to 22.3 ppm), U (up to 32 ppm) and W (up to 330 ppm). The mineralized interval is strongly oxidised to limonite (Plate 6). Eaton (1982) reported similar strong oxidation of mineralized intervals to depths of 150 m in the 1982 drill holes in the western part of the property.



Plate 6: Core photograph of mineralized interval in PM10-01 showing intensity of limonite (weathering). The sample tag at the upper right of the box marks 77.40 m - the beginning of the mineralized interval. The pale grey, vuggy quartz vein occurs on both sides of the “78.94” marker block.

Hole PM10-02 did not intersect any significantly mineralized interval. Possibly this hole would have been better targeting the eastern (upslope) side of the Bonanza Zone soil and rock anomaly.

10.2 Drill holes PM10-03 and PM10-04

Holes PM10-03 and -04 (Figures 6c & 6d) targeted the southern portion of the central Bonanza Zone soil anomaly. These holes were designed to test the anomaly beneath some of the highest grade rock samples (float) collected on the property (Figure 5).

Both holes intersected Prospector Mountain suite quartz monzonite and two fine-grained, porphyritic andesite dykes occur in PM10-03.

Both holes encountered local narrow intervals of specular hematite stringer veins with associated tourmaline alteration and bleaching (sericitisation) but gold and other metal values were nearly uniformly low. The highest gold value was from the sample of 152.0-154.0 m in PM10-03 which returned 1.23 g/t Au from the Au-AA23 (standard fire assay) analysis. A check analysis and the fire assay with gravimetric finish analysis (GRA-21) for this sample returned 0.15 and 0.25 g/t Au respectively suggesting a nugget effect.

Several broad intervals of fault gouge – particularly in PM10-04 – hampered drilling and core recovery in these holes. These structures are late and post-date the specular hematite mineralization. It is possible these gouge zones represent fault structures that may have dismembered the Bonanza Zone.

10.3 Drill holes PM10-05 and PM10-06

Holes PM10-05 and -06 were drilled near the central part of the Bonanza Zone, about mid-way between PM10-01 and -02 to the north and PM10-03 and -04 to the south. Both holes intersected quartz monzonite cut by several porphyritic andesite dykes (Figures 6e & 6f).


The broadest interval of anomalous gold was encountered in PM10-05 starting at 77.80 m. This 11.20 m interval returned 0.76 g/t Au and the highest grade sample in this interval returned 6.49 g/t Au over 1.0 m. This sample also returned elevated pathfinder elements including Ag (70 g/t), As (229 ppm), Bi (500 ppm), Cu (0.12%), Pb (654 ppm), Sb (215 ppm), U (47 ppm) and W (167 ppm). The interval is characterised by strong manganese staining, rare specular hematite stringer veins and a 30 cm wide, vuggy, oxidised (intense limonite) quartz vein at 82.30 m.

Two narrower mineralized intervals were intersected by PM10-06: 2.80 m of 0.49 g/t Au starting at 75.90 m and 1.37 m of 1.44 g/t Au starting at 172.63 m. The lower interval also returned 0.36% Cu, consistent with the presence of malachite. Both intervals are characterized by minor specular hematite and tourmaline alteration. The occurrence of two widely spaced mineralized zones in PM10-06 indicates that multiple mineralized structures are present within the Bonanza Zone, consistent with surface geological, geochemical and geophysical interpretations.

10.4 Drill hole PM10-07 and PM10-08

These holes form a fence across the broader part of the central Bonanza Zone soil anomaly about 75 m south of the fence formed by PM10-01 and -02. Both holes encountered quartz monzonite of the Prospector Mountain suite as well as dykes of porphyritic andesite (Figure 6b).

Both holes intersected minor mineralization (Table 8) associated with specular hematite and tourmaline alteration within a steeply west-dipping zone of altered and fractured quartz monzonite.



Silver Quest Resources Ltd.

Scale 1 : 1500	Prospector Mtn
Projection:UTM 8 NAD83	**Drill Section PM10-01_02**
Mining District: Whitehorse	**Looking 350°**
Prov/State: Yukon	**+/- 10m**
Plot Date: 18-Jan-2011	
Figure: 6a	

EQUITY

0 10 20 30 40m

Legend


Au ppm - Soils	Au ppm - Rocks
-0.005 to 0.005	< 0.1
0.005 to 0.020	0.1 to 1
0.020 to 0.050	1 to 5
0.050 to 0.133	5 to 10
>= 0.133	10 to 20
	>= 20

Late Cretaceous
Carmacks Volcanic Suite
- Andesite
- Andesite dyke

Prospector Mountain Suite
- Quartz Monzonite
- Altered (sericite-limonite) quartz monzonite
- Faulted, fractured Quartz Monzonite

Hydrothermal
- quartz vein
- Sub-cropping quartz-hematite-tourmaline veins

Other
- casing
- 20 ppm Au in Soil Anomaly



Silver Quest Resources Ltd.

Scale 1 : 1500	Prospector Mtn
Projection:UTM 8 NAD83	
Mining District: Whitehorse	**Drill Section PM10-07_08**
Prov/State: Yukon	**Looking 350°**
Plot Date: 18-Jan-2011	**+/- 10m**
Figure: 6b	
EQUITY	0 10 20 30 40m

Legend

Au ppm - Soils	Au ppm - Rocks
-0.005 to 0.005	< 0.1
0.005 to 0.020	0.1 to 1
0.020 to 0.050	1 to 5
0.050 to 0.133	5 to 10
>= 0.133	10 to 20
	>= 20


Late Cretaceous
Carmacks Volcanic Suite
- Andesite
- Andesite dyke

Prospector Mountain Suite
- Quartz Monzonite
- Altered (sericite-limonite) quartz monzonite
- Faulted, fractured Quartz Monzonite

Hydrothermal
- quartz vein
- Sub-cropping quartz-hematite-tourmaline veins

Other
- casing

20 ppm Au in Soil Anomaly



Silver Quest Resources Ltd.

Scale 1 : 1500	Prospector Mtn
Projection:UTM 8 NAD83	**Drill Section PM10-06**
Mining District: Whitehorse	**Looking 350°**
Prov/State: Yukon	**+/- 10m**
Plot Date: 18-Jan-2011	
Figure: 6c	

EQUITY

0 10 20 30 40m

Legend


Au ppm - Soils	Au ppm - Rocks
-0.005 to 0.005	< 0.1
0.005 to 0.020	0.1 to 1
0.020 to 0.050	1 to 5
0.050 to 0.133	5 to 10
>= 0.133	10 to 20
	>= 20

Late Cretaceous
Carmacks Volcanic Suite
- Andesite
- Andesite dyke

Prospector Mountain Suite
- Quartz Monzonite
- Altered (sericite-limonite) quartz monzonite
- Faulted, fractured Quartz Monzonite

Hydrothermal
- quartz vein
- Sub-cropping quartz-hematite-tourmaline veins

Other
- casing
- 20 ppm Au in Soil Anomaly



Silver Quest Resources Ltd.

Scale 1 : 1500	Prospector Mtn
Projection:UTM 8 NAD83	**Drill Section PM10-05**
Mining District: Whitehorse	**Looking 350°**
Prov/State: Yukon	**+/- 10m**
Plot Date: 18-Jan-2011	
Figure: 6d	

EQUITY

0 10 20 30 40m

Legend

Au ppm - Soils	Au ppm - Rocks
-0.005 to 0.005	< 0.1
0.005 to 0.020	0.1 to 1
0.020 to 0.050	1 to 5
0.050 to 0.133	5 to 10
>= 0.133	10 to 20
	>= 20


Late Cretaceous
Carmacks Volcanic Suite
- Andesite
- Andesite dyke

Prospector Mountain Suite
- Quartz Monzonite
- Altered (sericite-limonite) quartz monzonite
- Faulted, fractured Quartz Monzonite

Hydrothermal
- quartz vein
- Sub-cropping quartz-hematite-tourmaline veins

Other
- casing

20 ppm Au in Soil Anomaly



Silver Quest Resources Ltd.

Scale 1 : 1500	Prospector Mtn
Projection:UTM 8 NAD83	**Drill Section PM10-03**
Mining District: Whitehorse	**Looking 350°**
Prov/State: Yukon	**+/- 10m**
Plot Date: 18-Jan-2011	
Figure: 6e	
EQUITY	0 10 20 30 40m

Legend

Au ppm - Soils
- -0.005 to 0.005
- 0.005 to 0.020
- 0.020 to 0.050
- 0.050 to 0.133
- >= 0.133


Au ppm - Rocks
- < 0.1
- 0.1 to 1
- 1 to 5
- 5 to 10
- 10 to 20
- >= 20

Late Cretaceous
Carmacks Volcanic Suite
- Andesite
- Andesite dyke

Prospector Mountain Suite
- Quartz Monzonite
- Altered (sericite-limonite) quartz monzonite
- Faulted, fractured Quartz Monzonite

Hydrothermal
- quartz vein
- Sub-cropping quartz-hematite-tourmaline veins

Other
- casing
- 20 ppm Au in Soil Anomaly



Silver Quest Resources Ltd.

Scale 1 : 1500	Prospector Mtn
Projection:UTM 8 NAD83	
Mining District: Whitehorse	**Drill Section PM10-04**
Prov/State: Yukon	**Looking 350°**
Plot Date: 18-Jan-2011	**+/- 10m**
Figure: 6f	
EQUITY	0 10 20 30 40m

Legend

Au ppm - Soils
- -0.005 to 0.005
- 0.005 to 0.020
- 0.020 to 0.050
- 0.050 to 0.133
- >= 0.133

Au ppm - Rocks
- < 0.1
- 0.1 to 1
- 1 to 5
- 5 to 10
- 10 to 20
- >= 20

Late Cretaceous
Carmacks Volcanic Suite
- Andesite
- Andesite dyke

Prospector Mountain Suite
- Quartz Monzonite
- Altered (sericite-limonite) quartz monzonite
- Faulted, fractured Quartz Monzonite

Hydrothermal
- quartz vein
- Sub-cropping quartz-hematite-tourmaline veins

Other
- casing
- 20 ppm Au in Soil Anomaly

11.0 DISCUSSION AND CONCLUSIONS

11.1 Deposit model

Gold-bearing veins within the Bonanza Zone are primarily hosted within fault / vein structures cutting quartz monzonite but also occur with Carmacks suite andesitic rocks. Both of these igneous suites are late Cretaceous (ca. 70 Ma) (Selby and Creaser, 2001; Smuk et al., 1997; Templeman-Kluit, 1984) and are probably co-magmatic. Field relations at Prospector Mountain (andesite dykes cutting quartz monzonite) support this, although the Prospector Mountain quartz monzonite is generally cited as intruding into Carmacks suite volcanic rocks (Payne et al., 1987). Since the Carmacks suite is a thick unit comprising basal and upper units, it is possible that the Prospector Mountain suite quartz monzonite intruded into the lower part of the Carmacks but the latest Carmacks volcanic rocks post-dated emplacement of the Prospector Mountain intrusive rocks.

Contemporaneous with the Carmacks event is a region-wide hydrothermal event (Wynne et al., 1998). Evidence for this includes widespread resetting of K/Ar systems at ca. 70 Ma, widespread gold-rich polymetallic epithermal veins across the southern Dawson Range (Smuk et al., 1997) and resetting of paleomagnetic systems (Wynne et al., 1998). This event is also responsible for porphyry Cu-Mo+/-Au systems including Mt. Nansen, Casino and others (Selby and Creaser, 2001; Smuk et al., 1997).

The Bonanza Zone veins, therefore, are most likely related to this region-wide hydrothermal event. They share many characteristics with veins in the Mt. Nansen camp and the western part of the Prospector Mountain property, including high levels of Ag-As-Sb-Cu, epithermal textures, spatial association with dykes, general north or northwesterly trend, occurrence in various rock types and an association with tourmaline (Hart and Langdon, 1997).

The Bonanza Zone veins, however, are characterized by higher gold grades and by a widespread association with specular hematite. Possibly this is a host-rock effect (most of the western Prospector Mountain veins are hosted by Carmacks rocks) or part of a poorly understood metal zonation in the vein systems. At Mt. Nansen, for example, vein style, metal endowment and alteration vary across a porphyry to epithermal transition (Hart and Langdon, 1997). The Mount Nansen camp hosts about 30 mineral occurrences and most recently saw mining between 1996 and 1999. The combined ore reserve (in all categories) prior to mining was stated to be one million tonnes of 7.4 g/t Au and 148 g/t Ag (Hart and Langdon, 1997).

11.2 Exploration considerations

Our current understanding of the Prospector Mountain veins is at an early stage but further exploration should evaluate these veins primarily as typical epithermal vein systems. Metal zonation (horizontal and vertical) should be evaluated and the structural architecture of the system(s) considered in terms of typical vein systems. For example, vein blow-outs, dilational fault offsets and vein intersections will make good drilling targets if they can be identified. Most brittle vein systems form in multiple orientations simultaneously but to date the Bonanza Zone veins seem only to trend northerly. If the structural interpretation of the 2010 ground magnetic grid is correct, however, a conjugate and possibly dilational set of veins may occur in NNW-trending structures. Further geophysics, soil sampling and mapping may positively identify conjugate or cross structures in the Bonanza system. Zonation from predominantly base metal-rich to predominantly precious-metal rich veins may occur across the Prospector Mountain property from the 1980s trenches in the west (base metal rich) to the recently identified veins in the Bonanza Zone (gold-rich, base metal poor).

A secondary consideration in exploring the Prospector Mountain property is its porphyry potential. Although this has previously been targeted with little success, the ca. 70 Ma Prospector Mountain suite intrusions are known to drive porphyry systems elsewhere in the Dawson Range (most notably at the ca. 900 M tonne Casino deposit). Work in 2010 in the Bonanza Zone suggests that no signs of a nearby porphyry system exist; however, this target still warrants consideration.

Dykes are an important aspect of the Mt. Nansen vein systems and, based on the 2010 drilling, also appear to be spatially associated with the Bonanza Zone vein system. At Mt. Nansen, polymetallic veins tend to occur near the widespread ca. 105 Ma Mt. Nansen suite dykes. Smuk et al. (1997) showed that this close spatial association is fortuitous, however, since the alteration of these dykes was a Late Cretaceous (i.e. Carmacks-aged) event. Thus the veins may not necessarily be genetically linked with the dykes, but probably share the same fluid conduits or zones of weakness that the dyke systems followed. As such, the location of dykes can be an important exploration tool and the distribution of dykes at Prospector Mountain may be an important indicator of vein location, even if veins or alteration are not present at the current erosional level.

Based on magnetic susceptibility of drill core, the dykes encountered at Prospector Mountain are magnetically low relative to the host quartz monzonite. The linear lows on the ground magnetic image could be dykes or, magnetite-destructive alteration zones, or possibly both. As such, all linear magnetic lows on the magnetic survey are of interest.

11.3 Recommendations

Further exploration of the Prospector Mountain Bonanza Zone is warranted. Prior to additional drilling, however, the following steps should be taken:

- **Expanded soil coverage**: full suite (ICP and Au fire assay) soil coverage has been shown effective in delineating the Bonanza Zone mineralized structures even though soil development within the alpine regions of the property is poor. The 2010 soil grid should be expanded considerably. Significantly, samples from the 36 km^2 / ~4000 sample soil grid completed in 1971 across the Bonanza Zone were not analysed for gold so very little gold-in-soil coverage exists in the eastern part of the property.
- **Expand magnetic grid**: the ground magnetic survey should be expanded both north and south of the current coverage.
- **Vein transition across the property**: field mapping (preceded by digital compilation) should evaluate the systematics of the western vein systems and compare these with the Bonanza Zone veins. The intervening central part of the property – much of which was not part of the NAT joint Venture ground – should also be evaluated since this area may record a transition from the base metal-rich to precious-metal rich veins.

Respectfully submitted,

_____

Darcy Baker, Ph.D., P.Geo.

EQUITY EXPLORATION CONSULTANTS LTD.

Vancouver, British Columbia

January 18, 2011

Appendix A: Bibliography

Allebone, G. C., and Mehrotra, P. N., 1971, Occidental Minerals Corporation of Canada, Geology and Geochemistry of the Pro Claim Group, Whitehorse Mining District., Assessment report 061108.

Archer, A. R., 1981, Nat Joint Venture, Geological, Geochemical and Geophysical Report, Lilypad 1-429 Claims and Newts 1-132, 135-163 Claims., Assessment Report 090976.

Casselman, S. G., 1998, 1998 Assessment Report on the Prospector Mountain Property, Troymin Resources Ltd., Assessment Report 093889.

Casselman, S. G., 1999, 1999 Assessment Report on the Prospector Mountain Property, Troymin Resources Ltd., Assessment Report 094037.

Doherty, R. A., and Ouellette, D., 1997, 1997 Assessment Report on the Hayes Property, Assessment Report 093748.

Eaton, W. D., 1982, Nat Joint Venture, Diamond Drilling Report, Lilypad 1-429 Claims and Newt 1-132, 135-163 Claims, Assessment Report 091435, p. 66.

Giroux, G., and Casselman, S., 2010, Casino Project 2010 Mineral Resource Update, Western Copper Corporation, p. 155.

Hart, C. J. R., and Langdon, M., 1997, Geology and mineral deposits of the Mount Nansen camp, Yukon: Yukon Exploration and Geology 1997, p. 129-138.

Johnston, S. T., 1995, Geological compilation with interpretation from geophysical surveys of the northern Dawson Range, central Yukon (115-J/9 and 115-J/10, 115-I/12, 1:100 000 scale map), Exploration and Geological Services Division, Yukon, Indian and Northern Affairs Canada, Open file 1995-2(G).

Onasick, E. P., and Archer, A. R., 1981, Geochemical and Geological Report, Nat Joint Venture, Lilypad 1-32 claims and Newt 1-6 claims, Assessment Report 090741.

Payne, J. G., Gonzalez, R. A., Akhurst, K., and Sisson, W. G., 1987, Geology of Colorado Creek (115J/10), Selwyn River (115J/9) and Prospector Mountain (115I/5) Map Areas, Indian and Northern Affairs Canada: Yukon Region, Open File 1987-3.

Power, M., 1998, Induced Polarization Survey at the Prospector Mountain Property, Carmacks Area, Yukon Territory, Troymin Resources Ltd., Assessment Report 093889, p. 37.

Selby, D., and Creaser, R. A., 2001, Late and mid-Cretaceous Mineralization in the Nothern Canadian Cordillera: Constraints from Re-Os Molybdenite Dates: Economic Geology, v. 96, p. 1461-1467.

Smith, F. M., 1971, Phelps Dodge Corporation of Canada, Ltd., Geological and Geochemical Report on the Hayes Creek Project Claims, PDY Group, Claim Sheet 115I5, Prospector Mountain Area, Yukon Territory., Assessment Report 061109.

Smuk, K. A., Williams-Jones, A. E., and Francis, S., 1997, The Carmacks Hydrothermal Event: An Alteration Study in the Southern Dawson Range, Yukon: Yukon Exploration and Geology 1996, p. 92-106.

Templeman-Kluit, D. J., 1984, Geology of the Lebarge and Carmacks Map Sheets, Geological Survey of Canada, Open File 1101.

Waugh, D. H., 1970, Geological Assessment Report on the Frog Claim Group, Hayes Creek – Dawson Range Area, Whitehorse Mining District, Yukon Territory., International Mine Services Ltd., Assessment Report 060605, p. 21.

Wengzynowski, W. A., 2010, Assessment Report describing Prospecting and Hand Trenching at the Prospector Mountain Property, Tarsis Resources Ltd., p. 25.

Wynne, P. J., Enkin, R. J., Baker, J., Johnston, S. T., and Hart, C. J. R., 1998, The Big Flush - Paleomagnetic signature of a 70 Ma regional hydrothermal event in displaced rocks of the northern Canadian Cordillera: Canadian Journal of Earth Sciences, v. 35., p. 657-671.

Appendix B: Statement of Expenditures

STATEMENT OF EXPENDITURES
PROSPECTOR MOUNTAIN PROPERTY
Fieldwork: June 26 - October 4, 2010

PROFESSIONAL FEES AND WAGES:				
Darcy Baker, P. Geo.				
21.84 days @ $650/day	$	14,196.00		
Tom Bell, Prospector				
7.00 days @ $475/day		3,325.00		
Thomas Branson, Geologist				
6.70 days @ $525/day		3,517.50		
Warren Gregory, Sampler				
1.00 day @ $275/day		275.00		
Stewart Harris, P.Geo.				
1.81 days @ $650/day		1,176.50		
William James, Sampler				
7.00 days @ $275/day		1,925.00		
Jill Marshal, Cook				
29.00 days @ $450/day		13,050.00		
Scott Parker, GIS/Logistics				
120.00 hours @ $75/hour		9,000.00		
Neil Rushton, Project Manager/First Aid				
30.00 days @ $525/day		15,750.00		
Colin Slauenwhite, Project Manager/First Aid				
17.38 days @ $575/day		9,993.50		
Sean Suttie, Senior Sampler				
1.00 day @ $325/day		325.00		
Ryan Toole, Project Geologist				
35.90 days @ $650/day		23,337.50		
Tyler Woyiwada, Sampler				
20.00 days @ $275/day		5,500.00		
Ron Voordouw, Ph.D.				
1.00 day @ $650/day		650.00		
Agata Zurek, GIS				
8.00 hours @ $75/hour		600.00		
Clerical				
113.00 hours @ $35/hour		3,955.00	$	106,576.00
EQUIPMENT RENTALS				
Field Camp				
374 days @ $40/manday	$	14,960.00		
Chainsaw				
15 days @ $30/day		450.00		
Field Computers				
96 days @ $40/day		3,840.00		
First Aid Equipment (Level III)				
36 days @ $30/day		1,080.00		
Generator				
35 days @ $80/day		2,760.00		
Rental Truck Insurance				
9 days @ $10/day		90.00		
Satellite Phones (Iridium)				
5 weeks @ $75.00/week		375.00		
8 minutes @ $1.89/min		15.12		23,570.12

STATEMENT OF EXPENDITURES

EXPENSES:			
Chemical Analyses	$	41,646.86	
Materials and Supplies		13,385.53	
Maps and Publications		7.00	
Plot Charges		385.21	
Camp Food		13,210.95	
Meals		750.76	
Accommodation		926.00	
Taxis and Airporters		153.25	
Truck Rental (Non-Equity)		2,400.00	
Automotive Fuel		879.13	
Aircraft Charters		12,244.50	
Helicopter Charters		150,756.25	
Telephone Distance Charges		0.03	
Freight		24,006.43	
Bulk Fuel		52,623.71	
Drum Deposits		10,867.26	
Geophysical Equipment Rental		1,175.00	
Pad Building		12,904.76	
Contract Construction		6,000.00	
Satellite Phone Rental (Non-Equity)		468.44	
Generator Rental (Non-Equity)		75.00	
Excavator		3,562.50	
Drilling: Mob/Demob		13,900.00	
Drilling: Footage		161,116.72	
Drilling: Materials		11,059.88	
Drilling: Coreboxes		2,203.75	
Expediting		13,112.34	
Report (Estimation)		5,000.00	554,821.26
SUB-TOTAL:			$ 684,967.38
PROJECT SUPERVISION CHARGES:			55,982.33
TOTAL:			**$ 740,949.71**

Appendix C: Claim Data

GrantNumber	ClaimName	ClaimNbr	ClaimOwner	RecordingDate	ExpiryDate
YB66122	HAYES	1	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66123	HAYES	2	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66124	HAYES	3	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66125	HAYES	4	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66126	HAYES	5	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66127	HAYES	6	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66128	HAYES	7	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66129	HAYES	8	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66130	HAYES	9	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66131	HAYES	10	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66132	HAYES	11	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66133	HAYES	12	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66134	HAYES	13	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66135	HAYES	14	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66136	HAYES	15	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66137	HAYES	16	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66138	HAYES	17	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66139	HAYES	18	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66140	HAYES	19	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66141	HAYES	20	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66142	HAYES	21	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66143	HAYES	22	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66144	HAYES	23	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66145	HAYES	24	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66146	HAYES	25	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66147	HAYES	26	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66148	HAYES	27	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66149	HAYES	28	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66150	HAYES	29	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66151	HAYES	30	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66152	HAYES	31	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66153	HAYES	32	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66154	HAYES	33	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66155	HAYES	34	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66156	HAYES	35	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66157	HAYES	36	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66158	HAYES	37	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66159	HAYES	38	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66160	HAYES	39	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66161	HAYES	40	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66162	HAYES	41	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66163	HAYES	42	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66164	HAYES	43	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66165	HAYES	44	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66166	HAYES	45	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66167	HAYES	46	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66168	HAYES	47	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66169	HAYES	48	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66170	HAYES	49	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66171	HAYES	50	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66172	HAYES	51	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66173	HAYES	52	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66174	HAYES	53	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66175	HAYES	54	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66176	HAYES	55	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66177	HAYES	56	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66178	HAYES	57	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66179	HAYES	58	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66180	HAYES	59	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66181	HAYES	60	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66182	HAYES	61	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66183	HAYES	62	Tarsis Capital Corp. - 100%.	19950908	20130408

GrantNumber	ClaimName	ClaimNbr	ClaimOwner	RecordingDate	ExpiryDate
YB66184	HAYES	63	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66185	HAYES	64	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66186	HAYES	65	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66187	HAYES	66	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66188	HAYES	67	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66189	HAYES	68	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66190	HAYES	69	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66191	HAYES	70	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66192	HAYES	71	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66193	HAYES	72	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66194	HAYES	73	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66195	HAYES	74	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66196	HAYES	75	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66197	HAYES	76	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66198	HAYES	77	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66199	HAYES	78	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66200	HAYES	79	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66201	HAYES	80	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66202	HAYES	81	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66203	HAYES	82	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66204	HAYES	83	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66205	HAYES	84	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66206	HAYES	85	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66207	HAYES	86	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66208	HAYES	87	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66209	HAYES	88	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66210	HAYES	89	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66211	HAYES	90	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66212	HAYES	91	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66213	HAYES	92	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66214	HAYES	93	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66215	HAYES	94	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66216	HAYES	95	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66217	HAYES	96	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66218	HAYES	97	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66219	HAYES	98	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66220	HAYES	99	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66221	HAYES	100	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66222	HAYES	101	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66223	HAYES	102	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66224	HAYES	103	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66225	HAYES	104	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66226	HAYES	105	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66227	HAYES	106	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66228	HAYES	107	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66229	HAYES	108	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66230	HAYES	109	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66231	HAYES	110	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66232	HAYES	111	Tarsis Capital Corp. - 100%.	19950908	20130408
YB66233	HAYES	112	Tarsis Capital Corp. - 100%.	19950908	20130408
YB97090	HAYES	131	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97091	HAYES	132	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97092	HAYES	133	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97093	HAYES	134	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97094	HAYES	135	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97095	HAYES	136	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97096	HAYES	137	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97097	HAYES	138	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97098	HAYES	139	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97099	HAYES	140	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97100	HAYES	141	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97101	HAYES	142	Tarsis Capital Corp. - 100%.	19961230	20130408

GrantNumber	ClaimName	ClaimNbr	ClaimOwner	RecordingDate	ExpiryDate
YB97102	HAYES	143	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97103	HAYES	144	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97104	HAYES	145	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97105	HAYES	146	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97106	HAYES	147	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97107	HAYES	148	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97108	HAYES	149	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97109	HAYES	150	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97110	HAYES	151	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97111	HAYES	152	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97112	HAYES	153	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97113	HAYES	154	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97114	HAYES	155	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97115	HAYES	156	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97116	HAYES	157	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97117	HAYES	158	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97118	HAYES	159	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97119	HAYES	160	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97120	HAYES	161	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97121	HAYES	162	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97122	HAYES	163	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97123	HAYES	164	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97124	HAYES	165	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97125	HAYES	166	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97126	HAYES	167	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97127	HAYES	168	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97128	HAYES	169	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97129	HAYES	170	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97130	HAYES	171	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97131	HAYES	172	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97132	HAYES	181	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97133	HAYES	182	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97134	HAYES	183	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97135	HAYES	184	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97136	HAYES	185	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97137	HAYES	186	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97138	HAYES	187	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97139	HAYES	188	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97140	HAYES	189	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97141	HAYES	190	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97142	HAYES	191	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97143	HAYES	192	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97144	HAYES	193	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97145	HAYES	194	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97146	HAYES	195	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97147	HAYES	196	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97148	HAYES	197	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97149	HAYES	198	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97150	HAYES	199	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97151	HAYES	200	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97152	HAYES	201	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97153	HAYES	202	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97154	HAYES	203	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97155	HAYES	204	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97156	HAYES	205	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97157	HAYES	206	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97158	HAYES	207	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97159	HAYES	208	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97160	HAYES	209	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97161	HAYES	210	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97162	HAYES	211	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97163	HAYES	212	Tarsis Capital Corp. - 100%.	19961230	20130408

GrantNumber	ClaimName	ClaimNbr	ClaimOwner	RecordingDate	ExpiryDate
YB97164	HAYES	213	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97165	HAYES	214	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97166	HAYES	215	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97167	HAYES	216	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97168	HAYES	217	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97169	HAYES	218	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97170	HAYES	219	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97171	HAYES	220	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97172	HAYES	221	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97173	HAYES	222	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97174	HAYES	223	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97175	HAYES	224	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97176	HAYES	225	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97177	HAYES	226	Tarsis Capital Corp. - 100%.	19961230	20130408
YB97178	HAYES	113	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97179	HAYES	114	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97180	HAYES	115	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97181	HAYES	116	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97182	HAYES	117	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97183	HAYES	118	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97184	HAYES	119	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97185	HAYES	120	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97186	HAYES	121	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97187	HAYES	122	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97188	HAYES	123	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97189	HAYES	124	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97190	HAYES	125	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97191	HAYES	126	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97192	HAYES	127	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97193	HAYES	128	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97194	HAYES	129	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97195	HAYES	130	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97196	HAYES	173	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97197	HAYES	174	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97198	HAYES	175	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97199	HAYES	176	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97200	HAYES	177	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97201	HAYES	178	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97202	HAYES	179	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97203	HAYES	180	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97204	HAYES	227	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97205	HAYES	228	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97206	HAYES	229	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97207	HAYES	230	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97208	HAYES	231	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97209	HAYES	232	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97210	HAYES	233	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97211	HAYES	234	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97212	HAYES	235	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97213	HAYES	236	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97214	HAYES	237	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97215	HAYES	238	Tarsis Capital Corp. - 100%.	19970108	20130408
YB97216	HAYES	239	Tarsis Capital Corp. - 100%.	19970108	20130408
YD33632	HAYES	240	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33633	HAYES	241	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33634	HAYES	242	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33635	HAYES	243	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33636	HAYES	244	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33637	HAYES	245	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33638	HAYES	246	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33639	HAYES	247	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33640	HAYES	248	SilverQuest Resources Ltd. - 100%.	20100315	20110315

GrantNumber	ClaimName	ClaimNbr	ClaimOwner	RecordingDate	ExpiryDate
YD33641	HAYES	249	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33642	HAYES	250	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33643	HAYES	251	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33644	HAYES	252	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33645	HAYES	253	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33646	HAYES	254	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33647	HAYES	255	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33648	HAYES	256	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33649	HAYES	257	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33650	HAYES	258	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33651	HAYES	259	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33652	HAYES	260	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33653	HAYES	261	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33654	HAYES	262	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33655	HAYES	263	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33656	HAYES	264	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33657	HAYES	265	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33658	HAYES	266	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33659	HAYES	267	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33660	HAYES	268	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33661	HAYES	269	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33662	HAYES	270	SilverQuest Resources Ltd. - 100%.	20100315	20110315
YD33663	HAYES	271	SilverQuest Resources Ltd. - 100%.	20100315	20110315

Appendix D-1: Soil Geochemical Certificates

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

CERTIFICATE WH10089648

Project: SQI10-01

P.O. No.: SQI10-01_8

This report is for 171 Soil samples submitted to our lab in Whitehorse, YT, Canada on 6-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
SCR-41	Screen to -180um and save both

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
Sample Description LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I30851	0.52	0.010	0.40	2.22	10.7	<0.2	<10	140	2.29	2.10	0.49	0.54	46.6	19.7	32
I30852	0.54	0.009	0.10	1.97	8.8	<0.2	<10	130	2.02	1.31	0.62	0.19	46.1	9.6	29
I30853	0.62	0.008	0.07	2.20	10.2	<0.2	<10	160	2.04	0.94	0.48	0.26	48.8	9.2	28
I30854	0.64	0.013	0.35	2.09	8.3	<0.2	<10	100	1.75	2.03	0.52	0.38	43.8	9.0	33
I30855	0.28	0.031	0.76	1.53	7.7	<0.2	<10	110	1.25	1.66	0.21	0.26	23.3	6.2	27
I30856	0.70	0.024	0.25	1.96	7.7	<0.2	<10	130	1.51	2.30	0.46	0.67	46.6	12.2	34
I30857	0.52	0.043	0.24	1.89	7.0	<0.2	<10	130	1.98	13.75	0.47	0.30	76.6	9.4	29
I30858	0.42	0.020	0.12	2.16	7.7	<0.2	<10	210	2.15	3.65	0.53	0.60	44.4	10.4	33
I30859	0.44	0.017	0.13	2.27	8.2	<0.2	<10	170	3.09	4.84	0.61	0.31	85.7	11.7	23
I30860	0.32	0.017	0.45	2.99	9.8	<0.2	<10	120	3.69	12.85	0.39	0.57	44.3	12.1	32
I30861	0.38	0.019	0.45	3.16	9.9	<0.2	<10	120	3.90	9.93	0.43	0.58	46.1	12.4	33
I30862	0.52	0.011	0.49	2.30	8.8	<0.2	<10	110	2.64	6.23	0.56	1.67	45.7	12.9	30
I30863	0.46	0.015	0.16	2.11	10.9	<0.2	<10	90	1.71	1.25	0.26	0.26	43.6	13.0	39
I30864	0.72	0.020	0.17	1.29	7.0	<0.2	<10	90	1.31	3.04	0.51	0.39	55.9	10.5	30
I30865	0.44	0.014	0.28	1.55	9.4	<0.2	<10	80	1.65	4.00	0.35	0.26	38.7	9.9	32
I30866	0.44	0.018	0.16	1.67	8.7	<0.2	<10	120	1.72	2.27	0.55	0.30	51.5	12.1	41
I30867	0.40	0.023	0.13	2.26	8.8	<0.2	<10	130	2.76	2.53	0.49	0.24	51.8	12.2	31
I30868	0.46	0.037	0.10	1.25	11.6	<0.2	<10	130	0.89	0.64	0.55	0.32	45.3	10.5	46
I30869	0.54	0.009	0.13	1.25	9.4	<0.2	<10	80	0.79	0.45	0.34	0.16	33.7	9.2	43
I30870	0.48	0.006	0.08	1.86	9.6	<0.2	<10	120	1.62	1.03	0.44	0.24	40.3	11.9	49
I30871	0.46	0.015	0.17	1.94	7.7	<0.2	<10	100	1.88	2.59	0.39	0.12	38.8	9.5	25
I30872	0.54	0.011	0.18	2.32	8.2	<0.2	<10	130	1.91	3.17	0.55	0.29	47.2	9.4	24
I30873	0.50	0.011	0.11	1.80	8.1	<0.2	<10	100	1.47	2.79	0.34	0.20	47.3	10.0	29
I30874	0.44	0.009	0.16	1.94	7.6	<0.2	<10	110	1.74	2.56	0.43	0.58	35.4	11.3	31
I30875	0.52	0.015	0.48	2.61	10.3	<0.2	<10	120	2.98	4.79	0.53	0.83	47.0	13.2	33
I30876	0.56	0.021	0.17	2.33	6.6	<0.2	<10	130	1.65	3.49	0.52	0.33	44.6	8.9	31
I30877	0.52	0.291	0.08	1.42	7.2	<0.2	<10	110	0.59	0.57	0.33	0.28	26.6	7.8	28
I30878	0.72	0.038	0.46	2.17	10.0	<0.2	<10	130	1.72	4.12	0.45	0.51	52.1	10.1	30
I30879	0.56	0.006	0.15	2.18	17.9	<0.2	<10	100	1.41	2.20	0.23	0.27	37.1	11.0	32
I30880	0.52	<0.005	0.10	2.40	11.6	<0.2	<10	210	2.18	2.10	0.53	0.32	53.5	10.5	24
I30881	0.52	<0.005	0.32	2.46	14.2	<0.2	<10	100	1.66	2.14	0.54	0.23	48.7	10.2	31
I30882	0.58	<0.005	0.30	2.33	11.6	<0.2	<10	110	1.62	2.54	0.61	0.35	52.3	8.1	31
I30883	0.56	<0.005	0.33	2.43	13.3	<0.2	<10	110	1.75	2.56	0.60	0.39	53.3	8.9	33
I30884	0.58	<0.005	0.10	1.78	10.7	<0.2	<10	120	1.31	0.60	0.38	0.38	42.7	8.4	26
I30885	0.44	<0.005	0.09	2.17	11.7	<0.2	<10	100	1.49	0.74	0.55	0.29	46.8	8.4	28
I30886	0.58	0.006	0.23	1.86	30.8	<0.2	<10	90	1.78	1.98	0.57	0.91	57.3	8.1	24
I30887	0.46	0.005	0.09	1.81	10.9	<0.2	<10	100	0.86	0.40	0.53	0.39	37.2	10.7	31
I30888	0.46	<0.005	0.06	2.44	9.8	<0.2	<10	90	1.46	1.10	0.51	0.20	44.3	8.0	20
I30889	0.58	<0.005	0.10	2.49	15.8	<0.2	<10	110	3.04	7.40	1.47	0.62	62.5	8.8	19
I30890	0.50	0.009	1.48	3.31	12.0	<0.2	<10	200	3.39	0.68	0.98	0.83	53.5	17.1	60

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I30851		10.60	34.6	3.02	7.81	0.08	0.05	0.04	0.040	0.08	23.3	20.6	0.67	708	3.73	0.01
I30852		7.87	21.2	2.75	7.05	0.09	0.05	0.02	0.035	0.11	23.9	17.1	0.59	665	1.41	0.02
I30853		8.99	23.5	2.84	7.98	0.09	0.04	0.03	0.043	0.13	25.3	19.0	0.63	534	1.31	0.01
I30854		6.66	42.5	2.73	7.96	0.09	0.04	0.03	0.039	0.12	24.3	17.1	0.61	547	1.41	0.02
I30855		3.83	35.1	2.41	6.71	0.05	<0.02	0.15	0.029	0.07	12.3	7.0	0.27	524	2.37	0.01
I30856		4.16	50.8	2.91	6.86	0.07	0.05	0.04	0.038	0.09	23.0	14.8	0.57	551	1.04	0.02
I30857		5.45	338	2.86	6.15	0.08	0.04	0.03	0.046	0.08	37.5	13.1	0.54	669	0.76	0.02
I30858		6.60	77.9	3.26	7.90	0.08	0.03	0.04	0.036	0.10	21.2	16.8	0.63	742	0.91	0.02
I30859		7.32	50.3	3.35	8.85	0.10	0.02	0.04	0.046	0.09	44.3	19.4	0.68	1140	1.41	0.02
I30860		8.18	124.0	3.38	11.10	0.07	0.02	0.06	0.052	0.21	23.8	26.5	0.87	1460	1.34	0.01
I30861		8.12	131.5	3.55	11.35	0.08	0.02	0.05	0.055	0.22	24.9	27.4	0.92	1560	1.28	0.01
I30862		7.48	74.7	2.94	8.83	0.07	0.02	0.05	0.041	0.20	24.7	20.3	0.87	1180	1.34	0.02
I30863		5.00	53.0	3.02	7.82	0.07	0.03	0.09	0.030	0.09	19.7	17.0	0.62	698	1.65	0.01
I30864		10.25	27.3	2.88	5.36	0.10	0.05	0.02	0.024	0.10	28.5	13.3	0.46	705	1.16	0.02
I30865		10.25	28.0	2.82	6.67	0.07	0.02	0.06	0.029	0.08	18.3	14.7	0.52	732	1.60	0.01
I30866		7.44	37.9	3.00	6.71	0.09	0.03	0.03	0.024	0.13	24.4	16.6	0.68	700	1.04	0.02
I30867		9.15	50.1	2.75	8.32	0.07	0.02	0.06	0.033	0.16	28.2	18.4	0.89	865	1.27	0.02
I30868		7.89	31.5	2.91	5.48	0.10	0.05	0.02	0.023	0.09	21.8	14.8	0.53	533	0.85	0.02
I30869		5.78	27.0	2.61	5.79	0.08	0.03	0.05	0.019	0.07	16.5	15.9	0.53	320	1.11	0.02
I30870		7.84	37.3	3.02	7.52	0.07	0.02	0.03	0.025	0.11	17.4	23.4	0.77	563	1.19	0.02
I30871		8.45	34.9	2.41	7.24	0.06	0.02	0.05	0.029	0.08	20.6	17.0	0.65	636	1.32	0.02
I30872		8.72	26.1	2.74	7.79	0.06	<0.02	0.02	0.048	0.09	23.7	17.2	0.63	1050	1.21	0.02
I30873		5.01	26.2	2.74	6.45	0.06	0.02	0.03	0.034	0.08	20.5	15.3	0.53	891	1.18	0.01
I30874		5.69	48.9	2.78	7.83	0.07	0.02	0.05	0.034	0.08	18.9	16.1	0.71	712	1.31	0.02
I30875		7.48	99.1	3.21	9.57	0.07	0.02	0.06	0.047	0.14	24.3	19.5	0.79	1220	1.41	0.02
I30876		4.95	42.8	3.40	6.44	0.06	<0.02	0.03	0.044	0.11	21.0	12.5	0.65	1080	0.79	0.02
I30877		4.81	20.5	2.59	6.84	0.06	0.03	0.05	0.025	0.07	13.5	12.0	0.43	299	1.14	0.01
I30878		6.19	68.6	3.31	7.37	0.08	0.03	0.05	0.060	0.10	26.4	15.2	0.61	775	1.19	0.02
I30879		8.27	33.8	3.39	7.94	0.07	0.03	0.07	0.053	0.08	18.1	18.2	0.58	687	2.55	0.02
I30880		9.92	35.5	3.03	8.18	0.07	0.03	0.03	0.056	0.10	27.7	20.0	0.67	782	1.57	0.02
I30881		8.36	37.5	3.45	8.68	0.08	0.05	0.03	0.064	0.08	26.3	20.0	0.72	621	2.40	0.02
I30882		11.20	30.8	2.99	8.32	0.08	0.09	0.03	0.064	0.11	29.4	19.1	0.72	390	1.61	0.02
I30883		11.85	34.3	3.15	8.65	0.09	0.07	0.05	0.063	0.11	29.8	19.4	0.72	432	1.86	0.02
I30884		9.05	20.3	2.65	6.11	0.07	0.04	0.03	0.041	0.09	22.3	15.6	0.48	398	1.51	0.02
I30885		6.30	23.7	2.74	7.07	0.07	0.03	0.01	0.041	0.13	24.5	16.9	0.60	473	1.20	0.03
I30886		7.67	41.6	3.07	7.47	0.09	0.03	0.03	0.130	0.13	31.1	13.3	0.52	1140	3.09	0.02
I30887		9.43	27.5	2.69	5.97	0.08	0.04	0.02	0.032	0.10	18.7	15.7	0.57	359	1.37	0.03
I30888		6.72	26.0	2.44	7.44	0.05	0.02	0.01	0.048	0.10	23.0	15.3	0.57	641	1.05	0.03
I30889		9.19	30.4	2.66	8.56	0.07	0.02	0.03	0.120	0.10	36.2	24.4	0.89	1560	0.97	0.02
I30890		11.80	74.1	4.09	12.10	0.12	0.03	0.04	0.049	0.37	28.3	27.5	1.50	1760	1.01	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method Analyte Units LOR	ME-MS41 Nb ppm 0.05	ME-MS41 Ni ppm 0.2	ME-MS41 P ppm 10	ME-MS41 Pb ppm 0.2	ME-MS41 Rb ppm 0.1	ME-MS41 Re ppm 0.001	ME-MS41 S % 0.01	ME-MS41 Sb ppm 0.05	ME-MS41 Sc ppm 0.1	ME-MS41 Se ppm 0.2	ME-MS41 Sn ppm 0.2	ME-MS41 Sr ppm 0.2	ME-MS41 Ta ppm 0.01	ME-MS41 Te ppm 0.01	ME-MS41 Th ppm 0.2
I30851		1.59	20.5	1220	52.0	14.6	<0.001	0.02	0.52	5.7	0.6	0.8	139.0	<0.01	0.43	13.1
I30852		1.12	16.8	1040	24.3	20.2	<0.001	0.02	0.50	5.4	0.5	1.0	87.2	<0.01	0.06	22.6
I30853		2.55	16.2	1220	37.3	22.5	<0.001	0.02	0.61	4.5	0.5	1.3	143.0	<0.01	0.07	18.9
I30854		1.97	19.7	1420	31.2	31.8	<0.001	0.02	0.75	5.6	0.5	0.9	65.4	<0.01	0.07	12.6
I30855		0.85	15.0	1820	46.5	22.1	<0.001	0.21	0.65	1.3	0.7	0.6	36.8	<0.01	0.06	0.4
I30856		1.70	19.4	1420	61.3	16.8	<0.001	0.02	0.47	5.4	0.7	0.8	65.4	<0.01	0.09	11.7
I30857		1.49	16.9	1220	69.1	13.7	<0.001	0.02	0.62	4.2	0.7	0.8	121.0	<0.01	0.08	12.7
I30858		1.61	21.2	1570	102.5	18.3	<0.001	0.03	0.65	3.7	0.6	0.8	159.0	<0.01	0.10	10.0
I30859		0.89	16.3	1530	49.9	18.5	<0.001	0.03	0.62	2.9	0.7	1.1	157.0	<0.01	0.21	9.4
I30860		2.17	24.1	1210	148.5	49.0	<0.001	0.07	1.06	4.0	0.5	1.7	57.1	<0.01	0.08	4.1
I30861		2.18	24.6	1270	156.0	50.9	<0.001	0.06	1.09	4.4	0.6	1.6	58.9	<0.01	0.09	4.9
I30862		1.87	23.5	1630	94.1	40.4	<0.001	0.06	0.90	4.3	0.7	1.0	71.1	<0.01	0.63	5.7
I30863		1.68	27.8	1390	26.6	23.7	<0.001	0.08	0.67	2.6	0.8	0.8	24.7	0.01	0.10	1.9
I30864		1.20	17.0	1480	31.4	17.6	<0.001	0.01	0.70	3.9	0.6	1.0	62.8	<0.01	0.18	30.4
I30865		1.18	21.5	1200	41.6	16.7	<0.001	0.07	0.81	1.9	0.6	0.6	41.0	<0.01	0.36	3.3
I30866		2.12	25.8	1670	28.4	25.6	<0.001	0.03	0.61	3.7	0.6	0.9	76.9	<0.01	0.18	10.0
I30867		2.05	23.4	1500	35.1	31.8	<0.001	0.07	0.70	3.7	0.7	0.9	91.0	<0.01	0.37	5.4
I30868		1.29	22.9	1660	27.2	15.4	<0.001	0.02	0.58	4.1	0.6	0.6	72.0	<0.01	0.08	10.2
I30869		2.04	22.2	1030	19.1	12.8	<0.001	0.05	0.48	2.6	0.6	0.6	46.9	<0.01	0.04	5.4
I30870		2.40	26.8	1260	28.5	22.5	<0.001	0.04	0.53	3.1	0.5	1.1	59.7	<0.01	0.13	6.8
I30871		1.34	19.0	1120	36.2	17.9	<0.001	0.06	0.64	2.4	0.6	0.8	72.7	<0.01	0.36	2.2
I30872		1.26	15.2	1030	78.4	17.9	<0.001	0.03	0.59	2.5	0.4	0.8	119.5	<0.01	0.23	5.2
I30873		1.38	18.3	1090	35.3	16.0	<0.001	0.04	0.69	2.6	0.5	0.7	62.8	<0.01	0.17	7.1
I30874		1.77	22.8	1140	46.7	20.8	<0.001	0.07	0.78	3.0	0.6	1.0	70.7	<0.01	0.15	1.9
I30875		1.55	22.6	1490	108.5	32.9	<0.001	0.05	0.75	3.8	0.6	1.3	75.5	<0.01	0.09	3.5
I30876		0.78	14.4	1520	53.4	17.4	<0.001	0.03	0.59	3.0	0.5	0.8	98.1	<0.01	0.08	10.8
I30877		1.42	17.4	1010	23.3	11.5	<0.001	0.05	0.44	1.8	0.5	0.7	51.6	<0.01	0.03	2.4
I30878		1.72	19.4	1190	60.8	22.7	<0.001	0.03	0.75	4.2	0.4	1.4	77.4	<0.01	0.24	12.6
I30879		1.97	21.5	880	31.8	18.7	0.001	0.07	0.66	3.2	0.5	1.3	40.3	<0.01	0.08	6.6
I30880		1.96	16.0	1030	48.2	18.4	0.001	0.03	0.54	3.8	0.4	1.5	230	<0.01	0.06	13.3
I30881		2.31	16.3	1270	36.2	17.3	<0.001	0.03	0.57	4.8	0.5	1.1	70.5	<0.01	0.09	16.5
I30882		2.26	13.3	1190	48.5	24.9	0.001	0.02	0.59	5.7	0.4	1.3	55.0	<0.01	0.07	28.9
I30883		2.58	14.7	1160	51.7	26.0	<0.001	0.03	0.62	5.9	0.5	1.1	53.5	<0.01	0.08	26.6
I30884		3.16	15.6	1030	41.4	19.3	0.001	0.03	0.50	3.4	0.3	1.0	48.5	<0.01	0.04	16.7
I30885		2.40	14.9	960	40.6	29.6	0.001	0.04	0.59	4.3	0.4	1.1	54.6	0.01	0.03	20.4
I30886		1.37	11.4	1190	55.8	29.0	0.001	0.01	1.49	4.6	0.4	1.4	60.4	<0.01	0.09	22.9
I30887		2.18	19.0	1300	46.1	21.0	<0.001	0.01	0.46	4.6	0.3	0.8	62.6	<0.01	0.02	11.7
I30888		1.70	10.8	960	41.9	18.9	0.001	0.04	0.44	2.7	0.4	0.8	72.2	<0.01	0.04	6.8
I30889		0.36	8.9	4020	59.5	18.1	<0.001	0.02	0.72	1.7	0.3	1.3	113.0	<0.01	0.90	4.2
I30890		3.22	35.0	2420	87.7	55.0	<0.001	0.03	1.31	7.8	0.4	1.2	159.0	<0.01	0.02	8.6

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I30851		0.090	0.12	12.75	68	0.33	13.30	131	2.0
I30852		0.082	0.13	12.65	64	0.33	14.60	65	1.8
I30853		0.105	0.16	7.82	68	0.49	14.00	80	1.2
I30854		0.105	0.20	7.75	68	0.61	13.35	97	1.6
I30855		0.035	0.14	4.27	66	0.41	6.26	55	0.5
I30856		0.100	0.17	6.65	78	0.41	13.25	106	1.9
I30857		0.078	0.16	9.41	75	0.38	18.60	101	0.8
I30858		0.078	0.17	3.89	89	0.53	10.70	119	0.7
I30859		0.031	0.22	6.51	75	0.72	19.50	120	<0.5
I30860		0.078	0.37	5.66	78	0.83	9.95	220	0.5
I30861		0.078	0.39	6.05	82	0.72	10.80	231	0.5
I30862		0.084	0.33	5.90	71	0.60	11.35	252	0.7
I30863		0.090	0.20	4.28	86	0.52	9.68	82	0.9
I30864		0.089	0.12	18.50	73	1.35	15.30	81	2.0
I30865		0.066	0.15	6.50	69	0.71	7.62	78	0.6
I30866		0.110	0.14	9.30	87	0.55	11.60	75	1.0
I30867		0.075	0.21	11.90	69	0.54	12.75	86	0.6
I30868		0.104	0.13	7.33	85	0.42	13.45	68	1.7
I30869		0.109	0.11	3.35	81	1.51	7.28	50	1.1
I30870		0.120	0.13	4.55	88	0.59	8.62	75	0.8
I30871		0.057	0.15	7.85	56	0.53	8.73	80	<0.5
I30872		0.035	0.18	7.42	60	0.35	9.12	103	<0.5
I30873		0.060	0.15	6.12	66	0.57	10.50	88	<0.5
I30874		0.082	0.21	4.34	74	0.55	8.90	118	0.7
I30875		0.070	0.25	5.33	80	0.72	11.70	177	<0.5
I30876		0.058	0.17	5.91	77	0.45	10.95	125	<0.5
I30877		0.089	0.11	3.73	63	0.64	6.62	64	1.0
I30878		0.062	0.20	6.77	67	0.94	13.70	120	0.7
I30879		0.076	0.17	7.29	71	0.44	8.31	72	0.7
I30880		0.059	0.21	10.90	57	0.45	14.60	89	0.6
I30881		0.072	0.15	11.80	71	0.40	14.65	85	1.5
I30882		0.082	0.15	17.90	69	0.43	16.50	120	4.4
I30883		0.079	0.16	20.2	71	0.69	16.75	127	3.3
I30884		0.112	0.15	9.14	61	1.98	10.45	100	1.5
I30885		0.107	0.21	14.80	62	0.50	13.95	91	1.2
I30886		0.071	0.25	19.80	59	0.54	15.90	192	1.3
I30887		0.138	0.15	12.15	64	0.62	10.90	95	1.7
I30888		0.035	0.16	8.12	53	0.52	11.50	88	<0.5
I30889		0.017	0.28	27.5	38	0.57	13.60	110	<0.5
I30890		0.138	0.21	7.32	119	0.63	15.90	140	0.8

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
Sample Description LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I30891	0.52	0.009	0.26	2.00	9.6	<0.2	<10	100	2.06	2.89	0.62	0.51	56.4	13.8	49
I30892	0.50	<0.005	0.22	1.96	10.7	<0.2	<10	80	1.09	0.48	0.38	0.25	33.9	10.6	42
I30893	0.52	0.007	0.42	1.62	8.9	<0.2	<10	90	1.17	0.69	0.50	1.72	34.9	10.3	39
I30894	0.34	0.024	0.11	1.94	9.8	<0.2	<10	120	1.30	1.08	0.52	0.62	41.4	10.7	42
I30895	0.56	0.022	0.39	2.78	12.5	<0.2	<10	120	3.01	1.57	0.94	1.53	47.6	13.7	41
I30896	0.42	<0.005	0.13	1.39	9.0	<0.2	<10	100	0.62	0.37	0.27	0.32	20.1	9.3	30
I30897	0.42	<0.005	0.07	0.57	1.8	<0.2	<10	30	0.25	0.22	0.11	0.11	7.48	2.8	7
I30898	0.58	0.012	0.31	2.22	12.7	<0.2	<10	150	1.88	2.83	0.51	0.68	53.1	13.9	37
I30899	0.60	0.028	0.24	1.94	9.9	<0.2	<10	120	1.80	2.57	0.66	0.69	44.0	10.0	35
I30900	0.74	0.009	0.27	2.24	10.6	<0.2	<10	120	1.73	5.01	0.64	0.69	44.2	10.7	44
I30901	0.56	0.016	0.38	2.79	11.2	<0.2	<10	180	2.41	3.78	0.73	1.05	50.5	14.0	48
I30902	0.54	<0.005	0.54	2.75	10.1	<0.2	<10	90	1.80	2.72	0.33	0.35	34.3	10.4	39
I30903	0.48	<0.005	0.41	2.60	10.3	<0.2	<10	100	1.81	2.67	0.34	0.43	35.9	10.7	40
I30904	0.88	0.005	0.17	1.77	12.9	<0.2	<10	110	1.27	2.19	0.48	0.31	49.2	9.2	32
I30905	0.52	0.005	0.14	1.82	15.8	<0.2	<10	110	1.27	1.41	0.41	0.30	42.3	10.5	30
I30906	0.62	0.006	0.24	1.60	17.4	<0.2	<10	110	1.51	2.18	0.54	0.29	52.8	12.4	25
I30907	0.58	<0.005	0.27	2.07	25.0	<0.2	<10	130	1.77	2.51	0.52	0.27	44.7	11.3	25
I30908	0.52	0.025	3.20	2.19	2500	<0.2	<10	190	2.12	10.25	0.51	2.34	63.1	11.5	19
I30909	0.58	0.018	2.39	2.00	1370	<0.2	<10	220	2.33	11.00	0.52	2.35	59.2	13.6	20
I30910	0.66	0.013	2.35	2.33	1315	<0.2	<10	220	2.29	9.35	0.59	2.04	61.2	14.1	23
I30911	0.34	0.005	0.14	1.93	19.7	<0.2	<10	60	1.64	0.93	0.52	0.32	35.3	12.2	44
I30912	0.34	0.006	0.21	2.09	12.9	<0.2	<10	70	1.71	0.72	0.44	0.36	33.3	11.5	43
I30913	0.36	0.005	0.19	2.17	16.8	<0.2	<10	80	1.47	1.82	0.32	0.43	27.2	11.4	61
I30914	0.30	<0.005	0.13	1.80	11.1	<0.2	<10	70	1.28	0.75	0.57	0.25	30.2	11.0	58
I30915	0.28	<0.005	0.13	1.56	10.0	<0.2	<10	70	1.01	0.85	0.26	0.14	22.2	8.2	39
I30916	0.38	<0.005	0.14	1.59	10.6	<0.2	<10	70	1.13	1.11	0.28	0.19	22.1	8.0	37
I30917	0.34	<0.005	0.20	1.80	8.6	<0.2	<10	100	1.75	1.31	0.48	0.58	27.8	10.4	38
I30918	0.30	<0.005	0.15	1.93	9.2	<0.2	<10	80	1.76	1.34	0.32	0.17	30.2	10.5	34
I30919	0.38	0.005	0.09	1.38	9.7	<0.2	<10	50	0.90	0.72	0.58	0.22	35.5	8.2	51
I30920	0.26	<0.005	0.30	2.22	9.3	<0.2	<10	100	1.72	1.92	0.37	0.20	29.4	10.2	40
I30921	0.32	0.008	0.19	2.33	9.9	<0.2	<10	110	1.87	2.59	0.84	0.29	49.8	13.2	64
I30922	0.38	0.046	0.22	2.23	10.8	<0.2	<10	110	1.58	3.21	0.67	0.31	44.2	12.9	59
I30923	0.32	0.014	0.12	1.70	9.3	<0.2	<10	80	1.09	3.43	0.32	0.30	28.9	8.8	45
I30924	0.30	0.014	0.16	1.85	9.8	<0.2	<10	80	1.29	2.64	0.35	0.29	31.5	9.9	49
I30925	0.38	0.045	0.34	1.90	10.1	<0.2	<10	80	1.18	3.67	0.25	0.24	29.4	8.6	44
I30926	0.40	0.081	0.35	1.93	11.0	<0.2	<10	100	1.74	6.68	0.48	0.45	50.9	11.7	45
I30927	0.30	0.027	0.49	2.00	12.8	<0.2	<10	100	1.38	5.83	0.44	0.57	50.2	12.4	43
I30928	0.30	0.124	0.41	1.88	10.6	<0.2	<10	90	1.46	5.35	0.46	0.49	49.8	12.1	43
I30929	0.32	0.011	1.12	2.36	10.3	<0.2	<10	100	2.07	14.45	0.56	0.49	47.3	12.4	29
I30930	0.30	0.018	0.69	2.03	17.5	<0.2	<10	80	1.40	9.79	0.49	0.25	41.3	9.5	24

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I30891		4.73	73.1	3.57	7.61	0.10	0.04	0.03	0.036	0.09	25.3	16.0	0.60	1040	1.69	0.03
I30892		4.07	40.4	3.11	6.45	0.08	0.04	0.04	0.031	0.08	16.1	16.3	0.63	504	0.98	0.02
I30893		3.66	54.7	2.91	5.95	0.09	0.04	0.01	0.033	0.09	17.0	14.8	0.57	598	0.81	0.02
I30894		4.82	52.6	3.05	6.78	0.09	0.03	0.03	0.033	0.10	20.9	17.6	0.64	388	1.09	0.03
I30895		8.07	115.0	3.79	10.55	0.11	0.02	0.02	0.049	0.28	24.4	24.8	1.03	1640	1.12	0.02
I30896		4.26	29.7	2.66	6.89	0.05	0.03	0.05	0.034	0.08	8.6	13.9	0.47	623	1.37	0.02
I30897		1.24	14.9	0.93	2.82	<0.05	<0.02	0.02	0.009	0.02	3.6	1.9	0.08	122	0.40	0.03
I30898		4.62	70.5	3.80	8.48	0.09	0.03	0.06	0.050	0.10	25.1	19.0	0.59	1460	2.25	0.03
I30899		5.37	64.3	3.29	7.85	0.09	0.03	0.01	0.042	0.11	22.3	18.4	0.62	767	1.03	0.02
I30900		7.60	49.2	3.51	8.55	0.10	0.03	0.02	0.040	0.19	22.0	20.9	0.77	866	0.70	0.02
I30901		8.94	99.5	3.91	10.65	0.11	0.04	0.03	0.057	0.28	24.7	25.2	1.04	1510	1.08	0.03
I30902		6.72	52.7	3.53	10.75	0.07	0.03	0.05	0.065	0.13	18.3	23.1	0.77	898	1.03	0.02
I30903		7.27	52.5	3.54	10.65	0.08	0.03	0.04	0.068	0.14	18.8	23.3	0.78	1100	1.12	0.02
I30904		6.29	40.8	2.99	6.23	0.08	0.03	0.01	0.044	0.10	23.9	14.4	0.52	536	1.61	0.02
I30905		5.89	29.7	3.13	6.42	0.09	0.03	0.01	0.042	0.10	21.2	15.9	0.58	593	2.60	0.02
I30906		7.08	31.0	3.44	6.23	0.09	0.02	0.02	0.039	0.10	23.9	16.7	0.64	754	2.40	0.02
I30907		8.09	34.9	3.25	7.27	0.08	0.02	0.02	0.047	0.09	22.7	17.3	0.66	785	2.74	0.03
I30908		13.90	79.2	4.85	7.67	0.10	0.03	0.04	0.240	0.21	33.4	16.3	0.57	1000	7.44	0.04
I30909		12.70	76.0	4.24	7.07	0.10	0.03	0.03	0.183	0.17	31.5	17.0	0.60	1120	5.25	0.03
I30910		13.10	74.3	4.96	8.15	0.11	0.03	0.03	0.221	0.18	33.0	19.1	0.71	1250	5.48	0.04
I30911		5.23	51.2	2.80	7.16	0.08	0.06	0.03	0.031	0.06	18.0	20.8	0.56	518	0.81	0.02
I30912		4.53	46.5	2.99	7.36	0.08	0.04	0.05	0.031	0.06	17.3	18.5	0.58	497	1.01	0.02
I30913		4.92	38.8	3.12	7.34	0.06	0.02	0.10	0.029	0.11	12.9	19.2	0.68	521	1.95	0.02
I30914		4.09	38.1	2.99	6.67	0.07	0.03	0.04	0.022	0.10	16.4	16.2	0.60	494	0.75	0.02
I30915		3.44	26.5	2.66	6.38	0.05	0.02	0.06	0.027	0.04	11.9	11.6	0.41	297	0.88	0.02
I30916		3.54	26.0	2.64	6.71	0.05	<0.02	0.05	0.026	0.05	12.0	12.3	0.50	348	0.75	0.02
I30917		4.58	43.8	2.37	6.21	0.06	0.02	0.08	0.025	0.06	14.7	13.6	0.54	689	0.86	0.02
I30918		4.49	41.6	2.56	6.94	0.06	0.02	0.07	0.026	0.05	16.3	14.9	0.55	589	0.74	0.02
I30919		2.99	29.4	2.93	5.52	0.08	0.03	0.02	0.024	0.06	19.1	12.3	0.46	362	0.57	0.02
I30920		5.26	46.9	2.94	8.12	0.07	0.02	0.06	0.035	0.06	16.4	17.7	0.66	476	0.81	0.02
I30921		7.11	54.8	3.50	8.48	0.10	0.04	0.02	0.039	0.22	25.9	21.5	0.89	727	0.69	0.02
I30922		5.57	53.4	3.29	7.71	0.08	0.03	0.04	0.039	0.14	23.0	19.7	0.72	782	0.77	0.02
I30923		4.64	38.9	3.16	7.00	0.05	0.02	0.05	0.034	0.09	14.8	18.1	0.55	453	0.91	0.02
I30924		4.69	49.1	3.20	7.34	0.07	0.02	0.07	0.039	0.08	16.8	18.6	0.58	502	0.84	0.02
I30925		4.75	52.8	3.16	7.86	0.06	<0.02	0.06	0.040	0.07	16.3	14.9	0.54	417	1.09	0.02
I30926		5.44	57.5	3.36	7.29	0.09	0.02	0.03	0.058	0.08	24.9	15.9	0.61	1500	1.18	0.02
I30927		7.90	80.0	3.43	7.06	0.09	0.03	0.04	0.046	0.10	24.5	15.7	0.63	856	1.65	0.02
I30928		7.54	71.6	3.36	6.77	0.09	0.03	0.03	0.049	0.10	25.4	15.1	0.60	1020	1.46	0.02
I30929		9.73	199.5	2.89	8.15	0.06	0.02	0.09	0.067	0.09	26.7	18.1	0.70	1290	2.89	0.03
I30930		9.70	107.5	2.64	7.11	0.06	0.02	0.05	0.054	0.08	23.5	15.1	0.56	997	3.66	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I30891		2.12	23.8	2050	44.5	21.8	0.001	0.03	0.72	5.1	0.6	1.2	69.4	<0.01	0.15	7.0
I30892		2.50	25.7	1280	23.4	18.7	<0.001	0.04	0.61	3.6	0.5	0.7	33.1	0.01	0.03	3.4
I30893		2.14	22.3	1670	52.1	19.9	0.001	0.02	0.53	3.5	0.3	0.6	38.7	<0.01	0.02	5.9
I30894		2.59	27.0	1730	32.8	25.4	<0.001	0.02	0.56	4.4	0.5	0.7	55.5	<0.01	0.04	6.6
I30895		2.00	24.6	2380	125.5	49.4	0.001	0.02	0.80	6.6	0.4	1.2	119.0	<0.01	0.04	9.9
I30896		1.83	19.7	800	25.0	22.2	0.001	0.08	0.54	2.1	0.5	0.5	34.0	<0.01	0.04	0.6
I30897		0.28	4.3	580	24.1	4.8	<0.001	0.03	0.15	0.4	0.3	0.2	15.0	<0.01	0.02	<0.2
I30898		1.80	21.8	1860	115.5	21.4	<0.001	0.04	0.66	4.1	0.5	0.8	116.0	0.01	0.08	4.3
I30899		1.82	17.7	1960	71.2	24.8	<0.001	0.02	0.62	4.3	0.4	1.0	107.0	<0.01	0.06	10.0
I30900		2.81	19.9	1950	54.7	44.5	<0.001	0.02	0.70	5.2	0.4	1.4	74.8	<0.01	0.06	9.1
I30901		2.72	27.6	1970	80.2	47.2	<0.001	0.02	0.69	7.0	0.4	1.2	128.5	<0.01	0.11	12.5
I30902		2.78	18.6	1530	48.7	29.8	0.001	0.05	0.72	3.8	0.5	0.9	37.1	<0.01	0.05	4.9
I30903		2.72	18.6	1580	47.8	32.0	<0.001	0.05	0.74	3.7	0.4	1.0	39.9	<0.01	0.06	4.8
I30904		1.96	16.9	1330	32.3	23.4	<0.001	0.01	0.60	4.2	0.5	0.9	75.6	<0.01	0.21	13.3
I30905		2.31	16.0	1080	29.8	23.7	<0.001	0.02	0.58	3.9	0.4	1.0	70.9	<0.01	0.14	14.6
I30906		1.74	13.4	1300	32.4	19.0	<0.001	0.03	0.57	3.4	0.4	0.9	115.5	<0.01	0.28	16.5
I30907		1.75	15.3	1130	35.5	19.2	<0.001	0.04	0.57	3.5	0.6	1.0	131.5	0.01	0.22	13.1
I30908		1.28	9.9	1210	707	26.4	0.001	0.42	2.45	4.0	0.8	1.0	239	<0.01	0.61	22.9
I30909		1.46	10.8	1210	571	20.4	0.001	0.27	1.94	3.5	0.6	0.9	255	0.01	0.50	25.2
I30910		1.39	10.9	1380	518	24.0	<0.001	0.33	1.78	4.7	0.7	1.1	250	<0.01	0.63	29.8
I30911		2.88	23.5	1900	39.0	12.8	<0.001	0.02	0.62	3.1	0.3	0.6	33.1	<0.01	0.03	4.9
I30912		2.54	23.9	1830	33.9	15.0	<0.001	0.05	0.75	2.9	0.5	0.6	29.4	0.01	0.03	2.1
I30913		1.96	32.6	1770	26.1	24.0	<0.001	0.10	0.81	1.6	0.7	0.6	26.0	0.01	0.03	0.5
I30914		1.99	25.3	2040	30.8	19.0	<0.001	0.04	0.64	2.4	0.5	2.3	35.6	0.01	0.03	1.4
I30915		1.35	18.8	1140	25.4	11.3	<0.001	0.08	0.63	1.0	0.5	0.6	25.4	<0.01	0.03	<0.2
I30916		1.40	17.5	1170	34.9	12.8	<0.001	0.07	0.75	1.1	0.5	0.6	29.6	<0.01	0.03	<0.2
I30917		1.82	21.6	1530	34.5	15.0	<0.001	0.06	0.63	2.5	0.6	0.5	44.7	<0.01	0.03	1.0
I30918		1.72	20.3	1300	34.8	12.8	<0.001	0.07	0.67	1.9	0.6	0.6	33.5	<0.01	0.03	0.5
I30919		2.01	19.5	2150	20.1	12.5	<0.001	0.02	0.70	2.5	0.3	0.5	28.1	<0.01	0.02	3.4
I30920		2.08	21.8	1400	34.1	17.3	<0.001	0.07	0.71	2.3	0.5	0.7	36.3	<0.01	0.04	1.0
I30921		2.45	26.9	2280	34.1	40.4	<0.001	0.01	0.75	5.3	0.4	0.9	105.5	<0.01	0.11	7.8
I30922		2.00	26.9	2190	34.6	28.6	<0.001	0.02	0.71	4.1	0.4	0.8	79.4	<0.01	0.56	5.0
I30923		1.66	21.2	1150	34.6	21.8	<0.001	0.06	0.73	1.7	0.4	0.8	31.1	0.01	0.10	0.7
I30924		1.78	22.4	1470	28.7	20.4	<0.001	0.05	0.89	2.1	0.5	0.7	31.0	<0.01	0.10	1.1
I30925		1.29	21.8	1150	29.6	21.2	<0.001	0.08	1.13	1.3	0.5	0.9	28.0	<0.01	0.08	0.3
I30926		1.83	21.7	1720	43.2	20.4	<0.001	0.03	3.08	3.9	0.5	0.7	49.6	<0.01	0.09	6.0
I30927		2.01	25.9	1640	52.3	20.5	<0.001	0.03	1.16	3.7	0.6	0.7	36.3	0.01	0.12	8.6
I30928		2.13	21.7	1620	52.8	21.6	<0.001	0.03	1.37	3.6	0.4	0.7	44.0	<0.01	0.14	11.4
I30929		1.78	21.6	1360	71.8	22.3	<0.001	0.10	1.14	3.0	0.8	0.9	87.7	<0.01	0.11	1.9
I30930		1.66	15.2	1170	58.4	18.2	<0.001	0.06	1.06	3.0	0.5	0.9	132.0	<0.01	0.10	3.8

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I30891		0.110	0.18	5.57	102	1.61	14.20	91	1.4
I30892		0.119	0.17	1.77	84	0.52	8.70	64	1.2
I30893		0.107	0.15	2.24	82	1.07	9.20	142	1.3
I30894		0.117	0.16	3.16	84	0.53	11.35	107	1.3
I30895		0.134	0.38	6.48	107	0.72	13.35	213	0.8
I30896		0.082	0.10	0.87	62	0.29	3.48	75	1.2
I30897		0.031	0.05	0.50	27	0.12	1.59	19	<0.5
I30898		0.084	0.21	5.61	98	0.59	13.25	143	0.7
I30899		0.094	0.20	4.70	89	0.69	12.30	134	0.8
I30900		0.130	0.35	3.74	91	0.97	12.05	139	1.2
I30901		0.155	0.42	5.74	107	0.76	14.45	169	1.6
I30902		0.089	0.32	4.25	87	0.75	8.95	131	1.0
I30903		0.091	0.33	3.87	89	0.71	8.95	132	1.0
I30904		0.093	0.19	7.51	69	0.51	12.95	77	1.1
I30905		0.104	0.19	8.90	67	0.52	10.80	84	1.0
I30906		0.062	0.16	9.24	68	0.41	11.60	73	0.6
I30907		0.058	0.18	12.15	63	0.36	12.00	91	0.5
I30908		0.021	0.46	21.8	55	0.31	13.30	480	0.5
I30909		0.030	0.30	25.5	60	0.38	15.35	527	0.5
I30910		0.034	0.37	23.0	74	0.38	15.25	529	0.6
I30911		0.115	0.10	3.90	73	0.80	9.00	92	2.4
I30912		0.108	0.14	3.29	75	0.72	9.66	91	1.5
I30913		0.070	0.17	1.71	77	0.48	6.73	80	0.9
I30914		0.094	0.11	2.24	81	0.60	8.51	83	1.0
I30915		0.051	0.13	1.87	70	0.46	5.36	63	0.6
I30916		0.044	0.11	2.17	66	0.50	5.39	83	<0.5
I30917		0.074	0.15	3.75	61	0.48	8.81	80	1.0
I30918		0.064	0.17	3.24	62	0.47	8.59	80	0.7
I30919		0.094	0.09	1.99	80	0.63	9.00	80	1.1
I30920		0.074	0.16	3.02	72	0.51	7.98	100	0.9
I30921		0.114	0.29	5.33	101	0.75	13.15	107	1.2
I30922		0.099	0.26	3.57	94	0.72	10.90	100	0.8
I30923		0.073	0.18	2.29	83	0.56	6.43	89	0.7
I30924		0.073	0.21	2.62	85	0.61	7.85	91	0.7
I30925		0.049	0.23	2.92	84	0.49	6.79	78	0.5
I30926		0.079	0.22	5.48	83	0.61	12.55	142	0.6
I30927		0.097	0.21	6.21	82	0.85	11.35	113	0.9
I30928		0.084	0.20	6.49	80	0.76	11.40	143	0.8
I30929		0.049	0.28	10.65	60	0.55	12.90	128	0.5
I30930		0.045	0.22	10.50	52	0.60	11.45	148	<0.5

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1	ME-MS41 Cr ppm 1
I30931		0.40	0.010	0.55	2.55	15.0	<0.2	<10	110	1.60	9.97	0.49	0.40	40.4	10.9	27
I30932		0.36	0.006	0.12	1.66	11.4	<0.2	<10	90	0.89	3.62	0.25	0.31	30.2	8.4	33
I30933		0.34	0.043	0.21	1.82	8.5	<0.2	<10	100	1.28	4.07	0.59	0.36	47.0	9.4	37
I30934		0.42	0.071	0.29	2.02	9.9	<0.2	<10	70	1.41	6.19	0.41	0.41	39.5	10.3	41
I30935		0.32	0.019	0.51	2.06	10.4	<0.2	<10	80	1.41	5.96	0.39	0.48	38.6	11.1	38
I30936		0.40	0.017	0.47	1.70	9.1	<0.2	<10	70	1.07	11.15	0.33	0.60	36.6	9.5	46
I30937		0.40	0.031	0.20	1.79	11.2	<0.2	<10	70	0.99	1.61	0.19	0.24	25.4	8.7	42
I30938		0.40	0.007	0.43	2.44	10.8	0.4	<10	100	1.97	2.59	0.54	0.45	49.0	13.5	53
I30939		0.44	<0.005	0.22	2.49	12.2	<0.2	<10	110	1.55	1.01	0.56	0.38	48.4	14.8	64
I30940		0.42	0.015	0.20	2.30	11.7	<0.2	<10	100	1.73	1.38	0.48	0.39	41.4	12.8	57
I30941		0.22	0.006	0.38	3.43	8.7	<0.2	<10	210	3.46	4.26	0.90	0.21	54.1	13.5	55
I30942		0.40	<0.005	0.23	2.40	13.0	<0.2	<10	90	1.73	2.01	0.33	0.24	31.4	13.1	45
I30943		0.38	<0.005	0.23	2.51	10.5	<0.2	<10	100	1.93	1.30	0.37	0.30	33.8	11.5	45
I30944		0.32	<0.005	0.18	1.61	8.6	<0.2	<10	90	1.25	0.95	0.21	0.30	23.8	6.8	29
I30945		0.36	<0.005	0.06	1.97	10.4	<0.2	<10	60	1.13	0.45	0.37	0.26	28.0	10.1	45
I30946		0.34	<0.005	0.17	1.55	6.7	<0.2	<10	100	0.93	0.55	0.16	0.17	20.5	6.1	30
I30947		0.28	0.005	0.20	2.12	23.4	<0.2	<10	90	2.00	1.52	0.53	0.27	69.5	12.2	29
I30948		0.30	0.005	0.27	1.86	17.7	<0.2	<10	100	1.67	0.86	0.56	0.23	60.4	12.6	42
I30949		0.30	0.035	0.23	2.61	12.8	<0.2	<10	300	2.25	0.84	0.64	0.29	78.1	13.2	38
I30950		0.24	<0.005	0.41	1.89	29.3	<0.2	<10	150	1.85	2.45	0.34	0.18	63.9	13.0	28
I33001		0.42	0.029	0.12	1.80	10.1	<0.2	<10	90	1.50	1.52	0.50	0.37	43.1	10.7	47
I33002		0.60	<0.005	0.16	1.90	9.5	<0.2	<10	100	1.63	1.35	0.52	0.37	41.3	11.8	48
I33003		0.48	<0.005	0.14	1.82	9.0	<0.2	<10	90	1.48	1.51	0.57	0.39	42.3	10.6	55
I33004		0.48	<0.005	0.26	2.11	8.8	<0.2	<10	100	1.86	1.77	0.47	0.54	39.2	11.0	47
I33005		0.34	<0.005	0.12	1.46	9.9	<0.2	<10	70	0.77	0.56	0.17	0.23	19.50	7.5	41
I33006		0.46	0.011	0.08	1.80	10.1	<0.2	<10	80	0.95	0.45	0.38	0.34	30.2	11.2	46
I33007		0.46	0.041	0.31	1.93	16.3	<0.2	<10	150	2.08	1.55	0.63	0.31	44.6	13.1	66
I33008		0.60	0.070	0.30	1.98	15.7	<0.2	<10	190	2.35	1.28	0.65	0.25	43.8	12.6	62
I33009		0.52	<0.005	0.20	1.96	11.3	<0.2	<10	120	1.70	0.86	0.52	0.42	43.5	12.1	57
I33010		0.56	0.012	0.17	2.62	15.4	<0.2	<10	110	2.16	1.21	0.49	0.48	48.4	16.6	65
I33011		0.26	NSS	0.54	1.04	43.3	<0.2	<10	100	0.70	0.80	0.23	0.33	13.80	6.3	36
I33012		0.44	0.014	0.07	1.72	9.5	<0.2	<10	70	0.92	0.63	0.42	0.27	34.0	9.0	39
I33013		0.42	0.375	0.30	2.58	34.1	<0.2	<10	110	2.00	1.24	0.26	0.19	33.2	12.1	41
I33014		0.32	0.025	0.45	1.74	12.0	<0.2	<10	100	1.24	12.30	0.30	0.45	32.2	11.2	43
I33015		0.54	0.055	0.36	2.12	10.2	<0.2	<10	120	1.74	6.83	0.55	0.39	48.8	11.3	37
I33016		0.46	0.007	0.40	2.00	9.7	<0.2	<10	110	1.96	3.08	0.49	0.42	63.2	11.4	34
I33017		0.44	0.010	0.12	1.88	9.2	<0.2	<10	150	1.64	3.36	0.43	0.29	48.4	9.6	26
I33018		0.62	0.005	0.34	2.12	15.4	<0.2	<10	130	2.51	3.33	0.49	0.43	58.7	12.5	22
I33019		0.54	<0.005	0.81	2.02	14.7	<0.2	<10	150	2.27	4.97	0.46	0.87	75.6	12.7	25
I33020		0.40	<0.005	0.29	1.32	19.3	<0.2	<10	70	0.73	2.12	0.20	0.53	30.6	8.4	27

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method Analyte Units LOR	ME-MS41 Cs ppm 0.05	ME-MS41 Cu ppm 0.2	ME-MS41 Fe % 0.01	ME-MS41 Ga ppm 0.05	ME-MS41 Ge ppm 0.05	ME-MS41 Hf ppm 0.02	ME-MS41 Hg ppm 0.01	ME-MS41 In ppm 0.005	ME-MS41 K % 0.01	ME-MS41 La ppm 0.2	ME-MS41 Li ppm 0.1	ME-MS41 Mg % 0.01	ME-MS41 Mn ppm 5	ME-MS41 Mo ppm 0.05	ME-MS41 Na % 0.01
I30931		13.00	72.3	3.28	8.91	0.06	<0.02	0.06	0.061	0.16	19.7	20.4	0.58	1060	4.71	0.02
I30932		6.93	33.9	3.13	7.11	0.06	0.02	0.05	0.038	0.07	15.5	14.7	0.47	510	2.12	0.02
I30933		7.16	38.4	3.25	6.55	0.08	0.02	0.03	0.037	0.11	23.5	16.2	0.53	704	1.09	0.02
I30934		6.19	55.3	3.45	7.74	0.07	0.02	0.06	0.056	0.09	21.5	16.3	0.58	934	1.51	0.02
I30935		4.81	96.8	3.03	7.09	0.07	0.02	0.06	0.049	0.09	19.9	16.3	0.57	784	1.19	0.02
I30936		4.86	80.8	3.22	7.03	0.06	0.02	0.05	0.046	0.07	18.8	13.7	0.49	841	1.03	0.02
I30937		5.05	36.7	3.18	8.53	0.06	0.02	0.07	0.031	0.06	12.3	17.6	0.54	389	1.34	0.02
I30938		7.28	51.9	3.50	7.97	0.08	0.02	0.06	0.045	0.11	25.2	16.4	0.69	1070	0.98	0.02
I30939		4.84	54.7	3.64	8.33	0.09	0.03	0.08	0.036	0.10	24.5	19.0	0.67	773	1.01	0.02
I30940		5.11	42.5	3.28	8.05	0.08	0.03	0.05	0.035	0.10	21.5	19.9	0.61	928	0.91	0.02
I30941		11.20	37.1	3.90	10.70	0.08	0.03	0.03	0.059	0.27	29.4	19.2	1.31	3090	0.42	0.02
I30942		5.39	40.5	3.38	9.15	0.08	0.02	0.08	0.041	0.10	16.6	19.2	0.78	819	1.11	0.02
I30943		6.51	45.4	3.14	9.18	0.07	0.03	0.05	0.038	0.07	18.3	20.6	0.72	514	0.85	0.02
I30944		3.60	33.5	2.30	6.21	<0.05	0.02	0.08	0.024	0.04	12.2	10.8	0.38	260	0.96	0.02
I30945		3.91	26.6	2.92	7.62	0.06	0.02	0.03	0.029	0.04	15.3	16.8	0.53	388	0.72	0.02
I30946		3.20	32.9	2.25	6.49	0.05	0.02	0.07	0.027	0.03	10.7	9.1	0.35	197	1.07	0.02
I30947		12.10	36.3	3.53	8.18	0.06	0.02	0.03	0.078	0.11	31.4	19.6	0.72	722	5.96	0.02
I30948		14.05	50.7	3.35	6.97	0.09	0.02	0.03	0.052	0.13	28.2	18.0	0.73	722	3.87	0.02
I30949		19.50	50.4	3.54	8.39	0.09	0.03	0.03	0.053	0.15	38.7	19.2	0.82	1280	1.34	0.02
I30950		11.05	25.1	3.79	7.26	0.09	0.02	0.04	0.066	0.07	25.1	18.1	0.56	1870	5.08	0.01
I33001		5.05	34.6	3.00	6.27	0.10	0.03	0.03	0.035	0.07	20.3	15.7	0.54	927	0.85	0.01
I33002		6.10	39.3	2.95	6.99	0.10	0.03	0.04	0.033	0.08	19.6	17.4	0.59	689	0.78	0.02
I33003		4.65	36.9	3.13	6.75	0.11	0.04	0.03	0.031	0.08	20.7	16.7	0.59	442	0.75	0.01
I33004		5.71	59.2	2.95	7.51	0.10	0.04	0.05	0.033	0.08	18.2	19.5	0.68	388	0.79	0.02
I33005		3.40	27.5	2.69	7.14	0.07	0.03	0.06	0.031	0.05	9.3	13.6	0.39	284	1.19	0.01
I33006		3.65	42.1	2.82	6.08	0.10	0.04	0.03	0.024	0.07	14.0	20.0	0.61	565	0.76	0.01
I33007		8.14	61.1	3.34	7.74	0.14	0.03	0.02	0.029	0.17	22.2	20.9	0.63	1390	0.99	0.01
I33008		9.53	62.1	3.41	7.69	0.13	0.03	0.02	0.028	0.18	21.9	20.9	0.65	1450	0.98	0.01
I33009		5.45	51.4	3.12	7.14	0.11	0.04	0.03	0.028	0.14	20.8	21.0	0.64	885	0.81	0.01
I33010		5.84	53.7	3.48	9.61	0.12	0.04	0.05	0.040	0.13	21.6	27.3	0.82	1060	0.84	0.01
I33011		4.86	27.6	2.04	4.86	0.05	<0.02	0.08	0.019	0.10	7.3	9.6	0.32	289	1.22	0.02
I33012		2.78	33.3	2.62	5.26	0.09	0.05	0.02	0.023	0.06	16.2	14.3	0.50	389	0.65	0.02
I33013		5.58	58.7	3.05	9.20	0.08	0.04	0.06	0.033	0.07	16.1	24.6	0.74	425	1.21	0.02
I33014		5.71	74.2	3.16	7.32	0.09	0.02	0.10	0.032	0.10	15.0	17.8	0.55	942	1.38	0.02
I33015		7.90	114.5	3.17	7.99	0.12	0.04	0.02	0.039	0.17	24.0	24.3	0.79	638	1.16	0.02
I33016		6.34	80.0	3.12	7.07	0.12	0.03	0.04	0.037	0.10	29.2	19.0	0.67	935	2.24	0.02
I33017		7.27	35.0	2.87	6.39	0.08	<0.02	0.05	0.040	0.08	23.9	16.5	0.56	1470	1.61	0.01
I33018		8.66	33.7	3.09	6.70	0.10	0.03	0.03	0.050	0.08	29.7	17.1	0.60	2140	7.89	0.01
I33019		13.30	42.0	3.59	6.90	0.12	0.02	0.04	0.131	0.12	37.2	15.9	0.54	2170	5.51	0.01
I33020		6.06	23.0	2.99	6.86	0.07	0.02	0.11	0.035	0.05	13.7	9.7	0.31	589	3.23	0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I30931		2.26	14.5	1130	93.1	27.0	<0.001	0.06	1.11	2.8	0.5	1.2	235	<0.01	0.12	5.1
I30932		1.87	18.5	890	45.0	15.8	<0.001	0.06	1.22	1.9	0.5	1.0	43.5	<0.01	0.10	2.1
I30933		2.17	17.5	1620	50.2	22.0	<0.001	0.02	1.58	3.0	0.4	0.8	92.2	<0.01	0.13	11.1
I30934		2.11	18.8	1550	63.5	21.0	<0.001	0.03	1.92	2.7	0.4	1.0	37.6	<0.01	0.11	9.5
I30935		1.94	25.2	1480	65.5	22.3	<0.001	0.04	2.40	2.8	0.6	0.8	33.9	<0.01	0.18	3.2
I30936		1.26	18.9	1290	59.9	17.4	<0.001	0.05	3.43	1.7	0.4	0.9	35.9	<0.01	0.19	1.0
I30937		1.95	23.1	1010	30.1	19.9	<0.001	0.08	0.90	1.6	0.6	0.8	21.2	<0.01	0.06	0.4
I30938		2.12	25.9	1920	67.0	28.4	<0.001	0.04	2.19	3.3	0.5	0.8	44.6	0.01	0.17	6.9
I30939		2.53	29.1	2380	64.7	23.8	<0.001	0.04	1.12	3.2	0.6	0.8	42.5	0.01	0.04	5.0
I30940		2.55	29.9	2000	58.4	26.2	<0.001	0.04	1.26	2.6	0.5	0.8	37.4	<0.01	0.05	2.4
I30941		1.34	27.4	2030	36.8	47.3	<0.001	0.02	0.92	6.1	0.3	1.0	148.5	<0.01	0.19	11.0
I30942		1.98	27.0	1510	41.3	25.5	<0.001	0.09	0.83	2.3	0.6	0.7	32.0	<0.01	0.05	1.0
I30943		2.53	25.0	1530	42.3	18.8	<0.001	0.06	0.85	2.8	0.5	0.8	33.2	<0.01	0.03	1.3
I30944		1.37	18.0	1110	24.6	11.2	<0.001	0.10	0.72	1.1	0.6	0.6	29.6	<0.01	0.03	<0.2
I30945		1.79	21.9	1360	26.2	10.3	<0.001	0.05	0.64	1.3	0.4	0.6	29.7	<0.01	0.04	0.4
I30946		1.26	16.7	1200	23.7	8.4	<0.001	0.12	0.60	1.1	0.6	0.6	24.3	<0.01	0.04	<0.2
I30947		2.07	14.4	1260	44.1	25.7	<0.001	0.09	1.09	3.3	0.6	1.6	123.0	<0.01	0.11	9.4
I30948		2.13	22.6	1420	35.3	25.6	<0.001	0.06	1.19	4.2	0.6	1.0	77.6	<0.01	0.07	9.4
I30949		1.93	25.5	1400	38.5	29.1	<0.001	0.02	0.85	6.1	0.5	1.1	178.0	0.01	0.05	14.7
I30950		1.45	14.6	1140	53.6	15.8	<0.001	0.08	1.02	2.8	0.9	1.2	67.5	<0.01	0.25	6.7
I33001		1.76	21.0	2000	22.6	17.3	<0.001	0.03	0.78	3.0	0.5	0.5	41.2	<0.01	0.03	2.9
I33002		2.02	21.8	1930	33.5	19.6	<0.001	0.03	0.77	3.8	0.5	0.6	84.5	<0.01	0.02	3.6
I33003		2.25	21.7	2130	26.9	18.4	<0.001	0.02	0.79	3.8	0.5	0.6	51.7	<0.01	0.02	5.6
I33004		2.38	25.1	1760	70.5	19.1	<0.001	0.03	0.85	4.4	0.6	0.6	47.9	<0.01	0.03	4.0
I33005		1.47	20.5	1210	23.4	11.7	<0.001	0.09	0.80	1.3	0.6	0.6	19.4	<0.01	0.04	0.2
I33006		1.89	29.6	1420	24.8	14.4	<0.001	0.03	0.70	2.9	0.5	0.5	29.4	<0.01	0.02	1.9
I33007		1.71	28.9	2240	31.7	31.4	<0.001	0.02	1.21	4.4	0.5	0.7	101.5	<0.01	0.04	5.9
I33008		1.48	27.8	2160	27.6	32.2	<0.001	0.01	1.29	4.8	0.4	0.7	125.0	<0.01	0.04	6.6
I33009		2.20	29.6	1850	30.4	29.9	<0.001	0.02	0.75	4.8	0.5	0.7	49.6	<0.01	0.03	6.0
I33010		2.48	35.1	2130	59.3	26.6	<0.001	0.04	0.63	3.9	0.5	0.8	31.3	<0.01	0.10	4.1
I33011		1.19	23.7	1890	16.3	22.6	<0.001	0.21	0.70	0.7	0.6	0.6	27.9	<0.01	0.03	<0.2
I33012		1.67	24.4	1540	20.5	12.3	<0.001	0.03	0.59	3.0	0.5	0.5	25.9	<0.01	0.02	3.1
I33013		2.56	27.0	1290	62.6	18.9	<0.001	0.11	0.75	3.1	0.7	0.8	29.7	<0.01	0.04	1.2
I33014		1.44	22.6	1540	65.6	25.5	<0.001	0.09	0.84	1.8	0.5	1.0	39.1	<0.01	0.05	0.6
I33015		2.09	21.1	1700	55.2	30.5	<0.001	0.02	0.92	4.6	0.5	1.2	84.2	<0.01	0.10	13.0
I33016		1.87	20.8	1480	55.9	22.9	<0.001	0.02	0.78	4.6	0.6	0.8	55.1	<0.01	0.07	16.5
I33017		1.17	13.5	1190	86.5	17.3	<0.001	0.04	1.12	2.1	0.4	0.7	142.0	<0.01	0.06	6.6
I33018		1.15	11.7	1130	82.0	16.6	<0.001	0.02	1.11	2.9	0.6	0.8	89.9	<0.01	0.12	20.7
I33019		1.25	15.9	1380	68.8	26.2	<0.001	0.02	1.06	4.1	0.7	0.9	130.5	<0.01	0.24	15.5
I33020		1.24	12.9	1310	45.9	11.0	<0.001	0.13	0.83	1.2	0.6	0.8	33.6	<0.01	0.30	0.7

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I30931		0.041	0.26	6.79	66	0.55	9.21	148	<0.5
I30932		0.076	0.17	2.91	74	0.58	5.85	91	0.8
I30933		0.084	0.20	3.52	83	0.63	12.10	112	0.6
I30934		0.074	0.23	6.36	82	0.90	9.71	142	0.6
I30935		0.081	0.21	4.22	77	0.64	9.49	124	0.6
I30936		0.053	0.22	3.51	89	0.67	8.06	113	<0.5
I30937		0.074	0.21	1.67	85	0.45	4.73	80	0.8
I30938		0.082	0.24	4.45	92	0.62	10.75	112	0.7
I30939		0.082	0.27	3.13	104	0.71	10.95	117	0.9
I30940		0.099	0.20	2.71	93	0.70	10.45	108	1.1
I30941		0.053	0.58	2.71	105	0.52	13.70	127	0.7
I30942		0.072	0.19	3.00	82	0.48	7.99	110	0.9
I30943		0.094	0.18	3.39	79	0.51	8.94	109	1.4
I30944		0.046	0.16	1.86	55	0.40	5.88	60	0.8
I30945		0.073	0.13	1.74	75	0.48	6.60	87	0.8
I30946		0.045	0.15	2.23	57	0.37	5.23	51	0.9
I30947		0.047	0.22	13.00	68	0.52	15.60	84	<0.5
I30948		0.085	0.22	12.65	82	0.50	12.60	83	0.7
I30949		0.079	0.28	11.40	81	0.50	18.60	86	0.9
I30950		0.049	0.32	16.15	65	0.50	12.25	80	<0.5
I33001		0.094	0.16	2.42	75	0.69	9.91	81	1.2
I33002		0.104	0.16	3.13	77	0.63	11.00	89	1.4
I33003		0.112	0.14	2.68	85	0.76	11.10	91	1.9
I33004		0.118	0.17	3.10	78	0.50	11.55	106	1.6
I33005		0.070	0.15	1.27	78	0.43	4.41	62	0.9
I33006		0.108	0.13	1.38	77	0.47	7.62	74	1.4
I33007		0.112	0.22	4.11	100	0.68	12.15	84	1.0
I33008		0.114	0.22	4.41	97	0.69	12.45	82	1.2
I33009		0.130	0.18	3.50	89	0.69	12.05	83	1.8
I33010		0.124	0.30	2.89	102	0.77	10.75	112	1.3
I33011		0.033	0.15	1.62	55	0.43	3.48	46	0.6
I33012		0.099	0.13	1.30	68	0.48	8.46	64	1.6
I33013		0.105	0.30	3.03	79	0.62	8.15	94	1.5
I33014		0.070	0.23	2.74	85	0.97	7.12	91	0.7
I33015		0.133	0.24	6.36	80	1.15	12.90	109	1.4
I33016		0.099	0.19	12.50	69	0.72	15.35	117	1.0
I33017		0.038	0.19	6.21	60	0.57	11.20	84	<0.5
I33018		0.025	0.21	9.08	51	0.30	12.10	132	0.8
I33019		0.049	0.26	13.20	61	0.46	16.35	208	0.5
I33020		0.047	0.17	3.78	66	0.45	5.86	69	0.7

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1	ME-MS41 Cr ppm 1
I33021		0.52	0.008	0.31	2.19	52.5	<0.2	<10	170	2.20	2.18	0.67	0.42	77.1	12.4	25
I34401		0.56	0.019	0.28	1.70	31.4	<0.2	<10	120	2.05	2.75	0.50	0.55	52.1	11.7	31
I34402		0.36	0.006	0.40	2.56	68.7	<0.2	<10	120	2.30	3.03	0.51	1.01	42.1	14.8	40
I34403		0.46	0.007	0.45	2.57	109.5	<0.2	<10	110	1.85	5.44	0.26	0.20	33.1	9.4	41
I34404		0.44	<0.005	0.20	1.70	12.1	<0.2	<10	120	1.61	3.61	0.35	0.46	52.9	10.7	33
I34405		0.42	<0.005	0.24	1.88	11.0	<0.2	<10	150	1.65	1.94	0.47	0.47	48.9	10.5	37
I34406		0.48	0.018	0.11	1.50	7.8	<0.2	<10	70	0.74	0.88	0.36	0.24	32.5	8.1	34
I34407		0.68	0.011	0.11	1.47	7.2	<0.2	<10	80	1.00	1.30	0.53	0.51	38.8	7.9	42
I34408		0.52	0.019	0.19	1.73	8.3	<0.2	<10	90	1.22	2.07	0.42	0.43	37.6	10.0	47
I34409		0.56	0.022	0.22	2.15	8.9	<0.2	<10	110	1.63	1.88	0.45	0.53	37.7	10.7	41
I34410		0.48	0.050	0.12	1.76	8.7	<0.2	<10	90	1.07	1.17	0.49	0.37	37.7	9.5	50
I34411		0.62	0.106	0.17	1.95	8.9	<0.2	<10	110	1.48	1.93	0.57	0.48	43.8	10.2	49
I34412		0.58	0.011	0.12	2.04	38.9	<0.2	<10	120	1.78	1.82	0.28	0.20	25.4	10.2	27
I34413		0.58	<0.005	0.12	2.16	10.8	<0.2	<10	120	1.37	0.98	0.43	0.30	32.7	9.9	46
I34414		0.40	<0.005	0.08	2.01	9.4	<0.2	<10	90	1.65	4.32	0.47	0.24	42.7	10.9	44
I34415		0.42	0.008	0.07	1.86	9.2	<0.2	<10	100	1.70	0.89	0.62	0.24	43.0	11.4	60
I34416		0.48	0.039	0.08	2.51	11.6	<0.2	<10	130	2.44	0.59	0.82	0.28	58.5	15.6	80
I34417		0.56	<0.005	0.07	3.46	12.0	<0.2	<10	140	4.57	0.35	0.98	0.25	63.5	19.7	64
I34418		0.46	0.009	0.13	1.99	8.8	<0.2	<10	110	1.44	0.68	0.41	0.43	35.0	10.3	39
I34419		0.44	<0.005	0.05	1.59	7.9	<0.2	<10	80	0.83	0.68	0.42	0.29	29.7	9.6	45
I34420		0.48	<0.005	0.11	1.80	7.6	<0.2	<10	110	1.30	1.26	0.51	0.23	36.2	10.5	58
I34421		0.44	<0.005	0.11	1.80	7.3	<0.2	<10	110	1.32	1.25	0.53	0.26	35.7	10.3	57
I34422		0.26	0.008	0.11	2.42	10.0	<0.2	<10	390	2.32	1.55	0.54	0.31	56.1	7.8	18
I34423		0.30	0.215	1.46	2.00	15.2	1.3	<10	210	1.93	61.4	0.42	0.26	49.4	10.2	18
I34424		0.34	0.007	0.10	1.68	8.0	<0.2	<10	160	1.78	1.16	0.66	0.40	48.9	9.9	27
I34425		0.38	0.011	0.12	2.60	7.5	<0.2	<10	390	2.60	4.00	1.03	0.34	67.3	9.1	13
I34426		0.26	0.012	0.10	1.45	8.1	<0.2	<10	110	1.10	1.93	0.48	0.18	40.2	8.6	39
I34427		0.28	0.005	0.26	1.30	7.7	<0.2	<10	80	0.80	7.03	0.44	0.13	33.4	6.7	33
I34428		0.44	<0.005	0.13	1.67	9.4	<0.2	<10	110	1.30	2.56	0.32	0.34	44.5	10.1	30
I34429		0.24	0.006	0.28	2.00	7.4	<0.2	<10	100	1.62	3.50	0.37	0.39	25.6	8.3	25
I34430		0.30	0.105	0.19	2.41	12.3	0.6	<10	110	2.31	2.93	0.40	0.18	50.1	10.9	24
I34431		0.36	0.006	0.30	2.27	8.4	<0.2	<10	130	1.85	2.21	0.48	0.26	40.7	8.3	25
I34432		0.40	0.005	0.12	1.82	7.2	<0.2	<10	110	1.21	1.60	0.57	0.34	37.6	6.9	23
I34433		0.38	<0.005	0.12	2.12	21.9	<0.2	<10	110	1.40	2.08	0.33	0.12	37.3	8.5	19
I34434		0.42	<0.005	0.21	2.15	30.7	<0.2	<10	110	1.55	2.40	0.47	0.24	46.3	11.5	21
I34435		0.42	0.006	0.16	1.97	23.9	<0.2	<10	100	1.28	2.12	0.32	0.24	42.7	11.8	23
I34436		0.38	0.005	0.20	1.80	23.9	<0.2	<10	110	1.43	1.94	0.37	0.26	43.4	11.5	21
I34437		0.32	0.010	0.37	2.55	25.9	<0.2	<10	130	1.96	3.18	0.27	0.33	43.2	17.5	26
I34438		0.34	0.005	0.15	2.32	50.2	<0.2	<10	70	1.26	1.85	0.24	0.25	49.6	12.3	24
I34439		0.26	<0.005	0.24	1.56	13.9	<0.2	<10	120	0.78	1.28	0.20	0.29	28.4	5.7	21

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I33021		14.05	35.2	3.36	7.13	0.12	0.02	0.03	0.043	0.13	38.9	18.6	0.52	1740	4.57	0.02
I34401		9.34	36.4	3.35	6.30	0.11	0.03	0.02	0.042	0.12	25.2	18.3	0.56	830	3.07	0.01
I34402		8.85	54.6	3.18	9.14	0.10	0.03	0.06	0.042	0.12	20.6	23.2	0.77	1170	1.82	0.02
I34403		6.24	51.1	3.40	9.26	0.09	0.03	0.05	0.039	0.06	18.0	22.3	0.70	611	1.57	0.01
I34404		7.02	41.7	3.36	6.45	0.10	0.02	0.03	0.046	0.12	26.6	16.4	0.48	697	3.20	0.02
I34405		7.79	35.0	3.17	6.71	0.10	0.03	0.03	0.033	0.10	24.3	17.3	0.53	716	1.76	0.02
I34406		2.66	26.9	2.58	5.06	0.09	0.03	0.02	0.024	0.06	15.8	13.2	0.45	400	0.70	0.01
I34407		3.40	32.3	2.80	5.56	0.11	0.03	0.01	0.024	0.09	19.5	14.1	0.51	379	0.65	0.02
I34408		3.67	44.6	3.09	6.55	0.11	0.03	0.03	0.026	0.08	18.7	17.0	0.51	543	0.87	0.01
I34409		4.92	51.7	3.04	7.54	0.10	0.03	0.07	0.029	0.12	18.3	20.4	0.68	677	0.93	0.02
I34410		3.76	33.6	3.12	6.34	0.10	0.03	0.03	0.027	0.09	19.1	18.2	0.53	502	0.71	0.02
I34411		5.17	49.3	3.27	7.55	0.12	0.03	0.06	0.029	0.14	22.3	19.4	0.65	637	0.91	0.02
I34412		4.43	39.2	2.62	7.65	0.07	0.02	0.05	0.026	0.07	12.7	18.7	0.60	507	0.82	0.02
I34413		4.96	35.2	3.35	9.13	0.09	0.02	0.02	0.026	0.11	16.2	20.3	0.71	456	0.95	0.01
I34414		5.28	40.2	3.15	7.28	0.12	0.03	0.04	0.027	0.13	20.3	21.3	0.66	602	0.73	0.02
I34415		6.78	38.4	3.42	7.42	0.13	0.02	0.03	0.028	0.26	21.9	21.7	0.70	724	0.78	0.02
I34416		8.99	48.8	4.31	10.30	0.18	0.03	0.02	0.032	0.41	29.2	30.9	1.03	887	0.69	0.02
I34417		13.45	57.1	4.30	12.90	0.20	0.03	0.01	0.036	0.68	34.7	46.3	1.48	1080	0.53	0.02
I34418		3.47	42.9	3.08	6.50	0.10	0.05	0.07	0.028	0.09	17.8	16.5	0.59	307	0.87	0.02
I34419		3.12	24.9	2.87	5.73	0.09	0.04	0.04	0.024	0.06	15.6	16.4	0.49	418	0.72	0.02
I34420		4.96	39.5	3.06	6.62	0.10	0.05	0.03	0.025	0.08	19.4	16.8	0.57	451	1.01	0.02
I34421		4.82	37.6	2.99	6.64	0.10	0.04	0.02	0.026	0.08	19.3	16.7	0.57	450	0.87	0.02
I34422		18.80	16.3	3.20	7.13	0.09	0.02	0.03	0.079	0.12	27.0	17.2	0.56	2320	2.24	0.02
I34423		12.35	21.8	3.01	6.45	0.08	<0.02	0.04	0.052	0.10	26.2	16.9	0.51	1460	1.92	0.02
I34424		9.98	28.7	2.78	5.79	0.08	0.03	0.02	0.037	0.13	24.1	17.5	0.58	803	0.71	0.02
I34425		15.60	21.6	2.97	7.58	0.10	0.04	0.02	0.063	0.18	38.9	18.3	0.69	2050	0.69	0.02
I34426		7.19	24.0	2.89	5.60	0.09	0.02	0.02	0.026	0.09	19.9	17.5	0.57	583	0.89	0.02
I34427		6.51	18.3	2.80	5.28	0.08	<0.02	0.02	0.031	0.07	17.5	12.8	0.47	420	0.76	0.02
I34428		4.83	30.4	2.92	6.00	0.09	0.02	0.04	0.029	0.09	21.0	16.6	0.54	784	1.23	0.02
I34429		5.98	52.1	2.75	7.39	0.07	<0.02	0.05	0.039	0.10	14.1	16.1	0.59	779	1.34	0.02
I34430		8.03	47.4	3.33	8.26	0.10	<0.02	0.03	0.056	0.07	27.9	16.7	0.59	977	1.59	0.02
I34431		5.31	30.7	2.85	7.34	0.08	<0.02	0.04	0.042	0.08	22.6	16.8	0.60	745	1.27	0.02
I34432		4.49	19.7	2.85	6.27	0.10	<0.02	0.02	0.038	0.07	20.5	15.5	0.54	513	0.83	0.01
I34433		8.49	32.7	2.95	7.11	0.07	<0.02	0.02	0.055	0.06	20.0	17.1	0.51	635	2.22	0.02
I34434		10.20	34.8	3.35	7.00	0.10	<0.02	0.03	0.054	0.08	23.2	19.2	0.60	830	2.99	0.02
I34435		7.38	29.0	3.41	6.48	0.10	0.02	0.02	0.057	0.07	20.9	18.4	0.57	673	2.59	0.02
I34436		7.31	28.9	3.34	6.16	0.10	0.02	0.01	0.047	0.07	21.1	17.8	0.56	717	2.58	0.02
I34437		8.68	43.5	3.86	7.56	0.09	0.02	0.04	0.075	0.08	22.0	21.6	0.60	919	6.42	0.02
I34438		5.76	29.4	3.55	7.18	0.10	0.02	0.06	0.059	0.06	25.9	19.4	0.57	620	3.47	0.02
I34439		6.48	21.1	2.54	6.09	0.07	<0.02	0.07	0.054	0.04	15.1	10.6	0.38	307	1.47	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method Analyte Units LOR	ME-MS41 Nb ppm 0.05	ME-MS41 Ni ppm 0.2	ME-MS41 P ppm 10	ME-MS41 Pb ppm 0.2	ME-MS41 Rb ppm 0.1	ME-MS41 Re ppm 0.001	ME-MS41 S % 0.01	ME-MS41 Sb ppm 0.05	ME-MS41 Sc ppm 0.1	ME-MS41 Se ppm 0.2	ME-MS41 Sn ppm 0.2	ME-MS41 Sr ppm 0.2	ME-MS41 Ta ppm 0.01	ME-MS41 Te ppm 0.01	ME-MS41 Th ppm 0.2
I33021		1.44	11.3	1340	76.0	21.9	<0.001	0.04	0.70	3.4	0.6	1.0	442	<0.01	0.20	12.8
I34401		1.81	13.8	1370	66.5	21.5	<0.001	0.05	0.77	3.0	0.5	0.9	152.5	<0.01	0.27	15.6
I34402		2.73	21.1	1290	56.7	33.3	<0.001	0.11	0.80	4.3	0.6	1.1	68.6	<0.01	0.10	4.3
I34403		2.43	19.0	1190	46.5	19.6	<0.001	0.20	0.71	3.1	0.5	1.1	41.0	<0.01	0.09	1.9
I34404		1.93	14.6	1260	51.0	22.2	<0.001	0.08	0.86	2.7	0.5	1.0	89.8	<0.01	0.11	12.8
I34405		1.78	18.0	1490	45.9	22.0	<0.001	0.03	0.90	3.0	0.5	0.8	147.0	<0.01	0.08	8.8
I34406		1.69	17.9	1260	20.2	14.3	<0.001	0.02	0.84	2.5	0.4	0.6	30.6	<0.01	0.03	5.8
I34407		1.67	17.8	1740	24.2	23.0	<0.001	0.01	0.76	3.8	0.3	0.8	36.8	<0.01	0.03	4.9
I34408		2.11	19.6	1660	29.4	20.3	<0.001	0.02	2.73	3.0	0.4	0.8	32.8	<0.01	0.04	6.4
I34409		2.34	22.0	1560	34.9	29.1	<0.001	0.03	2.05	4.0	0.5	0.8	41.2	<0.01	0.04	3.7
I34410		2.06	20.6	1940	29.9	20.4	<0.001	0.02	1.34	2.8	0.4	0.7	38.6	<0.01	0.03	5.9
I34411		2.26	21.6	1930	36.4	29.1	<0.001	0.02	1.26	4.6	0.5	0.9	55.6	<0.01	0.04	9.9
I34412		1.81	17.9	970	33.6	17.8	<0.001	0.09	0.57	2.0	0.5	0.7	43.9	<0.01	0.04	0.6
I34413		2.33	20.9	1400	46.5	22.1	<0.001	0.04	0.78	2.3	0.4	1.0	48.3	<0.01	0.06	1.0
I34414		2.45	24.5	1630	23.2	29.8	<0.001	0.03	0.61	4.5	0.5	0.8	42.9	<0.01	0.03	4.0
I34415		2.79	23.3	2350	20.6	49.9	<0.001	0.02	0.93	4.8	0.4	0.9	53.0	<0.01	0.02	4.9
I34416		2.98	30.3	3200	23.5	77.6	<0.001	0.02	1.12	7.2	0.6	1.1	66.5	<0.01	0.02	10.1
I34417		1.80	35.9	3150	19.5	127.5	<0.001	0.01	0.54	10.6	0.6	1.5	97.0	<0.01	0.01	12.8
I34418		2.13	23.9	1650	25.8	22.0	<0.001	0.03	0.57	4.2	0.6	0.6	39.8	0.01	0.04	3.8
I34419		1.65	21.3	1530	13.8	14.2	<0.001	0.04	0.62	2.0	0.5	0.5	66.0	<0.01	0.02	1.3
I34420		2.38	21.6	1950	22.5	19.1	<0.001	0.02	0.78	3.2	0.4	0.6	100.0	<0.01	0.04	5.5
I34421		2.40	21.6	2010	22.1	19.5	<0.001	0.02	0.66	3.2	0.4	0.6	103.5	<0.01	0.04	5.9
I34422		1.67	8.4	950	90.9	20.8	<0.001	0.05	0.88	2.4	0.5	1.0	444	<0.01	0.07	9.7
I34423		1.30	8.8	980	50.7	19.3	<0.001	0.07	1.13	1.6	0.4	1.1	198.0	<0.01	0.15	5.8
I34424		1.08	15.4	1270	34.6	20.1	<0.001	0.02	0.53	3.8	0.5	0.8	112.5	<0.01	0.04	11.4
I34425		0.77	6.3	1220	60.2	29.3	<0.001	0.02	0.66	3.6	0.4	1.4	444	<0.01	0.03	18.6
I34426		1.95	15.7	1490	33.1	20.0	<0.001	0.03	0.68	2.5	0.4	0.7	65.2	<0.01	0.13	8.8
I34427		1.17	13.8	970	26.6	14.9	<0.001	0.03	0.68	1.8	0.4	0.7	52.0	<0.01	0.11	2.7
I34428		1.70	18.6	1090	33.0	20.4	<0.001	0.04	0.70	2.8	0.4	0.8	35.9	<0.01	0.30	7.3
I34429		1.41	15.5	1290	66.8	28.4	<0.001	0.09	0.68	1.7	0.4	1.0	62.6	<0.01	0.10	1.1
I34430		0.89	12.6	1020	54.5	19.1	<0.001	0.05	0.81	1.7	0.5	2.5	78.3	<0.01	0.09	2.3
I34431		1.34	12.3	1260	44.0	18.3	<0.001	0.06	0.52	2.1	0.5	1.0	96.4	<0.01	0.09	4.3
I34432		1.60	9.9	1410	33.3	13.8	<0.001	0.03	0.50	2.0	0.4	1.0	105.5	<0.01	0.07	8.9
I34433		0.90	10.9	840	40.6	13.7	<0.001	0.05	0.60	1.3	0.5	1.4	78.4	<0.01	0.09	1.4
I34434		1.34	13.7	1150	47.1	15.8	<0.001	0.04	0.61	2.4	0.7	1.3	83.8	<0.01	0.12	5.2
I34435		1.52	14.4	1060	48.9	13.3	<0.001	0.03	0.60	2.5	0.6	1.4	65.8	<0.01	0.11	4.8
I34436		1.58	14.2	1100	47.7	13.5	<0.001	0.03	0.60	2.7	0.6	1.4	69.9	<0.01	0.11	8.0
I34437		1.51	18.5	1170	69.9	13.8	<0.001	0.05	0.84	2.8	1.2	1.3	78.0	<0.01	0.17	5.8
I34438		1.53	13.6	1060	68.9	10.8	<0.001	0.06	0.85	2.1	1.2	1.2	49.1	<0.01	0.13	4.1
I34439		0.91	10.8	830	28.5	12.4	<0.001	0.08	0.62	0.8	0.6	1.2	86.2	<0.01	0.08	0.3

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I33021		0.043	0.20	13.80	69	0.48	18.00	133	<0.5
I34401		0.063	0.20	10.15	73	0.54	11.80	180	0.8
I34402		0.101	0.30	8.40	79	0.81	10.90	156	1.3
I34403		0.092	0.28	5.19	83	0.76	7.54	111	1.1
I34404		0.072	0.24	10.05	76	0.64	10.65	111	0.6
I34405		0.081	0.20	6.38	78	0.55	11.25	103	0.6
I34406		0.094	0.15	2.31	70	0.53	7.94	64	1.1
I34407		0.111	0.17	2.22	80	0.75	10.75	86	1.1
I34408		0.100	0.19	2.82	88	0.84	9.08	88	0.9
I34409		0.119	0.22	2.97	82	0.68	9.84	100	1.0
I34410		0.095	0.19	2.54	88	0.67	9.38	99	1.1
I34411		0.121	0.22	3.68	93	0.74	12.10	106	1.2
I34412		0.077	0.21	2.15	69	0.41	6.13	74	1.0
I34413		0.102	0.22	1.78	97	0.57	7.02	93	0.8
I34414		0.126	0.18	3.03	88	0.70	11.20	79	1.2
I34415		0.142	0.25	2.92	107	1.02	12.15	78	1.2
I34416		0.173	0.33	4.09	141	0.94	17.05	90	1.4
I34417		0.222	0.48	7.76	142	0.65	20.4	98	1.3
I34418		0.103	0.17	2.22	74	0.42	10.10	86	1.7
I34419		0.088	0.11	2.29	77	0.47	7.53	67	1.2
I34420		0.101	0.16	2.27	89	1.27	8.58	85	2.0
I34421		0.101	0.15	2.28	87	0.68	8.65	85	2.1
I34422		0.026	0.26	9.85	50	0.46	11.95	73	<0.5
I34423		0.021	0.20	7.84	46	1.10	9.44	70	<0.5
I34424		0.059	0.20	10.65	62	0.77	12.60	82	1.0
I34425		0.021	0.26	7.07	48	1.06	15.95	89	0.9
I34426		0.073	0.16	4.43	74	0.68	9.52	85	0.7
I34427		0.060	0.12	3.99	68	0.45	7.57	62	<0.5
I34428		0.078	0.18	6.54	68	0.58	8.80	81	0.7
I34429		0.047	0.22	3.66	65	0.55	5.80	128	<0.5
I34430		0.027	0.34	15.00	57	0.93	13.30	77	<0.5
I34431		0.037	0.19	6.89	62	0.42	11.15	81	<0.5
I34432		0.043	0.15	4.94	61	0.39	11.05	75	<0.5
I34433		0.031	0.24	6.01	51	0.38	7.81	68	<0.5
I34434		0.046	0.20	7.56	53	0.36	9.70	86	<0.5
I34435		0.063	0.18	5.89	59	0.36	8.66	85	<0.5
I34436		0.065	0.18	6.02	58	0.37	9.32	85	0.5
I34437		0.060	0.28	11.25	59	0.40	9.39	104	0.5
I34438		0.053	0.19	9.88	53	0.29	9.88	91	0.7
I34439		0.035	0.17	3.24	53	0.28	5.82	70	<0.5

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1	ME-MS41 Cr ppm 1
I34440		0.36	<0.005	0.08	1.76	18.4	<0.2	<10	80	0.82	1.29	0.24	0.28	28.6	9.5	24
I34441		0.44	0.039	0.08	1.52	5.3	<0.2	<10	60	0.73	0.80	0.30	0.21	27.8	7.3	23
I34442		0.40	<0.005	0.04	1.83	8.3	<0.2	<10	80	0.59	0.44	0.28	0.20	24.1	6.7	27
I34443		0.34	0.021	0.13	1.72	8.7	<0.2	<10	120	1.12	0.80	0.35	0.16	19.85	5.3	16
I34444		0.40	<0.005	0.05	1.85	5.9	<0.2	<10	180	1.90	0.27	0.50	0.18	39.8	7.7	27
I34445		0.36	0.013	0.13	1.70	6.4	<0.2	<10	130	1.80	1.10	0.44	0.23	45.1	5.5	15
I34446		0.42	0.009	0.14	1.99	13.7	<0.2	<10	160	3.33	3.51	0.92	0.44	78.7	8.5	16
I34447		0.54	<0.005	0.13	2.01	22.1	<0.2	<10	210	3.21	4.73	0.74	0.28	68.8	7.6	14
I34448		0.42	0.008	0.34	2.01	18.3	<0.2	<10	130	2.04	1.64	0.43	0.51	44.9	11.0	23
I34449		0.48	0.015	0.82	2.02	24.0	<0.2	<10	160	2.57	7.40	0.68	0.82	76.3	12.8	15
I34450		0.48	0.010	0.36	1.96	18.3	<0.2	<10	180	3.33	2.77	0.48	0.48	39.4	8.6	15

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I34440		5.91	23.1	2.91	6.88	0.08	0.02	0.05	0.040	0.06	13.6	16.4	0.50	458	1.41	0.01
I34441		3.26	16.6	1.98	4.53	0.08	0.05	0.02	0.028	0.05	15.0	12.5	0.39	377	0.57	0.01
I34442		7.25	16.5	2.61	7.24	0.07	0.02	0.02	0.030	0.06	11.4	13.0	0.45	347	0.73	0.03
I34443		3.57	15.5	1.72	5.61	0.05	<0.02	0.06	0.028	0.04	10.8	6.5	0.30	366	0.79	0.02
I34444		9.50	17.7	2.27	5.62	0.09	0.02	0.03	0.028	0.06	24.0	16.2	0.58	499	0.60	0.02
I34445		8.22	44.8	1.82	5.27	0.07	0.02	0.04	0.067	0.06	25.8	9.6	0.39	1100	0.83	0.02
I34446		10.90	20.4	2.17	5.37	0.10	0.03	0.03	0.078	0.10	42.5	13.7	0.43	1100	0.83	0.02
I34447		8.84	32.1	2.05	6.35	0.09	0.02	0.05	0.113	0.08	37.2	14.6	0.50	580	0.84	0.02
I34448		10.30	99.1	2.56	6.04	0.09	0.02	0.10	0.088	0.08	24.2	16.4	0.51	748	2.83	0.03
I34449		13.05	109.5	3.53	5.73	0.12	0.03	0.06	0.190	0.23	43.1	14.5	0.39	1290	6.12	0.04
I34450		10.40	146.0	2.61	5.76	0.08	<0.02	0.05	0.068	0.10	22.1	16.8	0.42	642	4.90	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I34440		1.61	15.8	840	22.3	13.3	<0.001	0.05	0.73	2.0	0.5	1.4	30.8	<0.01	0.09	1.4
I34441		1.62	14.7	910	26.3	9.2	<0.001	0.02	0.42	2.4	0.3	0.6	34.1	<0.01	0.02	3.7
I34442		2.04	14.4	710	24.6	13.1	<0.001	0.04	0.57	1.8	0.3	1.1	30.0	<0.01	0.05	1.5
I34443		1.09	7.8	1050	25.1	9.7	<0.001	0.10	0.43	0.7	0.5	0.8	66.6	<0.01	0.08	0.3
I34444		1.16	16.5	950	26.0	10.4	<0.001	0.02	0.42	3.3	0.4	0.6	180.5	<0.01	0.03	7.1
I34445		0.93	8.9	900	32.1	15.4	<0.001	0.07	0.65	1.4	0.5	0.8	120.0	<0.01	0.16	6.8
I34446		1.15	9.4	940	65.7	14.4	<0.001	0.02	0.45	2.7	0.5	1.5	184.5	<0.01	0.29	21.6
I34447		1.27	7.1	1020	52.5	13.7	<0.001	0.04	0.56	1.8	0.5	2.2	232	<0.01	0.08	13.8
I34448		1.27	16.6	1040	145.0	12.8	<0.001	0.06	0.87	3.1	0.9	1.3	167.0	<0.01	0.07	7.4
I34449		1.08	6.8	1020	169.0	28.4	<0.001	0.32	1.24	3.1	1.2	2.1	221	<0.01	0.12	37.6
I34450		1.64	10.2	950	113.5	17.7	<0.001	0.05	0.92	2.1	0.8	1.1	173.5	0.01	0.15	15.0

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I34440		0.080	0.15	2.91	64	0.34	5.33	71	0.9
I34441		0.084	0.09	2.42	45	0.21	6.09	54	1.8
I34442		0.093	0.10	1.63	59	0.31	4.40	56	1.0
I34443		0.021	0.17	3.43	38	0.24	3.79	42	<0.5
I34444		0.063	0.11	7.39	50	0.22	10.60	60	0.6
I34445		0.016	0.16	5.04	33	0.19	8.96	58	<0.5
I34446		0.021	0.20	12.50	39	0.32	18.30	63	0.6
I34447		0.014	0.22	13.90	33	0.23	15.70	69	<0.5
I34448		0.041	0.21	29.4	47	0.29	12.40	155	<0.5
I34449		0.021	0.42	36.1	43	0.30	22.1	217	<0.5
I34450		0.026	0.25	28.9	39	0.29	11.30	150	<0.5

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089648

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 19-AUG-2010
Account: EIASQI

CERTIFICATE VA10106009

Project: SQI10-04

P.O. No.: SQI10-01_04

This report is for 1 Other sample submitted to our lab in Vancouver, BC, Canada on 4-AUG-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
FND-03	Find Reject for Addn Analysis
BAG-01	Bulk Master for Storage
SPL-21	Split sample - riffle splitter
PUL-32	Pulverize 1000g to 85% < 75 um
SCR-21	Screen to -100 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-SCR21	Au Screen Fire Assay - 100 um	WST-SIM
Au-AA25	Ore Grade Au 30g FA AA finish	AAS
Au-AA25D	Ore Grade Au 30g FA AA Dup	AAS

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 19-AUG-2010
Account: EIASQI

Project: SQI10-04

CERTIFICATE OF ANALYSIS VA10106009

Sample Description	Method Analyte Units LOR	Au-SCR21 Au Total ppm 0.05	Au-SCR21 Au (+) F ppm 0.05	Au-SCR21 Au (-) F ppm 0.05	Au-SCR21 Au (+) m mg 0.001	Au-SCR21 WT. + Fr g 0.01	Au-SCR21 WT. - Fr g 0.1	Au-AA25 Au ppm 0.01	Au-AA25D Au ppm 0.01
I31060		5.97	115.5	3.30	2.114	18.31	750.6	3.28	3.32

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIASQI

CERTIFICATE VA10098181

Project: SQI10-01

P.O. No.: SQI10-01_8

This report is for 4 Other samples submitted to our lab in Vancouver, BC, Canada on 20-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
SCR-21	Screen to -100 um
BAG-01	Bulk Master for Storage
SPL-21	Split sample - riffle splitter
FND-03	Find Reject for Addn Analysis
PUL-32	Pulverize 1000g to 85% < 75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA25D	Ore Grade Au 30g FA AA Dup	AAS
Au-SCR21	Au Screen Fire Assay - 100 um	WST-SIM
Au-AA25	Ore Grade Au 30g FA AA finish	AAS

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS VA10098181

Sample Description	Method	Au-SCR21	Au-SCR21	Au-SCR21	Au-SCR21	Au-SCR21	Au-SCR21	Au-AA25	Au-AA25D
	Analyte	Au Total	Au (+) F	Au (-) F	Au (+) m	WT. + Fr	WT. - Fr	Au	Au
	Units	ppm	ppm	ppm	mg	g	g	ppm	ppm
	LOR	0.05	0.05	0.05	0.001	0.01	0.1	0.01	0.01
I031029		109.0	323	90.3	16.637	51.54	589.3	81.7	98.8
I031039		53.0	178.5	46.5	4.803	26.88	519.7	47.2	45.8
I031040		20.3	173.5	17.90	1.771	10.22	646.1	17.40	18.35
I031047		12.55	28.2	12.15	0.259	9.19	361.4	12.60	11.70

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-AUG-2010
Account: EIASQI

CERTIFICATE VA10099468

Project: SQI10-03

P.O. No.: SQI10-03_9

This report is for 1 Other sample submitted to our lab in Vancouver, BC, Canada on 21-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
FND-03	Find Reject for Addn Analysis
PUL-32	Pulverize 1000g to 85% < 75 um
SPL-21	Split sample - riffle splitter
BAG-01	Bulk Master for Storage
SCR-21	Screen to -100 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-SCR21	Au Screen Fire Assay - 100 um	WST-SIM
Au-AA25	Ore Grade Au 30g FA AA finish	AAS
Au-AA25D	Ore Grade Au 30g FA AA Dup	AAS

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature: 
Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-AUG-2010
Account: EIASQI

Project: SQI10-03

CERTIFICATE OF ANALYSIS VA10099468

Sample Description	Method	Au-SCR21	Au-SCR21	Au-SCR21	Au-SCR21	Au-SCR21	Au-SCR21	Au-AA25	Au-AA25D
	Analyte	Au Total	Au (+) F	Au (-) F	Au (+) m	WT. + Fr	WT. - Fr	Au	Au
	Units	ppm	ppm	ppm	mg	g	g	ppm	ppm
	LOR	0.05	0.05	0.05	0.001	0.01	0.1	0.01	0.01
I030962		19.40	20.2	19.40	0.085	4.21	1220.0	20.2	18.55

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 7-JUL-2010
Account: EIASQI

CERTIFICATE WH10084156

Project: SQI10-01

P.O. No.: SQI10-01_4

This report is for 13 Soil samples submitted to our lab in Whitehorse, YT, Canada on 24-JUN-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
SCR-41	Screen to -180um and save both

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 7-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10084156

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1	ME-MS41 Cr ppm 1
G091451		0.36	<0.005	0.09	2.02	4.1	<0.2	<10	260	0.27	0.14	0.60	0.24	32.4	11.7	17
G091452		0.62	<0.005	0.08	2.22	0.9	<0.2	<10	420	0.57	0.24	0.69	0.40	71.5	16.7	19
G091453		0.50	<0.005	0.10	0.98	10.8	<0.2	<10	160	0.29	0.08	0.49	0.29	30.9	10.6	22
G091454		0.52	<0.005	0.15	1.67	29.7	<0.2	<10	130	0.42	0.22	0.56	0.31	31.7	17.7	33
G091455		0.36	<0.005	0.10	1.39	7.2	<0.2	<10	100	0.28	0.16	0.38	0.16	24.4	12.9	29
G091456		0.46	<0.005	0.21	1.95	38.6	<0.2	<10	140	0.53	0.34	0.57	0.46	28.8	16.5	33
G091457		0.52	0.006	0.13	2.12	51.8	<0.2	<10	390	0.48	0.19	0.73	0.12	51.5	9.0	18
I034301		0.18	<0.005	0.07	2.02	4.0	<0.2	<10	230	0.31	0.10	0.61	0.25	32.3	11.6	19
I034302		0.22	<0.005	0.10	2.52	3.8	<0.2	<10	290	0.32	0.18	0.71	0.21	40.0	13.0	21
I034303		0.20	<0.005	0.35	1.72	61.7	<0.2	<10	110	0.54	0.74	0.73	0.60	31.6	14.3	34
I034304		0.20	<0.005	0.48	1.66	95.0	<0.2	<10	110	0.58	0.63	0.61	0.37	28.3	12.5	29
I034305		0.22	0.014	0.73	2.04	202	<0.2	<10	120	0.69	2.49	0.57	0.70	26.5	27.1	40
I034306		0.36	0.100	0.31	1.60	45.9	<0.2	<10	80	0.40	0.67	0.58	0.32	18.40	12.1	39

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 7-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10084156

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
G091451		1.90	9.4	3.34	7.38	0.14	0.04	0.04	0.038	0.39	16.6	20.0	0.78	821	0.57	0.03
G091452		2.93	16.8	4.78	9.50	0.26	0.12	0.02	0.069	0.83	38.3	14.7	1.26	1320	0.97	0.04
G091453		3.80	19.8	2.53	3.23	0.10	0.03	0.03	0.015	0.06	15.7	9.6	0.34	492	1.63	0.02
G091454		5.03	21.0	2.85	5.95	0.10	0.03	0.04	0.021	0.11	14.6	14.3	0.62	902	1.30	0.03
G091455		2.82	13.6	2.34	6.13	0.07	0.02	0.04	0.019	0.07	11.9	10.4	0.45	652	1.26	0.02
G091456		6.76	24.2	2.72	6.93	0.09	0.03	0.05	0.024	0.10	12.3	15.6	0.65	911	1.44	0.04
G091457		1.94	14.7	2.75	7.24	0.14	0.07	0.07	0.027	0.16	32.3	17.1	0.48	793	2.21	0.04
I034301		1.47	10.6	3.14	6.95	0.13	0.04	0.02	0.022	0.25	15.4	23.8	0.72	602	0.59	0.04
I034302		2.43	12.9	3.66	8.78	0.18	0.06	0.08	0.027	0.56	22.7	21.9	0.99	806	0.55	0.04
I034303		6.54	34.5	2.58	5.88	0.10	0.03	0.06	0.021	0.10	17.0	17.4	0.63	485	1.88	0.04
I034304		7.46	23.8	2.61	6.31	0.09	0.03	0.09	0.031	0.08	15.4	14.2	0.54	458	2.05	0.03
I034305		10.15	43.1	2.96	6.91	0.10	0.03	0.07	0.028	0.11	12.8	17.7	0.68	796	2.50	0.04
I034306		6.07	38.9	2.47	5.85	0.09	0.02	0.04	0.019	0.07	8.9	16.3	0.60	379	3.01	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 7-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10084156

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
G091451		2.00	10.4	590	5.1	47.6	<0.001	0.04	0.23	6.8	0.6	3.6	42.6	<0.01	0.02	3.7
G091452		1.06	17.1	1010	11.1	51.3	<0.001	0.02	0.40	14.3	1.2	2.9	42.4	0.01	0.01	11.4
G091453		0.72	22.5	870	5.3	9.0	0.001	0.03	0.64	3.3	1.3	4.6	35.9	<0.01	0.03	2.4
G091454		1.18	25.4	890	17.6	16.5	<0.001	0.04	1.06	4.3	0.7	3.7	46.8	<0.01	0.03	2.2
G091455		0.97	19.6	610	12.8	15.2	<0.001	0.04	0.73	3.2	0.5	1.2	27.5	<0.01	0.02	1.3
G091456		1.23	22.2	980	24.0	14.5	<0.001	0.05	1.21	4.5	0.7	3.4	54.7	0.01	0.04	1.7
G091457		2.17	10.6	800	9.0	25.1	0.001	0.05	2.00	8.0	1.0	2.2	55.8	0.01	0.02	6.2
I034301		1.98	12.5	770	4.7	33.9	<0.001	0.04	0.36	6.5	0.6	1.7	40.7	<0.01	0.02	4.1
I034302		2.08	14.1	950	6.0	51.8	<0.001	0.04	0.58	9.3	0.8	1.0	43.9	<0.01	0.02	4.8
I034303		1.10	23.5	780	25.1	15.1	<0.001	0.07	1.68	4.3	0.8	1.4	65.7	<0.01	0.05	2.5
I034304		0.96	19.3	870	44.3	15.6	<0.001	0.08	1.88	3.5	0.8	1.9	48.1	<0.01	0.05	1.3
I034305		1.18	27.7	890	48.4	16.6	<0.001	0.09	2.78	4.5	0.9	1.7	52.6	0.01	0.11	1.5
I034306		1.17	22.2	690	16.1	12.1	<0.001	0.05	1.53	3.7	0.6	3.8	40.2	<0.01	0.04	2.0

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 7-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10084156

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
G091451		0.164	0.28	2.67	74	2.39	10.90	86	1.2
G091452		0.141	0.41	1.79	102	0.22	28.3	119	3.4
G091453		0.047	0.07	1.32	44	0.13	10.00	57	0.5
G091454		0.098	0.18	1.06	65	0.29	8.47	70	0.8
G091455		0.079	0.12	0.89	62	0.15	4.76	55	0.5
G091456		0.109	0.22	1.26	73	0.26	8.76	72	1.1
G091457		0.092	0.20	9.49	60	0.39	25.2	57	2.2
I034301		0.157	0.21	3.64	72	0.15	10.75	83	1.2
I034302		0.186	0.36	3.12	84	0.36	15.95	84	1.8
I034303		0.086	0.26	3.97	57	0.46	9.23	71	0.8
I034304		0.075	0.21	2.21	62	0.16	8.39	68	0.7
I034305		0.098	0.37	1.95	69	0.60	9.21	76	1.0
I034306		0.100	0.22	2.83	63	0.82	5.56	57	0.7

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 7-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10084156

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

CERTIFICATE WH10089644

Project: SQI10-01

P.O. No.: SQI10-01-07

This report is for 50 Soil samples submitted to our lab in Whitehorse, YT, Canada on 5-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
SCR-41	Screen to -180um and save both

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature: 

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089644

Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
Sample Description LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I030801	0.26	0.016	1.23	2.09	14.9	<0.2	<10	70	1.29	4.55	0.23	0.45	35.7	10.2	33
I030802	0.32	0.012	0.80	2.14	17.1	<0.2	<10	80	2.74	2.43	0.74	0.41	47.6	14.0	46
I030803	0.40	0.065	0.31	2.70	8.0	<0.2	<10	80	2.48	2.51	1.20	0.90	53.1	18.7	23
I030804	0.40	0.005	1.13	2.34	15.5	<0.2	<10	10	2.45	1.70	1.36	0.28	50.6	6.5	4
I030805	0.40	0.007	0.42	2.23	7.9	<0.2	<10	70	2.35	1.64	0.86	0.44	45.2	9.0	16
I030806	0.36	<0.005	0.09	2.12	10.2	<0.2	<10	80	0.88	0.38	0.21	0.12	33.2	9.5	31
I030807	0.34	0.006	0.15	2.62	8.5	<0.2	<10	150	1.21	0.53	0.42	0.25	40.4	9.3	26
I030808	0.46	<0.005	0.47	2.66	4.9	<0.2	<10	210	3.19	2.16	1.11	0.82	79.6	10.1	18
I030809	0.40	<0.005	0.27	2.57	7.1	<0.2	<10	100	2.45	1.39	0.69	0.34	60.8	8.8	22
I030810	0.32	0.009	0.22	2.56	7.7	<0.2	<10	140	1.99	1.56	0.62	0.35	53.1	10.2	25
I030811	0.40	0.005	0.21	1.56	9.0	<0.2	<10	80	0.82	1.61	0.37	0.35	35.2	10.7	31
I030812	0.38	<0.005	0.33	1.49	9.8	<0.2	<10	110	1.56	2.29	0.35	0.31	51.7	8.8	17
I030813	0.38	<0.005	0.10	1.45	6.4	<0.2	<10	80	1.12	0.78	0.41	0.34	43.7	8.9	26
I030814	0.32	<0.005	0.11	1.82	9.9	<0.2	<10	60	0.69	0.45	0.12	0.10	30.9	9.5	33
I030815	0.32	0.044	0.51	1.37	9.9	<0.2	<10	70	0.72	5.27	0.31	0.34	22.9	8.3	34
I030816	0.40	0.018	0.35	2.09	12.7	<0.2	<10	90	1.71	4.52	0.36	0.26	56.4	11.5	29
I030817	0.28	0.011	1.45	2.48	12.0	<0.2	<10	100	2.34	7.39	0.56	0.41	55.0	16.8	26
I030818	0.34	0.028	0.39	1.75	8.8	<0.2	<10	80	1.47	5.21	0.49	0.48	42.4	10.3	31
I030819	0.30	0.036	0.61	1.65	7.8	0.6	<10	90	1.20	3.94	0.54	0.43	39.3	9.9	39
I030820	0.32	<0.005	0.16	1.74	7.6	<0.2	<10	70	2.02	0.29	0.53	0.63	32.7	10.3	40
I030821	0.34	<0.005	0.77	1.62	8.3	<0.2	<10	60	1.08	0.26	0.30	0.22	25.3	7.8	36
I030822	0.30	<0.005	0.13	1.66	10.1	<0.2	<10	60	1.34	0.60	0.52	0.28	38.5	9.8	47
I030823	0.24	<0.005	0.16	1.74	8.9	<0.2	<10	70	1.23	0.63	0.36	0.23	26.0	9.2	46
I030824	0.26	<0.005	0.17	1.97	11.3	<0.2	<10	80	1.57	0.68	0.49	0.47	35.7	10.2	54
I030825	0.24	0.006	0.24	2.25	8.7	<0.2	<10	100	2.24	0.69	0.68	0.43	41.6	10.1	41
I030826	0.22	0.010	0.25	2.04	9.7	<0.2	<10	100	1.70	3.22	0.54	0.46	40.9	10.6	46
I030827	0.24	0.011	0.17	2.54	10.4	<0.2	<10	130	2.32	7.26	0.82	0.41	48.7	14.6	66
I030828	0.24	0.032	0.44	2.07	7.1	0.3	<10	90	2.01	5.96	0.24	0.15	31.2	8.7	36
I030829	0.24	0.336	1.18	2.66	11.2	<0.2	<10	100	1.92	41.2	0.39	0.32	33.2	13.4	52
I030830	0.26	0.108	2.51	1.93	10.3	<0.2	<10	80	1.71	43.7	0.28	0.23	26.0	8.5	32
I030831	0.26	0.139	0.94	1.86	16.6	0.4	<10	80	1.59	23.6	0.42	0.33	40.2	10.9	39
I030832	0.32	0.030	0.38	2.00	10.7	<0.2	<10	80	1.67	10.40	0.34	0.31	40.5	9.8	40
I030833	0.36	0.087	0.58	2.25	11.8	<0.2	<10	100	2.15	14.85	0.49	0.39	45.7	12.0	38
I030834	0.28	0.021	0.59	2.25	20.4	<0.2	<10	100	2.04	14.05	0.44	0.69	42.5	11.2	32
I030835	0.28	0.049	0.35	1.67	27.6	<0.2	<10	100	1.40	6.78	0.43	0.65	35.6	8.3	32
I030836	0.30	0.011	0.79	1.68	74.7	<0.2	<10	140	1.50	5.13	0.44	1.47	45.4	9.2	30
I030837	0.28	0.005	1.51	0.82	38.4	<0.2	<10	70	0.56	2.38	0.12	0.54	17.55	3.0	17
I030838	0.30	0.005	1.64	2.19	84.5	<0.2	<10	150	2.41	5.89	0.50	1.15	44.5	10.7	22
I030839	0.30	<0.005	1.24	2.15	81.6	<0.2	<10	150	2.05	6.09	0.45	0.57	36.2	9.5	24
I030840	0.32	0.009	0.73	1.78	54.0	<0.2	<10	130	1.41	4.74	0.46	1.00	43.1	10.1	36

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089644

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I030801		8.08	80.8	3.26	7.37	0.07	0.03	0.14	0.060	0.05	16.0	19.4	0.55	1060	2.88	0.02
I030802		11.40	157.0	3.55	7.97	0.11	0.03	0.04	0.043	0.11	22.3	25.3	0.95	1440	1.09	0.03
I030803		22.6	40.6	2.58	7.11	0.09	0.04	0.06	0.021	0.12	22.4	20.4	0.61	1200	3.30	0.03
I030804		37.0	15.3	3.15	16.50	0.10	0.03	0.04	0.584	0.12	27.3	9.0	0.22	8410	6.77	0.03
I030805		20.8	41.0	2.54	8.70	0.09	0.03	0.07	0.140	0.12	24.4	17.3	0.47	2630	5.34	0.03
I030806		5.48	21.7	3.11	7.39	0.09	0.03	0.05	0.041	0.08	15.7	19.0	0.54	842	2.11	0.02
I030807		9.12	40.3	2.59	7.08	0.08	0.03	0.02	0.036	0.06	17.4	22.3	0.64	783	2.86	0.02
I030808		8.88	24.0	2.71	10.30	0.13	0.06	0.04	0.039	0.12	38.5	29.1	0.74	5090	6.64	0.03
I030809		12.90	24.9	2.91	9.47	0.10	0.03	0.04	0.058	0.08	31.7	21.4	0.63	2480	1.79	0.03
I030810		16.30	26.0	2.78	7.85	0.10	0.04	0.04	0.052	0.09	26.8	20.2	0.60	2060	1.82	0.02
I030811		5.37	25.7	2.78	5.45	<0.05	0.05	0.02	0.023	0.10	17.0	16.0	0.54	563	1.89	0.02
I030812		27.6	16.5	3.21	6.01	<0.05	0.03	0.03	0.028	0.11	27.6	14.5	0.35	2000	1.20	0.01
I030813		9.44	14.6	2.05	5.63	0.05	0.07	0.02	0.024	0.11	21.7	16.5	0.49	338	0.59	0.01
I030814		2.32	20.5	2.33	6.47	<0.05	0.04	0.05	0.037	0.07	14.6	15.4	0.47	387	1.08	0.01
I030815		5.91	36.4	3.08	6.80	<0.05	0.03	0.05	0.033	0.10	11.5	10.9	0.39	552	2.33	0.02
I030816		7.36	103.5	3.49	7.05	0.05	0.04	0.04	0.042	0.13	28.8	17.8	0.56	1040	1.94	0.02
I030817		12.50	436	3.83	7.24	0.05	0.04	0.04	0.072	0.13	25.2	18.3	0.56	1380	1.87	0.02
I030818		5.74	102.5	2.98	6.62	<0.05	0.03	0.05	0.046	0.14	22.2	15.9	0.54	1040	2.08	0.02
I030819		4.76	49.2	2.91	5.40	<0.05	0.04	0.08	0.031	0.10	19.1	13.8	0.56	743	0.90	0.02
I030820		6.64	34.2	2.32	5.78	<0.05	0.04	0.03	0.024	0.05	16.2	15.3	0.51	451	0.61	0.02
I030821		3.21	31.6	2.41	5.64	<0.05	0.03	0.05	0.021	0.05	13.0	14.4	0.44	303	1.33	0.02
I030822		5.16	46.1	2.76	6.18	<0.05	0.03	0.03	0.028	0.06	19.3	17.2	0.54	584	1.00	0.02
I030823		4.35	27.2	2.63	6.50	<0.05	0.03	0.04	0.027	0.04	14.1	17.7	0.53	361	0.68	0.02
I030824		4.38	44.0	3.00	6.67	<0.05	0.04	0.04	0.026	0.07	18.0	17.8	0.56	645	0.73	0.02
I030825		5.79	46.0	2.89	7.19	<0.05	0.03	0.04	0.027	0.10	21.2	19.1	0.62	505	0.63	0.02
I030826		5.72	53.8	2.98	6.98	0.05	0.03	0.03	0.037	0.09	20.2	17.8	0.65	523	1.73	0.02
I030827		7.40	50.9	3.69	7.83	0.05	0.04	0.02	0.043	0.16	23.9	20.9	1.01	1260	0.62	0.02
I030828		4.28	77.2	2.47	8.32	<0.05	0.02	0.05	0.044	0.06	17.5	20.3	0.66	355	0.81	0.01
I030829		11.10	248	4.03	9.28	<0.05	0.03	0.05	0.092	0.26	16.2	26.3	1.16	1210	1.15	0.02
I030830		6.56	375	2.83	6.66	<0.05	0.02	0.06	0.092	0.10	15.7	13.9	0.58	633	1.57	0.02
I030831		7.15	152.5	3.67	6.82	<0.05	0.03	0.04	0.074	0.13	20.0	18.1	0.64	1300	3.51	0.02
I030832		7.31	76.4	3.39	6.97	<0.05	0.02	0.05	0.048	0.10	20.2	18.9	0.67	956	2.20	0.02
I030833		7.79	107.5	3.38	7.54	<0.05	0.03	0.04	0.060	0.11	23.6	19.4	0.73	1340	2.08	0.02
I030834		7.03	94.0	3.13	7.45	<0.05	0.02	0.05	0.063	0.08	22.8	18.8	0.64	1140	2.24	0.02
I030835		8.26	42.6	3.04	5.65	<0.05	0.02	0.04	0.043	0.11	17.4	15.5	0.48	708	2.15	0.02
I030836		9.73	47.3	3.26	6.02	<0.05	0.03	0.03	0.064	0.17	21.2	17.3	0.54	881	3.51	0.03
I030837		3.41	24.4	1.64	3.12	<0.05	<0.02	0.07	0.030	0.04	9.2	3.5	0.13	129	2.10	0.02
I030838		10.85	60.7	2.67	6.81	<0.05	0.03	0.07	0.077	0.09	24.9	17.0	0.53	1140	3.88	0.03
I030839		9.26	51.9	2.90	6.87	<0.05	0.03	0.05	0.074	0.08	20.0	17.3	0.54	876	5.20	0.03
I030840		7.32	40.9	3.45	5.93	<0.05	0.04	0.03	0.056	0.13	21.3	16.6	0.56	842	2.79	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089644

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I030801		1.72	21.0	880	150.0	19.9	0.001	0.08	5.58	1.9	0.8	0.8	96.3	0.01	0.13	0.9
I030802		2.13	27.0	1520	47.0	27.9	<0.001	0.02	1.35	4.5	0.5	0.8	164.5	0.01	0.14	6.4
I030803		1.36	14.2	1420	103.0	19.8	0.001	0.01	0.78	3.4	0.5	0.8	566	0.01	0.14	32.3
I030804		0.16	6.5	700	68.6	29.4	0.001	0.01	2.04	3.5	0.4	0.4	180.0	0.01	0.04	29.4
I030805		1.27	13.6	1220	44.1	24.5	0.001	0.03	1.20	3.3	0.6	0.7	239	0.01	0.13	8.6
I030806		1.93	20.4	640	18.5	22.8	<0.001	0.03	0.73	3.3	0.6	0.7	38.7	0.01	0.04	4.1
I030807		2.06	21.3	950	40.3	14.9	<0.001	0.02	0.57	3.7	0.5	0.8	151.5	0.01	0.03	11.4
I030808		1.69	11.5	1750	106.5	21.0	0.001	0.01	0.52	6.6	0.6	1.1	398	0.01	0.09	50.3
I030809		1.22	12.3	1220	92.2	23.9	0.001	0.03	0.66	2.7	0.6	1.0	260	0.01	0.04	4.0
I030810		1.80	18.4	1000	66.2	21.1	0.001	0.02	0.64	4.3	0.5	0.8	151.0	0.01	0.06	15.1
I030811		2.06	19.6	1040	38.4	15.9	<0.001	0.02	0.52	3.6	0.2	0.8	33.5	<0.01	0.05	10.0
I030812		0.90	11.7	860	29.7	28.9	<0.001	0.01	1.45	2.7	<0.2	9.9	114.5	0.01	0.07	15.3
I030813		1.65	15.1	940	26.0	17.2	<0.001	0.01	0.43	4.3	0.3	0.7	45.5	0.01	0.09	13.3
I030814		1.26	24.2	410	20.8	12.4	<0.001	0.04	0.59	2.8	0.3	0.5	14.5	0.01	0.03	1.4
I030815		2.03	15.8	870	51.6	19.4	<0.001	0.08	1.44	2.3	<0.2	1.0	55.6	<0.01	0.07	2.9
I030816		2.07	15.4	1120	44.2	20.4	0.001	0.03	1.18	3.5	0.4	1.2	42.2	0.01	0.06	17.3
I030817		1.64	16.5	1260	69.4	18.6	<0.001	0.04	1.40	4.2	0.4	1.4	121.5	0.01	0.08	18.5
I030818		1.49	14.9	1140	61.8	22.9	<0.001	0.07	1.16	2.2	0.3	0.8	68.6	0.01	0.13	3.8
I030819		1.51	19.8	1480	41.3	17.4	<0.001	0.02	1.03	3.5	0.2	0.6	54.3	0.01	0.13	12.1
I030820		2.08	21.2	1770	59.6	9.9	<0.001	0.02	0.63	3.5	0.3	0.5	79.7	0.01	0.02	4.0
I030821		1.52	24.4	1180	24.5	10.1	<0.001	0.06	0.63	1.7	0.2	0.5	32.9	0.01	0.03	0.6
I030822		1.74	19.6	1920	28.2	12.0	<0.001	0.03	1.01	2.7	0.2	0.6	37.3	0.01	0.02	2.2
I030823		1.70	19.9	1420	27.3	10.9	<0.001	0.06	0.75	1.7	0.2	0.5	29.6	0.01	0.03	0.5
I030824		1.89	23.3	1900	47.7	14.4	<0.001	0.05	0.88	2.3	0.3	0.6	33.8	0.01	0.04	1.5
I030825		2.22	20.4	2150	28.7	20.3	<0.001	0.04	0.69	3.7	0.2	0.7	132.5	0.01	0.03	3.9
I030826		1.65	22.6	1890	66.5	18.7	<0.001	0.03	0.74	3.4	0.3	0.6	50.3	0.01	0.06	3.6
I030827		1.48	28.3	2340	36.8	33.4	<0.001	0.03	1.22	4.7	0.3	0.9	71.7	0.01	1.28	8.6
I030828		1.68	21.0	1000	44.6	14.7	<0.001	0.06	0.80	2.6	0.2	0.8	32.8	<0.01	0.08	1.0
I030829		2.72	30.4	1450	78.6	48.6	<0.001	0.10	1.06	3.9	0.2	1.3	38.6	<0.01	0.12	3.8
I030830		1.18	18.6	1350	65.1	24.9	<0.001	0.16	1.44	2.0	0.4	1.1	36.3	<0.01	0.12	0.6
I030831		1.60	18.6	1430	60.5	26.5	<0.001	0.06	3.52	2.7	0.2	0.9	41.1	<0.01	0.24	8.2
I030832		1.67	19.9	1320	60.9	19.2	<0.001	0.06	2.36	2.6	0.2	0.8	44.6	0.01	0.15	5.5
I030833		1.64	19.9	1410	73.9	24.6	<0.001	0.05	2.23	3.3	0.3	0.9	62.6	<0.01	0.16	5.7
I030834		1.42	18.3	1230	355	17.2	<0.001	0.06	2.43	2.8	0.3	0.8	82.5	0.01	0.19	3.4
I030835		1.60	14.8	1190	128.5	16.3	<0.001	0.06	1.43	2.4	0.3	0.8	96.9	<0.01	0.09	8.2
I030836		2.23	13.7	1250	407	22.7	<0.001	0.08	2.78	2.7	0.2	1.0	155.0	0.01	0.11	11.1
I030837		0.59	8.1	850	150.5	7.2	<0.001	0.12	1.12	0.8	0.2	0.7	44.2	<0.01	0.05	0.3
I030838		1.53	15.1	950	364	17.1	<0.001	0.10	2.12	2.8	0.5	1.0	127.0	<0.01	0.16	5.5
I030839		1.75	14.0	1000	338	13.8	<0.001	0.09	2.02	3.0	0.4	1.1	123.5	0.01	0.15	7.9
I030840		2.09	16.0	1280	242	20.5	<0.001	0.05	1.78	3.5	0.3	1.1	84.9	0.01	0.10	17.3

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089644

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I030801		0.073	0.19	3.37	73	0.41	7.79	89	0.7
I030802		0.094	0.23	4.25	93	0.80	11.70	78	0.6
I030803		0.035	0.15	9.65	52	0.49	11.30	71	0.9
I030804		<0.005	0.34	30.0	53	1.88	13.25	55	0.9
I030805		0.046	0.22	25.9	46	0.87	13.05	83	<0.5
I030806		0.104	0.18	3.36	64	0.33	6.97	61	0.8
I030807		0.052	0.18	5.78	52	0.48	10.25	62	0.6
I030808		0.068	0.28	11.45	47	1.25	22.3	136	1.1
I030809		0.044	0.25	9.25	55	0.55	16.80	132	<0.5
I030810		0.077	0.24	7.64	52	1.28	12.05	95	1.2
I030811		0.116	0.15	4.33	66	0.98	8.57	77	1.3
I030812		0.040	0.37	5.50	39	10.45	9.37	72	0.5
I030813		0.116	0.13	6.33	55	0.53	11.40	81	2.8
I030814		0.090	0.12	1.21	64	0.24	5.39	58	1.1
I030815		0.094	0.14	2.66	82	0.79	4.25	79	0.8
I030816		0.094	0.19	8.72	73	0.60	10.50	86	1.2
I030817		0.050	0.21	10.15	61	0.95	11.05	100	1.0
I030818		0.057	0.17	5.12	67	0.99	8.61	100	<0.5
I030819		0.089	0.15	4.24	75	0.49	9.57	81	0.9
I030820		0.108	0.11	2.39	63	0.51	8.29	83	1.8
I030821		0.079	0.09	1.22	63	0.37	6.16	63	1.0
I030822		0.097	0.13	2.78	77	0.58	9.24	84	0.9
I030823		0.075	0.12	1.91	70	0.50	6.54	79	0.9
I030824		0.098	0.13	2.30	85	0.77	8.67	112	1.0
I030825		0.094	0.13	4.41	84	0.91	9.89	93	0.9
I030826		0.088	0.20	3.70	81	0.61	10.10	145	0.6
I030827		0.081	0.32	2.86	102	0.72	10.65	117	0.8
I030828		0.061	0.26	3.50	71	0.60	7.16	98	0.5
I030829		0.128	0.51	3.01	101	0.72	6.85	172	0.7
I030830		0.047	0.26	6.47	63	0.52	7.39	89	<0.5
I030831		0.071	0.24	6.22	77	0.79	8.30	138	<0.5
I030832		0.070	0.21	5.96	77	0.60	7.89	118	0.5
I030833		0.071	0.25	8.43	77	0.68	10.70	130	<0.5
I030834		0.061	0.26	8.37	68	0.57	10.25	192	<0.5
I030835		0.069	0.16	5.46	71	0.64	7.71	187	0.5
I030836		0.088	0.22	5.90	74	0.80	9.78	290	0.5
I030837		0.030	0.13	4.58	40	0.46	3.90	72	<0.5
I030838		0.039	0.22	12.30	46	0.48	12.10	288	<0.5
I030839		0.049	0.23	10.45	55	0.49	9.76	247	0.6
I030840		0.098	0.19	6.45	81	0.85	9.53	202	1.3

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089644

Sample Description	Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I030841		0.26	0.006	0.33	2.09	31.3	<0.2	<10	90	2.46	5.23	0.90	0.81	64.4	11.0	20
I030842		0.32	0.006	0.19	2.24	25.3	<0.2	<10	110	2.57	4.79	0.62	0.37	61.3	10.0	24
I030843		0.30	0.009	0.14	1.88	25.0	<0.2	<10	280	2.37	2.72	0.71	0.31	50.6	10.6	21
I030844		0.42	<0.005	0.13	1.90	14.9	<0.2	<10	130	1.65	2.07	0.47	0.14	37.9	7.4	14
I030845		0.32	0.005	0.21	2.16	18.5	<0.2	<10	160	2.43	2.38	0.59	0.25	46.8	9.2	18
I030846		0.32	0.009	0.30	2.02	16.4	<0.2	<10	380	2.15	2.35	0.57	0.33	45.4	10.9	18
I030847		0.34	0.008	0.30	2.44	20.1	<0.2	<10	280	3.30	2.73	0.77	0.18	50.6	11.5	15
I030848		0.32	0.006	0.16	1.96	17.9	<0.2	<10	210	2.80	3.57	0.79	0.41	53.4	9.3	15
I030849		0.34	0.009	0.53	2.06	31.1	<0.2	<10	140	1.53	3.12	0.42	0.34	72.3	7.9	24
I030850		0.26	<0.005	0.12	2.14	21.5	<0.2	<10	140	0.95	1.69	0.30	0.21	35.5	11.9	23

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089644

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I030841		9.44	33.5	2.79	6.96	0.05	0.03	0.03	0.197	0.09	42.0	16.3	0.76	1310	1.42	0.03
I030842		8.64	27.1	2.99	7.76	<0.05	0.02	0.07	0.090	0.10	32.3	22.1	0.81	1250	1.52	0.01
I030843		16.35	41.9	3.15	5.98	<0.05	0.04	0.02	0.060	0.13	26.1	19.0	0.59	742	1.46	0.03
I030844		10.40	23.4	2.00	5.93	<0.05	0.02	0.04	0.055	0.08	22.0	13.3	0.49	777	1.39	0.02
I030845		13.20	41.9	2.61	6.61	<0.05	0.02	0.03	0.058	0.12	24.7	19.2	0.58	711	1.69	0.03
I030846		14.90	55.4	3.11	5.67	<0.05	0.02	0.03	0.069	0.18	22.3	20.9	0.52	832	3.21	0.03
I030847		14.05	71.9	2.67	6.50	0.08	0.03	0.05	0.065	0.10	27.3	23.4	0.55	908	3.92	0.03
I030848		9.94	47.0	2.34	5.87	0.08	0.02	0.05	0.082	0.11	27.8	19.3	0.52	774	1.95	0.02
I030849		9.18	56.6	3.57	6.93	0.11	0.03	0.03	0.112	0.22	37.1	16.1	0.51	632	5.33	0.03
I030850		6.61	13.3	3.33	7.49	0.07	0.02	0.04	0.058	0.06	12.5	19.4	0.63	574	2.96	0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089644

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I030841		0.87	7.3	1860	80.8	11.9	<0.001	0.07	0.66	2.1	0.3	1.0	123.0	<0.01	0.37	15.4
I030842		1.02	11.0	1430	61.4	15.6	<0.001	0.06	0.62	2.0	0.2	1.3	110.0	0.01	0.20	5.2
I030843		1.14	10.5	1450	61.8	16.2	<0.001	0.03	0.65	3.0	0.3	1.5	289	0.01	0.16	21.3
I030844		0.92	7.6	1070	44.7	12.4	<0.001	0.06	0.50	1.4	<0.2	1.0	114.0	<0.01	0.12	2.7
I030845		1.50	11.5	1030	59.1	15.8	0.001	0.06	0.60	2.7	0.3	1.3	152.5	0.01	0.13	12.9
I030846		1.90	9.4	980	83.2	21.9	<0.001	0.12	1.13	2.5	0.5	1.7	330	<0.01	0.13	15.8
I030847		1.43	10.3	1050	97.9	17.7	<0.001	0.06	0.99	2.5	0.9	1.4	279	0.01	0.16	11.6
I030848		1.76	9.7	1190	56.4	18.2	<0.001	0.04	0.68	2.6	0.7	2.0	229	0.01	0.16	12.9
I030849		2.28	11.8	1150	62.2	31.2	<0.001	0.20	1.37	3.4	0.8	1.7	116.0	<0.01	0.14	16.2
I030850		0.95	12.6	750	65.9	11.0	<0.001	0.03	0.66	2.0	0.4	0.7	133.5	<0.01	0.18	2.8

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089644

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I030841		0.018	0.19	14.10	43	0.35	11.05	214	0.5
I030842		0.021	0.25	11.10	51	0.44	9.96	115	<0.5
I030843		0.046	0.25	13.25	59	0.35	12.05	91	0.8
I030844		0.021	0.21	8.81	33	0.32	7.07	66	<0.5
I030845		0.040	0.22	15.40	45	0.34	9.90	92	<0.5
I030846		0.040	0.29	11.60	53	0.26	8.92	89	<0.5
I030847		0.024	0.27	26.1	38	0.28	11.70	95	<0.5
I030848		0.031	0.25	16.80	40	0.29	13.70	89	<0.5
I030849		0.083	0.32	13.15	63	0.57	12.35	115	0.6
I030850		0.038	0.17	3.83	58	0.48	6.05	102	0.8

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089644

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

Appendix D-2: Rock Geochemical Certificates

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

CERTIFICATE WH10089643

Project: SQI10-01

P.O. No.: SQI10-01-07

This report is for 24 Rock samples submitted to our lab in Whitehorse, YT, Canada on 5-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
EXTRA-01	Extra Sample received in Shipment
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089643

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1	ME-MS41 Cr ppm 1
I031011		0.86	0.024	0.08	0.32	6.4	<0.2	30	40	0.72	0.53	0.30	0.03	18.80	1.8	7
I031012		0.84	0.012	0.13	0.24	17.7	<0.2	40	20	0.53	0.84	0.30	0.02	25.0	1.8	12
I031013		0.86	0.017	0.22	0.12	20.3	<0.2	40	10	0.23	0.85	0.04	<0.01	6.90	14.0	30
I031014		0.78	0.006	0.11	0.13	10.9	<0.2	140	<10	0.67	0.28	0.57	0.07	8.95	2.7	8
I031015		0.68	0.006	0.49	0.10	2.5	<0.2	40	20	0.27	1.14	0.08	0.02	10.40	1.0	11
I031016		0.56	<0.005	0.05	0.08	6.6	<0.2	130	10	0.73	0.45	0.42	0.02	13.35	2.8	25
I031017		0.66	<0.005	0.25	0.22	2.0	<0.2	30	30	0.38	7.34	0.07	0.04	41.9	1.4	8
I031018		0.62	<0.005	0.03	0.12	20.4	<0.2	90	10	0.46	1.27	0.31	0.04	10.10	2.7	21
I031019		0.38	0.025	0.19	0.13	2.6	<0.2	50	30	0.20	0.69	0.10	0.01	4.54	0.8	12
I031020		0.56	0.008	0.11	0.46	5.8	<0.2	10	50	0.48	0.49	0.21	0.07	46.5	1.2	6
I031021		0.52	0.012	0.08	0.27	4.7	<0.2	20	30	0.51	0.32	0.12	0.04	25.3	2.8	24
I031022		0.70	0.006	0.13	0.45	4.5	<0.2	10	40	0.42	0.63	0.34	0.39	19.05	2.0	10
I031023		0.50	0.005	0.44	0.10	4.5	<0.2	50	20	0.20	0.25	0.10	0.12	3.59	0.4	7
I031024		0.62	0.006	0.07	0.25	6.8	<0.2	30	20	0.43	0.51	0.21	0.34	47.5	1.5	17
I034454		1.22	0.337	61.9	0.19	184.0	0.5	<10	50	0.17	4.32	0.01	8.61	3.26	5.4	8
I034455		0.92	0.084	0.74	0.10	3.1	<0.2	100	10	0.20	2.66	0.20	0.06	7.12	8.0	5
I034456		0.68	<0.005	0.34	0.83	68.5	<0.2	<10	100	0.26	1.15	0.23	0.06	26.4	5.9	20
I034457		0.92	0.013	0.84	0.25	52.9	<0.2	20	110	0.91	6.38	0.02	0.13	25.8	8.2	5
I034458		0.90	<0.005	0.31	0.26	3.5	<0.2	10	50	0.36	0.59	0.08	0.04	49.4	0.7	4
I034459		1.08	0.023	0.41	0.32	14.0	<0.2	<10	50	0.58	2.47	0.08	0.18	21.6	3.3	15
I034460		1.14	0.005	0.37	0.28	4.4	<0.2	10	30	0.35	1.62	0.08	0.10	16.90	3.1	5
I034461		0.84	0.036	0.48	0.30	37.8	<0.2	<10	30	0.61	3.03	0.08	0.51	46.6	3.1	5
I034051		0.28	<0.005	0.62	1.51	38.3	<0.2	<10	110	1.34	1.71	0.67	4.55	35.4	36.7	20
I034052		0.60	<0.005	0.23	0.97	5.5	<0.2	<10	120	0.66	1.05	0.32	0.20	21.0	8.3	12

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089643

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I031011		5.49	1.2	2.69	3.05	0.05	0.11	0.02	0.033	0.17	10.8	1.5	0.04	993	3.43	<0.01
I031012		2.06	1.5	1.21	1.18	0.05	0.12	0.01	0.017	0.14	13.9	1.1	0.03	353	6.35	<0.01
I031013		0.84	1.5	3.46	0.83	<0.05	0.07	0.04	0.008	0.09	3.7	0.7	0.01	41	1.13	<0.01
I031014		0.49	3.4	0.64	0.70	<0.05	0.24	0.01	0.017	0.01	4.4	0.7	0.03	194	0.72	<0.01
I031015		0.73	2.5	2.24	0.59	<0.05	0.14	0.02	0.010	0.06	4.8	0.4	0.01	435	0.88	0.02
I031016		0.14	1.3	3.67	0.51	0.07	0.18	0.02	0.099	<0.01	5.7	0.4	0.02	48	1.60	0.02
I031017		2.68	3.8	0.54	0.89	<0.05	0.05	<0.01	0.010	0.15	21.1	0.8	0.02	92	0.68	0.01
I031018		1.15	2.5	0.96	0.99	<0.05	0.08	<0.01	0.014	0.01	4.3	1.1	0.04	36	3.19	0.02
I031019		1.48	2.2	3.65	1.93	0.06	0.06	0.02	0.015	0.06	2.3	0.4	0.04	60	0.91	0.02
I031020		4.39	1.7	1.43	2.06	0.06	0.20	0.01	0.031	0.18	22.6	2.2	0.04	578	1.19	0.01
I031021		7.06	1.5	2.06	1.43	0.05	0.08	<0.01	0.017	0.14	12.0	1.2	0.02	176	4.28	0.01
I031022		3.01	4.2	0.63	2.44	<0.05	0.16	<0.01	0.018	0.13	7.8	12.0	0.25	441	2.06	0.05
I031023		1.19	3.9	0.32	0.59	<0.05	0.08	<0.01	0.013	0.03	1.5	0.7	0.01	180	0.52	0.02
I031024		1.90	11.3	0.33	1.01	0.06	0.10	<0.01	0.018	0.08	22.3	3.3	0.04	158	0.45	0.04
I034454		1.46	227	3.74	1.19	0.05	0.08	0.81	1.720	0.15	1.6	0.8	0.01	38	27.4	0.01
I034455		0.85	3.2	2.87	0.80	0.05	0.16	<0.01	0.026	0.01	3.3	0.5	0.02	62	0.62	0.02
I034456		3.11	2.6	1.98	4.89	0.08	0.33	<0.01	0.026	0.22	12.3	21.6	0.56	263	1.65	0.05
I034457		1.80	27.8	4.73	1.96	0.08	0.16	<0.01	0.043	0.16	14.3	1.0	0.02	86	6.40	0.02
I034458		1.42	3.8	0.84	0.87	0.05	0.19	<0.01	0.015	0.23	24.1	0.7	0.01	32	0.75	0.01
I034459		1.69	12.4	2.69	1.41	0.05	0.18	0.01	0.042	0.24	10.3	1.2	0.02	387	2.16	0.02
I034460		1.45	31.7	1.41	1.17	<0.05	0.17	0.01	0.026	0.22	7.9	1.0	0.02	65	0.91	0.01
I034461		2.85	8.3	3.27	1.42	0.07	0.09	0.08	0.024	0.22	22.5	1.3	0.02	41	1.94	0.01
I034051		2.10	5.8	3.52	7.28	0.09	0.56	0.01	0.181	0.07	18.1	19.8	0.91	1360	3.06	0.03
I034052		6.79	6.1	2.30	4.46	0.09	0.13	<0.01	0.011	0.37	9.7	30.1	0.69	196	1.97	0.05

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089643

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I031011		0.33	1.2	520	4.9	26.9	<0.001	<0.01	1.90	0.4	<0.2	20.7	16.4	<0.01	0.02	19.9
I031012		0.44	1.2	460	5.4	21.6	<0.001	0.06	0.73	0.4	0.3	8.7	9.2	<0.01	0.04	17.0
I031013		0.52	1.8	280	3.9	10.4	<0.001	1.60	0.50	0.3	0.3	19.0	4.7	<0.01	0.12	7.3
I031014		0.17	2.9	2490	3.1	1.4	<0.001	0.02	0.59	0.7	0.2	0.7	11.7	<0.01	0.10	16.1
I031015		0.30	0.7	340	7.7	7.6	<0.001	0.05	0.33	0.2	<0.2	5.3	6.0	<0.01	0.27	11.0
I031016		0.56	4.4	1760	3.7	0.3	<0.001	0.02	1.35	0.5	0.2	4.0	12.7	<0.01	0.04	13.2
I031017		0.10	0.6	240	9.1	18.4	<0.001	0.01	0.23	0.3	0.2	1.7	7.4	<0.01	0.40	14.9
I031018		0.19	3.3	1300	2.2	3.1	0.001	<0.01	0.69	0.5	0.2	0.3	6.5	<0.01	0.36	8.1
I031019		0.84	0.8	250	4.1	7.8	0.001	0.07	0.74	0.4	<0.2	16.4	4.9	<0.01	0.05	9.4
I031020		0.10	1.3	710	12.7	26.3	<0.001	0.01	1.26	1.3	0.3	1.5	13.5	<0.01	0.01	27.7
I031021		0.24	1.2	380	5.8	24.2	<0.001	<0.01	0.70	0.4	<0.2	9.6	9.4	<0.01	0.02	15.0
I031022		0.60	2.1	540	79.6	20.4	<0.001	0.04	0.52	1.2	0.2	0.8	9.6	<0.01	0.01	21.9
I031023		0.12	0.4	410	18.7	3.7	<0.001	<0.01	0.25	0.2	<0.2	0.9	8.9	<0.01	<0.01	20.0
I031024		0.45	1.2	700	25.5	7.3	<0.001	<0.01	0.47	0.9	0.2	0.7	10.8	<0.01	0.01	29.5
I034454		0.12	1.7	150	1385	16.5	<0.001	2.75	316	0.5	<0.2	3.5	4.2	<0.01	0.04	5.3
I034455		0.62	1.6	850	14.5	1.8	<0.001	0.02	1.87	0.3	0.3	4.2	11.4	<0.01	0.27	11.5
I034456		1.01	3.0	640	30.1	22.4	<0.001	1.03	1.22	3.1	0.8	0.8	13.9	<0.01	0.19	22.1
I034457		0.18	1.7	180	41.3	17.6	<0.001	0.23	1.79	0.4	0.7	1.5	5.4	<0.01	0.61	10.9
I034458		0.52	0.3	370	17.5	28.5	<0.001	<0.01	0.37	0.4	<0.2	0.5	5.4	<0.01	0.16	27.1
I034459		0.27	0.8	320	39.4	25.6	<0.001	<0.01	0.82	0.5	0.3	4.7	5.0	<0.01	0.65	19.9
I034460		0.30	0.5	330	49.9	28.2	<0.001	<0.01	1.96	0.3	0.2	16.4	4.2	<0.01	0.31	24.6
I034461		0.30	1.2	390	55.7	28.1	<0.001	0.09	0.82	0.6	0.5	10.6	5.9	<0.01	1.08	26.4
I034051		0.18	4.8	900	329	5.3	<0.001	1.58	1.92	4.1	0.4	0.8	27.4	<0.01	0.28	19.3
I034052		1.28	3.7	760	29.8	43.9	<0.001	1.72	1.22	5.7	1.2	2.9	19.7	<0.01	0.09	26.1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089643

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I031011		0.008	0.26	4.93	6	12.15	4.88	22	3.1
I031012		0.007	0.20	3.85	2	4.65	4.83	11	3.4
I031013		0.005	0.11	0.91	2	24.1	0.99	3	1.4
I031014		0.007	<0.02	1.91	5	0.35	5.59	10	9.2
I031015		<0.005	0.08	2.10	2	12.40	1.85	11	3.5
I031016		0.018	<0.02	1.31	12	21.7	10.40	13	7.1
I031017		<0.005	0.18	3.46	1	0.48	6.31	9	1.1
I031018		0.006	0.02	1.59	10	0.22	4.32	4	3.3
I031019		0.007	0.08	2.28	4	26.5	1.44	12	1.5
I031020		<0.005	0.27	3.84	13	1.33	10.70	35	5.3
I031021		0.006	0.20	2.32	4	6.31	3.13	22	1.8
I031022		0.041	0.18	4.59	14	0.46	6.44	51	3.9
I031023		<0.005	0.05	3.56	1	0.15	3.18	17	2.1
I031024		0.026	0.09	7.18	5	0.15	9.82	24	1.7
I034454		<0.005	0.25	6.09	3	1.79	0.68	393	2.6
I034455		0.045	0.02	1.62	7	2.61	4.20	6	3.9
I034456		0.085	0.15	5.42	34	0.44	9.34	42	7.1
I034457		<0.005	0.28	8.14	10	2.24	4.53	39	4.1
I034458		<0.005	0.28	4.51	2	1.51	4.40	21	4.7
I034459		<0.005	0.31	6.49	7	6.88	4.79	95	4.8
I034460		<0.005	0.32	4.48	4	10.60	4.44	31	4.4
I034461		0.007	0.31	13.75	14	8.17	6.96	88	2.1
I034051		0.013	0.21	6.91	60	0.22	8.28	751	22.4
I034052		0.110	0.48	6.03	54	0.43	8.75	51	2.8

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089643

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

CERTIFICATE WH10089647

Project: SQI10-01

P.O. No.: SQI10-01_8

This report is for 60 Rock samples submitted to our lab in Whitehorse, YT, Canada on 6-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-MS41	51 anal. aqua regia ICPMS	
Cu-OG46	Ore Grade Cu - Aqua Regia	VARIABLE
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature: 

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089647

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	Au-GRA21 Au Check ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02
I031025		1.02	0.009			0.40	0.35	10.4	<0.2	130	50	0.79	1.64	0.56	0.67	59.6
I031026		0.76	2.93	5.86	3.36	36.3	0.16	74.8	2.1	30	20	0.57	291	0.02	0.90	14.55
I031027		0.84	0.013			0.70	0.18	7.8	<0.2	130	20	0.75	3.97	0.22	1.32	24.2
I031028		0.68	0.011			1.02	0.32	8.2	<0.2	130	60	0.78	3.19	0.45	0.24	33.0
I031029		0.96	>10.0	112.5		>100	0.45	278	>25.0	<10	20	3.53	3710	0.02	0.53	10.75
I031030		1.16	0.297			1.43	0.56	17.7	0.2	<10	50	0.82	22.3	0.10	0.44	29.1
I031031		0.56	0.036			0.28	0.93	8.9	<0.2	<10	80	0.80	2.38	0.49	0.46	50.5
I031032		1.04	0.035			1.14	0.24	38.9	<0.2	260	10	1.00	8.47	0.43	0.06	20.6
I031033		0.64	6.42	6.41		>100	0.22	515	23.4	<10	30	2.20	1320	0.10	128.0	5.92
I031034		0.66	0.027			2.23	0.28	6.4	<0.2	70	40	0.59	10.50	0.15	0.62	46.2
I031035		1.02	0.344			2.62	0.16	80.5	0.3	20	30	0.13	11.90	<0.01	0.01	1.65
I031036		1.18	0.275			2.86	0.21	82.4	0.2	<10	40	0.15	11.95	<0.01	0.60	2.47
I031037		0.76	0.075			0.50	0.52	7.8	<0.2	<10	70	0.79	1.57	0.17	<0.01	43.5
I031038		0.96	0.025			0.62	0.25	6.4	<0.2	140	30	0.69	3.04	0.33	0.42	47.0
I031039		0.80	>10.0	50.1		>100	0.33	632	>25.0	<10	20	0.96	5000	0.01	3.03	10.95
I031040		0.94	>10.0	19.70		29.6	0.48	469	16.3	<10	60	2.48	882	0.03	1.73	18.10
I031041		0.52	0.071			1.23	0.31	4.6	<0.2	50	40	0.39	15.75	0.08	0.08	44.3
I031042		0.50	0.081			2.94	0.62	165.0	<0.2	20	250	0.26	45.5	0.28	0.01	26.3
I031043		0.50	0.049			0.61	0.16	29.5	<0.2	100	20	0.69	10.15	0.07	0.06	43.3
I031044		0.68	0.020			0.51	0.16	37.3	<0.2	50	20	0.92	3.62	0.09	0.31	19.70
I031045		0.44	0.013			0.62	0.21	9.6	<0.2	160	40	0.73	5.65	0.26	0.26	33.6
I031046		0.48	0.316			3.95	0.70	76.5	0.6	<10	70	1.08	208	0.02	0.90	33.5
I031047		0.68	>10.0	14.15		56.6	0.63	342	19.5	<10	20	3.99	576	0.02	0.58	12.25
I031048		0.88	0.054			0.78	0.30	23.2	<0.2	160	40	0.60	8.37	0.25	0.13	34.5
I031049		0.48	0.011			0.32	0.70	7.7	<0.2	10	130	0.30	2.36	0.22	0.11	27.9
I031050		0.62	0.008			0.18	0.33	4.5	<0.2	10	70	0.37	1.17	0.13	0.12	21.3
I034462		1.34	0.015			0.14	0.51	4.6	<0.2	20	80	0.33	0.92	0.07	0.05	17.05
I034463		1.32	0.013			0.15	0.22	7.5	<0.2	<10	40	0.16	0.93	0.06	<0.01	4.84
I034464		1.08	3.43	2.75		47.0	0.52	189.0	0.9	10	40	0.31	841	0.10	0.10	5.23
I034465		1.30	0.014			0.41	0.13	7.4	<0.2	30	20	0.34	3.71	0.07	0.04	14.75
I034466		1.20	0.037			1.57	0.31	219	<0.2	80	50	0.57	11.65	0.01	0.05	20.7
I034467		0.82	0.126			4.69	0.11	210	<0.2	20	10	0.38	20.1	0.02	0.47	4.66
I034468		0.78	0.142			0.98	0.34	216	<0.2	<10	40	0.59	9.63	0.02	0.52	21.0
I034469		1.22	0.056			2.28	0.18	176.5	<0.2	20	30	0.36	9.86	0.02	0.05	4.39
I034470		0.66	1.615	1.52		>100	0.27	576	1.8	<10	20	0.39	7.18	<0.01	9.19	5.65
I034471		0.84	0.305			1.42	0.17	31.9	<0.2	280	<10	0.99	1.20	0.47	0.10	10.50
I034472		0.78	0.181			2.42	0.84	48.4	0.2	10	80	0.86	5.56	0.19	0.38	49.7
I034473		0.80	0.449			0.29	0.37	29.6	<0.2	80	50	0.62	52.6	0.52	0.03	24.1
I034474		0.78	0.461			1.98	0.08	12.7	<0.2	<10	20	0.17	11.20	0.03	0.89	3.52
I034475		0.94	0.020			0.66	0.41	26.8	<0.2	80	20	0.98	2.71	0.19	0.11	50.3

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089647

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Co	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn
	Units	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm
	LOR	0.1	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5
I031025		7.3	7	2.61	10.3	1.39	1.40	<0.05	0.19	0.01	0.028	0.11	32.3	2.9	0.04	646
I031026		30.1	15	0.69	151.5	6.84	1.66	0.09	0.10	0.44	0.078	0.07	8.4	0.4	0.02	80
I031027		6.0	13	1.31	10.0	2.89	1.23	<0.05	0.36	0.01	0.030	0.04	11.9	1.0	0.03	350
I031028		4.1	7	2.16	5.3	1.49	1.21	<0.05	0.23	0.01	0.027	0.16	17.4	1.0	0.03	2010
I031029		125.5	3	5.08	>10000	27.2	3.63	0.35	0.05	0.04	2.11	0.13	5.7	1.0	0.01	51
I031030		7.4	7	8.81	531	3.00	2.43	<0.05	0.10	0.10	0.083	0.32	17.1	2.2	0.04	238
I031031		6.3	10	10.55	7.3	2.66	3.38	0.05	0.11	0.03	0.045	0.43	26.9	5.1	0.10	146
I031032		6.7	13	0.80	46.5	2.61	1.80	0.06	0.18	0.02	0.070	0.04	10.0	0.8	0.03	72
I031033		4.7	5	1.67	>10000	1.41	1.92	<0.05	0.02	10.20	0.627	0.17	3.9	1.1	0.02	145
I031034		1.0	10	2.39	435	1.81	1.21	<0.05	0.13	0.05	0.037	0.15	25.4	0.9	0.02	134
I031035		3.0	10	3.82	12.6	3.47	0.98	<0.05	0.03	0.05	0.011	0.13	1.2	0.8	0.01	67
I031036		3.0	6	2.64	110.5	4.22	1.48	0.05	0.05	0.09	0.033	0.16	1.5	0.8	0.01	142
I031037		6.9	5	9.20	3.9	10.60	2.48	0.15	0.10	0.05	0.020	0.34	23.1	1.7	0.03	253
I031038		3.1	6	2.21	11.3	1.31	1.24	<0.05	0.22	<0.01	0.024	0.08	24.9	1.3	0.03	547
I031039		131.5	8	2.46	>10000	22.2	3.91	0.29	0.05	0.12	2.34	0.18	6.1	1.0	0.01	37
I031040		22.7	5	11.25	1495	13.55	3.14	0.23	0.10	0.08	0.119	0.23	10.0	1.1	0.03	231
I031041		0.8	7	1.91	23.3	2.69	1.08	<0.05	0.13	0.01	0.030	0.18	24.9	1.3	0.02	87
I031042		8.1	5	3.17	112.5	2.58	2.91	0.07	0.17	0.01	0.025	0.12	14.4	6.1	0.20	180
I031043		1.0	10	1.51	11.9	0.73	0.85	<0.05	0.21	0.01	0.052	0.06	23.8	0.6	0.01	58
I031044		1.4	14	1.19	31.0	1.75	1.10	<0.05	0.09	<0.01	0.031	0.09	9.9	1.1	0.02	123
I031045		3.3	9	1.04	19.6	0.98	0.88	<0.05	0.26	<0.01	0.024	0.07	16.0	1.0	0.02	931
I031046		6.4	17	14.00	740	9.17	5.14	0.13	0.28	0.03	0.260	0.25	19.6	1.6	0.06	124
I031047		11.3	3	10.85	2110	17.25	7.31	0.31	0.04	0.01	4.61	0.15	8.8	1.0	0.01	340
I031048		6.6	8	1.81	31.6	2.40	1.04	0.05	0.20	<0.01	0.071	0.10	18.5	1.0	0.05	100
I031049		1.8	12	4.18	15.9	2.11	4.02	0.09	0.17	<0.01	0.022	0.23	15.3	17.2	0.34	165
I031050		1.4	6	1.58	5.6	1.30	1.41	<0.05	0.11	<0.01	0.009	0.20	12.0	3.6	0.06	62
I034462		0.7	5	2.44	2.2	1.23	1.24	<0.05	0.08	<0.01	0.031	0.40	9.7	1.2	0.02	63
I034463		1.8	8	1.48	1.7	2.44	1.12	<0.05	0.08	0.02	0.017	0.16	2.4	0.7	0.01	52
I034464		18.3	6	3.21	38.6	6.25	1.79	<0.05	0.05	<0.01	0.071	0.41	2.4	1.6	0.03	405
I034465		2.2	16	0.98	22.6	2.89	0.92	0.06	0.04	0.01	0.043	0.07	7.3	0.5	0.01	78
I034466		3.5	7	1.44	3.5	1.96	0.80	0.05	0.17	<0.01	0.076	0.21	10.5	0.8	0.02	49
I034467		1.4	14	1.93	7.5	9.26	1.30	0.14	0.02	0.04	0.018	0.05	2.2	0.9	0.01	144
I034468		2.8	12	1.69	32.7	6.88	2.29	0.11	0.02	0.02	0.052	0.19	9.6	1.2	0.02	599
I034469		19.4	5	1.58	5.9	12.30	1.20	0.19	0.08	0.02	0.038	0.09	2.2	0.6	0.01	34
I034470		1.5	5	1.11	1640	8.35	1.20	0.13	0.04	0.37	0.607	0.11	6.2	1.0	0.01	130
I034471		9.0	18	0.39	12.3	0.61	1.12	<0.05	0.14	<0.01	0.031	0.01	4.3	0.8	0.04	69
I034472		11.5	18	7.95	70.8	3.89	6.31	0.11	0.56	0.02	0.049	0.31	24.3	6.5	0.21	542
I034473		16.7	14	2.10	12.1	7.23	2.29	0.13	0.23	0.15	0.027	0.18	12.1	1.4	0.04	92
I034474		1.7	14	0.59	19.3	2.00	0.49	<0.05	0.02	0.03	0.198	0.04	1.7	1.1	<0.01	1120
I034475		2.5	5	2.92	11.3	2.72	2.11	0.10	0.15	0.01	0.052	0.16	24.5	1.7	0.04	132

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089647

Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
Analyte	Mo	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta
Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
Sample Description LOR	0.05	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01
I031025	1.26	0.01	0.25	2.4	2340	20.0	17.8	<0.001	0.02	1.09	0.5	<0.2	1.1	25.1	<0.01
I031026	1.92	0.01	0.78	6.6	250	152.0	8.3	<0.001	0.05	55.2	0.3	5.1	34.8	7.9	<0.01
I031027	0.98	0.01	0.34	2.8	990	12.8	6.2	<0.001	0.01	3.06	0.4	<0.2	1.5	11.6	<0.01
I031028	1.12	0.01	0.22	2.1	1960	7.8	27.6	<0.001	0.02	1.50	0.5	<0.2	1.3	22.4	<0.01
I031029	20.5	0.01	0.19	40.8	1210	1855	17.3	<0.001	0.07	22.3	0.4	4.4	5.8	4.8	<0.01
I031030	1.50	<0.01	0.44	1.7	410	307	38.6	<0.001	0.01	9.28	1.0	<0.2	10.1	7.1	<0.01
I031031	0.30	0.01	0.19	4.6	2070	26.2	48.9	<0.001	0.01	1.06	1.4	<0.2	8.1	11.1	<0.01
I031032	2.22	0.02	0.43	4.7	1890	8.4	7.0	<0.001	0.01	2.39	0.5	<0.2	4.9	11.6	<0.01
I031033	1.82	<0.01	<0.05	1.4	240	1025	28.6	<0.001	0.03	6910	0.2	0.3	3.3	8.1	<0.01
I031034	1.28	0.01	0.26	0.9	590	26.6	18.4	<0.001	0.01	23.4	0.3	<0.2	2.3	7.1	<0.01
I031035	1.47	<0.01	0.49	0.8	290	24.6	16.1	<0.001	0.44	2.67	0.3	0.4	43.9	61.8	<0.01
I031036	1.01	<0.01	0.45	0.7	250	10.6	19.3	<0.001	0.24	28.8	0.4	0.6	37.4	56.7	<0.01
I031037	0.84	<0.01	0.51	1.9	850	17.4	41.7	0.001	0.03	3.01	0.9	0.2	90.4	8.1	<0.01
I031038	0.48	0.01	0.22	1.5	1470	11.4	13.6	<0.001	0.03	1.39	0.5	<0.2	1.6	15.6	<0.01
I031039	56.0	<0.01	0.49	37.7	3470	4410	24.3	<0.001	0.06	86.8	0.5	3.4	60.0	3.3	<0.01
I031040	5.23	0.01	0.55	5.2	940	448	22.8	<0.001	0.15	5.82	0.7	2.8	22.3	34.7	0.01
I031041	0.89	0.01	0.39	0.9	370	50.5	21.6	<0.001	0.04	0.88	0.3	0.3	3.3	6.1	<0.01
I031042	121.5	0.07	1.30	1.7	950	59.7	9.3	0.007	1.05	2.48	1.0	1.5	44.4	26.5	<0.01
I031043	12.25	0.01	0.31	0.7	290	16.5	7.4	<0.001	0.01	0.97	0.2	<0.2	1.5	5.9	<0.01
I031044	5.24	0.01	0.16	1.4	380	21.8	12.2	<0.001	0.04	2.13	0.3	0.2	1.2	5.9	<0.01
I031045	1.19	0.01	0.19	1.5	1180	10.1	11.6	<0.001	0.01	1.95	0.6	<0.2	1.2	20.5	<0.01
I031046	16.80	<0.01	0.79	2.1	1010	497	52.3	<0.001	0.03	5.18	1.6	1.3	23.0	41.3	<0.01
I031047	38.7	<0.01	0.55	2.2	1790	665	24.7	<0.001	0.04	29.3	2.4	0.9	20.3	34.9	<0.01
I031048	0.99	0.01	0.37	3.6	1040	18.2	13.9	<0.001	0.01	3.04	0.7	<0.2	0.7	13.2	<0.01
I031049	5.48	0.09	2.48	1.8	800	51.0	35.2	0.001	0.17	0.93	2.1	1.5	3.0	56.8	0.01
I031050	4.36	0.04	0.10	1.1	780	37.3	14.5	<0.001	0.30	0.36	1.3	1.8	0.4	104.0	<0.01
I034462	1.34	0.01	0.15	0.7	490	3.5	46.2	<0.001	0.03	0.24	0.4	<0.2	2.4	11.0	<0.01
I034463	0.28	0.01	0.26	1.1	280	4.9	18.6	<0.001	0.25	0.47	0.4	<0.2	24.7	5.9	<0.01
I034464	1.23	0.01	0.12	2.6	580	207	63.8	<0.001	2.00	2.30	0.8	1.1	6.3	11.6	<0.01
I034465	1.47	0.01	0.19	1.3	250	32.4	8.6	<0.001	0.01	1.17	0.3	0.2	3.7	3.5	<0.01
I034466	2.11	0.02	0.19	1.4	180	97.4	27.2	<0.001	0.94	0.67	0.4	1.1	1.4	37.8	<0.01
I034467	6.51	0.02	0.12	1.5	160	45.4	5.5	<0.001	2.07	5.01	0.5	1.0	1.0	5.2	<0.01
I034468	8.89	0.01	0.10	2.3	270	52.6	22.9	<0.001	0.10	11.35	0.7	0.4	2.4	8.1	<0.01
I034469	7.57	0.01	0.17	1.8	250	76.3	12.7	<0.001	1.91	3.46	0.6	0.8	3.7	3.8	<0.01
I034470	66.8	0.02	0.10	1.4	490	>10000	13.2	<0.001	0.92	2980	0.8	0.8	2.5	4.5	<0.01
I034471	3.59	0.03	0.20	2.0	2000	40.2	1.6	<0.001	0.01	9.72	0.5	0.2	1.3	11.7	<0.01
I034472	1.68	0.01	0.18	4.1	630	201	32.7	<0.001	0.01	20.8	1.5	0.3	13.1	19.2	<0.01
I034473	0.91	0.02	1.56	18.0	2390	12.6	18.1	0.001	0.01	3.68	0.9	0.4	49.8	12.7	<0.01
I034474	3.47	0.01	0.20	2.3	110	50.8	5.3	<0.001	0.01	19.35	0.3	<0.2	0.9	3.2	<0.01
I034475	1.02	0.01	0.23	2.4	860	11.7	26.0	<0.001	0.01	2.65	0.5	0.2	0.7	16.4	<0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089647

Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	Cu-OG46	Ag-GRA21	Pb-OG46
Analyte	Te	Th	Ti	Tl	U	V	W	Y	Zn	Zr	Cu	Ag	Pb
Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	%
Sample Description LOR	0.01	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.001	5	0.001
I031025	0.18	16.8	0.011	0.21	4.19	5	1.71	6.47	29	9.1			
I031026	83.1	13.1	0.015	0.09	19.45	20	30.0	2.44	44	3.3			
I031027	0.86	14.8	0.016	0.08	8.15	7	2.43	4.66	44	10.3			
I031028	0.67	15.6	0.008	0.30	3.45	6	2.78	7.08	24	10.9			
I031029	46.3	8.5	<0.005	0.18	66.5	49	63.9	6.78	200	1.4	1.625	543	
I031030	0.42	24.6	0.008	0.48	6.43	38	12.20	7.13	64	2.5			
I031031	0.09	16.4	0.022	0.54	2.48	26	7.91	8.66	114	4.0			
I031032	0.71	10.8	0.017	0.07	2.90	12	19.10	5.52	24	8.0			
I031033	1.12	7.9	<0.005	0.38	45.3	14	1.30	2.16	441	0.6	3.16	509	
I031034	0.11	21.3	0.010	0.19	4.93	2	3.02	5.97	18	3.1			
I031035	0.54	2.4	0.005	0.16	1.63	8	26.4	0.39	7	0.8			
I031036	0.34	2.2	0.008	0.19	2.81	13	36.5	0.71	15	1.3			
I031037	0.12	10.3	0.024	0.39	8.01	37	55.5	8.69	71	2.2			
I031038	0.17	12.6	0.009	0.15	3.84	4	1.86	5.14	32	9.6			
I031039	11.45	5.6	<0.005	0.29	158.5	160	60.2	9.88	340	0.9	2.20	470	
I031040	5.68	22.9	<0.005	0.26	24.6	60	103.5	4.30	189	2.8			
I031041	2.12	22.4	0.008	0.26	4.42	4	2.89	5.15	20	3.4			
I031042	0.29	12.2	0.097	0.13	4.11	14	1.89	7.00	30	3.3			
I031043	1.20	22.9	<0.005	0.09	4.74	<1	1.07	4.75	14	4.8			
I031044	0.44	21.6	<0.005	0.19	11.30	3	0.90	5.43	35	2.0			
I031045	0.15	17.7	0.007	0.12	2.51	3	1.10	4.96	20	9.2			
I031046	0.85	18.3	0.023	0.47	26.9	46	21.9	4.28	84	10.0			
I031047	2.24	6.1	0.006	0.21	72.0	39	28.6	5.87	100	0.9			
I031048	0.16	19.5	0.018	0.14	3.60	10	2.81	5.82	41	5.9			
I031049	0.04	19.7	0.138	0.24	5.48	30	0.95	7.46	44	3.4			
I031050	0.02	26.5	0.008	0.17	5.17	8	0.15	5.52	16	2.6			
I034462	0.06	29.0	0.005	0.53	9.34	1	2.33	2.88	10	2.0			
I034463	0.02	6.8	0.009	0.17	1.22	10	18.25	1.20	7	2.5			
I034464	0.87	7.7	<0.005	0.67	6.29	9	5.45	2.27	23	1.4			
I034465	0.11	5.8	0.008	0.10	2.22	4	2.72	1.86	14	1.0			
I034466	0.15	7.9	0.005	0.43	1.44	1	0.23	1.68	15	4.6			
I034467	1.31	2.9	<0.005	0.08	16.10	7	4.94	3.28	147	0.5			
I034468	0.75	7.9	<0.005	0.35	21.7	12	4.52	2.60	74	0.6			
I034469	1.43	4.6	<0.005	0.18	11.15	10	2.91	1.02	13	2.1			
I034470	0.07	4.1	<0.005	0.19	85.2	9	28.9	1.07	528	1.1		153	1.680
I034471	0.07	19.6	0.008	0.02	3.43	4	0.53	5.87	11	4.7			
I034472	0.08	23.4	0.015	0.35	8.59	22	11.65	5.77	76	20.7			
I034473	17.55	20.4	0.107	0.17	7.22	29	101.5	7.15	21	10.6			
I034474	0.62	1.2	<0.005	0.05	0.77	5	12.70	0.62	87	1.0			
I034475	0.38	15.8	0.012	0.23	3.50	13	3.48	6.80	21	7.4			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089647

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	Au-GRA21 Au Check ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02
G092252		0.48	0.010			0.21	0.48	4.6	<0.2	<10	190	0.63	0.75	0.08	0.19	30.7
G092253		0.66	0.015			0.19	0.58	22.1	<0.2	10	190	0.45	2.75	0.13	0.03	14.50
G092254		0.74	0.029			0.26	1.14	303	<0.2	<10	50	0.46	6.38	0.48	0.16	40.6
G092255		0.74	0.015			2.07	0.40	16.8	<0.2	50	120	0.61	11.55	0.06	0.07	78.2
G092256		0.58	0.143			0.09	0.41	16.5	<0.2	70	20	0.47	2.84	0.40	0.14	25.3
G092257		0.90	0.133			3.11	0.42	7.5	<0.2	80	20	0.86	16.00	0.37	0.20	19.95
G092258		0.68	0.010			0.51	0.54	26.7	<0.2	10	130	0.51	13.15	0.47	0.24	57.9
G092259		0.56	0.043			0.38	0.22	118.5	<0.2	10	50	0.36	6.84	0.02	0.09	5.64
G092260		0.88	<0.005			0.11	0.40	6.4	<0.2	10	80	0.29	0.42	0.12	0.24	60.9
G092261		0.64	0.038			1.04	0.59	6.9	<0.2	<10	240	0.42	2.96	0.11	0.14	13.80
G092262		0.68	0.009			1.88	0.47	7.5	<0.2	<10	190	0.45	5.07	0.02	0.10	3.85
G092263		0.38	0.010			0.17	1.07	7.9	<0.2	<10	130	0.28	6.91	0.25	0.06	43.8
G092264		0.68	0.008			0.19	0.92	2.6	<0.2	<10	90	0.49	2.29	0.04	0.05	15.90
G092265		0.52	0.022			0.11	1.17	9.4	<0.2	<10	100	0.26	845	0.26	0.09	34.9
G092266		1.08	0.015			2.88	0.36	92.3	<0.2	<10	160	0.21	6.76	0.02	0.48	25.0
G092267		0.30	0.014			1.60	0.24	13.3	<0.2	10	110	0.17	1.85	0.01	0.20	6.08
G092268		1.08	0.017			7.35	0.36	59.9	<0.2	<10	110	0.20	15.95	0.04	0.25	21.7
G092269		0.86	0.016			1.99	0.55	88.0	<0.2	<10	160	0.31	5.28	0.03	0.45	43.7
G092270		0.76	0.014			2.04	0.29	7.9	<0.2	10	130	0.36	2.58	0.02	0.42	33.3
G092271		0.58	0.038			11.45	0.21	67.3	<0.2	10	90	0.36	37.8	0.02	0.51	25.8

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089647

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Co	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn
	Units	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm
	LOR	0.1	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5
G092252		3.0	6	2.90	19.5	1.64	1.93	0.06	0.11	<0.01	0.016	0.18	15.0	2.5	0.07	73
G092253		2.8	6	1.50	7.2	2.72	2.64	0.06	0.20	<0.01	0.032	0.17	7.3	8.7	0.21	131
G092254		25.0	51	17.80	7.3	7.84	6.08	0.22	0.65	<0.01	0.100	0.60	19.2	24.9	0.96	347
G092255		0.8	3	3.18	46.5	3.52	2.61	0.13	0.11	0.01	0.032	0.23	36.7	1.6	0.03	61
G092256		11.8	5	2.74	8.5	1.20	1.48	<0.05	0.13	0.01	0.044	0.23	11.8	1.5	0.03	357
G092257		6.3	3	4.03	26.7	6.58	2.71	0.12	0.18	0.02	0.031	0.16	9.2	1.2	0.03	130
G092258		5.3	4	2.69	6.8	1.81	1.56	0.08	0.13	0.03	0.038	0.30	27.6	1.9	0.04	415
G092259		1.3	7	1.14	6.1	2.20	0.82	<0.05	0.09	0.01	0.017	0.14	2.9	0.8	0.02	77
G092260		1.7	5	1.60	5.8	2.25	1.50	0.10	0.09	0.01	0.013	0.23	26.1	1.9	0.03	60
G092261		2.7	6	1.85	67.1	2.98	2.44	0.06	0.50	0.01	0.028	0.27	7.2	5.4	0.17	54
G092262		2.0	2	1.35	18.1	4.59	1.58	0.07	0.40	<0.01	0.009	0.27	2.3	2.5	0.05	35
G092263		4.3	13	16.55	24.9	2.50	6.60	0.15	0.27	<0.01	0.093	0.66	21.6	15.7	0.66	170
G092264		1.2	7	3.90	14.5	1.48	3.93	0.07	0.24	<0.01	0.016	0.59	7.6	33.8	0.64	86
G092265		4.5	11	7.24	69.3	1.84	6.54	<0.05	0.46	<0.01	0.067	0.37	15.8	18.7	0.59	167
G092266		0.3	3	2.41	12.3	2.93	2.44	0.05	0.17	0.01	0.097	0.65	13.3	1.8	0.02	56
G092267		0.2	2	1.16	9.8	1.13	0.79	<0.05	0.16	0.04	0.012	0.28	3.0	0.7	0.01	35
G092268		0.2	4	1.64	14.2	2.36	1.76	<0.05	0.17	0.04	0.167	0.58	12.6	1.6	0.03	42
G092269		0.7	5	3.65	25.0	3.73	4.20	0.07	0.12	0.01	0.103	0.81	25.7	5.2	0.10	76
G092270		0.4	5	1.68	32.8	1.86	1.18	<0.05	0.12	0.01	0.060	0.29	20.4	3.2	0.01	62
G092271		0.7	10	1.69	32.2	1.71	1.06	<0.05	0.09	0.09	0.078	0.20	12.8	1.0	0.01	65

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089647

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Mo	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01
G092252		14.25	0.07	0.24	1.8	340	19.6	25.0	0.003	0.42	1.62	1.1	1.1	0.4	14.7	<0.01
G092253		2.08	0.05	0.13	2.3	810	27.2	18.4	<0.001	1.05	0.68	1.0	1.5	1.2	23.8	<0.01
G092254		4.71	0.10	2.05	15.2	970	33.5	99.7	0.001	8.09	1.27	5.5	6.4	4.2	24.4	<0.01
G092255		21.6	0.03	0.13	0.9	1930	48.7	22.6	<0.001	0.26	1.43	0.5	1.6	1.2	208	<0.01
G092256		0.84	0.01	0.15	3.3	1620	12.1	41.1	<0.001	0.01	1.49	0.6	<0.2	1.9	15.0	<0.01
G092257		11.80	0.02	0.70	3.2	1670	22.3	29.2	<0.001	0.01	1.36	0.5	0.3	6.1	8.9	<0.01
G092258		31.1	0.01	0.10	2.6	780	23.4	28.8	<0.001	1.02	0.43	0.8	1.0	1.3	17.6	<0.01
G092259		23.0	0.02	0.29	0.9	100	21.5	20.3	<0.001	0.06	0.75	0.5	0.7	0.8	4.9	<0.01
G092260		17.60	0.02	0.08	1.3	840	31.5	29.8	0.004	1.21	0.33	0.4	0.9	0.7	7.8	<0.01
G092261		24.3	0.06	0.56	1.7	820	187.0	30.0	0.003	0.44	0.68	1.7	2.6	1.0	15.5	<0.01
G092262		23.3	0.07	0.25	0.9	600	255	27.3	0.003	0.71	0.42	0.8	2.9	0.7	40.4	<0.01
G092263		4.21	0.13	2.40	1.8	770	39.7	96.9	0.001	0.20	0.42	6.4	1.2	17.3	35.1	0.01
G092264		24.7	0.09	0.44	1.1	250	38.6	73.5	0.002	0.26	1.05	4.0	1.2	3.5	23.2	<0.01
G092265		5.52	0.08	0.94	5.4	730	39.3	58.2	0.003	0.53	1.55	4.6	8.9	6.3	16.5	0.01
G092266		6.87	0.03	0.10	0.5	300	758	64.3	0.001	1.02	1.09	0.6	1.1	0.8	19.1	<0.01
G092267		2.58	0.03	0.13	0.3	110	978	28.6	0.001	0.48	0.80	0.3	0.7	1.3	6.0	<0.01
G092268		9.52	0.03	0.22	0.5	200	875	49.5	0.001	0.89	2.04	0.8	0.6	2.6	8.5	<0.01
G092269		4.89	0.04	0.24	0.8	390	481	53.7	0.001	1.32	3.20	1.7	0.7	1.1	28.3	<0.01
G092270		17.70	0.03	0.07	0.7	200	221	24.7	0.001	0.58	0.52	0.7	0.9	0.5	17.0	<0.01
G092271		20.1	0.05	0.24	0.9	300	896	23.8	0.001	0.51	18.55	0.7	0.6	0.9	16.9	<0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089647

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	Cu-OG46	Ag-GRA21	Pb-OG46
	Analyte	Te	Th	Ti	Tl	U	V	W	Y	Zn	Zr	Cu	Ag	Pb
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	%
	LOR	0.01	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.001	5	0.001
G092252		0.03	42.3	0.005	0.23	16.40	5	0.41	5.67	77	3.1			
G092253		0.45	24.7	<0.005	0.25	4.13	10	0.06	5.20	24	5.8			
G092254		0.59	16.8	0.150	1.19	4.50	52	0.54	12.55	59	17.1			
G092255		0.39	4.5	0.009	0.27	3.13	8	1.15	5.73	16	4.5			
G092256		0.03	16.0	0.006	0.43	2.74	10	0.55	4.51	17	6.0			
G092257		7.54	22.7	0.049	0.29	10.95	17	10.75	7.98	48	7.3			
G092258		0.30	32.7	<0.005	0.36	7.80	3	0.32	11.80	32	3.0			
G092259		1.27	6.0	0.005	0.23	2.19	5	4.16	1.22	19	2.0			
G092260		0.04	10.6	<0.005	0.37	1.61	2	0.12	4.47	62	2.6			
G092261		0.06	13.4	0.026	0.34	2.79	19	0.23	3.94	80	20.9			
G092262		0.08	10.0	0.012	0.32	1.56	7	0.12	1.52	68	20.2			
G092263		0.13	28.1	0.193	1.48	6.58	56	2.00	11.40	28	5.1			
G092264		0.02	9.9	0.033	1.03	0.93	34	0.31	2.14	28	5.8			
G092265		1.65	28.9	0.104	0.79	11.00	40	0.36	11.25	28	9.4			
G092266		0.16	19.9	<0.005	0.98	1.22	3	0.32	0.82	41	5.1			
G092267		0.06	5.7	<0.005	0.32	0.70	1	1.52	0.40	18	3.2			
G092268		0.10	11.2	0.006	0.85	1.12	4	0.92	1.18	33	5.4			
G092269		0.13	20.9	0.009	1.09	2.84	12	0.36	2.13	27	4.3			
G092270		0.12	17.9	<0.005	0.37	2.44	2	0.22	2.34	44	4.0			
G092271		0.42	18.2	<0.005	0.55	2.48	3	27.6	1.07	90	3.4			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 17-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10089647

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

Appendix D-3: Core Geochemical Certificates

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

CERTIFICATE WH10127718

Project: SQI10-01

P.O. No.: SQI10-01_11

This report is for 88 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 17-SEP-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-AA23 Au Check ppm 0.005	Au-GRA21 Au ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02
I102121		1.84	<0.005			0.10	1.03	3.1	<0.2	<10	90	1.11	2.20	0.52	0.20	48.5
I102122		1.70	<0.005			0.23	1.02	3.7	<0.2	<10	80	1.08	2.09	0.51	0.76	48.0
I102123		2.59	0.020			1.38	1.61	3.5	<0.2	<10	70	1.32	5.47	0.45	0.61	56.6
I102124		1.56	<0.005			3.85	0.91	12.4	<0.2	<10	60	0.98	11.70	0.35	0.54	62.2
I102125		2.47	0.016			1.02	2.47	3.8	<0.2	<10	80	2.31	2.63	0.61	0.32	63.4
I102126		2.86	0.037			2.06	1.29	5.8	<0.2	<10	90	1.74	20.1	0.47	0.37	53.6
I102127		2.60	<0.005			3.21	0.98	19.0	<0.2	10	60	1.05	4.02	0.26	0.19	46.0
I102128		5.38	<0.005			0.16	0.81	3.1	<0.2	<10	50	1.02	0.80	0.35	0.13	42.8
I102129		4.87	<0.005			0.19	1.18	4.4	<0.2	<10	90	1.15	1.28	0.54	0.18	52.2
I102130		0.04	3.05		3.15	0.09	0.89	3.9	<0.2	<10	70	0.74	0.80	0.42	0.20	43.4
I102131		3.12	<0.005			2.04	1.78	517	2.6	20	120	0.26	235	9.20	0.68	27.9
I102132		4.98	<0.005			0.16	1.35	5.2	<0.2	<10	80	1.19	3.94	0.51	0.25	61.4
I102133		4.68	<0.005			0.09	2.20	3.9	<0.2	<10	20	1.08	7.80	0.65	0.10	42.5
I102134		2.12	<0.005			0.09	1.27	2.9	<0.2	<10	40	1.41	3.72	0.43	0.41	53.5
I102135		1.10	<0.005			0.12	1.75	6.0	<0.2	<10	60	1.70	5.95	0.56	0.28	53.8
I102136		4.86	0.006			0.21	1.76	6.9	<0.2	<10	40	0.97	4.89	0.90	0.26	33.9
I102137		2.41	<0.005			0.02	1.83	6.5	<0.2	<10	20	0.82	2.19	1.01	0.11	34.3
I102138		3.06	<0.005			0.05	1.21	4.6	<0.2	<10	40	1.00	1.15	0.96	0.13	37.4
I102139		2.09	<0.005			0.16	1.90	5.0	<0.2	<10	70	1.38	3.06	0.72	0.29	33.7
I102140		1.34	<0.005			0.08	0.68	5.5	<0.2	<10	90	0.63	0.35	0.28	0.25	32.3
I102141		2.70	<0.005			0.12	1.70	3.7	<0.2	<10	80	1.26	1.13	0.81	0.34	47.7
I102142		6.34	<0.005			0.08	1.08	4.9	<0.2	<10	80	0.70	1.12	0.82	0.16	44.1
I102143		3.36	<0.005			0.07	2.02	5.6	<0.2	<10	80	1.15	6.98	1.19	0.19	48.7
I102144		5.49	<0.005			0.07	1.20	7.1	<0.2	<10	130	0.48	0.27	0.90	0.20	49.8
I102145		5.46	<0.005			0.11	1.17	8.2	<0.2	<10	140	0.39	0.23	0.79	0.18	48.7
I102146		5.81	<0.005			0.07	1.08	7.6	<0.2	<10	110	0.55	0.77	0.87	0.19	52.0
I102147		4.12	<0.005			0.09	1.54	7.5	<0.2	<10	140	0.87	1.42	1.05	0.19	49.7
I102148		4.91	<0.005			0.07	1.32	7.1	<0.2	<10	140	0.68	0.27	1.24	0.15	44.5
I102149		0.81	<0.005			0.18	2.87	5.7	<0.2	<10	150	2.05	0.15	3.08	0.18	42.0
I102150		1.03	<0.005			0.23	2.90	6.1	<0.2	<10	170	2.21	0.13	2.75	0.18	43.3
I102151		3.25	<0.005			0.08	2.30	6.7	<0.2	<10	170	1.86	0.28	1.63	0.20	44.3
I102152		2.66	<0.005			0.07	1.31	6.5	<0.2	<10	130	0.91	0.41	0.98	0.17	37.9
I102153		4.26	<0.005			0.07	1.46	7.5	<0.2	<10	150	1.08	0.36	0.95	0.15	50.9
I102154		2.09	<0.005			0.05	1.52	7.1	<0.2	<10	110	1.27	0.31	0.87	0.17	64.2
I102155		3.69	<0.005			0.06	1.61	6.4	<0.2	<10	190	1.04	0.14	1.36	0.13	43.0
I102156		4.00	<0.005			0.06	1.66	6.4	<0.2	<10	90	1.59	0.18	1.40	0.13	40.6
I102157		6.48	<0.005			0.06	1.73	6.7	<0.2	<10	90	1.48	0.39	0.91	0.15	47.7
I102158		1.22	<0.005			0.05	1.89	6.2	<0.2	<10	80	2.89	0.80	0.98	0.26	43.4
I102159		3.18	<0.005			0.07	2.12	4.9	<0.2	<10	130	2.92	1.44	1.92	0.26	43.1
I102160		<0.02	<0.005			0.05	1.78	4.5	<0.2	<10	120	2.79	1.23	1.87	0.25	41.3

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Co	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn
	Units	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm
	LOR	0.1	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5
I102121		5.5	18	4.60	16.5	2.38	5.01	0.08	0.13	<0.01	0.036	0.33	26.7	17.7	0.63	860
I102122		4.9	15	4.98	17.2	2.34	4.72	0.08	0.14	<0.01	0.055	0.31	25.3	17.6	0.61	814
I102123		5.4	17	4.91	18.1	3.38	7.03	0.08	0.11	0.01	0.058	0.27	28.5	23.3	0.78	914
I102124		7.2	11	10.55	191.5	3.66	4.32	0.08	0.09	0.02	0.052	0.31	30.4	8.9	0.28	834
I102125		6.4	16	5.46	17.1	3.09	9.53	0.09	0.09	0.03	0.068	0.33	37.6	21.5	0.96	745
I102126		3.2	7	5.55	136.5	1.88	4.63	0.06	0.08	0.01	0.064	0.17	27.5	9.4	0.45	791
I102127		5.8	9	4.84	156.5	4.28	4.94	0.09	0.12	0.03	0.040	0.25	23.3	7.8	0.23	1140
I102128		3.6	13	3.96	11.7	1.96	3.94	0.07	0.22	<0.01	0.030	0.23	21.6	12.9	0.44	563
I102129		4.8	18	4.76	13.6	2.52	5.41	0.10	0.30	<0.01	0.040	0.40	25.6	18.4	0.58	670
I102130		4.4	15	4.09	9.3	2.11	4.37	0.10	0.23	<0.01	0.037	0.32	21.1	19.6	0.53	455
I102131		25.8	48	1.51	292	5.11	6.04	0.20	0.41	5.00	1.495	0.16	13.4	7.0	0.25	864
I102132		5.9	19	5.11	9.7	3.00	6.38	0.09	0.24	0.03	0.065	0.40	29.2	18.8	0.70	686
I102133		4.3	36	3.73	21.4	3.69	9.73	0.08	0.09	0.01	0.081	0.09	20.2	37.7	1.35	898
I102134		3.3	9	3.47	10.7	2.12	5.38	0.07	0.07	0.01	0.094	0.15	21.9	17.9	0.65	755
I102135		4.5	14	5.44	29.1	2.76	7.96	0.09	0.10	0.01	0.137	0.20	26.1	23.7	0.86	512
I102136		8.7	35	7.53	43.3	3.29	9.17	0.12	0.21	<0.01	0.063	0.10	17.0	43.4	1.23	667
I102137		5.1	34	1.50	2.9	3.31	9.40	0.12	0.22	<0.01	0.034	0.06	16.9	37.5	1.25	581
I102138		3.8	10	3.35	2.2	2.74	6.65	0.11	0.11	<0.01	0.037	0.12	18.3	26.1	0.80	474
I102139		7.0	12	5.89	63.1	2.81	8.44	0.10	0.11	<0.01	0.036	0.22	18.3	29.3	0.96	467
I102140		3.5	14	6.42	4.4	1.96	3.73	0.10	0.22	0.01	0.022	0.33	15.3	36.6	0.41	281
I102141		4.5	12	5.08	28.8	2.46	6.85	0.08	0.13	<0.01	0.047	0.25	23.6	16.7	0.69	429
I102142		4.6	11	5.96	9.4	2.59	5.42	0.10	0.11	<0.01	0.059	0.24	20.9	24.7	0.73	477
I102143		5.7	9	4.85	28.8	2.66	6.87	0.09	0.08	<0.01	0.133	0.19	22.7	25.5	0.90	468
I102144		5.8	9	7.58	6.7	2.52	5.59	0.12	0.13	<0.01	0.057	0.26	23.3	32.4	0.75	459
I102145		5.3	9	6.76	6.8	2.62	5.29	0.12	0.17	<0.01	0.048	0.27	23.6	25.7	0.65	431
I102146		5.2	10	9.35	9.4	2.60	5.08	0.11	0.12	<0.01	0.056	0.23	24.6	25.7	0.62	405
I102147		5.4	9	7.19	7.1	2.90	6.56	0.11	0.11	<0.01	0.073	0.30	24.6	26.6	0.83	453
I102148		5.0	9	7.00	5.4	2.67	5.42	0.09	0.10	<0.01	0.046	0.31	21.3	26.5	0.77	432
I102149		4.7	7	6.61	3.9	2.27	7.14	0.07	0.07	<0.01	0.043	0.27	21.2	23.5	0.88	489
I102150		4.7	7	7.30	3.6	2.24	6.67	0.07	0.07	0.01	0.042	0.27	21.6	22.9	0.84	444
I102151		5.1	9	6.06	3.9	2.43	7.15	0.08	0.11	<0.01	0.064	0.30	20.6	22.2	0.81	405
I102152		4.7	9	6.11	3.9	2.40	5.27	0.10	0.11	<0.01	0.057	0.31	18.3	21.0	0.73	389
I102153		5.0	9	7.31	9.0	2.56	6.14	0.10	0.16	<0.01	0.056	0.33	23.4	19.9	0.62	364
I102154		4.2	8	9.17	4.6	2.54	5.83	0.08	0.08	<0.01	0.061	0.22	35.9	14.5	0.57	277
I102155		4.3	9	5.95	4.4	2.23	5.50	0.08	0.16	<0.01	0.054	0.30	20.9	19.3	0.64	481
I102156		4.1	9	5.94	3.5	2.10	5.71	0.07	0.12	<0.01	0.048	0.24	20.8	21.0	0.71	514
I102157		4.1	10	6.00	3.4	2.24	6.22	0.08	0.16	<0.01	0.062	0.26	24.6	18.9	0.74	496
I102158		4.3	9	5.03	5.0	1.86	6.20	0.07	0.07	0.01	0.045	0.22	24.1	17.7	0.77	424
I102159		3.5	9	4.13	4.9	1.95	6.48	0.07	0.10	0.01	0.042	0.23	22.4	15.0	0.63	607
I102160		3.2	9	3.70	4.0	1.89	5.30	0.06	0.08	0.01	0.039	0.22	21.3	13.7	0.59	576

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Mo	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01
I102121		1.57	0.03	0.90	4.3	830	28.1	39.9	<0.001	0.06	0.74	2.7	0.2	1.7	41.9	<0.01
I102122		1.43	0.04	0.93	4.0	770	70.8	38.3	0.001	0.03	0.72	2.6	0.2	1.7	42.6	<0.01
I102123		0.81	0.04	0.20	4.8	850	96.6	30.0	<0.001	0.01	0.47	3.6	0.2	1.3	65.6	<0.01
I102124		1.10	0.01	0.18	3.3	960	181.5	40.3	<0.001	0.01	1.44	2.0	0.2	2.7	24.7	<0.01
I102125		0.48	0.02	0.14	5.2	950	34.6	41.1	<0.001	0.01	0.45	4.3	0.2	1.7	71.4	<0.01
I102126		0.55	0.01	0.10	2.7	650	129.5	22.0	<0.001	0.01	0.70	1.7	0.2	1.2	162.0	<0.01
I102127		2.71	0.01	0.24	2.6	810	19.8	31.0	<0.001	0.01	1.31	1.3	0.2	16.3	27.3	<0.01
I102128		2.45	0.03	1.23	3.1	630	26.8	26.2	<0.001	0.01	0.65	2.1	0.2	1.4	37.6	0.01
I102129		1.75	0.09	1.60	4.2	800	37.8	40.3	<0.001	0.01	0.76	3.4	0.3	2.2	53.9	0.02
I102130		2.07	0.05	1.59	3.8	730	30.4	36.5	<0.001	0.01	0.49	2.4	0.2	1.8	32.2	0.01
I102131		72.6	0.04	1.14	55.0	720	38.3	10.3	0.002	1.03	7.61	4.8	1.2	112.0	78.3	0.02
I102132		1.78	0.06	0.92	5.1	920	41.4	44.3	<0.001	0.01	0.74	4.1	0.3	2.8	46.4	0.01
I102133		0.20	0.03	0.09	9.7	1200	24.9	10.1	<0.001	0.01	0.33	3.3	<0.2	1.2	29.3	<0.01
I102134		0.31	0.03	0.13	3.6	550	34.6	16.2	<0.001	0.01	0.49	2.8	0.2	1.3	31.6	<0.01
I102135		0.39	0.03	0.17	4.5	850	35.2	19.7	<0.001	<0.01	0.75	4.0	0.2	2.4	71.6	<0.01
I102136		2.36	0.05	0.26	9.0	1090	50.8	15.6	<0.001	<0.01	0.76	3.2	0.2	2.7	42.4	<0.01
I102137		0.15	0.05	0.20	8.7	1090	9.7	5.7	<0.001	<0.01	0.88	2.7	0.2	1.7	36.7	<0.01
I102138		0.41	0.04	0.61	3.7	930	17.5	13.0	<0.001	<0.01	0.77	2.6	0.2	1.9	33.7	<0.01
I102139		0.59	0.04	0.33	4.3	970	39.7	22.2	<0.001	<0.01	0.67	3.6	0.2	2.5	38.7	<0.01
I102140		1.07	0.05	2.51	4.0	670	22.4	48.9	<0.001	<0.01	0.51	3.2	0.2	1.8	13.1	0.01
I102141		0.94	0.03	0.25	3.7	780	29.2	27.7	<0.001	0.01	0.50	3.3	0.2	1.9	55.0	<0.01
I102142		1.70	0.04	0.72	3.5	970	21.3	26.1	<0.001	<0.01	0.62	2.4	0.2	2.1	30.1	0.01
I102143		0.44	0.04	0.17	3.3	1100	21.0	19.5	<0.001	<0.01	0.58	2.3	<0.2	2.0	48.4	<0.01
I102144		1.33	0.05	0.82	3.6	1130	22.6	29.7	<0.001	0.01	0.60	2.2	0.2	2.5	42.5	<0.01
I102145		1.48	0.09	1.05	3.4	1180	22.9	27.2	<0.001	<0.01	0.75	2.1	0.3	2.9	64.3	0.01
I102146		1.16	0.05	0.77	3.3	1180	21.9	25.6	<0.001	0.01	0.70	2.4	0.2	2.7	48.8	<0.01
I102147		0.85	0.07	0.48	3.5	1160	21.4	34.5	<0.001	<0.01	0.75	2.6	0.2	3.0	66.5	<0.01
I102148		0.36	0.05	0.61	3.3	1160	22.3	35.0	<0.001	<0.01	0.59	2.1	0.2	2.2	58.8	<0.01
I102149		0.20	0.06	0.17	2.9	1040	21.8	26.8	<0.001	0.01	0.43	2.2	0.2	1.9	173.0	<0.01
I102150		0.18	0.08	0.18	3.0	1070	21.4	27.3	<0.001	0.01	0.45	2.0	0.2	1.8	214	<0.01
I102151		0.33	0.05	0.25	3.5	990	25.0	32.7	<0.001	0.01	0.54	2.9	0.2	2.2	187.0	<0.01
I102152		0.41	0.04	0.55	3.3	980	24.8	34.7	<0.001	0.01	0.57	2.5	0.2	2.1	62.8	<0.01
I102153		0.73	0.07	0.64	3.5	980	23.6	37.8	<0.001	<0.01	0.78	2.9	0.2	2.5	87.0	<0.01
I102154		0.36	0.03	0.17	2.8	950	22.8	25.4	<0.001	<0.01	0.92	3.0	0.2	2.5	130.0	<0.01
I102155		0.54	0.05	0.48	3.0	880	25.5	30.5	<0.001	<0.01	0.60	2.7	0.2	2.3	278	<0.01
I102156		0.57	0.03	0.29	2.9	800	24.3	25.2	<0.001	<0.01	0.48	2.2	0.2	1.9	50.2	<0.01
I102157		0.48	0.04	0.36	3.1	760	26.0	29.1	<0.001	<0.01	0.60	2.9	0.2	2.2	58.6	<0.01
I102158		0.35	0.02	0.21	3.1	690	33.3	27.7	<0.001	0.01	0.54	2.6	0.2	1.8	82.2	<0.01
I102159		0.39	0.02	0.30	3.1	630	32.7	26.3	<0.001	<0.01	0.45	2.8	0.2	2.0	228	<0.01
I102160		0.34	0.02	0.24	2.9	620	30.1	23.9	<0.001	<0.01	0.38	2.3	<0.2	1.7	217	0.01

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Te	Th	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102121		0.44	34.6	0.117	0.29	9.97	54	0.60	12.80	78	2.2
I102122		0.43	31.8	0.115	0.29	9.84	52	0.60	11.95	261	2.1
I102123		0.65	26.9	0.034	0.37	9.04	52	0.85	15.90	135	2.1
I102124		2.93	34.2	0.021	0.48	12.20	33	3.68	12.35	98	1.8
I102125		0.25	30.8	0.034	0.45	7.24	58	0.49	18.95	96	1.9
I102126		8.71	34.5	0.011	0.25	8.10	27	1.80	11.75	73	1.8
I102127		0.43	31.7	0.017	0.41	14.35	28	13.60	10.30	66	2.4
I102128		0.04	35.3	0.097	0.17	15.15	44	0.95	11.70	50	3.4
I102129		0.28	40.4	0.157	0.27	15.05	56	1.08	15.55	66	5.0
I102130		0.02	34.3	0.140	0.23	12.00	48	0.86	13.05	57	3.5
I102131		40.6	3.7	0.152	0.12	1.88	30	56.2	8.13	80	16.8
I102132		0.16	43.0	0.126	0.34	13.90	64	1.28	17.60	87	4.0
I102133		0.23	7.7	0.014	0.12	1.25	56	0.18	7.06	148	3.8
I102134		0.08	36.4	0.018	0.14	5.55	31	0.56	12.20	83	1.7
I102135		0.13	28.9	0.034	0.18	5.23	48	0.44	13.55	79	2.6
I102136		0.22	6.4	0.098	0.18	1.44	58	0.37	6.46	115	6.6
I102137		0.02	6.6	0.088	0.06	1.29	54	0.58	5.87	89	7.1
I102138		0.04	17.9	0.093	0.11	5.47	46	0.56	8.61	64	2.2
I102139		0.24	19.9	0.088	0.22	6.89	51	0.46	10.60	75	2.0
I102140		<0.01	32.1	0.139	0.30	10.45	49	0.63	13.85	35	3.4
I102141		0.05	26.3	0.051	0.24	7.80	46	0.62	12.95	58	2.8
I102142		0.04	18.4	0.097	0.24	6.70	47	0.56	9.84	62	2.0
I102143		0.18	14.0	0.050	0.20	3.36	44	0.54	9.50	71	1.7
I102144		0.01	15.5	0.143	0.25	4.54	48	0.96	9.41	56	2.2
I102145		<0.01	13.8	0.167	0.24	4.11	50	3.03	9.02	52	2.9
I102146		0.01	15.0	0.123	0.22	4.82	50	1.61	8.92	52	2.1
I102147		0.01	14.1	0.123	0.36	3.99	52	0.56	9.76	65	2.1
I102148		<0.01	13.7	0.130	0.33	3.43	51	0.41	8.13	55	1.9
I102149		<0.01	12.9	0.063	0.26	3.35	43	0.75	8.19	48	1.7
I102150		<0.01	13.5	0.054	0.25	3.23	44	0.90	8.22	47	1.6
I102151		<0.01	17.0	0.079	0.32	4.26	46	0.34	9.93	50	2.4
I102152		<0.01	17.5	0.109	0.32	5.70	47	0.31	9.21	53	2.2
I102153		<0.01	20.2	0.120	0.32	6.88	49	0.45	11.40	45	2.9
I102154		<0.01	20.5	0.031	0.24	6.48	40	0.96	13.30	47	1.7
I102155		<0.01	18.8	0.119	0.24	5.80	47	0.38	9.92	44	2.7
I102156		<0.01	19.5	0.075	0.20	5.17	43	0.32	9.45	44	2.4
I102157		<0.01	23.3	0.095	0.24	6.90	44	0.38	11.45	48	3.2
I102158		0.01	26.8	0.038	0.23	7.04	36	0.33	11.00	48	1.5
I102159		0.01	27.6	0.048	0.22	6.17	39	0.27	11.05	48	2.0
I102160		<0.01	27.0	0.040	0.21	6.03	37	0.21	9.93	45	1.5

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-AA23 Au Check ppm 0.005	Au-GRA21 Au ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02
I102161		0.84	<0.005			0.10	2.05	4.8	<0.2	<10	110	2.55	6.68	1.37	0.22	44.1
I102162		1.80	<0.005			0.20	1.52	8.9	<0.2	<10	220	1.54	1.91	0.68	0.19	47.9
I102163		3.64	<0.005			0.11	1.21	8.4	<0.2	<10	110	0.90	1.23	0.60	0.26	47.3
I102164		2.05	<0.005			0.06	1.16	7.0	<0.2	<10	100	1.00	1.36	0.58	0.23	52.1
I102165		4.71	<0.005			0.08	1.07	9.6	<0.2	<10	110	0.62	0.69	0.53	0.27	52.0
I102166		3.33	<0.005			0.07	1.04	7.8	<0.2	<10	90	0.67	0.35	0.46	0.22	52.8
I102167		4.54	<0.005			0.10	1.00	6.8	<0.2	<10	100	0.68	0.46	0.45	0.18	53.6
I102168		3.45	<0.005			0.07	1.19	6.9	<0.2	<10	90	1.07	0.53	0.48	0.28	53.1
I102169		3.63	0.005			0.12	0.99	6.0	<0.2	<10	90	0.90	6.11	0.43	0.33	65.8
I102170		0.04	0.285			9.32	0.52	8.1	0.3	<10	180	0.21	1.64	2.48	0.14	12.05
I102171		4.32	0.005			0.11	0.90	5.7	<0.2	<10	70	0.81	7.40	0.75	0.33	42.6
I102172		3.90	1.225	0.150	0.25	0.20	1.10	5.9	<0.2	<10	100	0.84	8.10	0.50	0.35	51.5
I102173		3.20	<0.005			0.09	0.85	4.0	<0.2	<10	80	0.78	0.42	0.45	0.14	51.7
I102174		4.45	<0.005			0.12	1.00	4.7	<0.2	<10	100	0.66	0.38	0.49	0.17	50.2
I102175		3.81	<0.005			0.09	1.69	4.0	<0.2	<10	200	1.56	0.96	1.10	0.20	53.3
I102176		3.89	<0.005			0.17	1.59	4.6	<0.2	<10	200	1.36	0.84	1.02	0.29	55.2
I102177		4.15	<0.005			0.12	1.29	4.2	<0.2	<10	130	1.23	0.36	1.17	0.21	52.5
I102178		4.42	<0.005			0.17	1.38	4.5	<0.2	<10	120	1.28	0.71	1.19	0.22	49.3
I102179		4.39	0.007			0.15	1.16	4.3	<0.2	<10	90	0.93	0.52	0.62	0.20	52.1
I102180		1.09	<0.005			0.08	0.80	4.9	<0.2	<10	110	0.67	0.32	0.34	0.13	36.9
I102181		1.00	<0.005			0.16	1.45	4.2	<0.2	<10	100	1.31	0.46	0.89	0.27	50.5
I102182		4.65	<0.005			0.27	2.11	3.9	<0.2	<10	90	2.07	3.88	1.04	0.77	53.8
I102183		1.72	0.009			0.25	0.89	3.7	<0.2	10	30	1.03	5.01	0.57	0.74	83.3
I102184		2.25	0.021			0.82	1.18	7.9	<0.2	10	90	1.06	13.95	0.43	0.68	53.3
I102185		1.44	0.010			0.34	1.66	85.6	<0.2	<10	90	3.20	24.5	0.67	1.43	59.6
I102186		1.70	<0.005			0.39	2.10	26.7	<0.2	<10	120	2.16	4.22	0.62	0.54	52.7
I102187		2.15	0.022			0.91	1.33	19.1	<0.2	<10	80	1.81	131.0	0.53	0.56	52.6
I102188		2.10	0.005			0.47	1.54	5.3	<0.2	<10	60	1.64	2.34	0.53	0.45	61.9
I102189		1.26	0.005			0.29	1.20	5.6	<0.2	<10	50	1.75	2.41	0.43	1.01	65.6
I102190		1.19	0.007			0.35	1.32	5.7	<0.2	10	50	1.81	3.46	0.40	1.17	69.7
I102191		2.98	<0.005			0.21	1.19	3.9	<0.2	<10	100	0.97	1.72	0.40	1.97	56.9
I102192		4.67	<0.005			0.21	2.14	4.5	<0.2	<10	60	2.27	2.22	0.77	1.04	54.6
I102193		4.61	<0.005			0.24	1.87	4.7	<0.2	<10	70	2.09	2.75	0.71	0.47	53.7
I102194		5.25	<0.005			0.25	2.02	7.2	<0.2	<10	80	1.94	2.28	0.67	0.65	53.2
I102195		4.87	<0.005			0.14	1.28	4.4	<0.2	<10	90	0.98	0.89	0.52	0.41	47.7
I102196		1.72	0.018			0.22	1.14	12.0	<0.2	<10	60	1.08	1.01	0.35	0.48	58.9
I102197		1.79	0.006			0.24	1.98	8.9	<0.2	<10	180	2.29	2.26	0.65	0.50	77.2
I102198		2.55	0.005			0.55	1.80	21.4	<0.2	<10	250	2.81	1.39	0.45	0.70	77.6
I102199		1.88	0.006			0.11	0.89	11.3	<0.2	20	30	1.11	1.03	0.38	0.14	56.8
I102200		<0.02	0.006			0.11	0.74	11.9	<0.2	10	20	1.22	1.03	0.39	0.15	55.6

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Co	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn
	Units	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm
	LOR	0.1	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5
I102161		3.9	8	5.36	11.1	3.34	6.44	0.07	0.07	0.01	0.037	0.23	22.4	12.9	0.64	567
I102162		6.2	8	9.78	36.3	2.03	4.96	0.07	0.09	0.01	0.043	0.26	25.1	14.7	0.52	372
I102163		5.3	12	5.89	4.4	2.27	5.55	0.11	0.16	<0.01	0.048	0.33	23.9	20.2	0.63	368
I102164		3.8	13	4.50	3.1	2.11	4.97	0.09	0.13	<0.01	0.043	0.30	26.2	16.9	0.55	310
I102165		6.0	15	4.54	4.8	2.28	5.36	0.13	0.15	<0.01	0.053	0.34	26.4	21.2	0.60	350
I102166		3.6	14	5.09	2.2	2.32	4.84	0.11	0.14	<0.01	0.043	0.34	26.4	21.9	0.58	421
I102167		3.7	15	5.53	3.2	2.29	4.89	0.11	0.15	<0.01	0.042	0.37	26.7	20.9	0.55	446
I102168		4.2	14	5.19	2.8	2.37	5.41	0.10	0.15	<0.01	0.039	0.34	27.3	21.3	0.65	470
I102169		4.4	13	4.10	45.1	2.36	4.65	0.10	0.32	<0.01	0.053	0.35	33.7	17.2	0.49	551
I102170		3.9	7	0.90	6270	1.51	1.69	<0.05	0.04	0.79	0.022	0.26	5.8	1.9	0.11	425
I102171		7.3	14	4.98	29.4	2.72	4.97	0.10	0.20	<0.01	0.037	0.31	21.2	19.2	0.55	540
I102172		5.1	14	5.39	16.5	2.55	5.54	0.10	0.14	<0.01	0.067	0.38	25.5	19.0	0.57	525
I102173		3.8	15	4.28	4.2	2.07	4.43	0.09	0.18	<0.01	0.018	0.33	25.1	15.7	0.45	448
I102174		3.8	16	4.51	3.1	2.10	4.79	0.10	0.17	<0.01	0.016	0.36	24.6	18.2	0.48	533
I102175		4.2	13	6.79	3.0	2.03	5.80	0.08	0.13	0.01	0.023	0.33	25.9	18.4	0.57	515
I102176		4.6	13	6.25	8.5	2.13	6.07	0.08	0.18	<0.01	0.025	0.37	27.6	19.6	0.56	521
I102177		4.3	13	5.36	3.3	1.98	5.30	0.08	0.14	<0.01	0.024	0.30	26.2	19.4	0.52	576
I102178		5.0	14	5.07	4.7	2.19	5.92	0.10	0.15	<0.01	0.043	0.35	24.0	22.5	0.57	522
I102179		3.9	14	6.38	3.1	2.13	5.07	0.10	0.16	<0.01	0.022	0.34	25.6	20.5	0.52	396
I102180		3.7	15	6.04	3.3	2.15	4.35	0.10	0.21	<0.01	0.019	0.40	16.3	34.2	0.42	275
I102181		3.8	14	6.78	3.1	2.18	5.73	0.08	0.14	<0.01	0.025	0.36	24.5	20.6	0.60	454
I102182		4.7	14	5.82	33.0	2.57	7.36	0.07	0.12	<0.01	0.122	0.33	26.5	18.7	0.73	626
I102183		1.9	4	3.42	17.1	1.64	2.12	0.09	0.06	<0.01	0.038	0.14	44.5	3.4	0.17	326
I102184		5.3	12	7.89	91.1	2.76	5.50	0.10	0.15	<0.01	0.408	0.46	25.3	18.3	0.58	454
I102185		8.0	6	8.64	153.0	3.87	5.18	0.09	0.10	<0.01	0.137	0.25	33.5	9.5	0.45	443
I102186		4.9	8	6.87	30.2	2.31	6.07	0.06	0.10	<0.01	0.064	0.35	23.4	13.8	0.57	362
I102187		4.2	5	7.05	56.7	2.74	3.98	0.08	0.08	<0.01	0.036	0.24	24.5	7.4	0.39	463
I102188		3.4	7	10.00	24.7	2.57	4.53	0.09	0.12	<0.01	0.063	0.32	35.0	8.7	0.37	408
I102189		4.8	8	5.92	20.4	2.45	4.21	0.08	0.10	<0.01	0.062	0.22	31.6	9.3	0.45	676
I102190		4.5	10	5.23	26.5	2.60	4.95	0.09	0.12	<0.01	0.083	0.28	32.1	11.1	0.47	785
I102191		4.2	16	8.48	15.0	2.86	6.29	0.11	0.15	<0.01	0.467	0.47	28.0	20.9	0.75	602
I102192		4.5	12	6.31	15.2	2.70	6.98	0.08	0.10	<0.01	0.108	0.27	28.7	15.5	0.76	962
I102193		5.9	11	5.39	37.1	2.65	6.48	0.07	0.08	<0.01	0.063	0.27	26.2	16.5	0.70	711
I102194		4.6	13	4.84	29.0	2.49	6.70	0.08	0.14	<0.01	0.057	0.31	27.8	15.6	0.67	837
I102195		4.0	14	5.60	8.9	2.13	5.60	0.09	0.13	<0.01	0.033	0.32	23.1	15.2	0.57	931
I102196		9.7	7	9.85	6.4	3.27	4.60	0.07	0.07	0.01	0.076	0.33	31.4	7.6	0.17	2920
I102197		5.4	11	10.65	11.5	2.39	7.00	0.10	0.11	<0.01	0.056	0.23	47.3	14.5	0.49	4380
I102198		9.1	9	18.25	20.5	4.60	6.93	0.10	0.15	<0.01	0.045	0.24	32.5	23.6	0.25	9700
I102199		4.9	3	13.60	13.0	2.33	2.83	0.06	0.07	<0.01	0.026	0.18	26.2	2.4	0.14	577
I102200		5.2	2	12.10	16.4	2.33	2.46	0.06	0.06	<0.01	0.026	0.14	25.3	2.1	0.13	584

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Mo	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01
I102161		0.32	0.02	0.19	2.9	690	26.5	27.2	<0.001	<0.01	0.45	2.2	0.2	2.3	244	<0.01
I102162		1.68	0.02	0.41	3.5	740	32.9	33.6	<0.001	0.11	0.77	2.5	0.2	3.2	46.0	<0.01
I102163		1.99	0.07	0.93	3.4	710	32.8	39.7	<0.001	0.06	0.76	2.4	0.2	2.6	51.0	0.01
I102164		0.90	0.04	0.90	3.2	710	28.2	35.5	<0.001	0.01	0.57	2.3	0.2	2.2	75.2	0.01
I102165		0.49	0.08	1.20	3.7	730	35.0	38.5	<0.001	<0.01	0.74	2.7	0.2	2.8	58.8	0.01
I102166		0.44	0.06	1.20	3.6	740	31.2	41.3	<0.001	<0.01	0.63	2.4	0.2	2.5	43.2	0.01
I102167		0.66	0.07	1.43	3.5	720	35.6	43.3	<0.001	<0.01	0.72	2.5	0.2	2.4	32.1	0.01
I102168		1.54	0.05	0.88	3.7	740	33.5	42.9	<0.001	<0.01	0.56	2.6	0.2	2.3	36.5	0.01
I102169		2.48	0.06	0.82	4.0	710	38.0	36.8	<0.001	<0.01	0.80	2.8	0.2	1.6	29.2	0.01
I102170		150.5	0.03	<0.05	4.3	400	18.2	6.6	0.035	1.50	14.00	0.7	0.5	0.3	361	<0.01
I102171		1.14	0.05	1.01	4.3	760	49.8	38.8	<0.001	0.01	0.74	2.5	0.2	1.6	25.5	0.01
I102172		1.28	0.07	0.98	3.9	760	58.8	43.7	<0.001	0.01	0.71	2.9	0.2	2.8	44.9	0.01
I102173		1.41	0.05	1.41	3.5	780	40.3	38.3	<0.001	0.01	0.63	2.2	0.3	1.6	26.6	<0.01
I102174		1.20	0.08	1.16	3.5	840	44.6	37.0	<0.001	0.01	0.53	1.9	0.3	1.6	48.5	<0.01
I102175		0.93	0.06	0.57	3.5	780	49.1	38.2	<0.001	0.01	0.47	2.6	0.2	1.6	403	<0.01
I102176		1.05	0.08	0.76	3.7	760	65.8	42.3	<0.001	0.01	0.63	2.8	0.3	1.7	377	0.01
I102177		0.73	0.05	0.74	3.3	750	51.8	37.3	<0.001	0.01	0.59	2.3	0.3	1.7	260	0.01
I102178		0.99	0.07	0.78	3.7	780	62.8	42.1	<0.001	0.01	0.64	2.7	0.3	1.9	177.5	0.01
I102179		1.35	0.05	1.03	3.6	800	54.5	42.7	<0.001	<0.01	0.49	2.0	0.3	1.8	73.0	<0.01
I102180		2.18	0.10	2.90	4.5	770	21.2	50.7	<0.001	0.01	0.39	2.7	0.3	2.4	19.5	0.01
I102181		1.18	0.05	0.74	3.7	810	59.6	41.6	<0.001	0.01	0.55	2.3	0.3	1.7	139.5	0.01
I102182		0.67	0.04	0.35	4.1	790	70.3	39.4	<0.001	0.01	0.50	4.1	0.2	1.8	124.5	<0.01
I102183		0.59	0.03	0.07	1.8	830	40.9	18.0	<0.001	0.01	0.51	0.7	0.2	0.5	41.0	<0.01
I102184		1.64	0.07	0.84	3.8	750	98.5	62.2	<0.001	0.01	1.07	4.0	0.4	1.8	42.2	<0.01
I102185		1.67	0.02	0.17	3.2	780	52.8	34.8	<0.001	0.01	2.09	1.9	0.6	1.3	185.5	<0.01
I102186		1.93	0.02	0.14	2.9	810	38.0	43.4	<0.001	0.01	0.57	2.5	0.4	1.1	218	<0.01
I102187		1.73	0.02	0.10	2.9	780	175.5	30.4	<0.001	0.01	0.77	1.4	0.5	1.4	111.0	<0.01
I102188		0.65	0.02	0.13	2.6	840	74.6	41.2	<0.001	0.01	1.11	1.9	0.3	3.1	59.3	<0.01
I102189		1.10	0.02	0.11	3.1	780	69.5	29.1	<0.001	0.01	0.56	1.9	0.4	2.0	43.4	<0.01
I102190		1.45	0.04	0.11	3.2	810	93.3	36.2	<0.001	0.01	0.63	2.1	0.3	1.8	37.1	<0.01
I102191		1.77	0.05	0.86	4.3	830	50.7	59.3	<0.001	0.01	0.71	4.8	0.3	2.3	68.6	<0.01
I102192		0.47	0.03	0.19	3.4	870	69.9	34.6	<0.001	0.01	0.60	3.4	0.3	1.7	71.0	<0.01
I102193		0.63	0.02	0.19	3.5	1220	48.6	35.7	<0.001	0.01	0.51	3.1	0.2	1.6	83.9	<0.01
I102194		0.66	0.04	0.27	3.7	820	49.3	35.4	<0.001	0.01	0.64	3.2	0.3	1.5	102.5	0.01
I102195		1.20	0.05	0.77	3.5	780	49.3	40.3	<0.001	0.01	0.61	2.2	0.3	1.8	89.8	0.01
I102196		3.83	0.01	0.11	2.7	800	21.7	46.2	<0.001	<0.01	2.20	2.2	0.3	7.2	89.3	<0.01
I102197		1.24	0.01	0.13	3.5	880	49.7	30.4	<0.001	0.01	2.36	5.4	0.4	2.0	223	0.01
I102198		3.31	0.01	0.12	4.5	910	86.9	35.9	<0.001	0.01	1.55	4.2	0.3	1.8	246	<0.01
I102199		1.53	0.01	<0.05	1.8	830	16.4	26.0	<0.001	<0.01	1.35	0.6	0.2	1.4	26.3	<0.01
I102200		1.54	0.01	<0.05	4.2	850	18.0	21.3	<0.001	0.01	1.22	0.5	0.2	1.1	24.5	<0.01

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Te	Th	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102161		0.01	24.2	0.026	0.31	5.35	34	0.23	11.00	46	1.4
I102162		0.03	27.2	0.063	0.31	8.50	30	0.34	10.35	47	1.9
I102163		<0.01	26.2	0.134	0.33	9.94	46	0.68	11.60	54	2.7
I102164		<0.01	27.8	0.119	0.26	9.77	47	0.45	11.30	46	2.3
I102165		0.01	25.8	0.153	0.29	10.95	50	0.59	11.95	55	2.6
I102166		<0.01	27.4	0.147	0.32	11.00	52	0.59	11.95	59	2.3
I102167		<0.01	27.4	0.149	0.34	10.65	51	0.61	12.40	64	2.4
I102168		<0.01	30.5	0.123	0.34	10.45	51	0.47	12.70	65	2.5
I102169		0.01	32.1	0.096	0.33	10.85	38	0.51	12.85	78	8.0
I102170		1.94	1.1	<0.005	0.04	0.88	12	4.49	4.35	40	1.5
I102171		0.02	29.8	0.114	0.32	11.85	45	1.03	12.50	82	4.0
I102172		0.06	28.4	0.134	0.42	10.85	49	1.39	12.75	119	2.3
I102173		0.01	32.5	0.133	0.28	14.00	52	0.60	13.30	57	3.1
I102174		0.01	30.2	0.151	0.27	13.30	54	0.51	13.15	64	2.9
I102175		0.02	28.3	0.111	0.26	8.30	52	0.34	12.45	62	2.3
I102176		0.01	32.7	0.131	0.31	11.55	51	0.48	14.25	62	3.0
I102177		<0.01	29.0	0.120	0.27	10.55	52	0.41	12.85	65	2.4
I102178		0.01	26.8	0.140	0.31	10.40	54	0.52	12.85	69	2.5
I102179		<0.01	28.7	0.144	0.31	11.55	53	0.53	12.70	67	2.8
I102180		<0.01	28.1	0.170	0.33	10.15	54	0.79	15.35	36	3.4
I102181		0.01	28.4	0.134	0.30	12.55	57	0.41	12.90	68	2.5
I102182		0.05	26.8	0.096	0.36	7.70	53	0.34	13.15	104	2.4
I102183		0.08	27.7	0.006	0.17	5.07	7	0.65	10.60	43	1.5
I102184		0.12	29.9	0.107	0.58	10.45	44	0.90	13.05	381	2.8
I102185		0.22	28.2	0.028	0.32	11.00	24	0.87	14.10	233	2.2
I102186		0.08	29.7	0.044	0.45	11.15	28	0.17	9.81	59	2.4
I102187		0.38	27.6	0.022	0.28	9.16	16	0.49	10.35	93	1.7
I102188		0.08	27.3	0.027	0.40	6.06	23	2.51	12.00	62	3.4
I102189		0.13	31.2	0.025	0.28	7.63	26	1.85	13.70	79	2.4
I102190		0.13	31.8	0.025	0.37	7.63	30	1.49	14.50	101	2.7
I102191		0.03	31.0	0.131	0.59	9.75	58	0.60	15.75	644	2.6
I102192		0.06	27.6	0.044	0.32	5.98	43	1.19	14.85	221	2.5
I102193		0.04	28.5	0.037	0.31	10.05	40	0.60	13.00	97	2.0
I102194		0.04	30.3	0.073	0.32	7.94	46	0.40	14.15	122	2.9
I102195		0.01	29.6	0.129	0.30	9.77	51	0.58	12.45	89	2.3
I102196		0.04	23.0	0.012	0.57	14.95	28	2.94	11.45	86	2.0
I102197		0.04	29.8	0.039	0.32	9.25	44	1.05	17.60	91	2.7
I102198		0.04	30.4	0.030	0.65	16.20	40	0.52	14.70	101	3.4
I102199		0.04	26.3	<0.005	0.27	12.55	7	0.64	10.05	24	1.9
I102200		0.04	25.9	<0.005	0.21	12.30	6	0.70	10.15	31	1.6

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	WEI-21	Au-AA23	Au-AA23	Au-GRA21	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Recvd Wt.	Au	Au Check	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce
	Units	kg	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.02	0.005	0.005	0.05	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02
I102201		2.25	<0.005			0.10	0.93	5.5	<0.2	10	30	1.34	0.53	0.50	0.22	77.1
I102202		2.20	0.006			0.41	1.17	8.3	<0.2	10	80	1.04	2.98	0.34	0.39	59.7
I102203		1.60	0.010			0.28	1.30	10.1	<0.2	<10	60	1.10	3.34	0.43	0.34	41.8
I102204		4.07	0.005			0.36	1.23	8.8	<0.2	<10	90	0.78	2.84	0.63	0.56	48.8
I102205		2.07	<0.005			0.47	0.90	11.4	<0.2	<10	80	0.72	2.74	0.55	0.41	48.1
I102206		4.72	<0.005			0.21	0.85	4.5	<0.2	<10	100	0.63	1.04	0.44	0.42	50.2
I102207		2.35	0.005			0.32	0.60	13.4	<0.2	<10	80	0.73	3.43	0.33	2.55	38.7
I102208		2.52	<0.005			0.18	0.85	7.7	<0.2	<10	110	0.50	1.22	0.41	0.43	46.5

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Co	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn
	Units	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm
	LOR	0.1	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5
I102201		2.1	4	2.90	10.8	1.62	2.79	0.07	0.10	<0.01	0.017	0.14	36.3	6.0	0.28	690
I102202		8.3	11	8.04	109.5	2.85	5.31	0.09	0.13	<0.01	0.068	0.43	28.6	17.1	0.55	681
I102203		7.4	14	7.28	199.0	3.18	6.58	0.08	0.11	<0.01	0.065	0.34	20.8	22.0	0.74	592
I102204		10.1	15	9.98	117.0	2.82	5.98	0.11	0.14	<0.01	0.058	0.52	24.6	26.6	0.77	517
I102205		12.8	12	8.96	79.8	2.83	4.51	0.11	0.17	0.01	0.049	0.36	23.7	16.6	0.50	485
I102206		5.3	15	6.47	18.5	2.14	4.61	0.11	0.21	<0.01	0.027	0.42	25.1	15.0	0.46	369
I102207		8.3	12	5.50	162.5	2.05	4.16	0.11	0.17	<0.01	0.054	0.25	20.0	14.7	0.39	288
I102208		4.8	14	6.35	20.1	2.00	4.99	0.13	0.19	<0.01	0.030	0.37	23.7	20.4	0.49	347

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Mo	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01
I102201		2.63	0.02	0.07	1.8	850	25.2	16.9	<0.001	0.01	0.45	0.8	0.2	0.8	31.1	<0.01
I102202		2.37	0.06	0.54	4.0	790	45.2	54.9	<0.001	0.04	0.94	3.2	0.4	1.7	43.6	<0.01
I102203		1.12	0.04	0.57	4.4	820	49.7	42.1	<0.001	0.01	0.61	4.0	0.3	2.1	35.3	<0.01
I102204		3.68	0.08	1.48	4.2	780	63.1	69.2	<0.001	0.05	0.93	4.9	0.8	3.3	32.8	0.01
I102205		8.78	0.05	1.23	3.7	770	55.4	48.2	<0.001	0.03	0.87	2.6	0.4	11.9	25.5	0.01
I102206		3.45	0.12	1.91	3.4	770	55.5	49.5	<0.001	0.01	0.54	2.3	0.3	2.2	25.2	0.01
I102207		1.78	0.05	1.82	3.1	750	95.3	37.7	<0.001	0.01	0.72	1.7	0.3	1.9	17.8	0.01
I102208		1.63	0.09	1.60	3.3	750	47.6	48.2	<0.001	<0.01	0.65	2.2	0.4	2.3	36.8	0.01

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Te	Th	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102201		0.01	30.0	0.009	0.18	5.59	10	0.27	12.45	26	2.5
I102202		0.05	30.0	0.079	0.57	10.80	39	1.61	13.35	95	2.7
I102203		0.06	28.5	0.099	0.48	8.99	49	0.67	11.70	88	2.1
I102204		0.07	28.4	0.171	0.67	11.90	53	0.83	13.60	99	2.4
I102205		0.07	27.5	0.131	0.43	10.70	44	5.43	12.55	78	3.0
I102206		0.01	31.6	0.154	0.38	16.65	53	0.98	13.95	70	3.4
I102207		0.06	27.0	0.113	0.24	13.05	39	0.89	11.20	186	3.1
I102208		0.02	30.7	0.146	0.29	12.40	50	1.00	13.60	63	3.1

Comments: Additional Au-AA23 check results for sample I102172 report 3.79ppm and 2.11ppm.

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127718

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

CERTIFICATE WH10127714

Project: SQI10-01

P.O. No.: SQI10-01_9

This report is for 74 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 17-SEP-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127714

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1
I102001		2.09	<0.005		0.38	1.00	4.5	<0.2	<10	60	0.75	0.90	0.63	0.32	41.7	6.0
I102002		4.42	<0.005		0.16	1.01	4.2	<0.2	<10	70	0.77	0.19	0.57	0.38	42.9	5.4
I102003		4.12	<0.005		0.57	1.33	13.2	<0.2	<10	40	1.85	0.94	1.46	1.58	62.6	12.9
I102004		4.48	<0.005		0.24	0.93	7.3	<0.2	10	40	1.19	0.34	1.84	1.23	54.1	9.0
I102005		3.09	<0.005		1.24	0.91	13.4	<0.2	10	40	1.13	1.97	1.23	6.53	54.9	6.8
I102006		0.71	<0.005		4.24	0.46	6.2	<0.2	10	30	0.83	7.19	1.69	11.15	63.8	1.2
I102007		3.79	<0.005		1.01	0.47	7.5	<0.2	10	40	0.92	1.58	2.12	2.44	54.9	4.7
I102008		4.55	<0.005		0.44	0.86	5.4	<0.2	<10	40	1.53	0.64	1.77	0.79	44.9	9.7
I102009		1.75	<0.005		3.70	0.87	14.3	<0.2	<10	40	1.17	6.65	1.29	2.21	47.7	6.2
I102010		0.03	2.76	2.58	2.24	1.68	533	2.7	30	130	0.42	244	9.27	0.61	27.6	29.8
I102011		2.29	<0.005		0.12	0.85	3.0	<0.2	<10	80	0.59	0.58	0.51	0.22	39.2	4.8
I102012		4.71	<0.005		0.24	0.91	3.7	<0.2	<10	90	0.60	0.57	0.54	0.53	40.1	4.7
I102013		4.51	<0.005		0.18	0.79	4.3	<0.2	<10	80	0.53	0.29	0.58	0.29	36.7	6.9
I102014		4.47	<0.005		0.14	0.69	3.1	<0.2	<10	80	0.44	0.19	0.45	0.35	40.9	4.8
I102015		1.96	<0.005		0.19	0.83	2.5	<0.2	<10	90	0.54	0.27	0.43	0.43	39.8	4.6
I102016		2.15	<0.005		0.29	0.83	2.7	<0.2	<10	70	0.66	1.73	0.57	0.30	39.7	4.8
I102017		3.88	<0.005		0.59	1.10	6.2	<0.2	<10	60	1.26	1.33	0.87	1.23	50.5	5.6
I102018		4.02	<0.005		0.26	1.02	3.2	<0.2	<10	80	0.95	0.46	0.63	0.48	44.0	5.7
I102019		4.22	<0.005		0.20	0.90	2.4	<0.2	<10	90	0.82	0.29	0.49	0.26	45.2	5.5
I102020		0.94	<0.005		0.05	0.71	4.5	<0.2	<10	100	0.56	0.30	0.27	0.17	29.8	3.4
I102021		3.63	<0.005		0.08	1.01	2.4	<0.2	<10	90	1.09	0.21	0.76	0.14	46.5	5.2
I102022		2.92	<0.005		0.11	1.30	1.9	<0.2	<10	130	1.69	0.22	0.72	0.14	41.8	5.3
I102023		2.06	<0.005		0.16	1.22	4.9	<0.2	<10	70	2.01	0.22	2.23	0.27	53.0	5.4
I102024		3.05	<0.005		0.35	1.28	8.8	<0.2	<10	90	1.98	0.54	1.16	1.09	49.8	5.8
I102025		1.83	0.005		0.54	0.89	26.4	<0.2	<10	70	1.60	0.36	1.04	0.66	45.0	5.5
I102026		4.07	<0.005		0.17	0.91	2.1	<0.2	<10	90	0.72	0.24	0.60	0.30	44.2	5.7
I102027		4.30	<0.005		0.20	0.87	1.8	<0.2	<10	90	0.64	0.33	0.48	0.35	41.8	5.2
I102028		3.21	<0.005		0.23	1.19	2.9	<0.2	<10	100	1.50	0.50	1.12	1.50	41.9	5.9
I102029		2.18	<0.005		0.12	0.93	1.9	<0.2	<10	100	0.74	0.18	0.49	0.18	42.5	5.6
I102030		1.88	<0.005		0.12	0.93	2.0	<0.2	<10	100	0.74	0.17	0.47	0.16	42.0	5.7
I102031		3.15	<0.005		0.16	0.88	1.9	<0.2	<10	90	0.68	0.23	0.79	0.40	39.8	5.2
I102032		3.55	<0.005		0.11	1.13	1.9	<0.2	<10	90	1.40	0.24	0.96	0.16	42.3	5.1
I102033		3.25	<0.005		0.14	0.77	1.9	<0.2	<10	80	0.83	0.27	0.50	0.16	43.9	4.6
I102034		2.54	<0.005		0.22	1.76	3.1	<0.2	<10	50	3.01	0.61	2.05	0.24	51.1	4.8
I102035		2.04	<0.005		0.58	1.41	1.8	<0.2	<10	60	2.07	3.71	0.54	0.18	47.6	4.8
I102036		1.53	0.085		0.94	0.79	87.0	<0.2	<10	30	1.87	11.15	0.34	0.41	49.2	33.7
I102037		3.27	0.016		1.62	1.51	5.5	<0.2	<10	50	2.19	24.5	0.56	0.37	55.8	9.8
I102038		3.24	<0.005		0.43	2.24	2.4	<0.2	<10	130	2.82	3.34	0.79	0.31	46.3	5.9
I102039		3.66	0.016		1.34	1.18	18.6	<0.2	10	60	1.57	10.05	0.40	0.23	56.7	15.6
I102040C		<0.02	0.022		1.25	1.15	20.9	<0.2	<10	50	1.53	10.30	0.41	0.24	57.1	15.1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127714

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo
	Units	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm
	LOR	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05
I102001		17	2.91	13.3	2.27	4.90	0.09	0.19	<0.01	0.024	0.19	20.9	16.0	0.61	941	4.14
I102002		17	3.44	16.0	2.28	4.92	0.08	0.18	<0.01	0.015	0.22	21.7	15.4	0.63	552	3.51
I102003		5	7.38	11.6	2.09	3.00	0.05	0.21	<0.01	0.090	0.33	34.8	16.8	0.37	1570	2.44
I102004		4	7.33	1.7	1.81	2.16	<0.05	0.29	<0.01	0.075	0.34	30.5	8.4	0.52	2180	3.46
I102005		3	9.16	5.3	2.44	2.71	0.05	0.29	0.01	0.094	0.38	31.5	6.6	0.45	2830	3.86
I102006		3	7.88	32.5	1.68	1.31	<0.05	0.35	0.01	0.202	0.31	36.2	1.9	0.11	3240	3.12
I102007		4	7.40	15.4	1.76	1.24	<0.05	0.32	<0.01	0.094	0.34	30.9	2.3	0.46	2580	2.71
I102008		5	7.25	7.3	2.08	1.70	<0.05	0.33	<0.01	0.094	0.31	25.6	6.6	0.55	1920	2.32
I102009		9	8.73	95.4	2.39	3.35	0.05	0.17	0.01	0.088	0.24	25.4	11.8	0.34	1420	3.24
I102010		51	1.50	292	5.08	6.62	0.22	0.41	4.86	1.415	0.16	14.2	7.6	0.26	863	74.4
I102011		15	3.31	11.3	2.06	4.49	0.08	0.16	0.01	0.011	0.27	20.0	12.2	0.55	404	3.28
I102012		16	3.78	11.4	2.13	4.60	0.09	0.16	<0.01	0.025	0.26	20.4	12.9	0.56	474	4.11
I102013		15	7.73	8.2	2.09	4.15	0.09	0.15	0.01	0.011	0.24	18.7	12.0	0.50	391	4.21
I102014		16	7.92	11.9	2.04	3.92	0.09	0.15	0.01	0.012	0.30	20.7	11.8	0.46	435	5.91
I102015		17	6.06	18.5	2.26	4.31	0.09	0.14	0.01	0.014	0.39	20.3	14.5	0.53	482	7.84
I102016		16	5.14	12.5	2.26	4.59	0.08	0.14	0.01	0.019	0.30	20.2	15.5	0.57	660	7.80
I102017		13	10.20	26.3	2.53	5.08	0.06	0.12	0.02	0.059	0.31	26.1	14.2	0.43	1370	5.53
I102018		18	6.47	29.4	2.44	5.18	0.09	0.15	<0.01	0.025	0.39	22.6	17.4	0.59	624	6.12
I102019		17	7.78	14.4	2.27	4.96	0.08	0.15	0.01	0.010	0.43	22.9	21.8	0.58	443	8.50
I102020		12	6.56	2.7	1.98	3.74	0.07	0.22	0.01	0.022	0.36	15.1	33.5	0.43	281	1.02
I102021		15	6.89	10.9	2.20	5.16	0.07	0.21	<0.01	0.013	0.46	24.0	30.9	0.53	651	3.15
I102022		14	9.33	13.3	2.14	5.55	0.06	0.16	0.01	0.013	0.45	21.6	29.5	0.56	648	7.43
I102023		13	9.09	12.2	2.37	5.05	0.06	0.14	<0.01	0.043	0.35	28.5	18.8	0.42	2380	6.36
I102024		13	12.50	32.2	2.44	5.50	0.06	0.14	0.01	0.051	0.40	25.8	16.0	0.43	1450	5.71
I102025		13	9.38	249	2.28	4.73	0.07	0.15	0.01	0.050	0.37	23.5	15.8	0.44	4010	8.37
I102026		17	7.68	19.0	2.35	5.12	0.09	0.17	<0.01	0.014	0.46	22.6	21.3	0.58	678	11.35
I102027		18	7.70	16.0	2.14	4.75	0.09	0.16	0.01	0.013	0.42	20.9	20.6	0.57	436	8.42
I102028		15	9.78	18.3	2.29	5.49	0.07	0.13	0.01	0.030	0.39	21.8	23.3	0.59	1420	8.66
I102029		17	8.51	17.7	2.28	5.16	0.09	0.15	<0.01	0.012	0.46	21.3	27.8	0.58	371	10.80
I102030		18	8.50	17.1	2.38	5.07	0.09	0.15	0.01	0.010	0.46	21.1	27.3	0.58	374	12.05
I102031		17	7.78	14.4	2.12	4.83	0.09	0.15	0.01	0.012	0.43	20.3	23.7	0.56	463	8.90
I102032		15	7.79	13.3	2.09	5.09	0.07	0.14	0.01	0.012	0.40	22.1	26.5	0.53	832	6.70
I102033		15	4.48	10.6	2.06	4.46	0.08	0.25	<0.01	0.012	0.37	22.3	24.2	0.47	401	4.13
I102034		12	6.30	13.4	1.99	5.79	0.05	0.13	0.01	0.031	0.24	27.1	12.0	0.46	2090	0.61
I102035		12	8.03	14.7	2.35	5.15	0.05	0.18	0.02	0.052	0.28	24.0	11.9	0.48	1000	0.64
I102036		7	12.65	50.1	6.11	4.73	0.07	0.09	0.03	0.078	0.27	27.4	3.1	0.15	726	5.09
I102037		11	11.50	264	3.67	6.39	0.06	0.09	0.01	0.116	0.22	28.7	12.7	0.53	2670	1.68
I102038		14	7.13	21.7	2.52	7.28	0.06	0.16	0.01	0.060	0.32	23.7	16.3	0.66	1500	0.96
I102039		9	12.30	48.0	4.11	5.52	0.07	0.11	0.01	0.071	0.31	31.5	11.9	0.30	2090	2.46
I102040C		9	12.55	55.5	4.13	5.49	0.07	0.12	0.01	0.066	0.27	31.3	11.5	0.31	2050	2.42

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127714

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01
I102001		0.03	1.18	4.5	850	39.3	21.2	<0.001	0.04	0.98	2.5	0.2	1.2	28.8	0.01	0.02
I102002		0.04	0.97	4.5	870	30.3	26.0	<0.001	0.02	1.21	2.4	0.2	1.3	28.5	0.01	0.01
I102003		<0.01	<0.05	3.7	760	174.5	33.4	<0.001	0.15	1.80	2.0	0.3	0.3	33.2	<0.01	0.01
I102004		<0.01	<0.05	3.5	670	131.5	38.8	<0.001	0.43	0.49	1.6	0.3	0.2	27.8	<0.01	0.01
I102005		<0.01	<0.05	3.5	660	714	41.7	0.001	0.43	1.03	1.4	0.4	0.2	24.9	<0.01	0.02
I102006		<0.01	<0.05	2.2	700	888	39.0	<0.001	0.03	3.99	1.8	0.3	<0.2	24.5	<0.01	0.06
I102007		<0.01	<0.05	2.7	660	199.0	40.1	<0.001	0.24	3.94	1.9	0.3	<0.2	41.5	<0.01	0.01
I102008		<0.01	<0.05	3.9	650	66.6	35.1	<0.001	0.49	1.41	2.1	0.3	0.2	51.5	<0.01	0.01
I102009		0.02	0.32	3.5	800	366	27.4	<0.001	0.28	21.1	2.8	0.3	0.5	25.4	<0.01	0.03
I102010		0.04	1.02	61.2	760	40.6	10.8	0.002	1.07	8.47	6.0	1.4	106.0	80.8	0.02	43.9
I102011		0.04	1.10	3.7	870	20.1	31.3	<0.001	<0.01	0.81	2.0	0.2	1.1	18.5	<0.01	0.06
I102012		0.05	1.26	4.0	850	29.1	29.4	<0.001	0.03	0.89	2.4	0.2	1.2	31.1	0.01	0.04
I102013		0.05	1.71	3.8	860	31.3	28.3	<0.001	0.34	0.62	2.1	0.2	1.1	48.8	<0.01	0.02
I102014		0.05	1.94	3.7	840	27.2	38.1	<0.001	0.03	0.43	2.0	0.2	1.2	29.2	<0.01	0.01
I102015		0.07	1.87	4.3	830	28.9	43.1	<0.001	<0.01	1.02	2.1	0.2	1.2	20.9	<0.01	0.01
I102016		0.05	1.40	4.2	830	37.3	38.2	<0.001	<0.01	1.35	2.7	0.2	1.2	23.6	<0.01	0.64
I102017		0.03	0.44	4.0	870	113.5	35.9	<0.001	<0.01	3.56	4.1	0.3	0.7	59.6	<0.01	0.06
I102018		0.06	1.40	4.5	870	36.2	45.2	<0.001	<0.01	1.38	2.7	0.3	1.2	31.7	<0.01	0.06
I102019		0.05	1.83	4.8	890	46.2	53.1	<0.001	<0.01	0.56	2.3	0.2	1.2	29.9	<0.01	0.01
I102020		0.06	2.13	4.0	660	19.9	49.2	<0.001	<0.01	0.39	3.7	0.2	1.5	14.1	0.01	<0.01
I102021		0.05	1.46	4.1	860	15.6	56.7	<0.001	<0.01	1.12	2.5	0.2	1.2	26.2	0.01	0.01
I102022		0.03	0.83	3.9	870	18.4	57.3	<0.001	<0.01	0.94	2.9	0.2	1.2	192.5	<0.01	0.01
I102023		0.03	0.56	3.7	820	98.5	43.1	<0.001	<0.01	0.99	4.8	0.3	0.9	100.5	<0.01	0.01
I102024		0.03	0.54	4.0	850	81.7	47.8	<0.001	0.06	2.52	4.2	0.3	0.9	112.0	<0.01	0.03
I102025		0.03	0.90	4.0	850	121.5	45.5	<0.001	0.03	11.35	3.4	0.3	0.9	53.1	<0.01	0.02
I102026		0.06	1.91	4.4	860	41.1	55.5	<0.001	<0.01	0.37	2.9	0.2	1.2	29.5	<0.01	0.02
I102027		0.05	1.77	4.1	840	33.0	52.8	<0.001	<0.01	0.52	2.3	0.2	1.2	27.5	<0.01	0.04
I102028		0.03	0.93	4.2	860	47.9	50.8	<0.001	<0.01	1.00	2.7	0.2	1.2	97.4	<0.01	0.08
I102029		0.06	2.00	4.3	870	41.8	57.7	<0.001	<0.01	0.36	2.3	0.3	1.3	42.3	<0.01	0.01
I102030		0.07	2.18	4.5	870	41.4	58.1	<0.001	<0.01	0.39	2.3	0.3	1.4	46.2	<0.01	0.01
I102031		0.06	1.95	4.0	830	74.9	55.0	<0.001	<0.01	0.32	2.2	0.2	1.2	34.1	<0.01	0.01
I102032		0.04	1.04	3.8	840	33.6	53.0	<0.001	<0.01	0.88	2.7	0.2	1.2	48.7	<0.01	<0.01
I102033		0.08	1.70	3.8	820	28.8	43.0	<0.001	<0.01	0.57	2.5	0.2	1.1	22.4	<0.01	<0.01
I102034		0.01	0.19	3.5	790	47.5	32.7	<0.001	<0.01	1.40	4.1	0.2	0.9	91.2	<0.01	0.02
I102035		0.01	0.31	3.6	830	44.7	39.2	<0.001	<0.01	0.84	3.2	0.2	0.9	66.7	<0.01	0.15
I102036		<0.01	0.07	3.6	790	26.1	37.8	<0.001	<0.01	3.02	1.4	0.7	0.9	22.3	<0.01	1.05
I102037		<0.01	0.08	3.9	830	80.7	36.3	<0.001	<0.01	1.00	2.6	0.3	0.6	102.5	<0.01	0.41
I102038		0.02	0.28	4.0	830	70.6	39.5	<0.001	<0.01	0.91	3.7	0.2	1.3	421	<0.01	0.03
I102039		0.01	0.11	4.1	750	38.1	44.3	<0.001	<0.01	1.50	2.1	0.3	1.0	74.4	<0.01	0.39
I102040C		0.01	0.12	4.0	760	37.9	42.0	<0.001	<0.01	1.53	2.1	0.4	0.9	71.7	<0.01	0.37

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127714

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Th	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102001		31.9	0.143	0.12	11.85	50	1.33	12.60	113	2.6
I102002		34.1	0.145	0.14	11.45	51	1.73	12.40	99	2.5
I102003		28.2	<0.005	0.42	8.61	12	0.20	14.00	295	7.1
I102004		22.0	<0.005	0.45	9.12	4	0.17	10.40	124	11.5
I102005		22.4	<0.005	0.59	10.10	4	0.18	9.69	637	12.1
I102006		22.7	<0.005	0.50	5.54	4	0.17	13.20	809	14.6
I102007		21.3	<0.005	0.49	8.42	4	0.14	11.00	234	11.7
I102008		20.9	<0.005	0.44	8.33	7	0.13	10.95	155	12.4
I102009		32.6	0.042	0.28	12.20	31	0.44	14.00	398	4.3
I102010		4.0	0.149	0.12	1.97	30	56.3	8.76	82	16.8
I102011		31.6	0.148	0.17	13.25	54	1.04	11.35	56	2.5
I102012		29.3	0.150	0.16	10.40	52	1.11	11.85	112	2.7
I102013		28.6	0.151	0.15	10.05	47	1.21	11.70	69	2.3
I102014		29.4	0.156	0.20	10.85	53	2.00	11.80	90	2.2
I102015		27.8	0.178	0.26	10.75	59	2.02	12.00	102	2.3
I102016		28.5	0.154	0.20	10.45	56	1.65	12.75	79	2.2
I102017		29.4	0.077	0.26	8.96	49	0.97	14.05	168	2.2
I102018		29.2	0.170	0.27	11.60	62	2.74	13.55	128	2.4
I102019		30.3	0.180	0.30	12.65	65	3.44	13.60	63	2.4
I102020		30.2	0.149	0.33	7.79	49	0.64	12.95	34	3.5
I102021		31.9	0.163	0.34	12.95	61	1.55	12.10	44	3.5
I102022		29.7	0.148	0.33	10.70	60	0.67	11.30	46	2.6
I102023		30.0	0.089	0.30	13.65	53	0.60	15.50	60	2.5
I102024		29.6	0.097	0.35	15.35	51	0.81	14.65	124	2.7
I102025		28.8	0.117	0.32	13.15	50	1.90	15.10	91	2.6
I102026		30.0	0.181	0.34	12.30	62	2.53	14.05	80	2.7
I102027		28.4	0.175	0.31	11.75	60	2.63	13.00	66	2.6
I102028		29.9	0.148	0.31	10.55	59	2.20	13.85	141	2.1
I102029		31.0	0.189	0.33	13.60	65	3.54	13.70	54	2.5
I102030		30.7	0.193	0.34	13.70	66	4.12	13.55	54	2.5
I102031		28.3	0.182	0.31	11.40	62	4.07	12.95	77	2.4
I102032		33.1	0.152	0.35	12.90	59	2.39	12.20	52	2.3
I102033		32.2	0.145	0.27	16.30	58	2.16	12.80	42	3.9
I102034		31.8	0.037	0.23	4.99	50	0.52	13.95	64	2.9
I102035		35.0	0.066	0.28	6.72	51	0.44	11.95	99	3.6
I102036		27.8	<0.005	0.48	27.2	34	1.67	10.75	49	2.2
I102037		31.6	0.013	0.35	9.34	42	0.55	14.90	98	2.3
I102038		29.7	0.081	0.30	6.46	55	0.57	13.20	100	3.2
I102039		27.6	0.016	0.52	16.50	33	1.12	12.00	82	2.7
I102040C		27.5	0.017	0.48	17.45	35	1.14	12.05	82	2.6

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127714

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1
I102041		1.81	<0.005		0.23	1.55	2.0	<0.2	<10	80	1.87	6.25	0.50	0.25	50.2	5.4
I102042		2.13	0.053		0.51	0.92	10.9	<0.2	<10	50	1.02	6.26	0.28	0.17	66.3	10.1
I102043		1.74	1.510	1.79	2.62	0.51	147.5	4.6	<10	40	0.78	50.0	0.09	0.04	23.8	15.2
I102044		1.74	>10.0	14.15	14.95	0.28	381	16.4	<10	20	0.33	547	0.08	0.04	5.85	36.2
I102045		2.70	1.040	0.92	0.79	1.19	19.3	1.3	<10	80	1.84	8.00	0.36	0.28	48.9	34.5
I102046		2.10	0.217		0.53	1.22	7.1	2.2	<10	50	1.94	2.19	0.48	0.22	44.3	7.0
I102047		2.71	<0.005		0.13	1.13	4.0	<0.2	<10	60	1.32	2.80	0.49	0.11	47.1	4.2
I102048		2.12	<0.005		0.10	2.07	3.0	<0.2	<10	70	2.38	6.66	0.85	0.24	47.9	5.6
I102049		2.59	0.021		0.11	1.99	2.7	<0.2	<10	30	2.03	26.6	0.69	0.16	52.2	6.7
I102050		0.03	2.88	2.57	2.11	1.72	527	2.8	30	120	0.29	253	9.27	0.70	29.8	25.6
I102051		0.87	0.007		0.18	2.14	6.6	<0.2	<10	70	2.59	16.50	0.95	0.26	55.3	12.5
I102052		3.45	<0.005		0.12	1.24	3.5	<0.2	<10	60	1.14	2.82	0.46	0.23	44.0	4.9
I102053		3.89	<0.005		0.08	1.09	4.3	<0.2	<10	50	0.97	1.98	0.48	0.25	40.3	5.6
I102054		4.17	<0.005		0.12	1.00	4.7	<0.2	<10	60	0.77	1.74	0.48	0.26	43.6	5.4
I102055		3.67	<0.005		0.10	1.21	5.0	<0.2	<10	30	1.14	3.40	0.52	0.25	44.9	6.9
I102056		4.63	<0.005		0.13	1.04	3.2	<0.2	<10	50	0.98	2.15	0.53	0.20	52.6	6.8
I102057		3.13	<0.005		0.09	1.43	3.3	<0.2	<10	50	1.44	1.25	0.51	0.33	53.9	6.6
I102058		4.53	<0.005		0.12	1.28	5.4	<0.2	<10	70	0.82	2.08	0.64	0.35	50.9	5.8
I102059		2.05	<0.005		0.12	1.07	5.8	<0.2	<10	70	0.63	1.07	0.70	0.39	49.3	5.0
I102060		0.97	<0.005		0.08	0.71	5.3	<0.2	<10	100	0.57	0.30	0.30	0.23	33.0	3.8
I102061		4.20	<0.005		0.28	1.09	3.2	<0.2	<10	70	0.86	7.79	0.71	0.21	46.4	7.4
I102062		4.24	<0.005		0.58	0.93	3.5	<0.2	<10	80	0.61	10.55	0.56	0.21	46.7	5.5
I102063		3.86	<0.005		0.08	0.93	4.2	<0.2	<10	90	0.61	0.83	0.51	0.18	45.8	5.6
I102064		2.12	<0.005		0.11	0.93	3.8	<0.2	<10	90	0.70	0.44	0.44	0.16	44.6	5.4
I102065		2.37	<0.005		0.41	1.80	3.5	<0.2	<10	70	2.47	5.39	0.68	0.29	51.3	6.7
I102066		4.04	<0.005		0.14	1.26	3.7	<0.2	<10	90	1.30	2.11	0.61	0.19	45.6	5.3
I102067		3.33	<0.005		0.21	1.14	3.7	<0.2	<10	80	1.27	1.62	0.52	0.18	46.9	5.9
I102068		1.72	<0.005		0.30	1.53	3.6	<0.2	<10	70	1.47	1.79	0.73	0.26	48.5	5.6
I102069		1.59	0.024		0.49	1.79	16.9	<0.2	<10	70	3.49	3.16	1.05	0.23	59.6	27.6
I102070		1.55	0.028		0.45	1.50	24.7	<0.2	<10	70	3.32	2.94	0.88	0.27	51.4	28.2
I102071		2.45	<0.005		0.35	2.05	4.8	<0.2	<10	60	3.09	6.14	0.82	0.27	48.9	6.4
I102072		4.02	<0.005		0.21	1.44	3.2	<0.2	<10	70	1.44	3.85	0.61	0.22	47.2	5.6
I102073		3.01	<0.005		0.16	1.36	2.8	<0.2	<10	70	1.40	2.67	0.55	0.26	49.1	6.4
I102074		3.48	<0.005		0.38	1.18	2.5	<0.2	<10	60	1.09	11.20	0.71	0.20	53.1	8.6

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127714

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo
	Units	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm
	LOR	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05
I102041		15	6.64	31.4	2.85	6.59	0.07	0.19	<0.01	0.062	0.32	23.8	21.2	0.73	1030	0.86
I102042		10	13.65	8.2	2.57	4.71	0.06	0.15	<0.01	0.060	0.33	35.6	10.8	0.20	846	1.36
I102043		6	5.71	25.6	12.20	5.74	0.11	0.11	0.02	0.139	0.27	14.5	2.2	0.03	169	16.00
I102044		6	3.19	36.1	14.70	3.84	0.12	0.05	0.39	0.126	0.15	3.6	0.6	0.02	62	22.3
I102045		16	11.35	21.3	3.98	5.53	0.07	0.18	0.04	0.075	0.28	26.0	14.3	0.39	1340	3.12
I102046		15	6.21	5.9	2.91	5.25	0.06	0.19	0.02	0.048	0.23	23.0	14.2	0.46	703	0.74
I102047		15	4.09	5.8	2.38	5.35	0.06	0.22	0.01	0.050	0.26	23.9	13.8	0.54	433	0.59
I102048		15	3.52	14.2	2.72	7.22	0.05	0.12	0.01	0.037	0.17	24.6	18.1	0.76	1050	0.36
I102049		16	2.92	3.5	2.82	7.57	0.05	0.08	0.01	0.034	0.14	27.5	21.1	0.89	1260	0.40
I102050		51	1.54	291	5.13	6.22	0.20	0.40	4.96	1.540	0.16	15.2	6.9	0.26	870	77.6
I102051		10	19.30	27.5	4.55	7.73	0.06	0.10	0.06	0.084	0.35	30.2	8.3	0.54	1200	0.78
I102052		16	4.85	12.4	2.50	5.51	0.07	0.15	0.01	0.051	0.31	21.9	20.2	0.68	557	0.91
I102053		15	4.15	6.4	2.33	5.07	0.07	0.13	<0.01	0.061	0.23	20.5	19.1	0.67	512	0.81
I102054		17	6.85	9.0	2.55	5.16	0.08	0.17	<0.01	0.058	0.26	22.2	15.2	0.59	492	1.63
I102055		17	4.08	8.7	2.85	6.03	0.07	0.21	<0.01	0.127	0.16	23.2	20.6	0.79	769	0.65
I102056		17	3.44	7.5	3.78	5.46	0.06	0.19	<0.01	0.046	0.25	27.5	15.7	0.64	874	1.96
I102057		17	5.16	7.1	3.31	6.70	0.06	0.21	0.01	0.058	0.26	29.1	19.9	0.84	1080	0.58
I102058		18	10.30	12.9	2.79	6.27	0.10	0.26	<0.01	0.094	0.30	26.1	22.2	0.80	696	0.97
I102059		19	11.75	9.2	2.41	5.46	0.10	0.25	<0.01	0.082	0.29	25.1	21.8	0.68	488	0.86
I102060		13	6.08	3.1	2.04	3.94	0.07	0.21	0.01	0.018	0.36	15.4	29.8	0.38	291	2.21
I102061		16	6.50	22.8	3.09	5.59	0.07	0.24	<0.01	0.058	0.36	23.4	20.0	0.72	801	1.57
I102062		16	5.90	13.3	2.68	4.86	0.07	0.28	<0.01	0.044	0.39	23.7	20.5	0.64	556	2.86
I102063		17	5.51	9.9	2.44	4.64	0.09	0.26	<0.01	0.040	0.40	23.1	22.9	0.62	467	2.08
I102064		16	6.11	9.4	2.28	4.43	0.09	0.24	<0.01	0.035	0.39	22.4	22.7	0.60	479	2.00
I102065		12	17.75	25.7	2.78	6.64	0.06	0.12	0.02	0.113	0.31	25.9	18.2	0.62	2430	0.70
I102066		16	6.42	10.3	2.57	5.36	0.07	0.18	<0.01	0.046	0.38	22.9	20.2	0.65	730	1.53
I102067		16	7.33	8.4	2.54	5.31	0.07	0.18	0.01	0.049	0.37	23.5	20.0	0.62	675	1.86
I102068		17	16.95	17.4	2.75	5.69	0.05	0.15	0.01	0.045	0.37	24.6	21.2	0.60	1170	1.78
I102069		10	35.8	20.3	3.00	6.77	<0.05	0.11	0.04	0.137	0.36	32.0	14.5	0.50	1210	1.20
I102070		9	32.7	16.4	3.24	6.03	0.05	0.10	0.03	0.125	0.34	27.1	11.9	0.45	1160	1.72
I102071		13	9.07	8.2	2.81	7.24	0.05	0.14	0.03	0.092	0.28	24.3	21.8	0.81	1020	0.42
I102072		16	5.78	10.0	3.19	6.93	0.06	0.18	0.01	0.070	0.34	23.8	22.6	0.83	799	1.18
I102073		15	6.41	7.1	2.88	6.13	0.06	0.18	0.01	0.059	0.31	22.9	22.2	0.83	644	0.77
I102074		17	7.32	26.6	3.40	6.38	0.06	0.14	<0.01	0.062	0.30	26.2	20.6	0.76	683	0.75

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127714

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01
I102041		0.03	0.35	4.4	840	36.4	39.7	<0.001	<0.01	0.57	4.1	0.2	1.0	173.0	<0.01	0.08
I102042		0.01	0.11	3.2	760	37.7	45.1	<0.001	<0.01	0.77	2.9	0.3	0.9	26.2	<0.01	0.08
I102043		<0.01	0.08	2.4	1280	20.2	39.3	<0.001	0.06	1.60	1.1	2.1	0.5	43.2	<0.01	0.74
I102044		<0.01	0.23	3.6	1210	66.8	18.5	0.001	0.03	7.61	0.4	1.6	3.3	20.9	<0.01	2.92
I102045		0.02	0.39	4.8	680	50.3	33.4	<0.001	0.01	1.56	3.3	0.2	1.4	69.4	0.01	0.23
I102046		0.02	0.47	3.8	770	31.9	26.9	<0.001	<0.01	0.70	3.0	0.2	2.6	33.9	0.01	0.10
I102047		0.04	0.79	3.8	770	25.6	26.4	<0.001	<0.01	0.51	2.9	<0.2	2.0	33.0	0.01	0.23
I102048		0.01	0.23	4.1	770	29.9	16.5	<0.001	<0.01	0.78	3.8	<0.2	1.8	72.4	0.01	0.44
I102049		0.01	0.10	4.8	900	26.3	14.0	<0.001	<0.01	0.47	3.1	<0.2	0.6	40.6	<0.01	0.12
I102050		0.03	1.02	53.5	740	39.8	9.5	0.003	1.05	8.73	5.3	1.3	113.0	79.1	0.03	41.0
I102051		<0.01	0.08	3.4	2020	34.4	45.7	<0.001	<0.01	2.17	2.3	0.2	3.5	52.5	<0.01	2.51
I102052		0.04	0.61	3.9	780	30.0	34.3	<0.001	<0.01	0.61	2.7	0.2	2.2	38.6	0.01	0.08
I102053		0.04	0.70	3.8	750	32.1	24.1	<0.001	<0.01	0.51	2.3	<0.2	1.9	50.5	0.01	0.03
I102054		0.06	1.01	3.8	780	44.4	24.7	<0.001	<0.01	0.61	2.4	0.2	2.4	67.3	0.01	0.04
I102055		0.03	0.51	4.7	810	38.2	14.9	<0.001	<0.01	0.62	2.8	0.2	2.1	57.3	0.01	0.04
I102056		0.02	0.32	4.0	770	56.6	26.0	<0.001	<0.01	0.52	2.7	<0.2	2.1	25.9	0.01	0.03
I102057		0.03	0.36	4.6	800	40.5	25.8	<0.001	<0.01	0.49	3.2	0.2	1.5	33.7	0.01	0.01
I102058		0.05	0.79	4.7	860	39.4	26.1	<0.001	<0.01	0.76	3.3	<0.2	1.9	69.3	0.01	0.01
I102059		0.06	1.08	4.4	800	42.9	25.0	<0.001	<0.01	0.74	3.3	<0.2	1.6	89.4	0.01	<0.01
I102060		0.08	3.25	4.4	660	20.4	47.3	<0.001	<0.01	0.41	3.1	0.2	1.6	17.4	0.01	0.01
I102061		0.04	0.91	4.3	790	82.3	41.5	<0.001	<0.01	0.64	3.4	0.2	1.4	31.4	0.01	0.15
I102062		0.05	1.33	4.2	810	62.6	45.0	<0.001	<0.01	0.60	3.0	0.2	1.3	43.8	0.01	0.11
I102063		0.06	1.45	4.2	830	29.6	40.8	<0.001	<0.01	0.60	2.4	<0.2	1.5	33.6	0.01	0.01
I102064		0.05	1.29	4.0	820	27.6	43.4	<0.001	<0.01	0.68	2.2	0.2	1.5	29.3	0.01	0.01
I102065		0.01	0.17	3.9	770	210	41.1	<0.001	<0.01	0.79	4.0	<0.2	1.2	250	<0.01	0.01
I102066		0.05	0.79	4.3	830	38.0	39.5	<0.001	<0.01	0.75	3.1	<0.2	1.5	105.0	0.01	0.02
I102067		0.04	0.84	4.1	820	40.3	41.4	<0.001	<0.01	0.79	3.0	<0.2	1.4	47.8	0.01	0.02
I102068		0.04	0.51	4.2	820	52.1	45.2	<0.001	<0.01	0.83	3.3	<0.2	1.3	111.5	0.01	0.01
I102069		0.02	0.16	4.1	890	24.2	54.8	<0.001	<0.01	4.77	3.3	0.2	2.0	105.0	<0.01	0.09
I102070		0.01	0.16	3.7	810	24.3	51.7	<0.001	<0.01	5.90	3.0	<0.2	1.7	86.4	<0.01	0.16
I102071		0.01	0.17	3.9	830	34.5	31.2	<0.001	<0.01	4.11	4.1	0.2	1.3	80.6	<0.01	0.04
I102072		0.03	0.40	4.4	780	34.5	35.8	<0.001	<0.01	0.83	3.6	<0.2	1.6	47.8	0.01	0.06
I102073		0.03	0.43	4.2	780	30.2	34.2	<0.001	<0.01	0.73	3.4	<0.2	1.3	67.4	<0.01	0.03
I102074		0.03	0.33	4.2	790	30.2	36.9	<0.001	<0.01	0.77	3.4	0.2	1.4	31.4	<0.01	0.09

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127714

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Th	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102041		33.5	0.082	0.32	7.41	58	0.45	14.15	92	3.5
I102042		31.4	0.013	0.48	25.1	36	0.95	12.20	91	3.3
I102043		23.3	<0.005	0.38	18.15	25	14.25	3.72	33	3.0
I102044		6.8	<0.005	0.24	31.5	55	330	1.73	21	1.4
I102045		29.9	0.069	0.31	10.90	49	3.71	13.85	76	3.7
I102046		29.7	0.083	0.17	7.35	54	1.62	13.95	70	3.3
I102047		32.8	0.125	0.15	7.92	53	1.23	14.55	60	3.8
I102048		34.0	0.051	0.13	5.44	52	0.57	12.95	78	2.7
I102049		31.2	0.018	0.13	4.76	49	1.24	14.65	153	2.2
I102050		4.0	0.154	0.11	1.98	31	62.1	8.41	80	17.0
I102051		30.5	0.009	0.53	13.40	46	4.33	15.00	143	3.0
I102052		29.9	0.128	0.23	10.50	54	1.58	12.20	96	2.5
I102053		30.9	0.124	0.14	9.22	48	1.20	11.45	89	2.2
I102054		31.8	0.144	0.15	11.40	52	1.51	12.25	97	2.6
I102055		28.6	0.108	0.12	7.01	52	0.83	13.30	130	4.2
I102056		31.1	0.058	0.23	8.93	47	1.50	13.25	107	4.2
I102057		32.4	0.082	0.22	8.06	55	0.68	15.75	152	4.6
I102058		29.6	0.157	0.17	8.27	57	0.95	14.35	133	5.2
I102059		30.6	0.170	0.15	7.60	53	1.07	14.55	126	5.0
I102060		33.2	0.155	0.28	8.60	47	0.92	12.50	34	3.6
I102061		30.8	0.130	0.27	11.65	58	0.99	14.55	91	4.8
I102062		29.9	0.152	0.27	11.35	59	0.82	14.10	82	5.4
I102063		28.4	0.177	0.22	11.20	60	1.05	13.85	68	4.9
I102064		28.1	0.169	0.23	10.40	60	1.83	13.75	65	4.7
I102065		27.4	0.053	0.29	7.16	48	0.52	13.35	113	2.8
I102066		28.3	0.158	0.22	9.86	62	0.93	13.95	81	3.4
I102067		28.4	0.148	0.24	9.31	62	1.04	13.40	72	3.3
I102068		28.5	0.123	0.25	9.14	59	1.09	14.30	83	3.0
I102069		25.7	0.041	0.41	7.86	42	1.17	13.60	72	2.9
I102070		25.5	0.038	0.39	8.54	41	1.30	12.45	65	2.9
I102071		27.6	0.054	0.24	5.38	52	0.44	12.90	82	3.5
I102072		28.4	0.098	0.26	8.33	60	0.79	13.35	83	4.0
I102073		29.3	0.103	0.21	8.95	58	0.61	13.70	75	3.7
I102074		28.9	0.072	0.32	9.70	56	0.67	14.30	87	2.9

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127714

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

CERTIFICATE WH10087519

Project: SQI10-01

P.O. No.: SQ110-06-6

This report is for 4 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 29-JUN-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10087519

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1	ME-MS41 Cr ppm 1
130790		6.21	<0.005	0.14	3.12	0.4	<0.2	<10	470	0.66	0.13	2.96	0.16	67.6	16.8	68
130791		2.52	0.014	0.40	1.60	8.6	<0.2	<10	340	0.70	0.36	2.97	0.44	56.3	16.9	38
130792		2.80	0.007	0.17	1.84	1.7	<0.2	<10	470	0.54	0.17	2.25	0.45	53.6	12.0	34
130793		1.96	<0.005	0.22	2.85	8.1	<0.2	<10	440	0.70	0.18	1.59	0.34	61.7	16.2	71

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10087519

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
130790		5.16	44.4	3.77	10.80	0.14	0.05	0.03	0.051	1.52	34.2	15.0	1.23	554	0.98	0.14
130791		1.93	52.2	3.72	6.30	0.11	0.06	0.08	0.045	0.71	28.1	10.5	0.81	757	1.49	0.03
130792		2.11	38.0	3.07	6.40	0.10	0.05	0.02	0.044	0.79	27.1	10.4	0.79	555	1.30	0.07
130793		5.00	50.0	3.78	9.82	0.14	0.07	0.04	0.045	1.38	32.0	13.4	1.14	556	2.29	0.11

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10087519

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
130790		0.23	47.8	770	11.6	85.0	0.002	0.35	0.18	9.4	0.8	1.6	91.9	0.01	0.02	10.8
130791		0.28	39.9	700	10.3	43.0	0.003	0.94	1.24	9.3	1.6	1.0	69.1	<0.01	0.29	9.8
130792		0.21	30.1	730	11.8	46.0	0.003	0.49	0.31	6.3	1.3	1.0	50.3	<0.01	0.03	8.6
130793		0.28	52.1	1190	10.7	77.8	0.005	0.67	0.26	8.7	1.9	1.4	61.9	0.01	0.07	9.5

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10087519

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
130790		0.170	0.58	1.99	71	0.17	21.1	92	1.2
130791		0.068	0.38	2.46	76	0.26	18.10	107	1.5
130792		0.082	0.30	3.41	48	0.12	18.90	98	1.4
130793		0.157	0.59	2.56	83	0.31	18.90	111	1.8

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 16-JUL-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10087519

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

CERTIFICATE WH10137460

Project: SQI10-01

P.O. No.: SQI10-01_14

This report is for 64 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 24-SEP-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
PUL-QC	Pulverizing QC Test
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-MS41	51 anal. aqua regia ICPMS	
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137460

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1
I102323		2.86	<0.005		0.14	1.60	5.2	<0.2	<10	120	1.72	0.59	0.71	0.10	42.5	5.3
I102324		2.28	<0.005		0.25	1.39	13.8	<0.2	<10	60	1.58	1.61	0.68	0.99	47.4	6.5
I102325		2.27	<0.005		0.37	2.14	7.0	<0.2	<10	170	2.38	0.68	0.73	14.15	49.3	4.4
I102326		2.71	0.039		10.60	1.35	67.2	<0.2	<10	90	2.11	15.00	0.46	29.8	55.8	3.9
I102327		4.21	<0.005		0.25	0.92	6.1	<0.2	<10	70	0.97	1.59	0.56	2.53	46.1	4.1
I102328		4.78	<0.005		0.25	0.78	5.5	<0.2	<10	70	0.74	1.28	0.54	0.55	43.7	3.3
I102329		4.35	<0.005		0.24	0.85	5.6	<0.2	<10	80	0.89	1.26	0.55	0.43	52.6	4.0
I102330		0.04	0.307		9.87	0.48	9.1	0.3	<10	140	0.27	1.84	2.37	0.18	13.55	4.2
I102331		2.63	<0.005		0.08	0.87	3.5	<0.2	<10	110	0.95	0.39	0.64	0.17	51.7	4.4
I102332		3.20	<0.005		0.47	1.29	2.6	<0.2	<10	70	1.96	0.20	1.27	0.09	54.8	4.6
I102333		2.93	0.014		0.84	1.15	61.1	<0.2	<10	90	1.54	6.38	0.38	0.38	61.9	11.9
I102334		1.60	0.314		0.75	0.90	78.5	<0.2	<10	40	1.69	5.27	0.37	0.50	70.4	14.8
I102335		3.04	<0.005		0.44	1.12	7.4	<0.2	<10	50	1.32	4.13	0.56	0.31	55.1	6.3
I102336		3.49	0.005		1.10	1.25	25.3	<0.2	<10	60	1.54	6.07	0.74	0.27	49.7	6.9
I102337		2.24	<0.005		0.31	1.08	22.7	<0.2	<10	40	1.40	2.28	1.02	0.27	63.2	5.7
I102338		2.33	0.012		0.85	0.98	8.1	<0.2	<10	30	1.29	3.69	1.02	0.19	75.2	8.4
I102339		1.50	0.005		0.32	1.32	22.7	<0.2	<10	40	1.35	8.83	0.98	0.70	62.0	9.0
I102340		1.06	<0.005		0.07	0.70	6.6	<0.2	<10	100	0.78	0.40	0.30	0.20	35.5	3.9
I102341		3.64	<0.005		0.37	1.23	26.5	<0.2	<10	30	1.65	3.71	0.64	0.24	73.9	8.0
I102342		2.32	<0.005		0.16	0.77	6.9	<0.2	<10	60	0.86	0.80	0.50	0.41	51.8	3.4
I102343		2.02	<0.005		0.17	0.76	3.1	<0.2	<10	70	0.72	1.95	0.38	0.26	45.6	4.6
I102344		1.64	0.016		0.37	0.68	7.3	<0.2	10	40	1.19	3.59	0.29	0.23	47.4	7.1
I102345		2.92	<0.005		0.16	1.00	3.7	<0.2	<10	80	1.18	0.50	0.44	0.29	49.7	5.0
I102346		3.22	<0.005		0.16	1.12	2.6	<0.2	<10	100	1.15	0.46	0.46	0.24	57.4	5.1
I102347		1.64	<0.005		0.27	2.58	3.5	<0.2	<10	300	3.68	0.72	1.52	2.13	59.8	5.4
I102348		1.50	<0.005		0.22	1.70	2.4	<0.2	<10	130	2.18	1.13	0.60	0.51	52.4	5.3
I102349		1.05	0.350		0.30	1.39	12.8	<0.2	10	150	2.37	2.75	0.52	0.25	59.4	14.1
I102350		1.06	0.024		0.31	1.33	10.2	<0.2	<10	130	2.24	2.43	0.49	0.22	64.7	10.1
I102351		1.32	0.552		3.85	0.51	56.8	18.6	<10	10	0.70	29.2	0.11	0.13	17.10	36.8
I102352		2.25	0.008		0.34	0.86	10.6	<0.2	10	50	1.17	3.31	0.23	0.21	54.2	9.6
I102353		3.49	<0.005		0.15	1.12	3.3	<0.2	<10	70	1.46	2.20	0.43	0.29	49.9	5.2
I102354		1.31	<0.005		0.11	1.83	4.5	<0.2	<10	100	2.35	1.75	0.71	0.46	49.9	6.2
I102355		3.64	0.006		0.15	1.21	5.0	<0.2	<10	100	1.18	1.85	0.68	0.31	47.4	6.5
I102356		3.74	<0.005		0.09	1.56	3.9	<0.2	<10	90	1.58	6.33	0.60	0.28	51.2	5.9
I102357		8.85	<0.005		0.10	1.08	4.9	<0.2	<10	100	0.83	3.23	0.53	0.25	44.9	5.8
I102358		1.96	<0.005		0.10	0.89	4.8	<0.2	<10	90	0.74	5.34	0.49	0.24	46.9	5.4
I102359		1.12	0.009		0.56	0.79	10.1	<0.2	<10	30	1.15	11.15	0.35	0.18	81.9	5.3
I102360		<0.02	0.011		0.58	0.84	9.8	<0.2	<10	40	1.26	11.50	0.35	0.15	75.1	5.2
I102361		1.30	0.006		0.54	0.94	15.5	<0.2	<10	50	1.38	6.09	0.38	0.19	77.6	12.6
I102362		4.30	<0.005		0.35	1.03	5.1	<0.2	<10	80	0.81	6.14	0.77	0.30	50.9	5.5

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137460

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo
	Units	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm
	LOR	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05
I102323		16	7.67	18.6	2.36	6.07	0.09	0.18	<0.01	0.038	0.35	22.6	19.7	0.63	533	2.95
I102324		11	3.78	13.9	2.06	6.05	0.09	0.18	0.01	0.055	0.21	27.3	20.0	0.62	614	1.39
I102325		15	7.56	9.7	2.53	6.72	0.09	0.13	0.03	0.040	0.36	26.0	18.2	0.64	1480	1.65
I102326		9	8.54	259	3.50	5.15	0.08	0.11	0.14	0.093	0.35	29.1	11.0	0.31	2030	4.69
I102327		17	6.44	23.8	2.36	4.98	0.12	0.16	<0.01	0.043	0.33	22.5	19.2	0.55	451	4.15
I102328		17	4.82	16.4	2.30	4.28	0.10	0.14	<0.01	0.044	0.29	20.7	15.2	0.44	308	4.16
I102329		18	6.52	22.4	2.37	4.66	0.13	0.17	0.01	0.038	0.37	25.6	21.1	0.46	326	4.68
I102330		6	0.96	6110	1.40	1.67	<0.05	0.04	0.83	0.020	0.24	6.3	1.7	0.10	406	148.5
I102331		16	6.74	13.0	2.03	4.69	0.11	0.18	0.01	0.021	0.37	25.4	23.7	0.46	376	3.30
I102332		15	4.36	6.8	2.00	5.17	0.07	0.16	<0.01	0.010	0.29	28.1	20.7	0.47	779	0.82
I102333		8	14.05	230	4.26	4.60	0.09	0.11	0.01	0.077	0.40	31.6	10.4	0.19	5920	10.20
I102334		5	18.00	88.3	6.91	4.68	0.13	0.07	0.02	0.168	0.28	35.1	10.6	0.12	19950	39.5
I102335		15	5.04	23.7	2.52	5.75	0.08	0.17	<0.01	0.049	0.24	28.2	17.5	0.61	1100	2.36
I102336		16	4.49	28.9	2.98	6.28	0.09	0.18	<0.01	0.055	0.27	24.6	18.5	0.63	883	3.10
I102337		13	4.12	69.1	2.68	5.52	0.09	0.14	<0.01	0.054	0.20	32.0	18.2	0.57	763	5.72
I102338		12	4.12	53.7	2.70	5.08	0.09	0.12	0.01	0.042	0.19	38.6	13.1	0.41	726	27.3
I102339		28	3.76	60.6	3.46	7.99	0.11	0.15	<0.01	0.072	0.22	31.4	25.4	0.82	697	25.9
I102340		14	6.30	5.7	2.14	4.22	0.10	0.20	0.01	0.020	0.33	16.6	34.7	0.39	308	2.06
I102341		13	2.90	81.8	2.75	6.70	0.08	0.10	<0.01	0.052	0.16	35.9	20.8	0.66	831	4.18
I102342		17	4.59	13.7	2.28	4.74	0.11	0.23	<0.01	0.031	0.30	26.1	14.5	0.46	409	5.47
I102343		16	6.34	9.6	1.99	4.67	0.10	0.18	<0.01	0.018	0.35	22.1	17.3	0.48	425	4.67
I102344		8	4.27	4.6	2.00	3.00	0.06	0.11	<0.01	0.021	0.24	24.1	8.9	0.22	906	1.50
I102345		16	5.79	7.3	2.17	5.18	0.09	0.19	<0.01	0.021	0.35	24.4	17.6	0.52	554	2.90
I102346		17	6.89	12.2	2.33	5.01	0.10	0.21	<0.01	0.016	0.42	28.9	24.2	0.56	527	3.44
I102347		13	8.48	10.3	2.46	6.74	0.08	0.12	0.02	0.022	0.24	31.4	18.9	0.68	6980	3.19
I102348		15	7.52	12.4	2.48	5.89	0.09	0.16	0.01	0.028	0.33	25.1	20.0	0.61	1430	1.44
I102349		10	11.15	9.0	4.51	5.28	0.12	0.14	0.02	0.056	0.26	28.6	12.6	0.42	3160	1.61
I102350		9	11.65	8.9	4.41	5.17	0.13	0.14	0.02	0.052	0.25	30.3	12.8	0.42	2770	1.22
I102351		4	11.65	46.4	4.21	2.43	0.07	0.06	0.02	0.150	0.18	9.4	3.1	0.04	517	4.24
I102352		9	10.00	175.5	3.99	3.75	0.08	0.14	0.01	0.058	0.31	22.4	6.0	0.15	490	1.81
I102353		13	6.59	57.0	2.28	5.44	0.10	0.23	<0.01	0.054	0.26	26.0	18.3	0.55	624	0.77
I102354		15	3.82	7.8	2.48	6.41	0.10	0.23	0.01	0.065	0.25	25.5	23.6	0.80	1060	0.63
I102355		17	4.58	9.7	2.37	5.33	0.11	0.25	0.01	0.071	0.30	23.6	21.4	0.62	780	1.40
I102356		16	5.84	14.0	3.02	7.12	0.11	0.21	<0.01	0.066	0.34	25.4	28.5	0.87	650	0.72
I102357		16	5.08	7.7	2.44	5.19	0.11	0.30	<0.01	0.044	0.36	22.7	23.2	0.64	529	1.62
I102358		17	4.73	6.9	2.28	4.57	0.12	0.32	<0.01	0.044	0.36	23.3	19.2	0.53	592	1.59
I102359		14	23.7	20.6	3.20	4.16	0.11	0.15	0.01	0.109	0.24	42.8	8.6	0.12	930	0.58
I102360		14	22.3	18.2	3.23	4.31	0.08	0.15	0.01	0.097	0.26	38.5	8.2	0.12	903	0.59
I102361		12	29.4	15.1	3.41	4.92	0.09	0.15	0.02	0.093	0.22	38.4	9.5	0.17	2230	1.30
I102362		19	5.49	7.5	2.86	5.85	0.12	0.27	<0.01	0.060	0.36	25.8	21.1	0.67	781	2.24

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137460

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01
I102323		0.04	0.62	4.2	760	30.1	40.5	<0.001	<0.01	1.46	2.8	0.3	1.7	114.0	<0.01	0.04
I102324		0.03	0.61	3.7	610	28.0	22.7	<0.001	0.04	1.70	2.7	0.3	1.8	43.5	<0.01	0.20
I102325		0.03	0.37	4.3	910	50.6	43.0	<0.001	<0.01	4.18	3.7	0.4	1.5	215	<0.01	0.04
I102326		0.01	0.16	4.6	910	69.9	44.5	<0.001	0.17	15.65	2.9	0.6	1.5	83.0	<0.01	0.15
I102327		0.05	1.34	4.2	860	33.9	43.6	<0.001	0.01	1.48	2.4	0.3	1.8	34.0	0.01	0.07
I102328		0.05	1.27	3.7	850	34.6	37.1	<0.001	<0.01	1.15	1.7	0.3	1.7	26.8	0.01	0.03
I102329		0.08	1.79	3.9	840	35.1	49.1	<0.001	<0.01	1.19	2.1	0.3	1.6	29.4	0.01	0.01
I102330		0.03	<0.05	4.4	390	15.5	6.1	0.037	1.43	15.50	0.8	0.6	0.3	355	<0.01	1.98
I102331		0.06	1.56	3.7	820	30.2	50.5	<0.001	0.01	1.09	2.5	0.2	1.2	77.5	0.01	<0.01
I102332		0.03	0.55	3.5	850	18.4	38.5	<0.001	<0.01	0.50	2.5	0.2	1.1	34.2	<0.01	<0.01
I102333		0.01	0.16	3.9	840	66.4	56.0	<0.001	0.01	5.64	2.0	0.5	4.4	134.0	<0.01	0.65
I102334		0.01	0.07	9.2	800	23.3	37.5	<0.001	0.01	4.04	1.9	0.5	1.2	232	<0.01	0.85
I102335		0.03	0.52	4.5	810	99.6	31.0	<0.001	<0.01	0.94	3.1	0.3	1.7	36.6	0.01	0.21
I102336		0.04	0.63	4.3	830	55.0	32.0	<0.001	0.12	1.29	3.0	0.3	2.6	47.9	0.01	0.88
I102337		0.03	0.38	4.3	800	39.4	24.6	0.001	0.28	1.20	2.9	0.4	1.5	31.0	0.01	0.23
I102338		0.02	0.08	3.7	770	25.1	23.5	<0.001	0.07	0.95	2.3	0.4	1.3	27.2	<0.01	1.19
I102339		0.04	0.28	5.5	860	34.8	27.1	0.001	0.37	0.70	4.1	0.6	1.8	26.9	0.01	0.47
I102340		0.06	2.70	4.2	760	21.6	47.1	<0.001	0.01	0.47	2.9	0.3	2.1	14.9	0.01	0.01
I102341		0.02	0.06	4.2	750	30.4	20.8	<0.001	0.12	0.49	2.6	0.3	0.6	23.1	<0.01	0.34
I102342		0.07	1.81	3.7	820	46.6	35.1	<0.001	0.03	0.77	2.5	0.3	2.3	22.6	0.01	0.03
I102343		0.04	1.80	3.7	790	50.2	47.1	<0.001	<0.01	0.82	2.1	0.2	1.2	22.1	0.01	0.01
I102344		0.01	0.33	2.4	820	24.5	34.5	<0.001	<0.01	0.89	1.4	0.2	5.5	28.0	<0.01	1.27
I102345		0.05	1.34	3.9	810	51.4	45.8	<0.001	<0.01	0.88	2.5	0.2	1.4	28.6	0.01	0.02
I102346		0.06	1.29	4.0	850	60.6	55.2	<0.001	<0.01	1.05	2.7	0.4	1.4	51.9	0.01	<0.01
I102347		0.03	0.26	3.5	2970	62.9	29.7	<0.001	<0.01	1.43	3.7	0.4	1.1	440	<0.01	0.02
I102348		0.03	0.57	3.9	890	70.8	46.0	<0.001	<0.01	0.82	3.5	0.3	1.3	104.5	<0.01	0.01
I102349		0.02	0.46	3.8	830	28.5	33.5	<0.001	<0.01	1.96	2.1	0.3	3.0	131.0	<0.01	0.06
I102350		0.02	0.43	3.8	870	25.7	34.9	<0.001	<0.01	1.73	2.2	0.3	2.6	110.5	<0.01	0.06
I102351		<0.01	0.10	1.7	350	22.8	29.8	<0.001	0.04	1.94	0.6	0.3	2.9	10.9	<0.01	0.32
I102352		0.01	0.16	2.1	580	40.8	42.0	<0.001	<0.01	1.88	1.1	0.4	1.3	14.4	<0.01	0.10
I102353		0.04	0.74	3.8	680	35.4	31.0	<0.001	<0.01	0.61	3.2	0.5	1.4	59.3	0.01	0.08
I102354		0.03	0.30	4.1	860	50.1	24.8	<0.001	<0.01	0.61	4.0	0.4	1.6	80.9	<0.01	0.05
I102355		0.05	0.79	4.0	830	52.5	29.7	<0.001	<0.01	0.87	3.5	0.4	1.7	74.7	0.01	0.07
I102356		0.03	0.50	4.4	850	38.9	38.8	<0.001	<0.01	0.51	4.2	0.4	1.6	57.3	<0.01	0.21
I102357		0.06	1.17	4.2	820	40.7	37.2	<0.001	<0.01	0.62	2.9	0.4	1.7	42.7	0.01	0.23
I102358		0.06	1.36	3.8	830	39.6	38.5	<0.001	<0.01	0.69	2.5	0.5	1.5	29.0	0.01	0.10
I102359		0.01	0.10	3.6	950	118.5	34.6	<0.001	<0.01	1.17	4.0	0.4	0.8	20.7	<0.01	0.15
I102360		0.01	0.07	3.6	920	96.5	35.9	<0.001	<0.01	1.28	4.3	0.3	0.8	21.4	<0.01	0.15
I102361		0.01	0.08	4.0	950	72.0	33.3	<0.001	<0.01	1.24	4.1	0.3	0.9	49.7	<0.01	0.28
I102362		0.05	1.28	4.8	810	42.1	40.2	<0.001	0.01	0.81	4.1	0.3	1.5	29.7	0.01	1.02

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137460

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Y	Zn	Zr	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5	5
I102323		31.9	0.097	0.26	9.89	49	2.29	13.55	58	4.0	
I102324		35.5	0.070	0.17	8.53	33	0.73	13.50	119	4.7	
I102325		32.8	0.083	0.33	8.83	54	0.52	15.60	608	2.6	
I102326		27.8	0.022	0.51	16.35	31	0.85	13.10	1630	2.3	
I102327		27.4	0.149	0.26	11.15	52	1.02	13.50	188	2.2	
I102328		26.2	0.136	0.21	9.98	51	1.19	12.85	52	1.9	
I102329		27.7	0.159	0.27	12.10	55	1.35	14.60	54	2.4	
I102330		1.1	<0.005	0.05	0.86	11	4.83	4.37	35	1.5	
I102331		30.9	0.148	0.27	10.65	54	0.65	12.45	39	2.6	
I102332		29.0	0.097	0.22	8.50	55	1.30	11.15	34	2.4	
I102333		29.5	0.017	0.69	17.90	30	2.46	11.75	79	2.3	
I102334		28.0	<0.005	0.61	38.6	19	0.94	15.10	140	1.4	
I102335		33.1	0.083	0.24	10.50	47	0.99	15.65	94	2.4	
I102336		30.6	0.096	0.25	7.66	46	1.03	14.50	80	2.9	
I102337		32.9	0.045	0.22	10.95	39	0.79	16.25	87	2.4	
I102338		32.2	0.008	0.24	8.90	34	1.59	17.20	69	2.4	
I102339		29.5	0.038	0.23	10.10	55	1.85	17.15	109	2.5	
I102340		29.1	0.150	0.30	8.39	52	0.76	14.80	35	3.1	
I102341		36.4	0.006	0.22	6.52	36	0.64	17.40	103	1.8	
I102342		37.7	0.148	0.23	17.60	53	1.65	12.25	81	3.2	
I102343		31.5	0.155	0.27	13.35	52	1.10	12.25	66	2.7	
I102344		35.3	0.025	0.34	9.95	19	2.59	9.77	39	2.2	
I102345		31.4	0.159	0.27	10.50	52	1.02	13.05	72	3.1	
I102346		32.8	0.177	0.33	12.10	58	1.19	13.60	62	3.1	
I102347		30.8	0.059	0.34	17.10	49	1.23	17.95	78	2.1	
I102348		32.9	0.125	0.32	9.17	57	0.85	12.50	80	2.7	
I102349		38.0	0.077	0.39	11.15	39	5.45	11.85	81	2.8	
I102350		39.2	0.073	0.36	10.50	37	4.48	11.85	78	2.8	
I102351		21.7	<0.005	0.34	22.5	23	5.89	4.28	42	1.2	
I102352		36.5	0.010	0.51	15.25	25	1.87	10.20	80	2.6	
I102353		38.1	0.101	0.21	10.85	44	0.74	15.40	87	3.7	
I102354		33.0	0.119	0.17	7.92	50	0.50	13.75	113	4.3	
I102355		30.7	0.159	0.19	9.88	52	0.72	13.30	105	4.4	
I102356		32.0	0.123	0.28	7.97	57	0.48	14.15	100	4.0	
I102357		32.7	0.166	0.22	11.15	53	0.82	13.85	83	5.4	
I102358		35.0	0.166	0.25	11.90	54	1.08	14.45	77	5.4	
I102359		37.7	0.009	0.35	13.05	45	1.52	14.25	104	3.5	
I102360		30.9	0.009	0.35	11.00	46	1.48	14.00	102	3.6	
I102361		30.4	0.012	0.36	12.00	46	1.50	16.25	100	3.8	
I102362		33.8	0.140	0.31	13.25	57	1.62	15.40	109	5.1	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137460

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1
I102363		2.16	<0.005		0.13	0.97	6.0	<0.2	<10	110	0.66	1.04	0.59	0.34	43.5	5.8
I102364		4.71	0.005		0.22	1.25	4.3	<0.2	<10	90	0.98	4.19	0.75	0.28	45.4	8.8
I102365		0.41	0.010		0.87	0.84	10.3	<0.2	<10	40	0.90	1.60	0.34	0.30	45.9	12.1
I102366		1.79	<0.005		0.18	1.28	4.1	<0.2	<10	100	1.00	4.49	0.57	0.20	46.9	6.9
I102367		2.27	<0.005		0.22	1.26	4.7	<0.2	<10	90	1.04	1.35	0.96	0.22	47.2	6.9
I102368		0.59	0.031		>100	1.72	9.9	<0.2	<10	110	2.02	8.65	0.63	0.30	49.0	13.5
I102369		3.89	<0.005		0.57	1.27	4.4	<0.2	<10	140	0.88	2.63	0.55	0.23	42.1	5.7
I102370		0.03	3.05	3.35	2.11	1.78	567	2.8	20	140	0.34	261	9.73	0.73	33.7	33.3
I102371		1.18	<0.005		0.20	1.03	5.2	<0.2	<10	100	0.88	2.18	0.47	0.17	48.0	5.0
I102372		1.35	<0.005		13.50	1.38	4.0	<0.2	<10	80	1.71	2.14	0.48	0.32	64.7	6.4
I102373		2.27	<0.005		0.42	0.76	8.8	<0.2	10	70	1.42	1.60	0.30	0.21	68.2	11.3
I102374		2.25	<0.005		0.33	1.13	4.8	<0.2	<10	40	1.49	0.80	0.34	0.38	67.2	7.1
I102375		3.73	<0.005		0.17	1.26	3.7	<0.2	<10	30	1.14	2.14	0.50	0.12	48.7	4.3
I102376		4.62	<0.005		0.15	1.30	4.0	<0.2	<10	40	1.13	1.76	0.50	0.10	55.0	5.2
I102377		1.99	<0.005		0.31	0.93	5.4	<0.2	<10	30	1.28	1.74	0.32	0.12	55.7	11.0
I102378		2.02	<0.005		0.28	0.97	12.7	<0.2	<10	50	1.29	1.63	0.32	0.17	67.0	8.1
I102379		2.98	0.068		0.18	1.19	3.5	<0.2	<10	80	1.16	2.78	0.52	0.25	51.3	6.4
I102380		0.93	<0.005		0.06	0.72	5.0	<0.2	<10	100	0.61	0.28	0.28	0.20	32.4	3.4
I102381		1.70	<0.005		1.14	1.21	6.2	<0.2	<10	80	1.60	2.90	0.45	0.72	62.6	9.5
I102382		2.07	1.525	1.44	18.30	1.35	253	2.0	<10	170	3.30	132.5	1.12	2.63	41.9	102.0
I102383		2.59	0.060		1.29	3.04	12.5	<0.2	<10	110	2.80	6.62	2.56	0.33	45.3	9.5
I102384		3.50	0.028		36.8	1.64	11.6	<0.2	<10	60	1.97	11.05	0.92	0.42	54.6	10.6
I102385		2.25	0.010		0.76	0.99	12.0	<0.2	<10	90	1.04	4.71	0.38	0.24	53.7	18.0
I102386		2.24	<0.005		0.17	1.03	4.2	<0.2	<10	100	0.85	0.99	0.48	0.28	56.0	6.1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137460

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo
	Units	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm
	LOR	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05
I102363		22	4.89	6.1	2.50	5.21	0.12	0.31	<0.01	0.034	0.43	21.6	18.3	0.60	467	2.13
I102364		19	6.14	13.4	3.10	6.38	0.10	0.24	<0.01	0.075	0.39	22.5	23.0	0.81	838	1.59
I102365		11	30.0	79.3	3.05	3.54	0.06	0.10	0.01	0.075	0.31	24.3	6.1	0.21	830	0.58
I102366		20	9.06	15.0	3.22	6.59	0.13	0.26	<0.01	0.075	0.43	23.6	22.4	0.82	734	1.06
I102367		19	5.64	4.4	3.09	6.50	0.10	0.18	<0.01	0.084	0.33	23.2	22.9	0.86	692	0.84
I102368		15	9.19	181.5	3.27	6.55	0.07	0.14	0.27	0.073	0.28	27.5	17.6	0.79	1120	1.08
I102369		20	6.77	7.5	3.03	6.37	0.11	0.22	0.01	0.072	0.44	20.2	26.8	0.91	788	1.50
I102370		52	1.66	302	5.48	7.53	0.30	0.47	5.17	1.370	0.17	16.5	8.1	0.27	917	85.5
I102371		17	6.52	9.3	2.70	5.83	0.11	0.24	0.01	0.061	0.40	23.2	24.9	0.74	588	1.22
I102372		16	8.69	74.9	3.36	5.92	0.08	0.16	0.16	0.061	0.24	32.9	15.3	0.62	1340	0.94
I102373		15	10.85	5.4	3.78	3.38	0.09	0.13	0.01	0.063	0.27	33.4	4.9	0.12	1140	1.31
I102374		18	11.10	5.6	3.55	5.78	0.08	0.11	0.01	0.053	0.21	32.1	11.7	0.49	1280	1.02
I102375		17	5.05	10.3	2.86	7.77	0.10	0.63	<0.01	0.079	0.13	25.8	23.4	0.75	638	1.30
I102376		15	3.41	7.3	2.90	7.89	0.10	0.64	<0.01	0.089	0.14	28.8	23.6	0.75	648	0.96
I102377		16	9.14	9.1	3.53	4.91	0.08	0.08	0.01	0.039	0.16	26.2	8.7	0.42	799	0.56
I102378		13	5.39	12.0	4.35	5.01	0.10	0.14	0.01	0.058	0.28	34.0	10.5	0.40	503	0.70
I102379		19	5.86	9.7	3.02	6.04	0.10	0.24	0.01	0.078	0.38	24.2	19.7	0.74	661	1.03
I102380		19	6.85	3.0	2.03	3.78	0.09	0.21	<0.01	0.021	0.36	15.4	33.8	0.42	291	0.90
I102381		20	7.15	137.0	3.27	5.82	0.09	0.20	0.01	0.100	0.33	31.6	17.9	0.63	1120	0.94
I102382		10	32.0	3610	10.20	11.25	0.17	0.10	0.25	0.563	0.24	21.7	7.4	0.20	4530	6.50
I102383		13	20.1	95.4	2.60	9.08	0.07	0.14	0.03	0.081	0.27	21.0	17.3	0.67	1540	0.59
I102384		26	19.75	101.5	3.44	7.03	0.08	0.18	0.13	0.081	0.26	28.7	15.9	0.56	1280	7.63
I102385		17	10.35	39.7	4.44	4.84	0.09	0.19	0.02	0.045	0.32	27.1	10.5	0.34	1040	2.19
I102386		19	7.33	9.5	2.55	4.94	0.10	0.26	<0.01	0.021	0.41	27.9	20.1	0.61	580	3.14

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137460

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01
I102363		0.09	2.02	4.7	840	30.9	43.2	<0.001	0.01	0.89	3.1	0.3	1.7	47.5	0.01	0.10
I102364		0.05	1.12	5.2	890	33.8	45.5	<0.001	0.01	1.02	3.8	0.3	2.0	38.2	0.01	0.06
I102365		0.01	0.11	2.9	720	38.0	45.5	<0.001	0.01	1.81	2.0	0.2	1.2	21.0	<0.01	0.05
I102366		0.07	1.18	5.1	900	32.8	51.1	<0.001	0.01	1.28	4.3	0.3	2.1	51.3	0.01	0.03
I102367		0.05	0.89	5.3	940	29.9	37.1	<0.001	0.01	1.08	3.8	0.2	2.0	43.9	0.01	0.02
I102368		0.09	0.39	4.4	900	128.5	36.5	0.002	0.01	1.12	3.6	0.3	3.3	62.7	<0.01	0.21
I102369		0.06	1.11	5.3	910	42.9	54.0	<0.001	0.01	0.90	4.3	0.2	2.2	38.8	0.01	0.14
I102370		0.04	1.48	67.0	790	45.1	10.9	0.003	1.15	9.35	7.6	1.5	107.0	87.6	0.03	41.8
I102371		0.06	1.24	5.1	900	41.3	48.0	<0.001	0.01	0.92	3.5	0.2	2.1	28.8	0.01	0.11
I102372		0.03	0.22	20.0	960	31.7	32.1	0.001	0.01	0.68	3.7	0.3	1.0	44.1	<0.01	0.10
I102373		0.01	0.09	3.6	940	91.7	37.3	<0.001	0.01	1.09	1.4	0.3	1.6	19.7	<0.01	0.07
I102374		0.03	0.08	4.0	860	42.4	27.6	<0.001	0.01	0.78	2.4	0.2	1.0	25.6	<0.01	0.04
I102375		0.04	0.56	3.9	660	25.3	16.2	<0.001	0.01	1.06	3.3	0.2	2.9	35.9	0.01	0.02
I102376		0.05	0.60	3.9	680	15.7	15.2	<0.001	0.01	1.10	3.4	0.2	1.9	39.8	0.01	0.04
I102377		0.02	0.08	3.3	870	45.1	22.4	<0.001	0.01	0.59	1.5	0.2	0.7	19.1	<0.01	0.06
I102378		0.02	0.29	3.3	770	22.5	38.9	<0.001	0.01	1.84	2.2	0.2	1.9	21.0	<0.01	0.03
I102379		0.06	0.97	4.9	1260	29.7	46.9	<0.001	0.01	1.15	3.8	0.3	1.8	35.6	0.01	0.04
I102380		0.06	2.48	3.9	690	19.5	53.2	<0.001	0.03	0.42	3.7	0.2	1.5	14.9	0.01	0.01
I102381		0.03	0.55	4.5	990	28.7	42.8	<0.001	0.02	3.91	4.1	0.3	1.5	41.2	<0.01	0.03
I102382		0.02	0.16	6.6	3990	172.0	42.4	0.001	0.03	148.0	2.4	0.7	6.6	241	<0.01	0.80
I102383		0.04	0.29	4.2	5270	43.3	37.4	<0.001	0.03	8.34	4.8	0.2	1.4	185.0	<0.01	0.04
I102384		0.03	0.28	6.1	1940	47.7	36.9	0.001	0.03	3.18	3.6	0.2	2.2	88.3	<0.01	0.10
I102385		0.03	0.55	4.2	960	23.3	38.5	<0.001	0.02	2.66	3.1	0.3	22.5	33.1	0.01	0.21
I102386		0.05	1.47	4.2	980	41.7	49.8	<0.001	0.01	0.76	3.0	0.3	1.6	32.4	0.01	0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137460

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Y	Zn	Zr	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5	5
I102363		30.6	0.191	0.29	12.85	57	2.43	14.35	85	6.0	
I102364		28.8	0.154	0.37	9.52	62	0.83	13.75	102	5.0	
I102365		24.6	0.011	0.43	6.58	26	2.16	11.30	63	2.5	
I102366		31.0	0.173	0.41	9.11	67	2.12	14.35	84	5.2	
I102367		28.8	0.135	0.27	8.51	65	0.74	13.80	86	3.5	
I102368		27.1	0.052	0.42	7.38	53	340	13.00	101	3.7	167
I102369		29.5	0.172	0.47	9.14	66	3.54	12.75	91	4.3	
I102370		4.7	0.164	0.14	2.42	32	70.4	9.39	85	20.7	
I102371		31.5	0.166	0.35	8.38	63	1.87	13.60	73	4.9	
I102372		32.5	0.036	0.37	8.51	56	199.5	16.90	99	3.9	
I102373		29.5	0.008	0.39	11.45	34	1.76	13.45	104	3.7	
I102374		30.4	0.010	0.34	8.10	49	1.35	14.70	107	2.6	
I102375		21.3	0.083	0.21	6.57	43	0.97	9.48	82	21.4	
I102376		25.1	0.089	0.18	6.80	43	0.56	10.60	81	19.8	
I102377		30.5	0.007	0.24	6.67	36	0.31	12.55	100	2.0	
I102378		32.3	0.037	0.43	7.65	43	2.40	11.75	67	3.6	
I102379		32.7	0.133	0.38	12.35	62	0.78	14.65	80	4.8	
I102380		31.4	0.146	0.33	8.37	50	0.71	13.10	35	3.6	
I102381		33.7	0.097	0.41	10.25	57	1.35	15.60	94	4.4	
I102382		24.7	0.006	0.99	64.9	63	85.0	11.70	166	3.0	
I102383		27.8	0.054	0.34	30.0	51	4.07	11.55	84	3.3	
I102384		27.1	0.042	0.37	12.90	45	136.0	11.90	90	5.5	
I102385		33.2	0.071	0.36	11.45	53	18.45	12.90	76	4.5	
I102386		33.5	0.168	0.29	14.05	62	2.86	15.45	82	5.1	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137460

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd.

2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

CERTIFICATE WH10137855

Project: SQI10-06

P.O. No.: SQI10-06_32

This report is for 200 Soil samples submitted to our lab in Whitehorse, YT, Canada on 27-SEP-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
SCR-41	Screen to -180um and save both

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I100145		0.64	0.006	0.15	2.61	10.8	<0.2	<10	330	0.48	0.16	0.61	0.17	51.5	14.8	30
I100146		0.44	0.005	0.12	1.81	6.0	<0.2	<10	230	0.30	0.12	0.31	0.20	29.5	13.4	24
I100147		0.46	0.016	0.12	1.80	5.4	<0.2	<10	230	0.31	0.12	0.32	0.17	28.7	11.6	25
I100148		0.42	<0.005	0.21	2.37	7.8	<0.2	<10	210	0.49	0.14	0.35	0.11	46.3	14.1	28
I100149		0.36	<0.005	0.33	1.83	6.9	<0.2	<10	180	0.32	0.18	0.17	0.21	20.6	6.3	22
I100150		0.30	<0.005	0.21	2.07	6.0	<0.2	<10	220	0.38	0.24	0.29	0.16	33.0	8.9	23
I100201		0.42	0.008	0.08	1.58	9.1	<0.2	<10	290	0.43	0.16	0.65	0.15	32.5	9.8	28
I100202		0.42	0.007	0.07	2.00	4.9	<0.2	<10	210	0.47	0.14	0.81	0.13	61.4	9.1	23
I100203		0.34	0.035	0.11	3.35	5.8	<0.2	<10	290	0.94	0.15	0.49	0.17	79.1	9.4	25
I100204		Not Recvd														
I100205		0.34	<0.005	0.05	1.81	8.0	<0.2	<10	240	0.34	0.14	0.46	0.14	20.4	8.5	27
I100206		0.32	0.006	0.13	1.84	8.7	<0.2	<10	350	0.53	0.14	0.92	0.31	30.7	10.3	29
I100207		0.40	0.013	0.11	1.48	7.8	<0.2	<10	390	0.45	0.12	1.20	0.26	25.1	8.7	25
I100208		0.40	0.006	0.05	1.80	4.4	<0.2	<10	190	0.39	0.10	0.45	0.10	54.5	10.4	23
I100209		0.28	<0.005	0.15	2.27	6.8	<0.2	<10	450	0.49	0.18	1.11	1.44	41.4	11.8	32
I100210		0.54	0.005	0.07	1.59	7.8	<0.2	<10	180	0.48	0.14	0.54	0.11	36.2	9.4	28
I100211		0.38	0.007	0.05	1.67	8.2	<0.2	<10	290	0.52	0.15	0.43	0.05	37.4	8.4	28
I100212		0.44	<0.005	0.09	1.75	4.9	<0.2	<10	390	0.46	0.13	0.43	0.15	35.5	9.7	23
I100213		0.52	<0.005	0.04	2.42	9.2	<0.2	<10	210	0.63	0.17	0.12	0.10	35.0	11.1	40
I100214		0.44	<0.005	0.07	1.96	6.3	<0.2	<10	350	0.42	0.15	0.41	0.15	24.6	10.9	27
I100215		0.44	<0.005	0.05	2.08	9.3	<0.2	<10	230	0.43	0.13	0.20	0.07	28.8	9.1	32
I100216		0.40	<0.005	0.03	2.55	8.3	<0.2	<10	140	0.46	0.13	0.16	0.09	24.1	8.7	29
I100217		0.38	<0.005	0.05	1.74	8.3	<0.2	<10	190	0.43	0.14	0.25	0.05	26.7	9.7	29
I100218		0.42	<0.005	0.07	1.44	5.2	<0.2	<10	240	0.31	0.15	0.24	0.10	20.4	10.1	22
I100219		0.44	<0.005	0.12	1.76	8.8	<0.2	<10	270	0.46	0.17	0.27	0.10	21.9	12.1	29
I100220		0.44	<0.005	0.08	1.67	8.5	<0.2	<10	220	0.33	0.15	0.26	0.06	23.0	9.0	28
I100221		Not Recvd														
I100222		0.24	<0.005	0.11	2.21	12.7	<0.2	<10	210	0.63	0.26	0.55	0.12	27.1	15.5	27
I100223		0.22	<0.005	0.08	1.80	7.2	<0.2	<10	170	0.43	0.19	0.91	0.15	17.35	11.6	17
I100224		0.30	<0.005	0.06	2.09	5.4	<0.2	<10	150	0.39	0.23	0.63	0.10	11.70	14.5	16
I100225		0.34	<0.005	0.09	2.01	10.1	<0.2	<10	160	0.38	0.19	0.61	0.07	12.15	12.1	17
I100226		0.22	<0.005	0.07	1.92	4.1	<0.2	<10	130	0.25	0.15	0.44	0.14	10.50	8.2	15
I100227		0.36	0.006	0.04	1.85	5.1	<0.2	<10	140	0.36	0.12	0.58	0.10	12.30	12.7	15
I100228		0.16	0.007	0.11	1.31	3.2	<0.2	<10	100	0.16	0.12	0.28	0.09	10.85	5.2	18
I100229		0.24	0.021	0.16	0.89	3.1	<0.2	<10	100	0.22	0.09	0.27	0.13	10.30	4.6	13
I100230		0.44	0.005	0.07	1.65	6.1	<0.2	<10	90	0.19	0.15	0.29	0.09	11.35	7.0	21
I100231		0.28	<0.005	0.05	2.04	4.2	<0.2	<10	160	0.35	0.14	0.63	0.08	14.30	15.8	17
I100232		0.50	<0.005	0.05	1.80	7.0	<0.2	<10	190	0.76	0.35	0.43	0.12	51.3	12.4	20
I100233		0.28	0.008	0.08	2.08	6.8	<0.2	<10	170	0.34	0.19	0.71	0.10	12.45	11.0	19
I100234		0.30	<0.005	0.12	2.24	9.0	<0.2	<10	280	0.78	0.16	0.60	0.07	25.6	16.2	17

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I100145		1.13	23.6	3.70	8.07	0.07	0.03	0.05	0.029	0.15	29.2	21.6	0.71	954	1.67	0.02
I100146		0.95	13.7	2.80	6.45	0.06	0.02	0.14	0.021	0.07	16.5	15.6	0.56	646	0.77	0.02
I100147		0.93	13.2	2.67	6.09	0.05	0.02	0.03	0.019	0.07	16.5	15.4	0.55	542	0.72	0.01
I100148		0.80	16.4	3.60	8.11	0.06	0.03	0.02	0.025	0.14	26.5	25.5	0.72	1000	1.11	0.01
I100149		0.90	14.6	2.85	7.77	0.05	0.03	0.03	0.020	0.15	13.4	9.1	0.39	294	1.52	0.02
I100150		1.04	21.0	2.91	8.59	0.08	0.03	0.04	0.019	0.17	20.5	14.3	0.55	297	1.47	0.01
I100201		0.54	26.3	2.62	4.97	0.07	0.06	0.04	0.022	0.07	16.3	14.6	0.53	392	0.83	0.02
I100202		1.14	21.8	2.80	6.80	0.11	0.15	0.04	0.020	0.30	33.6	16.2	0.60	416	0.60	0.02
I100203		1.52	28.4	4.07	10.85	0.13	0.17	0.03	0.027	0.52	65.8	20.5	0.68	447	0.87	0.02
I100204																
I100205		0.62	12.0	2.61	6.14	<0.05	0.04	0.02	0.023	0.08	10.7	14.5	0.47	302	1.22	0.02
I100206		0.61	32.4	2.70	5.29	0.07	0.10	0.05	0.023	0.07	16.3	12.1	0.52	627	0.75	0.03
I100207		0.50	27.8	2.12	4.30	0.05	0.08	0.05	0.022	0.05	13.4	9.4	0.36	736	1.20	0.02
I100208		0.89	15.0	2.71	6.23	0.08	0.04	0.30	0.016	0.35	33.6	15.8	0.61	574	0.81	0.02
I100209		0.94	35.3	3.19	6.98	0.07	0.14	0.02	0.029	0.24	21.7	14.7	0.70	596	0.89	0.06
I100210		0.69	26.1	2.73	4.98	0.08	0.17	0.03	0.020	0.12	20.0	15.0	0.55	367	0.86	0.02
I100211		0.47	24.2	2.69	4.96	0.06	0.19	0.04	0.025	0.06	20.5	15.0	0.51	271	0.80	0.02
I100212		0.42	13.4	2.77	5.94	<0.05	0.05	0.02	0.022	0.21	22.8	10.5	0.42	1820	1.13	0.01
I100213		0.70	15.4	3.35	6.99	0.06	0.18	0.03	0.030	0.09	17.3	14.1	0.51	462	1.03	0.01
I100214		0.72	11.2	2.89	6.36	0.05	0.04	0.02	0.024	0.22	13.7	14.5	0.50	1320	0.95	0.01
I100215		0.84	14.1	3.15	6.08	0.06	0.06	0.02	0.024	0.20	18.7	17.6	0.56	549	0.85	0.01
I100216		0.98	11.7	3.39	7.37	0.05	0.06	0.01	0.022	0.14	14.7	18.5	0.56	306	0.93	0.01
I100217		0.42	13.9	2.63	5.49	<0.05	0.10	0.02	0.022	0.07	14.2	14.1	0.48	269	0.90	0.01
I100218		0.42	10.8	2.36	5.18	<0.05	0.03	0.01	0.018	0.07	10.8	9.4	0.37	1000	1.07	0.01
I100219		0.40	13.5	2.81	5.74	0.06	0.07	0.02	0.023	0.24	10.9	11.8	0.46	575	1.10	0.01
I100220		0.41	12.6	2.68	5.14	<0.05	0.06	0.01	0.020	0.14	12.9	11.3	0.48	388	1.01	0.01
I100221																
I100222		1.09	23.0	3.16	7.01	0.06	0.03	0.03	0.026	0.05	13.3	11.2	0.66	458	0.80	0.02
I100223		0.93	14.4	2.67	5.08	0.05	0.04	0.08	0.021	0.05	9.0	8.2	0.54	498	0.66	0.02
I100224		0.94	13.5	3.17	6.77	0.06	0.03	0.03	0.023	0.05	6.1	10.1	0.67	461	0.67	0.02
I100225		1.02	17.0	3.88	6.45	0.06	0.03	0.06	0.021	0.03	6.1	9.0	0.64	346	0.98	0.02
I100226		0.81	12.2	2.73	5.77	0.05	0.02	0.04	0.016	0.03	5.3	7.3	0.59	195	0.58	0.02
I100227		0.86	9.8	2.95	5.50	0.05	0.03	0.03	0.018	0.03	5.9	8.9	0.62	521	0.46	0.02
I100228		0.62	9.9	1.68	4.88	<0.05	0.02	0.04	0.014	0.04	5.5	5.8	0.34	110	0.42	0.02
I100229		0.48	14.2	1.59	2.63	<0.05	<0.02	0.07	0.011	0.03	5.2	2.6	0.18	86	0.76	0.02
I100230		0.84	9.5	2.48	5.81	0.05	<0.02	0.04	0.017	0.04	6.5	7.6	0.50	163	0.65	0.02
I100231		0.85	9.9	3.32	5.67	0.05	0.02	0.03	0.018	0.04	6.7	8.3	0.71	899	0.53	0.02
I100232		1.46	19.4	2.99	5.63	0.07	0.04	0.04	0.026	0.11	25.8	10.7	0.58	345	0.88	0.02
I100233		0.73	12.6	3.03	6.51	0.06	0.02	0.03	0.021	0.05	6.3	9.6	0.72	350	0.61	0.02
I100234		1.99	24.7	3.54	6.80	0.08	0.06	0.03	0.022	0.24	16.1	15.5	0.84	458	1.02	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I100145		2.46	22.8	770	8.2	24.2	<0.001	0.04	0.51	4.9	0.6	0.7	55.9	<0.01	0.05	4.2
I100146		1.93	14.6	610	6.4	20.0	<0.001	0.03	0.30	3.2	0.4	0.5	25.0	<0.01	0.03	1.9
I100147		1.70	13.9	620	6.3	18.0	<0.001	0.02	0.28	3.0	0.4	0.6	25.7	<0.01	0.03	1.7
I100148		2.21	18.4	470	7.5	24.7	<0.001	0.01	0.39	4.1	0.4	0.7	26.8	<0.01	0.03	6.2
I100149		2.20	13.2	500	8.6	23.8	<0.001	0.02	0.43	3.0	0.4	0.7	17.8	<0.01	0.04	2.6
I100150		2.94	15.3	510	8.6	36.3	<0.001	0.02	0.34	4.5	0.8	0.6	28.3	<0.01	0.07	5.0
I100201		1.38	22.2	710	7.7	8.3	0.001	0.01	0.49	5.1	0.7	0.9	46.5	<0.01	0.03	3.7
I100202		3.44	17.1	540	7.2	40.2	0.001	0.02	0.48	5.5	1.0	0.6	53.9	<0.01	0.03	10.9
I100203		4.90	19.3	690	8.7	65.3	<0.001	<0.01	0.39	7.6	0.8	0.9	37.9	<0.01	0.03	25.1
I100204																
I100205		1.67	14.7	290	7.7	12.3	<0.001	0.02	0.37	3.4	0.4	0.6	32.9	<0.01	0.03	2.5
I100206		1.38	25.4	660	7.5	9.3	<0.001	0.04	0.72	4.8	0.7	0.5	58.3	<0.01	0.04	2.6
I100207		1.01	23.2	1000	6.2	5.6	<0.001	0.08	0.60	3.2	1.2	0.4	83.0	<0.01	0.05	1.0
I100208		2.26	13.4	730	6.4	34.4	<0.001	0.03	0.25	4.3	0.4	0.5	33.0	<0.01	0.02	6.5
I100209		2.21	29.6	1110	8.8	21.2	<0.001	0.05	0.58	5.6	0.7	0.6	62.4	<0.01	0.04	6.0
I100210		1.38	21.1	670	7.9	11.4	<0.001	0.02	0.58	5.1	0.5	0.5	35.7	<0.01	0.03	4.8
I100211		1.11	18.4	400	8.4	7.2	<0.001	0.02	0.65	4.8	0.4	0.5	31.9	<0.01	0.03	5.5
I100212		1.34	15.9	860	6.9	18.4	<0.001	0.02	0.33	4.2	0.3	0.6	36.4	<0.01	0.03	8.8
I100213		1.10	22.0	370	9.2	14.2	<0.001	0.03	0.52	6.5	0.4	0.7	15.9	<0.01	0.04	5.5
I100214		1.78	17.5	720	7.9	22.7	<0.001	0.03	0.34	3.6	0.3	0.6	32.2	<0.01	0.03	3.7
I100215		1.56	19.2	360	7.3	22.2	<0.001	0.02	0.51	3.8	0.3	0.6	19.4	<0.01	0.03	6.0
I100216		2.38	17.8	340	7.6	19.9	<0.001	0.01	0.49	3.1	0.3	0.6	15.4	<0.01	0.03	7.0
I100217		1.28	17.9	160	7.9	9.2	<0.001	<0.01	0.47	4.0	0.3	0.5	26.0	<0.01	0.04	5.7
I100218		1.32	14.4	280	7.3	8.2	<0.001	0.01	0.36	3.2	0.2	0.5	23.0	<0.01	0.03	3.3
I100219		1.62	20.2	550	8.6	15.7	<0.001	0.01	0.52	4.3	0.4	0.5	23.9	<0.01	0.04	4.5
I100220		1.40	19.7	290	7.5	12.1	<0.001	<0.01	0.46	3.5	0.3	0.5	21.9	<0.01	0.03	4.4
I100221																
I100222		1.02	18.5	570	7.7	11.3	<0.001	0.03	0.31	6.4	0.7	0.6	36.0	<0.01	0.04	1.9
I100223		0.85	11.2	660	5.5	13.0	<0.001	0.06	0.37	4.8	0.6	0.5	52.4	<0.01	0.04	0.9
I100224		0.99	10.4	490	7.8	9.7	<0.001	0.03	0.21	5.8	0.5	0.6	39.9	<0.01	0.04	1.3
I100225		0.92	10.8	580	8.9	6.4	0.001	0.06	0.22	5.0	0.6	0.5	38.9	<0.01	0.04	0.8
I100226		0.87	9.3	410	5.7	5.5	<0.001	0.03	0.17	4.5	0.4	0.4	29.1	<0.01	0.04	0.7
I100227		0.81	9.1	470	5.1	6.4	<0.001	0.03	0.19	5.3	0.4	0.5	33.9	<0.01	0.03	1.1
I100228		0.83	10.2	570	5.4	6.3	<0.001	0.06	0.18	2.9	0.6	0.4	20.8	<0.01	0.03	0.4
I100229		0.49	8.3	1100	3.5	4.0	<0.001	0.10	0.17	1.6	0.8	0.2	21.4	<0.01	0.05	<0.2
I100230		0.90	11.3	660	7.4	7.2	<0.001	0.04	0.18	2.8	0.5	0.4	18.5	<0.01	0.05	0.7
I100231		0.75	9.5	560	5.9	7.8	<0.001	0.03	0.18	5.1	0.5	0.5	34.5	<0.01	0.03	1.2
I100232		0.93	14.0	570	27.2	14.9	0.001	0.02	0.28	6.4	0.7	0.8	28.4	<0.01	0.04	10.2
I100233		0.90	11.6	470	8.8	7.5	0.001	0.04	0.20	4.9	0.6	0.5	42.3	<0.01	0.03	1.1
I100234		1.07	12.5	450	6.7	25.3	<0.001	0.02	0.26	6.7	0.7	0.6	38.3	0.01	0.04	2.9

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I100145		0.113	0.16	5.05	74	0.23	7.14	72	1.1
I100146		0.096	0.12	0.65	57	0.18	5.47	56	0.7
I100147		0.090	0.12	0.69	55	0.46	5.01	56	0.6
I100148		0.097	0.12	0.73	70	0.24	5.58	69	1.1
I100149		0.112	0.14	0.43	61	0.21	2.42	49	1.1
I100150		0.124	0.14	0.82	57	0.25	4.66	58	1.3
I100201		0.085	0.06	0.80	55	0.38	9.06	51	2.3
I100202		0.127	0.18	2.33	53	0.24	10.15	64	6.5
I100203		0.149	0.30	1.94	64	0.13	9.36	76	7.8
I100204									
I100205		0.085	0.08	0.48	58	0.19	3.49	47	1.5
I100206		0.090	0.07	1.38	55	0.29	10.80	55	3.9
I100207		0.055	0.05	1.59	45	0.23	9.09	37	2.7
I100208		0.110	0.16	2.08	55	0.19	9.55	57	1.4
I100209		0.109	0.13	0.85	59	0.25	9.05	106	5.3
I100210		0.107	0.10	0.86	59	0.33	11.35	59	7.2
I100211		0.092	0.06	0.75	54	0.18	9.13	56	7.9
I100212		0.069	0.13	0.72	52	0.16	4.93	56	2.1
I100213		0.100	0.09	0.71	71	0.20	4.80	73	6.8
I100214		0.098	0.12	0.41	60	0.19	2.93	67	1.4
I100215		0.106	0.13	0.54	65	0.18	3.22	56	2.4
I100216		0.116	0.14	0.37	70	0.17	2.15	76	2.2
I100217		0.075	0.07	0.67	54	0.16	2.80	37	4.0
I100218		0.073	0.08	0.42	53	0.14	2.22	40	1.3
I100219		0.088	0.09	0.50	59	0.19	2.66	57	2.6
I100220		0.093	0.07	0.42	59	0.19	2.67	46	3.0
I100221									
I100222		0.077	0.08	1.03	68	0.14	8.50	54	1.0
I100223		0.058	0.06	0.72	56	0.11	8.04	50	1.1
I100224		0.073	0.08	0.61	72	0.34	4.94	61	0.9
I100225		0.078	0.08	0.56	83	0.11	4.22	53	0.9
I100226		0.082	0.07	0.44	59	0.09	3.44	50	0.7
I100227		0.069	0.06	0.42	63	0.08	4.91	50	1.0
I100228		0.064	0.06	0.42	28	0.08	2.77	31	0.5
I100229		0.029	0.04	0.66	24	0.05	3.06	19	<0.5
I100230		0.072	0.07	0.43	59	0.11	2.81	42	0.5
I100231		0.068	0.06	0.50	70	0.09	4.74	56	0.6
I100232		0.072	0.11	2.38	60	0.17	12.35	65	1.1
I100233		0.080	0.07	0.58	69	0.11	3.91	58	0.7
I100234		0.128	0.19	1.96	76	0.15	15.40	50	1.5

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I100235		0.28	<0.005	0.20	1.78	104.5	<0.2	<10	260	0.48	0.28	0.73	0.32	26.3	11.5	21
I100236		0.26	0.011	0.23	1.62	87.9	<0.2	<10	300	0.48	0.21	1.52	1.10	24.0	10.4	18
I100237		0.36	0.005	0.14	1.97	44.5	<0.2	<10	270	0.44	0.20	0.72	0.21	20.9	16.6	22
I100238		0.42	<0.005	0.07	2.34	7.8	<0.2	<10	230	0.47	0.18	0.57	0.14	20.6	23.4	22
I100239		0.52	0.007	0.06	1.56	5.2	<0.2	<10	90	0.29	0.14	0.27	0.09	14.05	8.2	16
I100240		0.34	<0.005	0.08	1.74	4.4	<0.2	<10	110	0.26	0.19	0.26	0.12	15.15	7.7	20
I100241		0.30	0.018	0.07	1.50	4.4	<0.2	<10	100	0.20	0.15	0.26	0.09	13.65	6.1	19
I100242		0.30	0.010	0.09	1.21	4.9	<0.2	<10	110	0.23	0.10	0.24	0.11	15.10	4.6	13
I100243		Not Recvd														
I100244		0.40	0.006	0.06	1.84	3.9	<0.2	<10	140	0.25	0.14	0.37	0.10	13.05	11.5	22
I100245		0.42	<0.005	0.05	1.77	4.2	<0.2	<10	160	0.28	0.12	0.49	0.09	13.40	11.3	21
I100246		0.54	0.005	0.05	1.90	3.8	<0.2	<10	150	0.27	0.13	0.63	0.09	13.10	8.6	18
I100247		0.42	0.005	0.07	2.04	4.3	<0.2	<10	170	0.35	0.12	0.55	0.10	14.70	13.2	20
I100248		0.36	0.007	0.06	2.01	3.4	<0.2	<10	170	0.35	0.12	0.68	0.10	14.65	9.5	22
I100249		0.38	<0.005	0.07	2.05	5.1	<0.2	<10	180	0.41	0.20	0.87	0.16	15.20	11.3	19
I100250		0.32	<0.005	0.11	2.11	4.6	<0.2	<10	200	0.36	0.15	0.72	0.11	15.30	12.3	21
I100276		0.56	<0.005	0.04	2.18	10.2	<0.2	<10	140	0.33	0.13	0.16	0.09	16.15	11.4	19
I100277		0.40	<0.005	0.05	1.34	6.0	<0.2	<10	210	0.19	0.17	0.13	0.15	17.50	6.9	20
I100278		0.48	<0.005	0.10	2.07	5.1	<0.2	<10	170	0.30	0.12	0.20	0.11	27.8	11.8	17
I100279		0.50	<0.005	0.12	2.74	7.1	<0.2	<10	240	0.95	0.17	0.27	0.09	51.3	18.2	21
I100280		0.50	<0.005	0.06	2.23	7.4	<0.2	<10	200	0.27	0.11	0.24	0.08	22.4	9.5	22
I100281		0.44	<0.005	0.08	1.44	5.1	<0.2	<10	200	0.14	0.13	0.24	0.07	15.60	8.3	19
I100282		0.44	<0.005	0.06	1.74	6.0	<0.2	<10	170	0.25	0.11	0.19	0.06	29.4	7.7	21
I100283		0.50	<0.005	0.11	1.31	3.5	<0.2	<10	130	0.17	0.12	0.13	0.12	18.85	7.6	20
I100284		0.44	0.005	0.07	1.81	5.8	<0.2	<10	230	0.31	0.10	0.42	0.07	23.0	9.1	23
I100285		0.38	<0.005	0.05	1.74	5.6	<0.2	<10	170	0.18	0.10	0.23	0.07	15.80	7.8	18
I100286		0.28	0.009	0.08	2.16	5.7	<0.2	<10	360	0.41	0.11	0.52	0.16	101.0	13.6	22
I100287		0.46	0.005	0.11	1.48	3.6	<0.2	<10	130	0.23	0.08	0.22	0.11	30.3	5.8	16
I100288		0.36	0.017	0.02	1.53	5.8	<0.2	<10	120	0.21	0.12	0.14	0.06	18.70	5.9	21
I100289		0.50	<0.005	0.03	2.24	1.4	<0.2	<10	130	0.42	0.04	0.19	0.05	75.7	9.7	10
I100290		0.44	<0.005	0.08	1.79	2.7	<0.2	<10	140	0.33	0.05	0.17	0.08	28.8	7.5	12
I100291		0.42	NSS	0.16	2.28	4.1	<0.2	<10	200	0.47	0.10	0.29	0.14	52.7	7.5	17
I100292		0.46	0.006	0.13	1.86	4.5	<0.2	<10	170	0.25	0.10	0.25	0.12	36.5	7.7	18
I100293		0.52	0.008	0.16	2.32	6.9	<0.2	<10	180	0.31	0.16	0.24	0.14	36.9	10.6	26
I100294		0.34	<0.005	0.11	1.35	4.3	<0.2	<10	110	0.17	0.15	0.19	0.14	24.8	5.5	16
I100295		0.42	<0.005	0.07	2.02	9.3	<0.2	<10	210	0.37	0.19	0.22	0.15	33.8	12.5	32
I100296		0.38	0.008	0.13	1.28	3.2	<0.2	<10	120	0.17	0.12	0.16	0.14	28.4	4.7	15
I100297		0.28	0.024	0.14	1.76	4.2	<0.2	<10	150	0.23	0.12	0.19	0.11	29.8	6.6	19
I100298		0.20	NSS	0.17	1.42	3.9	<0.2	<10	160	0.33	0.09	0.23	0.16	41.9	6.5	15
I100299		0.32	NSS	0.20	1.47	3.3	<0.2	<10	190	0.36	0.11	0.37	0.23	37.4	4.7	16

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I100235		1.24	22.8	2.87	5.31	0.06	0.05	0.03	0.025	0.11	14.8	11.7	0.60	441	1.42	0.02
I100236		1.11	32.4	2.51	4.56	0.07	0.05	0.08	0.023	0.10	14.0	9.2	0.56	522	1.29	0.02
I100237		1.20	21.0	3.05	6.01	0.06	0.03	0.05	0.022	0.10	10.1	11.6	0.70	907	1.17	0.02
I100238		1.04	13.6	3.66	6.82	0.07	0.02	0.03	0.024	0.05	9.7	11.1	0.74	983	0.63	0.02
I100239		0.86	11.3	2.51	5.07	0.05	0.02	0.04	0.016	0.04	7.3	7.8	0.49	268	0.75	0.02
I100240		1.11	13.0	2.24	5.91	0.05	0.02	0.04	0.018	0.04	8.0	8.6	0.48	158	0.67	0.02
I100241		0.93	11.8	2.11	4.92	0.05	0.02	0.04	0.016	0.04	7.1	6.5	0.40	136	0.52	0.02
I100242		0.57	13.5	2.83	3.24	0.05	0.02	0.05	0.014	0.02	7.6	3.1	0.18	104	0.67	0.02
I100243																
I100244		0.74	11.4	2.44	5.93	<0.05	0.02	0.03	0.018	0.03	6.3	8.5	0.53	397	0.66	0.02
I100245		0.71	12.2	2.63	5.54	0.05	0.02	0.03	0.020	0.03	6.4	8.6	0.57	354	0.66	0.02
I100246		0.63	11.4	2.71	6.00	0.06	0.03	0.03	0.019	0.03	6.3	9.0	0.63	185	0.50	0.02
I100247		0.65	13.0	2.86	6.05	0.06	0.03	0.04	0.020	0.03	7.2	9.3	0.67	443	0.52	0.02
I100248		0.72	14.1	2.60	6.07	0.05	0.04	0.04	0.021	0.03	7.1	9.7	0.64	207	0.42	0.02
I100249		0.90	15.2	3.09	6.26	0.07	0.04	0.04	0.023	0.05	7.3	10.1	0.64	349	0.68	0.03
I100250		1.05	15.7	3.08	6.41	0.05	0.02	0.06	0.023	0.04	7.3	9.3	0.60	502	0.86	0.02
I100276		0.81	10.5	3.50	8.20	0.06	0.03	0.01	0.018	0.20	8.6	15.0	0.68	419	1.09	0.01
I100277		0.54	8.5	2.39	5.92	0.05	0.02	0.02	0.013	0.10	8.4	10.1	0.37	975	0.92	0.01
I100278		1.64	11.1	3.24	8.32	0.08	0.03	0.02	0.013	0.59	15.5	21.4	0.79	550	0.87	0.01
I100279		1.33	17.6	3.71	9.75	0.08	0.04	0.03	0.024	0.34	36.5	18.9	0.68	1070	1.42	0.02
I100280		1.03	10.8	3.78	8.08	<0.05	0.03	0.02	0.017	0.42	12.7	18.2	0.81	485	0.91	<0.01
I100281		0.85	9.1	2.65	6.13	<0.05	0.04	0.01	0.013	0.24	7.9	10.5	0.55	606	0.88	0.01
I100282		0.94	10.3	2.93	5.91	<0.05	0.04	0.02	0.017	0.32	19.7	14.3	0.59	311	1.06	0.01
I100283		0.48	10.9	2.52	5.09	<0.05	0.04	0.01	0.014	0.17	9.6	11.5	0.42	421	1.02	0.01
I100284		0.87	18.5	2.89	5.54	<0.05	0.19	0.03	0.020	0.24	13.6	17.7	0.66	402	0.64	0.02
I100285		0.82	9.4	2.89	6.27	<0.05	0.05	0.02	0.013	0.23	8.2	18.6	0.63	346	1.16	0.01
I100286		1.16	25.6	3.46	7.25	0.07	0.07	0.03	0.022	0.28	69.9	18.0	0.73	1500	1.29	0.02
I100287		0.74	9.1	2.31	5.07	<0.05	0.02	0.05	0.013	0.11	19.2	11.8	0.47	229	0.64	0.01
I100288		0.66	9.9	2.41	5.56	<0.05	0.02	0.02	0.018	0.04	10.4	11.9	0.37	182	0.78	<0.01
I100289		1.58	7.7	3.51	9.63	0.07	0.03	0.02	0.008	0.95	72.4	19.0	0.88	571	0.70	<0.01
I100290		1.02	8.7	2.81	6.05	<0.05	0.04	0.03	0.011	0.40	20.3	11.7	0.63	375	0.52	<0.01
I100291		0.93	11.9	3.03	7.50	<0.05	0.05	0.06	0.017	0.30	33.2	13.2	0.54	361	0.83	0.01
I100292		0.84	9.8	2.88	6.57	<0.05	0.03	0.05	0.016	0.18	25.4	13.9	0.59	350	0.78	0.01
I100293		0.90	12.5	3.25	8.40	<0.05	0.03	0.06	0.025	0.12	30.0	16.9	0.61	448	0.94	0.01
I100294		0.76	13.6	2.16	6.91	<0.05	0.03	0.02	0.012	0.11	17.0	9.5	0.42	222	0.77	0.01
I100295		0.76	20.3	3.25	7.14	<0.05	0.02	0.04	0.029	0.07	20.5	16.2	0.58	633	1.04	0.01
I100296		0.60	10.8	1.90	6.36	<0.05	0.02	0.03	0.014	0.08	21.7	8.1	0.36	181	0.77	0.01
I100297		0.73	10.9	2.54	6.80	<0.05	0.03	0.04	0.018	0.07	19.5	14.0	0.48	256	0.70	<0.01
I100298		0.65	12.9	2.30	5.47	<0.05	0.02	0.04	0.014	0.15	30.0	11.0	0.45	314	0.78	0.01
I100299		0.83	14.4	2.00	5.87	<0.05	0.02	0.06	0.018	0.12	27.9	8.6	0.33	225	0.90	0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I100235		0.86	17.5	360	13.7	12.4	0.001	0.02	0.63	5.0	0.9	0.8	39.0	<0.01	0.06	3.7
I100236		0.73	18.4	720	10.0	13.6	0.002	0.09	0.83	4.3	1.6	0.5	73.9	0.01	0.05	1.3
I100237		0.87	16.0	630	9.9	14.1	<0.001	0.04	0.42	4.8	1.1	0.5	42.5	<0.01	0.04	1.4
I100238		0.92	14.1	670	7.8	12.1	<0.001	0.05	0.23	6.2	0.6	0.6	37.3	<0.01	0.03	1.5
I100239		0.85	9.9	560	12.5	7.2	<0.001	0.04	0.20	3.1	0.5	0.4	18.4	<0.01	0.04	1.2
I100240		0.94	12.5	480	9.4	9.1	<0.001	0.03	0.26	3.2	0.4	0.5	19.9	<0.01	0.04	0.9
I100241		0.90	11.2	530	6.2	7.5	<0.001	0.05	0.17	2.7	0.6	0.5	18.9	<0.01	0.04	0.5
I100242		0.75	8.7	690	4.0	4.7	<0.001	0.07	0.16	2.3	0.7	0.3	18.4	<0.01	0.04	0.4
I100243																
I100244		0.93	13.0	500	5.6	6.4	<0.001	0.03	0.18	4.2	0.4	0.6	23.7	<0.01	0.03	0.8
I100245		0.89	13.1	500	4.8	5.3	<0.001	0.03	0.19	4.9	0.4	0.6	32.5	<0.01	0.03	1.0
I100246		0.76	10.4	540	5.1	5.8	<0.001	0.04	0.18	5.7	0.4	0.7	36.6	<0.01	0.03	0.9
I100247		0.84	11.8	550	5.2	6.2	<0.001	0.03	0.21	5.6	0.5	0.4	33.2	<0.01	0.04	1.3
I100248		0.91	13.0	570	5.1	6.5	<0.001	0.06	0.22	5.3	0.5	0.4	40.0	<0.01	0.02	0.9
I100249		0.85	12.0	650	6.0	7.3	<0.001	0.05	0.26	6.5	0.7	0.6	47.5	<0.01	0.03	1.1
I100250		0.79	12.6	770	5.2	6.2	<0.001	0.05	0.23	5.7	0.6	0.5	43.1	<0.01	0.04	0.6
I100276		3.64	13.3	460	7.0	30.4	<0.001	0.01	0.32	3.6	0.4	0.6	14.5	<0.01	0.04	4.5
I100277		1.85	10.8	370	7.3	14.4	<0.001	0.01	0.32	2.4	0.3	0.5	12.5	<0.01	0.03	3.0
I100278		5.52	11.4	370	5.6	66.6	<0.001	0.01	0.26	3.2	0.3	0.6	17.7	<0.01	0.04	7.6
I100279		4.29	13.1	1120	10.2	48.8	<0.001	0.01	0.27	3.6	0.5	0.6	25.8	<0.01	0.04	11.1
I100280		4.35	13.5	600	10.0	46.3	<0.001	<0.01	0.36	3.3	0.2	0.5	20.6	<0.01	0.02	5.8
I100281		3.41	10.3	270	7.5	33.5	<0.001	0.01	0.27	2.4	<0.2	0.5	21.7	<0.01	0.02	3.4
I100282		3.83	12.4	230	6.3	40.0	<0.001	0.01	0.36	2.9	0.2	0.4	18.1	<0.01	0.02	4.2
I100283		2.75	11.0	260	5.8	18.1	<0.001	0.04	0.38	2.4	<0.2	0.4	11.3	<0.01	0.01	3.2
I100284		3.15	14.9	530	6.2	29.0	<0.001	0.05	0.45	4.3	0.3	0.4	28.9	<0.01	0.02	7.3
I100285		4.02	10.9	290	6.7	29.7	<0.001	<0.01	0.28	2.6	<0.2	0.4	19.0	<0.01	0.02	4.1
I100286		5.18	18.2	640	6.6	27.3	<0.001	0.02	0.41	5.0	0.6	0.4	41.8	<0.01	0.03	9.6
I100287		2.47	8.9	510	5.5	19.3	<0.001	0.03	0.21	2.2	0.3	0.4	19.6	<0.01	0.02	1.8
I100288		1.67	11.0	320	6.7	9.0	<0.001	<0.01	0.28	2.4	<0.2	0.4	13.2	<0.01	0.02	1.3
I100289		5.28	5.3	360	4.1	86.5	<0.001	0.01	0.10	2.8	0.2	0.5	21.1	<0.01	0.01	7.0
I100290		4.76	6.1	440	4.7	37.3	<0.001	0.02	0.16	2.4	0.3	0.4	15.9	<0.01	0.01	4.0
I100291		3.83	9.0	670	6.5	37.8	<0.001	0.05	0.24	3.3	0.4	0.6	25.2	<0.01	0.02	3.9
I100292		3.37	9.8	570	5.7	24.4	<0.001	0.05	0.24	3.1	0.4	0.5	22.0	<0.01	0.02	3.6
I100293		2.96	13.2	660	8.6	21.5	<0.001	0.06	0.29	3.5	0.4	0.6	21.1	<0.01	0.03	3.2
I100294		2.98	10.7	230	7.8	25.3	<0.001	0.01	0.22	2.5	0.2	0.5	17.8	<0.01	0.02	2.7
I100295		1.16	21.6	590	9.9	16.4	<0.001	0.01	0.49	2.6	0.3	1.9	20.3	<0.01	0.03	0.9
I100296		2.26	8.4	300	6.6	17.1	<0.001	0.01	0.21	2.0	0.2	0.5	17.0	<0.01	0.01	1.7
I100297		3.25	10.2	380	7.2	14.3	<0.001	0.01	0.26	3.1	0.3	0.5	19.0	<0.01	0.02	3.0
I100298		2.46	9.4	540	6.4	20.6	<0.001	0.02	0.25	2.5	0.3	0.4	19.9	<0.01	0.02	2.6
I100299		2.24	8.7	600	6.7	21.5	<0.001	0.07	0.25	2.2	0.4	0.5	31.3	<0.01	0.02	1.1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I100235		0.075	0.09	1.24	58	0.17	8.67	85	1.5
I100236		0.053	0.08	1.46	48	0.12	13.90	85	1.6
I100237		0.087	0.11	1.03	66	0.15	6.89	73	0.9
I100238		0.070	0.09	0.73	78	0.10	7.41	68	0.8
I100239		0.063	0.07	0.83	53	0.28	3.36	42	<0.5
I100240		0.067	0.09	0.85	47	0.39	3.66	45	<0.5
I100241		0.060	0.07	0.70	37	0.10	3.33	38	0.5
I100242		0.041	0.06	0.74	34	0.10	4.07	20	0.7
I100243									
I100244		0.075	0.07	0.43	62	0.13	3.10	46	0.6
I100245		0.074	0.07	0.44	62	0.11	4.01	46	0.8
I100246		0.061	0.05	0.45	60	0.12	4.54	49	1.1
I100247		0.079	0.07	0.52	68	0.09	5.10	49	1.1
I100248		0.071	0.07	0.50	62	0.09	4.83	48	1.1
I100249		0.066	0.06	0.66	64	0.09	6.62	61	1.5
I100250		0.068	0.07	0.67	70	0.11	5.71	54	0.6
I100276		0.150	0.17	0.47	75	0.19	2.37	54	1.1
I100277		0.095	0.10	0.30	59	0.18	1.63	36	1.0
I100278		0.186	0.32	0.58	69	0.17	2.76	60	1.2
I100279		0.147	0.19	0.96	77	0.16	4.39	63	1.7
I100280		0.169	0.24	0.43	80	0.17	2.09	85	1.3
I100281		0.144	0.14	0.30	64	0.15	1.87	47	1.3
I100282		0.147	0.19	0.53	64	0.18	3.35	47	1.5
I100283		0.109	0.11	0.31	55	0.35	2.04	48	1.4
I100284		0.144	0.18	0.92	58	0.20	6.22	54	7.4
I100285		0.150	0.17	0.38	63	0.18	2.16	49	1.9
I100286		0.159	0.18	1.36	72	0.24	10.90	76	2.6
I100287		0.085	0.11	0.86	43	0.15	3.12	53	0.7
I100288		0.081	0.10	0.44	55	0.21	2.50	42	0.7
I100289		0.183	0.39	1.34	64	0.11	4.60	76	0.7
I100290		0.141	0.22	1.25	52	0.13	3.33	62	1.2
I100291		0.121	0.19	2.11	58	0.21	5.48	67	1.7
I100292		0.119	0.14	1.37	57	0.20	3.95	65	1.1
I100293		0.109	0.14	1.92	66	0.17	4.28	77	1.1
I100294		0.119	0.12	0.70	51	0.14	2.43	52	0.9
I100295		0.070	0.11	0.83	69	0.23	5.04	64	0.6
I100296		0.096	0.11	0.72	44	0.13	2.57	41	0.6
I100297		0.110	0.14	0.88	52	0.19	3.31	54	1.0
I100298		0.090	0.10	1.19	47	0.16	4.18	51	0.6
I100299		0.068	0.10	1.29	39	0.11	4.24	47	0.6

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I100300		0.36	0.012	0.20	2.79	8.3	<0.2	<10	270	0.34	0.23	0.31	0.17	45.8	10.9	29
I100301		0.26	0.008	0.09	1.58	3.8	<0.2	<10	130	0.29	0.12	0.14	0.13	25.8	5.2	15
I100302		0.46	0.005	0.14	1.62	5.0	<0.2	<10	120	0.32	0.12	0.13	0.24	24.5	6.0	19
I100303		0.34	0.005	0.06	1.42	6.7	<0.2	<10	90	0.22	0.17	0.08	0.09	18.15	4.2	19
I100304		0.48	0.006	0.04	1.48	9.1	<0.2	<10	70	0.17	0.20	0.08	0.13	19.70	4.4	25
I100305		0.36	<0.005	0.05	2.91	10.8	<0.2	<10	150	0.50	0.17	0.13	0.11	26.5	11.0	32
I100306		0.18	<0.005	0.08	2.35	7.6	<0.2	<10	110	0.41	0.15	0.17	0.13	25.0	8.7	24
I100307		0.32	0.006	0.06	1.75	7.7	<0.2	<10	180	0.27	0.15	0.19	0.11	29.9	10.5	28
I100308		Not Recvd														
I100309		0.40	<0.005	0.17	1.64	7.6	<0.2	<10	170	0.23	0.14	0.13	0.07	21.1	5.8	26
I100310		0.26	<0.005	0.37	1.55	6.8	<0.2	<10	240	0.33	0.17	0.21	0.19	31.0	7.2	24
I100311		0.30	<0.005	0.83	1.47	33.1	<0.2	<10	260	0.29	0.33	0.37	0.40	17.40	5.6	21
I100312		0.40	<0.005	0.88	2.20	34.2	<0.2	<10	250	0.33	0.57	0.16	0.55	19.35	11.3	30
I100313		0.38	<0.005	1.40	2.35	332	<0.2	<10	220	0.37	0.34	0.19	0.82	16.85	9.2	32
I100314		0.36	<0.005	1.74	2.98	55.0	<0.2	<10	250	0.45	0.26	0.20	0.65	20.9	13.1	40
I100315		0.32	0.005	0.57	1.16	12.1	<0.2	<10	320	0.43	0.16	0.92	0.29	35.0	5.8	13
I100316		0.22	0.006	0.31	0.47	52.0	<0.2	<10	160	0.16	0.15	0.93	0.89	10.15	2.5	10
I100317		0.28	0.022	0.59	0.68	34.8	<0.2	<10	190	0.29	0.14	0.77	1.27	23.2	5.1	13
I100318		0.28	0.019	0.19	1.12	105.0	<0.2	<10	80	0.20	0.61	0.18	0.46	27.0	8.6	27
I100319		0.46	<0.005	0.60	2.29	186.0	<0.2	<10	190	0.50	0.89	0.33	1.05	38.9	15.8	50
I100320		0.56	<0.005	0.34	2.21	62.7	<0.2	<10	170	0.41	0.54	0.34	1.24	33.6	13.0	39
I100321		0.26	<0.005	0.20	1.89	277	<0.2	<10	230	0.34	0.39	0.48	1.49	26.0	9.9	36
I100322		0.34	<0.005	0.45	1.52	65.0	<0.2	<10	270	0.25	0.30	0.45	1.26	32.2	56.2	48
I100323		0.32	0.007	0.21	1.83	19.3	<0.2	<10	180	0.27	0.34	0.52	0.58	28.7	8.9	43
I100324		0.28	0.006	0.44	1.54	185.5	<0.2	<10	520	0.31	0.46	0.50	2.55	68.9	89.5	37
I100325		0.28	0.010	0.46	1.39	180.5	<0.2	<10	240	0.23	0.31	0.47	0.84	23.1	22.3	37
I100326		0.44	<0.005	0.10	2.21	48.6	<0.2	<10	210	0.28	0.38	0.33	0.19	15.20	10.0	53
I100327		0.36	0.006	0.18	1.51	133.5	<0.2	<10	240	0.26	0.42	0.54	0.16	18.00	28.1	37
I100328		0.24	<0.005	0.07	0.89	18.6	<0.2	<10	80	0.14	0.17	0.08	0.40	8.53	3.9	19
I100329		0.34	<0.005	0.18	0.71	10.2	<0.2	<10	100	0.11	0.21	0.08	0.21	10.90	3.8	15
I100330		0.22	<0.005	0.15	0.50	6.7	<0.2	<10	60	0.09	0.13	0.06	0.75	7.20	3.7	11
I100331		0.42	<0.005	0.18	1.81	14.9	<0.2	<10	140	0.24	0.22	0.14	0.26	19.70	7.9	39
I100332		0.38	<0.005	0.11	1.48	8.6	<0.2	<10	200	0.23	0.17	0.11	0.45	18.75	8.5	36
I100333		0.34	<0.005	0.14	2.35	39.0	<0.2	<10	170	0.51	0.75	0.27	1.02	37.6	23.0	55
I100334		0.42	<0.005	0.20	2.11	38.5	<0.2	<10	170	0.46	0.60	0.23	0.98	32.0	17.5	47
I100335		0.62	<0.005	0.21	2.28	9.2	<0.2	<10	230	0.46	0.35	0.36	0.37	36.2	11.3	51
I100336		0.42	<0.005	0.16	1.49	5.5	<0.2	<10	220	0.24	0.18	0.74	0.34	22.3	16.6	32
I100337		0.38	<0.005	0.17	2.45	4.8	<0.2	<10	170	0.48	0.21	0.52	0.21	53.6	13.4	81
I100338		0.46	<0.005	0.46	2.46	65.6	<0.2	<10	180	0.45	0.48	0.81	0.82	27.7	23.7	101
I100339		0.42	<0.005	0.37	2.32	75.4	<0.2	<10	140	0.58	0.48	0.35	0.85	26.9	19.5	78

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I100300		1.36	17.7	4.02	11.95	<0.05	0.04	0.05	0.025	0.17	30.9	17.1	0.73	502	1.50	0.02
I100301		0.55	8.9	2.27	6.49	<0.05	<0.02	0.03	0.014	0.10	16.6	10.5	0.35	222	0.84	0.01
I100302		0.60	17.3	2.41	5.14	<0.05	<0.02	0.04	0.022	0.13	15.7	11.0	0.34	244	0.92	0.01
I100303		0.73	9.0	2.59	7.24	<0.05	0.02	0.01	0.018	0.05	10.0	10.7	0.28	166	1.09	0.01
I100304		0.83	8.9	3.37	7.61	<0.05	0.02	0.03	0.024	0.06	9.9	12.5	0.33	184	1.44	0.01
I100305		1.14	13.4	4.19	8.95	<0.05	0.03	0.04	0.032	0.12	13.1	26.4	0.65	455	1.27	0.01
I100306		1.22	12.9	3.46	8.96	<0.05	0.02	0.05	0.026	0.16	9.1	19.5	0.54	568	1.35	0.01
I100307		0.65	15.3	2.82	5.99	<0.05	<0.02	0.03	0.023	0.06	17.8	14.0	0.50	549	0.89	<0.01
I100308																
I100309		0.65	11.3	2.74	6.27	<0.05	0.04	0.02	0.019	0.04	12.1	14.3	0.45	241	0.94	<0.01
I100310		0.77	23.3	2.59	6.23	<0.05	0.03	0.04	0.021	0.07	18.1	8.3	0.38	471	1.34	0.01
I100311		0.71	23.8	2.66	6.01	<0.05	<0.02	0.02	0.021	0.11	8.8	11.0	0.33	263	1.97	0.02
I100312		0.97	26.0	3.24	7.05	<0.05	0.03	0.04	0.030	0.07	9.8	14.1	0.45	480	1.55	0.01
I100313		1.41	25.3	3.38	8.07	<0.05	0.03	0.04	0.030	0.06	8.7	15.8	0.48	428	1.96	<0.01
I100314		2.11	37.4	3.69	8.11	<0.05	0.06	0.07	0.035	0.07	10.2	19.3	0.59	469	2.33	0.01
I100315		1.91	34.5	1.40	3.16	<0.05	0.04	0.10	0.018	0.04	32.6	5.2	0.14	433	0.89	0.02
I100316		1.01	27.5	0.84	1.40	<0.05	0.02	0.11	0.012	0.04	6.9	2.1	0.13	114	1.28	0.02
I100317		1.55	30.6	0.95	2.04	0.08	0.02	0.11	0.010	0.04	13.2	2.8	0.17	240	1.15	0.03
I100318		3.00	43.0	2.55	5.14	0.08	<0.02	0.03	0.026	0.07	13.4	7.7	0.45	324	3.58	0.02
I100319		3.55	63.9	4.40	6.87	0.13	0.05	0.05	0.042	0.07	18.7	18.8	0.89	533	4.35	0.01
I100320		2.43	42.8	3.19	6.97	0.12	0.04	0.04	0.033	0.07	16.0	17.9	0.83	1020	2.05	0.01
I100321		1.58	35.1	3.63	5.92	0.11	0.04	0.06	0.026	0.05	12.7	13.1	0.63	1670	3.34	0.02
I100322		1.65	36.5	3.07	5.39	0.08	0.03	0.06	0.021	0.07	11.2	8.4	0.65	6910	4.79	0.02
I100323		1.53	32.4	2.23	5.71	0.11	0.04	0.05	0.034	0.06	14.2	12.2	0.71	394	1.04	0.02
I100324		1.20	35.0	5.60	7.20	0.13	0.03	0.05	0.047	0.04	13.2	6.3	0.36	21200	11.35	0.02
I100325		1.64	39.3	3.58	5.27	0.11	0.02	0.06	0.021	0.07	11.2	6.9	0.50	978	5.98	0.02
I100326		1.70	29.7	2.69	7.19	0.08	0.04	0.05	0.028	0.07	7.7	17.6	0.79	216	1.80	0.01
I100327		1.04	31.5	3.59	5.34	0.12	0.03	0.05	0.025	0.04	8.9	9.3	0.45	1020	2.62	0.02
I100328		0.78	20.7	1.74	5.61	<0.05	<0.02	0.02	0.010	0.04	4.2	4.1	0.18	120	1.35	0.02
I100329		0.57	14.0	1.87	6.66	<0.05	<0.02	0.03	0.009	0.04	5.4	2.4	0.10	214	1.59	0.01
I100330		0.58	17.1	1.19	4.02	<0.05	<0.02	0.04	0.007	0.04	3.5	1.7	0.07	86	0.93	0.02
I100331		1.52	28.6	3.72	9.86	0.08	0.03	0.02	0.024	0.07	9.7	11.3	0.44	295	2.05	0.01
I100332		1.43	35.0	2.80	6.93	0.07	0.02	0.02	0.018	0.06	9.4	7.1	0.43	240	1.81	0.01
I100333		4.88	89.4	4.50	8.94	0.14	0.02	0.02	0.040	0.11	18.7	20.9	0.89	1240	5.93	0.01
I100334		4.44	78.6	3.91	8.41	0.12	0.02	0.04	0.040	0.09	15.6	17.8	0.68	934	4.72	0.02
I100335		3.02	42.3	2.88	7.27	0.11	0.04	0.05	0.028	0.09	17.2	15.5	0.94	234	1.52	0.01
I100336		1.26	23.8	2.97	4.88	0.10	0.04	0.05	0.020	0.06	10.5	9.3	0.49	1190	2.43	0.02
I100337		3.60	27.6	3.11	8.12	0.16	0.05	0.03	0.033	0.15	31.1	16.9	1.50	319	1.31	0.01
I100338		3.70	54.3	3.70	6.89	0.13	0.05	0.05	0.025	0.15	13.3	12.5	1.69	1440	2.53	0.02
I100339		6.71	55.9	3.81	8.15	0.12	0.02	0.03	0.028	0.32	13.3	12.8	1.50	1240	2.31	0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I100300		4.54	16.4	730	10.0	34.4	<0.001	0.03	0.46	4.5	0.4	0.9	31.0	<0.01	0.04	3.3
I100301		1.27	8.2	480	6.0	15.1	<0.001	0.04	0.26	1.5	0.2	0.4	14.8	<0.01	0.02	0.3
I100302		1.65	12.2	480	6.6	14.8	<0.001	0.06	0.30	1.2	0.4	0.5	16.0	<0.01	0.03	0.3
I100303		2.28	8.1	380	8.3	11.1	<0.001	0.01	0.33	2.2	0.2	0.6	9.5	<0.01	0.02	1.8
I100304		2.23	9.1	490	10.7	11.5	<0.001	0.01	0.50	2.1	0.3	0.7	9.7	<0.01	0.03	1.3
I100305		3.78	17.8	410	10.1	22.1	<0.001	0.01	0.56	3.8	0.5	0.7	14.7	<0.01	0.04	5.0
I100306		3.93	16.2	510	10.0	35.0	<0.001	0.02	0.57	3.5	0.3	0.7	15.1	<0.01	0.03	4.7
I100307		1.05	17.2	510	8.0	14.3	<0.001	<0.01	0.42	2.3	0.3	0.6	17.3	<0.01	0.02	0.8
I100308																
I100309		1.89	13.8	240	7.7	8.6	<0.001	<0.01	0.37	3.1	<0.2	0.5	13.5	<0.01	0.02	4.0
I100310		1.87	15.8	440	9.2	18.6	<0.001	0.03	0.41	3.1	0.4	1.2	20.3	<0.01	0.03	2.5
I100311		1.19	17.5	390	11.6	10.2	<0.001	0.05	0.70	2.2	0.5	0.5	30.6	<0.01	0.04	1.3
I100312		1.42	22.1	270	20.6	12.2	<0.001	0.01	0.67	3.4	0.3	0.8	16.0	<0.01	0.03	2.4
I100313		1.53	23.7	430	18.1	13.5	<0.001	0.03	1.73	3.5	0.4	0.7	19.6	<0.01	0.03	2.0
I100314		1.85	40.4	510	21.4	12.8	<0.001	0.03	1.16	4.2	0.7	0.7	25.3	0.01	0.04	3.0
I100315		0.59	10.0	920	9.6	8.0	0.001	0.10	0.59	2.4	1.6	0.3	56.9	0.01	0.03	0.3
I100316		0.39	9.9	850	4.6	4.4	<0.001	0.13	0.97	1.2	0.9	3.1	51.3	<0.01	0.02	0.2
I100317		0.36	17.7	980	6.4	5.5	<0.001	0.13	0.91	1.5	1.6	0.2	48.2	0.01	0.03	<0.2
I100318		0.44	27.6	620	20.4	10.9	<0.001	0.04	2.63	2.6	1.9	3.2	17.1	<0.01	0.07	1.1
I100319		0.61	49.6	1000	142.5	13.3	<0.001	0.02	2.80	4.8	2.7	0.6	28.1	<0.01	0.09	5.3
I100320		0.80	36.0	700	72.1	14.1	<0.001	0.03	1.73	5.1	1.9	0.7	23.7	<0.01	0.04	3.6
I100321		0.70	31.1	830	38.1	8.8	<0.001	0.05	2.06	4.3	2.1	0.4	35.1	<0.01	0.06	2.6
I100322		0.51	28.1	1000	31.3	12.9	<0.001	0.08	1.16	4.0	2.3	2.2	32.9	<0.01	0.07	1.2
I100323		0.77	28.9	550	36.0	10.6	<0.001	0.04	0.97	4.6	1.7	0.5	29.8	<0.01	0.05	3.1
I100324		0.57	23.9	1370	48.5	8.4	<0.001	0.11	0.94	3.2	2.8	1.7	35.6	<0.01	0.14	1.4
I100325		0.55	26.8	1030	38.4	10.4	<0.001	0.08	0.99	2.9	1.8	0.4	29.7	<0.01	0.08	0.7
I100326		1.07	38.4	450	18.3	10.9	<0.001	0.02	1.16	5.0	0.9	1.0	22.9	<0.01	0.04	2.1
I100327		0.79	25.1	1090	10.5	7.2	<0.001	0.07	0.92	4.0	1.5	0.6	40.7	<0.01	0.06	0.8
I100328		0.68	14.6	320	10.5	6.0	<0.001	0.02	0.38	1.5	0.5	1.2	10.6	<0.01	0.02	<0.2
I100329		0.75	9.5	380	7.7	6.3	<0.001	0.02	0.43	1.3	0.5	0.6	10.8	<0.01	0.04	<0.2
I100330		0.44	9.5	330	6.2	4.8	<0.001	0.01	0.30	1.0	0.3	0.6	7.8	<0.01	0.02	<0.2
I100331		1.61	24.2	450	12.1	14.3	<0.001	0.02	0.50	3.6	0.6	0.7	14.5	<0.01	0.06	1.0
I100332		0.87	26.5	330	17.6	8.5	<0.001	0.01	0.32	3.0	0.7	1.3	11.8	<0.01	0.05	0.4
I100333		1.08	61.8	910	102.0	20.3	<0.001	0.04	0.62	4.4	2.3	0.6	25.1	<0.01	0.10	3.1
I100334		0.97	52.0	770	93.2	18.6	<0.001	0.03	0.60	3.7	1.8	0.5	24.4	<0.01	0.09	1.7
I100335		1.10	39.5	420	22.0	17.9	<0.001	0.02	0.28	5.0	1.3	0.6	25.2	<0.01	0.04	4.0
I100336		0.85	24.0	840	11.9	13.0	<0.001	0.09	0.30	2.9	1.1	0.5	34.2	<0.01	0.04	1.2
I100337		0.67	46.2	530	14.2	30.4	<0.001	0.05	0.19	6.7	1.1	0.8	24.0	<0.01	0.02	5.1
I100338		0.68	49.5	690	64.2	23.7	<0.001	0.06	1.03	7.4	2.2	0.4	35.3	<0.01	0.06	2.1
I100339		0.71	55.0	420	108.0	35.6	<0.001	0.04	1.06	4.9	1.6	0.6	23.6	<0.01	0.08	1.9

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I100300		0.158	0.23	0.85	92	0.22	4.42	83	1.5
I100301		0.057	0.11	0.92	47	0.16	3.20	43	<0.5
I100302		0.061	0.07	0.65	47	0.12	2.77	38	<0.5
I100303		0.092	0.11	0.37	64	0.14	1.89	32	0.7
I100304		0.085	0.11	0.49	74	0.24	1.97	36	0.9
I100305		0.105	0.17	0.73	79	0.24	3.65	64	1.2
I100306		0.115	0.15	0.52	73	0.17	2.40	73	0.9
I100307		0.062	0.10	0.74	60	0.19	4.33	56	0.5
I100308									
I100309		0.084	0.11	0.50	65	0.20	3.15	43	1.5
I100310		0.083	0.08	0.95	57	0.20	4.76	46	0.8
I100311		0.065	0.09	0.58	61	0.15	2.90	57	0.6
I100312		0.067	0.11	0.49	76	0.12	3.09	77	1.3
I100313		0.072	0.14	0.57	79	0.16	3.15	96	1.1
I100314		0.094	0.16	0.76	84	0.20	4.60	103	2.6
I100315		0.029	0.09	2.13	27	0.08	30.9	28	0.7
I100316		0.019	0.06	0.81	15	0.06	6.19	32	<0.5
I100317		0.023	0.08	1.43	18	0.09	13.50	43	<0.5
I100318		0.034	0.11	1.06	53	0.18	5.40	194	<0.5
I100319		0.034	0.27	1.49	66	0.18	8.41	349	1.5
I100320		0.047	0.20	1.22	59	0.16	8.68	204	1.3
I100321		0.034	0.14	1.14	73	0.16	10.10	151	1.1
I100322		0.044	0.25	1.30	54	0.11	8.74	114	0.7
I100323		0.049	0.12	1.20	51	0.19	7.58	167	1.4
I100324		0.045	0.30	1.39	100	0.18	9.17	124	1.2
I100325		0.048	0.14	1.09	83	0.15	7.36	107	0.5
I100326		0.091	0.18	0.50	89	0.14	4.73	93	1.9
I100327		0.053	0.09	0.72	74	0.16	7.53	55	1.0
I100328		0.066	0.06	0.27	54	0.13	1.79	30	0.5
I100329		0.082	0.07	0.24	66	0.11	1.59	30	0.5
I100330		0.053	0.05	0.20	37	0.08	1.36	22	<0.5
I100331		0.114	0.10	0.51	109	0.17	4.12	58	1.3
I100332		0.083	0.10	0.55	79	0.11	4.76	80	0.5
I100333		0.083	0.18	1.52	99	0.22	8.75	479	0.6
I100334		0.073	0.17	1.37	85	0.18	7.27	391	0.5
I100335		0.080	0.19	1.51	58	0.14	9.68	112	1.6
I100336		0.061	0.12	0.87	40	0.10	8.77	51	1.4
I100337		0.078	0.24	1.19	58	0.11	11.05	86	1.3
I100338		0.085	0.25	1.31	72	0.12	10.65	202	1.5
I100339		0.111	0.31	0.79	71	0.12	7.48	280	<0.5

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I100340		0.32	0.007	0.48	1.61	60.9	<0.2	<10	270	0.40	0.35	0.28	1.74	34.4	13.1	28
I100341		0.42	<0.005	0.20	1.02	11.7	<0.2	<10	130	0.15	0.20	0.13	0.31	16.25	3.5	19
I100351		0.38	0.005	0.07	2.07	6.5	<0.2	<10	180	0.35	0.24	0.32	0.16	36.6	11.7	23
I100352		0.32	<0.005	0.07	1.48	4.6	<0.2	<10	160	0.39	0.20	0.30	0.26	51.3	7.6	16
I100353		0.30	<0.005	0.11	1.67	4.6	<0.2	<10	280	0.40	0.18	0.49	0.24	37.9	10.6	29
I100354		0.36	<0.005	0.05	1.70	3.5	<0.2	<10	200	0.31	0.09	0.46	0.16	41.5	11.4	16
I100355		0.36	<0.005	0.08	1.82	11.5	<0.2	<10	240	0.37	0.10	0.53	0.22	74.5	11.9	20
I100356		0.38	<0.005	0.10	1.68	8.0	<0.2	<10	240	0.42	0.12	0.60	0.19	46.1	10.1	26
I100357		0.34	<0.005	0.06	1.76	5.1	<0.2	<10	230	0.29	0.10	0.51	0.15	47.8	10.2	22
I100358		0.44	<0.005	0.10	1.55	9.7	<0.2	<10	300	0.41	0.14	0.74	0.17	33.0	9.7	26
I100359		0.36	<0.005	0.09	1.60	9.4	<0.2	<10	300	0.47	0.16	0.75	0.18	32.7	11.0	26
I100360		0.34	<0.005	0.09	1.78	8.3	<0.2	<10	290	0.38	0.15	0.83	0.17	39.2	12.0	28
I100361		0.36	<0.005	0.09	1.77	8.5	<0.2	<10	300	0.42	0.14	0.32	0.08	35.4	9.9	33
I100362		0.40	<0.005	0.21	2.30	6.3	<0.2	<10	290	0.46	0.12	0.37	0.06	41.1	14.1	30
I100363		0.40	<0.005	0.10	2.39	7.4	<0.2	<10	220	0.47	0.14	0.54	0.06	27.3	12.8	34
I100364		0.34	<0.005	0.07	2.73	8.1	<0.2	<10	180	0.40	0.16	0.41	0.07	18.95	12.5	33
I100365		0.26	<0.005	0.04	2.17	5.1	<0.2	<10	140	0.28	0.11	0.48	0.05	15.30	9.9	27
I100366		0.20	<0.005	0.36	1.18	2.1	<0.2	<10	120	0.28	0.12	0.18	0.39	12.15	6.6	15
I100367		0.24	<0.005	0.41	2.27	4.6	<0.2	<10	160	0.46	0.15	0.25	0.19	14.65	10.3	24
I100368		0.24	<0.005	0.11	1.81	3.6	<0.2	<10	140	0.35	0.11	0.27	0.08	12.65	10.3	19
I100369		0.24	<0.005	0.12	1.19	2.7	<0.2	<10	130	0.27	0.15	0.16	0.18	8.96	5.6	15
I100370		0.26	<0.005	0.15	0.68	1.8	<0.2	<10	80	0.15	0.12	0.13	0.12	7.03	3.5	12
I100371		0.32	<0.005	0.04	2.51	5.9	<0.2	<10	170	0.45	0.14	0.35	0.05	22.9	15.7	31
I100372		0.40	0.006	0.05	2.80	8.7	<0.2	<10	190	0.30	0.19	0.31	0.14	17.90	12.3	35
I100373		0.28	<0.005	0.15	2.40	5.4	<0.2	<10	250	0.47	0.17	0.29	0.14	16.95	8.7	27
I100374		0.28	<0.005	0.08	0.79	2.4	<0.2	<10	80	0.19	0.10	0.10	0.10	7.05	3.3	12
I100375		0.28	<0.005	0.04	2.09	8.3	<0.2	<10	140	0.28	0.16	0.20	0.12	14.30	9.1	26
I100376		0.32	0.006	0.03	2.37	8.3	<0.2	<10	170	0.43	0.12	0.34	0.06	20.7	12.2	34
I100377		0.28	<0.005	0.11	1.24	3.3	<0.2	<10	120	0.29	0.11	0.16	0.10	8.98	3.6	15
I100378		0.36	<0.005	0.03	2.21	10.4	<0.2	<10	200	0.29	0.14	0.36	0.07	23.0	10.6	36
I100379		0.36	<0.005	0.11	2.96	16.5	<0.2	<10	410	0.65	0.15	0.36	0.07	25.8	12.7	25
I100380		0.28	<0.005	0.13	1.32	74.1	<0.2	<10	110	0.29	0.24	0.10	0.43	19.40	12.2	29
I100381		0.28	<0.005	0.89	1.07	24.9	<0.2	<10	250	0.35	0.12	0.19	0.69	28.8	3.9	15
I100382		0.24	<0.005	0.71	1.12	26.0	<0.2	<10	210	0.31	0.13	0.19	0.70	23.7	4.3	16
I100383		0.34	<0.005	0.09	2.09	181.5	<0.2	<10	150	0.30	0.25	0.16	0.40	32.2	10.8	36
I100384		0.38	<0.005	0.24	2.49	57.2	<0.2	<10	250	0.59	0.28	0.37	0.22	38.1	14.4	33
I100385		0.36	<0.005	0.46	2.51	45.5	<0.2	<10	440	0.40	0.36	0.38	0.66	31.7	11.6	34
I100386		0.36	<0.005	0.23	1.49	313	<0.2	<10	260	0.29	0.25	0.17	0.41	22.2	7.7	26
I100387		0.26	<0.005	1.07	1.24	100.5	<0.2	<10	350	0.35	0.20	0.35	2.06	20.7	6.8	22
I100388		0.32	<0.005	0.06	0.66	24.8	<0.2	<10	80	0.15	0.13	0.07	0.32	9.47	3.0	13

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I100340		3.87	63.6	3.01	6.06	0.14	<0.02	0.06	0.033	0.09	20.2	12.2	0.61	587	2.86	0.01
I100341		0.97	17.7	2.09	8.33	0.06	<0.02	0.02	0.016	0.03	8.1	3.0	0.15	203	1.29	0.01
I100351		1.06	16.4	3.39	8.34	0.08	0.03	0.01	0.021	0.32	25.1	15.4	0.69	534	13.70	0.03
I100352		0.87	14.4	2.74	7.90	0.07	0.02	0.02	0.016	0.17	33.7	9.1	0.35	466	2.42	0.03
I100353		1.12	23.5	2.33	5.84	0.07	0.03	0.04	0.023	0.08	19.9	12.6	0.54	496	0.69	0.03
I100354		0.90	16.1	2.87	5.96	0.09	0.04	0.03	0.015	0.51	23.1	17.6	0.76	573	0.95	0.02
I100355		0.95	15.8	2.64	7.04	0.18	0.05	0.03	0.014	0.30	41.2	15.0	0.61	560	0.95	0.02
I100356		0.68	26.5	2.70	5.63	0.13	0.08	0.03	0.017	0.13	23.9	11.9	0.56	435	0.69	0.02
I100357		0.85	15.9	2.51	6.44	0.13	0.08	0.04	0.014	0.23	27.5	13.8	0.66	537	0.73	0.02
I100358		0.51	29.8	2.53	5.12	0.12	0.11	0.04	0.016	0.09	17.0	11.5	0.53	373	0.67	0.03
I100359		0.49	29.5	2.53	5.13	0.12	0.10	0.03	0.062	0.07	16.0	11.3	0.50	424	0.74	0.02
I100360		0.60	35.6	2.88	5.92	0.12	0.12	0.04	0.021	0.13	21.1	12.3	0.58	761	1.07	0.02
I100361		0.48	17.0	2.88	5.76	0.09	0.13	0.01	0.018	0.14	16.4	9.6	0.47	315	0.90	0.01
I100362		0.71	27.4	3.52	6.85	0.06	0.12	0.02	0.022	0.42	21.2	12.0	0.73	900	1.30	0.02
I100363		0.71	27.8	3.02	6.49	0.06	0.06	0.03	0.026	0.04	12.8	13.2	0.75	236	0.53	0.03
I100364		0.87	21.2	3.54	7.58	0.05	0.05	0.02	0.028	0.05	9.3	13.6	0.80	352	0.67	0.03
I100365		0.60	17.3	3.01	6.44	<0.05	0.03	0.02	0.021	0.05	7.7	10.9	0.75	286	0.64	0.02
I100366		0.60	29.7	1.50	4.02	<0.05	<0.02	0.03	0.018	0.03	6.1	2.7	0.13	735	0.70	0.03
I100367		1.04	31.5	3.30	7.93	0.05	0.02	0.02	0.026	0.05	7.3	8.8	0.52	287	1.01	0.03
I100368		0.79	21.0	2.57	5.80	<0.05	0.02	0.02	0.021	0.04	6.4	7.5	0.44	283	0.70	0.03
I100369		0.54	20.8	1.48	5.01	<0.05	<0.02	0.02	0.016	0.04	4.6	4.1	0.15	259	0.66	0.03
I100370		0.55	17.5	1.17	3.61	<0.05	<0.02	0.03	0.011	0.03	3.6	2.3	0.13	95	0.70	0.02
I100371		0.94	29.7	3.64	7.10	0.07	0.09	0.02	0.032	0.05	11.4	13.1	0.78	427	0.69	0.02
I100372		1.01	33.3	3.61	8.46	0.05	0.05	0.01	0.029	0.05	8.8	14.7	0.67	321	0.96	0.02
I100373		0.86	27.9	2.72	7.06	<0.05	0.02	0.03	0.027	0.06	8.8	9.8	0.41	208	0.94	0.03
I100374		0.50	14.5	1.18	3.68	<0.05	<0.02	0.02	0.011	0.03	3.6	2.9	0.12	65	0.54	0.03
I100375		1.02	21.8	3.29	7.93	0.05	0.02	0.02	0.024	0.05	7.1	10.6	0.50	229	1.15	0.02
I100376		0.94	31.0	3.39	6.76	0.06	0.04	0.01	0.022	0.05	10.2	14.9	0.78	342	0.66	0.02
I100377		0.69	23.5	1.48	4.56	<0.05	<0.02	0.03	0.017	0.04	4.3	3.5	0.14	65	0.65	0.03
I100378		1.00	22.8	3.07	7.10	0.06	0.03	0.10	0.025	0.05	11.3	13.5	0.65	275	0.68	0.03
I100379		2.38	25.3	4.21	8.49	0.06	0.03	0.03	0.040	0.05	12.9	13.6	0.70	601	0.89	0.02
I100380		1.40	69.0	4.44	6.69	0.06	<0.02	0.02	0.038	0.05	9.6	5.3	0.19	403	4.12	0.01
I100381		0.87	41.9	1.62	4.94	0.09	0.03	0.05	0.019	0.03	34.6	4.7	0.13	64	1.59	0.03
I100382		0.89	35.0	1.85	4.92	0.07	0.02	0.05	0.020	0.03	25.1	5.5	0.15	77	1.79	0.03
I100383		1.89	33.1	4.06	9.04	0.06	0.03	0.02	0.033	0.06	16.4	13.8	0.49	327	2.11	0.02
I100384		1.80	35.7	3.20	6.57	0.06	0.06	0.03	0.037	0.08	19.6	14.8	0.57	297	1.32	0.02
I100385		2.04	32.6	3.35	8.37	0.06	0.02	0.03	0.040	0.08	17.9	18.2	0.53	445	3.86	0.02
I100386		1.74	36.2	3.13	6.87	0.05	<0.02	0.04	0.029	0.05	11.3	6.2	0.25	236	2.69	0.02
I100387		1.89	53.1	1.87	5.52	0.05	<0.02	0.04	0.022	0.07	15.8	4.1	0.17	317	1.75	0.03
I100388		0.75	22.3	1.27	4.49	<0.05	<0.02	0.02	0.012	0.03	5.4	2.6	0.13	93	0.87	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I100340		0.53	35.3	690	18.0	16.1	<0.001	0.03	1.16	4.1	1.4	0.5	21.3	<0.01	0.06	1.2
I100341		0.70	8.9	330	11.5	5.4	<0.001	0.01	0.36	1.1	0.4	0.6	15.0	<0.01	0.03	<0.2
I100351		2.92	14.1	580	32.1	38.0	<0.001	0.02	0.29	4.8	0.4	0.7	36.0	<0.01	0.02	7.9
I100352		1.92	9.2	740	11.8	25.3	<0.001	0.03	0.23	2.2	0.4	0.6	31.9	<0.01	0.03	1.7
I100353		1.65	19.1	660	11.5	15.2	<0.001	0.04	0.46	5.2	0.6	0.5	40.6	<0.01	0.03	3.4
I100354		3.01	11.9	660	7.4	44.1	0.006	0.07	0.28	4.4	0.4	0.5	33.7	<0.01	0.02	7.2
I100355		2.81	15.8	580	8.5	36.4	<0.001	0.02	0.29	4.3	0.8	0.5	41.2	<0.01	0.03	6.2
I100356		1.88	21.2	680	7.5	16.5	<0.001	0.02	0.49	4.8	0.9	0.4	44.6	<0.01	0.02	5.0
I100357		2.88	14.6	530	7.6	27.9	<0.001	0.02	0.33	4.4	0.7	0.4	36.0	<0.01	0.01	8.3
I100358		1.49	23.1	670	8.0	9.7	<0.001	0.01	0.57	4.5	0.8	0.4	47.5	<0.01	0.03	3.8
I100359		1.40	23.8	620	8.1	8.6	<0.001	0.02	0.54	4.5	0.9	0.4	49.6	<0.01	0.03	3.3
I100360		2.02	25.1	590	8.4	15.6	<0.001	0.03	0.59	5.0	1.0	0.4	54.5	<0.01	0.03	4.8
I100361		1.36	21.9	210	8.1	14.3	<0.001	0.01	0.46	5.3	0.6	0.5	28.8	<0.01	0.03	4.7
I100362		1.72	20.9	360	9.0	34.4	<0.001	0.01	0.35	6.3	0.4	0.5	28.7	<0.01	0.03	8.1
I100363		1.41	20.8	490	7.9	6.3	<0.001	0.01	0.37	7.1	0.5	0.6	35.8	<0.01	0.02	2.4
I100364		1.38	18.3	470	9.7	8.1	<0.001	0.01	0.26	6.4	0.4	0.6	29.9	<0.01	0.03	1.9
I100365		1.27	14.9	420	6.0	6.5	<0.001	0.01	0.21	4.7	0.3	0.4	28.4	<0.01	0.02	1.5
I100366		0.26	11.3	540	5.0	5.1	<0.001	0.02	0.17	0.8	0.4	0.3	19.6	<0.01	0.02	<0.2
I100367		0.87	15.1	710	6.1	9.3	<0.001	0.02	0.24	4.8	0.4	0.5	24.7	<0.01	0.03	0.3
I100368		0.70	10.8	420	4.7	6.2	<0.001	0.02	0.20	3.4	0.3	0.4	22.4	<0.01	0.02	0.2
I100369		0.56	9.3	500	6.2	6.4	<0.001	0.01	0.16	1.9	0.3	0.4	17.2	<0.01	0.02	<0.2
I100370		0.42	6.7	290	5.1	6.6	<0.001	0.01	0.15	1.1	0.3	0.3	14.5	<0.01	0.02	<0.2
I100371		1.07	16.9	390	7.8	7.5	<0.001	<0.01	0.30	7.7	0.4	0.5	26.4	<0.01	0.02	2.4
I100372		1.55	21.5	470	44.6	9.9	<0.001	<0.01	0.33	4.9	0.4	0.6	24.8	<0.01	0.03	2.1
I100373		0.76	17.5	560	7.2	9.4	<0.001	0.02	0.25	3.1	0.5	0.5	28.6	<0.01	0.03	0.2
I100374		0.28	6.6	310	3.8	4.3	<0.001	0.01	0.13	0.8	0.3	0.3	11.6	<0.01	0.02	<0.2
I100375		1.13	15.7	390	6.6	8.6	<0.001	0.01	0.30	3.8	0.3	0.6	19.2	<0.01	0.03	0.4
I100376		1.19	21.4	390	6.7	8.3	<0.001	0.01	0.30	5.4	0.4	0.5	26.4	<0.01	0.02	1.9
I100377		0.38	8.6	500	5.0	6.0	<0.001	0.02	0.18	1.0	0.3	0.3	17.1	<0.01	0.02	<0.2
I100378		1.29	22.6	530	8.5	10.0	<0.001	0.01	0.32	4.8	0.4	0.5	27.6	<0.01	0.03	1.5
I100379		0.66	13.7	410	11.1	10.0	<0.001	0.01	0.57	7.5	0.6	0.5	24.6	<0.01	0.03	0.7
I100380		0.40	41.8	680	21.0	9.7	<0.001	0.02	1.47	1.7	2.0	0.6	11.6	<0.01	0.10	0.2
I100381		0.54	17.7	430	11.7	7.4	<0.001	0.02	0.36	1.5	1.1	0.4	20.6	0.01	0.04	<0.2
I100382		0.58	16.7	490	13.5	8.3	<0.001	0.03	0.38	1.6	1.1	0.4	19.7	0.01	0.04	<0.2
I100383		1.61	28.1	290	21.4	10.9	<0.001	0.01	1.31	4.1	0.8	0.7	15.2	<0.01	0.06	4.5
I100384		1.16	34.6	630	26.1	14.4	<0.001	0.02	0.67	4.2	1.2	0.6	25.1	<0.01	0.04	4.8
I100385		1.04	30.6	620	27.5	14.5	<0.001	0.02	0.62	3.5	1.2	0.9	27.2	<0.01	0.05	2.5
I100386		0.65	21.6	590	26.1	12.1	<0.001	0.02	0.84	3.0	1.0	0.6	18.6	<0.01	0.06	0.4
I100387		0.60	28.4	1160	11.6	15.0	<0.001	0.04	0.59	2.0	1.0	0.5	29.4	<0.01	0.04	<0.2
I100388		0.36	8.9	360	7.3	7.7	<0.001	0.02	0.25	0.9	0.4	0.4	9.8	<0.01	0.03	<0.2

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I100340		0.041	0.11	1.19	59	0.14	13.15	166	<0.5
I100341		0.062	0.11	0.33	69	0.10	2.08	27	0.5
I100351		0.133	0.23	1.66	65	0.23	6.64	85	1.5
I100352		0.086	0.16	0.87	57	0.18	6.87	56	0.5
I100353		0.083	0.12	1.76	48	0.22	8.99	70	1.0
I100354		0.135	0.22	2.36	58	0.21	8.47	67	1.9
I100355		0.113	0.16	3.02	53	0.18	13.05	61	2.1
I100356		0.096	0.09	2.18	55	0.15	11.15	57	3.1
I100357		0.120	0.13	2.41	51	0.18	7.82	56	3.6
I100358		0.089	0.06	1.17	52	0.45	10.25	50	5.2
I100359		0.085	0.06	1.12	52	0.18	10.30	51	4.4
I100360		0.100	0.08	1.42	56	0.16	10.85	57	4.8
I100361		0.100	0.08	0.57	62	0.15	5.33	52	5.8
I100362		0.133	0.17	0.64	77	0.18	7.18	71	6.0
I100363		0.115	0.08	0.84	81	0.14	10.30	46	3.1
I100364		0.124	0.10	0.51	87	0.17	5.18	60	2.2
I100365		0.118	0.07	0.37	76	0.12	4.12	50	1.6
I100366		0.029	0.06	0.52	34	0.06	3.72	28	<0.5
I100367		0.086	0.09	0.69	75	0.11	5.78	49	0.7
I100368		0.072	0.07	0.42	59	0.11	4.46	39	0.6
I100369		0.058	0.06	0.31	38	0.09	2.46	31	<0.5
I100370		0.048	0.05	0.33	30	0.08	2.19	23	<0.5
I100371		0.122	0.09	0.60	85	0.12	8.86	60	4.7
I100372		0.142	0.12	0.39	88	0.16	4.12	75	2.7
I100373		0.071	0.09	0.66	57	0.12	5.84	50	0.6
I100374		0.040	0.05	0.34	29	0.08	1.97	18	<0.5
I100375		0.103	0.09	0.38	83	0.17	3.42	42	0.8
I100376		0.130	0.10	0.46	80	0.16	6.03	53	1.7
I100377		0.038	0.06	0.42	31	0.08	2.74	19	<0.5
I100378		0.130	0.11	0.48	75	0.18	6.30	48	1.3
I100379		0.033	0.12	0.44	85	0.17	24.4	51	0.5
I100380		0.023	0.12	0.72	80	0.20	6.12	138	<0.5
I100381		0.047	0.08	0.85	38	0.12	23.9	28	<0.5
I100382		0.049	0.07	0.75	41	0.10	17.15	31	<0.5
I100383		0.083	0.16	0.66	95	0.24	5.67	79	1.9
I100384		0.052	0.17	1.25	63	0.21	8.08	79	1.9
I100385		0.029	0.18	1.86	78	0.22	9.77	104	<0.5
I100386		0.029	0.15	0.62	77	0.16	5.58	79	<0.5
I100387		0.042	0.10	0.85	39	0.13	10.35	49	<0.5
I100388		0.046	0.08	0.32	37	0.10	2.72	23	<0.5

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1	ME-MS41 Cr ppm 1
I100389		0.30	<0.005	0.55	0.54	49.7	<0.2	<10	90	0.20	0.09	0.07	0.14	13.15	1.9	10
I100390		0.28	<0.005	0.20	1.61	72.9	<0.2	<10	120	0.28	0.20	0.55	0.16	17.20	16.3	34
I100391		0.34	<0.005	0.19	1.85	71.8	<0.2	<10	250	0.50	0.20	0.86	0.47	22.5	13.1	23
I100392		0.32	0.012	0.10	1.60	33.2	<0.2	<10	220	0.41	0.17	0.98	0.20	27.7	11.6	21
I100393		0.42	<0.005	0.09	2.46	16.9	<0.2	<10	280	0.50	0.21	0.59	0.05	23.2	13.6	27
I100394		0.36	<0.005	0.04	2.77	12.5	<0.2	<10	300	0.99	0.11	0.61	0.05	15.75	20.0	21
I100395		0.30	0.005	0.12	2.20	9.6	<0.2	<10	310	0.65	0.13	0.39	0.08	21.0	44.9	20
I100396		0.30	<0.005	0.05	1.97	6.5	<0.2	<10	200	0.41	0.10	0.46	0.06	13.00	14.7	26
I100397		0.34	<0.005	0.06	1.95	5.8	<0.2	<10	210	0.48	0.13	0.31	0.04	15.65	11.5	23
I100398		0.26	<0.005	0.25	0.69	2.4	<0.2	<10	190	0.43	0.06	0.76	0.05	9.87	7.0	8
I100399		0.30	<0.005	0.01	0.99	5.1	<0.2	<10	50	0.16	0.15	0.11	0.07	9.57	4.5	11
I100400		0.30	<0.005	0.14	1.91	5.7	<0.2	<10	210	0.47	0.19	0.53	0.08	24.3	11.3	19
I100401		0.40	<0.005	1.31	2.40	72.1	<0.2	<10	220	0.52	0.19	0.20	0.65	22.3	15.8	32
I100402		0.44	<0.005	0.29	1.70	98.5	<0.2	<10	260	0.36	0.25	0.14	0.18	32.3	5.3	26
I100403		0.44	<0.005	0.51	1.36	139.0	<0.2	<10	160	0.36	0.33	0.14	0.17	72.1	3.9	26
I100404		0.48	<0.005	0.93	1.52	133.0	<0.2	<10	180	0.41	0.43	0.14	0.23	76.2	5.4	24
I100405		0.34	<0.005	0.56	2.08	85.0	<0.2	<10	180	0.53	0.30	0.10	0.28	43.1	5.9	27
I100406		0.26	<0.005	0.65	1.39	93.2	<0.2	<10	200	0.47	0.23	0.22	0.63	47.6	7.1	23
I100407		0.24	NSS	0.41	1.18	46.0	<0.2	<10	130	0.49	0.12	0.25	0.47	42.4	6.1	14
I100408		0.38	0.011	0.23	1.46	37.6	<0.2	<10	110	0.51	0.21	0.15	0.29	54.9	11.2	26
I100409		0.58	0.005	0.52	2.02	42.6	<0.2	<10	230	0.49	0.23	0.20	0.67	50.4	21.8	32
I100410		0.28	0.010	0.52	2.00	23.8	<0.2	<10	220	0.48	0.17	0.20	0.55	43.8	13.3	39
I100411		0.44	<0.005	0.47	2.10	19.1	<0.2	<10	210	0.40	0.20	0.18	0.42	38.1	13.2	47
I100412		0.38	<0.005	0.52	0.87	5.2	<0.2	<10	150	0.42	0.13	0.10	0.55	20.6	4.4	17
I100413		0.32	<0.005	1.09	1.59	9.9	<0.2	<10	190	0.38	0.15	0.17	0.44	25.1	9.0	30
I100414		0.24	NSS	0.91	0.76	7.0	<0.2	<10	310	0.27	0.05	0.39	0.92	27.3	5.8	7
I100415		0.28	<0.005	1.36	1.47	79.0	<0.2	<10	200	0.40	0.20	0.20	0.43	28.8	7.8	28
I100416		0.16	NSS	0.58	0.55	16.3	<0.2	<10	160	0.29	0.07	0.21	0.75	25.2	5.1	12
I100417		0.42	<0.005	0.31	0.73	6.2	<0.2	<10	70	0.50	0.11	0.18	0.33	37.4	5.1	13
I100418		0.28	<0.005	0.29	0.61	11.2	<0.2	<10	90	0.46	0.09	0.38	0.30	31.6	9.9	12
I100419		0.36	<0.005	0.09	1.39	14.9	<0.2	<10	130	0.27	0.13	0.78	0.18	20.0	9.9	22
I100420		0.50	<0.005	0.66	2.07	64.9	<0.2	<10	180	0.67	0.18	0.18	0.36	22.2	11.1	28
I100421		0.38	<0.005	0.87	1.64	53.3	<0.2	<10	180	0.51	0.19	0.22	0.59	18.35	10.4	23
I100422		0.44	<0.005	0.67	1.76	54.2	<0.2	<10	150	0.50	0.18	0.18	0.42	19.70	9.3	24
I100423		0.48	<0.005	0.65	2.31	71.0	<0.2	<10	180	0.62	0.21	0.19	0.36	22.2	12.1	31
I100424		0.50	<0.005	0.65	1.77	56.9	<0.2	<10	160	0.52	0.19	0.17	0.45	22.2	9.5	24
I100425		0.36	<0.005	0.78	1.75	57.0	<0.2	<10	170	0.51	0.18	0.20	0.56	22.1	9.2	24
I100426		0.40	<0.005	0.66	1.72	60.7	<0.2	<10	160	0.49	0.19	0.18	0.44	22.5	9.4	24
I100427		0.42	<0.005	0.72	2.10	69.9	<0.2	<10	190	0.69	0.21	0.19	0.39	23.1	11.2	29
I100428		0.40	<0.005	0.68	1.81	58.7	<0.2	<10	170	0.50	0.19	0.19	0.47	22.9	9.6	25

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I100389		0.81	21.7	0.89	2.44	<0.05	<0.02	0.04	0.011	0.03	9.9	1.4	0.05	44	0.62	0.02
I100390		1.87	32.8	3.06	6.58	0.05	0.02	0.03	0.025	0.07	9.1	11.6	0.66	548	3.39	0.02
I100391		1.81	38.0	3.37	6.14	0.06	0.02	0.03	0.031	0.08	11.0	12.1	0.67	491	1.29	0.03
I100392		1.12	25.5	2.70	5.31	0.06	0.04	0.04	0.023	0.06	15.7	10.3	0.55	537	1.21	0.03
I100393		1.44	25.6	3.69	7.56	0.07	0.06	0.04	0.028	0.14	11.4	15.0	0.92	274	0.69	0.03
I100394		3.67	21.9	4.86	7.89	0.10	0.07	0.02	0.020	0.43	7.8	18.9	1.51	410	0.79	0.03
I100395		1.69	20.4	4.54	6.64	0.07	0.03	0.04	0.023	0.15	8.3	10.4	0.82	4090	1.47	0.03
I100396		1.36	18.3	3.21	6.14	0.06	0.03	0.03	0.017	0.13	6.5	11.5	0.88	510	0.90	0.03
I100397		1.34	19.3	3.09	6.73	0.06	0.03	0.02	0.021	0.15	7.9	12.3	0.76	329	0.82	0.03
I100398		0.62	20.2	1.20	3.07	<0.05	0.03	0.06	0.011	0.06	5.5	3.7	0.18	303	0.41	0.04
I100399		0.64	11.1	2.17	6.72	<0.05	0.03	0.02	0.015	0.04	4.9	3.8	0.27	143	1.11	0.02
I100400		1.42	21.4	3.07	6.90	0.08	0.02	0.04	0.037	0.07	15.6	10.3	0.59	512	0.92	0.02
I100401		2.41	29.2	3.17	7.62	0.06	0.02	0.03	0.035	0.07	13.2	14.9	0.50	1050	2.06	0.02
I100402		1.21	36.6	3.89	8.33	0.07	<0.02	0.01	0.035	0.17	19.9	8.9	0.31	189	4.81	0.02
I100403		1.46	37.9	3.37	8.82	0.09	0.02	0.01	0.047	0.10	34.6	6.8	0.28	170	5.85	0.01
I100404		2.55	34.1	2.68	6.79	0.09	0.04	0.02	0.057	0.14	41.9	9.5	0.33	207	5.52	0.02
I100405		2.07	40.2	2.84	8.82	0.06	0.03	0.02	0.043	0.11	22.8	11.3	0.30	173	3.01	0.03
I100406		1.97	50.5	2.54	6.17	0.09	0.02	0.05	0.036	0.10	23.2	7.8	0.31	237	4.11	0.02
I100407		1.33	84.9	1.73	2.87	0.06	0.03	0.07	0.026	0.08	18.3	3.8	0.16	121	1.16	0.02
I100408		2.84	33.7	2.60	6.11	0.09	0.02	0.02	0.029	0.17	27.3	12.8	0.51	388	1.48	0.02
I100409		2.56	43.7	2.84	7.43	0.08	0.02	0.04	0.035	0.12	26.7	20.1	0.62	603	1.60	0.01
I100410		2.47	51.8	2.87	7.76	0.09	0.02	0.02	0.033	0.13	22.2	18.3	0.77	334	2.08	0.02
I100411		2.83	48.6	3.19	9.48	0.08	0.02	0.03	0.035	0.14	19.7	17.5	0.94	406	2.84	0.02
I100412		1.36	43.8	1.17	4.80	<0.05	<0.02	0.03	0.019	0.04	11.6	3.2	0.13	78	0.70	0.02
I100413		1.62	41.6	2.34	6.96	0.07	<0.02	0.05	0.027	0.07	14.9	12.0	0.50	237	1.64	0.02
I100414		0.30	50.7	1.05	1.16	0.06	0.02	0.11	0.016	0.03	12.9	0.8	0.08	95	0.91	0.04
I100415		3.67	41.0	2.07	7.72	0.06	<0.02	0.05	0.025	0.07	17.7	14.8	0.48	203	2.86	0.02
I100416		2.24	39.3	0.92	1.90	0.05	<0.02	0.11	0.016	0.06	14.5	2.8	0.17	116	1.42	0.03
I100417		1.79	26.4	1.17	4.16	0.05	<0.02	0.03	0.016	0.04	18.1	7.2	0.18	214	0.72	0.02
I100418		1.50	38.0	1.13	2.71	0.06	0.02	0.06	0.014	0.07	17.3	4.6	0.19	447	1.51	0.02
I100419		0.82	19.5	2.18	5.00	0.06	0.05	0.08	0.025	0.06	10.2	11.4	0.55	337	0.98	0.04
I100420		1.33	26.1	3.05	8.29	0.05	0.02	0.02	0.034	0.06	13.6	12.9	0.37	311	1.80	0.02
I100421		1.12	22.2	2.68	7.71	0.05	0.02	0.01	0.028	0.06	11.3	9.4	0.28	327	1.78	0.03
I100422		1.31	20.7	2.82	7.70	0.05	0.02	0.01	0.031	0.05	11.9	10.5	0.33	292	1.64	0.02
I100423		1.63	25.6	3.27	9.02	0.06	0.04	0.02	0.038	0.06	13.2	13.5	0.42	339	1.86	0.02
I100424		1.36	22.3	2.85	7.66	0.05	0.02	0.02	0.029	0.06	12.9	11.2	0.33	299	1.61	0.02
I100425		1.44	23.0	2.80	7.45	0.06	<0.02	0.01	0.028	0.06	12.8	10.1	0.32	365	1.59	0.04
I100426		1.26	22.2	2.85	7.89	0.05	0.02	0.02	0.030	0.05	13.1	9.9	0.31	304	1.75	0.02
I100427		1.36	26.6	3.16	8.89	0.06	0.03	0.02	0.036	0.06	13.6	11.8	0.37	319	1.92	0.02
I100428		1.28	21.9	2.91	7.91	0.06	0.02	0.02	0.029	0.06	13.3	10.3	0.33	336	1.72	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I100389		0.19	7.6	420	65.1	4.9	<0.001	0.03	0.31	0.6	0.5	0.2	10.1	<0.01	0.03	<0.2
I100390		0.99	25.0	700	25.1	13.2	<0.001	0.04	0.38	3.8	1.0	0.5	37.0	<0.01	0.05	1.1
I100391		0.82	23.9	710	33.7	13.7	<0.001	0.05	0.50	5.4	0.8	0.4	50.8	<0.01	0.05	1.0
I100392		1.00	16.7	630	13.9	11.4	<0.001	0.06	0.41	4.1	0.9	0.4	64.4	<0.01	0.03	1.7
I100393		1.33	18.4	570	14.6	21.9	<0.001	0.02	0.35	6.2	0.5	0.6	40.2	<0.01	0.03	2.5
I100394		1.16	14.5	640	6.3	60.9	<0.001	0.02	0.24	4.3	0.5	0.4	44.4	<0.01	0.02	2.0
I100395		0.92	11.9	860	6.1	20.6	<0.001	0.05	0.28	3.7	0.8	0.4	29.5	<0.01	0.04	0.9
I100396		0.97	14.2	680	5.0	16.7	<0.001	0.03	0.21	3.6	0.4	0.4	31.5	<0.01	0.03	0.8
I100397		1.08	14.4	340	5.7	19.8	<0.001	0.01	0.22	4.2	0.4	0.5	26.8	<0.01	0.02	1.2
I100398		0.47	4.9	630	3.2	7.0	<0.001	0.07	0.24	3.1	1.1	0.2	37.9	<0.01	0.03	0.2
I100399		1.14	5.7	210	6.1	6.1	<0.001	0.03	0.27	2.1	0.3	0.5	10.9	<0.01	0.04	1.1
I100400		0.81	14.6	590	7.6	13.8	<0.001	0.06	0.35	6.3	0.8	0.8	31.3	<0.01	0.04	1.5
I100401		1.09	34.8	590	11.9	13.0	<0.001	0.05	1.12	3.6	0.8	0.5	23.2	<0.01	0.05	1.9
I100402		1.00	13.8	610	24.6	16.4	<0.001	0.30	1.97	3.1	1.3	0.6	31.8	<0.01	0.11	2.2
I100403		0.97	13.5	540	30.5	11.7	<0.001	0.12	3.08	2.6	2.2	0.6	26.5	<0.01	0.24	2.6
I100404		2.41	14.7	430	69.2	17.3	<0.001	0.26	1.68	2.2	1.9	0.6	24.3	<0.01	0.18	2.0
I100405		2.01	13.6	430	35.6	15.5	<0.001	0.15	1.02	3.0	1.3	0.8	18.3	<0.01	0.12	1.8
I100406		1.03	22.3	650	20.0	12.8	<0.001	0.12	2.18	2.0	3.0	0.4	29.2	0.01	0.12	0.5
I100407		0.90	16.2	800	10.9	10.2	<0.001	0.10	0.83	1.4	2.3	0.7	23.2	0.01	0.06	0.3
I100408		1.34	24.9	500	14.3	24.1	<0.001	0.04	0.75	2.6	1.1	0.4	16.8	<0.01	0.06	2.0
I100409		1.50	30.7	500	17.1	19.6	<0.001	0.03	0.91	4.3	1.3	0.5	21.4	<0.01	0.06	3.6
I100410		1.20	34.4	650	11.0	17.5	<0.001	0.07	0.63	4.4	1.6	0.4	20.0	<0.01	0.07	2.5
I100411		1.13	35.4	620	10.2	17.9	0.001	0.09	0.51	4.2	1.7	0.5	21.1	<0.01	0.08	1.5
I100412		0.26	13.4	470	7.1	9.3	<0.001	0.06	0.17	0.6	0.9	0.4	15.8	<0.01	0.04	<0.2
I100413		0.59	25.5	750	7.4	11.3	<0.001	0.08	0.29	1.7	1.8	0.4	21.5	<0.01	0.07	0.2
I100414		0.23	22.3	1140	2.8	1.7	<0.001	0.18	0.41	1.7	2.0	0.2	35.6	0.01	0.04	<0.2
I100415		0.70	32.5	600	11.1	13.9	<0.001	0.07	1.08	1.8	1.2	0.5	23.5	<0.01	0.09	0.4
I100416		0.26	13.7	860	8.8	5.8	<0.001	0.08	0.53	0.6	1.0	0.2	22.8	<0.01	0.03	0.2
I100417		0.35	14.0	400	7.5	11.5	<0.001	0.03	0.13	1.0	0.7	0.3	15.1	<0.01	0.03	0.2
I100418		0.49	16.0	810	6.3	8.7	<0.001	0.09	0.45	1.5	1.8	0.2	25.0	<0.01	0.05	0.6
I100419		1.11	18.8	620	9.2	10.8	0.002	0.08	0.49	4.1	1.1	0.4	41.4	<0.01	0.04	1.5
I100420		1.78	22.5	300	17.7	11.8	<0.001	0.06	0.75	3.3	0.7	0.7	22.8	<0.01	0.06	2.4
I100421		1.62	17.0	320	18.8	11.4	<0.001	0.06	0.62	2.5	0.6	0.7	21.5	<0.01	0.04	1.1
I100422		1.66	18.3	310	16.3	11.5	<0.001	0.05	0.65	2.7	0.5	0.7	21.8	<0.01	0.05	1.5
I100423		2.17	24.7	290	19.8	12.6	<0.001	0.06	0.78	3.6	0.6	0.8	23.7	<0.01	0.05	3.0
I100424		1.60	19.1	320	17.5	11.9	<0.001	0.01	0.67	2.7	0.5	0.7	22.3	<0.01	0.05	1.5
I100425		1.57	19.1	340	17.1	12.5	<0.001	0.03	0.67	2.6	0.6	0.6	24.7	<0.01	0.05	1.3
I100426		1.78	18.3	300	18.3	11.2	<0.001	0.02	0.71	2.8	0.6	0.7	22.6	<0.01	0.06	1.9
I100427		2.01	22.6	310	19.9	11.6	<0.001	0.02	0.80	3.3	0.7	0.8	21.3	<0.01	0.06	2.5
I100428		1.68	18.9	320	18.7	11.7	<0.001	0.03	0.68	2.8	0.6	0.7	23.3	<0.01	0.05	1.9

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I100389		0.023	0.06	0.64	19	0.05	6.81	13	<0.5
I100390		0.069	0.12	0.69	75	0.20	4.65	63	0.6
I100391		0.053	0.10	0.68	66	0.15	10.25	66	0.5
I100392		0.070	0.09	0.97	58	0.21	14.05	53	1.4
I100393		0.145	0.17	0.69	86	0.14	8.73	60	3.3
I100394		0.227	0.38	0.45	105	0.21	4.36	83	3.3
I100395		0.136	0.25	0.58	76	0.15	6.25	50	1.3
I100396		0.136	0.15	0.40	70	0.14	4.21	45	1.1
I100397		0.139	0.15	0.41	70	0.20	4.81	46	1.4
I100398		0.042	0.05	0.62	22	0.08	13.45	18	0.9
I100399		0.101	0.06	0.27	59	0.12	1.63	28	1.1
I100400		0.063	0.10	0.78	57	0.18	11.45	51	0.7
I100401		0.071	0.09	0.69	68	0.15	3.77	80	0.7
I100402		0.060	0.17	0.74	82	0.18	4.27	44	<0.5
I100403		0.064	0.14	1.32	81	0.21	5.75	46	0.7
I100404		0.048	0.21	1.69	58	0.23	10.85	51	0.7
I100405		0.047	0.18	1.55	63	0.16	7.61	48	0.8
I100406		0.032	0.18	2.11	52	0.16	15.65	62	<0.5
I100407		0.024	0.09	2.94	17	0.07	15.50	32	<0.5
I100408		0.061	0.17	1.63	40	0.17	11.65	65	<0.5
I100409		0.065	0.16	2.46	51	0.13	12.45	83	<0.5
I100410		0.070	0.17	2.24	62	0.11	11.05	101	<0.5
I100411		0.085	0.19	1.48	86	0.13	8.42	113	<0.5
I100412		0.023	0.08	1.78	23	0.06	7.02	30	<0.5
I100413		0.041	0.10	1.99	52	0.09	7.96	69	<0.5
I100414		0.018	0.02	2.92	7	<0.05	16.65	23	<0.5
I100415		0.040	0.14	1.50	47	0.15	8.75	85	<0.5
I100416		0.012	0.03	1.10	14	0.05	7.22	33	<0.5
I100417		0.029	0.07	1.20	22	0.06	8.74	26	<0.5
I100418		0.029	0.06	1.49	20	0.06	13.35	28	<0.5
I100419		0.075	0.06	0.73	49	0.18	5.38	65	1.6
I100420		0.068	0.10	0.61	70	0.14	4.35	61	0.9
I100421		0.067	0.09	0.53	65	0.15	3.97	55	0.5
I100422		0.064	0.09	0.54	67	0.15	3.95	58	0.6
I100423		0.078	0.11	0.63	78	0.19	4.65	68	1.8
I100424		0.062	0.09	0.57	66	0.14	4.00	58	0.6
I100425		0.068	0.09	0.56	65	0.15	4.01	61	0.5
I100426		0.068	0.09	0.54	67	0.16	4.08	58	0.8
I100427		0.074	0.11	0.61	76	0.16	4.47	66	1.3
I100428		0.070	0.10	0.58	69	0.15	3.97	61	0.7

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 8-OCT-2010
Account: EIASQI

Project: SQI10-06

CERTIFICATE OF ANALYSIS WH10137855

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-OCT-2010
Account: EIASQI

CERTIFICATE WH10137461

Project: SQI10-01

P.O. No.: SQI10-01_13

This report is for 37 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 24-SEP-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
PUL-QC	Pulverizing QC Test
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:
Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137461

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	Au-GRA21 Au Check ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02
I102286		2.10	<0.005			0.18	0.81	5.9	<0.2	<10	60	0.79	0.84	0.58	0.93	59.3
I102287		1.19	<0.005			3.19	1.46	9.9	<0.2	<10	60	1.63	10.15	0.40	3.19	70.9
I102288		1.70	<0.005			0.57	1.71	8.4	<0.2	<10	80	2.35	1.91	0.65	3.67	56.1
I102289		1.40	<0.005			0.19	2.08	2.5	<0.2	<10	80	3.34	0.64	0.78	2.50	42.4
I102290		0.06	2.97	2.89		2.08	1.91	569	2.5	20	130	0.30	257	9.94	1.13	30.6
I102291		2.87	0.043			2.59	1.17	47.7	<0.2	<10	70	1.87	4.90	0.47	1.98	54.2
I102292		1.26	0.131			7.08	1.32	50.2	<0.2	<10	60	1.21	7.43	0.46	34.6	78.7
I102293		1.75	<0.005			0.35	1.09	5.6	<0.2	<10	80	0.80	1.06	0.58	6.71	40.9
I102294		2.20	<0.005			0.27	0.91	5.2	<0.2	<10	80	0.90	1.02	0.56	0.63	50.2
I102295		3.31	0.152			2.12	1.50	8.6	0.2	<10	350	3.10	8.05	0.55	0.92	75.2
I102296		2.85	1.070	0.81		1.93	0.92	24.6	1.0	<10	70	1.10	110.5	0.18	1.17	75.2
I102297		1.42	6.49	4.98	5.09	69.7	0.55	229	2.8	<10	30	1.37	500	0.11	1.05	25.3
I102298		1.43	0.095			8.83	1.19	14.7	<0.2	<10	70	1.48	12.00	0.26	0.68	58.7
I102299		3.74	0.006			0.75	0.77	3.9	<0.2	<10	60	0.93	3.12	0.41	0.38	44.0
I102300		0.99	<0.005			0.19	0.85	5.9	<0.2	<10	110	0.67	0.72	0.32	0.16	34.6
I102301		0.03	<0.005			0.12	0.67	4.9	<0.2	<10	90	0.53	0.64	0.26	0.14	28.2
I102302		4.13	0.121			0.51	0.89	3.4	<0.2	<10	80	1.10	3.04	0.35	0.16	48.0
I102303		1.48	1.495	1.28	2.13	1.50	1.31	15.1	0.3	<10	150	2.04	75.2	0.44	0.25	48.8
I102304		1.95	0.014			1.21	2.17	3.6	<0.2	<10	450	3.24	21.5	0.79	0.41	57.1
I102305		1.91	0.050			0.69	1.28	3.7	<0.2	<10	110	1.68	5.07	0.61	0.15	43.8
I102306		3.72	<0.005			0.34	1.59	3.1	<0.2	<10	190	1.88	3.90	1.02	0.22	53.6
I102307		2.54	<0.005			0.11	2.02	2.6	<0.2	<10	220	2.74	0.45	1.91	0.16	42.7
I102308		2.39	<0.005			0.21	1.97	3.4	<0.2	<10	120	2.55	0.53	1.27	0.23	44.6
I102309		1.80	<0.005			0.13	1.16	3.4	<0.2	<10	90	1.41	0.42	0.66	0.14	39.5
I102310		1.90	<0.005			0.13	1.13	3.8	<0.2	<10	90	1.14	0.25	0.46	0.13	39.8
I102311		2.16	<0.005			0.09	0.89	4.3	<0.2	<10	80	0.78	0.20	0.41	0.17	37.7
I102312		2.14	<0.005			0.10	0.98	4.8	<0.2	<10	80	0.90	2.61	0.55	0.16	46.4
I102313		1.74	<0.005			0.95	1.81	4.0	<0.2	<10	100	2.12	2.04	0.70	0.39	47.8
I102314		2.63	0.010			0.67	1.85	9.4	<0.2	<10	60	2.29	3.15	0.70	0.63	49.7
I102315		3.48	<0.005			0.07	1.15	1.6	<0.2	<10	20	1.21	4.16	0.65	0.11	58.4
I102316		2.03	<0.005			0.26	1.13	1.2	<0.2	<10	20	1.26	4.25	0.50	0.12	55.5
I102317		2.25	<0.005			0.17	1.25	1.6	<0.2	<10	20	1.44	7.30	0.32	0.10	51.8
I102318		1.34	<0.005			0.55	1.93	15.2	<0.2	<10	20	2.92	1.90	0.75	0.16	53.7
I102319		3.30	<0.005			0.32	1.93	4.1	<0.2	<10	110	2.09	1.17	0.75	0.22	34.2
I102320		0.02	<0.005			0.38	1.94	4.6	<0.2	<10	110	2.57	1.52	0.76	0.26	42.6
I102321		4.09	<0.005			0.32	1.16	4.3	<0.2	<10	90	1.12	3.10	0.59	0.20	46.4
I102322		2.22	<0.005			0.12	1.16	4.9	<0.2	<10	80	0.90	4.68	0.66	0.24	40.0

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137461

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Co	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn
	Units	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm
	LOR	0.1	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5
I102286		3.7	15	5.53	55.3	2.06	4.33	0.11	0.24	0.01	0.026	0.30	33.3	13.4	0.48	506
I102287		7.1	11	27.3	234	3.16	6.57	0.10	0.12	0.02	0.139	0.31	40.5	16.6	0.41	3750
I102288		5.9	13	14.30	45.8	2.72	5.68	0.10	0.14	0.01	0.055	0.27	29.8	16.1	0.45	3580
I102289		5.3	14	6.27	11.0	2.41	6.43	0.08	0.15	0.01	0.066	0.28	28.7	14.5	0.57	3160
I102290		26.5	53	1.61	312	5.51	6.46	0.20	0.42	4.64	1.655	0.18	15.2	6.9	0.27	953
I102291		13.2	10	14.60	122.5	3.59	4.67	0.10	0.15	0.05	0.084	0.25	30.8	7.8	0.30	4560
I102292		10.5	7	25.8	1180	2.31	4.99	0.10	0.12	0.09	0.119	0.35	41.6	8.2	0.22	3350
I102293		6.5	17	6.73	15.1	2.65	4.84	0.08	0.15	0.01	0.035	0.33	20.6	12.6	0.57	1600
I102294		5.9	24	5.72	17.7	2.88	5.76	0.14	0.26	<0.01	0.025	0.41	25.8	14.6	0.58	721
I102295		5.6	13	19.20	39.3	3.31	7.28	0.11	0.16	0.01	0.042	0.24	36.3	12.2	0.52	8090
I102296		19.8	10	18.75	338	4.39	4.82	0.13	0.12	0.01	0.046	0.35	38.5	10.7	0.14	1770
I102297		11.9	5	8.42	1240	8.48	5.93	0.17	0.07	0.19	0.308	0.17	16.4	2.1	0.06	417
I102298		9.7	10	12.55	936	3.43	5.90	0.10	0.14	0.01	0.048	0.32	34.2	11.8	0.25	2350
I102299		4.0	14	5.45	44.9	1.93	4.46	0.10	0.23	<0.01	0.014	0.27	23.7	15.1	0.39	490
I102300		3.7	14	7.15	14.5	2.29	4.53	0.11	0.24	<0.01	0.019	0.43	17.7	36.9	0.43	346
I102301		3.2	15	6.29	5.3	1.90	3.74	0.10	0.22	<0.01	0.017	0.34	14.2	33.6	0.39	273
I102302		3.9	16	5.63	174.0	2.39	5.45	0.10	0.23	<0.01	0.024	0.34	25.2	18.4	0.40	597
I102303		9.8	13	10.85	134.5	3.54	6.27	0.11	0.13	0.01	0.040	0.26	26.2	16.6	0.41	1400
I102304		5.1	12	14.30	85.2	2.64	7.55	0.09	0.12	0.01	0.034	0.26	31.8	14.5	0.60	2030
I102305		4.9	14	7.26	21.2	2.27	5.40	0.08	0.16	<0.01	0.015	0.30	22.6	18.3	0.53	498
I102306		4.8	15	7.76	185.5	2.77	6.48	0.09	0.20	<0.01	0.036	0.35	28.3	21.1	0.55	1020
I102307		4.9	12	10.75	10.3	1.95	6.34	0.08	0.14	<0.01	0.010	0.30	23.0	16.5	0.64	861
I102308		5.2	14	6.26	7.3	2.32	6.60	0.09	0.21	<0.01	0.016	0.33	23.6	17.5	0.69	687
I102309		4.3	11	5.30	9.4	1.89	4.98	0.09	0.28	<0.01	0.011	0.31	20.9	19.2	0.55	442
I102310		4.1	12	4.64	6.9	2.04	4.96	0.11	0.37	<0.01	0.012	0.35	21.0	18.9	0.52	398
I102311		5.0	11	4.68	8.8	1.82	4.54	0.11	0.34	<0.01	0.009	0.34	19.5	20.1	0.53	372
I102312		7.1	16	4.93	10.0	2.51	5.66	0.15	0.22	<0.01	0.047	0.34	23.9	21.9	0.64	443
I102313		5.7	16	6.30	10.7	2.71	7.06	0.13	0.18	<0.01	0.063	0.37	23.9	20.7	0.85	1130
I102314		6.1	16	5.50	11.4	3.23	8.37	0.11	0.17	0.01	0.067	0.24	31.5	21.3	0.91	1280
I102315		4.2	14	2.67	5.9	2.66	6.91	0.09	0.39	<0.01	0.054	0.18	28.4	18.2	0.67	766
I102316		3.5	9	2.82	9.7	2.49	6.40	0.09	0.39	<0.01	0.066	0.16	25.9	16.5	0.66	705
I102317		4.4	12	2.52	19.8	2.59	6.57	0.07	0.37	<0.01	0.114	0.17	17.3	18.7	0.70	677
I102318		6.5	14	2.23	10.2	3.04	8.55	0.08	0.10	0.01	0.068	0.12	27.3	22.5	1.11	817
I102319		5.8	18	4.38	5.8	3.03	6.25	0.12	0.12	0.02	0.072	0.36	20.2	23.5	1.03	811
I102320		7.0	17	5.48	6.7	3.07	7.68	0.14	0.15	0.02	0.088	0.36	24.5	28.9	1.07	818
I102321		6.8	17	5.55	10.1	2.79	6.13	0.17	0.25	<0.01	0.051	0.37	24.7	21.4	0.68	770
I102322		6.7	17	4.62	14.9	2.82	6.34	0.18	0.25	0.01	0.052	0.34	21.5	24.3	0.73	543

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137461

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Mo	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01
I102286		4.16	0.03	1.56	3.9	740	84.8	34.6	<0.001	<0.01	1.96	2.7	0.3	1.3	28.3	<0.01
I102287		7.79	0.01	0.19	4.2	760	982	42.3	<0.001	0.01	19.55	3.6	0.4	1.1	62.3	<0.01
I102288		2.32	0.01	0.26	5.0	900	49.0	35.4	<0.001	<0.01	33.6	4.7	0.4	1.1	99.0	<0.01
I102289		0.70	0.01	0.29	4.7	840	24.1	37.2	<0.001	<0.01	7.69	3.1	0.4	1.2	79.0	<0.01
I102290		79.1	0.05	1.06	53.9	860	39.6	11.2	0.003	1.17	7.56	4.6	1.5	115.5	90.7	0.03
I102291		5.36	0.01	0.27	4.0	810	619	33.5	<0.001	0.08	31.6	2.6	0.5	1.2	81.0	<0.01
I102292		8.91	<0.01	0.14	7.2	1010	787	51.2	<0.001	0.59	57.1	2.3	0.6	0.9	76.0	<0.01
I102293		3.67	0.04	0.81	4.8	830	59.4	41.5	<0.001	0.01	1.34	2.8	0.2	1.4	64.3	0.01
I102294		3.71	0.08	2.00	4.8	990	38.8	48.8	<0.001	0.01	1.78	3.1	0.4	1.8	40.5	0.01
I102295		2.80	0.02	0.30	4.7	770	60.7	33.0	<0.001	<0.01	1.49	3.5	0.4	1.6	378	<0.01
I102296		6.63	0.01	0.23	3.3	530	51.8	48.4	<0.001	0.01	4.40	2.0	0.4	4.0	39.1	<0.01
I102297		30.3	0.01	0.26	2.2	1040	654	23.4	<0.001	0.12	215	0.7	1.5	8.5	104.0	<0.01
I102298		3.20	0.01	0.30	3.5	550	217	41.5	<0.001	<0.01	12.60	2.6	0.3	11.6	62.5	<0.01
I102299		3.07	0.04	1.63	3.1	690	59.3	35.7	<0.001	<0.01	2.20	1.9	0.2	1.4	34.0	0.01
I102300		2.11	0.09	2.77	4.2	680	25.3	54.5	<0.001	<0.01	0.68	3.2	0.3	1.8	21.6	0.01
I102301		1.91	0.05	2.96	3.7	630	20.6	47.2	<0.001	0.01	0.57	2.8	0.3	1.5	13.1	0.01
I102302		3.27	0.07	1.32	3.3	680	44.1	39.6	<0.001	<0.01	0.82	2.4	0.3	1.6	35.5	<0.01
I102303		0.80	0.01	0.42	3.5	710	125.0	35.0	<0.001	0.01	1.30	3.3	0.3	1.4	109.5	<0.01
I102304		0.61	0.01	0.19	3.7	880	101.5	31.2	<0.001	0.01	1.05	3.6	0.3	1.4	517	<0.01
I102305		0.62	0.02	0.64	3.5	760	41.0	37.4	<0.001	<0.01	0.57	2.8	0.2	1.4	112.5	<0.01
I102306		0.78	0.03	0.58	3.8	770	60.1	42.2	<0.001	<0.01	0.90	2.8	0.3	1.7	175.0	<0.01
I102307		0.37	0.02	0.36	3.3	730	28.2	36.3	<0.001	<0.01	0.56	2.6	0.3	1.2	452	<0.01
I102308		0.71	0.02	0.45	4.3	790	25.2	36.9	<0.001	<0.01	0.76	2.8	0.3	1.5	162.5	<0.01
I102309		1.05	0.03	0.93	3.4	640	26.0	34.7	<0.001	<0.01	0.64	2.2	0.3	1.2	67.1	0.01
I102310		1.31	0.06	1.40	3.5	600	26.4	37.2	<0.001	0.01	0.74	2.2	0.3	1.4	41.6	0.01
I102311		3.85	0.04	1.67	3.3	600	32.1	36.8	<0.001	0.01	0.69	2.0	0.3	1.2	22.1	0.01
I102312		2.11	0.04	1.51	4.4	860	44.1	36.9	<0.001	0.01	0.91	2.6	0.4	2.2	29.1	0.01
I102313		1.94	0.03	0.58	4.6	900	33.8	42.0	<0.001	0.01	0.68	3.0	0.3	2.0	63.9	<0.01
I102314		1.22	0.01	0.22	5.2	1260	112.0	29.2	<0.001	<0.01	0.61	3.0	0.3	1.4	49.2	<0.01
I102315		0.63	0.02	0.07	3.7	680	18.8	18.8	<0.001	<0.01	0.48	2.3	0.3	0.3	29.1	<0.01
I102316		0.43	0.02	0.06	3.0	750	24.9	15.3	<0.001	<0.01	0.43	2.0	0.3	0.2	26.8	<0.01
I102317		2.70	0.02	0.06	3.3	660	30.8	16.6	<0.001	<0.01	0.51	1.7	0.3	0.2	21.2	<0.01
I102318		0.58	0.01	0.06	5.4	1010	15.4	13.3	<0.001	<0.01	0.32	1.9	0.3	0.5	37.6	<0.01
I102319		0.93	0.03	0.29	4.0	1200	35.8	38.8	<0.001	0.02	0.80	3.0	0.2	1.5	36.8	<0.01
I102320		1.05	0.02	0.32	4.9	1210	44.5	47.0	0.001	0.02	0.83	3.7	0.4	1.9	43.6	0.01
I102321		1.00	0.05	1.03	4.7	910	73.9	49.0	<0.001	0.02	0.74	3.6	0.5	1.8	36.7	0.01
I102322		1.12	0.04	1.14	4.4	950	42.2	43.0	0.001	0.02	0.67	2.8	0.5	1.9	96.3	0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137461

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Te	Th	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102286		0.03	59.1	0.131	0.22	14.85	47	1.04	12.65	78	3.4
I102287		0.30	54.1	0.025	0.47	12.35	36	0.38	15.70	182	2.4
I102288		0.09	39.7	0.056	0.29	5.33	47	0.37	15.95	168	2.8
I102289		0.02	31.7	0.060	0.25	6.27	57	0.30	15.65	174	2.6
I102290		42.3	4.4	0.165	0.13	2.07	35	60.9	10.35	88	18.8
I102291		0.50	34.5	0.034	0.37	14.80	38	0.54	12.65	158	3.1
I102292		1.72	27.3	0.017	0.53	14.15	29	0.38	17.75	511	3.4
I102293		0.05	27.5	0.128	0.28	14.80	56	0.78	14.05	281	2.8
I102294		0.03	37.2	0.189	0.28	13.60	76	0.90	14.75	89	4.2
I102295		0.05	37.3	0.043	0.37	12.20	52	1.03	16.60	99	2.8
I102296		0.40	35.8	0.021	0.52	22.2	37	8.01	10.45	83	2.6
I102297		1.06	27.8	0.006	0.21	47.0	40	166.5	5.28	110	1.6
I102298		0.06	38.7	0.035	0.41	17.80	38	15.80	11.20	129	2.7
I102299		0.01	39.3	0.110	0.21	13.35	47	2.18	10.60	68	3.9
I102300		<0.01	35.2	0.163	0.34	11.25	51	1.08	13.90	40	3.9
I102301		<0.01	30.8	0.143	0.29	9.64	46	0.86	12.05	33	3.4
I102302		0.02	38.3	0.102	0.26	14.90	49	1.32	11.95	56	4.0
I102303		0.19	33.5	0.052	0.28	9.39	50	2.33	11.55	73	2.7
I102304		0.02	34.8	0.034	0.35	8.13	47	1.12	13.85	93	2.4
I102305		0.01	35.4	0.101	0.24	9.25	52	1.01	11.45	58	2.9
I102306		0.01	36.2	0.091	0.32	10.40	53	0.68	12.35	70	3.3
I102307		0.01	33.4	0.076	0.23	9.61	49	0.28	12.50	62	2.5
I102308		0.01	35.2	0.113	0.24	8.40	51	0.39	12.95	58	4.2
I102309		<0.01	33.9	0.113	0.19	9.47	42	0.56	12.85	56	5.5
I102310		<0.01	34.6	0.142	0.22	9.73	41	0.70	13.40	55	6.6
I102311		<0.01	35.1	0.150	0.21	12.55	40	1.20	12.85	60	6.2
I102312		0.01	30.0	0.166	0.25	9.95	56	1.73	13.75	79	3.8
I102313		0.01	31.2	0.136	0.32	7.49	60	1.17	13.95	67	3.6
I102314		0.03	27.2	0.049	0.26	6.94	51	0.77	15.15	143	5.6
I102315		0.02	26.4	0.006	0.19	6.80	35	0.12	12.70	90	14.6
I102316		0.01	24.7	0.006	0.15	6.66	33	0.40	12.65	89	14.6
I102317		0.08	26.0	0.006	0.16	5.54	34	0.34	11.10	91	13.2
I102318		0.14	25.3	0.007	0.14	4.32	44	0.77	12.50	117	3.8
I102319		0.02	22.3	0.100	0.30	5.78	61	1.18	10.70	96	2.4
I102320		0.02	28.1	0.095	0.37	7.68	63	1.38	13.05	100	2.8
I102321		<0.01	29.7	0.152	0.29	9.98	61	0.79	14.70	86	4.0
I102322		<0.01	28.9	0.160	0.25	10.50	62	1.64	13.40	81	4.1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 13-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137461

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

CERTIFICATE WH10137462

Project: SQI10-01

P.O. No.: SQI10-01_12

This report is for 77 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 24-SEP-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
PUL-QC	Pulverizing QC Test
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137462

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1
I102209		1.68	0.005		0.22	0.93	5.4	<0.2	<10	100	0.60	0.26	0.47	0.16	49.0	5.2
I102210		0.02	3.02	2.82	2.20	1.75	546	2.8	20	130	0.41	263	9.51	0.69	34.2	33.0
I102211		1.21	0.093		1.11	1.32	6.1	<0.2	<10	80	1.25	4.82	0.45	0.26	57.1	5.3
I102212		4.04	<0.005		0.11	0.99	4.3	<0.2	<10	90	0.96	0.73	0.45	0.13	49.3	5.4
I102213		5.61	<0.005		0.20	0.95	4.1	<0.2	<10	80	0.96	0.59	0.50	0.13	44.1	4.8
I102214		3.68	<0.005		0.16	1.09	4.1	<0.2	<10	80	1.24	0.60	0.55	0.26	50.6	5.1
I102215		4.56	<0.005		0.10	1.38	3.7	<0.2	<10	90	1.61	0.78	0.67	0.23	51.5	5.5
I102216		4.56	<0.005		0.13	1.84	3.1	<0.2	<10	130	2.41	0.54	1.18	0.25	52.4	6.0
I102217		5.70	<0.005		0.09	1.17	4.0	<0.2	<10	90	1.56	0.63	1.11	0.30	47.8	4.6
I102218		5.61	<0.005		0.09	0.94	4.9	<0.2	<10	80	1.03	0.78	0.82	0.18	43.7	4.5
I102219		0.90	<0.005		0.15	2.07	12.7	<0.2	<10	40	2.59	1.75	1.11	0.28	56.9	6.6
I102220		0.44	<0.005		0.07	0.74	6.7	<0.2	<10	100	0.86	0.37	0.33	0.18	36.3	4.4
I102221		2.66	0.005		0.12	1.06	4.0	<0.2	<10	80	1.38	1.04	0.41	0.16	42.6	4.8
I102222		4.75	0.017		0.08	1.01	3.8	<0.2	<10	60	1.53	1.02	0.40	0.16	40.7	4.5
I102223		4.52	<0.005		0.16	1.68	3.6	<0.2	<10	130	3.22	0.53	0.72	0.26	38.4	5.0
I102224		5.09	<0.005		0.10	1.05	5.2	<0.2	<10	80	1.23	0.54	0.59	0.14	40.1	5.4
I102225		4.09	0.005		0.08	1.16	5.6	<0.2	<10	90	1.36	0.46	0.63	0.23	44.4	5.6
I102226		4.17	0.005		0.07	0.81	2.9	<0.2	<10	60	1.46	0.29	0.41	0.11	39.4	4.3
I102227		4.17	<0.005		0.07	1.53	4.0	<0.2	<10	100	2.72	0.43	1.46	0.24	45.3	5.6
I102228		5.20	<0.005		0.06	1.13	6.4	<0.2	<10	70	1.56	1.09	0.70	0.18	44.9	5.2
I102229		2.23	<0.005		0.06	1.14	7.9	<0.2	<10	80	1.63	1.48	0.53	0.11	49.4	4.1
I102230		2.11	<0.005		0.07	1.20	6.7	<0.2	<10	90	1.70	0.90	0.60	0.10	47.4	4.0
I102231		3.88	<0.005		0.07	1.45	8.5	<0.2	<10	70	2.35	0.24	0.78	0.14	49.8	4.7
I102232		0.50	<0.005		0.05	2.04	6.6	<0.2	<10	60	3.70	0.15	0.95	0.18	44.0	4.3
I102233		3.83	<0.005		0.04	1.47	6.5	<0.2	<10	70	2.45	0.19	0.69	0.13	47.1	4.6
I102234		4.48	<0.005		0.06	2.07	8.1	<0.2	<10	70	2.85	0.66	1.13	0.16	44.2	7.7
I102235		4.59	<0.005		0.07	2.11	8.9	<0.2	<10	110	2.78	0.20	1.27	0.16	45.3	2.9
I102236		4.24	<0.005		0.06	1.72	8.2	<0.2	<10	130	2.23	0.27	0.83	0.13	43.9	2.9
I102237		3.72	<0.005		0.33	1.83	8.3	<0.2	<10	130	2.15	0.48	0.90	0.18	44.7	4.7
I102238		3.63	<0.005		0.07	2.01	8.2	<0.2	<10	190	2.04	0.50	0.86	0.19	48.6	6.4
I102239		3.74	<0.005		0.08	2.29	4.7	<0.2	<10	170	2.81	0.42	1.06	0.18	44.5	5.0
I102240		<0.02	<0.005		0.11	2.28	4.6	<0.2	<10	170	2.77	0.40	1.01	0.18	47.1	5.2
I102241		4.93	<0.005		0.16	2.53	5.0	<0.2	<10	120	2.67	0.95	1.21	0.16	51.7	5.0
I102242		5.00	<0.005		0.10	1.35	6.6	<0.2	<10	100	1.75	0.95	0.54	0.17	51.4	5.0
I102243		1.62	<0.005		0.11	1.26	6.7	<0.2	<10	110	1.41	0.50	0.49	0.11	51.4	5.2
I102244		2.65	0.012		0.41	2.70	9.2	<0.2	<10	100	5.38	3.70	0.91	0.37	59.2	11.5
I102245		4.70	<0.005		0.12	1.11	10.2	<0.2	<10	150	0.91	0.89	0.47	0.29	52.1	6.4
I102246		1.86	<0.005		0.04	0.90	9.1	<0.2	<10	90	0.66	0.52	0.42	0.18	46.5	3.4
I102247		1.30	<0.005		0.07	0.94	8.7	<0.2	<10	100	0.94	2.72	0.41	0.21	52.5	3.5
I102248		2.04	<0.005		0.10	1.17	7.7	<0.2	10	20	1.34	0.56	0.56	0.18	59.0	3.1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137462

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo
	Units	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm
	LOR	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05
I102209		20	7.03	9.6	2.56	4.69	0.10	0.17	<0.01	0.031	0.44	25.1	16.1	0.59	508	3.94
I102210		55	1.74	307	5.26	7.44	0.26	0.44	4.99	1.400	0.17	16.5	8.6	0.27	895	85.1
I102211		16	11.45	9.1	3.03	5.83	0.08	0.12	0.01	0.055	0.33	27.9	16.3	0.56	959	0.97
I102212		19	5.51	8.8	2.54	5.24	0.09	0.16	<0.01	0.031	0.38	24.3	17.5	0.61	462	2.84
I102213		19	5.27	8.2	2.47	4.92	0.08	0.15	<0.01	0.036	0.34	22.2	14.7	0.56	413	2.75
I102214		19	5.83	7.8	2.36	4.99	0.07	0.13	0.02	0.042	0.28	23.5	12.0	0.53	405	1.77
I102215		18	5.63	10.9	2.32	5.44	0.07	0.12	0.02	0.042	0.33	26.8	14.8	0.67	441	1.80
I102216		17	6.48	12.0	2.28	6.20	0.07	0.13	0.01	0.041	0.29	27.5	16.2	0.66	509	0.87
I102217		17	10.60	6.8	2.12	5.11	0.07	0.15	0.01	0.023	0.29	24.6	15.5	0.53	474	1.48
I102218		16	5.05	10.7	2.10	4.68	0.08	0.15	<0.01	0.019	0.29	22.1	15.6	0.46	420	1.33
I102219		13	14.45	13.0	2.22	6.57	0.06	0.08	0.01	0.054	0.24	36.1	7.4	0.46	346	0.61
I102220		16	6.09	3.5	2.25	4.14	0.09	0.22	0.01	0.023	0.35	17.1	36.6	0.40	319	3.06
I102221		10	6.93	8.6	2.00	4.75	0.06	0.19	<0.01	0.035	0.33	21.8	13.8	0.52	365	3.02
I102222		11	5.49	6.5	1.93	4.60	0.05	0.17	0.01	0.025	0.30	20.9	13.8	0.47	356	1.22
I102223		12	5.33	5.9	1.85	5.84	<0.05	0.13	0.01	0.024	0.27	21.5	14.9	0.58	536	0.64
I102224		14	5.43	4.8	2.15	4.62	0.06	0.18	<0.01	0.028	0.38	20.2	17.7	0.55	408	1.73
I102225		15	6.45	7.0	2.19	4.78	0.07	0.17	<0.01	0.034	0.35	21.9	16.1	0.51	404	1.64
I102226		14	4.62	11.1	1.78	3.99	0.05	0.17	<0.01	0.018	0.28	20.8	12.6	0.40	299	2.77
I102227		13	7.60	7.2	2.18	5.85	0.06	0.14	0.01	0.037	0.31	23.7	16.3	0.54	547	2.91
I102228		14	4.47	6.1	2.41	5.60	0.07	0.16	0.01	0.038	0.27	23.2	18.3	0.56	428	1.43
I102229		18	6.00	5.6	2.32	5.29	0.08	0.19	<0.01	0.030	0.30	26.2	17.3	0.55	340	1.18
I102230		19	5.69	5.3	2.25	5.19	0.07	0.18	0.01	0.028	0.29	26.3	16.5	0.55	322	1.10
I102231		16	5.14	11.3	2.29	5.79	0.08	0.19	<0.01	0.030	0.34	25.5	15.6	0.56	349	0.74
I102232		15	5.87	8.7	2.16	6.45	<0.05	0.13	<0.01	0.021	0.31	22.0	15.6	0.65	328	0.66
I102233		17	5.13	6.0	2.17	5.50	0.07	0.17	0.01	0.019	0.33	24.9	15.8	0.55	330	0.82
I102234		12	3.86	41.6	2.33	7.04	0.07	0.10	0.01	0.025	0.26	23.3	23.0	0.78	367	0.49
I102235		11	3.61	7.0	2.23	7.02	0.06	0.09	0.01	0.027	0.23	22.4	23.0	0.76	330	0.32
I102236		8	4.14	8.2	2.33	6.51	0.06	0.11	0.01	0.027	0.21	22.1	20.6	0.72	329	0.48
I102237		8	5.25	12.3	2.42	6.86	0.07	0.11	0.01	0.029	0.28	23.6	24.4	0.95	384	0.43
I102238		8	7.62	9.3	2.51	7.43	0.07	0.12	0.01	0.042	0.34	23.0	23.2	0.81	421	0.42
I102239		8	5.14	4.8	2.31	6.93	0.06	0.11	0.01	0.039	0.32	23.0	21.6	0.77	408	0.31
I102240		9	5.37	5.3	2.33	7.35	0.07	0.14	0.01	0.042	0.32	24.1	22.1	0.76	414	0.36
I102241		7	4.90	5.9	2.16	7.60	0.07	0.11	0.01	0.039	0.31	27.1	18.7	0.70	364	0.66
I102242		10	4.71	6.0	2.10	5.84	0.08	0.16	<0.01	0.034	0.34	27.2	24.4	0.65	316	0.91
I102243		11	5.73	7.3	2.29	5.83	0.11	0.19	<0.01	0.033	0.39	27.3	24.8	0.65	335	1.22
I102244		7	6.72	37.7	2.31	8.80	0.07	0.09	0.01	0.039	0.28	29.8	22.0	0.94	469	0.64
I102245		10	7.13	12.7	2.12	5.35	0.12	0.16	<0.01	0.040	0.36	26.9	25.0	0.60	369	1.76
I102246		12	4.70	2.7	2.16	4.09	0.11	0.16	<0.01	0.029	0.37	24.3	19.5	0.52	267	0.78
I102247		13	5.17	31.8	2.27	4.35	0.12	0.18	<0.01	0.039	0.34	27.4	18.9	0.45	354	2.31
I102248		4	4.89	59.7	2.01	2.45	0.05	0.11	<0.01	0.026	0.12	22.7	6.0	0.27	507	1.54

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137462

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01
I102209		0.08	1.57	4.4	900	28.3	58.9	<0.001	0.01	1.22	2.5	0.2	2.2	29.8	0.01	0.02
I102210		0.04	1.33	66.5	810	45.4	11.0	0.003	1.14	9.50	7.1	1.6	109.5	88.8	0.03	43.4
I102211		0.02	0.39	5.2	950	139.5	48.0	<0.001	<0.01	1.00	4.0	0.2	2.5	44.1	<0.01	0.06
I102212		0.06	1.25	4.6	930	26.3	50.7	<0.001	<0.01	0.98	2.5	0.2	1.9	26.9	0.01	0.03
I102213		0.06	1.06	4.2	870	28.1	43.7	<0.001	<0.01	0.96	2.5	0.2	2.1	35.2	0.01	0.02
I102214		0.04	0.53	4.1	880	41.4	35.7	<0.001	<0.01	0.61	3.5	0.2	1.8	58.3	<0.01	0.04
I102215		0.04	0.44	4.3	880	31.3	45.1	<0.001	<0.01	0.64	3.3	0.2	2.0	51.6	<0.01	0.04
I102216		0.04	0.38	4.1	800	29.5	37.5	<0.001	<0.01	0.53	3.4	0.2	1.9	165.0	<0.01	0.02
I102217		0.05	0.62	3.7	800	28.3	39.2	<0.001	0.01	0.62	2.6	0.2	1.6	81.7	0.01	0.02
I102218		0.06	1.05	3.7	800	30.4	38.5	<0.001	0.02	0.77	2.1	0.2	1.5	35.9	<0.01	0.02
I102219		0.02	0.08	2.8	1730	40.7	32.3	<0.001	0.01	0.85	3.9	0.3	3.1	46.9	0.01	0.06
I102220		0.06	3.27	4.7	850	23.1	43.2	<0.001	0.01	0.51	3.0	0.5	2.9	13.9	0.01	0.01
I102221		0.05	1.12	3.1	610	29.0	36.5	0.001	0.01	0.65	3.2	0.3	2.1	61.8	0.01	0.02
I102222		0.06	0.94	2.9	590	25.1	36.2	<0.001	0.01	0.50	2.9	0.2	1.9	39.8	0.01	0.02
I102223		0.03	0.41	3.1	790	29.8	31.1	<0.001	0.01	0.40	3.2	0.3	1.9	199.5	0.01	0.02
I102224		0.06	1.23	3.8	810	28.0	40.2	<0.001	<0.01	0.67	3.1	0.3	2.0	41.3	0.01	0.01
I102225		0.05	0.84	3.8	790	31.5	38.3	<0.001	<0.01	0.71	3.9	0.3	2.1	87.9	0.01	0.01
I102226		0.04	1.45	2.9	650	23.6	33.0	<0.001	<0.01	0.56	2.4	0.2	1.5	37.5	0.01	0.01
I102227		0.04	0.61	3.5	750	28.9	37.4	<0.001	<0.01	0.47	4.1	0.3	2.0	161.5	0.01	0.01
I102228		0.06	0.84	3.7	820	33.0	32.0	<0.001	<0.01	0.82	3.0	0.2	2.4	102.0	0.01	0.01
I102229		0.05	0.85	4.2	860	26.6	34.8	<0.001	<0.01	0.73	2.7	0.3	1.9	119.5	0.01	0.02
I102230		0.04	0.80	4.0	890	25.4	32.3	<0.001	0.01	0.67	2.8	0.3	1.8	163.5	0.01	0.01
I102231		0.05	0.76	3.9	850	24.7	37.7	<0.001	0.01	0.68	3.5	0.3	2.3	71.4	0.01	0.01
I102232		0.05	0.35	3.6	840	26.8	37.5	<0.001	0.01	0.63	3.1	0.3	1.6	86.3	0.01	0.01
I102233		0.05	0.64	3.8	870	25.1	35.5	<0.001	<0.01	0.61	3.1	0.3	1.5	60.9	0.01	0.01
I102234		0.03	0.27	3.5	1180	19.1	29.2	<0.001	<0.01	0.54	3.0	0.3	1.9	65.9	0.01	0.03
I102235		0.03	0.20	2.9	1190	23.7	24.1	<0.001	<0.01	0.49	2.5	0.2	1.6	79.2	<0.01	0.01
I102236		0.04	0.28	3.0	1200	21.0	21.4	<0.001	<0.01	0.60	2.3	0.2	1.6	177.0	0.01	0.01
I102237		0.04	0.30	3.3	1240	23.0	30.6	<0.001	<0.01	0.68	2.6	0.2	1.8	131.0	0.01	0.01
I102238		0.05	0.27	3.6	1140	22.8	37.5	<0.001	<0.01	0.71	3.7	0.2	1.8	265	0.01	0.01
I102239		0.05	0.23	3.3	1000	23.8	32.7	<0.001	<0.01	0.45	3.6	0.3	1.6	285	0.01	0.01
I102240		0.05	0.30	3.6	970	23.9	34.9	<0.001	<0.01	0.52	4.0	0.3	1.8	262	0.01	0.01
I102241		0.05	0.24	3.0	870	24.8	34.8	<0.001	<0.01	0.46	3.2	0.2	1.8	167.0	0.01	0.01
I102242		0.04	0.82	3.6	740	30.6	39.2	<0.001	<0.01	0.55	3.2	0.3	2.3	49.2	0.01	0.01
I102243		0.06	1.16	4.0	770	34.3	45.8	<0.001	<0.01	0.72	3.7	0.4	2.7	28.4	0.01	0.01
I102244		0.02	0.16	3.9	820	41.7	39.0	<0.001	<0.01	0.71	4.5	0.3	2.5	97.2	0.03	0.04
I102245		0.05	1.13	3.9	780	39.2	39.7	<0.001	0.10	0.81	3.3	0.4	3.2	42.3	0.01	0.02
I102246		0.07	1.37	3.2	740	28.3	34.3	<0.001	<0.01	0.78	2.4	0.3	2.1	22.7	0.01	0.01
I102247		0.07	1.31	3.8	760	32.9	34.2	<0.001	<0.01	1.20	2.3	0.4	2.2	32.4	0.01	0.02
I102248		0.03	0.05	3.0	1140	21.0	14.4	<0.001	<0.01	0.63	1.2	0.3	0.4	26.8	0.01	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137462

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Th	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102209		31.4	0.178	0.35	9.31	62	2.45	12.35	51	3.0
I102210		4.6	0.156	0.14	2.32	31	67.8	9.25	85	20.0
I102211		28.4	0.077	0.42	7.59	51	1.57	12.30	87	1.9
I102212		29.2	0.154	0.34	11.50	63	0.95	12.40	53	2.6
I102213		32.8	0.133	0.29	14.00	58	1.14	12.10	56	2.5
I102214		33.7	0.085	0.26	12.25	56	0.72	12.90	57	2.0
I102215		33.4	0.095	0.33	9.47	57	0.64	13.45	58	1.9
I102216		34.1	0.076	0.26	9.44	55	0.58	14.30	51	2.3
I102217		35.9	0.091	0.25	14.80	53	0.54	13.65	47	2.3
I102218		34.4	0.117	0.26	12.55	54	0.57	10.35	44	2.4
I102219		32.1	0.012	0.32	10.00	38	0.96	14.95	42	1.3
I102220		31.9	0.156	0.28	11.20	60	1.04	16.40	40	3.4
I102221		38.4	0.100	0.29	16.55	44	1.02	11.80	48	3.0
I102222		34.1	0.085	0.25	14.30	42	0.64	11.45	43	3.0
I102223		33.8	0.070	0.22	9.51	47	0.59	12.45	40	2.3
I102224		30.8	0.136	0.27	11.00	55	0.87	11.80	49	3.0
I102225		29.8	0.112	0.26	10.70	54	0.84	13.10	52	2.9
I102226		35.3	0.104	0.21	15.60	46	0.85	10.65	44	2.9
I102227		34.2	0.087	0.27	11.10	52	0.68	13.25	50	2.4
I102228		31.2	0.110	0.21	11.35	54	0.64	12.75	56	2.6
I102229		33.0	0.111	0.24	11.40	55	0.60	12.35	55	3.3
I102230		31.9	0.107	0.23	11.15	55	0.51	12.30	54	3.1
I102231		36.5	0.121	0.23	10.75	58	0.67	14.00	41	2.8
I102232		30.4	0.090	0.22	7.43	58	0.31	12.65	41	1.7
I102233		32.7	0.112	0.22	10.75	60	0.36	13.20	41	2.6
I102234		21.2	0.083	0.20	5.53	56	0.42	10.95	42	1.9
I102235		16.3	0.068	0.20	4.10	51	0.30	8.54	41	1.7
I102236		14.7	0.088	0.18	3.86	52	0.40	8.41	43	2.0
I102237		16.7	0.105	0.25	4.97	53	1.06	9.78	44	2.2
I102238		18.6	0.097	0.32	5.76	52	0.44	10.50	45	2.5
I102239		19.3	0.085	0.28	4.83	55	0.33	10.40	50	2.2
I102240		19.9	0.096	0.28	5.11	54	0.40	11.10	51	2.7
I102241		23.2	0.063	0.30	5.87	48	0.69	11.25	45	2.4
I102242		28.9	0.124	0.32	9.21	49	0.57	11.80	43	2.9
I102243		28.8	0.149	0.36	9.70	48	0.81	12.80	47	3.2
I102244		27.3	0.045	0.34	7.25	36	0.62	13.15	46	1.8
I102245		27.3	0.150	0.33	10.05	47	1.18	11.90	52	2.7
I102246		24.3	0.148	0.28	8.69	51	0.61	10.90	42	2.9
I102247		26.8	0.138	0.30	8.90	50	0.58	12.15	41	3.1
I102248		24.7	0.007	0.14	6.45	18	0.19	13.15	39	3.8

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137462

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-MS41 Ag ppm 0.01	ME-MS41 Al % 0.01	ME-MS41 As ppm 0.1	ME-MS41 Au ppm 0.2	ME-MS41 B ppm 10	ME-MS41 Ba ppm 10	ME-MS41 Be ppm 0.05	ME-MS41 Bi ppm 0.01	ME-MS41 Ca % 0.01	ME-MS41 Cd ppm 0.01	ME-MS41 Ce ppm 0.02	ME-MS41 Co ppm 0.1
I102249		1.22	<0.005		0.10	1.30	9.0	<0.2	<10	70	1.69	1.14	0.51	0.20	50.7	8.8
I102250		0.04	0.302		9.42	0.53	8.1	0.3	<10	240	0.23	1.70	2.41	0.15	12.35	4.4
I102251		3.81	<0.005		0.10	1.29	8.1	<0.2	<10	100	1.09	0.62	0.64	0.19	49.9	4.9
I102252		3.90	<0.005		0.07	1.07	6.3	<0.2	<10	100	0.92	1.60	0.48	0.16	48.7	3.9
I102253		3.01	<0.005		0.17	1.05	20.4	<0.2	<10	100	0.74	1.35	0.48	0.35	47.2	9.3
I102254		4.10	<0.005		0.10	1.65	8.3	<0.2	<10	90	2.40	1.17	0.61	0.20	54.1	5.7
I102255		4.21	<0.005		0.18	0.88	28.2	<0.2	<10	90	0.74	1.44	0.42	0.22	45.3	5.9
I102256		3.70	<0.005		0.22	0.80	21.7	<0.2	<10	100	0.47	1.51	0.36	0.38	48.8	7.9
I102257		3.88	<0.005		0.24	1.00	48.4	<0.2	<10	100	0.80	1.69	0.41	0.33	50.4	8.3
I102258		4.18	<0.005		0.21	0.68	8.7	<0.2	<10	90	0.41	0.82	0.37	0.23	50.2	4.4
I102259		4.17	<0.005		0.19	0.65	7.3	<0.2	<10	100	0.41	0.79	0.38	0.25	49.5	4.1
I102260		0.69	<0.005		0.08	0.70	5.0	<0.2	<10	100	0.70	0.30	0.29	0.20	31.2	3.4
I102261		4.58	<0.005		0.16	0.61	7.5	<0.2	<10	90	0.37	2.80	0.35	0.21	46.8	3.6
I102262		4.17	<0.005		0.35	0.79	17.5	<0.2	<10	100	0.53	5.61	0.42	0.38	43.2	6.6
I102263		3.36	0.007		0.26	0.98	9.2	<0.2	<10	100	0.84	12.05	0.52	0.24	44.0	7.2
I102264		4.31	<0.005		0.23	0.85	8.8	<0.2	<10	90	0.54	2.22	0.47	0.23	44.7	6.0
I102265		2.64	<0.005		0.23	1.03	12.8	<0.2	<10	100	0.89	0.96	0.44	0.25	47.0	8.0
I102266		3.16	<0.005		0.25	1.44	20.5	<0.2	<10	100	1.44	4.23	0.53	0.46	46.4	8.4
I102267		2.37	<0.005		0.14	1.42	15.3	<0.2	<10	90	1.44	4.96	0.51	0.25	47.0	7.5
I102268		1.99	<0.005		0.16	1.36	7.4	<0.2	<10	90	2.04	3.21	0.48	0.30	47.3	3.8
I102269		1.15	<0.005		0.23	2.25	9.6	<0.2	<10	110	1.99	1.96	0.75	0.16	53.1	6.0
I102270		1.37	NSS		0.20	2.05	10.0	<0.2	<10	110	1.98	2.01	0.77	0.18	49.8	6.1
I102271		3.75	<0.005		0.18	1.37	13.6	<0.2	<10	130	1.05	1.52	0.54	0.09	40.7	4.7
I102272		4.35	<0.005		0.22	1.02	25.6	<0.2	<10	90	0.81	8.33	0.48	0.33	44.1	4.9
I102273		3.98	<0.005		0.23	0.92	16.1	<0.2	<10	90	0.80	2.52	0.47	0.34	42.1	5.5
I102274		5.10	<0.005		0.13	1.42	9.8	<0.2	<10	120	1.61	1.25	0.51	0.21	45.6	4.7
I102275		4.11	<0.005		0.13	1.30	5.9	<0.2	10	90	1.56	1.02	0.44	0.17	51.5	4.2
I102276		3.20	0.016		0.35	1.14	10.1	<0.2	10	50	1.39	4.57	0.54	0.15	51.3	4.3
I102277		2.79	0.006		0.25	0.68	11.4	<0.2	20	100	1.39	0.99	0.25	0.15	59.2	6.0
I102278		2.82	<0.005		0.15	0.62	7.3	<0.2	30	40	0.73	1.21	0.26	0.11	41.2	3.1
I102279		4.27	<0.005		0.08	1.15	6.9	<0.2	<10	110	0.87	1.06	0.43	0.22	49.5	4.5
I102280		<0.02	<0.005		0.09	1.18	7.8	<0.2	<10	110	0.94	1.05	0.44	0.26	50.4	4.9
I102281		1.64	<0.005		0.13	1.51	5.5	<0.2	<10	90	1.36	1.06	0.55	0.20	60.2	3.9
I102282		4.90	<0.005		0.18	1.79	8.9	<0.2	<10	90	2.11	1.76	0.69	0.23	55.5	7.9
I102283		4.92	<0.005		0.10	2.03	7.9	<0.2	<10	110	2.22	1.06	0.75	0.24	53.0	6.7
I102284		3.19	0.018		0.13	1.98	6.0	<0.2	<10	130	1.94	1.08	0.77	0.25	49.8	5.3
I102285		2.17	0.032		0.14	0.98	20.7	<0.2	<10	80	1.91	0.79	0.54	0.17	57.3	16.8

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137462

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cr	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo
	Units	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm
	LOR	1	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05
I102249		8	4.86	53.5	2.28	4.57	0.07	0.15	0.01	0.047	0.30	27.2	13.3	0.50	379	0.81
I102250		3	0.88	6460	1.39	1.71	<0.05	0.04	0.89	0.021	0.28	6.0	1.9	0.11	414	148.5
I102251		12	4.50	29.9	2.11	5.04	0.09	0.18	<0.01	0.033	0.37	26.3	20.8	0.53	297	2.70
I102252		13	4.62	15.7	2.20	4.89	0.11	0.19	<0.01	0.025	0.37	25.0	20.4	0.53	246	1.76
I102253		13	5.31	43.8	2.42	4.98	0.12	0.19	<0.01	0.044	0.38	24.1	20.4	0.54	300	3.14
I102254		11	5.12	18.7	2.12	6.24	0.09	0.18	<0.01	0.038	0.34	29.5	21.2	0.66	340	0.94
I102255		12	4.97	23.6	2.05	4.65	<0.05	0.14	<0.01	0.037	0.35	23.8	21.2	0.49	274	2.59
I102256		12	5.64	11.8	2.47	4.51	0.05	0.17	<0.01	0.033	0.39	26.1	23.1	0.50	296	2.95
I102257		11	7.48	38.9	2.34	4.88	0.05	0.16	<0.01	0.048	0.38	26.5	21.5	0.48	358	3.09
I102258		15	5.73	7.8	2.06	4.26	0.05	0.20	<0.01	0.028	0.35	26.3	17.3	0.40	308	1.74
I102259		16	6.93	4.5	2.13	4.15	<0.05	0.24	<0.01	0.024	0.37	25.8	16.3	0.39	334	3.18
I102260		13	5.76	3.7	2.07	3.88	<0.05	0.20	<0.01	0.016	0.36	16.0	34.5	0.38	260	3.23
I102261		15	5.55	9.0	1.96	3.86	<0.05	0.21	<0.01	0.024	0.34	24.7	17.1	0.38	322	1.63
I102262		12	4.37	55.6	2.17	4.45	0.06	0.15	<0.01	0.044	0.37	23.2	20.5	0.48	289	3.59
I102263		13	5.65	58.9	2.18	5.07	<0.05	0.15	<0.01	0.072	0.35	23.7	22.8	0.52	343	3.71
I102264		15	4.87	11.7	1.99	4.44	<0.05	0.16	0.01	0.038	0.35	23.6	23.8	0.49	306	3.29
I102265		14	7.29	46.5	2.26	5.27	<0.05	0.15	<0.01	0.049	0.37	25.6	22.9	0.53	422	4.01
I102266		11	7.84	61.6	2.38	5.78	<0.05	0.14	<0.01	0.067	0.32	26.5	19.9	0.59	612	4.36
I102267		12	7.69	79.4	2.05	5.83	<0.05	0.18	<0.01	0.047	0.33	25.6	22.9	0.64	385	1.49
I102268		13	9.37	52.1	2.27	6.16	<0.05	0.15	<0.01	0.036	0.36	26.0	23.5	0.65	437	1.59
I102269		12	7.29	22.3	2.20	7.91	<0.05	0.12	<0.01	0.039	0.33	27.9	24.6	0.78	516	0.75
I102270		11	7.62	23.3	2.06	7.27	<0.05	0.11	<0.01	0.037	0.33	27.1	25.4	0.75	506	0.67
I102271		13	6.63	20.1	2.29	5.71	<0.05	0.14	<0.01	0.038	0.36	20.3	22.2	0.60	379	2.26
I102272		12	6.51	37.8	2.29	4.90	0.05	0.14	0.01	0.049	0.39	23.2	21.8	0.53	201	4.14
I102273		12	5.81	42.6	1.99	4.62	<0.05	0.13	<0.01	0.057	0.36	22.5	19.8	0.49	278	3.83
I102274		13	8.65	13.9	2.41	5.98	<0.05	0.13	<0.01	0.038	0.40	24.9	23.7	0.68	666	1.75
I102275		11	7.30	11.4	2.25	4.96	<0.05	0.11	<0.01	0.033	0.37	27.0	17.6	0.52	642	2.27
I102276		8	10.95	56.5	3.00	4.36	<0.05	0.13	0.01	0.061	0.30	27.2	8.7	0.30	821	2.76
I102277		7	32.2	25.5	4.80	3.23	<0.05	0.12	0.01	0.043	0.24	30.8	5.1	0.07	1240	3.35
I102278		8	7.57	26.3	2.52	2.37	<0.05	0.08	<0.01	0.035	0.20	19.5	3.9	0.10	265	3.63
I102279		15	10.05	3.5	2.50	5.73	<0.05	0.13	<0.01	0.036	0.44	25.5	22.9	0.66	498	4.27
I102280		15	10.05	6.8	2.58	5.89	<0.05	0.13	<0.01	0.039	0.45	25.5	24.1	0.65	507	4.32
I102281		12	11.70	4.6	2.07	5.82	<0.05	0.14	0.01	0.054	0.28	33.1	16.9	0.47	647	1.49
I102282		12	8.74	14.2	2.38	6.02	<0.05	0.15	<0.01	0.047	0.34	29.0	18.3	0.65	692	1.51
I102283		13	8.89	18.5	2.47	6.80	<0.05	0.14	<0.01	0.052	0.34	29.4	19.7	0.69	816	0.88
I102284		14	9.55	5.8	2.56	6.87	<0.05	0.13	<0.01	0.048	0.34	26.6	17.7	0.63	880	1.40
I102285		7	33.7	2.0	2.81	4.30	<0.05	0.11	0.01	0.075	0.30	32.0	6.4	0.15	2200	0.68

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137462

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Na	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.01	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01
I102249		0.05	0.53	3.8	830	36.7	31.2	<0.001	<0.01	0.72	3.1	0.3	2.2	37.4	0.01	0.03
I102250		0.03	0.05	4.1	400	15.4	6.3	0.042	1.46	14.05	0.9	0.3	0.3	370	<0.01	2.06
I102251		0.08	1.13	3.6	940	33.1	35.4	<0.001	<0.01	0.84	2.5	0.3	2.0	36.3	0.01	0.02
I102252		0.07	1.28	3.6	830	31.7	36.9	<0.001	<0.01	0.61	2.3	0.3	1.8	37.6	0.01	0.04
I102253		0.08	1.61	3.7	810	35.9	36.0	<0.001	0.39	0.86	3.0	0.6	2.3	40.7	0.01	0.05
I102254		0.04	0.59	3.7	860	37.1	36.9	<0.001	<0.01	0.67	3.7	0.3	2.3	59.9	0.01	0.04
I102255		0.06	1.58	4.1	770	43.2	39.1	<0.001	0.59	0.71	2.5	0.6	1.6	29.2	0.01	0.05
I102256		0.06	2.78	4.6	740	53.4	49.7	<0.001	1.67	0.82	3.7	1.0	2.3	64.9	0.01	0.07
I102257		0.07	1.79	4.0	790	56.8	44.3	0.001	0.94	0.87	3.6	0.7	2.7	41.6	0.01	0.10
I102258		0.07	2.03	3.1	780	62.7	39.1	<0.001	0.03	0.68	1.9	0.3	2.1	64.4	0.01	0.02
I102259		0.09	2.19	3.3	760	57.6	40.6	<0.001	0.07	0.61	2.0	0.3	2.0	69.8	0.01	0.01
I102260		0.08	2.64	3.7	690	20.6	44.2	<0.001	<0.01	0.39	2.7	0.3	1.6	17.2	0.01	<0.01
I102261		0.07	2.27	3.2	750	55.6	37.5	<0.001	0.06	0.57	2.0	0.3	1.8	45.9	0.01	0.02
I102262		0.06	2.06	3.5	730	52.7	43.1	<0.001	1.01	0.71	3.3	1.0	6.7	46.6	0.01	0.14
I102263		0.07	1.28	3.4	740	46.4	41.5	<0.001	0.17	0.73	3.1	0.8	7.4	35.8	0.01	0.13
I102264		0.06	1.56	3.0	770	46.4	39.7	<0.001	0.20	0.71	2.1	0.5	2.4	47.5	0.01	0.10
I102265		0.06	1.30	3.6	800	49.2	45.4	<0.001	0.06	1.10	3.1	0.4	3.5	39.0	0.01	0.04
I102266		0.04	0.73	3.7	760	46.9	40.1	<0.001	0.08	0.94	3.5	0.4	3.6	48.6	0.01	0.07
I102267		0.04	0.57	3.6	770	48.6	42.1	<0.001	0.01	0.75	3.1	0.3	3.4	45.0	<0.01	0.08
I102268		0.04	0.66	4.2	790	42.1	45.4	<0.001	<0.01	0.53	3.5	0.4	3.9	44.3	0.01	0.11
I102269		0.03	0.30	3.1	820	44.8	42.6	<0.001	<0.01	0.74	4.9	0.4	3.9	71.6	<0.01	0.12
I102270		0.02	0.33	3.2	830	43.2	43.3	<0.001	<0.01	0.81	4.9	0.4	4.0	94.2	<0.01	0.15
I102271		0.04	0.90	2.9	850	51.7	46.1	<0.001	0.56	0.90	4.5	1.1	4.1	119.5	0.01	0.10
I102272		0.06	1.80	3.4	790	47.5	50.3	<0.001	0.90	0.85	3.7	1.1	3.8	45.2	0.01	0.11
I102273		0.05	1.71	3.3	780	48.9	44.7	0.001	0.45	0.77	3.2	0.6	3.5	32.7	0.01	0.07
I102274		0.04	0.84	3.8	850	41.5	53.7	<0.001	0.13	0.63	4.0	0.5	3.3	69.0	<0.01	0.03
I102275		0.03	0.46	3.0	850	33.4	49.0	<0.001	0.01	0.88	2.8	0.3	2.7	53.1	<0.01	0.01
I102276		0.01	0.22	2.2	1600	29.2	43.7	0.001	<0.01	2.37	2.0	0.3	2.6	50.3	<0.01	0.10
I102277		0.01	0.17	2.4	940	21.5	39.3	<0.001	<0.01	2.78	1.0	0.2	2.8	48.7	<0.01	0.01
I102278		0.01	0.12	1.5	770	18.1	25.5	0.001	<0.01	1.59	0.9	0.2	1.1	18.8	<0.01	0.01
I102279		0.05	1.15	3.7	820	39.6	60.3	<0.001	<0.01	0.72	3.6	0.3	2.9	73.0	<0.01	<0.01
I102280		0.06	1.19	6.4	800	41.2	60.7	<0.001	<0.01	0.77	3.7	0.3	3.0	72.0	0.01	0.01
I102281		0.02	0.27	4.5	840	33.0	35.0	<0.001	<0.01	0.66	3.6	0.3	1.6	71.9	<0.01	<0.01
I102282		0.04	0.37	4.3	810	41.0	42.7	<0.001	<0.01	0.78	3.5	0.3	2.1	135.0	0.01	0.01
I102283		0.03	0.30	4.1	840	43.3	42.8	<0.001	<0.01	0.60	4.0	0.3	2.4	96.4	<0.01	0.01
I102284		0.05	0.39	3.7	850	35.3	41.4	<0.001	<0.01	0.84	3.5	0.3	2.2	297	<0.01	<0.01
I102285		0.01	0.08	2.5	1220	11.5	44.9	<0.001	<0.01	2.69	3.2	0.2	1.2	169.0	<0.01	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137462

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Th	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.2	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102249		27.8	0.097	0.24	7.24	39	0.53	12.05	42	3.1
I102250		0.9	<0.005	0.04	0.79	12	4.67	3.93	41	1.4
I102251		27.3	0.147	0.27	9.29	52	0.60	12.10	48	3.2
I102252		28.3	0.145	0.27	10.05	56	0.83	12.80	45	3.4
I102253		27.5	0.165	0.28	10.80	50	0.90	12.30	48	3.7
I102254		29.9	0.111	0.31	7.93	50	0.53	13.65	50	3.8
I102255		26.7	0.147	0.31	10.65	42	0.66	12.45	59	2.8
I102256		27.6	0.158	0.42	13.65	35	0.76	12.75	63	3.4
I102257		27.6	0.161	0.37	12.55	37	1.01	12.55	65	3.3
I102258		28.5	0.158	0.29	11.20	51	0.89	13.00	62	4.2
I102259		30.2	0.156	0.29	15.05	50	1.16	14.35	60	4.7
I102260		29.0	0.151	0.29	9.89	49	0.82	14.25	31	3.3
I102261		28.1	0.153	0.28	12.25	49	0.68	13.35	57	4.0
I102262		26.2	0.150	0.34	10.95	38	0.67	12.00	59	2.9
I102263		27.2	0.141	0.33	10.60	46	0.68	12.30	54	3.2
I102264		26.5	0.153	0.33	11.00	50	0.61	12.35	63	3.0
I102265		26.5	0.153	0.38	9.03	51	0.69	14.05	62	3.1
I102266		28.1	0.125	0.37	10.45	44	0.66	13.25	66	3.0
I102267		27.1	0.122	0.36	7.27	46	0.59	13.10	58	4.2
I102268		27.3	0.127	0.43	8.03	51	0.66	14.45	57	3.4
I102269		31.3	0.090	0.41	10.55	49	0.69	13.40	60	2.6
I102270		29.7	0.083	0.42	10.50	48	0.55	13.15	69	2.3
I102271		31.6	0.142	0.43	14.25	44	0.54	11.20	43	2.9
I102272		29.0	0.161	0.43	11.10	43	0.71	13.15	48	2.5
I102273		27.7	0.158	0.36	10.05	46	0.67	12.30	51	2.3
I102274		30.2	0.127	0.49	9.34	51	0.51	14.35	58	2.8
I102275		28.1	0.076	0.46	7.15	39	1.56	13.55	49	2.7
I102276		33.5	0.023	0.48	18.75	26	1.84	11.35	59	3.2
I102277		27.1	0.009	0.50	12.80	18	2.42	11.60	73	3.1
I102278		24.5	0.010	0.28	6.39	15	0.78	10.10	29	2.4
I102279		27.7	0.154	0.50	8.44	55	0.69	14.20	62	2.5
I102280		26.3	0.155	0.51	7.81	54	0.70	14.30	64	2.6
I102281		28.1	0.049	0.32	5.10	45	0.82	15.70	54	3.9
I102282		33.7	0.089	0.38	7.84	44	0.36	15.20	55	3.6
I102283		29.9	0.082	0.38	6.11	49	0.35	14.65	58	3.5
I102284		25.3	0.108	0.30	5.16	56	0.62	14.75	61	2.9
I102285		27.4	0.007	0.56	9.72	23	1.29	13.90	54	3.8

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137462

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

CERTIFICATE WH10137378

Project: SQI10-01

P.O. No.: SQI10-01_15

This report is for 32 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 24-SEP-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
PUL-QC	Pulverizing QC Test
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137378

Sample Description	Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I102387		2.41	<0.005	0.14	0.84	5.9	<0.2	<10	90	0.70	0.56	0.48	0.25	41.9	4.4	14
I102388		1.26	0.005	0.29	1.81	5.2	<0.2	<10	60	2.10	0.89	3.12	0.15	46.5	4.4	12
I102389		1.03	0.013	0.92	1.45	7.6	<0.2	<10	50	1.88	4.03	1.33	0.46	73.5	5.0	8
I102390		1.07	0.010	1.01	1.83	7.0	<0.2	<10	60	2.19	3.93	1.52	0.53	72.3	5.0	11
I102391		2.11	0.023	1.36	1.18	38.3	<0.2	10	20	1.33	8.01	0.43	0.76	68.8	8.3	6
I102392		2.10	0.164	3.72	0.84	74.0	0.2	<10	40	1.22	56.2	0.29	1.51	63.7	11.8	5
I102393		1.10	0.122	4.09	1.81	52.5	<0.2	<10	60	1.43	6.26	0.53	26.5	53.6	34.0	8
I102394		0.81	0.007	0.44	1.37	5.5	<0.2	<10	50	1.20	8.37	0.44	0.85	53.6	7.3	15
I102395		3.83	<0.005	0.28	1.11	5.3	<0.2	<10	60	0.92	2.66	0.54	0.67	49.5	7.6	16
I102396		2.24	<0.005	0.16	0.86	4.1	<0.2	<10	80	0.76	0.64	0.48	0.61	46.4	4.8	16
I102397		1.87	0.008	0.57	1.27	5.2	<0.2	<10	50	1.20	6.74	0.57	0.41	48.8	12.2	15
I102398		2.24	0.009	0.32	0.56	2.8	<0.2	20	30	1.06	7.93	0.26	0.38	60.9	7.1	9
I102399		1.73	<0.005	0.26	1.04	4.1	<0.2	10	50	1.29	9.76	0.35	0.36	63.3	7.2	13
I102400		<0.02	0.005	0.25	0.99	4.4	<0.2	10	40	1.23	9.96	0.35	0.35	62.5	7.2	13
I102401		2.22	0.009	0.24	1.09	4.2	<0.2	<10	80	0.80	1.69	0.63	0.30	44.0	6.1	17
I102402		2.15	0.005	0.22	1.06	3.0	<0.2	<10	90	0.79	1.80	0.57	0.25	48.0	5.3	17
I102403		0.33	0.005	0.09	0.99	1.2	<0.2	10	30	0.78	1.71	0.32	0.26	61.3	4.1	17
I102404		4.32	0.006	0.35	1.13	3.8	<0.2	<10	80	1.02	4.56	0.47	0.64	45.2	5.9	16
I102405		2.02	0.035	0.66	1.31	10.7	<0.2	<10	70	1.12	5.76	0.36	0.53	64.9	8.0	15
I102406		2.05	0.017	0.90	0.79	24.1	<0.2	10	40	0.99	1.05	0.14	0.33	68.2	13.1	6
I102407		1.84	0.060	0.61	1.27	10.8	<0.2	<10	90	1.32	2.56	0.34	0.68	59.6	10.8	13
I102408		1.83	0.098	1.68	0.76	42.5	<0.2	<10	60	0.82	6.49	0.15	0.41	51.9	13.7	8
I102409		1.67	0.017	0.37	0.70	20.6	<0.2	10	10	0.73	3.07	0.22	0.27	78.5	6.9	8
I102410		0.04	0.310	9.41	0.50	8.4	0.3	<10	180	0.18	1.77	2.40	<0.01	13.25	4.3	6
I102411		1.82	0.023	3.18	0.82	22.6	<0.2	<10	210	1.90	2.27	0.19	0.83	60.9	6.0	6
I102412		3.47	0.283	1.66	1.14	29.1	0.3	<10	280	1.74	2.25	0.23	0.56	61.1	8.8	8
I102413		2.12	<0.005	0.32	0.89	2.8	<0.2	<10	90	0.61	0.90	0.37	0.28	43.6	4.9	16
I102414		2.29	<0.005	0.32	0.85	4.4	<0.2	<10	80	0.45	0.38	0.44	0.53	42.2	4.4	17
I102415		2.39	<0.005	0.19	0.98	4.3	<0.2	<10	90	0.65	1.99	0.48	0.34	41.2	4.7	16
I102416		0.95	0.178	0.35	2.12	12.8	<0.2	<10	90	2.25	7.10	7.26	1.88	43.6	10.7	10
I102417		1.90	<0.005	0.21	0.95	4.4	<0.2	<10	80	0.65	1.07	0.45	0.23	43.7	4.4	17
I102418		2.30	<0.005	0.24	0.91	4.2	<0.2	<10	100	0.48	0.44	0.43	0.47	46.7	4.4	17

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137378

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I102387		4.23	7.6	1.98	4.33	0.09	0.22	<0.01	0.016	0.37	21.6	17.1	0.43	358	1.87	0.08
I102388		3.45	9.6	1.91	5.97	0.08	0.15	0.01	0.021	0.25	24.5	12.7	0.57	2690	1.01	0.04
I102389		7.02	52.1	2.07	4.45	0.09	0.12	<0.01	0.114	0.28	40.1	9.4	0.34	2220	1.49	0.01
I102390		7.39	55.4	2.29	5.53	0.10	0.11	0.01	0.152	0.33	39.2	11.0	0.38	2550	1.51	0.02
I102391		7.13	162.5	3.68	4.96	0.11	0.13	0.01	0.055	0.25	37.5	9.7	0.21	1720	8.72	0.02
I102392		14.15	147.5	5.06	6.81	0.12	0.10	0.03	0.203	0.28	35.6	8.4	0.12	7550	27.4	0.02
I102393		33.7	188.0	5.67	13.40	0.12	0.10	0.31	0.555	0.27	26.2	20.4	0.33	13900	28.1	0.03
I102394		4.90	50.7	2.85	6.95	0.10	0.21	0.01	0.139	0.24	27.3	21.6	0.68	963	1.65	0.04
I102395		4.57	32.6	2.63	5.93	0.11	0.21	<0.01	0.083	0.28	24.8	21.2	0.60	725	3.08	0.05
I102396		4.64	12.6	2.12	4.80	0.11	0.21	<0.01	0.024	0.35	24.5	15.6	0.44	639	2.81	0.09
I102397		4.51	30.6	3.06	6.68	0.11	0.14	<0.01	0.051	0.26	25.0	20.9	0.71	1020	3.63	0.04
I102398		2.69	27.8	3.62	3.13	0.10	0.11	<0.01	0.022	0.23	32.2	5.4	0.16	517	2.25	0.01
I102399		3.05	32.9	3.44	5.31	0.10	0.10	<0.01	0.035	0.25	34.0	12.8	0.44	687	1.59	0.02
I102400		2.94	31.2	3.36	5.18	0.10	0.09	<0.01	0.034	0.21	33.6	12.8	0.45	678	1.53	0.02
I102401		4.82	24.3	2.48	5.84	0.13	0.17	<0.01	0.053	0.32	22.6	21.4	0.67	626	4.45	0.06
I102402		5.36	20.7	2.49	5.47	0.12	0.16	<0.01	0.023	0.42	24.9	19.3	0.57	638	5.03	0.09
I102403		4.19	28.5	3.66	5.72	0.11	0.07	<0.01	0.021	0.25	36.0	21.3	0.53	651	0.73	0.02
I102404		5.77	23.9	2.82	6.11	0.13	0.16	<0.01	0.038	0.34	23.7	20.8	0.63	1280	2.37	0.05
I102405		8.37	19.6	3.52	7.86	0.12	0.15	<0.01	0.046	0.36	35.3	19.3	0.49	1450	3.58	0.03
I102406		11.55	223	3.63	3.75	0.10	0.05	0.02	0.123	0.39	36.0	3.3	0.05	2130	9.13	0.01
I102407		10.20	302	3.62	5.59	0.11	0.13	<0.01	0.044	0.34	31.6	15.8	0.30	2520	5.38	0.02
I102408		9.73	573	3.36	3.74	0.09	0.06	0.03	0.121	0.32	27.2	6.0	0.11	2680	9.56	0.01
I102409		6.97	17.7	2.06	3.16	0.09	0.05	0.01	0.071	0.34	43.5	4.9	0.04	1760	6.51	0.01
I102410		0.92	6270	1.42	1.79	<0.05	0.04	0.83	0.020	0.27	6.6	1.8	0.10	414	147.5	0.03
I102411		19.15	44.8	4.89	5.01	0.12	0.05	0.03	0.057	0.33	34.5	20.2	0.07	11550	11.35	0.01
I102412		19.85	21.8	4.78	7.61	0.06	0.07	0.02	0.105	0.41	31.9	28.2	0.14	16000	15.55	0.01
I102413		7.84	13.0	2.24	4.77	0.07	0.14	<0.01	0.018	0.45	22.4	16.4	0.52	610	7.50	0.06
I102414		4.62	21.7	2.23	4.51	0.05	0.18	<0.01	0.011	0.36	22.2	17.1	0.53	551	3.80	0.06
I102415		4.89	9.8	2.40	4.94	0.06	0.17	<0.01	0.022	0.40	21.5	16.3	0.55	664	5.74	0.08
I102416		22.2	4.7	3.34	6.84	0.05	0.12	0.02	0.080	0.32	25.5	9.3	0.43	3520	1.36	0.02
I102417		5.65	18.4	2.35	5.04	0.05	0.18	<0.01	0.025	0.35	21.8	16.5	0.57	601	5.53	0.06
I102418		6.90	22.0	2.35	4.95	0.06	0.18	<0.01	0.015	0.45	24.4	18.2	0.54	503	8.94	0.10

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137378

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I102387		1.72	3.5	800	23.8	41.2	<0.001	<0.01	0.93	2.1	0.3	1.2	23.6	<0.01	0.01	31.5
I102388		0.45	3.0	760	46.2	25.9	<0.001	<0.01	1.24	2.7	0.3	1.2	52.4	<0.01	0.01	32.6
I102389		0.22	3.2	830	41.8	33.7	<0.001	<0.01	6.12	2.9	0.3	0.7	70.4	<0.01	0.04	36.5
I102390		0.19	3.5	850	42.3	37.7	<0.001	<0.01	5.44	3.6	0.4	0.9	79.9	<0.01	0.03	36.3
I102391		0.17	3.3	810	29.4	35.9	<0.001	<0.01	12.15	1.7	0.5	0.8	24.9	<0.01	0.34	35.6
I102392		0.17	4.3	710	53.9	37.9	<0.001	0.03	25.8	1.7	0.4	1.5	129.5	<0.01	0.58	32.8
I102393		0.14	9.9	780	120.5	38.6	<0.001	0.01	15.35	2.8	0.4	1.4	203	<0.01	0.22	28.6
I102394		0.40	4.4	820	35.4	29.3	<0.001	<0.01	1.52	4.0	0.4	1.3	35.6	<0.01	0.02	34.7
I102395		0.93	7.9	830	43.3	31.6	<0.001	<0.01	1.16	3.1	0.3	1.6	29.4	<0.01	0.03	33.0
I102396		1.84	5.2	810	26.4	37.5	<0.001	<0.01	0.82	2.2	0.3	1.3	26.8	<0.01	0.01	32.1
I102397		0.66	5.1	850	45.5	28.8	<0.001	<0.01	0.71	2.9	0.3	1.8	26.8	<0.01	0.29	31.1
I102398		0.23	2.9	880	64.7	26.6	<0.001	<0.01	0.65	0.8	0.3	1.3	10.4	<0.01	2.22	31.1
I102399		0.25	3.8	860	58.4	26.3	<0.001	<0.01	0.60	1.5	0.3	1.6	17.9	<0.01	1.20	33.2
I102400		0.23	3.6	890	56.3	22.5	<0.001	<0.01	0.56	1.5	0.3	1.6	16.7	<0.01	1.18	34.2
I102401		1.37	4.5	880	51.9	33.6	<0.001	<0.01	0.78	2.9	0.3	2.1	70.5	<0.01	0.08	30.0
I102402		1.53	4.3	860	45.7	44.2	<0.001	<0.01	0.86	3.0	0.3	1.3	42.0	<0.01	0.06	27.2
I102403		0.17	4.1	900	14.6	30.4	<0.001	<0.01	0.20	1.9	0.3	0.3	11.4	<0.01	0.03	24.9
I102404		1.01	4.3	880	63.3	38.1	<0.001	<0.01	1.06	3.3	0.3	1.3	49.9	<0.01	0.08	28.1
I102405		0.42	4.7	910	78.6	45.1	<0.001	0.01	0.78	4.4	0.4	1.4	32.8	<0.01	0.25	30.8
I102406		0.12	2.4	750	17.5	53.5	<0.001	<0.01	0.97	1.8	0.4	1.7	25.3	<0.01	0.02	28.8
I102407		0.46	5.0	1020	42.1	44.5	<0.001	<0.01	1.33	4.4	0.7	5.6	42.2	<0.01	0.13	35.3
I102408		0.25	2.9	670	19.7	41.6	<0.001	<0.01	1.24	2.2	0.6	2.0	29.0	<0.01	0.09	27.5
I102409		0.10	1.6	830	18.1	47.9	<0.001	<0.01	1.01	1.5	0.4	0.6	19.5	<0.01	0.11	29.2
I102410		0.10	4.4	390	16.2	7.1	0.034	1.46	12.30	0.8	0.5	0.3	364	<0.01	1.99	1.4
I102411		0.12	5.3	820	34.3	51.9	<0.001	<0.01	1.08	2.5	0.4	0.4	100.0	<0.01	0.04	28.2
I102412		0.09	3.8	620	51.7	58.7	0.001	<0.01	1.81	2.7	0.3	1.1	168.0	<0.01	0.06	31.4
I102413		1.88	4.0	850	75.4	61.7	<0.001	<0.01	0.75	2.3	0.4	1.4	19.3	0.01	0.02	31.2
I102414		1.77	3.7	900	45.9	41.6	<0.001	<0.01	0.37	1.8	0.4	1.3	21.4	0.01	<0.01	29.1
I102415		1.42	3.9	820	43.5	43.6	<0.001	<0.01	0.51	2.4	0.3	1.3	28.0	0.01	<0.01	29.6
I102416		0.66	2.7	>10000	22.6	46.6	<0.001	<0.01	4.68	3.3	0.3	6.6	204	<0.01	0.18	23.2
I102417		1.57	4.4	950	45.6	42.0	<0.001	<0.01	0.62	2.3	0.3	1.4	27.1	0.01	0.01	29.7
I102418		2.11	3.9	840	47.4	54.9	0.001	<0.01	0.47	1.9	0.3	1.4	27.1	0.01	<0.01	32.1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137378

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102387		0.141	0.25	14.70	54	0.71	11.20	54	3.7
I102388		0.076	0.17	9.39	48	0.83	12.75	63	2.6
I102389		0.015	0.35	9.68	30	0.19	16.25	55	2.5
I102390		0.015	0.38	9.28	36	0.17	16.50	60	2.6
I102391		0.011	0.42	23.5	20	0.93	13.05	85	3.2
I102392		0.006	0.40	29.4	21	6.49	11.75	149	2.7
I102393		0.007	0.45	29.1	36	6.92	11.75	322	2.5
I102394		0.053	0.26	9.94	57	0.64	15.15	201	3.8
I102395		0.109	0.23	12.05	57	0.92	13.15	174	3.5
I102396		0.153	0.24	13.70	56	1.41	11.60	105	3.5
I102397		0.091	0.27	9.49	54	0.64	13.95	174	2.2
I102398		0.008	0.28	7.49	21	1.08	11.10	76	2.0
I102399		0.016	0.27	7.02	35	1.45	14.50	117	1.9
I102400		0.016	0.23	7.14	35	1.23	14.50	117	1.7
I102401		0.150	0.23	9.30	57	0.96	12.50	197	2.3
I102402		0.170	0.30	9.97	58	0.95	12.65	99	2.5
I102403		0.008	0.27	8.15	54	0.09	15.60	98	1.4
I102404		0.138	0.26	9.54	59	1.12	13.20	137	2.4
I102405		0.063	0.36	12.80	58	1.20	15.65	142	2.5
I102406		<0.005	0.80	18.25	22	2.28	14.35	99	0.9
I102407		0.072	0.42	15.90	53	3.17	16.30	138	2.4
I102408		0.015	0.59	15.85	25	1.92	11.05	83	1.3
I102409		<0.005	0.64	11.15	27	1.14	20.2	52	1.0
I102410		<0.005	0.05	1.04	11	4.86	4.46	38	1.4
I102411		<0.005	1.16	14.80	32	2.75	14.05	128	1.2
I102412		0.009	1.20	18.10	42	5.34	11.25	154	1.5
I102413		0.174	0.38	13.00	60	2.64	12.50	115	2.6
I102414		0.174	0.24	11.40	59	2.96	11.85	115	3.5
I102415		0.163	0.27	12.25	57	2.86	11.80	90	3.4
I102416		0.014	0.63	116.5	33	8.90	14.20	66	2.6
I102417		0.162	0.26	12.15	59	2.42	12.35	87	3.1
I102418		0.176	0.33	14.75	60	3.47	12.95	84	3.4

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10137378

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

CERTIFICATE WH10127719

Project: SQI10-01

P.O. No.: SQI10-01_10

This report is for 46 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 17-SEP-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	DARCY BAKER	

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-MS41	51 anal. aqua regia ICPMS	

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: DARCY BAKER
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:
Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127719

Sample Description	Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I102075		1.59	0.005	0.61	1.28	5.0	<0.2	<10	40	1.01	13.35	0.79	0.40	52.7	6.4	9
I102076		0.58	0.005	0.19	1.16	6.3	<0.2	<10	40	0.99	1.90	0.40	0.21	58.2	4.1	6
I102077		1.74	<0.005	0.19	1.11	4.7	<0.2	<10	40	1.05	2.27	0.41	0.19	57.8	4.6	7
I102078		2.23	0.006	0.40	1.28	8.2	<0.2	<10	90	0.92	11.20	0.80	0.29	50.1	8.9	16
I102079		2.74	0.008	0.49	1.25	43.6	<0.2	<10	60	1.10	5.79	1.10	0.39	59.4	9.2	15
I102080C		<0.02	0.007	0.56	1.24	43.7	<0.2	<10	60	1.05	5.56	1.10	0.37	59.6	9.1	15
I102081		2.65	0.010	1.30	1.13	46.8	<0.2	10	50	1.15	17.80	1.31	0.24	60.3	9.1	12
I102082		3.53	<0.005	0.49	1.39	15.4	<0.2	<10	40	1.14	3.79	1.01	0.41	63.6	7.2	18
I102083		1.79	<0.005	0.64	1.29	5.0	<0.2	<10	30	1.42	10.65	0.72	0.38	68.6	8.8	9
I102084		1.84	<0.005	0.28	2.22	7.5	<0.2	<10	100	2.32	2.42	1.53	0.39	67.5	4.5	14
I102085		1.85	<0.005	0.39	1.32	6.5	<0.2	<10	70	1.28	2.67	0.76	0.34	58.6	5.4	14
I102086		2.03	<0.005	0.36	1.23	4.5	<0.2	<10	70	1.26	2.78	0.73	0.33	57.5	5.6	15
I102087		2.27	<0.005	0.30	0.93	4.8	<0.2	<10	90	0.60	2.64	0.65	0.40	55.8	5.3	18
I102088		1.48	<0.005	0.28	1.47	9.3	<0.2	<10	60	1.31	2.66	1.48	0.24	62.1	12.7	13
I102089		1.64	0.006	0.42	1.39	3.9	<0.2	<10	60	1.10	15.45	1.29	0.30	61.0	6.5	15
I102090		0.05	0.304	9.98	0.48	7.2	0.3	<10	190	0.18	1.80	2.34	0.14	12.90	4.1	6
I102091		2.32	<0.005	0.23	0.98	4.5	<0.2	<10	90	0.69	2.31	0.69	0.35	51.3	6.0	17
I102092		1.82	0.007	0.30	1.04	7.1	<0.2	<10	80	0.91	1.76	0.72	0.50	45.0	7.2	13
I102093		0.68	0.009	1.69	1.04	33.8	<0.2	<10	60	1.54	13.20	0.54	0.19	66.4	5.6	11
I102094		2.10	<0.005	0.19	1.43	3.9	<0.2	<10	70	1.63	1.77	1.38	0.68	50.6	6.8	14
I102095		1.25	<0.005	0.16	0.98	4.8	<0.2	<10	90	1.06	1.22	0.40	2.49	54.3	7.8	15
I102096		1.34	0.008	0.56	1.15	9.0	<0.2	<10	60	0.79	1.48	0.36	0.31	57.2	5.0	12
I102097		1.61	0.021	1.93	0.83	31.9	<0.2	<10	150	2.74	8.72	0.07	9.53	39.5	47.2	7
I102098		1.34	0.019	1.70	1.05	83.4	<0.2	<10	490	5.39	22.3	0.09	21.7	81.3	95.0	5
I102099		2.15	0.028	0.43	1.04	30.3	<0.2	<10	70	1.59	5.38	0.28	0.53	43.9	4.9	12
I102100		1.03	0.006	0.50	1.15	31.9	<0.2	<10	80	1.72	5.77	0.33	0.66	47.0	5.4	13
I102101		2.83	0.006	0.68	1.38	22.8	<0.2	<10	70	1.81	18.90	0.28	1.04	56.4	11.9	25
I102102		2.79	0.006	0.51	1.33	5.5	<0.2	<10	30	1.50	2.96	0.29	0.49	56.0	9.7	22
I102103		0.93	0.134	2.13	0.96	24.6	<0.2	<10	80	1.94	19.90	0.26	0.25	46.4	21.4	16
I102104		4.14	<0.005	0.77	1.20	3.2	<0.2	<10	30	1.05	13.15	0.67	0.36	59.5	5.5	25
I102105		3.39	0.205	0.71	1.21	4.3	<0.2	<10	40	1.47	28.1	0.31	0.26	58.6	6.4	24
I102106		3.55	0.058	1.36	1.37	7.6	<0.2	<10	50	1.11	9.34	0.41	0.49	51.6	9.0	22
I102107		2.80	0.005	0.25	1.58	3.3	<0.2	<10	20	1.55	5.41	0.36	0.50	63.4	5.8	30
I102108		1.62	0.010	0.28	1.73	34.3	<0.2	<10	30	2.68	5.67	0.58	0.57	33.5	13.0	18
I102109		0.62	0.009	0.30	1.69	49.9	<0.2	<10	60	2.32	7.85	0.46	0.69	35.5	12.6	13
I102110		0.85	0.008	0.35	1.68	57.7	<0.2	<10	50	2.24	8.15	0.46	0.77	33.4	15.0	15
I102111		3.28	<0.005	0.36	1.30	17.2	<0.2	<10	90	0.87	6.30	0.55	0.35	48.0	6.8	19
I102112		4.37	<0.005	0.19	0.89	6.8	<0.2	<10	100	0.56	4.80	0.48	0.40	47.4	5.0	20
I102113		4.01	<0.005	0.18	0.88	4.9	<0.2	<10	90	0.65	4.31	0.44	0.34	47.1	4.5	18
I102114		1.82	0.013	2.17	2.16	30.9	<0.2	<10	100	2.11	50.9	0.62	3.03	44.8	13.7	15

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127719

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I102075		4.20	3.8	3.17	6.13	0.05	0.45	0.04	0.075	0.22	28.1	14.3	0.38	716	6.11	0.01
I102076		6.34	1.2	4.77	6.23	0.06	0.40	0.03	0.079	0.23	31.1	11.5	0.15	1020	6.84	<0.01
I102077		6.34	1.6	2.91	5.20	0.05	0.28	0.02	0.084	0.24	30.2	10.5	0.13	729	6.16	<0.01
I102078		7.12	31.7	2.98	6.96	0.12	0.21	<0.01	0.073	0.36	25.3	31.7	0.86	602	5.43	0.04
I102079		5.47	13.9	3.39	7.26	0.08	0.20	<0.01	0.060	0.29	29.9	27.4	0.76	707	65.4	0.03
I102080C		5.39	14.6	3.35	7.19	0.09	0.20	0.01	0.059	0.28	30.0	26.3	0.75	689	62.6	0.02
I102081		6.10	23.4	3.44	5.46	0.07	0.16	<0.01	0.057	0.27	30.7	17.0	0.50	882	20.5	0.02
I102082		5.45	56.0	2.99	8.01	0.10	0.16	<0.01	0.090	0.19	31.2	30.5	0.83	859	4.96	0.03
I102083		7.43	33.4	2.74	5.23	0.05	0.11	0.37	0.071	0.20	35.5	12.7	0.27	560	5.23	<0.01
I102084		11.20	12.2	2.90	6.75	0.06	0.19	0.02	0.095	0.30	33.5	20.7	0.51	872	2.18	0.03
I102085		7.18	25.8	2.76	6.09	0.05	0.22	<0.01	0.093	0.32	29.0	20.6	0.54	602	2.77	0.02
I102086		7.22	19.4	2.65	5.47	0.06	0.20	0.01	0.084	0.33	28.2	19.7	0.52	591	2.83	0.02
I102087		7.21	24.3	2.60	5.40	0.09	0.28	<0.01	0.050	0.39	27.3	23.0	0.63	459	3.08	0.06
I102088		25.6	10.5	3.01	6.83	0.06	0.30	<0.01	0.047	0.32	31.5	27.2	0.68	481	4.25	0.03
I102089		23.4	42.1	2.59	6.87	0.06	0.36	<0.01	0.093	0.31	30.1	26.1	0.73	502	3.63	0.02
I102090		0.94	5930	1.42	1.65	<0.05	0.04	0.81	0.021	0.26	6.1	2.0	0.10	405	140.5	0.02
I102091		7.82	20.8	2.57	5.53	0.10	0.28	<0.01	0.036	0.38	24.8	21.0	0.62	422	3.09	0.06
I102092		5.60	28.8	2.37	5.21	0.06	0.29	<0.01	0.030	0.30	21.1	22.0	0.57	375	3.39	0.04
I102093		9.05	91.9	3.08	5.10	0.06	0.21	<0.01	0.094	0.23	30.6	12.9	0.37	184	8.83	0.01
I102094		7.89	30.0	2.77	6.22	0.06	0.30	0.01	0.069	0.30	24.4	26.5	0.72	664	3.22	0.04
I102095		7.07	395	2.52	5.13	0.10	0.22	<0.01	0.063	0.40	25.1	31.0	0.60	731	6.45	0.05
I102096		7.90	112.5	2.04	5.12	0.05	0.21	0.01	0.127	0.35	27.8	19.9	0.32	286	3.62	0.01
I102097		14.70	586	5.68	6.30	0.07	0.17	0.02	0.114	0.24	18.8	9.4	0.13	18800	15.00	<0.01
I102098		47.2	876	7.73	10.35	0.13	0.21	0.03	0.088	0.40	32.7	60.8	0.12	43000	21.9	0.01
I102099		8.99	124.0	3.00	6.58	0.05	0.21	<0.01	0.048	0.34	22.6	21.3	0.31	688	3.91	0.02
I102100		10.40	132.5	3.25	6.60	0.05	0.20	0.01	0.054	0.38	24.2	23.2	0.32	953	4.24	0.02
I102101		8.38	201	3.43	9.16	0.05	0.40	<0.01	0.056	0.28	27.4	26.1	0.52	2440	4.90	0.02
I102102		5.14	31.4	2.65	8.47	<0.05	0.30	0.01	0.053	0.18	28.9	24.1	0.59	1520	1.49	0.02
I102103		22.5	159.5	4.87	7.27	0.05	0.29	0.01	0.087	0.24	20.7	8.3	0.17	1500	4.27	<0.01
I102104		1.51	23.4	2.56	9.04	<0.05	0.54	<0.01	0.050	0.16	31.5	24.2	0.65	1220	3.34	0.01
I102105		4.80	8.8	2.68	9.32	<0.05	0.44	<0.01	0.041	0.16	18.7	25.4	0.59	1440	1.87	<0.01
I102106		7.43	109.5	2.83	9.42	0.05	0.40	0.01	0.081	0.22	31.9	20.5	0.48	1550	1.08	<0.01
I102107		1.51	6.0	2.58	10.10	<0.05	0.51	<0.01	0.050	0.14	39.8	32.6	0.87	1080	0.50	0.01
I102108		4.18	123.0	4.01	9.01	0.09	0.19	0.01	0.073	0.17	18.3	21.5	0.81	703	0.68	0.04
I102109		6.45	149.5	3.93	8.06	0.09	0.19	0.01	0.100	0.38	18.6	21.0	0.72	618	1.47	0.02
I102110		6.22	154.5	4.30	8.62	0.10	0.19	<0.01	0.104	0.34	16.2	23.5	0.83	570	1.52	0.05
I102111		11.30	32.4	3.20	7.44	0.15	0.22	0.01	0.121	0.50	23.6	29.3	0.88	525	3.59	0.09
I102112		8.63	14.6	2.64	5.35	0.14	0.26	<0.01	0.116	0.45	23.2	22.3	0.62	477	3.99	0.11
I102113		5.05	9.7	2.61	5.72	0.13	0.23	<0.01	0.074	0.44	22.6	26.1	0.65	642	2.98	0.09
I102114		16.60	127.0	4.37	10.90	0.12	0.17	0.02	0.142	0.45	20.7	24.5	0.86	2330	1.94	0.05

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127719

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I102075		<0.05	3.3	830	43.1	26.9	<0.001	1.48	0.34	4.2	0.9	3.0	40.2	<0.01	0.42	20.2
I102076		0.07	3.1	770	9.8	28.5	<0.001	0.41	0.71	3.1	0.6	6.7	33.9	0.01	0.03	19.3
I102077		<0.05	2.8	890	12.9	31.8	<0.001	0.36	0.57	3.1	0.5	1.4	32.8	<0.01	0.06	20.2
I102078		1.39	5.2	890	35.1	44.9	<0.001	1.27	0.79	4.6	0.9	3.9	63.8	0.01	0.62	30.3
I102079		0.83	4.9	850	36.5	37.5	<0.001	1.38	0.63	4.4	0.8	2.9	36.2	0.01	0.49	32.5
I102080C		0.73	4.9	860	36.1	36.3	<0.001	1.42	0.62	4.3	0.8	2.7	35.7	0.01	0.53	31.2
I102081		0.20	4.1	810	44.0	31.9	<0.001	0.87	0.51	2.7	0.8	1.5	56.8	0.01	0.24	30.6
I102082		0.73	6.1	890	47.5	19.9	<0.001	0.33	0.77	5.1	0.6	3.1	52.5	0.01	0.34	29.9
I102083		0.06	4.0	880	29.3	25.8	<0.001	0.31	0.55	3.3	0.8	1.4	48.4	<0.01	0.49	26.5
I102084		0.18	4.5	890	33.5	34.6	<0.001	0.05	0.79	4.8	0.5	1.8	583	0.01	0.03	31.7
I102085		0.65	4.3	890	33.2	38.4	<0.001	0.21	1.08	3.9	0.5	1.7	49.2	0.01	0.06	31.2
I102086		0.61	4.1	880	30.6	38.2	<0.001	0.19	0.91	3.6	0.4	1.6	46.4	0.01	0.07	29.5
I102087		1.90	4.8	900	43.4	45.7	<0.001	0.10	0.77	3.8	0.5	1.8	43.5	0.01	0.06	30.4
I102088		0.37	5.5	870	34.1	45.5	<0.001	2.09	0.41	4.8	1.0	1.8	84.9	0.01	0.32	31.1
I102089		0.52	4.8	890	39.0	43.5	<0.001	0.57	0.42	4.5	0.6	1.9	66.3	0.01	0.67	30.8
I102090		<0.05	4.4	380	17.4	6.8	0.033	1.35	14.90	0.9	0.4	0.3	344	<0.01	2.01	0.9
I102091		1.67	4.8	870	36.5	36.3	<0.001	0.16	0.77	3.2	0.4	1.8	59.2	0.01	0.11	29.3
I102092		1.29	4.8	920	29.4	32.7	<0.001	0.38	0.88	3.1	0.5	1.5	50.3	0.01	0.07	30.3
I102093		0.29	3.5	940	154.5	29.7	<0.001	0.14	0.82	4.5	0.6	1.0	119.0	<0.01	0.08	29.9
I102094		0.54	5.5	880	30.2	36.1	<0.001	<0.01	0.64	4.9	0.4	1.4	169.5	0.01	0.02	28.2
I102095		1.44	5.4	900	47.0	44.5	<0.001	<0.01	1.13	2.6	0.5	1.9	19.8	0.01	0.01	29.4
I102096		0.53	3.2	750	33.0	48.4	<0.001	0.13	5.18	4.7	0.4	1.6	30.7	<0.01	0.02	28.9
I102097		0.14	2.9	770	86.1	34.9	<0.001	0.05	32.1	3.2	0.4	0.8	330	<0.01	0.05	29.3
I102098		0.24	6.9	800	46.8	59.4	<0.001	0.05	78.0	3.1	1.1	0.9	820	0.01	0.33	32.7
I102099		0.50	2.9	700	56.4	44.8	<0.001	0.24	3.93	3.2	0.7	1.9	49.3	<0.01	0.24	29.6
I102100		0.45	3.1	700	53.6	49.6	<0.001	0.29	5.71	3.3	0.8	2.3	62.3	<0.01	0.21	30.1
I102101		0.07	5.5	700	52.7	44.8	<0.001	0.35	3.25	2.8	0.9	0.9	56.6	<0.01	0.48	18.8
I102102		<0.05	5.7	660	54.1	23.3	<0.001	0.01	0.67	2.4	0.3	1.1	19.0	<0.01	0.55	21.5
I102103		0.05	4.0	700	156.0	36.4	<0.001	0.12	2.92	2.2	0.8	1.2	46.3	<0.01	2.08	20.1
I102104		<0.05	5.5	660	61.9	19.6	<0.001	0.18	0.47	2.8	0.5	0.9	23.9	<0.01	6.26	23.4
I102105		0.05	5.1	670	97.9	19.4	<0.001	<0.01	0.68	2.7	0.3	1.0	26.4	<0.01	14.95	21.6
I102106		<0.05	4.5	650	148.5	29.1	<0.001	<0.01	0.93	2.8	0.2	0.8	29.1	<0.01	3.30	21.0
I102107		<0.05	5.8	740	41.0	17.5	<0.001	<0.01	0.35	2.8	0.3	0.6	24.8	<0.01	1.17	22.0
I102108		0.16	5.4	850	39.7	25.0	<0.001	0.03	0.66	3.0	0.3	1.9	35.3	<0.01	0.32	26.2
I102109		0.30	4.1	780	60.9	55.1	<0.001	<0.01	1.03	3.8	0.4	3.0	29.0	<0.01	0.20	26.5
I102110		0.28	5.1	840	39.6	46.1	<0.001	0.02	0.94	4.2	0.5	3.0	26.3	0.01	0.43	28.3
I102111		1.21	5.5	900	37.8	66.2	<0.001	0.05	0.51	5.4	0.4	3.2	66.0	0.01	0.09	32.7
I102112		1.60	4.6	920	41.3	49.4	0.001	0.03	0.57	2.9	0.3	2.5	54.9	0.01	0.02	31.9
I102113		1.92	4.3	880	37.0	51.8	<0.001	0.03	0.59	2.9	0.3	3.4	27.3	0.01	0.02	33.3
I102114		0.23	5.9	890	256	63.4	<0.001	0.03	0.75	5.1	0.3	5.3	98.2	0.01	0.40	30.5

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127719

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102075		<0.005	0.30	7.97	30	0.85	13.60	89	18.0
I102076		0.008	0.34	8.70	37	14.90	15.75	111	15.0
I102077		<0.005	0.36	7.21	27	2.85	15.60	86	12.0
I102078		0.152	0.29	12.00	55	1.71	13.90	88	4.3
I102079		0.094	0.28	12.85	51	1.56	14.85	113	4.4
I102080C		0.090	0.27	13.00	51	1.35	14.85	112	4.3
I102081		0.023	0.29	12.50	34	4.53	15.05	95	3.5
I102082		0.105	0.14	12.30	57	0.86	14.95	130	3.2
I102083		0.009	0.21	12.60	34	2.58	16.95	105	3.5
I102084		0.048	0.24	13.75	53	0.97	19.45	97	5.1
I102085		0.099	0.24	15.15	54	1.52	15.45	94	4.9
I102086		0.096	0.24	13.75	53	1.37	14.65	92	4.4
I102087		0.178	0.26	11.40	61	0.80	16.30	97	5.1
I102088		0.056	0.33	13.20	46	0.35	18.10	81	7.7
I102089		0.080	0.26	10.00	55	0.41	17.05	93	8.7
I102090		<0.005	0.03	1.22	11	4.42	4.15	37	1.4
I102091		0.179	0.22	10.70	60	0.82	15.00	86	5.4
I102092		0.153	0.16	10.35	49	0.97	14.20	70	5.5
I102093		0.048	0.20	18.20	40	0.97	13.05	123	5.4
I102094		0.101	0.22	6.87	51	1.00	16.10	101	6.4
I102095		0.186	0.27	11.90	58	0.74	19.80	158	3.7
I102096		0.093	0.30	28.3	46	0.98	15.65	102	4.6
I102097		0.023	0.83	25.5	33	4.37	8.44	140	4.5
I102098		0.025	1.81	29.5	37	6.50	14.75	207	4.9
I102099		0.066	0.44	15.00	41	0.58	9.96	73	5.1
I102100		0.069	0.51	15.25	44	0.63	10.35	75	5.0
I102101		0.020	0.38	6.85	33	0.67	11.10	180	14.5
I102102		0.007	0.18	5.58	30	1.45	8.95	170	11.3
I102103		0.006	0.31	12.25	28	2.01	6.54	114	10.5
I102104		0.006	0.17	6.29	31	1.55	9.62	153	20.2
I102105		0.008	0.16	6.90	33	1.22	8.05	149	17.0
I102106		0.007	0.23	6.73	31	1.03	7.52	144	15.2
I102107		0.005	0.16	4.97	37	0.66	10.20	165	19.2
I102108		0.038	0.34	4.13	49	0.68	10.95	127	5.9
I102109		0.074	0.79	6.90	48	0.94	11.45	121	4.5
I102110		0.083	0.63	6.81	54	0.92	12.00	113	4.5
I102111		0.180	0.60	10.20	66	1.77	13.85	87	4.3
I102112		0.178	0.37	11.15	61	1.54	13.80	87	4.6
I102113		0.171	0.38	14.35	60	1.15	14.55	85	3.7
I102114		0.083	0.89	7.67	59	0.59	13.00	284	4.0

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127719

Sample Description	Method	WEI-21	Au-AA23	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
I102115		1.53	0.107	4.47	1.70	63.4	<0.2	<10	80	2.20	38.7	0.80	1.27	36.2	19.8	8
I102116		3.80	0.005	0.71	1.36	6.6	<0.2	<10	80	1.13	62.8	0.62	1.65	39.5	7.1	18
I102117		4.40	0.009	0.42	1.40	7.6	<0.2	<10	80	1.08	32.7	0.65	0.63	37.3	11.2	19
I102118		5.15	0.005	0.33	1.18	6.6	<0.2	<10	80	0.68	16.60	0.53	0.37	44.8	10.3	20
I102119		1.90	0.007	0.25	1.41	9.5	<0.2	<10	90	0.86	6.67	0.53	0.37	34.2	11.6	19
I102120C		<0.02	0.007	0.26	1.43	9.2	<0.2	<10	90	0.82	6.77	0.53	0.34	33.0	11.4	19

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127719

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
I102115		20.0	57.1	5.17	10.00	0.10	0.15	0.01	0.175	0.43	19.7	10.0	0.40	3170	1.72	0.05
I102116		8.01	81.3	3.37	7.81	0.12	0.15	0.01	1.020	0.45	19.3	28.0	0.89	808	2.10	0.08
I102117		6.95	96.9	3.23	7.75	0.14	0.16	0.02	0.171	0.41	18.5	25.4	0.85	716	2.91	0.08
I102118		6.96	69.4	3.65	7.42	0.14	0.21	<0.01	0.085	0.48	22.0	28.9	0.89	547	3.77	0.10
I102119		10.65	100.5	3.85	7.90	0.13	0.16	0.01	0.104	0.53	16.4	30.6	0.92	583	2.88	0.09
I102120C		10.05	99.8	3.82	7.95	0.13	0.15	<0.01	0.094	0.53	15.7	28.9	0.91	572	2.98	0.09

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127719

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
I102115		0.11	4.5	1520	103.0	57.3	<0.001	0.03	3.52	2.7	0.3	2.8	75.6	<0.01	0.31	24.1
I102116		0.71	5.3	860	48.7	56.8	<0.001	0.06	1.17	5.2	0.4	4.1	48.2	0.01	4.02	30.0
I102117		0.83	7.3	870	39.2	51.8	<0.001	0.04	0.63	4.5	0.4	4.1	42.1	0.01	4.62	27.3
I102118		1.19	6.3	880	43.6	58.5	<0.001	0.03	0.61	5.4	0.4	3.3	40.7	0.01	0.24	30.3
I102119		0.94	5.5	890	41.3	69.0	<0.001	0.06	0.51	5.9	0.4	2.7	37.1	0.01	0.23	29.2
I102120C		0.80	5.4	890	41.1	68.0	<0.001	0.05	0.48	5.7	0.3	2.7	36.4	0.01	0.20	29.3

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127719

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5
I102115		0.014	1.03	12.25	39	1.62	11.30	127	3.9
I102116		0.134	0.56	8.44	61	0.92	12.90	518	2.7
I102117		0.143	0.47	8.44	59	0.95	12.25	125	3.1
I102118		0.172	0.53	10.95	67	1.05	13.45	107	3.7
I102119		0.162	0.69	9.91	67	1.89	12.70	98	2.6
I102120C		0.158	0.70	9.85	67	1.77	12.30	97	2.5

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-OCT-2010
Account: EIASQI

Project: SQI10-01

CERTIFICATE OF ANALYSIS WH10127719

Method	CERTIFICATE COMMENTS
ME-MS41	Gold determinations by this method are semi-quantitative due to the small sample weight used (0.5g).

Appendix E: Rock Sample Descriptions

MINERALS AND ALTERATION TYPES

AC	Actinolite	FP	feldspar	PF	plagioclase
AL	alunite	GA	garnet	PH	phlogopite
AM	amphibole	GE	goethite	PL	pyrolusite
AS	arsenopyrite	GL	galena	PO	pyrrhotite
AU	augite	GR	graphite	PY	pyrite
AZ	azurite	HB	hornblende	QZ	quartz veining
BA	barite	HE	haematite	RE	realgar
BI	biotite	HS	specularite	RN	rhodonite
BO	bornite	HZ	hydrozincite	SB	stibnite
BT	pyrobitumen	IL	illite	SD	siderite
CA	calcite	JA	jarosite	SI	silicification
CB	Fe-carbonate	KF	potassium feldspar	SK	skarn
CC	chalcocite	MC	malachite	SM	smithsonite
CD	chalcedony	MG	magnetite	SP	sphalerite
CL	chlorite	MI	mica	SR	scorodite
CP	chalcopyrite	MN	Mn-oxides	SS	sulphosalts
CU	native copper	MO	molybdenite	ST	smectite
CV	covellite	MR	mariposite/fuchsite	TP	topaz
CY	clay	MS	sericite	TT	tetrahedrite
DC	dickite	MT	marcasite	VG	gold
DS	diaspore	MU	muscovite	ZE	Zeolite
DU	dumortierite	NA	natroalunite	ZN	zunyite
EN	enargite	NE	neotocite		
EP	epidote	PA	pyrargyrite		

ALTERATION INTENSITY

w	weak	s	strong
m	moderate	i	intense

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

G092252 Prospector Mountain *2*

Grid North: UTM 6926800 N | Grid East: UTM 355159 E | Elevation: | Sample Width: | Type: Float | Strike Length Exp: | True Width: | Host : Monzonite | Alteration: sMS | Metallics: 3-5HS, 1-2PY | Secondaries: wGE, mHE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.01	0.21	4.6	0.75
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
19.5	14.25	1.62	77 %

Sampled By: TB 30-Jun-10

QTZ stringers with HS in altered gang. PY in gang. New tag book - no 251. Only 1 rock of this material seen here.

G092253 Prospector Mountain *2*

Grid North: UTM 6927118 N | Grid East: UTM 355099 E | Elevation: | Sample Width: | Type: Float | Strike Length Exp: | True Width: | Host : Monzonite | Alteration: sMS | Metallics: 3-5PY, 5-7TO | Secondaries: mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.015	0.19	22.1	2.75
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
7.2	2.08	0.68	24 %

Sampled By: TB 30-Jun-10

Sample altered monzenite with deseminated PY+TO, a few rocks of this material here.

G092254 Prospector Mountain *2*

Grid North: UTM 6927180 N | Grid East: UTM 355071 E | Elevation: | Sample Width: | Type: Float | Strike Length Exp: | True Width: | Host : Monzonite | Alteration: wMS | Metallics: 5-7PY | Secondaries: sGE, sJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.029	0.26	303	6.38
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
7.3	4.71	1.27	59 %

Sampled By: TB 30-Jun-10

Sample good PY in altered gang. A few big blocks of this in talus.

G092255 Prospector Mountain *2*

Grid North: UTM 6927428 N | Grid East: UTM 355087 E | Elevation: | Sample Width: | Type: Float | Strike Length Exp: | True Width: | Host : Monzonite | Alteration: sMS | Metallics: 3-5HS, 7-10TO | Secondaries: sHE, sJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.015	2.07	16.8	11.55
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
46.5	21.6	1.43	16 %

Sampled By: TB 30-Jun-10

Sample big block in talus of HS-QTZ stringers and deseminated TO.

G092256 Prospector Mountain *2*

Grid North: UTM 6928041 N | Grid East: UTM 355139 E | Elevation: | Sample Width: | Type: | Strike Length Exp: | True Width: | Host : Monzonite | Alteration: sMS | Metallics: 3-5HS, 3-5TO | Secondaries: mHE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.143	0.09	16.5	2.84
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
8.5	0.84	1.49	17 %

Sampled By: TB 30-Jun-10

Sample QTZ with HS+TO

G092257 Prospector Mountain *2*

Grid North: UTM 6928000 N | Grid East: UTM 354941 E | Elevation: | Sample Width: | Type: Float | Strike Length Exp: | True Width: | Host : Monzonite | Alteration: sMS | Metallics: 7-10HS, 7-10TO | Secondaries: mHE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.133	3.11	7.5	16
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
26.7	11.8	1.36	48 %

Sampled By: TB 30-Jun-10

Sample talus boulder with HS+TO

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

G092258 Prospector Mountain *2*
Sampled By: TB 30-Jun-10

Grid North: UTM 6927849 N | Grid East: UTM 355003 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: wMS | Metallics: 5-7HS, 2-3PY, 3-5TO | Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.01	0.51	26.7	13.15
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
6.8	31.1	0.43	32 %

Glassy QTZ with HS, TO, + PY

G092259 Prospector Mountain *2*
Sampled By: TB 30-Jun-10

Grid North: UTM 6927695 N | Grid East: UTM 354972 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: mMS | Metallics: 5-7HS | Secondaries: mHE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.043	0.38	118.5	6.84
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
6.1	23	0.75	19 %

Glassy QTZ with HS

G092260 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926674 N | Grid East: UTM 354428 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: wMS | Metallics: 2-3PY, 5-7TO | Secondaries: sGE, sJA, sSR

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
<0.005	0.11	6.4	0.42
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
5.8	17.6	0.33	62 %

Sample hart showing. Glassy, sugary QTZ with deseminated PY+TO. "Showing" consists of 1 rounded float stone on hillside.

G092261 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926671 N | Grid East: UTM 354424 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: mCy, mMS | Metallics: 1TO | Secondaries: sHE, sJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.038	1.04	6.9	2.96
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
67.1	24.3	0.68	80 %

5m above 260, sample sugary, vuggy QTZ talus with TO and good oxides. Sample taken from small talus.

G092262 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926683 N | Grid East: UTM 354419 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: mCY, mMS | Metallics: 1-2TO | Secondaries: sGE, sJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.009	1.88	7.5	5.07
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
18.1	23.3	0.42	68 %

1m south of 261 sample bigger talus rock of sugary QTZ with somem TO and good oxides.

G092263 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926679 N | Grid East: UTM 354401 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: | Metallics: 1-2PY | Secondaries: mGE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.01	0.17	7.9	6.91
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
24.9	4.21	0.42	28 %

20m above 262, sample gang rock with PY and oxides

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

G092264 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926706 N | Grid East: UTM 354391 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: | Metallics: trHS, 1PY, 1-2TO | Secondaries: mGE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.008	0.19	2.6	2.29
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
14.5	24.7	1.05	28 %

Glassy, vuggy QTZ with some TO, PY, HS

G092265 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926686 N | Grid East: UTM 354375 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: | Metallics: 1-2HS, 2-3PY, 1-2TO | Secondaries: mGE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.022	0.11	9.4	845
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
69.3	5.52	1.55	28 %

Sample glassy, sugary QTZ with PY, TO, HS in talus

G092266 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926887 N | Grid East: UTM 354344 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: | Metallics: 1-2TO? | Secondaries: sJA, sSR?

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.015	2.88	92.3	6.76
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
12.3	6.87	1.09	41 %

Sample glassy, frothy QTZ with TO. Talus heaving out of ground. Grab over 1m.

G092267 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926891 N | Grid East: UTM 354342 E | Elevation: | Sample Width:
Type: | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: QZ | Metallics: 3-5TO | Secondaries: sJA, sSR?

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.014	1.6	13.3	1.85
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
9.8	2.58	0.8	18 %

Glassy, frothy QTZ with TO sampled from talus, 3m across slope from 266.

G092268 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926904 N | Grid East: UTM 354343 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: | Metallics: | Secondaries: sJA, sSR?

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.017	7.35	59.9	15.95
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
14.2	9.52	2.04	33 %

Sample frothy, vuggy QTZ talus with dark silica bands. Grab over 1m in small heaved talus.

G092269 Prospector Mountain *2*
Sampled By: TB 01-Jul-10

Grid North: UTM 6926909 N | Grid East: UTM 354349 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: sMS | Metallics: | Secondaries: sJA, sSR?

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.016	1.99	88	5.28
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
25	4.89	3.2	27 %

Sample MS altered gang rock with some frothy glassy QTZ taken from small heaved pebbles.

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

G092270	Grid North:		Grid East:		Type:	Alteration:	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6926986	N	UTM 354371	E	Strike Length Exp:	Metallics: 2-3HS, 1-2TO	0.014	2.04	7.9	2.58
2	Elevation:		Sample Width:		True Width:	Secondaries: sJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		32.8	17.7	0.52	44 %
Sampled By: TB 01-Jul-10	Sample glassy, vuggy QTZ with HS+TO. Good oxides. Taken 10m downslope from high soil hole (cc45113)									
G092271	Grid North:		Grid East:		Type: Float	Alteration: sMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6926980	N	UTM 354379	E	Strike Length Exp:	Metallics: trPY, 3-5TO	0.038	11.45	67.3	37.8
2	Elevation:		Sample Width:		True Width:	Secondaries: sJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		32.2	20.1	18.55	90 %
Sampled By: TB 01-Jul-10	Sample frothy, glassy QTZ on cat road with tourmaline.									
I031011	Grid North:		Grid East:		Type:	Alteration: HS (15-20%)	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927419	N	UTM 355416	E	Strike Length Exp:	Metallics:	0.024	0.08	6.4	0.53
2	Elevation:		Sample Width:		True Width:	Secondaries: he (s), ja (m)	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host :		1.2	3.43	1.9	22 %
Sampled By: TB 27-Jun-10	HS bands in glassy, vuggy qtz talus. Sample taken over 1 m area. Hs + qtz over 2m area									
I031012	Grid North:		Grid East:		Type: Grab	Alteration:	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927425	N	UTM 355417	E	Strike Length Exp: 1 m	Metallics: hs (20-25%), py (tr)	0.012	0.13	17.7	0.84
2	Elevation:		Sample Width: 20 cm		True Width: 20 cm	Secondaries:	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
	Vein 188°/88°				Host :		1.5	6.35	0.73	11 %
Sampled By: TB 27-Jun-10	5m above 011, sample 5-10cm wide quartz-hs vein in outcrop with hs stringers 20 cm away from main vein. Grab over 20 cm									
I031013	Grid North:		Grid East:		Type: Float	Alteration:	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927426	N	UTM 355422	E	Strike Length Exp:	Metallics: hs (10%), sp (tr), to (20-25	0.017	0.22	20.3	0.85
2	Elevation:		Sample Width:		True Width:	Secondaries:	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host :		1.5	1.13	0.5	3 %
Sampled By: TB 27-Jun-10	up slope and over to east, sample more HS, py, qtz in talus. Thi is a not along strike of 012. Lots of this material here is talus									
I031014	Grid North:		Grid East:		Type:	Alteration:	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927447	N	UTM 355463	E	Strike Length Exp:	Metallics:	0.006	0.11	10.9	0.28
2	Elevation:		Sample Width:		True Width:	Secondaries:	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host :		3.4	0.72	0.59	10 %
Sampled By: TB 27-Jun-10	more talus upslope from 013 with tourmaline and with traces of sphalerite									

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I031015 Prospector Mountain *2*	Grid North:		Grid East:		Type: Float	Alteration: hs (10-15%), py (tr), to (5%	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
	UTM 6927525	N	UTM 355464	E	Strike Length Exp:	Metallics:	0.006	0.49	2.5	1.14
	Elevation:		Sample Width:		True Width:	Secondaries: he (w), ja (w)	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host :		2.5	0.88	0.33	11 %
Sampled By: TB 27-Jun-10	more vein material in talus									
I031016 Prospector Mountain *2*	Grid North:		Grid East:		Type:	Alteration: hs (15-20%)	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
	UTM 6927514	N	UTM 355499	E	Strike Length Exp:	Metallics:	<0.005	0.05	6.6	0.45
	Elevation:		Sample Width:		True Width:	Secondaries:	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host :		1.3	1.6	1.35	13 %
Sampled By: TB 27-Jun-10	glassy quartz with specular hematite.									
I031017 Prospector Mountain *2*	Grid North:		Grid East:		Type: Float	Alteration: sCY	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
	UTM 6927463	N	UTM 355560	E	Strike Length Exp:	Metallics: 15-20HS	<0.005	0.25	2	7.34
	Elevation:		Sample Width:		True Width:	Secondaries: mHE, sJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		3.8	0.68	0.23	9 %
Sampled By: TB 27-Jun-10	Sample HS stringers along fractures in with altered monzenite.									
I031018 Prospector Mountain *2*	Grid North:		Grid East:		Type:	Alteration:	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
	UTM 6927405	N	UTM 355601	E	Strike Length Exp:	Metallics: 20-25HS, 5TO	<0.005	0.03	20.4	1.27
	Elevation:		Sample Width:		True Width:	Secondaries: sGE, sHE, sJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		2.5	3.19	0.69	4 %
Sampled By: TB 22-Jun-10	more sidehill talus									
I031019 Prospector Mountain *2*	Grid North:		Grid East:		Type: Float	Alteration:	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
	UTM 6927432	N	UTM 355449	E	Strike Length Exp:	Metallics: 20-25HS, >1PY	0.025	0.19	2.6	0.69
	Elevation:		Sample Width:		True Width:	Secondaries: sHE, sJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		2.2	0.91	0.74	12 %
Sampled By: TB 27-Jun-10	more HS with some PY in glassy, craggy quartz									
I031020 Prospector Mountain *2*	Grid North:		Grid East:		Type: Float	Alteration: CY	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
	UTM 6927390	N	UTM 355402	E	Strike Length Exp:	Metallics: 5-7HS	0.008	0.11	5.8	0.49
	Elevation:		Sample Width:		True Width:	Secondaries: wHE, sJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzenite		1.7	1.19	1.26	35 %
Sampled By: TB 27-Jun-10	sampled altered monzenite with HS stringers									

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I031021 Prospector Mountain *2*
Sampled By: TB 27-Jun-10

Grid North: UTM 6927345 N | Grid East: UTM 355391 E | Elevation: | Sample Width:
Type: | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: | Metallics: 15-20HS, trTO | Secondaries: wHE

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.012	0.08	4.7	0.32
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
1.5	4.28	0.7	22 %

more HS in vuggy QTZ with minor TO

I031022 Prospector Mountain *2*
Sampled By: TB 28-Jun-10

Grid North: UTM 6926800 N | Grid East: UTM 355277 E | Elevation: | Sample Width:
Type: | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: | Metallics: 5-7HS, >1PY, 1TO | Secondaries: wJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.006	0.13	4.5	0.63
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
4.2	2.06	0.52	51 %

Just up slope s.w. of camp. Sample 1-2cm wide, glassy QTZ stringers with HS+TO - minor PY in monzenite stuff

I031023 Prospector Mountain *2*
Sampled By: TB 28-Jun-10

Grid North: UTM 6926775 N | Grid East: UTM 355238 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: | Metallics: 10-15HS, 1TO | Secondaries: wHE, wJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.005	0.44	4.5	0.25
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
3.9	0.52	0.25	17 %

fist size rock sampled of glassy, vuggy QTZ with HS+TO in tables

I031024 Prospector Mountain *2*
Sampled By: TB 28-Jun-10

Grid North: UTM 6926417 N | Grid East: UTM 355321 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: | Metallics: 7-10HS | Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.006	0.07	6.8	0.51
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
11.3	0.45	0.47	24 %

Sample 1-2cm wide QTZ stringers with HS. Very little of this material here.

I031025 Prospector Mountain *2*
Sampled By: TB 28-Jun-10

Grid North: UTM 6927544 N | Grid East: UTM 355217 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: mCY, sMS | Metallics: 25-30HS, 1-2TO | Secondaries: mHE, wJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.009	0.4	10.4	1.64
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
10.3	1.26	1.09	29 %

sample big breccia boulder of HS+TO with MS, CY altered intrusive clasts. Taken in main bonanza zone near B.W's highgrade sample.

I031026 Prospector Mountain *2*
Sampled By: TB 28-Jun-10

Grid North: UTM 6927557 N | Grid East: UTM 355235 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: wEP | Metallics: HS, trTO | Secondaries: wHE

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
5.86 g/t	36.3	74.8	291
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
151.5	1.92	55.2	44 %

Sample QTZ with HS+TO in tables in Bonanza Zone.

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I031027	Grid North:		Grid East:		Type: Float	Alteration: sMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927569	N	UTM 355228	E	Strike Length Exp:	Metallics: 50-60HS, 3-5TO	0.013	0.7	7.8	3.97
2	Elevation:		Sample Width:		True Width:	Secondaries: wHE, wJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		10	0.98	3.06	44 %
Sampled By: TB 28-Jun-10	Sample taken from big semi-massive HS boulder in Bonanza Zone.									
I031028	Grid North:		Grid East:		Type: Float	Alteration: sMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927563	N	UTM 355216	E	Strike Length Exp:	Metallics: 25-30HS, 2-3TO	0.011	1.02	8.2	3.19
2	Elevation:		Sample Width:		True Width:	Secondaries: mHE, wJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		5.3	1.12	1.5	24 %
Sampled By: TB 28-Jun-10	sample more breccia style material. HS as matrix and HS, CY altered monzenite as clasts. Big boulder in talus in Bonanza zone.									
I031029	Grid North:		Grid East:		Type: Float	Alteration: sMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6928548	N	UTM 355201	E	Strike Length Exp:	Metallics: 7-10HS	112.5 g/t	543 g/t	278	3710
2	Elevation:		Sample Width:		True Width:	Secondaries: mGE, sHE, mJA, wMC	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		1.625 %	20.5	22.3	200 %
Sampled By: TB 28-Jun-10	sample same location of B.W's highgrade AU sample. Well oxidized, narrow HS stringers.									
I031030	Grid North:		Grid East:		Type: Float	Alteration: mCY, sMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927543	N	UTM 355180	E	Strike Length Exp:	Metallics: 3-5HS	0.297	1.43	17.7	22.3
2	Elevation:		Sample Width:		True Width:	Secondaries: mHE, mJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host :		531	1.5	9.28	64 %
Sampled By: TB 28-Jun-10	In Bonanza Zone, sample small HS-QTZ stringers in more oxidized monzenite. Grab over 2m radius.									
I031031	Grid North:		Grid East:		Type: Float	Alteration: sCL, sEP	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927601	N	UTM 355190	E	Strike Length Exp:	Metallics: 1-2TO	0.036	0.28	8.9	2.38
2	Elevation:		Sample Width:		True Width:	Secondaries: mHE, sJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		7.3	0.3	1.06	114 %
Sampled By: TB 28-Jun-10	sample tourmaline in EP, CY altered monzenite. Grab over 50cm in small talus. Taken just above Darcy's soil #I030859.									
I031032	Grid North:		Grid East:		Type: Float	Alteration: sMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927983	N	UTM 355149	E	Strike Length Exp:	Metallics: 30-40HS	0.035	1.14	38.9	8.47
2	Elevation:		Sample Width:		True Width:	Secondaries: wHE, wJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		46.5	2.22	2.39	24 %
Sampled By: TB 28-Jun-10	Sample semi-massive HS by old pit at highgrade location.									

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I031033 Prospector Mountain *2*
Sampled By: TB 28-Jun-10

Grid North: UTM 6927983 N | Grid East: UTM 355149 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: sMS | Metallics: | Secondaries: sMC

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
6.41 g/t	509 g/t	515	1320
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
3.16 %	1.82	6910	441 %

Right beside 032 sample QTZ with good MC on side of pit

I031034 Prospector Mountain *2*
Sampled By: TB 29-Jun-10

Grid North: UTM 6927491 N | Grid East: UTM 355101 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: wMS | Metallics: 10-15HS, 2-3TO | Secondaries: wHE

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.027	2.23	6.4	10.5
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
435	1.28	23.4	18 %

Sample more HS+TO in glassy, vuggy QTZ.

I031035 Prospector Mountain *2*
Sampled By: TB 29-Jun-10

Grid North: UTM 6927418 N | Grid East: UTM 355289 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: sMS | Metallics: 5-7HS, 1-2PY | Secondaries: sHE, sJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.344	2.62	80.5	11.9
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
12.6	1.47	2.67	7 %

Sample glassy, vuggy QTZ float with good HS+PY. Strong oxidization. Vein looks to be about 10cm wide.

I031036 Prospector Mountain *2*
Sampled By: TB 29-Jun-10

Grid North: UTM 6927418 N | Grid East: UTM 335286 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: mCy, sMS | Metallics: 10-15HS, trPY, trTO | Secondaries: mGE, sHE, sJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.275	2.86	82.4	11.95
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
110.5	1.01	28.8	15 %

2m over from 035 sample 2 large boulders of more brecciated looking material well oxidized. This comes from a much larger vein.

I031037 Prospector Mountain *2*
Sampled By: TB 29-Jun-10

Grid North: UTM 6927440 N | Grid East: UTM 355275 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: sMS | Metallics: 3-5HS | Secondaries: mHE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.075	0.5	7.8	1.57
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
3.9	0.84	3.01	71 %

Sample narrow (1cm) wide HS stringers with good oxidization in talus.

I031038 Prospector Mountain *2*
Sampled By: TB 29-Jun-10

Grid North: UTM 6927495 N | Grid East: UTM 355223 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: sMS | Metallics: 40-50HS, 1-2TO | Secondaries: mHE, wJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.025	0.62	6.4	3.04
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
11.3	0.48	1.39	32 %

Sample taken from 6 large breccia style boulders. HS matrix, with clasts of HS altered monzenite. Must be subcrop here.

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I031039	Grid North:		Grid East:		Type: Float	Alteration: sMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927515	N	UTM 355202	E	Strike Length Exp:	Metallics: 7-10HS	50.1 g/t	470 g/t	632	5000
2	Elevation:		Sample Width:		True Width:	Secondaries: sGE, sHE, sMC	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		2.2 %	56	86.8	340 %
Sampled By: TB 29-Jun-10	Sample well oxidized material with HS in vuggy QTZ. Just 1 rock with MC seen here.									
I031040	Grid North:		Grid East:		Type: Float	Alteration: sMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927515	N	UTM 355202	E	Strike Length Exp:	Metallics: 3-5HS	19.7 g/t	29.6	469	882
2	Elevation:		Sample Width:		True Width:	Secondaries: sGE, sHE, sJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		1495	5.23	5.82	189 %
Sampled By: TB 29-Jun-10	More well oxidized material with HS, 5m up slope from 039.									
I031041	Grid North:		Grid East:		Type: Float	Alteration:	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927478	N	UTM 355084	E	Strike Length Exp:	Metallics: 20-30HS, 2-3TO	0.071	1.23	4.6	15.75
2	Elevation:		Sample Width:		True Width:	Secondaries: wHE, wJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		23.3	0.89	0.88	20 %
Sampled By: TB 29-Jun-10	Sample glassy QTZ with HS+TO in talus									
I031042	Grid North:		Grid East:		Type: Float	Alteration: wMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927475	N	UTM 355059	E	Strike Length Exp:	Metallics: 3-5HS, 2-3PY, 1TO	0.081	2.94	165	45.5
2	Elevation:		Sample Width:		True Width:	Secondaries: mHE, mJA	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		112.5	121.5	2.48	30 %
Sampled By: TB 29-Jun-10	Frothy looking QTZ with PY, HS and TO in talus									
I031043	Grid North:		Grid East:		Type: Float	Alteration: wMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927418	N	UTM 354876	E	Strike Length Exp:	Metallics: 10-15HS	0.049	0.61	29.5	10.15
2	Elevation:		Sample Width:		True Width:	Secondaries: wHE	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		11.9	12.25	0.97	14 %
Sampled By: TB 29-Jun-10	Sample sugary QTZ talus with HS									
I031044	Grid North:		Grid East:		Type: Float	Alteration: mMS	**Au (ppb)**	**Ag (ppm)**	**As (ppm)**	**Bi (ppm)**
Prospector Mountain	UTM 6927515	N	UTM 354931	E	Strike Length Exp:	Metallics: 2-3PY	0.02	0.51	37.3	3.62
2	Elevation:		Sample Width:		True Width:	Secondaries: mHE	**Cu (ppm)**	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
					Host : Monzonite		31	5.24	2.13	35 %
Sampled By: TB 29-Jun-10	Glassy QTZ with HS+PY heaving out of ground.									

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I031045 Prospector Mountain *2*
Sampled By: TB 29-Jun-10

Grid North: UTM 6927789 N | Grid East: UTM 355020 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: mMS | Metallics: 15-20HS | Secondaries: mHE

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.013	0.62	9.6	5.65
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
19.6	1.19	1.95	20 %

HS in glassy vuggy QTZ talus

I031046 Prospector Mountain *2*
Sampled By: TB 29-Jun-10

Grid North: UTM 6928188 N | Grid East: UTM 354951 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: mMS | Metallics: 5-7HS | Secondaries: mHE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.316	3.95	76.5	208
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
740	16.8	5.18	84 %

Sample narrow HS stringers with good oxide at B.W's high AU sample site. Talus.

I031047 Prospector Mountain *2*
Sampled By: TB 29-Jun-10

Grid North: UTM 6928241 N | Grid East: UTM 354986 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: sMS | Metallics: 5-7HS | Secondaries: sGE, sHE, sJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
14.15 g/t	56.6	342	576
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
2110	38.7	29.3	100 %

Strongly oxidized HS in vein material. Talus sample.

I031048 Prospector Mountain *2*
Sampled By: TB 29-Jun-10

Grid North: UTM 6927914 N | Grid East: UTM 355167 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: sMS | Metallics: 40-50HS | Secondaries: wHE

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.054	0.78	23.2	8.37
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
31.6	0.99	3.04	41 %

Another big block of vein material with good HS plus TO

I031049 Prospector Mountain *2*
Sampled By: TB 30-Jun-10

Grid North: UTM 6926835 N | Grid East: UTM 355202 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: sMS | Metallics: 2-3HS, 1-2PY | Secondaries: mHE, sJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.011	0.32	7.7	2.36
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
15.9	5.48	0.93	44 %

Sample altered gang rock with HS stringers on fractures. Only 1 rock of this material here.

I031050 Prospector Mountain *2*
Sampled By: TB 30-Jun-10

Grid North: UTM 6926841 N | Grid East: UTM 355196 E | Elevation: | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Monzonite
Alteration: sMS | Metallics: 5-7HS, 1-2PY | Secondaries: mHE, mJA

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.008	0.18	4.5	1.17
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
5.6	4.36	0.36	16 %

5m above 049, sample glassy, vuggy QTZ stringers with HS. PY in gang rock. Sample taken from 2 rocks.

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I034454 Prospector Mountain *2*

Grid North: UTM N | Grid East: UTM E | Elevation: | Sample Width: | Type: | Strike Length Exp: | True Width: | Host : | Alteration: | Metallics: | Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.337	61.9	184	4.32
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
227	27.4	316	393 %

Sampled By: DB 26-Jun-10

Quartz Druze-lined cavities, silica box work proximal host is s SI, outside m MS (silky), epithermal (low sulphidation?) textures. At location of H884006 from 2009.

I034455 Prospector Mountain *2*

Grid North: UTM 6927458 N | Grid East: UTM 355399 E | Elevation: 1832 m | Sample Width: | Type: Float | Strike Length Exp: | True Width: | Host : | Alteration: to | Metallics: hs 15% | Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.084	0.74	3.1	2.66
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
3.2	0.62	1.87	6 %

Sampled By: DB 26-Jun-10

50x20x20 angular boulder, Hs-To vein, replacement style but w/ planar, sharp margins, tourmaline, as radiating clusters in vein and lesser in host monzonite. Within HS vein boulder train

---

I034456 Prospector Mountain *2*

Grid North: UTM 6927502 N | Grid East: UTM 355431 E | Elevation: 1869 m | Sample Width: | Type: Float | Strike Length Exp: 10 m | True Width: | Host : | Alteration: ms, si | Metallics: py - 4% | Secondaries: JA (w), Li (m)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
<0.005	0.34	68.5	1.15
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
2.6	1.65	1.22	42 %

Sampled By: DB 27-Jun-10

Conspicuously orange (gossanous) boulders in float train contain HS veins. The boulders contain 1 - 5 % disseminated pyrite, mg (0.5 - 2 mm)

I034457 Prospector Mountain *2*

Grid North: UTM 6927636 N | Grid East: UTM 354994 E | Elevation: 1857 m | Sample Width: | Type: Float | Strike Length Exp: | True Width: | Host : | Alteration: si (m) | Metallics: hs (4), PY (2) | Secondaries: JA (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.013	0.84	52.9	6.38
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
27.8	6.4	1.79	39 %

Sampled By: DB 27-Jun-10

frost boil on plateau with abundant veins of HS and with pyrite disseminated in wallrock. Sampled several similar cobbles in 1x1 m frost boil

---

I034458 Prospector Mountain *2*

Grid North: UTM 6927606 N | Grid East: UTM 355220 E | Elevation: 1858 m | Sample Width: | Type: Grab | Strike Length Exp: | True Width: | Host : | Alteration: cy (w), ms (w), to (s) | Metallics: hs (2) | Secondaries: ja (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
<0.005	0.31	3.5	0.59
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
3.8	0.75	0.37	21 %

Sampled By: BD 27-Jun-10

"Low grade". Lots of this material in float rain. Distinct spotted texture owing to ~15% To in 2 - 10 mm rosettes and replacing hornblende. Minor clear, euhedral Qz and dissemiated HS patches associated with tourmaline.

I034459 Prospector Mountain *2*

Grid North: UTM 6927645 N | Grid East: UTM 355230 E | Elevation: 1872 m | Sample Width: | Type: Float+Select | Strike Length Exp: | True Width: | Host : | Alteration: cy (w), ms (m) | Metallics: hs (10), py (tr) | Secondaries: ja (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.023	0.41	14	2.47
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
12.4	2.16	0.82	95 %

Sampled By: DB 27-Jun-10

40x15x10 angular boulder cut by 1.5 cm wide cockade texture clear quartz w/ intergrown specular hematite. Rock is non-magnetic. Monzogranite is Mto altered (patches) and mMS or Cy.

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I034460 Prospector Mountain *2*

Grid North: UTM 6927655 N Elevation: 1880 m
Grid East: UTM 355232 E Sample Width:
Type: Float Strike Length Exp: True Width: Host :
Alteration: ms (m), si (w), to (m) Metallics: HS (6%), py (1%) Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.005	0.37	4.4	1.62
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
31.7	0.91	1.96	31 %

Sampled By: DB 27-Jun-10

pale green (sericite?) altered plagioclase, several similar float (3 - 12 cm) so I sampled a composite. Cut by veins of euhedral clear qz-hs +/- c.g. pyrite with silica in wallrock, tourmaline as radiating aggregates.

I034461 Prospector Mountain *2*

Grid North: UTM 6927588 N Elevation: 1849 m
Grid East: UTM 355181 E Sample Width:
Type: Float Strike Length Exp: True Width: Host :
Alteration: Ms (m), si (w), to (m) Metallics: hs (6%), py (1%) Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.036	0.48	37.8	3.03
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
8.3	1.94	0.82	88 %

Sampled By: DB 27-Jun-10

Pale green altered (sericite) plagioclase, several similar float pieces so I sampled a composite. Cut by veins of euhedral qz-hs w/ c.g. pyrite. Weak silica is wallrock, tourmaline as radiating agregates.

I034462 Prospector Mountain *2*

Grid North: UTM 6927600 N Elevation: 1871 m
Grid East: UTM 355299 E Sample Width:
Type: Float+Select Strike Length Exp: True Width: Host :
Alteration: ms (s), to (s) Metallics: hs (6%) Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.015	0.14	4.6	0.92
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
2.2	1.34	0.24	10 %

Sampled By: DB 28-Jun-10

Hs-To vein stockwork in monzonite. Strong muscovite in hostrock. Soft, yellow-green coarse-grained sericite. Can discern individual grains, gives off characteristic sheen.

I034463 Prospector Mountain *2*

Grid North: UTM 6927513 N Elevation: 1832 m
Grid East: UTM 355309 E Sample Width:
Type: Float Strike Length Exp: True Width: Host :
Alteration: si (w), to (m) Metallics: hs (8%), py (2%) Secondaries: ja (w), li (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.013	0.15	7.5	0.93
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
1.7	0.28	0.47	7 %

Sampled By: DB 28-Jun-10

15x15x10 angular boulder in monzogranite talus. C.g. chunky, euhedral pyrite in rough layer parallel to 15 mm wide quartz vein with specular hematite. Non-magnetic

I034464 Prospector Mountain *2*

Grid North: UTM 6927499 N Elevation: 1829 m
Grid East: UTM 355295 E Sample Width:
Type: Float+Select Strike Length Exp: True Width: Host :
Alteration: ms (w), si (w), to (w) Metallics: hs (5%), py (3%) Secondaries: ja (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
2.75 g/t	47	189	841
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
38.6	1.23	2.3	23 %

Sampled By: DB 28-Jun-10

green-yellow oxidized boulder w/ 1 cm wide layer of c.g. (1-3mm) euhedral pyrite among irregular stack of to-hs. Plagiocalse is soft- ms (or cy) altered. Cy could be just surface oxidation

I034465 Prospector Mountain *2*

Grid North: UTM 6927505 N Elevation: 1847 m
Grid East: UTM 355086 E Sample Width:
Type: Float Strike Length Exp: True Width: Host :
Alteration: si (s), to (s) Metallics: hs (7), py (tr) Secondaries: ja (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.014	0.41	7.4	3.71
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
22.6	1.47	1.17	14 %

Sampled By: DB 29-Jun-10

hard, siliceous 18x15 boulder in a float train of qz-hs-to vein float

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I034466 Prospector Mountain *2*

Grid North: UTM 6927547 N | Grid East: UTM 354916 E | Elevation: 1854 m | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host :
Alteration: ms (m), to (m) | Metallics: py (3%) | Secondaries: ge(m), ja (s)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.037	1.57	219	11.65
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
3.5	2.11	0.67	15 %

Sampled By: DB 01-Jul-10

20x15x15 angular float boulder, strongly gossanous, non-magnetic, no veining but rather abundant m.g. disseminated pyrite, mMs of FL and isoalted patches of dark TO.

I034467 Prospector Mountain *2*

Grid North: UTM 6927558 N | Grid East: UTM 354919 E | Elevation: 1858 m | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host :
Alteration: qz (m), si (m), to (m) | Metallics: hs (1%), py (5%) | Secondaries: ja (m)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.126	4.69	210	20.1
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
7.5	6.51	5.01	147 %

Sampled By: DB 01-Jul-10

8x10 angular float chalcedonic with large (6 mm) blebs of c.g. pyrite, some chips of cockscomb quartz-amethyst veins nearby

I034468 Prospector Mountain *2*

Grid North: UTM 6927561 N | Grid East: UTM 354921 E | Elevation: 1852 m | Sample Width:
Type: Float+Select | Strike Length Exp: | True Width: | Host :
Alteration: qz (s) | Metallics: py (tr), to (tr) | Secondaries: ja (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.142	0.98	216	9.63
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
32.7	8.89	11.35	74 %

Sampled By: DB 01-Jul-10

largest piece of cockscomb vein float that could be found (6x8 cm). Several, similar bits here with colloform, euhedral quartz

I034469 Prospector Mountain *2*

Grid North: UTM 6927659 N | Grid East: UTM 354823 E | Elevation: 1785 m | Sample Width:
Type: Float+Select | Strike Length Exp: | True Width: | Host :
Alteration: to (s) | Metallics: py (4%) | Secondaries: hb (w), ja (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.056	2.28	176.5	9.86
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
5.9	7.57	3.46	13 %

Sampled By: DB 01-Jul-10

6 cm qz-py-to vein cutting non-magnetic strongly To-altered monzogranite, coarse grained pyrite

I034470 Prospector Mountain *2*

Grid North: UTM 6928249 N | Grid East: UTM 354819 E | Elevation: 1721 m | Sample Width:
Type: Float+Select | Strike Length Exp: | True Width: | Host : ?
Alteration: ms (w), si (s) | Metallics: py (1%) | Secondaries: he (w), ja (s), li (s)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
1.52 g/t	153 g/t	576	7.18
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
1640	66.8	2980	528 %

Sampled By: DB 01-Jul-10

8 cm thick vein with several paralel siliceous layers (ie not one single quartz vein) comprising bladed tz w/ 10% c.g. euhedral pyrite (now 90% has gone to limonite) minor sericite, strongly oxidized - locally vuggy where pyrite has been completely oxidized away.

I034471 Prospector Mountain *2*

Grid North: UTM 6928184 N | Grid East: UTM 354959 E | Elevation: 1787 m | Sample Width:
Type: Float+Select | Strike Length Exp: | True Width: | Host : ?
Alteration: qz (vn), to (i) | Metallics: hs (tr) | Secondaries: li (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.305	1.42	31.9	1.2
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
12.3	3.59	9.72	11 %

Sampled By: DB 01-Jul-10

white, vuggy, sugary quartz vein materialize with 40% dark green (looks black in hand sample) tourmaline as rosettes and larger clusters. Drusy quartz growing within vugs looks like a high temperature assemblage

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I034472 Prospector Mountain *2*

Grid North: UTM 6928153 N | Grid East: UTM 354987 E | Elevation: 1804 m | Sample Width:
Type: Float+Select | Strike Length Exp: | True Width: | Host :
Alteration: ms (w), si (w) to (w) | Metallics: hs (2%), | Secondaries: ja (w), li (w)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.181	2.42	48.4	5.56
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
70.8	1.68	20.8	76 %

Sampled By: DB 01-Jul-10

muscovite - tourmaline alteration. Monzonite cut by servearl < 1 mm thick HS veinlets. Boulder ~15x10x8 cm; angular. Most surrounding float is unaltered monzogranite.

I034473 Prospector Mountain *2*

Grid North: UTM 6928089 N | Grid East: UTM 355006 E | Elevation: 1822 m | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : monzogranite?
Alteration: ms (m), to (m) | Metallics: hs (3%) | Secondaries: li (m)

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.449	0.29	29.6	52.6
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
12.1	0.91	3.68	21 %

Sampled By: DB 01-Jul-10

monzogranite (?) cut by tourmaline - specular hematite filled breccia and several thin veinlets in multiple orientations, host rock bleaches (muscovite + cy)?

I034474 Prospector Mountain *2*

Grid North: UTM 6928031 N | Grid East: UTM 355532 E | Elevation: 1933 m | Sample Width:
Type: Float | Strike Length Exp: | True Width: | Host : Andesite
Alteration: | Metallics: hs (3%) | Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.461	1.98	12.7	11.2
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
19.3	3.47	19.35	87 %

Sampled By: DB 02-Jul-10

6 cm thick vein - banded, colloform texture, layer with HS, open-space euhedral quartz, nice epithermal texture

I034475 Prospector Mountain *2*

Grid North: UTM 6927902 N | Grid East: UTM 355243 E | Elevation: 1899 m | Sample Width:
Type: Float+Select | Strike Length Exp: | True Width: | Host : monzogranite
Alteration: ms (m), to (s) | Metallics: hs (3%) | Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.02	0.66	26.8	2.71
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
11.3	1.02	2.65	21 %

Sampled By: DB 02-Jul-10

from soil hole for I033007,8. Numerous angular cobbles on monzogranite breccia with tourmaline cement and isolated blebs of HS. Frost boil - can't find any similar material in immediate surrounding float.

I101401 Prospector Mountain *2*

Grid North: UTM 6926811 N | Grid East: UTM 356096 E | Elevation: 1597 m | Sample Width: 60 cm
Type: Float | Strike Length Exp: | True Width: | Host : Quartz tourmaline spec altered monzonite
Alteration: 4SI | Metallics: 5SP | Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.023	0.07	2.2	1.21
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
5.4	5.42	0.35	3 %

Sampled By: RT 20-Sep-10

Originally Prospector Mtn group monzonite now altered to tourmaline (60%), spec (5%), quartz (35%)

I101402 Prospector Mountain *2*

Grid North: UTM 6926811 N | Grid East: UTM 356096 E | Elevation: 1597 m | Sample Width: 50 cm
Type: Float | Strike Length Exp: | True Width: | Host : Quartz tourmaline spec altered monzonite
Alteration: 4SI | Metallics: 5SP | Secondaries:

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.804	0.19	4.7	0.74
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
3.6	1.37	0.24	5 %

Sampled By: RT 20-Sep-10

Same as I101402

Rock Sample Descriptions Prospector Mountain

Operator: Silver Quest **Project:** SQI10-01 2010 **NTS:** 115I/05

I101403
Prospector Mountain
2
Sampled By: RT
20-Sep-10

Grid North: UTM 6926811 N
Grid East: UTM 356096 E
Elevation: 1597 m
Sample Width: 50 cm
Type:
Alteration: 4SI
Strike Length Exp:
Metallics: 5SP
True Width:
Secondaries:
Host : Tourmaline quartz spec altered monzonite

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.383	0.06	3.1	0.22
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
3.6	1.21	0.3	5 %

Originally Prospector Mtn group monzonite now altered to tourmaline (60%), quartz (35%), spec (5%)

I101404
Prospector Mountain
2
Sampled By: RT
20-Sep-10

Grid North: UTM 6926811 N
Grid East: UTM 356096 E
Elevation: 1597 m
Sample Width: 30 cm
Type:
Alteration: 4SI
Strike Length Exp:
Metallics: 5SP
True Width:
Secondaries:
Host : Tourmaline quartz spec altered monzonite

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.023	0.62	4.6	2.03
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
3.5	9.7	0.67	6 %

Same as 403 tourmaline 50, quartz 45, spec 5

I101451
Prospector Mountain
2
Sampled By: RT
17-Sep-10

Grid North: UTM 6926811 N
Grid East: UTM 356096 E
Elevation: 1597 m
Sample Width: 10 cm
Type: Float
Alteration:
Strike Length Exp:
Metallics:
True Width:
Secondaries:
Host : Quartz vein

Au (ppb)	Ag (ppm)	As (ppm)	Bi (ppm)
0.012	0.15	3.5	0.86
Cu (ppm)	**Mo (ppm)**	**Sb (ppm)**	**Zn (ppm)**
1.9	1.17	0.99	10 %

Lost the rest of I101401 tag book. Quartz vein with oxidized sulfides. XRF gun read 43 PPM Au.

Appendix F: Drill Logs

Drill Log Legend



Andesite



Casing



Quartz Monzonite



Quartz Vein



Vein

EQUITY

DRILL LOG

Project: Prospector Mountain	**Collar Elevation (m):** 1809.0
Hole PM10-01	**Azimuth (º):** 80.0
Location: 6928037 m North, 354988 m East	**Dip (º):** -45.0
Logged by: Ryan Toole	**Length (m):** 197.82
Drilled by: Apex	**Horizontal Projection:**
Assayed by: ALS	**Vertical Projection:**
Core Size: NQ	**Objective** Bonanza Zone; complete fence across broadest part of anomaly with PM10-02
Date Started: 2010/09/06 **Date Completed:** 2010/09/08	
Dip Tests By:	

Summary Log:

0-3.05 CASING

3.05-15.00 MONZONITE – Mottled pink, grey, and black, coarse grained monzonite. Trace magnetite and local faulting associated with weak to moderate limonitic alteration.

15.00-25.45 ANDESITE – Light grey, fine grained, porphyritic andesite. Weakly bleached, 3-4% disseminated pyrite, and highly fractured associated with weak limonitic alteration.

25.45-63.20 MONZONITE - Mottled pink, grey, and black, coarse grained monzonite. Trace magnetite and local faulting associated with weak to moderate limonitic alteration.

63.20-77.40 MONZONITE/ALTERATION ZONE – Continuation of previous unit with local intense limonite alteration associated with tourmaline mineralization and specular hematite stringer veins.

77.40-79.32 QUARTZ VEIN/MONZONITE – Reddish brown, limonitic, vuggy quartz vein with intermixed monzonite in upper 1m. Late stringer specular hematite veins have been overprinted by limonitic alteration. No visible sulfides.

79.32-147.79 MONZONITE - Pink, grey, and black, coarse grained monzonite. Specular hematite stringers occur upper 2.5m and make up approximately 4% of rock composition. Local rare tourmaline mineralization with associated disseminated magnetite bands. Rare xenoliths of andesite with difuse margins occur throughout interval.

147.79-152.90 ANDESITE - Light grey, fine grained, porphyritic andesite. Phenoclasts consist of plagioclase, feldspar, and hornblende. 2% fine magnetite disseminations associated with hornblende. 5% pyrite disseminations. Diffuse contacts.


152.90-197.82 MONZONITE - Continuation of 79.32-147.79m. Local limonitic alteration from 180.75-181.90m. Rare specular hematite stringers between 180.75-193.0m. EOH

Downhole surveys:

Depth	Dip	Azimuth
15.24	-47.70	82.20
85.34	-48.50	81.10

Project: ProspectorMtn **Hole Number:** PM10-01


From	To	Rocktype & Description
0.00	3.05	Casing
		CASING - Overburden
3.05	15.00	Quartz Monzonite
		QUARTZ MONZONITE - Mottled pink, grey, and black, coarse grained, quartz monzonite. Approximately 45% feldspar, 40% plagioclase that has been weakly altered to sericite, 5% hornblende, 5% quartz, 4% biotite, and trace to 1% magnetite. Upper 1.5m is blocky with weakly oxidizd fractures. Unit is massive and featureless. Fault gouge at < @ 11.35 Fault Gouge 50.00º 13.00cm >. Rare local oxidized fractures contain trace to locally 1% pyrite and trace bornite. Weak epidote alteration is associted with fractures. Sharp lower contact at 45 degrees TCA
		ALTERATION
		« 13.25- 13.55 Limonite 1.00*»
		« 13.25- 13.55 Epidote 1.00*»
		MINERALIZATION
		« 13.25- 13.55 Pyrite 2.00%»
		« 13.25- 13.55 Bornite 0.10%»
		FAULTS
		< @ 11.35 Fault Gouge 50.00º 13.00cm >
15.00	25.45	Andesite
		ANDESITE - Light grey, porphyritic, fine grained, andesite dyke. 10% phenocrysts of which 9% are plagioclase up to 1cm, locally altered to sericite, and 1% hornblende. Oxidized fractures occur from top to bottom of unit associated with 1-2% disseminated pyrite. Bleaching occurs from 20.20-24.00m. Sharp lower contact at 60 degrees TCA.
		ALTERATION
		« Limonite 1.00*» (weak oxidation)
		« 20.20- 24.00 Silicification 2.00*»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
12.00	13.00	1.00	I102001	0.01	0.38	13
13.00	15.00	2.00	I102002	0.01	0.16	16
15.00	17.00	2.00	I102003	0.01	0.57	12
17.00	19.00	2.00	I102004	0.01	0.24	2
19.00	20.75	1.75	I102005	0.01	1.24	5
20.75	21.15	0.40	I102006	0.01	4.24	33
21.15	23.15	2.00	I102007	0.01	1.01	15
23.15	25.45	2.30	I102008	0.01	0.44	7

Project: ProspectorMtn **Hole Number:** PM10-01

From	To	Rocktype & Description
		« 20.75- 21.14 Limonite 2.00*»
		MINERALIZATION
		« Pyrite 1.00%»
25.45	63.20	Quartz Monzonite
		QUARTZ MONZONITE - Mottled pink, grey, and black, coarse grained, quartz monzonite. Approximately 45% feldspar, 40% plagioclase that has been altered to sericite, 5% hornblende, 5% quartz, 4% biotite, and trace to 1% magnetite. Continuation of 3.05-15.00m. Interval is locally faulted, gouged, and blocky from top to bottom. Rare 2-3mm chaotic calcite veins. Local zones of hydrothermal alteration (bleaching) contain 2-3mm graphite seems with associated limonitic mineralization. No visible mineralized veins. Sharp lower contact with alteration zone at 45 degrees TCA.
		ALTERATION
		« 35.57- 37.86 Limonite 1.00*»
		« 47.00- 49.70 Sericite 1.00*»
		« 47.00- 49.70 Limonite 1.00*»
		MINERALIATION
		« 47.00- 49.70 Pyrite 1.00%»
		FAULTS
		< @ 35.57 Fault 43.00° 229.00cm >
		< @ 55.00 Fault Gouge 35.00° 20.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
25.45	26.45	1.00	I102009	0.01	3.70	95
26.45	27.45	1.00	I102011	0.01	0.12	11
27.45	29.45	2.00	I102012	0.01	0.24	11
29.45	31.45	2.00	I102013	0.01	0.18	8
31.45	33.45	2.00	I102014	0.01	0.14	12
33.45	34.57	1.12	I102015	0.01	0.19	19
34.57	35.57	1.00	I102016	0.01	0.29	13
35.57	37.86	2.29	I102017	0.01	0.59	26
37.86	39.86	2.00	I102018	0.01	0.26	29
39.86	41.70	1.84	I102019	0.01	0.20	14
41.70	43.70	2.00	I102021	0.01	0.08	11
43.70	45.70	2.00	I102022	0.01	0.11	13
45.70	46.80	1.10	I102023	0.01	0.16	12
46.80	48.80	2.00	I102024	0.01	0.35	32
48.80	49.70	0.90	I102025	0.01	0.54	249
49.70	51.70	2.00	I102026	0.01	0.17	19
51.70	53.60	1.90	I102027	0.01	0.20	16
53.60	55.60	2.00	I102028	0.01	0.23	18
57.60	59.60	2.00	I102031	0.01	0.16	14
59.60	61.60	2.00	I102032	0.01	0.11	13
61.60	63.20	1.60	I102033	0.01	0.14	11

Project: ProspectorMtn **Hole Number:** PM10-01

From	To	Rocktype & Description
63.20	77.40	Quartz Monzonite / Alteration Zone

QUARTZ MONZONITE/ ALTERATION ZONE - Continuation of previous unit however interval is intensly fractured, with the longest interval of core reaching 20cm in length. Locally intense limonite alteration, associated with accessory tourmaline, and specular hematite seems. Locally sericite (altered from plagioclase) increases up to 20% of composition, forming as euhedral crystals up to 3mm wide, giving the monzonite a green color. 10cm brecciated, vuggy, highly oxidized quartz vein < @ 72.85 ven 55.00º 100.00mm > occurs at 72.85m. One occurance of magnetite in a vuggy 3cm quartz vein at 73.05m. Locally interval is gouged. Sharp lower contact with quartz vein at 45 degrees TCA.

ALTERATION

« Limonite 1.00*»
« Sericite 1.00*»

« 66.80- 67.30 Limonite 4.00*»

« 68.70- 69.12 Limonite 3.00*»

« 72.55- 72.90 Limonite 3.00*»

« 75.90- 77.40 Sericite 3.00*»


MINERALIZATION

« 72.70- 74.10 Specularite 2.00%» Stringers

« 67.30- 74.10 Tourmaline 2.00%» Mostly prismatic crystals

FAULTS

< @ 67.95 Fault Gouge 50.00º 15.00cm >
< @ 68.65 Fault Gouge 50.00º 40.00cm >
< @ 77.00 Fault Gouge 45.00º 40.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
63.20	65.20	2.00	I102034	0.01	0.22	13
65.20	66.75	1.55	I102035	0.01	0.58	15
66.75	68.00	1.25	I102036	0.09	0.94	50
68.00	70.00	2.00	I102037	0.02	1.62	264
70.00	72.00	2.00	I102038	0.01	0.43	22
74.00	75.70	1.70	I102041	0.01	0.23	31
75.70	77.40	1.70	I102042	0.05	0.51	8

Project: ProspectorMtn **Hole Number:** PM10-01

From	To	Rocktype & Description
77.40	79.32	Quartz Vein

QUARTZ VEIN/QUARTZ MONZONITE - Reddish brown, limonitic, vuggy quartz vein with intervals of monzonite in upper 1m. Interval exhibits intense limonite alteration. Late stringer veins have been over printed by limonite alteration, however show the same characteristics as specular hematite veins observed throughout the property. Locally faulted. No visible sulfides and not magnetic. Sharp lower contact at 60 degrees TCA.

ALTERATION

« Limonite 4.00*»

« 77.40- 78.40 Sericite 3.00*» Within monzonite intervals.

MINERALIZATION

Specular Hematite stringers have been overprinted by limonite alteration; the stringers make up 3% of the interval composition.

FAULTS

< @ 77.89 Fault Gouge 50.00° 5.00cm >


From	To	Rocktype & Description
79.32	147.79	Quartz Monzonite

QUARTZ MONZONITE - Mottled pink, grey, and black, coarse grained, quartz monzonite. Approximately 45% feldspar, 40% plagioclase, 5% hornblende, 5% quartz, 4% biotite, and 1% magnetite. Upper 12m is blocky and locally gouged. Specular hematite stringers occur from top of interval to 81.88m and make up approximately 4% of interval. Local rare magnetite bands associated with tourmaline mineralization. Xenoliths of andesite up to 5cm wide occur increasingly down unit from 115m, up to 3% of total composition. Sharp, irregular, baked lower contact with andesite.

ALTERATION

« 79.32- 88.50 Sericite 1.00*»


« 96.70- 99.00 Sericite 2.00*»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
77.40	78.75	1.35	I102043	1.79	2.62	26
78.75	79.32	0.57	I102044	14.15	14.95	36
79.32	80.80	1.48	I102045	0.92	0.79	21
80.80	81.90	1.10	I102046	0.22	0.53	6
81.90	83.90	2.00	I102047	0.01	0.13	6
83.90	85.90	2.00	I102048	0.01	0.10	14
85.90	88.00	2.10	I102049	0.02	0.11	4
88.00	88.40	0.40	I102051	0.01	0.18	28
88.40	90.40	2.00	I102052	0.01	0.12	12
90.40	92.40	2.00	I102053	0.01	0.08	6
92.40	94.40	2.00	I102054	0.01	0.12	9
94.40	96.40	2.00	I102055	0.01	0.10	9
96.40	98.40	2.00	I102056	0.01	0.13	8
98.40	100.40	2.00	I102057	0.01	0.09	7
100.40	102.40	2.00	I102058	0.01	0.12	13
102.40	103.40	1.00	I102059	0.01	0.12	9

Project: ProspectorMtn **Hole Number:** PM10-01


From	To	Rocktype & Description
		MINERALIZATION
		« 79.32- 81.88 Specularite 2.00%»
		Disseminated magnetite bands intermixed with tourmaline prismatic crystals and associated with epidote alteration occur between 96.7m and 99.0m.
		FAULTS
		< @ 84.04 Fault Gouge 45.00° 6.00cm >
		< @ 85.54 Fault Gouge 62.00° 15.00cm >
		< @ 84.14 Fault Gouge 45.00° 26.00cm >
		< @ 108.58 Fault Gouge 50.00° 30.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

Project: ProspectorMtn **Hole Number:** PM10-01


From	To	Rocktype & Description
147.79	152.90	Andesite
		ANDESITE - Light grey, porphyritic, fine grained, andesite. 5% euhedral plagioclase phenocrysts, 5% euhedral feldspar phenocrysts, and 5% subhedral hornblende phenocrysts up to 5mm wide. 2% fine magnetite disseminations typically associated with hornblende phenocrysts. Sharp irregular, diffuse lower contact with quartz monzonite. Interval is weakly bleached.
		ALTERATION
		« Silicification 1.00*»
		MINERALIZATION
		« Marcasite 2.00%» \
152.90	197.82	Quartz Monzonite
		QUARTZ MONZONITE - Mottled pink, grey, and black, coarse grained, quartz monzonite. Approximately 45% feldspar, 40% plagioclase, 5% hornblende, 5% quartz, 4% biotite, and 1% magnetite. Continuation of 79.32-147.79m. Rare xenoliths of andesite up to 8cm wide. Local limonitic alteration from 180.75m to181.90m. Earthy hematite mineralization zone from 187.33-191.30m. Rare specular hematite stringers occur between180.75-193.0m. EOH
		ALTERATION
		« 180.75- 181.90 Limonite 2.00*»
		MINERALIZATION



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
173.50	175.50	2.00	I102061	0.01	0.28	23
175.50	177.50	2.00	I102062	0.01	0.58	13
177.50	179.50	2.00	I102063	0.01	0.08	10
179.50	180.70	1.20	I102064	0.01	0.11	9
180.70	182.20	1.50	I102065	0.01	0.41	26
182.20	184.20	2.00	I102066	0.01	0.14	10
184.20	186.13	1.93	I102067	0.01	0.21	8
186.13	187.13	1.00	I102068	0.01	0.30	17
189.13	191.20	2.07	I102071	0.01	0.35	8
191.20	193.20	2.00	I102072	0.01	0.21	10
193.20	195.20	2.00	I102073	0.01	0.16	7
195.20	197.82	2.62	I102074	0.01	0.38	27

Project: ProspectorMtn **Hole Number:** PM10-01

From	To	Rocktype & Description
		« 187.33- 192.30 Hematite 50.00%»
		« 180.75- 193.00 Specularite 0.50%»
		FAULTS
		< @ 181.00 Fault 60.00º 20.00cm >
197.82	197.82	EOH



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

DRILL LOG

Project: Prospector Mountain	**Collar Elevation (m):** 1780.0
Hole PM10-02	**Azimuth (º):** 80.0
Location: 6928024 m North, 354908 m East	**Dip (º):** -45.0
Logged by: Ryan Toole	**Length (m):** 203.91
Drilled by: Apex	**Horizontal Projection:**
Assayed by: ALS	**Vertical Projection:**
Core Size: NQ	**Objective** Bonanza Zone; complete fence across broadest part of anomaly with PM10-01
Date Started: 2010/09/08 **Date Completed:** 2010/09/10	
Dip Tests By:	

Summary Log:

0-3.60 CASING

3.60-54.94 MONZONITE – Pinkish grey-green, coarse grained monzonite. Plagioclase has been weakly altered to sericite giving an overall light green color. Trace to 1% disseminated magnetite. Blocky with weak limonitic alteration associated with fractures.

54.94-59.39 ANDESITE – Medium grey, fine grained, porphyritic andesite. 5% pyrite disseminations. Heavily fractured, locally gouged, and weakly bleached.

59.39-78.68 MONZONITE – Pinkish grey-green, coarse grained monzonite. Heavily gouged. Trace to 1% disseminated magnetite.

78.68-82.08 ANDESITE - Medium grey, fine grained, porphyritic andesite. 5% pyrite disseminations. 4cm thick band of massive specular hematite with 10% intermixed pyrite at 80.28m.

82.08-170.09 MONZONITE – Pinkish grey-green, coarse grained monzonite with trace to 1% disseminated magnetite. Locally faulted and gouged.

170-09-172.90 MONZONITE/ALTERATION ZONE – Continuation of previous unit with intense sericite and locally intense manganese mineralization. Local manganese mineralization makes up 60% of composition. Local moderate limonite alteration. Moderate to locally strong sericite alteration.

172.90-186.35 ANDESITE – Light grey, fine grained, porphyritic andesite. Plagioclase phenocrysts have been altered to sericite. 5% medium grained disseminated pyrite. 2% fine grained disseminated magnetite. Local earthy hematite alteration. Weak bleaching.

186.35-203.91 MONZONITE - Pinkish grey-green, coarse grained monzonite with trace to 1% disseminated magnetite. Locally faulted and gouged with associated limonitic alteration. Limonitic alteration zone from 195.0-196.68m. EOH

Downhole surveys:

Depth	Dip	Azimuth
15.24	-46.60	81.90
97.54	-47.00	82.60
203.00	-47.60	82.70

Project: ProspectorMtn **Hole Number:** PM10-02

From	To	Rocktype	& Description
0.00	3.60	Casing	

CASING - Overburden

From	To	Rocktype	& Description
3.60	54.94	Quartz Monzonite	

QUARTZ MONZONITE - Pinkish green, coarse grained, quartz monzonite. Approximately 45% feldspar, 40% plagioclase that has been weakly altered to sericite, 5% hornblende, 5% quartz, 4% biotite, and trace to 1% magnetite. Entire interval is blocky with local fault gouging. Fractures exhibit weak oxidation. Interval is massive and featureless. Sharp lower contact with andesite at 40 degrees TCA.

ALTERATION


« Sericite 2.00*»

MINERALIZATION

« Marcasite 1.00%»

FAULTS

< @ 7.12 Fault Gouge 60.00° 22.00cm >
< @ 21.57 Fault 70.00° 356.00cm >
< @ 30.23 Fault Gouge 75.00° 15.00cm >
< @ 37.01 Fault Gouge 45.00° 6.00cm >
< @ 38.92 Fault Gouge 50.00° 30.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

Project: ProspectorMtn **Hole Number:** PM10-02

From	To	Rocktype & Description
54.94	59.39	Andesite

ANDESITE - Medium grey, fine grained, porphyritic andesite. 10% subhedral hornblende phenocrysts, 5% subhedral plagioclas phenocrysts (wealy altered to sericite, 2% subhedral feldspar phenocrysts, and 5% disseminated pyrite cubes up to 3mm. Interval is highly fractured and jointed, locally faulted, and weakly bleached. Lower contact is to fractured and broken to get an orientation.

ALTERATION

« Sericite 1.00*»
« Silicification 1.00*»

MINERALIZATION


« Pyrite 5.00%»

FAULTS

Interval is heavily jointed, with the dominate direction of jointing at 45 degrees TCA

From	To	Rocktype & Description
59.39	78.68	Quartz Monzonite


QUARTZ MONZONITE - Pinkish green, coarse grained, quartz monzonite.



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

Project: ProspectorMtn **Hole Number:** PM10-02


From	To	Rocktype & Description
		Approximately 45% feldspar, 40% plagioclase that has been altered to sericite, 5% hornblende, 5% quartz, 4% biotite, and trace to 1% magnetite. Interval is heavily gouged. Sharp lower contact with andesite at 70 degrees TCA. ALTERATION « 62.00- 62.12 Sericite 3.00*» « 71.20- 71.70 Sericite 3.00*» « 76.38- 76.53 Sericite 3.00*» « 76.88- 77.63 Sericite 3.00*» MINERALIZATION « Marcasite 1.00%» FAULTS < @ 62.00 Fault Gouge 70.00° 12.00cm > < @ 64.01 Fault 55.00° 40.00cm > < @ 68.15 Fault 50.00° 15.00cm > < @ 71.20 Fault Gouge 45.00° 50.00cm > < @ 73.38 Fault 40.00° 126.00cm > < @ 75.10 Fault 43.00° 20.00cm > < @ 75.83 Fault 45.00° 10.00cm > < @ 76.38 Fault Gouge 45.00° 15.00cm > < @ 76.88 Fault Gouge 90.00° 75.00cm >
78.68	82.08	Andesite
		ANDESITE - Medium grey, fine grained, porphyritic andesite. Phenocrysts are composed of 35% subhedral plagioclase, partially and weakly altered to sericite, 15% subhedral orthoclase, and 50% subhedral hornblende. 5% of total composition is pyrite disseminations. Interval is heavily fractured and weakly bleached. 4cm thick band of massive specular hematite with 10% intermixed pyrite from 80.28-80.32m. Sharp lower contact with monzonite at 50 degrees TCA. ALTERATION



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
79.26	80.26	1.00	I102075	0.01	0.61	4
80.26	80.58	0.32	I102076	0.01	0.19	1
80.58	81.58	1.00	I102077	0.01	0.19	2

Project: ProspectorMtn **Hole Number:** PM10-02


From	To	Rocktype & Description
		« Sericite 1.00*»
		« Silicification 1.00*»
		MINERALIZATION
		« Pyrite 5.00%»
82.08	170.09	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish green, coarse grained, quartz monzonite. Approximately 45% feldspar, 40% plagioclase that has been altered to sericite, 5% hornblende, 5% quartz, 4% biotite, and trace to 1% magnetite. Locally faulted and gouged. Massive and featureless. Sharp lower contact with fault/alteration zone.
		ALTERATION
		« 95.88- 99.00 Sericite 3.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		< @ 95.88 Fault 47.00° 3.12cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
90.75	91.75	1.00	I102078	0.01	0.40	32
93.00	94.35	1.35	I102081	0.01	1.30	23
94.35	96.00	1.65	I102082	0.01	0.49	56
96.00	97.00	1.00	I102083	0.01	0.64	33
97.00	98.00	1.00	I102084	0.01	0.28	12
98.00	99.00	1.00	I102085	0.01	0.39	26
99.00	100.00	1.00	I102086	0.01	0.36	19
110.35	111.35	1.00	I102087	0.01	0.30	24
111.35	112.20	0.85	I102088	0.01	0.28	11
112.20	112.96	0.76	I102089	0.01	0.42	42
112.96	113.96	1.00	I102091	0.01	0.23	21
145.29	146.29	1.00	I102092	0.01	0.30	29
146.29	146.65	0.36	I102093	0.01	1.69	92
146.65	147.65	1.00	I102094	0.01	0.19	30
169.00	169.50	0.50	I102095	0.01	0.16	395
169.50	170.27	0.77	I102096	0.01	0.56	113

Project: ProspectorMtn **Hole Number:** PM10-02

From	To	Rocktype & Description



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

Project: ProspectorMtn **Hole Number:** PM10-02

From	To	Rocktype & Description
170.09	172.90	Quartz Monzonite/Alteration Zone

QUARTZ MONZONITE/ALTERATION ZONE - Continuation of previous unit with intense sericite and locally intense manganese mineralization. Manganese locally makes up 60% of rock composition with an intersertal texture. Locally moderate limonite alteration. Primary textures are dominantly overprinted by alteration, with feldspar and plagiocase being altered to sericite. Heavily altered ambiguous lower contact with andesite.

ALTERATION


« Sericite 4.00*»

« 170.50- 172.00 Manganite 60.00%» (alteration/mineralization)

« 170.40- 172.70 Limonite 2.00*»

MINERALIZATION

« 172.50- 172.90 Tourmaline 10.00%»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
170.27	171.27	1.00	I102097	0.02	1.93	586
171.27	172.00	0.73	I102098	0.02	1.70	876

Project: ProspectorMtn **Hole Number:** PM10-02

From	To	Rocktype & Description
172.90	186.35	Andesite
186.35	203.91	Quartz Monzonite

ANDESITE - Light grey, fine grained, porphyritic,andesite with 40% plagioclase phenocrysts. Locally plagioclase phenocrysts have been altered to sericite. 5% medim grained disseminated pyrite, 2% fine grained specular hematite. Local earthy hematite mineralization. Weak bleaching throughout interval. Broken lower contact; unable to get orientation.

ALTERATION

« Sericite 1.00*»

MINERALIZATION

« Pyrite 5.00%»
« Specularite 2.00%»

« 172.90- 173.35 Hematite 10.00%»

QUARTZ MONZONITE - Pinkish green, coarse grained, quartz monzonite. Approximately 45% feldspar, 40% plagioclase that has been altered to sericite, 5% hornblende, 5% quartz, 4% biotite, and trace to 1% magnetite. Locally faulted and gouged with associated limonitic alteration. Upper 2m is blocky, gouged, and faulted. Limonite weathering zone with associated fault gouging from 195.0-196.68m no visible mineralization throughout interval. EOH

ALTERATION


« 186.35- 188.35 Sericite 3.00*»

« 195.00- 196.68 Limonite 2.00*»

MINERALIZATION

« Marcasite 1.00%»


« 186.35- 187.20 Tourmaline 5.00%»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
172.00	173.00	1.00	I102099	0.03	0.43	124
173.00	175.00	2.00	I102101	0.01	0.68	201
175.00	176.95	1.95	I102102	0.01	0.51	31
176.95	177.40	0.45	I102103	0.13	2.13	160
177.40	179.40	2.00	I102104	0.01	0.77	23
179.40	181.40	2.00	I102105	0.21	0.71	9
181.40	183.40	2.00	I102106	0.06	1.36	110
183.40	185.94	2.54	I102107	0.01	0.25	6
185.94	186.94	1.00	I102108	0.01	0.28	123
187.80	190.80	3.00	I102111	0.01	0.36	32
190.80	192.80	2.00	I102112	0.01	0.19	15
192.80	194.80	2.00	I102113	0.01	0.18	10
194.80	195.80	1.00	I102114	0.01	2.17	127
195.80	196.68	0.88	I102115	0.11	4.47	57
196.68	198.45	1.77	I102116	0.01	0.71	81
198.45	200.45	2.00	I102117	0.01	0.42	97
200.45	202.00	1.55	I102118	0.01	0.33	69

Project: ProspectorMtn **Hole Number:** PM10-02

From	To	Rocktype & Description
		FAULTS
		< @ 186.35 Fault 50.00° 200.00cm>
		< @ 195.90 Fault Gouge 45.00° 77.00cm >
		< @ 197.80 Fault 50.00° 3.00cm >
		< @ 198.15 Fault Gouge 45.00° 10.00cm >
		< @ 198.45 Fault Gouge 60.00° 35.00cm > (Two 2cm rose quartz veins parallel to fault)
203.91	**203.91**	**EOH**



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

DRILL LOG

Project: Prospector Mountain	**Collar Elevation (m):** 1833.0
Hole PM10-03	**Azimuth (º):** 80.0
Location: 6927533 m North, 355140 m East	**Dip (º):** -45.0
Logged by: Ryan Toole	**Length (m):** 236.53
Drilled by: Apex	**Horizontal Projection:**
Assayed by: ALS	**Vertical Projection:**
Core Size: NQ	**Objective** Southern end of Bonanza Zone near highest grade float samples
Date Started: 2010/09/10 **Date Completed:** 2010/09/13	
Dip Tests By:	

Summary Log:

0-3.13 CASING

3.13-24.25 QUARTZ MONZONITE- Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite.

24.25-35.59 ANDESITE - Light to medium grey, fine grained, porphyritic andesite with made up of 50% plagioclase phenocrysts, partly altered to feldspar, and 10% hornblende phenocrysts with hematite rims.

35.59-71.63 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Local alteration zones including specular hematite stringers, tourmaline mineralization, weak bleaching and weak limonite alteration. I

71.63-88.50 ANDESITE - Light grey, fine grained, porphyritic andesite. Phenocrysts are all plagoclase, mostly altered to sericite and become less altered downhole. Contains 3% fine disseminated magnetite.

88.50-172.63 QUARTZ MONZONITE - Originally this was pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. However the plagioclase has been altered to sericite to give the appearance that the feldspar are phenocrysts. This alteration weakens downhole and disappears by 140m. Interval is heavily gouged (~50%) with local limonite weathering and tourmaline mineralization.

172.63-199.95 QUARTZ MONZONITE/ALTERATION ZONE - Continuation of previous unit however with local alteration zones from 172.63-182.24m, and 193.35-199.95m containing tourmaline and specular hematite mineralization, and limonite and sericite weathering and alteration.

199.95-236.53 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase has been weakly altered to sericite. Local faulting with associated tourmaline mineralization, limonite and sericite alteration. EOH

Downhole surveys:

Depth	Dip	Azimuth
0.00	-45.00	80.00

Project: ProspectorMtn **Hole Number:** PM10-03


From	To	Rocktype & Description
0.00	3.13	Casing
		CASING - Overburden
3.13	24.25	Quartz Monzonite
		QUARTZ MONZONITE- Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Weak oxidation rims around feldspar grains. Locally gouged with a broken lower contact.
		ALTERATION
		« Sericite 1.00*» (Plagioclase grains are weakly altered to sericite to give a weak greenish tinge)
		« 15.10- 16.50 Sericite 2.00*» (altered plagioclase)
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		< @ 7.95 Fault Gouge 60.00° 10.00cm >
		NOTE: Entire hole is heavily gouged, faulted and blocky until a depth of 199.95m
24.25	35.59	Andesite
		ANDESITE - Light to medium grey, fine grained, porphyritic andesite with made up of 50% plagioclase phenocrysts, with feldspar rims, and 10% hornblende phenocrysts with hematite rims. Trace disseminated magnetite. Interval is blocky and lower 3.5m is fault gouged.
		ALTERATION
		« Sericite 1.00*»
		MINERALIZATION
		« Marcasite 1.00%»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

Project: ProspectorMtn **Hole Number:** PM10-03

From	To	Rocktype & Description
		FAULTS
		< @ 32.00 Fault 58.00º 359.00cm >
35.59	71.63	**Quartz Monzonite**
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Interval is heavily gouged with intense sericite alteration. Local alteration zones including specular hematite stringers, tourmaline mineralization, weak bleaching and weak limonite alteration. Irregular, diffuse lower contact between monzonite and andesite.
		ALTERATION
		« Sericite 3.00*»
		« 53.75- 59.80 Sericite 4.00*»
		« 53.75- 59.80 Limonite 1.00*»
		MINERALIZATION
		« 51.50- 53.75 Specularite 5.00%»
		« 51.50- 53.75 Tourmaline 5.00%»
		« 59.80- 61.60 Specularite 5.00%»
		« 59.80- 61.60 Tourmaline 5.00%»
		FAULTS
		Interval is faulted and gouged from top to bottom at 60 degrees TCA.
		< @ 35.59 Fault 60.00º 999.99cm >
		< @ 45.59 Fault 60.00º 999.99cm >
		< @ 55.59 Fault 60.00º 999.99cm >
		< @ 65.59 Fault 60.00º 604.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
50.45	51.45	1.00	I102121	0.01	0.10	17
51.45	52.40	0.95	I102122	0.01	0.23	17
52.40	53.97	1.57	I102123	0.02	1.38	18
53.97	56.69	2.72	I102124	0.01	3.85	192
56.69	59.74	3.05	I102125	0.02	1.02	17
59.74	61.64	1.90	I102126	0.04	2.06	137
61.64	62.79	1.15	I102127	0.01	3.21	157
62.79	65.84	3.05	I102128	0.01	0.16	12
65.84	68.88	3.04	I102129	0.01	0.19	14
68.88	71.68	2.80	I102131	0.01	0.09	9

Project: ProspectorMtn **Hole Number:** PM10-03

From	To	Rocktype & Description
71.63	88.50	Andesite

ANDESITE - Light grey, fine grained, porphyritic andesite. Phenocrysts are all plagoclase, mostly altered to sericite and become less altered downhole. Contains 3% fine disseminated magnetite. Interval is heavily gouged. Local interval of gouged monzonite from 77.80-81.28m. Sharp gouged lower contact at 45 degrees TCA.

ALTERATION

« Sericite 3.00*»

MINERALIZATION

« Marcasite 3.00%»

FAULTS

< @ 71.63 Fault 55.00° 999.99cm >
< @ 81.63 Fault 55.00° 687.00cm >

MONZONITE INTERVAL


« 77.80- 81.28 Monzonite »

From	To	Rocktype & Description
88.50	172.63	Quartz Monzonite

QUARTZ MONZONITE - Originally this was pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. However the plagioclase has been altered to sericite to give the appearance that the feldspar are phenocrysts. This alteration weakens downhole and disappears by 140m. Interval is heavily gouged (~50%) with local limonite weathering and tourmaline mineralization.

ALTERATION


« 87.82- 90.32 Sericite 4.00*»
« 93.62- 96.27 Sericite 4.00*»
« 111.00- 137.50 Sericite 4.00*»
« 170.30- 172.43 Sericite 3.00*»
« 135.60- 137.20 Limonite 1.00*»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
71.68	74.98	3.30	I102132	0.01	0.16	10
74.98	77.80	2.82	I102133	0.01	0.09	21
77.80	80.38	2.58	I102134	0.01	0.09	11
80.38	81.28	0.90	I102135	0.01	0.12	29
81.28	84.12	2.84	I102136	0.01	0.21	43
84.12	85.50	1.38	I102137	0.01	0.02	3
85.50	87.17	1.67	I102138	0.01	0.05	2
87.17	88.50	1.33	I102139	0.01	0.16	63
88.50	90.30	1.80	I102141	0.01	0.12	29
90.30	93.27	2.97	I102142	0.01	0.08	9
93.27	96.32	3.05	I102143	0.01	0.07	29
96.32	99.36	3.04	I102144	0.01	0.07	7
99.36	102.41	3.05	I102145	0.01	0.11	7
102.41	105.46	3.05	I102146	0.01	0.07	9
105.46	108.51	3.05	I102147	0.01	0.09	7
108.51	111.56	3.05	I102148	0.01	0.07	5
114.61	117.65	3.04	I102151	0.01	0.08	4
117.65	120.70	3.05	I102152	0.01	0.07	4
120.70	123.35	2.65	I102153	0.01	0.07	9
123.35	124.58	1.23	I102154	0.01	0.05	5
124.58	126.80	2.22	I102155	0.01	0.06	4
126.80	129.85	3.05	I102156	0.01	0.06	4
129.85	132.79	2.94	I102157	0.01	0.06	3

Project: ProspectorMtn **Hole Number:** PM10-03

From	To	Rocktype & Description
		MINERALIZATION
		« 135.60- 137.20 Tourmaline 5.00%»
		« 135.60- 137.20 Specularite 3.00%»
		« 148.98- 151.00 Tourmaline 5.00%»
		« 148.98- 151.00hs 3.00%»
		« Marcasite 1.00%»
		FAULTS
		< @ 87.83 Fault Gouge 50.00° 249.00cm >
		< @ 92.63 Fault Gouge 45.00° 265.00cm >
		< @ 111.00 Fault Gouge 45.00° 999.99cm >
		< @ 121.00 Fault Gouge 45.00° 999.99cm >
		< @ 131.00 Fault Gouge 45.00° 650.00cm >
		< @ 170.30 Fault Gouge 40.00° 213.00cm >




From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
132.79	133.79	1.00	I102158	0.01	0.05	5
135.22	135.94	0.72	I102161	0.01	0.10	11
135.94	137.00	1.06	I102162	0.01	0.20	36
137.00	139.00	2.00	I102163	0.01	0.11	4
139.00	140.00	1.00	I102164	0.01	0.06	3
140.00	142.00	2.00	I102165	0.01	0.08	5
142.00	144.00	2.00	I102166	0.01	0.07	2
144.00	146.00	2.00	I102167	0.01	0.10	3
146.00	148.00	2.00	I102168	0.01	0.07	3
148.00	150.00	2.00	I102169	0.01	0.12	45
150.00	152.00	2.00	I102171	0.01	0.11	29
152.00	154.00	2.00	I102172	0.25	0.20	17
154.00	156.00	2.00	I102173	0.01	0.09	4
156.00	158.00	2.00	I102174	0.01	0.12	3
158.00	160.00	2.00	I102175	0.01	0.09	3
160.00	162.00	2.00	I102176	0.01	0.17	9
162.00	164.00	2.00	I102177	0.01	0.12	3
164.00	166.00	2.00	I102178	0.01	0.17	5
166.00	168.00	2.00	I102179	0.01	0.15	3
168.00	170.00	2.00	I102181	0.01	0.16	3
170.00	172.60	2.60	I102182	0.01	0.27	33
172.60	173.60	1.00	I102183	0.01	0.25	17

Project: ProspectorMtn **Hole Number:** PM10-03

From	To	Rocktype & Description
172.63	199.95	Quartz Monzonite/Alteration Zone

QUARTZ MONZONITE/ALTERATION ZONE - Continuation of previous unit however with local alteration zones from 172.63-182.24m, and 193.35-199.95m containing tourmaline and specular hematite mineralization, and limonite and sericite weathering and alteration. Intense sericite alteration makes up interval between alteration zones. Lower contact signified by loss of alteration.


ALTERATION



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
173.60	174.80	1.20	I102184	0.02	0.82	91
174.80	175.80	1.00	I102185	0.01	0.34	153
175.80	176.85	1.05	I102186	0.01	0.39	30
176.85	178.00	1.15	I102187	0.02	0.91	57
178.00	179.00	1.00	I102188	0.01	0.47	25
180.00	181.66	1.66	I102191	0.01	0.21	15
181.66	184.71	3.05	I102192	0.01	0.21	15
184.71	187.76	3.05	I102193	0.01	0.24	37
187.76	190.81	3.05	I102194	0.01	0.25	29

Project: ProspectorMtn **Hole Number:** PM10-03


From	To	Rocktype & Description
		« 172.63- 182.24 Sericite 2.00*»
		« 182.24- 193.35 Sericite 4.00*»
		« 193.35- 199.95 Sericite 2.00*»
		« 172.63- 182.24 Limonite 4.00*»
		« 193.35- 199.95 Limonite 4.00*»
		« 182.24- 193.35 Limonite 1.00*»
		MINERALIZATION
		« 172.63- 182.24 Tourmaline 5.00%»
		« 193.35- 199.95 Tourmaline 5.00%»
		« 172.63- 182.24 Specularite 3.00%»
		« 193.35- 199.95 Specularite 3.00%»
199.95	236.53	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase has been weakly altered to sericite. Local faulting and tourmaline mineralization, limonite and sericite alteration. EOH
		ALTERATION
		« 208.98- 209.10 Limonite 2.00*»
		« 208.98- 209.10 Sericite 2.00*»
		« 222.17- 222.63 Limonite 2.00*»
		« 222.17- 222.63 Sericite 2.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		« 230.10- 233.30 Tourmaline 5.00%»
		FAULTS



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
190.81	193.32	2.51	I102195	0.01	0.14	9
193.32	194.42	1.10	I102196	0.02	0.22	6
194.42	195.52	1.10	I102197	0.01	0.24	12
195.52	196.90	1.38	I102198	0.01	0.55	21
197.90	198.90	1.00	I102201	0.01	0.10	11
198.90	199.90	1.00	I102202	0.01	0.41	110
199.90	200.90	1.00	I102203	0.01	0.28	199
200.90	203.00	2.10	I102204	0.01	0.36	117
203.00	204.00	1.00	I102205	0.01	0.47	80
204.00	206.00	2.00	I102206	0.01	0.21	19
206.00	207.00	1.00	I102207	0.01	0.32	163
207.00	208.00	1.00	I102208	0.01	0.18	20

Project: ProspectorMtn **Hole Number:** PM10-03

From	To	Rocktype & Description
		< @ 208.98 Fault 45.00° 12.00cm >
		< @ 222.17 Fault Gouge 45.00° 46.00cm >
236.53	236.53	EOH



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

EQUITY

DRILL LOG

Project: Prospector Mountain	**Collar Elevation (m):** 1821.0
Hole PM10-04	**Azimuth (º):** 80.0
Location: 6927498 m North, 355172 m East	**Dip (º):** -50.0
Logged by: Ryan Toole	**Length (m):** 186.31
Drilled by: Apex	**Horizontal Projection:**
Assayed by: ALS	**Vertical Projection:**
Core Size: NQ	**Objective** Southern end of Bonanza Zone near highest grade float samples; step out SE from PM10-03
Date Started: 2010/09/13 **Date Completed:** 2010/09/15	
Dip Tests By:	

Summary Log:

0-5.90 CASING

5.90-100.12 QUARTZ MONZONITE/FAULT ZONE - Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase has been weakly altered to sericite. 45% of interval is gouged and faulted. Rare local zones of limonite weathering, specular hematite stringers, and tourmaline mineralization. Alteration zone from 98.98-100.12 with 1% specular hematite stringers, moderate sericite alteration, and moderate oxidation.

100.12-142.86 QUARTZ MONZONITE - Continuation of previous unit however only 10% of interval is gouged. Gouged alteration zone from 113.09-115.37m containing 2% specular hematite stringers, 5% tourmaline mineralization, moderate oxidation and moderate to locally strong sericite alteration. Local specular hematite stringers and tourmaline mineralization.

142.86-154.15 QUARTZ MONZONITE/FAULT ZONE - Continuation of previous unit however heavily faulted and gouged. 85% of interval is rubbly sand to clay. Weak limonite weathering in lower 2m.

154.15-159.75 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 8% biotite, 5% quartz, 4% hornblende, 2% pyrite, and 1% disseminated magnetite. 2% disseminated medium grained pyrite cubes associated with 2% specular hematite stringers. Specular hematite stringers have 0.5cm oxidation "rims."


159.75-186.31 QUARTZ MONZONITE/FAULT ZONE - Continuation of previous unit however entire interval is heavily faulted and gouged. Alteration zone from 164.20-170.39m with 10% tourmaline mineralization, 2% specular hematite veins, and weak bleaching. Hole ended because of cave in after bit change. Tried to re-enter hole however blocked at ~300 ft. EOH

Downhole surveys:

Depth	Dip	Azimuth
12.19	-51.50	78.00

Project: ProspectorMtn **Hole Number:** PM10-04

From	To	Rocktype & Description
0.00	5.90	Casing
		CASING - Overburden
5.90	100.12	Quartz Monzonite
		QUARTZ MONZONITE/FAULT ZONE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase has been weakly altered to sericite. 45% of interval is gouged and faulted. Rare local zones of limonite weathering, specular hematite stringers, and tourmaline mineralization. Alteration zone from 98.98-100.12 with 1% specular hematite stringers, moderate sericite alteration, and moderate oxidation. Sharp lower contact at 55 degrees TCA between alteration zone and underlying quartz monzonite.
		ALTERATION
		« Sericite 3.00*»
		MINERALIZATION
		« 14.24- 14.94 Specularite 2.00%»
		« 98.98- 100.12 Specularite 1.00%»
		« 98.98- 100.12 Tourmaline 1.00%»
		FAULTS
		45%+ of the interval is gouged and faulted generaly between 45 and 50 degrees TCA.
		Major Gouges
		< @ 21.34 Fault Gouge 50.00° 906.00cm >
		< @ 36.50 Fault Gouge 45.00° 975.00cm >
		< @ 54.86 Fault Gouge 50.00° 264.00cm >
		< @ 63.90 Fault Gouge 45.00° 999.00cm >
		< @ 73.90 Fault Gouge 45.00° 999.00cm >
		< @ 83.90 Fault Gouge 45.00° 972.00cm >
		< @ 98.68 Fault 55.00° 142.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
12.64	13.64	1.00	I102209	0.01	0.22	10
13.64	15.00	1.36	I102211	0.09	1.11	9
15.00	18.29	3.29	I102212	0.01	0.11	9
18.29	21.34	3.05	I102213	0.01	0.20	8
21.34	24.38	3.04	I102214	0.01	0.16	8
24.38	27.43	3.05	I102215	0.01	0.10	11
27.43	30.48	3.05	I102216	0.01	0.13	12
30.48	33.53	3.05	I102217	0.01	0.09	7
33.53	36.58	3.05	I102218	0.01	0.09	11
36.58	38.62	2.04	I102219	0.01	0.15	13
38.62	39.62	1.00	I102221	0.01	0.12	9
39.62	42.67	3.05	I102222	0.02	0.08	7
42.67	45.72	3.05	I102223	0.01	0.16	6
45.72	48.77	3.05	I102224	0.01	0.10	5
48.77	51.82	3.05	I102225	0.01	0.08	7
51.82	54.86	3.04	I102226	0.01	0.07	11
54.86	57.91	3.05	I102227	0.01	0.07	7
57.91	60.96	3.05	I102228	0.01	0.06	6
64.00	67.05	3.05	I102231	0.01	0.07	11
67.05	70.10	3.05	I102232	0.01	0.05	9
70.10	73.15	3.05	I102233	0.01	0.04	6
73.15	76.20	3.05	I102234	0.01	0.06	42
76.20	79.25	3.05	I102235	0.01	0.07	7
79.25	82.30	3.05	I102236	0.01	0.06	8
82.30	85.34	3.04	I102237	0.01	0.33	12
85.34	88.39	3.05	I102238	0.01	0.07	9
91.44	94.49	3.05	I102241	0.01	0.16	6
94.49	97.54	3.05	I102242	0.01	0.10	6
97.54	98.68	1.14	I102243	0.01	0.11	7
98.68	100.12	1.44	I102244	0.01	0.41	38


Project: ProspectorMtn **Hole Number:** PM10-04

From	To	Rocktype & Description
100.12	142.86	Quartz Monzonite

QUARTZ MONZONITE - Pinkish grey, coarse grained qyuartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Continuation of previous unit however only 10% of interval is gouged. Gouged alteration zone from 113.09-115.37m containing 2% specular hematite stringers, 5% tourmaline mineralization, moderate oxidation and moderate to locally strong sericite alteration. Local specular hematite stringers and tourmaline mineralization. Sharp faulted lower contact at 60 degrees TCA.

ALTERATION


« 104.55- 104.65 Sericite 3.00*»
« 106.42- 106.47 Sericite 3.00*»
« 107.90- 108.46 Sericite 3.00*»
« 113.09- 115.75 Sericite 3.00*»
« 121.15- 123.87 Sericite 2.00*»
« 128.54- 128.69 Sericite 1.00*»
« 129.27- 129.52 Sericite 1.00*»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
100.12	102.12	2.00	I102245	0.01	0.12	13
111.40	112.40	1.00	I102246	0.01	0.04	3
112.40	113.09	0.69	I102247	0.01	0.07	32
113.09	114.76	1.67	I102248	0.01	0.10	60
114.76	115.46	0.70	I102249	0.01	0.10	54
115.46	117.46	2.00	I102251	0.01	0.10	30
117.46	119.46	2.00	I102252	0.01	0.07	16
119.46	121.05	1.59	I102253	0.01	0.17	44
121.05	123.72	2.67	I102254	0.01	0.10	19
123.72	125.72	2.00	I102255	0.01	0.18	24
125.72	127.72	2.00	I102256	0.01	0.22	12
127.72	129.72	2.00	I102257	0.01	0.24	39
129.72	131.72	2.00	I102258	0.01	0.21	8
131.72	133.72	2.00	I102259	0.01	0.19	5
133.72	135.72	2.00	I102261	0.01	0.16	9
135.72	137.72	2.00	I102262	0.01	0.35	56
137.72	139.41	1.69	I102263	0.01	0.26	59
139.41	141.41	2.00	I102264	0.01	0.23	12
141.41	142.86	1.45	I102265	0.01	0.23	47

Project: ProspectorMtn **Hole Number:** PM10-04


From	To	Rocktype & Description



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

Project: ProspectorMtn **Hole Number:** PM10-04


From	To	Rocktype & Description
		MINERALIZATION
		« 113.09- 115.37 Specularite 2.00%»
		« 120.00- 124.00 Specularite 2.00%»
		« 136.00- 142.86 Specularite 2.00%»
		« 113.09- 115.37 Tourmaline 5.00%»
		« 127.85- 128.00 Tourmaline 5.00%»
		FAULTS
		< @ 104.55 Fault 30.00° 10.00cm >
		< @ 106.42 Fault 50.00° 5.00cm >
		< @ 107.90 Fault 55.00° 56.00cm >
		< @ 113.09 Fault 45.00° 266.00cm >
		< @ 121.15 Fault 60.00° 272.00cm >
		< @ 128.54 Fault 52.00° 15.00cm >
		< @ 129.27 Fault 38.00° 25.00cm >
142.86	**154.15**	**Quartz Monzonite**
		QUARTZ MONZONITE/FAULT ZONE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Continuation of previous unit however heavily faulted and gouged. 85% of interval is rubbly sand to clay. Weak limonite weathering in lower 2m. Sharp faulted lower contact at 60 degrees TCA.
		ALTERATION
		« Sericite 3.00*»
		MINERALIZATION
		« Specularite 1.00%» Rare specular hematite stringers, mostly destroyed by faulting.



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
142.86	**144.50**	**1.64**	**I102266**	**0.01**	**0.25**	**62**
144.50	**146.30**	**1.80**	**I102267**	**0.01**	**0.14**	**79**
146.30	**149.35**	**3.05**	**I102268**	**0.01**	**0.16**	**52**

Project: ProspectorMtn **Hole Number:** PM10-04


From	To	Rocktype & Description
		« Pyrite 1.00%» Medium grained disseminated pyrite generally associated with specular hematite stringers. FAULTS < @ 142.86 Fault 60.00° 999.99cm > < @ 152.86 Fault 60.00° 129.00cm >
154.15	159.75	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 8% biotite, 5% quartz, 4% hornblende, 2% pyrite, and 1% disseminated magnetite. Interval is blocky however not gouged like previous interval. 2% disseminated medium grained pyrite cubes associated with 2% specular hematite stringers. Specular hematite stringers have 0.5cm oxidation rims. Interval becomes blockier down hole. Faulted lower contact at 70 degrees TCA. MINERALIZATION « Specularite 2.00%» « Pyrite 2.00%»
159.75	186.31	Quartz Monzonite/Fault Zone
		QUARTZ MONZONITE/FAULT ZONE - Continuation of previous unit however entire interval is heavily faulted and gouged. Alteration zone from 164.20-170.39m with 10% tourmaline mineralization, 2% specular hematite veins, and weak bleaching. Hole ended because of cave in after bit change. Tried to re-enter hole however blocked at ~300 ft. ALTERATION « 164.20- 170.39 Silicification 1.00*» MINERALIZATION « 164.20- 170.39 Tourmaline 10.00%» « 164.20- 170.39 Specularite 2.00%» « 184.88- 186.31 Specularite 1.00%»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
152.40	154.30	1.90	I102271	0.01	0.18	20
154.30	156.30	2.00	I102272	0.01	0.22	38
156.30	158.50	2.20	I102273	0.01	0.23	43
158.50	161.54	3.04	I102274	0.01	0.13	14
161.54	164.20	2.66	I102275	0.01	0.13	11
164.20	166.20	2.00	I102276	0.02	0.35	57
166.20	168.20	2.00	I102277	0.01	0.25	26
168.20	170.39	2.19	I102278	0.01	0.15	26
173.74	176.79	3.05	I102281	0.01	0.13	5
176.79	179.83	3.04	I102282	0.01	0.18	14
179.83	182.88	3.05	I102283	0.01	0.10	19
182.88	184.88	2.00	I102284	0.02	0.13	6
184.88	186.31	1.43	I102285	0.03	0.14	2

Project: ProspectorMtn **Hole Number:** PM10-04

From	To	Rocktype	& Description
			FAULTS
			Entire interval is faulted at 60 degrees TCA
			< @ 159.75 Fault 60.00º 999.99cm >
			< @ 169.75 Fault 60.00º 999.99cm >
			< @ 179.75 Fault 60.00º 656.00cm >
186.31	**186.31**		**EOH**



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

EQUITY

DRILL LOG

Project: Prospector Mountain	**Collar Elevation (m):** 1839.0
Hole PM10-05	**Azimuth (º):** 80.0
Location: 6927795 m North, 355044 m East	**Dip (º):** -45.0
Logged by: Ryan Toole	**Length (m):** 158.19
Drilled by: Apex	**Horizontal Projection:**
Assayed by: ALS	**Vertical Projection:**
Core Size: NQ	**Objective** Bonanza Zone; middle part
Date Started: 2010/09/15 **Date Completed:** 2010/09/17	
Dip Tests By:	

Summary Log:

0-3.50 CASING

3.50-77.80 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 50% plagioclase, 30% feldspar, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase crystals have feldspar rims. Gouged and faulted throughout interval. Fault gouge from 9.74-16.43m has moderate limonite weathering and weak manganese mineralization.

77.80-93.02 QUARTZ MONZONITE/ALTERATION ZONE - Continuation of previous unit with locally 5% manganese mineralization and rare specular hematite stringers which deminish downhole. Vuggy oxidized quartz vein with locally intense limonitic weathering from 82.30-82.55m.

93.02-124.94 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 50% plagioclase, 30% feldspar, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase crystals have feldspar rims. Massive and featurless

124.94-127.81 ANDESITE - Light to medium grey, fine grained, porphyritic andesite dyke. 10% plagioclase phenocrysts and 5% disseminated magnetite. Weakly bleached.

127.81-134.01 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 50% plagioclase, 30% feldspar, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase crystals have feldspar rims. Continuation of previous monzonite unit however heavily faulted and gouged.

134.01-140.65 ANDESITE - Light to medium grey, fine grained, porphyritic andesite with 40% plagioclase, 10% feldpsar, and 5% hornblende phenocrysts. 2% disseminated magnetite. Weakly bleached.


140.65-158.19 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 50% plagioclase, 30% feldspar, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase crystals have feldspar rims. Locally faulted. Andesite dyke the same as 134.01-140.65 from 156.55-157.50m. EOH

Downhole surveys:

Depth	Dip	Azimuth
60.96	-44.30	77.10
157.25	-43.50	78.20

Project: ProspectorMtn **Hole Number:** PM10-05


From	To	Rocktype & Description
0.00	3.50	Casing
		CASING - Overburden
3.50	77.80	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 50% plagioclase, 30% feldspar, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase crystals have feldspar rims. Gouged and faulted throughout interval. Fault gouge from 9.74-16.43m has moderate limonite weathering and weak manganese mineralization. No visible tourmaline or specular hematite stringers. Faulted lower contact with underlying alteration zone at 40 degrees TCA.
		ALTERATION
		« 9.74- 16.43 Sericite 3.00*»
		« 9.74- 16.43 Limonite 1.00*»
		« 19.00- 21.03 Sericite 3.00*»
		« 22.95- 25.78 Sericite 3.00*»
		« 66.90- 69.12 Sericite 3.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		Major Faults (Entire interval is blocky and gouged)
		< @ 9.74 Fault Gouge 50.00° 669.00cm >
		< @ 19.00 Fault Gouge 50.00° 203.00cm >
		< @ 22.95 Fault Gouge 50.00° 283.00cm >
		< @ 43.05 Fault 50.00° 999.99cm >
		< @ 53.05 Fault 50.00° 555.00cm >
		< @ 66.90 Fault Gouge 50.00° 222.00cm >
		< @ 71.60 Fault 50.00° 320.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
8.74	9.74	1.00	I102286	0.01	0.18	55
9.74	10.74	1.00	I102287	0.01	3.19	234
10.74	11.74	1.00	I102288	0.01	0.57	46
11.74	12.74	1.00	I102289	0.01	0.19	11
12.74	14.74	2.00	I102291	0.04	2.59	123
14.74	16.43	1.69	I102292	0.13	7.08	1180
16.43	17.43	1.00	I102293	0.01	0.35	15
76.80	77.80	1.00	I102294	0.01	0.27	18

Project: ProspectorMtn **Hole Number:** PM10-05


From	To	Rocktype & Description
77.80	93.02	Quartz Monzonite/Alteration Zone



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
77.80	79.80	2.00	I102295	0.15	2.12	39

Project: ProspectorMtn **Hole Number:** PM10-05


From	To	Rocktype & Description
		QUARTZ MONZONITE/ALTERATION ZONE - Continuation of previous unit with locally 5% manganese mineralization and rare specular hematite stringers which deminish downhole. Vuggy oxidized quartz vein with locally intense limonitic weathering from 82.30-82.55m. Interval is locally faulted and gouged. Lower contact signified by loss of alteration.
		ALTERATION
		« 77.80- 84.20 Sericite 2.00*»
		« 88.00- 92.18 Sericite 2.00*»
		« 77.80- 84.20 Limonite 3.00*»
		MINERALIZATION
		« 77.80- 84.20 Manganite 5.00%»
		« 77.80- 84.20 Specularite 2.00%»
		« 87.50- 92.18 Specularite 2.00%»
		« 91.90- 92.18 Tourmaline 5.00%»
		FAULTS
		< @ 77.80 Fault 50.00° 640.00cm >
		< @ 88.00 Fault 50.00° 418.00cm >
93.02	124.94	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 50% plagioclase, 30% feldspar, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase crystals have feldspar rims. Massive and featurless. Local faulting. Sharp diffuse lower contact with andesite at 65 degrees TCA.
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		< @ 93.43 Fault 55.00° 685.00cm >
		< @ 104.48 Fault 45.00° 30.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
79.80	81.69	1.89	I102296	0.81	1.93	338
81.69	82.69	1.00	I102297	5.09	69.70	1240
82.69	84.20	1.51	I102298	0.10	8.83	936
86.20	88.00	1.80	I102302	0.12	0.51	174
88.00	89.00	1.00	I102303	2.13	1.50	135
89.00	90.40	1.40	I102304	0.01	1.21	85
90.40	91.10	0.70	I102305	0.05	0.69	21
91.10	92.18	1.08	I102306	0.01	0.34	186
92.18	94.18	2.00	I102307	0.01	0.11	10
94.18	96.18	2.00	I102308	0.01	0.21	7
98.18	99.18	1.00	I102311	0.01	0.09	9

Project: ProspectorMtn **Hole Number:** PM10-05


From	To	Rocktype	& Description
			< @ 123.25 Fault 70.00º 50.00cm >
124.94	127.81	Andesite	ANDESITE - Light to medium grey, fine grained, porphyritic andesite dyke. 10% plagioclase phenocrysts and 5% disseminated magnetite. Weakly bleached. Broken lower contact. ALTERATION « Silicification 1.00*» MINERALIZATION « Marcasite 5.00%»
127.81	134.01	Quartz Monzonite	QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 50% plagioclase, 30% feldspar, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase crystals have feldspar rims. Continuation of previous monzonite unit however heavily faulted and gouged. No visible mineralization. Lower contact is within fault gouge. ALTERATION



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
130.26	131.26	1.00	I102312	0.01	0.10	10
131.26	132.50	1.24	I102313	0.01	0.95	11

Project: ProspectorMtn **Hole Number:** PM10-05


From	To	Rocktype & Description
		« 131.26- 134.65 Sericite 2.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		< @ 131.26 Fault Gouge 45.00º 239.00cm >
134.01	140.65	Andesite
		ANDESITE - Light to medium grey, fine grained, porphyritic andesite with 40% plagioclase, 10% feldpsar, and 5% hornblende phenocrysts. 2% disseminated magnetite. Interval begins in a fault gouge from previous unit and is locally blocky and faulted. Weakly bleached. Faulted lower contact at 45 degrees TCA.
		ALTERATION
		« Silicification 1.00*»
		« 139.65- 142.95 Sericite 4.00*»
		MINERALIZATION
		« Marcasite 2.00%»
		FAULTS
		< @ 139.65 Fault Gouge 45.00º 330.00cm >
140.65	158.19	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 50% plagioclase, 30% feldspar, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase crystals have feldspar rims. Locally faulted. Andesite dyke the same as 134.01-140.65 from 156.55-157.50m. EOH
		ALTERATION



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
132.50	134.65	2.15	I102314	0.01	0.67	11
134.65	136.65	2.00	I102315	0.01	0.07	6
136.65	138.04	1.39	I102316	0.01	0.26	10
138.04	139.65	1.61	I102317	0.01	0.17	20
139.65	140.65	1.00	I102318	0.01	0.55	10
142.95	144.95	2.00	I102321	0.01	0.32	10
144.95	145.95	1.00	I102322	0.01	0.12	15

Project: ProspectorMtn **Hole Number:** PM10-05

From	To	Rocktype & Description
		« 157.50- 157.60 Sericite 4.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		< @ 149.05 Fault 45.00° 20.00cm >
		< @ 157.50 Fault Gouge 60.00° 10.00cm >
		DYKES
		« 156.55- 157.50 Porphyritic Andesite Dyke »
158.19	158.19	EOH



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

DRILL LOG

Project: Prospector Mountain	**Collar Elevation (m):** 1836.0
Hole PM10-06	**Azimuth (º):** 80.0
Location: 6927890 m North, 355023 m East	**Dip (º):** -45.0
Logged by: Ryan Toole	**Length (m):** 206.96
Drilled by: Apex	**Horizontal Projection:**
Assayed by: ALS	**Vertical Projection:**
Core Size: NQ	**Objective** Bonanza Zone; middle part
Date Started: 2010/09/17 **Date Completed:** 2010/09/19	
Dip Tests By:	

Summary Log:

0-3.60 CASING

3.60-18.50 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite.

18.50-21.73 QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Pinkish grey, coarse grained monzonite. Continuation of previous unit, however heavily faulted with associated manganese and limonite mineralization. No visible specular hematite stringers.

21.73-31.06 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Massive and featureless with local faulting and gouging in lower 2m.

31.06-40.06 QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Pinkish grey, coarse grained monzonite. Heavily faulted with associated manganese and limonite mineralization and moderate sericite alteration.

40.06-74.31 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. Massive and featureless with local faulting and gouging. Once occurance of tourmaline and specular hematite mineralization from 69.90-70.63m.

74.31-79.70 QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Pinkish grey, coarse grained monzonite. Tourmaline mineralization, earthy hematite mineralization, and specular hematite stringers decrease away from fault zones. Lower contact is signified by loss of alteration.

79.70-134.88 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite.

134.88-137.88 ANDESITE - Light to medium grey, fine grained, porphyritic andesite dyke. 10% coarse grained plagioclase phenocrysts weakly altered to sericite, 5% fine grained hornblende phenocrysts, and 1% disseminated magnetite.

137.88-158.56 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. Vuggy quartz vein with moderate oxidation and highly oxidized specular hematite stringers from 142.80-142.95m.

158.56-162.24 QUARTZ MONZONITE / ALTERATION ZONE - Continuation of previous unit, continued in fault zone, with the addition of 10% tourmaline mineralization, 1% to locally 5% specular hematite stringers and rare disseminations, and weak to moderate sericite alteration.

162.24-167.50 ANDESITE - Light to medium grey, fine grained, porphyritic andesite dyke. 15% coarse grained plagioclase phenocrysts weakly altered to sericite, 5% fine grained hornblende phenocrysts, and 1% disseminated magnetite.

167.50-180.57 QUARTZ MONZONITE / ALTERATION ZONE - Pinkish grey, coarse grained monzonite.


180.57-206.96 QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. EOH.

Downhole surveys:

Depth	Dip	Azimuth
0.00	0.00	0.00
205.00	-45.50	77.30

Project: ProspectorMtn **Hole Number:** PM10-06


From	To	Rocktype & Description
0.00	3.60	Casing
		CASING - Overburden
3.60	18.50	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Blocky and locally faulted and gouged. Plagioclase has weakly been altered to sericite. Two 25 cm andesite dykes with diffuse contacts in lower 6 meters. Faulted lower contact. at 45 degrees TCA.
		ALTERATION
		« Sericite 1.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		DYKES
		« 12.80- 13.05 Andesite Dyke »
		« 14.42- 14.67 Andesite Dyke »
		FAULTS
		< @ 15.60 Fault 35.00° 85.00cm >
18.50	21.73	Quartz Monzonite/Fault Zone
		QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Continuation of previous unit, however heavily faulted with associated manganese and limonite mineralization. No visible specular hematite stringers. Sharp faulted lower contact at 35 degrees TCA.
		ALTERATION
		« 18.50- 18.90 Sericite 1.00*»
		« 19.74- 21.73 Sericite 1.00*»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
14.94	16.94	2.00	I102323	0.01	0.14	19
16.94	18.50	1.56	I102324	0.01	0.25	14
18.50	20.05	1.55	I102325	0.01	0.37	10
20.05	21.73	1.68	I102326	0.04	10.60	259

Project: ProspectorMtn **Hole Number:** PM10-06


From	To	Rocktype & Description
		« 18.50- 18.90 Limonite 1.00*»
		« 19.74- 21.73 Limonite 1.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		« 18.50- 18.90 Manganite 5.00%»
		« 19.74- 21.73 Manganite 5.00%»
		FAULTS
		< @ 18.50 Fault 70.00° 40.00cm >
		< @ 19.74 Fault 35.00° 199.00cm >
21.73	31.06	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Massive and featureless with local faulting and gouging in lower 2m. Faulted and broken lower contact.
		ALTERATION
		« 29.29- 29.60 Sericite 4.00*»
		« 30.18- 31.06 Sericite 2.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		< @ 29.29 Fault Gouge 35.00° 31.00cm >
		< @ 30.18 Fault 45.00° 88.00cm >
31.06	40.06	Quartz Monzonite
		QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Pinkish grey, coarse grained



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
21.73	23.73	2.00	I102327	0.01	0.25	24
23.73	25.73	2.00	I102328	0.01	0.25	16
25.73	27.73	2.00	I102329	0.01	0.24	22
27.73	29.29	1.56	I102331	0.01	0.08	13
29.29	31.06	1.77	I102332	0.01	0.47	7
31.06	33.12	2.06	I102333	0.01	0.84	230
33.12	33.98	0.86	I102334	0.31	0.75	88

Project: ProspectorMtn **Hole Number:** PM10-06


From	To	Rocktype & Description
		quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Continuation of previous unit, however heavily faulted with associated manganese and limonite mineralization and moderate sericite alteration. Alteration deminishes down hole with rare specular hematite stringers and associated tourmaline mineralization. Lower contact signified by loss of specular hematite stringers.
		ALTERATION
		« 31.06- 33.98 Sericite 2.00*»
		« 31.06- 33.98 Limonite 1.00*»
		MINERALIZATION
		« 31.06- 33.12 Manganite 10.00%»
		« 33.12- 33.98 Manganite 25.00%»
		« 37.37- 40.06 Tourmaline 1.00%»
		« 37.37- 40.06 Specularite 0.50%»
		FAULTS
		< @ 31.06 Fault 55.00° 292.00cm >
40.06	74.31	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Massive and featureless with local faulting and gouging. Once occurance of tourmaline and specular hematite mineralization from 69.90-70.63m. Core becomes blockier downhole. Faulted and broken lower contact.
		ALTERATION
		« Sericite 1.00*» (Weakly altered plagioclase)
		MINERALIZATION
		« Marcasite 1.00%»
		« 69.90- 70.63 Tourmaline 15.00%»
		« 69.90- 70.63 Specularite 2.00%»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
33.98	35.98	2.00	I102335	0.01	0.44	24
35.98	37.98	2.00	I102336	0.01	1.10	29
37.98	38.99	1.01	I102337	0.01	0.31	69
38.99	40.06	1.07	I102338	0.01	0.85	54
40.06	40.95	0.89	I102339	0.01	0.32	61
40.95	42.95	2.00	I102341	0.01	0.37	82
42.95	43.95	1.00	I102342	0.01	0.16	14
68.80	69.80	1.00	I102343	0.01	0.17	10
69.80	70.63	0.83	I102344	0.02	0.37	5
70.63	72.63	2.00	I102345	0.01	0.16	7
72.63	74.31	1.68	I102346	0.01	0.16	12

Project: ProspectorMtn **Hole Number:** PM10-06


From	To	Rocktype & Description
		FAULTS
		< @ 40.95 Fault 45.00° 35.00cm >
		< @ 51.51 Fault 80.00° 20.00cm >
		< @ 65.70 Fault 50.00° 50.00cm >
		< @ 70.30 Fault 45.00° 33.00cm >
74.31	79.70	**Quartz Monzonite/Fault Zone**
		QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Continuation of previous unit, however locally faulted with local associated manganese and limonite mineralization and moderate sericite alteration. Tourmaline mineralization, earth hematite mineralization, and specular hematite stringers decrease away from fault zones. Lower contact is signified by loss of alteration.
		ALTERATION
		« Sericite 1.00*»
		« 74.31- 76.54 Sericite 2.00*»
		« 76.75- 78.70 Limonite 3.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		« 74.31- 76.54 Manganite 10.00%»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
74.31	75.20	0.89	I102347	0.01	0.27	10
75.20	75.90	0.70	I102348	0.01	0.22	12
76.75	78.70	1.95	I102351	0.55	3.85	46
78.70	79.70	1.00	I102352	0.01	0.34	176

Project: ProspectorMtn **Hole Number:** PM10-06

From	To	Rocktype & Description
		« 76.54- 76.75 Tourmaline 10.00%»
		« 76.65- 76.75 Specularite 4.00%»
		« 76.65- 76.75 Hematite 5.00%»
		« 78.60- 79.70 Tourmaline 4.00%»
		« 78.60- 79.70 Specularite 1.00%»
		« 78.60- 79.70 Hematite 0.50%»
		FAULTS
		< @ 74.31 Fault 65.00° 223.00cm >
		< @ 76.75 Fault Gouge 65.00° 195.00cm >
79.70	134.88	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Locally faulted and overall moderately blocky. Massive and featureless. Gouged lower contact at 70 degrees TCA with andesite dyke.
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		< @ 100.28 Fault 45.00° 188.00cm > Highly oxidized



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
79.70	81.20	1.50	I102353	0.01	0.15	57
81.20	82.70	1.50	I102354	0.01	0.11	8
82.70	85.30	2.60	I102355	0.01	0.15	10
85.30	87.30	2.00	I102356	0.01	0.09	14
87.30	88.30	1.00	I102357	0.01	0.10	8
99.28	100.28	1.00	I102358	0.01	0.10	7
100.93	101.92	0.99	I102361	0.01	0.54	15
101.92	103.92	2.00	I102362	0.01	0.35	8
103.92	104.92	1.00	I102363	0.01	0.13	6

Project: ProspectorMtn **Hole Number:** PM10-06


From	To	Rocktype & Description
134.88	137.88	Andesite

ANDESITE - Light to medium grey, fine grained, porphyritic andesite dyke. 10% coarse grained plagioclase phenocrysts weakly altered to sericite, 5% fine grained hornblende phenocrysts, and 1% disseminated magnetite. Weakly bleached, blocky, and locally gouged. Faulted lower contact at 57 degrees TCA.

ALTERATION

« Sericite 1.00*»


« Silicification 1.00*»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
134.88	137.88	3.00	1	0.005	0.2	0.0

Project: ProspectorMtn **Hole Number:** PM10-06


From	To	Rocktype & Description
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		< @ 134.88 Fault Gouge 65.00º 5.00cm >
		< @ 137.70 Fault 57.00º 137.88cm >
137.88	158.56	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Vuggy quartz vein with moderate oxidation and highly oxidized specular hematite stringers from 142.80-142.95m. Locally faulted. Faulted lower contact.
		ALTERATION
		« 142.80- 142.95 Silicification 3.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		« 142.80- 142.95 Specularite 2.00%»
		FAULTS
		< @ 154.90 Fault Gouge 60.00º 54.00cm >
		< @ 157.35 Fault 70.00º 260.00cm >
158.56	162.24	Quartz Monzonite/Alteration Zone
		QUARTZ MONZONITE / ALTERATION ZONE - Continuation of previous unit, continued in fault zone, with the addition of 10% tourmaline mineralization, 1% to locally 5% specular hematite stringers and rare disseminations, and weak to moderate sericite alteration. Specular hematite increases to 5% from 160.0-160.15m associated with a 4cm vuggy quartz vein < @ 160.70 ven 50.00º 40.0mm > Tourmaline forms as laths and rarely radiating crystals. Faulted lower contact with underlying andesite dyke at 45 degrees TCA
		ALTERATION



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
141.80	142.80	1.00	I102364	0.01	0.22	13
142.80	142.95	0.15	I102365	0.01	0.87	79
142.95	143.95	1.00	I102366	0.01	0.18	15
153.90	154.90	1.00	I102367	0.01	0.22	4
154.90	155.44	0.54	I102368	0.03	167.00	182
155.44	157.44	2.00	I102369	0.01	0.57	8
157.44	158.56	1.12	I102371	0.01	0.20	9
158.56	160.00	1.44	I102372	0.01	13.50	75
160.00	161.00	1.00	I102373	0.01	0.42	5
161.00	162.24	1.24	I102374	0.01	0.33	6

Project: ProspectorMtn **Hole Number:** PM10-06

From	To	Rocktype & Description
		« Sericite 1.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		« Tourmaline 10.00%»
		« 158.56- 160.00 Specularite 1.00%»
		« 160.00- 160.15 Specularite 5.00%»
		« 160.15- 162.24 Specularite 1.00%»
		FAULTS
		< @ 160.80 Fault 45.00° 999.99cm >
		< @ 170.80 Fault 45.00° 893.00cm > Continues through the next 2 units.
162.24	167.50	ANDESITE
		ANDESITE - Light to medium grey, fine grained, porphyritic andesite dyke. 15% coarse grained plagioclase phenocrysts weakly altered to sericite, 5% fine grained hornblende phenocrysts, and 1% disseminated magnetite. Weakly bleached, blocky, and locally gouged. Faulted lower contact; unable to get orientation.
		ALTERATION
		« Silicification 1.00*»
		« Sericite 1.00*» (altered plagioclase grains)
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		Recorded in previous unit.
167.50	180.57	Quartz Monzonite/Alteration Zone
		QUARTZ MONZONITE / ALTERATION ZONE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Local specular hematite stringers with associated tourmaline mineralization. Local earthy hematite associated



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
162.24	164.24	2.00	I102375	0.01	0.17	10
164.24	167.50	3.26	I102376	0.01	0.15	7
167.50	168.50	1.00	I102377	0.01	0.31	9
168.50	170.00	1.50	I102378	0.01	0.28	12
170.00	171.54	1.54	I102379	0.07	0.18	10
171.54	172.63	1.09	I102381	0.01	1.14	137
172.63	174.00	1.37	I102382	1.44	18.30	3610

Project: ProspectorMtn **Hole Number:** PM10-06

From	To	Rocktype & Description

with fault gouging/clay and malachite mineralization, and also rarely with disseminate specular hematite. Sharp lower contact signified by loss of alteration at 47 degrees TCA.

ALTERATION

« 167.50- 172.96 Sericite 1.00*»

« 174.00- 175.51 Sericite 3.00*»

MINERALIZATION

« 167.50- 170.00 Tourmaline 3.00%»
« 167.50- 170.00 Specularite 2.00%»

« 172.63- 174.00 Hematite 40.00%»
« 173.20- 173.55 Malachite 5.00%»

« 179.53- 180.57 Hematite 3.00%»
« 179.53- 180.57 Specularite 2.00%»

FAULTS

Interval is faulted from top to bottom, however gouged from:

< @ 172.63 Fault Gouge 60.00° 288.00cm >


Sand Seam from 175.51-176.88m.

From	To	Rocktype & Description
180.57	206.96	Quartz Monzonite

QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Rare 5cm xenoliths of andesite with diffuse contacts. Massive and featureless. No alteration or mineralization. EOH.

MINERALIZATION


« Marcasite 1.00%»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
174.00	175.51	1.51	I102383	0.06	1.29	95
175.51	179.53	4.02	I102384	0.03	36.80	102
179.53	180.57	1.04	I102385	0.01	0.76	40
180.57	181.57	1.00	I102386	0.01	0.17	10

Project: ProspectorMtn **Hole Number:** PM10-06

From	To	Rocktype & Description
	206.96	EOH



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

EQUITY

DRILL LOG

Project: Prospector Mountain	**Collar Elevation (m):** 1834.0
Hole PM10-07	**Azimuth (º):** 80.0
Location: 6927993 m North, 355009 m East	**Dip (º):** -45.0
Logged by: Ryan Toole	**Length (m):** 146.00
Drilled by: Apex	**Horizontal Projection:**
Assayed by: ALS	**Vertical Projection:**
Core Size: NQ	**Objective** Bonanza Zone; complete fence across broad part of anomaly with PM10-08
Date Started: 2010/09/19 **Date Completed:** 2010/09/21	
Dip Tests By:	

Summary Log:

0-3.05 CASING

3.05-33.22 QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite.

33.22-39.02 QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Continuation of previous unit however heavily faulted and locally gouged with local tourmaline and manganese mineralization, and strong oxidation. Rare specular hematite disseminations associated with tourmaline mineralization.

39.02-56.88 QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase has weakly been altered to sericite. Local tourmaline mineralization and local gouging. No visible specular hematite.

56.88-65.65 QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Continuation of previous unit however 2-3% highly oxidized specular hematite stringers, heavily faulted with associated intense sericite alteration, local limonite, manganese, and tourmaline mineralization.

65.65-126.99 QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite.

126.99-130.90 ANDESITE - Light to medium grey, fine grained, porphyritic andesite dyke. 10% coarse grained magnetite, 5% plagioclas phenocrysts. Weakly bleached and blocky.

130.90-146.00 QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. EOH

Downhole surveys:

Depth	Dip	Azimuth
73.52	-46.10	80.10
144.30	-45.60	74.10

Project: ProspectorMtn **Hole Number:** PM10-07


From	To	Rocktype & Description
0.00	3.05	Casing
		CASING - Overburden
3.05	33.22	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Upper 8m is blocky with local weak oxidation on fracture planes. Plagioclase has weakly been altered to sericite. Massive and featureless. Faulted lower contact at 45 degrees TCA.
		ALTERATION
		« Sericite 1.00*» (Plagioclase grains)
		MINERALIZATION
		« Marcasite 1.00%»
33.22	39.02	Quartz Monzonite/Fault Zone
		QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Continuation of previous unit however heavily faulted and locally gouged with local tourmaline and manganese mineralization, and strong oxidation. Rare specular hematite disseminations associated with tourmaline mineralization. Faulted lower contact at 45 degrees TCA.



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
32.22	33.22	1.00	I102387	0.01	0.14	8
33.22	33.79	0.57	I102388	0.01	0.29	10
34.79	36.27	1.48	I102391	0.02	1.36	163
36.27	38.02	1.75	I102392	0.16	3.72	148
38.02	38.62	0.60	I102393	0.12	4.09	188
38.62	39.02	0.40	I102394	0.01	0.44	51

Project: ProspectorMtn **Hole Number:** PM10-07

From	To	Rocktype & Description
		ALTERATION
		« 33.22- 39.02 Sericite 3.00%»
		MINERALIZATION
		« 34.00- 38.02 Tourmaline 3.00%»
		« 34.00- 38.02 Specularite 2.00%» (Rare disseminations,no visible stringers)
		« 36.35- 36.60 Manganite 10.00%»
		FAULTS
		< @ 33.22 Fault 45.00° 580.00cm >
39.02	56.88	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase has weakly been altered to sericite. Local tourmaline mineralization and local gouging. No visible specular hematite. Massive and featureless. Faulted lower contact at 50 degrees TCA.
		ALTERATION
		« Sericite 1.00*» (Altered plagioclase grains)
		« 40.22- 40.44 Sericite 4.00*»
		MINERALIZATION
		« 47.45- 48.94 Tourmaline 10.00%»
		« 55.86- 55.91 Tourmaline 10.00%»
		FAULTS
		< @ 40.22 Fault Gouge 50.00° 22.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
39.02	41.02	2.00	I102395	0.01	0.28	33
41.02	42.02	1.00	I102396	0.01	0.16	13
46.45	47.45	1.00	I102397	0.01	0.57	31
47.45	48.45	1.00	I102398	0.01	0.32	28
49.25	50.25	1.00	I102401	0.01	0.24	24
54.86	55.86	1.00	I102402	0.01	0.22	21
55.86	56.02	0.16	I102403	0.01	0.09	29
56.02	57.88	1.86	I102404	0.01	0.35	24

Project: ProspectorMtn **Hole Number:** PM10-07

From	To	Rocktype & Description
56.88	65.65	Quartz Monzonite/Fault Zone

QUARTZ MONZONITE / FAULT ZONE / ALTERATION ZONE - Continuation of previous unit however 2-3% highly oxidized specular hematite stringers, heavily faulted with associated intense sericite alteration, local limonite, manganese, and tourmaline mineralization. Sharp lower contact with loss of alteration.

ALTERATION

« 56.88- 61.06 Sericite 2.00*»

« 61.06- 65.65 Sericite 4.00*»

« 60.86- 60.89 Limonite 3.00*»

MINERALIZATION

« 56.88- 65.65 Specularite 2.00%»

« 63.50- 64.60 Manganite 5.00%»

« 56.88- 61.06 Tourmaline 2.00%»

FAULTS

< @ 56.88 Fault 45.00° 418.00cm >

< @ 61.06 Fault Gouge 45.00° 459.00cm >


From	To	Rocktype & Description
65.65	126.99	Quartz Monzonite

QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase has weakly been altered to sericite. Rare faulting. Massive and featureless. Sharp lower contact with andesite dyke at 45 degrees TCA.

ALTERATION

« Sericite 1.00*» (Plagioclas grains.)


MINERALIZATION



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
57.88	58.88	1.00	I102405	0.04	0.66	20
58.88	59.88	1.00	I102406	0.02	0.90	223
59.88	60.80	0.92	I102407	0.06	0.61	302
60.80	61.80	1.00	I102408	0.10	1.68	573
61.80	62.80	1.00	I102409	0.02	0.37	18
62.80	63.70	0.90	I102411	0.02	3.18	45
63.70	65.65	1.95	I102412	0.28	1.66	22
65.65	66.55	0.90	I102413	0.01	0.32	13
80.72	81.72	1.00	I102414	0.01	0.32	22
81.72	82.72	1.00	I102415	0.01	0.19	10
82.72	83.80	1.08	I102416	0.18	0.35	5
83.80	84.80	1.00	I102417	0.01	0.21	18
84.80	85.80	1.00	I102418	0.01	0.24	22

Project: ProspectorMtn **Hole Number:** PM10-07


From	To	Rocktype & Description
		« Marcasite 1.00%»
		« 82.72- 83.30 Tourmaline 3.00%»
		FAULTS
		< @ 82.72 Fault 43.00° 58.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

Project: ProspectorMtn **Hole Number:** PM10-07


From	To	Rocktype	& Description
126.99	130.90	Andesite	ANDESITE - Light to medium grey, fine grained, porphyritic andesite dyke. 10% coarse grained magnetite, 5% plagioclas phenocrysts. Weakly bleached and blocky. Sharp lower contact at 50 degrees with quartz monzonite. ALTERATION « Silicification 1.00*» MINERALIZATION « Marcasite 10.00%» FAULTS < @ 129.88 Fault 445.00º 179.00cm >
130.90	146.00	Quartz Monzonite	QUARTZ MONZONITE - Pinkish grey, coarse grained quartz monzonite. 40% feldspar, 40% plagioclase, 10% biotite, 5% quartz, 4% hornblende, and 1% disseminated magnetite. Plagioclase has weakly been altered to sericite.Upper 1m is faulted. Massive and featureless. EOH ALTERATION « 130.90- 131.69 Sericite 2.00*» « 131.69- 146.00 Sericite 1.00*» MINERALIZATION



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

Project: ProspectorMtn **Hole Number:** PM10-07

From	To	Rocktype & Description
		« Marcasite 1.00%»
145		
146.00	146.00	EOH



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

EQUITY

DRILL LOG

Project: Prospector Mountain	**Collar Elevation (m):** 1840.0
Hole PM10-08	**Azimuth (º):** 80.0
Location: 6928000 m North, 355074 m East	**Dip (º):** -45.0
Logged by: Ryan Toole	**Length (m):** 127.71
Drilled by: Apex	**Horizontal Projection:**
Assayed by: ALS	**Vertical Projection:**
Core Size: NQ	**Objective** Bonanza Zone; complete fence across broad part of anomaly with PM10-02
Date Started: 2010/09/21 **Date Completed:** 2010/09/24	
Dip Tests By:	

Summary Log:

0-3.05 CASING

3.05-17.53 ANDESITE - Medium grey, fine grained, porphyritic andesite with 10% medium grained plagioclase phenocrysts, moderately altered to sericite, 3% medium grained disseminated magnetite, and 1% coarse grained feldspar phenocrysts.

17.53-64.37 QUARTZ MONZONITE - Pinkish Green, coarse grained, quartz monzonite with 45% feldspar, 35% plagioclase, 10% hornblende, 5% quartz, 4% biotite, and 1% magnetite. Feldspar and plagioclase have locally been weakly to moderately altered to sericite. Locally faulted and blocky with associated limonite and specular hematite mineralization. Rare localized specular hematite stringers. No visible tourmaline mineralization.

64.37-73.49 ANDESITE - Light grey, porphyritic, bleached andesite dyke. 10% subhedral, medium grained, plagioclase phenocrysts, 10% fine to medium grained hornblende phenocrysts, 5% coarse grained feldpar phenocrysts, and 2% medium grained disseminated magnetite. Sharp contacts.

73.49-111.26 QUARTZ MONZONITE - Pinkish Green, coarse grained, quartz monzonite with 45% feldspar, 35% plagioclase, 10% hornblende, 5% quartz, 4% biotite, and 1% magnetite. Locally faulted and gouged with rare oxidation. No visible mineralization associated with faulting.

111.26-112.88 QUARTZ MONZONITE / ALTERATION ZONE - Brecciated, silicified quartz monzonite however primary texture is non existent. Mottled appearance with 3% specular hematite stringers, 5% blotches of magnetite, and 3% blotches of earthy hematite.


112.88-127.71 QUARTZ MONZONITE - Pinkish Green, coarse grained, quartz monzonite with 45% feldspar, 35% plagioclase, 10% hornblende, 5% quartz, 4% biotite, and 1% magnetite. Hole/project was ended due to cold weather freezing waterlines at the drill. EOH

Downhole surveys:

Depth	Dip	Azimuth
63.70	-42.90	73.90
126.00	-40.40	80.80

Project: ProspectorMtn **Hole Number:** PM10-08


From	To	Rocktype & Description
0.00	3.05	Casing
		CASING - Overburden
3.05	17.53	Andesite
		ANDESITE - Medium grey, fine grained, porphyritic andesite with 10% medium grained plagioclase phenocrysts, moderately altered to sericite, 3% medium grained disseminated magnetite, and 1% coarse grained feldspar phenocrysts. Blocky with local weak oxidation on fracture planes. Sharp broken lower contact with underlying quartz monzonite at 45 degrees TCA.
		ALTERATION
		« Sericite 2.00*» (Altered plagioclase grains)
		MINERALIZATION
		« Marcasite 3.00%»
17.53	64.37	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish Green, coarse grained, quartz monzonite with 45% feldspar, 35% plagioclase, 10% hornblende, 5% quartz, 4% biotite, and 1% magnetite. Feldspar and plagioclase have locally been weakly to moderately altered to sericite. Locally faulted and blocky with associated limonite and specular hematite mineralization. Rare localized specular hematite stringers. No visible tourmaline mineralization. Fine to medium grained monzonite dyke with the same composition of host rock from 21.9-23.0m with sharp contacts at 45 degrees TCA. Andesite dyke from 56.36-56.66m with sharp contacts at 50 degrees TCA. Sharp lower contact at 50 degrees TCA.
		ALTERATION
		« Sericite 2.00*»
		« 30.18- 33.70 Limonite 1.00*»
		« 38.80- 39.70 Limonite 1.00*»
		MINERALIZATION
		« Marcasite 1.00%»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
3.05	5.79	2.74	I102419	0.01	0.87	26
5.79	8.84	3.05	I102421	0.01	1.40	57
8.84	11.89	3.05	I102422	0.02	1.42	82
11.89	14.94	3.05	I102423	0.01	0.24	15
14.94	17.53	2.59	I102424	0.01	0.12	14
17.53	21.03	3.50	I102425	0.01	0.14	19
21.03	24.08	3.05	I102426	0.01	0.11	8
24.08	24.30	0.22	I102427	0.01	0.09	4
24.30	27.13	2.83	I102428	0.01	0.10	6
29.40	30.62	1.22	I102431	0.02	0.73	36
30.62	31.95	1.33	I102432	0.01	0.14	10
31.95	33.86	1.91	I102433	0.01	0.67	36
33.86	36.00	2.14	I102434	0.01	0.20	10
36.00	37.17	1.17	I102435	0.01	0.22	10
37.17	39.32	2.15	I102436	0.01	0.72	117
39.32	41.23	1.91	I102437	0.01	0.68	754
41.23	41.70	0.47	I102438	2.58	2.03	1370
43.70	45.70	2.00	I102441	0.01	0.25	57
45.70	47.70	2.00	I102442	0.01	0.26	88
47.70	49.70	2.00	I102443	0.01	0.22	22
49.70	51.70	2.00	I102444	0.01	0.14	12
51.70	53.70	2.00	I102445	0.01	0.29	16
53.70	55.82	2.12	I102446	0.01	0.16	18
55.82	56.18	0.36	I102447	0.01	0.58	90
56.18	57.16	0.98	I102448	0.01	0.25	205
57.16	60.66	3.50	I102449	0.01	0.14	14
60.66	63.70	3.04	I102451	0.01	0.37	51

Project: ProspectorMtn **Hole Number:** PM10-08


From	To	Rocktype & Description
		« 24.08- 24.30 Specularite 1.00%»
		« 29.40- 30.62 Specularite 2.00%»
		« 31.95- 33.86 Specularite 2.00%»
		« 41.23- 41.50 Specularite 10.00%»
		« 41.23- 41.70 Manganite 10.00%»
		FAULTS
		< @ 37.17 Fault 45.00° 453.00cm >
		< @ 56.01 Fault 45.00° 829.00cm >
64.37	73.49	Andesite
		ANDESITE - Light grey, porphyritic, bleached andesite. 10% subhedral, medium grained, plagioclase phenocrysts, 10% fine to medium grained hornblende phenocrysts, 5% coarse grained feldpar phenocrysts, and 2% medium grained disseminated magnetite. Contacts are sharp, diffuse, and not bleached. Bleaching appears 30cm from contacts. Blocky and locally faulted. Sharp lower contact at 27 degrees TCA.
		ALTERATION
		« Silicification 1.00*»
		MINERALIZATION
		« Marcasite 2.00%»



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
63.70	64.37	0.67	I102452	0.01	0.11	21
64.37	66.37	2.00	I102453	0.01	0.08	36
66.37	68.37	2.00	I102454	0.01	0.07	16
68.37	70.37	2.00	I102455	0.01	0.14	37
70.37	72.37	2.00	I102456	0.01	0.08	20
72.37	73.49	1.12	I102457	0.01	0.09	20

Project: ProspectorMtn **Hole Number:** PM10-08

From	To	Rocktype & Description
		FAULTS
		< @ 70.93 Fault 45.00° 7.00cm >
		< @ 72.96 Fault 80.00° 43.00cm >
73.49	111.26	Quartz Monzonite
		QUARTZ MONZONITE - Pinkish Green, coarse grained, quartz monzonite with 45% feldspar, 35% plagioclase, 10% hornblende, 5% quartz, 4% biotite, and 1% magnetite. Locally faulted and gouged with rare oxidation. No visible mineralization associated with faulting. Sharp lower contact at 55 degrees TCA.
		ALTERATION
		« Sericite 1.00*»
		« 73.79- 74.00 Sericite 3.00*»
		« 77.37- 88.86 Sericite 3.00*»
		« 98.34- 99.01 Sericite 2.00*»
		« 100.02- 100.22 Sericite 4.00*»
		« 101.63- 102.33 Sericite 3.00*»
		« 79.64- 80.99 Limonite 2.00*»
		MINERALIZATION
		« Marcasite 1.00%»
		FAULTS
		< @ 73.79 Fault 55.00° 21.00cm >
		< @ 77.37 Fault 45.00° 999.99cm >
		< @ 87.37 Fault 45.00° 149.00cm >
		< @ 98.34 Fault 90.00° 67.00cm >
		< @ 100.02 Fault 55.00° 20.00cm >
		< @ 101.63 Fault 70.00° 60.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
73.49	75.49	2.00	I102458	0.01	0.12	20
75.49	77.37	1.88	I102459	0.02	0.29	30
77.37	78.84	1.47	I102461	0.01	0.14	7
78.84	79.64	0.80	I102462	0.01	7.46	1220
79.64	80.99	1.35	I102463	0.40	3.11	1230
80.99	82.40	1.41	I102464	0.01	0.46	54
82.40	84.40	2.00	I102465	0.01	0.20	19
84.40	85.52	1.12	I102466	0.01	0.10	15
85.52	87.79	2.27	I102467	0.01	0.17	13
87.79	88.86	1.07	I102468	0.01	0.12	8
110.26	111.26	1.00	I102471	0.01	0.09	6

Project: ProspectorMtn **Hole Number:** PM10-08

From	To	Rocktype & Description
111.26	112.88	Quartz Monzonite/Alteration Zone

QUARTZ MONZONITE / ALTERATION ZONE - Brecciated, silicified quartz monzonite however primary texture is non existent. Mottled appearance with 3% specular hematite stringers, 5% blotches of magnetite, and 3% blotches of earthy hematite. Lower 71 cm is faulted and gouged. Possible that this is an altered andesite dyke however no evidence other than a sharp upper contact to support this. Faulted lower contact at 55 degrees TCA.

ALTERATION

« Silicification 4.00*»

MINERALIZATION

« Specularite 3.00%»
« Hematite 3.00%»
« Marcasite 5.00%»

FAULTS

< @ 112.17 Fault 55.00° 71.00cm >
< @ 112.61 Fault Gouge 55.00° 27.00cm >

From	To	Rocktype & Description
112.88	127.71	Quartz Monzonite


QUARTZ MONZONITE - Pinkish Green, coarse grained, quartz monzonite with 45% feldspar, 35% plagioclase, 10% hornblende, 5% quartz, 4% biotite, and 1% magnetite. Locally faulted. Massive and featureless. Hole/project was ended due to cold weather freezing waterlines at the drill. EOH

MINERALIZATION

« Marcasite 1.00%»

FAULTS


< @ 126.25 Fault 55.00° 60.00cm >



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm
111.26	112.17	0.91	I102472	0.01	0.10	13
112.17	112.88	0.71	I102473	0.01	0.20	7
112.88	113.88	1.00	I102474	0.01	0.11	9

Project: ProspectorMtn **Hole Number:** PM10-08

From	To	Rocktype & Description
		< @ 127.40 Fault 12.00º 10.00cm >
127.71	127.71	EOH



From	To	Width	Sample	Au ppm	Ag ppm	Cu ppm

Appendix G: Geophysical Report

FIELD LOGISTICS REPORT

(SQI INTERNAL DOCUMENT)

Covering the Silver Quest Resources Ltd. Geophysics Field Program
June 28, 2010 to July 2, 2010

Prospector Mountain Property
Dawson Range, Yukon Territory

Prepared by: Canterra Minerals Corp.
Author: Francis Moul

Date: January 17, 2011

Table of Contents

1.0 Introduction 4

2.0 Background 5

3.0 Ground Magnetic Survey 5

3.1 Personnel 5

3. 2 Survey Area 6

3.3 Survey Time and Line Kilometers 6

3.4 Description of Survey Method 7

3.5 Planning 8

3.6 Logistics 8

3.7 Instrumentation 9

3.8 Acquisition Parameters 10

3.9 Data processing 10

4.0 Results 11

4.1 Interpretation 11

5.0 Recommendations 12

List of Appendices

Appendix A: Property and Survey Location Maps
Appendix B: Plots of Ground Magnetic Data with Claim Boundaries
Appendix C: Interpretation
Appendix D: Survey Information File
Appendix E: Digital Data

1.0 Introduction

This report summarizes the Silver Quest Resources Ltd. (“Silver Quest”) ground geophysics program undertaken on the Prospector Mountain Property (“Prospector Mountain) between June 28th and July 2nd, 2010.

The objective of the program was to create a geophysical base layer using the ground magnetic method prior to drilling. The ground magnetic program occurred concurrently with a soil and rock geochemical sampling and geological mapping program. The ground magnetic data was used to identify lineaments in the area of interest and assist in the selection of drill collar locations.

At the conclusion of the survey a single grid totaling 27.9 line kilometers (“lkm”) had been completed.

2.0 Background

The survey areas are in the immediate vicinity of the Prospector Mountain "Bonanza Zone" gold showing. The survey area was located in the south east of the property and represents a small portion of the total property area. Prospector Mountain is located approximately 90 km northwest of Carmacks, YT. The fly camp at Prospector Mountain was serviced by helicopter based at the Boulevard camp located approximately 90 km to the north-west. A location map showing the property boundaries, claims and camp locations is included (Appendix A – Figure 1).

A portion of the survey area was previously covered with an IP grid. There is no other known high resolution airborne or ground geophysics conducted in the survey area. The survey area was selected based on the estimated extent of the "Bonanza Zone" and the area of interest for drilling (Appendix A - Figure 2).

3.0 Ground Magnetic Survey

3.1 Personnel

The data were acquired by employees of Equity Exploration Consultants Ltd. ("Equity"). The program was planned by Francis Moul of Canterra Minerals Corp. ("Canterra") in the Silver Quest Boulevard camp. The program was managed by Darcy Baker of Equity in the base of operations at the Prospector Mountain fly camp. The ground magnetic data were quality reviewed, processed and preliminary interpreted by Francis Moul at the Canterra office in Vancouver, BC.

The survey data and interpretation are presented in the appendices. A list of personnel is located in Table 1.

Table 1 - Personnel List

Crew	Company	Location	Title
Francis Moul	Canterra Minerals Corp.	Field / Vancouver	Geophysicist
Darcy Baker	Equity Exploration Consultants Ltd.	Field	Field Program Manager, President
Sean Suttie	Equity Exploration Consultants Ltd.	Field	Equipment Operator, Sr. Sampler
Will James	Equity Exploration Consultants Ltd.	Field	Equipment Operator, Sampler

Equity Exploration Consultants Ltd. are located at 200-900 West Hastings St., Vancouver, BC (www.equityexploration.com).

3. 2 Survey Area

One survey grid was completed during the period between June 28, 2010 and July 2, 2010. The coordinates of a polygon defining the survey area in WGS-84 UTM Zone 8N are presented in Table 2.

Table 2 - Block Coordinates

Easting (m)	Northing (m)
354258	6928419
354248	6927503
353992	6927510
353995	6926598
355605	6926598
355605	6927591
355564	6927712
355564	6928419

3.3 Survey Time and Line Kilometers

Assuming an 8 hour survey day a total of 32 person-hours were required to complete the grid. A summary log is presented in Table 3.

Table 3 Summary Survey Log

Date	Survey Day	Personnel	Task
June 28, 2010	1	Will James	Survey
June 29, 2010	2	Will James	Survey
July 2, 2010	3	Will James, Sean Suttie	Survey

The total number of line kilometers completed on each claim are presented in Table 4 below. The claim boundaries are accurate as of August 18, 2010.

Table 4 Line Length Surveyed in each Claim Area

Grant Number	Line Length (km)	Fraction of Total Line Length (%)
YB97166	0.98	0.034
YB97164	1.81	0.063
YB97165	1.09	0.038
YB97210	0.12	0.004
YB97209	0.20	0.007
YB97163	2.08	0.073
YB97162	2.05	0.072
YB66223	1.35	0.047
YB66221	2.15	0.075
YB66220	1.51	0.053
YB66205	0.03	0.001
YB66203	0.77	0.027
YB97143	0.15	0.005
YB97150	1.21	0.042
YB97149	0.38	0.013
YB97156	0.70	0.024
YB97158	1.90	0.066
YB97151	2.05	0.072
YB66219	2.10	0.073
YB97159	0.33	0.012
YB97161	1.55	0.054
YB97160	2.00	0.070
YB66218	2.13	0.074
Totals	28.6	1.000

The approximate corners of the survey are presented in the table below. All coordinates are in the WGS84 datum UTM zone 8 North.

3.4 Description of Survey Method

The ground magnetic survey method allows definition of near surface variations in the magnetic field due to the presence of materials with contrasting magnetic susceptibility and remnant magnetization. In magnetically complicated environments the ground magnetic method offers improved near surface resolution relative to airborne magnetic methods.

A ground magnetic survey is typically conducted along a series of parallel traverse lines of a constant orientation. The line separation is smaller than employed in airborne surveys; typical line seperations are 25 m to 100 m. Station spacings vary from less than a metre in “walking mode” surveys to typically 12.5 m or 25 m spacings in “station mode” surveys.

The survey method requires a minimum of two magnetometers; one of which is employed as a static monitor of the total magnetic field intensity while the other is moved across the survey area in a regular manner. The difference between the value of the total magnetic field intensity at the rover (moving magnetometer) and the base (static magnetometer) is a record of the spatial variations of the magnetic field over the survey area. Typically the resulting data are gridded to provide a continuous surface representing the variation in the magnetic field. Generally, areas of relatively high total magnetic field intensity correlate with rocks of relatively high magnetic susceptibility and areas of relatively low total magnetic field intensity correlate with rocks or overburden of relatively low magnetic susceptibility. Magnetic susceptibility is directly related to the approximate proportion of magnetite and pyrhotite and to a limited extent other minerals present in the sample.

Areas of alternation correlating to intrusions or mineralising hydrothermal fluids are commonly defined by regions of magnetite destruction or regions of sulphide mineral accumulation.

3.5 Planning

The ground survey grids were initially planned using the orientation and extent of the “Bonanza Zone” to define the grid limits. Survey traverse line orientation was east-west and approximately perpendicular to the estimated strike of the target. Plan maps showing the topographic contours and survey lines were created and distributed to the survey crew prior to commencing operations. The plan was modified by the field crew after visit to the survey site and only the central portion of the survey block was completed. In the southern half of the survey block the lines were extended approximately 0.3 km west of the initial line terminus.

3.6 Logistics

Data was acquired over only a subset of the survey lines located approximately at the centre of the grid. A geological mapping and sampling program was undertaken at the same time as the magnetic survey in the same area of interest.

There were no internet communications available at the fly camp. Modifications of the survey plan were completed independently by the field crew. Data qualitity control and processing were not undertaken until the crew returned to the Boulevard Project camp and the data were transmitted to the Canterra office in Vancouver.

Several consecutive survey lines appear to have been acquired using the same instrument in the same line direction. A possible conclusion is that the helicopter was used to transport the operator and equipment from the end of line to the beginning of line. Presumably this would have been done only if there was an overriding safety or logistical concern requiring lines to be completed in the same direction.

The basic survey information metadata (the "survey information file") are presented in Appendix D.

3.7 Instrumentation

Three magnetometers were operated simultaneously at times throughout the survey period. All three of the magnetometers were property of Canterra. The details of the instruments used are presented in Table 5.

Table 5 Instrumentation

Magnetometer Type	Serial Number	Owner
GSM-19W v7.0 Overhauser	7052314	Canterra
GSM-19W v7.0 Overhauser	7052316	Canterra
GSM-19TG v5.0 Proton Precession	705699	Canterra

Throughout the survey, one or two GSM-19W magnetometers were used as rovers and the GSM-19TG magnetometer was employed as a static base station. Typically, the base station is deployed as close as possible to the active survey grid however the location of the base station was not recorded in this case. The base station was used as the primary source for magnetic differential correction.

The GSM-19W magnetometer were equipped with a GPS and real-time DGPS receiver allowing both accurate positioning and instrument clock synchronization. The Canada-wide DGPS service (CDGPS) broadcast was used for differential positioning; it is transmitted on L-band frequencies from the MSAT-1 communications satellite. The manufacturer quoted accuracy of the GPS receiver is less than 1 m.

The sensor on each GSM-19W instrument is a scalar magnetometer capable of measuring the earth's total magnetic field intensity. The Overhauser version allows sample rates down to 0.2 s with an absolute accuracy of +/- 0.1 nT. The manufacturer stated range of operating temperature is between -40ºC and +55ºC. The entire assembly weighs approximately 3 kg.

The GSM-19TG magnetometer was not equipped with a GPS reciever. Instrument internal clock synchronisation was accomplished by establishing link to one of the GPS

enabled GSM-19W magnetometers at the beginning of each the survey day using a data cable.

When the local ground station data were not available the total field data were used from the USGS operated Sitka magnetic station (SIT) located at located at 57.1 deg. N, 224.7 deg. W. The data were downloaded from INTERMAGNET (www.intermagnet.org) at a 1 sample per minute rate.

3.8 Acquisition Parameters

The traverse lines were separated by nominal 100 m spacing and oriented east-west.

The survey position data were collected in WGS-84 UTM 8N coordinates. Sample locations were recovered using real-time differentially corrected GPS sampling at two Hertz.

The magnetic data on the rovers were collected at a continuous two Hertz sample rate while the magnetic data on the base were collected at a continuous 0.33 Hertz sample rate (one sample each three seconds). The rover data were collected in "walking mode" where time, magnetic field and position values are continuously recorded while the base station data were recorded in "base mode" where only the time and magnetic field data are continuously recorded. The raw and processed data are included on DVD in Appendix E along with documentation of the digital file formats.

3.9 Data processing

The data were recorded to the GSM-19 data loggers in real-time and downloaded to a laptop computer at the end of each day. Basic data processing and quality control procedures were conducted at the end of the survey after the crew returned to the Bouldevard camp and were able to send the data archives to the Canterra office in Vancouver where final data processing and plotting was conducted. The data processing flow included the following steps:

1. Downloading of data from rover and base GSM-19W to laptop using Hyperterminal
2. Import of ASCII data files to Geosoft
3. Set coordinate datum to WGS-84 UTM 8N
4. Split rover data into lines named by nearest easting or northing
5. Review rover data for magnetic and position noise
6. Edit or apply non-linear filter to remove magnetic noise
7. Edit to remove bad position data
8. Review base data for diurnal variation and magnetic noise
9. Edit or apply non-linear filter to remove magnetic noise
10. Merge base and rover data

11. Calculate diurnal corrected channel (datum 0 nT, mean value at local base station during survey period was 56960 nT)
12. Trim survey lines to remove overlap
13. Deselect duplicate lines and copy essential channels to final database
14. Grid diurnally corrected magnetic data
15. Trim grids to survey block polygon
16. Determine total line kilometers from straight line path between start and end points of each line.

The base station failed on June 29, 2010 and July 2, 2010 for unknown reasons. Drop-outs in the signal approximately 12 minutes prior to failure on June 29, 2010 are consistent with local spherics (lightning) which may have resulted in the sensor tuning failure due to high magnetic field gradients. Data from the USGS Sitka (SIT) static magnetic monitoring station were used for diurnal correction when the local base station was not functioning. A datum shift was applied to the SIT data on each day so that the first value used was equal to the last good value from the local ground station.

4.0 Results

A single survey grid consisting of 27.9 lkm was completed in three survey days. Plan view maps of the resulting grids (total magnetic intensity, high-pass filtered total magnetic intensity, low-pass filtered total magnetic intensity profiles, digital terrain model and line path with satellite image) are presented in Appendix B – Figures 1 to 4.

4.1 Interpretation

The results of the interpretation are presented in figures 1 and 2 included in Appendix C.

There are areas of isolated magnetic total field intensity highs in the south-west (A) and north-east (B) portions of the grid. These appear to be anomalous responses independent of topography and likely related to increased susceptibility in the bedrock. Generally, in this survey area, the total field intensity is directly related to elevation on this grid. Possibly this is due an increase in overburden thickness due to debris on the slopes.

Lineaments were defined based on similar features identified on adjacent profiles. These lineaments are bias strongly along orientations close to perpendicular to the survey lines. These lineaments may be related to contacts, structural deformation or alteration in the bedrock. The lineaments trend between approximately 342 deg. and 20 deg. and are separated into two sets based on whether they conform to the topography or not.

In general, lineaments were better defined (due to high amplitudes) in topographically high portions of the grid. Those features which are traced across multiple lines and cross elevation contours while remaining well resolved are likely the result of structural or geologic boundaries. In some cases, there are clear lineaments at changes in slope which may correspond to exposed bedrock.

5.0 Recommendations

It is recommended that two base stations be operated whenever possible to mitigate the risk of base station malfunction as it is typically only monitored at the start and end of the day.

The survey area should be expanded to the north and south as the small size of the grid limits ability to recognise the subtle magnetic features on the scale of the hypothesised mineralized “Bonanza Zone”.


A review should be undertaken of the historic IP data where it overlaps the magnetic survey area on the south-west.

Appendix A:


Property and Survey Location Maps

List of Figures:

Figure 1 – Property Location
Figure 2 – Survey Locations



Appendix A - Figure 1



Appendix A - Figure 2

2010 Ground Magnetic TF Survey Area

Prospector Mountain Claims


Silver Quest Resources Ltd.
Prospector Mountain Project, YT **2010 Exploration Program** **Ground Total Magnetic Intensity Survey**
Survey Location
F.Moul, October 8, 2010

Appendix B:

Plots of Ground Magnetic Data with Claim Boundaries

List of Figures:

Figure 1 – Total Magnetic Intensity with Claim Boundaries
Figure 2 – High Pass Filtered Total Magnetic Intensity
Figure 3 – Digital Terrain Model with Elevation Contours
Figure 4 – Survey Line Path with Satellite Image



58609
58410
58241
58146
58092
58047
57999
57961
57925
57896
57868
57844
57820
57799
57780
57761
57741
57722
57702
57685
57669
57655
57638
57619
57601
57581
57564
57546
57522
57495
57465
57425
57382
57331
57280
57217
57148
57047

TMI
(nT)

Project

Company: Silver Quest Resources Ltd.
Project: Prospector Mountain
Location:Approx. 90 km NW of Carmacks, YT

Survey

Method: Total Field Magnetic Field
Rover Instruments: GSM-19W v7 CDGPS Walking Magnetometer
Base Instrument: GSM-19TG v5 Magnetic Gradiometer (base)
Survey Dates: June 28, 2010 - July 2, 2010
Orientation: 90 deg. / 270 deg.
Line Spacing: 100 m
Line Length: 27.9 lkm

Processing

Magnetic Data: Manual Despiking, Diurnal Correction
Position Data: Non-linear filter despiking, Running Mean

Grid

Cell Size: 20 m
Filters: None

Map

Contour Intervals: 100, 500, 2000 nT

Scale 1:15000

250 0 250

(meters)

WGS 84 / UTM zone 8N


Appendix B - Figure 1

Silver Quest Resources Ltd.

Prospector Mountain Project, YT
2010 Exploration Program
Ground Total Magnetic Intensity Survey

Total Magnetic Intensity

F.Moul, July 14, 2010




Appendix B - Figure 2


Silver Quest Resources Ltd.

Prospector Mountain Project, YT
2010 Exploration Program
Ground Total Magnetic Intensity Survey

Partial Vertical Derivative of Total Magnetic Intensity (Order 0.75)

F.Moul, July 14, 2010





Project

Company: Silver Quest Resources Ltd.
Project: Prospector Mountain
Location:Approx. 90 km NW of Carmacks, YT

Survey

Method: Total Field Magnetic Field
Rover Instruments: GSM-19W v7 CDGPS Walking Magnetometer
Base Instrument: GSM-19TG v5 Magnetic Gradiometer (base)
Survey Dates: June 28, 2010 - July 2, 2010
Orientation: 90 deg. / 270 deg.
Line Spacing: 100 m
Line Length: 27.9 lkm

Processing

Magnetic Data: Manual Despiking, Diurnal Correction
Position Data: Non-linear filter despiking, Running Mean


Grid

Cell Size: 20 m
Filters: None

Map

Contour intervals: 20, 100, 500 m






Appendix B - Figure 3

Silver Quest Resources Ltd.

Prospector Mountain Project, YT
2010 Exploration Program
Ground Total Magnetic Intensity Survey

Digital Terrain Model

F.Moul, July 14, 2010



Project

Company: Silver Quest Resources Ltd.
Project: Prospector Mountain
Location:Approx. 90 km NW of Carmacks, YT

Survey

Method: Total Field Magnetic Field
Rover Instruments: GSM-19W v7 CDGPS Walking Magnetometer
Base Instrument: GSM-19TG v5 Magnetic Gradiometer (base)
Survey Dates: June 28, 2010 - July 2, 2010
Orientation: 90 deg. / 270 deg.
Line Spacing: 100 m
Line Length: 27.9 lkm

Processing

Magnetic Data: Manual Despiking, Diurnal Correction
Position Data: Non-linear filter despiking, Running Mean

Grid

Cell Size: 20 m
Filters: Upward Continuation 10 m, Partial Vert. Derivative (Order = 0.75)

Map

Background is Worldview 0.5 m panchromatic Satellite Image

Scale 1:15000

250 0 250

(meters)

WGS 84 / UTM zone 8N

Appendix B - Figure 4


Silver Quest Resources Ltd.
Prospector Mountain Project, YT **2010 Exploration Program** **Ground Total Magnetic Intensity Survey**
Line Path
F.Moul, July 14, 2010

Appendix C:

Interpration

List of Figures:

Figure 1 – Total Magnetic Intensity Lineaments
Figure 2 – Total Magnetic Intensity Anomalous Highs



Project

Company: Silver Quest Resources Ltd.
Project: Prospector Mountain
Location:Approx. 90 km NW of Carmacks, YT

Survey

Method: Total Field Magnetic Field
Rover Instruments: GSM-19W v7 CDGPS Walking Magnetometer
Base Instrument: GSM-19TG v5 Magnetic Gradiometer (base)
Survey Dates: June 28, 2010 - July 2, 2010
Orientation: 90 deg. / 270 deg.
Line Spacing: 100 m
Line Length: 27.9 lkm

Processing

Magnetic Data: Manual Despiking, Diurnal Correction
Position Data: Non-linear filter despiking, Running Mean

Grid

Cell Size: 20 m
Filters: Upward Continuation 10 m, Partial Vert. Derivative (Order = 0.75)

Map

Contour Intervals: 2, 5, 20 nT/m

TMI High Lineament (Doesn't Conform to Topography)
TMI Low Lineament (Doesn't Conform to Topography)
TMI High Lineament (Conforms to Topography)
Anomalous Region of high TMI

Scale 1:15000

250 0 250

(meters)

WGS 84 / UTM zone 8N


Appendix C - Figure 1

Silver Quest Resources Ltd.

Prospector Mountain Project, YT
2010 Exploration Program
Ground Total Magnetic Intensity Survey

LPF TMI Profiles with Interpreted Lineaments

F.Moul, Oct. 8, 2010



Appendix C - Figure 2

Silver Quest Resources Ltd.
Prospector Mountain Project, YT **2010 Exploration Program** **Ground Total Magnetic Intensity Survey**
LPF TMI Profiles with Interpreted Lineaments
F.Moul, Oct. 8, 2010

Appendix D:

Survey Information File

Company: Silver Quest Resources Ltd.
Project: Prospector Mountain Property
Location: 90 km northwest of Carmacks, YT

Survey Type: Total Field Magnetics using GEM Magnetometers

Instruments:

7052314 GSM-19W v7 CDGPS Walking Magnetometer - rover, unit #1
7052316 GSM-19W v7 CDGPS Walking Magnetometer - rover, unit #3
705699 GSM-19TG v5 Magnetic Gradiometer - base, unit #4

Data rate set at 2 Hz on rover magnetometers and 0.33 Hz (1 sample/3 sec) on the base station.

Survey Dates: June 28th - July 2nd

Personnel:

Sean Suttie July 2 (Equity Exploration)
Will James June 28 - July 2 (Equity Exploration)

June 28 1 WJ Survey
June 29 2 WJ Survey Base station failed at 00:51:23 UTC - reason unknown. Drop-outs at approximately 00:38:37 UTC possibly lightning.
July 2 3 WJ,SS Survey Base station failed at 21:00:47 UTC - reason unknown.

Access to the site was by short helicopter flight from fly camp. Main camp was at Boulevard property. There were no internet communications at the fly camp.

Data deliveries: July 3, 2010

Total trimmed distance is 27.9 lkm.

Appendix E:

Digital Data

DVD archive including .pdf maps, packed Geosoft maps, Geosoft data files

Appendix H: Quality Control / Quality Assurance

1.0 QUALITY ASSURANCE / QUALITY CONTROL

1.1 Chain of Custody

Drill core samples were packed into rice sacks and sealed with uniquely-numbered straps to deter and identify evidence of tampering. Rice sacks were shipped via Small's Expediting to the ALS Laboratory Group (ALS) preparation lab in Whitehorse, YT which has been certified compliant with ISO9001:2008 requirements.

1.2 Blanks

Blanks are samples which are known to be barren of mineralization or are from locally derived material lacking obvious alteration of mineralization. Blanks are inserted into the sample stream in the field to determine whether contamination has occurred after sample collection. A total of 12 blanks were inserted into the sample sequence (approximately every 40th sample) and submitted for analysis. For the Prospector Mountain drilling program the blank material was collected from unweathered and unaltered boulders of Prospector Mountain suite quartz monzonite located near the 2010 drill camp.

Review of the analytical results from the blanks samples indicates that all blank samples in the drill core sample stream returned uniformly low values in all elements of interest with two exceptions (see table below). Blank sample I102100 returned an acceptable value of 6 ppb Au, but with values of Ag, As, Bi, Cu, Pb, Sb elevated from background and blank sample I102300 returned Ag and Cu values elevated from background.

Sample	Ag_ppm	As_ppm	Au_ppm	Bi_ppm	Cu_ppm	Pb_ppm	Sb_ppm	Zn_ppm
I102020	0.05	4.5	-0.005	0.30	2.7	19.9	0.39	34
I102060	0.08	5.3	-0.005	0.30	3.1	20.4	0.41	34
I102100	**0.50**	**31.9**	0.006	**5.77**	**132.5**	**53.6**	**5.71**	**75**
I102140	0.08	5.5	-0.005	0.35	4.4	22.4	0.51	35
I102180	0.08	4.9	-0.005	0.32	3.3	21.2	0.39	36
I102220	0.07	6.7	-0.005	0.37	3.5	23.1	0.51	40
I102260	0.08	5.0	-0.005	0.30	3.7	20.6	0.39	31
I102300	**0.19**	5.9	-0.005	0.72	**14.5**	25.3	0.68	40
I102340	0.07	6.6	-0.005	0.40	5.7	21.6	0.47	35
I102380	0.06	5.0	-0.005	0.28	3.0	19.5	0.42	35
I102420	0.10	5.9	-0.005	0.30	3.9	20.7	0.39	34
I102460	0.08	6.2	-0.005	0.37	3.8	21.9	0.44	37

1.3 Analytical Accuracy: Standard Performance

Standard reference materials are inserted into the sample stream to gauge the accuracy of the lab's analyses. Two standards were used in the course of the 2010 Prospector Mountain drilling program: Au standard PM921 and Cu-Ag-Au-Mo standard Cu137 both from WCM Minerals in Burnaby BC. The means and standard deviations established during round robin standard certification are used for calculating warning and control limits. Warning limits are set at the mean ±2 standard deviations (σ) and control limits are set at ±3σ. Any single standard beyond the upper and lower control limits is deemed a failure and consecutive standards on the same certificate exceeding the warning limits are also deemed failures.

Shewhart charts which plot concentration versus sample sequence with warning and control limits are presented below. By plotting the z-score, multiple standards can be displayed for each element; the z-score levels the mean and standard deviation for each standard so that warning limits are indicated by a z-score of ±2σ and control limits are indicated by a z-score of ±3σ. The Shewhart chart for Au standards (Figure 1) - the

main element of interest at Prospector Mountain - indicates that all samples were within the control limits with only one sample exceeding the warning limits.




Figure 1: Shewhart Chart for Au indicating all standard reference materials in the core sample stream. Warning limits are at a z-score of ±2σ and failure limits are at a z-score of ±3σ.

Also of lesser interest at Prospector Mountain is Cu and the performance of the Cu standards is illustrated below. Note that, strictly speaking four of the five Cu standards failed, each returning values higher than expected. However, review of ALS Chemex's internal standards indicates a consistent high bias in their Cu standards averaging at about two standard deviations, or the warning limit (Figure 3). This high bias in Cu would also affect the standards submitted in the field. However, due to the high bias in the ALS Chemex internal standards, just the sample with a z-score of 6.42 is deemed a failure (I102250) and the digest run containing this sample should be re-assayed for Cu if it were an element of interest rather than a pathfinder element at the Prospector Mountain Project. No action has been taken, but reanalysis of all samples for Cu would be recommended if Cu were an element of potentially economic interest, rather than a pathfinder element,




Figure 2: Shewhart Chart for Cu indicating all standard reference materials in the core sample stream. Warning limits are at a z-score of ±2σ and failure limits are at a z-score of ±3σ.




Figure 3: Chart downloaded from ALS Global's webtrieve system showing the performance of an internal standard for Cu. Many results during September and early October are higher than the upper acceptable limit consistent with the performance of Cu137.

1.4 Analytical Precision: Duplicate Analysis

Field duplicates analysis is collection and analysis of two separate samples from the same field location. In the case of core samples, the split half of the core was quartered and both quarter samples were submitted as field duplicates. These field duplicates are used to measure the reproducibility of sampling, which includes both laboratory variation and sample variation. The duplicate-pairs will contain all the cumulative error associated with the sampling and analytical process and may also allow the determination of true, or effective, detection limits (where the cumulative uncertainty of sampling and analytical techniques, or precision, equals 100%). A total of 12 field duplicate-pairs (approximately every 40th sample was a field duplicate) were inserted into the sample sequence and submitted for analysis. In addition, a total of 9 preparation duplicate-pairs were submitted for analysis by requesting that the prep lab prepare a second pulp from the same reject.

Generally speaking, acceptable levels of precision for base metals in field duplicates of drill core would be 90% of samples having a precision better than 30%. One could expect poorer precision for precious metals, particularly Au, with 90% of samples achieving better than 40% precision. In respect of prep duplicates acceptable levels of precision for base metals and precious would be 90% of samples with better than 20% and 30% precision, respectively. The main elements of interest at the Prospector Mountain Project are Au and Cu which both exhibit acceptable reproducibility or precision in field duplicates, as illustrated in Figure 4 below. Pathfinder elements Ag, As, Bi and Sb also show acceptable reproducibility.




Figure 4: Graph illustrating Thompson and Howarth estimation of analytical precision, method two. The data points represent duplicate pairs, the solid line represents the 90th percentile of the population, and the dashed line the 99th percentile of the population (n=12 duplicate pairs). In this instance, the precision was set at 30%, and at this level within the given dataset, 1 sample falling above the 90th percentile line, and 1 sample falling above the 99th percentile line. From the binomial probability it can be read that the probability of 1 samples falling above the 90th percentile is 71.8%.

Due to the limited number of preparation duplicate-pairs, the precision of the preparation duplicates is presented in scatter plots below. Preparation duplicates for Cu plot about the 45° line which represents perfect reproducibility. Gold preparation duplicates also show good reproducibility, however these points are clustered very near the detection limit and represent samples that primarily fell at or below the detection limit. The other pathfinder elements at Prospector Mountain, As, Bi, Sb and Ag also exhibit good reproducibility, although one preparation duplicate-pair outlier negatively impacts Ag and Sb.




Figure 5: Scatter plot illustrating Cu in preparation duplicate-pairs. A line with a slope of 1.0 represents perfect reproducibility.




Figure 6: Scatter plot illustrating As in preparation duplicate-pairs. A line with a slope of 1.0 represents perfect reproducibility.

1.5 Conclusions

- There is no evidence of tampering with the samples between collection and the laboratory.
- All blank samples returned values at or below detection limits for all elements of interest.
- All Au standards fell within control limits with a very slight high bias. A consistent high bias was noted in the Cu standards which is also noted in the laboratory's internal standards. Given that the Bonanza Zone is a gold-only prospect, re-analysis of the affected digest runs is not warranted.
- Field and preparation duplicate analysis of core samples indicates that the dataset shows good levels of precision and reproducibility for Au, Cu and pathfinder elements As, Bi, Sb and Ag in both field and prep duplicates.

Appendix I: Digital Data

Appendix J: Geologist’s Certificate

GEOLOGIST'S CERTIFICATE

Darcy E.L. Baker
Suite 114 – 2635 Prince Edward Street,
Vancouver, BC, Canada

I, Darcy Baker, P.Geo. do hereby certify that:

- I am a Geologist and President of Equity Exploration Consultants Ltd., with offices at Suite 200–900 West Hastings Street in the City of Vancouver, B.C., in the Province of British Columbia.
- I am a member in good standing (#33,448) of the Association of Professional Engineers and Geoscientists of British Columbia.
- I am a graduate of Dalhousie University (1997) with an Honours Bachelor of Science degree in Geology, and am a graduate of the University of Newcastle, Australia (2003) with a Doctor of Philosophy degree in Geology, and I have practiced my profession continuously since 1997.
- Since 1997 I have been involved in mineral exploration for gold, silver, copper, uranium, molybdenum, lead and zinc across Canada and in Alaska, Nevada and Australia.
- I am a Consulting Geologist and principal of Equity Exploration Consultants Ltd. (a geological consulting and contracting firm) and have been so since May 2003.
- I managed the Yukon field exploration campaigns for Silver Quest during 2010 including mapping at Prospector Mountain and managing the follow-up drilling programme.
- I am independent of Silver Quest.

Dated at Vancouver, British Columbia, this 18th day of January, 2011.

_____

Darcy Baker, Ph.D., P.Geo.

Prospector Mountain Suite Quartz Monzonite

Carmacks Volcanic Suite Andesite

MONZ

ANDS

qtz-hem-tour

PM10-01

PM10-02

PM10-03

PM10-04

PM10-05

PM10-06

PM10-07

PM10-08

6,928,500 mN

6,927,500 mN

6,926,500 mN

354,500 mE

355,500 mE

Newt Creek

Cat Trail

Star Creek

Crescent Creek

Prospector Mountain

2010 Drill Camp

80

88

84

Soil Anomalies

1:10,000

Soil Anomalies

> 90th percentile


- Gold
- Bismuth
- Copper
- Nickel
- Arsenic
- Rock Sample > 5 ppm Gold
- 2010 Drill Hole
- Interpreted Structures

MAP AREA 1:5,000

PROSPECTOR MTN CLAIM OUTLINE

1:150,000

Ground Magnetic Total Magnetic Intensity



1:15,000

- Interpreted Fault/Vein/Dyke

Total Magnetic Intensity
(does not conform topography)

- TM High Lineament
- TM Low Lineament

Total Magnetic Intensity
(conforms to topography)

- TM High Lineament

Suboutcrop Lithology

- Andesite
- Quartz Monzonite
- Quartz-Hematite-Tourmaline veins
- Rock Sample > 5 ppm Gold
- Historic DDH
- DDH trace
- Cat trail
- 2010 DDH
- Interpreted Structures
- 84 Vein

200m

Silver Quest Resources Ltd.

Prospector Mountain Project


Bonanza Zone
Compilation Map

EQUITY


Date:	January 2011	Scale:	1:5,000
U.T.M. Zone	UTM 8 - NAD83	Mining District	Whitehorse
N.T.S.	115I/05	Province	Yukon

Figure 4


SAMPLE LOCATIONS




GOLD




BISMUTH




COPPER



NICKEL



ARSENIC



Silver Quest Resources Ltd.

Prospector Mountain Project

Bonanza Zone

Soil and Rock Geochemistry

EQUITY

Date	January 2011	Scale	1:5,000
Mining Division	Whitehorse	Figure	5
NTS	115I/05	Province	Yukon

UTM 8 - NAD83