Aldrin Resource Corporation

2010 GEOLOGICAL, GEOCHEMICAL AND DIAMOND DRILLING REPORT ON THE KEYSTONE PROJECT

Volume I
Text, Appendices A – F

Located in the Mayo Lake Area
Mayo Mining District
NTS 105M/14
63°50’ N Latitude; 135°15’ W Longitude

-prepared for-

ALDRIN RESOURCE CORPORATION
Suite 2020-401 West Georgia Street
Vancouver, British Columbia, Canada, V6B 5A1

-prepared by-

David Swanton, M.Sc.
EQUITY EXPLORATION CONSULTANTS LTD.
Suite 200, 900 West Hastings Street
Vancouver, British Columbia, Canada, V6C 1E5

December 7, 2010

TABLE OF CONTENTS

TABLE OF CONTENTS 1
LIST OF APPENDICES 2
LIST OF TABLES 2
LIST OF FIGURES 2
LIST OF MAPS 2
1.0 SUMMARY 3
2.0 INTRODUCTION 3
3.0 RELIANCE ON OTHER EXPERTS 4
4.0 PROPERTY DESCRIPTION AND LOCATION 4
5.0 ACCESSIBILITY, CLIMATE, LOCAL RESOURCES, INFRASTRUCTURE, PHYSIOGRAPHY 7
6.0 HISTORY 7
6.1 Previous Work 7
6.2 2010 Exploration Program 8
7.0 REGIONAL GEOLOGY AND MINERALIZATION 8
7.1 Geology 8
7.2 Mineralization 9
7.2.1 Keno Hill 9
7.2.2 Mt. Hinton 9
7.2.3 Marg 9
8.0 GEOCHEMISTRY 11
8.1 Rock Geochemistry 11
8.2 Soil Geochemistry 11
9.0 PROPERTY GEOLOGY AND MINERALIZATION 12
9.1 Lithology and structural geology 12
9.2 Mineralization 15
10.0 DIAMOND DRILLING 16
10.1 Key10-01/02 18
10.2 Key10-03/04 18
10.3 Key10-05/06/09 21
10.4 Key10-07/08/10 21
10.5 Key10-11 21
10.6 Key10-12 25
10.7 Key10-13 25
11.0 DISCUSSION AND CONCLUSIONS 27

LIST OF APPENDICES

Appendix A: Bibliography
Appendix B: Statement of Expenditures
Appendix C: Rock Sample Descriptions
Appendix D: Drill Logs
Appendix E: Geotech Logs
Appendix F: Certificates of Analysis
Appendix G: Quality Control / Quality Assurance
Appendix H: Compact Disc
Appendix I: Geologist's Certificate

LIST OF TABLES

Table 1: Keystone claims 4
Table 2: Percentile values for elements of interest from 2010 grab samples 11
Table 3: Correlation matrix for elements of interest from 2010 grab samples 11
Table 4: Percentile values for elements of interest from 2006 - 2010 soil samples 12
Table 5: Correlation matrix for elements of interest from 2006 - 2010 soil samples 12
Table 6: Significant Mineralization in grab samples 16
Table 7: 2010 Diamond Drill Hole Summary 17
Table 8: Summary of core intervals with significant assay results 18

LIST OF FIGURES

Figure 1: Location Map 5
Figure 2: Tenure information 6
Figure 3: Property geology according to Murphy (1997) 10
Figure 4: Equal-area lower hemisphere stereonet plot showing poles to foliation with average pole/plane 14
Figure 5: Tight fold in metagreywacke layer of the Hyland Group. 14
Figure 6: Thrust fault contact between tectonized quartzite and normal Hyland Group rocks 15
Figure 7: Section of Key10-01/02/12 19
Figure 8: Section of Key10-03/04 20
Figure 9: Section of Key10-05/06/09 22
Figure 10: Section of Key10-07/08/10 23
Figure 11: Section of Key10-11 24
Figure 12: Section of Key10-13 26

LIST OF MAPS

Map 1: Drill collars, property geology and grab/soil sample locations ..... in pocket
Map 2a: 2010 soil sample locations ..... in pocket
Map 2b: 2010 soil sample Au values ..... in pocket
Map 2c: 2010 soil sample As values ..... in pocket
Map 2d: 2010 soil sample Sb values ..... in pocket

1.0 SUMMARY

The Keystone property lies approximately 40 kilometres northwest of Mayo, within the Mayo Mining District of the Yukon Territory. The claim block consists of 381 quartz claims covering approximately 7700 hectares, optioned by Aldrin Resource Corp. from Ryanwood Exploration.

The Keystone area lies on the western margin of the northern Canadian Rockies, an area of rugged fold-and-thrust style mountains of moderate height in a sub-arctic climate. Deformed sedimentary rocks which form the vast majority of the bedrock in the area were deposited in the continental-shelf type environment of the Selwyn Basin. Throughout the region, these sequences are intruded by post-deformation (Cretaceous) granitic stocks of the Tombstone Suite. These intrusions are the causative factor of much of the regional mineralization.

Exploration and mining in the area date back to the late 19th century, when placer gold was discovered and mined on Duncan Creek, part of the headwaters of which lie on the current Keystone claim block. All creeks in the area, including Keystone Creek itself, have either current or historical placer gold workings. The current program of work was initiated with a reconnaissance soil sampling program by Ryanwood Exploration. Follow-up work identified a significant soil anomaly, at which point Aldrin Resources optioned the claim block and undertook the exploration program detailed in this report.

The region surrounding the Keystone property is host to several large precious and base metal deposits. The most significant is at Keno Hill, where a large vein-hosted Ag-Pb-Zn deposit was actively mined for most of the 20th century. Closer to the property, a system of quartz veins on Mt. Hinton hosts a gold deposit of potentially economic size.

The 2010 exploration program on the Keystone property consisted of mapping, prospecting, soil sampling and diamond drilling. Mapping showed that the property is underlain by the Hyland Group, a late Proterozoic to Cambrian age turbidite sequence with subordinate quartzite and limestone. The unit is extremely folded and faulted, with at least two generations of deformation and two faulting events. A pervasive bedding-parallel foliation strikes southeast and dips moderately to the southwest. Grab samples taken from within the soil anomaly assayed quite high in gold and arsenic, but in other areas no significant mineralization was found. Extensions to the previous soil sampling grid identified several new anomalous areas.

Drilling to locate the bedrock source of the soil anomaly intersected a mineralized structure which appears to trend northeast and dip steeply to the southeast. This structure contains multiple zones averaging greater than 1.0 g/t Au over up to 6 metres in core. Gold mineralization appears to be associated with late-stage arsenopyrite-bearing quartz-carbonate veins which cross-cut foliation within these zones. Projection to surface of these auriferous sections matches well with the area of elevated Au-As-Sb defined by soil and rock sampling, and they are thus interpreted to be the cause of the anomaly.

2.0 INTRODUCTION

Equity Exploration Consultants Ltd (“Equity”) was contracted by Aldrin Resource Corporation (“Aldrin”) to carry out a field mapping and diamond drilling program in the summer of 2010. The purpose of the program was early-stage exploration of Aldrin’s Keystone property for its gold potential. All work was carried out under the direction of Cam Bartsch, (the primary project manager) or the author, with the exception of the soil sampling program which was carried out by Groundtruth Exploration. Subsequent to completion of the field program, Equity was requested by Aldrin to compile and interpret the results of both programs. The information used in compiling this report consists of assessment reports filed with the Yukon Department of Energy, Mines and Resources, peer-reviewed scientific papers and private information supplied by Aldrin. Both of the authors worked on the Keystone property during the 2010 program and have first-hand knowledge of its geology, mineralization and drill core.

3.0 RELIANCE ON OTHER EXPERTS

The authors have not relied on a report, opinion or statement of an expert for information concerning legal, environmental, political or other issues.

4.0 PROPERTY DESCRIPTION AND LOCATION

The Keystone property is located in the Mayo Mining District of the Yukon Territory, approximately 40 km northeast of the town of Mayo on the northern shore of Mayo Lake. The claim block is centred at 63°50' north latitude and 135°15' west longitude (Figure 1). Access was by road to a camp located on an airstrip approximately 5 km southwest of the claim block, directly west of Mayo Lake. From the camp, personnel and equipment were mobilized to the property by helicopter.

The claim block consists of 381 adjoining quartz claims with a total area of approximately 7672 hectares. There are four claim name series: claims Key 1-20 staked in 2004, Keywest 21-36 staked in 2006, Keyeast 37-72 staked in 2007 and 2009, and K 1-309 staked in 2009 and 2010 (Figure 2, Table 1: Keystone claims). A press release by Aldrin states that the company optioned the property from Ryanwood Exploration in October 2009 and is committed to payments of $450,000 to Ryanwood and exploration expenses of $1,500,000 before late 2013 in order to maintain its interest in the claims. Ryanwood has maintained a 2% NSR on the property. Claim boundaries are defined by claim posts, some of which have been located in the field but have not been legally surveyed.

Placer claims with the series name Creek Claim are staked over much of the run of Keystone Creek. These claims are currently being worked as a small-scale placer operation. The airstrip on which the camp was located was constructed and is maintained by the operator of the Creek Claim placers.

There are no known environmental liabilities on the property.

A Land Use permit has been issued for the camp, allowing occupancy for one year. Final inspection on August 30, 2010 showed that all material in the camp area had been removed and it had been returned to its original state. Drilling was conducted under a Class 1 Quartz Mining Land Use Permit.

Table 1: Keystone claims

Grant Numbers	Claim Names	Staking Date	Expiry Date
YC11702 – YC11711	Key 1 – 10	2/24/2004	3/5/2016
YC11712 – YC11717	Key 11 – 16	2/24/2004	3/5/2017
YC11718 – YC11721	Key 17 – 20	2/24/2004	3/5/2018
YC50788 – YC50793	Keywest 21 – 26	8/15/2006	1/5/2017
YC50794 – YC50795	Keywest 26 – 27	8/15/2006	1/5/2016
YC50796 – YC50803	Keywest 28 – 36	8/15/2006	1/5/2015
YC56615 – YC56624	Keyeast 37 – 48	6/29/2007	3/5/2015
YC57335 – YC57349	Keyeast 49 – 64	8/31/2007	1/5/2013
YC70669 – YC70676	Keyeast 65 - 72	1/17/2009	3/5/2011
YC92901 – YC93000	K 1 -100	9/24/2009	3/5/2011
YC93147 – YC93198	K 101 – 152	9/24/2009	3/5/2011
YD12783 – YD12798	K 153 – 168	2/25/2010	2/25/2011
YD12798 – YD12939	K 168 – 309	3/1/2010	3/1/2011

Aldrin Resources Corp.

Keystone Project

Location Map

EQUITY	Date: NOV 2010	Scale: 1:7,000,000	Figure 1
	U.T.M. Zone UTM 8 - NAD83	Mining District Mayo	
	N.T.S. 105M/14	Province Yukon	


Mayo Lake
ALDRIN RESOURCE CORP.
KEYSTONE PROJECT
2010 Land Tenure
EQUITY
Date November, 2010
Scale 1:60,000
U.T.M. Zone NAD83 Zone 8
Mining District Mayo
N.T.S. 105M/14
State/Province YT
Figure 2
0 400 800
METRES
SCALE 1:20,000

5.0 ACCESSIBILITY, CLIMATE, LOCAL RESOURCES, INFRASTRUCTURE, PHYSIOGRAPHY

The Keystone area is located on the western margin of the northern Canadian Rockies, characterized by fold-and-thrust mountains of moderate height. Climate is classified as sub-arctic with long cold winters and short, cool summers. Average temperature can range up to 20°C from June to August, with the greatest amount of precipitation falling during the same time period. Topography of the property is generally rugged, with sharp mountain peaks up to 1600m above sea level (ASL) grading steeply to creeks beds, the lowest points of which are approximately 750m ASL. Creeks on the southern half of the property all flow into Mayo Lake, which at 670m ASL forms a local base level. Streams which drain the northern section of the claim block flow into Duncan Creek, which joins the Mayo River several kilometres downstream of Mayo Lake. The area is classified as having extensive, discontinuous permafrost. Tree line is several hundred meters below the mountain peaks. Above the tree line, slopes are generally steep, consisting of talus at higher elevation and grassy meadows lower down. Slopes below the tree line are dominated by spruce forest, which gives way to dense willow thickets near watercourses.

The village of Mayo (population 500) is the closest service and supply centre to the Keystone camp, accessible by 40 km of maintained dirt road. The mostly abandoned town of Keno is closer, but has no services. The airstrip directly to the west of Mayo Lake upon which camp was located is suitable for landing small fixed wing aircraft. Water from the streams which drain into Mayo Lake is suitable for drinking. Access to the work area (approximately 10 km from camp) is via helicopter.

It is possible to operate a camp-based field program in the Keystone area from late May through early September with weather and snow pack making work difficult outside that time period. There is sufficient water flow in the streams draining the property to allow diamond drilling through the summer months. Apart from the placer claims on Keystone Creek, there are no surface rights which could present any impediment to mineral exploration.

6.0 HISTORY

6.1 Previous Work

In 1955 a block of 32 claims in what is now the western part of the Keystone block was staked as the Par group and explored by Northwestern Explorations for lead and zinc. Previous sampling by the Geological Survey of Canada had identified a hydro-geochemical heavy metal anomaly in Parent Creek, a tributary of Duncan Creek (Boyle et al. 1955). Later that year geological mapping, soil and plant sampling were conducted on the property. The results of the program indicated that there was no near-surface source for the stream anomaly, and that it may have been the result of ground water encountering mineralization before coming to surface (Noel 1955). No further work is recorded on the Par group and the claims were allowed to lapse.

Most of the creeks draining the Keystone property have at least minor historical placer gold production. The lower reaches of Duncan Creek produced some of the earliest recorded placers in the Yukon Territory, and Keystone Creek currently has small-scale workings on it. In 1996 a seismic reflector survey was conducted on lower Keystone and upper Duncan creeks to evaluate the feasibility of reaching the bedrock source of the placer gold. Bedrock was interpreted to be 20 – 30 m below surface in the lower part of Keystone Creek (Power 1996). There is no record of any follow-up work attempting to reach bedrock for mining purposes.

The area surrounding the headwaters of Keystone Creek was soil sampled at a reconnaissance scale in 2004 by Ryanwood Exploration Ltd (Ryan 2004). Several promising Au-As anomalies were detected based upon which approximately 1100 further soil samples (along ridge-and-spur and grid lines) were taken between 2006 and 2008. This sampling detected a 3-km long Au-As-Sb anomaly which became the target of the exploration program described in this report.

The claims which compose the current Keystone block were staked by Shawn Ryan of Ryanwood Exploration between 2004 and 2010 and subsequently optioned to Aldrin Resource Corp.

There is no record of drilling on the Keystone property prior to this year's program.

6.2 2010 Exploration Program

The 2010 Keystone Exploration program consisted of mapping, prospecting, soil sampling and diamond drilling. Field work was supported out of a road and fixed-wing aircraft accessible camp on a dirt airstrip directly west of Mayo Lake, which consisted of canvas wall tents and weatherhavens. Access to the claim block was via a Bell 206 Long Ranger helicopter contracted from Trans North Helicopters, based out of Mayo, Yukon.

Field crews collected a total of 82 grab samples from outcrop and/or subcrop/float which were analysed by ALS Chemex Labs for a 36-element suite. Sample locations are shown on Map 1. Analytical codes were Au-AA23 (fire assay for gold) and ME-ICP41 (ICP Mass Spectrometry for other elements). Sample sites were marked with blue and orange flagging tape, and a metal tag inscribed with the sample number. A sampling crew operated by Groundtruth Exploration based out of Dawson City, Yukon was contracted by Aldrin to extend the soil sample grid established previously by Ryanwood Exploration. A crew of eight people collected a total 2579 soil samples between July 1st and July 15th, which were subsequently analysed by ACME Labs for a 36-element suite. Sample locations are shown on Map 2a. Soil samples were taken from the B-horizon where possible. All samples locations for soil and rock samples were recorded by hand-held GPS. Most areas of accessible outcrop on the property were traversed and mapped even if no sampling was done.

During the 2010 program, 1875 m of core in thirteen holes (locations shown on Map 1) was drilled by Coretech Diamond Drilling of Princeton, BC. Two rigs were onsite for the majority of the program, one capable of drilling NQ thinwall size core and one BQ thinwall. Nine of the holes were drilled by the NQ thinwall rig, the remaining four by the BQ thinwall rig. The core was processed onsite at the Keystone camp. Recovery, percent rock quality descriptor (RQD; total length of unbroken segments longer than 10 cm) and magnetic susceptibility were measured for each drill run. A KT-9 Kappameter was used to measure magnetic susceptibility. Sample intervals were 1.5 m, delineated with numbered waterproof paper tags stapled at the end of the sample interval. A gas-powered core saw was used to split the core, with half being shipped to ALS Chemex Labs for analysis and half trucked to a storage facility in Dawson City owned by Ryanwood Exploration. Depending on personnel availability, samples were either delivered to the ALS Chemex preparation facility in Whitehorse by Equity staff, or shipped via Rick's Expediting (based in Mayo) to Mayo, then on to Whitehorse via Kluane Freight Lines. All samples were sealed in rice bags with numbered security tags to prevent tampering during shipping. ALS Chemex assayed the samples for gold via fire assay (code Au-AA23) and a further 35-element suite via ICP-MS (code ME-ICP41). Approximately 15% QA/QC samples were inserted into the sequence, the analysis of which is presented in Appendix F.

A magnetic declination of 23° E was used for all compass measurements. Structural measurements are all reported utilizing the right-hand rule. All maps and UTM coordinates are referenced to the 1983 North American Datum (NAD-83; Zone 8).

7.0 REGIONAL GEOLOGY AND MINERALIZATION

7.1 Geology

The Keystone property lies along the northern edge of the Selwyn Basin, a region of deep water off-shelf sedimentation that persisted from late Precambrian to early Carboniferous time. The sedimentary sequences which now form the bedrock of the area were uplifted to their present locations by later accretion of outboard terranes. Regional mapping by Murphy (1997) shows that the oldest unit in the region is the late Proterozoic to early Cambrian Hyland Group, an interbedded sequence of phyllite, quartzite, metagreywacke and limestone. This unit has been structurally emplaced by the Robert Service Thrust over top of the Devonian Earn Group (phyllite, metasiltstone and felsic volcanic units) and early Carboniferous Keno Hill Quartzite (Figure 3). Locally and in older literature, these units are termed the upper schist (Hyland Group), middle quartzite (Keno Hill Quartzite) and lower schist (Earn Group), reflecting their current structural arrangement.

Movement along the Robert Service Thrust predated emplacement of the only significant igneous body in the region: the Roop Lakes Stock, part of the Cretaceous Tombstone Plutonic Suite. This suite is an extensive northwest trending belt of biotite-hornblende monzonite to quartz monzonite. Igneous bodies range in scale from smalls stocks to large batholiths and are often associated with gold deposits throughout the Tintina Gold Belt.

7.2 Mineralization

7.2.1 Keno Hill

Keno Hill has been the site of extensive mining since the early 20th century. Between 1913 and 1989 over 6600 tonnes of silver, 35000 tonnes of lead and 21000 tonnes of zinc were extracted from the area (Lynch 1989). Mineralization is hosted in zoned quartz-feldspar-carbonate veins within the Keno Hill Quartzite, which extend laterally from the Cretaceous Roop Lake Stock (Lynch 1989). The system extends nearly 40 km outwards from the pluton, but the richest discovered Ag-Zn-Pb deposits are in the Keno Hill area. Even within this area, proper structural preparation is required for high-grade ore to form; preferred sites are at the intersections of multiple vein faults, or where those faults pass from thickly bedded quartzite into thinner quartzite or phyllite beds (Boyle 1965).

7.2.2 Mt. Hinton

Immediately to the northwest of the Keystone property is Mt. Hinton, the site of a 3.4 km-long by 300m-wide trend of gold and silver-bearing quartz veins. These veins are thought to represent an earlier stage of mineralization than the veins which host the Keno Hill deposit. As many as 50 mineralized veins are part of this trend, the best of which grade up to 40 g/t Au and 300 g/t Ag with widths of up to 1 m (Carne 2004). Vein distribution on Mt. Hinton is controlled by three types of faults: transverse, bedding plane and cross faults (Ouellette 1985). The majority of the mineralization is hosted in the east-northeast striking, southeast dipping transverse faults. Some minor mineralization has also been recorded where these transverse faults intersect bedding plane faults. It is thought that these faults acted as a conduit system for mineralizing fluids associated with the Roop Lakes Stock. A third generation of faults (termed cross-faults) cut both transverse and bedding plane faults and offset the mineralized zones in a left lateral sense. Re-brecciation of early-stage quartz-cemented veins by these later faults is common. On Mt. Hinton, mineralization of faults only occurred where the host rock was a brittle quartzite or greenstone of the Keno Hill Quartzite. It is likely that other units lacked sufficient competency to form wide, well-developed fluid conduits. Carne (2004) observed that where the vein faults cross from quartzite into more ductile phyllite, a narrow zone of fault gouge unsuitable for mineralization was often the only visible structure. Vein mineralogy is dominated by quartz, pyrite and minor galena. Some veins contain subordinate amounts of jamesonite and sphalerite. Mineralized veins always contain arsenopyrite.

7.2.3 Marg

The Marg deposit is a Devonian-Mississippian volcanogenic massive sulphide (VMS) polymetalic deposit situated approximately 40 km northeast of the Keystone property. It consists of a series of stacked sheets of massive to semi-massive sulphide mineralization hosted within felsic volcanic rocks of the Earn Group. Average grades within the mineralized lenses are estimated to be 1.5% Cu, 2% Pb, 3.8% Zn, 52 g/t Ag and 0.8 g/t Au (Carne 2007). This system has little bearing on the Keystone property, as the Earn Group is absent from the area and there is no evidence of any felsic volcanic units or associate massive sulphide mineralization.


Triassic
TD
Fine to medium grained green amphibole-chlorite-plagioclase meta-diorite or meta-gabbro
Mississippian
MK
Keno Hill Quartzite
Fine to coarsely foliated and lineated, light and dark grey quartzite with subordinate dark grey carbonaceous phyllite and calcareous quartzite
Upper Proterozoic
ZYF
ZYFI
Hyland Group (Yusezyu Formation)
(YF): Medium brown, foliated and lineated muscovite-chlorite phyllite, quartzofeldspathic and micaceous psammite and rare calc-silicate and marble (YFI): Limestone member
Thrust Fault
Boundaries of Keystone claim block
0 400 800
METRES
SCALE 1:20,000
TD
ZYF
MK
ZYFI
ALDRIN RESOURCE CORPORATION
KEYSTONE PROJECT
Bedrock Geology of the Keystone area
EQUITY
Date November, 2010
Scale 1:60,000
Figure 3
U.T.M. Zone NAD83 Zone 8
Mining District Mayo
N.T.S. 105M/14
State/Province YT

8.0 GEOCHEMISTRY

8.1 Rock Geochemistry

A total of 82 grab samples were collected in the course of reconnaissance mapping and prospecting during the 2010 program. Percentile values and a correlation matrix for the samples are shown below in tables Table 2 and Table 3. Samples locations are shown on Map 1 coded by Au percentile.

Table 2: Percentile values for elements of interest from 2010 grab samples

	Au (ppm)	Ag (ppm)	As (ppm)	Cu (ppm)	Ni (ppm)	Pb (ppm)	Sb (ppm)	Zn (ppm)
Population	82	82	82	82	82	82	82	82
Max Value	2.58	100	>10000	878	114	>10000	>10000	>10000
Min Value	0.01	0.2	2	1	1	2	2	2
98th	2.03	25.7	10000	296	56.5	2386	7262	2729
95th	0.96	2.69	7336	96.5	42.0	262	154	407
90th	0.52	1.09	2206	50.8	32.9	118	68	185
80th	0.10	0.50	67.8	33.8	21.8	52.8	21	64
50th	0.01	0.20	4.0	8.0	7.0	12.0	2	31

*Sample results below detection limit were included in percentile calculations

Table 3: Correlation matrix for elements of interest from 2010 grab samples

	Au	Ag	As	Cu	Ni	Pb	Sb
Au							
Ag	0.48						
As	0.75	0.47					
Cu	0.14	0.42	0.11				
Ni	-0.26	-0.21	-0.28	0.59			
Pb	0.49	0.98	0.47	0.45	-0.14		
Sb	0.39	0.87	0.35	0.69	-0.29	0.81	
Zn	0.55	0.96	0.54	0.47	-0.09	0.97	0.77

*Sample results below detection were excluded from correlation calculations

Table 3 shows excellent correlation between Ag, Pb, Sb and Zn. This is not surprising given the proximity of the Keno mining camp, and the samples which show anomalous levels of these elements may have been affected by distal elements of this system. There is also good correlation between Au and As, suggesting that anomalous gold values are related to a Mt. Hinton type system where Au and As are closely linked.

8.2 Soil Geochemistry

The soil geochemistry data from 2006 – 2008 was combined with the results from the 2010 soil sampling program to form a property-wide dataset. Table 4 and Table 5 show percentile values and a correlation matrix for that dataset. Sample locations are shown on Map 2a. Maps 2b – 2d show assayed values of gold, arsenic and antimony percentiles respectively.

Table 4: Percentile values for elements of interest from 2006 - 2010 soil samples

	Au (ppb)	Ag (ppm)	As (ppm)	Cu (ppm)	Ni (ppm)	Pb (ppm)	Sb (ppm)	Zn (ppm)
Population	4108	4108	4108	4108	4108	4108	4106	4108
Max Value	2588	21.9	>10000	902	238	2246	2001	679
Min Value	0	0	0	4.8	4.3	1.6	0.2	20
98th	104	1.2	610	182	88	58	111	204
95th	51	0.8	276	126	69	45	39	158
90th	29	0.6	149	92	55	37	17	133
80th	15	0.4	63	68	44	31	8	110
50th	5	0.2	23	43	31	23	3	82

*Sample results below detection were included in percentile calculations

Table 5: Correlation matrix for elements of interest from 2006 - 2010 soil samples

	Au	Ag	As	Cu	Ni	Pb	Sb	Zn
Au								
Ag	0.66							
As	0.59	0.23						
Cu	0.17	0.17	0.06					
Ni	0.12	0.05	0.13	0.68				
Pb	0.72	0.76	0.20	0.09	0.09			
Sb	0.35	0.27	0.31	0.03	0.05	0.26		
Zn	0.29	0.37	0.26	0.44	0.67	0.35	0.19	

*Sample results below detection were excluded from correlation calculations

Soil sampling during the 2010 program focussed on expanding the grid and potentially extending the geochemical anomaly established by prior work. Sample locations with gold and arsenic values categorized by percentile are shown on Maps 2a – 2c. The maps show that the soil anomaly does not continue across the fault valley which formed the southwestern edge of the old soil grid. There are several isolated pockets of anomalous Au-As values, but nothing of the same scale as the main anomaly. To the north and east of the original grid, the largest new anomaly is a 1km x 500m zone on the north bank of the upper reaches of Keystone Creek. The zone contains multiple samples in the 98th percentile for gold, arsenic and antimony. The long axis of this zone is oriented parallel to the strike of the pre-2010 anomaly, suggesting that it may have had its genesis in a parallel structure. The other new anomalous zones are all small and discontinuous.

9.0 PROPERTY GEOLOGY AND MINERALIZATION

9.1 Lithology and structural geology

The geology of the Keystone property as mapped during the 2010 field season conforms generally to that described by Murphy (1997). The majority of the property is underlain by the Hyland Group, which in the Keystone area was observed to be an interbedded sequence of dominantly quartz-muscovite schist (metagreywacke) and graphitic phyllite (metamudstone), with subordinate quartzite and limestone (Map 1). This unit is termed the Yusezyu Formation by Murphy (1997) and has been regionally metamorphosed to greenschist facies (Lynch 1989). Silica, carbonate and graphite alteration can all be found throughout the property though they are by no means pervasive. Silica alteration appears to be concentrated around major fault structures, though it can be found in isolated zones that do not lie near a visible fracture. Carbonate alteration is most readily observed on exposed faces above the tree line where iron carbonate has weathered to prominent gossan zones. Similarly, many areas of phyllite exposed on talus slopes are pervasively

graphiticly altered. The Robert Service Thrust lies on the eastern edge of the claim block, forming a boundary between Hyland Group rocks to the west and the Keno Hill Quartzite to the east (Figure 3). The small sliver of Keno Hill Quartzite shown by Murphy (1997) to the west of the main Robert Service Thrust was not identified during this year's field work and may be a quartzite member of the Hyland Group.

At least two episodes of deformation are recorded on the Keystone property. The dominant fabric is a set of foliations roughly parallel to compositional layering which strike NW-SE and dip shallowly to the southwest (Figure 4). However, on the outcrop scale it is possible to find tight to isoclinal folds, the limbs of which conform in orientation to the regional fabric (Figure 5). This suggests an episode of compression under a ductile regime which created the tight folds, followed by a second event which displaced the fabric from vertical to the present orientation. It is not clear from the scope of this work whether this later deformation was brittle or ductile.

In addition to the ductile deformation discussed above, there has been significant brittle deformation throughout the area. The most significant feature is the Robert Service Thrust, already described above. It is possible (though not confirmed by the present work) that the brittle deformation event which resulted in the Robert Service Thrust (among others) is also responsible for introducing the regional tilt illustrated in Figure 4.

Westward of the main trace of the thrust there are multiple parallel faults which suggest a complex deformation history (Map 1). For example, one of the tributaries of Keystone Creek follows the trace of an inferred normal fault in which the eastern (hanging wall) block appears to have been dropped at least one hundred meters. Most of the major NW-SE trending creek valleys parallel the Robert Service Thrust and have the appearance of fault valleys. At the outcrop scale there are numerous small faults of similar orientation. Given the tectonic setting of the area, it is likely that many of these small faults are minor thrusts.

A second set of faults, varying in scale from outcrop to property-spanning, strikes to the NE, nearly perpendicular to the Robert Service Thrust. The main channels of Keystone, Ping Pong and Duncan creeks are all oriented parallel to the strike of this fault set, as is the strike of the soil anomaly. This is also the orientation of the mineralized veins on Mt. Hinton. Alteration surrounding these structures and the results of the drill program (discussed in Section 10) suggest that it is these faults which host the gold mineralization which gave rise to the soil anomalies. However, the complex history of the area makes it possible that not all mineralized zones lie directly along the primary traces of these faults or are exposed on surface. Satellite thrusts of the Robert Service Thrust could have emplaced unmineralized rocks over additional mineralized zones, and small-scale NW-trending faults could have offset earlier gold-bearing NE-trending structures.

Parallel to this set of NE-trending faults is a large-scale southeast verging, northwest dipping (206° strike, 8° dip towards the northwest) thrust, located directly north of the anomalous soil trend which was the focus the 2010 exploration program (outlined on Maps 2a – 2c). The thrust emplaced a highly tectonized quartzite on top of the standard Hyland Group sequence of metagreywacke, phyllite and minor limestone. The quartzite is a prominent topographic feature, forming the cap of a 3 km long ridge (Figure 6). It is also thicker than most quartzite layers of the Hyland Group, suggesting the possibility that it is a tectonically emplaced sliver of Keno Hill Quartzite. Regional mapping by Murphy (1997) shows a similar sliver of Keno Hill Quartzite bounded by thrust faults, albeit at a different (almost due north-south) orientation.



Figure 4: Equal-area lower hemisphere stereonet plot showing poles to foliation with average pole/plane

Figure 5: Tight fold in metagreywacke layer of the Hyland Group.

Figure 6: Thrust fault contact between tectonized quartzite and normal Hyland Group rocks. Photo taken looking north from approximately 492,500E, 7079250N.

9.2 Mineralization

The trace of the Au-As soil anomaly delineated by pre-2010 soil sampling (Maps 2a – 2c) has the same strike as that of the northeast trending faults and appears to follow the topography in a manner consistent with a planar structure dipping steeply to the southeast (such as mineralized fault zone). If the soil anomalies are the result of a Mt. Hinton or Keno Hill style mineralizing event, then this fracture system is a likely candidate to be the conduit for the mineralizing fluids. As would be expected if the fractures were fluid conduits, zones of intense fracturing also host silica and carbonate altered Hyland Group rocks (most commonly metagreywacke) and breccias healed with both silica and carbonate. Small zones of stockwork-style quartz veining can be found throughout the property but do not host significant quantities of visible sulphide minerals.

Grab samples were taken from all outcrops that appeared to have any secondary veining or alteration, but the only ones which contained anomalous gold values were from the zone defined by the soil anomaly and contained large percentages of arsenopyrite (Table 6, Map 1). This trend was the focus of the 2010 drill program, described in detail in section 10.

Table 6: Significant Mineralization in grab samples

Sample ID	PY %	ASP %	Au ppm	Ag ppm	As ppm	Pb ppm	Sb ppm	Zn ppm
E855606	0.5	10	2.58	0.4	>10000	13	64	2060
E855508	2	8	2.19	100	>10000	>10000	>10000	>10000
E855608			1.93	0.6	14	2	33	64
E855701	tr	tr	1.62	0.2	7420	4	14	22
855605	tr	3	0.88	0.4	10000	18	30	65
E855513	3		0.64	0.8	9520	127	109	195
E855506	2	5	0.51	39.2	5740	5550	6760	3820
E855511	1	tr	0.51	0.7	5270	56	61	14

Aside from discontinuous minor arsenopyrite ± pyrite within the soil anomaly, very little mineralization was found on the property. Regional mapping and prospecting discovered numerous gossan zones which were primarily the result of iron carbonate weathering. Most outcrops of metagreywacke host abundant fabric-parallel quartz veins which appear to be syn-tectonic (perhaps the results of quartz “sweats” from siliceous protolith) and contain very little sulphide mineralization apart from minor pyrite and/or rare pyrrhotite. Many zones of the property host small quartz veins which cross-cut this tectonic fabric and locally contain minor amounts of pyrite, arsenopyrite, galena and/or tetrahedrite. None of the samples taken from these veins returned significant assay results.

10.0 DIAMOND DRILLING

Thirteen diamond drill holes totalling 1875m were drilled during the 2010 exploration program. Drill targets were chosen based on soil geochemical anomalies and interpreted structural geology. Nine of the holes (total depth 1275m) were drilled using NQ thinwall bit and rods, the remaining four (600m) with BQ thinwall. Table 7 summarizes location, depth and orientation for the 2010 drill holes; full logs are attached in Appendix E. Collar locations are shown on Map 1. A total of 1402 samples were taken at regular 1.5m intervals including 15% QA/QC samples. QA/QC analysis is presented in Appendix G.

Table 7: 2010 Diamond Drill Hole Summary

Hole ID	UTM (north)	UTM (east)	Elevation (ft)	Length (m)	Dip (°)	Azimuth (°)	Core Size
KEY10-01	7078105	490641	4515	158.8	-50	325	NTW
KEY10-02	7078105	490641	4515	219.51	-70	325	NTW
KEY10-03	7078137	491054	3622	26.51	-55	325	NTW
KEY10-04	7078137	491054	3622	102.72	-70	325	NTW
KEY10-05	7079440	491607	5396	66.15	-50	325	NTW
KEY10-06	7079440	491607	5396	178.31	-70	325	NTW
KEY10-07	7077639	490028	3937	248.41	-50	325	BTW
KEY10-08	7077639	490028	3937	73	-70	325	BTW
KEY10-09	7079440	491607	5396	224.64	-50	325	NTW
KEY10-10	7077639	490028	3937	182.88	-65	325	BTW
KEY10-11	7079393	491409	5289	169	-60	360	NTW
KEY10-12	7078161	490503	4326	93.57	-70	325	BTW
KEY10-13	7078331	491601	4085	130.74	-60	325	NTW

**UTM co-ordinates are projected in NAD83, Zone 8

All drill sites were chosen in an attempt to locate and define the source of the anomalous Au-As-Sb trend shown on Maps 2a – 2c. Based on field observations, knowledge of mineralization styles in the region (ie, Keno Hill and Mt. Hinton) and the surface trace of the anomaly relative to topography, it was hypothesized that the mineralizing structure was a fracture and/or vein system striking northeast-southwest and dipping steeply to the southeast. Collar sites were placed immediately southeast of the anomaly and in most cases drilled on an azimuth of 325°. On most setups, multiple holes at dips between -50° and -70° were drilled so as to intercept any mineralized structures at multiple points and better constrain their true width and orientation.

All holes encountered the same turbidite sequence of metagreywacke and phyllite with subordinate quartzite and limestone seen on surface. Foliation-parallel quartz veins of varying thickness (0.5 – 10 cm wide) are extremely common and are likely the result of “quartz sweats” from silica-rich members of the sedimentary sequence during metamorphism and deformation as opposed to a later hydrothermal event. Graphitic alteration is widespread in the phyllite layers and is likely the result of high carbon content in the mudstone which formed the protolith of the phyllite. Unaltered zones of phyllite can contain trace to several percent pyrite which appears to be diagenetic in origin and to predate mineralization. Pyrite can be present in other units but generally at lower concentrations. Some coarse-grained layers contain mm-scale blue quartz grains which have been described elsewhere (e.g. Carne 2004) as being diagnostic of the Hyland Group.

Aside from the graphitic alteration described above, the dominant types of alteration are silica, carbonate and chlorite, all of which are more intense around fault zones. More rarely, iron oxide and iron carbonate can be present. In many cases, alteration zones are bounded above, below or both by faults which likely acted as conduits for the hydrothermal fluids responsible for the alteration. Carbonate and silica alteration are generally more intense in coarser-grained layers, though not confined to them. Chlorite alteration is more intense in phyllite layers, but as with the other styles, can be found to at least a minor degree in all units. In these zones, pyrrhotite is present in phyllite layers in addition to pyrite, possibly as a replacement product from exposure to high-temperature fluids. Smaller, rarer quartz ± carbonate veins which cross-cut the regional fabric appear to be later and may be related to mineralization. Arsenopyrite is much less abundant than pyrite and pyrrhotite, and is generally associated with cross-cutting veins and fractures. There is a good correlation between arsenopyrite mineralization and gold, and though not all zones with elevated arsenic contained anomalous levels of gold, there were no significant gold-bearing zones which were not accompanied by elevated arsenic (Table 8).

Table 8: Summary of core intervals with significant assay results

Hole	From (m)	To (m)	Interval (m)	Au (ppm)	As (ppm)	Sb (ppm)	Ag (ppm)	Pb (ppm)	Zn (ppm)
KEY10-02	96.5	110	13.5	0.58	5100				
including	104	107	3	0.97	6850				
Key10-07	19	29.5	10.5	0.50	1400				
including	25	28	3	1.20	2730				
Key10-08	37.5	45	7.5	0.45	3400				
Key10-09	50.5	52	1.5	0.86	4700	1910	100	5180	10000
Key10-09	78.62	110	31.38	0.56	3645	208		263	441
including	78.62	79.28	0.66	1.90	10000	187		88	896
and	100	101.5	1.5	1.12	3770	994		1690	817
Key10-12	38.5	49	10.5	1.13	5303				
including	40	46	6	1.50	5790				

10.1 Key10-01/02

Holes Key10-01 and Key10-02 were drilled from the same collar location, at -50° and -70° respectively (Map 1). The holes were collared immediately to the southeast of a large gold-in-soil anomaly (up to 1026 ppb) and drilled to the northwest in an attempt to intersect the mineralized fault zone proposed to be the source of the soil anomaly. The holes encountered the normal regional sequence of quartzite, metagreywacke and phyllite with blebby pyrite and pyrrhotite in greater amounts around fracture zones (Figure 7). The only section of either hole which returned highly anomalous assay results was a 13.5m section of Key10-02 which averaged 0.58 g/t, up to 1 g/t over 3m (Table 8). An adjoining zone of Key10-01 contains a few samples with gold and arsenic elevated above background, but the zone is small and values are too low to be of economic interest. The unit these zones are hosted in was logged as heavily fractured phyllite with only minor metagreywacke. The locus of mineralization was most likely a zone of highly brecciated quartz veins which coincides with the most gold-rich zone. Though no arsenopyrite was visible in core, assays reported between 5000 and 7000 ppm arsenic, suggesting either the arsenopyrite was too fine grained to be visible or arsenic was bound up in some other mineral. Overall concentration of pyrrhotite was also higher than average over this interval.

10.2 Key10-03/04

Key10-03/04 were collared on the creek-bed down-slope form Key10-01/02, along the continuation of the anomalous soil trend which was the target of that setup. Overburden was thicker than anticipated and Key10-03 failed to reach bedrock. Key10-04 was drilled at a steeper angle and reached bedrock. The core was extremely faulted, with many intervals having core recovery close to zero. Rock types were the same as on surface and in Key10-01/02. The hole was ended before intended depth due to difficulty of drilling though metre-scale zones of fault gouge and lack of mineralization. The creek valley in which the hole was drilled was confirmed to be a fault, though it is unclear whether the structure was NE-trending, NW-trending, or at an intersection of the two. No samples from this hole returned any significant assay values, though carbonate and silica alteration were pervasive (Figure 8).





Aldrin Resource Corp

Keystone Project

DDH KEY10-01/02/12

Looking Southwest

EQUITY	Date: Nov, 2010	Scale: 1 : 1000	Figure: 7
	U.T.M. Zone: NAD 83 Zn 8	Mining District: Mayo	
	N.T.S.	State/Province: YK	





Aldrin Resource Corp

Keystone Project

DDH KEY10-03/04

Looking Southwest

EQUITY	Date: Nov, 2010	Scale: 1 : 1000	Figure: 8
	U.T.M. Zone: NAD 83 Zn 8	Mining District: Mayo	
	N.T.S.	State/Province: YK	

10.3 Key10-05/06/09

This setup was placed to test the sub-surface source of a 1084 ppb Au soil anomaly surrounded by several grab rock samples with up to 2.5 g/t Au. Though drilling was hampered by the extreme degree of fracturing (Key10-05 was lost in a fault zone and had to be re-drilled as Key10-09) two holes eventually reached target depths of over 200m and encountered the same basic rock package as the rest of the holes, already described above. In both holes, the package transitioned from interbedded metagreywacke and phyllite to essentially uninterrupted phyllite below ~75m depth (Figure 9). Perhaps as a result of the high degree of faulting, mineralization and alteration is more intense in this set of holes than in most of the others. Of note is an interval from 40 – 52 m depth which contained abundant vuggy quartz veins with well-developed crystals of tetrahedrite and stibiconite (after stibnite), the lowermost sample from which assayed extremely high in silver, lead, zinc, antimony and arsenic, and moderately high in gold (Table 8). A larger and more significant zone is between 78 and 102 m. Well mineralized with respect to both pyrite (5%) and arsenopyrite+scorodite (total 4%) the interval contains 0.5 g/t Au over its entire length, locally up to 2 g/t (Table 8). Sulphides are distributed as blebs throughout the unit, with concentrations around veins. There is intense and pervasive silica and iron oxide alteration. Unfortunately this mineralization appears to be confined to an isolated zone; it was not encountered elsewhere in Key10-09 or in Key10-06.

Though lacking in significant gold/arsenic values and mineralization apart from pyrite and pyrrhotite, Key10-06 shows abundant evidence of hyrdrothermal alteration. It is extremely faulted and displays intense chlorite, carbonate and silica alteration and (locally) up to 2% blebby disseminated pyrite and pyrrhotite.

10.4 Key10-07/08/10

These three holes were drilled to test a broad soil anomaly with gold values between 200 and 400 ppb on the eastern slope of the western tributary of Keystone Creek, potentially a continuation of the northeast trending structure investigated in other holes. As with elsewhere on the property, drilling was hindered by faulted ground; Key10-08 was lost in a fault zone and had to be re-drilled as Key10-10. These holes encountered a unit not seen elsewhere on the property; the upper 40 – 50 m of all three drilled through a thick layer of intensely carbonate-siderite altered quartzite with abundant, thick (multi-meter) breccia zones now healed with the same carbonate-siderite that altered the surrounding rocks. In Key10-07 one of these breccia zones is cut by a more recent, unhealed fault which contains notable quantities of arsenopyrite and gold (Table 8). Below these carbonate-quartzite layers the holes drilled though the same turbidite sequence as elsewhere on the property. The upper-most zone of this sequence is a 25 – 40m thick layer of dominantly metagreywacke which hosts gold/arsenic anomalies in all three holes (Figure 10). It is likely that the soil anomaly which provided the target for these holes is a result of this zone outcropping on surface northeast of the collar location. Discontinuously elsewhere in the holes, blebby pyrrhotite replacing pyrite suggests alteration by high-temperature fluids, but none of these zones assayed well for gold.

10.5 Key10-11

This hole was drilled 200m east of Key10-05/06/09 to investigate the same target. Though it encountered a similar package of highly faulted and altered turbidite rocks, locally mineralized with trace arsenopyrite and up to 0.5% pyrrhotite, there were no samples with gold assays in excess of 0.4 g/t and only a few zones of high arsenic (Figure 11). The overall lack of mineralization in this hole is an indication that the soil and grab samples anomalies are not the result of a large-scale mineralizing system.





Aldrin Resource Corp

Keystone Project

DDH KEY10-05/06/09

Looking Southwest

EQUITY	Date Nov, 2010	Scale 1 : 1000	Figure	9
	U.T.M. Zone NAD 83 Zn 8	Mining District Mayo		
	N.T.S.	State/Province YK		





Aldrin Resource Corp

Keystone Project

DDH KEY10-07/08/10

Looking Southwest

EQUITY	Date: Nov, 2010	Scale: 1 : 1000	Figure: 10
	U.T.M. Zone: NAD 83 Zn 8	Mining District: Mayo	
	N.T.S.	State/Province: YK	





Aldrin Resource Corp

Keystone Project

DDH KEY10-11

Looking West

EQUITY	Date: Nov, 2010	Scale: 1 : 1000	Figure: 11
	U.T.M. Zone: NAD 83 Zn 8	Mining District: Mayo	
	N.T.S.	State/Province: YK	

10.6 Key10-12

Key10-12 was drilled 150m northwest of Key10-01/02 in an attempt to intersect the structure responsible for the 1026 ppb soil anomaly which was the target of those earlier holes. Within the same package of rocks (though much closer to surface) as in Key10-01 and Key10-02 there is a 10m-wide zone with up to 1.0% disseminated arsenopyrite averaging over 1 g/t Au (Figure 7). It is possible that Key 10-01, Key 10-02 and Key 10-12 all cross-cut the same mineralized NE-trending, SE-dipping fault zone with a true width of approximately 10 metres. Figure 7 shows the projected section trace of this fault. If this zone is real it would outcrop almost directly underneath the soil anomaly, very close to the collar location of Key10-12. This suggests that Key10-12 may have been drilled almost directly down the structure. It is worth noting that the orientation of this mineralized zone is very similar to that in Key10-07/08/10, suggesting that both zones may be part of a larger structure.

10.7 Key10-13

Drilled to investigate the source of a 500 ppb soil anomaly which potentially represented a mineralized structure parallel to the main one drilled by the previous holes, Key10-13 intersected the same package of rocks as elsewhere. Carbonate alteration of the phyllite is slightly more intense than elsewhere, but otherwise the rocks are unremarkable (Figure 12). Despite abundant fracturing, very little mineralization was present (primarily pyrite) and apart from one sample which returned 50 ppm silver, there were no significant assay results. Most samples were below detection for gold.





Aldrin Resource Corp

Keystone Project

DDH KEY10-13

Looking Southwest

EQUITY	Date: Nov, 2010	Scale: 1 : 1000	Figure: 12
	U.T.M. Zone: NAD 83 Zn 8	Mining District: Mayo	
	N.T.S.	State/Province: YK	

11.0 DISCUSSION AND CONCLUSIONS

The 2010 exploration program thoroughly drill tested the soil anomaly identified by Ryanwood Exploration and which was the primary cause of interest in the Keystone property. In addition to the primary goal of drilling the anomalous zone, the program involved extensive prospecting of the entire Keystone claim block and enlargement of the existing soil grid.

Drilling revealed small amounts of gold associated with arsenopyrite in late-stage small-scale quartz veins concentrated along a northeast trending, southeast dipping structure. This zone has a similar mineralogy and morphology to those at the nearby Mt. Hinton deposit and may represent a distal portion of that same system. However, the veins on Keystone appear to be smaller than those on Mt. Hinton. It is possible that the Robert Service Thrust acted as a barrier to large-scale passage of mineralizing fluids from the Roop Lake Stock. Alternatively the bedrock underlying the Keystone property may have been less suitable to Mt. Hinton or Keno Hill-style mineralization; in both those deposits mineralized veins are confined to the Keno Hill Quartzite, a unit which is absent from all but the eastern-most edge of the Keystone property. The area is underlain instead by a turbidite sequence of the Hyland Group, a less competent unit than the quartzite which may not have been suited to the formation of large fluid channels required for the formation of large mineralized veins. Its pervasively fractured nature may be suitable instead to the formation of multiple smaller structures, in which case the parallel anomalous soil trends may represent multiple narrow mineralized zones.

Though none of the grab samples taken during property mapping outside the existing anomalous zone returned high assays of gold or other precious metals, the scale on which prospecting was conducted allows the possibility of small mineralized zones underneath overburden or on sections of the property that were not thoroughly examined. The expanded soil grid identified several new anomalous zones high in gold, arsenic and antimony which may be worthy of future investigation.

Overall, the work conducted this year revealed the presence of a small gold-bearing structure underlying the soil anomaly and advanced understanding of the property as a whole. Though the veins encountered by the drilling are large and well developed enough to be the source of the gold and arsenic detected in the soil survey, they are likely too small to form a significant deposit on their own. However, despite the small size of the drilled structure, its presence demonstrates that structurally controlled gold mineralization has occurred on the Keystone property. The abundant faulting throughout the area suggests that there may be other similar structures not yet discovered. Future exploration should focus on areas outside the scope of this year's drill program in order to locate additional structures similar to, but more significant than, the one discovered by this year's program.

Respectfully submitted,

_____

David Swanton, M.Sc.

EQUITY EXPLORATION CONSULTANTS LTD.

Vancouver, British Columbia

December 7, 2010

Appendix A: Bibliography

REFERENCES

Boyle, R.W. 1965. Geology, geochemistry, and origin of the lead-zinc-silver deposits of the Keno Hill- Galena Hill area, Yukon Territory (with short descriptions of the tin, tungsten, and gold deposits); Geological Survey of Canada, Bulletin 111, 302 p.

Boyle, R.W. Green, R N. Illsley, C T. 1955. A Geochemical Investigation of the Heavy Metal Content of the Streams in the Keno Hill – Galena Hill area, Yukon Territory. Geological Survey of Canada paper 54-18

Carne, R.C. 2004. Technical Report describing the exploration history, geology and gold-silver mineralization of the Mount Hinton property.

Carne, R.C. 2007. Technical Report describing geology, geochemistry, geophysics, diamond drilling and resource estimation at the Marg project.

Lynch, J.V.G. 1989. Large-scale hydrothermal zoning reflected in the tetrahedrite-freibergite solid solution, Keno Hill Ag-Pb-Zn district, Yukon. Canadian Mineralogist **27:**383-400.

Murphy, D.C. 1997. Geology of the McQuesten River region, northern McQuesten and Mayo map areas, Yukon Territory (115P/14, 15, 16: 105M/13, 14). Exploration and Geological Services Division, Yukon Region, Indian and Northern Affairs Canada, Bulletin 6, 122 p.

Noel, G.A. 1955. Northwestern Explorations Limited, Parent Creek Area, Yukon. Yukon Mining Recorder Report 17466.

Oullette, D.J. 1985. Report on the Mount Hinton area, 1984; assessment report prepared for United Keno Hill Mines Ltd.

Power, M.A. 1996. Duncan Creek Golddusters Ltd. Seismic refraction and reflection surveys on Duncan and Keystone creeks, Mayo area, Yukon Territory. Yukon Energy, Mines and Resources report 120169.

Ryan, S. 2004. Mayo regional soil survey report. YMIP report 04-044.

Thompson, M., Howarth, R.J. 1978. A new approach to the estimation of analytical precision. Journal of Geochemical Exploration **9(1):** 23-30.

Appendix B: Statement of Expenditures

STATEMENT OF EXPENDITURES
KEYSTONE PROPERTY
Fieldwork: May 30 - August 5, 2010

PROFESSIONAL FEES AND WAGES:

Darcy Baker, P.Geo.	1.26 days @	$650/day	$ 819.00	
Cameron Bartsch, Project Geologist	69.88 days @	$650/day	45,422.00	
Robin Black, P.Geo.	0.38 days @	$650/day	247.00	
Thomas Branson, Geologist	0.69 days @	$525/day	362.50	
Marcel Cercel, Cook/First Aid level III	19.00 days @	$500/day	9,500.00	
Louis Dessaints, Sampler	26.50 days @	$275/day	7,287.50	
Terry Graham, Sampler	53.50 days @	$275/day	14,712.50	
Oisin Kenny, Sampler	4.00 days @	$275/day	1,100.00	
Marilyn Livingston, Bull Cook	33.00 days @	$275/day	9,075.00	
Joe McCreery, Prospector	14.00 days @	$475/day	6,650.00	
Margot McKeown, Geologist	44.00 days @	$525/day	23,100.00	
Scott Parker, GIS/Logistics	14.00 hours @	$75/hour	1,050.00	
Neil Perk, Geologist	0.38 days @	$525/day	199.50	
John Robson, Sampler	44.50 days @	$275/day	12,237.50	
Edward Sinnot, Pad Builder	49.50 days @	$400/day	19,800.00	
Colin Slauenwhite, Project Manager	6.63 days @	$575/day	3,812.25	
Pete Smaluck, Sampler	22.00 days @	$275/day	6,050.00	
Dave Swanton, Project Geologist	36.25 days @	$650/day	23,559.50	
Dawn Thompson, Cook/First Aid level III	42.00 days @	$500/day	21,000.00	
William VanZanten, Prospector	40.27 days @	$475/day	19,129.00	
Tyler Woyiwada, Sampler	25.50 days @	$275/day	7,012.50	
Agata Zurek, GIS	7.50 hours @	$75/hour	562.50	
Clerical	72.00 hours @	$35/hour	2,520.00	$ 235,208.25

EQUIPMENT RENTALS

Field Camp				
	880 mandays @	$40/manday	$ 35,200.00	
Chainsaw				
	29 days @	$30/day	870.00	
Field Computers				
	176 days @	$40/day	7,040.00	
First Aid Equipment (Level III)				
	61 days @	$30/day	1,830.00	
Fuel Berm				
	2 days @	$15/day	30.00	
Generator (12kVA Diesel)				
	58 days @	$80/day	4,660.00	
Gas Coresaw				
	15 days @	$60/day	900.00	
Satellite Phones (Iridium)				
	11 weeks @	$75.00/wk	825.00	
	146 minutes @	$1.89/min	275.94	
Rental Truck Insurance				
	62 days @	$10/day	620.00	52,250.94

EXPENSES:

Chemical Analyses	$ 43,809.79
Field Equipment Repairs	57.15
Field Consumables	2,708.61
Materials and Supplies	18,561.13
Plot Charges	23.98
Camp Food	15,401.25
Meals	845.36
Accommodation	2,367.50
Taxis and Airporters	449.38
Truck Rental (Non-Equity)	12,214.29
Automotive Fuel	3,410.13
Automotive Expense	33.33
Aircraft Charters	6,847.75
Helicopter Charters	263,415.20
Telephone Distance Charges	0.92
Courier	14.69
Freight	21,650.39
Bulk Fuel	47,253.22
Drum Deposits	9,000.00
Geophysical Equipment Rental	975.00
Padbuilding	4,539.20
Satellite phone Rental (Non-Equity)	2,390.00
Radio Rental (Non-Equity)	3,127.00
Generator Rental (Non-Equity)	1,881.19
Excavator	450.00
Forklift	4,396.42
Drilling: Mob/Demob	5,000.00
Drilling: Footage	285,654.13
Drilling: Materials	31,156.59
Community/Permitting	900.00

Expediting	9,637.75	
Rent (other storage)	700.00	
Report (estimated)	3,000.00	801,871.35
SUB-TOTAL:		$1,089,330.54
PROJECT SUPERVISION CHARGES:		112,269.74
TOTAL:		**$1,201,600.28**

Appendix C: Rock Sample Descriptions

Sample ID	Easting	Northing	Lithology	PY%	ASP%	CP%	Comments
E855501	490424	7078793		TR		TR?	Quartz rock with bits of sulphide(Pyrite, Pyrrhotite and maybe Calco, Galena). Not much Gossan. Mineralization seems to be with small strands of chlorite altered rock?
E855502	490326	7078782					Similar to sample# 855501. Quartz veins in a schist type rock with trace Galena. Sample taken in subcrop.
E855503	490827	7076336					Rusty quartz with trace Galena and (Manganese/Spec Hem?)
E855504	489674	7077369					Skarn looking alteration/also looks a bit like a stockwork? Not much for sulphide.
E855505	489653	7077658					Large quartz boulder with nice alteration and weathering. Couldn't see much for sulphide.
E855506	491428	7079183		2	5		Nice quartz boulder with what I think is arsenopyrite.
E855507	491426	7079239					Rusty vuggy quartz. Couldn't see much sulphide, but is in line with sample # 855506 and looks similar.
E855508	491425	7079219		2	8		Same rock type as sample # 855506. Quartz rock with lots of arsenopyrite.
E855509	491676	7079484		Tr	1		Same quartz boulder and mineralization as 855506, 507, 508. Boulders are much harder and competent than other quartz veins in thearea.
E855510	491655	7079488		1	Tr		In the boulder train of sample # 855509.
E855511	491649	7079491		1	Tr		In the boulder train of sample # 855509.
E855512	491524	7079473		Tr	Tr		Similar rock to sample # 855509, 510, 511.
E855513	491525	7079472		3	?		
E855514	488043	7078448					Rusty weathered out (breccia?) looking stuff.
E855515	490911	7080086					Iron-strained schist from outcrop on top of the ridge
E855516	489815	7077725					Hematite-rich metagreywacke
E855517	489383	7077786					Black phyllite/slate from adjacent to a layer of yellow-red mud
E855518	493514	7076654					Rusty, druzzy quartz vein
E855551							Sample is not being submitted for assay - taken as a representative rock type.
E855552	491428	7079183	Phylitte		Tr?		Sample taken near float found with arsenopyrite. Carbonate alteration and

							possible mineralization.
E855553							Sample is not being submitted for assay - taken as a representative rock type.
E855554	491731	7079437	Schist		0.5		Vuggy quartz vein with grainy, black, vitreous material, possible mineralization. (MM036)
E855555	491174	7080262	Qtz Vein	Tr?	Tr?		Grey, granular, metalicblebs with limonite weathering around borders, possible mineralization.
E855556	491519	7080390	Qtz Vein		Tr?	Tr?	Grey, metalic mineralization (?) sample from intact 4ftx4ft intact qtz vein. See MM041
E855557	491764	7080853	Qtz Vein				Qtz vein with possible pyrrhotite. MM047
E855558	491609	7078872		Tr?			Schist hosted quartz vein with goethite(?)
E855559	490692	7077837	Graphitic phylitte and qzt vein	Tr			Qtz vein within highly altered graphitic mudstone with disseminated pyrite and abundant Fe-oxide staining
E855561	494852	7076866	QZ Vein		Tr		Possible scorodite indicating arsenopyrite
E855562	493817	7076797	Qz vein				Possible trace galena, found within 10m of the outcrop
E855563			Qz vein			Tr?	Need to get these coordinates possible trace chalco
E855564	487393	7078877	Qz Vein			Tr?	Vein within a hornsfeld host rock, has a sheen like chalco
E855565	487331	7078805	Qz-siderite vein			Tr?	Green-blue sheen possibly scorodite or trace chalco
E855566	488057	7077442	Qz Vein			TR?	Vein hosted in quartz sericite schist
E855567	488063	7077374	Qz vein		Tr?		Arseno in qtz vein hosted in sericite schist
E855568	487833	7076966	Qz Vein		Tr		Arseno or Manganese mneral along salvages of vein
E855569	487774	7076609	Qz vein		Tr?		Possible arseno
E855570	488086	7078997	Qtz-Sid vein		Tr?		Possibly arseno. in quartz siderite vein also botryoidal metalic mineral
E855571	488734	7077316			Tr?		Scorodite in qtz vein, possibly trace arseno.
E855572	488104	7077381	Qtz vein				Tetrahedrite and possibly an Sb oxide.
E855573	488129	7077295	Qtz vein				Tetrahedrite and possibly trace arseno
E855574	488123	7077353	Qtz vein				Tetrahedrite
E855575	488159	7077344	Qtz vein				Trace tetrahedrite in outcrop within fabric // qtz vein
E855576	492546	7079135	Qtz vein				Possible scorodite along the contact btwn limestone and phyllte

E855577	487401	7078785	Qtz-Siderite Vein				Goethite in quartz-siderite vein, may be mineralization.
E855578	488015	7078242	Qtz vein				Trace tetrahedrite in quartz boulder.
E855579	492727	7079544	Qtz vein				Fabric parallel qtz vein with Fe-oxide staining. Possible mineralization?
E855580	492801	7079280	Qtz-siderite vein				Fabric parallel qtz-siderite vein with abundnt Fe-oxide staining, possible mineralization (?).
E855581					Tr		From Longline, silver metalic mineral, likely arsenopyrite
E855582							From Longline. Abundant Fe-oxide staining, trace arsenopyrite.
E855601	490550	7078175		Tr			Near 1g/t soilanomaly. 5cm wide qz vein parallel to foliation in schist.
E855602	490487	7078354		3			Sulphide stringers along 060/75 faulte zone. 1-3 cm wide.
E855603	490492	7079016		3			Sugary pyrite in vuggy silica withing large gossan zone. Large zone of silicification.
E855604	491558	7080097	QZ vein	Tr			N-S striking zone of silicification, mainly Qz rubble. Trace Py and Ga
E855605	491398	7079514	QZ vein	Tr	3		Asp stringers in milky white quartz vein. Float, within 30 m of outcrop up slope
E855606	491398	7079514	QZ vein	0.5	10		Massive Asp in milky white QZ veins. 5 metres from above. Surrounded by lots of mineralized float - close to source.

Appendix D: Drill Logs

Abbreviations used in logs

Rock Types	Alteration and Mineralization	Features
CAS - Casing Brx – Breccia EOH – End of Hole GRNT – Granite MGWK – Metagreywacke MNDR – Monzodiorite PHYL – Phyllite QRZT – Quartzite SCHT - Schist	Apy – arsenopyrite Cal – calcite Chl – chlorite Fer – iron oxide Grp - graphite Po – pyrrhoitite Py – pyrite Ser – sericite Sid – siderite Sil – silca	Con – contact S1 – First generation fabric / relict bedding plane S2 – Second generation fabric V – Vein Fr – Fracture Ft - Fault

Note that alteration is measured on a relative scale of 1 – 4. The mineralization values shown are visual estimates of percent by volume.

Drill Log Legend

Breccia (BRX)

Casing (CAS)



Metagreywacke (MGWK)

Phyllite (PHYL)

Quartzite (QRZT)

Schist (SCHT)

EQUITY

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 4515.0
Hole KEY10-01	**Azimuth (º):** 325
Location: 7078105 m North, 490641 m East	**Dip (º):** -50.0
Logged by: M.McKeown	**Length (m):** 158.80
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: NTW	**Objective**
Date Started: 2010/06/06 **Date Completed:** 2010/06/14	Test for mineralization that is the source of a local soil anomaly of 1026.6 ppb Au along a Northerly trend that is observed both in anomalous, high Au soil sample results and the local structural geology which is thought to be controlling mineralization.
Dip Tests By:	

Summary Log:

4.57-15.22 Interlayered, foliated graphitic phyllite and metagreywacke with chlorite, sericite and muscovite alteration and trace disseminated pyrite and pyrrhotite focused in the graphitic phyllite.
15.22-15.34 Faulted and fractured zone ~100% fault gouge
15.34-52.35 Same interlayered graphitic phyllite and metagreywacke with similar alt.
52.35-55.35 Quartzite interlayered with metagreywacke with carbonate and chlorite alt.
55.35-77.67 Same interlayered graphitic phyllite and metagreywacke with similar alt.
77.67-79.29 Abundant fracturing and dry qtz veining in metagreywacke
79.29-88.72 Quartzite forming a more competent unit, trace py and po
88.72-111.35 Interlayered metagreywacke and phyllite with abundant fracturing and increase in disseminated py (still trace).
111.35-112.6 Foliated felsic dyke with slight compositional banding and sericite alt.
112.6-141 phyllite, highly fractured, increased chlorite alteration, greater py and po.
141-143.22 Foliated quartzite with abundant silica alt.
143.22-143.76 Graphitic phyllite with abundant chlorite alteration and trace py and po.
143.76-149.87 Quartzite, foliated with abundant silica and sericite alt.
149.87-152.54 phyllite with increased chlorite alteration and trace py and po.
152.54-157.28 Diorite (dyke), with little alteration and weak fabric relative to surrounding rocks.
157.28-157.79 Very magnetic fault gouge (high pyrrhotite content ~3%?).
157.79-158.8 phyllite with very abundant chlorite alteration and high po (~2%?)
158.8-158.8 End of Hole

Downhole surveys:

Depth	Dip	Azimuth
0.00	-50.00	325.00
158.80	-50.00	325.00

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
0.00	4.57	CAS
4.57	5.79	MGWK
		Foliated, sericite and muscovite altered, Interlayered siltstone and mudstone with mm to cm scale quartz veining that contains minor pyrite. < @ 19.00 S1 45.00° > < @ 19.00 lam 45.00° > < @ 15.60 Quartz (bull) wih some sulphide staining V 9.00in > < @ 19.00 Qtz veins along foliation V 0.10-4.00cm > « 15.60 - 19.00 mus » « ser 2.00» « within mm scale qtz veins along foliation py 1.00-2.00%
5.79	13.82	PHYL
		Foliated (schistose), carbonate, chlorite, muscovite and sericite altered finely laminated interbedded metagreywacke and phyllite with abundant cm scale quartz veins along foliation and rare, fine diseminated pyrite focused within chlorite < @ 13.82 mm to cm scale lam 45> < @ 13.82 S1 45° > < @ 13.82 Qtz veins (dry) along foliation, some pinched out. V 0.50-7.00cm > « bands of carbonate alteration following foliation cal 3.00» « mus 1.00» « blebs and strings following foliation, associated with quartz veins chl 1.00» « ser 1.00» « Rare, disseminated, focused in zones of chlorite alteration. py 0.10%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
4.57	6.07	E856001	0.01	0.20	5.00	31	56
4.57	6.07	E856002					
6.07	7.57	E856003	0.01	0.20	6.00	32	72
7.57	9.07	E856004	0.01	0.20	4.00	25	94
9.07	10.57	E856005	0.01	0.20	2.00	12	76
10.57	12.07	E856006	0.01	0.20	4.00	17	64
12.07	13.57	E856007	0.01	0.20	3.00	15	64

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
13.82	14.99	PHYL
		Foliated (schistose), interlayered phyllite>metagreywacke with chlorite, sericite, muscovite and carbonate alteration. htense, thick quartz veining cuts foliation, comprising 55% of the section. There are rusty weathering carbonate veinlets along foliation and rare, fine disseminated pyrite.
		< @ 14.99 mm scale lam 45 >
		< @ 13.82 S1 45° >
		< @ 13.82 Thick qtz (bull) cutting foliation V 55.00% >
		« abundant throughout chl 2.00»
		« ser 2.00»
		« in veinlets and bands with foliation cal »
		« mus 2.00»
		« rare, diseminated py 0.20%»
14.99	15.22	PHYL
		Foliated phyllite with abundant cm scale qtz-carbonate veins along foliation. Carbonate, sericite and chlorite alteration with rare diseminated pyrite.
		< @ 15.22 S1 45>
		< @ 15.22 Qtz-carbonate, along foliation V 1.00-3.00cm >
		« bands and strings throughout cal 3.00»
		« ser 1.00»
		« chl 2.00»
		« mus 1.00»
		« py 0.10%»
15.22	15.34	PHYL
		Rubble, with 30% of total rock fragments recovered
		< @ 15.22 Ft 12.00cm >
15.34	18.42	PHYL
		Foliated (schistose) phyllite > metagreywacke. Chlorite, muscovite, sericite, carbonate alteration with very rare diseminated pyrite. Moderately abundant mm scale, foliation parallel quartz veinlets with lessr mm to cm scale quartz



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
13.57	15.07	E856008	0.01	0.20	2.00	11	35
13.57	15.07	E856009					
13.57	15.07	E856010					
15.07	17.57	E856011	0.01	0.20	2.00	19	37
17.57	19.07	E856012	0.01	0.20	2.00	31	69

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
		veinlets cross-cutting foliation.
		< @ 18.42 S1 45.00° >
		< @ 15.34 qtz, following foliation V 15.00% 2.00-20.00mm >
		< @ 17.88 qtz V 13.00cm >
		« chl 2.00*»
		« ser 1.00*»
		« mus 1.00%»
		« mm scale bands along foliation cal 1.00*»
		« rare, disseminated py 0.10%»
18.42	23.19	MGWK
		Foliated (schistose), finely laminated (mm scale) graphitic metagreywacke > phyllite. Chlorite, carbonate, muscovite alteration. Abundant mm scale, blebby veinlets of carbonate alteration parallel to foliation.
		< @ 23.19 graphitic phyllite mm scale lam 45>
		< @ 23.19 S1 45° >
		« chl 3.00*»
		« abundant banding // to foliation cal 3.00*»
		« mus 1.00*»
23.19	24.46	MGWK
		Foliated (schistose), finely laminated (mm scale) metagreywacke>phyllite. Abundant carbonate alteration in bands parallel to foliation, chlorite, sericite and muscovite alteration. Very rare diseminated pyrite.
		< @ 24.46 lam 45° >
		< @ 23.19 S1 45° >
		« cm scale bands // to foliation cal 3*»
		« chl 2.00*»
		« ser 2.00*»
		« mus 1.00°»
		« py 0.10%»
24.46	32.27	PHYL
		Foliated, laminated phyllite > metagreywacke with minor crenulations. Abundant bands of carbonate alteration parallel to foliation, abundant chlorite alteration with lesser muscovite and sericite alterion. Quartz veins up to 5cm in foliation parallel bands but more so in blebs that do not follow foliation.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
19.07	20.57	E856013	0.01	0.20	2.00	35	67
20.57	22.07	E856014	0.01	0.20	2.00	16	75
22.07	23.57	E856015	0.01	0.20	2.00	23	56
23.57	25.07	E856016	0.01	0.20	2.00	16	54
25.07	26.57	E856017	0.01	0.20	3.00	13	64
26.57	28.07	E856018	0.01	0.20	3.00	19	59
28.07	29.57	E856019	0.01	0.20	5.00	18	56
29.57	31.07	E856020	0.01	0.20	6.00	29	72

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
		Rare disseminated pyrite in fine stringers along foliation. < @ 24.46 lam 45º > < @ 24.46 S1 45° > < @ 24.46 qtz blebs V 2.00-5.00cm > « abundant banding // to foliation cal 3.00*» « chl 2.00*» « mus 1.00*» « ser 1.00*» « py 0.10%»
32.27	44.90	MGWK
		Foliated and finely laminated (mm to cm scale) graphitic metagreywacke>phyllite with lesser interlayered quartzite? and 2-16cm quartz veins and blebs, some following foliation and some cutting it. Very abundant chlorite alteration with lesser sericite and minimal muscovite alteration. Minor crenulations occur. Minor diseminated pyrite preferentially along quartz vein salvages, trace arsenopyrite in quartz veins and trace pyrrhotite forming small blebs preferentially within chlorite alteration. < @ 44.90 Qtz veins and blebs V 20.00% 2.00-16.00cm > < @ 44.90 mm to cm scale lam 45º > < @ 44.90 S1 45° > < @ 44.90 Crenulation Sc 70º > « chl 3.00*» « preferentially altering more coarse interlayers? ser 1.00*» « mus 1.0 « veins crosscutting quartz veins cal 1.00-2.00cm» « py 0.30%» « small blebs po 0.10% 1.00-2.00mm» « trace apy 0.10%»
44.90	46.61	PHYL
		Foliated, laminated phyllite>metagreywacke with highly altered with bands of



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
31.07	32.57	E856021	0.01	0.20	5.00	23	80
31.07	32.57	E856022					
32.57	34.07	E856023	0.01	0.20	2.00	32	102
34.07	35.57	E856024	0.01	0.20	4.00	49	91
35.57	37.07	E856025	0.01	0.20	7.00	14	94
37.07	38.57	E856026	0.01	0.20	2.00	20	88
38.57	40.07	E856027	0.01	0.20	2.00	18	80
40.07	41.57	E856028	0.01	0.20	3.00	15	92
40.07	41.57	E856029					
40.07	41.57	E856030					
41.07	42.57	E856031	0.01	0.20	6.00	22	90
42.57	44.07	E856032	0.01	0.20	2.00	17	72
44.07	45.57	E856033	0.01	0.20	2.00	23	36
45.57	48.07	E856034	0.01	0.20	2.00	18	50

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
		chlorite and carbonate alteration along foliation. Moderately abundant quartz veins along foliation and blebs (cm scale). Trace pyrite. < @ 46.61 lam 45°> < @ 46.61 S1 45° > < @ 46.61 quartz veins and crosscuting blebs V 2.00-4.00cm > « chl 3.00*» « mus 1.00*» « cal 3.00*» « along foliation py 0.20%»
46.61	50.43	PHYL Highly foliated, fissile graphitic phyllite. Moderatly abundant mm scale bands of chlorite and carbonate alteration and abundant iron oxide staining along foliation. Minor cm scale quartz veins along foliation, minor mm scale calcite veins cross cutting foliation and quartz veins. < @ 46.61 S1 50° > < @ 46.61 qtz V 1.00-4.00cm > < @ 50.00 fault gouge Ft 43.00cm > « band of alteration cal 2.00*» « chl 2.00*» « mus 1.00*» « py 0.10%»
50.43	52.35	PHYL Laminated,foliated phyllite>metagreywacke with variable chlorite, carbonate, silica alteration and distinct iron oxide staining along foliation. Primary textures (laminations) have been disturbed by alteration of carbonate, chlorite and quartz forming blebs and bands. < @ 50.43 lam 50°> < @ 50.43 S1 50° > « bands and blebs chl 2.00*» « cal 2.00*» « mus 1.00*» « pervasive sil 1.00*» « py 0.10%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
48.07	49.57	E856035	0.01	0.20	2.00	18	46
49.57	51.07	E856036	0.01	0.20	4.00	17	32
51.07	52.57	E856037	0.01	0.20	5.00	32	45

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
52.35	55.35	QRZT
		Foliated (schistose), laminated quartzite and metagreywacke with abundant carbonate alteration and chlorite alteration. Pyrrhotite preferentially occuring as thin stringers along foliation within the greywacke.
		< @ 55.35 S1 45° >
		< @ 52.35 lam 45º >
		< @ 52.35 quartz veins and blebs V 1.00-3.00 >
		« cal 3.00*»
		« alteration of graphitic siltstone chl 2.00*»
		« mus 1.00*»
		« pervasive sil 1.0
		« po 0.20%»
		« py 0.20%
55.35	69.54	MGWK
		Foliated (schistose), laminated (2-16cm thick interlayers) metagreywacke>quarztite>phyllite. Silica, muscovite and lesser sericite alteration dominated the quartzite and metagreywacke layers and chlorite alteration dominates the graphitic/muddy layers. Pyrite is diseminated throughout and in fine stringers along foliation. Pyrrotite is also diseminated and in stringers along foliations. Possibly trace arsenopyrite along the salvages of quartz veins and blebs. Quartz veins occur along foliation as well as in blebs not folowing foliation.
		< @ 69.54 S1 45.00° >
		< @ 69.54 lam 45.00º >
		« favorably of the quartzite interlayers sil 2.00*»
		« favorably altering graphitic interlayers chl 2.00*»
		« mus 2.00*»
		« ser 1.00*»
		< @ 69.54 V Quartz 3.00-6.00cm >
		« disseminated and fine stringers py 0.50%»
		« disseminated and fine stringers pyr 0.5»
69.54	70.80	MGWK
		Schistose metagreywacke with a quartz vein (120cm) cutting foliation with



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
52.57	54.07	E856038	0.01	0.20	3.00	16	74
54.07	55.57	E856039	0.01	0.20	4.00	18	42
55.57	57.07	E856040	0.01	0.20	4.00	17	34
57.07	56.72	E856041	0.01	0.20	2.00	26	36
57.07	58.57	E856042					
58.57	60.07	E856043	0.01	0.20	5.00	18	35
60.07	61.57	E856044	0.01	0.20	7.00	25	35
61.57	63.07	E856045	0.01	0.20	12.00	19	28
63.07	64.57	E856046	0.01	0.20	47.00	20	32
64.57	66.07	E856047	0.01	0.20	4.00	22	48
66.07	67.57	E856048	0.01	0.20	7.00	23	60
66.07	67.57	E856049					
66.07	67.57	E856050					
67.57	69.07	E856051	0.01	0.20	28.00	30	68
69.07	70.57	E856052	0.01	0.20	24.00	28	44
70.57	72.07	E856053	0.05	0.20	767.00	35	100

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
		abundant chlorite, muscovite, sericite and lesser carbonate alteration of the schist on either side of the vein. Pyrite is trace at best.
		< @ 70.80 Quartz cross cutting foliation V 90.00% 120.00cm >
		« ser 2.00*»
		« chl 2.00*»
		« blebs cutting qtz vein cal 2.00*»
		« mus 2.00*»
		« trace disseminated py 0.10%»
70.80	76.94	MGWK
		Foliated (schistose), laminated metagreywacke>quartzite>phyllite. Abundant sericite, chlorite, muscovite alteration with moderatly abundant foliation parrallel and cross cuting quartz veins. Fine diseminated pyrite throughout and slightly larger ~1-2mm disseminations of pyrrhotite both in trace amounts. There is Fe-oxide staining along fracture surfaces.
		< @ 76.94 lam 50.00º >
		< @ 70.80 S1 50.00° >
		< @ 70.80 Quartz V 2.00-15.00cm >
		« chl 2.00*»
		« mus 1.00*»
		« ser 2.00*»
		« py 0.10%»
		« pyr 0.50%»
76.94	77.67	PHYL
		Highly foliated (schistose), interlayered phyllite>quartzite with abundant chlorite and sericitie alteration and mm scale quartz veining along foliation. Trace diseminated pyrite throughout.
		< @ 77.67 lam 50.00º >
		< @ 77.67 S1 50.00° >
		« chl 2.00*»
		« ser 2.00*»
		« py 0.10%»
77.67	79.29	MGWK



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
72.07	73.57	E856054	0.01	0.20	70.00	14	116
73.57	75.07	E856055	0.05	0.80	727.00	20	35
75.07	76.57	E856056	0.03	0.30	535.00	19	63
76.57	78.07	E856057	0.01	0.20	26.00	13	38

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
		Section of foliated, interlayered metagreywacke with abundant fracturing and quartz veining some of which follows foliation and some of which cuts it. There is abundant Fe-oxide staining along the fracture surfaces. « 77.67- 77.94 small zone of fault gouge flt 20.00%» < @ 77.67 S1 50.00° > < @ 79.29 quartz V 3.00-8.00cm > « chl 2.00*» « ser 1.00*»
79.29	88.72	QRZT
		Foliated (schistose) interlayered quartzite>phyllite with zones of variable siica, chlorite, muscovite and carbonate alteration of the quartzite and dominately chlorite alteration of the phyllite. Quartz veining variably follows foliation and cross cuts foliation. Carbonate alteration occurs along the salvages of quartz veins. < @ 79.29 lam 50.00° > < @ 79.29 S1 50.00° > < @ 79.29 Quartz V 2.00-7.00cm > « chl 2.00*» « mus 1.00%» « Along salvages of vuggy qtz veins cal 1.00*» « of quartzite layers sil » « disseminated py 0.10%» « pyrrhotite po 0.10%»
88.72	99.43	MGWK
		Foliated (schistose), laminated metagreywacke>quartzite>phyllite with moderatly abundant to abundant cm scale quartz veining both along foliation and cutting foliation. The lower 4.8m of this section is extremely faulted with broken rock and fault gouge dominating. The upper portion of this section is silica altered and also altered with muscovite, chlorite and sericite. There is carbonate alteration that is restricted to near the faulted zone. The carbonate alteration occurs with quartz veins, along the salvages or as blebs all occuring after the quartz veining. Textures in this section suggest multiple stages of alteration with quartz veins occuring first followed by seams of chlorite that roughly follow along foliation and in the sane direction as the quartz veins. Both the quartz veins and strings of chlorite are cut by mm



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
78.07	79.57	E856058	0.01	0.20	22.00	22	34
79.57	81.07	E856059	0.01	0.20	19.00	35	65
81.07	82.57	E856060	0.01	0.20	16.00	25	64
82.57	84.07	E856061	0.01	0.20	10.00	19	56
82.57	84.07	E856062					
84.07	85.57	E856063	0.01	0.20	6.00	21	36
85.57	87.07	E856064	0.01	0.20	8.00	31	73
87.07	88.57	E856065	0.01	0.20	39.00	21	51
88.57	90.07	E856066	0.15	0.20	1110.00	22	74
90.07	91.57	E856067	0.01	0.50	126.00	14	50
91.57	93.07	E856068	0.01	0.60	43.00	20	53
91.57	93.07	E856069					
91.57	93.07	E856070					
93.07	94.57	E856071	0.39	7.80	3690.00	31	82
94.57	96.07	E856072	0.01	0.20	66.00	34	57
96.07	98.07	E856073	0.01	0.20	19.00	26	80

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description

scale veinlets of sericite(?(see 90.58m). Crenulations demonstrate multiple stages of deformation. Sparse disseminated pyrite and pyrrhotite.

< @ 99.43 lam 45.00° 2.00-30.00mm >
< @ 99.43 S1 45.00° >
< @ 99.43 at 91.54m S2 62.00° >
< @ 94.64 -99.43 with fault gouge Ft 70.00% 4.79m >
< @ 99.43 Quartz V 2.00-12.00cm >
« sil 2.00*»
« chl 2.00*»
« mus 1.00*»
« ser 1.00*»
« py 0.20%»
« po 0.10%»

99.43 111.35 PHYL

Foliated, laminated phyllite>metagreywacke with extensive chlorite alteration throughout as well as limited zones of high silica alteration in which there are also abundant cm scale quartz veins. There is a great deal of faulting, particullarly in the lower 6m of this section. Sericite alteration occurs preferentially along the salvages of quartz veins. The majority of the quartz veins follow foliation though some also cut it. There is a great deal of faulting with fault gouge in the lower portion of this section. There are two veins that are off-white with a green tinge that may be composed of sericite with chlorite or perhaps K-spar with chlorite. These veins cut foliation and quartz veins. Pyrite ocurs as thin stringers along foliation. Pyrrhotite seems to occur preferentially in stringers of sericite alteration.

< @ 111.35 S1 45.00° >
< @ 111.35 lam 45.00° >
< @ 105.00 Fault gouge dominates Ft 46.00cm >
< @ 106.27 dominated by fault gouge Ft 4.37m >
< @ 99.43 quartz V >
< @ 106.24 Sericite V 30.00>
< @ 105.28 Sericite V 38.00° >

« chl 3.00*»
« sil 2.00*»
« mus 1.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
98.07	100.57	E856074	0.01	0.90	8.00	15	95
100.57	103.07	E856075	0.01	0.20	14.00	18	76
103.07	104.57	E856076	0.01	0.30	25.00	21	70
104.57	106.07	E856077	0.11	0.20	974.00	17	62
106.07	107.57	E856078	0.01	0.20	31.00	14	59
107.57	109.57	E856079	0.01	0.20	33.00	10	43
109.57	111.07	E856080	0.09	0.40	586.00	14	77

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
		« ser 1.00*»
		« po 0.50%»
		« thin stringers along foliation py 1.00%»
111.35	112.60	GRNT
		Highly foliated quartz rich, felsic dyke(?) with slight compositional banding. Alteration has overprinted much of the primary textures leading to some uncertainty identifying this unit. Much of the feldspar has altered to sericite and the mafic components are chlorite altered. There are fractures in the core above and below the contacts for this unit.
		< @ 112.60 S1 35.00° >
		« ser 2.00*»
		« chl 1.00*»
112.60	141.00	PHYL
		Foliated (schistose), laminated phyllite>metagreywacke>quartzite with extensive chlorite alteration and significant fractured and faulted zones. Quartz veins occur in limited zones. Pyrite and pyrrhotite are fairly consistent throughout as disseminations and blebs in the graphitic layers that have chlorite alteration and lesser sericite alteration. There are two zones with cross cutting quartz veins, adjacent to these veins in the graphitic host rock there is a greater abundance of pyrite
		< @ 112.60 fractured rocks and fault gouge Ft 65.00% 3.79m >
		< @ 135.76 fractured rock Ft 70.00% 2.43m >
		< @ 141.00 quartz V
		< @ 119.38 cross cutting quartz veins V 1.57m >
		< @ 122.54 cross cutting quartz veins V 13.00cm >
		< @ 132.56 cross cutting veins silica and chlortie V 22.00cm >
		« chl 3.00*»
		« ser 1.00*»
		« mus 1.00*»
		« adjacent to qtz veins sil 1.00*
		« py 2.00%»
		« po 1.00%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
111.07	112.57	E856081	0.07	0.80	480.00	24	65
111.07	112.57	E856082					
112.57	114.07	E856083	0.01	0.20	4.00	22	70
114.07	115.57	E856084	0.01	0.20	50.00	18	51
115.57	117.57	E856085	0.22	0.50	2130.00	13	33
117.57	119.57	E856086	0.46	0.30	2260.00	31	82
119.57	121.57	E856087	0.01	0.30	16.00	76	69
121.57	123.07	E856088	0.01	0.20	5.00	17	61
121.57	123.07	E856089					
121.57	123.07	E856090					
123.07	124.57	E856091	0.01	0.20	17.00	15	47
124.57	126.07	E856092	0.01	0.20	2.00	14	79
126.07	127.57	E856093	0.01	0.20	2.00	22	78
127.57	129.07	E856094	0.01	0.30	47.00	22	74
129.07	130.57	E856095	0.01	0.20	8.00	17	66
130.57	132.07	E856096	0.01	0.20	12.00	10	72
132.07	133.57	E856097	0.01	0.20	22.00	11	49
133.57	135.57	E856098	0.01	0.20	3.00	11	42
135.57	137.57	E856099	0.01	0.20	8.00	15	44
137.57	139.57	E856100	0.01	0.20	3.00	17	57

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
141.00	143.22	QRZT
		Foliated (schistose) quartzite with silica ,sericite and lesser chlorite alteration. Very rare, fine diseminated pyrite. The sericite alteration gives a speckled appearance in zones.
		< @ 143.22 S1 35.00° >
		« sil 2.00*»
		« ser 2.00*»
		« chl 1.00*»
		« py 1.00%»
143.22	143.76	PHYL
		Foliated (schistose) and laminated graphitic phyllite>metagreywacke with chlorite and sericite alteration and a large cross cutting quartz vein. Pyrite and pyrrhotite occur along foliation. The relationship with the upper and lower units is not clear due to fluid alteration. The unit is fractured at its upper and lower contacts.
		< @ 143.32 cross cutting quartz (lesser sericite and chlorite) V 22.00cm >
		@ 143.76 S1 40.00° >
		< @ 142.40 S1 // qtz veins with sericite altered salvages V 11.00cm >
		« chl 3.00*»
		« ser 2.00*»
		« sil 1.00*»
		« po 0.50%»
		« py 0.50%»
143.76	149.87	QRZT
		Moderately foliated quartzite(?) with abundant silica alteration and lesser sericite, chlorite and muscovite alteration. The unit appears speckled due to both the presence of sericite alteration and mm scale mafic minerals that are altered enough that they cannot be specifically identified. This unit is distinct in that it is more coherant than the graphitic foliated unit. There are zones with large cross cutting quartz veins. Very sparse disseminated



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
139.57	141.07	E856101	0.01	0.20	2.00	11	25
139.57	141.07	E856102					
141.07	143.07	E856103	0.01	0.20	2.00	11	12
143.07	145.07	E856104	0.01	0.30	2.00	57	21
145.07	145.07	E856105	0.01	0.20	2.00	16	13
147.07	149.07	E856106	0.01	0.20	2.00	11	13

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
		pyrite.
		< @ 149.87 Weak S1 50.00° >
		< @ 146.51 cross cutting quartz V 32.00 >
		« chl 1.00*»
		« sil 2.00*»
		« ser 2.00*»
		« mus 1.00%»
		« py 0.10%»
149.87	152.54	PHYL
		Foliated, laminated phyllite>quartzite with abundant chlorite alteration and foliation parallel quartz veining. This unit is interlayered with the above quartzite with the mafic minerals. There is sericite alteration focused in the quartzite layers. Trace disseminated pyrite and pyrrhotite.
		< @ 149.87 Graphitic mudstone and quartzite lam 45.00º 1.00-3.00cm >
		< @ 150.25 S1 45.00° >
		< @ 150.25 Foliation // and cross cutting quartz V 1.00-2.00cm >
		« chl 3.00*»
		« ser 1.00*»
		« within quartzite layers sil 1.00*»
		« py 0.10%»
		« po 0.10%»
152.54	157.28	MNDR
		Highly silicified monzo-diorite (?) dyke. Primary textures have been erased by alteration however remnant mm scale pyroxene(?) crystals can be seen and the unit is far more competant than the other rock units in this hole, it is very weakly foliated. The unit is dark grey with fine white specks which are likely sericite alteration of feldspar. Overall this unit has far less quartz veining than the metasedimentary package. There is quartz veining near the bottom contact where the unit transition into fault gouge. No mineralization.
		« sil 2.00*»
		« ser 1.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
149.07	151.07	E856107	0.01	0.20	2.00	9	14
151.07	152.57	E856108	0.01	0.20	2.00	9	33
151.07	152.57	E856109					
151.07	152.57	E856110					
152.57	154.07	E856111	0.01	0.70	14.00	44	110
154.07	155.57	E856112	0.01	0.20	2.00	12	18
155.57	157.07	E856113	0.01	0.20	2.00	13	19

Project: Keystone **Hole Number:** KEY10-01

From	To	Rocktype & Description
		« mus 1.00*»
		« only by lower contact chl 1.00*»
157.28	157.79	PHYL
		100% fault gouge that is very magnetic. Likely pyrrhotite has been concentrated as other minerals weather out.
		« fault gouge flt 100.00
		« po 4.00%»
		« py 1.00%»
157.79	158.80	PHYL
		Graphitic phyllite with interbeds of quartzite. The phyllite is magnetic due to pyrrhotite content.
		< @ 158.17 cross cutting quartz V 10.00cm >
		« of graphitic layers chl 2.00*»
		« of quarztite layers sil 2.00*»
		« of quartzite layers ser 1.00*»
		« py 1.00%»
		« fine elongate blebs along foliation po 2.00%»
158.80	158.80	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
157.07	158.57	E856114	0.02	3.20	117.00	13	52
158.57	158.80	E856115	0.03	0.50	287.00	31	54

EQUITY

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 4515.0
Hole KEY10-02	**Azimuth (º):** 325
Location: 7078105 m North, 490641 m East	**Dip (º):** -70.0
Logged by: C.Bartsch	**Length (m):** 219.50
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: NTW	**Objective**
Date Started: 2010/06/14 **Date Completed:** 2010/06/18	Test for mineralization that is the source of a local soil anomaly of 1026.6 ppb Au along a Northerly trend that is observed both in anomalous, high Au soil sample results and the local structural geology which is thought to be controlling mineralization.
Dip Tests By:	

Summary Log:

3.5 - 7.85 strongly foliated phyllite and 40% metagreywacke interbeds,
7.85 - 11.45 Quartzite with laminated phyllite interbeds. Moderate carbonate alteration of quartzite beds.
11.45 - 14.9 metagreywacke to laminated phyllite. 3% quartz veining paralel to foliation.
14.9 - 18.75 Carbonate alterred quartzite with phyllite and quartz carbonate veins. Phyllite is chloritized.
18.75 - 24.5 phyllite with interbedded metagreywacke. 25% quartz veins. Phyllite contains blebs of pyrrhotite
24.5 - 32.68 Iterbedded metagreywacke/phyllite, classic turbidite sequence. Alteration as above.
32.68 - 37.5 Fault altered rock. Sandstone layers have heavy carbonate alteration.
37.5 - 42.05 Carbonate altered quartzite with minor phyllite beds. Limonite alteration surrounds phyllite layers.
42.05 - 55.78 moderately silicified interbedded metagreywacke/phyllite. Fracture surfaces are graphitic
55.78 - 69 Interbedded meatagreywacke and phyllite. phyllite is graphitic. pyrite + pyrrhotite disseminated throughout.
69 - 81.7 metagreywacke grading to quartzite with no phyllite and minor quartz veins
81.7 - 95.3 quartzite, metagreywacke and phyllite with blebs of pyrrhotite in phyllite layers
95.3 - 113.5 Highly faulted graphitic phyllite with brecciated quartz veins and minor beds of quartzite.
113.5 - 116.5 phyllite with minor metagreywacke and quartz veins
116.5 - 123.5 silicified metagreywacke/phyllite with a layer of corase quartzite, silicified and containing abundant quartz eyes
123.5 - 138 dominantly graphitic phyllite with a 3m bed of metagreywacke
138 - 147 silicified metagreywacke with small phyllite interbeds
147 - 151.8 faulted graphitic phyllite with minor metagreywacke, cut by foliation-paralel quartz veins, as above
151.8 - 180.6 interbedded metagreywacke/phyllite cut by two generations of quartz/carbonate veins.
180.6 - 192 Silicified quartzite(?) with 0.5-cm scale blue-grey quartz eyes.
192 - 219.51 Interbedded metagreywacke/phyllite with abundant quartz veins. Same as rest of hole
219.51 EOH

Downhole surveys:

Depth	Dip	Azimuth
0.00	-70.00	325.00
219.50	-70.00	325.00

Project: Keystone **Hole Number:** KEY10-02

From	To	Rocktype & Description
0.00	3.50	CAS
		Casing
3.50	7.85	PHYL
		Strongly foliated phyllite with approx. 10% foliation parallel quartz veins. 40% silt/sandstone interbeds. 1% disseminated fe-oxides, likely after fe carbonates.
		< @ 6.60 Possiblly primary S1 46.00° >
		< @ 7.10 quartz with minor carb in fractures- typical in unit V 45.00º 11.00cm >
		< @ 7.44 S1 75.00° >
		< @ 7.85 lower contact con 60.00° >
7.85	11.45	MGWK
		Metagreywacke with finely laminated phyllite interbeds. Coarser layers have undergone moderate carboate alteration (calcareous sandstone?). Reduction in veining(2% overall) relative to mudstone above.
		« cal 3.00*»
		« localized in sandstone intervals ser 1.00*»
		« around minor veining chl 1.00*»
		< @ 8.40 ss/mudstn contact S1 45.00° >
		< @ 8.73 cross-cutting quartz-fe carb veinlet V 25.00º 5.00mm >
		< @ 10.05 foliation cutting main tend S2 70.00º >
		< @ 11.45 6 cm coarse gouge Ft 52.00º 60.00mm >
		< @ 11.75 con 56.00° >
11.45	14.90	MGWK
		Metagreywacke with local finely laminated phyllite. Weak serecite throughout, but preferential to certain layers. Approzimately 3% deformed quartz veining, all foliation //.
		« ser 1.00*»
		« small patchy blebs throughout cal 1.00*»
14.90	18.75	QRZT
		Carbonate altered quartzite with minor laminations of metagreywacke/phyllite. White speckly (carbonate) appearance with dark green/grey colour in mudstone (chlorite). Only 2% concordant quartz veining and minor cross cutting quartz-carb veinlets.
		< @ 15.95 concordant quartz vein V 50.00º 55.00mm >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
3.50	5.00	E856116	0.01	0.20	4.00	23	58
5.00	6.50	E856117	0.01	0.20	4.00	33	82
6.50	8.00	E856118	0.01	0.20	9.00	17	70
8.00	9.50	E856119	0.01	0.30	3.00	11	56
9.50	11.00	E856120	0.01	0.20	2.00	11	43
9.50	11.00	E856121					
11.00	12.50	E856122	0.01	0.20	2.00	15	42
12.50	14.00	E856123	0.01	0.20	2.00	15	46
14.00	15.50	E856124	0.01	0.30	2.00	12	56
15.50	17.00	E856125	0.01	0.20	2.00	13	47
17.00	18.50	E856126	0.01	0.30	5.00	15	58

Project: Keystone **Hole Number:** KEY10-02

From	To	Rocktype & Description
		< @ 16.12 crosscuts foliation. Qz-Carb V 28.00º >
		« py 0.10%»
		« cal 3.00*»
18.75	24.50	PHYL
		phyllite with interbedded metagreywacke laminations. 25% deformed quartz
		veining. Weak carbonate alteration, localized in more sandy intervals. Dark
		grey/green colour. Small belbs of pyrrhotite located throughout, restricted to
		mudstone intervals. One dark black Po+Qz+? vein at 23.68
		« chl 1.00*»
		« 18.75- 23.65 po 0.50%»
		« py 0.10%»
		« 23.65- 23.70 po 1.00%»
		« 23.70- 24.50 po 0.10%»
		< @ 23.68 Dark black Po vein, possible sulphosalts V 48.00º 5.00mm >
24.50	32.68	MGWK
		lterbedded metagreywacke, classic turbidite sequence. Alteration varies with
		rock type, but mainly consists of localized sericite, chlorite, and weak
		carbonate. Fe-oxides(likely after fe carb) increase downhole.
		< @ 26.75 S1 60.00° >
		< @ 25.56 cross-cutting vein V 35.00º 45.00mm >
		< @ 29.04 S1 45.00° >
		« 24.50- 26.60 po 0.50%»
		« py 0.50%»
		« 26.60- 32.68 po 0.10%»
		« py 0.10%»
32.68	37.50	PHYL
		Fault altered rock. Moderate limonite staining, particularly concentrated
		around mud intervals - gives very striped appearance. Stong carbonate
		alteration of sandstone intervals between mud layers and moderate chlorite
		around veins. More heavily altered rock contains tension gashes filled with Po
		, Py, Qz, and 0.5% possible needly Jamesonite from 34.75-37.5m. Two faults near
		bottom of interval likely responsible for most of alteration in unit.
		< @ 34.15 cross cutting quartz-carb vein V 12.00º 50.00 >
		< @ 35.40 S1 65.00° >
		< @ 35.90 3 cm fault gouge Ft 55.00º 30.00mm >< @ 36.34 6 cm of clay-rich
		gouge Ft 60.00º 60.00mm >
		« sil 1.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
18.50	20.00	E856127	0.01	0.20	5.00	13	61
20.00	21.50	E856128	0.01	0.20	4.00	15	79
20.00	21.50	E856129					
21.50	23.00	E856130	0.01	0.20	4.00	11	75
23.00	24.50	E856131	0.01	0.20	3.00	21	73
24.50	26.00	E856132	0.01	0.20	2.00	22	82
26.00	27.50	E856133	0.01	0.30	6.00	15	87
27.50	29.00	E856134	0.01	0.20	7.00	12	96
27.50	29.00	E856135					
29.00	30.50	E856136	0.01	0.20	3.00	11	93
30.50	32.00	E856137	0.01	0.20	6.00	12	71
32.00	33.50	E856138	0.01	0.20	3.00	24	72
33.50	35.00	E856139	0.01	0.30	3.00	11	49
35.00	36.50	E856140	0.01	0.30	2.00	16	59
35.00	36.50	E856141					

Project: Keystone **Hole Number:** KEY10-02

From	To	Rocktype & Description
		« chl 2.00*»
		« cal 2.00*»
		« hem 2.00%»
		« lim 3.00*»
		« ser 2.00*»
		< @ 35.24 Tension gash filled with qz and Po V 22.00° 5.00mm >
		< @ 37.10 S1 52.00° >
		< @ 37.33 cross cutting quartz carb vein V 18.00° 10.00mm >
		< @ 37.43 Late foliation with associated tension gashes S2 18.00° >
37.50	42.05	MGWK
		Carbonate altered metagreywacke, still has moderate amounts of limonite alteation around mudstone beds (after py?). Approx. 80% ss and 5% qz veining. Disseminated sulphides (pyrite and Po) throughout, and trace black needly mineral (jamesonite?).
		< @ 39.00 qz-carb-sulphide, cross-cutting V 18.00° 5.00mm < @ 39.75 S1 54.00° >
		« conc. in ss beds cal 3.00*»
		« ser 1.00*»
		« localized aroud mudstone lim 2.00*»
		« py 0.10%»
		« po 0.10%»
42.05	55.78	PHYL
		Interbedded seds that have undergone moderate degree of silicification leading up to a fault zone at 53.76m. Approx. 55% mud/siltstone, 35% ss, and 10% veining. Fracture surfaces are highly graphitic. Lack of carbonate and limonite relative to above. Greenish bleached appearance nearing fault zone with increase in blebby Po.
		< @ 45.55 cross cutting qz-carb vein V 20.00° 10.00 >
		< @ 42.05 Concordant quartz vein V 50.00° 3.00mm >
		< @ 46.44 late foliation with trace Po S2 40.00° >
		< @ 49.33 S1 60.00° >
		< @ 51.25 cross cutting veinlets with disseminated blebby Po V 34.00° 5.00mm >
		< @ 42.05 Quartz-Carb vein, fol // V 32.00° 65.00mm >
		< @ 53.76 10cm of clay rich gouge Ft 70.00° 100.00mm >
		< @ 53.25 Qz-chlorite-carb vein V 22.00° 15.00mm >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
36.50	38.00	E856142	0.01	0.20	2.00	15	39
38.00	39.50	E856143	0.01	0.30	2.00	14	35
39.50	41.00	E856144	0.01	0.20	3.00	14	34
41.00	42.50	E856145	0.01	0.20	3.00	17	35
42.50	44.00	E856146	0.01	0.30	2.00	17	29
44.00	45.50	E856147	0.01	0.20	3.00	16	22
45.50	47.00	E856148	0.01	0.20	5.00	16	31
45.50	47.00	E856149					
45.50	47.00	E856150					
47.00	48.50	E856151	0.01	0.20	2.00	21	33
48.50	50.00	E856152	0.01	0.20	2.00	19	47
50.00	51.50	E856153	0.01	0.20	2.00	20	51
51.50	53.00	E856154	0.01	0.20	4.00	21	59
53.00	54.50	E856155	0.01	0.20	2.00	46	114

Project: Keystone **Hole Number:** KEY10-02

From	To	Rocktype & Description
		< @ 55.40 S2 28.00° >
		« 42.05- 50.80 sil 2.00*»
		« 50.80- 55.78 sil 1.00*»
		« chl 2.00*»
		« 42.05- 49.85 mainly associated with mudstone po 0.50%»
		« 49.85- 53.76 blebby, in chlorite sections po 1.50%»
		« 53.76- 55.78 po 0.10%»
		« 42.05- 49.85 py 0.10%»
		« 49.85- 53.76 blebby py 1.00%»
		« 53.76- 55.78 py 0.10%»
55.78	69.00	PHYL
		Interbedded sandstone and phyllite. Patchy silicification and carbonate alteration throughout. Fol // quartz-carb-chlorite veining increase downhole, approx. 15% of overall unit. Limonite staining around quartz veins near bottom. Fine grained diss. Po and Py throughout. Phyllite moderately graphitic.
		« sil 1.00*»
		« cal 1.00*»
		« po 0.50%»
		« py 0.10%»
		< @ 59.70 cross-cutting qz-carb V 23.00° 7.00mm >
		< @ 55.78 bull white qz with secondary carb and chlorite V 38.00° 200.00mm >
		< @ 55.78 S1 50.00° >
		< @ 55.78 S1 65.00 >
		« chl 1.00*»
69.00	81.70	MGWK
		Light green, laminated/foliated metagreywacke. Approximately 5% quartz veins. Distinct lack of phyllite, minor coarser intervals grading to meta-sandstone.
		« ser 1.00*»
		« chl 2.00*»
		< @ 69.92 S1 55.00° >
		< @ 73.41 quartz-carb-chlorite vein V 45.00° 110.00mm
		< @ 74.60 S1 60.00° >
		< @ 77.52 6 cm gouge Ft 56.00° 60.00mm >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
54.50	56.00	E856156	0.01	0.20	2.00	25	68
56.00	57.50	E856157	0.01	0.20	2.00	10	56
57.50	59.00	E856158	0.01	0.20	2.00	20	41
59.00	60.50	E856159	0.01	0.20	2.00	21	34
60.50	62.00	E856160	0.01	0.20	2.00	20	39
62.00	63.50	E856161	0.01	0.20	2.00	25	46
62.00	63.50	E856162					
63.50	65.00	E856163	0.01	0.30	5.00	16	28
65.00	66.50	E856164	0.01	0.20	2.00	22	32
66.50	68.00	E856165	0.01	0.30	2.00	13	33
68.00	69.50	E856166	0.01	0.20	3.00	15	52
69.50	71.00	E856167	0.01	0.20	4.00	33	65
71.00	72.50	E856168	0.01	0.20	8.00	19	62
71.00	72.50	E856169					
71.00	72.50	E856170					
72.50	74.00	E856171	0.01	0.20	4.00	11	62
74.00	75.50	E856172	0.01	0.20	5.00	15	50
75.50	77.00	E856173	0.01	0.20	4.00	19	26
77.00	78.50	E856174	0.01	0.20	2.00	19	52
78.50	80.00	E856175	0.01	0.20	13.00	35	89

Project: Keystone **Hole Number:** KEY10-02

From	To	Rocktype	& Description
			< @ 77.64 quartz V 55.00º 100.00 >
			< @ 79.66 S1 65.00° >
			< @ 81.16 foliation parellel quartz/carbonate V 50.00º 15.00 >
81.70	95.30	MGWK	
			55% metagreywacke, 35% phyllite, 10% qtz/carbonate veins
			metagreywacke is generally silicified or carbonitized
			phyllite is slighlty graphitic
			minor chloritization in phyllite
			disseminated fine grained blebs concentrated in phyllite layers
			< @ 82.15 S1 60.00° >
			< @ 88.00 quartz V 60.00º 130.00 >
			< @ 92.60 S1 70.00° >
			< @ 94.20 quartz/carbonate V 55.00º 50.00 >
			< @ 94.90 S1 30.00° >
			« py 0.10%»
			« 81.70- 83.75 po 0.50%»
			« 83.75- 84.20 po 2.00%»
			« 84.20- 95.30 po 0.5« cal 1.00*»
			« sil 2.00*»
			« chl 1.00*»
95.30	113.50	PHYL	
			Whole unit is heavaily faulted and sheared up.
			Dominantly graphitic phyllite with interbedded metagreywacke.
			104 - 108 m ~50% brecciated quartz veins (mulitiple generations visible in some sections).
			pyrrhotite occurs as blebs in mudstone layers and muddy matrix of fault breccia.
			< @ 98.10 Ft 10.00º >
			< @ 99.10 S1 55.00° >
			< @ 101.00 Ft 20.00º >
			< @ 102.00 S1 70.00° >
			< @ 108.70 quartz vein discordant to S1 V 30.00º 5.00 >
			« py 0.10%»
			« concentrated in phyllite layers po 1.00%»
			< @ 103.50 quartz V 70.00º
			« 95.30- 104.00 grp 1.00*»
			« 104.00- 108.50 grp 3.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
80.00	81.50	E856176	0.01	0.20	2.00	25	66
81.50	83.00	E856177	0.01	0.20	2.00	11	45
83.00	84.50	E856178	0.01	0.20	3.00	20	42
84.50	86.00	E856179	0.01	0.20	6.00	20	46
86.00	87.50	E856180	0.01	0.20	3.00	22	49
87.50	89.00	E856181	0.01	0.20	4.00	18	58
87.50	89.00	E856182					
89.00	90.50	E856183	0.01	0.20	7.00	21	78
90.50	92.00	E856184	0.01	0.20	2.00	20	70
92.00	93.50	E856185	0.01	0.20	5.00	14	35
93.50	95.00	E856186	0.01	0.20	80.00	17	19
95.00	96.50	E856187	0.01	0.20	110.00	21	42
96.50	98.00	E856188	0.79	0.40	10000.00	13	76
96.50	98.00	E856189					
96.50	98.00	E856190					
98.00	99.50	E856191	0.50	0.20	6250.00	13	90
99.50	101.00	E856192	0.03	0.20	293.00	19	82
101.00	102.50	E856193	0.56	0.20	2890.00	14	41
102.50	104.00	E856194	0.07	0.20	399.00	12	38
104.00	105.50	E856195	1.13	0.20	7190.00	11	60
105.50	107.00	E856196	0.81	0.20	6490.00	15	45
107.00	108.50	E856197	0.45	0.20	4150.00	11	77
108.50	110.00	E856198	0.33	0.20	3500.00	12	51
110.00	111.50	E856199	0.03	0.20	212.00	14	44
111.50	113.00	E856200	0.11	0.20	1640.00	8	34

Project: Keystone **Hole Number:** KEY10-02

From	To	Rocktype & Description
		« 108.50- 113.50 grp 1.00*»
113.50	116.50	PHYL
		80% phyllite with 10% metagreywacke and 10% quartz veins.
		pyrrhotite is present as very thin layers paralel to S1.
		pyrite occurs as blebls near vein margins.
		< @ 114.00 quartz V 60.00º 20.00 >
		< @ 114.40 S1 60.00° >
		< @ 115.60 V 60.00º 15.00mm >
		« py 0.50%»
		« po 0.50%»
116.50	123.50	QRZT
		Highly silicified quartzite/phyllite/metagreywacke
		quartzite layer contains small blue quartz eyes and the same fabric/foliation
		as the rest of the unit
		phyllite layer contains S1-paralel layers of sulphide (py+po)
		phyllite has some minor graphitic alteration
		cm-scale quartz veins pervasive
		< @ 117.50 S1 60.00° >
		< @ 117.90 V 70.00º 50.00 >
		< @ 118.50 V 30.00º 5.00 >
		< @ 121.00 S1 70.00° >
		< @ 121.00 quartz V 70.00º 10.00 >
		« 119.50- 120.21 po 0.50%»
		« py 0.50%»
123.50	138.00	PHYL
		Interval is highly sheared and faulted
		Dominantly phyllite with subordinate metagreywacke (~15%) and a few quartz
		veins
		phyllite is all highly graphitic, moderately chloritic
		133 - 136m is a mostly competent bed of metagreywacke
		phyllite has abundant foliation-paralel pyrite (+/- pyrrhotite) thin layers
		< @ 127.50 S1 60.00° >
		< @ 127.50 V 60.00º 15.00 >
		< @ 130.80 quartz V 50.00º 50.00 >
		< @ 133.80 S1 60.00° >
		< @ 134.80 quartz V 50.00º 100.00 >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
113.00	114.50	E856201	0.31	0.20	2910.00	12	52
113.00	114.50	E856202					
114.50	116.00	E856203	0.02	0.20	99.00	28	69
116.00	117.50	E856204	0.02	0.20	162.00	6	25
117.50	119.00	E856205	0.01	0.20	93.00	7	10
119.00	120.50	E856206	0.01	0.20	26.00	12	42
120.50	122.00	E856207	0.01	0.20	5.00	13	14
122.00	123.50	E856208	0.11	0.20	475.00	12	40
122.00	123.50	E856209					
122.00	123.50	E856210					
123.50	125.00	E856211	0.05	0.20	274.00	11	52
125.00	126.50	E856212	0.10	0.20	536.00	14	40
126.50	128.00	E856213	0.13	0.20	313.00	255	36
128.00	129.50	E856214	0.15	0.60	791.00	23	50
129.50	131.00	E856215	0.06	0.20	475.00	6	26
131.00	132.50	E856216	0.01	0.20	48.00	15	30
132.50	134.00	E856217	0.03	0.20	91.00	8	36
134.00	135.50	E856218	0.24	0.20	2140.00	19	38
135.50	137.00	E856351	0.17	0.20	1270.00	10	45

Project: Keystone **Hole Number:** KEY10-02

From	To	Rocktype & Description
		< @ 135.50 Ft 20.00º >
		« grp 3.00*»
		« py 1.00%»
138.00	147.00	MGWK
		60% silicified metagreywacke with cm-scale interbeds of phyllite (30%) cut by
		abundant quartz veins (10%)
		5-cm healed breccia zone at 138.6 m
		Vein at 141m contains a few crystals of arsenopyrite
		phyllite layers contain blebby pyrite
		< @ 139.30 S1 50.00° >
		< @ 138.70 quartz, cutting against fabric V 1.00º 1.00 >
		< @ 138.80 quartz V 50.00º 40.00 >
		< @ 141.00 quartz, few aspy crystals V 30.00º 15.00 >
		< @ 141.80 vuggy quartz V 25.00º 10.00 >
		< @ 146.60 S1 60.00° >
		« sil 2.00*»
		« 140.00- 143.00 po 0.50%»
		« py 1.0%»
		« apy 0.10%»
147.00	151.80	PHYL
		highly faulted graphitic phyllite (70%) with minor metagreywacke (20%) and
		quartz veins (10%)
		phyllite is mostly lacking in sulphides
		< @ 148.30 S1 50.00° >
		< @ 159.30 quartz V 50.00º 15.00 >
151.80	180.60	MGWK
		interbedded package of metagreywacke and phyllite in nearly equal amounts cut
		by abundant 1 - 5 cm wide quartz veins with minor carbonate
		phyllite layers contain small stringers of pyrite + pyrrhotite parralel to S1
		A second generation of quartz veins cuts against s1 and contains abundant
		chlorite and moderate amounts of pyrrhotite and traces of arsenopyrite
		< @ 155.00 S1 65.00° >
		< @ 161.50 quartz, paralel to s1 V 60.00º 100.00 >
		< @ 166.60 quartz, chlorite vein cutting s1 V 30.00º 50.00 >
		< @ 171.90 S1 65.00° >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
137.00	138.50	E856220	0.29	0.20	2590.00	2	15
138.50	140.00	E856221	0.10	0.20	2550.00	2	28
138.50	140.00	E856222					
140.00	141.50	E856223	0.09	0.20	396.00	8	43
141.50	143.00	E856224	0.16	0.20	539.00	11	47
143.00	144.50	E856225	0.06	0.20	255.00	10	20
144.50	146.00	E856226	0.01	0.20	32.00	8	20
146.00	147.50	E856227	0.01	0.20	10.00	7	35
147.50	149.00	E856228	0.01	0.20	2.00	7	41
147.50	149.00	E856229					
147.50	149.00	E856230					
149.00	150.50	E856231	0.01	0.20	3.00	6	36
150.50	152.00	E856232	0.01	0.20	4.00	11	50
152.00	153.50	E856233	0.01	0.20	6.00	14	55
153.50	155.00	E856234	0.01	0.20	7.00	27	43
155.00	156.50	E856235	0.01	0.20	17.00	46	59
156.50	158.00	E856236	0.01	0.20	12.00	21	67
158.00	159.50	E856237	0.01	0.20	14.00	25	67
159.50	161.00	E856238	0.01	0.20	10.00	12	68
161.00	162.50	E856239	0.01	0.20	16.00	13	66
162.50	164.00	E856240	0.01	0.20	30.00	19	46
164.00	165.50	E856241	0.02	0.20	80.00	21	45
164.00	165.50	E856242					

Project: Keystone **Hole Number:** KEY10-02

From	To	Rocktype & Description
		< @ 175.70 quartz vein cutting s1 V 45.00º 10.00 >
		« py 0.50%»
		« po 0.50%»
		« sil 1.00*»
180.60	192.00	MGWK
		Dominant lithology is a highly silicified moderately coarse-grained
		meta-sandstone
		There are adundant blue-grey quartz eyes that may be recrystalized or replaced
		large grains
		186 - 189 m is dominantly mudstone
		« sil 3.00*»
		< @ 188.70 S1 50.00° >
		< @ 180.70 S1 65.00° >
		< @ 183.00 quartz V 60.00º >
192.00	219.51	PHYL
		Phyllite with interbedded siltstone and adundant quartz veins
		SOS as rest of hole
		cross-cutting quartz veins contain moderate chlorite and very little sulphide
		s1 fabric is still consistent and unchanged from above units
		< @ 193.00 quartz V 60.00º 50.00 >
		< @ 193.00 S1 60.00° >
		< @ 194.10 quartz, cross-cutting V 20.00º 20.00 >
		< @ 196.70 S1 65.00° >
		< @ 198.30 V 70.00º 25.00 >
		< @ 199.80 S1 60.00° >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
165.50	167.00	E856243	0.63	0.30	1700.00	15	45
167.00	168.50	E856244	0.01	0.20	18.00	16	50
168.50	170.00	E856245	0.01	0.30	8.00	17	49
170.00	171.50	E856246	0.01	0.20	9.00	8	42
171.50	173.00	E856247	0.01	0.20	20.00	13	62
173.00	174.50	E856248	0.01	0.20	24.00	12	55
173.00	174.50	E856249					
173.00	174.50	E856250					
174.50	176.00	E856251	0.01	0.20	3.00	5	38
176.00	177.50	E856252	0.01	0.20	4.00	7	52
177.50	179.00	E856253	0.01	0.20	8.00	19	53
179.00	180.50	E856254	0.01	0.20	6.00	18	50
180.50	182.00	E856255	0.01	0.20	2.00	3	20
182.00	183.50	E856256	0.01	0.20	4.00	11	26
183.50	185.00	E856257	0.01	0.20	2.00	6	24
185.00	186.50	E856258	0.01	0.20	3.00	7	27
186.50	188.00	E856259	0.01	0.20	9.00	18	42
188.00	189.50	E856260	0.01	0.20	5.00	31	66
189.50	191.00	E856261	0.01	0.20	2.00	31	38
189.50	191.00	E856262					
191.00	192.50	E856263	0.01	0.20	3.00	7	47
192.50	194.00	E856264	0.01	0.20	47.00	7	63
194.00	195.50	E856265	0.01	0.20	4.00	9	63
195.50	197.00	E856266	0.01	0.20	2.00	22	39
197.00	198.50	E856267	0.01	0.20	2.00	7	15
198.50	200.00	E856268	0.01	0.20	18.00	3	86
198.50	200.00	E856269					
198.50	200.00	E856270					
200.00	201.50	E856271	0.02	0.20	8.00	12	61
201.50	203.00	E856272	0.01	0.20	7.00	7	29
203.00	204.50	E856273	0.01	0.20	5.00	8	47
204.50	206.00	E856274	0.01	0.20	4.00	14	86

Project: Keystone **Hole Number:** KEY10-02

From	To	Rocktype & Description
		< @ 203.10 quartz cross-cutting V 20.00º 5.00 >
		< @ 205.50 S1 65.00° >
		< @ 207.60 quartz chlorite cross-cutting V 20.00º 10.00 >
		< @ 212.60 quartz V 60.00º 100.00 >
		< @ 219.00 S1 55.00° >
		« py 0.10%»
		« sil 2.00*»
		EOH @ 219.51Very dark grey to black, moderate fol, streaky textured by 20% lt
		green altered fs and qtz, occ spotted texture (0.7cm) non-mag
219.51	219.51	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
206.00	207.50	E856275	0.01	0.20	2.00	5	43
207.50	209.00	E856276	0.01	0.20	16.00	6	79
209.00	210.50	E856277	0.01	0.20	3.00	10	79
210.50	212.00	E856278	0.01	0.20	4.00	9	35
212.00	213.50	E856279	0.01	0.20	4.00	18	46
213.50	215.00	E856280	0.01	0.20	2.00	7	38
215.00	216.50	E856281	0.01	0.20	2.00	15	68
215.00	216.50	E856282					
216.50	218.00	E856283	0.01	0.20	6.00	19	72
218.00	219.50	E856284	0.01	0.20	10.00	17	66

EQUITY

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 3622.0
Hole KEY10-03	**Azimuth (º):** 325
Location: 7078137 m North, 491054 m East	**Dip (º):** -55.0
Logged by: D. Swanton	**Length (m):** 25.00
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: NTW	**Objective** Test for mineralization that is the source of several 100 - 200 ppb Au soil anomalies, the distribution of which is thought to be controlled by a northeast trending structure
Date Started: 2010/06/18 **Date Completed:** 2010/06/18	
Dip Tests By:	

Summary Log:

Hole abandonned due to excessive overburden. 25m were drilled without encountering bedrock

Downhole surveys:

Depth	Dip	Azimuth
0.00	-50.00	325.00
25.00	-50.00	325.00

EQUITY

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 3622.0
Hole KEY10-04	**Azimuth (º):** 325
Location: 7078137 m North, 491054 m East	**Dip (º):** -70.0
Logged by: D. Swanton	**Length (m):** 102.72
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: NTW	**Objective** Test for mineralization that is the source of several 100 - 200 ppb Au soil anomalies, the distribution of which is thought to be controlled by a northeast trending structure
Date Started: 2010/06/19 **Date Completed:** 2010/06/23	
Dip Tests By:	

Summary Log:

20.11 - 32.1: Interbedded metagreywacke (80%) and phyllite (20%) with abundant fabric parallel quartz veins. Trace pyrite and pyrhhotite in phyllite layers
32.1 - 42.1: Dominantly phyllite (60%) with metagretwacke and quartz veins. Phyllite is graphically altered, fine-grained metagreywacke chloriticly. Py/Po stringers in phyllite layers.
41.2 - 52: 75% phyllite with interlayered metagreywacke and very few quartz veins. Graphitic alteration is becoming quite strong, moderate carbonate alteration. Sulphides present in phyllite
52 - 57.4: Mostly graphiticly altered fault gouge
57.4 - 59.7: 50/50 phyllite and metagreywacke. Phyllite is chloritized and contains fine-grained pyrite
59.7 - 76.2: Metagreywacke with 10% quartz veins. Fine-grained layers are altered to sericte and chlorite
76.2 - 88.62: Metagreywacke with 40% interlayered phyllite. Moderate faulting. Bottom half of unit is carbonate-altered
88.62 - 90.8: Highly fractured carbonate-altered phyllite and metagreywacke
90.8 - 94.0: Relatively competent metagreywacke. Fine-grained layers are altered to sericite and contain minor pyrite.
94.0 - 99.5: Highly faulted metagreywacke
99.5 - 100.0: Entirely fault gouge
100.0 - 102.72: Moderately competent metagreywacke within minor phyllite. End of Hole

Downhole surveys:

Depth	Dip	Azimuth
0.00	-70.00	325.00
102.72	-70.00	325.00

Project: Keystone **Hole Number:** KEY10-04

From	To	Rocktype & Description
0.00	20.11	CAS
		Casing
20.11	32.10	MGWK
		Dominantly foliated metagreywacke with ~20% interbeds of phyllite and 5% fabric // qtz veins
		Fine-grained layers of metagreywacke are slightly chloriticly alterred
		phyllite is lightly graphiticly alterred
		Some phyllitic layers are crenulated
		Fine grained pyrite and pyrrhotite are concentrated in phyllite layer
		A later generation of quartz-carbonate veins cross-cuts the fabric
		< @ 20.20 S1 60.00° >
		< @ 26.00 cross-cutting qtz-carbonate V 35.00° 50.00 >
		< @ 27.10 cross-cutting qtz-carbonate V 45.00° 10.00 >
		< @ 28.30 quartz V 50.00° 10.00 >
		« concenrated in phyllite layers py 0.10%»
		« concentrated in phyllite layers po 0.10%»
		« chl 1.00*»
		« sil 1.00*»
		« grp 1.00%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
20.00	21.50	E856285	0.01	0.20	6.00	21	42
21.50	23.00	E856286	0.01	0.20	10.00	29	32
23.00	24.50	E856287	0.01	0.20	5.00	26	68
24.50	26.00	E856288	0.01	0.20	2.00	22	86
24.50	26.00	E856289					
24.50	26.00	E856290					
26.00	27.50	E856291	0.01	0.20	2.00	16	55
27.50	29.00	E856292	0.01	0.30	2.00	15	32
29.00	30.50	E856293	0.01	0.20	2.00	18	14
30.50	32.00	E856294	0.01	0.30	2.00	12	31
32.00	33.50	E856295	0.01	0.20	3.00	12	71

Project: Keystone **Hole Number:** KEY10-04

From	To	Rocktype & Description
32.10	42.10	PHYL
		60% phyllite with 35% metagreywacke and 5% quartz veins
		Phyllite layers show moderate crenulation and graphitic alteration
		Fine-grained metagreywacke is chloriticly alterred
		Phyllite contains fabric // stringers of pyrite/pyrrhotite
		« py 0.50%»
		« po 0.50%»
		« chl 1.00*»
		< @ 33.90 quartz V 60.00º 25.00 >
		< @ 33.90 S1 60.00° >
		< @ 34.80 cross-cutting qtz carbonate V 45.00º 5.00 >
		< @ 36.60 S1 55.00° >
		< @ 41.50 Fabric // fault Ft 55.00º 50.00mm >
42.10	52.00	PHYL
		75% phyllite with 25% metagreywacke
		There are a few fabric // quartz veins, but they are less common than above
		Graphitic alteration is becoming stronger than above
		Carbonate alteration is seen for the first time in this hole
		As above, phyllite contains stringers of sulphide
		Secondary quartz-carbonate veins are still present
		« 42.10- 46.30 crb 2.00*»
		« 46.80- 52.00 sil 1.00*»
		« py 1.00%»
		< @ 45.70 S1 70.00° >
		< @ 46.30 Ft 65.00º 400.00mm >
		< @ 47.85 Ft 350.00mm >
		< @ 51.70 S1 30.00° >
		< @ 47.00 cross-cuttng (secondary) quartz-carbonate V 35.00º 10.00 >
52.00	57.40	PHYL
		This whole unit is almost totally faulted
		Large sections are nothing but fault gouge
		Heavaily graphiticly alterred
		There are several 10-15 cm long peices of intact core that were likely
		metagreywacke beds within the phyllite
		« py 1.00%»
		« grp 3.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
33.50	35.00	E856296	0.01	0.30	2.00	21	54
35.00	36.50	E856297	0.01	0.30	68.00	24	52
36.50	38.00	E856298	0.01	0.20	15.00	19	47
38.00	39.50	E856299	0.01	0.30	185.00	12	44
39.50	41.00	E856300	0.04	0.50	821.00	9	79
41.00	42.50	E856301	0.01	0.20	13.00	11	50
41.00	42.50	E856302					
42.50	44.00	E856303	0.01	0.40	2.00	17	39
44.00	45.50	E856304	0.01	0.20	5.00	14	32
45.50	47.00	E856305	0.01	0.70	43.00	18	140
47.00	48.50	E856306	0.01	0.30	21.00	25	73
48.50	50.00	E856307	0.01	0.20	8.00	14	45
50.00	51.50	E856308	0.01	0.20	14.00	17	76
50.00	51.50	E856309					
50.00	51.50	E856310					
51.50	53.00	E856311	0.01	0.30	19.00	22	76
53.00	54.50	E856312	0.01	0.20	10.00	22	94
54.50	56.00	E856313	0.01	0.30	16.00	27	101

Project: Keystone **Hole Number:** KEY10-04

From	To	Rocktype & Description
		< @ 55.90 S1 55.00° >
57.40	59.70	MGWK
		50% Metagreywacke, 50% phyllite, immediately following fault zone.
		phyllite layers contain fine grained pyrite and are chloritized.
		< @ 58.50 S1 65.00° >
59.70	76.20	MGWK
		Almost entire metagreywacke - the phyllite is absent from this unit
		fabric // quartz veins are abundant (10%)
		metagreywacke is composed of an interbedded sequence of finer and coarser
		layers; the fine-grained layers are extensively altered to chlorite and
		sericite.
		Coarser-grained layers have a more silicic alteration pattern
		fine to very-fine grained pyrite is disseminated throughout the unit
		74.2 - 74.4 (adjacent to a large quartz vein) has an odd patchy silicic
		alteration.
		« chl 2.00*»
		« ser 2.00*»
		« sil 2.00*»
		« py 0.10%»
		< @ 60.10 Ft 75.00º 75.00mm >
		< @ 61.20 Ft 65.00º 50.00mm >
		< @ 62.20 S1 70.00° >
		< @ 64.80 small cross-cutting quartz V 20.00º 10.00 >
		< @ 68.10 small cross-cutting quartz V 20.00º 10.00 >
		< @ 70.70 fabric // quartz V 70.00º 25.00 >
		< @ 73.80 S1 60.00° >
		< @ 74.60 fabric // qtz V 70.00º 100.00 >
76.20	88.62	MGWK
		60% metagreywacke with 40% interbedded phyllite.
		Moderate degree of faulting/fracturing, as compared to the rest of hole
		lower half of the unit is very carbonate-altered
		almost no sulphides - only a few traces in the phyllite layers
		« ser 1.00*»
		« sil 1.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
56.00	57.50	E856314	0.01	0.20	12.00	10	111
57.50	59.00	E856315	0.01	0.30	4.00	16	50
59.00	60.50	E856316	0.01	0.20	18.00	18	71
60.50	62.00	E856560					
62.00	63.50	E856318	0.01	0.20	2.00	11	52
63.50	65.00	E856319	0.01	0.20	4.00	17	71
65.00	66.50	E856320	0.01	0.20	2.00	22	43
66.50	68.00	E856321	0.01	0.20	3.00	38	31
66.50	68.00	E856322					
68.00	69.50	E856323	0.01	0.20	2.00	53	50
69.50	71.00	E856324	0.01	0.20	2.00	32	24
71.00	72.50	E856325	0.01	0.20	4.00	42	59
72.50	74.00	E856326	0.01	0.20	22.00	24	81
74.00	75.50	E856327	0.01	0.20	2.00	29	49
75.50	77.00	E856328	0.01	0.20	7.00	22	79
75.50	77.00	E856329					
75.50	77.00	E856330					
77.00	78.50	E856331	0.01	0.30	21.00	19	96
78.50	80.00	E856332	0.01	0.20	9.00	19	83
80.00	81.50	E856333	0.01	0.20	5.00	15	78
81.50	83.00	E856334	0.01	0.20	5.00	12	27
83.00	84.50	E856335	0.01	0.20	7.00	26	53
84.50	86.00	E856336	0.01	0.20	8.00	20	68
86.00	87.50	E856337	0.01	0.20	6.00	35	73

Project: Keystone **Hole Number:** KEY10-04

From	To	Rocktype & Description
		« chl 1.00*»
		« 84.20- 88.62 crb 3.00*»
		< @ 79.50 quartz V 50.00º 10.00 >
		< @ 79.80 S1 55.00° >
		< @ 83.80 Ft 70.00º 70.00mm >
		< @ 87.20 S1 50.00° >
		< @ 87.20 V 50.00º 5.00 >
88.62	90.80	PHYL
		Highly fractured and faulted zone of interbedded phyllite and metagreywacke
		Two wide zones of fault gouge at 89.1 - 89.3 and 90.2 - 90.5
		< @ 89.00 S1 75.00° >
		« crb 3.00*»
90.80	94.00	MGWK
		Slightly more competent zone of mgwk. Still heavaily fractured
		Almost no phyllite
		numerous interbeds of fine-grained sericiticly altered material
		finer-grained layers have minor amounts of pyrite
		« ser 2.00*»
		« chl 1.00*»
		« sil 2.00*»
		< @ 91.20 S1 65.00° >
		< @ 92.70 V 60.00º 20.00 >
		« py 0.10%»
94.00	99.50	MGWK
		mostly metagreywacke with some phyllite between 94 and 95 m
		very heavily faulted
		98.7 - 99 entirely fault gouge
		Vein of unknown green mineral at 98.35
		« chl 1.00*»
		< @ 97.60 S1 70« sil 1.00*»
99.50	100.00	Brx
		Entirely fault gouge
100.00	102.72	MGWK
		Moderately competent metagreywacke within minor phyllite



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
87.50	89.00	E856338	0.01	0.20	2.00	14	39
89.00	90.50	E856339	0.01	0.90	14.00	15	31
90.50	92.00	E856340	0.01	0.50	5.00	18	57
92.00	93.50	E856341	0.01	0.20	2.00	17	23
92.00	93.50	E856342					
93.50	95.00	E856343	0.01	0.20	5.00	16	68
95.00	96.50	E856344	0.01	0.20	20.00	13	35
96.50	98.00	E856345	0.01	2.20	52.00	21	39
98.00	99.50	E856346	0.03	0.80	318.00	15	72
99.50	101.00	E856347	0.15	24.10	1530.00	17	73
101.00	102.70	E856348	0.01	0.20	14.00	21	36
101.00	102.70	E856349					

Project: Keystone **Hole Number:** KEY10-04

From	To	Rocktype & Description
< @ 101.20 S1 65.00° >		
< @ 101.80 cross-cutting quartz-chlorite V 30.00º 40.00 >		
EOH		
102.72	102.72	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
101.00	102.70	E856350					

EQUITY

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 5396.0
Hole KEY10-05	**Azimuth (º):** 325
Location: 7079440 m North, 491607 m East	**Dip (º):** -50.0
Logged by: C.Bartsch	**Length (m):** 66.15
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: NTW	**Objective** Test for mineralization that is the source of several >1000 ppb Au soil anomalies, the distribution of which is thought to be controlled by a northeast trending structure. Mineralized float (arsenopyrite/galena) also observed at surface.
Date Started: 2010/06/24 **Date Completed:** 2010/06/26	
Dip Tests By:	

Summary Log:

0 - 3.6: Casing
3.6 - 12.30: Phyllite. Moderate carbonate alteration and strongly deformed.
12.3 - 24.3: Siltstone. Moderate chlorite alteration.
24.3 - 51.05: Graphitic phyllite.
51.05 - 66.15: Siltstone. Carbonate and silicic alteration, locally with up to 0.5% arsenopyrite. Hole was lost in a fault zone at 66.15m.

Downhole surveys:

Depth	Dip	Azimuth
0.00	-50.00	325.00
66.15	-50.00	325.00

Project: Keystone **Hole Number:** KEY10-05

From	To	Rocktype & Description
0.00	3.60	CAS
		Casing.
3.60	12.30	PHYL
		Phyllite. Finely laminated, strong foliation with localized crenulations.
		Strongly deformed quartz veins (1-3cm wide) throughout, all // to foliation.
		Hematite on fracture surfaces and spotty carbonate alteration throughout.
		« forms pink spots cal 1.00*»
		« hem 1.00%»
		« chl 1.00*»
		< @ 5.60 S1 40.00° >
		< @ 7.73 graphitic Ft 35.00° 100.00mm >
		< @ 10.60 S1 48.00° >
		< @ 10.65 S2 30.00° >
		< @ 10.85 Qz-carb vein V 45.00° 15.00mm >
12.30	24.30	MGWK
		Light green metagreywacke, finely laminated but uniform appearance and with a
		lack of quratz veining relative to phyllite. Spotty white carbonate alteration
		present throughout, minor hematite on fracture surfaces. Localized faulted
		zones with clay-rich gouge.
		< @ 12.30 con 40.00° >
		< @ 15.46 S1 18.00° >
		< @ 17.37 fault gouge Ft 60.00° 120.00mm >
		< @ 20.42 shallow angle, highly broken for 1.5 m Ft 10.00° 800.00mm >
		« spotty - .5cm white diss. spots cal 1.00*»
24.30	51.05	PHYL
		Graphitic phyllite. As in previous phyllite unit, but higher degree of brittle
		fracturing and fauting, along with weak patchy silicification. Unit appears
		broken with moderate hematite staining on fractures and overall oxidized. 5%
		quartz veins overall, most deformed and foliation parallel. Minor
		cross-cutting quartz-carbonate veins towards base of unit. Also locally vuggy
		where spotty carbonate alteration has been weathered out.
		« sil 1.00*»
		« grp 2.00%»
		« oxidized on fractures hem 2.00%»
		< @ 25.80 hem on surface Fr 25.00° >
		< @ 29.13 S1 30.00° >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
3.60	5.00	E856352	0.01	0.20	14.00	15	60
5.00	6.50	E856353	0.01	0.20	9.00	13	46
6.50	8.00	E856354	0.01	0.20	4.00	13	27
8.00	9.50	E856355	0.01	0.20	3.00	10	31
9.50	11.00	E856356	0.01	0.20	6.00	13	44
11.00	12.50	E856357	0.01	0.20	31.00	13	76
12.50	14.00	E856358	0.01	0.20	40.00	3	91
14.00	15.50	E856359	0.01	0.20	20.00	5	116
15.50	17.00	E856360	0.01	0.20	32.00	2	145
17.00	18.50	E856361	0.01	0.20	52.00	2	156
17.00	18.50	E856362					
18.50	20.00	E856363	0.01	0.20	24.00	2	150
20.00	21.50	E856364	0.01	0.20	17.00	2	129
21.50	23.00	E856365	0.01	0.20	22.00	5	204
23.00	24.50	E856366	0.01	0.20	25.00	7	123
24.50	26.00	E856367	0.01	0.20	5.00	15	73
26.00	27.50	E856368	0.01	0.20	5.00	20	56
26.00	27.50	E856369					
26.00	27.50	E856370					
27.50	29.00	E856371	0.01	0.20	11.00	13	43
29.00	30.50	E856372	0.01	0.20	3.00	13	38
30.50	32.00	E856373	0.01	0.20	2.00	14	29
32.00	33.50	E856374	0.01	0.20	12.00	16	9
33.50	35.00	E856375	0.01	0.20	2.00	11	21
35.00	39.00	E856376	0.01	0.20	5.00	18	17
39.00	41.00	E856377	0.01	0.20	14.00	5	448
41.00	42.50	E856378	0.01	0.20	17.00	11	111

Project: Keystone **Hole Number:** KEY10-05

From	To	Rocktype & Description
		< @ 30.65 cross-cutting fracture Fr 10.00° >< @ 32.90 S1 48.00° >
		< @ 41.60 Fr 6.00° >
		< @ 42.32 qz-carb vein V 49.00° 20.00mm >
		< @ 42.08 S1 52.00° >
		< @ 47.30 S1 60.00° >
		< @ 44.10 Quartz vein - fol// V 42.00° 70.00mm >
		< @ 47.16 cross-cutting qz-carb vein V 38.00° 10.00mm >
		< @ 49.60 graphitic gouge Ft 42.00° 500.00mm >
51.05	66.15	MGWK
		Light green, finely laminated metagreywacke. Spotty carbonate alteration, locally dissolved near fractures giving a vesicular appearance. Minor foliation concordant veining (qz-carb, 1-5cm wide) and small cross-cutting stringers. Sulphides increase downhole, locally with up to 0.5% arsenopyrite and 1% pyrite in cross-cutting vein selvages. Two highly hematitic fault zones and bleaching around fractures near base of unit. Hole lost at 66.15 due to stuck rods in a fault zone. EOH @ 66.15
		« spotty cal 2.00*»
		« chl 2.00*»
		« 63.30- 64.80 euhedral crystals around qz-cb veinlets apy 0.50%»
		« finely diss. throughout matrix py 1.00%»
		« 64.80- 66.15 apy 0.10%»
		« py 0.10%»
		« 60.00- 64.50 concentrated in 2 fault zones hem 2.00%»
		< @ 57.65 S1 32.00° >
		< @ 60.00 Strongly hematitic gouge Ft 60.00° 300.00mm >
		< @ 61.85 qz-carb veinlet V 35.00° 3.00mm >
		< @ 63.56 Qz-carb veinlete with diss. aspy V 45.00° 5.00mm >
		< @ 63.62 hematitic fault gouge Ft 60.00° 900.00mm >
		< @ 64.55 cross-cutting veinlet with aspy V 45.00° 5.00mm >
66.15	66.15	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
42.50	44.00	E856379	0.01	0.20	8.00	19	69
44.00	45.50	E856380	0.01	0.20	8.00	14	50
45.50	47.00	E856381	0.01	0.20	7.00	9	49
45.50	47.00	E856382					
47.00	48.50	E856383	0.01	0.20	8.00	10	59
48.50	50.00	E856384	0.01	0.20	15.00	14	59
50.00	51.50	E856385	0.01	0.20	13.00	7	79
51.50	53.00	E856386	0.01	0.20	19.00	4	122
53.00	54.50	E856387	0.01	0.20	41.00	4	158
54.50	56.00	E856388	0.01	0.20	127.00	6	346
54.50	56.00	E856389					
54.50	56.00	E856390					
56.00	57.50	E856391	0.01	0.20	108.00	24	381
57.50	59.00	E856392	0.01	0.20	8.00	19	110
59.00	60.50	E856393	0.06	0.20	485.00	6	431
60.50	62.00	E856394	0.01	0.20	37.00	5	161
62.00	63.50	E856395	0.01	0.20	49.00	11	184
63.50	65.00	E856396	0.27	0.20	2040.00	2	546
65.00	66.15	E856397	0.01	0.20	110.00	2	434

2010/10/18 **Equity Exploration Ltd.** * depth component not to scale

* Samples with duplicate ranges are QA/QC samples and have no associated assays

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 5396.0
Hole KEY10-06	**Azimuth (º):** 325
Location: 7079440 m North, 491607 m East	**Dip (º):** -70.0
Logged by: M. McKeown	**Length (m):** 178.31
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: NTW	**Objective**
Date Started: 2010/06/24 **Date Completed:** 2010/07/06	To investigate the source of high local Au values in soil and float thought to be controlled by a NE structure. The soils ran 1084 and 2588 ppb Au and the quartz vein float , with arsenopyrite along salvages, ran ~2.5 g/tonne Au.
Dip Tests By:	

Summary Log:

0.4-8.56 Fractured phyllite with chlorite, sericite and carbonate alteration.
8.56-42.04 Interbedded graphitic phyllite and metagreywacke with chlorite and carbonate alteration and trace disseminated pyrite.
42.04-45.71 Fault zone within graphitic phyllite with vuggy quartz veins.
45.71-50.42 Metagreywacke with graphitic interlayers with moderately abundant spotty and banded carbonate alteration and abundant fractures.
50.42-54.02 Fractured graphitic phyllite with abundant cross cutting quartz veins.
54.02-56.93 Interbedded metagreywacke and graphitic phyllite with spotty and banded carbonate alteration.
56.93-60.95 Faulted graphitic phyllite.
60.95-66.19 Competent metagreywacke with graphitic interlayers and speckled carbonate alteration.
66.19-68.03 Same metagreywacke but highly fractured
68.03-74.92 Highly fractured graphitic phyllite.
74.92-92.46 Highly fractured, interlayered laminated metagreywacke (85%) and phyllite (15%) with abundant chlorite alteration and spotty carbonate alteration.
92.46-121.30 Highly fractured and faulted (40% fault gouge) graphitic phyllite with abundant chlorite and lesser carbonate alteration. Trace disseminated pyrite (1%) and trace pyrrhotite (0.5%).
94.70-121.30 Same as above however no carbonate alteration and lesser pyrite and pyrrhotite.
121.30-135.24 Large fractured and faulted zone within graphitic phyllite with moderately abundant silica alteration throughout and some brecciated zones. Trace disseminated pyrite (1.5%) and pyrrhotite (0.5%).
135.24-135.80 Brecciated graphitic phyllite, abundant quartz veining.
135.80-178.31 Silicified graphitic phyllite with abundant fractures and fault gouge. Trace pyrite.
178.31 EOH

Downhole surveys:

Depth	Dip	Azimuth
0.00	-70.00	325.00
178.31	-70.00	325.00

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
0.00	0.40	CAS
		Casing
0.40	7.59	PHYL
		Heavily foliated, finely laminated phyllite with abundant chlorite alteration and lesser carbonate and sericite (?) ateration. This unit has abundant fractures with minor fault gouge. Foliation // iron oxide weathering in zones. There are minor quartz veins and blebs that are not foliation // 2-4cm width.
		< @ 0.40 S1 30.00° >
		< @ 5.50 Xcutting quartz V 4.00cm >
		« chl 2.00*»
		« cal 1.00*»
		« minor, along foliation sil 1.00*»
		« along foliation ser 1.00*»
7.59	8.56	PHYL
		Same unit as above but highly fractured with moderate abundance of vuggy quartz veins with some later carbonate alteration.
		< @ 7.59 Highly fractured but no gouge Ft 97.00cm >
		« chl 2.00*»
		« ser 1.00*»
		« sil 1.00*»
		« cal 2.00*»
8.56	10.00	MGWK
		Light green metagreywacke (finely laminated, weakly foliated) with pervassive chlorite alteration and white specks of carbonate alteration.
		« specks of carbonate alteration cal 2.00* 1.00-3.00mm»
		« pervasive chl 2.00*»
10.00	17.55	PHYL
		Interbedded metagreywacke (20%) and graphitic phyllite (80%) with a greater abundance of phyllite. Layers vary from 30~200cm thickness. Phyllite layers are highly alterated, dominated by carbonate that appears both pervasive and as veinlets. Chlorite alteration is moderately abundant throughout both units. Within the phyllite are zones of slightly vuggy, fabric // quartz veins with iron oxide staining. The graphitic phylite unit is commonly fractured.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
0.00	1.90	E856451	0.01	0.20	8.00	10	54
1.90	5.79	E856452	0.01	0.20	8.00	12	35
5.79	7.12	E856453	0.01	0.20	17.00	13	44
7.12	8.86	E856454	0.01	0.20	50.00	9	82
8.86	10.23	E856455	0.01	0.20	39.00	8	86
10.23	12.53	E856456	0.01	0.20	34.00	8	45
12.53	14.24	E856457	0.01	0.30	82.00	16	43
14.24	16.90	E856458	0.01	0.20	16.00	15	79

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
		< @ 10.00 S1 30.00° >
		< @ 15.92 vuggy quartz vein V 3.00cm >
		« chl 2.00*»
		« white bands focused in phylite and stringers cal 3.00*»
		« phyllite grp 2.00*
17.55	19.45	PHYL
		Same interbedded graphitic phyllite 90% and metagreywacke 10% unit as above but heavily fractured.
		< @ 17.55 Heavily fractured Ft 1.90m >
		< @ 17.55 S1 30.00° >
		« chl 2.00*»
		« cal 2.00*»
		« in phylite grp 2.00*»
19.45	33.28	PHYL
		Finely laminated, graphitic phyllite with abundant alteration. There are zones with differing alteration though graphite and chlorite are throughout. Quartz veins are not abundant, those that do occur may also contain siderite and roughly follow the fabric with some blebs. There is abundant iron oxide staining along foliation. No mineralization.
		< @ 19.45 S1 40.00° >
		< @ 24.30 Abundant qtz veining with iron oxide staining V 12.00cm >
		< @ 26.36 Abundant qtz veining with iron oxide staining V 13.00cm >
		« grp 3.00*»
		« zones with specks or bands cal 2.00*»
		« chl 2.00*»
		« in zones sil 1.00*»
33.28	35.78	MGWK
		Light green metagreywacke (finely laminated, weakly foliated) with pervassive chlorite alteration and white specks of carbonate alteration. Also minor, cm-scale, carbonate (with lesser siderite) veinlets that cut foliation. There are minor, mm-scale quartz veins following fabric.
		< @ 33.38 Cross cuting carbonate veinlets V 45.00° 3.00mm >
		< @ 33.28 S1 50.00° >
		« pervasive chl 2.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
16.90	18.66	E856459	0.01	0.20	26.00	7	152
18.66	19.83	E856460	0.01	0.20	7.00	8	71
19.83	21.74	E856461	0.01	0.20	16.00	12	65
19.83	21.74	E856462					
21.74	23.83	E856463	0.01	0.20	9.00	9	57
23.83	25.45	E856464	0.01	0.20	11.00	14	40
25.45	27.04	E856465	0.01	0.20	4.00	16	66
27.04	28.69	E856466	0.01	0.20	3.00	9	64
28.69	30.19	E856467	0.01	0.20	3.00	17	61
30.19	32.08	E856468	0.01	0.20	7.00	13	77
30.19	32.08	E856469					
30.19	32.08	E856470					
32.08	33.72	E856471	0.01	0.30	21.00	13	82
33.72	35.32	E856472	0.01	0.50	34.00	79	91

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
		« specks of carbonate alteration and veinlets cutting fabric cal 2.00*
		1.00-3.00mm»
35.78	36.82	PHYL
		Interbed of graphitic phyllite wihin the greywacke.with abundant fabric //
		veins and alteration. Poorly defined crenulation. Minor cross cutting mm scale
		silica veinlets with hematite (?). No mineralization.
		< @ 36.00 S1 30.00° >
		< @ 36.11 Crenulation (75 degrees to S1) S2 45.00° >
		< @ 36.25 Pinched out, fabric // quartz vein V 2.00cm >
		« abundant grp 2.00*»
		« abundant chl 2.00*»
		« cal 1.00*»
		« as veins sil 1.00* 1.00-4.00cm»
36.82	42.04	MGWK
		Light green metagreywacke (finely laminated, weakly foliated)
		with pervasive chlorite alteration and white mm scale specks of carbonate
		alteration, forming fabric // bands in zones. There are fine (mm scale)
		graphitic interlayers, these have more abundant carbonate alteration. No
		mineralization.
		< @ 38.00 S1 40.00° >
		« chl 2.00*»
		« specks and bands cal 2.00*»
42.04	45.71	PHYL
		Highly fractured zone of graphitic phyllite with abundant carbonate alteration.
		Roughly 65% of the unit is fractured (rock fragments less than ~7cm) with ~5%
		fault gouge. At the upper end of the unit there is a 4cm thick vuggy
		interlayer in which 2-5mm spaces remain where carbonate (?) has weathered out.
		Thin bands of white carbonate alteration are abundant. Chlorite alteration is
		moderatly abundant. There are minute stringers of pyrite that follow the fabric
		in heavily altered zones.
		< @ 42.24 Highly fractured rock with minor fault gouge Ft 1.47m >
		< @ 42.06 S1 35.00° >
		< @ 42.11 Vuggy quartz with lesser siderite V 35.00° 6.00cm >
		« chl 2.00*»
		« forming bands cal 3.00*»
		« mm scale stringers py 0.10%»
45.71	47.90	MGWK



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
35.32	37.79	E856473	0.01	0.20	17.00	8	73
37.79	38.35	E856474	0.01	0.20	40.00	2	161
38.35	39.96	E856475	0.01	0.20	15.00	4	111
39.96	41.84	E856476	0.01	0.20	21.00	6	133
41.84	44.51	E856477	0.01	0.50	155.00	17	355

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
		Highly fractured light green greywacke with specks of white carbonate alteration throughout..
		< @ 35.00 S1 0° >
		< @ 45.71 highly fractured Ft 31.00cm >
		< @ 46.20 Ft 84.00cm >
		< @ 47.64 Cross cutting, vuggy quartz vein V 16.00cm >
		« mm scale specks and bands cal 2.00*»
		« chl 2.00*»
47.90	50.42	SCHT
		(Andalusite?) schist with graphitic interlayers. Similar to the greywacke unit seen above however the specks of carbonate are better defined and are likely replacing andalusite that has weathered. This andalusite schist is seen in outcrop near the drill site with a chiastolite pattern that can be made out in some cases.
		« Very abundant and pervasive chl 3.00*»
		« Abundant replacment cal 2.00*»
		« grp 1.00*»
		< @ 49.43 highly fractured Ft 80.00cm >
50.42	54.02	PHYL
		Fractured graphitic phyllite with abundant cm-scale quartz veining with possibly hematite staining near vein salvages. The abundance of quartz veins that cut the fabric creates a slight breccia texture.
		< @ 50.42 Quartz with hematite(?) V 8.00cm >
		« grp 2.00*»
		« chl 2.00*»
54.02	55.26	MGWK
		Green metagreywacke with speckled white carbonate alteration as seen above. This also may be the andalusite schist in which the carbonate has replaced the andalusite.
		« pervasive chl 3.00*»
		« specks replacing andalusite? cal 2.00*»
55.26	56.14	PHYL



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
44.51	46.26	E856478	0.01	0.20	71.00	21	145
46.26	47.98	E856479	0.01	0.20	116.00	21	254
47.98	49.66	E856480	0.01	0.20	63.00	3	205
49.66	51.15	E856481	0.01	0.20	25.00	7	139
49.66	51.15	E856482					
51.15	52.59	E856483	0.01	0.20	37.00	13	120

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
		Highly altered graphitic phyllite with moderatly abundant cross cutting quartz veins with abundant iron oxide staining along fractured surfaces. There is small zone with breccia texture due to the abundance of quartz veinlets.
		« grp 3.00*»
		« chl 2.00*»
56.14	56.93	MGWK
		Same as above with speckled carb alteration. The lower 30cm is dominated by thick quartz veining with hematite(?) staining that cuts folliation.
		« chl 3.00*»
		« cal 2.00*»
		< @ 56.34 quartz V 30.00cm >
56.93	60.95	PHYL
		Highly fractured and faulted graphitic phyllite. Fault gouge comprises ~25% of this section.
		< @ 57.22 ~25% fault gouge, highly fractured Ft 3.73m >
		« abundant mm scale bands cal 3.00*»
60.95	66.19	MGWK
		Very competent . Same green metagreywacke with speckled carbonate alteration with one interbed of the graphitic phylitte from 61.72-6.22m) the contact is 30 degrees. Iron oxide staining occurs along the contact of the two layers with heavily stained mm scale veinlets cross cutting into the greywacke unit. Within the greywacke unit there are mm scale cross cutting carbonate veins.
		« specks and veinlets within grwk cal 2.00*»
		« abundant within the phyllite grp 1.00*»
66.19	68.03	MGWK
		Same greywacke as above but highly fractured.
		< @ 66.30 60% fault gouge Ft 95.00cm >
		« chl 2.00*»

From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
52.59	55.09	E856484	0.01	0.20	8.00	3	69
55.09	55.60	E856485	0.01	0.20	13.00	5	121
55.60	57.35	E856486	0.01	0.30	18.00	35	115
57.35	59.01	E856487	0.01	0.20	54.00	5	170
59.01	60.73	E856488	0.01	17.30	55.00	4	183
59.01	60.73	E856489					
59.01	60.73	E856490					
60.73	62.28	E856491	0.01	2.60	35.00	32	305
62.28	63.63	E856492	0.01	0.60	15.00	5	143
63.63	65.17	E856493	0.01	0.30	10.00	4	130
65.17	66.59	E856494	0.01	0.20	7.00	7	139
66.59	68.21	E856495	0.01	0.50	8.00	19	102

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
		« cal 2.00*»
68.03	74.92	PHYL
		Graphitic phyllite with abundant fracturing. ~20% pieces over 7cm, 10% fault gouge, 70% highly fractured rock (pieces <7cm). The lower 1m of this section is more competant likely due to slight silicification associated with several quartz veins that occur in this section. There is trace pyrite in the last metre of this section (74-75m) occuring as small blebs or stringers along foliation.
		< @ 74.58 Quartz, along foliation V 7.00cm >
		< @ 68.03 10% fault gouge, highly fractured Ft 5.76mm >
		< @ 68.03 S1 25.00° >
		« grp 1.00*»
		« chl 2.00*»
		« 73.80- 74.92 sil 1.00*»
		« 74.00- 74.92 trace blebs and stringers py 0.10%»
74.92	92.46	MGWK
		Interlayered laminated green metagreywacke (85%) and laminated phylitte (15%) with chlorite and carbonate alteration throughout and several multiple fault zones. The dominant unit has mm scale chlorite altered laminations with lesser mm scale graphitic laminations. Carbonate alteration occurs as white specks as well as cm scale bands.
		< @ 78.38 S1 50.00° >
		< @ 92.44 Crenulation S2 20.00° >
		< @ 78.48 70% gouge Ft 24.00cm >
		< @ 79.09 85% gouge Ft 34.00cm >
		< @ 81.47 60% gouge Ft 2.79m >
		< @ 89.52 Fr 39.00cm >
		< @ 91.30 Fractured Fr 75.00cm >
		< @ 89.09 Cross cutting quartz V 23.00cm >
		« chl 3.00*»
		« moderately abundant throughout cal 2.00*»
		« Fine mm scale laminations grp 1.00*»
92.46	94.70	PHYL
		Highly altered and fractured graphitic phyllite. Abundant bands of carbonate alteration with lesser chlorite and muscovite alteration. Diseminated and fine



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
68.21	69.76	E856496	0.01	0.20	12.00	17	69
69.76	71.87	E856497	0.01	0.20	10.00	28	58
71.87	73.90	E856498	0.01	0.20	3.00	24	47
73.90	75.37	E856499	0.01	0.20	3.00	41	91
75.37	76.94	E856500	0.01	0.20	4.00	20	108
76.94	78.89	E856501	0.01	0.20	8.00	5	90
78.89	80.01	E856502	0.01	0.20	6.00	8	106
80.01	82.74	E856503	0.01	0.20	8.00	2	108
82.74	84.93	E856504	0.01	0.20	13.00	2	147
84.93	86.34	E856505	0.01	0.20	13.00	2	155
86.34	87.80	E856506	0.01	0.20	14.00	2	158
87.80	89.55	E856507	0.01	0.20	8.00	8	121
89.55	90.99	E856508	0.01	0.20	14.00	6	114
89.55	90.99	E856509					
89.55	90.99	E856510					
90.99	92.16	E856511	0.01	0.40	24.00	13	178
92.16	94.61	E856512	0.01	0.20	19.00	19	64
94.61	97.53	E856513	0.01	0.20	20.00	22	71

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
		blebs of pyrite and pyrrhotite occur whithin the most graphitic layers. The pyrite and pyrrhotite appear to follow laminations so most is early stage however some of the pyrrhotite appears to slightly cut fabric. Carbonate alteration occurs as white cm scale bands. There are well formed crenulations.
		< @ 92.46 con 35.00° >
		< @ 92.46 S1 25.00° >
		< @ 93.07 Well formed crenulation S2 10.00° >
		< @ 92.59 Folliation // quartz V 25.00° 6.00cm >
		< @ 93.57 Abundant fractures Fr 1.13m >
		« cal 2.00*»
		« chl 2.00*»
		« diseminated and blebs py 1%»
		« small blebs with pyrite po 0.50%»
94.70	121.30	PHYL
		Fault zone with ~50% gouge and 45% rock fragments smaller than 10cm. The rock unit is the graphitic phyllite. There is moderatly abundant quartz veining that cuts foliation. There is no carbonate alteration which is a large contrast from the previous section. In the lower portion of the unit the phylitte is brecciated with quartz veins. Alteration consists of silica with lesser muscovite and possibly minor sericite. There are several cm size pyrite blebs along the salvages of quartz veins. There is also trace diseminated pyrite whitin the graphitic phylitte with lesser trace pyrrhotite.
		< @ 100.00 S1 45.00° >
		< @ 94.70 Ft 23.70m >
		« largely as veins and veinlets sil 2.00*»
		« mus 1.00°»
		« ser 2.00*»
		« py 0.20%»
		« po 0.10%»
		**There were some discrepancies with the footage in this section. Between 97.23 and 104.24m there may have been an error in marking the blocks or the recovery was just very poor (~35%) which would not be surprising in such faulted ground.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
97.53	99.08	E856514	0.01	0.20	12.00	22	53
99.08	105.10	E856515	0.01	0.20	41.00	12	54
105.10	106.71	E856516	0.01	0.30	19.00	12	48
106.71	108.08	E856517	0.01	0.40	49.00	11	127
108.08	110.40	E856518	0.01	0.20	19.00	7	62
110.40	112.05	E856519	0.01	0.20	16.00	7	41
112.05	113.44	E856520	0.01	0.50	27.00	16	49
113.44	117.68	E856521	0.01	0.30	22.00	14	43
113.44	117.68	E856522					
117.68	120.58	E856523	0.10	1.30	580.00	12	60
120.58	123.09	E856524	0.05	9.10	527.00	12	59

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
121.30	135.24	PHYL

Highy brecciated and faulted graphitic phyllite with abundant silica veining and alteration. There is abundant mm-cm scale quartz veining along foliation as well as abundant cross cutting quartz veins causing brecciated texture. Foliation parallel fractures are abundant and there are zones comprised of 100% fault gouge. There are several late stage, cross cutting quartz veins that contain epidote. Quartz veins comprise as much as 35% of the this section. Trace pyrite is diseminated throughout as well as in up to 1.5cm blebs. Trace pyrrhotite occurs predominately along thin graphitic layers. There is no carbonate alteration.

< @ 123.00 S1 30.00° >
< @ 126.00 S2 5.00° >
< @ 121.30 fracturing along the entire unit Fr 30.00° 7.70m >
< @ 124.27 V brecciated quartz with lesser epidote 30.00cm >
< @ 124.57 100% fault gouge Ft 30.00mm >
< @ 127.60 50% fault gouge Ft 47.00cm >
< @ 130.36 80% gouge Ft 102.00cm >
< @ 133.34 20% gouge, abundant fractures Ft 43.00cm >
< @ 135.07 15% gouge Ft 17.00cm >
« abundant throughout but focussed in brecciated zones sil 3.00*»
« disseminated throughout py 1.50%»
« focussed along graphitic layers po 0.50%»

From	To	Rocktype & Description
135.24	135.80	Brx

Brecciated graphitic phyllite with abundant chlorite alteration, quartz veining and lesser sericite. The cross cutting quartz veining causing the breccia texture has thin strings of pyrite along the vein salvages. There are also trace amounts of arsenopyrite (?) that appears to be weathering to a dark brown/red material.

« chl 3.00*»
< @ 135.24 Quartz creating breccia texture V 56.00cm >
« along vein salvages py 2.00%»
« trace, fine blebs py 0.10%»

From	To	Rocktype & Description
135.80	178.31	PHYL

Silicified graphitic phyllite with abundant fractures and fault zones. The

From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
123.09	124.65	E856525	0.01	0.30	37.00	17	80
124.65	127.13	E856526	0.01	0.30	47.00	17	115
127.13	128.67	E856527	0.01	0.20	27.00	12	94
128.67	130.06	E856528	0.01	0.30	25.00	11	99
128.67	130.00	E856529					
128.67	130.00	E856530					
130.00	131.33	E856531	0.01	0.20	27.00	15	81
131.33	133.75	E856532	0.01	0.20	22.00	14	105
133.75	135.26	E856533	0.43	0.30	49.00	22	98
135.26	136.96	E856534	0.25	0.20	29.00	11	60
136.96	138.32	E856535	0.08	0.20	26.00	10	49
138.32	140.30	E856536	0.03	0.20	23.00	10	35

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
		unit has abundant mm scale, foliation parellel quartz veins, this along with bands of sericite alteration give the unit a striped appearance. There has been slight movement that cross cuts foliation evident by a 'stepped' pattern in the initial fabric creating an echelon type pattern. Trace pyrite focused in the most graphitic layers.
		< @ 167.00 S1 45.00° >
		< @ 163.50 crenulation S2 75.00° >
		< @ 136.41 20% fault gouge and abundant fractures Ft 1.50m >
		< @ 138.27 30% gouge Ft 20.00° 1.04m >
		< @ 142.20 25% gouge, abundant fractures Ft 1.80m >
		< @ 149.08 15% gouge Ft 1.41m >
		< @ 156.44 abundant randomly oriented fractures Fr 1.53m >
		< @ 158.30 randomly oriented fractures Fr 4.03m >
		< @ 164.38 along foliation Fr 35.00° 82.00mm >
		< @ 166.44 along foliation Fr 97.00cm >
		< @ 167.41 15% gouge, randomly oriented fractures Ft 31.00cm < @ 175.26 35% gouge, abundant fractures most randomly oriented Ft 3.05m >
		< @ 162.66 Cross cuting quartz, sericite alteration V 18.00cm >
		« quite abundant throughout sil 2.00*»
		« mus 2.00°»
		« ser 1.00*»
		« py 1.00%»
		EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
140.30	141.60	E856537	0.02	0.20	24.00	9	43
141.60	143.68	E856538	0.02	0.20	12.00	10	39
143.68	145.80	E856539	0.02	0.20	6.00	11	47
145.80	147.41	E856540	0.02	0.20	14.00	13	40
147.41	149.57	E856541	0.02	0.20	13.00	13	40
147.41	149.57	E856542					
149.57	151.50	E856543	0.03	0.20	11.00	9	30
151.50	153.03	E856544	0.12	0.20	293.00	8	45
153.03	155.35	E856545	0.07	0.30	142.00	15	56
155.35	157.58	E856546	0.05	0.20	86.00	9	68
157.58	159.24	E856547	0.05	0.20	102.00	10	46
159.24	161.08	E856548	0.05	0.20	97.00	10	44
159.24	161.08	E856549					
159.24	161.08	E856550					
161.08	162.81	E856551	0.02	0.20	25.00	7	46
162.81	164.67	E856552	0.02	0.20	23.00	17	56
164.67	166.18	E856553	0.01	0.20	21.00	9	67
166.18	167.77	E856554	0.03	0.20	26.00	13	66
167.77	169.16	E856555	0.09	0.50	369.00	8	66
169.16	172.90	E856556	0.11	0.60	664.00	6	62
172.90	174.00	E856557	0.03	0.20	96.00	10	74
174.00	175.40	E856558	0.02	0.20	69.00	12	77
175.40	176.39	E856559	0.01	0.20	11.00	8	70
176.39	178.31	E856578	0.02	0.20	34.00	6	68

Project: Keystone **Hole Number:** KEY10-06

From	To	Rocktype & Description
178.31	178.31	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm

EQUITY

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 3937.0
Hole KEY10-07	**Azimuth (º):** 325
Location: 7077639 m North, 490028 m East	**Dip (º):** -50.0
Logged by: D. Swanton	**Length (m):** 248.41
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: BTW	**Objective**
Date Started: 2010/06/28 **Date Completed:** 2010/07/06	To investigate the source of a broad soil anomaly with Au values 200 - 400 ppb on the eastern slope of the western tributary of Keystone Creek, and to look for continuation of the NE-SW trending structure investigated in earlier holes.
Dip Tests By:	

Downhole surveys:

Depth	Dip	Azimuth
0.00	-50.00	325.00

Summary Log:

0.0 – 7.00 Casing
7.00 – 9.90 Foliated quartzite/metasiltstone. Pervasive silicic and carbonate alteration. Small siderite and carbonate veins cross-cutting foliation
9.90 – 16.00 Quartzite breccia, healed with silica and overprinted with carbonate
16.00 – 24.30 Foliated quartzite/metasiltstone with pervasive silicic alteration and few bands of carbonate and sericite. Trace pyrite in carbonate and sericite zones.
24.30 – 25.45 Healed quartzite breccias, same as above
25.45 – 28.4 Faulted quartzite altered with quartz and FeCO3. Moderate mineralization, pyrite and pyrrhotite
28.4 – 32.0 Carbonitized silicified quartzite breccia. Large rusty quartz-carbonate veins surrounded by pyrite mineralization
32.0 – 38.5 Fault zone with a few competent pieces of the same breccia as above. Trace pyrite.
38.5 – 50.29 Silicified metagreywacke with interbedded graphitic phyllite and fabric parallel quartz veins. Phyllite layers contain up to 2% pyrite. Minor arsenopyrite in a quartz vein at 48.8m
50.29 – 64.25 Faulted, iron stained metagreywacke and phyllite with minor pyrite/pyrrhotite
64.25 – 70.7 Mostly silicified metagreywacke with minor black phyllite. Trace pyrite
70.7 – 77.7 Lightly silicified metagreywacke with cross cutting quartz-carbonate veins
77.7 – 87.1 Chloritized phyllite with subordiniate metagreywacke and thick fabric parallel quartz/chlorite veins.
87.1 – 99.7 Chloritic, sericitic phyllite
99.7 – 114.0 Carbonate altered metagreywacke with 30% chloritic phyllite. 104.6 – 104.7 m is nearly 10% pyrrhotite, elsewhere in the unit the pyrite and pyrrhotite are minor and disseminated
114.0 – 114.5 Carbonate-rich clay fault gouge
114.5 – 137.2 Metagreywacke and phyllite. Phyllite is highly chloritized and contains fine-grained pyrite and pyrrhotite
137.2 – 150.6 Dominantly chloritized phyllite with minor carbonitized metagreywacke. The few cross-cutting structures that are present are small. Minor pyrite and pyrrhotite in phyllite layers
150.6 – 156.65 Same as above, except 75% metagreywacke, 15% phyllite and 10% fabric parallel quartz veins
156.65 – 174.0 Same as above, except 40% metagreywacke, 50% phyllite and 10% fabric parallel quartz veins
174.0 – 183.5 Carbonate altered metagreywacke with a trace of pyrite
183.5 – 204.0 Dominantly metagreywacke with 10% phyllite and 5% quartz veins. Chlorite, silica, and sericite alteration have taken the place of carbonate. Silicicly altered zones have small blue quartz eyes
204.0 – 209.9 60% phyllite with 35% metagreywacke and 5% quartz veins. No carbonate alteration. Minor pyrite and pyrrhotite
209.9 – 219.1 Silicified quartz-eye bearing metagreywacke with minor phyllite and quartz veining
219.1 – 241.5 Dominantly phyllite with minor greywacke; mineralization and alteration patterns are the same as the rest of the hole
241.5 – 248.41 Same as the unit above, except the proportions of phyllite and sulphides are lower, and there is one cross-cutting quartz vein that contains stibnite.
248.41 EOH

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
0.00	7.00	CAS
		Casing
7.00	9.90	QRZT
		Foliated quartzite/metasilstone
		Moderate silicic alteration
		Small blebs of iron carbonate (siderite) and 'regular' white carbonate is
		pervasive, making up ~10% of the rock
		quartzite is stained red from siderite
		siderite and carbonate veins cross-cut foliation
		< @ 8.30 S1 35.00° >
		< @ 8.90 siderite V 75.00° 10.00 >
		< @ 9.50 carbonate V 75.00° 5.00 >
		« Mostly in the form of siderite/carbonate blebs crb 3.00*»
		« sil 2.00*»
9.90	16.00	Brx
		Carbonitized quartzite breccia, now healed
		Before brecciation, this rock was likely the same unit as above
		Now, the unit is cut by thick quartz veins and pervasively overprinted by
		patches of carbonate
		< @ 12.60 quartz V 75.00° 25.00 >
		< @ 15.50 quartz V 65.00° 20.00 >
		« very strong carbonate alteration crb 4.00*»
		« sil 2.00*»
16.00	24.30	QRZT
		Moderately foliated quartzite/silicified metasiltstone
		Unit is mostly silicicly alterred, but there are few layers that have similar
		iron carbonate alteration to the top-most unit
		20.5 - 21 m has fine-grained interbeds altered to sericite
		Sericite and siderite zones have trace of pyrite
		« sil 3.00*»
		« crb 2.00*»
		« 20.50- 21.00 ser 2.00*»
		« py 0.50%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
7.00	8.50	E856398	0.01	0.20	65.00	14	27
8.50	10.00	E856399	0.01	0.20	179.00	29	39
10.00	11.50	E856400	0.02	0.20	111.00	20	30
11.50	13.00	E856401	0.01	0.20	8.00	8	13
11.50	13.00	E856402					
13.00	14.50	E856403	0.01	0.20	8.00	13	40
14.50	16.00	E856404	0.01	0.20	12.00	19	29
16.00	17.50	E856405	0.01	0.20	6.00	17	42
17.50	19.00	E856406	0.01	0.20	88.00	17	27
19.00	20.50	E856407	0.19	0.30	767.00	17	27
20.50	22.00	E856408	0.28	0.40	1090.00	15	50
20.50	22.00	E856409					
20.50	22.00	E856410					
22.00	23.50	E856411	0.26	0.60	1050.00	20	38

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
		< @ 18.20 S1 55.00° >
		< @ 21.25 quartz/chlorite V 55.00º 30.00 >
		< @ 21.70 carbonate V 85.00º 3.00 >
		< @ 23.40 S1 70.00° >
24.30	25.45	Brx
		quartzite breccia healed with silica and siderite/carbonate
		Margins of cross-cutting quartz-carbonate vein contain moderate quantitiy of
		arsenopyrite
		« crb 3.00*»
		« sil 2.00*»
		< @ 24.80 quartz-carbonate with aspy V 20.00º 10.00 >
		« apy 0.50%»
		< @ 25.20 siderite V 35.00º 5.00 >
25.45	28.40	QRZT
		Almost entirely faulted quartzite, heavaily altered with quartz and iron
		carbonate
		Intact fragments that are cut by veins show moderate mineralization; both
		pyrite and aspy
		« py 0.50%»
		« apy 1.00%
		< @ 25.80 S1 55.00° >
28.40	32.00	Brx
		fractured breccia zone
		top 1 m of unit is mostly carbonate-altered sandstone
		Remainder of unit is carbonitized, silicified quartzite breccia
		Moderately faulted
		pyrite mineralization surrounds large rusty quartz-carbonate veins
		« py 1.00%»
		< @ 28.80 S1 40.00° >
		< @ 30.20 druzy quartz-carbonate V 80.00º 15.00 >
		< @ 31.20 surface is sericite Ft 50.00º 100.00mm >
		< @ 31.60 qtz-carbonate V 60.00º 10.00 >
		« crb 3.00*»
		« sil 2.00*»
32.00	38.50	Brx



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
23.50	25.00	E856412	0.20	0.30	902.00	12	44
25.00	26.50	E856413	1.55	0.50	2720.00	13	67
26.50	28.00	E856414	0.85	0.20	2740.00	12	191
28.00	29.50	E856415	0.14	0.20	594.00	16	16
29.50	31.00	E856416	0.06	0.20	317.00	6	14
31.00	32.50	E856417	0.01	0.20	120.00	13	16
32.50	34.00	E856418	0.01	0.20	151.00	10	15

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
		Highly fractured and faulted zone with a few more competent zones of the same
		breccia as above
		Fault surfaces covered with sericite/chlorite
		Breccia healed with pervasive quartz/carbonate/siderite alteration
		trace pyrite
		« py 0.10%»
		« crb 2.00*»
		« sil 2.00*»
		« chl 1.00*»
		« ser 1.00*»
		< @ 32.20 Ft 60.00° 100.00mm >
		< @ 32.00 S1 40.00° >
		< @ 36.20 Ft 40.00° 500.00mm >
38.50	50.29	MGWK
		Silicified metagreywacke with interbedded phyllite and minor fabric-paralel
		quartz veins
		phyllititc layers contain up to 2% pyrite
		small amount of aspy in quartz vein at 48.8m
		phyllite layers have light graphitic alteration
		lower 2.5 m contains minor, patchy iron staining
		« sil 1.00*»
		« grp 1.00*»
		« py 1.00%»
		< @ 40.40 S1 40.00° >
		< @ 40.40 fabric // qtz V 40.00° 25.00 >
		< @ 47.35 qtz-carb V 65.00° 30.00 >
		< @ 49.20 vuggy quartz V 80.00° 20.00 >
		< @ 49.70 vuggy quartz V 40.00° 10.00 >
		< @ 50.10 S1 30.00° >
50.29	64.25	MGWK
		Extremely faulted metagreywacke with interbedded phyllite
		Some (1%) sulphide hosted in quartz veins and disseminated in phyllite layers
		Iron staining and minor siderite veinlets are pervasive throughout unit
		few small aspy crystals in quartz vein around 57m
		< @ 52.00 quartz-siderite V 30.00° 200.00 >
		< @ 57.00 V 70.00° 50.00 >
		< @ 57.50 S1 75.00° >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
34.00	35.50	E856419	0.01	0.20	140.00	42	29
35.50	37.00	E856420	0.01	0.20	82.00	22	14
37.00	38.50	E856421	0.02	0.20	186.00	23	30
37.00	38.50	E856422					
38.50	40.00	E856423	0.08	0.20	244.00	17	31
40.00	41.50	E856424	0.01	0.20	10.00	29	45
41.50	43.00	E856425	0.01	0.20	2.00	24	52
43.00	44.50	E856426	0.01	0.20	15.00	16	29
44.50	46.00	E856427	0.03	0.20	1430.00	15	43
46.00	47.50	E856428	0.20	0.40	2560.00	61	26
46.00	47.50	E856429					
46.00	47.50	E856430					
47.50	49.00	E856431	0.08	0.20	295.00	13	11
49.00	50.50	E856432	0.16	0.20	1070.00	14	11
50.50	52.00	E856433	0.22	0.20	2530.00	9	21
52.00	53.50	E856434	0.11	0.40	1650.00	9	20
53.50	55.00	E856435	0.17	0.20	2620.00	14	41
55.00	56.50	E856436	0.07	0.20	539.00	16	10
56.50	58.00	E856437	0.29	0.20	4430.00	13	36
58.00	59.50	E856438	0.17	0.20	3470.00	21	31
59.50	61.00	E856439	0.31	0.30	2010.00	17	31
61.00	62.50	E856440	0.16	0.20	825.00	6	12
62.50	64.00	E856441	0.01	0.20	72.00	22	24

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
64.25	70.70	MGWK
		silicified metagreywacke, highly faulted with a few interbeds of phyllite
		A few large quartz-carbonate-chlorite veins cut the host rock
		Trace amounts of pyrite
		« py 0.10%»
		« sil 2.00*»
		< @ 67.10 quartz V 60.00º 5.00 >
		< @ 69.40 quartz carbonate V 70.00º 40.00 >
		< @ 70.10 S1 70.00° >
70.70	77.70	MGWK
		lightly silicified metagreywacke with small cross-cutting qtz-carb veins and
		almost no fabric // quartz veins
		« sil 1.00*»
		« py 0.10%»
		< @ 73.30 S1 60.00° >
		< @ 73.60 carbonate V 25.00º 5.00 >
77.70	87.10	PHYL
		chloritized phyllite with ~20% interbedded metagreywacke and abundant large (up
		to 35 cm wide) fabric // quartz veins
		Some layers have light sericite alteration
		some veins surrounded by patchy carbonate alteration
		some veins are up to 15% chlorite
		< @ 85.20 qtz-carbonate V 70.00º 10.00 >
		< @ 85.90 S1 60.00° >
		< @ 86.40 Ft 55.00º 50.00mm >« crb 1.00*»
		« sil 1.00*»
		« chl 2.00*»
		« ser 1.00*»
87.10	99.70	PHYL
		chloritic, sericitic phyllite with minor (<5%) quartz-carbonate veins
		small, discrete zones of silicic and carbonate alteration
		99 - 99.1 m is a zone of fractures, oddly iron-stained rock



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
62.50	64.00	E856442					
64.00	65.50	E856443	0.01	0.20	60.00	18	24
65.50	67.00	E856444	0.25	0.20	2300.00	18	24
67.00	68.50	E856445	0.01	0.20	115.00	14	16
68.50	70.00	E856446	0.01	0.20	92.00	14	33
70.00	71.50	E856447	0.01	0.20	14.00	13	24
71.50	73.00	E856448	0.01	0.20	28.00	15	19
71.50	73.00	E856449					
71.50	73.00	E856450					
73.00	74.50	E858001	0.01	0.20	35.00	25	41
74.50	76.00	E858002	0.01	0.20	13.00	18	19
76.00	77.50	E858003	0.01	0.20	3.00	17	20
77.50	79.00	E858004	0.01	0.20	4.00	17	18
79.00	80.50	E858005	0.01	0.20	4.00	16	16
80.50	82.00	E858006	0.01	0.20	3.00	8	34
82.00	83.50	E858007	0.01	0.20	3.00	40	63
83.50	85.00	E858008	0.01	0.20	2.00	7	78
83.50	85.00	E858009					
83.50	85.00	E858010					
85.00	86.50	E858011	0.01	0.20	2.00	9	67
86.50	88.00	E858012	0.01	0.20	2.00	9	66
88.00	89.50	E858013	0.01	0.20	2.00	9	97
89.50	91.00	E858014	0.01	0.20	3.00	8	75
91.00	92.50	E858015	0.01	0.20	2.00	21	83
92.50	94.00	E858016	0.01	0.20	2.00	4	89

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
		< @ 89.20 quartz-carbonate-chlorite V 60.00º 60.00 >
		< @ 90.50 S1 60.00° >
		< @ 90.70 gouge is highly chloritic Ft 30.00º 300.00mm >
		< @ 92.20 quartz-carbonate V 60.00º 30.00 >
		< @ 97.80 qtz-carbonate V 60.00º 10.00 >
		« chl 3.00*»
		« ser 2.00*»
		« sil 1.00*»
		« crb 1.00*»
99.70	114.00	MGWK
		Carbonitized metagreywacke with interbedded (~30%) chloritic phyllite
		There is some fabric // quartz-carbonate-chlorite veining (5%) and silicic
		ateration, but strong carbonate alteration is dominant especially in the top
		half of the unit
		Minor pyrite and pyrrhotite - 104.6 - 104.7 m is almost 10% pyrrhotite.
		Elsewhere it is mostly just disseminated
		carbonate
		< @ 100.10 vein of almost pure carbonate V 70.00º 150.00 >
		< @ 103.60 S1 60.00° >
		< @ 101.70 qtz-carb-chlorite V 50.00º 65.00 >
		< @ 113.00 S1 60.00° >
		« py 0.50%»
		« po 1.00%»
		« 104.60- 104.70 po 10.00%
		« 99.70- 114.00 crb 3.00*»
		« sil 1.00*»
		« chl 1.00*»
114.00	114.50	Clay
		Clay-sized fault gouge. Carbonate-rich
		« crb 3.00*»
114.50	137.20	MGWK
		50% metagreywacke, 40% phyllite, 10% quartz veins
		carbonate alteration is weaker than above, but still preveant throughout the
		metagreywacke layers
		Faults and phyllite layers are moderately chloritized.
		Fabric // veins are composed primariy of quartz, with subordinate carbonate and
		chlorite



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
94.00	95.50	E858017	0.01	0.20	2.00	23	73
95.50	97.00	E858018	0.01	0.20	2.00	24	76
97.00	98.50	E858019	0.01	0.20	2.00	4	74
98.50	100.00	E858020	0.09	0.20	3.00	20	64
100.00	101.50	E858021	0.01	0.30	16.00	19	35
100.00	101.50	E858022					
101.50	103.00	E858023	0.01	0.20	21.00	18	45
103.00	104.50	E858024	0.01	0.30	9.00	28	28
104.50	106.00	E858025	0.01	0.20	4.00	15	54
106.00	107.50	E858026	0.01	0.20	8.00	8	45
107.50	109.00	E858027	0.01	0.20	7.00	40	31
109.00	110.50	E858028	0.01	0.20	7.00	43	57
109.00	110.50	E858029					
109.00	110.50	E858030					
110.50	112.00	E858031	0.01	0.20	10.00	7	54
112.00	113.50	E858032	0.01	0.20	9.00	13	48
113.50	115.00	E858033	0.01	7.20	43.00	23	54
115.00	116.50	E858034	0.01	0.20	3.00	14	51
116.50	118.00	E858035	0.01	0.20	6.00	16	60
118.00	119.50	E858036	0.01	0.20	2.00	12	32
119.50	121.00	E858037	0.01	0.20	2.00	14	30
121.00	122.50	E858038	0.01	0.20	6.00	145	62
122.50	124.00	E858039	0.01	0.20	3.00	21	61
124.00	125.50	E858040	0.01	0.20	2.00	18	35

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
		Some layers of metagreywacke are silicly altered, though this is less widespread than carbonate alteration Many phyllite layers have fine-grained disseminated pyrite and pyrrhotite < @ 115.70 cross cutting qtz-carb V 50.00º 10.00 > < @ 121.00 filled with chloritic gouge Ft 20.00º 40.00mm > < @ 121.20 quartz V 60.00º 300.00 > < @ 120.60 S1 50.00° > < @ 125.60 cross-cutting carbonate V 50.00º 5.00 > < @ 127.05 qtz-carb-chlorite V -70.00º 100.00 > < @ 130.35 Ft 60.00º 50.00mm > < @ 134.70 S1 50.00° « py 0.50%» « po 0.50%» « crb 3.00*» « chl 2.00*» « sil 1.00*»
137.20	150.60	PHYL 60% chloritized phyllite, 35% carbonitized metagreywacke, 5% fabric // quartz-carbonate-chlorite veins chlorite alteration is concentrated in phyllite, carbonate in mgwk minor silicic alteration surrounds quartz veins pyrite and pyrrhotite occur mostly as fabric paralel wisps and small blebs, more common in phyllite than mgwk. Some layers show evidence of substantial secondary deformation in the form of crenulations The only cross-cutting structures are rare, small qtz-carbonate veinlets < @ 139.50 S1 60.00° > < @ 141.80 cross-cutting carbonate-qtz V 45.00º 5.00 > < @ 145.70 fabic // qtz V 70.00º 15.00 > < @ 150.50 S1 70.00° > « py 1.00%» « po 1.00%» « chl 2.00*»« crb 3.00*» « sil 1.00*»
150.60	156.65	MGWK Rocks types and alteration styles are the same as above, except proportions are: 75% metagreywacke, 15% phyllite, 10% quartz-carbonate-chlorite veins < @ 155.80 S1 60.00° >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
125.50	127.00	E858041	0.01	0.20	4.00	19	43
125.50	127.00	E858042					
127.00	128.50	E858043	0.01	0.20	2.00	23	39
128.50	130.00	E858044	0.01	0.20	5.00	13	15
130.00	131.50	E858045	0.01	0.20	2.00	12	56
131.50	133.00	E858046	0.01	0.20	6.00	15	59
133.00	134.50	E858047	0.01	0.20	2.00	13	43
134.50	136.00	E858048	0.01	0.20	2.00	15	33
134.50	136.00	E858049					
134.50	136.00	E858050					
136.00	137.50	E858051	0.01	0.60	27.00	50	198
137.50	139.00	E858052	0.01	0.20	2.00	24	51
139.00	140.50	E858053	0.01	0.20	3.00	20	39
140.50	142.00	E858054	0.01	0.20	2.00	16	43
142.00	143.50	E858055	0.01	0.20	2.00	15	44
143.50	145.00	E858056	0.01	0.20	2.00	9	33
145.00	146.50	E858057	0.01	0.20	3.00	12	42
146.50	148.00	E858058	0.01	0.60	2.00	21	51
148.00	149.50	E858059	0.01	0.20	7.00	15	39
149.50	151.00	E858060	0.01	0.20	2.00	20	38
151.00	152.50	E858061	0.01	0.20	2.00	10	24
151.00	152.50	E858062					
152.50	154.00	E858063	0.01	0.20	2.00	12	31
154.00	155.50	E858064	0.01	0.20	2.00	14	25

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
		< @ 153.65 qtz-carb-chlorite V 80.00º 100.00 >
		« po 1.00%»
		« py 0.50%»
		« crb 3.00*»
		« chl 2.00*»
156.65	174.00	PHYL
		Rocks types and alteration styles are the same as above, except proportions
		are: 40% metagreywacke, 50% phyllite, 10% quartz-carbonate-chlorite veins
		< @ 159.95 V 70.00º 15.00 >
		< @ 166.70 S1 60.00° >
		< @ 163.70 V 50.00º 150.00 >
		< @ 168.40 S1 50.00° >
		< @ 173.60 gouge is suphide-rich, slightly graphitic Ft 55.00º 250.00mm >
		« po 1.00%»
		« py 1.00%»
		« chl 2.00*»
		« crb 2.00*»
174.00	183.50	MGWK
		This unit is almost exclusively carbonate-altered metagreywacke
		Only a trace of disseminated pyrite
		« crb 4.00*»
		< @ 178.30 S1 65.00° >
		< @ 183.05 carbonate V 65.00º 35.00 >
183.50	204.00	MGWK
		Metagreywacke with 10% phyllite and 5% quartz veins
		Carbonate alteration is still present in several zones but not as widespread or
		intense as above
		Other alteration styles (chlorite, silica and sericite) are present in place of
		carbonate
		The whole unit has trace to 1% pyrite and pyrrhotite, with one zone (186.1 -
		186.4) containing nearly 5%



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
155.50	157.00	E858065	0.01	0.20	2.00	12	44
157.00	158.50	E858066	0.01	0.20	2.00	16	46
158.50	160.00	E858067	0.01	0.20	8.00	11	31
160.00	161.50	E858068	0.01	0.20	4.00	16	56
160.00	161.50	E858069					
160.00	161.50	E858070					
161.50	163.00	E858071	0.01	0.20	5.00	27	64
163.00	164.50	E858072	0.01	0.20	3.00	21	63
164.50	166.00	E858073	0.01	0.20	2.00	12	65
166.00	167.50	E858074	0.01	0.20	2.00	8	66
167.50	169.00	E858075	0.01	0.20	6.00	12	58
169.00	170.50	E858076	0.01	0.20	2.00	7	57
170.50	172.00	E858077	0.01	0.20	4.00	7	55
172.00	173.50	E858078	0.01	0.20	3.00	17	44
173.50	175.00	E858079	0.01	0.20	3.00	7	16
175.00	176.50	E858080	0.01	0.20	3.00	10	25
176.50	178.00	E858081	0.01	0.20	2.00	7	18
176.50	178.00	E858082					
178.00	179.50	E858083	0.01	0.20	2.00	11	29
179.50	181.00	E858084	0.01	0.20	2.00	9	16
181.00	182.50	E858085	0.01	0.20	2.00	32	46
182.50	184.00	E858086	0.01	0.70	2.00	26	40
184.00	185.50	E858087	0.01	0.30	2.00	58	46
185.50	187.00	E858088	0.01	0.20	11.00	24	42
185.50	187.00	E858089					
185.50	187.00	E858090					
187.00	188.50	E858091	0.01	0.60	7.00	24	58
188.50	190.00	E858092	0.01	0.20	2.00	21	42
190.00	191.50	E858093	0.01	0.20	3.00	28	41
191.50	193.00	E858094	0.01	0.30	2.00	25	43

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
		This zone contains 2-3mm wide blue quartz eyes and is bracketed by two large
		quartz veins which themselves contain sulphide blebs
		There are a few small cross-cutting carbonate veins
		« chl 1.00*»
		« ser 1.00*»
		« sil 2.00*»
		« py 01.0%»
		« 186.10- 184.40 py 2.50%»
		« po 2.50%»
		< @ 186.40 quartz with carbonate, sulphide and chlorite V 30.00° 500.00 >
		< @ 187.10 Ft 20.00° 5.00mm >
		« 194.00- 197.00 crb 2.00*»
		< @ 188.60 S1 70.00° >
		< @ 191.10 S1 70.00° >
		< @ 191.10 qtz-chl V 70.00° 50.00 >
		< @ 198.50 S1 70.00° >
204.00	209.90	PHYL
		60% phyllite, 35% mgwk, 5% quartz veins
		phyllite layers have 1% pyrite, 0.5 % pyrrhotite
		carbonate alteration is absent; silica and chlorite alteration are weak
		« chl 1.00*»
		« sil 1.00*»
		« py 0.50%»
		« po 0.25%»
		< @ 206.80 S1 70.00° >
		< @ 209.20 V 75.00° 60.00 >
209.90	219.10	MGWK
		80% mgwk, 15% phyllite, 5% quartz veins
		mgwk layers are silicified and contain rare blue quartz eyes
		cross-cutting structures are small and rare
		< @ 211.30 fabric // qtz V 60.00° 60.00 >
		< @ 212.50 S1 55.00° >
		< @ 215.20 cross-cutting qtz-carbonate V 75.00° 25.00 >
		< @ 209.90 S1 75.00° >
		« sil 2.00*»
		« chl 1.00*»
		« py 0.25%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
193.00	194.50	E858095	0.01	0.30	2.00	14	49
194.50	196.00	E858096	0.01	0.20	2.00	18	84
196.00	197.50	E858097	0.01	0.50	2.00	19	45
197.50	199.00	E858098	0.01	0.40	5.00	23	175
199.00	200.50	E858099	0.01	0.30	11.00	15	93
200.50	202.00	E858100	0.01	0.20	6.00	17	96
202.00	203.50	E858101	0.01	0.20	2.00	5	46
202.00	203.50	E858102					
203.50	205.00	E858103	0.01	0.20	5.00	14	65
205.00	206.50	E858104	0.01	0.20	2.00	60	45
206.50	208.00	E858105	0.01	0.20	2.00	19	93
208.00	209.50	E858106	0.01	0.20	2.00	20	92
209.50	211.00	E858107	0.01	0.20	4.00	18	51
211.00	212.50	E858108	0.01	0.20	8.00	6	57
211.00	212.50	E858109					
211.00	212.50	E858110					
212.50	214.00	E858111	0.01	0.30	63.00	22	236
214.00	215.50	E858112	0.01	0.50	4.00	14	32
215.50	217.00	E858113	0.01	0.20	2.00	10	31
217.00	218.50	E858114	0.01	0.20	5.00	10	46

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
		« po 0.25%»
219.10	241.50	PHYL
		70% phyllite, 25% mgwk and 5% quartz veins
		This is part of the same package of rocks as the rest of the hole, just slightly richer in phyllite than above. As there is more phyllite to act as a host, the overall proportion of pyrite and pyrrhotite is slightly higher, but they are still found almost entirely as fabric-paralel wisps in the phyllite layers. The sulphides are more abundant in the top part of the unit.
		< @ 227.90 V 70.00º >
		< @ 231.70 cross-cutting quartz-carbonate V 70.00º 20.00 >
		« po 1.00%»
		« py 0.50%»
		< @ 241.80 S1 80.00° >
241.50	248.41	PHYL
		60% phyllite, 30% mgwk, 10% quartz
		This unit is cut by several large late-stage quartz veins, one of which contans some well-formed stibnite crystals. The rest are barren, containing only quartz, or a mixture of quartz and chlorite. The overall concentration of sulphide has dropped in this unit, now only a trace except for a few isolated pyrite crystals.
		« sil 1.00*»
		« chl 1.00*»
		« py 0.50%»
		« po 0.10%»
		< @ 241.60 vuggy quartz; several vugs are inflled with euhedral stibnite V 10.00º 30.00 >
		< @ 243.30 cross-cutting quartz-chlorite V 35.00º 20.00 >
		< @ 244.00 S1 60.00° >
		< @ 248.00 S1 65.00° >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
218.50	220.00	E858115	0.01	0.30	4.00	23	59
220.00	221.50	E858116	0.01	0.20	9.00	9	74
221.50	223.00	E858117	0.01	0.20	4.00	17	90
223.00	224.50	E858118	0.01	0.20	9.00	13	53
224.50	226.00	E858119	0.01	0.20	2.00	7	42
226.00	227.50	E858120	0.01	0.20	6.00	20	64
227.50	229.00	E858121	0.01	0.20	2.00	34	59
227.50	229.00	E858122					
229.00	230.50	E858123	0.01	0.20	15.00	22	70
230.50	232.00	E858124	0.01	0.20	12.00	17	74
232.00	233.50	E858125	0.01	0.30	14.00	18	65
233.50	235.00	E858126	0.01	0.20	19.00	22	79
235.00	236.50	E858127	0.01	0.20	4.00	7	46
236.50	238.00	E858128	0.01	0.20	13.00	24	67
236.50	238.00	E858129					
236.50	238.00	E858130					
238.00	239.50	E858131	0.01	0.20	8.00	9	83
239.50	241.00	E858132	0.01	0.20	21.00	32	74
241.00	242.50	E858133	0.01	0.20	31.00	5	10
242.50	244.00	E858134	0.01	0.30	27.00	14	54
244.00	245.50	E858135	0.01	0.20	13.00	13	43
245.50	247.00	E858136	0.01	0.30	7.00	32	92
247.00	248.41	E858137	0.01	0.20	15.00	8	66

Project: Keystone **Hole Number:** KEY10-07

From	To	Rocktype & Description
		EOH@248.41
248.41	248.41	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm

EQUITY

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 3937.0
Hole KEY10-08	**Azimuth (º):** 325
Location: 7077639 m North, 490028 m East	**Dip (º):** -70.0
Logged by: D. Swanton	**Length (m):** 73.00
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: BTW	**Objective** To investigate the source of a broad soil anomaly with Au values 200 - 400 ppb on the eastern slope of the western tributary of Keystone Creek, and to look for continuation of the NE-SW trending structure investigated in earlier holes.
Date Started: 2010/07/07 **Date Completed:** 2010/07/10	
Dip Tests By:	

Summary Log:

0.00 - 4.50 Casing
4.5 - 8.0 Fractured iron-cabonate saturated foliated quartzite
8.0 - 13.95 Metagreywacke breccia healed with carbonate
13.95 - 17.0 Same as 4.5 - 8.0
17.0 - 25.4 Micaceous quartzite with trace disseminated pyrite, locally carbonate altered
25.4 - 28.6 iron carbonate altered quartzite, same as above
28.6 - 37.0 fractured quartzite grading to greywacke, with iron carbonate, minor chlorite and sericite.
37.0 - 42.1 fractured metagreywacke with phyllite interbeds altered to chlorite and sericite. MInor pyrite on fracture surfaces and fabric paralel quartz veins. Minor carbonate alteration
42.1 - 49.8 Silicified metagreywacke with subordinate carbonate alteration in upper section
49.8 - 51.9 Fractured metagreywacke and phyllite. Silicicly altered with carbonate veinlets
51.9 - 63.5 Silicified metagreywacke with traces of pyrite and fabric paralel quartz veins
63.5 - 71.5 Black phyllite and carbonate altered metagreywacke
71.5 - 73.0 Gravel fault zone; lost hole
73.0 EOH

Downhole surveys:

Depth	Dip	Azimuth
0.00	-70.00	325.00
73.00	-70.00	325.00

Project: Keystone **Hole Number:** KEY10-08

From	To	Rocktype & Description
0.00	4.50	CAS
		Casing
4.50	8.00	QRZT
		Very fractured iron-carbonate saturated foliated quartzite
		« Rusty iron carbonate crb 3.00*»
		< @ 5.50 S1 60.00° >
8.00	13.95	Brx
		-Metagreywacke breccia healed with carbonate
		-Carbonate forms cm-size clasts
		-20-cm long band of chlorite at 13 m
		< @ 12.30 carbonate V 80.00° 15.00 >
13.95	17.00	QRZT
		-Foliated quartzite with large mica on fabric surfaces
		-Stained dark red by intense iron carbonate alteration
		« red iron carbonate crb 3.00*»
		< @ 14.10 quartz-carbonate V 60.00° 10.00 >
		< @ 14.30 S1 60.00° >
		< @ 15.50 cross-cutting carbonate V 50.00° 7.00 >
17.00	25.40	QRZT
		-Foliated micacious grey quartzite
		-Trace disseminated pryite except at 19 m, where there are several cm-size blobs of pyrite
		-Locally alterred as above, but not as intensly
		-Very bottom of unit transitions into metagreywacke
		< @ 18.40 S1 60.00° >
		< @ 20.75 Ft 80.00°-50.00mm >
		< @ 24.90 cross-cutting siderite V 20.00° 20.00 >
25.40	28.60	QRZT
		-Same iron carbonate alterred quartzite as 13.95 - 17.00 m
		< @ 26.70 S1 50.00° >
		« red iron carbonate crb 3.00*»

From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
4.50	6.00	E858138	0.01	0.20	48.00	12	24
6.00	7.50	E858139	0.01	0.20	126.00	20	32
7.50	9.00	E858140	0.01	0.20	32.00	24	37
9.00	10.50	E858141	0.01	0.20	404.00	115	147
9.00	10.50	E858142					
10.50	12.00	E858143	0.01	0.20	59.00	55	112
12.00	13.50	E858144	0.01	0.20	9.00	10	50
13.50	15.00	E858145	0.01	0.20	141.00	16	58
15.00	16.50	E858146	0.02	0.20	142.00	22	27
16.50	18.00	E858147	0.01	0.30	56.00	23	40
18.00	19.50	E858148	0.01	0.20	17.00	24	20
18.00	19.50	E858149					
18.00	19.50	E858150					
19.50	21.00	E858151	0.01	0.40	59.00	19	24
21.00	22.50	E858152	0.01	0.20	18.00	16	31
22.50	24.00	E858153	0.01	0.20	8.00	29	37
24.00	25.50	E858154	0.01	0.20	24.00	30	72
25.50	27.00	E858155	0.01	0.20	143.00	26	37
27.00	28.50	E858156	0.01	0.20	51.00	15	19
28.50	30.00	E858157	0.01	0.20	127.00	29	31

Project: Keystone **Hole Number:** KEY10-08

From	To	Rocktype & Description
28.60	37.00	QRZT
		-Moderately fractured quartzite grading to mgwk with intermittent iron carbonate alteration
		-Some layers have minor chlorite and sericite alteration
		-Cross-cutting carbonate veinlets are common
		< @ 31.50 S1 70.00° >
		< @ 34.00 cross-cutting carbonate V 70.00° 5.00 >
		« py 0.10%»
		« crb 2.00*»
		« chl 1.00*»
		« ser 1.00*»
37.00	42.10	MGWK
		-Intensely fractured metagreywacke with phyllite interbeds which are altered to chlorite and sericite
		-crystaline pyrite is present on foliation surfaces and around a few fabric paralel quartz veins
		-several sections are intensly alterred by iron carbonate
		-40.8 - 41.0 quartz breccia infilled with iron carbonate
		« crb 2.00*»
		« chl 1.00*»
		« ser 1.00*»
		< @ 40.30 S1 50.00° >
		< @ 40.40 quartz-crb V 65.00° 15.00 >
		« py 0.50%»
42.10	49.80	MGWK
		-The unit is dominantly silicified metagreywacke with small carbonate veinlets and subodinate carbonate alteration
		-upper part is has carbonate stockwork veining
		-45.1 - 46.1 m is chorite/siderite altered phyllite and mgwk
		< @ 42.20 carbonate rimmed with siderite V 5.00° 10.00 >
		< @ 44.20 Rimmed by siderite Ft 40.00° 2.00mm >
		< @ 46.80 S1 70.00° >
		« sil 2.00*»
		« 45.00- 46.00 crb 2.00*»
		« chl 2.00*»
		« py 1.00%»
49.80	51.90	MGWK



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
30.00	31.50	E858158	0.01	0.20	87.00	17	27
31.50	33.00	E858159	0.01	0.20	91.00	9	41
33.00	34.50	E858160	0.01	0.80	133.00	19	40
34.50	36.00	E858161	0.02	0.30	281.00	11	28
34.50	36.00	E858162					
36.00	37.50	E858163	0.09	0.20	1750.00	13	39
37.50	39.00	E858164	0.34	0.60	4530.00	18	47
39.00	40.50	E858165	0.68	0.30	7600.00	24	57
40.50	42.00	E858166	0.56	0.40	2390.00	12	24
42.00	43.50	E858167	0.13	0.20	647.00	17	21
43.50	45.00	E858168	0.53	0.20	1835.00	5	7
43.50	45.00	E858169					
43.50	45.00	E858170					
45.00	46.50	E858171	0.01	0.70	159.00	44	128
46.50	48.00	E858172	0.01	0.20	6.00	15	16
48.00	49.50	E858173	0.01	0.20	26.00	22	47

Project: Keystone **Hole Number:** KEY10-08

From	To	Rocktype & Description
		-Unit is composed of even proportions of metagreywacke and phyllite -The entire length of the unit is highly fractured and broken -Dominant alteration style is silicic, though there are many carbonate veinlets < @ 51.70 S1 60.00° > < @ 51.70 vuggy quartz and carbonate V 60.00º 75.00 >
51.90	63.50	MGWK
		-Silicified metagreywacke -There are small, rare carbonate veinlets -more common are fabric paralel quartz-chlorite veins -only a few traces of pyrite, except for some well-formed pyrite and chalocopyrite crystals on a fracture surface at 51.9m « py 0.10%» < @ 53.00 quartz V 75.00º 20.00 > < @ 55.20 S1 50.00° > < @ 63.00 Ft 65.00º 50.00mm >« sil 2.00*»
63.50	71.50	MGWK
		-Approximately half carbonate-altered metagreywacke and half black phyllite -Both rock types are lightly chloritized -phyllite is cut by fabric paralel quartz-carbonate-chlorite veins < @ 65.50 S1 70.00° > < @ 69.30 V 60.00º 10.00 > « chl 1.00*» « 65.50- 67.00 crb 3.00*»
71.50	73.00	Fault
		Gravel fault zone; lost hole EOH@73.0m
73.00	73.00	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
49.50	51.00	E858174	0.27	0.20	4320.00	32	48
51.00	52.50	E858175	0.11	0.20	1570.00	15	55
52.50	54.00	E858176	0.02	0.20	214.00	19	52
54.00	55.50	E858177	0.01	0.20	123.00	15	32
55.50	57.00	E858178	0.01	0.20	29.00	10	17
57.00	58.50	E858179	0.01	0.20	43.00	15	32
58.50	60.00	E858180	0.01	0.20	13.00	23	40
60.00	61.50	E858181	0.01	0.20	15.00	15	68
60.00	61.50	E858182					
61.50	63.00	E858183	0.01	0.20	10.00	10	49
63.00	64.50	E858184	0.01	0.20	26.00	14	42
64.50	66.00	E858185	0.02	0.20	142.00	16	48
66.00	67.50	E858186	0.09	0.20	461.00	14	32
67.50	69.00	E858187	0.02	0.20	198.00	23	62
69.00	70.50	E858188	0.01	0.20	785.00	7	76
69.00	70.50	E858189	0.02	0.20	192.00	16	60
69.00	70.50	E858190					
70.50	72.00	E858191	0.07	0.20	2150.00	64	102
72.00	73.00	E858192					

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 5396.0
Hole KEY10-09	**Azimuth (º):** 325
Location: 7079440 m North, 491607 m East	**Dip (º):** -50.0
Logged by: M. McKeown	**Length (m):** 224.64
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: NTW	**Objective** To investigate possible mineralization creating the local 1075ppm Au soil anomaly thought to be controlled by a NE trending structure.
Date Started: 2010/07/07 **Date Completed:** 2010/07/14	
Dip Tests By:	

Summary Log:

4.5-12.3: Interlayered micaceous and graphitic phyllite with abundant Fe-oxide staining and trace pyrite (0.1%).
12.3-25.93: Fractured metagreywacke with bands of carbonate alteration and some pitted where the carbonate alteration has weathered out.
25.93-52.66: Interlayered micaceous (60%) and graphitic phyllite (20%) and metagreywacke(20%) with abundant Fe-oxide staining along fabric parallel fractures.
40.00-45.00: Same unit as above with vuggy quartz veins with trace tetrahedrite (0.5%) and possibly trace oxides of stibnite (0.5%).
52.66-53.31: Heavily chlorite altered schist with pits where carbonate alteration has weathered out.
53.31-78.62: Fractured and faulted metagreywacke with rare fabric-cutting quartz veins with trace arsenopyrite (0.1%) and pyrite (1%) along selvages.
78.62-79.28: Metagreywacke with abundant vuggy quatz veins with trace arsenopyrite (1.5%) and scorodite (2%).
79.28-82.69: Silicified phyllite with abundant fabric cutting quartz veins with trace arsenopyrite (0.5%).
82.69-113.35: Fault zone, 85% fault gouge.
113.5-223.05: Silica altered graphitic phyllite with trace disseminated py (2%) and apy (0.5%) throughout.
223.05-224.64: Highly magnetic sand/clay that may just be bit cuttings.
224.64: EOH

Downhole surveys:

Depth	Dip	Azimuth
0.00	-70.00	325.00
224.64	-70.00	325.00

Project: Keystone **Hole Number:** KEY10-09

From	To	Rocktype & Description
0.00	4.50	CAS
4.50	12.30	PHYL
		Interlayered light grey micaceous phyllite (40%)and dark grey-black graphitic phyllite (60%). Micaceous phyllite is silica altered and the more graphitic interlayers are chlorite altered. Abundant Fe-oxide staining along folliation/fracture surfaces. Few cross cutting quartz veins. Trace pyrite.
		< @ 12.00 S1 40.00° >
		< @ 11.00 S2 30.00° >
		< @ 4.50 10% fault gouge, abundant fractures Ft 1.26m >
		< @ 10.22 abundant fractures along foliation Fr 40.00° 1.29m >
		« chl 2.00*»
		« sil 2.00*»
		« trace py 0.10%»
12.30	25.93	MGWK
		Light green weakly foliated metagreywacke with moderatly abundant chlorite alteration throughout and minor carbonate alteration occuring as specks. There are some small fracture and fault zones. Where carbonate alteration occurs as bands there are some vuggy surfaces where the carbonate has weathered out. Minor Fe-oxide staining along some fracture surfaces (foliation //).
		< @ 20.00 S1 54.00° >
		< @ 14.23 45% gouge Ft 77.00cm >
		< @ 18.07 Fr 50.00cm >
		< @ 21.15 Abundant folliation // fractures and minor gouge Fr 55.00° 2.49m >
		< @ 24.33 randomly oriented fractures Fr 50.00cm >
		< @ 25.49 fabric // fractures Fr 55.00° 41.00cm >
		« chl 2.00*»
		« cal 2.00*
25.93	52.66	PHYL
		Interlayered grey phyllite (60%), graphitic phyllite (20%) and metagreywacke(?)(20%) with abundant folliation // fractures with Fe-oxide staining creating a distinct banded look. The interlayers are on the mm to cm scale. There is abundant carbonate alteration occuring as specks and bands that follow folliation. There is also lesser sericite alteration occuring as fabric

From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
4.50	6.00	E856561	0.01	0.20	35.00	10	24
4.50	6.00	E856562					
6.00	7.50	E856563	0.01	0.20	49.00	14	27
7.50	9.00	E856564	0.01	0.40	192.00	55	92
9.00	10.50	E856565	0.01	0.20	411.00	35	66
10.50	12.00	E856566	0.01	0.20	36.00	81	64
12.00	13.50	E856567	0.01	0.20	71.00	17	79
13.50	15.00	E856568	0.02	0.20	135.00	19	36
13.50	15.00	E856569					
13.50	15.00	E856570					
15.00	16.50	E856571	0.01	0.20	10.00	15	23
16.50	18.00	E856572	0.01	0.20	41.00	54	52
18.00	19.50	E856573	0.01	0.20	21.00	23	43
19.50	20.50	E856574	0.01	0.20	32.00	39	57
20.50	22.00	E856575	0.01	0.20	56.00	44	75
22.00	23.50	E856576	0.01	0.20	241.00	74	86
23.50	25.00	E856577	0.01	0.30	234.00	91	102
25.00	26.50	E856579	0.01	0.20	2.00	5	5
26.50	28.00	E856580	0.01	0.20	262.00	38	37
28.00	29.50	E856581	0.02	0.30	148.00	23	30
28.00	29.50	E856582					
29.50	31.00	E856583	0.04	0.20	232.00	12	27
31.00	32.50	E856584	0.01	0.20	271.00	21	59
32.50	34.00	E856585	0.03	0.60	380.00	15	33

Project: Keystone **Hole Number:** KEY10-09

From	To	Rocktype & Description
		// bands and pervasive silica alteration. There is a distinct zone that has abundant cm scale quartz veins with chlorite that don't always follow foliation. This zone is vuggy and contains both tetrahedrite and stibiconite (pseudomorphing stibnite) within these vugs. Pyrite appears to be forming on the tetrahedrite and weathering out creating a halo of Fe-oxide staining.
		< @ 35.00 S1 40.00° >
		< @ 49.60 Cross cutting quartz-siderite V 4.00cm >
		« cal 3.00*»
		« sil 1.00*»
		« mus 1.00%»
		« Patchy, preferential alteration of graphitic layers chl 2.00*»
		« ser 2.00*»
		« along fracture surfaces fer 2.00°»
		« 40.00- 45.00 In vugs tth 0.50%»
		« Stibiconite (oxide of stibnite) in vugs stb 0.50%
		« 40.00- 45.00 altered tetrahedrite? py 1.00%»
52.66	53.31	SCHT
		Heavily chlorite altered schist. with small pits along foliation where carbonate alteration has weathered out.
		< @ 53.11 100% fault gouge Ft 20.00cm >
		< @ 45.00 S1 0° >
		« pervasive chl 3.00*»
		« specks in bands cal 2.00*»
		« weathered out specks throughout py 1.00%»
53.31	78.62	MGWK
		Foliated and slightly laminated (with silty layers) metagreywacke with abundant fractures along foliation and iron-oxide weathering along fracture surfaces. Abundant pervasive chlorite alteration and lesser specks of carbonate alteration along folitation. There are sporatic ~1cm carbonate veins cutting fabric. Toward the lower portion of this unit pyrite disseminated along folliation and as small blebs becomes increasingly abundant though still trace. Trace arsenopyrite is seen as fine disseminations along fabric cutting quartz veins.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
34.00	35.50	E856586	0.44	0.20	2530.00	8	34
35.50	37.00	E856587	0.02	0.20	1025.00	14	17
37.00	38.50	E856588	0.30	0.30	5720.00	22	33
37.00	38.50	E856589					
37.00	38.50	E856590					
38.50	40.00	E856591	0.15	0.30	1125.00	29	21
40.00	41.50	E856592	0.12	0.20	1445.00	17	26
41.50	43.00	E856593	0.02	0.20	110.00	12	17
43.00	44.50	E856594	0.16	0.30	506.00	9	13
44.50	46.00	E856595	0.01	0.20	20.00	8	7
46.00	47.50	E856596	0.01	0.20	34.00	18	25
47.50	49.00	E856597	0.01	0.20	334.00	13	46
49.00	50.50	E856598	0.01	0.30	297.00	13	46
50.50	52.00	E856599	0.86	100.00	4700.00	5180	10000
52.00	53.00	E856600	0.01	0.40	41.00	35	150
53.00	54.00	E856601	0.01	0.20	19.00	22	60
53.00	54.00	E856602					
54.00	55.50	E856603	0.01	0.20	15.00	17	20
55.50	57.00	E856604	0.01	0.20	43.00	16	12
57.00	58.50	E856605	0.02	0.20	76.00	16	19
58.50	60.00	E856606	0.14	0.20	421.00	18	30
60.00	61.50	E856607	0.01	0.20	146.00	2	555
61.50	63.00	E856608	0.01	0.20	30.00	5	212
61.50	63.00	E856609					
61.50	63.00	E856610					
63.00	64.50	E856611	0.01	0.20	73.00	3	615

Project: Keystone **Hole Number:** KEY10-09

From	To	Rocktype & Description
		< @ 57.00 S1 45.00° >
		< @ 72.50 90% fault gouge Ft 50.00cm >
		< @ 59.07 cross cutting quartz creating nearly a bx texture V 64.00cm >
		< @ 71.06 randomly oriented fractures Fr 63.00cm >
		< @ 59.07 50% fault gouge, small rock fragments Ft 48.00cm >
		< @ 55.24 Several zones with abundant, randomly oriented fractures Fr 3.00m >
		< @ 73.19 abundant fracture zones, randomly oriented Fr 2.58m
		< @ 73.61 Fine quartz stockwork veining Vsw 33.00mm >
		« folliation // bands ser 1.00*
		« 59.07- 61.00 Staining along cross cutting qtz veins fer 1.00*»
		« 57.50- 58.00 Abundant staining along fractures fer 2.00*»
		« 53.31- 78.62 pervasive chl 2.00*»
		« 59.07- 61.00 Near fractures, folliation // , some vuggy cal 3.00*»
		« abundant as veins sil 2.00*»
		« 75.00- 78.62 blebs and disseminations along folliation py 0.5%»
		« Trace along qtz vein salvages, very fine py 0.20%»
		« as fine blebs and stringers associated with the iron oxide staining in the quartz vein py 1.00%»
		« fine disseminated apy 0.10%»
78.62	79.28	MGWK
		Mineralized zone of metageywacke with abundant alteration and some fracturing. Foliation // silica, sericite and chlorite alteration with abundant pyrite and lesser arsenopyrite along quartz and sericite veins. In the zone of heavy alteration there are fractures in which bright yellow scoroite occurs. Both arsenopyrite and pyrite occur as slightly blebby disseminations throughout this unit. There is abundant iron oxide staining along fracture surfaces and iron oxide stained fault gouge in the upper part of this section.
		< @ 79.00 S1 45.00° >
		< @ 78.80 80% iron oxide stained fault gouge Ft 35.00º 15.00cm
		« pervasive but also as veins sil 2.00*»
		« as foliation // veins ser 1.00*»
		« following qtz and sericite veins chl 1.00*»
		« In fault gouge and along sericite vein fer 2.00*»
		« blebs and stringers alog veins py 5.00%»
		« fine diseminations along veins apy 1.50%
		« along fractures scd 2.00%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
64.50	66.00	E856612	0.01	0.20	47.00	2	396
66.00	67.50	E856613	0.01	0.20	31.00	2	141
67.50	69.00	E856614	0.01	0.30	67.00	2	245
69.00	70.50	E856615	0.01	15.60	73.00	3	172
70.50	72.00	E856616	0.01	0.30	71.00	2	156
72.00	73.50	E856617	0.47	1.50	2460.00	4	142
73.50	75.00	E856618	0.15	1.10	653.00	7	169
75.00	76.50	E856619	0.25	1.00	2040.00	7	377
76.50	77.87	E856620	0.02	0.20	42.00	2	129
77.87	78.62	E856621	0.01	0.30	86.00	2	332
77.87	78.62	E856622					
78.62	79.28	E856623	1.53	1.70	10000.00	88	896

Project: Keystone **Hole Number:** KEY10-09

From	To	Rocktype & Description
79.28	79.67	PHYL
		Highly altered phyllite with hematite, chlorite and silica alteration along foliation giving a stripped appearance.
		< @ 79.28 S1 35.00° >
		« sil 2.00*»
		« chl 2.00*»
		« foliation // hem 5.00%»
		« fine disseminated along foliation py 0.50%»
		« fine disseminated along foliations apy 0.50%»
79.67	82.69	PHYL
		Highly silicified grey phyllite with abundant cross cutting quartz veins creating a breccia texture in the lower part of this section. Pyrite occurs as small blebs and stringers along folliation as well as along the salvages of cross cutting veins. Arsenopyrite occcurs as very fine disseminations along the phyllitic zones.
		< @ 81.00 S1 35.00° >
		< @ 81.86 Qtz vein creating a breccia texture Vbx 0.83cm >
		< @ 81.70 Fe-oxide stained fault gouge Ft 16.00cm >
		< @ 80.20 Cross cutting quartz V 50.00cm >
		« abundant pervasive alteration and veins sil 3.00*»
		« along vein salvages and disseminated py 2.00%»
		« trace disseminated apy 0.50%»
82.69	113.35	PHYL
		Large fault zone with 85% fault gouge within the graphitic phyllite with a minor interlayer of heavily chlorite altered metagreywacke. The few remaining rock fragments are small and the fractures are randomly oriented. Trace pyrite can be seen in the fault gouge.
		< @ 109.00 Quartz vein, highly fractured V 20.00cm >
		< @ 82.69 85% fault gouge Ft 30.66mm >
		« 100.00- 104.10 Pervasive within the competent rock chl 3.00*»
		« 82.69- 113.35 mus 1.00»
		« py 0.50%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
79.28	80.03	E856624	0.38	2.40	5930.00	134	385
80.03	81.00	E856625	0.36	2.50	3350.00	112	1735
81.00	82.50	E856626	0.88	3.50	10000.00	315	806
82.50	90.00	E856627	0.74	1.70	9900.00	146	305
90.00	91.50	E856628	0.06	1.20	177.00	15	83
90.00	91.50	E856629					
90.00	91.50	E856630					
91.50	94.00	E856631	0.02	1.10	121.00	28	118
94.00	97.00	E856632	0.26	2.60	2320.00	47	223
97.00	98.50	E856633	0.46	0.80	768.00	165	179
98.50	100.00	E856634	0.89	2.60	3240.00	61	470
100.00	101.50	E856635	1.01	3.60	3770.00	1690	817
101.50	103.00	E856636	0.08	3.60	418.00	53	203
103.00	104.50	E856637	0.54	2.50	2800.00	339	183
104.50	105.77	E856638	0.32	1.10	469.00	707	83
108.84	110.00	E856639	0.32	0.70	1410.00	46	124

Project: Keystone **Hole Number:** KEY10-09

From	To	Rocktype & Description
113.35	175.04	PHYL

Very thick, uniform sequence of silica altered graphitic phyllite with trace disseminated pyrite and arsenopyrite. There are numerous fractured zones and moderately abundnt fabric // and cross cutting quartz veins. Silica alteration is pervasive throughout. Disseminated trace pyrite occurs along foliation in blebs and stringers. Fine stringers of arsenopyrite occur along the salvage of cross cutting quartz veins and possibly very fine disseminated arsenopyrite may be occuring along foliation. The late stage, cross-cutting quartz veins tend to also have minor amounts of chlorite alteration within the veins.

< @ 117.00 S1 45.00° >
< @ 113.35 abundant fractures, most randomly oriented Fr 3.65m >
< @ 117.66 Cross cutting qtz vein with trace arsenopyrite and pyrite along salvages V 37.00cm >
< @ 121.95 Heavily silicified zone with stockwork qyz veining Vbx 18.00mm >
< @ 129.84 Abundant fractured rock Fr 45.00º 82.00cm >
< @ 131.00 Abundant fractured rock Fr 45.00º 1.70m >
< @ 140.53 Cross cutting quartz vein with py along salvages V 15.00 >
< @ 141.44 Quartz, foliation // with chlorite V 55.00º >
< @ 141.00 S1 55.00° >
< @ 148.11 abundant fractures, most fabric // Fr 65.00cm >
« pervasive sil 3.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
110.00	111.50	E856640	0.03	0.20	68.00	12	76
111.50	113.00	E856641	0.02	0.30	59.00	13	77
111.50	113.00	E856642					
113.00	114.50	E856643	0.04	0.20	49.00	13	70
114.50	116.00	E856644	0.17	1.70	812.00	9	45
116.00	117.50	E856645	0.43	2.70	1530.00	8	34
117.50	119.00	E856646	0.28	1.90	872.00	11	34
119.00	120.50	E856647	0.02	0.30	62.00	9	44
120.50	122.00	E856648	0.01	0.20	33.00	20	44
120.50	122.00	E856649					
120.50	122.00	E856650					
122.00	123.50	E856651	0.01	0.20	7.00	8	40
123.50	125.00	E856652	0.04	0.20	10.00	9	42
125.00	126.50	E856653	0.01	0.20	10.00	9	42
126.50	128.00	E856654	0.01	0.20	16.00	11	59
128.00	129.50	E856655	0.03	0.20	10.00	8	37
129.50	131.00	E856656	0.03	0.20	10.00	12	39
131.00	132.50	E856657	0.01	0.20	6.00	10	44
132.50	134.00	E856658	0.08	0.20	4.00	8	41
134.00	135.50	E856659	0.03	0.20	2.00	9	44
135.50	137.00	E856660	0.07	0.20	7.00	11	39
137.00	138.50	E856661	0.02	0.20	8.00	11	45
137.00	138.50	E856662					
138.50	140.00	E856663	0.06	0.20	6.00	12	57
140.00	141.50	E856664	0.03	0.20	8.00	10	53
141.50	143.00	E856665	0.01	0.20	14.00	9	40

Project: Keystone **Hole Number:** KEY10-09

From	To	Rocktype & Description
		« as disseminations and blebs py 2.00-3.00%»
		« trace, along vein salvages apy 0.50%»
		« alteration along quartz veins chl 1.00*»
175.04	175.50	PHYL



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
143.00	144.50	E856666	0.02	0.20	12.00	3	41
144.50	146.00	E856667	0.04	0.20	11.00	5	61
146.00	148.50	E856668	0.02	0.20	7.00	6	54
146.00	148.50	E856669					
146.00	148.50	E856670					
148.50	150.00	E856671	0.03	0.30	13.00	16	70
150.00	151.50	E856672	0.02	0.30	8.00	9	65
151.50	153.00	E856673	0.03	0.20	3.00	6	83
153.00	154.50	E856674	0.01	0.20	4.00	3	79
154.50	156.00	E856675	0.01	0.30	7.00	7	52
156.00	157.50	E856676	0.01	0.20	2.00	4	58
157.50	159.00	E856677	0.02	0.20	5.00	7	45
159.00	160.50	E856678	0.04	0.30	6.00	5	37
160.50	162.00	E856679	0.02	0.20	7.00	6	39
162.00	163.50	E856680	0.01	0.20	4.00	6	68
163.50	165.00	E856681	0.08	0.20	4.00	2	71
163.50	165.00	E856682					
165.00	166.50	E856683	0.01	0.20	8.00	7	78
166.50	168.00	E856684	0.01	0.20	10.00	16	50
168.00	169.50	E856685	0.02	0.20	2.00	13	35
169.50	171.00	E856686	0.04	0.20	4.00	8	38
171.00	173.50	E856687	0.03	0.20	6.00	7	35
173.50	175.00	E856688	0.04	0.20	7.00	7	38
173.50	175.00	E856689					
173.50	175.00	E856690					

Project: Keystone **Hole Number:** KEY10-09

From	To	Rocktype & Description
		Fault zone within graphitic phyllite with 70% fault gouge.
		< @ 175.04 70% fault gouge Ft 46.00cm >
175.50	223.05	PHYL
		Same graphitic phyllite unit as above the fault zone with pervasive silica alteration. Trace disseminated pyrite and trace disseminated arsenopyrite rarely along cross cutting vein salvages. Quartz veins are moderately abundant and largely cm scale, foliation // though their are rare cross-cutting quartz veins as well. Chlorite alteration occurs rarely within quartz veins. Pyrite associated with chlorite altered zones.
		< @ 182.70 S1 45.00° >
		< @ 178.20 crenulations S2 20.00° >
		< @ 185.55 Cross cutting quartz with moderately abundant chlorite V 11.00cm >
		< @ 194.65 folliation // quartz vein V 35.00° 10.00cm >
		< @ 201.24 fabric // quartz V 6.00cm >
		< @ 202.86 Highly silicified zone with quartz stockwork veining Vbx 65.00° 27.00cm >
		< @ 205.04 Cross cutting quartz vein with abundant xstaline pyrite in vugs V 18.00cm >
		< @ 206.00 Cross cutting quartz with sericite and chlorite V 28.00cm >
		< @ 208.56 Abundant foliation // fractures Fr 20.00° 84.00cm >
		< @ 211.00 S1 20.00° >
		< @ 221.46 Abundant fractures Fr 30.00cm >
		« pervasive sil 3.00*»
		« largely within cross cutting quartz veins chl 1.00*»
		« disseminated and blebs along foliation py 2.00-5.00%»
		« trace, along salvages of quartz veins apy 0.50%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
175.00	176.50	E856691	0.01	0.20	11.00	11	62
176.50	178.00	E856692	0.01	0.20	10.00	14	65
178.00	179.50	E856693	0.02	0.20	8.00	10	65
179.50	181.00	E856694	0.03	0.20	11.00	8	62
181.00	182.50	E856695	0.01	0.20	11.00	14	53
182.50	184.00	E856696	0.01	0.20	12.00	14	61
184.00	185.50	E856697	0.02	0.20	10.00	14	64
185.50	187.00	E856698	0.01	0.20	4.00	9	48
187.00	188.50	E856699	0.01	0.20	13.00	13	47
188.50	190.00	E856700	0.02	0.20	13.00	8	46
190.00	191.50	E856701	0.01	0.20	9.00	8	56
191.50	193.00	E856702	0.01	0.30	7.00	13	95
193.00	194.50	E856703	0.01	0.20	5.00	16	59
194.50	196.00	E856704	0.01	0.20	7.00	7	58
196.00	197.50	E856705	0.01	0.20	8.00	6	37
197.50	199.00	E856706	0.02	0.20	8.00	10	41
199.00	200.50	E856707	0.02	0.20	7.00	10	37
200.50	202.00	E856708	0.05	0.20	11.00	12	45
200.50	202.00	E856709					
200.50	202.00	E856710					
202.00	203.50	E856711	0.01	0.20	28.00	21	86
203.50	205.00	E856712	0.02	0.20	7.00	5	60
205.00	206.50	E856713	0.02	0.40	12.00	10	65
206.50	208.00	E856714	0.02	0.20	25.00	7	150
208.00	209.50	E856715	0.01	0.20	34.00	5	57
209.50	211.00	E856716	0.01	0.20	28.00	3	40
211.00	213.50	E856717	0.01	0.20	3.00	2	63
213.50	215.00	E856718	0.01	0.20	2.00	11	110
215.00	216.50	E856719	0.01	0.20	2.00	7	66
216.50	218.00	E856720	0.01	0.30	8.00	23	87
218.00	219.50	E856721	0.07	0.30	10.00	7	105
218.00	219.50	E856722					
219.50	221.00	E856723	0.01	0.20	10.00	10	101
221.00	222.50	E856724	0.01	0.20	13.00	9	74
222.50	224.00	E856725	0.22	11.00	743.00	62	111

Project: Keystone **Hole Number:** KEY10-09

From	To	Rocktype & Description
223.05	224.64	PHYL
		Highly magnetic fault gouge. Trace pyrite is visible though no pyrrhotite is visible.
		< @ 223.05 100% fault gouge Ft 1.59m >
		« py 2.00-3.00%»
		« not visible but section is highly magnetic po 5.00%»
		EOH at 224.64m
224.64	224.64	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
224.00	224.64	E856726	0.20	100.00	575.00	72	110

EQUITY

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 3937.0
Hole KEY10-10	**Azimuth (º):** 325
Location: 7077639 m North, 490028 m East	**Dip (º):** -65.0
Logged by: D. Swanton/MM	**Length (m):** 182.88
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: BTW	**Objective** To investigate possible mineralization associated with local soil anomalies of up to 246ppm, thought to be controlled by a NE trending structure.
Date Started: 2010/07/10 **Date Completed:** 2010/07/16	
Dip Tests By:	

Summary Log:

3.05-11.90: Siderite altered quartzite
11.90-14.20: Carbonate healed quartzite breccia
14:20-17.70: Carbonate and siderite altered quartzite
17.70-18.50: Carbonate healed quartzite breccia
18.50-30.90: Fractured, siderite altered quartzite>metagreywacke
30.90-31.70: Carbonate healed breccia
31.70-37.20: Fault zone within altered metagreywacke
37.20-42.10: Highly faulted metagreywacke with minor phyllite cut by thick quartz-siderite veins.
42.10-49.10: Strongly carbonate altered metagreywacke, minor carbonate veinlets
49.1-78.98: Silicified metagreywacke (85%), chloritic phyllite (15%) with fabric // quartz veins.
78.98-99.99: Interlayered, chlorite altered graphitic phyllite (85%) and intensely silicified metagreywacke (15%).
99.99-122.34: Same as above however with trace po (0.2%)
122.34-123.72: Silicified dirty quartzite with trace py (0.1%)
124.34-139.00: Silicified and heavily carbonate altered, interlayered graphitic phyllite (80%) and metagreywacke (20%) with ~1% po and 2% py.
139-151.51: Silicified graphitic phyllite with foliation parallel qtz veins, 1% py and 0.5% po.
151.51-179.55: Silicified and carbonate altered, interlayered phyllite (70%) and metagreywacke (30%) containing trace pyrite (1%) and po (1-4%).
179.55-182.88: Silicified and carbonate altered metagreywacke with trace py and no po.

Downhole surveys:

Depth	Dip	Azimuth
0.00	-65.00	325.00
182.88	-65.00	325.00

Project: Keystone **Hole Number:** KEY10-10

From	To	Rocktype & Description
0.00	3.05	CAS
		Casing
3.05	11.90	QRZT
		-Intensely siderite-altered quartzite
		-heavaily fractured
		< @ 7.00 S1 50.00° >
		« siderite alteration sid 3.00*»
		« ser 1.00*»
11.90	14.20	Brx
		-carbonate healed quartzite beccia
		« crb 4.00*»
14.20	17.70	QRZT
		-quartzite alterred with either calcite or siderite+/- chlorite and sericite
		-moderate degree of fracturing
		< @ 17.50 S1 60.00° >
		« crb 3.00*»
		« chl 1.0« ser 1.00*»
17.70	18.50	Brx
		-Carbonate healed quartzite breccia
		« crb 4.00*»
18.50	30.90	QRZT
		-Quartzite grading to metagreywacke, intensly altered by calcite and siderite
		-siderite-rich zones are faulted and highly fractured, almost to the point of
		being fault gouge
		-Some zones show silicic, sericitic and chloritic alteration
		< @ 22.50 cross-cutting quartz siderite V 70.00° 30.00 >
		< @ 26.50 S1 50.00° >
		< @ 28.10 V 80.00° 5.00 >
		« crb 3.0»
		« sil 2.00*»
		« chl 1.00*»
		« ser 1.00*»
30.90	31.70	Brx



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
3.00	5.00	E858193	0.01	0.20	35.00	10	24
5.00	6.50	E858194	0.01	0.20	36.00	12	27
6.50	8.00	E858195	0.01	0.20	49.00	14	27
8.00	9.50	E858196	0.01	0.40	192.00	55	92
9.50	11.00	E858197	0.01	0.20	411.00	35	66
11.00	12.50	E858198	0.01	0.20	36.00	81	64
12.50	14.00	E858199	0.01	0.20	71.00	17	79
14.00	15.50	E858200	0.02	0.20	135.00	19	36
15.50	17.00	E858201	0.01	0.20	70.00	13	38
15.50	17.00	E858202					
17.00	18.50	E858203	0.01	0.20	10.00	15	23
18.50	20.00	E858204	0.01	0.20	41.00	54	52
20.00	21.50	E858205	0.01	0.20	21.00	23	43
21.50	23.00	E858206	0.01	0.20	32.00	39	57
23.00	24.50	E858207	0.01	0.20	56.00	44	75
24.50	26.00	E858208	0.01	0.20	241.00	74	86
24.50	26.00	E858209					
24.50	26.00	E858210					
26.00	27.50	E858211	0.01	0.20	262.00	38	37
27.50	29.00	E858212	0.02	0.30	148.00	23	30
29.00	30.50	E858213	0.03	0.20	280.00	16	28

2010/10/18 **Equity Exploration Ltd.** * depth component not to scale

* Samples with duplicate ranges are QA/QC samples and have no associated assays

Project: Keystone **Hole Number:** KEY10-10

From	To	Rocktype & Description
		-Carbonate healed breccia
		« crb 4.00*»
31.70	37.20	MGWK
		Extremely faulted siderite altered mgwk
		unit is almost totally fault gouge
		« crb 3.00*»
		« ser 2.00*»
37.20	42.10	MGWK
		-Highly faulted metagreywacke with minor phyllite, cut by thick quartz-siderite
		veins
		-phyllite layers have up to 2% pyrite
		-Many of the faults appear to run paralel to S1
		< @ 39.10 cross-cutting quartz-siderite V 35.00° 100.00>
		< @ 39.40 S1 65.00° >
		« py 0.50%»
		« ser 1.00*»
		« sil 1.00*»
		« crb 1.00*»
42.10	49.10	MGWK
		-Metagreywacke with a few faults and cross-cutting carbonate veins
		-upper 1 m is silicicly alterred, rest of unit is strongly carbonate-altered
		« 42.10- 43.00 sil 2.00*»
		« 43.00- 49.10 crb 3.00*»
		« 42.10- 49.10 py 0.10%»
		< @ 43.30 qtz-crb-sid V 55.00° 70.00 >
		< @ 45.70 S1 60.00° >
		< @ 46.40 Ft 85.00° >
49.10	69.20	MGWK
		-Dominantly silicic mgwk with 15% chloritic phyllite and fabric parallel quartz
		veins
		-There are a few cross-cutting veinlets, but not many
		-silicic layers contain small blue quartz eyes
		« py 0.10%»
		« chl 1.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
30.50	32.00	E858214	0.04	0.20	232.00	12	27
32.00	33.50	E858215	0.01	0.20	271.00	21	59
33.50	35.00	E858216	0.03	0.60	380.00	15	33
35.00	36.50	E858217	0.44	0.20	2530.00	8	34
36.50	38.00	E858218	0.02	0.20	1025.00	14	17
38.00	39.50	E858219	0.30	0.30	5720.00	22	33
39.50	41.00	E858220	0.12	0.20	1050.00	19	43
41.00	42.50	E858221	0.10	0.30	917.00	22	21
41.00	42.50	E858222					
42.50	44.00	E858223	0.12	0.20	1445.00	17	26
44.00	45.50	E858224	0.02	0.20	110.00	12	17
45.50	47.00	E858225	0.16	0.30	506.00	9	13
47.00	48.50	E858226	0.01	0.20	20.00	8	7
48.50	50.00	E858227	0.01	0.20	34.00	18	25
50.00	51.50	E858228	0.01	0.20	334.00	13	46
50.00	51.50	E858229					
50.00	51.50	E858230					
51.50	53.00	E858231	0.01	0.40	41.00	35	150
53.00	54.50	E858232	0.01	0.20	19.00	22	60
54.50	56.00	E858233	0.07	0.20	220.00	17	33
56.00	57.50	E858234	0.01	0.20	15.00	17	20

Project: Keystone **Hole Number:** KEY10-10

From	To	Rocktype & Description
		« sil 2.00*»
		< @ 55.30 S1 55.00° >
		< @ 53.70 S1 40.00° >
		< @ 54.20 qtz-chlorite V 70.00° 130.00 >
		< @ 58.20 cross-cutting qtz-carb V 50.00° 5.00 >
		< @ 60.90 fabric // qtz V 60.00° 15.00 >
		< @ 67.30 S1 55.00>
69.20	78.98	MGWK
		Highly carbonate, chlorite and silica altered with moderately abundant detrital quartz crystals. Carbonate alteration occurs as thick bands. Chlorite and silica alteration is pervasive. No mineralization.
		« 76.56- 78.98 thick, fabric // band of carbonate alteration cal 45.00cm»
		« ser 1.00*»
		« pervasive chl 2.00*»
		« pervasive sil 1.00*»
78.98	99.99	PHYL
		Interlayered chlorite altered and graphitic phyllite with minor interlayers of metagreywacke (15%). Abundant pervasive chlorite alteration with zones of intense silica alteration and lesser sericite alteration. Significant, thick zones of carbonate veins (?) or thorough replacment. No mineralization.
		« pervasive chl 3.00*»
		« concentrated in zones with quartz veining sil 2.0
		« largely associated with quartz veins ser 1.00*»
		« 91.61- 92.29 thick veining(?) or pervasive cal 4.00*»
		« 78.98- 159.99 as thick bands of alteration cal 3.00*»
		< @ 97.00 S1 35.00° >
		< @ 95.76 Quartz veining, fabric // V 35.00° 9.00cm >
		« 80.24- 80.44 fine grain magnetite focused in graphitic layer mng
		0.50%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
57.50	59.00	E858235	0.01	0.20	43.00	16	12
59.00	60.50	E858236	0.02	0.20	76.00	16	19
60.50	62.00	E858237	0.14	0.20	421.00	18	30
62.00	63.50	E858238	0.01	2.10	33.00	15	38
63.50	65.00	E858239	0.01	0.20	15.00	13	15
65.00	66.50	E858240	0.06	0.20	597.00	16	13
66.50	68.00	E858241	0.30	0.40	2550.00	17	57
66.50	68.00	E858242					
68.00	69.50	E858243	0.14	0.30	2670.00	15	30
69.50	74.00	E858244	0.01	0.30	292.00	29	29
74.00	75.50	E858245	0.01	0.20	19.00	13	13
75.50	77.00	E858246	0.01	0.40	26.00	25	22
77.00	78.50	E858247	0.01	0.20	7.00	14	25
78.50	80.00	E858248	0.01	0.20	30.00	4	81
78.50	80.00	E858249					
78.50	80.00	E858250					
80.00	81.50	E858251	0.01	0.20	3.00	4	67
81.50	83.00	E858252	0.01	0.20	2.00	5	70
83.00	84.50	E858253	0.01	0.20	6.00	5	63
84.50	86.00	E858254	0.01	0.40	35.00	6	55
86.00	87.50	E858255	0.05	0.20	3.00	7	61
87.50	89.00	E858256	0.01	0.20	2.00	7	66
89.00	90.50	E858257	0.01	0.20	2.00	12	63
90.50	92.00	E858258	0.01	0.30	2.00	11	42
92.00	93.50	E858259	0.01	0.40	5.00	14	19
93.50	95.00	E858260	0.01	0.30	4.00	12	38
95.00	96.50	E858261	0.01	0.20	4.00	20	58
95.00	96.50	E858262					
96.50	98.00	E858263	0.01	0.20	4.00	13	50
98.00	99.50	E858264	0.01	0.20	12.00	9	57
99.50	101.00	E858265	0.01	0.20	2.00	20	38

Project: Keystone **Hole Number:** KEY10-10

From	To	Rocktype & Description
99.99	122.34	MGWK
		Interlayered metagreywacke (60%) and laminated phyllite (40%) with abundant foliation // and cross cutting cm scale quartz veins with pervasive silica and chlorite alteration. Trace pyrrhotite occurs as fine blebs along foliation in the more graphitic layers as well as along the salvages of cross-cutting, late stage quartz veins, often with chlorite alteration. Carbonate alteration occurs as cm scale veins and more pervasive in zones.
		< @ 110.00 S1 25.00° >
		« pervasive, focused within the graphitic phyllite chl 2.0»
		« pervasive near zones with abundant quartz veining sil 2.00*»
		« abundant, occurs as thick bands cal 2.00*»
		« po 0.20%»
122.34	123.72	QRZT
		Silicified dirty quartzite with trace disseminated pyrite.
		« pervasive sil 3.00*»
		« fine, disseminated py 0.10%»
124.34	139.00	PHYL
		Interlayered black (graphitic?) phyllite (80%) and metagreywacke(20%) with abundant, often pervasive carbonate alteration as well as pervasive silica alteration. Chlorite alteration occurs preferentially wthin metagreywacke layers. Pyrite and pyrrhotite both occur as foliation parallel blebs and stringers and also as blebs within foliation cutting quartz veins.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
101.00	102.50	E858266	0.01	0.20	2.00	24	32
102.50	104.00	E858267	0.01	0.20	5.00	40	40
104.00	105.50	E858268	0.01	0.20	2.00	18	47
104.00	105.50	E858269					
104.00	105.50	E858270					
105.50	107.00	E858271	0.01	0.20	2.00	53	53
107.00	108.50	E858272	0.01	0.30	3.00	23	53
108.50	110.00	E858273	0.01	0.30	3.00	23	39
110.00	111.50	E858274	0.01	0.20	2.00	28	52
111.50	113.00	E858275	0.01	0.30	7.00	15	35
113.00	114.50	E858276	0.01	0.30	3.00	19	38
114.50	116.00	E858277	0.01	0.40	2.00	15	62
116.00	117.50	E858278	0.01	0.20	4.00	22	73
117.50	119.00	E858279	0.01	0.20	2.00	30	65
119.00	120.50	E858280	0.01	0.20	2.00	20	73
120.50	122.00	E858281	0.01	0.20	2.00	21	46
120.50	122.00	E858282					
122.00	123.50	E858283	0.01	0.20	2.00	14	18
123.50	125.00	E858284	0.01	0.20	2.00	14	28
125.00	126.50	E858285	0.01	0.20	2.00	32	80
126.50	128.00	E858286	0.01	0.20	2.00	24	33
128.00	129.50	E858287	0.01	0.30	2.00	18	51
129.50	131.00	E858288	0.01	0.30	2.00	16	43
129.50	131.00	E858289					
129.50	131.00	E858290					

Project: Keystone **Hole Number:** KEY10-10

From	To	Rocktype & Description
		< @ 135.00 S1 30.00° >
		< @ 13.94 V 31.00cm >
		« pervasive sil 2.00*»
		« Pervasive in zones and as bands cal 3.00*»
		« within metagreywacke interlayers chl 1.00*»
		« py 2.00%»
		« po 1.00%»
139.00	141.53	PHYL
		Pervasively silicified graphitic phylite with abundant bands of carbonate alteration. Similar to above unit without metagreywacke interlayers and with less pyrite. Pyrrhotite is disseminated along foliation.
		< @ 139.42 crenulations S2 20.00º >
		< @ 140.00 S1 30.00° >
		« sil 3.00*»
		« as bands cal 3.00*»
		« po 1.00%»
		« py 0.50%»
141.53	151.51	PHYL
		Grey to black heavily silicified and carbonate altered phyllite with trace pyrite and pyrrhotite. Pinched out 1-4cm wide quartz veins are moderaltely abundant.
		< @ 151.00 S1 30.00° >
		« pervasive sil 2.00*»
		« pervasive in zones but also as veins cal 3.00*»
		« py 1.00%»
		« po 0.50%»
		« 148.95- 149.03 abundant in fine xcutting quartz veinlets po 5.00%»
151.51	154.85	MGWK
		Interlayered, laminated metagreywacke and graphitic phyllite with pervasive silica alteration but much lesser carbonate alteration than units above and



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
131.00	132.50	E858291	0.01	0.20	2.00	11	64
132.50	134.00	E858292	0.01	0.30	2.00	16	29
134.00	135.50	E858293	0.01	0.30	2.00	17	33
135.50	137.00	E858294	0.01	0.30	2.00	14	44
137.00	138.50	E858295	0.01	0.30	2.00	13	41
138.50	140.00	E858296	0.01	0.40	2.00	14	37
140.00	141.50	E858297	0.01	0.40	2.00	12	48
141.50	143.00	E858298	0.01	0.40	2.00	15	39
143.00	144.50	E858299	0.01	0.40	3.00	14	22
144.50	146.00	E858300	0.01	0.40	4.00	11	46
146.00	147.50	E858301	0.01	0.30	8.00	11	30
146.00	147.50	E858302					
147.50	148.00	E858303	0.01	0.40	7.00	13	23
148.00	149.50	E858304	0.01	0.30	3.00	17	116
149.50	151.00	E858305	0.01	0.20	3.00	13	61
151.00	152.50	E858306	0.01	0.20	2.00	15	55
152.50	154.00	E858307	0.01	0.20	4.00	19	76
154.00	155.50	E858308	0.01	0.40	2.00	17	47
154.00	155.50	E858309					
154.00	155.50	E858310					

Project: Keystone **Hole Number:** KEY10-10

From	To	Rocktype & Description
		below.
		< @ 152.09 quartz vein that cuts foliation V 40.00º 10.00cm >
		< @ 152.00 lam 35.00º >
		« pervasive sil 3.00*»
		« foccused near lower contact cal 1.00*»
		« alteration of metagreywacke chl 2.00*»
		« along foliation py 0.50%»
		« 154.43- 154.85 along foliation po 1.00%»
154.85	179.55	PHYL
		Highly silicified and carbonate altered, interlayered phyllite (70%) and metagreywacke (30%). Pyrrhotite is unusually abundant, though still in trace quantities. Carbonate alteration occurs primarily as bands and as a component of some cross cutting quartz veins. Silica alteration is pervasive and there are moderately abundant foliation parallel and foliation-cutting quartz veins. The trace pyrite and pyrrhotite occurs throughout with several higher grade zones (172.6-175) with pyrrhotite occuring along foliation as well as along the salvages of cross-cutting quartz veins with chlorite alteration.
		< @ 167.00 S1 25.00° >
		< @ 167.44 20% fault gouge and abundant fractures Ft 30.00º 73.00cm >
		< @ 171.66 cross cutting quartz V 8.00cm >
		< @ 176.00 Cross cutting quartz V 14.00cm >
		< @ 175.38 quartz and chlorite V 50.00º 10.00cm >
		< @ 174.74 cross cutting quartz and chlorite with abundant pyrrhotite V 12.00cm >
		« sil 3.00*»
		« cal 3.00*»
		« largely associated with quartz veins chl 1.00*»
		« py 1.00%»
		« 154.85- 172.60 po 2.00%»
		« 172.60- 175.00 In cross cutting quartz veins po 4.00%»
		« 175.00- 179.55 po 1.00%»
179.55	182.88	MGWK
		Highly silicified and thoroughly carbonate altered metagreywacke. Chlorite alteration occurs predominately near quartz veins which are all foliation



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
155.50	157.00	E858311	0.01	0.80	37.00	22	124
157.00	158.50	E858312	0.01	0.50	2.00	12	30
158.50	159.00	E858313	0.01	0.60	2.00	12	22
159.00	160.50	E858314	0.01	0.50	2.00	14	35
160.50	162.00	E858315	0.01	0.50	2.00	13	35
162.00	163.50	E858316	0.01	0.50	3.00	14	34
163.50	165.00	E858317	0.01	0.50	2.00	14	47
165.00	166.50	E858318	0.01	0.20	2.00	24	62
166.50	168.00	E858319	0.01	0.30	2.00	18	49
168.00	169.50	E858320	0.01	0.30	2.00	15	44
169.50	171.00	E858321	0.01	0.30	2.00	21	56
169.50	171.00	E858322					
171.00	172.50	E858323	0.01	0.20	2.00	18	74
172.50	174.00	E858324	0.01	0.30	2.00	20	76
174.00	175.50	E858325	0.01	0.20	2.00	9	102
175.50	177.00	E858326	0.01	0.20	2.00	21	59
177.00	178.50	E858327	0.01	0.40	6.00	38	51
178.50	180.00	E858328	0.01	0.20	3.00	11	47
178.50	180.00	E858329					
178.50	180.00	E858330					
180.00	181.50	E858331	0.01	0.30	4.00	20	23
181.50	182.88	E858332	0.01	0.40	5.00	11	20

Project: Keystone **Hole Number:** KEY10-10

From	To	Rocktype & Description
		parallel. This unit lacks the pyrrhotite that occurs in the unit above.
		< @ 181.00 S1 30.00° >
		« pervasive sil 3.00*»
		« occurs as specks and thick bands, well developed cal 2.00*»
		« chl 2.00*»
		« py 0.50%»
		EOH@182.88
182.88	182.88	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 5289.0
Hole KEY10-11	**Azimuth (º):** 325
Location: 7079393 m North, 491409 m East	**Dip (º):** -60.0
Logged by: M. McKeown	**Length (m):** 245.97
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: NTW	**Objective** To investigate the source of both a local soil anomaly of up to 2589ppm Au and a mineralized rock sample (855508) found nearby in float with 2.19ppm Au.
Date Started: 2010/07/16 **Date Completed:** 2010/07/20	
Dip Tests By:	

Summary Log:

0-6: Casing
6-15: Micaceous phyllite with carbonate alteration and Fe-oxide staining.
15-23: Faulted and highly carbonate altered metagreywacke.
23-24: Highly silicified quartzite.
24-57: Pervasively silicified metagreywacke (40%) and laminated phyllite (60%) with foliation parallel quartz-siderite veining with limited zones of pyrite (1%).
57-64: Highly silicified metagreywacke with small, detrital, purple quartz veins.
64-73: Silicified, interlayered metagreywacke and graphitic phyllite with trace pyrite (2%).
73-74: Silicified graphitic phyllite with trace pyrite (2%) and pyrrhotite (0.5%).
74-75: Carbonate healed breccia.
75-87: Fractured, silicified, laminated, interlayered phyllite and metagreywacke with sparse quartz-siderite veins.
87-90: Silicified, uniform, metagreywacke.
90-91: Brecciated limestone.
91-100: Foliated, silicified siltstone with rare graphitic phyllite interlayers with trace arsenopyrite (0.1%) and pyrite (1%).
100-116: Interlayered micaceous phyllite and graphitic phyllite.
116-118: Same as above with abundant bands of carbonate banding.
118-123: Silicified, highly fractured laminated graphitic phyllite with abundant fabric parallel quartz veins and trace arsenopyrite (0.1%) and pyrrhotite (0.5%).
123-166: Silicified, interlayered, metagreywacke (65%) and micaceous phyllite (35%) with trace disseminated pyrite (0.5%), arsenopyrite (0.1%) and pyrrhotite (0.2%).
166-169: Silicified metagreywacke with sparse, purple, detrital quartz crystals.
169-174: Silicified, interlayered metagreywacke (70%) and graphitic phyllite (30%) with discrete bands of intense carbonate alteration and trace pyrite (0.5%).
174-195: Highly fractured graphitic phyllite
195-197: Highly silicified metagreywacke with trace pyrite (1%) along foliation
197-231: Large fault zone within the graphitic phyllite, 40% fault gouge.
231-246: Out of the fault zone into silicified metagreywacke with trace pyrite(1%) and pyrrhotite (0.1%).
EOH

Downhole surveys:

Depth	Dip	Azimuth
0.00	-60.00	325.00
245.97	-60.00	325.00

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
0.00	6.07	CAS
6.07	8.00	PHYL
		Heavily iron-carbonate and chlorite altered micaceous phyllite with abundant fractures.
		< @ 7.00 S1 30.00° >
		< @ 6.07 randomly oriented fractures Fr 93.00cm >
		< @ 7.17 80% fault gouge Ft 27.00mm >
		« cal 2.00*»
		« with carbonate alteration along foliation fer 2.00%»
		« pervasive chl 2.00*»
		< @ 7.85 foliation cutting quartz V 10.00cm >
8.00	15.00	PHYL
		Highly foliated chlorite altered and silicified micaceous phyllite without the carbonate alteration above. Well formed pyrite is weathering out of the unit. This section is also highly fractured and faulted with minimal rock fragments greater than 10cm.
		< @ 8.00 S1 60.00° >
		< @ 8.00 30% gouge, poor recovery, highly fractured Ft 17.00m >
		« pervasive chl 3.00*»
		« pervasive sil 2.00*»
		« mus 2.00°»
15.00	23.75	MGWK
		Faulted and highly carbonate altered metagreywacke that is granular in zones.
		< @ 19.30 S1 30.00° >
		< @ 17.00 Ft 2.00m >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
6.00	7.50	E856727	0.01	0.20	4.00	14	33
7.50	9.00	E856728	0.01	0.20	27.00	32	39
7.50	9.00	E856729					
7.50	9.00	E856730					
9.00	12.00	E856731	0.01	0.20	37.00	34	48
12.00	15.00	E856732	0.01	0.20	23.00	23	45
15.00	18.00	E856733	0.01	0.20	48.00	19	32
18.00	20.00	E856734	0.01	0.40	31.00	22	33
20.00	22.00	E856735	0.01	0.20	30.00	23	65
22.00	23.50	E856736	0.03	0.20	135.00	19	75

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
		< @ 21.00 75% gouge Ft 2.48m >
		« pervasive cal 3.00*»
		« pervasive sil 2.00*»
23.75	24.24	QRZT
		Extremely silicified, weakly foliated quartzite.
		« pervasive sil 4.00*»
		« mus 1.00°»
		< @ 24.00 S1 50.00° >
24.24	27.06	MGWK
		Metagreywacke (80%) interlayerd with graphitic phyllite (20%). Quartz veins (cm scale) within the metagreywacke contain fragments of the graphitic phyllite. There is minor quartz-siderite veining within the graphitic interlayers.
		« mus 1.00»
		« sparse alteration cal 1.00*»
		« pervasive and as cm scale veins sil 2.00*»
		« associated with quartz veins fer 1.00%»
27.06	31.17	PHYL
		Graphitic phyllite with abundant mm-cm scale quartz veining and lesser cm scale quartz-siderite veins.
		< @ 29.00 S1 20.00° >
		< @ 28.84 quartz and siderite, abundant Fe-oxide staining V 25.00º 7.00cm >
		« grp 3.00%»
		« within cm scale veins sil 2.00*»
		« associated with quartz and siderite veins fer 2.00%»
		« as cm scale veins sid 2.00*»
31.17	47.95	PHYL
		Laminated, Interlayered and silicified phyllite (65%) and metagreywacke (35%) with moderately abundant cm scale foliation parallel quartz veins and lesser cross cutting quartz veins. Minor siderite component with some quartz veins. Iron oxide staining is associated with veining and is focused along foliation.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
23.50	25.00	E856737	0.01	0.20	4.00	6	5
25.00	26.50	E856738	0.01	0.20	9.00	29	58
26.50	28.00	E856739	0.01	0.20	8.00	12	78
28.00	29.50	E856740	0.01	0.20	8.00	17	79
29.50	31.00	E856741	0.01	0.40	15.00	12	58
29.50	31.00	E856742					
31.00	32.50	E856743	0.01	0.40	4.00	10	66
32.50	34.00	E856744	0.01	0.20	2.00	9	75
34.00	35.50	E856745	0.01	0.30	2.00	11	83
35.50	37.00	E856746	0.01	0.20	2.00	25	71
37.00	38.50	E856747	0.01	0.20	2.00	17	80
38.50	40.00	E856748	0.01	0.20	2.00	18	75
38.50	40.00	E856749					
38.50	40.00	E856750					

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
		< @ 37.00 S1 35.00° >
		« pervasive sil 3.00*»
		« sid 1.00*»
		< @ 42.26 cross cutting quartz with sericite alteration V 90.00° 24.00cm >
47.95	52.60	MGWK
		Similar to above unit with a greater proportion of granular metagreywacke. Laminated, interlayered and silicified metagreywacke (75%) and graphitic phyllite (25%). There is minor cm scale quartz veining.
		< @ 48.00 S1 10.00° >
		< @ 49.00 lam 10.00° >
		« pervasive sil 3.00*»
		« within the metagreywacke chl 1.00*»
52.60	54.20	MGWK
		Highly silicified metagreywacke with weak foliation, rare cm scale foliation parallel quartz veins and rare mm scale cross cutting veinlets of quartz and sericite.
		< @ 53.00 S1 15.00° >
		« pervasive sil 3.00*»
		« gives a speckled appearence ser 1.00*»
54.20	56.65	PHYL
		Similar to above units. Laminated, interlayered, silicified graphitic phyllite (55%) and metagreywacke(45%). One limited zone with a vuggy, quartz-siderite cross-cutting vein with blebby pyrite.
		< @ 55.70 cross-cutting, quartz-siderite with trace pyrite V 4.00cm >
		< @ 54.20 Highly fractured, randomly oriented fragments Fr 12.00cm >
		« pervasive sil 2.00*»
		« 55.70- 55.75 blebby, within vein py 2.00%»
56.65	63.85	MGWK



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
40.00	41.50	E856751	0.01	0.20	2.00	22	80
41.50	43.00	E856752	0.01	0.20	2.00	17	68
43.00	44.50	E856753	0.01	0.20	2.00	26	72
44.50	46.00	E856754	0.01	0.30	2.00	21	77
46.00	47.50	E856755	0.01	0.20	2.00	18	73
47.50	49.00	E856756	0.01	0.30	3.00	15	65
49.00	50.50	E856757	0.01	0.20	15.00	16	52
50.50	52.00	E856758	0.01	0.30	63.00	12	40
52.00	53.50	E856759	0.01	0.40	13.00	10	33
53.50	55.00	E856760	0.01	0.20	11.00	18	61
55.00	56.50	E856761	0.01	0.20	7.00	33	59
56.50	58.00	E856762	0.01	0.20	28.00	13	25
58.00	59.50	E856763	0.01	0.20	4.00	9	23

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
		Highly silicified, very weakly foliated metagreywacke that includes zones with small, detrital, slightly purple, quartz eyes. Rare cm scale, foliation parallel quartz veins. « pervasive sil 3.00*» « as specks within the matrix ser 1.00*»
63.85	65.30	PHYL
		Highly fractured, silicified, interlayered unit dominated by graphitic phyllite (90%) with metagreywacke (10%). < @ 63.85 Abundant, randomly oriented fractures Fr 95.00cm > « pervasive sil 2.00*» « minor staining along fracture surfaces fer 1.00*»
65.30	73.07	MGWK
		Silicified metagreywacke with interlayers of graphitic phyllite in the lower portion of this section. Sporadic, foliation parallel, rusty quartz veins with trace pyrite. < @ 72.00 S1 30.00° > « pervasive sil 3.00*» < @ 69.85 foliation parallel quartz with trace py and abundant Fe-oxide staining V 30.00° 10.00cm > « 69.85- 69.95 associated with quartz vein fer 2.00*» « blebs within quartz vein py 2.00%»
73.07	74.37	PHYL
		Laminated, silicified graphitic phyllite with a large cross cutting quartz-siderite, chlorite, iron oxide stained vein with trace pyrite and pyrrhotite. « pervasive sil 2.00*» < @ 73.12 Quartz, chlorite, iron oxide stained with trace py and po V 47.00cm > « 73.07- 73.70 blebs within vein py 2.00%» « trace blebs within vein po 0.50%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
59.50	61.00	E856764	0.01	0.20	5.00	10	12
61.00	62.50	E856765	0.01	0.20	18.00	18	30
62.50	64.00	E856766	0.02	0.20	322.00	18	44
64.00	65.50	E856767	0.02	0.30	863.00	18	45
65.50	67.00	E856768	0.02	0.40	712.00	18	79
65.50	67.00	E856769					
65.50	67.00	E856770					
67.00	68.50	E856771	0.01	0.20	10.00	15	58
68.50	70.00	E856772	0.01	0.20	10.00	13	52
70.00	71.50	E856773	0.01	0.20	5.00	28	46
71.50	73.00	E856774	0.01	0.20	2.00	12	51

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
74.37	75.05	Brx
		Metagreywacke unit brecciated with silica>carbonate rich fluids. Clasts are angular and 1-3cm.
		« pervasive sil 3.00*»
		« binding brecia cal 2.00*»
75.05	82.84	MGWK
		Fractured and silicified metagreywacke with minor phyllite interlayers.
		< @ 80.40 15% gouge with abundant, randomly oriented fractures Ft 35.00cm >
		< @ 79.61 30% gouge Ft 20.00cm >
		« pervasive sil 3.00*»
82.84	86.45	PHYL
		Highly fractured, silicified,laminated, interlayered phyllite and metagreywacke with abundant chlorite alteration. Abundant cm scale, foliation parallel quartz-siderite veins. Iron oxide staining is moderately abundant along fracture surfaces.
		« pervasive sil 3.00*»
		« chl 2.00*»
		« along fractures and with quartz-siderite veins fer 2.00*»
		< @ 82.84 Fr 3.61m >
86.45	90.86	MGWK
		Green-grey, fractured, silicified, fairly uniform metagreywacke.
		< @ 87.15 Highly fractured with 15% fault gouge Ft 1.36m >
		« pervasive sil 3.00*»
90.86	91.41	Brx
		Highly fractured, brecciated limestone with carbonate matrix and abundant iron-oxide staining along fracture surfaces.
		« fer 2.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
73.00	74.50	E856775	0.01	0.20	2.00	19	59
74.50	76.00	E856776	0.01	0.40	7.00	37	61
76.00	77.50	E856777	0.01	0.40	20.00	20	61
77.50	79.00	E856778	0.01	0.40	13.00	17	45
79.00	80.50	E856779	0.01	0.30	12.00	14	44
80.50	82.00	E856780	0.01	0.20	4.00	12	150
82.00	83.50	E856781	0.01	0.20	4.00	12	43
83.50	85.00	E856782	0.01	0.20	20.00	25	48
85.00	86.50	E856783	0.01	0.20	23.00	12	76
86.50	88.00	E856784	0.01	0.20	86.00	18	50
88.00	89.50	E856785	0.01	0.20	39.00	10	23
89.50	91.00	E856786	0.06	0.20	500.00	13	37
91.00	92.50	E856787	0.17	0.90	2470.00	31	98

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
		« interstitial material cal 3.00*»
91.41	100.03	MGWK
		Silica altered siltstone with rare graphitic phyllite interlayers and abundant cm scale quartz veins parallel to foliation. Trace arsenopyrite occurs along foliation along with trace pyrite.
		< @ 95.00 S1 50.00° >
		« pervasive sil 3.00*»
		« of the more phylitic layers chl 1.00*»
		« ser 1.00*»
		« apy 0.10%»
		« py 0.10%»
100.03	100.48	MGWK
		Same unit as above with very abundant carbonate alteration.
		« pervasive cal 3.00*»
100.48	116.08	PHYL
		Interlayered micaceous phyllite and graphitic phyllite with moderately abundant cm scale, foliation parallel quartz veins.
		< @ 112.00 S1 35.00° >
		< @ 109.10 foliation parallel quartz vein V 15.00cm >
		« pervasive chl 2.00*»
		« mus 2.00»
116.08	118.45	PHYL
		Same phyllite unit as above with abundant, thick bands of carbonate alteration.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
92.50	94.00	E856788	0.18	0.40	1350.00	19	56
92.50	94.00	E856789					
92.50	94.00	E856790					
94.00	95.50	E856791	0.02	0.20	139.00	15	40
95.50	97.00	E856792	0.01	0.20	13.00	14	32
97.00	98.50	E856793	0.01	0.20	3.00	14	30
98.50	100.00	E856794	0.01	0.20	16.00	16	60
100.00	101.50	E856795	0.01	0.20	9.00	21	38
101.50	103.00	E856796	0.01	0.20	38.00	31	79
103.00	104.50	E856797	0.01	0.20	2.00	19	68
104.50	106.00	E856798	0.01	0.30	8.00	24	65
106.00	107.50	E856799	0.01	0.20	6.00	9	69
107.50	109.00	E856800	0.01	0.20	3.00	10	103
109.00	110.50	E856801	0.01	0.20	6.00	14	81
109.00	110.50	E856802					
110.50	112.00	E856803	0.01	0.20	10.00	28	84
112.00	113.50	E856804	0.01	0.20	28.00	26	70
113.50	115.00	E856805	0.01	0.20	18.00	19	66
115.00	116.50	E856806	0.01	0.20	15.00	17	73
116.50	118.00	E856807	0.01	0.20	14.00	15	45
118.00	119.50	E856808	0.01	0.20	19.00	9	66
118.00	119.50	E856809					
118.00	119.50	E856810					

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
		very restricted to this zone.
		« chl 2.00*»
		« mus 2.00»
		« cal 2.00*»
118.45	122.77	PHYL
		Silicified, highly fractured, laminated graphitic phyllite with foliation parallel quartz veins some with sericite. Trace, disseminated arsenopyrite and trace blebs of pyrite occurs throughout.
		< @ 122.00 S1 20.00° >
		< @ 120.23 foliation parallel quartz with trace pyrite V 24.00cm >
		< @ 120.55 Highly fractured Fr 30.00cm >
		« pervasive sil 3.00*»
		« with quartz veins ser 1.00*»
		« with graphitic layers chl 1.00*»
		« apy 0.10%»
		« py 0.50%»
122.77	154.26	MGWK
		Interlayered and silicified chlorite altered metagreywacke (80%) and micaceous phyllite (20%). Moderately abundant foliation parallel quartz veins and cross cutting quartz veins.
		< @ 142.00 S1 40.00° >
		< @ 149.07 Cross cutting quartz, chlorite, sericite V 58.00cm >
		« pervasive chl 2.00*»
		« pervasive sil 2.00*»
		« within micaceous phyllite mus 2.00»
		« trace disseminated py 0.50%
		« sporatic, trace disseminated apy 0.10%»
		« sporatic as small, foliation parallel blebs po 0.20%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
119.50	121.00	E856811	0.01	0.30	23.00	40	65
121.00	122.50	E856812	0.01	0.20	20.00	17	75
122.50	124.00	E856813	0.01	0.20	11.00	20	60
124.00	125.50	E856814	0.01	0.20	8.00	19	65
125.50	127.00	E856815	0.01	0.20	4.00	12	58
127.00	128.50	E856816	0.01	0.20	22.00	12	51
128.50	130.00	E856817	0.01	0.20	3.00	8	59
130.00	131.50	E856818	0.01	0.20	4.00	25	66
131.50	133.00	E856819	0.01	0.20	7.00	5	67
133.00	134.50	E856820	0.01	0.20	5.00	18	54
134.50	136.00	E856821	0.01	0.20	2.00	18	53
134.50	136.00	E856822					
136.00	137.50	E856823	0.01	0.20	3.00	20	60
137.50	139.00	E856824	0.01	0.20	7.00	8	65
139.00	140.50	E856825	0.01	0.20	2.00	23	60
140.50	142.00	E856826	0.01	0.20	6.00	19	59
142.00	143.50	E856827	0.01	0.20	2.00	44	77
143.50	145.00	E856828	0.01	0.20	2.00	12	73
143.50	145.00	E856829					
143.50	145.00	E856830					
145.00	146.50	E856831	0.01	0.20	14.00	14	65
146.50	148.00	E856832	0.01	0.20	6.00	26	73

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
154.26	166.23	PHYL
		Interlayered graphitic phyllite (70%) and metagreywacke (30%). Similar to above unit.
		« pervasive sil 2.00*»
		« pervaive, in metagreywacke chl 2.00*»
		« foliation parallel blebs py 0.50%»
166.23	168.68	MGWK
		Silicified, more course grain metagreywacke with sparse, detrital, purple quartz crystals.
		« pervasive sil 3.00*»
		« with quartz veins ser 1.00*»
		< @ 166.34 Cross cutting quartz and sericite V 14.00cm >
168.68	174.25	MGWK
		Silicified, interlayered metagreywacke (70%) and graphitic phyllite (30%) with discrete bands of carbonate alteration.
		< @ 165.00 S1 30.00° >
		« pervasive sil 3.00*»
		< @ 172.82 Abundant foliation parallel quartz veins V 30.00° 72.00cm >
		« 164.56- 171.00 several bands of carbonate alteration cal 2.00*»
		« trace, along foliation py 0.50%»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
148.00	149.50	E856833	0.01	0.20	7.00	4	95
149.50	151.00	E856834	0.01	0.20	8.00	18	52
151.00	152.50	E856835	0.01	0.20	8.00	6	55
152.50	154.00	E856836	0.01	0.20	9.00	27	90
154.00	155.50	E856837	0.01	0.20	9.00	17	99
155.50	157.00	E856838	0.01	0.20	3.00	13	98
157.00	158.50	E856839	0.01	0.20	15.00	6	109
158.50	160.00	E856840	0.01	0.20	31.00	15	70
160.00	161.50	E856841	0.01	0.20	32.00	22	73
160.00	161.50	E856842					
161.50	163.00	E856843	0.01	0.20	10.00	14	70
163.00	164.50	E856844	0.01	0.20	19.00	17	53
164.50	166.00	E856845	0.01	0.20	13.00	13	55
166.00	167.50	E856846	0.02	0.20	271.00	19	18
167.50	169.00	E856847	0.01	0.20	123.00	15	30
169.00	170.50	E856848	0.05	0.20	492.00	24	51
169.00	170.50	E856849					
169.00	170.50	E856850					
170.50	172.00	E856851	0.05	0.20	484.00	23	56
172.00	173.50	E856852	0.16	0.20	1315.00	15	32
173.50	175.00	E856853	0.34	0.50	7500.00	11	40

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
174.25	194.88	PHYL
		Highly fractured graphitic phyllite with several large cross cutting quartz veins and zones with abundant chlorite alteration.
		< @ 185.00 S1 55.00° >
		< @ 180.00 Cross cutting quartz V 10.00 >
		< @ 184.92 Foliation cutting quartz V 12.00cm >
		< @ 188.18 Cross cutting quartz V 19.00cm >
		< @ 174.25 Fr 20.63m >
		« With cross cutting quartz veins and in select zones chl 2.00*»
		« graphitic unit grp 4.00%»
		« Disseminated and as blebs along foliation py 0.50%»
194.88	196.49	MGWK
		Heavily siicified metagreywacke with abundant foliation parallel cm scale quartz veining. Trace pyrite along foiation.
		« pervasive sil 3.00»
		« py 1.00%»
		< @ 196.00 metagreywacke brecciated by quartz flooding Vbx 11.00cm >
196.49	230.82	PHYL
		Large fault zone within graphitic phyllite with 40%fault gouge and are few intact rock fragments. There are abundant, cm scale, foliation parallel quartz veins.
		< @ 196.49 40% fault gouge, abundant fractures and rubble Ft 34.33mm >
		< @ 199.00 Brecciated zone altered to clay (gouge) Vbx 23.00cm >
		< @ 201.00 S1 10.00° >
		< @ 209.97 Quartz and chlorite vein V 12.00cm >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
175.00	176.50	E856854	0.04	0.40	231.00	10	56
176.50	179.00	E856855	0.04	0.30	268.00	5	52
179.00	180.50	E856856	0.01	0.20	33.00	12	126
180.50	182.00	E856857	0.01	0.20	30.00	7	61
182.00	183.50	E856858	0.01	0.30	10.00	7	76
183.50	185.00	E856859	0.01	0.20	5.00	7	194
185.00	186.50	E856860	0.01	0.30	2.00	12	265
186.50	188.00	E856861	0.01	0.30	3.00	9	74
186.50	188.00	E856862					
188.00	189.50	E856863	0.01	0.20	11.00	8	118
189.50	191.00	E856864	0.01	0.40	19.00	13	68
191.00	192.50	E856865	0.01	0.30	16.00	14	280
192.50	194.00	E856866	0.03	0.20	7.00	4	95
194.00	195.50	E856867	0.01	0.20	6.00	5	46
195.50	197.00	E856868	0.03	0.20	8.00	7	33
195.50	197.00	E856869					
195.50	197.00	E856870					
197.00	198.50	E856871	0.01	0.90	36.00	50	234
198.50	200.00	E856872	0.01	0.40	18.00	12	79
200.00	201.50	E856873	0.01	0.50	14.00	17	95
201.50	203.00	E856874	0.01	0.50	5.00	13	118
203.00	204.50	E856875	0.01	0.30	4.00	8	75
204.50	206.00	E856876	0.01	0.30	7.00	11	69
206.00	207.50	E856877	0.01	0.40	14.00	7	68
207.50	209.00	E856878	0.41	1.60	5330.00	34	116
209.00	210.50	E856879	0.03	0.50	257.00	52	56

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
		< @ 225.00 crenulations S2 >
		« intact rock fragments sil 1.00*»
		« mus 2.00»
		« Pervasive in zones and with quartz veins chl 2.00*»
		« along foliation py 0.5%
230.82	245.97	MGWK
		Out of the fault zone. Dark grey, silicified metagreywacke with moderately abundant, cm scale, foliation parallel quartz veins and rare foliation cutting quartz veins. Trace pyrite is largely foliation parallel and trace pyrrhotite occurs largely near the brecciated zones. There are discrete zones brecciated with carbonate rich fluids.
		< @ 238.33 90% fault gouge Ft 40.00cm >
		< @ 242.10 Brecciated with carbonate fluids Vbx >
		< @ 232.02 Brecciated with carbonate rich fluids Vbx 12.00cm >
		< @ 234.57 Foliation cutting quartz vein V 65.00° 15.00cm >
		« associated with quartz veins chl 1.00*»
		« ser 1.00*»
		« sil 3.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
210.50	212.00	E856880	0.01	0.20	8.00	13	35
212.00	213.50	E856881	0.01	0.20	4.00	33	34
212.00	213.50	E856882					
213.50	215.00	E856883	0.01	0.20	8.00	7	28
215.00	216.50	E856884	0.01	0.20	3.00	12	36
216.50	218.00	E856885	0.01	0.30	9.00	16	72
218.00	219.50	E856886	0.01	0.20	8.00	14	42
219.50	221.00	E856887	0.01	1.00	25.00	14	235
221.00	222.50	E856888	0.02	0.60	67.00	14	385
221.00	222.50	E856889					
221.00	222.50	E856890					
222.50	224.00	E856891	0.03	0.30	55.00	6	85
224.00	225.50	E856892	0.01	0.40	28.00	11	119
225.50	227.00	E856893	0.02	0.60	53.00	16	325
227.00	228.50	E856894	0.03	0.20	29.00	10	41
228.50	230.00	E856895	0.04	0.20	38.00	7	40
230.00	231.50	E856896	0.03	0.20	24.00	10	39
231.50	233.00	E856897	0.02	0.30	10.00	8	36
233.00	234.50	E856898	0.06	0.20	14.00	7	45
234.50	236.00	E856899	0.04	0.20	9.00	8	38
236.00	237.50	E856900	0.01	0.20	7.00	6	36
237.50	239.00	E856901	0.11	0.20	9.00	9	85
239.00	240.50	E856902	0.02	0.20	4.00	10	46
240.50	242.00	E856903	0.07	0.30	4.00	8	36
242.00	243.50	E856904	0.02	0.30	4.00	9	37
243.50	245.00	E856905	0.01	0.20	6.00	8	40
245.00	245.97	E856906	0.02	0.20	4.00	6	34

Project: Keystone **Hole Number:** KEY10-11

From	To	Rocktype & Description
		« py 1.00%»
		« po 0.10%»
		EOH @ 245.97
245.97	245.97	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 4326.0
Hole KEY10-12	**Azimuth (º):** 325
Location: 7078161 m North, 490503 m East	**Dip (º):** -70.0
Logged by: M. McKeown	**Length (m):** 93.57
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: BTW	**Objective** To further investigate the local soil anomaly of 1026ppb Au at a steeper inclination, thought to be controlled by NE trending structures.
Date Started: 2010/07/21 **Date Completed:** 2010/07/22	
Dip Tests By:	

Summary Log:

1.5-28.19: Silicified, iron-oxide altered metagreywacke with cross-cutting quartz and quartz-siderite veins.
28.19-42.21: Silicified metagreywacke
42.21-43.47: Silicified quartzite with trace apy (0.5%) and py (0.5%).
43.47-64.34: Silicified metagreywacke with zones of carbonate alteration
64.34-65.83: Same as above with abundant cross-cutting quartz-sericite vein
65.83-93.57: Silicified greywacke with minor graphitic interlayers, trace py (1%) and po(0.1%).
93.57 EOH

Downhole surveys:

Depth	Dip	Azimuth
0.00	-70.00	325.00
93.57	-70.00	325.00

Project: Keystone **Hole Number:** KEY10-12

From	To	Rocktype & Description
0.00	1.50	CAS
1.50	15.45	MGWK
		Silicified and fe-oxide altered metagreywacke with foliation parallel and cross-cutting quartz and siderite veins.
		< @ 12.15 cross-cutting quartz with Fe-oxide staining along selvages V 14.00cm >
		< @ 5.01 foliation parallel bull quartz V 8.00cm >
		< @ 9.00 S1 30.00° >
		« pervasive sil 3.00*»
		« foliation parallel and along veins fer 2.00*»
		« foliation parallel and cross-cutting veins sid 1.00*»
		« pervasive mus 1.00»
15.45	18.98	MGWK
		Same unit as above without the iron-oxide alteration and with greater muscovite alteration.
		« sil 3.00*»
		« mus 2.00»
		« sparse mm scale, cross-cutting veinlets sid »
18.98	28.19	MGWK
		Same as the first unit. Silicified, iron-oxide altered metagreywacke with rare quartz and quartz-siderite veins some of whch follow foliation and others that are cross-cutting.
		< @ 23.00 S1 50.00° >
		< @ 18.98 abundant foliation parallel and randomly oriented fractures Fr 9.21m >
		< @ 26.07 cross cutting quartz-siderite V 25.00° 6.00cm >
		« pervasive sil 3.00*»
		« as mm scale, cross-cutting veinlets sid 1.00*»
28.19	34.03	MGWK
		Uniform, silicified metagreywacke with sericitie and muscovite alteration.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
1.50	7.00	E856907	0.01	0.20	10.00	28	48
7.00	8.50	E856908	0.01	0.20	9.00	23	56
7.00	8.50	E856909					
7.00	8.50	E856910					
8.50	10.00	E856911	0.01	0.20	10.00	21	55
10.00	11.50	E856912	0.01	0.20	16.00	24	42
11.50	13.00	E856913	0.01	0.20	17.00	24	59
13.00	14.50	E856914	0.01	0.20	34.00	25	30
14.50	16.00	E856915	0.01	0.20	11.00	24	35
16.00	17.50	E856916	0.01	0.20	11.00	18	23
17.50	19.00	E856917	0.01	0.20	8.00	17	19
19.00	21.00	E856918	0.01	0.20	94.00	19	22
21.00	22.50	E856919	0.01	0.20	74.00	18	38
22.50	24.00	E856920	0.02	0.20	130.00	14	50
24.00	26.50	E856921	0.02	0.20	58.00	15	42
24.00	26.50	E856922					
26.50	28.00	E856923	0.01	0.20	41.00	13	90
28.00	29.50	E856924	0.01	0.20	26.00	6	120
29.50	31.00	E856925	0.01	0.20	14.00	19	71
31.00	32.50	E856926	0.01	0.20	49.00	17	77
32.50	34.00	E856927	0.11	0.20	848.00	5	72

Project: Keystone **Hole Number:** KEY10-12

From	To	Rocktype & Description
		< @ 33.18 Quartz vein V 22.00cm >
		« pervasive sil 3.00*»
		« mus 2.00»
		« along foliation ser 1.00*»
34.03	34.09	MGWK
		Same metagreywacke as above however with chlorite alteration.
		« pervasive sil 3.00*»
		« mus 1.00»
		« pervasive chl 2.00*»
		« appear as specks ser 1.00*»
34.09	42.21	MGWK
		Silicified metagreywacke that grades between a darker slighlty more course grained unit and a lighter more siilty unit with cross cutting quartz-sericite veinlets. Trace pyrite occurs along foliation.
		< @ 37.00 S1 50.00° >
		< @ 39.00 90% fault gouge Ft 40.00cm >
		< @ 39.45 Cross-cutting quartz vein V 11.00cm >
		< @ 39.80 series of cross cutting, mm scale quartz-sericite veinlets V 12.00cm >
		« pervasive sil 3.00*»
		« ser 1.00*»
42.21	43.47	QRZT
		Silicified quartzite interlayered with the metagreywacke package. This unit contains trace, acicular, disseminated arsenopyrite and disseminated pyrite.
		« silicified sil 3.00*»
		« mus 1.00»
		« py 0.50%»
		« apy 0.50%»
43.47	64.34	MGWK



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
34.00	35.50	E856928	0.04	0.20	482.00	9	55
34.00	35.50	E856929					
34.00	35.50	E856930					
35.50	37.00	E856931	0.02	0.20	122.00	8	44
37.00	38.50	E856932	0.01	0.20	65.00	6	34
38.50	40.00	E856933	0.58	0.20	1700.00	10	57
40.00	41.50	E856934	2.55	0.30	5520.00	4	29
41.50	43.00	E856935	1.26	0.20	3270.00	10	41
43.00	44.50	E856936	0.72	0.70	4570.00	12	36
44.50	46.00	E856937	1.29	0.70	9800.00	12	76

Project: Keystone **Hole Number:** KEY10-12

From	To	Rocktype & Description
		Interlayered, silicified metagreywacke (85%) and phyllite (15%) with limited zones of carbonate alteration. The unit is laminated in zones.
		< @ 54.00 S1 30.00° >
		< @ 55.00 lam 30.00° >
		< @ 47.00 40% fault gouge Ft 5.06m >
		« pervasive within metagreywacke sil 3.00*»
		« within phyllitic layers chl 2.00*»
		« 53.50- 54.45 bands of alteration cal 3.00*»
		« 43.47- 64.34 as specks throughout ser 1.00*»
		« trace diseminated py 0.50%»
64.34	65.83	MGWK
		Same metagreywacke unit with an extensive cross cutting, dendritic vein with several stages of alteration including quartz, sericite and chlorite. There are small parts of the vein that are siderite altered. Late stage blebs of pyrite are associated with the vein as well as trace, acicular arsenopyrite.
		< @ 64.34 Quartz, sericite, chlorite, siderite V 1.49m >
		« pervasive in metagreywacke sil 3.00*»
		« within vein chl 2.00*»
		« within vein ser 2.00*»
		« within vein sid 1.00*»
		« as blebs within vein py 2.00%»
		« diseminated, acicular apy 0.50%»
65.83	93.57	MGWK
		Silicified greywacke (85%) with minor graphitic phyllite interlayers (15%) both with abundant foliation parallel quartz veining and lesser cross-cutting quartz veins. There are zones with stringers of pyrite along foliation, largely within the graphitic phyllite. These zones also contain trace blebs of pyrrhotite.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
46.00	47.50	E856938	0.95	0.90	10000.00	8	55
47.50	49.00	E856939	0.39	0.40	2260.00	26	37
49.00	50.50	E856940	0.01	0.20	65.00	33	60
50.50	52.00	E856941	0.02	0.20	238.00	15	32
50.50	52.00	E856942					
52.00	53.50	E856943	0.01	0.20	19.00	20	51
53.50	55.00	E856944	0.01	0.20	19.00	21	32
55.00	56.50	E856945	0.01	0.20	6.00	21	35
56.50	58.00	E856946	0.01	0.20	7.00	14	69
58.00	59.50	E856947	0.01	0.30	29.00	19	27
59.50	61.00	E856948	0.01	0.20	11.00	16	63
59.50	61.00	E856949					
59.50	61.00	E856950					
61.00	62.50	E856951	0.01	1.20	13.00	60	99
62.50	64.00	E856952	0.01	0.20	8.00	11	24
64.00	65.50	E856953	0.01	0.20	5.00	11	50
65.50	67.00	E856954	0.01	0.20	4.00	20	53
67.00	68.50	E856955	0.01	0.20	2.00	17	63
68.50	70.00	E856956	0.01	0.20	2.00	19	81
70.00	71.50	E856957	0.01	0.40	207.00	15	59
71.50	73.00	E856958	0.01	0.30	24.00	12	75
73.00	74.50	E856959	0.01	0.40	2.00	20	50
74.50	76.00	E856960	0.01	0.20	2.00	14	63

Project: Keystone **Hole Number:** KEY10-12

From	To	Rocktype & Description
		< @ 72.00 S1 25.00° >
		< @ 11.00 Cross-cutting quartz with lesser sericite V 23.00cm >
		< @ 89.80 Cross-cutting quartz with minor sericite V >
		< @ 73.33 Foliation parallel quartz V 13.00cm >
		< @ 92.00 Cross cutting quartz with lesser chlorite V 68.00cm >
		« 65.83- 93.57 pervasive sil 2.00*»
		« ser 1.00*»
		« pervasive mus 1.00»
		« 65.83- 93.57 chl 1.00*»
		« 66.00- 79.00 stringers along foliation py 2.00%»
		« 79.00- 93.57 py 0.50%»
		« along foliation po 0.10%»
		EOH @ 93.57
93.57	93.57	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
76.00	77.50	E856961	0.01	0.20	2.00	14	64
76.00	77.50	E856962					
77.50	79.00	E856963	0.01	0.30	2.00	16	61
79.00	80.50	E856964	0.01	0.20	2.00	10	44
80.50	81.50	E856965	0.01	0.40	5.00	16	54
81.50	83.00	E856966	0.01	0.20	4.00	15	50
83.00	84.50	E856967	0.01	0.30	6.00	21	65
84.50	86.00	E856968	0.01	0.20	5.00	18	48
84.50	86.00	E856969					
84.50	86.00	E856970					
86.00	87.50	E856971	0.01	0.20	2.00	20	38
87.50	89.00	E856972	0.01	0.20	6.00	13	45
89.00	90.50	E856973	0.01	0.20	2.00	14	43
90.50	92.00	E856974	0.01	0.30	2.00	12	61

DRILL LOG

Project: Keystone	**Collar Elevation (ft):** 4085.0
Hole KEY10-13	**Azimuth (º):** 325
Location: 7078331 m North, 491601 m East	**Dip (º):** -60.0
Logged by: M. McKeown	**Length (m):** 130.74
Drilled by: Coretech	**Horizontal Projection:**
Assayed by: ALS Chemex	**Vertical Projection:**
Core Size: NTW	**Objective** To investigate the source of a local soil anomaly that is high in Au (546ppb). The source mineralization is thought to be controlled by a NE trending structure.
Date Started: 2010/07/23 **Date Completed:** 2010/07/24	
Dip Tests By:	

Summary Log:

0-6: Casing
6-8: Micaceous, chloritic phyllite with abundant fractures
8-10: Same as above with abundant carbonate and siderite alteration
10-26: Heavily sericite and chlorite altered phyllite
26-28: Same as above with abundant carbonate and siderite alteration
28-29: Same as above without the siderite alteration
29-42: Interlayered graphitic phyllite with abundant chlorite alteration (65%) and highly chlorite altered metagreywacke (35%).
42-68: Same interlayered unit as above with abundant carbonate alteration
68-76: Laminated chloritic and graphitic phyllite with carbonate alteration and quartz-siderite veins.
76-119: Fault zone within highly chlorite altered metagreywacke
119-127: Out of fault zone silicified, chlorite altered metagreywacke
127-131: Fault zone within graphitic phyllite
130.74: EOH

Downhole surveys:

Depth	Dip	Azimuth
0.00	-60.00	325.00
130.74	-60.00	325.00

Project: Keystone **Hole Number:** KEY10-13

From	To	Rocktype & Description
0.00	6.10	CAS
6.10	7.70	PHYL

Micaceous, heavily chlorite altered, fractured phyllite.

< @ 7.00 S1 60.00° >
< @ 6.10 Fractures along foliation Fr 1.60m >
« chl 3.00*»
« mus 2.00»

From	To	Rocktype & Description
7.70	9.60	PHYL

Same micaceous, chloritic phyllite however with abundant carbonate and quartz-siderite alteration and veining creating a slight breccia texture.

< @ 7.95 Quartz-siderite V 60.00° 9.00cm >
< @ 8.81 30% fault gouge Ft 80.00cm >
« alteration along foliation fer 2.00*»
« pervasive chl 3.00*»
« pervasive mus 2.00»
« within veins and along foliation sid 2.00*»

From	To	Rocktype & Description
9.60	26.42	PHYL

Heavily chlorite and sericite altered micaceous phyllite with zones of carbonate alteration.

< @ 17.00 S1 40.00° >
< @ 19.30 crenulations S2 10.00° >
< @ 14.00 20% gouge, fractured along foliation Fr 30.00cm >
< @ 14.89 Quartz with zones of iron oxide staining V 65.00° 9.00cm >
« pervasive chl 2.00*»
« pervasive ser 3.00*»
« 18.65- 18.85 band of carbonate alteration cal 3.00*»
« as minor veins and pervasive sil 1.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
6.10	7.50	E856976	0.01	0.20	7.00	7	100
7.50	9.00	E856977	0.01	0.80	12.00	73	39
9.00	10.50	E856978	0.01	0.20	2.00	3	92
10.50	12.00	E856979	0.01	0.20	2.00	6	79
12.00	13.50	E856980	0.01	0.20	2.00	2	92
13.50	15.00	E856981	0.01	0.20	2.00	19	67
13.50	15.00	E856982					
15.00	16.50	E856983	0.01	0.40	2.00	31	80
16.50	18.00	E856984	0.01	0.30	3.00	19	89
18.00	19.50	E856985	0.01	0.30	2.00	21	67
19.50	21.00	E856986	0.01	0.20	2.00	14	92
21.00	22.50	E856987	0.01	0.20	2.00	49	99
22.50	24.00	E856988	0.01	0.30	2.00	29	100
22.50	24.00	E856989					
22.50	24.00	E856990					
24.00	25.50	E856991	0.01	0.60	3.00	22	90

Project: Keystone **Hole Number:** KEY10-13

From	To	Rocktype & Description
26.42	27.97	PHYL
		Same chloritic, micaceous phyllite with abundant siderite and carbonate alteration. « as cross-cutting veins and along foliation sid 2.00*» « bands of alteration seeminly associated with the siderite alteration cal 2.00*» « pervasive ser 3.00*» « pervasive chl 2.00*»
27.97	29.44	PHYL
		Same unit as above however without the siderite alteration and with greater carbonate alteration. « chl 2.00*» « ser 3.00*» « as bands and blebs along foliation cal 3.00*» « mus 1.00»
29.44	42.00	PHYL
		Interalyered graphitic and chlorite altered phyllite (65%) with zones of very heavily chlorite altered metagreywacke (35%) with heavy specks and bands of chlorite alteration. < @ 32.00 S1 50.00° > < @ 33.04 quartz-siderite V 60.00° 11.00cm > < @ 35.00 quartz V 10.00cm > < @ 34.80 highly fractured, randomly oriented fragments Fr 90.00cm > « pervasive in both units however stronger in the metagreywacke unit chl 3.00*» « 38.38- 35.54 within the metagreywacke unit cal 2.00*» « 40.20- 40.65 within the metagreywacke unit cal 2.00*» « focused within the phyllite layers ser 2.00*»
42.00	68.30	PHYL
		Interlayered chloritic metagreywacke (30%) with chloritic and lesser graphitic phyllite (70%). Both units have zones with specks and bands of carbonate alteration.



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
25.50	27.00	E856992	0.01	0.40	2.00	16	91
27.00	28.50	E856993	0.01	0.30	7.00	19	78
28.50	30.00	E856994	0.01	0.30	4.00	13	69
30.00	31.50	E856995	0.01	0.40	3.00	8	68
31.50	33.00	E856996	0.01	0.20	9.00	31	67
33.00	34.50	E856997	0.01	0.50	7.00	6	131
34.50	36.00	E856998	0.01	0.30	5.00	13	74
36.00	37.50	E856999	0.01	0.30	3.00	13	63
37.50	39.00	E857000	0.01	0.30	21.00	18	72
39.00	40.50	E857001	0.01	0.40	17.00	14	56
39.00	40.50	E857002					
40.50	42.00	E857003	0.01	0.40	3.00	17	76
42.00	43.50	E857004	0.01	0.40	12.00	3	118
43.50	45.00	E857005	0.01	0.50	11.00	2	129
45.00	46.50	E857006	0.01	0.30	8.00	2	126
46.50	48.00	E857007	0.01	0.30	8.00	10	130

Project: Keystone **Hole Number:** KEY10-13

From	To	Rocktype & Description
		< @ 60.00 S1 45.00° >
		< @ 42.00 40% gouge Ft 54.00cm >
		< @ 42.00 Highly fractured zone Fr 2.66m >
		< @ 64.54 100% fault gouge Ft 35.00cm >
		< @ 52.00 foliation cutting quartz-siderite vein V 39.00cm >
		« pervasive chl 3.00*»
		« abundant as specks along foliation cal 2.00*»
		« along quartz veins, following foliation sid 1.00*»
		« trace diseminated py 0.1»
68.30	75.95	PHYL
		Laminated chloritic and graphitic phyllite with moderately abundant carbonate alteration and quartz-siderite veins.
		< @ 70.00 S1 60.00° >
		< @ 71.00 lam 60.00° >
		< @ 71.49 90% fault gouge Ft 27.00cm >
		« pervasive chl 3.00*»
		« with foliation parallel quartz veins ser 1.00*»
		« with quartz veins sid 1.00*»
		« as veins and bands cal 2.00*»
75.95	96.32	MGWK
		Highly chlorite altered metagreywacke with moderately abundant carbonate alteration as specks as bands. This section contains a large fault zone.
		< @ 79.48 40% fault gouge Ft 6.02m >



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
48.00	49.50	E857008	0.01	0.20	6.00	4	79
48.00	49.50	E857009					
48.00	49.50	E857010					
49.50	51.00	E857011	0.01	0.30	9.00	6	130
51.00	52.50	E857012	0.01	0.20	3.00	9	91
52.50	54.00	E857013	0.01	0.30	5.00	5	149
54.00	55.50	E857014	0.01	0.30	5.00	2	173
55.50	57.00	E857015	0.01	0.30	6.00	2	176
57.00	57.50	E857016	0.01	0.20	5.00	2	156
57.50	59.00	E857017	0.01	0.50	7.00	2	163
59.00	60.50	E857018	0.01	0.20	9.00	5	130
60.50	62.00	E857019	0.01	0.20	13.00	3	128
62.00	63.50	E857020	0.01	0.20	2.00	6	119
63.50	65.00	E857021	0.01	0.20	7.00	10	111
63.50	65.00	E857022					
65.00	66.50	E857023	0.01	0.20	3.00	13	59
66.50	68.00	E857024	0.01	0.20	2.00	18	61
68.00	69.50	E857025	0.01	0.20	3.00	14	86
69.50	71.00	E857026	0.01	0.20	5.00	16	91
71.00	72.50	E857027	0.01	0.20	124.00	25	67
72.50	74.00	E857028	0.01	0.20	25.00	15	76
72.50	74.00	E857029					
72.50	74.00	E857030					
74.00	75.50	E857031	0.01	0.30	50.00	20	182
75.50	77.00	E857032	0.01	0.20	17.00	8	114
77.00	78.50	E857033	0.01	0.20	12.00	2	129
78.50	80.00	E857034	0.01	0.20	60.00	2	127
80.00	81.50	E857035	0.01	0.20	118.00	2	144
81.50	83.00	E857036	0.01	0.20	57.00	5	136
83.00	85.50	E857037	0.01	0.20	103.00	16	113

Project: Keystone **Hole Number:** KEY10-13

From	To	Rocktype & Description
		« pervasive chl 3.00*»
		« as specks and bands along foliation cal 2.00*»
		« along fracture surfaces fer 1.00*»
		< @ 91.16 60% fault gouge Ft 1.84m >
96.32	97.00	PHYL
		Faulted zone of laminated graphitic phyllite with abundant bands of carbonate alteration.
		< @ 96.62 70% fault gouge Ft 15.00mm >
		< @ 96.40 lam 30.00° >
		« as bands along foliation cal 2.00*»
		« along fracture surfaces fer 1.00%»
97.00	118.62	MGWK
		Fault zone within chlorite altered metagreywacke with moderately abundant carbonate alteration as bands along foliation.
		< @ 98.00 S1 65.00° >
		< @ 97.00 abundant fractures Fr 6.00m >
		< @ 103.00 70% fault gouge Ft 1.10m >
		< @ 105.00 abundant fractures Fr 6.00m >
		< @ 111.00 randomly oriented fractures with 25% fault gouge Fr 7.62m >
		< @ 111.74 Quartz-siderite vein, highly fractured V 39.00cm >
		« pervasive chl 2.00*»
		« band along foliation cal 2.00*»



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
85.50	87.00	E857038	0.01	0.20	34.00	2	119
87.00	88.50	E857039	0.01	0.20	30.00	9	116
88.50	90.00	E857040	0.01	0.20	20.00	11	74
90.00	91.50	E857041	0.01	0.20	14.00	5	123
90.00	91.50	E857042					
91.50	93.00	E857043	0.01	0.20	120.00	11	89
93.00	94.50	E857044	0.01	0.20	10.00	4	110
94.50	96.00	E857045	0.01	0.20	5.00	3	129
96.00	97.50	E857046	0.01	0.20	20.00	7	98
97.50	99.00	E857047	0.01	0.20	27.00	7	94
99.00	100.50	E857048	0.01	0.20	20.00	2	100
99.00	100.50	E857049					
99.00	100.50	E857050					
100.50	102.00	E855751	0.01	0.30	20.00	18	80
102.00	103.50	E855752	0.01	0.20	7.00	4	126
103.50	105.00	E855753	0.01	0.20	12.00	7	94
105.00	106.50	E855754	0.01	0.20	33.00	6	112
106.50	108.00	E855755	0.01	0.20	23.00	6	129
108.00	109.50	E855756	0.01	0.20	23.00	10	43
109.50	111.00	E855757	0.01	0.20	18.00	12	24
111.00	112.50	E855758	0.01	0.20	112.00	10	42
112.50	114.00	E855759	0.01	0.20	34.00	33	97
114.00	115.50	E855760	0.01	0.20	65.00	38	160
115.50	118.00	E855761	0.01	0.20	127.00	11	45

Project: Keystone **Hole Number:** KEY10-13

From	To	Rocktype & Description
118.62	127.10	MGWK
		Same metagreywacke unit as above however less fractured , more silicified and with moderately abundant foliation parallel quartz-siderite veins.
		« pervasive sil 2.00*»
		« in quartz-siderite veins sid 1.00%»
		« within some veins and as foliation parallel veins cal 1.00*»
127.10	130.76	PHYL
		Fault zone within graphitic phyllite unit.
		< @ 129.00 fault gouge Ft 1.76m >
		« pervasive chl 2.00*»
		« pervasive mus 1.00»
		130.76 EOH
130.76	130.76	EOH



From	To	Sample	Au ppm	Ag ppm	As ppm	Pb ppm	Zn ppm
115.50	118.00	E855762					
118.00	119.50	E855763	0.01	0.30	24.00	15	60
119.50	121.00	E855764	0.01	0.20	5.00	21	48
121.00	122.50	E855765	0.01	0.20	9.00	19	40
122.50	124.00	E855766	0.01	0.90	33.00	13	31
124.00	125.50	E855767	0.01	0.20	14.00	29	37
125.50	127.00	E855768	0.04	0.20	178.00	13	76
125.50	127.00	E855769					
125.50	127.00	E855770					
127.00	128.50	E855771	0.01	0.90	46.00	38	174
128.50	130.76	E855772	0.01	48.50	13.00	12	123

Appendix E: Geotech Logs

Project: ***ALN10-01*** **Claim:** ***Keystone*** **Hole No :** ***KEY10-01***

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
0.00	5.79	5.79	0.90	16	0.21	4	0.104	0.413	64.77	66.90	2.13	1.78	84	1.02	48	0.213	1.122
5.79	7.01	1.22	1.15	94	0.29	24	0.000	0.197	66.90	69.19	2.29	1.96	86	1.16	51	0.211	0.601
7.01	7.92	0.91	0.83	91	0.35	38	0.215	0.685	69.19	70.71	1.52	1.34	88	0.57	38	0.058	0.330
7.92	10.06	2.14	1.93	90	0.67	31	0.214	0.690	70.71	71.32	0.61	0.65	107	0.00	0	0.168	1.180
10.06	10.97	0.91	0.70	77	0.10	11	0.178	0.423	71.32	72.24	0.92	0.58	63	0.24	26	0.139	0.349
10.97	12.80	1.83	1.41	77	0.41	22	0.193	2.206	72.24	74.07	1.83	1.49	81	0.56	31	0.577	2.564
12.80	14.33	1.53	1.36	89	0.30	20	0.038	0.296	74.07	74.68	0.61	0.64	105	0.52	85	0.163	0.417
14.33	15.70	1.37	1.12	82	0.41	30	0.099	0.915	74.68	77.11	2.43	1.73	71	0.32	13	0.111	0.614
15.70	17.37	1.67	1.13	68	1.05	63	0.089	0.241	77.11	77.44	0.33	0.33	100	0.00	0	0.077	0.206
17.37	19.81	2.44	2.17	89	0.66	27	0.186	1.079	77.44	82.07	4.63	3.81	82	0.99	21	-0.067	0.529
19.81	23.16	3.35	3.04	91	1.27	38	0.282	1.454	82.07	83.84	1.77	1.59	90	0.80	45	0.005	0.212
23.16	24.23	1.07	0.61	57	0.33	31	0.357	0.751	83.84	86.89	3.05	2.82	92	1.53	50	-0.717	0.485
24.23	25.30	1.07	1.06	99	0.22	21	0.263	0.742	86.89	88.72	1.83	1.68	92	0.88	48	0.084	0.589
25.30	28.96	3.66	3.50	96	2.47	67	0.228	1.040	88.72	90.58	1.86	1.84	99	0.77	41	0.114	0.383
28.96	30.18	1.22	1.06	87	0.57	47	0.150	0.754	90.58	93.57	2.99	2.46	82	1.14	38	0.045	0.484
30.18	32.61	2.43	2.40	99	2.15	88	0.168	0.994	93.57	93.88	0.31	0.28	90	0.22	71	0.171	0.731
32.61	34.44	1.83	1.59	87	1.08	59	0.267	0.951	93.88	94.64	0.76	0.41	54	0.21	28	0.123	0.256
34.44	35.66	1.22	1.23	101	0.66	54	0.152	0.518	94.64	95.40	0.76	0.30	39	0.00	0	0.125	0.822
35.66	37.49	1.83	1.49	81	0.65	36	0.180	1.131	95.40	96.14	0.74	0.53	72	0.00	0	0.037	0.244
37.49	39.62	2.13	2.02	95	1.81	85	0.319	0.750	96.14	98.14	2.00	1.04	52	0.37	19	0.062	0.479
39.62	41.15	1.53	1.46	95	0.99	65	0.215	0.618	98.14	99.38	1.24	0.37	30	0.00	0	0.071	0.373
41.15	43.59	2.44	1.98	81	1.31	54	0.228	2.370	99.38	101.80	2.42	1.48	61	0.00	0	0.114	0.306
43.59	45.11	1.52	1.56	103	0.89	59	0.209	1.873	101.80	102.41	0.61	0.49	80	0.23	38	0.131	0.274
45.11	46.33	1.22	1.39	114	0.63	52	0.190	1.256	102.41	103.94	1.53	1.07	70	0.10	7	0.219	0.453
46.33	47.55	1.22	0.89	73	0.25	20	0.115	0.454	103.94	105.16	1.22	0.99	81	0.00	0	0.175	0.550
47.55	48.46	0.91	0.71	78	0.11	12	0.210	1.536	105.16	106.68	1.52	1.01	66	0.12	8	0.098	0.225
48.46	49.07	0.61	0.62	102	0.35	57	0.211	1.601	106.68	108.05	1.37	0.36	26	0.00	0	0.123	0.567
49.07	50.29	1.22	0.78	64	0.00	0	0.172	1.135	108.05	109.88	1.83	0.58	32	0.00	0	0.132	1.287
50.29	53.34	3.05	2.93	96	2.19	72	0.342	2.115	109.88	110.64	0.76	0.59	78	0.00	0	0.085	0.511
53.34	56.39	3.05	3.00	98	2.45	80	0.568	3.113	110.64	112.93	2.29	1.69	74	0.40	17	0.077	0.275
56.39	57.76	1.37	1.37	100	1.20	88	0.162	0.741	112.93	113.69	0.76	0.51	67	0.00	0	0.146	1.281
57.76	58.67	0.91	1.02	112	0.88	97	0.132	0.243	113.69	114.91	0.76	0.54	71	0.00	0	0.133	1.443
58.67	61.72	3.05	3.02	99	2.68	88	0.125	0.636	114.91	116.28	1.37	0.63	46	0.00	0	0.071	0.169
61.72	64.77	3.05	2.78	91	1.37	45	0.112	0.568	116.28	117.92	1.64	1.43	87	0.86	52	0.154	1.200

Project: Aldrin **Claim: Keystone** **Hole # : KEY10-01** **Page 2 of 2**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
117.92	119.82	1.90	1.63	86	0.36	19	0.080	0.674									
119.82	121.01	1.19	0.99	83	0.40	34	0.011	0.132									
121.01	123.44	2.43	2.26	93	0.58	24	0.227	0.722									
123.44	124.50	1.06	1.00	94	0.34	32	0.249	0.669									
124.50	127.72	3.22	3.02	94	0.72	22	0.297	0.897									
127.72	128.62	0.90	0.81	90	0.11	12	0.456	1.045									
128.62	130.76	2.14	1.83	86	0.35	16	0.471	1.317									
130.76	132.00	1.24	1.13	91	0.23	19	0.217	0.648									
132.00	132.89	0.89	0.39	44	0.11	12	0.520	1.648									
132.89	135.03	2.14	1.26	59	0.00	0	0.372	0.885									
135.03	135.94	0.91	0.59	65	0.00	0	0.333	0.900									
135.94	137.46	1.52	0.67	44	0.00	0	-0.819	0.240									
137.46	138.07	0.61	0.43	70	0.00	0	0.084	0.179									
138.07	140.06	1.99	1.41	71	0.43	22	0.405	1.059									
140.06	140.97	0.91	0.78	86	0.00	0	0.595	1.782									
140.97	142.34	1.37	1.15	84	0.00	0	0.537	1.259									
142.34	142.65	0.31	0.31	100	0.24	77	0.402	0.785									
142.65	144.48	1.83	1.49	81	0.52	28	0.201	0.808									
144.48	145.85	1.37	1.24	91	0.46	34	0.076	0.165									
145.85	148.13	2.28	2.04	89	0.84	37	0.127	1.083									
148.13	149.50	1.37	1.25	91	0.21	15	0.107	0.312									
149.50	152.71	3.21	3.04	95	2.12	66	0.127	0.465									
152.71	153.77	1.06	1.05	99	0.00	0	0.119	0.443									
153.77	156.06	2.29	1.99	87	0.93	41	0.098	0.218									
156.06	157.28	1.22	0.73	60	0.00	0	0.174	0.315									
157.28	157.89	0.61	0.60	98	0.00	0	1.016	2.382									
157.89	158.80	0.91	0.85	93	0.10	11	0.467	2.145									
		END		OF		HOLE											

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *KEY10-02* **Page :** *1 of 2*

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
0.00	4.57	4.57	0.84	18	0.00	0	0.180	0.658	76.50	77.72	1.22	0.98	80	0.53	43	0.067	0.243
4.57	7.01	2.44	2.10	86	0.69	28	0.038	0.211	77.72	80.77	3.05	2.98	98	2.45	80	0.300	0.936
7.01	8.69	1.68	1.39	83	0.11	7	0.105	0.669	80.77	83.82	3.05	3.02	99	2.58	85	0.223	1.184
8.69	9.45	0.76	0.52	68	0.10	13	0.194	0.543	83.82	86.87	3.05	2.98	98	2.40	79	0.122	0.567
9.45	10.36	0.91	0.89	98	0.21	23	0.078	0.197	86.87	88.70	1.83	1.60	87	1.25	68	0.157	0.438
10.36	11.28	0.92	0.74	80	0.10	11	0.115	0.354	88.70	89.92	1.22	1.43	117	1.14	93	0.131	0.310
11.28	14.02	2.74	2.46	90	0.94	34	0.105	0.399	89.92	92.96	3.04	3.00	99	1.73	57	0.105	0.665
14.02	16.00	1.98	1.76	89	0.20	10	0.226	0.579	92.96	96.01	3.05	2.69	88	1.38	45	0.048	0.291
16.00	18.44	2.44	2.28	93	0.95	39	0.147	0.779	96.01	97.23	1.22	0.84	69	0.00	0	0.093	0.726
18.44	20.12	1.68	1.66	99	1.08	64	0.131	0.481	97.23	98.45	1.22	1.11	91	0.31	25	0.037	0.226
20.12	22.10	1.98	1.97	99	1.08	55	0.199	0.760	98.45	100.58	2.13	1.77	83	0.65	31	0.239	0.721
22.10	23.77	1.67	1.47	88	0.44	26	0.205	1.488	100.58	101.80	1.22	0.94	77	0.18	15	0.050	0.356
23.77	25.91	2.14	2.13	100	1.73	81	0.151	0.429	101.80	103.63	1.83	1.34	73	0.16	9	0.031	0.212
25.91	28.19	2.28	2.13	93	1.13	50	0.130	0.688	103.63	105.16	1.53	0.72	47	0.12	8	0.069	0.246
28.19	29.87	1.68	1.45	86	0.26	15	0.285	1.109	105.16	106.68	1.52	0.47	31	0.15	10	0.032	0.181
29.87	32.00	2.13	2.21	104	1.45	68	0.069	0.368	106.68	108.20	1.52	1.08	71	0.23	15	0.040	0.125
32.00	34.75	2.75	2.45	89	0.76	28	0.045	0.411	108.20	110.19	1.99	1.94	97	0.14	7	0.053	0.315
34.75	37.03	2.28	1.71	75	1.20	53	0.074	1.210	110.19	111.71	1.52	0.51	34	0.00	0	0.044	0.155
37.03	39.93	2.90	3.07	106	2.69	93	0.068	0.440	111.71	113.23	1.52	0.59	39	0.10	7	0.086	0.439
39.93	42.98	3.05	2.91	95	2.66	87	0.060	0.256	113.23	114.91	1.68	1.07	64	0.10	6	0.137	0.498
42.98	46.02	3.04	3.01	99	2.58	85	0.120	0.500	114.91	117.35	2.44	1.95	80	0.59	24	0.111	0.618
46.02	47.24	1.22	1.22	100	1.09	89	0.159	0.344	117.35	120.40	3.05	2.86	94	0.61	20	0.123	0.571
47.24	50.29	3.05	3.03	99	2.16	71	0.136	0.329	120.40	122.53	2.13	1.07	50	0.34	16	0.055	0.157
50.29	53.34	3.05	3.02	99	1.74	57	0.293	0.982	122.53	123.44	0.91	0.18	20	0.00	0	0.049	0.309
53.34	55.78	2.44	2.33	95	0.67	27	0.236	0.919	123.44	124.66	1.22	1.03	84	0.13	11	0.048	0.233
55.78	58.83	3.05	3.04	100	2.35	77	0.816	1.921	124.66	127.10	2.44	0.93	38	0.10	4	0.040	0.412
58.83	61.87	3.04	2.54	84	1.87	62	0.546	1.696	127.10	127.71	0.61	0.56	92	0.00	0	0.034	0.115
61.87	64.31	2.44	2.83	116	2.14	88	0.635	2.157	127.71	129.54	1.83	0.27	15	0.00	0	0.083	0.274
64.31	65.53	1.22	1.01	83	0.51	42	0.180	0.759	129.54	131.22	1.68	0.92	55	0.00	0	0.046	0.285
65.53	68.58	3.05	3.00	98	2.33	76	0.163	0.907	131.22	132.59	1.37	0.54	39	0.00	0	0.023	0.201
68.58	71.02	2.44	2.44	100	1.29	53	0.285	0.913	132.59	135.64	3.05	2.61	86	0.75	25	0.009	0.441
71.02	72.54	1.52	1.26	83	0.52	34	0.192	0.519	135.64	136.55	0.91	0.55	60	0.00	0	0.021	0.128
72.54	74.68	2.14	2.18	102	1.20	56	0.131	0.541	136.55	137.92	1.37	0.53	39	0.00	0	0.004	0.070
74.68	76.50	1.82	1.88	103	1.27	70	0.005	0.197	137.92	140.97	3.05	2.86	94	0.84	28	-0.017	0.467

Project : *ALN10-01* **Claim :** *Keystone* **Hole # :** *KEY10-02* **Page 2 of 2**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
140.97	142.95	1.98	1.82	92	0.46	23	0.016	0.197									
142.95	144.17	1.22	1.09	89	0.12	10	0.078	0.211									
144.17	144.78	0.61	0.38	62	0.14	23	0.097	0.293									
144.78	146.61	1.83	1.75	96	0.91	50	0.101	0.658									
146.61	147.22	0.61	0.57	93	0.00	0	0.067	0.193									
147.22	148.44	1.22	1.10	90	0.17	14	0.160	0.549									
148.44	149.50	1.06	0.42	40	0.00	0	0.134	0.381									
149.50	150.88	1.38	1.03	75	0.00	0	0.023	0.422									
150.88	153.92	3.04	2.49	82	1.76	58	0.016	0.293									
153.92	156.97	3.05	3.05	100	1.35	44	-0.035	0.886									
156.97	159.72	2.75	2.71	99	1.18	43	-0.134	0.240									
159.72	162.76	3.04	2.96	97	1.78	59	0.034	0.571									
162.76	163.98	1.22	1.22	100	0.20	16	0.029	0.473									
163.98	166.12	2.14	1.34	63	0.37	17	0.040	0.320									
166.12	169.16	3.04	3.04	100	2.04	67	-0.063	0.565									
169.16	171.30	2.14	2.14	100	1.35	63	-0.008	0.133									
171.30	173.40	2.10	1.56	74	0.21	10	-0.052	1.684									
173.40	175.30	1.90	1.83	96	1.53	81	-0.053	0.844									
175.30	178.35	3.05	3.04	100	2.45	80	-0.091	3.135									
178.35	181.40	3.05	3.02	99	2.48	81	-0.051	0.573									
181.40	184.45	3.05	3.05	100	1.68	55	-0.043	1.283									
184.45	187.50	3.05	3.20	105	1.87	61	-0.021	0.427									
187.50	190.54	3.04	3.03	100	1.34	44	0.041	0.507									
190.54	193.59	3.05	3.01	99	0.93	30	0.097	0.741									
193.59	196.64	3.05	2.98	98	1.43	47	0.120	3.965									
196.64	199.69	3.05	3.00	98	2.14	70	0.587	1.875									
199.69	202.74	3.05	3.02	99	2.09	69	0.128	0.365									
202.74	205.79	3.05	3.05	100	2.19	72	-0.255	0.934									
205.79	208.84	3.05	3.05	100	1.78	58	0.221	0.442									
208.84	210.45	1.61	1.61	100	0.30	19	0.096	0.353									
210.45	213.72	3.27	3.27	100	0.93	28	0.116	0.772									
213.72	216.46	2.74	2.74	100	2.52	92	0.178	0.500									
216.46	219.51	3.05	2.90	95	2.71	89	0.018	0.731									

Project : *ALN10-01* **Claim :** *Keystone* **Hole # :** *KEY10-04* **Page :** *1 of 1*

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
0.00	7.92	7.92	0.25	3	0.00	0	0.111	0.688	87.17	90.22	3.05	2.52	83	0.49	16	0.088	1.335
7.92	10.97	3.05	0.30	10	0.00	0	0.014	0.105	90.22	93.27	3.05	2.89	95	0.66	22	0.145	0.966
10.97	14.02	3.05	0.20	7	0.00	0	0.260	0.205	93.27	96.32	3.05	1.93	63	0.00	0	0.066	0.617
14.02	17.07	3.05	0.50	16	0.00	0	0.009	0.077	96.32	99.36	3.04	1.74	57	0.00	0	0.059	0.467
17.07	20.12	3.05	0.40	13	0.00	0	0.024	0.480	99.36	101.80	2.44	2.44	100	0.46	19	0.175	1.363
20.12	23.16	3.05	1.50	49	0.15	5	0.063	0.337	101.80	102.72	0.92	0.63	68	0.34	37	0.102	0.311
23.16	26.21	3.05	2.80	92	0.62	20	0.142	0.614									
26.21	29.26	3.05	3.00	98	1.01	33	0.236	1.369			END		OF		HOLE		
29.26	30.48	1.22	1.06	87	0.60	49	0.035	0.442									
30.48	30.94	0.46	0.40	87	0.00	0	0.039	0.113									
30.94	32.31	1.37	1.30	95	0.00	0	0.193	1.058									
32.31	32.92	0.61	0.50	82	0.00	0	0.300	1.128									
32.92	33.53	0.61	0.60	98	0.00	0	0.294	1.402									
33.53	33.83	0.30	0.20	66	0.00	0	0.137	0.535									
33.83	35.36	1.52	1.49	98	0.13	9	0.202	0.747									
35.36	38.40	3.05	2.25	74	0.35	11	0.240	1.408									
38.40	41.45	3.05	1.00	33	0.00	0	0.077	0.234									
41.45	44.50	3.05	1.80	59	0.22	7	0.074	0.312									
44.50	47.55	3.05	2.82	93	0.24	8	0.086	0.659									
47.55	50.60	3.05	2.04	67	0.37	12	0.067	0.559									
50.60	53.64	3.05	2.10	69	0.67	22	0.067	0.668									
53.64	56.69	3.05	2.21	73	0.11	4	0.026	0.306									
56.69	59.74	3.05	2.58	85	0.39	13	-0.729	0.359									
59.74	62.79	3.05	2.66	87	0.76	25	0.115	0.541									
62.79	64.92	2.13	1.51	71	0.28	13	0.082	0.201									
64.92	67.06	2.14	1.78	83	1.01	47	0.080	0.227									
67.06	67.97	0.91	0.91	100	0.46	51	0.063	0.222									
67.97	68.88	0.91	0.61	67	0.23	25	0.144	0.417									
68.88	71.93	3.05	2.85	93	1.84	60	0.089	0.427									
71.93	74.98	3.05	2.78	91	1.73	57	0.142	0.558									
74.98	78.03	3.05	2.79	91	1.58	52	0.182	0.569									
78.03	81.08	3.05	2.85	93	1.65	54	0.175	0.749									
81.08	84.12	3.04	2.98	98	0.78	26	0.100	0.684									
84.12	87.17	3.05	2.84	93	0.69	23	0.165	0.593									

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *KEY10-05* **Page 1 of 1**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
0.00	5.18	5.18	1.19	23	0.25	5	0.037	0.090									
5.18	8.23	3.05	2.05	67	0.49	16	0.015	0.132									
8.23	11.28	3.05	2.90	95	1.77	58	-0.086	0.180									
11.28	14.33	3.05	2.73	90	1.30	43	0.000	0.144									
14.33	17.37	3.04	2.40	79	1.59	52	0.111	0.201									
17.37	20.42	3.05	2.88	94	1.63	53	0.142	0.266									
20.42	23.47	3.05	2.50	82	0.73	24	-0.009	0.173									
23.47	26.52	3.05	2.11	69	0.43	14	0.059	0.121									
26.52	29.57	3.05	2.72	89	0.49	16	-0.003	0.109									
29.57	32.61	3.04	2.75	90	0.23	8	0.059	0.119									
32.61	35.66	3.05	2.24	73	0.58	19	-0.183	0.102									
35.66	38.71	3.05	0.59	19	0.13	4	0.002	0.046									
38.71	41.76	3.05	1.41	46	0.00	0	0.115	0.157									
41.76	44.81	3.05	2.24	73	0.55	18	0.038	0.285									
44.81	47.85	3.04	2.80	92	2.07	68	0.148	0.455									
47.85	50.90	3.05	1.93	63	0.88	29	-0.137	0.075									
50.90	53.95	3.05	2.31	76	1.16	38	0.173	0.173									
53.95	57.00	3.05	1.93	63	0.48	16	0.032	0.144									
57.00	60.05	3.05	2.70	89	1.49	49	0.031	0.186									
60.05	63.10	3.05	2.73	90	2.31	76	0.026	0.055									
63.10	66.15	3.05	2.80	92	1.91	63	0.103	0.229									

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *KEY 10-06* **Page 1 of 1**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
0.00	5.49	5.49	3.09	56	0.12	2	0.018	0.146	97.23	104.24	7.01	1.98	28	0.00	0	0.012	0.206
5.49	8.53	3.04	2.74	90	0.11	4	-0.053	0.041	104.24	105.77	1.53	0.95	62	0.00	0	0.001	0.647
8.53	11.58	3.05	2.43	80	1.67	55	0.064	0.698	105.77	108.81	3.04	2.49	82	0.00	0	-0.158	0.094
11.58	14.63	3.05	2.61	86	0.77	25	-0.043	0.319	108.81	111.86	3.05	1.71	56	0.00	0	-0.051	0.166
14.63	17.68	3.05	1.83	60	0.46	15	0.049	0.113	111.86	114.91	3.05	1.95	64	0.00	0	-0.102	0.119
17.68	20.42	2.74	2.63	96	0.23	8	0.060	0.296	114.91	117.96	3.05	0.83	27	0.10	3	0.016	0.207
20.42	23.47	3.05	2.55	84	0.56	18	0.089	0.372	117.96	121.01	3.05	1.32	43	0.00	0	-0.058	0.138
23.47	26.52	3.05	2.86	94	1.06	35	0.028	0.249	121.01	124.05	3.04	1.80	59	0.46	15	0.027	0.494
26.52	29.57	3.05	2.91	95	1.48	49	0.024	0.630	124.05	127.10	3.05	2.17	71	0.26	9	-0.067	0.111
29.57	32.61	3.04	2.69	88	0.42	14	-0.042	0.145	127.10	130.15	3.05	3.51	115	0.43	14	-0.095	0.182
32.61	35.66	3.05	2.79	91	1.28	42	-0.262	0.356	130.15	133.20	3.05	2.33	76	0.31	10	-0.052	0.185
35.66	38.71	3.05	2.87	94	1.51	50	0.026	0.387	133.20	136.25	3.05	3.05	0	0.23	8	0.230	0.054
38.71	41.76	3.05	2.72	89	1.96	64	0.087	0.751	136.25	139.30	3.05	2.88	94	0.24	8	0.021	0.115
41.76	44.81	3.05	1.78	58	0.00	0	0.090	0.153	139.30	142.35	3.05	3.05	100	0.00	0	-0.036	0.977
44.81	47.85	3.04	2.78	91	0.26	9	-0.065	0.057	142.35	145.40	3.05	2.26	74	0.72	24	-0.014	0.083
47.85	50.90	3.05	2.76	90	0.76	25	-0.327	0.969	145.40	148.45	3.05	2.58	85	1.12	37	0.014	0.158
50.90	53.95	3.05	2.87	94	0.41	13	0.006	0.101	148.45	151.50	3.05	2.69	88	0.66	22	-0.256	0.000
53.95	57.00	3.05	2.65	87	1.28	42	0.003	0.097	151.50	154.55	3.05	2.63	86	0.65	21	-0.033	0.173
57.00	59.59	2.59	2.21	85	0.27	10	0.045	0.198	154.55	157.58	3.03	2.37	78	0.31	10	-0.048	0.381
59.59	60.96	1.37	0.90	66	0.00	0	0.012	0.587	157.58	160.63	3.05	2.85	93	0.13	4	-0.064	0.082
60.96	63.09	2.13	2.13	100	1.93	91	0.087	0.870	160.63	163.68	3.05	2.73	90	0.33	11	-0.045	0.064
63.09	66.14	3.05	3.05	100	2.39	78	0.280	1.619	163.68	166.73	3.05	3.05	100	1.21	40	0.002	0.126
66.14	67.06	0.92	0.76	83	0.00	0	-0.056	0.231	166.73	169.77	3.04	2.79	92	0.37	12	0.010	0.194
67.06	69.19	2.13	1.69	79	0.30	14	-0.109	0.599	169.77	172.82	3.05	0.88	29	0.00	0	0.156	0.785
69.19	72.24	3.05	2.15	70	0.46	15	-0.013	0.466	172.82	175.87	3.05	3.05	100	0.33	11	-0.031	0.155
72.24	75.29	3.05	2.12	70	0.86	28	0.128	0.724	175.87	178.31	2.44	1.74	71	0.00	0	0.001	0.078
75.29	78.33	3.04	2.47	81	0.33	11	0.007	1.593									
78.33	81.38	3.05	2.00	66	0.38	12	-0.028	0.195									
81.38	84.43	3.05	1.98	65	0.22	7	-0.185	0.255									
84.43	87.48	3.05	2.99	98	1.55	51	-0.044	0.180									
87.48	90.50	3.02	2.65	88	1.23	41	0.004	0.289									
90.53	93.57	3.04	3.02	99	0.61	20	-0.139	0.077									
93.57	96.23	2.66	1.08	41	0.00	0	0.020	0.206									
96.23	97.23	1.00	0.22	22	0.00	0	0.005	0.153									

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *KEY10-07*

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
0.00	7.62	7.62	0.68	9	0.25	3	0.122	0.188	67.51	70.10	2.59	2.57	99	0.88	34	0.146	0.581
7.62	10.67	3.05	2.40	79	0.70	23	0.007	0.213	70.10	71.32	1.22	1.22	100	0.21	17	0.700	1.095
10.67	13.72	3.05	3.04	100	2.33	76	-0.541	0.028	71.32	72.24	0.92	0.76	83	0.33	36	0.350	0.528
13.72	16.46	2.74	2.37	86	1.76	64	0.144	0.266	72.24	74.68	2.44	2.63	108	0.99	41	0.060	0.186
16.46	17.07	0.61	0.49	80	0.11	18	0.144	0.174	74.68	77.72	3.04	2.89	95	1.15	38	0.085	1.498
17.07	19.20	2.13	1.40	66	1.34	63	0.148	0.372	77.72	80.77	3.05	2.83	93	1.00	33	0.110	0.714
19.20	21.64	2.44	2.03	83	1.01	41	0.045	0.141	80.77	83.82	3.05	1.63	53	0.25	8	0.001	0.222
21.64	22.25	0.61	0.60	98	0.23	38	0.182	0.338	83.82	86.87	3.05	2.75	90	1.59	52	0.495	4.766
22.25	24.38	2.13	1.47	69	0.42	20	-0.335	0.000	86.87	88.09	1.22	1.14	93	0.39	32	0.135	0.619
24.38	25.76	1.38	1.37	99	0.81	59	0.031	0.048	88.09	90.83	2.74	2.21	81	0.83	30	0.291	1.665
25.76	27.43	1.67	1.14	68	0.10	6	0.127	0.331	90.83	91.74	0.91	0.73	80	0.34	37	0.198	1.087
27.43	28.65	1.22	0.69	57	0.00	0	0.330	0.446	91.74	94.79	3.05	2.99	98	1.74	57	0.108	0.576
28.65	30.48	1.83	1.70	93	1.12	61	-0.116	0.046	94.80	96.00	1.20	0.67	56	0.11	9	0.126	0.769
30.48	31.39	0.91	0.63	69	0.11	12	0.182	0.411	96.00	99.06	3.06	2.97	97	0.52	17	0.218	0.936
31.39	32.92	1.53	1.15	75	0.63	41	0.013	0.273	99.06	102.10	3.04	3.17	104	1.14	38	0.058	0.662
32.92	33.22	0.30	0.30	100	0.00	0	0.111	0.256	102.10	105.16	3.06	3.04	99	2.00	65	0.105	3.904
33.22	36.27	3.05	1.72	56	0.76	25	0.040	0.289	105.16	106.70	1.54	1.31	85	0.35	22	0.119	0.702
36.27	38.25	1.98	1.27	64	0.50	25	0.026	0.319	106.70	108.90	2.20	1.88	85	0.66	30	0.103	0.732
38.25	40.23	1.98	1.74	88	0.97	49	0.011	0.477	108.80	111.25	2.45	2.60	106	1.45	59	0.017	1.345
40.23	42.67	2.44	2.12	87	1.19	49	-0.141	0.158	111.25	114.00	2.75	2.72	99	1.78	67	0.209	1.522
42.67	44.50	1.83	1.83	100	1.09	60	-0.330	0.326	114.00	117.35	3.35	3.38	101	1.13	34	0.097	0.892
44.50	45.72	1.22	0.94	77	0.13	11	0.009	0.129	117.35	120.40	3.05	2.47	81	1.72	56	0.178	1.279
45.72	47.85	2.13	1.62	76	0.54	25	-0.201	0.523	120.40	123.44	3.04	3.01	99	2.44	80	0.156	1.270
47.85	50.29	2.44	2.39	98	1.50	61	0.043	0.248	123.44	126.49	3.05	3.05	100	2.40	79	0.110	0.435
50.29	51.82	1.53	1.06	69	0.00	0	0.038	0.093	126.49	129.54	3.05	3.10	102	1.79	59	0.171	1.018
51.82	53.64	1.82	1.39	76	0.40	22	0.060	0.562	129.54	132.59	3.05	2.93	96	1.15	38	0.283	2.427
53.64	54.56	0.92	0.63	68	0.00	0	0.117	0.650	132.59	135.64	3.05	3.05	100	1.09	36	0.047	0.684
54.56	55.47	0.91	0.72	79	0.00	0	0.032	0.585	135.64	138.68	3.04	2.43	80	0.61	25	0.278	1.283
55.47	59.49	4.02	2.98	74	0.14	3	0.157	0.422	138.68	141.73	3.05	2.94	96	0.81	27	0.447	1.610
59.49	62.48	2.99	0.66	22	0.00	0	-0.343	0.254	141.73	144.78	3.05	2.95	97	0.95	31	0.402	1.299
62.48	64.31	1.83	0.86	47	0.00	0	-0.328	0.051	144.78	147.83	3.05	2.95	97	1.66	54	0.249	0.981
64.31	65.53	1.22	1.22	100	0.22	18	0.041	0.659	147.83	150.88	3.05	3.05	100	2.08	68	0.525	2.353
65.53	67.51	1.98	1.69	85	0.48	24	0.227	0.463	150.88	153.92	3.04	3.04	100	2.26	74	0.406	1.824
67.51	70.10	2.59	2.52	97	0.59	23	0.020	0.096	153.92	156.97	3.05	3.03	99	2.24	73	0.266	1.259

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *Key10-07* **page 2 of 2**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
156.97	160.02	3.05	3.05	100	1.55	51	0.224	2.807									
160.02	163.07	3.05	2.97	97	2.00	66	0.411	1.851									
163.07	166.12	3.05	3.05	100	2.41	79	0.193	0.694									
166.12	169.16	3.04	3.04	100	2.20	72	0.215	1.065									
169.16	172.21	3.05	3.05	100	2.15	70	0.444	1.761									
172.21	173.89	1.68	1.18	70	0.53	32	0.290	0.850									
173.89	176.94	3.05	2.96	97	2.66	87	0.558	3.017									
176.94	179.98	3.04	3.04	100	2.94	97	0.158	0.611									
179.98	182.88	2.90	2.89	100	2.79	96	-0.193	1.109									
182.88	185.93	3.05	3.05	100	2.70	89	0.107	0.732									
185.93	188.98	3.05	3.05	100	2.29	75	-0.101	0.522									
188.98	192.02	3.04	3.05	100	2.53	83	0.002	1.304									
192.02	193.55	1.53	1.48	97	1.36	89	0.033	1.085									
193.55	196.60	3.05	3.05	100	2.45	80	0.092	0.819									
196.60	199.64	3.04	3.04	100	0.47	15	0.193	1.599									
199.64	202.69	3.05	3.02	99	1.52	50	0.118	0.313									
202.69	205.74	3.05	2.65	87	1.56	51	-0.061	0.203									
205.74	208.79	3.05	3.02	99	1.92	63	0.120	2.764									
208.79	211.84	3.05	3.05	100	2.10	69	0.250	0.552									
211.84	214.88	3.04	3.04	100	2.15	71	0.111	1.217									
214.88	217.93	3.05	3.05	100	2.56	84	0.144	1.476									
217.93	220.98	3.05	3.01	99	1.48	49	0.215	0.973									
220.98	224.03	3.05	3.05	100	2.51	82	0.237	1.394									
224.03	227.08	3.05	2.94	96	1.78	58	0.200	1.000									
227.08	230.12	3.04	3.04	100	0.91	30	0.314	1.515									
230.12	233.17	3.05	3.04	100	2.38	78	0.279	1.829									
233.17	236.22	3.05	3.05	100	2.19	72	0.349	1.363									
236.22	239.27	3.05	3.05	100	0.97	32	0.094	1.516									
239.27	242.32	3.05	3.05	100	1.50	49	0.217	1.093									
242.32	245.36	3.04	2.94	97	1.21	40	0.170	0.984									
245.36	248.41	3.05	3.05	100	1.71	56	0.092	1.094									

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *KEY10-08* **Page 1 of 1**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
0.00	4.88	4.88	0.53	11	0.00	0	0.118	0.661	62.79	65.23	2.44	2.31	95	1.40	57	0.049	0.261
4.88	5.49	0.61	0.58	95	0.00	0	0.810	1.697	65.23	67.67	2.44	2.31	95	1.47	60	-0.015	0.596
5.49	6.10	0.61	0.51	84	0.00	0	0.054	0.158	67.67	69.49	1.82	1.51	83	0.75	41	-0.175	0.301
6.10	6.71	0.61	0.53	87	0.00	0	0.042	0.171	69.49	72.54	3.05	1.09	36	0.13	4	-0.394	0.136
6.71	10.67	3.96	1.98	50	1.01	26	0.122	0.684	72.54	73.00	0.46	0.46	100	0.00	0	-0.073	0.747
10.67	11.58	0.91	0.81	89	0.35	38	0.109	0.515									
11.58	14.33	2.75	2.62	95	1.94	71	0.148	0.573									
14.33	16.15	1.82	1.33	73	0.46	25	0.147	0.968									
16.15	17.68	1.53	1.47	96	1.09	71	0.149	1.086									
17.68	19.51	1.83	1.83	100	0.99	54	0.076	0.412									
19.51	20.42	0.91	0.88	97	0.38	42	0.199	1.517									
20.42	21.99	1.57	1.23	78	0.51	32	0.089	0.239									
21.99	23.77	1.78	1.57	88	0.49	28	0.046	0.621									
23.77	26.37	2.60	2.38	92	1.22	47	0.098	1.390									
26.37	27.74	1.37	1.26	92	0.58	42	0.029	0.162									
27.74	28.96	1.22	0.90	74	0.39	32	0.116	1.396									
28.96	29.87	0.91	0.71	78	0.65	71	0.183	1.011									
29.87	32.92	3.05	2.44	80	1.34	44	0.016	0.565									
32.92	34.44	1.52	0.86	57	0.30	20	0.130	0.841									
34.44	35.36	0.92	0.81	88	0.12	13	0.142	0.915									
35.36	36.27	0.91	0.81	89	0.21	23	0.201	0.319									
36.27	37.80	1.53	0.81	53	0.10	7	0.032	0.224									
37.80	39.32	1.52	1.45	95	0.00	0	0.103	0.848									
39.32	42.06	2.74	2.74	100	0.66	24	0.077	0.488									
42.06	45.11	3.05	3.05	100	1.18	39	0.154	0.972									
45.11	48.16	3.05	2.53	83	0.46	15	0.025	0.485									
48.16	50.25	2.09	2.04	98	0.76	36	0.097	0.526									
50.25	51.51	1.26	0.93	74	0.11	9	0.049	0.211									
51.51	52.27	0.76	0.88	116	0.43	57	0.125	0.825									
52.27	54.25	1.98	1.81	91	1.27	64	0.025	0.398									
54.25	57.30	3.05	2.72	89	2.20	72	0.108	0.842									
57.30	59.74	2.44	2.40	98	1.18	48	0.235	1.020									
59.74	60.04	0.30	0.28	93	0.18	60	0.052	0.111									
60.04	62.79	2.75	2.68	97	1.29	47	0.114	1.327									

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *KEY 10-09*

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
0.00	5.18	5.18	1.20	23	0.00	0	-0.193	0.253	111.86	114.91	3.05	3.05	100	0.10	3	0.040	0.205
5.18	8.23	3.05	2.45	80	0.63	21	0.037	0.115	114.91	117.96	3.05	3.05	100	1.20	39	0.050	0.268
8.23	11.28	3.05	2.20	72	0.99	32	-0.508	0.084	117.96	121.01	3.05	3.05	100	0.65	21	0.023	0.150
11.28	14.33	3.05	2.39	78	1.53	50	0.075	0.384	121.01	124.05	3.04	3.04	100	1.81	60	0.051	0.215
14.33	17.37	3.04	2.92	96	1.76	58	0.025	0.374	124.05	127.10	3.05	3.05	100	0.91	30	0.053	0.196
17.37	20.42	3.05	2.80	92	1.71	56	-0.239	0.316	127.10	130.15	3.05	3.05	100	0.50	16	0.059	0.210
20.42	23.47	3.05	2.67	88	0.68	22	-0.533	0.481	130.15	133.20	3.05	3.05	100	0.46	15	0.031	0.154
23.47	26.52	3.05	2.81	92	1.31	43	-0.261	0.386	133.20	136.25	3.05	3.05	100	1.20	39	0.034	0.322
26.52	29.57	3.05	2.78	91	1.60	52	0.529	1.101	136.25	139.29	3.04	3.04	100	2.01	66	0.076	0.622
29.57	32.61	3.04	3.04	100	1.74	57	-0.157	0.430	139.29	142.34	3.05	2.83	93	0.90	30	0.107	0.259
32.61	35.66	3.05	2.80	92	1.51	50	-0.078	0.910	142.34	145.39	3.05	3.05	100	0.89	29	0.074	0.288
35.66	38.71	3.05	2.91	95	1.01	33	-0.043	1.286	145.39	148.44	3.05	2.73	90	0.70	23	0.070	0.469
38.71	41.76	3.05	3.05	100	1.02	33	0.009	0.607	148.44	151.49	3.05	3.05	100	1.97	65	0.131	0.337
41.76	44.81	3.05	3.05	100	2.06	68	-0.161	0.768	151.49	154.53	3.04	2.82	93	1.46	55	0.057	0.196
44.81	47.85	3.04	2.63	87	1.31	43	-0.324	0.270	154.53	157.58	3.05	3.05	100	1.76	58	0.075	0.266
47.85	50.90	3.05	3.32	109	1.56	51	0.101	1.154	157.58	160.63	3.05	3.05	100	1.27	42	0.206	0.380
50.90	53.95	3.05	1.65	54	0.36	12	0.097	0.427	160.63	163.68	3.05	3.05	100	0.29	10	0.018	0.157
53.95	60.05	6.10	3.80	62	1.74	29	0.039	0.451	163.68	166.73	3.05	3.05	100	2.05	67	0.059	0.997
60.05	66.14	6.09	3.03	50	1.82	30	0.140	0.441	166.73	169.77	3.04	3.04	100	1.04	34	0.005	0.283
66.14	69.19	3.05	1.36	45	1.06	35	-0.378	1.031	169.77	172.82	3.05	3.05	100	1.74	55	0.022	0.180
69.19	72.24	3.05	2.71	89	1.25	41	0.177	0.444	172.82	175.87	3.05	3.05	100	0.63	21	0.061	0.561
72.24	75.29	3.05	2.92	96	1.66	54	0.172	0.366	175.87	178.92	3.05	3.05	100	1.06	35	0.100	0.097
75.29	78.33	3.04	2.88	95	2.56	84	0.124	0.436	178.92	181.97	3.05	3.05	100	0.95	31	0.035	0.186
78.33	81.38	3.05	3.11	102	1.98	65	-0.110	0.324	181.97	185.02	3.05	3.05	100	0.31	10	0.060	0.179
81.38	84.43	3.05	1.55	51	0.70	23	-0.041	0.209	185.02	188.07	3.05	3.05	100	0.68	22	0.094	0.222
84.43	87.48	3.05	0.52	17	0.00	0	0.015	0.091	188.07	191.11	3.04	3.04	100	0.66	22	0.006	0.343
87.48	90.53	3.05	0.79	26	0.00	0	-0.053	0.000	191.11	194.16	3.05	3.05	100	0.92	30	0.072	0.297
90.53	93.57	3.04	1.28	42	0.00	0	-0.024	0.064	194.16	197.21	3.05	3.05	100	1.91	63	0.046	0.386
93.57	96.62	3.05	0.62	20	0.00	0	-0.027	0.243	197.21	200.25	3.04	3.04	100	1.52	50	0.006	0.433
96.62	99.67	3.05	2.47	81	0.00	0	-0.049	0.204	200.25	203.30	3.05	3.05	100	0.85	28	0.022	0.269
99.67	102.72	3.05	2.24	73	0.65	21	0.021	0.327	203.30	206.35	3.05	2.98	98	1.52	50	0.357	0.032
102.72	105.77	3.05	3.05	100	0.24	8	0.081	0.335	206.35	209.40	3.05	3.05	100	0.33	11	0.018	0.278
105.77	108.84	3.07	0.00	0	0.00	0	0.000	0.000	209.40	212.45	3.05	3.05	100	0.58	19	0.096	0.249
108.84	111.86	3.02	3.02	100	0.00	0	0.124	0.334	212.45	215.49	3.04	3.04	100	2.29	75	0.015	0.657

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *Key10-09* **Page 2 of 2**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
215.49	218.54	3.05	1.58	52	0.60	20	0.067	0.660									
218.54	221.59	3.05	3.05	100	1.04	34	0.054	0.272									
221.59	224.64	3.05	3.05	100	0.43	14	0.004	3.801									

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *Key10-10*

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
3.05	4.72	1.67	1.40	84	0.00	0	0.208	1.551	60.05	63.09	3.04	2.47	81	0.74	24	0.155	1.35
4.72	5.64	0.92	0.92	100	0.29	32	0.047	0.229	63.09	66.14	3.05	2.88	94	1.95	64	0.125	1.06
5.64	8.23	2.59	1.67	64	0.28	11	0.074	0.517	66.14	69.19	3.05	2.41	79	1.34	44	0.082	1.71
8.23	11.28	3.05	2.58	85	0.12	4	0.078	0.418	69.19	72.24	3.05	0.29	10	0.00	0	0.075	0.15
11.28	14.33	3.05	2.94	96	2.32	76	0.250	1.498	72.24	75.29	3.05	1.30	43	0.27	9	0.706	0.27
14.33	17.07	2.74	2.59	95	1.29	47	0.086	0.505	75.29	77.88	2.59	2.59	100	2.04	79	0.038	0.43
17.07	19.20	2.13	2.09	98	1.29	61	0.109	0.479	77.88	79.25	1.37	1.20	88	0.33	24	0.130	1.39
19.20	20.41	1.21	1.15	95	0.70	58	0.089	0.221	79.25	81.08	1.83	1.46	80	0.67	37	0.248	5.82
20.41	23.47	3.06	2.90	95	1.07	35	0.200	1.521	81.08	84.43	3.35	3.00	90	1.04	31	2.194	22.38
23.47	26.49	3.02	2.75	91	0.55	18	0.076	0.272	84.43	87.48	3.05	2.55	84	0.98	32	0.151	0.88
26.49	28.80	2.31	2.28	99	0.82	35	0.121	0.819	87.48	90.53	3.05	2.97	97	0.93	30	0.184	0.97
28.80	30.18	1.38	1.12	81	0.21	15	0.108	0.226	90.53	93.57	3.04	2.82	93	1.73	57	0.174	1.27
30.18	32.92	2.74	2.45	89	1.38	50	-0.530	0.640	93.57	95.55	1.98	1.70	86	0.47	24	0.356	1.15
32.92	34.14	1.22	0.61	50	0.11	9	-0.326	0.000	95.55	98.60	3.05	3.05	100	1.66	54	0.117	1.59
34.14	35.05	0.91	0.54	59	0.10	11	-0.026	0.144	98.60	101.65	3.05	2.93	96	1.62	53	0.025	0.30
35.05	35.97	0.92	0.82	89	0.60	65	0.039	0.174	101.65	102.72	1.07	1.06	99	0.35	33	0.195	0.94
35.97	37.19	1.22	0.60	49	0.10	8	-0.778	0.000	102.72	105.77	3.05	3.01	99	1.67	55	0.055	0.37
37.19	38.71	1.52	1.29	85	0.10	7	0.071	0.251	105.77	108.81	3.04	3.04	100	1.93	63	0.135	0.85
38.71	40.23	1.52	1.52	100	0.00	0	0.016	0.185	108.81	111.86	3.05	2.89	95	2.05	67	0.027	1.20
40.23	41.76	1.53	0.23	15	0.00	0	0.021	0.037	111.86	114.91	3.05	3.05	100	2.10	67	0.071	0.84
41.76	44.20	2.44	2.23	91	0.99	41	0.100	0.761	114.91	117.96	3.05	2.98	98	1.29	42	0.086	0.23
44.20	46.63	2.43	2.40	99	1.42	58	-0.092	0.161	117.96	121.00	3.04	3.04	100	1.57	52	0.262	1.33
46.63	48.77	2.14	1.97	92	0.64	30	0.052	0.594	121.00	124.05	3.05	3.05	100	2.37	78	0.102	0.62
48.77	50.90	2.13	1.57	74	0.23	11	0.080	0.540	124.05	126.64	2.59	2.52	97	1.91	74	0.060	0.98
50.90	52.73	1.83	1.10	60	0.61	33	-0.818	0.000	126.64	129.69	3.05	3.05	100	1.61	53	0.090	1.00
52.73	55.17	2.44	2.44	100	0.81	33	0.103	0.524	129.69	132.74	3.05	3.05	100	1.65	54	0.367	0.92
55.17	56.54	1.37	1.50	109	0.48	35	0.045	0.162	132.74	135.64	2.90	2.90	100	2.38	82	0.277	1.22
56.54	57.00	0.46	0.56	122	0.39	85	0.051	0.326	135.64	138.68	3.04	2.82	93	1.65	54	0.187	1.39
57.00	60.05	3.05	2.57	84	1.78	58	0.094	0.638	138.68	141.73	3.05	3.05	100	1.94	64	0.410	1.22
									141.73	144.78	3.05	3.05	100	2.32	76	0.122	1.49
									144.78	147.83	3.05	3.00	98	2.39	78	0.267	1.32
									147.83	150.88	3.05	3.05	100	2.26	74	0.486	3.33
									150.88	153.92	3.04	3.04	100	2.24	74	0.290	1.56
									153.92	156.97	3.05	3.05	100	2.12	70	0.386	1.48

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *Key10-10*

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
156.97	160.02	3.05	3.05	100	2.25	74	0.434	1.646									
160.02	163.07	3.05	2.89	95	2.13	70	0.385	1.696									
163.07	163.68	0.61	0.61	100	0.58	95	0.398	1.372									
163.68	166.73	3.05	3.05	100	1.61	53	0.375	2.431									
166.73	168.25	1.52	1.40	92	0.57	37	0.400	0.379									
168.25	169.77	1.52	1.41	93	0.33	22	0.334	1.624									
169.77	172.82	3.05	3.05	100	1.53	50	0.006	1.663									
172.82	175.87	3.05	2.95	97	2.62	86	0.221	0.867									
175.87	178.92	3.05	3.01	99	2.82	92	0.099	0.195									
178.92	181.97	3.05	3.05	100	2.93	96	0.018	0.179									
181.97	182.88	0.91	0.91	100	0.83	91	0.040	0.304									

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *Key10-11* **Page 1 of 1**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
6.07	8.23	2.16	1.42	66	0.00	0	0.054	0.092									
8.23	11.28	3.05	1.11	36	0.49	16	0.031	0.086									
11.28	14.33	3.05	1.21	40	0.48	16	0.092	0.152									
14.33	17.37	3.04	0.46	15	0.00	0	0.014	0.078									
17.37	20.42	3.05	1.23	40	0.00	0	0.013	0.095									
20.42	23.47	3.05	1.82	60	0.00	0	0.039	0.183									
23.47	26.52	3.05	2.54	83	0.69	23	0.059	0.274									
26.52	29.57	3.05	3.05	100	0.81	27	0.025	0.178									
29.57	32.61	3.04	2.82	93	0.99	33	0.029	0.446									
32.61	35.66	3.05	3.05	100	2.12	70	0.171	0.647									
35.66	38.71	3.05	3.05	100	1.53	50	0.140	1.102									
38.71	41.76	3.05	2.93	96	1.44	50	0.086	0.788									
41.76	44.81	3.05	2.99	98	0.80	26	0.168	0.816									
44.81	47.85	3.04	3.00	98	1.44	47	0.195	1.292									
47.85	50.90	3.05	2.94	96	1.83	60	0.089	0.312									
50.90	53.95	3.05	3.05	100	1.52	50	0.082	0.546									
53.95	57.00	3.05	3.05	100	1.69	55	0.560	0.916									
57.00	60.05	3.05	3.00	98	1.88	62	0.134	0.385									
60.05	63.09	3.04	3.04	100	1.84	61	0.044	0.857									
63.09	66.14	3.05	2.82	92	0.25	12	0.024	0.139									
66.14	69.19	3.05	3.05	100	0.47	15	0.061	0.253									
69.19	72.24	3.05	2.89	95	1.34	44	0.040	0.537									
72.24	75.29	3.05	3.05	100	1.26	41	0.098	0.783									
75.29	78.33	3.04	3.04	100	0.76	25	0.077	0.223									
78.33	81.38	3.05	3.00	98	0.75	25	0.098	0.182									

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *KEY 10-12* **Page 1 of 1**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
1.52	4.57	3.05	0.13	4	0.00	0	0.211	0.482	79.86	81.69	1.83	1.70	93	0.41	22	0.255	1.669
4.57	8.53	3.96	1.81	46	0.62	16	0.109	0.734	81.69	84.73	3.04	2.72	89	0.29	10	0.221	1.804
8.53	9.75	1.22	1.21	99	0.47	39	0.092	0.528	84.73	87.78	3.05	2.56	84	0.65	21	0.111	1.584
9.75	12.50	2.75	2.27	83	1.57	57	0.158	1.329	87.78	90.83	3.05	2.80	92	0.82	27	0.189	1.426
12.50	14.63	2.13	2.13	100	0.83	39	0.075	0.865	90.83	93.57	2.74	2.51	92	0.70	26	0.140	1.063
14.63	16.15	1.52	1.22	80	0.39	26	0.194	0.840									
16.15	20.73	4.58	2.43	53	0.50	11	0.082	0.462			END		OF		HOLE		
20.73	22.56	1.83	0.26	14	0.00	0	0.209	0.734									
22.56	23.47	0.91	0.77	85	0.14	15	0.151	0.644									
23.47	25.30	1.83	0.11	6	0.00	0	0.059	0.197									
25.30	26.52	1.22	0.81	66	0.14	11	0.111	0.297									
26.52	28.65	2.13	1.57	74	0.57	27	0.233	0.990									
28.65	29.87	1.22	1.19	98	0.46	38	0.255	0.947									
29.87	31.09	1.22	1.17	96	0.64	52	0.120	0.285									
31.09	32.16	1.07	0.88	82	0.24	22	0.186	0.747									
32.16	32.92	0.76	0.29	38	0.00	0	0.171	0.369									
32.92	35.05	2.13	1.84	86	0.66	31	0.200	0.768									
35.05	35.97	0.92	0.56	61	0.11	12	0.107	0.272									
35.97	38.10	2.13	1.84	86	0.24	11	0.210	0.780									
38.10	39.32	1.22	0.77	63	0.13	11	0.161	0.937									
39.32	42.06	2.74	2.29	84	0.84	31	0.122	0.568									
42.06	45.11	3.05	2.59	85	0.75	25	0.097	0.699									
45.11	48.16	3.05	1.42	47	0.10	3	0.121	0.739									
48.16	51.21	3.05	2.43	80	1.17	38	0.097	0.407									
51.21	54.25	3.04	2.99	98	2.50	82	0.200	1.042									
54.25	57.30	3.05	3.04	100	2.30	75	0.104	1.358									
57.30	60.35	3.05	2.96	97	1.84	60	0.049	0.467									
60.35	63.40	3.05	3.04	100	2.57	84	0.162	1.012									
63.40	66.45	3.05	2.95	97	1.98	65	0.141	0.782									
66.45	69.49	3.04	3.04	100	2.07	68	0.406	1.529									
69.49	72.54	3.05	2.92	96	1.36	45	0.270	1.017									
72.54	75.59	3.05	2.87	94	0.96	31	0.384	1.181									
75.59	77.72	2.13	1.81	85	0.41	19	0.345	1.768									
77.72	79.86	2.14	1.89	88	0.37	17	0.321	0.919									

Project : *Aldrin* **Claim :** *Keystone* **Hole # :** *KEY10-13* **Page 1 of 1**

From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.	From	To	Interval	Recovery	Recovery	RQD	RQD	Mag.	Mag.
(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High	(metres)	(metres)	(metres)	(metres)	(%)	(metres)	(%)	Av.	High
6.10	8.23	2.13	1.23	58	0.34	16	0.089	0.599	108.81	111.86	3.05	2.51	82	0.00	0	0.043	2.098
8.23	11.28	3.05	2.61	86	1.53	50	0.026	0.302	111.86	114.91	3.05	1.26	41	0.00	0	0.050	0.227
11.28	14.33	3.05	2.64	87	1.34	44	0.076	0.285	114.91	117.96	3.05	0.67	22	0.00	0	0.067	0.236
14.33	17.37	3.04	2.83	93	1.28	42	0.073	0.354	117.96	121.01	3.05	2.24	73	0.65	21	0.051	0.347
17.37	20.42	3.05	2.70	89	1.30	43	0.072	0.268	121.01	124.05	3.04	2.74	90	0.85	28	0.083	0.314
20.42	23.47	3.05	2.86	94	1.93	63	0.079	0.290	124.05	127.10	3.05	1.37	45	0.13	4	0.082	0.204
23.47	26.52	3.05	2.52	83	1.42	47	0.053	0.306	127.10	130.15	3.05	1.06	35	0.00	0	0.079	0.315
26.52	29.57	3.05	2.67	88	0.75	25	0.067	0.245	130.15	130.76	0.61	0.22	36	0.00	0	0.036	0.140
29.57	32.61	3.04	2.34	77	0.43	14	0.070	0.243									
32.61	35.66	3.05	3.22	106	1.10	36	0.105	0.371			END		OF		HOLE		
35.66	38.71	3.05	1.77	58	0.78	26	0.114	0.394									
38.71	41.76	3.05	2.81	92	1.29	42	0.116	1.170									
41.76	44.81	3.05	2.09	69	0.49	16	0.110	0.280									
44.81	47.85	3.04	2.63	87	1.29	42	0.205	0.493									
47.85	50.90	3.05	2.69	88	0.96	31	0.096	0.515									
50.90	53.95	3.05	2.61	86	1.13	37	0.164	0.851									
53.95	57.00	3.05	3.00	98	2.74	90	0.321	0.601									
57.00	60.05	3.05	3.07	101	2.77	91	0.239	0.491									
60.05	63.09	3.04	2.79	92	2.63	87	0.224	0.547									
63.09	66.14	3.05	2.99	98	2.13	70	0.156	0.519									
66.14	69.19	3.05	2.93	96	2.27	74	0.126	0.290									
69.19	72.24	3.05	2.81	92	2.21	72	0.121	0.589									
72.24	75.29	3.05	2.92	96	1.10	36	0.086	0.309									
75.29	78.33	3.04	2.91	96	2.02	66	0.189	0.541									
78.33	81.38	3.05	2.03	67	0.77	25	0.115	0.387									
81.38	84.43	3.05	1.28	42	0.27	9	0.106	0.314									
84.43	87.48	3.05	1.87	61	0.00	0	0.093	0.473									
87.48	90.53	3.05	1.93	63	0.00	0	0.109	0.571									
90.53	93.57	3.04	1.87	62	0.57	19	0.131	0.580									
93.57	96.62	3.05	2.11	69	0.26	9	0.142	0.514									
96.62	99.67	3.05	2.17	71	0.25	8	0.099	0.434									
99.67	102.72	3.05	2.79	91	0.50	16	0.124	0.422									
102.72	105.77	3.05	2.09	69	0.00	0	0.074	0.314									
105.77	108.81	3.04	2.22	73	0.12	4	0.088	0.297									

Appendix F: Certificates of Analysis

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-AUG-2010
Account: EIAALN

CERTIFICATE TR10098765

Project: ALN10-01

P.O. No.: ALN10-01_13A

This report is for 52 GRAB samples submitted to our lab in Terrace, BC, Canada on 22-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS TR10098765

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E858086		3.45	<0.005	0.7	0.83	2	<10	40	<0.5	<2	5.43	<0.5	8	9	21	2.39
E858087		2.65	<0.005	0.3	1.05	2	<10	50	<0.5	<2	3.43	<0.5	7	9	14	2.41
E858088		2.38	<0.005	0.2	0.90	11	<10	40	<0.5	<2	2.39	<0.5	9	13	31	2.38
E858089		<0.02	<0.005	0.4	0.87	10	<10	50	<0.5	<2	2.50	<0.5	7	12	29	2.11
E858090		0.09	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	1	0.02
E858091		3.39	<0.005	0.6	1.12	7	<10	50	<0.5	<2	7.4	<0.5	13	11	28	2.73
E858092		1.80	<0.005	<0.2	0.58	2	<10	40	<0.5	<2	2.30	<0.5	8	6	13	1.98
E858093		2.05	<0.005	<0.2	0.50	3	<10	40	<0.5	<2	2.43	<0.5	7	5	17	1.86
E858094		2.18	<0.005	0.3	0.76	<2	<10	50	<0.5	<2	3.26	<0.5	9	7	24	2.52
E858095		2.27	<0.005	0.3	0.83	2	<10	40	<0.5	<2	4.99	<0.5	7	8	16	2.38
E858096		2.83	<0.005	0.2	0.34	2	<10	30	<0.5	<2	5.73	<0.5	5	4	9	1.60
E858097		1.93	<0.005	0.5	0.72	2	<10	40	<0.5	<2	9.0	<0.5	8	6	20	2.11
E858098		2.42	<0.005	0.4	1.33	5	<10	50	<0.5	<2	5.40	<0.5	10	12	29	2.95
E858099		2.09	<0.005	0.3	1.72	11	<10	60	<0.5	<2	2.92	<0.5	10	19	32	3.38
E858100		2.01	<0.005	<0.2	2.22	6	<10	70	<0.5	<2	0.15	<0.5	16	22	29	3.98
E858101		1.58	<0.005	<0.2	1.04	2	<10	40	<0.5	<2	0.56	<0.5	7	16	21	2.27
E858102		1.26	<0.005	<0.2	1.21	5	<10	40	<0.5	<2	0.53	<0.5	9	16	20	2.63
E858103		2.20	<0.005	<0.2	1.27	5	<10	50	<0.5	<2	0.57	<0.5	9	15	21	2.85
E858104		2.39	<0.005	<0.2	1.03	<2	<10	40	<0.5	<2	0.77	<0.5	7	13	19	2.47
E858105		2.92	<0.005	<0.2	2.06	2	<10	50	<0.5	<2	0.31	<0.5	13	22	32	4.17
E858106		2.31	<0.005	0.2	2.06	<2	<10	50	<0.5	<2	0.26	<0.5	14	21	35	4.07
E858107		2.43	<0.005	<0.2	1.19	4	<10	40	<0.5	<2	1.03	<0.5	8	13	17	2.57
E858108		2.04	<0.005	<0.2	1.20	8	<10	40	<0.5	<2	0.80	<0.5	7	12	17	2.65
E858109		<0.02	<0.005	<0.2	1.21	6	<10	40	<0.5	<2	0.79	<0.5	7	12	23	2.68
E858110		0.07	0.914	>100	0.50	4490	<10	20	<0.5	5	0.55	98.5	6	49	294	5.97
E858111		1.84	<0.005	0.3	0.94	63	<10	50	<0.5	<2	0.34	<0.5	8	10	25	2.32
E858112		2.12	<0.005	0.5	0.66	4	<10	30	<0.5	<2	0.22	<0.5	6	8	14	1.69
E858113		3.14	<0.005	<0.2	0.71	<2	<10	30	<0.5	<2	0.68	<0.5	4	8	9	2.02
E858114		2.61	<0.005	<0.2	1.02	5	<10	40	<0.5	<2	0.59	<0.5	6	10	17	2.60
E858115		2.56	<0.005	0.3	1.38	4	<10	50	<0.5	<2	0.81	<0.5	9	15	20	3.10
E858116		1.75	<0.005	<0.2	1.73	9	<10	60	<0.5	<2	0.58	<0.5	13	17	30	3.61
E858117		2.01	<0.005	<0.2	1.96	4	<10	50	<0.5	<2	0.60	<0.5	15	21	40	4.12
E858118		2.26	<0.005	<0.2	1.32	9	<10	60	<0.5	<2	0.13	<0.5	11	13	26	3.00
E858119		2.31	<0.005	<0.2	0.59	2	<10	40	<0.5	<2	0.17	<0.5	7	8	17	2.30
E858120		2.33	<0.005	<0.2	0.93	6	<10	50	<0.5	<2	0.66	<0.5	11	9	30	3.28
E858121		1.33	<0.005	<0.2	0.64	<2	<10	50	<0.5	<2	0.45	<0.5	9	8	32	2.80
E858122		1.27	<0.005	<0.2	0.95	4	<10	40	<0.5	<2	0.54	<0.5	14	11	31	3.37
E858123		2.09	<0.005	<0.2	1.11	15	<10	60	<0.5	<2	0.59	<0.5	17	12	39	3.88
E858124		1.90	<0.005	<0.2	1.09	12	<10	60	<0.5	<2	0.43	<0.5	14	11	33	4.19
E858125		1.67	<0.005	0.3	0.82	14	<10	60	<0.5	<2	0.51	<0.5	15	8	37	3.03

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS TR10098765

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E858086		<10	<1	0.16	10	0.62	775	1	0.02	15	320	26	0.57	<2	1	425
E858087		<10	<1	0.19	20	0.89	991	1	0.02	14	280	58	0.13	2	1	213
E858088		<10	<1	0.14	10	0.57	725	1	0.02	19	180	24	0.39	3	2	129
E858089		<10	<1	0.14	10	0.53	746	<1	0.02	21	190	28	0.26	4	2	130
E858090		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.01	<2	<1	1
E858091		<10	<1	0.18	10	0.90	1405	1	0.02	20	340	24	0.16	2	2	543
E858092		<10	<1	0.17	10	0.86	762	1	0.02	13	240	21	0.20	<2	1	63
E858093		<10	<1	0.16	20	0.86	745	<1	0.02	11	300	28	0.21	<2	1	65
E858094		<10	<1	0.19	10	0.76	717	<1	0.02	16	300	25	0.49	<2	1	142
E858095		<10	<1	0.18	10	0.90	401	1	0.02	15	220	14	0.31	<2	1	209
E858096		<10	<1	0.14	10	0.79	721	1	0.02	8	220	18	0.15	2	1	222
E858097		<10	<1	0.18	10	0.80	697	<1	0.02	13	320	19	0.28	2	1	369
E858098		<10	<1	0.17	10	0.86	437	<1	0.02	21	190	23	0.74	4	2	229
E858099		<10	1	0.19	10	0.84	490	<1	0.02	22	760	15	0.27	2	2	131
E858100		10	<1	0.24	20	0.86	349	<1	0.02	35	340	17	0.10	2	1	19
E858101		<10	1	0.13	20	0.44	469	<1	0.02	15	150	5	0.06	<2	1	27
E858102		<10	<1	0.13	20	0.51	483	<1	0.02	18	180	11	0.08	2	1	27
E858103		<10	1	0.15	20	0.54	540	<1	0.02	20	220	14	0.08	<2	1	30
E858104		<10	<1	0.15	20	0.47	761	3	0.02	15	290	60	0.11	<2	1	43
E858105		10	<1	0.20	20	0.81	586	<1	0.03	33	480	19	0.13	<2	1	32
E858106		10	<1	0.21	20	0.81	573	<1	0.03	33	380	20	0.14	<2	1	30
E858107		<10	<1	0.16	20	0.55	622	<1	0.02	17	290	18	0.09	2	1	61
E858108		<10	<1	0.15	20	0.49	528	<1	0.02	15	220	6	0.10	<2	1	43
E858109		<10	<1	0.16	20	0.48	522	<1	0.02	17	230	7	0.11	<2	1	43
E858110		<10	1	0.31	10	0.10	290	2	0.04	5	650	4820	7.5	1655	1	137
E858111		<10	<1	0.16	10	0.37	467	1	0.02	16	170	22	0.19	5	1	24
E858112		<10	<1	0.12	10	0.24	297	1	0.02	9	80	14	0.08	<2	1	16
E858113		<10	<1	0.12	10	0.37	599	<1	0.01	8	60	10	0.04	<2	1	32
E858114		<10	<1	0.13	10	0.48	712	1	0.01	13	100	10	0.07	<2	1	33
E858115		<10	1	0.17	10	0.64	624	<1	0.02	19	220	23	0.09	2	1	50
E858116		<10	<1	0.17	10	0.74	630	<1	0.02	26	520	9	0.09	<2	1	43
E858117		<10	1	0.18	10	0.85	695	<1	0.03	32	310	17	0.15	<2	2	43
E858118		<10	<1	0.18	10	0.51	811	1	0.02	22	300	13	0.15	<2	2	16
E858119		<10	<1	0.14	10	0.36	516	<1	0.01	13	200	7	0.28	3	1	13
E858120		<10	<1	0.17	10	0.73	858	<1	0.01	22	250	20	0.31	<2	2	38
E858121		<10	<1	0.18	10	0.50	575	1	0.02	26	240	34	0.55	<2	1	26
E858122		<10	<1	0.16	10	0.66	652	1	0.02	24	680	16	0.49	<2	1	34
E858123		<10	<1	0.21	10	0.78	932	<1	0.02	28	910	22	0.19	3	2	39
E858124		<10	<1	0.21	20	0.81	1140	1	0.02	25	220	17	0.13	2	2	29
E858125		<10	<1	0.20	10	0.49	507	1	0.02	27	400	18	0.80	2	1	28

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS TR10098765

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E858086		<20	0.01	<10	<10	6	<10	40		
E858087		<20	<0.01	<10	<10	7	<10	46		
E858088		<20	<0.01	<10	<10	6	<10	42		
E858089		<20	<0.01	<10	<10	7	<10	41		
E858090		<20	<0.01	<10	<10	<1	<10	4		
E858091		<20	<0.01	<10	<10	7	<10	58		
E858092		<20	<0.01	<10	<10	3	<10	42		
E858093		<20	<0.01	<10	<10	3	<10	41		
E858094		<20	<0.01	<10	<10	5	<10	43		
E858095		<20	<0.01	<10	<10	4	<10	49		
E858096		<20	<0.01	<10	<10	1	<10	84		
E858097		<20	<0.01	<10	<10	4	<10	45		
E858098		<20	<0.01	<10	<10	9	<10	175		
E858099		<20	<0.01	<10	<10	13	<10	93		
E858100		<20	0.01	<10	<10	13	<10	96		
E858101		<20	<0.01	<10	<10	8	<10	46		
E858102		<20	<0.01	<10	<10	9	<10	56		
E858103		<20	<0.01	<10	<10	8	<10	65		
E858104		<20	<0.01	<10	<10	7	<10	45		
E858105		<20	<0.01	<10	<10	12	<10	93		
E858106		<20	<0.01	<10	<10	12	<10	92		
E858107		<20	<0.01	<10	<10	8	<10	51		
E858108		<20	<0.01	<10	<10	7	<10	57		
E858109		<20	<0.01	<10	<10	7	<10	59		
E858110		<20	<0.01	<10	<10	6	10	>10000	1.320	114
E858111		<20	<0.01	<10	<10	6	<10	236		
E858112		<20	<0.01	<10	<10	5	<10	32		
E858113		<20	<0.01	<10	<10	4	<10	31		
E858114		<20	<0.01	<10	<10	7	<10	46		
E858115		<20	<0.01	<10	<10	8	<10	59		
E858116		<20	<0.01	<10	<10	11	<10	74		
E858117		<20	<0.01	<10	<10	12	<10	90		
E858118		<20	<0.01	<10	<10	10	<10	53		
E858119		<20	<0.01	<10	<10	4	<10	42		
E858120		<20	<0.01	<10	<10	6	<10	64		
E858121		<20	0.01	<10	<10	6	<10	59		
E858122		<20	<0.01	<10	<10	7	<10	67		
E858123		<20	<0.01	<10	<10	10	<10	70		
E858124		<20	<0.01	<10	<10	10	<10	74		
E858125		<20	<0.01	<10	<10	6	<10	65		

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS TR10098765

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E858126		2.02	<0.005	<0.2	1.16	19	<10	60	0.5	<2	0.22	<0.5	19	11	46	3.92
E858127		2.18	<0.005	<0.2	0.67	4	<10	50	<0.5	<2	0.31	<0.5	9	9	24	2.56
E858128		2.25	<0.005	<0.2	0.89	13	<10	50	<0.5	<2	0.20	<0.5	17	10	39	3.42
E858129		<0.02	0.005	0.2	0.89	16	<10	50	<0.5	<2	0.19	<0.5	18	9	40	3.49
E858130		0.10	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	1	0.02
E858131		2.51	<0.005	<0.2	1.36	8	<10	50	0.5	<2	0.20	<0.5	18	11	49	4.06
E858132		2.03	<0.005	<0.2	1.50	21	<10	50	<0.5	<2	0.16	<0.5	22	16	46	3.58
E858133		3.10	<0.005	<0.2	0.23	31	<10	20	<0.5	<2	0.10	<0.5	2	8	5	0.86
E858134		2.30	0.006	0.3	1.31	27	<10	60	<0.5	<2	0.32	<0.5	14	11	27	3.17
E858135		2.26	<0.005	<0.2	1.00	13	<10	50	<0.5	<2	0.47	<0.5	7	11	18	2.43
E858136		1.99	<0.005	0.3	1.60	7	<10	50	<0.5	<2	0.34	<0.5	12	15	33	4.02
E858137		2.40	<0.005	<0.2	1.31	15	<10	50	<0.5	<2	0.34	<0.5	12	12	29	3.34

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS TR10098765

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E858126		<10	<1	0.22	10	0.74	938	1	0.03	29	450	22	0.17	<2	2	24
E858127		<10	<1	0.17	10	0.44	511	1	0.02	18	130	7	0.46	<2	1	19
E858128		<10	<1	0.20	10	0.56	745	1	0.01	31	310	24	0.54	3	1	19
E858129		<10	<1	0.20	10	0.57	755	1	0.01	32	280	24	0.54	3	1	19
E858130		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	1	10	<2	0.01	<2	<1	<1
E858131		<10	<1	0.23	10	0.77	1055	<1	0.02	32	300	9	0.29	15	2	24
E858132		<10	1	0.20	10	0.68	792	<1	0.02	33	290	32	0.23	21	2	29
E858133		<10	<1	0.08	10	0.08	159	<1	0.01	4	30	5	0.10	11	<1	8
E858134		<10	<1	0.16	10	0.56	599	<1	0.02	21	430	14	0.28	19	2	41
E858135		<10	<1	0.16	10	0.45	393	1	0.02	14	680	13	0.15	8	1	31
E858136		<10	<1	0.19	20	0.75	565	2	0.02	29	220	32	0.20	12	3	28
E858137		<10	1	0.19	10	0.58	524	<1	0.02	23	260	8	0.11	14	2	24

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 3-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS TR10098765

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E858126		<20	<0.01	<10	<10	10	<10	79		
E858127		<20	<0.01	<10	<10	5	<10	46		
E858128		<20	<0.01	<10	<10	6	<10	67		
E858129		<20	<0.01	<10	<10	6	<10	67		
E858130		<20	<0.01	<10	<10	<1	<10	3		
E858131		<20	<0.01	<10	<10	9	<10	83		
E858132		<20	<0.01	<10	<10	14	<10	74		
E858133		<20	<0.01	<10	<10	2	<10	10		
E858134		<20	<0.01	<10	<10	9	<10	54		
E858135		<20	<0.01	<10	<10	7	<10	43		
E858136		<20	<0.01	<10	<10	13	<10	92		
E858137		<20	<0.01	<10	<10	10	<10	66		

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

CERTIFICATE WH10102790

Project: ALN10-01

P.O. No.: ALN10-01_20

This report is for 95 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 27-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102790

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E858238		1.80	0.005	2.1	0.50	33	<10	70	<0.5	<2	1.29	<0.5	15	8	24	2.27
E858239		2.18	0.008	<0.2	0.21	15	<10	40	<0.5	<2	1.03	<0.5	3	11	4	1.22
E858240		2.21	0.062	<0.2	0.26	597	<10	40	<0.5	<2	1.30	<0.5	3	6	5	1.36
E858241		0.80	0.295	0.4	0.28	2550	<10	50	<0.5	<2	3.39	<0.5	5	5	7	1.78
E858242		0.78	0.192	0.4	0.29	2160	<10	50	<0.5	<2	3.46	<0.5	5	6	8	1.78
E858243		2.00	0.135	0.3	0.32	2670	<10	50	<0.5	<2	3.30	<0.5	6	5	9	1.89
E858244		0.44	0.012	0.3	0.27	292	<10	30	<0.5	<2	3.01	<0.5	4	7	8	2.20
E858245		1.45	0.006	<0.2	0.22	19	<10	40	<0.5	<2	0.31	<0.5	2	9	7	0.96
E858246		2.34	0.007	0.4	0.23	26	<10	50	<0.5	<2	14.1	<0.5	6	3	14	1.37
E858247		2.12	<0.005	0.2	0.47	7	<10	60	<0.5	<2	0.80	<0.5	5	9	11	1.50
E858248		1.00	0.006	<0.2	1.71	30	<10	90	<0.5	<2	0.45	<0.5	17	14	34	3.67
E858249		<0.02	0.006	<0.2	1.78	27	<10	100	<0.5	<2	0.38	<0.5	18	14	32	3.88
E858250		0.10	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	1	0.03
E858251		2.25	<0.005	<0.2	1.39	3	<10	90	<0.5	<2	0.42	<0.5	16	16	33	3.23
E858252		2.20	<0.005	<0.2	1.39	<2	<10	90	<0.5	<2	0.31	<0.5	17	16	69	3.27
E858253		1.44	0.006	<0.2	1.26	6	<10	100	<0.5	<2	0.45	<0.5	16	15	30	3.17
E858254		1.16	0.008	0.4	1.03	35	<10	160	<0.5	<2	0.52	<0.5	14	14	21	2.50
E858255		2.42	0.054	<0.2	1.32	3	<10	90	<0.5	<2	0.30	<0.5	15	16	30	3.23
E858256		2.62	<0.005	<0.2	1.27	<2	<10	70	<0.5	<2	0.65	<0.5	17	18	40	2.74
E858257		2.01	0.007	<0.2	1.13	<2	<10	80	<0.5	<2	0.67	<0.5	20	35	97	2.62
E858258		1.72	<0.005	0.3	0.85	<2	<10	50	<0.5	<2	10.7	<0.5	10	12	29	1.71
E858259		2.35	0.005	0.4	0.51	5	<10	30	<0.5	<2	18.7	<0.5	4	5	10	1.29
E858260		2.24	<0.005	0.3	0.96	4	<10	40	<0.5	<2	12.9	<0.5	9	8	21	2.42
E858261		0.91	<0.005	<0.2	1.29	4	<10	70	<0.5	<2	1.56	<0.5	10	14	22	2.69
E858262		0.74	0.006	0.2	1.05	<2	<10	50	<0.5	<2	2.28	<0.5	8	12	13	2.27
E858263		2.10	0.005	0.2	1.31	4	<10	70	<0.5	<2	1.94	<0.5	9	14	16	2.62
E858264		2.29	0.005	0.2	1.49	12	<10	70	<0.5	<2	1.63	<0.5	16	16	25	3.11
E858265		1.88	<0.005	0.2	0.78	<2	<10	40	<0.5	<2	1.42	<0.5	5	11	6	1.73
E858266		2.12	0.005	0.2	0.73	2	<10	60	<0.5	<2	2.02	<0.5	6	10	8	1.62
E858267		1.91	0.006	<0.2	0.83	5	<10	60	<0.5	<2	2.03	<0.5	6	11	9	1.83
E858268		1.92	<0.005	0.2	1.01	<2	<10	60	<0.5	<2	2.44	<0.5	8	12	20	2.24
E858269		<0.02	<0.005	0.3	0.99	4	<10	60	<0.5	<2	2.58	<0.5	8	12	21	2.17
E858270		0.07	0.933	>100	0.51	4490	<10	20	<0.5	5	0.53	97.9	7	52	296	6.02
E858271		2.44	0.005	<0.2	1.13	<2	<10	60	<0.5	<2	1.36	<0.5	9	13	14	2.57
E858272		2.18	0.005	0.3	1.17	3	<10	60	<0.5	<2	2.06	<0.5	11	14	16	2.61
E858273		2.21	<0.005	0.3	0.82	3	<10	50	<0.5	<2	2.22	<0.5	5	11	9	1.77
E858274		2.34	0.011	0.2	1.21	2	<10	70	<0.5	<2	1.15	<0.5	10	15	17	2.55
E858275		1.95	0.005	0.3	0.99	7	<10	70	<0.5	<2	5.85	<0.5	12	10	25	2.15
E858276		2.29	0.008	0.3	0.97	3	<10	60	<0.5	<2	9.3	<0.5	8	10	13	2.20
E858277		1.94	0.006	0.4	1.54	2	<10	70	<0.5	<2	6.05	<0.5	14	14	32	3.33

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102790

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E858238		<10	<1	0.25	20	0.51	228	3	0.02	19	500	15	0.10	5	1	202
E858239		<10	<1	0.14	10	0.37	321	1	0.02	4	100	13	0.04	<2	<1	55
E858240		<10	<1	0.16	10	0.41	382	1	0.01	4	90	16	0.22	7	1	63
E858241		<10	<1	0.18	<10	0.37	620	<1	0.01	7	110	17	0.68	12	1	254
E858242		<10	<1	0.18	<10	0.33	625	1	0.01	8	110	19	0.72	14	1	259
E858243		<10	<1	0.19	10	0.31	558	1	0.01	10	190	15	0.82	10	1	231
E858244		<10	<1	0.10	10	0.51	721	1	0.03	6	160	29	0.17	14	1	171
E858245		<10	<1	0.13	10	0.13	123	<1	0.02	3	140	13	0.06	4	<1	26
E858246		<10	<1	0.20	<10	0.27	812	1	0.02	10	320	25	0.45	8	1	1070
E858247		<10	<1	0.22	20	0.31	320	1	0.02	8	200	14	0.09	3	1	52
E858248		<10	<1	0.32	30	0.81	691	<1	0.01	38	260	4	0.03	3	1	37
E858249		<10	1	0.34	30	0.85	709	<1	0.02	39	270	5	0.03	2	1	33
E858250		<10	<1	<0.01	<10	0.01	<5	<1	<0.01	<1	10	<2	<0.01	<2	<1	1
E858251		<10	1	0.29	20	0.72	975	<1	0.02	32	240	4	0.10	<2	1	29
E858252		<10	<1	0.30	20	0.69	836	<1	0.02	34	260	5	0.03	2	1	30
E858253		<10	<1	0.31	30	0.68	1200	<1	0.02	31	250	5	0.03	<2	1	32
E858254		<10	<1	0.22	20	0.62	707	1	0.02	23	260	6	0.01	<2	1	41
E858255		<10	<1	0.29	20	0.68	586	1	0.02	29	290	7	0.17	<2	1	28
E858256		<10	<1	0.22	20	0.79	858	<1	0.02	28	310	7	<0.01	<2	2	61
E858257		<10	<1	0.24	20	0.70	796	1	0.02	33	290	12	0.06	<2	1	55
E858258		<10	<1	0.16	10	0.52	1845	1	0.02	16	320	11	0.02	<2	2	284
E858259		<10	<1	0.10	10	0.35	2450	2	0.02	7	310	14	<0.01	<2	2	602
E858260		<10	<1	0.21	10	0.47	614	1	0.02	16	350	12	0.52	3	1	493
E858261		<10	<1	0.27	20	0.53	208	1	0.02	21	590	20	0.22	2	1	88
E858262		<10	<1	0.23	20	0.44	310	1	0.02	14	430	36	0.10	<2	1	101
E858263		<10	<1	0.26	20	0.53	390	<1	0.02	17	210	13	0.01	<2	1	105
E858264		<10	<1	0.27	20	0.66	330	<1	0.02	25	290	9	0.05	<2	1	103
E858265		<10	<1	0.17	20	0.40	420	1	0.02	9	130	20	0.05	<2	1	81
E858266		<10	<1	0.20	10	0.34	439	<1	0.03	9	120	24	0.06	<2	1	128
E858267		<10	<1	0.21	10	0.44	490	<1	0.03	10	120	40	0.05	<2	1	125
E858268		<10	<1	0.23	10	0.50	522	<1	0.03	13	250	18	0.10	<2	1	134
E858269		<10	<1	0.22	10	0.50	530	1	0.03	13	270	16	0.09	<2	1	142
E858270		<10	1	0.32	10	0.09	289	2	0.04	5	650	4860	7.4	1750	1	132
E858271		<10	<1	0.23	20	0.53	304	<1	0.02	15	180	53	0.09	<2	1	82
E858272		<10	<1	0.26	10	0.52	308	1	0.03	17	190	23	0.12	<2	1	140
E858273		<10	<1	0.19	20	0.44	611	1	0.02	12	120	23	0.05	<2	1	131
E858274		<10	1	0.26	20	0.54	296	1	0.02	18	150	28	0.08	4	1	61
E858275		<10	<1	0.28	20	0.42	604	1	0.02	16	410	15	0.06	<2	1	343
E858276		<10	<1	0.23	10	0.45	1215	1	0.02	13	300	19	0.10	<2	2	427
E858277		<10	<1	0.29	10	0.70	880	<1	0.01	24	420	15	0.29	<2	2	304

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102790

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E858238		<20	<0.01	<10	<10	3	<10	38		
E858239		<20	<0.01	<10	<10	2	<10	15		
E858240		<20	<0.01	<10	<10	1	<10	13		
E858241		<20	<0.01	<10	<10	1	<10	57		
E858242		<20	<0.01	<10	<10	2	<10	24		
E858243		<20	<0.01	<10	<10	2	<10	30		
E858244		<20	<0.01	<10	<10	1	<10	29		
E858245		<20	<0.01	<10	<10	1	<10	13		
E858246		<20	<0.01	<10	<10	2	<10	22		
E858247		<20	<0.01	<10	<10	2	<10	25		
E858248		20	<0.01	<10	<10	10	<10	81		
E858249		20	<0.01	<10	<10	10	<10	83		
E858250		<20	<0.01	<10	<10	<1	<10	3		
E858251		<20	0.01	<10	<10	10	<10	67		
E858252		20	0.03	<10	<10	11	<10	70		
E858253		20	0.01	<10	<10	11	<10	63		
E858254		<20	<0.01	<10	<10	7	<10	55		
E858255		<20	0.03	<10	<10	12	<10	61		
E858256		<20	0.01	<10	<10	10	<10	66		
E858257		<20	0.03	<10	<10	16	<10	63		
E858258		<20	0.01	<10	<10	8	<10	42		
E858259		<20	<0.01	<10	<10	3	<10	19		
E858260		<20	0.01	<10	<10	5	<10	38		
E858261		<20	0.01	<10	<10	8	<10	58		
E858262		<20	0.01	<10	<10	7	<10	45		
E858263		<20	0.02	<10	<10	8	<10	50		
E858264		<20	0.02	<10	<10	9	<10	57		
E858265		<20	0.01	<10	<10	6	<10	38		
E858266		<20	0.01	<10	<10	5	<10	32		
E858267		<20	<0.01	<10	<10	5	<10	40		
E858268		<20	<0.01	<10	<10	6	<10	47		
E858269		<20	<0.01	<10	<10	6	<10	46		
E858270		<20	<0.01	<10	<10	6	<10	>10000	1.300	148
E858271		<20	<0.01	<10	<10	7	<10	53		
E858272		<20	0.01	<10	<10	8	<10	53		
E858273		<20	<0.01	<10	<10	5	<10	39		
E858274		<20	0.01	<10	<10	8	<10	52		
E858275		<20	0.01	<10	<10	7	<10	35		
E858276		<20	0.01	<10	<10	6	<10	38		
E858277		<20	0.01	<10	<10	8	<10	62		

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102790

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E858278		2.45	0.007	0.2	1.70	4	<10	70	<0.5	<2	4.43	<0.5	13	16	31	3.71
E858279		2.05	<0.005	<0.2	1.38	<2	<10	70	<0.5	<2	2.04	<0.5	10	16	24	3.17
E858280		1.94	0.009	0.2	1.42	<2	<10	70	<0.5	<2	2.34	<0.5	8	17	22	3.15
E858281		1.30	<0.005	0.2	0.97	<2	<10	90	<0.5	<2	2.01	<0.5	7	11	21	2.40
E858282		1.12	<0.005	0.2	1.04	<2	<10	90	<0.5	<2	1.68	<0.5	7	11	19	2.45
E858283		2.20	<0.005	0.2	0.26	<2	<10	100	<0.5	<2	3.04	<0.5	3	6	6	1.20
E858284		2.18	<0.005	0.2	0.28	<2	<10	90	<0.5	<2	5.15	<0.5	6	4	10	1.87
E858285		2.24	0.005	0.2	0.33	2	<10	90	<0.5	<2	3.13	<0.5	5	6	11	1.50
E858286		2.34	<0.005	0.2	0.38	<2	<10	70	<0.5	<2	7.1	<0.5	8	5	14	2.19
E858287		2.16	<0.005	0.3	0.76	2	<10	50	<0.5	<2	7.5	<0.5	7	11	14	2.34
E858288		2.34	<0.005	0.3	0.88	<2	<10	70	<0.5	<2	6.9	<0.5	8	11	16	2.45
E858289		<0.02	0.006	0.3	0.85	<2	<10	70	<0.5	<2	6.42	<0.5	8	10	17	2.42
E858290		0.10	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.02	<0.5	<1	<1	<1	0.02
E858291		2.00	<0.005	<0.2	1.33	<2	<10	100	<0.5	<2	4.04	<0.5	9	15	20	2.86
E858292		2.41	0.005	0.3	0.46	<2	<10	70	<0.5	<2	13.5	<0.5	5	6	13	1.82
E858293		2.87	0.005	0.3	0.49	<2	<10	70	<0.5	<2	13.3	<0.5	6	7	13	1.74
E858294		2.35	0.006	0.3	0.83	2	<10	60	<0.5	<2	10.3	<0.5	7	9	15	2.03
E858295		2.09	<0.005	0.3	0.63	<2	<10	60	<0.5	<2	6.9	<0.5	6	8	15	2.00
E858296		2.34	0.005	0.4	0.56	<2	<10	60	<0.5	<2	11.7	<0.5	6	8	15	1.69
E858297		2.82	0.005	0.4	0.91	2	<10	80	<0.5	<2	10.4	<0.5	8	10	20	2.23
E858298		2.06	<0.005	0.4	0.42	<2	<10	70	<0.5	<2	20.2	<0.5	5	4	15	1.86
E858299		2.61	<0.005	0.4	0.26	3	<10	60	<0.5	<2	20.1	<0.5	4	2	10	1.44
E858300		2.27	<0.005	0.4	0.58	4	<10	120	<0.5	<2	12.4	<0.5	6	6	16	2.06
E858301		1.46	0.007	0.3	0.27	8	<10	180	<0.5	<2	19.9	<0.5	4	2	10	1.43
E858302		1.18	0.008	0.3	0.26	8	<10	180	<0.5	<2	20.9	<0.5	4	2	9	1.35
E858303		0.89	0.008	0.4	0.21	7	<10	150	<0.5	<2	22.4	<0.5	4	2	7	1.23
E858304		2.16	0.006	0.3	0.45	3	<10	90	<0.5	<2	16.5	<0.5	6	5	13	1.83
E858305		2.06	<0.005	0.2	1.24	3	<10	90	<0.5	<2	8.5	<0.5	8	14	17	2.70
E858306		2.02	<0.005	0.2	1.22	<2	<10	70	<0.5	<2	5.56	<0.5	8	15	22	2.80
E858307		1.34	<0.005	<0.2	1.75	4	<10	90	<0.5	<2	0.51	<0.5	12	21	27	3.43
E858308		2.38	0.009	0.4	0.77	2	<10	80	<0.5	<2	15.4	<0.5	7	8	18	2.20
E858309		<0.02	<0.005	0.5	0.70	<2	<10	70	<0.5	<2	15.5	<0.5	6	7	16	2.17
E858310		0.06	0.907	>100	0.51	4450	<10	30	<0.5	2	0.56	92.9	6	51	295	5.89
E858311		1.91	0.007	0.8	0.20	37	<10	70	<0.5	<2	22.3	<0.5	4	2	12	1.47
E858312		2.06	0.006	0.5	0.25	2	<10	70	<0.5	<2	20.7	<0.5	3	2	9	1.45
E858313		0.74	0.005	0.6	0.22	<2	<10	40	<0.5	<2	>25.0	<0.5	3	2	9	1.53
E858314		2.17	<0.005	0.5	0.20	<2	<10	60	<0.5	<2	18.2	<0.5	5	2	10	1.66
E858315		2.12	0.005	0.5	0.30	<2	<10	70	<0.5	<2	19.8	<0.5	5	2	13	1.71
E858316		2.13	0.005	0.5	0.27	3	<10	60	<0.5	<2	17.9	<0.5	5	3	16	1.87
E858317		2.37	<0.005	0.5	0.46	<2	<10	80	<0.5	<2	9.7	<0.5	8	4	19	2.63

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102790

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E858278		<10	<1	0.28	20	0.74	605	1	0.01	24	380	22	0.26	<2	2	208
E858279		<10	<1	0.27	20	0.57	349	1	0.01	21	420	30	0.26	<2	1	114
E858280		<10	<1	0.23	20	0.60	397	<1	0.02	18	380	20	0.16	<2	1	115
E858281		<10	<1	0.22	20	0.67	364	1	0.01	15	340	21	0.23	<2	1	72
E858282		<10	<1	0.23	20	0.69	341	1	0.01	14	310	16	0.17	<2	1	55
E858283		<10	<1	0.15	10	0.63	434	1	0.01	4	150	14	0.14	<2	1	109
E858284		<10	<1	0.21	10	1.13	635	1	0.01	7	210	14	0.27	<2	1	196
E858285		<10	<1	0.24	10	0.68	410	1	0.01	6	200	32	0.18	<2	1	120
E858286		<10	<1	0.22	10	0.81	544	1	0.02	13	200	24	0.62	<2	1	299
E858287		<10	<1	0.20	10	0.48	439	1	0.03	14	290	18	0.66	3	1	315
E858288		<10	<1	0.22	10	0.53	364	1	0.02	17	240	16	0.61	2	1	277
E858289		<10	<1	0.22	10	0.51	363	1	0.02	18	240	18	0.61	<2	1	275
E858290		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.01	<2	<1	2
E858291		<10	<1	0.26	20	0.82	351	<1	0.02	21	330	11	0.49	<2	1	151
E858292		<10	<1	0.18	<10	0.34	381	1	0.02	13	280	16	0.75	<2	2	562
E858293		<10	<1	0.17	<10	0.31	387	1	0.02	13	220	17	0.62	<2	1	548
E858294		<10	<1	0.20	10	0.50	554	1	0.02	14	220	14	0.42	<2	2	408
E858295		<10	<1	0.17	10	0.33	312	1	0.02	17	280	13	0.70	<2	1	251
E858296		<10	<1	0.16	10	0.32	426	1	0.03	16	220	14	0.49	<2	2	440
E858297		<10	<1	0.22	10	0.50	319	1	0.02	17	320	12	0.59	<2	2	414
E858298		<10	<1	0.15	10	0.48	357	1	0.02	12	470	15	0.9	<2	2	758
E858299		<10	<1	0.13	10	0.41	309	1	0.02	9	330	14	0.8	<2	2	765
E858300		<10	<1	0.17	10	0.66	372	1	0.02	14	220	11	0.89	<2	2	477
E858301		<10	<1	0.13	10	0.43	231	1	0.02	9	380	11	1.1	<2	2	765
E858302		<10	<1	0.12	10	0.40	226	1	0.02	9	350	12	1.0	<2	2	786
E858303		<10	<1	0.10	10	0.35	247	1	0.02	7	450	13	0.9	<2	2	655
E858304		<10	<1	0.14	10	0.40	370	1	0.03	13	280	17	1.0	<2	2	528
E858305		<10	<1	0.22	10	0.62	430	1	0.03	18	250	13	0.50	<2	2	300
E858306		<10	<1	0.23	10	0.60	431	1	0.03	20	200	15	0.50	<2	2	262
E858307		10	<1	0.26	20	0.83	163	<1	0.02	26	170	19	0.22	<2	1	28
E858308		<10	<1	0.20	<10	0.47	313	<1	0.02	15	290	17	0.83	<2	2	552
E858309		<10	<1	0.18	<10	0.46	296	<1	<0.01	16	280	15	0.91	<2	2	560
E858310		<10	1	0.31	10	0.10	284	2	0.02	4	660	4880	7.7	1690	1	132
E858311		<10	<1	0.11	<10	0.26	355	1	<0.01	8	290	22	0.8	<2	2	807
E858312		<10	<1	0.13	<10	0.35	480	1	<0.01	9	660	12	0.7	<2	2	762
E858313		<10	<1	0.09	10	0.34	742	<1	<0.01	9	1460	12	0.7	<2	2	908
E858314		<10	<1	0.11	10	0.34	294	1	<0.01	11	150	14	0.9	<2	2	664
E858315		<10	<1	0.13	<10	0.42	334	1	<0.01	11	450	13	0.8	<2	2	835
E858316		<10	<1	0.13	<10	0.41	433	<1	<0.01	12	700	14	0.9	<2	2	763
E858317		<10	<1	0.21	10	0.86	364	<1	<0.01	19	400	14	1.17	<2	2	427

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102790

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E858278		<20	<0.01	<10	<10	9	<10	73		
E858279		<20	<0.01	<10	<10	8	<10	65		
E858280		<20	<0.01	<10	<10	9	<10	73		
E858281		<20	<0.01	<10	<10	5	<10	46		
E858282		<20	<0.01	<10	<10	5	<10	48		
E858283		<20	<0.01	<10	<10	2	<10	18		
E858284		<20	<0.01	<10	<10	2	<10	28		
E858285		<20	<0.01	<10	<10	2	<10	80		
E858286		<20	<0.01	<10	<10	3	<10	33		
E858287		<20	<0.01	<10	<10	5	<10	51		
E858288		<20	<0.01	<10	<10	5	<10	43		
E858289		<20	<0.01	<10	<10	5	<10	44		
E858290		<20	<0.01	<10	<10	<1	<10	3		
E858291		20	<0.01	<10	<10	8	<10	64		
E858292		<20	<0.01	<10	<10	3	<10	29		
E858293		<20	<0.01	<10	<10	3	<10	33		
E858294		<20	<0.01	<10	<10	5	<10	44		
E858295		<20	<0.01	<10	<10	4	<10	41		
E858296		<20	<0.01	<10	<10	4	<10	37		
E858297		<20	<0.01	<10	<10	5	<10	48		
E858298		20	<0.01	<10	<10	3	<10	39		
E858299		20	<0.01	<10	<10	1	<10	22		
E858300		<20	<0.01	<10	<10	3	<10	46		
E858301		20	<0.01	<10	<10	1	<10	30		
E858302		20	<0.01	<10	<10	2	<10	28		
E858303		20	<0.01	<10	<10	1	<10	23		
E858304		20	<0.01	<10	<10	3	<10	116		
E858305		20	<0.01	<10	<10	8	<10	61		
E858306		<20	<0.01	<10	<10	8	<10	55		
E858307		20	<0.01	<10	<10	12	<10	76		
E858308		20	<0.01	<10	<10	5	<10	47		
E858309		<20	<0.01	<10	<10	5	<10	45		
E858310		<20	<0.01	<10	<10	6	10	>10000	1.275	147
E858311		<20	<0.01	<10	<10	2	<10	124		
E858312		<20	<0.01	<10	<10	2	<10	30		
E858313		20	<0.01	<10	<10	2	<10	22		
E858314		20	<0.01	<10	<10	2	<10	35		
E858315		20	<0.01	<10	<10	2	<10	35		
E858316		20	<0.01	<10	<10	2	<10	34		
E858317		20	<0.01	<10	<10	3	<10	47		

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102790

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E858318		2.24	0.005	0.2	0.55	<2	<10	70	<0.5	<2	4.10	<0.5	8	6	17	2.61
E858319		1.93	0.005	0.3	0.60	<2	<10	70	<0.5	<2	6.21	<0.5	8	8	16	2.41
E858320		2.04	0.006	0.3	0.37	<2	<10	40	<0.5	<2	5.13	<0.5	6	6	14	2.18
E858321		1.20	0.005	0.3	0.91	<2	<10	60	<0.5	<2	3.21	<0.5	8	10	16	2.73
E858322		1.07	<0.005	0.4	0.85	<2	<10	50	<0.5	<2	5.43	<0.5	7	9	17	2.26
E858323		2.49	<0.005	0.2	0.62	2	<10	60	<0.5	<2	3.64	<0.5	9	8	19	2.68
E858324		2.23	0.005	0.3	1.01	<2	<10	50	<0.5	<2	2.25	<0.5	10	9	26	3.21
E858325		2.51	0.005	<0.2	2.06	<2	<10	60	<0.5	<2	2.26	<0.5	14	19	31	4.40
E858326		2.30	0.006	0.2	1.12	<2	<10	50	<0.5	<2	2.23	<0.5	10	11	19	2.97
E858327		2.43	0.005	0.4	1.02	6	<10	60	<0.5	<2	2.81	<0.5	12	10	22	2.55
E858328		2.54	<0.005	0.2	0.78	3	<10	40	<0.5	<2	1.14	<0.5	8	9	14	2.06
E858329		<0.02	<0.005	<0.2	0.80	3	<10	40	<0.5	<2	1.13	<0.5	10	9	16	2.08
E858330		0.10	0.006	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.01
E858331		2.53	<0.005	0.3	0.23	4	<10	30	<0.5	<2	5.33	<0.5	4	5	4	1.41
E858332		2.59	0.006	0.4	0.19	5	<10	20	<0.5	<2	17.7	<0.5	3	2	5	1.28

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102790

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E858318		<10	<1	0.20	10	0.44	239	1	<0.01	20	170	24	1.37	<2	1	168
E858319		<10	<1	0.20	10	0.67	333	<1	0.01	16	210	18	0.97	<2	1	237
E858320		<10	<1	0.15	10	0.44	346	<1	<0.01	14	310	15	1.06	<2	1	256
E858321		<10	<1	0.24	10	0.58	517	<1	0.02	18	510	21	0.80	<2	1	150
E858322		<10	<1	0.19	10	0.46	449	1	0.01	16	470	21	0.58	<2	1	462
E858323		<10	<1	0.23	10	0.48	520	<1	0.01	19	380	18	1.04	<2	1	228
E858324		<10	<1	0.20	10	0.56	368	<1	0.01	24	470	20	1.17	<2	1	139
E858325		10	<1	0.22	10	1.04	546	<1	0.01	30	550	9	0.96	<2	2	129
E858326		<10	<1	0.19	10	0.69	925	<1	0.01	19	280	21	0.68	<2	1	121
E858327		<10	<1	0.23	10	0.68	672	<1	0.01	21	270	38	0.52	<2	1	146
E858328		<10	<1	0.15	10	0.53	413	<1	0.01	13	210	11	0.24	<2	1	43
E858329		<10	<1	0.16	10	0.52	406	<1	0.01	14	220	14	0.25	<2	1	45
E858330		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	<0.01	<2	<1	<1
E858331		<10	<1	0.12	10	0.96	792	<1	0.01	3	200	20	0.06	<2	1	247
E858332		<10	<1	0.11	10	0.69	1035	1	<0.01	4	410	11	<0.01	<2	1	702

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102790

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E858318		<20	<0.01	<10	<10	4	<10	62		
E858319		<20	<0.01	<10	<10	4	<10	49		
E858320		<20	<0.01	<10	<10	3	<10	44		
E858321		20	<0.01	<10	<10	6	<10	56		
E858322		<20	<0.01	<10	<10	5	<10	52		
E858323		<20	<0.01	<10	<10	3	<10	74		
E858324		<20	<0.01	<10	<10	6	<10	76		
E858325		<20	<0.01	<10	<10	11	<10	102		
E858326		<20	<0.01	<10	<10	6	<10	59		
E858327		20	<0.01	<10	<10	5	<10	51		
E858328		<20	<0.01	<10	<10	4	<10	47		
E858329		<20	<0.01	<10	<10	4	<10	48		
E858330		<20	<0.01	<10	<10	<1	<10	<2		
E858331		<20	<0.01	<10	<10	1	<10	23		
E858332		<20	<0.01	<10	<10	1	<10	20		

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

CERTIFICATE WH10102708

Project: ALN10-01

P.O. No.: ALN10_01_22

This report is for 180 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 27-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	WEI-21	Au-AA23	Au-GRA21	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu
	Units	kg	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.05	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1
E856727		2.05	<0.005		0.2	0.70	4	<10	90	<0.5	<2	7.3	<0.5	5	9	11
E856728		1.04	0.009		<0.2	0.46	27	<10	40	<0.5	<2	2.32	<0.5	3	9	6
E856729		<0.02	0.006		<0.2	0.42	30	<10	30	<0.5	<2	2.29	<0.5	3	9	10
E856730		0.07	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	1
E856731		2.29	0.006		0.2	0.77	37	<10	50	<0.5	<2	4.68	<0.5	5	10	10
E856732		1.75	<0.005		<0.2	1.04	23	<10	60	<0.5	2	5.53	<0.5	7	13	15
E856733		1.35	<0.005		<0.2	0.52	48	<10	50	<0.5	<2	2.44	<0.5	4	9	6
E856734		1.62	<0.005		0.4	0.47	31	<10	30	<0.5	<2	11.2	<0.5	4	8	8
E856735		1.13	<0.005		<0.2	1.21	30	<10	80	<0.5	2	4.32	<0.5	9	14	14
E856736		1.58	0.029		<0.2	1.01	135	<10	90	<0.5	<2	0.75	<0.5	11	13	18
E856737		1.16	<0.005		<0.2	0.19	4	<10	130	<0.5	<2	0.02	<0.5	1	12	4
E856738		3.56	<0.005		<0.2	0.35	9	<10	220	<0.5	2	3.55	<0.5	12	6	33
E856739		3.20	0.005		0.2	0.30	8	<10	80	<0.5	<2	2.16	<0.5	3	10	27
E856740		3.14	0.005		0.2	0.33	8	<10	60	<0.5	<2	1.04	0.5	2	13	25
E856741		1.38	0.005		0.4	0.16	15	<10	40	<0.5	<2	0.07	<0.5	1	11	14
E856742		1.42	<0.005		0.4	0.18	14	<10	50	<0.5	<2	0.04	<0.5	1	11	13
E856743		3.18	<0.005		0.4	0.89	4	<10	70	<0.5	<2	0.16	6.9	11	15	49
E856744		4.08	<0.005		0.2	1.43	<2	<10	60	<0.5	<2	0.23	3.3	18	17	34
E856745		3.61	<0.005		0.3	1.62	<2	<10	60	<0.5	<2	0.42	2.3	20	19	41
E856746		4.04	<0.005		<0.2	1.35	<2	<10	60	<0.5	<2	0.36	2.7	16	17	40
E856747		4.11	<0.005		0.2	1.72	2	<10	60	0.5	<2	0.19	0.9	18	21	44
E856748		3.66	<0.005		<0.2	1.58	2	<10	60	<0.5	<2	0.26	0.7	16	17	32
E856749		<0.02	<0.005		<0.2	1.66	<2	<10	60	<0.5	2	0.26	0.8	17	19	34
E856750		0.09	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	1
E856751		3.61	<0.005		<0.2	1.56	2	<10	60	<0.5	<2	0.48	0.9	15	18	30
E856752		3.62	<0.005		<0.2	1.14	<2	<10	40	<0.5	<2	0.42	2.3	12	14	18
E856753		4.66	<0.005		0.2	1.39	2	<10	60	<0.5	<2	0.38	0.8	13	17	30
E856754		3.52	<0.005		0.3	1.55	<2	<10	50	<0.5	<2	0.18	0.8	17	18	38
E856755		3.91	<0.005		<0.2	1.30	<2	<10	60	<0.5	<2	0.70	<0.5	14	14	38
E856756		4.19	<0.005		0.3	0.89	3	<10	50	<0.5	<2	1.47	<0.5	10	10	27
E856757		4.64	<0.005		<0.2	0.97	15	<10	50	<0.5	<2	0.99	<0.5	10	13	22
E856758		3.41	0.007		0.3	0.55	63	<10	40	<0.5	<2	1.08	<0.5	7	12	11
E856759		4.07	<0.005		0.4	0.75	13	<10	70	<0.5	<2	1.09	<0.5	6	9	22
E856760		4.97	<0.005		<0.2	0.67	11	<10	40	<0.5	<2	1.33	0.5	9	11	27
E856761		4.32	<0.005		0.2	0.83	7	<10	60	<0.5	2	0.64	<0.5	11	10	29
E856762		4.35	<0.005		<0.2	0.23	28	<10	130	<0.5	<2	0.93	<0.5	4	8	9
E856763		4.22	<0.005		<0.2	0.23	4	<10	60	<0.5	<2	0.68	<0.5	2	8	4
E856764		4.39	0.006		<0.2	0.25	5	<10	50	<0.5	<2	0.77	<0.5	2	10	6
E856765		3.76	<0.005		0.2	0.37	18	<10	170	<0.5	<2	0.59	<0.5	5	8	14
E856766		3.03	0.022		0.2	0.70	322	<10	110	<0.5	<2	0.47	<0.5	7	7	15

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856727		1.97	<10	<1	0.24	20	0.33	834	<1	0.02	12	230	14	<0.01	<2	1
E856728		1.32	<10	<1	0.14	10	0.16	866	<1	0.03	7	110	32	<0.01	14	1
E856729		1.20	<10	1	0.12	20	0.16	815	1	0.03	11	110	36	0.03	15	1
E856730		0.01	<10	<1	<0.01	<10	<0.01	<5	<1	0.01	1	10	2	0.01	<2	<1
E856731		1.93	<10	<1	0.17	20	0.32	783	<1	0.02	15	140	34	0.03	17	2
E856732		2.44	<10	1	0.16	10	0.59	688	<1	0.02	17	370	23	0.05	5	2
E856733		1.46	<10	<1	0.13	10	0.23	288	<1	0.02	9	120	19	0.01	3	1
E856734		1.45	<10	<1	0.11	10	0.32	851	<1	0.02	9	210	22	0.07	<2	1
E856735		2.69	<10	<1	0.23	20	0.50	497	<1	0.02	19	260	23	0.05	<2	1
E856736		2.39	<10	1	0.19	20	0.40	372	<1	0.02	28	210	19	0.02	6	1
E856737		0.59	<10	<1	0.09	10	0.04	51	1	0.01	2	30	6	0.07	<2	<1
E856738		2.55	<10	<1	0.15	10	1.84	932	1	0.02	26	330	29	0.18	2	1
E856739		1.82	<10	1	0.12	10	1.11	439	8	0.02	15	390	12	0.10	2	1
E856740		1.94	<10	<1	0.12	10	0.55	259	23	0.02	17	690	17	0.13	<2	1
E856741		1.44	<10	<1	0.10	10	0.03	58	33	0.01	11	380	12	0.14	<2	<1
E856742		1.41	<10	1	0.12	10	0.03	63	31	0.01	11	350	13	0.12	<2	<1
E856743		2.99	<10	<1	0.15	10	0.42	154	9	0.03	17	260	10	0.64	<2	1
E856744		3.47	<10	<1	0.17	10	0.62	242	<1	0.04	30	200	9	0.61	<2	1
E856745		4.02	<10	1	0.19	10	0.71	333	1	0.03	40	180	11	0.72	<2	1
E856746		3.60	<10	<1	0.20	10	0.58	396	1	0.03	32	420	25	0.96	<2	1
E856747		4.30	<10	<1	0.19	10	0.70	460	<1	0.03	37	280	17	0.60	<2	1
E856748		3.83	<10	<1	0.19	10	0.64	366	<1	0.03	32	230	18	0.47	<2	1
E856749		4.05	<10	<1	0.20	10	0.67	379	<1	0.03	33	240	23	0.50	<2	1
E856750		0.02	<10	<1	<0.01	<10	<0.01	<5	<1	0.01	<1	10	<2	0.02	<2	<1
E856751		3.76	<10	<1	0.19	10	0.69	596	<1	0.03	32	380	22	0.30	<2	1
E856752		2.97	<10	1	0.14	10	0.54	540	1	0.02	36	170	17	0.29	<2	1
E856753		3.51	<10	1	0.19	10	0.63	486	<1	0.03	27	220	26	0.39	<2	1
E856754		3.87	<10	<1	0.18	10	0.66	352	1	0.03	34	320	21	0.63	<2	1
E856755		3.60	<10	1	0.21	10	0.66	458	<1	0.03	32	330	18	0.79	<2	1
E856756		3.05	<10	1	0.23	10	0.64	425	<1	0.03	24	270	15	0.19	<2	1
E856757		2.85	<10	<1	0.23	10	0.55	428	<1	0.02	20	370	16	0.12	<2	1
E856758		2.08	<10	<1	0.18	10	0.44	399	<1	0.02	13	130	12	0.08	<2	1
E856759		2.34	<10	1	0.20	10	0.58	400	<1	0.02	14	100	10	0.06	<2	1
E856760		2.89	<10	<1	0.19	10	0.49	541	1	0.02	23	390	18	0.53	3	1
E856761		2.82	<10	<1	0.22	10	0.54	408	<1	0.02	23	310	33	0.62	<2	1
E856762		1.32	<10	<1	0.17	10	0.33	339	<1	0.01	6	120	13	0.15	<2	1
E856763		1.15	<10	<1	0.17	10	0.25	360	<1	0.02	3	80	9	0.06	<2	<1
E856764		1.24	<10	<1	0.18	10	0.28	366	<1	0.01	4	90	10	0.07	<2	<1
E856765		1.54	<10	<1	0.21	10	0.26	343	1	0.02	11	230	18	0.25	2	1
E856766		2.41	<10	<1	0.23	10	0.29	337	1	0.01	12	200	18	0.31	7	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856727		344	<20	<0.01	<10	<10	4	<10	33			
E856728		72	<20	<0.01	<10	<10	3	<10	39			
E856729		76	<20	<0.01	<10	<10	3	<10	41			
E856730		1	<20	<0.01	<10	<10	<1	<10	2			
E856731		211	<20	<0.01	<10	<10	5	<10	48			
E856732		212	<20	0.02	<10	<10	13	<10	45			
E856733		111	<20	<0.01	<10	<10	4	<10	32			
E856734		431	<20	<0.01	<10	<10	3	<10	33			
E856735		153	<20	<0.01	<10	<10	7	<10	65			
E856736		53	<20	<0.01	<10	<10	7	<10	75			
E856737		4	<20	<0.01	<10	<10	2	<10	5			
E856738		110	<20	<0.01	<10	<10	3	<10	58			
E856739		72	<20	<0.01	<10	<10	26	<10	78			
E856740		50	<20	<0.01	<10	<10	46	<10	79			
E856741		19	<20	<0.01	<10	<10	40	<10	58			
E856742		22	<20	<0.01	<10	<10	40	<10	59			
E856743		13	<20	<0.01	<10	<10	13	<10	66			
E856744		15	<20	<0.01	<10	<10	10	<10	75			
E856745		22	<20	<0.01	<10	<10	11	<10	83			
E856746		23	<20	<0.01	<10	<10	9	<10	71			
E856747		16	<20	<0.01	<10	<10	10	<10	80			
E856748		16	<20	<0.01	<10	<10	9	<10	75			
E856749		16	<20	<0.01	<10	<10	10	<10	78			
E856750		1	<20	<0.01	<10	<10	<1	<10	3			
E856751		28	<20	<0.01	<10	<10	9	<10	80			
E856752		23	<20	<0.01	<10	<10	8	<10	68			
E856753		22	<20	<0.01	<10	<10	10	<10	72			
E856754		14	<20	<0.01	<10	<10	10	<10	77			
E856755		33	<20	<0.01	<10	<10	8	<10	73			
E856756		70	<20	<0.01	<10	<10	6	<10	65			
E856757		52	<20	<0.01	<10	<10	8	<10	52			
E856758		57	<20	<0.01	<10	<10	4	<10	40			
E856759		54	<20	<0.01	<10	<10	6	<10	33			
E856760		70	<20	<0.01	<10	<10	5	<10	61			
E856761		44	<20	<0.01	<10	<10	4	<10	59			
E856762		96	<20	<0.01	<10	<10	1	<10	25			
E856763		83	<20	<0.01	<10	<10	1	<10	23			
E856764		95	<20	<0.01	<10	<10	1	<10	12			
E856765		79	<20	<0.01	<10	<10	3	<10	30			
E856766		44	<20	<0.01	<10	<10	3	<10	44			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	WEI-21	Au-AA23	Au-GRA21	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu
	Units	kg	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.05	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1
E856767		3.66	0.015		0.3	0.49	863	<10	70	<0.5	<2	1.75	<0.5	10	7	35
E856768		3.68	0.015		0.4	1.15	712	<10	60	<0.5	<2	0.57	<0.5	12	16	23
E856769		<0.02	0.016		0.3	1.18	668	<10	60	<0.5	<2	0.58	<0.5	12	15	24
E856770		0.08	0.846		>100	0.52	4530	<10	40	<0.5	4	0.55	100.5	7	53	297
E856771		3.70	<0.005		0.2	0.92	10	<10	40	<0.5	<2	0.80	<0.5	6	15	10
E856772		3.73	<0.005		<0.2	1.12	10	<10	40	<0.5	<2	0.76	<0.5	11	33	31
E856773		3.82	<0.005		0.2	0.95	5	<10	50	<0.5	<2	0.65	<0.5	8	17	18
E856774		3.78	<0.005		<0.2	1.10	<2	<10	60	<0.5	<2	0.71	<0.5	11	14	26
E856775		4.95	<0.005		0.2	1.17	2	<10	60	<0.5	<2	3.54	<0.5	12	15	38
E856776		3.39	<0.005		0.4	0.57	7	<10	40	<0.5	<2	8.1	0.5	10	6	33
E856777		3.24	<0.005		0.4	0.38	20	<10	70	<0.5	<2	6.82	0.5	9	6	66
E856778		4.03	<0.005		0.4	0.33	13	<10	70	<0.5	<2	6.38	<0.5	9	5	48
E856779		3.00	<0.005		0.3	0.37	12	<10	70	<0.5	<2	6.9	<0.5	9	5	49
E856780		3.89	<0.005		0.2	0.23	4	<10	50	<0.5	<2	1.07	0.7	4	6	12
E856781		3.02	<0.005		<0.2	0.35	4	<10	70	<0.5	<2	1.49	<0.5	5	7	17
E856782		3.89	<0.005		0.2	0.58	20	<10	80	<0.5	<2	0.43	<0.5	7	7	19
E856783		2.48	<0.005		<0.2	1.51	23	<10	80	<0.5	<2	0.21	<0.5	13	19	26
E856784		2.05	0.009		<0.2	0.76	86	<10	60	<0.5	<2	0.78	<0.5	8	12	14
E856785		4.09	<0.005		<0.2	0.51	39	<10	40	<0.5	<2	0.59	<0.5	4	12	7
E856786		3.79	0.056		0.2	0.37	500	<10	50	<0.5	<2	3.10	<0.5	3	8	5
E856787		3.82	0.174		0.9	0.34	2470	<10	100	<0.5	<2	9.9	<0.5	4	6	15
E856788		3.30	0.181		0.4	0.40	1350	<10	60	<0.5	<2	1.17	<0.5	10	8	19
E856789		<0.02	0.174		0.4	0.38	1345	<10	60	<0.5	<2	1.17	<0.5	7	7	20
E856790		0.12	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1
E856791		4.84	0.017		<0.2	0.50	139	<10	50	<0.5	<2	0.82	<0.5	7	11	13
E856792		4.05	<0.005		0.2	0.48	13	<10	40	<0.5	<2	0.57	<0.5	5	10	12
E856793		4.00	<0.005		<0.2	0.67	3	<10	40	<0.5	<2	0.62	<0.5	5	12	9
E856794		3.95	<0.005		0.2	1.08	16	<10	70	<0.5	<2	1.62	<0.5	12	14	30
E856795		3.04	<0.005		0.2	0.61	9	<10	100	<0.5	<2	4.12	<0.5	8	7	14
E856796		3.63	0.006		0.2	1.24	38	<10	70	<0.5	<2	3.05	<0.5	11	13	26
E856797		3.63	<0.005		0.2	1.32	2	<10	80	<0.5	<2	2.56	<0.5	11	15	22
E856798		3.87	<0.005		0.3	1.18	8	<10	140	<0.5	<2	1.80	<0.5	10	14	24
E856799		2.28	<0.005		<0.2	1.26	6	<10	240	<0.5	<2	0.60	<0.5	11	13	33
E856800		3.99	<0.005		<0.2	1.99	3	<10	80	<0.5	<2	0.81	<0.5	15	25	34
E856801		2.19	<0.005		<0.2	1.66	6	<10	60	<0.5	<2	0.76	<0.5	14	19	36
E856802		1.85	<0.005		<0.2	1.78	2	<10	70	<0.5	<2	0.65	<0.5	13	18	32
E856803		4.87	<0.005		<0.2	1.51	10	<10	60	<0.5	<2	0.60	<0.5	12	15	24
E856804		4.44	<0.005		0.2	1.54	28	<10	60	<0.5	<2	0.22	<0.5	13	15	29
E856805		3.62	<0.005		<0.2	1.59	18	<10	90	<0.5	<2	0.79	<0.5	12	15	21
E856806		3.49	<0.005		<0.2	2.09	15	<10	80	<0.5	<2	1.48	<0.5	16	52	29

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856767		2.40	<10	<1	0.23	10	0.76	387	2	0.01	18	320	18	0.65	18	1
E856768		2.92	<10	1	0.21	10	0.54	513	1	0.02	25	170	18	0.29	17	1
E856769		3.00	<10	<1	0.21	10	0.56	524	1	0.02	26	180	17	0.28	18	1
E856770		6.18	<10	1	0.32	10	0.10	294	2	0.04	5	660	5010	7.5	1805	1
E856771		2.24	<10	<1	0.18	20	0.40	501	<1	0.04	11	150	15	0.04	7	1
E856772		2.73	<10	<1	0.17	10	0.53	490	1	0.02	25	310	13	0.12	4	1
E856773		2.55	<10	<1	0.18	10	0.47	468	1	0.02	18	170	28	0.25	4	1
E856774		2.99	<10	<1	0.24	10	0.59	410	1	0.02	24	570	12	0.58	<2	1
E856775		3.50	<10	<1	0.24	10	1.81	783	1	0.02	25	320	19	0.69	24	2
E856776		3.13	<10	<1	0.19	10	3.90	1155	5	0.02	18	830	37	0.49	9	2
E856777		2.88	<10	<1	0.25	10	3.49	905	4	0.02	19	620	20	0.53	10	3
E856778		2.35	<10	<1	0.19	10	3.20	808	2	0.01	14	760	17	0.25	8	2
E856779		2.51	<10	<1	0.24	10	3.19	836	1	0.01	14	690	14	0.22	11	3
E856780		1.06	<10	<1	0.13	10	0.37	232	1	0.01	5	150	12	0.23	14	<1
E856781		1.49	<10	<1	0.20	10	0.38	300	1	0.01	8	280	12	0.21	28	1
E856782		2.17	<10	<1	0.23	10	0.23	274	1	0.01	11	260	25	0.42	15	1
E856783		3.32	<10	<1	0.23	20	0.59	312	<1	0.02	28	210	12	0.14	11	1
E856784		2.17	<10	<1	0.16	10	0.34	480	1	0.02	15	850	18	0.11	22	1
E856785		1.46	<10	<1	0.12	10	0.21	310	1	0.03	8	220	10	0.07	12	1
E856786		1.47	<10	1	0.10	10	0.23	532	1	0.02	7	100	13	0.22	15	1
E856787		1.70	<10	<1	0.15	<10	0.32	725	1	0.02	10	150	31	0.88	517	1
E856788		2.82	<10	<1	0.20	10	0.51	547	1	0.03	19	110	19	0.88	26	1
E856789		2.73	<10	<1	0.19	10	0.51	538	<1	0.03	19	100	16	0.84	27	1
E856790		0.02	<10	<1	<0.01	<10	<0.01	<5	<1	0.01	<1	10	<2	0.01	<2	<1
E856791		2.30	<10	<1	0.17	10	0.40	439	1	0.03	16	190	15	0.21	19	1
E856792		1.88	<10	<1	0.14	10	0.31	368	1	0.02	13	140	14	0.09	15	1
E856793		1.92	<10	<1	0.15	10	0.36	433	1	0.02	11	100	14	0.12	3	1
E856794		3.25	<10	<1	0.17	10	0.65	771	1	0.03	27	280	16	0.27	17	2
E856795		2.27	<10	<1	0.22	10	0.35	634	1	0.03	16	140	21	0.80	9	2
E856796		3.70	<10	<1	0.21	10	0.71	534	1	0.03	26	650	31	0.89	26	2
E856797		3.63	<10	<1	0.24	10	0.67	405	1	0.03	24	450	19	1.00	12	2
E856798		3.06	<10	<1	0.20	10	0.59	293	1	0.02	23	270	24	0.65	9	1
E856799		3.20	<10	<1	0.23	20	0.59	311	1	0.02	27	300	9	0.15	8	1
E856800		4.09	<10	1	0.18	20	0.86	504	<1	0.03	30	210	10	0.18	4	2
E856801		3.65	10	<1	0.21	20	0.80	629	1	0.03	30	540	14	0.12	4	2
E856802		3.70	<10	<1	0.23	20	0.80	539	1	0.03	29	500	16	0.11	6	2
E856803		3.47	<10	<1	0.23	20	0.70	673	1	0.03	23	260	28	0.11	15	1
E856804		3.59	<10	<1	0.24	20	0.59	1220	1	0.02	25	380	26	0.05	9	1
E856805		3.36	10	<1	0.29	30	0.65	520	1	0.03	21	420	19	0.14	8	2
E856806		4.06	10	<1	0.26	20	1.11	806	1	0.02	42	400	17	0.10	11	3

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856767		89	<20	<0.01	<10	<10	4	<10	45			
E856768		28	<20	<0.01	<10	<10	7	<10	79			
E856769		29	<20	<0.01	<10	<10	7	<10	79			
E856770		134	<20	<0.01	<10	<10	6	<10	>10000		1.300	145
E856771		55	<20	<0.01	<10	<10	6	<10	58			
E856772		35	<20	0.01	<10	<10	11	<10	52			
E856773		31	<20	<0.01	<10	<10	6	<10	46			
E856774		31	<20	<0.01	<10	<10	6	<10	51			
E856775		137	<20	<0.01	<10	<10	8	<10	59			
E856776		238	<20	<0.01	<10	<10	6	<10	61			
E856777		218	<20	<0.01	<10	<10	9	<10	61			
E856778		227	<20	<0.01	<10	<10	5	<10	45			
E856779		266	<20	<0.01	<10	<10	6	<10	44			
E856780		43	<20	<0.01	<10	<10	2	<10	150			
E856781		49	<20	<0.01	<10	<10	4	<10	43			
E856782		24	<20	<0.01	<10	<10	3	<10	48			
E856783		14	<20	<0.01	<10	<10	8	<10	76			
E856784		34	<20	<0.01	<10	<10	5	<10	50			
E856785		25	<20	<0.01	<10	<10	3	<10	23			
E856786		88	<20	<0.01	<10	<10	2	<10	37			
E856787		295	<20	<0.01	<10	<10	2	<10	98			
E856788		81	<20	<0.01	<10	<10	3	<10	56			
E856789		80	<20	<0.01	<10	<10	3	<10	55			
E856790		1	<20	<0.01	<10	<10	<1	<10	4			
E856791		46	<20	<0.01	<10	<10	4	<10	40			
E856792		32	<20	<0.01	<10	<10	3	<10	32			
E856793		30	<20	<0.01	<10	<10	4	<10	30			
E856794		86	<20	<0.01	<10	<10	7	<10	60			
E856795		196	<20	<0.01	<10	<10	4	<10	38			
E856796		139	20	<0.01	<10	<10	8	<10	79			
E856797		150	20	<0.01	<10	<10	8	<10	68			
E856798		124	<20	<0.01	<10	<10	7	<10	65			
E856799		36	<20	<0.01	<10	<10	8	<10	69			
E856800		33	<20	<0.01	<10	<10	15	<10	103			
E856801		29	<20	<0.01	<10	<10	11	<10	81			
E856802		26	<20	0.01	<10	<10	12	<10	82			
E856803		27	<20	<0.01	<10	<10	9	<10	84			
E856804		13	<20	<0.01	<10	<10	10	<10	70			
E856805		44	<20	0.01	<10	<10	9	<10	66			
E856806		86	<20	0.01	<10	<10	20	<10	73			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856807		3.50	<0.005		<0.2	1.06	14	<10	60	<0.5	<2	6.9	<0.5	10	10	15
E856808		3.95	<0.005		<0.2	1.26	19	<10	70	<0.5	<2	2.30	<0.5	12	13	22
E856809		<0.02	<0.005		0.2	1.29	10	<10	70	<0.5	<2	2.13	<0.5	12	13	22
E856810		0.08	1.600	1.33	>100	0.36	4360	<10	30	<0.5	6	0.79	508	6	51	844
E856811		3.07	0.010		0.3	0.79	23	<10	60	<0.5	<2	2.35	<0.5	12	12	34
E856812		3.54	0.005		<0.2	0.73	20	<10	80	<0.5	<2	1.33	<0.5	18	9	45
E856813		3.76	<0.005		0.2	0.57	11	<10	60	<0.5	<2	2.49	<0.5	10	8	24
E856814		4.71	<0.005		<0.2	1.10	8	<10	60	<0.5	<2	0.67	<0.5	11	13	18
E856815		4.14	<0.005		<0.2	1.11	4	<10	60	<0.5	<2	4.36	<0.5	10	10	18
E856816		2.92	<0.005		<0.2	0.83	22	<10	90	<0.5	<2	5.66	<0.5	15	11	28
E856817		2.37	<0.005		0.2	1.44	3	<10	80	<0.5	<2	0.37	<0.5	12	18	34
E856818		4.18	<0.005		<0.2	1.37	4	<10	70	<0.5	<2	0.58	<0.5	17	15	45
E856819		3.61	<0.005		<0.2	1.58	7	<10	90	<0.5	<2	1.10	<0.5	14	16	29
E856820		3.82	0.005		0.2	1.41	5	<10	70	<0.5	<2	6.24	<0.5	12	27	23
E856821		2.08	<0.005		<0.2	1.21	<2	<10	70	<0.5	<2	3.86	<0.5	9	12	16
E856822		2.28	<0.005		<0.2	1.29	<2	<10	70	<0.5	<2	3.55	<0.5	11	13	20
E856823		4.61	<0.005		<0.2	1.39	3	<10	90	<0.5	<2	1.84	<0.5	12	15	26
E856824		3.84	<0.005		<0.2	1.59	7	<10	80	<0.5	<2	2.13	<0.5	16	15	31
E856825		4.05	<0.005		<0.2	1.55	2	<10	80	<0.5	<2	1.76	<0.5	13	18	33
E856826		3.98	<0.005		<0.2	1.37	6	<10	70	<0.5	<2	2.57	<0.5	11	18	19
E856827		4.51	<0.005		<0.2	1.72	2	<10	80	<0.5	<2	1.65	<0.5	14	18	30
E856828		3.58	<0.005		<0.2	1.53	<2	<10	70	<0.5	<2	1.61	<0.5	14	18	31
E856829		<0.02	<0.005		<0.2	1.63	2	<10	70	<0.5	<2	1.49	<0.5	15	19	34
E856830		0.06	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	1	<1	<1
E856831		3.01	<0.005		<0.2	1.38	14	<10	70	<0.5	<2	0.70	<0.5	13	17	23
E856832		4.16	<0.005		<0.2	1.62	6	<10	70	<0.5	<2	1.59	<0.5	13	19	70
E856833		4.90	<0.005		<0.2	1.97	7	<10	110	<0.5	<2	0.88	<0.5	15	19	28
E856834		3.47	<0.005		<0.2	1.20	8	<10	70	<0.5	<2	2.63	<0.5	10	12	20
E856835		5.33	<0.005		<0.2	1.56	8	<10	90	<0.5	<2	5.07	<0.5	13	14	29
E856836		4.05	<0.005		<0.2	1.35	9	<10	80	<0.5	<2	1.80	<0.5	18	13	32
E856837		3.94	<0.005		<0.2	1.12	9	<10	90	<0.5	<2	2.37	<0.5	13	15	50
E856838		3.58	<0.005		<0.2	1.28	3	<10	100	<0.5	<2	3.64	0.6	11	17	48
E856839		3.90	0.005		<0.2	3.05	15	<10	80	<0.5	2	2.96	<0.5	22	38	42
E856840		3.87	0.008		<0.2	1.68	31	<10	70	<0.5	<2	0.90	<0.5	12	22	33
E856841		2.22	0.006		0.2	1.56	32	<10	60	<0.5	2	0.51	<0.5	14	16	33
E856842		2.59	<0.005		<0.2	1.58	24	<10	60	<0.5	<2	0.91	<0.5	12	19	32
E856843		3.83	<0.005		<0.2	1.61	10	<10	60	<0.5	<2	0.58	<0.5	13	20	30
E856844		4.50	<0.005		<0.2	1.03	19	<10	70	<0.5	<2	1.75	<0.5	9	13	19
E856845		4.72	<0.005		<0.2	0.98	13	<10	80	<0.5	<2	0.85	<0.5	10	13	17
E856846		4.62	0.024		<0.2	0.26	271	<10	60	<0.5	<2	1.30	<0.5	3	10	5

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856807		2.58	<10	1	0.22	20	0.61	1080	1	0.02	15	300	15	0.07	10	2
E856808		3.30	<10	<1	0.23	20	0.65	966	<1	0.02	23	350	9	0.12	24	2
E856809		3.34	<10	<1	0.23	20	0.67	948	1	0.02	23	350	7	0.12	21	2
E856810		6.87	<10	3	0.25	10	0.26	367	1	0.03	3	530	>10000	9.4	2520	1
E856811		3.32	<10	<1	0.19	10	1.16	968	3	0.02	29	690	40	0.63	54	2
E856812		3.35	<10	<1	0.22	10	0.69	525	1	0.02	33	340	17	0.69	46	2
E856813		2.75	<10	<1	0.20	10	0.63	710	1	0.02	18	230	20	0.20	26	1
E856814		2.87	<10	<1	0.22	20	0.65	465	1	0.02	19	250	19	0.08	11	1
E856815		2.68	<10	<1	0.23	20	0.56	643	1	0.02	18	290	12	0.14	10	1
E856816		3.21	<10	1	0.20	10	1.12	1030	1	0.02	27	450	12	0.32	27	2
E856817		3.49	<10	<1	0.23	20	0.70	399	1	0.02	26	240	8	0.46	6	1
E856818		3.43	<10	<1	0.26	20	0.66	581	1	0.02	30	270	25	0.56	9	1
E856819		3.41	<10	<1	0.28	20	0.67	554	1	0.02	24	410	5	0.18	4	1
E856820		2.96	<10	<1	0.25	10	0.70	895	1	0.03	26	360	18	0.18	4	2
E856821		2.54	<10	<1	0.24	20	0.53	739	1	0.03	16	270	18	0.13	3	2
E856822		2.68	<10	1	0.25	20	0.56	678	1	0.03	18	280	13	0.16	5	2
E856823		3.02	<10	<1	0.29	20	0.60	555	1	0.03	21	310	20	0.26	4	1
E856824		3.27	<10	<1	0.28	20	0.68	594	1	0.02	27	490	8	0.21	4	1
E856825		3.49	<10	<1	0.25	10	0.84	892	1	0.02	23	490	23	0.45	2	2
E856826		2.84	<10	<1	0.22	20	0.65	1240	1	0.03	19	300	19	0.11	<2	2
E856827		3.50	<10	1	0.27	20	0.73	732	1	0.03	25	350	44	0.19	2	2
E856828		3.49	<10	<1	0.24	10	0.75	827	1	0.02	25	250	12	0.59	2	2
E856829		3.69	<10	1	0.24	10	0.79	794	1	0.02	28	290	11	0.57	7	2
E856830		0.02	<10	<1	<0.01	<10	<0.01	<5	<1	0.01	<1	10	<2	0.01	<2	<1
E856831		3.00	<10	<1	0.25	20	0.60	356	<1	0.02	24	220	14	0.27	8	1
E856832		3.30	10	<1	0.26	20	0.77	1020	<1	0.02	25	240	26	0.16	3	1
E856833		4.57	10	<1	0.31	20	0.99	472	<1	0.02	28	270	4	0.16	5	2
E856834		2.98	<10	<1	0.23	20	0.72	808	<1	0.03	15	250	18	0.13	4	2
E856835		3.14	<10	<1	0.31	20	0.73	750	<1	0.02	21	380	6	0.14	2	2
E856836		2.87	<10	1	0.27	20	0.65	450	1	0.02	25	270	27	0.18	<2	1
E856837		2.46	<10	<1	0.26	10	1.16	561	3	0.02	31	860	17	0.56	<2	1
E856838		2.87	<10	<1	0.24	10	1.02	674	2	0.02	29	1080	13	0.61	<2	2
E856839		5.65	10	1	0.15	10	2.22	895	<1	0.03	45	1230	6	0.54	9	7
E856840		3.52	<10	<1	0.26	20	0.81	497	<1	0.02	29	270	15	0.18	6	2
E856841		3.55	<10	<1	0.25	20	0.75	452	<1	0.02	29	260	22	0.24	9	1
E856842		3.51	<10	<1	0.26	20	0.77	509	<1	0.02	28	350	15	0.10	8	1
E856843		3.40	<10	1	0.26	30	0.72	454	<1	0.02	30	290	14	0.02	2	1
E856844		2.69	<10	<1	0.26	20	0.56	600	<1	0.02	19	260	17	0.18	7	1
E856845		2.59	<10	<1	0.29	20	0.51	410	<1	0.02	18	220	13	0.10	4	1
E856846		1.11	<10	<1	0.19	20	0.23	370	<1	0.02	6	220	19	0.11	10	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856807		313	<20	<0.01	<10	<10	6	<10	45			
E856808		108	<20	<0.01	<10	<10	8	<10	66			
E856809		101	<20	<0.01	<10	<10	8	<10	69			
E856810		108	<20	<0.01	<10	<10	5	20	>10000	1.960	3.78	332
E856811		98	<20	<0.01	<10	<10	9	<10	65			
E856812		71	<20	<0.01	<10	<10	7	<10	75			
E856813		131	<20	<0.01	<10	<10	5	<10	60			
E856814		42	<20	<0.01	<10	<10	8	<10	65			
E856815		222	<20	<0.01	<10	<10	6	<10	58			
E856816		353	<20	<0.01	<10	<10	9	<10	51			
E856817		22	<20	<0.01	<10	<10	10	<10	59			
E856818		26	<20	0.01	<10	<10	8	<10	66			
E856819		48	20	0.01	<10	<10	9	<10	67			
E856820		330	<20	0.01	<10	<10	12	<10	54			
E856821		194	<20	0.01	<10	<10	7	<10	53			
E856822		187	<20	0.01	<10	<10	8	<10	57			
E856823		94	<20	0.01	<10	<10	8	<10	60			
E856824		112	<20	0.01	<10	<10	9	<10	65			
E856825		92	<20	0.01	<10	<10	11	<10	60			
E856826		131	<20	0.01	<10	<10	10	<10	59			
E856827		88	<20	0.01	<10	<10	11	<10	77			
E856828		92	<20	0.01	<10	<10	11	<10	73			
E856829		86	<20	0.01	<10	<10	11	<10	78			
E856830		1	<20	<0.01	<10	<10	<1	<10	2			
E856831		40	<20	0.01	<10	<10	10	<10	65			
E856832		83	<20	0.01	<10	<10	10	<10	73			
E856833		53	<20	0.01	<10	<10	12	<10	95			
E856834		147	<20	<0.01	<10	<10	8	<10	52			
E856835		265	<20	0.01	<10	<10	9	<10	55			
E856836		104	<20	0.01	<10	<10	8	<10	90			
E856837		96	<20	<0.01	<10	<10	15	<10	99			
E856838		242	<20	<0.01	<10	<10	16	<10	98			
E856839		247	<20	0.01	<10	<10	51	<10	109			
E856840		63	<20	<0.01	<10	<10	14	<10	70			
E856841		38	<20	<0.01	<10	<10	10	<10	73			
E856842		71	20	<0.01	<10	<10	10	<10	74			
E856843		43	20	<0.01	<10	<10	12	<10	70			
E856844		112	<20	<0.01	<10	<10	7	<10	53			
E856845		52	<20	<0.01	<10	<10	6	<10	55			
E856846		91	20	<0.01	<10	<10	1	<10	18			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856847		5.18	0.009		<0.2	0.48	123	<10	70	<0.5	<2	1.29	<0.5	5	10	10
E856848		4.69	0.050		<0.2	0.77	492	<10	90	<0.5	<2	2.14	<0.5	10	10	19
E856849		<0.02	0.049		<0.2	0.73	493	<10	80	<0.5	<2	2.06	<0.5	10	10	20
E856850		0.07	0.848		>100	0.61	4840	<10	10	<0.5	5	0.61	107.5	7	57	310
E856851		4.55	0.047		<0.2	0.53	484	<10	120	<0.5	<2	1.80	<0.5	11	9	25
E856852		5.22	0.155		<0.2	0.38	1315	<10	100	<0.5	<2	1.49	<0.5	5	12	9
E856853		3.25	0.339		0.5	0.42	7500	<10	170	<0.5	<2	2.39	<0.5	11	6	21
E856854		2.14	0.043		0.4	0.61	231	<10	530	<0.5	<2	0.50	<0.5	7	13	64
E856855		4.00	0.038		0.3	0.51	268	<10	470	<0.5	<2	0.79	<0.5	11	14	56
E856856		3.22	0.005		0.2	0.32	33	<10	370	<0.5	<2	0.45	0.9	7	13	65
E856857		2.44	0.009		0.2	0.36	30	<10	400	<0.5	<2	0.39	<0.5	4	14	40
E856858		2.44	0.008		0.3	0.73	10	<10	480	<0.5	<2	0.19	<0.5	9	18	52
E856859		2.96	<0.005		0.2	0.51	5	<10	140	<0.5	<2	0.55	1.4	9	13	59
E856860		4.13	0.005		0.3	0.33	<2	<10	170	<0.5	2	0.48	1.9	8	13	50
E856861		1.31	<0.005		0.3	0.28	3	<10	90	<0.5	<2	0.63	<0.5	6	10	82
E856862		1.18	<0.005		0.3	0.30	7	<10	100	<0.5	2	0.72	<0.5	7	11	82
E856863		1.41	<0.005		<0.2	0.25	11	<10	120	<0.5	<2	0.40	0.7	5	11	53
E856864		0.86	0.009		0.4	0.28	19	<10	70	<0.5	<2	0.67	<0.5	5	7	84
E856865		2.54	0.009		0.3	0.30	16	<10	130	<0.5	<2	0.23	2.1	8	14	35
E856866		2.95	0.030		<0.2	0.59	7	<10	420	<0.5	<2	0.22	0.5	7	15	45
E856867		3.35	0.007		0.2	0.79	6	<10	490	<0.5	<2	0.22	<0.5	8	17	92
E856868		3.22	0.031		<0.2	0.65	8	<10	420	<0.5	<2	1.44	<0.5	5	15	94
E856869		<0.02	0.022		<0.2	0.60	6	<10	410	<0.5	<2	1.06	<0.5	5	16	85
E856870		0.07	1.475	1.89	>100	0.39	4490	<10	20	<0.5	10	0.80	509	5	56	849
E856871		1.18	0.006		0.9	0.83	36	<10	300	<0.5	<2	0.37	1.0	9	16	75
E856872		1.69	0.007		0.4	1.15	18	<10	320	<0.5	<2	0.50	<0.5	11	20	67
E856873		2.15	0.011		0.5	1.20	14	<10	300	<0.5	<2	0.67	<0.5	10	20	70
E856874		1.36	0.009		0.5	1.37	5	<10	330	<0.5	<2	0.41	<0.5	10	23	39
E856875		1.65	0.010		0.3	1.02	4	<10	310	<0.5	<2	0.43	<0.5	9	19	45
E856876		1.79	0.010		0.3	1.05	7	<10	290	<0.5	<2	1.04	<0.5	7	17	54
E856877		2.45	0.009		0.4	0.98	14	<10	220	<0.5	<2	0.80	<0.5	9	19	78
E856878		1.62	0.409		1.6	0.55	5330	<10	170	<0.5	<2	0.56	<0.5	11	12	84
E856879		2.41	0.026		0.5	1.19	257	<10	210	<0.5	<2	0.45	<0.5	8	13	49
E856880		1.79	0.005		<0.2	0.86	8	<10	230	<0.5	<2	0.55	<0.5	6	14	53
E856881		1.29	<0.005		<0.2	0.76	4	<10	230	<0.5	<2	0.21	<0.5	5	12	42
E856882		1.36	<0.005		0.2	0.72	7	<10	250	<0.5	<2	0.94	<0.5	5	12	48
E856883		1.83	<0.005		<0.2	0.62	8	<10	220	<0.5	<2	0.16	<0.5	4	13	42
E856884		3.06	<0.005		0.2	0.88	3	<10	330	<0.5	<2	0.38	<0.5	7	13	46
E856885		3.29	<0.005		0.3	0.65	9	<10	340	<0.5	<2	1.02	0.7	6	11	20
E856886		2.07	<0.005		0.2	0.95	8	<10	240	<0.5	<2	1.12	<0.5	7	12	18

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856847		1.60	<10	<1	0.25	20	0.29	409	<1	0.03	10	190	15	0.09	5	1
E856848		2.61	<10	<1	0.34	20	0.53	722	<1	0.02	19	290	24	0.32	12	2
E856849		2.66	<10	<1	0.30	20	0.54	717	<1	0.02	20	290	20	0.32	13	2
E856850		6.43	<10	1	0.36	10	0.11	313	1	0.05	5	700	5350	8.0	1790	1
E856851		2.69	<10	<1	0.27	20	0.51	688	<1	0.03	18	210	23	0.38	16	2
E856852		1.84	<10	<1	0.25	10	0.40	591	<1	0.02	10	190	15	0.69	7	1
E856853		3.39	<10	<1	0.29	10	0.84	997	<1	0.02	21	430	11	2.08	18	2
E856854		2.32	<10	<1	0.13	10	0.38	1250	1	0.01	27	990	10	0.59	27	3
E856855		2.25	<10	<1	0.13	10	0.48	396	2	0.01	37	240	5	0.67	13	1
E856856		1.92	<10	<1	0.13	10	0.25	330	5	0.01	39	180	12	0.92	8	1
E856857		1.77	<10	<1	0.11	10	0.24	324	1	0.01	18	170	7	0.63	<2	1
E856858		2.56	<10	<1	0.15	10	0.40	294	1	0.02	32	210	7	0.81	<2	1
E856859		2.38	<10	1	0.16	10	0.32	330	12	0.02	49	340	7	1.27	<2	1
E856860		2.07	<10	<1	0.13	10	0.26	272	44	0.01	57	570	12	1.09	<2	1
E856861		2.37	<10	1	0.11	10	0.33	324	4	0.02	56	150	9	1.53	<2	1
E856862		2.40	<10	<1	0.11	10	0.40	340	4	0.02	55	180	6	1.49	<2	1
E856863		1.68	<10	<1	0.08	10	0.21	212	5	0.01	44	200	8	1.14	<2	1
E856864		1.71	<10	<1	0.09	<10	0.36	266	3	0.01	50	130	13	1.58	<2	1
E856865		1.68	<10	<1	0.11	<10	0.09	118	21	0.01	63	420	14	1.42	<2	1
E856866		1.86	<10	<1	0.12	10	0.31	127	5	0.01	32	190	4	0.64	<2	1
E856867		1.84	<10	<1	0.10	10	0.45	755	1	0.01	25	190	5	0.20	<2	1
E856868		2.41	<10	<1	0.11	10	0.51	4840	<1	0.02	20	4130	7	0.20	<2	2
E856869		2.00	<10	1	0.11	10	0.42	3510	<1	0.02	20	2850	7	0.17	<2	1
E856870		6.58	<10	3	0.27	10	0.26	373	1	0.03	5	570	>10000	9.6	2380	1
E856871		1.92	<10	<1	0.11	10	0.49	1755	1	0.01	31	200	50	0.18	7	1
E856872		2.50	<10	<1	0.13	10	0.65	752	1	0.02	42	300	12	0.33	2	1
E856873		3.40	<10	<1	0.14	10	0.69	1165	1	0.02	45	320	17	0.86	<2	1
E856874		3.19	<10	<1	0.13	10	0.75	793	<1	0.02	39	290	13	0.56	<2	1
E856875		2.34	<10	<1	0.12	10	0.54	1255	<1	0.01	35	210	8	0.34	<2	1
E856876		3.03	<10	1	0.12	10	0.69	4060	<1	0.01	29	340	11	0.48	<2	2
E856877		2.71	<10	<1	0.10	10	0.65	2670	<1	0.01	32	190	7	0.48	<2	2
E856878		2.65	<10	<1	0.11	10	0.39	471	<1	0.01	43	220	34	1.44	36	2
E856879		3.03	<10	<1	0.12	10	0.55	648	<1	0.01	30	270	52	0.46	15	2
E856880		2.18	<10	<1	0.11	10	0.61	1180	<1	0.01	22	420	13	0.02	<2	2
E856881		1.86	<10	<1	0.09	10	0.46	821	<1	0.01	22	200	33	0.03	<2	1
E856882		1.89	<10	<1	0.11	10	0.59	1335	<1	0.01	18	1060	7	0.02	<2	2
E856883		1.46	<10	<1	0.10	10	0.34	381	<1	<0.01	20	110	7	0.01	<2	1
E856884		2.29	<10	<1	0.13	10	0.47	441	<1	0.01	22	210	12	0.28	<2	1
E856885		2.09	<10	<1	0.14	10	0.50	451	1	0.02	20	390	16	0.36	<2	1
E856886		2.47	<10	<1	0.16	10	0.64	543	<1	0.02	14	440	14	0.12	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856847		84	20	<0.01	<10	<10	3	<10	30			
E856848		122	<20	<0.01	<10	<10	6	<10	51			
E856849		116	<20	<0.01	<10	<10	5	<10	50			
E856850		143	<20	<0.01	<10	<10	6	10	>10000		1.235	152
E856851		96	<20	<0.01	<10	<10	4	<10	56			
E856852		79	<20	<0.01	<10	<10	2	<10	32			
E856853		164	20	<0.01	<10	<10	3	<10	40			
E856854		104	<20	<0.01	<10	<10	12	<10	56			
E856855		113	<20	<0.01	<10	<10	11	<10	52			
E856856		69	<20	<0.01	<10	<10	24	<10	126			
E856857		43	<20	<0.01	<10	<10	14	<10	61			
E856858		30	<20	<0.01	<10	<10	15	<10	76			
E856859		85	<20	<0.01	<10	<10	39	<10	194			
E856860		68	<20	<0.01	<10	<10	39	<10	265			
E856861		97	<20	<0.01	<10	<10	10	<10	74			
E856862		101	<20	<0.01	<10	<10	11	<10	80			
E856863		63	<20	<0.01	<10	<10	12	<10	118			
E856864		102	<20	<0.01	<10	<10	9	<10	68			
E856865		50	<20	<0.01	<10	<10	55	<10	280			
E856866		48	<20	<0.01	<10	<10	25	<10	95			
E856867		40	<20	<0.01	<10	<10	16	<10	46			
E856868		245	<20	<0.01	<10	<10	14	<10	33			
E856869		176	<20	<0.01	<10	<10	13	<10	30			
E856870		109	<20	<0.01	<10	<10	5	20	>10000	1.920	3.72	313
E856871		51	<20	<0.01	<10	<10	16	<10	234			
E856872		62	<20	<0.01	<10	<10	21	<10	79			
E856873		72	<20	<0.01	<10	<10	19	<10	95			
E856874		46	<20	<0.01	<10	<10	22	<10	118			
E856875		51	<20	<0.01	<10	<10	16	<10	75			
E856876		103	<20	<0.01	<10	<10	18	<10	69			
E856877		79	<20	<0.01	<10	<10	18	<10	68			
E856878		127	<20	<0.01	<10	<10	13	<10	116			
E856879		59	<20	<0.01	<10	<10	13	<10	56			
E856880		60	<20	<0.01	<10	<10	16	<10	35			
E856881		24	<20	<0.01	<10	<10	13	<10	34			
E856882		112	<20	<0.01	<10	<10	13	<10	32			
E856883		19	<20	<0.01	<10	<10	12	<10	28			
E856884		37	<20	<0.01	<10	<10	9	<10	36			
E856885		101	<20	<0.01	<10	<10	8	<10	72			
E856886		109	<20	<0.01	<10	<10	5	<10	42			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856887		2.08	0.008		1.0	1.03	25	<10	240	<0.5	<2	0.68	2.1	13	15	52
E856888		2.12	0.020		0.6	0.33	67	<10	120	<0.5	<2	0.85	4.6	8	11	56
E856889		<0.02	0.023		0.6	0.35	70	<10	120	<0.5	<2	0.85	5.0	9	11	59
E856890		0.06	<0.005		NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS
E856891		2.90	0.032		0.3	0.70	55	<10	260	<0.5	<2	0.47	<0.5	9	14	73
E856892		3.47	0.011		0.4	0.44	28	<10	250	<0.5	<2	0.98	0.7	8	12	76
E856893		2.47	0.016		0.6	0.46	53	<10	140	<0.5	<2	1.68	3.6	7	15	52
E856894		3.15	0.026		0.2	0.61	29	<10	300	<0.5	<2	0.34	<0.5	9	15	103
E856895		1.75	0.041		<0.2	0.72	38	<10	330	<0.5	2	0.36	<0.5	12	14	103
E856896		2.26	0.025		0.2	0.85	24	<10	240	<0.5	<2	0.25	<0.5	8	18	93
E856897		4.60	0.020		0.3	0.93	10	<10	230	<0.5	<2	1.25	<0.5	7	19	92
E856898		4.26	0.060		<0.2	0.99	14	<10	220	<0.5	2	0.92	<0.5	10	15	132
E856899		4.26	0.035		0.2	0.81	9	<10	240	<0.5	2	0.70	<0.5	8	19	85
E856900		4.97	0.014		<0.2	0.55	7	<10	230	<0.5	<2	0.51	<0.5	6	18	68
E856901		5.04	0.106		0.2	0.60	9	<10	320	<0.5	<2	0.17	<0.5	8	16	78
E856902		4.40	0.020		0.2	0.79	4	<10	300	<0.5	<2	0.30	<0.5	8	19	82
E856903		4.63	0.067		0.3	0.88	4	<10	300	<0.5	<2	0.21	<0.5	8	22	80
E856904		3.41	0.024		0.3	0.91	4	<10	290	<0.5	<2	1.43	<0.5	4	18	64
E856905		3.83	0.013		0.2	1.09	6	<10	310	<0.5	<2	0.12	<0.5	7	19	75
E856906		2.85	0.020		0.2	0.85	4	<10	250	<0.5	<2	0.25	<0.5	6	20	75

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856887		3.06	<10	<1	0.20	10	0.52	420	7	0.02	56	760	14	0.98	7	1
E856888		2.30	<10	<1	0.13	<10	0.30	357	19	0.01	83	1070	14	1.74	7	1
E856889		2.41	<10	<1	0.14	<10	0.30	358	20	0.01	89	1120	16	1.89	7	1
E856890		NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS
E856891		2.25	<10	1	0.10	10	0.41	1500	<1	0.01	31	530	6	0.56	18	2
E856892		2.16	<10	<1	0.14	<10	0.48	574	3	0.02	42	340	11	1.22	4	1
E856893		2.51	<10	<1	0.19	<10	0.48	448	13	0.01	71	3670	16	1.92	3	1
E856894		1.71	<10	<1	0.09	10	0.43	1340	<1	0.01	29	190	10	0.27	20	2
E856895		1.87	<10	<1	0.09	10	0.45	2040	<1	0.01	33	150	7	0.19	15	2
E856896		1.79	<10	<1	0.09	10	0.51	1310	<1	0.01	28	130	10	0.10	14	2
E856897		1.83	<10	<1	0.10	10	0.62	10650	<1	0.01	23	1300	8	0.06	3	2
E856898		2.02	<10	<1	0.12	10	0.69	2840	1	0.02	30	630	7	0.08	3	2
E856899		1.90	<10	<1	0.10	10	0.55	3700	<1	0.01	24	340	8	0.12	5	2
E856900		1.59	<10	<1	0.09	10	0.48	1655	<1	0.02	20	130	6	0.08	<2	2
E856901		2.51	<10	<1	0.17	10	0.61	598	<1	0.02	25	250	9	0.27	<2	2
E856902		1.85	<10	<1	0.13	10	0.52	788	<1	0.01	25	150	10	0.27	<2	2
E856903		1.70	<10	<1	0.11	10	0.51	751	<1	0.01	24	120	8	0.12	<2	1
E856904		2.13	<10	<1	0.11	10	0.72	8820	<1	0.01	17	150	9	0.17	<2	1
E856905		1.97	<10	<1	0.13	10	0.64	536	<1	0.01	22	100	8	0.13	<2	1
E856906		1.51	<10	<1	0.11	10	0.52	1000	<1	0.01	18	100	6	0.05	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856887		65	<20	<0.01	<10	<10	26	<10	235			
E856888		99	<20	<0.01	<10	<10	54	<10	385			
E856889		101	<20	<0.01	<10	<10	58	<10	414			
E856890		NSS	NSS	NSS	NSS	NSS	NSS	NSS	NSS			
E856891		68	<20	<0.01	<10	<10	12	<10	85			
E856892		97	<20	<0.01	<10	<10	16	<10	119			
E856893		180	<20	<0.01	<10	<10	61	<10	325			
E856894		50	<20	<0.01	<10	<10	14	<10	41			
E856895		50	<20	<0.01	<10	<10	16	<10	40			
E856896		38	<20	<0.01	<10	<10	19	<10	39			
E856897		155	<20	<0.01	<10	<10	19	<10	36			
E856898		146	<20	<0.01	<10	<10	21	<10	45			
E856899		95	<20	<0.01	<10	<10	18	<10	38			
E856900		81	<20	<0.01	<10	<10	14	<10	36			
E856901		55	<20	<0.01	<10	<10	17	<10	85			
E856902		56	<20	<0.01	<10	<10	20	<10	46			
E856903		42	<20	<0.01	<10	<10	20	<10	36			
E856904		182	<20	<0.01	<10	<10	17	<10	37			
E856905		25	<20	<0.01	<10	<10	20	<10	40			
E856906		41	<20	<0.01	<10	<10	17	<10	34			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102708

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

CERTIFICATE WH10102707

Project: ALN10-01

P.O. No.: ALN10-01_26

This report is for 97 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 27-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E855751		3.85	<0.005		0.3	2.49	20	<10	20	<0.5	<2	6.28	<0.5	24	36	48
E855752		3.10	<0.005		<0.2	4.18	7	<10	30	<0.5	<2	2.59	<0.5	27	34	42
E855753		3.32	<0.005		<0.2	2.69	12	<10	90	<0.5	<2	5.44	<0.5	23	30	36
E855754		2.51	<0.005		<0.2	2.86	33	<10	100	<0.5	<2	3.94	<0.5	23	28	39
E855755		2.68	<0.005		0.2	2.70	23	<10	90	<0.5	<2	4.48	<0.5	24	27	39
E855756		2.53	<0.005		0.2	1.30	23	<10	70	<0.5	<2	1.49	<0.5	10	22	21
E855757		3.45	<0.005		0.2	0.47	18	<10	70	<0.5	<2	1.37	<0.5	4	6	8
E855758		2.23	0.008		0.2	0.86	112	<10	90	<0.5	<2	2.02	<0.5	8	13	15
E855759		1.16	<0.005		0.2	1.96	34	<10	80	<0.5	<2	5.32	<0.5	18	29	39
E855760		1.42	<0.005		<0.2	2.78	65	<10	50	<0.5	<2	5.03	<0.5	27	43	56
E855761		0.72	0.007		<0.2	1.13	127	<10	90	<0.5	<2	1.85	<0.5	12	17	19
E855762		1.02	<0.005		0.2	2.33	59	<10	70	<0.5	<2	2.15	<0.5	21	26	35
E855763		3.42	<0.005		0.3	1.33	24	<10	90	<0.5	<2	2.07	<0.5	13	20	25
E855764		3.36	<0.005		0.2	0.91	5	<10	100	<0.5	2	1.31	<0.5	10	10	24
E855765		3.99	<0.005		<0.2	0.89	9	<10	90	<0.5	<2	0.96	<0.5	8	9	15
E855766		4.12	<0.005		0.9	0.66	33	<10	70	<0.5	<2	0.99	<0.5	5	14	16
E855767		1.65	<0.005		0.2	0.73	14	<10	60	<0.5	<2	3.43	<0.5	8	8	20
E855768		1.11	0.043		<0.2	1.34	178	<10	80	<0.5	<2	0.55	<0.5	10	10	24
E855769		<0.02	0.051		<0.2	1.31	193	<10	80	<0.5	<2	0.55	<0.5	11	10	21
E855770		0.07	1.590	NSS	>100	0.37	4400	<10	20	<0.5	6	0.84	520	5	53	845
E855771		1.15	<0.005		0.9	2.33	46	<10	130	<0.5	<2	0.37	0.7	18	24	41
E855772		1.19	<0.005		48.5	0.59	13	<10	480	<0.5	<2	0.76	1.0	8	9	195
E856976		2.46	<0.005		0.2	2.33	7	<10	90	<0.5	<2	0.87	<0.5	17	24	18
E856977		3.44	<0.005		0.8	0.81	12	<10	70	<0.5	<2	7.7	<0.5	8	18	31
E856978		3.21	<0.005		0.2	2.33	<2	<10	120	<0.5	<2	0.83	<0.5	15	25	15
E856979		4.64	<0.005		0.2	1.99	<2	<10	110	<0.5	<2	2.38	<0.5	14	26	21
E856980		4.42	<0.005		<0.2	2.03	<2	<10	100	<0.5	<2	0.14	<0.5	17	22	44
E856981		2.19	<0.005		<0.2	1.76	<2	<10	70	0.5	<2	0.24	<0.5	15	20	37
E856982		2.27	<0.005		0.3	1.86	<2	<10	70	0.5	<2	0.23	<0.5	16	20	42
E856983		4.00	<0.005		0.4	2.17	<2	<10	100	<0.5	2	0.11	<0.5	17	25	40
E856984		4.26	<0.005		0.3	2.23	3	<10	80	<0.5	<2	0.13	<0.5	17	26	47
E856985		4.14	<0.005		0.3	1.86	<2	<10	80	<0.5	<2	0.70	<0.5	14	19	37
E856986		3.81	<0.005		0.2	2.30	2	<10	90	0.5	3	0.17	<0.5	18	25	40
E856987		4.43	<0.005		0.2	2.57	<2	<10	100	0.5	3	0.13	<0.5	19	30	48
E856988		3.98	<0.005		0.3	2.56	<2	<10	110	0.5	2	0.08	<0.5	19	30	30
E856989		<0.02	<0.005		0.4	2.56	3	<10	100	0.5	2	0.08	<0.5	19	30	32
E856990		0.07	NSS		>100	0.50	4590	<10	30	<0.5	5	0.52	98.6	6	51	295
E856991		3.54	<0.005		0.6	1.89	3	<10	110	<0.5	<2	0.84	<0.5	14	21	26
E856992		4.47	<0.005		0.4	2.22	<2	<10	110	<0.5	<2	0.50	<0.5	15	24	29
E856993		4.49	<0.005		0.3	2.09	7	<10	80	<0.5	2	5.15	<0.5	13	52	32

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E855751		4.96	10	<1	0.03	10	2.70	1025	1	0.04	40	1480	18	0.39	9	9
E855752		7.17	20	<1	0.05	10	3.80	712	1	0.02	47	2080	4	0.14	<2	11
E855753		4.88	10	1	0.12	10	2.12	969	1	0.03	41	1560	7	0.08	2	7
E855754		5.27	10	1	0.12	10	1.96	814	1	0.03	42	1820	6	0.06	<2	7
E855755		5.06	10	1	0.09	10	1.88	806	2	0.03	44	1900	6	0.13	3	6
E855756		2.62	<10	1	0.17	10	0.91	432	<1	0.02	19	520	10	0.05	2	3
E855757		1.39	<10	<1	0.28	20	0.18	492	<1	0.02	6	110	12	0.06	5	1
E855758		2.21	<10	<1	0.23	10	0.42	876	<1	0.02	14	440	10	0.09	7	2
E855759		4.10	10	<1	0.20	10	1.46	1400	<1	0.02	37	870	33	0.10	4	4
E855760		6.04	10	<1	0.13	10	1.72	1975	1	0.03	51	1610	38	0.10	8	9
E855761		2.70	<10	<1	0.24	20	0.70	601	<1	0.02	22	250	11	0.13	10	2
E855762		4.95	10	1	0.19	20	1.59	1010	1	0.02	36	1030	13	0.06	9	4
E855763		2.98	<10	1	0.27	20	0.73	618	<1	0.02	26	490	15	0.10	10	2
E855764		2.31	<10	<1	0.35	20	0.39	521	<1	0.02	19	190	21	0.17	5	1
E855765		1.95	<10	<1	0.34	20	0.35	412	<1	0.02	15	400	19	0.12	2	1
E855766		1.74	<10	<1	0.24	20	0.27	475	<1	0.02	11	170	13	0.07	6	1
E855767		2.20	<10	<1	0.23	20	0.47	1155	<1	0.03	15	250	29	0.10	16	1
E855768		3.11	<10	1	0.27	30	0.65	348	<1	0.01	23	340	13	0.13	20	1
E855769		3.01	<10	<1	0.28	30	0.63	345	<1	0.01	23	330	14	0.13	16	1
E855770		6.80	<10	2	0.25	10	0.26	372	1	0.02	5	540	>10000	9.2	2630	1
E855771		4.78	10	1	0.27	30	1.03	1255	<1	0.02	38	420	38	0.08	23	2
E855772		2.08	<10	<1	0.12	10	0.50	577	3	0.01	40	500	12	0.63	30	1
E856976		4.72	10	<1	0.25	20	1.03	544	<1	0.02	38	480	7	0.02	3	3
E856977		2.29	<10	1	0.12	10	0.40	990	1	0.04	16	300	73	0.11	2	2
E856978		4.88	10	<1	0.36	40	0.91	321	<1	0.01	37	260	3	0.02	2	2
E856979		4.00	10	1	0.32	30	0.79	632	<1	0.04	29	300	6	0.01	<2	3
E856980		4.10	10	<1	0.30	30	0.86	703	<1	0.02	36	360	2	0.01	<2	2
E856981		3.72	10	<1	0.23	20	0.68	934	<1	0.03	27	340	19	0.08	<2	2
E856982		3.78	<10	<1	0.21	20	0.69	1460	<1	0.03	35	300	13	0.04	<2	1
E856983		4.50	10	1	0.25	20	0.77	400	<1	0.03	38	340	31	0.16	<2	2
E856984		4.50	10	1	0.24	20	0.80	577	<1	0.03	36	350	19	0.11	<2	2
E856985		3.66	10	1	0.23	10	0.67	522	<1	0.03	28	290	21	0.09	<2	2
E856986		4.27	10	<1	0.25	20	0.90	526	<1	0.03	39	280	14	0.03	<2	2
E856987		4.73	10	1	0.25	20	1.06	551	<1	0.03	41	310	49	0.01	<2	2
E856988		4.72	10	1	0.26	30	1.06	522	<1	0.03	44	290	29	<0.01	<2	2
E856989		4.84	10	1	0.25	30	1.07	535	<1	0.03	44	290	43	<0.01	<2	2
E856990		5.72	<10	2	0.31	10	0.09	296	1	0.04	5	650	4850	7.6	1770	1
E856991		3.74	10	1	0.26	20	0.72	561	<1	0.03	33	290	22	0.02	2	2
E856992		4.30	10	1	0.26	30	0.99	477	<1	0.02	39	370	16	0.01	<2	2
E856993		3.44	10	1	0.19	10	1.45	1045	<1	0.03	49	530	19	0.02	<2	3

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E855751		415	<20	0.01	<10	<10	76	<10	80			
E855752		139	<20	0.02	<10	<10	79	<10	126			
E855753		346	<20	0.08	<10	<10	59	<10	94			
E855754		217	<20	0.06	<10	<10	55	<10	112			
E855755		244	<20	0.10	<10	<10	54	<10	129			
E855756		106	<20	0.02	<10	<10	23	<10	43			
E855757		80	<20	0.01	<10	<10	3	<10	24			
E855758		111	<20	0.01	<10	<10	13	<10	42			
E855759		343	<20	0.03	<10	<10	32	<10	97			
E855760		278	<20	0.04	<10	<10	71	<10	160			
E855761		121	<20	<0.01	<10	<10	12	<10	45			
E855762		130	<20	0.01	<10	<10	34	<10	113			
E855763		146	<20	0.01	<10	<10	16	<10	60			
E855764		90	<20	0.01	<10	<10	6	<10	48			
E855765		66	<20	0.01	<10	<10	6	<10	40			
E855766		58	<20	<0.01	<10	<10	5	<10	31			
E855767		192	<20	<0.01	<10	<10	4	<10	37			
E855768		36	<20	<0.01	<10	<10	6	<10	76			
E855769		36	<20	<0.01	<10	<10	7	<10	73			
E855770		108	<20	<0.01	<10	<10	5	20	>10000	1.960	3.74	318
E855771		27	<20	<0.01	<10	<10	15	<10	174			
E855772		80	<20	<0.01	<10	<10	28	170	123			
E856976		29	<20	0.01	<10	<10	21	<10	100			
E856977		359	<20	<0.01	<10	<10	9	<10	39			
E856978		41	<20	0.01	<10	<10	17	<10	92			
E856979		126	20	0.01	<10	<10	20	<10	79			
E856980		9	<20	0.01	<10	<10	15	<10	92			
E856981		13	<20	0.02	<10	<10	13	<10	67			
E856982		14	<20	0.01	<10	<10	12	<10	80			
E856983		10	<20	0.01	<10	<10	19	<10	80			
E856984		12	<20	0.01	<10	<10	19	<10	89			
E856985		43	<20	0.01	<10	<10	13	<10	67			
E856986		14	<20	0.01	<10	<10	17	<10	92			
E856987		11	<20	0.01	<10	<10	21	<10	99			
E856988		9	<20	0.01	<10	<10	22	<10	100			
E856989		9	<20	0.01	<10	<10	22	<10	101			
E856990		129	<20	<0.01	<10	<10	5	<10	>10000		1.280	142
E856991		52	<20	0.01	<10	<10	14	<10	90			
E856992		27	<20	0.02	<10	<10	18	<10	91			
E856993		270	<20	0.01	<10	<10	26	<10	78			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Sample Description	Method	WEI-21	Au-AA23	Au-GRA21	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu
	Units	kg	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.05	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1
E856994		4.58	<0.005		0.3	1.65	4	<10	100	<0.5	<2	3.16	<0.5	12	21	24
E856995		2.49	<0.005		0.4	1.72	3	<10	110	<0.5	<2	0.43	<0.5	12	19	45
E856996		3.40	<0.005		0.2	1.83	9	<10	100	<0.5	<2	1.36	<0.5	19	48	51
E856997		4.77	0.005		0.5	3.32	7	<10	50	<0.5	<2	1.66	<0.5	26	32	53
E856998		3.57	<0.005		0.3	2.23	5	<10	70	<0.5	<2	2.39	<0.5	17	29	43
E856999		2.88	<0.005		0.3	1.57	3	<10	100	<0.5	<2	0.09	<0.5	9	20	38
E857000		3.11	<0.005		0.3	3.03	21	<10	70	<0.5	<2	3.44	<0.5	26	281	24
E857001		2.32	<0.005		0.4	1.97	17	<10	140	<0.5	<2	0.89	<0.5	25	127	88
E857002		2.22	<0.005		0.2	2.41	14	<10	160	<0.5	<2	1.70	<0.5	18	83	41
E857003		4.41	<0.005		0.4	2.54	3	<10	190	<0.5	<2	1.59	<0.5	20	65	64
E857004		2.59	<0.005		0.4	4.01	12	<10	100	<0.5	2	2.60	<0.5	27	82	46
E857005		3.64	<0.005		0.5	3.72	11	<10	20	<0.5	3	3.99	<0.5	27	36	42
E857006		4.44	<0.005		0.3	4.19	8	<10	20	<0.5	<2	2.28	<0.5	29	39	35
E857007		4.05	<0.005		0.3	3.49	8	<10	60	<0.5	<2	3.50	<0.5	28	39	63
E857008		4.52	<0.005		0.2	2.89	6	<10	220	0.6	<2	5.72	<0.5	14	26	62
E857009		<0.02	<0.005		<0.2	2.85	<2	<10	210	0.6	<2	5.98	<0.5	14	26	65
E857010		0.05	0.008		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	1	1
E857011		3.98	<0.005		0.3	3.64	9	<10	170	<0.5	<2	4.43	<0.5	24	36	81
E857012		3.01	0.005		<0.2	2.65	3	<10	180	0.5	<2	6.31	<0.5	17	33	21
E857013		4.16	<0.005		0.3	4.07	5	<10	40	0.5	3	3.36	<0.5	33	45	48
E857014		4.89	<0.005		0.3	4.04	5	<10	30	0.5	3	2.23	<0.5	36	50	58
E857015		5.08	<0.005		0.3	4.45	6	<10	40	0.6	4	2.32	<0.5	36	47	85
E857016		2.44	<0.005		<0.2	3.92	5	<10	30	0.5	2	3.37	<0.5	31	43	58
E857017		4.45	<0.005		0.5	4.05	7	<10	30	0.5	2	2.85	<0.5	33	47	52
E857018		4.36	<0.005		<0.2	3.39	9	<10	20	<0.5	<2	3.33	<0.5	28	38	47
E857019		3.26	<0.005		<0.2	3.51	13	<10	10	<0.5	<2	2.41	<0.5	28	39	42
E857020		4.95	<0.005		<0.2	3.27	2	<10	20	<0.5	<2	4.61	<0.5	24	36	35
E857021		2.59	<0.005		<0.2	2.64	7	<10	100	<0.5	<2	4.12	<0.5	21	28	39
E857022		2.66	<0.005		<0.2	2.83	5	<10	90	<0.5	<2	4.31	<0.5	23	30	66
E857023		4.61	<0.005		<0.2	1.01	3	<10	160	<0.5	<2	5.06	<0.5	10	10	25
E857024		3.83	<0.005		<0.2	0.91	<2	<10	130	<0.5	<2	4.68	<0.5	10	9	57
E857025		4.39	<0.005		<0.2	1.74	3	<10	180	<0.5	<2	3.04	<0.5	18	20	47
E857026		4.96	0.013		<0.2	2.02	5	<10	160	<0.5	<2	2.64	<0.5	19	20	50
E857027		4.45	0.009		0.2	0.99	124	<10	230	<0.5	<2	0.23	<0.5	19	12	53
E857028		4.15	0.006		<0.2	1.34	25	<10	260	<0.5	2	0.41	<0.5	21	15	50
E857029		<0.02	<0.005		<0.2	1.36	23	<10	260	<0.5	<2	0.39	<0.5	21	16	49
E857030		0.07	0.887		>100	0.50	4330	<10	20	<0.5	7	0.54	93.9	6	50	285
E857031		5.12	<0.005		0.3	2.48	50	<10	230	0.5	2	0.74	<0.5	25	25	49
E857032		5.19	0.006		<0.2	3.75	17	<10	130	0.5	<2	1.46	<0.5	27	36	47
E857033		4.63	0.006		<0.2	4.19	12	<10	10	<0.5	<2	2.14	<0.5	29	40	40

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856994		3.22	<10	<1	0.27	20	0.70	623	<1	0.03	29	330	13	0.02	<2	2
E856995		3.60	<10	1	0.30	30	0.67	241	<1	0.03	26	350	8	0.04	<2	1
E856996		3.53	10	1	0.28	30	0.90	462	<1	0.03	58	450	31	0.02	<2	2
E856997		6.11	10	1	0.14	10	2.08	867	<1	0.03	52	1730	6	0.04	<2	6
E856998		3.89	10	<1	0.20	20	1.34	706	<1	0.03	44	790	13	0.02	<2	3
E856999		3.28	<10	1	0.29	30	0.62	217	<1	0.02	20	350	13	0.01	<2	1
E857000		4.24	10	<1	0.18	20	2.33	1155	<1	0.03	196	340	18	<0.01	<2	5
E857001		3.65	<10	<1	0.27	20	1.23	445	<1	0.03	101	340	14	0.20	<2	3
E857002		4.20	10	<1	0.27	30	1.58	765	<1	0.03	71	420	15	0.02	<2	3
E857003		4.46	10	1	0.26	20	1.61	684	<1	0.03	60	900	17	0.05	<2	4
E857004		6.35	20	1	0.14	10	3.12	809	<1	0.03	82	1970	3	0.03	<2	7
E857005		6.30	20	1	0.02	<10	2.70	864	<1	0.04	51	2250	<2	0.06	<2	10
E857006		6.94	20	<1	0.03	<10	3.28	720	<1	0.03	54	2270	<2	0.04	2	11
E857007		5.84	20	<1	0.06	<10	2.68	854	<1	0.04	53	2210	10	0.09	<2	9
E857008		3.70	10	1	0.37	20	2.54	1445	<1	0.03	33	770	4	0.02	<2	3
E857009		3.66	10	1	0.36	20	2.53	1475	<1	0.03	32	770	4	0.02	<2	3
E857010		0.02	<10	<1	<0.01	<10	0.01	<5	<1	0.01	1	10	2	0.01	<2	<1
E857011		5.83	10	<1	0.23	10	2.81	1295	<1	0.01	52	1950	6	0.05	<2	6
E857012		3.78	10	<1	0.24	10	2.19	1500	<1	0.02	39	1270	9	0.02	<2	6
E857013		6.88	20	1	0.03	<10	3.25	819	<1	0.03	62	2620	5	0.07	<2	11
E857014		7.00	20	1	0.02	<10	3.24	665	<1	0.03	63	2760	<2	0.15	<2	12
E857015		7.53	20	1	0.03	<10	3.58	682	<1	0.02	64	2760	<2	0.12	<2	11
E857016		6.82	20	1	0.02	<10	3.07	732	<1	0.02	57	2570	<2	0.11	<2	11
E857017		7.03	20	1	0.02	<10	3.14	655	<1	0.03	63	2760	<2	0.12	<2	11
E857018		6.06	20	<1	0.02	<10	2.73	772	<1	0.03	54	2180	5	0.09	<2	10
E857019		6.18	20	1	0.01	<10	2.81	596	<1	0.03	52	2250	3	0.05	<2	11
E857020		5.87	20	<1	0.02	<10	2.57	928	<1	0.03	44	1980	6	0.06	<2	11
E857021		5.04	10	1	0.15	10	2.53	1045	1	0.02	40	1250	10	0.03	<2	7
E857022		5.52	10	1	0.14	10	2.66	1080	<1	0.03	43	1530	8	0.12	<2	8
E857023		2.89	<10	1	0.30	30	2.83	1530	<1	0.02	22	540	13	<0.01	<2	2
E857024		2.78	<10	<1	0.25	20	2.60	1490	<1	0.02	22	500	18	<0.01	<2	2
E857025		4.13	<10	<1	0.31	20	1.74	1025	<1	0.02	35	990	14	0.03	<2	4
E857026		4.14	10	<1	0.27	20	1.93	962	<1	0.02	38	940	16	0.02	<2	3
E857027		3.03	<10	<1	0.33	40	0.50	335	<1	0.02	36	420	25	0.03	2	1
E857028		3.06	<10	<1	0.35	40	0.61	317	<1	0.02	39	510	15	<0.01	<2	2
E857029		3.03	<10	<1	0.35	40	0.62	304	<1	0.02	38	500	14	<0.01	<2	2
E857030		5.81	<10	2	0.31	10	0.10	286	1	0.04	6	640	4760	7.3	1590	1
E857031		4.69	10	1	0.29	30	1.61	392	<1	0.02	44	1060	20	<0.01	2	5
E857032		6.44	20	1	0.14	10	2.92	710	<1	0.02	48	1900	8	0.03	<2	10
E857033		7.43	20	<1	<0.01	<10	3.46	1000	<1	0.03	51	2340	<2	0.11	<2	12

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856994		171	<20	0.02	<10	<10	14	<10	69			
E856995		33	<20	0.02	<10	<10	13	<10	68			
E856996		95	<20	0.02	<10	<10	16	<10	67			
E856997		83	<20	0.03	<10	<10	50	<10	131			
E856998		135	<20	0.02	<10	<10	28	<10	74			
E856999		8	<20	0.02	<10	<10	13	<10	63			
E857000		221	<20	0.01	<10	<10	41	<10	72			
E857001		64	<20	0.01	<10	<10	24	<10	56			
E857002		117	<20	0.03	<10	<10	32	<10	59			
E857003		101	<20	0.11	<10	<10	38	<10	76			
E857004		137	<20	0.06	<10	<10	67	<10	118			
E857005		187	<20	0.09	<10	<10	83	<10	129			
E857006		113	<20	0.11	<10	<10	85	<10	126			
E857007		204	<20	0.10	<10	<10	81	<10	130			
E857008		392	<20	0.06	<10	<10	42	<10	79			
E857009		413	<20	0.06	<10	<10	40	<10	79			
E857010		2	<20	<0.01	<10	<10	<1	<10	5			
E857011		251	<20	0.11	<10	<10	66	<10	130			
E857012		341	<20	0.06	<10	<10	53	<10	91			
E857013		201	<20	0.15	<10	<10	108	<10	149			
E857014		156	<20	0.17	<10	<10	120	<10	173			
E857015		178	<20	0.14	<10	<10	113	<10	176			
E857016		315	<20	0.14	<10	<10	102	<10	156			
E857017		243	<20	0.14	<10	<10	113	<10	163			
E857018		234	<20	0.10	<10	<10	93	<10	130			
E857019		162	<20	0.09	<10	<10	93	<10	128			
E857020		371	<20	0.07	<10	<10	83	<10	119			
E857021		172	<20	0.01	<10	<10	58	<10	111			
E857022		180	<20	0.01	<10	<10	58	<10	117			
E857023		217	20	<0.01	<10	<10	9	<10	59			
E857024		223	<20	<0.01	<10	<10	7	<10	61			
E857025		226	<20	0.01	<10	<10	30	<10	86			
E857026		206	<20	0.02	<10	<10	27	<10	91			
E857027		18	20	<0.01	<10	<10	9	<10	67			
E857028		35	20	0.02	<10	<10	17	<10	76			
E857029		34	20	0.03	<10	<10	17	<10	75			
E857030		130	<20	<0.01	<10	<10	6	<10	>10000		1.315	NSS
E857031		70	20	0.03	<10	<10	38	<10	182			
E857032		141	<20	0.04	<10	<10	77	<10	114			
E857033		191	<20	0.04	<10	<10	99	<10	129			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E857034		3.70	0.005		<0.2	3.93	60	<10	10	<0.5	<2	2.35	<0.5	29	39	42
E857035		1.44	<0.005		<0.2	4.34	118	<10	10	<0.5	<2	1.82	<0.5	32	41	43
E857036		2.20	<0.005		<0.2	4.02	57	<10	20	<0.5	2	2.34	<0.5	30	37	44
E857037		2.76	<0.005		<0.2	2.46	103	<10	120	<0.5	<2	0.94	<0.5	23	23	59
E857038		2.57	<0.005		<0.2	3.24	34	<10	110	<0.5	2	2.00	<0.5	25	32	48
E857039		2.98	0.005		<0.2	3.41	30	<10	60	<0.5	<2	4.09	<0.5	27	64	52
E857040		2.85	<0.005		<0.2	1.97	20	<10	180	<0.5	<2	0.63	<0.5	13	33	37
E857041		1.57	<0.005		<0.2	3.26	14	<10	130	<0.5	<2	2.57	<0.5	23	31	50
E857042		1.47	<0.005		<0.2	3.91	46	<10	30	<0.5	2	2.72	<0.5	30	37	60
E857043		1.68	<0.005		<0.2	2.12	120	<10	100	<0.5	<2	1.76	<0.5	16	26	52
E857044		4.15	<0.005		<0.2	3.67	10	<10	70	<0.5	<2	3.41	<0.5	24	38	37
E857045		2.18	<0.005		<0.2	3.97	5	<10	30	<0.5	2	2.63	<0.5	27	37	57
E857046		3.82	<0.005		<0.2	3.85	20	<10	60	<0.5	<2	4.65	<0.5	26	152	41
E857047		3.65	<0.005		<0.2	3.66	27	<10	20	<0.5	<2	3.43	<0.5	27	56	47
E857048		3.89	<0.005		<0.2	4.00	20	<10	10	<0.5	<2	2.51	<0.5	24	39	36
E857049		<0.02	<0.005		<0.2	3.99	24	<10	<10	<0.5	<2	2.58	<0.5	26	40	38
E857050		0.04	0.009		<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	1	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E857034		7.25	20	<1	<0.01	<10	3.17	895	<1	0.03	51	2280	2	0.11	<2	12
E857035		7.62	20	1	<0.01	<10	3.32	891	<1	0.02	56	2360	2	<0.01	<2	12
E857036		7.30	20	1	0.02	<10	2.85	1115	<1	0.03	54	2310	5	0.04	<2	11
E857037		5.20	10	<1	0.22	20	1.51	866	<1	0.02	56	1250	16	0.01	<2	5
E857038		5.99	10	1	0.21	20	2.06	913	<1	0.02	47	1880	2	<0.01	<2	9
E857039		5.91	10	<1	0.11	10	2.57	1705	<1	0.02	55	1330	9	0.16	<2	8
E857040		3.84	<10	<1	0.25	20	1.31	497	<1	0.02	27	490	11	0.05	<2	3
E857041		5.82	10	<1	0.18	10	2.31	1010	<1	0.02	45	1530	5	0.22	<2	6
E857042		7.09	20	1	0.04	<10	3.12	892	1	0.03	53	2300	7	0.30	<2	11
E857043		4.48	10	<1	0.18	20	1.40	769	1	0.03	42	710	11	0.03	<2	4
E857044		6.05	10	<1	0.08	10	3.04	1030	<1	0.02	49	1820	4	0.09	<2	10
E857045		6.92	20	<1	0.04	<10	3.19	1055	<1	0.02	48	2100	3	0.21	<2	11
E857046		6.12	10	<1	0.10	<10	3.35	1095	<1	0.02	91	1230	7	0.09	<2	11
E857047		6.18	20	<1	0.02	10	3.20	1035	<1	0.03	53	1710	7	0.05	<2	11
E857048		6.55	20	1	0.01	10	3.83	717	<1	0.03	47	2060	2	0.07	6	11
E857049		6.67	20	<1	0.01	10	3.84	729	<1	0.03	48	2060	3	0.10	7	11
E857050		0.02	<10	<1	<0.01	<10	<0.01	<5	<1	0.01	1	10	2	0.01	<2	<1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E857034		254	<20	0.01	<10	<10	88	<10	127			
E857035		115	<20	0.03	<10	<10	100	<10	144			
E857036		146	<20	0.02	<10	<10	84	<10	136			
E857037		48	<20	0.01	<10	<10	41	<10	113			
E857038		102	<20	0.03	<10	<10	68	<10	119			
E857039		188	<20	0.01	<10	<10	60	<10	116			
E857040		37	<20	<0.01	<10	<10	24	<10	74			
E857041		130	<20	0.01	<10	<10	45	<10	123			
E857042		127	<20	0.01	<10	<10	76	<10	124			
E857043		79	<20	<0.01	<10	<10	28	<10	89			
E857044		272	<20	0.03	<10	<10	70	<10	110			
E857045		196	<20	0.04	<10	<10	88	<10	129			
E857046		259	<20	0.02	<10	<10	90	<10	98			
E857047		175	<20	0.02	<10	<10	79	<10	94			
E857048		111	<20	0.01	<10	<10	80	<10	100			
E857049		116	<20	0.01	<10	<10	82	<10	103			
E857050		<1	<20	<0.01	<10	<10	<1	<10	3			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 14-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102707

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-AUG-2010
Account: EIAALN

CERTIFICATE WH10102706

Project: ALN10-01

P.O. No.: ALN-10-01_21

This report is for 62 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 27-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102706

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
E856665		3.46	0.012	<0.2	0.74	14	<10	260	<0.5	<2	0.37	<0.5	11	14	94	1.67
E856666		3.34	0.017	<0.2	0.72	12	<10	290	<0.5	<2	0.41	<0.5	14	15	130	1.74
E856667		4.27	0.039	<0.2	1.06	11	<10	310	<0.5	<2	0.53	<0.5	15	17	113	2.44
E856668		3.71	0.021	<0.2	0.96	7	<10	300	<0.5	<2	0.31	<0.5	13	14	82	1.94
E856669		<0.02	0.007	0.3	0.98	11	<10	310	<0.5	<2	0.31	<0.5	15	14	87	2.07
E856670		0.07	0.860	>100	0.50	4340	<10	30	<0.5	3	0.55	97.7	7	49	287	6.25
E856671		4.39	0.028	0.3	0.86	13	<10	210	<0.5	<2	0.65	<0.5	12	15	104	1.93
E856672		4.48	0.016	0.3	1.06	8	<10	230	<0.5	<2	0.65	<0.5	13	18	88	2.24
E856673		4.56	0.025	<0.2	1.21	3	<10	260	<0.5	<2	0.48	<0.5	12	19	69	2.51
E856674		3.45	0.006	0.2	1.32	4	<10	260	<0.5	<2	0.14	<0.5	13	20	70	2.51
E856675		3.33	0.011	0.3	1.36	7	<10	180	<0.5	<2	0.45	<0.5	10	14	80	2.56
E856676		4.30	0.013	0.2	1.45	<2	<10	200	<0.5	<2	0.24	<0.5	10	17	78	2.65
E856677		3.82	0.015	<0.2	1.16	5	<10	190	<0.5	<2	0.78	<0.5	9	15	86	2.20
E856678		3.54	0.038	0.3	1.12	6	<10	200	<0.5	<2	0.32	<0.5	10	13	92	2.17
E856679		3.28	0.021	<0.2	1.03	7	<10	180	<0.5	<2	0.41	<0.5	8	15	82	1.88
E856680		4.01	0.011	<0.2	1.29	4	<10	190	<0.5	<2	0.14	<0.5	11	19	82	2.56
E856681		2.09	0.081	<0.2	1.43	4	<10	170	<0.5	<2	0.20	<0.5	10	21	88	3.00
E856682		2.42	0.041	<0.2	1.54	4	<10	190	<0.5	<2	0.20	<0.5	11	22	85	3.27
E856683		4.04	0.006	<0.2	1.43	8	<10	220	<0.5	<2	0.14	<0.5	14	23	100	2.86
E856684		4.24	0.010	<0.2	1.15	10	<10	200	<0.5	3	0.91	<0.5	8	15	81	2.05
E856685		3.50	0.020	<0.2	0.80	2	<10	210	<0.5	<2	0.96	<0.5	6	15	80	1.56
E856686		4.05	0.038	<0.2	0.89	4	<10	220	<0.5	3	0.33	<0.5	4	18	79	1.65
E856687		6.39	0.027	<0.2	0.83	6	<10	190	<0.5	3	0.22	<0.5	5	17	71	1.49
E856688		4.03	0.035	<0.2	0.99	7	<10	260	<0.5	<2	0.61	<0.5	6	17	81	1.83
E856689		<0.02	0.041	<0.2	0.94	7	<10	240	<0.5	3	0.61	<0.5	7	18	80	1.70
E856690		0.10	<0.005	<0.2	0.01	<2	<10	10	<0.5	4	0.01	<0.5	1	<1	5	0.02
E856691		3.56	<0.005	<0.2	1.87	11	<10	200	<0.5	2	0.45	<0.5	11	15	95	3.12
E856692		3.23	0.006	<0.2	1.56	10	<10	230	<0.5	2	1.40	<0.5	9	16	97	2.79
E856693		4.81	0.018	<0.2	1.61	8	<10	200	<0.5	<2	0.36	<0.5	11	17	88	2.78
E856694		4.56	0.027	<0.2	2.01	11	<10	200	<0.5	<2	1.27	<0.5	15	14	93	3.57
E856695		3.89	0.009	<0.2	1.62	11	<10	190	<0.5	3	0.44	<0.5	10	14	83	2.72
E856696		3.64	<0.005	<0.2	1.54	12	<10	200	<0.5	3	0.33	<0.5	12	15	82	2.72
E856697		4.56	0.015	<0.2	1.41	10	<10	210	<0.5	3	0.34	<0.5	12	19	100	2.53
E856698		3.56	0.013	<0.2	1.07	4	<10	170	<0.5	<2	0.18	<0.5	11	18	98	2.06
E856699		1.89	0.006	<0.2	0.96	13	<10	230	<0.5	2	0.67	<0.5	12	15	106	2.08
E856700		4.07	0.021	<0.2	1.03	13	<10	300	<0.5	2	0.41	<0.5	8	16	87	1.86
E856701		3.84	0.008	<0.2	1.33	9	<10	310	<0.5	2	0.77	<0.5	12	18	88	3.00
E856702		4.13	0.007	0.3	1.29	7	<10	230	<0.5	<2	0.26	<0.5	13	21	87	2.53
E856703		3.86	<0.005	<0.2	1.08	5	<10	270	<0.5	5	0.25	<0.5	11	18	87	2.00
E856704		3.73	<0.005	<0.2	1.12	7	<10	270	<0.5	<2	0.26	<0.5	9	18	55	2.07

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102706

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E856665		<10	<1	0.09	10	0.44	1860	1	0.01	27	300	9	0.16	<2	1	52
E856666		<10	<1	0.08	10	0.45	2950	1	0.01	34	210	3	0.22	<2	1	48
E856667		<10	<1	0.11	10	0.63	2600	1	0.01	38	340	5	0.36	2	1	62
E856668		<10	<1	0.11	10	0.53	1920	1	0.01	34	220	6	0.22	<2	1	40
E856669		<10	<1	0.11	10	0.54	1930	1	0.01	34	230	6	0.23	2	1	39
E856670		<10	1	0.30	10	0.10	294	2	0.05	4	660	4920	7.4	1670	1	133
E856671		<10	<1	0.09	10	0.51	3030	1	0.01	33	200	16	0.26	4	1	64
E856672		<10	<1	0.11	10	0.61	3080	1	0.01	46	390	9	0.28	<2	1	68
E856673		<10	1	0.14	10	0.66	2220	2	0.01	37	540	6	0.39	<2	1	53
E856674		<10	<1	0.15	10	0.71	833	1	0.01	39	330	3	0.31	<2	1	23
E856675		<10	<1	0.11	10	0.83	1750	1	0.01	21	210	7	0.11	<2	2	56
E856676		<10	1	0.12	10	0.88	1090	1	0.01	23	300	4	0.10	<2	2	32
E856677		<10	1	0.11	10	0.78	5100	<1	0.01	24	340	7	0.09	<2	1	102
E856678		<10	1	0.10	10	0.74	1340	<1	0.01	24	240	5	0.10	<2	1	40
E856679		<10	<1	0.08	10	0.68	1460	1	0.01	22	210	6	0.07	<2	1	48
E856680		<10	<1	0.14	10	0.63	907	1	0.01	30	400	6	0.20	<2	1	22
E856681		<10	1	0.13	10	0.64	1860	1	0.01	31	330	2	0.18	<2	2	30
E856682		10	<1	0.14	10	0.71	2400	1	0.02	34	390	3	0.27	<2	2	30
E856683		<10	1	0.15	10	0.69	1020	1	0.01	37	470	7	0.22	2	1	26
E856684		<10	1	0.12	10	0.62	12300	2	0.01	28	390	16	0.12	<2	1	106
E856685		<10	<1	0.09	10	0.50	4620	1	0.01	22	210	13	0.13	<2	1	127
E856686		<10	<1	0.09	10	0.54	1035	1	<0.01	20	100	8	0.12	<2	1	57
E856687		<10	<1	0.09	10	0.48	561	1	<0.01	19	190	7	0.15	<2	1	39
E856688		<10	<1	0.09	10	0.60	2360	1	<0.01	24	180	7	0.10	<2	1	71
E856689		<10	<1	0.09	10	0.58	2410	1	<0.01	22	180	11	0.10	<2	1	72
E856690		<10	<1	<0.01	<10	<0.01	11	1	<0.01	1	10	<2	0.01	<2	<1	<1
E856691		<10	<1	0.13	10	1.04	1740	<1	0.01	23	390	11	0.10	<2	2	56
E856692		<10	1	0.16	10	0.77	3870	2	0.01	27	940	14	0.13	<2	2	177
E856693		<10	<1	0.15	10	0.84	1350	1	0.01	27	240	10	0.13	<2	2	66
E856694		10	<1	0.14	10	1.16	3110	1	0.01	24	550	8	0.17	<2	3	152
E856695		<10	<1	0.14	10	0.93	1325	1	0.01	21	270	14	0.12	<2	2	68
E856696		<10	<1	0.15	10	0.81	1780	1	0.01	27	300	14	0.14	<2	2	39
E856697		<10	<1	0.15	10	0.63	1900	1	0.01	33	560	14	0.18	<2	1	42
E856698		<10	<1	0.10	10	0.41	1810	2	0.01	26	270	9	0.19	<2	1	24
E856699		<10	<1	0.11	10	0.48	4400	2	0.01	39	170	13	0.21	<2	1	52
E856700		<10	<1	0.13	10	0.48	2600	1	0.02	30	160	8	0.16	<2	2	40
E856701		<10	<1	0.14	10	0.67	6290	1	0.02	31	410	8	0.35	<2	2	66
E856702		<10	<1	0.12	10	0.52	1590	2	0.01	36	440	13	0.31	<2	1	32
E856703		<10	<1	0.12	10	0.52	1105	1	0.01	34	210	16	0.33	<2	1	34
E856704		<10	<1	0.10	10	0.53	1510	1	0.01	29	260	7	0.18	<2	1	35

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102706

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E856665		<20	<0.01	<10	<10	15	<10	40		
E856666		<20	<0.01	<10	<10	18	<10	41		
E856667		<20	<0.01	<10	<10	20	<10	61		
E856668		<20	<0.01	<10	<10	17	<10	54		
E856669		<20	<0.01	<10	<10	17	<10	54		
E856670		<20	<0.01	<10	<10	5	10	>10000	1.310	153
E856671		<20	<0.01	<10	<10	19	<10	70		
E856672		<20	<0.01	<10	<10	21	<10	65		
E856673		<20	<0.01	<10	<10	21	<10	83		
E856674		<20	<0.01	<10	<10	21	<10	79		
E856675		<20	<0.01	<10	<10	23	<10	52		
E856676		<20	<0.01	<10	<10	27	<10	58		
E856677		<20	<0.01	<10	<10	20	<10	45		
E856678		<20	<0.01	<10	<10	22	<10	37		
E856679		<20	<0.01	<10	<10	22	<10	39		
E856680		<20	<0.01	<10	<10	23	<10	68		
E856681		<20	<0.01	<10	<10	28	<10	71		
E856682		<20	<0.01	<10	<10	28	<10	78		
E856683		<20	<0.01	<10	<10	25	<10	78		
E856684		<20	<0.01	<10	<10	21	<10	50		
E856685		<20	<0.01	<10	<10	17	<10	35		
E856686		<20	<0.01	10	<10	21	<10	38		
E856687		<20	<0.01	<10	<10	19	<10	35		
E856688		<20	<0.01	<10	<10	21	<10	38		
E856689		<20	<0.01	<10	<10	20	<10	36		
E856690		<20	<0.01	<10	10	<1	<10	2		
E856691		<20	<0.01	<10	<10	30	<10	62		
E856692		<20	0.01	<10	<10	28	<10	65		
E856693		<20	0.01	<10	<10	26	<10	65		
E856694		<20	0.01	<10	<10	34	<10	62		
E856695		<20	<0.01	<10	<10	24	<10	53		
E856696		<20	<0.01	<10	<10	26	<10	61		
E856697		<20	0.01	<10	<10	27	<10	64		
E856698		<20	0.01	<10	<10	21	<10	48		
E856699		<20	<0.01	<10	<10	20	<10	47		
E856700		<20	<0.01	<10	<10	22	<10	46		
E856701		<20	<0.01	<10	<10	27	<10	56		
E856702		<20	<0.01	<10	<10	25	<10	95		
E856703		<20	<0.01	<10	<10	20	<10	59		
E856704		<20	<0.01	<10	<10	21	<10	58		

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102706

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E856705		3.69	0.012	<0.2	0.85	8	<10	240	<0.5	<2	0.45	<0.5	8	15	75	1.78
E856706		4.16	0.023	<0.2	0.91	8	<10	240	<0.5	<2	0.39	<0.5	7	16	67	1.82
E856707		3.84	0.022	<0.2	0.94	7	<10	310	<0.5	3	0.62	<0.5	6	15	57	1.90
E856708		4.16	0.050	<0.2	1.23	11	<10	310	<0.5	<2	0.60	<0.5	10	13	81	2.35
E856709		<0.02	0.012	<0.2	1.17	12	<10	330	<0.5	<2	0.60	<0.5	9	13	80	2.18
E856710		0.07	0.875	>100	0.56	4440	<10	20	<0.5	7	0.55	102.5	6	53	288	6.22
E856711		3.48	0.007	<0.2	1.21	28	<10	240	<0.5	2	4.95	<0.5	9	11	64	2.66
E856712		5.15	0.016	<0.2	1.29	7	<10	310	<0.5	5	0.57	<0.5	9	16	76	2.80
E856713		3.63	0.023	0.4	0.70	12	<10	300	<0.5	2	0.38	<0.5	8	14	77	2.57
E856714		3.36	0.017	0.2	0.36	25	<10	100	<0.5	4	0.71	0.9	7	11	109	2.63
E856715		3.47	0.013	<0.2	0.25	34	<10	420	<0.5	<2	0.67	<0.5	8	9	72	1.49
E856716		3.88	0.009	<0.2	0.25	28	<10	560	<0.5	3	0.90	<0.5	7	10	127	1.75
E856717		6.00	<0.005	<0.2	0.36	3	<10	300	<0.5	<2	0.54	<0.5	7	12	57	1.92
E856718		2.81	0.005	0.2	0.53	<2	<10	90	<0.5	4	0.80	0.6	7	14	66	2.94
E856719		2.98	0.006	0.2	0.73	<2	<10	230	<0.5	2	0.37	<0.5	7	14	64	2.42
E856720		1.65	0.009	0.3	0.94	8	<10	180	<0.5	<2	0.61	<0.5	10	17	96	3.49
E856721		1.52	0.072	0.3	1.62	10	<10	240	<0.5	<2	0.16	<0.5	12	25	90	3.75
E856722		1.37	0.075	<0.2	1.84	10	<10	250	<0.5	<2	0.16	<0.5	13	30	53	3.94
E856723		4.03	0.007	0.2	1.50	10	<10	260	<0.5	<2	0.14	<0.5	14	24	75	3.31
E856724		4.83	<0.005	<0.2	1.21	13	<10	250	<0.5	<2	0.47	<0.5	14	22	114	2.76
E856725		1.94	0.219	11.0	0.61	743	<10	180	<0.5	<2	1.08	0.5	12	67	105	4.04
E856726		1.26	0.204	>100	0.50	575	<10	220	<0.5	<2	0.86	0.5	10	69	292	3.37

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102706

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E856705		<10	<1	0.09	10	0.50	2460	1	0.01	25	120	6	0.13	<2	1	48
E856706		<10	1	0.09	10	0.56	1670	<1	0.01	22	170	10	0.13	<2	1	51
E856707		<10	<1	0.09	10	0.62	2720	<1	0.01	24	160	10	0.08	<2	1	75
E856708		<10	1	0.12	10	0.77	3180	1	0.01	25	520	12	0.09	<2	2	83
E856709		<10	<1	0.13	10	0.72	2980	<1	0.01	25	530	8	0.08	<2	2	80
E856710		<10	1	0.33	10	0.11	308	3	0.04	5	670	5060	7.5	1670	1	134
E856711		<10	<1	0.10	10	1.00	8210	1	0.01	16	1510	21	0.11	<2	2	768
E856712		<10	<1	0.12	10	0.78	2710	1	0.01	27	570	5	0.30	<2	2	94
E856713		<10	<1	0.11	10	0.42	1445	5	0.01	32	370	10	0.83	8	1	73
E856714		<10	<1	0.13	10	0.26	579	11	0.01	48	1260	7	1.42	19	1	93
E856715		<10	<1	0.09	10	0.30	545	2	0.01	34	210	5	0.57	22	1	91
E856716		<10	<1	0.09	10	0.46	813	1	0.01	19	170	3	0.42	20	1	115
E856717		<10	<1	0.10	10	0.27	597	2	0.01	30	310	2	0.83	<2	1	78
E856718		<10	<1	0.11	10	0.34	2530	5	0.01	38	1040	11	1.63	<2	1	95
E856719		10	<1	0.09	10	0.43	1395	3	0.01	31	240	7	1.11	3	1	45
E856720		<10	1	0.11	10	0.51	2440	6	0.01	38	630	23	1.62	11	1	64
E856721		<10	1	0.14	20	0.62	1745	1	0.02	39	580	7	0.36	2	2	30
E856722		<10	<1	0.16	20	0.68	1720	1	0.03	43	620	4	0.16	<2	2	32
E856723		<10	<1	0.16	20	0.59	1660	1	0.02	44	500	10	0.26	<2	1	25
E856724		<10	1	0.14	20	0.51	3710	<1	0.02	40	500	9	0.28	4	1	47
E856725		<10	1	0.13	10	0.65	1720	24	0.02	36	360	62	1.41	74	2	108
E856726		<10	<1	0.13	10	0.54	1135	267	0.02	48	310	72	1.04	79	2	100

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102706

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E856705		<20	<0.01	<10	<10	19	<10	37		
E856706		<20	<0.01	<10	<10	19	<10	41		
E856707		<20	<0.01	<10	<10	17	<10	37		
E856708		<20	<0.01	<10	<10	21	<10	45		
E856709		<20	<0.01	<10	<10	20	<10	43		
E856710		<20	<0.01	<10	<10	6	10	>10000	1.280	NSS
E856711		<20	<0.01	<10	<10	18	<10	86		
E856712		<20	<0.01	<10	<10	23	<10	60		
E856713		<20	<0.01	<10	<10	14	<10	65		
E856714		<20	<0.01	<10	<10	16	<10	150		
E856715		<20	<0.01	<10	<10	9	<10	57		
E856716		<20	<0.01	<10	<10	8	<10	40		
E856717		<20	<0.01	<10	<10	12	<10	63		
E856718		<20	<0.01	<10	<10	18	<10	110		
E856719		<20	<0.01	<10	<10	13	<10	66		
E856720		<20	<0.01	<10	<10	22	<10	87		
E856721		<20	0.01	<10	<10	31	<10	105		
E856722		<20	0.01	<10	<10	37	<10	116		
E856723		<20	0.01	<10	<10	28	<10	101		
E856724		<20	0.01	<10	<10	25	<10	74		
E856725		<20	<0.01	<10	<10	8	50	111		
E856726		<20	<0.01	<10	<10	8	60	110		181

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 12-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102706

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-AUG-2010
Account: EIAALN

CERTIFICATE WH10102702

Project: ALN10-01

P.O. No.: ALN-10-01_24

This report is for 69 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 27-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102702

Sample Description	Method	WEI-21	Au-AA23	Au-GRA21	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu
	Units	kg	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.05	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1
E856907		0.98	<0.005		<0.2	0.54	10	<10	130	<0.5	<2	3.30	<0.5	9	8	20
E856908		2.09	<0.005		<0.2	0.45	9	<10	110	<0.5	<2	1.18	<0.5	7	6	12
E856909		<0.02	<0.005		<0.2	0.46	11	<10	120	<0.5	3	1.22	<0.5	8	6	12
E856910		0.07	0.847		>100	0.52	4550	<10	30	<0.5	8	0.55	100.5	6	51	302
E856911		2.25	<0.005		<0.2	0.45	10	<10	130	<0.5	<2	0.87	<0.5	9	8	14
E856912		2.07	<0.005		<0.2	0.36	16	<10	110	<0.5	2	1.10	<0.5	6	5	7
E856913		2.15	<0.005		0.2	0.45	17	<10	120	<0.5	2	0.84	<0.5	8	7	16
E856914		2.38	0.005		<0.2	0.37	34	<10	100	<0.5	<2	2.11	<0.5	5	4	8
E856915		2.31	<0.005		0.2	0.38	11	<10	110	<0.5	2	1.90	<0.5	3	5	8
E856916		1.73	<0.005		<0.2	0.36	11	<10	110	<0.5	<2	2.17	<0.5	3	5	4
E856917		1.33	<0.005		<0.2	0.35	8	<10	110	<0.5	<2	1.59	<0.5	3	6	4
E856918		1.54	0.007		<0.2	0.30	94	<10	110	<0.5	<2	7.7	<0.5	3	3	5
E856919		1.13	0.007		<0.2	0.22	74	<10	70	<0.5	2	18.9	<0.5	4	3	6
E856920		0.84	0.024		0.2	0.29	130	<10	80	<0.5	<2	12.8	<0.5	4	4	9
E856921		0.41	0.018		0.2	0.35	58	<10	60	<0.5	2	2.07	<0.5	4	6	10
E856922		0.41	0.010		0.2	0.36	76	<10	60	<0.5	<2	1.52	<0.5	3	5	10
E856923		1.44	0.008		<0.2	0.90	41	<10	100	<0.5	4	0.16	<0.5	18	12	48
E856924		2.11	<0.005		0.2	2.04	26	<10	110	<0.5	5	0.12	<0.5	20	25	48
E856925		2.51	<0.005		<0.2	1.01	14	<10	100	<0.5	4	0.47	<0.5	9	12	31
E856926		1.58	0.006		<0.2	0.76	49	<10	70	<0.5	4	0.44	<0.5	13	8	25
E856927		2.04	0.105		0.2	0.95	848	<10	70	<0.5	3	0.60	<0.5	14	13	22
E856928		1.63	0.037		<0.2	0.73	482	<10	70	<0.5	3	0.56	<0.5	8	8	16
E856929		<0.02	0.035		<0.2	0.73	437	<10	70	<0.5	2	0.59	<0.5	7	8	16
E856930		0.05	0.007		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	1
E856931		2.13	0.020		<0.2	0.51	122	<10	70	<0.5	<2	0.55	<0.5	7	7	15
E856932		1.80	0.006		0.2	0.46	65	<10	70	<0.5	<2	0.49	<0.5	8	6	16
E856933		1.91	0.576		0.2	0.48	1700	<10	70	<0.5	2	0.56	<0.5	7	8	17
E856934		2.06	2.55	2.63	0.3	0.35	5520	<10	60	<0.5	<2	1.05	<0.5	4	5	8
E856935		2.07	1.255	1.33	<0.2	0.40	3270	<10	70	<0.5	2	0.90	<0.5	6	7	11
E856936		1.97	0.722		0.7	0.36	4570	<10	70	<0.5	<2	1.14	<0.5	4	5	12
E856937		1.35	1.290	1.33	0.7	0.45	9800	<10	70	<0.5	3	1.81	<0.5	12	6	28
E856938		0.82	0.949		0.9	0.49	>10000	<10	90	<0.5	<2	2.19	0.5	12	6	21
E856939		1.57	0.388		0.4	0.49	2260	<10	80	<0.5	3	2.37	<0.5	7	8	11
E856940		1.73	0.009		<0.2	0.38	65	<10	70	<0.5	<2	1.36	<0.5	9	6	15
E856941		1.29	0.022		<0.2	0.40	238	<10	70	<0.5	<2	3.55	<0.5	5	7	9
E856942		1.33	0.027		<0.2	0.39	197	<10	70	<0.5	<2	3.98	<0.5	6	5	9
E856943		2.58	<0.005		<0.2	0.45	19	<10	70	<0.5	<2	1.58	<0.5	7	8	12
E856944		3.07	0.005		<0.2	0.46	19	<10	80	<0.5	<2	5.75	<0.5	6	6	11
E856945		2.86	<0.005		<0.2	0.75	6	<10	100	<0.5	<2	2.39	<0.5	7	9	12
E856946		2.12	<0.005		<0.2	0.61	7	<10	70	<0.5	<2	2.48	<0.5	5	8	8

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102702

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856907		3.30	<10	<1	0.21	10	0.74	886	<1	0.02	19	180	28	0.03	18	2
E856908		2.30	<10	<1	0.19	10	0.43	518	<1	0.02	15	150	23	0.09	10	1
E856909		2.39	<10	<1	0.19	10	0.45	537	<1	0.02	15	150	23	0.09	12	1
E856910		5.92	<10	1	0.32	10	0.10	301	2	0.04	6	660	5100	7.6	1910	1
E856911		2.31	<10	<1	0.22	20	0.41	391	<1	0.02	16	160	21	0.15	6	1
E856912		1.73	<10	<1	0.22	20	0.41	405	<1	0.03	9	120	24	0.06	5	1
E856913		1.98	<10	<1	0.27	20	0.29	283	<1	0.03	17	310	24	0.09	8	1
E856914		1.54	<10	<1	0.24	20	0.67	349	<1	0.02	9	170	25	0.06	9	1
E856915		1.38	<10	<1	0.25	20	0.58	354	<1	0.02	7	150	24	0.06	10	1
E856916		1.14	<10	<1	0.22	20	0.65	309	<1	0.02	4	130	18	0.03	8	1
E856917		0.91	<10	<1	0.21	20	0.50	227	<1	0.02	4	130	17	0.03	8	1
E856918		1.21	<10	<1	0.17	10	0.65	495	<1	0.02	5	150	19	0.08	6	1
E856919		1.13	<10	<1	0.12	<10	0.55	548	<1	0.02	8	210	18	<0.01	7	1
E856920		1.66	<10	<1	0.17	<10	0.61	579	<1	0.02	9	220	14	0.23	6	2
E856921		3.15	<10	<1	0.17	10	0.99	836	<1	0.02	8	90	15	0.12	11	1
E856922		3.10	<10	<1	0.17	10	0.85	743	<1	0.01	10	70	15	0.10	11	1
E856923		4.70	<10	<1	0.26	20	0.94	469	<1	0.03	39	280	13	0.24	25	2
E856924		6.25	<10	<1	0.28	20	1.15	390	<1	0.04	44	280	6	0.21	9	2
E856925		3.26	<10	<1	0.26	20	0.65	499	<1	0.04	25	720	19	0.10	8	2
E856926		3.74	<10	<1	0.24	20	0.78	616	<1	0.03	29	310	17	0.16	16	2
E856927		3.85	<10	<1	0.24	10	0.79	667	<1	0.03	28	150	5	0.33	17	2
E856928		2.71	<10	<1	0.24	10	0.52	520	<1	0.03	19	90	9	0.22	6	1
E856929		2.69	<10	<1	0.24	10	0.52	530	<1	0.04	20	90	9	0.21	8	1
E856930		0.02	<10	1	<0.01	<10	0.01	<5	<1	<0.01	<1	10	<2	0.03	<2	<1
E856931		3.34	<10	<1	0.22	10	0.62	737	<1	0.03	19	290	8	0.22	10	1
E856932		2.59	<10	<1	0.23	10	0.55	645	<1	0.02	21	180	6	0.14	9	1
E856933		2.62	<10	<1	0.24	10	0.53	591	<1	0.02	21	130	10	0.43	18	1
E856934		1.60	<10	<1	0.19	10	0.39	607	<1	0.02	11	40	4	0.83	10	1
E856935		1.87	<10	<1	0.20	10	0.38	595	<1	0.03	14	70	10	0.79	14	1
E856936		1.84	<10	<1	0.20	10	0.41	515	<1	0.02	12	70	12	0.99	15	1
E856937		3.38	<10	<1	0.25	10	0.72	726	<1	0.02	28	230	12	2.10	32	2
E856938		3.56	<10	<1	0.26	<10	0.78	584	<1	0.02	32	610	8	2.27	35	2
E856939		2.12	<10	<1	0.24	10	0.53	448	<1	0.02	14	260	26	0.83	21	2
E856940		2.34	<10	<1	0.27	10	0.54	290	1	0.02	17	190	33	0.22	17	1
E856941		1.77	<10	<1	0.27	10	0.38	369	1	0.03	11	170	15	0.27	8	1
E856942		1.88	<10	1	0.27	10	0.43	395	<1	0.02	11	180	19	0.28	9	1
E856943		2.29	<10	<1	0.30	20	0.57	304	<1	0.04	13	190	20	0.15	5	2
E856944		1.77	<10	<1	0.33	10	0.35	421	<1	0.04	10	170	21	0.25	<2	2
E856945		1.96	<10	<1	0.35	20	0.43	330	<1	0.04	13	190	21	0.21	2	1
E856946		1.50	<10	<1	0.23	20	0.33	253	<1	0.03	9	140	14	0.11	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102702

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856907		117	<20	<0.01	<10	<10	4	<10	48			
E856908		53	<20	<0.01	<10	<10	3	<10	56			
E856909		56	<20	<0.01	<10	<10	3	<10	57			
E856910		135	<20	<0.01	<10	<10	5	20	>10000		1.305	NSS
E856911		44	20	<0.01	<10	<10	3	<10	55			
E856912		45	<20	<0.01	<10	<10	3	<10	42			
E856913		36	<20	<0.01	<10	<10	4	<10	59			
E856914		75	<20	<0.01	<10	<10	2	<10	30			
E856915		59	20	<0.01	<10	<10	2	<10	35			
E856916		64	<20	<0.01	<10	<10	2	<10	23			
E856917		39	<20	<0.01	<10	<10	2	<10	19			
E856918		299	<20	<0.01	<10	<10	1	<10	22			
E856919		1140	<20	<0.01	<10	10	2	<10	38			
E856920		594	<20	<0.01	<10	<10	2	<10	50			
E856921		109	<20	<0.01	<10	<10	3	<10	42			
E856922		82	<20	<0.01	<10	<10	3	<10	35			
E856923		13	<20	<0.01	<10	<10	7	<10	90			
E856924		11	<20	0.01	10	<10	15	<10	120			
E856925		28	<20	<0.01	<10	<10	7	<10	71			
E856926		25	<20	<0.01	<10	<10	6	<10	77			
E856927		50	<20	<0.01	<10	<10	7	<10	72			
E856928		32	<20	<0.01	<10	<10	5	<10	55			
E856929		33	<20	<0.01	<10	<10	5	<10	56			
E856930		<1	<20	<0.01	<10	<10	<1	<10	4			
E856931		28	<20	<0.01	<10	<10	4	<10	44			
E856932		28	<20	<0.01	<10	<10	3	<10	34			
E856933		42	<20	<0.01	<10	<10	4	<10	57			
E856934		104	<20	<0.01	<10	<10	2	<10	29			
E856935		76	<20	<0.01	<10	<10	3	<10	41			
E856936		102	<20	<0.01	<10	<10	2	<10	36			
E856937		173	<20	<0.01	<10	<10	3	<10	76			
E856938		168	<20	<0.01	<10	<10	4	<10	55			
E856939		135	<20	<0.01	<10	<10	3	<10	37			
E856940		57	<20	<0.01	<10	<10	3	<10	60			
E856941		165	<20	<0.01	<10	<10	3	<10	32			
E856942		176	<20	<0.01	<10	<10	3	<10	33			
E856943		67	<20	<0.01	<10	<10	4	<10	51			
E856944		251	<20	<0.01	<10	<10	4	<10	32			
E856945		108	<20	<0.01	<10	<10	5	<10	35			
E856946		105	<20	<0.01	<10	<10	4	<10	69			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102702

Sample Description	Method	WEI-21	Au-AA23	Au-GRA21	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu
	Units	kg	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.05	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1
E856947		2.35	0.006		0.3	0.44	29	<10	70	<0.5	<2	4.19	<0.5	6	6	12
E856948		1.99	<0.005		0.2	1.26	11	<10	70	<0.5	<2	1.17	<0.5	13	15	27
E856949		<0.02	<0.005		0.2	1.18	10	<10	60	<0.5	<2	1.08	<0.5	9	13	27
E856950		0.07	1.595	NSS	>100	0.37	4610	<10	30	<0.5	7	0.81	526	6	53	902
E856951		2.66	<0.005		1.2	1.60	13	<10	90	<0.5	<2	0.50	1.1	10	17	33
E856952		0.93	<0.005		0.2	0.58	8	<10	80	<0.5	<2	0.63	<0.5	7	8	7
E856953		3.30	<0.005		<0.2	0.98	5	<10	90	<0.5	<2	0.82	<0.5	8	18	16
E856954		3.20	<0.005		0.2	0.89	4	<10	90	<0.5	<2	0.57	<0.5	8	18	22
E856955		2.41	<0.005		0.2	1.20	2	<10	100	<0.5	<2	0.43	<0.5	14	17	39
E856956		2.51	<0.005		0.2	1.55	<2	<10	100	<0.5	<2	0.33	<0.5	16	16	43
E856957		2.47	0.013		0.4	1.15	207	<10	100	<0.5	<2	0.28	<0.5	14	16	46
E856958		2.49	<0.005		0.3	1.42	24	<10	140	<0.5	<2	0.45	<0.5	13	15	40
E856959		2.96	<0.005		0.4	1.00	<2	<10	130	<0.5	<2	0.19	<0.5	12	12	26
E856960		1.92	<0.005		0.2	1.13	<2	<10	130	<0.5	<2	0.11	<0.5	13	12	32
E856961		1.19	<0.005		<0.2	1.17	<2	<10	110	<0.5	<2	0.27	<0.5	16	14	36
E856962		1.24	<0.005		0.3	1.08	<2	<10	120	<0.5	<2	0.27	<0.5	15	14	35
E856963		1.68	<0.005		0.3	1.33	<2	<10	90	<0.5	<2	0.32	<0.5	14	18	43
E856964		1.98	<0.005		<0.2	0.91	2	<10	160	<0.5	<2	0.81	<0.5	9	12	21
E856965		1.78	0.005		0.4	1.18	5	<10	70	<0.5	<2	0.75	<0.5	11	15	27
E856966		1.64	<0.005		<0.2	1.26	4	<10	70	<0.5	<2	0.35	<0.5	9	18	22
E856967		2.89	<0.005		0.3	1.41	6	<10	60	<0.5	<2	0.54	<0.5	14	18	31
E856968		1.88	<0.005		<0.2	1.11	5	<10	70	<0.5	<2	0.21	<0.5	9	15	19
E856969		<0.02	0.005		0.2	1.08	5	<10	60	<0.5	<2	0.15	<0.5	8	14	19
E856970		0.04	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1
E856971		1.91	<0.005		<0.2	1.03	2	<10	60	<0.5	<2	0.12	<0.5	7	12	17
E856972		2.03	<0.005		0.2	1.10	6	<10	70	<0.5	<2	0.33	<0.5	8	14	18
E856973		2.09	<0.005		0.2	1.06	2	<10	60	<0.5	<2	0.89	<0.5	9	13	20
E856974		2.10	<0.005		0.3	1.47	<2	<10	60	<0.5	<2	0.27	<0.5	12	17	33
E856975		2.16	<0.005		<0.2	1.49	6	<10	50	<0.5	<2	0.32	<0.5	12	18	25

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102702

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856947		1.77	<10	1	0.21	10	0.41	477	<1	0.03	10	140	19	0.22	<2	1
E856948		3.04	<10	1	0.23	20	0.68	694	<1	0.03	23	610	16	0.13	<2	2
E856949		2.92	<10	1	0.20	20	0.65	651	<1	0.02	21	550	18	0.12	2	1
E856950		6.61	<10	4	0.24	10	0.25	373	<1	0.02	2	560	>10000	10.0	2560	1
E856951		3.30	<10	1	0.26	20	0.71	618	<1	0.03	27	350	60	0.17	4	1
E856952		1.39	<10	<1	0.17	10	0.31	383	<1	0.02	10	270	11	0.03	6	1
E856953		2.56	<10	1	0.18	10	0.55	600	<1	0.03	18	370	11	0.16	4	2
E856954		2.74	<10	1	0.20	10	0.50	514	<1	0.03	18	210	20	0.54	<2	2
E856955		3.36	<10	1	0.25	10	0.57	556	<1	0.02	29	290	17	0.82	<2	1
E856956		4.03	<10	1	0.25	10	0.70	464	<1	0.03	34	250	19	0.93	<2	1
E856957		3.31	<10	1	0.22	10	0.50	417	<1	0.03	30	330	15	0.89	<2	2
E856958		3.89	<10	1	0.23	10	0.67	596	<1	0.02	28	250	12	0.92	3	2
E856959		2.75	<10	1	0.21	10	0.39	397	<1	0.03	20	170	20	0.79	<2	1
E856960		3.08	<10	1	0.23	10	0.40	354	<1	0.04	28	120	14	0.95	<2	1
E856961		3.27	<10	1	0.21	10	0.47	420	<1	0.03	29	250	14	0.86	<2	1
E856962		3.07	<10	2	0.22	10	0.43	439	<1	0.04	29	220	17	0.79	<2	1
E856963		3.65	<10	2	0.21	10	0.56	485	<1	0.02	30	320	16	0.86	<2	1
E856964		2.55	<10	1	0.18	10	0.50	610	<1	0.03	16	210	10	0.51	<2	1
E856965		3.06	<10	1	0.22	10	0.63	789	<1	0.03	25	270	16	0.32	<2	2
E856966		2.75	<10	<1	0.20	10	0.54	670	<1	0.02	22	380	15	0.07	<2	1
E856967		3.44	<10	1	0.21	10	0.67	857	<1	0.02	27	370	21	0.23	2	2
E856968		2.30	<10	1	0.20	10	0.40	351	<1	0.02	17	570	18	0.08	<2	1
E856969		2.28	<10	1	0.18	10	0.39	360	<1	0.02	17	280	13	0.11	2	1
E856970		0.02	<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	2	0.03	<2	<1
E856971		2.13	<10	1	0.17	10	0.35	391	<1	0.02	13	260	20	0.09	<2	1
E856972		2.16	<10	<1	0.19	10	0.46	336	<1	0.02	18	120	13	0.06	<2	1
E856973		2.45	<10	1	0.18	10	0.60	493	<1	0.02	15	340	14	0.25	<2	1
E856974		3.11	10	<1	0.23	10	0.61	383	<1	0.02	24	310	12	0.32	<2	1
E856975		3.14	10	1	0.21	10	0.66	427	<1	0.02	25	240	13	0.34	<2	2

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102702

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856947		177	20	<0.01	<10	<10	2	<10	27			
E856948		50	<20	<0.01	<10	<10	7	<10	63			
E856949		45	<20	<0.01	<10	<10	6	<10	59			
E856950		113	<20	<0.01	10	<10	4	10	>10000	1.945	3.79	325
E856951		26	<20	<0.01	<10	<10	9	<10	99			
E856952		27	<20	<0.01	<10	<10	2	<10	24			
E856953		37	<20	<0.01	<10	<10	8	<10	50			
E856954		24	<20	<0.01	<10	<10	7	<10	53			
E856955		18	<20	<0.01	<10	<10	8	<10	63			
E856956		17	<20	<0.01	<10	<10	10	<10	81			
E856957		17	<20	<0.01	<10	<10	8	<10	59			
E856958		21	<20	<0.01	<10	<10	10	<10	75			
E856959		11	<20	<0.01	<10	<10	6	<10	50			
E856960		9	<20	<0.01	<10	<10	6	<10	63			
E856961		15	<20	<0.01	<10	<10	8	<10	64			
E856962		15	<20	<0.01	<10	<10	6	<10	66			
E856963		19	<20	<0.01	<10	<10	7	<10	61			
E856964		32	<20	<0.01	<10	<10	5	<10	44			
E856965		31	<20	<0.01	<10	<10	7	<10	54			
E856966		17	<20	<0.01	<10	<10	7	<10	50			
E856967		22	<20	<0.01	<10	<10	9	<10	65			
E856968		12	<20	<0.01	<10	<10	6	<10	48			
E856969		11	<20	<0.01	<10	<10	6	<10	49			
E856970		<1	<20	<0.01	<10	<10	<1	<10	2			
E856971		9	<20	<0.01	<10	<10	6	<10	38			
E856972		16	<20	<0.01	<10	<10	5	<10	45			
E856973		38	<20	<0.01	<10	<10	6	<10	43			
E856974		17	<20	<0.01	10	<10	9	<10	61			
E856975		18	<20	<0.01	<10	<10	10	<10	62			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 10-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102702

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

CERTIFICATE WH10095961

Project: ALN10-01

P.O. No.: ALN-10_15

This report is for 100 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 14-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E858138		2.02	0.005		<0.2	0.63	48	<10	40	<0.5	<2	2.40	<0.5	3	7	3
E858139		1.43	<0.005		<0.2	0.78	126	<10	50	<0.5	<2	2.87	<0.5	3	8	2
E858140		1.51	<0.005		<0.2	0.79	32	<10	10	<0.5	<2	17.0	<0.5	1	5	2
E858141		0.40	<0.005		0.2	3.68	404	<10	10	<0.5	<2	14.3	<0.5	9	25	21
E858142		0.52	<0.005		<0.2	4.80	98	<10	10	<0.5	2	14.4	<0.5	10	29	7
E858143		1.49	<0.005		<0.2	2.62	59	<10	30	<0.5	<2	13.3	<0.5	5	16	4
E858144		2.82	<0.005		<0.2	0.87	9	<10	10	<0.5	<2	18.8	<0.5	2	5	<1
E858145		1.89	<0.005		<0.2	0.74	141	<10	40	<0.5	<2	8.7	<0.5	6	7	4
E858146		1.83	0.017		<0.2	0.35	142	<10	60	<0.5	<2	5.40	<0.5	4	4	8
E858147		2.44	0.009		0.3	0.48	56	<10	40	<0.5	<2	5.34	<0.5	4	6	4
E858148		1.88	0.006		<0.2	0.29	17	<10	50	<0.5	<2	5.94	<0.5	3	4	11
E858149		<0.02	0.006		<0.2	0.24	15	<10	40	<0.5	<2	5.82	<0.5	3	4	12
E858150		0.08	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.02	<0.5	<1	<1	<1
E858151		1.95	0.005		0.4	0.37	59	<10	60	<0.5	<2	4.35	<0.5	6	4	8
E858152		2.55	0.005		<0.2	0.35	18	<10	60	<0.5	<2	4.42	<0.5	5	5	6
E858153		2.21	<0.005		<0.2	0.62	8	<10	50	<0.5	<2	3.96	<0.5	7	7	13
E858154		1.80	<0.005		<0.2	1.32	24	<10	30	<0.5	<2	9.4	<0.5	3	9	2
E858155		2.40	0.005		<0.2	0.43	143	<10	50	<0.5	<2	4.05	<0.5	5	6	5
E858156		2.16	0.007		<0.2	0.27	51	<10	40	<0.5	<2	2.58	<0.5	3	5	3
E858157		2.51	0.008		0.2	0.33	127	<10	60	<0.5	<2	9.5	<0.5	4	4	11
E858158		2.53	0.011		<0.2	0.24	87	<10	40	<0.5	<2	11.3	<0.5	5	31	20
E858159		2.03	<0.005		<0.2	0.46	91	<10	70	<0.5	<2	2.28	<0.5	4	7	3
E858160		0.69	0.010		0.8	0.44	133	<10	90	<0.5	<2	0.33	<0.5	9	5	21
E858161		1.05	0.020		0.3	0.39	281	<10	80	<0.5	<2	2.41	<0.5	4	7	7
E858162		0.91	0.021		0.4	0.46	287	<10	100	<0.5	<2	1.18	<0.5	6	6	9
E858163		1.92	0.086		<0.2	0.40	1750	<10	80	<0.5	<2	2.47	<0.5	4	6	7
E858164		1.58	0.336		0.6	0.35	4530	<10	70	<0.5	<2	2.17	<0.5	6	4	10
E858165		2.61	0.678		0.3	0.43	7600	<10	80	<0.5	<2	3.26	<0.5	7	5	11
E858166		2.34	0.559		0.4	0.34	2390	<10	80	<0.5	<2	3.76	<0.5	3	5	6
E858167		2.47	0.128		<0.2	0.30	647	<10	60	<0.5	<2	12.4	<0.5	4	3	3
E858168		2.34	0.530		<0.2	0.13	1835	<10	40	<0.5	<2	>25.0	<0.5	1	1	<1
E858169		<0.02	0.513		<0.2	0.14	1870	<10	40	<0.5	<2	>25.0	<0.5	1	1	<1
E858170		0.07	1.670	NSS	>100	0.37	4620	<10	20	<0.5	9	0.88	522	5	54	862
E858171		2.02	0.011		0.7	0.36	159	<10	80	<0.5	<2	10.9	0.6	4	4	8
E858172		1.67	<0.005		<0.2	0.19	6	<10	30	<0.5	<2	10.8	<0.5	2	3	2
E858173		2.53	<0.005		<0.2	0.40	26	<10	70	<0.5	<2	2.66	<0.5	6	6	16
E858174		2.47	0.273		<0.2	0.44	4320	<10	60	<0.5	<2	1.45	<0.5	7	8	18
E858175		1.56	0.112		<0.2	0.44	1570	<10	70	<0.5	<2	1.44	<0.5	8	7	19
E858176		2.14	0.022		<0.2	0.49	214	<10	70	<0.5	<2	1.60	<0.5	7	7	14
E858177		2.67	0.011		<0.2	0.29	123	<10	40	<0.5	<2	1.86	<0.5	3	7	4

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E858138		1.56	<10	<1	0.14	20	0.67	406	<1	0.03	3	140	12	0.02	<2	1
E858139		1.52	<10	<1	0.13	20	0.59	464	<1	0.03	4	200	20	0.01	<2	1
E858140		2.69	<10	<1	0.03	10	6.78	1575	<1	0.02	2	610	24	<0.01	<2	2
E858141		5.48	10	<1	0.02	10	6.72	1940	<1	0.02	15	750	115	0.02	3	5
E858142		5.97	10	<1	0.02	10	6.98	2230	<1	0.02	16	720	107	0.01	<2	6
E858143		3.74	10	<1	0.07	10	5.75	1740	<1	0.02	10	650	55	0.01	<2	3
E858144		2.96	<10	<1	0.02	10	7.66	2220	<1	0.02	2	650	10	<0.01	<2	2
E858145		2.02	<10	<1	0.15	10	3.01	1080	<1	0.02	7	140	16	0.20	8	2
E858146		1.77	<10	<1	0.20	10	1.71	739	<1	0.02	3	190	22	0.13	13	1
E858147		1.80	<10	<1	0.14	10	1.91	722	<1	0.03	4	130	23	0.19	5	1
E858148		1.89	<10	<1	0.17	10	2.23	697	<1	0.03	3	150	24	0.52	9	1
E858149		2.04	<10	<1	0.14	10	2.25	721	1	0.03	4	150	21	0.51	9	1
E858150		0.02	<10	<1	<0.01	<10	0.01	<5	<1	0.01	<1	10	2	0.01	<2	<1
E858151		1.56	<10	<1	0.20	10	1.39	508	<1	0.03	7	140	19	0.30	4	1
E858152		1.65	<10	<1	0.20	10	1.56	551	1	0.03	6	160	16	0.37	<2	1
E858153		1.76	<10	<1	0.17	10	1.38	550	<1	0.03	8	210	29	0.23	<2	1
E858154		2.97	<10	<1	0.08	10	3.27	1505	<1	0.04	4	150	30	0.03	<2	2
E858155		1.65	<10	<1	0.16	10	1.20	606	<1	0.03	6	140	26	0.07	3	2
E858156		1.06	<10	<1	0.16	10	0.87	328	<1	0.03	2	110	15	0.05	2	1
E858157		2.06	<10	<1	0.19	10	3.85	985	<1	0.03	6	190	29	0.24	7	1
E858158		1.80	<10	<1	0.14	10	4.42	1090	<1	0.02	9	260	17	0.03	4	1
E858159		2.12	<10	<1	0.24	10	0.78	497	<1	0.03	10	180	9	0.05	4	1
E858160		1.68	<10	<1	0.29	10	0.20	116	<1	0.02	17	280	19	0.24	14	1
E858161		2.17	<10	<1	0.23	10	0.57	644	<1	0.02	7	180	11	0.20	8	1
E858162		1.51	<10	<1	0.31	10	0.34	321	<1	0.02	9	200	10	0.20	7	1
E858163		2.41	<10	<1	0.24	10	0.57	612	<1	0.02	8	120	13	0.36	12	1
E858164		2.44	<10	<1	0.24	<10	0.77	543	<1	0.01	10	170	18	1.01	17	1
E858165		2.72	<10	<1	0.25	<10	0.72	422	<1	0.02	13	180	24	1.71	27	1
E858166		2.56	<10	<1	0.20	10	1.26	1215	<1	0.02	4	120	12	0.61	8	1
E858167		1.40	<10	<1	0.19	10	0.85	1100	<1	0.02	4	200	17	0.25	2	1
E858168		1.64	<10	<1	0.08	<10	0.80	1720	<1	0.02	1	450	5	<0.01	<2	1
E858169		1.70	<10	<1	0.08	<10	0.80	1740	1	0.02	<1	450	5	<0.01	<2	1
E858170		7.18	<10	2	0.25	10	0.26	377	1	0.03	4	560	>10000	9.9	2760	1
E858171		1.79	<10	<1	0.28	10	0.58	588	<1	0.02	6	370	44	0.08	11	2
E858172		1.00	<10	<1	0.13	10	0.90	759	<1	0.02	2	210	15	0.04	<2	1
E858173		2.21	<10	1	0.27	10	1.10	518	<1	0.01	13	280	22	0.10	2	2
E858174		2.74	<10	<1	0.24	10	0.51	455	<1	0.01	15	290	32	1.10	14	2
E858175		2.45	<10	1	0.27	10	0.70	317	<1	0.01	19	430	15	0.61	13	2
E858176		2.48	<10	<1	0.28	10	0.80	484	<1	0.02	16	200	19	0.23	7	2
E858177		1.39	<10	<1	0.18	10	0.64	417	<1	0.01	8	100	15	0.08	4	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E858138		64	<20	<0.01	<10	<10	4	<10	24			
E858139		73	<20	<0.01	<10	<10	5	<10	32			
E858140		775	<20	<0.01	<10	<10	5	<10	37			
E858141		444	20	0.01	<10	<10	28	<10	147			
E858142		484	20	0.01	<10	<10	39	<10	192			
E858143		528	<20	<0.01	<10	<10	18	<10	112			
E858144		680	<20	<0.01	<10	10	6	<10	50			
E858145		331	<20	<0.01	<10	<10	5	<10	58			
E858146		172	<20	<0.01	<10	<10	2	<10	27			
E858147		185	<20	<0.01	<10	<10	3	<10	40			
E858148		194	<20	<0.01	<10	<10	1	<10	20			
E858149		198	<20	<0.01	<10	<10	1	<10	20			
E858150		<1	<20	<0.01	<10	<10	<1	<10	2			
E858151		167	<20	<0.01	<10	<10	2	<10	24			
E858152		160	<20	<0.01	<10	<10	2	<10	31			
E858153		158	<20	<0.01	<10	<10	4	<10	37			
E858154		366	<20	<0.01	<10	<10	8	<10	72			
E858155		143	<20	<0.01	<10	<10	4	<10	37			
E858156		97	<20	<0.01	<10	<10	2	<10	19			
E858157		315	<20	<0.01	<10	<10	2	<10	31			
E858158		383	<20	0.01	<10	<10	8	<10	27			
E858159		75	<20	<0.01	<10	<10	3	<10	41			
E858160		13	<20	<0.01	<10	<10	3	<10	40			
E858161		86	<20	<0.01	<10	<10	2	<10	28			
E858162		46	<20	<0.01	<10	<10	3	<10	28			
E858163		75	<20	<0.01	<10	<10	2	<10	39			
E858164		95	<20	<0.01	<10	<10	2	<10	47			
E858165		187	<20	<0.01	<10	<10	3	<10	57			
E858166		136	<20	<0.01	<10	<10	2	<10	24			
E858167		513	<20	<0.01	<10	<10	1	<10	21			
E858168		618	<20	<0.01	<10	10	<1	<10	7			
E858169		610	<20	<0.01	<10	10	<1	<10	7			
E858170		116	<20	<0.01	<10	<10	5	20	>10000	1.860	3.56	313
E858171		264	<20	<0.01	<10	<10	2	<10	128			
E858172		366	<20	<0.01	<10	<10	1	<10	16			
E858173		109	<20	<0.01	<10	<10	3	<10	47			
E858174		84	<20	<0.01	<10	<10	3	<10	48			
E858175		95	<20	<0.01	<10	<10	3	<10	55			
E858176		94	<20	<0.01	<10	<10	4	<10	52			
E858177		112	<20	<0.01	<10	<10	2	<10	32			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E858178		2.28	<0.005		<0.2	0.29	29	<10	40	<0.5	<2	1.62	<0.5	3	7	2
E858179		2.25	<0.005		<0.2	0.45	43	<10	100	<0.5	<2	0.93	<0.5	9	6	13
E858180		2.62	<0.005		<0.2	0.98	13	<10	70	<0.5	<2	0.48	<0.5	9	11	15
E858181		1.13	<0.005		<0.2	0.83	15	<10	60	<0.5	<2	1.28	<0.5	5	9	8
E858182		1.66	<0.005		<0.2	0.75	9	<10	50	<0.5	<2	0.87	<0.5	4	9	7
E858183		1.48	<0.005		<0.2	1.13	10	<10	70	<0.5	<2	0.22	<0.5	9	13	14
E858184		2.51	<0.005		<0.2	0.60	26	<10	70	<0.5	<2	2.15	<0.5	7	7	18
E858185		3.28	0.015		<0.2	0.69	142	<10	80	<0.5	<2	1.14	<0.5	9	7	18
E858186		2.24	0.091		<0.2	0.59	461	<10	50	<0.5	2	2.57	<0.5	5	8	10
E858187		2.11	0.021		<0.2	0.86	198	<10	80	<0.5	<2	1.34	<0.5	8	12	33
E858188		0.97	0.014		<0.2	0.74	785	<10	100	<0.5	<2	0.61	<0.5	12	9	28
E858189		<0.02	0.011		<0.2	0.72	803	<10	100	<0.5	<2	0.59	<0.5	12	9	27
E858190		0.07	<0.005		0.3	0.01	<2	<10	<10	<0.5	2	0.01	<0.5	<1	<1	1
E858191		0.94	0.070		<0.2	0.68	2150	<10	90	<0.5	2	0.61	<0.5	15	9	51
E858192		0.55	0.015		<0.2	0.57	192	<10	60	<0.5	<2	0.78	<0.5	6	9	30
E858193		0.92	<0.005		<0.2	0.69	35	<10	50	<0.5	<2	2.05	<0.5	3	7	4
E858194		1.22	<0.005		<0.2	0.72	36	<10	50	<0.5	<2	2.67	<0.5	3	7	2
E858195		2.00	<0.005		<0.2	0.82	49	<10	50	<0.5	<2	2.17	<0.5	2	8	4
E858196		1.29	<0.005		0.4	1.89	192	<10	40	<0.5	<2	4.19	<0.5	8	18	3
E858197		1.48	<0.005		<0.2	1.80	411	<10	60	<0.5	<2	6.34	<0.5	6	12	6
E858198		1.85	<0.005		<0.2	2.34	36	<10	60	<0.5	2	12.4	<0.5	5	14	8
E858199		2.29	0.006		<0.2	1.65	71	<10	10	<0.5	<2	18.2	<0.5	5	6	<1
E858200		2.07	0.016		<0.2	0.55	135	<10	40	<0.5	<2	8.1	<0.5	3	5	5
E858201		1.22	0.014		0.2	0.28	70	<10	50	<0.5	<2	5.27	<0.5	5	3	8
E858202		1.11	0.014		<0.2	0.29	91	<10	50	<0.5	<2	5.28	<0.5	5	4	8
E858203		2.38	<0.005		<0.2	0.40	10	<10	40	<0.5	<2	11.4	<0.5	3	4	4
E858204		1.77	0.005		<0.2	1.44	41	<10	60	<0.5	<2	4.66	<0.5	6	12	13
E858205		1.88	<0.005		<0.2	0.61	21	<10	70	<0.5	<2	5.69	<0.5	7	5	12
E858206		1.41	0.005		<0.2	0.51	32	<10	80	<0.5	<2	4.31	<0.5	5	5	10
E858207		1.99	<0.005		<0.2	0.74	56	<10	50	<0.5	<2	4.47	<0.5	6	8	7
E858208		2.04	0.005		0.2	1.03	241	<10	50	<0.5	<2	3.41	<0.5	9	10	14
E858209		<0.02	0.005		0.3	0.97	234	<10	50	<0.5	<2	3.32	<0.5	9	10	40
E858210		0.07	0.009		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	1
E858211		2.09	0.006		<0.2	0.30	262	<10	50	<0.5	<2	6.27	<0.5	3	5	4
E858212		2.57	0.017		0.3	0.21	148	<10	40	<0.5	<2	4.79	<0.5	2	5	2
E858213		2.13	0.031		<0.2	0.23	280	<10	40	<0.5	<2	5.45	<0.5	3	4	6
E858214		2.20	0.044		<0.2	0.25	232	<10	50	<0.5	<2	11.8	<0.5	4	3	6
E858215		1.13	<0.005		0.2	0.37	271	<10	50	<0.5	<2	3.55	<0.5	7	5	8
E858216		1.29	0.026		0.6	0.41	380	<10	80	<0.5	<2	2.24	<0.5	6	6	14
E858217		0.84	0.442		<0.2	0.24	2530	<10	60	<0.5	<2	4.03	<0.5	2	5	2

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E858178		1.08	<10	<1	0.17	10	0.51	379	<1	0.01	4	130	10	0.01	2	1
E858179		1.71	<10	<1	0.26	20	0.47	296	<1	0.01	14	170	15	0.18	3	1
E858180		2.28	<10	<1	0.29	20	0.52	195	<1	0.01	18	360	23	0.22	4	1
E858181		1.92	<10	<1	0.22	10	0.53	349	<1	0.01	10	120	15	0.07	2	1
E858182		1.75	<10	<1	0.19	10	0.49	295	<1	0.01	9	190	16	0.05	4	1
E858183		2.75	<10	<1	0.28	20	0.58	168	<1	0.01	19	240	10	0.17	3	1
E858184		2.34	<10	<1	0.30	10	0.54	392	<1	0.01	14	280	14	0.15	3	1
E858185		2.18	<10	<1	0.32	20	0.39	258	<1	0.01	17	340	16	0.24	6	1
E858186		1.79	<10	<1	0.21	10	0.30	473	<1	0.02	11	150	14	0.24	9	1
E858187		3.01	<10	1	0.28	20	0.57	367	<1	0.02	19	200	23	0.35	8	2
E858188		3.67	<10	<1	0.37	20	0.72	300	<1	0.01	26	530	7	0.64	5	2
E858189		3.63	<10	<1	0.37	20	0.72	296	<1	0.01	25	530	8	0.60	7	2
E858190		0.01	<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	1	10	<2	<0.01	<2	<1
E858191		5.04	<10	<1	0.30	20	0.95	336	<1	<0.01	32	440	64	1.17	25	2
E858192		2.54	<10	<1	0.21	20	0.47	447	<1	0.01	15	300	16	0.24	9	2
E858193		1.45	<10	<1	0.16	20	0.63	401	<1	0.02	5	150	10	0.02	<2	1
E858194		1.63	<10	1	0.13	20	0.71	509	<1	0.01	5	140	12	0.01	<2	1
E858195		1.55	<10	<1	0.16	20	0.57	418	<1	0.01	5	160	14	0.01	<2	1
E858196		2.96	10	1	0.09	20	1.27	819	<1	0.01	18	220	55	<0.01	2	3
E858197		2.56	10	<1	0.15	10	1.97	870	<1	0.01	15	280	35	0.01	6	3
E858198		2.91	10	<1	0.17	10	5.21	1505	<1	0.01	14	690	81	0.07	<2	3
E858199		3.16	<10	<1	0.03	<10	6.72	2180	<1	0.01	8	480	17	<0.01	2	2
E858200		1.73	<10	1	0.14	10	2.81	949	<1	<0.01	7	180	19	0.18	9	1
E858201		1.67	<10	<1	0.17	10	1.92	709	<1	<0.01	7	140	13	0.45	7	1
E858202		1.79	<10	<1	0.17	10	1.97	721	<1	0.01	8	170	15	0.56	8	1
E858203		1.98	<10	1	0.15	10	4.83	1215	<1	0.01	9	430	15	0.22	<2	1
E858204		1.92	<10	<1	0.18	10	1.52	699	<1	0.02	10	230	54	0.09	<2	2
E858205		1.99	<10	<1	0.22	10	2.03	736	<1	0.02	9	230	23	0.53	4	1
E858206		2.11	<10	<1	0.24	20	1.05	735	<1	0.03	10	420	39	0.03	11	2
E858207		2.28	<10	<1	0.16	10	1.47	713	<1	0.02	11	170	44	0.08	10	2
E858208		2.27	<10	<1	0.14	10	1.32	630	<1	0.02	17	210	74	0.10	22	2
E858209		2.39	<10	<1	0.15	10	1.27	589	2	0.04	40	190	91	0.10	31	2
E858210		0.02	<10	<1	<0.01	<10	<0.01	<5	1	0.01	1	10	5	0.01	<2	<1
E858211		1.88	<10	<1	0.15	10	2.10	886	1	0.02	5	210	38	0.04	24	1
E858212		1.68	<10	<1	0.12	10	1.63	844	<1	0.02	3	100	23	0.04	10	1
E858213		1.90	<10	<1	0.13	10	1.88	796	<1	0.02	3	150	16	0.06	17	1
E858214		2.43	<10	<1	0.16	10	4.64	1345	<1	0.02	6	410	12	0.11	15	1
E858215		2.60	<10	<1	0.17	10	0.75	710	<1	0.02	14	180	21	0.08	25	2
E858216		2.54	<10	<1	0.29	10	0.48	624	<1	0.02	10	210	15	0.20	11	1
E858217		2.29	<10	<1	0.16	<10	0.61	979	1	0.02	4	230	8	0.12	14	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E858178		86	<20	<0.01	<10	<10	2	<10	17			
E858179		51	<20	<0.01	<10	<10	3	<10	32			
E858180		40	<20	<0.01	<10	<10	6	<10	40			
E858181		164	<20	<0.01	<10	<10	5	<10	68			
E858182		53	<20	<0.01	<10	<10	5	<10	33			
E858183		15	<20	<0.01	<10	<10	8	<10	49			
E858184		156	<20	<0.01	<10	<10	4	<10	42			
E858185		89	<20	<0.01	<10	<10	4	<10	48			
E858186		209	<20	<0.01	<10	<10	4	<10	32			
E858187		102	<20	<0.01	<10	<10	6	<10	62			
E858188		38	<20	<0.01	<10	<10	6	<10	76			
E858189		37	<20	<0.01	<10	<10	5	<10	77			
E858190		1	<20	<0.01	<10	<10	<1	<10	<2			
E858191		50	<20	<0.01	<10	<10	5	<10	102			
E858192		57	<20	<0.01	<10	<10	4	<10	60			
E858193		56	<20	<0.01	<10	<10	4	<10	24			
E858194		64	<20	<0.01	<10	<10	5	<10	27			
E858195		48	<20	<0.01	<10	<10	5	<10	27			
E858196		115	<20	<0.01	<10	<10	20	<10	92			
E858197		168	<20	<0.01	<10	<10	14	<10	66			
E858198		416	<20	<0.01	<10	<10	14	<10	64			
E858199		668	<20	<0.01	<10	<10	15	<10	79			
E858200		317	<20	<0.01	<10	<10	3	<10	36			
E858201		172	<20	<0.01	<10	<10	1	<10	38			
E858202		177	<20	<0.01	<10	<10	1	<10	34			
E858203		344	<20	<0.01	<10	<10	2	<10	23			
E858204		192	<20	<0.01	<10	<10	10	<10	52			
E858205		209	<20	<0.01	<10	<10	4	<10	43			
E858206		122	<20	<0.01	<10	<10	5	<10	57			
E858207		150	<20	<0.01	<10	<10	6	<10	75			
E858208		111	<20	<0.01	<10	<10	7	<10	86			
E858209		110	<20	<0.01	<10	<10	7	<10	102			
E858210		<1	<20	<0.01	<10	<10	<1	<10	5			
E858211		250	<20	<0.01	<10	<10	2	<10	37			
E858212		180	<20	<0.01	<10	<10	1	<10	30			
E858213		191	<20	<0.01	<10	<10	1	<10	28			
E858214		384	<20	<0.01	<10	<10	1	<10	27			
E858215		84	<20	<0.01	<10	<10	2	<10	59			
E858216		53	<20	<0.01	<10	<10	3	<10	33			
E858217		83	<20	<0.01	<10	<10	2	<10	34			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E858218		1.87	0.019		<0.2	0.22	1025	<10	40	<0.5	<2	19.3	<0.5	3	2	7
E858219		2.14	0.301		0.3	0.36	5720	<10	70	<0.5	<2	1.86	<0.5	7	5	16
E858220		1.35	0.122		<0.2	0.37	1050	<10	60	<0.5	<2	1.47	<0.5	8	6	13
E858221		0.59	0.104		0.3	0.28	917	<10	50	<0.5	<2	2.89	<0.5	3	4	8
E858222		0.67	0.152		0.3	0.26	1125	<10	50	<0.5	<2	3.07	<0.5	3	5	7
E858223		2.12	0.115		<0.2	0.29	1445	<10	50	<0.5	<2	6.10	<0.5	4	4	6
E858224		2.48	0.015		<0.2	0.19	110	<10	40	<0.5	<2	18.5	<0.5	3	3	5
E858225		2.32	0.162		0.3	0.20	506	<10	40	<0.5	<2	12.9	<0.5	3	3	5
E858226		1.42	<0.005		<0.2	0.10	20	<10	20	<0.5	<2	22.1	<0.5	2	1	4
E858227		2.00	<0.005		<0.2	0.24	34	<10	40	<0.5	<2	3.14	<0.5	4	5	6
E858228		1.41	0.011		0.2	0.44	334	<10	60	<0.5	<2	1.27	<0.5	9	8	15
E858229		<0.02	0.010		0.3	0.41	297	<10	50	<0.5	<2	1.31	<0.5	8	7	13
E858230		0.07	0.862		>100	0.52	4700	<10	20	<0.5	6	0.59	101.0	7	53	307
E858231		1.22	0.006		0.4	1.22	41	<10	60	<0.5	<2	0.73	<0.5	16	15	33
E858232		2.07	<0.005		<0.2	1.03	19	<10	50	<0.5	<2	1.10	<0.5	8	13	21
E858233		2.38	0.068		<0.2	0.43	220	<10	50	<0.5	<2	1.01	<0.5	6	7	9
E858234		2.99	<0.005		<0.2	0.30	15	<10	40	<0.5	<2	1.44	<0.5	3	7	2
E858235		1.22	<0.005		<0.2	0.21	43	<10	40	<0.5	<2	1.89	<0.5	3	5	2
E858236		1.66	0.021		<0.2	0.25	76	<10	50	<0.5	<2	1.80	<0.5	5	6	6
E858237		1.64	0.143		<0.2	0.48	421	<10	70	<0.5	<2	1.21	<0.5	6	7	11

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E858218		1.13	<10	<1	0.15	<10	0.45	695	<1	0.02	4	300	14	<0.01	4	1
E858219		2.55	<10	<1	0.26	10	0.72	416	<1	0.01	11	350	22	1.29	20	1
E858220		2.65	<10	<1	0.24	10	0.62	328	<1	0.02	14	240	19	0.39	13	1
E858221		1.82	<10	<1	0.18	10	1.16	542	<1	0.01	5	120	22	0.28	8	1
E858222		1.78	<10	<1	0.17	10	1.26	564	<1	0.01	4	90	29	0.28	9	1
E858223		1.95	<10	<1	0.19	10	1.49	723	<1	0.02	4	230	17	0.30	9	1
E858224		1.20	<10	<1	0.13	10	0.79	869	<1	0.02	4	360	12	<0.01	5	1
E858225		1.16	<10	<1	0.13	10	0.61	664	<1	0.02	4	230	9	0.09	2	1
E858226		0.71	<10	<1	0.08	<10	0.45	808	<1	0.02	1	310	8	<0.01	<2	1
E858227		1.89	<10	<1	0.16	10	0.96	509	<1	0.03	6	130	18	0.07	<2	1
E858228		3.01	<10	<1	0.24	20	0.58	358	1	0.03	16	260	13	0.21	7	2
E858229		2.81	<10	<1	0.22	20	0.58	345	<1	0.03	15	240	13	0.19	6	2
E858230		6.62	<10	1	0.32	10	0.10	305	2	0.05	6	690	5180	8.0	1910	1
E858231		4.67	<10	<1	0.27	20	0.86	360	<1	0.03	32	400	35	0.25	12	2
E858232		3.31	<10	<1	0.19	20	0.71	324	<1	0.03	16	200	22	0.15	2	1
E858233		2.01	<10	<1	0.21	10	0.51	307	<1	0.03	9	170	17	0.16	3	1
E858234		1.52	<10	<1	0.16	20	0.54	375	1	0.02	4	120	17	0.03	<2	1
E858235		1.33	<10	<1	0.16	10	0.63	491	<1	0.02	2	220	16	0.03	<2	1
E858236		1.66	<10	<1	0.20	20	0.71	490	<1	0.02	6	150	16	0.05	7	1
E858237		1.82	<10	<1	0.31	20	0.58	323	<1	0.02	9	250	18	0.12	6	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E858218		367	<20	<0.01	<10	10	<1	<10	17			
E858219		111	<20	<0.01	<10	<10	2	<10	33			
E858220		75	<20	<0.01	<10	<10	3	<10	43			
E858221		110	<20	<0.01	<10	<10	1	<10	21			
E858222		122	<20	<0.01	<10	<10	1	<10	21			
E858223		234	<20	<0.01	<10	<10	2	<10	26			
E858224		538	<20	<0.01	<10	10	<1	<10	17			
E858225		228	<20	<0.01	<10	<10	1	<10	13			
E858226		388	<20	<0.01	<10	10	<1	<10	7			
E858227		123	<20	<0.01	<10	<10	2	<10	25			
E858228		74	<20	<0.01	<10	<10	4	<10	46			
E858229		76	<20	<0.01	<10	<10	4	<10	46			
E858230		145	<20	<0.01	<10	<10	6	10	>10000		1.300	146
E858231		35	20	<0.01	<10	<10	8	<10	150			
E858232		89	<20	<0.01	<10	<10	7	<10	60			
E858233		50	<20	<0.01	<10	<10	3	<10	33			
E858234		59	<20	<0.01	<10	<10	2	<10	20			
E858235		74	<20	<0.01	<10	<10	1	<10	12			
E858236		81	<20	<0.01	<10	<10	2	<10	19			
E858237		74	<20	<0.01	<10	<10	3	<10	30			

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 28-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095961

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-AUG-2010
Account: EIAALN

CERTIFICATE WH10095939

Project: ALN10-01

P.O. No.: ALN10-01_17

This report is for 54 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 14-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095939

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E856561		2.13	<0.005	<0.2	1.22	4	<10	60	<0.5	<2	0.71	<0.5	13	15	30	2.86
E856562		1.88	<0.005	<0.2	1.36	8	<10	70	<0.5	<2	0.48	<0.5	12	16	45	3.15
E856563		3.05	<0.005	<0.2	0.89	6	<10	60	<0.5	<2	0.76	<0.5	5	14	11	1.99
E856564		2.27	<0.005	<0.2	0.81	<2	<10	70	<0.5	<2	0.61	<0.5	7	13	15	2.02
E856565		3.27	<0.005	<0.2	1.05	7	<10	80	<0.5	<2	0.50	<0.5	9	17	18	2.51
E856566		3.43	<0.005	11.6	1.27	17	<10	110	<0.5	<2	0.46	<0.5	12	21	42	2.87
E856567		3.32	<0.005	0.3	3.99	26	<10	70	<0.5	<2	2.45	<0.5	26	39	50	6.83
E856568		3.64	<0.005	0.4	4.65	49	<10	10	<0.5	<2	2.23	<0.5	25	45	23	7.65
E856569		<0.02	0.006	0.3	4.43	50	<10	10	<0.5	<2	2.12	<0.5	26	43	28	7.35
E856570		0.07	<0.005	<0.2	0.01	2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
E856571		4.56	<0.005	<0.2	4.53	25	<10	<10	<0.5	<2	2.22	<0.5	24	42	12	7.30
E856572		2.84	0.072	<0.2	4.84	17	<10	<10	<0.5	<2	1.72	<0.5	30	44	41	8.00
E856573		3.84	0.005	<0.2	4.79	48	<10	10	<0.5	<2	1.30	<0.5	28	47	33	8.22
E856574		4.35	<0.005	<0.2	4.82	14	<10	<10	<0.5	<2	1.64	<0.5	31	43	48	8.15
E856575		3.82	<0.005	<0.2	4.75	17	<10	<10	0.6	<2	1.67	<0.5	31	39	50	7.82
E856576		3.42	<0.005	<0.2	4.27	27	<10	<10	0.6	<2	1.63	<0.5	30	40	45	7.46
E856577		3.57	<0.005	<0.2	4.20	42	<10	10	0.6	<2	1.85	<0.5	29	42	63	7.64
E856578		Not Recvd														
E856579		3.74	<0.005	<0.2	2.88	29	<10	130	<0.5	<2	1.34	<0.5	20	31	35	5.74
E856580		4.12	<0.005	<0.2	1.60	9	<10	190	<0.5	<2	0.07	<0.5	12	21	33	3.76
E856581		2.30	<0.005	0.2	0.94	3	<10	90	<0.5	<2	1.03	<0.5	10	16	18	2.04
E856582		2.05	<0.005	<0.2	0.98	20	<10	80	<0.5	<2	0.92	<0.5	8	16	14	2.30
E856583		4.30	<0.005	0.2	1.02	3	<10	60	<0.5	<2	0.72	<0.5	11	16	18	2.58
E856584		4.42	<0.005	<0.2	0.74	2	<10	50	<0.5	<2	1.07	<0.5	8	13	17	2.07
E856585		4.61	<0.005	<0.2	0.56	6	<10	50	<0.5	<2	1.20	<0.5	6	11	12	2.09
E856586		4.23	<0.005	<0.2	0.57	14	<10	50	<0.5	<2	0.95	<0.5	6	13	7	1.68
E856587		3.99	<0.005	0.2	0.77	<2	<10	60	<0.5	2	0.91	<0.5	11	12	24	2.66
E856588		4.40	<0.005	<0.2	0.52	7	<10	60	<0.5	<2	0.38	<0.5	7	11	16	1.99
E856589		<0.02	<0.005	<0.2	0.52	5	<10	60	<0.5	<2	0.34	<0.5	7	10	15	1.95
E856590		0.07	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.01
E856591		3.39	<0.005	<0.2	1.05	11	<10	70	<0.5	<2	0.15	<0.5	10	15	33	2.73
E856592		3.47	<0.005	<0.2	1.57	3	<10	80	<0.5	<2	0.60	<0.5	21	21	49	4.38
E856593		4.27	<0.005	<0.2	2.79	30	<10	70	<0.5	<2	1.68	<0.5	22	33	40	6.08
E856594		4.63	<0.005	0.2	1.31	15	<10	80	<0.5	<2	0.97	<0.5	13	33	40	3.28
E856595		3.78	<0.005	<0.2	1.35	9	<10	100	<0.5	<2	0.60	<0.5	11	23	21	3.12
E856596		3.97	<0.005	<0.2	1.86	11	<10	100	<0.5	<2	1.59	<0.5	13	30	14	3.75
E856597		3.90	<0.005	<0.2	1.76	9	<10	130	<0.5	<2	2.34	<0.5	17	26	42	3.70
E856598		3.09	<0.005	<0.2	1.94	12	<10	150	<0.5	<2	3.84	0.5	20	23	100	4.10
E856599		2.11	<0.005	<0.2	1.14	3	<10	180	<0.5	<2	4.53	<0.5	10	12	44	3.11
E856600		2.11	<0.005	<0.2	2.37	197	<10	420	<0.5	<2	1.99	5.9	21	36	23	5.44

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095939

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E856561		<10	<1	0.25	20	0.49	364	<1	0.02	32	310	10	0.19	2	1	56
E856562		<10	<1	0.30	20	0.53	269	<1	0.02	21	280	8	0.19	<2	1	34
E856563		<10	<1	0.21	10	0.34	302	<1	0.02	16	120	15	0.05	<2	1	30
E856564		<10	<1	0.24	10	0.31	226	<1	0.02	17	130	17	0.30	<2	1	27
E856565		<10	1	0.39	10	0.42	240	1	0.02	19	210	10	0.20	2	1	23
E856566		<10	<1	0.38	20	0.54	335	5	0.03	22	250	14	0.10	2	1	18
E856567		20	<1	0.12	<10	2.88	1050	<1	0.03	52	2220	5	0.11	3	11	137
E856568		20	<1	<0.01	<10	3.49	1215	<1	0.03	59	2530	<2	0.02	4	14	99
E856569		20	<1	<0.01	<10	3.30	1190	<1	0.03	56	2420	2	0.02	4	13	94
E856570		<10	<1	<0.01	<10	0.01	<5	<1	<0.01	<1	10	<2	<0.01	<2	<1	<1
E856571		20	<1	<0.01	<10	3.47	1105	<1	0.02	54	2450	3	0.02	<2	13	102
E856572		20	1	<0.01	<10	3.81	1065	<1	0.02	55	2380	2	0.14	<2	13	87
E856573		20	1	<0.01	<10	3.93	1000	<1	0.02	53	2450	<2	0.04	6	13	69
E856574		20	1	<0.01	<10	3.86	985	<1	0.03	56	2500	<2	0.17	<2	13	94
E856575		20	<1	<0.01	<10	3.83	934	<1	0.02	55	2510	<2	0.10	<2	13	94
E856576		20	<1	<0.01	<10	3.42	791	<1	0.03	53	2440	<2	0.02	7	12	81
E856577		20	<1	<0.01	<10	3.14	790	<1	0.03	55	2500	<2	0.14	10	12	155
E856578																
E856579		10	1	0.20	10	1.80	627	<1	0.03	43	1250	11	0.17	5	7	82
E856580		<10	<1	0.49	20	0.58	250	<1	0.04	18	200	23	0.22	<2	1	3
E856581		<10	<1	0.29	10	0.32	348	<1	0.03	27	1100	10	0.15	<2	1	43
E856582		<10	<1	0.23	10	0.40	364	<1	0.03	27	1150	11	0.13	2	1	40
E856583		<10	<1	0.24	10	0.40	368	<1	0.02	32	90	14	0.39	<2	1	33
E856584		<10	<1	0.21	10	0.30	423	1	0.03	21	90	25	0.44	<2	1	56
E856585		<10	<1	0.20	10	0.24	521	1	0.02	11	110	15	0.67	2	1	62
E856586		<10	<1	0.20	10	0.23	483	<1	0.03	16	90	9	0.36	<2	1	54
E856587		<10	<1	0.27	10	0.31	458	<1	0.02	22	490	18	0.87	<2	1	40
E856588		<10	<1	0.30	10	0.14	228	<1	0.02	14	100	19	0.58	<2	<1	18
E856589		<10	<1	0.30	10	0.15	227	<1	0.02	15	100	19	0.54	<2	<1	17
E856590		<10	<1	<0.01	<10	<0.01	<5	1	<0.01	<1	10	<2	<0.01	<2	<1	<1
E856591		<10	1	0.34	20	0.40	266	1	0.02	15	220	12	0.26	6	1	9
E856592		10	<1	0.35	10	0.78	568	1	0.04	38	1010	16	0.77	7	2	23
E856593		10	1	0.20	10	1.56	968	<1	0.04	44	1390	6	0.43	<2	7	88
E856594		10	1	0.20	10	0.74	535	1	0.04	25	330	5	0.41	5	3	56
E856595		10	<1	0.26	10	0.77	451	1	0.04	26	200	15	0.41	2	2	28
E856596		10	<1	0.25	10	1.60	699	1	0.05	26	450	8	0.36	<2	3	79
E856597		10	<1	0.31	10	1.26	1020	<1	0.04	30	380	12	0.58	6	2	106
E856598		10	<1	0.38	10	1.43	1465	1	0.03	35	590	10	0.68	6	3	182
E856599		<10	<1	0.31	10	1.07	1080	<1	<0.01	22	560	13	0.40	2	2	235
E856600		10	1	0.20	10	1.89	791	<1	0.02	49	1860	<2	0.09	28	10	122

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095939

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
E856561		<20	0.01	10	<10	7	<10	57
E856562		<20	0.01	<10	<10	8	<10	57
E856563		<20	0.01	<10	<10	6	<10	30
E856564		<20	0.01	10	<10	6	<10	28
E856565		<20	0.02	<10	<10	8	<10	41
E856566		<20	0.03	<10	<10	11	10	51
E856567		<20	0.17	<10	<10	81	<10	83
E856568		<20	0.26	10	<10	104	<10	112
E856569		<20	0.24	<10	<10	98	10	109
E856570		<20	<0.01	<10	<10	<1	<10	3
E856571		<20	0.25	<10	<10	93	<10	105
E856572		<20	0.18	<10	<10	94	<10	133
E856573		<20	0.19	<10	<10	98	<10	151
E856574		<20	0.28	<10	<10	102	<10	133
E856575		<20	0.26	<10	<10	102	<10	147
E856576		<20	0.23	<10	<10	112	<10	193
E856577		<20	0.13	<10	<10	104	<10	154
E856578								
E856579		<20	0.04	<10	<10	50	<10	107
E856580		<20	0.03	<10	<10	12	<10	63
E856581		<20	0.01	<10	<10	7	<10	50
E856582		<20	0.02	<10	<10	11	<10	57
E856583		<20	0.01	<10	<10	7	<10	46
E856584		<20	0.01	<10	<10	5	<10	38
E856585		<20	<0.01	<10	<10	3	<10	23
E856586		<20	<0.01	<10	<10	4	<10	26
E856587		<20	<0.01	<10	<10	4	<10	33
E856588		<20	0.01	<10	<10	3	<10	14
E856589		<20	0.01	<10	<10	3	<10	16
E856590		<20	<0.01	<10	<10	<1	<10	<2
E856591		<20	0.01	<10	<10	6	<10	38
E856592		<20	0.02	<10	<10	20	<10	80
E856593		<20	0.02	<10	<10	52	<10	115
E856594		<20	0.01	<10	<10	22	<10	69
E856595		<20	0.01	<10	<10	12	<10	99
E856596		<20	0.01	<10	<10	30	<10	59
E856597		<20	0.02	<10	<10	23	<10	63
E856598		<20	0.02	<10	<10	20	<10	86
E856599		<20	<0.01	<10	<10	11	<10	51
E856600		<20	0.24	<10	<10	85	<10	578

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095939

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E856601		0.59	<0.005	<0.2	1.99	204	<10	220	0.6	<2	4.39	2.4	13	21	28	3.23
E856602		0.79	<0.005	<0.2	2.87	225	<10	220	0.7	<2	4.25	3.4	18	32	36	4.48
E856603		1.93	<0.005	<0.2	3.35	42	<10	140	0.6	<2	4.81	<0.5	19	37	43	5.05
E856604		2.01	<0.005	<0.2	2.94	77	<10	300	0.8	<2	2.90	<0.5	17	35	32	4.91
E856605		3.08	0.013	<0.2	3.81	158	<10	40	<0.5	<2	2.36	<0.5	26	55	5	7.10
E856606		2.80	0.140	<0.2	2.05	1445	<10	90	<0.5	<2	2.23	<0.5	29	31	11	7.23
E856607		1.58	<0.005	<0.2	3.98	146	<10	70	<0.5	<2	1.71	<0.5	35	52	18	9.72
E856608		2.14	0.008	<0.2	2.96	30	<10	110	<0.5	<2	2.61	<0.5	29	41	10	7.59
E856609		<0.02	<0.005	<0.2	3.02	25	<10	100	<0.5	<2	2.52	<0.5	27	52	18	7.61
E856610		0.13	<0.005	<0.2	0.01	<2	<10	10	<0.5	2	0.01	<0.5	<1	<1	<1	0.02
E856611		2.31	<0.005	<0.2	3.60	73	<10	80	<0.5	<2	2.11	<0.5	34	45	26	8.96
E856612		2.03	<0.005	<0.2	2.93	47	<10	740	<0.5	<2	1.90	<0.5	30	44	56	7.51
E856613		1.45	0.005	0.2	3.20	31	<10	280	0.5	<2	2.65	<0.5	34	41	37	7.31
E856614		2.44	0.007	0.3	2.77	67	<10	190	<0.5	<2	1.97	<0.5	32	39	43	8.15

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095939

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E856601		10	1	0.21	20	1.71	1225	<1	<0.01	37	530	9	0.01	53	4	442
E856602		10	1	0.22	20	2.51	1260	<1	0.01	48	930	5	<0.01	45	6	371
E856603		10	1	0.14	20	3.25	1245	<1	0.01	45	1300	3	<0.01	6	8	475
E856604		10	<1	0.35	20	2.89	1155	<1	0.01	34	670	47	0.09	18	8	198
E856605		20	1	0.03	20	4.29	1315	<1	0.04	55	1750	11	0.08	14	13	167
E856606		10	<1	0.04	<10	2.07	979	<1	0.04	51	2130	<2	0.27	30	11	159
E856607		30	1	0.02	10	3.58	1070	<1	0.04	72	2520	<2	0.06	30	17	109
E856608		20	<1	0.08	10	2.75	864	1	0.04	53	2560	5	0.04	4	12	196
E856609		20	<1	0.07	10	2.79	852	<1	0.04	53	2590	4	0.04	4	12	188
E856610		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.01	<2	<1	<1
E856611		20	<1	0.01	10	3.09	1060	<1	0.04	67	2650	3	0.10	29	13	139
E856612		20	1	0.06	<10	2.53	976	<1	0.05	58	2480	<2	0.24	14	13	152
E856613		20	1	0.02	<10	2.71	817	<1	0.04	56	2370	2	0.15	<2	12	353
E856614		20	<1	0.02	10	2.57	926	<1	0.05	59	2520	<2	0.16	21	13	141

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095939

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
E856601		<20	0.02	<10	<10	22	<10	427
E856602		<20	0.09	<10	<10	45	<10	678
E856603		<20	0.06	<10	<10	56	<10	205
E856604		<20	0.06	<10	<10	56	<10	140
E856605		<20	0.03	<10	<10	95	<10	219
E856606		<20	0.02	<10	<10	77	<10	343
E856607		<20	0.06	<10	<10	164	<10	555
E856608		<20	0.09	<10	<10	109	<10	212
E856609		<20	0.08	<10	<10	108	<10	206
E856610		<20	<0.01	<10	<10	<1	<10	2
E856611		<20	0.04	<10	<10	118	<10	615
E856612		<20	0.09	<10	<10	104	<10	396
E856613		<20	0.11	<10	<10	109	<10	141
E856614		<20	0.05	<10	<10	93	<10	245

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

CERTIFICATE WH10095938

Project: ALN10-01: Keystone

P.O. No.: ALN10-01_16

This report is for 17 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 14-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01: Keystone

CERTIFICATE OF ANALYSIS WH10095938

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856615		3.48	<0.005		15.6	2.62	73	<10	690	0.6	<2	2.40	<0.5	34	39	152
E856616		3.34	0.010		0.3	2.76	71	<10	110	0.8	<2	1.70	<0.5	34	41	53
E856617		3.10	0.467		1.5	1.90	2460	<10	140	<0.5	<2	4.19	<0.5	29	27	35
E856618		4.64	0.147		1.1	2.45	653	<10	100	0.5	<2	2.65	<0.5	37	32	60
E856619		4.68	0.253		1.0	2.96	2040	<10	190	0.6	<2	2.79	1.5	35	38	68
E856620		3.48	0.017		0.2	2.90	42	<10	680	0.6	<2	3.21	<0.5	30	42	33
E856621		0.96	0.011		0.3	3.34	86	<10	40	0.5	<2	2.70	<0.5	32	44	34
E856622		1.12	0.005		0.3	3.30	56	<10	30	0.5	<2	2.91	<0.5	29	43	29
E856623		2.20	1.525	1.90	1.7	1.09	>10000	<10	120	<0.5	<2	1.77	19.8	32	17	61
E856624		2.16	0.380		2.4	0.43	5930	<10	210	<0.5	<2	0.82	8.3	7	7	24
E856625		2.28	0.356		2.5	0.48	3350	<10	200	<0.5	<2	1.11	21.4	9	9	26
E856626		4.82	0.879		3.5	0.43	>10000	<10	160	<0.5	<2	0.80	8.9	5	8	20
E856627		1.52	0.736		1.7	0.60	9900	<10	130	<0.5	<2	1.54	2.3	8	10	34
E856628		1.96	0.062		1.2	0.79	177	<10	340	<0.5	<2	0.41	<0.5	9	15	77
E856629		Empty Bag														
E856630		0.10	NSS		>100	0.56	4810	<10	30	<0.5	4	0.57	102.5	6	55	314
E856631		1.92	0.024		1.1	0.70	121	<10	350	<0.5	<2	0.35	<0.5	9	11	53

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01: Keystone

CERTIFICATE OF ANALYSIS WH10095938

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856615		8.23	20	<1	0.05	10	2.19	973	<1	0.07	78	2630	3	0.26	27	13
E856616		7.64	20	<1	0.02	<10	2.11	933	<1	0.06	60	2630	<2	0.46	41	13
E856617		7.55	10	<1	0.08	<10	2.35	1275	1	0.05	57	2450	4	2.24	43	12
E856618		7.45	10	<1	0.04	<10	2.19	884	<1	0.06	50	2490	7	1.69	42	12
E856619		7.87	20	1	0.04	<10	2.16	926	<1	0.05	57	2540	7	1.72	54	12
E856620		7.26	20	<1	0.01	<10	2.25	853	<1	0.07	53	2520	<2	0.27	7	12
E856621		7.45	20	1	0.01	<10	2.50	1400	<1	0.05	62	2500	<2	0.27	11	13
E856622		7.29	20	<1	0.01	<10	2.49	1280	<1	0.04	55	2440	<2	0.21	9	12
E856623		7.02	10	<1	0.15	<10	0.96	2520	<1	0.04	57	1490	88	2.94	187	7
E856624		1.70	<10	<1	0.24	10	0.31	698	<1	0.01	13	150	134	0.85	133	1
E856625		1.74	<10	<1	0.24	10	0.42	1710	<1	0.02	9	130	112	0.61	138	1
E856626		2.69	<10	<1	0.19	<10	0.33	437	<1	0.02	11	240	315	1.85	241	1
E856627		3.53	<10	<1	0.18	<10	0.78	962	<1	0.02	23	300	146	2.20	106	2
E856628		2.72	<10	<1	0.21	10	0.51	891	<1	0.03	34	230	15	0.71	47	2
E856629																
E856630		6.01	<10	1	0.33	10	0.10	308	1	0.05	5	700	5110	8.0	1755	1
E856631		1.97	<10	<1	0.15	10	0.38	633	<1	0.03	33	260	28	0.47	34	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01: Keystone

CERTIFICATE OF ANALYSIS WH10095938

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	5
E856615		177	<20	0.03	<10	<10	87	130	172		
E856616		116	<20	0.03	<10	<10	89	<10	156		
E856617		390	<20	0.01	<10	<10	45	<10	142		
E856618		208	<20	0.02	<10	<10	68	<10	169		
E856619		240	<20	0.03	<10	<10	88	<10	377		
E856620		372	<20	0.06	<10	<10	101	<10	129		
E856621		283	<20	0.05	<10	<10	108	<10	332		
E856622		315	<20	0.04	<10	<10	106	<10	300		
E856623		140	<20	0.01	<10	<10	31	<10	896		
E856624		63	<20	<0.01	<10	<10	3	<10	385		
E856625		58	<20	<0.01	<10	<10	5	<10	1735		
E856626		63	<20	<0.01	<10	<10	6	<10	806		
E856627		204	<20	<0.01	<10	<10	9	<10	305		
E856628		53	<20	<0.01	<10	<10	19	<10	83		
E856629											
E856630		142	<20	<0.01	<10	<10	6	10	>10000	1.335	139
E856631		50	<20	<0.01	<10	<10	13	<10	118		

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01: Keystone

CERTIFICATE OF ANALYSIS WH10095938

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-AUG-2010
Account: EIAALN

CERTIFICATE WH10095043

Project: ALN10-01

P.O. No.: ALN10-01_18

This report is for 33 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 16-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095043

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
856632		1.47	0.262		2.6	0.97	2320	<10	110	<0.5	<2	2.93	1.3	8	13	92
856633		1.38	0.462		0.8	0.76	768	<10	220	<0.5	<2	1.45	1.0	9	14	60
856634		1.37	0.885		2.6	0.44	3240	<10	140	<0.5	<2	1.87	2.4	9	8	65
856635		2.10	1.010	1.12	3.6	1.11	3770	<10	70	<0.5	<2	2.09	7.8	18	9	74
856636		1.85	0.081		3.6	4.16	418	<10	70	0.5	<2	3.47	0.7	29	8	93
856637		2.15	0.543		2.5	3.26	2800	<10	110	0.5	<2	3.58	0.9	25	7	63
856638		1.49	0.324		1.1	0.77	469	<10	230	<0.5	<2	1.05	<0.5	10	9	59
856639		2.08	0.315		0.7	0.48	1410	<10	240	<0.5	<2	1.04	0.5	9	13	52
856640		2.40	0.026		0.2	0.52	68	<10	270	<0.5	<2	0.37	<0.5	9	9	64
856641		0.97	0.022		0.3	0.68	59	<10	290	<0.5	<2	0.52	<0.5	11	11	72
856642		1.13	0.017		0.2	0.59	57	<10	280	<0.5	<2	0.25	<0.5	11	8	67
856643		2.66	0.036		0.2	0.54	49	<10	250	<0.5	<2	0.48	<0.5	9	12	81
856644		3.74	0.170		1.7	0.37	812	<10	240	<0.5	<2	0.43	<0.5	9	12	82
856645		3.23	0.425		2.7	0.26	1530	<10	160	<0.5	<2	0.79	<0.5	9	13	64
856646		3.14	0.278		1.9	0.27	872	<10	180	<0.5	<2	1.05	<0.5	9	9	57
856647		4.39	0.015		0.3	0.29	62	<10	260	<0.5	<2	0.28	<0.5	8	9	77
856648		3.17	0.009		0.2	0.40	33	<10	290	<0.5	<2	4.14	<0.5	9	9	58
856649		<0.02	0.008		0.2	0.41	36	<10	310	<0.5	<2	3.58	<0.5	9	11	64
856650		0.11	<0.005		<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	1
856651		4.19	0.010		<0.2	0.55	7	<10	210	<0.5	<2	0.19	<0.5	6	14	71
856652		3.83	0.042		<0.2	0.95	10	<10	240	<0.5	<2	0.09	<0.5	8	19	105
856653		1.35	0.012		<0.2	1.01	10	<10	260	<0.5	<2	0.16	<0.5	8	12	84
856654		5.18	0.014		<0.2	1.56	16	<10	350	<0.5	<2	0.70	<0.5	11	15	97
856655		3.67	0.030		<0.2	0.92	10	<10	250	<0.5	<2	0.15	<0.5	7	17	109
856656		3.11	0.030		<0.2	0.93	10	<10	250	<0.5	<2	0.05	<0.5	8	14	85
856657		2.77	0.013		<0.2	0.69	6	<10	210	<0.5	<2	0.45	<0.5	5	17	157
856658		4.05	0.078		0.2	0.83	4	<10	230	<0.5	<2	0.04	<0.5	6	16	90
856659		4.79	0.032		<0.2	0.75	2	<10	270	<0.5	<2	0.37	<0.5	8	19	88
856660		3.76	0.073		<0.2	0.84	7	<10	230	<0.5	<2	0.72	<0.5	7	18	78
856661		2.60	0.020		<0.2	1.11	8	<10	230	<0.5	<2	0.27	<0.5	8	17	79
856662		2.44	0.013		<0.2	1.11	8	<10	260	<0.5	<2	0.31	<0.5	7	13	80
856663		3.42	0.062		<0.2	1.48	6	<10	320	<0.5	<2	0.92	<0.5	9	18	113
856664		3.01	0.029		<0.2	1.06	8	<10	280	<0.5	<2	0.20	<0.5	9	15	109

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095043

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
856632		6.26	<10	<1	0.12	<10	1.04	3260	<1	0.02	33	510	47	2.60	70	3
856633		3.36	<10	<1	0.12	10	0.73	2440	1	0.02	39	370	165	1.40	141	3
856634		3.24	<10	1	0.10	<10	0.89	1225	3	0.02	44	340	61	2.28	55	3
856635		5.55	<10	1	0.14	<10	1.14	953	1	0.02	44	1000	1690	3.49	994	6
856636		8.41	<10	1	0.05	<10	2.41	1330	<1	0.02	54	2560	53	0.76	93	13
856637		8.00	<10	<1	0.08	<10	2.26	1310	<1	0.02	47	2030	339	1.99	243	11
856638		3.71	<10	<1	0.09	10	0.67	1420	<1	0.02	30	460	707	1.54	594	3
856639		2.89	<10	<1	0.12	10	0.64	1290	1	0.02	34	320	46	1.32	47	2
856640		2.61	<10	<1	0.12	10	0.50	1820	1	0.02	29	270	12	0.68	30	2
856641		2.76	<10	<1	0.13	10	0.47	2000	1	0.02	36	220	13	0.57	33	2
856642		2.38	<10	<1	0.12	10	0.32	1095	1	0.02	40	220	12	0.52	27	2
856643		3.46	<10	<1	0.11	10	0.62	4100	<1	0.03	30	730	13	0.68	39	2
856644		2.27	<10	<1	0.11	10	0.36	1340	<1	0.02	31	220	9	0.82	40	1
856645		2.25	<10	<1	0.13	10	0.34	1160	1	0.01	33	120	8	1.61	31	1
856646		2.26	<10	<1	0.12	<10	0.47	1485	1	0.01	35	110	11	1.47	30	1
856647		2.00	<10	<1	0.12	10	0.32	967	1	0.02	25	120	9	0.78	27	1
856648		2.51	<10	<1	0.13	10	1.22	12050	1	0.02	35	2550	20	0.80	8	2
856649		2.44	<10	<1	0.14	<10	0.99	10650	1	0.01	40	2770	24	0.80	5	2
856650		0.03	<10	<1	<0.01	<10	<0.01	27	1	<0.01	<1	10	8	0.01	<2	<1
856651		1.57	<10	<1	0.10	10	0.38	533	<1	0.01	21	120	8	0.43	<2	1
856652		1.96	<10	<1	0.11	10	0.57	395	<1	<0.01	28	160	9	0.13	<2	1
856653		2.06	<10	<1	0.12	10	0.62	512	<1	<0.01	26	180	9	0.12	<2	1
856654		2.93	<10	<1	0.17	10	0.98	1255	<1	0.01	27	340	11	0.13	<2	2
856655		1.86	<10	<1	0.11	10	0.55	513	<1	<0.01	26	180	8	0.11	<2	1
856656		1.96	<10	1	0.11	10	0.55	381	<1	<0.01	29	130	12	0.16	<2	1
856657		1.57	<10	<1	0.10	10	0.49	1290	<1	<0.01	18	110	10	0.11	<2	1
856658		1.65	<10	<1	0.11	10	0.50	340	<1	<0.01	19	100	8	0.15	<2	1
856659		2.12	<10	1	0.12	10	0.55	918	<1	<0.01	26	210	9	0.53	<2	1
856660		1.99	<10	1	0.11	10	0.59	6070	<1	0.01	22	130	11	0.21	<2	1
856661		2.26	<10	<1	0.11	10	0.71	999	<1	<0.01	25	230	11	0.12	<2	1
856662		2.29	<10	<1	0.12	10	0.71	1180	<1	<0.01	23	220	14	0.11	<2	1
856663		2.79	<10	<1	0.15	10	0.75	739	<1	0.01	30	4170	12	0.19	<2	2
856664		2.38	<10	<1	0.11	10	0.54	1220	<1	0.01	25	290	10	0.18	<2	1

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095043

Sample Description	Method / Analyte / Units / LOR	ME-ICP41 Sr ppm 1	ME-ICP41 Th ppm 20	ME-ICP41 Ti % 0.01	ME-ICP41 Tl ppm 10	ME-ICP41 U ppm 10	ME-ICP41 V ppm 1	ME-ICP41 W ppm 10	ME-ICP41 Zn ppm 2
856632		241	<20	<0.01	<10	<10	21	<10	223
856633		166	<20	<0.01	<10	<10	18	<10	179
856634		272	<20	<0.01	<10	<10	18	<10	470
856635		239	<20	<0.01	<10	<10	18	<10	817
856636		412	<20	<0.01	<10	<10	19	<10	203
856637		404	<20	<0.01	<10	<10	17	<10	183
856638		135	<20	<0.01	<10	<10	12	<10	83
856639		142	<20	<0.01	<10	<10	11	10	124
856640		60	<20	<0.01	<10	<10	10	<10	76
856641		74	<20	<0.01	<10	<10	13	<10	77
856642		43	<20	<0.01	<10	<10	12	<10	83
856643		79	<20	<0.01	<10	<10	13	<10	70
856644		50	<20	<0.01	<10	<10	10	<10	45
856645		87	<20	<0.01	<10	<10	10	<10	34
856646		105	<20	<0.01	<10	<10	9	<10	34
856647		34	<20	<0.01	<10	<10	10	<10	44
856648		455	<20	<0.01	<10	<10	14	<10	44
856649		390	<20	<0.01	<10	<10	15	<10	47
856650		2	<20	<0.01	<10	<10	<1	<10	3
856651		24	<20	<0.01	<10	<10	15	<10	40
856652		17	<20	<0.01	<10	<10	23	<10	42
856653		25	<20	<0.01	<10	<10	20	<10	42
856654		103	<20	<0.01	<10	<10	24	<10	59
856655		26	<20	<0.01	<10	<10	22	<10	37
856656		13	<20	<0.01	<10	<10	19	<10	39
856657		62	<20	<0.01	<10	<10	16	<10	44
856658		12	<20	<0.01	<10	<10	19	<10	41
856659		59	<20	<0.01	<10	<10	19	<10	44
856660		84	<20	<0.01	<10	<10	19	<10	39
856661		39	<20	<0.01	<10	<10	22	<10	45
856662		42	<20	<0.01	<10	<10	21	<10	44
856663		144	<20	<0.01	<10	<10	29	<10	57
856664		38	<20	<0.01	<10	<10	23	<10	53

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUL-2010
Account: EIAALN

CERTIFICATE WH10094738

Project: ALN10-01

P.O. No.: ALN10-01_12

This report is for 66 GRAB samples submitted to our lab in Whitehorse, YT, Canada on 13-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094738

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E856496		2.87	<0.005	<0.2	1.41	12	<10	160	<0.5	<2	0.09	<0.5	19	16	36	3.08
E856497		2.57	<0.005	<0.2	1.34	10	<10	110	<0.5	<2	0.33	<0.5	15	15	30	2.85
E856498		2.37	<0.005	<0.2	1.11	3	<10	90	<0.5	<2	0.83	<0.5	10	12	19	2.26
E856499		3.77	<0.005	0.2	2.39	3	<10	100	<0.5	2	0.90	<0.5	22	29	34	4.79
E856500		3.42	<0.005	<0.2	2.98	4	<10	170	<0.5	3	1.23	<0.5	24	32	39	5.68
E856501		3.69	<0.005	<0.2	2.83	8	<10	130	<0.5	<2	1.40	<0.5	22	30	48	5.47
E856502		3.49	<0.005	<0.2	3.34	6	<10	120	<0.5	<2	1.15	<0.5	25	33	42	6.11
E856503		2.34	<0.005	<0.2	3.66	8	<10	30	<0.5	<2	2.53	<0.5	26	38	26	6.21
E856504		2.93	<0.005	<0.2	4.21	13	<10	20	<0.5	<2	3.15	<0.5	29	36	41	7.00
E856505		4.28	<0.005	<0.2	4.57	13	<10	10	<0.5	<2	2.75	<0.5	30	40	48	7.65
E856506		4.04	<0.005	<0.2	4.64	14	<10	<10	<0.5	2	2.83	<0.5	33	40	45	7.89
E856507		3.47	<0.005	<0.2	3.80	8	<10	40	<0.5	<2	5.71	<0.5	21	30	39	5.92
E856508		4.18	<0.005	<0.2	3.38	14	<10	60	<0.5	<2	5.47	<0.5	25	30	64	5.42
E856509		<0.02	<0.005	<0.2	3.36	11	<10	60	<0.5	<2	5.55	<0.5	23	31	62	5.46
E856510		0.07	0.955	>100	0.56	4790	<10	20	<0.5	6	0.56	102.0	7	54	318	5.93
E856511		4.46	<0.005	0.4	4.40	24	<10	10	<0.5	<2	3.40	<0.5	29	39	46	7.38
E856512		4.09	<0.005	<0.2	0.91	19	<10	60	<0.5	<2	6.66	<0.5	16	26	30	2.98
E856513		2.34	<0.005	0.2	1.30	20	<10	60	<0.5	<2	1.13	<0.5	10	12	22	3.07
E856514		2.20	<0.005	<0.2	0.92	12	<10	50	<0.5	<2	0.26	<0.5	12	8	22	2.10
E856515		1.62	0.007	<0.2	0.88	41	<10	150	<0.5	<2	0.63	<0.5	9	7	29	2.34
E856516		2.95	0.008	0.3	0.21	19	<10	320	<0.5	<2	0.11	<0.5	8	7	56	0.85
E856518		1.73	0.014	0.4	0.28	49	<10	300	<0.5	<2	0.68	1.0	7	9	62	1.99
E856519		2.24	0.009	<0.2	0.71	19	<10	350	<0.5	<2	0.43	<0.5	10	9	134	2.71
E856520		2.44	0.005	<0.2	0.41	16	<10	270	<0.5	<2	1.39	<0.5	8	9	113	2.11
E856521		1.24	0.013	0.5	0.47	27	<10	300	<0.5	2	1.69	<0.5	12	6	105	4.85
E856522		0.98	0.011	0.3	0.40	22	<10	250	<0.5	<2	1.38	<0.5	10	7	85	4.11
E856523		1.82	0.312	0.7	0.29	2090	<10	250	<0.5	<2	0.83	<0.5	7	7	51	2.06
E856524		3.26	0.096	1.3	0.30	580	<10	190	<0.5	<2	1.74	<0.5	9	9	216	2.17
E856525		3.41	0.047	9.1	0.51	527	<10	250	<0.5	<2	2.70	<0.5	9	9	118	2.95
E856526		3.37	0.010	0.3	0.78	37	<10	250	<0.5	<2	0.46	<0.5	8	15	60	2.09
E856527		3.24	0.011	0.3	0.98	47	<10	280	<0.5	<2	0.66	<0.5	12	14	66	3.37
E856528		4.12	0.009	0.2	0.62	27	<10	290	<0.5	<2	0.37	<0.5	11	13	42	2.27
E856529		<0.02	0.011	0.3	0.69	25	<10	330	<0.5	<2	0.37	<0.5	12	18	44	2.41
E856530		0.09	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	1	<1	<1	0.01
E856531		2.92	0.011	<0.2	0.55	27	<10	270	<0.5	<2	0.32	<0.5	9	10	50	1.89
E856532		3.25	0.008	0.2	0.90	27	<10	270	<0.5	<2	0.23	<0.5	11	16	61	2.36
E856533		3.98	0.009	<0.2	1.07	22	<10	300	<0.5	3	0.37	<0.5	11	18	40	2.74
E856534		4.40	0.433	0.3	1.10	49	<10	190	<0.5	3	0.50	<0.5	10	14	83	4.23
E856535		2.46	0.252	<0.2	0.52	29	<10	220	<0.5	2	0.39	<0.5	10	8	72	2.53
E856536		2.90	0.078	0.2	0.61	26	<10	270	<0.5	3	0.30	<0.5	11	15	102	1.98

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094738

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E856496		<10	<1	0.31	30	0.47	268	<1	0.02	36	300	17	0.15	7	1	8
E856497		<10	1	0.28	30	0.47	385	<1	0.02	24	330	28	0.06	4	1	28
E856498		<10	<1	0.21	20	0.41	487	<1	0.02	16	230	24	0.22	8	1	73
E856499		10	1	0.21	10	1.29	463	<1	0.03	40	1260	41	0.32	4	5	83
E856500		10	1	0.23	20	1.57	596	<1	0.03	48	1320	20	0.25	7	6	132
E856501		10	1	0.19	10	1.64	629	<1	0.02	44	1320	5	0.33	6	6	142
E856502		10	1	0.20	10	1.97	711	<1	0.03	48	1490	8	0.32	10	7	101
E856503		20	1	0.03	<10	2.36	786	<1	0.02	47	2040	<2	0.13	4	10	334
E856504		20	2	0.02	<10	2.81	1465	<1	0.02	49	2260	<2	0.11	<2	11	228
E856505		20	2	<0.01	<10	3.01	1355	<1	0.02	54	2550	<2	0.15	<2	13	195
E856506		20	2	<0.01	<10	3.02	1575	<1	0.02	56	2530	<2	0.15	<2	13	191
E856507		20	1	0.08	10	2.70	1450	<1	0.02	42	1790	8	0.07	<2	8	486
E856508		20	1	0.11	10	2.25	1315	<1	0.02	44	1630	6	0.10	2	8	394
E856509		10	1	0.10	10	2.25	1335	<1	0.02	42	1630	5	0.11	<2	8	398
E856510		<10	1	0.32	10	0.10	302	1	0.04	4	710	5130	8.2	1635	1	142
E856511		20	2	0.01	<10	2.85	1015	<1	0.03	52	2440	13	0.14	3	12	209
E856512		<10	<1	0.17	10	0.97	888	<1	0.03	46	450	19	0.47	10	3	390
E856513		<10	1	0.17	20	0.70	468	<1	0.02	21	510	22	0.21	9	2	70
E856514		<10	1	0.17	20	0.35	199	<1	0.01	17	290	22	0.10	10	1	24
E856515		<10	1	0.15	10	0.42	388	1	0.02	18	220	12	0.35	16	1	75
E856516		<10	<1	0.10	10	0.07	160	<1	0.02	21	90	12	0.43	27	1	22
E856518		<10	<1	0.09	<10	0.41	578	5	0.02	36	490	11	0.87	24	1	84
E856519		<10	<1	0.10	10	0.60	1860	<1	0.02	25	280	7	0.25	18	2	55
E856520		<10	1	0.10	<10	0.69	3010	<1	0.02	16	590	7	0.10	24	2	193
E856521		<10	1	0.11	<10	1.12	16650	<1	0.03	20	2020	16	0.43	47	2	243
E856522		<10	1	0.09	<10	0.93	15550	<1	0.02	19	1880	14	0.31	35	2	203
E856523		<10	<1	0.09	<10	0.47	823	<1	0.02	16	200	7	1.04	33	1	128
E856524		<10	1	0.08	<10	0.84	591	<1	0.02	17	220	12	0.60	120	2	218
E856525		<10	1	0.10	<10	1.23	1160	9	0.02	23	290	12	0.58	59	2	308
E856526		<10	1	0.10	10	0.46	631	1	0.02	29	300	17	0.42	34	1	57
E856527		<10	1	0.12	10	0.63	1300	<1	0.03	35	310	17	0.88	31	2	81
E856528		<10	<1	0.11	10	0.44	755	1	0.02	41	290	12	0.44	21	1	40
E856529		<10	<1	0.13	10	0.45	763	<1	0.03	42	300	11	0.46	23	1	41
E856530		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	<0.01	<2	<1	1
E856531		<10	<1	0.10	10	0.39	834	<1	0.02	29	230	8	0.29	23	1	37
E856532		<10	<1	0.11	10	0.54	912	1	0.02	45	340	15	0.34	13	1	32
E856533		<10	1	0.13	10	0.68	701	<1	0.02	47	300	14	0.42	11	1	43
E856534		<10	<1	0.08	10	0.70	2300	<1	0.02	29	360	22	0.95	11	2	56
E856535		<10	1	0.09	10	0.51	2470	<1	0.02	26	340	11	0.50	8	1	50
E856536		<10	1	0.09	10	0.45	1900	<1	0.01	35	310	10	0.27	7	1	34

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094738

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E856496		20	0.03	<10	<10	12	<10	69		
E856497		20	0.02	<10	<10	11	<10	58		
E856498		<20	0.01	<10	<10	7	<10	47		
E856499		<20	0.22	<10	<10	51	<10	91		
E856500		<20	0.21	<10	<10	58	<10	108		
E856501		<20	0.11	<10	<10	53	<10	90		
E856502		<20	0.15	<10	<10	63	<10	106		
E856503		<20	0.19	<10	<10	84	<10	108		
E856504		<20	0.05	<10	<10	81	<10	147		
E856505		<20	0.04	<10	<10	87	<10	155		
E856506		<20	0.03	<10	<10	88	<10	158		
E856507		<20	0.01	<10	<10	58	<10	121		
E856508		<20	0.01	<10	<10	52	<10	114		
E856509		<20	0.01	<10	<10	52	<10	116		
E856510		<20	<0.01	10	<10	6	<10	>10000	1.260	134
E856511		<20	0.02	<10	<10	80	<10	178		
E856512		<20	<0.01	<10	<10	11	<10	64		
E856513		<20	<0.01	<10	<10	12	<10	71		
E856514		<20	<0.01	<10	<10	5	<10	53		
E856515		<20	<0.01	<10	<10	6	<10	54		
E856516		<20	<0.01	<10	<10	6	<10	48		
E856518		<20	<0.01	<10	<10	17	<10	127		
E856519		<20	<0.01	<10	<10	16	<10	62		
E856520		<20	<0.01	<10	<10	10	<10	41		
E856521		<20	<0.01	<10	<10	9	<10	49		
E856522		<20	<0.01	<10	<10	8	<10	43		
E856523		<20	<0.01	<10	<10	7	<10	49		
E856524		<20	<0.01	<10	<10	10	<10	60		
E856525		<20	<0.01	<10	<10	13	<10	59		
E856526		<20	<0.01	<10	<10	12	<10	80		
E856527		<20	<0.01	<10	<10	18	<10	115		
E856528		<20	<0.01	<10	<10	12	<10	94		
E856529		<20	<0.01	<10	<10	14	<10	99		
E856530		<20	<0.01	<10	<10	<1	<10	2		
E856531		<20	<0.01	<10	<10	12	<10	70		
E856532		<20	<0.01	<10	<10	16	<10	81		
E856533		<20	<0.01	<10	<10	19	<10	105		
E856534		<20	<0.01	<10	<10	17	<10	98		
E856535		<20	<0.01	<10	<10	11	<10	60		
E856536		<20	<0.01	<10	<10	15	<10	49		

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094738

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1	ME-ICP41 Fe % 0.01
E856537		3.48	0.025	0.2	0.51	23	<10	250	<0.5	2	0.08	<0.5	12	11	98	1.62
E856538		2.77	0.015	<0.2	0.54	24	<10	220	<0.5	2	1.04	<0.5	11	13	92	1.92
E856539		4.26	0.017	0.2	0.71	12	<10	220	<0.5	3	0.39	<0.5	8	19	86	1.82
E856540		4.42	0.016	0.2	0.49	6	<10	210	<0.5	3	0.41	<0.5	9	13	79	1.73
E856541		3.05	0.021	0.2	0.41	14	<10	220	<0.5	3	0.57	<0.5	10	18	68	1.93
E856542		2.59	0.022	0.2	0.38	13	<10	210	<0.5	3	0.55	<0.5	10	11	76	1.95
E856543		3.33	0.017	<0.2	0.66	19	<10	190	<0.5	3	1.26	<0.5	8	16	83	2.00
E856544		4.37	0.027	<0.2	0.54	11	<10	130	<0.5	2	0.20	<0.5	6	12	55	1.32
E856545		5.57	0.115	0.2	0.80	293	<10	230	<0.5	2	0.27	<0.5	9	19	95	2.28
E856546		4.47	0.074	0.3	0.72	142	<10	210	<0.5	3	0.30	<0.5	11	14	107	2.24
E856547		3.82	0.051	0.2	0.57	86	<10	270	<0.5	2	0.39	<0.5	11	18	114	1.95
E856548		3.51	0.052	0.2	0.38	102	<10	230	<0.5	<2	0.19	<0.5	9	16	97	1.74
E856549		<0.02	0.050	0.2	0.39	97	<10	240	<0.5	4	0.19	<0.5	9	17	95	1.77
E856550		0.10	<0.005	0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.02
E856551		3.77	0.068	0.4	0.79	298	<10	220	<0.5	2	0.27	<0.5	10	17	78	2.54
E856552		3.98	0.017	<0.2	0.72	25	<10	200	<0.5	2	0.21	<0.5	7	13	89	2.06
E856553		3.91	0.021	<0.2	0.72	23	<10	220	<0.5	3	0.57	<0.5	12	15	89	2.53
E856554		3.51	0.009	<0.2	0.90	21	<10	170	<0.5	2	0.27	<0.5	13	11	96	3.18
E856555		3.78	0.028	<0.2	0.81	26	<10	200	<0.5	5	0.89	<0.5	11	13	76	3.09
E856556		3.28	0.092	0.5	0.65	369	<10	280	<0.5	3	0.60	<0.5	10	13	87	2.91
E856557		2.52	0.105	0.6	0.26	664	<10	220	<0.5	3	0.35	<0.5	10	9	79	2.04
E856558		1.63	0.027	<0.2	0.39	96	<10	330	<0.5	2	0.17	<0.5	15	10	91	2.20
E856559		1.44	0.021	<0.2	0.36	69	<10	210	<0.5	2	0.20	<0.5	8	9	67	2.51
E856560		2.32	<0.005	<0.2	1.73	11	<10	140	<0.5	2	0.38	<0.5	16	18	29	3.59
E856578		1.02	0.017	0.2	0.39	34	<10	240	<0.5	3	0.09	<0.5	10	10	98	2.44

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094738

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E856537		<10	<1	0.07	10	0.33	464	<1	0.01	30	150	10	0.18	5	1	12
E856538		<10	<1	0.07	10	0.56	3200	<1	0.01	32	340	9	0.19	13	1	103
E856539		<10	<1	0.09	10	0.50	1130	<1	0.01	26	120	10	0.21	17	1	40
E856540		<10	<1	0.09	10	0.41	791	<1	0.01	26	430	11	0.59	10	1	50
E856541		<10	<1	0.10	10	0.42	1330	1	0.01	31	160	13	0.72	24	1	68
E856542		<10	<1	0.09	10	0.41	1330	1	0.01	32	150	13	0.73	24	1	65
E856543		<10	<1	0.09	10	0.73	5160	<1	0.01	24	460	10	0.16	26	2	117
E856544		<10	1	0.07	10	0.37	2770	<1	0.01	14	130	9	0.12	18	1	22
E856545		<10	<1	0.11	10	0.59	2460	<1	0.01	24	470	8	0.33	33	1	41
E856546		<10	<1	0.09	10	0.50	1480	<1	0.01	34	290	15	0.42	48	1	41
E856547		<10	<1	0.09	10	0.44	2090	<1	0.01	37	220	9	0.34	55	1	47
E856548		<10	<1	0.08	10	0.39	1300	<1	0.02	33	200	10	0.37	46	1	27
E856549		<10	<1	0.09	10	0.38	1330	<1	0.02	33	200	10	0.36	43	1	27
E856550		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	<0.01	<2	<1	1
E856551		<10	1	0.12	10	0.63	1550	2	0.02	30	390	13	0.37	43	2	44
E856552		<10	<1	0.09	10	0.57	742	<1	0.01	21	150	7	0.16	41	1	35
E856553		<10	<1	0.13	10	0.75	2530	<1	0.01	24	380	17	0.13	29	2	58
E856554		<10	<1	0.12	10	0.86	1510	<1	0.01	27	340	9	0.15	41	2	43
E856555		<10	<1	0.14	10	0.88	3510	<1	0.02	26	790	13	0.19	45	3	98
E856556		<10	<1	0.13	10	0.78	2000	<1	0.02	27	290	8	0.45	52	2	89
E856557		<10	<1	0.08	10	0.44	856	<1	0.01	30	200	6	0.70	46	2	59
E856558		<10	<1	0.15	10	0.49	284	<1	0.01	34	190	10	0.49	32	2	40
E856559		<10	<1	0.10	10	0.58	259	<1	0.01	25	230	12	0.38	39	2	34
E856560		<10	<1	0.23	20	0.84	578	<1	0.02	30	280	8	0.08	5	1	23
E856578		<10	<1	0.11	10	0.54	238	<1	0.02	21	200	6	0.37	50	2	18

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094738

Sample Description	Method / Analyte / Units / LOR	ME-ICP41 Th ppm 20	ME-ICP41 Ti % 0.01	ME-ICP41 Tl ppm 10	ME-ICP41 U ppm 10	ME-ICP41 V ppm 1	ME-ICP41 W ppm 10	ME-ICP41 Zn ppm 2	Zn-OG46 Zn % 0.001	Ag-GRA21 Ag ppm 5
E856537		<20	<0.01	<10	<10	12	<10	35		
E856538		<20	<0.01	<10	<10	13	<10	43		
E856539		<20	<0.01	<10	<10	16	<10	39		
E856540		<20	<0.01	<10	<10	13	<10	47		
E856541		<20	<0.01	<10	<10	12	<10	40		
E856542		<20	<0.01	<10	<10	10	<10	40		
E856543		<20	0.01	<10	<10	14	<10	39		
E856544		<20	<0.01	<10	<10	11	<10	30		
E856545		<20	<0.01	<10	<10	17	<10	45		
E856546		<20	<0.01	<10	<10	15	<10	56		
E856547		<20	<0.01	<10	<10	13	<10	68		
E856548		<20	<0.01	<10	<10	9	<10	46		
E856549		<20	<0.01	<10	<10	9	<10	44		
E856550		<20	<0.01	<10	<10	<1	<10	<2		
E856551		<20	<0.01	<10	<10	16	<10	64		
E856552		<20	<0.01	<10	<10	15	<10	46		
E856553		<20	<0.01	<10	<10	15	<10	56		
E856554		<20	<0.01	<10	<10	17	<10	67		
E856555		<20	<0.01	<10	<10	15	<10	66		
E856556		<20	<0.01	<10	<10	12	<10	66		
E856557		<20	<0.01	<10	<10	7	<10	62		
E856558		<20	<0.01	<10	<10	10	<10	74		
E856559		<20	<0.01	<10	<10	9	<10	77		
E856560		<20	<0.01	<10	<10	10	<10	70		
E856578		<20	<0.01	<10	<10	11	<10	68		

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

CERTIFICATE WH10094736

Project: ALN10-01

P.O. No.: ALN10-01_13

This report is for 81 GRAB samples submitted to our lab in Whitehorse, YT, Canada on 13-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature: 

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	WEI-21	Au-AA23	Au-GRA21	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu
	Units	kg	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.05	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1
E858005		1.73	<0.005		<0.2	0.44	4	<10	60	<0.5	<2	0.36	<0.5	3	9	5
E858006		1.09	<0.005		<0.2	0.80	3	<10	80	<0.5	<2	0.47	<0.5	6	9	9
E858007		1.03	<0.005		<0.2	1.14	3	<10	80	<0.5	<2	0.68	<0.5	15	13	30
E858008		1.71	<0.005		<0.2	1.46	2	<10	100	<0.5	<2	0.26	<0.5	19	13	42
E858009		<0.02	0.024		<0.2	1.48	2	<10	110	<0.5	<2	0.21	<0.5	18	13	38
E858010		0.11	0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1
E858011		2.15	<0.005		<0.2	1.13	<2	<10	80	<0.5	<2	0.59	<0.5	15	12	26
E858012		2.19	<0.005		<0.2	1.07	2	<10	70	<0.5	<2	0.63	<0.5	14	14	17
E858013		1.86	<0.005		<0.2	1.69	<2	<10	70	<0.5	<2	0.39	<0.5	20	24	21
E858014		2.37	0.005		<0.2	1.33	3	<10	70	<0.5	<2	0.52	<0.5	17	13	38
E858015		1.65	<0.005		<0.2	1.55	<2	<10	50	<0.5	<2	0.66	<0.5	18	17	36
E858016		1.96	<0.005		<0.2	1.74	<2	<10	70	<0.5	<2	0.38	<0.5	19	17	23
E858017		1.50	<0.005		<0.2	1.45	<2	<10	50	<0.5	<2	0.66	<0.5	17	18	35
E858018		1.83	<0.005		<0.2	1.49	<2	<10	80	<0.5	<2	0.29	<0.5	19	14	85
E858019		2.33	<0.005		<0.2	1.36	<2	<10	80	<0.5	<2	0.57	<0.5	17	14	35
E858020		2.00	0.089		0.2	1.27	3	<10	80	<0.5	<2	2.77	<0.5	15	13	111
E858021		1.69	<0.005		0.3	1.16	16	<10	50	<0.5	<2	14.0	<0.5	12	8	22
E858022		0.98	<0.005		0.2	1.22	14	<10	50	<0.5	<2	12.6	<0.5	11	8	20
E858023		3.05	0.005		<0.2	1.40	21	<10	50	<0.5	<2	9.9	<0.5	15	10	29
E858024		2.28	<0.005		0.3	0.33	9	<10	30	<0.5	<2	19.8	<0.5	5	<1	11
E858025		2.84	<0.005		0.2	1.20	4	<10	60	<0.5	<2	6.57	<0.5	9	8	20
E858026		1.46	<0.005		0.2	1.22	8	<10	70	<0.5	<2	3.69	<0.5	11	8	22
E858027		2.22	<0.005		<0.2	0.74	7	<10	60	<0.5	<2	1.04	<0.5	10	6	20
E858028		2.11	0.006		<0.2	1.39	7	<10	80	<0.5	<2	0.82	<0.5	13	11	28
E858029		<0.02	<0.005		0.2	1.32	4	<10	80	<0.5	<2	0.84	<0.5	13	10	24
E858030		0.12	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1
E858031		2.07	<0.005		<0.2	1.52	10	<10	70	<0.5	<2	1.98	<0.5	12	16	26
E858032		1.95	<0.005		<0.2	1.26	9	<10	60	<0.5	<2	2.91	<0.5	11	10	25
E858033		2.12	0.006		7.2	1.17	43	<10	130	<0.5	<2	2.44	<0.5	13	21	37
E858034		2.57	0.006		0.2	1.03	3	<10	50	<0.5	2	3.28	<0.5	8	14	17
E858035		2.09	<0.005		<0.2	1.07	6	<10	50	<0.5	2	1.64	<0.5	9	15	15
E858036		1.54	<0.005		<0.2	0.78	<2	<10	40	<0.5	3	1.79	<0.5	5	14	7
E858037		1.82	<0.005		<0.2	0.61	<2	<10	40	<0.5	2	2.76	<0.5	5	10	4
E858038		1.75	<0.005		0.2	1.16	6	<10	60	<0.5	4	0.98	<0.5	13	17	24
E858039		2.39	<0.005		<0.2	1.09	3	<10	70	<0.5	<2	0.95	<0.5	12	14	20
E858040		2.68	<0.005		<0.2	0.61	2	<10	50	<0.5	3	1.43	<0.5	6	9	8
E858041		1.38	<0.005		<0.2	0.81	4	<10	50	<0.5	2	1.82	<0.5	8	11	13
E858042		1.20	0.005		<0.2	1.48	8	<10	70	<0.5	3	0.52	<0.5	17	16	27
E858043		2.20	<0.005		<0.2	1.09	2	<10	60	<0.5	<2	8.3	<0.5	10	11	20
E858044		1.81	<0.005		<0.2	0.36	5	<10	40	<0.5	2	6.52	<0.5	5	6	5

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E858005		1.00	<10	<1	0.23	20	0.17	159	<1	0.02	4	140	16	0.05	<2	<1
E858006		1.82	<10	<1	0.20	10	0.43	334	<1	0.03	8	340	8	0.06	<2	2
E858007		2.56	<10	<1	0.28	20	0.67	1360	2	0.03	27	280	40	0.11	<2	1
E858008		3.35	<10	<1	0.32	40	0.74	863	<1	0.02	34	290	7	0.01	<2	1
E858009		3.41	<10	<1	0.36	40	0.71	731	<1	0.02	34	290	7	0.01	<2	1
E858010		0.02	<10	<1	<0.01	<10	<0.01	<5	<1	0.01	<1	10	2	0.01	<2	<1
E858011		2.74	<10	<1	0.27	30	0.70	1710	<1	0.03	26	320	9	0.01	<2	1
E858012		2.67	<10	<1	0.25	30	0.70	1445	<1	0.03	24	300	9	0.02	<2	1
E858013		3.28	10	<1	0.25	40	1.02	1190	<1	0.03	32	240	9	0.01	<2	2
E858014		2.55	<10	<1	0.25	30	0.80	1125	<1	0.02	26	200	8	0.01	4	1
E858015		2.90	<10	<1	0.19	30	0.92	1975	1	0.03	29	240	21	0.01	2	1
E858016		3.45	10	<1	0.25	40	0.96	1025	<1	0.02	31	250	4	0.01	<2	1
E858017		2.62	<10	<1	0.19	30	0.85	1505	<1	0.03	24	230	23	0.02	<2	1
E858018		2.98	<10	<1	0.27	30	0.88	569	<1	0.02	31	310	24	0.01	<2	1
E858019		3.11	<10	1	0.26	30	0.82	626	<1	0.02	38	330	4	<0.01	<2	1
E858020		2.93	<10	<1	0.26	20	0.74	908	<1	0.02	30	340	20	0.02	<2	1
E858021		1.98	<10	<1	0.21	20	0.61	1865	<1	0.02	15	370	19	0.05	<2	2
E858022		2.10	<10	<1	0.22	20	0.61	1655	<1	0.02	15	360	19	0.06	<2	2
E858023		2.75	<10	<1	0.22	20	0.74	908	1	0.02	21	370	18	0.33	<2	2
E858024		1.39	<10	<1	0.13	10	0.28	1345	2	0.02	8	300	28	0.8	<2	1
E858025		2.88	<10	<1	0.25	20	0.54	642	<1	0.02	17	300	15	0.46	<2	1
E858026		2.30	<10	<1	0.28	20	0.52	618	<1	0.02	16	260	8	0.05	<2	1
E858027		1.51	<10	<1	0.24	20	0.33	208	<1	0.01	15	300	40	0.10	<2	1
E858028		2.76	<10	<1	0.32	20	0.61	198	<1	0.02	25	440	43	0.14	<2	1
E858029		2.62	<10	<1	0.31	20	0.59	204	<1	0.02	24	390	66	0.13	<2	1
E858030		0.02	<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	2	<0.01	<2	<1
E858031		3.03	<10	<1	0.29	30	0.65	429	<1	0.02	20	250	7	0.05	<2	1
E858032		2.43	<10	<1	0.24	20	0.60	554	<1	0.02	17	240	13	0.06	<2	1
E858033		2.52	<10	<1	0.26	20	0.56	573	3	0.02	20	230	23	0.06	<2	1
E858034		2.21	<10	<1	0.19	20	0.46	566	<1	0.03	16	170	14	0.02	<2	1
E858035		2.29	<10	<1	0.21	20	0.54	451	<1	0.02	18	150	16	0.07	<2	1
E858036		1.65	<10	<1	0.17	20	0.39	490	<1	0.03	9	130	12	0.05	<2	1
E858037		1.63	<10	<1	0.15	20	0.35	535	<1	0.02	7	170	14	0.05	<2	1
E858038		2.85	<10	1	0.24	20	0.62	337	<1	0.02	22	200	145	0.17	7	1
E858039		2.75	<10	<1	0.29	20	0.61	314	<1	0.03	22	290	21	0.13	<2	1
E858040		1.78	<10	<1	0.19	20	0.38	331	<1	0.02	10	170	18	0.07	2	1
E858041		2.11	<10	<1	0.23	20	0.44	408	<1	0.03	13	270	19	0.09	<2	1
E858042		3.61	<10	1	0.26	30	0.70	189	<1	0.01	24	380	20	0.15	<2	1
E858043		2.41	<10	<1	0.27	20	0.53	983	<1	0.02	15	350	23	0.11	<2	2
E858044		1.14	<10	<1	0.13	10	0.28	665	<1	0.02	6	260	13	0.05	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E858005		51	<20	0.02	<10	<10	3	<10	16			
E858006		38	<20	0.04	<10	<10	22	<10	34			
E858007		42	20	0.02	<10	<10	8	<10	63			
E858008		31	20	0.04	<10	<10	12	<10	78			
E858009		27	20	0.05	<10	<10	12	<10	76			
E858010		1	<20	<0.01	<10	<10	<1	<10	2			
E858011		60	20	0.04	<10	<10	15	<10	67			
E858012		66	<20	0.05	<10	<10	11	<10	66			
E858013		43	20	0.03	<10	<10	10	<10	97			
E858014		47	20	0.03	<10	<10	11	<10	75			
E858015		66	20	0.01	<10	<10	13	<10	83			
E858016		37	20	0.01	<10	<10	10	<10	89			
E858017		52	<20	0.01	<10	<10	13	<10	73			
E858018		25	<20	0.04	<10	<10	11	<10	76			
E858019		46	<20	0.05	<10	<10	14	<10	74			
E858020		191	<20	0.06	<10	10	14	<10	64			
E858021		323	20	0.02	<10	<10	7	<10	35			
E858022		291	<20	0.02	<10	<10	7	<10	34			
E858023		290	<20	0.01	<10	<10	8	<10	45			
E858024		712	<20	0.01	<10	<10	2	<10	28			
E858025		317	20	0.01	<10	<10	7	<10	54			
E858026		214	<20	0.02	<10	<10	7	<10	45			
E858027		62	<20	0.01	<10	<10	4	<10	31			
E858028		54	20	0.01	<10	<10	8	<10	57			
E858029		54	20	0.01	<10	<10	7	<10	54			
E858030		1	<20	<0.01	<10	<10	<1	<10	2			
E858031		115	20	0.02	<10	<10	10	<10	54			
E858032		187	<20	0.02	<10	<10	7	<10	48			
E858033		133	<20	0.02	<10	<10	7	20	54			
E858034		196	<20	0.01	<10	<10	7	<10	51			
E858035		99	<20	0.01	<10	<10	7	<10	60			
E858036		107	<20	0.01	<10	<10	5	<10	32			
E858037		172	<20	<0.01	<10	<10	4	<10	30			
E858038		62	<20	<0.01	<10	<10	6	<10	62			
E858039		53	<20	<0.01	<10	<10	7	<10	61			
E858040		77	<20	<0.01	<10	<10	3	<10	35			
E858041		89	<20	<0.01	<10	<10	5	<10	43			
E858042		37	20	<0.01	<10	<10	10	<10	59			
E858043		434	<20	<0.01	<10	<10	7	<10	39			
E858044		308	<20	<0.01	<10	<10	2	<10	15			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E858045		1.82	<0.005		<0.2	0.95	<2	<10	80	<0.5	2	2.23	<0.5	8	9	21
E858046		1.81	<0.005		<0.2	1.09	6	<10	70	<0.5	2	0.49	<0.5	12	12	29
E858047		1.58	<0.005		<0.2	0.77	<2	<10	70	<0.5	3	2.43	<0.5	7	10	14
E858048		2.03	<0.005		<0.2	0.62	<2	<10	50	<0.5	2	2.64	<0.5	7	8	13
E858049		<0.02	<0.005		<0.2	0.64	<2	<10	60	<0.5	2	2.56	<0.5	7	8	13
E858050		0.09	1.625	1.79	>100	0.39	4460	<10	30	<0.5	12	0.83	509	6	56	882
E858051		1.89	<0.005		0.6	0.48	27	<10	60	<0.5	2	5.58	0.9	15	6	26
E858052		2.44	<0.005		0.2	0.85	2	<10	70	<0.5	3	2.27	<0.5	11	9	21
E858053		1.97	0.005		<0.2	0.66	3	<10	50	<0.5	<2	8.1	<0.5	7	8	13
E858054		1.87	<0.005		<0.2	0.70	<2	<10	60	<0.5	2	7.4	<0.5	8	9	16
E858055		1.75	<0.005		<0.2	0.69	<2	<10	50	<0.5	<2	6.6	<0.5	7	10	13
E858056		1.87	<0.005		<0.2	0.64	2	<10	60	<0.5	<2	10.0	<0.5	6	7	14
E858057		2.75	<0.005		<0.2	1.17	3	<10	70	<0.5	2	1.78	<0.5	7	15	17
E858058		2.52	<0.005		0.6	1.23	2	<10	70	<0.5	3	1.42	<0.5	10	15	23
E858059		2.72	0.005		<0.2	1.35	7	<10	80	<0.5	3	0.48	<0.5	15	30	30
E858060		1.75	<0.005		<0.2	0.73	<2	<10	60	<0.5	2	6.08	<0.5	9	9	16
E858061		1.54	<0.005		<0.2	0.28	<2	<10	50	<0.5	<2	20.0	<0.5	4	3	8
E858062		1.29	<0.005		<0.2	0.29	4	<10	50	<0.5	<2	17.8	<0.5	5	3	9
E858063		2.43	<0.005		<0.2	0.55	<2	<10	50	<0.5	3	10.8	<0.5	6	8	11
E858064		3.01	<0.005		<0.2	0.47	<2	<10	40	<0.5	<2	5.47	<0.5	5	13	9
E858065		1.73	<0.005		<0.2	0.80	2	<10	60	<0.5	2	9.1	<0.5	8	9	17
E858066		2.25	<0.005		<0.2	0.63	2	<10	80	<0.5	2	10.4	<0.5	10	7	21
E858067		2.00	0.006		<0.2	0.27	8	<10	90	<0.5	<2	20.7	<0.5	4	2	10
E858068		1.97	0.006		<0.2	0.45	4	<10	80	<0.5	2	8.8	<0.5	11	5	19
E858069		<0.02	<0.005		<0.2	0.52	3	<10	90	<0.5	<2	8.4	<0.5	10	6	19
E858070		0.11	<0.005		<0.2	0.01	<2	<10	10	<0.5	2	0.01	<0.5	<1	<1	13
E858071		1.89	0.005		<0.2	0.42	5	<10	60	<0.5	<2	9.6	<0.5	10	5	18
E858072		1.92	<0.005		<0.2	1.40	3	<10	70	<0.5	<2	3.81	<0.5	10	16	22
E858073		2.03	<0.005		<0.2	1.28	2	<10	70	<0.5	<2	3.75	<0.5	11	16	22
E858074		2.00	<0.005		<0.2	1.46	<2	<10	90	<0.5	<2	1.86	<0.5	11	17	23
E858075		2.53	<0.005		<0.2	1.33	6	<10	70	<0.5	<2	0.54	<0.5	10	17	20
E858076		2.71	<0.005		<0.2	1.30	2	<10	70	<0.5	<2	1.88	<0.5	7	18	16
E858077		2.27	<0.005		<0.2	0.94	4	<10	60	<0.5	<2	11.4	<0.5	7	10	16
E858078		1.44	<0.005		<0.2	0.75	3	<10	70	<0.5	<2	13.3	<0.5	6	9	16
E858079		2.04	<0.005		<0.2	0.12	3	<10	40	<0.5	<2	18.4	<0.5	3	1	5
E858080		1.97	0.005		<0.2	0.41	3	<10	60	<0.5	<2	16.8	<0.5	6	4	15
E858081		1.51	<0.005		0.2	0.13	2	<10	50	<0.5	<2	19.8	<0.5	2	1	5
E858082		1.14	<0.005		0.2	0.13	2	<10	50	<0.5	<2	18.2	<0.5	3	1	6
E858083		2.04	<0.005		0.2	0.19	<2	<10	60	<0.5	<2	19.8	<0.5	4	1	10
E858084		2.68	<0.005		<0.2	0.12	<2	<10	40	<0.5	<2	19.7	<0.5	3	1	4

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E858045		2.15	<10	<1	0.23	20	0.79	375	<1	0.02	17	230	12	0.17	3	1
E858046		2.25	<10	<1	0.22	30	0.55	137	<1	0.01	24	450	15	0.19	3	1
E858047		2.05	<10	1	0.19	10	0.79	392	<1	0.02	14	200	13	0.19	<2	1
E858048		1.83	<10	<1	0.17	20	0.79	403	<1	0.02	13	230	15	0.19	2	1
E858049		1.86	<10	1	0.18	20	0.77	395	<1	0.02	12	230	14	0.19	<2	1
E858050		6.94	<10	2	0.26	10	0.27	377	1	0.03	5	560	>10000	9.7	2610	1
E858051		2.20	<10	1	0.20	10	0.87	591	<1	0.02	20	290	50	0.45	5	1
E858052		2.85	<10	1	0.23	10	0.99	433	<1	0.02	19	290	24	0.48	2	1
E858053		2.18	<10	<1	0.16	10	0.63	513	<1	0.02	15	200	20	0.48	<2	1
E858054		2.13	<10	1	0.20	10	0.54	393	<1	0.02	17	220	16	0.56	<2	1
E858055		2.10	<10	1	0.17	10	0.46	312	<1	0.02	16	270	15	0.64	<2	1
E858056		1.83	<10	<1	0.20	10	0.41	383	<1	0.02	14	270	9	0.49	<2	1
E858057		2.38	<10	1	0.25	20	0.61	185	<1	0.02	17	270	12	0.15	<2	1
E858058		3.00	<10	<1	0.23	20	0.66	178	<1	0.02	24	280	21	0.40	<2	1
E858059		3.08	<10	<1	0.26	20	0.71	124	<1	0.01	36	440	15	0.27	<2	1
E858060		2.22	<10	1	0.22	10	0.45	424	<1	0.02	20	180	20	0.60	<2	1
E858061		1.33	<10	1	0.11	10	0.26	318	<1	0.02	9	320	10	0.6	<2	1
E858062		1.38	<10	<1	0.12	10	0.27	311	<1	0.01	11	310	10	0.6	<2	1
E858063		1.74	<10	<1	0.13	10	0.37	314	<1	0.02	15	340	12	0.59	<2	1
E858064		1.30	<10	1	0.11	10	0.33	245	<1	0.02	10	160	14	0.35	<2	1
E858065		2.01	<10	<1	0.15	10	0.55	355	<1	0.02	17	180	12	0.48	<2	1
E858066		2.15	<10	1	0.15	10	0.63	480	<1	0.02	21	230	16	0.72	<2	1
E858067		1.51	<10	1	0.11	10	0.48	308	<1	0.02	10	520	11	0.9	2	2
E858068		2.46	<10	<1	0.16	10	0.87	454	<1	0.02	20	330	16	0.99	<2	1
E858069		2.51	<10	<1	0.19	10	0.84	443	<1	0.03	21	330	15	0.97	<2	1
E858070		0.03	<10	<1	<0.01	<10	<0.01	<5	2	<0.01	13	10	15	0.01	<2	<1
E858071		2.97	<10	<1	0.14	10	1.07	470	1	0.02	21	300	27	1.01	<2	2
E858072		3.25	<10	<1	0.23	10	0.74	406	1	0.03	21	290	21	0.67	<2	2
E858073		3.10	<10	<1	0.21	10	0.73	246	<1	0.02	22	200	12	0.71	<2	1
E858074		3.00	<10	<1	0.22	20	0.77	205	<1	0.02	23	170	8	0.40	<2	1
E858075		2.60	<10	<1	0.20	20	0.68	137	<1	0.02	22	180	12	0.10	<2	1
E858076		2.71	<10	<1	0.19	20	0.68	208	<1	0.02	19	180	7	0.27	<2	1
E858077		2.41	<10	<1	0.15	10	0.61	220	<1	0.02	17	410	7	0.76	<2	1
E858078		2.31	<10	<1	0.15	10	0.56	358	<1	0.02	15	160	17	0.89	<2	2
E858079		1.08	<10	<1	0.08	<10	0.28	276	<1	0.02	4	170	7	0.7	<2	1
E858080		2.00	<10	<1	0.13	10	0.39	242	<1	0.02	14	350	10	1.02	4	1
E858081		1.04	<10	<1	0.08	<10	0.24	292	<1	0.01	5	170	7	0.8	<2	1
E858082		1.18	<10	<1	0.08	<10	0.30	288	<1	0.01	5	180	7	0.7	<2	1
E858083		1.52	<10	<1	0.11	<10	0.31	291	<1	0.02	7	410	11	1.0	<2	2
E858084		1.05	<10	<1	0.08	<10	0.26	275	<1	0.01	4	220	9	0.7	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E858045		147	<20	<0.01	<10	<10	5	<10	56			
E858046		25	20	<0.01	<10	<10	5	<10	59			
E858047		98	<20	<0.01	<10	<10	4	<10	43			
E858048		86	<20	<0.01	<10	<10	3	<10	33			
E858049		83	<20	<0.01	<10	<10	3	<10	32			
E858050		112	<20	<0.01	<10	<10	5	10	>10000	1.925	3.72	NSS
E858051		216	<20	<0.01	<10	<10	3	<10	198			
E858052		63	<20	<0.01	<10	<10	5	<10	51			
E858053		340	<20	<0.01	<10	<10	4	<10	39			
E858054		285	<20	<0.01	<10	<10	5	<10	43			
E858055		288	<20	<0.01	<10	<10	5	<10	44			
E858056		435	<20	<0.01	<10	<10	4	<10	33			
E858057		99	<20	0.01	<10	<10	7	<10	42			
E858058		73	<20	0.01	<10	<10	8	<10	51			
E858059		26	<20	0.02	<10	<10	12	<10	39			
E858060		307	<20	0.01	<10	<10	5	<10	38			
E858061		740	<20	<0.01	<10	<10	3	<10	24			
E858062		659	<20	<0.01	<10	<10	2	<10	26			
E858063		410	<20	<0.01	<10	<10	4	<10	31			
E858064		197	<20	<0.01	<10	<10	3	<10	25			
E858065		346	<20	<0.01	<10	<10	5	<10	44			
E858066		385	<20	<0.01	<10	<10	4	<10	46			
E858067		669	<20	<0.01	<10	<10	3	<10	31			
E858068		295	<20	<0.01	<10	<10	3	<10	56			
E858069		279	20	<0.01	<10	<10	4	<10	56			
E858070		2	<20	<0.01	<10	<10	<1	<10	12			
E858071		350	<20	<0.01	<10	<10	3	<10	64			
E858072		176	<20	0.01	<10	<10	10	<10	63			
E858073		232	<20	0.01	<10	<10	8	<10	65			
E858074		122	20	0.01	<10	<10	10	<10	66			
E858075		32	<20	0.01	<10	<10	9	<10	58			
E858076		97	<20	0.01	<10	<10	10	<10	57			
E858077		467	20	<0.01	<10	<10	5	<10	55			
E858078		515	<20	<0.01	<10	<10	4	<10	44			
E858079		511	<20	<0.01	<10	<10	<1	<10	16			
E858080		709	<20	<0.01	<10	<10	1	<10	25			
E858081		551	<20	<0.01	<10	<10	<1	<10	18			
E858082		531	<20	<0.01	<10	<10	<1	<10	17			
E858083		709	<20	<0.01	<10	<10	<1	<10	29			
E858084		789	<20	<0.01	<10	<10	<1	<10	16			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E858085		2.54	<0.005		<0.2	0.51	<2	<10	60	<0.5	<2	9.8	<0.5	8	4	20

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E858085		2.89	<10	<1	0.20	10	0.67	443	<1	0.02	18	610	32	1.41	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E858085		561	20	<0.01	<10	<10	3	<10	46			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

CERTIFICATE WH10091337

Project: ALN10-01

P.O. No.: ALN10-01_5

This report is for 66 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 6-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091337

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
E856285		2.20	<0.005	0.2	0.91	6	<10	40	<0.5	<2	0.47	<0.5	8	13	22	2.51
E856286		1.28	<0.005	<0.2	0.58	10	<10	40	<0.5	<2	0.98	<0.5	7	14	17	1.91
E856287		3.50	<0.005	<0.2	1.45	5	<10	40	<0.5	<2	0.45	<0.5	13	17	30	3.41
E856288		3.32	<0.005	<0.2	1.33	2	<10	40	<0.5	<2	0.59	<0.5	15	18	36	3.44
E856289		<0.02	<0.005	0.3	1.34	<2	<10	50	<0.5	<2	0.62	<0.5	15	26	35	3.38
E856290		0.12	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.02
E856291		4.16	<0.005	<0.2	1.16	<2	<10	40	<0.5	<2	0.37	<0.5	11	14	27	2.85
E856292		3.82	<0.005	0.3	0.74	<2	<10	30	<0.5	<2	0.66	<0.5	7	12	16	2.19
E856293		3.96	<0.005	0.2	0.33	<2	<10	30	<0.5	<2	1.15	<0.5	3	16	6	1.53
E856294		4.20	<0.005	0.3	0.67	<2	<10	40	<0.5	<2	1.02	<0.5	7	12	15	2.23
E856295		3.50	<0.005	0.2	1.41	3	<10	50	<0.5	<2	0.43	<0.5	15	16	37	3.76
E856296		4.42	<0.005	0.3	1.25	<2	<10	50	<0.5	<2	0.78	<0.5	11	21	27	3.40
E856297		3.50	0.008	0.3	0.96	68	<10	50	<0.5	<2	0.48	<0.5	12	12	36	3.03
E856298		3.76	<0.005	0.2	0.92	15	<10	40	<0.5	<2	0.61	<0.5	11	10	28	2.95
E856299		1.56	0.014	0.3	0.43	185	<10	50	<0.5	<2	0.43	<0.5	10	17	48	2.63
E856300		0.72	0.039	0.5	0.51	821	<10	70	0.5	<2	0.53	<0.5	20	6	82	4.37
E856301		0.96	<0.005	0.2	0.37	13	<10	50	<0.5	<2	3.42	<0.5	12	4	23	2.66
E856302		1.00	<0.005	0.5	0.35	8	<10	50	<0.5	<2	3.89	<0.5	11	14	22	2.33
E856303		1.94	<0.005	0.4	0.27	<2	<10	50	<0.5	<2	5.64	<0.5	7	4	16	2.42
E856304		2.58	<0.005	0.2	0.30	5	<10	40	<0.5	<2	3.01	<0.5	7	5	16	1.99
E856305		3.44	0.013	0.7	0.33	43	<10	50	<0.5	<2	3.69	1.0	11	14	53	2.98
E856306		3.10	<0.005	0.3	0.76	21	<10	60	<0.5	<2	2.93	<0.5	14	9	42	3.11
E856307		2.90	<0.005	0.2	0.75	8	<10	80	<0.5	<2	2.86	<0.5	7	9	27	2.61
E856308		3.54	0.005	0.2	1.21	14	<10	80	<0.5	<2	2.01	<0.5	16	23	66	3.23
E856309		<0.02	0.005	0.3	1.14	14	<10	60	<0.5	<2	2.19	<0.5	14	13	57	3.14
E856310		0.22	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.02
E856311		1.98	0.014	0.3	0.92	19	<10	60	0.6	<2	2.21	<0.5	12	12	57	3.32
E856312		2.74	0.006	<0.2	1.66	10	<10	70	0.5	<2	1.65	<0.5	15	26	53	3.72
E856313		2.68	<0.005	0.3	1.90	16	<10	80	<0.5	<2	1.71	<0.5	19	22	71	4.24
E856314		1.40	<0.005	<0.2	2.40	12	<10	70	0.5	<2	0.35	<0.5	20	24	46	4.65
E856315		3.36	<0.005	0.3	0.78	4	<10	70	<0.5	<2	6.44	<0.5	8	13	21	2.65
E856316		3.46	<0.005	<0.2	1.69	18	<10	100	<0.5	<2	0.61	<0.5	14	16	32	3.55
E856317		2.54	<0.005	<0.2	1.93	11	<10	110	<0.5	<2	0.28	<0.5	16	18	33	3.86
E856318		3.92	<0.005	<0.2	1.42	2	<10	110	<0.5	<2	0.52	<0.5	8	22	23	2.71
E856319		2.80	<0.005	<0.2	1.90	4	<10	120	<0.5	<2	0.33	<0.5	13	20	26	3.57
E856320		3.28	<0.005	<0.2	1.18	2	<10	50	<0.5	<2	0.74	<0.5	8	12	18	2.51
E856321		1.54	<0.005	<0.2	0.77	3	<10	40	<0.5	<2	0.76	<0.5	6	17	13	1.81
E856322		1.86	<0.005	<0.2	0.73	5	<10	40	<0.5	<2	0.84	<0.5	5	9	10	1.75
E856323		3.28	<0.005	<0.2	1.26	2	<10	60	<0.5	<2	0.54	<0.5	11	14	24	2.77
E856324		4.10	<0.005	<0.2	0.63	<2	<10	30	<0.5	<2	0.77	<0.5	4	17	5	1.60

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091337

Sample Description	Method Analyte Units LOR	ME-ICP41 Ga ppm 10	ME-ICP41 Hg ppm 1	ME-ICP41 K % 0.01	ME-ICP41 La ppm 10	ME-ICP41 Mg % 0.01	ME-ICP41 Mn ppm 5	ME-ICP41 Mo ppm 1	ME-ICP41 Na % 0.01	ME-ICP41 Ni ppm 1	ME-ICP41 P ppm 10	ME-ICP41 Pb ppm 2	ME-ICP41 S % 0.01	ME-ICP41 Sb ppm 2	ME-ICP41 Sc ppm 1	ME-ICP41 Sr ppm 1
E856285		<10	<1	0.16	10	0.44	437	<1	0.02	20	190	21	0.08	<2	1	17
E856286		<10	<1	0.13	10	0.39	453	<1	0.02	12	180	29	0.03	<2	1	27
E856287		<10	<1	0.15	10	0.74	667	<1	0.02	29	220	26	0.27	<2	2	19
E856288		<10	<1	0.14	10	0.72	500	<1	0.03	31	230	22	0.47	<2	2	29
E856289		<10	<1	0.17	10	0.72	498	<1	0.03	30	230	17	0.47	<2	2	32
E856290		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	<0.01	<2	<1	1
E856291		<10	<1	0.14	10	0.58	387	<1	0.02	25	210	16	0.41	<2	1	18
E856292		<10	<1	0.11	10	0.48	437	<1	0.02	14	180	15	0.30	<2	1	36
E856293		<10	<1	0.08	10	0.43	549	<1	0.02	5	140	18	0.12	<2	1	60
E856294		<10	<1	0.12	10	0.55	536	<1	0.02	15	160	12	0.32	<2	1	55
E856295		<10	<1	0.16	10	0.78	430	<1	0.02	32	240	12	0.70	<2	1	29
E856296		<10	<1	0.17	10	0.76	570	<1	0.02	25	230	21	0.41	<2	2	40
E856297		<10	<1	0.17	10	0.61	371	<1	0.02	26	210	24	0.61	8	1	28
E856298		<10	<1	0.15	10	0.61	380	<1	0.02	22	450	19	0.52	8	1	35
E856299		<10	<1	0.15	10	0.52	318	<1	0.01	22	170	12	0.65	35	1	28
E856300		<10	<1	0.21	10	0.80	416	<1	0.02	46	580	9	0.90	58	2	32
E856301		<10	<1	0.14	10	0.76	352	<1	0.02	23	390	11	0.23	30	2	123
E856302		<10	<1	0.13	10	0.68	322	<1	0.02	23	330	18	0.30	27	2	157
E856303		<10	<1	0.13	10	0.98	464	<1	0.02	13	270	17	0.45	11	1	238
E856304		<10	<1	0.14	10	0.57	411	<1	0.02	13	210	14	0.37	15	1	117
E856305		<10	<1	0.16	10	1.06	585	4	0.02	30	880	18	1.00	56	2	114
E856306		<10	<1	0.16	10	1.29	794	1	0.02	26	680	25	0.57	107	2	127
E856307		<10	<1	0.12	10	1.33	842	<1	0.02	16	480	14	0.20	19	2	136
E856308		<10	<1	0.19	10	1.27	597	2	0.02	31	1030	17	0.56	37	2	87
E856309		<10	<1	0.15	10	1.34	658	1	0.02	29	990	19	0.49	35	2	93
E856310		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	<0.01	<2	<1	1
E856311		<10	<1	0.13	10	1.26	685	2	0.02	31	970	22	0.47	52	2	130
E856312		<10	<1	0.16	10	1.57	601	1	0.02	29	1130	22	0.57	16	2	86
E856313		10	<1	0.16	10	1.63	840	2	0.02	37	1190	27	0.60	11	2	74
E856314		10	<1	0.18	20	1.18	319	<1	0.02	44	590	10	0.22	9	2	23
E856315		<10	<1	0.17	10	1.06	617	<1	0.03	18	360	16	0.33	4	1	400
E856316		<10	<1	0.17	20	0.93	502	<1	0.02	29	250	18	0.17	22	1	29
E856317		<10	<1	0.19	20	0.87	512	<1	0.01	34	270	11	0.07	6	1	19
E856318		<10	<1	0.14	10	0.83	423	<1	0.01	20	200	11	0.11	<2	1	27
E856319		<10	<1	0.15	20	0.95	354	<1	0.02	28	310	17	0.12	4	1	20
E856320		<10	<1	0.13	10	0.66	573	<1	0.01	17	280	22	0.08	3	1	33
E856321		<10	<1	0.10	10	0.51	596	<1	0.01	10	130	38	0.07	4	1	30
E856322		<10	<1	0.09	10	0.52	623	<1	0.01	10	310	34	0.06	3	1	33
E856323		<10	<1	0.14	10	0.58	521	<1	0.01	19	810	53	0.19	3	1	28
E856324		<10	<1	0.08	10	0.47	722	<1	0.01	8	110	32	0.03	2	1	29

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091337

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E856285		<20	<0.01	<10	<10	7	<10	42		
E856286		<20	<0.01	<10	<10	4	<10	32		
E856287		<20	<0.01	<10	<10	11	<10	68		
E856288		<20	<0.01	<10	<10	15	<10	86		
E856289		<20	<0.01	<10	<10	15	<10	90		
E856290		<20	<0.01	<10	<10	<1	<10	3		
E856291		<20	<0.01	<10	<10	8	<10	55		
E856292		<20	<0.01	<10	<10	6	<10	32		
E856293		<20	<0.01	<10	<10	2	<10	14		
E856294		<20	<0.01	<10	<10	4	<10	31		
E856295		<20	<0.01	<10	<10	9	<10	71		
E856296		<20	<0.01	<10	<10	10	<10	54		
E856297		<20	<0.01	<10	<10	6	<10	52		
E856298		<20	<0.01	<10	<10	7	<10	47		
E856299		<20	<0.01	<10	<10	3	<10	44		
E856300		<20	<0.01	<10	<10	4	<10	79		
E856301		<20	<0.01	<10	<10	4	<10	50		
E856302		<20	<0.01	<10	<10	3	<10	40		
E856303		<20	<0.01	<10	<10	2	<10	39		
E856304		<20	<0.01	<10	<10	2	<10	32		
E856305		<20	<0.01	<10	<10	7	<10	140		
E856306		<20	<0.01	<10	<10	6	<10	73		
E856307		<20	<0.01	<10	<10	6	<10	45		
E856308		<20	<0.01	<10	<10	13	<10	76		
E856309		<20	<0.01	<10	<10	12	<10	76		
E856310		<20	<0.01	<10	<10	<1	<10	2		
E856311		<20	<0.01	<10	<10	13	<10	76		
E856312		<20	<0.01	<10	<10	21	<10	94		
E856313		<20	<0.01	<10	<10	22	<10	101		
E856314		20	<0.01	<10	<10	14	<10	111		
E856315		<20	<0.01	<10	<10	5	<10	50		
E856316		<20	<0.01	<10	<10	9	<10	71		
E856317		<20	0.01	<10	<10	11	<10	79		
E856318		<20	<0.01	<10	<10	8	<10	52		
E856319		<20	<0.01	<10	<10	11	<10	71		
E856320		<20	<0.01	<10	<10	6	<10	43		
E856321		<20	<0.01	<10	<10	4	<10	31		
E856322		<20	<0.01	<10	<10	4	<10	31		
E856323		<20	<0.01	<10	<10	7	<10	50		
E856324		<20	<0.01	<10	<10	3	<10	24		

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091337

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
E856325		4.10	<0.005	<0.2	1.58	4	<10	60	<0.5	<2	0.32	<0.5	13	17	33	3.17
E856326		4.00	<0.005	<0.2	2.08	22	<10	90	<0.5	<2	0.25	<0.5	24	19	43	4.23
E856327		3.60	<0.005	0.2	1.29	2	<10	50	<0.5	<2	0.54	<0.5	11	22	30	2.67
856328		4.00	<0.005	<0.2	2.02	7	<10	60	<0.5	<2	0.24	<0.5	15	20	31	3.80
E856329		<0.02	<0.005	<0.2	1.97	8	<10	60	<0.5	<2	0.30	<0.5	16	19	29	3.66
E856330		0.08	0.855	>100	0.52	4470	<10	40	<0.5	5	0.53	95.0	6	50	296	6.03
E856331		3.76	0.005	0.3	1.89	21	<10	70	<0.5	<2	0.62	<0.5	18	24	32	3.65
E856332		4.12	<0.005	<0.2	2.00	9	<10	80	<0.5	<2	0.65	<0.5	15	21	37	3.80
E856333		4.06	<0.005	<0.2	2.02	5	<10	60	<0.5	<2	0.43	<0.5	13	21	29	3.79
E856334		3.98	<0.005	<0.2	0.79	5	<10	50	<0.5	<2	1.03	<0.5	6	17	7	1.58
E856335		4.54	<0.005	<0.2	1.22	7	<10	70	<0.5	<2	1.27	<0.5	9	20	26	2.79
E856336		3.88	<0.005	<0.2	1.40	8	<10	70	<0.5	<2	1.63	<0.5	15	15	32	3.48
E856337		3.86	<0.005	<0.2	1.39	6	<10	110	<0.5	<2	2.45	<0.5	14	14	30	3.02
E856338		4.92	<0.005	0.2	0.49	2	<10	60	<0.5	<2	4.22	<0.5	8	10	15	2.13
E856339		4.08	0.007	0.9	0.36	14	<10	60	<0.5	<2	8.2	<0.5	7	6	14	2.07
E856340		4.72	<0.005	0.5	0.92	5	<10	140	<0.5	<2	1.70	<0.5	11	9	24	2.48
E856341		1.48	<0.005	<0.2	0.42	<2	<10	210	<0.5	<2	0.43	<0.5	5	13	8	1.23
E856342		1.74	<0.005	<0.2	0.45	<2	<10	180	<0.5	<2	0.37	<0.5	6	6	9	1.34
E856343		3.34	<0.005	0.2	1.25	5	<10	110	<0.5	<2	0.56	<0.5	10	11	23	2.89
E856344		2.32	<0.005	<0.2	0.47	20	<10	60	<0.5	<2	0.52	<0.5	7	14	14	1.84
E856345		2.10	0.006	2.2	0.23	52	<10	40	<0.5	<2	1.13	<0.5	6	5	13	2.25
E856346		3.20	0.030	0.8	0.50	318	<10	50	0.5	<2	0.67	<0.5	10	6	25	3.23
E856347		4.64	0.146	24.1	0.85	1530	<10	60	0.6	<2	0.83	<0.5	10	30	70	3.41
E856348		3.68	<0.005	0.2	0.56	14	<10	40	<0.5	<2	1.72	<0.5	6	9	15	2.11
E856349		<0.02	<0.005	0.2	0.52	12	<10	40	<0.5	<2	1.76	<0.5	6	7	13	2.04
E856350		0.20	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.02

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091337

Sample Description	Method / Analyte / Units / LOR	ME-ICP41 Ga ppm 10	ME-ICP41 Hg ppm 1	ME-ICP41 K % 0.01	ME-ICP41 La ppm 10	ME-ICP41 Mg % 0.01	ME-ICP41 Mn ppm 5	ME-ICP41 Mo ppm 1	ME-ICP41 Na % 0.01	ME-ICP41 Ni ppm 1	ME-ICP41 P ppm 10	ME-ICP41 Pb ppm 2	ME-ICP41 S % 0.01	ME-ICP41 Sb ppm 2	ME-ICP41 Sc ppm 1	ME-ICP41 Sr ppm 1
E856325		<10	<1	0.16	20	0.72	463	<1	0.02	26	290	42	0.13	3	1	18
E856326		10	<1	0.20	20	0.84	670	<1	0.01	35	320	24	0.11	<2	1	17
E856327		<10	<1	0.15	10	0.70	596	<1	0.02	21	160	29	0.21	<2	1	24
856328		<10	<1	0.19	20	0.95	342	<1	0.02	32	400	22	0.24	<2	1	17
E856329		<10	<1	0.17	20	0.94	362	<1	0.02	30	520	20	0.21	<2	1	19
E856330		<10	1	0.31	10	0.10	299	1	0.04	5	640	4850	7.7	1710	1	134
E856331		<10	<1	0.18	20	0.99	465	<1	0.02	32	450	19	0.19	5	1	30
E856332		<10	<1	0.19	20	1.02	419	<1	0.02	33	590	19	0.16	<2	1	31
E856333		10	<1	0.17	10	1.09	369	<1	0.02	32	270	15	0.14	<2	1	21
E856334		<10	<1	0.13	10	0.52	337	<1	0.01	9	1270	12	0.08	<2	1	33
E856335		<10	<1	0.18	20	0.68	303	<1	0.01	21	410	26	0.27	4	1	57
E856336		<10	<1	0.18	10	0.98	468	<1	0.02	29	430	20	0.56	6	1	63
E856337		<10	<1	0.20	10	0.74	294	<1	0.02	29	420	35	0.52	5	1	130
E856338		<10	<1	0.15	10	0.93	552	<1	0.02	15	240	14	0.56	2	1	162
E856339		<10	<1	0.13	10	0.96	801	<1	0.02	15	390	15	0.45	9	1	308
E856340		<10	<1	0.15	10	0.62	318	<1	0.02	22	250	18	0.52	<2	1	83
E856341		<10	<1	0.12	10	0.24	203	<1	0.01	9	130	17	0.31	4	<1	20
E856342		<10	<1	0.10	10	0.25	179	<1	0.01	9	120	16	0.31	2	<1	17
E856343		<10	<1	0.16	20	0.67	346	<1	0.01	23	310	16	0.23	4	1	30
E856344		<10	<1	0.12	10	0.41	343	<1	0.02	14	130	13	0.15	7	1	24
E856345		<10	<1	0.11	10	0.56	654	<1	0.01	13	100	21	0.31	13	1	47
E856346		<10	<1	0.13	10	0.67	500	<1	0.01	22	200	15	0.32	25	2	44
E856347		<10	<1	0.16	10	0.71	595	16	0.02	25	440	17	0.59	21	2	53
E856348		<10	<1	0.13	10	0.78	860	<1	0.01	12	170	21	0.27	7	1	60
E856349		<10	<1	0.12	10	0.79	869	<1	0.01	11	170	19	0.26	7	1	62
E856350		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091337

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	20	0.01	10	10	1	10	2	0.001	5
E856325		<20	<0.01	<10	<10	8	<10	59		
E856326		<20	0.01	<10	<10	12	<10	81		
E856327		<20	<0.01	<10	<10	8	<10	49		
856328		<20	0.01	<10	<10	11	<10	79		
E856329		<20	0.01	<10	<10	11	<10	79		
E856330		<20	<0.01	<10	<10	5	10	>10000	1.280	148
E856331		<20	<0.01	<10	<10	10	<10	96		
E856332		<20	0.01	<10	<10	11	<10	83		
E856333		<20	0.01	<10	<10	11	<10	78		
E856334		<20	<0.01	<10	<10	4	<10	27		
E856335		<20	<0.01	<10	<10	7	<10	53		
E856336		<20	<0.01	<10	<10	8	<10	68		
E856337		<20	<0.01	<10	<10	7	<10	73		
E856338		<20	<0.01	<10	<10	2	<10	39		
E856339		<20	<0.01	<10	<10	2	<10	31		
E856340		<20	<0.01	<10	<10	5	<10	57		
E856341		<20	<0.01	<10	<10	2	<10	23		
E856342		<20	<0.01	<10	<10	2	<10	28		
E856343		20	<0.01	<10	<10	6	<10	68		
E856344		<20	<0.01	<10	<10	3	<10	35		
E856345		<20	<0.01	<10	<10	2	<10	39		
E856346		<20	<0.01	<10	<10	4	<10	72		
E856347		<20	<0.01	<10	<10	5	<10	73		
E856348		<20	<0.01	<10	<10	3	<10	36		
E856349		<20	<0.01	<10	<10	3	<10	35		
E856350		<20	<0.01	<10	<10	<1	<10	2		

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

CERTIFICATE WH10091336

Project: ALN10-01

P.O. No.: ALN10-01_8

This report is for 46 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 7-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature: 

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091336

Method / Analyte / Units / LOR — Sample Description	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856352	4.08	<0.005		<0.2	1.35	14	<10	70	<0.5	<2	0.26	<0.5	11	15	47
E856353	3.24	<0.005		<0.2	1.22	9	<10	60	<0.5	<2	0.83	<0.5	12	18	19
E856354	5.66	<0.005		<0.2	0.87	4	<10	50	<0.5	<2	0.69	<0.5	6	14	12
E856355	4.02	<0.005		<0.2	0.92	3	<10	70	<0.5	<2	0.52	<0.5	8	14	12
E856356	4.62	<0.005		<0.2	1.20	6	<10	80	<0.5	<2	0.84	<0.5	11	17	27
E856357	3.72	<0.005		<0.2	1.97	31	<10	150	<0.5	<2	0.37	<0.5	18	22	31
E856358	4.54	<0.005		<0.2	4.16	40	<10	10	<0.5	<2	2.71	<0.5	27	42	34
E856359	5.00	<0.005		<0.2	3.95	20	<10	60	<0.5	<2	1.52	<0.5	29	36	42
E856360	3.94	<0.005		<0.2	4.76	32	<10	10	<0.5	<2	1.63	<0.5	26	39	33
E856361	2.18	<0.005		<0.2	4.42	52	<10	30	<0.5	<2	1.19	<0.5	29	45	46
E856362	1.62	<0.005		<0.2	4.20	47	<10	70	0.5	<2	1.19	<0.5	28	43	56
E856363	3.40	<0.005		<0.2	4.68	24	<10	10	<0.5	<2	1.01	<0.5	33	38	54
E856364	3.74	<0.005		0.2	3.73	17	<10	10	0.6	<2	1.96	<0.5	31	39	49
E856365	2.94	<0.005		<0.2	4.55	22	<10	10	0.5	<2	1.36	<0.5	30	36	53
E856366	3.96	<0.005		<0.2	3.93	25	<10	110	0.5	<2	1.61	<0.5	31	36	50
E856367	1.04	<0.005		<0.2	1.87	5	<10	220	<0.5	<2	0.14	<0.5	12	20	62
E856368	3.40	<0.005		<0.2	1.33	5	<10	150	<0.5	<2	0.87	<0.5	9	17	28
E856369	<0.02	<0.005		<0.2	1.28	3	<10	140	<0.5	<2	0.89	<0.5	9	17	27
E856370	0.22	<0.005		<0.2	0.04	<2	<10	10	<0.5	<2	0.02	<0.5	<1	1	<1
E856371	3.50	<0.005		<0.2	0.77	11	<10	70	<0.5	<2	0.55	<0.5	9	14	16
E856372	3.34	<0.005		<0.2	1.02	3	<10	80	<0.5	<2	0.38	<0.5	12	15	21
E856373	3.56	<0.005		<0.2	0.59	2	<10	70	<0.5	<2	0.62	<0.5	5	11	13
E856374	3.56	<0.005		<0.2	0.27	12	<10	50	<0.5	<2	0.57	<0.5	4	11	3
E856375	1.84	<0.005		<0.2	0.63	<2	<10	50	<0.5	<2	1.02	<0.5	5	12	7
E856376	3.70	<0.005		<0.2	0.41	5	<10	60	<0.5	<2	1.40	<0.5	10	10	10
E856377	2.20	<0.005		<0.2	2.81	14	<10	60	<0.5	<2	1.14	1.1	23	27	55
E856378	2.74	<0.005		<0.2	2.53	17	<10	90	<0.5	<2	0.90	<0.5	23	27	44
E856379	2.72	<0.005		<0.2	2.25	8	<10	70	<0.5	<2	5.69	<0.5	11	21	76
E856380	3.36	<0.005		<0.2	1.06	8	<10	90	<0.5	<2	1.90	<0.5	16	15	65
E856381	2.18	<0.005		<0.2	1.38	7	<10	140	<0.5	<2	0.19	<0.5	17	22	36
E856382	2.22	0.005		<0.2	1.43	6	<10	140	<0.5	<2	0.19	<0.5	16	23	36
E856383	4.68	<0.005		<0.2	1.63	8	<10	120	<0.5	<2	1.16	<0.5	14	28	29
E856384	3.50	<0.005		<0.2	1.91	15	<10	160	0.5	<2	5.02	<0.5	14	20	38
E856385	2.82	<0.005		<0.2	2.20	13	<10	170	0.5	<2	4.14	<0.5	15	25	27
E856386	2.32	<0.005		<0.2	2.95	19	<10	70	<0.5	<2	3.00	<0.5	27	38	37
E856387	3.26	<0.005		<0.2	2.82	41	<10	110	<0.5	<2	3.21	<0.5	26	41	34
E856388	2.88	0.006		<0.2	4.26	127	<10	70	<0.5	<2	2.20	1.0	26	48	8
E856389	<0.02	<0.005		<0.2	4.31	122	<10	70	0.5	<2	2.21	0.9	26	49	8
E856390	0.08	1.595	NSS	>100	0.39	4390	<10	20	<0.5	8	0.77	509	5	54	834
E856391	2.68	<0.005		<0.2	4.04	108	<10	20	0.5	<2	2.46	1.6	17	61	5

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091336

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856352		3.05	<10	<1	0.29	20	0.55	229	<1	0.01	22	660	15	0.17	4	1
E856353		2.61	<10	<1	0.26	10	0.48	362	<1	0.01	25	150	13	0.14	2	1
E856354		1.84	<10	<1	0.22	10	0.32	183	<1	0.02	12	1080	13	0.09	<2	1
E856355		2.13	<10	<1	0.26	10	0.35	191	<1	0.01	14	220	10	0.20	<2	1
E856356		2.64	<10	<1	0.30	20	0.47	332	<1	0.01	22	250	13	0.25	<2	1
E856357		4.01	10	<1	0.32	20	1.03	332	<1	0.02	33	660	13	0.10	7	2
E856358		7.05	20	<1	0.01	<10	3.17	1145	<1	0.03	52	2420	3	0.09	3	13
E856359		6.76	20	<1	0.07	10	3.10	899	<1	0.02	48	1900	5	0.23	3	10
E856360		7.76	20	<1	0.01	<10	3.72	978	<1	0.02	48	2350	<2	0.06	5	13
E856361		7.49	20	<1	0.02	<10	3.54	964	<1	0.02	48	2260	<2	0.09	12	12
E856362		7.11	20	<1	0.07	<10	3.33	939	1	0.03	55	2140	8	0.06	15	12
E856363		8.16	20	<1	<0.01	<10	3.84	928	<1	0.02	53	2470	2	0.19	3	13
E856364		6.67	20	<1	<0.01	<10	3.02	681	<1	0.04	53	2440	2	0.08	2	12
E856365		7.69	20	<1	<0.01	<10	3.78	868	<1	0.02	50	2460	5	0.06	4	13
E856366		6.84	20	<1	0.17	10	2.83	749	<1	0.03	62	1940	7	0.12	7	10
E856367		4.00	10	<1	0.36	20	0.78	277	<1	0.02	22	260	15	0.15	<2	2
E856368		2.84	<10	<1	0.32	20	0.51	401	<1	0.03	25	370	20	0.17	2	1
E856369		2.89	<10	<1	0.31	20	0.48	418	<1	0.03	26	340	19	0.17	<2	1
E856370		0.25	<10	<1	0.01	<10	0.01	28	1	0.02	<1	20	2	0.02	<2	<1
E856371		1.75	<10	<1	0.24	10	0.25	326	<1	0.03	21	110	13	0.19	<2	1
E856372		2.43	<10	<1	0.29	10	0.37	243	<1	0.02	24	90	13	0.42	<2	1
E856373		1.71	<10	<1	0.24	10	0.21	344	<1	0.02	12	150	14	0.33	<2	1
E856374		1.10	<10	<1	0.15	10	0.04	350	1	0.04	7	60	16	0.39	2	<1
E856375		1.60	<10	<1	0.18	10	0.25	525	<1	0.03	11	110	11	0.38	<2	1
E856376		1.67	<10	<1	0.21	10	0.10	695	<1	0.03	18	110	18	0.84	4	1
E856377		6.15	10	<1	0.23	20	1.66	933	<1	0.03	44	1420	5	0.44	6	6
E856378		4.90	10	<1	0.29	20	1.40	722	<1	0.03	42	850	11	0.33	3	4
E856379		3.26	10	<1	0.22	10	2.42	1615	<1	0.02	26	490	19	0.37	4	3
E856380		2.60	<10	<1	0.26	20	0.62	626	1	0.02	25	190	14	0.58	6	1
E856381		3.09	<10	<1	0.30	20	0.65	210	<1	0.02	24	260	9	0.37	8	2
E856382		3.11	10	<1	0.30	20	0.68	217	<1	0.03	27	310	8	0.39	8	2
E856383		3.26	10	<1	0.24	20	1.00	572	<1	0.04	27	330	10	0.35	3	3
E856384		2.84	10	<1	0.30	20	1.60	1405	<1	0.02	29	470	14	0.12	5	3
E856385		3.82	10	<1	0.28	20	1.91	1215	<1	0.03	31	890	7	0.15	3	5
E856386		5.62	20	<1	0.09	10	2.09	772	<1	0.05	44	1900	4	0.20	4	10
E856387		5.52	20	<1	0.11	10	2.02	785	<1	0.05	47	2010	4	0.11	11	10
E856388		6.44	20	<1	0.06	20	4.06	967	<1	0.04	49	1840	6	<0.01	12	13
E856389		6.50	20	<1	0.07	20	4.10	966	<1	0.04	50	1850	6	<0.01	12	13
E856390		6.55	<10	3	0.25	10	0.25	374	2	0.03	3	540	>10000	9.2	2630	1
E856391		4.69	20	1	0.02	30	5.05	1470	<1	0.05	48	900	24	0.02	12	11

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091336

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856352		8	<20	<0.01	<10	<10	7	<10	60			
E856353		33	<20	0.01	<10	<10	8	<10	46			
E856354		26	<20	0.01	<10	<10	6	<10	27			
E856355		22	<20	<0.01	<10	<10	6	<10	31			
E856356		42	<20	0.01	<10	<10	8	<10	44			
E856357		20	<20	0.03	<10	<10	20	<10	76			
E856358		156	<20	0.23	<10	<10	95	<10	91			
E856359		97	<20	0.16	<10	<10	75	<10	116			
E856360		77	<20	0.21	<10	<10	91	<10	145			
E856361		60	<20	0.21	<10	<10	92	<10	156			
E856362		53	<20	0.23	<10	<10	88	<10	157			
E856363		47	<20	0.27	<10	<10	97	<10	150			
E856364		156	<20	0.31	<10	<10	114	<10	129			
E856365		77	<20	0.22	<10	<10	103	<10	204			
E856366		107	<20	0.10	<10	<10	80	<10	123			
E856367		7	<20	0.04	<10	<10	15	<10	73			
E856368		41	<20	0.02	<10	<10	11	<10	56			
E856369		41	<20	0.02	<10	<10	9	<10	56			
E856370		1	<20	<0.01	<10	<10	<1	<10	3			
E856371		24	<20	0.02	<10	<10	5	<10	43			
E856372		17	<20	0.02	<10	<10	6	<10	38			
E856373		26	<20	<0.01	<10	<10	4	<10	29			
E856374		23	<20	<0.01	<10	<10	1	<10	9			
E856375		49	<20	<0.01	<10	<10	4	<10	21			
E856376		60	<20	<0.01	<10	<10	2	<10	17			
E856377		56	<20	0.01	<10	<10	47	<10	448			
E856378		42	<20	0.01	<10	<10	31	<10	111			
E856379		283	<20	<0.01	<10	<10	27	<10	69			
E856380		81	<20	<0.01	<10	<10	8	<10	50			
E856381		9	<20	<0.01	<10	<10	12	<10	49			
E856382		8	<20	<0.01	<10	<10	13	<10	51			
E856383		64	<20	<0.01	<10	<10	25	<10	59			
E856384		281	<20	0.01	<10	<10	18	<10	59			
E856385		252	<20	0.04	<10	<10	38	<10	79			
E856386		186	<20	0.16	<10	<10	89	<10	122			
E856387		247	<20	0.19	<10	<10	95	<10	158			
E856388		155	<20	0.22	<10	<10	106	<10	346			
E856389		155	<20	0.23	<10	<10	108	<10	342			
E856390		105	<20	<0.01	<10	<10	6	140	>10000	1.925	3.69	325
E856391		219	20	0.07	<10	<10	75	<10	381			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091336

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856392		3.82	<0.005		<0.2	3.71	8	<10	20	0.8	<2	2.94	0.5	18	53	28
E856393		4.36	0.057		0.2	2.96	485	<10	800	<0.5	<2	1.84	1.7	30	40	45
E856394		4.68	<0.005		<0.2	2.88	37	<10	790	<0.5	<2	2.45	<0.5	30	39	40
E856395		4.74	0.006		<0.2	3.09	49	<10	920	0.5	<2	2.47	<0.5	30	41	34
E856396		4.40	0.266		<0.2	1.85	2040	<10	210	<0.5	<2	1.87	<0.5	33	25	40
E856397		3.32	0.007		<0.2	2.89	110	<10	790	0.5	<2	1.94	<0.5	34	40	43

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091336

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856392		4.42	20	<1	0.03	30	4.38	1155	<1	0.03	37	900	19	<0.01	2	11
E856393		7.47	20	<1	0.08	10	2.47	931	<1	0.05	54	2380	6	0.23	68	13
E856394		7.44	20	<1	0.05	10	2.75	992	<1	0.06	50	2320	5	0.14	12	13
E856395		7.60	20	<1	0.06	10	2.77	885	<1	0.06	50	2400	11	0.13	13	13
E856396		7.78	10	<1	0.07	10	2.00	1140	<1	0.05	58	2450	<2	0.41	66	12
E856397		7.95	20	<1	0.04	10	2.61	958	<1	0.06	57	2460	<2	0.11	27	14

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091336

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856392		247	<20	0.04	<10	<10	70	<10	110			
E856393		167	<20	0.11	<10	<10	93	<10	431			
E856394		220	<20	0.09	<10	<10	98	<10	161			
E856395		248	<20	0.11	<10	<10	100	<10	184			
E856396		159	<20	0.02	<10	<10	52	<10	546			
E856397		184	<20	0.07	<10	<10	101	<10	434			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091336

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

CERTIFICATE WH10091335

Project: ALN10-01

P.O. No.: ALN10-01_9

This report is for 57 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 6-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091335

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856398		1.66	<0.005		<0.2	0.46	65	<10	60	<0.5	<2	1.59	<0.5	5	19	8
E856399		1.50	0.011		<0.2	0.70	179	<10	30	<0.5	<2	3.07	<0.5	4	9	3
E856400		1.80	0.015		<0.2	0.48	111	<10	20	<0.5	<2	15.0	<0.5	3	6	2
E856401		1.60	<0.005		<0.2	0.07	8	<10	10	<0.5	<2	19.4	<0.5	2	3	<1
E856402		1.06	<0.005		<0.2	0.08	5	<10	10	<0.5	<2	19.5	<0.5	2	2	<1
E856403		1.62	<0.005		<0.2	0.39	8	<10	10	<0.5	<2	17.5	<0.5	2	3	<1
E856404		1.54	<0.005		<0.2	0.50	12	<10	10	<0.5	<2	17.6	<0.5	2	3	<1
E856405		1.92	<0.005		<0.2	0.47	6	<10	10	<0.5	<2	18.7	<0.5	2	5	<1
E856406		2.52	0.006		<0.2	0.16	88	<10	30	<0.5	<2	6.03	<0.5	4	3	6
E856407		1.54	0.193		0.3	0.14	767	<10	30	<0.5	<2	5.21	<0.5	3	4	4
E856408		1.78	0.277		0.4	0.22	1090	<10	40	<0.5	<2	3.82	<0.5	5	10	10
E856409		<0.02	0.271		0.5	0.20	1100	<10	40	<0.5	<2	4.25	<0.5	4	4	10
E856410		0.14	<0.005		<0.2	0.01	2	<10	10	<0.5	<2	0.02	<0.5	<1	<1	<1
E856411		1.80	0.256		0.6	0.19	1050	<10	30	<0.5	<2	3.23	<0.5	4	6	9
E856412		1.76	0.204		0.3	0.18	902	<10	40	<0.5	<2	9.7	<0.5	4	7	4
E856413		2.18	1.545	1.39	0.5	0.16	2720	<10	30	<0.5	<2	7.7	<0.5	3	5	4
E856414		1.08	0.846		<0.2	0.19	2740	<10	40	<0.5	<2	4.79	0.5	3	5	2
E856415		1.54	0.143		<0.2	0.14	594	<10	30	<0.5	<2	15.2	<0.5	3	6	2
E856416		1.60	0.063		<0.2	0.10	317	<10	20	<0.5	<2	15.5	<0.5	1	2	2
E856417		1.44	0.011		<0.2	0.15	120	<10	30	<0.5	<2	15.3	<0.5	2	2	<1
E856418		1.14	0.010		<0.2	0.15	151	<10	30	<0.5	<2	13.2	<0.5	2	4	2
E856419		1.18	0.013		<0.2	0.13	140	<10	20	<0.5	<2	13.2	<0.5	3	3	<1
E856420		0.96	0.010		<0.2	0.15	82	<10	30	<0.5	<2	6.4	<0.5	2	3	5
E856421		0.72	0.015		<0.2	0.16	186	<10	30	<0.5	<2	10.4	<0.5	4	6	3
E856422		0.52	0.034		<0.2	0.14	111	<10	30	<0.5	<2	9.6	<0.5	3	3	2
E856423		1.48	0.078		<0.2	0.22	244	<10	50	<0.5	<2	2.83	<0.5	6	3	14
E856424		1.70	<0.005		<0.2	0.35	10	<10	50	<0.5	<2	1.69	<0.5	6	10	15
E856425		1.58	<0.005		<0.2	0.48	<2	<10	40	<0.5	<2	1.25	<0.5	6	7	11
E856426		2.14	<0.005		<0.2	0.23	15	<10	40	<0.5	<2	1.82	<0.5	5	5	6
E856427		1.62	0.027		0.2	0.32	1430	<10	60	<0.5	<2	0.62	<0.5	9	9	20
E856428		1.46	0.196		0.4	0.21	2560	<10	50	<0.5	<2	1.43	<0.5	5	4	9
E856429		<0.02	0.216		0.3	0.22	2640	<10	50	<0.5	<2	1.49	<0.5	4	4	10
E856430		0.10	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1
E856431		1.76	0.082		<0.2	0.20	295	<10	40	<0.5	<2	1.09	<0.5	1	13	2
E856432		2.40	0.160		0.2	0.20	1070	<10	40	<0.5	<2	1.23	<0.5	2	5	3
E856433		0.80	0.222		0.2	0.21	2530	<10	40	<0.5	<2	2.32	<0.5	3	11	10
E856434		0.84	0.113		0.4	0.18	1650	<10	40	<0.5	<2	1.78	<0.5	3	3	8
E856435		1.26	0.174		<0.2	0.26	2620	<10	50	<0.5	<2	0.80	<0.5	7	11	25
E856436		1.74	0.071		<0.2	0.19	539	<10	40	<0.5	<2	1.46	<0.5	1	6	3
E856437		0.68	0.292		<0.2	0.27	4430	<10	60	<0.5	<2	1.71	<0.5	4	14	10

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091335

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856398		1.31	<10	<1	0.16	10	0.48	308	<1	0.01	8	150	14	0.05	3	1
E856399		1.51	<10	<1	0.09	10	0.91	491	<1	0.01	7	90	29	<0.01	2	1
E856400		2.00	<10	<1	0.04	<10	6.12	1475	<1	<0.01	6	370	20	<0.01	<2	1
E856401		1.99	<10	<1	0.03	<10	7.93	1720	<1	0.01	4	500	8	<0.01	<2	1
E856402		1.87	<10	<1	0.03	<10	7.94	1680	<1	<0.01	5	460	9	<0.01	<2	1
E856403		2.12	<10	<1	0.01	<10	6.24	1960	<1	0.01	4	610	13	<0.01	<2	1
E856404		2.02	<10	<1	0.02	<10	6.60	1715	<1	0.01	5	680	19	<0.01	<2	1
E856405		2.31	<10	<1	0.02	10	7.18	2150	<1	0.01	6	670	17	<0.01	<2	1
E856406		1.68	<10	<1	0.11	<10	2.11	752	<1	0.01	8	180	17	0.47	65	1
E856407		1.40	<10	<1	0.10	<10	2.08	787	<1	<0.01	6	120	17	0.16	293	1
E856408		1.34	<10	<1	0.15	<10	1.42	590	<1	0.01	8	110	15	0.22	30	1
E856409		1.47	<10	<1	0.14	<10	1.57	649	<1	<0.01	8	120	17	0.22	27	1
E856410		0.01	<10	<1	<0.01	<10	0.01	<5	<1	<0.01	1	10	<2	<0.01	<2	<1
E856411		1.24	<10	<1	0.12	<10	1.20	506	<1	<0.01	5	90	20	0.21	950	1
E856412		1.73	<10	<1	0.12	<10	4.39	1230	<1	0.01	7	290	12	0.16	18	1
E856413		2.03	<10	<1	0.10	<10	3.72	1400	<1	<0.01	6	260	13	0.14	7	1
E856414		1.82	<10	<1	0.13	<10	0.71	913	<1	<0.01	8	250	12	0.21	15	1
E856415		1.37	<10	<1	0.09	<10	2.59	1135	<1	<0.01	6	410	16	0.04	183	1
E856416		2.12	<10	<1	0.06	<10	6.07	1435	<1	0.01	5	550	6	0.06	<2	1
E856417		1.89	<10	<1	0.09	<10	6.16	1365	<1	0.01	4	350	13	<0.01	3	1
E856418		1.96	<10	<1	0.10	<10	4.32	1225	<1	0.01	4	450	10	0.08	3	1
E856419		2.09	<10	<1	0.07	<10	5.15	1435	<1	0.01	5	360	42	0.03	4	1
E856420		1.54	<10	<1	0.11	10	2.53	781	<1	0.01	5	150	22	0.09	6	1
E856421		1.88	<10	<1	0.09	<10	4.32	1120	<1	0.01	9	290	23	0.09	10	1
E856422		1.61	<10	<1	0.09	<10	4.02	1005	<1	0.01	6	290	17	0.09	2	1
E856423		1.74	<10	<1	0.16	10	1.23	421	<1	0.01	11	540	17	0.37	6	1
E856424		2.12	<10	<1	0.20	10	0.82	444	<1	0.01	13	300	29	0.13	<2	1
E856425		2.02	<10	<1	0.16	10	0.70	332	<1	0.02	11	170	24	0.12	<2	1
E856426		2.02	<10	<1	0.15	10	0.79	510	<1	0.01	9	220	16	0.11	<2	1
E856427		1.94	<10	<1	0.20	10	0.36	139	<1	0.01	19	200	15	0.62	15	1
E856428		1.28	<10	<1	0.16	10	0.51	299	<1	0.01	9	250	61	0.64	37	1
E856429		1.34	<10	<1	0.17	10	0.54	309	<1	0.01	8	250	31	0.68	20	1
E856430		0.01	<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.01	<2	<1
E856431		0.57	<10	<1	0.13	<10	0.35	273	<1	0.01	2	80	13	0.09	<2	<1
E856432		0.89	<10	<1	0.13	<10	0.46	289	<1	<0.01	4	90	14	0.24	4	<1
E856433		1.79	<10	<1	0.15	<10	0.91	440	<1	0.01	9	140	9	0.71	8	1
E856434		1.43	<10	<1	0.13	<10	0.66	412	<1	0.01	5	90	9	0.51	7	1
E856435		2.82	<10	<1	0.18	10	0.56	239	<1	0.01	18	270	14	1.01	15	1
E856436		0.91	<10	<1	0.12	10	0.53	375	<1	0.01	2	190	16	0.12	<2	1
E856437		2.31	<10	<1	0.19	<10	0.63	262	<1	0.01	11	190	13	1.20	11	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091335

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	5
E856398		39	<20	<0.01	<10	<10	3	<10	27		
E856399		80	<20	<0.01	<10	<10	6	<10	39		
E856400		435	<20	<0.01	<10	<10	3	<10	30		
E856401		559	<20	<0.01	<10	<10	1	<10	13		
E856402		648	<20	<0.01	<10	<10	1	<10	13		
E856403		602	<20	<0.01	<10	<10	3	<10	40		
E856404		723	<20	<0.01	<10	<10	3	<10	29		
E856405		660	<20	<0.01	<10	<10	4	<10	42		
E856406		213	<20	<0.01	<10	<10	1	<10	27		
E856407		172	<20	<0.01	<10	<10	<1	<10	27		
E856408		120	<20	<0.01	<10	<10	1	<10	50		
E856409		130	<20	<0.01	<10	<10	1	<10	51		
E856410		1	<20	<0.01	<10	<10	<1	<10	<2		
E856411		106	<20	<0.01	<10	<10	1	<10	38		
E856412		281	<20	<0.01	<10	<10	1	<10	44		
E856413		171	<20	<0.01	<10	<10	1	<10	67		
E856414		134	<20	<0.01	<10	<10	1	<10	191		
E856415		485	<20	<0.01	<10	<10	1	<10	16		
E856416		375	<20	<0.01	<10	<10	1	<10	14		
E856417		424	<20	<0.01	<10	<10	1	<10	16		
E856418		337	<20	<0.01	<10	<10	1	<10	15		
E856419		340	<20	<0.01	<10	<10	1	<10	29		
E856420		185	<20	<0.01	<10	<10	1	<10	14		
E856421		305	<20	<0.01	<10	<10	1	<10	30		
E856422		307	<20	<0.01	<10	<10	1	<10	19		
E856423		93	<20	<0.01	<10	<10	1	<10	31		
E856424		65	<20	<0.01	<10	<10	3	<10	45		
E856425		53	<20	<0.01	<10	<10	3	<10	52		
E856426		68	<20	<0.01	<10	<10	2	<10	29		
E856427		40	<20	<0.01	<10	<10	2	<10	43		
E856428		68	<20	<0.01	<10	<10	1	<10	26		
E856429		70	<20	<0.01	<10	<10	1	<10	25		
E856430		1	<20	<0.01	<10	<10	<1	<10	2		
E856431		45	<20	<0.01	<10	<10	1	<10	11		
E856432		47	<20	<0.01	<10	<10	1	<10	11		
E856433		89	<20	<0.01	<10	<10	1	<10	21		
E856434		76	<20	<0.01	<10	<10	1	<10	20		
E856435		45	<20	<0.01	<10	<10	2	<10	41		
E856436		55	<20	<0.01	<10	<10	1	<10	10		
E856437		94	<20	<0.01	<10	<10	2	<10	36		

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091335

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856438		0.96	0.171		0.2	0.28	3470	<10	50	<0.5	<2	1.89	<0.5	4	6	9
E856439		0.38	0.305		0.3	0.27	2010	<10	50	<0.5	<2	2.37	<0.5	3	17	14
E856440		0.32	0.159		<0.2	0.14	825	<10	30	<0.5	<2	2.02	<0.5	1	6	1
E856441		0.46	<0.005		<0.2	0.26	72	<10	70	<0.5	<2	0.76	<0.5	7	14	11
E856442		0.40	0.007		<0.2	0.26	92	<10	70	<0.5	<2	0.36	<0.5	8	5	22
E856443		2.40	<0.005		<0.2	0.23	60	<10	70	<0.5	<2	0.50	<0.5	4	17	8
E856444		2.34	0.248		<0.2	0.25	2300	<10	60	<0.5	<2	0.67	<0.5	4	7	7
E856445		1.78	0.008		<0.2	0.23	115	<10	60	<0.5	<2	0.66	<0.5	3	15	5
E856446		1.78	0.007		0.2	0.38	92	<10	80	<0.5	<2	0.89	<0.5	8	13	18
E856447		2.00	<0.005		<0.2	0.34	14	<10	80	<0.5	<2	0.33	<0.5	6	13	11
E856448		2.66	<0.005		<0.2	0.30	28	<10	90	<0.5	<2	0.23	<0.5	5	7	6
E856449		<0.02	<0.005		<0.2	0.31	30	<10	90	<0.5	<2	0.27	<0.5	5	11	6
E856450		0.10	0.879		>100	0.50	4690	<10	20	<0.5	5	0.56	100.5	6	53	305
E858001		2.94	<0.005		0.2	0.24	35	<10	70	<0.5	<2	0.51	<0.5	6	6	7
E858002		2.38	0.010		<0.2	0.34	13	<10	70	<0.5	<2	0.29	<0.5	5	11	9
E858003		1.96	<0.005		<0.2	0.49	3	<10	70	<0.5	<2	0.26	<0.5	5	8	6
E858004		1.66	<0.005		<0.2	0.45	4	<10	60	<0.5	<2	0.39	<0.5	4	14	6

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091335

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856438		2.18	<10	<1	0.17	<10	0.72	343	<1	0.01	11	140	21	1.08	13	1
E856439		1.66	<10	<1	0.12	<10	0.88	525	<1	0.01	6	140	17	0.61	5	1
E856440		1.19	<10	<1	0.08	<10	0.78	452	<1	0.01	4	70	6	0.18	<2	1
E856441		1.68	<10	<1	0.25	20	0.43	322	<1	0.01	9	430	22	0.09	<2	1
E856442		2.23	<10	<1	0.25	20	0.50	186	<1	0.01	12	160	21	0.16	2	1
E856443		1.37	<10	<1	0.22	20	0.30	164	<1	0.01	8	120	18	0.13	<2	1
E856444		1.47	<10	<1	0.20	10	0.30	190	<1	0.01	8	120	18	0.53	5	1
E856445		1.03	<10	<1	0.21	10	0.26	222	<1	0.01	6	120	14	0.12	3	<1
E856446		1.87	<10	<1	0.26	20	0.41	245	<1	0.01	14	190	14	0.17	2	1
E856447		1.30	<10	<1	0.26	20	0.26	129	<1	0.02	10	190	13	0.17	<2	1
E856448		1.18	<10	<1	0.29	10	0.21	94	<1	0.01	9	130	15	0.16	<2	<1
E856449		1.17	<10	<1	0.28	10	0.22	96	<1	0.02	8	130	16	0.16	<2	<1
E856450		5.88	<10	1	0.31	10	0.10	293	1	0.04	5	660	5050	7.8	1810	1
E858001		1.42	<10	<1	0.25	10	0.29	149	<1	0.02	9	130	25	0.15	<2	1
E858002		1.19	<10	<1	0.25	20	0.21	116	<1	0.01	11	110	18	0.07	<2	<1
E858003		1.01	<10	<1	0.24	20	0.21	94	<1	0.01	8	120	17	0.04	<2	<1
E858004		0.88	<10	<1	0.25	20	0.19	132	<1	0.01	7	140	17	0.04	<2	<1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091335

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	5
E856438		95	<20	<0.01	<10	<10	3	<10	31		
E856439		89	<20	<0.01	<10	<10	2	<10	31		
E856440		76	<20	<0.01	<10	<10	1	<10	12		
E856441		63	<20	<0.01	<10	<10	2	<10	24		
E856442		34	<20	<0.01	<10	<10	2	<10	32		
E856443		43	<20	<0.01	<10	<10	2	<10	24		
E856444		58	<20	<0.01	<10	<10	1	<10	24		
E856445		40	<20	<0.01	<10	<10	2	<10	16		
E856446		62	<20	<0.01	<10	<10	4	<10	33		
E856447		30	<20	<0.01	<10	<10	2	<10	24		
E856448		23	<20	<0.01	<10	<10	2	<10	19		
E856449		26	<20	<0.01	<10	<10	2	<10	20		
E856450		135	<20	<0.01	<10	<10	6	<10	>10000	1.305	NSS
E858001		61	<20	<0.01	<10	<10	2	<10	41		
E858002		42	<20	<0.01	<10	<10	2	<10	19		
E858003		41	<20	0.01	<10	<10	3	<10	20		
E858004		50	<20	0.01	<10	<10	3	<10	18		

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 22-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091335

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

CERTIFICATE WH10091334

Project: ALN10-01

P.O. No.: ALN10-01_10

This report is for 45 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 6-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature: 

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091334

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856451		3.62	0.009		<0.2	1.33	8	<10	70	<0.5	<2	0.69	<0.5	11	16	37
E856452		3.88	<0.005		<0.2	0.89	8	<10	50	<0.5	<2	1.08	<0.5	8	13	15
E856453		4.06	<0.005		<0.2	1.16	17	<10	70	<0.5	<2	0.50	<0.5	10	15	21
E856454		3.98	<0.005		<0.2	2.15	50	<10	80	<0.5	<2	1.02	<0.5	18	22	37
E856455		3.94	0.006		0.2	3.11	39	<10	100	<0.5	<2	4.97	<0.5	20	27	37
E856456		3.66	<0.005		0.2	1.01	34	<10	90	<0.5	<2	5.19	<0.5	9	10	26
E856457		4.24	<0.005		0.3	0.83	82	<10	130	<0.5	<2	10.6	<0.5	10	8	30
E856458		4.04	<0.005		<0.2	1.96	16	<10	150	<0.5	<2	2.70	<0.5	19	15	47
E856459		3.88	<0.005		0.2	3.18	26	<10	60	<0.5	<2	6.33	<0.5	21	27	37
E856460		3.04	<0.005		<0.2	2.00	7	<10	160	<0.5	<2	1.02	<0.5	18	18	43
E856461		1.46	<0.005		<0.2	0.90	16	<10	100	<0.5	<2	0.33	<0.5	13	12	18
E856462		2.22	<0.005		<0.2	0.97	18	<10	90	<0.5	<2	0.35	<0.5	8	13	20
E856463		4.40	<0.005		<0.2	1.13	9	<10	80	<0.5	<2	0.57	<0.5	15	15	23
E856464		4.32	<0.005		<0.2	0.90	11	<10	60	<0.5	<2	0.33	<0.5	13	13	18
E856465		3.70	<0.005		<0.2	1.11	4	<10	80	<0.5	<2	0.55	<0.5	12	14	27
E856466		4.02	<0.005		<0.2	1.20	3	<10	70	<0.5	<2	0.58	<0.5	12	16	23
E856467		3.58	<0.005		<0.2	1.30	3	<10	70	<0.5	<2	0.98	<0.5	13	16	30
E856468		3.56	<0.005		<0.2	1.63	7	<10	70	<0.5	<2	0.55	<0.5	17	21	45
E856469		<0.02	<0.005		<0.2	1.69	8	<10	80	<0.5	<2	0.51	<0.5	17	22	39
E856470		0.10	0.866		>100	0.53	4630	<10	20	<0.5	5	0.53	97.6	6	52	295
E856471		3.46	<0.005		0.3	1.74	21	<10	60	<0.5	<2	4.83	<0.5	14	18	40
E856472		4.30	0.011		0.5	3.19	34	<10	30	<0.5	<2	4.43	<0.5	24	33	27
E856473		3.84	<0.005		<0.2	1.84	17	<10	160	<0.5	<2	0.90	<0.5	21	17	49
E856474		4.48	<0.005		<0.2	3.26	40	<10	400	<0.5	<2	2.62	<0.5	29	45	29
E856475		5.04	<0.005		<0.2	3.40	15	<10	700	<0.5	<2	3.14	<0.5	26	43	26
E856476		5.32	0.007		0.2	3.35	21	<10	150	<0.5	<2	3.44	<0.5	23	40	36
E856477		3.36	<0.005		0.5	1.96	155	<10	210	<0.5	<2	0.67	2.3	18	22	43
E856478		3.74	<0.005		<0.2	2.56	71	<10	90	<0.5	<2	2.92	<0.5	15	32	18
E856479		2.84	<0.005		<0.2	3.30	116	<10	30	<0.5	<2	0.84	1.3	24	40	34
E856480		4.04	<0.005		<0.2	3.61	63	<10	20	<0.5	<2	2.43	0.8	30	42	31
E856481		2.28	<0.005		<0.2	2.60	25	<10	250	0.7	<2	0.92	<0.5	22	30	33
E856482		1.72	<0.005		<0.2	2.59	29	<10	270	0.8	<2	0.93	0.5	23	30	38
E856483		3.96	0.007		<0.2	2.12	37	<10	300	0.9	<2	0.40	<0.5	18	28	43
E856484		3.52	<0.005		<0.2	1.67	8	<10	360	<0.5	<2	0.08	<0.5	14	16	27
E856485		3.90	<0.005		0.2	3.49	13	<10	150	0.5	<2	1.74	<0.5	26	29	53
E856486		4.86	0.005		0.3	2.59	18	<10	170	<0.5	<2	1.86	<0.5	20	32	42
E856487		3.38	<0.005		0.2	3.71	54	<10	60	<0.5	<2	2.97	<0.5	26	37	37
E856488		2.66	0.005		17.3	3.72	55	<10	130	<0.5	<2	1.83	<0.5	25	39	42
E856489		<0.02	0.005		20.8	3.65	53	<10	120	<0.5	<2	1.77	<0.5	25	38	46
E856490		0.10	1.540	NSS	>100	0.37	4450	<10	30	<0.5	7	0.73	475	5	51	873

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091334

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856451		3.15	<10	<1	0.28	10	0.55	278	<1	0.01	15	210	10	0.16	<2	1
E856452		1.95	<10	<1	0.19	10	0.37	296	<1	0.01	18	130	12	0.06	2	1
E856453		2.61	<10	<1	0.28	20	0.45	252	<1	0.01	18	310	13	0.03	3	1
E856454		4.36	10	<1	0.20	10	1.36	511	<1	0.01	31	880	9	0.10	10	4
E856455		5.43	10	1	0.19	10	2.18	930	<1	0.02	37	1430	8	0.14	7	7
E856456		2.49	<10	<1	0.18	10	0.58	581	<1	0.02	18	420	8	0.15	7	2
E856457		2.81	<10	<1	0.25	20	0.38	858	<1	0.02	20	270	16	0.30	10	2
E856458		4.53	10	<1	0.18	10	1.33	729	<1	0.01	32	920	15	0.59	5	4
E856459		5.65	10	<1	0.10	10	2.29	776	<1	0.03	33	1650	7	0.10	9	8
E856460		4.17	10	<1	0.25	10	1.27	364	<1	0.01	24	830	8	0.15	2	4
E856461		2.44	<10	<1	0.28	20	0.29	368	<1	0.02	24	150	12	0.19	12	1
E856462		2.64	<10	<1	0.24	10	0.35	210	<1	0.02	14	170	20	0.15	11	1
E856463		3.20	<10	<1	0.26	10	0.55	420	<1	0.02	24	260	9	0.56	4	1
E856464		2.68	<10	<1	0.21	10	0.45	305	<1	0.02	16	280	14	0.66	4	1
E856465		3.32	<10	<1	0.31	10	0.47	326	<1	0.02	24	530	16	0.84	3	1
E856466		3.14	<10	<1	0.26	10	0.52	497	<1	0.02	33	460	9	0.48	<2	1
E856467		3.44	<10	<1	0.31	10	0.52	547	<1	0.02	28	190	17	0.45	2	1
E856468		3.95	<10	<1	0.27	10	0.86	404	<1	0.01	25	400	13	0.37	3	1
E856469		4.06	<10	1	0.30	10	0.85	396	<1	0.01	25	390	7	0.38	3	1
E856470		6.15	<10	1	0.32	10	0.10	297	1	0.04	3	660	4870	7.7	1535	1
E856471		3.73	10	<1	0.21	10	1.20	668	<1	0.02	29	670	13	0.39	6	3
E856472		5.68	20	<1	0.10	10	2.46	1165	<1	0.03	41	1870	79	0.13	6	10
E856473		4.42	10	<1	0.25	10	1.24	511	1	0.01	37	980	8	0.42	13	3
E856474		6.54	20	<1	0.07	<10	2.47	677	<1	0.05	50	2350	2	0.13	10	12
E856475		6.82	20	<1	0.23	<10	2.72	835	<1	0.03	45	2230	4	0.20	4	12
E856476		5.69	20	<1	0.23	10	2.58	792	<1	0.04	42	1790	6	0.07	3	10
E856477		3.85	10	<1	0.29	20	1.24	743	<1	0.02	32	780	17	0.09	25	4
E856478		3.55	10	1	0.20	20	2.70	1275	<1	0.02	27	490	21	0.06	16	6
E856479		5.95	20	<1	0.04	<10	2.90	728	<1	0.04	40	2070	21	0.07	25	11
E856480		6.58	20	<1	0.01	<10	2.87	693	<1	0.03	49	2420	3	0.05	12	12
E856481		4.98	10	<1	0.24	10	1.72	388	<1	0.02	35	1230	7	0.09	12	6
E856482		5.04	10	1	0.26	20	1.67	416	<1	0.02	37	1190	6	0.10	8	6
E856483		4.49	10	<1	0.33	30	1.15	387	<1	0.02	37	460	13	0.13	11	4
E856484		3.57	<10	<1	0.41	20	0.69	252	<1	0.01	26	280	3	0.03	3	2
E856485		5.68	20	1	0.18	10	2.25	517	<1	0.02	51	1910	5	0.17	<2	9
E856486		4.44	10	<1	0.22	10	1.59	670	<1	0.03	37	1140	35	0.15	4	6
E856487		6.09	20	<1	0.09	10	2.47	1060	<1	0.03	48	2160	5	0.02	18	9
E856488		6.02	20	<1	0.10	10	2.58	754	9	0.02	46	2030	4	0.02	18	9
E856489		5.91	20	<1	0.09	10	2.54	744	10	0.02	45	2030	3	0.02	18	9
E856490		6.27	<10	3	0.24	10	0.24	342	1	0.03	3	550	>10000	9.8	2530	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091334

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856451		39	<20	<0.01	<10	<10	8	<10	54			
E856452		58	<20	<0.01	<10	<10	6	<10	35			
E856453		20	<20	0.01	<10	<10	7	<10	44			
E856454		68	<20	0.02	<10	<10	31	<10	82			
E856455		292	<20	0.08	<10	<10	50	<10	86			
E856456		293	<20	0.01	<10	<10	11	<10	45			
E856457		467	<20	0.01	<10	<10	7	<10	43			
E856458		156	<20	0.02	<10	<10	27	<10	79			
E856459		337	<20	0.23	<10	<10	64	<10	152			
E856460		76	<20	0.04	<10	<10	28	<10	71			
E856461		14	<20	0.01	<10	<10	6	<10	65			
E856462		18	<20	0.01	<10	<10	6	<10	61			
E856463		24	<20	<0.01	<10	<10	8	<10	57			
E856464		16	<20	<0.01	<10	<10	8	<10	40			
E856465		23	<20	<0.01	<10	<10	7	<10	66			
E856466		22	<20	<0.01	<10	<10	7	<10	64			
E856467		42	<20	<0.01	<10	<10	8	<10	61			
E856468		22	<20	<0.01	<10	<10	11	<10	77			
E856469		21	<20	<0.01	<10	<10	11	<10	78			
E856470		134	<20	<0.01	<10	<10	6	10	>10000		1.320	146
E856471		200	<20	<0.01	<10	<10	22	<10	82			
E856472		191	<20	0.03	<10	<10	67	<10	91			
E856473		36	<20	0.01	<10	<10	26	<10	73			
E856474		189	<20	0.27	<10	<10	109	<10	161			
E856475		244	<20	0.39	<10	<10	105	<10	111			
E856476		256	<20	0.34	<10	<10	90	<10	133			
E856477		29	<20	0.06	<10	<10	31	<10	355			
E856478		228	<20	0.08	<10	<10	37	<10	145			
E856479		66	<20	0.26	<10	<10	109	<10	254			
E856480		357	<20	0.28	<10	<10	118	<10	205			
E856481		108	<20	0.16	<10	<10	62	<10	139			
E856482		130	<20	0.14	<10	<10	58	<10	143			
E856483		45	<20	0.03	<10	<10	35	<10	120			
E856484		7	20	0.02	<10	<10	13	<10	69			
E856485		219	<20	0.20	<10	<10	85	<10	121			
E856486		203	<20	0.05	<10	<10	57	<10	115			
E856487		272	<20	0.08	<10	<10	85	<10	170			
E856488		164	<20	0.09	<10	<10	79	<10	183			
E856489		157	<20	0.09	<10	<10	78	<10	178			
E856490		111	<20	<0.01	<10	<10	5	10	>10000	1.915	3.65	NSS

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091334

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856491		4.76	<0.005		2.6	3.22	35	<10	180	0.5	<2	1.23	<0.5	23	35	54
E856492		4.54	<0.005		0.6	3.71	15	<10	370	<0.5	<2	1.95	<0.5	27	49	41
E856493		5.48	<0.005		0.3	2.92	10	<10	1990	0.5	<2	2.15	<0.5	27	42	40
E856494		2.84	<0.005		0.2	3.72	7	<10	240	<0.5	<2	2.73	<0.5	28	41	50
E856495		2.64	<0.005		0.5	2.85	8	<10	120	<0.5	<2	1.67	<0.5	21	30	37

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091334

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856491		5.52	20	<1	0.19	10	2.29	424	1	0.03	39	1780	32	0.24	7	8
E856492		6.48	20	<1	0.02	<10	2.71	609	<1	0.04	49	2270	5	0.11	5	12
E856493		6.58	20	<1	0.09	<10	2.19	605	<1	0.06	50	2380	4	0.12	3	13
E856494		7.00	20	1	0.01	<10	2.43	946	<1	0.04	49	2370	7	0.46	3	12
E856495		5.27	10	<1	0.15	10	1.66	655	<1	0.03	39	1610	19	0.26	14	7

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091334

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856491		139	<20	0.22	<10	<10	79	<10	305			
E856492		312	<20	0.35	<10	<10	113	<10	143			
E856493		453	<20	0.39	<10	<10	112	<10	130			
E856494		367	<20	0.54	<10	<10	108	<10	139			
E856495		167	<20	0.33	<10	<10	66	<10	102			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091334

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

CERTIFICATE WH10087540

Project: ALN10-01

P.O. No.: ALN10-01_6

This report is for 169 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 30-JUN-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856116		3.91	<0.005		0.2	1.17	4	<10	60	<0.5	<2	1.53	<0.5	8	15	24
E856117		2.68	<0.005		0.2	1.78	4	<10	70	<0.5	<2	0.35	<0.5	12	19	29
E856118		4.75	<0.005		0.2	1.64	9	<10	70	<0.5	<2	1.40	<0.5	12	19	32
E856119		3.67	<0.005		0.3	1.33	3	<10	60	<0.5	<2	5.00	<0.5	11	16	20
E856120		1.77	<0.005		0.2	1.20	2	<10	40	<0.5	<2	2.14	<0.5	6	16	12
E856121		2.08	<0.005		0.3	1.22	2	<10	40	<0.5	<2	2.38	<0.5	7	17	12
E856122		3.50	<0.005		0.2	1.11	2	<10	40	<0.5	<2	3.03	<0.5	6	15	13
E856123		3.53	<0.005		0.2	1.34	2	<10	50	<0.5	<2	1.42	<0.5	7	16	16
E856124		3.64	<0.005		0.3	1.38	<2	<10	60	<0.5	<2	4.25	<0.5	9	14	19
E856125		3.71	<0.005		0.2	1.14	2	<10	60	<0.5	<2	4.31	<0.5	8	13	15
E856126		3.52	<0.005		0.3	1.21	5	<10	50	<0.5	<2	6.13	<0.5	10	13	19
E856127		3.47	<0.005		0.2	1.46	5	<10	50	<0.5	<2	3.94	<0.5	10	14	24
E856128		3.69	<0.005		<0.2	1.74	4	<10	60	<0.5	<2	0.69	<0.5	11	20	26
E856129		<0.02	<0.005		0.2	1.64	2	<10	50	<0.5	<2	0.70	<0.5	11	19	26
E856130		3.63	<0.005		<0.2	1.60	4	<10	60	<0.5	<2	0.47	<0.5	12	18	27
E856131		3.57	<0.005		<0.2	1.60	3	<10	50	<0.5	<2	0.70	<0.5	11	19	26
E856132		3.78	<0.005		0.2	1.87	<2	<10	50	<0.5	2	0.69	<0.5	12	24	28
E856133		3.59	<0.005		0.3	2.08	6	<10	60	<0.5	<2	0.64	<0.5	15	25	47
E856134		3.45	<0.005		0.2	2.03	7	<10	60	<0.5	<2	0.59	<0.5	15	22	31
E856135		0.22	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	1.75	<0.5	<1	<1	<1
E856136		3.58	<0.005		<0.2	2.03	3	<10	70	0.5	<2	0.16	<0.5	14	21	35
E856137		3.90	<0.005		<0.2	1.58	6	<10	60	<0.5	<2	0.35	<0.5	14	18	32
E856138		3.21	<0.005		0.2	1.34	3	<10	50	<0.5	<2	1.61	<0.5	12	17	27
E856139		3.33	<0.005		0.3	1.07	3	<10	50	<0.5	<2	4.76	<0.5	9	10	17
E856140		1.27	<0.005		0.3	0.81	<2	<10	50	<0.5	<2	4.92	<0.5	11	9	21
E856141		1.44	<0.005		0.3	0.84	<2	<10	60	<0.5	<2	4.52	<0.5	11	9	24
E856142		2.93	<0.005		0.2	0.78	<2	<10	70	<0.5	<2	4.63	<0.5	7	9	11
E856143		3.91	<0.005		0.3	0.64	2	<10	70	<0.5	<2	8.0	<0.5	6	8	10
E856144		3.27	<0.005		0.2	0.78	3	<10	80	<0.5	<2	3.55	<0.5	7	9	11
E856145		3.47	<0.005		<0.2	0.70	3	<10	80	<0.5	<2	1.36	<0.5	9	8	15
E856146		3.38	<0.005		0.3	0.60	<2	<10	80	<0.5	<2	0.99	<0.5	7	8	12
E856147		3.56	<0.005		<0.2	0.51	3	<10	90	<0.5	<2	0.97	<0.5	5	6	8
E856148		3.58	<0.005		<0.2	0.68	5	<10	100	<0.5	<2	0.68	<0.5	7	8	13
E856149		<0.02	<0.005		<0.2	0.64	2	<10	90	<0.5	<2	0.67	<0.5	7	8	13
E856150		0.07	1.610	NSS	>100	0.35	4400	<10	20	<0.5	8	0.78	502	5	51	842
E856151		3.62	<0.005		<0.2	0.68	2	<10	80	<0.5	<2	0.83	<0.5	6	8	10
E856152		3.36	<0.005		<0.2	1.01	<2	<10	90	<0.5	<2	0.83	<0.5	9	10	19
E856153		4.09	<0.005		<0.2	0.99	<2	<10	80	<0.5	<2	0.85	<0.5	12	9	23
E856154		3.27	0.005		<0.2	1.27	4	<10	70	<0.5	<2	3.14	<0.5	11	11	24
E856155		4.05	<0.005		<0.2	2.39	<2	<10	130	0.5	<2	1.52	<0.5	19	22	33

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856116		2.63	<10	<1	0.18	20	0.46	421	<1	0.01	22	170	23	0.06	<2	1
E856117		3.64	10	<1	0.21	20	0.74	570	<1	0.01	28	350	33	0.10	<2	1
E856118		3.28	<10	<1	0.21	20	0.67	609	<1	0.02	25	420	17	0.14	<2	1
E856119		2.57	<10	<1	0.21	10	0.63	510	<1	0.01	23	210	11	0.20	<2	2
E856120		2.30	<10	<1	0.15	10	0.50	353	<1	0.01	14	560	11	0.07	<2	1
E856121		2.52	<10	<1	0.14	10	0.53	402	<1	0.01	17	200	11	0.10	<2	1
E856122		2.33	<10	<1	0.16	10	0.48	497	<1	0.01	15	170	15	0.12	<2	1
E856123		2.70	<10	<1	0.18	20	0.56	326	<1	0.01	18	230	15	0.09	<2	1
E856124		2.63	<10	<1	0.25	10	0.62	325	<1	0.01	19	220	12	0.26	<2	1
E856125		2.23	<10	<1	0.22	10	0.52	354	<1	0.01	17	210	13	0.20	<2	1
E856126		2.53	<10	<1	0.17	10	0.56	600	<1	0.01	18	150	15	0.20	<2	1
E856127		2.77	<10	<1	0.17	10	0.60	488	<1	0.02	21	360	13	0.13	<2	1
E856128		3.70	<10	<1	0.20	20	0.78	642	<1	0.02	26	300	15	0.15	<2	1
E856129		3.56	<10	<1	0.18	20	0.77	645	<1	0.02	25	280	16	0.16	<2	1
E856130		3.40	<10	<1	0.19	20	0.70	464	<1	0.03	25	150	11	0.15	<2	1
E856131		3.47	<10	<1	0.18	20	0.76	705	<1	0.02	23	270	21	0.18	<2	1
E856132		3.92	10	<1	0.17	20	0.86	742	<1	0.02	26	170	22	0.18	<2	2
E856133		4.16	10	<1	0.22	20	0.88	596	<1	0.03	30	980	15	0.26	<2	2
E856134		4.13	<10	<1	0.21	20	0.91	614	<1	0.02	30	750	12	0.17	<2	2
E856135		0.02	<10	<1	<0.01	<10	1.02	<5	<1	<0.01	<1	10	<2	0.01	<2	<1
E856136		3.98	<10	<1	0.22	30	0.85	372	<1	0.02	35	200	11	0.18	<2	1
E856137		3.28	<10	<1	0.19	20	0.65	427	<1	0.02	28	270	12	0.17	<2	1
E856138		2.95	<10	<1	0.19	10	0.62	565	<1	0.01	24	350	24	0.29	<2	1
E856139		2.49	<10	<1	0.18	10	0.59	321	<1	<0.01	20	360	11	0.47	<2	1
E856140		2.51	<10	<1	0.19	10	0.46	347	<1	0.01	22	230	16	0.90	<2	1
E856141		2.65	<10	<1	0.19	10	0.47	306	<1	0.01	26	190	15	1.06	<2	1
E856142		1.85	<10	<1	0.21	10	0.41	267	<1	0.01	14	180	15	0.35	<2	1
E856143		1.67	<10	<1	0.23	10	0.33	303	<1	0.01	12	190	14	0.44	<2	1
E856144		1.55	<10	<1	0.32	10	0.33	268	<1	0.01	12	170	14	0.17	<2	1
E856145		1.48	<10	<1	0.37	20	0.29	242	<1	<0.01	14	310	17	0.27	<2	1
E856146		1.31	<10	<1	0.35	10	0.24	198	<1	0.01	12	170	17	0.25	<2	1
E856147		0.93	<10	<1	0.31	20	0.18	165	<1	0.01	8	290	16	0.09	<2	1
E856148		1.29	<10	<1	0.43	20	0.25	175	<1	<0.01	14	360	16	0.14	<2	1
E856149		1.37	<10	<1	0.41	20	0.24	183	<1	<0.01	14	320	16	0.14	<2	1
E856150		6.45	<10	2	0.23	10	0.24	360	1	0.01	3	540	>10000	9.2	2330	1
E856151		1.35	<10	<1	0.33	20	0.27	200	<1	0.02	11	150	21	0.10	<2	1
E856152		1.90	<10	<1	0.37	20	0.37	188	<1	0.02	17	310	19	0.22	<2	1
E856153		2.58	<10	<1	0.33	20	0.42	276	<1	0.02	20	390	20	0.61	<2	1
E856154		2.74	<10	<1	0.28	10	0.58	644	<1	0.02	19	290	21	0.53	<2	1
E856155		4.83	10	<1	0.48	20	1.27	1195	<1	0.02	36	430	46	0.35	3	2

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856116		87	<20	<0.01	<10	<10	7	<10	58			
E856117		22	<20	0.01	<10	<10	12	<10	82			
E856118		78	<20	0.01	<10	<10	11	<10	70			
E856119		238	<20	<0.01	<10	<10	10	<10	56			
E856120		92	<20	<0.01	<10	<10	9	<10	43			
E856121		108	<20	<0.01	<10	<10	10	<10	46			
E856122		120	<20	<0.01	<10	<10	8	<10	42			
E856123		60	<20	<0.01	<10	<10	9	<10	46			
E856124		199	20	0.01	<10	<10	9	<10	56			
E856125		200	<20	<0.01	<10	<10	8	<10	47			
E856126		294	<20	<0.01	<10	<10	8	<10	58			
E856127		139	<20	<0.01	<10	<10	9	<10	61			
E856128		29	<20	<0.01	<10	<10	12	<10	79			
E856129		29	<20	<0.01	<10	<10	11	<10	74			
E856130		22	<20	<0.01	<10	<10	10	<10	75			
E856131		33	<20	0.01	<10	<10	11	<10	73			
E856132		34	<20	<0.01	<10	<10	15	<10	82			
E856133		38	<20	0.01	<10	<10	16	<10	87			
E856134		33	<20	0.01	<10	<10	14	<10	96			
E856135		95	<20	<0.01	<10	<10	1	<10	3			
E856136		14	20	0.01	<10	<10	13	<10	93			
E856137		18	<20	0.01	<10	<10	10	<10	71			
E856138		86	<20	0.01	<10	<10	9	<10	72			
E856139		233	<20	<0.01	<10	<10	7	<10	49			
E856140		214	<20	<0.01	<10	<10	5	<10	59			
E856141		190	<20	<0.01	<10	<10	5	<10	58			
E856142		238	<20	<0.01	<10	<10	6	<10	39			
E856143		307	<20	<0.01	<10	<10	5	<10	35			
E856144		158	<20	0.02	<10	<10	6	<10	34			
E856145		92	<20	0.02	<10	<10	5	<10	35			
E856146		84	<20	0.01	<10	<10	5	<10	29			
E856147		95	20	0.02	<10	<10	4	<10	22			
E856148		62	20	0.03	<10	<10	5	<10	31			
E856149		61	20	0.03	<10	<10	5	<10	31			
E856150		108	<20	<0.01	<10	<10	5	10	>10000	1.970	3.62	313
E856151		86	<20	0.03	<10	<10	5	<10	33			
E856152		82	20	0.02	<10	<10	6	<10	47			
E856153		61	20	0.01	<10	<10	6	<10	51			
E856154		214	20	0.01	<10	<10	7	<10	59			
E856155		72	20	0.01	<10	<10	13	<10	114			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856156		3.66	<0.005		<0.2	0.91	<2	<10	40	<0.5	<2	1.02	<0.5	10	8	20
E856157		3.39	<0.005		<0.2	0.91	<2	<10	50	<0.5	<2	0.98	<0.5	8	8	21
E856158		3.69	<0.005		<0.2	0.77	<2	<10	50	<0.5	<2	0.60	<0.5	8	7	19
E856159		3.13	0.005		<0.2	0.54	2	<10	40	<0.5	<2	5.53	<0.5	6	5	13
E856160		2.86	<0.005		<0.2	0.67	<2	<10	40	<0.5	<2	1.20	<0.5	10	6	22
E856161		1.59	<0.005		<0.2	0.83	<2	<10	50	<0.5	2	1.51	<0.5	12	9	23
E856162		2.28	<0.005		<0.2	0.71	<2	<10	50	<0.5	<2	1.35	<0.5	11	9	23
E856163		3.76	<0.005		0.3	0.31	5	<10	30	<0.5	<2	10.1	<0.5	5	5	9
E856164		3.57	<0.005		<0.2	0.74	<2	<10	60	<0.5	<2	0.97	<0.5	7	8	13
E856165		3.43	<0.005		0.3	0.54	2	<10	50	<0.5	<2	1.21	<0.5	5	7	13
E856166		4.95	<0.005		<0.2	0.98	3	<10	40	<0.5	<2	0.83	<0.5	8	11	16
E856167		4.32	<0.005		<0.2	1.48	4	<10	70	<0.5	<2	0.23	<0.5	14	16	34
E856168		3.52	<0.005		<0.2	1.67	8	<10	80	<0.5	<2	0.33	<0.5	14	19	27
E856169		<0.02	<0.005		<0.2	1.69	9	<10	80	<0.5	<2	0.32	<0.5	13	19	25
E856170		0.14	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.72	<0.5	<1	1	<1
E856171		4.30	<0.005		<0.2	1.40	4	<10	90	<0.5	<2	0.37	<0.5	10	19	30
E856172		6.11	<0.005		<0.2	1.22	5	<10	80	<0.5	<2	0.46	<0.5	10	16	22
E856173		4.20	<0.005		<0.2	0.70	4	<10	60	<0.5	<2	0.82	<0.5	5	15	10
E856174		4.19	<0.005		<0.2	1.19	2	<10	70	<0.5	<2	0.97	<0.5	8	16	18
E856175		5.69	<0.005		<0.2	1.84	13	<10	80	<0.5	<2	0.23	<0.5	19	21	42
E856176		4.95	<0.005		<0.2	1.57	2	<10	60	<0.5	<2	0.67	<0.5	9	18	23
E856177		5.09	<0.005		<0.2	1.07	<2	<10	50	<0.5	<2	0.84	<0.5	8	13	17
E856178		4.85	<0.005		<0.2	1.05	3	<10	60	<0.5	<2	1.97	<0.5	7	12	19
E856179		4.99	<0.005		<0.2	1.12	6	<10	60	<0.5	<2	0.66	<0.5	9	16	18
E856180		4.33	<0.005		<0.2	1.17	3	<10	60	<0.5	<2	0.81	<0.5	8	15	17
E856181		1.94	<0.005		0.2	1.40	4	<10	60	<0.5	<2	2.11	<0.5	10	17	25
E856182		2.22	<0.005		<0.2	1.37	2	<10	50	<0.5	<2	2.89	<0.5	9	16	24
E856183		6.14	<0.005		0.2	1.78	7	<10	50	0.5	<2	3.06	<0.5	13	20	32
E856184		4.83	<0.005		<0.2	1.38	<2	<10	60	<0.5	<2	2.04	<0.5	11	16	25
E856185		5.26	<0.005		0.2	0.72	5	<10	60	<0.5	<2	4.42	<0.5	7	9	12
E856186		4.22	<0.005		0.2	0.30	80	<10	40	<0.5	<2	3.49	<0.5	3	5	5
E856187		2.96	<0.005		<0.2	0.61	110	<10	50	<0.5	<2	3.13	<0.5	6	8	13
E856188		3.36	0.787		0.4	0.43	>10000	<10	90	<0.5	<2	1.38	<0.5	8	5	17
E856189		<0.02	0.800		0.4	0.38	>10000	<10	80	<0.5	<2	1.39	<0.5	8	4	16
E856190		0.13	<0.005		<0.2	0.01	14	<10	10	<0.5	<2	0.61	<0.5	<1	<1	<1
E856191		3.66	0.501		0.2	0.79	6250	<10	70	<0.5	<2	0.62	<0.5	13	8	31
E856192		4.58	0.029		<0.2	0.76	293	<10	60	<0.5	<2	1.01	<0.5	12	7	31
E856193		3.29	0.561		<0.2	0.31	2890	<10	50	<0.5	<2	10.6	<0.5	6	3	10
E856194		3.39	0.069		<0.2	0.28	399	<10	60	<0.5	<2	7.6	<0.5	7	4	18
E856195		2.33	1.130	1.18	<0.2	0.30	7190	<10	50	<0.5	<2	1.36	<0.5	11	5	29

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856156		2.56	<10	<1	0.22	10	0.63	514	<1	0.01	16	240	25	0.55	<2	1
E856157		2.43	<10	<1	0.26	10	0.58	445	<1	0.01	17	350	10	0.56	<2	1
E856158		1.85	<10	<1	0.24	10	0.41	273	<1	0.01	14	200	20	0.43	<2	1
E856159		1.79	<10	<1	0.22	10	0.75	522	<1	0.02	9	220	21	0.39	<2	1
E856160		2.12	<10	<1	0.21	10	0.45	388	<1	0.01	16	320	20	0.62	<2	1
E856161		2.61	<10	<1	0.27	10	0.53	485	<1	0.01	20	400	25	0.79	<2	1
E856162		2.39	<10	<1	0.23	10	0.48	426	<1	0.02	21	340	27	0.69	<2	1
E856163		1.43	<10	<1	0.17	10	0.64	527	<1	0.02	9	210	16	0.33	<2	1
E856164		1.78	<10	<1	0.26	20	0.57	345	<1	0.02	13	180	22	0.19	<2	1
E856165		1.72	<10	<1	0.21	10	0.56	368	<1	0.01	11	130	13	0.19	<2	1
E856166		2.32	<10	<1	0.20	20	0.70	259	<1	0.02	17	280	15	0.25	<2	1
E856167		3.19	<10	1	0.28	30	0.66	222	<1	0.02	30	220	33	0.17	<2	1
E856168		3.42	<10	<1	0.29	30	0.73	226	<1	0.02	29	490	19	0.09	<2	1
E856169		3.46	<10	<1	0.29	30	0.73	219	<1	0.02	27	590	21	0.09	<2	1
E856170		0.03	<10	<1	<0.01	<10	0.40	<5	<1	0.01	<1	20	<2	0.01	<2	<1
E856171		2.96	<10	1	0.29	20	0.54	203	<1	0.02	29	220	11	0.09	<2	1
E856172		2.54	<10	<1	0.26	20	0.48	255	<1	0.02	22	280	15	0.10	<2	1
E856173		1.38	<10	<1	0.16	20	0.29	308	<1	0.03	11	130	19	0.02	<2	1
E856174		2.41	<10	<1	0.19	20	0.51	360	<1	0.02	19	270	19	0.08	<2	1
E856175		3.77	10	<1	0.24	30	0.84	294	<1	0.02	37	370	35	0.21	<2	1
E856176		3.26	<10	1	0.22	20	0.80	530	<1	0.02	24	210	25	0.13	<2	1
E856177		2.22	<10	<1	0.20	20	0.56	432	<1	0.02	16	410	11	0.22	<2	1
E856178		2.33	<10	<1	0.23	20	0.58	475	<1	0.02	17	240	20	0.31	<2	1
E856179		2.35	<10	<1	0.21	20	0.58	293	<1	0.02	18	330	20	0.09	<2	1
E856180		2.42	<10	<1	0.20	20	0.50	292	<1	0.02	19	250	22	0.19	<2	1
E856181		2.63	<10	<1	0.20	20	0.62	304	<1	0.02	22	310	18	0.17	<2	1
E856182		2.71	<10	<1	0.18	20	0.63	383	<1	0.02	23	260	18	0.21	<2	1
E856183		3.47	<10	<1	0.21	20	0.77	472	<1	0.03	31	380	21	0.23	<2	1
E856184		3.09	<10	1	0.23	20	0.65	562	<1	0.03	23	260	20	0.42	2	1
E856185		1.81	<10	<1	0.19	10	0.35	605	<1	0.03	12	860	14	0.28	2	1
E856186		1.06	<10	<1	0.13	10	0.20	689	<1	0.03	5	120	17	0.17	9	1
E856187		1.95	<10	<1	0.18	10	0.36	598	<1	0.02	13	280	21	0.38	25	1
E856188		2.74	<10	<1	0.28	10	0.54	345	<1	0.02	21	190	13	1.83	32	1
E856189		2.80	<10	<1	0.25	10	0.54	340	<1	0.02	20	190	10	1.88	33	1
E856190		0.02	<10	<1	<0.01	<10	0.33	<5	<1	0.01	<1	20	<2	0.03	<2	<1
E856191		3.64	<10	<1	0.23	20	0.57	258	<1	0.02	30	360	13	1.41	102	1
E856192		3.18	<10	<1	0.21	20	0.57	374	1	0.02	26	300	19	0.71	54	1
E856193		1.84	<10	<1	0.15	<10	0.66	557	<1	0.02	11	300	14	1.06	24	2
E856194		1.87	<10	<1	0.15	10	0.45	1080	<1	0.02	14	230	12	0.68	23	1
E856195		3.01	<10	<1	0.15	10	0.66	632	1	0.01	22	250	11	1.80	32	2

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856156		31	<20	<0.01	<10	<10	4	<10	68			
E856157		26	20	<0.01	<10	<10	5	<10	56			
E856158		17	<20	<0.01	<10	<10	4	<10	41			
E856159		248	<20	<0.01	<10	<10	2	<10	34			
E856160		38	<20	<0.01	<10	<10	4	<10	39			
E856161		51	20	<0.01	<10	<10	5	<10	46			
E856162		42	<20	<0.01	<10	<10	4	<10	43			
E856163		424	<20	<0.01	<10	<10	2	<10	28			
E856164		44	<20	<0.01	<10	<10	4	<10	32			
E856165		50	<20	<0.01	<10	<10	3	<10	33			
E856166		41	<20	<0.01	<10	<10	6	<10	52			
E856167		24	20	0.01	<10	<10	10	<10	65			
E856168		30	<20	0.02	<10	<10	13	<10	62			
E856169		28	<20	0.02	<10	<10	13	<10	62			
E856170		34	<20	<0.01	<10	<10	<1	<10	3			
E856171		122	<20	0.02	<10	<10	11	<10	62			
E856172		55	<20	0.01	<10	<10	9	<10	50			
E856173		95	<20	<0.01	<10	<10	5	<10	26			
E856174		141	<20	<0.01	<10	<10	9	<10	52			
E856175		19	20	0.01	<10	<10	13	<10	89			
E856176		56	<20	0.01	<10	<10	12	<10	66			
E856177		55	<20	0.01	<10	<10	7	<10	45			
E856178		131	<20	0.01	<10	<10	8	<10	42			
E856179		55	<20	<0.01	<10	<10	9	<10	46			
E856180		60	<20	0.01	<10	<10	9	<10	49			
E856181		117	<20	<0.01	<10	<10	10	<10	58			
E856182		172	<20	<0.01	<10	<10	10	<10	61			
E856183		222	20	0.01	<10	<10	11	<10	78			
E856184		122	20	<0.01	<10	<10	10	<10	70			
E856185		310	<20	<0.01	<10	<10	5	<10	35			
E856186		221	<20	<0.01	<10	<10	2	<10	19			
E856187		193	<20	<0.01	<10	<10	4	<10	42			
E856188		80	<20	<0.01	<10	<10	3	<10	76			
E856189		82	<20	<0.01	<10	<10	3	<10	73			
E856190		33	<20	<0.01	<10	<10	<1	<10	2			
E856191		43	20	<0.01	<10	<10	5	<10	90			
E856192		62	20	<0.01	<10	<10	5	<10	82			
E856193		546	<20	<0.01	<10	<10	1	<10	41			
E856194		413	<20	<0.01	<10	<10	1	<10	38			
E856195		150	<20	<0.01	<10	<10	3	<10	60			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856196		1.99	0.809		<0.2	0.30	6490	<10	40	<0.5	<2	1.57	<0.5	7	6	16
E856197		4.63	0.452		<0.2	0.50	4150	<10	70	0.5	<2	0.67	<0.5	13	6	32
E856198		4.74	0.329		<0.2	0.35	3500	<10	60	<0.5	<2	0.80	<0.5	9	10	25
E856199		1.64	0.029		<0.2	0.47	212	<10	70	<0.5	<2	0.55	<0.5	7	8	18
E856200		1.76	0.106		<0.2	0.34	1640	<10	60	<0.5	<2	0.82	<0.5	7	5	12
E856201		0.85	0.312		<0.2	0.44	2910	<10	70	<0.5	<2	0.69	<0.5	10	6	28
E856202		0.86	0.059		<0.2	0.34	939	<10	60	<0.5	<2	0.33	<0.5	13	6	32
E856203		3.03	0.015		<0.2	0.41	99	<10	70	<0.5	<2	0.35	<0.5	17	6	46
E856204		3.04	0.016		<0.2	0.26	162	<10	100	<0.5	<2	0.41	<0.5	5	8	9
E856205		4.44	0.012		<0.2	0.23	93	<10	60	<0.5	<2	0.28	<0.5	3	10	3
E856206		4.01	0.009		<0.2	0.33	26	<10	60	<0.5	<2	0.22	<0.5	10	6	24
E856207		2.38	0.005		<0.2	0.24	5	<10	50	<0.5	<2	0.42	<0.5	3	9	4
E856208		3.06	0.107		<0.2	0.32	475	<10	50	<0.5	<2	0.68	<0.5	8	6	21
E856209		<0.02	0.105		<0.2	0.33	492	<10	50	<0.5	<2	0.68	<0.5	7	7	19
E856210		0.06	0.887		>100	0.55	4520	<10	30	<0.5	5	0.56	101.0	6	53	311
E856211		2.43	0.052		<0.2	0.42	274	<10	50	<0.5	<2	0.73	<0.5	9	8	24
E856212		2.42	0.099		<0.2	0.37	536	<10	40	<0.5	<2	0.70	<0.5	8	7	20
E856213		2.08	0.128		<0.2	0.43	313	<10	40	<0.5	2	0.59	<0.5	14	7	40
E856214		0.72	0.148		0.6	0.53	791	<10	50	0.5	<2	0.95	<0.5	9	9	33
E856215		3.55	0.062		<0.2	0.31	475	<10	30	<0.5	<2	0.84	<0.5	5	7	8
E856216		2.15	0.014		<0.2	0.35	48	<10	40	<0.5	<2	0.92	<0.5	6	6	13
E856217		2.84	0.029		<0.2	0.27	91	<10	40	<0.5	<2	0.91	<0.5	9	6	16
E856218		4.72	0.239		<0.2	0.32	2140	<10	40	<0.5	<2	1.78	<0.5	8	8	21
E856351		2.06	0.171		<0.2	0.33	1270	<10	40	<0.5	<2	1.64	<0.5	7	6	18
E856220		2.91	0.293		<0.2	0.28	2590	<10	60	<0.5	<2	1.20	<0.5	4	5	1
E856221		1.44	0.099		0.2	0.25	2550	<10	50	<0.5	<2	1.06	<0.5	8	3	13
E856222		1.53	0.133		<0.2	0.32	2550	<10	60	<0.5	<2	1.32	<0.5	6	4	12
E856223		4.88	0.090		<0.2	0.32	396	<10	50	<0.5	<2	1.07	<0.5	10	4	22
E856224		3.91	0.159		<0.2	0.30	539	<10	50	<0.5	<2	0.69	<0.5	11	5	28
E856225		3.96	0.062		<0.2	0.30	255	<10	50	<0.5	<2	0.79	<0.5	4	6	10
E856226		4.25	<0.005		<0.2	0.34	32	<10	50	<0.5	<2	0.79	<0.5	5	6	7
E856227		4.43	<0.005		<0.2	0.46	10	<10	40	<0.5	<2	0.88	<0.5	8	7	17
E856228		3.79	<0.005		<0.2	0.58	2	<10	40	<0.5	<2	0.71	<0.5	8	7	21
E856229		<0.02	<0.005		<0.2	0.61	5	<10	40	<0.5	<2	0.71	<0.5	10	7	20
E856230		0.15	<0.005		<0.2	0.01	<2	<10	20	<0.5	<2	1.02	<0.5	1	<1	<1
E856231		3.99	<0.005		<0.2	0.54	3	<10	40	<0.5	<2	1.09	<0.5	8	8	20
E856232		3.63	<0.005		<0.2	0.65	4	<10	40	<0.5	<2	0.65	<0.5	11	7	30
E856233		3.68	<0.005		<0.2	0.67	6	<10	40	<0.5	<2	0.46	<0.5	16	9	40
E856234		5.37	<0.005		<0.2	0.70	7	<10	50	<0.5	<2	0.75	<0.5	11	10	28
E856235		5.04	0.006		<0.2	0.75	17	<10	50	<0.5	<2	0.72	<0.5	11	12	46

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856196		2.40	<10	<1	0.15	<10	0.76	539	<1	0.02	13	120	15	1.66	28	1
E856197		3.91	<10	<1	0.22	10	0.67	509	1	0.02	29	260	11	1.74	38	2
E856198		3.00	<10	<1	0.18	10	0.62	380	1	0.02	18	230	12	1.23	29	2
E856199		2.68	<10	<1	0.24	10	0.59	323	<1	0.02	14	260	14	0.53	25	2
E856200		2.31	<10	<1	0.16	10	0.60	323	<1	0.02	13	200	8	0.93	18	1
E856201		3.46	<10	<1	0.23	10	0.65	452	<1	0.02	19	280	12	1.39	33	2
E856202		3.54	<10	<1	0.21	10	0.63	406	1	0.02	24	300	14	1.18	34	2
E856203		4.02	<10	<1	0.23	10	0.72	369	1	0.01	33	310	28	1.21	44	2
E856204		1.82	<10	<1	0.11	10	0.31	305	<1	0.02	7	190	6	0.37	13	1
E856205		1.11	<10	<1	0.08	10	0.16	213	<1	0.01	3	190	7	0.25	6	<1
E856206		2.64	<10	<1	0.15	10	0.43	309	1	0.03	18	230	12	0.73	17	1
E856207		1.44	<10	<1	0.10	10	0.26	333	<1	0.03	4	170	13	0.23	7	1
E856208		2.55	<10	<1	0.16	10	0.55	498	<1	0.03	15	200	12	0.63	19	1
E856209		2.53	<10	<1	0.17	10	0.55	500	<1	0.02	14	180	11	0.59	17	1
E856210		5.99	<10	1	0.33	10	0.10	302	2	0.04	3	690	5030	8.0	1880	1
E856211		2.51	<10	<1	0.20	10	0.54	488	<1	0.02	18	160	11	0.69	21	1
E856212		2.32	<10	<1	0.16	10	0.47	380	<1	0.02	12	140	14	0.62	27	2
E856213		2.64	<10	<1	0.19	10	0.35	321	<1	0.02	20	1300	255	1.17	194	1
E856214		2.79	<10	<1	0.18	10	0.56	449	1	0.02	17	150	23	0.91	41	2
E856215		1.75	<10	<1	0.13	10	0.41	359	<1	0.02	9	110	6	0.31	11	1
E856216		2.01	<10	<1	0.16	10	0.45	467	1	0.02	11	120	15	0.41	14	1
E856217		2.20	<10	<1	0.16	10	0.53	480	<1	0.02	11	160	8	0.30	15	1
E856218		2.68	<10	<1	0.18	10	0.81	727	<1	0.02	12	170	19	0.61	28	1
E856351		2.54	<10	<1	0.17	10	0.71	716	<1	0.02	12	130	10	0.71	19	1
E856220		1.20	<10	<1	0.15	10	0.40	397	<1	0.02	5	460	<2	0.48	4	1
E856221		1.83	<10	<1	0.15	10	0.39	355	<1	0.02	10	160	2	1.04	10	1
E856222		1.79	<10	<1	0.19	10	0.48	440	<1	0.02	9	130	4	0.79	12	1
E856223		2.40	<10	<1	0.18	10	0.53	417	1	0.02	17	180	8	1.15	19	1
E856224		2.92	<10	<1	0.17	10	0.56	578	1	0.03	21	210	11	1.08	20	1
E856225		1.54	<10	<1	0.14	10	0.35	296	1	0.02	8	140	10	0.28	10	1
E856226		1.31	<10	<1	0.13	10	0.36	232	1	0.03	6	180	8	0.07	3	1
E856227		2.36	<10	<1	0.16	10	0.57	458	<1	0.03	12	150	7	0.17	2	1
E856228		2.63	<10	<1	0.16	10	0.55	442	<1	0.03	17	190	7	0.21	<2	1
E856229		2.77	<10	<1	0.17	10	0.55	455	<1	0.03	16	240	12	0.23	<2	1
E856230		0.02	<10	<1	<0.01	<10	0.58	<5	<1	0.01	<1	20	<2	0.04	<2	<1
E856231		2.22	<10	<1	0.16	10	0.57	485	<1	0.03	13	180	6	0.15	<2	1
E856232		3.09	<10	<1	0.18	10	0.59	525	<1	0.03	20	350	11	0.28	3	1
E856233		3.40	<10	<1	0.19	10	0.62	605	<1	0.03	26	260	14	0.38	<2	1
E856234		2.94	<10	<1	0.18	10	0.61	796	<1	0.03	17	200	27	0.26	<2	1
E856235		3.13	<10	<1	0.18	10	0.67	650	<1	0.03	21	160	46	0.61	9	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856196		208	<20	<0.01	<10	<10	3	<10	45			
E856197		76	<20	<0.01	<10	<10	4	<10	77			
E856198		89	<20	<0.01	<10	<10	3	<10	51			
E856199		40	<20	<0.01	<10	<10	5	<10	44			
E856200		69	<20	<0.01	<10	<10	3	<10	34			
E856201		73	<20	<0.01	<10	<10	4	<10	52			
E856202		25	<20	<0.01	<10	<10	4	<10	57			
E856203		27	<20	<0.01	<10	<10	5	<10	69			
E856204		28	<20	<0.01	<10	<10	2	<10	25			
E856205		20	<20	<0.01	<10	<10	2	<10	10			
E856206		19	<20	<0.01	<10	<10	4	<10	42			
E856207		25	<20	<0.01	<10	<10	2	<10	14			
E856208		46	<20	<0.01	<10	<10	3	<10	40			
E856209		46	<20	<0.01	<10	<10	3	<10	37			
E856210		142	<20	<0.01	<10	<10	6	10	>10000		1.285	145
E856211		50	<20	<0.01	<10	<10	3	<10	52			
E856212		53	<20	<0.01	<10	<10	3	<10	40			
E856213		42	<20	<0.01	<10	<10	3	<10	36			
E856214		91	<20	<0.01	<10	<10	4	<10	50			
E856215		50	<20	<0.01	<10	<10	2	<10	26			
E856216		54	<20	<0.01	<10	<10	2	<10	30			
E856217		41	<20	<0.01	<10	<10	2	<10	36			
E856218		105	<20	<0.01	<10	<10	2	<10	38			
E856351		123	<20	<0.01	<10	<10	2	<10	45			
E856220		85	<20	<0.01	<10	<10	2	<10	15			
E856221		55	<20	<0.01	<10	<10	2	<10	28			
E856222		67	<20	<0.01	<10	<10	2	<10	29			
E856223		44	<20	<0.01	<10	<10	2	<10	43			
E856224		35	<20	<0.01	<10	<10	2	<10	47			
E856225		41	<20	<0.01	<10	<10	2	<10	20			
E856226		40	<20	<0.01	<10	<10	2	<10	20			
E856227		32	<20	<0.01	<10	<10	3	<10	35			
E856228		30	<20	<0.01	<10	<10	5	<10	41			
E856229		30	<20	<0.01	<10	<10	5	<10	43			
E856230		58	<20	<0.01	<10	<10	<1	<10	2			
E856231		43	<20	<0.01	<10	<10	3	<10	36			
E856232		31	<20	<0.01	<10	<10	4	<10	50			
E856233		23	<20	<0.01	<10	<10	5	<10	55			
E856234		34	<20	<0.01	<10	<10	5	<10	43			
E856235		47	<20	<0.01	<10	<10	6	<10	59			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Method	WEI-21	Au-AA23	Au-GRA21	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
Analyte	Recvd Wt.	Au	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu
Units	kg	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
Sample Description LOR	0.02	0.005	0.05	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1
E856236	5.23	<0.005		<0.2	1.33	12	<10	60	<0.5	<2	0.52	<0.5	18	14	58
E856237	4.96	<0.005		<0.2	1.26	14	<10	50	<0.5	<2	0.52	<0.5	16	14	43
E856238	3.95	<0.005		<0.2	1.44	10	<10	70	<0.5	<2	0.36	<0.5	13	14	50
E856239	4.55	<0.005		<0.2	1.17	16	<10	50	<0.5	<2	0.44	<0.5	16	12	37
E856240	5.52	0.007		<0.2	0.82	30	<10	40	<0.5	<2	0.78	<0.5	17	9	31
E856241	1.16	0.019		0.2	0.64	80	<10	30	<0.5	<2	0.82	<0.5	14	8	34
E856242	1.16	0.015		0.3	0.72	66	<10	30	<0.5	<2	0.91	<0.5	11	9	25
E856243	3.83	0.627		0.3	0.39	1700	<10	30	<0.5	<2	0.66	<0.5	9	5	22
E856244	4.36	<0.005		0.2	1.08	18	<10	30	<0.5	<2	0.62	<0.5	13	10	32
E856245	5.13	<0.005		0.3	0.92	8	<10	30	<0.5	<2	0.64	<0.5	9	9	21
E856246	5.12	<0.005		0.2	0.84	9	<10	30	<0.5	<2	0.74	<0.5	9	9	21
E856247	2.82	<0.005		0.2	1.22	20	<10	30	<0.5	<2	0.41	<0.5	11	16	23
E856248	3.26	<0.005		0.2	1.03	24	<10	40	<0.5	<2	0.55	<0.5	13	11	33
E856249	<0.02	<0.005		0.2	0.98	26	<10	40	<0.5	<2	0.59	<0.5	13	12	34
E856250	0.12	<0.005		<0.2	0.01	<2	<10	20	<0.5	<2	1.29	<0.5	1	1	<1
E856251	5.18	<0.005		<0.2	0.80	3	<10	40	<0.5	<2	0.29	<0.5	9	11	17
E856252	5.29	<0.005		<0.2	1.17	4	<10	50	<0.5	<2	0.31	<0.5	12	12	26
E856253	5.20	<0.005		<0.2	1.33	8	<10	50	<0.5	<2	0.46	<0.5	11	18	20
E856254	5.35	<0.005		<0.2	1.28	6	<10	40	<0.5	<2	0.48	<0.5	10	15	20
E856255	4.76	<0.005		<0.2	0.64	<2	<10	30	<0.5	<2	0.24	<0.5	4	12	11
E856256	3.75	<0.005		<0.2	0.76	4	<10	40	<0.5	<2	0.33	<0.5	6	11	15
E856257	4.61	<0.005		<0.2	0.72	<2	<10	40	<0.5	<2	0.51	<0.5	5	10	8
E856258	4.99	<0.005		<0.2	0.77	3	<10	30	<0.5	<2	0.20	<0.5	5	12	7
E856259	4.63	<0.005		<0.2	1.13	9	<10	40	<0.5	<2	0.17	<0.5	9	17	17
E856260	5.24	<0.005		<0.2	1.63	5	<10	50	<0.5	<2	0.31	<0.5	11	17	23
E856261	2.40	<0.005		<0.2	0.93	<2	<10	40	<0.5	<2	0.46	<0.5	6	12	16
E856262	2.25	<0.005		<0.2	0.93	<2	<10	40	<0.5	<2	0.50	<0.5	8	12	19
E856263	3.67	<0.005		<0.2	1.08	3	<10	50	<0.5	<2	0.76	<0.5	9	16	18
E856264	4.20	0.006		<0.2	1.44	47	<10	60	<0.5	<2	0.83	<0.5	12	18	25
E856265	4.12	<0.005		<0.2	1.52	4	<10	70	<0.5	<2	0.75	<0.5	11	25	30
E856266	4.41	<0.005		<0.2	0.87	<2	<10	50	<0.5	<2	0.96	<0.5	7	11	18
E856267	4.22	<0.005		<0.2	0.47	<2	<10	40	<0.5	<2	0.38	<0.5	3	11	5
E856268	4.05	<0.005		<0.2	2.00	18	<10	40	0.5	<2	0.26	<0.5	16	24	37
E856269	<0.02	<0.005		<0.2	2.05	19	<10	50	0.5	<2	0.27	<0.5	16	25	36
E856270	0.07	1.475	NSS	>100	0.38	4440	<10	30	<0.5	8	0.82	523	5	53	889
E856271	4.30	0.016		<0.2	1.19	8	<10	40	<0.5	<2	0.60	<0.5	8	16	24
E856272	4.44	<0.005		<0.2	0.71	7	<10	40	<0.5	<2	0.58	<0.5	4	12	9
E856273	5.29	0.008		<0.2	0.90	5	<10	30	<0.5	<2	0.23	<0.5	9	13	29
E856274	5.47	<0.005		<0.2	2.01	4	<10	50	0.5	<2	0.32	<0.5	14	23	35
E856275	5.17	<0.005		<0.2	0.90	2	<10	30	<0.5	<2	0.42	<0.5	8	13	22

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856236		3.31	<10	1	0.23	10	0.70	623	1	0.03	28	200	21	0.53	<2	1
E856237		3.57	<10	<1	0.20	10	0.78	927	<1	0.03	27	270	25	0.10	<2	2
E856238		3.69	<10	<1	0.26	20	0.75	747	<1	0.03	27	280	12	0.09	<2	2
E856239		3.39	<10	1	0.21	10	0.70	536	<1	0.03	28	300	13	0.16	3	1
E856240		2.68	<10	<1	0.22	10	0.61	450	<1	0.03	21	390	19	0.24	11	1
E856241		2.84	<10	<1	0.16	10	0.59	534	<1	0.01	26	190	21	0.53	20	1
E856242		2.88	<10	<1	0.16	10	0.66	570	<1	0.02	21	200	17	0.42	17	2
E856243		3.01	<10	<1	0.16	10	0.59	556	<1	0.01	17	240	15	0.88	22	1
E856244		3.23	<10	<1	0.19	10	0.68	617	<1	0.01	19	160	16	0.28	5	1
E856245		2.55	<10	<1	0.15	10	0.60	456	<1	0.01	16	210	17	0.09	<2	1
E856246		2.46	<10	<1	0.17	10	0.59	509	<1	0.02	16	230	8	0.07	<2	1
E856247		2.88	<10	<1	0.15	10	0.67	327	<1	0.02	22	280	13	0.05	5	1
E856248		2.76	<10	<1	0.21	10	0.61	527	<1	0.02	22	230	12	0.08	2	1
E856249		2.75	<10	<1	0.19	10	0.62	537	<1	0.02	22	220	10	0.09	2	1
E856250		0.02	<10	<1	<0.01	<10	0.73	<5	<1	0.01	<1	20	<2	0.03	<2	<1
E856251		2.21	<10	<1	0.21	10	0.40	374	<1	0.02	14	230	5	0.05	<2	1
E856252		2.75	<10	<1	0.23	20	0.50	442	<1	0.02	20	220	7	0.08	<2	1
E856253		2.64	<10	<1	0.20	10	0.54	411	<1	0.02	19	540	19	0.10	<2	1
E856254		2.65	<10	1	0.17	10	0.53	419	<1	0.02	19	740	18	0.12	<2	1
E856255		1.35	<10	<1	0.12	10	0.24	236	<1	0.02	7	130	3	0.03	<2	<1
E856256		1.69	<10	<1	0.16	10	0.27	303	<1	0.02	9	260	11	0.05	<2	1
E856257		1.65	<10	<1	0.16	10	0.32	414	<1	0.02	7	180	6	0.03	<2	1
E856258		1.78	<10	<1	0.13	10	0.29	403	<1	0.02	8	110	7	0.04	<2	1
E856259		2.60	<10	<1	0.13	10	0.43	504	<1	0.03	15	300	18	0.11	<2	2
E856260		3.32	<10	<1	0.17	10	0.62	432	<1	0.02	23	300	31	0.02	<2	2
E856261		2.34	<10	<1	0.17	10	0.45	428	<1	0.02	15	300	31	0.02	<2	1
E856262		2.38	<10	<1	0.17	10	0.46	450	<1	0.02	14	280	20	0.02	<2	1
E856263		2.65	<10	<1	0.19	10	0.58	726	<1	0.02	17	180	7	<0.01	<2	1
E856264		3.20	<10	1	0.17	10	0.70	718	<1	0.03	23	300	7	0.04	<2	2
E856265		3.27	<10	<1	0.19	10	0.74	746	<1	0.03	24	340	9	0.02	<2	2
E856266		2.26	<10	<1	0.16	10	0.55	708	<1	0.02	14	400	22	0.01	<2	1
E856267		1.29	<10	<1	0.12	10	0.23	309	<1	0.02	5	70	7	<0.01	<2	1
E856268		3.96	10	<1	0.19	20	0.75	506	<1	0.02	37	460	3	0.03	<2	2
E856269		4.09	10	<1	0.20	20	0.77	520	<1	0.03	37	500	7	0.04	<2	2
E856270		6.57	<10	3	0.24	10	0.25	374	1	0.02	2	580	>10000	>10.0	2730	1
E856271		2.73	<10	<1	0.16	10	0.53	559	<1	0.02	18	250	12	0.02	<2	1
E856272		1.55	<10	<1	0.15	10	0.32	422	<1	0.02	6	110	7	<0.01	<2	1
E856273		2.24	<10	<1	0.13	10	0.39	414	<1	0.02	17	190	8	0.01	<2	1
E856274		4.27	10	1	0.22	20	0.82	609	<1	0.03	35	420	14	0.02	2	2
E856275		2.38	<10	<1	0.15	10	0.48	482	<1	0.02	17	200	5	<0.01	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856236		32	<20	<0.01	<10	<10	8	<10	67			
E856237		28	<20	<0.01	<10	<10	9	<10	67			
E856238		23	<20	<0.01	<10	<10	9	<10	68			
E856239		23	<20	<0.01	<10	<10	7	<10	66			
E856240		29	<20	<0.01	<10	<10	6	<10	46			
E856241		32	<20	<0.01	<10	<10	6	<10	45			
E856242		37	<20	<0.01	<10	<10	7	<10	46			
E856243		31	<20	<0.01	<10	<10	3	<10	45			
E856244		22	<20	<0.01	<10	<10	8	<10	50			
E856245		21	<20	<0.01	<10	<10	7	<10	49			
E856246		27	<20	<0.01	<10	<10	6	<10	42			
E856247		24	<20	<0.01	<10	<10	8	<10	62			
E856248		29	<20	<0.01	<10	<10	7	<10	55			
E856249		30	<20	<0.01	<10	<10	7	<10	55			
E856250		76	<20	<0.01	<10	<10	<1	<10	2			
E856251		18	<20	<0.01	<10	<10	6	<10	38			
E856252		20	<20	0.01	<10	<10	9	<10	52			
E856253		28	<20	<0.01	<10	<10	9	<10	53			
E856254		26	<20	<0.01	<10	<10	8	<10	50			
E856255		15	<20	<0.01	<10	<10	4	<10	20			
E856256		19	<20	<0.01	<10	<10	5	<10	26			
E856257		25	<20	<0.01	<10	<10	5	<10	24			
E856258		12	<20	<0.01	<10	<10	7	<10	27			
E856259		14	<20	<0.01	<10	<10	11	<10	42			
E856260		20	<20	0.01	<10	<10	13	<10	66			
E856261		30	<20	<0.01	<10	<10	6	<10	38			
E856262		31	<20	<0.01	<10	<10	6	<10	39			
E856263		41	<20	<0.01	<10	<10	8	<10	47			
E856264		43	<20	<0.01	<10	<10	11	<10	63			
E856265		36	<20	<0.01	<10	<10	14	<10	63			
E856266		37	<20	<0.01	<10	<10	6	<10	39			
E856267		17	<20	<0.01	<10	<10	3	<10	15			
E856268		18	<20	<0.01	<10	<10	15	<10	86			
E856269		18	<20	<0.01	<10	<10	16	<10	88			
E856270		115	<20	<0.01	<10	<10	6	20	>10000	1.970	3.66	NSS
E856271		24	<20	<0.01	<10	<10	9	<10	61			
E856272		21	<20	<0.01	<10	<10	6	<10	29			
E856273		13	<20	<0.01	<10	<10	7	<10	47			
E856274		19	<20	<0.01	<10	<10	13	<10	86			
E856275		19	<20	<0.01	<10	<10	6	<10	43			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E856276		5.25	<0.005		<0.2	2.06	16	<10	60	0.5	<2	0.22	<0.5	16	23	33
E856277		4.08	<0.005		<0.2	1.69	3	<10	40	<0.5	<2	0.36	<0.5	12	19	38
E856278		3.97	0.005		<0.2	0.73	4	<10	40	<0.5	<2	0.44	<0.5	7	9	14
E856279		5.03	<0.005		<0.2	0.89	4	<10	40	<0.5	<2	0.40	<0.5	9	21	17
E856280		4.11	<0.005		<0.2	0.85	2	<10	40	<0.5	<2	0.39	<0.5	7	14	15
E856281		2.16	<0.005		<0.2	1.66	<2	<10	50	<0.5	<2	0.47	<0.5	11	22	24
E856282		2.46	<0.005		<0.2	1.41	5	<10	50	<0.5	<2	0.38	<0.5	13	23	24
E856283		5.12	<0.005		<0.2	1.62	6	<10	50	<0.5	<2	0.43	<0.5	16	18	58
E856284		5.06	<0.005		<0.2	1.56	10	<10	50	<0.5	<2	0.28	<0.5	17	19	44

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E856276		3.98	10	<1	0.22	20	0.81	653	<1	0.03	34	420	6	0.03	<2	2
E856277		3.89	10	<1	0.17	10	0.78	740	<1	0.03	31	800	10	0.06	<2	1
E856278		1.94	<10	<1	0.16	10	0.41	401	<1	0.02	12	500	9	<0.01	<2	1
E856279		2.47	<10	<1	0.15	10	0.48	532	<1	0.02	17	200	18	<0.01	<2	1
E856280		2.00	<10	<1	0.15	10	0.43	401	<1	0.02	13	220	7	0.01	<2	1
E856281		3.60	10	<1	0.19	10	0.81	850	<1	0.02	25	770	15	0.01	<2	2
E856282		3.43	<10	<1	0.19	10	0.74	928	<1	0.02	24	440	13	0.03	<2	2
E856283		3.66	<10	<1	0.20	10	0.83	928	<1	0.02	35	400	19	0.15	<2	1
E856284		3.69	<10	<1	0.22	10	0.78	1110	<1	0.02	32	260	17	0.07	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E856276		18	<20	<0.01	<10	<10	15	<10	79			
E856277		28	<20	<0.01	<10	<10	10	<10	79			
E856278		31	<20	<0.01	<10	<10	4	<10	35			
E856279		30	<20	<0.01	<10	<10	6	<10	46			
E856280		26	<20	<0.01	<10	<10	6	<10	38			
E856281		38	<20	<0.01	<10	<10	11	<10	68			
E856282		30	<20	<0.01	<10	<10	11	<10	57			
E856283		32	<20	<0.01	<10	<10	10	<10	72			
E856284		23	<20	<0.01	<10	<10	10	<10	66			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 18-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10087540

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

CERTIFICATE WH10094736

Project: ALN10-01

P.O. No.: ALN10-01_13

This report is for 81 GRAB samples submitted to our lab in Whitehorse, YT, Canada on 13-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um
LOG-22d	Sample login - Rcd w/o BarCode dup
SPL-21d	Split sample - duplicate
PUL-31d	Pulverize Split - duplicate
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature: 

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	WEI-21	Au-AA23	Au-GRA21	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu
	Units	kg	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.05	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1
E858005		1.73	<0.005		<0.2	0.44	4	<10	60	<0.5	<2	0.36	<0.5	3	9	5
E858006		1.09	<0.005		<0.2	0.80	3	<10	80	<0.5	<2	0.47	<0.5	6	9	9
E858007		1.03	<0.005		<0.2	1.14	3	<10	80	<0.5	<2	0.68	<0.5	15	13	30
E858008		1.71	<0.005		<0.2	1.46	2	<10	100	<0.5	<2	0.26	<0.5	19	13	42
E858009		<0.02	0.024		<0.2	1.48	2	<10	110	<0.5	<2	0.21	<0.5	18	13	38
E858010		0.11	0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1
E858011		2.15	<0.005		<0.2	1.13	<2	<10	80	<0.5	<2	0.59	<0.5	15	12	26
E858012		2.19	<0.005		<0.2	1.07	2	<10	70	<0.5	<2	0.63	<0.5	14	14	17
E858013		1.86	<0.005		<0.2	1.69	<2	<10	70	<0.5	<2	0.39	<0.5	20	24	21
E858014		2.37	0.005		<0.2	1.33	3	<10	70	<0.5	<2	0.52	<0.5	17	13	38
E858015		1.65	<0.005		<0.2	1.55	<2	<10	50	<0.5	<2	0.66	<0.5	18	17	36
E858016		1.96	<0.005		<0.2	1.74	<2	<10	70	<0.5	<2	0.38	<0.5	19	17	23
E858017		1.50	<0.005		<0.2	1.45	<2	<10	50	<0.5	<2	0.66	<0.5	17	18	35
E858018		1.83	<0.005		<0.2	1.49	<2	<10	80	<0.5	<2	0.29	<0.5	19	14	85
E858019		2.33	<0.005		<0.2	1.36	<2	<10	80	<0.5	<2	0.57	<0.5	17	14	35
E858020		2.00	0.089		0.2	1.27	3	<10	80	<0.5	<2	2.77	<0.5	15	13	111
E858021		1.69	<0.005		0.3	1.16	16	<10	50	<0.5	<2	14.0	<0.5	12	8	22
E858022		0.98	<0.005		0.2	1.22	14	<10	50	<0.5	<2	12.6	<0.5	11	8	20
E858023		3.05	0.005		<0.2	1.40	21	<10	50	<0.5	<2	9.9	<0.5	15	10	29
E858024		2.28	<0.005		0.3	0.33	9	<10	30	<0.5	<2	19.8	<0.5	5	<1	11
E858025		2.84	<0.005		0.2	1.20	4	<10	60	<0.5	<2	6.57	<0.5	9	8	20
E858026		1.46	<0.005		0.2	1.22	8	<10	70	<0.5	<2	3.69	<0.5	11	8	22
E858027		2.22	<0.005		<0.2	0.74	7	<10	60	<0.5	<2	1.04	<0.5	10	6	20
E858028		2.11	0.006		<0.2	1.39	7	<10	80	<0.5	<2	0.82	<0.5	13	11	28
E858029		<0.02	<0.005		0.2	1.32	4	<10	80	<0.5	<2	0.84	<0.5	13	10	24
E858030		0.12	<0.005		<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1
E858031		2.07	<0.005		<0.2	1.52	10	<10	70	<0.5	<2	1.98	<0.5	12	16	26
E858032		1.95	<0.005		<0.2	1.26	9	<10	60	<0.5	<2	2.91	<0.5	11	10	25
E858033		2.12	0.006		7.2	1.17	43	<10	130	<0.5	<2	2.44	<0.5	13	21	37
E858034		2.57	0.006		0.2	1.03	3	<10	50	<0.5	2	3.28	<0.5	8	14	17
E858035		2.09	<0.005		<0.2	1.07	6	<10	50	<0.5	2	1.64	<0.5	9	15	15
E858036		1.54	<0.005		<0.2	0.78	<2	<10	40	<0.5	3	1.79	<0.5	5	14	7
E858037		1.82	<0.005		<0.2	0.61	<2	<10	40	<0.5	2	2.76	<0.5	5	10	4
E858038		1.75	<0.005		0.2	1.16	6	<10	60	<0.5	4	0.98	<0.5	13	17	24
E858039		2.39	<0.005		<0.2	1.09	3	<10	70	<0.5	<2	0.95	<0.5	12	14	20
E858040		2.68	<0.005		<0.2	0.61	2	<10	50	<0.5	3	1.43	<0.5	6	9	8
E858041		1.38	<0.005		<0.2	0.81	4	<10	50	<0.5	2	1.82	<0.5	8	11	13
E858042		1.20	0.005		<0.2	1.48	8	<10	70	<0.5	3	0.52	<0.5	17	16	27
E858043		2.20	<0.005		<0.2	1.09	2	<10	60	<0.5	<2	8.3	<0.5	10	11	20
E858044		1.81	<0.005		<0.2	0.36	5	<10	40	<0.5	2	6.52	<0.5	5	6	5

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E858005		1.00	<10	<1	0.23	20	0.17	159	<1	0.02	4	140	16	0.05	<2	<1
E858006		1.82	<10	<1	0.20	10	0.43	334	<1	0.03	8	340	8	0.06	<2	2
E858007		2.56	<10	<1	0.28	20	0.67	1360	2	0.03	27	280	40	0.11	<2	1
E858008		3.35	<10	<1	0.32	40	0.74	863	<1	0.02	34	290	7	0.01	<2	1
E858009		3.41	<10	<1	0.36	40	0.71	731	<1	0.02	34	290	7	0.01	<2	1
E858010		0.02	<10	<1	<0.01	<10	<0.01	<5	<1	0.01	<1	10	2	0.01	<2	<1
E858011		2.74	<10	<1	0.27	30	0.70	1710	<1	0.03	26	320	9	0.01	<2	1
E858012		2.67	<10	<1	0.25	30	0.70	1445	<1	0.03	24	300	9	0.02	<2	1
E858013		3.28	10	<1	0.25	40	1.02	1190	<1	0.03	32	240	9	0.01	<2	2
E858014		2.55	<10	<1	0.25	30	0.80	1125	<1	0.02	26	200	8	0.01	4	1
E858015		2.90	<10	<1	0.19	30	0.92	1975	1	0.03	29	240	21	0.01	2	1
E858016		3.45	10	<1	0.25	40	0.96	1025	<1	0.02	31	250	4	0.01	<2	1
E858017		2.62	<10	<1	0.19	30	0.85	1505	<1	0.03	24	230	23	0.02	<2	1
E858018		2.98	<10	<1	0.27	30	0.88	569	<1	0.02	31	310	24	0.01	<2	1
E858019		3.11	<10	1	0.26	30	0.82	626	<1	0.02	38	330	4	<0.01	<2	1
E858020		2.93	<10	<1	0.26	20	0.74	908	<1	0.02	30	340	20	0.02	<2	1
E858021		1.98	<10	<1	0.21	20	0.61	1865	<1	0.02	15	370	19	0.05	<2	2
E858022		2.10	<10	<1	0.22	20	0.61	1655	<1	0.02	15	360	19	0.06	<2	2
E858023		2.75	<10	<1	0.22	20	0.74	908	1	0.02	21	370	18	0.33	<2	2
E858024		1.39	<10	<1	0.13	10	0.28	1345	2	0.02	8	300	28	0.8	<2	1
E858025		2.88	<10	<1	0.25	20	0.54	642	<1	0.02	17	300	15	0.46	<2	1
E858026		2.30	<10	<1	0.28	20	0.52	618	<1	0.02	16	260	8	0.05	<2	1
E858027		1.51	<10	<1	0.24	20	0.33	208	<1	0.01	15	300	40	0.10	<2	1
E858028		2.76	<10	<1	0.32	20	0.61	198	<1	0.02	25	440	43	0.14	<2	1
E858029		2.62	<10	<1	0.31	20	0.59	204	<1	0.02	24	390	66	0.13	<2	1
E858030		0.02	<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	2	<0.01	<2	<1
E858031		3.03	<10	<1	0.29	30	0.65	429	<1	0.02	20	250	7	0.05	<2	1
E858032		2.43	<10	<1	0.24	20	0.60	554	<1	0.02	17	240	13	0.06	<2	1
E858033		2.52	<10	<1	0.26	20	0.56	573	3	0.02	20	230	23	0.06	<2	1
E858034		2.21	<10	<1	0.19	20	0.46	566	<1	0.03	16	170	14	0.02	<2	1
E858035		2.29	<10	<1	0.21	20	0.54	451	<1	0.02	18	150	16	0.07	<2	1
E858036		1.65	<10	<1	0.17	20	0.39	490	<1	0.03	9	130	12	0.05	<2	1
E858037		1.63	<10	<1	0.15	20	0.35	535	<1	0.02	7	170	14	0.05	<2	1
E858038		2.85	<10	1	0.24	20	0.62	337	<1	0.02	22	200	145	0.17	7	1
E858039		2.75	<10	<1	0.29	20	0.61	314	<1	0.03	22	290	21	0.13	<2	1
E858040		1.78	<10	<1	0.19	20	0.38	331	<1	0.02	10	170	18	0.07	2	1
E858041		2.11	<10	<1	0.23	20	0.44	408	<1	0.03	13	270	19	0.09	<2	1
E858042		3.61	<10	1	0.26	30	0.70	189	<1	0.01	24	380	20	0.15	<2	1
E858043		2.41	<10	<1	0.27	20	0.53	983	<1	0.02	15	350	23	0.11	<2	2
E858044		1.14	<10	<1	0.13	10	0.28	665	<1	0.02	6	260	13	0.05	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E858005		51	<20	0.02	<10	<10	3	<10	16			
E858006		38	<20	0.04	<10	<10	22	<10	34			
E858007		42	20	0.02	<10	<10	8	<10	63			
E858008		31	20	0.04	<10	<10	12	<10	78			
E858009		27	20	0.05	<10	<10	12	<10	76			
E858010		1	<20	<0.01	<10	<10	<1	<10	2			
E858011		60	20	0.04	<10	<10	15	<10	67			
E858012		66	<20	0.05	<10	<10	11	<10	66			
E858013		43	20	0.03	<10	<10	10	<10	97			
E858014		47	20	0.03	<10	<10	11	<10	75			
E858015		66	20	0.01	<10	<10	13	<10	83			
E858016		37	20	0.01	<10	<10	10	<10	89			
E858017		52	<20	0.01	<10	<10	13	<10	73			
E858018		25	<20	0.04	<10	<10	11	<10	76			
E858019		46	<20	0.05	<10	<10	14	<10	74			
E858020		191	<20	0.06	<10	10	14	<10	64			
E858021		323	20	0.02	<10	<10	7	<10	35			
E858022		291	<20	0.02	<10	<10	7	<10	34			
E858023		290	<20	0.01	<10	<10	8	<10	45			
E858024		712	<20	0.01	<10	<10	2	<10	28			
E858025		317	20	0.01	<10	<10	7	<10	54			
E858026		214	<20	0.02	<10	<10	7	<10	45			
E858027		62	<20	0.01	<10	<10	4	<10	31			
E858028		54	20	0.01	<10	<10	8	<10	57			
E858029		54	20	0.01	<10	<10	7	<10	54			
E858030		1	<20	<0.01	<10	<10	<1	<10	2			
E858031		115	20	0.02	<10	<10	10	<10	54			
E858032		187	<20	0.02	<10	<10	7	<10	48			
E858033		133	<20	0.02	<10	<10	7	20	54			
E858034		196	<20	0.01	<10	<10	7	<10	51			
E858035		99	<20	0.01	<10	<10	7	<10	60			
E858036		107	<20	0.01	<10	<10	5	<10	32			
E858037		172	<20	<0.01	<10	<10	4	<10	30			
E858038		62	<20	<0.01	<10	<10	6	<10	62			
E858039		53	<20	<0.01	<10	<10	7	<10	61			
E858040		77	<20	<0.01	<10	<10	3	<10	35			
E858041		89	<20	<0.01	<10	<10	5	<10	43			
E858042		37	20	<0.01	<10	<10	10	<10	59			
E858043		434	<20	<0.01	<10	<10	7	<10	39			
E858044		308	<20	<0.01	<10	<10	2	<10	15			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E858045		1.82	<0.005		<0.2	0.95	<2	<10	80	<0.5	2	2.23	<0.5	8	9	21
E858046		1.81	<0.005		<0.2	1.09	6	<10	70	<0.5	2	0.49	<0.5	12	12	29
E858047		1.58	<0.005		<0.2	0.77	<2	<10	70	<0.5	3	2.43	<0.5	7	10	14
E858048		2.03	<0.005		<0.2	0.62	<2	<10	50	<0.5	2	2.64	<0.5	7	8	13
E858049		<0.02	<0.005		<0.2	0.64	<2	<10	60	<0.5	2	2.56	<0.5	7	8	13
E858050		0.09	1.625	1.79	>100	0.39	4460	<10	30	<0.5	12	0.83	509	6	56	882
E858051		1.89	<0.005		0.6	0.48	27	<10	60	<0.5	2	5.58	0.9	15	6	26
E858052		2.44	<0.005		0.2	0.85	2	<10	70	<0.5	3	2.27	<0.5	11	9	21
E858053		1.97	0.005		<0.2	0.66	3	<10	50	<0.5	<2	8.1	<0.5	7	8	13
E858054		1.87	<0.005		<0.2	0.70	<2	<10	60	<0.5	2	7.4	<0.5	8	9	16
E858055		1.75	<0.005		<0.2	0.69	<2	<10	50	<0.5	<2	6.6	<0.5	7	10	13
E858056		1.87	<0.005		<0.2	0.64	2	<10	60	<0.5	<2	10.0	<0.5	6	7	14
E858057		2.75	<0.005		<0.2	1.17	3	<10	70	<0.5	2	1.78	<0.5	7	15	17
E858058		2.52	<0.005		0.6	1.23	2	<10	70	<0.5	3	1.42	<0.5	10	15	23
E858059		2.72	0.005		<0.2	1.35	7	<10	80	<0.5	3	0.48	<0.5	15	30	30
E858060		1.75	<0.005		<0.2	0.73	<2	<10	60	<0.5	2	6.08	<0.5	9	9	16
E858061		1.54	<0.005		<0.2	0.28	<2	<10	50	<0.5	<2	20.0	<0.5	4	3	8
E858062		1.29	<0.005		<0.2	0.29	4	<10	50	<0.5	<2	17.8	<0.5	5	3	9
E858063		2.43	<0.005		<0.2	0.55	<2	<10	50	<0.5	3	10.8	<0.5	6	8	11
E858064		3.01	<0.005		<0.2	0.47	<2	<10	40	<0.5	<2	5.47	<0.5	5	13	9
E858065		1.73	<0.005		<0.2	0.80	2	<10	60	<0.5	2	9.1	<0.5	8	9	17
E858066		2.25	<0.005		<0.2	0.63	2	<10	80	<0.5	2	10.4	<0.5	10	7	21
E858067		2.00	0.006		<0.2	0.27	8	<10	90	<0.5	<2	20.7	<0.5	4	2	10
E858068		1.97	0.006		<0.2	0.45	4	<10	80	<0.5	2	8.8	<0.5	11	5	19
E858069		<0.02	<0.005		<0.2	0.52	3	<10	90	<0.5	<2	8.4	<0.5	10	6	19
E858070		0.11	<0.005		<0.2	0.01	<2	<10	10	<0.5	2	0.01	<0.5	<1	<1	13
E858071		1.89	0.005		<0.2	0.42	5	<10	60	<0.5	<2	9.6	<0.5	10	5	18
E858072		1.92	<0.005		<0.2	1.40	3	<10	70	<0.5	<2	3.81	<0.5	10	16	22
E858073		2.03	<0.005		<0.2	1.28	2	<10	70	<0.5	<2	3.75	<0.5	11	16	22
E858074		2.00	<0.005		<0.2	1.46	<2	<10	90	<0.5	<2	1.86	<0.5	11	17	23
E858075		2.53	<0.005		<0.2	1.33	6	<10	70	<0.5	<2	0.54	<0.5	10	17	20
E858076		2.71	<0.005		<0.2	1.30	2	<10	70	<0.5	<2	1.88	<0.5	7	18	16
E858077		2.27	<0.005		<0.2	0.94	4	<10	60	<0.5	<2	11.4	<0.5	7	10	16
E858078		1.44	<0.005		<0.2	0.75	3	<10	70	<0.5	<2	13.3	<0.5	6	9	16
E858079		2.04	<0.005		<0.2	0.12	3	<10	40	<0.5	<2	18.4	<0.5	3	1	5
E858080		1.97	0.005		<0.2	0.41	3	<10	60	<0.5	<2	16.8	<0.5	6	4	15
E858081		1.51	<0.005		0.2	0.13	2	<10	50	<0.5	<2	19.8	<0.5	2	1	5
E858082		1.14	<0.005		0.2	0.13	2	<10	50	<0.5	<2	18.2	<0.5	3	1	6
E858083		2.04	<0.005		0.2	0.19	<2	<10	60	<0.5	<2	19.8	<0.5	4	1	10
E858084		2.68	<0.005		<0.2	0.12	<2	<10	40	<0.5	<2	19.7	<0.5	3	1	4

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E858045		2.15	<10	<1	0.23	20	0.79	375	<1	0.02	17	230	12	0.17	3	1
E858046		2.25	<10	<1	0.22	30	0.55	137	<1	0.01	24	450	15	0.19	3	1
E858047		2.05	<10	1	0.19	10	0.79	392	<1	0.02	14	200	13	0.19	<2	1
E858048		1.83	<10	<1	0.17	20	0.79	403	<1	0.02	13	230	15	0.19	2	1
E858049		1.86	<10	1	0.18	20	0.77	395	<1	0.02	12	230	14	0.19	<2	1
E858050		6.94	<10	2	0.26	10	0.27	377	1	0.03	5	560	>10000	9.7	2610	1
E858051		2.20	<10	1	0.20	10	0.87	591	<1	0.02	20	290	50	0.45	5	1
E858052		2.85	<10	1	0.23	10	0.99	433	<1	0.02	19	290	24	0.48	2	1
E858053		2.18	<10	<1	0.16	10	0.63	513	<1	0.02	15	200	20	0.48	<2	1
E858054		2.13	<10	1	0.20	10	0.54	393	<1	0.02	17	220	16	0.56	<2	1
E858055		2.10	<10	1	0.17	10	0.46	312	<1	0.02	16	270	15	0.64	<2	1
E858056		1.83	<10	<1	0.20	10	0.41	383	<1	0.02	14	270	9	0.49	<2	1
E858057		2.38	<10	1	0.25	20	0.61	185	<1	0.02	17	270	12	0.15	<2	1
E858058		3.00	<10	<1	0.23	20	0.66	178	<1	0.02	24	280	21	0.40	<2	1
E858059		3.08	<10	<1	0.26	20	0.71	124	<1	0.01	36	440	15	0.27	<2	1
E858060		2.22	<10	1	0.22	10	0.45	424	<1	0.02	20	180	20	0.60	<2	1
E858061		1.33	<10	1	0.11	10	0.26	318	<1	0.02	9	320	10	0.6	<2	1
E858062		1.38	<10	<1	0.12	10	0.27	311	<1	0.01	11	310	10	0.6	<2	1
E858063		1.74	<10	<1	0.13	10	0.37	314	<1	0.02	15	340	12	0.59	<2	1
E858064		1.30	<10	1	0.11	10	0.33	245	<1	0.02	10	160	14	0.35	<2	1
E858065		2.01	<10	<1	0.15	10	0.55	355	<1	0.02	17	180	12	0.48	<2	1
E858066		2.15	<10	1	0.15	10	0.63	480	<1	0.02	21	230	16	0.72	<2	1
E858067		1.51	<10	1	0.11	10	0.48	308	<1	0.02	10	520	11	0.9	2	2
E858068		2.46	<10	<1	0.16	10	0.87	454	<1	0.02	20	330	16	0.99	<2	1
E858069		2.51	<10	<1	0.19	10	0.84	443	<1	0.03	21	330	15	0.97	<2	1
E858070		0.03	<10	<1	<0.01	<10	<0.01	<5	2	<0.01	13	10	15	0.01	<2	<1
E858071		2.97	<10	<1	0.14	10	1.07	470	1	0.02	21	300	27	1.01	<2	2
E858072		3.25	<10	<1	0.23	10	0.74	406	1	0.03	21	290	21	0.67	<2	2
E858073		3.10	<10	<1	0.21	10	0.73	246	<1	0.02	22	200	12	0.71	<2	1
E858074		3.00	<10	<1	0.22	20	0.77	205	<1	0.02	23	170	8	0.40	<2	1
E858075		2.60	<10	<1	0.20	20	0.68	137	<1	0.02	22	180	12	0.10	<2	1
E858076		2.71	<10	<1	0.19	20	0.68	208	<1	0.02	19	180	7	0.27	<2	1
E858077		2.41	<10	<1	0.15	10	0.61	220	<1	0.02	17	410	7	0.76	<2	1
E858078		2.31	<10	<1	0.15	10	0.56	358	<1	0.02	15	160	17	0.89	<2	2
E858079		1.08	<10	<1	0.08	<10	0.28	276	<1	0.02	4	170	7	0.7	<2	1
E858080		2.00	<10	<1	0.13	10	0.39	242	<1	0.02	14	350	10	1.02	4	1
E858081		1.04	<10	<1	0.08	<10	0.24	292	<1	0.01	5	170	7	0.8	<2	1
E858082		1.18	<10	<1	0.08	<10	0.30	288	<1	0.01	5	180	7	0.7	<2	1
E858083		1.52	<10	<1	0.11	<10	0.31	291	<1	0.02	7	410	11	1.0	<2	2
E858084		1.05	<10	<1	0.08	<10	0.26	275	<1	0.01	4	220	9	0.7	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E858045		147	<20	<0.01	<10	<10	5	<10	56			
E858046		25	20	<0.01	<10	<10	5	<10	59			
E858047		98	<20	<0.01	<10	<10	4	<10	43			
E858048		86	<20	<0.01	<10	<10	3	<10	33			
E858049		83	<20	<0.01	<10	<10	3	<10	32			
E858050		112	<20	<0.01	<10	<10	5	10	>10000	1.925	3.72	NSS
E858051		216	<20	<0.01	<10	<10	3	<10	198			
E858052		63	<20	<0.01	<10	<10	5	<10	51			
E858053		340	<20	<0.01	<10	<10	4	<10	39			
E858054		285	<20	<0.01	<10	<10	5	<10	43			
E858055		288	<20	<0.01	<10	<10	5	<10	44			
E858056		435	<20	<0.01	<10	<10	4	<10	33			
E858057		99	<20	0.01	<10	<10	7	<10	42			
E858058		73	<20	0.01	<10	<10	8	<10	51			
E858059		26	<20	0.02	<10	<10	12	<10	39			
E858060		307	<20	0.01	<10	<10	5	<10	38			
E858061		740	<20	<0.01	<10	<10	3	<10	24			
E858062		659	<20	<0.01	<10	<10	2	<10	26			
E858063		410	<20	<0.01	<10	<10	4	<10	31			
E858064		197	<20	<0.01	<10	<10	3	<10	25			
E858065		346	<20	<0.01	<10	<10	5	<10	44			
E858066		385	<20	<0.01	<10	<10	4	<10	46			
E858067		669	<20	<0.01	<10	<10	3	<10	31			
E858068		295	<20	<0.01	<10	<10	3	<10	56			
E858069		279	20	<0.01	<10	<10	4	<10	56			
E858070		2	<20	<0.01	<10	<10	<1	<10	12			
E858071		350	<20	<0.01	<10	<10	3	<10	64			
E858072		176	<20	0.01	<10	<10	10	<10	63			
E858073		232	<20	0.01	<10	<10	8	<10	65			
E858074		122	20	0.01	<10	<10	10	<10	66			
E858075		32	<20	0.01	<10	<10	9	<10	58			
E858076		97	<20	0.01	<10	<10	10	<10	57			
E858077		467	20	<0.01	<10	<10	5	<10	55			
E858078		515	<20	<0.01	<10	<10	4	<10	44			
E858079		511	<20	<0.01	<10	<10	<1	<10	16			
E858080		709	<20	<0.01	<10	<10	1	<10	25			
E858081		551	<20	<0.01	<10	<10	<1	<10	18			
E858082		531	<20	<0.01	<10	<10	<1	<10	17			
E858083		709	<20	<0.01	<10	<10	<1	<10	29			
E858084		789	<20	<0.01	<10	<10	<1	<10	16			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E858085		2.54	<0.005		<0.2	0.51	<2	<10	60	<0.5	<2	9.8	<0.5	8	4	20

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E858085		2.89	<10	<1	0.20	10	0.67	443	<1	0.02	18	610	32	1.41	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
E858085		561	20	<0.01	<10	<10	3	<10	46			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 25-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094736

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 4-JUL-2010
Account: EIAALN

CERTIFICATE WH10078771

Project: ALN10-01

P.O. No.: B2010KEY001

This report is for 75 Drill Core samples submitted to our lab in Whitehorse, YT, Canada on 16-JUN-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 4-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078771

Sample Description	Method / Analyte / Units / LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
856001		1.70	<0.005		<0.2	1.18	5	<10	60	<0.5	<2	0.66	<0.5	10	13	34
856002		1.67	0.005		<0.2	1.32	<2	<10	60	<0.5	<2	0.53	<0.5	10	13	34
856003		4.19	0.006		<0.2	1.59	6	<10	70	<0.5	<2	0.26	<0.5	12	18	28
856004		4.30	<0.005		<0.2	2.01	4	<10	70	<0.5	<2	0.33	<0.5	15	22	39
856005		3.86	<0.005		<0.2	1.78	2	<10	70	<0.5	<2	2.07	<0.5	12	18	28
856006		3.84	<0.005		<0.2	1.47	4	<10	60	<0.5	<2	5.38	<0.5	11	20	23
856007		4.03	<0.005		<0.2	1.44	3	<10	50	<0.5	<2	2.77	<0.5	8	22	14
856008		4.52	<0.005		<0.2	0.79	<2	<10	30	<0.5	<2	2.45	<0.5	5	28	18
856009		<0.02	<0.005		<0.2	0.78	<2	<10	30	<0.5	<2	2.38	<0.5	4	15	9
856010		0.07	1.540	1.67	>100	0.40	4610	<10	20	<0.5	8	0.77	534	5	56	893
856011		3.97	<0.005		<0.2	0.72	2	<10	30	<0.5	<2	1.36	<0.5	3	14	13
856012		3.67	<0.005		<0.2	1.47	2	<10	60	<0.5	<2	2.31	<0.5	11	16	23
856013		3.76	<0.005		<0.2	1.47	<2	<10	60	<0.5	<2	2.45	<0.5	13	13	27
856014		3.54	<0.005		<0.2	1.60	<2	<10	60	<0.5	<2	0.83	<0.5	10	15	22
856015		3.15	<0.005		<0.2	1.39	<2	<10	60	<0.5	<2	2.77	<0.5	9	15	19
856016		4.42	<0.005		<0.2	1.15	2	<10	60	<0.5	<2	6.12	<0.5	10	35	32
856017		3.99	<0.005		<0.2	1.38	3	<10	60	<0.5	<2	3.44	<0.5	11	16	24
856018		3.83	<0.005		<0.2	1.31	3	<10	50	<0.5	<2	6.35	<0.5	8	14	21
856019		4.16	<0.005		<0.2	1.26	5	<10	50	<0.5	<2	6.90	<0.5	8	12	21
856020		3.86	<0.005		<0.2	1.20	6	<10	50	<0.5	<2	8.8	<0.5	7	14	22
856021		1.77	<0.005		<0.2	1.78	5	<10	50	<0.5	<2	2.54	<0.5	12	17	36
856022		2.04	<0.005		<0.2	1.93	3	<10	60	<0.5	<2	2.78	<0.5	12	20	30
856023		4.07	<0.005		<0.2	2.22	<2	<10	60	<0.5	<2	0.39	<0.5	14	24	41
856024		4.15	<0.005		<0.2	2.19	4	<10	60	<0.5	<2	0.57	<0.5	11	29	20
856025		3.57	<0.005		<0.2	2.20	7	<10	60	<0.5	<2	0.49	<0.5	16	24	39
856026		4.13	<0.005		<0.2	2.04	<2	<10	60	<0.5	<2	0.57	<0.5	11	23	30
856027		4.39	<0.005		<0.2	1.80	2	<10	60	<0.5	<2	0.56	<0.5	11	19	27
856028		3.93	<0.005		<0.2	2.08	3	<10	80	<0.5	<2	0.43	<0.5	14	25	31
856029		<0.02	<0.005		<0.2	2.12	3	<10	90	<0.5	<2	0.42	<0.5	14	26	30
856030		0.07	0.885		>100	0.56	4590	<10	30	<0.5	6	0.53	100.0	6	54	311
856031		5.42	<0.005		<0.2	1.91	6	<10	60	<0.5	<2	0.51	<0.5	13	20	28
856032		5.95	<0.005		<0.2	1.38	<2	<10	50	<0.5	<2	1.83	<0.5	7	15	19
856033		5.16	<0.005		<0.2	0.63	<2	<10	40	<0.5	<2	6.15	<0.5	5	8	10
856034		5.45	<0.005		<0.2	0.71	<2	<10	60	<0.5	<2	7.0	<0.5	8	8	17
856035		5.31	<0.005		<0.2	0.86	<2	<10	70	<0.5	<2	5.52	<0.5	8	9	14
856036		5.23	<0.005		<0.2	0.72	4	<10	70	<0.5	<2	5.23	<0.5	5	15	7
856037		5.15	<0.005		<0.2	0.67	5	<10	70	<0.5	<2	5.62	<0.5	7	10	17
856038		5.25	<0.005		<0.2	0.62	3	<10	60	<0.5	<2	13.5	<0.5	6	7	15
856039		5.38	<0.005		<0.2	0.92	4	<10	90	<0.5	<2	1.38	<0.5	8	12	14
856040		3.95	<0.005		<0.2	0.75	4	<10	90	<0.5	<2	1.75	<0.5	7	10	12

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 4-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078771

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
856001		2.54	<10	<1	0.21	20	0.46	575	<1	0.01	23	230	31	0.09	<2	1
856002		2.80	<10	<1	0.21	30	0.52	605	<1	0.01	23	260	21	0.10	<2	1
856003		3.11	<10	1	0.22	20	0.60	463	<1	0.02	25	170	32	0.10	<2	1
856004		3.86	<10	<1	0.21	20	0.80	693	<1	0.02	34	150	25	0.22	<2	1
856005		3.18	<10	<1	0.23	20	0.71	452	<1	0.02	30	590	12	0.22	<2	1
856006		2.63	<10	<1	0.20	10	0.65	599	<1	0.02	25	290	17	0.18	<2	2
856007		2.57	<10	<1	0.18	10	0.61	489	<1	0.03	23	190	15	0.11	<2	2
856008		1.58	<10	<1	0.10	10	0.33	487	<1	0.02	13	90	11	0.08	<2	1
856009		1.51	<10	<1	0.10	10	0.31	476	<1	0.03	10	80	9	0.08	<2	1
856010		6.44	<10	3	0.25	10	0.25	372	<1	0.02	5	570	>10000	>10.0	2660	1
856011		1.39	<10	<1	0.11	10	0.28	259	<1	0.03	15	110	19	0.04	<2	1
856012		2.85	<10	<1	0.23	20	0.63	502	<1	0.02	24	440	31	0.41	<2	1
856013		2.92	<10	<1	0.25	20	0.64	518	<1	0.02	23	250	35	0.50	<2	1
856014		2.92	<10	1	0.24	20	0.70	257	<1	0.01	23	310	16	0.34	<2	1
856015		2.53	<10	<1	0.21	20	0.61	373	<1	0.02	18	230	23	0.29	<2	1
856016		2.28	<10	<1	0.17	10	0.53	615	<1	0.02	25	190	16	0.20	<2	2
856017		2.56	<10	1	0.20	10	0.57	310	<1	0.03	24	390	13	0.28	<2	1
856018		2.50	<10	1	0.18	10	0.60	509	<1	0.03	19	320	19	0.21	<2	1
856019		2.52	<10	<1	0.18	10	0.62	760	<1	0.03	20	350	18	0.17	<2	2
856020		2.61	<10	1	0.21	10	0.68	867	<1	0.04	18	230	29	0.17	<2	2
856021		3.37	<10	<1	0.20	10	0.78	594	<1	0.03	28	370	23	0.24	<2	1
856022		3.48	<10	<1	0.25	20	0.81	608	<1	0.04	28	510	22	0.27	<2	2
856023		4.15	10	<1	0.22	20	0.91	553	<1	0.03	36	310	32	0.28	<2	2
856024		3.77	10	<1	0.21	30	0.85	699	<1	0.04	29	280	49	0.09	<2	2
856025		3.88	10	<1	0.22	30	0.85	504	<1	0.03	34	840	14	0.25	<2	2
856026		3.75	10	<1	0.24	20	0.84	663	<1	0.04	28	250	20	0.26	<2	2
856027		3.28	<10	<1	0.21	20	0.75	645	<1	0.03	25	180	18	0.18	<2	1
856028		3.67	10	<1	0.25	20	0.78	456	<1	0.03	29	680	15	0.42	<2	1
856029		3.73	10	1	0.26	20	0.79	451	<1	0.03	31	710	18	0.44	<2	1
856030		5.75	<10	1	0.32	10	0.10	290	1	0.04	5	670	4940	8.1	1720	1
856031		3.53	10	<1	0.20	20	0.76	454	<1	0.03	30	350	22	0.19	<2	1
856032		2.65	<10	<1	0.19	10	0.60	624	<1	0.03	19	250	17	0.26	<2	1
856033		1.46	<10	<1	0.15	10	0.33	446	<1	0.02	13	200	23	0.26	<2	1
856034		2.19	<10	<1	0.20	<10	0.43	404	<1	0.02	20	310	18	0.83	<2	1
856035		2.03	<10	<1	0.21	10	0.45	342	<1	0.02	18	250	18	0.46	<2	1
856036		1.47	<10	<1	0.19	10	0.32	282	<1	0.02	12	110	17	0.24	<2	1
856037		1.78	<10	<1	0.22	10	0.33	371	1	0.03	17	180	32	0.56	<2	1
856038		1.52	<10	<1	0.27	<10	0.39	496	<1	0.02	13	340	16	0.41	<2	1
856039		1.79	<10	<1	0.36	20	0.38	225	<1	0.02	14	150	18	0.21	<2	1
856040		1.52	<10	<1	0.35	20	0.30	343	<1	0.02	13	140	17	0.22	<2	1

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 4-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078771

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
856001		38	<20	0.01	<10	<10	8	<10	56			
856002		27	<20	0.01	<10	<10	8	<10	58			
856003		17	<20	0.01	<10	<10	10	<10	72			
856004		20	<20	0.01	<10	<10	12	<10	94			
856005		136	<20	<0.01	<10	<10	11	<10	76			
856006		274	<20	<0.01	<10	<10	11	<10	64			
856007		121	<20	<0.01	<10	<10	12	<10	64			
856008		110	<20	<0.01	<10	<10	10	<10	35			
856009		110	<20	<0.01	<10	<10	7	<10	33			
856010		112	<20	<0.01	<10	<10	5	10	>10000	1.995	3.76	NSS
856011		59	<20	0.01	<10	<10	7	<10	37			
856012		101	<20	<0.01	<10	<10	10	<10	69			
856013		109	20	<0.01	<10	<10	8	<10	67			
856014		40	<20	<0.01	<10	<10	9	<10	75			
856015		134	<20	<0.01	<10	<10	10	<10	56			
856016		263	<20	0.01	<10	<10	13	<10	54			
856017		164	<20	<0.01	<10	<10	9	<10	64			
856018		336	<20	<0.01	<10	<10	8	<10	59			
856019		407	<20	<0.01	<10	<10	8	<10	56			
856020		561	<20	<0.01	<10	<10	8	<10	72			
856021		117	<20	<0.01	<10	<10	11	<10	80			
856022		136	<20	<0.01	<10	<10	12	<10	81			
856023		22	<20	<0.01	<10	<10	15	<10	102			
856024		46	<20	<0.01	<10	<10	17	<10	91			
856025		31	<20	<0.01	<10	<10	14	<10	94			
856026		40	<20	<0.01	<10	<10	13	<10	88			
856027		29	<20	<0.01	<10	<10	11	<10	80			
856028		27	<20	<0.01	<10	<10	14	<10	92			
856029		27	<20	<0.01	<10	<10	14	<10	91			
856030		135	<20	<0.01	<10	<10	6	10	>10000		1.335	147
856031		26	<20	<0.01	<10	<10	13	<10	90			
856032		111	<20	<0.01	<10	<10	9	<10	72			
856033		350	<20	<0.01	<10	<10	4	<10	36			
856034		355	<20	<0.01	<10	<10	4	<10	50			
856035		266	<20	<0.01	<10	<10	5	<10	46			
856036		272	<20	<0.01	<10	<10	5	<10	32			
856037		246	<20	<0.01	<10	<10	5	<10	45			
856038		590	<20	0.01	<10	<10	4	<10	74			
856039		88	20	0.02	<10	<10	7	<10	42			
856040		124	<20	0.02	<10	<10	5	<10	34			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 4-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078771

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
856041		1.77	<0.005		<0.2	0.73	<2	<10	100	<0.5	<2	0.69	<0.5	9	9	15
856042		1.82	<0.005		<0.2	0.84	<2	<10	100	<0.5	<2	0.58	<0.5	9	9	15
856043		5.60	<0.005		<0.2	0.56	5	<10	90	<0.5	<2	1.10	<0.5	7	8	11
856044		5.44	<0.005		<0.2	0.70	7	<10	110	<0.5	<2	0.74	<0.5	9	9	12
856045		5.21	<0.005		<0.2	0.63	12	<10	120	<0.5	<2	0.71	<0.5	8	8	13
856046		5.53	<0.005		<0.2	0.56	47	<10	110	<0.5	<2	0.72	<0.5	8	8	13
856047		5.46	<0.005		<0.2	0.95	4	<10	110	<0.5	<2	1.07	<0.5	7	10	14
856048		5.44	<0.005		<0.2	0.99	7	<10	80	<0.5	<2	1.01	<0.5	9	11	18
856049		<0.02	<0.005		<0.2	1.05	5	<10	90	<0.5	<2	1.01	<0.5	9	11	18
856050		0.09	<0.005		0.3	0.01	<2	<10	10	<0.5	<2	0.15	<0.5	<1	<1	1
856051		4.95	<0.005		<0.2	0.94	28	<10	70	<0.5	<2	1.45	<0.5	10	10	15
856052		5.13	<0.005		<0.2	0.60	24	<10	70	<0.5	<2	1.50	<0.5	9	8	19
856053		4.32	0.048		<0.2	0.55	767	<10	70	<0.5	<2	2.52	<0.5	13	6	30
856054		4.53	0.011		<0.2	0.48	70	<10	100	<0.5	<2	0.21	<0.5	17	7	28
856055		4.32	0.051		0.8	0.35	727	<10	60	<0.5	<2	1.93	<0.5	7	6	13
856056		4.38	0.029		0.3	0.41	535	<10	80	<0.5	<2	1.01	<0.5	10	7	33
856057		3.76	<0.005		<0.2	0.59	26	<10	70	<0.5	<2	0.40	<0.5	7	20	14
856058		3.85	<0.005		<0.2	0.57	22	<10	60	<0.5	<2	0.80	<0.5	5	13	13
856059		4.36	<0.005		<0.2	1.08	19	<10	80	<0.5	<2	0.74	<0.5	14	16	30
856060		4.62	<0.005		<0.2	0.44	16	<10	90	<0.5	<2	0.48	<0.5	9	11	20
856061		1.47	<0.005		<0.2	0.90	10	<10	70	<0.5	<2	1.18	<0.5	9	15	21
856062		1.85	<0.005		<0.2	0.97	8	<10	70	<0.5	<2	1.60	<0.5	9	14	24
856063		4.26	<0.005		<0.2	0.73	6	<10	60	<0.5	<2	2.85	<0.5	8	14	17
856064		4.15	<0.005		<0.2	1.32	8	<10	80	<0.5	<2	1.29	<0.5	12	14	27
856065		4.84	0.005		<0.2	0.47	39	<10	60	<0.5	<2	0.93	<0.5	9	10	24
856066		4.31	0.154		<0.2	0.78	1110	<10	70	<0.5	<2	1.43	<0.5	13	12	28
856067		4.12	0.006		0.5	0.74	126	<10	70	<0.5	<2	3.13	<0.5	9	13	25
856068		3.63	<0.005		0.6	0.58	43	<10	70	<0.5	<2	4.40	<0.5	6	8	18
856069		<0.02	<0.005		0.3	0.59	43	<10	70	<0.5	<2	4.26	<0.5	5	9	17
856070		0.07	0.878		>100	0.56	4880	<10	20	<0.5	5	0.58	105.0	7	56	312
856071		2.57	0.385		7.8	0.44	3690	<10	60	<0.5	<2	4.17	<0.5	6	6	34
856072		3.04	0.009		<0.2	0.39	66	<10	60	<0.5	<2	0.51	<0.5	12	6	32
856073		3.89	<0.005		0.2	0.74	19	<10	60	<0.5	<2	0.27	<0.5	16	11	45
856074		4.49	<0.005		0.9	0.85	8	<10	50	0.5	<2	0.20	<0.5	19	10	49
856075		4.34	<0.005		<0.2	0.80	14	<10	60	0.5	<2	0.29	<0.5	18	10	45

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 4-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078771

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
856041		1.72	<10	<1	0.38	20	0.32	208	<1	0.02	16	160	26	0.26	<2	1
856042		1.84	<10	<1	0.41	20	0.34	184	<1	0.02	17	180	23	0.29	<2	1
856043		1.25	<10	<1	0.35	20	0.21	253	<1	0.02	12	200	18	0.26	<2	1
856044		1.27	<10	<1	0.38	20	0.25	173	<1	0.02	13	270	25	0.10	<2	1
856045		1.21	<10	<1	0.41	30	0.21	223	<1	0.01	13	500	19	0.09	<2	1
856046		1.49	<10	<1	0.37	30	0.25	236	<1	0.01	14	170	20	0.12	<2	1
856047		1.88	<10	<1	0.37	30	0.38	301	<1	0.02	14	270	22	0.14	<2	1
856048		2.37	<10	<1	0.30	20	0.46	319	<1	0.02	18	250	23	0.31	<2	1
856049		2.39	<10	<1	0.33	20	0.46	318	<1	0.02	18	240	22	0.31	<2	1
856050		0.02	<10	<1	<0.01	<10	0.08	<5	<1	<0.01	1	10	3	<0.01	<2	<1
856051		2.88	<10	<1	0.23	20	0.60	527	<1	0.02	17	220	30	0.21	5	1
856052		1.99	<10	<1	0.25	20	0.68	510	<1	0.01	17	240	28	0.13	7	1
856053		3.15	<10	<1	0.27	10	1.37	677	1	0.01	26	440	35	0.75	19	1
856054		4.07	<10	<1	0.31	20	0.80	343	<1	0.01	37	290	14	0.20	18	2
856055		2.04	<10	<1	0.23	10	0.68	571	<1	0.01	13	210	20	0.30	18	1
856056		3.29	<10	<1	0.21	20	0.78	669	<1	0.02	23	320	19	0.25	28	2
856057		1.92	<10	<1	0.14	20	0.35	300	<1	0.02	14	140	13	0.05	7	1
856058		1.69	<10	<1	0.14	20	0.34	410	<1	0.03	11	230	22	0.07	6	1
856059		2.61	<10	<1	0.23	20	0.58	496	<1	0.02	26	260	35	0.12	7	1
856060		2.16	<10	<1	0.18	20	0.40	368	<1	0.02	18	180	25	0.11	18	1
856061		2.52	<10	<1	0.20	20	0.58	431	<1	0.02	20	270	19	0.13	5	1
856062		2.65	<10	<1	0.21	20	0.60	522	<1	0.02	21	240	20	0.13	4	1
856063		1.78	<10	<1	0.20	20	0.42	565	<1	0.02	14	290	21	0.21	<2	1
856064		3.34	<10	<1	0.27	20	0.70	356	<1	0.01	28	530	31	0.38	2	1
856065		2.46	<10	<1	0.21	20	0.57	376	<1	0.02	22	370	21	0.12	18	2
856066		3.05	<10	<1	0.25	20	0.75	327	<1	0.02	30	640	22	0.23	15	2
856067		2.28	<10	<1	0.21	20	0.48	501	<1	0.02	19	470	14	0.15	13	2
856068		2.15	<10	1	0.21	20	0.56	510	<1	0.03	15	140	20	0.13	9	2
856069		2.14	<10	<1	0.21	20	0.56	495	<1	0.03	15	150	18	0.13	10	2
856070		6.10	<10	1	0.33	10	0.10	309	1	0.04	5	710	5230	8.1	1690	1
856071		2.57	<10	<1	0.20	10	0.57	640	<1	0.02	17	190	31	0.89	24	2
856072		3.12	<10	<1	0.20	10	0.60	396	<1	0.02	26	280	34	0.68	24	2
856073		3.43	<10	<1	0.20	10	0.63	329	<1	0.02	36	230	26	0.78	9	1
856074		4.16	<10	<1	0.18	10	0.76	360	<1	0.03	41	470	15	1.03	4	2
856075		3.85	<10	<1	0.20	10	0.71	354	<1	0.02	37	370	18	0.97	6	2

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 4-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078771

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
856041		55	<20	0.01	<10	<10	5	<10	36			
856042		44	20	0.01	<10	<10	6	<10	38			
856043		92	<20	0.01	<10	<10	4	<10	35			
856044		73	20	0.02	<10	<10	5	<10	35			
856045		63	20	0.01	<10	<10	4	<10	28			
856046		72	20	<0.01	<10	<10	3	<10	32			
856047		91	20	0.01	<10	<10	6	<10	48			
856048		71	20	<0.01	<10	<10	6	<10	60			
856049		72	20	<0.01	<10	<10	6	<10	59			
856050		8	<20	<0.01	<10	<10	<1	<10	3			
856051		71	<20	<0.01	<10	<10	6	<10	68			
856052		58	<20	<0.01	<10	<10	3	<10	44			
856053		93	20	<0.01	<10	<10	4	<10	100			
856054		13	<20	<0.01	<10	<10	6	<10	116			
856055		70	<20	<0.01	<10	<10	2	<10	35			
856056		53	<20	<0.01	<10	<10	4	<10	63			
856057		26	<20	<0.01	<10	<10	5	<10	38			
856058		50	<20	<0.01	<10	<10	5	<10	34			
856059		54	<20	<0.01	<10	<10	8	<10	65			
856060		38	<20	<0.01	<10	<10	5	<10	64			
856061		91	<20	<0.01	<10	<10	7	<10	56			
856062		121	<20	<0.01	<10	<10	8	<10	59			
856063		219	<20	<0.01	<10	<10	5	<10	36			
856064		90	20	<0.01	<10	<10	8	<10	73			
856065		67	<20	<0.01	<10	<10	5	<10	51			
856066		107	<20	<0.01	<10	<10	7	<10	74			
856067		198	<20	<0.01	<10	<10	6	<10	50			
856068		266	<20	<0.01	<10	<10	4	<10	53			
856069		261	<20	<0.01	<10	<10	4	<10	52			
856070		140	<20	<0.01	<10	<10	6	<10	>10000		1.245	151
856071		251	<20	<0.01	<10	<10	3	40	82			
856072		35	<20	<0.01	<10	<10	4	<10	57			
856073		22	<20	<0.01	<10	<10	6	<10	80			
856074		22	<20	<0.01	<10	<10	7	10	95			
856075		28	<20	<0.01	<10	<10	8	<10	76			

***** See Appendix Page for comments regarding this certificate *****

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 4-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078771

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non-sufficient sample.

ALS Canada Ltd.

2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

CERTIFICATE WH10102709

Project: ALN10-01

P.O. No.: ALN10-01_25

This report is for 1 Rock sample submitted to our lab in Whitehorse, YT, Canada on 27-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102709

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
E855583		1.59	1.855	2.04	1.0	0.19	6440	<10	70	<0.5	<2	0.03	<0.5	2	12	6

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102709

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E855583		1.83	<10	1	0.13	<10	0.01	136	1	0.02	7	60	12	0.33	7	<1

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 11-AUG-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10102709

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	1	20	0.01	10	10	1	10	2
E855583		4	<20	<0.01	<10	<10	2	<10	10

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 26-JUL-2010
Account: EIAALN

CERTIFICATE WH10095960

Project: ALN10-01

P.O. No.: ALN10-10_14

This report is for 6 Rock samples submitted to our lab in Whitehorse, YT, Canada on 14-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 26-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095960

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
E885518		1.71	<0.005	<0.2	0.16	3	<10	20	<0.5	<2	0.01	<0.5	<1	13	14	1.32
E855576		2.42	0.006	0.2	0.43	21	<10	80	<0.5	<2	0.03	<0.5	8	14	42	3.57
E855577		1.97	<0.005	<0.2	0.21	<2	<10	90	<0.5	<2	0.02	<0.5	1	16	14	0.84
E855578		1.50	<0.005	<0.2	0.36	3	<10	10	<0.5	<2	0.05	<0.5	3	17	3	1.15
E855579		2.30	0.006	0.4	0.81	11	<10	150	<0.5	<2	0.01	<0.5	17	16	159	5.03
E855580		1.54	<0.005	<0.2	0.90	<2	<10	270	<0.5	<2	0.05	<0.5	3	24	8	1.91

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 26-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095960

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E885518		<10	<1	0.01	<10	0.04	65	1	<0.01	4	160	2	<0.01	<2	<1	3
E855576		<10	<1	0.19	10	0.05	145	13	<0.01	25	250	34	<0.01	17	1	8
E855577		<10	<1	0.03	<10	0.08	100	1	<0.01	4	180	<2	<0.01	<2	1	6
E855578		<10	<1	0.02	10	0.13	520	1	0.01	4	200	2	<0.01	<2	1	4
E855579		<10	1	0.05	10	0.17	209	1	0.01	72	640	19	0.01	3	2	13
E855580		<10	<1	0.08	10	0.29	209	1	0.01	9	320	<2	<0.01	<2	1	10

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 26-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095960

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
E885518		<20	<0.01	<10	<10	10	<10	11
E855576		<20	<0.01	<10	<10	18	<10	39
E855577		<20	<0.01	<10	<10	4	<10	12
E855578		<20	<0.01	<10	<10	5	<10	15
E855579		<20	<0.01	<10	<10	16	<10	190
E855580		<20	<0.01	<10	<10	20	<10	35

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-JUL-2010
Account: EIAALN

CERTIFICATE WH10095044

Project: ALN10-01

P.O. No.: ALN10-01_19

This report is for 2 GRAB samples submitted to our lab in Whitehorse, YT, Canada on 16-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095044

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
855581		0.33	0.956	17.5	0.04	2170	<10	30	<0.5	<2	0.02	0.8	1	7	13	0.50
855582		0.68	<0.005	0.6	0.30	24	<10	120	<0.5	<2	0.27	<0.5	4	6	11	1.68

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095044

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
855581		<10	1	0.02	<10	0.01	49	1	<0.01	1	10	68	0.44	8080	<1	3
855582		<10	<1	0.18	50	0.05	365	1	0.03	1	260	11	0.02	29	2	11

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10095044

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
855581		<20	<0.01	<10	<10	1	10	5
855582		20	0.01	<10	<10	8	<10	24

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 23-JUL-2010
Account: EIAALN

CERTIFICATE WH10094737

Project: ALN10-01

P.O. No.: ALN10-01_11

This report is for 19 GRAB samples submitted to our lab in Whitehorse, YT, Canada on 13-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 23-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094737

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
E855519		2.44	<0.005	<0.2	0.34	<2	<10	30	<0.5	<2	0.40	<0.5	2	9	2	1.07
E855520		2.56	<0.005	<0.2	0.42	<2	<10	20	<0.5	<2	0.12	<0.5	9	13	12	1.08
E855521		1.31	<0.005	<0.2	0.26	<2	<10	20	<0.5	<2	0.05	<0.5	5	10	3	0.80
E855522		0.77	<0.005	<0.2	0.34	2	<10	50	<0.5	2	0.04	<0.5	2	13	2	0.99
E855561		1.16	<0.005	0.3	0.21	4	<10	10	<0.5	<2	0.28	<0.5	5	13	<1	0.90
E855562		2.24	<0.005	0.3	0.27	3	<10	10	<0.5	2	0.22	<0.5	6	13	1	1.06
E855563		1.91	<0.005	<0.2	1.66	<2	<10	60	<0.5	<2	1.56	<0.5	9	17	18	2.95
E855564		2.38	0.005	<0.2	0.04	<2	<10	20	<0.5	<2	0.02	<0.5	1	12	5	0.55
E855565		1.24	<0.005	<0.2	0.09	2	<10	40	<0.5	<2	0.02	<0.5	<1	10	3	0.51
E855566		1.58	<0.005	<0.2	0.49	<2	<10	100	<0.5	<2	0.22	<0.5	4	11	8	1.79
E855567		2.32	<0.005	<0.2	0.12	<2	<10	20	<0.5	<2	0.11	<0.5	2	15	<1	0.94
E855568		1.94	<0.005	<0.2	0.06	<2	<10	10	<0.5	<2	0.48	<0.5	<1	13	<1	0.74
E855569		0.53	<0.005	<0.2	0.11	3	<10	20	<0.5	2	0.22	<0.5	1	14	4	0.81
E855570		2.69	<0.005	<0.2	0.57	<2	<10	50	<0.5	2	0.03	<0.5	1	14	3	1.76
E855571		0.70	<0.005	<0.2	0.32	<2	<10	<10	<0.5	<2	0.01	<0.5	1	12	7	1.13
E855572		2.09	<0.005	<0.2	0.01	<2	<10	<10	<0.5	2	<0.01	<0.5	<1	12	3	0.58
E855573		2.14	<0.005	0.2	0.29	<2	<10	20	<0.5	<2	0.35	<0.5	5	16	5	0.94
E855574		1.23	<0.005	<0.2	0.61	3	<10	30	<0.5	2	0.06	<0.5	6	14	6	1.56
E855575		1.76	<0.005	<0.2	0.60	<2	<10	50	<0.5	2	0.41	<0.5	4	16	8	1.44

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 23-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094737

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E855519		<10	<1	0.08	10	0.16	394	<1	0.01	3	130	123	0.01	<2	1	11
E855520		<10	<1	0.08	10	0.17	261	<1	0.02	11	200	41	0.01	<2	<1	12
E855521		<10	<1	0.06	10	0.10	307	<1	0.01	7	160	9	<0.01	<2	1	3
E855522		<10	<1	0.06	10	0.14	100	<1	0.02	6	100	4	0.01	<2	<1	3
E855561		<10	<1	0.04	10	0.07	375	<1	0.02	6	250	54	<0.01	<2	1	8
E855562		<10	<1	0.03	10	0.10	341	<1	0.02	8	170	59	<0.01	<2	1	6
E855563		<10	<1	0.20	20	0.65	492	<1	0.03	19	400	41	0.11	<2	1	104
E855564		<10	<1	0.01	<10	<0.01	62	<1	0.01	2	70	<2	<0.01	<2	<1	4
E855565		<10	<1	0.02	<10	0.02	68	<1	0.01	3	80	<2	<0.01	<2	<1	4
E855566		<10	<1	0.12	10	0.15	811	<1	0.01	10	440	15	0.01	<2	1	10
E855567		<10	<1	0.02	<10	0.06	588	<1	<0.01	1	270	6	<0.01	<2	1	5
E855568		<10	<1	0.01	<10	0.03	366	<1	0.02	1	80	6	<0.01	<2	<1	4
E855569		<10	<1	0.01	<10	0.05	294	<1	0.02	2	170	32	0.01	<2	<1	3
E855570		<10	<1	0.04	10	0.27	94	<1	0.01	6	340	<2	0.01	<2	1	5
E855571		<10	<1	0.01	<10	0.12	104	<1	0.02	1	50	15	0.01	<2	<1	2
E855572		<10	<1	<0.01	<10	<0.01	43	<1	<0.01	1	40	<2	<0.01	<2	<1	1
E855573		<10	<1	0.04	10	0.12	374	<1	0.02	6	650	17	0.01	<2	1	11
E855574		<10	<1	0.06	10	0.24	219	<1	0.02	15	240	<2	<0.01	<2	1	6
E855575		<10	<1	0.07	10	0.24	233	<1	0.04	9	320	13	0.02	<2	1	20

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 23-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10094737

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
E855519		<20	<0.01	<10	<10	2	<10	12
E855520		<20	<0.01	<10	<10	3	<10	21
E855521		<20	<0.01	<10	<10	2	<10	10
E855522		<20	<0.01	<10	<10	3	<10	12
E855561		<20	<0.01	<10	<10	1	<10	19
E855562		<20	<0.01	<10	<10	1	<10	24
E855563		<20	<0.01	<10	<10	10	<10	61
E855564		<20	<0.01	<10	<10	1	<10	5
E855565		<20	<0.01	<10	<10	1	<10	7
E855566		<20	0.01	<10	<10	4	<10	31
E855567		<20	<0.01	<10	<10	1	<10	6
E855568		<20	<0.01	<10	<10	<1	<10	3
E855569		<20	<0.01	<10	<10	1	<10	7
E855570		<20	<0.01	<10	<10	20	<10	32
E855571		<20	<0.01	<10	<10	3	<10	11
E855572		<20	<0.01	<10	<10	<1	<10	<2
E855573		<20	<0.01	<10	<10	2	<10	15
E855574		<20	<0.01	<10	<10	6	<10	30
E855575		<20	<0.01	<10	<10	5	<10	21

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

CERTIFICATE WH10091333

Project: ALN10-01

P.O. No.: ALN10-01_7

This report is for 6 Rock samples submitted to our lab in Whitehorse, YT, Canada on 7-JUL-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091333

Sample Description	Method	WEI-21	Au-AA23	Au-GRA21	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu
	Units	kg	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.005	0.05	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1
E855515		0.72	0.015		<0.2	0.93	6	<10	420	<0.5	<2	0.02	<0.5	6	12	67
E855516		0.76	<0.005		<0.2	0.28	8	<10	60	<0.5	<2	0.01	<0.5	8	6	5
E855517		0.96	0.006		0.4	3.03	32	<10	400	<0.5	<2	0.03	<0.5	3	103	42
E855607		2.64	<0.005		<0.2	0.35	<2	<10	100	<0.5	<2	0.04	<0.5	4	21	36
E855608		1.00	1.930	2.30	0.6	0.32	14	<10	10	<0.5	<2	0.04	<0.5	<1	25	51
E855609		1.00	0.008		0.7	0.02	8	<10	20	<0.5	<2	8.2	<0.5	1	8	4

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091333

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
E855515		1.89	<10	<1	0.12	10	0.41	133	<1	0.01	21	130	<2	0.02	<2	1
E855516		1.87	<10	<1	0.11	10	0.05	286	<1	<0.01	16	130	5	0.02	<2	1
E855517		5.85	10	<1	0.08	10	1.86	414	4	0.02	31	850	10	0.17	5	8
E855607		1.45	<10	<1	0.07	<10	0.10	344	<1	<0.01	16	150	4	0.01	<2	2
E855608		30.1	10	1	0.01	<10	0.04	1605	<1	<0.01	16	4170	2	0.04	33	4
E855609		0.62	<10	<1	0.01	<10	4.77	311	<1	0.01	2	100	72	0.02	103	<1

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 21-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10091333

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	1	20	0.01	10	10	1	10	2
E855515		8	<20	<0.01	<10	<10	16	10	49
E855516		6	<20	<0.01	<10	<10	3	<10	45
E855517		18	<20	<0.01	<10	<10	147	<10	123
E855607		4	<20	0.01	<10	<10	23	<10	22
E855608		8	<20	0.01	<10	<10	47	<10	64
E855609		88	<20	<0.01	<10	<10	2	<10	10

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUN-2010
Account: EIAALN

CERTIFICATE WH10078772

Project: ALN10-01

P.O. No.: B2010KEY002R

This report is for 8 GRAB samples submitted to our lab in Whitehorse, YT, Canada on 16-JUN-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUN-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078772

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
855559		1.68	<0.005		<0.2	0.52	<2	<10	30	<0.5	<2	0.32	<0.5	6	10	11
855560		3.65	0.041		<0.2	0.24	<2	<10	80	<0.5	4	0.02	<0.5	1	7	3
855719		0.47	0.008		<0.2	0.38	7	<10	130	<0.5	4	0.03	<0.5	5	22	23
855720		1.43	0.009		0.2	0.40	3	<10	70	<0.5	4	0.02	<0.5	5	11	40
855721		2.46	<0.005		<0.2	0.03	<2	<10	30	<0.5	4	2.45	<0.5	1	15	1
855604		1.10	<0.005		<0.2	0.11	<2	<10	60	<0.5	4	0.65	<0.5	1	14	9
855605		1.77	0.885		0.4	0.11	>10000	<10	80	<0.5	3	0.72	<0.5	3	19	3
855606		1.45	2.58	2.71	0.4	0.17	>10000	<10	90	<0.5	4	1.00	14.4	9	18	2

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUN-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078772

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
855559		1.71	<10	<1	0.06	<10	0.28	495	<1	0.01	20	150	36	0.05	<2	1
855560		0.91	<10	1	0.14	20	0.02	122	<1	0.06	<1	60	16	0.01	<2	1
855719		1.26	<10	<1	0.03	<10	0.10	163	<1	0.02	28	230	7	0.02	<2	1
855720		1.17	<10	<1	0.01	<10	0.02	323	<1	0.08	47	80	8	0.02	<2	2
855721		0.72	<10	<1	0.01	<10	1.14	215	<1	0.02	<1	70	<2	0.01	<2	<1
855604		0.93	<10	<1	0.03	<10	0.02	509	<1	0.06	2	250	<2	0.01	<2	<1
855605		1.76	<10	<1	0.06	<10	0.24	432	<1	0.02	5	110	18	0.67	30	1
855606		4.07	<10	1	0.10	<10	0.37	527	<1	0.03	18	230	13	2.20	64	1

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-JUN-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078772

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	1	20	0.01	10	10	1	10	2
855559		17	<20	<0.01	<10	<10	3	<10	35
855560		4	<20	<0.01	<10	<10	1	<10	21
855719		4	<20	<0.01	<10	<10	10	<10	36
855720		12	<20	<0.01	<10	<10	4	<10	55
855721		54	<20	<0.01	<10	<10	1	<10	7
855604		7	<20	<0.01	<10	<10	<1	<10	6
855605		37	<20	<0.01	<10	<10	1	<10	65
855606		74	<20	<0.01	<10	<10	2	<10	2060

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-JUL-2010
Account: EIAALN

CERTIFICATE WH10078770

Project: ALN10-01

P.O. No.: B2010KEY001R

This report is for 43 GRAB samples submitted to our lab in Whitehorse, YT, Canada on 16-JUN-2010.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	CAM BARTSCH	BERT JEFFRIES

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
Au-GRA21	Au 30g FA-GRAV finish	WST-SIM
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE
Ag-GRA21	Ag 30g FA-GRAV finish	WST-SIM

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: CAM BARTSCH
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078770

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
855501		1.61	0.009		<0.2	0.84	8	<10	60	<0.5	<2	0.08	<0.5	11	22	28
855502		1.23	0.009		<0.2	0.60	2	<10	70	<0.5	<2	0.05	<0.5	5	21	4
855503		1.06	0.009		0.3	0.33	2	<10	60	<0.5	<2	0.20	2.3	12	19	6
855504		1.14	0.008		0.2	0.12	17	<10	490	<0.5	2	11.2	2.2	5	9	10
855505		0.88	0.010		<0.2	0.39	71	<10	60	<0.5	<2	2.80	<0.5	12	16	9
855506		1.64	0.519		39.2	0.10	5740	<10	50	<0.5	2	0.13	42.1	2	18	98
855507		1.33	0.099		0.5	0.12	562	<10	60	<0.5	<2	0.03	2.4	<1	20	10
855508		0.94	2.19	2.15	>100	0.08	>10000	<10	30	<0.5	<2	0.01	244	1	13	519
855509		1.09	0.182		1.1	0.03	1305	<10	40	<0.5	<2	0.01	1.3	<1	15	4
855510		1.29	0.187		2.4	0.10	2210	<10	70	<0.5	<2	0.01	2.3	1	17	7
855511		0.97	0.516		0.7	0.03	5270	<10	20	<0.5	<2	<0.01	0.5	<1	18	5
855512		0.97	0.121		6.1	0.04	679	<10	20	<0.5	<2	0.02	0.6	<1	23	27
855513		1.10	0.647		0.8	0.20	9520	<10	90	<0.5	<2	0.10	2.4	1	14	4
855514		1.09	0.013		1.0	0.66	25	<10	1420	<0.5	<2	<0.01	0.5	<1	13	68
855701		0.52	1.620	1.61	<0.2	0.09	7420	<10	30	<0.5	<2	0.61	<0.5	2	13	6
855702		0.58	0.010		1.6	0.72	23	<10	80	<0.5	3	0.04	<0.5	5	27	125
855703		0.58	0.286		1.2	0.04	2670	<10	30	<0.5	<2	<0.01	<0.5	<1	19	4
855704		0.21	0.102		2.7	0.32	55	<10	30	1.4	<2	0.01	9.2	10	4	29
855705		1.14	0.010		<0.2	0.61	12	<10	50	<0.5	<2	0.17	1.4	5	15	16
855706		0.68	0.010		<0.2	0.92	18	<10	20	<0.5	<2	14.6	<0.5	6	17	3
855707		1.38	0.053		0.2	0.55	7	<10	220	<0.5	<2	0.08	<0.5	4	17	45
855708		1.19	0.008		<0.2	0.89	4	<10	40	<0.5	<2	0.29	<0.5	6	20	16
855709		0.66	0.006		<0.2	0.07	2	<10	20	<0.5	<2	0.40	<0.5	3	15	12
855710		1.40	<0.005		<0.2	0.25	2	<10	30	<0.5	<2	0.18	<0.5	2	20	6
855711		0.70	<0.005		<0.2	0.24	2	<10	150	<0.5	<2	0.04	<0.5	2	13	41
855712		0.96	<0.005		<0.2	0.02	<2	<10	20	<0.5	<2	<0.01	<0.5	<1	18	4
855713		0.85	0.006		0.2	0.25	2	<10	100	<0.5	<2	0.04	<0.5	13	19	35
855714		0.52	0.120		0.3	0.61	2	<10	150	<0.5	<2	0.01	<0.5	1	18	52
855715		0.53	0.030		0.5	1.32	49	<10	800	<0.5	3	11.1	4.2	15	10	878
855716		1.22	0.021		<0.2	0.21	<2	<10	70	<0.5	<2	0.05	<0.5	3	16	24
855717		1.46	0.005		0.3	0.80	160	<10	120	<0.5	<2	0.13	<0.5	13	11	26
855718		1.82	0.008		0.5	0.56	29	<10	240	<0.5	<2	0.03	<0.5	7	15	49
855601		1.05	0.007		<0.2	0.40	80	<10	60	<0.5	<2	0.54	<0.5	6	13	16
855602		0.95	0.222		0.2	0.33	1300	<10	80	<0.5	<2	3.55	<0.5	3	8	3
855603		1.45	0.007		0.5	0.11	15	<10	30	<0.5	<2	0.01	<0.5	1	8	3
855551		Not Recvd														
855552		1.51	<0.005		<0.2	1.18	7	<10	80	<0.5	<2	0.49	<0.5	5	19	8
855553		Not Recvd														
855554		2.35	<0.005		<0.2	0.16	12	<10	30	<0.5	<2	0.13	<0.5	2	24	8
855555		1.54	<0.005		<0.2	0.09	2	<10	20	<0.5	2	0.19	<0.5	3	16	3

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078770

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
855501		2.16	<10	<1	0.11	10	0.16	289	1	0.02	26	140	5	0.09	2	1
855502		2.67	<10	<1	0.07	10	0.26	518	1	0.01	13	110	6	<0.01	<2	1
855503		1.77	<10	<1	0.03	<10	0.14	708	1	0.01	41	110	389	<0.01	<2	1
855504		0.95	<10	<1	0.03	10	6.54	8470	8	0.03	35	140	13	<0.01	11	1
855505		2.72	<10	<1	0.08	<10	0.95	1620	1	0.02	33	80	12	<0.01	<2	4
855506		1.81	<10	1	0.03	<10	0.06	213	1	0.01	5	10	5550	1.03	6760	<1
855507		1.05	<10	<1	0.05	<10	0.01	114	1	0.01	2	10	30	0.01	55	<1
855508		3.18	<10	7	0.02	<10	<0.01	132	<1	0.01	3	10	>10000	4.77	>10000	<1
855509		0.93	<10	<1	0.01	<10	<0.01	84	1	0.01	<1	10	118	0.02	126	<1
855510		1.47	<10	<1	0.04	<10	<0.01	142	1	0.01	1	10	447	0.12	389	<1
855511		1.28	<10	<1	0.01	<10	<0.01	96	1	0.01	<1	10	56	0.16	61	<1
855512		0.93	<10	<1	0.02	<10	0.01	109	<1	0.01	<1	30	118	0.01	68	<1
855513		1.99	<10	<1	0.11	<10	0.04	153	1	0.01	3	50	127	0.64	109	1
855514		19.0	<10	<1	0.09	<10	0.03	84	19	0.03	7	1050	10	0.14	2	1
855701		1.80	<10	<1	0.04	<10	0.26	308	1	0.01	3	20	4	0.36	14	<1
855702		2.81	<10	<1	0.05	10	0.24	557	1	0.07	18	160	267	0.02	<2	2
855703		1.02	<10	<1	0.02	<10	<0.01	90	1	0.01	1	10	164	0.12	155	<1
855704		20.9	<10	<1	0.03	<10	0.02	284	11	0.01	46	100	48	0.08	7	1
855705		1.85	<10	<1	0.12	10	0.16	321	1	0.02	17	290	7	<0.01	<2	1
855706		2.32	<10	<1	0.03	10	0.92	695	1	0.02	32	740	16	0.01	2	4
855707		1.80	<10	<1	0.12	10	0.21	290	1	0.02	13	160	21	0.01	2	1
855708		2.10	<10	<1	0.04	10	0.68	254	1	0.02	20	180	6	0.01	<2	1
855709		1.20	<10	<1	0.02	<10	0.09	210	1	0.01	7	110	4	0.10	8	<1
855710		1.39	<10	<1	0.03	<10	0.20	191	1	0.01	9	170	12	0.02	<2	1
855711		1.36	<10	<1	0.02	<10	0.02	202	1	0.01	22	280	6	<0.01	<2	1
855712		0.92	<10	<1	<0.01	<10	<0.01	138	1	0.01	1	20	2	<0.01	<2	<1
855713		1.46	<10	<1	0.03	<10	0.08	7630	1	0.02	31	180	6	<0.01	<2	1
855714		2.26	<10	1	0.05	<10	0.24	247	1	0.01	9	120	4	<0.01	<2	1
855715		4.84	<10	<1	0.18	20	0.13	15700	1	0.04	114	>10000	81	<0.01	<2	4
855716		1.01	<10	<1	0.02	<10	0.07	964	1	0.01	8	260	6	<0.01	<2	<1
855717		2.14	<10	<1	0.02	<10	0.14	416	1	0.05	42	210	17	0.01	3	1
855718		2.00	<10	<1	0.08	10	0.13	475	1	0.05	33	160	30	<0.01	22	1
855601		3.13	<10	<1	0.15	10	0.32	643	1	0.03	16	280	6	0.02	10	1
855602		3.33	<10	<1	0.25	10	0.11	767	1	0.02	6	160	56	0.15	56	1
855603		2.26	<10	<1	0.06	10	0.01	66	1	0.01	2	20	40	1.80	<2	<1
855551																
855552		2.36	<10	<1	0.21	20	0.43	275	<1	0.04	13	110	10	<0.01	<2	1
855553																
855554		1.05	<10	<1	0.09	10	0.01	468	<1	0.06	7	150	20	<0.01	2	<1
855555		1.14	<10	<1	0.04	<10	0.04	302	<1	0.01	7	150	7	<0.01	<2	<1

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078770

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
855501		8	<20	<0.01	<10	<10	7	<10	24			
855502		9	<20	<0.01	<10	<10	7	<10	38			
855503		5	<20	0.01	<10	<10	3	<10	81			
855504		789	<20	<0.01	<10	<10	32	<10	274			
855505		106	<20	<0.01	<10	<10	4	<10	39			
855506		15	<20	<0.01	<10	<10	1	<10	3820			
855507		8	<20	<0.01	<10	<10	2	<10	36			
855508		7	<20	<0.01	<10	<10	1	10	>10000	3.33	1.890	191
855509		1	<20	<0.01	<10	<10	1	<10	56			
855510		4	<20	<0.01	<10	<10	1	<10	137			
855511		<1	<20	<0.01	<10	<10	1	<10	14			
855512		2	<20	<0.01	<10	<10	1	<10	33			
855513		18	<20	<0.01	<10	<10	2	<10	195			
855514		4	<20	<0.01	<10	<10	49	<10	414			
855701		86	<20	<0.01	<10	<10	2	<10	22			
855702		5	<20	<0.01	<10	<10	10	<10	31			
855703		<1	<20	<0.01	<10	<10	1	<10	10			
855704		1	<20	<0.01	<10	10	3	<10	617			
855705		7	<20	<0.01	<10	<10	7	<10	56			
855706		1820	<20	<0.01	<10	<10	17	<10	83			
855707		11	<20	<0.01	<10	<10	11	<10	46			
855708		26	<20	<0.01	<10	<10	7	<10	26			
855709		4	<20	<0.01	<10	<10	1	<10	2			
855710		9	<20	<0.01	<10	<10	3	<10	13			
855711		14	<20	<0.01	<10	<10	3	<10	29			
855712		<1	<20	<0.01	<10	<10	1	<10	2			
855713		43	<20	<0.01	<10	<10	7	<10	53			
855714		9	<20	<0.01	<10	<10	13	<10	36			
855715		2660	<20	<0.01	<10	<10	17	<10	201			
855716		12	<20	<0.01	<10	<10	3	<10	8			
855717		24	<20	<0.01	<10	<10	4	<10	47			
855718		14	<20	<0.01	<10	<10	11	<10	63			
855601		32	<20	<0.01	<10	<10	4	<10	42			
855602		87	<20	<0.01	<10	<10	2	<10	72			
855603		3	<20	<0.01	<10	<10	2	<10	<2			
855551												
855552		35	<20	<0.01	<10	<10	8	<10	45			
855553												
855554		8	<20	0.01	<10	<10	2	<10	10			
855555		5	<20	<0.01	<10	<10	1	<10	10			

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078770

Sample Description	Method Analyte Units LOR	WEI-21 Recvd Wt. kg 0.02	Au-AA23 Au ppm 0.005	Au-GRA21 Au ppm 0.05	ME-ICP41 Ag ppm 0.2	ME-ICP41 Al % 0.01	ME-ICP41 As ppm 2	ME-ICP41 B ppm 10	ME-ICP41 Ba ppm 10	ME-ICP41 Be ppm 0.5	ME-ICP41 Bi ppm 2	ME-ICP41 Ca % 0.01	ME-ICP41 Cd ppm 0.5	ME-ICP41 Co ppm 1	ME-ICP41 Cr ppm 1	ME-ICP41 Cu ppm 1
855556		0.61	<0.005		<0.2	0.06	<2	<10	150	<0.5	2	0.01	<0.5	<1	15	3
855557		1.83	<0.005		<0.2	1.29	4	<10	60	<0.5	2	0.15	<0.5	11	33	25
855558		1.90	<0.005		<0.2	0.15	<2	<10	<10	<0.5	<2	0.03	<0.5	2	18	4

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078770

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Fe	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc
	Units	%	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm
	LOR	0.01	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1
855556		0.81	<10	<1	0.02	<10	<0.01	91	<1	0.01	1	90	2	<0.01	<2	<1
855557		2.95	<10	<1	0.17	20	0.52	455	<1	0.06	26	480	28	0.02	<2	2
855558		0.98	<10	<1	0.03	<10	0.05	118	<1	0.04	3	140	7	<0.01	<2	<1

ALS Chemex
EXCELLENCE IN ANALYTICAL CHEMISTRY
ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 5-JUL-2010
Account: EIAALN

Project: ALN10-01

CERTIFICATE OF ANALYSIS WH10078770

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46	Ag-GRA21
	Analyte	Sr	Th	Ti	Tl	U	V	W	Zn	Pb	Zn	Ag
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	LOR	1	20	0.01	10	10	1	10	2	0.001	0.001	5
855556		<1	<20	<0.01	<10	<10	7	<10	2			
855557		8	<20	<0.01	<10	<10	15	<10	65			
855558		1	<20	<0.01	<10	<10	1	<10	8			

Aldrin Resource Corporation

2010 GEOLOGICAL, GEOCHEMICAL AND DIAMOND DRILLING REPORT ON THE KEYSTONE PROJECT

Volume II
Appendices F – I, Maps

Located in the Mayo Lake Area
Mayo Mining District
NTS 105M/14
63°50’ N Latitude; 135°15’ W Longitude

-prepared for-

ALDRIN RESOURCE CORPORATION
Suite 2020-401 West Georgia Street
Vancouver, British Columbia, Canada, V6B 5A1

-prepared by-

David Swanton, M.Sc.
EQUITY EXPLORATION CONSULTANTS LTD.
Suite 200, 900 West Hastings Street
Vancouver, British Columbia, Canada, V6C 1E5

December 7, 2010

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Submitted By: Johnathan More
Receiving Lab: Canada-Whitehorse
Received: July 28, 2010
Report Date: August 23, 2010
Page: 1 of 14

CERTIFICATE OF ANALYSIS WHI10000187.1

CLIENT JOB INFORMATION

Project: KYS
Shipment ID: KYS2
P.O. Number
Number of Samples: 369

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	369	Dry at 60C sieve 100g to -80 mesh			WHI
Dry at 60C	369	Dry at 60C			WHI
1DX2	369	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Aldrin Resources
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5
Canada

CC: Shawn Ryan
Isaac Fage
Bert Jeffries

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 111679	Soil		0.9	27.4	21.6	88	0.2	25.8	9.1	333	2.66	180.2	1.1	2.7	3.0	10	0.3	1.2	0.3	23	0.12	0.047
KYS 110996	Soil		1.9	41.1	30.2	110	0.2	38.9	14.5	443	3.16	21.3	1.9	2.9	13.2	22	0.7	3.1	0.3	10	0.31	0.046
KYS 111681	Soil		8.8	79.6	39.5	232	0.5	84.8	19.4	656	4.42	41.0	3.8	6.2	12.8	39	2.5	2.8	0.5	13	0.24	0.082
KYS 111682	Soil		0.7	43.1	34.3	112	0.1	40.9	18.0	808	3.75	18.6	1.7	1.7	11.8	14	0.2	0.6	0.5	6	0.17	0.044
KYS 111674	Soil		2.5	61.9	23.4	87	0.7	35.8	7.3	259	3.16	24.6	1.8	6.7	4.2	24	0.2	2.1	0.5	33	0.08	0.102
KYS 111680	Soil		0.7	40.3	31.0	118	0.2	43.5	16.5	732	3.11	66.4	1.5	5.8	10.0	16	0.5	0.9	0.3	14	0.26	0.055
KYS 109575	Soil		3.1	57.3	24.4	68	0.6	15.5	3.0	140	3.61	16.1	1.0	7.3	1.3	16	0.2	2.0	0.5	48	0.02	0.108
KYS 109571	Soil		2.7	41.6	19.6	83	0.4	22.0	5.5	225	3.69	11.9	0.9	10.6	4.4	9	0.2	1.7	0.4	54	0.04	0.058
KYS 109725	Soil		1.1	33.5	18.4	74	<0.1	25.3	10.1	382	2.89	38.3	1.3	3.2	4.1	7	0.1	1.4	0.2	28	0.05	0.041
KYS 109574	Soil		2.9	70.7	27.3	80	0.7	22.1	4.1	139	3.84	16.4	1.3	8.5	2.7	18	0.4	3.2	0.5	33	0.02	0.099
KYS 109586	Soil		0.5	49.9	20.6	109	0.2	55.2	20.9	796	3.93	11.1	1.1	2.2	11.9	24	0.4	1.3	0.2	11	0.47	0.045
KYS 109975	Soil		0.9	60.4	25.0	101	0.1	63.0	45.4	888	3.61	21.5	2.3	2.5	3.5	12	0.2	0.8	0.4	29	0.08	0.065
KYS 110938	Soil		0.6	33.8	26.6	93	<0.1	24.9	13.1	362	2.96	9.9	1.3	2.3	13.7	8	<0.1	0.5	0.4	7	0.08	0.039
KYS 109973	Soil		0.9	28.3	20.3	78	<0.1	27.4	14.4	601	2.76	14.1	1.5	3.2	1.7	9	0.2	0.9	0.2	32	0.07	0.053
KYS 111721	Soil		0.7	31.5	33.3	59	<0.1	27.0	15.3	887	3.30	47.2	1.0	1.5	5.3	113	0.1	0.7	0.4	11	2.11	0.077
KYS 111719	Soil		0.7	33.3	23.7	92	<0.1	39.2	15.4	432	3.03	25.6	1.6	7.9	10.9	20	0.1	0.8	0.3	19	0.25	0.047
KYS 111718	Soil		0.8	36.5	23.8	83	<0.1	36.5	15.1	584	3.49	26.7	1.2	1.8	9.3	18	0.1	1.0	0.3	14	0.25	0.051
KYS 111713	Soil		2.0	49.9	11.4	93	0.2	41.0	11.7	328	2.82	42.0	1.4	8.8	4.3	16	0.5	1.4	0.2	39	0.13	0.070
KYS 111720	Soil		0.8	43.2	29.6	93	0.1	32.2	14.7	609	3.28	85.6	2.1	5.3	10.6	39	0.1	0.8	0.4	15	0.58	0.056
KYS 109980	Soil		1.0	27.7	18.9	60	<0.1	22.2	8.4	258	3.39	78.7	0.9	1.3	2.8	9	0.1	1.3	0.3	44	0.06	0.043
KYS 109979	Soil		1.0	35.8	24.7	68	0.2	26.9	12.9	498	3.58	16.5	1.6	1.9	3.4	9	0.1	0.5	0.4	37	0.07	0.045
KYS 111714	Soil		1.9	44.3	14.0	88	0.1	37.2	12.9	416	3.20	44.6	1.6	3.8	2.3	14	0.2	1.4	0.3	58	0.12	0.082
KYS 111717	Soil		0.9	39.4	25.4	83	<0.1	38.5	15.8	643	3.81	28.2	1.3	2.0	9.5	20	0.1	1.1	0.3	16	0.29	0.057
KYS 112136	Soil		0.9	21.4	12.9	81	<0.1	25.8	11.8	529	2.90	18.6	1.3	2.2	3.4	14	0.3	0.9	0.2	33	0.13	0.058
KYS 112139	Soil		1.2	34.8	14.0	70	<0.1	22.6	8.0	262	2.75	12.4	1.7	3.3	5.0	20	0.2	1.3	0.3	33	0.10	0.062
KYS 112138	Soil		1.0	30.1	14.0	100	<0.1	30.9	11.4	379	2.66	14.2	1.3	1.5	7.4	13	0.7	2.1	0.2	30	0.14	0.060
KYS 112135	Soil		1.1	34.5	12.8	66	<0.1	26.0	9.4	306	2.44	18.1	1.4	7.8	5.7	14	0.2	1.7	0.2	37	0.13	0.061
KYS 112131	Soil		2.0	38.0	22.2	66	0.3	20.1	7.0	264	3.16	14.0	1.7	8.7	3.3	17	0.4	1.5	0.4	23	0.02	0.072
KYS 112134	Soil		1.0	32.8	15.4	67	<0.1	30.1	12.8	427	2.85	32.2	1.3	8.5	6.6	10	0.2	1.6	0.2	38	0.07	0.038
KYS 112137	Soil		4.4	35.2	12.2	99	1.0	19.2	5.5	345	2.00	10.7	2.3	5.4	5.0	21	0.6	2.5	0.2	35	0.17	0.078

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 111679	Soil	13	14	0.24	73	0.012	1	0.75	0.003	0.03	0.1	0.03	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 110996	Soil	22	17	0.47	511	0.001	2	1.05	0.003	0.09	<0.1	0.04	1.4	<0.1	<0.05	3	0.6	<0.2
KYS 111681	Soil	9	8	0.21	90	0.004	1	0.88	0.005	0.07	<0.1	0.20	2.2	0.2	0.10	2	1.6	<0.2
KYS 111682	Soil	16	10	0.38	39	0.003	2	0.77	0.004	0.06	<0.1	0.03	1.7	<0.1	<0.05	2	<0.5	<0.2
KYS 111674	Soil	16	24	0.29	68	0.011	<1	1.13	0.006	0.03	<0.1	0.11	1.8	<0.1	<0.05	4	1.8	0.3
KYS 111680	Soil	16	14	0.39	79	0.008	1	0.97	0.004	0.05	<0.1	0.03	2.0	<0.1	<0.05	2	0.6	<0.2
KYS 109575	Soil	9	21	0.13	295	0.005	<1	1.05	0.009	0.05	<0.1	0.10	1.3	<0.1	0.07	5	2.2	<0.2
KYS 109571	Soil	19	28	0.35	110	0.025	<1	1.32	0.005	0.04	0.1	0.09	1.6	<0.1	<0.05	6	1.5	0.2
KYS 109725	Soil	18	21	0.46	75	0.025	<1	1.42	0.005	0.04	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 109574	Soil	10	23	0.20	259	0.002	<1	1.22	0.010	0.05	<0.1	0.12	2.1	<0.1	0.06	4	2.6	<0.2
KYS 109586	Soil	18	26	0.54	100	0.003	1	1.20	0.006	0.10	<0.1	0.03	2.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109975	Soil	17	24	0.57	60	0.023	1	1.65	0.005	0.04	0.1	0.02	1.5	<0.1	<0.05	5	<0.5	0.3
KYS 110938	Soil	19	15	0.50	49	0.002	2	1.15	0.003	0.07	<0.1	0.02	1.0	<0.1	<0.05	3	<0.5	0.2
KYS 109973	Soil	15	21	0.42	68	0.022	<1	1.28	0.004	0.04	0.1	0.03	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 111721	Soil	12	10	0.24	106	0.004	1	0.92	0.004	0.07	<0.1	0.05	1.7	<0.1	0.09	2	<0.5	<0.2
KYS 111719	Soil	26	17	0.43	84	0.010	1	1.13	0.004	0.09	0.1	0.02	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 111718	Soil	24	26	0.54	88	0.003	1	1.26	0.003	0.07	<0.1	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 111713	Soil	21	34	0.49	107	0.020	<1	1.27	0.007	0.04	0.1	0.03	2.0	<0.1	<0.05	4	1.4	<0.2
KYS 111720	Soil	19	17	0.48	104	0.005	2	1.30	0.005	0.10	<0.1	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109980	Soil	15	23	0.41	62	0.035	1	1.11	0.003	0.05	0.2	0.05	1.4	<0.1	<0.05	5	<0.5	<0.2
KYS 109979	Soil	17	25	0.54	73	0.019	1	1.67	0.006	0.05	0.1	0.05	1.4	<0.1	<0.05	6	0.6	<0.2
KYS 111714	Soil	18	36	0.55	161	0.033	2	1.86	0.007	0.05	0.2	0.04	2.7	0.1	<0.05	6	0.7	<0.2
KYS 111717	Soil	24	30	0.58	104	0.003	1	1.42	0.005	0.07	<0.1	0.02	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 112136	Soil	17	24	0.46	171	0.025	1	1.34	0.006	0.05	<0.1	0.02	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 112139	Soil	22	23	0.44	136	0.027	<1	1.33	0.006	0.04	0.1	0.04	2.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112138	Soil	24	20	0.44	117	0.035	<1	1.12	0.006	0.05	0.2	0.02	2.1	<0.1	<0.05	3	<0.5	<0.2
KYS 112135	Soil	19	23	0.42	127	0.040	1	1.13	0.008	0.04	0.1	0.04	2.7	<0.1	<0.05	3	<0.5	<0.2
KYS 112131	Soil	17	20	0.28	81	0.006	<1	1.01	0.009	0.03	<0.1	0.07	1.4	<0.1	<0.05	3	0.8	<0.2
KYS 112134	Soil	19	26	0.45	131	0.037	2	1.60	0.007	0.05	0.2	0.04	2.7	<0.1	<0.05	4	<0.5	<0.2
KYS 112137	Soil	23	18	0.40	94	0.022	1	0.94	0.007	0.04	0.2	0.09	1.6	<0.1	<0.05	3	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112132	Soil	0.9	33.5	17.4	83	<0.1	29.4	13.4	356	2.75	10.9	1.1	4.7	6.9	7	0.3	3.9	0.2	27	0.05	0.034
KYS 112133	Soil	1.1	29.7	15.3	71	<0.1	29.0	13.0	482	2.68	10.9	1.1	9.4	7.7	12	0.2	1.1	0.2	39	0.11	0.049
KYS 110000	Soil	1.1	38.9	22.2	75	<0.1	30.7	16.0	607	3.11	13.8	1.6	2.8	7.5	12	0.1	0.9	0.3	44	0.07	0.046
KYS 112005	Soil	2.8	69.1	26.1	73	0.4	22.8	4.9	323	4.49	14.1	1.0	11.0	2.9	14	0.1	1.7	0.5	51	0.04	0.083
KYS 112010	Soil	3.4	83.4	29.2	208	0.6	66.2	26.3	1236	4.90	18.2	2.2	17.9	5.1	20	2.6	2.6	0.6	35	0.05	0.080
KYS 111560	Soil	2.8	57.4	42.3	152	0.3	49.3	19.0	990	4.27	32.9	2.2	3.6	4.8	17	0.9	1.7	0.6	37	0.15	0.102
KYS 109940	Soil	0.9	49.2	29.4	104	0.1	38.9	15.8	524	3.40	82.7	2.0	7.4	10.2	51	0.3	2.2	0.3	10	0.73	0.045
KYS 109947	Soil	0.4	26.4	22.6	64	<0.1	21.4	11.3	325	2.82	10.5	0.9	1.1	13.3	16	<0.1	0.9	0.3	9	0.19	0.043
KYS 109948	Soil	0.5	43.3	24.5	83	<0.1	29.5	14.7	377	3.19	12.0	1.6	2.2	16.0	16	<0.1	0.8	0.4	10	0.20	0.042
KYS 109944	Soil	0.8	47.7	33.8	127	<0.1	36.0	19.6	806	4.88	17.8	1.1	0.6	19.0	11	<0.1	0.7	0.7	20	0.13	0.050
KYS 111548	Soil	5.9	142.6	40.3	328	0.5	128.3	44.4	1039	5.32	87.3	3.2	6.2	11.8	36	2.4	2.2	0.5	50	0.46	0.120
KYS 111549	Soil	1.2	89.6	83.3	245	0.2	87.8	47.7	1434	5.48	28.5	1.8	2.3	18.2	13	0.6	1.5	0.7	11	0.17	0.057
KYS 111550	Soil	1.1	121.2	63.4	252	0.3	96.1	36.9	1415	5.72	32.7	2.5	2.5	19.4	22	1.3	0.8	0.7	9	0.33	0.067
KYS 109941	Soil	0.6	61.7	47.4	159	<0.1	53.3	19.1	522	3.44	36.4	2.2	4.6	17.0	32	0.2	9.1	0.3	10	0.41	0.055
KYS 109942	Soil	1.0	41.7	35.8	109	0.1	36.0	22.0	585	3.93	23.2	1.1	0.7	18.7	10	0.2	2.0	0.4	11	0.09	0.043
KYS 111551	Soil	1.4	90.4	36.0	149	0.2	65.8	25.3	796	4.67	16.6	2.2	2.5	8.9	25	0.4	0.8	0.5	30	0.37	0.086
KYS 111556	Soil	1.2	117.6	65.9	246	0.3	118.5	45.4	1684	5.08	53.8	3.0	3.8	12.7	20	1.4	1.4	0.7	11	0.26	0.064
KYS 112130	Soil	1.0	93.4	48.4	143	0.2	59.5	34.0	1139	4.94	137.1	3.0	14.3	23.0	20	0.1	86.1	0.7	11	0.24	0.057
KYS 112227	Soil	1.2	229.2	4.6	96	0.1	169.6	45.2	1515	6.32	28.4	0.6	1.4	2.4	32	0.2	2.9	<0.1	72	0.82	0.225
KYS 111555	Soil	1.3	122.4	64.5	256	0.3	120.7	45.8	1696	5.24	53.9	3.0	3.7	12.9	22	1.5	1.5	0.7	12	0.29	0.068
KYS 111554	Soil	1.5	100.2	40.4	262	0.2	84.3	30.8	1104	4.33	24.2	1.7	2.3	13.3	19	1.7	1.1	0.5	10	0.33	0.066
KYS 109943	Soil	2.2	51.3	31.3	95	0.1	42.4	27.6	658	4.06	37.1	1.3	2.0	14.6	26	0.1	2.5	0.4	18	0.24	0.057
KYS 109945	Soil	0.9	54.9	14.8	53	0.1	26.6	11.3	588	2.67	17.0	0.7	0.7	5.0	8	<0.1	1.3	0.4	26	0.10	0.051
KYS 111559	Soil	2.0	62.0	33.5	122	0.3	52.4	22.9	1005	4.11	32.2	2.4	3.0	9.5	18	0.4	1.9	0.4	19	0.08	0.067
KYS 111558	Soil	1.1	88.4	40.3	353	0.3	106.7	38.7	969	4.58	23.5	3.0	2.2	8.7	13	1.9	1.7	0.4	11	0.15	0.059
KYS 112194	Soil	2.2	24.9	15.1	43	0.3	9.6	4.1	232	2.66	13.0	0.6	4.0	2.2	10	0.1	1.5	0.3	73	0.05	0.044
KYS 112195	Soil	1.7	32.6	16.1	83	<0.1	33.3	11.5	252	3.34	19.4	0.7	2.6	5.3	11	0.2	2.0	0.2	63	0.07	0.035
KYS 110954	Soil	4.5	43.9	44.0	163	0.3	39.8	25.8	1825	3.87	42.4	2.3	5.0	14.0	13	1.0	12.9	0.4	18	0.13	0.065
KYS 112193	Soil	3.0	48.8	25.2	70	0.3	25.2	6.8	234	3.73	24.8	1.5	7.0	2.9	18	0.2	2.9	0.3	47	0.07	0.099
KYS 111716	Soil	0.6	68.3	15.7	77	<0.1	65.0	25.0	520	3.70	78.4	0.8	3.6	3.2	23	0.1	0.7	0.2	53	0.50	0.148

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112132	Soil		19	21	0.40	85	0.022	<1	1.35	0.006	0.04	0.1	0.04	2.0	<0.1	<0.05	3	0.6	0.2
KYS 112133	Soil		20	25	0.47	119	0.047	1	1.37	0.010	0.06	0.2	0.03	2.6	<0.1	<0.05	4	<0.5	<0.2
KYS 110000	Soil		20	30	0.57	128	0.046	2	2.06	0.008	0.06	0.2	0.05	3.2	<0.1	<0.05	5	0.6	<0.2
KYS 112005	Soil		13	33	0.37	112	0.014	1	1.48	0.006	0.03	<0.1	0.09	1.3	<0.1	<0.05	6	2.0	<0.2
KYS 112010	Soil		9	25	0.31	172	0.004	<1	1.37	0.008	0.03	<0.1	0.12	1.8	<0.1	<0.05	4	2.3	<0.2
KYS 111560	Soil		18	25	0.36	68	0.012	2	1.15	0.006	0.06	0.1	0.07	1.4	<0.1	<0.05	4	2.5	0.2
KYS 109940	Soil		11	23	0.58	141	0.002	2	1.23	0.006	0.08	<0.1	0.03	1.4	<0.1	<0.05	3	0.8	<0.2
KYS 109947	Soil		22	14	0.43	51	0.002	1	1.11	0.005	0.07	<0.1	0.02	0.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109948	Soil		26	17	0.53	66	0.002	<1	1.32	0.004	0.07	<0.1	0.03	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109944	Soil		26	40	1.01	23	0.004	<1	1.97	0.009	0.03	<0.1	<0.01	1.9	<0.1	<0.05	6	<0.5	<0.2
KYS 111548	Soil		21	58	1.09	103	0.051	<1	1.81	0.004	0.08	<0.1	0.08	3.1	<0.1	<0.05	5	2.3	0.2
KYS 111549	Soil		28	16	0.44	61	0.006	<1	1.12	0.003	0.07	<0.1	0.05	2.0	<0.1	<0.05	3	<0.5	0.2
KYS 111550	Soil		24	14	0.45	85	0.005	2	0.97	0.005	0.09	<0.1	0.06	2.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109941	Soil		21	14	0.38	160	0.004	<1	1.11	0.007	0.11	<0.1	0.04	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109942	Soil		35	20	0.65	74	0.002	1	1.50	0.003	0.07	<0.1	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 111551	Soil		18	46	0.92	66	0.014	1	1.76	0.005	0.05	<0.1	0.04	2.6	<0.1	<0.05	5	0.7	<0.2
KYS 111556	Soil		23	14	0.37	88	0.005	1	1.39	0.005	0.09	<0.1	0.06	2.2	<0.1	<0.05	3	<0.5	<0.2
KYS 112130	Soil		30	22	0.71	61	0.002	<1	1.62	0.007	0.06	<0.1	0.04	2.2	<0.1	<0.05	5	0.5	<0.2
KYS 112227	Soil		18	116	1.46	478	0.139	<1	2.19	0.006	0.22	<0.1	0.06	8.8	<0.1	<0.05	6	<0.5	<0.2
KYS 111555	Soil		24	14	0.39	85	0.004	2	1.41	0.005	0.09	<0.1	0.06	2.4	<0.1	<0.05	3	0.6	<0.2
KYS 111554	Soil		19	12	0.44	50	0.004	4	1.06	0.004	0.10	<0.1	0.07	1.9	<0.1	<0.05	3	1.2	<0.2
KYS 109943	Soil		27	31	0.77	183	0.002	1	1.50	0.007	0.08	<0.1	0.04	2.0	<0.1	0.06	4	<0.5	<0.2
KYS 109945	Soil		19	11	0.26	52	0.010	<1	0.88	0.007	0.07	<0.1	0.06	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 111559	Soil		21	19	0.43	52	0.007	<1	1.15	0.006	0.04	<0.1	0.05	1.8	<0.1	<0.05	3	1.6	<0.2
KYS 111558	Soil		26	14	0.45	34	0.004	1	1.48	0.006	0.04	<0.1	0.07	2.2	<0.1	<0.05	3	0.8	<0.2
KYS 112194	Soil		14	21	0.20	101	0.040	<1	1.30	0.006	0.04	0.3	0.04	1.8	0.2	<0.05	7	<0.5	<0.2
KYS 112195	Soil		13	36	0.48	204	0.055	2	2.31	0.008	0.06	0.2	0.04	3.7	0.1	<0.05	6	0.5	<0.2
KYS 110954	Soil		38	21	0.50	299	0.004	<1	1.35	0.006	0.07	<0.1	0.05	1.6	<0.1	<0.05	4	1.6	<0.2
KYS 112193	Soil		17	27	0.30	122	0.020	<1	1.54	0.006	0.04	0.2	0.04	2.0	<0.1	<0.05	5	0.8	0.2
KYS 111716	Soil		13	79	1.65	225	0.112	<1	2.18	0.004	0.05	<0.1	0.01	3.4	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 111712	Soil	2.6	56.5	20.0	104	0.2	34.2	10.7	395	3.57	49.8	1.5	5.0	1.6	15	0.3	1.9	0.3	45	0.09	0.089
KYS 109974	Soil	1.3	41.9	28.7	86	0.1	34.0	15.8	571	3.64	18.0	2.0	3.4	1.2	11	0.1	0.8	0.4	38	0.06	0.056
KYS 109732	Soil	1.6	25.5	23.5	80	<0.1	27.6	10.7	429	3.05	17.0	1.5	2.1	2.3	10	0.4	2.4	0.3	36	0.06	0.058
KYS 109982	Soil	1.0	46.6	36.8	89	<0.1	38.3	21.9	1124	3.96	272.5	1.7	2.7	2.7	13	0.2	2.4	0.5	29	0.12	0.057
KYS 109981	Soil	1.3	93.7	52.6	88	0.4	62.8	42.3	1095	4.52	703.9	5.2	9.3	4.4	35	<0.1	3.0	0.7	20	0.60	0.100
KYS 109729	Soil	6.6	41.0	17.4	97	0.9	20.3	6.6	319	2.30	17.8	2.2	4.0	1.4	24	0.6	3.8	0.3	43	0.12	0.090
KYS 109976	Soil	0.9	46.0	24.8	75	<0.1	39.9	18.7	581	3.06	12.8	1.5	2.1	3.5	13	0.2	1.0	0.3	36	0.08	0.035
KYS 109977	Soil	1.2	31.2	25.1	57	<0.1	24.3	9.3	294	3.30	14.3	1.1	1.8	2.6	11	0.1	0.8	0.3	44	0.09	0.038
KYS 109733	Soil	1.4	25.7	19.0	68	<0.1	24.1	7.5	281	2.95	13.5	1.1	5.1	1.4	12	0.1	1.3	0.3	42	0.08	0.054
KYS 109978	Soil	1.1	134.7	53.2	156	0.3	110.0	55.5	1347	6.17	26.7	4.9	3.9	10.7	18	0.2	0.6	0.6	20	0.17	0.056
KYS 110898	Soil	1.6	40.4	23.0	74	0.2	25.9	9.3	312	2.97	17.2	1.5	6.1	5.9	31	0.3	1.7	0.4	37	0.13	0.080
KYS 112152	Soil	1.2	51.9	36.1	104	0.3	42.4	16.8	608	3.53	237.3	1.7	28.4	8.0	53	0.2	256.0	0.4	15	1.71	0.058
KYS 112153	Soil	1.1	39.2	33.2	95	0.2	38.9	14.7	614	3.10	147.5	1.4	18.2	10.5	34	0.2	184.6	0.3	13	1.23	0.052
KYS 112158	Soil	1.1	57.0	35.4	101	0.2	32.9	11.7	472	3.52	155.2	2.2	13.0	11.0	34	0.1	204.3	0.5	14	0.52	0.061
KYS 112162	Soil	0.9	31.8	22.0	75	<0.1	25.4	11.5	681	2.66	26.6	1.0	10.9	6.5	15	0.2	27.3	0.3	22	0.34	0.054
KYS 112123	Soil	1.8	25.2	25.0	73	<0.1	23.6	9.9	483	3.06	28.0	1.0	4.2	7.8	16	0.2	5.8	0.3	31	0.17	0.039
KYS 112126	Soil	3.3	56.8	71.6	114	0.5	46.9	21.7	832	4.99	41.6	1.1	2.1	11.9	14	0.1	67.9	1.1	18	0.08	0.084
KYS 112128	Soil	2.1	63.4	54.7	94	<0.1	34.1	13.3	623	4.34	33.0	2.8	7.4	12.6	20	<0.1	93.6	0.7	10	0.14	0.056
KYS 112127	Soil	1.7	73.1	75.3	172	1.2	60.9	28.4	1015	4.68	1473	3.1	307.1	18.1	37	0.6	>2000	0.6	9	0.21	0.059
KYS 112155	Soil	1.4	52.3	33.5	87	0.2	24.6	8.8	350	3.63	65.2	1.7	8.2	11.8	17	0.1	75.2	0.5	16	0.28	0.050
KYS 112154	Soil	1.2	60.4	42.1	107	0.4	36.1	15.2	488	3.84	291.6	2.1	75.8	12.3	30	0.2	686.2	0.5	17	0.45	0.061
KYS 112163	Soil	1.4	59.3	44.6	132	0.1	63.3	31.1	1818	4.93	92.2	2.1	16.0	21.2	18	0.4	15.3	0.5	12	0.16	0.053
KYS 112159	Soil	1.1	64.6	55.0	115	0.2	30.0	12.2	442	4.46	522.6	2.3	57.8	17.9	17	<0.1	70.6	0.8	12	0.08	0.042
KYS 110976	Soil	1.2	41.4	36.7	107	0.4	35.1	14.5	845	3.27	398.0	2.6	18.1	7.3	58	0.6	72.1	0.3	15	0.60	0.061
KYS 110978	Soil	1.7	37.7	31.6	119	0.3	36.7	14.4	762	3.30	210.4	2.3	13.0	7.2	49	0.7	60.9	0.3	16	0.56	0.063
KYS 112034	Soil	0.7	34.8	28.5	80	<0.1	30.9	13.3	576	3.49	12.7	1.7	3.2	7.5	13	0.1	1.1	0.4	16	0.16	0.048
KYS 110979	Soil	1.6	36.5	31.2	113	0.3	36.2	14.2	721	3.19	203.5	2.3	10.1	7.1	50	0.6	60.5	0.3	15	0.58	0.062
KYS 112033	Soil	0.6	38.3	53.5	101	0.2	33.6	13.8	619	3.45	20.6	1.6	7.4	13.2	17	<0.1	0.9	0.4	10	0.22	0.040
KYS 112040	Soil	1.4	23.9	23.6	60	0.2	21.3	7.8	880	3.18	18.2	1.0	5.4	0.9	7	0.1	2.4	0.3	31	0.05	0.070
KYS 112042	Soil	1.3	21.9	24.3	44	0.2	16.2	3.3	365	1.68	24.7	1.0	1.9	0.4	8	0.3	0.9	0.6	18	0.07	0.078

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 111712	Soil	19	36	0.46	82	0.021	<1	1.48	0.006	0.05	0.1	0.04	1.5	<0.1	<0.05	4	1.2	<0.2
KYS 109974	Soil	15	32	0.50	75	0.019	<1	1.59	0.006	0.05	0.2	0.04	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 109732	Soil	20	24	0.35	80	0.019	1	1.19	0.006	0.06	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 109982	Soil	20	27	0.54	110	0.015	<1	1.54	0.007	0.06	0.1	0.03	1.7	<0.1	<0.05	5	<0.5	<0.2
KYS 109981	Soil	27	31	0.63	67	0.010	2	1.55	0.010	0.10	<0.1	0.08	1.9	<0.1	0.14	5	0.9	<0.2
KYS 109729	Soil	27	24	0.39	117	0.018	1	1.12	0.007	0.05	0.2	0.08	1.3	<0.1	<0.05	3	2.6	<0.2
KYS 109976	Soil	21	24	0.47	57	0.037	<1	1.34	0.006	0.04	0.2	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109977	Soil	18	27	0.42	80	0.029	<1	1.56	0.006	0.05	0.2	0.04	1.6	0.1	<0.05	6	<0.5	<0.2
KYS 109733	Soil	20	28	0.47	90	0.025	1	1.50	0.007	0.05	0.2	0.02	1.5	<0.1	<0.05	5	0.5	<0.2
KYS 109978	Soil	22	34	1.26	41	0.008	<1	2.69	0.007	0.07	<0.1	0.06	3.1	<0.1	<0.05	7	<0.5	<0.2
KYS 110898	Soil	23	28	0.44	138	0.040	<1	1.40	0.010	0.06	0.2	0.07	3.0	<0.1	<0.05	4	0.5	<0.2
KYS 112152	Soil	16	24	1.09	80	0.008	2	1.21	0.008	0.06	<0.1	0.05	1.9	<0.1	0.10	3	1.2	<0.2
KYS 112153	Soil	20	20	0.95	59	0.006	1	1.01	0.006	0.05	<0.1	0.04	1.3	<0.1	<0.05	3	0.8	<0.2
KYS 112158	Soil	21	19	0.50	57	0.005	2	1.04	0.008	0.03	<0.1	0.03	1.4	<0.1	<0.05	3	1.2	0.3
KYS 112162	Soil	20	17	0.43	105	0.007	<1	1.09	0.006	0.05	0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 112123	Soil	21	23	0.41	90	0.015	<1	1.11	0.006	0.06	0.1	0.02	1.3	<0.1	<0.05	4	0.5	<0.2
KYS 112126	Soil	24	25	0.51	52	0.003	1	1.43	0.006	0.06	<0.1	0.04	1.2	<0.1	<0.05	5	0.5	<0.2
KYS 112128	Soil	23	23	0.46	50	0.002	<1	1.08	0.006	0.05	<0.1	0.04	1.3	<0.1	<0.05	3	0.9	<0.2
KYS 112127	Soil	27	15	0.41	84	0.002	1	1.07	0.008	0.07	<0.1	0.05	2.2	<0.1	<0.05	3	0.6	<0.2
KYS 112155	Soil	26	21	0.51	92	0.007	1	1.07	0.007	0.04	<0.1	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 112154	Soil	22	21	0.62	83	0.006	1	1.20	0.007	0.04	<0.1	0.04	1.7	<0.1	<0.05	3	0.6	<0.2
KYS 112163	Soil	33	23	0.74	46	0.004	1	1.57	0.006	0.10	<0.1	0.02	1.8	<0.1	<0.05	4	0.6	<0.2
KYS 112159	Soil	32	19	0.54	78	0.001	<1	1.44	0.007	0.04	<0.1	0.05	1.5	<0.1	<0.05	4	0.5	<0.2
KYS 110976	Soil	14	19	0.53	218	0.002	<1	1.24	0.004	0.07	<0.1	0.05	1.4	<0.1	<0.05	3	1.3	<0.2
KYS 110978	Soil	18	22	0.57	346	0.003	1	1.16	0.004	0.06	<0.1	0.04	1.4	<0.1	<0.05	3	0.9	<0.2
KYS 112034	Soil	29	19	0.57	72	0.008	<1	1.34	0.006	0.05	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 110979	Soil	17	21	0.56	339	0.003	1	1.14	0.004	0.06	<0.1	0.03	1.4	<0.1	<0.05	3	0.9	<0.2
KYS 112033	Soil	44	15	0.47	58	0.005	<1	1.05	0.006	0.06	<0.1	0.06	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 112040	Soil	13	20	0.25	69	0.006	<1	1.06	0.006	0.04	<0.1	0.05	0.7	<0.1	<0.05	5	<0.5	<0.2
KYS 112042	Soil	11	17	0.16	45	0.004	1	0.60	0.009	0.04	<0.1	0.04	0.3	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112037	Soil	1.4	55.7	48.5	86	<0.1	53.3	28.8	1256	4.06	16.7	2.7	2.4	6.1	15	<0.1	0.5	0.5	9	0.18	0.053
KYS 112043	Soil	1.2	45.5	45.3	59	0.5	22.4	14.7	1367	3.02	25.9	3.2	1.6	1.5	8	0.3	0.6	0.3	19	0.05	0.146
KYS 112035	Soil	1.4	27.3	30.4	77	<0.1	32.2	11.9	512	2.74	11.3	1.6	2.7	3.1	12	0.3	0.9	0.3	28	0.08	0.053
KYS 112038	Soil	1.0	25.6	29.0	66	<0.1	23.2	13.1	627	2.61	12.2	1.0	2.8	2.8	9	0.1	0.7	0.3	24	0.09	0.050
KYS 112036	Soil	1.0	70.4	44.3	106	0.1	54.9	36.9	1293	4.22	20.5	2.5	3.0	3.9	16	0.1	0.5	0.6	14	0.18	0.063
KYS 112048	Soil	2.3	26.4	21.7	57	0.2	22.9	8.7	388	2.46	16.0	1.3	4.5	3.2	27	0.1	1.0	0.3	29	0.08	0.076
KYS 112110	Soil	1.6	41.6	32.0	99	0.2	39.5	16.5	641	3.33	52.5	2.0	15.6	13.5	23	0.3	4.0	0.4	10	0.31	0.047
KYS 112111	Soil	1.7	42.8	33.5	99	0.2	39.5	16.3	651	3.35	52.2	2.0	9.4	13.3	23	0.2	3.9	0.4	10	0.31	0.047
KYS 112052	Soil	1.2	24.1	21.0	51	0.3	25.4	7.9	191	2.58	10.2	1.4	3.2	7.0	9	0.1	0.9	0.2	28	0.06	0.049
KYS 112049	Soil	1.1	40.7	34.9	58	0.1	22.7	14.5	707	2.60	9.1	1.8	3.4	1.0	7	0.3	0.5	0.3	22	0.03	0.052
KYS 112047	Soil	2.1	40.5	26.0	78	0.3	30.0	10.7	392	2.88	21.0	2.2	13.6	5.5	41	<0.1	1.1	0.3	22	0.12	0.069
KYS 112050	Soil	1.2	29.1	16.6	62	<0.1	25.1	9.8	395	2.62	15.1	1.7	2.5	6.0	17	<0.1	1.3	0.3	39	0.09	0.050
KYS 112108	Soil	1.4	59.7	38.7	98	0.2	50.7	17.5	681	3.48	19.2	2.2	5.1	12.8	27	0.3	4.4	0.4	9	0.44	0.055
KYS 112105	Soil	2.4	81.0	30.0	117	0.6	55.7	9.9	370	3.88	13.0	1.7	5.4	11.7	25	0.2	1.6	0.6	24	0.20	0.058
KYS 112103	Soil	2.1	90.9	31.9	149	0.6	71.2	21.3	766	3.55	60.2	1.9	13.9	13.9	29	0.2	16.4	0.6	10	0.28	0.051
KYS 112102	Soil	0.8	53.5	38.4	73	<0.1	33.9	16.3	507	3.49	62.1	2.1	5.3	18.0	23	<0.1	4.2	0.4	7	0.19	0.036
KYS 112106	Soil	0.7	40.8	26.7	67	0.1	36.2	13.1	616	2.77	22.8	1.8	2.9	13.1	25	<0.1	1.4	0.3	8	0.32	0.038
KYS 112053	Soil	1.0	11.7	15.8	36	0.2	10.0	3.7	162	2.19	8.2	0.8	2.1	2.2	8	0.2	0.5	0.3	46	0.05	0.039
KYS 112055	Soil	3.0	66.6	11.6	137	1.0	35.8	9.9	266	3.34	103.6	1.7	12.0	4.3	29	0.2	38.5	0.2	35	0.05	0.053
KYS 112109	Soil	1.0	32.3	23.6	81	0.2	36.5	14.7	521	3.20	17.4	0.9	3.4	8.9	32	0.1	2.1	0.3	10	0.67	0.052
KYS 112056	Soil	1.6	33.8	10.7	63	0.2	22.7	8.8	307	2.95	22.3	1.0	9.5	5.0	10	0.2	9.6	0.2	43	0.05	0.034
KYS 112219	Soil	0.6	34.1	27.2	75	0.1	31.3	12.2	493	3.59	172.5	1.8	3.9	6.2	7	0.1	4.8	0.2	24	0.08	0.059
KYS 111506	Soil	0.6	16.7	16.7	24	0.2	4.6	1.3	46	1.86	5.2	0.4	0.9	1.4	5	0.2	1.2	0.2	26	0.03	0.049
KYS 111505	Soil	0.7	14.4	22.3	35	<0.1	10.0	3.3	143	1.80	7.3	0.5	1.2	4.4	7	<0.1	2.3	0.3	24	0.02	0.032
KYS 111509	Soil	0.9	29.5	12.4	62	<0.1	20.7	9.8	381	2.65	10.3	1.2	5.5	5.1	13	0.2	1.2	0.2	31	0.17	0.059
KYS 111507	Soil	1.2	38.5	25.4	72	<0.1	31.3	13.3	313	3.32	18.3	1.5	4.3	10.2	8	0.2	2.2	0.2	36	0.06	0.031
KYS 111508	Soil	1.2	30.8	13.8	72	0.1	23.4	10.4	361	2.63	9.3	1.2	6.2	5.4	15	0.2	1.7	0.2	38	0.20	0.063
KYS 112046	Soil	1.1	25.7	26.0	75	<0.1	30.8	15.3	506	3.46	29.5	0.9	2.4	5.0	9	0.2	0.7	0.2	43	0.12	0.058
KYS 112107	Soil	0.7	41.9	23.3	72	<0.1	40.5	15.0	453	3.07	16.8	1.5	2.0	11.9	20	0.1	1.1	0.3	7	0.33	0.044
KYS 112226	Soil	2.2	88.5	4.4	74	0.2	96.8	52.6	2836	5.95	22.6	0.3	2.8	0.4	15	0.4	0.4	<0.1	122	0.66	0.149

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112037	Soil	18	22	0.54	50	0.003	1	1.22	0.007	0.06	<0.1	0.02	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 112043	Soil	20	21	0.37	84	0.006	<1	1.33	0.007	0.06	<0.1	0.04	0.6	<0.1	<0.05	4	<0.5	<0.2
KYS 112035	Soil	20	28	0.44	70	0.023	<1	1.19	0.007	0.05	0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 112038	Soil	17	19	0.41	53	0.016	<1	0.96	0.006	0.05	0.2	0.04	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 112036	Soil	17	23	0.72	68	0.007	<1	1.57	0.007	0.05	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112048	Soil	17	24	0.39	110	0.018	<1	1.11	0.004	0.05	0.2	0.03	1.4	<0.1	<0.05	4	0.5	<0.2
KYS 112110	Soil	22	16	0.41	106	<0.001	<1	0.96	0.006	0.07	<0.1	0.05	1.4	<0.1	<0.05	2	0.6	<0.2
KYS 112111	Soil	22	16	0.42	109	0.001	<1	0.96	0.007	0.07	<0.1	0.05	1.5	<0.1	<0.05	3	0.7	<0.2
KYS 112052	Soil	20	23	0.38	70	0.021	<1	1.39	0.005	0.04	0.2	0.04	1.5	<0.1	<0.05	3	0.8	<0.2
KYS 112049	Soil	17	18	0.41	78	0.008	1	1.22	0.007	0.04	<0.1	0.02	0.6	<0.1	<0.05	4	<0.5	<0.2
KYS 112047	Soil	21	23	0.43	108	0.012	<1	1.06	0.007	0.06	<0.1	0.06	1.4	<0.1	<0.05	3	0.6	<0.2
KYS 112050	Soil	22	24	0.43	153	0.043	2	1.48	0.008	0.06	0.2	0.06	3.6	<0.1	<0.05	4	0.5	<0.2
KYS 112108	Soil	18	20	0.48	74	0.001	<1	1.02	0.007	0.08	<0.1	0.05	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 112105	Soil	11	30	0.55	74	0.001	<1	1.31	0.007	0.05	<0.1	0.10	1.8	<0.1	<0.05	3	1.1	<0.2
KYS 112103	Soil	18	15	0.43	63	0.001	<1	0.76	0.008	0.08	<0.1	0.07	1.5	<0.1	<0.05	2	0.7	<0.2
KYS 112102	Soil	29	11	0.42	45	0.002	<1	0.86	0.005	0.09	<0.1	0.02	1.0	<0.1	<0.05	2	<0.5	<0.2
KYS 112106	Soil	23	15	0.41	71	0.001	<1	0.92	0.006	0.14	<0.1	0.02	1.1	<0.1	<0.05	2	<0.5	<0.2
KYS 112053	Soil	16	17	0.21	83	0.023	<1	1.14	0.004	0.04	0.1	0.02	1.2	<0.1	<0.05	5	0.6	<0.2
KYS 112055	Soil	11	19	0.21	154	0.016	2	1.16	0.006	0.05	0.1	0.08	2.0	0.1	0.08	3	0.6	<0.2
KYS 112109	Soil	12	20	0.55	59	0.002	2	1.16	0.006	0.08	<0.1	0.04	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 112056	Soil	12	26	0.38	127	0.027	1	1.82	0.006	0.05	0.2	0.05	2.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112219	Soil	33	21	0.62	87	0.005	<1	1.48	0.004	0.05	<0.1	0.04	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 111506	Soil	15	10	0.04	49	0.003	<1	0.68	0.005	0.03	<0.1	0.03	0.3	<0.1	<0.05	4	<0.5	<0.2
KYS 111505	Soil	25	13	0.29	59	0.004	<1	1.23	0.003	0.04	<0.1	<0.01	0.7	<0.1	<0.05	5	<0.5	<0.2
KYS 111509	Soil	20	22	0.50	145	0.023	<1	1.29	0.007	0.05	0.1	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 111507	Soil	25	27	0.60	111	0.017	1	1.91	0.007	0.06	0.1	0.05	2.2	<0.1	<0.05	5	<0.5	<0.2
KYS 111508	Soil	21	27	0.49	172	0.026	1	1.38	0.008	0.06	0.2	0.04	2.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112046	Soil	16	38	0.76	74	0.017	<1	1.93	0.005	0.06	0.2	0.03	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 112107	Soil	21	16	0.52	56	0.001	1	1.06	0.004	0.15	<0.1	0.02	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 112226	Soil	5	76	3.34	189	0.010	<1	4.48	0.004	0.05	<0.1	0.10	9.6	<0.1	<0.05	10	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112228	Soil	0.7	41.1	1.6	56	<0.1	95.6	23.0	403	4.04	3.6	0.1	1.1	1.7	14	<0.1	0.3	<0.1	28	0.49	0.118
KYS 112054	Soil	3.5	74.7	11.5	158	1.0	37.0	10.5	290	3.63	118.6	1.7	12.2	4.5	33	0.1	42.4	0.2	36	0.05	0.053
KYS 112045	Soil	1.0	18.0	11.4	59	<0.1	20.8	7.9	279	2.68	30.8	0.8	1.9	3.4	10	0.1	0.8	0.2	44	0.13	0.068
KYS 112217	Soil	0.7	30.7	24.9	66	<0.1	26.1	12.0	430	2.87	31.2	1.3	2.6	5.9	8	0.1	4.7	0.2	31	0.09	0.050
KYS 112220	Soil	0.6	30.7	22.2	75	<0.1	29.6	12.2	538	3.87	23.4	1.5	1.3	8.7	6	<0.1	1.8	0.2	19	0.08	0.055
KYS 112218	Soil	1.1	34.4	27.5	73	0.1	29.7	12.9	527	3.30	32.8	1.5	4.0	4.1	14	0.1	2.8	0.3	35	0.20	0.061
KYS 111503	Soil	1.6	17.3	15.9	42	0.3	12.1	4.7	210	3.32	22.1	0.6	2.1	3.1	8	0.1	2.3	0.2	55	0.05	0.059
KYS 111504	Soil	0.9	31.6	17.4	73	<0.1	29.6	10.8	336	3.31	18.6	1.4	2.4	7.7	8	<0.1	1.7	0.2	34	0.06	0.037
KYS 111502	Soil	1.4	39.9	25.7	66	0.2	24.6	11.5	493	3.19	26.9	1.4	4.6	1.6	21	0.2	3.6	0.3	39	0.34	0.063
KYS 111501	Soil	0.8	33.1	15.8	67	0.2	34.9	9.8	360	2.51	11.1	2.0	5.0	2.2	30	0.2	1.1	0.2	24	0.57	0.068
KYS 112051	Soil	1.3	20.1	23.0	50	0.1	18.0	7.6	261	2.91	9.9	0.8	0.9	4.0	8	0.1	0.6	0.3	43	0.07	0.050
KYS 111688	Soil	1.4	32.7	9.9	68	0.2	26.4	7.2	260	2.55	14.3	1.1	3.7	5.1	12	0.4	1.3	0.2	39	0.15	0.077
KYS 109986	Soil	1.2	34.2	14.0	78	0.2	26.2	11.4	432	3.09	15.9	1.6	3.1	2.7	16	0.2	0.9	0.2	36	0.12	0.075
KYS 111689	Soil	2.1	21.0	13.5	56	0.3	18.5	5.7	219	3.43	17.3	0.6	3.4	1.4	10	0.2	1.4	0.2	47	0.08	0.069
KYS 109989	Soil	1.1	18.7	19.8	52	0.1	22.2	7.9	189	3.01	13.8	0.8	3.9	5.1	9	0.2	0.8	0.2	38	0.06	0.043
KYS 109999	Soil	0.7	42.6	32.8	81	<0.1	30.3	15.5	519	3.55	11.8	1.5	2.8	8.0	9	<0.1	0.4	0.4	19	0.02	0.027
KYS 112160	Soil	1.0	60.9	28.7	122	0.2	43.3	19.9	582	4.05	107.2	1.4	8.0	13.1	17	0.2	50.4	0.4	11	0.22	0.053
KYS 112124	Soil	2.0	31.7	20.3	55	<0.1	19.1	8.8	357	3.07	18.9	0.9	2.5	6.7	7	<0.1	4.6	0.3	20	0.04	0.035
KYS 112121	Soil	0.7	27.8	15.1	71	0.1	31.4	11.4	478	3.21	20.7	0.7	3.6	6.4	16	0.1	3.8	0.3	25	0.48	0.053
KYS 109987	Soil	1.3	25.1	17.0	66	0.2	24.5	9.8	345	3.00	12.5	1.1	4.3	2.2	17	0.1	0.7	0.3	33	0.06	0.058
KYS 109731	Soil	3.7	41.5	11.0	76	0.3	22.1	6.5	271	2.48	37.8	2.1	4.9	5.6	16	0.7	2.6	0.2	41	0.14	0.082
KYS 109985	Soil	0.9	18.5	15.5	64	<0.1	24.7	15.8	620	3.03	52.7	0.7	2.1	2.9	8	0.1	0.9	0.2	45	0.11	0.037
KYS 111692	Soil	1.5	11.0	9.0	25	0.2	7.5	2.1	67	1.53	9.2	0.7	1.9	0.5	9	<0.1	0.6	0.2	39	0.06	0.077
KYS 112267	Soil	0.9	18.2	20.9	62	0.1	19.6	10.1	618	3.19	21.9	0.8	4.2	1.3	11	0.1	0.6	0.3	29	0.16	0.072
KYS 112273	Soil	0.9	29.5	26.1	63	0.2	20.2	11.4	391	3.04	19.9	1.0	2.5	5.5	9	0.2	0.5	0.3	32	0.07	0.032
KYS 112272	Soil	0.7	42.2	27.9	74	0.2	30.3	16.5	829	3.36	21.4	1.6	2.0	5.9	9	<0.1	0.4	0.3	22	0.09	0.059
KYS 112279	Soil	1.2	28.1	11.5	58	<0.1	22.0	7.7	218	2.52	12.6	0.7	3.0	3.6	7	<0.1	1.1	0.2	46	0.06	0.028
KYS 110935	Soil	0.7	40.0	37.0	100	1.2	28.8	11.0	334	2.96	488.2	1.4	78.6	4.3	30	0.2	361.9	0.3	8	0.46	0.040
KYS 110945	Soil	0.9	23.1	19.2	66	0.1	24.1	11.7	521	2.70	37.2	1.1	<0.5	5.0	31	0.2	1.8	0.2	11	0.50	0.050
KYS 110934	Soil	0.6	41.7	36.4	106	1.2	28.8	11.7	374	3.22	497.0	1.3	51.3	5.3	21	0.2	356.6	0.3	9	0.27	0.045

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112228	Soil	5	82	1.68	64	0.134	<1	2.09	0.002	0.06	<0.1	0.01	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 112054	Soil	13	18	0.21	165	0.017	1	1.11	0.007	0.06	0.1	0.09	2.1	0.1	0.06	3	0.8	<0.2
KYS 112045	Soil	18	27	0.50	95	0.027	1	1.56	0.005	0.06	0.2	0.02	1.7	<0.1	<0.05	5	<0.5	<0.2
KYS 112217	Soil	27	23	0.54	65	0.018	1	1.40	0.004	0.06	0.1	0.03	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 112220	Soil	33	24	0.86	49	0.006	<1	1.84	0.004	0.06	<0.1	0.03	1.1	<0.1	<0.05	5	<0.5	<0.2
KYS 112218	Soil	28	28	0.63	120	0.013	<1	1.56	0.006	0.06	0.2	0.04	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 111503	Soil	15	21	0.25	76	0.022	1	1.28	0.004	0.05	0.2	0.03	1.2	<0.1	<0.05	6	<0.5	<0.2
KYS 111504	Soil	36	26	0.60	111	0.011	<1	1.87	0.005	0.07	0.1	0.03	1.6	0.1	<0.05	6	<0.5	<0.2
KYS 111502	Soil	15	23	0.34	133	0.012	<1	1.31	0.009	0.05	0.1	0.04	1.2	<0.1	<0.05	5	0.8	<0.2
KYS 111501	Soil	14	24	0.46	109	0.006	1	1.27	0.006	0.05	<0.1	0.05	1.5	<0.1	0.06	4	1.2	<0.2
KYS 112051	Soil	18	24	0.37	85	0.014	<1	1.52	0.004	0.05	0.1	0.03	1.4	0.1	<0.05	5	<0.5	<0.2
KYS 111688	Soil	16	23	0.33	76	0.031	<1	1.09	0.005	0.05	0.2	0.03	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109986	Soil	19	28	0.48	129	0.017	<1	1.46	0.006	0.06	0.1	0.05	1.7	<0.1	<0.05	5	<0.5	<0.2
KYS 111689	Soil	11	29	0.26	56	0.022	1	1.27	0.005	0.05	0.2	0.04	1.1	<0.1	<0.05	5	1.0	<0.2
KYS 109989	Soil	17	20	0.31	63	0.018	1	1.29	0.006	0.05	0.1	0.02	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 109999	Soil	23	22	0.68	59	0.009	<1	1.67	0.004	0.05	<0.1	0.01	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 112160	Soil	30	20	0.73	54	0.002	<1	1.57	0.005	0.06	0.1	0.04	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 112124	Soil	29	15	0.32	58	0.005	<1	1.01	0.004	0.05	<0.1	0.03	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 112121	Soil	23	18	0.56	122	0.006	<1	1.37	0.005	0.06	<0.1	0.04	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109987	Soil	18	21	0.34	92	0.012	<1	1.30	0.008	0.05	<0.1	0.03	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109731	Soil	22	21	0.40	126	0.031	<1	1.10	0.006	0.05	0.2	0.07	2.2	<0.1	<0.05	3	1.0	<0.2
KYS 109985	Soil	17	29	0.50	89	0.028	<1	1.40	0.005	0.05	0.2	0.03	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 111692	Soil	9	18	0.12	64	0.011	1	0.99	0.005	0.05	0.1	0.07	0.3	0.1	0.07	6	0.5	<0.2
KYS 112267	Soil	18	20	0.46	102	0.007	<1	1.31	0.004	0.06	<0.1	0.03	0.6	<0.1	<0.05	5	<0.5	<0.2
KYS 112273	Soil	23	20	0.36	81	0.017	1	1.23	0.003	0.03	0.1	0.02	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 112272	Soil	23	22	0.49	73	0.007	1	1.43	0.004	0.04	<0.1	0.05	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 112279	Soil	9	25	0.32	132	0.030	2	1.58	0.004	0.03	0.2	0.04	2.1	<0.1	<0.05	4	<0.5	<0.2
KYS 110935	Soil	8	12	0.36	135	0.002	2	0.88	0.004	0.07	<0.1	0.03	1.0	<0.1	<0.05	2	0.5	<0.2
KYS 110945	Soil	8	25	0.49	206	0.002	2	1.02	0.003	0.06	<0.1	0.03	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 110934	Soil	11	14	0.39	139	0.002	2	0.98	0.003	0.06	<0.1	0.03	1.1	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110943	Soil	0.7	38.6	22.7	78	<0.1	33.7	12.7	637	2.94	11.9	1.5	0.9	12.4	11	0.1	0.8	0.3	11	0.20	0.044
KYS 110944	Soil	0.6	29.9	21.6	75	<0.1	29.1	14.9	709	2.73	9.7	1.5	2.1	10.3	10	0.1	0.7	0.2	10	0.18	0.045
KYS 109677	Soil	2.2	32.2	31.0	63	0.3	32.2	9.2	383	3.20	84.6	1.2	3.3	2.8	15	0.1	97.7	0.3	10	0.03	0.049
KYS 109675	Soil	1.2	33.6	21.2	75	0.1	25.6	11.2	556	2.96	94.5	1.1	10.2	5.2	22	<0.1	15.2	0.2	11	0.29	0.046
KYS 110937	Soil	0.9	54.7	26.3	93	<0.1	37.3	15.3	609	3.21	19.1	2.4	2.8	13.8	14	0.1	1.7	0.4	8	0.23	0.045
KYS 112323	Soil	1.4	21.3	19.3	64	<0.1	21.3	8.4	387	2.47	16.5	1.0	1.5	3.2	13	0.1	0.9	0.3	30	0.13	0.044
KYS 112328	Soil	1.0	45.9	39.3	98	0.2	46.1	18.9	767	3.65	33.2	1.6	2.5	9.4	17	0.3	2.3	0.4	14	0.20	0.063
KYS 109875	Soil	1.1	32.9	29.9	83	<0.1	33.8	15.1	414	3.06	21.5	1.1	1.7	5.4	11	0.3	1.6	0.2	30	0.07	0.046
KYS 109876	Soil	0.6	38.9	86.3	74	0.1	44.2	18.8	443	2.80	21.0	1.3	1.8	10.4	5	0.1	1.6	1.3	18	0.04	0.027
KYS 109872	Soil	1.3	40.8	17.0	65	0.2	25.0	7.4	213	2.26	9.1	1.5	3.5	6.1	15	0.2	1.9	0.3	29	0.09	0.065
KYS 112324	Soil	1.1	16.4	12.8	55	<0.1	16.1	5.2	152	2.05	16.5	0.6	3.8	2.1	8	0.2	0.7	0.2	30	0.10	0.041
KYS 112329	Soil	2.6	51.6	25.2	67	0.7	32.0	10.2	329	3.41	27.2	1.5	8.1	5.6	21	0.2	2.0	0.4	19	0.29	0.070
KYS 112322	Soil	0.8	31.5	9.6	57	0.1	39.4	12.5	318	2.87	15.1	0.8	1.3	0.9	24	<0.1	0.4	0.1	36	0.41	0.101
KYS 112321	Soil	0.8	66.0	2.3	61	<0.1	64.5	18.8	547	3.87	10.4	0.3	1.2	1.0	14	<0.1	0.3	<0.1	44	0.45	0.161
KYS 112330	Soil	3.1	29.9	23.0	51	0.5	21.7	5.8	227	2.97	49.6	0.9	8.1	3.4	13	<0.1	2.6	0.4	20	0.15	0.066
KYS 112331	Soil	2.4	52.1	23.3	70	0.4	27.4	9.8	308	3.35	49.0	1.2	9.6	4.8	14	0.2	3.2	0.3	15	0.14	0.055
KYS 112326	Soil	0.6	14.7	17.9	41	<0.1	13.5	6.0	162	1.92	45.2	0.9	1.4	2.1	18	0.1	0.9	0.2	20	0.24	0.074
KYS 109718	Soil	0.7	25.6	13.1	57	<0.1	20.0	8.4	257	2.28	13.3	0.9	4.0	4.2	9	0.1	0.6	0.2	33	0.11	0.065
KYS 109727	Soil	0.9	32.7	13.5	71	<0.1	25.5	11.2	408	2.50	9.4	1.2	7.3	3.9	8	0.3	0.7	0.2	29	0.09	0.057
KYS 112213	Soil	0.6	40.5	19.0	77	<0.1	28.8	12.3	422	4.09	24.3	1.7	12.0	10.8	7	<0.1	0.3	0.2	19	0.04	0.039
KYS 112204	Soil	0.5	34.0	33.9	107	0.3	29.2	13.8	749	3.56	579.6	1.2	7.5	7.4	8	0.2	14.2	0.2	9	0.14	0.042
KYS 112203	Soil	0.6	53.4	21.4	87	<0.1	43.2	21.4	800	4.00	66.7	2.4	2.8	8.8	9	<0.1	1.9	0.3	10	0.10	0.048
KYS 112202	Soil	0.5	49.6	21.0	94	<0.1	45.1	22.0	879	3.99	48.3	2.1	3.2	6.4	10	<0.1	0.8	0.3	12	0.12	0.053
KYS 112205	Soil	0.6	40.2	26.6	100	0.2	35.4	17.6	743	3.62	432.0	1.4	7.1	11.9	8	0.1	12.3	0.2	8	0.15	0.047
KYS 109730	Soil	5.6	29.1	12.5	76	0.7	15.0	5.3	265	1.89	12.9	1.8	2.3	1.0	16	0.5	2.3	0.2	32	0.10	0.073
KYS 109726	Soil	0.8	24.2	11.6	54	<0.1	18.7	7.5	266	2.42	12.1	0.7	1.2	4.6	7	0.2	0.7	0.1	29	0.08	0.045
KYS 109591	Soil	2.8	40.9	18.8	70	0.5	24.6	7.9	264	2.53	25.5	1.3	5.3	4.4	13	0.2	3.4	0.3	32	0.08	0.069
KYS 112201	Soil	0.7	51.3	21.2	88	<0.1	42.0	19.2	741	3.99	40.5	2.2	1.4	5.5	7	<0.1	0.9	0.3	13	0.04	0.039
KYS 112208	Soil	1.8	35.1	33.8	113	0.5	39.1	12.6	821	3.54	601.1	1.6	7.2	4.9	15	0.2	11.7	0.3	12	0.33	0.072
KYS 112250	Soil	1.0	20.7	12.6	55	0.1	23.3	10.0	259	2.75	13.5	0.5	1.9	4.2	9	0.1	0.8	0.2	41	0.08	0.043

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110943	Soil	20	18	0.50	75	0.003	1	1.17	0.003	0.06	<0.1	0.02	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 110944	Soil	17	18	0.49	89	0.002	<1	1.18	0.002	0.06	<0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109677	Soil	12	29	0.23	42	0.002	2	0.84	0.005	0.07	<0.1	0.04	0.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109675	Soil	19	13	0.34	69	0.003	<1	0.93	0.004	0.05	<0.1	0.02	0.8	<0.1	<0.05	2	<0.5	0.2
KYS 110937	Soil	17	17	0.50	64	0.002	<1	1.20	0.002	0.06	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 112323	Soil	16	19	0.29	95	0.014	<1	0.93	0.003	0.04	0.1	0.03	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 112328	Soil	12	21	0.39	99	0.003	<1	1.05	0.004	0.06	<0.1	0.04	2.0	<0.1	<0.05	2	<0.5	<0.2
KYS 109875	Soil	15	37	0.69	115	0.007	<1	1.65	0.005	0.05	<0.1	0.02	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 109876	Soil	21	30	0.54	69	0.005	<1	1.30	0.003	0.06	<0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109872	Soil	17	19	0.28	78	0.023	<1	1.02	0.005	0.04	0.1	0.06	2.6	<0.1	<0.05	3	0.6	<0.2
KYS 112324	Soil	14	17	0.21	60	0.016	1	0.73	0.004	0.03	0.2	0.05	0.9	<0.1	<0.05	3	<0.5	<0.2
KYS 112329	Soil	8	23	0.29	129	0.001	<1	1.02	0.004	0.04	<0.1	0.08	1.8	<0.1	<0.05	3	1.3	<0.2
KYS 112322	Soil	10	51	0.91	162	0.019	1	1.53	0.005	0.03	<0.1	0.03	1.5	<0.1	<0.05	4	<0.5	0.2
KYS 112321	Soil	6	106	1.38	252	0.071	<1	1.98	0.003	0.07	<0.1	0.01	2.4	<0.1	<0.05	5	<0.5	<0.2
KYS 112330	Soil	6	20	0.13	91	0.001	<1	0.70	0.005	0.04	<0.1	0.09	1.2	<0.1	<0.05	3	0.8	<0.2
KYS 112331	Soil	9	12	0.15	106	<0.001	1	0.67	0.004	0.04	<0.1	0.07	1.5	<0.1	<0.05	2	1.2	0.5
KYS 112326	Soil	12	14	0.18	125	0.007	<1	0.85	0.004	0.07	0.1	0.02	0.9	0.1	<0.05	2	<0.5	<0.2
KYS 109718	Soil	16	24	0.41	71	0.034	1	1.32	0.004	0.03	0.2	0.03	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109727	Soil	18	21	0.41	94	0.025	<1	1.36	0.004	0.03	0.1	0.03	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 112213	Soil	31	30	0.82	41	0.010	<1	1.74	0.004	0.03	<0.1	0.01	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 112204	Soil	24	16	0.52	42	0.001	<1	1.21	0.005	0.05	<0.1	0.03	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 112203	Soil	25	19	0.70	24	0.002	<1	1.49	0.003	0.03	<0.1	0.02	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 112202	Soil	21	20	0.74	29	0.004	<1	1.60	0.004	0.03	<0.1	<0.01	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 112205	Soil	29	17	0.66	25	0.002	<1	1.28	0.004	0.04	<0.1	0.03	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109730	Soil	20	18	0.29	92	0.011	<1	0.88	0.004	0.03	0.1	0.07	0.9	<0.1	<0.05	2	1.8	<0.2
KYS 109726	Soil	13	20	0.34	70	0.034	1	1.11	0.004	0.03	0.2	0.04	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109591	Soil	12	21	0.27	342	0.013	1	1.04	0.004	0.04	<0.1	0.08	2.3	<0.1	<0.05	3	0.7	<0.2
KYS 112201	Soil	21	21	0.71	34	0.003	<1	1.60	0.004	0.03	<0.1	0.02	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 112208	Soil	18	37	0.47	93	0.002	<1	1.37	0.007	0.07	<0.1	0.04	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 112250	Soil	11	26	0.36	116	0.027	<1	1.80	0.005	0.04	0.2	0.03	2.0	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112247	Soil		1.1	14.5	18.3	54	<0.1	15.2	6.1	336	2.80	14.7	0.7	1.7	2.7	5	<0.1	1.0	0.2	36	0.05	0.039
KYS 109908	Soil		1.0	20.7	15.7	66	0.1	23.1	6.8	299	2.50	28.1	0.7	8.5	3.3	5	0.2	1.5	0.2	22	0.04	0.032
KYS 109909	Soil		1.0	19.0	15.7	67	0.1	22.2	7.3	296	2.56	38.9	0.7	5.2	4.5	4	0.2	1.6	0.2	18	0.04	0.031
KYS 109580	Soil		2.0	17.7	23.0	77	0.2	34.0	9.7	763	2.96	10.3	0.8	2.4	4.2	17	0.5	2.4	0.2	21	0.27	0.037
KYS 109577	Soil		3.3	44.1	19.5	120	0.6	61.0	17.9	569	4.15	51.7	1.2	9.6	7.7	9	0.4	5.3	0.2	24	0.03	0.056
KYS 109600	Soil		3.2	23.5	15.9	84	0.5	25.8	8.0	439	2.59	25.5	1.2	6.9	2.3	13	0.6	2.5	0.2	22	0.12	0.065
KYS 109905	Soil		2.7	50.3	18.4	161	0.2	47.5	12.0	494	3.30	33.9	2.0	6.7	5.4	9	0.6	7.9	0.2	29	0.03	0.048
KYS 109907	Soil		0.7	20.4	16.5	77	0.1	28.7	7.9	318	3.14	71.4	0.7	9.4	5.4	5	0.2	2.3	0.2	17	0.05	0.036
KYS 109904	Soil		2.4	38.9	17.7	131	0.2	49.9	17.2	606	3.33	177.8	1.4	15.6	6.6	9	0.4	9.0	0.2	26	0.04	0.050
KYS 109910	Soil		1.3	25.0	17.9	71	0.2	24.6	7.4	377	2.70	32.0	0.9	6.0	4.0	7	0.2	1.9	0.2	20	0.07	0.052
KYS 109906	Soil		1.5	35.2	20.4	137	0.1	45.2	13.2	592	3.19	16.1	1.5	5.3	6.1	7	0.5	2.8	0.2	21	0.05	0.046
KYS 112246	Soil		0.7	36.0	39.0	68	<0.1	38.1	17.9	1119	3.50	17.0	1.4	2.7	8.7	6	0.1	1.0	0.3	22	0.08	0.044
KYS 112200	Soil		1.1	25.7	10.6	65	0.2	22.2	5.6	203	2.43	13.0	1.0	4.6	1.5	8	0.2	2.4	0.2	33	0.07	0.046
KYS 112244	Soil		0.9	40.2	24.5	78	<0.1	36.9	10.2	374	3.89	22.6	1.7	1.7	13.1	6	<0.1	0.8	0.4	24	0.06	0.047
KYS 112199	Soil		1.0	23.6	13.9	62	0.1	19.7	6.5	278	2.53	9.7	1.1	5.6	1.1	8	0.1	1.3	0.3	27	0.08	0.056
KYS 112216	Soil		1.1	24.0	22.1	46	0.2	14.6	4.3	199	2.71	12.7	0.9	1.4	0.7	6	0.1	0.9	0.2	37	0.05	0.050
KYS 112251	Soil		1.2	17.1	13.4	53	<0.1	27.8	10.5	272	2.70	10.6	0.7	1.7	3.9	7	0.1	0.7	0.2	38	0.07	0.035
KYS 112248	Soil		1.1	20.0	21.3	58	0.3	23.9	11.5	384	2.92	15.1	0.9	2.7	4.5	7	0.1	0.7	0.2	38	0.09	0.053
KYS 112192	Soil		1.5	42.6	11.3	48	0.3	13.3	3.0	200	2.38	75.5	0.5	4.7	0.4	5	<0.1	5.6	0.2	29	0.02	0.054
KYS 112242	Soil		0.9	17.9	18.0	51	<0.1	20.6	10.3	513	2.57	13.0	0.9	4.4	1.5	7	0.2	0.5	0.2	31	0.09	0.053
KYS 112196	Soil		1.1	20.6	9.9	59	<0.1	18.8	7.0	288	2.80	11.7	0.9	4.1	4.1	7	<0.1	1.1	0.2	41	0.05	0.030
KYS 112197	Soil		1.9	38.3	15.4	56	0.1	25.3	7.0	403	2.60	11.4	0.6	12.0	1.1	6	0.2	4.0	0.2	29	0.03	0.052
KYS 112188	Soil		0.7	51.1	25.1	81	0.1	56.8	21.5	756	4.31	14.1	1.4	2.7	8.4	13	<0.1	0.5	0.2	36	0.19	0.058
KYS 109576	Soil		2.3	43.4	17.0	64	0.5	15.7	2.5	125	3.13	13.1	0.7	5.8	1.0	15	0.1	2.2	0.3	32	0.02	0.097
KYS 112245	Soil		0.6	20.3	24.5	39	<0.1	28.8	10.6	256	2.39	10.0	0.9	0.7	8.5	3	<0.1	1.0	0.2	17	0.04	0.038
KYS 112080	Soil		0.8	29.1	19.9	72	<0.1	31.6	11.2	314	3.69	20.2	1.4	2.1	7.5	6	<0.1	0.4	0.2	14	0.05	0.045
KYS 112071	Soil		1.4	46.9	29.7	65	0.3	46.0	20.3	943	3.23	29.9	3.4	2.9	5.7	13	<0.1	2.9	0.3	13	0.29	0.061
KYS 112101	Soil		0.9	49.1	33.1	62	<0.1	61.0	26.4	1279	3.98	36.5	1.6	4.6	13.7	107	<0.1	1.9	0.4	8	1.54	0.043
KYS 112104	Soil		1.0	35.4	20.4	62	<0.1	36.2	13.9	694	3.11	21.2	1.3	2.8	9.0	37	<0.1	0.9	0.2	10	0.56	0.053
KYS 112190	Soil		1.1	39.4	9.6	55	<0.1	25.0	7.3	323	2.73	15.3	1.1	6.3	4.2	9	0.1	1.3	0.2	41	0.07	0.034

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112247	Soil	14	19	0.36	47	0.011	<1	1.28	0.004	0.03	0.2	0.03	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 109908	Soil	14	19	0.37	84	0.004	<1	1.24	0.003	0.04	0.1	0.05	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109909	Soil	14	18	0.41	69	0.003	<1	1.25	0.003	0.05	<0.1	0.03	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109580	Soil	12	25	0.44	166	0.003	<1	1.29	0.003	0.06	0.1	0.04	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109577	Soil	10	58	0.85	288	0.002	<1	1.65	0.003	0.06	<0.1	0.07	1.5	<0.1	<0.05	5	1.4	<0.2
KYS 109600	Soil	10	13	0.22	313	0.004	1	0.90	0.003	0.04	0.1	0.10	0.7	<0.1	<0.05	3	1.3	<0.2
KYS 109905	Soil	15	18	0.36	292	0.008	<1	1.26	0.006	0.04	0.2	0.11	2.7	<0.1	<0.05	4	0.8	<0.2
KYS 109907	Soil	15	25	0.46	81	0.002	1	1.24	0.003	0.06	<0.1	0.03	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109904	Soil	13	23	0.40	156	0.005	<1	1.58	0.004	0.04	0.2	0.07	1.4	<0.1	<0.05	4	1.5	0.2
KYS 109910	Soil	13	17	0.37	71	0.004	<1	1.14	0.003	0.05	<0.1	0.05	0.9	<0.1	<0.05	3	0.8	<0.2
KYS 109906	Soil	16	19	0.40	91	0.008	<1	1.17	0.003	0.05	0.1	0.06	1.5	<0.1	<0.05	3	0.8	<0.2
KYS 112246	Soil	35	20	0.64	44	0.007	<1	1.52	0.004	0.05	<0.1	0.03	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 112200	Soil	13	19	0.33	95	0.013	1	1.20	0.005	0.04	0.2	0.06	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 112244	Soil	38	24	0.68	30	0.006	1	1.96	0.004	0.03	<0.1	0.04	1.2	<0.1	<0.05	6	<0.5	<0.2
KYS 112199	Soil	16	17	0.39	72	0.006	<1	1.23	0.004	0.04	0.2	0.04	0.8	<0.1	0.07	4	<0.5	<0.2
KYS 112216	Soil	17	18	0.33	48	0.011	<1	1.17	0.003	0.04	0.2	0.04	0.5	<0.1	<0.05	5	<0.5	<0.2
KYS 112251	Soil	11	26	0.40	135	0.020	1	1.67	0.006	0.06	0.2	0.05	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 112248	Soil	13	22	0.47	75	0.016	1	1.79	0.005	0.05	0.2	0.04	1.4	<0.1	<0.05	6	<0.5	<0.2
KYS 112192	Soil	11	9	0.02	55	0.007	<1	0.35	0.004	0.02	<0.1	0.02	0.4	<0.1	<0.05	3	<0.5	<0.2
KYS 112242	Soil	17	21	0.41	55	0.012	<1	1.23	0.004	0.04	0.1	0.03	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 112196	Soil	11	25	0.41	119	0.026	1	1.51	0.005	0.05	0.2	0.04	2.4	<0.1	<0.05	5	0.5	<0.2
KYS 112197	Soil	10	19	0.11	73	0.007	<1	0.83	0.008	0.03	<0.1	0.05	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 112188	Soil	27	54	1.28	93	0.011	<1	2.15	0.003	0.05	<0.1	0.03	3.0	<0.1	<0.05	7	<0.5	<0.2
KYS 109576	Soil	8	17	0.10	206	0.005	<1	1.00	0.006	0.04	0.1	0.10	0.9	<0.1	<0.05	4	2.0	<0.2
KYS 112245	Soil	22	14	0.37	30	0.005	<1	1.25	0.003	0.04	<0.1	0.02	0.6	<0.1	<0.05	5	<0.5	<0.2
KYS 112080	Soil	25	20	0.66	28	0.005	<1	1.44	0.003	0.04	<0.1	0.03	0.7	<0.1	<0.05	4	<0.5	<0.2
KYS 112071	Soil	30	17	0.60	40	0.005	1	1.20	0.005	0.05	<0.1	0.07	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 112101	Soil	16	21	0.64	40	0.002	1	1.11	0.006	0.07	<0.1	0.03	1.4	<0.1	0.08	3	<0.5	<0.2
KYS 112104	Soil	13	19	0.59	68	0.001	2	1.07	0.006	0.10	<0.1	0.03	1.1	<0.1	0.09	3	<0.5	<0.2
KYS 112190	Soil	14	23	0.40	95	0.031	<1	1.45	0.005	0.05	0.2	0.07	3.1	<0.1	<0.05	4	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109737	Soil	1.3	32.3	11.2	85	0.2	27.5	8.1	371	2.52	9.7	0.8	3.8	4.8	15	0.3	2.0	0.2	31	0.20	0.057
KYS 112243	Soil	1.0	31.6	21.7	81	<0.1	38.9	17.6	845	3.98	19.8	1.2	0.8	11.8	7	0.2	0.4	0.3	26	0.10	0.050
KYS 112249	Soil	1.0	13.8	12.2	45	0.1	15.0	5.7	321	2.78	12.2	0.6	9.0	3.4	5	<0.1	0.4	0.2	41	0.04	0.042
KYS 112191	Soil	0.9	20.4	15.2	48	0.2	23.4	7.3	289	2.56	10.1	0.8	6.4	0.9	10	0.1	0.6	0.2	25	0.10	0.051
KYS 112198	Soil	1.3	32.1	8.5	51	0.3	20.4	5.1	203	2.50	16.3	0.6	6.5	2.5	8	0.1	3.1	0.2	38	0.06	0.049
KYS 109863	Soil	1.1	20.8	14.1	62	<0.1	18.1	6.7	259	2.94	28.8	0.8	2.5	3.8	5	<0.1	3.5	0.2	21	0.04	0.043
KYS 109867	Soil	8.5	115.2	30.7	248	0.8	72.1	20.1	900	5.10	26.3	3.1	7.7	4.2	19	1.2	8.4	0.6	25	0.02	0.130
KYS 109869	Soil	2.6	58.9	25.0	81	0.4	23.3	6.9	239	3.63	18.9	1.3	6.3	2.2	20	0.2	2.7	0.5	44	0.02	0.105
KYS 109864	Soil	0.5	27.2	12.0	57	<0.1	23.4	16.0	880	2.84	12.2	0.4	0.5	6.7	25	<0.1	1.0	0.1	25	0.31	0.095
KYS 110951	Soil	6.0	66.9	38.2	205	0.3	57.5	18.7	415	4.42	21.5	2.3	1.9	14.5	16	2.1	3.7	0.4	16	0.19	0.072
KYS 109690	Soil	1.9	39.5	29.0	100	0.2	43.1	18.0	830	3.07	53.1	1.7	3.8	11.6	32	0.5	2.0	0.3	12	0.50	0.062
KYS 109870	Soil	2.9	66.5	31.0	99	0.6	33.3	11.8	363	4.68	24.9	0.9	7.1	2.6	12	0.2	4.0	0.5	43	0.03	0.211
KYS 109862	Soil	1.3	30.6	33.0	61	<0.1	26.5	15.3	844	2.88	24.8	0.8	2.0	11.0	6	0.1	8.2	0.3	8	0.06	0.043
KYS 112237	Soil	0.4	56.1	31.2	89	<0.1	45.3	23.7	657	3.62	17.9	1.4	1.4	18.2	6	<0.1	1.2	0.4	14	0.16	0.061
KYS 112235	Soil	0.5	41.4	28.3	78	<0.1	36.6	20.0	630	3.44	16.5	0.9	1.1	10.1	6	<0.1	1.3	0.4	15	0.10	0.061
KYS 109865	Soil	0.7	22.4	17.4	59	<0.1	17.5	7.9	195	2.91	10.7	0.7	1.5	9.4	4	<0.1	1.7	0.2	10	0.01	0.035
KYS 109871	Soil	2.0	31.0	18.3	54	0.2	18.8	5.5	185	3.03	18.8	0.8	8.1	2.8	14	0.2	2.1	0.4	48	0.05	0.120
KYS 112072	Soil	1.5	35.0	29.4	88	<0.1	34.4	17.6	739	3.28	25.2	1.7	1.1	6.1	13	0.2	1.2	0.3	23	0.20	0.100
KYS 112075	Soil	1.3	30.3	26.0	67	0.2	28.5	16.5	798	3.34	22.9	1.3	1.8	2.0	6	0.1	1.1	0.3	25	0.03	0.078
KYS 112079	Soil	1.6	45.7	30.1	85	<0.1	48.4	22.8	477	3.69	27.9	1.9	3.0	10.8	8	<0.1	0.6	0.2	15	0.05	0.049
KYS 112077	Soil	0.7	59.3	47.8	99	<0.1	49.3	31.5	1253	4.14	38.2	1.8	4.0	15.4	10	<0.1	1.0	0.4	16	0.07	0.062
KYS 112074	Soil	1.5	28.2	51.0	56	0.2	27.9	19.6	1144	2.90	21.2	1.5	1.2	1.5	6	0.1	0.8	0.3	23	0.03	0.130
KYS 112081	Soil	1.0	54.2	27.3	74	0.2	39.8	17.7	427	4.03	25.4	2.6	3.6	3.6	11	<0.1	0.5	0.3	28	0.05	0.104
KYS 109903	Soil	5.6	47.2	23.7	89	0.6	28.4	8.3	295	3.35	66.9	1.4	11.2	2.2	13	0.3	5.9	0.4	34	0.03	0.099
KYS 112073	Soil	2.0	28.9	35.8	71	<0.1	36.4	15.5	535	3.08	22.5	1.2	56.1	3.1	8	0.2	0.8	0.3	25	0.08	0.066
KYS 112082	Soil	0.9	47.0	23.4	73	0.2	38.6	14.2	431	4.24	21.4	2.4	6.4	2.8	8	<0.1	0.4	0.2	27	0.05	0.091
KYS 112189	Soil	1.5	31.3	18.5	56	0.3	18.2	12.1	490	2.35	14.1	1.3	5.4	0.5	17	0.2	0.8	0.3	34	0.07	0.077
KYS 112078	Soil	1.0	74.5	34.4	102	0.1	56.7	41.3	1480	4.18	39.0	2.9	10.3	14.0	15	<0.1	0.6	0.4	20	0.14	0.072
KYS 112076	Soil	1.5	26.9	23.9	69	<0.1	27.5	12.0	583	2.81	14.3	1.0	4.2	2.3	9	0.2	1.0	0.3	42	0.12	0.062
KYS 109933	Soil	7.9	48.7	20.5	184	0.7	53.6	13.6	513	3.11	24.5	3.0	6.6	3.7	26	2.6	4.7	0.2	28	0.40	0.069

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109737	Soil	17	25	0.48	222	0.025	<1	1.17	0.007	0.07	0.1	0.06	2.3	<0.1	<0.05	3	<0.5	<0.2
KYS 112243	Soil	29	26	0.73	81	0.014	1	1.87	0.004	0.06	<0.1	0.02	1.4	<0.1	<0.05	5	<0.5	<0.2
KYS 112249	Soil	16	16	0.30	76	0.011	1	1.32	0.004	0.04	0.2	0.02	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 112191	Soil	12	18	0.32	87	0.006	1	1.30	0.005	0.03	<0.1	0.05	0.8	<0.1	0.14	4	<0.5	<0.2
KYS 112198	Soil	10	20	0.22	118	0.017	<1	1.05	0.004	0.03	0.2	0.05	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109863	Soil	29	17	0.42	59	0.007	<1	1.34	0.003	0.05	0.1	0.03	1.0	0.1	<0.05	4	<0.5	<0.2
KYS 109867	Soil	13	19	0.18	180	0.006	1	1.13	0.008	0.05	0.1	0.26	2.3	0.1	0.09	2	3.9	<0.2
KYS 109869	Soil	10	26	0.25	256	0.008	<1	1.60	0.010	0.05	0.1	0.11	2.1	<0.1	0.09	5	1.9	<0.2
KYS 109864	Soil	14	25	0.55	44	0.005	<1	1.03	0.004	0.05	<0.1	0.02	2.4	<0.1	<0.05	4	<0.5	<0.2
KYS 110951	Soil	19	24	0.48	145	0.002	<1	1.11	0.004	0.06	<0.1	0.05	1.8	<0.1	<0.05	3	1.2	<0.2
KYS 109690	Soil	17	23	0.47	109	0.003	1	1.08	0.005	0.08	<0.1	0.04	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109870	Soil	12	30	0.20	79	0.013	<1	1.32	0.007	0.03	0.1	0.04	2.0	<0.1	<0.05	4	2.0	<0.2
KYS 109862	Soil	33	9	0.24	59	0.001	<1	0.61	0.006	0.07	<0.1	0.01	1.3	<0.1	<0.05	2	<0.5	<0.2
KYS 112237	Soil	39	24	0.92	27	0.003	<1	1.86	0.007	0.04	<0.1	0.02	1.9	<0.1	<0.05	5	<0.5	<0.2
KYS 112235	Soil	29	23	0.78	35	0.004	<1	1.64	0.005	0.04	<0.1	0.02	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 109865	Soil	28	15	0.41	47	0.002	<1	1.12	0.004	0.06	<0.1	0.02	0.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109871	Soil	14	27	0.29	90	0.021	<1	1.36	0.006	0.03	0.1	0.06	2.0	<0.1	<0.05	5	1.0	<0.2
KYS 112072	Soil	26	31	0.70	85	0.009	<1	1.49	0.007	0.06	<0.1	0.02	1.4	<0.1	<0.05	5	<0.5	<0.2
KYS 112075	Soil	24	26	0.54	69	0.007	<1	1.41	0.005	0.04	<0.1	0.03	0.7	<0.1	<0.05	5	<0.5	<0.2
KYS 112079	Soil	24	36	0.75	24	0.004	<1	1.61	0.006	0.05	<0.1	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 112077	Soil	32	24	0.77	38	0.005	<1	1.75	0.004	0.04	<0.1	0.04	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 112074	Soil	19	29	0.45	70	0.006	<1	1.18	0.007	0.04	<0.1	0.07	0.7	<0.1	0.06	4	<0.5	<0.2
KYS 112081	Soil	31	39	0.83	69	0.011	<1	1.78	0.007	0.04	<0.1	0.03	1.4	<0.1	<0.05	6	<0.5	<0.2
KYS 109903	Soil	14	26	0.30	176	0.005	<1	1.07	0.006	0.04	0.1	0.09	1.1	<0.1	0.05	4	1.4	<0.2
KYS 112073	Soil	24	39	0.58	60	0.009	<1	1.33	0.006	0.04	0.1	0.02	1.0	<0.1	<0.05	5	<0.5	<0.2
KYS 112082	Soil	31	41	0.90	65	0.009	<1	1.87	0.006	0.05	<0.1	0.03	1.2	<0.1	<0.05	6	<0.5	<0.2
KYS 112189	Soil	15	20	0.33	116	0.013	<1	1.13	0.005	0.04	<0.1	0.04	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 112078	Soil	42	29	0.85	50	0.008	2	1.80	0.006	0.05	<0.1	0.02	1.9	<0.1	<0.05	5	<0.5	<0.2
KYS 112076	Soil	23	31	0.43	94	0.021	<1	1.18	0.007	0.04	0.3	0.03	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109933	Soil	13	21	0.27	896	0.006	<1	0.93	0.005	0.04	0.1	0.18	1.8	<0.1	<0.05	3	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109597	Soil		0.9	33.0	22.3	76	0.2	27.4	12.9	836	2.63	24.4	1.3	5.4	2.8	40	0.3	1.4	0.3	23	0.77	0.071
KYS 111686	Soil		0.6	30.0	27.9	77	<0.1	29.3	14.0	392	3.18	34.7	1.0	3.5	10.6	9	0.2	0.7	0.4	14	0.14	0.049
KYS 109990	Soil		1.6	41.3	28.5	81	<0.1	26.3	14.1	615	4.28	15.6	1.4	1.3	5.1	8	0.1	0.7	0.4	53	0.04	0.067
KYS 109983	Soil		0.6	31.6	23.1	85	<0.1	30.8	18.3	631	3.54	73.5	1.0	0.9	3.4	6	0.2	1.0	0.2	24	0.04	0.050
KYS 111690	Soil		2.9	22.7	16.8	33	0.3	12.2	2.4	74	1.81	26.0	0.9	8.3	<0.1	10	<0.1	2.1	0.4	47	0.03	0.086
KYS 109988	Soil		1.0	31.3	22.7	62	<0.1	19.6	9.8	248	2.90	14.8	1.2	3.8	3.1	13	0.2	0.8	0.3	39	0.08	0.067
KYS 111683	Soil		2.6	51.3	33.9	103	0.2	32.8	13.8	442	3.16	48.4	2.0	5.8	4.6	13	0.3	1.3	0.4	13	0.08	0.063
KYS 109984	Soil		0.9	27.6	17.3	65	<0.1	28.8	13.7	359	3.33	156.5	1.0	2.2	4.6	8	0.2	1.4	0.3	37	0.06	0.045
KYS 112156	Soil		1.2	58.6	29.1	85	0.2	27.6	11.9	378	3.57	61.0	1.6	6.9	11.2	18	0.1	55.0	0.5	17	0.24	0.058
KYS 112129	Soil		1.2	92.7	33.1	70	0.3	35.8	16.7	693	3.18	34.6	5.2	9.4	7.1	69	0.2	115.4	0.4	9	1.48	0.065
KYS 109998	Soil		1.4	25.6	20.4	72	<0.1	26.1	10.3	346	3.19	14.4	0.8	1.0	4.8	8	0.2	0.7	0.3	46	0.08	0.031
KYS 109692	Soil		1.0	42.6	26.7	94	0.4	41.3	16.5	926	3.25	49.8	1.9	10.4	12.8	13	0.3	2.7	0.3	11	0.30	0.046
KYS 112236	Soil		0.5	41.8	26.0	82	<0.1	39.3	18.4	641	3.63	13.4	1.3	1.4	16.9	5	<0.1	1.1	0.4	9	0.15	0.046
KYS 112240	Soil		1.4	19.7	18.3	58	<0.1	19.9	12.2	510	3.04	14.5	1.1	3.3	2.9	8	0.1	0.6	0.3	41	0.06	0.047
KYS 112239	Soil		1.1	11.0	17.4	41	<0.1	14.4	6.7	411	2.78	10.0	0.6	2.8	5.1	7	0.1	0.6	0.3	45	0.05	0.027
KYS 112238	Soil		1.1	20.8	14.0	60	<0.1	21.5	12.0	356	2.70	11.9	1.0	2.5	2.0	10	0.2	0.8	0.3	44	0.10	0.049
KYS 112015	Soil		0.9	38.0	24.7	71	<0.1	32.4	16.5	501	3.09	15.5	1.0	1.9	10.0	16	0.1	11.4	0.3	8	0.75	0.042
KYS 109687	Soil		2.0	35.0	23.7	86	0.1	42.0	16.0	1409	3.51	16.9	2.0	3.3	13.1	17	0.6	1.9	0.3	8	0.18	0.045
KYS 112019	Soil		1.2	69.0	52.8	120	0.3	38.7	19.7	784	4.96	265.5	2.0	28.7	16.0	25	0.1	28.3	0.7	9	0.27	0.062
KYS 112017	Soil		0.9	37.7	18.7	130	0.1	59.5	24.2	876	2.94	38.3	0.9	5.0	8.6	20	0.1	23.9	0.3	13	0.85	0.056
KYS 112021	Soil		1.3	65.6	67.6	133	0.2	46.4	25.1	1080	4.84	100.8	1.6	8.3	15.1	16	0.3	83.9	0.5	16	0.19	0.060
KYS 112012	Soil		2.7	49.0	23.6	157	0.5	58.5	17.9	1161	3.88	20.0	2.2	25.8	7.3	14	1.4	3.2	0.4	16	0.16	0.058
KYS 112020	Soil		1.3	70.6	51.8	163	0.1	77.5	42.9	1878	4.66	100.4	4.1	1.5	19.4	15	0.4	36.6	0.6	15	0.19	0.055
KYS 112157	Soil		1.0	45.1	25.2	79	0.2	20.5	8.2	432	3.28	122.2	1.9	12.5	6.0	32	0.1	115.8	0.4	11	0.69	0.060
KYS 112161	Soil		1.1	38.9	22.0	80	<0.1	34.8	14.3	1075	3.25	41.8	1.3	4.5	6.7	11	0.2	8.3	0.3	24	0.11	0.060
KYS 112122	Soil		1.0	61.5	52.4	94	0.1	26.4	12.6	464	4.27	22.2	1.4	5.3	12.4	13	<0.1	6.1	0.8	8	0.09	0.049
KYS 112125	Soil		1.5	57.7	60.4	124	0.6	47.1	28.8	1166	4.49	760.2	2.3	157.1	10.2	18	0.4	>2000	0.6	7	0.11	0.045
KYS 112221	Soil		0.9	39.7	27.6	36	0.5	17.6	4.7	131	1.91	26.1	1.6	3.4	0.7	7	0.3	2.7	0.3	24	0.05	0.072
KYS 112229	Soil		1.2	80.9	2.7	69	<0.1	81.7	26.7	741	4.55	3.5	0.2	2.0	2.2	31	<0.1	0.7	<0.1	52	0.75	0.225
KYS 112231	Soil		0.6	78.3	2.4	78	<0.1	80.5	29.7	584	4.26	12.4	0.2	0.9	0.8	30	0.2	0.3	<0.1	82	0.93	0.197

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109597	Soil	11	21	0.35	156	0.010	1	0.95	0.007	0.04	0.1	0.05	2.0	<0.1	<0.05	3	0.5	<0.2
KYS 111686	Soil	26	14	0.36	88	0.004	<1	1.12	0.003	0.08	<0.1	0.02	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109990	Soil	22	26	0.48	86	0.017	<1	1.87	0.008	0.05	0.2	0.03	1.6	<0.1	<0.05	7	0.7	<0.2
KYS 109983	Soil	25	31	0.70	55	0.009	<1	1.56	0.004	0.06	<0.1	0.01	1.0	<0.1	<0.05	5	<0.5	<0.2
KYS 111690	Soil	8	23	0.09	46	0.007	<1	0.72	0.006	0.03	0.1	0.06	0.3	<0.1	<0.05	5	0.9	0.3
KYS 109988	Soil	14	20	0.38	75	0.024	<1	1.20	0.006	0.04	0.1	0.02	1.6	<0.1	<0.05	4	0.6	<0.2
KYS 111683	Soil	15	13	0.38	57	0.003	<1	0.86	0.004	0.06	<0.1	0.03	1.2	<0.1	<0.05	2	0.8	<0.2
KYS 109984	Soil	22	29	0.61	94	0.023	<1	1.77	0.005	0.03	0.1	0.02	2.2	<0.1	<0.05	5	<0.5	<0.2
KYS 112156	Soil	28	17	0.50	85	0.007	<1	1.04	0.007	0.03	<0.1	0.04	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 112129	Soil	10	18	0.45	80	0.002	1	0.99	0.008	0.05	<0.1	0.09	1.7	<0.1	0.06	3	1.1	<0.2
KYS 109998	Soil	15	29	0.50	135	0.024	<1	1.93	0.007	0.06	0.1	0.04	2.1	0.1	<0.05	5	0.5	<0.2
KYS 109692	Soil	26	20	0.58	84	0.002	<1	1.24	0.004	0.09	<0.1	0.04	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 112236	Soil	34	23	0.93	25	0.003	5	1.91	0.006	0.05	<0.1	0.02	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 112240	Soil	13	27	0.44	91	0.021	1	2.08	0.004	0.04	0.2	0.05	2.0	0.1	<0.05	5	0.5	<0.2
KYS 112239	Soil	17	20	0.27	100	0.021	<1	1.33	0.005	0.03	0.2	0.03	1.4	0.1	<0.05	5	<0.5	<0.2
KYS 112238	Soil	16	25	0.48	150	0.024	4	1.79	0.006	0.04	0.2	0.03	2.0	0.1	<0.05	5	0.6	<0.2
KYS 112015	Soil	21	17	0.70	62	0.003	2	1.28	0.005	0.05	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109687	Soil	24	17	0.50	79	0.012	2	1.08	0.003	0.09	<0.1	0.04	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 112019	Soil	24	20	0.62	71	0.002	2	1.46	0.006	0.05	<0.1	0.07	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 112017	Soil	22	15	0.76	78	0.009	3	1.10	0.005	0.05	<0.1	0.04	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 112021	Soil	28	27	0.76	58	0.003	2	1.61	0.008	0.05	<0.1	0.05	2.5	<0.1	<0.05	5	<0.5	<0.2
KYS 112012	Soil	14	25	0.35	114	0.006	<1	1.00	0.005	0.05	<0.1	0.07	1.6	<0.1	<0.05	3	1.2	<0.2
KYS 112020	Soil	21	28	0.84	64	0.002	2	1.87	0.005	0.06	<0.1	0.03	2.8	<0.1	<0.05	5	<0.5	<0.2
KYS 112157	Soil	16	17	0.49	60	0.004	2	0.94	0.006	0.04	<0.1	0.05	1.4	<0.1	<0.05	3	1.5	<0.2
KYS 112161	Soil	20	17	0.38	76	0.017	3	1.04	0.004	0.05	0.1	0.02	1.7	<0.1	<0.05	3	0.5	<0.2
KYS 112122	Soil	27	15	0.42	41	0.003	2	1.04	0.007	0.04	<0.1	0.04	1.4	<0.1	<0.05	3	0.5	0.4
KYS 112125	Soil	22	16	0.45	50	0.002	3	1.23	0.003	0.06	<0.1	0.05	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 112221	Soil	19	16	0.19	82	0.011	<1	0.96	0.007	0.04	0.1	0.06	0.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112229	Soil	9	110	1.88	121	0.059	2	2.14	0.003	0.05	<0.1	0.03	4.2	<0.1	<0.05	6	0.6	<0.2
KYS 112231	Soil	4	102	2.30	81	0.084	3	2.40	0.004	0.13	<0.1	0.03	2.3	<0.1	<0.05	6	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112223	Soil	1.2	23.7	21.0	84	<0.1	30.5	12.0	688	4.08	9.9	1.1	2.1	2.6	9	<0.1	0.6	0.2	14	0.05	0.058
KYS 112222	Soil	2.2	14.8	33.0	60	<0.1	27.2	7.6	972	3.23	4.5	0.6	1.3	2.0	8	0.2	0.4	0.2	10	0.11	0.053
KYS 112224	Soil	0.9	61.4	8.4	68	<0.1	25.5	12.9	376	2.72	12.6	0.6	8.6	3.6	15	0.2	0.8	0.1	49	0.21	0.075
KYS 112230	Soil	1.2	70.3	3.7	53	<0.1	57.9	23.1	759	3.41	2.1	0.2	1.2	1.3	46	<0.1	0.2	<0.1	47	0.97	0.169
KYS 112225	Soil	1.3	160.6	8.4	88	<0.1	47.3	20.4	380	2.92	10.7	0.7	4.9	3.3	13	0.4	0.9	0.2	53	0.20	0.096
KYS 109868	Soil	2.4	76.8	21.7	105	0.5	37.2	12.9	459	4.11	14.4	1.3	10.3	1.6	16	0.2	4.1	0.4	36	0.02	0.082
KYS 109866	Soil	0.6	12.3	12.2	45	<0.1	12.1	7.2	350	2.72	6.7	0.7	0.8	5.8	3	<0.1	1.0	0.2	10	0.02	0.046
KYS 109964	Soil	0.7	48.1	30.0	101	0.1	53.6	21.4	566	3.76	21.3	2.9	2.3	13.9	36	0.1	0.7	0.3	9	0.50	0.060
KYS 112041	Soil	0.8	51.4	24.1	116	0.1	59.2	29.1	1320	4.93	333.2	2.5	3.2	12.5	14	<0.1	2.6	0.4	10	0.15	0.054
KYS 110932	Soil	0.6	47.4	50.0	114	1.7	32.2	12.7	430	3.57	684.8	1.8	77.7	5.7	30	0.3	557.1	0.4	8	0.32	0.053
KYS 109678	Soil	0.7	34.3	56.6	71	0.4	31.1	14.6	561	3.31	486.5	1.5	102.1	8.5	9	0.2	204.1	0.3	13	0.06	0.043
KYS 109970	Soil	5.2	33.2	23.5	106	0.2	35.6	15.6	407	3.39	39.0	1.5	4.2	8.3	8	0.9	6.0	0.2	23	0.06	0.048
KYS 112039	Soil	2.1	15.0	25.6	70	<0.1	26.3	8.6	2245	4.31	8.0	0.7	0.6	0.8	8	0.2	0.5	0.2	13	0.13	0.098
KYS 109967	Soil	2.1	41.0	23.7	94	0.4	36.6	13.2	583	3.09	105.7	1.5	9.7	6.5	34	0.6	11.3	0.3	12	0.60	0.073
KYS 110952	Soil	0.5	47.7	33.8	78	<0.1	39.1	22.5	418	3.13	9.0	1.7	1.7	14.1	16	<0.1	0.3	0.4	9	0.19	0.052
KYS 109965	Soil	0.5	36.3	23.6	81	<0.1	39.3	16.7	351	3.41	15.5	1.3	2.3	15.0	20	<0.1	0.6	0.2	7	0.26	0.045
KYS 112044	Soil	0.9	13.8	11.7	50	<0.1	16.8	7.8	401	2.45	22.5	0.7	2.3	2.0	7	0.1	0.6	0.2	34	0.07	0.053
KYS 109968	Soil	2.1	43.7	44.6	121	0.5	38.5	15.7	806	3.13	83.8	1.4	17.1	6.9	15	0.9	44.3	0.3	13	0.22	0.062
KYS 112268	Soil	0.7	37.3	26.3	72	<0.1	29.6	13.8	551	3.21	17.6	1.6	2.8	1.9	6	0.2	0.3	0.4	21	0.05	0.050
KYS 112264	Soil	0.8	35.0	25.5	80	<0.1	37.1	17.4	525	3.40	14.4	1.3	1.9	4.2	13	0.1	0.8	0.4	20	0.13	0.108
KYS 111724	Soil	1.2	77.5	72.6	122	0.1	49.6	33.1	1548	4.09	68.1	2.1	4.6	10.5	31	0.2	1.1	0.6	11	0.70	0.055
KYS 112270	Soil	1.0	12.1	13.4	26	0.1	10.7	3.3	248	1.44	6.9	0.5	2.1	0.8	6	0.3	0.4	0.3	35	0.08	0.032
KYS 112271	Soil	1.7	16.1	24.2	42	0.1	17.4	4.5	415	2.29	10.0	0.7	0.6	2.2	4	0.2	0.4	0.2	31	0.03	0.038
KYS 111723	Soil	1.5	48.9	65.0	108	0.2	33.8	21.3	1057	3.90	50.6	2.3	3.7	8.7	28	0.1	1.5	0.4	9	0.38	0.076
KYS 112265	Soil	0.8	39.8	24.9	83	<0.1	41.9	18.1	562	3.43	14.0	1.3	2.2	7.0	9	0.1	0.9	0.4	20	0.09	0.053
KYS 109734	Soil	1.4	16.4	10.0	50	0.5	12.3	4.5	247	2.40	8.7	0.5	2.7	2.3	7	0.3	1.2	0.2	40	0.04	0.046
KYS 110942	Soil	0.5	40.1	23.1	66	0.1	28.8	12.5	557	2.57	12.9	1.5	4.1	8.6	40	0.1	1.1	0.3	9	0.64	0.055
KYS 112278	Soil	1.5	59.5	14.3	70	0.2	26.2	9.1	267	3.39	36.8	1.1	6.3	3.4	6	0.2	4.7	0.3	46	0.04	0.045
KYS 109735	Soil	4.5	22.9	15.5	45	0.3	9.5	2.0	125	1.95	11.2	0.6	3.8	0.9	8	0.2	2.7	0.2	30	0.03	0.060
KYS 112261	Soil	0.8	45.3	24.8	79	<0.1	39.4	19.7	893	3.63	45.1	1.7	8.6	7.0	11	0.1	1.1	0.4	9	0.14	0.037

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112223	Soil	13	19	0.40	47	0.008	<1	1.02	0.004	0.06	<0.1	0.03	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 112222	Soil	9	24	0.12	86	0.006	1	0.49	0.007	0.03	<0.1	0.03	1.3	<0.1	<0.05	2	<0.5	<0.2
KYS 112224	Soil	12	22	0.48	97	0.055	1	1.34	0.007	0.05	0.2	0.03	2.1	<0.1	<0.05	3	<0.5	<0.2
KYS 112230	Soil	7	79	1.54	102	0.028	2	1.83	0.005	0.03	<0.1	0.04	3.5	<0.1	<0.05	5	<0.5	<0.2
KYS 112225	Soil	11	26	0.54	98	0.056	1	1.60	0.006	0.05	0.3	0.03	2.4	<0.1	<0.05	4	0.6	<0.2
KYS 109868	Soil	11	27	0.24	181	0.009	2	1.47	0.006	0.04	<0.1	0.11	1.8	<0.1	0.05	4	2.3	<0.2
KYS 109866	Soil	34	14	0.36	55	0.002	2	1.13	0.003	0.05	<0.1	0.02	0.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109964	Soil	17	25	0.67	828	0.002	1	1.36	0.005	0.09	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112041	Soil	24	21	0.65	46	0.004	3	1.42	0.009	0.11	<0.1	0.02	3.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110932	Soil	14	14	0.52	53	0.002	2	1.16	0.005	0.07	<0.1	0.03	1.3	<0.1	<0.05	3	0.6	<0.2
KYS 109678	Soil	26	16	0.38	62	0.004	<1	1.07	0.004	0.08	<0.1	0.04	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109970	Soil	23	19	0.29	167	0.008	<1	1.06	0.004	0.07	0.1	0.06	1.4	<0.1	<0.05	3	1.4	<0.2
KYS 112039	Soil	6	32	0.24	64	0.006	<1	0.74	0.005	0.05	<0.1	0.06	1.0	<0.1	0.07	3	<0.5	<0.2
KYS 109967	Soil	14	16	0.37	58	0.004	2	0.74	0.007	0.06	<0.1	0.03	1.9	<0.1	0.05	2	1.1	<0.2
KYS 110952	Soil	17	24	0.65	275	0.001	1	1.42	0.004	0.08	<0.1	0.03	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109965	Soil	24	19	0.60	257	0.002	2	1.14	0.004	0.10	<0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 112044	Soil	17	21	0.40	78	0.022	2	1.31	0.004	0.04	0.1	0.02	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109968	Soil	15	18	0.42	266	0.001	<1	0.96	0.004	0.05	<0.1	0.05	1.4	<0.1	<0.05	3	0.7	<0.2
KYS 112268	Soil	9	21	0.50	71	0.006	<1	1.41	0.004	0.04	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 112264	Soil	13	21	0.59	60	0.012	1	1.38	0.004	0.05	0.1	0.01	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 111724	Soil	15	21	0.52	54	0.003	<1	1.35	0.003	0.06	<0.1	0.03	1.3	<0.1	0.06	3	<0.5	<0.2
KYS 112270	Soil	11	13	0.10	114	0.016	<1	0.62	0.004	0.04	0.1	0.02	0.5	<0.1	<0.05	4	<0.5	<0.2
KYS 112271	Soil	13	23	0.12	63	0.008	<1	0.91	0.005	0.04	0.1	0.02	0.7	<0.1	0.06	4	<0.5	<0.2
KYS 111723	Soil	12	16	0.36	78	0.002	<1	1.16	0.003	0.07	<0.1	0.04	1.2	<0.1	0.09	3	<0.5	<0.2
KYS 112265	Soil	16	21	0.59	73	0.010	<1	1.50	0.004	0.04	<0.1	0.01	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109734	Soil	9	17	0.12	110	0.012	<1	0.83	0.003	0.03	0.1	0.03	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 110942	Soil	10	14	0.39	141	0.002	<1	0.97	0.003	0.11	<0.1	0.04	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 112278	Soil	9	22	0.19	119	0.015	1	1.34	0.004	0.03	0.2	0.05	1.6	<0.1	<0.05	4	<0.5	0.3
KYS 109735	Soil	14	10	0.04	80	0.008	<1	0.45	0.004	0.03	0.1	0.03	0.5	<0.1	<0.05	3	1.0	<0.2
KYS 112261	Soil	15	16	0.61	36	0.003	<1	1.22	0.004	0.04	<0.1	0.02	1.4	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112276	Soil	0.7	31.0	16.1	57	0.3	27.9	9.1	246	2.31	14.5	1.6	16.0	2.2	18	0.2	1.6	0.3	21	0.29	0.055
KYS 112280	Soil	1.5	90.6	12.5	77	0.1	36.5	11.3	872	3.52	14.8	0.9	9.2	4.4	8	0.1	2.7	0.2	42	0.06	0.042
KYS 109736	Soil	1.4	28.9	13.6	63	<0.1	22.5	9.6	283	2.68	12.8	1.3	5.5	4.3	9	0.2	1.5	0.3	40	0.08	0.053
KYS 112260	Soil	0.5	39.3	19.9	82	<0.1	34.8	14.8	595	3.77	18.0	2.0	2.4	9.9	8	<0.1	0.8	0.3	10	0.06	0.036
KYS 112263	Soil	0.7	30.4	21.5	71	<0.1	31.9	15.6	543	3.13	14.3	1.0	<0.5	5.0	7	0.1	1.1	0.3	19	0.05	0.036
KYS 112257	Soil	0.5	44.7	23.8	82	<0.1	38.6	18.4	695	3.76	16.9	2.3	2.4	11.5	10	<0.1	0.9	0.3	10	0.08	0.036
KYS 112266	Soil	0.9	27.8	20.3	77	<0.1	28.6	14.0	531	3.35	12.4	0.9	1.8	3.3	11	0.1	0.6	0.3	24	0.10	0.044
KYS 109593	Soil	1.8	27.1	26.2	60	0.5	21.2	11.5	371	3.28	28.1	1.5	4.2	1.9	16	0.2	1.7	0.3	29	0.26	0.083
KYS 109682	Soil	0.7	69.7	40.9	90	0.1	48.4	25.1	641	3.65	100.8	1.9	11.9	16.4	30	<0.1	2.1	0.5	12	0.54	0.052
KYS 109594	Soil	1.1	19.2	16.3	48	0.4	16.1	6.9	487	2.01	13.3	1.0	3.2	0.6	37	0.2	1.1	0.2	27	0.86	0.071
KYS 109595	Soil	1.1	19.0	17.2	58	0.2	19.5	8.7	544	2.31	15.3	1.1	4.6	1.9	36	0.3	1.2	0.2	24	0.75	0.068
KYS 109890	Soil	1.1	47.4	30.4	163	0.2	42.5	17.4	704	3.63	34.9	2.5	1.1	8.2	25	0.5	2.4	0.4	11	0.38	0.056
KYS 112112	Soil	2.5	37.3	24.3	98	0.2	32.7	13.8	654	3.22	33.2	1.6	5.5	10.6	15	0.4	2.2	0.3	9	0.25	0.044
KYS 112317	Soil	4.7	186.5	6.6	70	0.2	96.1	47.0	1360	6.18	7.5	0.8	4.9	3.3	32	0.3	0.4	0.2	42	0.73	0.267
KYS 112320	Soil	1.0	60.1	6.1	71	<0.1	59.6	19.6	535	3.70	16.0	0.4	1.5	1.5	15	<0.1	0.6	0.1	51	0.35	0.116
KYS 112318	Soil	0.4	105.0	1.9	69	<0.1	93.0	27.9	635	3.81	5.9	0.2	3.5	1.0	22	<0.1	0.2	<0.1	47	0.77	0.244
KYS 109885	Soil	0.9	32.5	21.0	67	0.2	28.9	12.5	671	2.80	16.6	1.1	2.5	4.9	32	0.2	1.2	0.3	16	0.60	0.062
KYS 112141	Soil	15.4	66.6	24.2	144	0.9	47.7	10.3	414	3.98	20.7	2.1	6.2	6.0	18	1.0	2.8	0.4	50	0.09	0.092
KYS 112145	Soil	5.1	90.3	14.9	174	1.1	34.3	4.7	130	5.34	41.1	6.3	1.8	8.8	27	0.3	7.5	0.4	22	0.01	0.151
KYS 109878	Soil	0.8	14.0	15.7	46	<0.1	18.8	6.7	223	2.43	11.0	0.5	2.8	6.3	5	0.1	0.7	0.2	30	0.04	0.019
KYS 109881	Soil	0.6	10.8	9.6	40	0.1	12.9	4.5	129	1.77	12.0	0.5	1.1	6.8	3	<0.1	1.1	0.2	21	0.02	0.022
KYS 109873	Soil	3.0	19.6	19.0	46	0.6	15.1	4.9	133	2.35	9.8	0.9	13.8	4.7	15	0.2	1.2	0.3	38	0.03	0.062
KYS 109879	Soil	0.6	41.7	34.6	87	<0.1	31.7	16.3	564	3.58	13.3	1.2	1.4	8.3	10	0.3	2.2	0.3	22	0.10	0.052
KYS 109874	Soil	1.7	37.0	29.1	83	0.3	29.4	9.7	231	2.95	51.1	1.1	73.2	4.5	22	0.3	3.1	0.3	27	0.12	0.043
KYS 112095	Soil	0.7	43.9	26.0	85	0.2	31.1	18.2	862	2.87	34.6	3.2	6.1	3.6	31	0.2	1.1	0.3	21	0.56	0.062
KYS 112332	Soil	1.8	50.1	21.4	51	0.6	22.6	6.8	297	2.49	24.9	1.5	8.3	5.0	27	<0.1	3.2	0.3	14	0.32	0.057
KYS 112327	Soil	0.8	29.7	28.3	55	0.1	29.7	16.2	576	2.84	88.5	2.2	4.1	4.4	39	0.2	0.9	0.3	17	0.54	0.054
KYS 112333	Soil	2.7	60.7	25.7	82	0.5	27.9	10.3	375	3.12	35.7	1.5	6.3	6.4	25	0.2	4.3	0.4	16	0.25	0.083
KYS 112325	Soil	0.9	27.4	19.6	69	<0.1	23.1	10.7	490	2.60	17.2	1.0	6.5	6.0	12	0.2	0.8	0.3	31	0.15	0.057
KYS 109937	Soil	1.8	41.7	21.7	98	0.2	44.8	15.5	504	3.36	13.8	1.9	1.7	10.2	16	0.4	1.1	0.3	15	0.23	0.046

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112276	Soil	12	18	0.32	93	0.007	<1	0.96	0.005	0.03	<0.1	0.03	1.6	<0.1	<0.05	3	1.0	<0.2
KYS 112280	Soil	9	28	0.37	174	0.024	<1	1.62	0.005	0.06	0.2	0.04	2.8	<0.1	<0.05	4	0.6	<0.2
KYS 109736	Soil	17	26	0.42	144	0.019	<1	1.55	0.006	0.04	0.2	0.04	2.2	<0.1	<0.05	4	0.5	0.2
KYS 112260	Soil	26	21	0.79	26	0.004	<1	1.66	0.004	0.04	<0.1	0.01	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 112263	Soil	16	20	0.57	67	0.010	<1	1.34	0.003	0.04	<0.1	0.02	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 112257	Soil	26	19	0.78	26	0.002	<1	1.59	0.004	0.04	<0.1	0.01	1.2	<0.1	<0.05	4	<0.5	0.2
KYS 112266	Soil	15	19	0.51	58	0.013	<1	1.34	0.004	0.04	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109593	Soil	11	19	0.29	145	0.006	<1	1.17	0.005	0.04	0.1	0.08	1.5	0.1	<0.05	4	0.8	<0.2
KYS 109682	Soil	14	18	0.65	57	0.002	<1	1.34	0.004	0.07	<0.1	0.02	1.5	<0.1	<0.05	4	<0.5	0.2
KYS 109594	Soil	7	20	0.28	130	0.009	<1	1.00	0.006	0.04	0.1	0.06	1.0	<0.1	0.06	4	0.8	<0.2
KYS 109595	Soil	8	19	0.32	139	0.008	<1	0.97	0.007	0.04	0.1	0.05	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109890	Soil	11	16	0.41	84	0.004	<1	1.18	0.004	0.05	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 112112	Soil	16	15	0.41	95	0.002	<1	0.99	0.004	0.05	<0.1	0.05	1.1	<0.1	<0.05	2	0.7	<0.2
KYS 112317	Soil	14	64	1.28	203	0.021	1	1.78	0.004	0.04	<0.1	0.08	5.3	<0.1	0.12	5	0.7	0.5
KYS 112320	Soil	9	79	1.18	221	0.058	<1	1.82	0.004	0.06	0.1	0.02	2.1	<0.1	<0.05	5	<0.5	<0.2
KYS 112318	Soil	5	100	2.25	182	0.075	<1	2.26	0.004	0.07	<0.1	0.02	2.7	<0.1	<0.05	5	<0.5	<0.2
KYS 109885	Soil	11	19	0.44	189	0.004	<1	1.18	0.005	0.05	<0.1	0.04	1.2	<0.1	<0.05	3	<0.5	0.3
KYS 112141	Soil	12	19	0.28	211	0.001	<1	0.86	0.004	0.06	<0.1	0.25	1.5	<0.1	0.13	3	4.3	0.4
KYS 112145	Soil	12	14	0.12	518	0.001	<1	0.55	0.006	0.05	<0.1	0.08	1.6	<0.1	0.17	2	9.5	0.3
KYS 109878	Soil	19	24	0.36	105	0.008	<1	1.17	0.004	0.05	<0.1	0.02	1.0	<0.1	<0.05	5	<0.5	<0.2
KYS 109881	Soil	22	13	0.21	38	0.004	<1	0.99	0.004	0.04	<0.1	0.01	0.8	<0.1	<0.05	5	<0.5	<0.2
KYS 109873	Soil	17	20	0.17	130	0.011	<1	1.13	0.004	0.04	0.1	0.06	1.1	0.1	<0.05	4	0.9	0.3
KYS 109879	Soil	17	22	0.43	83	0.006	<1	1.47	0.005	0.06	<0.1	0.05	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109874	Soil	15	25	0.45	160	0.005	<1	1.42	0.004	0.04	0.1	0.02	1.1	<0.1	<0.05	5	<0.5	0.4
KYS 112095	Soil	22	24	0.53	141	0.007	<1	1.33	0.006	0.05	<0.1	0.05	1.1	<0.1	0.07	4	<0.5	<0.2
KYS 112332	Soil	9	12	0.20	102	<0.001	<1	0.61	0.005	0.04	<0.1	0.09	1.5	<0.1	<0.05	2	1.7	<0.2
KYS 112327	Soil	10	22	0.37	150	0.003	<1	1.16	0.006	0.06	<0.1	0.01	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 112333	Soil	11	15	0.30	150	0.001	1	0.80	0.005	0.04	<0.1	0.07	1.7	<0.1	<0.05	3	0.8	<0.2
KYS 112325	Soil	20	26	0.45	66	0.030	<1	0.98	0.006	0.04	0.2	<0.01	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109937	Soil	22	40	0.83	299	0.002	1	1.40	0.004	0.06	<0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 111557	Soil	1.5	161.0	116.9	377	0.7	132.3	72.3	1977	6.06	117.2	4.4	5.3	8.2	24	1.2	2.4	1.3	12	0.31	0.059
KYS 112083	Soil	0.7	41.4	23.7	77	0.1	38.3	21.7	555	3.57	18.1	1.8	11.8	7.4	12	<0.1	0.6	0.3	31	0.09	0.057
KYS 112084	Soil	1.9	57.5	43.2	69	0.1	45.7	29.8	1559	3.53	18.1	2.2	<0.5	5.5	10	<0.1	3.3	0.4	20	0.05	0.060
KYS 112093	Soil	0.8	17.1	14.8	49	<0.1	19.1	8.9	259	2.33	12.1	0.8	8.1	4.3	12	<0.1	0.7	0.2	38	0.11	0.043
KYS 112085	Soil	0.9	21.2	18.4	50	0.2	18.5	8.2	293	3.06	15.0	0.6	3.2	3.0	8	<0.1	0.6	0.2	38	0.08	0.039
KYS 109938	Soil	1.8	44.4	22.7	99	0.2	49.5	16.5	512	3.49	15.9	1.7	3.4	9.1	20	0.4	1.1	0.3	17	0.27	0.048
KYS 111547	Soil	2.3	85.7	17.8	107	0.2	74.9	31.4	811	4.55	29.7	0.8	2.5	4.7	34	0.4	0.6	0.2	63	0.80	0.228
KYS 109934	Soil	1.7	31.4	21.0	89	0.2	34.9	14.7	634	3.35	13.9	1.5	4.0	7.4	19	0.3	1.0	0.3	20	0.26	0.051
KYS 111561	Soil	3.4	57.2	34.4	172	0.4	61.5	18.6	764	3.60	15.7	2.3	4.6	3.1	26	0.9	1.3	0.4	32	0.37	0.078
KYS 112089	Soil	1.1	19.8	21.0	53	<0.1	16.2	6.9	247	2.92	14.3	0.8	14.2	5.7	9	0.2	0.8	0.3	46	0.06	0.036
KYS 112091	Soil	0.9	33.0	23.5	58	<0.1	26.2	10.9	300	2.83	14.7	1.0	2.0	7.1	11	<0.1	0.8	0.2	39	0.09	0.040
KYS 109728	Soil	6.1	37.8	17.6	81	0.4	19.2	6.6	277	2.72	19.0	1.8	6.4	2.9	27	0.2	3.1	0.3	41	0.10	0.101
KYS 109587	Soil	0.3	38.0	21.6	89	0.1	39.9	11.7	359	3.01	11.9	1.1	2.2	9.2	34	0.3	1.4	0.2	9	0.60	0.053
KYS 109715	Soil	1.2	34.7	22.2	80	0.1	25.6	14.2	432	3.15	25.7	1.4	3.5	3.1	13	0.2	0.9	0.3	43	0.10	0.073
KYS 109723	Soil	1.0	21.8	14.0	58	<0.1	20.1	7.6	263	2.56	12.3	1.1	0.9	1.4	12	<0.1	0.7	0.2	41	0.11	0.060
KYS 109721	Soil	0.9	19.6	12.2	58	<0.1	18.2	9.1	419	2.63	17.7	0.9	3.5	3.2	13	0.1	0.7	0.2	37	0.16	0.087
KYS 109720	Soil	0.9	17.7	12.0	57	<0.1	19.1	8.6	390	2.39	15.8	0.8	1.4	2.8	14	0.1	0.6	0.2	36	0.14	0.077
KYS 109717	Soil	1.0	29.7	14.2	71	<0.1	26.7	11.2	361	2.54	19.5	1.1	9.5	5.9	15	0.2	0.8	0.2	34	0.16	0.076
KYS 109719	Soil	0.7	26.4	10.0	65	<0.1	23.8	10.3	343	2.45	17.7	0.9	1.7	5.6	13	0.2	0.7	0.1	36	0.16	0.073
KYS 109722	Soil	1.1	24.3	13.4	62	<0.1	21.6	8.4	325	2.64	14.6	0.8	<0.5	2.7	12	0.1	0.8	0.2	38	0.11	0.055
KYS 109716	Soil	1.0	20.4	15.8	83	<0.1	21.7	12.5	459	2.85	16.2	1.0	7.4	3.0	14	0.2	0.8	0.2	45	0.13	0.081
KYS 109592	Soil	2.3	30.8	13.2	62	0.4	23.6	7.4	264	2.64	22.0	1.3	7.3	3.4	16	0.1	3.0	0.2	41	0.11	0.070
KYS 109724	Soil	1.1	30.1	17.2	68	<0.1	27.7	10.5	394	3.05	38.0	1.3	0.7	4.0	9	0.2	1.2	0.2	30	0.06	0.041
KYS 109969	Soil	0.7	30.4	33.0	63	0.1	34.2	15.3	977	3.31	75.8	1.2	7.5	9.7	40	0.3	6.2	0.3	6	1.07	0.051
KYS 110953	Soil	0.4	48.5	36.8	83	<0.1	35.8	18.9	399	3.32	7.0	2.2	2.3	18.1	27	<0.1	0.4	0.5	9	0.28	0.052
KYS 109966	Soil	1.7	48.1	31.3	97	0.3	41.2	16.6	660	3.44	105.6	1.8	8.6	7.1	50	0.3	8.2	0.4	11	0.62	0.073
KYS 110980	Soil	1.8	39.0	28.4	117	0.3	39.9	14.3	738	3.60	173.8	2.6	9.3	5.9	51	0.6	50.5	0.3	18	0.52	0.078
KYS 112016	Soil	0.8	41.1	21.0	101	0.2	35.0	15.4	515	2.80	57.6	1.2	6.5	5.7	33	0.2	47.3	0.3	16	0.96	0.054
KYS 110974	Soil	0.4	44.6	35.2	76	0.2	35.1	14.4	358	3.61	124.4	1.1	6.1	15.0	11	0.1	25.4	0.4	15	0.08	0.057
KYS 110975	Soil	0.6	43.0	32.6	103	<0.1	50.6	19.8	643	4.72	22.3	1.1	4.1	17.3	11	<0.1	5.0	0.4	15	0.16	0.052

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 111557	Soil	19	15	0.44	97	0.003	1	1.29	0.004	0.08	<0.1	0.10	1.9	<0.1	0.06	3	1.4	0.7
KYS 112083	Soil	31	48	0.99	62	0.021	<1	1.84	0.005	0.04	<0.1	0.02	1.8	<0.1	<0.05	6	<0.5	<0.2
KYS 112084	Soil	33	34	0.53	60	0.007	<1	1.30	0.006	0.04	<0.1	0.02	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 112093	Soil	16	23	0.38	114	0.034	<1	1.33	0.007	0.05	0.2	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 112085	Soil	20	30	0.56	60	0.013	<1	1.38	0.005	0.04	0.1	0.01	1.3	<0.1	<0.05	6	<0.5	<0.2
KYS 109938	Soil	22	42	0.82	274	0.002	<1	1.52	0.005	0.06	<0.1	<0.01	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 111547	Soil	10	87	1.79	106	0.115	<1	2.18	0.004	0.11	<0.1	<0.01	3.0	<0.1	0.05	6	<0.5	<0.2
KYS 109934	Soil	18	34	0.71	308	0.003	<1	1.37	0.005	0.06	<0.1	0.02	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 111561	Soil	23	18	0.36	111	0.014	1	1.30	0.011	0.04	<0.1	0.04	2.0	<0.1	<0.05	3	1.3	<0.2
KYS 112089	Soil	22	23	0.37	71	0.025	<1	1.51	0.005	0.05	0.2	0.01	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 112091	Soil	22	22	0.42	95	0.034	<1	1.53	0.007	0.05	0.1	<0.01	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109728	Soil	28	23	0.43	121	0.018	<1	1.35	0.005	0.05	<0.1	0.04	1.2	<0.1	<0.05	4	1.0	<0.2
KYS 109587	Soil	19	19	0.50	133	0.003	2	1.34	0.005	0.10	<0.1	<0.01	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109715	Soil	18	32	0.61	155	0.026	<1	2.08	0.007	0.05	0.2	0.03	2.6	0.1	<0.05	4	<0.5	<0.2
KYS 109723	Soil	18	26	0.42	95	0.031	<1	1.57	0.007	0.04	0.2	0.01	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109721	Soil	17	28	0.49	83	0.037	1	1.40	0.006	0.05	0.2	0.04	2.1	<0.1	0.06	4	<0.5	<0.2
KYS 109720	Soil	17	25	0.48	80	0.035	1	1.38	0.007	0.04	0.2	0.02	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109717	Soil	20	26	0.60	86	0.044	1	1.65	0.007	0.04	0.2	0.02	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109719	Soil	19	26	0.51	86	0.049	2	1.41	0.009	0.05	0.2	0.02	2.1	<0.1	<0.05	4	<0.5	<0.2
KYS 109722	Soil	19	24	0.42	62	0.037	1	1.32	0.007	0.05	0.1	<0.01	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109716	Soil	18	28	0.55	127	0.034	2	1.97	0.011	0.06	0.1	0.03	2.3	<0.1	<0.05	5	0.6	<0.2
KYS 109592	Soil	15	23	0.33	235	0.025	<1	1.34	0.005	0.04	0.1	0.06	2.4	<0.1	<0.05	4	0.8	<0.2
KYS 109724	Soil	23	22	0.49	79	0.029	<1	1.56	0.006	0.05	0.1	<0.01	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109969	Soil	22	8	0.13	284	0.002	2	0.97	0.007	0.12	<0.1	0.01	1.9	<0.1	0.12	1	0.5	<0.2
KYS 110953	Soil	35	16	0.55	204	0.003	<1	1.40	0.006	0.10	<0.1	<0.01	1.0	<0.1	0.07	4	<0.5	<0.2
KYS 109966	Soil	20	14	0.40	86	0.002	1	0.95	0.007	0.07	<0.1	0.02	1.7	<0.1	0.08	2	<0.5	<0.2
KYS 110980	Soil	20	20	0.62	569	0.004	1	1.39	0.005	0.07	<0.1	0.04	1.6	<0.1	0.09	4	0.7	<0.2
KYS 112016	Soil	18	16	0.60	93	0.006	2	1.13	0.008	0.05	<0.1	0.03	1.5	<0.1	0.10	3	0.7	<0.2
KYS 110974	Soil	33	16	0.50	104	0.002	<1	1.52	0.004	0.10	<0.1	<0.01	1.4	<0.1	0.10	4	<0.5	<0.2
KYS 110975	Soil	27	29	0.98	61	0.002	1	1.99	0.006	0.06	<0.1	<0.01	1.5	<0.1	0.08	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110973	Soil	0.6	52.9	61.2	81	1.1	28.7	13.9	384	3.73	501.1	1.2	41.2	13.2	14	0.1	92.4	0.3	9	0.07	0.046
KYS 110972	Soil	0.8	19.2	23.6	49	<0.1	21.6	12.6	461	2.25	270.3	0.7	15.0	7.0	12	0.1	42.1	0.2	27	0.12	0.050
KYS 110971	Soil	0.8	26.5	23.0	63	0.1	18.5	9.6	403	3.18	285.1	0.9	33.0	3.4	5	0.1	19.7	0.3	16	0.04	0.042
KYS 110970	Soil	1.1	41.2	26.0	88	0.2	31.5	13.9	546	3.55	413.4	1.5	62.2	7.4	11	0.1	16.0	0.4	13	0.12	0.049
KYS 112277	Soil	0.9	33.6	14.5	55	0.8	30.7	9.3	391	2.39	50.8	1.3	11.1	1.0	39	0.3	5.7	0.2	24	0.75	0.071
KYS 112262	Soil	1.1	22.9	18.5	63	<0.1	21.4	8.3	402	3.32	128.0	0.8	4.2	0.7	13	0.2	2.2	0.3	35	0.22	0.039
KYS 111725	Soil	0.6	26.7	44.1	112	<0.1	22.1	11.9	857	2.29	26.5	1.2	1.3	2.1	59	0.3	1.0	0.2	6	1.94	0.077
KYS 112269	Soil	1.3	14.7	18.8	61	<0.1	16.6	8.5	311	2.95	16.1	0.7	1.6	2.8	8	0.2	0.7	0.2	50	0.09	0.042
KYS 111726	Soil	0.9	15.0	26.5	53	<0.1	16.6	6.8	352	2.51	20.3	0.6	1.4	4.7	5	<0.1	1.6	0.2	26	0.05	0.033

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000187.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110973	Soil	19	15	0.47	62	0.003	1	1.13	0.004	0.10	<0.1	0.03	0.9	<0.1	0.06	3	0.6	<0.2
KYS 110972	Soil	16	16	0.28	74	0.019	1	0.82	0.004	0.08	0.3	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 110971	Soil	18	15	0.42	48	0.003	<1	1.19	0.003	0.04	0.1	0.03	0.7	<0.1	<0.05	4	<0.5	0.2
KYS 110970	Soil	20	15	0.48	82	0.004	<1	1.10	0.003	0.04	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 112277	Soil	9	17	0.32	154	0.007	2	1.19	0.007	0.04	<0.1	0.09	1.7	<0.1	0.06	3	2.3	<0.2
KYS 112262	Soil	14	22	0.45	61	0.012	<1	1.30	0.004	0.04	<0.1	0.03	0.8	<0.1	<0.05	4	0.6	<0.2
KYS 111725	Soil	6	9	0.20	77	0.002	2	0.73	0.004	0.04	<0.1	0.07	1.1	<0.1	0.11	2	0.7	<0.2
KYS 112269	Soil	13	25	0.42	105	0.028	1	1.65	0.005	0.05	0.2	0.05	1.7	0.1	<0.05	5	<0.5	<0.2
KYS 111726	Soil	20	14	0.24	41	0.009	<1	0.94	0.004	0.04	0.1	0.02	0.9	<0.1	<0.05	4	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
KYS 109574	Soil	2.9	70.7	27.3	80	0.7	22.1	4.1	139	3.84	16.4	1.3	8.5	2.7	18	0.4	3.2	0.5	33	0.02	0.099
REP KYS 109574	QC	2.9	71.2	27.7	82	0.7	21.9	4.2	135	3.89	16.4	1.3	10.0	2.9	18	0.4	3.2	0.5	35	0.02	0.099
KYS 112134	Soil	1.0	32.8	15.4	67	<0.1	30.1	12.8	427	2.85	32.2	1.3	8.5	6.6	10	0.2	1.6	0.2	38	0.07	0.038
REP KYS 112134	QC	1.0	31.1	15.2	67	<0.1	29.0	12.4	412	2.75	31.5	1.3	2.5	6.3	9	0.2	1.5	0.2	37	0.07	0.036
KYS 109947	Soil	0.4	26.4	22.6	64	<0.1	21.4	11.3	325	2.82	10.5	0.9	1.1	13.3	16	<0.1	0.9	0.3	9	0.19	0.043
REP KYS 109947	QC	0.5	27.8	22.4	64	<0.1	22.0	11.4	318	2.79	10.4	0.9	1.1	13.3	16	<0.1	0.8	0.3	8	0.19	0.043
KYS 111716	Soil	0.6	68.3	15.7	77	<0.1	65.0	25.0	520	3.70	78.4	0.8	3.6	3.2	23	0.1	0.7	0.2	53	0.50	0.148
REP KYS 111716	QC	0.6	71.3	15.8	80	<0.1	65.7	26.0	526	3.71	78.5	0.8	3.1	3.4	24	<0.1	0.7	0.2	55	0.51	0.148
KYS 112153	Soil	1.1	39.2	33.2	95	0.2	38.9	14.7	614	3.10	147.5	1.4	18.2	10.5	34	0.2	184.6	0.3	13	1.23	0.052
REP KYS 112153	QC	1.0	40.2	32.7	92	0.2	36.6	14.2	619	3.07	145.4	1.4	18.6	10.1	33	0.2	173.3	0.4	13	1.20	0.052
KYS 112052	Soil	1.2	24.1	21.0	51	0.3	25.4	7.9	191	2.58	10.2	1.4	3.2	7.0	9	0.1	0.9	0.2	28	0.06	0.049
REP KYS 112052	QC	1.3	23.7	21.2	51	0.3	26.3	7.7	191	2.57	10.1	1.5	3.6	6.8	8	0.2	1.0	0.2	27	0.05	0.049
KYS 112107	Soil	0.7	41.9	23.3	72	<0.1	40.5	15.0	453	3.07	16.8	1.5	2.0	11.9	20	0.1	1.1	0.3	7	0.33	0.044
REP KYS 112107	QC	0.7	41.9	22.4	72	<0.1	38.4	15.0	448	3.05	16.2	1.4	2.2	11.4	20	<0.1	1.0	0.2	8	0.35	0.044
KYS 111692	Soil	1.5	11.0	9.0	25	0.2	7.5	2.1	67	1.53	9.2	0.7	1.9	0.5	9	<0.1	0.6	0.2	39	0.06	0.077
REP KYS 111692	QC	1.6	10.6	9.2	27	0.2	7.8	2.2	70	1.63	9.6	0.7	2.5	0.1	10	<0.1	0.6	0.3	42	0.06	0.084
KYS 112326	Soil	0.6	14.7	17.9	41	<0.1	13.5	6.0	162	1.92	45.2	0.9	1.4	2.1	18	0.1	0.9	0.2	20	0.24	0.074
REP KYS 112326	QC	0.6	14.2	17.6	40	<0.1	14.0	5.8	163	1.89	43.9	0.9	0.8	2.0	18	<0.1	0.9	0.2	20	0.23	0.074
KYS 109904	Soil	2.4	38.9	17.7	131	0.2	49.9	17.2	606	3.33	177.8	1.4	15.6	6.6	9	0.4	9.0	0.2	26	0.04	0.050
REP KYS 109904	QC	2.4	38.4	17.7	126	0.2	52.8	19.0	638	3.48	172.4	1.3	15.2	6.3	8	0.4	8.5	0.2	27	0.04	0.054
KYS 112080	Soil	0.8	29.1	19.9	72	<0.1	31.6	11.2	314	3.69	20.2	1.4	2.1	7.5	6	<0.1	0.4	0.2	14	0.05	0.045
REP KYS 112080	QC	0.8	31.7	21.6	77	<0.1	34.2	11.3	301	3.63	21.0	1.4	1.8	7.4	6	<0.1	0.4	0.2	16	0.06	0.040
KYS 109869	Soil	2.6	58.9	25.0	81	0.4	23.3	6.9	239	3.63	18.9	1.3	6.3	2.2	20	0.2	2.7	0.5	44	0.02	0.105
REP KYS 109869	QC	2.4	56.9	26.6	81	0.5	24.0	6.7	234	3.61	18.8	1.3	5.8	2.3	20	0.2	2.7	0.5	44	0.03	0.102
KYS 112082	Soil	0.9	47.0	23.4	73	0.2	38.6	14.2	431	4.24	21.4	2.4	6.4	2.8	8	<0.1	0.4	0.2	27	0.05	0.091
REP KYS 112082	QC	0.9	46.1	23.1	71	0.2	35.1	13.9	413	4.06	21.4	2.3	4.4	3.5	8	<0.1	0.4	0.2	25	0.04	0.087
KYS 109998	Soil	1.4	25.6	20.4	72	<0.1	26.1	10.3	346	3.19	14.4	0.8	1.0	4.8	8	0.2	0.7	0.3	46	0.08	0.031
REP KYS 109998	QC	1.5	29.4	23.7	75	<0.1	26.9	12.3	353	3.25	17.0	0.9	1.5	5.3	11	0.2	0.9	0.4	51	0.07	0.037

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000187.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
KYS 109574	Soil	10	23	0.20	259	0.002	<1	1.22	0.010	0.05	<0.1	0.12	2.1	<0.1	0.06	4	2.6	<0.2
REP KYS 109574	QC	10	24	0.20	268	0.002	<1	1.24	0.010	0.05	<0.1	0.13	2.1	<0.1	0.07	4	2.7	<0.2
KYS 112134	Soil	19	26	0.45	131	0.037	2	1.60	0.007	0.05	0.2	0.04	2.7	<0.1	<0.05	4	<0.5	<0.2
REP KYS 112134	QC	17	24	0.43	125	0.035	1	1.55	0.006	0.05	0.1	0.04	2.5	<0.1	<0.05	4	0.5	<0.2
KYS 109947	Soil	22	14	0.43	51	0.002	1	1.11	0.005	0.07	<0.1	0.02	0.9	<0.1	<0.05	3	<0.5	<0.2
REP KYS 109947	QC	22	13	0.43	51	0.003	1	1.08	0.005	0.08	<0.1	0.02	0.9	<0.1	<0.05	3	<0.5	<0.2
KYS 111716	Soil	13	79	1.65	225	0.112	<1	2.18	0.004	0.05	<0.1	0.01	3.4	<0.1	<0.05	6	<0.5	<0.2
REP KYS 111716	QC	14	79	1.66	226	0.124	1	2.18	0.005	0.05	<0.1	0.01	3.4	<0.1	<0.05	6	<0.5	<0.2
KYS 112153	Soil	20	20	0.95	59	0.006	1	1.01	0.006	0.05	<0.1	0.04	1.3	<0.1	<0.05	3	0.8	<0.2
REP KYS 112153	QC	19	19	0.92	58	0.005	2	0.98	0.005	0.04	<0.1	0.02	1.3	<0.1	<0.05	3	0.8	<0.2
KYS 112052	Soil	20	23	0.38	70	0.021	<1	1.39	0.005	0.04	0.2	0.04	1.5	<0.1	<0.05	3	0.8	<0.2
REP KYS 112052	QC	21	23	0.38	70	0.021	<1	1.38	0.005	0.03	0.1	0.05	1.6	<0.1	<0.05	3	0.7	<0.2
KYS 112107	Soil	21	16	0.52	56	0.001	1	1.06	0.004	0.15	<0.1	0.02	1.0	<0.1	<0.05	3	<0.5	<0.2
REP KYS 112107	QC	21	17	0.54	53	0.001	<1	1.05	0.004	0.15	<0.1	0.03	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 111692	Soil	9	18	0.12	64	0.011	1	0.99	0.005	0.05	0.1	0.07	0.3	0.1	0.07	6	0.5	<0.2
REP KYS 111692	QC	9	19	0.12	69	0.010	1	1.04	0.006	0.05	0.1	0.07	0.3	0.1	0.07	6	0.7	<0.2
KYS 112326	Soil	12	14	0.18	125	0.007	<1	0.85	0.004	0.07	0.1	0.02	0.9	0.1	<0.05	2	<0.5	<0.2
REP KYS 112326	QC	12	13	0.17	122	0.006	<1	0.81	0.002	0.07	0.1	0.02	0.8	<0.1	<0.05	2	<0.5	<0.2
KYS 109904	Soil	13	23	0.40	156	0.005	<1	1.58	0.004	0.04	0.2	0.07	1.4	<0.1	<0.05	4	1.5	0.2
REP KYS 109904	QC	12	23	0.39	155	0.005	<1	1.60	0.004	0.04	0.2	0.07	1.5	<0.1	<0.05	3	1.3	<0.2
KYS 112080	Soil	25	20	0.66	28	0.005	<1	1.44	0.003	0.04	<0.1	0.03	0.7	<0.1	<0.05	4	<0.5	<0.2
REP KYS 112080	QC	25	21	0.67	27	0.005	<1	1.41	0.004	0.05	<0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109869	Soil	10	26	0.25	256	0.008	<1	1.60	0.010	0.05	0.1	0.11	2.1	<0.1	0.09	5	1.9	<0.2
REP KYS 109869	QC	11	26	0.24	256	0.009	<1	1.60	0.010	0.05	0.1	0.10	2.2	<0.1	0.10	4	2.0	<0.2
KYS 112082	Soil	31	41	0.90	65	0.009	<1	1.87	0.006	0.05	<0.1	0.03	1.2	<0.1	<0.05	6	<0.5	<0.2
REP KYS 112082	QC	30	39	0.87	64	0.009	<1	1.83	0.006	0.05	<0.1	0.04	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 109998	Soil	15	29	0.50	135	0.024	<1	1.93	0.007	0.06	0.1	0.04	2.1	0.1	<0.05	5	0.5	<0.2
REP KYS 109998	QC	16	28	0.52	148	0.028	<1	1.97	0.008	0.05	0.2	0.03	2.5	0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000187.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
KYS 112012	Soil	2.7	49.0	23.6	157	0.5	58.5	17.9	1161	3.88	20.0	2.2	25.8	7.3	14	1.4	3.2	0.4	16	0.16	0.058
REP KYS 112012	QC	3.0	51.3	24.1	161	0.5	59.6	17.7	1164	3.85	21.6	2.3	6.9	7.8	15	1.5	3.2	0.4	16	0.17	0.059
KYS 109965	Soil	0.5	36.3	23.6	81	<0.1	39.3	16.7	351	3.41	15.5	1.3	2.3	15.0	20	<0.1	0.6	0.2	7	0.26	0.045
REP KYS 109965	QC	0.5	36.4	23.3	82	<0.1	37.6	16.3	356	3.37	15.6	1.3	2.1	14.4	20	<0.1	0.5	0.2	7	0.26	0.046
KYS 112263	Soil	0.7	30.4	21.5	71	<0.1	31.9	15.6	543	3.13	14.3	1.0	<0.5	5.0	7	0.1	1.1	0.3	19	0.05	0.036
REP KYS 112263	QC	0.7	29.4	21.2	71	<0.1	32.3	14.9	520	3.01	14.9	0.9	24.2	4.5	7	0.1	1.1	0.3	18	0.05	0.034
KYS 112317	Soil	4.7	186.5	6.6	70	0.2	96.1	47.0	1360	6.18	7.5	0.8	4.9	3.3	32	0.3	0.4	0.2	42	0.73	0.267
REP KYS 112317	QC	4.9	191.5	6.8	71	0.2	96.9	48.8	1393	6.41	7.8	0.8	5.2	3.3	32	0.3	0.4	0.2	41	0.73	0.267
KYS 112085	Soil	0.9	21.2	18.4	50	0.2	18.5	8.2	293	3.06	15.0	0.6	3.2	3.0	8	<0.1	0.6	0.2	38	0.08	0.039
REP KYS 112085	QC	0.9	21.5	17.8	48	0.2	17.7	8.2	309	3.00	14.9	0.6	2.3	3.2	8	<0.1	0.6	0.3	39	0.08	0.038
KYS 109720	Soil	0.9	17.7	12.0	57	<0.1	19.1	8.6	390	2.39	15.8	0.8	1.4	2.8	14	0.1	0.6	0.2	36	0.14	0.077
REP KYS 109720	QC	0.9	16.8	11.3	58	<0.1	17.5	8.5	390	2.48	15.5	0.8	1.0	3.0	13	0.3	0.6	0.2	38	0.17	0.082
Reference Materials																					
STD DS7	Standard	22.8	106.7	69.1	408	1.0	59.2	10.3	720	2.60	46.2	4.8	70.7	4.6	84	6.3	5.6	4.4	91	1.03	0.077
STD DS7	Standard	21.8	133.6	69.6	445	1.1	61.7	10.3	680	2.58	57.1	5.1	89.4	4.9	80	7.6	7.0	5.2	94	1.04	0.086
STD DS7	Standard	24.2	131.1	70.1	451	1.1	66.1	10.7	667	2.60	57.9	5.2	73.0	5.2	80	7.3	6.7	5.1	96	1.05	0.083
STD DS7	Standard	17.5	85.2	60.8	396	0.9	50.3	7.3	514	2.18	45.7	3.8	70.9	3.7	74	5.1	4.9	3.7	75	0.96	0.071
STD DS7	Standard	19.9	91.7	63.6	380	0.9	50.1	8.9	608	2.34	51.9	4.6	68.7	4.3	73	6.1	5.6	4.4	81	0.89	0.076
STD DS7	Standard	22.1	114.4	64.1	405	0.9	57.3	9.4	636	2.37	50.8	4.5	65.0	4.5	85	5.8	5.8	4.8	92	0.98	0.081
STD DS7	Standard	21.2	107.2	68.7	401	1.0	60.3	10.1	650	2.47	50.2	4.7	73.6	4.4	71	6.5	5.9	4.8	87	0.97	0.078
STD DS7	Standard	22.0	122.3	67.8	418	1.0	59.7	11.0	641	2.43	60.2	5.0	70.2	4.9	75	7.1	6.5	5.1	97	0.96	0.088
STD DS7	Standard	20.6	106.6	76.7	397	1.0	56.1	9.1	627	2.36	51.5	5.6	72.8	5.7	92	6.4	7.0	5.2	84	0.96	0.076
STD DS7	Standard	20.1	108.0	57.9	387	1.4	54.8	9.1	616	2.36	50.3	4.2	67.7	3.9	66	5.6	4.9	4.1	86	0.92	0.078
STD DS7	Standard	21.5	111.2	71.2	408	1.0	58.4	9.8	632	2.46	51.0	4.9	82.4	4.8	79	5.9	5.6	4.6	87	0.96	0.074
STD DS7	Standard	20.5	108.7	60.1	402	1.0	57.0	9.2	626	2.41	50.8	4.3	113.9	4.0	65	6.5	5.1	4.1	85	0.93	0.075
STD DS7	Standard	22.7	122.3	73.2	410	1.1	59.2	10.0	624	2.39	51.6	5.0	68.2	5.0	79	6.2	6.4	4.7	89	0.89	0.075
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000187.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
KYS 112012	Soil	14	25	0.35	114	0.006	<1	1.00	0.005	0.05	<0.1	0.07	1.6	<0.1	<0.05	3	1.2	<0.2
REP KYS 112012	QC	13	26	0.35	107	0.001	2	1.05	0.005	0.05	<0.1	0.07	1.8	<0.1	<0.05	3	1.1	<0.2
KYS 109965	Soil	24	19	0.60	257	0.002	2	1.14	0.004	0.10	<0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
REP KYS 109965	QC	23	19	0.60	259	0.002	<1	1.17	0.004	0.09	<0.1	0.02	0.9	<0.1	<0.05	3	<0.5	<0.2
KYS 112263	Soil	16	20	0.57	67	0.010	<1	1.34	0.003	0.04	<0.1	0.02	1.0	<0.1	<0.05	3	<0.5	<0.2
REP KYS 112263	QC	17	19	0.54	67	0.009	<1	1.29	0.002	0.04	<0.1	0.02	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 112317	Soil	14	64	1.28	203	0.021	1	1.78	0.004	0.04	<0.1	0.08	5.3	<0.1	0.12	5	0.7	0.5
REP KYS 112317	QC	14	66	1.32	207	0.021	1	1.83	0.005	0.04	<0.1	0.08	5.5	<0.1	0.13	5	1.1	<0.2
KYS 112085	Soil	20	30	0.56	60	0.013	<1	1.38	0.005	0.04	0.1	0.01	1.3	<0.1	<0.05	6	<0.5	<0.2
REP KYS 112085	QC	19	30	0.51	59	0.014	<1	1.43	0.005	0.05	0.1	<0.01	1.3	<0.1	<0.05	6	<0.5	<0.2
KYS 109720	Soil	17	25	0.48	80	0.035	1	1.38	0.007	0.04	0.2	0.02	1.7	<0.1	<0.05	4	<0.5	<0.2
REP KYS 109720	QC	16	25	0.43	81	0.035	<1	1.34	0.008	0.04	0.2	<0.01	1.8	<0.1	<0.05	4	<0.5	<0.2
Reference Materials																		
STD DS7	Standard	14	256	1.13	431	0.121	41	1.12	0.114	0.53	3.7	0.23	2.2	4.4	0.22	5	3.0	1.3
STD DS7	Standard	14	225	1.12	436	0.153	42	1.11	0.110	0.52	4.2	0.24	3.1	4.3	0.22	6	3.5	1.5
STD DS7	Standard	14	217	1.16	440	0.156	44	1.14	0.112	0.53	3.9	0.24	2.8	4.2	0.22	5	3.4	1.2
STD DS7	Standard	11	214	1.10	393	0.091	41	0.97	0.104	0.50	3.8	0.21	1.9	3.8	0.39	5	3.0	1.2
STD DS7	Standard	12	207	1.02	372	0.107	41	1.02	0.102	0.46	3.6	0.22	2.6	3.9	0.20	5	3.0	0.9
STD DS7	Standard	14	217	1.05	396	0.142	39	1.09	0.107	0.46	3.3	0.24	2.4	3.8	0.21	5	3.3	0.9
STD DS7	Standard	13	234	1.06	451	0.113	47	1.03	0.102	0.49	3.8	0.23	2.5	4.2	0.21	5	3.4	1.2
STD DS7	Standard	14	187	1.04	419	0.141	41	1.02	0.103	0.47	3.6	0.22	3.0	4.2	0.17	5	3.3	1.3
STD DS7	Standard	15	212	1.02	407	0.147	42	1.00	0.100	0.47	3.8	0.24	2.6	4.0	0.17	5	2.9	0.9
STD DS7	Standard	12	211	1.05	391	0.126	39	1.00	0.098	0.47	3.4	0.21	2.2	3.8	0.23	5	2.9	1.7
STD DS7	Standard	14	221	1.10	406	0.131	38	1.09	0.103	0.49	4.0	0.23	2.5	4.3	0.20	5	3.6	1.4
STD DS7	Standard	12	210	1.03	388	0.106	36	0.99	0.109	0.48	3.5	0.22	2.4	3.9	0.17	5	2.8	1.0
STD DS7	Standard	14	201	1.02	408	0.137	39	1.00	0.099	0.47	3.8	0.22	2.3	4.0	0.19	5	2.6	1.1
STD DS7 Expected		12	179	1.05	410	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5	1.08
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000187.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000187.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Submitted By: Johnathan More
Receiving Lab: Canada-Whitehorse
Received: July 28, 2010
Report Date: August 18, 2010
Page: 1 of 13

CERTIFICATE OF ANALYSIS WHI10000186.1

CLIENT JOB INFORMATION

Project: KYS
Shipment ID: KYS2
P.O. Number
Number of Samples: 360

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	360	Dry at 60C sieve 100g to -80 mesh			WHI
Dry at 60C	360	Dry at 60C			WHI
1DX2	360	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Aldrin Resources
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5
Canada

CC: Shawn Ryan
Isaac Fage
Bert Jeffries

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109962	Soil	1.1	68.8	32.1	103	0.1	50.2	20.7	446	3.51	11.8	2.7	3.6	12.5	31	0.4	0.9	0.5	13	0.58	0.073
KYS 109667	Soil	0.6	35.6	24.2	80	0.1	32.4	13.6	416	3.34	17.8	1.5	1.4	8.4	24	<0.1	1.3	0.3	10	0.25	0.042
KYS 109668	Soil	0.5	30.4	24.0	83	<0.1	26.8	12.4	373	3.12	12.3	1.1	1.6	5.7	24	<0.1	0.9	0.3	16	0.22	0.054
KYS 109673	Soil	1.1	33.0	26.0	68	<0.1	31.8	14.6	671	3.07	21.4	0.8	2.8	8.6	10	0.2	1.2	0.2	25	0.12	0.067
KYS 109670	Soil	1.0	38.4	28.1	91	<0.1	35.5	16.9	498	3.79	54.6	1.4	4.5	10.0	15	0.1	1.8	0.4	20	0.16	0.042
KYS 109669	Soil	0.5	34.7	26.5	82	<0.1	34.2	17.9	573	3.49	23.5	1.1	1.8	12.4	11	<0.1	0.7	0.3	9	0.12	0.036
KYS 109956	Soil	0.9	22.8	17.4	103	<0.1	33.7	15.7	387	3.35	61.1	0.9	4.3	9.5	26	0.1	3.4	0.2	15	0.48	0.053
KYS 109961	Soil	2.5	58.9	22.9	134	0.2	47.7	16.1	437	3.51	10.5	2.3	2.5	12.1	25	0.9	1.1	0.3	10	0.33	0.056
KYS 109959	Soil	1.7	47.3	25.6	102	0.2	43.7	19.2	756	3.79	15.6	2.1	2.4	9.2	26	0.4	1.6	0.4	15	0.45	0.060
KYS 109654	Soil	35.4	73.7	57.2	249	1.5	67.7	9.7	218	4.99	95.4	5.5	7.7	3.4	27	2.5	90.6	0.2	125	0.04	0.207
KYS 109957	Soil	1.1	41.2	21.1	81	<0.1	40.6	18.2	772	3.23	62.8	1.6	4.8	7.1	44	0.2	3.8	0.3	13	0.81	0.061
KYS 109960	Soil	2.7	61.9	23.1	146	0.2	50.9	16.7	444	3.82	11.5	2.3	1.9	12.7	24	0.9	1.5	0.3	11	0.32	0.055
KYS 109636	Soil	1.3	48.7	56.5	172	2.1	41.3	18.5	688	3.83	1196	1.5	98.4	9.5	23	0.6	1432	0.3	8	0.19	0.048
KYS 109893	Soil	1.2	44.1	44.8	82	<0.1	28.2	20.3	1573	3.58	20.6	0.8	1.8	5.7	7	0.2	1.3	0.4	26	0.07	0.077
KYS 112166	Soil	1.0	42.4	24.0	94	0.1	38.4	16.4	608	3.72	158.1	1.0	13.4	12.5	15	<0.1	60.8	0.3	13	0.27	0.061
KYS 112169	Soil	0.9	42.0	32.2	93	0.5	35.0	12.5	558	3.29	444.4	1.4	50.0	6.5	28	0.1	397.0	0.3	10	0.50	0.057
KYS 109632	Soil	0.9	56.1	40.3	72	0.4	29.7	14.2	328	3.15	127.4	2.5	9.1	2.7	41	0.1	33.7	0.4	18	0.36	0.051
KYS 112165	Soil	0.7	46.2	28.4	95	0.2	42.9	19.6	836	3.91	119.9	1.1	11.6	7.9	16	0.1	10.8	0.4	14	0.29	0.058
KYS 112168	Soil	1.3	47.2	31.2	99	0.3	41.5	18.2	684	3.76	288.6	1.3	29.5	12.9	16	0.1	226.7	0.3	10	0.25	0.061
KYS 112167	Soil	1.0	41.1	28.6	94	0.4	35.1	14.9	547	3.58	343.9	1.1	45.0	10.1	17	0.1	282.8	0.3	10	0.29	0.056
KYS 109633	Soil	0.7	51.0	32.3	109	0.4	40.8	24.2	816	3.76	592.1	1.6	53.4	6.1	36	0.2	143.9	0.4	11	0.47	0.055
KYS 109634	Soil	1.2	50.0	139.4	141	3.7	41.0	18.7	707	3.93	1621	1.5	229.6	11.1	24	1.0	1121	0.3	8	0.16	0.042
KYS 109954	Soil	0.7	29.7	15.5	97	<0.1	53.5	19.7	520	4.12	201.0	2.2	3.3	12.2	17	<0.1	10.3	0.2	14	0.15	0.047
KYS 109952	Soil	0.9	33.1	33.4	97	<0.1	44.6	19.1	887	3.43	26.1	1.1	1.0	11.5	9	0.2	6.7	0.3	22	0.11	0.060
KYS 112068	Soil	1.0	38.0	14.8	80	<0.1	32.4	11.9	359	4.60	25.5	0.7	<0.5	10.2	3	<0.1	6.7	0.3	34	0.02	0.037
KYS 112100	Soil	1.4	44.2	13.9	89	<0.1	52.3	40.0	990	4.27	17.5	1.5	<0.5	16.3	4	<0.1	3.0	0.3	17	0.02	0.025
KYS 11207A	Soil	1.1	32.1	14.9	74	0.1	28.7	12.2	388	2.62	16.5	1.1	2.4	4.8	18	0.2	1.7	0.2	34	0.26	0.064
KYS 112069	Soil	2.0	44.7	27.6	74	0.2	24.5	7.1	251	4.39	19.7	1.3	2.1	8.5	16	<0.1	2.4	0.5	27	0.07	0.058
KYS 112096	Soil	1.1	47.3	13.3	84	0.3	33.1	21.3	556	2.97	62.5	1.3	6.1	4.1	22	0.2	6.1	0.2	29	0.37	0.066
KYS 109578	Soil	5.7	53.7	28.6	140	0.3	54.4	20.0	755	4.08	30.5	2.1	7.0	5.8	13	0.7	6.3	0.3	34	0.04	0.086

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109962	Soil	13	20	0.61	300	0.002	2	1.27	0.004	0.07	<0.1	0.04	1.2	<0.1	0.06	3	0.5	<0.2
KYS 109667	Soil	14	17	0.44	94	0.002	1	1.38	0.004	0.07	<0.1	0.03	0.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109668	Soil	9	18	0.37	139	0.003	2	1.39	0.004	0.07	<0.1	0.04	0.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109673	Soil	18	24	0.41	116	0.018	1	1.54	0.004	0.05	0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109670	Soil	21	26	0.59	87	0.005	1	1.66	0.003	0.04	<0.1	0.02	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 109669	Soil	21	20	0.59	76	0.002	1	1.48	0.003	0.06	<0.1	0.01	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109956	Soil	18	28	0.67	587	0.003	1	1.21	0.004	0.07	<0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109961	Soil	20	16	0.50	112	0.004	1	1.10	0.003	0.07	<0.1	0.06	1.1	<0.1	<0.05	3	1.0	<0.2
KYS 109959	Soil	14	23	0.65	178	0.002	1	1.31	0.004	0.06	<0.1	0.04	1.7	<0.1	<0.05	4	0.5	<0.2
KYS 109654	Soil	11	28	0.17	2852	0.015	<1	1.76	0.005	0.06	0.5	0.35	2.6	0.3	<0.05	5	5.3	<0.2
KYS 109957	Soil	13	25	0.63	385	0.002	1	1.22	0.004	0.07	<0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109960	Soil	21	17	0.54	217	0.003	1	1.09	0.004	0.07	<0.1	0.06	1.1	<0.1	<0.05	3	0.9	<0.2
KYS 109636	Soil	21	12	0.30	899	0.002	2	0.86	0.004	0.13	<0.1	0.04	1.0	<0.1	<0.05	2	0.6	<0.2
KYS 109893	Soil	18	20	0.35	73	0.010	<1	1.21	0.003	0.05	0.1	0.02	1.0	<0.1	<0.05	5	0.6	<0.2
KYS 112166	Soil	28	16	0.56	64	0.006	<1	1.20	0.005	0.08	<0.1	0.02	1.2	<0.1	<0.05	4	<0.5	0.3
KYS 112169	Soil	18	15	0.41	90	0.003	1	1.03	0.004	0.07	<0.1	0.05	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 109632	Soil	15	17	0.34	64	0.006	1	1.00	0.007	0.07	<0.1	0.03	0.9	<0.1	<0.05	3	<0.5	<0.2
KYS 112165	Soil	23	19	0.56	81	0.006	1	1.34	0.005	0.07	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112168	Soil	30	18	0.52	69	0.003	<1	1.25	0.005	0.08	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 112167	Soil	25	16	0.45	75	0.003	<1	1.06	0.004	0.08	<0.1	0.03	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 109633	Soil	15	16	0.52	66	0.004	1	1.21	0.006	0.11	<0.1	0.03	1.1	<0.1	<0.05	3	0.6	<0.2
KYS 109634	Soil	23	13	0.34	336	0.004	2	0.86	0.007	0.13	<0.1	0.06	1.2	<0.1	<0.05	2	0.7	<0.2
KYS 109954	Soil	38	26	0.63	133	0.005	1	1.32	0.003	0.12	<0.1	0.01	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109952	Soil	24	24	0.49	142	0.013	<1	1.60	0.004	0.06	<0.1	0.02	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112068	Soil	28	31	0.91	46	0.010	<1	2.24	<0.001	0.04	<0.1	0.02	1.3	<0.1	<0.05	8	0.5	<0.2
KYS 112100	Soil	41	30	1.07	68	0.005	<1	2.28	0.004	0.06	<0.1	0.02	1.4	<0.1	<0.05	6	<0.5	<0.2
KYS 11207A	Soil	21	24	0.45	190	0.030	2	1.23	0.007	0.06	0.2	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 112069	Soil	30	22	0.58	61	0.008	<1	1.42	0.004	0.05	<0.1	0.03	0.8	<0.1	<0.05	5	1.0	<0.2
KYS 112096	Soil	15	19	0.30	127	0.020	1	0.86	0.007	0.04	0.1	0.05	2.1	<0.1	<0.05	3	0.9	<0.2
KYS 109578	Soil	21	23	0.38	424	0.011	1	1.52	0.004	0.06	0.1	0.08	1.4	<0.1	<0.05	4	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109672	Soil	1.2	40.7	27.1	87	0.1	40.9	15.5	794	3.54	22.4	0.9	2.6	10.2	15	0.1	1.1	0.3	17	0.24	0.059
KYS 109579	Soil	4.9	56.6	28.0	144	0.3	57.1	21.0	741	4.12	28.8	2.0	5.0	6.4	13	0.6	6.2	0.3	32	0.04	0.082
KYS 109596	Soil	1.0	23.5	16.7	68	0.1	25.6	11.6	1400	2.83	21.4	0.9	2.9	3.3	30	0.2	1.3	0.2	19	0.66	0.057
KYS 109671	Soil	0.6	34.0	24.1	97	0.2	33.6	14.7	812	2.96	11.4	2.7	1.2	7.1	29	<0.1	0.7	0.3	17	0.36	0.069
KYS 109963	Soil	0.8	66.3	32.0	87	0.1	49.7	24.4	845	3.63	18.4	1.6	1.5	12.6	34	0.2	1.3	0.4	15	0.58	0.052
KYS 109666	Soil	0.6	18.2	15.4	74	<0.1	24.5	9.1	248	2.83	17.2	0.8	0.8	4.7	18	<0.1	0.7	0.3	17	0.21	0.061
KYS 112164	Soil	2.7	53.1	32.5	100	0.1	38.7	20.6	692	3.86	261.8	1.9	24.1	15.0	20	0.2	129.7	0.3	10	0.12	0.058
KYS 112170	Soil	0.7	35.0	39.6	97	0.9	26.6	12.9	567	3.05	647.6	1.7	78.3	4.9	44	0.2	769.4	0.3	7	0.56	0.048
KYS 109635	Soil	0.5	29.3	277.2	86	1.4	20.4	9.5	289	2.92	1220	1.0	112.7	13.0	9	0.7	134.8	0.3	7	0.07	0.045
KYS 109674	Soil	1.0	8.8	14.8	35	0.1	9.7	5.0	213	2.39	16.2	0.5	1.5	2.7	7	<0.1	1.2	0.2	39	0.05	0.041
KYS 109925	Soil	2.6	47.3	32.7	139	0.4	36.1	15.5	669	3.70	187.5	1.5	18.7	6.8	22	1.1	57.7	0.3	18	0.31	0.096
KYS 112097	Soil	1.0	46.9	14.1	79	0.3	29.7	20.6	552	2.82	58.6	1.6	7.6	4.9	22	0.2	6.5	0.2	26	0.35	0.070
KYS 109598	Soil	1.0	21.2	18.9	58	0.1	20.8	10.4	364	2.72	25.2	1.0	1.9	2.5	19	0.2	1.1	0.2	32	0.28	0.051
KYS 109599	Soil	0.7	20.2	17.4	57	<0.1	19.6	9.5	397	2.72	28.0	0.8	2.3	3.0	16	<0.1	1.2	0.2	23	0.24	0.047
KYS 112099	Soil	1.2	59.6	32.7	84	<0.1	28.2	11.8	328	4.14	23.1	2.0	2.5	14.8	9	<0.1	7.5	0.4	19	0.03	0.056
KYS 109926	Soil	2.4	47.0	35.2	117	0.3	36.6	16.7	748	3.79	176.5	1.8	14.1	8.1	18	0.6	39.0	0.3	19	0.19	0.079
KYS 109922	Soil	3.4	46.4	27.9	198	0.4	38.2	14.3	527	3.83	251.6	1.5	21.7	9.2	19	1.6	41.3	0.3	18	0.22	0.094
KYS 112098	Soil	1.2	59.5	32.5	88	<0.1	28.6	11.7	338	4.30	21.6	2.0	3.1	15.8	9	<0.1	7.3	0.4	19	0.04	0.055
KYS 109711	Soil	0.8	28.8	18.7	73	<0.1	26.8	12.4	373	2.77	38.2	1.0	3.8	7.0	14	0.2	1.1	0.2	31	0.14	0.076
KYS 109713	Soil	1.0	28.6	14.1	68	<0.1	26.2	12.7	445	2.80	25.4	0.9	2.1	5.2	13	0.2	1.0	0.2	41	0.14	0.074
KYS 110984	Soil	0.9	35.9	21.3	80	<0.1	35.6	16.5	580	3.21	49.9	1.2	4.9	8.5	41	0.3	3.1	0.2	14	0.72	0.051
KYS 110982	Soil	1.0	42.8	23.5	97	0.1	43.4	19.2	615	3.71	70.3	1.5	5.7	11.9	22	0.3	4.0	0.3	14	0.37	0.060
KYS 109693	Soil	1.0	74.5	37.3	105	0.2	51.6	23.7	2803	3.86	151.2	2.7	17.3	10.7	52	0.4	54.5	0.4	12	0.86	0.063
KYS 109707	Soil	1.0	48.3	23.4	99	0.2	32.4	14.7	459	2.95	268.9	3.7	14.3	4.2	76	0.3	166.6	0.3	9	1.43	0.076
KYS 110983	Soil	1.1	38.3	22.3	98	0.1	40.1	19.0	571	3.85	84.4	1.4	6.1	12.5	19	0.3	4.4	0.3	14	0.29	0.063
KYS 110962	Soil	1.1	33.0	16.9	70	<0.1	26.3	10.0	294	3.19	16.1	1.5	3.5	4.4	11	0.2	0.9	0.2	36	0.06	0.049
KYS 109706	Soil	1.2	56.5	29.3	105	0.2	35.6	17.0	542	3.65	334.2	1.6	15.8	10.0	40	0.2	267.2	0.4	8	2.42	0.060
KYS 109705	Soil	1.2	74.7	84.8	143	1.1	47.1	23.9	786	4.50	1097	2.3	148.9	13.4	32	0.5	1020	0.5	12	0.26	0.072
KYS 109704	Soil	1.6	67.8	51.8	137	0.5	38.9	20.6	705	4.67	985.7	2.2	97.4	12.5	20	0.3	1199	0.5	11	0.08	0.054
KYS 109703	Soil	1.1	69.0	40.7	144	0.6	52.3	24.1	629	4.40	888.7	4.3	156.2	9.3	46	0.6	1030	0.4	13	0.63	0.072

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109672	Soil	26	25	0.57	204	0.007	<1	1.44	0.005	0.06	<0.1	0.03	1.3	<0.1	<0.05	4	0.5	0.2
KYS 109579	Soil	19	22	0.37	386	0.012	1	1.49	0.005	0.06	0.1	0.07	1.4	<0.1	<0.05	4	1.4	<0.2
KYS 109596	Soil	10	22	0.36	133	0.007	1	0.99	0.005	0.05	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109671	Soil	14	21	0.49	170	0.003	<1	1.54	0.006	0.07	<0.1	0.04	1.3	<0.1	<0.05	5	0.5	<0.2
KYS 109963	Soil	17	24	0.62	130	0.002	<1	1.16	0.004	0.10	<0.1	0.05	1.9	<0.1	<0.05	3	0.6	<0.2
KYS 109666	Soil	11	19	0.43	109	0.003	1	1.35	0.007	0.08	<0.1	0.03	0.8	<0.1	<0.05	5	<0.5	<0.2
KYS 112164	Soil	26	16	0.50	54	0.001	1	1.27	0.004	0.07	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 112170	Soil	11	12	0.36	83	0.002	1	0.93	0.006	0.08	<0.1	0.04	0.9	<0.1	0.05	2	<0.5	<0.2
KYS 109635	Soil	35	12	0.28	95	0.001	1	1.01	0.004	0.10	<0.1	0.04	0.7	<0.1	<0.05	2	<0.5	<0.2
KYS 109674	Soil	11	20	0.23	62	0.016	<1	1.11	0.004	0.03	0.2	0.05	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109925	Soil	22	19	0.55	461	0.003	<1	1.28	0.005	0.05	<0.1	0.05	1.7	<0.1	<0.05	3	0.6	<0.2
KYS 112097	Soil	16	18	0.30	124	0.019	<1	0.86	0.007	0.04	0.1	0.07	2.5	<0.1	<0.05	2	0.9	<0.2
KYS 109598	Soil	12	23	0.36	175	0.012	<1	1.31	0.006	0.05	0.1	0.04	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109599	Soil	14	17	0.30	102	0.007	<1	1.09	0.006	0.04	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 112099	Soil	34	24	0.85	64	0.005	<1	1.76	0.008	0.05	<0.1	0.02	1.4	<0.1	<0.05	5	<0.5	<0.2
KYS 109926	Soil	23	21	0.59	811	0.003	<1	1.41	0.006	0.06	<0.1	0.04	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109922	Soil	27	16	0.53	145	0.003	<1	1.22	0.004	0.05	<0.1	0.07	1.7	<0.1	<0.05	3	1.2	<0.2
KYS 112098	Soil	36	25	0.92	62	0.005	<1	1.87	0.007	0.05	<0.1	0.03	1.6	<0.1	<0.05	5	0.5	<0.2
KYS 109711	Soil	19	25	0.51	72	0.031	<1	1.42	0.005	0.04	0.2	0.03	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109713	Soil	17	27	0.52	110	0.035	1	1.72	0.004	0.05	0.2	0.04	2.6	<0.1	<0.05	4	<0.5	<0.2
KYS 110984	Soil	14	28	0.63	602	0.002	1	1.14	0.004	0.07	<0.1	0.02	1.6	<0.1	0.06	3	0.6	<0.2
KYS 110982	Soil	25	29	0.70	379	0.003	1	1.38	0.005	0.08	<0.1	0.03	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109693	Soil	17	20	0.63	124	0.002	1	1.43	0.011	0.07	<0.1	0.05	1.8	<0.1	0.07	4	0.8	<0.2
KYS 109707	Soil	8	14	0.53	62	0.002	3	1.04	0.007	0.08	<0.1	0.07	1.0	<0.1	0.13	2	1.8	<0.2
KYS 110983	Soil	28	27	0.67	357	0.002	<1	1.28	0.003	0.08	<0.1	0.01	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110962	Soil	20	26	0.48	84	0.022	<1	1.68	0.005	0.04	0.1	0.04	2.1	<0.1	<0.05	5	<0.5	<0.2
KYS 109706	Soil	18	13	1.54	41	0.002	<1	0.90	0.007	0.05	<0.1	0.03	1.4	<0.1	0.06	2	0.6	<0.2
KYS 109705	Soil	28	16	0.44	87	0.003	<1	1.08	0.007	0.05	<0.1	0.04	2.1	<0.1	<0.05	3	0.5	<0.2
KYS 109704	Soil	30	16	0.37	76	0.001	<1	1.09	0.006	0.05	<0.1	0.04	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109703	Soil	20	18	0.50	76	0.003	1	1.28	0.009	0.06	<0.1	0.04	2.0	<0.1	<0.05	3	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110987	Soil	0.7	37.5	29.1	78	<0.1	33.4	18.1	414	3.35	24.9	0.7	2.0	12.6	6	0.1	4.0	0.3	26	0.06	0.038
KYS 110986	Soil	1.1	57.8	37.2	91	<0.1	36.2	20.9	757	3.52	23.1	1.0	4.1	7.9	11	<0.1	3.0	0.4	25	0.12	0.066
KYS 110981	Soil	1.1	44.5	24.5	104	0.1	43.7	19.1	642	3.78	62.9	1.7	4.9	11.8	24	0.3	3.9	0.3	17	0.40	0.060
KYS 109650	Soil	0.9	37.6	20.2	82	<0.1	33.8	20.1	855	4.57	29.8	0.8	1.6	4.3	6	<0.1	3.2	0.4	27	0.04	0.045
KYS 109645	Soil	4.6	87.1	26.1	106	0.3	48.2	23.6	1677	4.58	67.9	1.3	8.4	7.1	38	0.4	19.1	0.4	19	2.65	0.160
KYS 109651	Soil	0.7	30.1	14.9	70	<0.1	27.1	12.4	669	4.05	34.1	0.8	1.8	4.1	7	<0.1	3.0	0.3	17	0.09	0.039
KYS 109646	Soil	1.2	35.9	19.3	79	0.2	25.3	9.8	337	3.34	60.3	1.1	12.7	8.8	10	0.1	13.5	0.3	13	0.32	0.086
KYS 109649	Soil	1.2	91.0	16.5	113	<0.1	115.7	55.3	3614	7.85	43.4	1.5	2.9	5.2	9	0.2	3.3	0.2	25	0.09	0.079
KYS 109652	Soil	1.0	24.1	16.0	70	0.1	20.3	11.1	559	3.29	100.6	0.8	9.7	4.8	4	<0.1	17.0	0.3	15	0.02	0.051
KYS 109712	Soil	1.0	36.0	13.2	75	<0.1	31.1	13.2	502	2.77	19.5	1.1	3.5	6.9	15	0.3	0.9	0.2	40	0.16	0.078
KYS 109714	Soil	1.1	22.3	11.9	59	<0.1	20.7	11.3	468	2.72	26.4	0.8	2.2	3.4	11	0.2	0.9	0.2	43	0.11	0.060
KYS 109927	Soil	0.8	38.2	60.6	103	0.2	39.5	20.3	727	4.31	301.7	1.1	6.3	18.4	7	0.2	18.2	0.3	15	0.04	0.037
KYS 109932	Soil	4.4	43.4	18.5	127	0.6	40.7	11.4	459	2.82	18.4	3.1	5.1	4.9	26	1.3	3.8	0.3	24	0.35	0.071
KYS 109637	Soil	1.1	36.6	35.4	122	0.4	33.2	17.1	771	3.28	337.4	1.3	31.9	9.4	15	0.4	550.7	0.3	12	0.15	0.049
KYS 109928	Soil	0.4	32.5	50.3	85	<0.1	35.4	13.5	1196	2.90	5.7	1.1	2.5	10.8	124	0.3	1.5	0.4	5	2.22	0.063
KYS 109953	Soil	1.5	32.0	25.9	69	<0.1	26.1	11.0	328	3.72	81.0	0.6	1.3	9.7	6	0.1	15.0	0.4	30	0.04	0.037
KYS 109931	Soil	3.7	42.6	15.5	165	0.6	50.7	11.0	557	2.65	19.8	3.3	8.8	3.9	41	2.4	3.8	0.2	25	0.93	0.074
KYS 109929	Soil	2.8	50.4	97.3	273	1.0	119.3	31.5	2287	5.11	578.2	2.2	46.1	11.2	25	4.1	33.1	0.4	22	0.57	0.054
KYS 109958	Soil	1.1	49.5	24.9	103	0.2	38.6	16.8	603	3.59	17.0	1.9	2.1	12.2	17	0.4	1.5	0.4	12	0.27	0.056
KYS 109924	Soil	1.9	39.8	23.7	129	0.3	33.9	11.5	378	3.48	203.4	1.4	16.1	5.3	13	1.1	54.8	0.3	14	0.12	0.077
KYS 109955	Soil	1.1	25.0	24.1	102	0.1	32.0	19.4	514	3.76	68.7	1.5	3.9	9.2	37	0.3	3.1	0.3	15	0.64	0.058
KYS 109923	Soil	2.1	39.9	23.6	140	0.3	33.1	12.7	449	3.53	182.7	1.2	13.9	6.2	13	1.0	46.9	0.3	15	0.13	0.067
KYS 109638	Soil	0.8	45.2	44.0	78	0.1	38.8	18.1	503	3.62	40.9	1.2	0.9	17.9	10	<0.1	9.3	0.6	17	0.11	0.046
KYS 109661	Soil	1.0	24.9	17.5	58	0.1	33.6	9.7	276	2.86	18.2	0.8	2.0	2.8	10	0.3	1.0	0.2	49	0.08	0.039
KYS 111510	Soil	2.7	30.0	19.1	53	0.3	18.1	5.0	185	3.23	39.6	0.8	7.8	2.4	15	0.2	3.5	0.4	62	0.05	0.055
KYS 112031	Soil	1.1	56.5	35.5	111	0.2	44.6	21.6	917	4.27	152.3	1.6	17.6	17.7	16	0.2	349.4	0.3	10	0.16	0.057
KYS 109665	Soil	1.2	35.2	18.0	83	0.2	31.6	15.0	665	2.76	50.8	1.7	4.1	4.9	16	0.3	2.2	0.2	20	0.22	0.072
KYS 112026	Soil	2.2	75.8	44.4	148	0.3	51.8	30.9	968	4.59	120.6	2.2	6.5	12.4	18	0.2	46.7	0.8	6	0.16	0.066
KYS 112023	Soil	1.1	32.7	23.2	65	0.1	26.6	13.0	659	2.49	35.1	1.0	9.6	8.2	11	0.1	6.6	0.2	14	0.11	0.037
KYS 111728	Soil	0.9	20.6	25.3	63	<0.1	18.5	9.1	464	2.58	55.0	1.0	4.5	2.3	25	0.2	1.8	0.3	27	0.61	0.046

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110987	Soil		26	23	0.46	82	0.012	<1	1.67	0.005	0.05	<0.1	0.02	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110986	Soil		23	23	0.46	107	0.016	<1	1.27	0.005	0.05	<0.1	0.02	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 110981	Soil		24	32	0.74	327	0.002	<1	1.43	0.004	0.08	<0.1	0.02	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109650	Soil		15	35	0.60	71	0.007	<1	1.69	0.005	0.04	<0.1	0.02	2.0	<0.1	<0.05	5	<0.5	<0.2
KYS 109645	Soil		24	19	1.86	67	0.003	<1	1.39	0.006	0.05	<0.1	0.05	2.3	<0.1	0.06	4	<0.5	<0.2
KYS 109651	Soil		15	23	0.48	90	0.002	<1	1.38	0.007	0.05	<0.1	0.02	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109646	Soil		36	15	0.45	97	0.002	<1	1.08	0.005	0.06	<0.1	0.03	1.7	<0.1	<0.05	3	<0.5	0.2
KYS 109649	Soil		16	44	0.48	148	0.011	<1	1.49	0.005	0.06	<0.1	0.03	4.9	<0.1	<0.05	4	0.6	<0.2
KYS 109652	Soil		26	17	0.35	75	0.003	<1	1.18	0.005	0.05	<0.1	0.02	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 109712	Soil		19	27	0.50	94	0.042	<1	1.49	0.007	0.05	0.2	0.03	2.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109714	Soil		16	26	0.44	89	0.033	<1	1.68	0.006	0.04	0.2	0.03	2.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109927	Soil		33	23	0.64	2091	0.002	<1	2.09	0.004	0.07	<0.1	0.03	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 109932	Soil		14	18	0.33	521	0.008	2	0.96	0.006	0.04	0.1	0.12	1.9	<0.1	<0.05	3	1.6	<0.2
KYS 109637	Soil		22	15	0.40	254	0.005	1	1.02	0.006	0.10	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109928	Soil		11	12	0.27	153	<0.001	<1	1.13	0.005	0.06	<0.1	0.04	2.8	<0.1	<0.05	2	<0.5	<0.2
KYS 109953	Soil		27	20	0.41	76	0.011	<1	1.38	0.004	0.05	0.1	0.02	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 109931	Soil		9	18	0.33	782	0.010	1	0.85	0.007	0.04	0.1	0.15	1.9	<0.1	<0.05	2	1.9	<0.2
KYS 109929	Soil		20	45	0.93	506	0.004	1	1.63	0.005	0.08	<0.1	0.06	2.5	<0.1	<0.05	5	1.3	<0.2
KYS 109958	Soil		20	21	0.63	180	0.002	<1	1.42	0.005	0.06	<0.1	0.04	1.7	<0.1	<0.05	4	0.5	<0.2
KYS 109924	Soil		18	17	0.46	130	0.004	<1	1.16	0.005	0.05	<0.1	0.05	1.4	<0.1	<0.05	3	0.7	<0.2
KYS 109955	Soil		18	27	0.67	534	0.003	<1	1.32	0.007	0.07	<0.1	0.02	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109923	Soil		22	16	0.49	122	0.003	<1	1.19	0.005	0.05	<0.1	0.04	1.2	<0.1	<0.05	3	0.9	<0.2
KYS 109638	Soil		34	19	0.44	107	0.005	<1	1.48	0.006	0.07	<0.1	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109661	Soil		14	57	0.71	97	0.031	<1	1.51	0.005	0.04	0.1	0.03	2.1	<0.1	<0.05	6	<0.5	<0.2
KYS 111510	Soil		11	28	0.27	77	0.034	<1	1.34	0.005	0.04	0.2	0.05	1.7	<0.1	<0.05	7	1.1	<0.2
KYS 112031	Soil		30	22	0.64	54	0.004	<1	1.38	0.007	0.08	<0.1	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109665	Soil		15	22	0.40	142	0.010	<1	0.97	0.004	0.03	0.1	0.04	1.5	<0.1	<0.05	3	0.7	<0.2
KYS 112026	Soil		23	9	0.28	53	0.001	<1	0.70	0.004	0.05	<0.1	0.04	1.7	<0.1	<0.05	2	<0.5	0.2
KYS 112023	Soil		27	14	0.31	125	0.006	<1	0.93	0.005	0.05	<0.1	0.04	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 111728	Soil		14	14	0.19	92	0.017	1	0.80	0.007	0.04	0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112029	Soil	0.9	49.6	31.5	96	0.2	39.3	17.5	748	3.62	183.9	2.1	22.7	13.1	31	0.2	453.6	0.3	9	0.54	0.055
KYS 112024	Soil	1.0	101.1	25.0	107	<0.1	47.0	25.4	607	3.47	31.9	1.5	1.3	9.5	21	0.1	9.2	0.3	4	0.22	0.065
KYS 112025	Soil	0.9	35.4	33.8	111	<0.1	40.0	22.1	571	3.68	57.0	2.9	1.8	13.3	20	<0.1	33.0	0.4	8	0.23	0.046
KYS 112027	Soil	0.9	34.4	24.1	75	<0.1	30.0	11.7	352	2.94	62.1	0.8	0.8	11.1	7	<0.1	15.1	0.3	9	0.09	0.036
KYS 111578	Soil	2.1	29.1	15.2	48	0.2	17.5	4.9	203	2.61	27.7	1.0	6.7	2.0	15	0.1	2.4	0.3	44	0.06	0.061
KYS 111562	Soil	1.6	33.4	26.7	95	<0.1	34.6	15.4	574	3.32	14.4	1.0	2.1	3.4	11	0.3	0.8	0.3	39	0.12	0.063
KYS 111729	Soil	0.6	32.1	30.6	85	0.1	26.3	9.5	434	3.19	61.5	1.1	5.8	4.2	29	0.1	2.3	0.3	10	0.86	0.061
KYS 111727	Soil	1.3	21.4	36.7	75	<0.1	21.6	10.2	348	3.28	29.9	0.8	2.0	6.6	9	0.2	1.5	0.3	42	0.09	0.049
KYS 112174	Soil	0.9	33.6	25.5	90	<0.1	32.8	14.1	579	3.34	17.3	1.4	2.9	3.1	11	0.2	0.8	0.3	33	0.09	0.047
KYS 112178	Soil	0.9	36.0	33.5	77	<0.1	30.7	17.5	896	3.34	20.9	1.4	1.1	1.7	14	0.1	0.5	0.4	21	0.14	0.079
KYS 111576	Soil	3.3	56.1	21.5	43	0.9	17.5	3.3	122	3.33	64.8	1.1	18.5	1.7	21	0.2	5.2	0.5	37	0.04	0.095
KYS 111575	Soil	2.0	27.0	14.3	45	0.4	15.0	4.4	178	2.59	26.3	1.1	6.1	0.8	15	0.3	2.1	0.3	42	0.06	0.075
KYS 112177	Soil	0.7	27.7	28.0	74	<0.1	25.8	13.1	924	3.28	16.1	1.1	1.2	1.8	15	0.1	0.6	0.4	28	0.22	0.064
KYS 111572	Soil	5.4	64.4	37.9	50	1.8	20.1	3.9	195	4.46	80.8	1.7	19.8	5.9	32	0.3	6.3	0.8	30	0.08	0.318
KYS 112186	Soil	1.5	41.2	32.0	80	0.3	30.3	13.6	795	4.31	25.6	1.8	1.2	1.7	19	0.3	0.7	0.5	30	0.08	0.081
KYS 112173	Soil	0.8	48.3	28.8	95	<0.1	40.3	19.5	753	4.21	11.1	1.8	10.8	12.7	12	<0.1	0.7	0.5	12	0.15	0.052
KYS 112179	Soil	1.5	65.6	32.8	116	0.1	55.8	35.6	836	4.59	45.7	2.1	1.2	11.9	13	0.1	0.4	0.4	15	0.09	0.050
KYS 111708	Soil	1.0	35.6	23.7	76	<0.1	26.8	12.9	708	3.39	14.8	1.4	1.0	1.1	8	0.1	0.5	0.4	27	0.07	0.063
KYS 111710	Soil	1.2	21.6	17.7	65	<0.1	20.5	9.0	442	2.84	9.7	0.9	1.8	1.0	5	0.1	0.5	0.3	33	0.05	0.050
KYS 111701	Soil	0.9	23.6	18.9	64	0.1	23.5	11.9	532	2.95	32.5	1.0	3.9	1.3	6	<0.1	1.0	0.3	26	0.09	0.057
KYS 111707	Soil	1.5	26.0	23.3	79	<0.1	25.5	13.5	850	3.53	14.1	1.0	1.8	1.0	7	0.1	0.5	0.3	31	0.06	0.057
KYS 111702	Soil	0.7	30.3	17.7	74	0.1	27.6	10.7	513	3.12	24.0	1.3	3.3	5.1	9	0.1	0.8	0.3	18	0.15	0.051
KYS 111685	Soil	0.6	18.1	20.9	55	<0.1	20.5	10.1	528	2.71	13.7	0.8	1.5	7.0	9	<0.1	0.3	0.3	13	0.18	0.040
KYS 111703	Soil	0.6	22.2	17.0	65	<0.1	23.4	9.8	484	2.92	27.4	1.0	3.5	4.6	6	0.1	0.8	0.2	16	0.10	0.053
KYS 111711	Soil	0.9	21.0	14.1	65	<0.1	22.2	9.5	455	2.55	8.0	0.9	2.2	2.2	7	0.2	0.4	0.2	26	0.08	0.047
KYS 111704	Soil	0.7	19.1	17.4	68	<0.1	20.4	9.1	516	2.67	18.2	0.9	3.2	1.8	8	0.1	0.6	0.2	24	0.13	0.057
KYS 111700	Soil	1.0	19.0	15.5	68	<0.1	21.9	9.8	406	2.30	35.4	0.7	5.5	2.0	7	0.1	1.2	0.2	27	0.09	0.056
KYS 111706	Soil	1.0	21.0	18.0	67	<0.1	20.8	11.0	625	2.94	11.6	1.0	1.2	1.1	6	0.1	0.5	0.2	31	0.06	0.052
KYS 111705	Soil	1.1	30.0	20.1	67	<0.1	22.6	10.0	480	2.98	27.4	1.2	5.9	3.9	5	0.1	0.7	0.3	14	0.08	0.046
KYS 110040	Soil	2.5	34.6	56.7	120	0.5	28.4	14.2	593	3.50	195.0	1.7	18.9	7.4	25	0.7	51.2	0.3	14	0.51	0.063

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112029	Soil		23	19	0.54	59	0.002	1	1.22	0.006	0.08	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 112024	Soil		40	15	0.24	48	0.003	2	0.54	0.003	0.12	<0.1	0.04	1.1	<0.1	<0.05	2	<0.5	<0.2
KYS 112025	Soil		27	17	0.51	43	0.002	<1	1.31	0.006	0.06	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	0.2
KYS 112027	Soil		31	14	0.37	46	0.003	<1	0.97	0.006	0.06	<0.1	0.02	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 111578	Soil		11	28	0.28	73	0.026	<1	1.25	0.006	0.04	0.1	0.06	1.6	<0.1	<0.05	5	1.1	<0.2
KYS 111562	Soil		17	25	0.45	97	0.031	<1	1.52	0.006	0.04	0.2	0.03	2.1	<0.1	<0.05	4	0.7	<0.2
KYS 111729	Soil		12	10	0.19	80	0.006	1	0.58	0.005	0.06	<0.1	0.05	2.1	<0.1	<0.05	2	<0.5	<0.2
KYS 111727	Soil		19	23	0.33	73	0.030	1	1.39	0.006	0.05	0.2	0.04	1.8	<0.1	<0.05	5	<0.5	<0.2
KYS 112174	Soil		22	25	0.52	93	0.034	<1	1.56	0.005	0.05	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 112178	Soil		14	22	0.52	79	0.012	1	1.28	0.007	0.06	<0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 111576	Soil		9	23	0.13	104	0.009	<1	0.98	0.006	0.03	<0.1	0.08	1.4	<0.1	<0.05	4	1.9	<0.2
KYS 111575	Soil		11	24	0.22	76	0.018	<1	1.20	0.006	0.03	0.1	0.08	1.0	<0.1	<0.05	4	1.1	<0.2
KYS 112177	Soil		15	20	0.46	71	0.018	<1	1.22	0.006	0.04	0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 111572	Soil		13	35	0.13	81	0.004	<1	1.18	0.011	0.03	<0.1	0.13	1.8	<0.1	0.10	4	4.9	<0.2
KYS 112186	Soil		15	22	0.42	60	0.013	<1	1.41	0.006	0.05	<0.1	0.04	1.0	<0.1	<0.05	5	<0.5	<0.2
KYS 112173	Soil		41	19	0.72	84	0.004	<1	1.56	0.005	0.06	<0.1	0.02	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 112179	Soil		27	25	0.93	29	0.009	<1	2.00	0.005	0.06	<0.1	0.02	1.7	<0.1	<0.05	6	<0.5	<0.2
KYS 111708	Soil		15	21	0.44	65	0.013	<1	1.35	0.005	0.05	0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 111710	Soil		10	22	0.35	46	0.014	2	1.30	0.003	0.04	0.2	0.03	0.7	<0.1	<0.05	4	0.6	<0.2
KYS 111701	Soil		10	16	0.23	66	0.011	2	0.79	0.004	0.04	0.2	0.04	1.0	<0.1	<0.05	3	0.5	<0.2
KYS 111707	Soil		10	24	0.32	67	0.011	2	1.12	0.004	0.06	0.1	0.04	0.7	<0.1	<0.05	4	<0.5	<0.2
KYS 111702	Soil		15	13	0.28	85	0.011	1	0.80	0.003	0.04	<0.1	0.04	1.4	<0.1	<0.05	2	<0.5	<0.2
KYS 111685	Soil		14	12	0.29	111	0.003	1	1.07	0.002	0.08	<0.1	0.02	0.8	<0.1	<0.05	3	<0.5	0.2
KYS 111703	Soil		15	13	0.23	63	0.005	2	0.68	0.004	0.03	<0.1	0.03	1.3	<0.1	<0.05	2	<0.5	<0.2
KYS 111711	Soil		12	18	0.34	39	0.016	2	0.93	0.003	0.04	0.1	0.03	0.9	<0.1	<0.05	3	0.5	<0.2
KYS 111704	Soil		12	15	0.26	87	0.010	2	0.92	0.003	0.04	0.2	0.02	0.9	<0.1	<0.05	3	0.5	<0.2
KYS 111700	Soil		12	16	0.17	45	0.016	2	0.66	0.003	0.04	0.1	0.06	1.0	<0.1	<0.05	2	<0.5	<0.2
KYS 111706	Soil		11	19	0.30	57	0.013	1	0.98	0.003	0.04	0.2	0.02	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 111705	Soil		16	13	0.29	61	0.006	1	0.84	0.003	0.04	<0.1	0.04	1.1	<0.1	<0.05	2	0.6	<0.2
KYS 110040	Soil		13	13	0.30	106	0.001	2	0.78	0.003	0.07	<0.1	0.05	1.3	<0.1	<0.05	2	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110998	Soil		1.5	38.2	23.4	96	0.3	37.7	14.9	672	3.11	89.9	1.6	10.4	5.3	50	0.7	5.8	0.3	12	0.92	0.067
KYS 110999	Soil		1.6	37.8	37.3	119	0.4	36.2	14.3	726	3.18	96.4	1.4	13.1	6.5	27	0.6	28.8	0.3	12	0.58	0.066
KYS 111000	Soil		1.7	35.4	32.4	109	0.3	36.4	14.8	464	2.97	100.9	1.2	9.2	8.8	15	0.5	31.9	0.3	10	0.33	0.061
KYS 111673	Soil		2.7	17.4	11.4	47	0.3	13.2	3.3	96	2.18	14.0	0.7	2.4	0.9	9	0.2	0.9	0.3	59	0.04	0.075
KYS 110038	Soil		0.7	32.2	24.0	94	0.2	29.3	12.0	532	3.23	105.4	1.4	15.2	8.8	28	0.1	315.4	0.2	8	0.59	0.048
KYS 112274	Soil		0.6	36.9	17.6	73	0.2	38.0	15.1	610	3.39	14.8	2.2	4.1	4.1	42	0.1	0.5	0.2	28	0.84	0.060
KYS 111677	Soil		1.7	20.6	12.0	69	0.3	20.6	8.1	383	2.73	19.4	1.0	2.4	1.0	7	0.2	1.2	0.2	39	0.07	0.074
KYS 111678	Soil		3.1	19.7	14.6	69	0.2	21.0	7.0	306	3.23	41.4	1.0	2.1	1.4	14	0.2	1.2	0.3	52	0.12	0.070
KYS 112006	Soil		2.6	78.3	22.2	87	0.6	31.5	4.9	267	3.77	20.8	1.0	8.9	3.4	13	0.1	3.2	0.5	25	0.01	0.066
KYS 112004	Soil		2.5	90.7	17.1	124	0.9	54.7	11.5	786	3.99	8.9	1.0	76.9	6.4	12	0.1	1.4	0.4	29	0.03	0.084
KYS 112002	Soil		2.4	57.1	19.5	61	0.8	19.4	3.2	201	4.99	40.9	1.0	17.2	3.3	9	<0.1	3.0	0.5	30	0.04	0.112
KYS 109691	Soil		0.4	37.3	25.3	69	<0.1	40.9	18.8	538	2.84	63.2	0.9	11.4	8.1	61	0.1	2.4	0.3	4	1.73	0.036
KYS 109685	Soil		0.5	37.0	21.0	60	<0.1	31.9	14.7	1075	2.90	25.8	1.5	3.1	7.7	50	<0.1	1.1	0.2	13	0.87	0.049
KYS 112234	Soil		0.7	44.0	23.6	108	<0.1	46.7	20.4	788	4.05	32.8	1.6	8.0	12.1	7	<0.1	4.5	0.3	13	0.20	0.049
KYS 112232	Soil		0.6	32.6	24.0	153	<0.1	44.1	23.3	1197	3.69	30.2	1.1	3.9	10.8	6	0.1	5.0	0.2	13	0.12	0.036
KYS 112014	Soil		0.8	40.5	21.7	81	0.1	29.5	10.7	373	3.02	32.4	0.9	5.1	8.1	18	0.1	33.7	0.3	13	0.92	0.051
KYS 109676	Soil		0.8	30.0	21.0	55	0.1	23.2	12.2	503	2.54	27.7	1.8	3.3	4.5	85	0.1	13.4	0.2	9	1.01	0.064
KYS 110931	Soil		0.7	40.0	31.4	114	0.8	34.4	12.2	428	3.42	741.4	1.4	89.5	6.1	29	0.2	497.5	0.3	11	0.33	0.047
KYS 111715	Soil		0.6	84.4	4.7	82	0.1	78.0	25.0	552	3.77	224.7	0.8	10.6	1.4	31	0.1	0.8	<0.1	55	0.75	0.190
KYS 112018	Soil		1.2	60.7	38.6	122	0.2	40.6	17.6	698	4.70	279.2	1.7	25.4	15.1	17	0.2	71.8	0.5	14	0.21	0.066
KYS 110977	Soil		1.5	32.2	22.4	109	0.3	35.8	14.6	836	3.09	177.9	1.4	12.5	5.2	40	0.7	42.4	0.2	18	0.46	0.066
KYS 109679	Soil		0.8	38.9	39.1	115	0.9	35.1	14.7	406	3.71	793.8	1.6	97.9	8.0	23	0.2	734.4	0.3	10	0.20	0.042
KYS 111722	Soil		1.4	45.7	29.7	113	0.2	39.0	17.0	843	3.47	117.7	1.2	10.0	9.2	37	0.3	1.6	0.4	13	0.68	0.061
KYS 111570	Soil		4.1	58.7	26.3	70	0.9	26.9	6.4	263	3.50	39.3	1.4	10.4	2.7	23	0.2	3.8	0.6	44	0.08	0.171
KYS 111577	Soil		2.0	29.2	13.4	44	0.3	18.2	5.4	185	2.74	22.2	1.0	4.7	4.6	12	0.1	2.2	0.3	41	0.06	0.065
KYS 111571	Soil		1.5	39.7	11.8	70	0.3	28.7	10.3	345	2.67	18.2	1.2	7.3	3.8	12	0.4	1.3	0.2	32	0.09	0.078
KYS 111568	Soil		2.3	77.5	37.6	122	0.1	48.8	25.3	1518	4.44	37.4	1.5	1.1	10.8	10	0.4	1.0	0.5	20	0.15	0.073
KYS 111569	Soil		3.5	61.7	28.1	75	0.8	26.8	6.7	294	3.73	38.6	1.5	7.5	2.8	21	0.1	3.7	0.7	39	0.07	0.163
KYS 109919	Soil		0.7	33.5	31.4	106	0.1	35.7	14.0	527	3.03	42.4	1.3	4.5	6.2	20	0.3	2.5	0.3	13	0.45	0.048
KYS 111567	Soil		1.1	47.5	22.1	85	<0.1	33.1	16.4	1131	3.54	10.4	0.9	1.3	3.6	10	0.2	0.5	0.4	30	0.12	0.064

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110998	Soil	9	16	0.35	504	0.002	3	0.86	0.004	0.08	<0.1	0.04	1.2	<0.1	0.05	2	1.2	<0.2
KYS 110999	Soil	11	11	0.36	99	0.002	1	0.85	0.001	0.06	<0.1	0.04	1.2	<0.1	<0.05	2	0.9	<0.2
KYS 111000	Soil	17	14	0.37	68	0.001	1	0.82	0.004	0.05	<0.1	0.04	1.2	<0.1	<0.05	2	0.8	<0.2
KYS 111673	Soil	16	29	0.21	45	0.027	2	0.73	0.004	0.04	0.2	0.07	0.7	<0.1	<0.05	5	1.2	<0.2
KYS 110038	Soil	14	16	0.55	51	0.002	2	1.16	0.003	0.07	<0.1	0.04	1.0	<0.1	<0.05	3	0.6	<0.2
KYS 112274	Soil	18	41	0.88	118	0.008	2	1.55	0.005	0.06	<0.1	0.04	1.9	<0.1	<0.05	5	0.7	<0.2
KYS 111677	Soil	11	24	0.29	64	0.015	<1	1.12	0.004	0.05	0.2	0.05	0.9	<0.1	<0.05	4	1.2	<0.2
KYS 111678	Soil	12	27	0.30	105	0.017	2	1.36	0.004	0.05	0.2	0.04	1.1	<0.1	<0.05	5	1.4	<0.2
KYS 112006	Soil	4	21	0.28	98	<0.001	<1	1.04	0.005	0.03	<0.1	0.11	1.6	<0.1	<0.05	3	2.0	<0.2
KYS 112004	Soil	21	25	0.38	66	0.002	1	1.25	0.005	0.02	<0.1	0.09	1.1	<0.1	<0.05	4	1.6	<0.2
KYS 112002	Soil	6	23	0.11	86	<0.001	<1	0.91	0.006	0.03	<0.1	0.13	1.0	<0.1	<0.05	4	2.5	0.4
KYS 109691	Soil	7	6	0.13	62	<0.001	2	0.41	0.004	0.08	<0.1	0.05	1.2	<0.1	0.09	<1	0.5	<0.2
KYS 109685	Soil	10	15	0.49	102	0.001	2	1.02	0.006	0.13	<0.1	0.05	1.3	<0.1	0.06	3	<0.5	<0.2
KYS 112234	Soil	31	21	0.69	32	0.003	<1	1.55	0.004	0.05	<0.1	0.04	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 112232	Soil	23	17	0.69	44	0.004	1	1.54	0.003	0.06	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112014	Soil	15	14	0.73	62	0.002	1	1.08	0.003	0.04	<0.1	0.04	1.2	<0.1	<0.05	3	0.6	0.2
KYS 109676	Soil	9	13	0.39	84	0.002	2	0.95	0.007	0.08	<0.1	0.05	0.8	<0.1	0.07	2	0.9	<0.2
KYS 110931	Soil	13	13	0.41	48	0.002	1	1.02	0.003	0.08	<0.1	0.03	1.0	<0.1	<0.05	3	0.6	<0.2
KYS 111715	Soil	8	85	1.91	266	0.063	2	2.30	0.003	0.07	<0.1	0.02	3.4	<0.1	<0.05	6	<0.5	<0.2
KYS 112018	Soil	25	19	0.64	51	0.002	1	1.47	0.004	0.05	<0.1	0.04	1.5	<0.1	<0.05	4	0.6	0.2
KYS 110977	Soil	13	16	0.54	335	0.003	1	1.08	0.002	0.05	<0.1	0.04	1.1	<0.1	<0.05	3	1.0	0.3
KYS 109679	Soil	16	13	0.46	55	0.002	2	1.10	0.005	0.09	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 111722	Soil	12	15	0.50	45	0.001	1	1.26	0.003	0.07	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 111570	Soil	13	26	0.22	67	0.025	<1	1.29	0.008	0.05	<0.1	0.04	2.2	<0.1	<0.05	4	2.9	0.5
KYS 111577	Soil	9	26	0.21	71	0.022	<1	1.40	0.004	0.03	0.2	0.07	1.4	<0.1	<0.05	5	1.2	0.3
KYS 111571	Soil	11	22	0.23	76	0.020	<1	1.35	0.008	0.04	0.2	0.09	1.6	<0.1	<0.05	3	0.7	<0.2
KYS 111568	Soil	23	21	0.57	86	0.009	<1	1.47	0.005	0.05	<0.1	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 111569	Soil	13	27	0.20	70	0.015	<1	1.27	0.007	0.04	<0.1	0.04	1.9	<0.1	<0.05	4	2.9	<0.2
KYS 109919	Soil	14	15	0.24	89	0.005	<1	0.72	0.005	0.05	<0.1	0.04	1.8	<0.1	<0.05	2	<0.5	<0.2
KYS 111567	Soil	14	24	0.56	90	0.019	<1	1.38	0.004	0.05	0.1	0.04	1.0	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109918	Soil		1.0	32.1	14.7	64	0.2	33.4	9.1	256	2.37	24.8	1.5	4.4	5.4	16	0.2	2.0	0.2	22	0.23	0.066
KYS 111573	Soil		2.7	40.2	19.9	46	0.7	19.7	5.2	187	3.03	24.5	1.2	12.3	2.8	12	0.1	2.1	0.4	36	0.04	0.072
KYS 109921	Soil		0.6	36.1	32.5	91	<0.1	32.4	17.7	857	3.72	85.8	1.3	6.0	7.8	13	0.1	2.4	0.4	9	0.21	0.034
KYS 109917	Soil		1.4	22.1	14.7	49	0.2	20.4	5.8	212	2.40	26.9	0.8	8.2	2.6	13	0.2	2.1	0.2	28	0.18	0.053
KYS 109916	Soil		1.4	25.2	15.6	72	0.2	24.6	10.2	442	2.50	18.9	0.8	8.1	3.1	12	0.4	1.8	0.2	33	0.16	0.085
KYS 112003	Soil		2.3	102.9	27.6	116	0.9	53.2	12.1	1376	5.08	18.9	1.2	27.2	7.9	20	0.2	1.8	0.6	31	0.06	0.108
KYS 112011	Soil		2.4	60.9	22.3	204	0.6	78.8	24.1	1675	4.28	25.2	2.6	11.6	6.0	16	3.7	3.1	0.4	21	0.17	0.068
KYS 110947	Soil		13.1	61.7	35.4	84	1.4	21.2	4.5	166	3.59	43.1	4.1	8.8	4.4	20	0.4	9.4	0.4	42	0.06	0.111
KYS 111676	Soil		1.2	27.8	22.6	76	0.1	28.6	12.9	592	3.29	53.0	1.3	3.8	2.0	10	<0.1	1.0	0.3	29	0.09	0.062
KYS 111675	Soil		2.2	34.6	23.9	54	0.7	25.1	4.6	144	2.69	33.1	0.9	6.2	2.0	18	0.2	2.5	0.4	29	0.05	0.107
KYS 112113	Soil		3.4	44.3	24.4	114	0.2	46.5	21.0	684	3.77	26.5	1.7	3.2	10.9	16	0.5	1.5	0.3	14	0.26	0.055
KYS 112275	Soil		1.0	38.8	17.0	74	0.2	32.8	16.0	560	3.36	9.9	1.6	2.8	5.3	20	<0.1	0.4	0.2	24	0.18	0.061
KYS 109972	Soil		3.0	25.5	21.8	88	0.2	29.7	12.3	582	2.91	32.4	1.1	4.7	8.8	26	0.3	2.2	0.3	18	0.38	0.058
KYS 111563	Soil		1.9	31.0	11.5	90	0.2	34.8	10.7	246	3.27	21.7	0.9	1.9	2.5	9	0.2	1.4	0.2	58	0.07	0.051
KYS 112258	Soil		0.3	38.9	19.8	85	<0.1	36.2	17.8	838	3.98	21.6	1.5	1.9	10.1	9	<0.1	1.1	0.2	11	0.12	0.038
KYS 109971	Soil		2.1	46.4	31.4	95	0.3	43.1	17.0	892	3.36	117.7	1.4	8.2	10.4	45	0.4	4.5	0.3	12	0.76	0.056
KYS 112259	Soil		0.5	44.8	21.8	90	<0.1	40.1	21.7	897	4.20	20.8	2.0	2.1	12.7	8	<0.1	1.0	0.3	12	0.07	0.035
KYS 112214	Soil		0.8	50.7	24.9	85	0.1	49.0	23.6	598	4.27	20.1	2.0	1.6	5.6	10	<0.1	0.6	0.3	29	0.12	0.064
KYS 112207	Soil		0.7	25.4	39.7	103	0.7	21.9	10.0	942	3.02	610.4	0.9	14.4	2.5	9	0.3	17.9	0.3	19	0.11	0.080
KYS 112212	Soil		0.8	47.5	25.1	89	0.1	45.3	23.2	888	4.17	33.4	2.2	3.1	7.9	9	<0.1	0.6	0.3	14	0.07	0.054
KYS 112211	Soil		0.5	31.5	19.3	76	<0.1	33.8	17.0	770	3.46	20.5	1.6	1.9	5.2	8	<0.1	0.8	0.2	18	0.07	0.044
KYS 112215	Soil		1.1	25.0	26.7	62	<0.1	22.4	10.1	397	3.17	16.0	0.9	2.1	2.9	8	0.1	0.8	0.3	43	0.08	0.053
KYS 112210	Soil		0.6	23.6	12.6	71	<0.1	30.5	11.1	370	3.43	22.4	0.9	3.2	3.7	5	0.2	1.3	0.2	19	0.05	0.041
KYS 112206	Soil		0.7	37.2	51.8	123	0.3	32.4	15.7	612	3.57	794.7	1.4	13.9	6.9	7	0.2	32.3	0.3	16	0.03	0.034
KYS 110992	Soil		1.7	48.6	25.3	120	0.2	51.0	19.3	475	4.03	28.4	1.8	2.1	9.1	38	0.5	1.6	0.3	25	0.50	0.056
KYS 110991	Soil		1.3	44.3	25.9	103	0.1	46.4	17.7	401	3.42	34.6	1.6	2.8	10.4	30	0.4	1.3	0.3	17	0.34	0.045
KYS 110995	Soil		3.0	43.4	25.6	144	0.3	49.3	17.1	1041	3.36	22.1	2.0	2.2	10.0	35	1.2	3.5	0.3	17	0.62	0.065
KYS 112009	Soil		2.9	70.7	22.8	98	0.6	33.4	7.4	407	4.19	21.4	1.2	14.1	2.9	17	0.4	2.8	0.4	35	0.06	0.100
KYS 110997	Soil		1.3	46.5	28.2	101	0.2	42.6	17.8	857	3.19	17.8	1.7	1.7	11.2	25	0.5	1.6	0.3	15	0.36	0.053
KYS 109742	Soil		1.4	27.8	28.0	73	<0.1	22.1	14.4	1122	2.88	11.6	1.0	<0.5	0.7	8	0.2	0.6	0.4	39	0.07	0.071

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109918	Soil	12	21	0.33	101	0.009	<1	1.04	0.004	0.04	<0.1	0.05	1.7	<0.1	<0.05	3	0.5	0.2
KYS 111573	Soil	8	24	0.17	77	0.015	<1	1.11	0.004	0.03	0.1	0.11	1.4	<0.1	<0.05	4	1.8	0.3
KYS 109921	Soil	15	9	0.16	80	0.003	<1	0.62	0.004	0.06	<0.1	0.04	1.7	<0.1	<0.05	2	<0.5	<0.2
KYS 109917	Soil	10	21	0.23	81	0.010	<1	0.88	0.005	0.04	0.1	0.05	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 109916	Soil	11	21	0.32	102	0.023	<1	1.10	0.007	0.04	0.1	0.04	1.4	<0.1	<0.05	3	0.6	<0.2
KYS 112003	Soil	19	29	0.51	97	0.002	<1	1.43	0.002	0.03	<0.1	0.12	1.5	<0.1	0.05	4	1.8	<0.2
KYS 112011	Soil	12	19	0.35	151	0.001	<1	1.10	0.005	0.05	<0.1	0.08	1.6	<0.1	<0.05	4	1.3	0.2
KYS 110947	Soil	18	18	0.20	669	0.003	9	0.96	0.004	0.05	<0.1	0.24	1.2	0.1	0.06	3	5.2	<0.2
KYS 111676	Soil	19	22	0.40	80	0.015	<1	1.31	0.004	0.05	0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 111675	Soil	16	27	0.16	79	0.004	<1	1.13	0.006	0.03	<0.1	0.06	1.2	<0.1	<0.05	4	1.1	0.2
KYS 112113	Soil	20	20	0.56	148	0.002	<1	1.16	0.005	0.07	<0.1	0.07	1.2	<0.1	<0.05	3	0.6	<0.2
KYS 112275	Soil	19	31	0.69	132	0.008	<1	1.30	0.004	0.04	<0.1	0.04	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109972	Soil	21	19	0.43	204	0.004	<1	1.09	0.004	0.08	<0.1	0.04	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 111563	Soil	16	31	0.36	84	0.034	<1	1.53	0.005	0.04	0.2	0.06	1.8	<0.1	<0.05	5	1.4	<0.2
KYS 112258	Soil	31	20	0.87	35	0.003	<1	1.69	0.006	0.06	<0.1	0.02	1.1	<0.1	<0.05	5	<0.5	<0.2
KYS 109971	Soil	18	14	0.33	221	0.005	<1	0.96	0.005	0.11	<0.1	0.06	1.4	<0.1	<0.05	2	0.8	<0.2
KYS 112259	Soil	31	22	0.85	28	0.006	<1	1.73	0.007	0.07	<0.1	0.02	1.1	<0.1	<0.05	5	<0.5	<0.2
KYS 112214	Soil	35	39	0.91	66	0.012	<1	2.02	0.004	0.05	<0.1	0.04	1.3	<0.1	<0.05	6	<0.5	<0.2
KYS 112207	Soil	23	17	0.33	128	0.003	<1	1.26	0.006	0.07	<0.1	0.04	0.8	0.1	<0.05	4	<0.5	<0.2
KYS 112212	Soil	28	26	0.83	46	0.005	<1	1.88	0.005	0.06	<0.1	0.04	1.0	<0.1	<0.05	5	<0.5	<0.2
KYS 112211	Soil	25	21	0.63	58	0.008	<1	1.47	0.008	0.06	<0.1	0.02	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 112215	Soil	22	26	0.43	78	0.023	<1	1.49	0.004	0.05	0.2	0.04	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 112210	Soil	28	22	0.62	52	0.008	<1	1.60	0.005	0.04	<0.1	0.03	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 112206	Soil	30	18	0.49	68	0.008	<1	1.35	0.005	0.07	<0.1	0.05	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 110992	Soil	18	33	0.79	2910	0.003	<1	1.49	0.003	0.07	<0.1	0.04	1.7	<0.1	<0.05	4	0.9	<0.2
KYS 110991	Soil	20	30	0.70	1980	0.002	<1	1.48	0.003	0.08	<0.1	0.04	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 110995	Soil	21	19	0.49	960	0.002	<1	1.11	0.002	0.08	<0.1	0.06	1.2	<0.1	0.05	3	0.9	<0.2
KYS 112009	Soil	7	27	0.22	108	0.003	<1	1.15	0.007	0.03	<0.1	0.10	1.3	<0.1	<0.05	4	2.4	<0.2
KYS 110997	Soil	23	23	0.59	355	0.002	<1	1.33	0.003	0.10	<0.1	0.04	1.3	<0.1	<0.05	4	0.6	<0.2
KYS 109742	Soil	12	22	0.23	81	0.019	<1	1.02	0.005	0.06	<0.1	0.04	0.7	<0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112022	Soil		1.1	15.8	12.5	41	0.1	13.5	5.3	165	2.37	21.6	0.4	0.9	6.1	9	<0.1	2.9	0.3	26	0.21	0.026
KYS 112028	Soil		0.8	40.3	30.6	84	0.1	34.2	17.8	689	3.39	101.6	2.1	5.6	9.6	40	0.1	289.3	0.3	9	0.75	0.054
KYS 112316	Soil		2.0	25.3	12.8	51	0.1	21.8	7.7	239	2.84	16.7	0.8	6.4	1.3	9	0.2	1.1	0.2	57	0.08	0.061
KYS 109739	Soil		1.0	45.0	28.6	92	0.1	33.3	13.9	552	3.72	32.1	1.8	1.8	7.5	13	0.2	0.8	0.4	11	0.20	0.049
KYS 109743	Soil		0.9	48.5	37.0	96	0.2	39.0	19.4	997	3.61	55.3	2.1	7.0	4.9	12	0.2	0.8	0.5	17	0.14	0.068
KYS 109659	Soil		1.1	21.3	17.5	51	0.2	21.1	7.1	200	2.38	15.0	0.7	1.4	2.7	9	0.2	1.0	0.2	37	0.07	0.042
KYS 109663	Soil		0.8	45.0	31.2	84	0.1	42.4	19.5	586	3.34	26.8	1.2	4.9	17.1	14	0.3	3.0	0.3	15	0.16	0.046
KYS 109664	Soil		0.6	28.8	18.6	56	0.2	28.8	8.0	203	2.19	17.0	0.9	1.3	2.8	16	0.3	1.6	0.2	22	0.12	0.047
KYS 109662	Soil		0.9	31.0	24.1	75	<0.1	38.5	12.8	417	3.19	64.8	0.9	3.5	6.0	9	0.2	1.7	0.2	33	0.08	0.052
KYS 109883	Soil		1.1	30.3	23.4	84	0.2	28.9	14.4	723	3.15	21.7	1.3	2.1	5.8	30	0.3	1.1	0.3	14	0.46	0.065
KYS 109660	Soil		0.9	17.5	13.6	66	<0.1	31.0	8.0	237	2.56	9.7	0.6	0.8	2.5	7	0.2	1.1	0.2	37	0.06	0.037
KYS 112315	Soil		2.0	47.7	9.1	48	0.2	18.8	9.9	238	3.16	16.6	1.3	8.9	1.7	14	0.1	1.6	0.3	42	0.08	0.115
KYS 109882	Soil		1.2	28.2	20.3	86	0.2	27.5	13.2	1154	2.78	19.9	1.3	2.1	5.6	27	0.3	1.0	0.3	18	0.35	0.072
KYS 112319	Soil		0.4	91.8	2.6	71	<0.1	80.6	26.1	624	3.80	7.3	0.3	6.2	1.8	25	<0.1	0.3	<0.1	53	0.75	0.270
KYS 112314	Soil		1.6	58.9	15.8	78	0.1	32.0	11.6	374	3.03	102.8	0.9	3.4	1.0	13	0.3	2.0	0.2	50	0.13	0.089
KYS 109744	Soil		0.6	44.2	26.9	79	<0.1	33.6	15.6	724	3.32	13.3	1.8	0.8	9.1	8	<0.1	0.6	0.3	14	0.11	0.057
KYS 109741	Soil		0.9	36.5	26.9	81	<0.1	33.4	14.4	727	3.03	14.3	1.4	1.4	4.9	12	0.2	0.6	0.3	27	0.15	0.063
KYS 109738	Soil		0.9	46.8	29.8	86	0.1	36.0	18.6	831	3.56	56.0	1.6	2.9	11.7	12	0.2	1.3	0.4	8	0.23	0.070
KYS 112032	Soil		1.2	53.6	33.6	103	0.2	43.0	20.0	872	4.03	143.9	1.5	16.5	17.0	15	0.2	355.4	0.3	12	0.16	0.054
KYS 109740	Soil		1.1	27.0	19.7	55	0.1	19.3	7.7	290	2.55	16.1	1.0	0.6	1.2	8	0.1	0.7	0.3	29	0.10	0.058
KYS 109745	Soil		1.6	95.7	16.6	105	0.2	47.8	19.5	680	3.99	24.0	1.2	2.0	5.4	16	0.4	1.6	0.2	55	0.26	0.106
KYS 109884	Soil		1.0	28.5	19.5	73	0.1	26.9	13.2	617	2.98	19.5	1.1	2.2	5.5	32	0.2	1.2	0.2	16	0.54	0.063
KYS 112030	Soil		1.0	48.5	31.4	97	0.2	39.2	17.8	776	3.64	198.7	1.9	18.7	13.5	27	0.2	489.6	0.3	11	0.45	0.053
KYS 112180	Soil		1.0	42.0	28.6	89	<0.1	38.7	23.1	782	3.98	39.6	1.6	<0.5	4.2	12	0.1	0.5	0.4	13	0.14	0.058
KYS 110112	Soil		0.9	33.0	21.7	51	0.2	20.6	7.6	204	2.24	14.5	1.1	3.2	2.9	22	0.1	1.2	0.2	36	0.22	0.044
KYS 112057	Soil		1.6	27.2	19.9	62	0.1	22.4	9.9	291	3.09	26.5	1.2	4.7	8.5	10	<0.1	3.6	0.3	49	0.07	0.030
KYS 112175	Soil		0.9	24.3	21.8	72	<0.1	24.3	11.4	470	3.13	14.5	1.2	1.5	1.7	10	0.2	0.8	0.3	38	0.09	0.051
KYS 110075	Soil		1.0	34.9	27.2	67	0.2	24.2	8.3	201	2.91	22.7	1.4	2.3	3.6	16	0.1	2.1	0.3	43	0.14	0.065
KYS 112062	Soil		1.2	21.9	15.3	64	0.4	20.1	5.7	150	2.27	11.1	1.1	1.5	0.3	13	0.3	1.0	0.2	35	0.08	0.068
KYS 112063	Soil		1.1	21.9	20.1	62	<0.1	18.0	7.9	313	2.44	11.7	1.1	2.6	1.1	12	0.2	1.1	0.2	37	0.10	0.068

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112022	Soil		21	17	0.29	72	0.005	<1	1.05	0.005	0.04	<0.1	<0.01	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 112028	Soil		15	18	0.54	63	0.002	2	1.19	0.005	0.07	<0.1	0.03	1.1	<0.1	<0.05	3	0.6	<0.2
KYS 112316	Soil		12	28	0.29	57	0.034	1	1.42	0.006	0.04	0.2	0.10	1.6	<0.1	<0.05	5	0.6	<0.2
KYS 109739	Soil		16	13	0.40	52	0.002	<1	1.06	0.003	0.05	<0.1	0.03	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 109743	Soil		17	17	0.40	78	0.009	<1	1.10	0.007	0.05	<0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109659	Soil		15	27	0.37	96	0.014	<1	1.33	0.005	0.04	0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109663	Soil		28	23	0.60	124	0.004	<1	1.46	0.002	0.07	<0.1	0.02	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109664	Soil		15	32	0.52	156	0.004	<1	1.26	0.006	0.06	<0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109662	Soil		20	41	0.60	96	0.011	<1	1.54	0.005	0.05	0.1	0.03	1.7	<0.1	<0.05	5	<0.5	<0.2
KYS 109883	Soil		15	21	0.47	153	0.002	<1	1.27	0.006	0.05	<0.1	0.04	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109660	Soil		11	44	0.55	112	0.014	1	1.34	0.007	0.06	<0.1	0.03	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 112315	Soil		19	25	0.30	56	0.017	<1	1.14	0.007	0.04	0.2	0.03	1.2	<0.1	<0.05	4	1.0	<0.2
KYS 109882	Soil		17	18	0.42	203	0.004	<1	1.16	0.006	0.05	<0.1	0.05	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 112319	Soil		7	96	1.95	119	0.108	<1	2.20	0.004	0.08	<0.1	0.01	3.4	<0.1	<0.05	5	<0.5	<0.2
KYS 112314	Soil		15	35	0.45	95	0.020	<1	1.31	0.011	0.04	0.2	0.03	1.5	<0.1	<0.05	5	0.8	<0.2
KYS 109744	Soil		24	12	0.36	72	0.009	<1	1.02	0.006	0.04	<0.1	0.02	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 109741	Soil		18	19	0.36	90	0.019	1	1.08	0.007	0.05	0.2	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109738	Soil		26	8	0.27	44	0.004	<1	0.64	0.005	0.04	<0.1	0.03	2.0	<0.1	<0.05	2	<0.5	<0.2
KYS 112032	Soil		32	21	0.61	52	0.003	<1	1.36	0.006	0.08	<0.1	0.02	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109740	Soil		13	14	0.22	63	0.013	<1	0.81	0.007	0.05	0.1	0.04	0.9	<0.1	0.05	3	<0.5	<0.2
KYS 109745	Soil		20	48	0.88	135	0.027	<1	1.68	0.005	0.05	<0.1	0.03	3.4	<0.1	<0.05	5	0.7	<0.2
KYS 109884	Soil		16	20	0.48	150	0.003	<1	1.18	0.006	0.06	<0.1	0.03	1.3	<0.1	0.06	3	<0.5	<0.2
KYS 112030	Soil		26	19	0.54	57	0.003	<1	1.25	0.005	0.09	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 112180	Soil		16	21	0.72	33	0.004	<1	1.64	0.006	0.06	<0.1	0.02	1.4	<0.1	<0.05	5	<0.5	<0.2
KYS 110112	Soil		22	20	0.33	177	0.019	<1	1.26	0.007	0.08	0.2	0.04	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 112057	Soil		21	30	0.45	185	0.032	<1	2.09	0.007	0.05	0.2	0.03	3.2	0.1	<0.05	5	0.5	<0.2
KYS 112175	Soil		20	26	0.46	98	0.019	<1	1.65	0.006	0.05	0.1	0.04	1.5	<0.1	<0.05	5	0.6	<0.2
KYS 110075	Soil		21	26	0.46	206	0.019	<1	1.71	0.008	0.08	0.2	0.05	2.5	0.1	<0.05	5	0.6	<0.2
KYS 112062	Soil		14	21	0.36	117	0.009	<1	1.37	0.008	0.05	0.1	0.07	0.8	<0.1	<0.05	4	0.7	<0.2
KYS 112063	Soil		20	22	0.36	112	0.015	<1	1.27	0.006	0.05	0.1	0.02	1.2	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112064	Soil		0.9	32.0	18.0	68	0.2	25.9	10.6	386	2.66	9.8	1.1	2.8	1.6	17	0.3	1.4	0.3	31	0.16	0.066
KYS 112254	Soil		0.9	51.7	27.5	95	0.1	39.4	14.2	489	4.35	18.1	2.3	1.8	15.1	22	<0.1	5.9	0.4	18	0.27	0.050
KYS 112117	Soil		1.0	86.5	38.3	139	0.1	53.8	27.5	1369	5.00	48.5	2.5	4.4	20.0	28	0.3	33.1	0.6	14	0.26	0.055
KYS 110037	Soil		1.6	22.8	29.4	45	<0.1	9.4	3.8	158	2.28	22.3	1.1	1.5	3.1	9	<0.1	5.6	0.4	23	0.02	0.077
KYS 112118	Soil		0.9	64.5	76.4	265	0.2	58.5	49.5	2372	4.19	77.0	3.1	3.3	14.0	47	1.1	40.7	0.8	10	0.76	0.073
KYS 109656	Soil		1.5	41.7	14.9	79	0.3	30.3	8.5	221	2.66	15.2	0.9	4.4	4.5	13	0.3	3.2	0.2	36	0.07	0.066
KYS 109655	Soil		1.7	26.0	15.8	64	0.3	20.3	5.7	214	3.04	12.3	0.7	10.5	1.6	13	0.2	2.0	0.3	32	0.06	0.063
KYS 109658	Soil		1.0	22.0	18.6	48	0.1	23.7	8.0	210	2.43	11.9	0.7	2.7	5.3	9	0.1	1.0	0.2	29	0.13	0.058
KYS 109648	Soil		1.3	40.9	14.1	98	<0.1	60.9	30.4	927	5.05	29.4	0.7	2.5	5.4	12	0.3	1.7	0.2	27	0.20	0.068
KYS 110989	Soil		0.9	31.0	22.8	76	<0.1	46.6	17.1	660	3.50	13.7	0.9	1.6	6.9	13	<0.1	1.0	0.2	23	0.19	0.054
KYS 109647	Soil		1.6	26.7	22.2	66	0.2	22.2	8.8	500	3.29	40.0	1.0	4.4	5.3	16	0.1	10.6	0.3	13	0.57	0.123
KYS 110990	Soil		0.6	24.3	19.8	79	<0.1	30.7	12.5	380	3.31	9.0	1.1	1.8	9.4	14	<0.1	0.5	0.3	15	0.19	0.048
KYS 110988	Soil		0.6	25.3	33.1	86	<0.1	29.1	13.7	619	3.59	6.1	1.1	0.8	10.2	18	<0.1	0.4	0.3	14	0.24	0.055
KYS 109653	Soil		4.7	34.6	20.9	119	0.4	34.7	11.0	532	3.66	88.1	1.5	10.3	2.2	21	0.5	7.6	0.3	36	0.04	0.087
KYS 109644	Soil		16.6	90.5	30.9	114	0.6	66.9	33.1	2438	5.84	193.7	1.1	24.3	13.2	61	0.4	79.8	0.6	7	4.15	0.174
KYS 109657	Soil		2.0	17.5	14.7	50	0.2	14.0	4.0	146	2.91	14.2	0.6	1.9	1.4	7	0.2	1.4	0.3	47	0.04	0.061
KYS 110985	Soil		0.9	37.1	20.7	92	0.1	37.4	15.0	581	3.47	48.6	1.4	3.8	7.8	27	0.2	2.9	0.2	15	0.54	0.063
KYS 109701	Soil		1.5	41.2	25.2	77	<0.1	23.5	9.3	314	3.48	10.7	1.1	1.6	9.5	7	<0.1	5.3	0.4	16	0.04	0.040
KYS 110956	Soil		1.1	26.3	27.3	62	<0.1	27.9	15.9	910	3.27	13.9	1.2	2.6	3.0	9	0.1	0.5	0.3	33	0.10	0.050
KYS 110960	Soil		1.3	16.9	17.8	68	<0.1	21.6	11.0	593	3.93	17.0	0.6	2.0	2.8	7	0.2	0.7	0.2	48	0.07	0.056
KYS 109708	Soil		1.5	27.0	27.5	78	0.1	33.4	18.1	1019	3.11	15.0	1.4	2.3	3.3	8	0.3	0.7	0.2	36	0.08	0.068
KYS 109702	Soil		1.7	61.6	34.8	104	0.2	30.4	13.7	359	4.22	134.8	1.7	13.4	11.1	11	<0.1	200.2	0.5	9	0.09	0.052
KYS 109700	Soil		1.0	34.5	22.4	65	0.2	22.9	9.8	567	3.21	18.7	2.1	4.0	5.0	20	0.1	10.6	0.3	18	0.42	0.056
KYS 109697	Soil		0.7	39.2	22.9	78	0.1	33.2	14.0	839	3.29	31.4	1.6	4.9	10.2	33	<0.1	2.7	0.3	15	0.48	0.042
KYS 109709	Soil		1.0	21.4	16.2	66	<0.1	30.6	13.7	544	2.85	13.2	1.0	2.2	3.8	9	0.2	0.7	0.2	35	0.11	0.051
KYS 109710	Soil		1.0	37.9	37.7	82	0.3	46.0	22.0	1364	4.05	19.3	1.9	5.4	2.4	12	0.3	0.6	0.4	31	0.10	0.059
KYS 110957	Soil		1.3	16.1	17.6	54	<0.1	18.2	10.1	545	3.24	12.7	0.8	4.0	1.5	8	0.2	0.6	0.2	42	0.07	0.053
KYS 110959	Soil		1.9	19.4	20.3	57	0.2	22.4	10.3	781	2.75	11.2	1.3	2.2	0.4	9	0.3	0.8	0.3	37	0.07	0.082
KYS 110958	Soil		1.4	21.8	15.2	59	<0.1	19.8	8.9	387	3.01	12.5	1.1	2.7	1.1	10	0.2	0.6	0.2	48	0.09	0.051
KYS 112116	Soil		1.0	54.4	31.6	115	0.2	46.1	19.3	864	4.09	149.9	1.5	12.9	14.2	14	0.2	65.0	0.4	13	0.21	0.060

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112064	Soil	24	21	0.41	135	0.011	<1	1.33	0.007	0.05	<0.1	0.04	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 112254	Soil	44	25	1.01	49	0.005	<1	1.97	0.006	0.04	<0.1	0.02	1.6	<0.1	<0.05	6	<0.5	<0.2
KYS 112117	Soil	35	21	0.67	69	0.002	<1	1.70	0.009	0.07	<0.1	0.03	1.9	<0.1	<0.05	5	<0.5	<0.2
KYS 110037	Soil	43	14	0.50	52	0.003	<1	1.37	0.004	0.04	<0.1	0.02	0.5	<0.1	<0.05	6	<0.5	<0.2
KYS 112118	Soil	16	18	0.55	81	0.002	<1	1.51	0.009	0.07	<0.1	0.05	2.0	<0.1	0.06	4	<0.5	<0.2
KYS 109656	Soil	14	24	0.30	101	0.018	<1	1.57	0.007	0.04	<0.1	0.10	2.2	<0.1	<0.05	4	1.2	<0.2
KYS 109655	Soil	9	23	0.28	112	0.013	<1	1.47	0.005	0.04	0.1	0.06	1.2	<0.1	<0.05	4	0.9	0.2
KYS 109658	Soil	15	21	0.33	66	0.018	<1	1.31	0.004	0.05	0.2	0.04	1.4	<0.1	<0.05	3	0.6	<0.2
KYS 109648	Soil	17	65	0.71	88	0.004	<1	1.79	0.003	0.04	<0.1	0.02	3.0	<0.1	<0.05	5	<0.5	<0.2
KYS 110989	Soil	16	32	0.60	93	0.009	<1	1.46	0.004	0.07	0.1	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109647	Soil	14	14	0.43	168	0.002	<1	1.15	0.006	0.06	<0.1	0.05	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 110990	Soil	19	21	0.64	126	0.003	<1	1.70	0.003	0.07	<0.1	0.03	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 110988	Soil	17	18	0.51	146	0.002	1	1.51	0.003	0.06	<0.1	0.02	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 109653	Soil	18	23	0.33	365	0.012	<1	1.25	0.004	0.06	0.1	0.05	1.3	<0.1	<0.05	4	1.8	<0.2
KYS 109644	Soil	15	6	2.08	139	0.003	<1	0.37	0.004	0.05	0.2	0.08	2.9	0.1	<0.05	<1	0.7	<0.2
KYS 109657	Soil	11	23	0.21	90	0.017	<1	1.14	0.005	0.04	0.1	0.04	1.1	<0.1	<0.05	6	0.6	<0.2
KYS 110985	Soil	15	26	0.67	596	0.003	1	1.21	0.004	0.09	<0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109701	Soil	31	19	0.43	35	0.006	<1	1.19	0.004	0.04	<0.1	0.02	1.1	<0.1	<0.05	4	0.7	0.2
KYS 110956	Soil	20	25	0.51	90	0.017	<1	1.50	0.004	0.05	0.2	0.03	1.2	<0.1	<0.05	4	0.6	<0.2
KYS 110960	Soil	14	29	0.44	84	0.020	<1	1.70	0.004	0.05	0.2	0.04	1.7	<0.1	<0.05	6	0.5	<0.2
KYS 109708	Soil	12	25	0.44	80	0.022	2	1.64	0.006	0.06	0.2	0.06	1.5	<0.1	<0.05	4	0.6	<0.2
KYS 109702	Soil	25	17	0.47	51	0.002	<1	1.12	0.005	0.05	<0.1	0.02	1.3	<0.1	<0.05	3	0.9	<0.2
KYS 109700	Soil	18	20	0.46	92	0.005	<1	1.23	0.006	0.05	<0.1	0.05	1.3	<0.1	<0.05	3	1.2	<0.2
KYS 109697	Soil	26	20	0.66	63	0.004	<1	1.54	0.005	0.06	<0.1	0.02	1.2	<0.1	<0.05	4	0.8	<0.2
KYS 109709	Soil	16	22	0.37	60	0.030	1	1.29	0.005	0.05	0.2	0.03	1.3	<0.1	<0.05	4	0.5	<0.2
KYS 109710	Soil	16	23	0.49	111	0.017	<1	1.58	0.005	0.06	0.1	0.05	1.6	<0.1	<0.05	4	0.5	<0.2
KYS 110957	Soil	16	23	0.34	65	0.024	<1	1.29	0.005	0.05	0.1	0.03	1.1	<0.1	<0.05	5	0.7	<0.2
KYS 110959	Soil	13	23	0.29	105	0.014	<1	1.11	0.006	0.06	0.1	0.04	0.6	<0.1	<0.05	4	0.6	<0.2
KYS 110958	Soil	15	26	0.39	124	0.022	<1	1.75	0.005	0.06	0.2	0.04	1.4	<0.1	<0.05	5	0.9	<0.2
KYS 112116	Soil	32	18	0.71	69	0.004	<1	1.59	0.003	0.08	<0.1	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112058	Soil	1.3	29.2	20.0	62	<0.1	21.9	10.2	301	3.07	20.6	0.7	5.8	5.2	9	0.2	2.1	0.2	44	0.06	0.044
KYS 109892	Soil	1.0	66.6	55.2	153	0.1	47.8	26.2	1397	4.16	15.9	1.4	2.0	17.0	16	0.3	2.6	0.5	16	0.17	0.065
KYS 110074	Soil	0.8	26.8	19.4	56	<0.1	21.9	9.2	262	2.39	13.5	1.0	2.0	7.8	14	<0.1	1.3	0.2	33	0.13	0.043
KYS 112171	Soil	0.8	53.3	34.7	112	<0.1	47.3	25.0	1088	4.36	9.5	1.6	4.1	12.1	13	0.1	1.0	0.4	13	0.12	0.050
KYS 112252	Soil	1.2	17.6	25.9	62	0.3	28.3	11.5	416	3.05	12.8	0.9	3.8	7.9	10	0.2	0.7	0.2	39	0.11	0.038
KYS 112253	Soil	1.0	19.9	18.2	54	0.2	23.3	7.8	280	3.05	12.3	0.8	9.8	5.9	13	0.1	0.6	0.2	37	0.13	0.060
KYS 112172	Soil	0.6	50.8	24.0	90	<0.1	43.2	21.3	923	4.60	9.4	1.6	3.6	13.9	9	<0.1	0.7	0.4	11	0.12	0.044
KYS 112256	Soil	0.9	25.4	11.6	72	0.1	23.0	9.1	382	2.38	10.7	0.6	2.1	5.2	20	0.2	1.5	0.2	26	0.33	0.063
KYS 109886	Soil	1.1	26.6	19.3	83	0.2	29.5	14.1	921	3.26	15.8	1.0	4.3	6.1	23	0.2	1.1	0.2	18	0.44	0.062
KYS 109397	Soil	1.0	17.7	23.1	43	0.2	16.5	5.6	176	2.33	12.2	0.8	5.3	6.2	8	0.1	0.6	0.2	38	0.06	0.031
KYS 109887	Soil	1.1	32.8	20.4	78	0.2	32.1	12.6	536	3.06	17.5	1.1	5.9	4.8	38	0.2	1.2	0.2	14	0.74	0.068
KYS 109901	Soil	9.9	18.2	22.6	81	0.6	21.2	3.4	180	2.98	12.6	0.7	2.8	2.6	10	0.1	2.0	0.4	50	0.03	0.074
KYS 109896	Soil	3.7	71.9	25.4	58	1.1	13.9	2.6	197	4.72	11.7	2.8	7.8	3.1	18	<0.1	2.8	0.7	51	0.02	0.143
KYS 109894	Soil	5.0	56.0	34.7	78	0.9	19.1	3.6	221	4.14	41.2	1.3	12.2	2.3	13	0.4	3.6	0.6	34	0.01	0.106
KYS 109895	Soil	6.8	60.5	29.8	144	0.5	62.6	18.6	954	4.38	17.2	2.5	5.3	4.6	14	0.7	2.2	0.4	45	0.05	0.072
KYS 112184	Soil	1.0	12.4	18.4	49	0.1	14.2	8.7	662	2.55	11.4	0.6	1.3	3.1	9	0.1	0.5	0.3	47	0.11	0.030
KYS 112185	Soil	1.1	15.1	18.2	43	0.2	14.8	6.7	434	2.92	16.0	0.7	5.3	3.0	7	<0.1	0.6	0.3	45	0.07	0.040
KYS 112183	Soil	0.8	19.7	12.4	58	<0.1	29.5	12.3	637	2.51	23.2	0.8	3.2	5.1	11	0.2	0.9	0.2	38	0.14	0.052
KYS 110747	Soil	22.7	62.1	21.3	190	2.9	50.7	5.4	123	3.08	32.5	3.8	3.0	3.9	29	1.2	23.5	0.3	56	0.14	0.184
KYS 112187	Soil	0.9	25.0	22.0	72	0.1	21.2	13.9	739	3.25	19.8	1.1	0.9	2.8	8	0.2	0.4	0.4	36	0.06	0.056
KYS 112182	Soil	0.7	14.2	42.8	55	<0.1	13.6	9.4	1995	4.13	9.1	1.1	3.8	1.0	11	0.2	0.2	0.6	10	0.11	0.088
KYS 109902	Soil	2.7	56.8	18.3	84	0.3	30.9	7.7	332	3.72	21.4	1.0	10.2	2.8	12	0.2	2.6	0.3	36	0.04	0.065
KYS 112181	Soil	0.7	21.8	19.4	62	<0.1	26.1	11.8	443	3.00	33.7	1.0	0.6	3.0	6	<0.1	0.5	0.3	17	0.08	0.046
KYS 112061	Soil	1.6	50.2	14.6	69	0.3	28.3	9.3	383	2.59	20.5	1.5	12.5	1.6	13	0.2	4.4	0.2	33	0.12	0.056
KYS 112059	Soil	1.7	38.1	18.1	62	<0.1	23.9	8.6	254	2.96	20.2	1.0	11.1	4.4	8	0.3	3.9	0.2	37	0.06	0.042
KYS 112176	Soil	0.8	24.1	20.5	68	<0.1	26.5	12.3	578	2.99	22.8	1.2	2.4	1.3	8	0.1	0.7	0.2	33	0.07	0.049
KYS 112255	Soil	0.9	20.9	11.7	60	0.1	22.1	9.3	318	2.08	10.3	0.7	4.1	5.4	15	0.2	1.4	0.2	28	0.23	0.053
KYS 112115	Soil	1.0	54.1	31.7	104	0.2	38.1	17.9	673	4.02	168.2	1.7	19.1	13.6	24	0.1	51.4	0.4	15	0.38	0.055
KYS 112060	Soil	1.5	52.6	14.3	69	0.4	29.6	8.5	342	2.59	21.1	1.5	9.0	0.9	14	0.2	4.4	0.2	33	0.13	0.060
KYS 112114	Soil	0.9	42.2	22.1	106	0.2	44.4	18.7	780	3.26	114.8	1.0	21.4	7.1	20	0.2	56.3	0.3	17	0.80	0.055

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112058	Soil		16	26	0.39	113	0.030	2	1.35	0.007	0.04	0.2	0.02	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109892	Soil		26	24	0.72	63	0.004	<1	1.59	0.005	0.05	<0.1	0.02	1.7	<0.1	<0.05	5	<0.5	<0.2
KYS 110074	Soil		24	23	0.45	137	0.023	1	1.27	0.006	0.06	0.1	0.02	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 112171	Soil		31	20	0.88	48	0.006	<1	1.75	0.005	0.05	<0.1	0.02	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 112252	Soil		21	25	0.34	164	0.017	<1	1.69	0.006	0.11	0.1	0.06	1.6	0.1	<0.05	4	0.6	<0.2
KYS 112253	Soil		22	23	0.34	98	0.023	<1	1.31	0.005	0.09	0.2	0.03	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 112172	Soil		42	19	0.75	60	0.005	<1	1.70	0.004	0.06	<0.1	0.02	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 112256	Soil		23	21	0.41	213	0.023	<1	1.12	0.007	0.06	0.1	0.04	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109886	Soil		16	20	0.50	200	0.004	<1	1.42	0.006	0.06	<0.1	0.04	1.3	<0.1	<0.05	4	0.8	<0.2
KYS 109397	Soil		22	19	0.23	111	0.015	1	1.24	0.005	0.07	0.1	0.03	1.2	0.1	<0.05	5	<0.5	<0.2
KYS 109887	Soil		11	20	0.57	192	0.002	2	1.40	0.006	0.06	<0.1	0.05	1.2	<0.1	<0.05	3	0.5	<0.2
KYS 109901	Soil		13	23	0.10	167	0.019	1	0.80	0.005	0.05	0.2	0.05	0.9	<0.1	<0.05	5	1.6	<0.2
KYS 109896	Soil		10	26	0.18	265	0.004	<1	1.08	0.009	0.06	<0.1	0.14	0.9	<0.1	0.19	4	2.9	0.2
KYS 109894	Soil		12	24	0.17	259	0.002	<1	1.04	0.006	0.04	<0.1	0.11	1.3	<0.1	<0.05	4	3.6	0.2
KYS 109895	Soil		11	33	0.49	1012	0.002	<1	1.23	0.004	0.05	<0.1	0.13	1.7	<0.1	<0.05	3	2.1	<0.2
KYS 112184	Soil		16	23	0.33	121	0.014	<1	1.50	0.004	0.05	0.2	0.04	1.4	0.1	<0.05	6	<0.5	<0.2
KYS 112185	Soil		19	20	0.28	80	0.022	<1	1.09	0.003	0.05	0.2	0.03	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 112183	Soil		18	25	0.42	101	0.034	<1	1.42	0.007	0.05	0.2	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110747	Soil		7	11	0.04	333	0.003	2	0.93	0.003	0.09	0.4	0.97	1.1	0.2	0.19	1	4.7	<0.2
KYS 112187	Soil		19	20	0.33	85	0.008	<1	1.46	0.003	0.05	<0.1	0.04	1.0	0.1	<0.05	6	<0.5	<0.2
KYS 112182	Soil		6	11	0.18	56	0.003	<1	0.67	0.003	0.04	<0.1	0.03	1.2	<0.1	<0.05	2	<0.5	<0.2
KYS 109902	Soil		9	28	0.33	114	0.010	<1	1.47	0.006	0.04	0.1	0.08	1.4	<0.1	<0.05	4	1.4	<0.2
KYS 112181	Soil		14	20	0.52	59	0.002	<1	1.39	0.007	0.07	<0.1	0.04	0.8	<0.1	<0.05	5	<0.5	<0.2
KYS 112061	Soil		17	21	0.28	191	0.013	<1	1.10	0.006	0.05	0.1	0.08	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 112059	Soil		17	23	0.31	105	0.020	<1	1.32	0.006	0.05	0.1	0.05	1.7	<0.1	<0.05	3	<0.5	0.2
KYS 112176	Soil		20	23	0.45	79	0.015	<1	1.44	0.004	0.05	0.1	0.03	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 112255	Soil		23	21	0.39	146	0.029	<1	0.98	0.007	0.05	0.1	0.02	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 112115	Soil		34	22	0.66	72	0.004	<1	1.43	0.005	0.06	<0.1	0.04	1.5	<0.1	<0.05	4	0.5	<0.2
KYS 112060	Soil		18	21	0.27	191	0.014	<1	1.09	0.007	0.06	0.1	0.08	1.3	<0.1	<0.05	3	0.5	0.3
KYS 112114	Soil		22	22	0.68	85	0.005	<1	1.18	0.007	0.05	<0.1	0.04	1.4	<0.1	<0.05	3	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112119	Soil	0.9	57.5	44.1	127	0.1	42.9	20.8	558	4.74	33.9	2.3	1.3	14.4	34	0.1	17.2	0.6	12	0.36	0.046
KYS 112120	Soil	0.7	52.1	56.5	140	0.3	43.0	20.6	874	3.87	253.8	1.7	26.7	13.9	34	0.3	78.5	0.4	13	0.55	0.042
KYS 109888	Soil	1.1	26.8	23.7	97	<0.1	38.7	18.5	777	3.39	18.5	0.9	0.7	8.8	17	0.2	1.1	0.2	12	0.35	0.053
KYS 109398	Soil	0.7	21.3	16.9	55	<0.1	23.1	8.4	202	2.40	22.7	0.8	2.3	7.0	11	<0.1	1.7	0.2	31	0.09	0.031
KYS 109889	Soil	1.0	25.7	22.6	94	<0.1	39.0	18.2	781	3.30	17.8	1.0	1.7	8.9	18	0.2	1.1	0.2	12	0.34	0.050
KYS 109694	Soil	0.7	61.8	45.4	125	0.2	50.7	25.0	1080	4.41	113.5	1.6	15.8	18.2	20	0.3	35.1	0.5	14	0.35	0.048
KYS 109699	Soil	1.0	43.6	28.3	81	0.1	23.4	10.9	487	3.57	51.5	1.7	7.3	9.0	23	0.1	9.4	0.4	14	0.38	0.057
KYS 110955	Soil	0.9	33.7	23.8	72	<0.1	36.2	16.6	912	3.35	15.6	1.5	1.2	2.2	9	0.1	0.8	0.3	31	0.09	0.052
KYS 109696	Soil	0.7	51.6	69.5	135	0.4	40.8	17.7	618	3.90	217.3	2.1	29.1	11.6	48	0.3	57.5	0.4	11	0.82	0.048
KYS 109897	Soil	3.7	69.9	26.1	84	0.4	24.5	5.5	401	5.47	12.7	0.8	7.2	1.2	9	0.1	1.9	0.5	59	0.03	0.103
KYS 109698	Soil	0.8	42.2	20.7	84	0.2	36.9	14.6	879	3.62	32.1	1.2	8.8	9.8	16	<0.1	2.9	0.3	18	0.17	0.036
KYS 109695	Soil	0.6	62.4	40.9	120	0.2	44.5	22.0	832	3.96	119.7	1.5	17.9	11.5	46	0.3	27.2	0.4	14	0.91	0.057
KYS 110961	Soil	1.9	22.6	16.5	65	0.2	21.1	14.8	815	3.09	15.4	1.3	0.8	0.3	13	0.2	0.7	0.3	51	0.07	0.081
KYS 110748	Soil	11.2	64.3	35.3	205	1.2	77.4	21.4	818	4.37	24.0	3.5	5.0	5.5	25	2.4	4.3	0.3	34	0.11	0.117
KYS 109898	Soil	2.9	70.5	24.5	87	0.6	26.3	5.2	301	4.72	17.2	0.9	9.1	1.2	13	0.2	1.8	0.5	53	0.03	0.108
KYS 109899	Soil	3.3	28.4	30.7	74	0.8	20.7	4.9	276	3.80	16.0	0.8	5.3	2.2	14	0.2	2.6	0.7	40	0.04	0.119
KYS 109900	Soil	2.9	40.8	25.4	91	0.5	28.2	7.0	409	4.38	14.7	0.8	9.1	1.7	13	0.3	1.7	0.5	60	0.05	0.089
KYS 111564	Soil	2.8	22.8	15.5	59	0.2	18.8	4.9	174	2.91	17.1	0.9	3.4	0.5	8	0.1	1.1	0.3	82	0.05	0.079
KYS 109912	Soil	2.8	47.7	24.1	88	0.4	29.6	12.1	498	3.36	30.2	1.5	7.1	6.0	12	0.2	4.7	0.5	44	0.07	0.082
KYS 111566	Soil	1.1	37.2	34.5	85	0.1	33.3	16.7	594	3.35	44.9	1.5	2.9	6.8	8	0.2	1.2	0.4	32	0.07	0.055
KYS 111565	Soil	3.2	37.3	28.0	149	0.2	41.4	13.7	502	3.06	93.5	1.9	5.0	3.5	12	0.6	2.0	0.3	40	0.09	0.077
KYS 109915	Soil	2.6	35.5	16.8	75	0.6	24.6	7.1	272	2.44	22.3	1.5	8.7	2.3	18	0.3	2.8	0.3	42	0.17	0.089
KYS 111574	Soil	3.5	37.2	25.3	40	0.7	15.8	3.5	141	2.66	41.4	1.1	10.9	5.7	18	<0.1	4.3	0.6	38	0.05	0.070
KYS 109920	Soil	0.8	35.0	35.1	114	0.1	36.7	14.0	552	3.02	42.0	1.4	6.0	7.3	22	0.2	2.9	0.3	13	0.47	0.048
KYS 109911	Soil	2.1	32.6	18.2	70	0.3	22.4	8.2	351	2.83	25.0	1.0	7.9	2.4	13	0.2	3.5	0.3	42	0.09	0.075
KYS 109914	Soil	6.3	24.9	19.3	57	0.4	17.8	6.4	182	2.18	25.0	1.1	6.9	2.9	18	<0.1	5.0	0.3	30	0.11	0.062
KYS 109913	Soil	7.8	30.6	22.0	52	0.5	16.6	7.3	396	2.46	28.9	1.2	11.6	2.8	21	0.1	6.8	0.3	41	0.10	0.080
KYS 111691	Soil	2.0	17.1	15.2	25	0.2	8.6	1.9	71	1.49	19.9	0.6	6.4	0.2	10	<0.1	2.3	0.4	38	0.03	0.054
KYS 111709	Soil	1.2	26.4	22.6	72	<0.1	22.9	10.2	449	2.99	10.7	1.1	3.1	1.4	8	0.1	1.0	0.3	37	0.06	0.047
KYS 110946	Soil	4.0	45.7	39.7	149	0.3	43.5	20.3	890	3.77	91.7	2.0	7.7	15.3	15	0.7	4.0	0.5	21	0.17	0.066

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112119	Soil	29	21	0.58	66	0.001	<1	1.52	0.005	0.06	<0.1	0.02	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 112120	Soil	31	20	0.64	63	0.003	<1	1.36	0.005	0.07	<0.1	0.04	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109888	Soil	24	25	0.58	119	0.002	<1	1.25	0.004	0.08	<0.1	0.03	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109398	Soil	22	20	0.34	108	0.020	<1	1.06	0.005	0.07	0.1	0.03	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109889	Soil	24	24	0.56	122	0.002	<1	1.20	0.003	0.08	<0.1	0.03	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109694	Soil	36	22	0.68	68	0.008	<1	1.54	0.007	0.07	<0.1	0.04	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109699	Soil	28	22	0.49	45	0.004	<1	1.05	0.007	0.06	<0.1	0.03	1.1	<0.1	<0.05	3	0.5	<0.2
KYS 110955	Soil	22	24	0.51	99	0.014	<1	1.50	0.005	0.06	0.1	0.04	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 109696	Soil	24	19	0.58	63	0.002	<1	1.27	0.007	0.07	<0.1	0.06	1.4	<0.1	0.05	4	<0.5	<0.2
KYS 109897	Soil	10	44	0.37	157	0.009	<1	1.93	0.007	0.06	<0.1	0.12	1.4	<0.1	<0.05	7	2.3	0.3
KYS 109698	Soil	30	23	0.58	129	0.003	<1	1.46	0.006	0.07	<0.1	0.03	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109695	Soil	20	21	0.67	74	0.002	1	1.41	0.009	0.07	<0.1	0.06	1.7	<0.1	0.06	4	<0.5	<0.2
KYS 110961	Soil	16	29	0.34	111	0.010	<1	1.42	0.003	0.07	<0.1	0.05	0.5	0.1	<0.05	6	<0.5	<0.2
KYS 110748	Soil	16	32	0.42	1480	0.001	<1	1.11	0.003	0.08	<0.1	0.28	1.7	0.1	0.11	3	2.7	<0.2
KYS 109898	Soil	8	37	0.28	162	0.007	<1	1.79	0.006	0.05	<0.1	0.08	1.3	<0.1	0.06	6	1.7	<0.2
KYS 109899	Soil	13	32	0.24	161	0.006	<1	1.36	0.008	0.05	<0.1	0.07	0.9	<0.1	0.05	5	1.5	<0.2
KYS 109900	Soil	12	40	0.32	153	0.019	<1	1.56	0.006	0.07	0.1	0.05	1.5	<0.1	<0.05	6	1.0	<0.2
KYS 111564	Soil	15	33	0.17	64	0.026	<1	1.22	0.004	0.05	0.2	0.08	1.0	0.2	0.05	7	0.6	<0.2
KYS 109912	Soil	13	26	0.33	153	0.021	<1	1.69	0.006	0.05	0.1	0.10	2.7	<0.1	0.08	4	0.7	<0.2
KYS 111566	Soil	20	23	0.47	64	0.018	<1	1.46	0.004	0.05	0.1	0.04	1.4	<0.1	0.09	4	<0.5	<0.2
KYS 111565	Soil	14	20	0.25	57	0.018	1	1.13	0.004	0.03	0.2	0.04	1.5	<0.1	0.09	3	1.2	0.3
KYS 109915	Soil	12	21	0.26	267	0.019	1	1.11	0.005	0.04	0.2	0.14	1.7	<0.1	0.07	3	0.8	<0.2
KYS 111574	Soil	9	23	0.15	71	0.012	<1	1.01	0.005	0.03	<0.1	0.10	1.5	<0.1	0.07	4	2.0	0.2
KYS 109920	Soil	16	15	0.25	91	0.004	<1	0.73	0.005	0.05	<0.1	0.05	2.0	<0.1	0.07	2	<0.5	<0.2
KYS 109911	Soil	13	24	0.28	112	0.019	<1	1.24	0.006	0.04	0.1	0.06	1.6	<0.1	<0.05	4	0.5	<0.2
KYS 109914	Soil	13	16	0.15	238	0.006	<1	0.78	0.004	0.04	0.2	0.08	0.9	<0.1	<0.05	2	0.9	<0.2
KYS 109913	Soil	13	17	0.16	245	0.010	<1	0.80	0.004	0.05	0.2	0.12	1.2	<0.1	<0.05	2	2.1	0.2
KYS 111691	Soil	8	18	0.09	38	0.009	<1	0.77	0.003	0.02	<0.1	0.04	0.2	<0.1	<0.05	5	0.8	0.2
KYS 111709	Soil	16	24	0.37	73	0.018	<1	1.42	0.004	0.05	0.1	0.02	1.1	<0.1	<0.05	4	<0.5	0.2
KYS 110946	Soil	37	19	0.54	334	0.002	1	1.33	0.004	0.08	<0.1	0.06	1.2	<0.1	<0.05	3	0.9	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110933	Soil	0.5	48.4	56.5	119	1.5	37.2	17.0	587	3.86	657.3	1.9	178.5	6.6	36	0.2	494.3	0.4	8	0.46	0.056
KYS 110940	Soil	1.0	69.9	55.6	90	0.1	47.1	24.9	1040	4.34	23.6	1.9	3.9	5.3	63	<0.1	1.6	0.6	7	0.93	0.064
KYS 110939	Soil	0.9	35.5	39.0	102	<0.1	32.2	20.2	709	3.66	12.5	1.4	0.9	14.8	12	<0.1	1.1	0.4	10	0.19	0.057
KYS 110948	Soil	8.4	63.7	38.2	121	0.9	30.1	7.3	313	4.49	30.3	3.3	9.8	8.6	18	0.5	7.9	0.5	39	0.05	0.102
KYS 110949	Soil	2.9	53.0	23.0	146	0.2	54.5	22.6	634	4.48	115.8	2.4	8.1	14.0	12	0.7	4.2	0.3	26	0.15	0.069
KYS 110936	Soil	0.8	43.3	55.5	124	1.7	34.8	15.9	781	3.43	528.7	1.5	61.4	4.8	54	0.2	441.9	0.3	6	0.74	0.050
KYS 110941	Soil	1.4	72.9	35.3	131	0.1	62.6	23.3	777	4.66	13.0	1.8	1.2	22.8	21	<0.1	0.9	0.4	7	0.25	0.047
KYS 112001	Soil	2.4	101.8	28.9	99	0.5	43.1	8.3	564	4.70	25.1	1.5	22.9	6.8	17	<0.1	3.2	0.7	32	0.05	0.077
KYS 112209	Soil	0.7	29.8	25.3	80	<0.1	28.2	14.6	762	3.53	26.1	1.6	3.5	4.7	5	0.1	2.2	0.3	24	0.04	0.052
KYS 110950	Soil	0.7	62.7	12.6	107	<0.1	67.2	35.6	1093	7.26	2.8	0.5	1.8	8.3	30	<0.1	0.6	0.2	112	0.58	0.097
KYS 110039	Soil	1.7	44.4	46.4	119	0.4	42.6	16.7	821	3.36	99.8	1.5	12.1	11.3	17	0.4	36.2	0.3	10	0.29	0.062
KYS 111687	Soil	1.6	34.9	26.9	92	0.3	34.1	14.6	536	3.55	39.3	1.3	6.4	6.6	10	0.2	1.5	0.3	16	0.08	0.057
KYS 111684	Soil	0.6	40.6	47.0	99	<0.1	38.7	21.5	990	3.83	20.2	1.8	5.4	16.9	13	0.1	2.2	0.7	8	0.08	0.059
KYS 109681	Soil	0.7	43.7	29.5	72	<0.1	39.9	19.2	509	3.64	43.2	0.9	5.2	16.1	17	<0.1	2.3	0.3	21	0.26	0.038
KYS 112241	Soil	1.0	41.2	20.0	70	<0.1	37.9	20.3	563	3.54	19.9	1.0	3.7	5.6	16	0.2	0.9	0.2	58	0.19	0.047
KYS 112233	Soil	0.5	70.0	41.2	103	<0.1	59.6	31.0	731	4.36	26.1	1.8	11.2	22.6	6	<0.1	5.2	0.5	16	0.13	0.043
KYS 109684	Soil	0.5	54.2	29.6	71	<0.1	37.4	16.2	784	2.86	17.4	2.3	3.5	11.2	54	0.2	1.6	0.2	8	0.89	0.054
KYS 112013	Soil	0.8	46.2	30.6	100	0.2	36.5	15.1	648	3.45	136.9	1.3	20.2	8.7	25	0.2	163.1	0.4	14	0.85	0.050
KYS 109688	Soil	1.3	37.3	25.4	77	0.1	35.7	13.7	568	3.11	16.0	2.0	2.7	13.3	24	0.2	1.5	0.3	10	0.36	0.044
KYS 109689	Soil	1.2	58.4	31.1	93	0.1	52.6	17.1	981	3.56	19.4	2.9	3.7	15.7	33	0.6	1.5	0.4	10	0.43	0.050
KYS 109683	Soil	0.3	30.6	24.1	51	<0.1	26.6	13.7	681	2.27	16.3	1.5	2.0	11.2	51	<0.1	1.3	0.2	10	0.74	0.045
KYS 109686	Soil	1.1	53.9	28.7	92	0.2	40.7	17.3	622	3.59	9.6	2.5	3.7	13.9	40	0.2	0.9	0.4	11	0.61	0.058
KYS 109680	Soil	1.7	46.9	29.9	81	0.1	41.6	22.9	712	4.28	246.8	1.7	16.9	12.9	24	0.2	4.4	0.4	15	0.36	0.053
KYS 111552	Soil	1.4	80.0	37.3	140	0.2	70.1	25.6	800	4.80	16.3	2.2	2.2	8.5	22	0.3	1.0	0.5	30	0.36	0.085
KYS 109939	Soil	1.3	44.3	25.1	101	0.1	45.5	18.9	652	3.71	44.8	1.8	4.1	13.3	19	0.3	1.5	0.3	17	0.26	0.058
KYS 109946	Soil	0.7	63.8	47.0	68	0.1	41.1	21.5	524	3.66	18.4	1.5	3.1	12.0	36	0.1	1.1	0.5	5	0.62	0.054
KYS 109949	Soil	0.5	34.9	23.5	74	<0.1	28.5	13.5	540	2.96	12.5	1.3	1.5	12.9	26	<0.1	0.8	0.3	9	0.44	0.052
KYS 112088	Soil	0.8	34.9	27.3	67	0.1	27.1	12.8	493	3.03	17.5	1.4	3.2	2.8	8	0.1	1.3	0.2	32	0.07	0.059
KYS 112086	Soil	1.1	18.8	15.1	45	0.2	18.0	7.3	206	2.93	18.1	0.8	4.9	3.0	10	<0.1	1.0	0.2	51	0.09	0.046
KYS 112092	Soil	1.0	23.7	17.3	50	<0.1	17.8	7.6	200	2.45	13.4	0.9	6.5	3.8	12	<0.1	0.8	0.2	48	0.09	0.038

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110933	Soil	15	15	0.54	67	0.003	<1	1.20	0.005	0.08	<0.1	0.04	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 110940	Soil	8	17	0.35	43	0.002	<1	1.02	0.005	0.05	<0.1	0.03	1.4	<0.1	0.06	3	<0.5	0.3
KYS 110939	Soil	26	19	0.60	62	0.002	<1	1.31	0.004	0.07	<0.1	0.03	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 110948	Soil	25	25	0.32	487	0.003	<1	1.31	0.004	0.06	<0.1	0.17	1.5	<0.1	<0.05	4	4.1	0.3
KYS 110949	Soil	37	41	0.92	336	0.003	<1	1.75	0.003	0.06	<0.1	0.05	2.4	<0.1	<0.05	4	1.3	<0.2
KYS 110936	Soil	12	14	0.40	186	0.002	1	0.96	0.006	0.10	<0.1	0.04	1.2	<0.1	0.07	3	1.0	<0.2
KYS 110941	Soil	35	24	0.73	49	0.003	<1	1.38	0.003	0.06	<0.1	0.03	1.6	<0.1	0.06	4	0.5	<0.2
KYS 112001	Soil	18	32	0.46	85	0.001	<1	1.47	0.005	0.03	<0.1	0.10	1.6	<0.1	0.06	4	1.9	0.5
KYS 112209	Soil	29	24	0.57	72	0.007	<1	1.80	0.003	0.05	<0.1	0.03	1.1	<0.1	<0.05	5	<0.5	0.2
KYS 110950	Soil	14	149	3.24	108	0.030	<1	3.79	0.001	0.08	<0.1	0.01	10.1	<0.1	<0.05	13	<0.5	0.2
KYS 110039	Soil	24	15	0.41	183	0.002	<1	0.98	0.003	0.07	<0.1	0.07	1.4	<0.1	<0.05	3	0.7	<0.2
KYS 111687	Soil	22	21	0.47	70	0.004	<1	1.40	0.003	0.05	<0.1	0.02	1.2	<0.1	<0.05	4	0.7	<0.2
KYS 111684	Soil	41	15	0.38	83	0.004	<1	1.22	0.003	0.09	<0.1	0.02	1.9	<0.1	0.07	3	<0.5	<0.2
KYS 109681	Soil	22	19	0.66	59	0.002	<1	1.28	0.004	0.10	<0.1	0.02	2.2	<0.1	0.07	4	<0.5	<0.2
KYS 112241	Soil	21	47	0.80	233	0.037	<1	2.20	0.006	0.05	0.2	0.03	3.2	<0.1	<0.05	6	<0.5	<0.2
KYS 112233	Soil	47	28	1.00	36	0.003	<1	2.12	0.003	0.05	<0.1	0.01	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 109684	Soil	18	14	0.40	92	0.002	<1	0.91	0.006	0.17	<0.1	0.04	1.2	<0.1	0.12	2	<0.5	<0.2
KYS 112013	Soil	20	19	0.66	76	0.004	<1	1.16	0.006	0.05	<0.1	0.04	1.6	<0.1	0.09	3	0.7	<0.2
KYS 109688	Soil	26	20	0.57	76	0.002	<1	1.16	0.004	0.12	<0.1	0.04	1.3	<0.1	0.08	3	<0.5	<0.2
KYS 109689	Soil	24	21	0.59	115	0.002	<1	1.35	0.004	0.10	<0.1	0.04	1.4	<0.1	0.07	4	<0.5	<0.2
KYS 109683	Soil	17	13	0.35	92	0.003	<1	0.85	0.006	0.19	<0.1	0.04	1.2	<0.1	0.13	2	<0.5	<0.2
KYS 109686	Soil	21	23	0.74	73	0.002	<1	1.49	0.005	0.11	<0.1	0.05	1.4	<0.1	0.09	4	<0.5	0.3
KYS 109680	Soil	24	15	0.45	60	0.001	<1	0.86	0.005	0.09	<0.1	0.03	2.5	<0.1	0.12	3	<0.5	0.3
KYS 111552	Soil	19	45	0.94	65	0.014	<1	1.80	0.003	0.06	<0.1	0.03	2.2	<0.1	0.09	5	1.1	<0.2
KYS 109939	Soil	26	40	0.80	205	0.003	1	1.54	0.004	0.07	<0.1	0.03	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109946	Soil	14	11	0.29	54	0.001	1	0.68	0.007	0.06	<0.1	0.03	1.1	<0.1	0.08	2	<0.5	<0.2
KYS 109949	Soil	21	17	0.48	80	0.002	<1	1.09	0.005	0.08	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 112088	Soil	30	25	0.56	83	0.012	<1	1.52	0.005	0.05	0.1	0.03	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 112086	Soil	22	24	0.37	66	0.021	<1	1.26	0.005	0.05	0.2	0.02	1.3	<0.1	<0.05	6	<0.5	<0.2
KYS 112092	Soil	17	26	0.37	125	0.035	1	1.39	0.007	0.06	0.2	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 112094	Soil	0.9	27.8	17.8	46	0.2	17.7	7.1	177	2.61	14.3	1.0	4.4	4.8	10	<0.1	0.8	0.2	44	0.06	0.046
KYS 112090	Soil	1.2	24.7	23.3	55	0.3	19.0	8.8	221	3.06	14.9	0.9	1.6	4.6	12	0.1	0.7	0.3	51	0.08	0.049
KYS 109936	Soil	1.9	35.4	20.0	93	0.1	39.7	18.6	785	3.27	14.7	1.6	2.4	9.1	24	0.4	1.1	0.2	20	0.31	0.061
KYS 109935	Soil	1.8	37.4	22.3	104	0.2	40.3	17.7	750	3.33	14.9	1.7	3.4	7.5	29	0.5	1.1	0.3	23	0.37	0.063
KYS 111553	Soil	2.0	111.6	43.2	522	0.4	170.4	45.8	1267	4.83	657.3	5.7	15.4	8.6	25	4.6	2.6	0.6	16	0.34	0.093
KYS 112140	Soil	1.9	68.8	22.7	103	0.4	45.6	16.7	613	3.71	25.1	2.0	17.2	10.9	27	0.2	2.6	0.4	18	0.29	0.070
KYS 112147	Soil	3.0	88.2	28.6	108	0.7	28.2	5.2	310	4.79	27.2	2.1	8.5	5.8	15	0.2	3.6	0.6	36	0.02	0.110
KYS 112142	Soil	18.3	75.0	29.3	109	0.9	29.7	6.6	396	3.82	23.6	2.9	4.4	6.7	28	0.4	4.6	0.5	56	0.03	0.112
KYS 112148	Soil	2.7	85.6	30.6	142	0.6	44.4	10.6	512	4.26	39.0	2.1	8.4	7.8	15	0.5	4.2	0.5	30	0.07	0.089
KYS 112143	Soil	2.6	85.5	28.3	91	0.6	28.3	5.9	439	4.84	10.8	1.2	11.9	7.0	17	0.1	2.8	0.7	40	0.02	0.109
KYS 112149	Soil	2.7	84.9	29.4	94	0.7	24.6	7.2	382	4.22	21.8	2.4	10.5	7.0	11	0.2	3.0	0.6	37	0.03	0.104
KYS 112151	Soil	2.7	48.6	21.6	98	0.4	26.6	10.2	338	3.48	21.1	1.9	4.9	7.6	13	0.2	2.4	0.3	29	0.07	0.070
KYS 112146	Soil	8.3	89.7	26.2	120	0.7	32.4	5.9	209	4.11	32.0	4.6	6.1	7.0	27	0.3	4.9	0.5	38	0.02	0.127
KYS 112087	Soil	1.2	15.9	15.6	50	0.2	15.8	7.2	326	3.24	13.3	0.7	<0.5	1.8	11	0.1	0.6	0.3	60	0.09	0.068
KYS 112144	Soil	5.1	107.9	14.5	195	1.1	35.9	5.8	132	5.32	44.9	6.5	1.2	10.2	29	0.3	7.8	0.3	27	<0.01	0.167
KYS 109880	Soil	0.8	40.1	34.1	84	0.1	35.2	14.4	424	5.37	26.2	0.8	1.1	12.4	6	0.1	1.9	0.5	27	0.05	0.064
KYS 109877	Soil	0.7	29.0	27.2	68	<0.1	28.9	18.9	802	3.13	17.8	1.1	1.7	7.2	10	0.1	0.6	0.2	24	0.08	0.065
KYS 109572	Soil	2.0	65.2	19.6	76	0.7	22.1	3.7	213	3.75	13.5	1.1	4.7	3.0	13	0.1	2.4	0.5	36	0.03	0.141
KYS 109573	Soil	2.8	79.0	26.4	87	0.7	25.0	4.7	186	3.58	14.2	1.3	9.5	3.3	13	0.2	2.4	0.5	40	0.02	0.101
KYS 109569	Soil	4.1	53.6	21.5	92	0.5	27.6	9.8	316	3.30	18.9	1.3	12.5	4.3	11	0.3	4.4	0.3	40	0.06	0.078
KYS 109581	Soil	0.6	48.9	32.9	151	0.3	67.7	23.8	853	3.87	60.2	1.5	2.5	13.6	26	0.9	5.2	0.2	13	0.47	0.060
KYS 109584	Soil	0.4	51.4	32.2	102	0.1	42.5	15.4	453	2.91	19.5	1.4	2.1	11.3	35	0.4	1.7	0.3	10	0.66	0.059
KYS 109891	Soil	1.2	62.6	59.7	153	<0.1	48.4	27.8	1478	4.17	14.5	1.3	1.4	16.0	14	0.3	2.3	0.5	17	0.15	0.066
KYS 109589	Soil	0.4	31.1	17.8	70	0.1	27.8	8.0	460	1.94	7.6	0.9	<0.5	5.3	55	0.8	1.1	0.2	10	1.19	0.053
KYS 109570	Soil	0.9	66.5	11.8	182	0.2	77.0	26.8	609	5.39	13.0	2.4	<0.5	8.7	10	1.3	0.7	0.1	21	0.04	0.047
KYS 109582	Soil	0.5	30.9	30.5	114	0.1	39.1	11.6	402	2.56	30.8	1.6	1.5	10.0	25	0.6	1.9	0.3	7	0.55	0.046
KYS 109585	Soil	0.3	38.9	24.9	85	0.1	36.0	11.2	304	2.65	11.5	1.5	1.0	8.5	38	0.4	1.5	0.3	9	0.81	0.042
KYS 109568	Soil	2.0	105.2	28.6	129	0.7	60.7	16.4	621	4.36	34.6	1.1	16.1	8.6	11	0.2	32.4	0.4	18	0.05	0.054
KYS 109590	Soil	0.7	34.6	21.3	76	0.2	33.4	10.5	338	2.68	10.1	1.1	2.8	9.8	12	0.3	1.1	0.2	16	0.17	0.043
KYS 112007	Soil	2.6	85.3	27.2	85	0.7	29.0	4.5	263	4.09	24.5	1.2	11.6	4.1	16	<0.1	3.2	0.6	26	0.02	0.071

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

CERTIFICATE OF ANALYSIS WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 112094	Soil	18	24	0.37	116	0.026	1	1.37	0.007	0.05	0.2	0.04	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 112090	Soil	18	29	0.41	127	0.029	1	1.75	0.006	0.05	0.2	0.05	1.9	<0.1	<0.05	5	<0.5	<0.2
KYS 109936	Soil	23	39	0.71	336	0.004	1	1.35	0.005	0.06	<0.1	0.04	1.7	<0.1	<0.05	4	0.5	<0.2
KYS 109935	Soil	16	38	0.68	358	0.003	<1	1.41	0.005	0.06	<0.1	0.04	1.7	<0.1	<0.05	4	0.5	<0.2
KYS 111553	Soil	18	22	0.44	62	0.006	<1	1.37	0.005	0.06	<0.1	0.05	2.3	<0.1	<0.05	3	1.2	<0.2
KYS 112140	Soil	21	20	0.52	85	0.002	<1	1.10	0.006	0.07	<0.1	0.07	1.9	<0.1	<0.05	3	1.0	<0.2
KYS 112147	Soil	14	27	0.29	160	0.001	<1	1.21	0.009	0.03	<0.1	0.12	2.1	<0.1	<0.05	4	3.6	0.2
KYS 112142	Soil	19	22	0.31	392	0.002	1	0.95	0.005	0.05	<0.1	0.37	1.3	<0.1	0.06	3	4.9	<0.2
KYS 112148	Soil	15	22	0.27	167	0.002	<1	1.14	0.008	0.04	<0.1	0.10	2.1	<0.1	<0.05	4	2.5	0.2
KYS 112143	Soil	18	30	0.37	117	0.002	<1	1.38	0.007	0.03	<0.1	0.13	1.6	<0.1	<0.05	5	3.3	<0.2
KYS 112149	Soil	19	27	0.31	171	0.002	<1	1.35	0.007	0.04	<0.1	0.13	1.9	<0.1	<0.05	4	2.7	<0.2
KYS 112151	Soil	25	21	0.35	208	0.002	<1	1.23	0.006	0.04	<0.1	0.08	1.6	<0.1	<0.05	4	1.7	<0.2
KYS 112146	Soil	15	19	0.21	337	0.002	<1	0.94	0.008	0.04	<0.1	0.15	1.8	<0.1	0.06	3	5.4	<0.2
KYS 112087	Soil	21	26	0.32	111	0.023	<1	1.34	0.006	0.06	0.1	0.02	1.2	<0.1	<0.05	7	<0.5	<0.2
KYS 112144	Soil	17	15	0.16	514	0.002	<1	0.57	0.007	0.06	<0.1	0.08	2.1	<0.1	0.15	2	8.4	<0.2
KYS 109880	Soil	29	29	0.53	48	0.008	<1	1.64	0.006	0.06	<0.1	0.03	1.5	<0.1	<0.05	6	<0.5	<0.2
KYS 109877	Soil	24	26	0.46	94	0.006	<1	1.40	0.007	0.09	<0.1	0.03	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109572	Soil	12	25	0.22	317	0.001	<1	1.09	0.011	0.05	<0.1	0.11	1.9	<0.1	0.10	5	2.6	0.4
KYS 109573	Soil	16	29	0.22	220	0.002	<1	1.39	0.009	0.05	<0.1	0.13	2.0	<0.1	<0.05	4	2.6	<0.2
KYS 109569	Soil	24	22	0.34	146	0.010	<1	1.29	0.006	0.05	<0.1	0.08	1.5	<0.1	<0.05	4	2.2	<0.2
KYS 109581	Soil	30	29	0.74	160	0.002	<1	1.58	0.005	0.09	<0.1	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109584	Soil	22	20	0.51	143	0.002	1	1.28	0.005	0.10	<0.1	0.03	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 109891	Soil	31	24	0.69	66	0.005	<1	1.59	0.004	0.06	<0.1	0.02	1.8	<0.1	<0.05	5	<0.5	<0.2
KYS 109589	Soil	8	14	0.34	155	0.004	1	0.90	0.007	0.07	<0.1	0.04	1.1	<0.1	<0.05	2	0.5	<0.2
KYS 109570	Soil	16	53	0.81	607	0.002	1	1.54	0.005	0.05	<0.1	0.03	3.7	<0.1	<0.05	4	0.6	<0.2
KYS 109582	Soil	14	16	0.44	156	0.002	<1	1.06	0.004	0.10	<0.1	0.03	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109585	Soil	13	17	0.46	117	0.002	2	1.10	0.004	0.09	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109568	Soil	24	14	0.23	146	0.001	<1	0.71	0.004	0.03	<0.1	0.07	1.9	<0.1	<0.05	2	2.3	0.4
KYS 109590	Soil	19	19	0.44	162	0.004	<1	1.22	0.004	0.07	<0.1	0.05	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 112007	Soil	5	23	0.34	106	0.002	<1	1.06	0.005	0.02	<0.1	0.09	1.6	<0.1	<0.05	3	1.8	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

QUALITY CONTROL REPORT WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
KYS 109957	Soil	1.1	41.2	21.1	81	<0.1	40.6	18.2	772	3.23	62.8	1.6	4.8	7.1	44	0.2	3.8	0.3	13	0.81	0.061
REP KYS 109957	QC	1.1	41.3	20.7	81	<0.1	40.2	18.2	828	3.42	62.8	1.6	4.9	7.0	44	0.3	3.8	0.3	13	0.80	0.063
KYS 112069	Soil	2.0	44.7	27.6	74	0.2	24.5	7.1	251	4.39	19.7	1.3	2.1	8.5	16	<0.1	2.4	0.5	27	0.07	0.058
REP KYS 112069	QC	2.0	44.1	29.0	72	0.2	24.5	7.2	253	4.31	19.4	1.2	1.6	8.7	16	<0.1	2.4	0.5	27	0.07	0.060
KYS 112170	Soil	0.7	35.0	39.6	97	0.9	26.6	12.9	567	3.05	647.6	1.7	78.3	4.9	44	0.2	769.4	0.3	7	0.56	0.048
REP KYS 112170	QC	0.7	35.0	40.0	98	0.8	26.1	13.6	567	3.14	648.8	1.7	83.4	4.9	44	0.2	751.4	0.3	7	0.57	0.046
KYS 109650	Soil	0.9	37.6	20.2	82	<0.1	33.8	20.1	855	4.57	29.8	0.8	1.6	4.3	6	<0.1	3.2	0.4	27	0.04	0.045
REP KYS 109650	QC	0.9	35.4	20.0	80	<0.1	33.9	19.5	848	4.42	28.3	0.9	2.3	4.2	6	<0.1	3.2	0.4	25	0.04	0.043
KYS 111728	Soil	0.9	20.6	25.3	63	<0.1	18.5	9.1	464	2.58	55.0	1.0	4.5	2.3	25	0.2	1.8	0.3	27	0.61	0.046
REP KYS 111728	QC	0.9	21.6	24.4	60	<0.1	19.5	8.9	466	2.64	55.7	1.0	4.2	2.4	27	0.2	1.7	0.3	28	0.63	0.046
KYS 111562	Soil	1.6	33.4	26.7	95	<0.1	34.6	15.4	574	3.32	14.4	1.0	2.1	3.4	11	0.3	0.8	0.3	39	0.12	0.063
REP KYS 111562	QC	1.4	32.5	25.9	92	<0.1	34.4	15.8	574	3.26	14.4	1.0	3.2	3.2	11	0.3	0.8	0.3	38	0.11	0.066
KYS 111701	Soil	0.9	23.6	18.9	64	0.1	23.5	11.9	532	2.95	32.5	1.0	3.9	1.3	6	<0.1	1.0	0.3	26	0.09	0.057
REP KYS 111701	QC	0.9	22.1	18.1	61	0.1	23.4	11.0	549	2.77	31.9	0.9	3.6	1.4	7	<0.1	1.0	0.2	24	0.10	0.066
KYS 109679	Soil	0.8	38.9	39.1	115	0.9	35.1	14.7	406	3.71	793.8	1.6	97.9	8.0	23	0.2	734.4	0.3	10	0.20	0.042
REP KYS 109679	QC	0.7	43.5	40.3	119	0.9	37.7	15.1	433	3.91	788.8	1.7	128.2	8.7	24	0.2	752.3	0.3	9	0.19	0.043
KYS 111676	Soil	1.2	27.8	22.6	76	0.1	28.6	12.9	592	3.29	53.0	1.3	3.8	2.0	10	<0.1	1.0	0.3	29	0.09	0.062
REP KYS 111676	QC	1.2	29.0	22.2	77	0.1	28.7	13.3	594	3.35	54.3	1.2	1.6	1.8	9	0.2	0.9	0.3	29	0.10	0.063
KYS 110991	Soil	1.3	44.3	25.9	103	0.1	46.4	17.7	401	3.42	34.6	1.6	2.8	10.4	30	0.4	1.3	0.3	17	0.34	0.045
REP KYS 110991	QC	1.2	44.8	24.8	103	0.1	49.0	18.0	401	3.52	35.8	1.6	3.2	10.1	29	0.5	1.3	0.3	18	0.33	0.049
KYS 112319	Soil	0.4	91.8	2.6	71	<0.1	80.6	26.1	624	3.80	7.3	0.3	6.2	1.8	25	<0.1	0.3	<0.1	53	0.75	0.270
REP KYS 112319	QC	0.4	89.0	2.8	73	<0.1	80.9	26.8	605	3.84	6.9	0.3	2.4	1.9	24	<0.1	0.3	<0.1	53	0.75	0.260
KYS 110037	Soil	1.6	22.8	29.4	45	<0.1	9.4	3.8	158	2.28	22.3	1.1	1.5	3.1	9	<0.1	5.6	0.4	23	0.02	0.077
REP KYS 110037	QC	1.7	23.5	28.7	45	<0.1	9.7	4.0	156	2.25	22.4	1.0	1.2	3.5	9	<0.1	5.5	0.4	21	0.02	0.075
KYS 109702	Soil	1.7	61.6	34.8	104	0.2	30.4	13.7	359	4.22	134.8	1.7	13.4	11.1	11	<0.1	200.2	0.5	9	0.09	0.052
REP KYS 109702	QC	1.5	62.4	35.9	101	0.2	31.0	12.9	335	4.36	135.7	1.7	15.9	11.1	10	0.1	200.6	0.6	11	0.08	0.051
KYS 110957	Soil	1.3	16.1	17.6	54	<0.1	18.2	10.1	545	3.24	12.7	0.8	4.0	1.5	8	0.2	0.6	0.2	42	0.07	0.053
REP KYS 110957	QC	1.4	16.8	17.4	59	<0.1	19.5	10.5	538	3.32	13.0	0.8	2.0	1.4	8	0.2	0.6	0.2	44	0.07	0.059

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

QUALITY CONTROL REPORT WHI10000186.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
KYS 109957	Soil	13	25	0.63	385	0.002	1	1.22	0.004	0.07	<0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
REP KYS 109957	QC	13	27	0.63	391	0.002	2	1.21	0.004	0.08	<0.1	0.03	1.2	<0.1	0.07	3	<0.5	<0.2
KYS 112069	Soil	30	22	0.58	61	0.008	<1	1.42	0.004	0.05	<0.1	0.03	0.8	<0.1	<0.05	5	1.0	<0.2
REP KYS 112069	QC	29	23	0.59	62	0.008	<1	1.39	0.004	0.05	<0.1	0.03	0.8	<0.1	<0.05	6	0.8	0.2
KYS 112170	Soil	11	12	0.36	83	0.002	1	0.93	0.006	0.08	<0.1	0.04	0.9	<0.1	0.05	2	<0.5	<0.2
REP KYS 112170	QC	11	12	0.37	83	0.001	2	0.94	0.006	0.08	<0.1	0.04	0.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109650	Soil	15	35	0.60	71	0.007	<1	1.69	0.005	0.04	<0.1	0.02	2.0	<0.1	<0.05	5	<0.5	<0.2
REP KYS 109650	QC	15	34	0.60	68	0.007	<1	1.64	0.004	0.04	<0.1	0.01	2.0	<0.1	<0.05	5	<0.5	<0.2
KYS 111728	Soil	14	14	0.19	92	0.017	1	0.80	0.007	0.04	0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
REP KYS 111728	QC	13	15	0.19	92	0.017	<1	0.80	0.006	0.04	0.2	0.05	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 111562	Soil	17	25	0.45	97	0.031	<1	1.52	0.006	0.04	0.2	0.03	2.1	<0.1	<0.05	4	0.7	<0.2
REP KYS 111562	QC	17	24	0.44	98	0.031	1	1.52	0.006	0.04	0.2	0.03	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 111701	Soil	10	16	0.23	66	0.011	2	0.79	0.004	0.04	0.2	0.04	1.0	<0.1	<0.05	3	0.5	<0.2
REP KYS 111701	QC	10	15	0.23	64	0.011	2	0.82	0.006	0.04	0.1	0.04	0.9	<0.1	<0.05	2	<0.5	<0.2
KYS 109679	Soil	16	13	0.46	55	0.002	2	1.10	0.005	0.09	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
REP KYS 109679	QC	18	13	0.41	58	0.002	1	1.12	0.005	0.08	<0.1	0.03	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 111676	Soil	19	22	0.40	80	0.015	<1	1.31	0.004	0.05	0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
REP KYS 111676	QC	19	22	0.40	83	0.014	<1	1.29	0.004	0.06	0.2	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110991	Soil	20	30	0.70	1980	0.002	<1	1.48	0.003	0.08	<0.1	0.04	1.3	<0.1	<0.05	4	<0.5	<0.2
REP KYS 110991	QC	20	31	0.69	2140	0.002	<1	1.46	0.004	0.08	<0.1	0.03	1.3	<0.1	<0.05	4	0.6	0.4
KYS 112319	Soil	7	96	1.95	119	0.108	<1	2.20	0.004	0.08	<0.1	0.01	3.4	<0.1	<0.05	5	<0.5	<0.2
REP KYS 112319	QC	7	95	1.97	123	0.105	<1	2.22	0.004	0.08	0.1	0.02	3.5	<0.1	<0.05	5	<0.5	<0.2
KYS 110037	Soil	43	14	0.50	52	0.003	<1	1.37	0.004	0.04	<0.1	0.02	0.5	<0.1	<0.05	6	<0.5	<0.2
REP KYS 110037	QC	44	14	0.49	52	0.003	<1	1.43	0.005	0.04	<0.1	0.02	0.6	<0.1	<0.05	6	<0.5	<0.2
KYS 109702	Soil	25	17	0.47	51	0.002	<1	1.12	0.005	0.05	<0.1	0.02	1.3	<0.1	<0.05	3	0.9	<0.2
REP KYS 109702	QC	27	17	0.48	49	0.003	<1	1.13	0.007	0.05	<0.1	0.03	1.3	<0.1	<0.05	3	0.8	<0.2
KYS 110957	Soil	16	23	0.34	65	0.024	<1	1.29	0.005	0.05	0.1	0.03	1.1	<0.1	<0.05	5	0.7	<0.2
REP KYS 110957	QC	16	22	0.34	67	0.024	<1	1.36	0.004	0.05	0.2	0.03	0.9	<0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

QUALITY CONTROL REPORT WHI10000186.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
KYS 112061	Soil	1.6	50.2	14.6	69	0.3	28.3	9.3	383	2.59	20.5	1.5	12.5	1.6	13	0.2	4.4	0.2	33	0.12	0.056
REP KYS 112061	QC	1.5	51.0	15.0	69	0.3	28.5	9.3	382	2.63	21.2	1.6	10.7	1.6	13	0.2	4.4	0.2	34	0.12	0.056
KYS 109899	Soil	3.3	28.4	30.7	74	0.8	20.7	4.9	276	3.80	16.0	0.8	5.3	2.2	14	0.2	2.6	0.7	40	0.04	0.119
REP KYS 109899	QC	3.4	28.4	30.9	75	0.8	21.0	4.8	285	3.85	16.5	0.8	5.0	2.1	15	0.2	2.5	0.7	42	0.04	0.124
KYS 109913	Soil	7.8	30.6	22.0	52	0.5	16.6	7.3	396	2.46	28.9	1.2	11.6	2.8	21	0.1	6.8	0.3	41	0.10	0.080
REP KYS 109913	QC	8.0	29.5	22.2	56	0.5	18.7	7.8	408	2.52	28.9	1.3	11.1	2.8	21	<0.1	7.0	0.3	40	0.10	0.079
KYS 109683	Soil	0.3	30.6	24.1	51	<0.1	26.6	13.7	681	2.27	16.3	1.5	2.0	11.2	51	<0.1	1.3	0.2	10	0.74	0.045
REP KYS 109683	QC	0.4	29.0	23.7	49	<0.1	26.7	13.2	674	2.22	15.6	1.4	3.2	10.5	51	<0.1	1.2	0.2	12	0.75	0.044
KYS 112086	Soil	1.1	18.8	15.1	45	0.2	18.0	7.3	206	2.93	18.1	0.8	4.9	3.0	10	<0.1	1.0	0.2	51	0.09	0.046
REP KYS 112086	QC	1.2	18.6	15.2	45	0.2	17.3	7.2	199	2.83	17.9	0.8	1.7	3.2	9	<0.1	1.0	0.2	48	0.09	0.046
KYS 109581	Soil	0.6	48.9	32.9	151	0.3	67.7	23.8	853	3.87	60.2	1.5	2.5	13.6	26	0.9	5.2	0.2	13	0.47	0.060
REP KYS 109581	QC	0.5	48.3	33.2	154	0.3	67.5	23.5	865	3.97	62.1	1.5	3.4	14.0	26	0.9	5.3	0.3	13	0.48	0.061
KYS 109570	Soil	0.9	66.5	11.8	182	0.2	77.0	26.8	609	5.39	13.0	2.4	<0.5	8.7	10	1.3	0.7	0.1	21	0.04	0.047
REP KYS 109570	QC	0.8	69.6	11.8	182	0.2	79.8	27.0	608	5.51	13.1	2.5	<0.5	8.7	10	1.6	0.7	0.1	20	0.04	0.046
Reference Materials																					
STD DS7	Standard	21.5	118.4	66.8	407	0.9	56.2	10.1	635	2.49	55.3	4.8	87.5	4.8	76	6.4	6.0	4.8	87	1.01	0.088
STD DS7	Standard	22.7	99.2	59.9	436	1.0	58.9	9.6	703	2.56	50.8	4.3	75.3	4.0	71	5.7	5.3	4.2	87	0.92	0.075
STD DS7	Standard	20.3	113.4	66.5	404	0.9	56.9	9.6	647	2.44	56.0	4.9	88.8	4.7	74	6.8	6.2	4.9	90	0.97	0.087
STD DS7	Standard	21.6	112.7	65.5	398	1.0	62.4	10.6	666	2.53	54.0	4.4	67.0	4.3	69	6.1	5.7	4.7	87	0.95	0.078
STD DS7	Standard	22.2	102.3	62.0	394	1.0	55.3	8.7	625	2.48	47.7	4.2	74.3	4.3	86	6.0	5.4	4.2	87	1.08	0.079
STD DS7	Standard	21.0	117.8	69.7	420	1.0	58.4	10.0	666	2.57	58.8	5.1	75.9	4.9	81	6.9	6.3	5.0	90	1.03	0.087
STD DS7	Standard	23.3	114.5	63.5	416	1.0	62.0	10.4	652	2.56	59.6	4.3	66.3	4.2	75	6.3	5.8	4.6	94	1.01	0.084
STD DS7	Standard	22.3	106.7	63.5	396	1.0	61.3	10.5	676	2.56	54.6	4.5	81.6	4.4	86	5.9	5.6	4.5	96	1.05	0.075
STD DS7	Standard	22.9	121.7	77.3	426	1.0	62.1	10.5	692	2.61	56.3	5.3	72.7	5.5	82	6.6	6.7	5.1	93	1.04	0.081
STD DS7	Standard	21.8	121.7	64.6	408	1.0	57.7	11.0	643	2.45	55.6	5.0	68.5	5.0	80	7.0	6.1	5.0	89	1.00	0.088
STD DS7	Standard	20.8	106.5	69.6	382	1.1	51.0	9.3	609	2.37	48.4	5.0	73.7	4.6	74	6.0	5.6	4.7	80	0.94	0.075
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

QUALITY CONTROL REPORT WHI10000186.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
KYS 112061	Soil	17	21	0.28	191	0.013	<1	1.10	0.006	0.05	0.1	0.08	1.7	<0.1	<0.05	3	<0.5	<0.2
REP KYS 112061	QC	17	21	0.27	191	0.015	<1	1.09	0.006	0.05	0.1	0.09	1.7	<0.1	<0.05	3	0.5	<0.2
KYS 109899	Soil	13	32	0.24	161	0.006	<1	1.36	0.008	0.05	<0.1	0.07	0.9	<0.1	0.05	5	1.5	<0.2
REP KYS 109899	QC	13	33	0.25	164	0.007	1	1.39	0.009	0.05	<0.1	0.08	0.9	<0.1	0.06	5	1.4	<0.2
KYS 109913	Soil	13	17	0.16	245	0.010	<1	0.80	0.004	0.05	0.2	0.12	1.2	<0.1	<0.05	2	2.1	0.2
REP KYS 109913	QC	13	17	0.17	257	0.011	<1	0.83	0.004	0.05	0.2	0.12	1.2	<0.1	<0.05	3	1.8	<0.2
KYS 109683	Soil	17	13	0.35	92	0.003	<1	0.85	0.006	0.19	<0.1	0.04	1.2	<0.1	0.13	2	<0.5	<0.2
REP KYS 109683	QC	16	12	0.34	96	0.002	<1	0.83	0.005	0.19	<0.1	0.03	1.1	<0.1	0.12	2	<0.5	<0.2
KYS 112086	Soil	22	24	0.37	66	0.021	<1	1.26	0.005	0.05	0.2	0.02	1.3	<0.1	<0.05	6	<0.5	<0.2
REP KYS 112086	QC	21	23	0.37	65	0.017	<1	1.26	0.003	0.04	0.1	0.03	1.3	<0.1	<0.05	6	<0.5	<0.2
KYS 109581	Soil	30	29	0.74	160	0.002	<1	1.58	0.005	0.09	<0.1	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
REP KYS 109581	QC	30	30	0.75	165	0.002	<1	1.59	0.006	0.10	<0.1	0.03	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109570	Soil	16	53	0.81	607	0.002	1	1.54	0.005	0.05	<0.1	0.03	3.7	<0.1	<0.05	4	0.6	<0.2
REP KYS 109570	QC	15	52	0.80	603	0.002	<1	1.44	0.005	0.06	<0.1	0.02	3.7	<0.1	<0.05	4	1.1	<0.2
Reference Materials																		
STD DS7	Standard	13	210	1.04	402	0.138	41	1.07	0.103	0.47	3.4	0.22	2.8	4.0	0.20	5	3.4	1.1
STD DS7	Standard	12	252	1.01	447	0.105	39	0.99	0.099	0.49	3.7	0.23	2.2	4.3	0.14	5	3.2	1.7
STD DS7	Standard	13	211	1.07	408	0.134	42	1.04	0.107	0.47	3.5	0.22	2.7	3.8	0.16	5	3.2	1.8
STD DS7	Standard	13	229	1.06	405	0.127	40	1.05	0.111	0.47	3.7	0.21	2.3	4.2	0.24	5	4.0	1.6
STD DS7	Standard	14	241	1.07	439	0.118	40	1.09	0.108	0.54	3.6	0.23	2.3	4.3	0.16	5	3.7	0.9
STD DS7	Standard	14	207	1.11	409	0.138	42	1.11	0.110	0.51	3.8	0.23	2.8	4.3	0.15	5	3.1	1.3
STD DS7	Standard	13	243	1.07	421	0.128	45	1.08	0.109	0.49	3.9	0.21	2.1	4.1	0.21	5	3.4	1.9
STD DS7	Standard	15	279	1.10	455	0.131	40	1.14	0.112	0.51	3.7	0.22	2.7	4.3	0.20	5	3.1	1.3
STD DS7	Standard	15	228	1.14	442	0.131	38	1.11	0.108	0.50	3.7	0.22	2.7	4.2	0.26	5	3.2	1.6
STD DS7	Standard	15	222	1.08	410	0.140	39	1.12	0.114	0.47	3.7	0.22	3.0	4.0	0.16	5	2.9	1.2
STD DS7	Standard	13	225	1.03	426	0.128	36	1.03	0.094	0.45	3.8	0.21	2.4	4.2	0.18	5	2.9	0.5
STD DS7 Expected		12	179	1.05	410	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5	1.08
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

QUALITY CONTROL REPORT WHI10000186.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 18, 2010

QUALITY CONTROL REPORT WHI10000186.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Submitted By: Johnathan More
Receiving Lab: Canada-Whitehorse
Received: July 14, 2010
Report Date: August 24, 2010
Page: 1 of 6

CERTIFICATE OF ANALYSIS WHI10000181.1

CLIENT JOB INFORMATION

Project: KYS
Shipment ID: KYS1
P.O. Number
Number of Samples: 123

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	123	Dry at 60C sieve 100g to -80 mesh			VAN
Dry at 60C	123	Dry at 60C			VAN
1DX2	122	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Aldrin Resources
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5
Canada

CC: Isaac Fage
Bert Jeffries
Shawn Ryan

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110772	Soil	0.8	27.2	23.0	75	<0.1	33.3	13.0	490	3.17	85.0	0.9	5.3	6.3	9	0.1	1.9	0.4	25	0.11	0.058
KYS 110773	Soil	1.3	36.4	20.6	84	0.4	34.8	10.2	427	3.19	294.5	1.7	17.7	3.5	26	0.2	3.9	0.3	30	0.33	0.081
KYS 110774	Soil	1.4	46.6	22.1	87	0.4	33.1	10.4	429	3.34	240.8	1.2	29.4	4.1	11	0.2	4.0	0.4	32	0.09	0.074
KYS 110775	Soil	1.2	44.6	23.0	78	0.3	31.0	11.1	487	3.20	144.0	1.4	16.7	5.6	13	0.1	3.1	0.4	27	0.12	0.063
KYS 110777	Soil	1.4	52.3	18.0	87	0.3	34.4	8.8	324	3.15	61.7	1.5	14.9	5.8	14	0.2	2.3	0.3	32	0.12	0.063
KYS 110778	Soil	0.8	45.7	26.2	72	0.3	29.6	11.9	763	2.83	11.0	1.5	9.5	8.6	24	0.2	0.6	0.4	18	0.37	0.074
KYS 110779	Soil	1.4	23.9	12.9	63	0.4	21.3	5.6	181	2.42	23.7	1.0	6.4	0.9	11	0.2	1.7	0.2	32	0.09	0.081
KYS 110780	Soil	1.6	32.6	13.6	71	0.3	23.6	7.1	239	2.45	35.1	1.2	9.8	5.5	13	0.3	2.8	0.2	33	0.12	0.072
KYS 110781	Soil	2.2	42.7	22.9	50	0.7	19.7	4.7	250	3.04	31.8	1.5	13.4	2.5	7	0.3	3.7	0.4	30	0.03	0.081
KYS 110782	Soil	0.9	21.9	15.9	56	0.1	32.6	11.0	614	2.88	17.9	0.8	1.2	4.3	9	0.1	1.0	0.2	36	0.11	0.043
KYS 110783	Soil	1.5	54.4	24.0	95	0.3	38.2	10.5	427	3.10	17.1	1.3	7.4	4.9	20	0.2	1.2	0.3	24	0.13	0.070
KYS 110784	Soil	0.8	19.8	20.3	57	<0.1	33.5	14.1	506	3.07	15.5	0.9	1.2	4.6	9	0.1	0.5	0.2	37	0.07	0.042
KYS 110785	Soil	0.8	38.2	30.9	85	0.2	46.0	16.6	934	3.46	26.2	1.5	3.3	9.7	12	0.1	1.5	0.4	19	0.13	0.063
KYS 110786	Soil	0.8	19.2	16.7	60	<0.1	24.0	10.8	526	2.30	15.0	0.8	2.7	3.8	10	0.3	0.9	0.2	30	0.10	0.054
KYS 110787	Soil	2.3	57.6	49.2	97	0.2	24.2	13.0	541	3.56	50.5	1.2	5.8	5.8	5	0.1	2.9	0.5	20	0.04	0.050
KYS 110788	Soil	0.9	19.5	30.2	55	<0.1	23.7	12.2	350	3.03	12.9	0.9	1.0	6.7	9	0.2	0.7	0.3	32	0.09	0.042
KYS 110789	Soil	0.9	51.2	48.3	101	0.1	36.1	17.1	500	4.37	45.0	1.6	3.3	8.2	7	0.2	2.0	0.4	15	0.03	0.068
KYS 110790	Soil	2.0	27.1	24.6	60	0.7	19.4	3.8	178	2.70	64.3	0.9	8.9	0.6	12	<0.1	4.9	0.4	39	0.07	0.099
KYS 110791	Soil	2.5	58.9	28.1	77	0.5	17.9	3.2	191	3.53	43.5	1.3	4.7	5.2	12	<0.1	10.6	0.5	31	0.02	0.096
KYS 110792	Soil	2.2	52.7	27.9	91	0.6	20.4	4.1	229	3.83	61.2	1.6	2.6	6.6	17	<0.1	11.1	0.5	34	0.02	0.085
KYS 110793	Soil	2.4	80.6	28.9	105	0.6	20.8	3.6	235	4.47	44.5	0.9	7.1	6.0	13	<0.1	6.9	0.6	31	0.02	0.093
KYS 110794	Soil	1.8	54.3	23.1	59	0.8	16.3	2.7	375	4.40	30.5	0.6	65.6	3.3	10	<0.1	3.0	0.4	31	0.02	0.086
KYS 110795	Soil	3.2	40.2	31.4	74	0.6	17.7	3.0	194	4.60	32.4	0.7	8.6	1.9	11	<0.1	3.7	0.6	50	0.01	0.094
KYS 110796	Soil	2.0	28.3	32.5	67	0.6	14.5	2.4	152	3.84	21.3	1.0	1.1	4.3	31	<0.1	4.1	0.5	39	<0.01	0.096
KYS 110797	Soil	1.2	68.4	18.5	168	0.2	74.0	30.5	891	5.95	11.2	1.0	5.0	7.8	7	0.3	1.4	0.4	29	0.08	0.109
KYS 110798	Soil	0.7	24.7	27.2	75	0.1	38.2	14.9	681	3.65	41.1	1.0	3.0	8.9	17	<0.1	1.7	0.4	19	0.23	0.037
KYS 110799	Soil	0.5	28.7	29.8	83	<0.1	35.4	15.9	546	4.22	34.1	1.1	<0.5	16.0	8	0.2	1.4	0.6	14	0.11	0.047
KYS 110800	Soil	0.9	25.0	23.9	75	<0.1	24.4	11.5	378	3.05	65.5	1.1	3.8	4.0	11	<0.1	1.0	0.3	34	0.11	0.053
KYS 110801	Soil	0.5	22.2	26.5	65	<0.1	26.0	12.9	616	3.06	24.7	1.1	1.1	7.8	15	<0.1	0.6	0.4	18	0.21	0.045
KYS 110802	Soil	0.5	19.5	24.3	66	<0.1	23.8	13.1	406	3.15	43.8	0.8	2.4	8.6	5	0.1	0.6	0.3	18	0.05	0.038

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110772	Soil		19	24	0.43	92	0.008	2	1.23	0.005	0.06	0.1	0.02	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 110773	Soil		14	21	0.29	138	0.007	<1	1.14	0.006	0.05	0.1	0.05	1.8	<0.1	<0.05	3	0.6	<0.2
KYS 110774	Soil		14	22	0.32	137	0.007	1	1.32	0.006	0.05	0.1	0.07	1.7	<0.1	<0.05	4	0.5	0.2
KYS 110775	Soil		17	19	0.32	129	0.009	<1	1.15	0.005	0.05	<0.1	0.05	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 110777	Soil		15	22	0.38	150	0.009	<1	1.35	0.006	0.05	<0.1	0.06	2.1	<0.1	<0.05	4	<0.5	<0.2
KYS 110778	Soil		20	19	0.44	136	0.006	<1	1.32	0.004	0.07	<0.1	0.06	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 110779	Soil		11	19	0.20	80	0.017	<1	1.10	0.007	0.04	0.1	0.06	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110780	Soil		13	20	0.20	120	0.021	<1	1.07	0.005	0.04	0.2	0.05	2.3	<0.1	<0.05	3	0.5	<0.2
KYS 110781	Soil		8	22	0.13	51	0.007	<1	1.08	0.004	0.03	<0.1	0.09	1.3	<0.1	<0.05	3	1.4	0.2
KYS 110782	Soil		20	47	0.70	112	0.009	<1	1.42	0.004	0.08	<0.1	0.04	1.5	<0.1	<0.05	5	<0.5	0.3
KYS 110783	Soil		12	27	0.53	131	0.003	<1	1.34	0.006	0.09	<0.1	0.06	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 110784	Soil		19	54	0.84	87	0.012	<1	1.46	0.004	0.11	<0.1	0.02	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 110785	Soil		22	25	0.40	113	0.006	<1	1.10	0.005	0.07	<0.1	0.04	2.1	<0.1	<0.05	3	<0.5	<0.2
KYS 110786	Soil		16	19	0.32	106	0.018	1	1.18	0.004	0.11	0.1	0.06	1.2	0.1	<0.05	3	<0.5	<0.2
KYS 110787	Soil		18	17	0.24	73	0.009	<1	1.04	0.004	0.06	<0.1	0.04	1.2	<0.1	0.06	3	0.7	0.4
KYS 110788	Soil		20	19	0.34	88	0.013	<1	1.33	0.004	0.07	0.1	0.04	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110789	Soil		18	16	0.40	93	0.004	<1	1.41	0.006	0.07	<0.1	0.04	1.3	<0.1	0.08	4	<0.5	0.3
KYS 110790	Soil		10	23	0.21	161	0.006	<1	1.25	0.007	0.05	0.1	0.06	0.8	<0.1	0.07	4	1.4	<0.2
KYS 110791	Soil		12	19	0.12	124	0.001	<1	1.12	0.006	0.04	<0.1	0.06	2.1	<0.1	0.08	3	2.4	0.3
KYS 110792	Soil		11	20	0.10	207	0.002	<1	1.12	0.016	0.06	0.1	0.07	2.7	<0.1	0.18	3	1.9	0.4
KYS 110793	Soil		9	22	0.18	106	<0.001	<1	1.24	0.010	0.04	<0.1	0.07	1.9	<0.1	0.07	3	3.0	0.4
KYS 110794	Soil		8	19	0.17	124	0.004	<1	1.01	0.008	0.04	0.1	0.07	1.4	<0.1	0.09	4	2.2	0.3
KYS 110795	Soil		9	25	0.15	69	0.008	<1	1.19	0.007	0.03	<0.1	0.07	1.2	<0.1	0.06	5	2.0	0.3
KYS 110796	Soil		8	25	0.17	255	0.004	<1	1.51	0.022	0.07	<0.1	0.10	2.3	<0.1	0.14	5	2.2	0.5
KYS 110797	Soil		16	24	0.88	62	0.004	<1	2.40	0.005	0.05	<0.1	0.06	2.7	<0.1	<0.05	8	0.7	<0.2
KYS 110798	Soil		28	19	0.37	126	0.004	<1	1.36	0.004	0.06	<0.1	0.03	1.9	0.1	<0.05	4	<0.5	<0.2
KYS 110799	Soil		36	19	0.48	78	0.002	<1	1.39	0.004	0.06	<0.1	0.02	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 110800	Soil		18	24	0.48	114	0.011	<1	1.50	0.005	0.06	0.2	0.03	1.8	0.1	<0.05	5	<0.5	<0.2
KYS 110801	Soil		27	18	0.47	119	0.009	<1	1.29	0.005	0.12	<0.1	0.02	1.3	0.1	<0.05	4	<0.5	<0.2
KYS 110802	Soil		28	19	0.52	58	0.006	<1	1.41	0.003	0.06	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110803	Soil		1.0	23.8	41.3	76	0.1	29.1	11.9	422	3.62	24.1	1.2	2.1	6.2	9	<0.1	0.7	0.4	27	0.08	0.057
KYS 110804	Soil		0.6	59.1	30.9	81	<0.1	36.9	17.4	1153	3.19	3.2	2.0	1.3	13.6	15	0.1	0.2	0.4	18	0.15	0.047
KYS 110805	Soil		0.7	33.5	32.3	89	0.1	38.2	16.9	796	2.96	51.3	1.4	3.7	10.5	17	0.5	0.8	0.3	17	0.35	0.049
KYS 110806	Soil		0.6	45.0	38.0	114	0.2	50.1	20.5	646	3.53	37.3	1.2	1.9	14.6	32	0.3	1.0	0.5	10	0.79	0.058
KYS 110808	Soil		0.7	40.0	31.1	94	0.3	39.0	17.5	647	3.90	404.5	1.5	18.7	17.6	17	0.2	4.0	0.4	11	0.27	0.061
KYS 110809	Soil		1.7	21.2	13.4	55	0.4	18.0	5.0	154	2.61	24.0	0.9	3.5	0.6	9	0.1	2.1	0.3	39	0.05	0.070
KYS 110810	Soil		1.3	17.9	11.0	46	0.3	13.8	3.8	135	1.94	17.4	0.7	2.3	0.3	9	0.3	1.5	0.2	34	0.04	0.061
KYS 110811	Soil		1.3	25.5	12.0	63	0.2	17.8	8.1	385	2.35	16.4	0.9	3.1	0.6	10	0.3	1.4	0.3	33	0.06	0.067
KYS 110812	Soil		2.1	16.9	14.8	34	0.3	8.4	2.0	71	1.87	17.0	0.5	3.0	0.1	7	<0.1	1.3	0.3	32	0.02	0.054
KYS 110813	Soil		1.5	43.2	21.2	100	0.3	45.5	15.1	420	3.25	117.0	1.6	35.0	5.0	10	0.4	5.3	0.3	28	0.05	0.068
KYS 110814	Soil		1.5	51.2	21.3	119	0.4	53.2	17.7	484	3.14	123.9	2.0	41.1	5.6	11	0.5	5.7	0.3	23	0.05	0.075
KYS 110815	Soil		1.5	22.0	11.9	64	<0.1	18.0	7.3	293	2.68	17.0	1.1	<0.5	1.5	9	0.2	1.1	0.3	45	0.06	0.072
KYS 110816	Soil		1.7	30.1	12.9	52	0.3	16.8	6.0	283	2.83	19.6	1.0	9.5	0.7	12	0.3	2.1	0.3	41	0.05	0.082
KYS 110817	Soil		1.8	18.5	13.1	41	0.2	11.5	4.0	175	2.60	19.7	0.6	2.2	1.6	10	0.2	1.5	0.3	48	0.05	0.054
KYS 110818	Soil		2.2	22.0	13.3	52	0.4	15.8	5.6	261	2.35	27.9	0.9	8.2	1.3	16	0.2	2.4	0.3	35	0.07	0.086
KYS 110819	Soil		1.5	15.6	12.8	48	0.5	13.6	5.0	214	2.52	26.3	0.7	3.7	1.0	11	0.2	1.4	0.2	39	0.06	0.065
KYS 110820	Soil		1.7	17.2	12.0	59	0.2	15.6	6.3	271	2.58	19.8	0.8	3.4	0.6	12	0.2	1.5	0.3	42	0.07	0.068
KYS 110821	Soil		1.5	16.0	14.8	54	0.3	13.8	5.7	282	2.54	19.7	0.7	5.4	1.7	12	0.2	1.2	0.3	45	0.06	0.087
KYS 110822	Soil		1.6	20.1	12.0	69	0.2	18.6	6.2	304	2.64	23.5	0.9	4.8	2.2	14	0.3	1.5	0.3	47	0.06	0.072
KYS 110823	Soil		1.6	16.5	12.3	57	0.2	14.3	4.8	285	2.89	26.4	0.5	<0.5	1.2	11	0.2	1.4	0.3	53	0.09	0.076
KYS 110824	Soil		1.4	21.1	11.0	66	0.2	19.1	6.0	251	2.65	24.1	0.8	2.5	1.6	9	0.2	1.3	0.2	48	0.07	0.057
KYS 110825	Soil		1.4	25.0	12.6	60	0.2	19.8	6.9	296	2.58	17.9	0.9	6.6	3.6	11	0.3	1.5	0.2	35	0.08	0.076
KYS 110826	Soil		1.2	31.8	10.0	64	0.1	25.9	7.8	298	2.65	20.7	1.0	4.5	4.4	14	0.2	1.4	0.2	39	0.15	0.096
KYS 110827	Soil		1.9	18.5	16.4	62	0.2	16.2	5.2	184	3.02	22.4	0.7	1.2	1.6	10	0.3	1.1	0.4	56	0.06	0.073
KYS 110828	Soil		1.6	19.1	15.1	56	0.3	16.0	6.1	302	2.59	23.8	0.7	2.8	2.0	10	0.3	1.4	0.3	44	0.05	0.075
KYS 110829	Soil		1.4	19.4	10.9	65	0.3	15.1	6.2	682	2.14	94.8	0.5	16.5	0.7	12	0.6	1.6	0.3	50	0.08	0.054
KYS 110830	Soil		1.3	12.7	11.1	51	0.3	10.6	3.4	171	2.40	14.5	0.5	0.5	0.7	8	0.3	0.9	0.3	54	0.04	0.049
KYS 110831	Soil		1.4	19.4	11.9	69	0.2	20.7	5.9	218	2.66	19.7	0.6	3.7	2.3	9	0.4	1.1	0.2	44	0.07	0.053
KYS 110832	Soil		1.2	22.8	9.5	62	0.2	21.8	5.7	227	2.14	24.3	0.7	12.2	1.9	7	0.2	1.2	0.2	34	0.06	0.046
KYS 110833	Soil		0.9	19.8	8.4	47	0.1	17.0	3.4	104	1.75	19.6	0.6	11.3	0.7	6	0.2	1.1	0.2	25	0.04	0.033

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110803	Soil	25	23	0.47	111	0.007	<1	1.49	0.004	0.07	<0.1	0.03	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 110804	Soil	31	19	0.60	73	0.025	<1	1.17	0.004	0.06	<0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 110805	Soil	23	19	0.47	97	0.005	<1	1.18	0.003	0.07	<0.1	0.02	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 110806	Soil	26	15	0.49	94	0.003	<1	1.09	0.003	0.08	<0.1	0.04	2.0	<0.1	0.07	3	<0.5	0.2
KYS 110808	Soil	29	15	0.39	106	0.003	<1	1.05	0.005	0.08	<0.1	0.04	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 110809	Soil	10	22	0.14	54	0.009	<1	1.07	0.004	0.03	0.1	0.06	0.7	<0.1	<0.05	4	0.7	0.4
KYS 110810	Soil	8	18	0.20	75	0.011	3	0.90	0.004	0.03	0.2	0.05	0.6	<0.1	<0.05	3	0.6	<0.2
KYS 110811	Soil	8	17	0.21	83	0.013	2	0.95	0.004	0.03	0.1	0.03	1.0	<0.1	<0.05	3	0.6	<0.2
KYS 110812	Soil	6	12	0.06	39	0.006	3	0.57	0.004	0.02	<0.1	0.02	0.2	<0.1	<0.05	4	1.1	<0.2
KYS 110813	Soil	10	18	0.22	79	0.016	2	1.24	0.004	0.03	0.1	0.06	2.1	<0.1	<0.05	3	1.0	<0.2
KYS 110814	Soil	10	19	0.22	87	0.016	<1	1.40	0.005	0.04	0.1	0.07	2.2	<0.1	<0.05	3	1.5	<0.2
KYS 110815	Soil	11	26	0.39	113	0.024	1	1.76	0.006	0.04	0.2	0.04	2.1	0.1	<0.05	5	1.0	<0.2
KYS 110816	Soil	8	23	0.25	85	0.016	<1	1.19	0.006	0.03	0.1	0.06	1.2	<0.1	<0.05	4	1.5	<0.2
KYS 110817	Soil	8	23	0.21	65	0.023	<1	1.11	0.005	0.03	0.2	0.05	1.3	<0.1	<0.05	5	1.1	<0.2
KYS 110818	Soil	9	21	0.25	99	0.017	<1	1.31	0.006	0.03	0.1	0.07	1.3	<0.1	<0.05	4	1.0	<0.2
KYS 110819	Soil	9	23	0.27	87	0.018	<1	1.32	0.007	0.03	0.2	0.06	1.2	<0.1	<0.05	4	0.7	<0.2
KYS 110820	Soil	9	25	0.28	104	0.018	1	1.43	0.005	0.04	0.2	0.06	1.1	<0.1	<0.05	5	1.0	<0.2
KYS 110821	Soil	10	22	0.24	98	0.021	<1	1.37	0.006	0.04	0.2	0.06	1.6	<0.1	<0.05	5	0.7	<0.2
KYS 110822	Soil	11	25	0.31	108	0.028	<1	1.35	0.005	0.04	0.2	0.04	1.9	<0.1	<0.05	5	0.9	<0.2
KYS 110823	Soil	9	19	0.25	97	0.031	<1	1.02	0.003	0.04	0.2	0.04	1.4	<0.1	<0.05	5	0.6	<0.2
KYS 110824	Soil	11	23	0.28	82	0.033	<1	1.19	0.005	0.04	0.2	0.04	1.6	<0.1	<0.05	5	0.6	<0.2
KYS 110825	Soil	11	21	0.27	79	0.024	<1	1.07	0.006	0.03	0.2	0.05	1.8	<0.1	<0.05	3	0.7	<0.2
KYS 110826	Soil	13	23	0.33	86	0.037	1	1.33	0.005	0.04	0.2	0.05	2.1	<0.1	<0.05	4	0.7	<0.2
KYS 110827	Soil	12	25	0.34	112	0.030	1	1.52	0.006	0.04	0.2	0.04	1.8	0.1	<0.05	7	0.8	<0.2
KYS 110828	Soil	12	21	0.24	92	0.024	1	1.17	0.006	0.05	0.2	0.03	1.4	<0.1	<0.05	5	0.8	<0.2
KYS 110829	Soil	9	16	0.18	193	0.031	<1	0.88	0.005	0.04	0.2	0.03	1.1	0.1	<0.05	5	0.6	<0.2
KYS 110830	Soil	9	21	0.19	110	0.026	<1	1.22	0.005	0.03	0.2	0.05	1.1	<0.1	<0.05	6	0.5	<0.2
KYS 110831	Soil	12	21	0.33	136	0.029	<1	1.19	0.005	0.04	0.2	0.02	1.7	<0.1	<0.05	4	0.5	<0.2
KYS 110832	Soil	11	16	0.21	79	0.025	<1	0.91	0.004	0.03	0.2	0.03	1.5	<0.1	<0.05	3	0.6	<0.2
KYS 110833	Soil	9	13	0.13	70	0.017	1	0.67	0.004	0.02	0.2	0.03	0.9	<0.1	<0.05	2	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110834	Soil		1.2	53.7	11.8	102	0.3	38.5	17.0	1016	2.66	66.4	2.1	6.6	1.0	16	0.6	1.4	0.2	35	0.20	0.096
KYS 110835	Soil		1.1	27.6	10.4	70	0.1	20.0	7.2	258	2.24	21.2	0.9	12.9	1.8	11	0.3	1.3	0.2	38	0.09	0.062
KYS 110836	Soil		1.0	9.8	7.7	26	0.2	8.4	2.3	66	1.15	7.8	0.6	<0.5	0.1	8	0.2	0.5	0.2	26	0.05	0.053
KYS 110837	Soil		1.4	21.5	11.2	53	0.1	17.4	4.9	151	2.20	19.0	0.9	0.8	0.7	13	0.1	1.2	0.2	40	0.12	0.069
KYS 110838	Soil		1.5	24.1	11.7	61	0.2	18.1	7.2	327	2.37	20.5	0.9	5.6	2.7	14	0.3	1.6	0.2	40	0.12	0.085
KYS 110839	Soil		1.4	22.9	12.4	52	0.2	15.9	4.6	167	2.26	24.7	0.9	3.7	0.9	14	0.3	1.6	0.2	42	0.09	0.075
KYS 110840	Soil		1.1	18.5	9.7	47	0.2	14.7	4.6	190	2.03	21.8	0.8	4.0	1.0	12	0.2	1.3	0.2	40	0.11	0.066
KYS 110841	Soil		1.4	16.2	11.4	41	0.1	13.8	4.1	158	2.21	29.7	0.9	2.2	0.4	10	0.2	1.1	0.2	43	0.06	0.057
KYS 110842	Soil		1.6	24.3	15.5	40	0.4	12.8	4.0	155	2.09	41.5	1.2	10.2	0.3	19	0.2	3.1	0.3	41	0.05	0.073
KYS 110843	Soil		1.5	17.6	12.0	46	0.2	14.3	4.4	174	2.42	31.9	0.8	2.9	1.3	12	0.2	1.1	0.3	52	0.08	0.049
KYS 110844	Soil		1.5	17.0	12.5	44	0.1	13.7	4.4	168	2.36	30.6	0.8	2.5	1.4	12	0.2	1.1	0.3	50	0.07	0.044
KYS 110845	Soil		1.6	18.9	12.6	43	0.3	14.2	4.0	171	2.28	53.8	0.9	8.8	0.6	12	0.2	1.6	0.3	48	0.05	0.064
KYS 110846	Soil		2.2	30.5	20.7	75	0.2	14.6	3.9	218	3.47	13.5	1.0	2.5	3.2	7	<0.1	1.0	0.3	19	0.02	0.060
KYS 110847	Soil		5.7	49.8	23.4	86	0.3	18.1	5.5	269	4.56	20.2	2.1	4.2	4.9	14	0.1	2.1	0.4	33	0.02	0.078
KYS 110848	Soil		2.9	33.7	23.4	76	0.1	22.3	7.1	236	3.68	14.3	1.4	4.8	4.6	8	0.2	1.1	0.3	29	0.04	0.064
KYS 110849	Soil		4.9	63.3	20.1	138	0.3	38.2	10.7	310	3.67	30.1	3.1	5.7	4.6	15	0.4	2.7	0.3	34	0.06	0.087
KYS 110850	Soil		12.5	50.9	20.5	109	0.7	20.5	4.1	148	3.89	23.3	2.4	4.7	4.0	20	0.2	3.8	0.4	41	0.02	0.087
KYS 110851	Soil		7.3	52.3	18.2	100	0.5	29.3	6.6	209	3.31	19.4	2.0	3.2	3.3	22	0.3	2.5	0.3	43	0.04	0.089
KYS 110852	Soil		4.4	63.1	14.3	104	0.3	34.4	8.6	314	2.90	15.2	1.9	38.2	5.3	16	0.4	1.8	0.3	41	0.08	0.078
KYS 110853	Soil		7.5	53.3	14.5	95	0.8	25.3	8.9	431	3.03	21.6	2.6	7.0	2.3	20	0.5	3.4	0.2	45	0.11	0.127
KYS 110854	Soil		8.5	98.0	15.9	130	0.5	39.3	6.9	234	3.25	20.9	4.8	5.6	7.5	22	0.7	3.6	0.3	50	0.12	0.122
KYS 110855	Soil		8.7	99.0	14.4	120	0.4	38.1	11.7	442	3.13	18.6	4.9	3.2	5.0	17	0.5	2.9	0.2	44	0.07	0.100
KYS 110856	Soil		8.6	46.1	17.1	118	0.4	24.9	8.5	261	3.35	15.2	2.7	4.5	8.0	25	0.4	3.7	0.3	43	0.05	0.098
KYS 110857	Soil		14.5	43.5	20.5	85	1.0	14.7	2.4	107	2.74	31.3	4.0	2.1	0.7	28	0.8	4.0	0.3	60	0.05	0.116
KYS 110858	Soil		13.8	57.7	21.6	125	1.2	25.4	5.9	220	3.79	33.2	5.0	4.7	3.4	27	0.8	5.3	0.4	58	0.06	0.145
KYS 110859	Soil		7.3	28.2	15.1	97	0.7	22.3	7.0	250	2.80	17.6	1.9	2.6	1.3	14	0.6	2.3	0.2	45	0.07	0.092
KYS 110860	Soil		16.4	32.4	17.1	82	0.6	17.3	3.3	153	2.63	26.6	2.5	1.9	0.7	25	0.6	5.1	0.3	48	0.05	0.080
KYS 110861	Soil		10.5	43.3	20.6	96	0.4	22.4	6.0	249	3.35	19.0	4.2	2.5	4.2	24	0.6	3.2	0.3	43	0.06	0.106
KYS 110862	Soil		7.1	21.9	13.3	64	0.7	12.2	2.5	81	1.87	9.9	1.3	3.3	0.3	8	0.3	1.4	0.2	44	0.02	0.058
KYS 110863	Soil		8.1	31.2	15.1	87	0.3	21.5	7.6	373	2.96	16.1	2.1	3.2	6.4	16	0.3	3.2	0.3	50	0.06	0.060

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110834	Soil	11	25	0.40	155	0.018	<1	1.20	0.006	0.04	0.2	0.05	1.8	<0.1	<0.05	3	1.6	<0.2
KYS 110835	Soil	11	22	0.36	93	0.028	<1	1.36	0.005	0.04	0.2	0.03	1.7	<0.1	<0.05	4	0.8	<0.2
KYS 110836	Soil	9	14	0.17	76	0.015	<1	0.78	0.005	0.03	0.1	0.05	0.5	<0.1	<0.05	3	<0.5	<0.2
KYS 110837	Soil	10	21	0.31	105	0.023	<1	1.18	0.007	0.04	0.2	0.04	1.3	<0.1	<0.05	4	1.2	<0.2
KYS 110838	Soil	12	21	0.30	88	0.027	<1	1.17	0.006	0.04	0.2	0.04	1.8	<0.1	<0.05	4	1.0	<0.2
KYS 110839	Soil	11	20	0.28	110	0.022	1	1.13	0.006	0.04	0.2	0.06	1.2	<0.1	<0.05	4	1.4	0.4
KYS 110840	Soil	10	19	0.26	88	0.026	1	0.98	0.005	0.04	0.2	0.06	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110841	Soil	10	21	0.28	84	0.018	<1	1.11	0.006	0.04	0.2	0.05	0.9	<0.1	<0.05	5	0.9	<0.2
KYS 110842	Soil	10	21	0.22	108	0.013	<1	1.10	0.005	0.04	0.2	0.07	0.9	<0.1	<0.05	4	1.0	<0.2
KYS 110843	Soil	12	23	0.28	118	0.028	2	1.46	0.006	0.04	0.3	0.04	1.5	<0.1	<0.05	6	1.1	<0.2
KYS 110844	Soil	11	22	0.26	115	0.025	<1	1.32	0.005	0.03	0.2	0.04	1.6	<0.1	<0.05	5	0.7	<0.2
KYS 110845	Soil	9	21	0.24	72	0.021	<1	1.00	0.007	0.04	0.2	0.04	1.1	<0.1	<0.05	5	0.7	<0.2
KYS 110846	Soil	19	14	0.41	45	0.004	<1	1.12	0.005	0.04	<0.1	0.02	0.6	<0.1	0.05	4	1.2	<0.2
KYS 110847	Soil	21	19	0.44	122	0.003	<1	1.40	0.006	0.07	<0.1	0.09	1.2	<0.1	0.08	4	2.7	0.2
KYS 110848	Soil	18	20	0.45	69	0.007	<1	1.62	0.005	0.04	0.1	0.04	1.2	<0.1	<0.05	5	1.3	<0.2
KYS 110849	Soil	20	19	0.33	111	0.007	<1	1.53	0.006	0.06	0.2	0.10	1.5	<0.1	<0.05	4	2.9	<0.2
KYS 110850	Soil	23	20	0.33	137	0.003	<1	1.14	0.007	0.06	0.1	0.15	0.9	0.1	0.10	4	3.5	<0.2
KYS 110851	Soil	19	23	0.34	147	0.007	<1	1.51	0.006	0.06	0.1	0.16	1.3	0.1	0.05	4	2.4	<0.2
KYS 110852	Soil	19	22	0.42	118	0.013	1	1.52	0.005	0.05	0.2	0.10	1.8	0.1	<0.05	4	1.4	<0.2
KYS 110853	Soil	18	21	0.34	109	0.014	<1	1.20	0.007	0.05	0.2	0.15	1.4	0.1	0.06	3	2.4	<0.2
KYS 110854	Soil	22	21	0.38	150	0.019	1	1.37	0.006	0.05	0.2	0.19	2.2	0.1	<0.05	4	2.6	<0.2
KYS 110855	Soil	20	19	0.42	156	0.011	<1	1.59	0.004	0.06	0.2	0.22	2.1	0.2	<0.05	4	2.1	<0.2
KYS 110856	Soil	24	22	0.33	109	0.009	<1	1.38	0.005	0.05	0.1	0.18	1.5	<0.1	<0.05	4	2.8	<0.2
KYS 110857	Soil	20	14	0.17	204	0.007	6	0.93	0.008	0.06	0.2	0.18	0.5	0.1	0.10	3	3.8	<0.2
KYS 110858	Soil	23	20	0.28	218	0.010	<1	1.12	0.005	0.07	0.2	0.19	1.3	0.2	0.09	4	4.8	<0.2
KYS 110859	Soil	17	20	0.27	111	0.012	<1	1.34	0.004	0.04	0.2	0.12	1.0	0.1	<0.05	4	2.4	<0.2
KYS 110860	Soil	19	15	0.22	103	0.010	<1	0.92	0.004	0.06	0.2	0.19	0.6	0.2	<0.05	3	3.0	<0.2
KYS 110861	Soil	26	17	0.26	282	0.008	<1	1.40	0.004	0.07	0.1	0.17	1.3	0.2	<0.05	4	3.4	<0.2
KYS 110862	Soil	20	12	0.13	92	0.005	<1	1.01	0.004	0.04	0.1	0.06	0.3	0.1	<0.05	5	1.2	<0.2
KYS 110863	Soil	20	23	0.35	97	0.022	1	1.60	0.006	0.06	0.2	0.19	2.2	0.2	<0.05	4	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110864	Soil		6.7	46.6	15.0	98	0.4	24.8	7.4	348	2.96	16.8	2.3	4.7	6.3	15	0.6	3.4	0.3	44	0.08	0.076
KYS 110865	Soil		15.4	38.3	16.2	74	0.6	18.6	5.1	213	2.66	17.5	1.6	3.9	2.7	30	0.3	5.4	0.3	42	0.06	0.071
KYS 110866	Soil		20.4	29.6	19.4	105	0.8	25.2	5.2	170	2.80	23.7	2.9	3.2	5.9	39	0.5	4.9	0.2	57	0.15	0.095
KYS 110867	Soil		22.5	48.7	22.7	116	1.1	22.1	4.9	218	3.66	35.0	4.7	3.0	6.6	44	0.7	6.3	0.3	84	0.03	0.097
KYS 110868	Soil		20.8	64.0	24.3	114	1.1	24.9	5.6	219	4.20	28.6	4.0	2.2	3.1	39	0.6	5.3	0.4	85	0.03	0.117
KYS 110869	Soil		19.5	58.5	32.8	147	2.0	27.3	8.3	272	3.47	24.6	5.7	5.9	4.8	58	1.2	5.6	0.4	48	0.06	0.170
KYS 110870	Soil		27.9	42.5	24.5	142	1.2	29.0	6.5	286	2.89	26.8	6.2	3.5	4.8	79	1.3	7.4	0.3	69	0.13	0.096
KYS 110871	Soil		14.7	100.1	24.8	131	1.1	31.1	8.7	359	3.22	27.6	6.7	7.1	8.6	65	0.7	4.3	0.4	75	0.09	0.114
KYS 110872	Soil		16.1	98.1	34.5	153	2.1	23.1	5.5	329	3.83	21.8	6.9	7.4	10.3	94	0.6	4.4	0.6	80	0.12	0.138
KYS 110873	Soil		4.9	49.6	21.3	79	0.4	23.4	4.0	107	2.62	15.1	2.8	7.3	1.9	23	1.0	2.1	0.3	31	0.08	0.082
KYS 110874	Soil		8.4	46.2	27.9	65	0.7	15.3	2.5	100	2.91	16.3	2.5	3.6	0.9	20	0.9	2.1	0.3	40	0.03	0.088
KYS 110899	Soil		3.3	37.2	14.6	93	0.4	26.8	7.3	227	3.23	14.8	2.0	2.9	3.9	11	0.4	1.6	0.3	40	0.08	0.063
KYS 110900	Soil		4.9	45.9	16.5	89	0.5	27.0	6.9	203	3.36	16.2	2.1	2.7	1.6	14	0.3	1.6	0.3	41	0.06	0.068
KYS 110901	Soil		9.5	65.8	18.8	76	0.8	21.2	4.6	177	3.13	19.1	3.2	5.6	3.7	15	0.2	2.6	0.3	43	0.05	0.085
KYS 110902	Soil		5.3	49.3	16.0	89	0.3	25.6	6.3	158	3.00	16.0	1.9	4.0	3.0	19	0.3	1.8	0.3	40	0.04	0.070
KYS 110903	Soil		8.1	37.9	18.1	104	0.7	22.2	4.7	185	3.46	27.1	2.1	7.2	2.6	16	0.3	10.1	0.2	45	0.06	0.084
KYS 110904	Soil		4.8	27.1	12.3	83	0.2	19.8	6.6	294	2.86	14.7	1.6	2.9	3.3	12	0.4	1.8	0.2	46	0.08	0.071
KYS 110905	Soil		4.5	24.4	12.8	52	0.4	11.8	3.2	149	2.34	12.2	1.1	1.8	1.6	11	0.2	1.3	0.2	44	0.05	0.068
KYS 110906	Soil		10.7	43.8	22.8	115	0.6	22.2	7.1	350	3.73	26.3	2.0	1.3	2.6	18	0.9	4.0	0.3	59	0.06	0.138
KYS 110907	Soil		15.8	55.7	23.0	87	1.4	16.9	2.8	176	3.03	33.0	3.0	2.5	1.4	27	0.8	5.2	0.3	48	0.03	0.127
KYS 110908	Soil		30.5	24.6	25.1	74	0.9	12.1	1.5	84	2.07	25.2	1.7	1.3	0.9	14	1.3	5.8	0.4	122	0.03	0.139
KYS 110909	Soil		24.4	79.9	34.3	88	1.4	13.7	2.3	114	3.22	28.5	5.1	5.4	6.4	34	0.5	7.3	0.5	79	0.03	0.155
KYS 110910	Soil		43.8	63.1	26.4	182	1.5	16.6	2.0	93	5.49	80.0	5.3	1.9	6.2	23	0.7	12.5	0.3	98	0.02	0.218
KYS 110911	Soil		6.5	39.8	27.9	82	0.7	17.9	5.8	205	3.26	19.9	2.0	1.1	1.9	14	0.5	2.2	0.4	40	0.04	0.083
KYS 110912	Soil		6.1	44.2	19.9	106	0.4	25.0	8.9	261	2.88	13.3	2.4	10.6	1.9	20	1.7	1.9	0.3	30	0.13	0.067
KYS 110913	Soil		5.3	20.6	15.4	45	1.1	9.0	2.3	63	1.25	7.9	1.2	<0.5	0.3	10	1.0	1.1	0.3	34	0.03	0.059
KYS 110914	Soil		2.1	24.3	9.0	74	0.4	61.4	7.5	112	0.92	4.4	2.3	1.3	0.2	27	13.0	0.8	0.1	17	0.20	0.060
KYS 110915	Soil		6.9	23.9	15.8	51	0.3	9.5	2.7	127	2.31	16.2	1.1	0.5	0.5	13	0.5	2.4	0.3	46	0.03	0.062
KYS 110916	Soil		7.8	45.6	24.7	140	0.3	32.9	15.6	798	3.22	23.9	2.2	2.0	3.9	13	0.8	3.3	0.4	35	0.04	0.071
KYS 110917	Soil		10.6	45.1	21.8	113	0.4	20.1	8.3	240	3.51	22.7	2.5	1.7	4.8	23	0.5	5.1	0.3	41	0.02	0.085

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110864	Soil		22	21	0.40	103	0.022	<1	1.39	0.007	0.05	0.2	0.20	2.6	0.1	<0.05	4	1.9	<0.2
KYS 110865	Soil		21	17	0.26	124	0.009	<1	1.15	0.005	0.05	0.3	0.26	1.1	0.2	<0.05	3	2.9	<0.2
KYS 110866	Soil		23	12	0.35	199	0.011	<1	0.79	0.004	0.07	0.2	0.18	0.9	0.2	<0.05	3	5.6	<0.2
KYS 110867	Soil		28	15	0.33	190	0.016	<1	0.86	0.005	0.09	0.3	0.26	1.1	0.3	0.18	3	4.5	<0.2
KYS 110868	Soil		33	19	0.33	317	0.009	<1	1.20	0.006	0.12	0.2	0.31	1.2	0.2	0.18	4	6.2	0.2
KYS 110869	Soil		39	14	0.30	202	0.006	<1	0.92	0.005	0.07	0.1	0.42	1.0	0.2	0.10	3	7.0	<0.2
KYS 110870	Soil		33	11	0.23	196	0.011	<1	0.62	0.004	0.08	0.2	0.37	1.2	0.2	0.07	2	6.0	<0.2
KYS 110871	Soil		37	22	0.41	212	0.016	1	1.41	0.007	0.08	0.2	0.37	2.5	0.2	0.09	4	4.4	<0.2
KYS 110872	Soil		32	25	0.45	190	0.009	<1	1.31	0.004	0.08	0.1	0.42	2.0	0.2	0.09	4	5.8	0.2
KYS 110873	Soil		21	14	0.23	143	0.007	<1	0.96	0.005	0.05	0.1	0.15	1.2	0.1	<0.05	3	2.2	0.5
KYS 110874	Soil		22	13	0.17	184	0.003	<1	0.93	0.004	0.06	<0.1	0.15	0.6	0.1	<0.05	3	2.4	<0.2
KYS 110899	Soil		19	24	0.42	94	0.021	<1	1.75	0.003	0.05	0.2	0.09	1.8	0.2	<0.05	5	1.7	<0.2
KYS 110900	Soil		20	21	0.34	117	0.009	<1	1.39	0.006	0.06	0.1	0.08	1.1	0.1	<0.05	5	1.7	<0.2
KYS 110901	Soil		22	19	0.28	104	0.007	<1	1.36	0.004	0.05	0.1	0.16	1.3	0.1	0.05	4	3.0	<0.2
KYS 110902	Soil		21	21	0.30	143	0.009	<1	1.52	0.005	0.06	0.1	0.09	1.5	0.1	0.05	5	1.9	<0.2
KYS 110903	Soil		23	18	0.24	131	0.010	<1	1.04	0.007	0.06	0.2	0.20	1.4	0.1	<0.05	3	2.7	<0.2
KYS 110904	Soil		17	22	0.31	89	0.017	<1	1.38	0.004	0.05	0.2	0.09	1.4	0.1	<0.05	4	1.6	<0.2
KYS 110905	Soil		19	18	0.22	73	0.015	<1	1.22	0.004	0.04	0.1	0.10	1.2	0.1	<0.05	5	1.3	<0.2
KYS 110906	Soil		20	20	0.22	152	0.008	<1	1.09	0.005	0.05	0.2	0.16	1.0	0.1	0.08	4	3.6	<0.2
KYS 110907	Soil		25	16	0.19	220	0.004	<1	0.89	0.006	0.05	0.1	0.18	0.5	0.1	0.12	3	5.5	<0.2
KYS 110908	Soil		20	13	0.08	195	0.032	3	0.67	0.010	0.08	0.5	0.07	1.9	0.2	0.58	4	3.5	<0.2
KYS 110909	Soil		32	23	0.23	258	0.030	2	0.87	0.010	0.09	0.4	0.38	1.8	0.2	0.60	3	8.6	<0.2
KYS 110910	Soil		28	19	0.10	133	0.004	<1	0.54	0.004	0.06	0.4	0.66	1.5	0.2	0.16	3	11.0	<0.2
KYS 110911	Soil		17	16	0.21	96	0.008	<1	0.99	0.004	0.04	0.1	0.08	0.8	<0.1	<0.05	4	1.5	<0.2
KYS 110912	Soil		17	15	0.35	98	0.007	<1	1.04	0.004	0.05	0.1	0.08	0.8	<0.1	0.09	3	1.5	<0.2
KYS 110913	Soil		16	10	0.07	96	0.007	<1	0.60	0.007	0.04	0.1	0.10	0.6	0.1	0.08	3	1.1	<0.2
KYS 110914	Soil		12	10	0.08	99	0.003	<1	0.53	0.007	0.03	<0.1	0.11	0.2	<0.1	0.07	2	3.8	<0.2
KYS 110915	Soil		19	17	0.17	88	0.009	<1	0.97	0.004	0.04	0.1	0.08	0.5	0.1	<0.05	4	1.8	0.2
KYS 110916	Soil		21	15	0.29	131	0.006	<1	0.93	0.005	0.05	0.1	0.05	1.1	<0.1	0.05	3	2.5	<0.2
KYS 110917	Soil		25	15	0.27	164	0.005	<1	0.78	0.006	0.07	<0.1	0.15	0.9	0.1	0.16	3	3.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110918	Soil	12.6	59.5	28.8	126	0.5	24.8	6.8	268	4.31	29.0	3.1	2.8	6.5	30	0.8	6.2	0.4	54	0.02	0.119
KYS 110919	Soil	7.4	24.0	15.6	46	0.3	7.3	1.8	69	1.85	14.3	0.7	<0.5	0.7	10	0.4	2.0	0.3	54	0.01	0.057
KYS 110920	Soil	6.8	41.3	17.6	92	0.6	18.4	4.4	103	2.96	21.7	1.8	0.6	3.7	20	0.5	4.4	0.2	24	0.04	0.076

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

CERTIFICATE OF ANALYSIS WHI10000181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110918	Soil	24	16	0.22	259	0.004	<1	1.07	0.006	0.09	0.1	0.19	1.4	0.2	0.16	3	4.2	0.3
KYS 110919	Soil	24	12	0.08	123	0.006	<1	0.81	0.004	0.04	<0.1	0.02	0.5	0.1	<0.05	5	1.4	<0.2
KYS 110920	Soil	16	9	0.12	68	0.005	<1	0.42	0.004	0.04	<0.1	0.08	0.7	<0.1	0.07	1	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

QUALITY CONTROL REPORT WHI10000181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
KYS 110784	Soil	0.8	19.8	20.3	57	<0.1	33.5	14.1	506	3.07	15.5	0.9	1.2	4.6	9	0.1	0.5	0.2	37	0.07	0.042
REP KYS 110784	QC	0.6	20.1	21.2	60	<0.1	35.4	14.8	533	3.19	16.0	0.9	2.6	4.7	9	0.2	0.6	0.2	39	0.07	0.046
KYS 110804	Soil	0.6	59.1	30.9	81	<0.1	36.9	17.4	1153	3.19	3.2	2.0	1.3	13.6	15	0.1	0.2	0.4	18	0.15	0.047
REP KYS 110804	QC	0.6	60.4	32.0	81	<0.1	36.1	17.5	1163	3.18	3.4	2.1	0.6	13.3	15	<0.1	0.2	0.4	19	0.16	0.046
KYS 110819	Soil	1.5	15.6	12.8	48	0.5	13.6	5.0	214	2.52	26.3	0.7	3.7	1.0	11	0.2	1.4	0.2	39	0.06	0.065
REP KYS 110819	QC	1.5	16.1	12.7	52	0.5	13.6	5.0	219	2.48	26.7	0.8	4.6	1.0	11	0.2	1.4	0.3	39	0.06	0.067
KYS 110843	Soil	1.5	17.6	12.0	46	0.2	14.3	4.4	174	2.42	31.9	0.8	2.9	1.3	12	0.2	1.1	0.3	52	0.08	0.049
REP KYS 110843	QC	1.4	17.0	11.8	44	0.2	14.2	4.2	165	2.42	30.6	0.8	6.5	1.2	13	0.2	1.1	0.3	52	0.07	0.046
KYS 110847	Soil	5.7	49.8	23.4	86	0.3	18.1	5.5	269	4.56	20.2	2.1	4.2	4.9	14	0.1	2.1	0.4	33	0.02	0.078
REP KYS 110847	QC	5.8	50.5	24.2	88	0.3	18.3	5.8	275	4.84	20.3	2.2	4.3	5.2	14	0.1	2.1	0.4	33	0.02	0.077
KYS 110874	Soil	8.4	46.2	27.9	65	0.7	15.3	2.5	100	2.91	16.3	2.5	3.6	0.9	20	0.9	2.1	0.3	40	0.03	0.088
REP KYS 110874	QC	8.7	45.0	28.5	66	0.7	14.9	2.5	100	2.87	16.5	2.4	3.3	1.0	20	0.9	2.0	0.4	45	0.03	0.085
KYS 110912	Soil	6.1	44.2	19.9	106	0.4	25.0	8.9	261	2.88	13.3	2.4	10.6	1.9	20	1.7	1.9	0.3	30	0.13	0.067
REP KYS 110912	QC	5.7	44.9	19.8	109	0.4	25.5	8.8	271	2.92	13.0	2.5	<0.5	2.2	20	1.9	1.9	0.3	29	0.13	0.067
Reference Materials																					
STD DS7	Standard	19.6	98.5	65.8	385	1.0	54.4	9.0	638	2.36	53.4	4.9	83.6	4.9	76	6.0	5.7	4.6	82	0.97	0.082
STD DS7	Standard	21.1	111.8	65.6	420	1.0	55.1	9.3	676	2.49	56.5	5.0	77.1	4.4	77	7.3	6.3	4.9	86	0.93	0.081
STD DS7	Standard	20.4	95.5	62.1	390	1.0	52.4	7.7	603	2.29	47.2	4.4	78.5	4.4	81	5.5	5.3	4.2	80	1.01	0.068
STD DS7	Standard	20.8	109.8	67.1	396	1.0	53.4	9.4	664	2.46	55.9	4.6	85.6	4.9	78	6.7	6.2	4.7	86	0.96	0.079
STD DS7	Standard	20.2	105.8	69.2	393	0.9	56.8	9.4	614	2.39	50.6	4.7	65.8	4.4	71	5.6	5.7	4.4	83	0.90	0.077
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 24, 2010

QUALITY CONTROL REPORT WHI10000181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
KYS 110784	Soil	19	54	0.84	87	0.012	<1	1.46	0.004	0.11	<0.1	0.02	1.6	<0.1	<0.05	5	<0.5	<0.2
REP KYS 110784	QC	20	55	0.90	94	0.013	1	1.57	0.004	0.12	0.1	0.03	1.7	<0.1	<0.05	5	<0.5	<0.2
KYS 110804	Soil	31	19	0.60	73	0.025	<1	1.17	0.004	0.06	<0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2
REP KYS 110804	QC	30	19	0.60	75	0.023	<1	1.20	0.007	0.06	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 110819	Soil	9	23	0.27	87	0.018	<1	1.32	0.007	0.03	0.2	0.06	1.2	<0.1	<0.05	4	0.7	<0.2
REP KYS 110819	QC	9	24	0.26	85	0.018	1	1.37	0.004	0.03	0.1	0.07	1.2	<0.1	<0.05	5	0.9	<0.2
KYS 110843	Soil	12	23	0.28	118	0.028	2	1.46	0.006	0.04	0.3	0.04	1.5	<0.1	<0.05	6	1.1	<0.2
REP KYS 110843	QC	12	21	0.27	115	0.027	2	1.32	0.006	0.04	0.3	0.05	1.6	0.1	<0.05	5	0.8	<0.2
KYS 110847	Soil	21	19	0.44	122	0.003	<1	1.40	0.006	0.07	<0.1	0.09	1.2	<0.1	0.08	4	2.7	0.2
REP KYS 110847	QC	21	21	0.47	125	0.003	<1	1.52	0.007	0.07	<0.1	0.09	1.3	0.1	0.08	5	2.7	<0.2
KYS 110874	Soil	22	13	0.17	184	0.003	<1	0.93	0.004	0.06	<0.1	0.15	0.6	0.1	<0.05	3	2.4	<0.2
REP KYS 110874	QC	23	13	0.18	191	0.003	<1	0.94	0.006	0.06	<0.1	0.15	0.6	0.2	<0.05	4	2.2	<0.2
KYS 110912	Soil	17	15	0.35	98	0.007	<1	1.04	0.004	0.05	0.1	0.08	0.8	<0.1	0.09	3	1.5	<0.2
REP KYS 110912	QC	19	15	0.34	106	0.011	<1	1.01	0.004	0.05	0.1	0.08	1.0	<0.1	0.13	3	1.8	<0.2
Reference Materials																		
STD DS7	Standard	14	226	1.09	403	0.110	40	1.11	0.113	0.49	3.8	0.21	2.6	4.2	0.21	5	3.0	1.0
STD DS7	Standard	12	202	1.01	423	0.123	40	1.02	0.105	0.48	3.5	0.22	2.6	4.3	0.18	5	3.5	1.6
STD DS7	Standard	13	204	1.10	403	0.124	41	1.09	0.107	0.51	3.7	0.23	2.5	4.0	0.18	5	3.2	1.8
STD DS7	Standard	14	209	1.04	419	0.128	38	1.02	0.103	0.48	3.7	0.24	2.7	4.3	0.19	5	3.8	0.8
STD DS7	Standard	12	196	1.05	377	0.118	39	1.01	0.102	0.44	3.3	0.20	2.4	4.0	0.19	5	3.7	1.6
STD DS7 Expected		12	179	1.05	410	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5	1.08
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Submitted By: Johnathan More
Receiving Lab: Canada-Whitehorse
Received: July 14, 2010
Report Date: August 19, 2010
Page: 1 of 11

CERTIFICATE OF ANALYSIS WHI10000119.1

CLIENT JOB INFORMATION

Project: KYS
Shipment ID: KYS1
P.O. Number
Number of Samples: 280

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	280	Dry at 60C sieve 100g to -80 mesh			VAN
Dry at 60C	280	Dry at 60C			VAN
1DX2	280	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Aldrin Resources
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5
Canada

CC: Isaac Fage
Bert Jeffries
Shawn Ryan

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110486	Soil	1.6	39.2	21.0	82	0.2	30.3	11.2	622	2.75	15.7	1.6	8.6	4.4	11	0.3	2.0	0.3	31	0.12	0.071
KYS 110487	Soil	1.8	41.1	23.7	100	0.3	32.7	12.3	665	3.03	15.6	1.6	6.4	4.5	10	0.3	2.2	0.3	32	0.10	0.074
KYS 110488	Soil	1.4	33.9	19.8	73	0.2	27.3	10.0	483	2.62	14.5	1.3	10.0	3.7	10	0.3	1.9	0.3	33	0.09	0.062
KYS 110489	Soil	2.4	40.7	17.5	64	0.4	22.0	6.6	271	2.54	18.6	1.5	13.2	3.2	12	0.4	3.2	0.3	33	0.09	0.091
KYS 110490	Soil	2.7	48.9	31.4	70	0.6	24.4	5.3	296	3.28	24.1	1.4	16.2	1.4	19	0.1	3.2	0.6	44	0.06	0.133
KYS 110491	Soil	2.4	51.5	24.7	74	0.6	22.0	4.6	241	2.95	24.5	1.1	11.5	0.8	12	<0.1	3.0	0.4	34	0.03	0.094
KYS 110492	Soil	1.2	84.2	24.9	105	0.2	48.7	19.8	1811	3.64	29.1	1.8	11.3	10.9	19	0.2	3.1	0.3	21	0.21	0.067
KYS 110493	Soil	1.1	68.4	35.1	109	0.2	50.4	21.6	1149	3.81	28.1	1.9	10.8	14.0	18	0.2	4.4	0.3	22	0.23	0.077
KYS 110494	Soil	1.1	71.0	37.4	112	0.3	49.9	21.8	1153	3.85	28.7	1.9	10.9	14.2	19	0.2	4.6	0.3	22	0.24	0.076
KYS 110495	Soil	0.7	35.9	31.7	72	<0.1	33.3	21.0	695	3.33	21.9	1.2	2.8	2.6	9	<0.1	1.0	0.4	24	0.11	0.046
KYS 110496	Soil	1.0	36.8	29.0	72	0.1	30.4	13.9	561	3.42	19.3	1.4	4.5	1.7	9	<0.1	1.4	0.4	28	0.10	0.052
KYS 110497	Soil	0.5	57.8	30.1	90	0.1	51.1	23.2	1012	4.01	15.9	2.2	5.5	12.5	20	<0.1	1.1	0.4	11	0.32	0.051
KYS 110498	Soil	0.5	57.4	31.0	90	0.1	47.9	23.0	1053	3.99	16.1	2.3	3.7	12.8	20	<0.1	1.2	0.5	10	0.31	0.053
KYS 110499	Soil	0.5	37.5	29.8	75	0.1	33.0	12.0	588	3.38	14.3	1.7	2.6	4.0	39	<0.1	0.9	0.4	15	0.85	0.071
KYS 110500	Soil	0.6	37.6	20.1	80	<0.1	35.1	13.6	566	3.49	15.2	1.8	3.5	5.1	11	<0.1	0.9	0.3	18	0.13	0.046
KYS 110501	Soil	1.9	163.2	23.4	107	0.2	68.5	22.5	3028	3.10	19.3	1.3	29.2	6.7	20	0.2	3.2	0.3	35	0.11	0.078
KYS 110502	Soil	1.9	127.7	25.3	112	0.3	54.6	19.9	2995	3.47	21.2	1.4	21.6	5.0	22	0.2	3.9	0.4	43	0.12	0.108
KYS 110503	Soil	1.9	138.3	23.2	92	0.3	50.8	19.4	3656	3.19	18.2	1.2	191.8	3.8	15	0.2	2.3	0.4	40	0.07	0.095
KYS 110504	Soil	1.2	96.5	14.6	68	0.1	36.8	11.4	1662	2.58	12.6	1.1	9.7	4.9	15	0.2	1.6	0.2	40	0.10	0.060
KYS 110505	Soil	1.6	100.1	19.4	84	0.2	31.8	10.1	1727	2.87	14.5	1.0	16.1	1.1	14	<0.1	1.7	0.3	40	0.07	0.097
KYS 110506	Soil	1.6	151.5	29.4	132	0.4	78.6	27.9	4235	3.48	51.5	1.5	57.2	5.3	31	0.2	11.9	0.4	30	0.07	0.080
KYS 110507	Soil	1.5	85.5	19.2	112	0.2	54.9	19.5	2498	3.38	29.7	1.2	20.9	2.4	19	0.2	3.7	0.3	48	0.08	0.081
KYS 110508	Soil	1.4	75.1	20.0	134	0.3	62.4	23.5	1341	2.83	15.0	1.4	15.7	8.0	18	0.2	1.9	0.3	34	0.07	0.059
KYS 110509	Soil	1.4	60.1	22.9	100	0.3	44.0	17.7	1535	3.24	14.4	1.5	180.9	2.8	15	0.2	1.7	0.3	42	0.08	0.082
KYS 110510	Soil	1.6	49.4	21.9	82	0.2	27.7	12.4	1191	3.17	13.8	1.1	24.6	1.4	14	0.2	1.5	0.4	38	0.05	0.087
KYS 110511	Soil	5.2	63.0	98.2	454	0.3	224.6	55.1	>10000	5.08	84.8	5.0	10.3	3.6	23	3.7	7.7	0.5	30	0.23	0.140
KYS 110512	Soil	1.1	45.4	13.2	85	0.1	34.1	11.3	1029	2.79	11.6	1.1	6.8	1.8	10	0.2	1.7	0.2	34	0.07	0.048
KYS 110513	Soil	1.3	42.0	14.0	89	0.2	31.0	10.2	975	2.72	32.8	1.5	9.6	1.3	11	0.2	3.3	0.3	30	0.06	0.054
KYS 110514	Soil	1.2	40.0	13.9	86	<0.1	28.7	10.9	868	2.77	129.6	1.1	11.3	1.5	10	0.4	2.7	0.2	37	0.07	0.040
KYS 110515	Soil	1.5	47.9	17.2	95	0.2	36.1	12.4	1414	2.90	219.2	1.8	27.7	1.9	11	0.2	7.7	0.3	31	0.06	0.064

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110486	Soil	16	21	0.40	118	0.020	2	1.24	0.006	0.06	0.2	0.06	1.6	<0.1	0.08	3	0.6	<0.2
KYS 110487	Soil	16	23	0.40	97	0.016	2	1.40	0.007	0.05	0.2	0.08	1.3	<0.1	0.05	3	1.3	<0.2
KYS 110488	Soil	14	21	0.35	100	0.021	<1	1.21	0.007	0.06	0.1	0.07	1.4	<0.1	<0.05	3	0.7	0.2
KYS 110489	Soil	11	19	0.26	114	0.016	<1	0.90	0.013	0.03	0.1	0.09	1.3	<0.1	0.05	3	2.1	<0.2
KYS 110490	Soil	10	27	0.31	147	0.010	<1	1.49	0.006	0.04	0.2	0.15	1.5	<0.1	0.05	4	2.1	<0.2
KYS 110491	Soil	8	23	0.21	98	0.006	1	1.07	0.007	0.03	0.1	0.08	0.7	<0.1	<0.05	4	1.5	0.2
KYS 110492	Soil	28	21	0.64	86	0.004	2	1.33	0.006	0.05	<0.1	0.04	1.3	<0.1	<0.05	3	0.9	<0.2
KYS 110493	Soil	27	29	0.83	84	0.012	1	1.43	0.005	0.07	<0.1	0.04	1.8	<0.1	<0.05	4	0.7	<0.2
KYS 110494	Soil	27	31	0.82	85	0.015	1	1.47	0.005	0.07	<0.1	0.03	1.8	<0.1	<0.05	4	0.7	0.2
KYS 110495	Soil	16	21	0.56	48	0.010	1	1.44	0.004	0.05	0.1	0.02	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110496	Soil	17	21	0.47	66	0.012	<1	1.27	0.005	0.05	0.1	0.03	0.9	<0.1	<0.05	4	0.5	0.3
KYS 110497	Soil	25	16	0.60	36	0.005	1	1.35	0.008	0.09	<0.1	0.02	2.3	<0.1	<0.05	4	<0.5	<0.2
KYS 110498	Soil	23	17	0.64	36	0.007	2	1.47	0.006	0.05	<0.1	0.03	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 110499	Soil	14	17	0.52	73	0.006	<1	1.31	0.005	0.05	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 110500	Soil	23	20	0.62	70	0.008	2	1.54	0.004	0.05	<0.1	0.02	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 110501	Soil	23	22	0.50	104	0.019	<1	1.38	0.006	0.04	0.1	0.08	1.7	<0.1	<0.05	4	0.9	<0.2
KYS 110502	Soil	27	27	0.57	108	0.027	1	1.55	0.010	0.06	0.1	0.06	2.4	<0.1	<0.05	5	0.9	<0.2
KYS 110503	Soil	24	24	0.47	118	0.018	1	1.39	0.006	0.04	0.1	0.10	1.5	<0.1	<0.05	4	1.2	<0.2
KYS 110504	Soil	20	23	0.42	115	0.027	2	1.13	0.005	0.03	0.2	0.05	1.4	<0.1	<0.05	4	<0.5	0.2
KYS 110505	Soil	20	25	0.46	96	0.012	1	1.37	0.007	0.04	0.1	0.08	0.8	<0.1	0.06	4	0.8	0.2
KYS 110506	Soil	35	22	0.51	139	0.009	1	1.25	0.006	0.04	<0.1	0.09	1.7	<0.1	<0.05	4	1.0	0.4
KYS 110507	Soil	23	28	0.47	125	0.022	2	1.50	0.006	0.05	0.1	0.08	1.6	<0.1	<0.05	5	0.9	<0.2
KYS 110508	Soil	22	24	0.47	110	0.016	<1	1.27	0.007	0.04	0.1	0.04	1.5	<0.1	<0.05	4	0.7	<0.2
KYS 110509	Soil	23	23	0.46	121	0.017	<1	1.45	0.010	0.05	0.1	0.07	1.2	<0.1	<0.05	5	0.8	<0.2
KYS 110510	Soil	19	23	0.41	67	0.012	1	1.31	0.006	0.05	<0.1	0.06	1.0	<0.1	<0.05	5	0.7	<0.2
KYS 110511	Soil	27	17	0.45	292	0.008	<1	1.35	0.008	0.05	0.1	0.09	2.4	<0.1	<0.05	4	0.9	<0.2
KYS 110512	Soil	18	22	0.41	75	0.018	<1	1.21	0.005	0.04	0.1	0.04	0.9	<0.1	<0.05	4	0.7	<0.2
KYS 110513	Soil	20	20	0.41	95	0.009	<1	1.21	0.006	0.05	<0.1	0.03	0.8	<0.1	<0.05	4	0.7	<0.2
KYS 110514	Soil	17	23	0.37	91	0.020	<1	1.14	0.005	0.05	0.2	0.04	1.0	<0.1	<0.05	4	0.6	<0.2
KYS 110515	Soil	23	20	0.36	126	0.010	<1	1.25	0.005	0.04	0.1	0.04	1.2	<0.1	<0.05	4	<0.5	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110516	Soil	2.2	51.2	15.6	95	0.1	35.3	10.1	618	2.83	18.9	1.6	6.7	2.1	11	0.3	1.9	0.2	33	0.07	0.052
KYS 110517	Soil	2.3	43.3	16.0	80	0.2	31.1	9.7	772	2.84	54.1	1.5	10.4	1.0	36	0.2	4.6	0.3	40	0.34	0.084
KYS 110518	Soil	1.8	40.3	13.1	134	0.2	59.4	14.4	994	2.90	37.4	2.1	12.4	2.7	17	0.9	3.1	0.2	35	0.16	0.056
KYS 110519	Soil	2.2	46.2	14.3	89	0.3	29.7	8.3	270	2.82	17.1	1.5	7.0	3.3	14	0.4	3.1	0.3	42	0.13	0.089
KYS 110520	Soil	2.2	41.1	17.0	84	0.3	26.4	8.5	317	3.07	33.7	1.2	6.7	1.2	10	0.1	5.3	0.3	29	0.04	0.081
KYS 110521	Soil	2.1	44.4	15.5	85	0.3	24.7	9.9	423	2.91	32.6	1.2	13.8	2.4	10	0.1	6.7	0.3	34	0.05	0.069
KYS 110522	Soil	2.3	49.8	17.6	91	0.2	33.2	11.9	583	3.14	17.9	1.0	9.8	1.6	9	0.2	2.3	0.3	40	0.06	0.079
KYS 110523	Soil	2.2	39.3	16.0	90	0.3	24.7	10.1	391	2.94	34.1	1.4	7.0	2.8	12	0.3	4.0	0.3	46	0.10	0.085
KYS 110524	Soil	1.5	65.0	27.8	93	<0.1	74.9	35.9	1402	4.56	56.1	1.1	6.7	5.0	6	0.2	11.2	0.4	35	0.04	0.062
KYS 110525	Soil	1.3	31.1	18.7	70	<0.1	29.8	16.4	418	3.21	62.0	1.1	5.9	3.8	8	0.2	1.8	0.2	37	0.09	0.066
KYS 110526	Soil	1.8	38.6	19.0	84	<0.1	34.3	17.6	594	3.40	84.6	1.1	18.0	3.9	10	0.2	9.8	0.3	34	0.10	0.073
KYS 110527	Soil	2.4	34.7	15.4	77	<0.1	28.9	13.7	575	3.37	17.8	0.9	3.4	1.8	12	0.3	2.5	0.2	43	0.14	0.097
KYS 110528	Soil	1.5	20.0	13.8	60	<0.1	19.0	7.3	254	2.68	20.8	0.8	4.2	1.1	9	<0.1	2.9	0.2	44	0.09	0.058
KYS 110529	Soil	1.9	34.5	17.8	82	<0.1	30.6	13.6	670	3.12	27.9	1.7	5.2	3.2	11	0.3	2.7	0.3	38	0.10	0.074
KYS 110530	Soil	2.1	75.1	37.8	116	0.6	46.5	19.3	815	4.30	34.7	1.8	33.1	7.5	21	0.2	4.7	0.6	36	0.12	0.104
KYS 110531	Soil	1.4	34.2	19.7	76	0.1	26.4	13.8	566	3.00	21.8	1.1	6.5	3.4	11	0.2	3.8	0.3	33	0.09	0.065
KYS 110532	Soil	4.8	41.5	21.0	136	0.3	41.3	9.6	241	3.07	23.1	2.4	2.2	6.6	14	1.2	3.1	0.3	39	0.06	0.054
KYS 110534	Soil	2.2	49.6	21.4	88	0.6	26.5	6.4	246	2.96	32.5	1.0	12.9	1.1	13	0.1	3.4	0.4	29	0.04	0.083
KYS 110535	Soil	2.3	57.7	24.0	88	0.6	27.4	6.2	313	3.36	27.4	0.9	13.5	2.0	13	0.1	3.0	0.5	34	0.03	0.089
KYS 110536	Soil	2.1	62.8	26.5	95	0.6	30.7	6.6	288	3.90	21.5	1.0	19.6	3.4	15	0.1	2.4	0.5	35	<0.01	0.083
KYS 110537	Soil	2.6	73.4	29.1	98	0.7	30.0	7.3	345	4.22	22.5	0.9	17.7	2.3	16	<0.1	2.5	0.5	40	0.03	0.102
KYS 110538	Soil	2.3	60.8	24.0	75	0.7	25.3	5.3	235	3.87	18.3	1.0	10.2	2.0	15	0.1	2.2	0.4	43	0.02	0.097
KYS 110539	Soil	1.5	32.9	13.5	83	0.1	30.6	11.4	404	2.76	20.4	1.1	6.0	3.1	12	0.2	1.5	0.2	45	0.12	0.073
KYS 110540	Soil	1.6	39.7	11.2	92	0.2	28.0	8.5	294	2.66	20.8	1.4	13.1	5.3	13	0.3	2.3	0.2	47	0.14	0.080
KYS 110541	Soil	1.6	29.6	13.2	71	0.3	22.1	7.7	291	2.52	16.3	1.0	6.7	2.2	11	0.1	1.8	0.3	40	0.12	0.081
KYS 110542	Soil	2.0	27.2	14.7	57	0.2	17.1	4.6	169	2.63	23.2	0.9	8.9	0.9	9	0.1	2.1	0.3	41	0.06	0.064
KYS 110543	Soil	1.5	32.3	13.8	69	0.3	21.8	7.3	274	2.68	21.9	1.1	12.2	1.8	11	0.1	1.9	0.3	44	0.09	0.074
KYS 110544	Soil	2.1	58.1	24.8	96	0.5	29.0	5.7	187	3.17	79.3	0.9	4.7	5.4	13	<0.1	9.1	0.4	24	0.02	0.072
KYS 110545	Soil	2.6	43.5	20.8	66	0.9	18.1	3.6	153	2.77	37.8	0.9	15.4	0.7	8	<0.1	4.3	0.4	30	0.03	0.096
KYS 110546	Soil	3.5	43.0	23.3	79	0.6	19.9	4.9	256	3.21	28.5	1.0	12.9	2.0	9	0.2	3.1	0.5	36	0.04	0.098

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110516	Soil	20	22	0.40	183	0.016	<1	1.31	0.005	0.05	0.2	0.04	1.3	<0.1	<0.05	4	0.7	<0.2
KYS 110517	Soil	17	26	0.42	285	0.011	<1	1.20	0.006	0.05	0.1	0.06	1.0	<0.1	0.08	4	1.2	<0.2
KYS 110518	Soil	18	25	0.43	550	0.015	<1	1.19	0.005	0.05	0.1	0.05	1.7	<0.1	<0.05	3	0.7	<0.2
KYS 110519	Soil	15	21	0.31	83	0.026	2	1.09	0.006	0.05	0.2	0.06	2.1	<0.1	<0.05	4	0.9	<0.2
KYS 110520	Soil	11	15	0.15	69	0.010	<1	0.76	0.007	0.03	0.2	0.06	1.1	<0.1	0.07	3	0.9	<0.2
KYS 110521	Soil	13	18	0.22	76	0.020	<1	0.95	0.006	0.04	0.1	0.05	1.7	<0.1	<0.05	3	1.2	<0.2
KYS 110522	Soil	10	24	0.29	86	0.020	<1	1.17	0.004	0.03	0.2	0.04	1.1	<0.1	<0.05	4	1.4	<0.2
KYS 110523	Soil	16	25	0.44	157	0.031	1	1.44	0.006	0.05	0.2	0.05	2.6	<0.1	<0.05	4	0.8	<0.2
KYS 110524	Soil	22	45	0.75	156	0.011	<1	1.84	0.003	0.04	<0.1	0.04	2.4	<0.1	<0.05	5	<0.5	<0.2
KYS 110525	Soil	21	26	0.53	125	0.013	<1	1.50	0.003	0.04	0.1	0.04	1.8	<0.1	<0.05	4	0.7	<0.2
KYS 110526	Soil	23	20	0.35	112	0.011	<1	1.29	0.004	0.04	0.1	0.06	1.8	<0.1	<0.05	3	0.7	<0.2
KYS 110527	Soil	22	28	0.61	83	0.016	<1	1.55	0.004	0.04	0.1	0.04	1.4	<0.1	<0.05	5	1.0	<0.2
KYS 110528	Soil	16	24	0.43	91	0.019	<1	1.36	0.004	0.04	0.2	0.05	1.2	0.1	<0.05	5	0.6	<0.2
KYS 110529	Soil	21	24	0.50	127	0.020	<1	1.48	0.005	0.05	0.2	0.05	2.1	<0.1	<0.05	4	0.6	<0.2
KYS 110530	Soil	22	25	0.42	130	0.010	<1	1.41	0.005	0.04	<0.1	0.07	1.8	<0.1	<0.05	4	2.1	<0.2
KYS 110531	Soil	20	20	0.43	102	0.014	<1	1.24	0.004	0.04	0.2	0.04	1.3	<0.1	<0.05	4	0.7	<0.2
KYS 110532	Soil	19	18	0.30	124	0.014	<1	1.07	0.004	0.04	0.2	0.08	1.0	<0.1	<0.05	3	1.3	<0.2
KYS 110534	Soil	9	19	0.17	115	0.007	<1	1.01	0.005	0.03	<0.1	0.09	1.0	<0.1	<0.05	3	1.8	0.2
KYS 110535	Soil	9	24	0.27	101	0.008	<1	1.28	0.005	0.04	0.1	0.09	1.2	<0.1	<0.05	4	2.1	0.2
KYS 110536	Soil	9	26	0.32	86	0.004	2	1.48	0.004	0.03	<0.1	0.13	1.1	<0.1	<0.05	4	2.0	<0.2
KYS 110537	Soil	8	31	0.33	104	0.009	<1	1.77	0.005	0.04	0.1	0.12	1.4	<0.1	<0.05	4	3.0	0.3
KYS 110538	Soil	9	27	0.28	99	0.010	<1	1.36	0.005	0.04	<0.1	0.09	1.3	<0.1	<0.05	5	1.6	<0.2
KYS 110539	Soil	13	28	0.40	122	0.031	1	1.77	0.006	0.05	0.2	0.08	2.0	<0.1	<0.05	4	1.0	<0.2
KYS 110540	Soil	15	25	0.39	91	0.042	1	1.29	0.006	0.05	0.3	0.05	2.6	<0.1	<0.05	4	0.9	<0.2
KYS 110541	Soil	13	22	0.33	80	0.022	<1	1.22	0.004	0.04	0.2	0.07	1.5	<0.1	<0.05	4	1.0	<0.2
KYS 110542	Soil	12	24	0.28	90	0.014	<1	1.30	0.004	0.04	0.1	0.08	0.9	<0.1	<0.05	4	1.1	0.2
KYS 110543	Soil	14	25	0.38	104	0.024	<1	1.40	0.006	0.05	0.1	0.05	1.7	<0.1	<0.05	4	0.9	<0.2
KYS 110544	Soil	10	16	0.13	92	0.001	<1	0.84	0.006	0.03	<0.1	0.07	2.1	<0.1	<0.05	3	1.4	<0.2
KYS 110545	Soil	7	21	0.15	91	0.004	<1	0.93	0.007	0.03	<0.1	0.08	0.7	<0.1	<0.05	3	1.8	<0.2
KYS 110546	Soil	9	22	0.21	107	0.008	<1	1.16	0.004	0.04	0.1	0.12	1.2	<0.1	<0.05	4	2.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110547	Soil	2.4	48.8	24.3	61	0.8	19.0	3.1	187	3.31	45.4	1.0	14.5	2.1	9	0.1	2.7	0.5	37	0.02	0.085
KYS 110548	Soil	2.3	69.5	29.3	61	0.6	22.5	3.0	195	3.97	30.5	0.9	17.8	4.0	13	<0.1	2.7	0.5	41	0.01	0.096
KYS 110549	Soil	2.6	78.1	26.9	68	0.6	23.9	3.9	202	3.98	24.4	1.0	15.7	3.4	13	<0.1	2.3	0.5	46	0.02	0.091
KYS 110550	Soil	2.6	58.0	24.4	60	0.7	17.3	2.9	164	3.71	29.6	0.6	18.9	1.8	10	<0.1	3.0	0.5	38	0.01	0.080
KYS 110551	Soil	0.8	132.5	25.9	234	0.3	181.3	61.1	2920	4.67	95.4	2.9	8.8	9.6	14	1.3	12.8	0.4	6	0.36	0.079
KYS 110552	Soil	1.9	48.0	25.1	61	0.3	18.9	3.9	184	3.67	28.9	0.6	13.1	3.5	11	<0.1	2.9	0.4	28	0.02	0.075
KYS 110553	Soil	3.9	59.4	32.8	105	0.4	42.7	16.0	627	3.53	15.0	1.8	4.4	6.0	15	0.5	2.5	0.4	22	0.19	0.071
KYS 110554	Soil	35.3	40.0	25.5	165	1.5	28.7	4.3	175	3.58	54.2	3.1	9.7	1.2	22	0.7	7.7	0.4	66	0.04	0.124
KYS 110555	Soil	7.5	43.5	23.5	158	0.7	39.3	12.0	383	3.55	16.5	2.4	6.1	4.3	20	0.9	4.4	0.3	24	0.07	0.087
KYS 110556	Soil	19.2	46.3	26.0	203	1.4	40.1	6.3	363	3.00	86.4	3.7	5.8	4.4	38	3.4	19.5	0.3	58	0.19	0.138
KYS 110557	Soil	8.0	42.4	24.0	125	0.7	33.7	9.6	296	3.68	29.1	1.9	6.8	4.0	17	0.7	5.7	0.3	27	0.04	0.104
KYS 110558	Soil	6.5	71.0	25.5	185	0.8	43.9	7.9	301	3.96	55.3	2.3	10.7	3.4	15	0.4	8.1	0.4	31	0.02	0.102
KYS 110559	Soil	3.9	71.2	23.5	92	0.6	28.1	4.9	142	3.70	41.7	1.1	17.2	1.7	9	0.1	5.8	0.4	28	0.01	0.091
KYS 110560	Soil	2.9	110.7	20.0	70	0.8	20.4	3.3	540	5.39	36.1	1.2	35.5	2.1	16	<0.1	5.3	0.8	31	0.02	0.124
KYS 110561	Soil	1.9	27.7	13.5	53	0.4	18.5	5.4	204	2.93	13.7	0.7	12.8	2.9	7	<0.1	1.7	0.3	45	0.05	0.060
KYS 110562	Soil	2.2	27.2	66.5	29	0.9	8.2	1.8	90	2.45	1127	0.6	253.7	1.4	10	<0.1	4.3	0.5	27	0.02	0.063
KYS 110563	Soil	2.4	65.6	22.9	69	0.6	24.0	3.8	204	3.70	27.1	0.8	13.1	1.9	13	<0.1	3.0	0.4	35	0.02	0.086
KYS 110564	Soil	2.5	73.9	22.2	66	0.7	24.0	5.0	228	3.36	57.7	1.1	19.9	2.0	11	<0.1	2.7	0.4	38	0.02	0.070
KYS 110565	Soil	1.7	40.6	16.2	42	0.9	11.4	2.6	101	2.15	22.4	0.5	10.2	0.2	7	<0.1	1.3	0.3	33	0.02	0.065
KYS 110566	Soil	2.0	58.8	18.1	73	0.3	23.3	7.5	304	2.97	37.4	0.8	9.1	2.2	9	0.1	1.8	0.3	40	0.04	0.064
KYS 110567	Soil	2.3	30.6	18.5	49	0.6	15.7	3.9	123	2.65	71.2	0.8	12.3	1.0	10	0.1	2.9	0.3	42	0.05	0.072
KYS 110568	Soil	1.6	20.4	11.6	56	0.4	18.2	5.9	225	2.69	17.9	0.7	7.3	2.4	7	0.2	1.2	0.2	42	0.06	0.055
KYS 110572	Soil	1.2	23.7	9.8	48	0.2	23.6	8.3	229	2.56	18.0	0.6	6.8	4.0	8	0.2	1.1	0.2	45	0.07	0.052
KYS 110573	Soil	1.4	35.2	11.0	60	0.3	21.8	6.3	233	2.86	19.8	0.9	14.7	3.5	8	0.2	1.4	0.2	39	0.08	0.063
KYS 110574	Soil	1.4	23.1	11.1	45	0.3	14.9	4.1	154	2.30	15.7	0.5	6.5	1.2	7	0.1	1.0	0.2	39	0.05	0.042
KYS 110575	Soil	1.3	34.9	12.0	67	0.4	24.5	6.1	218	2.55	19.3	0.8	7.9	2.5	7	0.1	1.5	0.2	40	0.07	0.050
KYS 110576	Soil	1.1	28.8	11.8	79	0.2	32.6	11.7	550	2.37	35.3	1.2	2.4	4.3	9	0.4	1.8	0.2	18	0.15	0.056
KYS 110577	Soil	2.0	33.0	15.1	52	0.3	17.5	3.7	92	2.31	23.5	1.1	5.7	1.0	11	0.2	2.6	0.3	33	0.07	0.076
KYS 110578	Soil	3.3	32.0	17.2	45	0.5	15.6	4.3	161	2.48	27.3	1.0	10.3	0.5	13	0.1	3.3	0.3	40	0.06	0.074
KYS 110579	Soil	3.2	33.8	16.7	66	0.3	21.8	5.4	123	2.45	28.8	1.0	8.6	2.8	12	0.1	3.5	0.2	21	0.04	0.054

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110547	Soil	9	24	0.21	125	0.004	<1	1.25	0.006	0.04	<0.1	0.10	1.2	<0.1	0.06	4	2.2	0.3
KYS 110548	Soil	9	29	0.30	175	0.002	<1	1.52	0.008	0.05	<0.1	0.11	1.8	<0.1	0.07	5	2.6	<0.2
KYS 110549	Soil	8	28	0.29	197	0.004	<1	1.65	0.009	0.06	<0.1	0.13	1.5	<0.1	0.09	5	2.6	<0.2
KYS 110550	Soil	6	22	0.20	92	0.004	<1	1.07	0.006	0.03	<0.1	0.08	0.8	<0.1	<0.05	4	2.2	<0.2
KYS 110551	Soil	11	6	0.09	106	<0.001	<1	0.73	0.007	0.04	<0.1	0.03	3.7	<0.1	<0.05	<1	<0.5	<0.2
KYS 110552	Soil	7	23	0.19	91	0.002	<1	0.94	0.010	0.03	<0.1	0.08	1.2	<0.1	<0.05	3	1.9	0.3
KYS 110553	Soil	16	21	0.42	519	0.003	<1	1.08	0.005	0.04	<0.1	0.07	1.5	<0.1	<0.05	3	1.6	<0.2
KYS 110554	Soil	13	14	0.09	513	0.005	2	0.59	0.004	0.09	0.2	0.98	0.5	0.3	0.13	2	7.4	0.2
KYS 110555	Soil	18	18	0.29	1165	0.004	<1	0.84	0.003	0.05	<0.1	0.18	1.0	<0.1	0.05	2	3.9	<0.2
KYS 110556	Soil	7	9	0.04	484	0.002	4	0.42	0.006	0.11	0.1	0.43	1.4	0.3	0.22	1	5.8	<0.2
KYS 110557	Soil	18	26	0.34	1704	0.003	<1	0.96	0.004	0.05	<0.1	0.16	1.2	<0.1	0.06	3	3.1	<0.2
KYS 110558	Soil	10	15	0.12	106	0.001	<1	0.88	0.006	0.03	0.1	0.16	1.8	<0.1	<0.05	2	3.7	<0.2
KYS 110559	Soil	6	17	0.13	136	0.001	<1	0.81	0.005	0.03	<0.1	0.09	1.2	<0.1	<0.05	3	2.3	<0.2
KYS 110560	Soil	5	26	0.19	263	0.001	<1	1.23	0.006	0.05	<0.1	0.11	2.3	<0.1	0.09	4	2.6	<0.2
KYS 110561	Soil	9	27	0.23	87	0.019	<1	1.33	0.004	0.03	0.1	0.06	1.6	<0.1	<0.05	5	1.0	<0.2
KYS 110562	Soil	6	15	0.09	125	0.008	<1	0.81	0.008	0.04	0.1	0.16	1.2	<0.1	0.08	3	1.2	<0.2
KYS 110563	Soil	6	24	0.18	168	0.005	<1	1.33	0.007	0.04	<0.1	0.13	1.3	<0.1	<0.05	4	2.3	<0.2
KYS 110564	Soil	8	24	0.24	184	0.010	<1	1.36	0.005	0.05	0.1	0.10	1.9	<0.1	<0.05	4	1.6	<0.2
KYS 110565	Soil	7	15	0.09	119	0.011	<1	0.80	0.004	0.02	<0.1	0.06	0.3	<0.1	<0.05	4	0.8	<0.2
KYS 110566	Soil	9	23	0.23	139	0.007	<1	1.34	0.005	0.04	0.1	0.06	1.6	<0.1	<0.05	4	1.1	<0.2
KYS 110567	Soil	9	22	0.18	115	0.008	<1	1.16	0.004	0.04	0.1	0.09	1.0	<0.1	<0.05	4	1.0	<0.2
KYS 110568	Soil	10	26	0.29	114	0.017	3	1.48	0.004	0.04	0.2	0.06	1.5	<0.1	<0.05	4	0.9	<0.2
KYS 110572	Soil	11	26	0.33	124	0.022	<1	1.74	0.008	0.04	0.2	0.06	2.2	<0.1	<0.05	4	0.7	<0.2
KYS 110573	Soil	10	25	0.32	114	0.019	<1	1.48	0.004	0.04	0.2	0.07	1.9	<0.1	<0.05	4	0.9	<0.2
KYS 110574	Soil	10	20	0.21	103	0.010	<1	1.15	0.004	0.02	0.2	0.05	1.1	<0.1	<0.05	4	0.6	<0.2
KYS 110575	Soil	11	24	0.31	131	0.014	<1	1.36	0.002	0.04	0.2	0.06	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110576	Soil	12	19	0.31	118	0.007	<1	0.85	0.002	0.04	0.2	0.02	1.2	<0.1	<0.05	2	0.7	<0.2
KYS 110577	Soil	10	20	0.19	99	0.010	<1	1.03	0.004	0.03	0.1	0.09	1.0	<0.1	<0.05	3	1.3	<0.2
KYS 110578	Soil	8	19	0.17	165	0.006	<1	0.97	0.005	0.04	0.1	0.11	0.7	<0.1	<0.05	4	2.3	<0.2
KYS 110579	Soil	11	15	0.17	78	0.003	<1	0.78	0.003	0.04	<0.1	0.05	0.9	<0.1	<0.05	2	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110580	Soil	1.2	32.0	14.3	56	0.2	21.5	5.5	154	2.11	26.0	0.9	3.1	6.0	16	0.1	3.4	0.2	19	0.11	0.058
KYS 110581	Soil	1.1	43.8	23.0	82	0.2	35.2	12.2	541	3.19	33.5	1.4	4.0	5.8	19	0.2	2.6	0.2	12	0.43	0.049
KYS 110582	Soil	1.7	61.1	11.9	69	0.1	33.1	7.4	205	2.36	17.2	1.1	13.4	3.5	8	0.2	2.4	0.2	29	0.07	0.059
KYS 110583	Soil	1.3	24.5	11.3	56	0.2	19.0	5.2	147	2.32	15.8	0.9	4.7	1.3	8	0.2	1.3	0.2	41	0.07	0.058
KYS 110584	Soil	0.8	39.7	8.5	72	0.1	27.2	8.4	272	2.32	15.2	1.1	4.2	4.5	10	0.2	1.5	0.2	39	0.13	0.067
KYS 110585	Soil	0.7	37.0	10.0	69	<0.1	30.9	11.1	466	2.36	17.8	0.9	4.4	5.1	11	0.2	1.3	0.1	38	0.16	0.067
KYS 110586	Soil	1.2	41.5	17.9	72	0.2	29.9	12.8	511	2.72	30.5	0.9	5.3	3.7	8	0.2	1.4	0.2	29	0.09	0.062
KYS 110587	Soil	0.5	62.4	24.1	94	0.1	47.9	24.1	515	3.68	22.4	1.2	0.9	7.0	8	<0.1	0.9	0.4	10	0.19	0.051
KYS 110588	Soil	1.2	17.4	16.1	51	0.1	13.3	6.5	379	2.46	10.9	0.8	2.0	0.2	9	<0.1	0.6	0.2	40	0.10	0.056
KYS 110589	Soil	0.7	25.1	15.3	67	<0.1	24.9	11.2	503	2.86	13.1	1.0	5.3	1.6	11	<0.1	0.7	0.2	30	0.16	0.043
KYS 110590	Soil	1.0	18.6	13.8	71	0.1	16.8	10.0	648	2.24	10.3	0.7	0.9	0.3	20	0.2	0.5	0.2	30	0.39	0.060
KYS 110591	Soil	0.9	28.4	17.7	68	<0.1	22.9	11.3	363	2.84	11.8	1.0	5.6	2.0	7	0.2	0.7	0.2	34	0.06	0.044
KYS 110592	Soil	0.9	29.7	21.6	72	<0.1	23.1	12.2	471	3.08	11.9	1.0	2.3	3.3	7	0.1	0.5	0.2	28	0.07	0.049
KYS 110593	Soil	0.8	45.5	25.2	80	<0.1	29.9	12.9	400	2.87	9.6	1.4	14.4	4.4	8	0.2	0.6	0.2	22	0.10	0.062
KYS 110594	Soil	1.1	27.5	18.2	67	<0.1	20.0	8.8	316	2.87	11.3	1.1	2.4	1.8	7	0.1	0.6	0.2	36	0.07	0.044
KYS 110595	Soil	0.8	40.2	20.4	80	<0.1	26.8	10.7	366	2.97	11.1	1.5	2.5	5.9	7	<0.1	0.6	0.2	25	0.07	0.050
KYS 110596	Soil	1.1	27.9	16.1	71	<0.1	22.2	8.7	297	2.69	11.4	1.2	3.2	3.7	8	0.2	0.6	0.2	36	0.10	0.053
KYS 110597	Soil	0.9	20.3	14.6	57	<0.1	17.8	7.6	343	2.65	9.9	0.7	1.5	3.5	7	0.1	0.5	0.2	30	0.09	0.056
KYS 110598	Soil	0.9	28.3	18.4	66	<0.1	20.7	8.2	269	2.78	10.0	1.1	<0.5	4.2	9	<0.1	0.6	0.3	28	0.09	0.061
KYS 110599	Soil	0.7	28.8	18.4	60	<0.1	18.6	8.6	238	2.54	8.9	1.1	3.0	5.7	9	0.1	0.7	0.2	27	0.09	0.060
KYS 110600	Soil	0.9	17.3	18.3	49	<0.1	12.9	5.4	234	2.49	9.9	0.6	<0.5	1.6	7	<0.1	0.5	0.3	30	0.05	0.052
KYS 110601	Soil	1.0	30.0	18.8	67	<0.1	19.6	8.0	309	2.80	10.7	1.2	4.0	4.5	10	<0.1	0.8	0.3	32	0.10	0.063
KYS 110602	Soil	0.8	37.2	12.8	70	<0.1	25.9	9.3	349	2.60	11.0	1.3	2.1	4.9	10	0.2	1.0	0.2	33	0.10	0.056
KYS 110603	Soil	1.0	30.2	15.5	77	<0.1	30.1	10.3	396	2.61	10.4	1.1	4.5	3.6	13	0.2	0.9	0.2	35	0.14	0.076
KYS 110604	Soil	0.9	32.8	12.0	92	<0.1	33.6	11.6	448	2.61	10.1	1.2	8.0	6.5	12	0.2	0.9	0.2	30	0.15	0.071
KYS 110605	Soil	2.1	51.6	10.1	78	<0.1	24.5	6.3	269	2.24	9.5	2.1	<0.5	6.5	19	0.3	1.6	0.2	37	0.17	0.085
KYS 110606	Soil	3.3	26.1	13.2	83	0.1	19.3	8.5	370	2.79	16.1	2.5	1.0	3.4	15	0.2	1.7	0.3	51	0.10	0.102
KYS 110607	Soil	5.1	46.4	16.3	92	0.3	21.6	8.6	367	2.71	23.9	3.2	3.1	7.3	20	0.3	3.4	0.3	39	0.08	0.081
KYS 110608	Soil	0.8	27.6	58.7	66	<0.1	35.2	15.8	698	3.70	47.7	0.7	<0.5	6.2	17	0.5	2.2	0.3	23	0.19	0.059
KYS 110609	Soil	0.8	63.7	45.6	181	0.3	122.4	57.4	2416	3.21	28.8	1.5	1.3	8.7	41	1.0	1.7	0.3	18	0.62	0.073

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110580	Soil	13	15	0.15	70	0.006	<1	0.83	0.004	0.03	<0.1	0.04	1.3	<0.1	<0.05	3	0.6	<0.2
KYS 110581	Soil	14	13	0.21	203	0.003	<1	0.61	0.004	0.06	<0.1	0.04	2.0	<0.1	<0.05	2	0.7	0.3
KYS 110582	Soil	11	17	0.21	75	0.014	<1	1.00	0.003	0.02	0.1	0.07	1.6	<0.1	<0.05	3	0.9	<0.2
KYS 110583	Soil	11	23	0.29	95	0.017	<1	1.34	0.004	0.04	0.2	0.06	1.7	<0.1	<0.05	4	0.6	<0.2
KYS 110584	Soil	13	22	0.35	98	0.037	<1	1.46	0.006	0.06	0.2	0.05	3.1	<0.1	<0.05	4	0.6	<0.2
KYS 110585	Soil	14	24	0.37	106	0.037	<1	1.34	0.005	0.06	0.2	0.04	2.4	<0.1	<0.05	3	<0.5	<0.2
KYS 110586	Soil	17	21	0.32	64	0.012	<1	1.15	0.003	0.04	<0.1	0.04	1.4	<0.1	<0.05	4	0.5	<0.2
KYS 110587	Soil	17	20	0.82	17	0.003	<1	1.69	0.003	0.05	<0.1	0.03	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 110588	Soil	10	21	0.23	80	0.008	<1	1.10	0.003	0.05	0.1	0.03	0.3	<0.1	<0.05	5	<0.5	<0.2
KYS 110589	Soil	16	21	0.40	81	0.014	<1	1.34	0.004	0.04	0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110590	Soil	10	19	0.32	102	0.009	<1	1.07	0.004	0.05	0.1	0.03	0.4	<0.1	<0.05	4	<0.5	<0.2
KYS 110591	Soil	17	23	0.51	86	0.016	<1	1.57	0.004	0.04	0.2	0.03	1.4	<0.1	<0.05	4	0.7	<0.2
KYS 110592	Soil	18	21	0.53	51	0.017	<1	1.37	0.003	0.04	0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110593	Soil	21	18	0.49	50	0.016	<1	1.26	0.004	0.05	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 110594	Soil	16	24	0.40	73	0.016	<1	1.50	0.003	0.04	0.2	0.04	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 110595	Soil	20	21	0.53	63	0.016	<1	1.44	0.004	0.05	<0.1	0.03	1.9	<0.1	<0.05	4	<0.5	0.2
KYS 110596	Soil	17	26	0.40	77	0.020	<1	1.53	0.005	0.05	0.2	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110597	Soil	17	20	0.37	44	0.021	<1	1.15	0.004	0.04	0.1	0.02	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110598	Soil	17	22	0.45	60	0.025	1	1.37	0.005	0.03	0.1	0.02	1.7	<0.1	<0.05	4	0.6	<0.2
KYS 110599	Soil	17	22	0.46	69	0.031	2	1.48	0.006	0.04	0.2	0.02	2.0	<0.1	<0.05	4	0.7	<0.2
KYS 110600	Soil	18	18	0.37	39	0.020	1	1.11	0.004	0.03	0.2	0.03	0.9	<0.1	<0.05	4	0.5	<0.2
KYS 110601	Soil	18	24	0.45	68	0.026	1	1.36	0.007	0.04	0.1	0.02	1.8	<0.1	<0.05	4	0.6	<0.2
KYS 110602	Soil	19	23	0.44	90	0.039	2	1.42	0.006	0.05	0.2	0.02	2.6	<0.1	<0.05	4	<0.5	<0.2
KYS 110603	Soil	18	25	0.46	77	0.037	1	1.47	0.005	0.04	0.1	0.03	2.1	<0.1	<0.05	4	<0.5	<0.2
KYS 110604	Soil	18	23	0.46	83	0.035	1	1.40	0.006	0.04	0.2	0.03	2.3	<0.1	<0.05	4	<0.5	<0.2
KYS 110605	Soil	22	22	0.44	137	0.041	2	1.29	0.007	0.06	0.2	0.05	3.2	<0.1	<0.05	4	0.7	<0.2
KYS 110606	Soil	20	30	0.49	149	0.028	1	1.80	0.008	0.05	0.2	0.07	3.2	0.1	<0.05	5	1.1	<0.2
KYS 110607	Soil	28	21	0.40	115	0.019	1	1.34	0.005	0.05	0.1	0.13	2.3	<0.1	<0.05	4	1.2	<0.2
KYS 110608	Soil	18	22	0.33	123	0.014	1	1.18	0.005	0.07	0.1	0.02	1.7	<0.1	<0.05	3	0.5	<0.2
KYS 110609	Soil	30	18	0.38	168	0.011	1	1.21	0.007	0.13	<0.1	0.06	2.8	<0.1	<0.05	3	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110610	Soil	1.1	47.9	22.0	78	0.2	36.7	13.3	546	3.38	16.0	1.5	5.5	5.7	10	<0.1	1.2	0.3	25	0.09	0.060
KYS 110611	Soil	0.8	35.1	17.2	75	<0.1	36.1	12.6	469	2.82	22.0	0.9	7.3	6.5	15	0.2	1.4	0.3	30	0.16	0.055
KYS 110612	Soil	1.1	52.0	18.2	86	0.2	45.5	14.6	602	3.01	22.4	1.1	6.2	6.3	11	0.1	2.4	0.3	29	0.10	0.056
KYS 110613	Soil	1.2	47.1	18.0	84	0.2	45.9	14.7	589	2.93	21.8	1.1	2.0	6.3	11	0.2	2.5	0.3	30	0.10	0.058
KYS 110614	Soil	1.1	57.3	23.1	89	0.2	58.4	15.3	598	3.08	15.5	1.1	7.8	7.1	12	0.1	1.8	0.3	29	0.12	0.061
KYS 110615	Soil	2.6	44.9	23.8	68	0.5	19.1	6.0	365	3.69	86.2	1.3	13.5	0.5	10	<0.1	6.1	0.4	41	0.06	0.110
KYS 110616	Soil	1.1	50.4	29.3	119	0.2	51.7	15.0	1192	3.23	50.4	1.3	7.9	8.9	13	0.5	4.1	0.4	27	0.14	0.075
KYS 110617	Soil	2.1	48.3	20.6	72	0.3	21.6	6.9	307	3.56	30.2	0.9	10.7	1.5	10	<0.1	4.1	0.3	38	0.04	0.084
KYS 110618	Soil	1.0	53.1	19.3	116	0.3	52.0	14.0	606	2.95	68.8	1.3	10.0	5.7	11	0.3	3.4	0.3	30	0.10	0.074
KYS 110619	Soil	1.0	47.1	30.0	96	0.2	42.7	18.4	755	3.68	96.2	1.7	7.0	5.3	12	0.2	3.7	0.4	37	0.10	0.098
KYS 110620	Soil	1.8	55.2	24.5	78	0.5	28.5	8.1	329	3.64	149.3	1.1	14.8	1.3	22	0.1	5.0	0.4	39	0.17	0.079
KYS 110621	Soil	1.4	47.8	17.4	106	0.3	47.2	16.6	860	3.00	33.2	1.6	2.5	2.1	16	0.6	2.5	0.3	26	0.17	0.083
KYS 110622	Soil	1.5	34.9	9.8	74	0.3	22.6	6.7	244	2.35	17.5	1.3	3.3	5.6	20	0.5	2.1	0.2	39	0.21	0.113
KYS 110623	Soil	2.0	26.3	16.7	65	0.2	18.1	7.5	373	2.93	20.5	1.3	5.5	0.8	14	0.3	1.8	0.3	50	0.07	0.096
KYS 110624	Soil	2.0	39.9	19.2	96	0.3	31.1	10.4	307	3.16	37.7	1.4	5.6	1.1	10	0.2	2.5	0.4	38	0.05	0.082
KYS 110625	Soil	0.3	33.5	23.0	80	<0.1	34.1	16.2	593	3.32	8.0	0.9	<0.5	13.0	23	<0.1	0.2	0.2	13	0.18	0.044
KYS 110626	Soil	1.2	89.8	187.5	95	1.2	174.5	78.6	2455	5.05	205.0	1.8	3.5	10.7	81	0.5	11.8	0.3	19	0.52	0.078
KYS 110627	Soil	1.1	38.3	25.3	70	<0.1	43.0	13.8	423	4.11	15.6	1.0	0.7	13.6	11	<0.1	0.6	0.3	27	0.09	0.039
KYS 110628	Soil	0.6	19.7	34.2	60	0.1	26.4	13.9	455	2.88	11.6	0.7	<0.5	1.8	7	<0.1	0.6	0.2	20	0.04	0.053
KYS 110629	Soil	0.8	26.2	57.5	82	0.1	24.4	10.9	307	3.38	21.3	0.9	<0.5	7.6	7	0.1	1.6	0.3	28	0.06	0.041
KYS 110630	Soil	1.7	113.6	16.8	92	0.1	39.8	14.8	1664	3.04	18.1	1.0	11.0	3.6	15	0.2	3.9	0.2	45	0.11	0.088
KYS 110631	Soil	1.8	75.0	15.1	71	<0.1	26.2	9.0	888	3.16	17.1	0.8	7.4	0.5	12	0.1	2.1	0.3	57	0.08	0.100
KYS 110632	Soil	1.8	157.0	18.8	80	0.1	38.3	16.5	2351	3.04	16.7	1.0	7.1	0.6	11	0.1	1.3	0.3	49	0.06	0.089
KYS 110633	Soil	2.1	131.4	20.8	91	0.2	40.2	20.4	3338	3.80	19.7	1.2	18.7	1.3	14	0.2	1.3	0.4	54	0.07	0.105
KYS 110634	Soil	1.6	109.8	15.7	72	0.1	32.2	15.8	2361	2.93	15.9	0.9	18.1	1.0	11	0.2	1.1	0.3	41	0.06	0.090
KYS 110635	Soil	1.3	144.9	18.2	87	0.1	48.8	21.3	3037	2.69	15.1	1.0	14.6	2.6	16	0.1	1.7	0.3	35	0.08	0.079
KYS 110636	Soil	1.4	114.7	18.2	98	0.1	46.6	16.5	2742	3.08	14.2	0.9	32.3	2.3	17	0.2	1.2	0.3	38	0.09	0.086
KYS 110637	Soil	1.5	59.5	15.1	72	0.2	25.6	11.0	1678	2.66	11.3	0.8	35.6	0.5	11	<0.1	1.2	0.3	39	0.05	0.087
KYS 110638	Soil	1.5	75.8	16.0	93	0.1	36.4	14.2	1928	3.04	13.3	1.0	10.8	1.2	12	0.2	1.2	0.3	44	0.06	0.068
KYS 110639	Soil	1.5	63.7	22.3	97	0.2	44.9	16.5	2138	3.32	37.3	1.2	15.7	1.5	15	0.3	2.4	0.3	37	0.13	0.084

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110610	Soil	19	28	0.49	121	0.009	<1	1.30	0.005	0.06	0.1	0.05	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110611	Soil	19	28	0.43	98	0.023	1	1.12	0.006	0.06	<0.1	0.03	2.0	<0.1	<0.05	3	0.7	<0.2
KYS 110612	Soil	17	30	0.40	92	0.017	1	1.15	0.006	0.06	0.1	0.03	2.3	<0.1	<0.05	3	<0.5	<0.2
KYS 110613	Soil	18	28	0.39	91	0.017	<1	1.16	0.005	0.06	0.1	0.04	2.5	<0.1	<0.05	3	0.8	<0.2
KYS 110614	Soil	22	45	0.48	113	0.017	1	1.21	0.006	0.07	0.1	0.05	2.5	<0.1	<0.05	4	0.9	<0.2
KYS 110615	Soil	11	24	0.31	238	0.013	1	1.49	0.007	0.04	0.2	0.04	1.2	0.1	<0.05	5	2.0	<0.2
KYS 110616	Soil	24	19	0.35	191	0.025	1	1.05	0.007	0.07	0.2	0.05	3.1	<0.1	<0.05	3	0.6	<0.2
KYS 110617	Soil	12	26	0.26	108	0.014	1	1.21	0.007	0.04	0.1	0.07	1.4	<0.1	<0.05	4	1.3	0.3
KYS 110618	Soil	22	22	0.32	120	0.022	1	1.20	0.007	0.06	0.1	0.05	2.8	<0.1	<0.05	3	0.5	<0.2
KYS 110619	Soil	23	25	0.39	122	0.030	1	1.44	0.008	0.07	0.2	0.03	3.6	<0.1	<0.05	4	0.8	<0.2
KYS 110620	Soil	13	25	0.27	175	0.009	1	1.22	0.010	0.05	0.1	0.05	1.5	<0.1	<0.05	4	1.4	<0.2
KYS 110621	Soil	13	25	0.30	113	0.015	1	0.98	0.005	0.05	<0.1	0.03	1.8	<0.1	<0.05	3	0.8	<0.2
KYS 110622	Soil	16	23	0.31	104	0.049	1	0.89	0.010	0.05	0.3	0.04	2.7	<0.1	<0.05	3	0.8	<0.2
KYS 110623	Soil	12	32	0.30	79	0.022	<1	1.74	0.006	0.05	0.2	0.07	1.3	<0.1	<0.05	6	0.9	<0.2
KYS 110624	Soil	14	25	0.25	82	0.017	<1	1.37	0.006	0.04	0.1	0.05	1.5	<0.1	<0.05	4	1.1	<0.2
KYS 110625	Soil	18	24	0.59	75	0.005	<1	1.37	0.004	0.09	<0.1	<0.01	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110626	Soil	22	70	0.65	209	0.005	2	1.91	0.005	0.10	<0.1	0.12	6.0	<0.1	<0.05	3	0.6	<0.2
KYS 110627	Soil	35	51	0.90	59	0.007	1	1.81	0.004	0.08	<0.1	0.02	1.6	<0.1	<0.05	6	<0.5	<0.2
KYS 110628	Soil	23	31	0.52	62	0.006	1	1.53	0.004	0.06	<0.1	<0.01	0.8	0.1	<0.05	5	<0.5	<0.2
KYS 110629	Soil	27	22	0.31	55	0.014	<1	1.36	0.004	0.08	0.1	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 110630	Soil	23	27	0.51	113	0.030	1	1.51	0.006	0.04	0.1	0.07	2.6	<0.1	<0.05	5	0.6	<0.2
KYS 110631	Soil	19	29	0.35	91	0.024	1	1.24	0.006	0.05	0.1	0.08	1.1	<0.1	0.07	6	0.7	<0.2
KYS 110632	Soil	18	29	0.43	117	0.018	1	1.48	0.005	0.05	0.1	0.08	1.1	<0.1	<0.05	5	0.9	<0.2
KYS 110633	Soil	19	32	0.50	140	0.020	1	1.76	0.006	0.05	0.2	0.13	1.5	<0.1	0.06	6	1.3	0.2
KYS 110634	Soil	11	24	0.40	108	0.014	2	1.47	0.005	0.04	0.2	0.10	1.0	<0.1	0.08	5	0.5	<0.2
KYS 110635	Soil	16	20	0.50	115	0.015	2	1.32	0.004	0.04	0.2	0.09	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 110636	Soil	16	24	0.59	133	0.012	2	1.58	0.004	0.04	0.1	0.09	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 110637	Soil	13	23	0.36	105	0.010	<1	1.21	0.005	0.04	0.1	0.06	0.6	<0.1	<0.05	4	0.5	<0.2
KYS 110638	Soil	15	27	0.52	123	0.014	1	1.63	0.004	0.04	0.1	0.08	1.1	<0.1	<0.05	5	0.8	<0.2
KYS 110639	Soil	17	24	0.48	170	0.013	1	1.60	0.004	0.04	<0.1	0.08	1.4	<0.1	<0.05	4	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110640	Soil	1.0	51.4	11.8	75	0.2	29.4	12.3	1228	2.36	17.9	1.0	9.9	1.8	15	0.4	1.3	0.2	34	0.14	0.083
KYS 110641	Soil	1.2	45.7	13.4	78	0.2	29.6	11.5	1014	2.69	17.5	1.2	9.4	0.7	11	0.2	1.9	0.2	39	0.13	0.067
KYS 110642	Soil	1.6	59.8	18.4	115	0.3	43.7	14.3	1052	3.10	29.0	2.1	10.3	1.8	14	0.2	43.9	0.3	31	0.11	0.068
KYS 110643	Soil	1.5	50.9	20.2	91	0.2	38.1	16.8	950	2.80	49.9	1.4	8.7	2.9	12	0.2	4.8	0.2	26	0.05	0.051
KYS 110644	Soil	1.2	76.1	26.5	88	0.2	68.7	27.6	1236	3.89	185.3	1.8	8.4	9.0	11	0.2	3.2	0.5	20	0.15	0.070
KYS 110645	Soil	1.1	37.3	13.5	69	<0.1	32.7	11.3	659	2.51	23.0	0.9	6.3	2.3	12	0.2	2.4	0.2	29	0.12	0.044
KYS 110646	Soil	1.3	26.1	18.3	70	<0.1	21.1	10.5	474	2.95	26.8	1.0	4.9	1.9	6	0.2	1.3	0.3	31	0.05	0.047
KYS 110647	Soil	0.8	29.0	14.8	74	0.1	26.5	10.6	461	2.69	51.6	1.5	5.6	3.9	21	0.2	1.5	0.2	21	0.33	0.074
KYS 110648	Soil	3.3	62.3	21.6	154	0.8	38.0	8.6	229	2.87	22.8	2.2	4.7	5.5	18	1.5	8.1	0.3	24	0.03	0.060
KYS 110649	Soil	1.5	98.2	19.7	149	0.4	77.9	22.0	2611	2.92	14.6	1.2	29.2	5.1	18	0.3	1.2	0.3	34	0.12	0.081
KYS 110650	Soil	2.3	69.7	20.5	147	0.3	70.5	17.3	1623	3.48	19.1	1.2	15.2	5.0	23	0.5	4.0	0.3	27	0.10	0.071
KYS 110651	Soil	2.0	68.5	20.3	135	0.3	54.2	13.9	1101	3.47	18.6	1.3	10.6	3.4	22	0.2	3.6	0.3	28	0.09	0.079
KYS 110652	Soil	1.9	61.9	17.7	114	0.3	47.6	12.3	1131	3.04	16.1	1.1	22.9	2.4	22	0.2	2.3	0.3	30	0.09	0.071
KYS 110653	Soil	3.1	66.4	23.4	114	0.5	44.1	14.2	1382	3.50	19.7	1.4	11.7	1.7	22	0.3	2.4	0.3	40	0.07	0.088
KYS 110654	Soil	1.7	49.3	15.2	68	0.3	24.5	9.5	964	2.97	14.5	0.9	10.6	0.7	10	0.2	1.2	0.3	48	0.06	0.066
KYS 110655	Soil	2.4	67.5	17.8	93	0.3	36.1	14.1	1587	3.00	21.1	1.2	16.3	1.1	17	0.3	2.1	0.3	45	0.08	0.086
KYS 110656	Soil	2.5	44.4	13.4	70	0.3	26.7	9.0	1081	2.65	55.3	1.2	15.3	0.5	11	0.1	9.9	0.3	48	0.04	0.064
KYS 110657	Soil	1.2	62.0	11.2	82	0.2	34.4	11.4	1082	2.31	19.2	0.9	38.4	3.8	11	0.3	3.7	0.2	31	0.07	0.049
KYS 110658	Soil	1.3	49.1	13.1	79	0.1	30.6	10.2	739	2.85	30.5	1.2	14.3	1.7	8	0.1	3.8	0.3	42	0.05	0.052
KYS 110659	Soil	1.9	38.0	16.5	74	0.1	31.5	10.7	595	2.75	100.5	1.4	4.7	1.6	19	0.1	2.2	0.3	30	0.25	0.110
KYS 110660	Soil	1.0	26.7	16.7	67	<0.1	23.0	10.6	624	2.98	19.2	0.9	7.7	1.5	7	0.1	1.2	0.2	32	0.04	0.047
KYS 110661	Soil	1.2	24.2	14.1	56	<0.1	16.8	6.3	355	2.34	43.5	0.7	17.0	0.4	8	0.2	1.7	0.3	36	0.06	0.046
KYS 110662	Soil	1.3	20.5	19.9	63	<0.1	19.5	9.3	370	3.37	30.8	0.8	2.7	1.5	7	0.1	1.4	0.3	36	0.05	0.046
KYS 110663	Soil	1.4	32.7	18.7	75	0.1	23.2	10.7	611	2.80	110.4	1.4	5.6	1.5	17	0.2	3.6	0.3	27	0.23	0.088
KYS 110664	Soil	0.7	25.7	15.8	78	<0.1	26.5	9.9	420	2.74	298.6	0.9	42.4	3.3	11	0.1	6.2	0.3	31	0.15	0.059
KYS 110665	Soil	0.6	24.0	20.0	78	0.1	25.6	10.0	402	2.79	114.1	0.7	18.4	4.0	11	0.2	11.4	0.3	28	0.15	0.059
KYS 110666	Soil	0.8	25.1	15.9	75	<0.1	25.0	10.2	423	2.74	20.8	1.0	4.6	3.1	11	0.2	7.7	0.3	30	0.12	0.060
KYS 110667	Soil	2.0	52.5	27.6	95	0.1	36.2	16.5	750	3.46	103.2	1.8	31.0	5.7	13	0.3	5.4	0.4	28	0.15	0.078
KYS 110668	Soil	1.4	52.1	26.9	95	0.2	34.2	17.0	833	3.32	71.8	1.3	8.4	6.6	19	0.4	8.2	0.3	20	0.38	0.081
KYS 110669	Soil	1.3	54.8	34.9	95	0.1	48.2	24.5	1169	3.24	42.2	1.5	2.9	6.4	12	0.2	15.3	0.4	17	0.12	0.077

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110640	Soil	13	22	0.35	90	0.025	<1	0.87	0.006	0.04	0.2	0.04	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 110641	Soil	13	26	0.41	123	0.013	<1	1.31	0.004	0.05	0.2	0.07	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110642	Soil	15	23	0.40	107	0.011	<1	1.39	0.014	0.04	0.1	0.07	1.3	<0.1	<0.05	4	0.6	<0.2
KYS 110643	Soil	14	19	0.36	119	0.016	1	1.08	0.010	0.05	0.1	0.08	1.4	<0.1	0.06	3	0.8	<0.2
KYS 110644	Soil	18	19	0.61	84	0.011	<1	1.12	0.004	0.05	0.1	0.05	2.5	<0.1	<0.05	3	<0.5	<0.2
KYS 110645	Soil	14	20	0.40	89	0.018	<1	0.98	0.006	0.04	0.2	0.04	1.2	<0.1	<0.05	3	0.5	<0.2
KYS 110646	Soil	15	22	0.37	75	0.014	<1	1.29	0.006	0.05	0.1	0.02	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110647	Soil	15	20	0.47	100	0.010	1	1.09	0.005	0.05	<0.1	0.04	2.0	<0.1	<0.05	3	<0.5	<0.2
KYS 110648	Soil	11	7	0.08	3739	0.011	4	0.97	0.004	0.09	<0.1	0.11	1.8	0.2	0.07	1	3.4	0.3
KYS 110649	Soil	18	25	0.49	131	0.020	<1	1.28	0.005	0.04	0.1	0.10	1.8	<0.1	<0.05	3	0.9	<0.2
KYS 110650	Soil	17	37	0.49	155	0.008	<1	1.11	0.005	0.04	<0.1	0.09	1.7	<0.1	<0.05	3	1.1	<0.2
KYS 110651	Soil	18	32	0.50	175	0.005	<1	1.32	0.005	0.05	<0.1	0.08	1.4	<0.1	0.06	3	0.9	<0.2
KYS 110652	Soil	17	29	0.49	145	0.007	<1	1.22	0.008	0.05	0.1	0.07	1.2	<0.1	0.07	3	0.8	<0.2
KYS 110653	Soil	18	31	0.42	170	0.011	<1	1.32	0.010	0.06	0.2	0.11	1.4	<0.1	0.08	4	1.2	<0.2
KYS 110654	Soil	13	28	0.37	122	0.023	1	1.30	0.006	0.05	0.2	0.07	1.1	<0.1	0.07	5	0.7	<0.2
KYS 110655	Soil	15	29	0.43	251	0.022	<1	1.42	0.005	0.05	0.2	0.14	1.3	<0.1	0.08	4	0.9	0.2
KYS 110656	Soil	15	25	0.24	124	0.016	<1	1.04	0.004	0.05	0.1	0.10	0.9	<0.1	0.08	4	0.9	<0.2
KYS 110657	Soil	16	19	0.34	77	0.031	<1	0.97	0.005	0.04	0.2	0.05	1.4	<0.1	0.07	3	0.6	<0.2
KYS 110658	Soil	16	28	0.41	102	0.026	<1	1.42	0.004	0.03	0.2	0.06	1.7	<0.1	0.07	4	0.7	<0.2
KYS 110659	Soil	22	20	0.41	90	0.010	<1	1.16	0.002	0.04	0.1	0.04	1.0	<0.1	0.07	3	<0.5	<0.2
KYS 110660	Soil	16	24	0.38	108	0.015	<1	1.37	0.007	0.05	0.2	0.05	1.3	<0.1	0.07	4	<0.5	<0.2
KYS 110661	Soil	14	22	0.26	94	0.016	<1	1.09	0.006	0.04	0.1	0.04	0.7	<0.1	0.08	4	<0.5	<0.2
KYS 110662	Soil	13	24	0.39	82	0.018	4	1.39	0.004	0.05	0.1	0.03	1.1	0.1	<0.05	5	0.6	<0.2
KYS 110663	Soil	16	24	0.42	182	0.008	<1	1.49	0.006	0.06	0.1	0.03	1.0	0.1	0.11	4	<0.5	<0.2
KYS 110664	Soil	21	24	0.48	142	0.013	<1	1.52	0.005	0.05	0.1	0.03	1.7	<0.1	0.06	4	<0.5	<0.2
KYS 110665	Soil	19	24	0.54	169	0.012	<1	1.50	0.006	0.04	0.2	0.03	1.9	<0.1	0.06	4	<0.5	<0.2
KYS 110666	Soil	22	24	0.49	140	0.015	<1	1.52	0.005	0.04	0.2	0.02	1.8	<0.1	0.06	4	<0.5	<0.2
KYS 110667	Soil	25	22	0.54	123	0.014	<1	1.42	0.005	0.05	0.1	0.04	1.7	<0.1	0.06	4	0.5	<0.2
KYS 110668	Soil	20	18	0.59	89	0.012	<1	1.14	0.007	0.05	<0.1	0.03	1.7	<0.1	0.07	3	<0.5	<0.2
KYS 110669	Soil	24	16	0.42	91	0.011	<1	1.09	0.003	0.05	<0.1	0.03	1.3	<0.1	0.08	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110670	Soil		1.1	42.1	15.0	77	0.2	32.9	13.6	518	2.65	16.7	1.1	2.6	6.8	17	0.2	4.4	0.3	33	0.24	0.096
KYS 110671	Soil		1.1	18.8	15.2	80	<0.1	19.7	8.8	877	2.56	161.9	0.9	2.7	1.4	4	0.1	35.9	0.2	7	0.06	0.048
KYS 110672	Soil		1.5	16.3	20.0	44	<0.1	16.0	7.2	356	3.05	17.1	0.6	1.2	4.2	6	<0.1	6.0	0.3	50	0.05	0.031
KYS 110673	Soil		0.7	36.2	45.3	117	0.2	62.2	35.3	1407	4.83	18.0	2.1	0.7	14.8	9	0.2	36.6	0.3	6	0.07	0.080
KYS 110674	Soil		0.7	36.6	46.7	115	0.2	64.7	35.3	1423	4.96	16.6	2.2	1.4	16.7	9	0.1	37.8	0.3	6	0.08	0.083
KYS 110675	Soil		4.4	29.3	20.4	62	0.2	28.6	10.3	2605	2.93	63.3	0.5	10.5	1.3	100	0.4	35.7	0.3	7	11.66	0.158
KYS 110676	Soil		1.4	52.0	18.4	89	0.2	32.9	11.6	1075	3.08	17.1	1.1	16.1	1.5	12	0.2	2.0	0.3	40	0.11	0.071
KYS 110677	Soil		1.4	56.9	22.5	89	0.2	33.8	12.7	709	3.27	25.0	1.4	6.1	2.2	10	0.2	2.2	0.3	30	0.08	0.078
KYS 110678	Soil		1.2	52.3	21.6	89	0.2	36.9	12.7	748	3.02	39.2	1.4	8.4	5.8	11	0.2	4.4	0.3	31	0.09	0.061
KYS 110679	Soil		1.3	44.6	19.6	87	0.3	34.0	11.9	694	3.11	57.2	1.5	13.6	4.4	12	0.3	5.6	0.3	33	0.12	0.073
KYS 110680	Soil		1.4	37.8	21.7	83	0.2	31.6	12.0	925	3.05	25.2	1.4	5.4	5.8	11	0.2	4.1	0.2	26	0.10	0.070
KYS 110681	Soil		1.6	38.7	21.4	76	0.3	26.8	9.2	474	3.04	23.0	1.1	11.0	2.7	12	0.2	2.8	0.4	39	0.07	0.076
KYS 110682	Soil		1.9	16.7	9.6	68	1.4	24.9	8.5	482	4.26	7783	2.3	299.5	7.4	82	0.5	29.6	0.3	6	0.18	0.026
KYS 110683	Soil		1.0	34.4	21.5	74	<0.1	38.3	16.8	475	3.59	73.8	0.9	4.0	8.8	6	<0.1	2.8	0.3	24	0.04	0.031
KYS 110684	Soil		1.4	37.4	30.1	94	0.1	40.3	15.1	424	3.97	129.5	1.4	15.8	10.6	17	0.1	3.0	0.4	16	0.18	0.038
KYS 110685	Soil		0.9	57.0	31.6	95	0.2	45.1	21.2	914	4.88	45.9	0.9	14.5	12.2	14	<0.1	1.4	0.6	6	0.21	0.042
KYS 110686	Soil		1.6	32.9	17.6	66	0.3	25.9	8.1	201	3.06	34.3	0.6	4.4	2.4	8	0.2	2.2	0.3	41	0.05	0.041
KYS 110687	Soil		1.4	27.2	21.2	50	0.2	19.5	6.5	278	2.87	33.8	1.1	3.9	0.9	6	<0.1	1.3	0.3	27	0.03	0.062
KYS 110688	Soil		1.8	34.6	22.4	63	0.4	23.0	7.3	376	3.19	26.2	1.0	15.5	2.6	11	0.1	2.6	0.4	43	0.06	0.078
KYS 110689	Soil		2.3	40.2	26.2	80	0.6	26.6	7.6	291	3.26	39.0	1.1	17.9	3.2	13	0.2	3.3	0.4	36	0.05	0.074
KYS 110690	Soil		2.1	42.3	19.2	67	0.4	19.7	4.8	218	3.04	33.1	1.1	7.6	0.8	11	0.1	2.5	0.3	47	0.03	0.063
KYS 110691	Soil		1.8	44.6	15.9	77	0.5	28.0	6.3	324	2.95	21.9	1.2	10.9	0.3	10	0.2	2.1	0.3	40	0.04	0.077
KYS 110692	Soil		2.5	59.8	23.6	143	0.4	54.7	17.0	604	4.61	103.6	1.7	21.8	6.5	11	0.5	6.8	0.3	26	0.02	0.068
KYS 110693	Soil		2.1	50.5	25.0	89	0.5	29.5	9.1	406	3.74	24.6	1.2	11.6	2.3	13	0.1	2.9	0.4	34	0.03	0.077
KYS 110694	Soil		2.2	75.1	24.8	98	0.5	46.7	5.7	257	3.16	19.7	1.1	10.4	4.4	13	0.1	2.9	0.4	30	0.02	0.064
KYS 110695	Soil		3.2	71.9	23.1	94	0.8	34.3	8.1	293	3.84	26.8	1.5	15.1	2.5	14	0.1	3.0	0.4	38	0.03	0.078
KYS 110696	Soil		2.5	59.6	15.2	97	0.3	37.5	11.3	406	2.95	22.4	1.4	7.5	2.6	12	0.3	2.4	0.3	36	0.06	0.075
KYS 110697	Soil		4.0	82.0	46.5	96	1.4	27.1	8.1	545	4.64	33.1	2.4	20.8	1.4	16	0.1	3.1	0.7	39	0.04	0.167
KYS 110698	Soil		4.2	84.2	45.4	100	1.3	27.8	8.5	572	4.75	34.6	2.4	21.5	1.9	16	0.1	3.1	0.7	40	0.04	0.160
KYS 110699	Soil		7.4	33.5	25.2	78	0.8	20.6	5.6	218	3.08	45.5	1.7	15.3	0.6	12	<0.1	4.5	0.4	42	0.07	0.113

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110670	Soil	16	19	0.44	80	0.037	<1	1.08	0.005	0.04	0.3	0.04	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 110671	Soil	12	5	0.06	52	0.002	<1	0.28	0.002	0.05	<0.1	<0.01	0.4	<0.1	<0.05	1	<0.5	<0.2
KYS 110672	Soil	14	20	0.30	53	0.027	<1	1.28	0.004	0.04	0.3	0.03	1.4	0.1	<0.05	5	<0.5	<0.2
KYS 110673	Soil	35	7	0.17	73	0.001	<1	0.76	0.004	0.06	<0.1	0.08	1.4	<0.1	<0.05	1	<0.5	<0.2
KYS 110674	Soil	36	7	0.16	74	0.001	<1	0.74	0.003	0.06	<0.1	0.08	1.4	<0.1	0.06	1	<0.5	<0.2
KYS 110675	Soil	9	5	6.87	96	0.005	2	0.23	0.004	0.02	0.2	0.05	1.6	<0.1	<0.05	<1	<0.5	<0.2
KYS 110676	Soil	16	25	0.47	152	0.016	1	1.51	0.005	0.04	0.2	0.06	1.6	<0.1	<0.05	4	0.6	<0.2
KYS 110677	Soil	16	22	0.42	94	0.009	<1	1.43	0.005	0.04	0.1	0.05	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 110678	Soil	22	19	0.37	92	0.023	<1	1.16	0.004	0.04	0.2	0.05	1.9	<0.1	<0.05	3	1.0	<0.2
KYS 110679	Soil	22	21	0.40	120	0.017	1	1.30	0.003	0.05	0.2	0.06	1.9	<0.1	<0.05	3	0.6	<0.2
KYS 110680	Soil	24	19	0.36	93	0.009	<1	1.11	0.005	0.05	0.2	0.04	1.3	<0.1	<0.05	3	0.7	<0.2
KYS 110681	Soil	14	24	0.35	114	0.015	<1	1.41	0.005	0.04	0.2	0.09	1.6	<0.1	<0.05	4	1.0	<0.2
KYS 110682	Soil	5	3	0.02	181	<0.001	1	0.16	0.017	0.08	0.3	0.03	1.6	<0.1	0.23	<1	<0.5	<0.2
KYS 110683	Soil	18	24	0.35	96	0.005	<1	1.35	0.004	0.04	<0.1	0.03	1.5	<0.1	<0.05	3	0.8	<0.2
KYS 110684	Soil	18	19	0.39	123	0.002	<1	1.07	0.006	0.07	<0.1	0.02	2.1	0.1	<0.05	3	0.8	<0.2
KYS 110685	Soil	13	11	0.26	70	0.001	<1	0.78	0.003	0.04	<0.1	0.05	3.3	<0.1	<0.05	2	0.5	<0.2
KYS 110686	Soil	11	26	0.34	80	0.019	<1	1.28	0.005	0.04	0.1	0.05	1.4	<0.1	<0.05	4	0.7	<0.2
KYS 110687	Soil	14	19	0.26	60	0.010	<1	1.00	0.004	0.03	<0.1	0.04	0.8	<0.1	<0.05	3	0.8	<0.2
KYS 110688	Soil	13	27	0.33	99	0.018	<1	1.36	0.007	0.04	0.2	0.08	1.7	<0.1	<0.05	4	1.0	0.3
KYS 110689	Soil	12	21	0.23	99	0.015	5	1.12	0.006	0.04	0.2	0.13	1.8	<0.1	<0.05	4	1.5	<0.2
KYS 110690	Soil	11	24	0.20	75	0.016	<1	1.11	0.005	0.04	0.1	0.09	1.1	<0.1	<0.05	5	1.4	<0.2
KYS 110691	Soil	9	24	0.24	74	0.011	<1	1.24	0.004	0.03	0.2	0.07	0.7	<0.1	0.06	4	1.2	0.4
KYS 110692	Soil	14	20	0.17	76	0.007	<1	1.09	0.004	0.03	0.1	0.10	1.9	<0.1	<0.05	3	2.3	<0.2
KYS 110693	Soil	12	26	0.27	88	0.007	<1	1.53	0.006	0.04	0.1	0.08	1.4	<0.1	<0.05	4	1.4	0.2
KYS 110694	Soil	8	24	0.34	102	0.003	<1	1.63	0.004	0.03	0.1	0.13	2.2	<0.1	0.05	3	1.8	0.4
KYS 110695	Soil	9	25	0.30	119	0.011	<1	1.42	0.006	0.04	0.1	0.10	1.7	<0.1	0.06	4	2.2	<0.2
KYS 110696	Soil	11	23	0.31	97	0.020	<1	1.45	0.004	0.04	0.2	0.11	1.9	<0.1	<0.05	3	2.3	0.2
KYS 110697	Soil	9	28	0.28	80	0.010	<1	1.47	0.006	0.04	<0.1	0.10	1.2	<0.1	0.06	4	3.1	0.2
KYS 110698	Soil	10	28	0.29	82	0.007	<1	1.48	0.005	0.04	<0.1	0.11	1.3	<0.1	0.07	4	3.4	0.6
KYS 110699	Soil	11	22	0.26	144	0.016	<1	1.08	0.005	0.05	0.2	0.12	1.0	0.1	<0.05	4	2.7	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110700	Soil		2.6	37.9	16.7	77	0.3	24.8	8.2	326	3.01	22.4	1.3	8.6	2.9	14	0.2	2.9	0.3	42	0.11	0.084
KYS 110701	Soil		4.4	37.3	22.0	88	0.6	22.2	5.3	201	3.17	27.6	1.3	9.6	2.1	10	0.1	3.7	0.4	35	0.05	0.086
KYS 110702	Soil		3.0	47.8	27.4	75	0.7	21.3	3.8	178	3.17	30.8	1.0	7.6	4.5	12	<0.1	5.1	0.5	31	0.03	0.090
KYS 110703	Soil		3.6	54.9	25.0	72	0.7	21.5	4.2	220	3.14	38.9	1.2	11.2	4.0	11	0.2	5.0	0.5	33	0.06	0.097
KYS 110704	Soil		11.4	47.2	23.1	93	0.9	23.0	4.3	155	2.81	38.0	1.7	11.7	1.0	10	0.2	5.6	0.4	36	0.06	0.110
KYS 110705	Soil		3.0	52.4	28.7	59	0.9	23.3	5.6	289	2.98	24.1	1.2	17.3	2.6	11	0.1	3.1	0.5	35	0.06	0.088
KYS 110706	Soil		3.0	71.8	35.0	56	0.9	19.8	3.4	204	3.51	37.4	1.3	14.7	3.1	10	0.1	3.8	0.7	32	0.02	0.119
KYS 110707	Soil		3.0	57.2	33.1	53	0.7	14.7	2.8	154	4.08	31.4	0.9	15.8	2.9	9	<0.1	3.4	0.7	37	0.01	0.104
KYS 110708	Soil		15.0	38.0	29.4	100	1.2	19.3	4.2	154	3.01	28.9	1.9	6.3	3.0	15	0.3	7.4	0.4	37	0.02	0.146
KYS 110709	Soil		3.1	78.0	33.4	68	1.0	29.4	4.7	236	4.44	19.0	0.7	8.5	4.5	9	<0.1	2.0	0.5	38	0.02	0.083
KYS 110710	Soil		2.4	30.9	15.9	41	0.2	9.3	2.6	85	3.50	21.9	0.3	6.3	1.5	4	<0.1	2.7	0.4	52	0.01	0.066
KYS 110711	Soil		5.4	39.8	29.5	77	0.6	20.7	7.4	358	3.12	17.4	1.4	4.4	2.2	8	0.8	3.7	0.4	23	0.05	0.091
KYS 110712	Soil		2.7	65.9	29.8	72	0.6	25.6	5.6	322	4.77	22.1	0.8	8.0	2.5	9	<0.1	2.1	0.5	47	0.02	0.094
KYS 110713	Soil		3.9	30.7	21.4	80	0.4	25.8	9.7	585	2.70	18.9	1.4	2.7	4.0	18	0.3	2.3	0.3	18	0.26	0.070
KYS 110714	Soil		1.0	52.3	39.3	124	0.4	59.3	25.3	948	4.20	281.5	1.9	21.7	11.3	12	0.1	5.6	0.4	12	0.18	0.057
KYS 110715	Soil		4.6	46.6	27.2	125	0.7	35.1	7.6	279	2.97	45.8	1.6	8.6	2.9	35	1.1	4.3	0.3	22	0.40	0.086
KYS 110716	Soil		3.9	44.2	22.2	119	0.7	35.5	9.4	528	3.18	68.0	2.8	7.4	2.2	27	0.8	3.0	0.3	28	0.31	0.108
KYS 110717	Soil		2.1	47.6	26.2	68	0.3	23.6	5.6	258	3.44	44.0	0.7	8.5	3.9	16	<0.1	3.6	0.4	27	0.14	0.075
KYS 110718	Soil		2.4	61.5	42.4	67	3.2	23.7	5.0	238	3.39	246.9	1.0	30.1	2.6	20	0.1	6.4	0.5	30	0.20	0.091
KYS 110719	Soil		4.4	157.6	52.1	277	0.6	153.7	45.6	1808	5.24	1094	4.5	65.7	6.9	9	2.7	19.4	0.6	17	0.05	0.105
KYS 110720	Soil		1.6	35.8	86.9	82	0.4	26.6	21.2	447	3.70	34.3	1.9	0.7	4.4	21	0.2	2.0	0.6	14	0.21	0.067
KYS 110721	Soil		1.9	91.1	36.6	102	0.5	53.1	22.7	941	3.94	166.0	1.9	10.1	7.3	12	0.4	4.4	0.4	23	0.09	0.087
KYS 110722	Soil		2.9	76.1	33.7	103	0.4	41.1	14.8	549	4.22	41.1	2.0	11.1	9.7	14	0.2	4.7	0.4	25	0.09	0.064
KYS 110723	Soil		1.9	68.0	26.8	127	0.5	52.8	17.2	738	3.57	54.8	2.1	7.4	6.3	31	0.9	2.9	0.4	18	0.59	0.079
KYS 110724	Soil		1.8	60.2	34.6	121	0.2	60.4	23.1	1015	4.10	43.9	2.2	5.5	9.9	17	0.4	3.2	0.4	14	0.26	0.055
KYS 110725	Soil		2.3	80.0	39.2	98	1.1	34.1	9.7	353	4.07	509.1	1.5	74.7	4.8	17	0.2	9.2	0.5	33	0.02	0.069
KYS 110726	Soil		1.2	26.6	18.2	62	0.4	24.9	7.6	311	2.47	29.3	0.8	10.6	2.4	9	0.1	1.4	0.2	24	0.06	0.082
KYS 110727	Soil		1.2	25.8	16.1	50	<0.1	19.3	6.0	186	2.42	22.1	1.0	7.0	1.0	8	0.1	1.2	0.2	33	0.09	0.056
KYS 110728	Soil		0.9	36.5	14.3	69	<0.1	28.0	10.3	415	2.55	23.3	0.9	7.3	6.2	13	0.2	1.4	0.2	38	0.18	0.076
KYS 110729	Soil		1.0	30.1	18.2	62	0.1	22.4	10.0	379	2.74	17.5	0.9	9.0	6.9	10	0.1	1.3	0.2	29	0.13	0.064

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110700	Soil		14	25	0.34	95	0.027	1	1.21	0.005	0.04	0.2	0.07	2.1	<0.1	<0.05	4	1.5	<0.2
KYS 110701	Soil		12	21	0.26	110	0.010	<1	1.11	0.006	0.03	0.2	0.09	1.6	<0.1	<0.05	4	2.2	0.4
KYS 110702	Soil		12	22	0.21	115	0.003	<1	1.01	0.004	0.02	0.1	0.10	1.9	<0.1	<0.05	3	2.5	0.6
KYS 110703	Soil		12	21	0.24	132	0.007	<1	1.07	0.004	0.03	0.1	0.08	2.0	<0.1	<0.05	3	2.6	0.2
KYS 110704	Soil		9	18	0.18	155	0.007	<1	0.87	0.005	0.04	0.1	0.19	1.1	<0.1	0.06	3	3.0	0.2
KYS 110705	Soil		10	23	0.30	155	0.006	<1	1.24	0.006	0.04	<0.1	0.07	2.1	<0.1	0.05	4	1.9	0.2
KYS 110706	Soil		6	24	0.22	145	0.002	<1	1.18	0.007	0.04	<0.1	0.06	2.4	<0.1	0.18	4	3.1	<0.2
KYS 110707	Soil		8	25	0.18	124	0.003	<1	1.26	0.004	0.03	<0.1	0.08	1.3	<0.1	0.09	4	3.4	0.6
KYS 110708	Soil		8	10	0.09	923	0.004	<1	0.52	0.003	0.07	0.1	0.20	1.1	0.1	0.19	2	4.4	<0.2
KYS 110709	Soil		6	30	0.25	77	0.003	<1	1.82	0.004	0.02	<0.1	0.12	1.7	<0.1	0.11	5	1.9	0.3
KYS 110710	Soil		7	19	0.05	48	0.006	<1	0.69	0.004	0.02	<0.1	0.04	0.6	<0.1	0.07	6	1.7	<0.2
KYS 110711	Soil		12	16	0.19	844	0.002	<1	0.83	0.003	0.04	<0.1	0.08	0.9	<0.1	0.10	3	1.6	<0.2
KYS 110712	Soil		9	33	0.28	84	0.010	<1	1.75	0.003	0.03	<0.1	0.13	1.5	<0.1	0.05	6	2.3	0.6
KYS 110713	Soil		11	16	0.30	581	0.002	<1	0.87	0.003	0.04	<0.1	0.06	1.0	<0.1	0.05	3	0.9	<0.2
KYS 110714	Soil		19	16	0.43	98	0.002	3	1.15	0.003	0.06	<0.1	0.04	2.0	<0.1	<0.05	3	<0.5	<0.2
KYS 110715	Soil		9	17	0.27	888	0.002	<1	0.92	0.005	0.04	<0.1	0.11	1.1	<0.1	0.09	3	2.5	0.4
KYS 110716	Soil		7	21	0.24	499	0.003	<1	1.13	0.004	0.03	<0.1	0.16	1.5	<0.1	0.11	3	2.0	0.3
KYS 110717	Soil		8	21	0.24	117	0.002	<1	1.13	0.005	0.04	<0.1	0.05	1.4	<0.1	0.06	4	1.2	0.3
KYS 110718	Soil		7	21	0.19	131	0.003	<1	1.19	0.006	0.03	<0.1	0.13	1.4	<0.1	0.08	4	1.6	<0.2
KYS 110719	Soil		14	13	0.24	94	0.002	<1	1.12	0.003	0.04	<0.1	0.08	2.8	<0.1	0.05	2	1.4	0.4
KYS 110720	Soil		7	14	0.40	116	0.001	<1	1.27	0.004	0.05	<0.1	0.04	1.2	<0.1	0.06	3	0.6	0.3
KYS 110721	Soil		11	21	0.33	128	0.002	<1	1.38	0.005	0.06	<0.1	0.05	1.9	<0.1	0.07	3	1.3	<0.2
KYS 110722	Soil		13	18	0.45	125	0.003	<1	1.22	0.004	0.04	<0.1	0.07	2.1	<0.1	0.06	3	1.5	<0.2
KYS 110723	Soil		10	17	0.41	114	0.003	<1	1.04	0.005	0.05	<0.1	0.05	2.0	<0.1	0.07	3	1.0	<0.2
KYS 110724	Soil		15	23	0.50	90	0.002	<1	1.12	0.004	0.05	<0.1	0.03	2.1	<0.1	0.05	3	0.7	<0.2
KYS 110725	Soil		10	23	0.27	192	0.004	<1	1.37	0.006	0.05	0.1	0.07	2.1	<0.1	0.09	4	1.6	<0.2
KYS 110726	Soil		13	26	0.36	104	0.008	<1	0.92	0.003	0.05	<0.1	0.03	1.2	<0.1	0.05	3	<0.5	0.4
KYS 110727	Soil		15	22	0.29	60	0.016	<1	1.08	0.003	0.05	0.1	0.03	1.0	<0.1	0.06	4	<0.5	<0.2
KYS 110728	Soil		15	23	0.43	76	0.044	<1	1.08	0.004	0.05	0.2	0.03	2.0	<0.1	<0.05	3	<0.5	<0.2
KYS 110729	Soil		19	22	0.41	101	0.021	<1	1.10	0.005	0.08	0.2	0.03	1.7	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110730	Soil		3.1	47.6	24.4	78	0.5	28.7	10.0	393	3.28	28.0	1.3	6.8	4.9	13	0.3	3.0	0.3	29	0.11	0.073
KYS 110731	Soil		1.2	39.3	22.8	67	0.3	28.4	13.7	469	2.78	45.6	1.4	5.9	4.5	11	0.2	1.9	0.3	17	0.12	0.070
KYS 110732	Soil		11.9	39.3	13.7	72	0.7	24.6	8.9	242	2.38	38.2	2.6	2.9	3.1	22	0.2	5.1	0.2	54	0.10	0.080
KYS 110733	Soil		2.7	45.1	13.9	64	0.2	24.4	8.0	357	2.58	15.1	2.2	1.0	6.1	19	0.2	2.2	0.2	46	0.11	0.063
KYS 110734	Soil		16.0	52.2	17.4	49	0.7	14.0	5.0	195	1.76	13.4	2.4	2.5	4.8	20	<0.1	4.0	0.2	28	0.05	0.072
KYS 110735	Soil		12.3	40.1	16.9	58	0.5	16.6	4.6	151	1.82	24.9	3.1	1.8	7.7	35	0.3	5.1	0.3	38	0.08	0.068
KYS 110736	Soil		3.9	145.7	20.1	80	0.7	22.5	8.6	293	2.59	18.9	2.6	4.0	7.0	31	0.4	3.0	0.3	40	0.11	0.119
KYS 110737	Soil		5.2	63.3	18.7	82	0.7	21.9	8.4	354	3.05	16.8	3.1	6.8	5.6	35	0.3	2.5	0.3	47	0.13	0.101
KYS 110738	Soil		4.4	58.5	17.3	81	0.5	23.9	9.1	353	2.89	16.9	2.9	4.5	5.5	33	0.3	2.4	0.3	49	0.15	0.104
KYS 110739	Soil		4.5	66.4	14.7	72	0.2	23.0	10.4	356	2.69	15.8	2.5	2.6	4.5	21	0.3	2.4	0.2	47	0.11	0.079
KYS 110740	Soil		4.6	69.8	15.0	76	0.3	23.7	10.4	381	2.63	16.1	2.5	3.9	4.4	22	0.3	2.5	0.3	50	0.12	0.082
KYS 110741	Soil		8.4	51.7	13.5	82	0.3	26.7	10.5	388	2.33	19.3	3.3	1.7	6.4	28	0.9	4.1	0.2	47	0.09	0.074
KYS 110742	Soil		12.0	78.4	21.9	100	0.7	21.7	6.3	230	2.45	16.2	4.4	4.6	9.6	41	0.6	4.8	0.3	46	0.06	0.090
KYS 110743	Soil		12.7	33.4	27.1	57	0.9	10.3	3.0	149	2.51	14.0	1.9	2.5	3.1	27	0.3	2.8	0.4	63	0.06	0.166
KYS 110744	Soil		8.0	79.7	27.0	87	0.7	14.3	3.6	191	2.21	19.3	9.5	4.4	12.2	61	0.3	3.2	0.3	44	0.14	0.141
KYS 110745	Soil		5.7	28.3	25.8	68	0.4	17.1	7.4	302	2.35	31.6	1.4	3.8	3.5	20	0.3	2.1	0.3	43	0.09	0.095
KYS 110746	Soil		55.7	54.2	25.0	128	0.6	10.0	1.1	62	2.29	8.4	10.7	0.7	7.0	30	0.2	6.5	0.2	73	0.01	0.058
KYS 110749	Soil		1.2	42.5	29.8	61	0.1	33.5	17.9	649	2.87	42.8	1.3	4.7	4.0	9	0.2	1.5	0.5	24	0.09	0.059
KYS 110750	Soil		1.6	40.3	20.4	80	0.2	27.7	11.6	426	2.96	20.4	1.0	7.6	1.5	7	0.2	1.8	0.3	35	0.06	0.071
KYS 110751	Soil		1.8	24.4	19.9	60	0.1	18.3	6.9	346	2.45	24.1	0.8	5.1	0.8	7	0.2	1.9	0.3	40	0.05	0.057
KYS 110752	Soil		1.2	32.5	12.8	66	0.1	21.8	7.8	352	2.48	14.7	1.0	4.6	2.9	10	0.2	1.4	0.2	37	0.09	0.061
KYS 110753	Soil		1.2	29.0	12.9	67	0.1	21.4	7.4	338	2.43	13.7	1.0	5.4	3.2	9	0.2	1.3	0.2	38	0.08	0.061
KYS 110754	Soil		1.2	28.4	13.0	65	0.1	21.5	7.6	338	2.36	13.5	1.0	7.2	3.1	9	0.2	1.3	0.2	39	0.09	0.060
KYS 110755	Soil		2.1	105.4	24.1	109	0.7	32.7	7.7	187	3.46	47.0	1.4	38.7	3.7	9	0.2	7.4	0.3	27	0.03	0.072
KYS 110756	Soil		2.2	46.7	23.6	93	0.7	28.7	7.0	203	2.61	91.9	1.1	14.5	3.1	8	0.1	9.9	0.4	25	0.05	0.078
KYS 110757	Soil		1.7	22.4	17.1	46	0.5	14.5	3.5	146	1.90	26.6	0.8	10.6	0.4	8	<0.1	1.8	0.3	32	0.05	0.067
KYS 110758	Soil		1.6	33.4	16.5	63	0.3	22.2	6.3	247	2.39	34.6	0.9	6.5	1.7	10	0.2	2.6	0.3	35	0.07	0.072
KYS 110759	Soil		2.0	34.0	21.4	71	1.0	22.6	4.3	151	2.37	35.9	1.0	13.7	2.5	7	<0.1	6.5	0.4	27	0.04	0.076
KYS 110760	Soil		2.1	41.8	24.0	73	0.7	24.2	6.2	267	2.71	58.2	1.0	13.5	2.7	9	<0.1	8.9	0.4	29	0.04	0.079
KYS 110761	Soil		2.0	41.0	23.6	73	1.1	22.1	4.5	174	2.67	57.8	0.8	13.0	2.6	4	<0.1	13.3	0.3	19	0.01	0.074

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110730	Soil	13	19	0.23	456	0.005	<1	1.03	0.004	0.05	<0.1	0.07	2.0	<0.1	0.06	3	1.6	0.4
KYS 110731	Soil	13	18	0.33	105	0.005	<1	0.97	0.003	0.05	<0.1	0.04	1.5	<0.1	0.05	3	<0.5	<0.2
KYS 110732	Soil	21	22	0.39	155	0.028	<1	1.59	0.005	0.05	0.3	0.28	2.4	0.2	<0.05	4	2.3	<0.2
KYS 110733	Soil	20	24	0.44	212	0.046	<1	1.32	0.006	0.06	0.2	0.08	2.9	<0.1	<0.05	4	1.1	<0.2
KYS 110734	Soil	28	16	0.21	130	0.012	<1	1.37	0.008	0.04	0.1	0.27	1.4	0.3	0.09	2	4.5	<0.2
KYS 110735	Soil	25	14	0.28	135	0.029	<1	0.81	0.005	0.05	0.2	0.19	2.1	0.1	<0.05	2	1.9	<0.2
KYS 110736	Soil	24	27	0.41	119	0.019	<1	1.79	0.007	0.05	0.2	0.11	1.9	<0.1	<0.05	3	3.0	<0.2
KYS 110737	Soil	23	26	0.49	281	0.026	<1	1.48	0.018	0.06	0.2	0.14	2.5	<0.1	0.11	4	1.2	<0.2
KYS 110738	Soil	23	25	0.51	285	0.029	1	1.50	0.012	0.06	0.2	0.13	2.7	<0.1	<0.05	4	1.4	<0.2
KYS 110739	Soil	20	25	0.48	216	0.031	<1	1.47	0.006	0.06	0.2	0.11	3.0	0.1	<0.05	4	0.7	0.4
KYS 110740	Soil	20	26	0.48	227	0.033	<1	1.50	0.006	0.06	0.2	0.13	3.1	0.1	<0.05	5	0.9	<0.2
KYS 110741	Soil	18	17	0.33	185	0.053	<1	0.97	0.007	0.05	0.2	0.13	2.1	0.1	<0.05	3	2.0	<0.2
KYS 110742	Soil	28	19	0.36	153	0.023	<1	1.47	0.010	0.05	0.1	0.40	1.6	0.1	0.07	3	6.9	<0.2
KYS 110743	Soil	29	20	0.22	103	0.013	<1	0.70	0.008	0.05	0.1	0.13	0.8	<0.1	0.07	3	4.1	<0.2
KYS 110744	Soil	36	22	0.37	152	0.010	<1	1.20	0.006	0.05	<0.1	0.27	2.0	<0.1	<0.05	3	2.3	<0.2
KYS 110745	Soil	24	23	0.35	119	0.016	<1	1.42	0.006	0.04	0.2	0.10	1.3	<0.1	<0.05	4	1.4	<0.2
KYS 110746	Soil	35	12	0.17	170	0.002	<1	0.72	0.004	0.06	<0.1	0.32	1.5	<0.1	<0.05	2	4.5	<0.2
KYS 110749	Soil	18	20	0.36	87	0.011	<1	1.16	0.007	0.07	<0.1	0.05	1.2	<0.1	<0.05	3	0.5	<0.2
KYS 110750	Soil	11	20	0.33	70	0.015	<1	1.16	0.005	0.03	0.1	0.05	1.3	<0.1	<0.05	4	0.9	<0.2
KYS 110751	Soil	10	22	0.30	81	0.014	<1	1.19	0.005	0.04	0.1	0.03	1.1	<0.1	<0.05	4	0.9	<0.2
KYS 110752	Soil	14	23	0.44	94	0.029	3	1.30	0.010	0.04	0.2	0.03	2.1	<0.1	<0.05	4	0.7	<0.2
KYS 110753	Soil	14	22	0.41	70	0.033	<1	1.26	0.006	0.04	0.2	0.03	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110754	Soil	15	22	0.42	76	0.031	9	1.35	0.006	0.04	0.3	0.04	2.0	<0.1	<0.05	4	0.6	<0.2
KYS 110755	Soil	9	16	0.20	70	0.014	<1	0.83	0.005	0.03	0.2	0.05	2.4	<0.1	0.06	2	1.7	0.2
KYS 110756	Soil	11	16	0.17	79	0.005	<1	0.84	0.007	0.03	0.1	0.06	2.4	<0.1	<0.05	3	1.6	<0.2
KYS 110757	Soil	9	18	0.21	98	0.011	<1	0.97	0.006	0.03	0.1	0.08	1.1	<0.1	<0.05	3	1.0	<0.2
KYS 110758	Soil	11	20	0.30	102	0.016	<1	1.15	0.005	0.04	0.1	0.08	1.7	<0.1	<0.05	4	1.0	<0.2
KYS 110759	Soil	8	16	0.15	61	0.007	<1	0.80	0.005	0.03	0.1	0.07	1.3	<0.1	<0.05	3	2.0	<0.2
KYS 110760	Soil	9	18	0.18	85	0.006	<1	0.98	0.006	0.03	0.1	0.09	1.8	<0.1	<0.05	3	1.7	<0.2
KYS 110761	Soil	8	13	0.05	52	<0.001	<1	0.66	0.005	0.02	<0.1	0.06	1.2	<0.1	<0.05	2	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110762	Soil	2.3	57.0	24.8	85	0.6	31.4	11.9	407	3.12	82.2	1.1	18.6	3.8	4	0.1	15.5	0.4	21	<0.01	0.075
KYS 110763	Soil	2.7	65.9	22.5	121	0.6	45.3	12.1	743	4.02	51.2	0.9	21.3	3.7	9	0.2	6.4	0.6	25	0.01	0.085
KYS 110764	Soil	2.5	97.8	33.5	101	0.9	27.2	7.2	246	4.10	47.4	1.5	7.5	3.6	13	0.1	6.2	0.6	30	<0.01	0.093
KYS 110765	Soil	2.2	56.6	30.2	80	0.5	32.4	6.8	282	3.34	25.0	1.0	13.1	3.5	11	0.2	3.5	0.5	33	0.03	0.069
KYS 110766	Soil	1.3	41.0	13.5	95	<0.1	64.0	17.8	588	3.02	16.4	0.8	4.1	2.3	10	0.4	1.6	0.2	31	0.09	0.073
KYS 110767	Soil	1.5	21.9	13.2	54	<0.1	18.1	7.6	342	2.50	15.8	0.7	6.2	0.9	6	0.1	1.8	0.3	37	0.04	0.059
KYS 110768	Soil	1.1	28.6	21.1	72	<0.1	34.9	17.4	838	3.30	56.8	0.8	3.5	3.5	7	0.1	1.9	0.3	28	0.08	0.069
KYS 110769	Soil	1.5	33.2	26.0	74	<0.1	34.3	15.6	640	3.57	39.5	1.0	2.6	3.0	8	0.2	1.8	0.3	29	0.10	0.062
KYS 110770	Soil	1.4	21.9	24.4	83	<0.1	30.4	16.0	605	3.19	361.1	0.9	6.4	3.9	9	0.3	2.3	0.3	39	0.08	0.060
KYS 110771	Soil	0.6	27.6	32.6	70	<0.1	35.0	15.3	617	3.50	161.7	0.8	3.5	8.6	15	0.2	1.8	0.4	20	0.24	0.051

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

CERTIFICATE OF ANALYSIS WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110762	Soil	9	13	0.07	43	0.002	<1	0.61	0.005	0.02	<0.1	0.08	1.7	<0.1	<0.05	2	1.3	0.3
KYS 110763	Soil	8	17	0.19	68	0.003	<1	0.90	0.006	0.03	<0.1	0.09	1.7	<0.1	<0.05	3	1.8	0.3
KYS 110764	Soil	7	20	0.24	82	0.002	<1	1.03	0.007	0.03	<0.1	0.09	2.5	<0.1	0.05	3	2.2	0.3
KYS 110765	Soil	8	20	0.30	93	0.014	<1	1.14	0.006	0.04	<0.1	0.08	2.2	<0.1	<0.05	4	1.1	<0.2
KYS 110766	Soil	8	19	0.40	102	0.017	<1	1.36	0.005	0.03	<0.1	0.05	2.0	<0.1	<0.05	4	0.9	<0.2
KYS 110767	Soil	10	22	0.29	74	0.017	1	1.12	0.004	0.03	0.2	0.04	1.1	<0.1	<0.05	4	0.5	<0.2
KYS 110768	Soil	14	28	0.47	61	0.014	<1	1.18	0.004	0.04	0.1	0.02	1.4	<0.1	<0.05	4	0.6	<0.2
KYS 110769	Soil	15	26	0.38	55	0.012	1	1.22	0.004	0.04	0.1	0.03	1.0	<0.1	<0.05	4	0.6	<0.2
KYS 110770	Soil	15	27	0.39	134	0.020	1	1.55	0.005	0.05	0.2	0.04	2.1	0.1	<0.05	4	<0.5	<0.2
KYS 110771	Soil	20	19	0.33	85	0.009	<1	0.97	0.004	0.05	<0.1	0.03	2.1	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

QUALITY CONTROL REPORT WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
KYS 110492	Soil	1.2	84.2	24.9	105	0.2	48.7	19.8	1811	3.64	29.1	1.8	11.3	10.9	19	0.2	3.1	0.3	21	0.21	0.067
REP KYS 110492	QC	1.2	92.1	25.5	106	0.2	51.8	20.8	1794	3.68	29.4	1.7	12.8	11.1	18	0.1	3.1	0.3	21	0.21	0.064
KYS 110504	Soil	1.2	96.5	14.6	68	0.1	36.8	11.4	1662	2.58	12.6	1.1	9.7	4.9	15	0.2	1.6	0.2	40	0.10	0.060
REP KYS 110504	QC	1.3	99.8	14.4	71	0.1	37.3	11.4	1640	2.65	12.6	1.1	27.7	5.1	15	0.2	1.7	0.3	41	0.10	0.063
KYS 110538	Soil	2.3	60.8	24.0	75	0.7	25.3	5.3	235	3.87	18.3	1.0	10.2	2.0	15	0.1	2.2	0.4	43	0.02	0.097
REP KYS 110538	QC	2.2	61.9	23.8	77	0.7	25.2	5.2	244	3.84	18.3	1.2	9.3	2.1	15	0.1	2.1	0.4	44	0.02	0.095
KYS 110558	Soil	6.5	71.0	25.5	185	0.8	43.9	7.9	301	3.96	55.3	2.3	10.7	3.4	15	0.4	8.1	0.4	31	0.02	0.102
REP KYS 110558	QC	6.2	71.2	25.2	181	0.9	43.8	8.0	299	3.92	54.4	2.2	16.1	3.4	14	0.4	8.1	0.4	30	0.02	0.100
KYS 110559	Soil	3.9	71.2	23.5	92	0.6	28.1	4.9	142	3.70	41.7	1.1	17.2	1.7	9	0.1	5.8	0.4	28	0.01	0.091
REP KYS 110559	QC	3.7	68.1	21.8	88	0.6	26.2	4.5	136	3.50	39.2	1.1	19.0	1.7	9	0.2	5.5	0.4	28	0.01	0.086
KYS 110585	Soil	0.7	37.0	10.0	69	<0.1	30.9	11.1	466	2.36	17.8	0.9	4.4	5.1	11	0.2	1.3	0.1	38	0.16	0.067
REP KYS 110585	QC	0.9	36.7	10.5	69	<0.1	30.0	10.8	464	2.35	18.1	0.9	2.5	5.3	11	0.2	1.2	0.1	37	0.16	0.067
KYS 110599	Soil	0.7	28.8	18.4	60	<0.1	18.6	8.6	238	2.54	8.9	1.1	3.0	5.7	9	0.1	0.7	0.2	27	0.09	0.060
REP KYS 110599	QC	0.8	30.1	18.3	62	<0.1	19.3	8.7	242	2.57	9.3	1.0	1.8	5.3	9	<0.1	0.7	0.2	29	0.09	0.064
KYS 110625	Soil	0.3	33.5	23.0	80	<0.1	34.1	16.2	593	3.32	8.0	0.9	<0.5	13.0	23	<0.1	0.2	0.2	13	0.18	0.044
REP KYS 110625	QC	0.3	34.5	22.8	81	<0.1	35.2	16.8	609	3.57	8.1	0.9	<0.5	12.7	24	<0.1	0.2	0.2	13	0.20	0.047
KYS 110643	Soil	1.5	50.9	20.2	91	0.2	38.1	16.8	950	2.80	49.9	1.4	8.7	2.9	12	0.2	4.8	0.2	26	0.05	0.051
REP KYS 110643	QC	1.5	51.4	20.8	86	0.2	38.2	16.8	974	2.89	50.3	1.4	13.6	3.0	13	0.2	4.9	0.2	27	0.06	0.050
KYS 110654	Soil	1.7	49.3	15.2	68	0.3	24.5	9.5	964	2.97	14.5	0.9	10.6	0.7	10	0.2	1.2	0.3	48	0.06	0.066
REP KYS 110654	QC	1.7	48.8	14.2	69	0.2	24.8	9.8	967	2.96	14.0	0.9	10.0	0.6	10	0.2	1.2	0.3	51	0.06	0.067
KYS 110678	Soil	1.2	52.3	21.6	89	0.2	36.9	12.7	748	3.02	39.2	1.4	8.4	5.8	11	0.2	4.4	0.3	31	0.09	0.061
REP KYS 110678	QC	1.2	51.4	21.7	86	0.2	35.4	12.0	727	3.01	38.2	1.5	8.7	5.8	11	0.2	4.4	0.3	30	0.10	0.066
KYS 110692	Soil	2.5	59.8	23.6	143	0.4	54.7	17.0	604	4.61	103.6	1.7	21.8	6.5	11	0.5	6.8	0.3	26	0.02	0.068
REP KYS 110692	QC	2.4	57.7	23.7	144	0.4	52.2	16.9	594	4.55	105.6	1.7	24.5	6.2	11	0.4	6.7	0.3	25	0.02	0.066
KYS 110717	Soil	2.1	47.6	26.2	68	0.3	23.6	5.6	258	3.44	44.0	0.7	8.5	3.9	16	<0.1	3.6	0.4	27	0.14	0.075
REP KYS 110717	QC	2.0	43.1	25.6	67	0.2	24.8	5.5	259	3.39	42.3	0.7	16.1	3.7	15	<0.1	3.5	0.4	27	0.13	0.070
KYS 110735	Soil	12.3	40.1	16.9	58	0.5	16.6	4.6	151	1.82	24.9	3.1	1.8	7.7	35	0.3	5.1	0.3	38	0.08	0.068
REP KYS 110735	QC	12.6	42.0	18.2	57	0.5	15.9	4.5	147	1.82	25.8	3.2	2.5	7.8	35	0.3	5.6	0.3	40	0.07	0.071

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

QUALITY CONTROL REPORT WHI10000119.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
KYS 110492	Soil	28	21	0.64	86	0.004	2	1.33	0.006	0.05	<0.1	0.04	1.3	<0.1	<0.05	3	0.9	<0.2
REP KYS 110492	QC	28	22	0.65	88	0.004	1	1.28	0.005	0.06	<0.1	0.04	1.4	<0.1	<0.05	4	0.6	<0.2
KYS 110504	Soil	20	23	0.42	115	0.027	2	1.13	0.005	0.03	0.2	0.05	1.4	<0.1	<0.05	4	<0.5	0.2
REP KYS 110504	QC	22	23	0.43	110	0.027	<1	1.15	0.006	0.04	0.2	0.06	1.6	<0.1	<0.05	4	0.8	<0.2
KYS 110538	Soil	9	27	0.28	99	0.010	<1	1.36	0.005	0.04	<0.1	0.09	1.3	<0.1	<0.05	5	1.6	<0.2
REP KYS 110538	QC	9	27	0.28	98	0.011	<1	1.35	0.004	0.04	<0.1	0.09	1.2	<0.1	<0.05	5	1.7	<0.2
KYS 110558	Soil	10	15	0.12	106	0.001	<1	0.88	0.006	0.03	0.1	0.16	1.8	<0.1	<0.05	2	3.7	<0.2
REP KYS 110558	QC	9	15	0.12	97	0.002	<1	0.89	0.006	0.03	<0.1	0.16	1.5	<0.1	<0.05	3	4.1	<0.2
KYS 110559	Soil	6	17	0.13	136	0.001	<1	0.81	0.005	0.03	<0.1	0.09	1.2	<0.1	<0.05	3	2.3	<0.2
REP KYS 110559	QC	6	16	0.12	127	0.001	<1	0.78	0.005	0.02	<0.1	0.08	1.2	<0.1	<0.05	3	2.7	<0.2
KYS 110585	Soil	14	24	0.37	106	0.037	<1	1.34	0.005	0.06	0.2	0.04	2.4	<0.1	<0.05	3	<0.5	<0.2
REP KYS 110585	QC	14	24	0.37	104	0.036	<1	1.32	0.005	0.06	0.2	0.03	2.5	<0.1	<0.05	3	<0.5	<0.2
KYS 110599	Soil	17	22	0.46	69	0.031	2	1.48	0.006	0.04	0.2	0.02	2.0	<0.1	<0.05	4	0.7	<0.2
REP KYS 110599	QC	17	22	0.45	67	0.029	1	1.49	0.005	0.04	0.2	0.05	1.9	<0.1	<0.05	4	0.6	<0.2
KYS 110625	Soil	18	24	0.59	75	0.005	<1	1.37	0.004	0.09	<0.1	<0.01	1.2	<0.1	<0.05	4	<0.5	<0.2
REP KYS 110625	QC	19	26	0.60	73	0.005	1	1.42	0.004	0.10	<0.1	<0.01	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 110643	Soil	14	19	0.36	119	0.016	1	1.08	0.010	0.05	0.1	0.08	1.4	<0.1	0.06	3	0.8	<0.2
REP KYS 110643	QC	14	20	0.35	132	0.016	<1	1.04	0.004	0.05	0.1	0.08	1.3	<0.1	<0.05	3	0.7	<0.2
KYS 110654	Soil	13	28	0.37	122	0.023	1	1.30	0.006	0.05	0.2	0.07	1.1	<0.1	0.07	5	0.7	<0.2
REP KYS 110654	QC	14	28	0.35	118	0.018	<1	1.30	0.012	0.05	0.2	0.08	1.2	<0.1	0.06	5	0.7	<0.2
KYS 110678	Soil	22	19	0.37	92	0.023	<1	1.16	0.004	0.04	0.2	0.05	1.9	<0.1	<0.05	3	1.0	<0.2
REP KYS 110678	QC	21	20	0.40	92	0.016	<1	1.20	0.005	0.04	0.2	0.05	1.8	<0.1	<0.05	3	0.8	<0.2
KYS 110692	Soil	14	20	0.17	76	0.007	<1	1.09	0.004	0.03	0.1	0.10	1.9	<0.1	<0.05	3	2.3	<0.2
REP KYS 110692	QC	14	19	0.17	78	0.005	<1	1.14	0.005	0.03	0.1	0.08	1.7	<0.1	<0.05	3	2.1	0.2
KYS 110717	Soil	8	21	0.24	117	0.002	<1	1.13	0.005	0.04	<0.1	0.05	1.4	<0.1	0.06	4	1.2	0.3
REP KYS 110717	QC	7	20	0.23	109	0.002	<1	1.10	0.004	0.04	<0.1	0.04	1.1	<0.1	0.06	3	1.3	<0.2
KYS 110735	Soil	25	14	0.28	135	0.029	<1	0.81	0.005	0.05	0.2	0.19	2.1	0.1	<0.05	2	1.9	<0.2
REP KYS 110735	QC	25	15	0.30	139	0.030	<1	0.81	0.006	0.05	0.2	0.16	1.9	0.1	<0.05	3	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

QUALITY CONTROL REPORT WHI10000119.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
KYS 110756	Soil	2.2	46.7	23.6	93	0.7	28.7	7.0	203	2.61	91.9	1.1	14.5	3.1	8	0.1	9.9	0.4	25	0.05	0.078
REP KYS 110756	QC	2.1	46.3	22.7	89	0.6	27.3	6.8	200	2.56	90.4	1.1	41.5	2.9	8	0.1	9.8	0.4	25	0.05	0.077
KYS 110770	Soil	1.4	21.9	24.4	83	<0.1	30.4	16.0	605	3.19	361.1	0.9	6.4	3.9	9	0.3	2.3	0.3	39	0.08	0.060
REP KYS 110770	QC	1.5	21.4	24.6	80	<0.1	31.1	16.0	601	3.13	353.9	0.9	7.3	3.7	9	0.3	2.4	0.3	38	0.08	0.063
Reference Materials																					
STD DS7	Standard	18.7	96.7	64.8	361	0.9	49.4	8.1	544	2.08	46.7	4.3	72.3	3.8	61	5.7	5.0	4.0	74	0.82	0.073
STD DS7	Standard	21.4	120.2	67.3	407	1.0	59.8	9.8	629	2.45	52.6	4.7	73.5	4.4	69	6.4	6.0	4.8	87	0.92	0.082
STD DS7	Standard	21.2	112.1	68.6	411	0.9	60.1	9.6	628	2.47	53.0	5.4	70.4	4.9	79	6.5	6.3	4.8	92	0.98	0.075
STD DS7	Standard	20.2	107.1	58.6	381	1.0	54.7	9.0	602	2.29	48.2	4.3	69.0	4.0	62	6.0	5.0	3.9	82	0.90	0.071
STD DS7	Standard	19.5	96.1	64.9	373	1.0	54.2	9.3	622	2.36	52.5	4.5	78.6	4.6	74	5.8	5.4	4.6	85	0.98	0.074
STD DS7	Standard	22.3	126.1	74.5	441	1.0	61.7	10.6	723	2.73	56.0	5.2	88.0	4.7	75	6.6	6.8	5.0	94	1.05	0.092
STD DS7	Standard	22.5	112.2	68.0	387	1.1	57.3	9.5	619	2.40	50.5	4.6	73.7	4.6	74	6.5	5.9	4.5	83	0.94	0.078
STD DS7	Standard	22.0	116.9	69.8	422	1.0	61.6	10.1	677	2.56	54.2	4.8	73.6	4.8	78	6.3	6.0	4.7	93	1.00	0.078
STD DS7	Standard	20.8	113.1	67.0	386	1.0	54.5	8.8	614	2.30	48.2	4.9	68.3	4.6	72	5.8	5.7	4.5	86	0.94	0.072
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.03	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 19, 2010

QUALITY CONTROL REPORT WHI10000119.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
KYS 110756	Soil	11	16	0.17	79	0.005	<1	0.84	0.007	0.03	0.1	0.06	2.4	<0.1	<0.05	3	1.6	<0.2
REP KYS 110756	QC	10	15	0.17	84	0.010	<1	0.84	0.005	0.03	0.1	0.06	2.3	<0.1	<0.05	3	1.7	0.3
KYS 110770	Soil	15	27	0.39	134	0.020	1	1.55	0.005	0.05	0.2	0.04	2.1	0.1	<0.05	4	<0.5	<0.2
REP KYS 110770	QC	14	26	0.41	132	0.017	2	1.61	0.005	0.05	0.2	0.04	2.0	0.1	<0.05	4	<0.5	<0.2
Reference Materials																		
STD DS7	Standard	11	195	1.02	356	0.105	32	0.97	0.095	0.46	3.3	0.20	2.2	3.9	0.18	4	2.7	1.1
STD DS7	Standard	13	212	1.06	400	0.131	43	1.02	0.112	0.50	3.7	0.23	2.9	4.2	0.25	5	3.0	1.6
STD DS7	Standard	14	222	1.07	394	0.127	34	1.07	0.117	0.50	3.6	0.20	2.7	3.9	0.24	5	2.9	1.1
STD DS7	Standard	12	204	1.01	394	0.103	34	0.98	0.101	0.45	3.4	0.23	2.2	4.1	0.17	5	3.2	1.3
STD DS7	Standard	13	229	1.03	407	0.120	39	1.05	0.102	0.47	4.0	0.21	2.6	4.0	0.19	5	3.5	1.7
STD DS7	Standard	15	228	1.07	413	0.152	42	1.08	0.108	0.50	3.7	0.20	2.9	4.4	0.18	5	3.4	1.6
STD DS7	Standard	13	213	1.04	418	0.129	35	1.01	0.096	0.46	3.9	0.20	2.5	3.9	0.25	5	3.0	1.7
STD DS7	Standard	14	232	1.07	417	0.138	39	1.09	0.104	0.50	3.9	0.24	2.6	4.3	0.19	5	3.3	0.3
STD DS7	Standard	13	216	1.04	392	0.124	39	1.01	0.094	0.47	3.5	0.21	2.4	4.0	0.20	5	3.0	1.4
STD DS7 Expected		12	179	1.05	410	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5	1.08
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Submitted By: Johnathan More
Receiving Lab: Canada-Whitehorse
Received: July 14, 2010
Report Date: August 23, 2010
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI10000118.1

CLIENT JOB INFORMATION

Project: KYS
Shipment ID: KYS1
P.O. Number
Number of Samples: 315

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	315	Dry at 60C sieve 100g to -80 mesh			VAN
Dry at 60C	315	Dry at 60C			VAN
1DX2	314	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Aldrin Resources
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5
Canada

CC: Isaac Fage
Bert Jeffries
Shawn Ryan

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110132	Soil		1.3	22.8	13.7	62	0.2	21.1	7.6	180	2.49	38.7	1.2	17.2	1.6	10	0.2	2.3	0.3	39	0.06	0.058
KYS 110133	Soil		1.1	23.0	11.9	63	0.2	18.7	7.9	175	1.68	16.1	1.4	4.6	0.7	18	0.3	1.0	0.2	40	0.27	0.074
KYS 110134	Soil		1.2	22.2	8.8	59	0.1	18.2	5.1	172	2.03	12.6	0.7	4.2	2.5	12	0.2	1.4	0.2	41	0.12	0.057
KYS 110135	Soil		1.3	20.3	12.0	61	<0.1	18.9	8.1	325	2.65	15.3	0.9	3.2	2.2	11	0.2	1.2	0.2	47	0.10	0.068
KYS 110136	Soil		2.0	15.2	13.4	37	0.3	10.1	3.0	134	2.22	18.1	0.8	3.9	0.4	8	<0.1	1.3	0.3	55	0.04	0.049
KYS 110137	Soil		1.7	23.8	13.5	48	0.2	18.2	5.2	226	2.44	21.8	0.9	7.7	2.1	12	0.2	2.0	0.3	39	0.09	0.072
KYS 110138	Soil		1.6	20.4	15.5	30	0.2	11.5	2.8	96	2.00	32.3	0.8	4.6	0.6	7	0.1	2.0	0.3	38	0.04	0.054
KYS 110139	Soil		1.7	27.4	15.3	48	0.2	18.0	5.4	203	2.71	15.9	0.9	4.3	2.7	12	0.2	1.4	0.3	40	0.08	0.071
KYS 110140	Soil		1.8	25.9	13.9	51	0.2	18.0	6.8	251	2.63	17.1	1.1	5.6	1.4	12	0.1	1.1	0.3	48	0.07	0.058
KYS 110141	Soil		1.8	26.4	13.8	61	0.3	19.7	6.1	266	2.84	19.4	1.0	6.1	1.4	10	0.2	1.5	0.3	52	0.07	0.066
KYS 110142	Soil		1.4	26.1	12.1	47	0.3	18.0	5.3	197	2.29	19.3	1.2	8.2	4.4	13	0.1	1.7	0.3	40	0.07	0.052
KYS 110159	Soil		1.9	92.1	17.9	88	0.2	35.8	12.0	1614	3.12	21.7	1.1	26.2	3.4	11	0.2	3.3	0.3	43	0.06	0.071
KYS 110160	Soil		4.3	58.8	15.3	112	0.5	25.9	7.2	435	2.78	17.5	1.9	13.2	2.8	35	0.4	4.6	0.2	53	0.13	0.111
KYS 110161	Soil		1.0	44.8	10.6	66	<0.1	24.5	6.1	718	2.35	13.2	0.6	9.8	1.9	12	0.1	1.4	0.2	37	0.08	0.058
KYS 110162	Soil		1.1	44.4	10.7	64	0.1	21.8	6.5	755	2.25	12.7	0.7	16.9	1.7	12	0.2	1.4	0.2	38	0.08	0.062
KYS 110163	Soil		2.3	77.2	20.5	99	0.2	41.3	14.4	1732	3.44	20.8	1.3	10.0	1.7	22	0.3	2.1	0.3	50	0.18	0.104
KYS 110164	Soil		2.4	73.5	16.6	107	0.2	39.3	13.4	1287	2.91	14.5	1.3	25.1	5.1	13	0.5	1.7	0.3	38	0.09	0.063
KYS 110165	Soil		2.3	89.9	18.7	100	0.3	40.9	13.6	1505	3.39	18.1	1.3	12.7	1.0	18	0.2	1.5	0.4	52	0.12	0.120
KYS 110166	Soil		1.3	81.6	16.0	89	0.1	40.4	14.3	2045	2.65	16.8	1.1	41.7	4.0	15	0.2	1.7	0.3	42	0.10	0.076
KYS 110167	Soil		1.6	88.0	16.4	81	0.2	38.6	13.7	1730	2.85	19.2	1.1	15.7	3.0	15	0.1	1.6	0.3	42	0.10	0.073
KYS 110168	Soil		1.6	73.5	15.1	76	0.2	28.8	10.8	1230	2.77	18.3	1.1	16.2	0.4	16	0.3	1.5	0.3	48	0.11	0.134
KYS 110169	Soil		1.4	68.5	14.3	81	<0.1	32.3	14.3	1933	2.83	17.3	0.9	22.9	2.1	13	0.2	2.1	0.3	47	0.08	0.066
KYS 110170	Soil		1.5	64.9	15.2	67	0.2	29.5	10.8	1238	2.79	15.0	1.0	13.8	1.3	12	<0.1	1.6	0.3	48	0.09	0.077
KYS 110171	Soil		1.9	224.1	39.3	127	0.2	69.2	31.9	4912	4.21	27.0	1.0	35.7	6.1	34	0.2	7.8	0.4	36	0.16	0.096
KYS 110172	Soil		2.5	323.0	61.3	166	0.4	96.3	39.6	7277	4.59	43.7	1.5	35.3	9.0	41	0.4	16.9	0.6	35	0.15	0.109
KYS 110173	Soil		2.0	191.2	28.5	133	0.3	81.5	32.9	5238	4.02	25.7	1.8	26.5	4.9	23	0.2	6.7	0.4	34	0.05	0.075
KYS 110174	Soil		2.1	262.2	39.8	140	0.3	84.6	30.5	4395	4.86	356.6	2.3	50.3	6.3	34	<0.1	19.0	0.6	38	0.13	0.093
KYS 110175	Soil		2.1	200.2	46.1	133	1.0	62.6	29.7	5784	3.85	463.8	1.6	88.0	3.6	18	0.3	26.8	0.5	36	0.03	0.082
KYS 110176	Soil		1.3	62.4	23.6	103	0.3	40.3	13.4	761	3.63	25.7	1.5	10.4	2.5	14	<0.1	2.5	0.4	34	0.11	0.097
KYS 110177	Soil		2.1	69.5	63.1	159	0.4	66.8	28.6	2607	4.15	98.6	2.3	7.5	15.3	18	0.7	15.3	0.4	10	0.20	0.085

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110132	Soil	11	22	0.24	97	0.019	<1	1.28	0.004	0.03	0.1	0.05	1.4	<0.1	0.06	4	<0.5	<0.2
KYS 110133	Soil	10	22	0.36	149	0.024	<1	1.41	0.006	0.04	0.2	0.05	1.2	<0.1	0.12	4	1.2	<0.2
KYS 110134	Soil	10	20	0.37	100	0.033	<1	1.06	0.010	0.04	0.2	0.03	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 110135	Soil	11	26	0.44	117	0.028	1	1.74	0.005	0.04	0.2	0.06	1.9	<0.1	<0.05	4	0.9	<0.2
KYS 110136	Soil	10	20	0.19	54	0.021	1	1.13	0.005	0.03	0.2	0.05	0.7	<0.1	<0.05	6	0.6	<0.2
KYS 110137	Soil	10	20	0.27	72	0.024	<1	1.03	0.005	0.03	0.2	0.07	1.5	<0.1	<0.05	3	0.6	<0.2
KYS 110138	Soil	8	17	0.15	38	0.018	<1	0.76	0.004	0.03	0.1	0.06	0.6	<0.1	<0.05	4	0.7	<0.2
KYS 110139	Soil	10	24	0.26	74	0.022	<1	1.42	0.006	0.03	0.1	0.08	1.5	<0.1	<0.05	4	0.8	<0.2
KYS 110140	Soil	12	25	0.35	101	0.026	<1	1.44	0.006	0.04	0.2	0.07	1.6	<0.1	<0.05	5	0.8	<0.2
KYS 110141	Soil	11	27	0.33	98	0.027	1	1.53	0.006	0.04	0.2	0.06	1.5	<0.1	<0.05	5	0.7	<0.2
KYS 110142	Soil	12	22	0.28	91	0.027	1	1.20	0.004	0.03	0.2	0.05	2.1	<0.1	<0.05	4	0.6	<0.2
KYS 110159	Soil	26	22	0.45	133	0.022	2	1.55	0.003	0.04	<0.1	0.06	2.3	<0.1	<0.05	4	0.6	0.2
KYS 110160	Soil	18	22	0.40	732	0.030	<1	1.38	0.006	0.05	0.2	0.14	2.2	<0.1	<0.05	4	2.4	<0.2
KYS 110161	Soil	19	22	0.42	124	0.027	<1	1.30	0.005	0.04	0.1	0.03	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 110162	Soil	18	22	0.43	116	0.026	<1	1.30	0.005	0.04	0.1	0.04	1.4	<0.1	<0.05	4	0.7	<0.2
KYS 110163	Soil	17	29	0.47	215	0.023	1	1.70	0.008	0.06	0.1	0.07	2.0	0.1	<0.05	5	0.8	<0.2
KYS 110164	Soil	24	21	0.45	114	0.030	<1	1.31	0.004	0.04	0.1	0.07	1.9	<0.1	<0.05	4	1.1	<0.2
KYS 110165	Soil	16	33	0.51	266	0.018	2	1.97	0.008	0.06	0.2	0.11	1.7	<0.1	0.06	5	0.7	<0.2
KYS 110166	Soil	20	22	0.41	145	0.031	1	1.24	0.006	0.04	0.1	0.05	2.0	<0.1	<0.05	4	1.0	<0.2
KYS 110167	Soil	21	24	0.44	125	0.026	<1	1.28	0.004	0.04	0.1	0.07	1.9	<0.1	<0.05	4	0.6	<0.2
KYS 110168	Soil	15	26	0.40	185	0.020	1	1.45	0.008	0.06	0.2	0.10	1.1	<0.1	0.10	5	0.8	<0.2
KYS 110169	Soil	18	25	0.46	110	0.031	1	1.39	0.005	0.04	0.1	0.07	1.5	<0.1	<0.05	4	0.9	<0.2
KYS 110170	Soil	16	25	0.46	109	0.027	1	1.47	0.006	0.05	0.1	0.10	1.3	<0.1	<0.05	4	0.7	<0.2
KYS 110171	Soil	32	20	1.14	94	0.003	<1	2.13	0.004	0.04	<0.1	0.06	1.8	<0.1	<0.05	6	0.7	0.3
KYS 110172	Soil	34	22	0.75	110	0.005	<1	1.83	0.006	0.04	<0.1	0.13	2.1	<0.1	<0.05	5	1.0	0.7
KYS 110173	Soil	30	24	0.76	138	0.006	<1	1.81	0.005	0.03	<0.1	0.07	1.5	<0.1	<0.05	5	1.1	<0.2
KYS 110174	Soil	25	26	0.83	185	0.003	<1	2.27	0.006	0.06	<0.1	0.10	2.0	<0.1	<0.05	6	0.9	<0.2
KYS 110175	Soil	29	22	0.53	140	0.007	<1	1.50	0.006	0.04	<0.1	0.12	1.6	<0.1	<0.05	4	0.9	<0.2
KYS 110176	Soil	16	23	0.47	150	0.006	<1	1.64	0.006	0.06	<0.1	0.06	1.4	<0.1	<0.05	5	0.8	<0.2
KYS 110177	Soil	37	9	0.38	90	0.001	<1	0.92	0.003	0.05	<0.1	0.05	1.9	<0.1	<0.05	2	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110178	Soil	1.2	47.9	30.3	94	0.2	48.6	25.5	2258	3.72	27.7	1.6	0.8	7.6	17	0.3	4.8	0.3	19	0.20	0.093
KYS 110179	Soil	1.5	31.4	24.8	79	0.1	33.1	16.6	2132	3.67	49.9	2.1	7.6	2.4	9	0.2	10.3	0.3	25	0.09	0.081
KYS 110180	Soil	1.7	49.2	31.2	121	0.2	44.7	16.6	1368	3.66	20.5	2.0	3.7	3.3	24	0.4	3.9	0.3	26	0.40	0.092
KYS 110181	Soil	1.4	24.9	14.3	43	0.3	17.4	4.3	204	2.22	12.5	0.9	4.2	0.3	17	0.1	1.5	0.3	39	0.12	0.074
KYS 110182	Soil	2.0	37.8	18.2	61	0.6	19.4	5.5	278	2.85	16.0	1.1	11.0	0.5	13	0.2	1.9	0.4	43	0.05	0.079
KYS 110183	Soil	1.9	31.2	15.9	57	0.4	19.2	5.2	273	2.77	14.1	1.0	8.9	1.0	11	0.1	1.6	0.4	45	0.04	0.076
KYS 110184	Soil	2.0	31.0	18.7	68	0.2	18.7	6.3	313	3.26	13.5	1.0	5.5	1.9	10	0.1	1.5	0.4	44	0.04	0.069
KYS 110185	Soil	5.5	53.4	21.2	130	0.7	32.4	10.0	391	2.83	25.6	2.5	10.3	2.5	38	0.5	5.7	0.3	32	0.06	0.083
KYS 110186	Soil	3.5	35.2	20.9	81	0.3	27.6	7.9	268	2.89	17.2	1.6	11.3	2.1	17	0.3	2.3	0.3	34	0.05	0.073
KYS 110187	Soil	5.0	49.7	22.6	114	0.4	40.3	13.2	505	3.32	19.9	1.9	7.3	4.9	18	0.5	2.6	0.3	37	0.07	0.086
KYS 110188	Soil	1.9	44.9	20.4	94	<0.1	34.0	11.6	799	3.50	72.0	1.1	8.8	3.6	10	0.1	8.5	0.3	23	0.03	0.060
KYS 110189	Soil	2.2	40.9	20.4	96	0.2	32.9	13.3	814	3.42	48.0	1.4	8.4	3.8	10	0.2	4.6	0.3	23	0.06	0.061
KYS 110190	Soil	9.0	32.4	23.2	90	0.7	22.9	5.0	175	3.05	27.7	1.8	10.2	1.1	12	0.2	4.7	0.4	50	0.05	0.094
KYS 110191	Soil	14.3	39.2	26.5	119	1.0	27.9	5.0	149	2.73	41.4	2.2	7.5	3.1	20	0.2	11.4	0.4	39	0.03	0.105
KYS 110192	Soil	10.2	43.9	30.6	129	1.1	28.3	5.5	227	3.63	33.2	1.6	12.5	1.0	15	0.2	5.6	0.6	34	0.03	0.100
KYS 110193	Soil	3.9	68.4	33.5	138	0.7	39.8	7.6	267	4.36	79.2	2.1	23.8	3.5	13	0.2	14.6	0.6	25	0.03	0.105
KYS 110194	Soil	12.2	25.7	20.1	71	0.9	15.0	3.6	185	2.20	19.1	1.3	8.0	1.3	6	0.2	5.0	0.3	35	0.04	0.067
KYS 110195	Soil	14.5	34.6	21.2	86	0.8	20.9	4.9	222	2.79	30.4	2.1	7.7	5.1	11	0.2	7.4	0.3	43	0.07	0.089
KYS 110196	Soil	4.8	22.8	18.0	53	0.4	14.3	4.0	173	2.49	21.9	1.1	3.2	1.5	7	0.1	2.6	0.3	49	0.04	0.058
KYS 110197	Soil	3.8	35.8	16.1	82	0.5	25.4	8.8	337	2.66	21.5	1.5	10.6	3.8	11	0.3	2.9	0.2	36	0.08	0.078
KYS 110198	Soil	4.1	49.6	20.7	84	0.6	29.0	5.1	218	2.65	45.0	1.7	25.6	2.5	11	0.2	6.0	0.4	28	0.08	0.090
KYS 110199	Soil	6.4	39.2	25.3	89	0.7	21.6	5.4	307	3.39	30.0	1.9	12.1	1.7	13	0.1	4.6	0.5	39	0.06	0.134
KYS 110200	Soil	4.7	36.4	25.5	83	0.7	16.5	3.5	126	2.44	111.0	1.9	36.7	1.5	11	0.3	6.1	0.4	25	0.03	0.097
KYS 110201	Soil	28.4	68.2	33.7	292	1.3	55.0	11.7	534	3.86	450.8	5.0	68.6	0.9	28	3.8	34.5	0.4	52	0.02	0.133
KYS 110202	Soil	6.4	51.7	32.2	129	0.5	32.9	8.0	240	3.77	17.5	2.1	13.5	4.7	14	1.5	4.2	0.4	23	0.04	0.089
KYS 110203	Soil	34.4	81.6	31.6	369	1.6	73.5	13.7	389	4.25	84.1	7.1	23.5	4.6	25	3.5	18.6	0.4	53	0.02	0.119
KYS 110204	Soil	34.9	43.1	26.6	198	0.8	38.3	8.6	380	3.62	52.2	3.9	7.6	1.3	16	0.8	9.3	0.3	58	0.01	0.102
KYS 110205	Soil	1.6	18.7	15.5	43	0.3	13.6	4.1	172	3.66	18.6	0.6	3.4	3.9	8	0.2	1.3	0.3	67	0.06	0.058
KYS 110206	Soil	1.5	29.1	15.3	59	0.4	22.2	5.7	170	2.48	15.0	1.1	3.8	0.3	10	0.3	1.4	0.3	33	0.06	0.080
KYS 110207	Soil	1.5	13.8	12.4	32	0.4	8.2	2.4	112	1.66	13.8	0.7	2.5	0.1	12	0.2	1.3	0.3	35	0.04	0.079

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110178	Soil	26	23	0.53	126	0.005	<1	1.28	0.006	0.07	<0.1	0.05	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110179	Soil	19	16	0.27	97	0.006	<1	1.06	0.003	0.04	0.1	0.04	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 110180	Soil	20	19	0.50	140	0.010	2	1.31	0.005	0.06	0.1	0.05	1.4	<0.1	0.07	4	0.7	<0.2
KYS 110181	Soil	12	20	0.25	109	0.011	<1	1.02	0.006	0.04	0.1	0.05	0.5	<0.1	0.06	4	0.9	0.3
KYS 110182	Soil	12	24	0.29	87	0.014	1	1.27	0.005	0.05	<0.1	0.08	1.0	<0.1	0.06	5	2.0	<0.2
KYS 110183	Soil	14	24	0.25	66	0.018	<1	1.26	0.004	0.04	<0.1	0.08	1.0	<0.1	<0.05	5	1.2	<0.2
KYS 110184	Soil	15	24	0.23	68	0.021	<1	1.31	0.004	0.04	0.1	0.07	0.9	<0.1	0.07	5	1.4	<0.2
KYS 110185	Soil	15	17	0.21	141	0.015	1	1.05	0.004	0.03	0.1	0.13	1.2	<0.1	0.06	3	3.1	<0.2
KYS 110186	Soil	15	20	0.27	107	0.016	<1	1.15	0.005	0.03	0.1	0.09	1.1	<0.1	<0.05	4	2.1	<0.2
KYS 110187	Soil	16	22	0.34	127	0.017	<1	1.52	0.004	0.04	0.2	0.16	1.9	<0.1	<0.05	3	2.4	<0.2
KYS 110188	Soil	24	18	0.42	79	0.005	<1	1.24	0.003	0.04	<0.1	0.03	1.0	<0.1	<0.05	4	0.9	<0.2
KYS 110189	Soil	22	20	0.48	118	0.006	<1	1.43	0.004	0.05	<0.1	0.05	1.1	<0.1	<0.05	4	1.2	<0.2
KYS 110190	Soil	13	22	0.27	378	0.015	1	1.23	0.005	0.06	0.2	0.16	1.2	0.1	<0.05	4	1.8	<0.2
KYS 110191	Soil	12	13	0.13	842	0.005	<1	0.69	0.005	0.06	0.2	0.22	1.3	0.1	0.06	2	4.4	0.2
KYS 110192	Soil	11	18	0.16	185	0.008	<1	0.77	0.007	0.05	0.1	0.13	0.9	<0.1	<0.05	3	5.0	0.2
KYS 110193	Soil	11	14	0.10	131	0.004	<1	0.62	0.010	0.04	0.1	0.09	2.1	<0.1	<0.05	2	3.1	<0.2
KYS 110194	Soil	9	11	0.10	180	0.009	<1	0.60	0.004	0.03	0.2	0.18	0.7	<0.1	<0.05	2	3.1	<0.2
KYS 110195	Soil	12	17	0.21	246	0.020	<1	0.82	0.005	0.04	0.2	0.28	1.8	<0.1	<0.05	3	3.6	<0.2
KYS 110196	Soil	12	18	0.18	100	0.019	<1	1.11	0.004	0.04	0.1	0.09	1.1	<0.1	<0.05	5	1.9	<0.2
KYS 110197	Soil	12	21	0.34	145	0.024	1	1.34	0.005	0.04	0.2	0.13	2.0	<0.1	<0.05	3	1.9	<0.2
KYS 110198	Soil	10	16	0.19	117	0.013	<1	0.86	0.006	0.03	0.1	0.10	1.7	<0.1	<0.05	2	2.3	<0.2
KYS 110199	Soil	11	20	0.24	160	0.011	<1	1.02	0.007	0.04	0.1	0.10	1.3	<0.1	<0.05	4	3.1	<0.2
KYS 110200	Soil	13	12	0.12	222	0.004	2	0.63	0.005	0.03	0.1	0.08	1.5	<0.1	<0.05	2	3.3	<0.2
KYS 110201	Soil	9	12	0.06	272	0.006	<1	0.59	0.004	0.06	0.2	0.43	0.6	0.2	<0.05	2	5.3	0.2
KYS 110202	Soil	19	17	0.32	711	0.003	<1	0.92	0.005	0.05	<0.1	0.08	1.1	<0.1	0.08	2	2.4	0.4
KYS 110203	Soil	12	8	0.07	329	0.002	<1	0.43	0.003	0.08	0.2	0.71	1.2	0.3	0.18	1	7.4	0.3
KYS 110204	Soil	12	13	0.20	343	0.003	1	0.56	0.004	0.07	0.2	0.51	0.5	0.2	0.15	2	7.0	0.3
KYS 110205	Soil	11	23	0.21	52	0.045	<1	1.33	0.004	0.03	0.2	0.05	1.6	<0.1	<0.05	7	0.6	<0.2
KYS 110206	Soil	10	18	0.20	79	0.010	<1	1.22	0.005	0.03	<0.1	0.06	0.5	<0.1	<0.05	4	0.9	<0.2
KYS 110207	Soil	8	15	0.11	76	0.006	<1	0.73	0.005	0.03	<0.1	0.05	0.2	<0.1	<0.05	4	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110208	Soil		1.0	19.3	12.0	29	0.7	6.8	1.5	59	0.94	8.2	0.7	1.5	0.1	12	0.3	0.8	0.2	26	0.05	0.098
KYS 110209	Soil		1.1	11.3	11.2	24	0.5	6.2	1.7	58	1.47	14.4	0.7	3.0	0.2	10	0.2	0.8	0.3	35	0.05	0.071
KYS 110210	Soil		1.8	22.0	12.7	43	0.3	14.9	3.7	160	2.41	24.3	1.0	7.9	1.6	14	0.2	2.5	0.3	34	0.07	0.071
KYS 110211	Soil		1.6	38.5	13.6	56	0.3	18.5	5.5	227	2.52	20.4	1.6	10.5	0.7	11	0.3	1.5	0.3	42	0.06	0.073
KYS 110212	Soil		1.8	21.3	16.9	46	0.4	14.6	3.9	149	2.48	24.8	1.2	4.9	0.8	12	0.3	1.9	0.3	41	0.05	0.064
KYS 110213	Soil		1.3	21.2	11.2	57	0.3	15.7	5.0	188	2.21	19.0	0.9	2.0	0.9	11	0.1	1.4	0.2	38	0.06	0.081
KYS 110214	Soil		1.8	29.0	16.1	54	0.3	18.3	4.6	164	2.42	23.6	1.0	9.6	2.1	13	0.2	1.7	0.3	38	0.05	0.060
KYS 110215	Soil		1.6	17.2	13.4	53	0.3	14.9	5.0	221	2.66	18.5	0.9	3.7	1.3	11	0.2	1.3	0.3	43	0.06	0.080
KYS 110216	Soil		1.7	14.7	15.0	63	0.3	16.1	5.9	329	2.97	15.2	0.8	1.2	0.3	10	0.7	1.0	0.3	53	0.06	0.090
KYS 110217	Soil		1.2	15.0	10.5	38	0.4	12.0	4.1	156	2.49	14.2	0.7	25.1	2.7	10	0.2	1.0	0.2	44	0.07	0.065
KYS 110218	Soil		1.3	9.9	12.3	48	0.4	10.2	3.8	195	2.29	14.0	0.6	4.8	1.2	9	0.2	0.8	0.3	48	0.06	0.053
KYS 110219	Soil		1.9	18.1	16.6	42	0.5	13.9	3.4	115	2.43	17.5	0.7	2.5	3.0	10	0.4	1.5	0.3	40	0.07	0.107
KYS 110220	Soil		1.3	12.8	11.3	43	0.2	13.0	4.4	214	1.99	12.3	0.6	8.2	0.9	7	0.2	0.8	0.2	44	0.05	0.049
KYS 110221	Soil		1.3	14.2	11.1	51	0.1	13.3	4.4	170	2.30	13.7	0.6	4.5	2.1	7	0.2	0.7	0.2	47	0.06	0.048
KYS 110222	Soil		1.3	11.4	12.9	28	0.6	8.6	2.3	82	1.81	10.4	0.5	7.5	1.2	6	0.2	0.6	0.2	50	0.05	0.036
KYS 110223	Soil		1.2	11.9	10.8	40	0.1	10.8	3.7	140	1.75	12.2	0.6	3.8	0.7	7	0.1	0.7	0.2	39	0.06	0.057
KYS 110224	Soil		1.6	81.5	22.7	103	0.4	45.7	15.3	1119	3.32	22.6	1.5	13.3	5.5	12	0.2	2.1	0.4	36	0.07	0.089
KYS 110225	Soil		1.6	77.3	18.8	99	0.2	46.7	16.0	1827	3.20	16.7	1.1	24.0	6.1	13	0.2	2.0	0.3	36	0.09	0.070
KYS 110226	Soil		1.2	48.3	11.4	102	0.3	38.3	15.7	1090	2.34	57.5	2.1	6.0	2.1	17	0.8	1.1	0.2	34	0.31	0.095
KYS 110234	Soil		1.7	14.8	12.3	40	0.2	11.3	4.2	210	2.79	14.7	0.7	12.4	2.4	6	0.1	0.7	0.3	57	0.05	0.045
KYS 110235	Soil		1.4	15.7	11.8	42	<0.1	14.2	5.5	255	2.07	14.3	0.6	5.2	1.3	9	0.1	0.9	0.2	42	0.07	0.059
KYS 110236	Soil		1.5	10.9	9.3	32	0.4	9.2	3.3	144	1.91	11.6	0.5	5.0	1.1	7	0.1	0.7	0.2	45	0.05	0.039
KYS 110237	Soil		1.4	32.4	11.6	56	0.2	18.8	6.6	278	2.38	31.8	1.1	17.1	2.6	10	0.2	1.5	0.2	42	0.08	0.068
KYS 110238	Soil		1.3	34.5	11.0	50	0.1	20.8	5.6	177	2.13	17.0	0.9	18.6	3.7	11	0.1	1.5	0.2	37	0.11	0.064
KYS 110239	Soil		16.4	45.4	27.6	98	1.0	11.1	2.4	127	4.11	26.9	2.1	8.9	3.6	12	0.2	4.5	0.5	49	0.02	0.116
KYS 110240	Soil		12.7	51.6	29.6	112	0.7	20.8	5.6	224	4.04	33.3	3.1	5.7	6.6	16	0.2	2.8	0.4	45	0.02	0.091
KYS 110241	Soil		12.6	98.6	30.2	76	0.6	13.5	2.1	92	2.96	13.2	4.8	5.1	1.1	27	0.5	2.2	0.4	52	0.04	0.146
KYS 110242	Soil		8.7	41.1	23.6	63	0.6	12.5	2.8	123	3.10	18.3	1.6	4.0	2.5	22	0.2	2.0	0.4	54	0.03	0.112
KYS 110243	Soil		0.8	46.3	19.5	99	0.2	37.3	14.1	1277	2.88	24.1	2.0	2.1	2.1	25	0.8	0.6	0.3	13	0.52	0.075
KYS 110244	Soil		4.0	35.7	21.1	62	0.4	13.6	3.7	149	3.31	13.2	1.5	2.6	2.0	9	0.1	1.3	0.3	33	0.03	0.070

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110208	Soil	7	10	0.05	113	0.004	<1	0.62	0.008	0.03	<0.1	0.05	0.2	<0.1	<0.05	4	0.5	<0.2
KYS 110209	Soil	8	15	0.09	81	0.008	<1	0.74	0.006	0.03	<0.1	0.05	0.2	0.1	<0.05	5	0.7	<0.2
KYS 110210	Soil	10	20	0.22	68	0.018	<1	1.02	0.004	0.03	0.2	0.08	1.2	<0.1	<0.05	3	1.0	<0.2
KYS 110211	Soil	12	24	0.31	109	0.018	<1	1.61	0.005	0.04	0.2	0.06	1.4	<0.1	<0.05	5	0.9	<0.2
KYS 110212	Soil	10	21	0.25	112	0.015	<1	1.43	0.004	0.04	0.2	0.07	1.3	<0.1	<0.05	5	1.0	0.2
KYS 110213	Soil	10	18	0.28	94	0.020	<1	1.20	0.005	0.04	0.2	0.07	1.3	<0.1	<0.05	4	0.8	<0.2
KYS 110214	Soil	10	19	0.26	140	0.020	<1	1.15	0.006	0.03	0.1	0.05	1.8	<0.1	<0.05	4	1.1	<0.2
KYS 110215	Soil	11	23	0.28	97	0.021	<1	1.32	0.004	0.04	0.2	0.06	1.2	<0.1	<0.05	5	1.2	<0.2
KYS 110216	Soil	10	24	0.31	150	0.018	<1	1.37	0.006	0.04	0.2	0.08	0.8	0.1	0.06	6	0.7	<0.2
KYS 110217	Soil	14	22	0.24	98	0.027	<1	1.20	0.004	0.03	0.2	0.05	1.5	<0.1	<0.05	5	0.5	0.3
KYS 110218	Soil	12	21	0.24	89	0.023	1	1.19	0.006	0.04	0.2	0.05	1.2	<0.1	<0.05	6	0.5	<0.2
KYS 110219	Soil	10	19	0.25	107	0.023	<1	1.09	0.006	0.04	0.2	0.05	1.4	<0.1	<0.05	5	0.6	<0.2
KYS 110220	Soil	11	17	0.19	117	0.014	1	0.91	0.005	0.04	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110221	Soil	11	20	0.26	88	0.016	2	1.31	0.004	0.03	0.1	0.05	1.3	<0.1	<0.05	4	0.5	<0.2
KYS 110222	Soil	9	17	0.13	90	0.016	1	0.81	0.005	0.03	<0.1	0.03	1.1	<0.1	<0.05	5	<0.5	<0.2
KYS 110223	Soil	10	17	0.20	78	0.012	1	0.93	0.004	0.03	0.1	0.05	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110224	Soil	17	32	0.45	108	0.011	1	1.59	0.005	0.04	<0.1	0.06	1.9	<0.1	<0.05	4	1.0	<0.2
KYS 110225	Soil	20	23	0.51	126	0.017	1	1.37	0.003	0.04	<0.1	0.05	2.1	<0.1	<0.05	3	0.7	0.2
KYS 110226	Soil	11	25	0.38	145	0.015	1	1.20	0.004	0.04	0.1	0.04	1.9	<0.1	<0.05	3	1.1	<0.2
KYS 110234	Soil	10	23	0.24	60	0.018	1	1.31	0.005	0.03	0.2	0.06	1.5	<0.1	<0.05	6	0.7	<0.2
KYS 110235	Soil	11	18	0.28	74	0.017	1	1.10	0.006	0.04	<0.1	0.03	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110236	Soil	11	18	0.17	63	0.015	1	0.95	0.005	0.03	0.1	0.04	1.1	<0.1	<0.05	5	<0.5	<0.2
KYS 110237	Soil	13	22	0.30	69	0.023	1	1.28	0.005	0.04	0.2	0.05	1.8	0.1	<0.05	4	0.6	<0.2
KYS 110238	Soil	12	20	0.28	69	0.023	1	1.08	0.004	0.03	0.1	0.04	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 110239	Soil	30	18	0.28	88	0.002	<1	0.80	0.005	0.04	<0.1	0.19	0.7	<0.1	0.10	3	7.5	0.3
KYS 110240	Soil	32	18	0.31	121	0.002	<1	1.08	0.008	0.06	<0.1	0.16	1.0	0.1	0.10	3	3.6	<0.2
KYS 110241	Soil	26	18	0.20	231	0.002	<1	0.91	0.007	0.08	<0.1	0.12	0.4	<0.1	0.14	3	4.0	<0.2
KYS 110242	Soil	28	22	0.21	107	0.008	<1	0.93	0.004	0.05	<0.1	0.08	0.8	0.1	<0.05	4	2.6	<0.2
KYS 110243	Soil	9	17	0.51	114	0.005	1	1.24	0.006	0.06	<0.1	0.06	1.1	<0.1	0.07	3	<0.5	<0.2
KYS 110244	Soil	19	18	0.26	76	0.005	1	1.01	0.004	0.04	<0.1	0.04	0.7	<0.1	<0.05	4	1.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110245	Soil	3.9	36.2	24.7	68	0.4	15.5	4.6	197	3.74	15.5	1.4	3.7	3.9	10	<0.1	1.4	0.4	32	0.02	0.063
KYS 110246	Soil	8.9	53.0	24.3	88	0.3	20.9	7.8	324	4.13	19.3	3.3	11.0	5.7	14	0.2	2.3	0.4	38	0.03	0.104
KYS 110247	Soil	1.3	61.6	12.6	68	<0.1	29.5	10.7	850	2.71	13.4	0.8	9.7	3.7	11	0.2	1.0	0.2	47	0.11	0.051
KYS 110248	Soil	1.4	41.3	13.7	65	<0.1	25.2	9.5	721	2.77	11.9	0.6	11.2	2.5	9	0.2	0.8	0.2	49	0.09	0.052
KYS 110249	Soil	1.5	37.0	12.9	69	<0.1	20.5	8.2	478	2.73	11.4	0.6	6.6	2.8	11	0.2	1.0	0.2	52	0.10	0.053
KYS 110250	Soil	1.3	42.7	12.0	56	<0.1	20.9	7.4	376	2.60	10.9	0.6	11.5	2.8	9	<0.1	0.8	0.2	44	0.08	0.044
KYS 110251	Soil	1.6	65.4	15.3	74	0.3	25.7	8.0	697	3.06	14.2	0.8	14.0	1.0	14	0.2	1.2	0.3	51	0.07	0.093
KYS 110252	Soil	1.3	88.1	14.7	95	0.2	44.2	10.2	1184	2.51	12.5	0.9	24.0	6.1	16	0.2	1.1	0.2	36	0.13	0.074
KYS 110253	Soil	1.5	122.8	14.9	99	0.1	49.3	18.1	2422	2.86	17.2	1.1	34.6	4.7	20	0.3	1.5	0.2	43	0.17	0.096
KYS 110254	Soil	1.6	151.3	20.0	115	0.1	61.1	22.1	4246	3.37	17.5	1.2	29.2	5.8	25	0.3	1.3	0.3	44	0.16	0.103
KYS 110255	Soil	1.9	157.7	19.5	154	0.4	123.6	58.1	4827	3.33	13.9	2.6	53.6	5.4	20	0.3	1.3	0.3	41	0.09	0.081
KYS 110256	Soil	1.5	81.0	18.2	92	0.2	46.0	14.8	1566	2.96	12.4	1.1	16.0	3.1	13	0.1	1.1	0.3	38	0.06	0.065
KYS 110257	Soil	1.7	54.1	17.2	92	0.2	39.4	13.9	1280	3.28	14.7	1.1	15.5	2.2	14	0.2	2.1	0.3	48	0.07	0.072
KYS 110258	Soil	2.5	202.2	30.2	155	0.4	98.9	45.1	6040	4.05	173.6	2.7	65.7	7.9	25	0.4	11.1	0.4	38	0.05	0.083
KYS 110259	Soil	2.0	273.4	126.4	151	1.5	114.3	52.5	8339	3.76	163.2	1.8	49.5	12.6	20	0.4	29.1	0.6	26	0.03	0.066
KYS 110260	Soil	2.4	305.9	74.3	176	0.9	146.7	55.3	>10000	4.32	167.8	1.5	54.6	10.7	38	0.5	21.1	1.2	27	0.17	0.077
KYS 110261	Soil	3.1	339.5	70.9	173	0.8	121.4	65.6	9956	5.31	335.2	1.8	69.2	10.9	27	0.3	46.7	0.7	33	0.04	0.109
KYS 110262	Soil	2.6	209.7	40.5	149	0.7	81.3	33.9	3276	4.79	58.9	1.6	39.0	5.9	18	0.2	10.1	0.5	39	0.10	0.140
KYS 110263	Soil	1.7	62.0	35.8	107	0.2	38.9	18.1	561	4.43	21.0	1.4	3.5	9.5	11	<0.1	4.9	0.6	15	0.13	0.040
KYS 110264	Soil	0.5	39.5	33.3	87	0.2	31.4	16.3	820	3.82	55.6	1.1	11.6	8.4	9	<0.1	7.2	0.4	9	0.14	0.036
KYS 110265	Soil	1.5	89.7	18.5	111	0.2	45.0	15.3	2053	3.29	44.9	1.0	17.8	4.3	12	0.2	10.1	0.3	36	0.06	0.076
KYS 110266	Soil	1.8	77.1	20.8	115	0.2	43.4	15.0	1676	3.50	157.2	1.1	22.9	1.5	17	0.2	5.3	0.4	44	0.15	0.088
KYS 110267	Soil	1.3	19.7	15.4	67	0.1	15.6	6.0	587	2.68	48.1	0.6	4.5	0.4	20	0.3	2.7	0.3	38	0.38	0.099
KYS 110268	Soil	1.6	66.0	34.1	100	0.2	38.8	17.0	549	4.17	20.9	1.5	3.3	9.1	14	0.1	5.0	0.5	15	0.18	0.044
KYS 110269	Soil	0.7	17.5	17.8	52	0.1	16.9	7.6	589	2.55	30.8	0.8	3.3	1.9	28	0.1	0.9	0.2	24	0.42	0.090
KYS 110270	Soil	0.7	29.7	25.0	70	0.1	28.0	12.8	1238	3.06	107.1	1.3	13.6	3.4	33	0.2	2.1	0.3	15	0.52	0.083
KYS 110271	Soil	0.6	21.2	18.3	60	<0.1	27.0	11.9	717	2.79	53.2	0.8	5.2	4.6	18	0.1	1.2	0.2	19	0.27	0.065
KYS 110272	Soil	0.8	33.8	28.2	85	0.1	46.3	20.5	2067	3.43	21.0	1.4	10.8	6.8	27	0.4	1.0	0.3	23	0.39	0.063
KYS 110273	Soil	0.8	43.1	26.5	74	<0.1	50.7	22.1	1804	3.62	12.7	1.5	2.7	10.8	23	0.2	0.5	0.3	18	0.27	0.065
KYS 110274	Soil	0.5	36.4	23.1	67	<0.1	41.5	17.8	807	3.37	28.0	1.4	3.1	8.0	24	0.1	0.7	0.2	28	0.33	0.062

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110245	Soil	21	20	0.38	72	0.004	<1	1.19	0.004	0.05	<0.1	0.05	0.8	<0.1	<0.05	4	1.3	<0.2
KYS 110246	Soil	21	23	0.33	96	0.006	<1	1.26	0.004	0.05	<0.1	0.08	1.2	<0.1	0.06	3	2.7	<0.2
KYS 110247	Soil	16	26	0.47	108	0.029	1	1.53	0.006	0.04	0.2	0.04	2.1	<0.1	<0.05	4	<0.5	<0.2
KYS 110248	Soil	12	27	0.42	97	0.027	2	1.52	0.006	0.04	0.1	0.04	1.9	0.1	<0.05	5	<0.5	<0.2
KYS 110249	Soil	14	25	0.43	87	0.029	1	1.42	0.007	0.04	0.2	0.05	1.8	0.1	<0.05	5	0.5	<0.2
KYS 110250	Soil	14	24	0.44	81	0.028	1	1.29	0.006	0.04	0.1	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 110251	Soil	16	26	0.36	115	0.017	2	1.31	0.006	0.04	0.1	0.08	1.2	<0.1	0.05	5	0.7	<0.2
KYS 110252	Soil	20	22	0.41	81	0.027	1	1.13	0.006	0.03	0.1	0.07	1.8	<0.1	<0.05	3	0.7	<0.2
KYS 110253	Soil	20	24	0.51	118	0.028	1	1.45	0.005	0.03	0.2	0.06	2.0	<0.1	<0.05	4	0.9	<0.2
KYS 110254	Soil	25	24	0.60	135	0.023	<1	1.62	0.005	0.04	0.1	0.08	2.4	<0.1	<0.05	5	0.8	<0.2
KYS 110255	Soil	27	24	0.46	151	0.020	1	1.50	0.005	0.04	0.1	0.09	2.2	<0.1	<0.05	4	0.7	<0.2
KYS 110256	Soil	22	25	0.47	102	0.013	<1	1.34	0.006	0.03	0.1	0.08	1.4	<0.1	<0.05	4	0.7	<0.2
KYS 110257	Soil	19	30	0.46	116	0.018	1	1.57	0.006	0.05	0.1	0.09	1.6	<0.1	<0.05	5	0.7	<0.2
KYS 110258	Soil	31	25	0.47	131	0.012	<1	1.49	0.005	0.04	0.1	0.08	2.3	<0.1	<0.05	4	0.9	0.3
KYS 110259	Soil	38	20	0.52	83	0.006	<1	1.31	0.005	0.03	<0.1	0.06	2.0	<0.1	<0.05	4	0.6	<0.2
KYS 110260	Soil	31	17	0.57	89	0.002	<1	1.27	0.004	0.03	<0.1	0.08	2.3	<0.1	<0.05	3	1.0	<0.2
KYS 110261	Soil	33	23	0.60	103	0.003	<1	1.69	0.005	0.04	<0.1	0.09	2.8	<0.1	<0.05	5	1.3	0.4
KYS 110262	Soil	21	30	0.58	109	0.008	<1	1.86	0.007	0.04	<0.1	0.15	2.5	<0.1	<0.05	5	1.7	0.4
KYS 110263	Soil	17	20	0.76	80	0.003	1	1.79	0.007	0.08	<0.1	0.05	1.2	<0.1	<0.05	5	0.6	<0.2
KYS 110264	Soil	18	14	0.48	58	0.001	<1	1.17	0.005	0.08	<0.1	0.04	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 110265	Soil	22	23	0.47	117	0.018	1	1.38	0.005	0.04	0.2	0.06	2.2	<0.1	<0.05	4	0.5	<0.2
KYS 110266	Soil	20	30	0.55	180	0.012	1	1.65	0.006	0.05	0.2	0.05	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 110267	Soil	12	18	0.31	266	0.008	<1	1.14	0.005	0.06	<0.1	0.03	0.5	<0.1	<0.05	5	<0.5	<0.2
KYS 110268	Soil	16	19	0.77	79	0.003	<1	1.76	0.004	0.08	<0.1	0.05	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 110269	Soil	11	18	0.38	198	0.005	<1	1.24	0.005	0.09	0.1	0.02	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110270	Soil	14	17	0.43	132	0.004	<1	1.16	0.005	0.10	<0.1	0.04	1.2	<0.1	0.05	3	<0.5	<0.2
KYS 110271	Soil	17	17	0.48	104	0.006	1	1.08	0.003	0.09	0.1	0.03	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 110272	Soil	21	20	0.53	145	0.009	1	1.30	0.005	0.09	0.2	0.06	2.3	<0.1	<0.05	3	<0.5	<0.2
KYS 110273	Soil	24	29	0.82	95	0.008	1	1.40	0.006	0.11	<0.1	0.04	2.4	<0.1	<0.05	4	<0.5	<0.2
KYS 110274	Soil	19	50	1.07	112	0.012	1	1.60	0.004	0.12	<0.1	0.04	2.5	<0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110275	Soil		0.4	34.4	18.1	66	<0.1	41.7	20.4	781	3.45	35.0	1.4	4.0	9.4	16	0.1	1.1	0.1	31	0.22	0.073
KYS 110276	Soil		0.6	42.4	16.6	93	0.1	52.5	20.1	710	4.16	45.5	1.3	10.0	8.0	24	<0.1	2.8	0.2	43	0.26	0.073
KYS 110277	Soil		1.0	54.3	21.8	103	0.2	44.3	18.9	1049	3.59	36.3	1.5	4.9	11.3	16	0.2	3.3	0.3	19	0.14	0.067
KYS 110278	Soil		1.6	65.7	23.8	129	0.3	58.2	22.0	1408	3.85	33.5	1.7	10.9	9.6	16	0.3	2.2	0.3	24	0.13	0.069
KYS 110279	Soil		1.5	91.9	21.0	125	0.3	55.9	17.5	2035	3.37	21.3	1.1	24.2	7.4	12	0.2	2.0	0.3	27	0.06	0.057
KYS 110280	Soil		2.0	89.4	29.7	126	0.5	56.5	22.2	1787	4.40	51.3	1.6	11.3	7.7	17	0.2	2.7	0.4	26	0.14	0.075
KYS 110281	Soil		1.4	79.8	42.2	113	0.4	49.8	20.8	1686	3.60	87.0	1.3	19.4	10.5	18	0.3	9.9	0.3	21	0.20	0.070
KYS 110282	Soil		1.6	115.5	22.6	117	0.2	62.9	25.2	3062	3.76	20.1	1.3	17.2	8.9	17	0.2	2.2	0.3	24	0.13	0.067
KYS 110283	Soil		2.0	123.6	26.1	120	0.3	64.6	27.1	3379	3.93	27.5	1.3	18.1	8.6	25	0.2	4.1	0.3	26	0.18	0.080
KYS 110284	Soil		1.3	90.0	27.3	115	0.2	57.1	22.6	2096	3.54	20.6	1.6	54.4	10.3	17	0.2	3.2	0.3	22	0.11	0.065
KYS 110285	Soil		1.5	100.0	29.5	115	0.2	58.7	23.9	2192	3.85	27.7	1.5	15.6	9.7	18	0.2	3.3	0.4	23	0.12	0.061
KYS 110286	Soil		1.8	105.6	23.8	144	0.4	69.4	21.9	2224	3.76	17.2	1.3	15.7	5.8	22	0.2	2.4	0.4	31	0.08	0.062
KYS 110287	Soil		1.5	98.7	33.4	132	0.3	73.2	27.8	2589	3.73	23.3	1.8	13.2	10.1	18	0.1	3.2	0.4	23	0.10	0.056
KYS 110288	Soil		2.5	121.5	29.5	156	0.5	79.7	27.1	2539	4.15	49.9	1.6	21.3	8.3	19	0.5	7.9	0.4	28	0.09	0.070
KYS 110289	Soil		1.9	112.6	25.8	136	0.5	69.0	23.2	2721	3.99	237.2	1.4	25.0	8.7	17	0.2	9.2	0.4	29	0.06	0.064
KYS 110290	Soil		1.3	84.3	29.5	115	0.3	54.3	25.3	1934	3.96	218.2	1.7	22.8	13.0	18	0.2	13.7	0.3	17	0.16	0.073
KYS 110291	Soil		2.7	96.4	29.9	117	0.8	62.0	25.9	1993	4.37	643.5	1.8	46.4	9.0	28	0.3	21.9	0.3	19	0.23	0.109
KYS 110292	Soil		1.9	63.2	28.5	93	0.3	40.1	19.4	982	3.77	55.4	1.5	6.4	12.5	19	0.3	8.2	0.2	16	0.32	0.149
KYS 110293	Soil		3.1	76.3	88.3	120	0.7	44.3	16.9	1206	3.85	200.2	1.8	27.0	5.6	22	0.8	28.1	0.3	23	0.26	0.123
KYS 110294	Soil		2.5	60.9	53.5	127	0.7	37.7	14.2	854	3.57	205.3	1.8	32.6	7.9	15	0.7	24.8	0.3	19	0.20	0.102
KYS 110295	Soil		1.9	63.4	29.0	95	0.2	39.4	18.9	814	3.90	18.1	1.7	2.8	9.3	18	0.2	2.8	0.3	18	0.24	0.084
KYS 110296	Soil		0.9	46.1	56.8	83	0.2	23.1	16.0	635	3.94	121.0	1.8	5.2	6.4	38	0.2	23.9	0.5	10	0.11	0.095
KYS 110297	Soil		1.4	43.2	22.7	87	<0.1	32.2	16.4	661	3.93	55.7	1.0	4.4	7.8	9	<0.1	13.4	0.3	19	0.07	0.055
KYS 110298	Soil		1.1	41.6	38.5	100	<0.1	32.2	17.4	816	3.98	23.9	1.5	1.1	3.3	8	0.2	4.9	0.5	17	0.06	0.068
KYS 110299	Soil		9.1	54.9	29.2	134	0.3	38.7	14.1	563	4.11	298.8	2.2	30.1	8.4	17	0.8	111.0	0.3	29	0.17	0.074
KYS 110300	Soil		3.7	43.9	21.1	92	0.1	28.5	12.6	582	3.95	256.8	1.4	24.1	6.9	10	0.2	60.0	0.3	23	0.18	0.071
KYS 110301	Soil		4.7	91.6	32.6	167	0.2	73.2	26.1	1107	4.98	221.7	2.4	20.1	9.9	21	1.0	81.2	0.4	29	0.21	0.092
KYS 110302	Soil		2.3	24.4	27.4	75	<0.1	23.1	15.0	723	3.92	174.7	1.1	8.4	6.2	9	0.2	40.8	0.3	33	0.09	0.067
KYS 110303	Soil		1.3	41.2	30.6	80	<0.1	31.5	18.4	1382	4.14	103.3	1.7	1.3	5.1	9	0.2	10.0	0.3	15	0.04	0.041
KYS 110304	Soil		1.9	48.0	704.2	102	7.4	31.1	12.6	599	4.10	837.8	1.9	297.1	6.6	21	0.4	403.5	0.7	20	0.15	0.077

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110275	Soil	18	54	1.08	85	0.034	<1	1.54	0.003	0.09	<0.1	0.02	2.5	<0.1	<0.05	5	<0.5	<0.2
KYS 110276	Soil	18	79	1.44	133	0.034	<1	1.83	0.003	0.09	<0.1	0.04	3.5	<0.1	<0.05	7	<0.5	0.3
KYS 110277	Soil	24	19	0.51	77	0.005	<1	1.10	0.006	0.06	<0.1	0.02	1.4	<0.1	<0.05	3	0.6	<0.2
KYS 110278	Soil	25	28	0.64	77	0.007	<1	1.34	0.004	0.05	<0.1	0.04	1.8	<0.1	<0.05	4	0.7	<0.2
KYS 110279	Soil	30	23	0.57	81	0.006	<1	1.31	0.003	0.02	<0.1	0.08	1.4	<0.1	<0.05	4	1.3	<0.2
KYS 110280	Soil	26	24	0.60	97	0.003	<1	1.47	0.004	0.05	<0.1	0.10	1.5	<0.1	<0.05	4	1.3	<0.2
KYS 110281	Soil	27	18	0.51	81	0.004	<1	1.11	0.005	0.04	<0.1	0.05	1.4	<0.1	<0.05	3	0.5	<0.2
KYS 110282	Soil	26	22	0.69	91	0.003	<1	1.45	0.003	0.04	<0.1	0.06	1.4	<0.1	<0.05	4	0.8	0.2
KYS 110283	Soil	31	22	0.73	116	0.003	<1	1.52	0.004	0.04	<0.1	0.07	1.4	<0.1	<0.05	5	1.0	<0.2
KYS 110284	Soil	28	19	0.52	87	0.004	<1	1.27	0.004	0.04	<0.1	0.05	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110285	Soil	30	21	0.66	95	0.003	<1	1.43	0.003	0.04	<0.1	0.06	1.3	<0.1	<0.05	4	0.6	0.3
KYS 110286	Soil	25	27	0.59	117	0.004	<1	1.52	0.005	0.04	<0.1	0.12	1.4	<0.1	<0.05	4	1.1	0.5
KYS 110287	Soil	31	21	0.57	101	0.003	<1	1.39	0.004	0.05	<0.1	0.07	1.3	<0.1	<0.05	4	0.6	<0.2
KYS 110288	Soil	26	24	0.55	111	0.004	<1	1.42	0.004	0.04	<0.1	0.09	1.7	<0.1	<0.05	4	1.6	<0.2
KYS 110289	Soil	24	25	0.55	92	0.004	<1	1.37	0.005	0.03	<0.1	0.07	1.6	<0.1	<0.05	4	1.7	0.3
KYS 110290	Soil	31	18	0.63	75	0.003	<1	1.40	0.004	0.07	<0.1	0.05	1.5	<0.1	<0.05	4	0.5	<0.2
KYS 110291	Soil	27	19	0.60	97	0.002	<1	1.18	0.004	0.08	<0.1	0.06	1.9	<0.1	<0.05	3	0.8	0.2
KYS 110292	Soil	28	17	0.66	58	0.005	<1	1.21	0.003	0.07	<0.1	0.04	1.8	<0.1	<0.05	3	0.6	<0.2
KYS 110293	Soil	23	23	0.70	130	0.004	<1	1.26	0.004	0.09	<0.1	0.09	1.6	<0.1	<0.05	3	0.8	<0.2
KYS 110294	Soil	26	17	0.60	110	0.004	2	1.24	0.003	0.07	<0.1	0.07	1.5	<0.1	<0.05	3	0.6	<0.2
KYS 110295	Soil	20	18	0.58	70	0.006	<1	1.27	0.003	0.08	<0.1	0.06	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 110296	Soil	21	14	0.37	49	0.004	<1	0.98	0.007	0.07	<0.1	0.02	0.7	<0.1	<0.05	3	<0.5	<0.2
KYS 110297	Soil	28	21	0.63	55	0.008	<1	1.40	0.003	0.05	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110298	Soil	15	18	0.50	114	0.003	<1	1.39	0.004	0.05	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110299	Soil	25	18	0.51	919	0.005	<1	1.20	0.005	0.05	<0.1	0.13	1.6	<0.1	<0.05	3	1.2	<0.2
KYS 110300	Soil	30	21	0.61	373	0.006	<1	1.50	0.005	0.04	<0.1	0.05	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 110301	Soil	30	25	0.72	482	0.005	<1	1.66	0.005	0.05	<0.1	0.10	2.3	<0.1	<0.05	4	0.9	<0.2
KYS 110302	Soil	28	26	0.59	190	0.005	<1	1.82	0.005	0.05	0.1	0.03	1.4	0.1	<0.05	5	<0.5	<0.2
KYS 110303	Soil	14	17	0.43	82	0.002	<1	1.36	0.003	0.06	<0.1	0.02	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 110304	Soil	24	21	0.58	178	0.003	<1	1.48	0.004	0.06	<0.1	0.06	1.3	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110305	Soil		2.2	54.7	35.9	131	0.4	38.7	17.6	897	4.07	280.3	3.6	17.1	4.6	71	0.6	29.5	0.3	24	0.98	0.113
KYS 110306	Soil		4.0	77.0	38.5	245	0.3	70.7	28.2	891	5.29	139.8	3.8	10.1	12.0	25	2.6	20.7	0.3	55	0.27	0.082
KYS 110307	Soil		1.7	40.1	29.0	93	0.2	38.4	14.4	340	3.53	27.7	1.9	3.3	9.6	18	0.3	8.3	0.3	18	0.21	0.046
KYS 110308	Soil		38.3	95.1	26.4	511	0.6	158.5	16.4	566	3.82	52.1	8.2	5.2	3.6	11	6.5	16.8	0.3	61	0.04	0.074
KYS 110309	Soil		23.5	71.2	22.4	467	0.8	125.8	15.8	444	3.84	40.9	4.8	4.1	4.9	10	5.2	9.6	0.3	57	0.06	0.091
KYS 110310	Soil		19.7	65.8	22.3	181	0.8	48.6	6.0	162	2.50	32.7	3.2	7.2	4.2	21	1.7	7.3	0.3	31	0.07	0.068
KYS 110311	Soil		1.2	29.6	35.9	93	<0.1	51.6	21.5	611	3.65	18.2	1.2	1.6	8.8	22	0.4	1.6	0.2	44	0.21	0.046
KYS 110312	Soil		0.8	37.6	23.2	75	0.2	53.0	14.7	360	3.59	44.8	0.9	2.6	5.3	20	0.2	10.6	0.2	45	0.19	0.059
KYS 110313	Soil		7.5	57.3	27.3	131	0.3	41.4	15.8	679	4.33	321.0	2.1	29.9	7.1	17	0.7	100.2	0.3	27	0.18	0.077
KYS 110314	Soil		0.8	43.3	33.3	92	0.1	42.4	21.9	734	3.69	30.6	1.3	2.3	10.0	12	0.2	5.0	0.3	30	0.12	0.067
KYS 110315	Soil		1.0	41.5	34.1	84	<0.1	45.6	16.3	422	3.43	26.9	1.1	2.5	10.6	12	0.2	5.2	0.2	34	0.14	0.060
KYS 110316	Soil		1.1	35.1	30.0	72	0.1	40.4	12.8	373	3.47	23.1	1.3	2.2	5.1	22	0.2	3.0	0.3	35	0.20	0.055
KYS 110317	Soil		1.0	26.7	22.3	85	0.1	31.5	13.4	608	2.89	15.6	1.7	2.6	6.2	41	0.2	1.1	0.3	17	0.61	0.059
KYS 110318	Soil		1.9	27.3	23.2	127	0.3	48.8	20.7	2083	3.75	21.6	1.9	0.8	7.7	49	0.6	1.6	0.2	27	0.64	0.062
KYS 110319	Soil		2.4	29.7	20.5	105	0.3	44.7	18.4	835	3.52	24.0	1.9	2.7	9.6	29	0.7	1.8	0.2	24	0.34	0.051
KYS 110320	Soil		2.9	37.2	23.7	115	0.4	52.5	18.6	1534	3.40	23.6	2.6	2.9	7.5	52	1.0	1.8	0.2	23	0.67	0.060
KYS 110321	Soil		3.1	47.2	23.9	123	0.6	55.6	19.7	1016	3.54	18.3	2.9	3.8	8.3	44	0.9	2.0	0.3	25	0.57	0.058
KYS 110322	Soil		4.2	55.0	24.3	134	0.6	49.7	18.1	1024	3.66	24.2	3.3	6.5	6.1	79	0.8	3.7	0.3	25	1.03	0.078
KYS 110323	Soil		0.7	45.4	31.9	91	0.1	44.1	17.2	616	3.52	12.7	1.6	0.8	11.4	53	0.2	3.0	0.3	17	0.50	0.054
KYS 110324	Soil		1.4	213.2	57.4	92	0.3	158.4	77.6	1779	6.53	96.1	2.2	5.2	21.6	42	0.3	36.7	0.9	41	0.44	0.093
KYS 110325	Soil		0.7	68.7	33.0	138	<0.1	76.6	37.8	711	4.46	12.2	2.1	5.1	21.8	9	<0.1	1.5	0.3	10	0.08	0.041
KYS 110326	Soil		2.3	45.6	22.9	61	0.7	23.4	5.5	205	3.30	33.1	1.6	9.4	4.8	10	0.2	3.2	0.4	44	0.06	0.094
KYS 110327	Soil		3.8	51.1	20.3	46	2.1	14.9	2.5	72	2.76	30.2	1.7	9.4	0.9	7	<0.1	2.9	0.4	31	0.02	0.108
KYS 110328	Soil		2.3	40.3	18.9	57	0.5	24.0	5.7	193	2.97	25.7	1.5	9.3	1.6	11	0.2	2.1	0.4	44	0.06	0.072
KYS 110329	Soil		1.3	26.1	13.9	34	1.0	8.9	2.2	105	1.50	8.5	0.8	1.7	0.1	8	0.6	0.7	0.3	38	0.04	0.081
KYS 110330	Soil		1.7	28.8	15.4	60	0.6	20.0	5.3	177	2.62	20.1	1.2	8.1	0.5	12	0.3	1.9	0.3	45	0.08	0.067
KYS 110331	Soil		2.4	41.4	21.5	80	0.5	27.4	8.4	201	3.00	32.2	1.6	9.5	0.8	11	0.2	2.1	0.3	43	0.07	0.118
KYS 110332	Soil		1.9	28.0	14.4	63	0.3	18.7	5.9	248	2.71	23.1	1.2	7.3	1.4	13	0.2	2.0	0.3	51	0.09	0.073
KYS 110333	Soil		2.1	34.2	19.7	100	0.1	33.8	12.7	549	3.40	63.0	1.8	5.0	2.2	10	0.3	2.7	0.3	39	0.07	0.077
KYS 110334	Soil		1.5	27.4	14.4	74	0.2	27.0	10.6	362	2.67	25.3	1.6	3.9	1.8	15	0.3	1.7	0.2	43	0.16	0.070

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110305	Soil	14	22	0.71	198	0.004	2	1.42	0.005	0.06	<0.1	0.05	1.6	<0.1	0.07	4	1.1	<0.2
KYS 110306	Soil	17	35	0.79	5602	0.009	1	1.56	0.004	0.08	<0.1	0.04	2.7	<0.1	<0.05	4	0.8	<0.2
KYS 110307	Soil	18	32	0.60	575	0.002	<1	1.37	0.003	0.07	<0.1	0.05	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 110308	Soil	14	13	0.12	4567	0.010	1	1.52	0.003	0.05	0.4	0.76	2.3	0.2	<0.05	2	4.3	0.2
KYS 110309	Soil	17	14	0.08	312	0.016	<1	0.86	0.004	0.04	0.2	0.35	1.7	0.1	<0.05	2	4.5	<0.2
KYS 110310	Soil	13	9	0.08	1065	0.006	2	0.52	0.003	0.05	0.1	0.32	1.0	0.1	0.07	1	3.7	<0.2
KYS 110311	Soil	20	50	0.67	193	0.015	<1	1.72	0.005	0.07	0.1	0.03	2.3	<0.1	<0.05	5	<0.5	<0.2
KYS 110312	Soil	16	71	0.91	161	0.008	<1	1.84	0.005	0.05	<0.1	0.04	2.7	<0.1	<0.05	6	<0.5	<0.2
KYS 110313	Soil	30	19	0.53	1068	0.005	1	1.31	0.004	0.05	<0.1	0.11	1.8	<0.1	<0.05	3	0.9	<0.2
KYS 110314	Soil	28	33	0.58	139	0.008	<1	1.62	0.005	0.06	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 110315	Soil	24	38	0.62	105	0.018	<1	1.43	0.005	0.06	0.1	0.02	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110316	Soil	21	38	0.56	121	0.014	1	1.50	0.008	0.09	0.2	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 110317	Soil	12	22	0.52	249	0.003	<1	1.29	0.004	0.06	<0.1	0.04	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 110318	Soil	12	47	0.86	896	0.002	1	1.59	0.006	0.06	<0.1	0.09	2.0	<0.1	0.07	4	0.6	<0.2
KYS 110319	Soil	18	42	0.79	836	0.003	<1	1.42	0.004	0.06	<0.1	0.07	1.8	<0.1	<0.05	4	0.6	<0.2
KYS 110320	Soil	14	39	0.72	795	0.002	<1	1.33	0.003	0.05	<0.1	0.09	1.7	<0.1	0.05	4	1.2	0.2
KYS 110321	Soil	16	41	0.74	620	0.002	1	1.46	0.004	0.05	<0.1	0.08	1.8	<0.1	<0.05	4	1.0	<0.2
KYS 110322	Soil	10	32	0.66	666	0.002	3	1.32	0.002	0.06	<0.1	0.11	1.5	<0.1	0.08	3	1.6	<0.2
KYS 110323	Soil	18	30	0.58	152	0.003	2	1.50	0.004	0.10	<0.1	0.03	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 110324	Soil	23	94	1.20	127	0.006	<1	2.28	0.003	0.08	<0.1	0.06	5.6	<0.1	<0.05	7	<0.5	<0.2
KYS 110325	Soil	43	22	0.77	48	0.004	1	1.78	0.003	0.10	<0.1	0.01	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 110326	Soil	9	28	0.21	89	0.016	<1	1.58	0.004	0.04	0.1	0.12	2.1	<0.1	<0.05	4	2.2	<0.2
KYS 110327	Soil	5	19	0.04	39	0.006	<1	0.64	0.004	0.02	<0.1	0.11	0.5	<0.1	<0.05	3	1.8	<0.2
KYS 110328	Soil	11	26	0.23	105	0.017	<1	1.28	0.005	0.04	0.1	0.12	1.6	<0.1	<0.05	4	1.1	<0.2
KYS 110329	Soil	10	16	0.06	72	0.007	1	0.76	0.005	0.04	<0.1	0.05	0.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110330	Soil	12	26	0.26	105	0.016	1	1.46	0.005	0.05	0.2	0.08	1.1	<0.1	<0.05	5	0.7	<0.2
KYS 110331	Soil	16	29	0.37	162	0.011	<1	1.66	0.007	0.05	0.1	0.07	1.2	<0.1	<0.05	5	0.8	<0.2
KYS 110332	Soil	14	29	0.30	110	0.025	1	1.48	0.006	0.05	0.2	0.06	1.7	<0.1	<0.05	4	0.9	<0.2
KYS 110333	Soil	15	29	0.36	114	0.014	<1	1.57	0.004	0.04	0.1	0.05	1.6	<0.1	<0.05	4	0.7	<0.2
KYS 110334	Soil	13	27	0.40	125	0.026	<1	1.42	0.005	0.05	0.2	0.06	1.6	<0.1	<0.05	4	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110335	Soil	1.5	37.5	17.2	114	0.3	47.4	16.2	777	2.81	53.0	2.7	5.3	4.9	13	0.5	3.0	0.3	18	0.18	0.059
KYS 110336	Soil	1.4	35.8	16.6	94	0.2	38.6	16.4	859	2.70	61.4	2.0	5.4	2.8	8	0.4	2.7	0.2	20	0.07	0.056
KYS 110337	Soil	1.3	29.7	16.8	94	0.2	37.8	15.3	738	2.68	48.2	2.2	14.9	4.4	9	0.3	2.4	0.2	17	0.15	0.060
KYS 110338	Soil	1.0	24.3	16.9	89	0.2	32.5	11.8	586	2.48	40.6	1.6	5.1	2.1	11	0.5	2.0	0.2	18	0.18	0.069
KYS 110339	Soil	1.0	16.0	8.0	53	0.3	18.2	6.4	305	2.22	12.3	0.5	6.3	4.9	10	<0.1	1.3	0.2	28	0.12	0.033
KYS 110340	Soil	0.8	15.6	7.1	59	0.2	22.4	6.9	134	2.02	8.8	0.5	0.6	3.0	13	0.2	1.0	0.1	31	0.19	0.063
KYS 110341	Soil	1.5	29.7	12.0	83	0.2	25.8	9.6	358	2.56	17.1	1.0	6.9	3.7	15	0.3	2.1	0.2	41	0.15	0.072
KYS 110342	Soil	1.2	17.9	12.5	51	0.3	16.9	6.4	243	2.68	17.3	0.6	13.0	1.3	9	<0.1	1.2	0.3	50	0.08	0.048
KYS 110343	Soil	1.3	19.6	15.8	55	0.3	17.2	6.7	246	2.47	70.1	0.7	19.3	1.5	11	0.1	3.3	0.3	41	0.10	0.058
KYS 110344	Soil	1.7	22.5	25.9	65	0.6	23.6	9.1	282	2.71	89.8	0.8	37.3	3.2	9	0.2	5.6	0.3	39	0.07	0.052
KYS 110345	Soil	2.3	40.4	12.5	80	0.4	35.2	26.7	2216	4.03	99.4	1.9	7.4	1.4	19	0.4	1.3	0.2	35	0.31	0.096
KYS 110346	Soil	1.0	25.1	16.8	52	0.2	21.0	6.7	210	2.41	35.0	0.7	2.8	4.4	6	<0.1	1.3	0.3	17	0.06	0.046
KYS 110347	Soil	1.4	46.3	18.4	78	0.2	30.4	12.5	439	2.76	35.3	1.1	7.7	5.0	12	0.3	1.7	0.3	31	0.12	0.076
KYS 110348	Soil	1.1	17.4	13.9	44	<0.1	16.0	5.9	220	2.30	17.2	0.7	6.2	0.8	8	0.2	0.8	0.3	37	0.08	0.052
KYS 110349	Soil	1.2	22.9	13.9	53	<0.1	21.8	7.7	267	2.53	19.4	0.7	3.4	4.8	10	0.2	1.1	0.2	36	0.12	0.069
KYS 110350	Soil	1.2	22.6	14.6	56	<0.1	21.1	9.3	351	2.68	24.0	0.6	2.6	2.5	9	0.2	1.2	0.2	37	0.11	0.060
KYS 110351	Soil	0.9	34.1	21.7	57	0.2	24.0	8.8	214	2.82	57.7	0.8	3.9	2.6	4	0.1	1.6	0.3	17	0.03	0.043
KYS 110352	Soil	1.6	37.6	21.4	66	0.2	30.9	11.9	467	3.09	35.5	1.1	6.7	3.1	11	0.3	1.7	0.4	34	0.07	0.064
KYS 110358	Soil	16.2	75.8	35.6	158	1.6	25.0	2.4	299	5.27	33.0	6.3	9.2	10.4	38	0.2	6.4	0.5	35	0.02	0.189
KYS 110359	Soil	17.1	102.1	40.8	157	1.1	25.2	5.3	202	3.50	23.1	8.1	4.9	13.0	41	0.4	5.2	0.5	48	0.04	0.145
KYS 110360	Soil	8.8	54.0	20.6	75	1.0	15.5	3.8	168	3.00	19.1	3.3	2.0	1.4	21	0.3	2.4	0.4	51	0.04	0.119
KYS 110361	Soil	6.4	71.0	19.5	94	0.5	22.5	8.4	298	3.26	17.9	3.1	3.8	4.1	20	0.5	2.3	0.3	50	0.08	0.108
KYS 110362	Soil	5.3	27.8	16.9	75	0.3	16.3	4.2	182	2.49	17.1	1.9	4.7	1.4	16	0.4	1.6	0.3	47	0.06	0.077
KYS 110363	Soil	5.0	29.7	14.9	78	0.6	19.5	5.3	256	3.13	19.4	1.5	2.1	3.8	15	0.3	1.7	0.3	49	0.06	0.087
KYS 110364	Soil	13.2	89.1	49.7	167	1.8	28.7	3.8	380	5.02	5.9	8.7	5.5	13.5	27	1.0	2.5	0.4	26	0.05	0.191
KYS 110365	Soil	19.6	101.0	38.7	182	3.5	22.6	4.1	156	5.72	53.4	9.7	9.0	4.1	45	0.5	6.2	0.5	75	0.04	0.377
KYS 110366	Soil	8.0	43.4	30.8	155	0.7	26.2	8.5	481	4.87	19.6	2.4	6.1	11.6	20	0.4	1.9	0.3	33	0.04	0.111
KYS 110367	Soil	4.4	49.1	37.7	182	0.3	39.4	7.5	367	5.02	12.8	2.2	2.4	14.2	20	0.4	1.4	0.4	24	0.01	0.080
KYS 110368	Soil	4.9	85.4	41.3	103	0.7	15.5	3.4	256	4.52	7.9	4.5	1.0	7.5	21	0.6	1.6	0.4	25	0.06	0.150
KYS 110369	Soil	3.6	26.3	14.9	81	0.3	19.8	10.4	494	3.01	16.3	1.5	4.4	3.8	16	0.4	1.7	0.2	47	0.10	0.083

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110335	Soil	12	21	0.39	243	0.007	<1	1.01	0.003	0.04	0.1	0.05	1.5	<0.1	<0.05	3	1.1	<0.2
KYS 110336	Soil	12	17	0.29	118	0.007	<1	0.95	0.002	0.03	0.1	0.03	1.4	<0.1	<0.05	3	0.8	<0.2
KYS 110337	Soil	11	19	0.36	167	0.007	<1	0.90	0.003	0.04	0.3	0.03	1.5	<0.1	<0.05	3	1.1	<0.2
KYS 110338	Soil	10	18	0.33	142	0.007	<1	0.87	0.011	0.04	0.2	0.03	1.0	<0.1	<0.05	3	1.0	<0.2
KYS 110339	Soil	11	16	0.20	63	0.033	<1	0.61	0.003	0.03	0.2	0.06	1.6	<0.1	<0.05	3	1.3	<0.2
KYS 110340	Soil	10	19	0.30	116	0.027	1	0.90	0.005	0.03	0.1	0.04	1.5	<0.1	<0.05	3	0.7	<0.2
KYS 110341	Soil	13	24	0.40	135	0.034	1	1.47	0.007	0.05	0.2	0.06	2.7	<0.1	<0.05	4	<0.5	<0.2
KYS 110342	Soil	13	24	0.38	73	0.027	<1	1.25	0.005	0.04	<0.1	0.04	1.4	<0.1	<0.05	5	<0.5	<0.2
KYS 110343	Soil	11	24	0.35	113	0.022	1	1.54	0.006	0.04	0.2	0.06	1.7	<0.1	<0.05	4	0.6	<0.2
KYS 110344	Soil	10	25	0.32	99	0.020	3	1.53	0.005	0.03	0.2	0.07	1.9	<0.1	<0.05	4	0.6	<0.2
KYS 110345	Soil	12	26	0.40	184	0.014	1	1.33	0.005	0.04	0.1	0.04	1.7	<0.1	<0.05	3	1.0	<0.2
KYS 110346	Soil	15	15	0.31	42	0.004	<1	0.87	0.003	0.04	<0.1	0.03	0.9	<0.1	<0.05	3	<0.5	<0.2
KYS 110347	Soil	17	21	0.39	81	0.020	<1	1.18	0.005	0.05	0.1	0.05	2.0	<0.1	<0.05	3	0.5	<0.2
KYS 110348	Soil	13	21	0.27	73	0.015	<1	1.40	0.004	0.04	0.1	0.04	1.0	0.1	<0.05	5	0.5	<0.2
KYS 110349	Soil	13	23	0.30	62	0.024	1	1.51	0.004	0.03	0.2	0.05	1.8	<0.1	<0.05	4	0.7	0.3
KYS 110350	Soil	13	22	0.36	71	0.026	1	1.17	0.004	0.04	0.1	0.05	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 110351	Soil	15	17	0.30	36	0.009	<1	0.82	0.006	0.04	<0.1	0.03	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 110352	Soil	15	24	0.35	118	0.016	<1	1.43	0.005	0.04	<0.1	0.08	2.0	<0.1	<0.05	4	0.5	<0.2
KYS 110358	Soil	27	18	0.25	182	0.003	<1	1.19	0.005	0.06	<0.1	0.33	1.3	<0.1	0.15	3	10.8	<0.2
KYS 110359	Soil	47	24	0.33	170	0.004	<1	1.15	0.004	0.05	<0.1	0.45	2.9	<0.1	<0.05	3	8.7	<0.2
KYS 110360	Soil	23	24	0.25	133	0.009	<1	1.26	0.005	0.05	<0.1	0.18	0.6	0.1	0.06	4	2.9	<0.2
KYS 110361	Soil	24	26	0.36	138	0.015	1	1.71	0.006	0.05	0.2	0.20	1.8	0.1	<0.05	4	2.0	<0.2
KYS 110362	Soil	22	23	0.27	101	0.014	1	1.22	0.005	0.04	0.1	0.13	1.0	0.1	<0.05	4	1.8	0.3
KYS 110363	Soil	19	26	0.32	97	0.019	<1	1.49	0.005	0.04	0.2	0.08	1.5	0.1	<0.05	5	1.1	0.3
KYS 110364	Soil	31	17	0.39	139	0.004	<1	1.60	0.011	0.06	<0.1	0.17	1.1	<0.1	0.12	3	7.0	<0.2
KYS 110365	Soil	23	34	0.30	112	0.005	<1	1.22	0.005	0.09	<0.1	0.27	1.0	0.1	0.20	3	12.7	0.5
KYS 110366	Soil	20	22	0.34	139	0.005	<1	1.85	0.006	0.06	<0.1	0.10	1.0	0.1	0.10	3	3.8	0.5
KYS 110367	Soil	20	18	0.40	118	0.003	<1	1.79	0.006	0.06	<0.1	0.06	0.8	<0.1	0.08	4	2.5	<0.2
KYS 110368	Soil	33	19	0.37	105	0.007	<1	1.38	0.011	0.06	<0.1	0.06	0.9	<0.1	0.17	3	2.9	<0.2
KYS 110369	Soil	17	25	0.35	104	0.029	<1	1.25	0.005	0.05	0.1	0.06	1.6	0.1	<0.05	4	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110370	Soil		3.1	28.9	14.5	76	0.3	22.2	8.4	288	2.83	16.7	1.6	1.8	3.3	15	0.4	1.4	0.2	52	0.09	0.080
KYS 110371	Soil		3.2	33.1	14.7	69	0.4	21.6	6.7	203	2.97	14.4	1.8	3.3	5.3	16	0.5	1.3	0.2	49	0.06	0.058
KYS 110372	Soil		8.9	69.8	31.3	156	1.6	34.6	6.9	470	4.40	24.8	6.2	4.7	4.2	36	0.9	2.9	0.4	39	0.07	0.155
KYS 110373	Soil		5.9	71.2	38.1	186	1.7	48.3	7.2	326	4.37	15.8	5.4	1.7	10.2	44	2.9	1.9	0.4	24	0.22	0.137
KYS 110374	Soil		26.2	104.2	50.6	150	2.2	29.9	4.8	234	7.01	19.5	7.7	7.3	8.3	33	0.6	6.4	0.5	62	0.03	0.247
KYS 110375	Soil		5.5	22.5	24.6	58	0.5	9.2	1.8	113	3.16	15.5	1.1	1.9	5.5	16	0.2	1.3	0.3	30	0.02	0.066
KYS 110376	Soil		14.3	36.6	29.8	149	1.1	23.1	4.9	184	3.65	44.1	3.1	5.1	6.4	25	0.4	6.4	0.3	43	0.04	0.103
KYS 110377	Soil		7.5	19.7	22.4	59	1.0	12.1	3.2	155	2.11	14.3	1.3	2.6	1.9	15	0.3	2.0	0.4	28	0.11	0.063
KYS 110378	Soil		5.1	40.2	36.1	142	0.4	39.3	7.3	339	4.83	25.9	2.9	1.7	12.1	16	0.6	4.5	0.4	25	0.08	0.086
KYS 110379	Soil		4.5	32.7	18.4	123	0.7	38.7	13.2	825	2.39	13.2	4.3	2.9	4.5	39	2.5	1.9	0.3	22	0.62	0.066
KYS 110380	Soil		5.6	58.3	30.4	195	0.4	62.5	24.3	596	3.39	10.9	6.6	2.2	6.0	21	2.7	1.7	0.4	18	0.19	0.058
KYS 110381	Soil		5.2	40.1	19.2	191	0.4	44.2	10.1	933	2.64	10.7	2.8	2.6	5.9	21	2.2	1.7	0.3	23	0.23	0.054
KYS 110382	Soil		3.7	50.5	27.2	142	0.6	41.1	14.2	382	2.99	10.5	3.4	2.2	5.1	28	1.5	1.6	0.3	24	0.42	0.060
KYS 110383	Soil		8.1	48.5	26.1	207	0.6	53.7	13.7	310	3.25	18.9	3.7	1.6	7.8	23	2.6	3.7	0.3	23	0.29	0.060
KYS 110384	Soil		11.0	57.7	35.9	66	0.7	8.1	1.4	277	3.96	20.7	1.9	4.1	10.9	15	0.2	5.0	0.5	42	<0.01	0.093
KYS 110385	Soil		13.6	119.3	51.6	252	2.6	43.9	20.9	386	4.95	17.2	17.6	4.9	16.8	105	4.6	4.4	0.7	60	0.04	0.149
KYS 110386	Soil		16.4	103.4	56.1	400	2.2	63.5	12.9	265	6.83	25.2	13.0	7.8	15.6	47	4.0	6.0	0.6	64	0.05	0.180
KYS 110387	Soil		4.6	46.1	21.0	132	0.6	30.9	8.7	280	3.03	15.6	2.8	3.5	3.2	23	1.0	2.2	0.3	37	0.09	0.078
KYS 110388	Soil		4.8	54.1	22.7	82	0.5	23.2	6.2	195	2.65	16.5	2.6	3.6	0.7	25	1.1	2.1	0.3	39	0.06	0.082
KYS 110400	Soil		2.6	108.4	26.6	113	0.3	58.9	28.5	2031	3.41	20.8	1.3	26.8	1.5	8	0.3	4.2	0.4	32	0.05	0.122
KYS 110401	Soil		1.0	50.7	19.7	83	0.1	31.3	14.8	1228	2.92	15.0	1.2	11.5	5.7	7	0.3	2.4	0.3	23	0.07	0.068
KYS 110402	Soil		5.8	61.0	20.2	86	0.3	27.4	9.1	727	3.07	14.8	1.6	10.6	2.7	15	0.2	2.3	0.3	32	0.07	0.073
KYS 110403	Soil		1.9	183.1	25.2	139	0.3	71.1	25.9	3458	3.50	26.8	1.5	57.5	3.8	21	0.4	8.3	0.3	30	0.10	0.082
KYS 110404	Soil		1.7	176.2	24.7	127	0.3	61.9	22.5	4003	3.55	29.6	1.1	434.5	4.5	25	0.4	8.8	0.3	33	0.13	0.092
KYS 110405	Soil		1.4	219.4	24.9	106	0.2	50.0	32.5	2908	3.46	63.2	1.0	66.1	2.3	18	0.2	5.4	0.3	38	0.06	0.078
KYS 110406	Soil		1.7	91.6	13.1	72	0.2	25.3	8.9	722	2.35	14.2	1.0	41.9	3.0	21	0.2	4.7	0.2	33	0.11	0.069
KYS 110407	Soil		1.5	97.8	15.6	107	0.4	39.3	14.3	1472	3.10	491.4	1.1	77.6	4.7	17	0.4	19.3	0.2	38	0.13	0.094
KYS 110408	Soil		1.2	92.3	16.1	86	<0.1	45.6	15.5	2367	2.93	19.4	0.9	24.8	4.1	14	<0.1	5.7	0.3	35	0.06	0.050
KYS 110409	Soil		1.4	116.7	19.1	90	0.1	51.8	17.9	2762	2.94	15.2	0.9	23.4	6.8	19	0.2	1.7	0.2	37	0.11	0.063
KYS 110410	Soil		1.4	122.2	18.7	93	0.1	51.1	17.2	2879	2.86	14.8	0.8	25.9	5.3	25	0.2	1.1	0.3	36	0.16	0.074

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110370	Soil	16	26	0.38	132	0.027	<1	1.49	0.007	0.05	0.2	0.08	2.0	0.1	<0.05	5	1.0	<0.2
KYS 110371	Soil	17	27	0.33	123	0.018	<1	1.73	0.005	0.04	0.2	0.10	2.0	0.1	<0.05	5	1.0	<0.2
KYS 110372	Soil	23	20	0.26	144	0.006	<1	1.18	0.004	0.05	0.1	0.15	0.9	<0.1	0.07	3	4.2	0.5
KYS 110373	Soil	27	18	0.41	180	0.003	<1	1.30	0.006	0.07	<0.1	0.11	1.2	<0.1	0.08	3	3.3	<0.2
KYS 110374	Soil	16	26	0.26	148	0.006	1	1.49	0.005	0.07	0.1	0.19	1.7	0.2	0.22	3	15.5	<0.2
KYS 110375	Soil	24	16	0.21	161	0.005	<1	1.11	0.004	0.05	<0.1	0.05	0.7	0.1	0.05	4	1.4	<0.2
KYS 110376	Soil	18	13	0.19	206	0.004	<1	0.70	0.003	0.06	0.2	0.14	1.0	0.1	0.11	2	4.6	<0.2
KYS 110377	Soil	12	12	0.20	105	0.004	<1	0.76	0.004	0.04	0.1	0.20	0.4	0.1	<0.05	3	3.8	<0.2
KYS 110378	Soil	16	18	0.43	85	0.003	<1	1.56	0.003	0.06	<0.1	0.04	0.9	<0.1	0.05	3	3.0	<0.2
KYS 110379	Soil	12	13	0.34	204	0.006	<1	0.89	0.004	0.04	0.1	0.17	1.1	<0.1	0.06	3	5.2	<0.2
KYS 110380	Soil	17	12	0.36	151	0.003	<1	1.30	0.004	0.04	<0.1	0.11	1.3	<0.1	<0.05	3	3.0	0.3
KYS 110381	Soil	19	14	0.31	114	0.005	<1	0.89	0.003	0.04	<0.1	0.06	1.1	<0.1	<0.05	3	2.7	<0.2
KYS 110382	Soil	17	14	0.38	151	0.004	<1	1.04	0.004	0.04	<0.1	0.11	1.1	<0.1	<0.05	3	4.2	<0.2
KYS 110383	Soil	20	10	0.31	110	0.002	<1	0.84	0.004	0.04	<0.1	0.13	1.1	<0.1	0.05	2	4.0	<0.2
KYS 110384	Soil	24	20	0.26	110	0.003	<1	0.97	0.003	0.04	<0.1	0.27	1.2	0.1	0.08	3	8.0	<0.2
KYS 110385	Soil	40	27	0.50	156	0.002	<1	1.46	0.003	0.05	<0.1	0.38	1.7	<0.1	0.06	4	4.5	0.4
KYS 110386	Soil	35	30	0.36	119	0.004	<1	1.34	0.003	0.05	<0.1	0.39	1.6	<0.1	0.08	4	6.6	<0.2
KYS 110387	Soil	19	19	0.35	148	0.011	<1	1.19	0.007	0.05	0.1	0.10	1.2	<0.1	<0.05	3	1.5	<0.2
KYS 110388	Soil	17	16	0.21	169	0.008	<1	0.97	0.004	0.04	0.1	0.12	0.8	<0.1	<0.05	3	1.4	<0.2
KYS 110400	Soil	14	23	0.38	86	0.008	<1	1.25	0.004	0.03	<0.1	0.09	0.9	<0.1	<0.05	4	1.4	<0.2
KYS 110401	Soil	21	17	0.45	112	0.010	<1	1.13	0.006	0.03	<0.1	0.03	1.7	<0.1	<0.05	3	0.5	<0.2
KYS 110402	Soil	19	19	0.45	239	0.008	<1	1.31	0.004	0.05	<0.1	0.07	1.3	<0.1	<0.05	4	0.9	<0.2
KYS 110403	Soil	20	19	0.50	358	0.009	<1	1.27	0.004	0.04	<0.1	0.09	1.5	<0.1	<0.05	4	1.3	<0.2
KYS 110404	Soil	22	19	0.63	283	0.011	<1	1.48	0.004	0.04	<0.1	0.09	1.8	<0.1	<0.05	4	1.0	0.3
KYS 110405	Soil	16	23	0.69	185	0.006	<1	1.49	0.004	0.04	<0.1	0.03	1.3	<0.1	<0.05	4	1.1	0.5
KYS 110406	Soil	17	16	0.38	318	0.021	<1	1.03	0.004	0.04	0.1	0.06	1.5	<0.1	<0.05	3	1.0	<0.2
KYS 110407	Soil	20	20	0.44	142	0.027	<1	1.23	0.004	0.05	0.2	0.04	2.5	<0.1	<0.05	3	0.7	0.3
KYS 110408	Soil	28	18	0.39	187	0.019	<1	1.21	0.004	0.04	<0.1	0.06	2.1	<0.1	<0.05	4	0.7	0.2
KYS 110409	Soil	25	22	0.61	139	0.025	1	1.42	0.006	0.05	0.1	0.04	2.0	<0.1	<0.05	4	0.6	<0.2
KYS 110410	Soil	23	20	0.56	146	0.023	<1	1.31	0.005	0.04	<0.1	0.05	2.0	<0.1	<0.05	4	0.6	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110411	Soil		1.2	71.7	11.4	73	0.1	36.7	11.3	1357	2.44	12.8	1.0	14.2	4.2	15	0.2	1.2	0.2	37	0.17	0.082
KYS 110412	Soil		1.2	81.4	12.3	85	0.1	37.2	11.8	1717	2.51	12.7	0.9	23.0	4.9	18	0.3	1.0	0.2	38	0.17	0.087
KYS 110413	Soil		1.3	77.4	16.4	86	0.2	35.4	11.2	1233	2.68	21.9	1.0	26.0	2.9	16	0.2	1.4	0.2	39	0.09	0.071
KYS 110414	Soil		1.3	79.4	14.1	79	0.2	35.2	12.2	1398	2.49	16.6	0.9	13.0	4.7	17	0.2	1.3	0.2	35	0.14	0.082
KYS 110415	Soil		1.1	75.9	12.2	78	0.1	35.1	11.4	1699	2.43	14.4	0.9	13.0	5.0	16	0.3	1.2	0.2	35	0.14	0.077
KYS 110416	Soil		1.7	70.6	16.7	79	0.2	32.8	11.0	1447	3.11	18.2	1.0	22.3	0.9	14	0.2	1.6	0.3	48	0.07	0.090
KYS 110417	Soil		1.6	50.5	15.5	81	0.3	28.7	10.5	1131	3.21	17.7	0.9	11.2	1.4	11	0.2	1.9	0.3	52	0.07	0.075
KYS 110418	Soil		3.0	463.0	42.1	174	0.4	150.2	91.0	>10000	3.86	27.1	3.5	91.8	4.2	33	0.5	2.1	0.6	36	0.10	0.121
KYS 110419	Soil		2.4	205.7	33.7	164	0.5	126.9	49.0	7469	3.92	22.4	2.9	66.8	7.2	43	0.2	4.4	0.5	31	0.09	0.081
KYS 110420	Soil		2.3	237.5	31.8	128	0.3	84.0	34.4	5309	4.11	134.6	1.6	41.3	9.3	37	0.2	11.4	0.4	30	0.15	0.086
KYS 110421	Soil		2.1	119.3	35.6	98	0.8	36.5	14.6	1366	3.99	233.4	1.0	46.9	2.3	10	<0.1	14.8	0.5	33	0.02	0.089
KYS 110422	Soil		1.6	51.0	26.8	109	0.2	40.1	16.9	721	3.92	37.6	1.9	3.8	10.5	10	0.2	8.8	0.4	9	0.12	0.028
KYS 110423	Soil		0.9	12.0	19.6	42	0.3	11.5	5.0	316	1.87	11.1	0.6	1.0	4.2	5	<0.1	0.8	0.2	31	0.03	0.031
KYS 110424	Soil		2.1	29.4	16.7	72	0.3	23.4	8.2	319	2.73	35.4	1.1	16.4	1.4	8	0.2	2.7	0.3	39	0.05	0.065
KYS 110425	Soil		2.4	44.4	19.0	94	0.2	29.3	11.6	391	3.37	18.5	1.0	4.9	1.8	9	0.3	1.6	0.3	41	0.04	0.088
KYS 110426	Soil		1.9	21.0	16.3	61	0.2	18.0	5.9	239	2.64	18.6	1.1	8.6	0.6	11	0.2	1.5	0.3	49	0.06	0.079
KYS 110427	Soil		2.0	24.1	15.2	64	0.2	19.0	7.1	248	2.78	17.6	1.2	7.2	1.2	10	0.2	1.3	0.3	55	0.07	0.075
KYS 110428	Soil		1.9	45.9	18.3	99	0.1	39.2	13.8	530	3.35	15.8	1.2	8.1	1.5	9	0.2	1.5	0.3	44	0.06	0.057
KYS 110429	Soil		1.7	13.9	15.8	52	0.3	16.1	5.2	176	3.31	14.4	0.7	2.6	2.7	11	0.3	0.9	0.3	55	0.06	0.050
KYS 110430	Soil		1.5	16.4	12.1	40	0.2	12.6	4.4	185	1.85	14.3	0.7	4.8	2.4	10	0.1	1.1	0.2	50	0.07	0.053
KYS 110431	Soil		2.0	111.9	21.8	112	0.1	49.2	19.3	2081	3.36	18.6	1.3	35.3	2.7	12	0.3	2.8	0.3	45	0.08	0.084
KYS 110432	Soil		1.9	81.8	29.9	129	0.2	52.1	18.8	1886	3.51	24.4	1.7	8.3	4.6	11	0.4	3.8	0.4	26	0.13	0.073
KYS 110433	Soil		1.7	70.6	18.9	105	0.4	40.8	14.5	1516	3.17	162.5	1.2	32.8	0.9	11	0.2	8.4	0.3	46	0.05	0.077
KYS 110434	Soil		1.4	61.0	25.4	114	0.2	49.5	19.3	1225	3.48	26.1	1.4	19.3	7.0	11	0.2	5.9	0.3	24	0.06	0.044
KYS 110435	Soil		1.2	67.0	25.4	117	0.3	55.0	19.2	1148	3.37	36.5	1.3	12.1	7.2	10	0.2	5.3	0.3	25	0.06	0.046
KYS 110436	Soil		1.8	82.7	23.9	127	0.6	55.4	17.5	1516	3.64	67.3	1.3	20.1	3.4	13	0.3	4.1	0.4	41	0.05	0.066
KYS 110437	Soil		1.9	89.5	29.2	196	0.7	91.3	26.8	1790	4.34	184.9	1.4	26.2	8.3	18	0.4	6.8	0.4	39	0.04	0.063
KYS 110438	Soil		1.9	91.2	26.6	166	0.6	81.2	24.6	2099	4.06	155.9	1.2	27.3	4.5	16	0.3	5.3	0.4	40	0.06	0.065
KYS 110439	Soil		2.1	98.6	28.2	183	0.6	90.1	26.4	2204	3.92	62.1	1.2	25.9	7.3	23	0.3	3.4	0.4	38	0.12	0.077
KYS 110440	Soil		2.1	117.0	30.0	177	0.6	89.6	26.8	2592	4.10	52.1	1.1	30.3	6.3	21	0.3	3.2	0.4	35	0.12	0.074

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110411	Soil		19	21	0.44	106	0.033	1	1.23	0.003	0.04	0.2	0.06	2.1	<0.1	<0.05	3	0.7	<0.2
KYS 110412	Soil		18	22	0.45	111	0.032	1	1.21	0.005	0.04	0.2	0.06	1.9	<0.1	<0.05	3	1.0	<0.2
KYS 110413	Soil		17	23	0.42	82	0.023	<1	1.20	0.005	0.03	0.1	0.06	1.4	<0.1	<0.05	4	0.8	<0.2
KYS 110414	Soil		17	20	0.39	105	0.028	<1	1.05	0.005	0.03	0.1	0.05	1.7	<0.1	<0.05	3	0.8	<0.2
KYS 110415	Soil		19	20	0.40	100	0.029	<1	1.06	0.005	0.03	0.2	0.05	1.6	<0.1	<0.05	3	0.9	<0.2
KYS 110416	Soil		17	27	0.45	149	0.017	<1	1.50	0.005	0.04	0.1	0.07	1.1	<0.1	0.07	5	0.9	<0.2
KYS 110417	Soil		14	30	0.48	103	0.024	1	1.51	0.005	0.05	0.2	0.09	1.4	0.1	<0.05	5	0.8	<0.2
KYS 110418	Soil		20	24	0.50	178	0.008	<1	1.77	0.006	0.04	<0.1	0.24	1.7	<0.1	<0.05	5	1.2	0.3
KYS 110419	Soil		30	24	0.68	144	0.005	<1	1.62	0.005	0.03	<0.1	0.11	1.6	<0.1	<0.05	5	1.5	0.3
KYS 110420	Soil		26	21	0.70	105	0.004	<1	1.54	0.004	0.03	<0.1	0.05	1.7	<0.1	<0.05	5	1.1	0.2
KYS 110421	Soil		11	26	0.49	90	0.004	<1	1.38	0.004	0.03	<0.1	0.12	1.5	<0.1	<0.05	5	1.5	<0.2
KYS 110422	Soil		17	11	0.42	64	<0.001	<1	1.00	0.004	0.07	<0.1	0.06	1.5	<0.1	<0.05	3	0.7	<0.2
KYS 110423	Soil		22	12	0.16	61	0.016	<1	0.85	0.005	0.08	<0.1	0.03	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110424	Soil		11	22	0.20	65	0.016	<1	1.20	0.006	0.03	0.1	0.04	1.4	<0.1	<0.05	4	0.9	<0.2
KYS 110425	Soil		10	22	0.16	59	0.012	2	1.05	0.006	0.03	<0.1	0.04	1.4	<0.1	<0.05	4	0.8	<0.2
KYS 110426	Soil		11	28	0.31	77	0.016	<1	1.50	0.006	0.04	0.1	0.05	1.1	<0.1	<0.05	5	0.9	<0.2
KYS 110427	Soil		13	30	0.38	89	0.023	<1	1.68	0.006	0.04	0.1	0.05	1.8	<0.1	<0.05	5	0.5	<0.2
KYS 110428	Soil		14	24	0.25	81	0.021	<1	1.41	0.005	0.04	0.1	0.05	1.9	<0.1	<0.05	5	0.7	<0.2
KYS 110429	Soil		11	32	0.32	118	0.030	<1	1.79	0.008	0.04	0.2	0.05	2.0	<0.1	<0.05	6	0.6	<0.2
KYS 110430	Soil		14	19	0.18	64	0.040	<1	0.93	0.007	0.03	0.1	0.03	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 110431	Soil		22	28	0.56	119	0.021	1	1.65	0.007	0.05	0.2	0.06	2.1	<0.1	<0.05	5	<0.5	0.3
KYS 110432	Soil		25	20	0.46	207	0.008	<1	1.33	0.007	0.06	<0.1	0.06	2.1	<0.1	<0.05	3	0.5	<0.2
KYS 110433	Soil		20	28	0.40	119	0.015	<1	1.50	0.007	0.05	0.1	0.06	1.1	<0.1	<0.05	4	0.8	<0.2
KYS 110434	Soil		26	19	0.40	95	0.009	<1	1.11	0.007	0.06	<0.1	0.06	1.7	<0.1	<0.05	3	0.5	<0.2
KYS 110435	Soil		24	20	0.38	94	0.010	<1	1.01	0.008	0.04	0.1	0.07	1.6	<0.1	<0.05	3	0.5	<0.2
KYS 110436	Soil		21	31	0.47	97	0.018	<1	1.54	0.008	0.04	0.1	0.11	1.6	<0.1	<0.05	4	1.0	<0.2
KYS 110437	Soil		29	35	0.64	134	0.010	<1	1.83	0.007	0.04	<0.1	0.16	2.0	<0.1	<0.05	4	2.2	<0.2
KYS 110438	Soil		27	32	0.60	137	0.012	<1	1.65	0.009	0.05	<0.1	0.14	1.6	<0.1	<0.05	4	2.0	0.4
KYS 110439	Soil		26	31	0.60	132	0.014	<1	1.51	0.007	0.04	0.1	0.12	1.8	<0.1	<0.05	4	1.9	0.3
KYS 110440	Soil		31	31	0.63	107	0.010	<1	1.44	0.008	0.04	<0.1	0.10	1.5	<0.1	<0.05	4	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110441	Soil		2.8	264.2	40.4	212	0.6	130.0	41.8	4609	4.23	78.2	1.7	68.2	9.5	17	0.3	4.3	0.5	35	0.08	0.075
KYS 110442	Soil		2.7	180.9	38.3	205	0.7	116.0	38.1	4887	4.50	63.7	1.7	31.2	13.3	21	0.4	6.7	0.5	33	0.08	0.077
KYS 110443	Soil		2.4	190.4	34.9	165	0.5	96.0	32.0	3390	4.33	33.8	1.6	33.9	7.8	20	0.2	4.2	0.5	35	0.10	0.075
KYS 110444	Soil		2.5	231.9	34.3	147	0.4	102.4	39.9	5276	4.11	46.3	1.4	54.5	9.2	25	0.1	4.1	0.4	32	0.14	0.071
KYS 110445	Soil		3.1	292.1	39.7	171	0.4	110.2	42.8	5344	4.36	44.4	1.6	55.0	9.5	32	0.2	3.4	0.4	37	0.16	0.079
KYS 110446	Soil		2.1	315.4	38.7	122	0.4	82.7	35.3	7037	4.06	25.8	1.2	53.8	6.3	42	0.2	1.2	0.3	40	0.23	0.126
KYS 110447	Soil		2.7	182.3	34.8	174	0.5	120.6	42.7	7344	4.17	15.6	1.9	42.7	8.3	34	0.4	2.3	0.4	41	0.12	0.092
KYS 110448	Soil		2.1	155.7	31.8	166	0.5	115.0	46.8	5303	3.73	17.1	1.6	21.0	8.1	26	0.2	2.2	0.4	38	0.05	0.071
KYS 110449	Soil		2.3	161.4	28.8	126	0.5	73.9	31.4	3354	3.54	18.9	2.2	25.3	8.6	30	0.3	3.5	0.3	44	0.14	0.092
KYS 110450	Soil		2.0	88.7	16.6	98	0.2	63.4	34.1	2713	3.00	15.2	1.4	19.5	4.3	16	0.3	2.8	0.3	51	0.10	0.055
KYS 110451	Soil		2.1	108.3	24.4	102	0.2	58.8	23.4	3154	3.09	15.5	1.3	95.0	3.7	16	0.2	2.0	0.3	45	0.09	0.079
KYS 110452	Soil		2.9	197.9	27.1	172	0.3	128.9	47.1	8241	3.57	24.0	3.5	68.6	8.6	36	0.4	3.2	0.4	45	0.12	0.092
KYS 110453	Soil		2.4	225.5	33.7	147	0.4	95.2	44.1	5563	4.09	168.1	3.0	71.6	5.1	26	0.3	11.2	0.4	44	0.06	0.098
KYS 110454	Soil		2.0	117.9	32.8	153	1.3	53.1	15.2	1430	3.98	614.9	1.3	54.7	7.8	11	0.2	42.4	0.4	16	<0.01	0.061
KYS 110455	Soil		1.8	103.8	23.5	114	0.4	57.1	17.4	2291	3.38	133.6	1.4	28.5	7.9	14	0.3	10.4	0.3	36	0.07	0.056
KYS 110456	Soil		2.2	76.4	31.3	116	0.3	51.6	22.5	1613	3.48	40.0	1.4	24.2	4.0	19	0.5	6.8	0.3	29	0.20	0.074
KYS 110457	Soil		1.5	55.7	25.9	78	0.1	33.7	16.1	541	3.45	35.9	1.2	9.9	5.1	9	0.2	5.1	0.3	38	0.08	0.044
KYS 110458	Soil		0.9	64.3	40.7	110	0.2	49.3	25.0	1090	3.99	83.6	1.7	9.3	18.3	9	<0.1	7.3	0.4	14	0.11	0.040
KYS 110459	Soil		1.4	92.0	27.3	113	0.2	56.8	25.8	1834	4.37	19.7	1.7	9.6	10.8	19	0.2	1.9	0.3	28	0.18	0.066
KYS 110460	Soil		1.4	94.7	28.4	115	0.2	59.5	27.1	1892	4.44	20.2	1.7	8.0	10.8	19	<0.1	2.0	0.3	31	0.18	0.069
KYS 110461	Soil		1.5	93.9	27.8	115	0.2	57.5	24.7	1965	4.10	17.5	1.5	9.7	9.0	20	0.1	2.6	0.3	28	0.15	0.062
KYS 110462	Soil		1.4	72.4	25.0	114	0.2	56.5	26.0	1499	4.46	38.8	2.1	12.2	11.1	22	0.2	3.4	0.3	29	0.21	0.080
KYS 110463	Soil		1.8	75.3	26.1	121	0.2	60.1	26.8	1544	4.40	118.6	1.7	13.3	13.3	24	0.3	5.5	0.3	19	0.24	0.098
KYS 110464	Soil		1.1	75.6	23.0	136	0.2	59.1	25.8	1621	4.65	182.6	1.4	20.7	8.8	23	0.1	4.5	0.3	45	0.22	0.069
KYS 110465	Soil		1.5	79.5	26.5	139	0.4	68.5	29.2	1930	4.68	236.8	1.5	18.8	11.6	23	0.3	8.8	0.3	30	0.23	0.083
KYS 110466	Soil		1.2	81.5	30.9	146	1.0	73.8	31.3	2359	5.26	1602	1.6	107.5	9.5	24	0.3	27.2	0.3	32	0.30	0.082
KYS 110467	Soil		1.2	80.2	29.4	140	1.1	75.4	32.4	2379	5.23	1588	1.6	105.4	9.8	25	0.3	27.7	0.3	31	0.30	0.081
KYS 110468	Soil		1.1	65.5	26.3	101	0.3	48.4	18.4	1218	3.40	261.3	1.5	32.4	8.6	15	0.2	11.2	0.3	23	0.15	0.070
KYS 110469	Soil		1.1	64.4	26.7	105	0.4	40.9	16.3	1057	3.24	245.4	1.5	44.6	9.3	23	0.2	10.2	0.3	18	0.38	0.090
KYS 110470	Soil		1.6	52.0	21.3	77	0.4	30.9	12.3	682	3.03	81.2	1.4	10.9	5.5	25	0.1	6.6	0.2	15	0.43	0.099

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110441	Soil	37	30	0.62	111	0.010	<1	1.61	0.007	0.04	<0.1	0.08	2.1	<0.1	<0.05	4	1.4	0.3
KYS 110442	Soil	36	29	0.65	83	0.007	<1	1.54	0.007	0.03	<0.1	0.08	2.5	<0.1	<0.05	4	2.0	<0.2
KYS 110443	Soil	32	31	0.68	99	0.007	<1	1.57	0.006	0.03	<0.1	0.13	1.8	<0.1	<0.05	4	1.9	0.4
KYS 110444	Soil	37	26	0.75	107	0.005	<1	1.54	0.007	0.03	<0.1	0.09	1.9	<0.1	<0.05	4	1.1	0.3
KYS 110445	Soil	37	28	0.86	116	0.007	<1	1.79	0.008	0.04	<0.1	0.10	2.2	<0.1	<0.05	5	1.1	0.3
KYS 110446	Soil	36	25	0.90	149	0.013	<1	1.90	0.006	0.04	<0.1	0.14	2.2	<0.1	<0.05	5	0.8	<0.2
KYS 110447	Soil	32	28	0.61	130	0.019	<1	1.56	0.008	0.04	0.1	0.08	2.1	<0.1	<0.05	4	1.0	<0.2
KYS 110448	Soil	35	32	0.62	127	0.012	<1	1.62	0.013	0.04	<0.1	0.10	2.0	<0.1	<0.05	4	1.2	<0.2
KYS 110449	Soil	31	27	0.59	121	0.032	<1	1.57	0.008	0.05	0.1	0.11	2.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110450	Soil	24	27	0.39	122	0.038	1	1.35	0.008	0.05	0.2	0.07	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 110451	Soil	25	29	0.44	93	0.027	<1	1.53	0.008	0.05	0.1	0.07	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 110452	Soil	30	26	0.47	164	0.031	<1	1.44	0.008	0.05	0.1	0.09	2.5	<0.1	<0.05	4	0.7	<0.2
KYS 110453	Soil	31	28	0.49	140	0.016	<1	1.73	0.008	0.05	<0.1	0.08	2.2	<0.1	<0.05	5	0.9	<0.2
KYS 110454	Soil	29	10	0.10	102	0.002	<1	0.45	0.008	0.04	<0.1	0.09	2.5	<0.1	<0.05	1	1.4	<0.2
KYS 110455	Soil	27	22	0.42	145	0.019	<1	1.15	0.007	0.04	0.1	0.07	2.6	<0.1	<0.05	3	0.6	<0.2
KYS 110456	Soil	21	21	0.42	128	0.011	<1	1.28	0.008	0.06	<0.1	0.05	1.3	<0.1	<0.05	3	0.9	<0.2
KYS 110457	Soil	24	25	0.46	67	0.024	<1	1.39	0.007	0.06	0.1	0.04	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 110458	Soil	41	16	0.53	61	0.006	<1	1.24	0.005	0.07	<0.1	0.04	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 110459	Soil	23	34	0.97	116	0.010	<1	1.72	0.003	0.06	<0.1	0.04	2.3	<0.1	<0.05	5	<0.5	0.2
KYS 110460	Soil	24	37	1.00	121	0.010	<1	1.81	0.004	0.06	<0.1	0.04	2.5	<0.1	<0.05	6	0.6	<0.2
KYS 110461	Soil	24	29	0.79	116	0.004	<1	1.64	0.006	0.06	<0.1	0.06	1.8	<0.1	<0.05	5	1.1	0.2
KYS 110462	Soil	24	35	0.95	91	0.009	<1	1.62	0.003	0.08	<0.1	0.04	2.4	<0.1	<0.05	5	0.6	<0.2
KYS 110463	Soil	26	21	0.66	78	0.002	<1	1.29	0.004	0.07	<0.1	0.04	2.0	<0.1	<0.05	4	0.7	<0.2
KYS 110464	Soil	19	57	1.29	163	0.021	<1	1.84	0.003	0.07	<0.1	0.05	3.6	<0.1	<0.05	7	0.8	0.3
KYS 110465	Soil	26	45	1.00	105	0.008	<1	1.70	0.003	0.07	<0.1	0.04	2.5	<0.1	<0.05	6	0.8	<0.2
KYS 110466	Soil	22	40	0.91	115	0.002	<1	1.60	0.004	0.05	<0.1	0.07	3.9	<0.1	<0.05	5	1.0	<0.2
KYS 110467	Soil	22	39	0.85	114	0.002	<1	1.54	0.005	0.05	<0.1	0.08	3.8	<0.1	<0.05	5	0.9	<0.2
KYS 110468	Soil	17	20	0.52	93	0.008	<1	1.23	0.004	0.05	<0.1	0.06	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 110469	Soil	19	16	0.50	78	0.006	<1	1.16	0.005	0.06	<0.1	0.04	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 110470	Soil	10	15	0.52	90	0.003	<1	1.01	0.001	0.07	<0.1	0.06	1.3	<0.1	<0.05	2	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110471	Soil		1.7	58.7	30.2	95	0.5	36.4	13.9	815	3.25	172.7	1.4	29.6	6.7	18	0.3	10.7	0.3	17	0.25	0.079
KYS 110472	Soil		2.1	63.3	24.5	93	0.3	38.6	14.8	925	3.23	108.5	1.4	28.9	5.9	14	0.2	8.0	0.3	20	0.16	0.091
KYS 110473	Soil		1.9	81.3	23.3	125	0.5	50.4	13.8	984	3.94	25.9	2.1	15.0	8.2	19	0.1	5.9	0.4	22	0.16	0.070
KYS 110474	Soil		1.2	54.6	21.5	89	0.4	34.6	11.9	776	3.15	238.3	1.2	34.3	7.0	17	0.2	9.9	0.3	19	0.19	0.079
KYS 110475	Soil		1.4	48.3	22.6	91	0.2	34.1	13.4	595	3.24	31.7	1.3	8.5	9.3	13	0.1	4.2	0.3	16	0.18	0.073
KYS 110476	Soil		2.1	57.7	20.7	91	0.4	39.7	15.5	1096	3.40	115.3	1.4	12.8	7.7	17	0.2	7.4	0.2	23	0.22	0.102
KYS 110477	Soil		2.1	59.9	21.1	95	0.4	39.8	15.2	1104	3.44	115.7	1.4	19.9	7.8	17	0.3	7.6	0.2	23	0.23	0.100
KYS 110478	Soil		1.3	57.5	25.1	94	0.4	38.1	12.7	800	3.15	77.4	1.3	26.9	6.8	17	0.2	5.9	0.3	20	0.25	0.070
KYS 110479	Soil		1.8	60.5	41.1	113	0.4	40.8	16.6	898	3.35	95.6	1.7	21.1	8.8	18	0.5	14.9	0.3	15	0.25	0.097
KYS 110480	Soil		1.5	56.9	19.4	90	0.2	34.5	12.7	960	3.06	81.2	1.3	9.2	1.5	9	0.3	3.5	0.3	42	0.07	0.092
KYS 110481	Soil		1.6	40.1	19.9	84	0.2	33.0	13.2	575	2.87	27.7	1.5	6.1	1.9	11	0.2	1.8	0.3	38	0.09	0.075
KYS 110482	Soil		1.5	39.8	16.4	84	0.2	28.2	11.3	521	2.83	20.7	1.2	6.4	2.2	10	0.3	1.6	0.2	43	0.09	0.068
KYS 110483	Soil		1.3	31.5	13.8	67	0.2	22.0	8.2	372	2.53	17.5	1.2	4.1	0.9	9	0.2	1.6	0.2	39	0.07	0.076
KYS 110484	Soil		1.5	41.4	16.5	77	0.2	26.4	10.4	440	2.67	20.2	1.3	13.3	1.7	10	0.2	2.4	0.3	39	0.09	0.073
KYS 110485	Soil		1.3	42.5	16.3	79	0.2	26.7	10.2	441	2.61	20.2	1.4	7.9	1.8	10	0.2	2.4	0.3	38	0.09	0.071

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110471	Soil	14	18	0.55	79	0.004	<1	1.12	0.003	0.06	<0.1	0.06	1.6	<0.1	<0.05	3	0.6	<0.2
KYS 110472	Soil	16	18	0.58	89	0.005	<1	1.22	0.003	0.05	<0.1	0.04	1.6	<0.1	<0.05	3	<0.5	0.5
KYS 110473	Soil	18	19	0.51	70	0.003	<1	1.16	0.006	0.04	<0.1	0.08	1.8	<0.1	<0.05	3	1.1	0.2
KYS 110474	Soil	19	17	0.53	86	0.004	<1	1.21	0.005	0.06	<0.1	0.04	1.6	<0.1	<0.05	3	0.7	0.2
KYS 110475	Soil	22	15	0.41	72	0.007	<1	0.92	0.004	0.06	<0.1	0.08	1.6	<0.1	<0.05	3	0.5	<0.2
KYS 110476	Soil	18	24	0.70	75	0.004	<1	1.16	0.006	0.07	<0.1	0.04	2.2	<0.1	<0.05	3	0.5	<0.2
KYS 110477	Soil	21	25	0.71	77	0.006	<1	1.20	0.003	0.07	<0.1	0.04	2.2	<0.1	<0.05	3	0.8	<0.2
KYS 110478	Soil	16	21	0.56	90	0.004	<1	1.23	0.004	0.06	<0.1	0.06	1.7	<0.1	<0.05	3	0.6	<0.2
KYS 110479	Soil	21	17	0.57	68	0.004	<1	1.11	0.003	0.05	<0.1	0.03	1.3	<0.1	<0.05	3	0.8	<0.2
KYS 110480	Soil	16	26	0.49	113	0.019	<1	1.64	0.005	0.05	0.2	0.04	1.7	<0.1	<0.05	5	0.6	<0.2
KYS 110481	Soil	13	24	0.45	103	0.018	<1	1.51	0.005	0.05	0.1	0.05	1.6	<0.1	<0.05	4	0.7	0.2
KYS 110482	Soil	13	26	0.47	119	0.023	<1	1.55	0.006	0.05	0.2	0.06	2.1	<0.1	<0.05	4	<0.5	<0.2
KYS 110483	Soil	12	22	0.39	83	0.017	<1	1.36	0.005	0.04	0.2	0.05	1.4	0.1	<0.05	4	0.6	<0.2
KYS 110484	Soil	13	23	0.41	113	0.020	1	1.32	0.005	0.05	0.2	0.06	2.0	<0.1	<0.05	4	0.9	<0.2
KYS 110485	Soil	13	23	0.40	112	0.023	<1	1.37	0.007	0.05	0.3	0.06	1.9	<0.1	<0.05	4	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
KYS 110141	Soil	1.8	26.4	13.8	61	0.3	19.7	6.1	266	2.84	19.4	1.0	6.1	1.4	10	0.2	1.5	0.3	52	0.07	0.066
REP KYS 110141	QC	1.9	25.0	13.6	57	0.2	18.1	5.9	259	2.74	18.9	0.9	5.6	1.3	10	0.2	1.4	0.3	52	0.07	0.066
KYS 110195	Soil	14.5	34.6	21.2	86	0.8	20.9	4.9	222	2.79	30.4	2.1	7.7	5.1	11	0.2	7.4	0.3	43	0.07	0.089
REP KYS 110195	QC	13.9	35.0	20.5	90	0.7	20.4	5.0	228	2.62	30.0	2.0	7.9	5.0	11	0.2	7.3	0.4	42	0.08	0.090
KYS 110201	Soil	28.4	68.2	33.7	292	1.3	55.0	11.7	534	3.86	450.8	5.0	68.6	0.9	28	3.8	34.5	0.4	52	0.02	0.133
REP KYS 110201	QC	28.0	69.7	33.8	295	1.3	55.0	11.3	532	3.87	453.0	4.9	71.3	0.8	28	4.0	33.8	0.5	53	0.01	0.128
KYS 110204	Soil	34.9	43.1	26.6	198	0.8	38.3	8.6	380	3.62	52.2	3.9	7.6	1.3	16	0.8	9.3	0.3	58	0.01	0.102
REP KYS 110204	QC	33.8	45.3	25.5	192	0.8	39.3	9.1	371	3.72	51.5	3.6	6.8	1.1	16	1.0	9.1	0.4	54	0.01	0.100
KYS 110224	Soil	1.6	81.5	22.7	103	0.4	45.7	15.3	1119	3.32	22.6	1.5	13.3	5.5	12	0.2	2.1	0.4	36	0.07	0.089
REP KYS 110224	QC	1.5	86.1	22.6	107	0.4	45.3	15.8	1154	3.46	23.8	1.5	22.4	5.5	12	0.2	2.3	0.4	37	0.07	0.088
KYS 110261	Soil	3.1	339.5	70.9	173	0.8	121.4	65.6	9956	5.31	335.2	1.8	69.2	10.9	27	0.3	46.7	0.7	33	0.04	0.109
REP KYS 110261	QC	3.4	337.0	71.8	174	0.9	120.4	65.1	9968	5.35	345.6	1.8	66.4	10.8	25	0.3	45.9	0.7	33	0.04	0.109
KYS 110273	Soil	0.8	43.1	26.5	74	<0.1	50.7	22.1	1804	3.62	12.7	1.5	2.7	10.8	23	0.2	0.5	0.3	18	0.27	0.065
REP KYS 110273	QC	0.8	42.9	26.4	71	0.1	50.6	21.6	1724	3.43	12.8	1.5	1.6	11.1	22	0.2	0.5	0.2	17	0.28	0.064
KYS 110292	Soil	1.9	63.2	28.5	93	0.3	40.1	19.4	982	3.77	55.4	1.5	6.4	12.5	19	0.3	8.2	0.2	16	0.32	0.149
REP KYS 110292	QC	2.1	63.4	30.3	92	0.3	43.0	19.9	995	3.86	55.5	1.6	7.1	13.2	21	0.2	8.6	0.3	17	0.34	0.150
KYS 110307	Soil	1.7	40.1	29.0	93	0.2	38.4	14.4	340	3.53	27.7	1.9	3.3	9.6	18	0.3	8.3	0.3	18	0.21	0.046
REP KYS 110307	QC	1.7	39.9	28.5	93	0.2	38.5	13.9	337	3.46	27.5	1.9	4.0	9.2	17	0.4	8.4	0.3	19	0.21	0.045
KYS 110330	Soil	1.7	28.8	15.4	60	0.6	20.0	5.3	177	2.62	20.1	1.2	8.1	0.5	12	0.3	1.9	0.3	45	0.08	0.067
REP KYS 110330	QC	1.7	28.6	15.3	61	0.6	19.8	5.3	177	2.62	19.7	1.2	5.5	0.6	12	0.3	1.8	0.3	46	0.07	0.064
KYS 110346	Soil	1.0	25.1	16.8	52	0.2	21.0	6.7	210	2.41	35.0	0.7	2.8	4.4	6	<0.1	1.3	0.3	17	0.06	0.046
REP KYS 110346	QC	1.1	25.9	16.4	54	0.2	20.9	7.2	211	2.48	33.9	0.7	6.0	4.3	6	<0.1	1.4	0.3	17	0.06	0.046
KYS 110372	Soil	8.9	69.8	31.3	156	1.6	34.6	6.9	470	4.40	24.8	6.2	4.7	4.2	36	0.9	2.9	0.4	39	0.07	0.155
REP KYS 110372	QC	9.4	70.9	30.1	152	1.7	34.5	7.3	458	4.39	24.7	6.5	3.4	3.7	37	1.1	2.7	0.4	40	0.07	0.153
KYS 110378	Soil	5.1	40.2	36.1	142	0.4	39.3	7.3	339	4.83	25.9	2.9	1.7	12.1	16	0.6	4.5	0.4	25	0.08	0.086
REP KYS 110378	QC	5.1	42.1	35.5	140	0.4	41.4	7.9	348	4.92	25.9	2.9	1.9	12.3	15	0.5	4.6	0.5	27	0.08	0.089
KYS 110418	Soil	3.0	463.0	42.1	174	0.4	150.2	91.0	>10000	3.86	27.1	3.5	91.8	4.2	33	0.5	2.1	0.6	36	0.10	0.121
REP KYS 110418	QC	2.7	462.0	40.7	171	0.4	151.9	90.4	>10000	3.83	26.4	3.5	54.6	4.2	34	0.6	2.1	0.6	36	0.09	0.122

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000118.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
KYS 110141	Soil	11	27	0.33	98	0.027	1	1.53	0.006	0.04	0.2	0.06	1.5	<0.1	<0.05	5	0.7	<0.2
REP KYS 110141	QC	11	26	0.33	92	0.028	<1	1.50	0.005	0.04	0.2	0.07	1.4	<0.1	<0.05	5	1.1	<0.2
KYS 110195	Soil	12	17	0.21	246	0.020	<1	0.82	0.005	0.04	0.2	0.28	1.8	<0.1	<0.05	3	3.6	<0.2
REP KYS 110195	QC	12	16	0.21	245	0.016	<1	0.85	0.005	0.04	0.2	0.25	1.8	<0.1	<0.05	3	3.7	<0.2
KYS 110201	Soil	9	12	0.06	272	0.006	<1	0.59	0.004	0.06	0.2	0.43	0.6	0.2	<0.05	2	5.3	0.2
REP KYS 110201	QC	10	12	0.05	284	0.007	<1	0.57	0.004	0.06	0.2	0.43	0.7	0.2	<0.05	2	5.6	0.4
KYS 110204	Soil	12	13	0.20	343	0.003	1	0.56	0.004	0.07	0.2	0.51	0.5	0.2	0.15	2	7.0	0.3
REP KYS 110204	QC	12	13	0.19	340	0.003	<1	0.52	0.003	0.06	0.2	0.50	0.6	0.2	0.13	2	6.7	<0.2
KYS 110224	Soil	17	32	0.45	108	0.011	1	1.59	0.005	0.04	<0.1	0.06	1.9	<0.1	<0.05	4	1.0	<0.2
REP KYS 110224	QC	19	25	0.45	99	0.011	1	1.57	0.005	0.04	0.1	0.07	2.0	<0.1	<0.05	4	0.9	<0.2
KYS 110261	Soil	33	23	0.60	103	0.003	<1	1.69	0.005	0.04	<0.1	0.09	2.8	<0.1	<0.05	5	1.3	0.4
REP KYS 110261	QC	34	23	0.61	101	0.003	<1	1.76	0.009	0.04	<0.1	0.09	3.0	<0.1	<0.05	5	1.4	0.3
KYS 110273	Soil	24	29	0.82	95	0.008	1	1.40	0.006	0.11	<0.1	0.04	2.4	<0.1	<0.05	4	<0.5	<0.2
REP KYS 110273	QC	24	28	0.83	93	0.008	1	1.41	0.004	0.11	<0.1	0.03	2.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110292	Soil	28	17	0.66	58	0.005	<1	1.21	0.003	0.07	<0.1	0.04	1.8	<0.1	<0.05	3	0.6	<0.2
REP KYS 110292	QC	30	18	0.69	58	0.005	<1	1.26	0.002	0.08	<0.1	0.04	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 110307	Soil	18	32	0.60	575	0.002	<1	1.37	0.003	0.07	<0.1	0.05	1.4	<0.1	<0.05	4	<0.5	<0.2
REP KYS 110307	QC	18	32	0.61	581	0.002	<1	1.40	0.003	0.07	<0.1	0.04	1.3	<0.1	<0.05	3	0.5	<0.2
KYS 110330	Soil	12	26	0.26	105	0.016	1	1.46	0.005	0.05	0.2	0.08	1.1	<0.1	<0.05	5	0.7	<0.2
REP KYS 110330	QC	13	28	0.26	103	0.015	1	1.44	0.005	0.05	0.1	0.07	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 110346	Soil	15	15	0.31	42	0.004	<1	0.87	0.003	0.04	<0.1	0.03	0.9	<0.1	<0.05	3	<0.5	<0.2
REP KYS 110346	QC	17	15	0.31	44	0.005	<1	0.87	0.005	0.04	<0.1	0.03	1.0	<0.1	<0.05	3	0.7	<0.2
KYS 110372	Soil	23	20	0.26	144	0.006	<1	1.18	0.004	0.05	0.1	0.15	0.9	<0.1	0.07	3	4.2	0.5
REP KYS 110372	QC	23	20	0.27	146	0.007	<1	1.23	0.004	0.05	0.1	0.14	1.0	<0.1	0.07	3	4.4	<0.2
KYS 110378	Soil	16	18	0.43	85	0.003	<1	1.56	0.003	0.06	<0.1	0.04	0.9	<0.1	0.05	3	3.0	<0.2
REP KYS 110378	QC	16	18	0.43	84	0.003	<1	1.56	0.004	0.05	<0.1	0.05	1.1	<0.1	0.05	3	3.0	<0.2
KYS 110418	Soil	20	24	0.50	178	0.008	<1	1.77	0.006	0.04	<0.1	0.24	1.7	<0.1	<0.05	5	1.2	0.3
REP KYS 110418	QC	19	24	0.53	180	0.008	<1	1.84	0.004	0.03	<0.1	0.24	1.7	<0.1	<0.05	5	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000118.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
KYS 110426	Soil	1.9	21.0	16.3	61	0.2	18.0	5.9	239	2.64	18.6	1.1	8.6	0.6	11	0.2	1.5	0.3	49	0.06	0.079
REP KYS 110426	QC	1.9	20.9	16.3	63	0.2	17.8	6.1	234	2.65	18.2	1.1	4.3	0.8	11	0.1	1.5	0.3	49	0.06	0.078
KYS 110453	Soil	2.4	225.5	33.7	147	0.4	95.2	44.1	5563	4.09	168.1	3.0	71.6	5.1	26	0.3	11.2	0.4	44	0.06	0.098
REP KYS 110453	QC	2.6	220.8	32.5	146	0.4	94.9	43.4	5413	4.03	166.6	2.9	60.4	5.3	26	0.3	11.0	0.4	42	0.05	0.098
KYS 110459	Soil	1.4	92.0	27.3	113	0.2	56.8	25.8	1834	4.37	19.7	1.7	9.6	10.8	19	0.2	1.9	0.3	28	0.18	0.066
REP KYS 110459	QC	1.5	93.1	27.5	115	0.2	58.1	26.2	1899	4.48	20.1	1.6	14.5	10.4	19	0.2	2.0	0.3	31	0.17	0.066
KYS 110483	Soil	1.3	31.5	13.8	67	0.2	22.0	8.2	372	2.53	17.5	1.2	4.1	0.9	9	0.2	1.6	0.2	39	0.07	0.076
REP KYS 110483	QC	1.3	29.9	14.1	66	0.2	21.9	8.3	372	2.55	17.4	1.1	10.2	0.9	8	0.2	1.7	0.2	40	0.07	0.076
Reference Materials																					
STD DS7	Standard	18.7	96.7	64.8	361	0.9	49.4	8.1	544	2.08	46.7	4.3	72.3	3.8	61	5.7	5.0	4.0	74	0.82	0.073
STD DS7	Standard	19.7	98.8	65.2	362	0.9	53.8	8.9	618	2.32	51.2	4.6	72.2	4.6	73	6.0	5.6	4.3	82	0.98	0.073
STD DS7	Standard	22.2	108.7	65.5	401	1.0	57.3	9.5	640	2.50	55.1	4.6	67.9	4.5	75	6.4	5.9	4.6	87	1.00	0.080
STD DS7	Standard	21.1	108.7	70.9	413	1.1	58.7	9.8	670	2.56	55.7	5.7	84.8	5.1	80	6.8	6.3	5.0	87	0.96	0.083
STD DS7	Standard	21.4	113.6	69.4	408	1.1	59.5	9.5	653	2.45	55.4	5.5	75.9	5.1	82	6.1	6.3	5.1	88	0.99	0.080
STD DS7	Standard	24.6	131.1	74.3	448	1.1	69.5	11.3	699	2.73	57.6	5.3	87.1	5.3	82	7.4	6.6	5.1	103	1.09	0.084
STD DS7	Standard	20.9	112.9	67.6	392	1.1	57.2	9.3	612	2.35	49.4	4.5	73.2	4.4	74	5.7	5.9	4.6	83	0.92	0.075
STD DS7	Standard	20.6	104.8	69.5	373	1.0	54.4	9.3	615	2.30	48.3	4.7	88.0	4.3	66	5.7	4.1	4.6	83	0.87	0.073
STD DS7	Standard	22.2	121.1	71.6	414	1.1	62.8	10.3	636	2.44	49.7	5.0	73.3	5.1	75	6.6	5.6	4.7	92	0.96	0.072
STD DS7	Standard	21.8	119.3	73.4	416	1.0	61.7	10.1	672	2.51	53.5	5.0	64.9	4.7	69	7.2	6.3	4.8	92	0.99	0.081
STD DS7	Standard	20.8	109.8	67.1	396	1.0	53.4	9.4	664	2.46	55.9	4.6	85.6	4.9	78	6.7	6.2	4.7	86	0.96	0.079
STD DS7	Standard	22.7	122.3	73.2	410	1.1	59.2	10.0	624	2.39	51.6	5.0	68.2	5.0	79	6.2	6.4	4.7	89	0.89	0.075
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.03	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000118.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
KYS 110426	Soil	11	28	0.31	77	0.016	<1	1.50	0.006	0.04	0.1	0.05	1.1	<0.1	<0.05	5	0.9	<0.2
REP KYS 110426	QC	11	27	0.29	74	0.014	7	1.44	0.006	0.04	0.1	0.04	1.1	<0.1	<0.05	5	0.7	<0.2
KYS 110453	Soil	31	28	0.49	140	0.016	<1	1.73	0.008	0.05	<0.1	0.08	2.2	<0.1	<0.05	5	0.9	<0.2
REP KYS 110453	QC	29	27	0.47	140	0.016	<1	1.64	0.008	0.05	<0.1	0.08	2.2	<0.1	<0.05	4	0.8	<0.2
KYS 110459	Soil	23	34	0.97	116	0.010	<1	1.72	0.003	0.06	<0.1	0.04	2.3	<0.1	<0.05	5	<0.5	0.2
REP KYS 110459	QC	24	36	0.99	122	0.010	<1	1.68	0.003	0.06	<0.1	0.04	2.3	<0.1	<0.05	6	<0.5	0.2
KYS 110483	Soil	12	22	0.39	83	0.017	<1	1.36	0.005	0.04	0.2	0.05	1.4	0.1	<0.05	4	0.6	<0.2
REP KYS 110483	QC	11	22	0.38	80	0.016	<1	1.36	0.005	0.04	0.2	0.06	1.4	<0.1	<0.05	4	0.7	<0.2
Reference Materials																		
STD DS7	Standard	11	195	1.02	356	0.105	32	0.97	0.095	0.46	3.3	0.20	2.2	3.9	0.18	4	2.7	1.1
STD DS7	Standard	13	224	1.04	395	0.119	38	1.04	0.104	0.45	3.6	0.23	2.6	3.9	0.20	5	3.4	1.2
STD DS7	Standard	13	233	1.09	420	0.122	39	1.08	0.106	0.48	3.7	0.23	2.5	4.2	0.23	5	3.7	0.9
STD DS7	Standard	13	221	1.10	440	0.130	39	1.06	0.101	0.49	3.9	0.23	2.7	4.2	0.22	5	3.8	0.9
STD DS7	Standard	14	220	1.08	413	0.136	44	1.07	0.104	0.49	3.7	0.20	2.4	4.1	0.19	5	3.4	1.3
STD DS7	Standard	14	260	1.16	429	0.155	43	1.13	0.116	0.53	3.8	0.23	2.7	4.3	0.23	5	3.2	1.4
STD DS7	Standard	13	213	1.01	375	0.126	39	1.07	0.101	0.46	3.7	0.22	2.4	4.2	0.19	5	3.2	1.5
STD DS7	Standard	11	212	1.04	388	0.101	38	1.01	0.101	0.47	1.9	0.21	2.4	3.9	0.18	5	2.9	0.4
STD DS7	Standard	14	235	1.05	378	0.135	35	1.03	0.103	0.48	3.6	0.24	2.8	4.1	0.21	5	2.7	2.0
STD DS7	Standard	13	205	1.10	447	0.129	39	1.06	0.100	0.50	3.9	0.24	2.6	4.3	0.19	5	3.5	1.3
STD DS7	Standard	14	209	1.04	419	0.128	38	1.02	0.103	0.48	3.7	0.24	2.7	4.3	0.19	5	3.8	0.8
STD DS7	Standard	14	201	1.02	408	0.137	39	1.00	0.099	0.47	3.8	0.22	2.3	4.0	0.19	5	2.6	1.1
STD DS7 Expected		12	179	1.05	410	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5	1.08
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000118.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000118.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Submitted By: Johnathan More
Receiving Lab: Canada-Whitehorse
Received: July 14, 2010
Report Date: August 23, 2010
Page: 1 of 11

CERTIFICATE OF ANALYSIS WHI10000117.1

CLIENT JOB INFORMATION

Project: KYS
Shipment ID: KYS1
P.O. Number
Number of Samples: 300

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	300	Dry at 60C sieve 100g to -80 mesh			VAN
Dry at 60C	300	Dry at 60C			VAN
1DX2	299	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Aldrin Resources
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5
Canada

CC: Isaac Fage
Bert Jeffries
Shawn Ryan

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109438	Soil	1.8	51.0	14.1	60	<0.1	22.3	6.9	597	2.44	9.1	0.8	7.8	0.5	9	0.1	1.1	0.3	51	0.03	0.058
KYS 109439	Soil	1.2	63.3	16.5	85	0.1	28.5	7.5	520	2.96	9.5	1.1	20.5	3.8	16	0.2	1.2	0.3	44	0.09	0.060
KYS 109501	Soil	3.0	67.9	31.1	61	0.6	21.9	5.5	232	3.96	62.9	1.1	14.1	5.5	12	0.2	5.1	0.5	25	0.02	0.081
KYS 109502	Soil	0.5	25.7	22.0	57	<0.1	32.3	12.7	240	4.35	11.5	1.0	1.8	11.8	4	<0.1	0.6	0.4	16	0.05	0.039
KYS 109503	Soil	7.8	64.6	29.4	193	0.9	54.1	12.2	475	3.90	27.4	3.2	7.3	3.4	39	2.3	4.2	0.4	29	0.42	0.116
KYS 109504	Soil	2.4	90.0	31.0	106	0.4	42.3	14.2	588	4.34	59.5	1.0	14.3	5.6	12	0.2	4.6	0.5	29	0.07	0.082
KYS 109505	Soil	3.1	114.9	35.4	105	0.6	38.4	7.3	283	4.71	120.3	1.3	17.6	4.9	14	0.1	5.5	0.6	35	0.01	0.100
KYS 109506	Soil	2.9	105.7	37.1	97	0.6	35.2	6.9	270	4.49	105.8	1.3	16.6	4.6	13	<0.1	5.2	0.6	35	<0.01	0.096
KYS 109507	Soil	3.0	93.8	36.7	87	0.7	29.8	5.0	171	4.18	77.3	1.2	24.8	4.3	14	<0.1	3.7	0.6	34	0.01	0.091
KYS 109508	Soil	3.1	95.1	35.8	77	0.6	26.7	4.5	148	3.96	32.0	1.3	10.1	2.8	14	0.1	3.5	0.6	40	0.02	0.122
KYS 109509	Soil	2.5	42.5	25.5	37	1.7	10.5	2.1	73	2.06	19.4	0.8	3.9	0.3	8	0.2	2.7	0.4	39	0.02	0.105
KYS 109510	Soil	3.2	65.7	31.5	51	0.8	17.0	3.4	199	4.99	34.1	0.7	55.0	4.1	9	<0.1	3.7	0.6	61	0.01	0.091
KYS 109511	Soil	3.1	64.4	35.8	60	0.6	25.1	3.3	138	3.66	28.8	1.1	5.0	7.7	18	<0.1	7.0	0.6	32	0.01	0.097
KYS 109512	Soil	2.9	117.2	29.6	85	0.8	33.0	6.5	247	4.53	31.9	1.2	15.7	5.1	16	0.1	4.0	0.5	52	0.02	0.085
KYS 109513	Soil	2.8	79.5	30.7	82	0.4	26.8	5.6	251	4.65	28.3	1.0	20.0	3.8	17	<0.1	2.6	0.6	60	0.02	0.098
KYS 109514	Soil	3.8	78.5	55.6	100	1.1	28.5	5.3	255	5.69	45.7	0.9	39.9	1.8	21	<0.1	5.9	1.1	66	0.03	0.140
KYS 109515	Soil	1.9	26.4	16.8	66	0.3	23.2	8.8	266	3.29	23.6	1.3	2.7	6.3	10	0.1	1.7	0.3	70	0.07	0.051
KYS 109518	Soil	2.1	26.3	16.5	64	0.3	22.3	8.6	257	3.18	24.5	1.0	4.0	6.0	11	0.3	1.7	0.3	61	0.07	0.080
KYS 109519	Soil	2.2	34.4	22.3	70	0.9	20.8	5.5	228	3.32	26.4	0.6	6.4	1.7	12	0.2	2.2	0.4	47	0.05	0.082
KYS 109520	Soil	1.2	62.4	36.1	112	0.1	75.0	27.5	951	4.92	20.1	1.2	2.7	12.2	10	0.2	1.1	0.4	26	0.12	0.081
KYS 109521	Soil	1.1	42.7	22.6	87	0.1	40.9	14.3	367	3.70	16.8	1.0	3.4	9.3	12	0.1	1.2	0.3	27	0.15	0.057
KYS 109522	Soil	1.4	30.9	22.8	76	0.1	36.0	10.8	296	4.04	25.2	0.7	13.4	4.8	9	0.1	1.2	0.3	44	0.08	0.054
KYS 109523	Soil	1.8	34.4	15.7	67	0.4	23.5	7.0	354	2.76	49.1	0.9	5.4	1.1	5	<0.1	2.4	0.2	29	0.02	0.067
KYS 109524	Soil	2.1	59.0	17.6	96	0.3	49.8	19.4	823	3.37	68.0	2.1	5.9	2.7	17	0.3	2.2	0.3	42	0.23	0.105
KYS 109525	Soil	1.2	34.1	19.8	62	0.1	25.6	8.2	201	2.98	45.9	0.8	2.8	3.9	7	<0.1	1.7	0.4	28	0.06	0.051
KYS 109526	Soil	1.3	84.1	25.2	101	<0.1	48.3	15.9	312	4.05	51.5	1.2	4.0	6.5	6	0.2	2.1	0.4	24	0.07	0.064
KYS 109527	Soil	1.5	34.5	22.0	78	0.1	30.1	14.4	556	3.39	34.0	1.0	5.2	5.5	10	0.2	1.8	0.3	26	0.11	0.076
KYS 109528	Soil	1.3	50.3	22.0	98	0.1	49.4	19.6	635	4.16	27.4	1.5	3.1	11.6	12	0.2	2.0	0.3	24	0.21	0.061
KYS 109529	Soil	1.2	64.8	28.0	104	0.1	51.8	20.3	779	4.39	30.5	1.5	3.7	16.7	19	0.2	3.0	0.4	14	0.39	0.063
KYS 109530	Soil	1.5	71.4	33.6	109	0.2	63.9	22.7	685	4.80	38.1	1.4	3.2	16.7	18	0.2	3.6	0.4	17	0.36	0.055

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109438	Soil	17	21	0.30	75	0.017	<1	1.06	0.007	0.03	0.1	0.07	0.5	<0.1	<0.05	5	<0.5	0.2
KYS 109439	Soil	20	29	0.52	75	0.032	<1	1.51	0.006	0.03	0.2	0.06	1.8	<0.1	<0.05	4	<0.5	0.3
KYS 109501	Soil	6	20	0.13	86	0.004	<1	0.97	0.012	0.03	<0.1	0.10	1.4	<0.1	<0.05	3	2.2	<0.2
KYS 109502	Soil	26	18	0.50	43	0.003	<1	1.46	0.004	0.05	<0.1	0.02	0.9	<0.1	<0.05	5	<0.5	0.2
KYS 109503	Soil	10	23	0.33	1190	0.004	<1	1.10	0.006	0.03	<0.1	0.21	1.5	<0.1	<0.05	3	2.7	<0.2
KYS 109504	Soil	10	21	0.29	110	0.004	<1	1.03	0.007	0.04	<0.1	0.08	2.0	<0.1	<0.05	4	1.4	<0.2
KYS 109505	Soil	7	26	0.29	102	0.002	<1	1.24	0.008	0.04	<0.1	0.11	2.6	<0.1	<0.05	4	2.5	0.2
KYS 109506	Soil	7	24	0.28	96	0.002	<1	1.16	0.009	0.03	<0.1	0.11	2.3	<0.1	<0.05	4	2.4	0.2
KYS 109507	Soil	6	25	0.25	117	0.002	<1	1.16	0.009	0.03	<0.1	0.11	2.1	<0.1	<0.05	4	2.4	<0.2
KYS 109508	Soil	7	26	0.23	114	0.004	<1	1.34	0.008	0.03	<0.1	0.12	2.0	<0.1	<0.05	4	2.1	<0.2
KYS 109509	Soil	6	19	0.08	87	0.005	<1	0.81	0.009	0.03	<0.1	0.12	0.5	<0.1	<0.05	4	1.1	<0.2
KYS 109510	Soil	9	31	0.19	109	0.007	<1	1.39	0.006	0.03	<0.1	0.09	1.6	<0.1	<0.05	6	2.1	0.3
KYS 109511	Soil	6	23	0.22	137	0.002	<1	1.18	0.008	0.03	<0.1	0.10	2.4	<0.1	<0.05	3	2.3	0.3
KYS 109512	Soil	8	31	0.32	166	0.006	<1	1.58	0.010	0.04	<0.1	0.11	2.3	<0.1	<0.05	5	2.2	0.3
KYS 109513	Soil	9	34	0.29	193	0.008	<1	1.63	0.008	0.04	0.1	0.10	1.9	<0.1	<0.05	6	2.1	0.3
KYS 109514	Soil	7	37	0.25	104	0.009	<1	1.55	0.007	0.03	<0.1	0.08	1.5	<0.1	<0.05	7	3.3	0.3
KYS 109515	Soil	15	37	0.39	121	0.049	1	2.15	0.006	0.04	0.2	0.05	3.7	0.1	<0.05	6	0.7	<0.2
KYS 109518	Soil	13	34	0.34	122	0.037	<1	1.92	0.007	0.04	0.2	0.09	2.6	<0.1	<0.05	6	0.7	<0.2
KYS 109519	Soil	10	22	0.21	89	0.022	<1	1.02	0.007	0.04	0.1	0.06	1.4	<0.1	<0.05	4	0.8	<0.2
KYS 109520	Soil	26	47	0.71	158	0.007	<1	1.90	0.005	0.06	<0.1	0.04	2.5	<0.1	<0.05	5	<0.5	<0.2
KYS 109521	Soil	31	28	0.46	146	0.009	<1	1.51	0.008	0.07	<0.1	0.03	2.1	<0.1	<0.05	5	<0.5	<0.2
KYS 109522	Soil	20	40	0.47	79	0.021	<1	1.81	0.006	0.06	0.1	0.03	2.1	<0.1	<0.05	6	<0.5	<0.2
KYS 109523	Soil	12	23	0.31	49	0.006	<1	0.95	0.004	0.03	0.2	0.04	0.8	<0.1	<0.05	4	0.7	<0.2
KYS 109524	Soil	16	34	0.45	154	0.023	<1	1.50	0.006	0.03	0.2	0.04	2.3	<0.1	<0.05	4	0.7	<0.2
KYS 109525	Soil	21	22	0.36	49	0.012	<1	1.20	0.005	0.04	<0.1	0.04	1.4	<0.1	<0.05	5	<0.5	<0.2
KYS 109526	Soil	26	22	0.49	41	0.010	<1	1.22	0.005	0.06	<0.1	0.02	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109527	Soil	15	27	0.43	66	0.009	<1	1.16	0.005	0.05	<0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 109528	Soil	24	36	0.63	145	0.005	<1	1.64	0.005	0.06	<0.1	0.03	2.7	<0.1	<0.05	5	<0.5	<0.2
KYS 109529	Soil	27	25	0.60	107	0.003	<1	1.49	0.005	0.06	<0.1	0.03	2.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109530	Soil	23	30	0.70	108	0.002	<1	1.60	0.005	0.06	<0.1	0.03	2.9	<0.1	<0.05	4	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109531	Soil	1.4	71.8	33.5	114	0.2	60.6	22.3	732	4.75	35.7	1.4	5.3	16.9	20	0.2	3.3	0.4	18	0.43	0.057
KYS 109532	Soil	0.6	73.7	37.0	104	<0.1	50.3	22.9	412	4.34	587.3	2.0	10.0	20.8	43	<0.1	2.7	0.5	8	0.69	0.058
KYS 109533	Soil	3.9	100.9	30.6	103	0.5	46.1	13.6	389	4.64	39.1	1.6	7.0	7.3	23	0.3	4.6	0.4	38	0.16	0.120
KYS 109534	Soil	1.7	95.6	27.9	93	0.2	48.6	19.0	624	4.77	192.1	1.3	8.5	10.1	13	0.1	5.5	0.4	17	0.12	0.071
KYS 109535	Soil	1.0	98.5	36.1	110	0.2	58.4	33.1	827	4.96	27.3	3.4	3.2	4.8	19	0.2	1.1	0.5	15	0.20	0.089
KYS 109536	Soil	1.2	85.2	30.7	138	<0.1	75.5	31.3	727	4.58	26.1	3.4	2.6	9.6	19	0.2	1.1	0.4	18	0.27	0.112
KYS 109537	Soil	0.9	73.1	43.0	120	0.1	61.6	41.7	645	4.60	17.2	4.1	7.1	3.5	19	0.2	0.6	0.4	14	0.06	0.075
KYS 109538	Soil	0.9	28.2	29.0	60	<0.1	18.5	8.3	210	2.92	11.6	1.1	2.4	3.1	7	0.1	0.6	0.2	26	0.04	0.042
KYS 109539	Soil	0.8	28.6	30.9	57	<0.1	16.2	7.8	237	3.01	9.9	0.9	3.0	4.6	8	<0.1	0.6	0.3	27	0.06	0.050
KYS 109540	Soil	1.1	30.1	20.7	58	<0.1	20.4	10.1	402	3.29	12.4	1.0	3.6	5.1	8	0.2	0.7	0.3	32	0.07	0.056
KYS 109541	Soil	1.0	35.0	28.6	77	<0.1	31.5	14.9	475	3.23	11.4	1.4	1.5	4.0	8	<0.1	1.6	0.3	29	0.09	0.042
KYS 109542	Soil	0.9	24.5	16.0	69	<0.1	21.7	10.0	381	2.84	11.1	0.9	2.2	3.0	8	0.2	0.8	0.2	38	0.09	0.053
KYS 109543	Soil	0.9	24.4	15.2	68	<0.1	20.2	9.7	370	2.74	11.0	1.0	3.1	2.9	9	0.2	0.7	0.2	39	0.10	0.055
KYS 109544	Soil	1.2	23.2	14.8	62	<0.1	20.0	10.5	452	3.23	12.7	0.9	3.8	1.7	7	0.2	0.6	0.2	37	0.06	0.049
KYS 109545	Soil	1.1	23.3	17.0	67	<0.1	19.1	9.3	321	3.07	12.4	0.9	1.8	1.8	10	0.2	0.6	0.2	38	0.06	0.048
KYS 109546	Soil	1.2	19.9	14.6	58	<0.1	16.9	7.4	267	2.87	12.3	0.8	5.1	1.3	8	0.2	0.6	0.2	40	0.05	0.046
KYS 109547	Soil	1.3	19.6	15.3	61	<0.1	16.6	9.5	479	3.11	13.2	0.9	1.2	0.8	8	0.2	0.6	0.2	43	0.05	0.055
KYS 109548	Soil	1.2	24.2	16.1	70	<0.1	23.4	11.8	609	3.08	15.2	0.8	1.4	1.3	7	0.2	0.6	0.2	38	0.07	0.074
KYS 109549	Soil	1.4	11.8	13.2	45	0.1	12.1	5.0	254	2.62	11.8	0.6	2.6	0.9	6	0.2	0.6	0.2	48	0.04	0.051
KYS 109550	Soil	1.2	31.3	15.5	96	<0.1	33.1	11.3	438	3.12	13.5	1.3	4.3	3.3	9	0.6	0.8	0.2	43	0.09	0.057
KYS 109551	Soil	1.8	34.9	16.5	111	0.1	37.1	13.9	385	2.72	11.2	1.3	5.2	3.7	13	0.9	0.8	0.2	38	0.10	0.069
KYS 109552	Soil	3.2	60.6	16.2	110	0.1	33.9	11.9	356	2.90	13.3	2.2	2.9	5.7	19	0.6	1.6	0.3	41	0.10	0.077
KYS 109553	Soil	2.5	49.6	15.4	125	0.2	43.8	15.9	396	3.15	11.8	1.5	3.0	2.3	12	0.7	1.0	0.2	38	0.10	0.073
KYS 109554	Soil	1.6	52.9	12.8	118	0.1	38.1	15.3	515	2.74	10.1	1.7	3.7	6.2	11	0.5	0.9	0.2	37	0.11	0.066
KYS 109555	Soil	1.6	49.9	12.6	116	0.1	39.3	15.3	515	2.70	9.8	1.7	4.2	6.2	11	0.5	0.9	0.2	34	0.11	0.067
KYS 109556	Soil	2.8	55.9	10.7	86	0.2	24.3	10.1	526	2.52	14.3	1.9	4.0	5.4	16	0.4	1.4	0.2	41	0.15	0.098
KYS 109557	Soil	4.0	50.4	12.5	83	0.3	20.6	7.5	271	2.51	13.7	1.7	5.2	4.2	16	0.2	1.7	0.2	44	0.11	0.085
KYS 109558	Soil	4.0	35.8	9.6	56	0.2	19.1	5.3	193	1.95	12.8	2.2	8.2	1.6	12	0.2	1.9	0.2	43	0.10	0.067
KYS 109559	Soil	4.5	24.2	9.3	58	0.2	14.6	4.9	223	2.21	12.5	1.3	2.1	1.0	17	0.2	1.8	0.2	49	0.10	0.068
KYS 109560	Soil	7.0	39.8	17.2	83	0.4	20.1	7.1	259	2.55	24.8	4.0	2.5	2.5	25	0.4	3.0	0.2	40	0.09	0.107

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109531	Soil	24	30	0.70	114	0.002	<1	1.58	0.005	0.06	<0.1	0.03	3.1	<0.1	<0.05	4	0.5	<0.2
KYS 109532	Soil	28	15	0.36	63	0.004	<1	0.98	0.005	0.13	<0.1	0.02	2.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109533	Soil	12	35	0.46	346	0.004	<1	1.42	0.009	0.07	<0.1	0.07	3.1	<0.1	0.05	4	2.5	<0.2
KYS 109534	Soil	17	17	0.33	73	0.001	<1	0.94	0.006	0.06	<0.1	0.04	2.7	<0.1	<0.05	3	1.3	<0.2
KYS 109535	Soil	14	27	0.74	37	0.005	<1	1.75	0.007	0.06	<0.1	0.05	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 109536	Soil	19	24	0.65	66	0.006	<1	1.52	0.007	0.05	<0.1	0.04	2.3	<0.1	<0.05	4	<0.5	0.4
KYS 109537	Soil	11	17	0.51	46	0.005	1	1.47	0.006	0.04	<0.1	0.04	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 109538	Soil	13	15	0.29	45	0.010	1	0.95	0.004	0.03	0.2	0.04	0.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109539	Soil	17	18	0.31	46	0.015	<1	1.07	0.004	0.03	0.1	0.04	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 109540	Soil	21	22	0.37	48	0.023	1	1.12	0.004	0.03	0.1	0.05	1.1	<0.1	<0.05	4	0.5	<0.2
KYS 109541	Soil	22	18	0.35	85	0.014	<1	1.20	0.002	0.03	0.2	0.04	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109542	Soil	16	24	0.41	77	0.027	<1	1.48	0.005	0.04	0.2	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109543	Soil	16	24	0.40	81	0.028	1	1.48	0.005	0.04	0.2	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109544	Soil	18	24	0.42	80	0.015	<1	1.50	0.004	0.03	0.1	0.03	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109545	Soil	17	25	0.41	84	0.020	1	1.46	0.005	0.04	0.2	0.04	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 109546	Soil	17	26	0.38	68	0.021	<1	1.45	0.003	0.03	0.1	0.04	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 109547	Soil	15	25	0.39	73	0.020	<1	1.42	0.004	0.04	0.1	0.03	1.1	0.1	<0.05	5	<0.5	<0.2
KYS 109548	Soil	17	24	0.40	61	0.025	1	1.31	0.005	0.04	0.1	0.03	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 109549	Soil	15	19	0.18	59	0.020	<1	1.03	0.005	0.03	0.2	0.03	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 109550	Soil	16	27	0.41	119	0.023	<1	1.80	0.005	0.04	0.2	0.04	2.1	0.1	<0.05	5	0.6	<0.2
KYS 109551	Soil	21	23	0.32	90	0.022	<1	1.33	0.005	0.03	0.2	0.05	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109552	Soil	21	24	0.38	137	0.023	1	1.35	0.006	0.04	0.1	0.05	2.2	<0.1	<0.05	3	0.7	<0.2
KYS 109553	Soil	21	26	0.39	93	0.019	2	1.67	0.004	0.04	0.1	0.05	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109554	Soil	22	25	0.39	102	0.027	<1	1.54	0.006	0.03	0.1	0.05	2.3	<0.1	<0.05	3	0.5	<0.2
KYS 109555	Soil	22	24	0.39	101	0.028	<1	1.56	0.006	0.04	0.2	0.04	2.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109556	Soil	21	28	0.36	104	0.031	<1	1.52	0.007	0.04	0.2	0.07	2.6	<0.1	<0.05	3	1.0	<0.2
KYS 109557	Soil	28	29	0.39	127	0.021	<1	1.54	0.005	0.04	0.1	0.12	1.7	<0.1	<0.05	4	1.0	<0.2
KYS 109558	Soil	20	21	0.30	121	0.027	1	1.26	0.005	0.04	0.2	0.12	2.0	0.1	<0.05	4	0.7	<0.2
KYS 109559	Soil	19	24	0.32	82	0.022	<1	1.13	0.005	0.03	0.2	0.04	1.1	<0.1	<0.05	4	0.8	<0.2
KYS 109560	Soil	28	22	0.34	153	0.016	<1	1.36	0.005	0.04	0.2	0.14	1.8	0.1	<0.05	4	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109561	Soil	7.3	28.2	15.6	77	0.5	18.4	8.3	341	3.21	19.3	1.3	2.7	2.2	17	0.5	1.8	0.2	57	0.10	0.112
KYS 109562	Soil	4.0	29.7	13.8	58	0.2	16.7	6.3	186	2.37	13.8	1.6	3.1	2.1	17	0.4	1.4	0.2	48	0.07	0.081
KYS 109563	Soil	6.3	57.5	12.4	86	0.4	26.7	8.0	263	2.40	19.1	3.8	2.8	5.8	24	0.6	2.9	0.2	42	0.15	0.102
KYS 109564	Soil	5.3	43.9	17.6	76	0.3	16.8	5.9	266	2.90	18.3	2.4	3.5	5.4	21	0.3	2.4	0.3	51	0.08	0.097
KYS 109565	Soil	6.0	73.8	18.3	96	0.5	22.7	9.0	403	2.90	19.3	4.1	4.5	4.7	22	0.3	2.4	0.3	52	0.07	0.088
KYS 109566	Soil	4.0	33.6	17.9	76	0.3	15.1	4.9	200	3.05	11.5	1.5	3.4	4.0	16	0.3	1.3	0.3	46	0.07	0.089
KYS 109567	Soil	4.2	42.5	15.0	83	0.2	21.1	8.8	369	2.88	14.9	2.6	3.7	5.5	18	0.2	2.1	0.2	48	0.08	0.071
KYS 109601	Soil	2.7	51.5	28.2	90	0.5	24.9	5.1	275	3.90	48.6	0.7	11.3	4.3	11	0.1	3.2	0.4	34	0.01	0.074
KYS 109602	Soil	2.7	49.5	27.1	81	0.4	24.9	5.3	272	3.88	44.2	0.7	14.9	3.8	11	<0.1	3.0	0.4	34	0.02	0.077
KYS 109603	Soil	10.1	41.4	23.3	144	0.6	35.0	13.0	555	3.50	19.1	2.1	5.2	3.9	19	0.9	3.2	0.3	27	0.04	0.078
KYS 109604	Soil	3.0	56.3	30.1	96	0.7	32.8	5.3	268	3.78	23.8	1.0	12.1	5.6	16	0.6	2.5	0.5	34	0.04	0.079
KYS 109605	Soil	2.8	109.9	30.5	79	1.0	25.0	4.5	279	4.78	37.1	1.2	16.6	2.6	10	0.1	3.6	0.5	39	0.01	0.115
KYS 109606	Soil	2.9	91.0	42.9	86	0.8	25.6	4.7	194	5.27	52.2	1.2	6.2	6.6	14	<0.1	4.6	0.7	34	<0.01	0.131
KYS 109607	Soil	2.6	76.8	35.6	70	1.9	17.8	3.5	230	3.91	44.4	0.9	13.1	1.5	8	0.1	3.8	0.7	33	0.01	0.129
KYS 109608	Soil	2.5	78.4	36.4	71	0.6	20.6	3.4	127	3.75	44.5	1.1	2.6	6.7	10	<0.1	6.0	0.6	30	<0.01	0.098
KYS 109609	Soil	2.8	40.8	34.5	56	1.3	24.3	6.7	331	3.69	32.3	1.7	8.7	3.8	19	0.4	4.2	0.5	28	0.03	0.151
KYS 109610	Soil	2.4	52.3	35.2	50	0.8	16.1	3.3	172	4.29	30.4	1.4	14.2	2.7	13	<0.1	4.2	0.7	45	0.01	0.113
KYS 109611	Soil	2.0	26.5	16.9	46	0.4	15.3	4.4	259	3.33	18.1	0.8	11.9	1.3	8	0.1	1.6	0.4	58	0.04	0.100
KYS 109612	Soil	1.8	29.7	17.2	61	0.8	19.3	7.6	266	3.27	18.1	1.1	4.7	4.9	11	0.2	1.2	0.4	59	0.05	0.052
KYS 109613	Soil	2.1	30.3	32.0	64	3.2	16.4	5.9	271	3.70	370.6	0.8	164.7	3.3	9	0.2	12.2	0.5	54	0.04	0.075
KYS 109614	Soil	1.8	47.1	27.1	84	0.7	29.7	10.6	323	4.10	79.3	1.1	19.6	4.0	11	0.2	6.7	0.3	38	0.05	0.092
KYS 109615	Soil	1.6	33.9	19.5	75	0.7	26.7	11.4	552	3.40	86.8	0.9	12.6	3.9	11	0.2	4.5	0.3	49	0.07	0.077
KYS 109616	Soil	1.4	46.8	20.5	74	0.3	32.6	8.7	368	2.84	58.2	1.3	15.5	4.4	11	0.2	4.0	0.4	32	0.04	0.053
KYS 109617	Soil	1.4	39.5	17.4	74	0.3	29.9	9.0	353	2.84	47.9	1.2	14.7	4.2	12	0.2	3.3	0.3	37	0.07	0.061
KYS 109618	Soil	1.6	25.0	19.9	50	0.7	16.5	4.3	150	2.36	59.8	0.7	7.7	0.5	10	0.1	3.8	0.3	41	0.03	0.058
KYS 109619	Soil	1.4	28.0	14.7	63	0.2	22.8	7.1	286	2.76	34.5	0.9	9.1	3.4	12	0.2	2.6	0.3	43	0.09	0.065
KYS 109620	Soil	1.4	25.9	16.3	63	0.4	19.5	11.4	519	2.70	29.9	1.1	5.9	1.2	14	0.3	1.8	0.3	42	0.11	0.092
KYS 109621	Soil	1.3	32.3	19.6	66	0.2	25.2	11.3	499	2.50	33.0	1.4	7.1	4.8	15	0.2	2.0	0.3	20	0.16	0.074
KYS 109622	Soil	1.2	30.9	23.7	73	0.2	26.9	12.7	504	2.73	35.2	1.6	4.0	5.3	13	0.2	1.7	0.3	18	0.13	0.076
KYS 109623	Soil	1.2	37.6	20.1	83	0.2	30.9	11.0	441	2.79	23.4	1.4	6.1	6.1	18	0.4	1.6	0.3	30	0.19	0.085

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109561	Soil	17	31	0.40	114	0.029	<1	1.73	0.006	0.05	0.2	0.08	1.7	0.1	<0.05	6	1.7	<0.2
KYS 109562	Soil	20	25	0.29	117	0.023	<1	1.38	0.005	0.04	0.2	0.06	1.6	0.1	<0.05	5	1.3	<0.2
KYS 109563	Soil	23	19	0.35	142	0.042	<1	1.19	0.008	0.04	0.2	0.13	2.5	0.1	<0.05	3	1.5	<0.2
KYS 109564	Soil	27	26	0.34	148	0.020	1	1.41	0.005	0.04	0.2	0.11	1.6	0.1	<0.05	4	2.5	<0.2
KYS 109565	Soil	30	26	0.36	166	0.023	<1	1.60	0.006	0.05	0.2	0.19	2.5	0.1	<0.05	4	2.4	<0.2
KYS 109566	Soil	24	25	0.30	75	0.020	1	1.40	0.004	0.04	0.2	0.06	1.5	<0.1	<0.05	4	1.0	<0.2
KYS 109567	Soil	26	25	0.41	183	0.029	1	1.46	0.005	0.05	0.2	0.11	3.0	0.1	<0.05	4	1.3	<0.2
KYS 109601	Soil	8	26	0.26	100	0.004	<1	1.58	0.006	0.03	<0.1	0.12	1.7	<0.1	<0.05	4	2.4	0.3
KYS 109602	Soil	8	25	0.25	97	0.004	<1	1.49	0.007	0.03	<0.1	0.13	1.5	<0.1	<0.05	4	2.1	<0.2
KYS 109603	Soil	19	20	0.27	821	0.002	<1	0.85	0.003	0.04	<0.1	0.15	1.0	<0.1	<0.05	2	2.9	<0.2
KYS 109604	Soil	8	26	0.29	161	0.006	<1	1.44	0.006	0.03	<0.1	0.13	1.7	<0.1	<0.05	4	2.1	0.4
KYS 109605	Soil	8	27	0.20	90	0.003	<1	1.36	0.005	0.03	<0.1	0.11	2.0	<0.1	<0.05	4	3.5	<0.2
KYS 109606	Soil	6	23	0.25	98	0.001	<1	1.29	0.006	0.03	<0.1	0.16	2.8	<0.1	0.08	4	4.4	<0.2
KYS 109607	Soil	5	23	0.18	83	0.003	<1	1.04	0.006	0.02	<0.1	0.12	1.1	<0.1	0.07	4	2.7	<0.2
KYS 109608	Soil	7	16	0.13	94	<0.001	<1	0.79	0.006	0.03	<0.1	0.12	3.5	<0.1	0.06	2	2.4	<0.2
KYS 109609	Soil	7	25	0.13	104	0.003	<1	1.52	0.006	0.03	<0.1	0.18	2.4	<0.1	0.09	4	3.1	<0.2
KYS 109610	Soil	8	29	0.15	147	0.007	<1	1.52	0.008	0.04	<0.1	0.19	1.7	<0.1	0.06	5	2.9	<0.2
KYS 109611	Soil	11	28	0.23	77	0.027	<1	1.38	0.005	0.03	0.1	0.04	1.5	<0.1	<0.05	6	0.9	<0.2
KYS 109612	Soil	12	32	0.35	140	0.030	<1	1.98	0.006	0.05	0.1	0.07	3.0	0.1	<0.05	6	0.8	<0.2
KYS 109613	Soil	10	28	0.23	116	0.020	<1	1.61	0.005	0.04	0.2	0.10	2.0	<0.1	<0.05	6	1.8	<0.2
KYS 109614	Soil	10	24	0.26	82	0.022	2	1.53	0.006	0.03	0.1	0.09	2.1	<0.1	<0.05	4	2.0	<0.2
KYS 109615	Soil	11	26	0.27	125	0.020	<1	1.46	0.006	0.04	0.1	0.05	2.1	<0.1	<0.05	5	1.1	<0.2
KYS 109616	Soil	11	21	0.35	115	0.018	<1	1.23	0.006	0.04	0.1	0.06	2.0	<0.1	<0.05	4	1.2	<0.2
KYS 109617	Soil	12	24	0.34	112	0.025	<1	1.45	0.006	0.04	0.2	0.06	2.1	<0.1	<0.05	4	0.7	<0.2
KYS 109618	Soil	10	20	0.22	135	0.013	<1	1.14	0.006	0.04	0.1	0.05	0.9	<0.1	<0.05	4	0.6	<0.2
KYS 109619	Soil	13	23	0.32	117	0.024	<1	1.41	0.005	0.04	0.2	0.06	1.8	<0.1	<0.05	4	0.9	<0.2
KYS 109620	Soil	14	25	0.40	177	0.020	1	1.59	0.007	0.05	0.1	0.05	1.8	<0.1	<0.05	4	1.1	<0.2
KYS 109621	Soil	13	19	0.32	107	0.008	<1	0.87	0.005	0.05	<0.1	0.04	1.5	<0.1	<0.05	3	0.7	<0.2
KYS 109622	Soil	17	19	0.39	102	0.007	<1	1.01	0.006	0.05	<0.1	0.03	1.5	<0.1	<0.05	3	0.7	<0.2
KYS 109623	Soil	18	22	0.46	273	0.035	<1	1.05	0.008	0.07	0.1	0.05	2.6	<0.1	<0.05	3	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109624	Soil		0.7	23.6	17.0	47	<0.1	18.7	7.4	280	2.53	18.3	0.8	2.2	4.5	8	0.2	1.1	0.2	24	0.08	0.064
KYS 109625	Soil		0.9	10.2	11.5	27	0.1	9.0	3.0	85	1.59	15.2	0.8	2.6	0.2	10	0.1	0.8	0.2	39	0.09	0.055
KYS 109626	Soil		1.1	17.1	11.0	35	0.3	10.7	3.4	99	1.38	11.2	0.9	5.7	0.2	19	0.2	1.2	0.2	27	0.17	0.058
KYS 109627	Soil		1.6	33.4	19.1	56	0.2	20.4	5.1	167	2.69	23.6	0.9	10.3	3.0	12	0.2	3.1	0.3	32	0.05	0.060
KYS 109628	Soil		1.6	41.9	16.9	63	0.5	24.0	5.7	181	2.71	25.9	1.2	16.3	3.9	14	0.2	3.8	0.3	22	0.03	0.062
KYS 109629	Soil		1.9	38.8	18.6	56	0.6	18.6	4.2	150	2.78	29.6	0.9	12.7	1.1	9	0.2	3.8	0.3	30	0.03	0.087
KYS 109630	Soil		2.4	43.4	59.5	63	1.2	28.6	6.7	173	4.36	57.7	1.4	34.4	5.0	15	0.4	9.6	2.1	35	0.07	0.102
KYS 109631	Soil		8.2	106.7	33.0	71	2.0	15.0	1.8	71	5.79	53.6	2.0	13.8	4.8	27	0.2	6.3	0.7	62	0.01	0.174
KYS 109639	Soil		6.3	67.9	20.0	106	0.4	22.8	7.3	350	2.96	18.0	3.7	6.2	7.5	24	0.5	3.7	0.3	43	0.06	0.084
KYS 109640	Soil		11.8	43.8	19.7	82	0.6	16.9	6.2	299	2.85	26.8	2.9	4.5	7.2	42	0.3	6.5	0.3	54	0.10	0.127
KYS 109641	Soil		3.6	63.1	16.6	91	0.2	27.2	8.9	334	2.69	13.6	2.7	4.6	7.9	21	0.7	2.0	0.3	39	0.11	0.087
KYS 109642	Soil		4.1	68.9	17.4	147	0.3	29.2	8.6	244	2.90	65.6	3.1	4.2	7.5	25	0.7	4.4	0.3	32	0.06	0.066
KYS 109643	Soil		1.0	23.3	17.4	90	<0.1	27.9	9.7	352	2.75	12.2	1.4	1.6	1.9	8	0.4	1.1	0.2	25	0.07	0.050
KYS 109747	Soil		0.5	43.4	22.8	86	<0.1	32.1	14.5	451	3.68	20.9	2.4	3.1	8.5	9	<0.1	1.0	0.3	9	0.09	0.044
KYS 109748	Soil		0.6	51.1	25.8	86	<0.1	35.1	17.3	594	4.00	19.0	2.5	7.0	7.2	10	<0.1	0.8	0.3	12	0.05	0.044
KYS 109749	Soil		0.8	33.2	26.3	75	<0.1	25.1	10.5	318	3.21	281.4	1.4	8.3	3.0	9	0.1	2.6	0.3	20	0.05	0.057
KYS 109750	Soil		0.9	38.5	32.3	81	<0.1	29.0	12.5	345	3.26	12.6	1.9	2.4	6.5	8	0.1	0.6	0.4	20	0.05	0.044
KYS 109751	Soil		1.0	52.0	34.1	83	<0.1	27.6	12.8	564	4.29	21.2	2.1	3.2	6.8	7	0.1	0.6	0.5	17	0.01	0.062
KYS 109752	Soil		6.6	53.5	21.5	106	0.4	24.4	7.8	219	3.44	20.7	2.5	5.5	4.5	18	<0.1	1.8	0.4	31	0.02	0.066
KYS 109753	Soil		2.2	54.9	33.6	89	0.1	27.4	12.8	390	3.68	13.7	1.9	3.0	5.0	11	0.1	0.9	0.4	21	0.02	0.052
KYS 109754	Soil		2.3	68.2	22.4	106	0.2	37.7	14.6	340	3.37	13.2	2.6	4.2	6.6	10	0.2	1.3	0.4	26	0.04	0.052
KYS 109755	Soil		1.0	34.8	26.5	90	<0.1	29.9	13.2	417	3.83	11.8	1.6	1.4	6.2	10	0.1	0.6	0.4	17	0.09	0.043
KYS 109756	Soil		21.7	83.8	26.1	108	0.9	25.4	5.4	155	3.01	27.8	4.7	5.3	4.8	26	0.2	7.2	0.4	52	0.05	0.119
KYS 109757	Soil		17.6	82.3	25.3	108	0.8	25.7	5.6	177	3.09	23.0	4.0	5.4	4.7	25	0.2	5.2	0.4	49	0.04	0.109
KYS 109758	Soil		6.9	110.8	18.7	115	0.5	42.1	13.4	299	2.97	15.8	3.9	6.1	4.9	22	0.5	2.8	0.3	45	0.06	0.083
KYS 109759	Soil		11.0	136.4	18.8	127	0.7	40.6	11.8	270	3.22	24.0	5.1	7.7	7.8	33	1.0	4.5	0.3	48	0.10	0.129
KYS 109760	Soil		13.2	64.8	16.7	78	0.5	24.9	9.8	319	2.72	27.3	3.9	7.3	6.1	17	0.3	4.8	0.3	53	0.12	0.111
KYS 109761	Soil		14.8	39.9	17.2	68	0.6	17.0	5.7	214	2.38	22.8	4.0	3.1	8.2	17	0.3	5.8	0.3	46	0.11	0.094
KYS 109762	Soil		17.6	47.1	41.6	114	0.7	19.7	4.9	212	3.15	20.6	4.2	6.3	5.4	25	0.3	5.7	0.5	62	0.05	0.101
KYS 109763	Soil		7.7	27.9	15.4	60	0.3	15.6	6.8	290	2.63	20.4	2.9	2.2	4.6	19	0.2	2.8	0.3	55	0.07	0.068

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109624	Soil	10	24	0.28	68	0.018	<1	1.64	0.004	0.03	0.1	0.05	1.6	<0.1	<0.05	3	0.9	<0.2
KYS 109625	Soil	12	17	0.21	104	0.012	1	1.03	0.009	0.04	0.1	0.04	0.5	0.1	<0.05	5	0.5	<0.2
KYS 109626	Soil	9	13	0.14	197	0.010	1	0.80	0.009	0.04	0.1	0.06	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109627	Soil	9	17	0.18	94	0.012	<1	0.91	0.009	0.04	0.1	0.06	1.3	<0.1	<0.05	3	0.9	<0.2
KYS 109628	Soil	7	14	0.15	106	0.008	<1	0.86	0.010	0.04	<0.1	0.07	1.6	<0.1	0.05	3	0.9	<0.2
KYS 109629	Soil	7	17	0.12	55	0.008	<1	0.75	0.006	0.03	<0.1	0.07	0.8	<0.1	<0.05	3	1.1	0.2
KYS 109630	Soil	8	23	0.14	56	0.007	<1	1.25	0.007	0.03	<0.1	0.11	2.0	<0.1	0.06	4	1.6	0.3
KYS 109631	Soil	5	18	0.08	785	0.003	2	0.76	0.009	0.09	<0.1	0.20	2.4	<0.1	0.26	3	11.6	<0.2
KYS 109639	Soil	32	22	0.48	121	0.021	<1	1.51	0.006	0.05	<0.1	0.11	1.8	<0.1	<0.05	4	1.8	0.2
KYS 109640	Soil	26	22	0.35	185	0.021	<1	1.20	0.006	0.06	0.2	0.21	1.8	0.2	<0.05	3	2.3	<0.2
KYS 109641	Soil	24	22	0.43	125	0.029	1	1.35	0.006	0.05	0.1	0.07	2.2	<0.1	<0.05	3	1.3	<0.2
KYS 109642	Soil	22	16	0.26	144	0.012	<1	0.90	0.008	0.05	0.1	0.10	2.3	<0.1	<0.05	2	1.8	<0.2
KYS 109643	Soil	18	19	0.40	75	0.013	<1	1.26	0.006	0.05	0.1	0.02	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109747	Soil	20	18	0.69	32	0.004	<1	1.53	0.006	0.05	<0.1	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109748	Soil	18	20	0.71	38	0.004	<1	1.60	0.005	0.04	<0.1	0.02	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109749	Soil	19	16	0.41	53	0.007	<1	1.12	0.005	0.04	0.1	0.03	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 109750	Soil	26	21	0.63	49	0.009	<1	1.48	0.006	0.05	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109751	Soil	24	23	0.62	43	0.006	<1	1.60	0.006	0.05	<0.1	0.02	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 109752	Soil	19	18	0.39	138	0.006	<1	1.06	0.007	0.07	<0.1	0.11	1.3	<0.1	0.17	3	1.7	<0.2
KYS 109753	Soil	18	20	0.49	85	0.007	<1	1.40	0.006	0.05	<0.1	0.04	1.1	<0.1	<0.05	4	0.8	0.4
KYS 109754	Soil	20	20	0.50	73	0.015	<1	1.23	0.006	0.05	<0.1	0.06	2.1	<0.1	<0.05	4	1.4	<0.2
KYS 109755	Soil	20	21	0.66	57	0.006	<1	1.42	0.005	0.04	<0.1	0.02	1.3	<0.1	<0.05	4	0.5	<0.2
KYS 109756	Soil	26	19	0.26	161	0.008	<1	1.06	0.005	0.07	0.2	0.31	1.2	0.2	0.12	3	4.7	<0.2
KYS 109757	Soil	27	21	0.27	161	0.006	<1	1.13	0.006	0.07	0.2	0.28	1.2	0.2	0.11	4	4.1	<0.2
KYS 109758	Soil	22	24	0.38	114	0.022	<1	1.36	0.005	0.05	0.2	0.18	1.8	0.1	0.05	3	2.6	<0.2
KYS 109759	Soil	23	22	0.38	207	0.021	<1	1.27	0.007	0.07	0.2	0.25	2.3	0.1	0.11	4	3.6	<0.2
KYS 109760	Soil	19	23	0.35	121	0.031	<1	1.29	0.005	0.05	0.3	0.23	2.3	0.2	<0.05	4	2.7	0.2
KYS 109761	Soil	18	20	0.32	99	0.040	<1	1.00	0.004	0.04	0.2	0.24	2.0	0.1	<0.05	3	2.8	<0.2
KYS 109762	Soil	27	23	0.29	121	0.018	<1	1.12	0.004	0.05	0.2	0.31	1.6	0.2	<0.05	4	3.9	<0.2
KYS 109763	Soil	20	25	0.34	126	0.025	<1	1.43	0.005	0.04	0.3	0.13	2.1	0.2	<0.05	5	2.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109764	Soil	11.5	73.3	25.1	224	0.4	40.4	7.6	292	4.80	22.5	3.3	3.7	4.2	19	1.2	6.4	0.4	57	0.05	0.142
KYS 109765	Soil	27.1	57.4	23.2	112	0.7	20.6	3.2	133	2.82	56.9	5.7	4.2	10.3	31	0.5	10.6	0.4	65	0.02	0.105
KYS 109766	Soil	14.6	48.4	18.3	99	0.4	23.2	6.4	225	2.85	46.5	5.3	5.8	7.4	52	0.2	9.4	0.3	51	0.06	0.095
KYS 109767	Soil	12.6	49.4	18.3	66	0.4	12.6	2.7	131	2.08	23.5	2.7	3.8	1.9	22	0.2	4.6	0.3	48	0.05	0.074
KYS 109768	Soil	6.7	83.1	32.5	230	0.6	15.2	1.9	96	4.73	6.7	11.4	1.3	27.9	50	0.7	2.6	0.4	33	0.04	0.254
KYS 109769	Soil	4.6	31.8	19.3	137	0.9	17.9	3.0	118	3.76	8.7	3.5	1.2	5.2	31	0.2	1.8	0.3	30	0.04	0.084
KYS 109770	Soil	3.8	53.2	19.7	128	0.2	36.6	10.1	276	2.78	11.7	2.5	1.1	5.0	24	1.1	2.1	0.3	37	0.08	0.068
KYS 109771	Soil	2.9	32.5	17.4	121	0.2	39.5	12.2	357	2.66	10.3	1.7	6.7	5.2	16	1.0	1.7	0.2	33	0.09	0.066
KYS 109772	Soil	4.6	50.4	18.6	137	0.4	46.8	18.6	505	2.88	11.3	2.7	1.8	6.1	19	1.4	2.0	0.2	32	0.07	0.062
KYS 109773	Soil	2.2	21.7	14.2	108	0.1	37.9	11.8	396	3.17	7.9	0.9	2.5	4.2	7	0.6	1.1	0.2	31	0.04	0.063
KYS 109774	Soil	9.9	89.5	34.3	470	1.1	157.3	60.8	1237	5.10	18.8	5.3	8.0	9.1	43	4.8	10.4	0.6	25	0.07	0.122
KYS 109775	Soil	14.4	100.1	35.7	133	1.3	19.0	5.2	192	4.27	27.4	7.5	4.7	16.6	96	1.0	4.8	0.5	58	0.07	0.167
KYS 109776	Soil	11.1	75.3	32.9	165	1.0	39.0	13.5	345	3.34	20.8	5.2	5.1	11.5	57	1.6	4.0	0.5	30	0.08	0.109
KYS 109777	Soil	12.9	129.8	34.3	101	1.1	18.1	4.2	117	1.65	25.0	9.2	9.8	9.3	133	1.0	6.9	0.4	34	0.15	0.151
KYS 109778	Soil	11.3	55.0	25.8	87	0.9	18.3	4.2	133	2.40	21.5	5.0	5.5	3.8	81	0.5	3.8	0.4	41	0.10	0.123
KYS 109797	Soil	10.9	63.7	30.9	118	1.3	12.9	2.5	126	3.96	26.4	4.5	5.1	5.4	24	0.2	4.5	0.5	53	0.02	0.188
KYS 109798	Soil	10.4	52.6	26.9	153	1.1	26.1	4.2	179	4.26	17.5	4.1	3.9	5.3	35	0.3	3.6	0.3	40	0.02	0.146
KYS 109799	Soil	9.0	64.8	21.2	106	0.8	29.2	8.6	227	3.30	17.3	3.3	3.8	7.1	26	0.4	3.1	0.3	46	0.06	0.104
KYS 109800	Soil	6.5	24.4	17.5	44	0.3	7.6	1.7	78	2.10	11.7	1.2	2.2	0.3	15	0.2	1.1	0.3	51	0.02	0.062
KYS 109817	Soil	6.5	42.1	17.7	83	0.9	22.8	7.5	285	3.02	19.8	2.1	5.7	5.8	20	0.5	2.1	0.3	55	0.06	0.104
KYS 109818	Soil	11.6	63.9	25.7	99	2.9	21.9	5.4	225	3.24	37.3	5.0	8.6	1.9	33	1.2	3.0	0.4	59	0.06	0.180
KYS 109819	Soil	9.0	45.1	24.4	94	0.5	19.3	4.8	170	2.98	21.5	3.1	6.8	1.6	13	1.1	2.9	0.3	42	0.06	0.091
KYS 109820	Soil	18.3	149.4	50.8	199	3.6	47.8	12.0	283	5.22	62.7	9.1	12.2	7.5	39	1.9	7.0	0.6	67	0.04	0.190
KYS 109821	Soil	3.4	37.2	17.9	80	0.4	27.0	10.3	268	3.25	16.8	1.8	3.0	6.3	12	0.9	2.0	0.2	48	0.07	0.054
KYS 109822	Soil	2.2	24.9	17.8	91	0.3	22.5	8.5	358	2.67	16.1	1.5	7.3	5.4	8	0.5	1.8	0.3	45	0.05	0.051
KYS 109823	Soil	4.6	25.8	13.1	61	0.3	16.9	6.8	246	2.59	16.9	1.5	3.4	3.6	10	0.6	1.8	0.3	50	0.05	0.079
KYS 109824	Soil	3.3	18.1	12.4	42	0.6	16.7	2.7	90	1.75	10.7	1.0	3.6	0.5	10	1.4	1.1	0.3	40	0.07	0.056
KYS 109825	Soil	7.3	53.8	18.6	90	0.2	20.4	5.5	158	4.92	22.0	2.5	2.4	3.9	17	0.4	3.1	0.3	56	0.03	0.103
KYS 109826	Soil	10.5	27.8	16.2	74	0.6	11.4	3.3	139	2.97	24.8	1.5	1.8	0.8	12	0.5	3.0	0.3	64	0.02	0.086
KYS 109827	Soil	4.8	59.9	15.9	128	0.7	46.4	8.7	1321	2.63	15.3	3.6	3.1	0.8	23	4.2	2.3	0.3	43	0.19	0.092

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109764	Soil	22	26	0.39	81	0.012	<1	1.27	0.004	0.04	0.1	0.08	1.2	0.1	<0.05	4	4.0	0.2
KYS 109765	Soil	30	16	0.26	144	0.006	<1	0.70	0.011	0.06	<0.1	0.29	1.3	0.2	0.15	2	6.6	<0.2
KYS 109766	Soil	32	21	0.36	146	0.018	<1	1.33	0.005	0.05	0.1	0.21	2.1	0.2	<0.05	3	3.5	<0.2
KYS 109767	Soil	25	16	0.18	107	0.013	<1	0.72	0.009	0.05	0.1	0.11	1.0	<0.1	0.10	3	4.2	<0.2
KYS 109768	Soil	28	14	0.26	278	0.002	<1	0.73	0.010	0.30	<0.1	0.15	1.7	0.2	0.75	3	5.8	<0.2
KYS 109769	Soil	20	15	0.12	158	0.009	<1	0.64	0.008	0.10	<0.1	0.04	0.9	<0.1	0.32	3	2.8	<0.2
KYS 109770	Soil	18	20	0.29	84	0.020	<1	1.37	0.004	0.04	0.1	0.04	1.5	<0.1	<0.05	4	1.1	<0.2
KYS 109771	Soil	18	16	0.29	86	0.023	<1	1.06	0.004	0.04	0.1	0.04	1.5	<0.1	<0.05	3	1.5	0.4
KYS 109772	Soil	20	20	0.37	123	0.021	<1	1.40	0.007	0.05	0.2	0.08	2.4	<0.1	<0.05	3	2.1	<0.2
KYS 109773	Soil	17	17	0.30	71	0.014	<1	1.14	0.004	0.04	0.1	0.03	1.1	<0.1	<0.05	3	1.4	<0.2
KYS 109774	Soil	19	15	0.40	185	0.002	<1	1.48	0.004	0.05	<0.1	0.20	1.4	<0.1	<0.05	2	4.3	<0.2
KYS 109775	Soil	52	25	0.43	361	0.002	<1	1.45	0.023	0.13	<0.1	0.37	2.3	0.2	0.32	4	6.8	0.3
KYS 109776	Soil	39	16	0.42	182	0.003	<1	1.04	0.016	0.06	<0.1	0.19	1.4	0.1	0.11	3	4.4	<0.2
KYS 109777	Soil	45	9	0.14	192	0.004	<1	0.63	0.006	0.04	0.1	0.47	1.3	0.1	<0.05	2	4.6	<0.2
KYS 109778	Soil	39	18	0.21	173	0.011	<1	1.15	0.005	0.04	0.2	0.25	1.2	0.1	<0.05	3	3.3	<0.2
KYS 109797	Soil	37	31	0.37	108	0.004	<1	1.14	0.008	0.06	<0.1	0.14	1.1	<0.1	0.11	4	6.5	<0.2
KYS 109798	Soil	34	19	0.27	108	0.004	<1	0.89	0.007	0.06	<0.1	0.14	1.0	<0.1	0.08	3	6.9	<0.2
KYS 109799	Soil	28	22	0.32	132	0.019	1	0.97	0.005	0.05	0.1	0.21	1.9	<0.1	<0.05	3	4.4	<0.2
KYS 109800	Soil	22	17	0.16	101	0.007	<1	0.88	0.006	0.04	0.1	0.04	0.3	0.1	<0.05	5	2.1	<0.2
KYS 109817	Soil	22	28	0.33	104	0.025	1	1.61	0.006	0.05	0.1	0.12	2.0	0.1	<0.05	5	2.2	<0.2
KYS 109818	Soil	22	27	0.26	138	0.011	<1	1.65	0.007	0.06	0.2	0.43	1.0	0.1	0.06	4	4.2	<0.2
KYS 109819	Soil	21	19	0.29	110	0.007	1	1.01	0.005	0.04	<0.1	0.09	0.6	<0.1	<0.05	4	2.1	<0.2
KYS 109820	Soil	25	27	0.34	109	0.006	<1	1.35	0.005	0.08	<0.1	0.21	2.0	0.1	0.14	3	10.7	<0.2
KYS 109821	Soil	14	28	0.36	107	0.025	1	1.87	0.005	0.05	0.2	0.10	2.1	0.1	<0.05	4	1.5	<0.2
KYS 109822	Soil	13	20	0.29	93	0.017	1	1.42	0.004	0.04	0.2	0.04	1.5	<0.1	<0.05	4	0.8	<0.2
KYS 109823	Soil	16	23	0.27	106	0.022	<1	1.36	0.006	0.05	0.2	0.10	1.7	0.1	<0.05	4	1.4	0.2
KYS 109824	Soil	15	15	0.13	114	0.012	<1	0.80	0.004	0.03	0.2	0.07	0.7	<0.1	<0.05	4	1.5	0.2
KYS 109825	Soil	18	25	0.25	202	0.008	<1	1.35	0.005	0.05	0.2	0.10	1.3	0.1	0.06	4	3.3	<0.2
KYS 109826	Soil	21	16	0.09	80	0.016	<1	0.71	0.003	0.03	0.2	0.07	0.6	<0.1	<0.05	5	1.8	<0.2
KYS 109827	Soil	16	22	0.35	171	0.011	1	1.32	0.007	0.05	0.2	0.11	1.2	0.1	<0.05	4	4.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109828	Soil	4.0	64.2	24.3	96	0.4	30.9	11.4	277	3.15	16.8	3.4	6.2	1.5	9	1.2	1.9	0.3	41	0.06	0.081
KYS 109829	Soil	46.3	49.9	32.2	90	3.9	12.5	1.4	31	6.21	128.2	2.4	5.1	2.3	22	0.2	14.7	0.5	136	0.02	0.176
KYS 109830	Soil	16.4	43.2	21.6	109	1.2	19.0	3.9	149	2.67	24.8	3.1	2.5	0.5	30	1.9	3.5	0.3	59	0.20	0.107
KYS 109831	Soil	2.5	42.5	26.4	121	0.2	33.8	9.8	308	4.22	21.8	1.7	3.0	10.7	11	0.4	3.6	0.3	24	0.03	0.065
KYS 109832	Soil	3.9	61.2	27.2	155	0.2	47.8	9.0	229	4.50	35.2	3.6	2.0	7.0	11	1.5	3.8	0.3	28	0.05	0.075
KYS 109833	Soil	5.8	52.5	25.4	122	1.2	36.0	11.3	414	3.37	22.6	2.8	3.4	5.8	17	1.3	2.8	0.3	31	0.11	0.080
KYS 109834	Soil	2.2	49.8	26.8	128	0.3	47.8	10.7	279	2.77	23.0	4.0	0.9	4.1	16	1.4	1.2	0.3	14	0.20	0.054
KYS 109835	Soil	4.8	53.9	25.8	143	0.3	41.4	14.0	651	2.97	14.0	3.9	2.5	3.3	19	1.3	1.8	0.4	29	0.14	0.068
KYS 109836	Soil	1.8	47.8	29.3	199	0.1	52.9	20.3	622	3.10	20.6	3.0	1.3	5.6	14	2.0	1.8	0.3	16	0.17	0.062
KYS 109837	Soil	1.9	67.3	34.4	229	0.3	70.0	25.2	585	3.80	9.5	3.9	1.4	5.7	10	3.3	1.4	0.4	17	0.06	0.063
KYS 109838	Soil	2.6	73.9	31.0	206	0.4	78.5	21.6	481	3.38	12.2	4.1	2.0	3.1	31	4.8	1.6	0.4	27	0.35	0.067
KYS 109839	Soil	6.7	52.7	22.3	149	0.2	39.8	13.9	430	3.30	17.4	2.8	1.9	3.9	14	1.1	3.6	0.3	42	0.04	0.067
KYS 109840	Soil	5.9	53.1	20.9	110	0.4	36.0	7.5	212	2.88	25.1	3.7	3.8	4.5	14	1.6	3.2	0.3	41	0.04	0.059
KYS 109841	Soil	2.8	41.1	24.1	109	0.2	35.5	11.4	368	3.24	14.1	2.1	2.2	2.6	17	1.6	1.9	0.3	37	0.14	0.058
KYS 109842	Soil	2.7	41.9	22.4	110	0.2	37.7	12.9	398	3.30	13.5	2.1	0.9	3.3	16	1.4	1.8	0.3	38	0.13	0.057
KYS 109843	Soil	0.6	57.6	27.7	88	0.1	41.8	21.3	653	4.15	21.1	2.3	1.2	8.7	12	<0.1	1.1	0.3	13	0.12	0.051
KYS 109844	Soil	1.2	63.1	35.2	108	0.2	40.3	17.5	421	4.18	20.9	3.2	2.9	2.4	18	0.1	0.9	0.4	15	0.10	0.085
KYS 109845	Soil	0.7	67.2	90.4	146	0.2	50.2	24.0	632	4.96	21.7	2.8	35.6	6.4	17	0.2	0.6	0.6	13	0.20	0.081
KYS 109846	Soil	0.8	45.3	32.7	74	<0.1	25.9	12.0	440	3.48	17.0	1.7	0.7	3.8	9	<0.1	0.5	0.4	20	0.05	0.073
KYS 109847	Soil	1.0	70.5	40.3	79	0.1	19.2	8.8	316	4.23	19.5	1.9	10.7	7.6	7	<0.1	0.5	0.5	13	0.04	0.070
KYS 109848	Soil	1.2	40.9	44.5	77	<0.1	19.9	9.3	334	3.73	15.2	1.4	1.5	3.5	9	<0.1	0.7	0.4	24	0.03	0.059
KYS 109849	Soil	1.2	42.8	46.8	77	<0.1	20.8	10.1	347	3.77	15.8	1.5	2.2	4.1	9	<0.1	0.8	0.4	23	0.03	0.062
KYS 109850	Soil	1.3	42.0	30.7	67	<0.1	15.6	7.6	327	3.56	14.8	1.2	2.0	2.8	9	0.1	0.6	0.4	27	0.04	0.063
KYS 109851	Soil	1.1	56.2	45.2	92	0.1	36.0	20.9	677	4.18	12.2	2.0	3.4	5.1	11	<0.1	0.5	0.6	12	0.03	0.041
KYS 109852	Soil	1.3	31.4	23.9	67	0.1	25.5	15.3	469	3.59	14.2	1.3	1.6	4.3	16	0.1	0.7	0.4	32	0.06	0.068
KYS 109853	Soil	0.9	28.6	18.9	83	<0.1	38.4	17.7	709	3.57	13.7	1.2	2.4	4.4	15	0.2	0.7	0.3	32	0.10	0.059
KYS 109854	Soil	1.0	36.6	24.9	112	<0.1	47.8	19.2	735	3.90	19.2	1.6	2.0	5.6	8	0.5	0.7	0.3	32	0.07	0.055
KYS 109855	Soil	3.0	47.2	20.6	132	0.2	55.6	19.0	324	3.02	21.6	1.7	3.0	7.5	23	0.8	1.5	0.4	33	0.11	0.097
KYS 109856	Soil	2.7	45.3	12.7	79	0.3	27.2	9.7	266	3.02	14.7	2.3	<0.5	5.1	17	0.3	1.4	0.3	42	0.07	0.076
KYS 109857	Soil	6.6	70.9	23.7	97	0.2	24.7	9.3	210	3.08	22.3	2.3	2.7	3.8	26	0.3	2.3	0.5	41	0.04	0.110

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109828	Soil	16	19	0.22	88	0.013	<1	1.11	0.004	0.04	0.2	0.08	1.1	<0.1	<0.05	3	1.3	<0.2
KYS 109829	Soil	26	21	0.06	278	0.005	<1	0.76	0.006	0.13	0.3	0.67	0.6	0.4	0.23	3	14.6	0.7
KYS 109830	Soil	18	16	0.13	168	0.007	<1	0.76	0.007	0.06	0.2	0.15	0.4	<0.1	0.08	3	3.0	0.2
KYS 109831	Soil	18	19	0.36	486	0.005	<1	1.54	0.004	0.05	<0.1	0.05	1.3	<0.1	<0.05	4	1.3	<0.2
KYS 109832	Soil	17	15	0.32	74	0.003	<1	1.15	0.004	0.03	<0.1	0.07	1.1	<0.1	<0.05	3	2.2	<0.2
KYS 109833	Soil	20	16	0.40	112	0.005	<1	1.19	0.004	0.04	0.1	0.12	1.0	<0.1	<0.05	3	2.0	<0.2
KYS 109834	Soil	12	10	0.32	159	0.002	<1	1.04	0.003	0.04	<0.1	0.07	1.1	<0.1	<0.05	2	3.2	<0.2
KYS 109835	Soil	22	14	0.34	118	0.006	<1	1.06	0.003	0.05	0.1	0.09	1.1	0.1	<0.05	3	1.3	<0.2
KYS 109836	Soil	16	13	0.39	57	0.005	<1	1.03	0.005	0.05	<0.1	0.04	1.3	<0.1	<0.05	3	2.4	<0.2
KYS 109837	Soil	17	13	0.41	55	0.005	<1	1.17	0.003	0.04	<0.1	0.05	1.2	<0.1	<0.05	3	1.0	<0.2
KYS 109838	Soil	16	16	0.39	168	0.008	1	1.21	0.005	0.04	0.1	0.06	1.5	<0.1	<0.05	3	1.9	<0.2
KYS 109839	Soil	22	17	0.29	119	0.010	<1	0.97	0.004	0.05	0.1	0.06	1.1	0.1	<0.05	3	2.0	<0.2
KYS 109840	Soil	25	17	0.22	191	0.011	<1	1.21	0.004	0.05	0.2	0.11	1.5	<0.1	<0.05	3	1.8	<0.2
KYS 109841	Soil	20	17	0.24	208	0.011	1	1.10	0.004	0.04	0.1	0.05	1.4	<0.1	<0.05	4	0.7	<0.2
KYS 109842	Soil	19	17	0.26	185	0.011	<1	1.16	0.005	0.04	0.1	0.05	1.5	<0.1	<0.05	3	0.7	<0.2
KYS 109843	Soil	18	20	0.78	29	0.005	<1	1.66	0.005	0.06	<0.1	0.03	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109844	Soil	10	19	0.57	68	0.003	<1	1.49	0.006	0.06	<0.1	0.05	1.2	<0.1	0.06	4	<0.5	<0.2
KYS 109845	Soil	14	18	0.86	51	0.004	<1	1.65	0.006	0.05	<0.1	0.05	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109846	Soil	24	21	0.75	37	0.008	<1	1.60	0.005	0.05	<0.1	0.04	0.7	<0.1	<0.05	5	<0.5	<0.2
KYS 109847	Soil	26	19	0.63	29	0.004	<1	1.44	0.005	0.05	<0.1	0.04	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109848	Soil	24	20	0.49	51	0.010	<1	1.50	0.005	0.05	<0.1	0.02	1.0	<0.1	<0.05	5	<0.5	<0.2
KYS 109849	Soil	24	21	0.52	50	0.010	<1	1.60	0.005	0.05	<0.1	0.03	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109850	Soil	21	21	0.47	51	0.014	<1	1.38	0.005	0.05	<0.1	0.02	0.8	<0.1	<0.05	4	0.6	<0.2
KYS 109851	Soil	17	19	0.72	45	0.004	<1	1.51	0.006	0.05	<0.1	0.02	1.0	<0.1	<0.05	4	0.6	<0.2
KYS 109852	Soil	17	22	0.46	61	0.018	<1	1.28	0.004	0.05	<0.1	0.04	1.3	<0.1	<0.05	5	0.7	<0.2
KYS 109853	Soil	19	25	0.58	89	0.018	<1	1.44	0.005	0.04	<0.1	0.02	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 109854	Soil	20	25	0.56	74	0.021	<1	1.68	0.006	0.05	0.1	0.03	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 109855	Soil	20	22	0.34	73	0.022	<1	1.36	0.008	0.05	0.1	0.05	1.6	<0.1	<0.05	3	1.4	<0.2
KYS 109856	Soil	17	28	0.42	103	0.031	<1	1.94	0.008	0.04	0.1	0.09	2.8	<0.1	<0.05	4	1.5	<0.2
KYS 109857	Soil	23	31	0.40	97	0.012	<1	1.69	0.005	0.05	<0.1	0.08	1.6	<0.1	<0.05	4	2.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109858	Soil		2.8	65.3	15.1	73	0.4	19.8	7.7	226	2.58	18.0	2.3	4.5	4.0	21	0.3	2.7	0.4	40	0.08	0.094
KYS 109859	Soil		6.0	47.6	18.3	81	0.3	12.8	5.4	191	2.53	25.1	1.7	5.9	5.0	19	0.2	3.3	0.4	38	0.04	0.078
KYS 109860	Soil		2.7	35.7	16.7	77	0.1	23.6	8.3	217	3.15	12.4	1.4	0.9	1.8	10	0.3	1.1	0.3	47	0.06	0.092
KYS 109861	Soil		11.4	25.0	14.6	30	1.2	11.5	3.2	163	1.49	22.9	3.4	4.3	5.2	20	0.2	5.0	0.2	42	0.05	0.054
KYS 110005	Soil		1.2	46.2	9.7	70	<0.1	25.3	8.4	615	2.64	11.8	0.7	5.0	0.8	11	0.3	1.2	0.2	42	0.10	0.069
KYS 110006	Soil		1.6	37.7	12.8	55	<0.1	17.6	4.5	162	2.38	19.0	1.1	13.2	1.1	7	0.2	5.4	0.2	32	0.06	0.060
KYS 110007	Soil		0.5	41.2	15.5	80	<0.1	27.3	12.1	675	3.06	30.2	0.9	3.7	6.1	8	0.2	2.8	0.3	26	0.12	0.069
KYS 110008	Soil		0.8	37.4	25.7	86	0.1	30.8	13.5	570	3.32	61.8	1.1	4.6	5.5	8	0.1	4.7	0.3	27	0.10	0.057
KYS 110009	Soil		0.9	32.8	21.3	81	<0.1	27.9	11.3	402	3.28	14.2	1.4	7.7	3.8	10	0.1	1.4	0.3	27	0.10	0.065
KYS 110010	Soil		1.2	61.4	27.7	83	0.2	39.1	19.9	1019	3.90	21.1	1.2	1.9	10.4	19	0.3	2.0	0.4	10	0.49	0.062
KYS 110011	Soil		5.3	35.7	18.2	85	0.2	33.6	12.5	373	3.30	33.7	2.1	4.9	4.7	12	0.3	3.5	0.2	23	0.08	0.044
KYS 110013	Soil		15.1	52.0	23.4	140	0.5	39.3	12.3	321	3.35	17.9	4.3	1.7	3.5	35	0.7	3.2	0.3	35	0.07	0.076
KYS 110014	Soil		1.2	32.6	18.4	75	<0.1	26.6	10.9	366	2.99	7.6	1.5	2.2	2.7	13	0.3	2.0	0.2	23	0.07	0.050
KYS 110015	Soil		2.1	33.2	18.1	98	<0.1	39.3	14.3	404	3.22	13.2	1.5	1.7	4.3	18	0.6	2.3	0.2	27	0.11	0.066
KYS 110016	Soil		4.5	30.8	16.6	115	0.3	31.8	9.1	290	2.93	18.5	1.9	2.6	4.0	22	0.8	3.3	0.2	20	0.07	0.064
KYS 110017	Soil		5.8	44.3	26.4	118	0.3	42.0	14.2	584	3.40	12.9	2.5	2.6	2.4	24	0.7	2.8	0.3	22	0.12	0.069
KYS 110018	Soil		2.0	46.5	28.6	118	0.2	42.2	18.6	865	4.25	11.7	1.5	1.2	6.2	15	0.6	2.6	0.4	12	0.24	0.073
KYS 110019	Soil		4.2	60.8	31.6	125	0.2	61.1	24.3	689	4.09	18.4	3.2	2.3	8.2	12	1.0	7.0	0.4	13	0.17	0.072
KYS 110020	Soil		1.9	42.7	28.2	117	0.2	40.7	17.6	792	3.81	13.0	1.7	0.8	9.2	12	0.7	3.7	0.3	12	0.14	0.066
KYS 110021	Soil		2.6	38.8	22.0	100	0.2	32.8	12.5	537	3.18	11.7	1.9	1.7	5.3	12	0.5	3.4	0.3	19	0.11	0.061
KYS 110022	Soil		1.1	52.5	31.8	106	0.1	40.0	21.5	738	4.22	39.8	2.5	2.4	9.5	10	0.2	7.8	0.4	20	0.11	0.054
KYS 110023	Soil		1.3	42.8	13.1	58	<0.1	20.6	8.8	2183	2.74	14.1	0.6	11.8	0.6	10	0.1	2.0	0.2	42	0.06	0.062
KYS 110024	Soil		1.7	117.6	16.2	64	<0.1	35.9	14.6	2812	2.53	19.1	0.7	30.2	1.8	17	0.2	4.0	0.2	35	0.10	0.075
KYS 110025	Soil		1.5	91.2	15.2	60	<0.1	30.7	10.5	1317	2.60	16.6	0.7	12.9	1.3	10	0.1	2.5	0.2	37	0.06	0.049
KYS 110026	Soil		1.5	182.7	24.7	98	0.1	59.0	26.6	5008	3.20	18.1	0.9	27.1	3.6	30	0.3	2.1	0.3	38	0.12	0.105
KYS 110027	Soil		1.8	97.7	16.6	69	0.2	35.3	15.1	1593	3.46	21.3	1.0	11.0	0.8	12	<0.1	2.4	0.3	51	0.06	0.091
KYS 110028	Soil		1.9	103.4	25.7	64	0.2	30.6	10.2	1161	2.17	13.3	0.9	12.8	4.8	46	0.1	3.1	0.3	25	0.05	0.058
KYS 110029	Soil		1.6	145.0	18.8	88	0.2	43.2	19.3	2695	3.28	20.6	1.0	32.1	2.4	17	0.2	3.0	0.3	39	0.07	0.081
KYS 110030	Soil		3.1	116.6	21.4	132	0.3	68.3	25.4	2721	3.99	58.0	1.8	11.4	13.8	65	0.7	5.2	0.3	19	0.94	0.080
KYS 110031	Soil		4.5	140.7	27.3	179	0.4	75.6	26.9	2748	4.29	57.9	1.9	17.6	9.3	39	0.9	6.2	0.4	25	0.36	0.075

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109858	Soil	24	22	0.41	83	0.018	<1	1.35	0.006	0.04	0.1	0.12	1.6	<0.1	<0.05	4	2.3	0.2
KYS 109859	Soil	33	22	0.28	91	0.018	<1	1.09	0.004	0.04	<0.1	0.18	1.1	<0.1	<0.05	3	4.3	<0.2
KYS 109860	Soil	17	24	0.36	77	0.017	<1	1.49	0.004	0.04	0.2	0.05	1.2	<0.1	<0.05	5	1.2	<0.2
KYS 109861	Soil	23	12	0.24	242	0.019	<1	0.68	0.003	0.05	0.3	0.34	1.8	0.2	0.07	2	2.1	<0.2
KYS 110005	Soil	13	22	0.34	108	0.023	<1	1.18	0.005	0.03	0.2	0.04	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 110006	Soil	16	16	0.23	90	0.015	<1	0.99	0.003	0.03	0.1	0.05	1.3	<0.1	<0.05	3	0.8	<0.2
KYS 110007	Soil	28	19	0.59	169	0.011	<1	1.51	0.004	0.06	0.2	0.03	2.3	<0.1	<0.05	4	<0.5	<0.2
KYS 110008	Soil	25	21	0.49	117	0.013	<1	1.39	0.004	0.05	0.1	0.05	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 110009	Soil	19	20	0.43	100	0.012	<1	1.33	0.003	0.04	0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 110010	Soil	20	10	0.30	69	0.005	<1	0.72	0.003	0.04	<0.1	0.04	1.9	<0.1	<0.05	2	0.8	<0.2
KYS 110011	Soil	15	13	0.25	94	0.014	<1	0.92	0.005	0.05	<0.1	0.07	1.3	<0.1	<0.05	3	0.9	<0.2
KYS 110013	Soil	15	17	0.35	91	0.013	<1	1.19	0.006	0.06	0.1	0.21	1.5	0.1	<0.05	3	2.9	<0.2
KYS 110014	Soil	13	16	0.36	49	0.018	<1	1.07	0.006	0.04	<0.1	0.04	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 110015	Soil	13	18	0.41	72	0.024	<1	1.18	0.005	0.04	0.1	0.04	1.5	<0.1	<0.05	3	0.8	<0.2
KYS 110016	Soil	14	13	0.29	52	0.013	<1	0.85	0.004	0.04	<0.1	0.08	1.0	<0.1	<0.05	2	1.6	<0.2
KYS 110017	Soil	9	14	0.32	823	0.006	<1	1.04	0.005	0.05	<0.1	0.08	1.4	<0.1	<0.05	3	1.3	<0.2
KYS 110018	Soil	12	11	0.31	120	0.006	<1	0.80	0.005	0.04	<0.1	0.05	2.1	<0.1	<0.05	2	<0.5	<0.2
KYS 110019	Soil	13	12	0.39	77	0.008	<1	1.12	0.003	0.04	<0.1	0.08	2.4	<0.1	<0.05	2	1.0	<0.2
KYS 110020	Soil	17	9	0.25	102	0.005	<1	0.75	0.003	0.04	<0.1	0.04	1.9	<0.1	<0.05	2	0.6	<0.2
KYS 110021	Soil	16	13	0.30	183	0.012	<1	0.93	0.004	0.05	<0.1	0.05	1.9	<0.1	<0.05	3	0.9	<0.2
KYS 110022	Soil	24	18	0.58	124	0.010	<1	1.42	0.004	0.06	<0.1	0.04	2.4	<0.1	<0.05	4	0.7	<0.2
KYS 110023	Soil	13	20	0.35	94	0.019	<1	1.12	0.004	0.03	0.1	0.05	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 110024	Soil	15	18	0.42	102	0.020	<1	1.06	0.003	0.03	0.1	0.07	1.2	<0.1	<0.05	4	0.6	<0.2
KYS 110025	Soil	14	20	0.44	91	0.025	1	1.28	0.005	0.03	0.2	0.08	1.1	<0.1	<0.05	4	0.5	<0.2
KYS 110026	Soil	22	18	0.67	123	0.014	1	1.52	0.003	0.04	<0.1	0.10	1.8	<0.1	<0.05	5	0.5	<0.2
KYS 110027	Soil	13	27	0.42	122	0.017	<1	1.60	0.005	0.05	0.2	0.13	1.2	<0.1	<0.05	6	<0.5	<0.2
KYS 110028	Soil	23	15	0.32	91	0.015	<1	0.87	0.003	0.04	0.1	0.08	1.5	<0.1	<0.05	3	0.9	0.7
KYS 110029	Soil	20	22	0.48	114	0.019	1	1.38	0.003	0.05	0.1	0.09	1.5	<0.1	<0.05	5	1.0	0.4
KYS 110030	Soil	22	14	0.47	115	0.002	<1	1.02	0.004	0.06	<0.1	0.06	1.8	<0.1	<0.05	3	1.4	<0.2
KYS 110031	Soil	23	15	0.45	139	0.002	<1	1.05	0.005	0.07	<0.1	0.11	2.0	<0.1	<0.05	3	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110032	Soil		4.0	170.4	25.3	134	0.4	75.4	25.5	3919	3.94	34.2	1.6	29.1	7.0	36	0.5	7.5	0.3	25	0.20	0.077
KYS 110033	Soil		3.9	171.3	25.6	131	0.3	73.5	26.3	3825	3.85	33.5	1.7	20.3	7.6	37	0.4	7.6	0.3	27	0.18	0.078
KYS 110034	Soil		3.2	97.8	21.3	139	0.2	60.8	22.1	1828	3.72	43.6	1.5	15.2	7.5	28	0.6	4.7	0.3	22	0.32	0.081
KYS 110035	Soil		3.3	101.1	22.9	135	0.2	56.8	21.1	1676	3.40	45.9	1.5	22.8	7.3	24	0.6	4.7	0.3	19	0.25	0.096
KYS 110036	Soil		3.2	98.5	21.3	135	0.2	60.0	20.9	1823	3.36	44.3	1.4	24.4	7.7	21	0.6	4.7	0.3	22	0.21	0.086
KYS 110041	Soil		1.3	43.1	11.2	52	<0.1	17.7	6.7	713	2.73	12.6	0.6	10.7	0.8	8	0.1	1.1	0.2	51	0.05	0.052
KYS 110042	Soil		1.8	156.4	26.1	111	0.3	58.1	25.3	3879	3.53	22.0	1.4	33.2	2.8	16	0.2	1.3	0.4	43	0.07	0.091
KYS 110043	Soil		3.0	207.0	28.2	140	0.6	76.2	30.7	6738	4.08	25.3	1.5	28.7	5.5	39	0.3	3.3	0.4	41	0.11	0.120
KYS 110044	Soil		12.3	114.2	29.4	104	1.8	45.5	15.1	2504	4.25	38.9	1.5	7.9	6.3	50	0.2	6.7	0.4	76	0.06	0.133
KYS 110045	Soil		10.2	92.7	30.7	112	1.8	46.4	15.5	1886	3.90	41.2	1.9	14.3	2.2	57	0.4	6.2	0.4	79	0.06	0.143
KYS 110046	Soil		5.0	40.0	21.8	95	0.7	39.1	13.0	758	3.32	21.1	1.1	8.7	3.5	46	0.3	3.2	0.3	42	0.19	0.113
KYS 110047	Soil		8.2	64.9	23.0	96	1.2	40.2	11.3	1153	3.45	31.5	1.5	16.2	2.6	63	0.2	4.8	0.3	53	0.10	0.135
KYS 110048	Soil		3.7	56.8	18.0	98	0.4	37.0	12.9	1278	3.30	22.5	1.2	10.6	1.5	25	0.3	2.6	0.3	45	0.07	0.084
KYS 110049	Soil		4.1	64.3	19.1	102	0.5	40.2	11.1	1482	3.02	17.5	1.0	17.8	2.0	26	0.2	2.8	0.3	32	0.12	0.076
KYS 110050	Soil		2.1	72.9	17.2	96	0.2	37.3	12.6	1290	2.82	37.7	1.0	17.4	1.4	17	0.2	4.1	0.3	36	0.10	0.060
KYS 110051	Soil		1.9	54.4	17.8	90	0.2	26.6	11.7	1611	3.36	31.6	1.1	6.9	0.5	19	0.2	3.2	0.4	51	0.12	0.102
KYS 110052	Soil		1.7	48.8	13.8	80	0.2	26.4	10.6	1129	3.05	23.5	0.9	10.9	0.8	11	0.1	1.8	0.3	49	0.07	0.057
KYS 110053	Soil		1.4	52.7	11.3	81	<0.1	28.7	11.2	920	2.75	18.8	1.0	6.1	1.7	10	0.2	1.5	0.2	45	0.06	0.053
KYS 110054	Soil		1.6	38.2	9.4	65	0.2	21.4	6.4	664	2.44	17.9	0.9	9.6	0.4	16	0.2	1.4	0.2	42	0.13	0.067
KYS 110055	Soil		1.4	38.7	10.6	72	0.3	22.6	8.5	944	2.54	22.4	1.1	7.6	0.5	12	0.3	2.1	0.2	43	0.09	0.074
KYS 110056	Soil		1.3	33.2	11.8	63	<0.1	20.3	9.3	623	2.56	19.2	0.9	7.2	0.8	8	0.2	1.5	0.2	39	0.06	0.066
KYS 110057	Soil		1.0	37.6	18.5	78	<0.1	28.5	13.5	769	2.93	29.6	1.0	5.6	2.8	9	0.2	2.0	0.3	32	0.07	0.040
KYS 110058	Soil		1.1	38.7	18.6	78	<0.1	29.9	14.0	785	2.93	31.2	1.0	6.8	2.5	9	0.2	2.0	0.2	33	0.07	0.040
KYS 110059	Soil		1.2	51.5	24.6	97	<0.1	41.4	24.5	1246	3.84	490.7	1.5	33.4	2.4	8	0.2	11.5	0.3	25	0.05	0.046
KYS 110060	Soil		1.5	55.4	24.4	116	0.3	38.7	13.9	902	3.38	20.9	1.5	7.3	3.2	13	0.3	7.5	0.4	30	0.11	0.079
KYS 110061	Soil		1.3	53.5	21.7	116	0.1	42.5	16.9	993	3.49	26.5	1.8	37.2	7.1	11	0.2	7.1	0.3	21	0.09	0.068
KYS 110062	Soil		1.3	54.2	22.6	113	0.1	42.5	17.5	1019	3.50	29.0	1.8	6.5	7.3	12	0.2	7.2	0.3	22	0.11	0.067
KYS 110063	Soil		0.9	54.0	27.7	109	0.1	36.3	15.6	848	3.60	15.9	2.0	4.6	10.3	12	<0.1	7.5	0.4	16	0.17	0.052
KYS 110064	Soil		1.3	43.0	23.5	103	0.1	34.5	15.3	676	3.39	17.5	1.3	3.1	5.2	13	0.3	6.2	0.3	29	0.14	0.064
KYS 110065	Soil		1.0	60.0	33.9	101	0.1	35.8	21.0	1027	3.64	11.2	1.1	2.8	8.7	11	0.2	10.7	0.4	19	0.16	0.056

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110032	Soil	23	16	0.42	184	0.002	<1	1.08	0.004	0.05	<0.1	0.12	1.7	<0.1	<0.05	3	1.7	0.6
KYS 110033	Soil	23	16	0.44	185	0.002	<1	1.11	0.004	0.04	<0.1	0.12	1.7	<0.1	<0.05	3	1.7	0.4
KYS 110034	Soil	20	18	0.49	147	0.005	<1	1.11	0.004	0.05	<0.1	0.07	1.8	<0.1	<0.05	3	1.4	<0.2
KYS 110035	Soil	22	16	0.45	167	0.006	<1	1.05	0.004	0.04	<0.1	0.07	1.6	<0.1	<0.05	3	1.5	<0.2
KYS 110036	Soil	21	15	0.41	148	0.005	<1	0.92	0.003	0.04	<0.1	0.07	1.5	<0.1	<0.05	3	1.5	<0.2
KYS 110041	Soil	15	24	0.27	69	0.023	<1	1.03	0.003	0.03	0.3	0.06	1.0	<0.1	<0.05	5	0.7	0.3
KYS 110042	Soil	24	28	0.57	131	0.018	1	1.73	0.006	0.04	0.4	0.12	1.9	<0.1	<0.05	6	1.2	<0.2
KYS 110043	Soil	23	22	0.61	260	0.015	1	1.52	0.009	0.06	0.1	0.15	2.5	<0.1	0.12	5	2.0	<0.2
KYS 110044	Soil	18	19	0.32	398	0.010	2	0.86	0.021	0.19	0.2	0.69	2.2	0.2	0.58	3	8.0	<0.2
KYS 110045	Soil	15	22	0.31	421	0.005	1	0.82	0.018	0.13	0.2	0.75	1.2	0.1	0.42	3	5.9	<0.2
KYS 110046	Soil	15	33	0.66	253	0.007	<1	1.18	0.009	0.09	<0.1	0.13	1.6	<0.1	0.24	4	2.1	<0.2
KYS 110047	Soil	14	26	0.42	507	0.006	<1	0.99	0.010	0.09	0.1	0.32	1.6	<0.1	0.25	3	3.8	0.3
KYS 110048	Soil	16	26	0.43	266	0.015	<1	1.35	0.005	0.05	0.2	0.11	1.5	<0.1	<0.05	4	1.2	<0.2
KYS 110049	Soil	17	25	0.47	304	0.006	<1	1.12	0.005	0.05	0.1	0.13	1.3	<0.1	<0.05	4	1.2	<0.2
KYS 110050	Soil	15	24	0.43	195	0.015	<1	1.20	0.005	0.04	0.2	0.08	1.6	<0.1	<0.05	4	0.9	<0.2
KYS 110051	Soil	14	28	0.42	246	0.023	1	1.44	0.006	0.06	0.1	0.07	1.0	<0.1	0.14	6	0.9	<0.2
KYS 110052	Soil	16	26	0.36	120	0.027	2	1.30	0.005	0.05	0.3	0.06	1.3	<0.1	<0.05	5	0.9	<0.2
KYS 110053	Soil	16	26	0.40	104	0.028	<1	1.52	0.005	0.04	0.2	0.04	1.8	<0.1	<0.05	5	0.9	<0.2
KYS 110054	Soil	16	24	0.29	137	0.018	1	0.99	0.006	0.05	0.2	0.04	0.7	<0.1	0.07	5	0.9	<0.2
KYS 110055	Soil	15	23	0.32	122	0.019	<1	1.14	0.005	0.04	0.2	0.06	0.9	<0.1	0.08	4	0.8	<0.2
KYS 110056	Soil	15	24	0.33	72	0.020	<1	1.41	0.006	0.04	0.1	0.03	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 110057	Soil	17	21	0.39	96	0.024	1	1.22	0.004	0.04	0.1	0.05	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 110058	Soil	17	22	0.39	92	0.024	<1	1.22	0.004	0.05	0.1	0.04	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 110059	Soil	18	17	0.33	95	0.014	<1	1.26	0.003	0.05	<0.1	0.04	1.3	<0.1	<0.05	4	1.1	<0.2
KYS 110060	Soil	22	20	0.39	124	0.010	<1	1.37	0.006	0.06	0.1	0.05	1.4	<0.1	0.06	4	1.0	0.2
KYS 110061	Soil	32	16	0.38	96	0.010	<1	1.19	0.004	0.06	<0.1	0.04	1.4	<0.1	<0.05	4	0.7	<0.2
KYS 110062	Soil	32	17	0.40	102	0.016	<1	1.22	0.004	0.05	<0.1	0.04	1.5	<0.1	<0.05	4	0.7	<0.2
KYS 110063	Soil	30	15	0.58	88	0.007	1	1.44	0.003	0.07	<0.1	0.04	1.5	<0.1	<0.05	4	0.8	<0.2
KYS 110064	Soil	28	22	0.56	105	0.017	1	1.48	0.005	0.06	0.1	0.03	1.6	<0.1	<0.05	5	0.6	<0.2
KYS 110065	Soil	26	18	0.59	79	0.008	1	1.41	0.004	0.07	<0.1	0.02	1.5	<0.1	<0.05	5	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110066	Soil		0.7	56.4	33.0	101	0.2	35.6	18.0	908	3.60	13.7	1.1	3.0	11.4	11	0.3	19.0	0.3	22	0.24	0.050
KYS 110067	Soil		1.2	56.2	31.6	92	<0.1	40.1	22.3	777	3.55	34.5	1.2	3.9	9.9	15	0.2	8.4	0.4	34	0.17	0.073
KYS 110068	Soil		0.8	33.3	40.3	79	<0.1	27.0	13.4	673	3.48	18.1	1.0	1.9	5.7	13	0.1	6.7	0.4	13	0.47	0.078
KYS 110069	Soil		0.9	28.6	27.5	67	<0.1	24.1	14.2	885	3.15	14.9	0.7	1.7	4.3	11	0.2	3.6	0.3	30	0.14	0.088
KYS 110070	Soil		1.8	44.8	18.2	83	<0.1	31.3	15.2	604	3.92	22.9	1.2	2.7	2.6	8	0.2	33.3	0.3	36	0.08	0.080
KYS 110071	Soil		1.2	27.2	23.3	119	<0.1	27.0	15.6	926	3.15	111.8	1.1	2.4	3.5	9	0.3	19.9	0.2	29	0.06	0.062
KYS 110073	Soil		0.6	35.8	79.7	147	0.8	28.5	15.3	626	3.02	420.3	1.2	42.2	9.5	17	0.9	62.9	0.2	8	0.05	0.030
KYS 110076	Soil		1.9	40.7	17.3	78	0.2	28.9	8.9	441	3.27	30.9	1.1	15.6	4.3	14	0.3	2.4	0.3	41	0.13	0.106
KYS 110077	Soil		1.6	32.3	14.3	74	0.2	24.7	8.8	346	2.86	21.9	1.1	7.2	1.1	11	0.2	1.6	0.2	47	0.10	0.084
KYS 110078	Soil		1.5	33.7	15.4	84	0.2	24.6	9.0	430	3.07	21.9	1.1	5.3	0.9	15	0.3	1.5	0.3	50	0.14	0.082
KYS 110079	Soil		1.7	40.0	15.4	87	0.2	27.8	10.0	353	3.17	18.9	1.3	4.7	3.4	13	0.3	1.8	0.3	49	0.12	0.080
KYS 110080	Soil		3.0	39.1	16.5	98	0.2	27.2	10.2	470	3.22	33.7	1.4	7.7	1.7	12	0.3	3.1	0.3	48	0.10	0.094
KYS 110081	Soil		2.4	35.6	17.3	83	0.2	23.1	9.3	404	2.83	28.1	1.6	4.6	1.8	10	0.3	2.7	0.3	39	0.09	0.083
KYS 110082	Soil		1.7	32.1	16.6	77	0.2	23.3	8.0	271	2.54	38.7	1.3	12.7	1.4	9	0.3	3.8	0.3	38	0.08	0.071
KYS 110083	Soil		1.8	31.8	17.1	79	0.2	24.5	8.1	286	2.53	45.6	1.4	13.5	1.4	9	0.3	4.6	0.3	38	0.08	0.072
KYS 110084	Soil		2.8	31.1	16.0	65	0.6	20.8	7.1	270	2.34	15.0	1.8	5.6	1.9	13	0.2	2.5	0.3	38	0.11	0.082
KYS 110085	Soil		1.9	31.7	16.3	63	0.3	20.7	7.4	314	2.69	18.7	1.3	4.7	0.7	10	0.3	2.0	0.3	39	0.05	0.082
KYS 110086	Soil		1.5	38.3	15.3	66	0.3	24.8	7.1	277	2.70	18.2	1.4	9.7	2.7	11	0.3	1.9	0.3	40	0.09	0.075
KYS 110087	Soil		1.9	47.7	21.7	75	0.8	24.7	6.2	278	2.71	28.7	1.0	13.3	0.9	11	0.2	3.4	0.4	29	0.05	0.084
KYS 110088	Soil		2.6	53.2	29.7	84	1.1	22.8	3.7	206	3.24	28.3	1.0	15.4	3.8	11	<0.1	4.0	0.5	30	0.04	0.105
KYS 110089	Soil		2.8	52.7	29.6	78	0.8	23.8	3.8	230	3.76	27.2	1.0	10.2	3.8	9	<0.1	4.2	0.5	34	0.02	0.099
KYS 110090	Soil		2.8	68.0	30.5	93	0.7	35.2	8.1	289	3.91	44.9	1.3	15.8	4.4	11	0.1	6.8	0.6	29	0.01	0.084
KYS 110091	Soil		2.4	38.8	26.3	73	0.6	17.4	7.0	789	3.38	23.7	0.8	6.5	1.1	9	0.1	3.5	0.5	41	0.03	0.128
KYS 110092	Soil		1.8	26.2	16.6	53	0.5	10.4	2.9	305	1.68	10.5	1.3	3.7	0.2	8	<0.1	1.9	0.3	36	0.04	0.087
KYS 110093	Soil		2.4	54.4	26.2	84	0.4	28.8	5.8	202	3.75	27.0	0.9	9.4	3.8	9	0.1	4.4	0.5	33	0.01	0.071
KYS 110094	Soil		1.6	36.7	16.1	72	0.2	27.1	10.5	371	2.68	20.3	1.2	4.7	2.1	10	0.2	2.2	0.3	36	0.09	0.065
KYS 110095	Soil		1.4	29.6	17.3	69	<0.1	24.2	11.5	442	2.88	18.1	1.1	5.4	2.4	10	0.2	1.6	0.3	38	0.10	0.068
KYS 110096	Soil		1.5	25.2	12.1	56	<0.1	18.7	6.2	239	2.26	16.3	1.0	12.3	1.6	10	0.1	1.6	0.2	40	0.08	0.062
KYS 110097	Soil		1.6	26.4	14.4	63	0.1	18.1	7.7	321	2.52	28.9	1.2	3.4	1.8	10	0.1	1.7	0.3	43	0.08	0.071
KYS 110098	Soil		1.7	34.9	26.6	86	<0.1	30.8	18.1	792	3.49	45.6	1.6	2.0	3.4	7	0.3	2.4	0.4	16	0.06	0.057

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110066	Soil	29	20	0.71	90	0.018	<1	1.40	0.006	0.06	0.1	0.03	2.0	<0.1	<0.05	5	0.7	<0.2
KYS 110067	Soil	31	22	0.61	122	0.030	<1	1.55	0.008	0.04	0.2	0.02	2.1	<0.1	<0.05	5	0.7	<0.2
KYS 110068	Soil	13	14	0.46	105	0.012	<1	1.11	0.005	0.05	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 110069	Soil	19	23	0.48	63	0.025	1	1.40	0.005	0.04	0.1	0.03	1.4	<0.1	0.07	4	0.6	<0.2
KYS 110070	Soil	27	27	0.57	81	0.014	<1	1.74	0.004	0.04	0.1	0.03	1.4	<0.1	0.05	5	0.8	<0.2
KYS 110071	Soil	21	19	0.30	96	0.015	1	1.31	0.005	0.07	0.1	0.05	1.5	0.1	<0.05	4	0.5	<0.2
KYS 110073	Soil	24	9	0.30	55	0.003	<1	0.79	0.003	0.08	<0.1	0.05	1.0	<0.1	<0.05	2	0.7	<0.2
KYS 110076	Soil	18	25	0.40	110	0.029	1	1.24	0.006	0.04	0.1	0.04	2.4	<0.1	<0.05	4	2.2	<0.2
KYS 110077	Soil	16	27	0.41	101	0.024	<1	1.44	0.006	0.05	0.2	0.05	1.7	<0.1	0.06	5	1.2	<0.2
KYS 110078	Soil	14	29	0.53	143	0.023	1	1.57	0.008	0.05	0.2	0.05	1.7	0.1	0.11	6	0.7	<0.2
KYS 110079	Soil	20	30	0.50	102	0.038	1	1.56	0.007	0.05	0.2	0.06	2.7	0.1	<0.05	5	0.9	<0.2
KYS 110080	Soil	18	27	0.45	109	0.024	2	1.50	0.006	0.05	0.2	0.08	2.2	<0.1	0.06	5	1.3	<0.2
KYS 110081	Soil	15	23	0.40	89	0.021	1	1.25	0.005	0.04	0.2	0.06	1.9	<0.1	0.07	4	0.5	<0.2
KYS 110082	Soil	14	22	0.37	88	0.018	<1	1.30	0.005	0.04	0.2	0.05	1.6	<0.1	0.05	4	0.7	<0.2
KYS 110083	Soil	14	21	0.35	93	0.017	1	1.23	0.005	0.04	0.2	0.05	1.8	<0.1	<0.05	4	0.7	<0.2
KYS 110084	Soil	14	21	0.37	167	0.018	8	1.16	0.005	0.04	0.2	0.14	1.5	<0.1	<0.05	3	1.5	0.2
KYS 110085	Soil	10	22	0.34	95	0.016	1	1.22	0.005	0.04	0.2	0.07	1.0	<0.1	<0.05	4	1.4	<0.2
KYS 110086	Soil	14	24	0.39	97	0.026	1	1.32	0.005	0.03	0.1	0.08	2.1	<0.1	<0.05	4	1.0	<0.2
KYS 110087	Soil	9	21	0.25	110	0.008	<1	1.01	0.007	0.03	0.1	0.07	1.0	<0.1	0.05	3	1.5	<0.2
KYS 110088	Soil	9	26	0.27	74	0.003	<1	1.21	0.006	0.03	<0.1	0.09	1.6	<0.1	<0.05	4	2.3	<0.2
KYS 110089	Soil	10	27	0.28	68	0.003	<1	1.27	0.005	0.03	0.2	0.07	1.5	<0.1	<0.05	4	2.6	0.2
KYS 110090	Soil	9	22	0.20	83	0.002	<1	1.16	0.005	0.03	0.1	0.12	1.7	<0.1	<0.05	3	1.9	<0.2
KYS 110091	Soil	9	25	0.15	89	0.007	<1	1.02	0.006	0.03	<0.1	0.07	0.8	<0.1	<0.05	5	1.6	0.4
KYS 110092	Soil	8	12	0.07	83	0.004	1	0.46	0.007	0.04	<0.1	0.05	0.3	<0.1	<0.05	3	0.5	<0.2
KYS 110093	Soil	9	26	0.25	86	0.005	4	1.30	0.005	0.03	<0.1	0.11	1.6	<0.1	<0.05	4	1.6	<0.2
KYS 110094	Soil	13	21	0.32	71	0.023	<1	1.02	0.005	0.04	0.1	0.04	1.7	<0.1	<0.05	4	0.9	<0.2
KYS 110095	Soil	15	23	0.36	78	0.027	1	1.36	0.005	0.04	0.2	0.05	1.8	<0.1	<0.05	4	0.6	<0.2
KYS 110096	Soil	13	22	0.30	80	0.024	1	1.28	0.004	0.04	0.2	0.05	1.6	<0.1	<0.05	4	0.8	<0.2
KYS 110097	Soil	14	24	0.36	107	0.023	2	1.51	0.005	0.04	0.2	0.05	2.0	<0.1	<0.05	5	0.6	0.3
KYS 110098	Soil	17	15	0.18	62	0.005	<1	0.62	0.004	0.03	<0.1	0.03	1.0	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 110099	Soil	1.7	35.0	27.0	76	<0.1	30.2	16.5	670	3.55	34.4	1.4	8.2	1.7	7	0.2	2.1	0.4	24	0.06	0.063
KYS 110100	Soil	1.7	44.9	21.6	81	0.2	36.7	10.1	426	3.10	75.5	1.3	18.6	3.1	11	0.2	5.3	0.4	29	0.07	0.070
KYS 110101	Soil	1.9	65.0	25.6	95	0.5	37.3	7.3	244	3.31	134.2	1.4	10.7	3.3	11	<0.1	9.7	0.4	26	0.02	0.074
KYS 110102	Soil	2.4	46.4	26.5	59	0.7	19.2	3.8	151	2.92	29.8	0.9	9.0	1.4	10	<0.1	2.9	0.5	33	0.02	0.090
KYS 110103	Soil	2.5	55.1	27.0	71	0.4	25.0	5.4	241	3.56	28.8	1.0	10.4	2.7	11	<0.1	2.7	0.5	35	0.03	0.080
KYS 110104	Soil	2.2	53.6	26.4	63	0.4	23.9	5.7	240	3.26	37.7	1.1	12.4	3.2	12	<0.1	2.5	0.5	30	0.05	0.077
KYS 110106	Soil	2.0	46.4	27.6	59	0.4	22.2	5.0	252	3.05	44.0	1.0	10.2	2.4	23	0.1	1.8	0.5	33	0.19	0.097
KYS 110107	Soil	1.7	62.6	24.6	82	0.3	38.2	10.9	400	3.74	48.7	1.6	12.0	6.0	15	0.1	3.0	0.4	27	0.09	0.056
KYS 110108	Soil	1.5	54.0	29.6	74	0.2	39.0	16.7	523	3.49	89.5	1.7	11.8	6.0	13	0.1	2.8	0.4	20	0.13	0.049
KYS 110109	Soil	1.8	57.3	22.8	96	0.3	46.3	11.9	453	3.54	37.4	1.7	8.8	7.5	14	0.2	2.8	0.4	27	0.12	0.063
KYS 110110	Soil	1.5	53.2	21.3	92	0.3	45.9	12.1	466	3.52	36.8	1.6	12.7	7.4	12	0.2	2.6	0.3	26	0.10	0.056
KYS 110111	Soil	1.1	49.1	35.9	86	0.5	34.8	9.6	582	2.85	199.1	4.7	27.8	3.6	81	0.3	3.9	0.5	18	1.22	0.072
KYS 110114	Soil	1.5	24.5	20.3	77	0.4	30.5	12.9	401	3.18	19.4	1.4	4.3	6.4	12	0.2	1.6	0.3	48	0.09	0.067
KYS 110115	Soil	2.6	33.7	27.4	48	0.8	23.1	4.8	161	3.42	17.1	1.2	11.6	8.6	15	0.2	2.9	0.4	39	0.04	0.065
KYS 110116	Soil	0.8	23.0	21.8	71	0.1	27.5	13.2	385	2.79	7.7	1.0	1.1	8.0	7	0.2	1.2	0.4	17	0.09	0.043
KYS 110117	Soil	1.9	29.2	18.2	60	0.3	21.7	5.3	199	2.79	24.1	1.4	6.2	1.5	17	0.2	3.1	0.3	39	0.06	0.077
KYS 110118	Soil	1.4	18.0	12.5	57	0.2	14.9	5.0	223	2.41	18.0	1.0	3.5	1.1	13	0.2	1.1	0.3	51	0.08	0.063
KYS 110119	Soil	1.6	20.4	13.8	55	0.2	15.1	5.5	236	2.45	18.7	1.2	4.5	0.8	12	0.2	1.3	0.3	48	0.08	0.064
KYS 110120	Soil	1.7	18.1	13.8	49	0.2	12.9	4.8	206	2.62	23.2	0.8	2.3	2.0	13	0.2	1.6	0.3	49	0.06	0.057
KYS 110121	Soil	1.6	14.7	14.4	47	0.1	12.1	4.9	221	2.49	16.6	0.7	0.6	0.6	12	0.2	1.1	0.3	48	0.06	0.066
KYS 110122	Soil	1.4	14.5	12.0	45	0.3	11.7	4.2	146	2.34	14.2	0.8	1.8	1.0	10	0.1	0.8	0.2	48	0.07	0.055
KYS 110123	Soil	1.2	15.8	10.9	56	0.6	12.6	4.6	235	2.82	18.3	0.5	5.5	1.2	8	0.3	1.2	0.2	47	0.05	0.058
KYS 110124	Soil	1.3	20.8	12.5	49	0.2	14.0	4.0	168	2.20	20.9	0.8	2.1	1.6	10	0.2	1.3	0.3	42	0.05	0.055
KYS 110125	Soil	1.4	15.1	12.2	41	0.4	10.4	3.6	168	2.23	14.5	0.6	2.8	0.7	10	0.2	1.0	0.3	48	0.05	0.047
KYS 110126	Soil	1.5	26.7	13.1	68	0.2	25.0	9.9	294	2.89	25.5	1.0	11.7	3.8	14	0.4	2.2	0.2	43	0.10	0.076
KYS 110127	Soil	1.1	20.1	13.3	58	0.2	21.7	6.8	237	2.85	20.7	0.7	2.1	3.3	11	0.2	1.5	0.2	49	0.09	0.063
KYS 110128	Soil	1.7	15.3	12.9	63	0.4	15.8	6.9	218	2.83	17.2	0.9	1.4	4.7	11	0.2	1.1	0.2	53	0.09	0.071
KYS 110129	Soil	1.3	16.0	10.6	53	0.3	14.9	4.8	183	2.28	21.5	0.7	15.7	1.9	12	0.3	1.1	0.2	45	0.11	0.065
KYS 110130	Soil	1.1	10.1	10.8	35	0.2	9.0	3.1	120	2.03	13.9	0.6	1.1	0.7	9	0.2	0.7	0.3	51	0.06	0.057
KYS 110131	Soil	1.4	24.5	13.4	63	0.2	18.8	7.7	195	2.31	38.2	1.1	10.9	1.1	10	0.2	2.0	0.2	39	0.07	0.060

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 110099	Soil	14	20	0.25	66	0.009	1	0.80	0.002	0.03	<0.1	0.03	1.1	<0.1	<0.05	3	0.6	0.2
KYS 110100	Soil	14	22	0.27	108	0.009	<1	1.06	0.006	0.04	<0.1	0.05	1.8	<0.1	<0.05	3	0.8	<0.2
KYS 110101	Soil	11	17	0.12	120	0.004	<1	0.91	0.007	0.03	<0.1	0.09	2.1	<0.1	<0.05	3	1.6	<0.2
KYS 110102	Soil	8	19	0.21	136	0.004	<1	1.04	0.007	0.04	<0.1	0.07	1.1	<0.1	<0.05	4	1.6	0.3
KYS 110103	Soil	10	23	0.26	133	0.005	<1	1.24	0.006	0.05	<0.1	0.07	1.4	<0.1	<0.05	4	1.8	<0.2
KYS 110104	Soil	9	22	0.28	140	0.003	<1	1.14	0.007	0.04	<0.1	0.06	1.4	<0.1	<0.05	4	1.6	<0.2
KYS 110106	Soil	7	22	0.26	183	0.003	<1	1.16	0.008	0.04	<0.1	0.09	1.4	<0.1	<0.05	4	1.1	<0.2
KYS 110107	Soil	13	23	0.32	133	0.005	<1	1.26	0.006	0.04	<0.1	0.07	1.8	<0.1	<0.05	4	1.1	<0.2
KYS 110108	Soil	12	19	0.31	98	0.003	8	1.13	0.004	0.03	<0.1	0.05	1.7	<0.1	<0.05	3	0.9	<0.2
KYS 110109	Soil	13	26	0.53	234	0.005	<1	1.33	0.006	0.05	<0.1	0.06	2.7	<0.1	<0.05	4	<0.5	<0.2
KYS 110110	Soil	14	26	0.52	219	0.005	<1	1.29	0.007	0.05	<0.1	0.06	2.6	<0.1	<0.05	3	0.9	<0.2
KYS 110111	Soil	6	16	0.29	219	0.003	2	0.98	0.007	0.05	<0.1	0.07	1.9	<0.1	0.07	3	1.2	<0.2
KYS 110114	Soil	16	30	0.42	155	0.035	1	1.91	0.007	0.05	0.2	0.08	2.9	0.1	<0.05	5	0.9	<0.2
KYS 110115	Soil	10	26	0.20	73	0.009	<1	1.39	0.005	0.03	<0.1	0.11	1.8	<0.1	<0.05	4	1.9	<0.2
KYS 110116	Soil	22	13	0.25	117	0.005	<1	1.15	0.003	0.03	<0.1	0.04	1.5	<0.1	<0.05	3	0.7	<0.2
KYS 110117	Soil	10	26	0.22	95	0.014	<1	1.42	0.006	0.03	0.1	0.07	1.5	<0.1	<0.05	4	1.0	<0.2
KYS 110118	Soil	12	25	0.31	105	0.026	<1	1.47	0.006	0.05	0.1	0.05	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 110119	Soil	12	25	0.32	108	0.022	<1	1.58	0.006	0.04	0.2	0.07	1.4	<0.1	<0.05	5	<0.5	<0.2
KYS 110120	Soil	11	26	0.29	100	0.026	<1	1.41	0.009	0.04	0.2	0.06	1.6	<0.1	<0.05	5	0.8	<0.2
KYS 110121	Soil	12	24	0.29	114	0.019	<1	1.48	0.005	0.04	0.1	0.06	1.3	0.1	<0.05	5	0.6	<0.2
KYS 110122	Soil	12	24	0.31	117	0.020	<1	1.51	0.005	0.04	0.2	0.05	1.6	0.1	<0.05	5	0.9	<0.2
KYS 110123	Soil	11	23	0.24	58	0.033	<1	1.02	0.005	0.04	0.2	0.05	1.3	<0.1	<0.05	5	0.7	<0.2
KYS 110124	Soil	12	20	0.22	84	0.023	<1	1.15	0.005	0.04	0.2	0.04	1.6	<0.1	<0.05	4	0.8	<0.2
KYS 110125	Soil	13	21	0.22	80	0.021	<1	1.14	0.006	0.04	0.1	0.04	1.1	<0.1	<0.05	5	0.7	<0.2
KYS 110126	Soil	12	29	0.36	136	0.026	<1	1.94	0.007	0.05	0.2	0.09	2.5	<0.1	<0.05	4	1.0	0.2
KYS 110127	Soil	12	26	0.37	111	0.032	<1	1.83	0.006	0.04	0.2	0.05	2.6	<0.1	<0.05	5	0.8	<0.2
KYS 110128	Soil	14	33	0.43	119	0.037	<1	2.06	0.007	0.05	0.2	0.07	2.8	0.1	<0.05	5	1.1	<0.2
KYS 110129	Soil	13	24	0.32	112	0.028	<1	1.51	0.006	0.04	0.2	0.05	1.9	<0.1	<0.05	5	0.7	0.2
KYS 110130	Soil	14	22	0.22	86	0.024	<1	1.23	0.005	0.04	<0.1	0.04	1.3	0.1	<0.05	6	0.7	<0.2
KYS 110131	Soil	12	23	0.24	110	0.016	<1	1.34	0.004	0.03	0.1	0.04	1.6	<0.1	<0.05	4	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
KYS 109509	Soil	2.5	42.5	25.5	37	1.7	10.5	2.1	73	2.06	19.4	0.8	3.9	0.3	8	0.2	2.7	0.4	39	0.02	0.105
REP KYS 109509	QC	2.2	42.0	24.1	37	1.7	10.9	2.1	71	2.02	19.2	0.7	5.4	0.4	8	0.2	2.7	0.4	38	0.03	0.102
KYS 109534	Soil	1.7	95.6	27.9	93	0.2	48.6	19.0	624	4.77	192.1	1.3	8.5	10.1	13	0.1	5.5	0.4	17	0.12	0.071
REP KYS 109534	QC	1.7	96.3	29.3	95	0.2	48.9	19.2	630	4.86	193.5	1.4	9.4	10.4	13	0.2	5.5	0.5	17	0.12	0.073
KYS 109546	Soil	1.2	19.9	14.6	58	<0.1	16.9	7.4	267	2.87	12.3	0.8	5.1	1.3	8	0.2	0.6	0.2	40	0.05	0.046
REP KYS 109546	QC	1.1	22.2	14.6	61	<0.1	18.6	7.2	267	2.91	12.5	0.9	1.6	1.2	8	0.2	0.6	0.2	40	0.05	0.044
KYS 109604	Soil	3.0	56.3	30.1	96	0.7	32.8	5.3	268	3.78	23.8	1.0	12.1	5.6	16	0.6	2.5	0.5	34	0.04	0.079
REP KYS 109604	QC	2.8	56.4	29.6	94	0.7	33.6	5.3	273	3.80	23.5	1.0	11.6	5.4	15	0.5	2.6	0.5	34	0.04	0.080
KYS 109610	Soil	2.4	52.3	35.2	50	0.8	16.1	3.3	172	4.29	30.4	1.4	14.2	2.7	13	<0.1	4.2	0.7	45	0.01	0.113
REP KYS 109610	QC	2.4	51.4	31.3	50	0.7	16.4	3.2	170	4.05	28.8	1.3	10.7	2.8	13	0.1	4.1	0.6	45	0.02	0.112
KYS 109641	Soil	3.6	63.1	16.6	91	0.2	27.2	8.9	334	2.69	13.6	2.7	4.6	7.9	21	0.7	2.0	0.3	39	0.11	0.087
REP KYS 109641	QC	3.3	64.5	16.7	94	0.2	26.0	9.3	341	2.80	13.7	2.8	3.0	8.1	21	0.5	2.0	0.3	37	0.12	0.088
KYS 109766	Soil	14.6	48.4	18.3	99	0.4	23.2	6.4	225	2.85	46.5	5.3	5.8	7.4	52	0.2	9.4	0.3	51	0.06	0.095
REP KYS 109766	QC	14.7	49.9	18.3	102	0.5	23.9	6.8	247	3.08	48.4	5.4	3.3	7.6	55	0.3	9.3	0.3	54	0.07	0.097
KYS 109775	Soil	14.4	100.1	35.7	133	1.3	19.0	5.2	192	4.27	27.4	7.5	4.7	16.6	96	1.0	4.8	0.5	58	0.07	0.167
REP KYS 109775	QC	13.6	96.2	34.3	132	1.2	19.5	4.9	184	4.09	26.9	7.6	3.5	16.2	92	1.2	4.7	0.5	55	0.06	0.159
KYS 109838	Soil	2.6	73.9	31.0	206	0.4	78.5	21.6	481	3.38	12.2	4.1	2.0	3.1	31	4.8	1.6	0.4	27	0.35	0.067
REP KYS 109838	QC	2.6	74.7	31.9	210	0.4	76.4	22.0	444	3.22	11.9	4.1	1.5	3.6	30	4.9	1.8	0.4	26	0.35	0.067
KYS 109855	Soil	3.0	47.2	20.6	132	0.2	55.6	19.0	324	3.02	21.6	1.7	3.0	7.5	23	0.8	1.5	0.4	33	0.11	0.097
REP KYS 109855	QC	2.8	46.6	20.6	127	0.2	54.1	19.5	330	3.10	21.3	1.7	2.1	6.6	22	1.1	1.5	0.3	32	0.11	0.099
KYS 110013	Soil	15.1	52.0	23.4	140	0.5	39.3	12.3	321	3.35	17.9	4.3	1.7	3.5	35	0.7	3.2	0.3	35	0.07	0.076
REP KYS 110013	QC	15.2	49.1	23.1	132	0.4	36.6	11.5	308	3.26	17.5	4.1	2.4	3.4	34	0.6	3.3	0.3	34	0.07	0.073
KYS 110028	Soil	1.9	103.4	25.7	64	0.2	30.6	10.2	1161	2.17	13.3	0.9	12.8	4.8	46	0.1	3.1	0.3	25	0.05	0.058
REP KYS 110028	QC	1.9	107.8	27.2	68	0.2	32.7	10.5	1261	2.30	13.5	0.9	12.9	5.3	48	0.1	3.1	0.3	25	0.05	0.057
KYS 110053	Soil	1.4	52.7	11.3	81	<0.1	28.7	11.2	920	2.75	18.8	1.0	6.1	1.7	10	0.2	1.5	0.2	45	0.06	0.053
REP KYS 110053	QC	1.4	49.9	11.8	77	<0.1	28.3	10.9	878	2.74	18.8	1.1	10.2	1.6	10	0.3	1.4	0.2	45	0.07	0.053
KYS 110064	Soil	1.3	43.0	23.5	103	0.1	34.5	15.3	676	3.39	17.5	1.3	3.1	5.2	13	0.3	6.2	0.3	29	0.14	0.064
REP KYS 110064	QC	1.3	45.1	23.1	104	0.1	35.5	16.2	693	3.50	18.6	1.4	2.8	5.5	13	0.2	6.6	0.3	31	0.14	0.062

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000117.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
KYS 109509	Soil	6	19	0.08	87	0.005	<1	0.81	0.009	0.03	<0.1	0.12	0.5	<0.1	<0.05	4	1.1	<0.2
REP KYS 109509	QC	6	19	0.09	85	0.005	<1	0.82	0.010	0.03	<0.1	0.11	0.5	<0.1	<0.05	4	1.1	<0.2
KYS 109534	Soil	17	17	0.33	73	0.001	<1	0.94	0.006	0.06	<0.1	0.04	2.7	<0.1	<0.05	3	1.3	<0.2
REP KYS 109534	QC	18	18	0.33	72	0.001	<1	0.96	0.007	0.06	<0.1	0.04	2.8	<0.1	<0.05	3	1.3	<0.2
KYS 109546	Soil	17	26	0.38	68	0.021	<1	1.45	0.003	0.03	0.1	0.04	1.3	<0.1	<0.05	5	<0.5	<0.2
REP KYS 109546	QC	16	25	0.39	69	0.020	<1	1.47	0.003	0.03	0.2	0.04	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 109604	Soil	8	26	0.29	161	0.006	<1	1.44	0.006	0.03	<0.1	0.13	1.7	<0.1	<0.05	4	2.1	0.4
REP KYS 109604	QC	7	26	0.28	153	0.002	<1	1.43	0.006	0.03	<0.1	0.13	1.7	<0.1	<0.05	4	1.7	0.3
KYS 109610	Soil	8	29	0.15	147	0.007	<1	1.52	0.008	0.04	<0.1	0.19	1.7	<0.1	0.06	5	2.9	<0.2
REP KYS 109610	QC	8	27	0.15	137	0.005	<1	1.49	0.006	0.03	<0.1	0.17	1.7	<0.1	0.06	5	3.0	0.4
KYS 109641	Soil	24	22	0.43	125	0.029	1	1.35	0.006	0.05	0.1	0.07	2.2	<0.1	<0.05	3	1.3	<0.2
REP KYS 109641	QC	25	22	0.43	124	0.025	1	1.35	0.006	0.05	0.1	0.06	2.1	<0.1	<0.05	4	1.2	<0.2
KYS 109766	Soil	32	21	0.36	146	0.018	<1	1.33	0.005	0.05	0.1	0.21	2.1	0.2	<0.05	3	3.5	<0.2
REP KYS 109766	QC	33	22	0.36	154	0.020	<1	1.31	0.003	0.06	0.2	0.22	2.2	0.2	<0.05	3	4.5	0.2
KYS 109775	Soil	52	25	0.43	361	0.002	<1	1.45	0.023	0.13	<0.1	0.37	2.3	0.2	0.32	4	6.8	0.3
REP KYS 109775	QC	51	24	0.41	349	0.002	<1	1.37	0.023	0.12	<0.1	0.36	2.1	0.2	0.29	4	7.0	<0.2
KYS 109838	Soil	16	16	0.39	168	0.008	1	1.21	0.005	0.04	0.1	0.06	1.5	<0.1	<0.05	3	1.9	<0.2
REP KYS 109838	QC	16	14	0.38	168	0.006	<1	1.18	0.005	0.04	0.1	0.07	1.3	<0.1	<0.05	3	1.9	<0.2
KYS 109855	Soil	20	22	0.34	73	0.022	<1	1.36	0.008	0.05	0.1	0.05	1.6	<0.1	<0.05	3	1.4	<0.2
REP KYS 109855	QC	20	22	0.35	71	0.022	<1	1.37	0.005	0.05	0.1	0.05	1.4	<0.1	<0.05	3	1.6	<0.2
KYS 110013	Soil	15	17	0.35	91	0.013	<1	1.19	0.006	0.06	0.1	0.21	1.5	0.1	<0.05	3	2.9	<0.2
REP KYS 110013	QC	15	17	0.34	87	0.013	<1	1.18	0.006	0.05	0.1	0.21	1.5	0.1	<0.05	3	3.0	<0.2
KYS 110028	Soil	23	15	0.32	91	0.015	<1	0.87	0.003	0.04	0.1	0.08	1.5	<0.1	<0.05	3	0.9	0.7
REP KYS 110028	QC	23	15	0.32	89	0.013	<1	0.90	0.003	0.04	<0.1	0.08	1.3	<0.1	<0.05	3	0.8	0.3
KYS 110053	Soil	16	26	0.40	104	0.028	<1	1.52	0.005	0.04	0.2	0.04	1.8	<0.1	<0.05	5	0.9	<0.2
REP KYS 110053	QC	16	25	0.40	106	0.031	1	1.48	0.005	0.04	0.3	0.05	1.8	<0.1	<0.05	5	0.8	<0.2
KYS 110064	Soil	28	22	0.56	105	0.017	1	1.48	0.005	0.06	0.1	0.03	1.6	<0.1	<0.05	5	0.6	<0.2
REP KYS 110064	QC	29	23	0.57	113	0.019	1	1.52	0.005	0.05	0.1	0.03	1.6	<0.1	<0.05	5	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000117.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
KYS 110086	Soil	1.5	38.3	15.3	66	0.3	24.8	7.1	277	2.70	18.2	1.4	9.7	2.7	11	0.3	1.9	0.3	40	0.09	0.075
REP KYS 110086	QC	1.5	38.3	14.7	66	0.3	24.0	7.0	265	2.70	18.6	1.3	3.8	2.4	11	0.3	1.8	0.3	37	0.09	0.073
KYS 110115	Soil	2.6	33.7	27.4	48	0.8	23.1	4.8	161	3.42	17.1	1.2	11.6	8.6	15	0.2	2.9	0.4	39	0.04	0.065
REP KYS 110115	QC	2.7	33.2	27.2	48	0.8	22.6	4.5	153	3.41	16.9	1.1	12.3	8.2	15	0.2	3.0	0.4	38	0.04	0.070
KYS 110128	Soil	1.7	15.3	12.9	63	0.4	15.8	6.9	218	2.83	17.2	0.9	1.4	4.7	11	0.2	1.1	0.2	53	0.09	0.071
REP KYS 110128	QC	1.5	16.0	13.1	64	0.3	16.2	7.0	220	2.94	17.4	1.0	1.5	5.0	11	0.1	1.1	0.3	57	0.09	0.070
Reference Materials																					
STD DS7	Standard	21.0	121.9	70.0	374	0.8	54.8	9.4	587	2.25	47.7	5.5	63.5	5.4	66	6.6	5.9	5.0	84	0.91	0.070
STD DS7	Standard	21.1	107.3	70.3	408	0.9	59.9	9.2	624	2.35	52.5	5.4	74.9	5.1	76	6.6	6.2	4.9	84	0.93	0.075
STD DS7	Standard	20.8	102.7	62.3	395	1.0	56.7	9.4	624	2.37	52.8	4.5	66.6	4.5	70	6.1	5.7	4.4	84	0.91	0.073
STD DS7	Standard	21.3	112.2	69.8	412	1.0	57.0	9.6	634	2.41	51.7	4.7	66.6	4.5	73	5.6	6.0	4.4	87	0.94	0.075
STD DS7	Standard	21.2	112.6	61.7	390	1.0	56.6	9.4	618	2.38	49.3	4.3	67.0	4.3	62	5.8	5.0	3.8	84	0.88	0.074
STD DS7	Standard	19.9	108.5	67.6	387	1.0	52.5	8.3	590	2.26	52.2	5.4	67.2	4.6	77	6.8	5.9	4.5	80	0.93	0.078
STD DS7	Standard	21.7	109.6	64.0	388	1.0	55.5	9.3	627	2.42	54.4	4.7	70.2	4.7	74	6.5	6.0	4.6	88	1.00	0.082
STD DS7	Standard	21.1	122.2	67.6	419	1.0	56.1	9.7	656	2.53	55.4	4.8	68.0	4.7	77	6.7	6.2	4.5	86	0.98	0.077
STD DS7	Standard	20.8	109.8	67.1	396	1.0	53.4	9.4	664	2.46	55.9	4.6	85.6	4.9	78	6.7	6.2	4.7	86	0.96	0.079
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000117.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
KYS 110086	Soil	14	24	0.39	97	0.026	1	1.32	0.005	0.03	0.1	0.08	2.1	<0.1	<0.05	4	1.0	<0.2
REP KYS 110086	QC	14	23	0.38	102	0.023	1	1.32	0.005	0.04	0.2	0.07	2.1	<0.1	<0.05	4	0.9	<0.2
KYS 110115	Soil	10	26	0.20	73	0.009	<1	1.39	0.005	0.03	<0.1	0.11	1.8	<0.1	<0.05	4	1.9	<0.2
REP KYS 110115	QC	9	26	0.20	68	0.008	<1	1.36	0.005	0.02	<0.1	0.14	1.6	<0.1	<0.05	4	2.0	<0.2
KYS 110128	Soil	14	33	0.43	119	0.037	<1	2.06	0.007	0.05	0.2	0.07	2.8	0.1	<0.05	5	1.1	<0.2
REP KYS 110128	QC	14	34	0.42	125	0.041	<1	2.05	0.006	0.06	0.2	0.06	3.2	0.1	<0.05	5	0.9	<0.2
Reference Materials																		
STD DS7	Standard	13	213	0.98	370	0.144	41	1.01	0.096	0.38	3.6	0.21	2.6	4.0	0.07	4	2.7	0.9
STD DS7	Standard	13	203	1.06	417	0.128	37	1.08	0.108	0.47	3.6	0.22	2.7	4.0	0.18	5	2.7	0.9
STD DS7	Standard	12	212	0.99	389	0.118	36	0.96	0.098	0.46	3.7	0.21	2.5	3.9	0.17	5	3.3	1.4
STD DS7	Standard	13	221	1.06	402	0.126	37	1.00	0.096	0.46	3.8	0.22	2.6	4.1	0.19	5	3.7	1.2
STD DS7	Standard	13	218	1.04	385	0.125	44	1.00	0.102	0.45	3.7	0.23	2.4	4.0	0.17	5	2.5	1.1
STD DS7	Standard	13	205	1.00	394	0.123	38	1.00	0.104	0.47	3.5	0.20	2.6	3.9	0.20	4	2.9	1.2
STD DS7	Standard	13	211	1.05	420	0.125	42	1.08	0.110	0.51	3.8	0.22	2.5	4.0	0.18	5	3.3	1.5
STD DS7	Standard	13	188	1.07	423	0.135	41	1.04	0.103	0.48	4.0	0.24	2.9	4.3	0.22	5	3.8	1.5
STD DS7	Standard	14	209	1.04	419	0.128	38	1.02	0.103	0.48	3.7	0.24	2.7	4.3	0.19	5	3.8	0.8
STD DS7 Expected		12	179	1.05	410	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5	1.08
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Submitted By: Johnathan More
Receiving Lab: Canada-Whitehorse
Received: July 14, 2010
Report Date: August 20, 2010
Page: 1 of 13

CERTIFICATE OF ANALYSIS WHI10000116.1

CLIENT JOB INFORMATION

Project: KYS
Shipment ID: KYS1
P.O. Number
Number of Samples: 350

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	350	Dry at 60C sieve 100g to -80 mesh			VAN
Dry at 60C	350	Dry at 60C			VAN
1DX2	350	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Aldrin Resources
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5
Canada

CC: Isaac Fage
Bert Jeffries
Shawn Ryan

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109084	Soil	2.6	70.4	27.3	141	0.3	48.7	15.4	1166	3.33	12.1	1.4	8.1	4.6	17	0.4	1.6	0.4	19	0.24	0.069
KYS 109085	Soil	5.5	193.9	59.3	151	0.3	79.3	52.1	2024	5.13	28.2	3.2	5.3	15.8	12	0.6	2.1	0.9	19	0.20	0.120
KYS 109086	Soil	1.0	30.5	23.3	60	<0.1	25.9	11.5	687	2.97	10.9	1.3	1.6	5.3	10	0.1	0.9	0.3	28	0.12	0.041
KYS 109087	Soil	0.9	34.5	23.0	65	<0.1	29.3	13.6	730	2.96	12.4	1.1	2.6	9.4	7	0.1	0.9	0.3	27	0.09	0.044
KYS 109088	Soil	0.8	20.7	19.3	59	<0.1	19.6	8.7	404	2.68	11.5	0.7	2.3	6.0	13	<0.1	0.7	0.3	29	0.20	0.036
KYS 109089	Soil	0.9	22.9	17.3	60	<0.1	21.2	9.1	494	2.46	9.8	1.0	4.5	3.4	18	0.1	0.7	0.2	30	0.24	0.061
KYS 109090	Soil	1.1	19.9	15.0	58	<0.1	18.3	7.0	384	2.80	14.5	0.8	3.5	1.7	9	<0.1	3.8	0.3	33	0.11	0.040
KYS 109091	Soil	0.9	19.5	18.0	55	<0.1	19.0	7.6	365	2.58	12.2	0.6	3.0	3.2	14	<0.1	4.6	0.3	31	0.22	0.036
KYS 109092	Soil	0.8	22.8	20.6	63	<0.1	22.2	10.8	372	2.84	10.8	0.8	2.1	3.4	12	0.2	2.6	0.3	28	0.16	0.027
KYS 109093	Soil	0.9	28.2	24.5	68	<0.1	25.5	13.9	577	2.95	11.0	1.3	2.4	2.4	10	0.2	1.6	0.3	27	0.10	0.056
KYS 109094	Soil	1.0	23.8	21.3	62	0.2	19.0	7.1	366	2.94	13.8	1.5	2.2	1.5	18	0.1	1.9	0.3	35	0.26	0.061
KYS 109095	Soil	1.1	19.0	18.6	51	<0.1	17.7	6.9	278	2.84	14.3	0.8	1.4	1.9	11	<0.1	2.6	0.3	37	0.13	0.033
KYS 109096	Soil	0.8	23.4	13.1	64	0.1	17.2	7.7	445	2.51	32.8	0.7	5.2	3.2	9	<0.1	9.6	0.2	26	0.13	0.043
KYS 109097	Soil	0.8	29.3	21.2	64	<0.1	26.8	12.7	513	2.94	15.2	1.1	3.4	5.0	9	0.3	1.9	0.2	30	0.10	0.056
KYS 109098	Soil	0.9	30.3	20.5	66	<0.1	26.5	12.7	508	2.91	14.9	1.1	4.9	5.1	9	0.2	1.8	0.3	34	0.10	0.055
KYS 109099	Soil	0.8	38.6	25.6	82	<0.1	34.0	18.9	828	3.53	22.2	1.2	2.8	5.0	9	0.1	1.8	0.3	26	0.09	0.055
KYS 109100	Soil	0.7	38.9	20.9	78	<0.1	25.8	12.5	1019	4.10	20.3	1.7	3.5	5.8	6	<0.1	1.2	0.4	10	0.04	0.030
KYS 109101	Soil	0.7	43.8	27.8	85	0.1	27.3	12.6	405	4.25	24.6	1.9	5.1	6.4	6	<0.1	1.4	0.5	10	0.05	0.032
KYS 109102	Soil	1.7	81.3	18.5	98	0.2	34.6	15.8	1960	2.99	17.4	1.3	16.3	3.1	11	0.3	3.3	0.3	38	0.08	0.077
KYS 109103	Soil	2.3	63.9	16.4	96	0.2	34.4	12.0	1199	2.78	19.0	1.2	12.2	4.2	9	0.3	4.3	0.2	32	0.06	0.065
KYS 109104	Soil	1.4	15.3	18.2	53	<0.1	16.0	6.4	263	3.31	13.9	0.6	3.2	3.4	7	0.2	1.9	0.2	44	0.07	0.039
KYS 109105	Soil	5.7	30.5	33.1	88	0.2	19.6	7.8	199	3.77	15.4	2.0	3.5	5.5	9	0.1	8.7	0.3	14	0.02	0.056
KYS 109106	Soil	0.8	52.8	40.9	140	0.2	66.5	37.1	1613	5.59	11.9	2.8	2.4	8.7	13	0.2	9.9	0.7	7	0.10	0.061
KYS 109107	Soil	1.5	28.8	28.9	99	<0.1	28.3	12.3	483	3.64	25.9	1.6	4.6	2.5	10	0.2	8.8	0.4	20	0.14	0.056
KYS 109108	Soil	0.7	51.0	37.1	92	0.1	38.4	21.0	724	3.80	39.1	1.8	3.1	12.0	11	0.1	6.2	0.4	13	0.14	0.056
KYS 109109	Soil	0.6	56.3	41.2	113	0.1	50.8	27.2	960	4.28	899.5	2.7	196.5	17.6	18	0.1	11.1	0.5	11	0.16	0.055
KYS 109110	Soil	0.7	47.1	32.6	90	0.1	35.3	15.3	516	3.60	224.0	2.0	42.4	7.5	19	0.1	12.2	0.4	18	0.25	0.058
KYS 109111	Soil	0.8	30.6	22.1	80	<0.1	26.9	11.8	454	3.08	148.3	1.5	22.7	7.3	12	0.1	9.0	0.3	17	0.17	0.053
KYS 109112	Soil	0.5	36.5	27.6	86	0.1	29.7	13.2	465	3.37	124.4	1.7	16.7	9.1	15	0.1	7.9	0.3	17	0.21	0.058
KYS 109113	Soil	0.4	32.6	25.8	87	<0.1	30.7	13.2	461	3.35	101.7	1.5	10.5	12.2	15	<0.1	4.4	0.4	14	0.22	0.055

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109084	Soil	13	13	0.39	109	0.003	<1	1.03	0.005	0.04	<0.1	0.07	1.3	<0.1	0.07	2	0.6	0.4
KYS 109085	Soil	36	17	0.75	58	0.002	<1	1.45	0.003	0.05	<0.1	0.12	2.1	<0.1	<0.05	4	1.0	<0.2
KYS 109086	Soil	20	19	0.45	101	0.011	1	1.34	0.004	0.03	0.2	0.03	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109087	Soil	21	20	0.50	69	0.014	<1	1.55	0.005	0.03	0.1	0.03	1.6	<0.1	<0.05	4	0.6	<0.2
KYS 109088	Soil	13	16	0.43	70	0.014	<1	1.06	0.004	0.03	0.1	0.03	1.1	<0.1	<0.05	4	<0.5	0.4
KYS 109089	Soil	13	18	0.41	91	0.014	1	1.08	0.005	0.04	0.1	0.02	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109090	Soil	12	19	0.42	114	0.008	<1	1.23	0.004	0.04	0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109091	Soil	13	18	0.42	120	0.012	2	1.12	0.005	0.04	0.2	0.02	1.2	<0.1	<0.05	4	0.6	<0.2
KYS 109092	Soil	13	19	0.44	86	0.010	<1	1.22	0.005	0.04	0.1	0.01	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 109093	Soil	13	17	0.39	91	0.012	<1	1.21	0.005	0.04	0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109094	Soil	12	20	0.42	177	0.012	<1	1.26	0.006	0.05	0.2	0.05	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109095	Soil	11	18	0.37	64	0.014	<1	1.20	0.004	0.03	0.1	0.03	1.1	<0.1	<0.05	5	<0.5	<0.2
KYS 109096	Soil	22	17	0.49	133	0.008	<1	1.31	0.004	0.04	0.1	0.04	1.2	<0.1	<0.05	4	0.5	<0.2
KYS 109097	Soil	16	21	0.43	117	0.017	<1	1.40	0.005	0.04	0.2	0.04	2.1	<0.1	<0.05	4	<0.5	<0.2
KYS 109098	Soil	16	21	0.44	121	0.017	<1	1.44	0.005	0.04	0.1	0.04	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109099	Soil	17	21	0.55	91	0.011	<1	1.47	0.005	0.05	<0.1	0.03	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 109100	Soil	16	16	0.60	54	0.001	<1	1.38	0.005	0.04	<0.1	0.03	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109101	Soil	16	13	0.59	38	0.001	<1	1.26	0.005	0.05	<0.1	0.03	1.4	<0.1	<0.05	4	0.5	<0.2
KYS 109102	Soil	20	20	0.47	111	0.020	1	1.22	0.004	0.04	0.1	0.05	1.9	<0.1	<0.05	3	0.5	0.6
KYS 109103	Soil	21	16	0.36	103	0.017	1	0.98	0.003	0.03	0.1	0.03	1.6	<0.1	<0.05	3	0.7	<0.2
KYS 109104	Soil	12	21	0.30	53	0.036	<1	1.07	0.005	0.03	0.2	0.05	1.4	<0.1	<0.05	5	<0.5	<0.2
KYS 109105	Soil	11	7	0.12	38	0.005	<1	0.47	0.006	0.04	<0.1	0.09	1.1	<0.1	<0.05	2	1.1	<0.2
KYS 109106	Soil	14	8	0.44	30	0.002	<1	0.78	0.005	0.03	<0.1	0.05	2.3	<0.1	<0.05	2	0.6	<0.2
KYS 109107	Soil	14	12	0.30	94	0.006	<1	0.88	0.006	0.04	<0.1	0.06	1.3	<0.1	<0.05	2	<0.5	<0.2
KYS 109108	Soil	26	14	0.58	58	0.005	<1	1.27	0.005	0.04	<0.1	0.04	1.6	<0.1	<0.05	3	<0.5	0.4
KYS 109109	Soil	33	16	0.65	67	0.004	<1	1.31	0.005	0.06	<0.1	0.03	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 109110	Soil	21	18	0.56	82	0.006	<1	1.36	0.005	0.05	<0.1	0.04	1.7	<0.1	<0.05	4	1.0	<0.2
KYS 109111	Soil	21	13	0.40	89	0.004	<1	1.05	0.004	0.05	<0.1	0.05	1.5	<0.1	<0.05	3	0.6	<0.2
KYS 109112	Soil	23	17	0.54	103	0.005	<1	1.33	0.006	0.05	0.1	0.05	1.8	<0.1	<0.05	4	0.5	<0.2
KYS 109113	Soil	25	16	0.61	68	0.004	<1	1.33	0.004	0.05	<0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109114	Soil		0.6	26.9	23.0	80	<0.1	25.6	11.9	449	3.18	134.8	1.3	17.9	7.2	12	0.1	6.4	0.3	18	0.15	0.061
KYS 109115	Soil		1.0	29.8	24.0	73	0.2	27.0	12.1	617	3.13	68.6	2.3	5.7	5.9	11	0.1	5.0	0.3	16	0.15	0.070
KYS 109116	Soil		0.3	21.0	19.8	67	<0.1	20.1	10.1	428	2.85	47.7	1.7	4.1	8.8	18	<0.1	2.2	0.3	12	0.30	0.053
KYS 109117	Soil		0.3	20.5	19.1	67	<0.1	19.7	10.4	403	2.82	46.8	1.2	4.2	11.9	10	<0.1	1.9	0.3	9	0.16	0.036
KYS 109118	Soil		0.4	20.4	19.1	69	<0.1	21.1	10.1	435	2.77	36.5	1.3	1.7	11.4	10	<0.1	1.3	0.3	12	0.15	0.046
KYS 109119	Soil		0.3	24.2	20.5	71	<0.1	23.5	12.4	556	2.79	24.6	2.0	2.0	11.6	11	<0.1	1.4	0.4	11	0.17	0.045
KYS 109120	Soil		0.4	22.7	19.7	67	<0.1	21.9	10.8	509	2.41	12.9	1.4	2.0	6.7	16	0.1	1.2	0.3	19	0.24	0.062
KYS 109121	Soil		0.4	21.9	19.5	63	<0.1	20.3	10.6	515	2.35	12.9	1.4	1.6	6.8	16	0.1	1.2	0.3	17	0.27	0.061
KYS 109122	Soil		0.5	22.7	16.5	65	<0.1	20.8	8.9	369	2.45	15.7	2.4	2.3	5.8	12	<0.1	1.4	0.3	21	0.17	0.048
KYS 109123	Soil		1.1	16.9	19.2	50	<0.1	16.1	8.1	201	3.19	10.6	0.7	0.8	6.5	5	0.1	0.6	0.3	33	0.04	0.027
KYS 109124	Soil		1.0	28.7	22.0	66	0.1	22.1	10.0	246	3.37	5.6	1.3	2.7	3.2	6	0.1	0.7	0.3	17	0.03	0.040
KYS 109125	Soil		1.1	35.4	25.4	70	<0.1	26.6	18.7	567	3.31	12.7	1.5	4.2	3.9	8	0.1	3.8	0.4	22	0.09	0.068
KYS 109126	Soil		1.0	32.8	23.4	68	<0.1	25.6	17.6	395	3.56	9.1	1.6	2.5	5.4	7	0.2	1.7	0.4	31	0.05	0.041
KYS 109127	Soil		1.0	24.3	20.7	56	<0.1	18.1	7.9	259	3.16	8.2	1.2	3.1	3.6	7	<0.1	1.0	0.3	32	0.04	0.046
KYS 109128	Soil		1.1	43.8	26.8	82	<0.1	28.6	13.2	274	4.60	5.7	2.0	2.2	7.3	4	<0.1	1.0	0.5	12	0.01	0.030
KYS 109129	Soil		1.1	44.4	36.2	99	<0.1	27.6	16.1	299	4.69	6.1	1.9	<0.5	5.3	6	<0.1	0.7	0.4	16	0.02	0.037
KYS 109130	Soil		1.1	50.3	27.2	92	<0.1	29.0	16.3	468	5.06	5.2	2.4	2.3	6.2	6	<0.1	0.8	0.5	15	0.02	0.036
KYS 109131	Soil		0.8	24.1	19.0	90	0.1	20.0	10.1	549	3.17	6.3	3.4	0.9	1.8	36	0.3	0.6	0.3	18	0.36	0.068
KYS 109132	Soil		0.9	29.1	22.9	89	0.1	26.0	16.0	941	3.27	7.6	1.7	0.7	1.0	19	0.3	1.0	0.3	19	0.25	0.067
KYS 109133	Soil		0.5	18.4	16.2	60	<0.1	18.4	11.1	462	2.41	8.2	1.4	2.2	3.4	19	<0.1	0.9	0.2	23	0.26	0.063
KYS 109134	Soil		3.1	37.7	26.3	99	0.2	31.6	13.2	550	3.25	73.7	2.4	6.6	8.1	23	0.3	4.8	0.3	5	0.17	0.041
KYS 109135	Soil		2.8	45.1	26.4	110	0.2	34.8	15.7	623	3.61	25.9	2.4	3.9	5.8	19	0.6	3.1	0.4	9	0.18	0.045
KYS 109136	Soil		0.4	38.0	26.6	88	0.1	30.0	15.3	500	3.56	67.7	2.3	7.1	6.9	22	0.1	3.6	0.4	5	0.30	0.043
KYS 109137	Soil		0.3	38.3	31.5	98	0.2	32.0	14.2	540	3.46	180.4	1.7	15.3	14.3	17	0.1	8.0	0.4	4	0.25	0.042
KYS 109138	Soil		2.1	64.8	50.4	98	0.2	22.3	12.2	255	5.96	3.8	2.3	8.4	7.3	27	<0.1	1.8	1.2	11	0.03	0.049
KYS 109139	Soil		0.8	64.1	43.1	107	0.1	35.4	23.3	510	5.09	7.0	2.6	2.1	5.3	8	0.2	3.1	0.6	10	0.04	0.055
KYS 109140	Soil		0.9	48.1	30.1	97	0.1	29.7	13.2	428	4.47	8.6	2.5	4.2	11.5	11	0.2	4.0	0.5	9	0.14	0.037
KYS 109141	Soil		1.1	44.2	30.5	85	0.2	32.4	14.5	475	4.10	11.3	2.2	3.6	10.8	13	0.2	3.8	0.4	10	0.19	0.041
KYS 109142	Soil		0.8	53.8	32.3	97	0.1	31.1	17.4	437	4.71	12.2	2.1	1.2	8.9	13	0.1	3.4	0.5	9	0.13	0.039
KYS 109143	Soil		0.7	47.9	28.2	92	0.1	33.8	17.0	479	4.26	88.8	1.8	13.9	9.9	9	0.2	4.1	0.4	8	0.10	0.037

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109114	Soil	22	17	0.56	117	0.004	<1	1.37	0.005	0.05	<0.1	0.03	1.6	<0.1	<0.05	4	<0.5	0.4
KYS 109115	Soil	19	15	0.44	93	0.004	<1	1.13	0.003	0.04	<0.1	0.04	1.8	<0.1	<0.05	3	0.7	<0.2
KYS 109116	Soil	19	13	0.52	59	0.003	<1	1.14	0.002	0.04	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109117	Soil	24	14	0.61	51	0.004	<1	1.25	0.005	0.06	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109118	Soil	25	15	0.62	80	0.004	<1	1.35	0.003	0.05	<0.1	0.02	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109119	Soil	25	14	0.63	65	0.004	<1	1.34	0.003	0.06	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109120	Soil	20	15	0.49	104	0.006	3	1.25	0.009	0.06	<0.1	0.04	1.8	<0.1	0.08	3	0.8	<0.2
KYS 109121	Soil	21	16	0.48	108	0.006	<1	1.27	0.004	0.06	0.1	0.03	1.8	<0.1	0.06	3	0.5	<0.2
KYS 109122	Soil	19	17	0.48	84	0.010	2	1.22	0.005	0.05	<0.1	0.04	1.7	<0.1	<0.05	3	0.6	<0.2
KYS 109123	Soil	17	18	0.38	84	0.007	1	1.62	0.004	0.04	0.1	0.03	1.5	<0.1	<0.05	4	0.9	0.5
KYS 109124	Soil	17	14	0.45	51	0.006	2	1.17	0.005	0.05	<0.1	0.04	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109125	Soil	18	16	0.47	53	0.015	<1	1.18	0.005	0.04	<0.1	0.02	1.3	<0.1	<0.05	3	0.7	<0.2
KYS 109126	Soil	16	21	0.51	63	0.016	2	1.63	0.008	0.04	<0.1	0.05	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109127	Soil	16	19	0.43	87	0.011	2	1.40	0.005	0.05	0.1	0.04	1.5	<0.1	<0.05	4	0.8	<0.2
KYS 109128	Soil	19	13	0.49	46	0.002	1	1.28	0.005	0.05	<0.1	0.03	1.3	<0.1	<0.05	3	0.7	<0.2
KYS 109129	Soil	16	18	0.61	60	0.006	<1	1.69	0.007	0.05	<0.1	0.04	1.4	<0.1	<0.05	4	0.6	0.2
KYS 109130	Soil	17	19	0.68	61	0.004	<1	1.65	0.007	0.06	<0.1	0.04	1.5	<0.1	<0.05	4	<0.5	0.2
KYS 109131	Soil	11	15	0.47	99	0.004	<1	1.45	0.006	0.04	<0.1	0.04	1.2	<0.1	<0.05	4	1.0	<0.2
KYS 109132	Soil	11	16	0.48	103	0.007	<1	1.24	0.006	0.06	<0.1	0.03	1.0	<0.1	<0.05	3	0.8	<0.2
KYS 109133	Soil	15	18	0.46	116	0.008	<1	1.30	0.006	0.04	<0.1	0.04	1.5	<0.1	<0.05	3	0.9	<0.2
KYS 109134	Soil	17	6	0.25	45	0.002	1	0.62	0.004	0.06	<0.1	0.05	1.3	<0.1	<0.05	2	0.9	<0.2
KYS 109135	Soil	13	9	0.39	46	0.002	<1	0.93	0.004	0.04	<0.1	0.05	1.4	<0.1	<0.05	2	1.0	0.4
KYS 109136	Soil	15	8	0.36	35	0.001	<1	0.83	0.006	0.05	<0.1	0.02	1.1	<0.1	<0.05	2	0.6	0.4
KYS 109137	Soil	26	9	0.41	36	0.001	1	0.90	0.004	0.06	<0.1	0.03	1.5	<0.1	<0.05	2	0.5	0.4
KYS 109138	Soil	17	14	0.58	36	0.002	<1	1.44	0.007	0.05	<0.1	0.05	1.6	<0.1	<0.05	3	0.7	0.2
KYS 109139	Soil	15	16	0.67	28	0.002	<1	1.48	0.007	0.04	<0.1	0.05	1.1	<0.1	<0.05	4	<0.5	0.4
KYS 109140	Soil	23	15	0.68	32	0.001	<1	1.42	0.004	0.05	<0.1	0.04	1.2	<0.1	<0.05	3	0.6	0.2
KYS 109141	Soil	25	12	0.61	43	0.001	<1	1.28	0.006	0.06	<0.1	0.05	1.3	<0.1	<0.05	3	1.0	<0.2
KYS 109142	Soil	19	14	0.57	40	0.002	1	1.25	0.005	0.06	<0.1	0.04	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109143	Soil	20	12	0.66	31	0.002	2	1.23	0.006	0.05	<0.1	0.03	1.5	<0.1	0.05	3	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109144	Soil		0.8	43.8	28.1	93	0.1	30.4	14.6	461	4.09	114.6	1.5	23.3	11.3	11	0.2	9.5	0.4	8	0.15	0.041
KYS 109145	Soil		0.8	38.7	30.2	81	0.1	27.7	13.1	422	4.08	55.8	1.5	8.0	10.6	9	0.1	28.4	0.4	9	0.13	0.037
KYS 109146	Soil		0.7	43.5	30.5	90	0.2	29.9	13.5	447	4.12	78.1	1.7	13.4	10.1	8	<0.1	24.4	0.4	8	0.10	0.040
KYS 109147	Soil		0.6	46.1	29.7	101	0.2	32.0	15.5	462	4.19	150.6	2.2	22.9	7.8	8	0.2	10.0	0.4	8	0.09	0.040
KYS 109148	Soil		1.1	27.4	24.3	88	<0.1	24.0	11.7	477	3.40	48.1	1.6	5.8	5.1	10	0.1	3.6	0.3	19	0.14	0.062
KYS 109149	Soil		0.8	29.3	21.1	79	<0.1	25.7	11.7	526	3.31	59.9	1.5	4.7	5.8	14	0.1	5.5	0.3	20	0.18	0.055
KYS 109150	Soil		0.8	22.9	19.0	76	<0.1	21.4	11.1	476	3.13	53.8	1.3	5.5	5.4	14	0.2	6.4	0.2	19	0.19	0.063
KYS 109151	Soil		0.9	23.2	20.3	63	0.2	19.2	14.2	990	2.99	45.8	1.4	7.4	2.1	18	0.1	7.2	0.3	18	0.25	0.104
KYS 109152	Soil		1.7	36.5	21.2	103	0.2	26.5	9.8	293	2.77	23.4	1.8	7.4	5.4	25	0.3	4.3	0.3	12	0.29	0.053
KYS 109153	Soil		0.9	50.7	38.2	105	0.1	63.9	33.2	1643	4.42	19.3	2.1	5.2	8.0	6	0.1	0.9	0.4	13	0.05	0.051
KYS 109154	Soil		1.0	46.8	26.4	82	<0.1	39.0	15.9	733	4.10	13.4	2.3	2.8	5.9	11	0.1	1.0	0.4	15	0.09	0.040
KYS 109155	Soil		0.5	60.7	30.0	97	<0.1	36.6	19.1	1137	5.03	19.4	1.8	4.4	8.4	7	<0.1	1.0	0.5	12	0.08	0.042
KYS 109156	Soil		1.0	37.3	19.6	65	<0.1	30.6	14.4	675	3.46	13.3	1.3	6.4	6.4	5	0.1	0.9	0.4	29	0.04	0.030
KYS 109157	Soil		1.6	13.3	16.9	48	<0.1	12.0	8.8	626	2.94	10.2	0.5	4.1	4.1	7	0.2	0.9	0.2	50	0.06	0.026
KYS 109158	Soil		0.9	22.1	11.9	60	<0.1	18.9	6.9	308	2.43	8.1	0.9	4.7	2.2	9	0.1	0.6	0.2	27	0.11	0.052
KYS 109159	Soil		1.3	58.5	27.5	85	<0.1	30.9	12.8	257	4.83	3.2	2.0	1.7	6.9	11	<0.1	0.4	0.4	12	0.03	0.033
KYS 109160	Soil		0.9	58.0	30.4	92	<0.1	30.6	13.1	370	4.65	6.8	1.8	2.7	9.3	6	<0.1	0.8	0.4	11	0.03	0.027
KYS 109161	Soil		0.8	47.7	31.4	92	0.1	41.8	21.1	575	4.48	5.1	2.3	2.7	5.1	7	<0.1	4.3	0.4	14	0.10	0.047
KYS 109162	Soil		1.1	17.9	15.6	45	0.2	12.7	5.5	165	2.35	15.1	0.7	2.9	0.4	6	0.1	3.9	0.2	33	0.05	0.065
KYS 109163	Soil		0.7	24.6	14.2	68	<0.1	21.3	14.2	609	2.54	45.9	0.8	7.8	4.3	10	0.2	35.8	0.2	27	0.13	0.048
KYS 109164	Soil		1.0	26.2	17.1	60	<0.1	21.5	9.3	280	2.87	9.8	1.2	2.5	4.4	8	0.2	1.6	0.2	36	0.10	0.042
KYS 109165	Soil		1.1	29.0	20.7	68	<0.1	27.0	12.9	379	2.97	9.7	1.2	2.2	7.0	10	0.1	2.0	0.3	28	0.13	0.058
KYS 109166	Soil		0.9	31.2	20.0	66	<0.1	23.9	10.9	409	3.03	9.8	1.5	2.9	3.3	9	0.1	1.5	0.3	31	0.10	0.052
KYS 109167	Soil		0.8	27.9	14.6	66	<0.1	27.2	13.1	549	2.56	10.3	1.0	2.6	5.9	9	0.2	1.2	0.2	26	0.13	0.058
KYS 109168	Soil		0.7	21.0	13.4	54	<0.1	20.2	8.2	333	2.47	9.6	0.8	2.7	3.7	11	<0.1	1.2	0.2	32	0.17	0.047
KYS 109169	Soil		0.5	50.2	28.9	83	0.1	40.3	21.2	769	4.00	12.7	2.2	3.1	12.0	13	<0.1	1.0	0.5	7	0.14	0.052
KYS 109170	Soil		0.4	39.5	17.5	61	<0.1	32.4	16.4	447	3.22	16.7	1.9	2.5	11.8	11	<0.1	2.1	0.3	6	0.13	0.033
KYS 109171	Soil		0.7	57.6	32.8	97	<0.1	45.1	19.0	422	4.14	16.8	3.8	5.0	19.1	17	<0.1	5.2	0.5	8	0.27	0.030
KYS 109172	Soil		1.0	27.2	13.5	64	<0.1	23.6	8.4	395	2.60	8.4	1.1	3.5	5.1	10	0.1	0.7	0.2	28	0.13	0.058
KYS 109173	Soil		0.6	58.4	36.8	100	0.2	41.7	17.9	885	4.76	157.3	2.5	14.2	13.0	12	0.1	9.5	0.5	10	0.13	0.048

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109144	Soil	22	12	0.59	35	0.001	<1	1.13	0.005	0.05	<0.1	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109145	Soil	22	12	0.54	32	0.002	<1	1.03	0.005	0.05	<0.1	0.03	1.4	<0.1	0.05	3	<0.5	<0.2
KYS 109146	Soil	20	12	0.57	33	0.002	1	1.10	0.005	0.04	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109147	Soil	19	14	0.67	39	0.002	<1	1.32	0.004	0.05	<0.1	0.04	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109148	Soil	20	17	0.64	94	0.006	2	1.46	0.006	0.05	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109149	Soil	21	19	0.61	99	0.006	<1	1.50	0.006	0.04	<0.1	0.03	1.4	<0.1	<0.05	4	1.0	<0.2
KYS 109150	Soil	21	15	0.57	90	0.007	<1	1.29	0.005	0.04	<0.1	0.04	1.3	<0.1	0.07	4	0.9	0.3
KYS 109151	Soil	14	14	0.43	151	0.005	<1	1.20	0.007	0.05	<0.1	0.04	1.0	<0.1	0.09	4	<0.5	0.3
KYS 109152	Soil	16	11	0.44	84	0.003	<1	0.94	0.005	0.04	<0.1	0.05	1.2	<0.1	0.09	3	1.5	<0.2
KYS 109153	Soil	21	19	0.66	59	0.004	1	1.66	0.005	0.04	<0.1	0.03	1.6	<0.1	<0.05	4	0.7	<0.2
KYS 109154	Soil	19	18	0.63	69	0.006	<1	1.50	0.006	0.04	<0.1	0.03	1.4	<0.1	<0.05	4	0.8	0.3
KYS 109155	Soil	17	26	0.87	39	0.003	2	1.79	0.018	0.07	<0.1	0.02	1.7	<0.1	<0.05	6	0.7	0.3
KYS 109156	Soil	20	21	0.42	115	0.010	2	1.65	0.005	0.04	<0.1	0.04	1.9	<0.1	<0.05	4	<0.5	0.2
KYS 109157	Soil	14	19	0.19	79	0.022	2	1.23	0.004	0.03	0.1	0.01	1.5	0.1	<0.05	5	<0.5	<0.2
KYS 109158	Soil	17	18	0.37	72	0.013	2	1.17	0.005	0.04	0.1	0.03	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109159	Soil	14	16	0.56	59	0.002	1	1.36	0.006	0.08	<0.1	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109160	Soil	23	14	0.50	41	0.001	<1	1.25	0.006	0.06	<0.1	0.02	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109161	Soil	20	17	0.56	31	0.004	<1	1.31	0.004	0.04	<0.1	0.01	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 109162	Soil	12	19	0.22	49	0.007	2	1.15	0.004	0.03	0.1	0.05	0.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109163	Soil	21	18	0.35	93	0.021	1	1.06	0.004	0.05	<0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109164	Soil	17	21	0.33	102	0.026	2	1.31	0.005	0.04	0.2	0.03	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109165	Soil	22	17	0.38	72	0.026	1	1.17	0.004	0.04	0.1	0.02	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109166	Soil	20	20	0.37	103	0.020	2	1.40	0.005	0.06	0.2	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109167	Soil	19	18	0.34	79	0.028	2	1.10	0.005	0.05	0.1	0.02	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 109168	Soil	20	20	0.35	93	0.020	1	1.27	0.008	0.05	0.1	0.02	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109169	Soil	27	8	0.24	41	0.004	1	0.66	0.005	0.07	<0.1	0.03	1.8	<0.1	<0.05	2	<0.5	<0.2
KYS 109170	Soil	24	6	0.22	36	0.003	1	0.58	0.005	0.08	<0.1	0.02	1.3	<0.1	<0.05	1	<0.5	<0.2
KYS 109171	Soil	28	12	0.45	36	0.002	1	1.20	0.005	0.07	<0.1	0.01	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109172	Soil	24	19	0.39	82	0.021	2	1.26	0.004	0.06	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 109173	Soil	29	17	0.57	57	0.002	<1	1.50	0.004	0.06	<0.1	0.04	1.7	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109174	Soil		0.7	50.8	34.4	91	0.2	37.1	15.8	846	3.89	190.6	1.5	22.9	12.9	13	<0.1	10.9	0.4	9	0.26	0.037
KYS 109175	Soil		0.4	44.3	24.6	83	0.1	35.2	15.6	635	3.49	103.8	1.4	14.6	15.7	14	<0.1	5.5	0.4	8	0.35	0.047
KYS 109176	Soil		0.4	45.4	26.7	86	0.1	34.0	14.6	573	3.66	109.0	1.5	14.9	14.2	14	<0.1	6.0	0.4	9	0.31	0.044
KYS 109177	Soil		0.5	44.2	23.5	87	<0.1	35.5	13.9	659	3.76	58.3	1.6	7.6	14.3	10	<0.1	4.4	0.3	9	0.21	0.036
KYS 109178	Soil		1.2	55.1	32.0	130	0.1	49.1	19.6	821	4.55	51.0	1.9	6.9	13.7	11	0.2	7.2	0.4	11	0.13	0.044
KYS 109179	Soil		1.4	25.5	18.3	56	0.2	21.6	8.2	321	3.48	21.7	0.8	2.9	3.2	7	0.2	2.1	0.2	44	0.06	0.045
KYS 109180	Soil		2.4	58.6	29.5	153	0.1	67.4	25.3	1331	4.56	23.6	1.8	3.6	12.4	11	1.1	2.1	0.3	15	0.16	0.052
KYS 109181	Soil		2.2	268.6	17.0	131	0.8	68.7	35.4	2751	4.32	14.1	2.8	52.6	3.5	9	0.4	2.2	0.3	37	0.04	0.082
KYS 109182	Soil		2.1	226.1	23.0	93	0.3	59.8	52.7	1667	3.37	20.1	1.9	37.3	6.0	13	0.5	2.0	0.3	36	0.07	0.076
KYS 109183	Soil		1.8	45.7	13.2	48	<0.1	15.4	6.2	384	3.07	13.9	0.7	9.0	3.8	9	0.1	1.3	0.2	50	0.07	0.034
KYS 109184	Soil		1.8	75.9	12.6	71	0.2	32.4	11.3	553	2.88	15.8	1.3	12.4	5.0	12	0.2	1.9	0.2	40	0.10	0.046
KYS 109185	Soil		1.7	61.0	10.4	59	<0.1	22.3	6.5	258	2.43	12.3	1.0	18.4	4.1	10	0.2	2.3	0.2	38	0.08	0.034
KYS 109186	Soil		1.8	48.3	11.3	57	0.1	16.9	7.2	565	2.64	11.8	0.9	14.2	1.0	9	0.3	1.4	0.2	47	0.07	0.055
KYS 109187	Soil		8.8	50.0	16.1	104	0.5	18.1	6.4	409	2.12	11.6	1.8	12.1	0.8	10	0.6	2.2	0.2	32	0.03	0.075
KYS 109188	Soil		1.0	24.7	18.0	62	<0.1	20.6	10.8	390	2.71	8.9	0.9	4.8	4.6	9	0.2	0.7	0.3	34	0.10	0.041
KYS 109189	Soil		1.0	43.2	24.7	83	<0.1	37.3	19.9	827	3.45	19.4	1.2	3.9	4.7	17	<0.1	0.9	0.3	31	0.24	0.059
KYS 109190	Soil		1.0	29.3	19.8	67	<0.1	24.8	10.6	576	3.11	13.3	1.1	3.2	3.5	15	0.2	0.7	0.2	32	0.19	0.053
KYS 109191	Soil		1.1	38.3	15.9	77	0.1	26.4	8.6	371	2.78	5.7	1.4	4.1	8.5	13	<0.1	0.5	0.3	23	0.17	0.059
KYS 109192	Soil		1.7	29.7	17.2	80	<0.1	21.3	8.4	456	2.77	12.4	1.3	4.2	3.6	14	0.2	3.0	0.3	23	0.15	0.061
KYS 109193	Soil		1.0	29.6	19.2	68	<0.1	22.1	8.9	478	2.71	18.8	1.1	5.8	4.1	12	0.2	10.1	0.3	23	0.14	0.053
KYS 109194	Soil		0.8	61.4	24.4	84	0.3	33.0	13.2	843	2.88	234.2	1.4	77.6	10.0	17	0.2	235.3	0.4	17	0.22	0.055
KYS 109195	Soil		0.6	41.3	21.6	68	0.1	24.4	10.0	490	2.56	68.7	1.2	23.9	8.5	11	<0.1	63.5	0.4	19	0.15	0.040
KYS 109196	Soil		0.6	32.0	17.6	65	<0.1	23.5	9.1	443	2.52	12.6	1.2	7.5	5.3	14	0.1	5.6	0.3	22	0.23	0.042
KYS 109197	Soil		1.1	81.8	26.5	92	0.4	33.0	13.7	769	3.41	424.5	1.4	91.4	9.4	15	0.1	85.6	0.4	16	0.14	0.050
KYS 109198	Soil		0.8	37.9	23.6	75	<0.1	25.7	12.3	602	2.96	26.7	1.1	7.9	6.3	9	0.2	7.9	0.3	26	0.12	0.049
KYS 109199	Soil		3.8	55.7	23.1	104	0.4	28.5	9.8	445	3.21	28.5	1.7	8.2	12.2	29	0.2	12.4	0.3	24	0.19	0.071
KYS 109200	Soil		0.7	33.7	21.3	70	<0.1	26.9	12.0	704	3.09	21.2	1.1	12.0	7.2	9	0.1	7.7	0.3	21	0.09	0.038
KYS 109201	Soil		0.7	56.3	36.4	84	0.2	36.3	18.1	777	4.24	22.3	1.8	3.1	3.8	6	<0.1	2.1	0.5	12	0.06	0.059
KYS 109202	Soil		0.4	57.7	26.7	102	<0.1	46.8	20.1	854	4.52	75.9	2.0	15.7	10.9	8	<0.1	3.6	0.4	11	0.08	0.037
KYS 109203	Soil		2.2	45.0	24.0	119	0.1	35.8	16.7	669	3.50	11.0	1.9	1.6	9.3	10	0.6	1.3	0.3	13	0.07	0.062

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109174	Soil	30	12	0.37	62	0.003	2	1.04	0.005	0.06	<0.1	0.04	2.0	<0.1	<0.05	3	<0.5	<0.2
KYS 109175	Soil	37	12	0.47	44	0.004	<1	1.14	0.002	0.07	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109176	Soil	35	14	0.57	50	0.003	2	1.30	0.004	0.08	<0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109177	Soil	34	15	0.60	40	0.002	1	1.33	0.005	0.06	<0.1	0.02	1.4	<0.1	<0.05	3	<0.5	0.2
KYS 109178	Soil	31	15	0.47	58	0.002	1	1.34	0.004	0.06	<0.1	0.04	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109179	Soil	15	26	0.25	84	0.037	2	1.43	0.005	0.04	0.2	0.07	1.7	<0.1	<0.05	5	0.6	<0.2
KYS 109180	Soil	31	20	0.64	90	0.003	<1	1.59	0.004	0.07	<0.1	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109181	Soil	21	27	0.39	134	0.012	1	1.81	0.004	0.06	0.1	0.15	1.7	<0.1	<0.05	4	1.3	<0.2
KYS 109182	Soil	24	23	0.42	155	0.021	1	1.69	0.004	0.04	0.1	0.11	1.7	<0.1	<0.05	4	0.9	0.3
KYS 109183	Soil	18	21	0.26	102	0.034	<1	1.19	0.004	0.04	0.2	0.03	1.6	<0.1	<0.05	5	<0.5	<0.2
KYS 109184	Soil	19	26	0.35	137	0.044	1	1.59	0.005	0.05	0.2	0.08	2.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109185	Soil	20	20	0.27	117	0.037	2	1.03	0.005	0.04	0.2	0.03	1.6	<0.1	<0.05	3	0.6	<0.2
KYS 109186	Soil	18	22	0.24	103	0.027	2	1.07	0.005	0.04	0.2	0.04	1.1	<0.1	<0.05	4	0.7	<0.2
KYS 109187	Soil	22	12	0.12	110	0.014	1	0.67	0.005	0.04	0.1	0.22	0.5	<0.1	<0.05	3	1.8	<0.2
KYS 109188	Soil	16	19	0.30	82	0.020	<1	1.17	0.005	0.05	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 109189	Soil	16	24	0.52	93	0.018	<1	1.47	0.006	0.06	<0.1	0.02	1.7	<0.1	<0.05	5	<0.5	<0.2
KYS 109190	Soil	17	22	0.39	131	0.016	<1	1.34	0.006	0.06	0.1	0.02	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109191	Soil	29	19	0.48	125	0.007	<1	1.41	0.004	0.06	<0.1	0.05	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109192	Soil	18	16	0.42	132	0.009	1	1.19	0.005	0.04	<0.1	0.03	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109193	Soil	20	16	0.44	111	0.011	2	1.12	0.006	0.04	<0.1	0.03	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 109194	Soil	27	15	0.51	135	0.004	1	1.27	0.006	0.05	0.1	0.05	2.0	<0.1	<0.05	3	<0.5	0.3
KYS 109195	Soil	25	16	0.49	106	0.008	2	1.17	0.007	0.07	0.2	0.04	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109196	Soil	22	17	0.42	98	0.013	1	1.12	0.005	0.06	<0.1	0.03	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109197	Soil	30	11	0.28	171	0.004	2	0.86	0.005	0.05	<0.1	0.07	2.4	<0.1	<0.05	2	<0.5	0.3
KYS 109198	Soil	25	17	0.48	101	0.012	1	1.31	0.005	0.04	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 109199	Soil	34	16	0.50	207	0.006	2	1.22	0.005	0.06	<0.1	0.15	1.7	<0.1	<0.05	4	0.6	<0.2
KYS 109200	Soil	24	17	0.47	127	0.006	<1	1.32	0.005	0.06	<0.1	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109201	Soil	13	14	0.39	66	0.003	<1	1.15	0.006	0.05	<0.1	0.05	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109202	Soil	24	22	0.70	42	0.004	2	1.67	0.010	0.09	<0.1	0.03	1.8	<0.1	<0.05	5	<0.5	<0.2
KYS 109203	Soil	28	15	0.53	48	0.005	<1	1.20	0.005	0.06	<0.1	0.03	0.9	<0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109204	Soil	0.5	34.2	18.5	80	<0.1	25.3	10.5	393	3.63	12.9	1.6	2.7	7.1	6	<0.1	0.8	0.3	12	0.04	0.034
KYS 109205	Soil	0.5	31.2	18.6	79	<0.1	24.4	9.3	333	3.47	15.0	1.3	1.8	5.4	7	<0.1	0.9	0.3	11	0.06	0.037
KYS 109206	Soil	1.1	28.0	29.8	65	0.1	17.5	7.8	291	3.23	269.0	1.2	5.1	1.6	9	0.1	2.4	0.4	20	0.05	0.062
KYS 109207	Soil	3.3	43.7	22.4	85	<0.1	23.9	8.1	275	3.60	15.2	1.8	4.5	5.8	10	0.2	1.8	0.3	31	0.05	0.060
KYS 109208	Soil	2.8	66.1	47.3	93	0.2	39.1	20.9	1234	4.87	57.1	2.9	7.2	5.0	37	0.4	7.9	0.5	5	0.69	0.060
KYS 109209	Soil	0.4	50.9	29.8	85	<0.1	40.3	21.3	668	4.40	49.4	2.6	6.0	15.4	14	<0.1	3.7	0.6	4	0.12	0.040
KYS 109210	Soil	0.3	42.0	28.8	75	<0.1	34.1	21.4	635	3.32	33.6	1.8	3.4	12.4	15	0.2	3.6	0.3	4	0.13	0.032
KYS 109211	Soil	2.3	48.7	27.1	102	0.2	31.0	13.9	365	4.03	4.8	2.9	1.4	7.1	24	0.3	1.5	0.4	11	0.06	0.028
KYS 109212	Soil	7.0	68.9	35.2	160	0.4	64.2	23.8	682	5.08	48.9	4.6	2.7	15.1	40	1.2	6.9	0.5	18	0.15	0.053
KYS 109213	Soil	2.6	70.0	38.2	129	0.2	51.1	23.2	1029	4.67	16.1	3.3	3.6	7.1	46	0.6	3.9	0.5	10	0.20	0.064
KYS 109214	Soil	3.9	63.4	30.1	105	0.2	40.0	15.4	656	3.81	10.5	3.1	3.8	2.4	36	0.7	3.3	0.4	17	0.24	0.072
KYS 109215	Soil	3.0	62.3	22.4	101	0.1	34.2	14.9	492	3.55	5.0	2.3	3.0	3.8	19	0.4	2.8	0.3	19	0.18	0.089
KYS 109216	Soil	3.1	80.7	34.5	150	0.3	51.8	17.3	1152	4.32	9.9	4.1	4.8	3.8	23	1.1	6.8	0.4	15	0.14	0.088
KYS 109217	Soil	15.2	46.1	34.9	87	0.3	25.5	7.1	259	2.73	20.9	3.6	1.5	7.8	82	0.6	7.0	0.5	13	0.10	0.065
KYS 109218	Soil	12.6	34.9	25.7	78	0.3	20.0	8.1	367	2.50	17.8	2.2	2.0	6.2	22	0.4	5.2	0.4	16	0.08	0.047
KYS 109219	Soil	2.1	25.1	15.8	65	<0.1	16.1	6.4	266	3.07	9.8	1.0	1.7	1.6	12	0.2	1.5	0.3	42	0.05	0.043
KYS 109220	Soil	1.0	99.3	17.6	65	0.1	26.5	10.4	546	2.71	12.6	1.1	11.2	4.4	19	0.3	1.3	0.2	37	0.10	0.038
KYS 109221	Soil	2.6	81.6	15.4	87	0.2	27.4	8.6	446	3.01	8.2	1.5	14.2	2.3	28	0.3	3.6	0.2	40	0.07	0.053
KYS 109222	Soil	1.2	83.0	14.3	67	<0.1	24.4	7.6	363	2.76	11.2	1.1	10.0	1.3	15	0.2	2.3	0.2	40	0.07	0.048
KYS 109223	Soil	1.4	228.1	27.5	98	0.2	43.9	21.0	1862	3.04	10.8	2.0	25.7	3.5	32	0.1	2.2	0.3	37	0.10	0.085
KYS 109224	Soil	2.1	226.4	28.9	125	0.3	54.5	23.8	1835	3.65	18.6	3.5	17.5	5.5	29	0.3	10.0	0.3	33	0.07	0.067
KYS 109225	Soil	2.5	231.0	30.8	135	0.5	51.8	16.9	1726	3.70	254.6	4.3	110.2	6.3	30	0.5	20.2	0.4	31	0.05	0.071
KYS 109226	Soil	2.3	136.2	38.7	153	0.3	51.0	16.8	1402	4.34	90.1	3.6	42.7	7.6	24	0.5	28.7	0.5	25	0.06	0.055
KYS 109227	Soil	2.2	98.3	35.5	132	0.2	46.4	18.0	1084	4.19	96.3	3.2	40.1	6.5	20	0.3	16.3	0.4	19	0.05	0.052
KYS 109228	Soil	1.9	101.9	39.2	124	0.2	51.6	25.0	1096	4.38	63.1	2.5	10.6	16.5	39	0.5	12.0	0.5	10	0.17	0.054
KYS 109230	Soil	1.7	93.1	45.0	115	0.1	56.3	38.0	878	5.00	18.5	3.8	4.4	7.9	13	0.2	7.6	0.7	10	0.10	0.056
KYS 109231	Soil	1.9	68.5	35.0	118	0.2	51.1	26.8	942	4.42	14.7	2.6	2.3	8.0	23	0.3	2.2	0.5	8	0.25	0.058
KYS 109232	Soil	1.6	66.4	31.5	106	0.1	52.9	27.0	1082	3.96	22.0	2.5	3.8	9.1	18	0.3	3.0	0.5	7	0.14	0.052
KYS 109233	Soil	2.4	86.0	35.8	124	0.2	55.2	28.8	1272	4.58	30.1	3.0	4.2	10.3	25	0.5	3.0	0.5	11	0.17	0.056
KYS 109234	Soil	2.5	83.4	34.7	126	0.2	53.8	28.5	1287	4.38	30.0	2.7	5.5	9.8	25	0.5	2.8	0.5	11	0.18	0.056

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109204	Soil	24	19	0.74	41	0.004	1	1.70	0.005	0.05	<0.1	0.01	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 109205	Soil	20	18	0.69	38	0.002	<1	1.46	0.006	0.04	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109206	Soil	17	17	0.42	65	0.005	<1	1.19	0.006	0.04	0.1	0.03	0.7	<0.1	<0.05	4	0.5	<0.2
KYS 109207	Soil	25	21	0.42	66	0.018	<1	1.36	0.005	0.04	0.2	0.05	1.3	<0.1	<0.05	4	1.1	<0.2
KYS 109208	Soil	11	5	0.26	53	0.005	1	0.46	0.009	0.06	<0.1	0.04	2.3	<0.1	0.09	1	1.0	0.2
KYS 109209	Soil	22	5	0.20	31	0.004	<1	0.46	0.006	0.06	<0.1	0.02	1.9	<0.1	<0.05	1	<0.5	0.2
KYS 109210	Soil	16	6	0.27	23	0.002	<1	0.68	0.005	0.07	<0.1	0.02	1.5	<0.1	<0.05	2	<0.5	<0.2
KYS 109211	Soil	13	14	0.54	23	0.003	<1	1.24	0.010	0.05	<0.1	0.04	1.2	<0.1	<0.05	3	0.8	<0.2
KYS 109212	Soil	23	17	0.66	39	0.003	<1	1.67	0.014	0.07	<0.1	0.07	2.0	<0.1	<0.05	4	1.7	<0.2
KYS 109213	Soil	14	10	0.33	58	0.004	<1	0.83	0.014	0.06	<0.1	0.07	2.2	<0.1	0.08	2	0.8	0.3
KYS 109214	Soil	12	13	0.39	71	0.007	<1	1.06	0.008	0.05	<0.1	0.05	1.7	<0.1	<0.05	3	1.1	0.2
KYS 109215	Soil	16	14	0.52	104	0.005	<1	1.09	0.005	0.04	<0.1	0.06	1.9	<0.1	<0.05	3	0.6	<0.2
KYS 109216	Soil	13	12	0.37	48	0.005	<1	0.94	0.006	0.04	<0.1	0.07	1.9	<0.1	<0.05	2	0.9	0.3
KYS 109217	Soil	15	8	0.19	77	0.003	<1	0.54	0.006	0.06	<0.1	0.19	1.4	0.2	0.09	2	1.7	0.2
KYS 109218	Soil	21	8	0.21	83	0.003	<1	0.60	0.004	0.04	<0.1	0.20	1.4	0.1	<0.05	2	1.7	0.2
KYS 109219	Soil	15	18	0.33	79	0.019	<1	1.16	0.003	0.05	0.2	0.04	1.2	0.1	<0.05	5	<0.5	<0.2
KYS 109220	Soil	17	21	0.45	108	0.038	<1	1.30	0.007	0.05	0.2	0.04	2.0	<0.1	<0.05	4	0.5	<0.2
KYS 109221	Soil	20	20	0.30	247	0.029	<1	1.23	0.006	0.05	<0.1	0.06	1.3	<0.1	0.06	4	0.6	<0.2
KYS 109222	Soil	15	23	0.45	118	0.027	<1	1.31	0.006	0.05	0.1	0.06	1.3	<0.1	0.06	4	<0.5	<0.2
KYS 109223	Soil	26	22	0.61	138	0.021	<1	1.27	0.006	0.05	0.1	0.07	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 109224	Soil	24	22	0.71	162	0.019	<1	1.53	0.007	0.06	<0.1	0.06	2.1	<0.1	<0.05	4	<0.5	0.2
KYS 109225	Soil	29	20	0.62	121	0.011	<1	1.47	0.006	0.05	<0.1	0.07	1.8	<0.1	<0.05	4	0.7	0.9
KYS 109226	Soil	29	19	0.64	109	0.008	<1	1.48	0.007	0.05	<0.1	0.05	1.9	<0.1	<0.05	4	0.7	0.6
KYS 109227	Soil	26	16	0.48	105	0.005	<1	1.38	0.006	0.07	<0.1	0.05	1.7	<0.1	<0.05	4	0.5	0.4
KYS 109228	Soil	18	11	0.40	95	0.004	1	1.05	0.019	0.08	<0.1	0.05	1.7	<0.1	0.20	3	1.1	0.2
KYS 109230	Soil	14	14	0.50	41	0.003	<1	1.20	0.006	0.05	<0.1	0.04	1.5	<0.1	0.05	3	<0.5	0.3
KYS 109231	Soil	14	11	0.46	40	0.003	<1	0.97	0.008	0.05	<0.1	0.04	1.9	<0.1	<0.05	2	0.5	<0.2
KYS 109232	Soil	13	11	0.42	39	0.002	1	0.98	0.006	0.04	<0.1	0.04	1.5	<0.1	<0.05	2	<0.5	<0.2
KYS 109233	Soil	17	12	0.50	63	0.002	<1	1.16	0.007	0.06	<0.1	0.04	1.7	<0.1	<0.05	3	0.6	0.3
KYS 109234	Soil	17	12	0.48	51	0.002	1	1.14	0.006	0.06	<0.1	0.05	1.9	<0.1	<0.05	3	0.6	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109235	Soil		2.0	144.7	28.3	115	0.2	53.0	21.8	3135	3.73	45.3	1.4	24.3	4.0	17	0.2	11.8	0.4	40	0.08	0.091
KYS 109236	Soil		1.7	95.5	22.2	109	0.3	49.4	17.3	2082	3.39	26.3	1.3	17.2	4.1	13	0.2	4.3	0.4	41	0.06	0.077
KYS 109237	Soil		1.7	102.0	21.6	107	0.1	47.1	16.0	2131	3.38	31.4	1.3	20.9	2.5	11	0.3	7.1	0.3	37	0.06	0.074
KYS 109238	Soil		2.0	73.5	22.6	111	0.1	33.8	13.3	1261	3.53	24.2	1.8	8.8	2.1	9	0.2	3.4	0.4	35	0.05	0.079
KYS 109239	Soil		1.3	45.3	19.7	97	0.2	36.2	14.6	1077	3.26	46.2	1.3	12.4	2.5	9	0.2	7.2	0.3	30	0.05	0.049
KYS 109240	Soil		1.4	49.3	18.5	114	0.2	35.8	11.3	995	3.37	64.2	1.0	15.8	2.6	17	0.3	10.9	0.3	26	0.26	0.085
KYS 109241	Soil		1.5	52.7	28.0	105	0.3	38.5	16.6	1188	3.91	106.0	1.7	21.7	6.4	18	0.3	11.9	0.3	20	0.45	0.080
KYS 109242	Soil		0.8	68.9	57.7	113	0.1	54.2	27.2	939	3.76	73.9	2.3	6.8	19.8	19	0.2	9.5	0.4	9	0.36	0.066
KYS 109243	Soil		0.8	49.9	23.5	89	0.2	37.2	14.9	796	3.58	143.2	1.6	22.2	9.7	16	0.2	8.6	0.3	21	0.21	0.066
KYS 109244	Soil		1.1	54.7	23.2	106	0.3	40.3	15.0	921	3.48	184.7	1.4	34.4	5.9	11	0.2	11.3	0.3	21	0.06	0.054
KYS 109245	Soil		1.2	42.6	15.9	81	0.3	31.7	9.7	558	2.72	68.7	1.4	26.6	5.1	12	0.4	4.3	0.2	41	0.10	0.047
KYS 109246	Soil		1.2	49.9	25.6	104	0.2	36.8	17.3	1057	3.44	55.5	1.4	17.2	3.6	10	0.2	4.8	0.3	29	0.07	0.068
KYS 109247	Soil		1.7	82.8	29.2	136	0.5	62.8	21.5	1683	4.17	58.6	1.6	38.9	6.9	20	0.3	6.3	0.4	27	0.22	0.069
KYS 109248	Soil		1.8	80.6	29.6	143	0.4	65.6	22.3	1394	3.89	22.0	1.8	8.4	11.7	18	0.4	3.2	0.4	27	0.10	0.068
KYS 109249	Soil		2.1	100.3	28.6	167	0.5	73.7	22.9	2013	3.86	58.5	1.7	20.3	10.5	17	0.4	3.2	0.4	27	0.08	0.075
KYS 109250	Soil		2.2	170.5	33.1	180	0.5	92.6	30.6	3238	4.45	30.5	1.8	41.0	8.1	19	0.2	2.9	0.5	34	0.10	0.067
KYS 109251	Soil		2.2	164.9	31.2	155	0.6	83.2	30.4	3767	4.28	21.0	1.7	26.1	8.7	18	0.2	2.4	0.5	30	0.07	0.071
KYS 109252	Soil		2.3	202.7	31.0	138	0.3	82.3	32.3	4123	3.97	32.8	1.6	56.9	9.0	21	0.1	3.0	0.5	30	0.10	0.068
KYS 109253	Soil		2.2	224.7	34.9	135	0.1	76.7	34.3	5081	4.51	28.7	1.3	43.8	7.3	21	0.1	2.0	0.5	35	0.10	0.074
KYS 109254	Soil		2.3	217.6	32.0	154	0.4	95.0	35.8	5094	4.32	31.8	1.7	45.1	10.9	36	0.2	8.8	0.5	30	0.14	0.078
KYS 109255	Soil		1.9	237.8	31.0	134	0.3	85.8	33.0	6421	4.16	36.0	1.2	32.4	9.1	43	0.2	10.9	0.4	31	0.18	0.088
KYS 109256	Soil		2.0	164.4	30.5	156	0.4	90.7	31.2	3906	3.97	21.2	1.6	88.1	10.7	32	0.3	2.1	0.4	31	0.12	0.068
KYS 109257	Soil		1.8	173.3	30.4	152	0.4	87.4	30.5	3818	3.85	19.6	1.5	73.1	9.8	32	0.2	2.3	0.5	35	0.11	0.067
KYS 109258	Soil		2.2	183.9	38.0	163	0.5	108.0	41.0	4784	4.07	21.8	1.6	41.6	12.0	34	0.3	3.5	0.5	34	0.11	0.065
KYS 109259	Soil		2.4	256.2	38.9	145	0.3	105.3	47.8	6680	4.55	32.3	1.9	57.6	6.0	27	0.1	2.9	0.6	41	0.09	0.086
KYS 109260	Soil		2.3	177.2	34.5	128	0.4	75.1	29.6	4497	4.04	48.4	1.8	56.7	6.0	23	0.2	6.2	0.5	39	0.07	0.081
KYS 109261	Soil		2.2	221.3	36.7	139	0.4	85.7	33.5	5112	3.87	106.0	1.8	40.6	8.8	20	0.3	12.8	0.5	31	0.06	0.069
KYS 109262	Soil		2.0	172.9	42.3	146	1.9	80.4	30.6	4619	3.73	435.6	1.5	105.6	9.4	23	0.5	32.8	0.4	25	0.04	0.056
KYS 109263	Soil		2.8	142.3	35.1	119	0.7	69.8	30.1	3146	4.36	439.7	1.9	64.0	10.3	28	0.4	32.4	0.4	24	0.13	0.095
KYS 109264	Soil		1.4	65.5	27.2	88	0.3	39.0	17.9	1389	3.17	302.3	1.9	61.3	10.7	15	0.2	16.5	0.3	15	0.12	0.058

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109235	Soil	27	25	0.53	128	0.018	<1	1.48	0.009	0.04	0.2	0.07	2.5	<0.1	<0.05	4	0.8	0.2
KYS 109236	Soil	23	24	0.52	114	0.019	2	1.52	0.006	0.04	0.1	0.07	2.0	<0.1	<0.05	4	0.6	<0.2
KYS 109237	Soil	22	23	0.52	137	0.016	2	1.44	0.008	0.05	0.1	0.05	2.1	<0.1	<0.05	4	<0.5	0.2
KYS 109238	Soil	23	23	0.52	176	0.014	1	1.54	0.005	0.05	0.1	0.04	1.7	<0.1	<0.05	4	0.5	<0.2
KYS 109239	Soil	20	21	0.43	114	0.016	<1	1.35	0.006	0.05	0.1	0.04	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109240	Soil	17	23	0.40	143	0.008	1	1.10	0.009	0.05	0.1	0.04	1.3	<0.1	<0.05	3	0.6	<0.2
KYS 109241	Soil	17	16	0.48	107	0.005	2	1.10	0.007	0.06	0.1	0.07	2.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109242	Soil	25	11	0.55	42	0.004	1	1.07	0.005	0.05	<0.1	0.03	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 109243	Soil	24	17	0.46	97	0.008	1	1.12	0.006	0.06	<0.1	0.04	2.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109244	Soil	22	17	0.39	102	0.009	<1	1.08	0.007	0.05	0.1	0.06	1.6	<0.1	<0.05	3	0.6	<0.2
KYS 109245	Soil	17	22	0.37	109	0.035	2	1.14	0.007	0.04	0.3	0.07	2.1	<0.1	<0.05	3	0.6	<0.2
KYS 109246	Soil	17	20	0.38	95	0.010	<1	1.08	0.006	0.04	0.1	0.07	1.5	<0.1	<0.05	3	<0.5	0.2
KYS 109247	Soil	15	22	0.53	105	0.005	<1	1.24	0.010	0.04	<0.1	0.07	2.4	<0.1	<0.05	4	1.1	<0.2
KYS 109248	Soil	24	22	0.50	78	0.005	<1	1.26	0.006	0.04	<0.1	0.07	1.9	<0.1	<0.05	4	1.0	0.2
KYS 109249	Soil	26	23	0.50	78	0.007	<1	1.24	0.007	0.03	<0.1	0.06	1.9	<0.1	<0.05	3	1.6	0.3
KYS 109250	Soil	31	30	0.74	120	0.004	2	1.66	0.009	0.03	<0.1	0.14	1.9	<0.1	<0.05	5	1.9	0.2
KYS 109251	Soil	32	28	0.69	134	0.005	1	1.64	0.008	0.04	<0.1	0.15	1.9	<0.1	<0.05	4	2.0	0.4
KYS 109252	Soil	32	24	0.68	118	0.004	<1	1.53	0.005	0.03	<0.1	0.13	1.8	<0.1	<0.05	4	1.3	0.2
KYS 109253	Soil	34	25	0.90	149	0.005	1	1.85	0.007	0.03	<0.1	0.13	2.1	<0.1	<0.05	6	1.2	<0.2
KYS 109254	Soil	35	24	0.61	112	0.007	<1	1.43	0.006	0.03	<0.1	0.09	2.2	<0.1	<0.05	4	1.4	0.3
KYS 109255	Soil	32	22	0.81	120	0.007	1	1.60	0.007	0.04	<0.1	0.11	2.2	<0.1	<0.05	5	0.7	0.2
KYS 109256	Soil	33	25	0.68	117	0.006	<1	1.52	0.007	0.03	<0.1	0.10	1.9	<0.1	<0.05	5	1.3	0.2
KYS 109257	Soil	31	29	0.73	122	0.007	1	1.66	0.008	0.03	<0.1	0.11	1.8	<0.1	<0.05	5	1.4	<0.2
KYS 109258	Soil	32	27	0.71	113	0.008	<1	1.71	0.007	0.03	<0.1	0.11	2.1	<0.1	<0.05	5	1.5	<0.2
KYS 109259	Soil	25	29	0.74	138	0.008	<1	1.93	0.007	0.04	<0.1	0.17	2.2	<0.1	<0.05	6	1.1	0.2
KYS 109260	Soil	26	26	0.65	133	0.009	1	1.76	0.009	0.04	<0.1	0.14	1.8	<0.1	<0.05	5	1.0	<0.2
KYS 109261	Soil	33	22	0.63	109	0.007	<1	1.60	0.006	0.04	<0.1	0.10	1.9	<0.1	<0.05	5	0.5	<0.2
KYS 109262	Soil	32	17	0.43	99	0.006	<1	1.08	0.005	0.04	<0.1	0.10	1.9	<0.1	<0.05	4	0.9	0.4
KYS 109263	Soil	29	24	0.69	93	0.009	1	1.29	0.007	0.05	<0.1	0.07	2.4	<0.1	<0.05	4	0.6	0.4
KYS 109264	Soil	30	12	0.40	106	0.007	1	0.92	0.005	0.09	<0.1	0.05	1.6	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109265	Soil	1.9	62.5	32.7	147	0.4	39.6	17.3	1004	3.44	200.4	1.9	17.3	7.1	16	0.5	21.6	0.3	19	0.17	0.070
KYS 109266	Soil	1.7	66.9	24.8	94	0.3	40.6	15.0	1334	3.62	74.8	2.2	10.5	7.4	16	0.3	6.6	0.3	22	0.21	0.108
KYS 109267	Soil	1.6	127.7	23.2	114	0.3	67.0	25.6	3479	3.07	18.1	1.0	29.7	4.9	14	0.2	2.3	0.4	33	0.05	0.081
KYS 109268	Soil	1.6	107.7	23.3	155	0.4	77.8	24.9	2501	3.39	24.3	1.3	17.9	6.9	15	0.3	3.8	0.4	25	0.04	0.070
KYS 109269	Soil	1.7	76.7	18.4	109	0.4	46.9	14.3	1374	3.23	15.2	1.2	17.6	4.8	19	0.2	1.7	0.3	35	0.08	0.085
KYS 109270	Soil	1.5	41.8	14.4	64	0.2	23.5	7.1	556	2.94	13.2	0.9	5.2	1.2	12	0.2	1.2	0.3	39	0.04	0.071
KYS 109271	Soil	1.4	40.3	13.3	66	0.4	24.9	7.3	429	2.82	13.6	0.9	8.2	1.0	10	0.2	1.1	0.3	40	0.05	0.064
KYS 109272	Soil	1.6	62.2	16.3	127	0.4	50.1	16.0	1731	3.06	13.7	1.1	10.2	1.8	11	0.4	1.4	0.3	33	0.04	0.069
KYS 109273	Soil	1.7	48.5	15.6	97	0.2	39.7	14.0	891	3.09	13.9	1.0	6.2	1.1	10	0.5	1.2	0.3	39	0.05	0.070
KYS 109274	Soil	1.7	52.3	25.2	114	0.2	47.5	20.1	1405	3.85	20.3	1.3	4.0	4.1	13	0.3	4.3	0.3	22	0.09	0.065
KYS 109275	Soil	2.6	47.7	22.3	123	0.2	42.2	18.5	1329	3.61	18.4	1.5	4.0	5.5	11	0.3	3.7	0.3	20	0.08	0.098
KYS 109276	Soil	1.5	55.7	26.8	147	0.2	62.2	29.9	2582	3.85	147.5	1.6	18.4	7.2	15	0.5	10.6	0.3	15	0.08	0.060
KYS 109277	Soil	1.6	95.8	20.7	128	0.2	61.2	22.8	3151	3.44	140.2	1.1	20.8	3.2	13	0.3	25.5	0.3	20	0.05	0.065
KYS 109278	Soil	0.9	43.0	20.4	93	0.1	37.7	18.3	1150	3.30	43.6	1.2	4.0	5.5	11	0.2	4.7	0.3	15	0.08	0.060
KYS 109279	Soil	1.0	32.9	19.3	85	0.1	28.1	12.9	888	3.48	85.1	1.0	59.5	2.5	5	0.1	4.4	0.3	21	0.02	0.062
KYS 109280	Soil	1.4	38.0	15.6	92	0.1	32.4	10.9	856	3.04	28.0	1.1	6.4	2.5	8	0.1	3.0	0.2	26	0.05	0.051
KYS 109281	Soil	2.2	42.0	17.7	108	0.3	35.5	12.7	586	3.39	18.2	1.5	7.1	2.6	10	1.1	2.1	0.3	28	0.08	0.088
KYS 109282	Soil	2.6	108.9	15.3	320	0.4	107.7	38.8	1303	5.17	23.0	4.5	4.7	4.9	13	2.6	4.6	0.2	26	0.17	0.063
KYS 109283	Soil	3.0	37.0	18.0	118	0.3	33.3	9.5	441	2.88	21.8	1.6	4.7	3.9	9	0.7	3.1	0.3	28	0.05	0.078
KYS 109284	Soil	4.4	48.2	18.1	154	0.3	49.9	14.8	664	3.22	20.4	2.2	7.1	2.5	11	1.3	2.6	0.3	34	0.08	0.090
KYS 109285	Soil	2.9	54.0	21.6	84	0.6	23.5	5.0	230	3.26	16.1	1.2	12.7	3.0	13	0.2	2.6	0.4	30	0.04	0.082
KYS 109286	Soil	3.1	39.7	25.6	74	0.7	18.6	4.3	227	3.10	18.8	1.0	10.5	4.4	13	0.2	3.2	0.5	28	0.04	0.094
KYS 109287	Soil	6.6	146.3	26.3	134	0.7	47.9	7.5	754	5.19	26.7	1.1	18.2	2.1	19	0.3	3.2	0.4	33	0.02	0.120
KYS 109288	Soil	2.0	18.7	13.2	50	0.1	13.3	4.9	211	2.50	17.4	0.6	4.9	0.8	8	0.2	1.4	0.3	50	0.05	0.058
KYS 109289	Soil	1.8	25.2	13.5	64	0.2	19.2	5.9	201	2.67	16.9	0.7	12.6	1.7	10	0.1	1.8	0.2	37	0.07	0.061
KYS 109290	Soil	8.3	41.0	20.8	77	0.4	19.0	4.6	148	2.81	19.5	1.6	5.3	1.0	8	0.3	3.3	0.3	36	0.04	0.075
KYS 109291	Soil	7.2	29.0	20.1	51	0.5	12.0	2.6	75	2.17	17.5	1.3	7.1	1.0	10	0.2	2.9	0.3	39	0.02	0.078
KYS 109292	Soil	8.2	92.4	34.8	162	1.1	37.9	8.3	948	4.97	25.0	1.9	29.8	2.8	11	0.6	3.5	0.7	40	0.02	0.131
KYS 109293	Soil	9.7	51.1	29.6	101	0.6	26.2	9.1	336	3.62	19.1	1.8	6.3	3.9	15	0.6	4.5	0.4	26	0.02	0.094
KYS 109294	Soil	3.7	73.8	32.3	96	1.1	25.1	5.8	279	4.21	25.3	1.0	13.4	2.5	15	0.4	4.3	0.7	26	0.02	0.109

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109265	Soil	18	17	0.46	90	0.009	1	1.12	0.005	0.06	<0.1	0.05	1.7	<0.1	<0.05	3	0.9	<0.2
KYS 109266	Soil	19	19	0.48	108	0.009	<1	1.18	0.006	0.06	<0.1	0.05	2.0	<0.1	<0.05	3	0.8	<0.2
KYS 109267	Soil	19	21	0.51	94	0.014	1	1.38	0.005	0.03	0.1	0.06	1.9	<0.1	<0.05	4	1.0	<0.2
KYS 109268	Soil	19	17	0.34	79	0.008	<1	1.03	0.004	0.02	<0.1	0.09	2.0	<0.1	<0.05	3	1.4	<0.2
KYS 109269	Soil	18	22	0.41	80	0.017	1	1.26	0.007	0.03	0.3	0.09	1.5	<0.1	<0.05	4	0.9	<0.2
KYS 109270	Soil	13	22	0.28	91	0.014	1	1.06	0.006	0.03	0.2	0.10	0.9	<0.1	0.06	4	1.0	<0.2
KYS 109271	Soil	12	24	0.31	74	0.016	1	1.27	0.006	0.03	0.2	0.07	1.1	<0.1	0.05	4	0.9	<0.2
KYS 109272	Soil	14	20	0.34	87	0.015	<1	1.15	0.004	0.03	0.1	0.06	1.5	<0.1	<0.05	4	1.1	<0.2
KYS 109273	Soil	12	24	0.35	76	0.015	<1	1.33	0.006	0.04	0.1	0.08	1.2	<0.1	<0.05	4	0.7	<0.2
KYS 109274	Soil	19	20	0.49	75	0.006	<1	1.34	0.004	0.05	0.1	0.04	1.4	<0.1	<0.05	4	0.5	<0.2
KYS 109275	Soil	30	20	0.65	75	0.002	<1	1.64	0.004	0.05	<0.1	0.04	1.3	<0.1	<0.05	4	0.6	<0.2
KYS 109276	Soil	28	15	0.44	100	0.003	<1	1.28	0.005	0.05	<0.1	0.04	1.6	<0.1	<0.05	3	0.5	<0.2
KYS 109277	Soil	22	15	0.31	102	0.005	<1	0.88	0.005	0.04	<0.1	0.05	1.5	<0.1	<0.05	3	0.8	<0.2
KYS 109278	Soil	20	16	0.51	76	0.004	<1	1.27	0.005	0.05	<0.1	0.02	1.1	<0.1	<0.05	4	0.5	<0.2
KYS 109279	Soil	18	17	0.43	71	0.006	<1	1.33	0.004	0.05	<0.1	0.03	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109280	Soil	18	19	0.38	79	0.009	<1	1.26	0.004	0.04	<0.1	0.04	1.2	<0.1	<0.05	4	0.6	<0.2
KYS 109281	Soil	14	23	0.34	186	0.020	<1	1.48	0.006	0.05	0.1	0.08	1.5	<0.1	<0.05	3	2.0	<0.2
KYS 109282	Soil	12	50	0.87	174	0.011	<1	1.50	0.005	0.04	<0.1	0.06	3.4	<0.1	<0.05	4	1.3	<0.2
KYS 109283	Soil	14	21	0.33	168	0.014	1	1.05	0.006	0.03	0.1	0.05	1.9	<0.1	<0.05	3	1.2	<0.2
KYS 109284	Soil	14	26	0.36	86	0.018	<1	1.16	0.004	0.05	0.1	0.07	1.7	<0.1	<0.05	3	1.6	<0.2
KYS 109285	Soil	11	20	0.22	88	0.009	<1	0.98	0.005	0.04	0.1	0.08	1.8	<0.1	<0.05	3	1.8	0.2
KYS 109286	Soil	13	18	0.22	83	0.008	<1	0.93	0.007	0.04	0.1	0.11	1.7	<0.1	<0.05	3	2.3	<0.2
KYS 109287	Soil	6	16	0.22	120	0.005	<1	0.84	0.004	0.04	<0.1	0.15	1.8	<0.1	0.09	3	4.0	<0.2
KYS 109288	Soil	10	22	0.22	77	0.026	<1	1.15	0.005	0.04	0.2	0.06	1.2	<0.1	<0.05	5	0.9	<0.2
KYS 109289	Soil	11	21	0.30	103	0.021	<1	1.24	0.005	0.03	0.1	0.06	1.7	<0.1	<0.05	4	1.1	<0.2
KYS 109290	Soil	13	17	0.23	242	0.011	<1	0.99	0.005	0.04	0.1	0.11	1.1	0.1	<0.05	3	2.4	<0.2
KYS 109291	Soil	15	13	0.14	276	0.008	<1	0.68	0.004	0.04	0.1	0.09	0.6	0.1	0.06	3	2.5	<0.2
KYS 109292	Soil	12	22	0.29	185	0.003	<1	1.26	0.006	0.04	<0.1	0.14	1.9	<0.1	0.09	4	4.2	0.2
KYS 109293	Soil	16	13	0.26	1602	0.004	<1	0.96	0.005	0.06	<0.1	0.13	1.2	0.1	0.14	3	3.6	<0.2
KYS 109294	Soil	12	18	0.18	172	0.002	<1	0.82	0.005	0.03	<0.1	0.10	1.5	<0.1	0.09	3	4.0	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109295	Soil	4.3	84.0	40.7	99	1.0	25.6	6.1	244	4.77	29.5	1.1	12.1	3.4	17	0.2	4.9	1.0	28	0.02	0.120
KYS 109296	Soil	8.6	60.6	32.1	171	0.7	51.2	12.7	369	4.21	17.8	3.4	9.3	4.4	19	1.4	3.7	0.4	25	0.06	0.083
KYS 109297	Soil	11.1	53.6	28.8	154	1.0	41.6	13.5	363	3.57	22.5	2.5	5.3	3.9	44	0.8	4.8	0.3	23	0.06	0.088
KYS 109298	Soil	11.2	52.4	27.0	154	0.9	38.1	12.4	324	3.36	23.2	2.5	6.4	3.5	43	0.9	4.9	0.3	23	0.05	0.095
KYS 109299	Soil	1.7	18.4	12.4	55	<0.1	18.3	6.4	238	3.20	18.2	0.6	2.5	3.3	7	0.2	2.0	0.3	65	0.05	0.028
KYS 109300	Soil	1.1	24.2	20.8	71	<0.1	22.5	13.7	694	2.68	26.6	0.9	1.2	2.3	8	0.3	1.3	0.2	30	0.07	0.066
KYS 109301	Soil	0.6	49.8	35.0	92	0.1	35.0	16.0	610	4.53	9.9	3.8	4.7	3.6	17	0.2	1.2	0.7	11	0.15	0.058
KYS 109302	Soil	0.8	50.1	33.1	106	0.1	43.5	24.0	863	4.23	33.8	2.6	4.0	6.9	10	0.3	3.3	0.5	9	0.10	0.036
KYS 109303	Soil	0.4	41.4	27.4	82	<0.1	33.0	18.4	714	3.76	78.8	2.1	6.3	10.4	17	<0.1	5.4	0.4	5	0.16	0.042
KYS 109304	Soil	0.3	42.5	37.5	87	0.1	34.4	15.5	576	3.41	97.0	1.8	7.4	15.5	22	<0.1	4.7	0.4	9	0.37	0.041
KYS 109305	Soil	1.1	56.6	35.2	108	0.2	44.9	20.8	834	4.62	102.5	2.3	15.2	17.9	23	0.2	11.8	0.5	7	0.29	0.046
KYS 109306	Soil	0.4	33.6	22.6	65	<0.1	26.7	13.5	440	3.23	27.3	1.8	3.3	7.7	12	<0.1	3.1	0.3	6	0.14	0.030
KYS 109307	Soil	1.2	35.7	27.7	70	0.1	27.1	12.5	487	3.25	16.7	2.0	3.1	6.1	13	<0.1	2.1	0.4	9	0.13	0.031
KYS 109308	Soil	2.3	36.0	22.2	88	0.2	33.4	13.1	512	3.43	23.9	2.1	<0.5	6.5	16	0.3	4.6	0.3	10	0.11	0.044
KYS 109309	Soil	3.8	43.4	31.4	105	0.2	34.6	14.8	546	3.82	11.8	2.5	2.2	4.6	31	0.5	2.7	0.4	7	0.15	0.061
KYS 109310	Soil	2.4	39.3	29.2	97	0.2	35.8	16.0	642	3.48	9.1	2.3	4.7	3.8	20	0.4	2.0	0.4	11	0.13	0.047
KYS 109311	Soil	2.6	36.2	26.0	97	0.2	32.2	11.2	510	3.78	17.8	2.5	3.1	2.3	19	0.7	3.0	0.3	11	0.30	0.066
KYS 109312	Soil	3.1	52.1	27.1	134	0.2	46.6	17.1	791	3.98	8.3	3.1	2.1	5.0	21	1.2	2.5	0.3	8	0.19	0.075
KYS 109313	Soil	8.9	28.8	26.3	101	0.3	24.0	8.8	362	2.86	14.0	2.1	2.0	2.8	29	0.5	3.4	0.4	17	0.19	0.064
KYS 109314	Soil	5.7	43.3	23.1	86	0.3	26.9	8.2	316	2.88	9.8	2.3	6.6	1.3	26	0.5	2.3	0.3	28	0.05	0.061
KYS 109315	Soil	6.6	91.8	22.4	98	0.4	28.4	7.1	446	3.39	10.4	2.7	10.3	1.1	170	0.4	2.8	0.3	22	0.05	0.098
KYS 109316	Soil	2.6	84.4	14.0	81	0.2	23.9	7.1	650	2.87	8.8	1.7	15.1	0.7	32	0.2	2.3	0.2	37	0.06	0.075
KYS 109317	Soil	2.4	119.2	23.1	100	0.3	34.9	10.4	604	3.26	20.5	1.8	21.8	3.6	26	0.3	3.4	0.3	33	0.10	0.084
KYS 109318	Soil	1.7	79.8	15.4	79	0.2	26.7	11.2	705	2.98	15.1	1.1	12.9	2.1	16	0.4	1.9	0.3	45	0.07	0.059
KYS 109319	Soil	2.7	191.9	23.7	105	0.3	55.0	18.6	2045	3.43	17.3	1.8	26.3	2.1	27	0.3	1.8	0.3	41	0.07	0.079
KYS 109320	Soil	1.8	144.4	22.0	100	0.2	39.3	12.5	945	3.39	17.6	1.6	16.9	1.8	14	0.3	2.2	0.3	48	0.06	0.078
KYS 109321	Soil	2.7	113.6	21.6	98	0.2	32.0	11.2	830	3.24	17.3	1.5	20.6	2.7	16	0.4	5.4	0.3	39	0.07	0.076
KYS 109322	Soil	4.2	74.0	19.3	75	0.3	19.6	5.9	295	3.46	103.9	1.1	30.5	1.8	15	0.1	13.7	0.3	41	0.05	0.064
KYS 109323	Soil	1.2	45.9	29.3	128	0.1	46.7	21.5	1056	4.05	145.0	1.1	31.0	6.0	8	0.2	39.5	0.4	14	0.08	0.053
KYS 109324	Soil	1.4	17.0	18.2	54	<0.1	20.7	8.8	352	2.59	12.3	0.7	2.3	1.9	8	<0.1	1.6	0.3	45	0.06	0.035

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109295	Soil	12	19	0.20	179	<0.001	<1	0.91	0.005	0.03	<0.1	0.12	1.9	<0.1	<0.05	4	4.4	0.3
KYS 109296	Soil	18	16	0.29	581	0.004	<1	0.94	0.007	0.05	<0.1	0.17	1.5	<0.1	0.09	3	3.0	<0.2
KYS 109297	Soil	17	15	0.28	1467	0.003	<1	0.73	0.004	0.05	<0.1	0.28	1.3	0.1	0.09	2	5.9	<0.2
KYS 109298	Soil	16	14	0.28	1225	0.003	<1	0.75	0.004	0.05	<0.1	0.21	1.2	0.1	0.12	2	5.4	0.2
KYS 109299	Soil	13	41	0.35	86	0.026	<1	1.69	0.004	0.04	0.2	0.03	2.4	0.2	<0.05	7	0.5	<0.2
KYS 109300	Soil	15	17	0.25	102	0.016	<1	0.90	0.006	0.10	0.1	0.03	1.2	<0.1	<0.05	4	0.6	<0.2
KYS 109301	Soil	10	12	0.43	64	0.003	<1	0.97	0.006	0.06	<0.1	0.03	1.5	<0.1	0.06	3	0.6	<0.2
KYS 109302	Soil	12	11	0.49	33	0.003	<1	1.05	0.006	0.05	<0.1	0.03	1.3	<0.1	<0.05	2	0.5	0.5
KYS 109303	Soil	16	7	0.29	30	0.002	1	0.64	0.004	0.08	<0.1	0.02	1.6	<0.1	<0.05	1	<0.5	<0.2
KYS 109304	Soil	19	12	0.56	38	0.002	<1	1.10	0.004	0.08	<0.1	0.01	1.3	<0.1	<0.05	3	<0.5	0.3
KYS 109305	Soil	21	8	0.37	41	0.002	<1	0.81	0.005	0.07	<0.1	0.02	2.1	<0.1	0.05	2	1.1	<0.2
KYS 109306	Soil	13	8	0.33	25	0.002	<1	0.71	0.004	0.06	<0.1	0.02	1.3	<0.1	<0.05	2	0.7	<0.2
KYS 109307	Soil	12	9	0.34	36	0.002	<1	0.79	0.005	0.06	<0.1	0.02	1.1	<0.1	<0.05	2	<0.5	<0.2
KYS 109308	Soil	15	9	0.35	44	0.004	<1	0.82	0.005	0.04	<0.1	0.04	1.3	<0.1	<0.05	2	1.3	<0.2
KYS 109309	Soil	10	8	0.27	53	0.002	<1	0.68	0.012	0.05	<0.1	0.05	1.2	<0.1	0.07	1	2.0	0.5
KYS 109310	Soil	11	11	0.36	63	0.004	<1	0.92	0.004	0.04	<0.1	0.04	1.5	<0.1	<0.05	2	0.8	0.3
KYS 109311	Soil	6	7	0.24	52	0.002	1	0.66	0.005	0.03	<0.1	0.08	1.3	<0.1	<0.05	1	2.6	<0.2
KYS 109312	Soil	11	8	0.34	40	0.002	<1	0.73	0.005	0.03	<0.1	0.06	1.8	<0.1	<0.05	2	2.1	<0.2
KYS 109313	Soil	12	10	0.30	76	0.003	1	0.76	0.004	0.03	<0.1	0.14	1.0	<0.1	<0.05	2	0.8	0.3
KYS 109314	Soil	14	14	0.30	97	0.010	1	0.97	0.005	0.04	0.1	0.09	0.9	<0.1	<0.05	3	1.1	0.3
KYS 109315	Soil	12	13	0.21	518	0.008	<1	0.68	0.012	0.05	<0.1	0.12	0.8	<0.1	0.13	2	1.2	0.3
KYS 109316	Soil	13	19	0.22	317	0.015	2	0.88	0.005	0.04	0.1	0.09	0.8	<0.1	0.05	3	0.9	<0.2
KYS 109317	Soil	18	19	0.49	221	0.020	2	1.23	0.006	0.05	0.2	0.10	1.3	<0.1	<0.05	3	1.4	0.6
KYS 109318	Soil	16	23	0.43	188	0.024	<1	1.31	0.006	0.05	0.2	0.09	1.5	<0.1	<0.05	4	0.7	<0.2
KYS 109319	Soil	17	23	0.60	282	0.015	<1	1.55	0.005	0.05	0.2	0.12	1.5	<0.1	<0.05	4	0.6	0.3
KYS 109320	Soil	16	26	0.58	244	0.015	2	1.65	0.005	0.04	0.1	0.09	1.4	<0.1	<0.05	5	<0.5	0.5
KYS 109321	Soil	18	22	0.52	167	0.016	<1	1.28	0.004	0.04	0.2	0.08	1.3	<0.1	<0.05	4	1.0	0.5
KYS 109322	Soil	19	19	0.32	174	0.016	2	1.17	0.005	0.04	0.2	0.11	1.1	<0.1	<0.05	4	1.7	<0.2
KYS 109323	Soil	20	10	0.37	83	0.004	2	0.96	0.001	0.03	<0.1	0.03	1.6	<0.1	<0.05	3	0.5	0.5
KYS 109324	Soil	12	19	0.31	86	0.019	1	1.26	0.005	0.05	0.2	0.05	1.4	0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109325	Soil		2.1	33.5	21.7	75	<0.1	28.6	10.4	415	3.14	16.8	1.1	3.0	2.5	9	<0.1	3.3	0.3	39	0.06	0.039
KYS 109326	Soil		1.9	39.5	18.6	65	0.1	21.0	7.6	376	2.96	12.3	0.7	6.1	2.8	10	0.2	1.9	0.3	46	0.05	0.035
KYS 109327	Soil		2.6	70.4	17.7	67	0.3	23.6	9.4	868	3.13	14.4	1.0	10.4	0.8	19	0.2	2.4	0.3	43	0.05	0.082
KYS 109328	Soil		1.6	73.6	17.7	60	<0.1	20.2	9.6	775	2.93	13.2	0.9	4.5	1.0	10	<0.1	2.1	0.3	48	0.05	0.051
KYS 109329	Soil		40.2	43.1	51.9	72	0.7	19.7	6.2	388	3.55	10.8	1.7	18.7	6.9	177	0.3	14.4	0.6	48	0.03	0.059
KYS 109330	Soil		44.0	38.4	54.5	64	0.7	16.6	5.4	344	3.57	9.8	1.7	16.0	7.2	182	0.2	14.8	0.7	52	0.02	0.059
KYS 109331	Soil		2.9	79.7	22.0	65	0.1	25.4	7.3	327	2.77	15.2	1.4	20.3	0.7	20	0.1	2.8	0.4	37	0.04	0.071
KYS 109332	Soil		1.6	72.5	14.8	84	<0.1	36.5	11.8	1178	2.95	25.2	1.1	24.7	2.8	16	0.3	2.3	0.3	44	0.11	0.078
KYS 109333	Soil		1.6	77.8	15.7	93	0.1	38.2	12.7	1465	2.99	17.8	1.0	12.4	2.1	13	0.2	2.7	0.2	46	0.09	0.080
KYS 109334	Soil		1.5	29.4	31.3	121	0.2	32.8	11.7	667	3.29	37.6	1.9	5.3	4.3	28	0.8	6.4	0.3	13	0.44	0.058
KYS 109335	Soil		0.7	33.6	22.8	88	0.1	32.6	11.1	526	3.22	50.8	1.6	9.1	9.2	14	0.5	7.1	0.3	8	0.21	0.039
KYS 109336	Soil		1.0	40.4	27.9	83	<0.1	35.9	16.0	692	3.69	41.6	2.0	7.2	11.3	15	0.1	5.3	0.4	6	0.18	0.044
KYS 109337	Soil		2.4	34.8	22.7	85	0.1	30.1	14.1	506	3.31	18.2	1.9	2.6	6.2	14	0.3	3.1	0.3	8	0.12	0.038
KYS 109338	Soil		6.1	17.3	20.5	55	0.2	15.5	4.3	155	2.16	14.0	1.2	2.7	1.9	29	0.3	2.7	0.3	7	0.05	0.038
KYS 109339	Soil		2.5	121.8	19.0	107	0.3	38.2	12.4	635	3.22	6.8	1.9	13.6	2.6	21	0.4	1.1	0.3	12	0.05	0.059
KYS 109340	Soil		2.6	65.7	11.6	45	0.5	13.5	4.1	299	2.51	15.7	0.8	58.1	0.7	11	0.1	1.6	0.2	28	0.03	0.060
KYS 109341	Soil		7.8	43.1	19.5	73	0.3	19.4	6.7	326	2.86	14.8	2.0	7.8	1.4	49	0.2	2.6	0.3	17	0.12	0.078
KYS 109342	Soil		8.8	35.5	21.0	73	0.1	22.1	8.3	396	2.72	18.7	2.5	4.3	2.1	19	0.2	3.2	0.3	17	0.06	0.061
KYS 109343	Soil		5.2	63.2	19.6	94	0.2	31.7	10.7	641	2.92	14.8	2.0	8.0	3.4	18	0.6	4.0	0.2	16	0.11	0.063
KYS 109344	Soil		4.8	66.7	20.5	97	0.2	32.9	10.3	637	2.84	14.9	2.1	7.6	3.6	18	0.5	4.1	0.3	16	0.11	0.063
KYS 109345	Soil		4.3	57.9	11.7	60	0.2	21.0	6.1	445	1.75	10.5	0.6	9.6	0.7	13	0.3	7.1	0.2	26	0.02	0.051
KYS 109346	Soil		2.7	204.7	26.9	94	0.3	27.8	8.3	572	3.67	19.6	1.7	23.3	6.5	31	0.3	5.1	0.4	29	0.05	0.069
KYS 109347	Soil		2.2	80.7	14.5	61	0.2	21.1	8.1	307	2.80	12.7	1.0	10.3	2.7	13	0.3	1.6	0.3	38	0.05	0.056
KYS 109348	Soil		4.1	176.2	27.2	117	0.3	44.9	12.2	1107	3.87	18.5	1.8	25.1	1.3	28	0.3	2.2	0.4	37	0.06	0.093
KYS 109349	Soil		7.3	135.5	22.9	204	0.5	64.2	16.3	1456	3.53	9.6	2.5	23.8	6.8	31	2.5	2.4	0.3	27	0.09	0.084
KYS 109350	Soil		16.9	91.5	24.1	177	0.9	43.1	8.3	641	2.54	23.3	3.9	8.6	4.9	96	1.1	4.9	0.3	33	0.10	0.095
KYS 109351	Soil		3.8	63.5	15.2	128	0.3	37.4	10.1	640	2.76	12.1	1.6	30.9	1.8	14	1.1	2.3	0.2	34	0.07	0.063
KYS 109352	Soil		3.2	58.5	20.0	136	0.2	42.9	15.1	797	3.31	29.7	1.6	9.1	6.3	16	1.3	8.2	0.3	28	0.16	0.074
KYS 109353	Soil		2.3	55.9	24.0	113	0.2	38.9	14.2	600	3.78	146.6	1.5	24.1	7.1	20	0.3	28.3	0.3	16	0.21	0.095
KYS 109354	Soil		2.6	124.7	27.0	111	0.3	54.4	21.4	1668	3.81	330.7	1.3	49.7	7.5	16	0.3	226.7	0.3	21	0.10	0.055

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109325	Soil	14	20	0.37	69	0.020	<1	1.33	0.006	0.05	0.2	0.06	1.4	0.1	<0.05	4	0.7	<0.2
KYS 109326	Soil	15	18	0.30	87	0.020	<1	1.09	0.005	0.04	0.2	0.05	1.2	<0.1	<0.05	5	0.6	0.3
KYS 109327	Soil	16	17	0.27	106	0.016	2	0.82	0.005	0.05	0.1	0.12	0.6	<0.1	0.06	4	1.1	0.5
KYS 109328	Soil	17	20	0.30	106	0.017	1	1.18	0.005	0.05	0.1	0.08	0.9	0.1	<0.05	5	<0.5	<0.2
KYS 109329	Soil	23	13	0.12	530	0.015	<1	0.52	0.012	0.28	0.2	0.42	1.1	0.1	0.53	3	1.9	0.8
KYS 109330	Soil	24	12	0.11	453	0.015	2	0.50	0.013	0.30	0.2	0.46	1.2	0.1	0.61	3	2.2	0.6
KYS 109331	Soil	18	16	0.23	118	0.007	<1	1.03	0.005	0.04	0.1	0.07	0.8	<0.1	0.06	4	0.7	0.6
KYS 109332	Soil	22	25	0.55	111	0.029	2	1.50	0.006	0.04	0.1	0.05	2.1	<0.1	<0.05	5	<0.5	<0.2
KYS 109333	Soil	21	23	0.56	151	0.023	1	1.50	0.006	0.05	<0.1	0.06	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109334	Soil	13	11	0.30	70	0.005	1	0.81	0.006	0.05	<0.1	0.04	1.5	<0.1	0.06	2	0.9	<0.2
KYS 109335	Soil	20	9	0.32	41	0.002	1	0.76	0.004	0.05	<0.1	0.03	1.4	<0.1	<0.05	2	0.5	<0.2
KYS 109336	Soil	23	8	0.31	35	0.002	<1	0.74	0.005	0.06	<0.1	0.03	1.5	<0.1	<0.05	2	<0.5	<0.2
KYS 109337	Soil	13	11	0.40	37	0.002	<1	0.95	0.004	0.05	<0.1	0.03	1.3	<0.1	<0.05	3	1.2	<0.2
KYS 109338	Soil	7	5	0.06	59	0.002	<1	0.28	0.005	0.04	<0.1	0.11	0.7	<0.1	0.06	<1	1.0	<0.2
KYS 109339	Soil	13	12	0.33	117	0.004	<1	0.75	0.004	0.04	<0.1	0.06	0.8	<0.1	<0.05	2	1.3	<0.2
KYS 109340	Soil	11	12	0.13	178	0.008	<1	0.59	0.004	0.04	0.1	0.10	0.6	<0.1	<0.05	3	1.2	<0.2
KYS 109341	Soil	7	10	0.18	156	0.005	3	0.66	0.011	0.04	<0.1	0.12	1.1	<0.1	0.10	2	2.2	<0.2
KYS 109342	Soil	11	9	0.19	284	0.004	35	0.78	0.004	0.04	<0.1	0.14	1.1	<0.1	<0.05	2	1.9	<0.2
KYS 109343	Soil	14	11	0.25	161	0.005	<1	0.79	0.004	0.03	<0.1	0.07	1.5	<0.1	<0.05	2	1.3	<0.2
KYS 109344	Soil	15	11	0.28	173	0.006	<1	0.82	0.004	0.04	0.1	0.07	1.5	<0.1	<0.05	2	1.2	<0.2
KYS 109345	Soil	12	7	0.04	114	0.008	<1	0.32	0.003	0.03	0.1	0.05	0.4	<0.1	<0.05	2	1.0	0.2
KYS 109346	Soil	25	21	0.59	234	0.007	<1	1.33	0.007	0.04	<0.1	0.11	1.4	<0.1	<0.05	3	1.8	0.7
KYS 109347	Soil	16	21	0.29	129	0.019	<1	1.26	0.004	0.04	0.2	0.07	1.3	<0.1	<0.05	4	1.2	0.4
KYS 109348	Soil	17	25	0.59	334	0.009	1	1.70	0.007	0.06	0.2	0.13	1.1	<0.1	<0.05	5	1.2	0.5
KYS 109349	Soil	23	17	0.46	232	0.012	<1	1.04	0.005	0.03	0.1	0.27	1.8	<0.1	<0.05	3	2.1	0.3
KYS 109350	Soil	26	11	0.28	240	0.008	<1	0.73	0.007	0.05	0.1	0.60	1.1	0.1	0.05	2	3.8	<0.2
KYS 109351	Soil	16	19	0.35	173	0.016	<1	1.13	0.004	0.04	0.1	0.13	1.4	<0.1	<0.05	4	1.0	<0.2
KYS 109352	Soil	22	17	0.43	175	0.018	<1	1.17	0.005	0.05	0.1	0.09	2.2	<0.1	<0.05	3	1.2	0.3
KYS 109353	Soil	24	14	0.49	114	0.004	1	1.23	0.004	0.06	<0.1	0.07	2.2	<0.1	<0.05	3	0.7	<0.2
KYS 109354	Soil	27	15	0.55	143	0.006	<1	1.25	0.004	0.05	<0.1	0.06	1.5	<0.1	<0.05	4	0.9	0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109355	Soil	2.6	121.9	27.1	113	0.3	52.5	20.4	1695	3.76	338.4	1.3	56.9	7.5	16	0.3	222.4	0.4	22	0.11	0.055
KYS 109356	Soil	1.2	116.5	28.2	107	1.0	50.5	22.2	2191	3.71	1220	1.2	354.0	11.3	28	0.3	172.6	0.3	11	0.19	0.053
KYS 109357	Soil	1.6	91.7	17.1	73	0.3	32.0	13.2	863	2.88	39.7	1.0	22.2	4.2	15	0.3	14.7	0.2	42	0.06	0.040
KYS 109358	Soil	1.4	46.5	10.8	50	0.4	14.0	4.4	422	2.02	14.7	0.5	8.6	0.7	9	0.1	4.3	0.3	44	0.05	0.065
KYS 109359	Soil	1.1	174.4	18.6	111	0.3	56.3	20.8	791	2.87	42.1	1.3	43.2	5.6	15	0.4	12.3	0.2	34	0.12	0.070
KYS 109361	Soil	1.1	148.8	18.4	94	0.2	45.5	17.6	928	2.87	17.9	0.9	31.5	3.8	15	0.3	7.0	0.3	38	0.11	0.068
KYS 109362	Soil	1.6	79.9	16.1	65	0.2	26.8	11.5	1019	2.74	17.4	0.8	18.3	0.9	11	0.2	4.3	0.3	45	0.06	0.078
KYS 109363	Soil	2.0	130.7	27.6	136	0.3	72.3	27.1	4113	3.83	33.8	1.2	31.9	5.9	19	0.3	5.8	0.4	37	0.07	0.096
KYS 109364	Soil	2.6	120.9	27.9	132	0.3	64.9	24.7	3313	4.13	26.7	1.2	28.9	5.4	17	0.3	4.3	0.4	44	0.09	0.101
KYS 109365	Soil	1.8	114.2	22.2	133	0.2	70.8	24.7	3530	3.54	37.2	1.1	38.0	6.5	18	0.3	9.4	0.3	31	0.11	0.082
KYS 109366	Soil	6.1	68.4	29.4	130	0.3	44.7	16.2	646	4.12	137.5	2.0	18.9	8.7	33	0.8	62.0	0.4	12	0.30	0.078
KYS 109367	Soil	6.6	46.8	28.4	136	0.2	41.7	14.8	526	3.49	21.8	3.3	4.7	6.6	19	1.2	7.4	0.4	11	0.09	0.050
KYS 109368	Soil	0.6	37.2	23.5	79	0.1	30.7	14.5	610	3.89	85.1	1.9	9.5	9.8	25	0.1	4.4	0.3	5	0.60	0.041
KYS 109369	Soil	1.3	37.5	21.1	84	0.2	28.3	13.4	613	3.47	118.4	2.1	9.3	4.4	28	0.3	5.5	0.3	8	0.54	0.063
KYS 109370	Soil	1.5	53.2	29.2	105	0.2	37.9	17.7	728	4.15	67.4	2.0	14.4	8.8	17	0.3	11.3	0.4	11	0.22	0.059
KYS 109371	Soil	1.7	50.3	23.7	112	0.2	34.0	15.5	712	3.77	12.7	2.6	3.5	4.8	29	0.5	2.3	0.3	10	0.43	0.071
KYS 109372	Soil	1.7	53.0	23.2	113	0.2	40.9	16.6	669	3.89	28.7	2.2	6.1	8.0	16	0.7	3.8	0.3	11	0.21	0.067
KYS 109373	Soil	4.8	100.7	21.6	78	0.6	21.6	5.8	540	3.73	9.4	1.5	33.2	1.7	76	0.2	3.0	0.3	20	0.02	0.094
KYS 109374	Soil	1.6	175.6	23.4	95	0.4	36.4	19.3	1832	3.00	17.2	1.3	13.8	2.5	11	0.3	2.8	0.3	27	0.02	0.062
KYS 109375	Soil	1.2	214.4	19.0	85	0.3	52.0	18.4	1020	2.84	14.4	1.2	23.0	3.3	15	0.3	2.5	0.2	33	0.09	0.065
KYS 109376	Soil	2.7	131.0	18.4	89	0.3	33.7	9.5	624	3.23	13.2	1.5	47.9	1.9	18	0.2	3.3	0.3	30	0.07	0.086
KYS 109377	Soil	2.1	128.4	18.8	100	0.2	38.4	13.8	839	3.02	14.4	1.4	56.5	4.3	14	0.3	2.4	0.3	30	0.05	0.057
KYS 109378	Soil	3.5	79.1	16.6	73	0.3	22.9	6.8	439	2.78	24.3	1.0	12.5	0.9	15	0.2	4.7	0.3	30	0.04	0.068
KYS 109379	Soil	6.1	115.5	26.4	93	0.3	26.0	10.4	793	3.68	19.7	1.8	39.6	1.3	23	0.3	3.7	0.4	32	0.05	0.093
KYS 109380	Soil	8.3	123.6	22.2	88	0.5	18.8	3.8	225	4.05	8.4	2.0	15.9	8.7	58	<0.1	3.4	0.4	19	0.01	0.091
KYS 109381	Soil	4.3	101.0	18.7	101	0.4	33.8	14.4	1084	3.20	13.7	2.0	19.2	1.6	16	0.5	1.8	0.3	37	0.06	0.073
KYS 109382	Soil	6.1	70.5	19.5	93	0.4	23.9	6.0	432	3.74	15.2	1.2	9.9	0.2	14	0.6	2.0	0.4	46	0.04	0.100
KYS 109383	Soil	0.5	44.9	36.8	81	0.2	35.4	18.1	879	3.44	10.0	1.6	42.2	16.5	13	0.1	0.6	0.4	13	0.16	0.035
KYS 109384	Soil	1.3	53.6	25.7	81	0.3	31.7	12.7	682	3.22	10.6	1.9	12.5	9.4	21	0.2	0.7	0.4	14	0.31	0.070
KYS 109385	Soil	1.5	37.9	19.1	76	<0.1	26.6	12.2	749	2.87	11.7	1.2	3.5	8.7	13	0.3	1.1	0.2	21	0.15	0.060

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109355	Soil	26	16	0.56	148	0.004	<1	1.24	0.003	0.05	<0.1	0.05	1.5	<0.1	<0.05	4	0.9	<0.2
KYS 109356	Soil	23	8	0.22	82	0.002	<1	0.59	0.003	0.06	0.3	0.11	2.6	<0.1	<0.05	2	<0.5	0.4
KYS 109357	Soil	20	22	0.35	84	0.029	<1	1.12	0.004	0.04	0.3	0.08	1.6	<0.1	<0.05	4	0.7	0.5
KYS 109358	Soil	15	16	0.21	87	0.018	1	0.77	0.004	0.05	0.1	0.08	0.9	<0.1	<0.05	5	<0.5	0.2
KYS 109359	Soil	20	19	0.45	289	0.025	<1	1.20	0.005	0.04	0.1	0.08	1.8	<0.1	<0.05	3	<0.5	0.4
KYS 109361	Soil	22	22	0.55	132	0.019	<1	1.30	0.004	0.04	0.2	0.07	1.6	<0.1	<0.05	4	0.7	0.6
KYS 109362	Soil	17	23	0.36	116	0.018	1	1.19	0.007	0.04	0.2	0.08	1.1	<0.1	<0.05	5	0.7	0.3
KYS 109363	Soil	31	24	0.59	130	0.017	<1	1.61	0.007	0.04	<0.1	0.07	2.4	<0.1	<0.05	5	1.2	<0.2
KYS 109364	Soil	28	35	0.66	136	0.020	1	1.76	0.008	0.05	<0.1	0.08	2.6	<0.1	<0.05	6	1.2	<0.2
KYS 109365	Soil	29	20	0.43	162	0.018	<1	1.16	0.006	0.04	0.1	0.05	2.5	<0.1	<0.05	4	1.1	0.2
KYS 109366	Soil	24	9	0.32	89	0.001	<1	0.92	0.004	0.06	<0.1	0.08	1.9	<0.1	<0.05	2	1.8	<0.2
KYS 109367	Soil	20	10	0.32	74	0.002	<1	0.88	0.004	0.05	<0.1	0.06	1.7	<0.1	<0.05	2	1.4	<0.2
KYS 109368	Soil	19	8	0.43	40	0.002	<1	0.69	0.004	0.06	<0.1	0.02	1.7	<0.1	<0.05	2	<0.5	<0.2
KYS 109369	Soil	10	9	0.36	58	0.002	1	0.79	0.005	0.04	<0.1	0.03	1.5	<0.1	0.05	2	0.8	<0.2
KYS 109370	Soil	19	11	0.40	72	0.003	1	0.97	0.004	0.06	<0.1	0.03	1.9	<0.1	<0.05	3	1.2	<0.2
KYS 109371	Soil	11	10	0.39	46	0.003	<1	0.81	0.004	0.04	<0.1	0.05	1.7	<0.1	<0.05	2	1.2	<0.2
KYS 109372	Soil	18	11	0.38	52	0.002	<1	0.92	0.005	0.06	<0.1	0.03	1.8	<0.1	<0.05	3	0.7	<0.2
KYS 109373	Soil	19	13	0.14	350	0.009	<1	0.66	0.004	0.06	<0.1	0.11	0.8	<0.1	0.08	2	1.8	0.3
KYS 109374	Soil	14	15	0.44	175	0.008	2	1.10	0.004	0.04	<0.1	0.10	0.8	<0.1	0.05	3	0.5	0.2
KYS 109375	Soil	16	20	0.47	114	0.019	1	1.23	0.003	0.04	0.2	0.13	1.1	<0.1	<0.05	3	0.6	<0.2
KYS 109376	Soil	14	18	0.27	118	0.015	1	1.10	0.004	0.04	0.2	0.11	1.0	<0.1	0.06	3	0.9	0.3
KYS 109377	Soil	15	18	0.42	155	0.015	1	1.19	0.004	0.03	0.1	0.06	1.2	<0.1	<0.05	3	0.6	0.6
KYS 109378	Soil	13	16	0.27	131	0.014	1	0.91	0.005	0.04	0.2	0.06	0.6	<0.1	<0.05	3	0.7	0.6
KYS 109379	Soil	16	18	0.33	275	0.013	1	1.13	0.005	0.05	0.1	0.09	0.9	<0.1	<0.05	4	1.9	<0.2
KYS 109380	Soil	26	12	0.17	256	0.004	<1	0.61	0.009	0.05	<0.1	0.24	0.9	<0.1	0.11	2	3.1	0.3
KYS 109381	Soil	18	19	0.35	186	0.014	1	1.14	0.004	0.04	0.2	0.09	0.9	<0.1	<0.05	4	1.4	0.7
KYS 109382	Soil	14	22	0.27	162	0.011	<1	1.03	0.004	0.04	0.1	0.09	0.3	<0.1	0.05	5	1.3	<0.2
KYS 109383	Soil	30	13	0.55	61	0.007	1	1.23	0.004	0.06	<0.1	0.06	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109384	Soil	25	14	0.55	101	0.005	1	1.29	0.005	0.06	<0.1	0.09	1.6	<0.1	<0.05	4	0.6	<0.2
KYS 109385	Soil	20	14	0.43	109	0.014	1	0.98	0.004	0.04	<0.1	0.03	1.3	<0.1	<0.05	3	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109386	Soil		2.6	56.2	24.1	122	0.3	39.5	14.8	938	3.53	201.0	1.4	39.9	4.8	16	0.5	38.7	0.3	21	0.19	0.082
KYS 109387	Soil		2.5	55.6	23.5	123	0.3	39.8	14.5	894	3.58	209.2	1.4	38.6	4.5	16	0.5	41.1	0.3	21	0.18	0.081
KYS 109388	Soil		1.6	52.9	27.3	97	0.2	34.9	14.0	540	3.63	137.9	1.6	22.8	5.4	18	0.3	58.2	0.3	19	0.19	0.067
KYS 109389	Soil		1.2	80.6	25.8	96	0.3	40.4	15.7	1112	3.53	388.8	1.2	86.5	8.2	17	0.2	178.0	0.3	21	0.18	0.058
KYS 109390	Soil		1.0	91.7	28.8	111	0.5	37.8	14.7	794	3.93	841.4	1.3	155.0	9.4	17	0.1	93.0	0.4	9	0.20	0.059
KYS 109391	Soil		1.4	172.4	22.4	94	0.2	47.4	16.8	1208	3.54	163.7	0.9	43.2	4.8	12	<0.1	36.7	0.3	35	0.05	0.053
KYS 109392	Soil		1.8	134.4	22.8	97	0.2	44.3	17.9	1286	3.59	146.8	1.1	38.3	2.1	11	0.2	33.4	0.4	47	0.05	0.084
KYS 109393	Soil		2.3	65.4	14.7	57	0.3	18.2	6.7	437	2.49	22.4	0.8	18.3	0.7	12	0.2	8.0	0.3	37	0.04	0.063
KYS 109394	Soil		19.0	147.2	33.0	305	1.1	66.4	16.2	734	3.69	30.7	4.6	12.1	11.9	72	2.4	26.8	0.4	34	0.16	0.126
KYS 109395	Soil		10.8	109.1	24.4	120	0.7	35.6	8.6	503	3.08	24.0	2.2	17.8	1.3	39	0.5	8.2	0.4	53	0.18	0.095
KYS 109396	Soil		4.4	78.1	23.8	113	0.3	48.3	18.0	1312	3.70	13.3	1.2	12.5	5.3	19	0.4	5.4	0.3	32	0.15	0.085
KYS 109399	Soil		0.4	41.3	28.0	70	<0.1	32.3	15.6	460	3.81	10.8	2.4	1.9	6.1	15	<0.1	1.5	0.4	4	0.19	0.035
KYS 109400	Soil		28.0	43.6	35.8	125	0.5	27.7	10.5	316	3.17	77.7	1.7	1.6	5.4	37	0.3	13.7	0.4	16	0.07	0.034
KYS 109401	Soil		0.8	38.5	25.3	79	0.1	34.7	14.5	551	3.30	13.9	2.0	3.1	3.8	10	0.2	2.8	0.3	20	0.04	0.048
KYS 109402	Soil		9.1	54.0	34.7	141	0.2	44.8	15.2	433	4.53	19.9	3.4	3.4	7.7	41	1.0	4.6	0.4	10	0.06	0.058
KYS 109403	Soil		5.6	83.2	29.4	148	0.3	51.1	20.7	752	4.44	7.5	3.2	4.7	4.3	30	0.6	3.3	0.3	10	0.34	0.099
KYS 109404	Soil		4.7	44.8	29.4	101	0.1	42.2	17.5	482	3.85	10.7	2.4	5.4	2.2	23	0.3	3.6	0.4	11	0.23	0.063
KYS 109405	Soil		3.3	53.5	30.7	133	0.3	52.2	17.6	854	4.81	12.8	2.4	3.7	2.5	21	0.9	3.8	0.3	11	0.25	0.067
KYS 109406	Soil		4.0	42.1	24.3	125	0.2	36.3	13.1	729	3.90	11.6	1.8	2.6	2.4	14	0.8	4.2	0.2	14	0.15	0.067
KYS 109407	Soil		8.5	46.8	23.0	92	0.2	28.9	10.5	324	2.71	15.5	2.4	3.0	6.5	32	0.6	5.3	0.3	8	0.10	0.068
KYS 109408	Soil		4.4	145.0	27.4	189	0.3	73.7	19.9	1304	4.07	8.4	3.0	23.3	2.7	19	2.6	2.7	0.3	21	0.04	0.058
KYS 109409	Soil		3.0	105.5	20.6	92	0.2	30.7	7.6	420	2.83	10.1	1.4	11.2	0.5	39	0.3	2.6	0.3	29	0.03	0.071
KYS 109410	Soil		9.4	89.8	24.9	94	0.5	21.6	4.6	217	3.62	10.0	3.2	11.2	0.4	153	0.2	5.9	0.3	29	0.05	0.115
KYS 109411	Soil		2.3	83.5	15.4	105	0.2	32.7	10.3	657	3.03	20.8	1.3	6.1	0.4	12	0.3	6.0	0.2	40	0.04	0.071
KYS 109412	Soil		1.2	75.6	13.3	76	0.1	32.6	9.5	760	3.06	11.8	1.1	18.5	1.2	13	0.3	2.1	0.2	30	0.06	0.043
KYS 109413	Soil		1.5	41.5	11.1	68	<0.1	25.0	7.5	642	2.60	10.3	0.7	24.0	1.0	7	0.2	1.5	0.2	36	0.06	0.038
KYS 109414	Soil		14.4	76.4	23.2	77	0.7	19.2	5.0	432	3.10	20.2	3.4	11.9	0.9	213	0.2	9.2	0.4	17	0.03	0.069
KYS 109415	Soil		1.7	247.2	20.5	94	0.2	51.2	17.0	1575	3.40	18.1	1.3	19.7	2.4	18	0.2	5.0	0.3	33	0.09	0.063
KYS 109416	Soil		2.0	206.6	30.2	159	0.5	62.9	23.8	2243	3.86	126.7	1.3	46.5	6.3	19	0.3	25.4	0.3	24	0.07	0.054
KYS 109417	Soil		2.9	65.9	26.4	174	0.3	70.7	27.3	2285	4.30	33.0	1.3	8.8	10.0	17	1.0	9.5	0.3	11	0.25	0.086

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109386	Soil	21	16	0.46	153	0.010	1	1.25	0.004	0.05	<0.1	0.06	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109387	Soil	21	16	0.45	160	0.008	<1	1.23	0.004	0.05	<0.1	0.05	1.9	<0.1	<0.05	4	0.6	<0.2
KYS 109388	Soil	20	17	0.56	127	0.005	<1	1.42	0.004	0.06	<0.1	0.05	1.8	<0.1	<0.05	3	0.6	<0.2
KYS 109389	Soil	28	17	0.55	175	0.005	<1	1.32	0.004	0.06	<0.1	0.06	1.8	<0.1	<0.05	3	0.7	<0.2
KYS 109390	Soil	32	7	0.11	183	0.008	<1	0.63	0.004	0.06	<0.1	0.12	2.6	<0.1	<0.05	1	0.5	0.6
KYS 109391	Soil	24	23	0.61	131	0.005	<1	1.46	0.003	0.04	<0.1	0.09	1.6	<0.1	<0.05	5	<0.5	0.6
KYS 109392	Soil	19	27	0.44	119	0.014	1	1.65	0.004	0.06	0.2	0.07	1.7	<0.1	<0.05	5	0.6	<0.2
KYS 109393	Soil	20	19	0.24	123	0.017	<1	0.97	0.005	0.05	0.1	0.06	0.8	<0.1	<0.05	4	0.7	0.2
KYS 109394	Soil	32	12	0.35	214	0.004	<1	0.88	0.004	0.06	<0.1	0.39	1.5	0.1	<0.05	2	4.2	0.4
KYS 109395	Soil	22	21	0.38	295	0.015	1	1.16	0.004	0.06	0.1	0.33	1.0	0.1	<0.05	4	2.5	<0.2
KYS 109396	Soil	24	19	0.52	173	0.010	1	1.40	0.003	0.05	0.1	0.09	1.4	<0.1	<0.05	4	0.8	0.5
KYS 109399	Soil	14	5	0.16	33	0.002	<1	0.46	0.004	0.07	<0.1	0.02	1.2	<0.1	<0.05	1	<0.5	<0.2
KYS 109400	Soil	10	4	0.10	34	0.001	<1	0.34	0.008	0.07	<0.1	0.09	0.9	0.1	0.10	<1	3.3	0.4
KYS 109401	Soil	17	17	0.43	56	0.011	1	1.22	0.005	0.04	<0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109402	Soil	10	11	0.38	51	0.002	<1	0.93	0.018	0.05	<0.1	0.07	0.9	<0.1	0.10	2	1.8	0.4
KYS 109403	Soil	12	10	0.41	44	0.002	<1	0.83	0.004	0.04	<0.1	0.07	1.5	<0.1	<0.05	2	1.2	<0.2
KYS 109404	Soil	9	11	0.28	72	0.004	<1	0.87	0.005	0.05	<0.1	0.05	1.1	<0.1	<0.05	2	0.7	<0.2
KYS 109405	Soil	8	10	0.23	54	0.003	<1	0.74	0.005	0.04	<0.1	0.09	1.7	<0.1	<0.05	2	1.3	<0.2
KYS 109406	Soil	9	10	0.18	60	0.006	<1	0.61	0.004	0.04	<0.1	0.11	1.7	<0.1	<0.05	2	1.2	<0.2
KYS 109407	Soil	17	7	0.18	48	0.003	<1	0.55	0.003	0.04	<0.1	0.11	1.4	<0.1	<0.05	1	1.0	<0.2
KYS 109408	Soil	14	15	0.26	118	0.011	<1	1.02	0.004	0.04	<0.1	0.10	1.5	<0.1	<0.05	3	1.4	<0.2
KYS 109409	Soil	13	14	0.15	168	0.010	<1	0.70	0.005	0.04	<0.1	0.07	0.6	<0.1	0.07	3	1.2	<0.2
KYS 109410	Soil	12	17	0.16	389	0.011	1	0.84	0.016	0.09	0.1	0.19	0.8	0.1	0.24	3	1.9	0.3
KYS 109411	Soil	11	19	0.15	491	0.026	1	0.98	0.003	0.04	0.1	0.08	0.7	<0.1	<0.05	4	1.3	<0.2
KYS 109412	Soil	13	16	0.38	257	0.020	1	1.25	0.004	0.04	0.2	0.08	1.0	<0.1	0.06	4	0.7	<0.2
KYS 109413	Soil	11	18	0.35	164	0.025	1	1.36	0.005	0.04	0.2	0.05	1.0	<0.1	0.05	4	0.6	<0.2
KYS 109414	Soil	9	9	0.16	403	0.004	<1	0.51	0.012	0.11	0.1	0.32	0.6	0.1	0.28	2	2.8	0.4
KYS 109415	Soil	18	19	0.53	114	0.016	<1	1.50	0.003	0.05	0.4	0.07	1.3	<0.1	0.05	4	0.9	0.8
KYS 109416	Soil	24	16	0.50	141	0.012	<1	1.22	0.003	0.04	<0.1	0.09	1.8	<0.1	0.06	3	1.3	0.4
KYS 109417	Soil	17	11	0.71	42	0.002	<1	1.29	0.002	0.04	<0.1	0.05	1.7	<0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109418	Soil	1.9	44.0	27.3	115	0.1	58.0	20.2	950	4.58	7.6	1.6	2.1	5.2	13	0.3	3.0	0.4	7	0.12	0.043
KYS 109419	Soil	2.3	50.4	19.8	101	0.2	36.2	13.5	916	3.42	38.7	1.2	17.8	3.6	12	0.3	15.1	0.3	18	0.18	0.061
KYS 109420	Soil	4.9	86.2	27.6	145	0.4	74.7	28.7	1445	5.05	12.7	2.2	3.1	6.9	28	0.6	5.5	0.4	13	0.39	0.086
KYS 109421	Soil	1.3	49.5	30.7	97	0.1	50.1	22.9	946	4.50	6.4	1.6	1.6	6.0	29	0.2	1.3	0.4	5	0.58	0.038
KYS 109422	Soil	2.3	55.7	29.4	114	0.2	63.4	28.9	1583	4.72	8.3	2.0	1.7	9.1	17	0.3	1.8	0.4	7	0.19	0.046
KYS 109423	Soil	1.3	51.1	31.3	91	0.1	53.6	24.5	1336	4.25	10.7	1.7	1.6	8.6	14	0.2	2.3	0.4	5	0.14	0.035
KYS 109424	Soil	1.8	61.1	29.4	96	0.1	52.6	24.2	1237	4.29	13.7	1.7	1.3	8.8	15	0.2	1.4	0.4	7	0.12	0.034
KYS 109425	Soil	1.0	91.8	35.0	98	0.2	59.4	27.1	842	4.15	31.8	1.7	7.6	5.2	11	0.1	9.1	0.5	8	0.14	0.045
KYS 109426	Soil	13.8	83.5	24.7	75	0.7	21.9	5.4	434	2.99	18.9	3.3	14.8	1.0	226	0.1	8.4	0.4	17	0.03	0.071
KYS 109427	Soil	2.0	89.6	19.3	88	0.2	45.4	15.7	2273	3.43	15.6	0.9	24.1	1.6	12	<0.1	2.1	0.3	34	0.08	0.073
KYS 109428	Soil	1.9	89.4	15.9	87	0.2	43.0	13.4	1887	3.15	14.8	0.9	51.3	1.2	12	0.2	1.8	0.2	33	0.08	0.084
KYS 109429	Soil	2.0	160.0	19.8	106	0.3	69.8	28.8	4981	3.14	14.8	1.0	42.6	1.5	18	0.2	2.5	0.3	29	0.08	0.081
KYS 109430	Soil	2.2	84.7	16.0	90	0.2	43.4	15.6	2181	3.04	15.4	1.0	19.8	2.8	9	0.3	2.7	0.2	32	0.08	0.068
KYS 109431	Soil	2.3	58.6	18.3	87	0.2	33.7	12.3	1347	3.11	19.3	1.2	16.7	2.2	6	0.2	3.8	0.2	27	0.06	0.064
KYS 109432	Soil	1.5	51.7	13.6	72	0.1	30.0	8.4	830	2.74	10.6	1.0	13.4	4.0	9	0.1	1.9	0.2	18	0.12	0.046
KYS 109433	Soil	3.2	75.8	23.2	88	0.6	39.9	12.1	1747	3.80	21.1	1.4	22.5	2.4	26	0.1	2.1	0.3	28	0.21	0.095
KYS 109434	Soil	2.2	120.9	20.9	111	0.5	49.5	15.2	2434	3.67	632.3	1.0	113.6	1.5	18	0.2	23.2	0.3	32	0.06	0.065
KYS 109435	Soil	1.4	48.5	12.2	86	0.3	39.5	11.2	1298	2.85	13.0	0.8	17.8	1.4	10	0.2	1.3	0.2	34	0.07	0.049
KYS 109436	Soil	1.6	72.5	18.3	118	0.4	64.6	15.6	1988	3.28	23.5	0.9	21.8	6.0	12	0.2	1.5	0.3	30	0.08	0.048
KYS 109437	Soil	1.3	55.7	11.9	73	0.2	37.8	10.8	1154	2.63	11.0	0.7	22.2	3.0	10	0.2	1.1	0.2	31	0.08	0.044

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

CERTIFICATE OF ANALYSIS WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109418	Soil	10	10	0.50	52	0.003	<1	1.17	0.007	0.08	<0.1	0.04	1.6	<0.1	0.07	3	0.6	<0.2
KYS 109419	Soil	17	13	0.51	126	0.006	<1	1.26	0.004	0.04	<0.1	0.06	1.6	<0.1	<0.05	3	0.8	<0.2
KYS 109420	Soil	13	11	0.61	57	0.005	<1	1.19	0.004	0.05	<0.1	0.07	1.5	<0.1	0.13	3	2.0	<0.2
KYS 109421	Soil	10	7	0.54	31	0.004	<1	0.77	0.005	0.05	<0.1	0.04	1.4	<0.1	0.13	2	0.7	<0.2
KYS 109422	Soil	14	8	0.49	42	0.001	<1	1.05	0.004	0.05	<0.1	0.04	1.2	<0.1	0.09	3	1.0	<0.2
KYS 109423	Soil	15	8	0.42	30	0.001	<1	0.99	0.004	0.05	<0.1	0.03	1.2	<0.1	0.07	3	<0.5	<0.2
KYS 109424	Soil	18	8	0.39	42	0.001	<1	0.94	0.004	0.06	<0.1	0.04	1.2	<0.1	0.07	2	0.7	<0.2
KYS 109425	Soil	15	8	0.39	38	0.003	<1	0.94	0.006	0.06	<0.1	0.03	1.1	<0.1	0.08	2	0.7	<0.2
KYS 109426	Soil	11	10	0.18	426	0.004	<1	0.58	0.017	0.10	<0.1	0.32	0.7	0.1	0.29	2	2.6	0.4
KYS 109427	Soil	19	22	0.50	92	0.014	<1	1.51	0.007	0.04	0.1	0.10	1.2	<0.1	0.09	5	1.2	<0.2
KYS 109428	Soil	19	21	0.49	77	0.015	<1	1.45	0.006	0.05	0.1	0.07	1.2	<0.1	0.08	5	0.9	<0.2
KYS 109429	Soil	20	17	0.44	96	0.012	<1	1.41	0.004	0.04	<0.1	0.08	1.1	<0.1	0.06	4	0.9	0.3
KYS 109430	Soil	21	18	0.49	102	0.023	<1	1.40	0.005	0.05	0.1	0.06	1.7	<0.1	0.10	4	1.1	<0.2
KYS 109431	Soil	22	15	0.41	106	0.013	<1	1.30	0.004	0.05	0.1	0.06	1.5	<0.1	0.06	4	1.0	<0.2
KYS 109432	Soil	20	13	0.42	100	0.010	<1	1.08	0.003	0.04	<0.1	0.04	1.3	<0.1	<0.05	3	0.5	<0.2
KYS 109433	Soil	17	18	0.48	329	0.006	<1	1.27	0.006	0.07	0.1	0.14	1.3	<0.1	0.11	4	1.2	<0.2
KYS 109434	Soil	19	18	0.42	340	0.012	1	1.45	0.005	0.06	0.2	0.09	1.7	<0.1	0.07	4	1.3	0.2
KYS 109435	Soil	19	21	0.46	87	0.017	<1	1.39	0.005	0.04	0.2	0.07	1.0	<0.1	0.06	4	1.0	<0.2
KYS 109436	Soil	23	21	0.53	84	0.017	<1	1.45	0.004	0.04	0.1	0.09	1.5	<0.1	<0.05	4	1.1	<0.2
KYS 109437	Soil	19	19	0.44	68	0.023	<1	1.33	0.005	0.04	0.2	0.06	1.1	<0.1	0.06	4	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

QUALITY CONTROL REPORT WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
KYS 109101	Soil	0.7	43.8	27.8	85	0.1	27.3	12.6	405	4.25	24.6	1.9	5.1	6.4	6	<0.1	1.4	0.5	10	0.05	0.032
REP KYS 109101	QC	0.8	41.5	27.6	78	0.1	26.6	11.8	391	4.11	24.0	2.0	5.4	5.7	6	<0.1	1.3	0.4	10	0.04	0.033
KYS 109104	Soil	1.4	15.3	18.2	53	<0.1	16.0	6.4	263	3.31	13.9	0.6	3.2	3.4	7	0.2	1.9	0.2	44	0.07	0.039
REP KYS 109104	QC	1.2	14.6	17.7	51	<0.1	14.6	6.5	262	3.23	13.7	0.6	1.8	3.2	7	0.2	1.7	0.2	41	0.06	0.039
KYS 109137	Soil	0.3	38.3	31.5	98	0.2	32.0	14.2	540	3.46	180.4	1.7	15.3	14.3	17	0.1	8.0	0.4	4	0.25	0.042
REP KYS 109137	QC	0.2	40.6	30.5	101	0.1	34.8	15.2	533	3.49	180.6	1.8	14.5	15.1	18	<0.1	7.8	0.4	3	0.25	0.042
KYS 109143	Soil	0.7	47.9	28.2	92	0.1	33.8	17.0	479	4.26	88.8	1.8	13.9	9.9	9	0.2	4.1	0.4	8	0.10	0.037
REP KYS 109143	QC	0.7	47.2	29.9	87	0.1	33.1	16.8	483	4.39	93.5	1.8	13.6	10.6	9	0.1	4.2	0.4	7	0.09	0.037
KYS 109169	Soil	0.5	50.2	28.9	83	0.1	40.3	21.2	769	4.00	12.7	2.2	3.1	12.0	13	<0.1	1.0	0.5	7	0.14	0.052
REP KYS 109169	QC	0.6	49.9	28.9	82	0.1	39.9	21.5	770	4.02	12.8	2.2	2.2	11.7	13	<0.1	1.1	0.5	6	0.14	0.050
KYS 109183	Soil	1.8	45.7	13.2	48	<0.1	15.4	6.2	384	3.07	13.9	0.7	9.0	3.8	9	0.1	1.3	0.2	50	0.07	0.034
REP KYS 109183	QC	1.6	44.5	12.7	48	<0.1	15.7	6.1	372	2.94	13.2	0.6	7.5	3.9	8	0.1	1.2	0.2	46	0.06	0.031
KYS 109205	Soil	0.5	31.2	18.6	79	<0.1	24.4	9.3	333	3.47	15.0	1.3	1.8	5.4	7	<0.1	0.9	0.3	11	0.06	0.037
REP KYS 109205	QC	0.5	30.6	18.1	79	<0.1	25.7	9.9	349	3.50	15.2	1.3	1.6	5.4	8	<0.1	0.8	0.3	11	0.06	0.038
KYS 109223	Soil	1.4	228.1	27.5	98	0.2	43.9	21.0	1862	3.04	10.8	2.0	25.7	3.5	32	0.1	2.2	0.3	37	0.10	0.085
REP KYS 109223	QC	1.3	225.3	25.7	92	0.2	41.2	20.0	1742	2.84	9.8	1.9	49.6	3.7	31	0.2	2.1	0.3	34	0.09	0.088
KYS 109231	Soil	1.9	68.5	35.0	118	0.2	51.1	26.8	942	4.42	14.7	2.6	2.3	8.0	23	0.3	2.2	0.5	8	0.25	0.058
REP KYS 109231	QC	1.9	72.8	35.4	118	0.1	54.1	27.1	967	4.45	14.8	2.6	3.5	7.7	23	0.3	2.2	0.5	8	0.26	0.058
KYS 109252	Soil	2.3	202.7	31.0	138	0.3	82.3	32.3	4123	3.97	32.8	1.6	56.9	9.0	21	0.1	3.0	0.5	30	0.10	0.068
REP KYS 109252	QC	2.2	208.3	30.0	139	0.3	88.0	33.3	4387	4.03	33.4	1.6	51.8	8.3	22	<0.1	3.1	0.5	32	0.10	0.069
KYS 109265	Soil	1.9	62.5	32.7	147	0.4	39.6	17.3	1004	3.44	200.4	1.9	17.3	7.1	16	0.5	21.6	0.3	19	0.17	0.070
REP KYS 109265	QC	1.7	61.6	34.1	148	0.4	39.5	17.1	1017	3.50	200.1	1.9	20.4	6.9	16	0.4	21.2	0.3	19	0.17	0.071
KYS 109288	Soil	2.0	18.7	13.2	50	0.1	13.3	4.9	211	2.50	17.4	0.6	4.9	0.8	8	0.2	1.4	0.3	50	0.05	0.058
REP KYS 109288	QC	2.1	18.4	12.6	52	<0.1	14.1	4.8	208	2.51	17.5	0.6	7.8	0.8	8	0.2	1.4	0.3	52	0.05	0.060
KYS 109310	Soil	2.4	39.3	29.2	97	0.2	35.8	16.0	642	3.48	9.1	2.3	4.7	3.8	20	0.4	2.0	0.4	11	0.13	0.047
REP KYS 109310	QC	2.4	41.8	28.2	97	0.2	36.4	15.6	676	3.49	9.0	2.2	2.7	3.5	20	0.3	2.0	0.4	13	0.13	0.044
KYS 109319	Soil	2.7	191.9	23.7	105	0.3	55.0	18.6	2045	3.43	17.3	1.8	26.3	2.1	27	0.3	1.8	0.3	41	0.07	0.079
REP KYS 109319	QC	2.5	192.7	24.0	107	0.3	55.2	19.7	2037	3.50	18.2	1.7	17.8	2.1	27	0.3	1.7	0.3	42	0.07	0.079

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

QUALITY CONTROL REPORT WHI10000116.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
KYS 109101	Soil	16	13	0.59	38	0.001	<1	1.26	0.005	0.05	<0.1	0.03	1.4	<0.1	<0.05	4	0.5	<0.2
REP KYS 109101	QC	15	14	0.55	38	0.001	<1	1.21	0.005	0.04	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109104	Soil	12	21	0.30	53	0.036	<1	1.07	0.005	0.03	0.2	0.05	1.4	<0.1	<0.05	5	<0.5	<0.2
REP KYS 109104	QC	12	20	0.29	48	0.034	<1	1.05	0.005	0.03	0.2	0.04	1.4	<0.1	<0.05	5	0.6	<0.2
KYS 109137	Soil	26	9	0.41	36	0.001	1	0.90	0.004	0.06	<0.1	0.03	1.5	<0.1	<0.05	2	0.5	0.4
REP KYS 109137	QC	27	9	0.41	41	0.002	1	0.90	0.004	0.07	<0.1	0.03	1.4	<0.1	<0.05	3	1.0	<0.2
KYS 109143	Soil	20	12	0.66	31	0.002	2	1.23	0.006	0.05	<0.1	0.03	1.5	<0.1	0.05	3	0.5	<0.2
REP KYS 109143	QC	21	13	0.66	32	0.001	<1	1.24	0.004	0.05	<0.1	0.03	1.4	<0.1	0.05	4	<0.5	0.4
KYS 109169	Soil	27	8	0.24	41	0.004	1	0.66	0.005	0.07	<0.1	0.03	1.8	<0.1	<0.05	2	<0.5	<0.2
REP KYS 109169	QC	25	8	0.24	41	0.004	<1	0.65	0.006	0.07	<0.1	0.03	1.5	<0.1	<0.05	1	<0.5	<0.2
KYS 109183	Soil	18	21	0.26	102	0.034	<1	1.19	0.004	0.04	0.2	0.03	1.6	<0.1	<0.05	5	<0.5	<0.2
REP KYS 109183	QC	16	20	0.25	85	0.025	<1	1.09	0.004	0.03	0.2	0.04	1.4	<0.1	<0.05	4	<0.5	0.4
KYS 109205	Soil	20	18	0.69	38	0.002	<1	1.46	0.006	0.04	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
REP KYS 109205	QC	20	18	0.66	38	0.004	<1	1.48	0.005	0.04	<0.1	0.02	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109223	Soil	26	22	0.61	138	0.021	<1	1.27	0.006	0.05	0.1	0.07	1.6	<0.1	<0.05	4	<0.5	<0.2
REP KYS 109223	QC	23	20	0.62	130	0.016	<1	1.32	0.006	0.05	0.1	0.06	1.5	<0.1	<0.05	4	<0.5	0.2
KYS 109231	Soil	14	11	0.46	40	0.003	<1	0.97	0.008	0.05	<0.1	0.04	1.9	<0.1	<0.05	2	0.5	<0.2
REP KYS 109231	QC	12	11	0.45	40	0.003	1	0.93	0.007	0.05	<0.1	0.04	1.8	<0.1	0.05	2	0.7	0.3
KYS 109252	Soil	32	24	0.68	118	0.004	<1	1.53	0.005	0.03	<0.1	0.13	1.8	<0.1	<0.05	4	1.3	0.2
REP KYS 109252	QC	35	25	0.72	118	0.004	1	1.60	0.007	0.04	<0.1	0.13	1.8	<0.1	<0.05	4	1.6	0.3
KYS 109265	Soil	18	17	0.46	90	0.009	1	1.12	0.005	0.06	<0.1	0.05	1.7	<0.1	<0.05	3	0.9	<0.2
REP KYS 109265	QC	18	16	0.44	90	0.010	1	1.05	0.004	0.06	<0.1	0.05	1.7	<0.1	<0.05	3	0.8	<0.2
KYS 109288	Soil	10	22	0.22	77	0.026	<1	1.15	0.005	0.04	0.2	0.06	1.2	<0.1	<0.05	5	0.9	<0.2
REP KYS 109288	QC	10	21	0.25	77	0.027	<1	1.22	0.005	0.04	0.2	0.06	1.2	<0.1	0.06	6	1.0	<0.2
KYS 109310	Soil	11	11	0.36	63	0.004	<1	0.92	0.004	0.04	<0.1	0.04	1.5	<0.1	<0.05	2	0.8	0.3
REP KYS 109310	QC	11	11	0.36	65	0.004	<1	0.93	0.004	0.04	<0.1	0.05	1.5	<0.1	<0.05	2	1.0	<0.2
KYS 109319	Soil	17	23	0.60	282	0.015	<1	1.55	0.005	0.05	0.2	0.12	1.5	<0.1	<0.05	4	0.6	0.3
REP KYS 109319	QC	17	23	0.60	283	0.018	2	1.55	0.006	0.05	0.2	0.12	1.5	<0.1	<0.05	4	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

QUALITY CONTROL REPORT WHI10000116.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
KYS 109354	Soil	2.6	124.7	27.0	111	0.3	54.4	21.4	1668	3.81	330.7	1.3	49.7	7.5	16	0.3	226.7	0.3	21	0.10	0.055
REP KYS 109354	QC	2.5	124.4	27.0	106	0.3	52.1	20.3	1641	3.70	325.4	1.3	60.5	7.4	16	0.3	226.9	0.3	20	0.11	0.050
KYS 109367	Soil	6.6	46.8	28.4	136	0.2	41.7	14.8	526	3.49	21.8	3.3	4.7	6.6	19	1.2	7.4	0.4	11	0.09	0.050
REP KYS 109367	QC	6.4	47.7	28.4	132	0.2	44.8	15.6	536	3.54	21.8	3.3	5.9	8.0	19	1.3	7.7	0.4	10	0.10	0.053
KYS 109389	Soil	1.2	80.6	25.8	96	0.3	40.4	15.7	1112	3.53	388.8	1.2	86.5	8.2	17	0.2	178.0	0.3	21	0.18	0.058
REP KYS 109389	QC	1.3	81.9	26.4	103	0.4	41.4	16.7	1157	3.71	386.6	1.2	80.5	8.5	17	0.2	175.7	0.4	20	0.18	0.055
KYS 109410	Soil	9.4	89.8	24.9	94	0.5	21.6	4.6	217	3.62	10.0	3.2	11.2	0.4	153	0.2	5.9	0.3	29	0.05	0.115
REP KYS 109410	QC	10.1	90.3	24.8	90	0.5	20.8	4.4	216	3.64	9.5	3.2	9.8	0.5	153	0.2	5.9	0.4	29	0.05	0.113
KYS 109415	Soil	1.7	247.2	20.5	94	0.2	51.2	17.0	1575	3.40	18.1	1.3	19.7	2.4	18	0.2	5.0	0.3	33	0.09	0.063
REP KYS 109415	QC	1.7	246.0	20.8	97	0.2	51.9	17.4	1603	3.53	18.2	1.3	19.8	2.3	18	0.2	5.0	0.3	34	0.09	0.064
KYS 109434	Soil	2.2	120.9	20.9	111	0.5	49.5	15.2	2434	3.67	632.3	1.0	113.6	1.5	18	0.2	23.2	0.3	32	0.06	0.065
REP KYS 109434	QC	2.3	116.3	20.1	111	0.5	51.3	15.3	2362	3.74	639.1	0.9	114.1	1.6	17	0.2	22.8	0.3	32	0.06	0.064
Reference Materials																					
STD DS7	Standard	19.4	107.6	63.2	390	1.0	53.3	8.9	595	2.33	50.6	4.6	69.4	4.1	65	6.4	5.6	4.6	85	0.91	0.075
STD DS7	Standard	21.4	114.6	62.2	387	1.0	57.4	9.4	629	2.44	50.9	4.7	66.6	4.7	72	6.2	5.0	4.1	86	0.97	0.072
STD DS7	Standard	21.3	100.9	63.7	376	1.0	54.1	9.2	613	2.39	52.5	4.5	156.7	4.7	77	6.3	5.8	4.3	82	0.95	0.077
STD DS7	Standard	19.8	106.6	70.0	408	1.0	53.6	8.9	617	2.37	52.4	4.9	65.4	4.7	77	5.9	5.7	4.6	89	0.92	0.076
STD DS7	Standard	19.6	100.4	72.4	394	1.1	51.0	8.6	625	2.35	51.5	4.8	80.0	4.7	76	5.9	5.7	4.8	86	0.91	0.082
STD DS7	Standard	19.1	94.8	65.0	389	0.9	49.9	8.7	604	2.25	48.1	4.7	56.1	4.4	73	5.9	5.6	4.3	79	0.90	0.073
STD DS7	Standard	20.2	90.5	58.4	410	1.0	55.3	7.8	608	2.36	41.0	3.9	70.4	4.0	70	5.0	4.6	3.8	84	0.95	0.060
STD DS7	Standard	21.5	117.2	73.8	404	1.0	58.7	9.5	621	2.43	53.6	5.5	64.1	5.1	79	7.0	6.4	5.3	86	0.95	0.073
STD DS7	Standard	21.6	119.2	72.4	395	1.0	51.5	9.6	623	2.43	52.0	5.7	69.9	5.2	81	7.1	6.8	5.2	83	1.00	0.076
STD DS7	Standard	20.9	106.8	63.8	386	1.0	53.3	9.0	615	2.34	52.9	4.3	68.8	4.2	73	6.3	6.2	4.5	78	0.92	0.077
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

QUALITY CONTROL REPORT WHI10000116.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
KYS 109354	Soil	27	15	0.55	143	0.006	<1	1.25	0.004	0.05	<0.1	0.06	1.5	<0.1	<0.05	4	0.9	0.5
REP KYS 109354	QC	27	16	0.56	138	0.003	<1	1.26	0.004	0.05	<0.1	0.05	1.6	<0.1	<0.05	4	1.0	<0.2
KYS 109367	Soil	20	10	0.32	74	0.002	<1	0.88	0.004	0.05	<0.1	0.06	1.7	<0.1	<0.05	2	1.4	<0.2
REP KYS 109367	QC	24	10	0.29	82	0.003	<1	0.90	0.006	0.06	<0.1	0.06	1.9	0.1	<0.05	2	1.5	<0.2
KYS 109389	Soil	28	17	0.55	175	0.005	<1	1.32	0.004	0.06	<0.1	0.06	1.8	<0.1	<0.05	3	0.7	<0.2
REP KYS 109389	QC	29	17	0.57	175	0.008	<1	1.31	0.005	0.06	<0.1	0.07	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 109410	Soil	12	17	0.16	389	0.011	1	0.84	0.016	0.09	0.1	0.19	0.8	0.1	0.24	3	1.9	0.3
REP KYS 109410	QC	11	16	0.15	381	0.009	<1	0.81	0.016	0.08	<0.1	0.18	0.7	0.1	0.20	2	2.4	1.3
KYS 109415	Soil	18	19	0.53	114	0.016	<1	1.50	0.003	0.05	0.4	0.07	1.3	<0.1	0.05	4	0.9	0.8
REP KYS 109415	QC	18	19	0.53	113	0.016	<1	1.48	0.003	0.05	0.2	0.07	1.4	<0.1	<0.05	4	1.0	0.7
KYS 109434	Soil	19	18	0.42	340	0.012	1	1.45	0.005	0.06	0.2	0.09	1.7	<0.1	0.07	4	1.3	0.2
REP KYS 109434	QC	18	17	0.43	334	0.011	<1	1.44	0.005	0.06	0.1	0.09	1.6	<0.1	0.08	4	1.2	0.3
Reference Materials																		
STD DS7	Standard	12	199	1.02	396	0.114	38	1.00	0.097	0.47	3.7	0.23	2.1	4.1	0.21	5	3.1	1.4
STD DS7	Standard	14	228	1.04	408	0.134	36	1.04	0.107	0.47	3.8	0.19	2.8	4.0	0.15	5	3.1	1.5
STD DS7	Standard	13	216	1.01	397	0.121	40	1.02	0.102	0.47	3.5	0.22	2.6	3.9	0.18	5	3.3	1.6
STD DS7	Standard	13	209	1.05	409	0.120	42	1.02	0.101	0.46	3.6	0.23	2.4	4.0	0.20	5	2.9	0.8
STD DS7	Standard	13	214	1.05	415	0.114	44	1.05	0.100	0.47	3.5	0.24	2.6	4.4	0.21	5	2.8	0.7
STD DS7	Standard	13	200	1.00	373	0.106	39	0.99	0.097	0.44	3.2	0.21	2.4	3.7	0.19	4	3.9	1.9
STD DS7	Standard	12	209	1.06	392	0.125	35	1.00	0.098	0.46	4.0	0.22	1.9	4.1	0.23	5	3.0	1.5
STD DS7	Standard	14	183	1.04	407	0.135	39	1.00	0.100	0.49	3.9	0.22	2.8	4.3	0.18	5	3.4	1.4
STD DS7	Standard	14	188	1.07	405	0.132	41	1.04	0.103	0.50	3.7	0.23	2.8	4.1	0.23	5	3.2	1.3
STD DS7	Standard	13	163	1.03	418	0.122	41	0.98	0.096	0.49	3.5	0.21	2.6	4.0	0.21	5	3.1	0.9
STD DS7 Expected		12	179	1.05	410	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5	1.08
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

QUALITY CONTROL REPORT WHI10000116.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 20, 2010

QUALITY CONTROL REPORT WHI10000116.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Submitted By: Johnathan More
Receiving Lab: Canada-Whitehorse
Received: July 14, 2010
Report Date: August 23, 2010
Page: 1 of 13

CERTIFICATE OF ANALYSIS WHI10000108.1

CLIENT JOB INFORMATION

Project: KYS
Shipment ID: KYS1
P.O. Number
Number of Samples: 350

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	350	Dry at 60C sieve 100g to -80 mesh			VAN
Dry at 60C	350	Dry at 60C			VAN
1DX2	350	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Aldrin Resources
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5
Canada

CC: Isaac Fage
Bert Jeffries
Shawn Ryan

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 94382	Soil	1.1	23.8	22.7	50	<0.1	41.0	10.0	338	2.89	13.5	0.7	6.1	3.0	13	0.1	0.6	0.3	40	0.13	0.043
KYS 94383	Soil	1.4	31.4	20.6	64	0.2	27.8	7.4	230	2.69	13.5	0.9	2.4	1.8	5	0.1	1.1	0.3	29	0.04	0.050
KYS 94384	Soil	1.6	33.7	20.3	72	0.3	20.5	12.2	720	2.81	51.6	1.1	11.4	0.8	9	0.2	2.4	0.3	35	0.07	0.066
KYS 94385	Soil	3.3	53.2	34.6	58	0.7	17.0	3.3	144	3.24	50.9	1.2	10.6	0.8	10	0.1	7.8	0.6	30	0.03	0.101
KYS 94386	Soil	2.6	84.4	29.9	83	0.6	22.1	4.1	173	3.81	32.3	1.2	10.6	2.1	13	<0.1	6.1	0.5	33	0.02	0.093
KYS 94387	Soil	2.5	78.5	29.4	74	1.2	16.8	2.6	129	3.69	50.3	1.1	11.0	1.6	9	<0.1	6.9	0.5	30	<0.01	0.103
KYS 94388	Soil	2.8	80.6	32.1	69	1.0	17.0	2.7	150	4.05	39.6	1.0	10.3	1.7	13	<0.1	4.5	0.5	35	0.01	0.106
KYS 94389	Soil	2.9	69.4	33.3	70	0.5	18.5	4.3	226	4.32	35.5	0.8	6.5	2.2	13	<0.1	3.6	0.5	42	0.01	0.087
KYS 94390	Soil	1.8	28.6	20.6	44	0.4	13.0	3.6	142	2.81	41.6	0.6	5.0	1.2	6	<0.1	2.3	0.3	30	0.01	0.061
KYS 94391	Soil	1.4	28.8	24.0	72	0.2	27.8	12.9	521	3.33	29.0	0.8	3.6	2.4	8	0.1	1.7	0.3	25	0.04	0.060
KYS 94392	Soil	1.2	27.7	24.7	69	0.2	26.8	12.0	505	3.17	55.9	0.8	11.9	3.4	8	<0.1	1.5	0.3	26	0.06	0.044
KYS 94393	Soil	1.1	27.9	24.9	67	0.3	26.8	11.7	519	3.17	54.3	0.8	6.6	3.4	8	<0.1	1.6	0.3	26	0.06	0.046
KYS 94394	Soil	1.4	27.4	16.1	68	0.3	26.8	7.4	250	2.56	23.0	0.9	5.3	0.5	8	0.1	1.7	0.3	30	0.06	0.081
KYS 94395	Soil	1.3	21.0	17.3	77	0.1	35.2	13.1	486	2.84	20.4	0.7	1.2	4.0	13	0.2	0.4	0.3	20	0.12	0.072
KYS 94396	Soil	0.4	29.4	30.1	67	<0.1	26.9	13.4	668	2.71	33.0	0.7	1.6	6.1	6	0.2	0.5	0.2	17	0.08	0.057
KYS 94397	Soil	1.0	22.5	23.8	67	0.2	34.1	12.4	331	3.24	15.2	0.8	1.0	10.6	4	<0.1	0.4	0.4	24	0.02	0.027
KYS 94398	Soil	1.1	23.0	20.1	59	<0.1	26.0	13.3	796	2.89	2.8	1.1	0.8	6.8	6	<0.1	0.3	0.5	28	0.06	0.033
KYS 94399	Soil	1.5	28.2	27.6	67	0.3	21.4	6.7	190	2.76	112.0	1.6	99.2	3.0	16	0.5	1.6	0.5	34	0.04	0.049
KYS 94400	Soil	1.2	35.9	22.8	84	0.2	47.2	17.7	588	3.61	52.6	1.1	5.7	7.0	12	0.3	1.7	0.3	28	0.08	0.061
KYS 94401	Soil	2.0	22.7	14.9	61	0.4	17.6	7.7	376	2.50	30.2	1.0	4.1	0.3	8	0.2	1.8	0.3	45	0.05	0.077
KYS 94402	Soil	0.7	30.4	40.1	67	<0.1	29.2	16.5	787	2.95	9.2	1.0	0.6	9.7	11	<0.1	0.2	0.3	17	0.17	0.060
KYS 94403	Soil	0.5	31.7	47.5	52	0.1	28.3	19.5	1347	2.30	8.5	2.1	1.8	8.0	38	0.1	0.2	0.3	9	0.84	0.082
KYS 94404	Soil	1.8	29.2	15.0	73	0.4	25.1	7.7	268	2.81	15.0	1.0	3.7	0.6	9	0.3	1.2	0.3	43	0.05	0.059
KYS 94405	Soil	1.3	12.0	8.3	27	0.6	8.9	2.8	280	2.34	6.3	0.5	1.9	<0.1	7	0.2	0.6	0.1	29	0.04	0.074
KYS 94406	Soil	1.4	10.3	10.4	31	0.2	8.5	3.0	164	1.95	10.8	0.5	3.7	0.8	8	<0.1	0.8	0.2	49	0.04	0.032
KYS 94407	Soil	1.9	15.3	13.7	43	0.2	12.8	4.7	207	2.84	16.5	0.6	4.0	1.6	9	0.1	1.1	0.3	61	0.05	0.045
KYS 102426	Soil	0.8	58.5	40.0	134	<0.1	90.0	45.5	1127	4.43	510.2	3.7	7.3	6.4	7	0.2	12.8	0.4	15	0.08	0.054
KYS 102427	Soil	1.0	34.2	23.8	74	0.2	31.1	12.2	395	3.14	142.0	1.5	17.5	2.1	7	0.1	5.3	0.3	25	0.06	0.058
KYS 102428	Soil	1.2	36.8	25.1	76	0.1	32.3	13.5	442	3.33	36.1	1.8	6.3	2.3	8	0.1	2.8	0.3	31	0.07	0.058
KYS 102429	Soil	0.9	36.9	23.1	73	0.1	33.7	14.0	540	3.11	76.9	1.7	9.1	4.5	10	0.1	6.3	0.3	28	0.11	0.051

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 94382	Soil	14	54	0.47	100	0.015	<1	1.21	0.004	0.05	0.1	0.02	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 94383	Soil	12	25	0.35	60	0.007	<1	1.10	0.004	0.04	0.1	0.04	0.9	<0.1	<0.05	4	0.8	<0.2
KYS 94384	Soil	10	22	0.35	160	0.016	<1	1.32	0.005	0.04	0.1	0.05	0.9	<0.1	<0.05	4	0.6	0.2
KYS 94385	Soil	7	18	0.15	261	0.004	<1	0.95	0.008	0.04	0.1	0.07	1.1	<0.1	<0.05	3	2.1	0.2
KYS 94386	Soil	7	21	0.19	125	0.004	<1	1.03	0.009	0.04	<0.1	0.05	1.7	<0.1	0.05	3	2.1	0.2
KYS 94387	Soil	6	20	0.17	101	0.002	<1	0.95	0.008	0.03	<0.1	0.06	1.3	<0.1	<0.05	3	1.7	<0.2
KYS 94388	Soil	7	24	0.24	146	0.003	<1	1.17	0.012	0.05	<0.1	0.08	1.4	<0.1	0.09	4	2.5	0.2
KYS 94389	Soil	7	26	0.23	125	0.004	3	1.26	0.012	0.04	<0.1	0.07	1.4	<0.1	<0.05	4	2.2	<0.2
KYS 94390	Soil	11	19	0.14	77	0.005	<1	0.89	0.006	0.03	<0.1	0.04	0.8	<0.1	<0.05	4	0.8	<0.2
KYS 94391	Soil	16	22	0.32	76	0.007	<1	1.15	0.005	0.05	0.1	0.03	1.0	<0.1	<0.05	4	0.6	<0.2
KYS 94392	Soil	20	21	0.28	73	0.009	<1	1.09	0.004	0.06	<0.1	0.03	1.0	<0.1	<0.05	3	0.6	<0.2
KYS 94393	Soil	20	23	0.30	70	0.012	<1	1.11	0.004	0.07	<0.1	0.04	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 94394	Soil	10	23	0.25	67	0.008	<1	0.95	0.005	0.04	0.1	0.04	0.7	<0.1	<0.05	3	<0.5	<0.2
KYS 94395	Soil	16	36	0.65	72	0.004	<1	1.43	0.004	0.06	<0.1	0.03	0.9	<0.1	<0.05	4	<0.5	<0.2
KYS 94396	Soil	17	19	0.45	57	0.007	<1	1.12	0.004	0.06	<0.1	0.04	1.0	<0.1	<0.05	4	<0.5	0.2
KYS 94397	Soil	26	34	0.58	65	0.010	<1	1.43	0.004	0.05	<0.1	0.04	1.1	<0.1	<0.05	4	<0.5	<0.2
KYS 94398	Soil	21	18	0.42	69	0.027	<1	1.03	0.003	0.04	<0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 94399	Soil	20	18	0.20	63	0.011	<1	0.98	0.005	0.05	<0.1	0.03	0.9	<0.1	<0.05	5	0.7	<0.2
KYS 94400	Soil	21	56	0.68	93	0.007	<1	1.65	0.007	0.05	<0.1	0.03	1.9	<0.1	<0.05	5	<0.5	<0.2
KYS 94401	Soil	9	21	0.20	70	0.013	<1	1.09	0.004	0.04	0.1	0.03	0.6	<0.1	<0.05	4	0.7	0.2
KYS 94402	Soil	17	23	0.50	71	0.005	<1	1.53	0.002	0.07	<0.1	0.01	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 94403	Soil	33	11	0.31	104	0.005	2	0.88	0.006	0.14	<0.1	0.06	1.7	<0.1	<0.05	2	<0.5	<0.2
KYS 94404	Soil	10	23	0.23	68	0.021	<1	1.17	0.004	0.04	0.1	0.06	1.1	<0.1	<0.05	4	0.7	<0.2
KYS 94405	Soil	5	11	0.08	51	0.006	<1	0.57	0.004	0.03	<0.1	0.05	0.4	<0.1	<0.05	3	<0.5	<0.2
KYS 94406	Soil	13	19	0.13	41	0.028	<1	0.81	0.003	0.03	0.2	0.03	0.9	<0.1	<0.05	5	<0.5	<0.2
KYS 94407	Soil	13	25	0.19	49	0.040	1	1.01	0.004	0.04	0.2	0.02	1.3	<0.1	<0.05	6	<0.5	<0.2
KYS 102426	Soil	16	16	0.39	42	0.010	<1	1.18	0.004	0.03	<0.1	0.02	1.6	<0.1	<0.05	3	<0.5	0.2
KYS 102427	Soil	16	16	0.31	82	0.008	<1	1.07	0.005	0.05	0.1	0.05	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 102428	Soil	18	22	0.44	93	0.015	<1	1.35	0.005	0.05	0.1	0.04	1.3	<0.1	<0.05	4	0.6	<0.2
KYS 102429	Soil	22	20	0.44	103	0.015	<1	1.28	0.005	0.05	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 102430	Soil	0.9	28.6	20.4	65	<0.1	27.9	11.5	535	2.79	51.5	1.4	4.6	4.4	10	<0.1	3.8	0.2	27	0.13	0.042
KYS 102431	Soil	0.7	65.0	40.7	100	<0.1	56.3	38.5	1408	4.01	50.9	1.6	3.8	9.3	7	0.1	3.3	0.4	18	0.12	0.052
KYS 102432	Soil	0.4	48.9	33.5	90	0.2	43.6	22.3	1012	3.98	310.9	2.5	31.1	23.7	10	<0.1	9.3	0.4	8	0.18	0.049
KYS 102433	Soil	0.4	46.3	29.4	101	0.1	40.2	17.6	664	3.53	60.3	1.3	9.8	18.0	10	<0.1	4.9	0.4	10	0.22	0.042
KYS 102434	Soil	1.7	36.3	15.5	43	<0.1	14.8	5.0	194	2.51	14.6	0.6	8.3	3.4	14	0.2	2.0	0.3	55	0.16	0.033
KYS 102435	Soil	2.6	105.9	23.6	141	0.1	41.1	37.4	2889	3.88	11.7	1.1	21.3	4.1	8	0.2	2.8	0.3	38	0.04	0.058
KYS 102436	Soil	3.5	39.2	21.7	74	<0.1	23.4	11.3	505	3.29	15.7	2.1	2.2	3.4	10	0.2	2.7	0.3	10	0.05	0.045
KYS 102437	Soil	3.1	59.6	17.0	94	0.2	23.5	11.7	1660	3.50	19.6	1.5	5.7	0.5	15	0.3	2.7	0.3	42	0.06	0.094
KYS 102438	Soil	23.2	127.7	39.2	125	1.0	16.0	4.9	466	3.87	20.9	3.5	36.3	0.3	17	0.1	6.5	0.5	36	0.01	0.123
KYS 102439	Soil	3.8	302.9	39.0	246	0.2	79.6	43.0	5630	4.76	30.7	3.9	28.8	2.1	11	0.7	3.5	0.4	34	0.03	0.121
KYS 102440	Soil	4.7	66.1	28.8	166	0.3	52.8	19.9	1346	4.00	11.9	2.0	7.5	9.9	20	1.0	2.1	0.4	18	0.24	0.080
KYS 102441	Soil	2.8	79.9	28.6	103	0.3	53.1	20.7	1338	4.14	13.6	1.5	3.8	11.6	26	0.3	1.6	0.5	12	0.59	0.087
KYS 102442	Soil	0.8	37.7	28.3	74	0.1	29.8	19.3	910	3.32	16.8	1.1	1.5	5.6	11	0.2	0.9	0.3	23	0.16	0.067
KYS 102443	Soil	0.9	38.9	29.5	66	<0.1	33.9	18.3	1150	3.38	17.3	1.2	2.8	9.2	8	0.2	1.0	0.3	26	0.07	0.048
KYS 102444	Soil	0.5	34.7	31.0	75	<0.1	33.6	18.5	957	3.17	10.9	1.2	2.0	13.8	11	0.1	0.7	0.4	17	0.16	0.049
KYS 102445	Soil	0.5	33.5	30.5	77	<0.1	33.8	17.5	955	3.12	10.4	1.2	3.1	13.6	11	0.1	0.7	0.4	17	0.15	0.050
KYS 102446	Soil	0.7	30.7	22.4	76	<0.1	26.0	10.5	479	2.99	12.5	2.2	2.3	5.0	19	0.2	0.8	0.4	27	0.25	0.047
KYS 102447	Soil	1.0	26.4	23.6	74	<0.1	24.3	11.8	568	2.94	11.8	1.0	9.4	6.9	11	0.2	1.7	0.3	25	0.13	0.044
KYS 102448	Soil	0.5	40.2	16.9	77	0.1	24.1	10.2	295	3.55	52.8	1.8	9.5	7.5	6	<0.1	2.0	0.4	5	0.07	0.027
KYS 102449	Soil	0.5	46.2	23.5	91	<0.1	31.2	14.0	504	4.04	57.3	1.9	7.8	9.2	9	<0.1	3.6	0.4	10	0.07	0.034
KYS 102450	Soil	1.0	44.6	32.1	68	0.3	24.3	14.4	883	4.36	30.9	1.6	3.0	5.7	8	<0.1	2.0	0.4	20	0.07	0.062
KYS 102451	Soil	0.6	32.6	23.8	66	0.1	27.1	12.8	712	2.87	49.5	1.2	9.3	9.6	10	0.1	5.1	0.3	18	0.13	0.038
KYS 102452	Soil	0.8	25.9	15.9	64	<0.1	18.8	9.1	584	2.57	18.7	0.9	9.5	4.2	9	0.1	5.3	0.2	28	0.08	0.050
KYS 102453	Soil	0.7	23.3	18.3	66	<0.1	19.7	8.6	438	2.79	81.2	1.0	11.8	3.5	10	<0.1	34.6	0.3	30	0.11	0.042
KYS 102454	Soil	1.1	16.5	14.0	48	<0.1	14.4	6.2	305	2.28	11.4	0.7	2.9	2.4	13	0.2	1.8	0.2	31	0.15	0.039
KYS 102455	Soil	0.9	15.4	19.1	45	<0.1	15.4	6.8	255	2.73	13.7	0.7	1.3	3.6	9	0.2	1.4	0.3	37	0.09	0.044
KYS 102456	Soil	0.5	39.2	17.2	67	0.2	25.2	8.4	366	2.58	59.6	1.2	45.7	8.1	16	<0.1	51.9	0.3	19	0.23	0.056
KYS 102457	Soil	0.5	21.6	15.8	64	<0.1	20.3	6.4	245	2.33	7.5	0.8	4.0	6.4	14	0.1	3.1	0.3	17	0.25	0.048
KYS 102459	Soil	1.5	39.3	23.4	97	<0.1	34.2	14.8	661	3.61	54.5	1.2	5.0	2.5	14	0.4	8.2	0.3	27	0.26	0.107
KYS 102460	Soil	1.4	33.4	22.6	81	0.1	30.5	13.6	607	3.17	74.6	1.1	7.1	4.9	20	0.3	6.6	0.3	31	0.50	0.085

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 102430	Soil	21	19	0.39	108	0.016	<1	1.17	0.005	0.05	<0.1	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 102431	Soil	18	23	0.60	75	0.012	<1	1.48	0.004	0.04	<0.1	0.04	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 102432	Soil	34	12	0.45	45	0.003	<1	1.04	0.003	0.06	<0.1	0.04	1.7	<0.1	<0.05	2	<0.5	<0.2
KYS 102433	Soil	33	15	0.56	49	0.006	<1	1.21	0.003	0.07	<0.1	0.03	1.6	<0.1	<0.05	3	<0.5	0.2
KYS 102434	Soil	18	17	0.25	97	0.032	1	0.85	0.003	0.08	0.2	0.02	1.1	<0.1	<0.05	5	<0.5	<0.2
KYS 102435	Soil	20	21	0.32	95	0.011	<1	1.18	0.002	0.03	0.1	0.05	1.0	<0.1	<0.05	4	1.0	0.3
KYS 102436	Soil	13	12	0.30	107	0.003	2	0.91	0.011	0.03	<0.1	0.06	1.2	<0.1	<0.05	2	0.8	<0.2
KYS 102437	Soil	12	26	0.32	176	0.015	2	1.42	0.007	0.04	0.1	0.06	0.9	<0.1	<0.05	5	0.8	0.2
KYS 102438	Soil	10	11	0.05	246	0.007	2	0.40	0.006	0.05	0.2	0.27	0.4	<0.1	<0.05	2	3.5	0.3
KYS 102439	Soil	17	26	0.46	244	0.012	2	1.32	0.006	0.03	<0.1	0.08	1.1	<0.1	<0.05	4	1.4	0.9
KYS 102440	Soil	19	14	0.36	153	0.008	2	0.94	0.007	0.05	<0.1	0.13	2.1	<0.1	<0.05	2	1.7	0.4
KYS 102441	Soil	18	14	0.57	185	0.004	2	1.01	0.006	0.04	<0.1	0.11	2.3	<0.1	<0.05	3	0.9	<0.2
KYS 102442	Soil	13	23	0.46	74	0.020	2	1.49	0.008	0.04	0.1	0.04	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 102443	Soil	22	21	0.44	57	0.018	2	1.23	0.007	0.05	0.1	0.03	1.4	<0.1	<0.05	4	0.6	0.3
KYS 102444	Soil	30	18	0.57	83	0.014	2	1.28	0.007	0.05	<0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 102445	Soil	30	18	0.56	82	0.017	1	1.20	0.006	0.05	<0.1	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 102446	Soil	24	22	0.50	84	0.017	1	1.30	0.008	0.06	0.1	0.02	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 102447	Soil	21	20	0.45	83	0.019	2	1.27	0.007	0.04	0.2	0.02	1.5	<0.1	<0.05	4	<0.5	0.2
KYS 102448	Soil	19	14	0.43	25	0.001	2	1.02	0.008	0.05	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 102449	Soil	21	18	0.49	55	0.003	2	1.22	0.011	0.07	<0.1	0.04	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 102450	Soil	17	19	0.38	35	0.011	2	1.27	0.007	0.05	0.1	0.05	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 102451	Soil	29	18	0.43	137	0.010	<1	1.35	0.007	0.05	<0.1	0.04	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 102452	Soil	23	20	0.46	125	0.021	2	1.28	0.007	0.05	0.3	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 102453	Soil	21	22	0.41	113	0.019	2	1.36	0.008	0.05	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 102454	Soil	13	18	0.28	99	0.025	1	0.85	0.008	0.05	0.1	0.02	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 102455	Soil	16	20	0.32	81	0.025	1	1.14	0.007	0.04	0.2	0.04	1.3	<0.1	<0.05	5	<0.5	<0.2
KYS 102456	Soil	27	19	0.52	134	0.009	1	1.33	0.007	0.06	<0.1	0.04	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 102457	Soil	23	16	0.44	101	0.026	2	1.13	0.007	0.05	0.1	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 102459	Soil	29	21	0.49	167	0.012	2	1.37	0.008	0.06	0.2	0.04	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 102460	Soil	22	24	0.65	141	0.016	2	1.36	0.011	0.05	0.2	0.03	2.1	<0.1	<0.05	4	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 102461	Soil		1.7	48.5	26.1	92	0.2	43.6	20.3	777	3.83	87.9	1.4	10.4	10.5	15	0.3	9.1	0.3	24	0.19	0.077
KYS 102462	Soil		1.5	45.4	17.5	88	0.1	45.3	20.9	809	4.88	33.0	0.9	2.9	3.7	17	0.2	6.0	0.3	48	0.18	0.092
KYS 102463	Soil		1.2	36.5	26.2	87	0.1	37.9	15.3	927	3.32	46.5	1.3	6.5	5.0	16	0.5	11.9	0.2	33	0.19	0.097
KYS 102464	Soil		1.3	35.3	16.1	93	<0.1	42.9	20.3	837	3.28	41.4	1.0	4.7	2.9	15	0.7	5.8	0.2	42	0.21	0.072
KYS 102465	Soil		0.7	48.9	31.7	86	<0.1	41.1	20.3	1505	3.69	36.0	0.9	2.4	20.3	5	0.3	5.3	0.4	11	0.11	0.054
KYS 102466	Soil		1.2	32.1	16.0	86	<0.1	27.0	8.6	363	3.03	47.0	1.1	5.5	2.5	12	0.2	6.0	0.2	28	0.19	0.081
KYS 102467	Soil		0.8	33.4	22.4	102	0.2	25.9	13.7	789	3.30	1777	1.0	216.2	11.0	5	0.3	20.0	0.2	6	0.06	0.046
KYS 102468	Soil		1.5	46.5	14.0	66	<0.1	19.8	8.4	710	3.24	15.4	0.7	12.0	0.9	12	0.2	1.5	0.3	55	0.07	0.068
KYS 102469	Soil		1.5	68.2	14.0	81	<0.1	27.6	10.1	825	2.94	17.9	0.8	23.4	1.5	13	0.2	3.4	0.2	45	0.11	0.068
KYS 102470	Soil		2.3	79.2	17.3	97	0.2	30.3	9.1	674	3.18	20.4	1.4	18.2	4.4	13	0.2	5.2	0.3	39	0.09	0.089
KYS 102471	Soil		2.1	69.8	16.4	83	0.2	27.2	12.5	685	2.64	25.6	1.2	8.9	5.5	9	0.3	5.0	0.2	28	0.07	0.070
KYS 102472	Soil		1.1	40.4	20.5	85	0.2	26.7	10.6	506	3.04	31.3	1.3	5.2	6.4	8	0.2	3.0	0.3	24	0.08	0.067
KYS 102473	Soil		0.7	37.7	20.0	66	<0.1	25.6	9.5	305	2.80	9.2	1.5	3.0	8.5	6	<0.1	1.5	0.3	20	0.07	0.044
KYS 102474	Soil		1.1	41.5	25.0	82	0.1	39.5	17.9	718	3.39	14.3	1.9	<0.5	7.9	12	0.2	1.9	0.3	28	0.24	0.062
KYS 102475	Soil		5.2	41.6	26.1	81	0.2	28.6	12.7	621	3.10	23.6	2.0	2.0	6.2	20	0.2	2.4	0.3	21	0.22	0.068
KYS 102476	Soil		4.5	41.7	25.0	90	0.2	33.6	12.4	509	3.37	114.2	2.4	6.2	5.5	18	0.2	3.1	0.4	23	0.14	0.054
KYS 102477	Soil		2.1	33.2	16.5	75	0.1	28.1	10.2	377	2.87	28.8	1.7	3.2	5.1	12	0.2	2.4	0.2	26	0.09	0.042
KYS 102478	Soil		1.7	40.2	23.0	85	0.1	32.9	13.4	532	3.28	62.2	2.2	3.7	11.0	15	0.2	2.9	0.3	21	0.12	0.047
KYS 102479	Soil		1.8	35.8	19.2	84	0.1	30.3	11.6	454	3.11	57.6	1.7	6.1	4.8	14	0.2	3.3	0.3	22	0.11	0.058
KYS 102480	Soil		1.9	31.2	19.4	82	<0.1	29.1	12.7	610	3.01	36.9	1.5	2.3	4.6	12	0.1	2.4	0.3	27	0.09	0.049
KYS 102481	Soil		1.3	46.9	26.5	97	0.1	39.0	15.8	697	3.45	22.5	1.8	<0.5	9.6	10	0.2	2.3	0.3	23	0.10	0.049
KYS 102482	Soil		1.7	33.6	16.3	75	<0.1	25.3	9.5	404	2.74	16.9	1.6	6.7	6.2	9	0.1	2.1	0.2	26	0.08	0.046
KYS 102483	Soil		1.7	39.1	20.3	93	0.2	31.4	12.9	533	3.27	14.0	1.6	1.3	6.8	10	0.3	2.0	0.3	26	0.10	0.062
KYS 102484	Soil		1.5	51.5	11.8	51	<0.1	21.2	7.5	774	2.41	13.9	0.6	12.2	1.3	8	<0.1	1.5	0.2	45	0.05	0.040
KYS 102485	Soil		1.5	78.5	16.7	67	0.2	36.6	12.3	1597	2.48	12.0	0.8	15.9	3.0	16	0.2	1.2	0.3	37	0.08	0.052
KYS 102486	Soil		2.1	153.4	27.7	92	0.3	58.2	19.7	3821	3.14	21.9	1.1	24.3	5.2	29	0.2	1.5	0.4	37	0.13	0.093
KYS 102487	Soil		1.8	139.0	19.7	162	0.2	90.9	29.1	2793	3.64	116.9	2.5	12.6	6.8	32	0.2	8.1	0.2	26	0.15	0.075
KYS 102488	Soil		1.7	125.2	19.9	77	0.2	38.3	12.4	1877	2.91	19.1	1.0	33.5	1.2	16	<0.1	1.8	0.4	36	0.07	0.097
KYS 102489	Soil		3.7	180.7	28.9	100	0.3	58.7	23.0	3488	3.40	45.1	1.3	26.1	6.7	38	0.1	3.3	0.3	29	0.14	0.081
KYS 102490	Soil		5.6	187.6	38.7	169	0.5	79.3	25.2	2855	4.40	337.5	1.9	33.1	9.9	45	0.8	11.4	0.4	24	0.15	0.088

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 102461	Soil		30	23	0.67	120	0.012	2	1.39	0.009	0.06	0.1	0.04	2.8	<0.1	<0.05	4	0.7	<0.2
KYS 102462	Soil		20	37	0.84	123	0.012	1	1.76	0.009	0.05	0.1	0.03	3.9	<0.1	<0.05	6	0.6	<0.2
KYS 102463	Soil		28	24	0.47	183	0.027	1	1.38	0.010	0.05	0.2	0.04	3.2	<0.1	<0.05	4	0.9	<0.2
KYS 102464	Soil		18	28	0.60	133	0.024	1	1.53	0.010	0.04	0.2	0.02	2.9	<0.1	<0.05	4	0.7	<0.2
KYS 102465	Soil		48	17	0.58	84	0.006	1	1.43	0.006	0.09	<0.1	0.02	2.1	<0.1	<0.05	4	<0.5	<0.2
KYS 102466	Soil		30	23	0.51	151	0.012	2	1.56	0.008	0.05	0.1	0.03	1.7	<0.1	<0.05	4	0.5	<0.2
KYS 102467	Soil		24	8	0.11	88	0.004	1	0.47	0.007	0.05	<0.1	0.03	1.6	<0.1	<0.05	1	0.6	<0.2
KYS 102468	Soil		18	28	0.34	90	0.036	2	1.32	0.008	0.04	0.3	0.04	1.3	<0.1	<0.05	6	0.9	<0.2
KYS 102469	Soil		17	25	0.42	110	0.032	2	1.31	0.008	0.04	0.2	0.05	1.5	<0.1	<0.05	5	0.6	<0.2
KYS 102470	Soil		25	25	0.43	127	0.030	1	1.38	0.008	0.05	0.1	0.05	2.4	<0.1	<0.05	4	1.0	<0.2
KYS 102471	Soil		27	17	0.39	120	0.020	1	1.13	0.007	0.04	0.1	0.05	2.1	<0.1	<0.05	4	1.0	<0.2
KYS 102472	Soil		31	20	0.51	100	0.015	1	1.50	0.008	0.06	0.1	0.04	2.0	<0.1	<0.05	4	0.6	<0.2
KYS 102473	Soil		22	18	0.44	76	0.009	<1	1.20	0.003	0.04	<0.1	0.02	1.9	<0.1	<0.05	3	0.6	<0.2
KYS 102474	Soil		16	27	0.79	89	0.014	2	1.48	0.003	0.05	<0.1	0.05	2.8	<0.1	<0.05	4	0.8	<0.2
KYS 102475	Soil		16	17	0.49	105	0.005	<1	1.17	0.004	0.05	<0.1	0.06	1.7	<0.1	<0.05	4	0.9	0.2
KYS 102476	Soil		16	16	0.38	88	0.008	<1	1.12	0.004	0.04	0.2	0.06	1.6	<0.1	<0.05	3	1.3	<0.2
KYS 102477	Soil		18	19	0.43	81	0.018	<1	1.19	0.004	0.04	0.1	0.03	1.8	<0.1	<0.05	3	0.7	<0.2
KYS 102478	Soil		27	18	0.54	80	0.014	<1	1.25	0.005	0.05	<0.1	0.03	1.8	<0.1	<0.05	4	0.7	<0.2
KYS 102479	Soil		18	19	0.47	98	0.010	1	1.20	0.004	0.05	<0.1	0.02	1.5	<0.1	<0.05	3	1.0	<0.2
KYS 102480	Soil		18	20	0.48	87	0.013	<1	1.25	0.004	0.04	0.1	0.03	1.8	<0.1	<0.05	4	0.7	0.4
KYS 102481	Soil		26	27	0.66	106	0.009	<1	1.50	0.003	0.05	<0.1	0.03	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 102482	Soil		22	19	0.49	85	0.014	<1	1.33	0.003	0.04	0.1	0.03	1.7	<0.1	<0.05	4	0.7	<0.2
KYS 102483	Soil		20	21	0.61	142	0.010	<1	1.50	0.003	0.05	<0.1	0.04	2.0	<0.1	<0.05	5	<0.5	0.2
KYS 102484	Soil		15	22	0.36	87	0.022	<1	1.26	0.004	0.03	0.2	0.06	1.3	<0.1	<0.05	4	<0.5	0.4
KYS 102485	Soil		19	23	0.42	105	0.023	<1	1.27	0.005	0.03	0.1	0.09	1.3	<0.1	<0.05	4	0.7	<0.2
KYS 102486	Soil		23	24	0.50	113	0.016	<1	1.36	0.006	0.04	0.1	0.11	1.5	<0.1	<0.05	4	1.0	<0.2
KYS 102487	Soil		17	16	0.39	116	0.008	<1	1.39	0.005	0.02	<0.1	0.04	3.5	<0.1	<0.05	3	0.8	<0.2
KYS 102488	Soil		19	22	0.41	99	0.010	<1	1.32	0.005	0.03	<0.1	0.10	1.0	<0.1	<0.05	4	0.7	0.4
KYS 102489	Soil		28	18	0.51	138	0.007	<1	1.19	0.004	0.04	0.1	0.10	1.7	<0.1	<0.05	4	1.4	0.2
KYS 102490	Soil		35	16	0.33	128	0.004	<1	0.98	0.006	0.05	<0.1	0.11	2.4	<0.1	<0.05	2	1.6	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 102491	Soil		5.1	71.3	35.6	115	0.6	51.5	17.2	991	3.70	26.2	2.0	5.7	7.3	44	0.6	3.6	0.5	17	0.79	0.048
KYS 102492	Soil		5.5	902.9	54.3	218	0.6	238.2	112.5	>10000	4.23	47.6	4.6	117.5	8.3	31	1.0	13.3	0.6	30	0.07	0.140
KYS 102493	Soil		2.3	221.9	28.2	97	0.3	62.5	29.9	4978	3.53	22.0	0.8	70.0	4.2	28	0.1	2.7	0.3	32	0.10	0.089
KYS 102494	Soil		2.4	225.9	29.0	96	0.2	60.7	28.9	4930	3.62	22.7	0.8	58.6	4.3	27	<0.1	2.7	0.3	34	0.11	0.098
KYS 102495	Soil		1.8	269.2	27.6	111	0.2	71.4	30.2	5158	3.73	20.0	1.0	35.3	7.1	28	0.2	1.8	0.3	33	0.11	0.069
KYS 102496	Soil		2.3	224.8	45.4	131	0.2	82.8	30.2	5250	4.28	36.3	1.3	12.6	5.7	20	0.1	12.3	0.5	38	0.06	0.066
KYS 102497	Soil		1.7	155.3	28.7	106	0.1	62.4	25.9	4335	3.75	22.5	1.4	23.3	5.2	17	<0.1	5.9	0.4	34	0.06	0.068
KYS 102498	Soil		1.1	48.9	38.6	94	0.2	49.0	24.4	1694	4.61	759.5	1.4	124.0	10.1	15	0.5	12.8	0.2	22	0.23	0.112
KYS 102499	Soil		1.1	54.1	35.3	102	0.3	54.2	27.0	1820	4.98	952.0	1.4	158.3	9.1	16	0.5	14.2	0.2	24	0.25	0.125
KYS 102500	Soil		1.4	31.8	17.9	96	<0.1	29.8	13.3	567	2.88	176.9	1.0	20.6	7.4	10	0.3	7.0	0.2	26	0.12	0.078
KYS 105681	Soil		1.6	17.6	13.3	54	<0.1	16.2	5.8	197	2.62	13.3	1.0	2.3	1.9	11	<0.1	0.8	0.2	49	0.11	0.075
KYS 105682	Soil		1.5	33.6	21.9	55	0.2	26.1	9.0	254	2.90	42.4	0.9	4.3	5.0	7	0.2	1.7	0.3	27	0.05	0.063
KYS 105750	Soil		1.4	37.2	23.6	71	0.2	29.4	11.0	466	2.98	34.5	1.1	4.8	7.3	10	0.2	1.8	0.3	25	0.08	0.083
KYS 105800	Soil		1.0	22.3	13.0	62	<0.1	21.3	8.9	291	2.49	22.2	1.0	1.2	2.3	10	0.1	4.0	0.2	36	0.09	0.049
KYS 105801	Soil		0.9	19.7	14.8	51	<0.1	18.1	6.9	201	2.23	16.1	0.9	1.3	1.8	8	0.1	4.0	0.2	30	0.06	0.044
KYS 105802	Soil		0.8	19.9	11.6	64	<0.1	20.2	8.6	294	2.24	12.5	0.9	5.6	4.3	12	0.1	2.5	0.2	33	0.16	0.067
KYS 105803	Soil		0.8	29.8	23.6	67	0.2	26.2	13.1	397	2.56	365.0	1.5	42.8	4.0	11	0.1	16.7	0.2	17	0.07	0.055
KYS 105804	Soil		3.8	95.2	32.4	137	0.4	69.6	35.7	1481	3.98	71.9	2.6	7.2	8.6	28	0.5	29.0	0.4	24	0.22	0.133
KYS 105805	Soil		2.2	50.4	26.4	89	0.2	44.5	17.0	802	3.41	26.1	2.1	5.0	6.0	20	0.4	7.0	0.3	19	0.23	0.094
KYS 105806	Soil		2.1	51.3	18.3	81	0.2	38.2	12.8	581	3.21	21.0	2.2	4.4	5.5	17	0.2	6.8	0.2	16	0.24	0.100
KYS 105807	Soil		0.9	42.4	26.4	69	<0.1	33.2	15.5	648	3.03	22.6	1.5	3.1	12.2	13	0.2	6.2	0.4	11	0.18	0.070
KYS 105808	Soil		1.9	44.6	20.9	84	0.2	36.1	13.1	531	3.13	21.6	1.8	3.3	7.0	14	0.4	8.3	0.3	21	0.19	0.090
KYS 105809	Soil		0.9	22.5	27.6	55	<0.1	17.1	10.3	502	2.41	38.4	1.5	5.8	2.7	12	0.2	6.9	0.3	21	0.14	0.047
KYS 105810	Soil		0.5	38.6	33.2	69	0.1	35.8	18.3	531	2.96	59.8	1.7	3.7	8.8	12	0.2	5.4	0.4	17	0.14	0.053
KYS 105811	Soil		0.4	34.0	29.6	65	0.1	32.3	15.4	492	2.79	41.1	1.6	4.5	11.5	16	0.1	3.6	0.4	13	0.20	0.047
KYS 105812	Soil		0.3	45.9	36.3	61	<0.1	32.5	18.9	918	2.93	34.2	1.1	1.5	17.4	16	0.1	2.0	0.5	10	0.23	0.047
KYS 105813	Soil		0.3	40.5	29.5	66	<0.1	32.9	15.7	479	3.05	24.0	1.5	0.7	15.7	15	<0.1	1.6	0.4	9	0.23	0.043
KYS 105814	Soil		0.5	46.4	29.8	75	<0.1	30.7	11.1	334	3.39	20.0	2.3	2.0	9.0	20	<0.1	1.4	0.5	13	0.30	0.047
KYS 105815	Soil		0.4	33.3	25.6	68	<0.1	26.1	9.6	232	2.92	7.8	1.7	0.8	10.8	25	<0.1	0.6	0.4	10	0.41	0.045
KYS 105816	Soil		0.4	42.9	27.6	70	<0.1	31.8	14.8	409	3.12	7.1	1.3	0.9	15.2	20	0.1	0.8	0.4	8	0.33	0.038

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 102491	Soil	14	9	0.29	134	0.001	<1	0.75	0.004	0.04	<0.1	0.14	2.1	<0.1	0.08	1	2.9	<0.2
KYS 102492	Soil	23	18	0.43	224	0.005	<1	2.60	0.007	0.05	<0.1	0.15	2.5	<0.1	0.07	4	2.4	1.4
KYS 102493	Soil	27	18	0.73	144	0.006	<1	1.52	0.004	0.03	<0.1	0.07	1.3	<0.1	<0.05	5	0.8	0.4
KYS 102494	Soil	27	19	0.76	147	0.006	<1	1.57	0.004	0.03	<0.1	0.07	1.4	<0.1	<0.05	5	0.5	0.2
KYS 102495	Soil	28	22	0.80	152	0.005	<1	1.70	0.003	0.03	<0.1	0.10	1.7	<0.1	<0.05	4	0.9	<0.2
KYS 102496	Soil	23	25	0.68	296	0.002	<1	1.81	0.005	0.04	<0.1	0.09	1.9	<0.1	<0.05	5	1.0	<0.2
KYS 102497	Soil	24	24	0.69	150	0.003	<1	1.70	0.003	0.03	<0.1	0.10	1.5	<0.1	<0.05	5	0.7	0.2
KYS 102498	Soil	28	17	0.54	227	0.012	<1	1.17	0.004	0.04	<0.1	0.05	4.7	<0.1	<0.05	5	0.6	<0.2
KYS 102499	Soil	27	18	0.57	249	0.011	<1	1.26	0.005	0.04	0.1	0.04	5.1	<0.1	<0.05	5	0.6	<0.2
KYS 102500	Soil	21	19	0.41	65	0.020	<1	1.11	0.004	0.04	0.2	0.01	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 105681	Soil	13	27	0.36	107	0.025	1	1.76	0.005	0.05	0.2	0.06	2.1	0.1	<0.05	5	1.1	<0.2
KYS 105682	Soil	15	21	0.29	73	0.009	<1	1.28	0.004	0.04	<0.1	0.05	1.3	<0.1	<0.05	3	0.9	<0.2
KYS 105750	Soil	17	22	0.32	74	0.012	<1	1.19	0.004	0.05	<0.1	0.05	1.7	<0.1	<0.05	3	0.9	<0.2
KYS 105800	Soil	16	20	0.35	85	0.024	<1	1.15	0.004	0.04	0.2	0.02	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 105801	Soil	16	15	0.24	83	0.018	<1	0.87	0.003	0.03	<0.1	0.02	1.0	<0.1	<0.05	3	<0.5	<0.2
KYS 105802	Soil	17	18	0.31	66	0.036	<1	0.96	0.005	0.04	0.3	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 105803	Soil	20	11	0.18	80	0.009	<1	0.65	0.003	0.04	0.1	0.04	1.3	<0.1	<0.05	2	<0.5	<0.2
KYS 105804	Soil	26	18	0.46	71	0.013	1	1.12	0.004	0.04	0.1	0.06	2.3	<0.1	<0.05	3	0.5	<0.2
KYS 105805	Soil	20	18	0.44	67	0.008	1	1.09	0.004	0.04	<0.1	0.05	1.5	<0.1	<0.05	3	0.5	<0.2
KYS 105806	Soil	21	15	0.45	75	0.005	<1	0.97	0.003	0.03	<0.1	0.05	1.7	<0.1	<0.05	2	<0.5	0.3
KYS 105807	Soil	21	10	0.32	82	0.012	1	0.70	0.004	0.04	<0.1	0.02	1.6	<0.1	<0.05	2	<0.5	<0.2
KYS 105808	Soil	22	16	0.48	83	0.009	<1	1.12	0.004	0.03	<0.1	0.04	2.0	<0.1	<0.05	3	<0.5	<0.2
KYS 105809	Soil	12	10	0.22	97	0.012	1	0.73	0.004	0.06	0.1	0.03	0.8	<0.1	<0.05	3	<0.5	<0.2
KYS 105810	Soil	22	13	0.41	67	0.011	<1	0.95	0.004	0.07	0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 105811	Soil	25	12	0.44	66	0.010	1	1.04	0.007	0.09	<0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 105812	Soil	29	11	0.51	54	0.008	<1	1.06	0.003	0.06	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 105813	Soil	28	12	0.47	44	0.004	<1	1.04	0.004	0.06	<0.1	0.02	1.4	<0.1	<0.05	3	0.6	<0.2
KYS 105814	Soil	21	16	0.57	77	0.006	1	1.38	0.005	0.08	<0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 105815	Soil	24	12	0.47	67	0.004	1	1.13	0.004	0.09	<0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 105816	Soil	29	10	0.48	48	0.003	<1	0.94	0.003	0.09	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 105817	Soil	0.3	30.0	27.2	57	<0.1	24.6	10.0	288	2.61	5.4	1.9	1.4	12.5	23	<0.1	0.8	0.3	8	0.39	0.033
KYS 105818	Soil	0.3	34.0	26.1	61	<0.1	27.9	10.9	330	2.73	6.0	1.7	1.2	13.4	19	<0.1	0.7	0.3	8	0.31	0.040
KYS 105819	Soil	0.5	33.7	28.3	67	<0.1	30.7	12.2	444	2.87	7.9	1.7	3.4	11.2	14	<0.1	0.8	0.4	14	0.17	0.042
KYS 105820	Soil	1.0	11.5	15.0	37	<0.1	12.0	5.5	206	1.95	6.3	0.8	4.9	0.3	9	0.1	0.6	0.3	32	0.07	0.059
KYS 105821	Soil	0.8	28.4	20.2	66	<0.1	25.5	11.0	456	2.74	7.2	1.4	5.5	4.5	9	0.2	0.7	0.3	26	0.10	0.058
KYS 105822	Soil	0.8	26.8	20.4	105	0.1	27.6	13.9	585	3.43	15.1	2.3	2.7	2.3	16	0.3	4.3	0.4	19	0.23	0.057
KYS 105823	Soil	0.5	25.2	15.6	87	0.1	38.2	11.2	361	2.92	10.0	7.2	2.2	2.3	30	0.1	3.5	0.3	18	0.43	0.054
KYS 105824	Soil	0.8	25.5	16.6	67	0.1	23.7	11.0	484	2.56	9.7	3.4	2.0	1.6	41	0.2	1.6	0.3	22	0.52	0.057
KYS 105825	Soil	0.8	16.4	16.2	59	<0.1	19.5	8.4	363	2.35	10.3	1.2	<0.5	3.4	15	0.1	0.9	0.2	36	0.16	0.060
KYS 105826	Soil	1.0	16.0	15.8	60	<0.1	21.5	10.2	482	2.44	11.5	1.7	4.4	2.9	15	0.2	1.2	0.2	40	0.16	0.053
KYS 105827	Soil	0.8	28.1	17.7	70	<0.1	26.8	10.1	416	2.59	13.3	1.9	8.9	5.7	19	0.2	1.7	0.2	38	0.25	0.066
KYS 105828	Soil	0.8	19.5	19.8	56	<0.1	22.0	8.5	305	2.52	11.6	1.2	2.2	4.6	14	0.1	1.5	0.3	35	0.16	0.049
KYS 105829	Soil	0.7	26.5	25.1	56	<0.1	20.3	9.8	420	2.58	7.0	1.4	1.5	6.1	17	<0.1	0.9	0.3	17	0.28	0.053
KYS 105830	Soil	0.8	26.1	25.7	55	<0.1	20.9	9.2	430	2.60	7.2	1.4	1.8	6.7	16	0.1	1.0	0.3	16	0.24	0.049
KYS 105831	Soil	6.7	45.2	28.3	143	0.2	45.8	12.4	351	3.45	13.4	3.2	3.0	3.5	26	0.8	11.3	0.4	10	0.13	0.052
KYS 105832	Soil	1.7	40.4	25.4	88	0.1	32.4	13.3	492	3.83	30.7	2.4	4.7	8.4	14	0.1	2.9	0.4	8	0.09	0.040
KYS 105833	Soil	0.5	34.5	27.5	73	<0.1	27.7	13.7	518	3.10	159.4	1.9	13.0	10.3	14	0.2	7.6	0.3	6	0.17	0.038
KYS 105834	Soil	1.2	55.0	30.7	113	0.2	46.6	17.8	829	4.23	68.4	2.4	10.9	8.1	18	0.6	8.7	0.4	10	0.24	0.053
KYS 105835	Soil	0.8	43.4	22.4	98	0.1	38.7	15.2	556	3.28	11.2	2.7	2.5	6.2	10	0.6	1.5	0.4	7	0.15	0.036
KYS 105836	Soil	0.8	40.0	22.7	94	0.1	34.0	11.8	476	3.37	49.7	2.0	8.9	8.9	13	0.4	6.9	0.3	8	0.20	0.040
KYS 105837	Soil	3.0	37.3	21.3	84	0.1	30.1	11.7	430	3.18	13.7	2.3	1.8	6.9	17	0.3	2.9	0.3	11	0.11	0.043
KYS 105838	Soil	3.7	100.8	15.9	75	0.3	19.9	4.1	283	2.38	14.0	1.0	25.4	1.3	17	0.2	8.8	0.3	12	0.01	0.056
KYS 105839	Soil	1.3	220.7	27.4	98	0.4	47.3	16.2	1167	3.51	33.3	1.9	26.0	3.4	28	0.3	2.4	0.3	25	0.08	0.059
KYS 105840	Soil	9.0	84.3	19.9	61	0.4	13.4	3.0	404	3.17	5.4	1.7	9.2	1.7	84	0.2	2.4	0.3	17	0.03	0.069
KYS 105841	Soil	2.3	73.9	13.8	67	0.2	23.8	9.0	1105	2.49	8.7	1.0	19.1	0.5	9	0.2	1.7	0.3	32	0.02	0.070
KYS 105842	Soil	4.1	52.2	18.8	65	0.4	19.7	7.8	351	2.83	10.2	1.5	6.8	0.8	32	0.3	1.8	0.3	30	0.06	0.073
KYS 105843	Soil	4.8	45.6	14.7	51	0.2	16.0	4.7	447	2.05	17.0	1.1	5.1	0.2	9	0.1	5.7	0.3	21	0.03	0.074
KYS 105844	Soil	7.0	43.7	21.6	85	0.2	26.2	9.5	435	2.83	14.9	2.3	3.1	2.5	18	0.3	4.2	0.3	12	0.08	0.060
KYS 105845	Soil	2.0	129.1	25.8	63	0.3	22.4	7.3	432	2.84	12.9	1.0	18.1	1.5	9	0.2	1.9	0.3	32	0.03	0.067
KYS 105846	Soil	5.7	128.1	30.7	87	0.4	27.4	7.4	405	3.83	15.6	2.2	13.8	1.0	62	0.3	2.4	0.5	33	0.04	0.103

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 105817	Soil	25	7	0.34	65	0.003	2	0.83	0.002	0.13	<0.1	0.03	1.1	<0.1	<0.05	2	<0.5	<0.2
KYS 105818	Soil	27	10	0.42	59	0.005	1	0.96	0.004	0.10	<0.1	0.03	1.2	<0.1	<0.05	2	<0.5	<0.2
KYS 105819	Soil	26	12	0.40	70	0.009	<1	1.02	0.004	0.07	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	0.3
KYS 105820	Soil	15	17	0.28	57	0.010	<1	1.14	0.005	0.04	<0.1	0.03	0.4	<0.1	<0.05	4	<0.5	0.3
KYS 105821	Soil	30	18	0.44	84	0.023	<1	1.42	0.005	0.05	<0.1	0.03	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 105822	Soil	12	16	0.45	101	0.005	<1	1.33	0.006	0.05	<0.1	0.02	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 105823	Soil	12	17	0.45	83	0.010	<1	1.21	0.007	0.05	<0.1	0.03	1.7	<0.1	<0.05	3	0.5	<0.2
KYS 105824	Soil	12	16	0.40	73	0.012	1	1.10	0.006	0.04	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 105825	Soil	17	21	0.43	93	0.024	<1	1.29	0.006	0.04	0.2	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 105826	Soil	18	24	0.44	118	0.023	<1	1.46	0.006	0.05	0.2	0.03	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 105827	Soil	22	22	0.47	118	0.035	1	1.32	0.007	0.06	0.2	0.05	2.3	<0.1	<0.05	4	<0.5	<0.2
KYS 105828	Soil	22	20	0.42	106	0.022	<1	1.35	0.005	0.05	0.2	0.02	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 105829	Soil	24	12	0.33	114	0.008	<1	1.05	0.005	0.08	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 105830	Soil	25	12	0.32	113	0.008	<1	0.99	0.004	0.08	0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 105831	Soil	15	9	0.31	65	0.002	<1	0.86	0.004	0.04	<0.1	0.05	1.2	<0.1	<0.05	2	0.8	<0.2
KYS 105832	Soil	21	10	0.35	47	0.003	<1	0.98	0.005	0.06	<0.1	0.02	1.4	<0.1	<0.05	2	<0.5	<0.2
KYS 105833	Soil	24	8	0.30	31	0.002	<1	0.68	0.003	0.06	<0.1	0.01	1.1	<0.1	<0.05	2	<0.5	<0.2
KYS 105834	Soil	19	11	0.37	51	0.004	1	0.81	0.004	0.05	<0.1	0.03	1.8	<0.1	<0.05	2	0.5	<0.2
KYS 105835	Soil	13	9	0.34	32	0.003	<1	0.82	0.003	0.03	<0.1	0.02	1.4	<0.1	<0.05	2	<0.5	<0.2
KYS 105836	Soil	22	11	0.38	49	0.002	<1	0.95	0.003	0.05	<0.1	0.03	1.3	<0.1	<0.05	2	<0.5	<0.2
KYS 105837	Soil	18	10	0.34	42	0.007	<1	0.83	0.004	0.04	<0.1	0.03	1.2	<0.1	<0.05	2	0.6	<0.2
KYS 105838	Soil	19	6	0.06	287	0.008	<1	0.32	0.003	0.03	<0.1	0.04	0.6	<0.1	<0.05	1	1.0	0.3
KYS 105839	Soil	17	17	0.47	380	0.010	<1	1.15	0.004	0.04	<0.1	0.06	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 105840	Soil	13	9	0.14	337	0.006	<1	0.46	0.008	0.06	<0.1	0.13	0.6	<0.1	0.18	2	1.1	<0.2
KYS 105841	Soil	10	14	0.12	136	0.015	1	0.73	0.003	0.03	0.2	0.07	0.4	<0.1	0.06	3	0.6	<0.2
KYS 105842	Soil	8	18	0.20	253	0.013	<1	0.94	0.007	0.04	0.2	0.11	0.7	<0.1	<0.05	3	0.9	<0.2
KYS 105843	Soil	6	8	0.09	233	0.005	<1	0.63	0.004	0.03	0.1	0.06	0.2	<0.1	<0.05	2	<0.5	<0.2
KYS 105844	Soil	10	9	0.19	179	0.003	<1	0.69	0.002	0.03	<0.1	0.08	0.9	<0.1	<0.05	2	0.8	<0.2
KYS 105845	Soil	13	20	0.38	77	0.011	<1	1.14	0.003	0.03	0.1	0.07	0.7	<0.1	<0.05	4	0.8	<0.2
KYS 105846	Soil	14	20	0.32	596	0.008	<1	1.31	0.005	0.05	0.1	0.13	0.8	<0.1	<0.05	4	1.3	0.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 105847	Soil		21.2	99.2	23.1	396	0.8	92.3	15.8	1267	3.16	15.5	4.5	4.0	4.6	20	2.8	3.8	0.3	29	0.06	0.086
KYS 105848	Soil		1.4	54.6	16.1	57	0.3	29.1	12.9	752	2.86	10.4	0.9	8.6	3.8	12	0.9	1.0	0.2	34	0.13	0.069
KYS 105849	Soil		3.6	90.6	25.1	103	0.3	41.1	18.8	1278	3.96	11.4	1.6	9.3	8.4	23	0.3	0.9	0.4	17	0.19	0.075
KYS 105850	Soil		3.6	56.5	23.2	113	0.2	35.3	13.9	850	3.24	11.9	1.8	4.5	3.9	29	0.6	1.6	0.3	29	0.27	0.087
KYS 105851	Soil		2.9	45.4	21.3	109	0.2	33.7	13.5	675	3.51	132.8	1.2	30.7	3.7	14	0.3	39.2	0.3	24	0.15	0.067
KYS 105852	Soil		1.9	56.0	27.8	100	0.2	36.9	15.6	627	3.66	153.0	1.6	21.9	6.3	18	0.3	51.5	0.3	17	0.19	0.074
KYS 105853	Soil		1.3	105.7	29.9	88	0.5	32.7	12.6	851	3.10	617.8	1.2	134.4	8.2	20	0.2	459.4	0.3	17	0.16	0.051
KYS 105854	Soil		1.6	145.6	21.8	74	0.4	37.1	14.4	1142	2.62	169.4	1.3	48.4	0.7	38	0.2	33.7	0.3	24	0.31	0.091
KYS 105855	Soil		1.7	112.9	16.6	74	0.2	30.1	10.1	579	3.01	28.0	0.8	16.7	2.3	11	0.2	8.9	0.3	40	0.04	0.050
KYS 105856	Soil		1.3	248.8	32.1	88	0.4	52.1	21.7	1183	3.09	48.2	1.4	60.0	3.9	18	0.1	18.0	0.4	38	0.09	0.075
KYS 105857	Soil		5.4	141.2	25.3	89	0.5	35.4	12.0	795	3.61	23.7	1.4	25.8	4.6	29	0.2	16.1	0.4	39	0.08	0.094
KYS 105858	Soil		2.3	117.8	23.0	81	0.2	32.3	8.7	463	3.33	23.0	0.9	16.6	1.3	13	0.2	8.7	0.4	43	0.06	0.077
KYS 105859	Soil		3.7	143.2	22.1	96	0.2	34.8	12.1	559	3.34	17.9	1.3	29.3	3.0	17	0.3	8.6	0.3	39	0.08	0.076
KYS 105860	Soil		4.0	142.8	16.6	100	0.3	41.8	14.0	1169	2.83	17.3	1.6	29.7	4.1	21	0.4	6.2	0.2	42	0.15	0.101
KYS 105861	Soil		0.7	42.7	22.4	83	<0.1	32.8	14.9	593	3.43	25.0	1.0	4.7	8.5	9	<0.1	2.3	0.3	27	0.11	0.045
KYS 105862	Soil		0.5	69.1	25.1	92	<0.1	43.5	23.4	767	4.33	21.4	0.9	2.9	17.7	7	<0.1	1.3	0.4	16	0.13	0.051
KYS 105863	Soil		0.4	49.2	30.4	105	<0.1	71.1	31.5	1465	3.98	94.4	1.9	7.2	14.8	12	0.1	3.4	0.4	5	0.11	0.044
KYS 105864	Soil		0.3	54.8	28.4	93	<0.1	66.0	29.4	720	4.10	10.5	1.6	2.2	23.4	16	<0.1	0.3	0.5	6	0.17	0.038
KYS 105865	Soil		0.4	49.1	27.3	88	<0.1	60.6	26.3	696	4.04	8.5	1.4	1.9	22.9	14	<0.1	0.4	0.5	7	0.19	0.041
KYS 105866	Soil		1.3	63.5	29.9	71	<0.1	39.4	19.7	1107	3.68	22.3	1.4	3.6	8.0	49	0.1	0.3	0.5	6	4.57	0.066
KYS 105867	Soil		0.4	35.3	33.7	74	0.3	41.0	16.3	927	3.64	36.6	1.0	10.6	8.7	43	<0.1	3.7	0.3	5	1.19	0.041
KYS 105868	Soil		0.5	37.6	34.4	81	0.3	43.0	17.5	988	3.89	38.6	1.0	11.1	9.2	46	<0.1	4.1	0.3	5	1.23	0.043
KYS 105869	Soil		10.8	37.9	20.0	111	0.2	32.9	10.6	327	2.80	11.3	3.1	4.4	1.1	24	0.5	2.3	0.2	36	0.09	0.071
KYS 105870	Soil		1.0	57.0	22.9	121	0.2	49.8	17.9	597	3.61	19.1	2.9	3.4	3.9	42	1.0	4.9	0.2	19	0.08	0.078
KYS 105871	Soil		3.3	67.4	29.9	113	0.2	40.4	16.9	502	4.20	10.2	2.5	5.2	3.4	25	0.5	2.5	0.4	19	0.10	0.078
KYS 105872	Soil		1.1	31.2	20.8	86	<0.1	34.8	13.3	711	3.40	9.9	0.8	1.6	2.9	10	0.2	3.1	0.2	26	0.17	0.045
KYS 105873	Soil		1.5	47.2	32.1	124	0.2	46.1	20.4	1276	4.33	12.8	1.2	1.6	9.8	18	0.7	2.8	0.3	18	0.38	0.051
KYS 105874	Soil		4.7	88.4	40.6	195	0.2	79.6	34.0	1658	4.96	10.0	2.2	1.0	19.1	27	1.6	3.8	0.5	11	0.74	0.085
KYS 105875	Soil		6.1	54.9	37.3	219	0.2	62.4	21.6	1030	4.04	13.5	1.6	4.2	12.2	20	1.5	4.5	0.4	7	0.17	0.063
KYS 105876	Soil		7.5	62.3	34.8	171	0.2	62.7	22.2	620	4.84	8.5	3.2	0.8	11.2	15	1.0	3.9	0.4	8	0.10	0.064

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 105847	Soil	23	7	0.12	176	0.004	<1	0.57	0.002	0.03	0.1	0.53	1.5	<0.1	<0.05	1	3.0	<0.2
KYS 105848	Soil	11	23	0.28	86	0.029	1	1.35	0.004	0.04	0.2	0.06	1.5	<0.1	<0.05	3	0.6	<0.2
KYS 105849	Soil	22	14	0.51	124	0.007	1	1.23	0.002	0.06	<0.1	0.10	1.7	<0.1	<0.05	3	0.8	<0.2
KYS 105850	Soil	20	19	0.44	228	0.010	1	1.28	0.004	0.04	<0.1	0.10	1.7	<0.1	<0.05	4	0.9	<0.2
KYS 105851	Soil	18	18	0.45	218	0.005	<1	1.39	0.004	0.04	<0.1	0.05	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 105852	Soil	19	16	0.52	110	0.012	<1	1.25	0.003	0.05	<0.1	0.05	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 105853	Soil	27	14	0.39	122	0.004	<1	1.01	0.003	0.06	<0.1	0.08	1.5	<0.1	<0.05	3	<0.5	0.4
KYS 105854	Soil	13	14	0.21	274	0.005	1	0.72	0.005	0.04	<0.1	0.09	0.4	<0.1	0.05	3	<0.5	0.5
KYS 105855	Soil	17	24	0.43	97	0.012	1	1.38	0.004	0.03	0.1	0.06	1.0	<0.1	<0.05	4	<0.5	0.4
KYS 105856	Soil	20	24	0.55	99	0.019	1	1.35	0.004	0.05	0.2	0.07	1.8	<0.1	<0.05	4	0.7	0.5
KYS 105857	Soil	21	23	0.40	247	0.017	1	1.28	0.005	0.06	0.1	0.05	1.4	<0.1	<0.05	4	1.7	0.5
KYS 105858	Soil	18	26	0.52	169	0.013	<1	1.36	0.005	0.05	0.2	0.09	0.8	<0.1	<0.05	5	<0.5	0.5
KYS 105859	Soil	22	24	0.49	147	0.010	1	1.39	0.003	0.04	0.2	0.09	1.2	<0.1	<0.05	4	1.1	0.2
KYS 105860	Soil	20	23	0.47	170	0.022	1	1.18	0.003	0.05	0.2	0.14	1.7	<0.1	<0.05	4	1.2	0.3
KYS 105861	Soil	23	22	0.56	115	0.011	<1	1.55	0.005	0.06	<0.1	0.04	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 105862	Soil	36	21	0.73	72	0.008	2	1.73	0.002	0.08	<0.1	0.01	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 105863	Soil	29	11	0.32	63	0.004	1	1.15	0.009	0.05	<0.1	0.04	2.0	<0.1	<0.05	2	<0.5	<0.2
KYS 105864	Soil	28	14	0.46	54	0.004	2	1.17	0.007	0.09	<0.1	0.02	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 105865	Soil	27	12	0.42	51	0.004	<1	1.07	0.007	0.08	<0.1	0.01	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 105866	Soil	7	7	0.96	54	0.015	1	0.43	0.006	0.09	<0.1	0.03	3.2	<0.1	<0.05	1	<0.5	<0.2
KYS 105867	Soil	12	4	0.09	68	0.003	<1	0.44	0.004	0.04	<0.1	0.06	2.4	<0.1	<0.05	<1	<0.5	0.3
KYS 105868	Soil	12	5	0.10	67	0.003	<1	0.46	0.004	0.04	<0.1	0.07	2.5	<0.1	<0.05	<1	<0.5	<0.2
KYS 105869	Soil	13	17	0.24	72	0.014	<1	0.97	0.005	0.05	0.1	0.12	0.9	<0.1	<0.05	3	1.6	<0.2
KYS 105870	Soil	9	13	0.23	77	0.021	<1	0.99	0.008	0.05	<0.1	0.04	1.8	0.1	<0.05	2	1.0	0.3
KYS 105871	Soil	14	13	0.32	119	0.008	<1	0.99	0.005	0.05	<0.1	0.07	1.8	0.1	<0.05	3	0.7	<0.2
KYS 105872	Soil	14	15	0.23	89	0.014	<1	0.84	0.004	0.04	0.1	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 105873	Soil	20	12	0.37	69	0.009	<1	0.84	0.005	0.04	<0.1	0.07	2.4	<0.1	<0.05	2	<0.5	<0.2
KYS 105874	Soil	21	8	0.45	41	0.003	<1	0.80	0.005	0.04	<0.1	0.08	2.4	<0.1	<0.05	1	0.7	<0.2
KYS 105875	Soil	19	5	0.13	49	0.004	<1	0.46	0.003	0.04	<0.1	0.10	1.7	<0.1	<0.05	1	0.5	<0.2
KYS 105876	Soil	14	10	0.29	55	0.003	<1	0.88	0.004	0.04	<0.1	0.10	1.6	<0.1	<0.05	2	1.4	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 105877	Soil	11.2	44.1	36.9	108	0.4	31.4	8.9	152	3.43	22.8	4.1	1.6	5.9	76	0.8	6.1	0.5	12	0.03	0.059
KYS 105878	Soil	4.8	74.4	29.9	100	0.3	31.8	12.5	508	3.44	6.0	3.0	4.3	6.6	42	0.8	3.5	0.4	16	0.04	0.037
KYS 105879	Soil	4.5	119.6	28.7	113	0.3	36.4	12.9	820	3.69	11.2	2.9	14.9	2.1	42	0.8	5.4	0.4	25	0.04	0.066
KYS 105880	Soil	2.7	89.7	34.7	145	0.2	48.2	22.0	748	3.96	6.0	3.7	7.5	6.3	26	2.3	6.3	0.4	15	0.05	0.049
KYS 105881	Soil	3.0	107.7	28.0	156	0.3	59.0	24.7	1494	3.95	226.3	2.5	32.6	7.0	30	1.3	20.0	0.4	16	0.07	0.046
KYS 105882	Soil	2.5	99.8	29.5	129	0.2	48.1	22.3	1220	3.85	211.2	2.7	24.9	8.1	17	0.6	21.1	0.4	14	0.03	0.041
KYS 105883	Soil	5.4	117.5	23.4	139	0.3	42.5	16.3	1011	3.47	110.0	2.4	21.6	5.7	26	0.6	16.6	0.3	18	0.03	0.067
KYS 105884	Soil	2.6	154.9	22.8	127	0.2	52.0	20.4	1177	4.04	42.0	2.5	14.1	4.1	28	0.4	11.7	0.3	37	0.10	0.086
KYS 105885	Soil	2.3	274.8	29.2	102	0.4	64.3	26.4	2744	3.56	32.3	1.5	83.3	4.1	22	0.2	8.3	0.4	31	0.07	0.089
KYS 105886	Soil	7.3	524.3	45.9	292	1.1	103.3	39.9	3013	6.14	22.0	3.7	41.8	4.8	66	1.0	29.8	0.5	31	0.10	0.163
KYS 105887	Soil	2.6	250.1	33.4	133	0.3	101.0	43.6	2805	4.58	21.7	1.8	46.4	12.4	29	0.3	3.3	0.6	16	0.35	0.084
KYS 105888	Soil	3.4	175.8	28.6	108	0.2	48.7	22.8	1471	3.49	51.1	1.7	21.1	7.1	19	0.4	6.9	0.4	22	0.11	0.077
KYS 105889	Soil	1.0	84.8	34.9	119	0.1	62.3	35.1	1119	4.86	48.9	3.0	5.9	15.9	15	0.2	13.2	0.6	11	0.12	0.048
KYS 105890	Soil	2.5	78.2	33.7	131	0.2	58.5	32.2	1133	5.00	26.6	2.5	7.5	8.0	16	0.3	5.9	0.5	11	0.16	0.065
KYS 105891	Soil	1.0	60.5	26.7	105	0.1	47.9	25.1	821	4.24	13.1	1.8	2.9	9.1	13	0.2	1.6	0.4	9	0.14	0.050
KYS 105892	Soil	3.2	131.7	25.5	120	0.5	54.9	17.8	2268	3.25	22.5	1.4	34.5	6.9	25	0.5	3.7	0.3	33	0.12	0.112
KYS 105893	Soil	2.7	71.3	35.8	119	0.6	44.6	14.6	1404	4.04	19.4	1.7	11.0	3.5	21	0.4	4.8	0.4	25	0.18	0.091
KYS 105894	Soil	1.2	65.1	18.0	101	0.2	86.7	23.7	1425	3.84	33.2	1.3	6.7	8.0	26	0.3	2.5	0.2	34	0.20	0.087
KYS 105895	Soil	1.8	131.1	22.3	129	0.3	73.8	23.5	2895	3.25	20.6	1.2	18.2	3.5	20	0.3	1.6	0.3	36	0.12	0.077
KYS 105896	Soil	0.6	25.3	20.2	70	<0.1	22.7	12.0	417	2.96	91.0	1.2	12.3	5.5	11	<0.1	4.2	0.3	20	0.13	0.065
KYS 105897	Soil	1.2	16.5	19.7	61	<0.1	17.6	13.1	994	2.72	47.4	1.1	3.1	1.3	11	0.2	4.7	0.3	26	0.13	0.092
KYS 105898	Soil	0.8	19.4	15.5	62	<0.1	19.8	9.9	416	2.56	31.6	1.1	3.6	4.2	11	0.1	3.7	0.2	19	0.16	0.049
KYS 105899	Soil	0.7	27.0	15.7	78	<0.1	27.3	17.7	504	3.05	16.4	1.6	2.9	5.1	13	0.2	1.7	0.3	19	0.18	0.056
KYS 105900	Soil	0.7	23.7	17.9	77	<0.1	25.7	15.1	510	2.95	19.6	1.4	3.2	5.7	11	0.1	1.4	0.3	23	0.12	0.059
KYS 105901	Soil	1.1	18.7	17.8	48	0.2	15.2	5.8	243	2.93	11.8	0.7	2.1	2.2	7	0.2	0.9	0.3	34	0.06	0.042
KYS 105902	Soil	1.3	33.4	27.3	71	<0.1	23.9	15.8	558	3.90	11.3	1.3	2.7	3.1	7	0.2	1.2	0.4	29	0.05	0.044
KYS 105903	Soil	1.0	39.9	28.2	79	<0.1	22.8	18.6	724	4.76	8.0	1.8	3.2	2.3	15	0.1	1.3	0.6	19	0.13	0.160
KYS 105904	Soil	1.1	17.4	15.3	57	<0.1	17.9	7.9	433	2.69	5.8	2.0	1.3	1.3	18	<0.1	0.6	0.3	19	0.23	0.052
KYS 105905	Soil	1.2	56.0	28.2	79	0.1	23.8	10.2	337	4.81	8.6	1.6	4.0	2.8	6	<0.1	1.4	0.5	21	0.04	0.077
KYS 105906	Soil	1.1	23.9	19.9	50	0.1	15.2	6.1	169	2.75	9.2	1.2	2.4	1.5	8	0.1	1.1	0.3	33	0.06	0.044

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 105877	Soil	10	7	0.15	80	0.002	<1	0.65	0.005	0.07	<0.1	0.19	1.4	0.2	0.10	2	2.9	0.3
KYS 105878	Soil	12	12	0.44	89	0.004	<1	1.04	0.008	0.06	<0.1	0.08	1.4	<0.1	0.08	3	1.1	0.3
KYS 105879	Soil	15	16	0.50	166	0.009	1	1.28	0.007	0.07	<0.1	0.10	1.1	<0.1	0.10	4	0.8	0.4
KYS 105880	Soil	13	13	0.51	124	0.004	<1	1.25	0.004	0.04	<0.1	0.04	1.4	<0.1	<0.05	3	0.7	<0.2
KYS 105881	Soil	16	11	0.42	128	0.002	<1	1.06	0.005	0.05	<0.1	0.04	1.9	<0.1	<0.05	3	1.0	<0.2
KYS 105882	Soil	22	10	0.35	112	0.004	<1	0.88	0.006	0.04	<0.1	0.05	1.7	<0.1	<0.05	2	0.9	<0.2
KYS 105883	Soil	19	10	0.31	766	0.004	<1	0.91	0.004	0.05	<0.1	0.08	1.3	<0.1	<0.05	2	1.5	<0.2
KYS 105884	Soil	19	20	0.73	342	0.016	1	1.47	0.004	0.07	<0.1	0.08	2.5	<0.1	<0.05	5	0.9	0.2
KYS 105885	Soil	25	19	0.52	185	0.009	1	1.33	0.005	0.04	<0.1	0.12	2.0	<0.1	<0.05	4	1.5	0.6
KYS 105886	Soil	24	19	0.33	313	0.006	<1	1.27	0.004	0.05	<0.1	0.37	2.2	<0.1	0.07	4	5.0	0.8
KYS 105887	Soil	22	12	0.62	105	0.007	<1	1.09	0.003	0.04	<0.1	0.07	2.0	<0.1	0.07	3	1.4	0.4
KYS 105888	Soil	25	14	0.48	212	0.009	<1	1.08	0.006	0.05	<0.1	0.07	2.0	<0.1	0.05	3	1.3	<0.2
KYS 105889	Soil	26	17	0.63	54	0.009	8	1.43	0.011	0.09	<0.1	0.02	1.8	<0.1	<0.05	4	0.6	0.3
KYS 105890	Soil	18	12	0.52	60	0.002	<1	1.22	0.007	0.05	<0.1	0.03	2.0	<0.1	<0.05	3	0.8	<0.2
KYS 105891	Soil	18	12	0.48	47	0.006	<1	1.16	0.010	0.08	<0.1	0.03	2.1	<0.1	<0.05	3	0.6	<0.2
KYS 105892	Soil	23	19	0.45	148	0.019	<1	1.22	0.006	0.03	0.1	0.14	2.2	<0.1	<0.05	4	1.6	0.3
KYS 105893	Soil	21	14	0.28	154	0.008	<1	0.94	0.006	0.03	0.1	0.13	1.8	<0.1	<0.05	3	1.5	0.4
KYS 105894	Soil	18	67	0.86	151	0.023	<1	1.57	0.007	0.05	0.1	0.05	3.9	<0.1	<0.05	5	0.6	<0.2
KYS 105895	Soil	21	29	0.52	170	0.014	<1	1.45	0.006	0.04	0.2	0.09	2.2	<0.1	<0.05	4	0.8	0.2
KYS 105896	Soil	22	18	0.50	109	0.006	<1	1.49	0.006	0.05	<0.1	0.03	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 105897	Soil	18	18	0.40	144	0.005	<1	1.21	0.006	0.06	<0.1	0.02	0.8	0.1	<0.05	4	<0.5	<0.2
KYS 105898	Soil	20	16	0.44	94	0.006	<1	1.19	0.004	0.04	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 105899	Soil	19	17	0.55	93	0.006	<1	1.49	0.004	0.05	<0.1	0.02	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 105900	Soil	24	18	0.54	107	0.008	<1	1.51	0.005	0.06	<0.1	0.02	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 105901	Soil	14	17	0.30	50	0.020	<1	1.19	0.004	0.04	<0.1	0.04	1.2	<0.1	<0.05	5	<0.5	<0.2
KYS 105902	Soil	14	23	0.42	62	0.016	1	1.60	0.004	0.04	<0.1	0.05	1.6	<0.1	<0.05	4	0.7	<0.2
KYS 105903	Soil	11	16	0.37	45	0.006	<1	1.26	0.006	0.05	<0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 105904	Soil	14	14	0.34	78	0.005	<1	1.10	0.006	0.04	<0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 105905	Soil	17	17	0.49	35	0.006	<1	1.27	0.007	0.05	<0.1	0.04	1.1	<0.1	<0.05	4	0.5	<0.2
KYS 105906	Soil	15	17	0.27	73	0.017	1	1.08	0.006	0.05	0.1	0.03	1.3	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 105907	Soil	1.0	28.5	19.8	61	<0.1	23.7	10.5	353	2.85	10.7	1.4	3.1	4.4	10	0.1	1.7	0.3	37	0.08	0.046
KYS 105908	Soil	1.0	31.6	19.1	60	<0.1	23.9	9.7	290	2.68	9.1	1.5	2.7	1.9	8	0.1	1.5	0.3	38	0.06	0.044
KYS 105909	Soil	1.1	49.7	27.2	88	<0.1	24.0	11.2	223	4.55	3.6	1.9	2.5	6.0	6	<0.1	0.7	0.4	15	0.02	0.044
KYS 105910	Soil	0.9	30.7	20.5	60	<0.1	22.7	9.3	231	2.88	12.0	1.2	2.9	2.4	7	0.2	3.3	0.3	31	0.06	0.044
KYS 105911	Soil	1.2	25.8	22.5	46	0.1	14.0	5.3	100	2.75	5.1	1.6	0.9	1.4	5	<0.1	0.5	0.3	18	0.03	0.067
KYS 105912	Soil	0.6	50.7	29.2	97	<0.1	35.3	16.4	602	4.08	35.2	2.3	4.5	10.2	19	0.1	1.7	0.4	8	0.23	0.045
KYS 105913	Soil	3.6	49.3	30.4	119	0.1	41.2	16.1	638	4.02	8.0	2.8	1.5	7.8	22	0.6	2.8	0.5	11	0.10	0.038
KYS 105914	Soil	0.5	50.7	30.6	109	0.1	43.1	22.1	704	4.37	11.0	2.9	1.4	9.7	15	0.3	2.4	0.5	13	0.13	0.043
KYS 105915	Soil	0.9	24.3	22.1	70	<0.1	20.2	8.7	431	2.83	10.4	1.3	<0.5	1.1	11	0.4	2.7	0.3	21	0.13	0.082
KYS 105916	Soil	0.7	41.2	31.2	92	0.1	35.0	13.9	530	3.35	28.2	2.3	3.8	10.6	31	0.3	5.3	0.4	6	0.59	0.043
KYS 105917	Soil	0.7	46.9	30.5	92	0.1	37.2	16.8	589	3.73	65.8	2.1	12.4	16.3	18	0.2	9.4	0.4	9	0.23	0.042
KYS 105918	Soil	1.0	40.8	27.1	78	0.1	31.9	14.9	511	3.52	30.0	2.4	2.1	9.5	15	0.3	4.3	0.4	8	0.14	0.042
KYS 105919	Soil	2.4	41.1	27.4	92	0.2	32.4	14.1	499	3.70	15.9	2.3	2.2	6.1	16	0.3	2.8	0.4	10	0.16	0.042
KYS 105920	Soil	4.4	36.5	22.2	83	0.1	32.2	13.8	448	2.91	6.8	2.4	1.5	6.0	20	0.4	2.5	0.3	18	0.14	0.052
KYS 105921	Soil	0.5	75.3	50.4	100	0.2	53.4	26.7	1702	5.02	14.0	2.8	2.1	8.3	22	0.3	4.7	0.8	6	0.36	0.052
KYS 105922	Soil	0.5	52.0	30.4	96	0.1	39.8	19.2	667	3.62	17.9	2.0	2.7	9.3	11	0.3	2.9	0.4	10	0.18	0.062
KYS 105923	Soil	0.8	50.1	34.9	100	0.2	42.5	20.5	656	4.06	61.7	1.9	12.4	9.5	13	0.2	8.1	0.5	5	0.19	0.048
KYS 105924	Soil	0.8	58.0	32.0	108	0.1	44.2	23.0	620	4.55	144.9	1.9	13.2	18.1	12	0.1	45.9	0.6	9	0.17	0.053
KYS 105925	Soil	0.8	61.7	36.9	114	0.2	41.1	18.5	508	4.80	200.2	2.8	23.8	9.9	11	0.3	17.5	0.6	11	0.10	0.047
KYS 105926	Soil	0.8	49.3	36.9	107	0.1	36.2	15.4	461	4.41	115.4	2.5	15.3	6.9	13	0.1	9.6	0.5	14	0.19	0.046
KYS 105927	Soil	0.8	42.9	33.3	105	<0.1	35.6	17.6	484	4.19	86.0	2.2	8.3	8.8	8	0.1	9.3	0.5	13	0.08	0.047
KYS 105928	Soil	1.3	53.6	28.5	107	0.1	37.9	16.8	614	3.90	52.9	1.9	7.9	10.3	16	0.3	5.3	0.4	23	0.19	0.071
KYS 105929	Soil	1.0	56.5	32.7	112	0.1	41.6	18.0	745	4.21	153.3	2.6	23.3	14.2	14	0.2	5.0	0.4	16	0.16	0.059
KYS 105930	Soil	1.1	36.1	30.4	90	0.1	28.4	13.8	691	3.70	104.9	1.7	7.3	5.2	23	0.2	8.7	0.4	22	0.32	0.087
KYS 105931	Soil	0.3	24.3	19.1	75	<0.1	22.9	10.0	331	3.11	69.3	1.4	4.3	11.9	8	<0.1	5.4	0.3	16	0.07	0.035
KYS 105932	Soil	0.7	24.8	19.5	71	<0.1	24.9	10.7	378	3.29	44.1	1.6	4.8	6.2	16	<0.1	3.5	0.3	23	0.21	0.061
KYS 105933	Soil	6.4	33.0	24.0	77	0.2	25.3	8.6	409	3.07	28.9	2.6	3.7	3.3	14	0.2	3.5	0.3	17	0.04	0.059
KYS 105934	Soil	2.0	31.5	22.1	77	0.1	30.7	9.0	307	2.77	9.3	1.4	1.7	4.6	16	0.4	1.8	0.3	30	0.12	0.054
KYS 105935	Soil	5.1	36.7	21.2	104	0.2	28.7	9.9	547	2.74	11.7	2.6	1.8	2.5	30	0.9	2.7	0.3	12	0.53	0.074
KYS 105936	Soil	7.8	42.5	27.9	99	0.3	32.7	10.5	686	2.95	19.9	2.7	3.5	3.9	41	0.9	5.6	0.4	13	0.34	0.076

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 105907	Soil	17	23	0.42	136	0.022	<1	1.61	0.005	0.06	0.2	0.04	2.3	0.1	<0.05	4	<0.5	<0.2
KYS 105908	Soil	17	22	0.40	105	0.019	<1	1.53	0.006	0.05	0.1	0.05	1.9	<0.1	<0.05	4	<0.5	<0.2
KYS 105909	Soil	25	17	0.58	49	0.004	<1	1.25	0.006	0.06	<0.1	0.03	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 105910	Soil	18	18	0.39	59	0.015	<1	1.13	0.005	0.04	<0.1	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 105911	Soil	10	12	0.27	54	0.003	<1	1.02	0.006	0.06	<0.1	0.06	0.8	<0.1	<0.05	3	0.5	<0.2
KYS 105912	Soil	23	12	0.42	45	0.002	<1	1.05	0.007	0.06	<0.1	0.03	1.5	<0.1	0.05	3	<0.5	<0.2
KYS 105913	Soil	17	11	0.37	44	0.002	<1	0.90	0.005	0.05	<0.1	0.05	1.4	<0.1	<0.05	2	0.5	<0.2
KYS 105914	Soil	17	11	0.44	32	0.003	1	1.06	0.005	0.06	<0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 105915	Soil	11	11	0.27	78	0.006	<1	0.90	0.006	0.04	<0.1	0.03	0.6	<0.1	0.07	3	0.7	<0.2
KYS 105916	Soil	16	12	0.44	46	0.002	<1	1.02	0.005	0.07	<0.1	0.02	1.1	<0.1	0.06	2	0.6	<0.2
KYS 105917	Soil	23	7	0.33	35	0.002	<1	0.82	0.004	0.06	<0.1	0.02	1.4	<0.1	<0.05	2	<0.5	<0.2
KYS 105918	Soil	18	4	0.25	29	0.002	<1	0.60	0.004	0.06	<0.1	0.02	1.3	<0.1	<0.05	1	0.5	<0.2
KYS 105919	Soil	14	12	0.38	35	0.003	<1	0.99	0.004	0.06	<0.1	0.04	1.2	<0.1	<0.05	3	1.0	<0.2
KYS 105920	Soil	14	7	0.25	43	0.003	<1	0.65	0.003	0.03	<0.1	0.06	1.0	<0.1	<0.05	2	0.7	<0.2
KYS 105921	Soil	17	15	0.68	35	0.002	<1	1.36	0.004	0.05	<0.1	0.04	2.4	<0.1	<0.05	4	<0.5	<0.2
KYS 105922	Soil	17	14	0.67	33	0.002	<1	1.27	0.003	0.04	<0.1	0.04	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 105923	Soil	16	8	0.35	30	0.001	<1	0.68	0.004	0.04	<0.1	0.05	1.5	<0.1	<0.05	2	<0.5	<0.2
KYS 105924	Soil	29	13	0.58	31	0.002	<1	1.15	0.003	0.06	<0.1	0.02	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 105925	Soil	20	13	0.59	32	0.002	<1	1.27	0.003	0.04	<0.1	0.04	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 105926	Soil	17	13	0.57	58	0.003	<1	1.25	0.004	0.04	<0.1	0.05	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 105927	Soil	22	15	0.54	79	0.005	<1	1.23	0.005	0.04	<0.1	0.03	1.7	<0.1	<0.05	3	<0.5	<0.2
KYS 105928	Soil	31	18	0.72	79	0.007	<1	1.51	0.004	0.06	<0.1	0.04	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 105929	Soil	29	17	0.67	64	0.005	<1	1.52	0.004	0.05	<0.1	0.04	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 105930	Soil	19	18	0.52	108	0.006	1	1.42	0.006	0.07	<0.1	0.03	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 105931	Soil	28	13	0.54	61	0.007	<1	1.32	0.003	0.05	<0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 105932	Soil	20	17	0.52	107	0.007	<1	1.44	0.005	0.05	0.1	0.03	1.4	<0.1	<0.05	4	<0.5	0.2
KYS 105933	Soil	13	9	0.21	71	0.004	<1	0.75	0.004	0.05	<0.1	0.12	1.2	<0.1	<0.05	2	1.4	0.4
KYS 105934	Soil	17	18	0.39	64	0.034	<1	1.05	0.006	0.05	0.1	0.03	1.5	<0.1	<0.05	3	0.6	<0.2
KYS 105935	Soil	7	6	0.24	63	0.003	<1	0.58	0.005	0.04	<0.1	0.10	1.1	<0.1	0.07	1	1.5	0.2
KYS 105936	Soil	14	8	0.26	88	0.003	<1	0.72	0.004	0.05	<0.1	0.13	1.3	<0.1	0.06	2	0.9	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 105937	Soil		5.8	90.5	21.4	145	0.4	47.6	18.4	1016	4.27	7.9	2.1	6.7	4.9	38	0.6	4.0	0.3	25	0.21	0.120
KYS 105938	Soil		1.8	74.6	14.8	75	0.1	25.1	7.8	506	3.14	11.2	1.1	20.6	3.0	24	0.3	2.0	0.2	40	0.09	0.068
KYS 105939	Soil		2.4	74.9	18.9	62	0.2	19.0	4.9	294	2.76	14.2	1.0	13.6	1.5	17	0.2	1.9	0.3	36	0.04	0.054
KYS 105940	Soil		5.3	96.6	28.9	84	0.5	26.3	5.5	306	3.56	17.9	2.0	12.3	0.3	64	0.2	3.0	0.5	53	0.06	0.106
KYS 105941	Soil		1.4	128.8	19.5	81	0.1	32.5	11.4	652	2.99	16.6	1.1	17.3	2.9	13	0.4	2.4	0.3	44	0.07	0.065
KYS 105942	Soil		5.6	164.6	26.3	100	0.3	36.9	12.0	1401	3.75	12.0	2.0	51.0	4.1	30	0.2	1.9	0.5	34	0.05	0.083
KYS 105943	Soil		2.3	68.8	16.4	74	0.2	24.0	7.8	728	2.86	12.9	1.1	16.1	0.6	18	0.8	1.6	0.3	40	0.08	0.066
KYS 105944	Soil		2.7	95.2	16.4	71	0.6	25.0	6.3	349	2.24	10.6	2.3	10.5	0.5	33	0.5	2.8	0.3	35	0.16	0.102
KYS 105945	Soil		6.1	109.0	22.1	120	0.4	32.9	8.9	572	3.46	15.1	2.3	11.6	2.3	27	0.5	7.7	0.4	38	0.06	0.072
KYS 105980	Soil		2.8	64.6	32.2	133	0.3	44.0	16.7	541	3.92	197.6	1.8	35.2	10.3	19	0.5	39.9	0.5	13	0.25	0.067
KYS 105981	Soil		2.9	63.2	30.0	91	0.2	30.4	10.2	829	3.85	15.9	1.7	2.3	2.4	16	0.2	3.6	0.5	43	0.11	0.058
KYS 105982	Soil		1.6	106.3	19.9	75	0.3	27.9	10.3	682	2.93	18.0	0.8	8.4	2.1	18	0.2	7.2	0.3	50	0.06	0.057
KYS 105983	Soil		1.5	56.9	14.5	61	0.1	21.5	9.4	1252	2.85	11.1	0.6	4.5	1.9	8	0.2	1.9	0.2	49	0.07	0.045
KYS 105984	Soil		1.5	43.4	9.1	37	0.4	13.9	6.3	1053	1.65	7.4	0.5	4.6	<0.1	9	0.1	3.1	0.3	43	0.07	0.077
KYS 105985	Soil		1.4	52.2	8.0	34	0.4	12.7	5.5	1030	1.75	8.8	0.5	12.0	0.2	7	<0.1	2.6	0.3	49	0.04	0.051
KYS 105986	Soil		1.6	70.4	12.2	65	0.1	35.1	11.0	691	2.86	10.6	0.8	11.8	2.1	13	0.2	7.2	0.2	42	0.07	0.040
KYS 105987	Soil		2.0	77.7	13.6	60	0.2	23.9	8.0	561	2.58	9.1	0.8	18.1	1.4	12	0.2	4.0	0.2	43	0.06	0.045
KYS 105988	Soil		2.3	161.8	23.5	108	0.2	65.9	26.3	4303	3.43	21.9	1.3	42.0	5.1	15	0.2	7.1	0.3	36	0.06	0.078
KYS 105989	Soil		2.0	137.4	20.4	99	0.2	51.0	20.9	2593	3.51	19.1	1.3	26.7	3.2	15	0.2	3.7	0.3	45	0.11	0.099
KYS 105990	Soil		1.8	134.1	20.5	102	0.2	46.9	22.7	2177	3.35	20.4	1.3	16.3	2.0	11	0.2	5.1	0.3	40	0.07	0.086
KYS 105991	Soil		1.9	88.2	21.2	95	0.1	39.1	18.7	1237	3.35	23.1	1.2	12.8	2.7	10	0.2	5.0	0.3	40	0.09	0.084
KYS 105992	Soil		1.6	57.4	22.0	91	0.2	36.0	15.5	1104	3.35	18.4	1.3	7.7	3.8	11	0.2	2.4	0.3	32	0.14	0.080
KYS 105993	Soil		1.1	39.0	19.6	82	0.1	32.0	12.5	611	3.08	8.6	1.5	8.1	4.6	13	0.3	1.8	0.2	23	0.22	0.076
KYS 105994	Soil		3.1	128.8	22.0	102	0.1	47.5	14.6	1372	3.49	18.9	1.4	14.7	2.8	19	0.2	3.3	0.3	34	0.08	0.075
KYS 105995	Soil		3.5	135.0	22.3	113	0.2	50.6	14.0	1648	3.71	17.5	1.4	22.2	1.8	20	0.2	2.5	0.3	40	0.07	0.077
KYS 105996	Soil		2.4	46.5	14.6	58	<0.1	22.6	7.5	611	2.74	10.1	0.7	9.7	0.6	10	0.1	1.5	0.3	43	0.05	0.055
KYS 105997	Soil		4.1	60.1	14.3	71	0.3	24.6	8.0	623	2.57	10.9	0.9	10.0	0.5	14	0.1	3.4	0.2	43	0.07	0.075
KYS 105998	Soil		15.2	88.4	19.5	115	1.3	36.0	5.6	243	4.03	39.7	2.7	10.1	0.7	49	0.5	18.8	0.2	59	0.10	0.202
KYS 105999	Soil		4.0	60.6	13.6	91	0.5	27.1	6.9	383	2.74	14.4	1.3	12.6	0.9	22	0.3	4.7	0.2	57	0.10	0.087
KYS 106000	Soil		1.9	76.3	14.8	100	0.3	36.0	12.1	857	3.32	245.0	1.3	57.4	2.6	15	0.2	18.5	0.2	49	0.12	0.085

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 105937	Soil		20	10	0.31	176	0.006	<1	1.01	0.004	0.06	<0.1	0.11	2.1	<0.1	<0.05	3	1.2	0.2
KYS 105938	Soil		18	19	0.28	148	0.033	<1	0.84	0.006	0.04	0.2	0.07	1.1	<0.1	<0.05	3	0.6	0.2
KYS 105939	Soil		18	16	0.30	128	0.021	<1	0.83	0.004	0.04	0.1	0.06	0.8	<0.1	0.05	3	0.8	0.4
KYS 105940	Soil		14	24	0.29	464	0.012	1	1.33	0.008	0.08	0.2	0.16	0.6	0.1	0.09	5	0.8	0.5
KYS 105941	Soil		20	15	0.45	116	0.022	<1	1.34	0.003	0.04	0.1	0.05	1.4	<0.1	<0.05	4	<0.5	0.4
KYS 105942	Soil		26	19	0.44	128	0.013	1	1.23	0.005	0.05	<0.1	0.13	1.4	<0.1	<0.05	4	1.5	0.4
KYS 105943	Soil		17	21	0.35	87	0.015	<1	1.10	0.005	0.05	0.1	0.06	0.6	<0.1	<0.05	4	0.6	0.5
KYS 105944	Soil		16	17	0.29	509	0.010	<1	1.16	0.007	0.05	0.2	0.14	0.7	<0.1	0.09	4	<0.5	0.5
KYS 105945	Soil		23	21	0.37	310	0.017	<1	1.30	0.006	0.05	0.2	0.14	1.4	<0.1	0.05	4	1.6	0.3
KYS 105980	Soil		29	12	0.44	99	0.003	<1	1.07	0.004	0.06	<0.1	0.07	2.0	<0.1	<0.05	3	<0.5	<0.2
KYS 105981	Soil		18	18	0.36	117	0.011	<1	1.22	0.005	0.06	0.1	0.06	0.9	<0.1	<0.05	5	<0.5	0.3
KYS 105982	Soil		19	23	0.44	126	0.015	<1	1.48	0.005	0.06	0.1	0.08	1.3	<0.1	<0.05	4	0.8	0.3
KYS 105983	Soil		13	22	0.32	134	0.016	2	1.31	0.004	0.05	0.2	0.07	1.1	0.1	<0.05	5	<0.5	<0.2
KYS 105984	Soil		11	13	0.14	110	0.008	1	0.67	0.004	0.06	<0.1	0.11	0.2	<0.1	0.07	4	<0.5	0.5
KYS 105985	Soil		12	16	0.14	76	0.010	<1	0.68	0.003	0.04	0.1	0.07	0.4	<0.1	<0.05	5	<0.5	0.3
KYS 105986	Soil		14	25	0.37	85	0.024	2	1.56	0.004	0.04	0.2	0.07	1.3	<0.1	<0.05	4	0.6	<0.2
KYS 105987	Soil		16	19	0.28	71	0.013	<1	1.04	0.003	0.04	0.2	0.07	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 105988	Soil		24	20	0.51	105	0.018	1	1.37	0.003	0.03	<0.1	0.06	2.0	<0.1	<0.05	4	0.6	0.3
KYS 105989	Soil		23	25	0.59	115	0.022	2	1.61	0.005	0.05	0.1	0.06	2.2	<0.1	<0.05	5	0.6	<0.2
KYS 105990	Soil		21	24	0.53	127	0.016	1	1.57	0.005	0.05	0.1	0.06	1.7	<0.1	<0.05	4	0.7	<0.2
KYS 105991	Soil		23	24	0.57	143	0.015	<1	1.73	0.004	0.06	0.1	0.05	2.0	<0.1	<0.05	5	0.7	<0.2
KYS 105992	Soil		24	22	0.55	193	0.011	<1	1.47	0.005	0.05	0.1	0.04	1.4	<0.1	<0.05	4	0.6	<0.2
KYS 105993	Soil		15	20	0.46	127	0.008	<1	1.15	0.004	0.04	<0.1	0.05	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 105994	Soil		19	21	0.44	124	0.014	1	1.28	0.005	0.06	0.1	0.05	1.4	<0.1	<0.05	4	0.7	0.3
KYS 105995	Soil		20	24	0.50	184	0.014	1	1.44	0.006	0.06	<0.1	0.09	1.2	<0.1	<0.05	4	1.1	<0.2
KYS 105996	Soil		20	21	0.33	94	0.015	1	1.27	0.003	0.03	<0.1	0.06	0.7	<0.1	<0.05	5	0.7	<0.2
KYS 105997	Soil		16	19	0.32	1070	0.011	<1	0.99	0.003	0.05	0.1	0.10	0.6	<0.1	0.05	4	1.0	0.2
KYS 105998	Soil		15	16	0.19	848	0.013	1	1.47	0.004	0.09	0.7	0.86	1.2	0.2	0.14	4	6.7	<0.2
KYS 105999	Soil		16	23	0.32	2087	0.022	2	1.33	0.005	0.06	0.2	0.20	1.3	<0.1	0.05	4	1.7	<0.2
KYS 106000	Soil		20	28	0.49	129	0.033	2	1.54	0.005	0.06	0.2	0.05	2.6	<0.1	<0.05	5	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109001	Soil	7.2	101.5	32.7	188	0.4	81.1	37.4	1512	5.00	15.2	4.5	1.9	14.0	38	2.0	10.3	0.4	21	0.35	0.112
KYS 109002	Soil	0.8	34.3	20.6	77	<0.1	34.9	16.5	637	2.63	11.0	1.1	4.2	3.8	14	0.2	3.8	0.2	19	0.19	0.057
KYS 109003	Soil	2.6	63.4	33.0	119	0.2	55.2	27.0	1439	4.32	13.0	2.2	2.0	10.4	32	0.5	5.0	0.4	22	0.27	0.078
KYS 109004	Soil	2.0	65.7	30.3	113	0.1	58.3	28.1	1284	4.39	31.5	2.4	2.9	18.5	18	0.2	5.6	0.3	18	0.29	0.096
KYS 109005	Soil	2.0	68.7	31.1	116	0.2	60.3	28.5	1385	4.56	31.4	2.4	2.8	18.9	19	0.3	5.6	0.3	18	0.30	0.099
KYS 109006	Soil	1.1	43.4	18.3	92	0.2	46.8	18.8	707	3.76	188.8	2.3	45.0	7.0	8	0.2	14.1	0.2	23	0.08	0.054
KYS 109007	Soil	1.0	41.8	26.4	91	0.1	39.4	20.8	903	3.63	71.3	1.9	8.8	9.0	7	0.1	11.0	0.3	17	0.09	0.057
KYS 109008	Soil	1.2	35.8	18.4	77	0.1	31.7	13.7	543	2.90	59.8	1.5	15.1	8.6	13	0.2	6.4	0.2	23	0.18	0.061
KYS 109009	Soil	1.0	35.6	19.2	77	0.2	29.9	13.0	436	2.98	126.8	1.6	27.1	8.0	11	0.2	13.2	0.2	20	0.17	0.056
KYS 109010	Soil	0.7	42.0	22.3	88	0.1	40.0	18.5	609	3.47	118.1	1.4	16.0	10.0	13	0.1	8.0	0.3	21	0.21	0.051
KYS 109011	Soil	0.8	34.2	21.9	78	0.1	33.5	14.5	516	3.23	157.4	1.3	29.1	7.6	13	0.1	10.4	0.3	19	0.21	0.052
KYS 109012	Soil	1.6	41.0	21.5	94	0.2	45.5	17.9	590	3.65	48.7	1.8	12.1	8.5	15	0.2	8.8	0.3	19	0.24	0.087
KYS 109013	Soil	0.4	37.7	24.2	79	<0.1	34.8	15.4	506	3.32	62.7	1.3	6.6	13.2	15	<0.1	3.6	0.3	12	0.36	0.049
KYS 109014	Soil	0.9	60.6	58.0	97	0.1	53.9	23.9	1431	4.62	64.1	4.7	7.0	15.4	14	<0.1	3.7	0.7	10	0.22	0.055
KYS 109015	Soil	0.3	34.6	24.0	78	<0.1	30.9	14.0	470	3.34	31.3	1.4	1.9	13.4	16	<0.1	1.7	0.3	14	0.32	0.042
KYS 109016	Soil	0.3	36.6	22.0	83	<0.1	31.8	15.1	582	3.37	19.7	1.5	1.7	15.0	13	<0.1	1.8	0.3	13	0.25	0.046
KYS 109017	Soil	0.3	35.8	22.2	85	<0.1	31.9	15.0	571	3.30	19.3	1.5	2.3	14.9	14	<0.1	1.7	0.4	13	0.24	0.044
KYS 109018	Soil	0.4	36.9	22.7	67	<0.1	29.8	12.3	472	3.11	13.7	1.7	0.8	11.1	17	<0.1	1.0	0.3	10	0.37	0.045
KYS 109019	Soil	0.3	32.8	24.8	74	<0.1	27.4	12.8	463	2.89	15.5	1.4	2.3	14.9	11	<0.1	1.0	0.4	11	0.15	0.036
KYS 109020	Soil	0.4	43.6	25.5	74	0.1	28.1	12.6	453	3.09	9.2	2.6	2.7	11.6	19	<0.1	0.7	0.4	10	0.30	0.046
KYS 109021	Soil	0.5	39.4	23.5	73	<0.1	28.3	11.9	414	3.21	7.3	2.4	2.1	10.8	17	<0.1	0.7	0.3	8	0.25	0.039
KYS 109022	Soil	0.4	39.9	25.5	67	<0.1	24.1	9.4	297	2.86	7.4	2.0	2.2	7.6	35	<0.1	0.8	0.4	8	0.65	0.045
KYS 109023	Soil	0.5	40.2	26.3	69	<0.1	28.1	13.1	481	3.22	7.7	1.8	3.2	8.5	25	0.1	0.6	0.4	11	0.38	0.050
KYS 109024	Soil	0.7	39.4	25.6	81	0.2	31.4	13.5	788	3.21	15.3	1.6	4.9	10.8	17	0.2	5.0	0.3	22	0.22	0.062
KYS 109025	Soil	0.9	47.1	29.7	87	<0.1	41.4	21.9	801	3.93	56.5	1.4	7.5	11.7	6	<0.1	17.1	0.4	18	0.03	0.035
KYS 109026	Soil	1.1	19.5	20.0	51	<0.1	20.9	8.6	237	2.35	6.9	1.0	6.8	1.5	7	<0.1	0.6	0.2	28	0.06	0.048
KYS 109027	Soil	0.8	32.5	27.6	80	<0.1	26.9	15.0	673	3.27	9.6	2.1	3.2	7.1	9	0.1	1.0	0.4	38	0.07	0.050
KYS 109028	Soil	0.8	37.4	24.9	103	0.1	29.5	13.3	466	3.80	15.4	2.5	4.4	2.6	18	0.3	2.8	0.4	15	0.27	0.052
KYS 109029	Soil	1.1	37.6	21.6	83	0.1	74.1	19.7	3360	3.49	19.5	4.2	3.4	4.0	23	0.4	5.1	0.3	22	0.28	0.045
KYS 109030	Soil	1.1	25.9	21.6	72	<0.1	21.5	10.9	301	3.39	8.0	1.4	2.8	4.5	8	0.2	0.9	0.3	30	0.06	0.048

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109001	Soil	27	24	0.80	44	0.003	<1	1.69	0.005	0.06	<0.1	0.06	2.0	<0.1	<0.05	4	0.8	<0.2
KYS 109002	Soil	17	15	0.30	56	0.012	<1	0.85	0.006	0.04	0.1	0.03	1.1	<0.1	<0.05	2	<0.5	<0.2
KYS 109003	Soil	28	21	0.64	57	0.007	<1	1.48	0.005	0.05	<0.1	0.04	2.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109004	Soil	42	17	0.67	75	0.006	<1	1.25	0.004	0.06	<0.1	0.04	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109005	Soil	43	18	0.70	71	0.006	<1	1.30	0.004	0.06	<0.1	0.04	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109006	Soil	22	19	0.33	79	0.011	1	1.02	0.002	0.05	0.1	0.05	2.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109007	Soil	31	13	0.31	93	0.007	1	0.98	0.004	0.05	<0.1	0.04	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109008	Soil	25	15	0.34	100	0.018	1	0.87	0.004	0.04	0.1	0.03	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109009	Soil	26	15	0.34	94	0.009	<1	0.96	0.003	0.05	0.1	0.04	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109010	Soil	27	20	0.51	81	0.011	1	1.26	0.004	0.05	0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
KYS 109011	Soil	23	17	0.44	85	0.007	<1	1.15	0.003	0.05	0.1	0.03	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109012	Soil	30	19	0.43	83	0.007	<1	1.08	0.004	0.05	<0.1	0.04	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109013	Soil	30	16	0.55	44	0.006	<1	1.20	0.004	0.06	<0.1	0.03	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109014	Soil	29	16	0.55	62	0.004	<1	1.26	0.004	0.05	<0.1	0.04	2.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109015	Soil	27	17	0.62	58	0.007	1	1.40	0.004	0.07	<0.1	0.03	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109016	Soil	35	16	0.62	55	0.008	<1	1.37	0.004	0.08	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109017	Soil	31	16	0.60	54	0.008	<1	1.35	0.003	0.07	<0.1	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109018	Soil	27	13	0.49	51	0.004	1	1.11	0.003	0.07	<0.1	0.03	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109019	Soil	31	13	0.54	56	0.004	<1	1.24	0.003	0.06	<0.1	0.02	1.3	<0.1	<0.05	3	0.5	<0.2
KYS 109020	Soil	25	14	0.52	62	0.004	1	1.18	0.004	0.08	<0.1	0.04	1.4	<0.1	<0.05	3	0.6	<0.2
KYS 109021	Soil	23	12	0.49	55	0.003	1	1.12	0.004	0.07	<0.1	0.04	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 109022	Soil	18	11	0.41	70	0.003	2	0.94	0.005	0.09	<0.1	0.05	1.2	<0.1	0.06	3	<0.5	<0.2
KYS 109023	Soil	19	13	0.42	100	0.004	1	1.14	0.005	0.07	<0.1	0.05	1.6	<0.1	<0.05	3	0.6	<0.2
KYS 109024	Soil	29	17	0.48	109	0.016	<1	1.14	0.005	0.04	0.1	0.04	2.0	<0.1	<0.05	3	0.7	<0.2
KYS 109025	Soil	35	19	0.47	60	0.005	<1	1.43	0.004	0.05	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109026	Soil	14	18	0.33	63	0.013	<1	1.15	0.004	0.05	0.1	0.04	1.0	<0.1	<0.05	4	<0.5	<0.2
KYS 109027	Soil	19	27	0.48	92	0.031	<1	1.66	0.004	0.06	0.1	0.06	2.3	0.1	<0.05	4	<0.5	<0.2
KYS 109028	Soil	13	15	0.49	98	0.002	1	1.47	0.006	0.06	<0.1	0.03	1.4	<0.1	<0.05	4	0.9	<0.2
KYS 109029	Soil	19	14	0.34	177	0.015	1	1.05	0.006	0.05	0.1	0.03	2.0	<0.1	<0.05	3	0.8	<0.2
KYS 109030	Soil	21	21	0.45	93	0.015	1	1.49	0.005	0.05	0.2	0.03	1.8	<0.1	<0.05	4	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109031	Soil	0.9	23.6	19.1	61	<0.1	16.4	7.5	219	3.22	6.3	1.1	2.1	5.9	6	<0.1	0.7	0.3	23	0.03	0.034
KYS 109032	Soil	0.9	27.6	21.6	67	<0.1	25.1	13.7	446	3.08	8.2	2.0	1.8	5.8	17	<0.1	1.4	0.3	23	0.18	0.029
KYS 109033	Soil	1.4	45.2	21.5	88	0.2	27.6	11.4	427	2.97	16.2	1.7	13.7	7.6	8	0.2	3.5	0.3	18	0.06	0.043
KYS 109034	Soil	0.7	30.4	22.9	68	<0.1	26.0	12.3	405	2.79	8.6	2.1	4.3	6.4	20	0.2	1.0	0.3	28	0.28	0.059
KYS 109035	Soil	0.4	33.1	25.2	69	<0.1	23.9	10.4	301	2.97	5.6	1.8	2.2	12.2	15	<0.1	0.6	0.4	11	0.24	0.041
KYS 109036	Soil	0.5	45.3	30.4	86	0.2	37.0	17.6	774	3.53	205.8	1.5	17.8	14.0	11	0.2	20.4	0.4	8	0.17	0.045
KYS 109037	Soil	1.2	39.0	32.6	139	0.2	38.4	14.3	616	3.39	77.2	1.4	11.8	19.2	17	0.8	29.8	0.4	10	0.33	0.055
KYS 109038	Soil	1.2	44.7	29.2	118	0.2	40.5	16.4	850	3.24	49.6	1.6	14.3	16.2	18	0.7	18.3	0.3	11	0.38	0.067
KYS 109039	Soil	2.0	36.4	23.6	91	0.1	29.0	12.2	636	3.08	36.4	2.3	4.9	8.2	14	0.4	3.5	0.3	8	0.15	0.040
KYS 109040	Soil	1.9	56.0	31.7	111	0.1	43.9	21.8	933	4.54	17.3	2.5	3.0	8.5	16	0.4	3.6	0.5	6	0.24	0.039
KYS 109041	Soil	1.8	46.5	39.9	106	0.1	34.1	16.4	685	4.01	33.9	1.8	3.4	3.6	7	0.5	5.3	0.6	14	0.07	0.079
KYS 109042	Soil	1.7	49.5	48.9	167	0.1	49.1	25.7	822	4.53	107.5	2.7	11.1	3.2	9	0.3	38.3	0.7	10	0.10	0.055
KYS 109043	Soil	1.4	142.6	16.9	87	0.2	35.9	13.9	1794	2.72	15.0	1.2	13.2	1.6	15	0.3	2.7	0.3	34	0.05	0.067
KYS 109044	Soil	4.4	62.7	19.1	53	0.3	14.0	5.0	707	2.19	10.0	0.8	50.7	2.7	19	<0.1	2.5	0.3	33	0.02	0.051
KYS 109045	Soil	1.6	60.5	12.1	51	0.2	15.0	3.8	363	1.83	9.7	0.7	6.9	0.9	13	0.1	1.6	0.3	35	0.04	0.050
KYS 109046	Soil	1.8	32.4	15.2	49	0.2	12.7	4.5	310	2.63	12.9	0.9	8.8	0.4	8	0.2	1.5	0.3	56	0.05	0.066
KYS 109047	Soil	5.8	114.9	23.2	98	0.2	27.6	7.4	599	3.30	19.8	1.9	12.5	1.7	18	0.2	5.1	0.3	24	0.04	0.081
KYS 109048	Soil	6.0	113.1	21.5	94	0.2	24.8	7.1	560	3.06	19.2	1.8	13.0	1.6	17	0.1	4.7	0.3	23	0.04	0.081
KYS 109049	Soil	3.2	81.3	18.0	82	0.2	23.3	8.4	538	2.71	14.1	1.7	8.2	1.6	16	0.2	2.8	0.3	33	0.07	0.064
KYS 109050	Soil	5.5	49.5	21.8	88	0.1	23.4	7.6	428	2.81	15.3	2.4	8.7	2.8	17	0.5	4.0	0.3	24	0.07	0.068
KYS 109051	Soil	6.3	39.9	20.3	81	0.2	21.5	7.6	401	2.71	13.9	2.4	3.2	3.7	17	0.2	4.0	0.3	16	0.05	0.053
KYS 109052	Soil	5.9	39.4	20.3	74	0.2	20.4	7.4	400	2.62	13.7	2.3	6.7	3.5	16	0.2	4.1	0.3	16	0.05	0.050
KYS 109056	Soil	2.1	60.5	19.9	95	0.1	31.8	11.5	824	3.17	9.0	1.3	7.0	6.9	16	0.3	0.9	0.3	22	0.13	0.068
KYS 109057	Soil	0.8	36.3	23.7	67	0.2	28.6	10.8	630	2.81	9.7	1.4	5.0	8.5	12	<0.1	0.7	0.3	20	0.12	0.040
KYS 109058	Soil	0.7	37.7	20.0	75	0.1	25.4	9.5	440	2.95	7.3	1.5	4.4	10.8	11	<0.1	0.5	0.3	14	0.17	0.050
KYS 109059	Soil	1.1	41.0	18.8	75	0.1	24.7	9.9	522	2.69	6.6	1.5	2.9	8.6	18	0.1	0.7	0.3	16	0.25	0.062
KYS 109060	Soil	1.4	30.7	14.5	74	0.1	23.8	9.4	522	2.70	10.1	1.3	3.9	1.3	10	0.3	1.2	0.3	33	0.09	0.069
KYS 109061	Soil	1.5	38.0	17.8	86	0.2	29.3	13.1	547	2.90	86.8	1.0	11.2	6.7	13	0.3	23.7	0.2	22	0.17	0.063
KYS 109062	Soil	0.7	37.5	23.4	74	0.2	31.8	13.4	746	3.02	14.7	1.4	3.6	9.6	14	0.1	5.0	0.3	19	0.19	0.057
KYS 109063	Soil	1.3	88.4	26.0	94	0.5	34.6	14.1	1150	3.23	493.0	1.2	121.8	8.0	19	0.2	387.8	0.3	22	0.19	0.055

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109031	Soil	22	17	0.40	55	0.011	<1	1.29	0.004	0.04	<0.1	0.02	1.2	<0.1	<0.05	4	0.6	0.3
KYS 109032	Soil	20	14	0.39	60	0.010	<1	1.04	0.005	0.05	<0.1	0.02	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109033	Soil	21	13	0.44	59	0.016	<1	0.95	0.003	0.04	<0.1	0.02	1.5	<0.1	<0.05	3	0.6	<0.2
KYS 109034	Soil	24	18	0.43	126	0.017	1	1.22	0.006	0.06	0.1	0.03	2.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109035	Soil	28	12	0.47	70	0.005	<1	1.10	0.004	0.07	<0.1	0.04	1.8	<0.1	<0.05	3	<0.5	0.3
KYS 109036	Soil	28	10	0.43	52	0.002	<1	1.03	0.005	0.05	<0.1	0.04	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109037	Soil	32	14	0.93	42	0.001	<1	1.36	0.003	0.04	<0.1	0.04	1.5	<0.1	<0.05	3	0.9	<0.2
KYS 109038	Soil	30	14	0.88	43	0.002	<1	1.24	0.004	0.04	<0.1	0.04	1.5	<0.1	<0.05	3	0.7	<0.2
KYS 109039	Soil	22	9	0.32	43	0.003	<1	0.82	0.004	0.04	<0.1	0.03	1.3	<0.1	<0.05	2	0.8	<0.2
KYS 109040	Soil	19	8	0.30	51	0.002	1	0.71	0.004	0.05	<0.1	0.05	1.9	<0.1	<0.05	2	0.9	0.2
KYS 109041	Soil	16	15	0.44	52	0.003	<1	1.22	0.005	0.06	<0.1	0.04	0.9	<0.1	<0.05	4	0.8	<0.2
KYS 109042	Soil	18	11	0.38	66	0.002	<1	1.12	0.008	0.05	<0.1	0.03	1.1	<0.1	<0.05	3	0.8	<0.2
KYS 109043	Soil	20	18	0.43	152	0.013	<1	1.26	0.005	0.05	<0.1	0.07	1.4	<0.1	<0.05	4	<0.5	0.3
KYS 109044	Soil	31	13	0.16	113	0.009	<1	0.78	0.003	0.04	<0.1	0.07	0.9	<0.1	<0.05	4	1.1	0.3
KYS 109045	Soil	22	13	0.25	117	0.008	<1	0.69	0.004	0.05	<0.1	0.06	0.7	<0.1	<0.05	4	0.6	0.4
KYS 109046	Soil	14	21	0.24	83	0.020	<1	1.18	0.005	0.04	0.2	0.06	0.8	0.1	<0.05	6	0.6	<0.2
KYS 109047	Soil	21	15	0.27	202	0.008	1	0.88	0.005	0.04	0.1	0.10	1.1	<0.1	<0.05	3	2.2	0.5
KYS 109048	Soil	20	15	0.24	184	0.008	<1	0.84	0.005	0.04	0.1	0.10	0.9	<0.1	<0.05	3	2.2	0.6
KYS 109049	Soil	19	18	0.34	267	0.018	<1	1.10	0.006	0.04	0.2	0.07	1.4	<0.1	<0.05	4	0.9	0.2
KYS 109050	Soil	19	13	0.29	144	0.010	<1	0.95	0.005	0.04	0.1	0.07	1.5	<0.1	<0.05	3	0.8	0.3
KYS 109051	Soil	22	9	0.24	143	0.004	<1	0.73	0.004	0.03	<0.1	0.07	1.4	<0.1	<0.05	2	0.9	<0.2
KYS 109052	Soil	23	9	0.23	139	0.005	<1	0.73	0.004	0.03	<0.1	0.07	1.2	<0.1	<0.05	2	1.0	<0.2
KYS 109056	Soil	32	16	0.58	219	0.007	1	1.44	0.004	0.05	<0.1	0.07	2.1	<0.1	<0.05	4	0.9	0.2
KYS 109057	Soil	28	17	0.44	88	0.013	<1	1.08	0.005	0.05	<0.1	0.05	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109058	Soil	29	15	0.53	74	0.007	<1	1.23	0.004	0.06	<0.1	0.05	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109059	Soil	25	15	0.54	89	0.006	1	1.30	0.004	0.06	<0.1	0.07	1.6	<0.1	<0.05	3	<0.5	<0.2
KYS 109060	Soil	18	20	0.42	131	0.016	1	1.36	0.005	0.05	0.2	0.04	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 109061	Soil	24	15	0.43	103	0.015	1	1.03	0.004	0.05	<0.1	0.04	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109062	Soil	25	16	0.45	99	0.014	<1	1.12	0.006	0.05	<0.1	0.04	1.8	<0.1	<0.05	3	<0.5	<0.2
KYS 109063	Soil	30	16	0.47	166	0.005	<1	1.23	0.005	0.06	<0.1	0.08	2.0	<0.1	<0.05	3	<0.5	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
KYS 109064	Soil	1.0	66.9	23.0	90	0.4	32.3	12.4	703	3.13	665.9	1.1	141.5	6.9	14	0.1	62.2	0.3	16	0.18	0.049
KYS 109065	Soil	0.9	73.8	18.4	78	0.3	31.0	10.9	730	2.77	261.0	1.0	90.1	6.0	14	<0.1	50.5	0.3	23	0.16	0.046
KYS 109066	Soil	1.2	71.4	17.0	79	0.1	31.4	13.4	1457	2.89	198.7	0.8	25.3	0.9	9	0.1	46.4	0.3	35	0.04	0.063
KYS 109067	Soil	1.2	49.6	24.7	77	0.2	35.9	16.3	1177	2.77	32.5	1.1	8.7	11.5	10	0.2	12.8	0.3	15	0.14	0.052
KYS 109068	Soil	11.4	81.4	23.5	181	1.1	36.3	8.9	488	2.70	19.9	3.0	6.9	6.1	72	0.8	10.9	0.3	39	0.28	0.113
KYS 109069	Soil	0.8	63.2	16.3	87	0.2	44.2	21.3	586	3.53	47.5	1.1	3.5	4.5	7	0.1	12.5	0.2	10	0.07	0.043
KYS 109070	Soil	0.9	46.3	27.6	86	<0.1	39.2	20.5	832	4.05	56.5	1.3	6.4	10.8	6	<0.1	15.9	0.4	18	0.04	0.034
KYS 109071	Soil	1.5	49.9	31.3	85	0.2	40.5	22.3	885	4.18	33.4	2.6	1.6	3.9	13	0.3	4.2	0.5	12	0.12	0.049
KYS 109072	Soil	1.3	44.1	25.0	86	0.1	32.7	15.0	562	3.66	24.1	2.0	1.6	6.6	11	0.2	2.6	0.3	20	0.12	0.057
KYS 109073	Soil	1.2	44.5	24.9	82	0.1	31.2	14.8	536	3.83	20.7	2.1	3.9	4.2	7	0.2	2.4	0.4	16	0.05	0.049
KYS 109074	Soil	1.0	37.6	20.6	78	<0.1	29.0	12.9	434	3.53	25.9	1.7	3.4	5.9	8	0.1	2.3	0.3	20	0.07	0.047
KYS 109075	Soil	1.2	39.0	24.4	79	<0.1	24.6	11.8	404	3.73	30.1	1.8	3.9	3.7	6	0.1	2.7	0.4	23	0.05	0.048
KYS 109076	Soil	1.1	46.1	24.8	88	<0.1	32.0	15.5	419	4.13	30.5	2.1	4.9	7.9	7	0.1	3.9	0.4	16	0.05	0.040
KYS 109077	Soil	1.0	39.5	27.1	85	0.1	25.1	12.9	455	4.02	30.4	1.8	4.0	7.0	5	0.1	3.6	0.4	13	0.05	0.041
KYS 109078	Soil	1.0	43.5	27.2	88	0.1	27.2	12.1	398	4.13	27.1	2.1	2.8	7.4	7	<0.1	3.8	0.5	12	0.10	0.040
KYS 109079	Soil	0.8	38.2	23.1	88	0.1	28.6	11.9	402	3.98	12.6	1.8	1.5	11.2	7	0.1	3.7	0.3	13	0.09	0.040
KYS 109080	Soil	1.9	53.0	17.1	85	0.1	30.4	10.0	450	2.71	16.4	2.1	3.0	4.4	15	0.3	3.1	0.2	16	0.16	0.050
KYS 109081	Soil	2.1	160.2	17.6	177	0.4	57.5	8.2	517	3.07	16.0	16.2	8.2	3.8	25	0.5	2.4	0.2	36	0.21	0.079
KYS 109082	Soil	3.4	97.6	29.4	175	0.4	64.6	30.0	1380	3.98	16.9	1.8	6.0	16.9	12	0.7	2.9	0.4	14	0.10	0.051
KYS 109083	Soil	5.8	114.9	30.9	259	0.4	93.9	31.3	2358	4.16	16.6	2.9	48.8	5.4	10	1.2	3.9	0.4	25	0.07	0.077

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

CERTIFICATE OF ANALYSIS WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
KYS 109064	Soil	27	11	0.25	192	0.004	<1	0.87	0.004	0.05	<0.1	0.08	2.0	<0.1	<0.05	2	<0.5	<0.2
KYS 109065	Soil	24	15	0.35	127	0.010	<1	1.00	0.006	0.05	0.1	0.07	1.9	<0.1	<0.05	3	<0.5	0.2
KYS 109066	Soil	18	19	0.32	103	0.010	1	1.11	0.005	0.06	0.1	0.03	1.1	<0.1	<0.05	4	0.6	0.4
KYS 109067	Soil	27	12	0.43	132	0.011	<1	1.00	0.004	0.06	<0.1	0.05	1.9	<0.1	<0.05	3	<0.5	<0.2
KYS 109068	Soil	29	13	0.33	296	0.008	1	0.89	0.004	0.06	<0.1	0.69	1.5	0.1	<0.05	2	2.5	0.2
KYS 109069	Soil	22	13	0.38	46	0.003	<1	1.16	0.005	0.07	<0.1	0.05	1.1	<0.1	<0.05	3	<0.5	<0.2
KYS 109070	Soil	35	20	0.50	63	0.005	<1	1.53	0.005	0.06	<0.1	0.03	1.5	<0.1	<0.05	5	<0.5	<0.2
KYS 109071	Soil	14	10	0.40	60	0.004	<1	1.06	0.005	0.05	<0.1	0.05	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109072	Soil	19	15	0.46	100	0.014	<1	1.17	0.006	0.05	<0.1	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109073	Soil	17	13	0.44	73	0.006	<1	1.21	0.007	0.05	<0.1	0.04	1.4	<0.1	<0.05	3	<0.5	<0.2
KYS 109074	Soil	20	16	0.44	73	0.012	<1	1.15	0.005	0.05	<0.1	0.02	1.5	<0.1	<0.05	3	<0.5	<0.2
KYS 109075	Soil	19	17	0.52	67	0.011	<1	1.45	0.005	0.05	<0.1	0.02	1.5	<0.1	<0.05	4	<0.5	<0.2
KYS 109076	Soil	23	15	0.52	48	0.007	<1	1.25	0.005	0.05	<0.1	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2
KYS 109077	Soil	23	14	0.56	54	0.002	<1	1.37	0.004	0.05	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
KYS 109078	Soil	23	15	0.57	57	0.002	<1	1.43	0.008	0.05	<0.1	0.03	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109079	Soil	30	16	0.58	51	0.004	<1	1.37	0.005	0.05	<0.1	0.04	1.4	<0.1	<0.05	4	<0.5	<0.2
KYS 109080	Soil	19	11	0.31	71	0.008	<1	0.80	0.006	0.03	<0.1	0.04	1.3	<0.1	<0.05	2	0.6	<0.2
KYS 109081	Soil	18	22	0.44	137	0.029	2	1.35	0.007	0.06	0.1	0.12	3.5	<0.1	<0.05	3	1.0	<0.2
KYS 109082	Soil	28	14	0.52	92	0.005	1	1.31	0.004	0.06	<0.1	0.14	1.4	<0.1	<0.05	3	1.0	0.4
KYS 109083	Soil	25	15	0.36	217	0.008	1	1.08	0.003	0.04	<0.1	0.12	1.5	<0.1	<0.05	3	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.1	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
KYS 94385	Soil	3.3	53.2	34.6	58	0.7	17.0	3.3	144	3.24	50.9	1.2	10.6	0.8	10	0.1	7.8	0.6	30	0.03	0.101
REP KYS 94385	QC	2.9	50.2	34.0	57	0.7	16.2	3.0	139	3.13	50.3	1.1	10.1	0.7	10	0.1	7.6	0.6	30	0.03	0.095
KYS 94401	Soil	2.0	22.7	14.9	61	0.4	17.6	7.7	376	2.50	30.2	1.0	4.1	0.3	8	0.2	1.8	0.3	45	0.05	0.077
REP KYS 94401	QC	2.0	21.9	15.4	61	0.4	17.1	7.3	374	2.49	29.6	1.0	7.4	0.2	8	0.2	1.8	0.3	43	0.04	0.077
KYS 102439	Soil	3.8	302.9	39.0	246	0.2	79.6	43.0	5630	4.76	30.7	3.9	28.8	2.1	11	0.7	3.5	0.4	34	0.03	0.121
REP KYS 102439	QC	3.7	303.0	38.7	236	0.2	76.5	42.9	5444	4.67	29.9	4.0	23.4	2.2	10	0.7	3.6	0.4	33	0.04	0.121
KYS 102454	Soil	1.1	16.5	14.0	48	<0.1	14.4	6.2	305	2.28	11.4	0.7	2.9	2.4	13	0.2	1.8	0.2	31	0.15	0.039
REP KYS 102454	QC	1.0	16.0	13.8	48	<0.1	14.3	6.1	293	2.18	10.7	0.7	2.5	2.4	13	0.1	1.8	0.2	32	0.15	0.042
KYS 102485	Soil	1.5	78.5	16.7	67	0.2	36.6	12.3	1597	2.48	12.0	0.8	15.9	3.0	16	0.2	1.2	0.3	37	0.08	0.052
REP KYS 102485	QC	1.4	81.2	17.0	71	0.2	39.3	12.4	1713	2.70	12.1	0.8	40.0	2.9	16	0.1	1.1	0.2	39	0.09	0.057
KYS 105750	Soil	1.4	37.2	23.6	71	0.2	29.4	11.0	466	2.98	34.5	1.1	4.8	7.3	10	0.2	1.8	0.3	25	0.08	0.083
REP KYS 105750	QC	1.4	37.9	23.0	72	0.2	29.4	10.4	467	3.00	34.2	1.1	5.0	7.0	9	0.2	1.7	0.3	24	0.08	0.086
KYS 105810	Soil	0.5	38.6	33.2	69	0.1	35.8	18.3	531	2.96	59.8	1.7	3.7	8.8	12	0.2	5.4	0.4	17	0.14	0.053
REP KYS 105810	QC	0.5	38.9	33.2	70	<0.1	35.7	18.3	535	2.91	60.6	1.8	4.4	9.3	12	0.1	5.4	0.4	16	0.14	0.051
KYS 105836	Soil	0.8	40.0	22.7	94	0.1	34.0	11.8	476	3.37	49.7	2.0	8.9	8.9	13	0.4	6.9	0.3	8	0.20	0.040
REP KYS 105836	QC	0.8	37.1	21.6	93	0.1	33.6	11.1	485	3.26	49.0	2.0	7.0	8.8	13	0.4	6.7	0.3	9	0.20	0.039
KYS 105853	Soil	1.3	105.7	29.9	88	0.5	32.7	12.6	851	3.10	617.8	1.2	134.4	8.2	20	0.2	459.4	0.3	17	0.16	0.051
REP KYS 105853	QC	1.2	109.6	28.4	87	0.5	34.3	12.9	899	3.19	607.2	1.2	125.5	8.5	19	0.2	461.0	0.3	17	0.18	0.051
KYS 105859	Soil	3.7	143.2	22.1	96	0.2	34.8	12.1	559	3.34	17.9	1.3	29.3	3.0	17	0.3	8.6	0.3	39	0.08	0.076
REP KYS 105859	QC	3.8	142.1	21.9	93	0.2	35.4	12.0	551	3.33	17.6	1.3	117.4	3.0	16	0.2	8.6	0.3	40	0.08	0.078
KYS 105883	Soil	5.4	117.5	23.4	139	0.3	42.5	16.3	1011	3.47	110.0	2.4	21.6	5.7	26	0.6	16.6	0.3	18	0.03	0.067
REP KYS 105883	QC	5.3	116.9	23.4	134	0.4	43.3	15.9	1018	3.44	110.6	2.4	16.8	5.8	27	0.6	17.1	0.3	18	0.03	0.065
KYS 105897	Soil	1.2	16.5	19.7	61	<0.1	17.6	13.1	994	2.72	47.4	1.1	3.1	1.3	11	0.2	4.7	0.3	26	0.13	0.092
REP KYS 105897	QC	1.2	16.2	19.1	62	<0.1	17.4	12.9	972	2.64	47.1	1.0	3.2	1.1	11	0.2	4.7	0.3	25	0.13	0.089
KYS 105923	Soil	0.8	50.1	34.9	100	0.2	42.5	20.5	656	4.06	61.7	1.9	12.4	9.5	13	0.2	8.1	0.5	5	0.19	0.048
REP KYS 105923	QC	0.7	48.8	36.0	100	0.2	40.7	20.6	659	4.01	62.0	1.9	9.1	9.1	13	0.2	8.2	0.5	5	0.18	0.047
KYS 105937	Soil	5.8	90.5	21.4	145	0.4	47.6	18.4	1016	4.27	7.9	2.1	6.7	4.9	38	0.6	4.0	0.3	25	0.21	0.120
REP KYS 105937	QC	5.7	89.8	21.2	142	0.4	47.5	19.2	1041	4.31	8.0	2.0	5.0	4.7	39	0.4	3.8	0.3	24	0.21	0.118

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000108.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
KYS 94385	Soil	7	18	0.15	261	0.004	<1	0.95	0.008	0.04	0.1	0.07	1.1	<0.1	<0.05	3	2.1	0.2
REP KYS 94385	QC	6	18	0.14	252	0.004	<1	0.90	0.008	0.04	0.2	0.08	0.9	<0.1	0.05	3	2.0	0.2
KYS 94401	Soil	9	21	0.20	70	0.013	<1	1.09	0.004	0.04	0.1	0.03	0.6	<0.1	<0.05	4	0.7	0.2
REP KYS 94401	QC	10	21	0.20	69	0.013	<1	1.08	0.004	0.04	0.1	0.05	0.6	<0.1	<0.05	4	0.7	<0.2
KYS 102439	Soil	17	26	0.46	244	0.012	2	1.32	0.006	0.03	<0.1	0.08	1.1	<0.1	<0.05	4	1.4	0.9
REP KYS 102439	QC	17	25	0.46	245	0.011	2	1.34	0.007	0.03	<0.1	0.07	1.1	<0.1	<0.05	4	1.1	0.2
KYS 102454	Soil	13	18	0.28	99	0.025	1	0.85	0.008	0.05	0.1	0.02	1.2	<0.1	<0.05	4	<0.5	<0.2
REP KYS 102454	QC	13	17	0.28	102	0.032	1	0.85	0.008	0.05	0.2	0.04	1.2	<0.1	<0.05	4	<0.5	<0.2
KYS 102485	Soil	19	23	0.42	105	0.023	<1	1.27	0.005	0.03	0.1	0.09	1.3	<0.1	<0.05	4	0.7	<0.2
REP KYS 102485	QC	19	23	0.45	105	0.025	<1	1.39	0.005	0.04	0.1	0.10	1.5	<0.1	<0.05	4	0.8	0.6
KYS 105750	Soil	17	22	0.32	74	0.012	<1	1.19	0.004	0.05	<0.1	0.05	1.7	<0.1	<0.05	3	0.9	<0.2
REP KYS 105750	QC	17	22	0.33	75	0.012	<1	1.24	0.004	0.05	<0.1	0.05	1.7	<0.1	<0.05	3	1.0	0.4
KYS 105810	Soil	22	13	0.41	67	0.011	<1	0.95	0.004	0.07	0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
REP KYS 105810	QC	22	13	0.41	68	0.011	1	0.99	0.004	0.06	0.1	0.03	1.3	<0.1	<0.05	3	<0.5	<0.2
KYS 105836	Soil	22	11	0.38	49	0.002	<1	0.95	0.003	0.05	<0.1	0.03	1.3	<0.1	<0.05	2	<0.5	<0.2
REP KYS 105836	QC	21	11	0.36	47	0.002	<1	0.96	0.003	0.05	<0.1	0.03	1.3	<0.1	<0.05	2	<0.5	<0.2
KYS 105853	Soil	27	14	0.39	122	0.004	<1	1.01	0.003	0.06	<0.1	0.08	1.5	<0.1	<0.05	3	<0.5	0.4
REP KYS 105853	QC	26	14	0.40	118	0.003	1	1.01	0.003	0.06	<0.1	0.07	1.6	<0.1	<0.05	3	0.6	<0.2
KYS 105859	Soil	22	24	0.49	147	0.010	1	1.39	0.003	0.04	0.2	0.09	1.2	<0.1	<0.05	4	1.1	0.2
REP KYS 105859	QC	22	24	0.49	143	0.011	1	1.32	0.003	0.04	0.2	0.09	1.0	<0.1	<0.05	4	0.9	0.2
KYS 105883	Soil	19	10	0.31	766	0.004	<1	0.91	0.004	0.05	<0.1	0.08	1.3	<0.1	<0.05	2	1.5	<0.2
REP KYS 105883	QC	20	10	0.32	768	0.004	<1	0.92	0.004	0.05	<0.1	0.09	1.4	<0.1	<0.05	2	1.7	0.4
KYS 105897	Soil	18	18	0.40	144	0.005	<1	1.21	0.006	0.06	<0.1	0.02	0.8	0.1	<0.05	4	<0.5	<0.2
REP KYS 105897	QC	17	17	0.39	138	0.007	<1	1.31	0.006	0.06	0.1	0.02	0.8	<0.1	<0.05	4	<0.5	<0.2
KYS 105923	Soil	16	8	0.35	30	0.001	<1	0.68	0.004	0.04	<0.1	0.05	1.5	<0.1	<0.05	2	<0.5	<0.2
REP KYS 105923	QC	16	7	0.35	31	0.001	<1	0.69	0.005	0.04	0.2	0.05	1.5	<0.1	<0.05	2	<0.5	0.2
KYS 105937	Soil	20	10	0.31	176	0.006	<1	1.01	0.004	0.06	<0.1	0.11	2.1	<0.1	<0.05	3	1.2	0.2
REP KYS 105937	QC	21	12	0.31	181	0.006	<1	1.05	0.005	0.06	<0.1	0.10	2.3	<0.1	<0.05	3	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000108.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
KYS 105996	Soil	2.4	46.5	14.6	58	<0.1	22.6	7.5	611	2.74	10.1	0.7	9.7	0.6	10	0.1	1.5	0.3	43	0.05	0.055
REP KYS 105996	QC	2.4	47.5	14.1	59	<0.1	23.4	7.7	602	2.81	10.6	0.6	7.0	0.8	10	0.1	1.6	0.3	43	0.05	0.055
KYS 109016	Soil	0.3	36.6	22.0	83	<0.1	31.8	15.1	582	3.37	19.7	1.5	1.7	15.0	13	<0.1	1.8	0.3	13	0.25	0.046
REP KYS 109016	QC	0.3	37.2	21.7	84	<0.1	31.3	14.5	568	3.18	19.6	1.5	3.1	14.8	14	<0.1	1.7	0.3	13	0.24	0.043
KYS 109030	Soil	1.1	25.9	21.6	72	<0.1	21.5	10.9	301	3.39	8.0	1.4	2.8	4.5	8	0.2	0.9	0.3	30	0.06	0.048
REP KYS 109030	QC	1.0	25.5	20.6	67	<0.1	19.3	9.9	278	3.14	7.2	1.4	2.8	4.0	8	0.1	0.9	0.3	28	0.05	0.047
KYS 109056	Soil	2.1	60.5	19.9	95	0.1	31.8	11.5	824	3.17	9.0	1.3	7.0	6.9	16	0.3	0.9	0.3	22	0.13	0.068
REP KYS 109056	QC	2.0	58.8	18.4	91	0.1	29.5	10.5	814	3.17	8.7	1.3	5.3	6.3	16	0.3	0.8	0.3	22	0.12	0.066
KYS 109074	Soil	1.0	37.6	20.6	78	<0.1	29.0	12.9	434	3.53	25.9	1.7	3.4	5.9	8	0.1	2.3	0.3	20	0.07	0.047
REP KYS 109074	QC	1.0	37.5	20.9	76	<0.1	25.9	12.2	430	3.42	25.6	1.7	4.1	5.7	8	0.1	2.2	0.3	20	0.07	0.050
Reference Materials																					
STD DS7	Standard	21.3	106.3	67.7	403	1.0	53.4	9.3	612	2.35	53.0	5.1	70.1	4.8	77	6.7	6.3	4.7	83	0.90	0.075
STD DS7	Standard	21.2	109.1	69.1	379	0.9	56.3	9.2	613	2.28	48.0	4.8	110.7	4.6	74	5.8	5.5	4.5	84	0.92	0.067
STD DS7	Standard	19.6	100.9	62.7	356	0.8	51.3	8.5	562	2.18	46.8	4.7	63.1	4.4	73	5.4	5.4	4.4	77	0.91	0.069
STD DS7	Standard	22.2	125.9	69.5	420	1.1	63.2	10.4	657	2.44	54.5	4.9	74.5	4.6	73	6.2	5.9	4.6	91	1.00	0.079
STD DS7	Standard	22.0	116.9	69.8	422	1.0	61.6	10.1	677	2.56	54.2	4.8	73.6	4.8	78	6.3	6.0	4.7	93	1.00	0.078
STD DS7	Standard	22.3	109.9	69.9	407	1.0	56.5	9.6	634	2.49	52.9	5.2	86.9	5.2	82	6.4	6.3	4.8	97	1.00	0.078
STD DS7	Standard	22.9	112.6	76.1	399	1.0	61.9	10.3	641	2.45	49.3	5.0	70.1	5.0	75	5.8	5.9	4.6	92	0.97	0.075
STD DS7	Standard	23.5	113.1	74.6	396	1.0	60.8	10.6	668	2.54	46.3	5.1	77.5	4.9	76	5.9	5.6	4.5	95	1.03	0.075
STD DS7	Standard	21.4	111.9	68.9	407	1.0	53.2	9.3	613	2.31	55.1	4.8	77.4	4.8	76	6.7	5.9	4.8	81	0.96	0.077
STD DS7	Standard	22.7	122.3	73.2	410	1.1	59.2	10.0	624	2.39	51.6	5.0	68.2	5.0	79	6.2	6.4	4.7	89	0.89	0.075
STD DS7 Expected		20.5	109	70.6	411	0.9	56	9.7	627	2.39	48.2	4.9	70	4.4	69	6.4	4.6	4.5	84	0.93	0.08
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	0.4	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000108.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
KYS 105996	Soil	20	21	0.33	94	0.015	1	1.27	0.003	0.03	<0.1	0.06	0.7	<0.1	<0.05	5	0.7	<0.2
REP KYS 105996	QC	20	21	0.34	93	0.014	<1	1.26	0.003	0.03	<0.1	0.05	0.7	<0.1	<0.05	5	0.5	<0.2
KYS 109016	Soil	35	16	0.62	55	0.008	<1	1.37	0.004	0.08	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
REP KYS 109016	QC	31	16	0.60	51	0.008	1	1.33	0.003	0.07	<0.1	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
KYS 109030	Soil	21	21	0.45	93	0.015	1	1.49	0.005	0.05	0.2	0.03	1.8	<0.1	<0.05	4	0.7	<0.2
REP KYS 109030	QC	19	18	0.42	83	0.014	<1	1.43	0.004	0.05	0.1	0.03	1.8	<0.1	<0.05	4	<0.5	<0.2
KYS 109056	Soil	32	16	0.58	219	0.007	1	1.44	0.004	0.05	<0.1	0.07	2.1	<0.1	<0.05	4	0.9	0.2
REP KYS 109056	QC	28	15	0.55	205	0.006	<1	1.36	0.004	0.05	<0.1	0.07	2.0	<0.1	<0.05	4	0.5	<0.2
KYS 109074	Soil	20	16	0.44	73	0.012	<1	1.15	0.005	0.05	<0.1	0.02	1.5	<0.1	<0.05	3	<0.5	<0.2
REP KYS 109074	QC	20	15	0.48	72	0.012	<1	1.22	0.005	0.05	<0.1	0.03	1.4	<0.1	<0.05	3	<0.5	<0.2
Reference Materials																		
STD DS7	Standard	14	198	1.00	376	0.125	36	1.05	0.095	0.43	3.7	0.20	2.5	4.2	0.17	5	3.7	1.2
STD DS7	Standard	13	213	0.98	381	0.127	37	0.94	0.093	0.42	3.6	0.20	2.4	3.9	0.16	5	3.0	1.2
STD DS7	Standard	12	198	0.93	366	0.119	40	0.91	0.095	0.41	3.3	0.21	2.1	3.5	0.13	5	3.0	1.0
STD DS7	Standard	13	224	1.07	394	0.133	41	1.04	0.105	0.49	3.7	0.22	2.6	4.1	0.20	5	3.5	1.8
STD DS7	Standard	14	232	1.07	417	0.138	39	1.09	0.104	0.50	3.9	0.24	2.6	4.3	0.19	5	3.3	0.3
STD DS7	Standard	14	216	1.07	422	0.134	37	1.08	0.106	0.48	3.7	0.22	2.5	3.9	0.21	5	3.1	0.8
STD DS7	Standard	14	240	1.06	396	0.139	38	1.05	0.104	0.46	3.8	0.21	2.7	4.1	0.19	5	3.4	1.9
STD DS7	Standard	13	244	1.12	418	0.126	42	1.11	0.102	0.49	4.0	0.24	2.4	4.4	0.21	5	3.7	1.5
STD DS7	Standard	13	178	1.05	410	0.122	41	1.02	0.114	0.48	3.8	0.22	2.7	4.2	0.19	5	3.6	1.2
STD DS7	Standard	14	201	1.02	408	0.137	39	1.00	0.099	0.47	3.8	0.22	2.3	4.0	0.19	5	2.6	1.1
STD DS7 Expected		12	179	1.05	410	0.124	39	0.959	0.089	0.44	3.4	0.2	2.5	4.2	0.19	5	3.5	1.08
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000108.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 U ppm 0.1	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.1	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Aldrin Resources**
Suite 600 - 595 Howe Street
Vancouver BC V6C 2T5 Canada

Project: KYS
Report Date: August 23, 2010

QUALITY CONTROL REPORT WHI10000108.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Appendix G: Quality Control / Quality Assurance

QUALITY CONTROL / QUALITY ASSURANCE

I Chain of Custody

All samples were packed in rice sacks and sealed with uniquely-numbered non-resealable security straps. Rice sacks were delivered either by Equity personnel or by Kluane Freight Lines Ltd. to the ALS Chemex Labs Ltd. preparation facility in Whitehorse, an ISO 9001 registered laboratory. ALS Chemex reported that all bags were received in good condition, with all security straps intact, and with no evidence of tampering.

II Blanks

Blanks are samples which are known to be barren of mineralization and are inserted into the sample stream in the field to determine whether contamination has occurred after sample collection. Powdered silica sand was used as a blank on the Keystone project. A total of 39 blanks were inserted into the core sample sequence and submitted to the lab. Analyses for elements of interest are presented in the table below. All samples returned gold values less than five times the detection limit of 5 ppb, and thus none of the samples are judged to be failures with respect to gold. Flushing procedures at the lab are judged to be acceptable.

Sample ID	Au	As	Ag	Pb	Sb	Zn
E856050	<0.005	<2	0.3	3	<2	3
E856090	<0.005	<2	<0.2	2	<2	16
E856135	<0.005	<2	<0.2	<2	<2	3
E856170	<0.005	<2	<0.2	<2	<2	3
E856190	<0.005	14	<0.2	<2	<2	2
E856230	<0.005	<2	<0.2	<2	<2	2
E856290	<0.005	<2	<0.2	<2	<2	3
E856310	<0.005	<2	<0.2	<2	<2	2
E856350	<0.005	<2	<0.2	<2	<2	2
E856370	<0.005	<2	<0.2	2	<2	3
E856410	<0.005	2	<0.2	<2	<2	<2
E856430	<0.005	<2	<0.2	<2	<2	2
E856530	<0.005	<2	<0.2	<2	<2	2
E856550	<0.005	<2	0.2	<2	<2	<2
E856570	<0.005	2	<0.2	<2	<2	3
E856590	<0.005	<2	<0.2	<2	<2	<2
E856610	<0.005	<2	<0.2	<2	<2	2
E856650	<0.005	<2	<0.2	8	<2	3
E856690	<0.005	<2	<0.2	<2	<2	2
E856730	<0.005	<2	<0.2	2	<2	2
E856750	<0.005	<2	<0.2	<2	<2	3
E856790	<0.005	<2	<0.2	<2	<2	4
E856830	<0.005	<2	<0.2	<2	<2	2
E856890	<0.005	NSS	NSS	NSS	NSS	NSS
E856930	0.007	<2	<0.2	<2	<2	4
E856970	<0.005	<2	<0.2	2	<2	2
E857010	0.008	<2	<0.2	2	<2	5
E857050	0.009	<2	<0.2	2	<2	3
E858010	0.005	<2	<0.2	2	<2	2
E858030	<0.005	<2	<0.2	2	<2	2

E858070	<0.005	<2	<0.2	15	<2	12
E858090	<0.005	<2	<0.2	<2	<2	4
E858130	<0.005	<2	<0.2	<2	<2	3
E858150	<0.005	<2	<0.2	2	<2	2
E858190	<0.005	<2	0.3	<2	<2	<2
E858210	0.009	<2	<0.2	5	<2	5
E858250	<0.005	<2	<0.2	<2	<2	3
E858290	<0.005	<2	<0.2	<2	<2	3
E858330	0.006	<2	<0.2	<2	<2	<2

III Field and Preparation Duplicate Analysis

Field duplicates are the collection and analysis of two separate samples from the same field location; in the case of core samples; split core was split a second time into two ¼ core samples, each of which were submitted as separate samples creating the duplicate-pair. These field duplicates are used to measure the reproducibility or precision of sampling, which includes both laboratory variation and sample variation. The duplicate-pairs will contain all the cumulative error associated with the sampling and analytical process and may also allow the determination of true, or effective, detection limits (where the cumulative uncertainty of sampling and analytical techniques, or precision, equals 100%). A total of 64 field duplicate-pairs were inserted into the sample sequence (approximately every 20th sample) and submitted for analysis.

Preparation duplicates are separate analyses of two portions of a prepared sample. They are used to measure the reproducibility of laboratory analyses, eliminating variability introduced earlier in sample processing. The lab was requested to perform duplicate analyses of every 20th core sample for a total of 68 sample pairs.



Generally acceptable levels of precision for drill core are 30% for quarter-core or field duplicates and 20% for preparation duplicates at the 90th percentile level for the whole dataset. Alternatively, 90% of field duplicates should have a precision of 30% or better and 90% of prep duplicates should have a precision of

20% or better. The above plot of Absolute Relative Difference or precision versus rank for the field and prep duplicates shows that the field duplicates have a precision of about 40% while the prep duplicates have a precision of about 25%, both at the 90th percentile for the dataset.



The precision can be reviewed a little more closely with the above plot of Absolute Relative Difference (ARD), a proxy for precision, versus concentration. It can be read that precision at lower concentrations, less than 30 ppb Au, is from 30% to 40%. The precision diminishes at higher concentrations to about 60%.



Similarly, for the preparation duplicates, the precision can be estimated at about 50% at concentrations less than 50 ppb Au and 10% at concentrations greater than 50 ppb Au.

The poor precision of the field duplicate data is likely due to heterogeneities in the sampled material. Au mineralization commonly displays poor precision in particular vein-controlled mineralization as observed at Keystone. The better precision in the prep duplicates at higher concentrations suggests that much of the cumulative error, or lack of precision, can be attributed to the sampled material and sampling. The poor precision in both field and prep duplicates at lower concentrations is likely strongly influenced by analytical error at concentrations near the effective detection limits.

IV Standards

Standards are samples which contain known element concentrations, and are used to gauge accuracy and consistency of analytical results. A total of 30 standards were inserted during the 2010 drill program, approximately every 60th sample. Two types of standards (labelled T101 and T102) were created by WCM Minerals Ltd. The table below shows WCM's stated element concentrations in the samples.

Standard	Au (ppm)	Std. Deviation (Au)	Ag (ppm)	Pb (%)	Zn (%)	As (%)	Sb (%)
T101	0.87	0.037	153	0.52	1.32	0.43	0.2
T102	1.61	0.064	330	2.01	3.60	0.43	0.29

A total of 18 T101 and 12 T102 standards were inserted into the core sequence. As shown in the charts below, assay values for gold fall within two standard deviations of the certified value in all but three cases. In all three, the values fall within three standard deviations. As none of the samples which assay outside of two standard deviations are sequential with one another, they are not judged to be failures. Arsenic assays show a bias towards higher-than-actual values in all cases, though never by more than 10%. Gold assays display no such bias, reporting both higher and lower than reference values. Overall, the standards are judged to have an acceptable level of error.


Au values of standards with reported value and standard deviation lines
Au (ppm)
2
1.8
1.6
1.4
1.2
1
0.8
0.6
0.4
0.2
0
T101
Reported T101 value
T102
Reported T102 value
±2 standard deviations
±3 standard deviations


As values of standards with reported value and 10% margin of error
As (ppm)
5500
5000
4500
4000
3500
3000
T101
T102
Reported Value
± 10% error

V Conclusions

- There is no evidence of tampering with the samples between collection and the laboratory.
- Low values for metals of interest blank samples indicate that there was no significant contamination of samples in the field or in the lab.
- Quarter-core field duplicates and preparation duplicates show approximately 40% and 25% precision (respectively) over 90% of the samples. This implies that some variability is present between duplicate samples, as would be expected from the low-grade vein-hosted nature of mineralization.
- Assay values of standards inserted into the sample stream compare well to the true values for those standards, with error rarely exceeding two standard deviations or 10%, although As values appear to be consistently overstated. No similar bias is present in gold values.
- Although not presented here, ALS Chemex carries out a full QA/QC protocol, including blanks, duplicates and standards, on laboratory handling and analysis of samples and satisfy themselves that results are satisfactory, prior to issuing certificates.

Appendix H: Compact Disc

Report text, geochemical and drill databases, geophysical files, drafting and plot files, photographs

Appendix I: Geologist's Certificate

GEOLOGIST'S CERTIFICATE

David A. Swanton
402-1595 East 6th Avenue
Vancouver, British Columbia
daves@equityexploration.com

I, David Swanton, do herby certify that:

- I am a Project Geologist with Equity Exploration Consultants Ltd, with offices at Suite 200-900 West Hastings St., Vancouver, British Columbia.
- I am a graduate of the University of British Columbia (2004) with a Bachelor of Science degree and of Acadia University (2010) with a Master of Science degree in Geology.
- I have been involved in the mineral exploration industry since 2006.
- I assisted in the supervision of the 2010 exploration program on the Keystone property and have first-hand field knowledge of said property.

Dated at Vancouver, British Columbia, this _____ day of _____, 2010.

_____

David Swanton, M.Sc.



ALDRIN RESOURCE CORPORATION

KEYSTONE PROJECT

Map of Keystone claim block with drill collars, grab samples, geochemistry and geology

EQUITY

Date November, 2010	*Scale* 1:20,000	*Map*
U.T.M. Zone NAD83 Zone 8	*Mining District* Mayo	1
N.T.S. 105M/14	*State/Province* YT	



ALDRIN RESOURCE CORPORATION

KEYSTONE PROJECT
2010 Soil Sample Locations

EQUITY

Date: November, 2010	Scale: 1:12,500	Map: 2a
U.T.M. Zone: NAD83 Zone 8	Mining District: Mayo	
N.T.S.: 105M/14	State/Province: YT	

7,082,500 mN

7,080,000 mN

7,077,500 mN

7,075,000 mN

7,072,500 mN

482,500 mE

485,000 mE

487,500 mE

490,000 mE

492,500 mE

495,000 mE

497,500 mE

N

2010 Soil Geochemistry
Au (ppb)

- > 104 (98th percentile)
- 51 - 104 (95th percentile)
- 29 - 51 (90th percentile)
- 15 - 29 (80th percentile)
- 5 - 15 (50th percentile)
- < 5 (below 50th percentile)

pre-2010 Soil Geochemistry
Au (ppb)

- > 104 (98th percentile)
- 51 - 104 (95th percentile)
- 29 - 51 (90th percentile)
- 15 - 29 (80th percentile)
- 5 - 15 (50th percentile)
- < 5 (below 50th percentile)

ALDRIN RESOURCE CORPORATION

KEYSTONE PROJECT

Gold values in soil

EQUITY

Date: November, 2010	Scale: 1:20,000	Map: 2b
U.T.M. Zone: NAD83 Zone 8	Mining District: Mayo	
N.T.S.: 105M/14	State/Province: YT	



ALDRIN RESOURCE CORPORATION

KEYSTONE PROJECT

Arsenic values in soil

EQUITY	Date: November, 2010	Scale: 1:20,000	Map: 2c
	U.T.M. Zone: NAD83 Zone 8	Mining District: Mayo	
	N.T.S.: 105M/14	State/Province: YT	

7,082,500 mN

7,080,000 mN

7,077,500 mN

7,075,000 mN

7,072,500 mN

482,500 mE

485,000 mE

487,500 mE

490,000 mE

492,500 mE

495,000 mE

497,500 mE

N

2010 Soil Geochemistry
Sb (ppm)
- > 111 (98th percentile)
- 39 - 111 (95th percentile)
- 17 - 39 (90th percentile)
- 8 - 17 (80th percentile)
- 3 - 8 (50th percentile)
- < 3 (below 50th percentile)

pre-2010 Soil Geochemistry
Sb (ppm)
- > 111 (98th percentile)
- 39 - 111 (95th percentile)
- 17 - 39 (90th percentile)
- 8 - 17 (80th percentile)
- 3 - 8 (50th percentile)
- < 3 (below 50th percentile)

Region of anomalous gold

ALDRIN RESOURCE CORPORATION

KEYSTONE PROJECT

Antimony values in soil

EQUITY

Date: November, 2010	Scale: 1:20,000	Map: 2d
U.T.M. Zone: NAD83 Zone 8	Mining District: Mayo	
N.T.S.: 105M/14	State/Province: YT	